



ภาคผนวก 46


เอกสารการจัดตั้งหน่วยงานด้านความปลอดภัย และ
เจ้าหน้าที่ความปลอดภัยในการทำงานระดับวิชาชีพ



การบริหารงานด้านความปลอดภัยและสิ่งแวดล้อม



© SCGC 2022



© SCGC 2022



Safety Management and SD

นายอาทิตย์ ชื่นบุญชู
ผู้จัดการส่วน Safety Management and SD

Sustainable Development

น.ส.ศศิเพ็ญ ลายไม้
ผู้จัดการ Sustainable Development

Environmental and Governance

Occupational Health & Industrial Hygiene

Emergency and Security

Safety Management

น.ส.ชินจิต สุกปาน
ผู้จัดการ Safety Management

Safety Operation

Safety System

นายจิรทีปต์ เตียพิริยะกิจ
ผู้จัดการแผนก Env.&Governance

น.ส.กัญธดา ศรีงาม
ผู้จัดการแผนก Occ.Health&Industrial Hygiene

นายภาณุวิทย์ ธนาวัชรวรดิษฐ์
ผู้จัดการแผนก Emergency and Security

นายสมฤกษ์ นิยมธรรมรัตน์
ผู้จัดการแผนก Safety Operation

น.ส.สวิตา เลิศสุโกวณิชย์
ผู้จัดการแผนก Safety System

น.ส.อรุณรัตน์ นาคเรืองศรี
พช.วศ. Occ.Health&Industrial Hygiene

นายมนตรี ทำเนียม
วิศวกร Env.&Governance

น.ส.วริศรา ปลุกเสก
วิศวกร Env.&Governance

นายศิริพงษ์ พวงสุตรักษ์
Emergency & Fire Supervisor

นายชูพันธ์ พงษ์พันธ์
Field Security Officer

นายวิชิต เปียดนอก
วิศวกร Safety Operation

นายประเสริฐ วัฒนรัตน์
วิศวกร Safety Operation

นายสันติภาพ เมืองสุข
วิศวกร Safety System

น.ส.นลินรัตน์ นามกระโทก
วิศวกร Env.&Governance

นายสุทธิรัตน์ สว่างโรจน์
เจ้าหน้าที่ Env.&Governance

นายวัชรพงษ์ ยั่งยืน
Fire Chief Day Time

นายสังคม ตีบน้อยดี
Fire Chief of Shift A

นายนิโรจน์ เข้มพรมมา
เจ้าหน้าที่ Safety Operation

นายชูชาติ เพิ่มพระคลัง
เจ้าหน้าที่ Safety Operation

นายกฤษณ์ เงินขาว
วิศวกร Safety System

นายเอกชัย เกரியกระโทก
Fire Chief of Shift B

นายบุญช่วย บุตรดา
Fire Chief of Shift C

นายสามารถ อุบลรัตน์
Field Safety Officer

นายบัณฑิต ไรสรกุล
Field Safety Officer

นายธนพล อภินันทเวช
วิศวกร Safety System

นายวิจิตร ศรีเจิม
Field Safety Officer

นาย ตุลวิทย์ วิโรจน์ศิริ
Field Safety Officer

คำสั่งที่ 30/2565

เรื่อง แต่งตั้งคณะกรรมการความปลอดภัย อาชีวอนามัยและสภาพแวดล้อมในการทำงาน

ด้วยพิจารณาเห็นเป็นการสมควรจึงให้ยกเลิกคำสั่งที่ 30/2563 เรื่องการแต่งตั้งคณะกรรมการความปลอดภัย อาชีวอนามัยและสภาพแวดล้อมในการทำงานชุดปัจจุบันได้สิ้นสุดวาระลงในวันที่ 2 มิถุนายน 2565 และเพื่อให้การบริหารจัดการด้านความปลอดภัยเป็นไปตามนโยบายบริษัท และสอดคล้องกับกฎหมาย เรื่อง คณะกรรมการความปลอดภัย อาชีวอนามัยและสภาพแวดล้อมในการทำงาน บริษัท ฯ จึงขอประกาศแต่งตั้งคณะกรรมการความปลอดภัย ฯ ขึ้นใหม่ จำนวน 11 คน ดังมีรายชื่อต่อไปนี้

- | | | |
|---------------------------|---|--|
| 1. นายชนกร วิศุทธิ์ | ผู้จัดการ Compound & Functional Material Production | เป็นประธานคณะกรรมการ |
| 2. นายนิทัศน์ วิสุทธิ์ | ผู้จัดการแผนกผลิต Functional Material Production | เป็นกรรมการผู้แทนนายจ้างระดับบังคับบัญชา |
| 3. นายชัยยศ รัตนคุณ | ผู้จัดการแผนกผลิต LDPE | เป็นกรรมการผู้แทนนายจ้างระดับบังคับบัญชา |
| 4. นายสุพจน์ ฝาคำ | ผู้จัดการแผนกปฏิบัติการ Packing1 | เป็นกรรมการผู้แทนนายจ้างระดับบังคับบัญชา |
| 5. นายสมชัย บัญชีเจริญ | ผู้จัดการแผนก Pilot Plant | เป็นกรรมการผู้แทนนายจ้างระดับบังคับบัญชา |
| 6. นายเนทวุฒ โกฎคำ | พนักงานผลิต LDPE | เป็นกรรมการผู้แทนลูกจ้าง |
| 7. นายณัฐยศ พิษพันธ์ุ | พนักงานผลิต LLDPE | เป็นกรรมการผู้แทนลูกจ้าง |
| 8. นายณัฐพล เศรษฐศักดิ์โก | พนักงานผลิต PP#3 | เป็นกรรมการผู้แทนลูกจ้าง |
| 9. นายชนกฤต บุญช่วย | พนักงานปฏิบัติการคลังสินค้า | เป็นกรรมการผู้แทนลูกจ้าง |
| 10. นายมาโนช แซ่มจิ่ง | พนักงานปฏิบัติการ Packing | เป็นกรรมการผู้แทนลูกจ้าง |
| 11. นายสันติภาพ เมืองสุข | วิศวกร Safety System | เป็นกรรมการและเลขานุการ |

โดยคณะกรรมการมีหน้าที่ ดังต่อไปนี้

- 1.) พิจารณานโยบายและแผนงานด้านความปลอดภัยในการทำงานรวมทั้งความปลอดภัยนอกงานเพื่อป้องกันและลดการเกิดอุบัติเหตุ การประสบอันตราย การเจ็บป่วย หรือการเกิดเหตุเดือดร้อนรำคาญอันเนื่องมาจากการทำงาน หรือความไม่ปลอดภัยในการทำงานเสนอต่อนายจ้าง
- 2.) รายงานและเสนอแนะมาตรการหรือแนวทางปรับปรุงแก้ไข ให้ถูกต้องตามกฎหมายเกี่ยวกับความปลอดภัยในการทำงาน และมาตรฐานความปลอดภัยในการทำงานต่อนายจ้าง เพื่อความปลอดภัยในการทำงานของลูกจ้างผู้รับเหมา และบุคคลภายนอกที่เข้ามาปฏิบัติงานหรือเข้ามาใช้บริการในสถานประกอบกิจการ
- 3.) ส่งเสริม สนับสนุน กิจกรรมด้านความปลอดภัย ในการทำงาน ของ สถานประกอบกิจการ



คำสั่งที่ 18/2565

เรื่อง แต่งตั้งเจ้าหน้าที่ความปลอดภัยในการทำงาน ระดับวิชาชีพ

ด้วยบริษัท ไทยโพลิเอทิลีน จำกัด พิจารณาเห็นเป็นการสมควรและขอแต่งตั้งให้ผู้ที่มิรายชื่อเป็นเจ้าหน้าที่ความปลอดภัยในการทำงานประจำ บริษัท ไทยโพลิเอทิลีน จำกัด "สำนักงานใหญ่" ซึ่งตามกฎหมายกระทรวงกำหนดมาตรฐานในการบริหารและการจัดการด้านความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงาน พ.ศ. 2549 ข้อ 36 ลงวันที่ 16 พฤษภาคม พ.ศ. 2549 เรื่อง การแต่งตั้งเจ้าหน้าที่ความปลอดภัยในการทำงานประจำสถานประกอบกิจการ เพื่อให้การจัดการด้านอาชีวอนามัยและความปลอดภัย ของบริษัท เป็นไปอย่างมีประสิทธิภาพ และถูกต้องตามกฎหมาย โดยเจ้าหน้าที่ความปลอดภัยทุกระดับ ต้องมีคุณสมบัติตามหลักเกณฑ์ที่กฎหมายกำหนด

บริษัทฯ ได้พิจารณาแล้วจึงเห็นสมควร และขอแต่งตั้งให้ผู้ที่มิรายชื่อเป็นเจ้าหน้าที่ความปลอดภัยในการทำงาน ระดับวิชาชีพ ประจำบริษัท ไทยโพลิเอทิลีน จำกัด "สำนักงานใหญ่" และประกาศให้ทราบโดยทั่วกัน ดังรายชื่อต่อไปนี้

- นางสาวชินจิต สุกปาน ผู้จัดการ Safety Management

โดยกำหนดหน้าที่รับผิดชอบของเจ้าหน้าที่ความปลอดภัยระดับวิชาชีพ ดังนี้

- ตรวจสอบและเสนอแนะ ให้นายจ้างปฏิบัติตามกฎหมายเกี่ยวกับความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงาน
- วิเคราะห์งานเพื่อชี้บ่งอันตราย รวมทั้งกำหนดมาตรการป้องกัน หรือขั้นตอนการทำงานอย่างปลอดภัย เสนอต่อนายจ้าง
- ประเมินความเสี่ยงด้านความปลอดภัยในการทำงาน
- วิเคราะห์แผนงานโครงการ รวมทั้งข้อเสนอแนะของหน่วยงานต่างๆ และเสนอแนะมาตรการความปลอดภัยในการทำงาน ต่อนายจ้าง
- ตรวจประเมินการปฏิบัติงานของสถานประกอบกิจการ ให้เป็นไปตามแผนงาน โครงการ หรือมาตรการ ความปลอดภัยในการทำงาน
- แนะนำให้ลูกจ้างปฏิบัติตามข้อบังคับ และคู่มือตามข้อ 3
- แนะนำ ฝึกสอน อบรมลูกจ้าง เพื่อให้การปฏิบัติงานปลอดภัยจากเหตุอันจะทำให้เกิดความไม่ปลอดภัยในการทำงาน
- ตรวจวัด และประเมินสภาพแวดล้อมในการทำงาน หรือดำเนินการร่วมกับบุคคล หรือหน่วยงาน ที่ขึ้นทะเบียนกับกรมสวัสดิการและคุ้มครองแรงงาน เป็นผู้รับรอง หรือตรวจสอบเอกสารหลักฐาน รายงานในการตรวจสอบสภาพแวดล้อมในการทำงาน ภายในสถานประกอบกิจการ
- เสนอแนะต่อนายจ้าง เพื่อให้มีการจัดการด้านความปลอดภัยในการทำงาน ที่เหมาะสมกับสถานประกอบกิจการ และพัฒนาให้มีประสิทธิภาพอย่างต่อเนื่อง

ตรวจสอบ...

10. ตรวจสอบสาเหตุ และวิเคราะห์การประสบอันตราย การเจ็บป่วย หรือการเกิดเหตุเดือดร้อนรำคาญ อันเนื่องมาจากการทำงาน และรายงานผล รวมทั้งเสนอแนะต่อนายจ้าง เพื่อป้องกันการเกิดเหตุโดยไม่ซ้ำซ้ำ
11. รวบรวมสถิติ วิเคราะห์ข้อมูล จัดทำรายงาน และข้อเสนอแนะเกี่ยวกับการประสบอันตราย การเจ็บป่วย หรือการเกิดเหตุเดือดร้อนรำคาญ อันเนื่องมาจากการทำงานของลูกจ้าง
12. ปฏิบัติงานด้านความปลอดภัยในการทำงานอื่น ตามที่นายจ้างมอบหมาย

โดยให้เจ้าหน้าที่ความปลอดภัยในการทำงานระดับวิชาชีพ ต้องปฏิบัติหน้าที่ตามความรับผิดชอบที่ได้กำหนด โดยเคร่งครัด ให้กับบริษัท ไทยโพลีเอททีลีน จำกัด "สำนักงานใหญ่"

ทั้งนี้เริ่มผลตั้งแต่วันที่ 1 เมษายน 2565 เป็นต้นไป

สั่ง ณ วันที่ 1 เมษายน 2565



ภาคผนวก 47

ผลการจัดทำการประเมินอันตรายร้ายแรง



ที่ ออก ๐๓๑๒/

๗๔๑



กองส่งเสริมเทคโนโลยีความปลอดภัยโรงงาน
กรมโรงงานอุตสาหกรรม
ถนนพระรามที่ ๖ แขวงทุ่งพญาไท
เขตราชเทวี กรุงเทพฯ ๑๐๕๐๐

๐ ๕ กรกฎาคม ๒๕๖๔

เรื่อง รายงานการวิเคราะห์ความเสี่ยงจากอันตรายที่อาจเกิดจากการประกอบกิจการโรงงาน

เรียน กรรมการผู้จัดการ บริษัท ไทยโพลิเอททีลีน จำกัด

อ้างถึง หนังสือบริษัท ไทยโพลิเอททีลีน จำกัด ที่ บพพ. ๐๓๒/๒๕๖๔ ลงวันที่ ๒๗ พฤษภาคม ๒๕๖๔

ตามหนังสือที่อ้างถึง ท่านได้ส่งรายงานการวิเคราะห์ความเสี่ยงจากอันตรายที่อาจเกิดจากการประกอบกิจการโรงงานของ บริษัท ไทยโพลิเอททีลีน จำกัด ประกอบกิจการ ๑.ผลิตเม็ดพลาสติกโพลิเอททีลีน ชนิดความหนาแน่นสูง กำลังการผลิต ประมาณ ๕๐๐,๐๐๐ ตัน/ปี ๒.ผลิตเม็ดพลาสติกโพลิโพรพิลีน ชนิด Homo-Polymer ๑๘๓,๙๖๐ ตัน/ปี,ชนิด Co- Polymer ๔๒๙,๒๔๐ ตัน/ปี และผลิตภัณฑ์พลอยได้ (Polymerized Liquid ๔๓๘ ตัน/ปี, Low Polymer ๑๔,๐๐๐ ตัน/ปี, Fouled Hexane ๒,๕๒๐ ตัน/ปี และ PE-Wax ๑๒,๖๐๐ ตัน/ปี) ทะเบียนโรงงาน น.๔๒(๑)-๔/๒๕๕๐-นอล. ตั้งอยู่ เลขที่ ๘๘/๔-๕ ถนนทางหลวงระยอง-สาย ๓๓๔๑ ตำบลมาตาพุด อำเภอเมืองระยอง จังหวัดระยอง นั้น

กองส่งเสริมเทคโนโลยีความปลอดภัยโรงงาน กรมโรงงานอุตสาหกรรม ได้รับรายงานดังกล่าวแล้ว จึงขอให้ท่านปฏิบัติตามมาตรการป้องกันและควบคุมอันตราย และแผนงานบริหารจัดการความเสี่ยงอย่างเคร่งครัด และดำเนินการปรับปรุงรายงานครั้งต่อไปตามที่กำหนดในประกาศกระทรวงอุตสาหกรรม เรื่อง มาตรการคุ้มครองความปลอดภัยในการดำเนินงาน ในส่วนที่เกี่ยวข้อง

๑. โรงที่ ๓ (PP3) มีประเด็นเพิ่มเติม ดังนี้

๑.๑ ปรับปรุงแผนผังโรงงานขนาดมาตราส่วน ๑ : ๑๐๐ หรือขนาดที่เหมาะสม สามารถอ่านได้โดยชัดเจน และแสดงรายละเอียดการติดตั้งอุปกรณ์และเครื่องมือที่เกี่ยวข้องกับความปลอดภัย และสิ่งอื่น ๆ ที่มีความสำคัญ ต่อการเกิด การป้องกันหรือการควบคุมเพลิงไหม้ การระเบิด การรั่วไหลของสารเคมีหรือวัตถุอันตราย

๑.๒ ปรับปรุงบัญชีรายการสิ่งที่เป็นความเสี่ยงและอันตรายให้ครอบคลุมกิจกรรมที่นอกเหนือจากกระบวนการผลิต เช่น อันตรายจากระบบทำความเย็น การผลิตไอน้ำ ระบบไฟฟ้า และระบบซ่อมบำรุง เป็นต้น

๑.๓ ปรับปรุงการชี้บ่งอันตรายด้วยวิธี HAZOP โดยระบุค่าควบคุมให้ครบถ้วน

๑.๔ ทบทวนแผนงานลดความเสี่ยง โดยมาตรการที่ดำเนินการแล้วต้องนำกลับไปพิจารณาประเมินความเสี่ยงว่าลดลงอยู่ในระดับที่ยอมรับได้ หากระดับความเสี่ยงไม่ลดลงให้พิจารณามาตรการอื่นเพิ่มเติม

๑.๕ ระบุรายละเอียดหลักเกณฑ์หรือมาตรฐานที่ใช้ควบคุม และหัวข้อเรื่องที่ควบคุมในแผนบริหารจัดการความเสี่ยงให้ชัดเจน

๑.๖ ระบุความหมายของอักษรย่อที่ใช้

๒. โรงที่ ๔...

-๒-

๒. โรงที่ ๔ (HDPE4) มีประเด็นเพิ่มเติม ดังนี้

๒.๑ ปรับปรุงบัญชีรายการสิ่งที่เป็นความเสี่ยงและอันตรายให้ครอบคลุมทุกกิจกรรมและขั้นตอนกระบวนการผลิต เช่น การทำวัตถุดิบให้บริสุทธิ์

๒.๒ ปรับปรุงผลการศึกษา วิเคราะห์ และทบทวนการดำเนินงานในโรงงานเพื่อการชี้บ่งอันตรายและการประเมินความเสี่ยง ดังนี้

๒.๒.๑ ปรับปรุงการชี้บ่งอันตรายด้วยวิธี HAZOP โดยระบุปัจจัยการผลิต ค่าควบคุม มาตรการป้องกันและควบคุมอันตราย รวมทั้งอ้างอิงหมายเลขแบบแปลนให้ครบถ้วน

๒.๒.๒ ปรับปรุงเหตุการณ์ที่เกิดขึ้นตามมา โดยระบุอันตรายและผลที่เกิดขึ้นตามมาที่เป็นผลจากเหตุการณ์แรกจนถึงอันตรายสุดท้ายที่อาจเกิดขึ้นได้ให้ครบถ้วน และให้ครอบคลุมผลกระทบต่อบุคคล ทรัพย์สิน ชุมชน และสิ่งแวดล้อม

๒.๒.๓ ปรับปรุงการจัดระดับความรุนแรงของเหตุการณ์ให้สอดคล้องกับเหตุการณ์ที่เกิดขึ้นตามมา เช่น กรณีสารเคมีรั่วไหล ไฟไหม้ หรือระเบิด ควรจัดระดับความรุนแรงเป็นระดับ ๓ หรือ ๔

๒.๒.๔ ปรับปรุงการจัดระดับโอกาสในการเกิดเหตุการณ์ให้สอดคล้องกับมาตรการควบคุมและป้องกันอันตราย


๒.๓ ปรับปรุงแผนงานควบคุมความเสี่ยงให้สอดคล้องกับการชี้บ่งอันตรายและประเมินความเสี่ยงที่ได้จัดทำขึ้นใหม่ ทั้งนี้ ให้นำมาตรการป้องกัน/ควบคุม/แก้ไข จากการชี้บ่งอันตรายและประเมินความเสี่ยงทุกข้อมาจัดทำแผนงานควบคุมความเสี่ยง

๒.๔ ระบุรายละเอียดหลักเกณฑ์หรือมาตรฐานที่ใช้ควบคุม และหัวข้อเรื่องที่ควบคุมในแผนบริหารจัดการความเสี่ยงให้ชัดเจน

๒.๕ ระบุความหมายของอักษรย่อที่ใช้

จึงเรียนมาเพื่อทราบ ทั้งนี้ หากมีข้อสงสัยสอบถามรายละเอียดเพิ่มเติมได้ที่ นางนภาพรพรณ นาคสวัสดิ์ และท่านสามารถดูรายละเอียดคู่มือเพิ่มเติมได้ที่ http://php.div.go.th/safety/?page_id=๖๕๔

ขอแสดงความนับถือ



คณะทำงานตรวจรายงานการวิเคราะห์ความเสี่ยง


จากอันตรายที่อาจเกิดจากการประกอบกิจการโรงงาน คณะที่ ๒

โทร. ๐ ๒๒๐๒ ๔๒๒๐


โทรสาร ๐ ๒๓๕๔ ๓๓๔๒

Risk Analysis Summary


(R1,R2,R3,R4) Mode of Operation




Risk Category



All Initiating Event Category



PHA recommendation



Detail	Risk level	Q'ty
PHA recommendations	R1	0
	R2	15
	Total	15




CONFIDENTIAL Do Not Distribute

Scope of PHA: Block Gas Phase Reactor

Following areas are covered under the Gas Phase Reactor PHA:

- Gas Phase Reactor (R-3401, E-3401, C-3401)
- Ethylene stripper (T-3402)




CONFIDENTIAL Do Not Distribute

Scope of PHA: Block Loop reactor

Following areas are covered under the Loop reactor PHA:

- Loop Reactor (R-3201, R-3202)



CONFIDENTIAL Do Not Distribute

Summary of Major Hazard

Fire & explosion from overpressure & leakage

- VCE and Jet fire of C3

The Hazard & Risk has evaluated and put to PHA recommendation by using the Risk matrix

2 Major Consequence from:

R-3401 VCE
T-3402 VCE



26 Hazard scenarios



CONFIDENTIAL Do Not Distribute

Thank You



CONFIDENTIAL Do Not Distribute

Summary of Major Hazard

Fire & explosion from overpressure & leakage

– VCE and Jet fire of C3

The Hazard & Risk has evaluated and put to PHA recommendation by using the Risk matrix

3 Major Consequence from:

R-3201 VCE
R-3202 VCE
D-3202 VCE



48 Hazard scenarios



CONFIDENTIAL Do Not Distribute


Risk Analysis Summary

Mode of operation for SHE concern




Normal operation Startup/Shutdown

Risk category




R1 R2 R3 R4 NO SHE concern

Failure category (All scenarios)



Mechanical system failure Control system failure Human failure External event Total scenarios

PHA Recommendation



R1
R2



Detail	Risk level	Q'ty
PHA recommendations	R1	0
	R2	0
Total		0



CONFIDENTIAL Do Not Distribute



ภาคผนวก 48

Lay Out ที่ตั้งอุปกรณ์ที่สอดคล้องกับมาตรฐาน NFPA/ API





ภาคผนวก 49

เอกสารการรับรองอุปกรณ์ไฟฟ้า



สำนักเทคโนโลยีความปลอดภัย
กรมโรงงานอุตสาหกรรม

สำหรับเจ้าหน้าที่รับเรื่อง

รหัส

เลขที่รับ

วันที่

เอกสารรับรองความปลอดภัยของระบบไฟฟ้า

ข้าพเจ้า.....นายสมเกียรติ ประทุมมิตร.....อายุ.....51.....ปี อาชีพ.....วิศวกรไฟฟ้า
ที่อยู่เลขที่.....79/8.....หมู่ที่.....6.....ตรอก/ซอย.....-.....ถนน.....-.....
แขวง/ตำบล.....บ้านใหม่.....เขต/อำเภอ.....ปากเกร็ด.....จังหวัด.....นนทบุรี
โทรศัพท์.....086-626-6375.....ได้รับใบอนุญาตเป็นผู้ประกอบวิชาชีพวิศวกรรมควบคุม ประเภท.....สามัญ.....วิศวกร
สาขาวิศวกรรมไฟฟ้า แขวงไฟฟ้ากำลัง ตามพระราชบัญญัติวิศวกร พ.ศ.2542
เลขทะเบียน.....สฟก.4690.....ตั้งแต่วันที่.....27 มกราคม 2564.....ถึงวันที่.....26 มกราคม 2569
และไม่อยู่ในระหว่างถูกสั่งพักหรือเพิกถอนใบอนุญาตดังกล่าว พร้อมกันนี้ได้แนบสำเนาใบอนุญาตมาด้วยแล้ว
ข้าพเจ้าได้ตรวจสอบระบบไฟฟ้าโรงงานชื่อ.....บริษัท ไทยโพลิเอททีลีน จำกัด Site#7 Plant PP3
ชื่อผู้ประกอบการโรงงาน.....บริษัท ไทยโพลิเอททีลีน จำกัด Site#7 Plant PP3
ประกอบกิจการ.....ผลิตเม็ดพลาสติกโพลิเอททีลีน.....ทะเบียนโรงงานเลขที่.....น.42(1)-4/2550-นอล.
ตั้งอยู่เลขที่.....88/4-5.....หมู่ที่.....-.....ตรอก/ซอย.....-.....ถนน.....ทางหลวงระยอง-สาย3191
แขวง/ตำบล.....มาบตาพุด.....เขต/อำเภอ.....เมืองระยอง.....จังหวัด.....ระยอง
โทรศัพท์.....0-3868-3393.....เมื่อวันที่.....11.....เดือน.....ตุลาคม.....พ.ศ.....2565

ข้าพเจ้าขอรับรองว่าได้ตรวจสอบระบบไฟฟ้าของโรงงานรายนี้แล้ว ตามความรู้ซึ่งได้ทำดีที่สุดตามหลัก
วิชาชีพและตามมาตรฐานที่อ้างอิง โดยมีผลการตรวจสอบและรายละเอียดตามแบบรายงานการตรวจสอบระบบและ
อุปกรณ์ไฟฟ้ากับแบบแปลนระบบไฟฟ้าพร้อม Single Line Diagram ที่แนบ ซึ่งสามารถใช้งานได้ต่อไปได้อีก 1 ปี
โดยปลอดภัย ทั้งนี้ต้องมีการใช้งานอย่างถูกวิธีและมีการบำรุงรักษาตามหลักวิชาการ ข้าพเจ้าจึงลงลายมือชื่อไว้เป็น
หลักฐาน

ลง
ผู้

ลงชื่อ

วิศวกร



- หมายเหตุ
1. ผู้ตรวจสอบต้องเป็นผู้ได้รับใบอนุญาตให้ประกอบวิชาชีพวิศวกรรมควบคุมตามพระราชบัญญัติ วิศวกร พ.ศ. 2542
 2. ใช้เอกสารรับรองฉบับนี้ 1 ฉบับ ต่อทะเบียนโรงงาน 1 โรง



ภาคผนวก 50
การซีลปั๊มและข้อต่อต่าง ๆ
บริเวณ Polymerization Reactor





ALPHA GROUP CO., LTD.

F.A.R.S.R.T.04 Rev.03 (14 Nov. 2019)



 阿尔法集团有限公司
 ALPHA GROUP CO., LTD.

P-ARS-HT-04 Rev.03 (14 Nov. 2019)



ALPHA GROUP CO., LTD.

[illegible]


 अधिकांश शिक्षण संस्था
 अधिकांश शिक्षण संस्था

[illegible]



PL-ME-F-0085-000PL-ME-F-0085-000PL-ME-F-0085-000

APPROVED BY: *[Signature]* DATE: 2-11-65

MAINTENANCE CHECK SHEET FOR

P-3202

EQ. TYPE: AXIAL PUMP	MODEL:	S/N NO:	MFG: LAWRENTH	PLANT:THP3
START DATE: 05-10-15	FINISH DATE: 03-11-15	MO NO: 1030654522	INSPECTOR NAME: 0071	

Laser Alignment
Spec < 0.05 mm


Coupling targets

	BEFORE REMOVE	FINAL ADJUST
L1	98	98
L2	99	99
L3	99	99
L4	104	100
R1	98	98
R2	105	100
R3	98	100
R4	98	100

Vertical targets	0.01 mm
Horizontal targets	-0.00 mm
	-0.03 mm


MAINTENANCE CHECK SHEET				
PLANT	EQUIPMENT NO.	EQUIPMENT TYPE.	SPEED(RPM)	
MFG.	MODEL NO.	SN.	92264-1	
MO. NO.	START DATE	FINISH DATE	8-11-15	

Check Run Out Shaft



No.1	Before	After	No.2	Before	After
0	0	0	0	0.00	0.00
90	+0.01	+0.01	90	+0.01	+0.01
180	+0.01	+0.01	180	+0.01	+0.01
270	+0.01	+0.01	270	+0.01	+0.01

Check Gap Sleeve & Shaft




Before 0.00 mm. After 0.00 mm.

Checked By: 0071 Date: 8-11-15 Approved By: 0071 Date:

PL-ME-F-0085-000

MAINTENANCE CHECK SHEET				
PLANT	EQUIPMENT NO.	EQUIPMENT TYPE.	SPEED(RPM)	
MFG.	MODEL NO.	SN.	92264-1	
MO. NO.	START DATE	FINISH DATE	8-11-15	


Check Gap Propeller



Torque Bolt Propeller 510 Nm

	Before	After
0	2.50	2.50
90	2.50	2.50
180	2.50	2.50
270	2.50	2.50

Check Shaft End Play



	Before	After
With Mech Seal	0.00	0.03

Not Mech Seal


	Before	After
	0.00	0.09

Checked By: 0071 Date: 8-11-15 Approved By: 0071 Date:

PL-ME-F-0085-000

MAINTENANCE CHECK SHEET				
PLANT	EQUIPMENT NO.	EQUIPMENT TYPE.	AXIAL PUMP	
MFG.	MODEL NO.	SN.	92264-1	
MO. NO.	START DATE	FINISH DATE	8-11-15	

Distance of flange suction & discharge P-3201



Groove face (A) 8 Millimetre(mm.)
Gasket (B) 3 Millimetre(mm.)
A-B = 5 Millimetre(mm.)
Groove face (C) 6.9 Millimetre(mm.)
* Groove C - (A-B) = 1.9 Millimetre(mm.)

Before dis-mounting (Loose bolt)

	0	90	180	270	Remark
Suction flange	8.0	8.1	8.1	8.0	-
Discharge flange	7.2	7.2	7.1	7.2	-

After mounting (torque bolt)

	0	90	180	270	Remark
Suction flange	8.0	8.1	8.0	8.0	OK
Discharge flange	7.2	7.1	7.2	7.2	OK

ALLOWABLE PUMP NOZZLE LOADS (8TH EDITION)

NOZZLE	SUCTION FLANGE	DISCHARGE FLANGE
FX	5000 LBS (22240 N)	5000 LBS (22240 N)
FY	5000 LBS (22240 N)	5000 LBS (22240 N)
FZ	5000 LBS (22240 N)	5000 LBS (22240 N)
FR	5000 LBS (22240 N)	5000 LBS (22240 N)
MX	15000 FT-LBS (20340 N-M)	15000 FT-LBS (20340 N-M)
MY	15000 FT-LBS (20340 N-M)	15000 FT-LBS (20340 N-M)
MZ	15000 FT-LBS (20340 N-M)	15000 FT-LBS (20340 N-M)
MR	18000 FT-LBS (24408 N-M)	18000 FT-LBS (24408 N-M)

Checked By: 0071 Date: 8-11-15 Approved By: 0071 Date:

PL-ME-F-0085-000

MAINTENANCE CHECK SHEET							
PLANT	PP3	EQ. NO.	P-3202	EQ. TYPE.	AXIAL PUMP	MFG.	LAWRENCE
MODEL NO.	SERIES 9500, 8"X8"		SERIAL NO.	92364-1		SPEED(RPM)	1500
START DATE	26/10/65		FINISH DATE	9/11/65		MO. NO.	10310653769

☒ Torque 18.6 N-m (Set screw collar)
☒ Torque 7.9 N-m (Sleeve lock nut)
☒ Shaft support ค้อนหมุนเพล่า
☒ Change O-ring
☒ Torque 339 N-m (Outboard seal bolt)
 Note: Setting plate ออกหลังจาก Lock Mech seal sleeve แป้นกับเพลาลูก
 Static test Mech seal 10 bar 30 นาที drop ไม่เกิน 3 bar

Static test Mech seal 30 bar 30 นาที drop ไม่เกิน 3 bar

Checked By: [Signature] Date: 9/11/65
 Approved By: [Signature] Date: 1/1/65

PL-ME-F-0085-000

1/2

MAINTENANCE CHECK SHEET FOR 528FF3-A3301				
EQ. TYPE: AGITATOR	MODEL:	S/N NO: A-3301	MFG: SAMIC	PLANT: THPP3
START DATE: 26/10/65	FINISH DATE: 2/11/65	MO NO: 10310653769	INSPECTOR NAME: Komsorn P	

GEAR BOX AND COUPLING

- ☒ Check tightness of mounting bolt
- ☒ Check condition of Coupling element and change if damage
- ☒ Check alignment Coupling by stress edge
- ☒ Check run out for Out put shaft by Dial gauge limit 0.05mm.
- ☒ Change lube oil and check level
- ☒ เปลี่ยนน้ำมันหล่อลื่นของ Output shaft gear
- ☒ เปลี่ยนน้ำมันหล่อลื่นของ Input shaft Agitator

TOP BEARING

Shaft OD	Clearance	Bearing ID	Frame ID	Clearance	Bearing OD
Max					
Min					
Actual	0.02	0.02			

Grease type	สภาพการหล่อ	Level	Quantity
SHELL ALVANIA EP2	หล่อ	หล่อ	Actual Spec 0.7 L

- ☒ เปลี่ยนความแน่นของ Bearing Lock nut
- ☒ ไข Bearing Lock washer เติมน้ำมัน Bearing Lock nut คลายตัว
- ☒ เปลี่ยน Oil seal ด้านบนและเปลี่ยนฟลักซ์น้ำมัน Oil seal ใต้ถั่วกลอง
- ☒ เปลี่ยนการสึกหรอของ Shaft ที่สัมผัสกับ Oil seal
- ☒ เปลี่ยนฟลักซ์น้ำมันของ Bearing
- ☒ เปลี่ยน Oil seal ด้านล่างและเปลี่ยนฟลักซ์น้ำมัน Oil seal ใต้ถั่วกลอง
- ☒ เปลี่ยน Torque Bolt
- ☐ เช็ค Radial clearance ของ Bearing _____ mm.

BOTTOM BEARING

Shaft OD	Clearance	Bearing ID	Frame ID	Clearance	Bearing OD
Max					
Min					
Actual	0.02	0.02			

Grease type	สภาพการหล่อ	Level	Quantity
SHELL ALVANIA EP2	หล่อ	หล่อ	Actual Spec 0.7 L

Stuffing box

- ☒ เปลี่ยน Mechanical seal
- ☒ เปลี่ยนความแน่นของ Shaft ด้านที่สัมผัสกับ Mech seal

Approved by: [Signature] Date: 1/1/65

REV. 1, 30/3/2005

PM CHECK SHEET FOR				
EQ. TYPE: Agitator	MODEL NO:	S/N NO: A-3301	MFG:	PLANT: THPP3
START DATE: 26/10/65	FINISH DATE: 2/11/65	MO NO: 10310653769	INSPECTOR NAME: Komsorn P	

FL	ITEM	Operation Description	ทำ	ไม่ทำ	ไม่ตรวจ	ไม่ตรวจ	ไม่ตรวจ	Remark	Int.
A3301	0006	GRINDING OPS DYNAMIC SEPARATOR (SGL)	<input checked="" type="checkbox"/>						12 M.
A3301	0106	GRINDING MOTOR BEARING (DYNAMIC FILT)	<input checked="" type="checkbox"/>					Overhaul Motor	12 M.
A3301	0118	CHECK SEAL OIL LEAK MECHANICAL SEAL	<input checked="" type="checkbox"/>					Change Mech Seal	12 M.
A3301	0128	CHECK OIL PRESSURE LIMIT TANK (CHECKING)	<input checked="" type="checkbox"/>					opt Drain oil and Pot	12 M.
A3301	0138	CHECK SEAL OIL LEVEL PRESSURE SEAL POT	<input checked="" type="checkbox"/>						12 M.
A3301	0148	CLEANING IMPELLER SURFACE	<input checked="" type="checkbox"/>						12 M.
A3301	0158	CHECK COUPLING ELEMENT	<input checked="" type="checkbox"/>					Change Pulley Coupling	12 M.

(Remark) ☒ ทำตามตารางตรวจเช็ค (ถ้าพบข้อบกพร่องให้แก้ไขตามตาราง) ☒ ไม่ทำตามตารางตรวจเช็ค (ถ้าพบข้อบกพร่องให้แก้ไขตามตาราง)

APPROVED BY: [Signature] DATE: 3/11/65

MAINTENANCE CHECK SHEET							
PLANT	PP3	EQ. NO.	A-3301	EQ. TYPE.	DYNAMIC SEPARATOR	MFG.	SAMIC
MODEL NO.			SERIAL NO.			SPEED(RPM)	1500
START DATE	26/10/65		FINISH DATE	2/11/65		MO. NO.	10310653769

RUN OUT CHECK SHEET

ค่าทาง	A	B	C	D
0	0	0	0.00	0
90	-0.02	+0.05	0.00	+0.01
170	0	+0.02	0.00	+0.03
270	+0.07	+0.03	0.00	-0.03

MAINTENANCE CHECK SHEET					
PLANT	PP3	EQ. NO.	A-3301	EQ. TYPE.	DYNAMIC SEPARATOR
MODEL NO.		SERIAL NO.		MFG.	SAMC
START DATE	22/10/65	FINISH DATE	2/11/65	SPEED(RPM)	1500
		MO. NO.	10310653769		

PART BY PART CHECK SHEET

Recon Dynamic Separator Speed

MAINTENANCE CHECK SHEET					
PLANT	PP3	EQ. NO.	A-3301	EQ. TYPE.	DYNAMIC SEPARATOR
MODEL NO.		SERIAL NO.		MFG.	SAMC
START DATE	22/1/65	FINISH DATE	22/1/65	SPEED(RPM)	1500
		MO. NO.	10410001392		

TOP BEARING ASSEMBLY

	Housing ID	Bearing OD	Tolerance	Sleeve OD	Bearing ID	Tolerance
Top	800.01	199.99	(0)-(+0.02)	99.00	95.00	(0)-(+0.02)
Bottom	800.01	199.99		99.99	95.00	

BOTTOM BEARING ASSEMBLY

	Housing ID	Bearing OD	Tolerance	Shaft OD	Bearing ID	Tolerance
Roller Bearing	190.01	199.99	(0)-(+0.02)	90.00	95.00	(0)-(+0.02)

Checked By *ME PP3* Date *22/1/65* Approved *[Signature]* Date *22/01/65*

MAINTENANCE CHECK SHEET					
PLANT	PP3	EQ. NO.	A-3301	EQ. TYPE.	DYNAMIC SEPARATOR
MODEL NO.		SERIAL NO.		MFG.	SAMC
START DATE	22/1/65	FINISH DATE	22/1/65	SPEED(RPM)	1500
		MO. NO.	10410001392		

RUN OUT CHECK

ตำแหน่ง	A	B	C	D	E
0	0	0	0	0	0
90	-1	0	0	0	0
170	0	0	+1	+1	-1
270	0	0	0	0	-3

* Change Bearing, o-ring, oil seal NBN
 * Change Rubber Coupling NBN
 * เปลี่ยนไส้/น้ำมัน Seal
 * Recon ใช้น้ำมัน stock ชั้น 3 #900

MDR COMMUNITY ENTERPRISE CO., LTD.
 1/1 Soi Tonyang, Klongnamhoo Road, Nernpra Muang Rayong 21150
 Tel: (038) 947166, 694435-6 Fax: (038) 694437
 Mobile Phone -081-9830469 E-mail: sarpipulmdr@gmail.com
 www.mdrbalance.com เลขประจำตัวผู้เสียภาษี 0215552001999

ใบเสนอราคา QUOTATION


ชื่อลูกค้า	บริษัท ไทยโพลีเอททีลีน จำกัด	เลขที่	13
ที่อยู่	88/4-5 อ.พนาพร 4 ระยะ 4 - ซอย 3191 ต.พนาพร 4 อ.เมืองระยอง 21150	วันที่	01/006
Address	โทร (038) 937000, แฟกซ์ (038) 915310	วันที่	January 10, 2022
เลขที่อ้างอิงลูกค้า	เลขที่อ้างอิงบริษัท	Sale	เดวิดพัชร
Customer Reference	Our Reference	Mechanic	
PR. NO.:		หมายเลขงาน	DBL-01/057
เลขทะเบียน	083-9756793	Job Number	

รายการสินค้าบริการ	จำนวน	ราคาต่อหน่วย	จำนวนเงิน
Description	Quantity	Unit Price	Amount (Baht)
TAG.NO. A-3301 I. DYNAMIC SHOP BALANCE STANDARD PRICE LIST 2021-2022 อ้างอิงราคาตามใบตอบรับราคาเลขที่: PMM-SCGCH-2021-188 I. W142DYBR00063 : DYN BALC PUMP W (Kgs.)-99	1	7,000.00	7,000.00
รวมเงิน / Sub Total			7,000.00
ภาษีมูลค่าเพิ่ม / Vat 7%			490.00
เงินต้นหรือยกเข้าแบบถาวร			รวมเงินสุทธิ / Net Total
			7,490.00

ผู้สั่งซื้อ / Customer	อนุมัติ โดย / Approved by
วันที่ / Date	วันที่ / Date
	วันที่ / Date January 10, 2022

DYNAMIC BALANCE CERTIFICATE

Customer :	TPE Site 7		Order No :	01/057	
Equipment No :	A-3301		Date :	January 24, 2022	
Description :	AGITATOR IMPELLER		Balance Quality :	ISO 1940	G - 1
Instrument : CX Balancer Serial No. I246		Sensor : AC102-1A		Test Date : January 15, 2022	
Rotor weights :	98	KGS.	Machine Speed :	1478	RPM.
Balance Tolerance :	316.75	Gram-mm.	Balance Speed :	900	RPM.
Left : Correction Radius:	100	mm.	Right : Correction Radius	110	mm.
Left Tolerance :	3.167	Grams	Right Tolerance :	2.880	Grams.



$$m = \frac{M \cdot G \cdot 30000}{R \cdot \pi \cdot 2 \cdot N}$$

$$m = 30000 \times M \times G / 6.28 \times R \times N$$

$$m = 4777 \times M \times G / R \times N$$

m = Balance Tolerance (Gram-mm.)

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

M = Rotor Weights (KGS.)

N = Machine Speed (RPM).





Radius	300 mm.	PLANE 1		PLANE 2	
Long	1900 mm.	Amplitude	Degrees	Amplitude	Degrees
Original Condition :	mm/sec	34.00	271	0.87	339
Correction Callout :	Grams	0.00	0	6.00	150
Final Condition :	mm/sec	0.16	285	0.15	342
Final Residual Unbalance :	Grams	0.00	0	0.31	150


Remarks AGITATOR WAS BALANCED BY GRINDING WEIGHT 6 GRAMS AT 150 DEGREE ON IMPELLER.

AFTER BALANCE, AGITATOR IS IN SATISFACTORY CONDITION.

COMPLETE BY			
SIGNATURE			
NAME			
DATE			



	Temp	Temp	pressure	Temp	Temp	pressure
13087/6/11/1510	1	2	3	4	5	6
16.10	34	35	0	38	30	26
16.15	34	35	1	45	30	2
16.25	35	39	1	48	39	2
16.35	38	44	1	52	40	2
16.55	30.5	38.8	1	32	26	2
16.50	32	35	1.8	42	42	2
16.00	34	39	1.8	5	35	2



These recommendations are also relevant to other research on adolescent users of mass media communication, who may benefit from the opportunity to participate in a supportive association.



ภาคผนวก 51

ระบบดับเพลิงที่ออกแบบได้มาตรฐาน NFPA/ API





Project : TPE HDPE#4 Project
Job No. : HC3910
Doc. No. : 003AS1001

INDIVIDUAL SPECIFICATION FOR FIRE FIGHTING EQUIPMENT

C O N T E N T S

	<u>PAGE</u>
1. GENERAL.....	1
2. TECHNICAL REQUIREMENTS.....	2

ATTACHMENT :

- 1 : Water Hydrant
- 2 : Water Monitor
- 3 : Fire Hose Cabinet
- 4 : Water Nozzle
- 5 : Indoor Hydrant
- 6 : Dry Chemical Fire Extinguisher
- 7 : CO2 Fire Extinguisher
- 8 : Foam/Water Monitor
- 9 : Piping & Instrument Diagram Section 800 Utilities Fire Fighting System



Project : TPE HDPE#4 Project
Job No. : HC3910
Doc. No. : 003AS1001

Revision List

Rev No.	Date	Item	Page	Description
0	2007-12-28	All	All	Original Issue
1	2008-4-28	1	2	Add Potable Extinguisher
		2	4	Change quantity and rate capacity
		3	8 & 9	Add Foam/Water Monitor Data Sheet
		4	10	Replace P&ID
2	2008-05-22	1	3 to 7	Incorporated comment in HD4-TPE-MES-L-542
		2	8, 9	Added data sheet of fire extinguisher
3	2009-06-24	1	4 & 10	Corrected normal pressure in operating conditions
		2	7	Revised valve type and connection
		3	12	Replace P&ID



Project : TPE HDPE#4 Project
 Job No. : HC3910
 Doc. No. : 003AS1001

2 TECHNICAL REQUIREMENTS

The following item, but not limited to, shall be supplied:

- (a) Water Hydrant
- (b) Water Monitor
- (c) Fire Hose Cabinet
- (d) Water Nozzle
- (e) Indoor Hydrant
- (f) Potable Extinguisher

For detailed specifications, refer to the attached data sheets.



Project : TPE HDPE#4 Project
 Job No. : HC3910
 Doc. No. : 003AS1001

1. GENERAL

1.1 Scope

1.1.1 This specification covers the specific requirements for design, material, manufacturing, marking, inspection and testing of Fire Fighting Equipments.

1.1.2 If any conflict exists between this specification and the related documents described in paragraph 1.2, priority is given in the following order.

- 1) Purchase Specification
- 2) This Specification
- 3) Project Specifications
- 4) Codes and Standards
- 5) Manufacturer's Standards

1.2 Referenced Documents

The following documents shall form an integral part of this specification to the extent specified herein.

1.2.1 Codes and standards

Any codes and standards to be used shall be the latest editions issued before April 2007.

1) ASME Standards

- B1.1 Unified Inch Screw Threads, UN and UNR Thread Form
- B1.20.1 Pipe Threads, General Purpose, Inch
- B16.11 Forged Steel Fittings, Socket-Welding and Threaded
- B16.5 Pipe Flanges and Flanged Fittings
- B18.2.1 Square and Hex Bolts and Screws Inch Series
- B18.2.2 Square and Hex Nuts
- B31.3 Process Piping
- B46.1 Surface Texture, Surface Roughness, Waviness and Lay

2) ASTM Standard

3) NFPA

- 10 Portable Fire Extinguisher
- 13 Installation of Sprinkler System
- 14 Installation of Standpipe and Hose System
- 15 Water Spray Fixed System for Fire Protection
- 24 Installation of Private Fire Service Main and Their Appurtenances

1.2.2 Project Specification

- 1) Engineering Specification for Fire Fighting and Fire Protection(Doc. No. SP-002)

WATER MONITOR DATA SHEET

Attachment-2

SERVICE : Water Monitor		LOCATION : <input checked="" type="checkbox"/> Outdoor <input type="checkbox"/> Indoor		
ITEM NO. :		MFR'S NAME :		
TYPE : <input checked="" type="checkbox"/> Fixed <input type="checkbox"/> Portable <input type="checkbox"/> Oscillating		MFR'S MODEL NO. :		
<input type="checkbox"/> Remote Control				
NO. REQUIRED : 9 pcs (include spare)				
OPERATING CONDITIONS				
Fluid Handled	<input checked="" type="checkbox"/> Fresh Water <input type="checkbox"/> Sea Water <input type="checkbox"/> Air Foam Solution			
Temperature	Design 65.0 °C, Nor 35.0 °C			
Pressure	Design 16.0 kg/cm ² , Normal 10.0 kg/cm ²			
DESIGN FEATURES				
Body	Operation Type	<input type="checkbox"/> NA <input checked="" type="checkbox"/> Lever <input type="checkbox"/> Gear <input checked="" type="checkbox"/> Manual <input type="checkbox"/> Remote		
	Oscillating Driving Mechanism	<input checked="" type="checkbox"/> NA <input type="checkbox"/> Water Screw <input type="checkbox"/> Piston Type <input type="checkbox"/> Other		
	Changeover Switch for Oscillat'g/Manual	<input checked="" type="checkbox"/> NA <input type="checkbox"/> Required		
	Movement	Horizontally : 360 deg Vertically : ~30 to 90 deg		
	Connector	Inlet Connector	Flange <input type="checkbox"/> NA <input checked="" type="checkbox"/> Yes, Size : 4" Rating : ANSI 150# RF	
		Coupling	<input checked="" type="checkbox"/> NA <input type="checkbox"/> Yes, Size : No. :	
			Shutoff Valve <input type="checkbox"/> Built-in <input checked="" type="checkbox"/> Separate : Ball Valve <input type="checkbox"/> None	
	Nozzle	Type	<input type="checkbox"/> Fog <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Fog & Straight <input type="checkbox"/> Fog & Straight Shut-off	
		Connector	Size : 2-1/2"	
			<input type="checkbox"/> Instant <input checked="" type="checkbox"/> Threaded <input type="checkbox"/> Male <input type="checkbox"/> Female	
Rated Capacity		2,840 L/min. @ 7 kg/cm ² G at Monitor Inlet Connection		
Reach		70m @ 7 kg/cm ² G at Monitor Inlet Connection		
ACCESSORIES				
<input type="checkbox"/> Cap(Plug) & Chain <input checked="" type="checkbox"/> Flange Gasket <input type="checkbox"/> Companion Flange <input type="checkbox"/> Nozzle Cap				
<input checked="" type="checkbox"/> Coupling Gasket <input checked="" type="checkbox"/> Flange bolt Nut <input checked="" type="checkbox"/> Ball Valve 4" <input type="checkbox"/> Pick-up Tube				
<input type="checkbox"/> Hydraulic Tube Bundle <input type="checkbox"/>				
<input type="checkbox"/>				
MATERIALS				
Monitor Body	<input type="checkbox"/> Cast <input type="checkbox"/> Bronze <input checked="" type="checkbox"/> Brass <input type="checkbox"/> MFR			
Nozzle	<input type="checkbox"/> Bronze <input checked="" type="checkbox"/> Brass <input type="checkbox"/> Aluminum Alloy <input type="checkbox"/> MFR			
Coupling	<input type="checkbox"/> Bronze <input checked="" type="checkbox"/> Brass <input type="checkbox"/> Aluminum Alloy <input type="checkbox"/> MFR			
Ball Valve	MFR			
TEST & INSPECTION				
Dimensions & Workmanship : <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No				
Hydrostatic Test : <input checked="" type="checkbox"/> Yes, MFR kg/cm ² <input type="checkbox"/> No				
Performance Test : <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
SPARE PARTS				
<input checked="" type="checkbox"/> Coupling Gasket : %		Monitor Body : <input type="checkbox"/> Yes, <input type="checkbox"/> No		
<input type="checkbox"/> Pick-up Tube :		Nozzle : <input type="checkbox"/> Yes, <input type="checkbox"/> No		
<input checked="" type="checkbox"/> Flange Gasket :		Coupling : <input type="checkbox"/> Yes, <input type="checkbox"/> No		
<input type="checkbox"/>		Control Panel : <input type="checkbox"/> Yes, <input type="checkbox"/> No		
<input type="checkbox"/>				
UNIT WEIGHT	MFR kg			
REMARKS				
MFR : By Manufacturer				
NA : Not Applicable				
1. Vendor to submit the discharge performance curve for monitor.				
2. Vendor to recommend the suitable material to satisfy the required design pressure.				

WATER HYDRANT DATA SHEET

Attachment-1

SERVICE : Water Hydrant (3-way)		LOCATION : <input checked="" type="checkbox"/> Outdoor <input type="checkbox"/> Indoor		
ITEM NO. :		MFR'S NAME :		
TYPE : <input checked="" type="checkbox"/> 3 Way <input checked="" type="checkbox"/> Pillar <input type="checkbox"/> Subsurface		MFR'S MODEL NO. :		
<input type="checkbox"/> Dry Barrel <input checked="" type="checkbox"/> Wet Barrel				
NO. REQUIRED : 21 pcs (include spare)				
OPERATING CONDITIONS				
Fluid Handled	<input checked="" type="checkbox"/> Fresh Water <input type="checkbox"/> Sea Water <input type="checkbox"/> Air Foam Solution			
Temperature	Design 65.0 °C, Normal 35.0 °C			
Pressure	Design 16.0 kg/cm ² , Normal 10.0 kg/cm ²			
Fire Water Main	Size 6 inch(es) <input checked="" type="checkbox"/> Aboveground <input type="checkbox"/> Underground (depth m)			
DESIGN FEATURES				
Connector	Flange Connector To Fire Main	Flange	Size : 6 inch, Rating : ANSI 150#, RF	
	Hose Connector	Main Valve	<input checked="" type="checkbox"/> NA <input type="checkbox"/> Built-in <input type="checkbox"/> Separate <input type="checkbox"/>	
		Coupling	Size : 1-1/2 inch, No. : 2 pcs Type : <input type="checkbox"/> JIS <input type="checkbox"/> BS <input checked="" type="checkbox"/> NH <input type="checkbox"/> DIN <input type="checkbox"/> NF Height From Ground Level : MFR mm	
		Valve	<input type="checkbox"/> NA <input type="checkbox"/> Built-in <input checked="" type="checkbox"/> Separate <input type="checkbox"/>	
	Pumper Connector	Valve	<input type="checkbox"/> Built-in <input checked="" type="checkbox"/> Separate	
		Coupling	Size : 4 inch, No. : 1 pc Type : <input type="checkbox"/> JIS <input type="checkbox"/> BS <input checked="" type="checkbox"/> NH <input type="checkbox"/> DIN <input type="checkbox"/> NF Height From Ground Level : MFR mm	
		Valve	<input type="checkbox"/> NA <input type="checkbox"/> Built-in <input checked="" type="checkbox"/> Separate <input type="checkbox"/>	
		Valve	<input type="checkbox"/> Built-in <input checked="" type="checkbox"/> Separate	
	ACCESSORIES			
	<input type="checkbox"/> Companion Flange <input checked="" type="checkbox"/> Hose Coupling Gasket <input type="checkbox"/> Elbow & Support <input checked="" type="checkbox"/> Auto Drain Valve			
<input checked="" type="checkbox"/> Cap(Plug) & Chain <input type="checkbox"/> Anchor Bolt & nut <input checked="" type="checkbox"/> Flange bolt Nut <input checked="" type="checkbox"/> Main Flange Gasket				
<input checked="" type="checkbox"/> Hydrant Wrench <input type="checkbox"/> Coupling Spanner Wrench <input type="checkbox"/>				
MATERIALS				
Hydrant Body	Carbon Steel or MFR			
Main connector	Flange	Carbon Steel or MFR		
Rose	Coupling	<input type="checkbox"/> Bronze <input checked="" type="checkbox"/> Brass <input type="checkbox"/> MFR		
Connector	Valve	MFR		
Pumper	Coupling	<input type="checkbox"/> Bronze <input checked="" type="checkbox"/> Brass <input type="checkbox"/> MFR		
Connector	Valve	MFR		
Cap	<input type="checkbox"/> Bronze <input checked="" type="checkbox"/> Brass <input type="checkbox"/> MFR			
Chain	<input checked="" type="checkbox"/> Stainless Steel			
TEST & INSPECTION		PAINTING		
Dimensions & Workmanship : <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Body : Yes: Red <input type="checkbox"/> No		
Hydrostatic Test : <input checked="" type="checkbox"/> Yes MFR kg/cm ² <input type="checkbox"/> No				
SPARE PARTS				
<input checked="" type="checkbox"/> Hose Coupling Gasket : 100 % <input checked="" type="checkbox"/> Flange Gasket : MFR <input checked="" type="checkbox"/> 1-1/2" Valve with Coupling : MFR				
<input checked="" type="checkbox"/> Main Valve Seat Packing : MFR <input type="checkbox"/>				
UNIT WEIGHT	MFR kg			
REMARKS				
MFR : Manufacturer shall recommend the specification.				
1. Hydrant shall be painted with red for corrosion protection.				

WATER NOZZLE DATA SHEET

Attachment-4

SERVICE : Water Nozzle		LOCATION : <input checked="" type="checkbox"/> Outdoor <input type="checkbox"/> Indoor	
ITEM NO. :		MFR'S NAME :	
TYPE :		MFR'S MODEL NO. :	
NO. REQUIRED : Refer to Attachment-3			
OPERATING CONDITIONS			
Fluid Handled	<input checked="" type="checkbox"/> Fresh Water <input type="checkbox"/> Sea Water <input type="checkbox"/> Air Foam Solution		
Temperature	Design 65.0 °C, Normal 35.0 °C		
Pressure	Design 16.0 kg/cm ² , Normal 10.0 kg/cm ²		
DESIGN FEATURES			
Type	<input type="checkbox"/> Fog <input type="checkbox"/> Straight <input type="checkbox"/> Fog & Straight (Combination type) <input checked="" type="checkbox"/> Fog, Straight & Shut-off (gun / 3 position type)		
Hose Coupling	Size 1-1/2 inch		
	Type <input type="checkbox"/> JIS <input type="checkbox"/> BS <input checked="" type="checkbox"/> NH <input type="checkbox"/> DIN <input type="checkbox"/> NF		
Rated Capacity	480 L/min. @ 7.0 kg/cm ² G		
ACCESSORIES			
<input type="checkbox"/> Hanger Belt <input type="checkbox"/> Operation Hanger <input type="checkbox"/>			
<input checked="" type="checkbox"/> MFR <input type="checkbox"/>			
MATERIALS			
Nozzle Tip	<input type="checkbox"/> Bronze <input type="checkbox"/> Brass <input type="checkbox"/> Aluminum Alloy <input checked="" type="checkbox"/> MFR		
Play Pipe	<input type="checkbox"/> Bronze <input type="checkbox"/> Brass <input type="checkbox"/> Aluminum Alloy <input checked="" type="checkbox"/> MFR		
Coupling	<input type="checkbox"/> Bronze <input type="checkbox"/> Brass <input type="checkbox"/> Aluminum Alloy <input checked="" type="checkbox"/> MFR		
TEST & INSPECTION			
Dimensions & Workmanship : <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Performance Test : <input type="checkbox"/> Yes, kg/cm ² G <input checked="" type="checkbox"/> No	
SPARE PARTS		PAINTING	
<input checked="" type="checkbox"/> Hose Coupling Gasket : %		Nozzle Tip : <input type="checkbox"/> Yes, <input type="checkbox"/> No	
<input checked="" type="checkbox"/> Nozzle Coupling Gasket : %		Play Pipe : <input type="checkbox"/> Yes, <input type="checkbox"/> No	
<input type="checkbox"/>		Coupling : <input type="checkbox"/> Yes, <input type="checkbox"/> No	
<input type="checkbox"/>			
UNIT WEIGHT	MFR kg		
REMARKS			
MFR : By Manufacturer			
NA : Not Applicable			
Water nozzle type shall be complied with SP-002.			

FIRE HOSE CABINET DATA SHEET

Attachment-3

[illegible]

Dry Chemical FIRE EXTINGUISHER DATA SHEET

Attachment-6

[illegible]

INDOOR HYDRANT DATA SHEET

Attachment-5

SERVICE :		LOCATION : <input type="checkbox"/> Outdoor <input checked="" type="checkbox"/> Indoor		
ITEM NO. :		MFR'S NAME :		
TYPE : Class II type according to NPFA 14		MFR'S MODEL NO. :		
NO. REQUIRED : 6 pcs (include spare)				
OPERATING CONDITIONS				
Fluid Handled	<input checked="" type="checkbox"/> Fresh Water <input type="checkbox"/> Sea Water <input type="checkbox"/> Air Foam Solution			
Temperature	Design 65.0 °C, Normal 35.0 °C			
Pressure	Design 16.0 kg/cm ² , Normal 7.0 kg/cm ²			
DESIGN FEATURES				
Connector	Type	<input type="checkbox"/> Recessed Type <input type="checkbox"/> Self-standing Type <input checked="" type="checkbox"/> Wall-mounted Type <input type="checkbox"/>		
	Door	<input type="checkbox"/> Hinged Right <input type="checkbox"/> Hinged Left <input type="checkbox"/> Double Hinged <input checked="" type="checkbox"/> MFR		
	Support	<input checked="" type="checkbox"/> Leg <input type="checkbox"/> Lug <input type="checkbox"/> Not Required <input type="checkbox"/>		
	Dimension	W MFR mm x L MFR mm x H MFR mm		
	Shelves or Racks	Item to be Stored	Specification	Quantity
		<input checked="" type="checkbox"/> Fire Hose (hose reel type)	1-1/2 inch x 20 m	1pc
		<input checked="" type="checkbox"/> Water Nozzle	1-1/2 inch	1pc
<input type="checkbox"/> Coupling Spanner Wrench				
DESIGN FEATURES				
Nozzle	Type	<input type="checkbox"/> Fog <input type="checkbox"/> Straight <input type="checkbox"/> Fog & Straight (Combination type) <input checked="" type="checkbox"/> Fog, Straight & Shut-off (gun / 3 position type)		
	Coupling	Size	1-1/2 inch	
		Type	<input type="checkbox"/> JIS <input type="checkbox"/> BS <input checked="" type="checkbox"/> NH <input type="checkbox"/> DIN <input type="checkbox"/> NF	
	Rated Capacity	480 L/min. @ 4.5 kg/cm ² G (with 20m discharge range at least)		
Hydrant	Type	<input checked="" type="checkbox"/> 90° Angle Valve <input type="checkbox"/> Gate valve		
	Piping Connector	Size	1-1/2 inch	
		Type	<input type="checkbox"/> NPT <input type="checkbox"/> PT <input type="checkbox"/> Male <input type="checkbox"/> Female <input checked="" type="checkbox"/> ANSI 150# RF	
Piping Connection	<input type="checkbox"/> Right Side <input type="checkbox"/> Left Side <input type="checkbox"/> Rear Side <input checked="" type="checkbox"/> MFR			
ACCESSORIES				
<input checked="" type="checkbox"/> Drilling Expansion Bolt & Nut <input type="checkbox"/> <input type="checkbox"/>				
<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>				
MATERIALS				
Hydrant Box	<input checked="" type="checkbox"/> Steel (min MFR mm ²) <input type="checkbox"/>		Hinge <input checked="" type="checkbox"/> Stainless Steel	
Shelves or Racks	<input checked="" type="checkbox"/> Steel <input type="checkbox"/>		Knob <input checked="" type="checkbox"/> Stainless Steel	
Legs	<input checked="" type="checkbox"/> Steel <input type="checkbox"/>			
Hydrant Valve	<input type="checkbox"/> Brass <input type="checkbox"/> Bronze <input checked="" type="checkbox"/> MFR			
TEST & INSPECTION				
Dimensions & Workmanship : <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Hydrostatic Test : <input checked="" type="checkbox"/> Yes kg/cm ² <input type="checkbox"/> No		
SPARE PARTS		PAINTING		
<input checked="" type="checkbox"/> Hose Coupling Gasket : 100 # <input type="checkbox"/> Hydrant Valve		Cabinet	Internal <input checked="" type="checkbox"/> Yes, MFR <input type="checkbox"/> No External <input checked="" type="checkbox"/> Yes, MFR <input type="checkbox"/> No	
		Legs	<input checked="" type="checkbox"/> Yes, MFR <input type="checkbox"/> No	
		Letter	<input checked="" type="checkbox"/> Yes, MFR <input type="checkbox"/> No	
UNIT WEIGHT		MFR kg		
REMARKS				
Water nozzle shall be complied with SP-002				

FOAM/WATER MONITOR DATA SHEET


Attachment-8

SERVICE : Foam/Water Monitor		LOCATION : <input type="checkbox"/> Outdoor <input type="checkbox"/> Indoor	
ITEM NO. :		MFR'S NAME :	
TYPE : <input checked="" type="checkbox"/> Fixed <input type="checkbox"/> Portable <input type="checkbox"/> Oscillating		MFR'S MODEL NO. :	
<input type="checkbox"/> Remote Control			
NO. REQUIRED : 2 pcs		(include spare)	
OPERATING CONDITIONS			
Fluid Handled		<input checked="" type="checkbox"/> Fresh Water <input type="checkbox"/> Sea Water <input checked="" type="checkbox"/> Air Foam Solution	
Temperature		Design 65.0 °C, Nor 35.0 °C	
Pressure		Design 16.0 kg/cm ² , Normal 10.0 kg/cm ²	
DESIGN FEATURES			
Body	Operation Type		<input type="checkbox"/> NA <input checked="" type="checkbox"/> Lever <input type="checkbox"/> Gear <input checked="" type="checkbox"/> Manual <input type="checkbox"/> Remote
	Oscillating Driving Mechanism		<input checked="" type="checkbox"/> NA <input type="checkbox"/> Water Screw <input type="checkbox"/> Piston Type <input type="checkbox"/> Other
	Changeover Switch for Oscillat'g/Manual		<input checked="" type="checkbox"/> NA <input type="checkbox"/> Required
	Movement		Horizontally : 360 deg Vertically : -30 to 90 deg
	Connector	Inlet Connector (Water)	Flange <input type="checkbox"/> NA <input checked="" type="checkbox"/> Yes, Size : 4" Rating : ANSI 150# RF Coupling <input checked="" type="checkbox"/> NA <input type="checkbox"/> Yes, Size : No, : Shutoff Valve <input type="checkbox"/> Built-in <input checked="" type="checkbox"/> Separate : Ball Valve <input type="checkbox"/> None
		Inlet Connector (Foam)	Pick-up tube type
		Type	<input type="checkbox"/> Fog <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Fog & Straight <input type="checkbox"/> Fog & Straight Shut-off <input checked="" type="checkbox"/> Foam/Water <input checked="" type="checkbox"/> Built-in air foam maker <input checked="" type="checkbox"/> Built-in inductor with shut-off valve
	Nozzle	Connector	Size : 2-1/2" <input type="checkbox"/> Instant <input checked="" type="checkbox"/> Threaded <input type="checkbox"/> Male <input type="checkbox"/> Female <input type="checkbox"/> JIS <input type="checkbox"/> BS <input type="checkbox"/> DIN <input checked="" type="checkbox"/> NPT
	Rated Capacity		2,840 L/min. @ 7 kg/cm ² G at Monitor Inlet Connection
Reach		70m @ 7 kg/cm ² G at Monitor Inlet Connection	
ACCESSORIES			
<input type="checkbox"/> Cap(Plug) & Chain		<input checked="" type="checkbox"/> Flange Gasket <input type="checkbox"/> Companion Flange <input type="checkbox"/> Nozzle Cap	
<input checked="" type="checkbox"/> Coupling Gasket		<input type="checkbox"/> Flange bolt Nut <input checked="" type="checkbox"/> Ball Valve 4" <input checked="" type="checkbox"/> Pick-up Tube	
<input type="checkbox"/> Hydraulic Tube Bundle		<input type="checkbox"/> <input type="checkbox"/>	
<input type="checkbox"/>		<input type="checkbox"/>	
MATERIALS			
Monitor Body		<input type="checkbox"/> Cast <input type="checkbox"/> Bronze <input type="checkbox"/> Brass <input checked="" type="checkbox"/> MFR	
Nozzle		<input type="checkbox"/> Bronze <input type="checkbox"/> Brass <input type="checkbox"/> Aluminum Alloy <input checked="" type="checkbox"/> MFR	
Coupling		<input type="checkbox"/> Bronze <input type="checkbox"/> Brass <input type="checkbox"/> Aluminum Alloy <input checked="" type="checkbox"/> MFR	
Ball Valve		MFR	
Pick-up tube		MFR	
TEST & INSPECTION			
Dimensions & Workmanship : <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
Hydrostatic Test : <input checked="" type="checkbox"/> Yes, MFR kg/cm ² G <input type="checkbox"/> No			
Performance Test : <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			

CO2 FIRE EXTINGUISHER DATA SHEET

Attachment-7

[illegible]



FOAM/WATER MONITOR DATA SHEET

Attachment-8

SPARE PARTS		PAINTING	
<input checked="" type="checkbox"/> Coupling Gasket :	1/2	Monitor Body :	<input type="checkbox"/> Yes, <input type="checkbox"/> No
<input type="checkbox"/> Pick-up Tube :		Nozzle :	<input type="checkbox"/> Yes, <input type="checkbox"/> No
<input checked="" type="checkbox"/> Flange Gasket :		Coupling :	<input type="checkbox"/> Yes, <input type="checkbox"/> No
<input type="checkbox"/>		Control Panel :	<input type="checkbox"/> Yes, <input type="checkbox"/> No
<input type="checkbox"/>			
UNIT WEIGHT		MFR kg	
REMARKS			
MFR : By Manufacturer			
NA : Not Applicable			
1. Vendor to submit the discharge performance curve for monitor.			
2. Vendor to recommend the suitable material to satisfy the required design pressure.			



ภาคผนวก 52
เอกสารเกี่ยวกับแนวท่อขนส่งวัตถุดิบ





ภาคผนวก 52-1
มาตรการด้านความปลอดภัยบริเวณแนวท่อขนส่ง



SERVICE SOLUTION: INSPECTION FOR ABOVEGROUND PIPELINES



1. Visual Inspection

Visual inspection – rust, coating damages, trees, piping guide and support, etc.



2. Insulation Inspection

Visual inspection – insulation damages.
Dismantle insulation for CUI if damages found (case by case)



3. Portable Gas Detector

Survey entire pipelines' routes by using portable gas detector to detect for invisible Hydrocarbon leakages.



4. Soap Solution Test

Using soap solution to test for any leakages at all accessible valve, flange, vent/drain without using scaffolding by monthly.



5. Soap Solution Test

Using soap solution to test for any leakages at all accessible valve, flange, vent/drain with using scaffolding by half-year.



6. Pipe Surface Thickness: UTM

Annually measure pipe surface thickness for tracking pipe remaining life time.
Criteria: 1 point / 2 km / pipe



7. Welding Inspection: MT/PT

Annually random welding seam inspection using MT or PT.
Criteria: 1 point / pipe-year



8. Pipe Coating Thickness: DFT

Annually measure pipe coating thickness.
Criteria: 1 location / 2 km / pipe

SERVICE SOLUTION: INSPECTION FOR UNDERGROUND PIPELINES



1. Pipeline Settlement

Visual inspect for pipeline settlement and soil erosion.
Criteria: Record by level (scope) annually.



2. Pipe to Soil Potential

Measure pipe to soil potential using high impedance digital multi-meter with Copper / Copper-two Sulphate reference electrode.
Normal condition: 850 – 1200 mV.



2. Pipe to Soil Potential



3. Insulation Flange Testing

Using insulation tester to test insulation flange. If insulate property fail, it will effect cathodic system life time.



4. Right of Way Patrol

Secure land and visual inspect for abnormality condition.



5. Tracer Leak Detector

Using portable gas detector to inspect at trace leak detector for underground leakage tracing.



6. Leakage Inspection

Visual inspection for leakage using soap solution.




7. Vent Sleeve Inspection

Using portable gas detector to inspect at vent sleeve pipe for underground leakage tracing at crossing area (roads, canals).



ภาคผนวก 52-2
Work Permit บริเวณแนวท่อขนส่ง





บริษัท DTTC/CPE

เลขที่ใบอนุญาต RPL 1929/๒๕๖

ใบขออนุญาตทำงาน / Work Permit

☐ งานทั่วไป (Cold Work) ☒ งานที่อาจก่อให้เกิดความร้อน (Hot work class II) ☐ งานที่ก่อให้เกิดประกายไฟ (Hot work class I) ☐ งานอับอากาศ (Confined Space Work)

1. การขออนุญาตทำงาน : Work Permit Requisition (ส่วนที่ 1 โดย Permit Requester)

ขออนุญาตทำงานวันที่ 12/07/65
ช่วงเวลาในการขออนุญาตทำงาน : Duration of Permit เริ่มตั้งแต่เวลา 09:00 ถึงเวลา 17:00
1.1 Permit Requester (ชื่อ-สกุล) นายสมชาย ใจดี ในตำแหน่ง ช่างเทคนิค ชื่อบริษัท DTTC/CPE หน่วยงาน PTTEC/CPE
1.2 มีความประสงค์จะขออนุญาตทำงาน ซ่อมแซมและเปลี่ยนท่อส่งก๊าซ PTTEC สถานที่ทำงาน Corridor 1-4
หมายเลขอุปกรณ์ W/S Pipeline PTTEC สถานการณ์ Corridor 1-4
เครื่องจักรหรือเครื่องมือหลักที่ใช้ในงานคือ เลเซอร์ DCVC, CIPS, ท่อเหล็ก
ชื่อบริษัทผู้รับจ้าง PTTEC/CPE จำนวนผู้ปฏิบัติงาน 3
1.3 Safety Lead (ชื่อ-สกุล) นายสมชาย ใจดี
1.4 เอกสารประกอบขออนุญาต
เอกสารแนบ ☒ การวิเคราะห์งานเพื่อความปลอดภัยและสิ่งแวดล้อม (JSA) ☒ ราชข้อปฏิบัติงาน ☐ Safety Data Sheet (SDS) (ถ้ามี)
☐ ราชการแผนผังเครื่องมือ - อุปกรณ์ (ถ้ามี) ☒ Plot plan (ถ้ามี) ☐ อื่นๆ
งานที่ต้องได้รับรองความปลอดภัยในการทำงาน (Safe Work Check list) - Job Types
☐ งานที่มีความร้อนหรือประกายไฟ ☐ งานในพื้นที่อับอากาศ ☐ งานบนที่สูง > 1.8 เมตร ☐ งานขุด ☐ งานที่เกี่ยวข้องกับแรงดันสูง
☐ งานของหนัก (Lifting Plan) ☐ งานนำรถเข้ากระบวนการผลิต ☐ งานประต่อน้ำ ☐ งานที่เกี่ยวข้องกับรังสี ☒ งานที่เกี่ยวข้องกับไฟฟ้า
☐ อื่นๆ
1.5 สารเคมีสุดท้ายที่อยู่ในกระบวนการ หรือสารเคมีเฉพาะอย่างที่ใช้สำหรับงานที่ขออนุญาต ☐ ไม่เกี่ยวข้อง
สารเคมี (ชื่อ) _____
1.6 กำหนดมาตรการความปลอดภัยส่วนบุคคล ที่จะต้องเปิดและ / หรืออุปกรณ์คุ้มครองความปลอดภัยปฏิบัติงาน (ถ้ามี) และขณะปฏิบัติงาน
☒ อุปกรณ์ป้องกันศีรษะ ระบุ หมวกนิรภัย ☐ อุปกรณ์ป้องกันมือ ระบุ _____
☒ อุปกรณ์ป้องกันใบหน้าและดวงตา ระบุ แว่นตา ☐ อุปกรณ์ป้องกันการหายใจ ระบุ _____
☐ อุปกรณ์ป้องกันมือ ระบุ _____ ☐ อุปกรณ์ป้องกันลำตัว ระบุ _____
1.7 ลงชื่อผู้ตรวจสอบความปลอดภัยและมาตรการการขออนุญาตทำงาน (วันที่รับ Permit Requester)

2. การอนุญาตทำงาน : Permit Initial Approval (ส่วนที่ 2 โดย Permit Verifier)

☐ Simple Lock No. ☐ ข้อจำกัดการเข้าถึง Gas & Condition ☐ แจ้งให้พื้นที่อื่นที่ได้รับผลกระทบทราบ ☒ ตรวจสอบงานโดยเจ้าของพื้นที่ที่ถูกต้อง 4 ขน.
☐ Complex Lock Box No. ☒ ตรวจสอบ O2/LEL ก่อนเริ่มงาน ☐ กำหนดจุดตัดแหล่งพลังงาน (ไฟฟ้า, น้ำ, อากาศ) ☒ ตรวจสอบงานโดยผู้ขออนุญาต 4 ขน.
☐ ป้ายบอก, วาง, หลุม ☐ ตรวจสอบ O2/LEL ทุก... ขน. ☐ กำหนดจุดปลอดภัยที่กระทบกับสิ่งแวดล้อม ☒ ตรวจสอบงานโดย Safety Lead ทุก... ขน.
☐ ปิดกั้นการระบายน้ำ ☐ ตรวจสอบพื้นที่รอบรั้วและประตูรั้ว ☐ ตรวจสอบพื้นที่รอบรั้วและประตูรั้ว ☒ ตรวจสอบความปลอดภัยและสิ่งแวดล้อมที่ขออนุญาตแล้ว
☐ Bypassing อุปกรณ์ระบบ ☐ ชื่อสารเคมี ค่า TLV ☐ การปิดล้อมและปิดล้อมพื้นที่ ☒ อื่นๆ ตามลักษณะงาน
ข้าพเจ้าได้กำหนดมาตรการความปลอดภัยที่จำเป็นและเหมาะสมในการเตรียมพื้นที่ให้ปลอดภัยรวมทั้งมอบหมายให้ผู้ที่เกี่ยวข้องดำเนินการปฏิบัติงานแล้ว
ลงชื่อ นายสมชาย ใจดี Permit Verifier วันที่ 11/7/65 เวลา 18:10
กรณีพื้นที่ข้างเคียง งานจะต้องได้รับการอนุมัติร่วมกันโดยเจ้าของพื้นที่ข้างเคียง (CO-Signing) งานทำในพื้นที่ใดควรระบุเข้าข้างเคียง
ลงชื่อ (ผู้ตรวจสอบความปลอดภัย) Permit Co-Signer วันที่ _____ เวลา _____
ได้ตรวจสอบเอกสารการขออนุญาต และอนุญาตให้เริ่มใช้ใบอนุญาตทำงานนี้ได้
ลงชื่อ นายสมชาย ใจดี Permit Approver วันที่ 12/07/65 เวลา 08:15
หมายเหตุ : งานที่มีประกายไฟในพื้นที่อันตรายและงานอับอากาศ ต้องได้รับการอนุญาตโดยผู้จัดการส่วนขึ้นไป
ลงชื่อ _____ วันที่ _____ เวลา _____

3. การรับรองความปลอดภัยก่อนทำงาน : On Field Permit Verify (ส่วนที่ 3 โดย Permit Requester/Safety Lead/Field Verifier)

3.1 ข้าพเจ้าได้รับแจ้งผลการตรวจสอบความปลอดภัยก่อนทำงานเรียบร้อยแล้ว
3.2 ข้าพเจ้าได้รับแจ้งผลการตรวจสอบความปลอดภัยก่อนทำงานเรียบร้อยแล้ว
3.3 ข้าพเจ้าได้รับแจ้งผลการตรวจสอบความปลอดภัยก่อนทำงานเรียบร้อยแล้ว
ลงชื่อ _____ วันที่ _____ เวลา _____

4. การติดตามความปลอดภัยขณะทำงาน : Safe Work Monitoring (ส่วนที่ 4 โดยผู้รับรองความปลอดภัย Field Verifier รับผลตอบกลับ)


การตรวจสอบระหว่างปฏิบัติงาน โดยผู้ตรวจก๊าซ (Gas Tester) (กรณีเริ่มงานหลังเที่ยงคืน 1 ชั่วโมง ต้องตรวจสอบก๊าซก่อนเริ่มงานใหม่ ให้มีการวัดก๊าซก่อนเริ่มปฏิบัติงาน)

ตำแหน่ง	ครั้งที่	1	2	3	4	5	6	7	8
ผู้ตรวจก๊าซ (Gas Tester)	%Oxygen	20.9							
	%ก๊าซติดไฟ	0							
	ก๊าซพิษ (ppm)								
	ก๊าซพิษ (ppm)								
ชื่อผู้ตรวจก๊าซ	วันที่	12/07/65							
	ชื่อผู้ตรวจก๊าซ	นายสมชาย ใจดี							

การตรวจสอบสภาพงานเป็นไปตามมาตรฐานความปลอดภัยระหว่างการทำงาน รวมถึงการตรวจสอบและแจ้งข้อมูลหากพบผิดปกติ

ตรวจสอบโดย	ครั้งที่	1	2	3	4	5	6
Field Verifier	วันที่	12/07/65					
	ชื่อ	นายสมชาย ใจดี					
Permit Requester	วันที่	12/07/65					
	ชื่อ	นายสมชาย ใจดี					
Safety Lead	วันที่	12/07/65					
	ชื่อ	นายสมชาย ใจดี					

การระงับใบอนุญาตทำงานชั่วคราวเนื่องจาก : Cause of Permit Suspend



[illegible][illegible]

[illegible][illegible]

วันที่ 12 เดือน ๖ พ.ศ. ๖5

ใช้ร่วมกับใบอนุญาตเลขที่ RPL 1929.2022

ประจำประตูที่ ๘-๗

เข้าพื้นที่บริษัท ☐ MTT ☐ RTC ☒ RPL

[illegible]

หัวหน้างาน / จป.บริษัทสุริยิเบตมา

บริษัท



SCG ใบแจ้งรายการสิ่งของ (ของผู้รับเหมา) เพื่อนำเข้า และนำออกจากโรงงานมาบตาพุด Site

NO. 505187

1	2	3	5	6	7
---	---	---	---	---	---

1. สิ่งของตามรายการนี้นำไปใช้ในงานของผู้รับเหมาชื่อ..... บริษัท ซีพี ออลล์ จำกัด (มหาชน)สังกัดบริษัท CPG/CPB
เป็นงานของหน่วยงาน..... บริษัท CPBวันที่ 12/03/65เวลานำเข้า 13.05ทะเบียนพาหนะ -
2. สิ่งของเหล่านี้ไม่ได้ออก/นำออกบางส่วน/นำออกทั้งหมด ภายในวันที่ 12/03/65 เดือน มี.ค. ปี 65

[illegible]

SE - F - 010

๓. ...ผู้นำเข้า

ลง..... (พนักงานรักษาความปลอดภัย)

..... (ผู้ควบคุมงานของโรงงาน)

หมายเหตุ 1. ใบแจ้งนี้ผู้นำเข้าจะต้องเป็นฝ่ายรวบรวมและเฝ้าระวังการสั่งของ

- พนักงาน รปภ. ต้องตรวจสอบสิ่งของให้ตรงรายการที่แจ้ง

3. ผู้นำเข้าต้องให้ผัควบคุมงานตรวจสอบรับทราบ และลงชื่อรับรองการนำออกไปแสดงต่อพนักงานรักษาความปลอดภัยเก็บไว้เป็นหลักฐานเพื่อการนำออกครบตามจำนวนที่นำเข้า



ภาคผนวก 52-3
เอกสารการตรวจสอบและบำรุงรักษาแนวท่อ



TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RF-07/65
PERIOD:	July, 2022	Work Order no.:	RPL-PM/M-07/65
CLIENT:	THAI MMA CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (<=10%LEL and <10 %LEL) Can not cause fire or explosive.
		First action within 2 hrs. Should be repaired within 5 days. Should be repaired within 30 days or as fast as possible. Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: July, 2022	Date: July, 2022	Date: July, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RJ-07/65
PERIOD:	July, 2022	Work Order no.:	RPL-PM/M-07/65
CLIENT:	MAP TA PHUT OLEFINS CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible of combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (>0%LEL and <10 %LEL) Can not cause fire or explosive.

First action within 2 hrs. Should be repaired within 5 days.
Should be repaired within 30 days or as fast as possible.
Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: July, 2022	Date: July, 2022	Date: July, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RH-07/65
PERIOD:	July, 2022	Work Order no.:	RPL-PM-IN-07/65
CLIENT:	PTT GLOBAL CHEMICAL PUBLIC COMPANY LIMITED		
BY:	REPO.(RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:			
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	First action within 2 hrs. Should be repaired within 5 days.
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: July, 2022	Date: July, 2022	Date: July, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-07/65
PERIOD:	July, 2022		
CLIENT:	THAI POLYETHYLENE CO., LTD.	Work Order no.:	RPL-PM/IM-07/65
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E EMERGENCY	Visible of combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	First action within 2 hrs. Should be repaired within 5 days.
I IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
N NORMAL	Gas detected between 0-10%LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: July, 2022	Date: July, 2022	Date: July, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RR-07/65
PERIOD:	July, 2022	Work Order no.:	RPL-PM-M-07/65
CLIENT:	AIR LIQUIDE (THAILAND) CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (<=10%LEL and <10 %LEL) Can not cause fire or explosive.
		First action within 2 hrs. Should be repaired within 5 days. Should be repaired within 30 days or as fast as possible. Should be repaired within 90 days or as fast as possible.

Inspected by:	Minthada Proseekham	Reviewed by:	Suwichaya Saengmanee
Company:	REPCO	Company:	REPCO
Date:	July, 2022	Date:	July, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: July, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-BI-07/65
PERIOD:	July, 2022	Work Order no.:	RPL-PW/M-07/65
CLIENT:	BANGKOK SYNTHETICS COMPANY LIMITED		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:			
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	First action within 2 hrs. Should be repaired within 5 days.
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee
Company: REPCO	Company: REPCO
Date: July, 2022	Date: July, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: July, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RH-07/65
PERIOD:	July, 2022	Work Order no.:	RPL-PM/M-07/65
CLIENT:	DOW CHEMICAL (THAILAND) CO., LTD.		
BY:	REPOC (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible of combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.

First action within 2 hrs. Should be repaired within 5 days.
Should be repaired within 30 days or as fast as possible.
Should be repaired within 90 days or as fast as possible.

Inspected by:	Minthada Proseekham	Reviewed by:	Suwichaya Saengmanee
Company:	REPCO	Company:	REPCO
Date:	July, 2022	Date:	July, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: July, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-07/65
PERIOD:	July, 2022	Work Order no.:	RPL-WM/M-07/65
CLIENT:	GLOBAL POWER SYNERGY CO., LTD.		
By:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible of combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.

First action within 2 hrs. Should be repaired within 5 days.
Should be repaired within 30 days or as fast as possible.
Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee
Company: REPCO	Company: REPCO
Date: July, 2022	Date: July, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: July, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-08/65
PERIOD:	August, 2022	Work Order no.:	RPL-PM-M-08/65
CLIENT:	MAP TA PHUT OLEFINS CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (<=10%LEL and <10 %LEL) Can not cause fire or explosive.
		First action within 2 hrs. Should be repaired within 5 days. Should be repaired within 30 days or as fast as possible. Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-08/65
PERIOD:	August, 2022	Work Order no.:	RPL-WM-08/65
CLIENT:	RAYONG PIPELINE CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:			
E	EMERGENCY	Visible of combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)	First action within 2 hrs. Should be repaired within 5 days.
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (>0%LEL and <10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Surwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RF-08/65
PERIOD:	August, 2022	Work Order no.:	RPL-PM-M-06/65
CLIENT:	THAI POLYETHYLENE CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:			
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	First action within 2 hrs. Should be repaired within 5 days.
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (<10%LEL and <10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-08/65
PERIOD:	August, 2022	Work Order no.:	RPL-PW/M-08/65
CLIENT:	RAYONG OLEFINS CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E EMERGENCY	Visible of combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	First action within 2 hrs. Should be repaired within 5 days.
I IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
N NORMAL	Gas detected between 0-10%LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RJ-08/05
PERIOD:	August, 2022	Work Order no.:	RPL-PM/IM-08/05
CLIENT:	BANGKOK SYNTHETICS COMPANY LIMITED		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (<=10%LEL and <10 %LEL) Can not cause fire or explosive.
		First action within 2 hrs. Should be repaired within 5 days. Should be repaired within 30 days or as fast as possible. Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-08/65
PERIOD:	August, 2022	Work Order no.:	RPL-PM/M-08/65
CLIENT:	THAI MMA CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.

First action within 2 hrs. Should be repaired within 5 days.

Should be repaired within 30 days or as fast as possible.

Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Sawichaya Seengmanee	Reviewed by: Dani Pornsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-08/65
PERIOD:	August, 2022	Work Order no.:	RPL-PM-W-08/65
CLIENT:	GLOBAL POWER SYNERGY CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:			
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	First action within 2 hrs. Should be repaired within 5 days.
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (<10%LEL and <10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-R1-06/65
PERIOD:	August, 2022	Work Order no.:	RPL-PM-M-06/65
CLIENT:	PTT GLOBAL CHEMICAL PUBLIC COMPANY LIMITED		
By:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible of combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (<10%LEL and ≤10 %LEL) Can not cause fire or explosive.

First action within 2 hrs. Should be repaired within 5 days.
Should be repaired within 30 days or as fast as possible.
Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RJ-08/65
PERIOD:	August, 2022	Work Order no.:	RPL-PM/IM-08/65
CLIENT:	LINDE (THAILAND) PUBLIC CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (<=10%LEL and <10 %LEL) Can not cause fire or explosive.
		First action within 2 hrs. Should be repaired within 5 days. Should be repaired within 30 days or as fast as possible. Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-08/65
PERIOD:	August, 2022	Work Order no.:	RPL-PM/M-08/65
CLIENT:	AIR LIQUIDE (THAILAND) CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:			
E	EMERGENCY	Visible of combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	First action within 2 hrs. Should be repaired within 5 days.
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Sawichaya Seengmanee	Reviewed by: Dani Pornsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-08/65
PERIOD:	August, 2022	Work Order no.:	RPL-PW/M-08/65
CLIENT:	SAK CHAISIDHI CO., LTD.		
BY:	BEPCO (RAYONG) ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:			
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	First action within 2 hrs. Should be repaired within 5 days.
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-R1-08/65
PERIOD:	August, 2022		
CLIENT:	DOW CHEMICAL (THAILAND) CO., LTD.	Work Order no.:	RPL-PM-M-08/65
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible of combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (<10%LEL and ≤10 %LEL) Can not cause fire or explosive.
		First action within 2 hrs. Should be repaired within 5 days. Should be repaired within 30 days or as fast as possible. Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuan
Company: REPCO	Company: REPCO	Company: RPL
Date: August, 2022	Date: August, 2022	Date: August, 2022

Page 7 of 14Page 5 of 14Page 8 of 14Page 6 of 14

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-IL-09/65
PERIOD:	September, 2022	Work Order no.:	RPL-WO-09/65
CLIENT:	AIR LIQUIDE (THAILAND) CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.
		First action within 2 hrs. Should be repaired within 5 days. Should be repaired within 30 days or as fast as possible. Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Prosekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Danti Pomsuan
Company: REPCO	Company: REPCO	Company: RPL
Date: September, 2022	Date: September, 2022	Date: September, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-09/65
PERIOD:	September, 2022	Work Order no.:	RPL-PM/M-09/65
CLIENT:	BANGKOK SYNTHETICS COMPANY LIMITED		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and <50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (>0%LEL and <10 %LEL) Can not cause fire or explosive.
		First action within 2 hrs. Should be repaired within 5 days. Should be repaired within 30 days or as fast as possible. Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseidham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: September, 2022	Date: September, 2022	Date: September, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-09/65
PERIOD:	September, 2022	Work Order no.:	RPL-WO/RI-09/65
CLIENT:	DOW CHEMICAL (THAILAND) CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and <50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and <10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Prosekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: September, 2022	Date: September, 2022	Date: September, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-IL-09/65
PERIOD:	September, 2022	Work Order no.:	RPL-PM/14-09/65
CLIENT:	GLOBAL POWER SYNERGY CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	First action within 2 hrs. Should be repaired within 5 days.
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and <50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (<10%LEL and <10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: September, 2022	Date: September, 2022	Date: September, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: September, 2023

Reviewed by: Dani Pomsuwan
Company: RPL
Date: October, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: September, 2023

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-10/65
PERIOD:	October, 2022	Work Order no.:	RPL-WO-M/10/65
CLIENT:	MAP TA PHUT OLEFINS CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: October, 2022	Date: October, 2022	Date: October, 2022

Page 5 of 14

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-10/05
PERIOD:	October, 2022	Work Order no.:	RPL-PM/14-10/05
CLIENT:	THAI POLYETHYLENE CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: October, 2022	Date: October, 2022	Date: October, 2022

Page 6 of 14

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPJ-R-10/65
PERIOD:	October, 2022	Work Order no.:	RPJ-PM/M-10/65
CLIENT:	RAYONG PIPELINE CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and <50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection (>0%LEL and <10 %LEL) Can not cause fire or explosive.
		First action within 2 hrs. Should be repaired within 5 days. Should be repaired within 30 days or as fast as possible. Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseetham	Reviewed by: Sunichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: October, 2022	Date: October, 2022	Date: October, 2022

Page 3 of 14


TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-10/05
PERIOD:	October, 2022	Work Order no.:	RPL-WO/M-10/05
CLIENT:	RAYONG OLEFINS CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]


PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and <50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection (>0%LEL and <10 %LEL) Can not cause fire or explosive.
		First action within 2 hrs. Should be repaired within 5 days. Should be repaired within 30 days or as fast as possible. Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseikhham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: October, 2022	Date: October, 2022	Date: October, 2022

Page 4 of 14

[illegible]


Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pornsuwan
Company: REPCD	Company: REPCD	Company: RPL
Date: October, 2022	Date: October, 2022	Date: October, 2022

[illegible]

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pornsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: October, 2022	Date: October, 2022	Date: October, 2022

[illegible]


Inspected by:	Mintthada Proseekham	Reviewed by:	Suwichaya Saengmanee	Reviewed by:	Dani Pomsuwan
Company:	REPCO	Company:	REPCO	Company:	RPL
Date:	October, 2022	Date:	October, 2022	Date:	October, 2022

[illegible]

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: October, 2022	Date: October, 2022	Date: October, 2022

[illegible]


Inspected by:	Minhada Prosekham	Reviewed by:	Suwichaya Saengmanee	Reviewed by:	Dani Pomsuwan
Company:	REPCO	Company:	REPCO	Company:	RPL
Date:	October, 2022	Date:	October, 2022	Date:	October, 2022

[illegible]

Inspected by:	Minthada Prosekham	Reviewed by:	Suwichaya Saengmanee	Reviewed by:	Dani Pomsuwan
Company:	REPCO	Company:	REPCO	Company:	RPL
Date:	October, 2022	Date:	October, 2022	Date:	October, 2022

[illegible]

Inspected by: Minthada Prosekham	Reviewed by: Sunichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: October, 2022	Date: October, 2022	Date: October, 2022

[illegible]

Inspected by:	Minthada Proseekham	Reviewed by:	Surichaya Saengmanee	Reviewed by:	Dani Pomsuwan
Company:	REPCO	Company:	REPCO	Company:	RPL
Date:	October, 2022	Date:	October, 2022	Date:	October, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RL-11/65
PERIOD:	November, 2022	Work Order no.:	RPL-PM-M-11/65
CLIENT:	THAI MMA CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (<10%LEL and <10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Prosekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Danti Ponsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: November, 2022	Date: November, 2022	Date: November, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RJ-11/65
PERIOD:	November, 2022	Work Order no.:	RPL-PM/M-11/65
CLIENT:	MAP TA PHUT OLEFINS CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)	First action within 2 hrs. Should be repaired within 5 days.
E EMERGENT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and <50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
I IMPORTANT	Gas detected between 0-10 %LEL of leak detection. (<0%LEL and <10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.
N NORMAL		

Inspected by: Minthada Proseeham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: November, 2022	Date: November, 2022	Date: November, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-R/11/65
PERIOD:	November, 2022	Work Order no.:	RPL-W/11/65
CLIENT:	PTT GLOBAL CHEMICAL PUBLIC COMPANY LIMITED		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and <50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and <10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Danti Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: November, 2022	Date: November, 2022	Date: November, 2022

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-N-11/65
PERIOD:	November, 2022	Work Order no.:	RPL-PM/M-11/65
CLIENT:	THAI POLYETHYLENE CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	First action within 2 hrs, Should be repaired within 5 days.
I	IMPORTANT	
I	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and <50 %LEL) Can not cause any fire or explosive.	Should be repaired within 30 days or as fast as possible.
N	NORMAL	
	Gas detected between 0-10 %LEL of leak detection, (<0%LEL and <10 %LEL) Can not cause fire or explosive.	Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseikhiam	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: November, 2022	Date: November, 2022	Date: November, 2022



TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-11/165
PERIOD:	November, 2022	Work Order no.:	RPL-WO/M-11/165
CLIENT:	AIR LIQUIDE (THAILAND) CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤ 50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (>0%LEL and ≤ 10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Proseekham
Company: REPCO
Date: November, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: November, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: November, 2022

ROUTINE INSPECTION MONTHLY REPORT

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-M/11/65
PERIOD:	November, 2022	Work Order no.:	RPL-WO-M/11/65
CLIENT:	DOW CHEMICAL (THAILAND) CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤ 50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤ 10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Proseekham
Company: REPCO
Date: November, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: November, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: November, 2022

TYPE: MONTHLY INSPECTION LOG SHEET	Sheet no.: RPL-R/11/65	TYPE: MONTHLY INSPECTION LOG SHEET	Sheet no.: RPL-R/11/65
PERIOD: November, 2022	Work Order no.: RPL-W/11/65	PERIOD: November, 2022	Work Order no.: RPL-W/11/65
CLIENT: DOW CHEMICAL (THAILAND) CO., LTD.		CLIENT: GLOBAL POWER SYNERGY CO., LTD.	
BY: REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		BY: REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)	

[illegible]

PRIORITY:			PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.	I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.	N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.
First action within 2 hrs, Should be repaired within 5 days.			First action within 2 hrs, Should be repaired within 5 days.		
Should be repaired within 30 days or as fast as possible.			Should be repaired within 30 days or as fast as possible.		
Should be repaired within 90 days or as fast as possible.			Should be repaired within 90 days or as fast as possible.		

Inspected by: Minthada Proseekham
Company: REPCO
Date: November, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: November, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: November, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: November, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: November, 2022

Inspected by: Minthada Proseekham
Company: REPCO
Date: December, 2022

Inspected by: Minthada Proseekham
Company: REPCO
Date: November, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: November, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: November, 2022

Inspected by: Minthada Proseekham
Company: REPCO
Date: December, 2022

Inspected by: Minthada Proseekham
Company: REPCO
Date: November, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: November, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: November, 2022



RAYONG PIPELINE CO., LTD. / RIL1996 CO., LTD.
RAYONG ENGINEERING PLANT SERVICE CO., LTD.



RAYONG PIPELINE CO., LTD. / RIL1996 CO., LTD.
RAYONG ENGINEERING PLANT SERVICE CO., LTD.

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-12/65
PERIOD:	December, 2022	Work Order no.:	RPL-WO/M-12/65
CLIENT:	MAP TA PHUT OLEFINS CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤ 50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (>0%LEL and ≤ 10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Proseekham
Company: REPCO
Date: December, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: December, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: December, 2022

Page 5 of 14



RAYONG PIPELINE CO., LTD. / RIL1996 CO., LTD.
RAYONG ENGINEERING PLANT SERVICE CO., LTD.



RAYONG PIPELINE CO., LTD. / RIL1996 CO., LTD.
RAYONG ENGINEERING PLANT SERVICE CO., LTD.

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-12/65
PERIOD:	December, 2022	Work Order no.:	RPL-WO/M-12/65
CLIENT:	THAI POLYETHYLENE CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤ 50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤ 10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Proseekham
Company: REPCO
Date: December, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: December, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: December, 2022

Page 6 of 14

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPJ-RJ-12/65
PERIOD:	December, 2022	Work Order no.:	RPJ-PM/M-12/65
CLIENT:	RAYONG PIPELINE CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Proseekham
Company: REPCO
Date: December, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: December, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: December, 2022

Page 3 of 14



RAYONG PIPELINE CO., LTD. / RIL1996 CO., LTD.
RAYONG ENGINEERING PLANT SERVICE CO., LTD.

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-R/12/65
PERIOD:	December, 2022	Work Order no.:	RPL-PM/M-12/65
CLIENT:	RAYONG OLEFINS CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]


PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition. (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection. (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection. (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Proseekham
Company: REPCO
Date: December, 2022


Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: December, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: December, 2022

Page 4 of 14

[illegible]


Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pornsuwan
Company: REPCD	Company: REPCD	Company: RPL
Date: December, 2022	Date: December, 2022	Date: December, 2022

[illegible]

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Ponsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: December, 2022	Date: December, 2022	Date: December, 2022

[illegible]

Inspected by: Minthada Proseekham	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: December, 2022	Date: December, 2022	Date: December, 2022

[illegible]

Inspected by: Minthada Proseekhem	Reviewed by: Suwichaya Saengmanee	Reviewed by: Dani Pomsuwan
Company: REPCO	Company: REPCO	Company: RPL
Date: December, 2022	Date: December, 2022	Date: December, 2022



TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-RI-12/65
PERIOD:	December, 2022	Work Order no.:	RPL-WO-M/12/65
CLIENT:	LINDE (THAILAND) PUBLIC CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Proseekham
Company: REPCO
Date: December, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: December, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: December, 2022

ROUTINE INSPECTION MONTHLY REPORT

TYPE:	MONTHLY INSPECTION LOG SHEET	Sheet no.:	RPL-R1-12/65
PERIOD:	December, 2022	Work Order no.:	RPL-WM/M-12/65
CLIENT:	SAK CHAISIDHI CO., LTD.		
BY:	REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		

[illegible]

PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (>0%LEL and ≤10 %LEL) Can not cause fire or explosive.

Inspected by: Minthada Proseekham
Company: REPCO
Date: December, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: December, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: December, 2022

TYPE: MONTHLY INSPECTION LOG SHEET	Sheet no.: RPL-RS-12/65	TYPE: MONTHLY INSPECTION LOG SHEET	Sheet no.: RPL-RS-12/65
PERIOD: December, 2022	Work Order no.: RPL-RM/M-12/65	PERIOD: December, 2022	Work Order no.: RPL-RM/M-12/65
CLIENT: SAK CHAISIDHI CO., LTD.		CLIENT: DOW CHEMICAL (THAILAND) CO., LTD.	
BY: REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)		BY: REPCO (RAYONG ENGINEERING & PLANT SERVICE CO., LTD.)	

[illegible]

PRIORITY:			PRIORITY:		
E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)	E	EMERGENCY	Visible or combustible fluid leakage or more than 50%LEL of leak condition, (>50%LEL)
I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.	I	IMPORTANT	Gas detected between 10-50 %LEL of leak detection, (>10%LEL and ≤50 %LEL) Can not cause any fire or explosive.
N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (<10%LEL and ≤10 %LEL) Can not cause fire or explosive.	N	NORMAL	Gas detected between 0-10 %LEL of leak detection, (<10%LEL and ≤10 %LEL) Can not cause fire or explosive.
		First action within 2 hrs. Should be repaired within 5 days.			First action within 2 hrs. Should be repaired within 5 days.
		Should be repaired within 30 days or as fast as possible.			Should be repaired within 30 days or as fast as possible.
		Should be repaired within 90 days or as fast as possible.			Should be repaired within 90 days or as fast as possible.

Inspected by: Minthada Proseekham
Company: REPCO
Date: December, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: December, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: December, 2022

Inspected by: Minthada Proseekham
Company: REPCO
Date: December, 2022

Reviewed by: Suwichaya Saengmanee
Company: REPCO
Date: December, 2022

Reviewed by: Dani Pomsuwan
Company: RPL
Date: December, 2022



ภาคผนวก 52-4
แผนฉุกเฉินกรณีเกิดการรั่วไหลบริเวณแนวท่อขนส่ง



Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 2 of 17
DocType : Procedure		
Company : RPL		

- SE-P-7005 แผนฉุกเฉิน RIL
- HS-W-8005 พนักงานสื่อสารและประสานงาน EC RPL

4. นิยามและคำย่อ

EC-EFT	=	Emergency Center ของบริษัท Eastern Fluid Transport Co., Ltd.
EC-ROC	=	Emergency Center ของบริษัท Rayong Olefin Co., Ltd.
EC-RIL	=	Emergency Center ของบริษัท Map Ta Phut Olefin Co., Ltd.
EC-RPL	=	Emergency Center ของบริษัท Rayong Pipe Line Co., Ltd.
EC-TPC	=	Emergency Center ของบริษัท Thai Plastic and Chemicals Public Co., Ltd.
EMCC	=	Environmental Monitoring Control Center.
MRR-ERT	=	Maptaphut Tank Terminal Co., Ltd. / Rayong terminal Co., Ltd. / Rayong Pipe Line Co., Ltd. – Emergency response team
SKV	=	Sukhumvit

External Customer

ALT	=	AIR LIQUIDE (THAILAND) Co., Ltd.
BIG	=	BIG Co., Ltd.
BST	=	Bangkok Synthetics Co., Ltd.
DOW	=	DOW Chemicals (Thailand) Co., Ltd.
GPSC	=	Global Power Synergy Company Public Limited
GLOW	=	GLOW Power Energy Company Public Limited
SAKC	=	SAK CHAISIDHI Co., Ltd.
LINDE	=	LINDE (Thailand) Public Co., Ltd.
PTTGC	=	PTT Global Chemical Public Company Limited.
MIG	=	Maptaphut industrial gas Co., Ltd.

SCG Chemical Group

MOC	=	Map Ta Phut Olefins Co., Ltd.
ROC	=	Rayong Olefin Co., Ltd.
SMPC	=	SIAM MITSUI P.T.A Co., Ltd.
TMMA	=	Thai MMA Co., Ltd.

Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 1 of 17
DocType : Procedure		
Company : RPL		

1. วัตถุประสงค์

ระเบียบวิธีการนี้ จัดทำขึ้นเพื่อใช้เป็นแนวทางปฏิบัติของพนักงานและผู้ที่ได้รับมอบหมาย ในการควบคุมภาวะฉุกเฉินที่ อาจเกิดขึ้นทั้งนี้ เพื่อลดความสูญเสียต่อชีวิต, ทรัพย์สิน,ผลกระทบต่อสิ่งแวดล้อมฯ ชุมชน บริษัทข้างเคียง และใช้เป็นแนวในการควบคุมภาวะฉุกเฉินที่เกี่ยวข้องกับภัยคุกคามที่มีผลต่อการรักษาความปลอดภัยของท่อรับส่งผลิตภัณฑ์

1. เพื่อใช้เป็นแนวทางในการปฏิบัติการระงับเหตุฉุกเฉินต่างๆ ที่เกิดขึ้นในพื้นที่อย่างเป็นระบบ และตามข้อกำหนดที่ถูกต้อง
2. เพื่อจำกัด ,ลดผลกระทบ และควบคุมเหตุการณ์ให้เกิดความเสียหายต่อชีวิต ร่างกาย ทรัพย์สิน ตลอดจนสิ่งแวดล้อมฯ ชุมชน และบริษัทข้างเคียง ให้น้อยที่สุด
3. กู้ภัยช่วยเหลือผู้ประสบภัย หรือผู้ที่บาดเจ็บ ตลอดจนผู้ที่เกี่ยวข้องต่างๆที่ได้รับผลกระทบ ให้ได้รับความปลอดภัย
4. เพื่อให้การติดต่อประสานงานกับทางหน่วยงานภายใน และภายนอกให้เป็นไปด้วยความถูกต้องและมีประสิทธิภาพ
5. เพื่อใช้เป็นแนวทางในการฝึกซ้อมการระงับเหตุฉุกเฉิน
6. เพื่อใช้เป็นแนวทางในการพิจารณาจัดหาเครื่องมือ อุปกรณ์ในการควบคุมเหตุให้มีความเหมาะสม และเพียงพอต่อความต้องการใช้งาน
7. เพื่อใช้เป็นแนวทางในการฟื้นฟูหลังการเกิดเหตุและการใช้แผนความต่อเนื่องทางธุรกิจ (Business Continuity Plan) ได้อย่างมีประสิทธิภาพ

2. ขอบข่าย

ใช้ในการควบคุมภาวะฉุกเฉินในพื้นที่ ที่บริษัทระยองไปป์ไลน์จำกัด รับผิดชอบ ทั้งกรณีสารเคมีรั่วไหล เพลิงไหม้ ระเบิด หรือกรณีอื่นๆ ที่อาจก่อให้เกิดอันตรายร้ายแรง โดยครอบคลุมถึงบุคคลที่เกี่ยวข้อง อันได้แก่บุคคลที่เป็นพนักงานบริษัท และบุคคลที่ไม่ได้เป็นพนักงานบริษัทฯ เช่น ผู้รับเหมา แยกเชื่อมฯ ราชการ ชุมชนรอบข้างและบริษัทที่มีพื้นที่ข้างเคียง เป็นต้น

3. เอกสารอ้างอิง

- EFT-SD-006 แผนฉุกเฉิน EFT
- SE-P-0008 แผนฉุกเฉิน MRR
- SE-S-0001 คู่มือแผนฉุกเฉิน ROC

Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 4 of 17
DocType : Procedure		
Company : RPL		

4. เจ้าของ Pipe rack	<p>-มีหน้าที่ในการสื่อสารและประเมินสถานการณ์ร่วมกับเจ้าของท่อผลิตภัณฑ์</p> <p>-เข้าพื้นที่เกิดเหตุ</p> <p>-ดูความปลอดภัย Rack</p> <p>-ดูผลกระทบ Rack</p> <p>-สื่อสารกับ EC RPL เพื่อ Support ข้อมูลเบื้องต้นเฉพาะ Pipe rack RPL</p>
----------------------	---

5.1.2 พื้นที่รับผิดชอบ

ลำดับ ที่	พื้นที่	เจ้าของพื้นที่	เจ้าของท่อเกิด เหตุฯ	เจ้าของท่อ ข้างเคียงเกิด เหตุฯ	เจ้าของ Pipe rack
1	1.1 นิคมฯRIL -Pipe rack RIL -Corridor underground pipe	RPL	Pipe owner	Pipe owner	RPL
	1.2 นิคมฯRIL -Pipe rack GPSC	RPL	Pipe owner	Pipe owner	GPSC
2	2.1 ROC -Box culvert SKV -Rack G -Rack F1 นอกกระบวนการผลิต	ROC Safety	Pipe owner	Pipe owner	RPL
	2.2 ROC -Rack G -Rack F1 -Rack F2 ในพื้นที่โรงงาน TMMA	TMMA	Pipe owner	Pipe owner	RPL
	2.3 ROC	ROC Safety	Pipe owner	Pipe owner	RPL

Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 3 of 17
DocType : Procedure		
Company : RPL		

MTT	=	Maptaphut Tank Terminal Co., Ltd.
RPL	=	Rayong Pipe Line Co., Ltd.
RIL	=	RIL 1996 Co., Ltd.
TPE	=	Thai Polyethylene Co., Ltd.
RTC	=	Rayong terminal Co., Ltd.
TPC	=	Thai Plastic and Chemicals Public Co., Ltd.

Neighbor

VNT	=	Vinythai Public Co., Ltd.
PTTGC 2	=	PTT Global Chemical Public Company Limited.
BST	=	Bangkok Synthetics Co., Ltd.
TATA	=	TATA Steel (Thailand) Public Company Limited
SYS	=	Siam Yamato Steel Co., Ltd.

5. วิธีการปฏิบัติงาน


5.1 บทบาทหน้าที่และพื้นที่รับผิดชอบ

5.1.1 บทบาทหน้าที่

ผู้รับผิดชอบ	บทบาท/หน้าที่
1. เจ้าของพื้นที่	<p>-มีหน้าที่ในการตรวจสอบพื้นที่และเข้าระงับเหตุเบื้องต้น พร้อมทั้งสื่อสารให้กับเจ้าของท่อขนส่งผลิตภัณฑ์ทราบตามขั้นตอนการแจ้งเหตุ</p> <p>-มีหน้าที่ในการจัดการเหตุฉุกเฉิน เช่น การประเมินและควบคุมสถานการณ์ การยกระดับภาวะฉุกเฉิน การสื่อสารกับชุมชนหน่วยงานราชการและสื่อมวลชน</p>
2. เจ้าของท่อเกิดเหตุฯ	-มีหน้าที่ในการร่วมจัดการเหตุฉุกเฉิน
3. เจ้าของท่อข้างเคียงเกิดเหตุฯ	-มีหน้าที่กำหนดให้ส่งทีม Operation ที่เกี่ยวข้องไปร่วมประเมินสถานการณ์และวางแผนสำหรับเข้าระงับเหตุร่วมกับเจ้าของท่อผลิตภัณฑ์ด้วย

Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 6 of 17
DocType : Procedure		
Company : RPL		

5.2 Site Plan แสดงพื้นที่ Pipe rack ที่บริษัท RPL ดูแลรับผิดชอบ




Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 5 of 17
DocType : Procedure		
Company : RPL		

	-Rack H นอกกระบวนการผลิต				
	2.4 ROC -Rack H ในพื้นที่โรงงาน ROC	ROC Utility	Pipe owner	Pipe owner	RPL
	2.5 ROC -Rack 3C ในพื้นที่โรงงาน ROC	ROC Utility	Pipe owner	Pipe owner	RPL
3	3.1 นิคมฯมาบตาพุด -Rack 3B	VNT/EFT	Pipe owner	Pipe owner	RPL
	3.2 นิคมฯมาบตาพุด -Rack 3A	PTTGC 2/ EFT	Pipe owner	Pipe owner	RPL
	3.3 นิคมฯมาบตาพุด -Rack 5 -Box culvert ROC -Rack 7A -Rack 7B -Rack 8A	EFT	Pipe owner	Pipe owner	RPL
	3.4 นิคมฯท่าเรือมาบตาพุด -Rack 8B -Rack 8C -Rack 8D	EFT	Pipe owner	Pipe owner	RPL
4	4.1 นิคมฯมาบตาพุด - Pipe underground TPC	RPL	TPC	Pipe owner	N/A
	4.2 นิคมฯมาบตาพุด - Pipe rack TPC	RPL	Pipe owner	Pipe owner	TPC
5	5.1 นิคมฯท่าเรือมาบตาพุด -Pipe rack RTC	RPL	Pipe owner	Pipe owner	RPL

Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 8 of 17
DocType : Procedure		
Company : RPL		

Flow Notify & Role กรณีการเกิดเหตุในพื้นที่ นิคมอุตสาหกรรม RIL



5.3.2 กรณีการเกิดเหตุ Pipe rack RPL ในพื้นที่ ROC และ TMMA

5.3.2.1 การแจ้งเหตุ

ผู้พบเหตุการณ์จะแจ้งไปยัง EC-ROC ให้รับทราบและแจ้งผู้เกี่ยวข้องดังต่อไปนี้

- 1.แจ้ง EMCC ตามแบบรายงานแจ้งเหตุการณ์ผิดปกติ/เหตุฉุกเฉินเบื้องต้น ของการนิคมอุตสาหกรรม มาบตาพุดภายใน 10 นาที
- 2.แจ้งไปยัง MRR-ERT เพื่อเข้าแผนฉุกเฉิน SE-P-0008 MRR
- 3.แจ้งไปยัง EC#RPL ให้รับทราบจากนั้น EC RPLแจ้งผู้เกี่ยวข้องตามลำดับดังต่อไปนี้
 - 3.1 แจ้งไปยังเจ้าของท่อที่เกิดเหตุ

Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 7 of 17
DocType : Procedure		
Company : RPL		

5.3 การตอบโต้ภาวะฉุกเฉิน

5.3.1 กรณีการเกิดเหตุในพื้นที่ นิคมอุตสาหกรรม RIL

5.3.1.1 การแจ้งเหตุ

ผู้พบเหตุการณ์จะแจ้งไปยัง EC-RPL ให้รับทราบและแจ้งผู้เกี่ยวข้องดังต่อไปนี้

- 1.แจ้ง EMCC และ EC RIL ตามแบบรายงานแจ้งเหตุการณ์ผิดปกติ/เหตุฉุกเฉินเบื้องต้น ของการนิคมอุตสาหกรรมมาบตาพุดภายใน 10 นาที
- 2.แจ้งไปยังเจ้าของท่อที่เกิดเหตุ
- 3.แจ้งไปยัง MRR-ERT เพื่อเข้าแผนฉุกเฉิน SE-P-0008 MRR พร้อม Support ข้อมูลดังต่อไปนี้ Safety data sheet, Isometric drawing, Piping and instrument diagram, Cross section drawing, General arrangement, Plot plan, Customer contract.
- 4.แจ้งไปยัง EC-ROC กรณีที่เกิดเหตุ Box culvert SKV.
- 5.แจ้งไปยังเจ้าของท่อข้างเคียง

5.3.1.2 การตอบโต้ภาวะฉุกเฉิน

Response	Pipeline Owner	MRR-ERT	RPL
Support	RIL	EM-MOC	กนอ.RIL
Fight Response Team	MOC Team	Pipeline Owner	เทศบาล
Emergency Plan	SE-P-MOC-0011 Emergency Respond Plan Site#7		

Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 10 of 17
DocType : Procedure		
Company : RPL		

5.3.3 กรณีการเกิดเหตุ Pipe rack RPL ในพื้นที่นิคมอุตสาหกรรมมาบตาพุด

5.3.3.1 การแจ้งเหตุ

ผู้พบเหตุการณ์จะแจ้งไปยัง EC-EFT ให้รับทราบและแจ้งผู้เกี่ยวข้องดังต่อไปนี้

- 1.แจ้ง EMCC และ Safety EFT ตามแบบรายงานแจ้งเหตุการณ์ผิดปกติ/เหตุฉุกเฉินเบื้องต้น ของการนิคมอุตสาหกรรมมาบตาพุดภายใน 10 นาที
- 2.แจ้งไปยังเจ้าของท่อที่เกิดเหตุ
- 3.แจ้งไปยัง EC#RPL ให้รับทราบจากนั้น EC RPLแจ้งผู้เกี่ยวข้องตามลำดับดังต่อไปนี้

3.1 แจ้งไปยังเจ้าของท่อที่เกิดเหตุ

3.2 แจ้งไปยัง MRR-ERT เพื่อเข้าแผนฉุกเฉิน SE-P-0008 MRR พร้อม Support ข้อมูลดังต่อไปนี้

Safety data sheet, Isometric drawing, Piping and instrument diagram, Cross section drawing, General arrangement, Plot plan, Customer contract

4.แจ้งไปยัง EC#ROC จากนั้น EC#ROC แจ้งไปยัง MRR-ERT เพื่อเข้าแผนฉุกเฉิน SE-P-0008

5.แจ้งไปยังเจ้าของท่อข้างเคียง

5.3.3.2 การตอบโต้ภาวะฉุกเฉิน

Response	Pipeline Owner	IEAT	MRR-ERT
Support	RPL	EFT	เทศบาล
Fight Response Team	ROC Team	Pipeline Owner	เทศบาล
Emergency Plan	SE-P-0008 Emergency Respond Plan ROC		

Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 9 of 17
DocType : Procedure		
Company : RPL		

3.2 แจ้งไปยัง MRR-ERT เพื่อเข้าแผนฉุกเฉิน SE-P-0008 พร้อม Support ข้อมูลดังต่อไปนี้


Safety data sheet, Isometric drawing, Piping and instrument diagram, Cross section drawing, General arrangement, Plot plan, Customer contract.

3.3.แจ้งไปยังเจ้าของท่อข้างเคียง

5.3.2.2 การตอบโต้ภาวะฉุกเฉิน

Response	Pipeline Owner	MRR-ERT	EM-MOC
Support	RPL	MOC	เทศบาล
Fight Response Team	ROC Team	Pipeline Owner	เทศบาล
Emergency Plan	SE-S-0001 Emergency Respond Plan Site#3		

Flow Notify & Role กรณีการเกิดเหตุ Pipe rack RPL ในพื้นที่ ROC และ TMMA



สีเหลืองคือหน้าที่ของ RPL ที่ต้องปฏิบัติ


Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 12 of 17
DocType : Procedure		
Company : RPL		

- 3.แจ้งไปยัง MRR-ERT เพื่อเข้าแผนฉุกเฉิน SE-P-0008 MRR พร้อม Support ข้อมูลดังต่อไปนี้ Safety data sheet, Isometric drawing, Piping and instrument diagram, Cross section drawing, General arrangement, Plot plan, Customer contract
- 4.แจ้งไปยังเจ้าของท่อข้างเคียง

5.3.4.2 การตอบโต้ภาวะฉุกเฉิน


Response	TPC	IEAT	MRR-ERT
Support	RPL	EFT	เทศบาล
Fight Response Team	ROC Team	Pipeline Owner	เทศบาล
Emergency Plan	SE-P-0008 Emergency Respond Plan ROC		

Flow Notify & Role กรณีการเกิดเหตุในพื้นที่ Pipe rack TPC และท่อ TPC



Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 11 of 17
DocType : Procedure		
Company : RPL		

Flow Notify & Role กรณีการเกิดเหตุ Pipe rack RPL ในพื้นที่นิคมอุตสาหกรรมมาบตาพุด




5.3.4 กรณีการเกิดเหตุในพื้นที่ Pipe rack TPC และท่อ TPC

5.3.4.1 การแจ้งเหตุ

ผู้พบเหตุการณ์จะแจ้งไปยัง EC-RPL ให้ทราบและแจ้งผู้เกี่ยวข้อง ดังต่อไปนี้

- 1.แจ้ง EMCC ตามแบบรายงานแจ้งเหตุการณ์ผิดปกติ/เหตุฉุกเฉินเบื้องต้น ของการนิคมอุตสาหกรรมมาบตาพุดภายใน 10 นาที
- 2.แจ้งไปยังเจ้าของท่อที่เกิดเหตุ EC-TPC

Flow Notify & Role กรณีการเกิดเหตุในพื้นที่ Pipe rack RTC เป็นท่อของ SCG



5.3.6 กรณีการเกิดเหตุในพื้นที่ Pipe rack RTC เป็นท่อของลูกค้า

5.3.6.1 การแจ้งเหตุ

ผู้พบเหตุการณ์จะแจ้งไปยัง EC-ROC ให้รับทราบและแจ้งผู้เกี่ยวข้องดังต่อไปนี้

1.แจ้งไปยัง EC#RPL ให้รับทราบจากนั้น EC RPLแจ้งผู้เกี่ยวข้องตามลำดับดังต่อไปนี้

- 1.1 แจ้ง EMCC ตามแบบรายงานแจ้งเหตุการณ์ผิดปกติ/เหตุฉุกเฉินเบื้องต้น ของการนิคมอุตสาหกรรมมาบตาพุดภายใน 10 นาที
- 1.2 แจ้งไปยังเจ้าของท่อที่เกิดเหตุ

5.3.5 กรณีการเกิดเหตุในพื้นที่ Pipe rack RTC เป็นท่อของ SCG

5.3.5.1 การแจ้งเหตุ

ผู้พบเหตุการณ์จะแจ้งไปยัง EC-ROC ให้รับทราบและแจ้งผู้เกี่ยวข้อง ดังต่อไปนี้

- 1.แจ้ง EMCC ตามแบบรายงานแจ้งเหตุการณ์ผิดปกติ/เหตุฉุกเฉินเบื้องต้น ของการนิคมอุตสาหกรรมมาบตาพุดภายใน 10 นาที
- 2.แจ้งไปยังเจ้าของท่อที่เกิดเหตุ
3. แจ้งไปยัง MRR-ERT เพื่อเข้าแผนฉุกเฉิน SE-P-0008 MRR
4. แจ้งไปยัง EC#RPL ให้รับทราบจากนั้น EC RPLแจ้งผู้เกี่ยวข้องตามลำดับดังต่อไปนี้

4.1 แจ้งไปยังเจ้าของท่อที่เกิดเหตุ

4.2 แจ้งไปยัง MRR-ERT เพื่อเข้าแผนฉุกเฉิน SE-P-0008 MRR พร้อม Support ข้อมูลดังต่อไปนี้ Safety data sheet, Isometric drawing, Piping and instrument diagram, Cross section drawing, General arrangement, Plot plan, Customer contract

4.3 แจ้งไปยังเจ้าของท่อข้างเคียง

5.3.4.2 การตอบโต้ภาวะฉุกเฉิน

Response	Pipeline Owner	MTP	MRR-ERT
Support	RPL	RTC	เทศบาล
Fight Response Team	ROC Team	Pipeline Owner	เทศบาล
Emergency Plan	SE-P-0008 Emergency Respond Plan ROC		

Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 16 of 17
DocType : Procedure		
Company : RPL		

5.4 การกำหนดการฝึกซ้อมรับภาวะฉุกเฉินประจำปี

5.4.1 เจ้าหน้าที่ความปลอดภัย RPL

5.4.1.1 จัดทำกำหนดการฝึกซ้อมแผนในแบบกำหนดการซ้อมแผนฉุกเฉินประจำปี HS-F-8016 อย่างน้อยต้องซ้อม

การซ้อมแผน	ความถี่	หมายเหตุ
1.Table top	Weekly	ซ้อมการสื่อสาร EC RPL
2.อพยพ	2 ครั้ง/ปี	ตาม EIA
3.Full exercise	1 ครั้ง/ปี	ตาม EIA

5.4.1.2 นำสถานการณ์จำลองสำหรับการซ้อมแผนฉุกเฉิน (HS-F-8014) และ ORGANIZATION EMERGENCY PLAN DRILL (HS-F-8015) ที่จะใช้ในการฝึกซ้อม ให้ประธานคณะกรรมการความปลอดภัย อาชีวอนามัยและสภาพแวดล้อมในการทำงานพิจารณา และลงนามอนุมัติ

5.4.1.3 สำเนาสรุปผลการซ้อมแผนฉุกเฉิน (HS-F-8013) ให้ผู้ที่เกี่ยวข้องรับทราบ

5.4.1.4 กรณีซ้อมในนิคมมาบตาพุด ทาง EFT ดำเนินการจัดทำหนังสือแจ้งหน่วยงานภายนอก ให้รับทราบถึงการฝึกซ้อมตามแผนฉุกเฉินของบริษัท5.4.1.5 กรณีซ้อมในนิคม RIL ทาง RIL 1996 ดำเนินการจัดทำหนังสือแจ้งหน่วยงานภายนอกให้รับทราบถึงการฝึกซ้อมตามแผนฉุกเฉินของบริษัท

5.4.1.6 ทำการนัดผู้ที่เกี่ยวข้องในการซ้อมแผนฉุกเฉินในครั้งนั้นๆ ทุกตำแหน่งมาดำเนินการทำ Table Top ก่อนการซ้อมแผนฉุกเฉินจริงทุกครั้ง พร้อมทั้งแจ้ง วัน / เวลา ในการซ้อมให้ทุกคนรับทราบ

5.4.1.7 ดำเนินการฝึกซ้อมตามรายละเอียดการฝึกซ้อม

Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 15 of 17
DocType : Procedure		
Company : RPL		


1.3 แจ้งไปยัง MRR-ERT เพื่อเข้าแผนฉุกเฉิน SE-P-0008 MRR พร้อม Support ข้อมูลดังต่อไปนี้

Safety data sheet, Isometric drawing, Piping and instrument diagram, Cross section drawing,

General arrangement, Plot plan, Customer contract

1.4 แจ้งไปยังเจ้าของท่อข้างเคียง

Flow Notify & Role กรณีการเกิดเหตุในพื้นที่ Pipe rack RTC เป็นท่อของลูกค้า



สีเหลืองคือหน้าที่ของ RPL ที่ต้องปฏิบัติ

Title : ระเบียบการปฏิบัติงานเรื่องแผนฉุกเฉิน RPL	Doc No : HS-P-8001-003	Page(s) : Page 17 of 17
DocType : Procedure		
Company : RPL		

5.4.1.8 ประชุมสรุปผลการฝึกซ้อมหลังจากดำเนินการฝึกซ้อมแล้วเสร็จ

5.4.1.9 บันทึกผลการฝึกซ้อมลงในแบบสรุปการแก้ไขข้อบกพร่องที่พบจากการฝึกซ้อมตามแผนฉุกเฉิน (HS-F-8013) พร้อมทั้งระบุแนวทางการแก้ไข

5.4.1.10 นำบันทึกผลการฝึกซ้อมแผนฉุกเฉิน (HS-F-8013) ให้ประธานคณะกรรมการความปลอดภัยอาชีวอนามัยและสภาพแวดล้อมในการทำงาน พิจารณานุมัติและสำเนาแจกจ่ายให้ผู้เกี่ยวข้อง เพื่อดำเนินการแก้ไขตามที่ COMMENT ต่อไป

6. เอกสารสนับสนุน

- HS-F-8013 สรุปผลการซ้อมแผนฉุกเฉิน
- HS-F-8014 สถานการณ์จำลอง
- HS-F-8015 ORGANIZATION EMERGENCY PLAN DRILL
- HS-F-8016 แผนกำหนดการฝึกซ้อมแผนฉุกเฉินประจำปี



ภาคผนวก 53
ผลการสอบเทียบอุปกรณ์วัดปริมาณวัตถุบิในถังเก็บ





CALIBRATION CERTIFICATE

Tag Name : HD4-LT-7729

Certificate No. : S1-22/3352

Date of Received : 01-Sep-22

Calibration Interval : 3 years

Date of Calibration : 01-Sep-22

Calibration Due Date : 01-Sep-25

Name of Plant : High Density Polyethylene 4/

Input Range : -1313.000 to -139.000 mmH2O (G)

Function name : Diff Pressure Transmitter

Output Range : 4.000 to 20.000 mA

Manufacturer : Yokogawa

Sensor Type : -

Model Name : EJX110A-JMS4G-917DB/KU22/D4/X2/A/C2

Classification : -


Serial Number : 90Y811436 232

Criteria : 0.25 % of span

Environment Temp./RH : 23 °C / 55 %

Reference Standard :

Model : Serial Number	Traceability	Certificate No.	Due Date
7250i : 66673			
P_-1 to 0 bar/g : 66673	IRPC	CL1-P220043	23-May-24
8846A : 2548001			
EL : 2548001	NA Caltechnologies	E1U222628	16-Jun-23



Calibration Results : As Found

Passed

Input [mmH2O]	Output [mA]	Error [mA]	Error [% of span]	Uncertainty [% of span]
-1313.0	3.980	-0.0200	-0.125	0.853
-1019.5	7.981	-0.0190	-0.119	0.854
-726.0	11.982	-0.0180	-0.113	0.855
-432.5	15.982	-0.0180	-0.113	0.856
-139.0	19.983	-0.0170	-0.106	0.857
-432.5	15.982	-0.0180	-0.113	0.856
-726.0	11.983	-0.0170	-0.106	0.855
-1019.5	7.982	-0.0180	-0.113	0.854
-1313.0	3.981	-0.0190	-0.119	0.853

Remark :

UUC IS NEW

Calibrated by

The uncertainty are for a confidence probability of approximately 95 %

This results of measurement was found accurate as show on date as place of calibration only which is valid exclusively for calibration as mentioned in the report.



CALIBRATION CERTIFICATE

Tag Name : PP3-LT-2301A

Certificate No. : S1-22/5013

Date of Received : 28-Oct-22

Calibration Interval : 6 years

Date of Calibration : 28-Oct-22

Calibration Due Date : 28-Oct-28

Name of Plant : Polypropylene Plant 3 (THPP3)/

Input Range : -5905.300 to -3808.300 mmH2O (G)

Function name : Diff Pressure Transmitter (Diaphragm)

Output Range : 4.000 to 20.000 mA

Manufacturer : Yokogawa

Sensor Type : -

Model Name : EJX118A-EMSCG-917DB-WA42C2SW20

Classification : -

Serial Number : 91J305334 911

Criteria : 0.25 % of span

Environment Temp./RH : 23 °C / 55 %

Reference Standard :

Model : Serial Number

Traceability

Certificate No.

Due Date

7250i : 66673

P_-1 to 0 bar/g : 66673

IRPC

CL1-P220043

23-May-24


8846A : 2548001

EL : 2548001

NA Caltechnologies

E1U222628

16-Jun-23



Calibration Results : As Found

Failed

Input [mmH2O]	Output [mA]	Error [mA]	Error [% of span]	Uncertainty [% of span]
-5905.3	3.807	-0.1930	-1.206	0.479
-5381.1	6.836	-1.1636	-7.273	0.480
-4856.8	10.850	-1.1500	-7.188	0.481
-4332.6	14.861	-1.1386	-7.116	0.483
-3803.3	18.879	-1.1591	-7.245	0.485
-4332.6	14.874	-1.1256	-7.035	0.483
-4856.3	10.864	-1.1398	-7.124	0.481
-5381.1	6.842	-1.1576	-7.235	0.480
-5905.3	3.807	-0.1930	-1.206	0.479

Calibration Results : As Left

Passed

Input [mmH2O]	Output [mA]	Error [mA]	Error [% of span]	Uncertainty [% of span]
-5905.3	4.007	0.0070	0.044	0.479
-5381.1	8.004	0.0044	0.027	0.480
-4856.8	12.009	0.0090	0.056	0.482
-4332.6	16.010	0.0104	0.065	0.484
-3803.3	20.013	-0.0251	-0.157	0.486
-4332.6	16.013	0.0134	0.084	0.484
-4856.8	12.016	0.0160	0.100	0.482
-5381.1	8.014	0.0144	0.090	0.480
-5905.3	4.015	0.0150	0.094	0.479

Calibr

The uncertainty are for a confidence probability of approximately 95%

This results of measurement was found accurate as show on date as place of calibration only
which is valid exclusively for calibration as mentioned in the report.



CALIBRATION CERTIFICATE

Tag Name : PP3-LT-2301B

Certificate No. : S1-22/5015

Date of Received : 28-Oct-22

Calibration Interval : 6 years

Date of Calibration : 28-Oct-22

Calibration Due Date : 28-Oct-28

Name of Plant : Polypropylene Plant 3 (THPP3)/

Input Range : -5845.700 to -3746.700 mmH₂O (G)

Function name : Diff Pressure Transmitter (Diaphragm)

Output Range : 4.000 to 20.000 mA

Manufacturer : Yokogawa

Sensor Type : -

Model Name : EJA118A-EMSCG-917DB-WA42C2SW20

Classification : -


Serial Number : 91V209046 907

Criteria : 0.25 % of span

Environment Temp./RH : 23 °C / 55 %

Reference Standard :

Model : Serial Number	Traceability	Certificate No.	Due Date
7250i : 66673			
P_-1 to 0 bar/g : 66673	IRPC	CL1-P220043	23-May-24
8846A : 2548001			
EL : 2548001	NA Caltechnologies	E1U222628	16-Jun-23



Calibration Results : As Found

Failed

Input [mmH ₂ O]	Output [mA]	Error [mA]	Error [% of span]	Uncertainty [% of span]
-5845.7	4.075	0.0750	0.469	0.478
-5321.0	8.073	0.0734	0.459	0.480
-4796.0	12.072	0.0705	0.441	0.481
-4271.5	16.068	0.0684	0.427	0.483
-3746.7	20.065	0.0650	0.406	0.486
-4271.5	16.070	0.0704	0.440	0.483
-4796.0	12.078	0.0765	0.478	0.481
-5321.0	8.079	0.0794	0.496	0.480
-5845.7	4.098	0.0980	0.613	0.478

Calibration Results : As Left

Passed

Input [mmH ₂ O]	Output [mA]	Error [mA]	Error [% of span]	Uncertainty [% of span]
-5845.7	4.008	0.0080	0.050	0.478
-5321.0	8.007	0.0074	0.046	0.480
-4796.0	12.005	0.0035	0.022	0.481
-4271.5	15.999	-0.0006	-0.004	0.483
-3746.7	19.995	-0.0050	-0.031	0.486
-4271.5	15.995	-0.0046	-0.029	0.483
-4796.0	11.995	-0.0065	-0.041	0.481
-5321.0	7.995	-0.0046	-0.029	0.480
-5845.7	3.995	-0.0050	-0.031	0.478

Calibrated by:

The uncertainty is

This results of measurement was found accurate as show on date as place of calibration only which is valid exclusively for calibration as mentioned in the report.