

ภาคผนวก

ภาคผนวกที่	1	ผลการพิจารณารายงานการประเมินผลกระทบสิ่งแวดล้อมของโครงการ
ภาคผนวกที่	2	ผลการตรวจสอบคุณภาพน้ำ ประจำเดือนมกราคม-มิถุนายน 2569
ภาคผนวกที่	3	เอกสารการนำส่งรายงานผลการปฏิบัติตามมาตรการป้องกัน และแก้ไขผลกระทบสิ่งแวดล้อม และมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม ประจำเดือนกรกฎาคม-ธันวาคม 2568
ภาคผนวกที่	4	แผนฉุกเฉิน
ภาคผนวกที่	5	เอกสารตรวจสอบระบบท่อน้ำใช้
ภาคผนวกที่	6	เอกสารแนะนำการใช้เครื่องปรับอากาศ
ภาคผนวกที่	7	เอกสารตรวจสอบบำรุงรักษาอุปกรณ์ไฟฟ้า
ภาคผนวกที่	8	เอกสารการขนส่งมูลฝอย
ภาคผนวกที่	9	เอกสารการสูบล้างสิ่งปฏิกูล
ภาคผนวกที่	10	ภาพเจ้าหน้าที่ตรวจสอบและสูบล้างตะกอนจากระบบบำบัดน้ำเสีย
ภาคผนวกที่	11	เอกสารการฝึกอบรมการป้องกันและระงับอัคคีภัย ประจำปี 2568
ภาคผนวกที่	12	เอกสารการตรวจสอบระบบป้องกันและระงับอัคคีภัยและอุปกรณ์ดับเพลิง
ภาคผนวกที่	13	ทีมปฏิบัติการฉุกเฉิน
ภาคผนวกที่	14	ผลการตรวจสอบคุณภาพน้ำในสระน้ำ ประจำเดือนมกราคม-มิถุนายน 2569
ภาคผนวกที่	15	รายงานแบบ ทส.1 และ ทส.2
ภาคผนวกที่	16	เอกสารการฝึกอบรมการป้องกันและระงับอัคคีภัย (ฝึกภายในโครงการ)
ภาคผนวกที่	17	เอกสารตรวจสอบและทำความสะอาดแผ่นกรองอากาศและชุดทำความเย็น
ภาคผนวกที่	18	รายงานการทำความสะอาดถังพักน้ำและบ่อเก็บน้ำ
ภาคผนวกที่	19	การล้างทำความสะอาดและฆ่าเชื้อโรคฝักบัวภายในห้องพัก
ภาคผนวกที่	20	การบำรุงรักษาเครื่องปรับอากาศ
ภาคผนวกที่	21	การตรวจสอบค่าคลอรีนอิสระตกค้างในถังพักน้ำ

ภาคผนวกที่ 1

ผลการพิจารณารายงานการประเมินผลกระทบสิ่งแวดล้อมของโครงการ



ที่ ทส 1009/4427

สำนักงานนโยบายและแผน
ทรัพยากรธรรมชาติและสิ่งแวดล้อม
60/1 ซอยพหลุพัฒนา 7 ถนนพระรามที่ 6
กรุงเทพฯ 10400

14 พฤษภาคม 2550

เรื่อง การพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการโรงแรมซัมเมอร์เซ็ท
เลคพอยท์

เรียน อธิบดีกรมการปกครอง

อ้างถึง หนังสือสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ที่ ทส 1009/7821
ลงวันที่ 11 กันยายน 2549

- สิ่งที่ส่งมาด้วย 1. เงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติ
อย่างเคร่งครัด
2. แนวทางการเสนอรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบ
สิ่งแวดล้อมและมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม

ตามหนังสือที่อ้างถึง สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม
ได้แจ้งผลการพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้
ประโยชน์อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์
ของกองทุนรวมสินทรัพย์ไทย 2 ตั้งอยู่ที่อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ ซอยสุขุมวิท
16 ถนนรัชดาภิเษก แขวงคลองเตย เขตวัฒนา กรุงเทพมหานคร พื้นที่โครงการ 3-0-92 ไร่
ประกอบด้วยอาคารโรงแรม 479 ยูนิต ห้องพัก 567 ห้อง จัดทำรายงานฯ โดยบริษัท ไบรอัน เทคโนโลยี
จำกัด ซึ่งคณะกรรมการผู้ชำนาญการพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการ
การประชุมชน ในการประชุมครั้งที่ 7/2549 เมื่อวันที่ 24 สิงหาคม 2549 มีมติไม่เห็นชอบรายงานฯ โดย
ให้แก้ไขเพิ่มเติมรายละเอียดให้ครบถ้วนสมบูรณ์ ต่อมาโครงการได้เสนอรายงานฯ เพิ่มเติม ให้
สำนักงานฯ ดำเนินการตามขั้นตอนการพิจารณารายงานฯ นั้น

2/สำนักงาน...

2

สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ได้พิจารณารายงานการ
วิเคราะห์ผลกระทบสิ่งแวดล้อมฉบับเพิ่มเติมดังกล่าว และนำเสนอคณะกรรมการผู้ชำนาญการพิจารณา
รายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการการประชุมชน ในการประชุมครั้งที่ 10/2550 เมื่อ
วันที่ 18 เมษายน 2550 คณะกรรมการผู้ชำนาญการฯ มีมติเห็นชอบรายงานการวิเคราะห์ผลกระทบ
สิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้ประโยชน์อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์
เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์ โดยให้โครงการปฏิบัติตามเงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท
เลคพอยท์ ต้องยึดถือปฏิบัติอย่างเคร่งครัด และโครงการต้องนำเสนอรายงานผลการปฏิบัติตามมาตรการ
ป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมและมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม รายละเอียด
ตามสิ่งที่ส่งมาด้วย 1 และ 2 อนึ่ง ตามมาตรา 50 วรรคท้ายของพระราชบัญญัติส่งเสริมและรักษาคุณภาพ
สิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 กำหนดให้เจ้าหน้าที่ซึ่งมีอำนาจอนุญาตตามกฎหมายในการพิจารณา
อนุญาตหรือต่อใบอนุญาต นำมาตรการที่เสนอไว้ในรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมไปกำหนด
เป็นเงื่อนไขในการสั่งอนุญาตหรือต่อใบอนุญาต โดยให้ถือว่าเป็นเงื่อนไขที่กำหนดตามกฎหมายในเรื่องนั้น
ด้วย

จึงเรียนมาเพื่อโปรดทราบ

ขอแสดงความนับถือ

(นายชนินทร์ ทองธรรมชาติ)
รองเลขาธิการ ทรัพยากรธรรมชาติและสิ่งแวดล้อม

เลขาธิการสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม

สำนักวิเคราะห์ผลกระทบสิ่งแวดล้อม
โทรศัพท์ 0-2265-6500 ต่อ 6810-6815
โทรสาร 0-2265-6616

ที่ ทส 1009/4427

สำนักงานนโยบายและแผน
ทรัพยากรธรรมชาติและสิ่งแวดล้อม
60/1 ซอยพิบูลย์พัฒนา 7 ถนนพระรามที่ 6
กรุงเทพฯ 10400

14 พฤษภาคม 2550

เรื่อง การพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการโรงแรมซัมเมอร์เซ็ท
เลคพอยท์

เรียน อธิบดีกรมการปกครอง

อ้างถึง หนังสือสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ที่ ทส 1009/7821
ลงวันที่ 11 กันยายน 2549

- สิ่งที่ส่งมาด้วย 1. เงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติ
อย่างเคร่งครัด
2. แนวทางการเสนอรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบ
สิ่งแวดล้อมและมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม

ตามหนังสือที่อ้างถึง สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม
ได้แจ้งผลการพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้
ประโยชน์อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์
ของกองทุนธนสินทรัพย์ไทย 2 ตั้งอยู่ที่อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ ซอยสุขุมวิท
16 ถนนรัชดาภิเษก แขวงคลองเตย เขตวัฒนา กรุงเทพมหานคร พื้นที่โครงการ 3-0-92 ไร่
ประกอบด้วยอาคารโรงแรม 479 ยูนิต ห้องพัก 567 ห้อง จัดทำรายงานฯ โดยบริษัท โปรเอ็น เทคโนโลยี
จำกัด ซึ่งคณะกรรมการผู้ชำนาญการพิจารณาการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการ
บริกรชุมชน ในการประชุมครั้งที่ 7/2549 เมื่อวันที่ 24 สิงหาคม 2549 มีมติไม่เห็นชอบรายงานฯ โดย
ให้แก้ไขเพิ่มเติมรายละเอียดให้ครบถ้วนสมบูรณ์ ต่อมาโครงการได้เสนอรายงานฯ เพิ่มเติม ให้
สำนักงานฯ ดำเนินการตามขั้นตอนการพิจารณารายงานฯ นั้น

2/สำนักงาน...

12.5 การบำบัดน้ำเสีย : น้ำเสียที่จะเกิดขึ้นมาจาก 2 ส่วน คือ

(ก) น้ำเสียจากกิจกรรมการก่อสร้าง

น้ำเสียที่เกิดจากกิจกรรมการก่อสร้างในแต่ละวันจะมีปริมาณน้อยมาก เนื่องจากน้ำใช้ส่วน
หนึ่งจะรวมเป็นส่วนหนึ่งของผลิตภัณฑ์หรือระเหยไป เช่น น้ำที่ใช้ในการบ่มคอนกรีต น้ำที่ฉีดพรมพื้นที่
เป็นดิน สำหรับน้ำใช้ล้างอุปกรณ์ก่อสร้างจะไหลเข้าสู่บ่อดักตะกอน เพื่อคัดแยกดินและทรายที่เปื้อนอยู่บน
อุปกรณ์ ก่อนนำไปฉีดพรมพื้นที่เพื่อลดฝุ่นละอองต่อไป

(ข) น้ำเสียจากพนักงานและคนงานก่อสร้าง

น้ำเสียที่เกิดจากพนักงานและคนงานก่อสร้างมีประมาณ 10 ลบ.ม. (ร้อยละ 100 ของ
ปริมาณน้ำใช้เพื่อการอุปโภค-บริโภค) เป็นน้ำเสียจากห้องอาบน้ำและการอุปโภคทั่วไป 7.50 ลบ.ม. (ร้อยละ
75 ของปริมาณน้ำใช้ทั้งหมด) และไหลลงสู่ระบบระบายน้ำที่บริเวณซีกล่าง ผ่านตะแกรงดักขยะก่อนไหลลง
บ่อดักตะกอน แล้วระบายลงสู่ระบบน้ำสาธารณะหน้าโครงการ ส่วนน้ำเสียจากห้องส้วม 2.50 ลบ.ม./วัน (ร้อยละ
25 ของปริมาณน้ำใช้ทั้งหมด) จะถูกบำบัดโดยบ่อเกรอะ-บ่อซึม ซึ่งจัดไว้ 14 ชุด ในพื้นที่ก่อสร้าง

12.6 การจัดการขยะมูลฝอย : ขยะมูลฝอยที่เกิดขึ้นในช่วงก่อสร้างมาจาก 2 แหล่ง ดังนี้

(ก) เศษวัสดุก่อสร้าง

เศษวัสดุก่อสร้างที่ยังใช้ได้ให้คนงานนำมาใช้ใหม่ หรือขายให้แก่ผู้ที่ต้องการ ส่วนที่นำ
กลับมาใช้ไม่ได้จะรวมรวบไว้ในถังรองรับขยะมูลฝอยขนาด 200 ลิตร ที่จัดไว้ในบริเวณพื้นที่โครงการ
จำนวน 6 ใบ

(ข) ขยะมูลฝอยที่เกิดจากการอุปโภค-บริโภคของคนงาน

ขยะมูลฝอยที่เกิดจากคนงานจำนวนสูงสุด 50 คน มีปริมาณ 50 กก./วัน หรือ 150 ลิตร/วัน
(อัตราการเกิดมูลฝอย 1.0 กก./คน/วัน หรือ 3 ลิตร/คน/วัน) จะจัดให้มีถังรองรับขยะมูลฝอยขนาด 200 ลิตร
จำนวน 6 ใบ แยกเป็นขยะเปียก 3 ใบและขยะแห้ง 3 ใบ ไม่รื้อซึมพร้อมทั้งมีฝาปิดตั้งไว้ในพื้นที่โครงการ
และว่าจ้างให้ทางห้างหุ้นส่วนจำกัด ศรีประสิทธิ์ เก็บขนไปกำจัด

12.7 การระบายน้ำและป้องกันน้ำท่วม

โครงการได้ขุดดินทำเป็นร่องระบายน้ำขนาดกว้าง x ลึกเท่ากับ 1.0 x 0.6 ม. โดยรอบโครงการ เพื่อ
ควบคุมและรองรับน้ำหลาก ก่อนระบายน้ำผ่านออกจากพื้นที่โครงการและระบายลงสู่ที่ระบายน้ำสาธารณะ
บนซอยกิ่งแก้ว 25/1 โดยมีบ่อดักขยะก่อนระบายออกสู่ที่ระบายน้ำภายนอกโครงการและมีบ่อพักน้ำของ
โครงการเป็นระยะเพื่อให้เกิดการตกตะกอนก่อนระบายน้ำออกสู่ที่ระบายน้ำสาธารณะ

สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ได้พิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมฉบับเพิ่มเติมดังกล่าว และนำเสนอคณะกรรมการผู้ชำนาญการพิจารณา รายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการบริการชุมชน ในการประชุมครั้งที่ 10/2550 เมื่อวันที่ 18 เมษายน 2550 คณะกรรมการผู้ชำนาญการฯ มีมติเห็นชอบรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้ประโยชน์อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์ โดยให้โครงการปฏิบัติตามเงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติอย่างเคร่งครัด และโครงการต้องนำเสนอรายงานผลการปฏิบัติตามมาตรการ ป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมและมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม รายละเอียด ตามสิ่งที่ส่งมาด้วย 1 และ 2 อนึ่ง ตามมาตรา 50 วรรคท้ายของพระราชบัญญัติส่งเสริมและรักษาคุณภาพ สิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 กำหนดให้เจ้าหน้าที่ซึ่งมีอำนาจอนุญาตตามกฎหมายในการพิจารณา อนุญาตหรือต่อใบอนุญาต นำมาตรการที่เสนอไว้ในรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมไปกำหนด เป็นเงื่อนไขในการสั่งอนุญาตหรือต่อใบอนุญาต โดยให้ถือว่าเป็นเงื่อนไขที่กำหนดตามกฎหมายในเรื่องนั้น ด้วย

จึงเรียนมาเพื่อโปรดทราบ

ขอแสดงความนับถือ

(นายประสิทธิ์ ทองธรรมสวัสดิ์)

รองเลขาธิการนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม

เลขาธิการสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม

สำนักวิเคราะห์ผลกระทบสิ่งแวดล้อม

โทรศัพท์ 0-2265-6500 ต่อ 6810-6815

โทรสาร 0-2265-6616

5
25/5/50
1/5
1/5
1/5
1/5

(ก) บ่อน้ำมัน

การพัฒนาโครงการจะทำให้อัตราการไหลของน้ำฝนออกสู่พื้นที่โครงการมากขึ้น เท่ากับ 0.0517 ลบ.ม./วินาที เพราะฉะนั้นการพัฒนาโครงการต้องสร้างบ่อน้ำมันปริมาณอย่างน้อย 109.83 ลบ.ม. ซึ่งโครงการได้สร้างให้มีขนาด 110 ลบ.ม. เพื่อให้มีพื้นที่ตกลงบนพื้นที่โครงการถูกรวบรวมลงบ่อพักแล้วผ่านท่อระบายน้ำภายในพื้นที่โครงการ ขนาด $\varnothing$ 0.4 ม. มาบ่อน้ำมันที่บ่อน้ำมัน ก่อนไหลผ่านท่อระบายน้ำ ขนาด $\varnothing$ 0.2 ม. เป็นการควบคุมอัตราการระบายน้ำออกนอกโครงการให้ ลดลงเหลือ 0.04 ลบ.ม./วินาที ซึ่งเป็นอัตราการระบายน้ำที่น้อยกว่าอัตราการระบายน้ำก่อนพัฒนาโครงการ (0.043 ลบ.ม./วินาที) จากนั้นจึงระบายออกผ่านท่อระบายน้ำภายนอกโครงการ ขนาด $\varnothing$ 0.6 ม. เพื่อลงสู่ท่อระบายน้ำสาธารณะบริเวณซอยกิ่งแก้ว 25/1 ต่อไป

9.5 การจัดการมูลฝอย

(ก) ปริมาณขยะมูลฝอยที่เกิดขึ้นจากโครงการ

ปริมาณขยะมูลฝอยจากสำนักงาน = 0.034 ลบ.ม./วัน หรือ 2.462 กก./วัน

ปริมาณขยะมูลฝอยจากร้านค้า = 0.083 ลบ.ม./วัน หรือ 28.534 กก./วัน

ปริมาณขยะมูลฝอยจากห้องครัว = 0.028 ลบ.ม./วัน หรือ 8 กก./วัน

ปริมาณขยะมูลฝอยจากผู้พักอาศัย = 1.836 ลบ.ม./วัน หรือ 612 กก./วัน

ดังนั้น โครงการจะมีขยะมูลฝอยเกิดขึ้นทั้งสิ้น 1.981 ลบ.ม./วัน หรือ 650.996 กก./วัน

(ข) ภาชนะรองรับขยะมูลฝอยและห้องพักมูลฝอยรวมของโครงการ

โครงการได้จัดเตรียมถังรองรับขยะมูลฝอยแบบมีฝาปิดขนาด 100 ลิตร จำนวนชั้นละ 2 ถัง โดยมีพนักงานทำความสะอาดรวบรวมขยะมูลฝอยไปเก็บรวมไว้ที่ห้องพักมูลฝอยรวม

ห้องพักมูลฝอยรวมของโครงการ มีความกว้าง 4.00 ม. ความยาว 4.00 ม. และความสูง 2.40 ม. จำนวน 1 ห้อง สามารถกองขยะมูลฝอยได้สูง 1.5 ม. หรือสามารถสะสมขยะมูลฝอยรวมสูงสุด เท่ากับ 24.0 ลบ.ม./ห้อง และจากปริมาณขยะมูลฝอยของโครงการเท่ากับ 1.981 ลบ.ม./วัน ดังนั้นห้องพัก ขยะมูลฝอยรวมของโครงการสามารถรองรับขยะมูลฝอยได้ประมาณ 12 วัน ซึ่งเป็นไปตามเกณฑ์ประกอบการ ประเมินผลกระทบสิ่งแวดล้อมของสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ที่ กำหนดให้ห้องพักมูลฝอยรวมต้องรองรับปริมาณขยะมูลฝอยได้ไม่น้อยกว่า 3 วัน (ตำแหน่งห้องพักขยะ มูลฝอยรวมแสดงดังรูปที่ 2.2-1 หน้า 2-7 ในรายงานฉบับหลัก)

ที่ ทส 1009/4426



สำนักงานนโยบายและแผน
ทรัพยากรธรรมชาติและสิ่งแวดล้อม
60/1 ซอยพิบูลวัฒนา 7 ถนนพระรามที่ 6
กรุงเทพฯ 10400

14 พฤษภาคม 2550

เรื่อง การพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการโรงแรมซัมเมอร์เซ็ท
เลคพอยท์

เรียน กรรมการผู้จัดการกองทุนรวมสินทรัพย์ไทย 2

อ้างถึง หนังสือสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ที่ ทส 1009/7825
ลงวันที่ 11 กันยายน 2549

- สิ่งที่ส่งมาด้วย 1. เงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติอย่าง
เคร่งครัด
2. แนวทางการเสนอรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบ
สิ่งแวดล้อมและมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม

ตามหนังสือที่อ้างถึง สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม
ได้แจ้งผลการพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้
ประโยชน์อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ของ
กองทุนรวมสินทรัพย์ไทย 2 ตั้งอยู่ที่อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ ซอยสุขุมวิท 16
ถนนรัชดาภิเษก แขวงคลองเตย เขตวัฒนา กรุงเทพมหานคร พื้นที่โครงการ 3-0-92 ไร่
ประกอบด้วยอาคารโรงแรม 479 ยูนิต ห้องพัก 567 ห้อง จัดทำรายงานฯ โดยบริษัท โป้นเอ็น เทคโนโลยี
จำกัด ซึ่งคณะกรรมการผู้ชำนาญการพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการ
บริการชุมชน ในการประชุมครั้งที่ 7/2549 เมื่อวันที่ 24 สิงหาคม 2549 มีมติไม่เห็นชอบรายงานฯ โดย
ให้แก้ไขเพิ่มเติมรายละเอียดให้ครบถ้วนสมบูรณ์ ต่อมาโครงการได้เสนอรายงานฯ เพิ่มเติม ให้
สำนักงานฯ ดำเนินการตามขั้นตอนการพิจารณารายงานฯ

2/สำนักงาน...

2

สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ได้พิจารณารายงานการ
วิเคราะห์ผลกระทบสิ่งแวดล้อมฉบับเพิ่มเติมดังกล่าว และนำเสนอคณะกรรมการผู้ชำนาญการพิจารณา
รายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการบริการชุมชน ในการประชุมครั้งที่ 10/2550
เมื่อวันที่ 18 เมษายน 2550 คณะกรรมการผู้ชำนาญการฯ มีมติเห็นชอบรายงานการวิเคราะห์
ผลกระทบสิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้ประโยชน์อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส
เรสซิเดนส์ เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ของกองทุนรวมสินทรัพย์ไทย 2 โดยให้โครงการปฏิบัติ
ตามเงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติอย่างเคร่งครัด และโครงการ
ต้องนำเสนอรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมและมาตรการ
ติดตามตรวจสอบคุณภาพสิ่งแวดล้อม รายละเอียดตามสิ่งที่ส่งมาด้วย 1 และ 2 โดยโครงการจะต้อง
ประสานให้บริษัทที่ปรึกษารวบรวมรายละเอียดทั้งหมดตามลำดับการพิจารณาของคณะกรรมการฯ จัดทำ
เป็นรายงานฉบับสมบูรณ์และแผ่นบันทึกข้อมูล (CD - ROM) ในรูปของ Digital File (pdf) Adobe Acrobat
เสนอต่อสำนักงานฯ ภายในเวลา 1 เดือน เพื่อใช้เป็นเอกสารอ้างอิงและส่งให้หน่วยงานที่เกี่ยวข้องต่อไป

จึงเรียนมาเพื่อโปรดพิจารณาดำเนินการในส่วนที่เกี่ยวข้องต่อไป

ขอแสดงความนับถือ

(นายชินันท์ ทองธรรมชาติ)

รองเลขาธิการ วิทยาการวางแผน

เลขาธิการสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม

สำนักวิเคราะห์ผลกระทบสิ่งแวดล้อม
โทรศัพท์ 0-2265-6500 ต่อ 6810-6815
โทรสาร 0-2265-6616

ที่ ทส 1009/4426

สำนักงานนโยบายและแผน
ทรัพยากรธรรมชาติและสิ่งแวดล้อม
60/1 ซอยพิบูลย์วัฒนา 7 ถนนพระรามที่ 6
กรุงเทพฯ 10400

14 พฤษภาคม 2550

เรื่อง การพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการโรงแรมซัมเมอร์เซ็ท
เลคพอยท์

เรียน กรรมการผู้จัดการกองทุนรวมสินทรัพย์ไทย 2

อ้างถึง หนังสือสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ที่ ทส 1009/7825
ลงวันที่ 11 กันยายน 2549

- สิ่งที่ส่งมาด้วย 1. เงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติอย่าง
เคร่งครัด
2. แนวทางการเสนอรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบ
สิ่งแวดล้อมและมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม

ตามหนังสือที่อ้างถึง สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม
ได้แจ้งผลการพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้
ประโยชน์อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ของ
กองทุนรวมสินทรัพย์ไทย 2 ตั้งอยู่ที่อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ ซอยสุขุมวิท 16
ถนนรัชดาภิเษก แขวงคลองเตย เขตวัฒนา กรุงเทพมหานคร พื้นที่โครงการ 3-0-92 ไร่
ประกอบด้วยอาคารโรงแรม 479 บูนิต ห้องพัก 567 ห้อง จัดทำรายงานฯ โดยบริษัท โปรเอ็น เทคโนโลยี
จำกัด ซึ่งคณะกรรมการผู้ชำนาญการพิจารณา รายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการ
บริการชุมชน ในการประชุมครั้งที่ 7/2549 เมื่อวันที่ 24 สิงหาคม 2549 มีมติไม่เห็นชอบรายงานฯ โดย
ให้แก้ไขเพิ่มเติมรายละเอียดให้ครบถ้วนสมบูรณ์ ต่อมาโครงการได้เสนอรายงานฯ เพิ่มเติม ให้
สำนักงานฯ ดำเนินการตามขั้นตอนการพิจารณา รายงานฯ นั้น

2/สำนักงาน...

2

สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ได้พิจารณา รายงานการ
วิเคราะห์ผลกระทบสิ่งแวดล้อมฉบับเพิ่มเติมดังกล่าว และนำเสนอคณะกรรมการผู้ชำนาญการพิจารณา
รายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการบริการชุมชน ในการประชุมครั้งที่ 10/2550
เมื่อวันที่ 18 เมษายน 2550 คณะกรรมการผู้ชำนาญการฯ มีมติเห็นชอบรายงานการวิเคราะห์
ผลกระทบสิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้ประโยชน์อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส
เรสซิเดนส์ เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ของกองทุนรวมสินทรัพย์ไทย 2 โดยให้โครงการปฏิบัติ
ตามเงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติอย่างเคร่งครัด และโครงการ
ต้องนำเสนอรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมและมาตรการ
ติดตามตรวจสอบคุณภาพสิ่งแวดล้อม รายละเอียดตามสิ่งที่ส่งมาด้วย 1 และ 2 โดยโครงการจะต้อง
ประสานให้บริษัทที่ปรึกษารวบรวมรายละเอียดทั้งหมดตามลำดับการพิจารณาของคณะกรรมการฯ จัดทำ
เป็นรายงานฉบับสมบูรณ์และแนบบันทึกข้อมูล (CD - ROM) ในรูปของ Digital File (pdf) Adobe Acrobat
เสนอต่อสำนักงานฯ ภายในเวลา 1 เดือน เพื่อใช้เป็นเอกสารอ้างอิงและส่งให้หน่วยงานที่เกี่ยวข้องต่อไป

จึงเรียนมาเพื่อโปรดพิจารณาดำเนินการในส่วนที่เกี่ยวข้องต่อไป

ขอแสดงความนับถือ

(นายชนินทร์ ทองธรรมชาติ)
รองเลขาธิการฯ รักษาการแทน
เลขาธิการสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม

สำนักวิเคราะห์ผลกระทบสิ่งแวดล้อม
โทรศัพท์ 0-2265-6500 ต่อ 6810-6815
โทรสาร 0-2265-6616

ผู้ตรวจ
ผู้แทน
ผู้พิมพ์
ผู้ร่าง
ผู้คัดค้าน

11. ความเพียงพอของพื้นที่สีเขียวในโครงการ

โครงการจัดให้มีพื้นที่สีเขียวเป็นพื้นที่ทั้งหมด 926.02 ตร.ม. (ร้อยละ 28.94 ของพื้นที่โครงการ) หรือคิดเป็นอัตราส่วนพื้นที่สีเขียวต่อผู้อยู่อาศัยและใช้ประโยชน์ในพื้นที่โครงการ 1.30 ตร.ม. ต่อ 1 คน ทั้งนี้จะเป็นพื้นที่สีเขียวบริเวณชั้นล่าง 699.08 ตร.ม. (ร้อยละ 75.49 ของพื้นที่สีเขียวทั้งหมด) และในพื้นที่สีเขียวชั้นล่างนี้จะเป็นไม้ยืนต้น 376.42 ตร.ม. (ร้อยละ 53.85 ของพื้นที่สีเขียวชั้นล่าง) การจัดพื้นที่สีเขียวจะกระจายอยู่บริเวณโดยรอบพื้นที่โครงการและบนชั้นดาดฟ้าของอาคาร (เป็นไปตามองค์ประกอบการประเมินผลกระทบสิ่งแวดล้อมของสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ซึ่งกำหนดให้โครงการต้องมีสัดส่วนของพื้นที่สีเขียวต่อผู้พักอาศัยไม่น้อยกว่า 1 ตร.ม. ต่อ 1 คน และต้องจัดให้มีพื้นที่สีเขียวบริเวณชั้นล่างไม่น้อยกว่าร้อยละ 50 ของพื้นที่สีเขียวที่ต้องจัดให้มีตามเกณฑ์ ทั้งนี้ต้องเป็นไม้ยืนต้นไม่น้อยกว่าร้อยละ 50 ของพื้นที่สีเขียวชั้นล่างที่ต้องจัดให้มีตามเกณฑ์)

ผังภูมิสถาปัตย์และพื้นที่สีเขียวในพื้นที่โครงการ แสดงดังรูปที่ 2.4-1 หน้า 2-28 ในรายงานฉบับหลัก

12. สรุปรายละเอียดเกี่ยวกับการก่อสร้างโครงการ

12.1 ระยะเวลาในการก่อสร้าง : ประมาณ 450 วัน หรือ 15 เดือน

12.2 คนงานก่อสร้าง : ช่วงที่มีคนงานสูงสุดจะมีจำนวนประมาณ 50 คน และคนงานก่อสร้างจะพักอยู่ในพื้นที่โครงการ

12.3 น้ำใช้ : ขอดัดตั้งมิเตอร์น้ำชั่วคราวจากการประปานครหลวง สำนักงานประปาสาขาพระโขนง โดยมีกิจกรรมการใช้น้ำ ดังนี้

(ก) การใช้น้ำเพื่อการอุปโภค-บริโภค

การใช้น้ำเพื่อการอุปโภค-บริโภคของคนงานก่อสร้าง พิจารณาจากจำนวนคนงานก่อสร้างสูงสุด 50 คน และอัตราการใช้น้ำสำหรับคนงานที่พักอยู่ในพื้นที่โครงการเท่ากับ 200 ลิตร/คน/วัน (Metcalf & Eddy Inc, 1977) ดังนั้นมีการใช้น้ำประมาณ 10.00 ลบ.ม./วัน ส่วนน้ำดื่มทางผู้รับเหมาก่อสร้างจะจัดหาน้ำดื่มบรรจุขวดไว้ให้คนงาน

(ข) การใช้น้ำเพื่อการก่อสร้าง

การใช้น้ำเพื่อก่อสร้างโครงการจะเป็นการใช้น้ำเพื่อล้างเครื่องมือ ผิดพรหมพื้นที่ เป็นต้น ซึ่งคาดว่ามิอัตราการใช้น้ำประมาณ 20.00 ลบ.ม./วัน

ดังนั้น ปริมาณน้ำใช้ในช่วงการก่อสร้างของโครงการประมาณ 30 ลบ.ม./วัน

21.4 ไฟฟ้า : ขอใช้ไฟฟ้าชั่วคราวจากการไฟฟ้านครหลวงเขตประเวศ



ที่ ทส 1009/4425

สำนักงานนโยบายและแผน
ทรัพยากรธรรมชาติและสิ่งแวดล้อม
60/1 ซอยพิบูลย์พัฒนา 7 ถนนพระรามที่ 6
กรุงเทพฯ 10400

14 พฤษภาคม 2550

เรื่อง การพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการโรงแรมซัมเมอร์เซ็ท
เลคพอยท์

เรียน ผู้ว่าราชการกรุงเทพมหานคร

อ้างถึง หนังสือสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ที่ ทส 1009/7824
ลงวันที่ 11 กันยายน 2549

สิ่งที่ส่งมาด้วย 1. เรือนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติ
อย่างเคร่งครัด
2. แนวทางการเสนอรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบ
สิ่งแวดล้อมและมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม

ตามหนังสือที่อ้างถึง สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม
ได้แจ้งผลการพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้
ประโยชน์อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ของ
กองทุนรวมสินทรัพย์ไทย 2 ตั้งอยู่ที่อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ ซอยสุขุมวิท 16
ถนนรัชดาภิเษก แขวงคลองเตย เขตวัฒนา กรุงเทพมหานคร พื้นที่โครงการ 3-0-92 ไร่
ประกอบด้วยอาคารโรงแรม 479 ยูนิต ห้องพัก 567 ห้อง จัดทำรายงานฯ โดยบริษัท โปรเอ็น เทคโนโลยี
จำกัด ซึ่งคณะกรรมการผู้ชำนาญการพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการ
บริการชุมชน ในการประชุมครั้งที่ 7/2549 เมื่อวันที่ 24 สิงหาคม 2549 มีมติไม่เห็นชอบรายงานฯ โดย
ให้แก้ไขเพิ่มเติมรายละเอียดให้ครบถ้วนสมบูรณ์ ต่อมาโครงการได้เสนอรายงานฯ เพิ่มเติม ให้
สำนักงานฯ ดำเนินการตามขั้นตอนการพิจารณารายงานฯ นั้น

2/สำนักงาน...

สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ได้พิจารณาการวิเคราะห์ผลกระทบสิ่งแวดล้อมฉบับเพิ่มเติมดังกล่าว และนำเสนอคณะกรรมการผู้ชำนาญการพิจารณา รายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการบริการชุมชน ในการประชุมครั้งที่ 10/2550 เมื่อวันที่ 18 เมษายน 2550 คณะกรรมการผู้ชำนาญการฯ มีมติเห็นชอบรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้ประโยชน์อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ของกองทุนรวมสินทรัพย์ไทย 2 โดยให้โครงการปฏิบัติตามเงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติอย่างเคร่งครัด และโครงการต้องนำเสนอรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมและมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม รายละเอียดตามสิ่งที่ส่งมาด้วย 1 และ 2 อนึ่ง ตามมาตรา 50 วรรคท้ายของพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 กำหนดให้เจ้าหน้าที่ซึ่งมีอำนาจอนุญาตตามกฎหมายในการพิจารณาอนุญาตหรือต่อใบอนุญาต นำมาตรการที่เสนอไว้ในรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมไปกำหนดเป็นเงื่อนไขในการสั่งอนุญาตหรือต่อใบอนุญาต โดยให้ถือว่าเป็นเงื่อนไขที่กำหนดตามกฎหมายในเรื่องนั้นด้วย ทั้งนี้ สำนักงานฯ ได้มีหนังสือแจ้งกองทุนรวมสินทรัพย์ไทย 2 และสำเนาหนังสือแจ้งบริษัท ไพรเอ็น เทคโนโลยี จำกัด เพื่อดำเนินการต่อไปด้วยแล้ว

จึงเรียนมาเพื่อโปรดทราบ

ขอแสดงความนับถือ

(นายชนินทร์ ทองธรรมชาติ)

รองเลขาธิการฯ รักษาการแทน

เลขาธิการสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม

สำนักวิเคราะห์ผลกระทบสิ่งแวดล้อม

โทรศัพท์ 0-2265-6500 ต่อ 6810-6815

โทรสาร 0-2265-6616

ที่ ทส 1009/4425

สำนักงานนโยบายและแผน

ทรัพยากรธรรมชาติและสิ่งแวดล้อม

60/1 ซอยพินุลพัฒนา 7 ถนนพระรามที่ 6

กรุงเทพฯ 10400

14 พฤษภาคม 2550

เรื่อง การพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์

เรียน ผู้ว่าราชการกรุงเทพมหานคร

อ้างถึง หนังสือสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ที่ ทส 1009/7824 ลงวันที่ 11 กันยายน 2549

- สิ่งที่ส่งมาด้วย 1. เงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติ อย่างเคร่งครัด
2. แนวทางการเสนอรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบ สิ่งแวดล้อมและมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม

ตามหนังสือที่อ้างถึง สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ได้แจ้งผลการพิจารณาการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้ประโยชน์อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ของกองทุนรวมสินทรัพย์ไทย 2 ตั้งอยู่ที่อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ ซอยสุขุมวิท 16 ถนนรัชดาภิเษก แขวงคลองเตย เขตวัฒนา กรุงเทพมหานคร พื้นที่โครงการ 3-0-92 ไร่ ประกอบด้วยอาคารโรงแรม 479 ยูนิต ห้องพัก 567 ห้อง จัดทำรายงานฯ โดยบริษัท ไพรเอ็น เทคโนโลยี จำกัด ซึ่งคณะกรรมการผู้ชำนาญการพิจารณาการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการบริการชุมชน ในการประชุมครั้งที่ 7/2549 เมื่อวันที่ 24 สิงหาคม 2549 มีมติไม่เห็นชอบรายงานฯ โดยให้แก้ไขเพิ่มเติมรายละเอียดให้ครบถ้วนสมบูรณ์ ต่อมาโครงการได้เสนอรายงานฯ เพิ่มเติม ให้สำนักงานฯ ดำเนินการตามขั้นตอนการพิจารณาการรายงานนั้น

2/สำนักงาน...

ระเบียบวาระการประชุม

คณะผู้บริหารผู้อำนวยการพิจารณาโครงการวิเคราะห์ผลกระทบสิ่งแวดล้อม-พื้นที่โครงการที่พักอาศัย
ครั้งที่ 21/2550 วันที่ 18 พฤษภาคม 2550 ณ ห้องประชุม 3 ชั้น 6 สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม กรุงเทพมหานคร 10400

- วาระที่ 1 เรื่องที่ประธานแจ้งที่ประชุมทราบ
- วาระที่ 2 เรื่องรับรองรายงานการประชุม ครั้งที่ 20/2550 พฤษภาคม 2550
- วาระที่ 3 ผลที่ประชุมของมติเบื้องต้นรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการบ้านทะเลสาบ
- วาระที่ 4 เรื่องสืบเนื่องเพื่อพิจารณา
เรียน ผู้ว่าราชการจังหวัดเพชรบุรี
4.1 โครงการ ที่.ตบลิ.ว.ง.ค.อ.ม.ด.ย.บ.ช. ค.อ.น.ด.ม.น.ย.ม. 1
ตั้งอยู่ที่ หมู่ที่ 5 ซอยนาเกลือ 16 ตำบลนาเกลือ อำเภอบางละมุง จังหวัดชลบุรี
สิ่งที่ส่งมาด้วย 1. หนังสือขออนุญาตขุดลอกคลองสาธารณะในที่ดินโฉนดที่ดินเลขที่ 177/50 ลงวันที่ 25 เมษายน 2550
2. สัญญาเช่าที่ดินของกรมที่ดินจากกรมที่ดินและสำนักงานที่ดินจังหวัดชลบุรี
4.3 โครงการ ขุดลอกคลองสาธารณะ 41 แห่ง ถนนสุขุมวิท
ขุดลอกคลองสาธารณะ 41 แห่ง ถนนสุขุมวิท และแนวทางการจัดทำรายงานผลกระทบ
ตั้งอยู่ที่ ซอยวัดศรีเยี่ยม ถนนศรีนครินทร์ แขวงบางนา เขต กทม.
สิ่งแวดล้อมเบื้องต้น และรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมในเขตพื้นที่
- วาระที่ 5 เรื่องเพื่อพิจารณา
5.1 โครงการขุดลอกคลองสาธารณะ อำเภอสองพี่น้อง จังหวัดสุพรรณบุรี อำเภอหัวหิน และอำเภอบางละมุง
จังหวัดสุพรรณบุรี
5.2 โครงการ คอนโดมิเนียม สูง 8 ชั้น
ตั้งอยู่ที่ ซอยเหล็กละ อ.หนองบัว 50 พระโขนง กรุงเทพมหานคร
ด้วย บริษัท ศรีสุขคำ จำกัด ได้มอบอำนาจให้บริษัท ไทย-ไทยวิศวกรรม จำกัด จัดทำและ
5.3 โครงการ ประภาคาร เพลส
เสนอรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมเบื้องต้นจากสำนักงานฯ ประกอบด้วยอาคารชุดพักอาศัย เดิมได้รับความ
ระอา จังหวัดเพชรบุรี ให้สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ดังรายละเอียด
วาระที่ 6 เรื่องที่ 1 ซึ่งรายงานฯ ฉบับดังกล่าวระบุว่าโครงการเป็นอาคารชุดพักอาศัย เดิมได้รับความ
เห็นชอบรายงานผลกระทบสิ่งแวดล้อมเบื้องต้นจากสำนักงานฯ ประกอบด้วยอาคารชุดพักอาศัย ขนาด
ความสูง 1-4 ชั้น จำนวน 41 หลัง มีจำนวนห้องชุด 79 ห้อง ขนาดพื้นที่โครงการ 13-2-03 ไร่ โฉนดที่ดิน
เลขที่ 9909 และ 19864 ต่อมาได้มีการแบ่งแยกโฉนดที่ดินเลขที่ 9909 เป็น 3 แปลง และได้ดำเนินการ
ก่อสร้างโครงการส่วนขยาย ประกอบด้วยอาคารชุดพักอาศัย ขนาดความสูง 2 ชั้น จำนวน 9 อาคาร มี
จำนวนห้องชุด 9 ห้อง บนโฉนดที่ดินเลขที่ 65529 ขนาดพื้นที่ 1-1-28 ไร่ (ที่แบ่งแยกออกจากโฉนด
ที่ดินเลขที่ 9909) รวมจำนวนห้องชุดของโครงการส่วนเดิมและส่วนขยายทั้งสิ้น 88 ห้อง จึงเข้าข่ายต้อง
จัดทำและเสนอรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อม ในชั้นขอขยายโครงการ

2/ สำนักงาน ...

2

สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ได้พิจารณาโครงการ
วิเคราะห์ผลกระทบสิ่งแวดล้อมฉบับเพิ่มเติมดังกล่าว และนำเสนอคณะกรรมการผู้อำนวยการพิจารณา
รายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการบริการชุมชน ในการประชุมครั้งที่ 10/2550
เมื่อวันที่ 18 เมษายน 2550 คณะกรรมการผู้อำนวยการฯ มีมติเห็นชอบรายงานการวิเคราะห์
ผลกระทบสิ่งแวดล้อมโครงการขอเปลี่ยนแปลงการใช้ประโยชน์อาคารชั้นเมอริเซ็ท เลคพอยท์ เซอร์วิส
เรสซิเดนส์ เป็นโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ของกองทุนรวมสินทรัพย์ไทย 2 โดยให้โครงการปฏิบัติ
ตามเงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติอย่างเคร่งครัด และโครงการ
ต้องนำเสนอรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมและมาตรการ
ติดตามตรวจสอบคุณภาพสิ่งแวดล้อม รายละเอียดตามที่ส่งมาด้วย 1 และ 2 อนึ่ง ตามมาตรา 50
วรรคท้ายของพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 กำหนดให้
เจ้าหน้าที่ซึ่งมีอำนาจอนุญาตตามกฎหมายในการพิจารณาอนุญาตหรือต่อใบอนุญาต นำมาตรการที่
เสนอไว้ในรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมไปกำหนดเป็นเงื่อนไขในการสั่งอนุญาตหรือต่อ
ใบอนุญาต โดยให้ถือว่าเป็นเงื่อนไขที่กำหนดตามกฎหมายในเรื่องนั้นด้วย ทั้งนี้ สำนักงานฯ ได้มี
หนังสือแจ้งกองทุนรวมสินทรัพย์ไทย 2 และสำเนาหนังสือแจ้งบริษัท โปรเอน เทคโนโลยี จำกัด เพื่อ
ดำเนินการต่อไปด้วยแล้ว

จึงเรียนมาเพื่อโปรดทราบ

ขอแสดงความนับถือ

(นายชินห์ ท่องธรรมชาติ)
รองเลขาธิการ รักษาการกรม

เลขาธิการสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม

สำนักวิเคราะห์ผลกระทบสิ่งแวดล้อม
โทรศัพท์ 0-2265-6500 ต่อ 6810-6815
โทรสาร 0-2265-6616

ผู้ตรวจ
ผู้ทำ
ผู้พิมพ์
ผู้ร่าง
ผู้แก้ไข

บันทึกข้อความ

ส่วนราชการ สวผ./โครงการบริการชุมชนและที่พักอาศัย โทร. 6623
ที่ สวผ. วันที่ พฤษภาคม 2550
เรื่อง วันนั่งพิจารณาตัดสินครั้งแรกของศาลปกครองกลาง ในคดีหมายเลขดำที่ 877/2548

เรียน ผอ.กนต.

ตามที่ กนต. แจ้งว่าสำนักงานคดีปกครอง ได้แจ้งกำหนดวันนั่งพิจารณาตัดสินครั้งแรกของศาลปกครองกลาง ในคดีหมายเลขดำที่ 877/2548 ในวันที่ 23 พฤษภาคม 2550 เวลา 11.00 น. ที่ศาลปกครองกลาง ชั้น 31 ห้องพิจารณาคดีที่ 7 ซึ่งมีนายตั้งใจ ศาสตรศิธิ กับพวกรวม 8 คน เป็นผู้ฟ้องคดี จึงขอให้ สวผ. นำเรียนคณะกรรมการผู้ชำนาญการฯ หากมีความประสงค์จะส่งข้อเท็จจริงใดให้ศาลเพิ่มเติม ให้ส่งเอกสารดังกล่าวให้ กนต. ภายในวันที่ 14 พฤษภาคม 2550 และขอให้แจ้งรายชื่อผู้ประสานคดี เพื่อ กนต. จะได้ดำเนินการต่อไป ความละเอียดแจ้งแล้ว นั้น

สวผ. ได้นำเรื่องดังกล่าวเสนอคณะกรรมการผู้ชำนาญการฯ ในการประชุมครั้งที่ 19/2550 เมื่อวันที่ 3 พฤษภาคม 2550 ซึ่งคณะกรรมการผู้ชำนาญการฯ ไม่มีความประสงค์จะแจ้งข้อเท็จจริงใดต่อศาลเป็นการเพิ่มเติม และมอบหมายให้ประธานกรรมการ (เลขาธิการสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม) ดำเนินการทางคดีแทนต่อไป รายละเอียดมติที่ประชุมตามเอกสารแนบ และขอแจ้งรายชื่อผู้ประสานงานคดี ดังนี้

- นางสาวสุชญา อัมราลิขิต ผอ.โครงการบริการชุมชนและที่พักอาศัย
- นางสาวพรรณนิภา หล่อเรืองศิลป์ นักวิชาการสิ่งแวดล้อม 6 ว.

จึงเรียนมาเพื่อโปรดพิจารณาดำเนินการต่อไป

เงื่อนไขที่โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ของกองทุนรวมสินทรัพย์ไทย 2 ต้องยึดถือปฏิบัติอย่างเคร่งครัด

โครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ของกองทุนรวมสินทรัพย์ไทย 2 ตั้งอยู่ที่อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนส์ ซอยสุขุมวิท 16 ถนนรัชดาภิเษก แขวงคลองเตย เขตวัฒนา กรุงเทพมหานคร พื้นที่โครงการ 3-0-92 ไร่ ประกอบด้วยอาคารที่มีอยู่เดิมในปัจจุบัน คืออาคาร A สูง 31 ชั้น ความสูง 107 เมตร และอาคาร B สูง 26 ชั้น ความสูง 82 เมตร รวมทั้งห้องพัก 479 ยูนิต จำนวนห้องพัก 567 ห้อง จะต้องปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม และมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อมตามที่เสนอไว้ในรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อม รายละเอียดดังต่อไปนี้

- โครงการจะต้องยึดถือปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม และมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อมตามที่เสนอไว้ในรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการโรงแรมซัมเมอร์เซ็ท เลคพอยท์ ของกองทุนรวมสินทรัพย์ไทย 2 และรายละเอียดในเอกสารแนบอย่างเคร่งครัด
- โครงการจะต้องบันทึกผลการติดตามตรวจสอบการดำเนินการหรือการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม และมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อมตามที่เสนอไว้ในรายงานฯ และส่งผลการดำเนินการมายังหน่วยงานผู้อนุญาตและสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ตามแนวทางการนำเสนอผลการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม รายละเอียดตามสิ่งที่ส่งมาด้วย 2
- หากโครงการจะเปลี่ยนแปลงรายละเอียดโครงการ รวมทั้งมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม และมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อมให้แตกต่างจากที่เสนอไว้ในรายงานฯ โครงการจะต้องเสนอรายละเอียดการเปลี่ยนแปลงดังกล่าว ให้หน่วยงานผู้อนุญาต และสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม เพื่อนำเสนอคณะกรรมการผู้ชำนาญการพิจารณาให้ความเห็นชอบด้านสิ่งแวดล้อมก่อนดำเนินการเปลี่ยนแปลงใด ๆ
- หากได้รับการร้องเรียนจากประชาชนว่า ได้รับความเดือดร้อนรำคาญจากกิจกรรมการดำเนินโครงการ หรือโครงการก่อให้เกิดความเสียหายแก่สาธารณสมบัติ เจ้าของโครงการจะต้องดำเนินการแก้ไขปัญหาดังกล่าวโดยไม่ชักช้า และแจ้งหน่วยงานผู้อนุญาต สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม และหน่วยงานที่เกี่ยวข้องทราบ เพื่อหาแนวทางและมาตรการในการแก้ไขปัญหาต่อไป

หน้า 1 หน้า
ลงชื่อ ผู้รับแจ้ง

ตารางที่ 1 แสดงผลกระทบสิ่งแวดล้อมที่สำคัญ มาตรการป้องกันและลดผลกระทบสิ่งแวดล้อมและมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
ของโครงการเปลี่ยนแปลงการใช้ประโยชน์ อาคารซีเอ็มเอวีซีเอ็ม เลคพอยท์ เซอร์วิส เรสซิเดนส์ เป็นโรงแรม ซีเอ็มเอวีซีเอ็ม เลคพอยท์

ก. ระยะตัดแปลงอาคาร

องค์ประกอบทางสิ่งแวดล้อม และคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบ สิ่งแวดล้อม
1. คุณภาพอากาศ/ระดับเสียง	กิจกรรมการตัดแปลงอาคาร และการขนส่งวัสดุอุปกรณ์ ก่อให้เกิดการฟุ้งกระจายของฝุ่นละออง และเสียงดัง ดังนั้น ผู้รับเหมาและเจ้าของโครงการได้กำหนดมาตรการ และปฏิบัติตามข้อบังคับอย่างเคร่งครัด เพื่อลดผล กระทบที่จะเกิดขึ้นซึ่งเป็นผลกระทบในระดับต่ำ และ เมื่อหมดกิจกรรมนี้ผลกระทบจะหมดไป	ปฏิบัติตามกฎกระทรวงฉบับที่ 4 (2526) ออกตามความใน พ.ร.บ. ควบคุมอาคาร 2522 และข้อบังคับของกทม. ตาม ประกาศกรุงเทพมหานคร 2534 อย่างเคร่งครัด อาทิเช่น - รถบรรทุกวัสดุอุปกรณ์ต้องปิดคลุมกระเบื้องหลังคาเพื่อ ลดการรบกวนหรือฟุ้งกระจายของวัสดุก่อสร้าง - ทำความสะอาดรถบรรทุกและล้อรถ ก่อนออกสู่ถนนหรือทาง จราจรอื่นๆ - ดำเนินการภายในอาคารเท่านั้น ซึ่งเป็นการปิดกั้นล้อมรอบ บริเวณที่จะทำการก่อสร้าง/ตัดแปลงอาคาร - การกองวัสดุที่มีฝุ่นต้องปิดหรือปกคลุม หรือเก็บในที่ปิดล้อม และฉีดพรมด้วยน้ำเพื่อให้ฝุ่นเปียกอยู่เสมอ • กำหนดช่วงการตัดแปลงอาคารให้อยู่ในช่วงกลางวัน โดยเฉพาะ การขนส่งวัสดุอุปกรณ์จัดให้อยู่ในช่วงกลางวันนอกเวลาเร่งด่วน • หมั่นตรวจสอบประสิทธิภาพของเครื่องจักรและยานพาหนะให้ดี อยู่เสมอ • จัดให้มีที่ครอบหรือที่อุดหูแก่เจ้าหน้าที่และคนงานที่อยู่ใน บริเวณที่เกิดเสียงดัง • พื้นที่ที่มีการตัดแปลงอาคารและพื้นที่อยู่ติดลงมา 1 ชั้น จะไม่ อนุญาตให้มีการเข้าพัก เพื่อป้องกันเสียงจากการตัดแปลงอาคาร	

องค์ประกอบทางสิ่งแวดล้อม และคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบ สิ่งแวดล้อม
		กำหนดแผนงาน/วิธีการก่อสร้างที่เหมาะสม เครื่องจักรที่มีเสียง ดังควรมีการบำรุงรักษาสม่ำเสมอและไม่ควรทำงานที่มีเสียงดังใน ช่วงกลางคืน	
2. แหล่งน้ำและคุณภาพน้ำผิวดิน	บริเวณโครงการไม่มีแหล่งน้ำผิวดินที่มีความสำคัญทาง ระบบนิเวศวิทยาแต่อย่างใด และน้ำเสียที่เกิดขึ้นจากกิจ กรรมการตัดแปลงอาคารมีประมาณ 1.1 ลบ.ม./วัน จะถูกรวบรวมเข้าระบบบำบัดน้ำเสียระบบตะกอนแ่ง ของอาคาร A โดยมีค่า BOD หลังบำบัดไม่เกินค่ามาตรฐาน ที่กำหนด (20 มก./ลบ.ม.) ก่อนระบายลงท่อ สาธารณะของ กทม. ดังนั้นผลกระทบจึงไม่มีต่อแหล่ง น้ำผิวดินแต่อย่างใด	- จัดให้มีการเก็บเศษวัสดุอุปกรณ์ ทำความสะอาดพื้นที่ตัดแปลง อาคารในเวลาหลังจากเลิกงานทุกวัน - ใช้ระบบบำบัดน้ำเสียชนิดตะกอนแ่งของโครงการ เพื่อลดการ การรองรับค่าความสกปรกของแหล่งน้ำผิวดิน รวมทั้งตรวจสอบ ระบบฯ ให้สามารถทำงานได้มีประสิทธิภาพอย่างสม่ำเสมอ	
3. การจราจร	การขนส่งวัสดุอุปกรณ์ จะใช้เส้นทางถนนวิภาวดีเอกเข้า สู่ซอยสุขุมวิท 16 เพื่อเดินทางมายังพื้นที่โครงการ ปริมาณการขนส่งที่เพิ่มขึ้นสูงสุดเท่ากับ 6 PCU/วัน จะ ทำให้ความสามารถในการรองรับปริมาณการจราจรของ เส้นทางคมนาคมบริเวณโครงการมีค่าเปลี่ยนแปลงไป จากปัจจุบันเล็กน้อย ผลกระทบที่คาดว่าจะเกิดขึ้น ได้แก่ การรบกวนของเศษวัสดุก่อสร้าง การจราจรติด ขัด อุบัติเหตุจากการขนส่ง และผิวจราจรเสียหาย เป็นต้น	- หลีกเลี่ยงการขนส่งวัสดุอุปกรณ์ในช่วงชั่วโมงเร่งด่วนทั้ง เช้า-เย็น ทำการขนส่งในช่วงสภาพการจราจรเบาบางหรือนอกช่วงเวลาเร่ง ด่วน - ควบคุมน้ำหนักบรรทุกทุกตามขีดของรัฐบาล เพื่อป้องกันการ ชำรุดของถนน - ระมัดระวังไม่ให้เกิดการรบกวนของวัสดุอุปกรณ์ เช่น ใช้อุปกรณ์ ไม่มีดัด เพื่อป้องกันการเกิดอุบัติเหตุจากจราจร - จัดเจ้าหน้าที่อำนวยความสะดวกบริเวณทางเข้า-ออกโครงการ เพื่อป้องกันไม่ให้เกิดการจราจรติดขัด รวมทั้งการจราจรบน การจราจรของรถบรรทุกวัสดุอุปกรณ์ภายในพื้นที่โครงการให้สอดคล้อง กับสภาพการจราจรภายนอกโครงการ	

องค์ประกอบทางสิ่งแวดล้อมและคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
4. การจัดการมูลฝอย	มูลฝอยคนงานคัดแปลงอาคารประมาณ 0.06 ลบ.ม./วัน จะรวบรวมใส่ภาชนะรองรับมูลฝอยเพื่อรอการเก็บขนจากรถเก็บขนมูลฝอยของสำนักงานเขตคลองเตย ซึ่งจะเข้ามาเก็บขนทุกวัน สำหรับเศษวัสดุอุปกรณ์ที่ไม่ใช่แล้ว จะรวมอยู่ในมูลฝอยที่จะต้องกำจัดด้วย ซึ่งมีปริมาณไม่มาก และสามารถนำไปถมที่ได้ ดังนั้นผลกระทบในด้านการจัดการมูลฝอยจึงอยู่ในระดับต่ำ	- จัดหาภาชนะรองรับมูลฝอยอย่างถูกสุขลักษณะ ขนาด 200 ลิตร จำนวน 2 ถึง 10 เพื่อรองรับต่อปริมาณมูลฝอยที่เกิดขึ้นทั้งบริเวณพื้นที่โครงการ - เศษวัสดุเหลือใช้จากการตัดแปลงอาคาร ผู้รับเหมาจะจัดหารอบรรทุกมาขนไปจัดการวันละ 1 เที่ยว เก็บขนมูลฝอยออกจากพื้นที่อย่าให้มีขยะตกค้าง - จัดบริเวณที่จะรวบรวมเศษวัสดุอุปกรณ์ก่อสร้าง/ตัดแปลงอาคาร และทำรั้วกั้นล้อมพื้นที่รวบรวมเศษวัสดุ เพื่อป้องกันการปนเปื้อนต่อพื้นที่ภายนอกและเพื่อความเป็นระเบียบเรียบร้อย โดยจะต้องมีผ้าคลุมอย่างมิดชิด - ส่งเสริมให้มีการแยกประเภทมูลฝอยก่อนทิ้งลงสู่ภาชนะรองรับ เพื่อลดปริมาณมูลฝอย นำบางส่วนกลับมาใช้ประโยชน์ได้ - เศษวัสดุอุปกรณ์ที่จะนำไปกำจัดนอกพื้นที่โครงการจะต้องมีผ้าใบหรือเครื่องป้องกันการร่วงหล่นหรือฟุ้งกระจายลงบนถนน และบริเวณที่จะนำไปทิ้ง ที่จะต้องได้รับอนุญาตจากเจ้าพนักงาน	
5. การบำบัดน้ำเสีย	น้ำเสียจากคนงานมีปริมาณประมาณ 1.1 ลบ.ม./วัน โดยจะผ่านระบบบำบัดน้ำเสียระบบตะกอนเร่งของอาคาร A และน้ำทิ้งที่จะระบายลงสู่ท่อสาธารณะมีค่า BOD อยู่ในเกณฑ์มาตรฐานที่กำหนด ดังนั้นจึงไม่ได้เพิ่มค่าความสกปรกให้แก่แหล่งรองรับน้ำทิ้งใกล้เคียงแต่อย่างใด ผลกระทบจึงอยู่ในระดับต่ำ	- ใช้บำบัดน้ำเสียชนิดตะกอนเร่งของอาคาร A เพื่อบำบัดน้ำเสียให้มีค่า BOD ต่ำกว่า 20 มก./ลิตร และอยู่ในมาตรฐานที่กำหนด - หมั่นตรวจสอบดูแลการทำงานของระบบบำบัดน้ำเสียให้มีประสิทธิภาพดีอยู่เสมอ	ตรวจสอบคุณภาพน้ำทิ้งจากระบบบำบัดน้ำเสียอาคาร A เป็นประจำทุกเดือน (ปัจจุบันโครงการมีการตรวจสอบเป็นประจำทุกเดือน)

องค์ประกอบทางสิ่งแวดล้อมและคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
6. การระบายน้ำและป้องกันน้ำท่วม	ผลกระทบต่อการระบายน้ำส่วนใหญ่มีสาเหตุมาจากการวางท่อของเศษวัสดุก่อสร้าง เข้าไปอุดตันที่ระบายน้ำ และเกิดน้ำท่วมขังได้	- จัดให้มีพื้นที่กองเศษวัสดุอุปกรณ์อย่างเป็นระเบียบ มีผ้าใบปกคลุมอย่างมิดชิด และอยู่ห่างจากวางระบายน้ำของโครงการ - ติดตั้งตะแกรงดักเศษขยะที่ปลายท่อระบายน้ำของโครงการ ก่อนเชื่อมสู่ท่อสาธารณะ	
7. อากาศอันธพาล ความปลอดภัย และการป้องกันอัคคีภัย	ผลกระทบจากกิจกรรมการก่อสร้างตัดแปลงส่วนใหญ่ เกิดจากความประมาท และการจัดการสาธารณูปโภคที่ไม่ดีพอ รวมถึงความไม่พร้อมของเครื่องจักร/อุปกรณ์ที่ใช้ในงาน ที่จะทำให้เกิดการวางท่อของเศษวัสดุก่อสร้างจากตัวอาคาร อัคคีภัยจากถังเก็บเชื้อเพลิง อุปกรณ์เหตุจากการทำงานของคนงาน และจากการชนสิ่งวัสดุอุปกรณ์ การแพร่กระจายของเชื้อโรค ฯลฯ ซึ่งจะมีผลกระทบต่อสุขภาพอนามัย และเกิดเสียต่อทรัพย์สินและความปลอดภัยของบุคคล	- ปฏิบัติตามข้อกำหนด/กฎหมายที่เกี่ยวข้องกับงานก่อสร้าง/ตัดแปลงอาคารอย่างเคร่งครัด โดยเฉพาะข้อบัญญัติกรุงเทพมหานคร (2522) เรื่องการควบคุมการก่อสร้าง/ตัดแปลงอาคาร ประกาศกรม. (2534) กฎกระทรวงฉบับที่ 4 (2526) และประกาศกระทรวงมหาดไทย เรื่องความปลอดภัยในการก่อสร้าง - จัดหาอุปกรณ์ป้องกันอันตรายส่วนบุคคลให้คนงานสวมใส่อย่างพอเพียง เช่น หมวกกันน็อก แว่นตา หมวกกันน็อก ไม้เท้าพาดและเหมาะสมต่อจำนวนคนงานและลักษณะงาน - จัดเตรียมและตรวจสอบอุปกรณ์ป้องกันอัคคีภัยและอุปกรณ์เหตุไฟไหม้เพียงพอ และพร้อมใช้งานอยู่เสมอ เช่น ถังดับเพลิงมือถือ น้ำดับเพลิง เป็นต้น - จัดเก็บสารเคมีที่ติดไฟง่าย และเชื้อเพลิงที่ใช้ในการก่อสร้าง/ตัดแปลง ให้เป็นระเบียบและให้อยู่ห่างกัน - ติดตั้งป้ายคำเตือนให้ระมัดระวังหรือห้ามเข้าในส่วนพื้นที่อาคารที่ปรับปรุง - จัดเตรียมระบบสาธารณูปโภคสำหรับคนงานให้เพียงพอ - จัดเตรียมอุปกรณ์ปฐมพยาบาลเบื้องต้นไว้บริเวณตัดแปลงพื้นที่อาคาร และมีเบอร์ติดต่อประสานงานกับสถานบริการด้านสาธารณสุขที่รัฐและเอกชนได้อย่างทั่วถึง - ในกรณีที่เกิดเหตุเพลิงไหม้ฉุกเฉินจนเกินขีดความสามารถของอุปกรณ์ดับเพลิงที่มี ให้ติดต่อขอรับการสนับสนุนจากหน่วยงานดับเพลิงที่ใกล้ที่สุด - ติดตั้งสัญญาณไฟ หรือป้ายเตือนให้ผู้สัญจรไปมาไม่มีความระมัดระวัง เพื่อไม่ให้เกิดอุบัติเหตุจากการชนสิ่งวัสดุอุปกรณ์	

องค์ประกอบทางสิ่งแวดล้อม และคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบ สิ่งแวดล้อม
8. สภาพทางเศรษฐกิจ-สังคม	ผลกระทบด้านบวกที่สำคัญคือ การเพิ่มอัตราการจ้างงาน สำหรับผลกระทบด้านลบส่วนใหญ่เป็นปัญหาด้านสังคมและสิ่งแวดล้อม ได้แก่ การรบกวนความสงบสุขของชุมชน เสียงดัง การจราจรติดขัด และ มลพิษทางอากาศ เป็นต้น	- ปฏิบัติตามมาตรการลดผลกระทบด้านเสียง มั่นละออง และการขนส่งวัสดุอย่างเคร่งครัด - ประชาสัมพันธ์แผนการตัดแปลงอาคารของโครงการให้ประชาชนในบริเวณใกล้เคียงทราบ - เฝ้าระวังและดูแลความปลอดภัยของพนักงานมิให้เกิดความเดือดร้อนและปัญหาต่างๆ แก่คนงานด้วยกับและประชาชนในพื้นที่ข้างเคียง	
9. การสาธารณสุข	การตัดแปลงอาคารอาจก่อให้เกิดผลกระทบต่อสุขภาพการสาธารณสุขดังนี้ - ความเสี่ยงจากอุบัติเหตุ จากงานตัดแปลงอาคาร - การแพร่กระจายของโรคติดต่อจากคนงาน อย่างไรก็ตามบริเวณโครงการมีสถานบริการสาธารณสุขทั้งของรัฐและเอกชนหลายแห่งที่สามารถรองรับได้อย่างเพียงพอ จึงคาดว่าจะไม่เกิดผลกระทบแต่อย่างใด	- จัดเตรียมอุปกรณ์ป้องกันอันตรายส่วนบุคคล เช่น หมวก/แว่นตา/นิรภัย ปลั๊กอุดหู ฯลฯ ให้เพียงพอและเหมาะสมต่อจำนวนคนงานและลักษณะงาน - ติดตั้งป้ายเตือนอันตราย สำหรับบุคคลภายนอกให้รับทราบพร้อมทั้งล้อมรั้วบริเวณก่อสร้างอย่างมิดชิด - ปฏิบัติตามมาตรการลดและป้องกันผลกระทบคุณภาพสิ่งแวดล้อมอย่างเคร่งครัด - จัดเตรียมระบบสุขาภิบาลและอนามัยสิ่งแวดล้อมให้เพียงพอและอยู่ในสภาพพร้อมใช้งาน - จัดเตรียมอุปกรณ์ปฐมพยาบาลเบื้องต้นไว้ในพื้นที่โครงการและประสานงานกับสถานบริการสาธารณสุขใกล้เคียงทั้งรัฐและเอกชนเพื่อแก้ปัญหาได้ทันที	

องค์ประกอบทางสิ่งแวดล้อม และคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบ สิ่งแวดล้อม
10. ทัศนียภาพ	ระยะตัดแปลงอาคารอาจจะมีทัศนียภาพที่ไม่น่าดูต่อผู้ใช้บริการ หรือผู้เข้าพัก กรณีไม่มีการปิดกั้น/แยกพื้นที่ตัดแปลงออกจากพื้นที่ใช้งานของโรงแรม การก่อสร้างวัสดุอุปกรณ์ที่ไม่เป็นระเบียบ หรือการวิ่งเข้า-ออก ของรถบรรทุก เป็นต้น ทั้งนี้เพื่อป้องกันไม่ให้เกิดทัศนียภาพที่ไม่น่าดูในช่วงระยะเวลาดังกล่าว ทางผู้รับเหมาจะต้องปฏิบัติตามมาตรการที่กำหนดไว้อย่างเคร่งครัด	- ปฏิบัติตามประกาศกรุงเทพมหานคร (2534) และกฎกระทรวงฉบับที่4(2526)อย่างเคร่งครัด - ดำเนินการภายในอาคารเท่านั้น ซึ่งเป็นการปิดกั้นล้อมรอบบริเวณที่จะทำการก่อสร้าง/ตัดแปลงอาคาร - จัดให้มีผ้าใบปิดคลุมกระเบื้องหลังคาให้เป็นระเบียบ - จัดระเบียบเศษวัสดุอุปกรณ์ให้เป็นระเบียบ และหมั่นทำความสะอาดหลังเลิกงานในแต่ละวัน - ประชาสัมพันธ์กับประชาชนในพื้นที่ข้างเคียงก่อนเริ่มงาน	

ข. ระยะดำเนินการ

องค์ประกอบทางสิ่งแวดล้อมและคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
1. คุณภาพอากาศและระดับเสียง	ยานพาหนะที่ใช้บริการโครงการ จะทำให้เกิดการระบายมลสารต่าง ๆ ได้แก่ CO เท่ากับ 0.043 ppm, NO ₂ เท่ากับ 0.002 มก./ลบ.ม. และ HC เท่ากับ 0.007 ppm ซึ่งทั้งหมดมีค่าอยู่ในมาตรฐานคุณภาพอากาศในบรรยากาศ จึงไม่ก่อให้เกิดผลกระทบต่อคุณภาพอากาศแต่อย่างใด ส่วนผลกระทบด้านเสียงที่อาจเกิดขึ้น ได้แก่ เสียงรบกวนที่เกิดจากการจราจรภายในพื้นที่โครงการ ซึ่งเป็นผลกระทบในระดับต่ำ	- จัดระบบการเดินรถและเส้นทางเข้า-ออกโครงการ ให้เหมาะสมกับสภาพการจราจรภายนอกเพื่อลดปัญหาการจราจรติดขัด โดยมีเจ้าหน้าที่คอยอำนวยความสะดวก - ปฏิบัติตามกฎหมายที่ห้ามติดเครื่องแตรในส่วนของที่จอดรถอย่างเคร่งครัด - โครงการได้ออกแบบที่จอดรถของอาคารให้มีอัตราการระบายอากาศประมาณ 4 เท่า ของปริมาตรห้องใน 1 ชม. ซึ่งมากกว่าข้อกำหนดตามกฎหมายฉบับที่ 50 (พ.ศ.2540) ออกตามความในพระราชบัญญัติควบคุมอาคาร พ.ศ.2522 ที่กำหนดให้มีอัตราการระบายอากาศเท่ากับ 4 เท่าของปริมาตรห้องใน 1 ชม. - ติดตั้งป้ายห้ามบีบแตรหรือเหยียบคันเร่งให้มีเสียงดังรวมทั้งติดตั้งป้ายจำกัดความเร็วที่วิ่งภายในพื้นที่โครงการไม่เกิน 30 กม./ชม. - ปลูกต้นไม้รอบพื้นที่โครงการเพื่อลดระดับอุณหภูมิและดูดซับมลพิษ	
2. แหล่งน้ำและคุณภาพน้ำผิวดิน	การดำเนินการขอโครงการไม่ก่อให้เกิดผลกระทบต่อแหล่งน้ำและคุณภาพน้ำผิวดินโดยตรง เนื่องจากน้ำเสียจะผ่านระบบบำบัดน้ำเสียก่อนที่จะระบายลงสู่ท่อสาธารณะ แต่ดำเนินการไม่ดูแลระบบบำบัดน้ำเสียให้มีประสิทธิภาพการบำบัดที่ดีอยู่เสมอ จะส่งผลต่อคุณภาพน้ำในแหล่งรองรับน้ำทิ้งได้	- ระบบบำบัดน้ำเสียของอาคาร A และอาคาร B บริเวณชั้นใต้ดินเป็นชนิดตะกอนเร่ง (Activated Sludge) สามารถรองรับปริมาณน้ำเสียได้สูงสุด 230 และ 150 ลบ.ม./วัน ตามลำดับ - ควบคุมดูแลประสิทธิภาพของระบบบำบัดน้ำเสียของโครงการ ให้ทำงานได้ตามมาตรฐานน้ำทิ้งจากอาคารประเภท ก. ก่อนระบายออกนอกโครงการ - ก่อนที่จะระบายน้ำออกสู่บ่อบำบัดสาธารณะจะต้องติดตั้งตะแกรงดักขยะและตรวจสอบเป็นประจำ เพื่อกำจัดขยะที่ตกค้าง	

องค์ประกอบทางสิ่งแวดล้อมและคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
3. การจราจร	เมื่อโครงการเปิดดำเนินการจะทำให้ปริมาณยานพาหนะในโครงข่ายระบบจราจรบริเวณพื้นที่โครงการ และพื้นที่ข้างเคียงเพิ่มขึ้นจากเดิมเท่ากับ 329 PCU/ชม. โดยเฉพาะในช่วงชั่วโมงเร่งด่วนเช้า หรืออีกนัยหนึ่งกล่าวคือ ปริมาณการจราจรจากโครงการจะทำให้ความจุของถนนสายต่าง ๆ เปลี่ยนไปจากเดิมก่อนดำเนินโครงการ แต่ในปัจจุบันพบว่าสภาพการจราจรของถนนในซอยสุขุมวิท 16 ถนนในซอยสุขุมวิท 22 และถนนรัชดาภิเษก พอใช้ได้มีติดขัดเป็นบางช่วงซึ่งเป็นผลมาจากสภาพการจราจรโดยรวมโครงการเป็นส่วนใหญ่จากการประเมินพบว่าโครงข่ายถนนบริเวณรอบโครงการมีศักยภาพเพียงพอในการรองรับปริมาณจราจรที่คาดว่าจะเกิดจากโครงการได้ในระดับที่น่าพอใจ แต่อย่างไรก็ตามผู้ประกอบการควรปฏิบัติตามมาตรการที่กำหนดเพื่อช่วยลดปัญหาด้านการจราจรที่จะเกิดขึ้น	- ประชาสัมพันธ์ให้ผู้ใช้บริการ และพนักงานของโครงการใช้ระบบขนส่งมวลชนให้มากขึ้น เพื่อที่จะลดปริมาณการใช้รถยนต์ส่วนบุคคล - โครงการต้องจัดให้มีพื้นที่จอดรถอย่างน้อย 323 คัน โดยคิดจากพื้นที่ที่มีพื้นที่ใช้สอยที่ต่อเนื่องกันมาคิดที่จอดรถทั้งหมด 40,980 ตร.ม. อย่างไรก็ตาม โครงการได้จัดให้มีพื้นที่จอดรถ จำนวน 329 คัน ซึ่งมากกว่าที่กฎหมายกำหนดไว้ - จัดให้มีเจ้าหน้าที่ประจำพื้นที่จอดรถของโครงการ และทางเข้า-ออก เพื่อควบคุมและอำนวยความสะดวกในการเข้าจอดรถ และป้องกันรถติดภายนอกและภายในโครงการ - จัดให้มีป้ายบอกสำหรับรับจ่ายบัตรบริเวณทางเข้า-ออก จะต้องไว้ให้ลึกเข้าไปจากปากทางเข้า-ออกอย่างน้อย 30 เมตรเพื่อป้องกันปัญหาการกีดขวางการจราจร - จัดเตรียมแผนควบคุมการจราจรในกรณีฉุกเฉิน เช่น อัคคีภัย ฯลฯ - จำกัดความเร็วของพาหนะทุกคันในโครงการไม่เกิน 30 กม./ชม. เพื่อป้องกันอุบัติเหตุ - จัดระบบการเดินรถของโครงการให้เหมาะสมกับสภาพการจราจรภายนอกเพื่อลดปัญหาการจราจรติดขัด - ประสานงานกับตำรวจจราจรในพื้นที่รับผิดชอบ เมื่อทางโรงแรมมีการจัดงานเลี้ยงหรือกิจกรรมที่ทำให้ผู้ใช้บริการใช้รถยนต์ส่วนบุคคล เดินทางมายังพื้นที่โครงการ เพื่ออำนวยความสะดวกและจัดระบบการจราจรให้สอดคล้องกันในแต่ละโครงการขั้วคมนาคมที่เกี่ยวข้อง เพื่อป้องกันปัญหาการจราจรติดขัด - ในช่วงชั่วโมงเร่งด่วนเช้า (06.00-09.00 น.) และช่วงเย็น (16.00-19.00 น.) ห้ามให้รถที่ออกจากทางออกของโครงการเลี้ยวขวาตัดและแทรกจราจรในซอยสุขุมวิท 16 โดยให้รถทุกคันต้องเลี้ยวซ้ายเข้าซอยสุขุมวิท 16 เพื่อไปใช้เส้นทางตัดออกสู่ซอยอื่นๆ โดยโครงการได้มีการประชาสัมพันธ์ให้ผู้พักอาศัยทราบ และติดตั้งป้ายห้ามเลี้ยวขวาและช่วงเวลาไว้บริเวณทางออกของโครงการ	

องค์ประกอบทางสิ่งแวดล้อม และคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบ สิ่งแวดล้อม
3. การจราจร (ต่อ)		จัดให้มีรถบัส หรือรถตู้ บริการรับส่งผู้ที่จะเข้ามาใช้บริการห้องจัดเลี้ยงตลอดจนกิจกรรมอื่นๆ ในโครงการ โดยโรงแรมประสานงานกับเจ้าของงานเสี่ยงในการประชาสัมพันธ์ให้แขกที่จะมาร่วมงานรับทราบ ถึงจุดจอดรถ เวลานัดหมาย ฯลฯ ทั้งนี้ เพื่อลดการใช้ยานพาหนะลงในช่วงเวลาดังกล่าว ซึ่งอาจรวมถึงการใช้ยานพาหนะร่วมกันโรงแรมใกล้เคียงในกรณีที่มีงานเลี้ยงในเวลาเดียวกัน	
4. การใช้น้ำ	ภายหลังพัฒนาโครงการและเปิดให้บริการแล้วประมาณ การใช้น้ำที่โครงการประมาณ 451 ลบ.ม./วัน น้ำ ใต้ได้จากการประปานครหลวง (กปน.) ซึ่งมีความ สามารถในการให้บริการโครงการได้อย่างเพียงพอ อย่างไรก็ดี โครงการจัดให้มีมาตรการประหยัดการใช้น้ำ	- ส่งเสริมและประชาสัมพันธ์การประหยัดน้ำให้กับผู้เข้าพัก และ พนักงาน รับทราบและปฏิบัติตาม โดยการจัดบอร์ดประชาสัมพันธ์ การติดตั้งป้ายเตือนให้ประหยัดน้ำภายในห้องน้ำทั้งในส่วนของโรงแรม พัก สำนักงาน และพื้นที่สาธารณะอื่นๆ เป็นต้น - ตรวจสอบรอยรั่วของท่อจ่ายน้ำ บริเวณรอยต่อและปั๊มน้ำ เพื่อลด การสูญเสียอย่างเปล่าประโยชน์ - การรดต้นไม้ อาจจะเลือกใช้ระบบสปริงเคลส แทนการรดน้ำด้วย สายยาง ซึ่งจะประหยัดน้ำได้มากกว่า	

10
10
10

องค์ประกอบทางสิ่งแวดล้อม และคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบ สิ่งแวดล้อม
5. การใช้ไฟฟ้า	อาคาร A และอาคาร B มีความต้องการกระแสไฟฟ้า หลังพัฒนาโครงการประมาณ 2,573 และ 1,844 kVA ตามลำดับ และมีเครื่องกำเนิดไฟฟ้าสำรองขนาด 200 และ 300 kVA ตามลำดับ ซึ่งได้รับบริการจากการไฟฟ้า นครหลวงเขตคลองเตย อย่างไรก็ดี โครงการจะต้อง มีการจัดการประหยัดพลังงานไฟฟ้าที่เหมาะสมเพื่อลด ผลกระทบด้านการใช้พลังงานไฟฟ้า	- ส่งเสริมและประชาสัมพันธ์การอนุรักษ์พลังงานภายในอาคารให้กับ พนักงานประจำอาคาร ผู้พักอาศัย และผู้ให้บริการจากภายนอก โดย การจัดบอร์ดประชาสัมพันธ์ และติดตั้งป้ายเตือนการเปิด-ปิดไฟ การสิ้นเปลืองไฟฟ้า การเปิด-ปิดแอร์ภายในห้องพักเมื่อไม่ได้ใช้งาน เป็นต้น - ติดป้ายแนะนำวิธีการใช้ระบบปรับอากาศภายในห้องพัก เช่น การ เปิดแอร์ การตั้งอุณหภูมิที่เหมาะสม การปิดแอร์ทุกครั้งเมื่อออกจาก ห้องหรือไม่อยู่ในห้อง - หมั่นทำความสะอาดแผ่นกรองอากาศและชุดทำความเย็นเมื่อพบว่สกปรก เนื่องจากคราบความสกปรกจะทำให้พื้นผิวมีความร้อนถ่ายเทความร้อนได้ไม่ดี ทำให้น้ำเย็นที่กลับไปยังเครื่องทำน้ำเย็นมี อุณหภูมิต่ำลง ซึ่งมีผลทำให้ประสิทธิภาพของเครื่องทำน้ำเย็นต่ำลง - ทดสอบและปรับแต่งระบบปรับอากาศให้สมบูรณ์อยู่เสมอตามหมาย กำหนดการที่จัดไว้ตลอดอายุการใช้งานของระบบเช่น 1-2 ครั้งต่อปี - ตั้งเทอร์โมสแตทให้ควบคุมอุณหภูมิที่พอเหมาะกับความสบาย (25.5-26.7 °C) ไม่ควรตั้งเทอร์โมสแตทไว้ที่ต่ำสุด และหมั่นตรวจสอบ การทำงานของเทอร์โมสแตทว่าปกติหรือไม่ - ทำความสะอาดคอนเดนเซอร์เป็นประจำตรวจสอบและอุดรอยรั่ว ตามผนัง มีเพดาน ประตู หน้าต่าง หรืออื่นๆ เพื่อป้องกันการรั่วไหลของความเย็นภายในห้องพักหรือพื้นที่ที่ใช้ระบบปรับอากาศออกสู่ภายนอก - หลีกเลี่ยงการเก็บเอกสารหรือวัสดุอื่นใดที่ไม่จำเป็นต้องใช้งานใน พื้นที่ที่ใช้ระบบปรับอากาศเพื่อลดการสูญเสียและใช้พลังงานในการปรับอากาศภายในอาคาร - หมั่นทำความสะอาดหลอดไฟ เพราะจะช่วยเพิ่มแสงสว่าง โดยไม่ ต้องใช้พลังงานมากขึ้นและตรวจสอบสภาพของอุปกรณ์ต่าง ๆ เช่น หลอดไฟและสวิตช์ไฟ เมื่อพบอุปกรณ์ชำรุดให้ทำการซ่อมแซมในทันที	

11
11
11

องค์ประกอบทางสิ่งแวดล้อมและคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
6. การใช้ไฟฟ้า (ต่อ)		- หมั่นดูแลและบำรุงรักษาอุปกรณ์ของระบบปรับอากาศและไฟฟ้าให้อยู่เสมอ - ปิดสวิตช์ไฟและเครื่องใช้ไฟฟ้าทุกชนิดเมื่อเลิกใช้งาน - พื้นที่ปรับอากาศบางแห่ง เช่น ส่วนภัตตาคาร และนันทนาการ ซึ่งจะมีผู้ใช้บริการมากในบางช่วงเวลา ซึ่งต้องเปิดให้อากาศบริสุทธิ์เข้ามาได้เต็มที่ แต่ในช่วงเวลาอื่นจะสามารถลดอากาศบริสุทธิ์เข้ามาน้อยลง ซึ่งสามารถประหยัดพลังงานได้	
7. การจัดการมูลฝอย	เมื่อโครงการเปิดดำเนินการจะมีปริมาณมูลฝอยจากกิจกรรมต่างๆ ประมาณ 5 ลบ.ม./วัน เพิ่มขึ้นจากปัจจุบันประมาณ 1 ลบ.ม./วัน ทำให้ภาระในการเก็บขนของสำนักงานเขตคลองเตยเพิ่มขึ้นเล็กน้อย เมื่อพิจารณาถึงความสามารถในการเก็บขน และกำจัดขยะพบว่าทางสำนักงานเขตคลองเตยยังมีประสิทธิภาพเพียงพอต่อการให้บริการ ดังนั้นจึงไม่มีผลกระทบแต่อย่างใด แต่ดำเนินการฯ ไม่มีการจัดการมูลฝอยที่เหมาะสมจะมีผลทำให้เกิดการตกค้างและปนเปื้อนลงสู่พื้นที่โดยรอบได้	- ห้องพักมูลฝอยที่ทางโครงการจัดเตรียมไว้บริเวณชั้น 1 ของอาคาร A มีขนาดกว้าง x ยาว x สูง เท่ากับ 2.8 x 8.0 x 3.2 ม. คิดเป็นปริมาตร 45 ลบ.ม. ซึ่งสามารถเก็บมูลฝอยที่เกิดขึ้นได้ประมาณ 9 วัน ในกรณีที่ไม่มีการนำขยะมูลฝอยไปทิ้ง - จัดเตรียมถังรองรับมูลฝอยตั้งไวตามพื้นที่สาธารณะและภายในห้องพักให้เพียงพอ และเป็นถังรองรับแบบแยกประเภทมูลฝอยที่มีฝาปิด ถังรองรับอย่างมีขีด - ส่งเสริมและประชาสัมพันธ์ในการแยกประเภทของมูลฝอย เพื่อช่วยลดขั้นตอน ประสิทธิภาพในการทำงาน ทำลายขยะ และช่วยลดการกำจัด นอกจากนี้ควรส่งเสริมให้แยกส่วนที่สามารถนำกลับมาใช้ประโยชน์ได้อีกออกมา เพื่อลดปริมาณมูลฝอยให้น้อยลง - ควบคุมดูแลการเก็บขนมูลฝอยในส่วนต่าง ๆ ของอาคารไปยังห้องพักมูลฝอยอย่างใกล้ชิด เพื่อป้องกันการปนเปื้อนต่อพื้นที่สาธารณะ หรือหลีกเลี่ยงไปใช้เส้นทางอื่น - ควรทำความสะอาดห้องพักมูลฝอยอย่างน้อย 1 ครั้งต่อสัปดาห์ และนำสิ่งไว้ระบายน้ำเข้าสู่ระบบบำบัดน้ำเสียของโครงการ - ไม่ควรให้มีขยะตกค้างอยู่ภายในห้องพักขยะมูลฝอย เพื่อป้องกันการแพร่กระจายของเชื้อโรค และกลิ่นไม่พึงประสงค์	

หน้า ๒
ลงชื่อ.....ผู้รับรอง

องค์ประกอบทางสิ่งแวดล้อมและคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
8. การบำบัดน้ำเสีย	กิจกรรมต่างๆ ภายในโครงการ จะก่อให้เกิดน้ำเสียเท่ากับ 361 ลบ.ม./วัน (มาจากอาคาร A และอาคาร B ประมาณ 214 และ 147 ลบ.ม./วัน ตามลำดับ) จะถูกบำบัดด้วยระบบบำบัดน้ำเสียชนิดตะกอนเร่ง (Activated Sludge) ของอาคาร A และอาคาร B จนค่า BOD ไม่เกิน 20 มก./ลบ.ม. ซึ่งไม่เกินมาตรฐานน้ำทิ้งจากอาคารประเภท ก. ดังนั้นจึงไม่เป็นการเพิ่มภาระให้กับโรงบำบัดน้ำเสียพระโขนง-คลองเตยแต่อย่างใด คาดว่าผลกระทบจะอยู่ในระดับต่ำ นอกจากนี้โครงการได้จัดเตรียมมาตรการในการดูแล บำรุงรักษาระบบให้มีประสิทธิภาพดีอยู่เสมอ และหมั่นตรวจสอบคุณภาพน้ำก่อนที่จะระบายลงสู่ท่อระบายน้ำสาธารณะตามระยะเวลาที่กำหนดในมาตรการติดตามตรวจสอบระบบบำบัดน้ำเสียของโครงการ ซึ่งคาดว่าจะไม่มีผลกระทบใดๆ ที่จะเกิดขึ้นจากการดำเนินการโครงการ	- จัดให้มีการบำบัดน้ำเสียที่เกิดขึ้นจากโครงการ ด้วยระบบบำบัดน้ำเสียชนิดตะกอนเร่ง (Activated Sludge) ของอาคาร A และอาคาร B ในบริเวณใต้อาคาร A และอาคาร B บริเวณทางขึ้นลงที่จอดรถด้านหลังโครงการ ตามรูปที่ 1 สามารถรองรับปริมาณน้ำเสียได้สูง 230 และ 150 ลบ.ม./วัน ตามลำดับ ปริมาณความสกปรกในรูป BOD เท่ากับ 250 มก./ล. ซึ่งมีประสิทธิภาพในการบำบัดไม่น้อยกว่า 90 % ทำให้ BOD ที่ออกจากระบบ มีค่าไม่เกิน 20 มก./ล. - ส่งเสริมและประชาสัมพันธ์การประหยัดน้ำ ทั้งผู้ให้บริการ และพนักงาน อย่างไรก็ดี โครงการไม่สามารถนำน้ำทิ้งกลับมาใช้ประโยชน์ได้ เนื่องจากข้อจำกัดในด้านพื้นที่กักเก็บน้ำที่ผ่านการบำบัดแล้วเพื่อนำมาใช้รดน้ำต้นไม้เพียงพอ - ตรวจสอบ บำรุงรักษาระบบบำบัดน้ำเสียให้มีประสิทธิภาพดีอยู่เสมอ - หมั่นสูบลบตะกอนออกจากระบบบำบัดน้ำเสียทุกเดือน หรือตามความเหมาะสม - ถังดักไขมัน จะได้รับการตรวจสอบ ดูแล บำรุงรักษาให้มีประสิทธิภาพดีอยู่เสมอ โดยเฉพาะระบบระบายอากาศ และตามรอบวิธีชี้แจงต่าง ๆ เพื่อป้องกันกลิ่นรบกวน - หมั่นตรวจสอบ บำรุงรักษา เครื่องดูดตะกอนไขมัน ให้มีประสิทธิภาพในการกำจัดตะกอนไขมันดีอยู่เสมอ	มาตรการติดตามตรวจสอบประสิทธิภาพของระบบบำบัดน้ำเสียในระบดำเนินการ - ดัชนีที่ตรวจวัด (pH , BOD , SS , Oil & Grease , TKN , อัตราการไหลของน้ำเสีย) - สถานีตรวจวัด จำนวน 5 จุด (รูปที่ 1) - บ่อกรอง (Septic tank) ของระบบบำบัด อาคาร A และอาคาร B จำนวน 2 จุด - บ่อระบายน้ำที่สุดท้ายก่อนระบายสู่ท่อของโครงการ (Effluent tank) ของระบบบำบัด อาคาร A และอาคาร B จำนวน 2 จุด - บ่อพักน้ำสุดท้ายของโครงการ บริเวณด้านหลังโครงการ ก่อนระบายลงสู่ท่อของ กทม. จำนวน 1 จุด - ช่วงเวลาตรวจวัด/ความถี่ - เก็บตัวอย่างทุกเดือนตลอดระยะดำเนินการ - ตรวจสอบปริมาณไขมัน/น้ำมัน ที่บ่อดักไขมันทุกเดือนถ้ามีปริมาณมากให้ตักออก - ตรวจเช็คถังเก็บตะกอนทุก 30 วัน ถ้าตะกอนใกล้เต็มควรรีบสูบลบ - ผู้รับผิดชอบ เจ้าของ/ผู้บริหารโครงการ

หน้า ๓
ลงชื่อ.....ผู้รับรอง

องค์ประกอบทางสิ่งแวดล้อม และคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบ สิ่งแวดล้อม
9. การระบายน้ำและป้องกันน้ำ ท่วม	จากการประเมินโดยใช้โปรแกรม Monkey V.1.0 พบว่า อัตราการระบายน้ำผิวดินเมื่อโครงการเปิดดำเนินการหรือภายหลังการพัฒนาขึ้นมีปริมาณสูงกว่า ก่อนการพัฒนาโครงการ ซึ่งจะต้องจัดเตรียมพื้นที่ชะลอน้ำหรือพื้นที่กักเก็บน้ำฝนส่วนเกินอย่างน้อย 312 ลบ.ม. ในระยะเวลา 3 ชม. และเมื่อมีการระบายน้ำไว้ในพื้นที่ที่หน่วยงานต่าง ๆ ที่จัดเตรียมไว้ อาจจะไม่มีดินตะกอนหรือเศษวัสดุต่าง ๆ ตกค้างอยู่ภายในพื้นที่ที่หน่วยงาน ทำให้อาจเกิดการกัดเซาะพังทลายได้ ดังนั้นจึงต้องมีการจัดการในการป้องกันผลกระทบดังกล่าว	• ทนรับตรวจสอบสิ่งแวดล้อมหรือทิศทางทางไหลของน้ำในระบายน้ำ และภายในบ่อพักน้ำ ถ้ามีการสะสมตัวของเศษดิน ตะกอนต่าง ๆ ใน ระบายน้ำและบ่อพักน้ำมาก ให้ดำเนินการทำความสะอาดทาง ระบายน้ำและบ่อพักน้ำ โดยเฉพาะช่วงก่อนถึงฤดูฝนให้ทำการตัด ขยะและดินตะกอนที่ตกค้างออกให้หมด รวมทั้งตรวจสอบและทำ ความสะอาดบ่อพักน้ำสาธารณะหน้าโครงการด้วย • ติดตั้งตะแกรงดักมูลฝอยที่บ่อพักน้ำบ่อสุดท้ายก่อนระบายน้ำลงท่อ ระบายน้ำสาธารณะหน้าโครงการ • จัดให้มีพื้นที่กักเก็บน้ำฝนส่วนเกินไว้ที่บ่อหน้าบ่อน้ำใต้ถนนบริเวณ ด้านหน้าอาคาร A ตามผังรูปที่ 1 มีความสามารถในการกักเก็บน้ำ ฝนส่วนเกินได้ไม่ต่ำกว่า 360 ลบ.ม. ไว้สำหรับกักเก็บน้ำฝนในระย ะเวลา 3 ชม. • ควบคุมการระบายน้ำออกจากพื้นที่ที่หน่วยงาน โดยเมื่อฝนหยุดตก แล้วให้ค่อย ๆ ระบายน้ำออกจากพื้นที่ที่หน่วยงาน โดยเฉพาะพื้นที่ หน่วยงานด้านหลังอาคารให้ระบายออกให้หมด แล้วจึงทำความสะอาด ไม่ให้มีดินตะกอนหรือเศษวัสดุอื่น ๆ ตกค้าง • ติดตั้งเครื่องสูบน้ำ 1 ชุด (จำนวน 2 เครื่อง สำหรับใช้งาน 1 เครื่อง และสำรอง 1 เครื่อง) ในบ่อพักน้ำบริเวณพื้นที่ที่หน่วยงานบนถนนด้าน หลังอาคาร เพื่อสูบน้ำออกจากพื้นที่ที่หน่วยงาน • ติดตามตรวจสอบการทำงานและซ่อมบำรุงระบบบ่อน้ำและ อุปกรณ์ที่เกี่ยวข้องเป็นประจำทุกเดือน เพื่อให้ระบบสามารถทำงาน ได้อย่างมีประสิทธิภาพ	

หน้า 14
วันที่ 14/11/2563
ลงชื่อ 14/11/2563

องค์ประกอบทางสิ่งแวดล้อม และคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบ สิ่งแวดล้อม
10. อาชีวอนามัย ความปลอดภัย และการป้องกันอัคคีภัย	อาจเกิดเหตุเพลิงไหม้หรือเหตุฉุกเฉิน เนื่องจาก ความประมาทของผู้พักอาศัยหรืออุบัติเหตุอื่น ๆ ใน โครงการ ซึ่งเป็นระดับความเสี่ยงที่ค่อนข้างต่ำ รวมทั้ง โครงการจัดเป็นประเภทที่เสี่ยงภัยน้อย และมีการติดตั้ง ระบบต่าง ๆ ได้แก่ ระบบป้องกันอัคคีภัย ระบบแสงสว่าง ระบบไฟฟ้าฉุกเฉิน เป็นต้น อยู่ในมาตรฐานที่ยอมรับ ดังนั้นจึงมีผลกระทบในระดับต่ำ	• การฝึกอบรมเจ้าหน้าที่รักษาความปลอดภัย และเจ้าหน้าที่ที่เกี่ยวข้องให้รับผิดชอบ การป้องกันและระงับอัคคีภัย และการประสาน งานขอความช่วยเหลือจากหน่วยงานบรรเทาสาธารณภัยภายนอกทั้ง ภาครัฐและเอกชน เพื่อความสะดวกรวดเร็วเมื่อเกิดเหตุการณ์ ฉุกเฉิน • โครงการได้ออกแบบระบบสัญญาณแจ้งเหตุเพลิงไหม้ ระบบขม ควันไฟ ทางหนีไฟ ซึ่งประกอบด้วยอุปกรณ์และรายละเอียดการทำงาน สอดคล้องกับกฎกระทรวงฉบับที่ 33 (2535) กฎกระทรวงฉบับที่ 50 (2540) และมาตรฐานต่าง ๆ ตามรายละเอียดในบทที่ 2 • ประชาสัมพันธ์ให้ความรู้แก่ผู้พักอาศัย ผู้ให้บริการและพนักงาน โครงการทราบวิธีการปฏิบัติตนเมื่อเกิดไฟไหม้ และการใช้อุปกรณ์ ดับเพลิง โดยจัดให้มีคู่มือฉุกเฉิน และติดลิ้นแวนผังอาคารแสดง ตำแหน่งทางหนีไฟ และอุปกรณ์ดับเพลิงประจำบริเวณโถงลิฟท์ของ ทุกชั้น รวมทั้งจัดทำป้ายเรื่องแสงแสดงเส้นทางหนีไฟบอกเป็นระยะ ๆ • ตรวจสอบประสิทธิภาพของระบบป้องกันอัคคีภัยต่าง ๆ เป็นประจำ ตามที่ระบุในคู่มือให้พร้อมใช้งานอยู่เสมอ • จัดให้มีการตรวจ/แผนฉุกเฉิน หรือแผนอพยพผู้คนที่ รวมมีมาตรการ ประสานงานขอความช่วยเหลือจากหน่วยงานบรรเทาสาธารณภัย ภายนอกเพื่อความสะดวกรวดเร็วเมื่อเกิดเหตุการณ์ฉุกเฉิน รวมถึง จัดให้มีการฝึกซ้อมดับเพลิง และอพยพหนีไฟอย่างน้อยปีละครั้ง • จัดตั้งทีมปฏิบัติการฉุกเฉินของโครงการ และให้มีการฝึกอบรมเจ้า หน้าที่ภายในทีม รวมถึงเจ้าหน้าที่ที่เกี่ยวข้อง ให้ความรู้ความ สำคัญในการปฏิบัติตามมาตรการ/แผนฉุกเฉินดังกล่าว	มาตรการติดตามตรวจสอบประสิทธิภาพของ ระบบป้องกันอัคคีภัยในขณะดำเนินการ 1) จัดให้มีการตรวจสอบอุปกรณ์ป้องกันอัคคี ภัยให้พร้อมใช้งานอยู่เสมอ เช่น ระบบหัว ฉีดน้ำดับเพลิง ถังดับเพลิง บิมสูบน้ำดับ เพลิง ระบบอัดอากาศ ลิฟท์ดับเพลิง เป็นต้น ถ้าพบความเสียหายหรือชำรุดให้ รีบดำเนินการซ่อมแซมทันที 2) จัดให้มีการอบรมวิธีการใช้อุปกรณ์ของ ระบบป้องกันอัคคีภัย และฝึกอบรมเรื่อง การอพยพหนีไฟทุกคน เมื่อเกิดเหตุเพลิง ไหม้ แก่พนักงาน ผู้พักอาศัย และรับ. • ช่วงเวลาที่ตรวจวัด/ความถี่ 1) เป็นประจำประมาณ 2 ครั้ง/ปี 2) อย่างน้อยปีละครั้ง • ผู้รับผิดชอบ เจ้าของ/ผู้บริหารโครงการ

หน้า 15
วันที่ 15/11/2563
ลงชื่อ 15/11/2563

องค์ประกอบทางสิ่งแวดล้อม และคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
10. การป้องกันบรรเทาสาธารณภัย (ต่อ)		- บริเวณจุดรับน้ำดิบเพลิงด้านหน้าอาคาร A และอาคาร B สำหรับรับน้ำจากลดดับเพลิงที่มีท่อดับเพลิงชนิดต่อสวมเร็วแบบมีเขี้ยวและมีลิ้นก้นน้ำกลับ ขนาดเส้นผ่าศูนย์กลาง 65 มม. เพื่อให้บริการกับพื้นที่อาคารและจ่ายน้ำให้กับถังเก็บน้ำขึ้นได้ดิน จะต้องเป็นพื้นที่ว่างไม่มีสิ่งกีดขวางทางวิ่ง - จัดให้มีพื้นที่จัดรวมพลของโครงการอยู่บริเวณถนนภายในโครงการด้านข้างอาคาร A และบริเวณพื้นที่สีเขียวระหว่างอาคาร A และอาคาร B มีพื้นที่รวมประมาณ 408 ตร.ม. คิดเป็น 0.34 ตร.ม./คน เนื่องจากอยู่ภายในพื้นที่โครงการและห่างจากจุดเกิดเหตุ จึงไม่เกิดขวางเส้นทางวิ่งของรถดับเพลิง สามารถอพยพออกไปยังถนนซอยสุขุมวิท 16 ได้โดยสะดวก ดังนั้น จุดรวมพลจึงมีความเพียงพอที่จะรองรับจำนวนผู้อพยพสูงสุดของโครงการ ในกรณีเกิดเหตุฉุกเฉิน	
11. การสาธารณสุข	เมื่อโครงการเปิดดำเนินการจะมีผู้มาใช้บริการ อาจจะทำให้เกิดการระบาดของโรคติดต่อได้ การเจ็บป่วยจากอุบัติเหตุเนื่องจากความประมาท และจากระบบสุขาภิบาลที่ไม่ถูกสุขลักษณะ เป็นต้น	มาตรการในการจัดการระบบสาธารณสุข สุขาภิบาลและอนามัยสิ่งแวดล้อม ได้แก่ - จัดเตรียมระบบการปฐมพยาบาล และอุปกรณ์ต่างๆที่จำเป็นเบื้องต้น รวมทั้งพาหนะสำรองในกรณีฉุกเฉินที่ต้องนำส่งสถานพยาบาลให้พร้อมในพื้นที่โครงการ - มีการประสานงานกับสถานบริการทางสาธารณสุขรัฐและเอกชนในบริเวณใกล้เคียงเพื่อสำรองยานฉุกเฉิน - ตรวจสอบประสิทธิภาพของระบบสุขาภิบาลและอนามัยสิ่งแวดล้อมให้มีประสิทธิภาพที่ดีอยู่เสมอ	


หน้า 16
ลงชื่อ.....
.....

องค์ประกอบทางสิ่งแวดล้อม และคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
11. การสาธารณสุข (ต่อ)		มาตรการในการจัดการระบบปรับอากาศ ได้แก่ - ซ่อมแซม ดูแล และบำรุงรักษาระบบปรับอากาศให้อยู่ในสภาพที่ดีและสะอาดพร้อมที่จะใช้งานตลอดเวลา - ทำความสะอาดถังพักน้ำและบ่อเก็บน้ำเมื่อตรวจความสกปรก และให้ระบายตะกอนก้นถังทิ้ง 1-2 ครั้ง/ปี - ให้มีการหมุนเวียนการใช้น้ำในถังพักน้ำและบ่อเก็บน้ำ - ควบคุมค่าคลอรีนอิสระตกค้างในถังพักน้ำและบ่อเก็บน้ำไม่ให้ต่ำกว่า 0.2 มก./ล. - ถอดล้างทำความสะอาดและฆ่าเชื้อโรค หัวที่อกน้ำและมิเตอร์ภายในห้องพักและห้องน้ำสาธารณะทุกห้อง - ทำความสะอาดและเปลี่ยนน้ำบริเวณสระน้ำอยู่เสมอ	
12. ทัศนียภาพ	อาคารมีลักษณะที่สอดคล้องกับทัศนียภาพของพื้นที่โดยรอบ ซึ่งเป็นอาคารสูงเช่นเดียวกัน รวมทั้งการตกแต่งภายนอกอาคารมีลักษณะที่กลมกลืนกับสภาพแวดล้อมโดยรอบ นอกจากนี้โครงการยังได้จัดให้มีพื้นที่สีเขียว มีพื้นที่ปลูกต้นไม้รอบบริเวณโครงการ จากลักษณะดังกล่าวทัศนียภาพจะเห็นว่าลักษณะของโครงการมีความคล้ายคลึงกับสภาพแวดล้อม จึงไม่เกิดความแตกต่างทางด้านภูมิทัศน์ จึงเป็นภาพที่อินตา ดังนั้นผลกระทบของโครงการที่มีต่อทัศนียภาพ จึงไม่เกิดผลกระทบแต่อย่างใด	- โครงการได้จัดให้มีพื้นที่สีเขียวรวม 1,696 ตร.ม. คิดเป็นอัตราส่วนพื้นที่สีเขียวต่อจำนวนผู้พักอาศัยกับพนักงานประจำโครงการ (1,214 คน) เท่ากับ 1.6 :1 เพื่อเป็นที่พักผ่อนหย่อนใจของผู้พักอาศัย ซึ่งพื้นที่สีเขียวมีตำแหน่งที่ตั้งอยู่ทั่วบริเวณ - ชั้นที่ 1 บริเวณรอบโครงการ ทั้งด้านหน้า ด้านข้างและด้านหลังริมถนนทางเข้าโครงการ มีพื้นที่ประมาณ 968 ตร.ม. หรือร้อยละ 51.0 ของพื้นที่สีเขียวทั้งหมด - บนอาคาร A ชั้นที่ 7 และ 8 บริเวณสระน้ำและภายในอาคาร มีพื้นที่ประมาณ 177 ตร.ม. หรือร้อยละ 9.3 ของพื้นที่สีเขียวทั้งหมด - บนอาคาร B ชั้นที่ 7, 9, 11, 15, 17, 20 และ 23 มีพื้นที่ประมาณ 735 ตร.ม. หรือร้อยละ 38.7 ของพื้นที่สีเขียวทั้งหมดตามผังรูปที่ 2 ถึงรูปที่ 11 - ดูแลรักษา บำรุงพันธุ์ไม้ในสวนหย่อมให้คงงามอยู่เสมอ โดยเฉพาะตามบริเวณริมขอบอาคารและสวนหย่อมหน้าโครงการ - ควรปลูกต้นไม้ประเภทไม้เลื้อยเพิ่มมากขึ้น เพื่อให้อาคารบางส่วนเป็นคอนกรีตลดลง	ติดตามตรวจสอบสภาพพื้นที่สีเขียวให้คงอยู่ตามสภาพปกติทุก 6 เดือน


หน้า 17
ลงชื่อ.....
.....



องค์ประกอบทางสิ่งแวดล้อมและคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
13. การอนุรักษ์พลังงาน	โครงการจัดเป็นอาคารขนาดใหญ่ หรืออาคารขนาดใหญ่พิเศษซึ่งมีปริมาณการใช้ไฟฟ้าเป็นจำนวนมาก โดยที่การใช้พลังงานสำหรับระบบปรับอากาศจะมีค่าสูงสุด ซึ่งการใช้พลังงานภายในโครงการจะมีผลต่อการใช้พลังงานในอนาคต ดังนั้นเพื่อไม่ให้เกิดการใช้พลังงานได้อย่างมีประสิทธิภาพสูงสุด จึงกำหนดมาตรการอนุรักษ์พลังงานภายในอาคาร เพื่อลดผลกระทบดังกล่าว	มาตรการอนุรักษ์พลังงานภายในอาคารสามารถดำเนินการในระบะดัดแปลง (การออกแบบและตกแต่ง) โดยการเลือกใช้อุปกรณ์และวัสดุต่าง ๆ ให้เหมาะสมกับลักษณะการใช้งาน และเลือกวิธีการอื่น ๆ ที่สามารถช่วยอนุรักษ์พลังงานภายในอาคารได้ ซึ่งมาตรการดังกล่าวประกอบด้วย - การประหยัดพลังงานไฟฟ้า - ติดตั้งฉนวนหรือมู่ลี่เพื่อป้องกันแสงแดดส่องเข้ามาภายในอาคาร และลดอุณหภูมิภายในห้องพักหรือพื้นที่ที่ใช้ระบบปรับอากาศ ซึ่งมีผลทำให้การใช้พลังงานของระบบปรับอากาศน้อยลง - ติดตั้งฉนวนกันความร้อนหรือพื้นที่ที่ใช้ระบบปรับอากาศ เพื่อลดการสูญเสียพลังงานจากการถ่ายเทความร้อนเข้ามาภายในตัวอาคาร - ติดตั้งอุปกรณ์ควบคุมการเปิด-ปิดประตูของห้องพักและพื้นที่ที่ใช้ระบบปรับอากาศ เพื่อลดการสูญเสียพลังงานจากการถ่ายเทความร้อน - จัดพื้นที่สีเขียวหรือพื้นที่สวนหย่อมรอบ ๆ อาคารเพื่อลดความร้อน และเพิ่มความชื้นหรือความเย็นให้กับอาคาร - เลือกใช้หลอดไฟประหยัดพลังงาน เช่น หลอดคอม หลอดตะเกียบ หรือหลอดคอมแพคท์ฟลูออเรสเซนต์ - เลือกใช้วัสดุสตั๊ปปะระหัดไฟหรือวัสดุฉนวนกันความร้อนกับหลอดคอม เพื่อช่วยเพิ่มประสิทธิภาพในการประหยัดไฟ - ภายในห้องพักหรือบริเวณที่มีการใช้โคมไฟควรวางโคมไฟแบบมีแผ่นสะท้อนแสง เพื่อช่วยให้แสงสว่างจากหลอดไฟกระจายได้อย่างเต็มประสิทธิภาพ ทำให้ไม่จำเป็นต้องใช้หลอดไฟฟลูออเรสเซนต์ จึงช่วยประหยัดพลังงานได้เป็นอย่างดี	



องค์ประกอบทางสิ่งแวดล้อมและคุณค่าต่าง ๆ	ผลกระทบต่อสิ่งแวดล้อมที่สำคัญ	มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม	มาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
13. การอนุรักษ์พลังงาน (ต่อ)		- ควรใช้สีอ่อนตกแต่งอาคาร ทาผนังนอกอาคารส่วนที่เป็นคอนกรีต เพื่อการสะท้อนแสงที่ดี และทาภายในอาคารเพื่อให้ห้องสว่างยิ่งขึ้น - ใช้แสงสว่างจากธรรมชาติให้มากที่สุด เพื่อให้ความสว่างแก่ภายในห้องพักและส่วนต่าง ๆ ของอาคาร - การติดตั้งสวิตช์ไฟเพื่อระบบแสงสว่างและระบบปรับอากาศ ควรติดตั้งแยกออกจากกันเพื่อให้เปิด-ปิดได้เฉพาะจุด ไม่ใช้ปุ่มเดียวกันในการเปิด-ปิดทั้งชิ้น และมีตัวบอกให้ทราบถึงสถานะการทำงานของหลอดไฟฟ้าและระบบปรับอากาศในแต่ละส่วนของแต่ละชิ้น ซึ่งทำให้ลดการสิ้นเปลืองและสูญเสียพลังงานไฟฟ้าได้ยิ่งขึ้น การประหยัดน้ำ - ควรเลือกใช้เครื่องสุขภัณฑ์ภายในห้องพักและพื้นที่ส่วนอื่น ๆ แบบประหยัดน้ำ เช่น ชักโครก ผักบัวและก๊อกน้ำแบบประหยัดน้ำ เป็นต้น - เมื่อติดตั้งท่อจ่ายน้ำและเครื่องสุขภัณฑ์ภายในอาคารแล้วควรมีการตรวจสอบการรั่วซึมก่อนที่จะเปิดดำเนินการ	



รูปที่ 1 ส่วนแผนที่ที่แสดงระบบบำบัดน้ำเสีย บ่อพักน้ำ และจุดตรวจวัดคุณภาพน้ำจากระบบบำบัดน้ำเสียของโครงการ









ผลการดำเนินงานและมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม
โครงการด้านทรัพยากรมนุษย์และสถานที่พักตากอากาศ

เพื่อให้รูปแบบของระบบการปฏิบัติงานตามโครงการฯ เป็นไปในแนวทางเดียวกัน สหพันธ์ฯ จึง
แนะวิธีการในการดำเนินงานของห้องฯ ของโครงการ หรือผู้ดูแลมอบหมายแก่ห้องโครงการ ให้เป็นลำดับ
รายละเอียดตามกรอบงานตามผลการปฏิบัติงานตามโครงการฯ ตามรูปแบบตัวอย่าง ดังนี้

1.1 ปกหน้าประกอบด้วย

- ၄၈၂ -

- เข้าของโครงการและสถานที่ผู้ติดตามได้
- สถานที่ตั้งโครงการ
- บริษัทที่ปรึกษาผู้จัดทำรายงาน (ถ้ามี)

(PLG) PUNGLZLWQOH₈. RUSPULHNSN -

1.2 หนังสือประกอบการจัดทำรายงาน ฯ ปฏิบัติราชการของผู้บังคับการรายงานไปตามแบบ ศส. 1

2.1 รายละเอียดโครงการ โดยสังเขป' ตามแบบ ศค.2

- พืชสังเคราะห์แสงและทางใบ
- การลำเลียงน้ำและอาหารในพืช
- การสืบพันธุ์แบบอาศัยเพศและไม่อาศัยเพศ

2.2 ความจำเป็นของการจัดทำรายงาน

2.3 แผนการดำเนินงานโครงการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมและมาตรการบรรเทาผลกระทบสิ่งแวดล้อม ตามระบุไว้ในรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อม

3. ผลการดำเนินงานการตามมาตรการป้องกันและลดผลกระทบสิ่งแวดล้อม

3.1 ข้อจำกัดทางงบประมาณในการฝึกอบรมและการฝึกอบรมบุคลากรในท้องถิ่นสามารถดำเนินการได้

[illegible]

- 3.2 หากโครงการมีการเปลี่ยนแปลงรายละเอียดการดำเนินการหรือมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมที่แตกต่างไปจากรายละเอียดหรือมาตรการที่เสนอไว้ในรายงาน ฯ ที่ผ่านความเห็นชอบแล้ว ให้เสนอมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมที่เปลี่ยนแปลงดังกล่าว พร้อมให้เหตุผลประกอบ โดยแสดงข้อมูลพร้อมภาพประกอบด้วย

4. ผลการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม

- 4.1 แสดงจุดเก็บตัวอย่างคุณภาพสิ่งแวดล้อม เช่น คุณภาพน้ำ เป็นต้น ต้องแสดงโดยใช้แผนที่ประกอบ พร้อมทั้งแสดงพารามิเตอร์ในการตรวจวัด และมาตรฐานเปรียบเทียบ
- 4.2 ให้เปรียบเทียบผลการตรวจวัดคุณภาพสิ่งแวดล้อมกับมาตรฐานคุณภาพสิ่งแวดล้อมของประเทศไทย ผลการตรวจวัดของทุกครั้งที่ผ่านมาและคุณภาพสิ่งแวดล้อมที่ประเมินได้ในรายงาน ฯ ที่ผ่านความเห็นชอบ โดยแสดงในรูปกราฟ ตารางหรือลักษณะอื่น ๆ ที่สามารถแสดงการเปรียบเทียบผล การตรวจวัดคุณภาพสิ่งแวดล้อมได้อย่างชัดเจน รวมทั้งวิจารณ์ผลและให้ข้อเสนอแนะ
- 4.3 ต้องมีภาพถ่ายแสดงขณะทำการเก็บตัวอย่าง ภาพถ่ายเครื่องมือขณะตรวจวัด (ภาคสนาม) พร้อมแสดง วันที่ และเวลาในภาพถ่ายอย่างชัดเจน โดยการถ่ายภาพจะต้องแสดงให้เห็นว่า เป็นการตรวจวัด ณ สถานที่ ตามที่กำหนดไว้ในรายงาน ฯ

5. สรุปผลการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม

สรุปผลการติดตามตรวจสอบการปฏิบัติตามเงื่อนไขของมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมและผลการตรวจวัดคุณภาพสิ่งแวดล้อมในการติดตามตรวจสอบครั้งนี้ พร้อมทั้งสรุปประเด็นการปฏิบัติที่ต้องปรับปรุงโดยเสนอแนะมาตรการเพิ่มเติมหรือเห็นสมควรยุติการปฏิบัติ เนื่องจากการปฏิบัติตามมาตรการที่ผ่านมาสามารถป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมได้อย่างสมบูรณ์หรือมาตรการดังกล่าวไม่มีความจำเป็นต้องปฏิบัติอีกต่อไป โดยมีข้อมูลต่าง ๆ สนับสนุนอย่างเพียงพอ หากผู้ประกอบการต้องการปรับเปลี่ยนมาตรการฯ หรือวิธีการปฏิบัติอย่างหนึ่งอย่างใด ต้องเสนอรายละเอียดให้คณะกรรมการผู้ชำนาญการพิจารณาเห็นชอบกับมาตรการฯ ที่ขอเปลี่ยนแปลงก่อนจึงจะสามารถดำเนินการเปลี่ยนแปลงได้

6. ภาคผนวก

ประกอบด้วยแหล่งที่มาของเอกสารอ้างอิงต่าง ๆ ส่วนหนังสืออนุญาตขึ้นทะเบียนห้องปฏิบัติการวิเคราะห์เอกชน ส่วนหนังสืออนุญาตการขอเปลี่ยนแปลงรายละเอียดโครงการหรือมาตรการ แผนภาพหรือภาพถ่ายอุปกรณ์เครื่องมือที่ใช้ในการเก็บตัวอย่าง เพื่อตรวจวิเคราะห์คุณภาพสิ่งแวดล้อมและข้อมูลประกอบอื่น ๆ เป็นต้น

การเสนอรายงาน

หน่วยงานที่จัดส่ง : รายงานผลการปฏิบัติตามมาตรการที่จัดทำขึ้น จะต้องส่งให้หน่วยงานที่เกี่ยวข้องพิจารณา ดังนี้

- | | |
|---|---------------------------------|
| 1. สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม | จำนวน 1 ฉบับ พร้อม CD-ROM 1 ชุด |
| 2. สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อมจังหวัด | จำนวน 1 ฉบับ พร้อม CD-ROM 1 ชุด |
| 3. องค์การปกครองส่วนท้องถิ่น | จำนวน 1 ฉบับ พร้อม CD-ROM 1 ชุด |

หมายเหตุ : กรณีโครงการตั้งอยู่ใน กทม. ให้ส่ง สผ. และ สำนักงานเขตในพื้นที่รับผิดชอบ

ระยะเวลาที่จัดส่ง : ส่ง 2 ครั้ง ต่อปี คือ ภายในเดือนกรกฎาคม (รวบรวมผลการติดตามตรวจสอบของเดือนมกราคมถึงมิถุนายน) และภายในเดือนมกราคม (รวบรวมผลการติดตามตรวจสอบของเดือนกรกฎาคมถึงธันวาคมของปีก่อน)

หนังสือรับรองการจัดทำรายงานผล การปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม
และมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม
โครงการด้านที่พักอาศัย บริการชุมชนและสถานที่พักตากอากาศ

วันที่ เดือน พ.ศ.

หนังสือรับรองฉบับนี้ ขอรับรองว่า เป็นผู้จัดทำ
รายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมและมาตรการติดตาม
ตรวจสอบคุณภาพสิ่งแวดล้อม โครงการ
ของ ประจำเดือน โดยมีคณะผู้จัดทำ
รายงาน ดังต่อไปนี้

ผู้จัดทำรายงาน	ลายมือชื่อ	ตำแหน่ง
.....		
.....		
.....		
.....		

ขอแสดงความนับถือ

ตำแหน่ง
(ประทับตราบริษัท)

รายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม
และมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม
โครงการด้านที่พักอาศัย บริการชุมชนและสถานที่พักตากอากาศ

- ชื่อโครงการ
- สถานที่ตั้ง
- ชื่อเจ้าของโครงการ
- จัดทำโดย
- โครงการผ่านการพิจารณาของคณะกรรมการผู้ชำนาญการเมื่อวันที่ เดือน พ.ศ.
- โครงการได้นำเสนอรายงานผลการปฏิบัติตามครั้งสุดท้าย เมื่อวันที่ เดือน พ.ศ.
- รายละเอียดโครงการ

7.1 ลักษณะ / ประเภทโครงการ

7.2 พื้นที่โครงการ

7.3 กิจกรรมในโครงการ

• การนำบักขี้เณร

• การระบายน้ำ

• การจัดการขยะมูลฝอย

• เปรียบเทียบรายละเอียดการดำเนินการของโครงการที่เปลี่ยนแปลงหรือแตกต่างไปจาก
รายละเอียดที่เสนอไว้ในรายงานผลกระทบสิ่งแวดล้อมเบื้องต้น

ตารางที่ 1. แบบรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม
และมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อม

โครงการ

เงื่อนไขตามมาตรการ	ผลการปฏิบัติตามมาตรการ	ปัญหา อุปสรรค ที่ไม่สามารถปฏิบัติตามมาตรการ และแนวทางแก้ไข
มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมที่เสนอไว้ในรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อม		
1 ...		
2 ...		
3 ...		

ตารางที่ 2 แบบบันทึกผลการตรวจวัดคุณภาพน้ำ

ตารางที่ 2.1 แบบบันทึกผลการตรวจวัดคุณภาพน้ำผิวดิน

ชื่อโครงการ

ตั้งอยู่ที่

ครั้งที่ ประจำปี พ.ศ. วันที่ เดือน พ.ศ.

สถานที่เก็บตัวอย่าง

ตำแหน่งตรวจวัด	พารามิเตอร์ที่ตรวจวัด					
มาตรฐาน *						

หมายเหตุ : * มาตรฐานคุณภาพน้ำในแหล่งน้ำผิวดินประเภท จากประกาศสำนักงานคณะกรรมการสิ่งแวดล้อมแห่งชาติ ฉบับที่ 8 (พ.ศ.2537) เรื่อง กำหนดมาตรฐานคุณภาพน้ำในแหล่งน้ำผิวดิน ลงวันที่ 24 กุมภาพันธ์ พ.ศ. 2537

ตารางที่ 2.2 แบบบันทึกผลการตรวจวัดคุณภาพน้ำทิ้ง

ชื่อโครงการ

ตั้งอยู่ที่

ครั้งที่ ประจำปี พ.ศ. วันที่ เดือน พ.ศ.

สถานที่เก็บตัวอย่าง

ตำแหน่งตรวจวัด	พารามิเตอร์ที่ตรวจวัด		
มาตรฐาน*, **			

หมายเหตุ : * มาตรฐานคุณภาพน้ำทิ้งจากโรงงานอุตสาหกรรม เทคโนโลยีและสิ่งแวดล้อม ฉบับที่ 5 (พ.ศ. 2539) เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากต้นจัดสรร

** มาตรฐานคุณภาพน้ำทิ้งจากโรงงานอุตสาหกรรม เทคโนโลยีและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด

ที่ ทส 1009.5/ 1041



สำนักงานนโยบายและแผน
ทรัพยากรธรรมชาติและสิ่งแวดล้อม
60/1 ซอยพิบูลวัฒนา 7 ถนนพระรามที่ 6
กรุงเทพฯ 10400

7 กุมภาพันธ์ 2551

เรื่อง ขอเปลี่ยนแปลงจำนวนห้องพัก รายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการ
เปลี่ยนแปลงการใช้ประโยชน์ อาคารซัมเมอร์เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนซ์
เป็นโรงแรม ซัมเมอร์เซ็ท เลคพอยท์

เรียน กรรมการผู้จัดการบริษัทหลักทรัพย์จัดการกองทุน อเบอร์ติน จำกัด

อ้างถึง หนังสือบริษัทหลักทรัพย์จัดการกองทุน อเบอร์ติน จำกัด ที่ ส.ก.750/2550
ลงวันที่ 21 ธันวาคม 2550

ตามหนังสือที่อ้างถึง บริษัทหลักทรัพย์จัดการกองทุน อเบอร์ติน จำกัด ในฐานะ
ผู้จัดการกองทุนรวมสินทรัพย์ไทย 2 ได้มีหนังสือถึงสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและ
สิ่งแวดล้อม แจ้งว่า บริษัทฯ มีความจำเป็นต้องลดจำนวนห้องพักอาคาร A จากที่ได้นำเสนอ
ไว้ในรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมโครงการเปลี่ยนแปลงการใช้ประโยชน์ อาคารซัมเมอร์
เซ็ท เลคพอยท์ เซอร์วิส เรสซิเดนซ์ เป็นโรงแรม ซัมเมอร์เซ็ท เลคพอยท์ ซึ่งได้รับความเห็นชอบ
จากสำนักงานฯ ตามหนังสือ ที่ ทส 1009/4425 ลงวันที่ 14 พฤษภาคม 2550 จำนวน 280 ยูนิต
ลดลงเหลือ 230 ยูนิต โดยจะเปลี่ยนแปลงรายละเอียดการใช้พื้นที่อาคารในชั้นที่ 8-20 และชั้นที่ 28-
31 ของอาคาร A (ชั้นที่ 21-27 ไม่เปลี่ยนแปลง) ทั้งนี้ การเปลี่ยนแปลงดังกล่าวไม่ส่งผลกระทบต่อ
ระบบสาธารณสุขโลก สาธารณูปการภายในโครงการ และพื้นที่การใช้ประโยชน์อาคารแต่อย่างใด

สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ได้นำเสนอเรื่องดังกล่าว
ต่อคณะกรรมการผู้ชำนาญการพิจารณารายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อมด้านโครงการกวดขัน

2ชุมชน

2

ชุมชน ในการประชุมครั้งที่ 3/2551 เมื่อวันที่ 22 มกราคม 2551 คณะกรรมการผู้ชำนาญการฯ มีมติ
เห็นชอบกับการขอเปลี่ยนแปลงจำนวนห้องพักของอาคาร A จากจำนวน 280 ยูนิต เหลือ 230 ยูนิต ของ
โครงการโรงแรม ซัมเมอร์เซ็ท เลคพอยท์ โดยให้โครงการปฏิบัติตามเงื่อนไขที่โครงการโรงแรม
ซัมเมอร์เซ็ท เลคพอยท์ ต้องยึดถือปฏิบัติอย่างเคร่งครัด และโครงการต้องนำเสนอรายงานผลการ
ปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมและมาตรการติดตามตรวจสอบคุณภาพ
สิ่งแวดล้อม ตามหนังสือสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม ที่ ทส
1009/4425 ลงวันที่ 14 พฤษภาคม 2550

จึงเรียนมาเพื่อโปรดพิจารณาดำเนินการในส่วนที่เกี่ยวข้องต่อไป

ขอแสดงความนับถือ

(นายชินกร ทยธรรมชาติ)
รองเลขาธิการ ปฏิบัติราชการแทน

เลขาธิการสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม

สำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อม

โทรศัพท์ 0-2265-8500 ต่อ 8810-8815

โทรสาร 0-2265-8616



ที่ มท ๐๓๐๗.๖/๖๕๐๓๑



กรมการปกครอง
ถนนอัษฎางค์ กทม. ๑๐๒๐๐

พ๐ พุทธศักราช ๒๕๖๑

เรื่อง บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด ขอเปลี่ยนชื่อโรงแรม

เรียน ผู้ประกอบธุรกิจโรงแรม “โรงแรม ซัมเมอร์เซ็ท เลค พอยท์”

อ้างถึง คำขอแจ้งความประสงค์ทั่วไปตามแบบ ร.ร.๑/๓ เลขที่รับ ๓๖๗/๒๕๖๑ ลงวันที่ ๒๑ สิงหาคม ๒๕๖๑

ตามที่ บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด ผู้ประกอบธุรกิจโรงแรม “โรงแรม ซัมเมอร์เซ็ท เลค พอยท์” ได้ยื่นคำขอเปลี่ยนชื่อโรงแรมจาก “โรงแรม ซัมเมอร์เซ็ท เลค พอยท์” เป็น “โรงแรม ชามา เลควิว อโศก” และเปลี่ยนชื่อภาษาต่างประเทศจาก “SOMERSET LAKE POINT HOTEL” เป็น “shama lakeview asoke” นั้น

บัดนี้ นายทะเบียนโรงแรมกรุงเทพมหานครได้พิจารณาอนุญาตให้ บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด เปลี่ยนชื่อโรงแรมได้ตามคำขอ จึงขอให้ท่านไปรับใบอนุญาตประกอบธุรกิจโรงแรม ณ ส่วนการรักษาความสงบเรียบร้อย ๓ สำนักการสอบสวนและนิติการ กรมการปกครอง (วังไชยา) ถนนนครสวรรค์ เขตดุสิต กรุงเทพมหานคร ในวัน และเวลาราชการต่อไป

จึงเรียนมาเพื่อทราบและดำเนินการ

ขอแสดงความนับถือ

(นายวิสิทธิ์พัฒน์ อนันตรสุชาติ)

ผู้อำนวยการสำนักการสอบสวนและนิติการ ปฏิบัติราชการแทน

อธิบดีกรมการปกครอง

นายทะเบียนโรงแรมกรุงเทพมหานคร

สำนักการสอบสวนและนิติการ

ส่วนการรักษาความสงบเรียบร้อย ๓

โทร./โทรสาร ๐-๒๓๕๖-๕๕๕๕

ภาคผนวกที่ 2

ผลการตรวจสอบคุณภาพน้ำ ประจำเดือนมกราคม-มิถุนายน 2569



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsnitwong 46 Jarunsnitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



รายงานหมายเลข (Report No.) 2580126 วันที่ (Date) 21 มกราคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6901249 No. 6901250
ลักษณะตัวอย่างทางกายภาพ ขุ่นตะกอนสีน้ำตาล สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 14 มกราคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 14 มกราคม 2569 - 21 มกราคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 13 มกราคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH v	-	6.5	6.8	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids	mg/L	408 ✓	709	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids	mg/L	20.5	2.0	-	ไม่เกิน 30	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand	mg/L	36.8 ✓	4.7	-	ไม่เกิน 20	5 Days BOD Test, Azide Modification Method (5210 B)
Oil and Grease	mg/L	1.8	0.7	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen	mg/L	55.4	1.3	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	5.8	0.4	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด พ.ศ. 2567 (ประเภท ก)


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากรายงาน

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- วัฏจักรการให้ผลการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ขัดตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ไม่รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 2590126 วันที่ (Date) 21 มกราคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6901249 No. 6901250
ลักษณะตัวอย่างทางกายภาพ ขุ่นตะกอนสีน้ำตาล สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 14 มกราคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 14 มกราคม 2569 - 21 มกราคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 13 มกราคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)


พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids	ml/L	< 0.1	< 0.1	-	-	Imhoff cone (2540 F)


หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่ได้จากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com



รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 2600126 วันที่ (Date) 21 มกราคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6901251 No. 6901252
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีน้ำตาล สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวพี บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 14 มกราคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 14 มกราคม 2569 - 21 มกราคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 13 มกราคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH v	-	7.0	6.8	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids	mg/L	280 ✓	523	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids	mg/L	37.5 ✓	4.0	-	ไม่เกิน 40	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand	mg/L	25.8 ✓	2.2	-	ไม่เกิน 30	5 Days BOD Test, Azide Modification Method (5210 B)
Oil and Grease	mg/L	1.8	1.2	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen	mg/L	3.1	0.6	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	0.0	0.3	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด พ.ศ. 2567 (ประเภท ข)


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ✓ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)




TESTING
No.0090


รายงานหมายเลข (Report No.) 2610126 วันที่ (Date) 21 มกราคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6901251 No. 6901252
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีน้ำตาล สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 14 มกราคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 14 มกราคม 2569 - 21 มกราคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 13 มกราคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids	ml/L	1.5 ✓	< 0.1	-	-	Imhoff cone (2540 F)

หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

- ^c เป็นข้อมูลที่มาจากลูกค้า
- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C
 - ✓ รายการที่ได้รับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025:2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ
 - ห้องปฏิบัติการมีนโยบายไม่เก็บตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวพิชพรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ไม่รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำหังฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0510226 วันที่ (Date) 11 กุมภาพันธ์ 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6902043 No. 6902044
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงรรมขามมา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 กุมภาพันธ์ 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 กุมภาพันธ์ 2569 - 11 กุมภาพันธ์ 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 3 กุมภาพันธ์ 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH v	-	6.2	6.8	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids	mg/L	276 ✓	729	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids	mg/L	17.0	3.0	-	ไม่เกิน 30	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand	mg/L	44.2 ✓	5.9	-	ไม่เกิน 20	5 Days BOD Test, Azide Modification Method (5210 B)
Oil and Grease	mg/L	3.2	0.9	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen	mg/L	14.2	1.3	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	1.8 ✓	0.2	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด พ.ศ. 2567 (ประเภท ก)

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ✓ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิรันดร์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834958-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0520226 วันที่ (Date) 11 กุมภาพันธ์ 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6902043 No. 6902044
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 กุมภาพันธ์ 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 กุมภาพันธ์ 2569 - 11 กุมภาพันธ์ 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 3 กุมภาพันธ์ 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)


พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids	ml/L	0.2	< 0.1	-	-	Imhoff cone (2540 F)

หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราวัฒน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์ญัติน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ให้บริการเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ (ANALYSIS REPORT)



รายงานหมายเลข (Report No.) 0530226 วันที่ (Date) 11 กุมภาพันธ์ 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6902045 No. 6902046
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีน้ำตาล สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิววู บิซิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมปามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 กุมภาพันธ์ 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 กุมภาพันธ์ 2569 - 11 กุมภาพันธ์ 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 3 กุมภาพันธ์ 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH V	-	6.8	7.7	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids	mg/L	240 ✓	506	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids	mg/L	21.0	1.5	-	ไม่เกิน 40	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand	mg/L	40.5 ✓	3.0	-	ไม่เกิน 30	5 Days BOD Test, Azide Modification Method (5210 B)
Oil and Grease	mg/L	0.6	0.5	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen	mg/L	6.0	0.6	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	0.0	0.3	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำจากอาคารบางประเภทและบางขนาด พ.ศ. 2567 (ประเภท ข)

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากรหัส

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- วัสดุการที่ได้รับความรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิกรรัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีซี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0540226 วันที่ (Date) 11 กุมภาพันธ์ 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6902045 No. 6902046
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีน้ำตาล สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 กุมภาพันธ์ 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 กุมภาพันธ์ 2569 - 11 กุมภาพันธ์ 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 3 กุมภาพันธ์ 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)


พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids	ml/L	0.1	< 0.1	-	-	Imhoff cone (2540 F)

หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากการสุ่ม

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่รับตัวอย่างเอง


(นายฐานันท์ นิภารัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834958-7 , (02) 8834274 Fax : (02) 8834958 E-mail address hv_eng@hotmail.com



รายงานผลการทดสอบ (ANALYSIS REPORT)

TESTING
No.0090

รายงานหมายเลข (Report No.) 0290326 วันที่ (Date) 11 มีนาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6903024 No. 6903025
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีน้ำตาล สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิว บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 มีนาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 มีนาคม 2569 - 11 มีนาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 มีนาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH v	-	6.9	7.1	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids	mg/L	363 ✓	577	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids	mg/L	14.0	3.0	-	ไม่เกิน 30	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand	mg/L	16.2	5.7	-	ไม่เกิน 20	5 Days BOD Test, Azide Modification Method (5210 B)
Oil and Grease	mg/L	1.3	1.3	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen	mg/L	39.1 ✓	1.3	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	0.3	0.0	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำจากอาคารบางประเภทและขนาด พ.ศ. 2567 (ประเภท ก)


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ✓ รายงานที่ได้มีการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025:2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิภารัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0300326 วันที่ (Date) 11 มีนาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6903024 No. 6903025
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีน้ำตาล สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิว บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 มีนาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 มีนาคม 2569 - 11 มีนาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 มีนาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids	ml/L	0.1	< 0.1	-	-	Imhoff cone (2540 F)

หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง

จุฑาโณ นิรันดร์
(นายฐานันท์ นิรันดร์)
ผู้จัดการฝ่ายวิชาการ

ปิณฑิรา
(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำให้อ่าน



บริษัท เอชวีอี จำกัด 603 ซอยเจริญสุขนิทวงศ์ 46 ถนนเจริญสุขนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834958-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0310326 วันที่ (Date) 11 มีนาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6903026 No. 6903027
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงรณรามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 มีนาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 มีนาคม 2569 - 11 มีนาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 มีนาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH v	-	7.0	7.8	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids v	mg/L	203	391	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids	mg/L	11.0	1.5	-	ไม่เกิน 40	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand	mg/L	35.5	2.2	-	ไม่เกิน 30	5 Days BOD Test, Azide Modification Method (5210 B)
Oil and Grease	mg/L	1.2	0.4	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen	mg/L	4.6	0.6	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	0.0	0.0	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานคุณภาพการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด พ.ศ. 2567 (ประเภท ข)


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023


^c เป็นข้อมูลที่มาจากลูกค้า

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- วัสดุการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิการัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ไปรับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำให้องค์



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0320326 วันที่ (Date) 11 มีนาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6903026 No. 6903027
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 มีนาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 มีนาคม 2569 - 11 มีนาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 มีนาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids	mg/L	< 0.1	< 0.1	-	-	Imhoff cone (2540 F)

หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่ได้จากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราธร)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0850426 วันที่ (Date) 9 เมษายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6904079 No. 6904080
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลดวิ อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 2 เมษายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 2 เมษายน 2569 - 9 เมษายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 1 เมษายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH v	-	6.5	7.0	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids	mg/L	247 ✓	623	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids	mg/L	8.5	5.0	-	ไม่เกิน 30	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand	mg/L	42.5 ✓	3.0	-	ไม่เกิน 20	5 Days BOD Test, Azide Modification Method (5210 B)
Oil and Grease	mg/L	1.9	4.8	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen	mg/L	46.6 ✓	0.3	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	5.4	0.0	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด พ.ศ. 2567 (ประเภท ก)


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- วัสดุการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิการัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำให้ง่าย



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0860426 วันที่ (Date) 9 เมษายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6904079 No. 6904080
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวบู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 2 เมษายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 2 เมษายน 2569 - 9 เมษายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 1 เมษายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids	ml/L	< 0.1	< 0.1	-	-	Imhoff cone (2540 F)

หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

- ^c เป็นข้อมูลที่ได้จากลูกค้า
- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C
- ห้องปฏิบัติการมีนโยบายไม่ใช้ตัวอย่างเอง


(นายฐานันท์ นิการัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0870426 วันที่ (Date) 9 เมษายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6904081 No. 6904082
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีน้ำตาล สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิววี บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 2 เมษายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 2 เมษายน 2569 - 9 เมษายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 1 เมษายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH √	-	6.6	7.5	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids √	mg/L	205	357	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids	mg/L	13.5	1.0	-	ไม่เกิน 40	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand	mg/L	32.0 √	2.2	-	ไม่เกิน 30	5 Days BOD Test, Azide Modification Method (5210 B)
Oil and Grease	mg/L	2.7	1.5	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen	mg/L	0.9	0.3	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	0.0	0.0	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด พ.ศ. 2567 (ประเภท ข)

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- วัสดุการวิเคราะห์ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jaruansanitwong 46 Jaruansanitwong Road Bangyeeakan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0880426 วันที่ (Date) 9 เมษายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6904081 No. 6904082
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีน้ำตาล สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขาม่า เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 2 เมษายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 2 เมษายน 2569 - 9 เมษายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 1 เมษายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids	ml/L	< 0.1	< 0.1	-	-	Imhoff cone (2540 F)

หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากรายงาน

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C
- ห้องปฏิบัติการมีนโยบายไม่ใช้ตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0590526 วันที่ (Date) 11 พฤษภาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6905063 No. 6905064
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวบู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 พฤษภาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 พฤษภาคม 2569 - 11 พฤษภาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 พฤษภาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH v	-	7.2	7.3	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids √	mg/L	193	487	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids	mg/L	63.0 √	1.0	-	ไม่เกิน 40	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand	mg/L	32.0	3.0	-	ไม่เกิน 30	5 Days BOD Test, Azide Modification Method (5210 B)
Oil and Grease	mg/L	5.2	0.9	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen	mg/L	15.6	0.6	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	0.0	1.2 √	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด พ.ศ. 2567 (ประเภท ข)

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- √ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิรารัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0600526 วันที่ (Date) 11 พฤษภาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6905063 No. 6905064
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวยู มิลินส์ ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 พฤษภาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 พฤษภาคม 2569 - 11 พฤษภาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 พฤษภาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids	ml/L	0.7 ✓	0.0	-	-	Imhoff cone (2540 F)

หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ $25 \pm 5^\circ\text{C}$

- ✓ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายธรรณ นีรนันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์ญัติน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING

No.0090

รายงานหมายเลข (Report No.) 0570526 วันที่ (Date) 11 พฤษภาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6905061 No. 6905062
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิววู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงรรมฆ่ามา เลคคิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 พฤษภาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 พฤษภาคม 2569 - 11 พฤษภาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 พฤษภาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH v	-	6.6	6.7	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids	mg/L	190 ✓	647	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids	mg/L	52.0 ✓	2.5	-	ไม่เกิน 30	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand	mg/L	23.5	6.8	-	ไม่เกิน 20	5 Days BOD Test, Azide Modification Method (5210 B)
Oil and Grease	mg/L	1.2	0.6	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen	mg/L	31.7 ✓	0.7	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	1.4 ✓	0.0	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด พ.ศ. 2557 (ประเภท ก)

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- วัสดุการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0580526 วันที่ (Date) 11 พฤษภาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6905061 No. 6905062
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 พฤษภาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 พฤษภาคม 2569 - 11 พฤษภาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 พฤษภาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids	ml/L	4.0 ✓	0.0	-	-	Imhoff cone (2540 F)

หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ $25 \pm 5^\circ\text{C}$
- ✓ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ
- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิภารัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์ญัติน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834958-7 , (02) 8834274 Fax : (02) 8834958 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



รายงานหมายเลข (Report No.) 0590626 วันที่ (Date) 12 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6906048 No. 6906049
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวยู บิซิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 5 มิถุนายน 2569 - 12 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH v	-	6.6	6.2	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids v	mg/L	257	427	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids v	mg/L	28.0	50.0	-	ไม่เกิน 30	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand v	mg/L	23.8	23.0	-	ไม่เกิน 20	5 Days BOD Test, Azide Modification Method (6210 B)
Oil and Grease	mg/L	1.7	1.2	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen v	mg/L	30.1	21.1	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	1.3 v	0.0	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารประเภทและขนาด พ.ศ. 2567 (ประเภท ก)


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- v รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025:2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการเป็นไปตามไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราธิ์น)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์

- รายงานผลการทดสอบนี้ไม่รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700.
HVE CO. LTD. 603 Soi Jarunsnitwong 46 Jarunsnitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834958-7 , (02) 8834274 Fax : (02) 8834958 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090


รายงานหมายเลข (Report No.) 0600626 วันที่ (Date) 12 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6906048 No. 6906049
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 5 มิถุนายน 2569 - 12 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids √	ml/L	1.2	5.5	-	-	Imhoff cone (2540 F)

หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่ได้จากลูกค้า

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C
- ทุกรายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ
- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีซี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834958-7 , (02) 8834274 Fax : (02) 8834958 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ (ANALYSIS REPORT)



รายงานหมายเลข (Report No.) 0610626 วันที่ (Date) 12 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6906050 No. 6906051
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิววู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 5 มิถุนายน 2569 - 12 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

TESTING
No.0090

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
pH v	-	6.7	6.8	-	5.5 - 9.0	Electrometric Method, pH Meter (4500-H ⁺ B)
Total Dissolved Solids v	mg/L	213	267	-	ไม่เกิน 1,000	Glass Fiber Filter Disc, Dried at 180 °C (2540 C)
Total Suspended Solids v	mg/L	95.0	60.0	-	ไม่เกิน 40	Glass Fiber Filter Disc, Dried at 103 - 105 °C (2540 D)
Biochemical Oxygen Demand v	mg/L	39.0	55.0	-	ไม่เกิน 30	5 Days BOD Test, Azide Modification Method (5210 B)
Oil and Grease	mg/L	4.6	2.2	-	ไม่เกิน 20	Liquid-Liquid Partition Gravimetric Method (5520 B)
Total Kjeldahl Nitrogen	mg/L	11.0	16.9	-	ไม่เกิน 35	Macro Kjeldahl, Titrimetric Method (In-house method based on 4500-N _{org} B)
Sulfide	mg/L	2.9	0.1	-	ไม่เกิน 1.0	Titrate, Iodometric Method (4500-S ²⁻ F)

หมายเหตุ : ^{1/} ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด พ.ศ. 2557 (ประเภท ข)


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023


^c เป็นข้อมูลที่มาจากลูกค้า

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- วัสดุการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิภารัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์

- รายงานผลการทดสอบนี้ให้บริการเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางมด เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsnitwong 46 Jarunsnitwong Road Bangyeekean Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0620626 วันที่ (Date) 12 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำเข้า (Influent) น้ำออก (Effluent)
รหัสตัวอย่าง (Sample No.) No. 6906050 No. 6906051
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีดำ สีตะกอนสีน้ำตาล
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงนมชา มา เลควิ อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 5 มิถุนายน 2569 - 12 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)		MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำเข้า (Influent)	น้ำออก (Effluent)			
Settleable Solids ✓	ml/L	3.0	2.0	-	-	Imhoff cone (2540 F)

หมายเหตุ : ^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากการสุ่ม

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ✓ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025:2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด

ภาคผนวกที่ 3

เอกสารการนำส่งรายงานผลการปฏิบัติตามมาตรการป้องกัน
และแก้ไขผลกระทบสิ่งแวดล้อม และมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
ประจำเดือนกรกฎาคม-ธันวาคม 2568



shama
lakeview asoke

23 มกราคม 2569

เรื่อง ขอส่งรายงานการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม และมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม ครั้งที่ 2/2568 ประจำปีเดือนกรกฎาคม-ธันวาคม พ.ศ. 2568

เรียน อธิบดีกรมการปกครอง

- สิ่งที่ส่งมาด้วย 1. รายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบทางสิ่งแวดล้อม และมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม โครงการ Shama Lakeview Asoke ของบริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด ครั้งที่ 2/2568 ประจำปีเดือนกรกฎาคม-ธันวาคม พ.ศ. 2568 จำนวน 4 ฉบับ
2. แผ่นแม่เหล็กบันทึกข้อมูล จำนวน 4 แผ่น

ตามที่บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด ได้เปิดดำเนินการโครงการ Shama Lakeview Asoke ตั้งอยู่เลขที่ 41 ซอยสุขุมวิท 16 แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110 และได้ทำรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบทางสิ่งแวดล้อม และมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม ตามเงื่อนไขในการรายงานวิเคราะห์ผลกระทบสิ่งแวดล้อมเพื่อเสนอต่อหน่วยงาน ที่เกี่ยวข้อง ทั้งนี้บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด จึงขอส่งมอบรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบทางสิ่งแวดล้อม และมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อมครั้งที่ 2/2568 ประจำปีเดือนกรกฎาคม-ธันวาคม พ.ศ. 2568 จำนวน 4 ฉบับ และแผ่นแม่เหล็กบันทึกข้อมูล จำนวน 4 แผ่น เพื่อให้กรมการปกครอง นำรายงานส่งต่อสำนักงานเขตคลองเตย และสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและสิ่งแวดล้อมพิจารณาให้ความเห็นต่อไป

จึงเรียนมาเพื่อโปรดพิจารณาดำเนินการต่อไป

ขอแสดงความนับถือ

(นางสาวทิพย์รัตน์ แก้วกระแสร)

ผู้จัดการโรงแรม ชามาเลควิวอัสโก

บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด

ได้รับต้นฉบับแล้ว

วันที่ 27 ม.ค. 69

ผู้รับเอกสาร... สร. 2641111



23 มกราคม 2569

เรื่อง ขอส่งรายงานการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม และมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม ครั้งที่ 2/2568 ประจำปีเดือนกรกฎาคม-ธันวาคม พ.ศ. 2568

เรียน ผู้อำนวยการเขตคลองเตย

- สิ่งที่ส่งมาด้วย 1. ขอส่งรายงานการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม และมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม โครงการ Shama Lakeview Asoke ของบริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด ครั้งที่ 2/2568 ประจำปีเดือนกรกฎาคม-ธันวาคม พ.ศ. 2568 จำนวน 1 ฉบับ
2. แผ่นแม่เหล็กบันทึกข้อมูล จำนวน 1 แผ่น

ตามที่บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด ได้เปิดดำเนินการโครงการ Shama Lakeview Asoke ตั้งอยู่เลขที่ 41 ซอยสุขุมวิท 16 แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110 และได้ทำรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบทางสิ่งแวดล้อม และมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม ตามเงื่อนไขในการรายงานการประเมินผลกระทบสิ่งแวดล้อมเพื่อเสนอต่อหน่วยงาน ที่เกี่ยวข้อง ทั้งนี้บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด จึงขอส่งมอบรายงานผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบทางสิ่งแวดล้อม และมาตรการติดตามตรวจสอบคุณภาพสิ่งแวดล้อมครั้งที่ 2/2568 ประจำปีเดือนกรกฎาคม-ธันวาคม พ.ศ. 2568 จำนวน 1 ฉบับ และแผ่นแม่เหล็กบันทึกข้อมูล จำนวน 1 แผ่น เพื่อให้สำนักงานเขตคลองเตย พิจารณาให้ความเห็นต่อไป

จึงเรียนมาเพื่อโปรดพิจารณาดำเนินการต่อไป

ขอแสดงความนับถือ

(นางสาวทิพย์รัตน์ แก้วกระแสร์)

ผู้จัดการโรงแรม ชามาเลควิวอโศก

บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด

ผู้รับเอกสาร.....

30 ม.ค. 2569

ภาคผนวกที่ 4

แผนฉุกเฉิน

SAB Fire & Emergency Plan 2025

Fire Related Information

Fire Prevention and Contingency

The outbreak of a fire in a Shama lakeview asoke is a serious danger, which requires appropriate action in order to safeguard guests, Team Members and assets alike.

As indicated in the title of this dossier, a coherent fire plan must include prevention, which will minimize the chances of a fire erupting.

However, no amount of preparation may totally exclude a fire outbreak, and a contingency plan is necessary.

This document will therefore serve as a guide to establish the property's fire prevention and contingency planning

Information

General

Fire is a serious hazard which requires quick and decisive actions to combat it. In order to minimize the chances of a fire erupting and adequately fighting it, a basic understanding of the different matters related to fire and methods to extinguish it is therefore necessary.

Causes of fire

Fires occur for several reasons, either accidental or intentional. According to research, the major causes of hotel fires are the following:

- Human error (72% of hotel fires), which are induced by a Team Member or a guest's actions
- Equipment failure (15%)
- Electrical (9%)
- Arson (4%)

Information

Types of fire and extinguishers

There are six different classes of fire, which require different methods for extinguishing them

CLASS	FUEL/HEAT SOURCE	IDEOGRAM	EXTINGUISHER
A	Solid materials of an organic nature (e.g. wood, paper, cloth, etc.)		- Water hose - Dry chemical extinguisher (not to be used in a closed area) - Carbone dioxide extinguisher - Halon extinguisher
B	Liquids (e.g. petrol, diesel, paint, etc.)		- Dry chemical extinguisher (not to be used in a closed area) - Carbone dioxide extinguisher - Halon extinguisher
C	Flammable gases		- Dry chemical extinguisher (not to be used in a closed area) - Carbone dioxide extinguisher - Halon extinguisher
D	Flammable metals (e.g. magnesium, aluminium, titanium, etc.)		Dry powder extinguisher
E	Electric equipment		Halon extinguisher
F	Cooking oil or fat	NONE	Wet chemical extinguisher

Information

Types of fire alarms

Several systems may be implemented to warn guests and/or Team Members of the breakout of a fire in the hotel:

- Smoke detectors
- Heat detectors
- Manual stations
- Sprinkler flows
- Oral alarm

HOW TO USE A FIRE EXTINGUISHER

Remember the Phrase **PASS**



Types of fire alarms

Smoke detectors

- Provide effective and immediate warning to occupants of the building in case of problems or hazards
- Often the first warning of a fire outbreak
- Linked to the main fire alarm control room by an uninterruptible power supply system



Heat detectors

- Provide effective and immediate warning to occupants of the building in case of problems or hazards
- Linked to the main fire alarm control room by an uninterruptible power supply system



Manual stations

- Need to be physically activated in the case of a fire outbreak



Sprinkler flows

- Usually charged with water and linked to a master pumping system and water tanks
- Linked to the main fire alarm control room



Chapter 1

Actions to be taken in the event of finding a fire or other emergencies— number to be called.



Instructions for person discover fire

1. Respond to all fire alarms as if they are real. Hesitating for even a moment can have devastating consequences.
2. Control the spread of smoke by closing all doors, including laundry chutes
3. Clear the corridors by removing all housekeeping, maintenance, and service carts. Place them in service areas or vacant rooms.
4. Help evacuate the area. Provide aid to guests with disabilities. Assist guests with directions to the nearest exits.
5. Implement departmental procedures.
6. Meet at the Assembly Area.





Fire action






1. Operate nearest fire alarm.

2. Leave building by nearest exit.

3. Report to assembly point.

Behind of Tower A

Do not use lifts



เมื่อพบเหตุเพลิงไหม้






1. กดปุ่มแจ้งเหตุฉุกเฉินใกล้ที่สุด และโทรแจ้งหมายเลข "0" ทันที

2. รีบไปจุดรวมพลเพื่อความปลอดภัย โดยใช้บันไดหนีไฟที่ใกล้ที่สุด

3. จุดรวมพลของโรงแรมอยู่ที่

ด้านหลังตึก A

ห้ามใช้ลิฟต์เด็ดขาด

Security

1. Rush to the fire area.
2. Having the security guards to control the entrance of hotel in order to prevent the external persons get into the premises.
 - Entrance exit for employees
 - Front gate at guard house area
 - Hotel entrance at Lobby Area.
3. Arrange Security Guards to control the road at entrance exit area of the hotel in order to stop any vehicles getting into the hotel premises except fire trucks.
4. Coordinate with police fire truck when arriving to the hotel.
5. Take care of fire trucks to the right parking space.

THE PROCEDURE FOR RESPONSIBLE DUTIES OF VARIOUS SECTIONS

Engineering

1. Rush to the accident area.
2. Set up all elevators to station at ground floor after helping the employees.
3. Turn off all electrical switches, which connected to the accident area.
4. Inspect the operation of fire elevator.
5. Be sure all employees have already evacuated from the area.
6. Coordinate with police fire brigade department for building structure.


Accounting

1. Keep all the important documents.
2. Keep all money, checks and proprietary documents in the safe.
3. Turn off all electrical switches, remove all electrical plugs of office equipment from the outlets.
4. Close all doors and windows.
5. Rush to the assembly point.

Housekeeping

1. Check master keys including all documents in the safe place.
2. Evacuate all guests from the rooms by knocking the door starting from the highest floor.
3. Inform all guests to keep the keys with themselves and prepare wet handkerchief for helping breath.
4. Open the room for inspection if no answer when knocking the door.
5. Show the way and inform guests going to the nearest fire escape.
6. Tell everybody not to use the elevator, if necessary they must use the fire lift.
8. Hang sign "CHECKED" at all doors and windows that guests have already been evacuated.
9. Turn off the switches of all machines.
1. Turn off all electrical switches including computers and keep all diskettes in the safe place.
8. Keep all-important documents.
9. Rush to the assembly point

Emergency flow chart



Human Resources

1. Keep all-important documents.
2. Turn off all electrical switches and appliances at staff canteen.
3. Prepare all employees name list.
4. Be sure all remained employees have already been evacuated.
5. Close and lock all doors.
6. Timekeeper has to carry First Aids Boxes for helping employees.
7. Rush to the assembly point.
8. Check the name of all employees who work on that day. (repeat for every 15 minutes)
9. Make names' list of the loss persons to the police fire brigade for scorching.
10. Review the names' list of all guests.

GM's Office/Sales/ Executive Office

1. Keep all-important documents.
2. Turn off all electrical switches and office equipment.
3. Close and lock all doors.

Chapter 2 Training plan

Month	Subject	Who	Fire Life & Safety Training	Type
Jan	Fire, Life Safety	ERT & EST (Morning Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill
Feb	Fire, Life Safety	ERT & EST (Afternoon Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill
	Fire, Life Safety	ALL TMs	2 hours training session for all TMs on Fire Prevention, What to do in the event of a fire, OHG Emergency Codes & Evacuation Drills and Guest Requiring Assistance	Lecture & Test
Mar	Fire, Life Safety	ERT & EST (Night Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill
Apr	Fire, Life Safety	Eng/Sec/ERT/MCOs	Elevator Entrapment Training	Practical Drill
	Fire, Life Safety	ERT & EST (Morning Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill
May	Fire, Life Safety	ERT & EST (Afternoon Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill
	Fire, Life Safety	Sec & Front Office TMs	Guest Requiring Evacuation Assistance Drill	Practical Drill
Jun	Fire, Life Safety	ERT & EST (Night Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill
Jul	Fire, Life Safety	ERT & EST (Morning Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill
	Fire, Life Safety	All TMs	Fire Prevention Campaign	Exhibits and Posters
Aug	Fire, Life Safety	ERT & EST (Afternoon Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill
	Fire, Life Safety	Laundry TMs	Specialist Laundry Fire Training	Practical Drill
Sep	Fire, Life Safety	ERT & EST (Night Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill
	Fire, Life Safety	Engineering TMs	Specialist Plant Room Fire Training	Practical Drill
Oct	Fire, Life Safety	ERT & EST (Morning Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill
	Fire, Life Safety	Kitchen TMs	Specialist Plant Room Fire Training	Practical Drill
Nov	Fire, Life Safety	ERT & EST (Afternoon Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill
	Fire, Life Safety	Eng/Sec/ERT/MCOs	Elevator Entrapment Training	Practical Drill
Dec	Fire, Life Safety	ERT & EST (Night Shift)	Silent Reaction Drill including MCO as Fire Commander	Practical Drill

Information

Escape routes

1. A clear and uninterrupted exit to a safe ground level exterior location is mandatory throughout the hotel.
2. Escape routes must lead the guests or Team Members through a protected and smoke insulated horizontal exit zone (e.g. corridor, etc.), to a protected vertical zone (e.g. fire escape staircase, etc.), before finally leading to open air.
3. The escape routes must be direct and offer protection, as well as clear signage and segregation from potentially dangerous areas (e.g. kitchens, machine rooms, etc.).
4. Escape routes must never be obstructed by objects

Chapter 3 Escape routes



Fire escape staircases

1. Fire doors must be installed at every fire escape staircase entrance/exit, in order to make the area sealable.
2. The escape staircases must be pressurized and if possible without windows or openings other than doors.



TOWER A

TOWER B



Chapter 4

ERT&EST Organization chart


Emergency Response Team (ERT)		
Morning Shift	Afternoon Shift	Night Shift
Engineering	Engineering	Engineering
Engineering	Engineering	Engineering
Security	Security	Security

ERT + EST	
Emergency Response Team : 3 man 24/7 (Department)	Emergency Support Team : 3 man 24/7 (Department)
Engineering	Engineering
Engineering	Security
Security	House Man/Concierge or Bell Man

Emergency Support Team (EST)		
Morning Shift	Afternoon Shift	Night Shift
Engineering	House Man	House Man
Engineering	Concierge/Bell	Concierge/Bell
Security	Security	Security

FIRST AIDERS		
Morning Shift	Afternoon Shift	Night Shift
1 person	1 person	1 person

shama lakeview asoke





ONYX EMERGENCY CODES	
Code 1 (Bomb Threat)	BOMB THREAT: Any incident or finding that leads to the suspicion that there may be an explosive device in the property. P-SEC-01-001
Code 2 (Fire)	FIRE: Any incident or finding that leads to the suspicion that there may be a fire in the property. P-SEC-01-002
Code 3 (Medical Emergency)	MEDICAL EMERGENCY: A person requiring immediate medical assistance. Only First Aider and ERT will immediately attend. P-SEC-01-003
Code Bravo (Bomb Threat)	BOMB THREAT: Any incident or finding that leads to the suspicion that there may be an explosive device in the property. P-SEC-01-001
Code Delta (Intruder)	INTRUDER (DEATH): An observed person's dangerous threat to the property. P-SEC-01-004
Code Echo (Earthquake)	EARTHQUAKE: Once earthquake occurs, EMERGENCY RESPONSE TEAM (ERT) shall prepare for next step according to P-SEC-01-005
Code Mike (Medical Emergency)	MEDICAL EMERGENCY: A person requiring immediate medical assistance. Only First Aider and ERT will immediately attend. P-SEC-01-003
Code Red (Intruder)	ARMED INTRUDER: There is a person with a weapon in the building.
Code Sierra (Shelter Station Activation)	SHELTER STATION ACTIVATION: There is a physical danger to occupants but the senior manager on duty receives a warning that may not be the safest option. P-SEC-01-006

shama lakeview asoke



Chapter 5

Evacuation Assemble points



Chapter 6

Department in the event of an Evacuation

Action Plan	
Front Office (Coordinating Team)	
	Procedure
1	When received the fire alarm they responds immediately or not and what time?
2	They inform ERT by "CODE 1" and also the location or not?
3	They bring an "Emergency Card" to the scence or not?
4	When they received "CODE 2" then they call to all head departments or not?
5	When they received "CODE 3" from ERT+EST then they call to ask for approval from GM or not?
6	They are prepared 2 teams between Internal Team and External Team or not?
7	They inform to ERT&EST and all departments when CODE 3 has been approved by GM?
8	Dose the External Team immediete contact Fire Station and Hospital and also give them a correct details?
9	How do they inform the guests about the fire alarm *** Information provided to the guests is "Security Team is now checking on Fire Alarm, please wait in Lobby area Thank you."
10	Dose the internal team prepare all the information for evacuation or not? *Guests name list *Back up Data *Duty Roster of the employees *The important data/document of each department *First Aid Box
11	Is the evacuation taken seriously?



Engineering (Fire Fighting Team)	
	Procedure
1	What time they receive "CODE 1"?
2	When received "CODE 1" ERT have arrived the scence within 1 minute or not (if not how?)
3	Dose ERT carry the fire extinguisher to the scence or not?
4	If there is a real fire occurred, ERT informs "CODE 2" to FO team and EST or not?
5	ERT inform to EST while "CODE 2" for fire hose assistant?
6	Dose EST have full equiped and take action immediately or not?
7	Do they use it correctly and properly? 1. Fire extinguisher 2. Fire hose 3. Fire Suit, Axe, Prevention Items
8	When the fire is out of control, ERT+EST inform FO Team for approve "CODE 3" from GM or not?
9	What time is the general alarm?
10	They do escort Fire fighting department to the scence with Building Plan or not?
11	How do they coordinating between ERT+EST and FO Team about fire man?
12	How do they coordinating between ERT+EST and Fireman department?
13	Do they take Building Plan to coordinate with Fireman?
14	How are they organized "Fire Pump Room" and "MDB". Is it open and ready to operate?
15	Do they bring Building Plan to the assembly Point?
16	Do they check the Team member name list when they reach at Assembly Point and then pass it to Check-Team?
17	Is the evacuation taken seriously?



Housekeeping (Evacuation Team)	
	Procedure
1	They have acknowledge "CODE 2" or not and what time?
2	They have acknowledge "CODE 3" or not and what time?
3	When received "CODE 3" HK Centre Team informs to Team Leader and all Room Attendant for checking guest room or not?
4	When received "CODE 3" HK Centre Team informs to all Room Attendant for evacuation?
5	Do they checking all guest room and hanging Check-Sign on the door or not?
6	Do they take necessary evacuation items such flashlight, cloth and water?
7	Are there anything blocked Fire Exits?
8	Do they check the guest name list when they reach at Assembly Point and then pass it to check team?
9	Do they check the team member name list when they reach at Assembly Point and then pass it to check team or not ?
10	In case missing people, the Searching Team take action immediately or not ?
11	Is the evacuation taken seriously?
Sales and Marking Team (First Aid Team)	
	Procedure
1	Why they have acknowledge for "CODE 2"?
2	When they have receives "CODE 3" for the evacuation?
3	Do they bring First Aid items to the Assembly Point?
4	Do they collect and bring an important documents to the Assembly Point or not?
5	Do they have first aid correct or not ?
6	Do they check the Team member name list when reach at Assembly Point and then pass it to Check Team or not ?
7	Is the evacuation taken seriously?



Human Resource & Accounting (Check Team)	
	Procedure
1	They have acknowledge CODE2 or not and what time?
2	They have acknowledge CODE3 or not and what time?
3	They have prepare Guest name list or not?
4	They have prepare Team Member name list or not?
5	They do quickly and complete check all name list or not?
6	Do they have prepare an important documentation
7	Is the evacuation taken seriously?
Security & Concierge(Security Team)	
	Procedure
Security Team	
1	When received CODE3 they have prepare Department Signage at the Assembly Point
2	They have prepare parking space for Fire Department and control traffic facilities or not?
3	Control the Assembly Point stay in peace or not?
4	Standby at lobby for escort the guest to the Assembly point
5	Bring the Wheel chair to pick up disable guest by using the Fire Man Lift



Chapter 7

Maintenance & inspect of fire fighting equipment & system



FLSDS 05 Record of the monthly inspection of the Fire Fighting Team equipment									
Item	Description	Unit	Sub-Inspector	Inspector	Sub-Inspector	Inspector	Sub-Inspector	Inspector	Remark
1.	Fire pump / ปั๊มดับเพลิง	1							
2.	Rescue equipment / อุปกรณ์กู้ภัย	1							
3.	Water pump / ปั๊มน้ำ	2							
4.	Water hose / สายน้ำ	2							
5.	Generator / เครื่องปั่นไฟ	1							
6.	Exhaustion pump / ปั๊มดูดน้ำ	2							
7.	Pressure / ความดัน	3							
8.	Fire Fighting helmet / หมวกดับเพลิง	1							
9.	Fire hose / สายน้ำ	2							

Area Hotel General Manager-Shama Bangkok

Director Operations

Human resource Department

Housekeeping Department

Engineering Department

Sale & Marketing Department

IT Manager

Front office Department

Security Department

Finance Department

THANK YOU



ภาคผนวกที่ 5

เอกสารตรวจสอบระบบท่อน้ำใช้

SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#624570

 Status Completed	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	 Due Date 01/01/2026	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date01/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Suphakon Tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Man op

02/01/2026 08:48 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

Wrench

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#626475

📌

Status

Completed

🏠

Asset

ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

📅

Due Date

02/01/2026

🏠

Location

SAB (Shama Lakeview Asoke Bangkok)

👤

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date02/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Suphakon Tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#627968

 Status Completed	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	 Due Date 03/01/2026	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date03/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status


Normal

9 Inspection By (Name & Position)

Natthaphon Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB

#629476

Status Completed	Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	Due Date 04/01/2026	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date04/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Natthaphon Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#631131

 Status Completed	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	 Due Date 05/01/2026	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date05/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

06/01/2026 07:48 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

-

#633246

📌 Status

Completed

🏠 Asset

ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

📅 Due Date

06/01/2026

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date06/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#634560

 Status	 Asset	 Due Date	 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	07/01/2026	SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date07/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Manop

08/01/2026 10:05 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#635865

📌 Status

Completed

🏠 Asset

ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

📅 Due Date

08/01/2026

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date01/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

https://app.limblecmms.com/completedTasks/71719?modalStack=pop-bulk-tasks

22/93

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#638782

 Status	 Asset	 Due Date	 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	09/01/2026	SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date09/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status


Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai
10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





SAB (Shama Lakeview Asoke Bangkok)

**ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -**
SAB

#640272

 Status Completed	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	 Due Date 10/01/2026	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date10/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#642466

 Status	 Asset	 Due Date	 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	11/01/2026	SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date11/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

11/01/2026 20:09 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB

-

#643620

📌 Status

Completed

🏠 Asset

ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

📅 Due Date

12/01/2026

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date12/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#645731

 Status	 Asset	 Due Date	 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	13/01/2026	SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date13/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

13/01/2026 21:22 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#646958

📌 Status

Completed

🏠 Asset

ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

📅 Due Date

14/01/2026

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date14/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

https://app.limblecmms.com/completedTasks/71719?modalStack=pop-bulk-tasks

40/93

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4


Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#648451

 Status Completed	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	 Due Date 15/01/2026	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date15/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#650422

 Status Completed	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	 Due Date 16/01/2026	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date16/01/2026
- 2 SAB-PWP-001
- 1 Function Mode

Manual / Auto
- 1 Overload Status

No Overload
- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Normal
- 3 SAB-PWP-002
- 1 Function Mode

Manual / Auto
- 1 Overload Status

No Overload
- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Normal
- 4 SAB-PWP-003
- 1 Function Mode

Manual / Auto
- 1 Overload Status

No Overload
- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Normal
- 5 SAB-PWP-004

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4


Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#651938

 Status	 Asset	 Due Date	 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	17/01/2026	SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date17/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

17/01/2026 08:04 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#653408

📌 Status

Completed

🏠 Asset

ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

📅 Due Date

18/01/2026

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date18/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

https://app.limblecmms.com/completedTasks/71719?modalStack=pop-bulk-tasks

52/93

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#654585

 Status	 Asset	 Due Date	 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	19/01/2026	SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date19/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB

-
#655872

📌 Status Completed	🏠 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	📅 Due Date 20/01/2026	🏠 Location SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date20/01/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#657422

 Status	 Asset	 Due Date	 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	21/01/2026	SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date21/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status


Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB

#658913

Status Completed	Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	Due Date 22/01/2026	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date22/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4


Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#660195

 Status Completed	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	 Due Date 23/01/2026	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date23/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status


Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB

#661736

Status Completed	Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	Due Date 24/01/2026	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date24/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#662942

 Status Completed	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	 Due Date 25/01/2026	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date25/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

26/01/2026 07:55 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#664140

📌 Status

Completed

🏠 Asset

ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

📅 Due Date

26/01/2026

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date26/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

https://app.limblecmms.com/completedTasks/71719?modalStack=pop-bulk-tasks

76/93

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#665092

 Status Completed	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	 Due Date 27/01/2026	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date27/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

28/01/2026 21:22 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#666400

📌 Status

Completed

🏠 Asset

ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

📅 Due Date

28/01/2026

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date28/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

https://app.limblecmms.com/completedTasks/71719?modalStack=pop-bulk-tasks

82/93

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#667760

 Status	 Asset	 Due Date	 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	29/01/2026	SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date29/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

31/01/2026 15:30 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

-

#670781

📌 Status

Completed

🏠 Asset

ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

📅 Due Date

30/01/2026

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date30/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4



Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -

SAB

#671972

 Status Completed	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	 Due Date 31/01/2026	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date31/01/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

31/01/2026 17:00 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #673569

Status Completed	Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	Due Date 01/02/2026	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date01/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB #675351

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
02/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date02/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





🔑 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB #676794

🔔 Status Completed	🔧 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	📅 Due Date 03/02/2026	🏠 Location SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1

Inspection Date

03/02/2026

2

SAB-PWP-001

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

3

SAB-PWP-002

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

4

SAB-PWP-003

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

https://app.limblecmms.com/completedTasks/71719?modalStack=pop-bulk-tasks

7/84

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking



4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB #678613

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
04/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date04/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





🔑 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #680303

📌 Status Completed	🔧 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	📅 Due Date 05/02/2026	🏠 Location SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date05/02/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking



4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - -
SAB #682273

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
06/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date06/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status


Normal

9 Inspection By (Name & Position)

Nitinrun&Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





🔑 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB #683653

🔔 Status Completed	🔧 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	📅 Due Date 07/02/2026	🏠 Location SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date07/02/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

https://app.limblecmms.com/completedTasks/71719?modalStack=pop-bulk-tasks

19/84

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking



4 Overall Status

Normal

9 Inspection By (Name & Position)

Nitnirun&Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB #685544

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
08/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date08/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Nitnirun&Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

08/02/2026 22:28 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #688961

Status Completed	Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	Due Date 09/02/2026	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date09/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB #690317

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
10/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date10/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status


Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





SAB (Shama Lakeview Asoke Bangkok)



🔑 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #691772

📌 Status Completed	🔧 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	📅 Due Date 11/02/2026	🏠 Location SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date11/02/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

https://app.limblecmms.com/completedTasks/71719?modalStack=pop-bulk-tasks

31/84

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking



4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB #693181

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
12/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date12/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

12/02/2026 17:42 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #695526

Status Completed	Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	Due Date 13/02/2026	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date13/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Nitnirun&Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - -
SAB #697377

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
14/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date14/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status


Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





🔑 **ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -** **SAB** **#702875**

🔔 Status	🔧 Asset	📅 Due Date	🏠 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	15/02/2026	SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date

15/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking



4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB #704879

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
16/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date16/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

16/02/2026 21:55 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #706118

Status	Asset	Due Date	Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	17/02/2026	SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date17/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking



4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB #707680

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
18/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date18/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status


Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





🔑 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #709158

🔔 Status	🔧 Asset	📅 Due Date	🏠 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	19/02/2026	SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date

19/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking



4 Overall Status

Normal

9 Inspection By (Name & Position)

Nitnirun&Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB #710431

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
20/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date20/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status


Normal

9 Inspection By (Name & Position)

Nitinrun&Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved





🔑 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #711936

🔔 Status	🔧 Asset	📅 Due Date	🏠 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	21/02/2026	SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date21/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - -
SAB #713440

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
22/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date22/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

24/02/2026 18:39 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #714749

Status Completed	Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	Due Date 23/02/2026	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date23/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking



4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB #715809

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
24/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date24/02/2026

2 SAB-PWP-001

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

3 SAB-PWP-002

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

4 SAB-PWP-003

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

5 SAB-PWP-004

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

6 SAB-PWP-005

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

7 SAB-PWP-005

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

8 SAB-PWP-006

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration


3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

24/02/2026 17:57 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #717275

Status Completed	Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	Due Date 25/02/2026	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date25/02/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking



4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB #719199

Status
Completed

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Due Date
26/02/2026

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date26/02/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

https://app.limblecmms.com/completedTasks/71719?modalStack=pop-bulk-tasks

76/84

7/3/69 09:58

app.limblecmms.com/completedTasks/71719?modalStack=pop-bulk-tasks

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal


9 Inspection By (Name & Position)

Nitinirun&Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

https://app.limblecmms.com/completedTasks/71719?modalStack=pop-bulk-tasks

77/84



🔑 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #720334

🔔 Status	🔧 Asset	📅 Due Date	🏠 Location
Completed	ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering	27/02/2026	SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering			

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date27/02/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking



4 Overall Status

Normal

9 Inspection By (Name & Position)

Nitnirun&Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - -
SAB #722620

📌 **Status**
Completed

🏠 **Asset**
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

📅 **Due Date**
28/02/2026

🏠 **Location**
SAB (Shama Lakeview Asoke Bangkok)

👤 **Completed By**
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date28/02/2026

2 SAB-PWP-001

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

3 SAB-PWP-002

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

4 SAB-PWP-003

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

5 SAB-PWP-004

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

6 SAB-PWP-005

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

7 SAB-PWP-005

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration

3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

8 SAB-PWP-006

1 Function Mode
Manual / Auto

1 Overload Status
No Overload

2 Vibration Status
No Vibration


3 Leaking Status
Normal / No Leaking

4 Overall Status
Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



Wisit

28/02/2026 19:12 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

ONYX

Engineering Group

🔧

ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #725050

🔔 Status
Completed

📅 Due Date
01/03/2026

👤 Completed By
SAB (Shama Lakeview
Asoke Bangkok) 1.Manager
Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date01/03/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Nitnirun&Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

02/03/2026 08:51 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

02/03/2026 08:51 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2/74

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

3/74



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #726891

Status
Completed

Due Date
02/03/2026

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date02/03/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Normal
- 6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 9 Inspection By (Name & Position)

Boonyarit
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

02/03/2026 11:32 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #728453

Status Completed	Due Date 03/03/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date03/03/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Boonyarit

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

06/03/2026 12:54 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering



TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

8/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

06/03/2026 12:54 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

9/74



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #729882

Status
Completed

Due Date
04/03/2026

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date04/03/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Normal
- 6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 9 Inspection By (Name & Position)

Boonyarit/tech
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

06/03/2026 12:59 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #731967

Status Completed	Due Date 05/03/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date05/03/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Boonyarit/tech

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

06/03/2026 12:50 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering



TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

14/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

06/03/2026 12:50 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

15/74



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #734065

Status
Completed

Due Date
06/03/2026

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date06/03/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Normal
- 6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration


3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 9 Inspection By (Name & Position)

boonyarit
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #735690

Status Completed	Due Date 07/03/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date07/03/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking


4

Overall Status

Normal

9 Inspection By (Name & Position)
Wong/Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT

07/03/2026 15:56 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #737377


Status Completed	Due Date 08/03/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date08/03/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload

- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Wong/Technician
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #740456

Status Completed	Due Date 09/03/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
---------------------	------------------------	--

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date09/03/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Boonyarit

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

09/03/2026 20:44 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering



TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

26/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

09/03/2026 20:44 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

27/74



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #742479

Status
Completed

Due Date
10/03/2026

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date10/03/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Normal
- 6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration


3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 9 Inspection By (Name & Position)

Boonyarit
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #744743

Status Completed	Due Date 11/03/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date11/03/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Boonyarit

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

12/03/2026 16:42 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering



TIME SPENT

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

12/03/2026 16:42 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #746230

Status
Completed

Due Date
12/03/2026

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date12/03/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Normal
- 6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration


3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 9 Inspection By (Name & Position)

Boonyarit
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #748297

Status Completed	Due Date 13/03/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
---------------------	------------------------	--

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date13/03/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Boonyarit

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

13/03/2026 11:33 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering



TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

38/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

13/03/2026 11:33 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

39/74

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #749659

Status
Completed

Due Date
14/03/2026

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date14/03/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Normal
- 6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 9 Inspection By (Name & Position)

0
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

14/03/2026 11:08 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #751137

Status
Completed

Due Date
15/03/2026

Completed By
SAB (Shama Lakeview
Asoke Bangkok) 1.Manager
Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date15/03/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Wong/Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

15/03/2026 22:09 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Wisit

TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

44/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

15/03/2026 22:09 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

45/74



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #753098

Status
Completed

Due Date
16/03/2026

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date16/03/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

46/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)
Wong/Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

47/74



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #754956

Status Completed	Due Date 17/03/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
---------------------	------------------------	--

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date17/03/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Wong/Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

18/03/2026 13:15 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering



TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

50/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

18/03/2026 13:15 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

51/74



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #756675

 **Status**
Completed

 **Due Date**
18/03/2026

 **Completed By**
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date18/03/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Boonyarit

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

18/03/2026 13:23 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #757874

Status Completed	Due Date 19/03/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date19/03/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

54/74

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

55/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Off

1 Reason

0

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Boonyarit

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

20/03/2026 10:02 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

TIME SPENT

20/03/2026 10:02 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

56/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #759272

🔔 Status

Completed

📅 Due Date

20/03/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date20/03/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

57/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Boonyarit

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

20/03/2026 10:22 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Wisit

TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

58/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

20/03/2026 10:22 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

59/74



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #760622

Status
Completed

Due Date
21/03/2026

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date21/03/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

60/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)
Wong/Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

61/74



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #762130

Status Completed	Due Date 22/03/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date22/03/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Wong/Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

22/03/2026 09:57 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Wisit

TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

64/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

22/03/2026 09:57 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

65/74



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #763320

Status
Completed

Due Date
23/03/2026

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date23/03/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload

- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Boonyarit
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

23/03/2026 22:32 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #764679

Status Completed	Due Date 24/03/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
---------------------	------------------------	--

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date24/03/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Boonyarit

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

24/03/2026 21:46 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

70/74

3/26/26, 10:44 AM

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

24/03/2026 21:46 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

71/74

 **ONYX**
Engineering Standard

SAB (Shama Lakeview Asoke Bangkok)

 **ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #767043**

 **Status**
Completed

 **Due Date**
26/03/2026

 **Completed By**
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date26/03/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Normal
- 6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal
- 9 Inspection By (Name & Position)

Boonyarit
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



26/03/2026 09:10 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

TIME SPENT



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #775808

Status Completed	Due Date 01/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
---------------------	------------------------	--

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date01/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Naithaphon Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

02/04/2026 17:23 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

2/90

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

02/04/2026 17:23 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 01/04/2026 03:18

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 01/04/2026 07:11

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 01/04/2026 07:11

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 01/04/2026 07:12

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 02/04/2026 17:23

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 02/04/2026 17:23

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

3/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #778033

Status Completed	Due Date 02/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---


DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date02/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Naithaphon Technician*
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

02/04/2026 17:27 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 02/04/2026 02:35

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 02/04/2026 06:45

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 02/04/2026 06:46

Approval approved.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 02/04/2026 17:27

This task has been completed.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 02/04/2026 17:27

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

Engineering

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #779632

🔔 Status

Completed

📅 Due Date

03/04/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date03/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Suphakon

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

03/04/2026 20:26 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

8/90

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

03/04/2026 20:26 - 0 hr and 15 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 03/04/2026 03:49

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 03/04/2026 16:44

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 03/04/2026 16:47

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 03/04/2026 20:26

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 03/04/2026 20:27

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

9/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB - #781184

Status Completed	Due Date 04/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date04/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Suphakon
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

05/04/2026 20:59 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 04/04/2026 03:22

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 04/04/2026 08:06

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 04/04/2026 08:09

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 05/04/2026 20:59

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 05/04/2026 20:59

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

Engineering

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #783027

🔔 Status

Completed

📅 Due Date

05/04/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date05/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Suphakon

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

05/04/2026 21:06 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

14/90

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

05/04/2026 21:06 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 05/04/2026 03:41

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 05/04/2026 09:37

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 05/04/2026 09:38

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 05/04/2026 21:06

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 05/04/2026 21:06

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

15/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #785033

Status Completed	Due Date 06/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date06/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Naithaphon Technician*
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

08/04/2026 07:53 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 06/04/2026 03:23

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 06/04/2026 06:47

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 06/04/2026 06:48

Approval approved.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 08/04/2026 07:53

This task has been completed.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 08/04/2026 07:53

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

Engineering

SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #786502

Status

Completed

Due Date

07/04/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date07/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Naithaphon Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

08/04/2026 08:08 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

20/90

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

08/04/2026 08:08 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 07/04/2026 03:37

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 07/04/2026 06:47
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 07/04/2026 06:48
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 08/04/2026 08:08
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 08/04/2026 08:08

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

21/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB #787883

Status Completed	Due Date 08/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---


DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date08/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Naithaphon Technician*
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

08/04/2026 08:21 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 08/04/2026 03:02

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 08/04/2026 06:46

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 08/04/2026 06:46

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 08/04/2026 06:47

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 08/04/2026 08:20

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 08/04/2026 08:21

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #790767

Status

Completed

Due Date

09/04/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date09/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Suphakon

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

09/04/2026 19:46 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

26/90

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

09/04/2026 19:46 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 09/04/2026 03:46

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 09/04/2026 15:34

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 09/04/2026 15:35

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 09/04/2026 19:46

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 09/04/2026 19:46

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

27/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB - #793019

Status Completed	Due Date 10/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---


DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date10/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Suphakon
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

11/04/2026 10:33 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 10/04/2026 02:40

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 11/04/2026 06:51

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 11/04/2026 06:52

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 11/04/2026 10:33

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 11/04/2026 10:33

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

Engineering Group

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #794501

🔔 Status

Completed

📅 Due Date

11/04/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date

11/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Suphakon

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

12/04/2026 16:03 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

32/90

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

12/04/2026 16:03 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 11/04/2026 03:25

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 11/04/2026 16:44

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 11/04/2026 16:45

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 12/04/2026 16:03

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 12/04/2026 16:03

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

33/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #795736

Status Completed	Due Date 12/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---


DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date12/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Suphakon Tech
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

12/04/2026 16:05 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 12/04/2026 02:12

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 12/04/2026 10:44

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 12/04/2026 10:46

Approval approved.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 12/04/2026 16:05

This task has been completed.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 12/04/2026 16:05

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

Engineering Group

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #798004

🔔 Status

Completed

📅 Due Date

13/04/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date13/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Naithaphon Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

13/04/2026 12:13 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

38/90

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

13/04/2026 12:13 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 13/04/2026 03:36

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 13/04/2026 06:41

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 13/04/2026 06:41

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 13/04/2026 06:42

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 13/04/2026 12:13

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 13/04/2026 12:13

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

39/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB #799317

Status Completed	Due Date 14/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---


DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date14/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Naithaphon Technician*
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

14/04/2026 11:26 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 14/04/2026 03:06

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 14/04/2026 06:58

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 14/04/2026 06:58

Approval approved.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 14/04/2026 11:26

This task has been completed.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 14/04/2026 11:26

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

Engineering Group

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #800998

🔔 Status

Completed

📅 Due Date

15/04/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date15/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Suphakon

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

15/04/2026 18:40 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

44/90

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

15/04/2026 18:40 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 15/04/2026 03:11

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 15/04/2026 14:05
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 15/04/2026 14:07
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/04/2026 18:40
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/04/2026 18:40

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

45/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #803191

Status Completed	Due Date 16/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date16/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Suphakon
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

17/04/2026 09:00 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 16/04/2026 03:46

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 16/04/2026 21:33

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 16/04/2026 21:34

Approval approved.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 17/04/2026 09:00

This task has been completed.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 17/04/2026 09:00

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

Engineering Group

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #804495

🔔 Status

Completed

📅 Due Date

17/04/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date17/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Naithaphon Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

17/04/2026 08:48 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

17/04/2026 08:49 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 17/04/2026 03:46

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 17/04/2026 06:56

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 17/04/2026 06:57

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 17/04/2026 08:48

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 17/04/2026 08:49

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

50/90

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

51/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection -
SAB - #805890

Status Completed	Due Date 18/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---


DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date18/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Naithaphon Technician*
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

19/04/2026 13:18 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 18/04/2026 03:32

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 18/04/2026 06:43

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 18/04/2026 06:44

Approval approved.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 19/04/2026 13:18

This task has been completed.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 19/04/2026 13:18

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #807052

Status

Completed

Due Date

19/04/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date19/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Naithaphon Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

19/04/2026 13:24 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

19/04/2026 13:24 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 19/04/2026 03:35

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 19/04/2026 06:42

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 19/04/2026 06:43

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 19/04/2026 13:24

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 19/04/2026 13:24



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #808315

Status Completed	Due Date 20/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---


DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date20/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Naitthaphon Technician
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

21/04/2026 08:26 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 20/04/2026 03:28

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 20/04/2026 07:06

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 20/04/2026 07:06

Approval approved.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 21/04/2026 08:26

This task has been completed.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 21/04/2026 08:26

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

Engineering

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #809784

🔔 Status

Completed

📅 Due Date

21/04/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date21/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Naithaphon Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

23/04/2026 09:07 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

23/04/2026 09:07 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 21/04/2026 02:36

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 21/04/2026 06:59

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 21/04/2026 07:00

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 23/04/2026 09:07

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 23/04/2026 09:07

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks62/90

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks63/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #811166

Status Completed	Due Date 22/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date22/04/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Naithaphon Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

23/04/2026 09:56 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 22/04/2026 02:27

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 22/04/2026 06:51

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 22/04/2026 06:52

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 23/04/2026 09:56

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 23/04/2026 09:56

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

Engineering

SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #812531

Status

Completed

Due Date

23/04/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date23/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Boonyarit/tech

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

23/04/2026 10:05 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

68/90

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

23/04/2026 10:05 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 23/04/2026 02:35

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 23/04/2026 07:41

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 23/04/2026 07:42

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 23/04/2026 10:05

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 23/04/2026 10:05

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

69/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #813819

Status Completed	Due Date 24/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---


DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date24/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Boonyarit
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

24/04/2026 19:30 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 24/04/2026 03:49

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 24/04/2026 07:34

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 24/04/2026 07:35

Approval approved.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 24/04/2026 19:30

This task has been completed.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 24/04/2026 19:30

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

Engineering

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #814943

🔔 Status

Completed

📅 Due Date

25/04/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date25/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Naithaphon Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

26/04/2026 11:23 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

74/90

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

26/04/2026 11:23 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 25/04/2026 03:29

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 25/04/2026 06:44

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 25/04/2026 06:44

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 25/04/2026 06:45

Approval approved. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 26/04/2026 11:23

This task has been completed. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 26/04/2026 11:23

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

75/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #815988

Status Completed	Due Date 26/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---


DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date26/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Naithaphon Technician*
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

26/04/2026 11:29 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 26/04/2026 03:29

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 26/04/2026 06:59

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 26/04/2026 06:59

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 26/04/2026 11:29

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 26/04/2026 11:29

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #817001

Status

Completed

Due Date

27/04/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date27/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Naithaphon Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

27/04/2026 19:24 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

27/04/2026 19:24 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 27/04/2026 02:20

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 27/04/2026 06:46

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 27/04/2026 06:46

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 27/04/2026 06:46

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 27/04/2026 06:46

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 27/04/2026 06:46

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 27/04/2026 06:46

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 27/04/2026 06:46

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 27/04/2026 06:47

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 27/04/2026 19:24

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 27/04/2026 19:24

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

81/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB #818187

Status Completed	Due Date 28/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---


DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date28/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 3 SAB-PWP-002
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 4 SAB-PWP-003
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 5 SAB-PWP-004
- 1 Function Mode
- Manual / Auto

- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 6 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 7 SAB-PWP-005
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 8 SAB-PWP-006
- 1 Function Mode
- Manual / Auto
- 1 Overload Status
- No Overload
- 2 Vibration Status
- No Vibration
- 3 Leaking Status
- Normal / No Leaking
- 4 Overall Status
- Normal
- 9 Inspection By (Name & Position)
- Naithaphon Technician*
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

29/04/2026 09:12 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 28/04/2026 02:13

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 28/04/2026 06:57

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 28/04/2026 06:57

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 28/04/2026 06:58

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/04/2026 09:12

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/04/2026 09:12

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

ONYX

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB

- #819394

🔔 Status

Completed

📅 Due Date

29/04/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date29/04/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

6

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7

SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8

SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9

Inspection By (Name & Position)

Naithaphon Technician

10

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

29/04/2026 09:29 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

86/90

12/5/69 11:20

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

TIME SPENT

29/04/2026 09:29 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 29/04/2026 02:27

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 29/04/2026 06:45
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 29/04/2026 06:46
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/04/2026 09:29
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/04/2026 09:29

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal,pop-bulk-tasks

87/90



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB #821524

Status Completed	Due Date 30/04/2026	Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
----------------------------	-------------------------------	---

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date30/04/2026
- 2 SAB-PWP-001
- 1 Function Mode
Manual / Auto
- 1 Overload Status
No Overload
- 2 Vibration Status
No Vibration
- 3 Leaking Status
Normal / No Leaking
- 4 Overall Status
Normal
- 3 SAB-PWP-002
- 1 Function Mode
Manual / Auto
- 1 Overload Status
No Overload
- 2 Vibration Status
No Vibration
- 3 Leaking Status
Normal / No Leaking
- 4 Overall Status
Normal
- 4 SAB-PWP-003
- 1 Function Mode
Manual / Auto
- 1 Overload Status
No Overload
- 2 Vibration Status
No Vibration
- 3 Leaking Status
Normal / No Leaking
- 4 Overall Status
Normal
- 5 SAB-PWP-004
- 1 Function Mode
Manual / Auto

- 1 Overload Status
No Overload
- 2 Vibration Status
No Vibration
- 3 Leaking Status
Normal / No Leaking
- 4 Overall Status
Normal
- 6 SAB-PWP-005
- 1 Function Mode
Manual / Auto
- 1 Overload Status
No Overload
- 2 Vibration Status
No Vibration
- 3 Leaking Status
Normal / No Leaking
- 4 Overall Status
Normal
- 7 SAB-PWP-005
- 1 Function Mode
Manual / Auto
- 1 Overload Status
No Overload
- 2 Vibration Status
No Vibration
- 3 Leaking Status
Normal / No Leaking
- 4 Overall Status
Normal
- 8 SAB-PWP-006
- 1 Function Mode
Manual / Auto
- 1 Overload Status
No Overload
- 2 Vibration Status
No Vibration
- 3 Leaking Status
Normal / No Leaking
- 4 Overall Status
Normal
- 9 Inspection By (Name & Position)
Manop
- 10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
30/04/2026 16:38 - 0 hr and 3 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 30/04/2026 02:38

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 30/04/2026 16:36
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 30/04/2026 16:38
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 30/04/2026 16:38
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 30/04/2026 16:38



ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #824485

SAB (Shama Lakeview Asoke Bangkok)

 **Status**
Completed

 **Due Date**
01/05/2026

 **Completed By**
SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS
1 Inspection Date01/05/2026
2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved



Wisit

02/05/2026 16:17 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
02/05/2026 16:17 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 01/05/2026 02:39	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 02/05/2026 09:58	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 02/05/2026 10:00	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 02/05/2026 16:17	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 02/05/2026 16:17	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #826076

📌 Status Completed	📅 Due Date 02/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date02/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved



Wisit

02/05/2026 16:25 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
02/05/2026 16:25 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 02/05/2026 02:22	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 02/05/2026 08:37	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 02/05/2026 08:39	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 02/05/2026 16:25	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 02/05/2026 16:25	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #827380

📌 Status Completed	📅 Due Date 03/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date03/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Off

1 Reason

7 SAB-PWP-005

1 Function Mode

Off

1 Reason

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

03/05/2026 08:24 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

03/05/2026 08:24 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

System Generated • 03/05/2026 02:33

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 03/05/2026 08:11
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 03/05/2026 08:13
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 03/05/2026 08:24
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 03/05/2026 08:24

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #829138

📌 Status Completed	📅 Due Date 04/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date04/05/2026
- 2 SAB-PWP-001

1	Function Mode	Manual / Auto
1	Overload Status	No Overload
2	Vibration Status	No Vibration
3	Leaking Status	Normal / No Leaking
4	Overall Status	Normal
3	SAB-PWP-002	
1	Function Mode	Manual / Auto
1	Overload Status	No Overload
2	Vibration Status	No Vibration
3	Leaking Status	Normal / No Leaking
4	Overall Status	

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Off

1 Reason

20 9/12/11

7 SAB-PWP-005

1 Function Mode

Off

1 Reason

22 9/12/11

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

04/05/2026 10:07 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Wisit

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 04/05/2026 08:04
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 04/05/2026 08:05
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 04/05/2026 10:07
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 04/05/2026 10:07

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #830835

📌 Status Completed	📅 Due Date 05/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date05/05/2026
2 SAB-PWP-001

1 Function Mode

Manual / Auto
1 Overload Status
No Overload
2 Vibration Status
No Vibration
3 Leaking Status
Normal / No Leaking
4 Overall Status
Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto
1 Overload Status
No Overload
2 Vibration Status
No Vibration
3 Leaking Status
Normal / No Leaking
4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Off

1 Reason

20/01/1

7 SAB-PWP-005

1 Function Mode

Off

1 Reason

22/01/1

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

06/05/2026 22:38 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Wisit

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 05/05/2026 08:17
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 05/05/2026 08:21
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 06/05/2026 22:38
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 06/05/2026 22:39

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #833657

📌 Status Completed	📅 Due Date 06/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date06/05/2026
- 2 SAB-PWP-001

1	Function Mode	Manual / Auto
1	Overload Status	No Overload
2	Vibration Status	No Vibration
3	Leaking Status	Normal / No Leaking
4	Overall Status	Normal
3	SAB-PWP-002	
1	Function Mode	Manual / Auto
1	Overload Status	No Overload
2	Vibration Status	No Vibration
3	Leaking Status	Normal / No Leaking
4	Overall Status	

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Off

1 Reason

20/01/1

7 SAB-PWP-005

1 Function Mode

Off

1 Reason

20/01/1

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

06/05/2026 22:23 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Wisit

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 06/05/2026 08:02
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 06/05/2026 08:05
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 06/05/2026 22:23
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 06/05/2026 22:23

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #835064

📌 Status Completed	📅 Due Date 07/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date07/05/2026
- 2 SAB-PWP-001
- 1 Function Mode

Manual / Auto
- 1 Overload Status

No Overload
- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Normal
- 3 SAB-PWP-002
- 1 Function Mode

Manual / Auto
- 1 Overload Status

No Overload
- 2 Vibration Status

No Vibration
- 3 Leaking Status

Normal / No Leaking
- 4 Overall Status

Abnormal

1 Action Note

มีเสียงดังเล็กเกินขอบการตรวจเช็คอย่างละเอียด

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Arurak

10 SAB (Shama Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved



TIME SPENT

08/05/2026 21:30 - 0 hr and 11 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 07/05/2026 02:35

This Task's Status was changed from Open to In Progress

SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 07/05/2026 11:44

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 07/05/2026 12:11

Approval approved.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 08/05/2026 21:30

This task has been completed.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 08/05/2026 21:30



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #836630

📌 Status Completed	📅 Due Date 08/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date08/05/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved



Wisit

08/05/2026 21:49 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
08/05/2026 21:49 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 08/05/2026 02:48	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 08/05/2026 07:56	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 08/05/2026 07:58	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 08/05/2026 21:49	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 08/05/2026 21:49	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #839547

📌 Status Completed	📅 Due Date 09/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date09/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved



Wisit

10/05/2026 09:49 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
10/05/2026 09:49 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 09/05/2026 02:29	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 09/05/2026 08:45	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 09/05/2026 08:47	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 10/05/2026 09:49	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 10/05/2026 09:49	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #841186

📌 Status Completed	📅 Due Date 10/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1 Inspection Date10/05/2026	
2 SAB-PWP-001	
1 Function Mode	Manual / Auto
1 Overload Status	No Overload
2 Vibration Status	No Vibration
3 Leaking Status	Normal / No Leaking
4 Overall Status	Normal
3 SAB-PWP-002	
1 Function Mode	Manual / Auto
1 Overload Status	No Overload
2 Vibration Status	No Vibration
3 Leaking Status	Normal / No Leaking
4 Overall Status	

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved



Wisit

10/05/2026 09:53 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
10/05/2026 09:53 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 10/05/2026 02:36	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 10/05/2026 08:28	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 10/05/2026 08:30	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 10/05/2026 09:53	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 10/05/2026 09:53	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #842872

📌 Status Completed	📅 Due Date 11/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1 Inspection Date11/05/2026	
2 SAB-PWP-001	
1 Function Mode	Manual / Auto
1 Overload Status	No Overload
2 Vibration Status	No Vibration
3 Leaking Status	Normal / No Leaking
4 Overall Status	Normal
3 SAB-PWP-002	
1 Function Mode	Manual / Auto
1 Overload Status	No Overload
2 Vibration Status	No Vibration
3 Leaking Status	Normal / No Leaking
4 Overall Status	

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved



Wisit

12/05/2026 08:15 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
12/05/2026 08:16 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 11/05/2026 02:34	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 11/05/2026 08:11	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 11/05/2026 08:13	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 12/05/2026 08:15	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 12/05/2026 08:16	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #844242

📌 Status Completed	📅 Due Date 12/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1 Inspection Date12/05/2026	
2 SAB-PWP-001	
1 Function Mode	Manual / Auto
1 Overload Status	No Overload
2 Vibration Status	No Vibration
3 Leaking Status	Normal / No Leaking
4 Overall Status	Normal
3 SAB-PWP-002	
1 Function Mode	Manual / Auto
1 Overload Status	No Overload
2 Vibration Status	No Vibration
3 Leaking Status	Normal / No Leaking
4 Overall Status	

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





15/05/2026 11:56 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
15/05/2026 11:56 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 12/05/2026 02:35	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 12/05/2026 09:35	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 12/05/2026 09:37	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/05/2026 11:56	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/05/2026 11:56	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #846242

📌 Status Completed	📅 Due Date 13/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date13/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





15/05/2026 11:59 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

15/05/2026 11:59 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 13/05/2026 02:37

This Task's Status was changed from Open to In Progress

SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 13/05/2026 07:53

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 13/05/2026 07:55

Approval approved.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/05/2026 11:59

This task has been completed.

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/05/2026 11:59



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #847569

📌 Status
Completed

📅 Due Date
14/05/2026

👤 Completed By
SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date14/05/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





16/05/2026 09:33 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT 16/05/2026 09:33 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 14/05/2026 02:32 This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 14/05/2026 09:01 Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 14/05/2026 09:02 Approval approved. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 16/05/2026 09:33 This task has been completed. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 16/05/2026 09:33	

SAB (Shama Lakeview Asoke Bangkok)



 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #849037

 Status Completed	 Due Date 15/05/2026	 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
--	---	--

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS 1 Inspection Date15/05/2026 2 SAB-PWP-001 1 Function Mode		Manual / Auto
1	Overload Status	
	No Overload	
2	Vibration Status	
	No Vibration	
3	Leaking Status	
	Normal / No Leaking	
4	Overall Status	
	Normal	
3	SAB-PWP-002	
1	Function Mode	Manual / Auto
1	Overload Status	
	No Overload	
2	Vibration Status	
	No Vibration	
3	Leaking Status	
	Normal / No Leaking	
4	Overall Status	

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





16/05/2026 09:40 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
16/05/2026 09:40 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 15/05/2026 02:47	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 15/05/2026 08:22	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 15/05/2026 08:24	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 16/05/2026 09:40	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 16/05/2026 09:40	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #850942

📌 Status Completed	📅 Due Date 16/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date16/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved

Anurak



16/05/2026 10:11 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
16/05/2026 10:11 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 16/05/2026 02:25	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 16/05/2026 08:18	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 16/05/2026 08:20	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 16/05/2026 10:11	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 16/05/2026 10:11	

SAB (Shama Lakeview Asoke Bangkok)



 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #852532

 Status Completed	 Due Date 17/05/2026	 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
--	---	--

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date17/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Natthaphon Technician

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





17/05/2026 17:33 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
17/05/2026 17:33 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 17/05/2026 02:40	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 17/05/2026 06:41	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 17/05/2026 06:41	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 17/05/2026 17:33	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 17/05/2026 17:33	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #853946

📌 Status Completed	📅 Due Date 18/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date18/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





18/05/2026 17:10 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT 18/05/2026 17:10 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 18/05/2026 02:32 This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 18/05/2026 08:23 Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 18/05/2026 08:25 Approval approved. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 18/05/2026 17:10 This task has been completed. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 18/05/2026 17:10	

SAB (Shama Lakeview Asoke Bangkok)



 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #855240

 Status Completed	 Due Date 19/05/2026	 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
--	---	--

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS 1 Inspection Date19/05/2026 2 SAB-PWP-001 1 Function Mode	
Manual / Auto	
1 Overload Status	
No Overload	
2 Vibration Status	
No Vibration	
3 Leaking Status	
Normal / No Leaking	
4 Overall Status	
Normal	
3 SAB-PWP-002	
1 Function Mode	
Manual / Auto	
1 Overload Status	
No Overload	
2 Vibration Status	
No Vibration	
3 Leaking Status	
Normal / No Leaking	
4 Overall Status	

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





19/05/2026 15:42 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT 19/05/2026 15:42 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 19/05/2026 02:32 This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 19/05/2026 08:11 Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 19/05/2026 08:12 Approval approved. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 19/05/2026 15:42 This task has been completed. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 19/05/2026 15:42	



 **ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #856521**

 **Status**
Completed

 **Due Date**
20/05/2026

 **Completed By**
SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS 1 Inspection Date20/05/2026 2 SAB-PWP-001 1 Function Mode Manual / Auto 1 Overload Status No Overload 2 Vibration Status No Vibration 3 Leaking Status Normal / No Leaking 4 Overall Status Normal 3 SAB-PWP-002 1 Function Mode Manual / Auto 1 Overload Status No Overload 2 Vibration Status No Vibration 3 Leaking Status Normal / No Leaking 4 Overall Status	
---	--

SAB (Shama Lakeview Asoke Bangkok)

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





21/05/2026 13:57 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
21/05/2026 13:57 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 20/05/2026 02:33	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 20/05/2026 09:39	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 20/05/2026 09:41	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 21/05/2026 13:57	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 21/05/2026 13:57	



 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #858020

 Status

Completed

 Due Date

21/05/2026

 Completed By

SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date21/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

SAB (Shama Lakeview Asoke Bangkok)

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





21/05/2026 14:04 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
21/05/2026 14:04 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 21/05/2026 02:29	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 21/05/2026 08:25	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 21/05/2026 08:28	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 21/05/2026 14:04	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 21/05/2026 14:05	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #859441

📌 Status Completed	📅 Due Date 22/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date23/05/2026
2	SAB-PWP-001
1	Function Mode
Manual / Auto	
1	Overload Status
No Overload	
2	Vibration Status
No Vibration	
3	Leaking Status
Normal / No Leaking	
4	Overall Status
Normal	
3	SAB-PWP-002
1	Function Mode
Manual / Auto	
1	Overload Status
No Overload	
2	Vibration Status
No Vibration	
3	Leaking Status
Normal / No Leaking	
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





22/05/2026 08:38 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
22/05/2026 08:39 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 22/05/2026 02:48	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 22/05/2026 08:22	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 22/05/2026 08:25	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 22/05/2026 08:38	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 22/05/2026 08:39	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #860658

📌 Status Completed	📅 Due Date 23/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date23/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





24/05/2026 08:16 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
24/05/2026 08:16 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 23/05/2026 02:22	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 23/05/2026 08:30	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 23/05/2026 08:31	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 24/05/2026 08:16	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 24/05/2026 08:16	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #861980

📌 Status Completed	📅 Due Date 24/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date24/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status


Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





24/05/2026 10:54 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
24/05/2026 10:54 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 24/05/2026 02:26	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 24/05/2026 08:49	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 24/05/2026 08:51	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 24/05/2026 10:54	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 24/05/2026 10:54	

SAB (Shama Lakeview Asoke Bangkok)



 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #863159

 Status Completed	 Due Date 25/05/2026	 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
--	---	--

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date25/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





28/05/2026 09:49 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
28/05/2026 09:49 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 25/05/2026 02:30	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 25/05/2026 07:53	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 25/05/2026 07:54	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/05/2026 09:49	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/05/2026 09:49	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #864363

📌 Status Completed	📅 Due Date 26/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date26/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





28/05/2026 09:48 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
28/05/2026 09:49 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 26/05/2026 02:29	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 26/05/2026 10:10	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 26/05/2026 10:11	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/05/2026 09:48	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/05/2026 09:49	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #865440

📌 Status Completed	📅 Due Date 27/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date27/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





28/05/2026 09:48 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
28/05/2026 09:48 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 27/05/2026 02:32	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 27/05/2026 07:39	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 27/05/2026 07:41	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/05/2026 09:48	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/05/2026 09:48	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #866559

📌 Status Completed	📅 Due Date 28/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date28/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Boonyarat

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





28/05/2026 09:46 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
28/05/2026 09:46 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 28/05/2026 02:28	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 28/05/2026 09:04	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 28/05/2026 09:05	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/05/2026 09:46	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/05/2026 09:46	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #867861

📌 Status Completed	📅 Due Date 29/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date29/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Anurak

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





29/05/2026 13:37 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
29/05/2026 13:37 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 29/05/2026 02:54	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 29/05/2026 08:18	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 29/05/2026 08:18	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 29/05/2026 08:21	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/05/2026 13:37	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/05/2026 13:37	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #868934

📌 Status Completed	📅 Due Date 30/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date30/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Normal

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





30/05/2026 09:21 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT	
30/05/2026 09:21 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
COMMENTS	
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 30/05/2026 02:21	
This Task's Status was changed from Open to In Progress	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 30/05/2026 08:10	
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 30/05/2026 08:11	
Approval approved.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 30/05/2026 09:21	
This task has been completed.	
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 30/05/2026 09:21	

SAB (Shama Lakeview Asoke Bangkok)



🔧 ONYX_ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #871300

📌 Status Completed	📅 Due Date 31/05/2026	👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
-----------------------	--------------------------	---

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS	
1	Inspection Date31/05/2026
2	SAB-PWP-001
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status
	Normal
3	SAB-PWP-002
1	Function Mode
	Manual / Auto
1	Overload Status
	No Overload
2	Vibration Status
	No Vibration
3	Leaking Status
	Normal / No Leaking
4	Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking


4 Overall Status

Normal

9 Inspection By (Name & Position)

Kritchai

10 SAB (Shana Lakeview Asoke Bangkok) 1. Manager Engineering successfully approved





31/05/2026 09:36 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

31/05/2026 09:36 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 31/05/2026 02:35

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 31/05/2026 07:56
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer • 31/05/2026 07:57
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 31/05/2026 09:36
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 31/05/2026 09:36



🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #874586

 Status Completed	 Priority 1 Daily Jobs	 Type PM	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	 Due Date 01/06/2026	 Downtime 0 hr and 0 min	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	 Completed Date 04/06/2026 13:22		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date01/06/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm

04/06/2026 13:22 By SAB (Shama Lakeview Asoke Bangkok) 1. Manager Engineering

TIME SPENT

04/06/2026 13:22 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

3 SAB-PWP-002

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #876358

 Status Completed	 Priority 1 Daily Jobs	 Type  PM	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	 Due Date 02/06/2026	 Downtime 0 hr and 0 min	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	 Completed Date 04/06/2026 13:22		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date02/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



04/06/2026 13:22 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

04/06/2026 13:22 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #877636

 **Status**
Completed

 **Priority**
1 Daily Jobs

 **Type**
PM

 **Asset**
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

 **Assigned to**
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

 **Due Date**
03/06/2026

 **Downtime**
0 hr and 0 min

 **Location**
SAB (Shama Lakeview Asoke Bangkok)

 **Completed By**
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

 **Completed Date**
04/06/2026 13:22

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date03/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Kittichai

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm

04/06/2026 13:21 By SAB (Shama Lakeview Asoke Bangkok) 1. Manager Engineering

TIME SPENT

04/06/2026 13:22 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

3 SAB-PWP-002

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #879372

 **Status**
Completed

 **Priority**
1 Daily Jobs

 **Type**
PM

 **Asset**
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

 **Assigned to**
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

 **Due Date**
04/06/2026

 **Downtime**
0 hr and 0 min

 **Location**
SAB (Shama Lakeview Asoke Bangkok)

 **Completed By**
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

 **Completed Date**
04/06/2026 13:21

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date04/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



04/06/2026 13:21 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

04/06/2026 13:21 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #881183

Status
Completed

Priority
1 Daily Jobs

Type
PM

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Assigned to
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date
05/06/2026

Downtime
0 hr and 0 min

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date
07/06/2026 18:28

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date05/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

07/06/2026 18:28 By SAB (Shama Lakeview Asoke Bangkok) 1. Manager Engineering

TIME SPENT

07/06/2026 18:28 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #883768

 Status Completed	 Priority 1 Daily Jobs	 Type  PM	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	 Due Date 06/06/2026	 Downtime 0 hr and 0 min	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	 Completed Date 07/06/2026 18:28		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date06/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



07/06/2026 18:28 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

07/06/2026 18:28 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #885277

Status
Completed

Priority
1 Daily Jobs

Type
PM

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Assigned to
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date
07/06/2026

Downtime
0 hr and 0 min

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date
07/06/2026 18:27

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date07/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

07/06/2026 18:27 By SAB (Shama Lakeview Asoke Bangkok) 1. Manager Engineering

TIME SPENT

07/06/2026 18:27 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #886921

 Status Completed	 Priority 1 Daily Jobs	 Type  PM	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	 Due Date 08/06/2026	 Downtime 0 hr and 0 min	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	 Completed Date 12/06/2026 10:12		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date08/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/06/2026 10:12 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

12/06/2026 10:12 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #889883

Status Completed	Priority 1 Daily Jobs	Type 🔧 PM	Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 09/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 12/06/2026 12:54		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date09/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Wong/Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

12/06/2026 12:54 By SAB (Shama Lakeview Asoke Bangkok) 1. Manager Engineering

TIME SPENT

12/06/2026 12:54 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #892010

 Status Completed	 Priority 1 Daily Jobs	 Type  PM	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	 Due Date 10/06/2026	 Downtime 0 hr and 0 min	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	 Completed Date 12/06/2026 12:57		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date10/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Wong/Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/06/2026 12:57 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 12:57 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #893501

Status
Completed

Priority
1 Daily Jobs

Type
PM

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Assigned to
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date
11/06/2026

Downtime
0 hr and 0 min

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date
13/06/2026 15:36

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS
1 Inspection Date11/06/2026
2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

13/06/2026 15:36 By SAB (Shama Lakeview Asoke Bangkok) 1. Manager Engineering

TIME SPENT

13/06/2026 15:36 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #894825

 Status Completed	 Priority 1 Daily Jobs	 Type  PM	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	 Due Date 12/06/2026	 Downtime 0 hr and 0 min	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	 Completed Date 13/06/2026 15:36		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date12/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



13/06/2026 15:36 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
13/06/2026 15:36 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #896851

Status
Completed

Priority
1 Daily Jobs

Type
PM

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Assigned to
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date
13/06/2026

Downtime
0 hr and 0 min

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date
13/06/2026 15:36

DESCRIPTION
@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

- 1 Inspection Date13/06/2026
- 2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

13/06/2026 15:36 By SAB (Shama Lakeview Asoke Bangkok) 1. Manager Engineering

TIME SPENT

13/06/2026 15:36 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #898152

 Status Completed	 Priority 1 Daily Jobs	 Type  PM	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	 Due Date 14/06/2026	 Downtime 0 hr and 0 min	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	 Completed Date 14/06/2026 18:53		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date14/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 18:53 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

14/06/2026 18:53 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #899871

Status
Completed

Priority
1 Daily Jobs

Type
PM

Asset
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

Assigned to
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date
15/06/2026

Downtime
0 hr and 0 min

Location
SAB (Shama Lakeview Asoke Bangkok)

Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date
15/06/2026 18:50

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date15/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

15/06/2026 18:50 By SAB (Shama Lakeview Asoke Bangkok) 1. Manager Engineering

TIME SPENT

15/06/2026 18:50 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #901833

 Status Completed	 Priority 1 Daily Jobs	 Type  PM	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	 Due Date 16/06/2026	 Downtime 0 hr and 0 min	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	 Completed Date 16/06/2026 21:36		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date16/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Nitnirun & Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



16/06/2026 21:36 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

16/06/2026 21:36 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #903375

🔔 Status Completed	🕒 Priority 1 Daily Jobs	🔧 Type PM	🏠 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
👤 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	📅 Due Date 17/06/2026	🕒 Downtime 0 hr and 0 min	🏠 Location SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	📅 Completed Date 18/06/2026 11:31		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date17/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Nitnirun & Technician

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm

18/06/2026 11:31 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

18/06/2026 11:31 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #904876

 Status Completed	 Priority 1 Daily Jobs	 Type  PM	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	 Due Date 18/06/2026	 Downtime 0 hr and 0 min	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	 Completed Date 18/06/2026 10:42		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date18/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



18/06/2026 10:42 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

18/06/2026 10:42 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #906213

 **Status**
Completed

 **Priority**
1 Daily Jobs

 **Type**
PM

 **Asset**
ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering

 **Assigned to**
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

 **Due Date**
19/06/2026

 **Downtime**
0 hr and 0 min

 **Location**
SAB (Shama Lakeview Asoke Bangkok)

 **Completed By**
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

 **Completed Date**
19/06/2026 17:23

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date19/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

19/06/2026 17:23 By SAB (Shama Lakeview Asoke Bangkok) 1. Manager Engineering

TIME SPENT

19/06/2026 17:23 - 1 hr and 0 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #907433

Status Completed	Priority 1 Daily Jobs	Type PM	Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 20/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 20/06/2026 22:50		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date20/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



20/06/2026 22:50 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

20/06/2026 22:50 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #908872

Status Completed	Priority 1 Daily Jobs	Type 🔧 PM	Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 21/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 21/06/2026 14:46		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date21/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

7 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

8 SAB-PWP-006

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

21/06/2026 14:45 By SAB (Shama Lakeview Asoke Bangkok) 1. Manager Engineering

TIME SPENT

21/06/2026 14:46 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 13-02 Domestic Cold-Water Pumps Daily Visual Inspection - SAB - #910227

 Status Completed	 Priority 1 Daily Jobs	 Type  PM	 Asset ENG 13-02 Domestic Cold Water Pumps Daily Visual Inspection > ENG 13 Domestic Cold Water Pumps > 4. SAB Engineering
 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	 Due Date 22/06/2026	 Downtime 0 hr and 0 min	 Location SAB (Shama Lakeview Asoke Bangkok)
 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	 Completed Date 22/06/2026 22:04		

DESCRIPTION

@Engineering Standard; @ENG 13-02;

INSTRUCTIONS

1 Inspection Date22/06/2026

2 SAB-PWP-001

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

3 SAB-PWP-002

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

4 SAB-PWP-003

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

5 SAB-PWP-004

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4 Overall Status

Normal

6 SAB-PWP-005

1 Function Mode

Manual / Auto

1 Overload Status

No Overload

2 Vibration Status

No Vibration

3 Leaking Status

Normal / No Leaking

4

Overall Status

Normal

7 SAB-PWP-005

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

8 SAB-PWP-006

1

Function Mode

Manual / Auto

1

Overload Status

No Overload

2

Vibration Status

No Vibration

3

Leaking Status

Normal / No Leaking

4

Overall Status

Normal

9 Inspection By (Name & Position)

Pranotsak/tech

10 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



22/06/2026 22:04 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

22/06/2026 22:04 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS