

ผลการตรวจสอบระบบตรวจจับการรั่วไหลของสารเคมี

MaintPlant	Basic fin. date	Order	Description	Functional Loc.	Description	Priority	MaintActivType	Order Type	User status	System status
C939	01/28/2017	20008898057	3M AT-90401 S:DI(237) Apolarm detector.	C939-PS -MISC -AT-90401	S:DI(238)S:DI(237)ES-1890 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9 COMP	CLSD MACM PRC SETC
C939	01/28/2017	20008898058	3M AT-90411 S:DI(333)Apolarm detector	C939-PS -MISC -AT-90411	S:DI(392)S:DI(333)ES-1390 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9	CLSD MACM PRC SETC
C939	01/28/2017	20008898059	3M AT-90431 S:DI(253) Apolarm detector.	C939-PS -MISC -AT-90431	S:DI(257)S:DI(253)ES-1395 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9 COMP	CLSD MACM PRC SETC
C939	01/28/2017	20008898060	3M AT-90471 S:DI(258) Apolarm detector.	C939-PS -MISC -AT-90471	S:DI(280)S:DI(258)MOD MEMO BAT CPU CHR	3	100	Z010	SCP9 PLN9 MAT8 SCH9 COMP	CLSD MACM PRC SETC
C939	01/28/2017	20008898061	3M AT-90492 S:DI(312) Apolarm detector.	C939-PS -MISC -AT-90492	S:DI(323)S:DI(312)ES-1891 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9 COMP	CLSD MACM PRC SETC
C939	01/31/2017	20009219087	SAI(334) Repair conduit Level and Light	C939-PS -MISC -AT-90401	S:DI(238)S:DI(237)ES-1890 HC SENSOR FAIL	3	R07	Z020	SCP9 PLN9 MAT3 SCH9	CLSD MACM PRC SETC
C939	04/28/2017	20009175642	3M AT-90401 S:DI(237) Apolarm detector.	C939-PS -MISC -AT-90401	S:DI(238)S:DI(237)ES-1890 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH1	CLSD PRT MACM PRC SETC
C939	04/28/2017	20009175643	3M AT-90411 S:DI(333)Apolarm detector	C939-PS -MISC -AT-90411	S:DI(392)S:DI(333)ES-1390 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH1	CLSD PRT MACM PRC SETC
C939	04/28/2017	20009175644	3M AT-90431 S:DI(253) Apolarm detector.	C939-PS -MISC -AT-90431	S:DI(257)S:DI(253)ES-1395 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH1	CLSD PRT MACM PRC SETC
C939	04/28/2017	20009175645	3M AT-90471 S:DI(258) Apolarm detector.	C939-PS -MISC -AT-90471	S:DI(280)S:DI(258)MOD MEMO BAT CPU CHR	3	100	Z010	SCP9 PLN9 MAT8 SCH1	CLSD PRT MACM PRC SETC
C939	04/28/2017	20009175646	3M AT-90492 S:DI(312) Apolarm detector.	C939-PS -MISC -AT-90492	S:DI(323)S:DI(312)ES-1891 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH1	CLSD PRT MACM PRC SETC
C939	07/28/2017	20009413237	3M AT-90401 S:DI(237) Apolarm detector.	C939-PS -MISC -AT-90401	S:DI(238)S:DI(237)ES-1890 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9	TECO PRT MACM PRC SETC
C939	07/28/2017	20009413238	3M AT-90411 S:DI(333)Apolarm detector	C939-PS -MISC -AT-90411	S:DI(392)S:DI(333)ES-1390 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9	TECO PRT MACM PRC SETC
C939	07/28/2017	20009413239	3M AT-90431 S:DI(253) Apolarm detector.	C939-PS -MISC -AT-90431	S:DI(257)S:DI(253)ES-1395 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9	TECO PRT MACM PRC SETC
C939	07/28/2017	20009413240	3M AT-90471 S:DI(258) Apolarm detector.	C939-PS -MISC -AT-90471	S:DI(280)S:DI(258)MOD MEMO BAT CPU CHR	3	100	Z010	SCP9 PLN9 MAT8 SCH9	TECO PRT MACM PRC SETC
C939	07/28/2017	20009413241	3M AT-90492 S:DI(312) Apolarm detector.	C939-PS -MISC -AT-90492	S:DI(323)S:DI(312)ES-1891 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9	TECO PRT MACM PRC SETC
C939	10/28/2017	20009638613	3M AT-90401 S:DI(237) Apolarm detector.	C939-PS -MISC -AT-90401	S:DI(238)S:DI(237)ES-1890 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9	TECO MACM PRC SETC
C939	10/28/2017	20009638614	3M AT-90411 S:DI(333)Apolarm detector	C939-PS -MISC -AT-90411	S:DI(392)S:DI(333)ES-1390 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9	TECO MACM PRC SETC
C939	10/28/2017	20009638615	3M AT-90431 S:DI(253) Apolarm detector.	C939-PS -MISC -AT-90431	S:DI(257)S:DI(253)ES-1395 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9	TECO MACM PRC SETC
C939	10/28/2017	20009638616	3M AT-90471 S:DI(258) Apolarm detector.	C939-PS -MISC -AT-90471	S:DI(280)S:DI(258)MOD MEMO BAT CPU CHR	3	100	Z010	SCP9 PLN9 MAT8 SCH9	TECO MACM PRC SETC
C939	10/28/2017	20009638617	3M AT-90492 S:DI(312) Apolarm detector.	C939-PS -MISC -AT-90492	S:DI(323)S:DI(312)ES-1891 HC SENSOR FAIL	3	100	Z010	SCP9 PLN9 MAT8 SCH9	TECO MACM PRC SETC