

Report No	Incident Date	Date of Notification	Time	Asset	Location	Summary of Incident	IOGP	Event Type	Incident Classification	Job Classification	Spill	Immediate Actions
W0090	18 Mar 2019	21 Mar 2019	17:45	PTTEP1	UT1-3	Fire from the fuse low voltage of Provincial Electricity Authority sparks.	Production	-Incident with consequences	Property	Company	-	Operator pushed ESD for shut down wellsite and inform to Supervisor Operation, Supervisor Operation inform to operator that assess the situation before put out fire by fire extinguisher.
W0129	16 Mar 2019	10 Apr 2019	00:59	PTTEP1	PTTEP1	Micro-sleep of BRK driver (Road Tanker License No.70-1960)detected by Guardian System	Production	-Near miss		Contractor	-	- Guardian In-cab Alerts(both sound and seat vibration)immediately alarmed the driver waking up from micro-sleep(1.72 sec after eye closure) - Guardian Center called BRK responsible person to notify this micro-sleep event around 01:05 am.
W0061	25 Feb 2019	26 Feb 2019	11:30	PTTEP1	UT1-7	Crude oil leaked from flow meter into the soil.	Production	-Incident with consequences	Spill	Company	1 l	Stopped leak and cleaned up area.
W0010	05 Jan 2019	14 Jan 2019	18:50	PTTEP1	NPI-A	Crude oil release from 42-RV-432 to NPI-A09's well cellar during crude oil loading activities.	Production	-Incident with consequences	LOPC	Company	2.52 m3	- Stop crude oil loading activities. - On site Operator informed On duty supervisor and pump back the liquid to the process.
W0086	18 Apr 2018	18 Apr 2018	07:56	PTTEP1	NPI-A	07.56 hrs, road tanker hit with loading gantry of NPI-A resulted to loading gantry and tanker damaged but no personal injury and no spill.	Production	-Incident with consequences	Property	Contractor	-	Helper wellsite are observed road tanker hit with loading gantry. He stop work driver and informed to NPI-A OPR. NPI-A OPR informed to OPR Onduty UT1-7 and Suphanburi Supervisor Operation. Supervisor informed to VP and informed to Site SSHE for responsible to site investigate.
W0049	09 Mar 2018	09 Mar 2018	00:27	PTTEP1	PTTEP1	BRK RT is overturned at Suphanburi bypass road after unloading crude oil at BCP. No personal injury and 20 liter of motor oil spill to asphalt road.	Production	-Incident with consequences	Property,Spill	Contractor	20 l	- Driver are blocked area, standby fire extinguisher and use spill kit absorb motor oil. - Driver informed BRK Supervisor. - BRK Supervisor informed to OPR Onduty. - OPR Onduty informed to Suphanburi supervisor operation. - Suphanburi supervisor operation informed to VP. - Move road tanker from incident area to BRK yard and clear spill area to normal.
W0027	31 Jan 2018	01 Feb 2018	14:30	PTTEP1	PTTEP1	Crude oil road tanker No.XP-58 crash with ISUZU pickup at Suphanburi bypass. No injury and spill. Road tanker damaged.	Production	-Incident with consequences	Property	Contractor	-	Driver inform to BRK supervisor and operator on duty. BRK team block that area and contact insurance to processing. Site SSHE representative conduct alcohol testing.
W0175	26 Jun 2017	26 Jun 2017	07:19	PTTEP1	PTTEP1	A company light vehicle slightly hit a dog on a local public road.	Production	-Incident with consequences	Property	Company	-	- Report to Operator on duty UT1-7 wellsite. - Call car insurance.
W0414	26 Nov 2016	27 Nov 2016	22:06	PTTEP1	PTTEP1	The road tanker No. XP-56 was fired by gun. The resulted to one injured person and property damaged (front mirror damaged)	Production	-Incident with consequences	FAC,Property	Contractor	-	- BRK'S driver informed supervisor - BRK'S driver informed Police - Rescue and Police arrived accident area and sent driver injured to Chaophrayayommarat hospital - Cancel crude evacuation 242.98 bbl
W0243	09 Jul 2016	11 Jul 2016	21:40	PTTEP1	UT1-7	The operator cab of the crane collided with the platform of loading gantry during coiled tubing operation.	Production	-Incident with consequences	Property	Contractor	-	Notify the incident to UT1-7 operator and PTTEP S1 super intend. Stop the operation and commencing meeting.
W0479	13 Nov 2015	17 Nov 2015	20:20	PTTEP1	PTTEP1	Crude Transport Truck was scraped.	Production	-Incident with consequences	Property	Contractor	-	- Truck Driver reported to BRK's Supervisor. - BRK's Supervisor reported to Operator on-duty. - Driver contacted insurance.
W0303	18 Jul 2015	21 Jul 2015	17:40	PTTEP1	PTTEP1	Cow front of the car instant	Production	-Incident with consequences	Property	Company	-	- Report to Operator on duty UT1-7 - Call Polish duty. - Call car insurance. - To trolleys the car out of the way. - First negotiations to litigant.
W0214	26 May 2015	27 May 2015	18:30	PTTEP1	UT1-7	The storm wind blew new parking to damage.	Construction	-Incident with consequences	Property	Contractor	-	Inform Supervisor and contractor for repair ,shut down electrical system and block area.
W0105	05 Mar 2015	12 Mar 2015	10:30	PTTEP1	BTI-D	The rice straw was burned by welding work	Construction	-Incident with consequences	Property	Contractor	-	Fire fighting and notify the owner area and stop work for investigation.
W0536	15 Oct 2014	26 Feb 2015	09:00	PTTEP1	NPI-A	PTTEP's contractor who spreaded soil into villager	Construction	-External complaint		Contractor	-	After having received the complaint, PTTEP staff at Suphanburi immediately contacted the land owner to inform her that PTTEP was aware of the situation and already started the internal process to handle the issue. A few hours later PTTEP community staff and the site supervisor had a meeting with the complainer in person to investigate the situation and found out that there was soil spreaded into her land along the drilling site access road. PTTEP informed the contractor to remove the soil but at that time her land had been flooding, so the contractor needed to wait for a few months to start to remove the soil. In December 30th the contractor complete removed the soil as promise.
W0238	02 Jun 2014	18 Jul 2014	20:00	PTTEP1	BKM-B	The guardhouse bumps the employee, while had storm wind	Production	-Incident with consequences	FAC	Company	0 l	1.Accident Investigation 2.Accelerate the implementation of install the guardhouse base is permanent.
W0237	26 May 2014	18 Jul 2014	19:00	PTTEP1	UT1-7	Hydraulic oil spill from Sophon crane, when it parking at UT1-7.	Production	-Incident with consequences	Spill	Contractor	10 l	1. accident investigations 2.To scoop contaminated soil away from this area for disposal and move the new soil and stone down to this area.
W0236	24 Feb 2014	18 Jul 2014	14:00	PTTEP1	PTTEP1	The sedan collided with a Fortuner car's Suphanburi asset at the bridge Phrama 6 Soi 32 three separate.	Unspecified	-Incident with consequences	Property	Company	0 l	Because the vehicles have insurance. Therefore, the application program costs for car repair insurance.