

ภาคผนวก ข-41

เอกสารการทบทวนเหตุการณ์อุบัติเหตุ/อุบัติภัย

แบบสอบสวนอุบัติเหตุ หรือเหตุการณ์ผิดปกติ (Incident Initial & Investigation report)

สถานที่เกิดเหตุ	Location of incident: PVC loading (PVC Silo)		
วัน/เดือน/ปี ที่เกิดเหตุ/พบเหตุการณ์	Date of incident: 23 Feb, 2022	เวลา	Time: 02.56 PM
วัน/เดือน/ปี ที่เหตุการณ์สิ้นสุด	Date of ended incident: 23 Feb, 2022	เวลา	Time: 06.00 PM
วัน/เดือน/ปี ที่สอบสวน	Date of investigation: 23 Feb, 2022	เวลา	Time: 03.30 AM
ผู้รายงาน	Reporter: [REDACTED]		

รายละเอียดเหตุการณ์ที่เกิดขึ้น (ใคร ทำอะไร ที่ไหน เมื่อไหร่ อย่างไร)

Title: PVC Leakage at PVC Loading (PVC Silo)

Situation (Who, What, Where, When)

On Wednesday 23 February 2022 (02.56 PM), TSSK who is transporter to supply our R/M (PVC) does not check a cover as red circle is shown while loading of PVC.

A cover wasn't completely closed, then PVC in tank of lorry truck was leaked and spreaded out. For preliminary investigation, TSSK's Driver told that he doesn't



get a permission to interfere the condition of tank. A cover of tank which wasn't completely closed may be occurred from their loading activities at TPC. The amount of PVC was leaked about 190 kg. At our area, it already has cleaned all leakage for corrective action as pictures below;



However, TPC are during investigation to find root cause and will create prevention action in the next shipment. They will process to issue the root cause and corrective/preventive action and make an appointment for this case on 1 Mar 2022 at 10.00 AM.