เอกสารแนบที่ 42

Noise Contour Map ปี 2564

รายงานผลการจัดทำแผนที่เส้นระดับเสียง
(Noise Contour Map) ภายในสถานประกอบการ
บริษัท ไทยโพลีคาร์บอเนต จำกัด
นิคมอุตสาหกรรมผาแดง จังหวัดระยอง
ระหว่างวันที่ 20-21 กันยายน 2564

สารบัญ

หน้า

สารบัญ i
สารบัญตาราง ii

1. บทนำ 1
2. วัตถุประสงค์ 1
3. ขอบเขตของการตรวจวัด 1
4. ขอบเขตของการดำเนินการ 1
   4.1 ตำแหน่งตรวจวัดและช่วงเวลาดำเนินการ 1
   4.2 วิธีตรวจวัดและวิเคราะห์ข้อมูล 3
5. ผลการตรวจวัด 3
6. สรุปผลการตรวจวัดและข้อเสนอแนะ 6

ภาคผนวก ก Noise Contour Map
ภาคผนวก ข - สำเนาหนังสือรับรองห้องปฏิบัติการวิเคราะห์เอกชน บริษัท เอสจีเอส (ประเทศไทย) จำกัด
- สำเนาใบรับรองมาตรฐาน ISO 9001:2015
ภาคผนวก ค มาตรฐานที่ใช้เปรียบเทียบ

สารบัญตาราง

หน้า

ตารางที่

4.1-1 ตำแหน่งและจำนวนจุดตรวจวัดระดับเสียงภายในสถานประกอบการ บริษัท ไทยโพลีคาร์บอเนต จำกัด โรงงานที่ 1 (TPCC 1) และ โรงงานที่ 2 (TPCC 2) ระหว่างวันที่ 20-21 กันยายน 2564 2
4.2-1 วิธีการตรวจวัดและการวิเคราะห์ข้อมูล 3
5.1 ผลการตรวจวัดระดับเสียงภายในสถานประกอบการ โรงงานที่ 1 (TPCC 1) บริษัท ไทยโพลีคาร์บอเนต จำกัด ระหว่างวันที่ 20-21 กันยายน 2564 4
5.2 ผลการตรวจวัดระดับเสียงภายในสถานประกอบการ โรงงานที่ 2 (TPCC 2) บริษัท ไทยโพลีคาร์บอเนต จำกัด ระหว่างวันที่ 20-21 กันยายน 2564 5

SGS

รายงานผลการจัดทำแผนที่เส้นระดับเสียง (Noise Contour Map) ภายในสถานประกอบการ บริษัท ไทยโพลีคาร์บอเนต จำกัด ระหว่างวันที่ 20-21 กันยายน 2564

1. บทนำ

บริษัท ไทยโพลีคาร์บอเนต จำกัด ได้ก่อตั้งขึ้นเมื่อวันที่ 1 พฤษภาคม 2539 ด้วยทุนจดทะเบียนกว่า 1,000 ล้านบาท มีกำลังการผลิตอยู่ที่ 170,000 ตันต่อปี บริษัท ไทยโพลีคาร์บอเนต จำกัด เป็นผู้ผลิตโพลีคาร์บอเนตชนิดแรกของเอเชียตะวันออกเฉียงใต้ และมีการผลิตหลายลักษณะด้านวิศวกรรมที่มีคุณภาพสูง สำหรับการส่งออกทั้งภายในและภายนอกประเทศ

บริษัท ไทยโพลีคาร์บอเนต จำกัด ได้มอบหมายให้บริษัท เอสจีเอส (ประเทศไทย) จำกัด ดำเนินการตรวจวัดระดับเสียงและจัดทำแผนที่เส้นระดับเสียง (Noise Contour Map) ภายในสถานประกอบการ ของบริษัท ไทยโพลีคาร์บอเนต จำกัด ซึ่งตั้งอยู่ที่นิคมอุตสาหกรรมผาแดง จังหวัดระยอง ระหว่างวันที่ 20-21 กันยายน 2564 โดยมีรายละเอียดของการตรวจวัดดังจะกล่าวต่อไป

2. วัตถุประสงค์

เพื่อตรวจวัดระดับเสียงและจัดทำแผนที่เส้นระดับเสียง (Noise Contour Map) ภายในสถานประกอบการ โรงงานที่ 1 (TPCC 1) และภายในโรงงานที่ 2 (TPCC 2) บริษัท ไทยโพลีคาร์บอเนต จำกัด

3. ขอบเขตการตรวจวัด

การตรวจวัดระดับเสียงเพื่อจัดทำแผนที่เส้นระดับเสียง (Noise Contour Map) ดำเนินการตรวจวัดบริเวณสถานประกอบการบริษัท ไทยโพลีคาร์บอเนต จำกัด ภายในโรงงานที่ 1 (TPCC 1) และภายในโรงงานที่ 2 (TPCC 2) ซึ่งดำเนินการตรวจวัดระหว่างวันที่ 20-21 กันยายน 2564

4. ขอบเขตของการดำเนินการ

4.1 ตำแหน่งตรวจวัดและช่วงเวลาดำเนินการ

การตรวจวัดระดับเสียงเพื่อจัดทำแผนที่เส้นระดับเสียง (Noise Contour Map) บริษัท ไทยโพลีคาร์บอเนต จำกัด ระหว่างวันที่ 20-21 กันยายน 2564 รายละเอียดของตำแหน่งและจำนวนจุดตรวจวัดสามารถสรุปได้ดังตารางที่ **4.1-1**

ตารางที่ 4.1-1 ตำแหน่งและจำนวนจุดตรวจวัดระดับเสียงภายในสถานประกอบการ บริษัท ไทยโพลีคาร์บอเนต จำกัด โรงงานที่ 1 (TPCC 1) และ โรงงานที่ 2 (TPCC 2) ระหว่างวันที่ 20-21 กันยายน 2564

โรงงานที่ 1 (TPCC 1)		โรงงานที่ 2 (TPCC 2)	
ตำแหน่งตรวจวัด	จำนวนจุดตรวจวัด (จุด)	ตำแหน่งตรวจวัด	จำนวนจุดตรวจวัด (จุด)
1. PT1-1	274	1. PT2-1	68
2. PT1-2	95	2. PT2-2	60
3. PT1-3	24	3. PT2-3	16
4. PT1-4	34	4. PT2-4	24
5. PT1-5	25	5. PT2-5	58
6. PT1-6	26	6. PT2-6	24
7. BPA Silo	54	7. PT2-7	17
8. CO Unit	39	8. BPA Warehouse	55
9. G Structure 1FL	104	9. CCR	46
10. G Structure 2FL	50	10. CTY	41
11. G Structure 3FL	42	11. Compressor Unit	37
12. G Structure 4FL	18	12. Cooling	46
13. Tank Yard	39	13. G Structure 1FL	69
14. P Structure 1FL	92	14. G Structure 2FL	33
15. P Structure 2FL	58	15. G Structure 3FL	32
16. P Structure 3FL	41	16. G Structure 4FL	10
17. P Structure 4FL	35	17. PC Silo	44
18. P Structure 5FL	20	18. P Structure 1FL	57
19. VP1 PC Silo	50	19. P Structure 2FL	27
20. VP1 Utility Unit	61	20. P Structure 3FL	27
		21. P Structure 4FL	24
		22. P Structure 5FL	22
		23. P Structure 6FL	6
		24. Tank Yard & Refrigerator	90
รวม	1,181	รวม	935

4.2 วิธีการตรวจวัดและการวิเคราะห์ข้อมูล

ทำการเลือกแผนที่ตรวจวัด โดยการสุ่มเลือกแบบกริดพื้นที่แบบไม่ระบุจะจง (Grid Sampling) โดยการวาง Block Grid ตามขนาดพื้นที่แบบ Symmetric คือ 5x5 เมตร โดยใช้โปรแกรม ARC GIS คำนวณการตรวจวัดระดับเสียงเฉลี่ย 2-5 นาที (Leq 2-5 min) โดยใช้มาตระดับเสียง (Sound Level Meter) ที่ได้มาตรฐาน IEC 61672 โดยทำการปรับเทียบความถูกต้อง (Calibration) ด้วยอุปกรณ์ตรวจสอบความถูกต้อง (Noise Calibrator) ที่ได้มาตรฐาน IEC 60942 ก่อนและหลังทำการตรวจวัด และจัดทำแผนที่เส้นระดับเสียง (Noise Contour Map) โดยใช้โปรแกรม Sound Plan 7.3 แสดงดังตารางที่ 4.2-1

ตารางที่ 4.2-1 วิธีการตรวจวัดและการวิเคราะห์ข้อมูล

พารามิเตอร์	เครื่องมือตรวจวัด	การวิเคราะห์ข้อมูล
ระดับเสียงเฉลี่ย (Leq) 2-5 นาที	Sound Level Meter	Sound Plan 7.3

5. ผลการตรวจวัด

การตรวจวัดค่าระดับเสียงเพื่อจัดทำแผนที่เส้นระดับเสียง (Noise Contour Map) ภายในสถานประกอบการของบริษัท ไทยโพลีคาร์บอเนต จำกัด ระหว่างวันที่ 20-21 กันยายน 2564 ดำเนินการตรวจวัดทั้งหมด 2,116 จุด พบค่าระดับเสียงแสดงในตารางที่ 5.1 ถึงตารางที่ 5.2 สำหรับแผนผังแสดงจุดตรวจวัดระดับเสียงและแผนที่เส้นระดับเสียง (Noise Contour Map) แสดงดังภาคผนวก ก

ตารางที่ 5.1 ผลการตรวจวัดระดับเสียงภายในสถานประกอบการ โรงงานที่ 1 (TPCC 1) บริษัท ไทยโพลีคาร์บอเนต จำกัด ระหว่างวันที่ 20-21 กันยายน 2564

ตำแหน่งตรวจวัด	ระดับเสียงสูง-ต่ำ (เดซิเบลเอ)	จำนวนจุดที่มีค่ามากกว่าและเท่ากับ 85 เดซิเบลเอ
1. PT1-1	50.4-82.5	-
2. PT1-2	63.3-95.0	22
3. PT1-3	70.2-83.1	-
4. PT1-4	74.2-81.7	-
5. PT1-5	79.8-88.4	6
6. PT1-6	59.0-83.8	-
7. BPA Silo	69.2-102.7	18
8. CO Unit	64.4-80.0	-
9. G Structure 1FL	71.2-82.1	-
10. G Structure 2FL	73.5-82.8	-
11. G Structure 3FL	70.2-77.7	-
12. G Structure 4FL	68.1-73.8	-
13. Tank Yard	67.1-78.8	-
14. P Structure 1FL	69.8-87.9	5
15. P Structure 2FL	71.4-87.6	3
16. P Structure 3FL	73.0-85.7	5
17. P Structure 4FL	78.2-92.5	9
18. P Structure 5FL	74.2-82.6	-
19. VP1 PC Silo	69.8-87.0	2
20. VP1 Utility Unit	69.2-96.7	8

ตารางที่ 5.2 ผลการตรวจวัดระดับเสียงภายในสถานประกอบการ โรงงานที่ 2 (TPCC 2) บริษัท ไทยโพลีคาร์บอเนต จำกัด ระหว่างวันที่ 20-21 กันยายน 2564

ตำแหน่งตรวจวัด	ระดับเสียงสูง-ต่ำ (เดซิเบลเอ)	จำนวนจุดที่มีค่ามากกว่าและเท่ากับ 85 เดซิเบลเอ
1. PT2-1	65.1-90.9	6
2. PT2-2	61.3-90.4	4
3. PT2-3	63.2-70.2	-
4. PT2-4	65.0-77.1	-
5. PT2-5	62.1-79.0	-
6. PT2-6	72.1-87.8	3
7. PT2-7	78.2-87.9	3
8. BPA Warehouse	62.1-84.9	-
9. CCR	67.2-76.0	-
10. CTY	69.1-86.0	2
11. Compressor Unit	59.0-79.1	-
12. Cooling	69.7-88.2	4
13. G Structure 1FL	72.2-85.2	1
14. G Structure 2FL	78.4-87.3	7
15. G Structure 3FL	73.1-87.3	2
16. G Structure 4FL	69.8-78.5	-
17. PC Silo	63.7-76.3	-
18. P Structure 1FL	69.5-78.3	-
19. P Structure 2FL	74.2-77.3	-
20. P Structure 3FL	74.4-86.7	2
21. P Structure 4FL	72.9-92.4	12
22. P Structure 5FL	64.2-83.9	-
23. P Structure 6FL	71.8-73.5	-
24. Tank Yard & Refrigerator	71.8-93.2	21

6. สรุปผลการตรวจวัดและข้อเสนอแนะ

จากการจัดทำแผนที่เส้นระดับเสียง (Noise Contour Map) บริษัท ไทยโพลีคาร์บอเนต จำกัด โดยตำแหน่งการตรวจวัดระหว่างวันที่ 20-21 กันยายน 2564 พบว่า พื้นที่ส่วนใหญ่มีค่าระดับเสียงต่ำกว่า 85 เดซิเบลเอ

ดังนั้น เพื่อความปลอดภัยในการปฏิบัติงานของพนักงาน สำหรับพื้นที่ที่มีค่าระดับเสียงสูงกว่า 85 เดซิเบลเอ โรงงานควรจัดให้มีอุปกรณ์คุ้มครองความปลอดภัยส่วนบุคคล ได้แก่ ปลั๊กลดเสียงหรือที่ครอบหูลดเสียงให้กับพนักงาน และกำหนดให้พนักงานมีการสวมใส่ปลั๊กลดเสียงหรือที่ครอบหูลดเสียงทุกครั้งที่เข้าไปปฏิบัติงานในบริเวณที่มีเสียงดัง และควรจัดให้มีเครื่องหมายเตือนให้ใช้อุปกรณ์คุ้มครองความปลอดภัยส่วนบุคคลติดไว้ให้พนักงานเห็นได้อย่างชัดเจน รวมทั้งควรมีการตรวจสอบหาสาเหตุที่ก่อให้เกิดเสียงดังและควบคุมที่ต้นกำเนิดเสียงหรือทางผ่านของเสียง หรือบริหารจัดการเพื่อควบคุมระดับเสียงที่พนักงานจะได้รับให้ไม่เกินมาตรฐานที่กำหนด ตามกฎกระทรวง เรื่อง กำหนดมาตรฐานในการบริหาร จัดการ และดำเนินการด้านความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงานเกี่ยวกับความร้อน แสงสว่าง และเสียง พ.ศ. 2556 และประกาศกรมสวัสดิการและคุ้มครองแรงงาน เรื่อง มาตรฐานระดับเสียงที่ยอมให้ลูกจ้างได้รับเฉลี่ยตลอดระยะเวลาการทำงานในแต่ละวัน พ.ศ. 2561 และประกาศกรมสวัสดิการและคุ้มครองแรงงาน เรื่อง หลักเกณฑ์และวิธีการจัดทำมาตรการคุ้มครองการทำงานในสถานประกอบกิจการ พ.ศ. 2561

ภาคผนวก ก

Noise Contour Map


Noise Contour Map : TPCC 1

Location : PT1-1

SGS

Noise Contour Map
Area : TPCC-PT1-1
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	274	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	50.4	dB(A)
	Max. Noise Level	82.5	dB(A)



SGS

Noise Contour Map
Area : TPCC-PT1-1
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	274	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	50.4	dB(A)
	Max. Noise Level	82.5	dB(A)




Location : PT1-2

SGS

Noise Contour Map
Area : TPCC-PT1-1
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	274	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	50.4	dB(A)
	Max. Noise Level	82.5	dB(A)



SGS


Noise Contour Map
Area : TPCC-PT1-2
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	95	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	63.3	dB(A)
	Max. Noise Level	95.0	dB(A)






Location : PT1-3



SGS

Noise Contour Map
Area : TPCC-PT1-3
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	24	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Anankorn Nanthasaeng	Min. Noise Level	70.2	dB(A)
	Max. Noise Level	83.1	dB(A)



SGS

Noise Contour Map
Area : TPCC-PT1-3
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	24	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Anankorn Nanthasaeng	Min. Noise Level	70.2	dB(A)
	Max. Noise Level	83.1	dB(A)




Location : PT1-4

SGS

Noise Contour Map
Area : TPCC-PT1-3
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	24	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Anankorn Nanthasaeng	Min. Noise Level	70.2	dB(A)
	Max. Noise Level	83.1	dB(A)



SGS

Noise Contour Map
Area : TPCC-PT1-4
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	34	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.2	dB(A)
	Max. Noise Level	81.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-PT1-4
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	34	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.2	dB(A)
	Max. Noise Level	81.7	dB(A)




Location : PT1-5

SGS

Noise Contour Map
Area : TPCC-PT1-4
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	34	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.2	dB(A)
	Max. Noise Level	81.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-PT1-5
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	25	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	79.8	dB(A)
	Max. Noise Level	88.4	dB(A)




SGS

Noise Contour Map
Area : TPCC-PT1-5
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	25	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	79.8	dB(A)
	Max. Noise Level	88.4	dB(A)






Location : PT1-6

SGS

Noise Contour Map
Area : TPCC-PT1-5
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	25	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	79.8	dB(A)
	Max. Noise Level	88.4	dB(A)



SGS

Noise Contour Map
Area : TPCC-PT1-6
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	26	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	59.0	dB(A)
	Max. Noise Level	83.8	dB(A)



SGS

Noise Contour Map
Area : TPCC-PT1-6
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	26	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	59.0	dB(A)
	Max. Noise Level	83.8	dB(A)




Location : BPA Silo

SGS

Noise Contour Map
Area : TPCC-PT1-6
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	26	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	59.0	dB(A)
	Max. Noise Level	83.8	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-BPA Silo
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	54	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.2	dB(A)
	Max. Noise Level	102.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-BPA Silo
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	54	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.2	dB(A)
	Max. Noise Level	102.7	dB(A)




Location : CO Unit

SGS

Noise Contour Map
Area : TPCC-VP1-BPA Silo
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	54	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.2	dB(A)
	Max. Noise Level	102.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-CO Unit
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	39	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	64.4	dB(A)
	Max. Noise Level	80.0	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-CO Unit
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	39	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	64.4	dB(A)
	Max. Noise Level	80.0	dB(A)




Location : GS1

SGS

Noise Contour Map
Area : TPCC-VP1-CO Unit
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	39	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	64.4	dB(A)
	Max. Noise Level	80.0	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP1-G Structure 1FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	104	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	71.2	dB(A)
	Max. Noise Level	82.1	dB(A)






Location : GS2

SGS

Noise Contour Map
Area : TPCC-VP1-G Structure 1FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	104	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	71.2	dB(A)
	Max. Noise Level	82.1	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP1-G Structure 2FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	50	Points
Contour Interval	3	dB(A)
Min. Noise Level	73.5	dB(A)
Max. Noise Level	82.8	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP1-G Structure 2FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	50	Points
Contour Interval	3	dB(A)
Min. Noise Level	73.5	dB(A)
Max. Noise Level	82.8	dB(A)




Location : GS3

SGS

Noise Contour Map
Area : TPCC-VP1-G Structure 2FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat


Total Measured Point	50	Points
Contour Interval	3	dB(A)
Min. Noise Level	73.5	dB(A)
Max. Noise Level	82.8	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-G Structure 3FL
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	42	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	70.2	dB(A)
	Max. Noise Level	77.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-G Structure 3FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	42	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	70.2	dB(A)
	Max. Noise Level	77.7	dB(A)




Location : GS4

SGS

Noise Contour Map
Area : TPCC-VP1-G Structure 3FL
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	42	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	70.2	dB(A)
	Max. Noise Level	77.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-G Structure 4FL
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	18	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	68.1	dB(A)
	Max. Noise Level	73.8	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-G Structure 4FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	18	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	68.1	dB(A)
	Max. Noise Level	73.8	dB(A)




Location : TY

SGS

Noise Contour Map
Area : TPCC-VP1-G Structure 4FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	18	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	68.1	dB(A)
	Max. Noise Level	73.8	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP1-G Hazardous Tank Yard
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	39	Points
Contour Interval	3	dB(A)
Min. Noise Level	67.1	dB(A)
Max. Noise Level	78.8	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP1-G Hazardous Tank Yard
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	39	Points
Contour Interval	3	dB(A)
Min. Noise Level	67.1	dB(A)
Max. Noise Level	78.8	dB(A)




Location : PS1

SGS

Noise Contour Map
Area : TPCC-VP1-G Hazardous Tank Yard
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat


Total Measured Point	39	Points
Contour Interval	3	dB(A)
Min. Noise Level	67.1	dB(A)
Max. Noise Level	78.8	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 1FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	92	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.8	dB(A)
	Max. Noise Level	87.9	dB(A)






Location : PS2

SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 1FL
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	92	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.8	dB(A)
	Max. Noise Level	87.9	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 2FL
THAI POLYCARBONATE COMPANY LIMITED


Report No. September 20-21, 2021	Total Measured Point	58	Points
Measurement Date : 2021-5002540-3	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	71.4	dB(A)
	Max. Noise Level	87.6	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 2FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. September 20-21, 2021	Total Measured Point	58	Points
Measurement Date : 2021-5002540-3	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	71.4	dB(A)
	Max. Noise Level	87.6	dB(A)




Location : PS3

SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 2FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. September 20-21, 2021	Total Measured Point	58	Points
Measurement Date : 2021-5002540-3	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	71.4	dB(A)
	Max. Noise Level	87.6	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 3FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	41	Points
Contour Interval	3	dB(A)
Min. Noise Level	73.0	dB(A)
Max. Noise Level	85.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 3FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	41	Points
Contour Interval	3	dB(A)
Min. Noise Level	73.0	dB(A)
Max. Noise Level	85.7	dB(A)




Location : PS4

SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 3FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat


Total Measured Point	41	Points
Contour Interval	3	dB(A)
Min. Noise Level	73.0	dB(A)
Max. Noise Level	85.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 4FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	35	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	78.2	dB(A)
	Max. Noise Level	92.5	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 4FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	35	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	78.2	dB(A)
	Max. Noise Level	92.5	dB(A)




Location : PS5

SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 4FL
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	35	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	78.2	dB(A)
	Max. Noise Level	92.5	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 5FL
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	20	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.2	dB(A)
	Max. Noise Level	82.6	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 5FL
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	20	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.2	dB(A)
	Max. Noise Level	82.6	dB(A)




Location : VP1 PC Silo

SGS

Noise Contour Map
Area : TPCC-VP1-P Structure 5FL
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	20	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.2	dB(A)
	Max. Noise Level	82.6	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-PC Silo
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	50	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.8	dB(A)
	Max. Noise Level	87.0	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-PC Silo
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	50	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.8	dB(A)
	Max. Noise Level	87.0	dB(A)




Location : VP1 Utility

SGS

Noise Contour Map
Area : TPCC-VP1-PC Silo
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	50	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.8	dB(A)
	Max. Noise Level	87.0	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-Utility Unit
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	61	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.2	dB(A)
	Max. Noise Level	96.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP1-Utility Unit
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	61	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.2	dB(A)
	Max. Noise Level	96.7	dB(A)




Noise Contour Map : TPCC 2

SGS

Noise Contour Map
Area : TPCC-VP1-Utility Unit
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	61	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.2	dB(A)
	Max. Noise Level	96.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-PT2-1
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	68	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	65.1	dB(A)
	Max. Noise Level	90.9	dB(A)






Location : PT2-1

SGS

Noise Contour Map
Area : TPCC-PT2-1
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point 68 Points
Contour Interval 3 dB(A)
Min. Noise Level 65.1 dB(A)
Max. Noise Level 90.9 dB(A)




SGS

Noise Contour Map
Area : TPCC-PT2-1
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point 68 Points
Contour Interval 3 dB(A)
Min. Noise Level 65.1 dB(A)
Max. Noise Level 90.9 dB(A)




SGS

Noise Contour Map
Area : TPCC-PT2-2
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	60	Points
Contour Interval	3	dB(A)
Min. Noise Level	61.3	dB(A)
Max. Noise Level	90.4	dB(A)




Location : PT2-2

SGS

Noise Contour Map
Area : TPCC-PT2-2
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	60	Points
Contour Interval	3	dB(A)
Min. Noise Level	61.3	dB(A)
Max. Noise Level	90.4	dB(A)




SGS

Noise Contour Map
Area : TPCC-PT2-2
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	60	Points
Contour Interval	3	dB(A)
Min. Noise Level	61.3	dB(A)
Max. Noise Level	90.4	dB(A)





SGS

Noise Contour Map
Area : TPCC-PT2-3
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	16	Points
Contour Interval	3	dB(A)
Min. Noise Level	63.2	dB(A)
Max. Noise Level	70.2	dB(A)





Location : PT2-3


SGS

Noise Contour Map
Area : TPCC-PT2-3
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	16	Points
Contour Interval	3	dB(A)
Min. Noise Level	63.2	dB(A)
Max. Noise Level	70.2	dB(A)






SGS

Noise Contour Map
Area : TPCC-PT2-3
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	16	Points
Contour Interval	3	dB(A)
Min. Noise Level	63.2	dB(A)
Max. Noise Level	70.2	dB(A)






SGS

Noise Contour Map
Area : TPCC-PT2-4
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	23	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	65.0	dB(A)
	Max. Noise Level	77.1	dB(A)




Location : PT2-4

SGS

Noise Contour Map
Area : TPCC-PT2-4
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point 23 Points
Contour Interval 3 dB(A)
Min. Noise Level 65.0 dB(A)
Max. Noise Level 77.1 dB(A)





SGS

Noise Contour Map
Area : TPCC-PT2-4
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point 23 Points
Contour Interval 3 dB(A)
Min. Noise Level 65.0 dB(A)
Max. Noise Level 77.1 dB(A)






SGS

Noise Contour Map
Area : TPCC-PT2-5
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	56	Points
Contour Interval	3	dB(A)
Min. Noise Level	62.1	dB(A)
Max. Noise Level	79.0	dB(A)




Location : PT2-5

SGS

Noise Contour Map
Area : TPCC-PT2-5
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	56	Points
Contour Interval	3	dB(A)
Min. Noise Level	62.1	dB(A)
Max. Noise Level	79.0	dB(A)




SGS

Noise Contour Map
Area : TPCC-PT2-5
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	56	Points
Contour Interval	3	dB(A)
Min. Noise Level	62.1	dB(A)
Max. Noise Level	79.0	dB(A)





SGS

Noise Contour Map
Area : TPCC-PT2-6
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	24	Points
Contour Interval	3	dB(A)
Min. Noise Level	72.1	dB(A)
Max. Noise Level	87.8	dB(A)






SGS

Noise Contour Map
Area : TPCC-PT2-6
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	24	Points
Contour Interval	3	dB(A)
Min. Noise Level	72.1	dB(A)
Max. Noise Level	87.8	dB(A)




SGS

Noise Contour Map
Area : TPCC-PT2-6
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	24	Points
Contour Interval	3	dB(A)
Min. Noise Level	72.1	dB(A)
Max. Noise Level	87.8	dB(A)





SGS

Noise Contour Map
Area : TPCC-PT2-7
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	17	Points
Contour Interval	3	dB(A)
Min. Noise Level	78.2	dB(A)
Max. Noise Level	87.9	dB(A)






SGS

Noise Contour Map
Area : TPCC-PT2-7
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	17	Points
Contour Interval	3	dB(A)
Min. Noise Level	78.2	dB(A)
Max. Noise Level	87.9	dB(A)




SGS

Noise Contour Map
Area : TPCC-PT2-7
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	17	Points
Contour Interval	3	dB(A)
Min. Noise Level	78.2	dB(A)
Max. Noise Level	87.9	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-BPA Warehouse
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	55	Points
Contour Interval	3	dB(A)
Min. Noise Level	62.1	dB(A)
Max. Noise Level	84.9	dB(A)




Location : BPA Warehouse

SGS

Noise Contour Map
Area : TPCC-VP2-BPA Warehouse
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	55	Points
Contour Interval	3	dB(A)
Min. Noise Level	62.1	dB(A)
Max. Noise Level	84.9	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-BPA Warehouse
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat


Total Measured Point	55	Points
Contour Interval	3	dB(A)
Min. Noise Level	62.1	dB(A)
Max. Noise Level	84.9	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-CCR
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	48	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	67.2	dB(A)
	Max. Noise Level	76.0	dB(A)






SGS

Noise Contour Map
Area : TPCC-VP2-CCR
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	48	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	67.2	dB(A)
	Max. Noise Level	76.0	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-CCR
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	48	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	67.2	dB(A)
	Max. Noise Level	76.0	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-Chemical Tank Yard
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	41	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.1	dB(A)
	Max. Noise Level	86.0	dB(A)






SGS

Noise Contour Map
Area : TPCC-VP2-Chemical Tank Yard
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	41	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.1	dB(A)
	Max. Noise Level	86.0	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-Chemical Tank Yard
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	41	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.1	dB(A)
	Max. Noise Level	86.0	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-Compressor Unit
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	37	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	59.0	dB(A)
	Max. Noise Level	79.1	dB(A)




Location : Compressor Unit

SGS

Noise Contour Map
Area : TPCC-VP2-Compressor Unit
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	37	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	59.0	dB(A)
	Max. Noise Level	79.1	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-Compressor Unit
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	37	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	59.0	dB(A)
	Max. Noise Level	79.1	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-Cooling
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	46	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.7	dB(A)
	Max. Noise Level	88.2	dB(A)




Location : Cooling

SGS

Noise Contour Map
Area : TPCC-VP2-Cooling
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	46	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.7	dB(A)
	Max. Noise Level	88.2	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-Cooling
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	46	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.7	dB(A)
	Max. Noise Level	88.2	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 1 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	69	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	72.2	dB(A)
	Max. Noise Level	85.2	dB(A)






SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 1 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	69	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	72.2	dB(A)
	Max. Noise Level	85.2	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 1 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	69	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	72.2	dB(A)
	Max. Noise Level	85.2	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 2 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	33	Points
Contour Interval	3	dB(A)
Min. Noise Level	78.4	dB(A)
Max. Noise Level	87.3	dB(A)




Location : GS2

SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 2 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	33	Points
Contour Interval	3	dB(A)
Min. Noise Level	78.4	dB(A)
Max. Noise Level	87.3	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 2 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat


Total Measured Point	33	Points
Contour Interval	3	dB(A)
Min. Noise Level	78.4	dB(A)
Max. Noise Level	87.3	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 3 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	32	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	73.1	dB(A)
	Max. Noise Level	87.3	dB(A)




Location : GS3

SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 3 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	32	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	73.1	dB(A)
	Max. Noise Level	87.3	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 3 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	32	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	73.1	dB(A)
	Max. Noise Level	87.3	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 4 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	10	Points
Contour Interval	3	dB(A)
Min. Noise Level	69.8	dB(A)
Max. Noise Level	78.5	dB(A)




Location : GS4

SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 4 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat

Total Measured Point	10	Points
Contour Interval	3	dB(A)
Min. Noise Level	69.8	dB(A)
Max. Noise Level	78.5	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-G-Structure 4 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3
Measurement Date : September 20-21, 2021
Measured By : Phatsakorn Soonthornwiphat


Total Measured Point	10	Points
Contour Interval	3	dB(A)
Min. Noise Level	69.8	dB(A)
Max. Noise Level	78.5	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-PC-Silo
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	44	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	63.7	dB(A)
	Max. Noise Level	76.3	dB(A)




Location : PC Silo

SGS

Noise Contour Map
Area : TPCC-VP2-PC-Silo
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	44	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	63.7	dB(A)
	Max. Noise Level	76.3	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-PC-Silo
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	44	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	63.7	dB(A)
	Max. Noise Level	76.3	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 1 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	57	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.5	dB(A)
	Max. Noise Level	78.3	dB(A)






SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 1 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	57	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.5	dB(A)
	Max. Noise Level	78.3	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 1 FI
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	57	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	69.5	dB(A)
	Max. Noise Level	78.3	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 2 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	27	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.2	dB(A)
	Max. Noise Level	77.3	dB(A)






SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 2 FI
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	27	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.2	dB(A)
	Max. Noise Level	77.3	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 2 FI
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	27	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.2	dB(A)
	Max. Noise Level	77.3	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 3 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	27	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.4	dB(A)
	Max. Noise Level	86.7	dB(A)




Location : PS3

SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 3 FI
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	27	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.4	dB(A)
	Max. Noise Level	86.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 3 FI
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	27	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	74.4	dB(A)
	Max. Noise Level	86.7	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 4 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	24	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	72.9	dB(A)
	Max. Noise Level	92.4	dB(A)




Location : PS4

SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 4 FI
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	24	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	72.9	dB(A)
	Max. Noise Level	92.4	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 4 FI
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	24	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	72.9	dB(A)
	Max. Noise Level	92.4	dB(A)




SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 5 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	22	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	64.2	dB(A)
	Max. Noise Level	83.9	dB(A)






SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 5 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	22	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	64.2	dB(A)
	Max. Noise Level	83.9	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 5 FI
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	22	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	64.2	dB(A)
	Max. Noise Level	83.9	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 6 FI
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	6	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	71.8	dB(A)
	Max. Noise Level	73.5	dB(A)




Location : PS6

SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 6 FI
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	6	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	71.8	dB(A)
	Max. Noise Level	73.5	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-P-Structure 6 FI
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	6	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	71.8	dB(A)
	Max. Noise Level	73.5	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-Tank Yard & Refrigerator
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	90	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	71.8	dB(A)
	Max. Noise Level	93.2	dB(A)




Location : TYR

SGS

Noise Contour Map
Area : TPCC-VP2-Tank Yard & Refrigerator
THAI POLYCARBONATE COMPANY LIMITED


Report No. 2021-5002540-3	Total Measured Point	90	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	71.8	dB(A)
	Max. Noise Level	93.2	dB(A)



SGS

Noise Contour Map
Area : TPCC-VP2-Tank Yard & Refrigerator
THAI POLYCARBONATE COMPANY LIMITED

Report No. 2021-5002540-3	Total Measured Point	90	Points
Measurement Date : September 20-21, 2021	Contour Interval	3	dB(A)
Measured By : Phatsakorn Soonthornwiphat	Min. Noise Level	71.8	dB(A)
	Max. Noise Level	93.2	dB(A)



เอกสารแนบที่ 43

การตรวจวัดเสียงโดย Personal Dosimeter ประจำปี 2567

ผลการตรวจวัดปริมาณเสียงสะสมติดตัวบุคคล (Noise Dose) ตลอดระยะเวลาทำงาน 12 ชั่วโมงระหว่างเดือน มกราคม-มิถุนายน 2567

ตำแหน่ง	ชื่อ-สกุล	วันที่ตรวจ	เวลา	ผลการตรวจวัด TWA Sound Level [dB (A)]*	ผลการคำนวนจากที่พนักงานสวมใส่อุปกรณ์ลดเสียง		
					Sound Level [dB (A)]*	NRR_{adj} [dB (A)]**	Protected [dB (A)][4]
PT1-Additive	นาย คุณเมธา ศรีรัตน์	18/06/2567	8.30-17.30	88.5	88.5	13.25	75.25
VP1-Shift Supervisor	นาย นาท จักนามน	17/06/2567	7.00-19.00	78.3	78.3	13.25	65.05
VP1-UT	นาย สุริยา นนทรีย์	17/06/2567	7.00-19.00	77.9	77.9	13.25	64.65
VP1-GS	นาย ศรชัย แดงจันทร์	17/06/2567	7.00-19.00	76.6	76.6	13.25	63.35
VP1-ATR	นาย สุรศักดิ์ หรือสุวรรณ	17/06/2567	7.00-19.00	88.5	88.5	13.25	75.25
VP1-CO&Waste	นาย ธเรศ ห้าวหาญ	17/06/2567	7.00-19.00	79.6	79.6	13.25	66.35
PT1-Ex1	นาย ไชยิน	17/06/2567	7.00-19.00	89.5	89.5	13.25	76.25
PT1-Ex2	นาย สหรัฐ สุขเจริญ	17/06/2567	7.00-19.00	88.2	88.2	13.25	74.95
PT1-UT	นาย สามารถ	17/06/2567	7.00-19.00	89.7	89.7	13.25	76.45
VP1-BPA	นาย วิรัตน์	18/06/2567	7.00-19.00	78.4	78.4	13.25	65.15
PT1-Shift Supervisor	นาย ปัญญวัฒน์	18/06/2567	7.00-19.00	78.9	78.9	13.25	65.65
PK1-Leade	นาย สมภพ ไทยประโดน	18/06/2567	7.00-19.00	86.4	86.4	13.25	73.15
PK1-Clean Room	นาย คุณแสงรัตน์ กู่พึ่ง	18/06/2567	7.00-19.00	80.3	80.3	13.25	67.05
PK1-Pellet	นาย ภาณุพงศ์ จันทะแสน	18/06/2567	7.00-19.00	80.7	80.7	13.25	67.45
PK1-Sample	นาย จักรี	18/06/2567	7.00-19.00	78.4	78.4	13.25	65.15
PK1-Forklift	นาย พิชิต	18/06/2567	7.00-19.00	76.7	76.7	13.25	63.45
VP2-Shift Supervisor	นาย ประดิษฐ์ สังข์ทองคำ	19/06/2567	7.00-19.00	77.2	77.2	13.25	63.95
VP2-UT	นาย สุเทพ ศรีเกา	19/06/2567	7.00-19.00	84.8	84.8	13.25	71.55
VP2-GS	นาย ประดิษฐา	19/06/2567	7.00-19.00	84.2	84.2	13.25	70.95
VP2-PS	นาย บัณฑิต	19/06/2567	7.00-19.00	83.8	83.8	13.25	70.55
VP2-ATR	นาย วีระยุทธ บัวเขียว	19/06/2567	7.00-19.00	86.7	86.7	13.25	73.45
PT2-Shift Supervisor	นาย สามารถ	19/06/2567	7.00-19.00	73.4	73.4	13.25	60.15
PT2-UT	นาย นะเรณ หายโศรก	19/06/2567	7.00-19.00	77.7	77.7	13.25	64.45
PT2-Adtitive	นาย ปริวรรธ	19/06/2567	7.00-19.00	75.6	75.6	13.25	62.35
PK2-Leader	นาย ชยพล	19/06/2567	7.00-19.00	77.8	77.8	13.25	64.55
PK2-Line K	นาย นพรัตน์ เอี่ยมสะอาด	19/06/2567	7.00-19.00	84.1	84.1	13.25	70.85
PK2-Line K	นาย ชินวุฒ ศรีสุภาพ	19/06/2567	7.00-19.00	84.1	84.1	13.25	70.85
PK2-M60	นาย ชัยชนะ เถาถาวงษ์	19/06/2567	7.00-19.00	84.0	84.0	13.25	70.75
PK2-Fake	นาย ประชา บุญสุข	19/06/2567	7.00-19.00	81.5	81.5	13.25	68.25
ค่ามาตรฐาน				≤83	-	-	≤83

มาตรฐาน: ประกาศกรมสวัสดิการและคุ้มครองแรงงาน เรื่อง มาตรฐานระดับเสียงที่ยอมให้ลูกจ้างได้รับเฉลี่ยตลอดระยะเวลาทำงานในแต่ละวัน (Time Weight Average) และประกาศกรมสวัสดิการและคุ้มครองแรงงาน เรื่อง การคำนวนระดับเสียงที่สัมผัสในหูเมื่อสวมใส่อุปกรณ์คุ้มครองความปลอดภัยส่วนบุคคล พ.ศ. 2561

TWA Sound Level (dB (A)): * ผลการตรวจวัดปริมาณเสียงสะสมติดตัวบุคคล (ที่พนักงานได้รับหากไม่มีการสวมใส่อุปกรณ์ลดเสียง)

NRR_{adj}: ** ค่าการลดเสียงที่ระบุไว้บนฉลากหรืออุปกรณ์คุ้มครองความปลอดภัยส่วนบุคคล โดยค่า Noise Reduction Rating (NRR) เท่ากับ 27 dB(A) ซึ่งร้อยละ 25 ของค่าลดเสียงคือ 13.25 dB(A) โดยอุปกรณ์คุ้มครองความปลอดภัยส่วนบุคคลที่พนักงานใช้คือที่ครอบหู (ผู้ผลิต บริษัท 3 เอ็ม ประเทศไทย จำกัด รุ่น Optime 105 (H10P3E))

Protected (dB (A)): ระดับเสียงที่สัมผัสในหูเมื่อสวมใส่อุปกรณ์คุ้มครองความปลอดภัยส่วนบุคคลในสเกลเอ (Scale A) หรือ เดซิเบล เอ (dB(A)

สูตรการคำนวนค่า Protected (dB (A)) = Sound Level (dB (A)) – [NRR_{adj} – 7]

บริษัทผู้ทำการตรวจวัดและวิเคราะห์ : บริษัท เอส จี เอส ประเทศไทย จำกัด

เอกสารแนบที่ 44

บันทึกชนิดและปริมาณที่เข้าสู่พื้นที่โรงงาน

เอกสารปริมาณรถยนต์เข้า-ออกพื้นที่

บริษัท ไทยไพลีอะซิทัล จำกัด และ บริษัท ไทยไพลีคาร์บอเนต จำกัด

ประจำปี 2567

เอกที่	ชนิดยานพาหนะ	ปริมาณรถยนต์เข้าออกประจำปี 2567												ออกเฉลี่ย	ออกเฉลี่ย
		ม.ค.	ก.พ.	มี.ค.	เม.ย.	พ.ค.	มิ.ย.	ก.ค.	ส.ค.	ก.ย.	ต.ค.	พ.ย.	ธ.ค.	เที่ยว / เดือน	เที่ยว / วัน
1	รถบรรทุก BPA (Bulk)	712	627	670	624	651	661							329	10
2	รถรับสินค้า ชนิด เทลเลอร์	222	236	234	232	254	220							117	4
3	รถย้ายสินค้า คอนเทนเนอร์	630	571	589	772	805	824							350	11
4	รถส่งสารเคมี	39	36	32	45	44	60							22	1
5	รถขนส่ง waste	63	62	56	46	48	60							28	1
6	อื่นๆ	201	219	213	193	198	210							103	4
รวมทั้งหมด		1867	1751	1794	1912	2000	2035	0	0	0	0	0	0	949	31

เอกสารปริมาณรถเข้า-ออกพื้นที่ประจำเดือน : _____ ประจำปี 25__

ลำดับ	ชนิดยานพาหนะ	วันที่																													รวม
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
1	รถบรรทุก BPA (Bulk)																																
2	รถรับสินค้าชนิดเทลเลอร์																																
3	รถย้ายสินค้าชนิดคอนเทรนเนอร์																																
4	รถส่งสารเคมี																																
5	รถขนส่ง Waste																																
6	อื่นๆ																																
รวม																																	

ผู้จัดทำ : Miss Nannapas Saesom

Information Security

ผู้ตรวจสอบ : Chanitsara N.

SHE

เอกสารปริมาณรถเข้า-ออกพื้นที่ประจำเดือน : _____ ประจำปี 25__

ลำดับ	ชนิดยานพาหนะ	วันที่																													รวม
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
1	รถบรรทุก BPA (Bulk)																																
2	รถรับสินค้าชนิดเทลเลอร์																																
3	รถย้ายสินค้าชนิดคอนเทรนเนอร์																																
4	รถส่งสารเคมี																																
5	รถขนส่ง Waste																																
6	อื่นๆ																																
รวม																																	

ผู้จัดทำ : Miss Nannapas Saesom

Information Security

ผู้ตรวจสอบ : Chanitsara N.

SHE

เอกสารปริมาณรถเข้า-ออกพื้นที่ประจำเดือน : _____ ประจำปี 25__

ลำดับ	ชนิดยานพาหนะ	วันที่																													รวม
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
1	รถบรรทุก BPA (Bulk)																																
2	รถรับสินค้าชนิดเทลเลอร์																																
3	รถย้ายสินค้าชนิดคอนเทรนเนอร์																																
4	รถส่งสารเคมี																																
5	รถขนส่ง Waste																																
6	อื่นๆ																																
รวม																																	

Chanitsara N.

เอกสารปริมาณรถเข้า-ออกพื้นที่ประจำเดือน : _____ ประจำปี 25__

ลำดับ	ชนิดยานพาหนะ	วันที่																													รวม
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
1	รถบรรทุก BPA (Bulk)																																
2	รถรับสินค้าชนิดเทลเลอร์																																
3	รถย้ายสินค้าชนิดคอนเทรนเนอร์																																
4	รถส่งสารเคมี																																
5	รถขนส่ง Waste																																
6	อื่นๆ																																
รวม																																	

Chanitsara N.

เอกสารปริมาณรถเข้า-ออกพื้นที่ประจำเดือน : _____ ประจำปี 25__

ลำดับ	ชนิดยานพาหนะ	วันที่																													รวม
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
1	รถบรรทุก BPA (Bulk)																																
2	รถรับสินค้าชนิดเทลเลอร์																																
3	รถย้ายสินค้าชนิดคอนเทรนเนอร์																																
4	รถส่งสารเคมี																																
5	รถขนส่ง Waste																																
6	อื่นๆ																																
รวม																																	

Chanitsara N.

เอกสารแนบที่ 45

ตัวอย่างใบตรวจสอบยานพาหนะเข้า-ออกโครงการ

บริษัท ไทยโพลีอะซีทัล จำกัด
THAI POLYACETAL CO., LTD.

บริษัท ไทยโพลีคาร์บอเนต จำกัด
THAI POLYCARBONATE CO., LTD.

เล่มที่ 050 **ใบตรวจสอบยานพาหนะ เข้า - ออก (ป้อม2)** เลขที่ 04985

ประเภท ☐ รถ BPA ☐ รถขนส่งสารเคมี ☐ รถรับ-ส่งสินค้า ☐ รถเสียบ ☐ รถเครน
☑ รถหกล้อ ☐ รถสิบล้อ ☑ รถส่งพาเลท ☐ รถอื่นๆ

วันที่ 25/5/14 บริษัท NPC ทะเบียน 69-6964 เวลาเข้า 08/10 น.

สถานที่ส่งของ : ☐ ซ่อมบำรุง ☐ อาคารบริหาร ☐ TPAC ☑ TPCC1 ☐ TPCC2 ☐ WH1 ☐ WH2

สภาพทั่วไปของรถ	เข้า / ออก: เรียบร้อย	เข้า / ออก: ไม่เรียบร้อย	ระบุรายละเอียด
1. สภาพยานพาหนะ (Vehicle)			
1.1 มีน้ำมันเครื่องหรือสารเคมีรั่วไหลหรือไม่?	✓		
1.2 รถที่ใช้เชื้อเพลิง NGV มีใบอนุญาตรับรองผ่านการตรวจสภาพถูกต้องหรือไม่?			ใบอนุญาตการตรวจสภาพหมดอายุหรือไม่?
1.3 ประตูตู้สินค้า หรือ แผงกั้นกันของตก ปิดสนิทหรือไม่?	✓		
1.4 สวมท่อป้องกันประกายไฟ	✓		
1.5 ใบอนุญาตทะเบียนและประกันภัย พ.ร.บ. หมดอายุหรือไม่?	✓		
1.6 ตรวจสอบหาระเบิด / วัตถุต้องสงสัยภายในรถ / ใต้ท้องรถ	✓		พบเห็นสิ่งผิดปกติแจ้ง 1301 - 1309 ทันที
2. พนักงานขับรถ (Driver)			
2.1 แต่งกายสุภาพเรียบร้อย ไม่มีอาการเมาสุราหรืออาการผิดปกติ	✓		
2.2 ใบอนุญาตขับขี่ถูกต้องหรือไม่ / หมดอายุหรือไม่?	✓		(รถขนส่งสารเคมี ใบขับขี่ประเภท 4)
2.3 บัตรผ่านการอบรม (กรณีขนส่งสารเคมีเข้าพื้นที่การผลิต) หมดอายุหรือไม่?	✓		(ตรวจสอบบัตรผ่านการอบรมฯ)
2.4 มีอุปกรณ์ป้องกันอันตรายครบถ้วน (หมวก,แว่นตา,รองเท้า)	✓		
2.5 ฝากบุหรี่และไฟแช็กไว้ที่ป้อมรักษาการ			
[redacted]			

3. การตรวจสอบรถขนส่งสินค้า, สารเคมี, รถขนย้าย, รถ BPA และอื่นๆ (เจ้าหน้าที่ของฝ่ายคลังสินค้ากำหนดหัวข้อในการตรวจสอบดังนี้)	รถออก: เรียบร้อย	รถออก: ไม่เรียบร้อย	ระบุรายละเอียด
☐ ภายในห้องคนขับ (มีสิ่งของ, สินค้า หรือวัสดุอื่นๆ ของบริษัทฯ ติดมาหรือไม่?)			
☐ ตรวจซีลล็อกประตูตู้สินค้า (ต้องอยู่ในสภาพที่ดีไม่มีร่องรอยการงัดแงะ)			
☐ ตรวจภายในตู้คอนเทนเนอร์ (มีสิ่งของ, สินค้า / วัสดุอื่นๆ ของบริษัทติดมาหรือไม่?)			
☐ ตรวจตู้สินค้าภายนอก (ต้องปิดล็อกเรียบร้อยและแน่นหนาทุกจุด)			
☐ ตรวจนับจำนวนสิ่งของออก (สิ่งของออกมีจำนวนตรงกับใบของออกหรือไม่?)			
[redacted]			

หมายเหตุ :
1. รถเข้า : กรณีที่ตรวจสอบแล้วพบว่าไม่เรียบร้อย ไม่อนุญาตให้รถเข้ามาในเขตบริษัท หนักงาน รปภ. ไทรแจ้งไปฝ่ายที่เกี่ยวข้องทันที
2. รถออก : - กรณีที่ไม่มีลายมือผู้ตรวจสอบของหนักงานบริษัท TPAC & TPCC / Sankyu ไม่อนุญาตให้รถออกโดยเด็ดขาด ไทรแจ้งไปฝ่ายที่เกี่ยวข้องทันที
- - กรณีตรวจสอบพบว่ามีสินค้า, สิ่งของของบริษัทฯ ติดมา หนักงาน รปภ. ไทรแจ้งไปยังเจ้าหน้าที่ของ WH ที่เกี่ยวข้องทันที
3. พบเห็นสิ่งผิดปกติ แจ้ง 1301 - 1309 ทันที

3SE-F081(0)

บริษัท ไทยโพลีอะซีทัล จำกัด
THAI POLYACETAL CO., LTD.

บริษัท ไทยโพลีคาร์บอเนต จำกัด
THAI POLYCARBONATE CO., LTD.

เล่มที่ 028 **ใบตรวจสอบยานพาหนะ เข้า - ออก (ป้อม2)** เลขที่ 02782

ประเภท ☑ รถ BPA ☐ รถขนส่งสารเคมี ☐ รถรับ-ส่งสินค้า ☐ รถเสียบ ☐ รถเครน
☐ รถหกล้อ ☐ รถสิบล้อ ☐ รถส่งพาเลท ☐ รถอื่นๆ

วันที่ 04/01/67 บริษัท PTT ทะเบียน 73-4540 เวลาเข้า 19/00 น.

สถานที่ส่งของ : ☐ ซ่อมบำรุง ☐ อาคารบริหาร ☐ TPAC ☑ TPCC1 ☐ TPCC2 ☐ WH1 ☐ WH2

สภาพทั่วไปของรถ	เข้า / ออก: เรียบร้อย	เข้า / ออก: ไม่เรียบร้อย	ระบุรายละเอียด
1. สภาพยานพาหนะ (Vehicle)			
1.1 มีน้ำมันเครื่องหรือสารเคมีรั่วไหลหรือไม่?			
1.2 รถที่ใช้เชื้อเพลิง NGV มีใบอนุญาตรับรองผ่านการตรวจสภาพถูกต้องหรือไม่?			ใบอนุญาตการตรวจสภาพหมดอายุหรือไม่?
1.3 ประตูตู้สินค้า หรือ แผงกั้นกันของตก ปิดสนิทหรือไม่?			
1.4 สวมท่อป้องกันประกายไฟ			
1.5 ใบอนุญาตทะเบียนและประกันภัย พ.ร.บ. หมดอายุหรือไม่?			
1.6 ตรวจสอบหาระเบิด / วัตถุต้องสงสัยภายในรถ / ใต้ท้องรถ			พบเห็นสิ่งผิดปกติแจ้ง 1301 - 1309 ทันที
2. พนักงานขับรถ (Driver)			
2.1 แต่งกายสุภาพเรียบร้อย ไม่มีอาการเมาสุราหรืออาการผิดปกติ			
2.2 ใบอนุญาตขับขี่ถูกต้องหรือไม่ / หมดอายุหรือไม่?			(รถขนส่งสารเคมี ใบขับขี่ประเภท 4)
2.3 บัตรผ่านการอบรม (กรณีขนส่งสารเคมีเข้าพื้นที่การผลิต) หมดอายุหรือไม่?			(ตรวจสอบบัตรผ่านการอบรมฯ)
2.4 มีอุปกรณ์ป้องกันอันตรายครบถ้วน (หมวก,แว่นตา,รองเท้า)			
2.5 ฝากบุหรี่และไฟแช็กไว้ที่ป้อมรักษาการ			
[redacted]			

3. การตรวจสอบรถขนส่งสินค้า, สารเคมี, รถขนย้าย, รถ BPA และอื่นๆ (เจ้าหน้าที่ของฝ่ายคลังสินค้ากำหนดหัวข้อในการตรวจสอบดังนี้)	รถออก: เรียบร้อย	รถออก: ไม่เรียบร้อย	ระบุรายละเอียด
☑ ภายในห้องคนขับ (มีสิ่งของ, สินค้า หรือวัสดุอื่นๆ ของบริษัทฯ ติดมาหรือไม่?)	✓		
☐ ตรวจซีลล็อกประตูตู้สินค้า (ต้องอยู่ในสภาพที่ดีไม่มีร่องรอยการงัดแงะ)			
☐ ตรวจภายในตู้คอนเทนเนอร์ (มีสิ่งของ, สินค้า / วัสดุอื่นๆ ของบริษัทติดมาหรือไม่?)			
☑ ตรวจตู้สินค้าภายนอก (ต้องปิดล็อกเรียบร้อยและแน่นหนาทุกจุด)	✓		
☐ ตรวจนับจำนวนสิ่งของออก (สิ่งของออกมีจำนวนตรงกับใบของออกหรือไม่?)			
[redacted]			

หมายเหตุ :
1. รถเข้า : กรณีที่ตรวจสอบแล้วพบว่าไม่เรียบร้อย ไม่อนุญาตให้รถเข้ามาในเขตบริษัท หนักงาน รปภ. ไทรแจ้งไปฝ่ายที่เกี่ยวข้องทันที
2. รถออก : - กรณีที่ไม่มีลายมือผู้ตรวจสอบของหนักงานบริษัท TPAC & TPCC / Sankyu ไม่อนุญาตให้รถออกโดยเด็ดขาด ไทรแจ้งไปฝ่ายที่เกี่ยวข้องทันที
- - กรณีตรวจสอบพบว่ามีสินค้า, สิ่งของของบริษัทฯ ติดมา หนักงาน รปภ. ไทรแจ้งไปยังเจ้าหน้าที่ของ WH ที่เกี่ยวข้องทันที
3. พบเห็นสิ่งผิดปกติ แจ้ง 1301 - 1309 ทันที

3SE-F081(0)

บริษัท ไทยโพลีอะซีทัล จำกัด
THAI POLYACETAL CO., LTD.

บริษัท ไทยโพลีคาร์บอเนต จำกัด
THAI POLYCARBONATE CO., LTD.

เล่มที่ 029 **ใบตรวจสอบยานพาหนะ เข้า - ออก (ป้อม2)** เลขที่ 02852

ประเภท ☐ รถ BPA ☐ รถขนส่งสารเคมี ☐ รถรับ-ส่งสินค้า ☐ รถเสียบ ☐ รถเครน
☑ รถหกล้อ ☐ รถสิบล้อ ☐ รถส่งพาเลท ☐ รถอื่นๆ

วันที่ 10 ม.ค. 67 บริษัท NPR. ทะเบียน 83 1218 เวลาเข้า 08-40 น.

สถานที่ส่งของ : ☐ ซ่อมบำรุง ☐ อาคารบริหาร ☐ TPAC ☐ TPCC1 ☐ TPCC2 ☐ WH1 ☐ WH2

สภาพทั่วไปของรถ	เข้า / ออก: เรียบร้อย	เข้า / ออก: ไม่เรียบร้อย	ระบุรายละเอียด
1. สภาพยานพาหนะ (Vehicle)			
1.1 มีน้ำมันเครื่องหรือสารเคมีรั่วไหลหรือไม่?			
1.2 รถที่ใช้เชื้อเพลิง NGV มีใบอนุญาตรับรองผ่านการตรวจสภาพถูกต้องหรือไม่?			ใบอนุญาตการตรวจสภาพหมดอายุหรือไม่?
1.3 ประตูตู้สินค้า หรือ แผงกั้นกันของตก ปิดสนิทหรือไม่?			
1.4 สวมท่อป้องกันประกายไฟ			
1.5 ใบอนุญาตทะเบียนและประกันภัย พ.ร.บ. หมดอายุหรือไม่?			
1.6 ตรวจสอบหาระเบิด / วัตถุต้องสงสัยภายในรถ / ใต้ท้องรถ			พบเห็นสิ่งผิดปกติแจ้ง 1301 - 1309 ทันที
2. พนักงานขับรถ (Driver)			
2.1 แต่งกายสุภาพเรียบร้อย ไม่มีอาการเมาสุราหรือยาเสพติด			
2.2 ใบอนุญาตขับขี่ถูกต้องหรือไม่ / หมดอายุหรือไม่?			(รถขนส่งสารเคมี ใบขับขี่ประเภท 4)
2.3 บัตรผ่านการอบรม (กรณีขนส่งสารเคมีเข้าพื้นที่การผลิต) หมดอายุหรือไม่?			(ตรวจสอบบัตรผ่านการอบรมฯ)
2.4 มีอุปกรณ์ป้องกันอันตรายครบถ้วน (หมวก,แว่นตา,รองเท้า)			
2.5 ฝากบุหรี่และไฟแช็กไว้ที่ป้อมรักษาการ			
2.6 มีผู้โดยสารมากับรถหรือไม่ (ถ้ามีให้รอนอกบริษัทฯ)			

[redacted]

3. การตรวจสอบรถขนส่งสินค้า, สารเคมี, รถขนย้าย, รถ BPA และอื่นๆ (เจ้าหน้าที่ของฝ่ายคลังสินค้ากำหนดหัวข้อในการตรวจสอบดังนี้)	รถออก: เรียบร้อย	รถออก: ไม่เรียบร้อย	ระบุรายละเอียด
☑ ภายในห้องคนขับ (มีสิ่งของ, สินค้า หรือวัสดุอื่นๆ ของบริษัทฯ ติดมาหรือไม่?)			
☐ ตรวจซีลล็อกประตูตู้สินค้า (ต้องอยู่ในสภาพที่ดีไม่มีร่องรอยการงัดแงะ)			
☑ ตรวจภายในตู้คอนเทนเนอร์ (มีสิ่งของ, สินค้า / วัสดุอื่นๆ ของบริษัทติดมาหรือไม่?)			
☑ ตรวจตู้สินค้าภายนอก (ต้องปิดล็อคเรียบร้อยและแน่นหนาทุกจุด)			
☑ ตรวจนับจำนวนสิ่งของออก (สิ่งของออกมีจำนวนตรงกับใบของออกหรือไม่?)			

[redacted]

หมายเหตุ :
1. รถเข้า : กรณีที่ตรวจสอบแล้วพบว่าไม่เรียบร้อย ไม่อนุญาตให้รถเข้ามาในเขตบริษัท หนักงาน รปภ. โทรแจ้งไปฝ่ายที่เกี่ยวข้องทันที
2. รถออก : - กรณีที่ไม่มีลายมือผู้ตรวจสอบของหนักงานบริษัท TPAC & TPCC / Sankyu ไม่อนุญาตให้รถออกโดยเด็ดขาด โทรแจ้งไปฝ่ายที่เกี่ยวข้องทันที
: - กรณีตรวจสอบพบว่ามีสินค้า, สิ่งของของบริษัทฯ ติดมา หนักงาน รปภ. โทรแจ้งไปยังเจ้าหน้าที่ของ WH ที่เกี่ยวข้องทันที
3. พบเห็นสิ่งผิดปกติ แจ้ง 1301 - 1309 ทันที

3SE-F081(0)

บริษัท ไทยโพลีอะซีทัล จำกัด
THAI POLYACETAL CO., LTD.

บริษัท ไทยโพลีคาร์บอเนต จำกัด
THAI POLYCARBONATE CO., LTD.

เล่มที่ 041 **ใบตรวจสอบยานพาหนะ เข้า - ออก (ป้อม2)** เลขที่ 04002

ประเภท ☑ รถ BPA ☐ รถขนส่งสารเคมี ☐ รถรับ-ส่งสินค้า ☐ รถเสียบ ☐ รถเครน
☐ รถหกล้อ ☐ รถสิบล้อ ☐ รถส่งพาเลท ☐ รถอื่นๆ

วันที่ 12-1-67 บริษัท PTT ทะเบียน 73-4467 เวลาเข้า 10 : 10 น.

สถานที่ส่งของ : ☐ ซ่อมบำรุง ☐ อาคารบริหาร ☐ TPAC ☐ TPCC1 ☑ TPCC2 ☐ WH1 ☐ WH2

สภาพทั่วไปของรถ	เข้า / ออก: เรียบร้อย	เข้า / ออก: ไม่เรียบร้อย	ระบุรายละเอียด
1. สภาพยานพาหนะ (Vehicle)			
1.1 มีน้ำมันเครื่องหรือสารเคมีรั่วไหลหรือไม่?			
1.2 รถที่ใช้เชื้อเพลิง NGV มีใบอนุญาตรับรองผ่านการตรวจสภาพถูกต้องหรือไม่?			ใบอนุญาตการตรวจสภาพหมดอายุหรือไม่?
1.3 ประตูตู้สินค้า หรือ แผงกั้นกันของตก ปิดสนิทหรือไม่?			
1.4 สวมท่อป้องกันประกายไฟ			
1.5 ใบอนุญาตทะเบียนและประกันภัย พ.ร.บ. หมดอายุหรือไม่?			
1.6 ตรวจสอบหาระเบิด / วัตถุต้องสงสัยภายในรถ / ใต้ท้องรถ			พบเห็นสิ่งผิดปกติแจ้ง 1301 - 1309 ทันที
2. พนักงานขับรถ (Driver)			
2.1 แต่งกายสุภาพเรียบร้อย ไม่มีอาการเมาสุราหรือยาเสพติด			
2.2 ใบอนุญาตขับขี่ถูกต้องหรือไม่ / หมดอายุหรือไม่?			(รถขนส่งสารเคมี ใบขับขี่ประเภท 4)
2.3 บัตรผ่านการอบรม (กรณีขนส่งสารเคมีเข้าพื้นที่การผลิต) หมดอายุหรือไม่?			(ตรวจสอบบัตรผ่านการอบรมฯ)
2.4 มีอุปกรณ์ป้องกันอันตรายครบถ้วน (หมวก,แว่นตา,รองเท้า)			
2.5 ฝากบุหรี่และไฟแช็กไว้ที่ป้อมรักษาการ			
2.6 มีผู้โดยสารมากับรถหรือไม่ (ถ้ามีให้รอนอกบริษัทฯ)			

[redacted]

3. การตรวจสอบรถขนส่งสินค้า, สารเคมี, รถขนย้าย, รถ BPA และอื่นๆ (เจ้าหน้าที่ของฝ่ายคลังสินค้ากำหนดหัวข้อในการตรวจสอบดังนี้)	รถออก: เรียบร้อย	รถออก: ไม่เรียบร้อย	ระบุรายละเอียด
☑ ภายในห้องคนขับ (มีสิ่งของ, สินค้า หรือวัสดุอื่นๆ ของบริษัทฯ ติดมาหรือไม่?)	✓		
☐ ตรวจซีลล็อกประตูตู้สินค้า (ต้องอยู่ในสภาพที่ดีไม่มีร่องรอยการงัดแงะ)			
☑ ตรวจภายในตู้คอนเทนเนอร์ (มีสิ่งของ, สินค้า / วัสดุอื่นๆ ของบริษัทติดมาหรือไม่?)	✓		
☐ ตรวจตู้สินค้าภายนอก (ต้องปิดล็อคเรียบร้อยและแน่นหนาทุกจุด)			

[redacted]


หมายเหตุ :
1. รถเข้า : กรณีที่ตรวจสอบแล้วพบว่าไม่เรียบร้อย ไม่อนุญาตให้รถเข้ามาในเขตบริษัท หนักงาน รปภ. โทรแจ้งไปฝ่ายที่เกี่ยวข้องทันที
2. รถออก : - กรณีที่ไม่มีลายมือผู้ตรวจสอบของหนักงานบริษัท TPAC & TPCC / Sankyu ไม่อนุญาตให้รถออกโดยเด็ดขาด โทรแจ้งไปฝ่ายที่เกี่ยวข้องทันที
: - กรณีตรวจสอบพบว่ามีสินค้า, สิ่งของของบริษัทฯ ติดมา หนักงาน รปภ. โทรแจ้งไปยังเจ้าหน้าที่ของ WH ที่เกี่ยวข้องทันที
3. พบเห็นสิ่งผิดปกติ แจ้ง 1301 - 1309 ทันที


3SE-F081(0)


เอกสารแนบที่ 46


บันทึกการอบรมความปลอดภัยสำหรับผู้รับเหมา


และพนักงานขับรถขนส่ง


















Mark	สถานะ	รหัสบัตร	ชื่อ	นามสกุล	จำนวนรูปถ่าย	เพศ	สัญชาติ	เลข 13 หลัก/เลข Passport	วันเกิด	อายุ ปี-เดือน	สังกัด บริษัท/หน่วยงาน	วันออกบัตร	วันหมดอายุ /งานเสร็จ	ประเภท	ตำแหน่ง /หน้าที่	พื้นที่อนุญาตให้เข้าทำงาน
☐	Active	004784	ประพนธ์	บุญเรืองโรจน์	2	Male	Thai	3100101234559	31/03/1972	52-03	Released	08/04/2024	31/12/2024	CONTRACTOR		TPAC - TPCC
☑	Expired	004788	ภาพน	เนื่องมิตร	2	Male	Thai	1259900255594	14/03/1997	27-03	PKS	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004789	สิริพงษ์	พันธ์ไพ	2	Male	Thai	1329900181699	25/07/1993	30-11	PKS	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004790	วิเชียร	แย้มพันธุ์ดี	2	Male	Thai	3100800072221	26/03/1968	56-13	PKS	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004791	ธงชาย	ดุดวก	2	Male	Thai	1411900156828	01/02/1990	34-04	PKS	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004792	ชนะศักดิ์	แก้วใจมา	2	Male	Thai	1330499191782	31/11/1968	55-07	ไม่ได้ทำงาน	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004793	ประหยัด	แสงจรัส	2	Male	Thai	3330400971111	04/11/1962	61-07	ไม่ได้ทำงาน	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004794	แอ๊ด	หนูน่อมศักดิ์	2	Male	Thai	1809900278103	03/07/1991	32-11	ไม่ได้ทำงาน	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004795	จันทนา	เสถียรธารทิพย์	2	Female	Thai	1100600446193	11/07/1968	55-11	ไม่ได้ทำงาน	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004796	ชัยวัฒน์	เพ็ญสวัสดิ์	2	Male	Thai	3411000375708	25/03/1979	49-03	ไม่ได้ทำงาน	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004797	ภูริวัฒน์	สัมฤทธิ์ผลวัฒนกุล	2	Male	Thai	1209900117857	09/08/1991	32-10	ไม่ได้ทำงาน	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004798	พันธนนู่	เพียรสุข	2	Male	Thai	3102006021696	21/07/1981	42-11	ไม่ได้ทำงาน	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004800	บุริพงษ์	มัญชนิทร์	2	Male	Thai	3430200862914	27/07/1969	54-11	ไม่ได้ทำงาน	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004803	ภาสุข	ไชยมิตร	2	Male	Thai	3260400170372	08/09/1982	41-09	ไม่ได้ทำงาน	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004804	พัฒนกร	ใจสุข	2	Male	Thai	1571298889168	28/07/1998	25-11	ไม่ได้ทำงาน	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004805	พัฒกรณ	แสนยืด	2	Male	Thai	1219901707068	16/07/1997	26-11	ไม่ได้ทำงาน	08/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Active	004807	ภัทรงค์	เพ็ญนพคุณกุล	2	Male	Thai	1219900381395	17/12/1992	31-06	Automation	07/03/2024	31/12/2024	CONTRACTOR		TPAC - TPCC
☑	Expired	004808	สถาพร	ยอดจาก	2	Male	Thai	1219900587298	28/03/1997	27-01	Automation	08/02/2022	31/12/2022	CONTRACTOR		TPAC - TPCC
☑	Expired	004809	ทวีพงษ์	สาพระ	2	Male	Thai	3471500206296	05/10/1962	61-08	Automation	20/01/2022	31/12/2022	CONTRACTOR		TPAC - TPCC
☑	Expired	004810	สิทธิศักดิ์	ศรีวิบูลย์	2	Male	Thai	1501900053843	08/10/1990	27-08	AMC	12/07/2022	31/12/2022	CONTRACTOR		TPAC - TPCC
☑	Expired	004811	ธนบดี	แก้วจีนา	2	Male	Thai	1670700151802	31/01/1989	35-05	AMC	20/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC
☑	Expired	004812	ศราวุธ	แจ่มคำดง	2	Male	Thai	1139900168353	09/08/1994	29-10	AMC	20/04/2021	31/12/2021	CONTRACTOR		TPAC - TPCC



Details | Course | Transfer

Copy | Paste

	วันที่	วิชา	ชม.	ครบกลม	Life Cycle	ผู้สอน	หมายเหตุ 1	หมายเหตุ 2	Modified date	Modifie
1	20/02/2023	05 : Basic Safety	3.0		317	Exp วันที่				
2	25/02/2024	05 : Basic Safety	3.0		103	ประกัน			24/02/2024	adm

Mark	สถานะ	รหัสบัตร	ชื่อ	นามสกุล	จำนวนรูปถ่าย	เพศ	สัญชาติ	เลข 13 หลัก/เลข Passport	วันเกิด	อายุ ปี-เดือน	สังกัด บริษัท/หน่วยงาน	วันออกบัตร	วันหมดอายุ /งานเสร็จ	ประเภท	ตำแหน่ง /หน้าที่	พื้นที่อนุญาตให้เข้าทำงาน
☐	Active	002597	[illegible]	[illegible]	2	Male	Thai	3270700067942	01/12/1978	47-04	T-ประชัยพัฒนา	08/04/2024	31/12/2024	CONTRACTOR		TPAC - TPCC
☑	Expired	002598	นพร	เอี่ยวเอม	2	Male	Thai	1340700326585	01/01/1991	33-03	Nissan	06/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002599	สงกรณ	กอนอก้า	2	Male	Thai	1410200179513	16/08/1993	30-10	Nissan	06/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002600	ธนา	ทำนาน	2	Male	Thai	1209900761613	28/12/1991	32-06	Nissan	06/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002601	ธาวี	ดำโก	1	Male	Thai	3310800583067	01/01/1996	28-03	โรงเลี้ยงหาย	06/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002602	วิเชษ	สมศรี	2	Male	Thai	3259700004581	30/07/1982	41-11	OMC	06/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002603	ชัยวัฒน์	พิมพ์เกื้อ	2	Male	Thai	3679900143204	11/06/1980	43-10	OMC	06/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002604	พิเชษ	นามเกิ	2	Male	Thai	3800600488703	25/01/1979	45-05	OMC	06/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002605	ศุภฤกษ์	ปิยะกา	2	Male	Thai	3120600446118	22/11/1974	49-07	OMC	06/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002606	ไกรสาส	ดำเนิ	2	Male	Thai	3660500155363	26/06/1976	47-10	OMC	06/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002609	คณิสร์ศักดิ์	สุภาพ	2	Male	Thai	1330600042877	01/01/1988	36-05	หมู่โคมพล	06/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002610	ณรัชพัฒ	ปันกร	2	Male	Thai	3100600018536	21/06/1978	45-10	หมู่โคมพล	06/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☐	Active	002611	สิริพร	สนิมงคล	2	Female	Thai	3160300020098	12/10/1975	48-08	GPSC	28/05/2024	31/12/2024	CONTRACTOR		TPAC - TPCC
☑	Expired	002612	ไกรวี	ศิริอุบลพันธ์	2	Female	Thai	1109900041574	16/08/1968	55-10	GLOW	11/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Active	002613	สิริพรรณ	ดวงจันทะ	2	Female	Thai	3220100448747	21/10/1971	52-08	GPSC	28/05/2024	31/12/2024	CONTRACTOR		TPAC - TPCC
☑	Active	002614	ธนาพัฒน์	ราษฎร์ยอดชัย	2	Male	Thai	1740200017903	22/04/1985	39-02	สหไทยกาน	07/03/2024	31/12/2024	CONTRACTOR		TPAC - TPCC
☑	Expired	002615	ธนพิชิ	ปิยะมา	2	Male	Thai	1301400084982	25/06/1986	38-00	T-ประชัยพัฒนา	23/03/2022	31/12/2022	CONTRACTOR		TPAC - TPCC
☑	Active	002616	ประกรณ์	คงพ่วงประ	2	Male	Thai	3100200987441	28/07/1978	53-11	T-ประชัยพัฒนา	23/03/2024	31/12/2024	CONTRACTOR		TPAC - TPCC
☑	Expired	002617	ธนนท	พันธ์ปัน	2	Male	Thai	1209301688601	03/04/1988	34-02	SAN	11/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002618	โรจน	ลำพันธ์	2	Male	Thai	3600400004408	11/07/1983	40-11	SAN	11/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002619	นพพิชย์	โกรมพุดซอ	2	Male	Thai	1101500852011	09/09/1995	28-08	SAN	11/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC
☑	Expired	002620	กฤตนนท์	ปัดแดง	2	Male	Thai	3199900072573	01/02/1978	46-04	SAN	11/02/2020	31/12/2020	CONTRACTOR		TPAC - TPCC



Details | Course | Transfer

Copy | Paste

	วันที่	วิชา	ชม.	ครบกลม	Life Cycle	ผู้สอน	หมายเหตุ 1	หมายเหตุ 2	Modified date	Modifie
1	20/02/2023	05 : Basic Safety	3.0		1[illegible]	Exp วันที่			24/04/2023	adm
2	08/04/2024	05 : Basic Safety	3.0		246	ประกัน			11/04/2024	adm

เอกสารแนบที่ 47

ประกาศความร่วมมือในการหลีกเลี่ยงการขนส่งผ่านชุมชน

THAI POLYACETAL CO., LTD. THAI POLYCARBONATE CO., LTD.


[redacted]

[redacted]

THAI POLYACETAL CO., LTD. THAI POLYCARBONATE CO., LTD.

[redacted]

[redacted]



หัวข้อการประชุม

Safety Meeting with Transportation Company

วันจันทร์ที่ 17 พฤศจิกายน 2557 เวลา 14.00 – 15.30 น.

สถานที่ แผนงานบัง

งาน Import, Export (FCL&LCL)

1.เรื่อง การสวมใส่อุปกรณ์ Safety ขณะแผนกจัดหนักงานขนับรถทุกคนต้องสวมใส่ ร่างให้เห็นการใช้ เป็นที่ยอมรางเข้าไปที่โซนสินค้าทุก Warehouse


2.เรื่อง ในกรณี ขณะแผนกจัดหนักงานขนับรถด้วยนะคะ ร่วมหาบารุงสินค้าเสร็จเรียบร้อยแล้วให้คลา ไปทำบัตรทางแผนกงานหน้าด้วย และให้ตรวจสอบความถูกต้องของใบส่งสินค้าว่าใช่ของตัวเองหรือไม่ เพื่อให้ถูกต้องกับผู้ที่รางแผนเข้าไปที่โหลดใหม่

3.เรื่อง การตรวจสภาพสภาพของหนักงานขับรถ ขณะเข้าพื้นส่งและบริษัทส่งผลการตรวจสภาพสภาพ ของหนักงานขนับรถแก่ให้ด้วยนะคะ ภายในวันที่ 30 พฤศจิกายน 2557 นี้

4.เรื่อง เอกสาร CY เข้าไปที่โหลดสินค้า ขณะแผนกจัดหนักงานขับรถ ด้วยนะคะ ว่าที่รู้ว่าด้วยจะเป็นผู้ด้วย เอกสารให้เข้าหน้างานแผนกว่า เหรอแผนกงานขับรถขณะคิดว่าผู้ด้วยจะเข้างานที่ไหนก็ได้ มีใบสั่งงานก็เก็บของตัวเองไปก่อน แล้วค่อยว่ากันทีหลังเป็นแบบนี้ห้ามนะคะ ขอให้โหลดตามตัวนะคะ

6.เรื่องการจัดบอร์ดผู้ขับ ขณะไม่ให้แจ้งหนักงานที่ทราบหน้าที่ของบอร์ดผู้ ก่อนที่จะทำการส่งบอร์ดผู้ก็ ให้ทีหลาย ECL ให้ทางตรงจักขอบคุณนะคะ กรณีเกิดแผนหรือร่วมเรื่องบอร์ดผู้ก็ดีแผนออกมาทุกท่าน

7.เรื่องการกำหนดเวลาออกด้านในกิดแผนช่วงเช้า ตั้งแต่เวลา 7.00 – 8.00 น.และ ช่วงบ่าย เวลา 16.30 – 17.30 น.ห้ามการเข้าไปในบริเวณโรงงานโดยเด็ดขาดนะคะ และรวมถึงรถยนต์ของท่านและรถที่แขกด้วย



THAI POLYACETAL CO., LTD. THAI POLYCARBONATE CO., LTD.

ที่ ...

เรื่อง ขอความร่วมมือในการปฏิบัติงานด้านความปลอดภัย

เรียน ...

ด้วย ...

ดังนั้น ...

THAI POLYACETAL CO., LTD. THAI POLYCARBONATE CO., LTD.

วันที่ ...



เรื่อง ...

ด้วย ...


ดังนั้น ...

เอกสารแนบที่ 48

การตรวจสอบและควบคุมเส้นทางการขนส่ง


Transportation Route Patrol Check Sheet Date 13-February-2024								
No.	Truck No.	Truck Company	Truck Type	To leave	To check point	Used Time	Picture	Weight tickets
1	73-2299	Mr. Wiyakorn / TWT	Semi Tailer relocate	Recheck by GPS				None
2	73-2277	Mr. Somya / TWT	Semi Tailer relocate	Recheck by GPS				None
3	77-1284	Mr. Siriwat / SN	Semi Tailer relocate	Recheck by GPS				None
4	71-7890	Mr. Sarawut / Sankyu	Full Tailer relocate	Recheck by GPS				None
5	72-2732	Mr. Threerapong / Sankyu	Full Tailer relocate	Recheck by GPS				None
6	72-3792	Mr. Suthad / Sankyu	Full Tailer relocate	Recheck by GPS				None
7	73-8327	Mr.Manit / PK	Semi Tailer Export	Loading at TPCC				
8	73-8325	Mr.Thepchai / PK	Semi Tailer Export	Loading at TPCC				
9	72-8032	Mr. Ronnachai / TKLS	Semi Tailer Export	Loading at TPCC				
10	72-6234	Mr. Raewat / TKLS	Semi Tailer Export	Loading at TPCC				

รายงาน GPS วันที่วิ่งงาน Formaline ทะเบียน 70-1607, 70-0632 วันที่ 15/11/2023




Transportation Route Patrol Check Sheet Date 23-April-2024								
No.	Truck No.	Truck Company	Truck Type	To leave	To check point	Used Time	Picture	Weight tickets
1	73-4114	Mr.Boonsom / TWT	Semi Tailer relocate	Recheck by GPS				None
2	73-4466	Mr.Panthep / TWT	Semi Tailer relocate	Recheck by GPS				None
3	7-1282	Mr.Sakorn / SN	Semi Tailer relocate	Recheck by GPS				None
4	72-3791	Mr. Wirat / SANKYU	Full Tailer relocate	Recheck by GPS				None
5	72-2736	Mr. Threerapong / SANKYU	Full Tailer relocate	Recheck by GPS				None
6	71-7890	Mr. Sarawut / SANKYU	Full Tailer relocate	Recheck by GPS				None
7	73-8328	Mr. Somphong / PK	Semi Tailer Export	Loading at TPCC				
8	73-8073	Mr. Wimon / PK	Semi Tailer Export	Loading at TPCC				
9	73-7379	Mr. Tanom / TKLS	Semi Tailer Export	Loading at TPCC				
10	72-8032	Mr. Ronnachai / TKLS	Semi Tailer Export	Loading at TPCC				

รายงาน GPS วันที่วิ่งงาน Formaline ทะเบียน 70-4366 , 70-0633 วันที่ 25/04/2024



Transportation Route Patrol Check Sheet Date 05-June-2024								
No.	Truck No.	Truck Company	Truck Type	To leave	To check point	Used Time	Picture	Weight tickets
1	71-3113	Mr.Tanut / TWT	Semi Tailer relocate	Recheck by GPS				None
2	73-2277	Mr.Somya / TWT	Semi Tailer relocate	Recheck by GPS				None
3	73-4466	Mr.Panthep / TWT	Semi Tailer relocate	Recheck by GPS				None
4	72-2736	Mr. Threerapong / SANKYU	Full Tailer relocate	Recheck by GPS				None
5	72-2402	Mr. Arthorn / SANKYU	Full Tailer relocate	Recheck by GPS				None
6	72-2401	Mr. Somporn / SANKYU	Full Tailer relocate	Recheck by GPS				None
7	73-8329	Mr. Kan / PK	Semi Tailer Export	Loading at TPCC				
8	73-8327	Mr. Manit / PK	Semi Tailer Export	Loading at TPCC				
9	72-8032	Mr. Ronnachai / TKLS	Semi Tailer Export	Loading at TPCC				
10	72-6234	Mr. Raewat / TKLS	Semi Tailer Export	Loading at TPCC				

รายงาน GPS วันที่วิ่งงาน Formaline ทะเบียน 70-4366 , 70-0633 วันที่ 28/05/2024




เอกสารแนบที่ 49

รายงานการกำจัดสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว

(ใบกำกับการขนย้ายของเสียอันตราย

Uniform Hazardous Waste Manifest)



บริษัท ไทยโพลิคาร์บอเนต จำกัด
THAI POLYCARBONATE CO.,LTD.

เรื่อง รายงานการจ้างคืนผู้ปฏิบัติงานเครื่องจักรไฟฟ้าสำหรับประจำเดือน

เรียน นายจ้างหรือผู้ประกอบกิจการ

ด้วย ผู้ขอรับใบอนุญาตทำการตรวจสอบความปลอดภัยในการใช้งานลิฟต์ ได้ทำการตรวจสอบลิฟต์ ประจำเดือน ตามที่ได้รับแจ้งจากนายจ้างหรือผู้ประกอบกิจการ

ข้อมูลลิฟต์

1. ลิฟต์โดยสาร จำนวน 18 เครื่อง
2. ลิฟต์บรรทุกของ จำนวน 1 เครื่อง
3. ลิฟต์ขนส่งของ จำนวน 4 เครื่อง

บริษัท ไทย โพลิคาร์บอเนต จำกัด ขอเรียนผู้ประกอบการตรวจสอบการตรวจสอบลิฟต์ ตามที่ได้รับแจ้งจากนายจ้างหรือผู้ประกอบกิจการ ดังนี้

ผลการตรวจสอบ ลิฟต์ 18 เครื่อง ผ่านการตรวจสอบ

ลิฟต์บรรทุกของ จำนวน 1 เครื่อง ผ่านการตรวจสอบ

ลิฟต์ขนส่งของ จำนวน 4 เครื่อง ผ่านการตรวจสอบ

จึงเรียนมาเพื่อโปรดทราบ

ขอแสดงความนับถือ

(นายสมชาย แซ่ลิ้มโรจน์)
ผู้ได้รับใบอนุญาตให้ใช้ลิฟต์และประกอบกิจการ








































































































































บริษัท ไทยโพลีคาร์บอเนต จำกัด
THAI POLYCARBONATE CO.,LTD















































































































บริษัท ไทยโพลีคาร์บอเนต จำกัด
THAI POLYCARBONATE CO.,LTD.

Emporium Tower, Floor 24/44-5, 622 Sukhumvit Road, Klongton, Klongtoey, Bangkok 10110, Thailand Tel. 0-2261-3277 to 9
Plant : Pakkong Industrial Estate 1/1 Pakkong Road, Map-Ta-Phut, Rayong 21150, Thailand Tel. 0-3868-5400 Fax. 0-3868-5420

บริษัท ไทยโพลีคาร์บอเนต จำกัด
เลขที่ 1/1 นิคมอุตสาหกรรมมาบตาพุด
ต.มาบตาพุด อ.เมือง จังหวัดระยอง 21150

วันที่ 15 เมษายน 25--

เรื่อง รายงานการกำจัดสิ่งปฏิกูลหรือวัสดุไม่ใช้แล้วประจำเดือน _____ ปีงบประมาณ พ.ศ. ----

เรียน นายกเทศมนตรีเมืองมาบตาพุด

สำเนา ผู้ว่าราชการจังหวัดระยองหรือนายอุตสาหกรรมจังหวัดระยองหรือนายกรุงเมืองมาบตาพุด

สิ่งที่ส่งมาด้วย

1. สำเนาใบกำกับการขนส่งของบริษัทผู้ประกอบการขนส่งที่ได้รับอนุญาตครั้งแรก 11 รายการ
2. สำเนาใบกำกับการขนส่งของบริษัทผู้ประกอบการขนส่งที่ได้รับอนุญาตครั้งต่อไป 63 รายการ
3. สำเนาใบกำกับการขนส่งของผู้ขนส่งรายย่อยที่ได้รับอนุญาตครั้งแรกจำนวน 1 รายการ

บริษัท ไทย โพลีคาร์บอเนต จำกัด ขอเรียนผู้ประกอบการอุตสาหกรรมระดับที่ 3.4211 ที่ 19
ประกอบกิจการ ผลิตเม็ดพลาสติกโพลีคาร์บอเนต ตั้งอยู่ในพื้นที่นิคมอุตสาหกรรมมาบตาพุด เลขที่ 1/1 หมู่ 11
ตำบลมาบตาพุด อำเภอเมืองระยอง จังหวัดระยอง 21150
โทรศัพท์ 0-3868-5400 โทรสาร 0-3868-5420

ขอรายงานการกำจัดสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้วประจำเดือน ปีงบประมาณ พ.ศ. ----

1. ของปีงบประมาณ จำนวน 11 รายการ เป็นเงิน ---,--- บาท
2. ของครั้งนี้ จำนวน 63 รายการ เป็นเงิน ---,--- บาท
3. ของยอดยกมา จำนวน 1 รายการ เป็นเงิน ---,--- บาท

จึงเรียนมาเพื่อโปรดทราบ

ขอแสดงความนับถือ

(นายกเทศมนตรีเมืองมาบตาพุด)
ผู้ได้รับใบอนุญาตให้ใช้ที่ดินและประกอบกิจการ























































































บริษัท ไทยโพลีคาร์บอเนต จำกัด
THAI POLYCARBONATE CO.,LTD.



บริษัท ไทยโพลีคาร์บอเนต จำกัด
THAI POLYCARBONATE CO.,LTD.





















































































































บริษัท ไทยโพลีคาร์บอเนต จำกัด
THAI POLYCARBONATE CO.,LTD.


บริษัท ไทยโพลีคาร์บอเนต จำกัด
THAI POLYCARBONATE CO.,LTD.







