# เอกสารแนบที่ 8

# รายงานการใช้ไฟฟ้า/น้ำ

OmniDirection

Service Partner of Schneider Electric

## Stay Wellbeing – TR PM2023

RESORTLIFE CO.,LTD.
56/80 M.4 Rawai A.Muang Phuket 83130
Phone 076-363250

Contact customer : Khun Tu
Contact number : 089-4706071

# Maintenance Report

***Date of work : 31 Aug 2023***

| | |
|---|---|
| **OMNI DIRECTION**<br>Ekachai Rungsuwan<br><br>31 Aug 2023 | *Report prepared by*<br>Mr. Ekachai Rungsuwan<br><br>Date<br>31 Aug 2023<br><br>*Service Order reference :* |



## Table of Content

Table of Content ..... 2
Summary of Defect ..... 3
Photograph ..... 5
Test sheets ..... 11

*We are recommended to establish/continues the following practices which will prevent possible damage to equipment and injury to personnel, as well as save your additional cost.*

- *A regular preventive maintenance schedule should be established/continues to obtain the best service and reliability from equipments.*
- *Plant operation and local conditions will dictate the frequency of inspection required.*
- *Keep spare part of critical part*
- *Consult to equipment specialist for any requirement*

*A permanent record of all preventive maintenance work should be kept, the status of equipment depending on the operation conditions. In any event, it will be a valuable reference for subsequent maintenance work and for station operation. It is recommended that the record include reports of tests made, the condition of equipment and repairs and adjustments that were made.*

*We hope you will keep Schneider Thailand-Services in mind for future projects in which we might be able to service your electrical distribution system.*



OmniDirection
Service Partner of Schneider Electric

## Summary of Defect equipment and its status

**Thank you for the opportunity to provide us to perform the services in the above reference project. Hereafter is quick summary for your consideration**

| Item | Equipments | Status | Faulty list | Corrective Action | Remark |
|---|---|---|---|---|---|
| | | | | | |
| | | | | | |

## Photograph




***Photo 1-20***

Preventive maintenance of TR

- Inspect physical and mechanical condition.
- Cleaning overall ,
- Test Insulation Resistance
- Connection tightening torque
- Oil - Dielectric Breakdown Strength Test.



## Test sheets



Schneider Electric

# FIELD INSPECTION AND TEST RECORD
## DISTRIBUTION TRANSFORMER - OIL IMMERSED

OmniDirection

| | | | |
|---|---|---|---|
| Project Ref. : | STAY Wellbeing - PM2023 | Location. : | EE Substation |
| Site. : | - | Panel No. : | - |
| Customer. : | RESORTLIFE CO.,LTD. | Feeder Name. : | TR.1 (315) |

**TECHNICAL DATA**

| | | | | | |
|---|---|---|---|---|---|
| Manufacture | QTC | | % impedance voltage | 3.98% | |
| Type | Oil Immersed | | Top oil temperature rise | 60K | °c |
| Year of manufacture | 2020 | | Winding temperature rise | - | °c |
| Standard | IEC 60076 | | Insulation class | A | |
| No. of Phase | 3 | | Serial no. | 63310403 | |
| Frequency | 50 | Hz. | | | |
| Rated power | 315 | kVA. | | | |
| Type of cooling | ONAN | | | | |
| Vector group | Dyn11 | | | | |
| Primary voltage | 33000 | kV. | | | |
| Primary current | 5.51 | A. | | | |
| Secondary voltage | 400/230 | V. | | | |
| Secondary current | 454.66 | A. | | | |

| Tap position | Rated Voltage ( V ) | |
|---|---|---|
| | Terminal : H1 H2 H3 | Terminal : X1 X2 X3 |
| 1 | 34650 | 400/230 |
| 2 | 33825 | |
| 3 | 33000 | |
| 4 | 32175 | |
| 5 | 31350 | |

**1. VISUAL INSPECTION AND FUNCTION TEST**

| | Checked | Remark |
|---|---|---|
| - Inspection physical and mechanical condition | ☑ | |
| - Inspection alignment and grounging | ☑ | |
| - Inspection winding temperature indicator | ☐ | N/A |
| - Inspection oil temperature indicator | ☑ | |
| - Inspection oil level indicator | ☑ | |
| - Inspection silica gel | ☐ | N/A |
| - Inspection oil leakage | ☑ | |
| - Inspection gasket | ☑ | |
| - Clean the unit and bushings | ☑ | |
| - Verify the control alarm and trip setting on temperature indicators are as specified | ☐ | N/A |
| - Verify that cooling fans operate | ☐ | N/A |
| - Verify tightness of accessible bolted electrical connections | ☑ | |
| - Verify that as-left tap connections are as specified | ☑ | |
| - Verify tap changer position | ☑ | |
| - Verify the presence of surge arresters | ☑ | |

**2. INSULATION RESISTANCE AND POLARIZATION INDEX MEASUREMENT**

**Test Instruments :** Megger C.A 6505 **, Serial Number :** 837655

| Test connection | | Test voltage | Insulation resistance ( GΩ ) at any time ( min ) | | | | | | | | | | PI = MΩ at 10 min. / MΩ at 1 min. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Positive | Negative | ( Vdc ) | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | |
| HV. | LV. | 5000 | 2.88 | 2.63 | 2.47 | | | | | | | | |
| HV. | Gnd. | 5000 | 2.38 | 2.35 | 1.42 | | | | | | | | |
| LV. | Gnd. | 5000 | N/A | N/A | N/A | | | | | | | | |

Humidity : _____ % , Ambient Temperature : _____ °c

| Responsibility | Tested by | Approved by | Witnessed By |
|---|---|---|---|
| Company | Omni Direction Co.Ltd. | Omni Direction Co.Ltd. | |
| Name | Mr. Sombat Komat | Mr. Ekachai Rungsuwan | |
| Signature | Sombat K. | Ekachai R. | |
| Date | 31/9/2023 | 31/9/2023 | |

Schneider Electric

# FIELD INSPECTION AND TEST RECORD
## DISTRIBUTION TRANSFORMER - OIL IMMERSED

OmniDirection

| | | | |
|---|---|---|---|
| Project Ref. : | STAY Wellbeing - PM2023 | Location. : | EE Substation |
| Site. : | - | Panel No. : | - |
| Customer. : | RESORTLIFE CO.,LTD. | Feeder Name. : | TR.1 (315) |

### 3. TURN RATIO AND POLARITY MEASUREMENT

**Test Instruments :** _____ **, Serial Number :** _____

| Tap position | Rated Ratio | Terminal : - : - | | | Terminal : - : - | | | Terminal : - : - | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | As found | % Error | Phase Dev. | As found | % Error | Phase Dev. | As found | % Error | Phase Dev. |
| | | | | | | | | | | |
| | | | | | | | | | | |

**Polarity :** ☐ Correct ☐ Not correct

### 4. WINDING RESISTANCE MEASUREMENT

**Test Instruments :** **, Serial Number :**

| Side of Xfmr | Tap position | Terminal : - | | | Terminal : - | | | Terminal : - | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Volt ( V ) | Amp ( A ) | R ( Ω ) | Volt ( V ) | Amp ( A ) | R ( Ω ) | Volt ( V ) | Amp ( A ) | R ( Ω ) |
| HV. | 1. | | | | | | | | | |
| | 2. | | | | | | | | | |
| | 3. | | | | | | | | | |
| | 4. | | | | | | | | | |
| | 5. | | | | | | | | | |
| Side of Xfmr | Tap position | Terminal : - | | | Terminal : - | | | Terminal : - | | |
| | | Volt ( mV ) | Amp ( A ) | R ( mΩ ) | Volt ( mV ) | Amp ( A ) | R ( mΩ ) | Volt ( mV ) | Amp ( A ) | R ( mΩ ) |
| LV. | - | | | | | | | | | |
| | | | | | | | | | | |

### 5. EXCITATION CURRENT MEASUREMENT

**Test Instruments :** **, Serial Number :**

| Side of Xfmr | Tap position | Test Voltage ( Vac ) | Terminal : - | | Terminal : - | | Terminal : - | |
|---|---|---|---|---|---|---|---|---|
| | | | Voltage ( V ) | Current ( mA. ) | Voltage ( V ) | Current ( mA. ) | Voltage ( V ) | Current ( mA. ) |
| HV. | 1. | | | | | | | |
| | 2. | | | | | | | |
| | 3. | | | | | | | |
| | 4. | | | | | | | |
| | 5. | | | | | | | |
| | | | | | | | | |
| Side of Xfmr | Tap position | Test Voltage ( Vac ) | Terminal : - | | Terminal : - | | Terminal : - | |
| | | | Voltage ( V ) | Current ( A. ) | Voltage ( V ) | Current ( A. ) | Voltage ( V ) | Current ( A. ) |
| LV. | - | | | | | | | |

| Responsibility | Tested by | Approved by | Witnessed By |
|---|---|---|---|
| Company | Omni Direction Co.Ltd. | Omni Direction Co.Ltd. | |
| Name | Mr. Sombat Komat | Mr. Ekachai Rungsuwan | |
| Signature | Sombat K. | Ekachai R. | |
| Date | 31/9/2023 | 31/9/2023 | |



Schneider Electric

FIELD INSPECTION AND TEST RECORD
DISTRIBUTION TRANSFORMER - OIL IMMERSED

OmniDirection

| | | | |
|---|---|---|---|
| Project Ref. : | STAY Wellbeing - PM2023 | Location. : | EE Substation |
| Site. : | - | Panel No. : | - |
| Customer. : | RESORTLIFE CO.,LTD. | Feeder Name. : | TR.1 (315) |

### 6. OIL DIELECTRIC STRENGTH MEASUREMENT

**Test Instruments :** Megger OTS60PB **, Serial Number :** 101520004

| Position of oil sample | Gap distance ( mm ) | Electrode shape | Breakdown voltage ( kV ) | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | 1 | 2 | 3 | 4 | 5 | 6 | AVG. |
| Main tank | 2.54 | Cylindrical | 42.7 | 45.1 | 42.8 | 38.3 | 37.8 | 40.1 | 41.1 |

Humidity : - % , Ambient Temperature : - °c

**Note:** Use ASTM D877 standard for testing

### 7. MOISTURE CONTENT MEASUREMENT

**Test Instruments :** **, Serial Number :**

| Position of oil sample | Moisture content ( ppm ) | |
|---|---|---|
| | Should be | As found |
| Main tank | Not more than 35 | |
| | | |

Humidity : % , Ambient Temperature : °c

**Note:** Use IEEE C57.106 standard for testing

| Test Method | Electrodes | Gap (mm.) | Oil Dielectric Strength (kV) | Result |
|---|---|---|---|---|
| ASTM D877-02 | | 2.54 | > 30 | Good |
| | | | 27 - 29 | Fair |
| | | | 21 - 26 | Recondition |
| | | | < 20 | Poor |
| IEC 60156 | | 2.5 | > 40 | Good |
| | | | 36 - 40 | Fair |
| | | | 30 - 35 | Recondition |
| | | | < 30 | Poor |

**Remark :** _____

| Responsibility | Tested by | Approved by | Witnessed By |
|---|---|---|---|
| Company | Omni Direction Co.Ltd. | Omni Direction Co.Ltd. | |
| Name | Mr. Sombat Komat | Mr. Ekachai Rungsuwan | |
| Signature | Sombat K. | Ekachai R. | |
| Date | 31/9/2023 | 31/9/2023 | |

Schneider Electric

# FIELD INSPECTION AND TEST RECORD
## DISTRIBUTION TRANSFORMER - OIL IMMERSED

OmniDirection

| | | | |
|---|---|---|---|
| Project Ref. : | STAY Wellbeing - PM2023 | Location. : | EE Substation |
| Site. : | - | Panel No. : | - |
| Customer. : | RESORTLIFE CO.,LTD. | Feeder Name. : | TR.2 (1250) |

**TECHNICAL DATA**

| | | | | | |
|---|---|---|---|---|---|
| Manufacture | CHAROENCHAI | | % impedance voltage | 6.44 | |
| Type | Oil Immersed | | Top oil temperature rise | 60K | °c |
| Year of manufacture | 2019 | | Winding temperature rise | - | °c |
| Standard | - | | Insulation class | A | |
| No. of Phase | 3 | | Serial no. | GB257589 | |
| Frequency | 50 | Hz. | | | |
| Rated power | 1250 | kVA. | | | |
| Type of cooling | KNAN | | | | |
| Vector group | Dyn11 | | | | |
| Primary voltage | 33000 | kV. | | | |
| Primary current | 21.87 | A. | | | |
| Secondary voltage | 400/230 | V. | | | |
| Secondary current | 1804.22 | A. | | | |

| Tap position | Rated Voltage ( V ) | |
|---|---|---|
| | Terminal : H1 H2 H3 | Terminal : X1 X2 X3 |
| 1 | 34650 | 400/230 |
| 2 | 33825 | |
| 3 | 33000 | |
| 4 | 32175 | |
| 5 | 31350 | |

**1. VISUAL INSPECTION AND FUNCTION TEST**

| | Checked | Remark |
|---|---|---|
| - Inspection physical and mechanical condition | ☑ | |
| - Inspection alignment and grounging | ☑ | |
| - Inspection winding temperature indicator | ☐ | N/A |
| - Inspection oil temperature indicator | ☑ | |
| - Inspection oil level indicator | ☑ | |
| - Inspection silica gel | ☐ | N/A |
| - Inspection oil leakage | ☑ | |
| - Inspection gasket | ☑ | |
| - Clean the unit and bushings | ☑ | |
| - Verify the control alarm and trip setting on temperature indicators are as specified | ☐ | N/A |
| - Verify that cooling fans operate | ☐ | N/A |
| - Verify tightness of accessible bolted electrical connections | ☑ | |
| - Verify that as-left tap connections are as specified | ☑ | |
| - Verify tap changer position | ☑ | |
| - Verify the presence of surge arresters | ☑ | |

**2. INSULATION RESISTANCE AND POLARIZATION INDEX MEASUREMENT**

**Test Instruments :** Megger C.A 6505 **, Serial Number :** 837655

| Test connection | | Test voltage | Insulation resistance ( GΩ ) at any time ( min ) | | | | | | | | | | PI = MΩ at 10 min. / MΩ at 1 min. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Positive | Negative | ( Vdc ) | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | |
| HV. | LV. | 5000 | 1.25 | 1.13 | 1.1 | | | | | | | | |
| LV. | Gnd. | 5000 | 1.33 | 1.34 | 1.08 | | | | | | | | |
| HV. | Gnd. | 5000 | N/A | N/A | N/A | | | | | | | | |

Humidity : _____ % , Ambient Temperature : _____ °c

| Responsibility | Tested by | Approved by | Witnessed By |
|---|---|---|---|
| Company | Omni Direction Co.Ltd. | Omni Direction Co.Ltd. | |
| Name | Mr. Sombat Komat | Mr. Ekachai Rungsuwan | |
| Signature | Sombat K. | Ekachai R. | |
| Date | 31/9/2023 | 31/9/2023 | |



Schneider Electric

FIELD INSPECTION AND TEST RECORD
DISTRIBUTION TRANSFORMER - OIL IMMERSED

OmniDirection

| | | | |
|---|---|---|---|
| Project Ref. : | STAY Wellbeing - PM2023 | Location. : | EE Substation |
| Site. : | - | Panel No. : | - |
| Customer. : | RESORTLIFE CO.,LTD. | Feeder Name. : | TR.2 (1250) |

**3. TURN RATIO AND POLARITY MEASUREMENT**

**Test Instruments :** **, Serial Number :**

| Tap position | Rated Ratio | Terminal : - : - | | | Terminal : - : - | | | Terminal : - : - | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | As found | % Error | Phase Dev. | As found | % Error | Phase Dev. | As found | % Error | Phase Dev. |
| | | | | | | | | | | |

**Polarity :** ☐ Correct ☐ Not correct

**4. WINDING RESISTANCE MEASUREMENT**

**Test Instruments :** **, Serial Number :**

| Side of Xfmr | Tap position | Terminal : - | | | Terminal : - | | | Terminal : - | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Volt ( V ) | Amp ( A ) | R ( Ω ) | Volt ( V ) | Amp ( A ) | R ( Ω ) | Volt ( V ) | Amp ( A ) | R ( Ω ) |
| HV. | 1. | | | | | | | | | |
| | 2. | | | | | | | | | |
| | 3. | | | | | | | | | |
| | 4. | | | | | | | | | |
| | 5. | | | | | | | | | |
| Side of Xfmr | Tap position | Terminal : - | | | Terminal : - | | | Terminal : - | | |
| | | Volt ( mV ) | Amp ( A ) | R ( mΩ ) | Volt ( mV ) | Amp ( A ) | R ( mΩ ) | Volt ( mV ) | Amp ( A ) | R ( mΩ ) |
| LV. | - | | | | | | | | | |

**5. EXCITATION CURRENT MEASUREMENT**

**Test Instruments :** **, Serial Number :**

| Side of Xfmr | Tap position | Test Voltage ( Vac ) | Terminal : - | | Terminal : - | | Terminal : - | |
|---|---|---|---|---|---|---|---|---|
| | | | Voltage ( V ) | Current ( mA. ) | Voltage ( V ) | Current ( mA. ) | Voltage ( V ) | Current ( mA. ) |
| HV. | 1. | | | | | | | |
| | 2. | | | | | | | |
| | 3. | | | | | | | |
| | 4. | | | | | | | |
| | 5. | | | | | | | |
| Side of Xfmr | Tap position | Test Voltage ( Vac ) | Terminal : - | | Terminal : - | | Terminal : - | |
| | | | Voltage ( V ) | Current ( A. ) | Voltage ( V ) | Current ( A. ) | Voltage ( V ) | Current ( A. ) |
| LV. | - | | | | | | | |

| Responsibility | Tested by | Approved by | Witnessed By |
|---|---|---|---|
| Company | Omni Direction Co.Ltd. | Omni Direction Co.Ltd. | |
| Name | Mr. Sombat Komat | Mr. Ekachai Rungsuwan | |
| Signature | Sombat K. | Ekachai R. | |
| Date | 31/9/2023 | 31/9/2023 | |

Schneider Electric

# FIELD INSPECTION AND TEST RECORD
## DISTRIBUTION TRANSFORMER - OIL IMMERSED

OmniDirection

| | | | | | |
|---|---|---|---|---|---|
| Project Ref. | : | STAY Wellbeing - PM2023 | Location. | : | EE Substation |
| Site. | : | - | Panel No. | : | - |
| Customer. | : | RESORTLIFE CO.,LTD. | Feeder Name. | : | TR.2 (1250) |

**6. OIL DIELECTRIC STRENGTH MEASUREMENT**

**Test Instruments :** Megger OTS60PB **, Serial Number :** 101520004

| Position of oil sample | Gap distance ( mm ) | Electrode shape | Breakdown voltage ( kV ) | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | 1 | 2 | 3 | 4 | 5 | 6.0 | AVG. |
| Main tank | 2.54 | Cylindrical | 6.4 | 5.5 | 7.1 | 8.5 | 9.5 | 13.3 | 8.4 |

Humidity : - % , Ambient Temperature : - °c

**Note:** Use ASTM D877 standard for testing

**7. MOISTURE CONTENT MEASUREMENT**

**Test Instruments :** **, Serial Number :**

| Position of oil sample | Moisture content ( ppm ) | |
|---|---|---|
| | Should be | As found |
| Main tank | Not more than 35 | |
| | | |

Humidity : % , Ambient Temperature : °c

**Note:** Use IEEE C57.106 standard for testing

| Test Method | Electrodes | Gap (mm.) | Oil Dielectric Strength (kV) | Result |
|---|---|---|---|---|
| ASTM D877-02 | | 2.54 | > 30 | Good |
| | | | 27 - 29 | Fair |
| | | | 21 - 26 | Recondition |
| | | | < 20 | Poor |
| IEC 60156 | | 2.5 | > 40 | Good |
| | | | 36 - 40 | Fair |
| | | | 30 - 35 | Recondition |
| | | | < 30 | Poor |

**Remark :** ผลทดสอบค่าน้ำมันหม้อแปลงต่ำกว่ามาตรฐาน ควรทำการกรองหรือเปลี่ยนน้ำมันหม้อแปลงใหม่

| Responsibility | Tested by | Approved by | Witnessed By |
|---|---|---|---|
| Company | Omni Direction Co.Ltd. | Omni Direction Co.Ltd. | |
| Name | Mr. Sombat Komat | Mr. Ekachai Rungsuwan | |
| Signature | Sombat K. | Ekachai R. | |
| Date | 31/9/2023 | 31/9/2023 | |

2401-2185

ใบเสร็จรับเงิน/ใบกำกับภาษี เลขที่ AA6011670220008
การไฟฟ้าส่วนภูมิภาคตำบลฉลอง (สาขาที่ 00943)
เลขที่ 1/113 หมู่ 5 ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัด
ภูเก็ต 83130
เลขประจำตัวผู้เสียภาษีอากร 0994000165501
เลขประจำเครื่อง K06401-A6011

---

ชื่อ บริษัท รีสอร์ทไลฟ์ จำกัด
Tax ID 0105558184379 สาขา 00001
ที่อยู่ เลขที่ 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมือง
ภูเก็ต จ.ภูเก็ต 83130
รหัสเครื่องวัด 6001695890 ประเภทอัตรา 5124
K06401 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
หมายเลขผู้ใช้ไฟฟ้า 20021947759
ประจำเดือน 01/2567 วันที่อ่านหน่วย 31/01/2567
เลขอ่านครั้งหลัง 875.54 เลขอ่านครั้งก่อน 848.89

| | |
|---|---|
| หน่วยที่ใช้ | 294,210 หน่วย |
| ค่าไฟฟ้าฐาน | 1,079,676.60 บาท |
| ค่า FT 0.3972 บาท/หน่วย | 116,860.21 บาท |
| รวมเงินค่าไฟฟ้า | 1,196,536.81 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 83,757.58 บาท |
| รวมเงินทั้งสิ้น | 1,280,294.39 บาท |

ชำระ 1,280,294.39 บาท ทอนเงิน 0.00 บาท
- เช็ค ธ.ไทยพาณิชย์ จำกัด (มหาชน) ห้างแยกฉลอง (ภูเก็ต) 1,280,294.39 บาท
00803521 ลว 15/02/2567

---

วันที่ชำระเงิน 20/02/2567 เวลา 12.45 น. คุมใบเสร็จ 427464

---

อ้างถึงใบแจ้งค่าไฟฟ้าเลขที่ 850809360924
ลว.05/02/2567

ผู้รับเงิน อุสา เครือยศ รหัสผู้รับเงิน 461858

---

ใบเสร็จรับเงิน/ใบกำกับภาษี เลขที่ AA6011670220008
การไฟฟ้าส่วนภูมิภาคตำบลฉลอง (สาขาที่ 00943)
เลขที่ 1/113 หมู่ 5 ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัด
ภูเก็ต 83130
เลขประจำตัวผู้เสียภาษีอากร 0994000165501
เลขประจำเครื่อง K06401-A6011

---

ชื่อ บริษัท รีสอร์ทไลฟ์ จำกัด
Tax ID 0105558184379 สาขา 00001
ที่อยู่ เลขที่ 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมือง
ภูเก็ต จ.ภูเก็ต 83130
รหัสเครื่องวัด 6001695890 ประเภทอัตรา 5124
K06401 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
หมายเลขผู้ใช้ไฟฟ้า 20021947759
ประจำเดือน 01/2567 วันที่อ่านหน่วย 31/01/2567
เลขอ่านครั้งหลัง 875.54 เลขอ่านครั้งก่อน 848.89

| | |
|---|---|
| หน่วยที่ใช้ | 294,210 หน่วย |
| ค่าไฟฟ้าฐาน | 1,079,676.60 บาท |
| ค่า FT 0.3972 บาท/หน่วย | 116,860.21 บาท |
| รวมเงินค่าไฟฟ้า | 1,196,536.81 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 83,757.58 บาท |
| รวมเงินทั้งสิ้น | 1,280,294.39 บาท |

ชำระ 1,280,294.39 บาท ทอนเงิน 0.00 บาท
- เช็ค ธ.ไทยพาณิชย์ จำกัด (มหาชน) ห้างแยกฉลอง (ภูเก็ต) 1,280,294.39 บาท
00803521 ลว 15/02/2567

---

วันที่ชำระเงิน 20/02/2567 เวลา 12.45 น. คุมใบเสร็จ 427464

---

อ้างถึงใบแจ้งค่าไฟฟ้าเลขที่ 850809360924
ลว.05/02/2567

ผู้รับเงิน อุสา เครือยศ รหัสผู้รับเงิน 461858

---

ใบเสร็จรับเงิน/ใบกำกับภาษี เลขที่ A943986703150029
การไฟฟ้าส่วนภูมิภาคตำบลฉลอง (สาขาที่ 00943)
เลขที่ 1/113 หมู่ 5 ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัด
ภูเก็ต 83130
เลขประจำตัวผู้เสียภาษีอากร 0994000165501
เลขประจำเครื่อง K06401-94398

---

ชื่อ บริษัท รีสอร์ทไลฟ์ จำกัด
Tax ID 0105558184379 สาขา 00001
ที่อยู่ เลขที่ 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมือง
ภูเก็ต จ.ภูเก็ต 83130
รหัสเครื่องวัด 6001695890 ประเภทอัตรา 5124
K06401 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
หมายเลขผู้ใช้ไฟฟ้า 20021947759
ประจำเดือน 02/2567 วันที่อ่านหน่วย 29/02/2567
เลขอ่านครั้งหลัง 900.94 เลขอ่านครั้งก่อน 875.54

| | |
|---|---|
| หน่วยที่ใช้ | 276,750 หน่วย |
| ค่าไฟฟ้าฐาน | 981,659.87 บาท |
| ค่า FT 0.3972 บาท/หน่วย | 109,925.10 บาท |
| รวมเงินค่าไฟฟ้า | 1,091,584.97 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 76,410.95 บาท |
| รวมเงินที่ต้องชำระ | 1,167,995.92 บาท |

การชำระเงินค่าไฟฟ้า

| | |
|---|---|
| ชำระเงินส่วนที่เหลือ | 1,085,769.12 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 76,003.84 บาท |
| รวมเงินทั้งสิ้น | 1,161,772.96 บาท |

ชำระ 1,161,772.96 บาท ทอนเงิน 0.00 บาท
- เช็ค ธ.ไทยพาณิชย์ จำกัด (มหาชน) ห้างแยกฉลอง (ภูเก็ต) 1,161,772.96 บาท
00803522 ลว.15/03/2567

---

วันที่ชำระเงิน 15/03/2567 เวลา 11:31 น. คุมใบเสร็จ 427464

---

อ้างถึงใบแจ้งค่าไฟฟ้าเลขที่ 871602682041
ลว.02/03/2567

ผู้รับเงิน ปุญญิศา นิยมจิตต์ รหัสผู้รับเงิน 9009214

---

ใบเสร็จรับเงิน/ใบกำกับภาษี เลขที่ A943986703150029
การไฟฟ้าส่วนภูมิภาคตำบลฉลอง (สาขาที่ 00943)
เลขที่ 1/113 หมู่ 5 ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัด
ภูเก็ต 83130
เลขประจำตัวผู้เสียภาษีอากร 0994000165501
เลขประจำเครื่อง K06401-94398

---

ชื่อ บริษัท รีสอร์ทไลฟ์ จำกัด
Tax ID 0105558184379 สาขา 00001
ที่อยู่ เลขที่ 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมือง
ภูเก็ต จ.ภูเก็ต 83130
รหัสเครื่องวัด 6001695890 ประเภทอัตรา 5124
K06401 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
หมายเลขผู้ใช้ไฟฟ้า 20021947759
ประจำเดือน 02/2567 วันที่อ่านหน่วย 29/02/2567
เลขอ่านครั้งหลัง 900.94 เลขอ่านครั้งก่อน 875.54

| | |
|---|---|
| หน่วยที่ใช้ | 276,750 หน่วย |
| ค่าไฟฟ้าฐาน | 981,659.87 บาท |
| ค่า FT 0.3972 บาท/หน่วย | 109,925.10 บาท |
| รวมเงินค่าไฟฟ้า | 1,091,584.97 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 76,410.95 บาท |
| รวมเงินที่ต้องชำระ | 1,167,995.92 บาท |

การชำระเงินค่าไฟฟ้า

| | |
|---|---|
| ชำระเงินส่วนที่เหลือ | 1,085,769.12 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 76,003.84 บาท |
| รวมเงินทั้งสิ้น | 1,161,772.96 บาท |

ชำระ 1,161,772.96 บาท ทอนเงิน 0.00 บาท
- เช็ค ธ.ไทยพาณิชย์ จำกัด (มหาชน) ห้างแยกฉลอง (ภูเก็ต) 1,161,772.96 บาท
00803522 ลว.15/03/2567

---

วันที่ชำระเงิน 15/03/2567 เวลา 11:31 น. คุมใบเสร็จ 427464

---

อ้างถึงใบแจ้งค่าไฟฟ้าเลขที่ 871602682041
ลว.02/03/2567

ผู้รับเงิน ปุญญิศา นิยมจิตต์ รหัสผู้รับเงิน 9009214

#871602682041 *Printed: 04-03-2024 10:19:42

การไฟฟ้าส่วนภูมิภาค
PROVINCIAL ELECTRICITY AUTHORITY

# หนังสือแจ้งค่าไฟฟ้า

เลขที่ มท.5307.60/871602682041 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
เรื่อง แจ้งค่าไฟฟ้า วันที่ 02 มีนาคม พ.ศ. 2567
เรียน ท่านผู้ใช้ไฟฟ้า บริษัท รีสอร์ทไลฟ์ จำกัด

*ที่อยู่สำหรับแจ้งค่าไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130*

ที่อยู่สถานที่ใช้ไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130

การไฟฟ้าส่วนภูมิภาค ขอแจ้งค่าไฟฟ้าประจำเดือนกุมภาพันธ์ พ.ศ. 2567 (02/2567) ตามรายละเอียดดังนี้

| รหัสการไฟฟ้า | หมายเลขผู้ใช้ไฟฟ้า | รหัสเครื่องวัด | ประเภทอัตรา | แรงดัน | ตัวคูณ | วันที่อ่านหน่วย |
|---|---|---|---|---|---|---|
| K06401 | KCLO9016 - 020021947759 | 6001695890 | 5124 | 22-33 KV | 4500 | 29/02/2567 |

| | | เลขอ่านครั้งหลัง | เลขอ่านครั้งก่อน | กิโลวัตต์/หน่วย/กิโลวาร์ | จำนวนเงิน (บาท) |
|---|---|---|---|---|---|
| พลังไฟฟ้าสูงสุด | P | 5.171 | 5.037 | 603.00 | 80,156.79 |
| (กิโลวัตต์) | OP | 4.326 | 4.206 | 540.00 | |
| | H | 5.045 | 4.909 | 612.00 | |
| พลังงานไฟฟ้า | P | 900.940 | 875.540 | 114300.00 | 478,219.77 |
| (หน่วย) | OP | 635.200 | 616.200 | 85500.00 | 422,971.07 |
| | H | 743.310 | 726.210 | 76950.00 | |
| | | ค่าบริการ 312.24 บาท ได้รับการอุดหนุน 0.00 บาท | | | 312.24 |
| | | | | ค่าไฟฟ้าฐาน | 981,659.87 |
| กิโลวาร์ | | 0.636 | 0.617 | 85.50 | |

| | |
|---|---|
| ค่า FT ระบบผลิต (บาท/หน่วย) | 0.3972 |
| ค่า FT ระบบส่ง (บาท/หน่วย) | 0.0000 |
| ค่า FT ระบบจำหน่าย (บาท/หน่วย) | 0.0000 |
| รวมค่า FT (บาท/หน่วย) | 0.3972 |
| หน่วยที่คิดค่า FT (หน่วย) | 276,750.00 |
| รวมจำนวนเงินค่า FT (บาท) | 109,925.10 |

| | จำนวนเงิน (บาท) |
|---|---|
| ค่าไฟฟ้าฐาน | 981,659.87 |
| ค่าไฟฟ้า + ค่า FT | 1,091,584.97 |
| ค่าเพาเวอร์แฟคเตอร์ | |
| รวมเงินค่าไฟฟ้า | 1,091,584.97 |
| ภาษีมูลค่าเพิ่ม 7 % | 76,410.95 |
| รวมเงินก่อนหักผลประโยชน์ฯ | 1,167,995.92 |

*คืนผลประโยชน์เงินประกัน 6,222.96บาท

**รวมเงินที่ต้องชำระ 1,161,772.96บาท

| | ระบบผลิต (บาท) | ระบบส่ง (บาท) | ระบบจำหน่าย (บาท) |
|---|---|---|---|
| ค่าพลังไฟฟ้าสูงสุด | | | 80,156.79 |
| ค่าพลังงานไฟฟ้า | 819,980.69 | 81,210.15 | |
| การอุดหนุนค่าไฟฟ้า | | | |
| ค่า FT | 109,925.10 | | |

***PEA คืนเงินผลประโยชน์โดยหักลดในใบแจ้งค่าไฟเดือน ก.พ.67 แล้ว***

**รวมเงินที่ต้องชำระ =หนึ่งล้านหนึ่งแสนหกหมื่นห้าพันเจ็ดร้อยเจ็ดสิบสองบาทเก้าสิบหกสตางค์=**

**โปรดชำระภายในวันที่ 20 มีนาคม พ.ศ. 2567**

**หมายเหตุ: ท่านสามารถชำระเงินดังกล่าวได้ที่สำนักงานการไฟฟ้าเท่านั้น**

**จึงเรียนมาเพื่อโปรดชำระเงินภายในวันที่กำหนดต่อไปด้วย จะขอบคุณยิ่ง**

0200219477592402000000011617729606

**การไฟฟ้าส่วนภูมิภาค**

"เอกสารนี้ออกโดยระบบอัตโนมัติ จึงไม่ต้องมีการลงนาม"

**ติดต่อ: การไฟฟ้าส่วนภูมิภาคตำบลฉลอง**

---

ใบเสร็จรับเงินใบกำกับภาษี เลขที่ AA5011670416012B
การไฟฟ้าส่วนภูมิภาคตำบลฉลอง (สาขาที่ 00943)
เลขที่ 1/113 หมู่ 6 ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัด
ภูเก็ต 83130
เลขประจำตัวผู้เสียภาษีอากร 0994000165501
เลขประจำเครื่อง K06401-A6011

ชื่อ บริษัท รีสอร์ทไลฟ์ จำกัด
Tax ID 0105558184379 สาขา 00001
ที่อยู่ เลขที่ 56/80 ม.4 ซ สุขสันต์ 2 ต ราไวย์ อ เมือง
ภูเก็ต จ.ภูเก็ต 83130
รหัสเครื่องวัด 6001695890 ประเภทอัตรา 5124
K06401 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
หมายเลขผู้ใช้ไฟฟ้า 20021947759
ประจำเดือน 03/2567 วันที่อ่านหน่วย 31/03/2567
เลขอ่านครั้งหลัง 925.19 เลขอ่านครั้งก่อน 900.94

| | |
|---|---|
| หน่วยที่ใช้ | 286,560 หน่วย |
| ค่าไฟฟ้าฐาน | 997,230.08 บาท |
| ค่า FT 0.3972 บาท/หน่วย | 113,821.63 บาท |
| รวมเงินค่าไฟฟ้า | 1,111,051.71 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 77,773.62 บาท |
| รวมเงินทั้งสิ้น | 1,188,825.33 บาท |

| | |
|---|---|
| ชำระ 1,188,825.33 บาท | ทอนเงิน 0.00 บาท |
| - เช็ค ธ ไทยพาณิชย์ จำกัด (มหาชน) ห้าแยกฉลอง (ภูเก็ต) 00821581 ลว 15/04/2567 | 1,188,825.33 บาท |

วันที่ชำระเงิน 18/04/2567 เวลา 11.19 น คุมใบเสร็จ 427464

อ้างถึงใบแจ้งค่าไฟฟ้าเลขที่ 870204591565 ลว 02/04/2567

ผู้รับเงิน อุสา เครือยศ รหัสผู้รับเงิน 461858

---

ใบเสร็จรับเงินใบกำกับภาษี เลขที่ AA5011670416012B
การไฟฟ้าส่วนภูมิภาคตำบลฉลอง (สาขาที่ 00943)
เลขที่ 1/113 หมู่ 6 ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัด
ภูเก็ต 83130
เลขประจำตัวผู้เสียภาษีอากร 0994000165501
เลขประจำเครื่อง K06401-A6011

ชื่อ บริษัท รีสอร์ทไลฟ์ จำกัด
Tax ID 0105558184379 สาขา 00001
ที่อยู่ เลขที่ 56/80 ม.4 ซ สุขสันต์ 2 ต ราไวย์ อ เมือง
ภูเก็ต จ.ภูเก็ต 83130
รหัสเครื่องวัด 6001695890 ประเภทอัตรา 5124
K06401 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
หมายเลขผู้ใช้ไฟฟ้า 20021947759
ประจำเดือน 03/2567 วันที่อ่านหน่วย 31/03/2567
เลขอ่านครั้งหลัง 925.19 เลขอ่านครั้งก่อน 900.94

| | |
|---|---|
| หน่วยที่ใช้ | 286,560 หน่วย |
| ค่าไฟฟ้าฐาน | 997,230.08 บาท |
| ค่า FT 0.3972 บาท/หน่วย | 113,821.63 บาท |
| รวมเงินค่าไฟฟ้า | 1,111,051.71 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 77,773.62 บาท |
| รวมเงินทั้งสิ้น | 1,188,825.33 บาท |

| | |
|---|---|
| ชำระ 1,188,825.33 บาท | ทอนเงิน 0.00 บาท |
| - เช็ค ธ ไทยพาณิชย์ จำกัด (มหาชน) ห้าแยกฉลอง (ภูเก็ต) 00821581 ลว 15/04/2567 | 1,188,825.33 บาท |

วันที่ชำระเงิน 18/04/2567 เวลา 11.19 น คุมใบเสร็จ 427464

อ้างถึงใบแจ้งค่าไฟฟ้าเลขที่ 870204591565 ลว 02/04/2567

ผู้รับเงิน อุสา เครือยศ รหัสผู้รับเงิน 461858

#870204591565 *Printed: 02-04-2024 15:16:21

การไฟฟ้าส่วนภูมิภาค
PROVINCIAL ELECTRICITY AUTHORITY

# หนังสือแจ้งค่าไฟฟ้า

เลขที่ มท.5307.60/870204591565 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
เรื่อง แจ้งค่าไฟฟ้า วันที่ 02 เมษายน พ.ศ. 2567
เรียน ท่านผู้ใช้ไฟฟ้า บริษัท รีสอร์ทไลฟ์ จำกัด

*ที่อยู่สำหรับแจ้งค่าไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130*

ที่อยู่สถานที่ใช้ไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130

การไฟฟ้าส่วนภูมิภาค ขอแจ้งค่าไฟฟ้าประจำเดือนมีนาคม พ.ศ. 2567 (03/2567) ตามรายละเอียดดังนี้

| รหัสการไฟฟ้า | หมายเลขผู้ใช้ไฟฟ้า | รหัสเครื่องวัด | ประเภทอัตรา | แรงดัน | ตัวคูณ | วันที่อ่านหน่วย |
|---|---|---|---|---|---|---|
| K06401 | KCLO9016 - 020021947759 | 6001695890 | 5124 | 22-33 KV | 4500 | 31/03/2567 |

| | | เลขอ่านครั้งหลัง | เลขอ่านครั้งก่อน | กิโลวัตต์/หน่วย/กิโลวาร์ | จำนวนเงิน (บาท) |
|---|---|---|---|---|---|
| พลังไฟฟ้าสูงสุด | P | 5.302 | 5.171 | 589.50 | 78,362.24 |
| (กิโลวัตต์) | OP | 4.440 | 4.326 | 513.00 | |
| | H | 5.175 | 5.045 | 585.00 | |
| พลังงานไฟฟ้า | P | 925.190 | 900.940 | 109125.00 | 456,568.09 |
| (หน่วย) | OP | 654.020 | 635.200 | 84690.00 | 461,987.51 |
| | H | 763.920 | 743.310 | 92745.00 | |
| | | ค่าบริการ 312.24 บาท ได้รับการอุดหนุน 0.00 บาท | | | 312.24 |
| | | | | ค่าไฟฟ้าฐาน | 997,230.08 |
| กิโลวาร์ | | 0.655 | 0.636 | 85.50 | |

| | |
|---|---|
| ค่า FT ระบบผลิต (บาท/หน่วย) | 0.3972 |
| ค่า FT ระบบส่ง (บาท/หน่วย) | 0.0000 |
| ค่า FT ระบบจำหน่าย (บาท/หน่วย) | 0.0000 |
| รวมค่า FT (บาท/หน่วย) | 0.3972 |
| หน่วยที่คิดค่า FT (หน่วย) | 286,560.00 |
| รวมจำนวนเงินค่า FT (บาท) | 113,821.63 |

| | จำนวนเงิน (บาท) |
|---|---|
| ค่าไฟฟ้าฐาน | 997,230.08 |
| ค่าไฟฟ้า + ค่า FT | 1,111,051.71 |
| ค่าเพาเวอร์แฟคเตอร์ | |
| รวมเงินค่าไฟฟ้า | 1,111,051.71 |
| ภาษีมูลค่าเพิ่ม 7 % | 77,773.62 |
| รวมเงินที่ต้องชำระ | 1,188,825.33 |

| | ระบบผลิต (บาท) | ระบบส่ง (บาท) | ระบบจำหน่าย (บาท) |
|---|---|---|---|
| ค่าพลังไฟฟ้าสูงสุด | | | 78,362.24 |
| ค่าพลังงานไฟฟ้า | 841,022.29 | 77,533.31 | |
| การอุดหนุนค่าไฟฟ้า | | | |
| ค่า FT | 113,821.63 | | |

รวมเงินที่ต้องชำระ =หนึ่งล้านหนึ่งแสนแปดหมื่นแปดพันแปดร้อยยี่สิบห้าบาทสามสิบสามสตางค์=

โปรดชำระภายในวันที่ 22 เมษายน พ.ศ. 2567

หมายเหตุ: ท่านสามารถชำระเงินดังกล่าวได้ที่สำนักงานการไฟฟ้าเท่านั้น

จึงเรียนมาเพื่อโปรดชำระเงินภายในวันที่กำหนดต่อไปด้วย จะขอบคุณยิ่ง

0200219477592403000000118882533 61

การไฟฟ้าส่วนภูมิภาค

"เอกสารนี้ออกโดยระบบอัตโนมัติ จึงไม่ต้องมีการลงนาม"

ติดต่อ: การไฟฟ้าส่วนภูมิภาคตำบลฉลอง

---

ใบเสร็จรับเงิน/ใบกำกับภาษี เลขที่ A943986705200142
การไฟฟ้าส่วนภูมิภาคตำบลฉลอง (สาขาที่ 00943)
เลขที่ 1/113 หมู่ 5 ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83130
เลขประจำตัวผู้เสียภาษีอากร 0994000165501
เลขประจำเครื่อง K06401-94398

ชื่อ บริษัท รีสอร์ทไลฟ์ จำกัด
Tax ID 0105558184379 สาขา 00001
ที่อยู่ เลขที่ 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130
รหัสเครื่องวัด 6001695890 ประเภทอัตรา 5124
K06401 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
หมายเลขผู้ใช้ไฟฟ้า 20021947759
ประจำเดือน 04/2567 วันที่อ่านหน่วย 30/04/2567
เลขอ่านครั้งหลัง 952.59 เลขอ่านครั้งก่อน 925.19

| | |
|---|---|
| หน่วยที่ใช้ | 305,505 หน่วย |
| ค่าไฟฟ้าฐาน | 1,071,947.43 บาท |
| ค่า FT 0.3972 บาท/หน่วย | 121,346.59 บาท |
| รวมเงินค่าไฟฟ้า | 1,193,294.02 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 83,530.58 บาท |
| รวมเงินทั้งสิ้น | 1,276,824.60 บาท |

ชำระ 1,276,824.60 บาท ทอนเงิน 0.00 บาท
- เช็ค ธ.ไทยพาณิชย์ จำกัด (มหาชน) ห้าแยกฉลอง (ภูเก็ต) 1,276,824.60 บาท
821592 ลว.15/05/2567

วันที่ชำระเงิน 20/05/2567 เวลา 14:33 น. คุมใบเสร็จ 427464

อ้างถึงใบแจ้งค่าไฟฟ้าเลขที่ 871402788836 ลว.02/05/2567

ผู้รับเงิน ปุญญิสา นิยมจิตต์ รหัสผู้รับเงิน 9009214

---

ใบเสร็จรับเงิน/ใบกำกับภาษี เลขที่ A943986705200142
การไฟฟ้าส่วนภูมิภาคตำบลฉลอง (สาขาที่ 00943)
เลขที่ 1/113 หมู่ 5 ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83130
เลขประจำตัวผู้เสียภาษีอากร 0994000165501
เลขประจำเครื่อง K06401-94398

ชื่อ บริษัท รีสอร์ทไลฟ์ จำกัด
Tax ID 0105558184379 สาขา 00001
ที่อยู่ เลขที่ 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130
รหัสเครื่องวัด 6001695890 ประเภทอัตรา 5124
K06401 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
หมายเลขผู้ใช้ไฟฟ้า 20021947759
ประจำเดือน 04/2567 วันที่อ่านหน่วย 30/04/2567
เลขอ่านครั้งหลัง 952.59 เลขอ่านครั้งก่อน 925.19

| | |
|---|---|
| หน่วยที่ใช้ | 305,505 หน่วย |
| ค่าไฟฟ้าฐาน | 1,071,947.43 บาท |
| ค่า FT 0.3972 บาท/หน่วย | 121,346.59 บาท |
| รวมเงินค่าไฟฟ้า | 1,193,294.02 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 83,530.58 บาท |
| รวมเงินทั้งสิ้น | 1,276,824.60 บาท |

ชำระ 1,276,824.60 บาท ทอนเงิน 0.00 บาท
- เช็ค ธ.ไทยพาณิชย์ จำกัด (มหาชน) ห้าแยกฉลอง (ภูเก็ต) 1,276,824.60 บาท
821592 ลว.15/05/2567

วันที่ชำระเงิน 20/05/2567 เวลา 14:33 น. คุมใบเสร็จ 427464

อ้างถึงใบแจ้งค่าไฟฟ้าเลขที่ 871402788836 ลว.02/05/2567

ผู้รับเงิน ปุญญิสา นิยมจิตต์ รหัสผู้รับเงิน 9009214

#871402788836 *Printed: 02-05-2024 16:10:53

การไฟฟ้าส่วนภูมิภาค
PROVINCIAL ELECTRICITY AUTHORITY

# หนังสือแจ้งค่าไฟฟ้า

เลขที่ มท.5307.60/871402788836 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
เรื่อง แจ้งค่าไฟฟ้า วันที่ 02 พฤษภาคม พ.ศ. 2567
เรียน ท่านผู้ใช้ไฟฟ้า บริษัท รีสอร์ทไลฟ์ จำกัด
*ที่อยู่สำหรับแจ้งค่าไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130*
ที่อยู่สถานที่ใช้ไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130
การไฟฟ้าส่วนภูมิภาค ขอแจ้งค่าไฟฟ้าประจำเดือนเมษายน พ.ศ. 2567 (04/2567) ตามรายละเอียดดังนี้

| รหัสการไฟฟ้า | หมายเลขผู้ใช้ไฟฟ้า | รหัสเครื่องวัด | ประเภทอัตรา | แรงดัน | ตัวคูณ | วันที่อ่านหน่วย |
|---|---|---|---|---|---|---|
| K06401 | KCLO9016 - 020021947759 | 6001695890 | 5124 | 22-33 KV | 4500 | 30/04/2567 |

| | | เลขอ่านครั้งหลัง | เลขอ่านครั้งก่อน | กิโลวัตต์/หน่วย/กิโลวาร์ | จำนวนเงิน (บาท) |
|---|---|---|---|---|---|
| พลังไฟฟ้าสูงสุด | P | 5.438 | 5.302 | 612.00 | 81,353.16 |
| (กิโลวัตต์) | OP | 4.561 | 4.440 | 544.50 | |
| | H | 5.311 | 5.175 | 612.00 | |
| พลังงานไฟฟ้า | P | 952.590 | 925.190 | 123300.00 | 515,874.87 |
| (หน่วย) | OP | 674.140 | 654.020 | 90540.00 | 474,407.16 |
| | H | 784.290 | 763.920 | 91665.00 | |
| กิโลวาร์ | | 0.674 | 0.655 | 85.50 | |

ค่าบริการ 312.24 บาท ได้รับการอุดหนุน 0.00 บาท 312.24
ค่าไฟฟ้าฐาน 1,071,947.43

| | |
|---|---|
| ค่า FT ระบบผลิต (บาท/หน่วย) | 0.3972 |
| ค่า FT ระบบส่ง (บาท/หน่วย) | 0.0000 |
| ค่า FT ระบบจำหน่าย (บาท/หน่วย) | 0.0000 |
| รวมค่า FT (บาท/หน่วย) | 0.3972 |
| หน่วยที่คิดค่า FT (หน่วย) | 305,505.00 |
| รวมจำนวนเงินค่า FT (บาท) | 121,346.59 |

| | จำนวนเงิน (บาท) |
|---|---|
| ค่าไฟฟ้าฐาน | 1,071,947.43 |
| ค่าไฟฟ้า + ค่า FT | 1,193,294.02 |
| ค่าเพาเวอร์แฟคเตอร์ | |
| รวมเงินค่าไฟฟ้า | 1,193,294.02 |
| ภาษีมูลค่าเพิ่ม 7 % | 83,530.58 |
| รวมเงินที่ต้องชำระ | 1,276,824.60 |

| | ระบบผลิต (บาท) | ระบบส่ง (บาท) | ระบบจำหน่าย (บาท) |
|---|---|---|---|
| ค่าพลังไฟฟ้าสูงสุด | | | 81,353.16 |
| ค่าพลังงานไฟฟ้า | 902,677.38 | 87,604.65 | |
| การอุดหนุนค่าไฟฟ้า | | | |
| ค่า FT | 121,346.59 | | |

รวมเงินที่ต้องชำระ =หนึ่งล้านสองแสนเจ็ดหมื่นหกพันแปดร้อยยี่สิบสี่บาทหกสิบสตางค์=
โปรดชำระภายในวันที่ 20 พฤษภาคม พ.ศ. 2567

หมายเหตุ: ท่านสามารถชำระเงินดังกล่าวได้ที่สำนักงานการไฟฟ้าเท่านั้น
จึงเรียนมาเพื่อโปรดชำระเงินภายในวันที่กำหนดต่อไปด้วย จะขอบคุณยิ่ง

0200219477592404000000127682450 17

การไฟฟ้าส่วนภูมิภาค
"เอกสารนี้ออกโดยระบบอัตโนมัติ จึงไม่ต้องมีการลงนาม"

ติดต่อ: การไฟฟ้าส่วนภูมิภาคตำบลฉลอง

2406 - 2005

ใบเสร็จรับเงิน/ใบกำกับภาษี เลขที่ A9439867061900 90
การไฟฟ้าส่วนภูมิภาคตำบลฉลอง (สาขาที่ 00943)
เลขที่ 1/113 หมู่ 5 ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83130
เลขประจำตัวผู้เสียภาษีอากร 0994000165501
เลขประจำเครื่อง K06401-94398

ชื่อ บริษัท รีสอร์ทไลฟ์ จำกัด
Tax ID 0105558184379 สาขา 00001
ที่อยู่ เลขที่ 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130
รหัสเครื่องวัด 6001695890 ประเภทอัตรา 5124
K06401 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
หมายเลขผู้ใช้ไฟฟ้า 20021947759
ประจำเดือน 05/2567 วันที่อ่านหน่วย 31/05/2567
เลขอ่านครั้งหลัง 979.39 เลขอ่านครั้งก่อน 952.59

| | |
|---|---|
| หน่วยที่ใช้ | 307,215 หน่วย |
| ค่าไฟฟ้าฐาน | 1,076,918.70 บาท |
| ค่า FT 0.3972 บาท/หน่วย | 122,025.80 บาท |
| รวมเงินค่าไฟฟ้า | 1,198,944.50 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 83,926.12 บาท |
| รวมเงินทั้งสิ้น | 1,282,870.62 บาท |

ชำระ 1,282,870.62 บาท ทอนเงิน 0.00 บาท
- เช็ค ธ.ไทยพาณิชย์ จำกัด (มหาชน) ห้างแยกฉลอง (ภูเก็ต) 821582 ลว.15/06/2567 1,282,870.62 บาท

วันที่ชำระเงิน 19/06/2567 เวลา 11:13 น. คุมใบเสร็จ 427464

อ้างถึงใบแจ้งค่าไฟฟ้าเลขที่ 870604700477 ลว.02/06/2567

ผู้รับเงิน ปุญญิสา นิยมจิตต์ รหัสผู้รับเงิน 9009214

ใบเสร็จรับเงิน/ใบกำกับภาษี เลขที่ A9439867061900 90
การไฟฟ้าส่วนภูมิภาคตำบลฉลอง (สาขาที่ 00943)
เลขที่ 1/113 หมู่ 5 ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83130
เลขประจำตัวผู้เสียภาษีอากร 0994000165501
เลขประจำเครื่อง K06401-94398

ชื่อ บริษัท รีสอร์ทไลฟ์ จำกัด
Tax ID 0105558184379 สาขา 00001
ที่อยู่ เลขที่ 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130
รหัสเครื่องวัด 6001695890 ประเภทอัตรา 5124
K06401 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
หมายเลขผู้ใช้ไฟฟ้า 20021947759
ประจำเดือน 05/2567 วันที่อ่านหน่วย 31/05/2567
เลขอ่านครั้งหลัง 979.39 เลขอ่านครั้งก่อน 952.59

| | |
|---|---|
| หน่วยที่ใช้ | 307,215 หน่วย |
| ค่าไฟฟ้าฐาน | 1,076,918.70 บาท |
| ค่า FT 0.3972 บาท/หน่วย | 122,025.80 บาท |
| รวมเงินค่าไฟฟ้า | 1,198,944.50 บาท |
| ภาษีมูลค่าเพิ่ม 7% | 83,926.12 บาท |
| รวมเงินทั้งสิ้น | 1,282,870.62 บาท |

ชำระ 1,282,870.62 บาท ทอนเงิน 0.00 บาท
- เช็ค ธ.ไทยพาณิชย์ จำกัด (มหาชน) ห้างแยกฉลอง (ภูเก็ต) 821582 ลว.15/06/2567 1,282,870.62 บาท

วันที่ชำระเงิน 19/06/2567 เวลา 11:13 น. คุมใบเสร็จ 427464

อ้างถึงใบแจ้งค่าไฟฟ้าเลขที่ 870604700477 ลว.02/06/2567

ผู้รับเงิน ปุญญิสา นิยมจิตต์ รหัสผู้รับเงิน 9009214

#870604700477 *Printed: 02-06-2024 17:11:24

การไฟฟ้าส่วนภูมิภาค
PROVINCIAL ELECTRICITY AUTHORITY

# หนังสือแจ้งค่าไฟฟ้า

เลขที่ มท.5307.60/870604700477 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
เรื่อง แจ้งค่าไฟฟ้า วันที่ 02 มิถุนายน พ.ศ. 2567
เรียน ท่านผู้ใช้ไฟฟ้า บริษัท รีสอร์ทไลฟ์ จำกัด
*ที่อยู่สำหรับแจ้งค่าไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130*
ที่อยู่สถานที่ใช้ไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130
การไฟฟ้าส่วนภูมิภาค ขอแจ้งค่าไฟฟ้าประจำเดือนพฤษภาคม พ.ศ. 2567 (05/2567) ตามรายละเอียดดังนี้

| รหัสการไฟฟ้า | หมายเลขผู้ใช้ไฟฟ้า | รหัสเครื่องวัด | ประเภทอัตรา | แรงดัน | ตัวคูณ | วันที่อ่านหน่วย |
|---|---|---|---|---|---|---|
| K06401 | KCLO9016 - 020021947759 | 6001695890 | 5124 | 22-33 KV | 4500 | 31/05/2567 |

| | | เลขอ่านครั้งหลัง | เลขอ่านครั้งก่อน | กิโลวัตต์/หน่วย/กิโลวาร์ | จำนวนเงิน (บาท) |
|---|---|---|---|---|---|
| พลังไฟฟ้าสูงสุด (กิโลวัตต์) | P | 5.582 | 5.438 | 648.00 | 86,138.64 |
| | OP | 4.687 | 4.561 | 567.00 | |
| | H | 5.451 | 5.311 | 630.00 | |
| พลังงานไฟฟ้า (หน่วย) | P | 979.390 | 952.590 | 120600.00 | 504,578.34 |
| | OP | 693.490 | 674.140 | 87075.00 | 485,889.48 |
| | H | 806.410 | 784.290 | 99540.00 | |
| ค่าบริการ 312.24 บาท ได้รับการอุดหนุน 0.00 บาท | | | | | 312.24 |
| | | | | ค่าไฟฟ้าฐาน | 1,076,918.70 |
| กิโลวาร์ | | 0.693 | 0.674 | 85.50 | |

| | |
|---|---|
| ค่า FT ระบบผลิต (บาท/หน่วย) | 0.3972 |
| ค่า FT ระบบส่ง (บาท/หน่วย) | 0.0000 |
| ค่า FT ระบบจำหน่าย (บาท/หน่วย) | 0.0000 |
| รวมค่า FT (บาท/หน่วย) | 0.3972 |
| หน่วยที่คิดค่า FT (หน่วย) | 307,215.00 |
| รวมจำนวนเงินค่า FT (บาท) | 122,025.80 |

| | จำนวนเงิน (บาท) |
|---|---|
| ค่าไฟฟ้าฐาน | 1,076,918.70 |
| ค่าไฟฟ้า + ค่า FT | 1,198,944.50 |
| ค่าเพาเวอร์แฟคเตอร์ | |
| รวมเงินค่าไฟฟ้า | 1,198,944.50 |
| ภาษีมูลค่าเพิ่ม 7 % | 83,926.12 |
| รวมเงินที่ต้องชำระ | 1,282,870.62 |

| | ระบบผลิต (บาท) | ระบบส่ง (บาท) | ระบบจำหน่าย (บาท) |
|---|---|---|---|
| ค่าพลังไฟฟ้าสูงสุด | | | 86,138.64 |
| ค่าพลังงานไฟฟ้า | 904,781.52 | 85,686.30 | |
| การอุดหนุนค่าไฟฟ้า | | | |
| ค่า FT | 122,025.80 | | |

รวมเงินที่ต้องชำระ =หนึ่งล้านสองแสนแปดหมื่นสองพันแปดร้อยเจ็ดสิบบาทหกสิบสองสตางค์=
โปรดชำระภายในวันที่ 20 มิถุนายน พ.ศ. 2567

หมายเหตุ: ท่านสามารถชำระเงินดังกล่าวได้ที่สำนักงานการไฟฟ้าเท่านั้น

จึงเรียนมาเพื่อโปรดชำระเงินภายในวันที่กำหนดต่อไปด้วย จะขอบคุณยิ่ง

|0994000165501000200219477596706201282870 62

การไฟฟ้าส่วนภูมิภาค

"เอกสารนี้ออกโดยระบบอัตโนมัติ จึงไม่ต้องมีการลงนาม"

ติดต่อ: การไฟฟ้าส่วนภูมิภาคตำบลฉลอง

#422505056292 *Printed: 02-07-2024 09:13:14

การไฟฟ้าส่วนภูมิภาค
PROVINCIAL ELECTRICITY AUTHORITY

# หนังสือแจ้งค่าไฟฟ้า

เลขที่ มท.5307.60/422505056292 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
เรื่อง แจ้งค่าไฟฟ้า วันที่ 02 กรกฎาคม พ.ศ. 2567
เรียน ท่านผู้ใช้ไฟฟ้า บริษัท รีสอร์ทไลฟ์ จำกัด
*ที่อยู่สำหรับแจ้งค่าไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130*
ที่อยู่สถานที่ใช้ไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130
การไฟฟ้าส่วนภูมิภาค ขอแจ้งค่าไฟฟ้าประจำเดือนมิถุนายน พ.ศ. 2567 (06/2567) ตามรายละเอียดดังนี้

| รหัสการไฟฟ้า | หมายเลขผู้ใช้ไฟฟ้า | รหัสเครื่องวัด | ประเภทอัตรา | แรงดัน | ตัวคูณ | วันที่อ่านหน่วย |
|---|---|---|---|---|---|---|
| K06401 | KCLO9016 - 020021947759 | 6001695890 | 5124 | 22-33 KV | 4500 | 30/06/2567 |

| | | เลขอ่านครั้งหลัง | เลขอ่านครั้งก่อน | กิโลวัตต์/หน่วย/กิโลวาร์ | จำนวนเงิน (บาท) |
|---|---|---|---|---|---|
| พลังไฟฟ้าสูงสุด (กิโลวัตต์) | P | 5.715 | 5.582 | 598.50 | 79,558.61 |
| | OP | 4.803 | 4.687 | 522.00 | |
| | H | 5.589 | 5.451 | 621.00 | |
| พลังงานไฟฟ้า (หน่วย) | P | 1002.410 | 979.390 | 103590.00 | 433,410.21 |
| | OP | 710.350 | 693.490 | 75870.00 | 470,072.00 |
| | H | 829.670 | 806.410 | 104670.00 | |
| ค่าบริการ 312.24 บาท ได้รับการอุดหนุน 0.00 บาท | | | | | 312.24 |
| | | | | ค่าไฟฟ้าฐาน | 983,353.06 |
| กิโลวาร์ | | 0.712 | 0.693 | 85.50 | |

| | |
|---|---|
| ค่า FT ระบบผลิต (บาท/หน่วย) | 0.3972 |
| ค่า FT ระบบส่ง (บาท/หน่วย) | 0.0000 |
| ค่า FT ระบบจำหน่าย (บาท/หน่วย) | 0.0000 |
| รวมค่า FT (บาท/หน่วย) | 0.3972 |
| หน่วยที่คิดค่า FT (หน่วย) | 284,130.00 |
| รวมจำนวนเงินค่า FT (บาท) | 112,856.44 |

| | จำนวนเงิน (บาท) |
|---|---|
| ค่าไฟฟ้าฐาน | 983,353.06 |
| ค่าไฟฟ้า + ค่า FT | 1,096,209.50 |
| ค่าเพาเวอร์แฟคเตอร์ | |
| รวมเงินค่าไฟฟ้า | 1,096,209.50 |
| ภาษีมูลค่าเพิ่ม 7 % | 76,734.67 |
| รวมเงินที่ต้องชำระ | 1,172,944.17 |

| | ระบบผลิต (บาท) | ระบบส่ง (บาท) | ระบบจำหน่าย (บาท) |
|---|---|---|---|
| ค่าพลังไฟฟ้าสูงสุด | | | 79,558.61 |
| ค่าพลังงานไฟฟ้า | 829,881.51 | 73,600.70 | |
| การอุดหนุนค่าไฟฟ้า | | | |
| ค่า FT | 112,856.44 | | |

รวมเงินที่ต้องชำระ =หนึ่งล้านหนึ่งแสนเจ็ดหมื่นสองพันเก้าร้อยสี่สิบสี่บาทสิบเจ็ดสตางค์=
โปรดชำระภายในวันที่ 24 กรกฎาคม พ.ศ. 2567

หมายเหตุ: ท่านสามารถชำระเงินดังกล่าวได้ที่สำนักงานการไฟฟ้าเท่านั้น

จึงเรียนมาเพื่อโปรดชำระเงินภายในวันที่กำหนดต่อไปด้วย จะขอบคุณยิ่ง

|0994000165501000200219477596707241172944 17

การไฟฟ้าส่วนภูมิภาค

"เอกสารนี้ออกโดยระบบอัตโนมัติ จึงไม่ต้องมีการลงนาม"

ติดต่อ: การไฟฟ้าส่วนภูมิภาคตำบลฉลอง

#850809360924 *Printed: 07-02-2024 13:25:41

การไฟฟ้าส่วนภูมิภาค
PROVINCIAL ELECTRICITY AUTHORITY

# หนังสือแจ้งค่าไฟฟ้า

เลขที่ มท.5307.60/850809360924 การไฟฟ้าส่วนภูมิภาคตำบลฉลอง
เรื่อง แจ้งค่าไฟฟ้า วันที่ 06 กุมภาพันธ์ พ.ศ. 2567
เรียน ท่านผู้ใช้ไฟฟ้า บริษัท รีสอร์ทไลฟ์ จำกัด

*ที่อยู่สำหรับแจ้งค่าไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130*

ที่อยู่สถานที่ใช้ไฟฟ้า: 56/80 ม.4 ซ.สุขสันต์ 2 ต.ราไวย์ อ.เมืองภูเก็ต จ.ภูเก็ต 83130

การไฟฟ้าส่วนภูมิภาค ขอแจ้งค่าไฟฟ้าประจำเดือนมกราคม พ.ศ. 2567 (01/2567) ตามรายละเอียดดังนี้

| รหัสการไฟฟ้า | หมายเลขผู้ใช้ไฟฟ้า | รหัสเครื่องวัด | ประเภทอัตรา | แรงดัน | ตัวคูณ | วันที่อ่านหน่วย |
|---|---|---|---|---|---|---|
| K06401 | KCLO9016 - 020021947759 | 6001695890 | 5124 | 22-33 KV | 4500 | 31/01/2567 |

| | | เลขอ่านครั้งหลัง | เลขอ่านครั้งก่อน | กิโลวัตต์/หน่วย/กิโลวาร์ | จำนวนเงิน (บาท) |
|---|---|---|---|---|---|
| พลังไฟฟ้าสูงสุด | P | 5.037 | 4.830 | 931.50 | 123,824.30 |
| (กิโลวัตต์) | OP | 4.206 | 3.999 | 931.50 | |
| | H | 4.909 | 4.782 | 571.50 | |
| พลังงานไฟฟ้า | P | 875.540 | 848.890 | 119925.00 | 501,754.21 |
| (หน่วย) | OP | 616.200 | 595.910 | 91305.00 | 453,785.85 |
| | H | 726.210 | 707.770 | 82980.00 | |
| | | ค่าบริการ 312.24 บาท ได้รับการอุดหนุน 0.00 บาท | | | 312.24 |
| | | | | ค่าไฟฟ้าฐาน | 1,079,676.60 |
| กิโลวาร์ | | 0.617 | 0.587 | 135.00 | |

| | |
|---|---|
| ค่า FT ระบบผลิต (บาท/หน่วย) | 0.3972 |
| ค่า FT ระบบส่ง (บาท/หน่วย) | 0.0000 |
| ค่า FT ระบบจำหน่าย (บาท/หน่วย) | 0.0000 |
| รวมค่า FT (บาท/หน่วย) | 0.3972 |
| หน่วยที่คิดค่า FT (หน่วย) | 294,210.00 |
| รวมจำนวนเงินค่า FT (บาท) | 116,860.21 |

| | จำนวนเงิน (บาท) |
|---|---|
| ค่าไฟฟ้าฐาน | 1,079,676.60 |
| ค่าไฟฟ้า + ค่า FT | 1,196,536.81 |
| ค่าเพาเวอร์แฟคเตอร์ | |
| รวมเงินค่าไฟฟ้า | 1,196,536.81 |
| ภาษีมูลค่าเพิ่ม 7 % | 83,757.58 |
| รวมเงินที่ต้องชำระ | 1,280,294.39 |

| | ระบบผลิต (บาท) | ระบบส่ง (บาท) | ระบบจำหน่าย (บาท) |
|---|---|---|---|
| ค่าพลังไฟฟ้าสูงสุด | | | 123,824.30 |
| ค่าพลังงานไฟฟ้า | 870,333.35 | 85,206.71 | |
| การอุดหนุนค่าไฟฟ้า | | | |
| ค่า FT | 116,860.21 | | |

รวมเงินที่ต้องชำระ =หนึ่งล้านสองแสนแปดหมื่นสองร้อยเก้าสิบสี่บาทสามสิบเก้าสตางค์=

โปรดชำระภายในวันที่ 27 กุมภาพันธ์ พ.ศ. 2567

หมายเหตุ: ท่านสามารถชำระเงินดังกล่าวได้ที่สำนักงานการไฟฟ้าเท่านั้น

จึงเรียนมาเพื่อโปรดชำระเงินภายในวันที่กำหนดต่อไปด้วย จะขอบคุณยิ่ง

0200219477592401000001280294392 8

การไฟฟ้าส่วนภูมิภาค

"เอกสารนี้ออกโดยระบบอัตโนมัติ จึงไม่ต้องมีการลงนาม"

ติดต่อ: การไฟฟ้าส่วนภูมิภาคตำบลฉลอง

# ใบแจ้งหนี้/ใบเสร็จรับเงิน ค่าใช้น้ำบาดาลและค่าอนุรักษ์น้ำบาดาล

ส่วนของลูกค้า

สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อมจังหวัดภูเก็ต
เลขที่ 109/401 หมู่ที่ 1 ตำบลวิชิต อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83000
โทร 076-211067 ต่อ 15 หรือ 080-3910327 โทรสาร 076-216974
E-mail water_report@hotmail.com

| | |
|---|---|
| เลขที่ | 31-2024-1-0600 |
| REF1 | 3120241060080 |
| REF2 | 20240430000617900 |
| กำหนดชำระเงิน | ภายในวันที่ 30/04/2567 |
| จำนวนเงินที่ต้องชำระ | 46,179.00 |

เรียน บริษัท รีสอร์ทไลฟ์ จำกัด
เลขที่ 56/80 หมู่ 4 ซอยสุขสันต์ 3
ตำบลราไวย์ อำเภอเมืองภูเก็ต จ ภูเก็ต
83130

ที่ ภก.0014.4/ 2510 วันที่ 9 /04/2567 ประจำงวด 1/2567 (ม.ค. 67 - มี.ค. 67)

| ลำดับที่ | หมายเลขบ่อน้ำบาดาล | หมายเลขใบอนุญาตใช้น้ำบาดาล | ปริมาณน้ำที่ได้รับอนุญาต | อัตรา (บาท/ลบ.ม.) ค่าใช้น้ำฯ | อัตรา (บาท/ลบ.ม.) ค่าอนุรักษ์ฯ | ปริมาณน้ำที่ใช้ (ลบ.ม.) | รวมเงิน ค่าใช้น้ำฯ | รวมเงิน ค่าอนุรักษ์ฯ | รวมเป็นเงินทั้งสิ้น |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 6004-0207 | 31-50466-0203 | 60.00 ลบ.ม./วัน | 3.50 (ลดหย่อน) | .00 (ยกเว้น) | 572.0 | 1,501.50 | 0.00 | 1,501.50 |
| 2 | 6004-0208 | 31-50466-0204 | 60.00 ลบ.ม./วัน | 3.50 (ลดหย่อน) | .00 (ยกเว้น) | 1,168.0 | 3,066.00 | 0.00 | 3,066.00 |
| 3 | 6004-0209 | 31-50466-0202 | 60.00 ลบ.ม./วัน | 3.50 (ลดหย่อน) | .00 (ยกเว้น) | 5,620.0 | 14,752.50 | 0.00 | 14,752.50 |
| 4 | 6004-0210 | 31-50466-0205 | 60.00 ลบ.ม./วัน | 3.50 (ลดหย่อน) | .00 (ยกเว้น) | 10,232.0 | 26,859.00 | 0.00 | 26,859.00 |
| ****สี่หมื่นหกพันหนึ่งร้อยเจ็ดสิบเก้าบาทถ้วน**** | | | | | | | 46,179.00 | 0.00 | 46,179.00 |

หมายเหตุ
หากชำระเงินเกินกำหนด และ/หรือ จำนวนเงินไม่เท่ากับยอดรวมของใบแจ้งหนี้ และ/หรือ ชำระเงินเพิ่ม กรุณาติดต่อขอชำระเงินที่สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อมจังหวัดภูเก็ต
ใบเสร็จรับเงินนี้จะสมบูรณ์ต่อเมื่อมีลายมือชื่อผู้รับเงินพร้อมการประทับตราและหากราชการได้รับเงินครบถ้วนแล้ว

คำเตือน
หากชำระเงินระหว่างวันที่ 01/05/2567 ถึงวันที่ 30/05/2567 คิดอัตรา 1.1 เท่า เป็นเงิน 50,796.90 บาท
หากชำระเงินระหว่างวันที่ 31/05/2567 ถึงวันที่ 29/06/2567 คิดอัตรา 1.2 เท่า เป็นเงิน 55,414.80 บาท
หากชำระเงินระหว่างวันที่ 30/06/2567 ถึงวันที่ 29/07/2567 คิดอัตรา 1.3 เท่า เป็นเงิน 60,032.70 บาท
หากชำระเงินตั้งแต่วันที่ 30/07/2567 เป็นต้นไป คิดอัตรา 2 เท่า เป็นเงิน 92,358.00 บาท

( นายวัฒนพงษ์ สุกใส )
ผู้อำนวยการ
สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อมจังหวัดภูเก็ต

ได้รับเงินตามจำนวนข้างต้นเรียบร้อยแล้ว
ผู้รับเงิน .....
วันที่ .....
(ลายมือชื่อและประทับตรา)

---

## ใบแจ้งยอดการชำระเงินเพื่อนำเข้าบัญชี

ส่วนของธนาคารและตัวแทนรับชำระเงิน

สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อมจังหวัดภูเก็ต (ค่าใช้น้ำบาดาล)
ผู้ชำระเงิน
บริษัท รีสอร์ทไลฟ์ จำกัด

ธนาคารกรุงไทย Comp. Code : 1168 สนง.ทสจ. ภูเก็ต

| | |
|---|---|
| REF1 | 3120241060080 |
| REF2 | 20240430000617900 |
| กำหนดชำระเงิน | ภายในวันที่ 30/04/2567 |

| | | | | |
|---|---|---|---|---|
| สาขาของธนาคารที่รับฝาก | | วันที่ชำระเงิน | | สำหรับเจ้าหน้าที่ธนาคารผู้รับเงิน |
| เงินสด/Cash | | | จำนวนเงิน/Amount | |
| เลขที่เช็ค / Chq No. | ธนาคาร / สาขา Bank/Branch | เช็คลงวันที่ / Chq Due Date | จำนวนเงิน/Amount | ผู้รับมอบอำนาจ |
| ยอดรวม จำนวนเงินที่ชำระ / Total Payment (ตัวอักษร) ****สี่หมื่นหกพันหนึ่งร้อยเจ็ดสิบเก้าบาทถ้วน**** | | | จำนวนเงิน/Amount 46,179.00 | |

# ใบแจ้งหนี้/ใบเสร็จรับเงิน ค่าใช้น้ำบาดาลและค่าอนุรักษ์น้ำบาดาล

ส่วนของลูกค้า

สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อมจังหวัดภูเก็ต
เลขที่ 109/401 หมู่ที่ 1 ตำบลวิชิต อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83000
โทร. 076 211067 ต่อ 15 หรือ 086 3910327 โทรสาร 076-216974
E-mail water_report@hotmail.com

| | |
|---|---|
| เลขที่ | 31-2024-2-0490 |
| REF1 | 3120242049036 |
| REF2 | 202407300004375876 |
| กำหนดชำระเงิน | ภายในวันที่ 30/07/2567 |
| จำนวนเงินที่ต้องชำระ | 43,758.76 |

เรียน บริษัท รีสอร์ทไลฟ์ จำกัด
เลขที่ 56/80 หมู่ 4 ซอยสุขสันต์ 3
ตำบลราไวย์ อำเภอเมืองภูเก็ต จ.ภูเก็ต
83130

ที่ ภก.0014.4/ วันที่ /07/2567 ประจำงวด 2/2567 (เม.ย. 67 - มิ.ย. 67)

| ลำดับที่ | หมายเลขบ่อน้ำบาดาล | หมายเลขใบอนุญาตใช้น้ำบาดาล | ปริมาณน้ำที่ได้รับอนุญาต | อัตรา (บาท/ลบ.ม.) ค่าใช้น้ำฯ | อัตรา (บาท/ลบ.ม.) ค่าอนุรักษ์ฯ | ปริมาณน้ำที่ใช้ (ลบ.ม.) | รวมเงิน ค่าใช้น้ำฯ | รวมเงิน ค่าอนุรักษ์ฯ | รวมเป็นเงินทั้งสิ้น |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 6004-0210 | 31-50466-0205 | 60.00 ลบ.ม./วัน | 3.50 (ลดหย่อน) | .00 (ยกเว้น) | 10,820.0 | 28,402.50 | 0.00 | 28,402.50 |
| 2 | 6004-0207 | 31-50466-0203 | 60.00 ลบ.ม./วัน | 3.50 (ลดหย่อน) | .00 (ยกเว้น) | 216.0 | 567.00 | 0.00 | 567.00 |
| 3 | 6004-0208 | 31-50466-0204 | 60.00 ลบ.ม./วัน | 3.50 (ลดหย่อน) | .00 (ยกเว้น) | 2,781.0 | 7,300.13 | 0.00 | 7,300.13 |
| 4 | 6004-0209 | 31-50466-0202 | 60.00 ลบ.ม./วัน | 3.50 (ลดหย่อน) | .00 (ยกเว้น) | 2,853.0 | 7,489.13 | 0.00 | 7,489.13 |
| ****สี่หมื่นสามพันเจ็ดร้อยห้าสิบแปดบาทเจ็ดสิบหกสตางค์**** | | | | | | | 43,758.76 | 0.00 | 43,758.76 |

**หมายเหตุ**
หากชำระเงินเกินกำหนด และ/หรือ จำนวนเงินไม่เท่ากับยอดรวมของใบแจ้งหนี้ และ/หรือ ชำระเงินเพิ่ม กรุณาติดต่อขอชำระเงินที่สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อมจังหวัดภูเก็ต
ใบเสร็จรับเงินนี้จะสมบูรณ์ต่อเมื่อมีลายมือชื่อผู้รับเงินพร้อมการประทับตราและทางราชการได้รับเงินครบถ้วนแล้ว

**คำเตือน**
หากชำระเงินระหว่างวันที่ 31/07/2567 ถึงวันที่ 29/08/2567 คิดอัตรา 1.1 เท่า เป็นเงิน 48,134.64 บาท
หากชำระเงินระหว่างวันที่ 30/08/2567 ถึงวันที่ 28/09/2567 คิดอัตรา 1.2 เท่า เป็นเงิน 52,510.51 บาท
หากชำระเงินระหว่างวันที่ 29/09/2567 ถึงวันที่ 28/10/2567 คิดอัตรา 1.3 เท่า เป็นเงิน 56,886.39 บาท
หากชำระเงินตั้งแต่วันที่ 29/10/2567 เป็นต้นไป คิดอัตรา 2 เท่า เป็นเงิน 87,517.52 บาท

จ.ชาย

( นายวัฒนพงษ์ สุกใส )
ผู้อำนวยการ
สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อมจังหวัดภูเก็ต

ได้รับเงินตามจำนวนข้างต้นเรียบร้อยแล้ว
ผู้รับเงิน _____
วันที่ _____
(ลงลายมือชื่อและประทับตรา)

---

# ใบแจ้งยอดการชำระเงินเพื่อนำเข้าบัญชี

ส่วนของธนาคารและตัวแทนรับชำระเงิน

สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อมจังหวัดภูเก็ต (ค่าใช้น้ำบาดาล)
ผู้ชำระเงิน
บริษัท รีสอร์ทไลฟ์ จำกัด

| | |
|---|---|
| REF1 | 3120242049036 |
| REF2 | 202407300004375876 |
| กำหนดชำระเงิน | ภายในวันที่ 30/07/2567 |

ธนาคารกรุงไทย Comp. Code : 1168 สนง.ทสจ. ภูเก็ต

| | | | | |
|---|---|---|---|---|
| สาขาของธนาคารที่รับฝาก | | วันที่ชำระเงิน | | สำหรับเจ้าหน้าที่ธนาคารผู้รับเงิน |
| เงินสด/Cash | | | จำนวนเงิน/Amount | |
| เลขที่เช็ค / Chq No. | ธนาคาร / สาขา Bank/Branch | เช็คลงวันที่ / Chq Due Date | จำนวนเงิน/Amount | ผู้รับมอบอำนาจ |
| ยอดรวม จำนวนเงินที่ชำระ / Total Payment (ตัวอักษร) ****สี่หมื่นสามพันเจ็ดร้อยห้าสิบแปดบาทเจ็ดสิบหกสตางค์**** | | | จำนวนเงิน/Amount 43,758.76 | |

# เอกสารแนบที่ 9

# ใบเสร็จมูลฝอย

ใบเสร็จรับเงิน/ใบกำกับภาษี

นางสาวสลิลทิพย์ กิตติธรกุล

เลขที่ 69/162 ถนนเจ้าฟ้า ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83130

โทรศัพท์ 095-0519999 เลขประจำตัวผู้เสียภาษี 3839900281273

ชื่อลูกค้า : Resortlife Co.,Ltd.(สาขา00001) เลขที่ : 001/2567

ที่อยู่ : 56/80 หมู่ที่ 4 ตำบลราไวย์ อำเภอเมือง จังหวัดภูเก็ต วันที่ : 31/01/2567

เลขประจำตัวผู้เสียภาษี 01055 58184 379

| ลำดับ | รายละเอียด | จำนวน | จำนวนเงิน |
|---|---|---|---|
| 1 | ค่าเก็บขยะมูลฝอยประจำเดือน มกราคม | 1 | 12,000.00 |

| | | |
|---|---|---|
| | จำนวนเงิน | 12,000.00 |
| | ภาษีมูลค่าเพิ่ม7% | 840.00 |
| ( หนึ่งหมื่นสองพันแปดร้อยสี่สิบบาทถ้วน ) | ยอดเงินสุทธิ | 12,840.00 |

ลูกค้า : .....

วันที่ : .....

ผู้รับเงิน : .....

วันที่ : 31.01.67

ใบเสร็จรับเงิน/ใบกำกับภาษี

นางสาวสลิลทิพย์ กิตติธรกุล

เลขที่ 69/162 ถนนเจ้าฟ้า ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83130

โทรศัพท์ 095-0519999 เลขประจำตัวผู้เสียภาษี 3839900281273

ชื่อลูกค้า : Resortlife Co.,Ltd.(สาขา00001) เลขที่ : 002/2567

ที่อยู่ : 56/80 หมู่ที่ 4 ตำบลราไวย์ อำเภอเมือง จังหวัดภูเก็ต วันที่ : 29/02/2567

เลขประจำตัวผู้เสียภาษี 01055 58184 379

| ลำดับ | รายละเอียด | จำนวน | จำนวนเงิน |
|---|---|---|---|
| 1 | ค่าเก็บขยะมูลฝอยประจำเดือน กุมภาพันธ์ | 1 | 12,000.00 |

| | | |
|---|---|---|
| | จำนวนเงิน | 12,000.00 |
| | ภาษีมูลค่าเพิ่ม7% | 840.00 |
| ( หนึ่งหมื่นสองพันแปดร้อยสี่สิบบาทถ้วน ) | ยอดเงินสุทธิ | 12,840.00 |

ลูกค้า : .....

วันที่ : .....

ผู้รับเงิน : .....

วันที่ : 29.2.62

ใบเสร็จรับเงิน/ใบกำกับภาษี

นางสาวสลิลทิพย์ กิตติธรกุล

เลขที่ 69/162 ถนนเจ้าฟ้า ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83130

โทรศัพท์ 095-0519999 เลขประจำตัวผู้เสียภาษี 3839900281273

ชื่อลูกค้า : Resortlife Co.,Ltd.(สาขา00001) เลขที่ : 003/2567

ที่อยู่ : 56/80 หมู่ที่ 4 ตำบลราไวย์ อำเภอเมือง จังหวัดภูเก็ต วันที่ : 31/03/2567

เลขประจำตัวผู้เสียภาษี 01055 58184 379

| ลำดับ | รายละเอียด | จำนวน | จำนวนเงิน |
|---|---|---|---|
| 1 | ค่าเก็บขยะมูลฝอยประจำเดือน มีนาคม | 1 | 12,000.00 |
| | | จำนวนเงิน | 12,000.00 |
| | | ภาษีมูลค่าเพิ่ม7% | 840.00 |
| | ( หนึ่งหมื่นสองพันแปดร้อยสี่สิบบาทถ้วน ) | ยอดเงินสุทธิ | 12,840.00 |

ลูกค้า : .....

วันที่ : .....

ผู้รับเงิน : .....

วันที่ : 31.3.67

ใบเสร็จรับเงิน/ใบกำกับภาษี

นางสาวสลิลทิพย์ กิตติธรกุล

เลขที่ 69/162 ถนนเจ้าฟ้า ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83130

โทรศัพท์ 095-0519999 เลขประจำตัวผู้เสียภาษี 3839900281273

ชื่อลูกค้า : Resortlife Co.,Ltd.(สาขา00001) เลขที่ : 006/2567

ที่อยู่ : 56/80 หมู่ที่ 4 ตำบลราไวย์ อำเภอเมือง จังหวัดภูเก็ต วันที่ : 30/06/2567

เลขประจำตัวผู้เสียภาษี 01055 58184 379

| ลำดับ | รายละเอียด | จำนวน | จำนวนเงิน |
|---|---|---|---|
| 1 | ค่าเก็บขยะมูลฝอยประจำเดือน มิถุนายน | 1 | 12,000.00 |
| | | จำนวนเงิน | 12,000.00 |
| | | ภาษีมูลค่าเพิ่ม7% | 840.00 |
| | ( หนึ่งหมื่นสองพันแปดร้อยสี่สิบบาทถ้วน ) | ยอดเงินสุทธิ | 12,840.00 |

ลูกค้า : .....

วันที่ : .....

ผู้รับเงิน : .....

วันที่ : 30.6.67

ใบเสร็จรับเงิน/ใบกำกับภาษี

นางสาวสลิลทิพย์ กิตติธรกุล

เลขที่ 69/162 ถนนเจ้าฟ้า ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83130

โทรศัพท์ 095-0519999 เลขประจำตัวผู้เสียภาษี 3839900281273

ชื่อลูกค้า : Resortlife Co.,Ltd.(สาขา00001) เลขที่ : 005/2567

ที่อยู่ : 56/80 หมู่ที่ 4 ตำบลราไวย์ อำเภอเมือง จังหวัดภูเก็ต วันที่ : 31/05/2567

เลขประจำตัวผู้เสียภาษี 01055 58184 379

| ลำดับ | รายละเอียด | จำนวน | จำนวนเงิน |
|---|---|---|---|
| 1 | ค่าเก็บขยะมูลฝอยประจำเดือน พฤษภาคม | 1 | 12,000.00 |

| | | |
|---|---|---|
| | จำนวนเงิน | 12,000.00 |
| | ภาษีมูลค่าเพิ่ม7% | 840.00 |
| ( หนึ่งหมื่นสองพันแปดร้อยสี่สิบบาทถ้วน ) | ยอดเงินสุทธิ | 12,840.00 |

ลูกค้า : .....

วันที่ : .....

ผู้รับเงิน : สลิลทิพย์

วันที่ : 31/5/67

ใบเสร็จรับเงิน/ใบกำกับภาษี

นางสาวสลิลทิพย์ กิตติธรกุล

เลขที่ 69/162 ถนนเจ้าฟ้า ตำบลฉลอง อำเภอเมืองภูเก็ต จังหวัดภูเก็ต 83130

โทรศัพท์ 095-0519999 เลขประจำตัวผู้เสียภาษี 3839900281273

ชื่อลูกค้า : Resortlife Co.,Ltd.(สาขา00001) เลขที่ : 004/2567

ที่อยู่ : 56/80 หมู่ที่ 4 ตำบลราไวย์ อำเภอเมือง จังหวัดภูเก็ต วันที่ : 30/04/2567

เลขประจำตัวผู้เสียภาษี 01055 58184 379

| ลำดับ | รายละเอียด | จำนวน | จำนวนเงิน |
|---|---|---|---|
| 1 | ค่าเก็บขยะมูลฝอยประจำเดือน เมษายน | 1 | 12,000.00 |

| | | |
|---|---|---|
| | จำนวนเงิน | 12,000.00 |
| | ภาษีมูลค่าเพิ่ม7% | 840.00 |
| ( หนึ่งหมื่นสองพันแปดร้อยสี่สิบบาทถ้วน ) | ยอดเงินสุทธิ | 12,840.00 |

ลูกค้า : .....

วันที่ : .....

ผู้รับเงิน : สลิลทิพย์

วันที่ : 30/4/67

# เอกสารแนบที่ 10

# รายงานการตรวจเช็คกล้องวงจรปิด (CCTV)

## Report CCTV of NVR1

Jan-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 1 | Courtyard-01 | | Online | กล้องบริเวณประตูทางเข้า Fresca |
| 2 | 1 | Courtyard-02 | | Online | กล้องบริเวณทางขึ้นบันได้ Fresca |
| 3 | 1 | Fresca-01 | | Online | กล้องบริเวณภายใน Fresca ใกล้แคชเชียร์ |
| 4 | 1 | Fresca-02 | | Online | กล้องบริเวณภายใน Fresca ใกล้บาร์ กับ เครื่องทำกาแฟ |
| 5 | 1 | Fresca-03 | | Online | กล้องบริเวณแคชเชียร์ Fresca |
| 6 | 1 | Fresca-04 | | Online | กล้องบริเวณหน้าลิฟ ชั้น 1 ภายใน Fresca |
| 7 | 1 | Fresca-05 | | Online | กล้องบริเวณที่จอดรถใกล้ Fresca |
| 8 | 1 | Coridor-B-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหน้า |
| 9 | 1 | Coridor-B-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหลัง |

## Report CCTV of NVR1

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 10 | 1 | Coridor-B-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได้ ตึก B ชั้น 2 |
| 11 | 1 | Coridor-B-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหน้า |
| 12 | 1 | Coridor-B-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหลัง |
| 13 | 1 | Outdoor-B14-02 | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซด์ |
| 14 | 1 | Outdoor-B14-01 | | Online | กล้องบริเวณบันไดทางเข้าโรงแรม |
| 15 | 1 | Reception-01 | | Online | กล้องบริเวณหน้า Reception ใกล้ทางเข้าห้องน้ำ |
| 16 | 1 | Lobby-02 | | Online | กล้องบริเวณหน้าลิฟท์ Clinic ชั้น 1 ใกล้ Reception |
| 17 | 1 | Luggage Room | | Online | กล้องบริเวณภายในห้องเก็บของสัมภาระของลูกค้า |
| 18 | 1 | Safe Room | | Online | กล้องบริเวณภายในห้องเก็บตู้เซฟและเอกสารสำคัญ |
| 19 | 1 | Lobby-01 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ทางเข้าโรงแรม |

## Report CCTV of NVR1

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 20 | 1 | Reception-02 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ห้องประชุม |
| 21 | 1 | Lobby-03 | | Online | กล้องบริเวณ โถงรับแขก ใกล้บันไดทางขึ้นไปห้อง โยคะ |
| 22 | 1 | Outdoor-Lobby-15 | | Online | กล้องบริเวณจุดรับสัมภาระ ใกล้ร้านอาหาร Fresca |
| 23 | 1 | Coridor-D-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ให้ทางเดินไปตึก E |
| 24 | 1 | Coridor-D-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ลิฟท์ |
| 25 | 1 | Coridor-D-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ห้อง D106 |
| 26 | 1 | Coridor-D-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D203 |
| 27 | 1 | Coridor-D-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D208 |
| 28 | 1 | Coridor-D-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ห้อง D303 |
| 29 | 1 | Coridor-D-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ ห้อง D306 |

## Report CCTV of NVR1

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 30 | 1 | Shop DELI | | Online | กล้องบริเวณภายใน Shop deli Fresca |
| 31 | 1 | Hot kitchen | | Online | กล้องบริเวณภายในห้องครัวร้อน Fresca |
| 32 | 1 | Stewarding | | Online | กล้องบริเวณภายในห้องล้างจาน Fresca |

## Report CCTV of NVR2

Jan-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 2 | Coridor-C-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลานจอดรถ |
| 2 | 2 | Coridor-C-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลิฟท์ |
| 3 | 2 | Coridor-C-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 |
| 4 | 2 | Coridor-C-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C203 |
| 5 | 2 | Coridor-C-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C208 - C209 |
| 6 | 2 | Coridor-C-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C302 - C303 |
| 7 | 2 | Coridor-C-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C306 |
| 8 | 2 | Outdoor-C-45 | | Online | กล้องบริเวณทางเดิน ตึก C ไป ตึก B ใกล้ลานจอดรถ |
| 9 | 2 | Outdoor-C-48 | | Online | กล้องบริเวณทางเดิน สระน้ำ ใกล้ตึก C |

## Report CCTV of NVR2

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 10 | 2 | Coridor-G-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G101 |
| 11 | 2 | Coridor-G-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G105 |
| 12 | 2 | Coridor-G-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก G ชั้น 2 |
| 13 | 2 | Coridor-G-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G201 |
| 14 | 2 | Coridor-G-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G205 - G206 |
| 15 | 2 | Coridor-H-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H101 |
| 16 | 2 | Coridor-H-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H105 |
| 17 | 2 | Coridor-H-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก H ชั้น 2 |
| 18 | 2 | Coridor-H-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H201 |

## Report CCTV of NVR2

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 19 | 2 | Coridor-H-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H205 - H206 |
| 20 | 2 | Outdoor-H-26 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก H |
| 21 | 2 | Outdoor-H-29 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก H ใกล้สระน้ำ |
| 22 | 2 | Coridor-E-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ลานจอดรถ |
| 23 | 2 | Coridor-E-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ลิฟท์ |
| 24 | 2 | Coridor-E-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 1 ใกล้ ห้อง E106 |
| 25 | 2 | Coridor-E-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 ใกล้ห้อง E203 |
| 26 | 2 | Coridor-E-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 |
| 27 | 2 | Coridor-E-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E303 |

## Report CCTV of NVR2

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 28 | 2 | Coridor-E-F3-07 |  | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E306 |
| 29 | 2 | Outdoor-E-54 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก E ใกล้สระน้ำ |
| 30 | 2 | Outdoor-D-55 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้สระน้ำ |
| 31 | 2 | Outdoor-D-56 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้บันไดขึ้นสระน้ำ |
| 32 | 2 | Outdoor-D-57 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้ห้องน้ำ |

## Report CCTV of NVR3

Jan-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 3 | Coridor-F-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 |
| 2 | 3 | Coridor-F-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลานจอดรถ |
| 3 | 3 | Coridor-F-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลิฟท์ |
| 4 | 3 | Coridor-F-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F202 - F203 |
| 5 | 3 | Coridor-F-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F206 |
| 6 | 3 | Coridor-F-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F301 |
| 7 | 3 | Coridor-F-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F304 |
| 8 | 3 | Outdoor-F-49 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สระน้ำ |
| 9 | 3 | Outdoor-F-50 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สนามเด็กเล่น |
| 10 | 3 | Coridor-A-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A101 |

## Report CCTV of NVR3

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 11 | 3 | Coridor-A-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A105 |
| 12 | 3 | Coridor-A-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก A ชั้น 2 |
| 13 | 3 | Coridor-A-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A201 |
| 14 | 3 | Coridor-A-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A205 - A206 |
| 15 | 3 | Outdoor-A-36 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ staygreen |
| 16 | 3 | Outdoor-A-37 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ทางเชื่อมไป ตึก B |
| 17 | 3 | Outdoor-A-39 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ประตูไม้ |
| 18 | 3 | B12-F1-01 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 1 |
| 19 | 3 | B12-F1-02 | | Online | กล้องบริเวณ Reception stayfit ชั้น 1 |
| 20 | 3 | B12-F1-03 | | Online | กล้องบริเวณทางเข้า Stayfit |

## Report CCTV of NVR3

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 21 | 3 | B12-F2-04 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 2 |
| 22 | 3 | B12-F3-05 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 3 |
| 23 | 3 | Lift-C | | Online | กล้องบริเวณภายในลิฟท์ ตึก C |
| 24 | 3 | Lift-D | | Online | กล้องบริเวณภายในลิฟท์ ตึก D |
| 25 | 3 | Lift-E | | Online | กล้องบริเวณภายในลิฟท์ ตึก E |
| 26 | 3 | Lift-F | | Online | กล้องบริเวณภายในลิฟท์ ตึก F |
| 27 | 3 | Poolbar-01 | | Online | กล้องบริเวณเคาน์เตอร์ Staygreen |
| 28 | 3 | Poolbar-02 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-03 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-Kitchen | | Online | กล้องบริเวณภายในห้องครัว ร้านอาหาร Staygreen |

## Report CCTV of NVR4

Jan-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 4 | B15-Meeting | | Online | กล้องบริเวณทางเดิน ตึก Fresca ชั้น 2 ใกล้ห้อง meeting |
| 2 | 4 | Thai-Restaurant-01 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 |
| 3 | 4 | Thai-Restaurant-02 | | Online | กล้องบริเวณภายในร้าน kamin restaurant ชั้น 3 ด้านหลัง |
| 4 | 4 | Thai-Restaurant-03 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 ทางเข้า |
| 5 | 4 | BM-Canteen | | Online | กล้องภายในโรงอาหาร พนักงาน ชั้นใต้ดิน |
| 6 | 4 | BM-Receiving | | Online | กล้องบริเวณพื้นที่รับ-ส่งของ ชั้นใต้ดิน |
| 7 | 4 | BM-Purchase | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้องจัดซื้อ |
| 8 | 4 | BM-Kitchen | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้อง butcher |
| 9 | 4 | Spa-01 | | Online | กล้องบริเวณ Reception Spa |

## Report CCTV of NVR4

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 10 | 4 | Spa-02 | | Online | กล้องบริเวณ Reception Spa โซนนั่งเล่น |
| 11 | 4 | Spa-03 | | Online | กล้องบริเวณทางเดินไปชั้น 2 ใกล้ห้องล็อคเกอร์ |
| 12 | 4 | Spa-04 | | Online | กล้องบริเวณทางเดินไป Onsen ตึก Spa ใกล้ห้องพนักงาน |
| 13 | 4 | Spa-FL2-1 | | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 ใกล้บันไดทางขึ้น |
| 14 | 4 | Spa-FL2-2 | | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 |
| 15 | 4 | Yoga | | Online | กล้องบริเวณหน้าห้อง Yoga ชั้น 2 |
| 16 | 4 | Server Room | | Online | กล้องบริเวณหน้าห้อง Server ชั้น 2 ใกล้ Clinic |
| 17 | 4 | Clinic | | Online | กล้องบริเวณ Reception Clinic |
| 18 | 4 | Outdoor-Spa-1 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้จุด สูบบุหรี่ |
| 19 | 4 | Outdoor-Spa-2 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้ลานจอดจักรยาน |

## Report CCTV of NVR4

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 20 | 4 | Outdoor-Spa-3 | | Online | กล้องบริเวณทางเดิน ภายนอก ตึก Spa ใกล้ประตูไม้ |
| 21 | 4 | Outdoor-Spa-4 | | Online | กล้องบริเวณทางเดินภายนอก ตึก Spa ด้านหลัง ใกล้ ตึก A |
| 22 | 4 | Stroe Wine | | Online | กล้องบริเวณภายในห้องเก็บไวน์ |
| 23 | 4 | Acc-Room | | Online | บริเวณภายในห้อง บัญชี |

## Report CCTV of NVR5

Jan-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 5 | MainEntrance-IN | | Online | กล้องบริเวณทางเข้าที่จอดรถโรงแรม ใกล้ป้อมยาม |
| 2 | 5 | MainEntrance-OUT | | Online | กล้องบริเวณลานจอดรถยนต์ |
| 3 | 5 | Car Park 1 (Gen) | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ป้อมยาม |
| 4 | 5 | Car Park 2 | | Online | กล้องบริเวณที่จอดรถหน้าโรงแรม |
| 5 | 5 | Car Park 3 | | Online | กล้องบริเวณลานจอดรถ |
| 6 | 5 | Car Park 4 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 92 |
| 7 | 5 | Car Park 5 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 91 |
| 8 | 5 | Spirit House | | Online | กล้องบริเวณทางเข้าประตู Villa ใกล้ ศาลพระภูมิ |
| 9 | 5 | Outdoor-Villa-1 | | Online | กล้องบริเวณถนน Villa ใกล้ด้านหลัง Stayfit |

## Report CCTV of NVR5

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 10 | 5 | Outdoor-Villa-2 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 1 |
| 11 | 5 | Outdoor-Villa-3 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 8 |
| 12 | 5 | Outdoor-Villa-4 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 9 |
| 13 | 5 | ExitDoor-Villa | | Online | กล้องบริเวณประตูทางออกไป 4 ไร่ |
| 14 | 5 | Outdoor-H | | Online | กล้องบริเวณถนน ใกล้ตึก H |
| 15 | 5 | Outdoor-G | | Online | กล้องบริเวณถนน ใกล้ตึก G |
| 16 | 5 | Outdoor-F | | Online | กล้องบริเวณถนน ใกล้ตึก F |
| 17 | 5 | Outdoor-E-1 | | Online | กล้องบริเวณถนน ใกล้ตึก E |
| 18 | 5 | Outdoor-E-2 | | Online | กล้องบริเวณถนน ใกล้ตึก E ใกล้ลานจอดรถ |

## Report CCTV of NVR5

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 19 | 5 | Outdoor-E-3 | | Online | กล้องบริเวณถนน ตึก E ใกล้ลานจอดรถ |
| 20 | 5 | Outdoor-D-1 | | Online | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 21 | 5 | Outdoor-D-2 | | Offline | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 22 | 5 | Outdoor-C-1 | | Online | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |
| 23 | 5 | Outdoor-C-2 | | Offline | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |

## Report CCTV of NVR6 at 4Rai

Jan-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 6 | Right entrance | | Online | กล้องบริเวณประตูทางเข้าหอพัก 4ไร่ ชั้น 1 |
| 2 | 6 | Second floor stairs | | Online | กล้องบริเวณบันไดหอพัก 4 ไร่ ชั้น 2 |
| 3 | 6 | Boxing stadium door | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 4 | 6 | Boxing stadium left | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 5 | 6 | Boxing stadium | | Online | กล้องบริเวณเวที 8 มวยไทย ชั้น 3 |
| 6 | 6 | HK Store-1 | | Online | กล้องบริเวณภายในห้องแม่บ้าน |
| 7 | 6 | HK Store-2 | | Online | กล้องบริเวณภายในห้องเก็บของแม่บ้าน |
| 8 | 6 | Parking | | Online | กล้องบริเวณลานจอดรถมอเตอร์ไซค์ |
| 9 | 6 | Staff room | | Online | กล้องบริเวณทางเดินหอพักพนักงาน |

## Report CCTV of NVR6 at 4Rai

Jan-24

| | | | | | |
|---|---|---|---|---|---|
| 10 | 6 | Workshop | | Online | กล้องบริเวณห้องเก็บของช่าง ด้านใน |
| 11 | 6 | Workshop2 | | Online | กล้องบริเวณห้องเก็บของช่าง |
| 12 | 6 | Office stairs | | Online | กล้องบริเวณบันไดชั้น 2 ใกล้ประตูทางเข้า Office HR |
| 13 | 6 | OFFICE | | Online | กล้องบริเวณ Office HR |
| 14 | 6 | StayWild | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ประตูทางเข้าหอพักพนักงาน |
| 15 | 6 | Front area | | Online | กล้องบริเวณลานจอดรถ 4ไร่ (มุมสูง) ชั้น 3 |
| 15 | 6 | Staff room | | Online | กล้องบริเวณทางเดินไปห้อง Staff Locker |

## Report CCTV of NVR1

Feb-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 1 | Courtyard-01 | | Online | กล้องบริเวณประตูทางเข้า Fresca |
| 2 | 1 | Courtyard-02 | | Online | กล้องบริเวณทางขึ้นบันได Fresca |
| 3 | 1 | Fresca-01 | | Online | กล้องบริเวณภายใน Fresca ใกล้แคชเชียร์ |
| 4 | 1 | Fresca-02 | | Online | กล้องบริเวณภายใน Fresca ใกล้บาร์ กับ เครื่องทำกาแฟ |
| 5 | 1 | Fresca-03 | | Online | กล้องบริเวณแคชเชียร์ Fresca |
| 6 | 1 | Fresca-04 | | Online | กล้องบริเวณหน้าลิฟ ชั้น 1 ภายใน Fresca |
| 7 | 1 | Fresca-05 | | Online | กล้องบริเวณที่จอดรถใกล้ Fresca |
| 8 | 1 | Coridor-B-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหน้า |
| 9 | 1 | Coridor-B-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหลัง |
| 10 | 1 | Coridor-B-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก B ชั้น 2 |
| 11 | 1 | Coridor-B-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหน้า |

| | | | | | |
|---|---|---|---|---|---|
| 12 | 1 | Coridor-B-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหลัง |
| 13 | 1 | Outdoor-B14-02 | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ |
| 14 | 1 | Outdoor-B14-01 | | Online | กล้องบริเวณบันไดทางเข้าโรงแรม |
| 15 | 1 | Reception-01 | | Online | กล้องบริเวณหน้า Reception ใกล้ทางเข้าห้องน้ำ |
| 16 | 1 | Lobby-02 | | Online | กล้องบริเวณหน้าลิฟท์ Clinic ชั้น 1 ใกล้ Reception |
| 17 | 1 | Luggage Room | | Online | กล้องบริเวณภายในห้องเก็บของสัมภาระของลูกค้า |
| 18 | 1 | Safe Room | | Online | กล้องบริเวณภายในห้องเก็บตู้เซฟและเอกสารสำคัญ |
| 19 | 1 | Lobby-01 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ทางเข้าโรงแรม |
| 20 | 1 | Reception-02 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ห้องประชุม |
| 21 | 1 | Lobby-03 | | Online | กล้องบริเวณ โถงรับแขก ใกล้บันไดทางขึ้นไปห้อง โยคะ |
| 22 | 1 | Outdoor-Lobby-15 | | Online | กล้องบริเวณจุดรับสัมภาระ ใกล้ร้านอาหาร Fresca |
| 23 | 1 | Coridor-D-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ให้ทางเดินไปตึก E |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 1 | Coridor-D-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ลิฟท์ |
| 25 | 1 | Coridor-D-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ห้อง D106 |
| 26 | 1 | Coridor-D-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D203 |
| 27 | 1 | Coridor-D-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D208 |
| 28 | 1 | Coridor-D-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ห้อง D303 |
| 29 | 1 | Coridor-D-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ ห้อง D306 |
| 30 | 1 | Shop DELI | | Online | กล้องบริเวณภายใน Shop deli Fresca |
| 31 | 1 | Hot kitchen | | Online | กล้องบริเวณภายในห้องครัวร้อน Fresca |
| 32 | 1 | Stewarding | | Online | กล้องบริเวณภายในห้องล้างจาน Fresca |

## Report CCTV of NVR2

Feb-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 2 | Coridor-C-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลานจอดรถ |
| 2 | 2 | Coridor-C-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลิฟท์ |
| 3 | 2 | Coridor-C-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 |
| 4 | 2 | Coridor-C-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C203 |
| 5 | 2 | Coridor-C-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C208 - C209 |
| 6 | 2 | Coridor-C-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C302 - C303 |
| 7 | 2 | Coridor-C-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C306 |
| 8 | 2 | Outdoor-C-45 | | Online | กล้องบริเวณทางเดิน ตึก C ไป ตึก B ใกล้ลานจอดรถ |
| 9 | 2 | Outdoor-C-48 | | Online | กล้องบริเวณทางเดิน สระน้ำ ใกล้ตึก C |
| 10 | 2 | Coridor-G-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G101 |
| 11 | 2 | Coridor-G-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G105 |
| 12 | 2 | Coridor-G-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก G ชั้น 2 |
| 13 | 2 | Coridor-G-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G201 |
| 14 | 2 | Coridor-G-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G205 - G206 |
| 15 | 2 | Coridor-H-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H101 |
| 16 | 2 | Coridor-H-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H105 |
| 17 | 2 | Coridor-H-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก H ชั้น 2 |
| 18 | 2 | Coridor-H-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H201 |
| 19 | 2 | Coridor-H-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H205 - H206 |
| 20 | 2 | Outdoor-H-26 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก H |
| 21 | 2 | Outdoor-H-29 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก H ใกล้สระน้ำ |
| 22 | 2 | Coridor-E-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ ลานจอดรถ |
| 23 | 2 | Coridor-E-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ ลิฟท์ |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 2 | Coridor-E-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 1 ใกล้ ห้อง E106 |
| 25 | 2 | Coridor-E-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 ใกล้ห้อง E203 |
| 26 | 2 | Coridor-E-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 |
| 27 | 2 | Coridor-E-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E303 |
| 28 | 2 | Coridor-E-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E306 |
| 29 | 2 | Outdoor-E-54 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก E ใกล้สระน้ำ |
| 30 | 2 | Outdoor-D-55 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้สระน้ำ |
| 31 | 2 | Outdoor-D-56 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้บันไดขึ้นสระน้ำ |
| 32 | 2 | Outdoor-D-57 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้ห้องน้ำ |

## Report CCTV of NVR3

Feb-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 3 | Coridor-F-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 |
| 2 | 3 | Coridor-F-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลานจอดรถ |
| 3 | 3 | Coridor-F-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลิฟท์ |
| 4 | 3 | Coridor-F-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F202 - F203 |
| 5 | 3 | Coridor-F-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F206 |
| 6 | 3 | Coridor-F-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F301 |
| 7 | 3 | Coridor-F-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F304 |
| 8 | 3 | Outdoor-F-49 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สระน้ำ |
| 9 | 3 | Outdoor-F-50 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สนามเด็กเล่น |
| 10 | 3 | Coridor-A-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A101 |
| 11 | 3 | Coridor-A-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A105 |
| 12 | 3 | Coridor-A-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก A ชั้น 2 |

| | | | | | |
|---|---|---|---|---|---|
| 13 | 3 | Coridor-A-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A201 |
| 14 | 3 | Coridor-A-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A205 - A206 |
| 15 | 3 | Outdoor-A-36 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ staygreen |
| 16 | 3 | Outdoor-A-37 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ทางเชื่อมไป ตึก B |
| 17 | 3 | Outdoor-A-39 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ประตูไม้ |
| 18 | 3 | B12-F1-01 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 1 |
| 19 | 3 | B12-F1-02 | | Online | กล้องบริเวณ Reception stayfit ชั้น 1 |
| 20 | 3 | B12-F1-03 | | Online | กล้องบริเวณทางเข้า Stayfit |
| 21 | 3 | B12-F2-04 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 2 |
| 22 | 3 | B12-F3-05 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 3 |
| 23 | 3 | Lift-C | | Online | กล้องบริเวณภายในลิฟท์ ตึก C |
| 24 | 3 | Lift-D | | Online | กล้องบริเวณภายในลิฟท์ ตึก D |
| 25 | 3 | Lift-E | | Online | กล้องบริเวณภายในลิฟท์ ตึก E |

| | | | | | |
|---|---|---|---|---|---|
| 26 | 3 | Lift-F | | Online | กล้องบริเวณภายในลิฟท์ ตึก F |
| 27 | 3 | Poolbar-01 | | Online | กล้องบริเวณเคาน์เตอร์ Staygreen |
| 28 | 3 | Poolbar-02 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-03 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-Kitchen | | Online | กล้องบริเวณภายในห้องครัว ร้านอาหาร Staygreen |

Feb-24

## Report CCTV of NVR4

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 4 | B15-Meeting | | Online | กล้องบริเวณทางเดิน ตึก Fresca ชั้น 2 ใกล้ห้อง meeting |
| 2 | 4 | Thai-Restaurant-01 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 |
| 3 | 4 | Thai-Restaurant-02 | | Online | กล้องบริเวณภายในร้าน kamin restaurant ชั้น 3 ด้านหลัง |
| 4 | 4 | Thai-Restaurant-03 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 ทางเข้า |
| 5 | 4 | BM-Canteen | | Online | กล้องภายในโรงอาหาร พนักงาน ชั้นใต้ดิน |
| 6 | 4 | BM-Receiving | | Online | กล้องบริเวณพื้นที่รับ-ส่งของ ชั้นใต้ดิน |
| 7 | 4 | BM-Purchase | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้องจัดซื้อ |
| 8 | 4 | BM-Kitchen | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้อง butcher |
| 9 | 4 | Spa-01 | | Online | กล้องบริเวณ Reception Spa |
| 10 | 4 | Spa-02 | | Online | กล้องบริเวณ Reception Spa โซนนั่งเล่น |
| 11 | 4 | Spa-03 | | Online | กล้องบริเวณทางเดินไปชั้น 2 ใกล้ห้องล็อคเกอร์ |
| 12 | 4 | Spa-04 | | Online | กล้องบริเวณทางเดินไป Onsen ตึก Spa ใกล้ห้องพนักงาน |
| 13 | 4 | Spa-FL2-1 | | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 ใกล้บันไดทางขึ้น |
| 14 | 4 | Spa-FL2-2 | | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 |
| 15 | 4 | Yoga | | Online | กล้องบริเวณหน้าห้อง Yoga ชั้น 2 |
| 16 | 4 | Server Room | | Online | กล้องบริเวณหน้าห้อง Server ชั้น 2 ใกล้ Clinic |
| 17 | 4 | Clinic | | Online | กล้องบริเวณ Reception Clinic |
| 18 | 4 | Outdoor-Spa-1 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้จุด สูบบุหรี่ |
| 19 | 4 | Outdoor-Spa-2 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้ลานจอดจักรยาน |
| 20 | 4 | Outdoor-Spa-3 | | Online | กล้องบริเวณทางเดิน ภายนอก ตึก Spa ใกล้ประตูไม้ |
| 21 | 4 | Outdoor-Spa-4 | | Online | กล้องบริเวณทางเดินภายนอก ตึก Spa ด้านหลัง ใกล้ ตึก A |
| 22 | 4 | Stroe Wine | | Online | กล้องบริเวณภายในห้องเก็บไวน์ |
| 23 | 4 | Acc-Room | | Online | บริเวณภายในห้อง บัญชี |

## Report CCTV of NVR5

Feb-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 5 | MainEntrance-IN | | Online | กล้องบริเวณทางเข้าที่จอดรถโรงแรม ใกล้ป้อมยาม |
| 2 | 5 | MainEntrance-OUT | | Online | กล้องบริเวณลานจอดรถยนต์ |
| 3 | 5 | Car Park 1 (Gen) | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ป้อมยาม |
| 4 | 5 | Car Park 2 | | Online | กล้องบริเวณที่จอดรถหน้าโรงแรม |
| 5 | 5 | Car Park 3 | | Online | กล้องบริเวณลานจอดรถ |
| 6 | 5 | Car Park 4 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 92 |
| 7 | 5 | Car Park 5 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 91 |
| 8 | 5 | Spirit House | | Online | กล้องบริเวณทางเข้าประตู Villa ใกล้ ศาลพระภูมิ |
| 9 | 5 | Outdoor-Villa-1 | | Online | กล้องบริเวณถนน Villa ใกล้ด้านหลัง Stayfit |
| 10 | 5 | Outdoor-Villa-2 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 1 |
| 11 | 5 | Outdoor-Villa-3 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 8 |

| | | | | | |
|---|---|---|---|---|---|
| 12 | 5 | Outdoor-Villa-4 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 9 |
| 13 | 5 | ExitDoor-Villa | | Online | กล้องบริเวณประตูทางออกไป 4 ไร่ |
| 14 | 5 | Outdoor-H | | Online | กล้องบริเวณถนน ใกล้ตึก H |
| 15 | 5 | Outdoor-G | | Online | กล้องบริเวณถนน ใกล้ตึก G |
| 16 | 5 | Outdoor-F | | Online | กล้องบริเวณถนน ใกล้ตึก F |
| 17 | 5 | Outdoor-E-1 | | Online | กล้องบริเวณถนน ใกล้ตึก E |
| 18 | 5 | Outdoor-E-2 | | Online | กล้องบริเวณถนน ใกล้ตึก E ใกล้ลานจอดรถ |
| 19 | 5 | Outdoor-E-3 | | Online | กล้องบริเวณถนน ตึก E ใกล้ลานจอดรถ |
| 20 | 5 | Outdoor-D-1 | | Online | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 21 | 5 | Outdoor-D-2 | | Offline | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 22 | 5 | Outdoor-C-1 | | Online | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |
| 23 | 5 | Outdoor-C-2 | | Offline | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |

## Report CCTV of NVR6 at 4Rai

Feb-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 6 | Right entrance | | Online | กล้องบริเวณประตูทางเข้าหอพัก 4ไร่ ชั้น 1 |
| 2 | 6 | Second floor stairs | | Online | กล้องบริเวณบันไดหอพัก 4 ไร่ ชั้น 2 |
| 3 | 6 | Boxing stadium door | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 4 | 6 | Boxing stadium left | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 5 | 6 | Boxing stadium | | Online | กล้องบริเวณเวที 8 มวยไทย ชั้น 3 |
| 6 | 6 | HK Store-1 | | Online | กล้องบริเวณภายในห้องแม่บ้าน |
| 7 | 6 | HK Store-2 | | Online | กล้องบริเวณภายในห้องเก็บของแม่บ้าน |
| 8 | 6 | Parking | | Online | กล้องบริเวณลานจอดรถมอเตอร์ไซค์ |
| 9 | 6 | Staff room | | Online | กล้องบริเวณทางเดินหอพักพนักงาน |
| 10 | 6 | Workshop | | Online | กล้องบริเวณห้องเก็บของช่าง ด้านใน |
| 11 | 6 | Workshop2 | | Online | กล้องบริเวณห้องเก็บของช่าง |

| | | | | | |
|---|---|---|---|---|---|
| 12 | 6 | Office stairs | | Online | กล้องบริเวณบันไดชั้น 2 ใกล้ประตูทางเข้า Office HR |
| 13 | 6 | OFFICE | | Online | กล้องบริเวณ Office HR |
| 14 | 6 | StayWild | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ประตูทางเข้าหอพักพนักงาน |
| 15 | 6 | Front area | | Online | กล้องบริเวณลานจอดรถ 4 ไร่ (มุมสูง) ชั้น 3 |
| 15 | 6 | Staff room | | Online | กล้องบริเวณทางเดินไปห้อง Staff Locker |

## Report CCTV of NVR1

Mar-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 1 | Courtyard-01 | | Online | กล้องบริเวณประตูทางเข้า Fresca |
| 2 | 1 | Courtyard-02 | | Online | กล้องบริเวณทางขึ้นบันได้ Fresca |
| 3 | 1 | Fresca-01 | | Online | กล้องบริเวณภายใน Fresca ใกล้แคชเชียร์ |
| 4 | 1 | Fresca-02 | | Online | กล้องบริเวณภายใน Fresca ใกล้บาร์ กับ เครื่องทำกาแฟ |
| 5 | 1 | Fresca-03 | | Online | กล้องบริเวณแคชเชียร์ Fresca |
| 6 | 1 | Fresca-04 | | Online | กล้องบริเวณหน้าลิฟ ชั้น 1 ภายใน Fresca |
| 7 | 1 | Fresca-05 | | Online | กล้องบริเวณที่จอดรถใกล้ Fresca |
| 8 | 1 | Coridor-B-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหน้า |
| 9 | 1 | Coridor-B-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหลัง |
| 10 | 1 | Coridor-B-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได้ ตึก B ชั้น 2 |
| 11 | 1 | Coridor-B-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหน้า |

| | | | | | |
|---|---|---|---|---|---|
| 12 | 1 | Coridor-B-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหลัง |
| 13 | 1 | Outdoor-B14-02 | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ |
| 14 | 1 | Outdoor-B14-01 | | Online | กล้องบริเวณบันไดทางเข้าโรงแรม |
| 15 | 1 | Reception-01 | | Online | กล้องบริเวณหน้า Reception ใกล้ทางเข้าห้องน้ำ |
| 16 | 1 | Lobby-02 | | Online | กล้องบริเวณหน้าลิฟท์ Clinic ชั้น 1 ใกล้ Reception |
| 17 | 1 | Luggage Room | | Online | กล้องบริเวณภายในห้องเก็บของสัมภาระของลูกค้า |
| 18 | 1 | Safe Room | | Online | กล้องบริเวณภายในห้องเก็บตู้เซฟและเอกสารสำคัญ |
| 19 | 1 | Lobby-01 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ทางเข้าโรงแรม |
| 20 | 1 | Reception-02 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ห้องประชุม |
| 21 | 1 | Lobby-03 | | Online | กล้องบริเวณ โถงรับแขก ใกล้บันไดทางขึ้นไปห้อง โยคะ |
| 22 | 1 | Outdoor-Lobby-15 | | Online | กล้องบริเวณจุดรับสัมภาระ ใกล้ร้านอาหาร Fresca |
| 23 | 1 | Coridor-D-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใช้ทางเดินไปตึก E |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 1 | Coridor-D-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ลิฟท์ |
| 25 | 1 | Coridor-D-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ห้อง D106 |
| 26 | 1 | Coridor-D-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D203 |
| 27 | 1 | Coridor-D-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D208 |
| 28 | 1 | Coridor-D-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ห้อง D303 |
| 29 | 1 | Coridor-D-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ ห้อง D306 |
| 30 | 1 | Shop DELI | | Online | กล้องบริเวณภายใน Shop deli Fresca |
| 31 | 1 | Hot kitchen | | Online | กล้องบริเวณภายในห้องครัวร้อน Fresca |
| 32 | 1 | Stewarding | | Online | กล้องบริเวณภายในห้องล้างจาน Fresca |

## Report CCTV of NVR2

Mar-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 2 | Coridor-C-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลานจอดรถ |
| 2 | 2 | Coridor-C-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลิฟท์ |
| 3 | 2 | Coridor-C-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 |
| 4 | 2 | Coridor-C-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C203 |
| 5 | 2 | Coridor-C-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C208 - C209 |
| 6 | 2 | Coridor-C-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C302 - C303 |
| 7 | 2 | Coridor-C-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C306 |
| 8 | 2 | Outdoor-C-45 | | Online | กล้องบริเวณทางเดิน ตึก C ไป ตึก B ใกล้ลานจอดรถ |
| 9 | 2 | Outdoor-C-48 | | Online | กล้องบริเวณทางเดิน สระน้ำ ใกล้ตึก C |
| 10 | 2 | Coridor-G-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G101 |
| 11 | 2 | Coridor-G-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G105 |
| 12 | 2 | Coridor-G-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก G ชั้น 2 |
| 13 | 2 | Coridor-G-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G201 |
| 14 | 2 | Coridor-G-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G205 - G206 |
| 15 | 2 | Coridor-H-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H101 |
| 16 | 2 | Coridor-H-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H105 |
| 17 | 2 | Coridor-H-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก H ชั้น 2 |
| 18 | 2 | Coridor-H-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H201 |
| 19 | 2 | Coridor-H-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H205 - H206 |
| 20 | 2 | Outdoor-H-26 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก H |
| 21 | 2 | Outdoor-H-29 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก H ใกล้สระน้ำ |

| | | | | | |
|---|---|---|---|---|---|
| 22 | 2 | Coridor-E-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ลานจอดรถ |
| 23 | 2 | Coridor-E-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ลิฟท์ |
| 24 | 2 | Coridor-E-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 1 ใกล้ ห้อง E106 |
| 25 | 2 | Coridor-E-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 ใกล้ห้อง E203 |
| 26 | 2 | Coridor-E-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 |
| 27 | 2 | Coridor-E-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E303 |
| 28 | 2 | Coridor-E-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E306 |
| 29 | 2 | Outdoor-E-54 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก E ใกล้สระน้ำ |
| 30 | 2 | Outdoor-D-55 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้สระน้ำ |
| 31 | 2 | Outdoor-D-56 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้บันไดขึ้นสระน้ำ |
| 32 | 2 | Outdoor-D-57 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้ห้องน้ำ |

## Report CCTV of NVR3

Mar-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 3 | Coridor-F-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 |
| 2 | 3 | Coridor-F-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลานจอดรถ |
| 3 | 3 | Coridor-F-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลิฟท์ |
| 4 | 3 | Coridor-F-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F202 - F203 |
| 5 | 3 | Coridor-F-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F206 |
| 6 | 3 | Coridor-F-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F301 |
| 7 | 3 | Coridor-F-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F304 |
| 8 | 3 | Outdoor-F-49 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สระน้ำ |
| 9 | 3 | Outdoor-F-50 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สนามเด็กเล่น |
| 10 | 3 | Coridor-A-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A101 |
| 11 | 3 | Coridor-A-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A105 |

| | | | | | |
|---|---|---|---|---|---|
| 12 | 3 | Coridor-A-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก A ชั้น 2 |
| 13 | 3 | Coridor-A-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A201 |
| 14 | 3 | Coridor-A-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A205 - A206 |
| 15 | 3 | Outdoor-A-36 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ staygreen |
| 16 | 3 | Outdoor-A-37 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ทางเชื่อมไป ตึก B |
| 17 | 3 | Outdoor-A-39 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ประตูไม้ |
| 18 | 3 | B12-F1-01 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 1 |
| 19 | 3 | B12-F1-02 | | Online | กล้องบริเวณ Reception stayfit ชั้น 1 |
| 20 | 3 | B12-F1-03 | | Online | กล้องบริเวณทางเข้า Stayfit |
| 21 | 3 | B12-F2-04 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 2 |
| 22 | 3 | B12-F3-05 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 3 |
| 23 | 3 | Lift-C | | Online | กล้องบริเวณภายในลิฟท์ ตึก C |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 3 | Lift-D | | Online | กล้องบริเวณภายในลิฟท์ ตึก D |
| 25 | 3 | Lift-E | | Online | กล้องบริเวณภายในลิฟท์ ตึก E |
| 26 | 3 | Lift-F | | Online | กล้องบริเวณภายในลิฟท์ ตึก F |
| 27 | 3 | Poolbar-01 | | Online | กล้องบริเวณเคาน์เตอร์ Staygreen |
| 28 | 3 | Poolbar-02 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-03 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-Kitchen | | Online | กล้องบริเวณภายในห้องครัว ร้านอาหาร Staygreen |

Mar-24

## Report CCTV of NVR4

STAY

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 4 | B15-Meeting | | Online | กล้องบริเวณทางเดิน ตึก Fresca ชั้น 2 ใกล้ห้อง meeting |
| 2 | 4 | Thai-Restaurant-01 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 |
| 3 | 4 | Thai-Restaurant-02 | | Online | กล้องบริเวณภายในร้าน kamin restaurant ชั้น 3 ด้านหลัง |
| 4 | 4 | Thai-Restaurant-03 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 ทางเข้า |
| 5 | 4 | BM-Canteen | | Online | กล้องภายในโรงอาหาร พนักงาน ชั้นใต้ดิน |
| 6 | 4 | BM-Receiving | | Online | กล้องบริเวณพื้นที่รับ-ส่งของ ชั้นใต้ดิน |
| 7 | 4 | BM-Purchase | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้องจัดซื้อ |
| 8 | 4 | BM-Kitchen | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้อง butcher |
| 9 | 4 | Spa-01 | | Online | กล้องบริเวณ Reception Spa |
| 10 | 4 | Spa-02 | | Online | กล้องบริเวณ Reception Spa โซนนั่งเล่น |
| 11 | 4 | Spa-03 | | Online | กล้องบริเวณทางเดินไปชั้น 2 ใกล้ห้องล็อคเกอร์ |
| 12 | 4 | Spa-04 | | Online | กล้องบริเวณทางเดินไป Onsen ตึก Spa ใกล้ห้องพนักงาน |
| 13 | 4 | Spa-FL2-1 | | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 ใกล้บันไดทางขึ้น |
| 14 | 4 | Spa-FL2-2 | | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 |
| 15 | 4 | Yoga | | Online | กล้องบริเวณหน้าห้อง Yoga ชั้น 2 |
| 16 | 4 | Server Room | | Online | กล้องบริเวณหน้าห้อง Server ชั้น 2 ใกล้ Clinic |
| 17 | 4 | Clinic | | Online | กล้องบริเวณ Reception Clinic |
| 18 | 4 | Outdoor-Spa-1 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้จุด สูบบุหรี่ |
| 19 | 4 | Outdoor-Spa-2 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้ลานจอดจักรยาน |
| 20 | 4 | Outdoor-Spa-3 | | Online | กล้องบริเวณทางเดิน ภายนอก ตึก Spa ใกล้ประตูไม้ |
| 21 | 4 | Outdoor-Spa-4 | | Online | กล้องบริเวณทางเดินภายนอก ตึก Spa ด้านหลัง ใกล้ ตึก A |
| 22 | 4 | Stroc Wine | | Online | กล้องบริเวณภายในห้องเก็บไวน์ |
| 23 | 4 | Acc-Room | | Online | บริเวณภายในห้อง บัญชี |

## Report CCTV of NVR5

STAY

Mar-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 5 | MainEntrance-IN | | Online | กล้องบริเวณทางเข้าที่จอดรถโรงแรม ใกล้ป้อมยาม |
| 2 | 5 | MainEntrance-OUT | | Online | กล้องบริเวณลานจอดรถยนต์ |
| 3 | 5 | Car Park 1 (Gen) | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ป้อมยาม |
| 4 | 5 | Car Park 2 | | Online | กล้องบริเวณที่จอดรถหน้าโรงแรม |
| 5 | 5 | Car Park 3 | | Online | กล้องบริเวณลานจอดรถ |
| 6 | 5 | Car Park 4 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 92 |
| 7 | 5 | Car Park 5 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 91 |
| 8 | 5 | Spirit House | | Online | กล้องบริเวณทางเข้าประตู Villa ใกล้ ศาลพระภูมิ |
| 9 | 5 | Outdoor-Villa-1 | | Online | กล้องบริเวณถนน Villa ใกล้ด้านหลัง Stayfit |
| 10 | 5 | Outdoor-Villa-2 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 1 |

| | | | | | |
|---|---|---|---|---|---|
| 11 | 5 | Outdoor-Villa-3 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 8 |
| 12 | 5 | Outdoor-Villa-4 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 9 |
| 13 | 5 | ExitDoor-Villa | | Online | กล้องบริเวณประตูทางออกไป 4 ไร่ |
| 14 | 5 | Outdoor-H | | Online | กล้องบริเวณถนน ใกล้ตึก H |
| 15 | 5 | Outdoor-G | | Online | กล้องบริเวณถนน ใกล้ตึก G |
| 16 | 5 | Outdoor-F | | Online | กล้องบริเวณถนน ใกล้ตึก F |
| 17 | 5 | Outdoor-E-1 | | Online | กล้องบริเวณถนน ใกล้ตึก E |
| 18 | 5 | Outdoor-E-2 | | Online | กล้องบริเวณถนน ใกล้ตึก E ใกล้ลานจอดรถ |
| 19 | 5 | Outdoor-E-3 | | Online | กล้องบริเวณถนน ตึก E ใกล้ลานจอดรถ |
| 20 | 5 | Outdoor-D-1 | | Online | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 21 | 5 | Outdoor-D-2 | | Offline | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 22 | 5 | Outdoor-C-1 | | Online | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |
| 23 | 5 | Outdoor-C-2 | | Offline | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |

## Report CCTV of NVR6 at 4Rai

STAY

Mar-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 6 | Right entrance | | Online | กล้องบริเวณประตูทางเข้าหอพัก 4ไร่ ชั้น 1 |
| 2 | 6 | Second floor stairs | | Online | กล้องบริเวณบันไดหอพัก 4 ไร่ ชั้น 2 |
| 3 | 6 | Boxing stadium door | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 4 | 6 | Boxing stadium left | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 5 | 6 | Boxing stadium | | Online | กล้องบริเวณเวที 8 มวยไทย ชั้น 3 |
| 6 | 6 | HK Store-1 | | Online | กล้องบริเวณภายในห้องแม่บ้าน |
| 7 | 6 | HK Store-2 | | Online | กล้องบริเวณภายในห้องเก็บของแม่บ้าน |
| 8 | 6 | Parking | | Online | กล้องบริเวณลานจอดรถมอเตอร์ไซค์ |
| 9 | 6 | Staff room | | Online | กล้องบริเวณทางเดินหอพักพนักงาน |
| 10 | 6 | Workshop | | Online | กล้องบริเวณห้องเก็บของช่าง ด้านใน |
| 11 | 6 | Workshop2 | | Online | กล้องบริเวณห้องเก็บของช่าง |
| 12 | 6 | Office stairs | | Online | กล้องบริเวณบันไดชั้น 2 ใกล้ประตูทางเข้า Office HR |
| 13 | 6 | OFFICE | | Online | กล้องบริเวณ Office HR |
| 14 | 6 | StayWild | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ประตูทางเข้าหอพักพนักงาน |
| 15 | 6 | Front area | | Online | กล้องบริเวณลานจอดรถ 4 ไร่ (มุมสูง) ชั้น 3 |
| 15 | 6 | Staff room | | Online | กล้องบริเวณทางเดินไปห้อง Staff Locker |

Apr-24

## Report CCTV of NVR1

STAY

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 1 | Courtyard-01 | | Online | กล้องบริเวณประตูทางเข้า Fresca |
| 2 | 1 | Courtyard-02 | | Online | กล้องบริเวณทางขึ้นบันได Fresca |
| 3 | 1 | Fresca-01 | | Online | กล้องบริเวณภายใน Fresca ใกล้แคชเชียร์ |
| 4 | 1 | Fresca-02 | | Online | กล้องบริเวณภายใน Fresca ใกล้บาร์ กับ เครื่องทำกาแฟ |
| 5 | 1 | Fresca-03 | | Online | กล้องบริเวณแคชเชียร์ Fresca |
| 6 | 1 | Fresca-04 | | Online | กล้องบริเวณหน้าลิฟ ชั้น 1 ภายใน Fresca |
| 7 | 1 | Fresca-05 | | Online | กล้องบริเวณที่จอดรถใกล้ Fresca |
| 8 | 1 | Coridor-B-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหน้า |
| 9 | 1 | Coridor-B-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหลัง |
| 10 | 1 | Coridor-B-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก B ชั้น 2 |
| 11 | 1 | Coridor-B-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหน้า |
| 12 | 1 | Coridor-B-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหลัง |
| 13 | 1 | Outdoor-B14-02 | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ |
| 14 | 1 | Outdoor-B14-01 | | Online | กล้องบริเวณบันไดทางเข้าโรงแรม |
| 15 | 1 | Reception-01 | | Online | กล้องบริเวณหน้า Reception ใกล้ทางเข้าห้องน้ำ |
| 16 | 1 | Lobby-02 | | Online | กล้องบริเวณหน้าลิฟท์ Clinic ชั้น 1 ใกล้ Reception |
| 17 | 1 | Luggage Room | | Online | กล้องบริเวณภายในห้องเก็บของสัมภาระของลูกค้า |
| 18 | 1 | Safe Room | | Online | กล้องบริเวณภายในห้องเก็บตู้เซฟและเอกสารสำคัญ |
| 19 | 1 | Lobby-01 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ทางเข้าโรงแรม |
| 20 | 1 | Reception-02 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ห้องประชุม |
| 21 | 1 | Lobby-03 | | Online | กล้องบริเวณ โถงรับแขก ใกล้บันไดทางขึ้นไปห้อง โยคะ |
| 22 | 1 | Outdoor-Lobby-15 | | Online | กล้องบริเวณจุดรับสัมภาระ ใกล้ร้านอาหาร Fresca |
| 23 | 1 | Coridor-D-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ให้ทางเดินไปตึก E |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 1 | Coridor-D-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ลิฟท์ |
| 25 | 1 | Coridor-D-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ห้อง D106 |
| 26 | 1 | Coridor-D-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D203 |
| 27 | 1 | Coridor-D-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D208 |
| 28 | 1 | Coridor-D-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ห้อง D303 |
| 29 | 1 | Coridor-D-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ ห้อง D306 |
| 30 | 1 | Shop DELI | | Online | กล้องบริเวณภายใน Shop deli Fresca |
| 31 | 1 | Hot kitchen | | Online | กล้องบริเวณภายในห้องครัวร้อน Fresca |
| 32 | 1 | Stewarding | | Online | กล้องบริเวณภายในห้องล้างจาน Fresca |

## Report CCTV of NVR2

Apr-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 2 | Coridor-C-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลานจอดรถ |
| 2 | 2 | Coridor-C-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลิฟท์ |
| 3 | 2 | Coridor-C-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 |
| 4 | 2 | Coridor-C-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C203 |
| 5 | 2 | Coridor-C-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C208 - C209 |
| 6 | 2 | Coridor-C-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C302 - C303 |
| 7 | 2 | Coridor-C-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C306 |
| 8 | 2 | Outdoor-C-45 | | Online | กล้องบริเวณทางเดิน ตึก C ไป ตึก B ใกล้ลานจอดรถ |
| 9 | 2 | Outdoor-C-48 | | Online | กล้องบริเวณทางเดิน สระน้ำ ใกล้ตึก C |
| 10 | 2 | Coridor-G-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G101 |

| | | | | | |
|---|---|---|---|---|---|
| 11 | 2 | Coridor-G-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G105 |
| 12 | 2 | Coridor-G-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก G ชั้น 2 |
| 13 | 2 | Coridor-G-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G201 |
| 14 | 2 | Coridor-G-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G205 - G206 |
| 15 | 2 | Coridor-H-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H101 |
| 16 | 2 | Coridor-H-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H105 |
| 17 | 2 | Coridor-H-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก H ชั้น 2 |
| 18 | 2 | Coridor-H-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H201 |
| 19 | 2 | Coridor-H-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H205 - H206 |
| 20 | 2 | Outdoor-H-26 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก H |
| 21 | 2 | Outdoor-H-29 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก H ใกล้สระน้ำ |

| | | | | | |
|---|---|---|---|---|---|
| 22 | 2 | Coridor-E-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ ลานจอดรถ |
| 23 | 2 | Coridor-E-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ ลิฟท์ |
| 24 | 2 | Coridor-E-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 1 ใกล้ ห้อง E106 |
| 25 | 2 | Coridor-E-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 ใกล้ห้อง E203 |
| 26 | 2 | Coridor-E-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 |
| 27 | 2 | Coridor-E-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E303 |
| 28 | 2 | Coridor-E-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E306 |
| 29 | 2 | Outdoor-E-54 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก E ใกล้สระน้ำ |
| 30 | 2 | Outdoor-D-55 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้สระน้ำ |
| 31 | 2 | Outdoor-D-56 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้บันไดขึ้นสระน้ำ |
| 32 | 2 | Outdoor-D-57 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้ห้องน้ำ |

## Report CCTV of NVR3

Apr-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 3 | Coridor-F-F1-01 |  | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 |
| 2 | 3 | Coridor-F-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลานจอดรถ |
| 3 | 3 | Coridor-F-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลิฟท์ |
| 4 | 3 | Coridor-F-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F202 - F203 |
| 5 | 3 | Coridor-F-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F206 |
| 6 | 3 | Coridor-F-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F301 |
| 7 | 3 | Coridor-F-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F304 |
| 8 | 3 | Outdoor-F-49 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สระน้ำ |
| 9 | 3 | Outdoor-F-50 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สนามเด็กเล่น |
| 10 | 3 | Coridor-A-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A101 |
| 11 | 3 | Coridor-A-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A105 |
| 12 | 3 | Coridor-A-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก A ชั้น 2 |
| 13 | 3 | Coridor-A-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A201 |
| 14 | 3 | Coridor-A-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A205 - A206 |
| 15 | 3 | Outdoor-A-36 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ staygreen |
| 16 | 3 | Outdoor-A-37 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ทางเชื่อมไป ตึก B |
| 17 | 3 | Outdoor-A-39 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ประตูไม้ |
| 18 | 3 | B12-F1-01 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 1 |
| 19 | 3 | B12-F1-02 | | Online | กล้องบริเวณ Reception stayfit ชั้น 1 |
| 20 | 3 | B12-F1-03 | | Online | กล้องบริเวณทางเข้า Stayfit |
| 21 | 3 | B12-F2-04 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 2 |
| 22 | 3 | B12-F3-05 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 3 |
| 23 | 3 | Lift-C | | Online | กล้องบริเวณภายในลิฟท์ ตึก C |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 3 | Lift-D | | Online | กล้องบริเวณภายในลิฟท์ ตึก D |
| 25 | 3 | Lift-E | | Online | กล้องบริเวณภายในลิฟท์ ตึก E |
| 26 | 3 | Lift-F | | Online | กล้องบริเวณภายในลิฟท์ ตึก F |
| 27 | 3 | Poolbar-01 | | Online | กล้องบริเวณเคาน์เตอร์ Staygreen |
| 28 | 3 | Poolbar-02 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-03 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-Kitchen | | Online | กล้องบริเวณภายในห้องครัว ร้านอาหาร Staygreen |

## Report CCTV of NVR4

Apr-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 4 | B15-Meeting | | Online | กล้องบริเวณทางเดิน ตึก Fresca ชั้น 2 ใกล้ห้อง meeting |
| 2 | 4 | Thai-Restaurant-01 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 |
| 3 | 4 | Thai-Restaurant-02 | | Online | กล้องบริเวณภายในร้าน kamin restaurant ชั้น 3 ด้านหลัง |
| 4 | 4 | Thai-Restaurant-03 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 ทางเข้า |
| 5 | 4 | BM-Canteen | | Online | กล้องภายในโรงอาหาร พนักงาน ชั้นใต้ดิน |
| 6 | 4 | BM-Receiving | | Online | กล้องบริเวณพื้นที่รับ-ส่งของ ชั้นใต้ดิน |
| 7 | 4 | BM-Purchase | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้องจัดซื้อ |
| 8 | 4 | BM-Kitchen | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้อง butcher |
| 9 | 4 | Spa-01 | | Online | กล้องบริเวณ Reception Spa |
| 10 | 4 | Spa-02 | | Online | กล้องบริเวณ Reception Spa โซนนั่งเล่น |
| 11 | 4 | Spa-03 | | Online | กล้องบริเวณทางเดินไปชั้น 2 ใกล้ห้องล็อคเกอร์ |

| | | | | | |
|---|---|---|---|---|---|
| 12 | 4 | Spa-04 | | Online | กล้องบริเวณทางเดินไป Onsen ตึก Spa ใกล้ห้องพนักงาน |
| 13 | 4 | Spa-FL2-1 | | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 ใกล้บันไดทางขึ้น |
| 14 | 4 | Spa-FL2-2 | | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 |
| 15 | 4 | Yoga | | Online | กล้องบริเวณหน้าห้อง Yoga ชั้น 2 |
| 16 | 4 | Server Room | | Online | กล้องบริเวณหน้าห้อง Server ชั้น 2 ใกล้ Clinic |
| 17 | 4 | Clinic | | Online | กล้องบริเวณ Reception Clinic |
| 18 | 4 | Outdoor-Spa-1 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้จุด สูบบุหรี่ |
| 19 | 4 | Outdoor-Spa-2 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้ลานจอดจักรยาน |
| 20 | 4 | Outdoor-Spa-3 | | Online | กล้องบริเวณทางเดิน ภายนอก ตึก Spa ใกล้ประตูไม้ |
| 21 | 4 | Outdoor-Spa-4 |  | Online | กล้องบริเวณทางเดินภายนอก ตึก Spa ด้านหลัง ใกล้ ตึก A |
| 22 | 4 | Stroe Wine | | Online | กล้องบริเวณภายในห้องเก็บไวน์ |
| 23 | 4 | Acc-Room | | Online | บริเวณภายในห้อง บัญชี |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 4 | Onsen-Male | | Online | บริเวณภายในห้อง ONSEN ชาย |
| 25 | 4 | Onsen-Female | | Online | บริเวณภายในห้อง ONSEN หญิง |

## Report CCTV of NVR5

Apr-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 5 | MainEntrance-IN | | Online | กล้องบริเวณทางเข้าที่จอดรถโรงแรม ใกล้ป้อมยาม |
| 2 | 5 | MainEntrance-OUT | | Online | กล้องบริเวณลานจอดรถยนต์ |
| 3 | 5 | Car Park 1 (Gen) | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ป้อมยาม |
| 4 | 5 | Car Park 2 | | Online | กล้องบริเวณที่จอดรถหน้าโรงแรม |
| 5 | 5 | Car Park 3 | | Online | กล้องบริเวณลานจอดรถ |
| 6 | 5 | Car Park 4 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 92 |
| 7 | 5 | Car Park 5 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 91 |
| 8 | 5 | Spirit House | | Online | กล้องบริเวณทางเข้าประตู Villa ใกล้ ศาลพระภูมิ |
| 9 | 5 | Outdoor-Villa-1 | | Online | กล้องบริเวณถนน Villa ใกล้ ด้านหลัง Stayfit |
| 10 | 5 | Outdoor-Villa-2 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 1 |
| 11 | 5 | Outdoor-Villa-3 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 8 |
| 12 | 5 | Outdoor-Villa-4 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 9 |
| 13 | 5 | ExitDoor-Villa | | Online | กล้องบริเวณประตูทางออกไป 4 ไร่ |
| 14 | 5 | Outdoor-H | | Online | กล้องบริเวณถนน ใกล้ตึก H |
| 15 | 5 | Outdoor-G | | Online | กล้องบริเวณถนน ใกล้ตึก G |
| 16 | 5 | Outdoor-F | | Online | กล้องบริเวณถนน ใกล้ตึก F |
| 17 | 5 | Outdoor-E-1 | | Online | กล้องบริเวณถนน ใกล้ตึก E |
| 18 | 5 | Outdoor-E-2 | | Online | กล้องบริเวณถนน ใกล้ตึก E ใกล้ลานจอดรถ |
| 19 | 5 | Outdoor-E-3 | | Online | กล้องบริเวณถนน ตึก E ใกล้ลานจอดรถ |
| 20 | 5 | Outdoor-D-1 | | Online | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 21 | 5 | Outdoor-D-2 | | Offline | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 22 | 5 | Outdoor-C-1 | | Online | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |

| | | | | | |
|---|---|---|---|---|---|
| 23 | 5 | Outdoor-C-2 | | Offline | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |

## Report CCTV of NVR6 at 4Rai

Apr-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 6 | Right entrance | | Online | กล้องบริเวณประตูทางเข้าหอพัก 4ไร่ ชั้น 1 |
| 2 | 6 | Second floor stairs | | Online | กล้องบริเวณบันไดหอพัก 4 ไร่ ชั้น 2 |
| 3 | 6 | Boxing stadium door | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 4 | 6 | Boxing stadium left | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 5 | 6 | Boxing stadium | | Online | กล้องบริเวณเวที 8 มวยไทย ชั้น 3 |
| 6 | 6 | HK Store-1 | | Online | กล้องบริเวณภายในห้องแม่บ้าน |
| 7 | 6 | HK Store-2 | | Online | กล้องบริเวณภายในห้องเก็บของแม่บ้าน |
| 8 | 6 | Parking | | Online | กล้องบริเวณลานจอดรถมอเตอร์ไซค์ |
| 9 | 6 | Staff room | | Online | กล้องบริเวณทางเดินหอพักพนักงาน |
| 10 | 6 | Workshop | | Online | กล้องบริเวณห้องเก็บของช่าง ด้านใน |

| | | | | | |
|---|---|---|---|---|---|
| 11 | 6 | Workshop2 | | Online | กล้องบริเวณห้องเก็บของช่าง |
| 12 | 6 | Office stairs | | Online | กล้องบริเวณบันไดชั้น 2 ใกล้ประตูทางเข้า Office HR |
| 13 | 6 | OFFICE | | Online | กล้องบริเวณ Office HR |
| 14 | 6 | StayWild | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ประตูทางเข้าหอพักพนักงาน |
| 15 | 6 | Front area | | Online | กล้องบริเวณลานจอดรถ 4 ไร่ (มุมสูง) ชั้น 3 |
| 15 | 6 | Staff room | | Online | กล้องบริเวณทางเดินไปห้อง Staff Locker |

## Report CCTV of NVR1

May-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 1 | Courtyard-01 | | Online | กล้องบริเวณประตูทางเข้า Fresca |
| 2 | 1 | Courtyard-02 | | Online | กล้องบริเวณทางขึ้นบันได Fresca |
| 3 | 1 | Fresca-01 | | Online | กล้องบริเวณภายใน Fresca ใกล้แคชเชียร์ |
| 4 | 1 | Fresca-02 | | Online | กล้องบริเวณภายใน Fresca ใกล้บาร์ กับ เครื่องทำกาแฟ |
| 5 | 1 | Fresca-03 | | Online | กล้องบริเวณแคชเชียร์ Fresca |
| 6 | 1 | Fresca-04 | | Online | กล้องบริเวณหน้าลิฟ ชั้น 1 ภายใน Fresca |
| 7 | 1 | Fresca-05 | | Online | กล้องบริเวณที่จอดรถใกล้ Fresca |
| 8 | 1 | Coridor-B-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหน้า |
| 9 | 1 | Coridor-B-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหลัง |
| 10 | 1 | Coridor-B-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก B ชั้น 2 |
| 11 | 1 | Coridor-B-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหน้า |

| | | | | | |
|---|---|---|---|---|---|
| 12 | 1 | Coridor-B-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหลัง |
| 13 | 1 | Outdoor-B14-02 |  | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ |
| 14 | 1 | Outdoor-B14-01 | | Online | กล้องบริเวณบันไดทางเข้าโรงแรม |
| 15 | 1 | Reception-01 | | Online | กล้องบริเวณหน้า Reception ใกล้ทางเข้าห้องน้ำ |
| 16 | 1 | Lobby-02 | | Online | กล้องบริเวณหน้าลิฟท์ Clinic ชั้น 1 ใกล้ Reception |
| 17 | 1 | Luggage Room | | Online | กล้องบริเวณภายในห้องเก็บของสัมภาระของลูกค้า |
| 18 | 1 | Safe Room | | Online | กล้องบริเวณภายในห้องเก็บตู้เซฟและเอกสารสำคัญ |
| 19 | 1 | Lobby-01 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ทางเข้าโรงแรม |
| 20 | 1 | Reception-02 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ห้องประชุม |
| 21 | 1 | Lobby-03 | | Online | กล้องบริเวณ โถงรับแขก ใกล้บันไดทางขึ้นไปห้อง โยคะ |
| 22 | 1 | Outdoor-Lobby-15 | | Online | กล้องบริเวณจุดรับสัมภาระ ใกล้ร้านอาหาร Fresca |
| 23 | 1 | Coridor-D-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ให้ทางเดินไปตึก E |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 1 | Coridor-D-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ลิฟท์ |
| 25 | 1 | Coridor-D-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ห้อง D106 |
| 26 | 1 | Coridor-D-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D203 |
| 27 | 1 | Coridor-D-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D208 |
| 28 | 1 | Coridor-D-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ห้อง D303 |
| 29 | 1 | Coridor-D-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ ห้อง D306 |
| 30 | 1 | Shop DELI | | Online | กล้องบริเวณภายใน Shop deli Fresca |
| 31 | 1 | Hot kitchen | | Online | กล้องบริเวณภายในห้องครัวร้อน Fresca |
| 32 | 1 | Stewarding | | Online | กล้องบริเวณภายในห้องล้างจาน Fresca |

May-24

## Report CCTV of NVR2

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 2 | Coridor-C-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลานจอดรถ |
| 2 | 2 | Coridor-C-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลิฟท์ |
| 3 | 2 | Coridor-C-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 |
| 4 | 2 | Coridor-C-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C203 |
| 5 | 2 | Coridor-C-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C208 - C209 |
| 6 | 2 | Coridor-C-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C302 - C303 |
| 7 | 2 | Coridor-C-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C306 |
| 8 | 2 | Outdoor-C-45 | | Online | กล้องบริเวณทางเดิน ตึก C ไป ตึก B ใกล้ลานจอดรถ |
| 9 | 2 | Outdoor-C-48 | | Online | กล้องบริเวณทางเดิน สระน้ำ ใกล้ตึก C |
| 10 | 2 | Coridor-G-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G101 |
| 11 | 2 | Coridor-G-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G105 |
| 12 | 2 | Coridor-G-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก G ชั้น 2 |
| 13 | 2 | Coridor-G-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G201 |
| 14 | 2 | Coridor-G-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G205 - G206 |
| 15 | 2 | Coridor-H-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H101 |
| 16 | 2 | Coridor-H-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H105 |
| 17 | 2 | Coridor-H-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก H ชั้น 2 |
| 18 | 2 | Coridor-H-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H201 |
| 19 | 2 | Coridor-H-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H205 - H206 |
| 20 | 2 | Outdoor-H-26 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก H |
| 21 | 2 | Outdoor-H-29 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก H ใกล้สระน้ำ |

| | | | | | |
|---|---|---|---|---|---|
| 22 | 2 | Coridor-E-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ลานจอดรถ |
| 23 | 2 | Coridor-E-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ลิฟท์ |
| 24 | 2 | Coridor-E-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 1 ใกล้ ห้อง E106 |
| 25 | 2 | Coridor-E-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 ใกล้ห้อง E203 |
| 26 | 2 | Coridor-E-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 |
| 27 | 2 | Coridor-E-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E303 |
| 28 | 2 | Coridor-E-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E306 |
| 29 | 2 | Outdoor-E-54 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก E ใกล้สระน้ำ |
| 30 | 2 | Outdoor-D-55 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้สระน้ำ |
| 31 | 2 | Outdoor-D-56 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้บันไดขึ้นสระน้ำ |
| 32 | 2 | Outdoor-D-57 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้ห้องน้ำ |

## Report CCTV of NVR3

May-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 3 | Coridor-F-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 |
| 2 | 3 | Coridor-F-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลานจอดรถ |
| 3 | 3 | Coridor-F-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลิฟท์ |
| 4 | 3 | Coridor-F-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F202 - F203 |
| 5 | 3 | Coridor-F-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F206 |
| 6 | 3 | Coridor-F-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F301 |
| 7 | 3 | Coridor-F-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F304 |
| 8 | 3 | Outdoor-F-49 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สระน้ำ |
| 9 | 3 | Outdoor-F-50 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สนามเด็กเล่น |
| 10 | 3 | Coridor-A-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A101 |
| 11 | 3 | Coridor-A-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A105 |

| | | | | | |
|---|---|---|---|---|---|
| 12 | 3 | Coridor-A-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก A ชั้น 2 |
| 13 | 3 | Coridor-A-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A201 |
| 14 | 3 | Coridor-A-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A205 - A206 |
| 15 | 3 | Outdoor-A-36 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ staygreen |
| 16 | 3 | Outdoor-A-37 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ทางเชื่อมไป ตึก B |
| 17 | 3 | Outdoor-A-39 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ประตูไม้ |
| 18 | 3 | B12-F1-01 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 1 |
| 19 | 3 | B12-F1-02 | | Online | กล้องบริเวณ Reception stayfit ชั้น 1 |
| 20 | 3 | B12-F1-03 | | Online | กล้องบริเวณทางเข้า Stayfit |
| 21 | 3 | B12-F2-04 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 2 |
| 22 | 3 | B12-F3-05 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 3 |
| 23 | 3 | Lift-C | | Online | กล้องบริเวณภายในลิฟท์ ตึก C |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 3 | Lift-D | | Online | กล้องบริเวณภายในลิฟท์ ตึก D |
| 25 | 3 | Lift-E | | Online | กล้องบริเวณภายในลิฟท์ ตึก E |
| 26 | 3 | Lift-F | | Online | กล้องบริเวณภายในลิฟท์ ตึก F |
| 27 | 3 | Poolbar-01 | | Online | กล้องบริเวณเคาน์เตอร์ Staygreen |
| 28 | 3 | Poolbar-02 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-03 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-Kitchen | | Online | กล้องบริเวณภายในห้องครัว ร้านอาหาร Staygreen |

## Report CCTV of NVR4

May-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 4 | B15-Meeting | | Online | กล้องบริเวณทางเดิน ตึก Fresca ชั้น 2 ใกล้ห้อง meeting |
| 2 | 4 | Thai-Restaurant-01 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 |
| 3 | 4 | Thai-Restaurant-02 | | Online | กล้องบริเวณภายในร้าน kamin restaurant ชั้น 3 ด้านหลัง |
| 4 | 4 | Thai-Restaurant-03 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 ทางเข้า |
| 5 | 4 | BM-Canteen | | Online | กล้องภายในโรงอาหาร พนักงาน ชั้นใต้ดิน |
| 6 | 4 | BM-Receiving | | Online | กล้องบริเวณพื้นที่รับ-ส่งของ ชั้นใต้ดิน |
| 7 | 4 | BM-Purchase | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้องจัดซื้อ |
| 8 | 4 | BM-Kitchen | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้อง butcher |
| 9 | 4 | Spa-01 | | Online | กล้องบริเวณ Reception Spa |
| 10 | 4 | Spa-02 | | Online | กล้องบริเวณ Reception Spa โซนนั่งเล่น |
| 11 | 4 | Spa-03 | | Online | กล้องบริเวณทางเดินไปชั้น 2 ใกล้ห้องล็อคเกอร์ |
| 12 | 4 | Spa-04 | | Online | กล้องบริเวณทางเดินไป Onsen ตึก Spa ใกล้ห้อง พนักงาน |
| 13 | 4 | Spa-FL2-1 | | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 ใกล้บันไดทางขึ้น |
| 14 | 4 | Spa-FL2-2 | | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 |
| 15 | 4 | Yoga | | Online | กล้องบริเวณหน้าห้อง Yoga ชั้น 2 |
| 16 | 4 | Server Room | | Online | กล้องบริเวณหน้าห้อง Server ชั้น 2 ใกล้ Clinic |
| 17 | 4 | Clinic | | Online | กล้องบริเวณ Reception Clinic |
| 18 | 4 | Outdoor-Spa-1 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้จุด สูบบุหรี่ |
| 19 | 4 | Outdoor-Spa-2 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้ลานจอดจักรยาน |
| 20 | 4 | Outdoor-Spa-3 | | Online | กล้องบริเวณทางเดิน ภายนอก ตึก Spa ใกล้ประตูไม้ |
| 21 | 4 | Outdoor-Spa-4 | | Online | กล้องบริเวณทางเดินภายนอก ตึก Spa ด้านหลัง ใกล้ ตึก A |
| 22 | 4 | Stroe Wine | | Online | กล้องบริเวณภายในห้องเก็บ ไวน์ |
| 23 | 4 | Acc-Room | | Online | บริเวณภายในห้อง บัญชี |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 4 | Onsen-Male | | Online | บริเวณภายในห้อง ONSEN ชาย |
| 25 | 4 | Onsen-Female | | Online | บริเวณภายในห้อง ONSEN หญิง |
| 26 | 4 | CHICA-Bar | | Online | บริเวณภายในบาร์กับห้องครัว CHICA |

## Report CCTV of NVR5

May-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 5 | MainEntrance-IN | | Online | กล้องบริเวณทางเข้าที่จอดรถโรงแรม ใกล้ป้อมยาม |
| 2 | 5 | MainEntrance-OUT | | Online | กล้องบริเวณลานจอดรถยนต์ |
| 3 | 5 | Car Park 1 (Gen) | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ป้อมยาม |
| 4 | 5 | Car Park 2 | | Online | กล้องบริเวณที่จอดรถหน้าโรงแรม |
| 5 | 5 | Car Park 3 | | Online | กล้องบริเวณลานจอดรถ |
| 6 | 5 | Car Park 4 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 92 |
| 7 | 5 | Car Park 5 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 91 |
| 8 | 5 | Spirit House | | Online | กล้องบริเวณทางเข้าประตู Villa ใกล้ ศาลพระภูมิ |
| 9 | 5 | Outdoor-Villa-1 | | Online | กล้องบริเวณถนน Villa ใกล้ด้านหลัง Stayfit |
| 10 | 5 | Outdoor-Villa-2 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 1 |

| | | | | | |
|---|---|---|---|---|---|
| 11 | 5 | Outdoor-Villa-3 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 8 |
| 12 | 5 | Outdoor-Villa-4 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 9 |
| 13 | 5 | ExitDoor-Villa | | Online | กล้องบริเวณประตูทางออกไป 4 ไร่ |
| 14 | 5 | Outdoor-H | | Online | กล้องบริเวณถนน ใกล้ตึก H |
| 15 | 5 | Outdoor-G | | Online | กล้องบริเวณถนน ใกล้ตึก G |
| 16 | 5 | Outdoor-F | | Online | กล้องบริเวณถนน ใกล้ตึก F |
| 17 | 5 | Outdoor-E-1 | | Online | กล้องบริเวณถนน ใกล้ตึก E |
| 18 | 5 | Outdoor-E-2 | | Online | กล้องบริเวณถนน ใกล้ตึก E ใกล้ลานจอดรถ |
| 19 | 5 | Outdoor-E-3 | | Online | กล้องบริเวณถนน ตึก E ใกล้ลานจอดรถ |
| 20 | 5 | Outdoor-D-1 | | Online | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 21 | 5 | Outdoor-D-2 | | Offline | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 22 | 5 | Outdoor-C-1 | | Online | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |
| 23 | 5 | Outdoor-C-2 | | Offline | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |

## Report CCTV of NVR6 at 4Rai

May-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 6 | Right entrance | | Online | กล้องบริเวณประตูทางเข้าหอพัก 4ไร่ ชั้น 1 |
| 2 | 6 | Second floor stairs | | Online | กล้องบริเวณบันไดหอพัก 4 ไร่ ชั้น 2 |
| 3 | 6 | Boxing stadium door | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 4 | 6 | Boxing stadium left | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 5 | 6 | Boxing stadium | | Online | กล้องบริเวณเวที 8 มวยไทย ชั้น 3 |
| 6 | 6 | HK Store-1 | | Online | กล้องบริเวณภายในห้องแม่บ้าน |
| 7 | 6 | HK Store-2 | | Online | กล้องบริเวณภายในห้องเก็บของแม่บ้าน |
| 8 | 6 | Parking | | Online | กล้องบริเวณลานจอดรถมอเตอร์ไซค์ |
| 9 | 6 | Staff room | | Online | กล้องบริเวณทางเดินหอพักพนักงาน |
| 10 | 6 | Workshop | | Online | กล้องบริเวณห้องเก็บของช่าง ด้านใน |
| 11 | 6 | Workshop2 | | Online | กล้องบริเวณห้องเก็บของช่าง |
| 12 | 6 | Office stairs | | Online | กล้องบริเวณบันไดชั้น 2 ใกล้ประตูทางเข้า Office HR |
| 13 | 6 | OFFICE | | Online | กล้องบริเวณ Office HR |
| 14 | 6 | StayWild | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ประตูทางเข้าหอพักพนักงาน |
| 15 | 6 | Front area | | Online | กล้องบริเวณลานจอดรถ 4 ไร่ (มุมสูง) ชั้น 3 |
| 15 | 6 | Staff room | | Online | กล้องบริเวณทางเดินไปห้อง Staff Locker |

## Report CCTV of NVR1

STAY

Jun-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 1 | Courtyard-01 | | Online | กล้องบริเวณประตูทางเข้า Fresca |
| 2 | 1 | Courtyard-02 | | Online | กล้องบริเวณทางขึ้นบันได้ Fresca |
| 3 | 1 | Fresca-01 | | Online | กล้องบริเวณภายใน Fresca ใกล้แคชเชียร์ |
| 4 | 1 | Fresca-02 | | Online | กล้องบริเวณภายใน Fresca ใกล้บาร์ กับ เครื่องทำกาแฟ |
| 5 | 1 | Fresca-03 | | Online | กล้องบริเวณแคชเชียร์ Fresca |
| 6 | 1 | Fresca-04 | | Online | กล้องบริเวณหน้าลิฟ ชั้น 1 ภายใน Fresca |
| 7 | 1 | Fresca-05 | | Online | กล้องบริเวณที่จอดรถใกล้ Fresca |
| 8 | 1 | Coridor-B-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหน้า |
| 9 | 1 | Coridor-B-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 1 ด้านหลัง |
| 10 | 1 | Coridor-B-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได้ ตึก B ชั้น 2 |
| 11 | 1 | Coridor-B-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหน้า |
| 12 | 1 | Coridor-B-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก B ชั้น 2 ด้านหลัง |
| 13 | 1 | Outdoor-B14-02 | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ |
| 14 | 1 | Outdoor-B14-01 | | Online | กล้องบริเวณบันไดทางเข้าโรงแรม |
| 15 | 1 | Reception-01 | | Online | กล้องบริเวณหน้า Reception ใกล้ทางเข้าห้องน้ำ |
| 16 | 1 | Lobby-02 | | Online | กล้องบริเวณหน้าลิฟท์ Clinic ชั้น 1 ใกล้ Reception |
| 17 | 1 | Luggage Room | | Online | กล้องบริเวณภายในห้องเก็บของสัมภาระของลูกค้า |
| 18 | 1 | Safe Room | | Online | กล้องบริเวณภายในห้องเก็บตู้เซฟและเอกสารสำคัญ |
| 19 | 1 | Lobby-01 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ทางเข้าโรงแรม |
| 20 | 1 | Reception-02 | | Online | กล้องบริเวณ โถงรับแขก ใกล้ห้องประชุม |
| 21 | 1 | Lobby-03 | | Online | กล้องบริเวณ โถงรับแขก ใกล้บันไดทางขึ้นไปห้อง โยคะ |
| 22 | 1 | Outdoor-Lobby-15 | | Online | กล้องบริเวณจุดรับสัมภาระ ใกล้ร้านอาหาร Fresca |
| 23 | 1 | Coridor-D-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ให้ทางเดินไปตึก E |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 1 | Coridor-D-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ลิฟท์ |
| 25 | 1 | Coridor-D-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 1 ใกล้ห้อง D106 |
| 26 | 1 | Coridor-D-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D203 |
| 27 | 1 | Coridor-D-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 2 ใกล้ห้อง D208 |
| 28 | 1 | Coridor-D-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ห้อง D303 |
| 29 | 1 | Coridor-D-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก D ชั้น 3 ใกล้ ห้อง D306 |
| 30 | 1 | Shop DELI | | Online | กล้องบริเวณภายใน Shop deli Fresca |
| 31 | 1 | Hot kitchen | | Online | กล้องบริเวณภายในห้องครัวร้อน Fresca |
| 32 | 1 | Stewarding | | Online | กล้องบริเวณภายในห้องล้างจาน Fresca |

## Report CCTV of NVR2

Jun-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 2 | Coridor-C-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลานจอดรถ |
| 2 | 2 | Coridor-C-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 ใกล้ลิฟท์ |
| 3 | 2 | Coridor-C-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 1 |
| 4 | 2 | Coridor-C-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C203 |
| 5 | 2 | Coridor-C-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 2 ใกล้ห้อง C208 - C209 |
| 6 | 2 | Coridor-C-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C302 - C303 |
| 7 | 2 | Coridor-C-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก C ชั้น 3 ใกล้ห้อง C306 |
| 8 | 2 | Outdoor-C-45 | | Online | กล้องบริเวณทางเดิน ตึก C ไป ตึก B ใกล้ลานจอดรถ |
| 9 | 2 | Outdoor-C-48 | | Online | กล้องบริเวณทางเดิน สระน้ำ ใกล้ตึก C |
| 10 | 2 | Coridor-G-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G101 |

| | | | | | |
|---|---|---|---|---|---|
| 11 | 2 | Coridor-G-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 1 ใกล้ห้อง G105 |
| 12 | 2 | Coridor-G-F2-03 |  | Online | กล้องบริเวณทางขึ้นบันได ตึก G ชั้น 2 |
| 13 | 2 | Coridor-G-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G201 |
| 14 | 2 | Coridor-G-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก G ชั้น 2 ใกล้ ห้อง G205 - G206 |
| 15 | 2 | Coridor-H-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H101 |
| 16 | 2 | Coridor-H-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 1 ใกล้ห้อง H105 |
| 17 | 2 | Coridor-H-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก H ชั้น 2 |
| 18 | 2 | Coridor-H-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H201 |
| 19 | 2 | Coridor-H-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก H ชั้น 2 ใกล้ห้อง H205 - H206 |
| 20 | 2 | Outdoor-H-26 |  | Online | กล้องบริเวณทางเดินด้านนอก ตึก H |
| 21 | 2 | Outdoor-H-29 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก H ใกล้สระน้ำ |

| | | | | | |
|---|---|---|---|---|---|
| 22 | 2 | Coridor-E-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ ลานจอดรถ |
| 23 | 2 | Coridor-E-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก E ใกล้ ลิฟท์ |
| 24 | 2 | Coridor-E-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 1 ใกล้ ห้อง E106 |
| 25 | 2 | Coridor-E-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 ใกล้ห้อง E203 |
| 26 | 2 | Coridor-E-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 2 |
| 27 | 2 | Coridor-E-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E303 |
| 28 | 2 | Coridor-E-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก E ชั้น 3 ใกล้ห้อง E306 |
| 29 | 2 | Outdoor-E-54 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก E ใกล้สระน้ำ |
| 30 | 2 | Outdoor-D-55 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้สระน้ำ |
| 31 | 2 | Outdoor-D-56 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้บันไดขึ้นสระน้ำ |
| 32 | 2 | Outdoor-D-57 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก D ใกล้ห้องน้ำ |

## Report CCTV of NVR3

Jun-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 3 | Coridor-F-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 |
| 2 | 3 | Coridor-F-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลานจอดรถ |
| 3 | 3 | Coridor-F-F1-03 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 1 ใกล้ลิฟท์ |
| 4 | 3 | Coridor-F-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F202 - F203 |
| 5 | 3 | Coridor-F-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 2 ใกล้ห้อง F206 |
| 6 | 3 | Coridor-F-F3-06 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F301 |
| 7 | 3 | Coridor-F-F3-07 | | Online | กล้องบริเวณทางเดิน ตึก F ชั้น 3 ใกล้ห้อง F304 |
| 8 | 3 | Outdoor-F-49 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สระน้ำ |
| 9 | 3 | Outdoor-F-50 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก F ใกล้สนามเด็กเล่น |
| 10 | 3 | Coridor-A-F1-01 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A101 |
| 11 | 3 | Coridor-A-F1-02 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 1 ใกล้ห้อง A105 |
| 12 | 3 | Coridor-A-F2-03 | | Online | กล้องบริเวณทางขึ้นบันได ตึก A ชั้น 2 |
| 13 | 3 | Coridor-A-F2-04 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A201 |
| 14 | 3 | Coridor-A-F2-05 | | Online | กล้องบริเวณทางเดิน ตึก A ชั้น 2 ใกล้ห้อง A205 - A206 |
| 15 | 3 | Outdoor-A-36 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ staygreen |
| 16 | 3 | Outdoor-A-37 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ทางเชื่อมไป ตึก B |
| 17 | 3 | Outdoor-A-39 | | Online | กล้องบริเวณทางเดินด้านนอก ตึก A ใกล้ประตูไม้ |
| 18 | 3 | B12-F1-01 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 1 |
| 19 | 3 | B12-F1-02 | | Online | กล้องบริเวณ Reception stayfit ชั้น 1 |
| 20 | 3 | B12-F1-03 | | Online | กล้องบริเวณทางเข้า Stayfit |
| 21 | 3 | B12-F2-04 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 2 |
| 22 | 3 | B12-F3-05 | | Online | กล้องบริเวณภายใน Stayfit ชั้น 3 |
| 23 | 3 | Lift-C | | Online | กล้องบริเวณภายในลิฟท์ ตึก C |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 3 | Lift-D | | Online | กล้องบริเวณภายในลิฟท์ ตึก D |
| 25 | 3 | Lift-E | | Online | กล้องบริเวณภายในลิฟท์ ตึก E |
| 26 | 3 | Lift-F | | Online | กล้องบริเวณภายในลิฟท์ ตึก F |
| 27 | 3 | Poolbar-01 | | Online | กล้องบริเวณเคาน์เตอร์ Staygreen |
| 28 | 3 | Poolbar-02 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-03 | | Online | กล้องบริเวณภายในร้านอาหาร Staygreen |
| 29 | 3 | Poolbar-Kitchen | | Online | กล้องบริเวณภายในห้องครัว ร้านอาหาร Staygreen |

## Report CCTV of NVR4

Jun-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 4 | B15-Meeting | | Online | กล้องบริเวณทางเดิน ตึก Fresca ชั้น 2 ใกล้ห้อง meeting |
| 2 | 4 | Thai-Restaurant-01 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 |
| 3 | 4 | Thai-Restaurant-02 | | Online | กล้องบริเวณภายในร้าน kamin restaurant ชั้น 3 ด้านหลัง |
| 4 | 4 | Thai-Restaurant-03 | | Online | กล้องบริเวณภายในร้านอาหาร kamin restaurant ชั้น 3 ทางเข้า |
| 5 | 4 | BM-Canteen | | Online | กล้องภายในโรงอาหาร พนักงาน ชั้นใต้ดิน |
| 6 | 4 | BM-Receiving | | Online | กล้องบริเวณพื้นที่รับ-ส่งของ ชั้นใต้ดิน |
| 7 | 4 | BM-Purchase | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้องจัดซื้อ |
| 8 | 4 | BM-Kitchen | | Online | กล้องบริเวณทางเดินชั้นใต้ดิน ใกล้ห้อง butcher |
| 9 | 4 | Spa-01 | | Online | กล้องบริเวณ Reception Spa |
| 10 | 4 | Spa-02 | | Online | กล้องบริเวณ Reception Spa โซนนั่งเล่น |
| 11 | 4 | Spa-03 | | Online | กล้องบริเวณทางเดินไปชั้น 2 ใกล้ห้องล็อคเกอร์ |

| | | | | | |
|---|---|---|---|---|---|
| 12 | 4 | Spa-04 |  | Online | กล้องบริเวณทางเดินไป Onsen ตึก Spa ใกล้ห้องพนักงาน |
| 13 | 4 | Spa-FL2-1 |  | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 ใกล้บันไดทางขึ้น |
| 14 | 4 | Spa-FL2-2 | | Online | กล้องบริเวณทางเดิน ตึก Spa ชั้น 2 |
| 15 | 4 | Yoga | | Online | กล้องบริเวณหน้าห้อง Yoga ชั้น 2 |
| 16 | 4 | Server Room | | Online | กล้องบริเวณหน้าห้อง Server ชั้น 2 ใกล้ Clinic |
| 17 | 4 | Clinic | | Online | กล้องบริเวณ Reception Clinic |
| 18 | 4 | Outdoor-Spa-1 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้จุด สูบบุหรี่ |
| 19 | 4 | Outdoor-Spa-2 | | Online | กล้องบริเวณทางเดินด้านข้าง ตึก Spa ใกล้ลานจอดจักรยาน |
| 20 | 4 | Outdoor-Spa-3 | | Online | กล้องบริเวณทางเดิน ภายนอก ตึก Spa ใกล้ประตูไม้ |
| 21 | 4 | Outdoor-Spa-4 | | Online | กล้องบริเวณทางเดินภายนอก ตึก Spa ด้านหลัง ใกล้ ตึก A |
| 22 | 4 | Stroe Wine | | Online | กล้องบริเวณภายในห้องเก็บไวน์ |
| 23 | 4 | Acc-Room | | Online | บริเวณภายในห้อง บัญชี |

| | | | | | |
|---|---|---|---|---|---|
| 24 | 4 | Onsen-Male | | Online | บริเวณภายในห้อง ONSEN ชาย |
| 25 | 4 | Onsen-Female | | Online | บริเวณภายในห้อง ONSEN หญิง |
| 26 | 4 | CHICA-Bar | | Online | บริเวณภายในบาร์กับห้องครัว CHICA |

## Report CCTV of NVR5

Jun-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 5 | MainEntrance-IN | | Online | กล้องบริเวณทางเข้าที่จอดรถโรงแรม ใกล้ป้อมยาม |
| 2 | 5 | MainEntrance-OUT | | Online | กล้องบริเวณลานจอดรถยนต์ |
| 3 | 5 | Car Park 1 (Gen) | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ป้อมยาม |
| 4 | 5 | Car Park 2 | | Online | กล้องบริเวณที่จอดรถหน้าโรงแรม |
| 5 | 5 | Car Park 3 | | Online | กล้องบริเวณลานจอดรถ |
| 6 | 5 | Car Park 4 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 92 |
| 7 | 5 | Car Park 5 | | Online | กล้องบริเวณลานจอดรถ ใกล้ Villa 91 |
| 8 | 5 | Spirit House | | Online | กล้องบริเวณทางเข้าประตู Villa ใกล้ ศาลพระภูมิ |
| 9 | 5 | Outdoor-Villa-1 | | Online | กล้องบริเวณถนน Villa ใกล้ด้านหลัง Stayfit |
| 10 | 5 | Outdoor-Villa-2 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 1 |

| | | | | | |
|---|---|---|---|---|---|
| 11 | 5 | Outdoor-Villa-3 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 8 |
| 12 | 5 | Outdoor-Villa-4 | | Online | กล้องบริเวณถนน Villa ใกล้ Villa 9 |
| 13 | 5 | ExitDoor-Villa | | Online | กล้องบริเวณประตูทางออกไป 4 ไร่ |
| 14 | 5 | Outdoor-H | | Online | กล้องบริเวณถนน ใกล้ตึก H |
| 15 | 5 | Outdoor-G | | Online | กล้องบริเวณถนน ใกล้ตึก G |
| 16 | 5 | Outdoor-F | | Online | กล้องบริเวณถนน ใกล้ตึก F |
| 17 | 5 | Outdoor-E-1 | | Online | กล้องบริเวณถนน ใกล้ตึก E |
| 18 | 5 | Outdoor-E-2 | | Online | กล้องบริเวณถนน ใกล้ตึก E ใกล้ลานจอดรถ |
| 19 | 5 | Outdoor-E-3 | | Online | กล้องบริเวณถนน ตึก E ใกล้ลานจอดรถ |
| 20 | 5 | Outdoor-D-1 | | Online | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 21 | 5 | Outdoor-D-2 | | Offline | กล้องบริเวณถนน ตึก D ใกล้ลานจอดรถ |
| 22 | 5 | Outdoor-C-1 | | Online | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |
| 23 | 5 | Outdoor-C-2 | | Offline | กล้องบริเวณถนน ตึก C ใกล้ลานจอดรถ |

## Report CCTV of NVR6 at 4Rai

STAY

Jun-24

| No. | NVR | Name | Location to View | Status | Remark & Action |
|---|---|---|---|---|---|
| 1 | 6 | Right entrance | | Online | กล้องบริเวณประตูทางเข้าหอพัก 4ไร่ ชั้น 1 |
| 2 | 6 | Second floor stairs | | Online | กล้องบริเวณบันไดหอพัก 4 ไร่ ชั้น 2 |
| 3 | 6 | Boxing stadium door | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 4 | 6 | Boxing stadium left | | Online | กล้องบริเวณโถง 8 มวยไทย ชั้น 3 |
| 5 | 6 | Boxing stadium | | Online | กล้องบริเวณเวที 8 มวยไทย ชั้น 3 |
| 6 | 6 | HK Store-1 | | Online | กล้องบริเวณภายในห้องแม่บ้าน |
| 7 | 6 | HK Store-2 | | Online | กล้องบริเวณภายในห้องเก็บของแม่บ้าน |
| 8 | 6 | Parking | | Online | กล้องบริเวณลานจอดรถมอเตอร์ไซค์ |
| 9 | 6 | Staff room | | Online | กล้องบริเวณทางเดินหอพักพนักงาน |
| 10 | 6 | Workshop | | Online | กล้องบริเวณห้องเก็บของช่าง ด้านใน |
| 11 | 6 | Workshop2 | | Online | กล้องบริเวณห้องเก็บของช่าง |
| 12 | 6 | Office stairs | | Online | กล้องบริเวณบันไดชั้น 2 ใกล้ประตูทางเข้า Office HR |
| 13 | 6 | OFFICE | | Online | กล้องบริเวณ Office HR |
| 14 | 6 | StayWild | | Online | กล้องบริเวณที่จอดรถมอเตอร์ไซค์ ใกล้ประตูทางเข้าหอพักพนักงาน |
| 15 | 6 | Front area | | Online | กล้องบริเวณลานจอดรถ 4 ไร่ (มุมสูง) ชั้น 3 |
| 15 | 6 | Staff room | | Online | กล้องบริเวณทางเดินไปห้อง Staff Locker |

# เอกสารแนบที่ 11

# รายงานการทำความสะอาดเครื่องปรับอากาศ

PM Air-con M 1

STAY

ENGINEERING DEPRTMENT
DATE 2/01/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก A

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 15:00 FINISH TIME 16:00 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 3/01/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก B

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 15:30 FINISH TIME 16:30 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 4/01/67

P.M. FOR : EN-PM-C-01 Air condition
P.M. CODE :
M/C CODE

FREQUENCY CODE

LOCATION : ตึก C

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 14:40 FINISH TIME 15:40 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 5/01/67

P.M. FOR : EN-PM-C-01 Air condition
P.M. CODE :
M/C CODE

FREQUENCY CODE

LOCATION : ตึก D

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 14:45 FINISH TIME 15:45 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 6/01/67

P.M. FOR : Air condition
P.M. CODE :

EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก E

| DESCRIPTION | Result | | | |
|---|---|---|---|---|
| **GENERAL** | | | | |
| Clean condensor fans and fins | ✓ CLEAN | ( ) DIRTY | | |
| Check the level oil in gear pump | ✓ OK | ( ) LOW | ( ) LITS | |
| Check the gas pressure on discharge side | | | | |
| Check the oil level in the compressor unit | ✓ OK | ( ) LOW | ( ) LITS | ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE | ✓ | OK | |
| Examine the vibratin | ( ) ADJUST | ( ) | RUST | |
| Examine anti-vibration mountings | ✓ OK | ( ) | DEFECTIVE | |
| Clean and examine valves , clocks and automatic drain | | | | |
| Test thermostats | ✓ OK | ( ) | DEFECTIVE | |
| Check refrigerant leaks | ✓ OK | | | |
| **ELECTRIC** | | | | |
| Examine terminal for tightness | ( ) LOOSE | ✓ | TIGHT | |
| Clean contactor with contact cleaner | ✓ OK | ( ) | ARCED | |
| Test relay | ( ) QUIET OPERATION | | | |
| Examine operation of magnetic switch | ( ) HUM OPERATION | | | |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 16:00 FINISH TIME 17:00 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 7/01/67

P.M. FOR : Air condition
P.M. CODE :

EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก F

| DESCRIPTION | Result | | | |
|---|---|---|---|---|
| **GENERAL** | | | | |
| Clean condensor fans and fins | ✓ CLEAN | ( ) DIRTY | | |
| Check the level oil in gear pump | ✓ OK | ( ) LOW | ( ) LITS | |
| Check the gas pressure on discharge side | | | | |
| Check the oil level in the compressor unit | ✓ OK | ( ) LOW | ( ) LITS | ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE | ✓ | OK | |
| Examine the vibratin | ( ) ADJUST | ( ) | RUST | |
| Examine anti-vibration mountings | ✓ OK | ( ) | DEFECTIVE | |
| Clean and examine valves , clocks and automatic drain | | | | |
| Test thermostats | ✓ OK | ( ) | DEFECTIVE | |
| Check refrigerant leaks | ✓ OK | | | |
| **ELECTRIC** | | | | |
| Examine terminal for tightness | ( ) LOOSE | ✓ | TIGHT | |
| Clean contactor with contact cleaner | ✓ OK | ( ) | ARCED | |
| Test relay | ( ) QUIET OPERATION | | | |
| Examine operation of magnetic switch | ( ) HUM OPERATION | | | |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 15:50 FINISH TIME 16:50 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 8/01/67

P.M. FOR : EN-PM-C-01 Air condition
P.M. CODE :
M/C CODE

FREQUENCY CODE

LOCATION : ตึก B

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 13.20 FINISH TIME 14:20 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : [illegible]
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 9/01/67

P.M. FOR : EN-PM-C-01 Air condition
P.M. CODE :
M/C CODE

FREQUENCY CODE

LOCATION : ตึก H

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 15:10 FINISH TIME 16:10 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : [illegible]
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 10/01/67

P.M. FOR : Air condition
P.M. CODE : M/C CODE

EN-PM-C-01

FREQUENCY CODE

LOCATION : ฝั่งเหนือ

| DESCRIPTION | Result | | | |
|---|---|---|---|---|
| **GENERAL** | | | | |
| Clean condensor fans and fins | ✓ CLEAN | ( ) DIRTY | | |
| Check the level oil in gear pump | ✓ OK | ( ) LOW | ( ) LITS | |
| Check the gas pressure on discharge side | | | | |
| Check the oil level in the compressor unit | ✓ OK | ( ) LOW | ( ) LITS | ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE | ✓ | OK | |
| Examine the vibratin | ( ) ADJUST | ( ) | RUST | |
| Examine anti-vibration mountings | ✓ OK | ( ) | DEFECTIVE | |
| Clean and examine valves , clocks and automatic drain | | | | |
| Test thermostats | ✓ OK | ( ) | DEFECTIVE | |
| Check refrigerant leaks | ✓ OK | | | |
| **ELECTRIC** | | | | |
| Examine terminal for tightness | ( ) LOOSE | ✓ | TIGHT | |
| Clean contactor with contact cleaner | ✓ OK | ( ) | ARCED | |
| Test relay | ( ) QUIET OPERATION | | | |
| Examine operation of magnetic switch | ( ) HUM OPERATION | | | |

COMMENTS :

DONE BY 2. 3. 4.

START AT 10:00 FINISH TIME 11:00 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 11/01/67

P.M. FOR : Air condition
P.M. CODE : M/C CODE

EN-PM-C-01

FREQUENCY CODE

LOCATION : ฝั่ง

| DESCRIPTION | Result | | | |
|---|---|---|---|---|
| **GENERAL** | | | | |
| Clean condensor fans and fins | ✓ CLEAN | ( ) DIRTY | | |
| Check the level oil in gear pump | ✓ OK | ( ) LOW | ( ) LITS | |
| Check the gas pressure on discharge side | | | | |
| Check the oil level in the compressor unit | ✓ OK | ( ) LOW | ( ) LITS | ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE | ✓ | OK | |
| Examine the vibratin | ( ) ADJUST | ( ) | RUST | |
| Examine anti-vibration mountings | ✓ OK | ( ) | DEFECTIVE | |
| Clean and examine valves , clocks and automatic drain | | | | |
| Test thermostats | ✓ OK | ( ) | DEFECTIVE | |
| Check refrigerant leaks | ✓ OK | | | |
| **ELECTRIC** | | | | |
| Examine terminal for tightness | ( ) LOOSE | ✓ | TIGHT | |
| Clean contactor with contact cleaner | ✓ OK | ( ) | ARCED | |
| Test relay | ( ) QUIET OPERATION | | | |
| Examine operation of magnetic switch | ( ) HUM OPERATION | | | |

COMMENTS :

DONE BY 2. 3. 4.

START AT 14:30 FINISH TIME 15:30 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 12/01/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : 457

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 15:40 FINISH TIME 16:40 TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 12/01/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : [illegible]

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 15:45 FINISH TIME 16:45 TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

PM Air-Con M.1

STAY

Wellbeing & Lifestyle Resort

ENGINEERING DEPRTMENT
DATE 19 ต.ค. 67

P.M. FOR : EN-PM-C-01 Air condition
P.M. CODE :
M/C CODE

FREQUENCY CODE

LOCATION : ห้องล

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 13:40 FINISH TIME 14:40 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : [signature]
Approve BY :

PM Air-Con . M. . 2

STAY

Wellbeing & Lifestyle Resort

ENGINEERING DEPRTMENT
DATE 5/02/67

P.M. FOR : EN-PM-C-01 Air condition
P.M. CODE :
M/C CODE

FREQUENCY CODE

LOCATION : ตึก D

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ชม HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : [signature]
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 6/02/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก E

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 15:30 2. 3. 4.

START AT 15:30 FINISH TIME 16:30 TOTAL 1 ชม HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : วิศิษฐ์
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 7/02/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก F

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 14:20 FINISH TIME 15:30 TOTAL 1:10 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : ชาญ
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 8/02/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก B

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 15:40 FINISH TIME 16:30 TOTAL 50 น. HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : ตึก
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 9/02/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก H

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 14:40 FINISH TIME 15:40 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : อาทิต + ตึก
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 10/02/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ฝั่งเหนือ

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | ✓ CLEAN ( ) DIRTY |
| Check the level oil in gear pump | ✓ OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ✓ OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE ✓ OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | ✓ OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | ✓ OK ( ) DEFECTIVE |
| Check refrigerant leaks | ✓ OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE ✓ TIGHT |
| Clean contactor with contact cleaner | ✓ OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 10:00 FINISH TIME 11:20 TOTAL 1:20 HOURS

SUPERVISOR COMMENTS :

= ANUAL Q = QUARTERLY
= SEMI-ANUAL M = MONTHLY

Check By : ธานินทร์
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 11/02/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึกป่า

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | ✓ CLEAN ( ) DIRTY |
| Check the level oil in gear pump | ✓ OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ✓ OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE ✓ OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | ✓ OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | ✓ OK ( ) DEFECTIVE |
| Check refrigerant leaks | ✓ OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE ✓ TIGHT |
| Clean contactor with contact cleaner | ✓ OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 11:40 FINISH TIME 12:40 TOTAL 1. HOURS

SUPERVISOR COMMENTS :

= ANUAL Q = QUARTERLY
= SEMI-ANUAL M = MONTHLY

Check By : อภิสิทธิ์
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 12/02/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ห้องสัมมนา

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | ✓ CLEAN ( ) DIRTY |
| Check the level oil in gear pump | ✓ OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ✓ OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE ✓ OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | ✓ OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | ✓ OK ( ) DEFECTIVE |
| Check refrigerant leaks | ✓ OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE ✓ TIGHT |
| Clean contactor with contact cleaner | ✓ OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 16:00 FINISH TIME 17:00 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : ศิลป์+ธก
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 17/02/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : เพลาก้า

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | ✓ CLEAN ( ) DIRTY |
| Check the level oil in gear pump | ✓ OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ✓ OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE ✓ OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | ✓ OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | ✓ OK ( ) DEFECTIVE |
| Check refrigerant leaks | ✓ OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE ✓ TIGHT |
| Clean contactor with contact cleaner | ✓ OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 14:50 FINISH TIME 15:55 TOTAL 1:05 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : ศิลป์+ชาญ
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 18/02/17

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : √ 1-4

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (√) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (√) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (√) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (√) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (√) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (√) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (√) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (√) TIGHT |
| Clean contactor with contact cleaner | (√) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 15:00 FINISH TIME 16:30 TOTAL 1:30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 19/02/17

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : √ 5-8

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (√) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (√) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (√) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (√) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (√) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (√) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (√) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (√) TIGHT |
| Clean contactor with contact cleaner | (√) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 14:30 FINISH TIME 16:00 TOTAL 1:30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 20/02/17

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : V 9-10

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 15:20 FINISH TIME 16:30 TOTAL 1:10 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : โสภณ สัก
Approve BY :

PM Air-con N.3

STAY

ENGINEERING DEPRTMENT
DATE 9/03/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก A

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 11:30 FINISH TIME 13:10 TOTAL 1:00 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : สัก+โสภณ
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 10/03/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก B

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 13:00 FINISH TIME 14:00 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 17/03/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : อาคาร C

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 15:00 FINISH TIME 16:00 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 23/03/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : Villa V4

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 16.40 FINISH TIME 16.55 TOTAL 15 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : โอ๊ก+ฝัก
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 23/03/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : villa 3

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 16.25 FINISH TIME 16.40 TOTAL 15 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : โอ๊ก+ฝัก
Approve BY :

STAY

Wellbeing & Lifestyle Resort

ENGINEERING DEPRTMENT
DATE 29/03/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : villa 2

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 16:15 FINISH TIME 16:25 TOTAL 15 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : โชคชัย
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 23/03/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : villa 1

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 16:00 FINISH TIME 16:15 TOTAL 15 น. HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : โชคชัย
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 24/09/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : [illegible]

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 10:00 FINISH TIME 11:00 TOTAL 1 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : [illegible]
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 30/09/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : villa 5

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 15:00 FINISH TIME 15:30 TOTAL 30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : [illegible]
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 30/03/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : villa 6

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 16:00 FINISH TIME 16:30 TOTAL 30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สัก
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 30/03/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : villa 7

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B\ 2. 3. 4.

START AT 14:40 FINISH TIME 15:10 TOTAL 30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : ไสก + วก
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 30/03/17

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : villa 8

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixe | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 16:00 FINISH TIME 16:30 TOTAL 30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 31/03/17

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : villa 10

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixe | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 16:10 FINISH TIME 16:40 TOTAL 30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : OAT
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 31/03/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : N/119 9

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drain | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE BY 2. 3. 4.

START AT 15:30 FINISH TIME 16:00 TOTAL 30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

PM Air-con M.4

STAY

ENGINEERING DEPRTMENT
DATE 13/12/69

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก A

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | ( ) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ติดตั้งเรียบร้อย

DONE BY 2. 3. 4.

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ชั่วโมง HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : OAT + ศักดิ์
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 14/8/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก B

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW (✓) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE ( ) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ✓ ✓

DONE B' 2. 3. 4.

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ชม. HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 15/8/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก C

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 18/4/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก D

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำงานปกติ

DONE B` 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 18/4/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก E

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | ( ) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำงานปกติ

DONE B` 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 19/4/69

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : ห้อง F

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำความสะอาด

DONE B` _____ 2. _____ 3. _____ 4. _____

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ชั่วโมง HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์ + ศรี + แมน
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 19/4/69

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : ห้อง H

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำความสะอาด

DONE B` _____ 2. _____ 3. _____ 4. _____

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ชั่ว. HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์ + ก้อ
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 19/4/69

P.M. FOR : EN-PM-C-01 Air condition
P.M. CODE :
M/C CODE

FREQUENCY CODE

LOCATION : MA G

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำงานปกติ

DONE B` 2. 3. 4.

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ชั่วโมง HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : ศิริพงษ์ + ต้น
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 19/4/69

P.M. FOR : EN-PM-C-01 Air condition
P.M. CODE :
M/C CODE

FREQUENCY CODE

LOCATION : V. 1, 2

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำงานปกติ

DONE B` 2. 3. 4.

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ชั่วโมง HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : ศิริพงษ์ + ต้น + เบนท์
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 29/10/69

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : 3,4

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ถ้าออกร้อน

DONE B` 2. 3. 4.

START AT 15:00 FINISH TIME 16:00 TOTAL 1 0.2 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : ศักดิ์ + ต้อ
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 30/10/69

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : 5,6

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ถ้าเบอร์ร้อน

DONE B` 2. 3. 4.

START AT 15:00 FINISH TIME 16:00 TOTAL 1 0.2 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : ศักดิ์ + ต้อ + เพ็ง
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 30/04/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : 7,8

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำความสะอาด

DONE B` _____ 2. _____ 3. _____ 4. _____

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ช.ม. HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์ + ดิ + แบด
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 30/04/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : V.9, 10

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำความสะอาด

DONE B` _____ 2. _____ 3. _____ 4. _____

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ช.ม. HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์ + ดิ + BAT
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 8/4/67

P.M. FOR : EN-PM-C-01 Air condition
P.M. CODE : M/C CODE

FREQUENCY CODE

LOCATION : แม่บ้าน

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : คืนวันเสร็จ

DONE B' 2. 3. 4.

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ชั่วโมง HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : คิงส์ + ลิว + อสท
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 8/4/67

P.M. FOR : EN-PM-C-01 Air condition
P.M. CODE : M/C CODE

FREQUENCY CODE

LOCATION : ภายนอกตึก

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : คืนวันเสร็จ

DONE B' 2. 3. 4.

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ชั่วโมง HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : คิงส์ + ลิว + แมว
Approve BY :

STAY

EN-PM-C-01

ENGINEERING DEPRTMENT
DATE 22/4/67

P.M. FOR : Air condition
P.M. CODE :
M/C CODE_____

FREQUENCY CODE _____

LOCATION : เฟสก้า

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ชั่วโมง HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : ศักดิ์ + ดิ์ + เนต
Approve BY : _____

STAY

EN-PM-C-01

ENGINEERING DEPRTMENT
DATE 22/6/67

P.M. FOR : Air condition
P.M. CODE :
M/C CODE_____

FREQUENCY CODE _____

LOCATION : ฟิตเนส

| DESCRIPTION | Result |
|---|---|
| **GENERAL** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| **ELECTRIC** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ติดอดรโอต

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT 15:00 FINISH TIME 16:00 TOTAL 1 ชั่วโมง HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : ศักดิ์ + ดิ์ + อาท
Approve BY : _____

STAY

PM Air-Con M.B

ENGINEERING DEPRTMENT
DATE 14/5/69

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : ตึก A

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ล้างคอยล์เย็น

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT 13:00 FINISH TIME 16:30 TOTAL 1.30 นาที HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์ + ศุภ + เกษตร
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 18/5/69

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : ตึก B

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ล้างคอยล์เย็น

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT 14:00 FINISH TIME 15:30 น. TOTAL 1.30 นาที HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์ + ศุภ + เกษตร
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 19/8/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก C

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK (✓) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำความสะอาด

DONE B' 2. 3. 4.

START AT 15:30 FINISH TIME 16:30 น. TOTAL 1 ชม HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : โชติ + แมคอ์
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 18/8/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ตึก D

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำความสะอาด

DONE B' 2. 3. 4.

START AT 15:00 FINISH TIME 16:30 น. TOTAL 1.30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL
Q = QUARTERLY
M = MONTHLY

Check By : โชติ + ศิว
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 18/8/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก E

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ถ่ายลงน้ำมัน

DONE B' 2. 3. 4.

START AT 14:00 FINISH TIME 15:30 TOTAL 1.30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : เมฆ + ดิว
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 19/8/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก F

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ถ่ายลงน้ำมัน

DONE B' 2. 3. 4.

START AT 15:00 FINISH TIME 16:30 TOTAL 1.30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : เมฆ + ดิว
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 29/8/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก G

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ล้างคอยโบน

DONE B' 2. 3. 4.

START AT 15:00 FINISH TIME 16:30 TOTAL 1.30 ม. HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : เพชร + สิทธิ์
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 30/8/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก H

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ล้างฟิลเตอร์ ล้างคอยโบน

DONE B' 2. 3. 4.

START AT 14:00 FINISH TIME 15:30 TOTAL 1.30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์ + เพชร
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 30/5/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ฟิตเนส

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำความสะอาดพื้นดูดฝุ่น

DONE B' 2. 3. 4.

START AT 15:00 FINISH TIME 16:30 TOTAL 1.30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์ + ศิริ
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 30/5/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : แอร์ ศูนย์

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำความสะอาดพื้นดูดฝุ่น

DONE B' 2. 3. 4.

START AT 15:00 FINISH TIME 16:30 TOTAL 1.30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์ + ศิริ
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 5/3/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : แอร์ เฟสที่ 1

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำความสะอาด ตลอดโซน

DONE B' 2. 3. 4.

START AT 14:00 FINISH TIME 15:30 TOTAL 1:30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : ศักดิ์ชาย ดีจิ
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 5/3/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : แอร์ตลิตตลิม

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : ทำความสะอาด ตลอดโซน

DONE B' 2. 3. 4.

START AT 15:00 FINISH TIME 16:30 TOTAL 1:30 HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

PM Air-con M.6

STAY

ENGINEERING DEPRTMENT
DATE 1/06/67

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ห้อง A

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 2/06/17

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE

FREQUENCY CODE

LOCATION : ห้อง B

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE ( ) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 3/06/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก C

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B` 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 4/06/67

P.M. FOR : EN-PM-C-01
P.M. CODE : Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก D

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 5/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก E

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : ศัก
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 6/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก F

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : ศักดิ์
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 7/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก B

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 8/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ตึก H

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 9/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : V1

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : _____
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 10/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : V 2

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | ( ) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : _____
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 11/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : V 3

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : [illegible]
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 12/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : V4

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : [illegible]
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 14/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : เวรามรม

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : [illegible]
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 13/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : อาคาร A

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : [illegible]
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 14/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : อาคาร B

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : [illegible]
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 15/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : อาคาร C

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : [illegible]
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 14/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : V61

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : เมือ
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 13/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : V5

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : เมือ + [illegible]
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 15/06/17

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : V7

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 16/08/17

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : V8

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 16/01/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : ตึก D

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สมาน
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 17/01/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : ตึก E

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สมาน
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 18/01/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : ชั้น F

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : ศักดิ์
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 17/01/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : ✓ 9

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : ศักดิ์
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 18/6/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : V10

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : แป้น +ล่ก
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 19/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE_____

FREQUENCY CODE _____

LOCATION : ตึก 8

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : ชัยวัฒน์
Approve BY : _____

STAY

ENGINEERING DEPRTMENT
DATE 20/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ชั้น 4

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 21/06/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : ห้องนอน

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By :
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 22/01/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : กะทัด

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์
Approve BY :

PM Air-con M.6

STAY

ENGINEERING DEPRTMENT
DATE 24/01/67

P.M. FOR :
P.M. CODE :

EN-PM-C-01
Air condition
M/C CODE

FREQUENCY CODE

LOCATION : อ.ป.ว

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS :

DONE B' 2. 3. 4.

START AT FINISH TIME TOTAL HOURS

SUPERVISOR COMMENTS :

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สิทธิ์
Approve BY :

STAY

ENGINEERING DEPRTMENT
DATE 29/06/17

P.M. FOR : Air condition
P.M. CODE : EN-PM-C-01
M/C CODE_____

FREQUENCY CODE _____

LOCATION : เพดาน

| DESCRIPTION | Result |
|---|---|
| ***GENERAL*** | |
| Clean condensor fans and fins | (✓) CLEAN ( ) DIRTY |
| Check the level oil in gear pump | (✓) OK ( ) LOW ( ) LITS |
| Check the gas pressure on discharge side | |
| Check the oil level in the compressor unit | (✓) OK ( ) LOW ( ) LITS ( ) ADD |
| Ensure safety guards are in position and securely fixed | ( ) LOOSE (✓) OK |
| Examine the vibratin | ( ) ADJUST ( ) RUST |
| Examine anti-vibration mountings | (✓) OK ( ) DEFECTIVE |
| Clean and examine valves , clocks and automatic drains | |
| Test thermostats | (✓) OK ( ) DEFECTIVE |
| Check refrigerant leaks | (✓) OK |
| ***ELECTRIC*** | |
| Examine terminal for tightness | ( ) LOOSE (✓) TIGHT |
| Clean contactor with contact cleaner | (✓) OK ( ) ARCED |
| Test relay | ( ) QUIET OPERATION |
| Examine operation of magnetic switch | ( ) HUM OPERATION |

COMMENTS : _____

DONE B' _____ 2. _____ 3. _____ 4. _____

START AT _____ FINISH TIME _____ TOTAL _____ HOURS

SUPERVISOR COMMENTS : _____

= ANUAL
= SEMI-ANUAL

Q = QUARTERLY
M = MONTHLY

Check By : สมชาย
Approve BY : _____

# เอกสารแนบที่ 12

# รายงานการเข้าทำบริการกำจัดสัตว์พาหะ

Pest control 09/1/24

STAY

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING A-1** | | | | |
| | 1101 | JKGV | | |
| | 1102 | JKGV | | |
| | 1103 | JKGV | | |
| | 1104 | JKGV | | |
| | 1105 | JKGV | | |
| | 1106 | JTGV | | |
| | 1107 | JTGV | | |
| | 1108 | JTGV | | |
| | 1201 | JKPV | | |
| | 1202 | JKGV | | |
| | 1203 | JKGV | | |
| | 1204 | JKGV | | |
| | 1205 | JKPV | | |
| | 1206 | JTGV | | |
| | 1207 | JTGV | | |
| | 1208 | JTGV | | |
| | 1209 | JTGV | | |
| **BUILDING B-2** | | | | |
| | 2101 | JKPV | | |
| | 2102 | JKPV | | |
| | 2103 | JKPV | | |
| | 2104 | JKPV | | |
| | 2105 | JKPV | | |
| | 2106 | JTGV | | |
| | 2107 | JTGV | | |
| | 2108 | JTGV | | |
| | 2201. | JKPV | | |
| | 2202 | JKPV | | |
| | 2203 | JKPV | | |
| | 2204 | JKPV | | |
| | 2205 | JKPV | | |
| | 2206 | JTGV | | |
| | 2207 | JTGV | | |
| | 2208 | JTGV | | |
| | 2209 | JTGV | | |
| **BUILDING C-3** | | | | |
| | 3101 | 1BKGV | | |
| | 3102 | 1BKGV | | |
| | 3103 | 1BKPA | | |
| | 3104 | 1BKPA | | |
| | 3105 | 1BKPA | | |
| | 3106 | 1BKPA | | |
| | 3107 | 1BKPA | | |
| | 3108 | 1BKGV | | |
| | 3109 | 1BKGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING C-3 / 26** | | | | |
| | 3201 | 1BKGV | | |
| | 3202 | 2BGV | | |
| | 3203 | 1BKGV | | |
| | 3204 | 1BKPV | | |
| | 3205 | 1BKPV | | |
| | 3206 | 1BKPV | | |
| | 3207 | 1BKPV | | |
| | 3208 | 1BKPV | | |
| | 3209 | 1BKPV | | |
| | 3210 | 1BKPV | | |
| | 3301 | 1BKGV | | |
| | 3302 | 2BGV | | |
| | 3303 | 2BPV | | |
| | 3304 | 1BKPV | | |
| | 3305 | 2BPPP | | |
| | 3306 | 1BKPV | | |
| | 3307 | 1BKPV | | |
| **BUILDING D-4 / 22** | | | | |
| | 4101 | 1BKGV | | |
| | 4102 | 1BKGV | | |
| | 4103 | 1BKGV | | |
| | 4104 | 1BKGV | | |
| | 4105 | 1BKGV | | |
| | 4106 | 1BKGV | | |
| | 4107 | 2BGV | | |
| | 4201 | 2BGV | | |
| | 4202 | 2BGV | | |
| | 4203 | 1BKPV | | |
| | 4204 | 1BKPV | | |
| | 4205 | 1BKPV | | |
| | 4206 | 1BKPV | | |
| | 4207 | 1BKGV | | |
| | 4208 | 1BKGV | | |
| | 4209 | 2BGV | | |
| | 4301 | 1BKGV | | |
| | 4302 | 2BGPP | | |
| | 4303 | 2BPV | | |
| | 4304 | 1BKPV | | |
| | 4305 | 2BPPP | | |
| | 4306 | 2BGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING E-5 / 21** | | | | |
| | 5101 | 1BKPV | | |
| | 5102 | 1BKPV | | |
| | 5103 | 1BKPV | | |
| | 5104 | 1BKPV | | |
| | 5105 | 1BKPV | | |
| | 5106 | 1BKGV | | |
| | 5107 | 2BGV | | |
| | 5201 | 2BGV | | |
| | 5202 | 2BGV | | |
| | 5203 | 1BKPV | | |
| | 5204 | 1BKPV | | |
| | 5205 | 1BKPV | | |
| | 5206 | 1BKPV | | |
| | 5207 | 2BPV | | |
| | 5208 | 2BGV | | |
| | 5301 | 1BKGV | | |
| | 5302 | 2BGPP | / | |
| | 5303 | 2BPV | | |
| | 5304 | 1BKPV | | |
| | 5305 | 2BPPP | / | |
| | 5306 | 2BGV | | |
| **BUILDING F-6 / 15** | | | | |
| | 6101 | 1BKGV | | |
| | 6102 | 1BKGV | | |
| | 6103 | 1BKPA | | |
| | 6104 | 1BKPA | | |
| | 6105 | 1BKPA | | |
| | 6201 | 1BKGV | | |
| | 6202 | 1BKGV | | |
| | 6203 | 1BKPV | | |
| | 6204 | 1BKPV | | |
| | 6205 | 2BPV | | |
| | 6206 | 1BKGV | | |
| | 6301 | 2BPV | | |
| | 6302 | 2BPPP | | |
| | 6303 | 1BKPV | | |
| | 6304 | 1BKGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING G-7** | | | | |
| | 7101 | JKPA | | |
| | 7102 | JKPA | | |
| | 7103 | JKPA | | |
| | 7104 | JKPA | | |
| | 7105 | JKPA | | |
| | 7106 | JTGV | | |
| | 7107 | JTGV | | |
| | 7108 | JTGV | | |
| | 7201 | JKPV | | |
| | 7202 | JKPV | | |
| | 7203 | JKPV | | |
| | 7204 | JKPV | | |
| | 7205 | JKPV | | |
| | 7206 | JTGV | | |
| | 7207 | JTGV | | |
| | 7208 | JTGV | | |
| | 7209 | JTGV | | |
| **BUILDING H-8** | | | | |
| | 8101 | JKPA | | |
| | 8102 | JKPA | | |
| | 8103 | JKPA | | |
| | 8104 | JKPA | | |
| | 8105 | JKPA | | |
| | 8106 | JTGV | | |
| | 8107 | JTGV | | |
| | 8108 | JTGV | | |
| | 8201 | JKPV | | |
| | 8202 | JKPV | | |
| | 8203 | JKPV | | |
| | 8204 | JKPV | | |
| | 8205 | JKPV | | |
| | 8206 | JTGV | | |
| | 8207 | JTGV | | |
| | 8208 | JTGV | | |
| | 8209 | JTGV | | |
| **VILLA-9** | | | | |
| | V101 | 3VPP | | |
| | V102 | 3VPP | | |
| | V103 | 3VPP | | |
| | V104 | 3VPP | | |
| | V105 | 3VPPA | | |
| | V106 | 3VPPA | | |
| | V107 | 3VPPA | / | |
| | V108 | 3VPPA | / | |
| | V109 | 3VPP | | |
| | V110 | 3VPP | | |

* จุดที่ U1 - Light โล่ง

By... Por.

- ฉีดพ่นไล่ยุงทามแนวต้นไม้ทั้งหมดของโรงแรม
- ใส่สารอะเบสในท่อน้ำทิ้งทั้งหมด

---


บริษัท แอ๊ดวานซ์ กรุ๊ป เอเชีย จำกัด
234/9 ถนนเสรีไทยแขวงคันนายาวเขตคันนายาว 10230
234/9 Seri Thai Road, Khannayao Subdistrict, Khannayao District, Thailand. Bangkok 10230
โทร 0-2704-5333 แฟกซ์ 0-2704-5353 Website : www.advancegroupasia.com


## Service Report
## รายงานการเข้าทำบริการ

เลขที่ :A2024-006268

วันที่ : 08/01/2024

เลขที่สัญญา : CT23-0011131 ชื่อผู้ว่าจ้าง : บริษัท รีสอร์ทไลฟ์ จำกัด (สาขา 00001) ผู้ประสานงาน/ผู้ติดต่อ : คุณเจมส์ 076-363250

ที่อยู่ : 56/80 Moo 4 T.Rawai A.Muang จังหวัด ภูเก็ต 83130

โทรศัพท์ : 076 363 250 โทรสาร :

วันที่เข้าบริการ : 09/01/2024 เวลา : เวลาออก : ระยะสัญญา : 01/07/2023 - 30/06/2024

หมายเหตุ : กำจัด ปลวดBio.ม.ส.น.ย. 4ครั้ง/เดือน(แมลง)

| พื้นที่ทำบริการ / รายละเอียดงาน | ชนิดของแมลง | สารเคมีที่ใช้ | ผลการตรวจสอบ | หมายเหตุ |
|---|---|---|---|---|
| สเตย์ เวลบีอิ้ง แอนด์ ไลฟ์สไตล์ รีสอร์ต | | -เฟนโดน่า 10 SC 120 cc | | |
| ☑ ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบมด แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | มด | -โบรมาดิโอกราด 2 ซอง | | |
| ☐ วางเหยื่อกำจัดหนู ประเภทออกฤทธิ์ช้า ในบริเวณรอบนอกอาคาร | หนู | -กระดานกาวสำเร็จรูป | | |
| ☐ วางกาวดามพื้นที่ที่วางเหยื่อพิษไม่ได้ วางกาวบริเวณพื้นที่ภายใน | | -พรีแม็กซ์ 250 EC 90 cc | | |
| ☑ โยนเหยื่อพิษรอบนอกอาคาร | | - ทราฟอเล็ต 3 ซอง | | |
| ☑ ฉีดพ่นเคมีแบบครอบคลุมพื้นที่ โดยพ่นแบบฝอยละเอียด หรือพ่นหมอกควัน บริเวณภายในตัวอาคาร และพ่นแบบหมอกควันบริเวณท่อน้ำเสีย และท่อน้ำทิ้งนอกอาคาร | ยุง | | | |
| ☑ ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบแมลงสาบ แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | แมลงสาบ | | | |

| Team | พนักงาน | หมายเหตุ |
|---|---|---|
| ทีม A | นายพิษณุพงศ์ ชูวงศ์ | ทำการฉีดพ่นเคมีภายในห้องพักแขก กลิ่นวิลล่า ห้องเป็นต้น ห้องน้ำ และตามจุดต่างๆ และจุดอื่นๆ ตามความต้องการ ก่อนสิ้นสุดการบริการ ได้ทำการเช็ดถูพื้นห้องน้ำ และทำความสะอาดพื้นที่ให้เรียบร้อย และได้ทำการเก็บกวาดเศษขยะ ขนออกไปทิ้งนอกบริเวณ ตามที่ลูกค้าต้องการ เพื่อความสะดวกสบายของลูกค้าและความปลอดภัยของลูกค้า เพื่อความเรียบร้อยและความสวยงามของสถานที่ |

พิษณุพงศ์ . ชูวงศ์

บริษัท แอ๊ดวานซ์ กรีป เอเชีย จำกัด
234/9 ถนนเสรีไทยแขวงคันนายาวเขตคันนายาว 10230
234/9 Seri Thai Road, Khannayao Subdistrict, Khannayao District, Thailand. Bangkok 10230
โทร 0-2704-5333 แฟกซ์ 0-2704-5353 Website : www.advancegroupasia.com

## Service Report
## รายงานการเข้าทำบริการ

วันที่ : 08/01/2024 เลขที่ :A2024-006255
เลขที่สัญญา : CT23-0011131 ชื่อผู้ว่าจ้าง : บริษัท รีสอร์ทไลฟ์ จำกัด (สาขา 00001) ผู้แจ้ง/ผู้ติดต่อ : คุณเจมส์ 076-363250
ที่อยู่ : 56/80 Moo 4 T.Rawai A.Muang จังหวัด ภูเก็ต 83130
โทรศัพท์ : 076 363 250 โทรสาร :
วันที่เข้าบริการ : 09/01/2024 เวลา : เวลาออก : ระยะสัญญา : 01/07/2023 - 30/06/2024
หมายเหตุ : กำจัด ปลวกBio.ม.ส.น.ย. 4ครั้ง/เดือน(ปลวกBio)

| พื้นที่ทำบริการ / รายละเอียดงาน | ชนิดของแมลง | สารเคมีที่ใช้ | ผลการตรวจสอบ | หมายเหตุ |
|---|---|---|---|---|
| สเตย์ เวลบีอิ้ง แอนด์ ไลฟ์สไตล์ รีสอร์ต | | -แม็กนั่ม โปร AO 11 | | |
| ☐ เจาะพื้น อัดน้ำยาลงดิน หรือส่วนที่เห็นว่าเป็นจุดล่อแหลมต่อการบุกรุกเข้าทำลายของปลวก | ปลวกระบบเคมี | | | |
| ☑ ฉีดพ่นน้ำยาเคมีภายในและรอบนอกตามรอยแตกรอยร้าวและจุดที่พบปัญหา | | | | |
| ☑ ตรวจเช็ค และติดตามผล พร้อมกับการทำงานประจำเดือน | ปลวกระบบ Bio | | | |

| Team | พนักงาน | หมายเหตุ |
|---|---|---|
| ทีม A | นายพิษณุพงศ์ ชูวงศ์ | [illegible] |

บริษัท แอ๊ดวานซ์ กรีป เอเชีย จำกัด
234/9 ถนนเสรีไทยแขวงคันนายาวเขตคันนายาว 10230
234/9 Seri Thai Road, Khannayao Subdistrict, Khannayao District, Thailand. Bangkok 10230
โทร 0-2704-5333 แฟกซ์ 0-2704-5353 Website : www.advancegroupasia.com

## Service Report
## รายงานการเข้าทำบริการ

วันที่ : 20/02/2024 เลขที่ :A2024-050943
เลขที่สัญญา : CT23-0011131 ชื่อผู้ว่าจ้าง : บริษัท รีสอร์ทไลฟ์ จำกัด (สาขา 00001) ผู้แจ้ง/ผู้ติดต่อ : คุณเจมส์ 076-363250
ที่อยู่ : 56/80 Moo 4 T.Rawai A.Muang จังหวัด ภูเก็ต 83130
โทรศัพท์ : 076 363 250 โทรสาร :
วันที่เข้าบริการ : 20/02/2024 เวลา : 13.30 เวลาออก : 15.30 ระยะสัญญา : 01/07/2023 - 30/06/2024
หมายเหตุ : กำจัด ปลวกBio.ม.ส.น.ย. 4ครั้ง/เดือน(แมลง)

| พื้นที่ทำบริการ / รายละเอียดงาน | ชนิดของแมลง | สารเคมีที่ใช้ | ผลการตรวจสอบ | หมายเหตุ |
|---|---|---|---|---|
| สเตย์ เวลบีอิ้ง แอนด์ ไลฟ์สไตล์ รีสอร์ต | | -เฟนโดนา 10 SC 60 ซีซี | | |
| ☑ ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบมด แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | มด | -โบรมาดีโอกราด 300 กรัม | - [illegible] | |
| ☐ วางเหยื่อกำจัดหนู ประเภทออกฤทธิ์ช้า ในบริเวณรอบนอกอาคาร | หนู | -กระดานกาวสำเร็จรูป | - [illegible] | |
| ☐ วางกาวตามพื้นที่ที่วางเหยื่อพิษไม่ได้ วางกาวบริเวณพื้นที่ภายใน | | -พรีแม็กซ์ 250 EC AO 11 | [illegible] | |
| ☑ วางเหยื่อพิษรอบนอกอาคาร | | | | |
| ☑ ฉีดพ่นเคมีแบบครอบคลุมพื้นที่ โดยพ่นแบบฝอยละเอียด หรือพ่นหมอกควัน บริเวณภายในตัวอาคาร และพ่นแบบหมอกควันบริเวณท่อน้ำเสีย และท่อน้ำทิ้งนอกอาคาร | ยุง | | | |
| ☑ ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบแมลงสาบ แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | แมลงสาบ | | | |

| Team | พนักงาน | หมายเหตุ |
|---|---|---|
| ทีม F | นายทัศพล อาด่า | - [illegible]<br>- [illegible]<br>- [illegible]<br>- [illegible] |

20/2/24

STAY

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING A-1** | | | | |
| | 1101 | JKGV | | |
| | 1102 | JKGV | | |
| | 1103 | JKGV | | |
| | 1104 | JKGV | | |
| | 1105 | JKGV | | |
| | 1106 | JTGV | | |
| | 1107 | JTGV | | |
| | 1108 | JTGV | | |
| | 1201 | JKPV | | |
| | 1202 | JKGV | | |
| | 1203 | JKGV | | |
| | 1204 | JKGV | | |
| | 1205 | JKPV | | |
| | 1206 | JTGV | | |
| | 1207 | JTGV | | |
| | 1208 | JTGV | | |
| | 1209 | JTGV | | |
| **BUILDING B-2** | | | | |
| | 2101 | JKPV | | |
| | 2102 | JKPV | | |
| | 2103 | JKPV | | |
| | 2104 | JKPV | | |
| | 2105 | JKPV | | |
| | 2106 | JTGV | | |
| | 2107 | JTGV | | |
| | 2108 | JTGV | | |
| | 2201 | JKPV | | |
| | 2202 | JKPV | | |
| | 2203 | JKPV | | |
| | 2204 | JKPV | | |
| | 2205 | JKPV | | |
| | 2206 | JTGV | | |
| | 2207 | JTGV | | |
| | 2208 | JTGV | | |
| | 2209 | JTGV | | |
| **BUILDING C-3** | | | | |
| | 3101 | 1BKGV | | |
| | 3102 | 1BKGV | | |
| | 3103 | 1BKPA | | |
| | 3104 | 1BKPA | | |
| | 3105 | 1BKPA | | |
| | 3106 | 1BKPA | | |
| | 3107 | 1BKPA | | |
| | 3108 | 1BKGV | | |
| | 3109 | 1BKGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING C-3 / 26** | | | | |
| | 3201 | 1BKGV | | |
| | 3202 | 2BGV | | |
| | 3203 | 1BKGV | | |
| | 3204 | 1BKPV | | |
| | 3205 | 1BKPV | | |
| | 3206 | 1BKPV | | |
| | 3207 | 1BKPV | | |
| | 3208 | 1BKPV | | |
| | 3209 | 1BKPV | | |
| | 3210 | 1BKPV | | |
| | 3301 | 1BKGV | | |
| | 3302 | 2BGV | | |
| | 3303 | 2BPV | | |
| | 3304 | 1BKPV | | |
| | 3305 | 2BPPP | | |
| | 3306 | 1BKPV | | |
| | 3307 | 1BKPV | | |
| **BUILDING D-4 / 22** | | | | |
| | 4101 | 1BKGV | | |
| | 4102 | 1BKGV | | |
| | 4103 | 1BKGV | | |
| | 4104 | 1BKGV | | |
| | 4105 | 1BKGV | | |
| | 4106 | 1BKGV | | |
| | 4107 | 2BGV | | |
| | 4201 | 2BGV | | |
| | 4202 | 2BGV | | |
| | 4203 | 1BKPV | | |
| | 4204 | 1BKPV | | |
| | 4205 | 1BKPV | | |
| | 4206 | 1BKPV | | |
| | 4207 | 1BKGV | | |
| | 4208 | 1BKGV | | |
| | 4209 | 2BGV | | |
| | 4301 | 1BKGV | | |
| | 4302 | 2BGPP | | |
| | 4303 | 2BPV | | |
| | 4304 | 1BKPV | | |
| | 4305 | 2BPPP | | |
| | 4306 | 2BGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING E-5 / 21** | | | | |
| | 5101 | 1BKPV | | |
| | 5102 | 1BKPV | | |
| | 5103 | 1BKPV | | |
| | 5104 | 1BKPV | | |
| | 5105 | 1BKPV | | |
| | 5106 | 1BKGV | | |
| | 5107 | 2BGV | | |
| | 5201 | 2BGV | | |
| | 5202 | 2BGV | | |
| | 5203 | 1BKPV | | |
| | 5204 | 1BKPV | | |
| | 5205 | 1BKPV | | |
| | 5206 | 1BKPV | | |
| | 5207 | 2BPV | | |
| | 5208 | 2BGV | | |
| | 5301 | 1BKGV | | |
| | 5302 | 2BGPP | | |
| | 5303 | 2BPV | | |
| | 5304 | 1BKPV | | |
| | 5305 | 2BPPP | | |
| | 5306 | 2BGV | | |
| **BUILDING F-6 / 15** | | | | |
| | 6101 | 1BKGV | | |
| | 6102 | 1BKGV | | |
| | 6103 | 1BKPA | | |
| | 6104 | 1BKPA | | |
| | 6105 | 1BKPA | | |
| | 6201 | 1BKGV | | |
| | 6202 | 1BKGV | | |
| | 6203 | 1BKPV | | |
| | 6204 | 1BKPV | | |
| | 6205 | 2BPV | | |
| | 6206 | 1BKGV | | |
| | 6301 | 2BPV | | |
| | 6302 | 2BPPP | | |
| | 6303 | 1BKPV | | |
| | 6304 | 1BKGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING G-7** | | | | |
| | 7101 | JKPA | | |
| | 7102 | JKPA | | |
| | 7103 | JKPA | | |
| | 7104 | JKPA | | |
| | 7105 | JKPA | | |
| | 7106 | JTGV | | |
| | 7107 | JTGV | | |
| | 7108 | JTGV | | |
| | 7201 | JKPV | | |
| | 7202 | JKPV | | |
| | 7203 | JKPV | | |
| | 7204 | JKPV | | |
| | 7205 | JKPV | | |
| | 7206 | JTGV | | |
| | 7207 | JTGV | | |
| | 7208 | JTGV | | |
| | 7209 | JTGV | | |
| **BUILDING H-8** | | | | |
| | 8101 | JKPA | | |
| | 8102 | JKPA | | |
| | 8103 | JKPA | | |
| | 8104 | JKPA | | |
| | 8105 | JKPA | | |
| | 8106 | JTGV | | |
| | 8107 | JTGV | | |
| | 8108 | JTGV | | |
| | 8201 | JKPV | | |
| | 8202 | JKPV | | |
| | 8203 | JKPV | | |
| | 8204 | JKPV | | |
| | 8205 | JKPV | | |
| | 8206 | JTGV | | |
| | 8207 | JTGV | | |
| | 8208 | JTGV | | |
| | 8209 | JTGV | | |
| **VILLA-9** | | | | |
| | V101 | 3VPP | | |
| | V102 | 3VPP | | |
| | V103 | 3VPP | | |
| | V104 | 3VPP | | |
| | V105 | 3VPPA | | |
| | V106 | 3VPPA | | |
| | V107 | 3VPPA | | |
| | V108 | 3VPPA | | |
| | V109 | 3VPP | | |
| | V110 | 3VPP | | |

By Max


บริษัท แอ๊ดวานซ์ กรุ๊ป เอเชีย จำกัด
234/9 ถนนเสรีไทยแขวงคันนายาวเขตคันนายาว 10230
234/9 Seri Thai Road, Khannayao Subdistrict, Khannayao District, Thailand. Bangkok 10230
โทร 0-2704-5333 แฟกซ์ 0-2704-5353 Website : www.advancegroupasia.com


## Service Report
## รายงานการเข้าทำบริการ

วันที่ : 18/03/2024 เลขที่ :A2024-077950

เลขที่สัญญา : CT23-0011131 ชื่อผู้ว่าจ้าง : บริษัท รีสอร์ทไลฟ์ จำกัด (สาขา 00001) ผู้แจ้ง/ผู้ติดต่อ : คุณเจมส์ 076-363250

ที่อยู่ : 56/80 Moo 4 T.Rawai A.Muang จังหวัด ภูเก็ต 83130

โทรศัพท์ : 076 363 250 โทรสาร :

วันที่เข้าบริการ : 19/03/2024 เวลา : เวลาออก : ระยะสัญญา : 01/07/2023 - 30/06/2024

หมายเหตุ : กำจัด ปลวดBio.ม.ส.น.ย. 4ครั้ง/เดือน(แมลง)

| พื้นที่ทำบริการ / รายละเอียดงาน | ชนิดของแมลง | สารเคมีที่ใช้ | ผลการตรวจสอบ | หมายเหตุ |
|---|---|---|---|---|
| สเตย์ เวลบีอิ้ง แอนด์ ไลฟ์สไตล์ รีสอร์ต | | -เฟนโดน่า 10 SC | | |
| ☑ ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบมด แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | มด | -โบรมาดิโอกราด 200 g<br>-ไอคอน 150cc | | |
| ☐ วางเหยื่อกำจัดหนู ประเภทออกฤทธิ์ช้า ในบริเวณรอบนอกอาคาร | หนู | -กระดานกาวสำเร็จรูป | | |
| ☐ วางกาวตามพื้นที่ที่วางเหยื่อพิษไม่ได้ วางกาวบริเวณพื้นที่ภายใน | | -พรีเม็กซ์ 250 EC 80 cc | | |
| ☑ โยนเหยื่อพิษรอบนอกอาคาร | | | | |
| ☑ ฉีดพ่นเคมีแบบครอบคลุมพื้นที่ โดยพ่นแบบฝอยละเอียด หรือพ่นหมอกควัน บริเวณภายในตัวอาคาร และพ่นแบบหมอกควันบริเวณท่อน้ำเสีย และท่อน้ำทิ้งนอกอาคาร | ยุง | | | |
| ☑ ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบแมลงสาบ แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | แมลงสาบ | | | |

| Team | พนักงาน | หมายเหตุ |
|---|---|---|
| ทีม A | นายพิษณุพงศ์ ชูวงศ์ | - ทำบริการฉีดพ่นเคมีบริเวณภายในและภายนอกห้องพัก, ใต้ถุน อาคาร ท่อทอน ระเบียงของโซน ที่อยู่ของตัวแมลงสาบ มด แมลงวัน โยนเหยื่อรอบนอก พ่นควันเคมีภายนอกห้องพัก, ใต้ถุน อาคาร พ่นท่อระบายน้ำ เพื่อกำจัดยุง |

พิษณุพงศ์ . ศิริวงศ์

19/3/24

# นิทแวลง 19/03/24

STAY

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING A-1** | | | | |
| | 1101 | JKGV | | |
| | 1102 | JKGV | | |
| | 1103 | JKGV | | |
| | 1104 | JKGV | | |
| | 1105 | JKGV | | |
| | 1106 | JTGV | | |
| | 1107 | JTGV | | |
| | 1108 | JTGV | | |
| | 1201 | JKPV | | |
| | 1202 | JKGV | | |
| | 1203 | JKGV | | |
| | 1204 | JKGV | | |
| | 1205 | JKPV | | |
| | 1206 | JTGV | | |
| | 1207 | JTGV | | |
| | 1208 | JTGV | | |
| | 1209 | JTGV | | |
| **BUILDING B-2** | | | | |
| | 2101 | JKPV | | |
| | 2102 | JKPV | | |
| | 2103 | JKPV | | |
| | 2104 | JKPV | | |
| | 2105 | JKPV | | |
| | 2106 | JTGV | | |
| | 2107 | JTGV | | |
| | 2108 | JTGV | | |
| | 2201 | JKPV | ✓ | |
| | 2202 | JKPV | | |
| | 2203 | JKPV | | |
| | 2204 | JKPV | | |
| | 2205 | JKPV | | |
| | 2206 | JTGV | | |
| | 2207 | JTGV | | |
| | 2208 | JTGV | | |
| | 2209 | JTGV | | |
| **BUILDING C-3** | | | | |
| | 3101 | 1BKGV | | |
| | 3102 | 1BKGV | | |
| | 3103 | 1BKPA | | |
| | 3104 | 1BKPA | | |
| | 3105 | 1BKPA | ✓ | |
| | 3106 | 1BKPA | | |
| | 3107 | 1BKPA | | |
| | 3108 | 1BKGV | | |
| | 3109 | 1BKGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING C-3 / 26** | | | | |
| | 3201 | 1BKGV | | |
| | 3202 | 2BGV | ✓ | |
| | 3203 | 1BKGV | | |
| | 3204 | 1BKPV | | |
| | 3205 | 1BKPV | | |
| | 3206 | 1BKPV | | |
| | 3207 | 1BKPV | | |
| | 3208 | 1BKPV | | |
| | 3209 | 1BKPV | | |
| | 3210 | 1BKPV | | |
| | 3301 | 1BKGV | | |
| | 3302 | 2BGV | | |
| | 3303 | 2BPV | | |
| | 3304 | 1BKPV | | |
| | 3305 | 2BPPP | ✓ | |
| | 3306 | 1BKPV | | |
| | 3307 | 1BKPV | | |
| **BUILDING D-4 / 22** | | | | |
| | 4101 | 1BKGV | | |
| | 4102 | 1BKGV | | |
| | 4103 | 1BKGV | | |
| | 4104 | 1BKGV | | |
| | 4105 | 1BKGV | | |
| | 4106 | 1BKGV | | |
| | 4107 | 2BGV | ✓ | |
| | 4201 | 2BGV | | |
| | 4202 | 2BGV | | |
| | 4203 | 1BKPV | | ~ |
| | 4204 | 1BKPV | | |
| | 4205 | 1BKPV | ✓ | |
| | 4206 | 1BKPV | | |
| | 4207 | 1BKGV | | |
| | 4208 | 1BKGV | | |
| | 4209 | 2BGV | | |
| | 4301 | 1BKGV | | |
| | 4302 | 2BGPP | | |
| | 4303 | 2BPV | | |
| | 4304 | 1BKPV | ✓ | |
| | 4305 | 2BPPP | | |
| | 4306 | 2BGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING E-5 / 21** | | | | |
| | 5101 | 1BKPV | | |
| | 5102 | 1BKPV | | |
| | 5103 | 1BKPV | ✓ | |
| | 5104 | 1BKPV | | |
| | 5105 | 1BKPV | ✓ | |
| | 5106 | 1BKGV | | |
| | 5107 | 2BGV | ✓ | |
| | 5201 | 2BGV | ✓ | |
| | 5202 | 2BGV | ✓ | |
| | 5203 | 1BKPV | | |
| | 5204 | 1BKPV | ✓ | |
| | 5205 | 1BKPV | | |
| | 5206 | 1BKPV | | |
| | 5207 | 2BPV | | |
| | 5208 | 2BGV | | |
| | 5301 | 1BKGV | | |
| | 5302 | 2BGPP | | — |
| | 5303 | 2BPV | ✓ | |
| | 5304 | 1BKPV | | |
| | 5305 | 2BPPP | | |
| | 5306 | 2BGV | ✓ | |
| **BUILDING F-6 / 15** | | | | |
| | 6101 | 1BKGV | | |
| | 6102 | 1BKGV | | |
| | 6103 | 1BKPA | | |
| | 6104 | 1BKPA | | |
| | 6105 | 1BKPA | | |
| | 6201 | 1BKGV | | |
| | 6202 | 1BKGV | | |
| | 6203 | 1BKPV | | |
| | 6204 | 1BKPV | | |
| | 6205 | 2BPV | | |
| | 6206 | 1BKGV | | |
| | 6301 | 2BPV | ✓ | |
| | 6302 | 2BPPP | ✓ | |
| | 6303 | 1BKPV | | |
| | 6304 | 1BKGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING G-7** | | | | |
| | 7101 | JKPA | | |
| | 7102 | JKPA | | |
| | 7103 | JKPA | | |
| | 7104 | JKPA | | |
| | 7105 | JKPA | | |
| | 7106 | JTGV | | |
| | 7107 | JTGV | | |
| | 7108 | JTGV | | |
| | 7201 | JKPV | | |
| | 7202 | JKPV | | |
| | 7203 | JKPV | | |
| | 7204 | JKPV | | |
| | 7205 | JKPV | | |
| | 7206 | JTGV | | |
| | 7207 | JTGV | | |
| | 7208 | JTGV | | |
| | 7209 | JTGV | | |
| **BUILDING H-8** | | | | |
| | 8101 | JKPA | ✓ | |
| | 8102 | JKPA | ✓ | |
| | 8103 | JKPA | | |
| | 8104 | JKPA | | |
| | 8105 | JKPA | | |
| | 8106 | JTGV | | |
| | 8107 | JTGV | | |
| | 8108 | JTGV | | |
| | 8201 | JKPV | | |
| | 8202 | JKPV | | |
| | 8203 | JKPV | | |
| | 8204 | JKPV | | |
| | 8205 | JKPV | | |
| | 8206 | JTGV | | |
| | 8207 | JTGV | | |
| | 8208 | JTGV | | |
| | 8209 | JTGV | | |
| **VILLA-9** | | | | |
| | V101 | 3VPP | ✓ | |
| | V102 | 3VPP | | |
| | V103 | 3VPP | | |
| | V104 | 3VPP | ✓ | |
| | V105 | 3VPPA | ✓ | |
| | V106 | 3VPPA | ✓ | |
| | V107 | 3VPPA | ✓ | |
| | V108 | 3VPPA | | |
| | V109 | 3VPP | ✓ | |
| | V110 | 3VPP | ✓ | |

By Yee

13:30

# Advance Pest Control on. 22/4

STAY

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING A-1** | | | | |
| | 1101 | JKGV | | |
| | 1102 | JKGV | | |
| | 1103 | JKGV | | |
| | 1104 | JKGV | | |
| | 1105 | JKGV | | |
| | 1106 | JTGV | | |
| | 1107 | JTGV | | |
| | 1108 | JTGV | | |
| | 1201 | JKPV | | |
| | 1202 | JKGV | | |
| | 1203 | JKGV | | |
| | 1204 | JKGV | | |
| | 1205 | JKPV | | |
| | 1206 | JTGV | | |
| | 1207 | JTGV | | |
| | 1208 | JTGV | | |
| | 1209 | JTGV | | |
| **BUILDING B-2** | | | | |
| | 2101 | JKPV | | |
| | 2102 | JKPV | | |
| | 2103 | JKPV | | |
| | 2104 | JKPV | | |
| | 2105 | JKPV | | |
| | 2106 | JTGV | | |
| | 2107 | JTGV | | |
| | 2108 | JTGV | | |
| | 2201 | JKPV | | |
| | 2202 | JKPV | | |
| | 2203 | JKPV | | |
| | 2204 | JKPV | | |
| | 2205 | JKPV | | |
| | 2206 | JTGV | | |
| | 2207 | JTGV | | |
| | 2208 | JTGV | | |
| | 2209 | JTGV | | |
| **BUILDING C-3** | | | | |
| | 3101 | 1BKGV | | |
| | 3102 | 1BKGV | | |
| | 3103 | 1BKPA | / | |
| | 3104 | 1BKPA | | |
| | 3105 | 1BKPA | / | |
| | 3106 | 1BKPA | | |
| | 3107 | 1BKPA | | |
| | 3108 | 1BKGV | / | |
| | 3109 | 1BKGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING C-3 / 26** | | | | |
| | 3201 | 1BKGV | | |
| | 3202 | 2BGV | | |
| | 3203 | 1BKGV | | |
| | 3204 | 1BKPV | | |
| | 3205 | 1BKPV | / | |
| | 3206 | 1BKPV | | |
| | 3207 | 1BKPV | | |
| | 3208 | 1BKPV | | |
| | 3209 | 1BKPV | | |
| | 3210 | 1BKPV | | |
| | 3301 | 1BKGV | | |
| | 3302 | 2BGV | / | |
| | 3303 | 2BPV | | |
| | 3304 | 1BKPV | | |
| | 3305 | 2BPPP | | |
| | 3306 | 1BKPV | | |
| | 3307 | 1BKPV | | |
| **BUILDING D-4 / 22** | | | | |
| | 4101 | 1BKGV | | |
| | 4102 | 1BKGV | | |
| | 4103 | 1BKGV | / | |
| | 4104 | 1BKGV | // | |
| | 4105 | 1BKGV | | |
| | 4106 | 1BKGV | / | |
| | 4107 | 2BGV | / | |
| | 4201 | 2BGV | / | |
| | 4202 | 2BGV | // | |
| | 4203 | 1BKPV | | |
| | 4204 | 1BKPV | | |
| | 4205 | 1BKPV | | |
| | 4206 | 1BKPV | | |
| | 4207 | 1BKGV | | |
| | 4208 | 1BKGV | | |
| | 4209 | 2BGV | / | |
| | 4301 | 1BKGV | | |
| | 4302 | 2BGPP | / | |
| | 4303 | 2BPV | / | |
| | 4304 | 1BKPV | | |
| | 4305 | 2BPPP | / | |
| | 4306 | 2BGV | / | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING E-5 / 21** | | | | |
| | 5101 | 1BKPV | / | |
| | 5102 | 1BKPV | / | |
| | 5103 | 1BKPV | | |
| | 5104 | 1BKPV | | |
| | 5105 | 1BKPV | / | |
| | 5106 | 1BKGV | / | |
| | 5107 | 2BGV | / | |
| | 5201 | 2BGV | / | |
| | 5202 | 2BGV | | |
| | 5203 | 1BKPV | | |
| | 5204 | 1BKPV | / | |
| | 5205 | 1BKPV | / | |
| | 5206 | 1BKPV | | |
| | 5207 | 2BPV | / | |
| | 5208 | 2BGV | / | |
| | 5301 | 1BKGV | | |
| | 5302 | 2BGPP | / | |
| | 5303 | 2BPV | | |
| | 5304 | 1BKPV | / | |
| | 5305 | 2BPPP | | |
| | 5306 | 2BGV | / | |
| **BUILDING F-6 / 15** | | | | |
| | 6101 | 1BKGV | / | |
| | 6102 | 1BKGV | | |
| | 6103 | 1BKPA | | |
| | 6104 | 1BKPA | | |
| | 6105 | 1BKPA | | |
| | 6201 | 1BKGV | | |
| | 6202 | 1BKGV | | |
| | 6203 | 1BKPV | | |
| | 6204 | 1BKPV | | |
| | 6205 | 2BPV | / | |
| | 6206 | 1BKGV | | |
| | 6301 | 2BPV | | |
| | 6302 | 2BPPP | | |
| | 6303 | 1BKPV | | |
| | 6304 | 1BKGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING G-7** | | | | |
| | 7101 | JKPA | | |
| | 7102 | JKPA | | |
| | 7103 | JKPA | | |
| | 7104 | JKPA | | |
| | 7105 | JKPA | | |
| | 7106 | JTGV | | |
| | 7107 | JTGV | | |
| | 7108 | JTGV | | |
| | 7201 | JKPV | | |
| | 7202 | JKPV | | |
| | 7203 | JKPV | | |
| | 7204 | JKPV | | |
| | 7205 | JKPV | | |
| | 7206 | JTGV | | |
| | 7207 | JTGV | | |
| | 7208 | JTGV | | |
| | 7209 | JTGV | | |
| **BUILDING H-8** | | | | |
| | 8101 | JKPA | | |
| | 8102 | JKPA | | |
| | 8103 | JKPA | | |
| | 8104 | JKPA | | |
| | 8105 | JKPA | | |
| | 8106 | JTGV | | |
| | 8107 | JTGV | | |
| | 8108 | JTGV | | |
| | 8201 | JKPV | | |
| | 8202 | JKPV | | |
| | 8203 | JKPV | | |
| | 8204 | JKPV | | |
| | 8205 | JKPV | | |
| | 8206 | JTGV | | |
| | 8207 | JTGV | | |
| | 8208 | JTGV | | |
| | 8209 | JTGV | | |
| **VILLA-9** | | | | |
| | V101 | 3VPP | | |
| | V102 | 3VPP | / | |
| | V103 | 3VPP | | |
| | V104 | 3VPP | | |
| | V105 | 3VPPA | / | |
| | V106 | 3VPPA | | |
| | V107 | 3VPPA | | |
| | V108 | 3VPPA | | |
| | V109 | 3VPP | | |
| | V110 | 3VPP | / | |

* ห้องที่สกัดสี่เหลี่ยมไว้ เข้าได้ทุกห้อง

บริษัท แอ๊ดวานซ์ กรุ๊ป เอเชีย จำกัด
234/9 ถนนเสรีไทยแขวงคันนายาวเขตคันนายาว 10230
234/9 Seri Thai Road, Khannayao Subdistrict, Khannayao District, Thailand. Bangkok 10230
โทร 0-2704-5333 แฟกซ์ 0-2704-5353 Website : www.advancegroupasia.com

## Service Report
## รายงานการเข้าทำบริการ

วันที่ : 22/04/2024 เลขที่ :A2024-109843
เลขที่สัญญา : CT23-0011131 ชื่อผู้ว่าจ้าง : บริษัท รีสอร์ทไลฟ์ จำกัด (สาขา 00001) ผู้แจ้ง/ผู้ติดต่อ : คุณเจมส์ 076-363250
ที่อยู่ : 56/80 Moo 4 T.Rawai A.Muang จังหวัด ภูเก็ต 83130
โทรศัพท์ : 076 363 250 โทรสาร :
วันที่เข้าบริการ : 23/04/2024 เวลา : เวลาออก : ระยะสัญญา : 01/07/2023 - 30/06/2024
หมายเหตุ : กำจัด ปลวดBio.ม.ส.น.ย. 4ครั้ง/เดือน(แมลง)

| พื้นที่ทำบริการ / รายละเอียดงาน | ชนิดของแมลง | สารเคมีที่ใช้ | ผลการตรวจสอบ | หมายเหตุ |
|---|---|---|---|---|
| สเตย์ เวลบีอิ้ง แอนด์ ไลฟ์สไตล์ รีสอร์ต | | -เฟนโตน่า 10 SC | | |
| [✓] ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบมด แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | มด | -โบรมาดิโอกราด 100 g<br>-ไบไฟร 120 cc | | |
| [ ] วางเหยื่อกำจัดหนู ประเภทออกฤทธิ์ช้า ในบริเวณรอบนอกอาคาร | หนู | -กระดานกาวสำเร็จรูป | | |
| [ ] วางกาวตามพื้นที่ที่วางเหยื่อพิษไม่ได้ วางกาวบริเวณพื้นที่ภายใน | | -พรีแม็กซ์ 250 EC 80 cc | | |
| [✓] โยนเหยื่อพิษรอบนอกอาคาร | | | | |
| [✓] ฉีดพ่นเคมีแบบครอบคลุมพื้นที่ โดยพ่นแบบฝอยละเอียด หรือพ่นหมอกควัน บริเวณภายในตัวอาคาร และพ่นแบบหมอกควันบริเวณท่อน้ำเสีย และท่อน้ำทิ้งนอกอาคาร | ยุง | | | |
| [✓] ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบแมลงสาบ แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | แมลงสาบ | * ตรวจเช็คแมงวัน แมลงเม่าเปรี้ยวเปรี้ยว ตัวแมลงเล็กไร้ | | |

| Team | พนักงาน | หมายเหตุ |
|---|---|---|
| ทีม A | นายพิษณุพงศ์ ชูวงศ์ | - ทำบริการฉีดพ่นเคมีบริเวณ ภายในภายนอกห้องพัก ใช้พ่นตาม ท่อเดิน วาเปียดาวเทียม หมอนนิ่ม เพื่อป้องกันแมลงกัดต่อยต่างๆ มด หนูแมลงสาบ โดยเกลี่ยเหยื่อรอบนอกอาคาร พ่นพ่นเคมีภายนอกอาคาร ตาม พุ่มไม้ ท่อระบายน้ำ เพื่อกำจัดยุง |

พิษณุพงศ์ ชูวงศ์ ผู้สำรวจเบื้องต้น

บริษัท แอ๊ดวานซ์ กรุ๊ป เอเชีย จำกัด
234/9 ถนนเสรีไทยแขวงคันนายาวเขตคันนายาว 10230
234/9 Seri Thai Road, Khannayao Subdistrict, Khannayao District, Thailand. Bangkok 10230
โทร 0-2704-5333 แฟกซ์ 0-2704-5353 Website : www.advancegroupasia.com

## Service Report
## รายงานการเข้าทำบริการ

วันที่ : 31/05/2024 เลขที่ :A2024-151437
เลขที่สัญญา : CT23-0011131 ชื่อผู้ว่าจ้าง : บริษัท รีสอร์ทไลฟ์ จำกัด (สาขา 00001) ผู้แจ้ง/ผู้ติดต่อ : คุณเจมส์ 076-363250
ที่อยู่ : 56/80 Moo 4 T.Rawai A.Muang จังหวัด ภูเก็ต 83130
โทรศัพท์ : 076 363 250 โทรสาร :
วันที่เข้าบริการ : 18/06/2024 เวลา : 13:00 เวลาออก : ระยะสัญญา : 01/07/2023 - 30/06/2024
หมายเหตุ : กำจัด ปลวดBio.ม.ส.น.ย. 4ครั้ง/เดือน(แมลง)

| พื้นที่ทำบริการ / รายละเอียดงาน | ชนิดของแมลง | สารเคมีที่ใช้ | ผลการตรวจสอบ | หมายเหตุ |
|---|---|---|---|---|
| สเตย์ เวลบีอิ้ง แอนด์ ไลฟ์สไตล์ รีสอร์ต | | -เฟนโตน่า 10 SC | | |
| [✓] ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบมด แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | มด | -โบรมาดิโอกราด<br>การรอการเจาะ 3 หลอด | | |
| [ ] วางเหยื่อกำจัดหนู ประเภทออกฤทธิ์ช้า ในบริเวณรอบนอกอาคาร | หนู | -กระดานกาวสำเร็จรูป | | |
| [ ] วางกาวตามพื้นที่ที่วางเหยื่อพิษไม่ได้ วางกาวบริเวณพื้นที่ภายใน | | -พรีแม็กซ์ 250 EC<br>40 cc | | |
| [ ] โยนเหยื่อพิษรอบนอกอาคาร | | | | |
| [✓] ฉีดพ่นเคมีแบบครอบคลุมพื้นที่ โดยพ่นแบบฝอยละเอียด หรือพ่นหมอกควัน บริเวณภายในตัวอาคาร และพ่นแบบหมอกควันบริเวณท่อน้ำเสีย และท่อน้ำทิ้งนอกอาคาร | ยุง | * ได้ทำการรดน้ำยาเคมีตามบริเวณที่มีน้ำขังและจุดเสี่ยงต่างๆ<br>* พ่นสารปรับเสมอระดับ เพื่อป้องกันมดไฟต่างๆ และจุดเสี่ยงต่างๆ โดยรอบรอบบริเวณทั้งหมด | | |
| [✓] ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบแมลงสาบ แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | แมลงสาบ | | | |

| Team | พนักงาน | หมายเหตุ |
|---|---|---|
| ทีม A | นายศิรวิชญ์ คุ้มบ้าน | * ได้ทำการฉีดสารปราบเคมีตามห้องพักและตามโต๊ะ เช่น ห้องครัว, ตู้โชกา, ห้องน้ำ และพุ่งไม้ และห้องพุ่งต่างๆ<br>* ได้ทำการฉีดสารปราบเคมีที่ห้องจะเนื่องจากการสำรวจยังมีห้องตกค้าง |

ศิรวิชญ์ คุ้มบ้าน ผู้ปฏิบัติงาน

18/06/24

STAY

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING A-1** | | | | |
| | 1101 | JKGV | | |
| | 1102 | JKGV | | |
| | 1103 | JKGV | | |
| | 1104 | JKGV | | |
| | 1105 | JKGV | | |
| | 1106 | JTGV | | |
| | 1107 | JTGV | | |
| | 1108 | JTGV | | |
| | 1201 | JKPV | | |
| | 1202 | JKGV | | |
| | 1203 | JKGV | ✓ | |
| | 1204 | JKGV | | |
| | 1205 | JKPV | | |
| | 1206 | JTGV | | |
| | 1207 | JTGV | | |
| | 1208 | JTGV | | |
| | 1209 | JTGV | | |
| **BUILDING B-2** | | | | |
| | 2101 | JKPV | | |
| | 2102 | JKPV | | |
| | 2103 | JKPV | | |
| | 2104 | JKPV | | |
| | 2105 | JKPV | | |
| | 2106 | JTGV | | |
| | 2107 | JTGV | | |
| | 2108 | JTGV | | |
| | 2201 | JKPV | | |
| | 2202 | JKPV | | |
| | 2203 | JKPV | | |
| | 2204 | JKPV | | |
| | 2205 | JKPV | | |
| | 2206 | JTGV | | |
| | 2207 | JTGV | | |
| | 2208 | JTGV | | |
| | 2209 | JTGV | | |
| **BUILDING C-3** | | | | |
| | 3101 | 1BKGV | | |
| | 3102 | 1BKGV | | |
| | 3103 | 1BKPA | | |
| | 3104 | 1BKPA | | |
| | 3105 | 1BKPA | | |
| | 3106 | 1BKPA | | |
| | 3107 | 1BKPA | | |
| | 3108 | 1BKGV | | |
| | 3109 | 1BKGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING C-3 / 26** | | | | |
| | 3201 | 1BKGV | | |
| | 3202 | 2BGV | | |
| | 3203 | 1BKGV | | |
| | 3204 | 1BKPV | | |
| | 3205 | 1BKPV | | |
| | 3206 | 1BKPV | | |
| | 3207 | 1BKPV | ✓ | |
| | 3208 | 1BKPV | | |
| | 3209 | 1BKPV | | |
| | 3210 | 1BKPV | | |
| | 3301 | 1BKGV | | |
| | 3302 | 2BGV | | |
| | 3303 | 2BPV | | |
| | 3304 | 1BKPV | | |
| | 3305 | 2BPPP | | |
| | 3306 | 1BKPV | | |
| | 3307 | 1BKPV | | |
| **BUILDING D-4 / 22** | | | | |
| | 4101 | 1BKGV | | |
| | 4102 | 1BKGV | | |
| | 4103 | 1BKGV | | |
| | 4104 | 1BKGV | | |
| | 4105 | 1BKGV | | |
| | 4106 | 1BKGV | | |
| | 4107 | 2BGV | | |
| | 4201 | 2BGV | | |
| | 4202 | 2BGV | | |
| | 4203 | 1BKPV | | |
| | 4204 | 1BKPV | | |
| | ~~4205~~ | 1BKPV | ✓ DBLLOCK. | |
| | 4206 | 1BKPV | | |
| | 4207 | 1BKGV | | |
| | 4208 | 1BKGV | | |
| | 4209 | 2BGV | | |
| | 4301 | 1BKGV | In | |
| | 4302 | 2BGPP | | |
| | 4303 | 2BPV | | |
| | 4304 | 1BKPV | | |
| | 4305 | 2BPPP | | |
| | 4306 | 2BGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING E-5 / 21** | | | | |
| | 5101 | 1BKPV | | |
| | 5102 | 1BKPV | | |
| | 5103 | 1BKPV | | |
| | 5104 | 1BKPV | | |
| | 5105 | 1BKPV | | |
| | 5106 | 1BKGV | | |
| | 5107 | 2BGV | | |
| | 5201 | 2BGV | | |
| | 5202 | 2BGV | | |
| | 5203 | 1BKPV | | |
| | 5204 | 1BKPV | | |
| | 5205 | 1BKPV | | |
| | 5206 | 1BKPV | | |
| | 5207 | 2BPV | | |
| | 5208 | 2BGV | | |
| | 5301 | 1BKGV | | |
| | 5302 | 2BGPP | | |
| | 5303 | 2BPV | | |
| | 5304 | 1BKPV | | |
| | 5305 | 2BPPP | | |
| | 5306 | 2BGV | | |
| **BUILDING F-6 / 15** | | | | |
| | 6101 | 1BKGV | | |
| | 6102 | 1BKGV | | |
| | 6103 | 1BKPA | | |
| | 6104 | 1BKPA | | |
| | 6105 | 1BKPA | | |
| | 6201 | 1BKGV | | |
| | 6202 | 1BKGV | | |
| | 6203 | 1BKPV | | |
| | 6204 | 1BKPV | | |
| | 6205 | 2BPV | | |
| | 6206 | 1BKGV | | |
| | 6301 | 2BPV | | |
| | 6302 | 2BPPP | | |
| | 6303 | 1BKPV | | |
| | 6304 | 1BKGV | | |

| Attd. | Room No. | Room Type | Status DONE | Status Not Done |
|---|---|---|---|---|
| **BUILDING G-7** | | | | |
| | 7101 | JKPA | | |
| | 7102 | JKPA | | |
| | 7103 | JKPA | | |
| | 7104 | JKPA | | |
| | 7105 | JKPA | | |
| | 7106 | JTGV | | |
| | 7107 | JTGV | | |
| | 7108 | JTGV | | |
| | 7201 | JKPV | | |
| | 7202 | JKPV | | |
| | 7203 | JKPV | | |
| | 7204 | JKPV | | |
| | 7205 | JKPV | | |
| | 7206 | JTGV | | |
| | 7207 | JTGV | | |
| | 7208 | JTGV | | |
| | 7209 | JTGV | | |
| **BUILDING H-8** | | | | |
| | 8101 | JKPA | | |
| | 8102 | JKPA | | |
| | 8103 | JKPA | | |
| | 8104 | JKPA | | |
| | 8105 | JKPA | | |
| | 8106 | JTGV | | |
| | 8107 | JTGV | | |
| | 8108 | JTGV | | |
| | 8201 | JKPV | | |
| | 8202 | JKPV | | |
| | 8203 | JKPV | | |
| | 8204 | JKPV | ✓ | |
| | 8205 | JKPV | ✓ | |
| | 8206 | JTGV | | |
| | 8207 | JTGV | | |
| | 8208 | JTGV | | |
| | 8209 | JTGV | | |
| **VILLA-9** | | | | |
| | V101 | 3VPP | | |
| | V102 | 3VPP | | |
| | V103 | 3VPP | | |
| | V104 | 3VPP | | |
| | V105 | 3VPPA | | |
| | V106 | 3VPPA | | |
| | V107 | 3VPPA | | |
| | V108 | 3VPPA | | |
| | V109 | 3VPP | | |
| | V110 | 3VPP | | |

By Beam.


บริษัท แอ็ดวานซ์ กรุ๊ป เอเชีย จำกัด
234/9 ถนนเสรีไทยแขวงคันนายาวเขตคันนายาว 10230
234/9 Seri Thai Road, Khannayao Subdistrict, Khannayao District, Thailand. Bangkok 10230
โทร 0-2704-5333 แฟกซ์ 0-2704-5353 Website : www.advancegroupasia.com


## Service Report
## รายงานการเข้าทำบริการ

วันที่ : 10/06/2024 เลขที่ :A2024-157934

เลขที่สัญญา : CT23-0011131 ชื่อผู้ว่าจ้าง : บริษัท รีสอร์ทไลฟ์ จำกัด (สาขา 00001) ผู้แจ้ง/ผู้ติดต่อ : คุณเจมส์ 076-363250

ที่อยู่ : 56/80 Moo 4 T.Rawai A.Muang จังหวัด ภูเก็ต 83130

โทรศัพท์ : 076 363 250 โทรสาร :

วันที่เข้าบริการ : 11/06/2024 เวลา : เวลาออก : ระยะสัญญา : 01/07/2023 - 30/06/2024

หมายเหตุ : กำจัด ปลวดBio.ม.ส.น.ย. 4ครั้ง/เดือน(แมลง)

| พื้นที่ทำบริการ / รายละเอียดงาน | ชนิดของแมลง | สารเคมีที่ใช้ | ผลการตรวจสอบ | หมายเหตุ |
|---|---|---|---|---|
| สเตย์ เวลบีอิ้ง แอนด์ ไลฟ์สไตล์ รีสอร์ต | | -เฟนโดน่า 10 SC 1200 | | |
| ☑ ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบมด แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | มด | -โบรมาดิโอกราด -เกมีการ 1% 5 ซอง | | |
| ☐ วางเหยื่อกำจัดหนู ระเภทออกฤทธิ์ช้า ในบริเวณรอบนอกอาคาร | หนู | -กระดานกาวสำเร็จรูป | | |
| ☐ วางกาวตามพื้นที่ที่วางเหยื่อพิษไม่ได้ วางกาวบริเวณพื้นที่ภายใน | | -พรีเบ็กซ์ 250 EC | | |
| ☐ โยนเหยื่อพิษรอบนอกอาคาร | | | | |
| ☑ ฉีดพ่นเคมีแบบครอบคลุมพื้นที่ โดยพ่นแบบฝอยละเอียด หรือพ่นหมอกควัน บริเวณภายในตัวอาคาร และพ่นแบบหมอกควันบริเวณท่อน้ำเสีย และท่อน้ำทิ้งนอกอาคาร | ยุง | | | |
| ☑ ฉีดพ่นน้ำยาเคมีภายในและรอบนอก โดยเน้นจุดที่สำรวจพบแมลงสาบ แหล่งอาหาร ,รัง , ที่หลบซ่อนและแหล่งน้ำ | แมลงสาบ | | | |

| Team | พนักงาน | หมายเหตุ |
|---|---|---|
| ทีม A | นายศิรวิชญ์ คุ้มบ้าน | -ทำบริการฉีดเคมีควบคุมปริมาณยุงตามจุดที่ยังไม่ได้ทำฉีดพ่นหมอกควัน เช่น พุ่มไม้ ท่อน้ำ สิ่งปลูกสร้างสูง<br>-โรยกาวดักจับกำจัดหนู บริเวณจุดที่มีปัญหา เช่น ท่อทอง น้ำ แต่งน้ำ ที่ซ่อนตัวและจุดที่มีปัญหาปลวก |