
PREVENTIVE MAINTENANCE
DB PANEL

ตรวจสอบและทำความสะอาดภายใน และภายนอกตู้
ด้วยการเป่า และดูดฝุ่น เช็คการคลายตัวของน็อตสกรู
ตรวจเช็ค Busbar ตรวจสอบความเที่ยงตรงค่าต่าง ๆ
เมื่อวันที่ 11 สิงหาคม 2568



PREVENTIVE MAINTENANCE
DB PANEL

ตรวจสอบและทำความสะอาดภายใน และภายนอกตู้
ด้วยการเป่า และดูดฝุ่น เช็คการคลายตัวของน็อตสกรู
ตรวจเช็ค Busbar ตรวจสอบความเที่ยงตรงค่าต่าง ๆ
เมื่อวันที่ 11 สิงหาคม 2568



PREVENTIVE MAINTENANCE
DB PANEL

ตรวจสอบและทำความสะอาดภายใน และภายนอกตู้
ด้วยการเป่า และดูดฝุ่น เช็คการคลายตัวของน็อตสกรู
ตรวจเช็ค Busbar ตรวจสอบความเที่ยงตรงค่าต่าง ๆ
เมื่อวันที่ 11 สิงหาคม 2568




PREVENTIVE MAINTENANCE
DB PANEL

ตรวจสอบและทำความสะอาดภายใน และภายนอกตู้
ด้วยการเป่า และดูดฝุ่น เช็คการคลายตัวของน็อตสกรู
ตรวจเช็ค Busbar ตรวจสอบความเที่ยงตรงค่าต่าง ๆ
เมื่อวันที่ 11 สิงหาคม 2568



PREVENTIVE MAINTENANCE
DB PANEL

ตรวจสอบและทำความสะอาดภายใน และภายนอกตู้
ด้วยการเป่า และดูดฝุ่น เช็คการคลายตัวของน็อตสกูร
ตรวจเช็ค Busbar ตรวจสอบความเที่ยงตรงค่าต่าง ๆ
เมื่อวันที่ 11 สิงหาคม 2568






PREVENTIVE MAINTENANCE
DB PANEL

ตรวจสอบและทำความสะอาดภายใน และภายนอกตู้
ด้วยการเป่า และดูดฝุ่น เช็คการคลายตัวของน็อตสกูร
ตรวจเช็ค Busbar ตรวจสอบความเที่ยงตรงค่าต่าง ๆ
เมื่อวันที่ 11 สิงหาคม 2568




PREVENTIVE MAINTENANCE
TEST CAP. BANK

ตรวจสอบสภาพของชุดคาปาซิเตอร์ หน้าสัมผัส
ตรวจวัดค่าคาปาซิเตอร์ ตามมาตราฐาน
เมื่อวันที่ 11 สิงหาคม 2568






PREVENTIVE MAINTENANCE
TEST CAP. BANK

ตรวจสอบสภาพของชุดคาปาซิเตอร์ หน้าสัมผัส
ตรวจวัดค่าคาปาซิเตอร์ ตามมาตราฐาน
เมื่อวันที่ 11 สิงหาคม 2568






PREVENTIVE MAINTENANCE
TEST CAP. BANK

ตรวจสอบสภาพของชุดคาปาซิเตอร์ หน้าสัมผัส
ตรวจวัดค่าคาปาซิเตอร์ ตามมาตราฐาน
เมื่อวันที่ 11 สิงหาคม 2568





PREVENTIVE MAINTENANCE
TEST CAP. BANK

ตรวจสอบสภาพของชุดคาปาซิเตอร์ หน้าสัมผัส
ตรวจวัดค่าคาปาซิเตอร์ ตามมาตราฐาน
เมื่อวันที่ 11 สิงหาคม 2568





PREVENTIVE MAINTENANCE
TEST CAP. BANK

ตรวจสอบสภาพของชุดคาปาซิเตอร์ หน้าสัมผัส
ตรวจวัดค่าคาปาซิเตอร์ ตามมาตราฐาน
เมื่อวันที่ 11 สิงหาคม 2568





PREVENTIVE MAINTENANCE
TEST CAP. BANK

ตรวจสอบสภาพของชุดคาปาซิเตอร์ หน้าสัมผัส
ตรวจวัดค่าคาปาซิเตอร์ ตามมาตราฐาน
เมื่อวันที่ 11 สิงหาคม 2568





PREVENTIVE MAINTENANCE
TEST CAP. BANK


ตรวจสอบสภาพของชุดคาปาซิเตอร์ หน้าสัมผัส
ตรวจวัดค่าคาปาซิเตอร์ ตามมาตราฐาน
เมื่อวันที่ 11 สิงหาคม 2568





PREVENTIVE MAINTENANCE
TEST CAP. BANK

ตรวจสอบสภาพของชุดคาปาซิเตอร์ หน้าสัมผัส
ตรวจวัดค่าคาปาซิเตอร์ ตามมาตราฐาน
เมื่อวันที่ 11 สิงหาคม 2568


PREVENTIVE MAINTENANCE
TEST CAP. BANK

ตรวจสอบสภาพของชุดคาปาซิเตอร์ หน้าสัมผัส
ตรวจวัดค่าคาปาซิเตอร์ ตามมาตราฐาน
เมื่อวันที่ 11 สิงหาคม 2568





PREVENTIVE MAINTENANCE
TEST CAP. BANK

ตรวจสอบสภาพของชุดคาปาซิเตอร์ หน้าสัมผัส
ตรวจวัดค่าคาปาซิเตอร์ ตามมาตราฐาน
เมื่อวันที่ 11 สิงหาคม 2568





PREVENTIVE MAINTENANCE
BUSDUCT

ตรวจสอบและทำความสะอาดภายนอกของ FEEDER BUSDUCT ตรวจสอบจุดต่อต่าง ๆ และกวดขันจุดต่อตามรายละเอียดแรงกวดขันโดยใช้ประแจกำหนดเอง
เมื่อวันที่ 11 สิงหาคม 2568






PREVENTIVE MAINTENANCE
BUSDUCT


ตรวจสอบและทำความสะอาดภายนอกของ FEEDER BUSDUCT ตรวจสอบจุดต่อต่าง ๆ และกวดขันจุดต่อตามรายละเอียดแรงกวดขันโดยใช้ประแจกำหนดเอง
เมื่อวันที่ 11 สิงหาคม 2568





PREVENTIVE MAINTENANCE
TEST GROUNDING SYSTEM

ตรวจวัดค่าระบบกราวด์ ต้องวัดได้ค่าไม่เกิน 5 Ω
ตรวจสอบสายตัวนำ การเชื่อมต่อ กล่องทดสอบ และจุดเชื่อมต่อ เมื่อวันที่ 11 สิงหาคม 2568







PREVENTIVE MAINTENANCE
TEST GROUNDING SYSTEM

ตรวจวัดค่าระบบกราวด์ ต้องวัดได้ค่าไม่เกิน 5 Ω
ตรวจสอบสายตัวนำ การเชื่อมต่อ กล่องทดสอบ และจุดเชื่อมต่อ เมื่อวันที่ 11 สิงหาคม 2568







PREVENTIVE MAINTENANCE
TEST GROUNDING SYSTEM

ตรวจวัดค่าระบบกราวด์ ต้องวัดได้ค่าไม่เกิน 5 Ω
ตรวจสอบสายตัวนำ การเชื่อมต่อ กล่องทดสอบ และ
จุดเชื่อมต่อ เมื่อวันที่ 11 สิงหาคม 2568







PREVENTIVE MAINTENANCE
TEST GROUNDING SYSTEM


ตรวจวัดค่าระบบกราวด์ ต้องวัดได้ค่าไม่เกิน 5 Ω
ตรวจสอบสายตัวนำ การเชื่อมต่อ กล่องทดสอบ และ
จุดเชื่อมต่อ เมื่อวันที่ 11 สิงหาคม 2568






PREVENTIVE MAINTENANCE
TEST GROUNDING SYSTEM

ตรวจวัดค่าระบบกราวด์ ต้องวัดได้ค่าไม่เกิน 5 Ω
ตรวจสอบสายตัวนำ การเชื่อมต่อ กล่องทดสอบ และ
จุดเชื่อมต่อ เมื่อวันที่ 11 สิงหาคม 2568






PREVENTIVE MAINTENANCE
TEST GROUNDING SYSTEM

ตรวจวัดค่าระบบกราวด์ ต้องวัดได้ค่าไม่เกิน 5 Ω
ตรวจสอบสายตัวนำ การเชื่อมต่อ กล่องทดสอบ และ
จุดเชื่อมต่อ เมื่อวันที่ 11 สิงหาคม 2568




PREVENTIVE MAINTENANCE
TEST ACB


ตรวจสอบชุด Unit Trip สามารถทำงานตามฟังชั่น
หรือไม่ ตรวจวัดค่ากลไก ทาง Mechanic ตรวจ
หน้าสัมผัส, รางดับอาร์ค เมื่อวันที่ 11 สิงหาคม 2568



PREVENTIVE MAINTENANCE
TEST ACB

ตรวจสอบชุด Unit Trip สามารถทำงานตามฟังชั่น
หรือไม่ ตรวจวัดค่ากลไก ทาง Mechanic ตรวจ
หน้าสัมผัส, รางดับอาร์ค เมื่อวันที่ 11 สิงหาคม 2568



PREVENTIVE MAINTENANCE
TEST ACB

ตรวจสอบชุด Unit Trip สามารถทำงานตามฟังชั่น
หรือไม่ ตรวจวัดค่ากลไก ทาง Mechanic ตรวจ
หน้าสัมผัส, รางดับอาร์ค เมื่อวันที่ 11 สิงหาคม 2568






PREVENTIVE MAINTENANCE
TEST ACB

ตรวจสอบชุด Unit Trip สามารถทำงานตามฟังชั่น
หรือไม่ ตรวจวัดค่ากลไก ทาง Mechanic ตรวจ
หน้าสัมผัส, รางดับอาร์ค เมื่อวันที่ 11 สิงหาคม 2568






PREVENTIVE MAINTENANCE
TEST ACB

ตรวจสอบชุด Unit Trip สามารถทำงานตามฟังชั่น
หรือไม่ ตรวจวัดค่ากลไก ทาง Mechanic ตรวจ
หน้าสัมผัส, รางดับอาร์ค เมื่อวันที่ 11 สิงหาคม 2568



PREVENTIVE MAINTENANCE
TEST ACB

ตรวจสอบชุด Unit Trip สามารถทำงานตามฟังชั่น
หรือไม่ ตรวจวัดค่ากลไก ทาง Mechanic ตรวจ
หน้าสัมผัส, รางดับอาร์ค เมื่อวันที่ 11 สิงหาคม 2568



PREVENTIVE MAINTENANCE
TEST ACB

ตรวจสอบชุด Unit Trip สามารถทำงานตามฟังชั่น
หรือไม่ ตรวจวัดค่ากลไก ทาง Mechanic ตรวจ
หน้าสัมผัส, รางดับอาร์ค เมื่อวันที่ 11 สิงหาคม 2568



THANK YOU



WITH COMPLETEMENT BY:
N.R.C. INTERNATIONAL CO., LTD.
TEL. 02-916-5472
MOBILE : 081-838-4824
E-MAIL: nrc_inter@hotmail.com

NTN ELECTRICAL SYSTEM CO.,LTD.

99/1105 Rat Phattana 22 Sapan Sung, Bangkok 10240 Tel:02-003-0055,081-922-7952

INSPECTION REPORT

ชื่อลูกค้า DelmonSiam Limited	สัญญาเลขที่: NTN26GEN04024 Dated 25/06/26
ที่อยู่: 189 Sukhumvit Rd., Kwang Klongtoey Nua, Khet Wattana Bkk. 10110	สถานที่ติดตั้ง: Sukhumvit 13

Gen. model:C1250DSA	S/N:700127	Radiator S/N: -	☐ Pre-delivery
Alternator model:	S/N: -	HOUR: 95.3	☐ Commissioning
Engine model:KTA-38-G9	S/N:25312512	DATE: 25/06/2026 1st/6	☑ Preventive maintenance

Item	Description	Check	Remark
1	ระบบหล่อเย็น: (Cooling System)		Generator No. 2
1.1	ตรวจเช็ค ระดับน้ำในหม้อน้ำ : (Top up), ตรวจเช็คสภาพของฝาหม้อน้ำ	√	
1.2	ตรวจเช็คสภาพของ Belt Tension, Thermostat Housing	√	
1.3	ตรวจเช็คสภาพของ Radiator, Water pump, การรั่วซึมของหม้อน้ำ, ท่อยาง, ปั๊มน้ำ	√	
2	ระบบหล่อลื่น : (Lubrication System)		
2.1	ตรวจเช็คระดับน้ำมันหล่อลื่นจาก Dipstick (H:☑ / M:☐ / L:☐)	√	
2.2	ตรวจเช็คสภาพของ Oil Filter และ การรั่วซึมของน้ำมันหล่อลื่นตามจุดต่าง ๆ	√	
2.3	ตรวจเช็คสภาพของ Breather Pipe, Oil Sampling Point, Filler Cap	√	
3	ระบบน้ำมันเชื้อเพลิง: (Fuel System)		
3.1	ตรวจเช็คระดับน้ำมันเชื้อเพลิงในถัง (F:☑ / M:☐ /E:☐)	√	
3.2	ตรวจเช็คสภาพของ Primary Fuel Filter และ การรั่วซึมของน้ำมันเชื้อเพลิง	√	
3.3	ตรวจเช็คสภาพของ Secondary Fuel Filter และ การรั่วซึมของน้ำมันเชื้อเพลิง	√	
3.4	ตรวจเช็คสภาพของ Fuel Injection Pump, Relief Valve, Fuel Lift Pump,	√	
3.5	ตรวจเช็คสภาพของ Governor, Throttle Lever, Governor Weights	√	
4	ระบบอากาศ: (Air System & Exhaust System)		
4.1	ตรวจเช็คสภาพของ Air Filter Component	√	
4.2	ตรวจเช็คสภาพของ Turbocharger, Inlet Manifold, Exhaust Manifold	√	
5	ระบบไฟฟ้า: (Electric System)		
5.1	ตรวจสภาพของ สายไฟ, จุดต่อสายไฟตามจุดต่าง ๆ	√	
5.2	DC: ตรวจเช็คสภาพของแบตเตอรี่, ขั้วแบตเตอรี่, สายไฟ และ สาย Ground	√	
5.3	DC: ตรวจเช็คระดับน้ำกรดในแบตเตอรี่ ระดับ (Top up) (H:☐ / M:☐ / L:☐)	√	
5.4	AC: ตรวจเช็คสภาพและการทำงานของ Circuit breaker	√	
6	Control Panel Functional Operation:		
6.1	ทดสอบหลอดไฟ LED แสดงสัญญาณเตือน: (Lamp Test / Reset)	√	
6.2	เกจวัดความดันน้ำมันเครื่อง (PSI) (708 kPa BAR)	√	
6.3	เกจวัดอุณหภูมิน้ำหล่อเย็น (43. °C) (- °F)		
6.4	เกจวัด ความเร็วรอบ (1498 rpm) (ที่ความถี่ 50 Hz)	√	
6.5	เกจวัด Battery Charging (DC 25.4 Volt)		
6.6	การทำงานของสัญญาณเตือนสภาวะบกพร่องในส่วนต่าง ๆ	√	
6.7	การทำงานของปุ่ม Emergency Stop Push:	√	
6.8	การทำงานของสวิทช์ AC Volt & Amp Selector:	√	
6.9	การทำงานของสวิทช์ Start แบบ Manual (Run), แบบ Auto และ: Stop	√	

7	การทดสอบเครื่องกำเนิดไฟฟ้า	ค่าแรงดันไฟฟ้า : (Volt)						ค่ากระแสไฟฟ้า : (Amp)		
	ตำแหน่งที่ทำการวัด	L1–N	L2–N	L3–N	L1–L2	L2–L3	L3–L1	L 1	L 2	L 3
7.1	สภาวะไม่มีโหลด : (No Load)	230	230	230	400	400	400			
7.2	สภาวะมีโหลด : (Load)									

ลงชื่อ: [redacted] (ลำดับที่การ)

( ) วันที่ : 25 / 06 /2026

NTN ELECTRICAL SYSTEM CO.,LTD.

99/1105 Rat Phattana 22 Sapan Sung, Bangkok 10240 Tel:02-003-0055,081-922-7952

INSPECTION REPORT

ชื่อลูกค้า DelmonSiam Limited	สัญญาเลขที่: NTN26GEN04024 Dated 24/04/26
ที่อยู่: 189 Sukhumvit Rd., Kwang Klongtoey Nua, Khet Wattana Bkk. 10110	สถานที่ติดตั้ง: Sukhumvit 13

Gen. model:C1250DSA	S/N:700126	Radiator S/N: -	☐ Pre-delivery
Alternator model:	S/N: -	HOUR: 91.4	☐ Commissioning
Engine model:KTA-38-G9	S/N:25318513	DATE: 25/06/2026 1st/6	☑ Preventive maintenance

Item	Description	Check	Remark
1	ระบบหล่อเย็น: (Cooling System)		Generator No. 1
1.1	ตรวจเช็ค ระดับน้ำในหม้อน้ำ : (Top up), ตรวจเช็คสภาพของฝาหม้อน้ำ	√	
1.2	ตรวจเช็คสภาพของ Belt Tension, Thermostat Housing	√	
1.3	ตรวจเช็คสภาพของ Radiator, Water pump, การรั่วซึมของหม้อน้ำ, ท่อยาง, ปั๊มน้ำ	√	
2	ระบบหล่อลื่น : (Lubrication System)		
2.1	ตรวจเช็คระดับน้ำมันหล่อลื่นจาก Dipstick (H:☑ / M:☐ / L:☐)	√	
2.2	ตรวจเช็คสภาพของ Oil Filter และ การรั่วซึมของน้ำมันหล่อลื่นตามจุดต่าง ๆ	√	
2.3	ตรวจเช็คสภาพของ Breather Pipe, Oil Sampling Point, Filler Cap	√	
3	ระบบน้ำมันเชื้อเพลิง: (Fuel System)		
3.1	ตรวจเช็คระดับน้ำมันเชื้อเพลิงในถัง (F:☑ / M:☐ /E:☐)	√	
3.2	ตรวจเช็คสภาพของ Primary Fuel Filter และ การรั่วซึมของน้ำมันเชื้อเพลิง	√	
3.3	ตรวจเช็คสภาพของ Secondary Fuel Filter และ การรั่วซึมของน้ำมันเชื้อเพลิง	√	
3.4	ตรวจเช็คสภาพของ Fuel Injection Pump, Relief Valve, Fuel Lift Pump,	√	
3.5	ตรวจเช็คสภาพของ Governor, Throttle Lever, Governor Weights	√	
4	ระบบอากาศ: (Air System & Exhaust System)		
4.1	ตรวจเช็คสภาพของ Air Filter Component	√	
4.2	ตรวจเช็คสภาพของ Turbocharger, Inlet Manifold, Exhaust Manifold	√	
5	ระบบไฟฟ้า: (Electric System)		
5.1	ตรวจสภาพของ สายไฟ, จุดต่อสายไฟตามจุดต่าง ๆ	√	
5.2	DC: ตรวจเช็คสภาพของแบตเตอรี่, ขั้วแบตเตอรี่, สายไฟ และ สาย Ground	√	
5.3	DC: ตรวจเช็คระดับน้ำกรดในแบตเตอรี่ ระดับ (Top up) (H:☐ / M:☐ / L:☐)	√	
5.4	AC: ตรวจเช็คสภาพและการทำงานของ Circuit breaker	√	
6	Control Panel Functional Operation:		
6.1	ทดสอบหลอดไฟ LED แสดงสัญญาณเตือน: (Lamp Test / Reset)	√	
6.2	เกจวัดความดันน้ำมันเครื่อง (103 PSI) (BAR)	√	
6.3	เกจวัดอุณหภูมิน้ำหล่อเย็น (44 °C) (- °F)		
6.4	เกจวัด ความเร็วรอบ (1500 rpm) (ที่ความถี่ 50 Hz)	√	
6.5	เกจวัด Battery Charging (DC 29.9 Volt)		
6.6	การทำงานของสัญญาณเตือนสภาวะบกพร่องในส่วนต่าง ๆ	√	
6.7	การทำงานของปุ่ม Emergency Stop Push:	√	
6.8	การทำงานของสวิทช์ AC Volt & Amp Selector:	√	
6.9	การทำงานของสวิทช์ Start แบบ Manual (Run), แบบ Auto และ: Stop	√	

7	การทดสอบเครื่องกำเนิดไฟฟ้า	ค่าแรงดันไฟฟ้า : (Volt)						ค่ากระแสไฟฟ้า : (Amp)		
	ตำแหน่งที่ทำการวัด	L1–N	L2–N	L3–N	L1–L2	L2–L3	L3–L1	L 1	L 2	L 3
7.1	สภาวะไม่มีโหลด : (No Load)	230	230	230	400	400	400			
7.2	สภาวะมีโหลด : (Load)									

ลงชื่อ: [redacted] (ลำดับที่การ)

( ) วันที่ : 25 / 06 /2026

PRO.FIRE ENGINEERING LIMITED PARTNERSHIP ห้างหุ้นส่วนจำกัด โปร.ไฟร์ เอ็นจิเนียริ่ง
29/1596 ซ.3/5 ถ.รังสิต-นครนายก ต.คลองหก อ.คลองหลวง จ.ปทุมธานี 12120
โทร(02) 569-7895 โทรสาร(02)832-7891 E-mail: profire.engineer@gmail.com

DATA TEST

JOCKEY PUMP

Project Name : โรงแรม เดอ/เทล	Service date : 26/3/69
Customer Name :	Time :
Address :	Technician : ศักรินทร์ LZ
Attention :	

PUMP		MOTOR		CONTROLLER :	
Pump Brand:		Motor Brand:		Control Brand :	
Model:		Model:		Model :	
S/N:		S/N:		S/N :	
Pump speed	RPM	Frame:	Type:	☐ NFPA20 ☐ UL LISTED ☐ FM APPROVED	
Flow Rate	GPM	Horse Power	HP	Power Supply 380 V 3 PH 50 HZ	
TDH	PSI	Engine Speed	RPM	Type Start ☑ D.O.L ☐ Star-Delta	
Max. Working Pressure	PSI	Power Supply	V PH HZ		
		Full Load	A		

Item	PUMP	Y	N	N/A	Item	DATA TEST	
1	Inboard ball bearing	√			1	Suction Pressure 0	PSI
2	Outboard ball bearing	√			2	Discharge Pressure 130	PSI
3	Mechanical seals (front & back)	√			3	Water Flow Rate -	GPM
4	Packing seal (front & back)			√	4	Relief Valve Seting 150	PSI
5	Lubrication			√	5	Pump Speed -	RPM
6	Checking Vibration	√			6	Voltage (R-S,S-T,T-R) 394 - 395 - 39	Volt
7	Suction pressure 0 PSI Discharge pressure 130 PSI	√			7	Amperage (R-S-T) 15.6 - 16.1 - 16.9	AMP
Item	MOTOR TEST	Y	N	N/A	8	Pressure cut-in 100	PSI
1	Inboard ball bearing	√			9	Pressure cut-out 150	PSI
2	Outboard ball bearing	√					
3	Lubrication			√			
4	Running ampsenge R=16.6 A, S=16.1 A, T=16.9 A	√					
Item	CONTROLLER TEST	Y	N	N/A			
1	Manual Start-Stop	√			Remark : Auto / manual ปกติ		
2	Automatic Start-Stop	√					
3	Power Supply condition 380 V	√					
4	Magnetic Contractor Start ☑ D.O.L ☐ Star - Delta	√					
5	Overload Relay 39 A , Set At 26 A	√					
6	Timer Relay Set 10 SEC	√					
7	Pressure Switch Test Start Set 120 PSI, Stop Set 150 P	√					

[redacted]

Date : 26/3/69 Date : 26/3/69 Date :

PRO.FIRE ENGINEERING LIMITED PARTNERSHIP ห้างหุ้นส่วนจำกัด โปร.ไฟร์ เอ็นจิเนียริ่ง
29/1596 ซ.3/5 ถ.รังสิต-นครนายก ต.คลองหก อ.คลองหลวง จ.ปทุมธานี 12120
โทร(02) 569-7895 โทรสาร(02)832-7891 E-mail: profire.engineer@gmail.com

DATA TEST

DIESEL ENGINE FIRE PUMP

Project Name : โรงแรม โรงแรม [illegible]	Service date : 26/3/69
Customer Name :	Time :
Address :	Technician : ศักรินทร์ High zone
Attention :	

PUMP		ENGINE		CONTROLLER :	
Pump Brand:		Engine Brand:		Control Brand :	
Model:		Model:		Model :	
S/N:		S/N:		S/N :	
☐ NFPA20 ☐ UL LISTED ☐ FM APPROVED		☐ NFPA20 ☐ UL LISTED ☐ FM APPROVED		☐ NFPA20 ☐ UL LISTED ☐ FM APPROVED	
Pump speed	RPM	Power Rating	HP	Power Supply 220 V 1 PH 50HZ	
Flow Rate	GPM	Engine Speed	RPM		
TDH	PSI	Power Supply	12 VDC		
Max. Working Pressure	PSI				

Item	PUMP	Y	N	N/A	Item	CONTROLLER TEST	Y	N	N/A
1	Inboard ball bearing	√			1	Checking Starting Battery # 1			
2	Outboard ball bearing	√			2	Checking Starting Battery # 2			
3	Packing seal (front & back)	√			3	Automatic Start by Draining water system			
4	Suction pressure +10 psi Discharge pressure 260 Psi	√			4	Manual Stop by Engine shut Down			
Item	ENGINE TEST	Y	N	N/A	5	Battery charger # 1			
1	Manual Crank on Battery # 1	√			6	Battery Charger # 2			
2	Manual Crank on Battery # 2	√			7	Test Charger Malfunction 12 VDC			
3	Low oil Pressure 60 PSI	√			8	Automatic Weekly Starting Test			√
4	Fuel Pressure - PSI			√		Start Day Time Stop Day Time			√
5	Water Temperature 85 C.	√			9	Water Temperature 85 C.			
6	Service Hour Meter 20.4 HR	√			10	Low oil Pressure 60 PSI			
7	Tachometer 2300 RPM	√			11	Engine over speed			
8	Cooling Loop 10 pos PSI	√			12	Failed to Start			
					13	Timer Relay (Set Manual Stop min.)			
					14	Pressure Switch Test (Start Set 150 PSI.) (Stop Set Manual Stop)			

Item	DATA TEST		Remark :
1	Discharge Pressure 260	PSI	Auto / manual ปกติ
2	Suction Pressure + 10	PSI	= เปลี่ยนหัว อัตราธี ใช้ได้ไม่เกิน 2 ปี
3	Water Flow Rate -	GPM	
4	Pump Speed 2300	RPM	
5	Relief Valve Setting 260	PSI	
6	Pressure cut-in 160	PSI	
7	Pressure cut-out Manual Stop	PSI	

[redacted]

Date : 26/3/69 Date : 26/3/69 Date :

PRO.FIRE ENGINEERING LIMITED PARTNERSHIP ห้างหุ้นส่วนจำกัด โปร.ไฟร์ เอ็นจิเนียริ่ง
29/1596 ซ.3/5 ถ.รังสิต-นครนายก ต.คลองสาม อ.คลองหลวง จ.ปทุมธานี 12120
โทร(02) 569-7895 โทรสาร(02)832-7891 E-mail: profire.engineer@gmail.com

DATA TEST
DIESEL ENGINE FIRE PUMP

Project Name :	โรงแรม โซฟิเทล สุขุมวิท	Service date :	26/3/69
Customer Name :		Time :	
Address :		Technician :	จักรพันธ์ LZ
Attention :			

PUMP	ENGINE	CONTROLLER :
Pump Brand:	Engine Brand:	Control Brand :
Model:	Model:	Model :
S/N:	S/N:	S/N :
☐ NFPA20 ☐ UL LISTED ☐ FM APPROVED	☐ NFPA20 ☐ UL LISTED ☐ FM APPROVED	☐ NFPA20 ☐ UL LISTED ☐ FM APPROVED
Pump speed RPM	Power Rating HP	Power Supply 380 V 1 PH 50 HZ
Flow Rate GPM	Engine Speed RPM	
TDH PSI	Power Supply 12 VDC	
Max. Working Pressure PSI		

Item	PUMP	Y	N	N/A
1	Inboard ball bearing	✓		
2	Outboard ball bearing	✓		
3	Packing seal (front & back)	✓		
4	Suction pressure 0 Psi Discharge pressure 140 Psi	✓		

Item	ENGINE TEST	Y	N	N/A
1	Manual Crank on Battery # 1	✓		
2	Manual Crank on Battery # 2	✓		
3	Low oil Pressure 70 PSI	✓		
4	Fuel Pressure - PSI			✓
5	Water Temperature 80 C.	✓		
6	Service Hour Meter 20.1 2070 HR	✓		
7	Tachometer 2100 RPM	✓		
8	Cooling Loop 80 PSI	✓		

Item	CONTROLLER TEST	Y	N	N/A
1	Checking Starting Battery # 1	✓		
2	Checking Starting Battery # 2	✓		
3	Automatic Start by Draining water system	✓		
4	Manual Stop by Engine shut Down	✓		
5	Battery charger # 1	✓		
6	Battery Charger # 2	✓		
7	Test Charger Malfunction 12 VDC			✓
8	Automatic Weekly Starting Test			✓
	Start Day Time Stop Day Time			✓
9	Water Temperature 90 C.	✓		
10	Low oil Pressure 70 PSI	✓		
11	Engine over speed	✓		
12	Failed to Start	✓		
13	Timer Relay (Set Manual Stop min.)	✓		
14	Pressure Switch Test (Start Set 80 PSI.) (Stop Set Manual Stop)	✓		

Item	DATA TEST	
1	Discharge Pressure 180	PSI
2	Suction Pressure 0	PSI
3	Water Flow Rate -	GPM
4	Pump Speed 2350	RPM
5	Relief Valve Setting 180	PSI
6	Pressure cut-in 80	PSI
7	Pressure cut-out Manual Stop	PSI

Remark : Auto/manual ปกติ
-เปลี่ยนหัวฉีดทดแทน ปีที่ใช้ 4 ปี/ 2 หัว

[redacted]

Date : 23/6/69 Date : 26/3/69 Date :

PRO.FIRE ENGINEERING LIMITED PARTNERSHIP ห้างหุ้นส่วนจำกัด โปร.ไฟร์ เอ็นจิเนียริ่ง
29/1596 ซ.3/5 ถ.รังสิต-นครนายก ต.คลองสาม อ.คลองหลวง จ.ปทุมธานี 12120
โทร(02) 569-7895 โทรสาร(02)832-7891 E-mail: profire.engineer@gmail.com

DATA TEST
JOCKEY PUMP

Project Name :	โรงแรม โซฟิเทล สุขุมวิท	Service date :	26/3/69
Customer Name :		Time :	
Address :		Technician :	จักรพันธ์ HZ
Attention :			

PUMP	MOTOR	CONTROLLER :
Pump Brand:	Motor Brand:	Control Brand :
Model:	Model:	Model :
S/N:	S/N:	S/N :
Pump speed RPM	Frame: Type:	☐ NFPA20 ☐ UL LISTED ☐ FM APPROVED
Flow Rate GPM	Horse Power HP	Power Supply 380 V 3 PH 50 HZ
TDH PSI	Engine Speed RPM	Type Start ☑ D.O.L ☐ Star-Delta
Max. Working Pressure PSI	Power Supply 380 V 3 PH 50 HZ	
	Full Load A	

Item	PUMP	Y	N	N/A
1	Inboard ball bearing	✓		
2	Outboard ball bearing	✓		
3	Mechanical seals (front & back)	✓		
4	Packing seal (front & back)			✓
5	Lubrication			✓
6	Checking Vibration	✓		
7	Suction pressure 0 PSI Discharge pressure 205 PSI	✓		

Item	MOTOR TEST	Y	N	N/A
1	Inboard ball bearing	✓		
2	Outboard ball bearing	✓		
3	Lubrication			✓
4	Running amperage R-21 A, S-22 A, T-21 A			

Item	CONTROLLER TEST	Y	N	N/A
1	Manual Start-Stop	✓		
2	Automatic Start-Stop	✓		
3	Power Supply condition 380 V	✓		
4	Magnetic Contractor Start ☑ D.O.L. ☐ Star - Delta	✓		
5	Overload Relay 42 A , Set At 33 A	✓		
6	Timer Relay Set 40 SEC	✓		
7	Pressure Switch Test Start Set 185 PSI, Stop Set 205 PSI	✓		

Item	DATA TEST	
1	Suction Pressure 0	PSI
2	Discharge Pressure 205	PSI
3	Water Flow Rate -	GPM
4	Relief Valve Seting 205	PSI
5	Pump Speed -	RPM
6	Voltage (R-S,S-T,T-R) 395 378 380	Volt
7	Amperage (R-S-T) 21 - 22 - 21	AMP
8	Pressure cut-in 185	PSI
9	Pressure cut-out 205	PSI

Remark : Auto/Manual ปกติ

[redacted]

Date : 26/3/69 Date : 26/3/69 Date :

SOFITEL HOTELS & RESORTS BANGKOK SUKHUMVIT

WEEKLY FIRE PUMP WARM - UP LOG SHEET
FP1 DATE 15/1/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ✓ Low ☐ ( ) add ..... lts.
- Diesel fuel tank level (750 - 800 Ltrs.) 1000	Full level 810 ltrs. Add ltrs.
- Clean air filter	( ) clean ( ) dirty, cleaned
- Record hours meter reading	17.7 hrs.
BATTERY	
- Check current charging to battery	( ) chagre ( ) No charge
- Check battery terminals	( ) tight, clean ( ) loose, tightened
- Check distilled water level	Full ☐ Low ☐
- Record SP.G. level	( ) red ( ) yellow ( ) green
GENERAL	
- Water in serving tank	Full ☐ Low ☐
- Clean control panel	( ) clean ( ) dirty, cleaned
- Check pressure recorder in system	140 psi
- Check valves for free travel	( ) normal ( ) abnormal
- Suction pressure	3 psi
OPERATIONAL CHECK	
ENGINE	Started PS Running (____ mins)
- Check lubricating oil pressure	65 bar bar
- Cooling water temp (50°C - 70°C)	85 °C °C
- Engine speed	1900 rpm rpm
- Check current charging to battery	27/66 amp amp
- Check for leaks around the engine	( ) Normal ( ) leak
- Noises	( ) Normal ( ) abnormal
- Vibration	( ) Normal ( ) abnormal
- Smoke	( ) Normal ( ) abnormal
PUMP AND PIPING	
- Check line pressure	170 psi
- Pressure relief valve maintain pressure at	psi
- Check for leaks around the pump & piping	( ) Normal ( ) leak
- Check mechanical seal / packing for leak	( ) Normal ( ) leak
- Examine for abnormal noise, heat, vibration	( ) Normal ( ) abnormal

Time start 13.50 Time stop 14.25 Total mins
Supervisor' s comments เครื่องทำงานปกติดี

[redacted]

18.1 H / 800 L

SOFITEL HOTELS & RESORTS BANGKOK SUKHUMVIT

WEEKLY FIRE PUMP WARM - UP LOG SHEET
FP2 DATE 15/1/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ✓ Low ☐ ( ) add ..... lts.
- Diesel fuel tank level (750 - 800 Ltrs.) 1750	Full level 1390 ltrs. Add ltrs.
- Clean air filter	( ) clean ( ) dirty, cleaned
- Record hours meter reading	17.9 hrs.
BATTERY	
- Check current charging to battery	( ) chagre ( ) No charge
- Check battery terminals	( ) tight, clean ( ) loose, tightened
- Check distilled water level	Full ☐ Low ☐
- Record SP.G. level	( ) red ( ) yellow ( ) green
GENERAL	
- Water in serving tank	Full ✓ Low ☐
- Clean control panel	( ) clean ( ) dirty, cleaned
- Check pressure recorder in system	200 psi
- Check valves for free travel	( ) normal ( ) abnormal
- Suction pressure	3 psi
OPERATIONAL CHECK	
ENGINE	Started PS Running (____ mins)
- Check lubricating oil pressure	60 bar bar
- Cooling water temp (50°C - 70°C)	83 °C °C
- Engine speed	2400 rpm rpm
- Check current charging to battery	0.35/0.49 amp amp
- Check for leaks around the engine	( ) Normal ( ) leak
- Noises	( ) Normal ( ) abnormal
- Vibration	( ) Normal ( ) abnormal
- Smoke	( ) Normal ( ) abnormal
PUMP AND PIPING	
- Check line pressure	260 psi
- Pressure relief valve maintain pressure at	- psi
- Check for leaks around the pump & piping	( ) Normal ( ) leak
- Check mechanical seal / packing for leak	( ) Normal ( ) leak
- Examine for abnormal noise, heat, vibration	( ) Normal ( ) abnormal

Time start 13.55 Time stop 14.25 Total 30 mins
Supervisor' s comments เครื่องทำงานปกติดี

[redacted]

18.4H/1380L

SOFITEL
HOTELS & RESORTS
BANGKOK SUKHUMVIT

WEEKLY FIRE PUMP WARM - UP LOG SHEET

FP 1 DATE 29/01/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full [/] Low [ ] ( ) add ..... lts.
- Diesel fuel tank level (750 - 800 Ltrs.) 1000	Full level 800 ltrs. Add _____ ltrs.
- Clean air filter	(/) clean ( ) dirty, cleaned
- Record hours meter reading	18.4 hrs.
BATTERY	
- Check current charging to battery	(/) chagre ( ) No charge
- Check battery terminals	(/) tight, clean ( ) loose, tightened
- Check distilled water level	Full [/] Low [ ]
- Record SP.G. level	( ) red ( ) yellow (/) green
GENERAL	
- Water in serving tank	Full [/] Low [ ]
- Clean control panel	(/) clean ( ) dirty, cleaned
- Check pressure recorder in system	150 psi
- Check valves for free travel	(/) normal ( ) abnormal _____
- Suction pressure	3 psi
OPERATIONAL CHECK	
ENGINE	Started (Psi) Running (____ mins)
- Check lubricating oil pressure	65 bar _____ bar
- Cooling water temp (50°C - 70°C)	85 °C _____ °C
- Engine speed	2300 rpm _____ rpm
- Check current charging to battery	9.6 / 6.5 amp _____ amp
- Check for leaks around the engine	(/) Normal ( ) leak
- Noises	(/) Normal ( ) abnormal _____
- Vibration	(/) Normal ( ) abnormal _____
- Smoke	(/) Normal ( ) abnormal _____
PUMP AND PIPING	
- Check line pressure	170 psi
- Pressure relief valve maintain pressure at	_____ psi
- Check for leaks around the pump & piping	(/) Normal ( ) leak _____
- Check mechanical seal / packing for leak	(/) Normal ( ) leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal ( ) abnormal _____

Time start 13.26 Time stop 13.56 Total 30 mins

Supervisor' s comments

เครื่องทำงานปกติ

[redacted]

SOFITEL
HOTELS & RESORTS
BANGKOK SUKHUMVIT

WEEKLY FIRE PUMP WARM - UP LOG SHEET

FP 2 DATE 29/01/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full [/] Low [ ] ( ) add ..... lts.
- Diesel fuel tank level (750 - 800 Ltrs.) 1750	Full level 1350 ltrs. Add _____ ltrs.
- Clean air filter	(/) clean ( ) dirty, cleaned
- Record hours meter reading	18.1 hrs.
BATTERY	
- Check current charging to battery	(/) chagre ( ) No charge
- Check battery terminals	(/) tight, clean ( ) loose, tightened
- Check distilled water level	Full [/] Low [ ]
- Record SP.G. level	( ) red ( ) yellow (/) green
GENERAL	
- Water in serving tank	Full [/] Low [ ]
- Clean control panel	(/) clean ( ) dirty, cleaned
- Check pressure recorder in system	200 psi
- Check valves for free travel	(/) normal ( ) abnormal _____
- Suction pressure	3 psi
OPERATIONAL CHECK	
ENGINE	Started (Psi) Running (____ mins)
- Check lubricating oil pressure	65 bar _____ bar
- Cooling water temp (50°C - 70°C)	84 °C _____ °C
- Engine speed	2300 rpm _____ rpm
- Check current charging to battery	0.37 / 0.5 amp _____ amp
- Check for leaks around the engine	(/) Normal ( ) leak
- Noises	(/) Normal ( ) abnormal _____
- Vibration	(/) Normal ( ) abnormal _____
- Smoke	(/) Normal ( ) abnormal _____
PUMP AND PIPING	
- Check line pressure	260 psi
- Pressure relief valve maintain pressure at	_____ psi
- Check for leaks around the pump & piping	(/) Normal ( ) leak _____
- Check mechanical seal / packing for leak	(/) Normal ( ) leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal ( ) abnormal _____

Time start 13.29 Time stop 13.59 Total 30 mins

Supervisor' s comments

เครื่องทำงานปกติ

[redacted]

SOFITEL
HOTELS & RESORTS
BANGKOK SUKHUMVIT

WEEKLY FIRE PUMP WARM - UP LOG SHEET

FP 1 DATE 12/2/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full [/] Low [ ] ( ) add ..... lts.
- Diesel fuel tank level (750 - 800 Ltrs.)	Full level 800 ltrs. Add _____ ltrs.
- Clean air filter	(/) clean ( ) dirty, cleaned
- Record hours meter reading	18.6 hrs. ทำ 19.1
BATTERY	
- Check current charging to battery	(/) chagre ( ) No charge
- Check battery terminals	(/) tight, clean ( ) loose, tightened
- Check distilled water level	Full [/] Low [ ]
- Record SP.G. level	( ) red ( ) yellow (/) green
GENERAL	
- Water in serving tank	Full [/] Low [ ]
- Clean control panel	(/) clean ( ) dirty, cleaned
- Check pressure recorder in system	150 psi
- Check valves for free travel	( ) normal ( ) abnormal _____
- Suction pressure	2 psi
OPERATIONAL CHECK	
ENGINE	Started Running (____ mins)
- Check lubricating oil pressure	55 bar 55 bar
- Cooling water temp (50°C - 70°C)	85 °C 85 °C
- Engine speed	2250 rpm 2250 rpm
- Check current charging to battery	6.1 / 7.8 amp 5.8 / 7.8 amp
- Check for leaks around the engine	(/) Normal ( ) leak
- Noises	(/) Normal ( ) abnormal _____
- Vibration	(/) Normal ( ) abnormal _____
- Smoke	(/) Normal ( ) abnormal _____
PUMP AND PIPING	
- Check line pressure	180 psi
- Pressure relief valve maintain pressure at	80 psi
- Check for leaks around the pump & piping	(/) Normal ( ) leak _____
- Check mechanical seal / packing for leak	(/) Normal ( ) leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal ( ) abnormal _____

Time start 13.27 Time stop 13.56 Total 30 mins

Supervisor' s comments

Normal

[redacted]

SOFITEL
HOTELS & RESORTS
BANGKOK SUKHUMVIT

WEEKLY FIRE PUMP WARM - UP LOG SHEET

FP 2 DATE 12/2/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full [/] Low [ ] ( ) add ..... lts.
- Diesel fuel tank level (750 - 800 Ltrs.)	Full level 1300 ltrs. Add _____ ltrs.
- Clean air filter	(/) clean ( ) dirty, cleaned
- Record hours meter reading	18.9 hrs. ทำ 19.4
BATTERY	
- Check current charging to battery	(/) chagre ( ) No charge
- Check battery terminals	(/) tight, clean ( ) loose, tightened
- Check distilled water level	Full [/] Low [ ]
- Record SP.G. level	( ) red ( ) yellow (/) green
GENERAL	
- Water in serving tank	Full [/] Low [ ]
- Clean control panel	(/) clean ( ) dirty, cleaned
- Check pressure recorder in system	187 psi
- Check valves for free travel	(/) normal ( ) abnormal _____
- Suction pressure	4 psi
OPERATIONAL CHECK	
ENGINE	Started Running (____ mins)
- Check lubricating oil pressure	60 bar 50 bar
- Cooling water temp (50°C - 70°C)	85 °C 85 °C
- Engine speed	2300 rpm 2200 rpm
- Check current charging to battery	1.2 / 1.6 amp 1.1 / 1.4 amp
- Check for leaks around the engine	( ) Normal ( ) leak
- Noises	( ) Normal ( ) abnormal _____
- Vibration	( ) Normal ( ) abnormal _____
- Smoke	( ) Normal ( ) abnormal _____
PUMP AND PIPING	
- Check line pressure	260 psi
- Pressure relief valve maintain pressure at	_____ psi
- Check for leaks around the pump & piping	( ) Normal ( ) leak _____
- Check mechanical seal / packing for leak	( ) Normal ( ) leak _____
- Examine for abnormal noise, heat, vibration	( ) Normal ( ) abnormal _____

Time start 13.27 Time stop 13.56 Total 30 mins

Supervisor' s comments

Normal

[redacted]

SOFITEL
HOTELS & RESORTS
BANGKOK SUKHUMVIT

WEEKLY FIRE PUMP WARM - UP LOG SHEET

FP 2 DATE 26/2/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full [✓] Low [ ] ( ) add ..... lts.
- Diesel fuel tank level (750 - 800 Ltrs.)	Full level 1300 ltrs. Add _____ ltrs.
- Clean air filter	(✓) clean ( ) dirty, cleaned
- Record hours meter reading	19.4 hrs.
BATTERY	
- Check current charging to battery	(✓) chagre ( ) No charge
- Check battery terminals	(✓) tight, clean ( ) loose, tightened
- Check distilled water level	Full [✓] Low [ ]
- Record SP.G. level	( ) red ( ) yellow (✓) green
GENERAL	
- Water in serving tank	Full [✓] Low [ ]
- Clean control panel	(✓) clean ( ) dirty, cleaned
- Check pressure recorder in system	187 psi
- Check valves for free travel	(✓) normal 4 ( ) abnormal_____
- Suction pressure	_____ psi
OPERATIONAL CHECK	
ENGINE	Started / Running (____ mins)
- Check lubricating oil pressure	69 bar / 55 bar
- Cooling water temp (50°C - 70°C)	77 °C / 85 °C
- Engine speed	2300 rpm / 2300 rpm
- Check current charging to battery	2.43/2.11 amp / 1.53/1.66 amp
- Check for leaks around the engine	(✓) Normal ( ) leak
- Noises	(✓) Normal ( ) abnormal _____
- Vibration	(✓) Normal ( ) abnormal _____
- Smoke	(✓) Normal ( ) abnormal _____
PUMP AND PIPING	
- Check line pressure	260 psi
- Pressure relief valve maintain pressure at	_____ psi
- Check for leaks around the pump & piping	(✓) Normal ( ) leak _____
- Check mechanical seal / packing for leak	(✓) Normal ( ) leak _____
- Examine for abnormal noise, heat, vibration	(✓) Normal ( ) abnormal _____

Time start 13.34 Time stop 14.03 Total 30 mins

Supervisor' s comments Normal

[redacted]

SOFITEL
HOTELS & RESORTS
BANGKOK SUKHUMVIT

WEEKLY FIRE PUMP WARM - UP LOG SHEET

FP1 DATE 26/2/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full [✓] Low [ ] ( ) add ..... lts.
- Diesel fuel tank level (750 - 800 Ltrs.)	Full level 770 ltrs. Add _____ ltrs.
- Clean air filter	(✓) clean ( ) dirty, cleaned
- Record hours meter reading	19.1 hrs.
BATTERY	
- Check current charging to battery	(✓) chagre ( ) No charge
- Check battery terminals	(✓) tight, clean ( ) loose, tightened
- Check distilled water level	Full [✓] Low [ ]
- Record SP.G. level	( ) red ( ) yellow (✓) green
GENERAL	
- Water in serving tank	Full [✓] Low [ ]
- Clean control panel	(✓) clean ( ) dirty, cleaned
- Check pressure recorder in system	142 psi
- Check valves for free travel	(✓) normal 2 ( ) abnormal_____
- Suction pressure	_____ psi
OPERATIONAL CHECK	
ENGINE	Started / Running (____ mins)
- Check lubricating oil pressure	80 bar / 54 bar
- Cooling water temp (50°C - 70°C)	85 °C / 85 °C
- Engine speed	2200 rpm / 2200 rpm
- Check current charging to battery	_____ amp / 0.4/4.9 amp
- Check for leaks around the engine	(✓) Normal ( ) leak
- Noises	(✓) Normal ( ) abnormal _____
- Vibration	(✓) Normal ( ) abnormal _____
- Smoke	(✓) Normal ( ) abnormal _____
PUMP AND PIPING	
- Check line pressure	187 psi
- Pressure relief valve maintain pressure at	_____ psi
- Check for leaks around the pump & piping	(✓) Normal ( ) leak _____
- Check mechanical seal / packing for leak	(✓) Normal ( ) leak _____
- Examine for abnormal noise, heat, vibration	(✓) Normal ( ) abnormal _____

Time start 13.34 Time stop 14.03 Total 30 mins

Supervisor' s comments ปกติ

[redacted]

SOFITEL
HOTELS & RESORTS
BANGKOK SUKHUMVIT

WEEKLY FIRE PUMP WARM - UP LOG SHEET

FP.2 DATE 16/4/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full [✓] Low [ ] ( ) add ..... lts.
- Diesel fuel tank level (750 - 800 Ltrs.)	Full level 1290 ltrs. Add _____ ltrs.
- Clean air filter	(✓) clean ( ) dirty, cleaned
- Record hours meter reading	20.4 hrs.
BATTERY	
- Check current charging to battery	(✓) chagre ( ) No charge
- Check battery terminals	(✓) tight, clean ( ) loose, tightened
- Check distilled water level	Full [✓] Low [ ]
- Record SP.G. level	( ) red ( ) yellow (✓) green
GENERAL	
- Water in serving tank	Full [✓] Low [ ]
- Clean control panel	(✓) clean ( ) dirty, cleaned
- Check pressure recorder in system	185 psi
- Check valves for free travel	(✓) normal 12 ( ) abnormal_____
- Suction pressure	_____ psi
OPERATIONAL CHECK	
ENGINE	Started / Running (____ mins)
- Check lubricating oil pressure	65 bar / _____ bar
- Cooling water temp (50°C - 70°C)	84 °C / _____ °C
- Engine speed	2300 rpm / _____ rpm
- Check current charging to battery	0.4/0.6 amp / _____ amp
- Check for leaks around the engine	(✓) Normal ( ) leak
- Noises	(✓) Normal ( ) abnormal _____
- Vibration	(✓) Normal ( ) abnormal _____
- Smoke	(✓) Normal ( ) abnormal _____
PUMP AND PIPING	
- Check line pressure	259 psi
- Pressure relief valve maintain pressure at	_____ psi
- Check for leaks around the pump & piping	(✓) Normal ( ) leak _____
- Check mechanical seal / packing for leak	(✓) Normal ( ) leak _____
- Examine for abnormal noise, heat, vibration	(✓) Normal ( ) abnormal _____

Time start 13.32 Time stop 13.37 Total 5 mins

Supervisor' s comments ปกติ

[redacted]

SOFITEL
HOTELS & RESORTS
BANGKOK SUKHUMVIT

WEEKLY FIRE PUMP WARM - UP LOG SHEET

FP.1 DATE 16/4/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full [✓] Low [ ] ( ) add ..... lts.
- Diesel fuel tank level (750 - 800 Ltrs.)	Full level 750 ltrs. Add _____ ltrs.
- Clean air filter	( ) clean ( ) dirty, cleaned
- Record hours meter reading	20.1 hrs.
BATTERY	
- Check current charging to battery	(✓) chagre ( ) No charge
- Check battery terminals	(✓) tight, clean ( ) loose, tightened
- Check distilled water level	Full [✓] Low [ ]
- Record SP.G. level	( ) red ( ) yellow (✓) green
GENERAL	
- Water in serving tank	Full [✓] Low [ ]
- Clean control panel	(✓) clean ( ) dirty, cleaned
- Check pressure recorder in system	163 psi
- Check valves for free travel	(✓) normal 4 ( ) abnormal_____
- Suction pressure	_____ psi
OPERATIONAL CHECK	
ENGINE	Started / Running (____ mins)
- Check lubricating oil pressure	80 bar / _____ bar
- Cooling water temp (50°C - 70°C)	80 °C / _____ °C
- Engine speed	2200 rpm / _____ rpm
- Check current charging to battery	0.4/4.7 amp / _____ amp
- Check for leaks around the engine	(✓) Normal ( ) leak
- Noises	(✓) Normal ( ) abnormal _____
- Vibration	(✓) Normal ( ) abnormal _____
- Smoke	(✓) Normal ( ) abnormal _____
PUMP AND PIPING	
- Check line pressure	165 psi
- Pressure relief valve maintain pressure at	90 psi
- Check for leaks around the pump & piping	(✓) Normal ( ) leak _____
- Check mechanical seal / packing for leak	(✓) Normal ( ) leak _____
- Examine for abnormal noise, heat, vibration	(✓) Normal ( ) abnormal _____

Time start 13.32 Time stop 13.37 Total 5 mins

Supervisor' s comments ปกติ

[redacted]

PREVENTIVE MAINTENANCE AND TESTING REPORT

FIRE ALARM SYSTEM

SOFITEL BANGKOK SUKHUMVIT HOTEL



TEST 4/4

10 - 12 JUNE 2026

FIRE WORK SYSTEM & SERVICE CO., LTD.

Operation & Data Testing Report

Fire Alarm System

Fire Alarm System

FIRE WORK SYSTEM & SERVICE

OPERATION & DATA TEST REPORT

FIRE ALARM SYSTEM

DATE : 10 - 12 มิถุนายน 2569

TIME : 09.00 - 17.00 น.

System : ระบบสัญญาณแจ้งเหตุเพลิงไหม้

Subject : งานบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้

Location : SOFITEL BANGKOK SUKHUMVIT HOTEL **Operator** :

Telephone : 02-246-2323 ต่อ 1803

Owner contact : SOFITEL BANGKOK SUKHUMVIT HOTEL

Address : 189 ถนนสุขุมวิท ซอย 13-15 แขวงคลองเตยเหนือ เขตวัฒนา กรุงเทพมหานคร 10110

PANEL DESCRIPTION

Panel Manufacturer : NOTIFIER Model : NFS2-3030E

Circuit Styles : Class A

Last date system had any sevice performed : 12 June 2025

Last date that any software or configuration was revised :

Location (Panel Number) : Control Room, 5th Floor

System Capacity

- Intelligent Signaling Line Circu : 6 Loop Style : Class A
- Intelligent Detectors :
- Addressable Monitor/Control Modul :

System Power

- Primary Input Power Voltage : ☐ 110 VAC ☑ 220 VAC
- Total Output 24V Power : ☑ 6 Amps ☐ 10 Amps ☐ 15 Amps ☐ 20 Amps
- Ground Chassis : ☑ Yes ☐ No

Secondary Power Voltage (Back up Battery)

Quantity of : 2 Set

Amp-Hr. rating : 18 Ah

Voltage : 24 VDC

Type of Battery : ☐ Dry Cell ☑ Seal Lead-Acid ☐ Nickel Cadmium ☐ Seal Lead Calcium Batt

FIWSS
FIRE WORK SYSTEM & SERVICE

SYSTEM TESTS AND INSPECTIONS

	Pass	Fail	Comment
Type			
Control Unit	☑	☐	
Interface equipment	☑	☐	
Lamp and LEDs	☑	☐	
Fuses	☑	☐	
Primary (main) power supply	☑	☐	
Trouble signal	☑	☐	
Ground Fault Monitoring	☑	☐	
Secondary Power			
Battery Condition	☑	☐	
Load voltage	☑	☐	
Discharge Test	☑	☐	
Charge Test	☑	☐	
Notification Appliances			
Audible device	☑	☐	
Visual device	☑	☐	

System restored to normal operation Date : 12 June 2026 **Time :** 09.00 am. – 05:00 pm

Comment :

Name of Inspector : [redacted]

Signature :

Name of Owner or Representative SOFITEL BANGKOK SUKHUMVIT HOTEL

THIS TESTING WAS PERFORMED IN ACCORDANCE WITH APPLICABLE NFPA STANDARDS

Project : Fire Alarm
Location : Sofitel Bangkok Sukhumvit Hotel
Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ
Trouble : สายขาด Open Circuit
Disable : ระบบการทำงานถูกปิดชั่วคราว

FIWSS
FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
1	BZD1	FL.B	1	M001	-	✓	-	-	-					
2	BZD2	FL.B	1	M002	-	✓	-	-	-					
3	BZD3	FL.B	1	M003	-	✓	-	-	-					
4	GZD1	FL.G	1	M004	-	✓	-	-	-	✓	✓		✓	
5	GZD2	FL.G	1	M005	-	✓	-	-	-			✓		
6	GZD3	FL.G	1	M006	-	✓	-	-	-	✓		✓		
7	BSVS12	FL.B	1	M007	-	✓	-	-	-					
8	BSVS13	FL.B	1	M008	-	✓	-	-	-					
9	2ZD1	FL.2	1	M009	-	✓	-	-	-	✓				
10	2ZD2	FL.2	1	M010	-	✓	-	-	-			✓		
11	2ZD3	FL.2	1	M011	-	✓	-	-	-	✓	✓		✓	
12	2ZD4	FL.2	1	M012	-	✓	-	-	-	✓		✓	✓	
13	3ZD1	FL.3	1	M013	-	✓	-	-	-		✓		✓	
14	3ZD2	FL.3	1	M014	-	-	✓	-	-			✓		
15	3ZD3	FL.3	1	M015	-	✓	-	-	-	✓	✓	✓	✓	
16	3ZD4	FL.3	1	M016	-	✓	-	-	-	✓		✓	✓	
17	3ZD5	FL.3	1	M017	-	✓	-	-	-	✓		✓	✓	
18	4ZD1	FL.4	1	M018	-	✓	-	-	-				✓	
19	4ZD2	FL.4	1	M019	-	✓	-	-	-				✓	
20	4ZD3	FL.4	1	M020	-	✓	-	-	-			✓		
21	4ZD4	FL.4	1	M021	-	✓	-	-	-	✓	✓	✓	✓	
22	4ZD5	FL.4	1	M022	-	✓	-	-	-	✓	✓	✓	✓	
23	4ZD6	FL.4	1	M023	-	✓	-	-	-	✓		✓	✓	
24	5ZD1	FL.5	1	M024	-	✓	-	-	-					
25	5ZD2	FL.5	1	M025	-	✓	-	-	-			✓		
26	5ZD3	FL.5	1	M026	-	✓	-	-	-	✓			✓	
27	5ZD4	FL.5	1	M027	-	✓	-	-	-	✓	✓	✓	✓	
28	5ZD5	FL.5	1	M028	-	✓	-	-	-	✓	✓	✓	✓	
29	5ZD6	FL.5	1	M029	-	✓	-	-	-					
30	7ZD1	FL.7	1	M030	-	✓	-	-	-	✓				
31	7ZD2	FL.7	1	M031	-	✓	-	-	-				✓	
32	7ZD3	FL.7	1	M032	-	✓	-	-	-	✓		✓		
33	7ZD4	FL.7	1	M033	-	✓	-	-	-	✓	✓		✓	
34	7ZD5	FL.7	1	M034	-	✓	-	-	-					
35	6ZD1	FL.6	1	M035	-	✓	-	-	-				✓	
36	6ZD2	FL.6	1	M036	-	✓	-	-	-	✓	✓	✓	✓	
37	6ZD3	FL.6	1	M037	-	✓	-	-	-			✓	✓	
38	6ZD4	FL.6	1	M038	-	✓	-	-	-		✓		✓	

Project : Fire Alarm
Location : Sofitel Bangkok Sukhumvit Hotel
Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ
Trouble : สายขาด Open Circuit
Disable : ระบบการทำงานถูกปิดชั่วคราว

FIWSS
FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
39	6ZD5	FL.6	1	M039	-	✓	-	-	-					
40	5PAF1	FL.5	1	M040	-	✓	-	-	-					
41	7PAF1	FL.7	1	M041	-	✓	-	-	-					
42	BZB1	FL.B	1	M045	-	✓	-	-	-					
43	GZB1	FL.G	1	M046	-	✓	-	-	-					
44	2ZB1	FL.2	1	M047	-	✓	-	-	-					
45	3ZB1	FL.3	1	M048	-	✓	-	-	-					
46	4ZB1	FL.4	1	M049	-	✓	-	-	-					
47	4SF1	FL.4	1	M050	-	✓	-	-	-					
48	4LIFT1	FL.4	1	M051	-	✓	-	-	-					
49	5ZB1	FL.5	1	M052	-	✓	-	-	-					
50	7ANSUL	FL.7	1	M053	-	✓	-	-	-					
51	7ANSUL2	FL.7	1	M054	-	✓	-	-	-					
52	7GAS	FL.7	1	M055	-	✓	-	-	-					
53	BSVS11	FL.B	1	M056	-	✓	-	-	-					
54	6ZB1	FL.6	1	M057	-	✓	-	-	-					
55	6SF1	FL.6	1	M058	-	✓	-	-	-					
56	7ZB1	FL.7	1	M060	-	✓	-	-	-					
57	BZAHU1	FL.B	1	M061	-	✓	-	-	-					
58	BLIFT	FL.B	1	M062	-	✓	-	-	-					
59	BSVS10	FL.B	1	M063	-	✓	-	-	-					
60	BSVS2	FL.B	1	M064	-	✓	-	-	-					
61	BSVS3	FL.B	1	M065	-	✓	-	-	-					
62	BSVS4	FL.B	1	M066	-	✓	-	-	-					
63	BSVS5	FL.B	1	M067	-	✓	-	-	-					
64	BSVS6	FL.B	1	M068	-	✓	-	-	-					
65	BSVS7	FL.B	1	M069	-	✓	-	-	-					
66	BSVS8	FL.B	1	M070	-	✓	-	-	-					
67	BSVS9	FL.B	1	M071	-	✓	-	-	-					
68	7ZAHU1	FL.7	1	M072	-	✓	-	-	-					
69	7ZAHU2	FL.7	1	M073	-	✓	-	-	-					
70	6FS01	FL.6	1	M074	-	✓	-	-	-					
71	6FS02	FL.6	1	M075	-	✓	-	-	-					
72	6SS01	FL.6	1	M076	-	✓	-	-	-					
73	6SS02	FL.6	1	M077	-	✓	-	-	-					
74	7ZAHU3	FL.7	1	M078	-	✓	-	-	-					
75	7ZAHU4	FL.7	1	M079	-	✓	-	-	-					
76	BFS01	FL.B	1	M080	-	✓	-	-	-					

Project : Fire Alarm
Location : Sofitel Bangkok Sukhumvit Hotel
Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ
Trouble : สายขาด Open Circuit
Disable : ระบบการทำงานถูกปิดชั่วคราว

FIWSS
FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
77	BFS02	FL.B	1	M081	-	✓	-	-	-					
78	BSS01	FL.B	1	M082	-	✓	-	-	-					
79	BSS02	FL.B	1	M083	-	✓	-	-	-					
80	B/STATUS FP1	FL.B	1	M084	-	✓	-	-	-					
81	B/STATUS FP2	FL.B	1	M085	-	✓	-	-	-					
82	B/ALARM JP1	FL.B	1	M086	-	✓	-	-	-					
83	B/ALARM JP2	FL.B	1	M087	-	✓	-	-	-					
84	GFS01	FL.G	1	M088	-	✓	-	-	-					
85	GFS02	FL.G	1	M089	-	✓	-	-	-					
86	GSS01	FL.G	1	M090	-	✓	-	-	-					
87	GSS02	FL.G	1	M091	-	✓	-	-	-					
88	BSVS14	FL.B	1	M092	-	✓	-	-	-					
89	BSVS15	FL.B	1	M093	-	✓	-	-	-					
90	BSVS16	FL.B	1	M094	-	✓	-	-	-					
91	BSVS17	FL.B	1	M095	-	✓	-	-	-					
92	GZAHU1	FL.G	1	M096	-	✓	-	-	-					
93	GZAHU2	FL.G	1	M097	-	✓	-	-	-					
94	GZAHU3	FL.G	1	M098	-	✓	-	-	-					
95	2ZAHU1	FL.2	1	M099	-	✓	-	-	-					
96	2ZAHU2	FL.2	1	M100	-	✓	-	-	-					
97	2ANSUL	FL.2	1	M101	-	✓	-	-	-					
98	2FS01	FL.2	1	M102	-	✓	-	-	-					
99	2FS02	FL.2	1	M103	-	✓	-	-	-					
100	2SS01	FL.2	1	M104	-	✓	-	-	-					
101	2SS02	FL.2	1	M105	-	✓	-	-	-					
102	2GAS	FL.2	1	M106	-	✓	-	-	-					
103	Z3AHU1	FL.3	1	M107	-	✓	-	-	-					
104	Z3AHU2	FL.3	1	M108	-	✓	-	-	-					
105	Z3AHU3	FL.3	1	M109	-	✓	-	-	-					
106	3ANSUL1	FL.3	1	M110	-	✓	-	-	-					
107	3ANSUL2	FL.3	1	M111	-	✓	-	-	-					
108	3FS01	FL.3	1	M112	-	✓	-	-	-					
109	3FS02	FL.3	1	M113	-	✓	-	-	-					
110	3SS01	FL.3	1	M114	-	✓	-	-	-					
111	3SS02	FL.3	1	M115	-	✓	-	-	-					
112	3ANUSUL3	FL.3	1	M116	-	✓	-	-	-					
113	3ANUSUL4	FL.3	1	M117	-	✓	-	-	-					
114	3GAS	FL.3	1	M118	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
115	4ZAHU1	FL.4	1	M119	-	✓	-	-	-					
116	4ZAHU2	FL.4	1	M120	-	✓	-	-	-					
117	4ANUSL	FL.4	1	M121	-	✓	-	-	-					
118	4FS01	FL.4	1	M122	-	✓	-	-	-					
119	4FS02	FL.4	1	M123	-	✓	-	-	-					
120	4SS01	FL.4	1	M124	-	✓	-	-	-					
121	4SS02	FL.4	1	M125	-	✓	-	-	-					
122	4GAS	FL.4	1	M126	-	✓	-	-	-					
123	5ZAHU1	FL.5	1	M127	-	✓	-	-	-					
124	5ZAHU2	FL.5	1	M128	-	✓	-	-	-					
125	5ZAHU3	FL.5	1	M129	-	✓	-	-	-					
126	5ZAHU4	FL.5	1	M130	-	✓	-	-	-					
127	5ZAHU5	FL.5	1	M131	-	✓	-	-	-					
128	5ZAHU6	FL.5	1	M132	-	✓	-	-	-					
129	5ZAHU7	FL.5	1	M133	-	✓	-	-	-					
130	5ZAHU8	FL.5	1	M134	-	✓	-	-	-					
131	5ZBGS	FL.5	1	M135	-	✓	-	-	-					
132	5FM1	FL.5	1	M136	-	✓	-	-	-					
133	5FM2	FL.5	1	M137	-	✓	-	-	-					
134	6ZAHU1	FL.6	1	M138	-	✓	-	-	-					
135	6ZAHU2	FL.6	1	M139	-	✓	-	-	-					
136	6ZAHU3	FL.6	1	M140	-	✓	-	-	-					
137	6ZAHU4	FL.6	1	M141	-	✓	-	-	-					
138	5FS01	FL.5	1	M142	-	✓	-	-	-					
139	5FS02	FL.5	1	M143	-	✓	-	-	-					
140	5SS01	FL.5	1	M144	-	✓	-	-	-					
141	5SS02	FL.5	1	M145	-	✓	-	-	-					
142	6ZAHU5	FL.6	1	M146	-	✓	-	-	-					
143	6ANUSUL	FL.6	1	M147	-	✓	-	-	-					
144	6GAS	FL.6	1	M148	-	✓	-	-	-					
145	6FM1	FL.6	1	M149	-	✓	-	-	-					
146	7ZAHU5	FL.7	1	M150	-	✓	-	-	-					
147	7ZAHU6	FL.7	1	M151	-	✓	-	-	-					
148	7ZB2	FL.7	1	M152	-	✓	-	-	-					
149	7ZB3	FL.7	1	M153	-	✓	-	-	-					
150	7FS01	FL.7	1	M154	-	✓	-	-	-					
151	7FS02	FL.7	1	M155	-	✓	-	-	-					
152	7SS01	FL.7	1	M156	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
153	7SS02	FL.7	1	M157	-	✓	-	-	-					
154	P7FS01	FL.7	1	M158	-	✓	-	-	-					
155	P7SS01	FL.7	1	M159	-	✓	-	-	-					
156	8ZD1	FL.8	2	M001	-	✓	-	-	-	✓	✓	✓	✓	
157	8ZD2	FL.8	2	M002	-	✓	-	-	-	✓	✓	✓	✓	
158	8ZD3	FL.8	2	M003	-	✓	-	-	-					
159	11ZSVS02/2	FL.11	2	M004	-	✓	-	-	-					
160	11ZSVS02/3	FL.11	2	M005	-	✓	-	-	-					
161	11ZSVS02/4	FL.11	2	M006	-	✓	-	-	-					
162	11ZSVS03/2	FL.11	2	M007	-	✓	-	-	-					
163	11ZSVS03/3	FL.11	2	M008	-	✓	-	-	-					
164	11ZSVS03/4	FL.11	2	M009	-	✓	-	-	-					
165	10ZSVS02/1	FL.10	2	M010	-	✓	-	-	-					
166	10ZSVS03/1	FL.10	2	M011	-	✓	-	-	-					
167	9AHU1	FL.9	2	M012	-	✓	-	-	-					
168	9AHU2	FL.9	2	M013	-	✓	-	-	-					
169	9ZD1	FL.9	2	M014	-	✓	-	-	-	✓			✓	
170	9ZD2	FL.9	2	M015	-	✓	-	-	-				✓	
171	9ZD3	FL.9	2	M016	-	✓	-	-	-	✓	✓	✓	✓	
172	9ZD4	FL.9	2	M017	-	✓	-	-	-		✓			
173	9SZD1	FL.9	2	M018	-	✓	-	-	-					
174	9SZD2	FL.9	2	M019	-	✓	-	-	-					
175	9SZD3	FL.9	2	M020	-	✓	-	-	-					
176	9SZD4	FL.9	2	M021	-	✓	-	-	-					
177	10ZD15	FL.10	2	M022	-	✓	-	-	-		✓	✓	✓	
178	10ZD16	FL.10	2	M023	-	✓	-	-	-	✓	✓	✓	✓	
179	11ZD1	FL.11	2	M024	-	✓	-	-	-	✓	✓	✓	✓	
180	12ZD1	FL.12	2	M025	-	✓	-	-	-	✓	✓	✓	✓	
181	14ZD1	FL.14	2	M026	-	✓	-	-	-		✓	✓	✓	
182	PZD1	FL.P9 PARK	2	M027	-	✓	-	-	-					
183	PZD2	FL.P9 PARK	2	M028	-	✓	-	-	-					
184	PZD3	FL.P9 PARK	2	M029	-	✓	-	-	-					
185	PZD4	FL.G PARK	2	M030	-	✓	-	-	-				✓	
186	PZD5	FL.1st PARK	2	M031	-	✓	-	-	-	✓	✓	✓	✓	
187	PZD6	FL.P9 PARK	2	M032	-	✓	-	-	-					
188	PZD7	FL.P9 PARK	2	M033	-	✓	-	-	-					
189	PZD8	FL.P9 PARK	2	M034	-	✓	-	-	-					
190	PZD9	FL.P9 PARK	2	M035	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
191	PZD10	FL.P9 PARK	2	M036	-	✓	-	-	-					
192	PZD11	FL.P9 PARK	2	M037	-	✓	-	-	-					
193	9AHU3	FL.9	2	M038	-	✓	-	-	-					
194	9AHU4	FL.9	2	M039	-	✓	-	-	-					
195	9AHU5	FL.9	2	M040	-	✓	-	-	-					
196	9AHU6	FL.9	2	M041	-	✓	-	-	-					
197	9AHU7	FL.9	2	M042	-	✓	-	-	-					
198	9AHU8	FL.9	2	M043	-	✓	-	-	-					
199	9AHU9	FL.9	2	M044	-	✓	-	-	-					
200	8AHU1	FL.8	2	M045	-	✓	-	-	-					
201	8AHU2	FL.8	2	M046	-	✓	-	-	-					
202	8LIFT	FL.8	2	M047	-	✓	-	-	-					
203	8SF1	FL.8	2	M048	-	✓	-	-	-					
204	8SF1	FL.8	2	M049	-	✓	-	-	-					
205	8FS01	FL.8	2	M060	-	✓	-	-	-					
206	8FS02	FL.8	2	M061	-	✓	-	-	-					
207	8SS01	FL.8	2	M062	-	✓	-	-	-					
208	8SS02	FL.8	2	M063	-	✓	-	-	-					
209	9FS01	FL.9	2	M064	-	✓	-	-	-					
210	9FS02	FL.9	2	M065	-	✓	-	-	-					
211	9SS01	FL.9	2	M066	-	✓	-	-	-					
212	9SS02	FL.9	2	M067	-	✓	-	-	-					
213	10FS01	FL.10	2	M068	-	✓	-	-	-					
214	10FS02	FL.10	2	M069	-	✓	-	-	-					
215	10SS01	FL.10	2	M070	-	✓	-	-	-					
216	10SS02	FL.10	2	M071	-	✓	-	-	-					
217	11FS01	FL.11	2	M072	-	✓	-	-	-					
218	11FS02	FL.11	2	M073	-	✓	-	-	-					
219	11SS01	FL.11	2	M074	-	✓	-	-	-					
220	11SS02	FL.11	2	M075	-	✓	-	-	-					
221	12FS01	FL.12	2	M076	-	✓	-	-	-					
222	12FS02	FL.12	2	M077	-	✓	-	-	-					
223	12SS01	FL.12	2	M078	-	✓	-	-	-					
224	12SS02	FL.12	2	M079	-	✓	-	-	-					
225	14FS01	FL.14	2	M080	-	✓	-	-	-					
226	14FS02	FL.14	2	M081	-	✓	-	-	-					
227	14SS01	FL.14	2	M082	-	✓	-	-	-					
228	14SS02	FL.14	2	M083	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
229	FS1	FL.P9 PARK	2	M084	-	✓	-	-	-					
230	FS2	FL.P9 PARK	2	M085	-	✓	-	-	-					
231	FS3	FL.P9 PARK	2	M086	-	✓	-	-	-					
232	FS4	FL.P9 PARK	2	M087	-	✓	-	-	-					
233	FS5	FL.P9 PARK	2	M088	-	✓	-	-	-					
234	FS6	FL.P9 PARK	2	M089	-	✓	-	-	-					
235	FS7	FL.P9 PARK	2	M090	-	✓	-	-	-					
236	FS8	FL.P9 PARK	2	M091	-	✓	-	-	-					
237	FS9	FL.P9 PARK	2	M092	-	✓	-	-	-					
238	FS10	FL.G PARK	2	M093	-	✓	-	-	-					
239	FS11	FL.P9 PARK	2	M094	-	✓	-	-	-					
240	FS12	FL.P9 PARK	2	M095	-	✓	-	-	-					
241	PZSV1	FL.P9 PARK	2	M096	-	✓	-	-	-					
242	PZSV2	FL.P9 PARK	2	M097	-	✓	-	-	-					
243	PZSV3	FL.P9 PARK	2	M098	-	✓	-	-	-					
244	PZSV4	FL.P9 PARK	2	M099	-	✓	-	-	-					
245	8ZB1	FL.8	2	M100	-	✓	-	-	-					
246	8LIFT1	FL.8	2	M101	-	✓	-	-	-					
247	8TELL	FL.8	2	M102	-	✓	-	-	-					
248	8SF01	FL.8	2	M103	-	✓	-	-	-					
249	8SF02	FL.8	2	M104	-	✓	-	-	-					
250	9ZB1	FL.9	2	M105	-	✓	-	-	-					
251	9SF01	FL.9	2	M106	-	✓	-	-	-					
252	9SF02	FL.9	2	M107	-	✓	-	-	-					
253	9TELL	FL.9	2	M108	-	✓	-	-	-					
254	10ZB1	FL.10	2	M109	-	✓	-	-	-					
255	11ZB1	FL.11	2	M110	-	✓	-	-	-					
256	12ZB1	FL.12	2	M111	-	✓	-	-	-					
257	12LIFT1	FL.12	2	M112	-	✓	-	-	-					
258	14ZB1	FL.14	2	M113	-	✓	-	-	-					
259	PZB1	FL.P1 PARK	2	M114	-	✓	-	-	-					
260	PZB2	FL.P9 PARK	2	M115	-	✓	-	-	-					
261	PZB3	FL.P9 PARK	2	M116	-	✓	-	-	-					
262	PZB4	FL.P9 PARK	2	M117	-	✓	-	-	-					
263	PZB5	FL.P9 PARK	2	M118	-	✓	-	-	-					
264	PZB6	FL.P9 PARK	2	M119	-	✓	-	-	-					
265	PZB7	FL.P9 PARK	2	M120	-	✓	-	-	-					
266	PZB8	FL.P9 PARK	2	M121	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
267	PZB10	FL.P9 PARK	2	M123	-	✓	-	-	-					
268	PZB11	FL.P9 PARK	2	M124	-	✓	-	-	-					
269	PZSV5	FL.P9 PARK	2	M130	-	✓	-	-	-					
270	PZSV6	FL.P9 PARK	2	M131	-	✓	-	-	-					
271	PZSV7	FL.P9 PARK	2	M132	-	✓	-	-	-					
272	PZSV8	FL.P9 PARK	2	M133	-	✓	-	-	-					
273	PZSV9	FL.P9 PARK	2	M134	-	✓	-	-	-					
274	PZSV10	FL.G PARK	2	M135	-	✓	-	-	-					
275	PZSV11	FL.P9 PARK	2	M136	-	✓	-	-	-					
276	PZSV12	FL.P9 PARK	2	M137	-	✓	-	-	-					
277	PZG1	FL.G PARK	2	M138	-	✓	-	-	-					
278	PZG2	FL.G PARK	2	M139	-	✓	-	-	-					
279	15ZD1	FL.15	3	M001	-	✓	-	-	-	✓	✓	✓	✓	
280	16ZD1	FL.16	3	M002	-	✓	-	-	-	✓	✓	✓	✓	
281	17ZD1	FL.17	3	M003	-	✓	-	-	-	✓	✓	✓	✓	
282	18ZD1	FL.18	3	M004	-	✓	-	-	-	✓	✓	✓	✓	
283	15FS01	FL.15	3	M060	-	✓	-	-	-					
284	15FS02	FL.15	3	M061	-	✓	-	-	-					
285	15SS01	FL.15	3	M062	-	✓	-	-	-					
286	15SS02	FL.15	3	M063	-	✓	-	-	-					
287	16FS01	FL.16	3	M064	-	✓	-	-	-					
288	16FS02	FL.16	3	M065	-	✓	-	-	-					
289	16SS01	FL.16	3	M066	-	✓	-	-	-					
290	16SS02	FL.16	3	M067	-	✓	-	-	-					
291	17FS01	FL.17	3	M068	-	✓	-	-	-					
292	17FS02	FL.17	3	M069	-	✓	-	-	-					
293	17SS01	FL.17	3	M070	-	✓	-	-	-					
294	17SS02	FL.17	3	M071	-	✓	-	-	-					
295	18FS01	FL.18	3	M072	-	✓	-	-	-					
296	18FS02	FL.18	3	M073	-	✓	-	-	-					
297	18SS01	FL.18	3	M074	-	✓	-	-	-					
298	18SS02	FL.18	3	M075	-	✓	-	-	-					
299	15ZB1	FL.15	3	M100	-	✓	-	-	-					
300	16ZB1	FL.16	3	M101	-	✓	-	-	-					
301	17ZB1	FL.17	3	M102	-	✓	-	-	-					
302	18ZB1	FL.18	3	M103	-	✓	-	-	-					
303	19ZD1	FL.19	4	M001	-	✓	-	-	-	✓	✓	✓	✓	
304	20ZD1	FL.20	4	M002	-	✓	-	-	-	✓	✓	✓	✓	

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
305	21ZD1	FL.21	4	M003	-	✓	-	-	-	✓	✓	✓	✓	
306	22ZD1	FL.22	4	M004	-	✓	-	-	-	✓	✓		✓	
307	22SZD1	FL.22	4	M005	-	✓	-	-	-	✓				
308	22SZD2	FL.22	4	M006	-	✓	-	-	-	✓				
309	19FS01	FL.19	4	60	-	✓	-	-	-					
310	19FS02	FL.19	4	61	-	✓	-	-	-					
311	19SS01	FL.19	4	62	-	✓	-	-	-					
312	19SS02	FL.19	4	63	-	✓	-	-	-					
313	20FS01	FL.20	4	64	-	✓	-	-	-					
314	20FS02	FL.20	4	65	-	✓	-	-	-					
315	20SS01	FL.20	4	66	-	✓	-	-	-					
316	20SS02	FL.20	4	67	-	✓	-	-	-					
317	21FS01	FL.21	4	68	-	✓	-	-	-					
318	21FS02	FL.21	4	69	-	✓	-	-	-					
319	21SS01	FL.21	4	70	-	✓	-	-	-					
320	21SS02	FL.21	4	71	-	✓	-	-	-					
321	22FS01	FL.22	4	72	-	✓	-	-	-					
322	22FS02	FL.22	4	73	-	✓	-	-	-					
323	22SS01	FL.22	4	74	-	✓	-	-	-					
324	22SS02	FL.22	4	75	-	✓	-	-	-					
325	19ZB1	FL.19	4	100	-	✓	-	-	-					
326	20ZB1	FL.20	4	101	-	✓	-	-	-					
327	21ZB1	FL.21	4	102	-	✓	-	-	-					
328	22ZB1	FL.22	4	103	-	✓	-	-	-					
329	MONITOR GENERAL	SUPPLY	4	155	-	✓	-	-	-					
330	MONITOR AC FAIL	POWER SUPPLY	4	156	-	✓	-	-	-					
331	MONITOR BATTERY	POWER SUPPLY	4	157	-	✓	-	-	-					
332	MONITOR GROUND	GROUND FAULT	4	158	-	✓	-	-	-					
333	23ZD1	FL.23	5	1	-	✓	-	-	-	✓	✓	✓	✓	
334	24ZD1	FL.24	5	2	-	✓	-	-	-	✓	✓	✓	✓	
335	25ZD1	FL.25	5	3	-	✓	-	-	-	✓	✓	✓	✓	
336	26ZD1	FL.26	5	4	-	✓	-	-	-	✓	✓	✓	✓	
337	23FS01	FL.23	5	60	-	✓	-	-	-					
338	23FS02	FL.23	5	61	-	✓	-	-	-					
339	23SS01	FL.23	5	62	-	✓	-	-	-					
340	23SS02	FL.23	5	63	-	✓	-	-	-					
341	24FS01	FL.24	5	64	-	✓	-	-	-					
342	24FS02	FL.24	5	65	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
343	24SS01	FL.24	5	66	-	✓	-	-	-					
344	24SS02	FL.24	5	67	-	✓	-	-	-					
345	25FS01	FL.25	5	68	-	✓	-	-	-					
346	25FS02	FL.25	5	69	-	✓	-	-	-					
347	25SS01	FL.25	5	70	-	✓	-	-	-					
348	25SS02	FL.25	5	71	-	✓	-	-	-					
349	26FS01	FL.26	5	72	-	✓	-	-	-					
350	26FS02	FL.26	5	73	-	✓	-	-	-					
351	26SS01	FL.26	5	74	-	✓	-	-	-					
352	26SS02	FL.26	5	75	-	✓	-	-	-					
353	23ZB1	FL.23	5	100	-	✓	-	-	-					
354	24ZB1	FL.24	5	101	-	✓	-	-	-					
355	24TELL	FL.24	5	102	-	✓	-	-	-					
356	25ZB1	FL.25	5	103	-	✓	-	-	-					
357	26ZB1	FL.26	5	104	-	✓	-	-	-					
358	27ZD1	FL.27	6	1	-	✓	-	-	-	✓	✓	✓	✓	
359	28ZD1	FL.28	6	2	-	✓	-	-	-	✓	✓	✓	✓	
360	29ZD2	FL.29	6	3	-	✓	-	-	-	✓	✓	✓	✓	
361	30ZD3	FL.30	6	4	-	✓	-	-	-	✓	✓	✓	✓	
362	31ZD1	FL.31	6	5	-	✓	-	-	-	✓	✓	✓	✓	
363	32ZD5	FL.32	6	6	-	✓	-	-	-	✓	✓		✓	
364	32/GDC-F32-01 REL	FL.32	6	7	-	✓	-	-	-					
365	32/GDC-F32-01 TBL	FL.32	6	8	-	✓	-	-	-					
366	33ZD1	FL.33	6	9	-	✓	-	-	-			✓		
367	34ZD1	FL.34	6	10	-	✓	-	-	-			✓		
368	35ZD1	FL.35	6	11	-	✓	-	-	-					
369	36SZD1	FL.36	6	12	-	✓	-	-	-	✓				
370	36SZD2	FL.36	6	13	-	✓	-	-	-					
371	32ZD1	FL.32	6	14	-	✓	-	-	-		✓		✓	
372	32ZD2	FL.32	6	15	-	✓	-	-	-				✓	
373	32ZD3	FL.32	6	16	-	✓	-	-	-					
374	32ZD4	FL.32	6	17	-	✓	-	-	-	✓	✓		✓	
375	35ZAHU1	FL.35	6	19	-	✓	-	-	-					
376	35ZAHU2	FL.35	6	20	-	✓	-	-	-					
377	35ZSF1	FL.35	6	21	-	✓	-	-	-					
378	35ZSF2	FL.35	6	22	-	✓	-	-	-					
379	34ZAHU	FL.34	6	23	-	✓	-	-	-					
380	34LIFT1	FL.34	6	24	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
381	34LIFT2	FL.34	6	25	-	✓	-	-	-					
382	33ZAHU1	FL.33	6	26	-	✓	-	-	-					
383	33ZAHU2	FL.33	6	27	-	✓	-	-	-					
384	32ZAHU1	FL.32	6	28	-	✓	-	-	-					
385	32ZAHU2	FL.32	6	29	-	✓	-	-	-					
386	32ZAHU3	FL.32	6	30	-	✓	-	-	-					
387	32ZAHU4	FL.32	6	31	-	✓	-	-	-					
388	32ZAHU5	FL.32	6	32	-	✓	-	-	-					
389	32ZAHU6	FL.32	6	33	-	✓	-	-	-					
390	31ZAHU	FL.31	6	34	-	✓	-	-	-					
391	31ANSUL	FL.31	6	35	-	✓	-	-	-					
392	30ZTEL	FL.30	6	36	-	✓	-	-	-					
393	32ANSUL	FL.32	6	37	-	✓	-	-	-					
394	27FS01	FL.27	6	60	-	✓	-	-	-					
395	27FS02	FL.27	6	61	-	✓	-	-	-					
396	27SS01	FL.27	6	62	-	✓	-	-	-					
397	27SS02	FL.27	6	63	-	✓	-	-	-					
398	28FS01	FL.28	6	64	-	✓	-	-	-					
399	Library	FL.32	6	65	-	✓	-	-	-					
400	28SS01	FL.28	6	66	-	✓	-	-	-					
401	28SS02	FL.28	6	67	-	✓	-	-	-					
402	29FS01	FL.29	6	68	-	✓	-	-	-					
403	29FS02	FL.29	6	69	-	✓	-	-	-					
404	29SS01	FL.29	6	70	-	✓	-	-	-					
405	29SS02	FL.29	6	71	-	✓	-	-	-					
406	30FS01	FL.30	6	72	-	✓	-	-	-					
407	30FS02	FL.30	6	73	-	✓	-	-	-					
408	30SS01	FL.30	6	74	-	✓	-	-	-					
409	30SS02	FL.30	6	75	-	✓	-	-	-					
410	31FS01	FL.31	6	76	-	✓	-	-	-					
411	31FS02	FL.31	6	77	-	✓	-	-	-					
412	31SS01	FL.31	6	78	-	✓	-	-	-					
413	31SS02	FL.31	6	79	-	✓	-	-	-					
414	32FS01	FL.32	6	80	-	✓	-	-	-					
415	32FS02	FL.32	6	81	-	✓	-	-	-					
416	32SS01	FL.32	6	82	-	✓	-	-	-					
417	32SS02	FL.32	6	83	-	✓	-	-	-					
418	33FS01	FL.33	6	84	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
419	33FS02	FL.33	6	85	-	✓	-	-	-					
420	33SS01	FL.33	6	86	-	✓	-	-	-					
421	33SS02	FL.33	6	87	-	✓	-	-	-					
422	34FS01	FL.34	6	88	-	✓	-	-	-					
423	34FS02	FL.34	6	89	-	✓	-	-	-					
424	34SS01	FL.34	6	90	-	✓	-	-	-					
425	34SS02	FL.34	6	91	-	✓	-	-	-					
426	35FS01	FL.35	6	92	-	✓	-	-	-					
427	35FS02	FL.35	6	93	-	✓	-	-	-					
428	35SS01	FL.35	6	94	-	✓	-	-	-					
429	35SS02	FL.35	6	95	-	✓	-	-	-					
430	36FS01	FL.36	6	96	-	✓	-	-	-					
431	36FS02	FL.36	6	97	-	✓	-	-	-					
432	36SS01	FL.36	6	98	-	✓	-	-	-					
433	36SS02	FL.36	6	99	-	✓	-	-	-					
434	27ZB1	FL.27	6	100	-	✓	-	-	-					
435	28ZB1	FL.28	6	101	-	✓	-	-	-					
436	29ZB1	FL.29	6	102	-	✓	-	-	-					
437	30ZB1	FL.30	6	103	-	✓	-	-	-					
438	31ZB1	FL.31	6	104	-	✓	-	-	-					
439	32ZB1	FL.32	6	105	-	✓	-	-	-					
440	33ZB1	FL.33	6	106	-	✓	-	-	-					
441	34ZB1	FL.34	6	107	-	✓	-	-	-					
442	34LIFT	FL.34	6	108	-	✓	-	-	-					
443	35ZB1	FL.35	6	109	-	✓	-	-	-					
444	35PAF1	FL.35	6	110	-	✓	-	-	-					
445	35AHU1	FL.35	6	111	-	✓	-	-	-					
446	36SF01	FL.36	6	112	-	✓	-	-	-					
447	36SF02	FL.36	6	113	-	✓	-	-	-					
448	36TELL	FL.36	6	114	-	✓	-	-	-					
449	35PAF2	FL.35	6	150	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
1	810.RM	FL.8	2	D001	-	✓	-	-	-					
2	809.RM	FL.8	2	D002	-	✓	-	-	-				✓	
3	808.RM	FL.8	2	D003	-	✓	-	-	-				✓	
4	807.RM	FL.8	2	D004	-	✓	-	-	-					
5	807.RM	FL.8	2	D005	-	✓	-	-	-					
6	807.RM	FL.8	2	D006	-	✓	-	-	-					
7	807.RM	FL.8	2	D007	-	✓	-	-	-					
8	807.RM	FL.8	2	D008	-	✓	-	-	-					
9	807.RM	FL.8	2	D009	-	✓	-	-	-					
10	807.RM	FL.8	2	D010	-	✓	-	-	-					
11	807.RM	FL.8	2	D011	-	✓	-	-	-					
12	818.RM	FL.8	2	D012	-	✓	-	-	-				✓	
13	820.RM	FL.8	2	D013	-	✓	-	-	-				✓	
14	819.RM	FL.8	2	D014	-	✓	-	-	-				✓	
15	817.RM	FL.8	2	D015	-	✓	-	-	-					
16	815.RM	FL.8	2	D016	-	✓	-	-	-					
17	1011.RM	FL.10	2	D017	-	✓	-	-	-					
18	1010.RM	FL.10	2	D018	-	✓	-	-	-					
19	1009.RM	FL.10	2	D019	-	✓	-	-	-				✓	
20	1008.RM	FL.10	2	D020	-	✓	-	-	-				✓	
21	1007.RM	FL.10	2	D021	-	✓	-	-	-				✓	
22	1006.RM	FL.10	2	D022	-	✓	-	-	-					
23	1014.RM	FL.10	2	D023	-	✓	-	-	-					
24	1016.RM	FL.10	2	D024	-	✓	-	-	-					
25	1018.RM	FL.10	2	D025	-	✓	-	-	-				✓	
26	1020.RM	FL.10	2	D026	-	✓	-	-	-					
27	1019.RM	FL.10	2	D027	-	✓	-	-	-					
28	1017.RM	FL.10	2	D028	-	✓	-	-	-					
29	1015.RM	FL.10	2	D029	-	✓	-	-	-				✓	
30	1012.RM	FL.10	2	D030	-	✓	-	-	-					
31	1112.RM	FL.11	2	D031	-	✓	-	-	-				✓	
32	1111.RM	FL.11	2	D032	-	✓	-	-	-					
33	1110.RM	FL.11	2	D033	-	✓	-	-	-				✓	
34	1109.RM	FL.11	2	D034	-	✓	-	-	-				✓	
35	1108.RM	FL.11	2	D035	-	✓	-	-	-				✓	
36	1107.RM	FL.11	2	D036	-	✓	-	-	-				✓	
37	1106.RM	FL.11	2	D037	-	✓	-	-	-				✓	
38	1114.RM	FL.11	2	D038	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
39	1116.RM	FL.11	2	D039	-	✓	-	-	-				✓	
40	1118.RM	FL.11	2	D040	-	✓	-	-	-				✓	
41	1120.RM	FL.11	2	D041	-	✓	-	-	-					
42	1119.RM	FL.11	2	D042	-	✓	-	-	-					
43	1117.RM	FL.11	2	D043	-	✓	-	-	-				✓	
44	1115.RM	FL.11	2	D044	-	✓	-	-	-				✓	
45	1101.RM	FL.11	2	D045	-	✓	-	-	-					
46	1102.RM	FL.11	2	D046	-	✓	-	-	-					
47	1103.RM	FL.11	2	D047	-	✓	-	-	-				✓	
48	1104.RM	FL.11	2	D048	-	✓	-	-	-	✓			✓	
49	1105.RM	FL.11	2	D049	-	✓	-	-	-					
50	1105.RM	FL.11	2	D050	-	✓	-	-	-					
51	1212.RM	FL.12	2	D051	-	✓	-	-	-				✓	
52	1211.RM	FL.12	2	D052	-	✓	-	-	-					
53	1210.RM	FL.12	2	D053	-	✓	-	-	-					
54	1209.RM	FL.12	2	D054	-	✓	-	-	-					
55	1208.RM	FL.12	2	D055	-	✓	-	-	-				✓	
56	1207.RM	FL.12	2	D056	-	✓	-	-	-				✓	
57	1206.RM	FL.12	2	D057	-	✓	-	-	-					
58	1214.RM	FL.12	2	D058	-	✓	-	-	-				✓	
59	1216.RM	FL.12	2	D059	-	✓	-	-	-					
60	1218.RM	FL.12	2	D060	-	✓	-	-	-				✓	
61	1220.RM	FL.12	2	D061	-	✓	-	-	-				✓	
62	1219.RM	FL.12	2	D062	-	✓	-	-	-					
63	1217.RM	FL.12	2	D063	-	✓	-	-	-				✓	
64	1215.RM	FL.12	2	D064	-	✓	-	-	-					
65	1201.RM	FL.12	2	D065	-	✓	-	-	-					
66	1202.RM	FL.12	2	D066	-	✓	-	-	-					
67	1203.RM	FL.12	2	D067	-	✓	-	-	-					
68	1204.RM	FL.12	2	D068	-	✓	-	-	-					
69	1205.RM	FL.12	2	D069	-	✓	-	-	-					
70	1205.RM	FL.12	2	D070	-	✓	-	-	-					
71	1412.RM	FL.14	2	D071	-	✓	-	-	-				✓	
72	1411.RM	FL.14	2	D072	-	✓	-	-	-				✓	
73	1410.RM	FL.14	2	D073	-	✓	-	-	-					
74	1409.RM	FL.14	2	D074	-	✓	-	-	-				✓	
75	1408.RM	FL.14	2	D075	-	✓	-	-	-				✓	
76	1407.RM	FL.14	2	D076	-	✓	-	-	-				✓	

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
77	1406.RM	FL.14	2	D077	-	✓	-	-	-					
78	1414.RM	FL.14	2	D078	-	✓	-	-	-				✓	
79	1416.RM	FL.14	2	D079	-	✓	-	-	-				✓	
80	1418.RM	FL.14	2	D080	-	✓	-	-	-				✓	
81	1420.RM	FL.14	2	D081	-	✓	-	-	-				✓	
82	1419.RM	FL.14	2	D082	-	✓	-	-	-				✓	
83	1417.RM	FL.14	2	D083	-	✓	-	-	-				✓	
84	1415.RM	FL.14	2	D084	-	✓	-	-	-				✓	
85	1401.RM	FL.14	2	D085	-	✓	-	-	-				✓	
86	1402.RM	FL.14	2	D086	-	✓	-	-	-					
87	1403.RM	FL.14	2	D087	-	✓	-	-	-					
88	1404.RM	FL.14	2	D088	-	✓	-	-	-					
89	1405.RM	FL.14	2	D089	-	✓	-	-	-					
90	1405.RM	FL.14	2	D090	-	✓	-	-	-					
91	1512.RM	FL.15	3	D001	-	✓	-	-	-					
92	1511.RM	FL.15	3	D002	-	✓	-	-	-					
93	1510.RM	FL.15	3	D003	-	✓	-	-	-					
94	1509.RM	FL.15	3	D004	-	✓	-	-	-				✓	
95	1508.RM	FL.15	3	D005	-	✓	-	-	-				✓	
96	1507.RM	FL.15	3	D006	-	✓	-	-	-				✓	
97	1506.RM	FL.15	3	D007	-	✓	-	-	-					
98	1514.RM	FL.15	3	D008	-	✓	-	-	-					
99	1516.RM	FL.15	3	D009	-	✓	-	-	-					
100	1518.RM	FL.15	3	D010	-	✓	-	-	-				✓	
101	1520.RM	FL.15	3	D011	-	✓	-	-	-					
102	1519.RM	FL.15	3	D012	-	✓	-	-	-				✓	
103	1517.RM	FL.15	3	D013	-	✓	-	-	-				✓	
104	1515.RM	FL.15	3	D014	-	✓	-	-	-				✓	
105	1501.RM	FL.15	3	D015	-	✓	-	-	-				✓	
106	1502.RM	FL.15	3	D016	-	✓	-	-	-				✓	
107	1503.RM	FL.15	3	D017	-	✓	-	-	-				✓	
108	1504.RM	FL.15	3	D018	-	✓	-	-	-				✓	
109	1505.RM	FL.15	3	D019	-	✓	-	-	-				✓	
110	1505.RM	FL.15	3	D020	-	✓	-	-	-				✓	
111	1612.RM	FL.16	3	D021	-	✓	-	-	-				✓	
112	1611.RM	FL.16	3	D022	-	✓	-	-	-					
113	1610.RM	FL.16	3	D023	-	✓	-	-	-					
114	1609.RM	FL.16	3	D024	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องวง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
115	1608.RM	FL.16	3	D025	-	✓	-	-	-					
116	1607.RM	FL.16	3	D026	-	✓	-	-	-					
117	1606.RM	FL.16	3	D027	-	✓	-	-	-					
118	1614.RM	FL.16	3	D028	-	✓	-	-	-					
119	1616.RM	FL.16	3	D029	-	✓	-	-	-					
120	1618.RM	FL.16	3	D030	-	✓	-	-	-				✓	
121	1620.RM	FL.16	3	D031	-	✓	-	-	-					
122	1619.RM	FL.16	3	D032	-	✓	-	-	-				✓	
123	1617.RM	FL.16	3	D033	-	✓	-	-	-					
124	1615.RM	FL.16	3	D034	-	✓	-	-	-					
125	1601.RM	FL.16	3	D035	-	✓	-	-	-					
126	1602.RM	FL.16	3	D036	-	✓	-	-	-					
127	1603.RM	FL.16	3	D037	-	✓	-	-	-					
128	1604.RM	FL.16	3	D038	-	✓	-	-	-					
129	1605.RM	FL.16	3	D039	-	✓	-	-	-					
130	1605.RM	FL.16	3	D040	-	✓	-	-	-					
131	1712.RM	FL.17	3	D041	-	✓	-	-	-					
132	1711.RM	FL.17	3	D042	-	✓	-	-	-					
133	1710.RM	FL.17	3	D043	-	✓	-	-	-					
134	1709.RM	FL.17	3	D044	-	✓	-	-	-					
135	1708.RM	FL.17	3	D045	-	✓	-	-	-				✓	
136	1707.RM	FL.17	3	D046	-	✓	-	-	-				✓	
137	1706.RM	FL.17	3	D047	-	✓	-	-	-					
138	1714.RM	FL.17	3	D048	-	✓	-	-	-					
139	1716.RM	FL.17	3	D049	-	✓	-	-	-					
140	1718.RM	FL.17	3	D050	-	✓	-	-	-				✓	
141	1720.RM	FL.17	3	D051	-	✓	-	-	-				✓	
142	1719.RM	FL.17	3	D052	-	✓	-	-	-					
143	1717.RM	FL.17	3	D053	-	✓	-	-	-					
144	1715.RM	FL.17	3	D054	-	✓	-	-	-					
145	1701.RM	FL.17	3	D055	-	✓	-	-	-					
146	1702.RM	FL.17	3	D056	-	✓	-	-	-					
147	1703.RM	FL.17	3	D057	-	✓	-	-	-				✓	
148	1704.RM	FL.17	3	D058	-	✓	-	-	-				✓	
149	1705.RM	FL.17	3	D059	-	✓	-	-	-					
150	1705.RM	FL.17	3	D060	-	✓	-	-	-					
151	1812.RM	FL.18	3	D061	-	✓	-	-	-					
152	1811.RM	FL.18	3	D062	-	✓	-	-	-				✓	

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องวง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
153	1810.RM	FL.18	3	D063	-	✓	-	-	-					
154	1809.RM	FL.18	3	D064	-	✓	-	-	-					
155	1808.RM	FL.18	3	D065	-	✓	-	-	-				✓	
156	1807.RM	FL.18	3	D066	-	✓	-	-	-					
157	1806.RM	FL.18	3	D067	-	✓	-	-	-				✓	
158	1814.RM	FL.18	3	D068	-	✓	-	-	-					
159	1816.RM	FL.18	3	D069	-	✓	-	-	-					
160	1818.RM	FL.18	3	D070	-	✓	-	-	-				✓	
161	1820.RM	FL.18	3	D071	-	✓	-	-	-					
162	1819.RM	FL.18	3	D072	-	✓	-	-	-				✓	
163	1817.RM	FL.18	3	D073	-	✓	-	-	-					
164	1815.RM	FL.18	3	D074	-	✓	-	-	-					
165	1801.RM	FL.18	3	D075	-	✓	-	-	-					
166	1802.RM	FL.18	3	D076	-	✓	-	-	-					
167	1803.RM	FL.18	3	D077	-	✓	-	-	-					
168	1804.RM	FL.18	3	D078	-	✓	-	-	-					
169	1805.RM	FL.18	3	D079	-	✓	-	-	-					
170	1805.RM	FL.18	3	D080	-	✓	-	-	-					
171	1912.RM	FL.19	4	D001	-	✓	-	-	-					
172	1911.RM	FL.19	4	D002	-	✓	-	-	-					
173	1910.RM	FL.19	4	D003	-	✓	-	-	-					
174	1909.RM	FL.19	4	D004	-	✓	-	-	-				✓	
175	1908.RM	FL.19	4	D005	-	✓	-	-	-				✓	
176	1907.RM	FL.19	4	D006	-	✓	-	-	-					
177	1906.RM	FL.19	4	D007	-	✓	-	-	-					
178	1914.RM	FL.19	4	D008	-	✓	-	-	-					
179	1916.RM	FL.19	4	D009	-	✓	-	-	-				✓	
180	1918.RM	FL.19	4	D010	-	✓	-	-	-				✓	
181	1920.RM	FL.19	4	D011	-	✓	-	-	-					
182	1919.RM	FL.19	4	D012	-	✓	-	-	-				✓	
183	1917.RM	FL.19	4	D013	-	✓	-	-	-				✓	
184	1915.RM	FL.19	4	D014	-	✓	-	-	-					
185	1901.RM	FL.19	4	D015	-	✓	-	-	-				✓	
186	1902.RM	FL.19	4	D016	-	✓	-	-	-					
187	1903.RM	FL.19	4	D017	-	✓	-	-	-				✓	
188	1904.RM	FL.19	4	D018	-	✓	-	-	-					
189	1905.RM	FL.19	4	D019	-	✓	-	-	-				✓	
190	1905.RM	FL.19	4	D020	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องวง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
191	2012.RM	FL.20	4	D021	-	✓	-	-	-					
192	2011.RM	FL.20	4	D022	-	✓	-	-	-					
193	2010.RM	FL.20	4	D023	-	✓	-	-	-					
194	2009.RM	FL.20	4	D024	-	✓	-	-	-					
195	2008.RM	FL.20	4	D025	-	✓	-	-	-				✓	
196	2007.RM	FL.20	4	D026	-	✓	-	-	-					
197	2006.RM	FL.20	4	D027	-	✓	-	-	-					
198	2014.RM	FL.20	4	D028	-	✓	-	-	-					
199	2016.RM	FL.20	4	D029	-	✓	-	-	-					
200	2018.RM	FL.20	4	D030	-	✓	-	-	-				✓	
201	2020.RM	FL.20	4	D031	-	✓	-	-	-					
202	2019.RM	FL.20	4	D032	-	✓	-	-	-					
203	2017.RM	FL.20	4	D033	-	✓	-	-	-					
204	2015.RM	FL.20	4	D034	-	✓	-	-	-				✓	
205	2001.RM	FL.20	4	D035	-	✓	-	-	-					
206	2002.RM	FL.20	4	D036	-	✓	-	-	-					
207	2003.RM	FL.20	4	D037	-	✓	-	-	-					
208	2004.RM	FL.20	4	D038	-	✓	-	-	-					
209	2005.RM	FL.20	4	D039	-	✓	-	-	-					
210	2005.RM	FL.20	4	D040	-	✓	-	-	-					
211	2112.RM	FL.21	4	D041	-	✓	-	-	-					
212	2111.RM	FL.21	4	D042	-	✓	-	-	-					
213	2110.RM	FL.21	4	D043	-	✓	-	-	-					
214	2108.RM	FL.21	4	D044	-	✓	-	-	-					
215	2108.RM	FL.21	4	D045	-	✓	-	-	-					
216	2107.RM	FL.21	4	D046	-	✓	-	-	-					
217	2106.RM	FL.21	4	D047	-	✓	-	-	-					
218	2114.RM	FL.21	4	D048	-	✓	-	-	-					
219	2116.RM	FL.21	4	D049	-	✓	-	-	-					
220	2118.RM	FL.21	4	D050	-	✓	-	-	-				✓	
221	2120.RM	FL.21	4	D051	-	✓	-	-	-				✓	
222	2119.RM	FL.21	4	D052	-	✓	-	-	-					
223	2117.RM	FL.21	4	D053	-	✓	-	-	-				✓	
224	2115.RM	FL.21	4	D054	-	✓	-	-	-					
225	2101.RM	FL.21	4	D055	-	✓	-	-	-				✓	
226	2102.RM	FL.21	4	D056	-	✓	-	-	-					
227	2103.RM	FL.21	4	D057	-	✓	-	-	-					
228	2104.RM	FL.21	4	D058	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องวง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
229	2105.RM	FL.21	4	D059	-	✓	-	-	-					
230	2105.RM	FL.21	4	D060	-	✓	-	-	-					
231	2212.RM	FL.22	4	D061	-	✓	-	-	-					
232	2211.RM	FL.22	4	D062	-	✓	-	-	-					
233	2210.RM	FL.22	4	D063	-	✓	-	-	-					
234	2208.RM	FL.22	4	D064	-	✓	-	-	-					
235	2208.RM	FL.22	4	D065	-	✓	-	-	-					
236	2207.RM	FL.22	4	D066	-	✓	-	-	-				✓	
237	2206.RM	FL.22	4	D067	-	✓	-	-	-					
238	2214.RM	FL.22	4	D068	-	✓	-	-	-					
239	2216.RM	FL.22	4	D069	-	✓	-	-	-					
240	2218.RM	FL.22	4	D070	-	✓	-	-	-				✓	
241	2220.RM	FL.22	4	D071	-	✓	-	-	-					
242	2219.RM	FL.22	4	D072	-	✓	-	-	-					
243	2217.RM	FL.22	4	D073	-	✓	-	-	-				✓	
244	2215.RM	FL.22	4	D074	-	✓	-	-	-				✓	
245	2201.RM	FL.22	4	D075	-	✓	-	-	-					
246	2202.RM	FL.22	4	D076	-	✓	-	-	-					
247	2203.RM	FL.22	4	D077	-	✓	-	-	-					
248	2204.RM	FL.22	4	D078	-	✓	-	-	-				✓	
249	2205.RM	FL.22	4	D079	-	✓	-	-	-					
250	2205.RM	FL.22	4	D080	-	✓	-	-	-					
251	2312.RM	FL.23	5	D001	-	✓	-	-	-					
252	2311.RM	FL.23	5	D002	-	✓	-	-	-					
253	2310.RM	FL.23	5	D003	-	✓	-	-	-					
254	2308.RM	FL.23	5	D004	-	✓	-	-	-					
255	2308.RM	FL.23	5	D005	-	✓	-	-	-					
256	2307.RM	FL.23	5	D006	-	✓	-	-	-					
257	2306.RM	FL.23	5	D007	-	✓	-	-	-					
258	2314.RM	FL.23	5	D008	-	✓	-	-	-					
259	2316.RM	FL.23	5	D009	-	✓	-	-	-				✓	
260	2318.RM	FL.23	5	D010	-	✓	-	-	-				✓	
261	2320.RM	FL.23	5	D011	-	✓	-	-	-				✓	
262	2319.RM	FL.23	5	D012	-	✓	-	-	-				✓	
263	2317.RM	FL.23	5	D013	-	✓	-	-	-					
264	2315.RM	FL.23	5	D014	-	✓	-	-	-					
265	2301.RM	FL.23	5	D015	-	✓	-	-	-					
266	2302.RM	FL.23	5	D016	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
267	2303.RM	FL.23	5	D017	-	✓	-	-	-				✓	
268	2304.RM	FL.23	5	D018	-	✓	-	-	-					
269	2305.RM	FL.23	5	D019	-	✓	-	-	-					
270	2305.RM	FL.23	5	D020	-	✓	-	-	-					
271	2412.RM	FL.24	5	D021	-	✓	-	-	-					
272	2411.RM	FL.24	5	D022	-	✓	-	-	-					
273	2410.RM	FL.24	5	D023	-	✓	-	-	-					
274	2408.RM	FL.24	5	D024	-	✓	-	-	-					
275	2408.RM	FL.24	5	D025	-	✓	-	-	-					
276	2407.RM	FL.24	5	D026	-	✓	-	-	-	✓				
277	2406.RM	FL.24	5	D027	-	✓	-	-	-					
278	2414.RM	FL.24	5	D028	-	✓	-	-	-					
279	2416.RM	FL.24	5	D029	-	✓	-	-	-				✓	
280	2418.RM	FL.24	5	D030	-	✓	-	-	-				✓	
281	2420.RM	FL.24	5	D031	-	✓	-	-	-					
282	2419.RM	FL.24	5	D032	-	✓	-	-	-				✓	
283	2417.RM	FL.24	5	D033	-	✓	-	-	-					
284	2415.RM	FL.24	5	D034	-	✓	-	-	-					
285	2401.RM	FL.24	5	D035	-	✓	-	-	-					
286	2402.RM	FL.24	5	D036	-	✓	-	-	-					
287	2403.RM	FL.24	5	D037	-	✓	-	-	-					
288	2404.RM	FL.24	5	D038	-	✓	-	-	-					
289	2405.RM	FL.24	5	D039	-	✓	-	-	-					
290	2405.RM	FL.24	5	D040	-	✓	-	-	-					
291	2512.RM	FL.25	5	D041	-	✓	-	-	-					
292	2511.RM	FL.25	5	D042	-	✓	-	-	-					
293	2510.RM	FL.25	5	D043	-	✓	-	-	-					
294	2508.RM	FL.25	5	D044	-	✓	-	-	-					
295	2508.RM	FL.25	5	D045	-	✓	-	-	-					
296	2507.RM	FL.25	5	D046	-	✓	-	-	-					
297	2506.RM	FL.25	5	D047	-	✓	-	-	-					
298	2514.RM	FL.25	5	D048	-	✓	-	-	-					
299	2516.RM	FL.25	5	D049	-	✓	-	-	-					
300	2518.RM	FL.25	5	D050	-	✓	-	-	-					
301	2520.RM	FL.25	5	D051	-	✓	-	-	-					
302	2519.RM	FL.25	5	D052	-	✓	-	-	-					
303	2517.RM	FL.25	5	D053	-	✓	-	-	-					
304	2515.RM	FL.25	5	D054	-	✓	-	-	-				✓	

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
305	2501.RM	FL.25	5	D055	-	✓	-	-	-					
306	2502.RM	FL.25	5	D056	-	✓	-	-	-					
307	2503.RM	FL.25	5	D057	-	✓	-	-	-				✓	
308	2504.RM	FL.25	5	D058	-	✓	-	-	-				✓	
309	2505.RM	FL.25	5	D059	-	✓	-	-	-					
310	2505.RM	FL.25	5	D060	-	✓	-	-	-					
311	2612.RM	FL.26	5	D061	-	✓	-	-	-					
312	2611.RM	FL.26	5	D062	-	✓	-	-	-					
313	2610.RM	FL.26	5	D063	-	✓	-	-	-					
314	2609.RM	FL.26	5	D064	-	✓	-	-	-					
315	2608.RM	FL.26	5	D065	-	✓	-	-	-				✓	
316	2607.RM	FL.26	5	D066	-	✓	-	-	-					
317	2606.RM	FL.26	5	D067	-	✓	-	-	-					
318	2614.RM	FL.26	5	D068	-	✓	-	-	-					
319	2616.RM	FL.26	5	D069	-	✓	-	-	-					
320	2618.RM	FL.26	5	D070	-	✓	-	-	-					
321	2620.RM	FL.26	5	D071	-	✓	-	-	-					
322	2615.RM	FL.26	5	D072	-	✓	-	-	-					
323	2615.RM	FL.26	5	D073	-	✓	-	-	-					
324	2601.RM	FL.26	5	D074	-	✓	-	-	-					
325	2602.RM	FL.26	5	D075	-	✓	-	-	-					
326	2603.RM	FL.26	5	D076	-	✓	-	-	-				✓	
327	2604.RM	FL.26	5	D077	-	✓	-	-	-				✓	
328	2605.RM	FL.26	5	D078	-	✓	-	-	-					
329	2605.RM	FL.26	5	D079	-	✓	-	-	-					
330	2712.RM	FL.27	6	D001	-	✓	-	-	-					
331	2707.RM	FL.27	6	D002	-	✓	-	-	-					
332	2707.RM	FL.27	6	D003	-	✓	-	-	-					
333	2707.RM	FL.27	6	D004	-	✓	-	-	-					
334	2706.RM	FL.27	6	D005	-	✓	-	-	-					
335	27014.RM	FL.27	6	D006	-	✓	-	-	-					
336	2716.RM	FL.27	6	D007	-	✓	-	-	-					
337	2718.RM	FL.27	6	D008	-	✓	-	-	-				✓	
338	2715.RM	FL.27	6	D009	-	✓	-	-	-					
339	2715.RM	FL.27	6	D010	-	✓	-	-	-				✓	
340	2701.RM	FL.27	6	D011	-	✓	-	-	-					
341	2702.RM	FL.27	6	D012	-	✓	-	-	-					
342	2703.RM	FL.27	6	D013	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
343	2704.RM	FL.27	6	D014	-	✓	-	-	-					
344	2705.RM	FL.27	6	D015	-	✓	-	-	-					
345	2705.RM	FL.27	6	D016	-	✓	-	-	-					
346	2812.RM	FL.28	6	D017	-	✓	-	-	-					
347	2810.RM	FL.28	6	D018	-	✓	-	-	-					
348	2808.RM	FL.28	6	D019	-	✓	-	-	-					
349	2808.RM	FL.28	6	D020	-	✓	-	-	-					
350	2807.RM	FL.28	6	D021	-	✓	-	-	-					
351	2806.RM	FL.28	6	D022	-	✓	-	-	-					
352	2814.RM	FL.28	6	D023	-	✓	-	-	-					
353	2816.RM	FL.28	6	D024	-	✓	-	-	-				✓	
354	2818.RM	FL.28	6	D025	-	✓	-	-	-				✓	
355	2815.RM	FL.28	6	D026	-	✓	-	-	-				✓	
356	2815.RM	FL.28	6	D027	-	✓	-	-	-				✓	
357	2801.RM	FL.28	6	D028	-	✓	-	-	-					
358	2802.RM	FL.28	6	D029	-	✓	-	-	-					
359	2803.RM	FL.28	6	D030	-	✓	-	-	-					
360	2804.RM	FL.28	6	D031	-	✓	-	-	-				✓	
361	2805.RM	FL.28	6	D032	-	✓	-	-	-					
362	2805.RM	FL.28	6	D033	-	✓	-	-	-					
363	2912.RM	FL.29	6	D034	-	✓	-	-	-					
364	2910.RM	FL.29	6	D035	-	✓	-	-	-					
365	2908.RM	FL.29	6	D036	-	✓	-	-	-					
366	2908.RM	FL.29	6	D037	-	✓	-	-	-					
367	2907.RM	FL.29	6	D038	-	✓	-	-	-					
368	2906.RM	FL.29	6	D039	-	✓	-	-	-					
369	2914.RM	FL.29	6	D040	-	✓	-	-	-					
370	2916.RM	FL.29	6	D041	-	✓	-	-	-					
371	2916.RM	FL.29	6	D042	-	✓	-	-	-					
372	2915.RM	FL.29	6	D043	-	✓	-	-	-					
373	2915.RM	FL.29	6	D044	-	✓	-	-	-					
374	2901.RM	FL.29	6	D045	-	✓	-	-	-				✓	
375	2902.RM	FL.29	6	D046	-	✓	-	-	-				✓	
376	2903.RM	FL.29	6	D047	-	✓	-	-	-				✓	
377	2904.RM	FL.29	6	D048	-	✓	-	-	-					
378	2905.RM	FL.29	6	D049	-	✓	-	-	-					
379	2905.RM	FL.29	6	D050	-	✓	-	-	-					
380	3012.RM	FL.30	6	D051	-	✓	-	-	-				✓	

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS


10-12 มิถุนายน 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
381	3007.RM	FL.30	6	D052	-	✓	-	-	-					
382	3007.RM	FL.30	6	D053	-	✓	-	-	-					
383	3007.RM	FL.30	6	D054	-	✓	-	-	-					
384	3016.RM	FL.30	6	D055	-	✓	-	-	-				✓	
385	3016.RM	FL.30	6	D056	-	✓	-	-	-					
386	3001.RM	FL.30	6	D058	-	✓	-	-	-					
387	3001.RM	FL.30	6	D059	-	✓	-	-	-				✓	
388	3003.RM	FL.30	6	D060	-	✓	-	-	-				✓	
389	3004.RM	FL.30	6	D061	-	✓	-	-	-					
390	3004.RM	FL.30	6	D062	-	✓	-	-	-					
391	PRIVATE DINNING	FL.32	6	D063	-	✓	-	-	-					
392	LIFT LOBBY	FL.32	6	D064	-	✓	-	-	-					
393	LIBRARY	FL.32	6	D065	-	✓	-	-	-	✓				
394	LIBRARY	FL.32	6	D066	-	✓	-	-	-					
395	EE/RM.	FL.32	6	D067	-	✓	-	-	-					

Maintenance Equipment for Fire Alarm Systems
(การตรวจสอบเชิงบำรุงรักษา อุปกรณ์และระบบสัญญาณแจ้งเตือนเหตุเพลิงไหม้)

Control Panel (ตู้ควบคุมระบบ)

- Check the signal cable connection point on the circuit board in the control panel that receives the signal from the Detector device of the system.
  ตรวจเช็คจุดเชื่อมต่อสายสัญญาณที่ตู้ควบคุมทำหน้าที่รับและส่งสัญญาณจากอุปกรณ์ตรวจจับในระบบ
- Check the power supply and battery. By checking the terminals and measuring the input voltage of the battery.
  ตรวจเช็คแหล่งจ่ายไฟและ แบตเตอรี่ โดยตรวจสอบขั้วต่อสายพร้อมวัดแรงดันไฟฟ้าเข้าของแบตเตอรี่
- Check the integrity of the display and notifications LED.
  ตรวจเช็คความสมบูรณ์ของจอแสดงผลและ LED แจ้งเตือน
- Check the integrity of the operation switch and response to function.
  ตรวจเช็คความสมบูรณ์ของสวิตช์ควบคุมการทำงานและการตอบสนองฟังก์ชั่นการทำงาน
- Clean the control panel in ready to use.
  ทำความสะอาดตู้ควบคุม ให้อยู่ในสภาพที่พร้อมใช้งาน



38/873 ถ.ไทยรามัญ แขวงสามวาตะวันตก เขตคลองสามวา กรุงเทพฯ 10510
38/873 THAIRAMAN ROAD, SAMWATAWANTOK, KHLONGSAMWA BANGKOK 10510 TEL 02-548-6074 FAX 02-509-0049
Email : fwss_alarm@hotmail.comwww.fwssthailand.com

FIRE ALARM SYSTEM
FIRE WORK SYSTEM & SERVICE CO., LTD.
บริษัท ไฟร์ เวิร์ค ซิสเต็ม แอนด์ เซอร์วิส จำกัด

Maintenance Equipment for Fire Alarm Systems
(การตรวจสอบเชิงบำรุงรักษา อุปกรณ์และระบบสัญญาณแจ้งเตือนเหตุเพลิงไหม้)

Graphic Annunciator (ตู้แผนผังแสดงจุดที่มีการแจ้งเตือนเหตุ)

- Check the LED indicator. And the signaling device sends alarm signals from the circuit (Buzzer). From the cabinet, the map displays the points that are being notified (Graphic Annunciator). Be in ready to use.
  ตรวจเช็คหลอดไฟ LED และอุปกรณ์ส่งสัญญาณจะส่งสัญญาณเตือนจากวงจร(Buzzer)จากตู้แผนผังแสดงจุดที่มีการแจ้งให้เตือนจากระบบ (Graphic Annunciator) ให้อยู่ในสภาพพร้อมใช้งาน
- Clean the Graphic Annunciator cabinet to be in a ready-to-use condition
  ทำความสะอาดตู้แผนผังแสดงจุดที่มีการแจ้ง ให้อยู่ในสภาพที่พร้อมใช้งาน




38/873 ถ.ไทยรามัญ แขวงสามวาตะวันตก เขตคลองสามวา กรุงเทพฯ 10510
38/873 THAIRAMAN ROAD, SAMWATAWANTOK, KHLONGSAMWA BANGKOK 10510 TEL 02-548-6074 FAX 02-509-0049
Email : fwss_alarm@hotmail.comwww.fwssthailand.com

FIRE ALARM SYSTEM
FIRE WORK SYSTEM & SERVICE CO., LTD.
บริษัท ไฟร์ เวิร์ค ซิสเต็ม แอนด์ เซอร์วิส จำกัด

Maintenance Equipment for Fire Alarm Systems
(การตรวจสอบเชิงบำรุงรักษา อุปกรณ์และระบบสัญญาณแจ้งเตือนเหตุเพลิงไหม้)

Smoke Detector (อุปกรณ์ตรวจจับควันไฟ)

- The test uses a simulated smoke generator, such as a Smoke tester, to test detection and the response signal is sent back to the Control panel and displayed to other peripherals in the system.
  การทดสอบจะใช้อุปกรณ์สร้างควันจำลอง เช่น สเปรย์ควันทดลองเพื่อทดสอบการตรวจจับและการส่งสัญญาณตอบสนองกลับไปที่ตู้ควบคุมและแสดงผลไปที่อุปกรณ์ต่อพ่วงอื่นๆ ในระบบ




38/873 ถ.ไทยรามัญ แขวงสามวาตะวันตก เขตคลองสามวา กรุงเทพฯ 10510
38/873 THAIRAMAN ROAD, SAMWATAWANTOK, KHLONGSAMWA BANGKOK 10510 TEL 02-548-6074 FAX 02-509-0049
Email : fwss_alarm@hotmail.comwww.fwssthailand.com

FIRE ALARM SYSTEM
FIRE WORK SYSTEM & SERVICE CO., LTD.
บริษัท ไฟร์ เวิร์ค ซิสเต็ม แอนด์ เซอร์วิส จำกัด

Maintenance Equipment for Fire Alarm Systems
(การตรวจสอบเชิงบำรุงรักษา อุปกรณ์และระบบสัญญาณแจ้งเตือนเหตุเพลิงไหม้)

Manual Station(อุปกรณ์แจ้งเหตุด้วยมือผู้ใช้)

- Test user notification device (Manual Station). By testing the availability of equipment various with actual use. Such as pulling the lever (Pull Down), Push Button or break the glass to break (Break glass). To inform according to the usage of the device
  ทดสอบอุปกรณ์แจ้งเหตุด้วยมือผู้ใช้ (Manual Station) โดยทดสอบความพร้อมของอุปกรณ์ต่างๆ ด้วยการใช้งานจริง เช่น การดึงคันโยก (Pull Down) การกดปุ่ม (Push Button) หรือทุบกระจกให้แตก (Break glass) เพื่อแจ้งเหตุตามลักษณะการใช้งานของอุปกรณ์
- Cleaning equipment.
  ทำความสะอาดอุปกรณ์




38/873 ถ.ไทยรามัญ แขวงสามวาตะวันตก เขตคลองสามวา กรุงเทพฯ 10510
38/873 THAIRAMAN ROAD, SAMWATAWANTOK, KHLONGSAMWA BANGKOK 10510 TEL 02-548-6074 FAX 02-509-0049
Email : fwss_alarm@hotmail.comwww.fwssthailand.com

Maintenance Equipment for Fire Alarm Systems
(การตรวจสอบเชิงบำรุงรักษา อุปกรณ์และระบบสัญญาณแจ้งเตือนเหตุเพลิงไหม้)

ตู้ควบคุมระบบ Fire Alarm Control Panel
ตู้แสดง Graphic Annunciator

- Check the control panel of the receiving signal system is stuck.
  ตรวจเช็คแผงควบคุมระบบรับสัญญาณ LED ติดค้าง ปกติ
- Check the notification sound Fire incident
  ตรวจเช็คเสียงแจ้งเตือน การเกิดเหตุเพลิงไหม้
- Test of Receive-send signal between the control cabinet, send signal to the cabinet, map showing the incident spot Fire displays. The notification (LED) and computers (PC) in the event of a fire.
  ทดสอบการ รับ-ส่ง สัญญาณระหว่างตู้ควบคุมส่งสัญญาณไปยังตู้แผนผังแสดงจุดเกิดเหตุ
  เพลิงไหม้ LED แจ้งเตือน และ คอมพิวเตอร์ (PC) เมื่อเกิดเหตุเพลิงไหม้
- Show status and location map to match the location of the incident.
  แสดงสถานะแจ้ง Location Map ตรงตามตำแหน่งที่เกิดเหตุ




38/873 ถ.ไทยรามัญ แขวงสามวาตะวันตก เขตคลองสามวา กรุงเทพฯ 10510
38/873 THAIRAMAN ROAD, SAMWATAWANTOK, KHLONGSAMWA BANGKOK 10510 TEL 02-548-6074 FAX 02-509-0049
Email : fwss_alarm@hotmail.comwww.fwssthailand.com

ภาคผนวก

อุปกรณ์ที่ใช้ในการทดสอบ SMOKE DETECTOR



อุปกรณ์ที่ใช้ในการทดสอบ HEAT DETECTOR



อุปกรณ์ที่ใช้ในการทดสอบ

Solo 100/101/108 Telescopic Access Poles

The core element of the Solo range is the telescopic and extension access poles which are extremely lightweight and quickly extend to provide access to detectors up to 9 metres*.



สเปรย์ควันเทียมทดสอบ SMOKE DETECTOR



อุปกรณ์ที่ใช้ในการปฏิบัติงาน



มิเตอร์ดิจิตอล



วิทยุสื่อสาร



บันได



ปลั๊กไฟพ่วง



ชุดไขควง



ชุดคีม

อุปกรณ์ที่ใช้ในการทำความสะอาด



ครีมทำความสะอาด



แปรงทำความสะอาดอุปกรณ์



ผ้าทำความสะอาดอุปกรณ์




โบเวอร์

PREVENTIVE MAINTENANCE AND TESTING REPORT

FIRE ALARM SYSTEM

SOFITEL BANGKOK SUKHUMVIT HOTEL



TEST 3/4

19 - 20 MARCH 2026

FWSS

FIRE WORK SYSTEM & SERVICE CO., LTD.

Fire Alarm System

Operation & Data Testing Report
Fire Alarm System

FIRE WORK SYSTEM & SERVICE

OPERATION & DATA TEST REPORT

FIRE ALARM SYSTEM

DATE : 19- 20 มีนาคม 2569

TIME : 09.00 - 17.00 น.

System : ระบบสัญญาณแจ้งเหตุเพลิงไหม้

Subject : งานบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้

Location : SOFITEL BANGKOK SUKHUMVIT HOTEL **Operator** :

Telephone : 02-246-2323 ต่อ 1803

Owner contact : SOFITEL BANGKOK SUKHUMVIT HOTEL

Address : 189 ถนนสุขุมวิท ซอย 13-15 แขวงคลองเตยเหนือ เขตวัฒนา กรุงเทพมหานคร 10110

PANEL DESCRIPTION

Panel Manufacturer : NOTIFIER Model : NFS2-3030E

Circuit Styles : Class A

Last date system had any sevice performed : 24 December 2025

Last date that any software or configuration was revised :

Location (Panel Number) : Control Room, 5th Floor

System Capacity

- Intelligent Signaling Line Circu : 6 Loop Style : Class A
- Intelligent Detectors :
- Addressable Monitor/Control Modul :

System Power

- Primary Input Power Voltage : ☐ 110 VAC ☑ 220 VAC
- Total Output 24V Power : ☑ 6 Amps ☐ 10 Amps ☐ 15 Amps ☐ 20 Amps
- Ground Chassis : ☑ Yes ☐ No

Secondary Power Voltage (Back up Battery)

Quantity of : 2 Set

Amp-Hr. rating : 18 Ah

Voltage : 24 VDC

Type of Battery : ☐ Dry Cell ☑ Seal Lead-Acid ☐ Nickel Cadmium ☐ Seal Lead Calcium Batt

FIRE WORK SYSTEM & SERVICE

SYSTEM TESTS AND INSPECTIONS

	Pass	Fail	Comment
Type			
Control Unit	☑	☐	
Interface equipment	☑	☐	
Lamp and LEDs	☑	☐	
Fuses	☑	☐	
Primary (main) power supply	☑	☐	
Trouble signal	☑	☐	
Ground Fault Monitoring	☑	☐	
Secondary Power			
Battery Condition	☑	☐	
Load voltage	☑	☐	
Discharge Test	☑	☐	
Charge Test	☑	☐	
Notification Appliances			
Audible device	☑	☐	
Visual device	☑	☐	

System restored to normal operation Date : 20 March 2026 **Time** : 09.00 am. – 05:00 pm

Comment :

Name of Inspector : [redacted]

Signature :

Name of Owner or Representative SOFITEL BANGKOK SUKHUMVIT HOTEL

THIS TESTING WAS PERFORMED IN ACCORDANCE WITH APPLICABLE NFPA STANDARDS

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
1	BZD1	FL.B	1	M001	-	✓	-	-	-					
2	BZD2	FL.B	1	M002	-	✓	-	-	-					
3	BZD3	FL.B	1	M003	-	✓	-	-	-					
4	GZD1	FL.G	1	M004	-	✓	-	-	-	✓	✓			
5	GZD2	FL.G	1	M005	-	✓	-	-	-			✓		
6	GZD3	FL.G	1	M006	-	✓	-	-	-	✓		✓		
7	BSVS12	FL.B	1	M007	-	✓	-	-	-					
8	BSVS13	FL.B	1	M008	-	✓	-	-	-					
9	2ZD1	FL2.	1	M009	-	✓	-	-	-	✓				
10	2ZD2	FL2.	1	M010	-	✓	-	-	-			✓		
11	2ZD3	FL2.	1	M011	-	✓	-	-	-	✓	✓			
12	2ZD4	FL2.	1	M012	-	✓	-	-	-	✓		✓		
13	3ZD1	FL.3	1	M013	-	✓	-	-	-		✓			
14	3ZD2	FL.3	1	M014	-	-	✓	-	-			✓		
15	3ZD3	FL.3	1	M015	-	✓	-	-	-	✓	✓	✓		
16	3ZD4	FL.3	1	M016	-	✓	-	-	-	✓		✓		
17	3ZD5	FL.3	1	M017	-	✓	-	-	-	✓		✓		
18	4ZD1	FL.4	1	M018	-	✓	-	-	-					
19	4ZD2	FL.4	1	M019	-	✓	-	-	-					
20	4ZD3	FL.4	1	M020	-	✓	-	-	-			✓		
21	4ZD4	FL.4	1	M021	-	✓	-	-	-	✓	✓	✓		
22	4ZD5	FL.4	1	M022	-	✓	-	-	-	✓	✓	✓		
23	4ZD6	FL.4	1	M023	-	✓	-	-	-	✓		✓		
24	5ZD1	FL.5	1	M024	-	✓	-	-	-					
25	5ZD2	FL.5	1	M025	-	✓	-	-	-			✓		
26	5ZD3	FL.5	1	M026	-	✓	-	-	-	✓		✓		
27	5ZD4	FL.5	1	M027	-	✓	-	-	-	✓	✓	✓		
28	5ZD5	FL.5	1	M028	-	✓	-	-	-	✓	✓	✓		
29	5ZD6	FL.5	1	M029	-	✓	-	-	-					
30	7ZD1	FL.7	1	M030	-	✓	-	-	-	✓				
31	7ZD2	FL.7	1	M031	-	✓	-	-	-					
32	7ZD3	FL.7	1	M032	-	✓	-	-	-	✓		✓		
33	7ZD4	FL.7	1	M033	-	✓	-	-	-	✓	✓			
34	7ZD5	FL.7	1	M034	-	✓	-	-	-					
35	6ZD1	FL.6	1	M035	-	✓	-	-	-					
36	6ZD2	FL.6	1	M036	-	✓	-	-	-	✓	✓	✓		
37	6ZD3	FL.6	1	M037	-	✓	-	-	-			✓		
38	6ZD4	FL.6	1	M038	-	✓	-	-	-		✓			

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
39	6ZD5	FL.6	1	M039	-	✓	-	-	-					
40	5PAF1	FL.5	1	M040	-	✓	-	-	-					
41	7PAF1	FL.7	1	M041	-	✓	-	-	-					
42	BZB1	FL.B	1	M045	-	✓	-	-	-					
43	GZB1	FL.G	1	M046	-	✓	-	-	-					
44	2ZB1	FL.2	1	M047	-	✓	-	-	-					
45	3ZB1	FL.3	1	M048	-	✓	-	-	-					
46	4ZB1	FL.4	1	M049	-	✓	-	-	-					
47	4SF1	FL.4	1	M050	-	✓	-	-	-					
48	4LIFT1	FL.4	1	M051	-	✓	-	-	-					
49	5ZB1	FL.5	1	M052	-	✓	-	-	-					
50	7ANSUL	FL.7	1	M053	-	✓	-	-	-					
51	7ANSUL2	FL.7	1	M054	-	✓	-	-	-					
52	7GAS	FL.7	1	M055	-	✓	-	-	-					
53	BSVS11	FL.B	1	M056	-	✓	-	-	-					
54	6ZB1	FL.6	1	M057	-	✓	-	-	-					
55	6SF1	FL.6	1	M058	-	✓	-	-	-					
56	7ZB1	FL.7	1	M060	-	✓	-	-	-					
57	BZAHU1	FL.B	1	M061	-	✓	-	-	-					
58	BLIFT	FL.B	1	M062	-	✓	-	-	-					
59	BSVS10	FL.B	1	M063	-	✓	-	-	-					
60	BSVS2	FL.B	1	M064	-	✓	-	-	-					
61	BSVS3	FL.B	1	M065	-	✓	-	-	-					
62	BSVS4	FL.B	1	M066	-	✓	-	-	-					
63	BSVS5	FL.B	1	M067	-	✓	-	-	-					
64	BSVS6	FL.B	1	M068	-	✓	-	-	-					
65	BSVS7	FL.B	1	M069	-	✓	-	-	-					
66	BSVS8	FL.B	1	M070	-	✓	-	-	-					
67	BSVS9	FL.B	1	M071	-	✓	-	-	-					
68	7ZAHU1	FL.7	1	M072	-	✓	-	-	-					
69	7ZAHU2	FL.7	1	M073	-	✓	-	-	-					
70	6FS01	FL.6	1	M074	-	✓	-	-	-					
71	6FS02	FL.6	1	M075	-	✓	-	-	-					
72	6SS01	FL.6	1	M076	-	✓	-	-	-					
73	6SS02	FL.6	1	M077	-	✓	-	-	-					
74	7ZAHU3	FL.7	1	M078	-	✓	-	-	-					
75	7ZAHU4	FL.7	1	M079	-	✓	-	-	-					
76	BFS01	FL.B	1	M080	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
77	BFS02	FL.B	1	M081	-	✓	-	-	-					
78	BSS01	FL.B	1	M082	-	✓	-	-	-					
79	BSS02	FL.B	1	M083	-	✓	-	-	-					
80	B/STATUS FP1	FL.B	1	M084	-	✓	-	-	-					
81	B/STATUS FP2	FL.B	1	M085	-	✓	-	-	-					
82	B/ALARM JP1	FL.B	1	M086	-	✓	-	-	-					
83	B/ALARM JP2	FL.B	1	M087	-	✓	-	-	-					
84	GFS01	FL.G	1	M088	-	✓	-	-	-					
85	GFS02	FL.G	1	M089	-	✓	-	-	-					
86	GSS01	FL.G	1	M090	-	✓	-	-	-					
87	GSS02	FL.G	1	M091	-	✓	-	-	-					
88	BSVS14	FL.B	1	M092	-	✓	-	-	-					
89	BSVS15	FL.B	1	M093	-	✓	-	-	-					
90	BSVS16	FL.B	1	M094	-	✓	-	-	-					
91	BSVS17	FL.B	1	M095	-	✓	-	-	-					
92	GZAHU1	FL.G	1	M096	-	✓	-	-	-					
93	GZAHU2	FL.G	1	M097	-	✓	-	-	-					
94	GZAHU3	FL.G	1	M098	-	✓	-	-	-					
95	2ZAHU1	FL.2	1	M099	-	✓	-	-	-					
96	2ZAHU2	FL.2	1	M100	-	✓	-	-	-					
97	2ANSUL	FL.2	1	M101	-	✓	-	-	-					
98	2FS01	FL.2	1	M102	-	✓	-	-	-					
99	2FS02	FL.2	1	M103	-	✓	-	-	-					
100	2SS01	FL.2	1	M104	-	✓	-	-	-					
101	2SS02	FL.2	1	M105	-	✓	-	-	-					
102	2GAS	FL.2	1	M106	-	✓	-	-	-					
103	Z3AHU1	FL.3	1	M107	-	✓	-	-	-					
104	Z3AHU2	FL.3	1	M108	-	✓	-	-	-					
105	Z3AHU3	FL.3	1	M109	-	✓	-	-	-					
106	3ANSUL1	FL.3	1	M110	-	✓	-	-	-					
107	3ANSUL2	FL.3	1	M111	-	✓	-	-	-					
108	3FS01	FL.3	1	M112	-	✓	-	-	-					
109	3FS02	FL.3	1	M113	-	✓	-	-	-					
110	3SS01	FL.3	1	M114	-	✓	-	-	-					
111	3SS02	FL.3	1	M115	-	✓	-	-	-					
112	3ANUSUL3	FL.3	1	M116	-	✓	-	-	-					
113	3ANUSUL4	FL.3	1	M117	-	✓	-	-	-					
114	3GAS	FL.3	1	M118	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
115	4ZAHU1	FL.4	1	M119	-	✓	-	-	-					
116	4ZAHU2	FL.4	1	M120	-	✓	-	-	-					
117	4ANUSL	FL.4	1	M121	-	✓	-	-	-					
118	4FS01	FL.4	1	M122	-	✓	-	-	-					
119	4FS02	FL.4	1	M123	-	✓	-	-	-					
120	4SS01	FL.4	1	M124	-	✓	-	-	-					
121	4SS02	FL.4	1	M125	-	✓	-	-	-					
122	4GAS	FL.4	1	M126	-	✓	-	-	-					
123	5ZAHU1	FL.5	1	M127	-	✓	-	-	-					
124	5ZAHU2	FL.5	1	M128	-	✓	-	-	-					
125	5ZAHU3	FL.5	1	M129	-	✓	-	-	-					
126	5ZAHU4	FL.5	1	M130	-	✓	-	-	-					
127	5ZAHU5	FL.5	1	M131	-	✓	-	-	-					
128	5ZAHU6	FL.5	1	M132	-	✓	-	-	-					
129	5ZAHU7	FL.5	1	M133	-	✓	-	-	-					
130	5ZAHU8	FL.5	1	M134	-	✓	-	-	-					
131	5ZBGS	FL.5	1	M135	-	✓	-	-	-					
132	5FM1	FL.5	1	M136	-	✓	-	-	-					
133	5FM2	FL.5	1	M137	-	✓	-	-	-					
134	6ZAHU1	FL.6	1	M138	-	✓	-	-	-					
135	6ZAHU2	FL.6	1	M139	-	✓	-	-	-					
136	6ZAHU3	FL.6	1	M140	-	✓	-	-	-					
137	6ZAHU4	FL.6	1	M141	-	✓	-	-	-					
138	5FS01	FL.5	1	M142	-	✓	-	-	-					
139	5FS02	FL.5	1	M143	-	✓	-	-	-					
140	5SS01	FL.5	1	M144	-	✓	-	-	-					
141	5SS02	FL.5	1	M145	-	✓	-	-	-					
142	6ZAHU5	FL.6	1	M146	-	✓	-	-	-					
143	6ANUSUL	FL.6	1	M147	-	✓	-	-	-					
144	6GAS	FL.6	1	M148	-	✓	-	-	-					
145	6FM1	FL.6	1	M149	-	✓	-	-	-					
146	7ZAHU5	FL.7	1	M150	-	✓	-	-	-					
147	7ZAHU6	FL.7	1	M151	-	✓	-	-	-					
148	7ZB2	FL.7	1	M152	-	✓	-	-	-					
149	7ZB3	FL.7	1	M153	-	✓	-	-	-					
150	7FS01	FL.7	1	M154	-	✓	-	-	-					
151	7FS02	FL.7	1	M155	-	✓	-	-	-					
152	7SS01	FL.7	1	M156	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
153	7SS02	FL.7	1	M157	-	✔	-	-	-					
154	P7FS01	FL.7	1	M158	-	✔	-	-	-					
155	P7SS01	FL.7	1	M159	-	✔	-	-	-					
156	8ZD1	FL.8	2	M001	-	✔	-	-	-	✔	✔	✔		
157	8ZD2	FL.8	2	M002	-	✔	-	-	-	✔	✔	✔		
158	8ZD3	FL.8	2	M003	-	✔	-	-	-					
159	11ZSVS02/2	FL.11	2	M004	-	✔	-	-	-					
160	11ZSVS02/3	FL.11	2	M005	-	✔	-	-	-					
161	11ZSVS02/4	FL.11	2	M006	-	✔	-	-	-					
162	11ZSVS03/2	FL.11	2	M007	-	✔	-	-	-					
163	11ZSVS03/3	FL.11	2	M008	-	✔	-	-	-					
164	11ZSVS03/4	FL.11	2	M009	-	✔	-	-	-					
165	10ZSVS02/1	FL.10	2	M010	-	✔	-	-	-					
166	10ZSVS03/1	FL.10	2	M011	-	✔	-	-	-					
167	9AHU1	FL.9	2	M012	-	✔	-	-	-					
168	9AHU2	FL.9	2	M013	-	✔	-	-	-					
169	9ZD1	FL.9	2	M014	-	✔	-	-	-	✔				
170	9ZD2	FL.9	2	M015	-	✔	-	-	-					
171	9ZD3	FL.9	2	M016	-	✔	-	-	-	✔	✔	✔		
172	9ZD4	FL.9	2	M017	-	✔	-	-	-		✔			
173	9SZD1	FL.9	2	M018	-	✔	-	-	-					
174	9SZD2	FL.9	2	M019	-	✔	-	-	-					
175	9SZD3	FL.9	2	M020	-	✔	-	-	-					
176	9SZD4	FL.9	2	M021	-	✔	-	-	-					
177	10ZD15	FL.10	2	M022	-	✔	-	-	-		✔	✔		
178	10ZD16	FL.10	2	M023	-	✔	-	-	-	✔	✔	✔		
179	11ZD1	FL.11	2	M024	-	✔	-	-	-	✔	✔	✔		
180	12ZD1	FL.12	2	M025	-	✔	-	-	-	✔	✔	✔		
181	14ZD1	FL.14	2	M026	-	✔	-	-	-		✔	✔		
182	PZD1	FL.P9 PARK	2	M027	-	✔	-	-	-					
183	PZD2	FL.P9 PARK	2	M028	-	✔	-	-	-					
184	PZD3	FL.P9 PARK	2	M029	-	✔	-	-	-					
185	PZD4	FL.G PARK	2	M030	-	✔	-	-	-					
186	PZD5	FL.5st PARK	2	M031	-	✔	-	-	-	✔	✔	✔		
187	PZD6	FL.P9 PARK	2	M032	-	✔	-	-	-					
188	PZD7	FL.P9 PARK	2	M033	-	✔	-	-	-					
189	PZD8	FL.P9 PARK	2	M034	-	✔	-	-	-					
190	PZD9	FL.P9 PARK	2	M035	-	✔	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
191	PZD10	FL.P9 PARK	2	M036	-	✔	-	-	-					
192	PZD11	FL.P9 PARK	2	M037	-	✔	-	-	-					
193	9AHU3	FL.9	2	M038	-	✔	-	-	-					
194	9AHU4	FL.9	2	M039	-	✔	-	-	-					
195	9AHU5	FL.9	2	M040	-	✔	-	-	-					
196	9AHU6	FL.9	2	M041	-	✔	-	-	-					
197	9AHU7	FL.9	2	M042	-	✔	-	-	-					
198	9AHU8	FL.9	2	M043	-	✔	-	-	-					
199	9AHU9	FL.9	2	M044	-	✔	-	-	-					
200	8AHU1	FL.8	2	M045	-	✔	-	-	-					
201	8AHU2	FL.8	2	M046	-	✔	-	-	-					
202	8LIFT	FL.8	2	M047	-	✔	-	-	-					
203	8SF1	FL.8	2	M048	-	✔	-	-	-					
204	8SF1	FL.8	2	M049	-	✔	-	-	-					
205	8FS01	FL.8	2	M060	-	✔	-	-	-					
206	8FS02	FL.8	2	M061	-	✔	-	-	-					
207	8SS01	FL.8	2	M062	-	✔	-	-	-					
208	8SS02	FL.8	2	M063	-	✔	-	-	-					
209	9FS01	FL.9	2	M064	-	✔	-	-	-					
210	9FS02	FL.9	2	M065	-	✔	-	-	-					
211	9SS01	FL.9	2	M066	-	✔	-	-	-					
212	9SS02	FL.9	2	M067	-	✔	-	-	-					
213	10FS01	FL.10	2	M068	-	✔	-	-	-					
214	10FS02	FL.10	2	M069	-	✔	-	-	-					
215	10SS01	FL.10	2	M070	-	✔	-	-	-					
216	10SS02	FL.10	2	M071	-	✔	-	-	-					
217	11FS01	FL.11	2	M072	-	✔	-	-	-					
218	11FS02	FL.11	2	M073	-	✔	-	-	-					
219	11SS01	FL.11	2	M074	-	✔	-	-	-					
220	11SS02	FL.11	2	M075	-	✔	-	-	-					
221	12FS01	FL.12	2	M076	-	✔	-	-	-					
222	12FS02	FL.12	2	M077	-	✔	-	-	-					
223	12SS01	FL.12	2	M078	-	✔	-	-	-					
224	12SS02	FL.12	2	M079	-	✔	-	-	-					
225	14FS01	FL.14	2	M080	-	✔	-	-	-					
226	14FS02	FL.14	2	M081	-	✔	-	-	-					
227	14SS01	FL.14	2	M082	-	✔	-	-	-					
228	14SS02	FL.14	2	M083	-	✔	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
229	FS1	FL.P9 PARK	2	M084	-	✔	-	-	-					
230	FS2	FL.P9 PARK	2	M085	-	✔	-	-	-					
231	FS3	FL.P9 PARK	2	M086	-	✔	-	-	-					
232	FS4	FL.P9 PARK	2	M087	-	✔	-	-	-					
233	FS5	FL.P9 PARK	2	M088	-	✔	-	-	-					
234	FS6	FL.P9 PARK	2	M089	-	✔	-	-	-					
235	FS7	FL.P9 PARK	2	M090	-	✔	-	-	-					
236	FS8	FL.P9 PARK	2	M091	-	✔	-	-	-					
237	FS9	FL.P9 PARK	2	M092	-	✔	-	-	-					
238	FS10	FL.G PARK	2	M093	-	✔	-	-	-					
239	FS11	FL.P9 PARK	2	M094	-	✔	-	-	-					
240	FS12	FL.P9 PARK	2	M095	-	✔	-	-	-					
241	PZSV1	FL.P9 PARK	2	M096	-	✔	-	-	-					
242	PZSV2	FL.P9 PARK	2	M097	-	✔	-	-	-					
243	PZSV3	FL.P9 PARK	2	M098	-	✔	-	-	-					
244	PZSV4	FL.P9 PARK	2	M099	-	✔	-	-	-					
245	8ZB1	FL.8	2	M100	-	✔	-	-	-					
246	8LIFT1	FL.8	2	M101	-	✔	-	-	-					
247	8TELL	FL.8	2	M102	-	✔	-	-	-					
248	8SF01	FL.8	2	M103	-	✔	-	-	-					
249	8SF02	FL.8	2	M104	-	✔	-	-	-					
250	9ZB1	FL.9	2	M105	-	✔	-	-	-					
251	9SF01	FL.9	2	M106	-	✔	-	-	-					
252	9SF02	FL.9	2	M107	-	✔	-	-	-					
253	9TELL	FL.9	2	M108	-	✔	-	-	-					
254	10ZB1	FL.10	2	M109	-	✔	-	-	-					
255	11ZB1	FL.11	2	M110	-	✔	-	-	-					
256	12ZB1	FL.12	2	M111	-	✔	-	-	-					
257	12LIFT1	FL.12	2	M112	-	✔	-	-	-					
258	14ZB1	FL.14	2	M113	-	✔	-	-	-					
259	PZB1	FL.P1 PARK	2	M114	-	✔	-	-	-					
260	PZB2	FL.P9 PARK	2	M115	-	✔	-	-	-					
261	PZB3	FL.P9 PARK	2	M116	-	✔	-	-	-					
262	PZB4	FL.P9 PARK	2	M117	-	✔	-	-	-					
263	PZB5	FL.P9 PARK	2	M118	-	✔	-	-	-					
264	PZB6	FL.P9 PARK	2	M119	-	✔	-	-	-					
265	PZB7	FL.P9 PARK	2	M120	-	✔	-	-	-					
266	PZB8	FL.P9 PARK	2	M121	-	✔	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
267	PZB10	FL.P9 PARK	2	M123	-	✔	-	-	-					
268	PZB11	FL.P9 PARK	2	M124	-	✔	-	-	-					
269	PZSV5	FL.P9 PARK	2	M130	-	✔	-	-	-					
270	PZSV6	FL.P9 PARK	2	M131	-	✔	-	-	-					
271	PZSV7	FL.P9 PARK	2	M132	-	✔	-	-	-					
272	PZSV8	FL.P9 PARK	2	M133	-	✔	-	-	-					
273	PZSV9	FL.P9 PARK	2	M134	-	✔	-	-	-					
274	PZSV10	FL.G PARK	2	M135	-	✔	-	-	-					
275	PZSV11	FL.P9 PARK	2	M136	-	✔	-	-	-					
276	PZSV12	FL.P9 PARK	2	M137	-	✔	-	-	-					
277	PZG1	FL.G PARK	2	M138	-	✔	-	-	-					
278	PZG2	FL.G PARK	2	M139	-	✔	-	-	-					
279	15ZD1	FL.15	3	M001	-	✔	-	-	-	✔	✔	✔		
280	16ZD1	FL.16	3	M002	-	✔	-	-	-	✔	✔	✔		
281	17ZD1	FL.17	3	M003	-	✔	-	-	-	✔	✔	✔		
282	18ZD1	FL.18	3	M004	-	✔	-	-	-	✔	✔	✔		
283	15FS01	FL.15	3	M060	-	✔	-	-	-					
284	15FS02	FL.15	3	M061	-	✔	-	-	-					
285	15SS01	FL.15	3	M062	-	✔	-	-	-					
286	15SS02	FL.15	3	M063	-	✔	-	-	-					
287	16FS01	FL.16	3	M064	-	✔	-	-	-					
288	16FS02	FL.16	3	M065	-	✔	-	-	-					
289	16SS01	FL.16	3	M066	-	✔	-	-	-					
290	16SS02	FL.16	3	M067	-	✔	-	-	-					
291	17FS01	FL.17	3	M068	-	✔	-	-	-					
292	17FS02	FL.17	3	M069	-	✔	-	-	-					
293	17SS01	FL.17	3	M070	-	✔	-	-	-					
294	17SS02	FL.17	3	M071	-	✔	-	-	-					
295	18FS01	FL.18	3	M072	-	✔	-	-	-					
296	18FS02	FL.18	3	M073	-	✔	-	-	-					
297	18SS01	FL.18	3	M074	-	✔	-	-	-					
298	18SS02	FL.18	3	M075	-	✔	-	-	-					
299	15ZB1	FL.15	3	M100	-	✔	-	-	-					
300	16ZB1	FL.16	3	M101	-	✔	-	-	-					
301	17ZB1	FL.17	3	M102	-	✔	-	-	-					
302	18ZB1	FL.18	3	M103	-	✔	-	-	-					
303	19ZD1	FL.19	4	1	-	✔	-	-	-	✔	✔	✔		
304	20ZD1	FL.20	4	2	-	✔	-	-	-	✔	✔	✔		

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
305	21ZD1	FL.21	4	3	-	✓	-	-	-	✓	✓	✓		
306	22ZD1	FL.22	4	4	-	✓	-	-	-	✓	✓			
307	22SZD1	FL.22	4	5	-	✓	-	-	-	✓				
308	22SZD2	FL.22	4	6	-	✓	-	-	-	✓				
309	19FS01	FL.19	4	60	-	✓	-	-	-					
310	19FS02	FL.19	4	61	-	✓	-	-	-					
311	19SS01	FL.19	4	62	-	✓	-	-	-					
312	19SS02	FL.19	4	63	-	✓	-	-	-					
313	20FS01	FL.20	4	64	-	✓	-	-	-					
314	20FS02	FL.20	4	65	-	✓	-	-	-					
315	20SS01	FL.20	4	66	-	✓	-	-	-					
316	20SS02	FL.20	4	67	-	✓	-	-	-					
317	21FS01	FL.21	4	68	-	✓	-	-	-					
318	21FS02	FL.21	4	69	-	✓	-	-	-					
319	21SS01	FL.21	4	70	-	✓	-	-	-					
320	21SS02	FL.21	4	71	-	✓	-	-	-					
321	22FS01	FL.22	4	72	-	✓	-	-	-					
322	22FS02	FL.22	4	73	-	✓	-	-	-					
323	22SS01	FL.22	4	74	-	✓	-	-	-					
324	22SS02	FL.22	4	75	-	✓	-	-	-					
325	19ZB1	FL.19	4	100	-	✓	-	-	-					
326	20ZB1	FL.20	4	101	-	✓	-	-	-					
327	21ZB1	FL.21	4	102	-	✓	-	-	-					
328	22ZB1	FL.22	4	103	-	✓	-	-	-					
329	MONITOR GENERAL SUPPLY		4	155	-	✓	-	-	-					
330	MONITOR AC FAIL	POWER SUPPLY	4	156	-	✓	-	-	-					
331	MONITOR BATTERY	POWER SUPPLY	4	157	-	✓	-	-	-					
332	MONITOR GROUND	GROUND FAULT	4	158	-	✓	-	-	-					
333	23ZD1	FL.23	5	1	-	✓	-	-	-	✓	✓	✓		
334	24ZD1	FL.24	5	2	-	✓	-	-	-	✓	✓	✓		
335	25ZD1	FL.25	5	3	-	✓	-	-	-	✓	✓	✓		
336	26ZD1	FL.26	5	4	-	✓	-	-	-	✓	✓	✓		
337	23FS01	FL.23	5	60	-	✓	-	-	-					
338	23FS02	FL.23	5	61	-	✓	-	-	-					
339	23SS01	FL.23	5	62	-	✓	-	-	-					
340	23SS02	FL.23	5	63	-	✓	-	-	-					
341	24FS01	FL.24	5	64	-	✓	-	-	-					
342	24FS02	FL.24	5	65	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
343	24SS01	FL.24	5	66	-	✓	-	-	-					
344	24SS02	FL.24	5	67	-	✓	-	-	-					
345	25FS01	FL.25	5	68	-	✓	-	-	-					
346	25FS02	FL.25	5	69	-	✓	-	-	-					
347	25SS01	FL.25	5	70	-	✓	-	-	-					
348	25SS02	FL.25	5	71	-	✓	-	-	-					
349	26FS01	FL.26	5	72	-	✓	-	-	-					
350	26FS02	FL.26	5	73	-	✓	-	-	-					
351	26SS01	FL.26	5	74	-	✓	-	-	-					
352	26SS02	FL.26	5	75	-	✓	-	-	-					
353	23ZB1	FL.23	5	100	-	✓	-	-	-					
354	24ZB1	FL.24	5	101	-	✓	-	-	-					
355	24TELL	FL.24	5	102	-	✓	-	-	-					
356	25ZB1	FL.25	5	103	-	✓	-	-	-					
357	26ZB1	FL.26	5	104	-	✓	-	-	-					
358	27ZD1	FL.27	6	1	-	✓	-	-	-	✓	✓	✓		
359	28ZD1	FL.28	6	2	-	✓	-	-	-	✓	✓	✓		
360	29ZD2	FL.29	6	3	-	✓	-	-	-	✓	✓	✓		
361	30ZD3	FL.30	6	4	-	✓	-	-	-	✓	✓	✓		
362	31ZD1	FL.31	6	5	-	✓	-	-	-	✓	✓	✓		
363	32ZD5	FL.32	6	6	-	✓	-	-	-	✓	✓			
364	32/GDC-F32-01 REL	FL.32	6	7	-	✓	-	-	-					
365	32/GDC-F32-01 TBL	FL.32	6	8	-	✓	-	-	-					
366	33ZD1	FL.33	6	9	-	✓	-	-	-				✓	
367	34ZD1	FL.34	6	10	-	✓	-	-	-				✓	
368	35ZD1	FL.35	6	11	-	✓	-	-	-					
369	36SZD1	FL.36	6	12	-	✓	-	-	-	✓				
370	36SZD2	FL.36	6	13	-	✓	-	-	-					
371	32ZD1	FL.32	6	14	-	✓	-	-	-		✓			
372	32ZD2	FL.32	6	15	-	✓	-	-	-					
373	32ZD3	FL.32	6	16	-	✓	-	-	-					
374	32ZD4	FL.32	6	17	-	✓	-	-	-	✓	✓			
375	35ZAHU1	FL.35	6	19	-	✓	-	-	-					
376	35ZAHU2	FL.35	6	20	-	✓	-	-	-					
377	35ZSF1	FL.35	6	21	-	✓	-	-	-					
378	35ZSF2	FL.35	6	22	-	✓	-	-	-					
379	34ZAHU	FL.34	6	23	-	✓	-	-	-					
380	34LIFT1	FL.34	6	24	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
381	34LIFT2	FL.34	6	25	-	✓	-	-	-					
382	33ZAHU1	FL.33	6	26	-	✓	-	-	-					
383	33ZAHU2	FL.33	6	27	-	✓	-	-	-					
384	32ZAHU1	FL.32	6	28	-	✓	-	-	-					
385	32ZAHU2	FL.32	6	29	-	✓	-	-	-					
386	32ZAHU3	FL.32	6	30	-	✓	-	-	-					
387	32ZAHU4	FL.32	6	31	-	✓	-	-	-					
388	32ZAHU5	FL.32	6	32	-	✓	-	-	-					
389	32ZAHU6	FL.32	6	33	-	✓	-	-	-					
390	31ZAHU	FL.31	6	34	-	✓	-	-	-					
391	31ANSUL	FL.31	6	35	-	✓	-	-	-					
392	30ZTEL	FL.30	6	36	-	✓	-	-	-					
393	32ANSUL	FL.32	6	37	-	✓	-	-	-					
394	27FS01	FL.27	6	60	-	✓	-	-	-					
395	27FS02	FL.27	6	61	-	✓	-	-	-					
396	27SS01	FL.27	6	62	-	✓	-	-	-					
397	27SS02	FL.27	6	63	-	✓	-	-	-					
398	28FS01	FL.28	6	64	-	✓	-	-	-					
399	Library	FL.32	6	65	-	✓	-	-	-					
400	28SS01	FL.28	6	66	-	✓	-	-	-					
401	28SS02	FL.28	6	67	-	✓	-	-	-					
402	29FS01	FL.29	6	68	-	✓	-	-	-					
403	29FS02	FL.29	6	69	-	✓	-	-	-					
404	29SS01	FL.29	6	70	-	✓	-	-	-					
405	29SS02	FL.29	6	71	-	✓	-	-	-					
406	30FS01	FL.30	6	72	-	✓	-	-	-					
407	30FS02	FL.30	6	73	-	✓	-	-	-					
408	30SS01	FL.30	6	74	-	✓	-	-	-					
409	30SS02	FL.30	6	75	-	✓	-	-	-					
410	31FS01	FL.31	6	76	-	✓	-	-	-					
411	31FS02	FL.31	6	77	-	✓	-	-	-					
412	31SS01	FL.31	6	78	-	✓	-	-	-					
413	31SS02	FL.31	6	79	-	✓	-	-	-					
414	32FS01	FL.32	6	80	-	✓	-	-	-					
415	32FS02	FL.32	6	81	-	✓	-	-	-					
416	32SS01	FL.32	6	82	-	✓	-	-	-					
417	32SS02	FL.32	6	83	-	✓	-	-	-					
418	33FS01	FL.33	6	84	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร้องลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
419	33FS02	FL.33	6	85	-	✓	-	-	-					
420	33SS01	FL.33	6	86	-	✓	-	-	-					
421	33SS02	FL.33	6	87	-	✓	-	-	-					
422	34FS01	FL.34	6	88	-	✓	-	-	-					
423	34FS02	FL.34	6	89	-	✓	-	-	-					
424	34SS01	FL.34	6	90	-	✓	-	-	-					
425	34SS02	FL.34	6	91	-	✓	-	-	-					
426	35FS01	FL.35	6	92	-	✓	-	-	-					
427	35FS02	FL.35	6	93	-	✓	-	-	-					
428	35SS01	FL.35	6	94	-	✓	-	-	-					
429	35SS02	FL.35	6	95	-	✓	-	-	-					
430	36FS01	FL.36	6	96	-	✓	-	-	-					
431	36FS02	FL.36	6	97	-	✓	-	-	-					
432	36SS01	FL.36	6	98	-	✓	-	-	-					
433	36SS02	FL.36	6	99	-	✓	-	-	-					
434	27ZB1	FL.27	6	100	-	✓	-	-	-					
435	28ZB1	FL.28	6	101	-	✓	-	-	-					
436	29ZB1	FL.29	6	102	-	✓	-	-	-					
437	30ZB1	FL.30	6	103	-	✓	-	-	-					
438	31ZB1	FL.31	6	104	-	✓	-	-	-					
439	32ZB1	FL.32	6	105	-	✓	-	-	-					
440	33ZB1	FL.33	6	106	-	✓	-	-	-					
441	34ZB1	FL.34	6	107	-	✓	-	-	-					
442	34LIFT	FL.34	6	108	-	✓	-	-	-					
443	35ZB1	FL.35	6	109	-	✓	-	-	-					
444	35PAF1	FL.35	6	110	-	✓	-	-	-					
445	35AHU1	FL.35	6	111	-	✓	-	-	-					
446	36SF01	FL.36	6	112	-	✓	-	-	-					
447	36SF02	FL.36	6	113	-	✓	-	-	-					
448	36TELL	FL.36	6	114	-	✓	-	-	-					
449	35PAF2	FL.35	6	150	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
1	810.RM	FL.8	2	D001	-	✓	-	-	-					
2	809.RM	FL.8	2	D002	-	✓	-	-	-					
3	808.RM	FL.8	2	D003	-	✓	-	-	-					
4	807.RM	FL.8	2	D004	-	✓	-	-	-					
5	807.RM	FL.8	2	D005	-	✓	-	-	-					
6	807.RM	FL.8	2	D006	-	✓	-	-	-					
7	807.RM	FL.8	2	D007	-	✓	-	-	-					
8	807.RM	FL.8	2	D008	-	✓	-	-	-					
9	807.RM	FL.8	2	D009	-	✓	-	-	-					
10	807.RM	FL.8	2	D010	-	✓	-	-	-					
11	807.RM	FL.8	2	D011	-	✓	-	-	-					
12	818.RM	FL.8	2	D012	-	✓	-	-	-					
13	820.RM	FL.8	2	D013	-	✓	-	-	-					
14	819.RM	FL.8	2	D014	-	✓	-	-	-					
15	817.RM	FL.8	2	D015	-	✓	-	-	-					
16	815.RM	FL.8	2	D016	-	✓	-	-	-					
17	1011.RM	FL.10	2	D017	-	✓	-	-	-					
18	1010.RM	FL.10	2	D018	-	✓	-	-	-					
19	1009.RM	FL.10	2	D019	-	✓	-	-	-					
20	1008.RM	FL.10	2	D020	-	✓	-	-	-					
21	1007.RM	FL.10	2	D021	-	✓	-	-	-					
22	1006.RM	FL.10	2	D022	-	✓	-	-	-					
23	1014.RM	FL.10	2	D023	-	✓	-	-	-					
24	1016.RM	FL.10	2	D024	-	✓	-	-	-					
25	1018.RM	FL.10	2	D025	-	✓	-	-	-					
26	1020.RM	FL.10	2	D026	-	✓	-	-	-					
27	1019.RM	FL.10	2	D027	-	✓	-	-	-					
28	1017.RM	FL.10	2	D028	-	✓	-	-	-					
29	1015.RM	FL.10	2	D029	-	✓	-	-	-					
30	1012.RM	FL.10	2	D030	-	✓	-	-	-					
31	1112.RM	FL.11	2	D031	-	✓	-	-	-					
32	1111.RM	FL.11	2	D032	-	✓	-	-	-					
33	1110.RM	FL.11	2	D033	-	✓	-	-	-					
34	1109.RM	FL.11	2	D034	-	✓	-	-	-					
35	1108.RM	FL.11	2	D035	-	✓	-	-	-					
36	1107.RM	FL.11	2	D036	-	✓	-	-	-					
37	1106.RM	FL.11	2	D037	-	✓	-	-	-					
38	1114.RM	FL.11	2	D038	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
39	1116.RM	FL.11	2	D039	-	✓	-	-	-					
40	1118.RM	FL.11	2	D040	-	✓	-	-	-					
41	1120.RM	FL.11	2	D041	-	✓	-	-	-					
42	1119.RM	FL.11	2	D042	-	✓	-	-	-					
43	1117.RM	FL.11	2	D043	-	✓	-	-	-					
44	1115.RM	FL.11	2	D044	-	✓	-	-	-					
45	1101.RM	FL.11	2	D045	-	✓	-	-	-					
46	1102.RM	FL.11	2	D046	-	✓	-	-	-					
47	1103.RM	FL.11	2	D047	-	✓	-	-	-					
48	1104.RM	FL.11	2	D048	-	✓	-	-	-	✓				
49	1105.RM	FL.11	2	D049	-	✓	-	-	-					
50	1105.RM	FL.11	2	D050	-	✓	-	-	-					
51	1212.RM	FL.12	2	D051	-	✓	-	-	-					
52	1211.RM	FL.12	2	D052	-	✓	-	-	-					
53	1210.RM	FL.12	2	D053	-	✓	-	-	-					
54	1209.RM	FL.12	2	D054	-	✓	-	-	-					
55	1208.RM	FL.12	2	D055	-	✓	-	-	-					
56	1207.RM	FL.12	2	D056	-	✓	-	-	-					
57	1206.RM	FL.12	2	D057	-	✓	-	-	-					
58	1214.RM	FL.12	2	D058	-	✓	-	-	-					
59	1216.RM	FL.12	2	D059	-	✓	-	-	-					
60	1218.RM	FL.12	2	D060	-	✓	-	-	-					
61	1220.RM	FL.12	2	D061	-	✓	-	-	-					
62	1219.RM	FL.12	2	D062	-	✓	-	-	-					
63	1217.RM	FL.12	2	D063	-	✓	-	-	-					
64	1215.RM	FL.12	2	D064	-	✓	-	-	-					
65	1201.RM	FL.12	2	D065	-	✓	-	-	-					
66	1202.RM	FL.12	2	D066	-	✓	-	-	-					
67	1203.RM	FL.12	2	D067	-	✓	-	-	-					
68	1204.RM	FL.12	2	D068	-	✓	-	-	-					
69	1205.RM	FL.12	2	D069	-	✓	-	-	-					
70	1205.RM	FL.12	2	D070	-	✓	-	-	-					
71	1412.RM	FL.14	2	D071	-	✓	-	-	-					
72	1411.RM	FL.14	2	D072	-	✓	-	-	-					
73	1410.RM	FL.14	2	D073	-	✓	-	-	-					
74	1409.RM	FL.14	2	D074	-	✓	-	-	-					
75	1408.RM	FL.14	2	D075	-	✓	-	-	-					
76	1407.RM	FL.14	2	D076	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
77	1406.RM	FL.14	2	D077	-	✓	-	-	-					
78	1414.RM	FL.14	2	D078	-	✓	-	-	-					
79	1416.RM	FL.14	2	D079	-	✓	-	-	-					
80	1418.RM	FL.14	2	D080	-	✓	-	-	-					
81	1420.RM	FL.14	2	D081	-	✓	-	-	-					
82	1419.RM	FL.14	2	D082	-	✓	-	-	-					
83	1417.RM	FL.14	2	D083	-	✓	-	-	-					
84	1415.RM	FL.14	2	D084	-	✓	-	-	-					
85	1401.RM	FL.14	2	D085	-	✓	-	-	-					
86	1402.RM	FL.14	2	D086	-	✓	-	-	-					
87	1403.RM	FL.14	2	D087	-	✓	-	-	-					
88	1404.RM	FL.14	2	D088	-	✓	-	-	-					
89	1405.RM	FL.14	2	D089	-	✓	-	-	-					
90	1405.RM	FL.14	2	D090	-	✓	-	-	-					
91	1512.RM	FL.15	3	D001	-	✓	-	-	-					
92	1511.RM	FL.15	3	D002	-	✓	-	-	-					
93	1510.RM	FL.15	3	D003	-	✓	-	-	-					
94	1509.RM	FL.15	3	D004	-	✓	-	-	-					
95	1508.RM	FL.15	3	D005	-	✓	-	-	-					
96	1507.RM	FL.15	3	D006	-	✓	-	-	-					
97	1506.RM	FL.15	3	D007	-	✓	-	-	-					
98	1514.RM	FL.15	3	D008	-	✓	-	-	-					
99	1516.RM	FL.15	3	D009	-	✓	-	-	-					
100	1518.RM	FL.15	3	D010	-	✓	-	-	-					
101	1520.RM	FL.15	3	D011	-	✓	-	-	-					
102	1519.RM	FL.15	3	D012	-	✓	-	-	-					
103	1517.RM	FL.15	3	D013	-	✓	-	-	-					
104	1515.RM	FL.15	3	D014	-	✓	-	-	-					
105	1501.RM	FL.15	3	D015	-	✓	-	-	-					
106	1502.RM	FL.15	3	D016	-	✓	-	-	-					
107	1503.RM	FL.15	3	D017	-	✓	-	-	-					
108	1504.RM	FL.15	3	D018	-	✓	-	-	-					
109	1505.RM	FL.15	3	D019	-	✓	-	-	-					
110	1505.RM	FL.15	3	D020	-	✓	-	-	-					
111	1612.RM	FL.16	3	D021	-	✓	-	-	-					
112	1611.RM	FL.16	3	D022	-	✓	-	-	-					
113	1610.RM	FL.16	3	D023	-	✓	-	-	-					
114	1609.RM	FL.16	3	D024	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
115	1608.RM	FL.16	3	D025	-	✓	-	-	-					
116	1607.RM	FL.16	3	D026	-	✓	-	-	-					
117	1606.RM	FL.16	3	D027	-	✓	-	-	-					
118	1614.RM	FL.16	3	D028	-	✓	-	-	-					
119	1616.RM	FL.16	3	D029	-	✓	-	-	-					
120	1618.RM	FL.16	3	D030	-	✓	-	-	-					
121	1620.RM	FL.16	3	D031	-	✓	-	-	-					
122	1619.RM	FL.16	3	D032	-	✓	-	-	-					
123	1617.RM	FL.16	3	D033	-	✓	-	-	-					
124	1615.RM	FL.16	3	D034	-	✓	-	-	-					
125	1601.RM	FL.16	3	D035	-	✓	-	-	-					
126	1602.RM	FL.16	3	D036	-	✓	-	-	-					
127	1603.RM	FL.16	3	D037	-	✓	-	-	-					
128	1604.RM	FL.16	3	D038	-	✓	-	-	-					
129	1605.RM	FL.16	3	D039	-	✓	-	-	-					
130	1605.RM	FL.16	3	D040	-	✓	-	-	-					
131	1712.RM	FL.17	3	D041	-	✓	-	-	-					
132	1711.RM	FL.17	3	D042	-	✓	-	-	-					
133	1710.RM	FL.17	3	D043	-	✓	-	-	-					
134	1709.RM	FL.17	3	D044	-	✓	-	-	-					
135	1708.RM	FL.17	3	D045	-	✓	-	-	-					
136	1707.RM	FL.17	3	D046	-	✓	-	-	-					
137	1706.RM	FL.17	3	D047	-	✓	-	-	-					
138	1714.RM	FL.17	3	D048	-	✓	-	-	-					
139	1716.RM	FL.17	3	D049	-	✓	-	-	-					
140	1718.RM	FL.17	3	D050	-	✓	-	-	-					
141	1720.RM	FL.17	3	D051	-	✓	-	-	-					
142	1719.RM	FL.17	3	D052	-	✓	-	-	-					
143	1717.RM	FL.17	3	D053	-	✓	-	-	-					
144	1715.RM	FL.17	3	D054	-	✓	-	-	-					
145	1701.RM	FL.17	3	D055	-	✓	-	-	-					
146	1702.RM	FL.17	3	D056	-	✓	-	-	-					
147	1703.RM	FL.17	3	D057	-	✓	-	-	-					
148	1704.RM	FL.17	3	D058	-	✓	-	-	-					
149	1705.RM	FL.17	3	D059	-	✓	-	-	-					
150	1705.RM	FL.17	3	D060	-	✓	-	-	-					
151	1812.RM	FL.18	3	D061	-	✓	-	-	-					
152	1811.RM	FL.18	3	D062	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
153	1810.RM	FL.18	3	D063	-	✓	-	-	-					
154	1809.RM	FL.18	3	D064	-	✓	-	-	-					
155	1808.RM	FL.18	3	D065	-	✓	-	-	-					
156	1807.RM	FL.18	3	D066	-	✓	-	-	-					
157	1806.RM	FL.18	3	D067	-	✓	-	-	-					
158	1814.RM	FL.18	3	D068	-	✓	-	-	-					
159	1816.RM	FL.18	3	D069	-	✓	-	-	-					
160	1818.RM	FL.18	3	D070	-	✓	-	-	-					
161	1820.RM	FL.18	3	D071	-	✓	-	-	-					
162	1819.RM	FL.18	3	D072	-	✓	-	-	-					
163	1817.RM	FL.18	3	D073	-	✓	-	-	-					
164	1815.RM	FL.18	3	D074	-	✓	-	-	-					
165	1801.RM	FL.18	3	D075	-	✓	-	-	-					
166	1802.RM	FL.18	3	D076	-	✓	-	-	-					
167	1803.RM	FL.18	3	D077	-	✓	-	-	-					
168	1804.RM	FL.18	3	D078	-	✓	-	-	-					
169	1805.RM	FL.18	3	D079	-	✓	-	-	-					
170	1805.RM	FL.18	3	D080	-	✓	-	-	-					
171	1912.RM	FL.19	4	D001	-	✓	-	-	-					
172	1911.RM	FL.19	4	D002	-	✓	-	-	-					
173	1910.RM	FL.19	4	D003	-	✓	-	-	-					
174	1909.RM	FL.19	4	D004	-	✓	-	-	-					
175	1908.RM	FL.19	4	D005	-	✓	-	-	-					
176	1907.RM	FL.19	4	D006	-	✓	-	-	-					
177	1906.RM	FL.19	4	D007	-	✓	-	-	-					
178	1914.RM	FL.19	4	D008	-	✓	-	-	-					
179	1916.RM	FL.19	4	D009	-	✓	-	-	-					
180	1918.RM	FL.19	4	D010	-	✓	-	-	-					
181	1920.RM	FL.19	4	D011	-	✓	-	-	-					
182	1919.RM	FL.19	4	D012	-	✓	-	-	-					
183	1917.RM	FL.19	4	D013	-	✓	-	-	-					
184	1915.RM	FL.19	4	D014	-	✓	-	-	-					
185	1901.RM	FL.19	4	D015	-	✓	-	-	-					
186	1902.RM	FL.19	4	D016	-	✓	-	-	-					
187	1903.RM	FL.19	4	D017	-	✓	-	-	-					
188	1904.RM	FL.19	4	D018	-	✓	-	-	-					
189	1905.RM	FL.19	4	D019	-	✓	-	-	-					
190	1905.RM	FL.19	4	D020	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
191	2012.RM	FL.20	4	D021	-	✓	-	-	-					
192	2011.RM	FL.20	4	D022	-	✓	-	-	-					
193	2010.RM	FL.20	4	D023	-	✓	-	-	-					
194	2009.RM	FL.20	4	D024	-	✓	-	-	-					
195	2008.RM	FL.20	4	D025	-	✓	-	-	-					
196	2007.RM	FL.20	4	D026	-	✓	-	-	-					
197	2006.RM	FL.20	4	D027	-	✓	-	-	-					
198	2014.RM	FL.20	4	D028	-	✓	-	-	-					
199	2016.RM	FL.20	4	D029	-	✓	-	-	-					
200	2018.RM	FL.20	4	D030	-	✓	-	-	-					
201	2020.RM	FL.20	4	D031	-	✓	-	-	-					
202	2019.RM	FL.20	4	D032	-	✓	-	-	-					
203	2017.RM	FL.20	4	D033	-	✓	-	-	-					
204	2015.RM	FL.20	4	D034	-	✓	-	-	-					
205	2001.RM	FL.20	4	D035	-	✓	-	-	-					
206	2002.RM	FL.20	4	D036	-	✓	-	-	-					
207	2003.RM	FL.20	4	D037	-	✓	-	-	-					
208	2004.RM	FL.20	4	D038	-	✓	-	-	-					
209	2005.RM	FL.20	4	D039	-	✓	-	-	-					
210	2005.RM	FL.20	4	D040	-	✓	-	-	-					
211	2112.RM	FL.21	4	D041	-	✓	-	-	-					
212	2111.RM	FL.21	4	D042	-	✓	-	-	-					
213	2110.RM	FL.21	4	D043	-	✓	-	-	-					
214	2108.RM	FL.21	4	D044	-	✓	-	-	-					
215	2108.RM	FL.21	4	D045	-	✓	-	-	-					
216	2107.RM	FL.21	4	D046	-	✓	-	-	-					
217	2106.RM	FL.21	4	D047	-	✓	-	-	-					
218	2114.RM	FL.21	4	D048	-	✓	-	-	-					
219	2116.RM	FL.21	4	D049	-	✓	-	-	-					
220	2118.RM	FL.21	4	D050	-	✓	-	-	-					
221	2120.RM	FL.21	4	D051	-	✓	-	-	-					
222	2119.RM	FL.21	4	D052	-	✓	-	-	-					
223	2117.RM	FL.21	4	D053	-	✓	-	-	-					
224	2115.RM	FL.21	4	D054	-	✓	-	-	-					
225	2101.RM	FL.21	4	D055	-	✓	-	-	-					
226	2102.RM	FL.21	4	D056	-	✓	-	-	-					
227	2103.RM	FL.21	4	D057	-	✓	-	-	-					
228	2104.RM	FL.21	4	D058	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
229	2105.RM	FL.21	4	D059	-	✓	-	-	-					
230	2105.RM	FL.21	4	D060	-	✓	-	-	-					
231	2212.RM	FL.22	4	D061	-	✓	-	-	-					
232	2211.RM	FL.22	4	D062	-	✓	-	-	-					
233	2210.RM	FL.22	4	D063	-	✓	-	-	-					
234	2208.RM	FL.22	4	D064	-	✓	-	-	-					
235	2208.RM	FL.22	4	D065	-	✓	-	-	-					
236	2207.RM	FL.22	4	D066	-	✓	-	-	-					
237	2206.RM	FL.22	4	D067	-	✓	-	-	-					
238	2214.RM	FL.22	4	D068	-	✓	-	-	-					
239	2216.RM	FL.22	4	D069	-	✓	-	-	-					
240	2218.RM	FL.22	4	D070	-	✓	-	-	-					
241	2220.RM	FL.22	4	D071	-	✓	-	-	-					
242	2219.RM	FL.22	4	D072	-	✓	-	-	-					
243	2217.RM	FL.22	4	D073	-	✓	-	-	-					
244	2215.RM	FL.22	4	D074	-	✓	-	-	-					
245	2201.RM	FL.22	4	D075	-	✓	-	-	-					
246	2202.RM	FL.22	4	D076	-	✓	-	-	-					
247	2203.RM	FL.22	4	D077	-	✓	-	-	-					
248	2204.RM	FL.22	4	D078	-	✓	-	-	-					
249	2205.RM	FL.22	4	D079	-	✓	-	-	-					
250	2205.RM	FL.22	4	D080	-	✓	-	-	-					
251	2312.RM	FL.23	5	D001	-	✓	-	-	-					
252	2311.RM	FL.23	5	D002	-	✓	-	-	-					
253	2310.RM	FL.23	5	D003	-	✓	-	-	-					
254	2308.RM	FL.23	5	D004	-	✓	-	-	-					
255	2308.RM	FL.23	5	D005	-	✓	-	-	-					
256	2307.RM	FL.23	5	D006	-	✓	-	-	-					
257	2306.RM	FL.23	5	D007	-	✓	-	-	-					
258	2314.RM	FL.23	5	D008	-	✓	-	-	-					
259	2316.RM	FL.23	5	D009	-	✓	-	-	-					
260	2318.RM	FL.23	5	D010	-	✓	-	-	-					
261	2320.RM	FL.23	5	D011	-	✓	-	-	-					
262	2319.RM	FL.23	5	D012	-	✓	-	-	-					
263	2317.RM	FL.23	5	D013	-	✓	-	-	-					
264	2315.RM	FL.23	5	D014	-	✓	-	-	-					
265	2301.RM	FL.23	5	D015	-	✓	-	-	-					
266	2302.RM	FL.23	5	D016	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟหรือสัญญาณร่วงลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
267	2303.RM	FL.23	5	D017	-	✓	-	-	-					
268	2304.RM	FL.23	5	D018	-	✓	-	-	-					
269	2305.RM	FL.23	5	D019	-	✓	-	-	-					
270	2305.RM	FL.23	5	D020	-	✓	-	-	-					
271	2412.RM	FL.24	5	D021	-	✓	-	-	-					
272	2411.RM	FL.24	5	D022	-	✓	-	-	-					
273	2410.RM	FL.24	5	D023	-	✓	-	-	-					
274	2408.RM	FL.24	5	D024	-	✓	-	-	-					
275	2408.RM	FL.24	5	D025	-	✓	-	-	-					
276	2407.RM	FL.24	5	D026	-	✓	-	-	-	✓				
277	2406.RM	FL.24	5	D027	-	✓	-	-	-					
278	2414.RM	FL.24	5	D028	-	✓	-	-	-					
279	2416.RM	FL.24	5	D029	-	✓	-	-	-					
280	2418.RM	FL.24	5	D030	-	✓	-	-	-					
281	2420.RM	FL.24	5	D031	-	✓	-	-	-					
282	2419.RM	FL.24	5	D032	-	✓	-	-	-					
283	2417.RM	FL.24	5	D033	-	✓	-	-	-					
284	2415.RM	FL.24	5	D034	-	✓	-	-	-					
285	2401.RM	FL.24	5	D035	-	✓	-	-	-					
286	2402.RM	FL.24	5	D036	-	✓	-	-	-					
287	2403.RM	FL.24	5	D037	-	✓	-	-	-					
288	2404.RM	FL.24	5	D038	-	✓	-	-	-					
289	2405.RM	FL.24	5	D039	-	✓	-	-	-					
290	2405.RM	FL.24	5	D040	-	✓	-	-	-					
291	2512.RM	FL.25	5	D041	-	✓	-	-	-					
292	2511.RM	FL.25	5	D042	-	✓	-	-	-					
293	2510.RM	FL.25	5	D043	-	✓	-	-	-					
294	2508.RM	FL.25	5	D044	-	✓	-	-	-					
295	2508.RM	FL.25	5	D045	-	✓	-	-	-					
296	2507.RM	FL.25	5	D046	-	✓	-	-	-					
297	2506.RM	FL.25	5	D047	-	✓	-	-	-					
298	2514.RM	FL.25	5	D048	-	✓	-	-	-					
299	2516.RM	FL.25	5	D049	-	✓	-	-	-					
300	2518.RM	FL.25	5	D050	-	✓	-	-	-					
301	2520.RM	FL.25	5	D051	-	✓	-	-	-					
302	2519.RM	FL.25	5	D052	-	✓	-	-	-					
303	2517.RM	FL.25	5	D053	-	✓	-	-	-					
304	2515.RM	FL.25	5	D054	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟฟ้าหรือสัญญาณร้ำลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
305	2501.RM	FL.25	5	D055	-	✓	-	-	-					
306	2502.RM	FL.25	5	D056	-	✓	-	-	-					
307	2503.RM	FL.25	5	D057	-	✓	-	-	-					
308	2504.RM	FL.25	5	D058	-	✓	-	-	-					
309	2505.RM	FL.25	5	D059	-	✓	-	-	-					
310	2505.RM	FL.25	5	D060	-	✓	-	-	-					
311	2612.RM	FL.26	5	D061	-	✓	-	-	-					
312	2611.RM	FL.26	5	D062	-	✓	-	-	-					
313	2610.RM	FL.26	5	D063	-	✓	-	-	-					
314	2609.RM	FL.26	5	D064	-	✓	-	-	-					
315	2608.RM	FL.26	5	D065	-	✓	-	-	-					
316	2607.RM	FL.26	5	D066	-	✓	-	-	-					
317	2606.RM	FL.26	5	D067	-	✓	-	-	-					
318	2614.RM	FL.26	5	D068	-	✓	-	-	-					
319	2616.RM	FL.26	5	D069	-	✓	-	-	-					
320	2618.RM	FL.26	5	D070	-	✓	-	-	-					
321	2620.RM	FL.26	5	D071	-	✓	-	-	-					
322	2615.RM	FL.26	5	D072	-	✓	-	-	-					
323	2615.RM	FL.26	5	D073	-	✓	-	-	-					
324	2601.RM	FL.26	5	D074	-	✓	-	-	-					
325	2602.RM	FL.26	5	D075	-	✓	-	-	-					
326	2603.RM	FL.26	5	D076	-	✓	-	-	-					
327	2604.RM	FL.26	5	D077	-	✓	-	-	-					
328	2605.RM	FL.26	5	D078	-	✓	-	-	-					
329	2605.RM	FL.26	5	D079	-	✓	-	-	-					
330	2712.RM	FL.27	6	D001	-	✓	-	-	-					
331	2707.RM	FL.27	6	D002	-	✓	-	-	-					
332	2707.RM	FL.27	6	D003	-	✓	-	-	-					
333	2707.RM	FL.27	6	D004	-	✓	-	-	-					
334	2706.RM	FL.27	6	D005	-	✓	-	-	-					
335	27014.RM	FL.27	6	D006	-	✓	-	-	-					
336	2716.RM	FL.27	6	D007	-	✓	-	-	-					
337	2718.RM	FL.27	6	D008	-	✓	-	-	-					
338	2715.RM	FL.27	6	D009	-	✓	-	-	-					
339	2715.RM	FL.27	6	D010	-	✓	-	-	-					
340	2701.RM	FL.27	6	D011	-	✓	-	-	-					
341	2702.RM	FL.27	6	D012	-	✓	-	-	-					
342	2703.RM	FL.27	6	D013	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟฟ้าหรือสัญญาณร้ำลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
343	2704.RM	FL.27	6	D014	-	✓	-	-	-					
344	2705.RM	FL.27	6	D015	-	✓	-	-	-					
345	2705.RM	FL.27	6	D016	-	✓	-	-	-					
346	2812.RM	FL.28	6	D017	-	✓	-	-	-					
347	2810.RM	FL.28	6	D018	-	✓	-	-	-					
348	2808.RM	FL.28	6	D019	-	✓	-	-	-					
349	2808.RM	FL.28	6	D020	-	✓	-	-	-					
350	2807.RM	FL.28	6	D021	-	✓	-	-	-					
351	2806.RM	FL.28	6	D022	-	✓	-	-	-					
352	2814.RM	FL.28	6	D023	-	✓	-	-	-					
353	2816.RM	FL.28	6	D024	-	✓	-	-	-					
354	2818.RM	FL.28	6	D025	-	✓	-	-	-					
355	2815.RM	FL.28	6	D026	-	✓	-	-	-					
356	2815.RM	FL.28	6	D027	-	✓	-	-	-					
357	2801.RM	FL.28	6	D028	-	✓	-	-	-					
358	2802.RM	FL.28	6	D029	-	✓	-	-	-					
359	2803.RM	FL.28	6	D030	-	✓	-	-	-					
360	2804.RM	FL.28	6	D031	-	✓	-	-	-					
361	2805.RM	FL.28	6	D032	-	✓	-	-	-					
362	2805.RM	FL.28	6	D033	-	✓	-	-	-					
363	2912.RM	FL.29	6	D034	-	✓	-	-	-					
364	2910.RM	FL.29	6	D035	-	✓	-	-	-					
365	2908.RM	FL.29	6	D036	-	✓	-	-	-					
366	2908.RM	FL.29	6	D037	-	✓	-	-	-					
367	2907.RM	FL.29	6	D038	-	✓	-	-	-					
368	2906.RM	FL.29	6	D039	-	✓	-	-	-					
369	2914.RM	FL.29	6	D040	-	✓	-	-	-					
370	2916.RM	FL.29	6	D041	-	✓	-	-	-					
371	2916.RM	FL.29	6	D042	-	✓	-	-	-					
372	2915.RM	FL.29	6	D043	-	✓	-	-	-					
373	2915.RM	FL.29	6	D044	-	✓	-	-	-					
374	2901.RM	FL.29	6	D045	-	✓	-	-	-					
375	2902.RM	FL.29	6	D046	-	✓	-	-	-					
376	2903.RM	FL.29	6	D047	-	✓	-	-	-					
377	2904.RM	FL.29	6	D048	-	✓	-	-	-					
378	2905.RM	FL.29	6	D049	-	✓	-	-	-					
379	2905.RM	FL.29	6	D050	-	✓	-	-	-					
380	3012.RM	FL.30	6	D051	-	✓	-	-	-					

Project : Fire Alarm

Location : Sofitel Bangkok Sukhumvit Hotel

Ground : ไฟฟ้าหรือสัญญาณร้ำลง Ground

Normal : ระบบทำงานเป็นปกติ

Trouble : สายขาด Open Circuit

Disable : ระบบการทำงานถูกปิดชั่วคราว

FIRE WORK SYSTEM & SERVICE

FIRE ALARM INSPECTIONS

19-20 มีนาคม 2569

No.	Location	Area	Loop	Point No.	System Status					Testing				Comment
					Invrep	Normal	Trouble	Disable	Ground	Test no.1	Test no.2	Test no.3	Test no.4	
381	3007.RM	FL.30	6	D052	-	✓	-	-	-					
382	3007.RM	FL.30	6	D053	-	✓	-	-	-					
383	3007.RM	FL.30	6	D054	-	✓	-	-	-					
384	3016.RM	FL.30	6	D055	-	✓	-	-	-					
385	3016.RM	FL.30	6	D056	-	✓	-	-	-					
386	3001.RM	FL.30	6	D058	-	✓	-	-	-					
387	3001.RM	FL.30	6	D059	-	✓	-	-	-					
388	3003.RM	FL.30	6	D060	-	✓	-	-	-					
389	3004.RM	FL.30	6	D061	-	✓	-	-	-					
390	3004.RM	FL.30	6	D062	-	✓	-	-	-					
391	PRIVATE DINNING	FL.32	6	D063	-	✓	-	-	-					
392	LIFT LOBBY	FL.32	6	D064	-	✓	-	-	-					
393	LIBRARY	FL.32	6	D065	-	✓	-	-	-	✓				
394	LIBRARY	FL.32	6	D066	-	✓	-	-	-					
395	EE/RM.	FL.32	6	D067	-	✓	-	-	-					

FIRE ALARM SYSTEM

FIRE WORK SYSTEM & SERVICE CO., LTD.

บริษัท ไฟร์ เวิร์ค ซิสเต็ม แอนด์ เซอร์วิส จำกัด

Maintenance Equipment for Fire Alarm Systems

(การตรวจสอบเชิงบำรุงรักษา อุปกรณ์และระบบสัญญาณแจ้งเตือนเหตุเพลิงไหม้)

Control Panel (ตู้ควบคุมระบบ)

- Check the signal cable connection point on the circuit board in the control panel that receives the signal from the Detector device of the system.
  ตรวจเช็คจุดเชื่อมต่อสายสัญญาณที่ตู้ควบคุมทำหน้าที่รับและส่งสัญญาณจากอุปกรณ์ตรวจจับในระบบ
- Check the power supply and battery. By checking the terminals and measuring the input voltage of the battery.
  ตรวจเช็คแหล่งจ่ายไฟและ แบตเตอรี่ โดยตรวจสอบขั้วต่อสายพร้อมวัดแรงดันไฟฟ้าเข้าของแบตเตอรี่
- Check the integrity of the display and notifications LED.
  ตรวจเช็คความสมบูรณ์ของจอแสดงผลและ LED แจ้งเตือน
- Check the integrity of the operation switch and response to function.
  ตรวจเช็คความสมบูรณ์ของสวิตช์ควบคุมการทำงานและการตอบสนองฟังก์ชั่นการทำงาน
- Clean the control panel in ready to use.
  ทำความสะอาดตู้ควบคุม ให้อยู่ในสภาพที่พร้อมใช้งาน



38/873 ถ.ไทยรามัญ แขวงสามวาตะวันตก เขตคลองสามวา กรุงเทพฯ 10510


38/873 THAIRAMAN ROAD, SAMWATAWANTOK, KHLONGSAMWA BANGKOK 10510 TEL 02-548-6074 FAX 02-509-0049

Email : fwss_alarm@hotmail.comwww.fwssthailand.com

Maintenance Equipment for Fire Alarm Systems
(การตรวจสอบเชิงบำรุงรักษา อุปกรณ์และระบบสัญญาณแจ้งเตือนเหตุเพลิงไหม้)

Graphic Annunciator (ตู้แผนผังแสดงจุดที่มีการแจ้งเตือนเหตุ)

- Check the LED indicator. And the signaling device sends alarm signals from the circuit (Buzzer). From the cabinet, the map displays the points that are being notified (Graphic Annunciator). Be in ready to use.
  ตรวจเช็คหลอดไฟ LED และอุปกรณ์ส่งสัญญาณจะส่งสัญญาณเตือนจากวงจร(Buzzer)จากตู้แผนผังแสดงจุดที่มีการแจ้งให้เตือนจากระบบ (Graphic Annunciator) ให้อยู่ในสภาพพร้อมใช้งาน
- Clean the Graphic Annunciator cabinet to be in a ready-to-use condition
  ทำความสะอาดตู้แผนผังแสดงจุดที่มีการแจ้ง ให้อยู่ในสภาพที่พร้อมใช้งาน




38/873 ถ.ไทยรามัญ แขวงสามวาตะวันตก เขตคลองสามวา กรุงเทพฯ 10510
38/873 THAIRAMAN ROAD, SAMWATAWANTOK, KHLONGSAMWA BANGKOK 10510 TEL 02-548-6074 FAX 02-509-0049
Email : fwss_alarm@hotmail.comwww.fwssthailand.com

FIRE ALARM SYSTEM
FIRE WORK SYSTEM & SERVICE CO., LTD.
บริษัท ไฟร์ เวิร์ค ซิสเต็ม แอนด์ เซอร์วิส จำกัด

Maintenance Equipment for Fire Alarm Systems
(การตรวจสอบเชิงบำรุงรักษา อุปกรณ์และระบบสัญญาณแจ้งเตือนเหตุเพลิงไหม้)

Smoke Detector (อุปกรณ์ตรวจจับควันไฟ)

- The test uses a simulated smoke generator, such as a Smoke tester, to test detection and the response signal is sent back to the Control panel and displayed to other peripherals in the system.
  การทดสอบจะใช้อุปกรณ์สร้างควันจำลอง เช่น สเปรย์ควันทดลองเพื่อทดสอบการตรวจจับและการส่งสัญญาณตอบสนองกลับไปที่ตู้ควบคุมและแสดงผลไปที่อุปกรณ์ต่อพ่วงอื่นๆ ในระบบ




38/873 ถ.ไทยรามัญ แขวงสามวาตะวันตก เขตคลองสามวา กรุงเทพฯ 10510
38/873 THAIRAMAN ROAD, SAMWATAWANTOK, KHLONGSAMWA BANGKOK 10510 TEL 02-548-6074 FAX 02-509-0049
Email : fwss_alarm@hotmail.comwww.fwssthailand.com

FIRE ALARM SYSTEM
FIRE WORK SYSTEM & SERVICE CO., LTD.
บริษัท ไฟร์ เวิร์ค ซิสเต็ม แอนด์ เซอร์วิส จำกัด

Maintenance Equipment for Fire Alarm Systems
(การตรวจสอบเชิงบำรุงรักษา อุปกรณ์และระบบสัญญาณแจ้งเตือนเหตุเพลิงไหม้)

Heat Detector(อุปกรณ์ตรวจจับความร้อน)

- The test uses heat generation equipment. To test the operation of the heat detector Along with checking the situation of the equipment alerts and sending alarm signals to the source control cabinet or other peripherals
  การทดสอบใช้อุปกรณ์กำเนิดความร้อน เพื่อทดสอบการทำงานของอุปกรณ์ตรวจจับความร้อน พร้อมเช็คสถานการณ์แจ้งเตือนของอุปกรณ์ และ การส่งสัญญาณแจ้งเหตุไปยังตู้ควบคุมต้นทางหรืออุปกรณ์ต่อพ่วงอื่นๆ



38/873 ถ.ไทยรามัญ แขวงสามวาตะวันตก เขตคลองสามวา กรุงเทพฯ 10510
38/873 THAIRAMAN ROAD, SAMWATAWANTOK, KHLONGSAMWA BANGKOK 10510 TEL 02-548-6074 FAX 02-509-0049
Email : fwss_alarm@hotmail.comwww.fwssthailand.com

FIRE ALARM SYSTEM
FIRE WORK SYSTEM & SERVICE CO., LTD.
บริษัท ไฟร์ เวิร์ค ซิสเต็ม แอนด์ เซอร์วิส จำกัด

Maintenance Equipment for Fire Alarm Systems
(การตรวจสอบเชิงบำรุงรักษา อุปกรณ์และระบบสัญญาณแจ้งเตือนเหตุเพลิงไหม้)

Manual Station(อุปกรณ์แจ้งเหตุด้วยมือผู้ใช้)

- Test user notification device (Manual Station). By testing the availability of equipment various with actual use. Such as pulling the lever (Pull Down), Push Button or break the glass to break (Break glass). To inform according to the usage of the device
  ทดสอบอุปกรณ์แจ้งเหตุด้วยมือผู้ใช้ (Manual Station) โดยทดสอบความพร้อมของอุปกรณ์ต่างๆ ด้วยการใช้งานจริง เช่น การดึงคันโยก (Pull Down) การกดปุ่ม (Push Button) หรือทุบกระจกให้แตก (Break glass) เพื่อแจ้งเหตุตามลักษณะการใช้งานของอุปกรณ์
- Cleaning equipment.
  ทำความสะอาดอุปกรณ์




38/873 ถ.ไทยรามัญ แขวงสามวาตะวันตก เขตคลองสามวา กรุงเทพฯ 10510
38/873 THAIRAMAN ROAD, SAMWATAWANTOK, KHLONGSAMWA BANGKOK 10510 TEL 02-548-6074 FAX 02-509-0049
Email : fwss_alarm@hotmail.comwww.fwssthailand.com

Maintenance Equipment for Fire Alarm Systems
(การตรวจสอบเชิงบำรุงรักษา อุปกรณ์และระบบสัญญาณแจ้งเตือนเหตุเพลิงไหม้)

ตู้ควบคุมระบบ Fire Alarm Control Panel
ตู้แสดง Graphic Annunciator

- Check the control panel of the receiving signal system is stuck.
  ตรวจเช็คแผงควบคุมระบบรับสัญญาณ LED ติดค้าง ปกติ
- Check the notification sound Fire incident
  ตรวจเช็คเสียงแจ้งเตือน การเกิดเหตุเพลิงไหม้
- Test of Receive-send signal between the control cabinet, send signal to the cabinet, map showing the incident spot Fire displays. The notification (LED) and computers (PC) in the event of a fire.
  ทดสอบการ รับ-ส่ง สัญญาณระหว่างตู้ควบคุมส่งสัญญาณไปยังตู้แผนผังแสดงจุดเกิดเหตุ
  เพลิงไหม้ LED แจ้งเตือน และ คอมพิวเตอร์ (PC) เมื่อเกิดเหตุเพลิงไหม้
- Show status and location map to match the location of the incident.
  แสดงสถานะแจ้ง Location Map ตรงตามตำแหน่งที่เกิดเหตุ




38/873 ถ.ไทยรามัญ แขวงสามวาตะวันตก เขตคลองสามวา กรุงเทพฯ 10510
38/873 THAIRAMAN ROAD, SAMWATAWANTOK, KHLONGSAMWA BANGKOK 10510 TEL 02-548-6074 FAX 02-509-0049
Email : fwss_alarm@hotmail.comwww.fwssthailand.com

ภาคผนวก

อุปกรณ์ที่ใช้ในการทดสอบ SMOKE DETECTOR



อุปกรณ์ที่ใช้ในการทดสอบ HEAT DETECTOR



อุปกรณ์ที่ใช้ในการทดสอบ

Solo 100/101/108 Telescopic Access Poles

The core element of the Solo range is the telescopic and extension access poles which are extremely lightweight and quickly extend to provide access to detectors up to 9 metres*.



สเปรย์ควันเทียมทดสอบ SMOKE DETECTOR



อุปกรณ์ที่ใช้ในการปฏิบัติงาน



มิเตอร์ดิจิตอล



วิทยุสื่อสาร



บันได



ปลั๊กไฟพ่วง



ชุดไขควง



ชุดคีม

อุปกรณ์ที่ใช้ในการทำความสะอาด



ครีมทำความสะอาด



ผ้าทำความสะอาดอุปกรณ์



แปรงทำความสะอาดอุปกรณ์




โบเวอร์

PREVENTIVE MAINTENANCE AND TESTING REPORT

GAS SUPPRESSION AND WET CHEMICAL SYSTEM

SOFITEL BANGKOK HOTEL



25 MARCH 2026

FIRE WORK SYSTEM & SERVICE CO., LTD.

น.3/59

FIRE WORK System & SERVICE CO., LTD.

38/873 THAIRAMAN ROAD ,SAMWATAWANTOK,

KHLONGSAMWA BANGKOK 10510 TEL 02-5486074 FAX 02-509-0049

Test Function System

Gas Suppression

System ☑ CO_2 ☐ FM-200 ☐ N_2 ☐ Other

Test Record and Commissioning Gas Suppression System	Control Panel	: KIDDE / AEGIS	Project : Sofitel Bangkok Hotels
	Cylinder	: KIDDE	Building : Sofitel Bangkok Hotels
	Pressure	-	Room : Generator room
	Sum	: 1 cylinder	Date : 25/3/2026

System	Action	Bell	Horn	Strobe	Shutdown	Lamp on panel	Test result	Remark
Normal	None	Off	Off	Off	Run		☑ Yes ☐ No	
Detector A or B	Activated	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☐ No	
Detector A and B	Activated	☐ Off ☐ On	☐ Off ☐ On	☐ Off ☐ On	☐ Off ☐ On	☐ Off ☐ On	☐ Yes ☐ No	
Abort	Activated Count down ..60…. sec	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☐ No	
	Control Head Trigger	☐ Off ☐ On	☐ Off ☐ On	☐ Off ☐ On	☐ Off ☐ On	☐ Off ☐ On	☐ Yes ☐ No	
Manual	Control Head Count down …0…. sec	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☐ No	
Pressure Switch	Activated	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☐ No	
Reset	Reset	☐ Off ☐ On	☐ Off ☐ On	☐ Off ☐ On	☐ Off ☐ On	Normal	☐ Yes ☐ No	

Remark : Battery = 27.00 VDC

System Normal

Inspected By FWSS

Signature : [redacted]

Name :

Date :

Customer By Sofitel Bangkok Hotels

Signature :

Name :

Date :

FIRE WORK SYSTEM & SERVICE CO., LTD.

Tel.02-548-6074 Fax. 02-509-0049

Date : 25/3/2026

Project : Sofitel Bangkok Hotels

Inspection and testing

Photo	Description
	Photo: Before work Location: Generator room - Preparatory work before the test.
	Photo: Test Heat Location: Generator room - Testing of Heat,By Heatgun
	Photo: Test Cabinets Control Location: Generator room - Test run of cabinets Control Panel.
	Photo: Test Manual Location: Generator room - Test run of Manual.


FIRE WORK SYSTEM & SERVICE CO., LTD.

Tel.02-548-6074 Fax. 02-509-0049

Date : 25/3/2026

Project : Sofitel Bangkok Hotels

Inspection and testing

Photo	Description
	Photo: Test Abort Location: Generator room - Test run of Abort
	Photo: Test Solenoid Location: Generator room - Test run of Solenoid
	Photo: Test Horn (Outside) Location: Generator room - Test run of Horn.
	Photo: Test Horn (Inside) Location: Generator room - Test run of Horn.

FIRE WORK SYSTEM & SERVICE CO., LTD.

Tel.02-548-6074 Fax. 02-509-0049

Date : 25/3/2026

Project : Sofitel Bangkok Hotels

Inspection and testing

Photo	Description
	Photo: Check the Pressue Switch Location: Generator room - Check the pressue switch at the CO_2 tank.
	Photo: Battery Location: Generator room - Check normal backup power
	Photo: Clean up Location: Generator room - Clean the equipment inside the system.
	Photo: System Normal Location: Generator room -System Normal.

FIRE WORK SYSTEM & SERVICE CO., LTD.

38/873 THAIRAMAN ROAD ,SAMWATAWANTOK,

KHLONGSAMWA BANGKOK 10510 TEL 02-5486074 FAX 02-509-0049

Test Function System

Gas Suppression

System ☑ CO_2 ☐ FM-200 ☐ N_2 ☐ Other

Test Record and Commissioning Gas Suppression System	Control Panel	: KIDDE / AEGIS	Project	: Sofitel Bangkok Hotels
	Cylinder	: KIDDE	Building	: Sofitel Bangkok Hotels
	Pressure	-	Room	: Main Distribution Board Room
	Sum	: 3 cylinder	Date	: 25/3/2026

System	Action	Bell	Horn	Strobe	Shutdown	Lamp on panel	Test result	Remark
Normal	None	Off	Off	Off	Run	Normal	☑ Yes ☐ No	
Detector A or B	Activated	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☐ No	
Detector A and B	Activated	☐ Off ☐ On	☐ Off ☐ On	☐ Off ☐ On	☐ Off ☐ On	☐ Off ☐ On	☐ Yes ☐ No	
Abort	Activated Count down ..60…. sec	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☑ Yes ☐ No	
	Control Head Trigger	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☐ No	
Manual	Control Head Count down …0…. sec	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☑ Off ☐ On	☐ Off ☑ On	☑ Yes ☐ No	
Pressure Switch	Activated	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☑ Yes ☐ No	
Reset	Reset	☑ Off ☐ On	☑ Off ☐ On	☑ Off ☐ On	☑ Off ☐ On	Normal	☑ Yes ☐ No	

Remark : Battery = 27.03 VDC

The buzzer at the control cabinet is damaged, no alarm buzzer sound

but the main function is still working normally.

SYSTEM NORMAL

Inspected By FWSS

Signature : [redacted]

Name :

Date :

Customer By Sofitel Bangkok Hotels

Signature :

Name :

Date :



FIRE WORK SYSTEM& SERVICE CO., LTD.

Tel.02-548-6074 Fax. 02-509-0049

Date : 25/3/2026

Project : Sofitel Bangkok Hotels

Inspection and testing

Photo	Description
	Photo: Before work Location: Main Distribution Board Room - Preparatory work before the test. Open cabinets Main Distribution Board to test smoke detector.
	Photo: Test Smoke Location: Main Distribution Board Room - Spray Testing of Smoke
	Photo: Test Cabinets Control Location: Main Distribution Board Room - Test run of cabinets Control Panel.
	Photo: Test Manual Location: Main Distribution Board Room - Test run of Manual.

FIRE WORK SYSTEM& SERVICE CO., LTD.

Tel.02-548-6074 Fax. 02-509-0049

Date : 25/3/2026

Project : Sofitel Bangkok Hotels

Inspection and testing

Photo	Description
	Photo: Test Abort Location: Main Distribution Board Room - Test run of Abort
	Photo: Test Solenoid Location: Main Distribution Board Room - Test run of Solenoid
	Photo: Test Horn (Outside) Location: Main Distribution Board Room - Test run of Horn.
	Photo: Test Horn (Inside) Location: Main Distribution Board Room - Test run of Horn.



FIRE WORK SYSTEM& SERVICE CO., LTD.

Tel.02-548-6074 Fax. 02-509-0049

Date : 25/3/2026

Project : Sofitel Bangkok Hotels

Inspection and testing

Photo	Description
	Photo: Check the Pressue Switch Location: Main Distribution Board Room - Check the pressue switch at the CO_2 tank.
	Photo: Battery Location: Main Distribution Board Room - Check normal backup power
	Photo: Clean up Location: Main Distribution Board Room - Clean the equipment inside the system.
	Photo: System Normal Location: Main Distribution Board Room - System Normal

FIRE WORK SYSTEM & SERVICE CO., LTD.

38/873 THAIRAMAN ROAD ,SAMWATAWANTOK,

KHLONGSAMWA BANGKOK 10510 TEL 02-5486074 FAX 02-509-0049

Test Function System

Gas Suppression

System ☐ CO_2 ☑ FM-200 ☐ N_2 ☐ Other

Test Record and Commissioning Gas Suppression System			
Control Panel	: KIDDE / AEGIS	Project	: Sofitel Bangkok Hotels
Cylinder	: KIDDE	Building	: Sofitel Bangkok Hotels
Pressure	: 360 psi	Room	: Server Room
Sum	: 1 cylinder	Date	: 25/3/2026

System	Action	Bell	Horn	Strobe	Shutdown	Lamp on panel	Test result	Remark
Normal	None	Off	Off	Off	Run	Normal	☑ Yes ☐ No	
Detector A or B	Activated	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☑ No	Signal to SMS
Detector A and B	Activated	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☑ No	Signal to SMS
Abort	Activated Count down ..60…. sec	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☑ No	Signal to SMS
	Control Head Trigger	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☑ No	
Manual	Control Head Count down …0…. sec	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☑ No	Signal to SMS
Pressure Switch	Activated	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Yes ☑ No	Signal to SMS
Reset	Reset	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	☐ Off ☑ On	Normal	☑ Yes ☐ No	

Remark : Battery = 27.21 VDC

System Normal

Inspected By FWSS

Signature : [redacted]

Name :

Date :

Customer By Sofitel Bangkok Hotels

Signature :

Name :

Date :

FIRE WORK SYSTEM& SERVICE CO., LTD.

Tel.02-548-6074 Fax. 02-509-0049

Date : 25/3/2026

Project : Sofitel Bangkok Hotels

Inspection and testing

Photo	Description
	Photo: Before work Location: Server Room - Preparatory work before the test.
	Photo: Test Smoke Location: Server Room - Spray Testing of Smoke.
	Photo: Test Cabinets Control Location: Server Room - Test run of cabinets Control Panel.
	Photo: Test Manual Location: Server Room - Test run of Manual.



FIRE WORK SYSTEM& SERVICE CO., LTD.

Tel.02-548-6074 Fax. 02-509-0049

Date : 25/3/2026

Project : Sofitel Bangkok Hotels

Inspection and testing

Photo	Description
	Photo: Test Abort Location: Server Room - Test run of Abort.
	Photo: Test Solenoid Location: Server Room - Test run of Solenoid.
	Photo: Test Horn (Outside) Location: Server Room - Test run of Horn.
	Photo: Test Horn (Inside) Location: Server Room - Test run of Horn.

FIRE WORK SYSTEM& SERVICE CO., LTD.

Tel.02-548-6074 Fax. 02-509-0049

Date : 25/3/2026

Project : Sofitel Bangkok Hotels

Inspection and testing

Photo	Description
	Photo: Check the pressure inside the tank Location: Server Room - Check the pressure inside the tank by reading the Pressur Gauge. 360 psi normal
	Photo: Check Pressue Switch Location: Server Room - Check the pressue switch at the FM-200 tank.
	Photo: Battery Location: Server Room - Check normal backup power
	Photo: Clean up Location: Server Room - Clean the equipment inside the system.

FIRE WORK SYSTEM& SERVICE CO., LTD. Tel.02-548-6074 Fax. 02-509-0049	Date : 25/3/2026 Project : Sofitel Bangkok Hotels

Inspection and testing

Photo	Description	
	Photo	System Normal
	Location	Server Room
	- System Normal	

FIRE WORK SYSTEM & SERVICE CO., LTD.
38/873 THAIRAMAN ROAD ,SAMWATAWANTOK,
KHLONGSAMWA BANGKOK 10510 TEL 02-5486074 FAX 02-509-0049

Project : Sofitel Bangkok Hotels
Location : Kitchen Floor.31
Building : Sofitel Bangkok Hotels
Brand : Ansul
Date : 25/3/2026

Test Report For Wet Chemical

Checklist of Equipment

Item	Description	Pass	Fail	Remark
1	**Detector**			
	Fusible Link,Type	√		
2	**Basic System(Not Include Cartridge)**			
	Mechanical "Ansul Automan"			
	3.0 Gallon In Stainless Steel For Mechanical	√		
	1.5 Gallon In Stainless Steel For Mechanical	√		
	3.0 Gallon Reaulated Actuator Assembly	√		
	3.0 Gallon Stainless Tank in Stainless Enclosure	√		
3	**Remote Pull Station**			
	Remote Pull Station	√		
	Break Rod	√		
	Break Away Rod	—		
	Wire Rope	√		
4	**Gas Shut Off Equipment**			
	Gas Valve,Mechanical Size:……	—		
	Solenoild Valve Size:…….	—		
	Relay-Manual Reset	—		
5	**Nozzles(All Nozzles Inclue Blow-off Caps)**			
	Nozzle For Appliance	√		
	Nozzle For Plenum	√		
	Nozzle For Duct	—		
6	**Agent**			
	1.5 Gallon (5.7 lt) ANSULEX	√		
	3.0 Gallon (11.4 lt) ANSULEX	√		
7	**Cartridges**			
	Cartridges, Nitrogen,LT-20-R	—		
	Cartridges, Nitrogen,LT-30-R	√		
	Cartridges, Nitrogen,R-102-R	—		
	Cartridges, Nitrogen,LT-101-30	—		

Testing System

Item	Description	Pass	Fail	Remark
1	**Testing Mechanical Gas Valve**			
	Remove Gas Cartidge and Simulate			
	Automatic Trip of System Below			
	A.Gas Valve Closs(if Applicable) and So Indicates	—		
	B.Check burner for Gaseous Odor	—		
2	**Testing Manual Pull Station**			
	Simulate Manual Pull Trip of System,			
	Removeglass break Rod and Pull ring handle			
	on Pull Station			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,	—		
	(Snap-action)Fuse off,Fan On			
3	**Testing Detector System**			
	Simulate Automatic Trip of System,			
	Remove Fusible link and install atest link			
	and cut for simulate			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,			
	(Snap-action)Fuse off,Fan On			
	C.Alarm Warning,(Strobe light"Flash")			




Remark : System All Normal

Inspected By : [redacted]
Date :

Customer By : Sofitel Bangkok Hotels
Date :

FIRE WORK SYSTEM & SERVICE CO., LTD. Tel. 02-548-6074 Fax. 02-509-0049	Date : 25 March 2026 Project : Sofitel Bangkok Hotels


Inspection and Testing

Photo	Description	
	Photo	Check the System and Equipment Wet Chemical
	Location	Kitchen Floor.31
	- Check the overall condition of the tank system and equipment.	
	Wet Chemical System	
	Photo	Check Fuse Detector
	Location	Kitchen Floor.31
	- Check Fuse Detector	
	Photo	Cleaning
	Location	Kitchen Floor.31
	- Cleaning Nozzle	
	Photo	Test wet chemical System
	Location	Kitchen Floor.31
	- Test Wet Chemical System by removing the Fuse	
	and cutting the Fuse System Normal	
	Photo	Check the tank wet chemical
	Location	Kitchen Floor.31
	- Check the Wet Chemical tank to be in ready condition.	

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels

Inspection and Testing

Photo	Description
	Photo: Cleaning Location: Kitchen Floor.31 - Cleaning Fuse Detector
	Photo: Test Manual Location: Kitchen Floor.31 - Test run of Manual.
	Photo: Check the mechanism of the tank Wet chemical Location: Kitchen Floor.31 - Check the mechanism of the tank Wet Chemical
	Photo: Reset Wet chemical System Location: Kitchen Floor.31 - Reset Wet Chemical System

FIRE WORK SYSTEM & SERVICE CO., LTD.
38/873 THAIRAMAN ROAD ,SAMWATAWANTOK,
KHLONGSAMWA BANGKOK 10510 TEL 02-5486074 FAX 02-509-0049

Project : Sofitel Bangkok Hotels
Location : Kitchen Floor.7-1
Building : Sofitel Bangkok Hotels
Brand : Anaul
Date : 25/3/2026

Test Report For Wet Chemical

Checklist of Equipment

Item	Description	Pass	Fail	Remark
1	**Detector**			
	Fusible Link,Type	√		
2	**Basic System(Not Include Cartridge)**			
	Mechanical "Ansul Automan"			
	3.0 Gallon In Stainless Steel For Mechanical	√		
	1.5 Gallon In Stainless Steel For Mechanical	√		
	3.0 Gallon Reaulated Actuator Assembly	√		
	3.0 Gallon Stainless Tank in Stainless Enclosure	√		
3	**Remote Pull Station**			
	Remote Pull Station	√		
	Break Rod	√		
	Break Away Rod	—		
	Wire Rope	√		
4	**Gas Shut Off Equipment**			
	Gas Valve,Mechanical Size:…3/4……	√		
	Solenoild Valve Size:…….	—		
	Relay-Manual Reset	—		
5	**Nozzles(All Nozzles Inclue Blow-off Caps)**			
	Nozzle For Appliance	√		
	Nozzle For Plenum	√		
	Nozzle For Duct	—		
6	**Agent**			
	1.5 Gallon (5.7 lt) ANSULEX	√		
	3.0 Gallon (11.4 lt) ANSULEX	√		
7	**Cartridges**			
	Cartridges, Nitrogen,LT-20-R	√		
	Cartridges, Nitrogen,LT-30-R	—		
	Cartridges, Nitrogen,R-102-R	—		
	Cartridges, Nitrogen,LT-101-30	—		

Testing System

Item	Description	Pass	Fail	Remark
1	**Testing Mechanical Gas Valve**			
	Remove Gas Cartidge and Simulate			
	Automatic Trip of System Below			
	A.Gas Valve Closs(if Applicable) and So Indicates	√		
	B.Check burner for Gaseous Odor	√		
2	**Testing Manual Pull Station**			
	Simulate Manual Pull Trip of System,			
	Removeglass break Rod and Pull ring handle			
	on Pull Station			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,	—		
	(Snap-action)Fuse off,Fan On			
3	**Testing Detector System**			
	Simulate Automatic Trip of System,			
	Remove Fusible link and install atest link			
	and cut for simulate			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,			
	(Snap-action)Fuse off,Fan On			
	C.Alarm Warning,(Strobe light"Flash")			

Remark : System All Normal

Inspected By [redacted]
Date :

Customer By : Sofitel Bangkok Hotels
Date :

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels


Inspection and Testing

Photo	Description
	Photo: Check the System and Equipment Wet Chemical Location: Kitchen Floor.7-1 - Check the overall condition of the tank system and equipment. Wet Chemical System
	Photo: Check Fuse Detector Location: Kitchen Floor.7-1 - Check Fuse Detector
	Photo: Cleaning Location: Kitchen Floor.7-1 - Cleaning Nozzle
	Photo: Test wet chemical System Location: Kitchen Floor.7-1 - Test Wet Chemical System by removing the Fuse and cutting the Fuse System Normal
	Photo: Check the tank wet chemical Location: Kitchen Floor.7-1 - Check the Wet Chemical tank to be in ready condition.

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels

Inspection and Testing

Photo	Description
	Photo: Cleaning Location: Kitchen Floor.7-1 - Cleaning Fuse Detector
	Photo: Test Manual Location: Kitchen Floor.7-1 - Test run of Manual.
	Photo: Check the mechanism of the tank Wet chemical Location: Kitchen Floor.7-1 - Check the mechanism of the tank Wet Chemical
	Photo: Reset Wet chemical System Location: Kitchen Floor.7-1 - Reset Wet Chemical System

FIRE WORK SYSTEM & SERVICE CO., LTD.
38/873 THAIRAMAN ROAD ,SAMWATAWANTOK,
KHLONGSAMWA BANGKOK 10510 TEL 02-5486074 FAX 02-509-0049

Project : Sofitel Bangkok Hotels
Location : Kitchen Floor.7-2
Building : Sofitel Bangkok Hotels
Brand : Ansul
Date : 25/3/2026

Test Report For Wet Chemical

Checklist of Equipment

Item	Description	Pass	Fail	Remark
1	**Detector**			
	Fusible Link,Type	√		
2	**Basic System(Not Include Cartridge)**			
	Mechanical "Ansul Automan"			
	3.0 Gallon In Stainless Steel For Mechanical	√		
	1.5 Gallon In Stainless Steel For Mechanical	√		
	3.0 Gallon Reaulated Actuator Assembly	√		
	3.0 Gallon Stainless Tank in Stainless Enclosure	√		
3	**Remote Pull Station**			
	Remote Pull Station	√		
	Break Rod	√		
	Break Away Rod	—		
	Wire Rope	√		
4	**Gas Shut Off Equipment**			
	Gas Valve,Mechanical Size:…3/4……	√		
	Solenoild Valve Size:…….	—		
	Relay-Manual Reset	—		
5	**Nozzles(All Nozzles Inclue Blow-off Caps)**			
	Nozzle For Appliance	√		
	Nozzle For Plenum	√		
	Nozzle For Duct	—		
6	**Agent**			
	1.5 Gallon (5.7 lt) ANSULEX	√		
	3.0 Gallon (11.4 lt) ANSULEX	√		
7	**Cartridges**			
	Cartridges, Nitrogen,LT-20-R	√		
	Cartridges, Nitrogen,LT-30-R	√		
	Cartridges, Nitrogen,R-102-R	—		
	Cartridges, Nitrogen,LT-101-30	—		

Testing System

Item	Description	Pass	Fail	Remark
1	**Testing Mechanical Gas Valve**			
	Remove Gas Cartidge and Simulate			
	Automatic Trip of System Below			
	A.Gas Valve Closs(if Applicable) and So Indicates	√		
	B.Check burner for Gaseous Odor	√		
2	**Testing Manual Pull Station**			
	Simulate Manual Pull Trip of System,			
	Removeglass break Rod and Pull ring handle			
	on Pull Station			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,	—		
	(Snap-action)Fuse off,Fan On			
3	**Testing Detector System**			
	Simulate Automatic Trip of System,			
	Remove Fusible link and install atest link			
	and cut for simulate			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,			
	(Snap-action)Fuse off,Fan On			
	C.Alarm Warning,(Strobe light"Flash")			

Remark : System All Normal

ในคราชั้น 7 (2) สถิงถ้าทำให้ Function ไม่เป็นไปตามการทำงานจริง คือ เมื่อมีการตัด Fuse Test ตัวไหนตัวหนึ่งใน 3 จุด แล้ว
กดไกหัวถังไม่สั่งปิด R102 ต่อเมื่อตัด Fuse Test อีก 1 จุดถึงจะสั่งยิดได้ ดังนั้นจึงไม่เป็นไปตาม Function

Inspected By : [redacted]
Date :

Customer By : Sofitel Bangkok Hotels
Date :

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels


Inspection and Testing

Photo	Description
	Photo: Check the System and Equipment Wet Chemical Location: KITCHEN FLOOR.7-2 - Check the overall condition of the tank system and equipment. Wet Chemical System
	Photo: Check Fuse Detector Location: KITCHEN FLOOR.7-2 - Check Fuse Detector
	Photo: Cleaning Location: KITCHEN FLOOR.7-2 - Cleaning Nozzle
	Photo: Test wet chemical System Location: KITCHEN FLOOR.7-2 - Test Wet Chemical System by removing the Fuse and cutting the Fuse System Normal
	Photo: Check the tank wet chemical Location: KITCHEN FLOOR.7-2 - Check the Wet Chemical tank to be in ready condition.

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels

Inspection and Testing

Photo	Description
	Photo: Cleaning Location: KITCHEN FLOOR.7-2 - Cleaning Fuse Detector
	Photo: Test Manual Location: KITCHEN FLOOR.7-2 - Test run of Manual.
	Photo: Check the mechanism of the tank Wet chemical Location: KITCHEN FLOOR.7-2 - Check the mechanism of the tank Wet Chemical
	Photo: Reset Wet chemical System Location: KITCHEN FLOOR.7-2 - Reset Wet Chemical System

FIRE WORK SYSTEM & SERVICE CO., LTD.
38/873 THAIRAMAN ROAD ,SAMWATAWANTOK,
KHLONGSAMWA BANGKOK 10510 TEL 02-5486074 FAX 02-509-0049

Project : Sofitel Bangkok Hotels
Location : Kitchen Floor.6
Building : Sofitel Bangkok Hotels
Brand : Ansul
Date : 25/3/2026

Test Report For Wet Chemical

Checklist of Equipment

Item	Description	Pass	Fail	Remark
1	**Detector**			
	Fusible Link,Type	√		
2	**Basic System(Not Include Cartridge)**			
	Mechanical "Ansul Automan"			
	3.0 Gallon In Stainless Steel For Mechanical	√		
	1.5 Gallon In Stainless Steel For Mechanical	√		
	3.0 Gallon Reaulated Actuator Assembly	√		
	3.0 Gallon Stainless Tank in Stainless Enclosure	√		
3	**Remote Pull Station**			
	Remote Pull Station	√		
	Break Rod	√		
	Break Away Rod	—		
	Wire Rope	√		
4	**Gas Shut Off Equipment**			
	Gas Valve,Mechanical Size:…3/4……	√		
	Solenoild Valve Size:…….	—		
	Relay-Manual Reset	—		
5	**Nozzles(All Nozzles Inclue Blow-off Caps)**			
	Nozzle For Appliance	√		
	Nozzle For Plenum	√		
	Nozzle For Duct	—		
6	**Agent**			
	1.5 Gallon (5.7 lt) ANSULEX	√		
	3.0 Gallon (11.4 lt) ANSULEX	√		
7	**Cartridges**			
	Cartridges, Nitrogen,LT-20-R	√		
	Cartridges, Nitrogen,LT-30-R	—		
	Cartridges, Nitrogen,R-102-R	—		
	Cartridges, Nitrogen,LT-101-30	—		

Testing System

Item	Description	Pass	Fail	Remark
1	**Testing Mechanical Gas Valve**			
	Remove Gas Cartidge and Simulate			
	Automatic Trip of System Below			
	A.Gas Valve Closs(if Applicable) and So Indicates	√		
	B.Check burner for Gaseous Odor	√		
2	**Testing Manual Pull Station**			
	Simulate Manual Pull Trip of System,			
	Removeglass break Rod and Pull ring handle			
	on Pull Station			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,	—		
	(Snap-action)Fuse off,Fan On			
3	**Testing Detector System**			
	Simulate Automatic Trip of System,			
	Remove Fusible link and install atest link			
	and cut for simulate			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,			
	(Snap-action)Fuse off,Fan On			
	C.Alarm Warning,(Strobe light"Flash")			

Remark : System All Normal


Inspected By [redacted]
Date :

Customer By : Sofitel Bangkok Hotels
Date :

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels

Inspection and Testing

Photo	Description
	Photo: Check the System and Equipment Wet Chemical Location: Kitchen Floor.6 - Check the overall condition of the tank system and equipment. Wet Chemical System
	Photo: Check Fuse Detector Location: Kitchen Floor.6 - Check Fuse Detector
	Photo: Cleaning Location: Kitchen Floor.6 - Cleaning Nozzle
	Photo: Test wet chemical System Location: Kitchen Floor.6 - Test Wet Chemical System by removing the Fuse and cutting the Fuse System Normal
	Photo: Check the tank wet chemical Location: Kitchen Floor.6 - Check the Wet Chemical tank to be in ready condition.

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels

Inspection and Testing

Photo	Description
	Photo: Cleaning Location: Kitchen Floor.6 - Cleaning Fuse Detector
	Photo: Test Manual Location: Kitchen Floor.6 - Test run of Manual.
	Photo: Check the mechanism of the tank Wet chemical Location: Kitchen Floor.6 - Check the mechanism of the tank Wet Chemical
	Photo: Reset Wet chemical System Location: Kitchen Floor.6 - Reset Wet Chemical System

FIRE WORK SYSTEM & SERVICE CO., LTD.
38/873 THAIRAMAN ROAD ,SAMWATAWANTOK,
KHLONGSAMWA BANGKOK 10510 TEL 02-5486074 FAX 02-509-0049

Project : Sofitel Bangkok Hotels
Location : Kitchen Floor.4
Building : Sofitel Bangkok Hotels
Brand : Ansul
Date : 25/3/2026

Test Report For Wet Chemical

Checklist of Equipment

Item	Description	Pass	Fail	Remark
1	**Detector**			
	Fusible Link,Type	√		
2	**Basic System(Not Include Cartridge)**			
	Mechanical "Ansul Automan"			
	3.0 Gallon In Stainless Steel For Mechanical	√		
	1.5 Gallon In Stainless Steel For Mechanical	—		
	3.0 Gallon Reaulated Actuator Assembly	√		
	3.0 Gallon Stainless Tank in Stainless Enclosure	√		
3	**Remote Pull Station**			
	Remote Pull Station	√		
	Break Rod	√		
	Break Away Rod	—		
	Wire Rope	√		
4	**Gas Shut Off Equipment**			
	Gas Valve,Mechanical Size:……	—		
	Solenoild Valve Size:…….	—		
	Relay-Manual Reset	—		
5	**Nozzles(All Nozzles Inclue Blow-off Caps)**			
	Nozzle For Appliance	√		
	Nozzle For Plenum	√		
	Nozzle For Duct	—		
6	**Agent**			
	1.5 Gallon (5.7 lt) ANSULEX	—		
	3.0 Gallon (11.4 lt) ANSULEX	√		
7	**Cartridges**			
	Cartridges, Nitrogen,LT-20-R	√		
	Cartridges, Nitrogen,LT-30-R	—		
	Cartridges, Nitrogen,R-102-R	—		
	Cartridges, Nitrogen,LT-101-30	—		

Testing System

Item	Description	Pass	Fail	Remark
1	**Testing Mechanical Gas Valve**			
	Remove Gas Cartidge and Simulate			
	Automatic Trip of System Below			
	A.Gas Valve Closs(if Applicable) and So Indicates	—		
	B.Check burner for Gaseous Odor	—		
2	**Testing Manual Pull Station**			
	Simulate Manual Pull Trip of System,			
	Removeglass break Rod and Pull ring handle			
	on Pull Station			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,	—		
	(Snap-action)Fuse off,Fan On			
3	**Testing Detector System**			
	Simulate Automatic Trip of System,			
	Remove Fusible link and install atest link			
	and cut for simulate			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,			
	(Snap-action)Fuse off,Fan On			
	C.Alarm Warning,(Strobe light"Flash")			

Remark : System All Normal

Inspected By [redacted]
Date :

Customer By : Sofitel Bangkok Hotels
Date :

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels

Inspection and Testing

Photo	Description
	Photo: Check the System and Equipment Wet Chemical Location: Kitchen Floor.4 - Check the overall condition of the tank system and equipment. Wet Chemical System
	Photo: Check Fuse Detector Location: Kitchen Floor.4 - Check Fuse Detector
	Photo: Cleaning Location: Kitchen Floor.4 - Cleaning Nozzle
	Photo: Test wet chemical System Location: Kitchen Floor.4 - Test Wet Chemical System by removing the Fuse and cutting the Fuse System Normal
	Photo: Check the tank wet chemical Location: Kitchen Floor.4 - Check the Wet Chemical tank to be in ready condition.

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels

Inspection and Testing

Photo	Description
	Photo: Cleaning Location: Kitchen Floor.4 - Cleaning Fuse Detector
	Photo: Test Manual Location: Kitchen Floor.4 - Test run of Manual.
	Photo: Check the mechanism of the tank Wet chemical Location: Kitchen Floor.4 - Check the mechanism of the tank Wet Chemical
	Photo: Reset Wet chemical System Location: Kitchen Floor.4 - Reset Wet Chemical System

FIRE WORK SYSTEM & SERVICE CO., LTD.
38/873 THAIRAMAN ROAD ,SAMWATAWANTOK,
KHLONGSAMWA BANGKOK 10510 TEL 02-5486074 FAX 02-509-0049

Project : Sofitel Bangkok Hotels
Location : Kitchen Floor.2-1
Building : Sofitel Bangkok Hotels
Brand : ANSUL
Date : 25/3/2026

Test Report For Wet Chemical

Checklist of Equipment

Item	Description	Pass	Fail	Remark
1	**Detector**			
	Fusible Link,Type	√		
2	**Basic System(Not Include Cartridge)**			
	Mechanical "Ansul Automan"			
	3.0 Gallon In Stainless Steel For Mechanical	—		
	1.5 Gallon In Stainless Steel For Mechanical	√		
	3.0 Gallon Reaulated Actuator Assembly	√		
	3.0 Gallon Stainless Tank in Stainless Enclosure	√		
3	**Remote Pull Station**			
	Remote Pull Station	√		
	Break Rod	√		
	Break Away Rod	—		
	Wire Rope	√		
4	**Gas Shut Off Equipment**			
	Gas Valve,Mechanical Size:……	—		
	Solenoild Valve Size:…….	—		
	Relay-Manual Reset	—		
5	**Nozzles(All Nozzles Inclue Blow-off Caps)**			
	Nozzle For Appliance	√		
	Nozzle For Plenum	√		
	Nozzle For Duct	—		
6	**Agent**			
	1.5 Gallon (5.7 lt) ANSULEX	√		
	3.0 Gallon (11.4 lt) ANSULEX	—		
7	**Cartridges**			
	Cartridges, Nitrogen,LT-20-R	√		
	Cartridges, Nitrogen,LT-30-R	—		
	Cartridges, Nitrogen,R-102-R	—		
	Cartridges, Nitrogen,LT-101-30	—		

Testing System

Item	Description	Pass	Fail	Remark
1	**Testing Mechanical Gas Valve**			
	Remove Gas Cartidge and Simulate			
	Automatic Trip of System Below			
	A.Gas Valve Closs(if Applicable) and So Indicates	—		
	B.Check burner for Gaseous Odor	—		
2	**Testing Manual Pull Station**			
	Simulate Manual Pull Trip of System,			
	Removeglass break Rod and Pull ring handle			
	on Pull Station			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,	—		
	(Snap-action)Fuse off,Fan On			
3	**Testing Detector System**			
	Simulate Automatic Trip of System,			
	Remove Fusible link and install atest link			
	and cut for simulate			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,			
	(Snap-action)Fuse off,Fan On			
	C.Alarm Warning,(Strobe light"Flash")			

Remark : System All Normal


Inspected By : [redacted]
Date :

Customer By : Sofitel Bangkok Hotels
Date :

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels



Inspection and Testing

Photo	Description
	Photo: Check the System and Equipment Wet Chemical Location: Kitchen Floor.2-1 - Check the overall condition of the tank system and equipment. Wet Chemical System
	Photo: Check Fuse Detector Location: Kitchen Floor.2-1 - Check Fuse Detector
	Photo: Cleaning Location: Kitchen Floor.2-1 - Cleaning Nozzle
	Photo: Test wet chemical System Location: Kitchen Floor.2-1 - Test Wet Chemical System by removing the Fuse and cutting the Fuse System Normal
	Photo: Check the tank wet chemical Location: Kitchen Floor.2-1 - Check the Wet Chemical tank to be in ready condition.

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels

Inspection and Testing

Photo	Description
	Photo: Cleaning Location: Kitchen Floor.2-1 - Cleaning Fuse Detector
	Photo: Test Manual Location: Kitchen Floor.2-1 - Test run of Manual.
	Photo: Check the mechanism of the tank Wet chemical Location: Kitchen Floor.2-1 - Check the mechanism of the tank Wet Chemical
	Photo: Reset Wet chemical System Location: Kitchen Floor.2-1 - Reset Wet Chemical System

FIRE WORK SYSTEM & SERVICE CO., LTD.
38/873 THAIRAMAN ROAD ,SAMWATAWANTOK,
KHLONGSAMWA BANGKOK 10510 TEL 02-5486074 FAX 02-509-0049

Project : Sofitel Bangkok Hotels
Location : Kitchen Floor.2-2
Building : Sofitel Bangkok Hotels
Brand : Ansul
Date : 25/3/2026

Test Report For Wet Chemical

Checklist of Equipment

Item	Description	Pass	Fail	Remark
1	**Detector**			
	Fusible Link,Type	√		
2	**Basic System(Not Include Cartridge)**			
	Mechanical "Ansul Automan"			
	3.0 Gallon In Stainless Steel For Mechanical	—		
	1.5 Gallon In Stainless Steel For Mechanical	√		
	3.0 Gallon Reaulated Actuator Assembly	√		
	3.0 Gallon Stainless Tank in Stainless Enclosure	√		
3	**Remote Pull Station**			
	Remote Pull Station	√		
	Break Rod	√		
	Break Away Rod	—		
	Wire Rope	√		
4	**Gas Shut Off Equipment**			
	Gas Valve,Mechanical Size:.....	—		
	Solenoild Valve Size:.....	—		
	Relay-Manual Reset	—		
5	**Nozzles(All Nozzles Inclue Blow-off Caps)**			
	Nozzle For Appliance	—		
	Nozzle For Plenum	—		
	Nozzle For Duct	√		
6	**Agent**			
	1.5 Gallon (5.7 lt) ANSULEX	√		
	3.0 Gallon (11.4 lt) ANSULEX	—		
7	**Cartridges**			
	Cartridges, Nitrogen,LT-20-R	√		
	Cartridges, Nitrogen,LT-30-R	—		
	Cartridges, Nitrogen,R-102-R	—		
	Cartridges, Nitrogen,LT-101-30	—		

Testing System

Item	Description	Pass	Fail	Remark
1	**Testing Mechanical Gas Valve**			
	Remove Gas Cartidge and Simulate			
	Automatic Trip of System Below			
	A.Gas Valve Closs(if Applicable) and So Indicates	—		
	B.Check burner for Gaseous Odor	—		
2	**Testing Manual Pull Station**			
	Simulate Manual Pull Trip of System,			
	Removeglass break Rod and Pull ring handle			
	on Pull Station			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,	—		
	(Snap-action)Fuse off,Fan On			
3	**Testing Detector System**			
	Simulate Automatic Trip of System,			
	Remove Fusible link and install atest link			
	and cut for simulate			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,			
	(Snap-action)Fuse off,Fan On			
	C.Alarm Warning,(Strobe light"Flash")			

Remark : System All Normal




Inspected By [redacted]
Date :

Customer By : Sofitel Bangkok Hotels
Date :

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels

Inspection and Testing


Photo	Description
	Photo: Check the System and Equipment Wet Chemical Location: Kitchen Floor.2-2 - Check the overall condition of the tank system and equipment. Wet Chemical System
	Photo: Check Fuse Detector Location: Kitchen Floor.2-2 - Can not be verified because Fuse and Nozzle are inside of Duct
	Photo: Cleaning Location: Kitchen Floor.2-2 - Can not be verified because Fuse and Nozzle are inside of Duct
	Photo: Test wet chemical System Location: Kitchen Floor.2-2 - Can not be verified because Fuse and Nozzle are inside of Duct
	Photo: Check the tank wet chemical Location: Kitchen Floor.2-2 - Check the Wet Chemical tank to be in ready condition.

น.3/69

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049

Date : 25 March 2026
Project : Sofitel Bangkok Hotels

Inspection and Testing

Photo	Description
	Photo: Cleaning Location: Kitchen Floor.2-2 - Can not be verified because Fuse and Nozzle are inside of Duct
	Photo: Test Manual Location: Kitchen Floor.2-2 - Test run of Manual.
	Photo: Check the mechanism of the tank Wet chemical Location: Kitchen Floor.2-2 - Check the mechanism of the tank Wet Chemical
	Photo: Reset Wet chemical System Location: Kitchen Floor.2-2 - Reset Wet Chemical System

FIRE WORK SYSTEM & SERVICE CO., LTD.
38/873 THAIRAMAN ROAD ,SAMWATAWANTOK,
KHLONGSAMWA BANGKOK 10510 TEL 02-5486074 FAX 02-509-0049

Project : Sofitel Bangkok Hotels
Location : Kitchen Floor.2-3
Building : Sofitel Bangkok Hotels
Brand : Ansul
Date : 25/3/2026

Test Report For Wet Chemical

Checklist of Equipment

Item	Description	Pass	Fail	Remark
1	**Detector**			
	Fusible Link,Type	√		
2	**Basic System(Not Include Cartridge)**			
	Mechanical "Ansul Automan"			
	3.0 Gallon In Stainless Steel For Mechanical	√		
	1.5 Gallon In Stainless Steel For Mechanical	—		
	3.0 Gallon Reaulated Actuator Assembly	√		
	3.0 Gallon Stainless Tank in Stainless Enclosure	√		
3	**Remote Pull Station**			
	Remote Pull Station	√		
	Break Rod	√		
	Break Away Rod	—		
4	**Gas Shut Off Equipment**			
	Gas Valve,Mechanical Size:…3/4……	√		
	Solenoild Valve Size:……	—		
	Relay-Manual Reset	—		
5	**Nozzles(All Nozzles Inclue Blow-off Caps)**			
	Nozzle For Appliance	√		
	Nozzle For Plenum	√		
	Nozzle For Duct	—		
6	**Agent**			
	1.5 Gallon (5.7 lt) ANSULEX	—		
	3.0 Gallon (11.4 lt) ANSULEX	√		
7	**Cartridges**			
	Cartridges, Nitrogen,LT-20-R	√		
	Cartridges, Nitrogen,LT-30-R	√		
	Cartridges, Nitrogen,R-102-R	—		
	Cartridges, Nitrogen,LT-101-30	—		

Testing System

Item	Description	Pass	Fail	Remark
1	**Testing Mechanical Gas Valve**			
	Remove Gas Cartidge and Simulate			
	Automatic Trip of System Below			
	A.Gas Valve Closs(if Applicable) and So Indicates	√		
	B.Check burner for Gaseous Odor	√		
2	**Testing Manual Pull Station**			
	Simulate Manual Pull Trip of System,			
	Removeglass break Rod and Pull ring handle			
	on Pull Station			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,	—		
	(Snap-action)Fuse off,Fan On			
3	**Testing Detector System**			
	Simulate Automatic Trip of System,			
	Remove Fusible link and install atest link			
	and cut for simulate			
	A.Release Mechanism Trip,Pin Extends,	√		
	Flag Shows"Firde"			
	B.Micro Switch/Pressure Switch Trip,			
	(Snap-action)Fuse off,Fan On			
	C.Alarm Warning,(Strobe light"Flash")			

Remark : System All Normal

While testing the system by pulling down MANUAL STATION but there is no Alarm occurred. After checking issue, found the MANUAL STAION cable is broken (connected in the pipe). Then FWSS team performed connected cable for temporarly used and inform Sofitel's technician team for basic operation already.

ในคราชั้น 7 (2) สถิงสั่งทำให้ Function ไม่เป็นไปตามการทำงานจริง คือ เมื่อมีการตัด Fuse Test ตัวใหนตัวหนึ่งใน 3 จุด แล้ว กลไกหัวถังไม่สั่งเปิด R102 ต่อเมื่อตัด Fuse Test อีก 1 จุดถึงจะสั่งยิงได้ ดังนั้นจึงไม่เป็นไปตาม Function

Inspected By : [redacted]
Date :

Customer By : Sofitel Bangkok Hotels
Date :

FIRE WORK SYSTEM & SERVICE CO., LTD.
Tel. 02-548-6074 Fax. 02-509-0049


Date : 25 March 2026
Project : Sofitel Bangkok Hotels

Inspection and Testing

Photo	Description
	Photo: Check the System and Equipment Wet Chemical Location: Kitchen Floor.2-3 - Check the overall condition of the tank system and equipment. Wet Chemical System
	Photo: Check Fuse Detector Location: Kitchen Floor.2-3 - Check Fuse Detector
	Photo: Cleaning Location: Kitchen Floor.2-3 - Cleaning Nozzle
	Photo: Test wet chemical System Location: Kitchen Floor.2-3 - Test Wet Chemical System by removing the Fuse and cutting the Fuse System Normal
	Photo: Check the tank wet chemical Location: Kitchen Floor.2-3 - Check the Wet Chemical tank to be in ready condition.

FIRE WORK SYSTEM & SERVICE CO., LTD. Tel. 02-548-6074 Fax. 02-509-0049	Date : 25 March 2026 Project : Sofitel Bangkok Hotels

Inspection and Testing


Photo	Description
	Photo: Cleaning Location: Kitchen Floor.2-3 - Cleaning Fuse Detector
	Photo: Test Manual Location: Kitchen Floor.2-3 Test run of Manual.
	Photo: Check the mechanism of the tank Wet chemical Location: Kitchen Floor.2-3 - Check the mechanism of the tank Wet Chemical
	Photo: Reset Wet chemical System Location: Kitchen Floor.2-3 - Reset Wet Chemical System

Preventive Maintenance Program Schedule



วันที่	ค่าคลอรีนCLเช้า	ค่าPHเช้า	ค่าคลอรีนCLบ่าย	ค่าPHบ่าย
1/6/2026	0.6	8.5	0.7	8.4
2/6/2026	1	8.4	0.6	8.5
3/6/2026	0.7	8.4	0.7	8.27
4/6/2026	0.7	8.5	0.7	8.44
5/6/2026	0.9	8.4	0.8	8.26
6/6/2026	0.7	8.1	0.6	8.47
7/6/2026	0.7	8.2	0.7	8.46
8/6/2026	0.9	8.5	0.77	8.37
9/6/2026	0.83	8.5	1	8.22
10/6/2026	0.85	8.2	0.9	8.38
11/6/2026	0.82	8.5	0.8	8.49
12/6/2026	0.85	8.5	0.81	8.42
13/6/2026	0.84	8.5	0.64	8.52
14/6/2026	1	8.5	0.88	8.66
15/6/2026	0.9	8.5	0.94	8.41
16/6/2026	0.9	8.5	0.78	8.45
17/6/2026	0.8	8.1	2	8.54
18/6/2026	0.78	8.3	0.89	8.75
19/6/2026	0.82	8.3	0.69	8.46
20/6/2026	0.84	8.3	0.78	8.39
21/6/2026	0.94	8.3	0.96	8.41
22/6/2026	1	8.5	0.98	8.44
23/6/2026	0.6	8.5	0.9	8.57
24/6/2026	0.6	8.5	0.78	8.51
25/6/2026	0.7	8.5	0.98	8.52
26/6/2026	0.7	8.5	0.89	8.52
27/6/2026	0.9	8.6	0.78	8.49
28/6/2026	0.8	8.5	0.76	8.46
29/6/2026	1	8.3	1	8.45
30/6/2026	0.6	8.34	0.98	8.44

14. การทำความสะอาดพื้นที่ส่วนกลาง




15. การสูบตะกอนจากระบบบำบัดน้ำเสีย



16. การตักไขมันออกจากบ่อดักไขมัน



17. การตรวจสอบเส้นท่อประปา



18. การขนย้ายมูลฝอยในโครงการ





18. การขนย้ายมูลฝอยในโครงการ





19. การขนย้ายมูลฝอยจากสำนักงานเขต






20. การล้างทำความสะอาดห้องพักมูลฝอย







ล้างห้องขยะแห้ง



ล้างห้องขยะเปียก

21. การขุด/ลอกบ่อหน่วงน้ำและการระบายน้ำ



24. การซ้อมดับเพลิง




23. การล้างทำความสะอาดเครื่องปรับอากาศ




24. ล้างถังเก็บน้ำในโครงการ



26. การตรวจสอบระบบป้องกันและเตือนอัคคีภัยในโครงการ



27. การทำความสะอาดสระว่ายน้ำ



28. การซ่อมแซมส่วนงานต่างๆ ภายในโครงการ



29. การตักใบไม้ / เศษขยะออกจากระบบระบายน้ำ



30. การกำจัดสัตว์พาหะนำโรค

