

ภาคผนวกที่ 2-2
เอกสารซ่อมบำรุงระบบบำบัดมลพิษทางอากาศ



On Site Work Report

Record	Engineer	Manager
Taivivat 24/01/19	Taivivat 24/01/19	<i>[Signature]</i> 24/01/19

Date work: 12.1.19~12.1.19
 Time: 08:00 ~ 18:30
 Report by: MR.TAIVIVAT
 Customer Name: RYOBI DIE CASTING (THAILAND) CO., LTD.
 M/C name: UDC-824PS-371
 M/C No.:
 Project Code: MC180230
 Location: Rayong
 Working Period: Addition exhaust duct of ductcollector
 change filter bag addtion and addtion auto drain

T.Sinto Staff

1	MR.TAIVIVAT	2	MR.Damrong	3	
4		5		6	

Sub-contractor Name: CNS
 Foreman: 1
 Worker: 8

Used Part

ITEM	DRAWING NO.	Name	Q'ty	Remark

Picture

Detail


Before

After




Change of Position
Higher

Old hole



Close the old hole Outside the building

Outside the building



Addition exhaust duct of ductcollector
completed

Picture

Detail



Before


After



Change Z sping

Before

After



Chang Filter bag
take-out old filter and cleaning room
change new filter bag

Change Z sping
take-out old Z sping
change new Z sping

Picture

Detail



Addition auto drain

Addition Auto Drain **No.2**
 In system air supply
 For Dust collector UDC-824PS-371

No.1

N0.2



Before

After