

ภาคผนวกที่ 3-8
คู่มือการดูแลถึงเก็บน้ำสำเร็จรูป

คู่มือการใช้งานผลิตภัณฑ์
ถังเก็บน้ำสำเร็จรูป



ถังเก็บน้ำ
รุ่น

“FX-series”



FIBERTECH CO., LTD.

36 MOO 15 SOI RAMANIVEJ, KING-KAEW RD., BANGPEE, SAMUTPRAKARN 10540

Tel. (66)2-721-0730-5 Fax (66)2-321-4854

www.biotech.co.th Email : contact@biotech.co.th



ถังเก็บน้ำสำเร็จรูปไบโอเทค รุ่น FX-series

ถังเก็บน้ำผลิตจากไฟเบอร์กลาส Food grade เป็นอุปกรณ์ในการกักเก็บน้ำ เพื่อการใช้น้ำตามปกติหรือสำรองน้ำ ใช้ตามความต้องการ

การใช้งานและดูแลรักษาถังเก็บน้ำสำเร็จรูปไบโอเทค รุ่น FX-series

1. กรณีพ่นน้ำ / สำรองน้ำเป็นเวลานานให้ตรวจสอบปริมาณน้ำในถังเก็บน้ำ หากไม่มีการรั่วซึมของถังระดับน้ำในถังควรคงที่
2. ตรวจสอบลูกกลอยภายในถังเก็บน้ำ ทำงานเป็นปกติหรือไม่
3. ควรล้างทำความสะอาดทุก 6 เดือน วิธีทำความสะอาดถังเก็บน้ำสามารถทำได้โดยใส่น้ำให้เต็มถังเก็บน้ำแล้วใส่คลอรีนน้ำหรือคลอรีนผง เลือกใช้ปริมาณคลอรีน / ปริมาณน้ำ ตามสัดส่วนด้านล่าง
 - 3.1 คลอรีนชนิดน้ำ 5% ควรใช้น้ำยาคลอรีน 100 ลบ.ซม. ต่อปริมาณน้ำ 1 ลบ.ม.
 - 3.2 คลอรีนชนิดน้ำ 10% ควรใช้น้ำยาคลอรีน 50 ลบ.ซม. ต่อปริมาณน้ำ 1 ลบ.ม.
 - 3.3 คลอรีนชนิดผง ควรใช้ประมาณ 8 กรัม ต่อปริมาณน้ำ 1 ลบ.ม.

จากนั้นกวนน้ำและคลอรีนให้เข้ากันเพื่อให้คลอรีนทำปฏิกิริยากับน้ำอย่างทั่วถึง และพักไว้ประมาณ 3 ชั่วโมง แล้วจึงปล่อยน้ำคลอรีนออกจากถังเก็บน้ำให้หมด คลอรีนจะฆ่าเชื้อโรคภายในถัง จากนั้นจึงใส่น้ำประปาลงไป จะทำให้น้ำประปาที่สำรองไว้ใช้เป็นน้ำที่มีคุณภาพดี สะอาดและปราศจากเชื้อโรค
4. ตรวจสอบการปิดสนิทของฝาแมนโฮลด์ เพื่อป้องกันสิ่งสกปรกปนเปื้อนน้ำใช้ในถังเก็บน้ำ
5. ห้ามวางสิ่งของต่างๆ บนฝาปิดแมนโฮลด์ เพื่อให้สามารถปฏิบัติงานและดูแลรักษาได้ตลอดเวลา

ฝ่ายเทคนิคและวิศวกรรม

โทร. 02-721-0730-5



ภาคผนวกที่ 3-9
เอกสารการตรวจสอบระบบไฟฟ้าประจำปี 2565



PREVENTIVE MAINTENANCE ELECTRICAL SYSTEM 2022

ERECTION SITE:

THE PARK NINE SUVARNABHUMI

CUSTOMER:

RAA HOLDER CO., LTD.

Preventive Maintenance Report 22 February 2022

ESSI ENERGY GROUP CO., LTD.

1 Soi Ramkhamhaeng 164 Sub 16,
Minburi Sub-District
Minburi District
Bangkok 10510
Hotline 0881696156

Report prepared by: Apichat M.

Date: **22 February 2022**

Introduction

This test and inspection is preventive maintenance at **The Park Nine Suvarnabhumi.**

The objective of this preventive maintenance is to ensure that all tested electrical equipment still are in good condition and to find out any damaged and / or unsafe condition.

This test and inspection were performed during **February 22, 2022** all test & inspection result and any comment have been recorded in this test report.

Table of content

Introduction	2
Table of content.....	3
Scope of Work	4
Content	6
Conclusion	7
Suggestion / Recommendations	8
Photograph	9
Test Sheet	22

Scope of Work

1. Load Break Switch

1. Inspection and cleaning the cubicle.
2. Retightening power cable termination / ground cable.
3. Operation the switch-disconnector several times (3-5 times) to make mechanism movement.
4. Inspection / cleaning lower and upper fuse connection.
5. Test interlocking mechanism used to open switch-disconnector when fuse blows.
6. Insulation check.

2. Transformer (Oil type)

1. General inspection and cleaning.
2. Dielectric test of oil.
3. Bushing condition check.
4. Grounding connection check.
5. Retighten with torque wrench (busing connection).
6. Insulation resistance.

3. Air Circuit Breaker

1. Cleaning the air circuit breaker and relubricating the operating mechanism.
2. Cleaning and check Arc-chuter.
3. Insulation check.
4. Rack-in / rack-out circuit breaker.
5. Trip unit function test. (Protection unit).
6. Parameter checking and recording of protective relay
7. Contact resistance test.
8. Operate spring test.

4. LV Switchboard

1. Cleaning all panel.
2. Retorque the busbar at Main incoming and between panel.
3. Insulation test.
4. Metering check.
5. General condition check.
6. Grounding connection check.
7. Busbar check.
8. Magnetic contactors condition check.
9. Fuse and fuse bases check.

5. Capacitor Bank

1. Inspect for physical damage, broken insulation.
2. Tightness of connection wiring.
3. General cleaning and cleaning at connection of fuse .
4. Operating function.
5. Insulation resistance.
6. Current operated check.
7. Capacitive measurement.
8. Wiring check.

6. DB Panel

1. Cleaning all panel.
2. Retorque busbar and cable connection at main incoming and between panel.
3. Retorque at connection of MCCB and busbar or cable.
4. Metering check.
5. General condition check.
6. Grounding connection check.
7. Busbar check and retorque.
8. Fuse and fuse bases check.

7. Busduct, Busway System
























1. General inspection and cleaning.
2. Inspection of all electrical joints and terminals for tightness
3. Check alignment of installation.
4. Support check and tightness.

8. Plug-In Unit

1. Inspect for physical damage, broken insulation.
2. Tightness of connection beaker and busbar.
3. Check ground connection.
4. Cleaning.
5. Operating function test.

Content

The Park Nine Suvarnabhumi

-  MV
-  LBS
-  Transformer
-  Electrical Room
-  LV Switchboard
 -  ACB MAIN
 -  MCCB BUSDUCT 1250A
 -  MCCB DB-VRV
 -  MCCB MAIN CAP.
 -  MCCB LP5
 -  MCCB LP2
 -  MCCB LP12
 -  MCCB LP11
 -  MCCB DBB
 -  MCCB ATS&EMDB
 -  MCCB MCC-POOL
 -  MCCB MCC-HWP
 -  MCCB MCC-LIFT3
 -  MCCB DBA
 -  MCCB KITCHEN
 -  MCCB AC PANEL
 -  CAP. BANK
 -  GROUND

Conclusion

From results of test & inspection, all of defected equipments are shown in table below.

Item	Equipments	Status	Faulty list	Corrective Action	Remark

Suggestion / Recommendations

From results of test & inspection, all of suggestion/recommandations are shown in table below.

Item	Description	Suggestion/Recommendation
1	All electrical equipment.	Should be preventive maintenance once a year.

Photograph



Photo 1-2-3-4-5-6: ภาพของการทำความสะอาดและทดสอบ
Load Break Switch









Photo 7-8-9-10-11-12: ภาพแสดงการตรวจสอบและทำความสะอาดของหม้อแปลง, การทดสอบ Insulation Resistance ของหม้อแปลงขณะทำ Preventive Maintenance









Photo 13-14-15-16: ภาพแสดงการทำความสะอาดและทำการทดสอบ Trip unit, Contact Resistance ของ Air Circuit Breaker








Photo 17-18-19-20-21-22-23-24-25-26: ภาพแสดงการทำ Preventive Maintenance ตู้ LV MDB, Cap. Bank, Plug-in unit, DB Panel โดยการ Inspection, Cleaning, Tightening torque











Test Sheet

Here below are the reports of maintenance jobs which have been performed.



ESSI ENERGY GROUP CO., LTD.

1. LOAD BREAK SWITCH

ESSI ENERGY GROUP CO., LTD.



FIELD INSPECTION AND TEST RECORD

LOAD BREAK SWITCH

PROJECT	: PREVENTIVE MAINTENANCE	LOCATION	: MV LBS.
ERECTION SITE	: THE PARK NINE SUVARNABHUMI	CUBICLE NAME	: LBS.
CUSTOMER	: RAA HOLDER CO., LTD.	FEEDER	: TO TR.

TECHNICAL DATA

Manufacture	Schneider	Serial no.	TL641125-2
Type	L-TRI 5/24/630/275-UH-KS-A	Rated normal current	630 A.
Year of manufacture	2015	Standard	IEC 60265-1/1998
Rated voltage	24 kV.	Rated duration of short-circuit	25 kA 1 sec
Impulse withstand voltage	125 kV.	Rated frequency	50/60 Hz.
Power freq. withstand voltage	- kV.	Rate power fuse	80 A.

VISUAL AND MECHANICAL INSPECTION

Checked

1. Busbar installed according to design and manufacturer's instructions	<input checked="" type="checkbox"/>
2. Check of busbar undamaged and cleaned	<input checked="" type="checkbox"/>
3. Clean cable compartment	<input checked="" type="checkbox"/>
4. Check tightening torque	<input checked="" type="checkbox"/>

INSULATION RESISTANCE MEASUREMENT (Close Disconnect switch)

Instrument : Megger model MIT515

Test connection	Test voltage (Vdc)	Insulation resistance (MΩ)	Recommended Minimum Insulation Resistance
A to B	5,000	8,660	≥ 5,000 MΩ
B to C		7,940	
C to A		6,610	
A to Gnd.		8,350	
B to Gnd.		6,870	
C to Gnd.		7,740	

Refer.: ANSI/NETA MTS-2011

Humidity : 51 % Amb. Temp. : 31 °C

Remark : _____

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	



ESSI ENERGY GROUP CO., LTD.

2. TRANSFORMER

ESSI ENERGY GROUP CO., LTD.



FIELD INSPECTION AND TEST RECORD

TRANSFORMER

PROJECT	: PREVENTIVE MAINTENANCE	LOCATION	: TRANSFORMER YARD
ERECTION SITE	: THE PARK NINE SUVARNABHUMI	TR. NAME	: TR.1
CUSTOMER	: RAA HOLDER CO., LTD.		

TECHNICAL DATA

Manufacture	CHAROENCHAI	Serial No.	FI234592
Type	OIL TYPE	Type of cooling	ONAN
Year of manufacture	2016	Weight	4135 kg.
Rate Frequency	50 Hz	Oil volume	865 L
Rate Power	1600 kVA	Impedance @75 °C	5.96 %
Rate Voltage HV	24000 V	Tap position	1
Rate Voltage LV	416/240 V	Insulation class	A
Rated current HV	38.49 A	Oil temperature	60 °C
Rated current LV	2220.58 A	Winding temperature	65 °C
Vector-group symbol	Dyn11	Amb. temperature	40 °C
Standard	IEC 60076	Insulation oil	MINERAL
Phase	3	Winding HV/LV	CU/CU

VISUAL INSPECTION AND FUNCTION TEST

- Transformer undamaged and clean .
- The oil level ☐ Min. ☐ Med. ☒ Max.
- Check that all valves are set at right position
- Check possible oil leakage .
- Bushing undamaged and clean.
- Grounding resistance measurement 1.08 Ω

Pass	Not pass	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/>	<input type="checkbox"/>	N/A
<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	

INSULATION RESISTANCE MEASUREMENT

Instrument : Megger Model MIT515 Serial no. : 13117

Test connection	Test voltage (Vdc)	Insulation resistance (MΩ)	Recommended Minimum Insulation Resistance
HV to GND	2500	3,120	500 MΩ
HV to LV	2500	3,260	500 MΩ

Refer.: CHAROENCHAI TRANSFORMER CO., LTD.

Humidity : 51 % Amb. Temp. : 31 °C

Remark : _____

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	



FIELD INSPECTION AND TEST RECORD

TRANSFORMER

PROJECT	: PREVENTIVE MAINTENANCE	LOCATION	: TRANSFORMER YARD
ERECTION SITE	: THE PARK NINE SUVARNABHUMI	TR. NAME	: TR.1
CUSTOMER	: RAA HOLDER CO., LTD.		

รายงานผลการทดสอบ Breakdown Voltage ของน้ำมันหม้อแปลง

- | | |
|---|--|
| <input checked="" type="checkbox"/> ทดสอบน้ำมันจากหม้อแปลงที่กำลังใช้งาน | <input type="checkbox"/> ทดสอบน้ำมันจากหม้อแปลงใหม่ที่ยังไม่ได้ใช้งาน |
| <input type="checkbox"/> ทดสอบน้ำมันจากหม้อแปลงเก่าจัดเก็บที่ไม่ได้ใช้งาน | <input type="checkbox"/> ทดสอบน้ำมันใหม่จากถัง 200 ลิตร / Bulk เบอร์ถัง..... |
| <input type="checkbox"/> ทดสอบหลังกรองน้ำมัน หน่วยงาน | |

ลักษณะของตัวอย่างน้ำมัน

- | | |
|--|--|
| <input checked="" type="checkbox"/> สีอ่อนใส | <input type="checkbox"/> มีเศษผง/ตะกอนเล็กน้อย |
| <input type="checkbox"/> สีเข้มเล็กน้อย | <input type="checkbox"/> มีเศษผง/ตะกอนมาก |
| <input type="checkbox"/> สีเข้มมาก | <input type="checkbox"/> มีกลิ่นไหม้ |
| <input type="checkbox"/> ขุ่นข้น | <input type="checkbox"/> อื่น ๆ..... |

ข้อมูลการทดสอบ Breakdown Voltage ของน้ำมันหม้อแปลง

ผลการทดสอบหม้อแปลง							ค่าเฉลี่ยที่ได้
หม้อแปลง (kVA)	ครั้งที่1	ครั้งที่2	ครั้งที่3	ครั้งที่4	ครั้งที่5	ครั้งที่6	
1600	59.6	54.6	62.9	56.4	62.0	58.4	59.0

Note : ค่าเฉลี่ยที่ได้ **59.0** เกณฑ์มาตรฐานไม่ต่ำกว่า **36 kV**

มาตรฐานการทดสอบ

- | | |
|---|-------------------------------------|
| <input checked="" type="checkbox"/> IEC 156 | <input type="checkbox"/> ASTM D 877 |
| <input type="checkbox"/> อื่น ๆ..... | <input type="checkbox"/> ASTM D1816 |

สรุปผลการทดสอบ

- | | |
|--|--|
| <input checked="" type="checkbox"/> ผ่าน สามารถใช้งานได้ | |
| <input type="checkbox"/> ควรทดสอบอย่างอื่นเพิ่มเติม เพื่อแก้ไขปัญหาได้ถูกต้องแม่นยำมากกว่านี้ ได้แก่ | |
| <input type="checkbox"/> Acid Number <input type="checkbox"/> Interfacial Tension <input type="checkbox"/> Power Factor <input type="checkbox"/> Water Content | |
| <input type="checkbox"/> อื่น ๆ..... | |
| <input type="checkbox"/> ไม่ผ่าน ควรแก้ไขโดย | |
| <input type="checkbox"/> กรองน้ำมันที่หน่วยงาน <input type="checkbox"/> เปลี่ยนน้ำมันใหม่ที่หน่วยงาน <input type="checkbox"/> ส่งเข้ารับการ Overhaul | |

Remark :

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	



ESSI ENERGY GROUP CO., LTD.

3. LV MDB.

ESSI ENERGY GROUP CO., LTD.



FIELD INSPECTION AND TEST RECORD

LV SWITCHBOARD

PROJECT : PREVENTIVE MAINTENANCE	LOCATION : ELECTRICAL ROOM
ERECTION SITE : THE PARK NINE SUVARNABHUMI	CUBICLE NAME : MDB.1
CUSTOMER : RAA HOLDER CO., LTD.	

VISUAL INSPECTION

	Normal	Abnormal	
1. Cleaning all panel	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2. Re-torque the busbar at main incoming and between panel	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3. Re-torque at connection of MCCB and busbar or cable	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
4. Insulation test	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5. Metering check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6. General condition check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7. Grounding condition check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
8. Busbar check and re-torque	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
9. Fuse and fuse bases check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

INSULATION RESISTANCE MEASUREMENT

Instrument : Megger Model MIT515 Serial no. : 13117

Test connection	Test voltage (Vdc)	Insulation resistance (MΩ)	Accept.
A-B	500	15,360	≥ 1.0 MΩ
B-C		14,260	
C-A		15,030	
A-Gnd.		5,530	
B-Gnd.		9,160	
C-Gnd.		9,770	

Note : LV circuit insulation value (U < 500 Volts): 1000 ohms/volt of nominal voltage (IEC 61439-6) allowed.

Humidity : 51 % Amb. Temp. : 31 °C

Remark : _____

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	



FIELD INSPECTION AND TEST RECORD

AIR CIRCUIT BREAKER (ABB)

PROJECT	: PREVENTIVE MAINTENANCE	LOCATION	: ELECTRICAL ROOM
ERECTION SITE	: THE PARK NINE SUVARNABHUMI	CUBICLE NAME	: MDB.1
CUSTOMER	: RAA HOLDER CO., LTD.	FEEDER	: MAIN ACB

VISUAL INSPECTION

- Cleaning the air circuit breaker and re-lubricating the operating mechanism.
- Cleaning and check Arc-chute.
- Insulation check.
- Rack-in / rack-out circuit breaker.
- Trip unit function test. (Protection unit).
- Parameter checking and recording of protective relay.
- Contact resistance test.

Normal Abnormal

<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	

TECHNICAL DATA

Manufacture	ABB
Type	E4.2N
Ampere Trip (In)	3200 A
Serial no.	BF93000058
Ue	690 V
Frequency	50/60 Hz
Standard	IEC 60947-2

Trip Device

Icu

Pole

Frame

<input checked="" type="checkbox"/>	Ekip Dip
<input type="checkbox"/>	Ekip Touch
<input checked="" type="checkbox"/>	66 kA
<input type="checkbox"/>	75 kA
<input type="checkbox"/>	85 kA
<input type="checkbox"/>	100 kA
<input checked="" type="checkbox"/>	3P
<input type="checkbox"/>	4P
<input checked="" type="checkbox"/>	Fixed
<input type="checkbox"/>	Draw-out

1. Accessories

1.1 Under voltage trip device (MN)	<input type="checkbox"/> 100/130 VAC/VDC	<input checked="" type="checkbox"/> 200-250 VAC/VDC	<input type="checkbox"/> Other
1.2 Shunt trip device (MX)	<input type="checkbox"/> 100/130 VAC/VDC	<input checked="" type="checkbox"/> 200-250 VAC/VDC	<input type="checkbox"/> Other
1.3 Closing coil (XF)	<input type="checkbox"/> 100/130 VAC/VDC	<input type="checkbox"/> 200-250 VAC/VDC	<input type="checkbox"/> Other
1.4 Motor charger device (MCH)	<input type="checkbox"/> 100/130 VAC/VDC	<input type="checkbox"/> 200-250 VAC/VDC	<input type="checkbox"/> Other

2. Electronic Trip Device Setting

Electronic trip device setting	Setting value
Long time (I1)	1
Long time delay (T1)	12
Short time (I2)	5
Short time delay (T2)	0.3
Instantaneous (I3)	8
Ground fault (I4)	0.3
Ground fault time delay (T4)	0.2

☒ $t=k/I^2$ ☐ $t=k$

☒ $t=k/I^2$ ☐ $t=k$

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	



FIELD INSPECTION AND TEST RECORD

AIR CIRCUIT BREAKER (ABB)

PROJECT	: PREVENTIVE MAINTENANCE	LOCATION	: ELECTRICAL ROOM
ERECTION SITE	: THE PARK NINE SUVARNABHUMI	CUBICLE NAME	: MDB.1
CUSTOMER	: RAA HOLDER CO., LTD.	FEEDER	: MAIN ACB

3. Operating and Inspect

Operating and Inspect	Result		
	Pass	Not pass	N/A
Manual charge spring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Manual closing operation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Manual opening operation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Check moving part	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Check LV auxiliaries plug	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cleaning arc chute chamber	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Characteristics of electronic trip device	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

4. Testing Result of Electronic Trip Device

Function	Inject Current	Should be Time (Sec)	Operating Time (Sec)	Trip Indicator	
				Passed	Failed
Long time	3xI _n	12.00	12.032	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Short time	6xI _n	0.833	0.836	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Instantaneous	10xI _n	<0.03	0.019	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ground fault	2xI _Δ	0.500	0.504	<input checked="" type="checkbox"/>	<input type="checkbox"/>

$$t = (9t_1) / (I_f/I_1)^2$$

$$t = (100t_2) / (I_f)^2$$

$$t < 30 \text{ ms}$$

$$t = 2 / (I_f/I_Δ)^2$$

5. Testing Result of Contact Resistance

Phase	Test current (Adc)	Contact resistance (μΩ)	Accept.
A	10	15	≤ 41.5 μΩ
B		17	
C		16	
N			

6. Testing Result of Insulation Resistance

or Testing Result of Insulation Resistance					
Test Voltage (Vdc)	Insulation Resistance (MΩ)			Accept.	
500	Interrupter A :	-	Interrupter B :	-	≥ 100 MΩ
	A to B+C+G :	-	B to A+C+G :	-	

OVERALL TEST RESULT ☒ **PASS** ☐ **NOT PASS**

Remark : _____

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	

ESSI ENERGY GROUP CO., LTD.



FIELD INSPECTION AND TEST RECORD

MOLD CASE CIRCUIT BREAKER

PROJECT : PREVENTIVE MAINTENANCE **LOCATION** : ELECTRICAL ROOM
ERECTION SITE : THE PARK NINE SUVARNABHUMI **CUBICLE NAME** : MDB.1
CUSTOMER : RAA HOLDER CO., LTD.

Name of MCCB : BUSDUCT 1250A **Rated In (A)** : 1250 **Model** : SACE T7S 1250
Manufacture : ABB **Protection Relay type** : SACE PR231/P
Protection Setting I1 = 1 t1 = 12 I2 = 4.5 t2 = 0.1

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Name of MCCB : DB-VRV **Rated In (A)** : 1000 **Model** : SACE T7S 1000
Manufacture : ABB **Protection Relay type** : SACE PR231/P
Protection Setting I1 = 1 t1 = 12 I2 = 4.5 t2 = 0.1

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Name of MCCB : MAIN CAP. **Rated In (A)** : 1000 **Model** : SACE T7S 1000
Manufacture : ABB **Protection Relay type** : SACE PR231/P
Protection Setting I1 = 1 t1 = 12 I2 = 4.5 t2 = 0.1

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	

ESSI ENERGY GROUP CO., LTD.



FIELD INSPECTION AND TEST RECORD

MOLD CASE CIRCUIT BREAKER

PROJECT : PREVENTIVE MAINTENANCE **LOCATION** : ELECTRICAL ROOM
ERECTION SITE : THE PARK NINE SUVARNABHUMI **CUBICLE NAME** : MDB.1
CUSTOMER : RAA HOLDER CO., LTD.

Name of MCCB : LP5 **Rated In (A)** : 63 **Model** : XT1S 160
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Name of MCCB : LP2 **Rated In (A)** : 80 **Model** : XT1S 160
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Name of MCCB : LP12 **Rated In (A)** : 63 **Model** : XT1S 160
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	

ESSI ENERGY GROUP CO., LTD.



FIELD INSPECTION AND TEST RECORD

MOLD CASE CIRCUIT BREAKER

PROJECT : PREVENTIVE MAINTENANCE **LOCATION** : ELECTRICAL ROOM
ERECTION SITE : THE PARK NINE SUVARNABHUMI **CUBICLE NAME** : MDB.1
CUSTOMER : RAA HOLDER CO., LTD.

Name of MCCB : LP11 **Rated In (A)** : 63 **Model** : XT1S 160
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Name of MCCB : DBB **Rated In (A)** : 125 **Model** : XT1S 160
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Name of MCCB : ATS&EMDB **Rated In (A)** : 400 **Model** : T5H400
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	

ESSI ENERGY GROUP CO., LTD.



FIELD INSPECTION AND TEST RECORD

MOLD CASE CIRCUIT BREAKER

PROJECT : PREVENTIVE MAINTENANCE **LOCATION** : ELECTRICAL ROOM
ERECTION SITE : THE PARK NINE SUVARNABHUMI **CUBICLE NAME** : MDB.1
CUSTOMER : RAA HOLDER CO., LTD.

Name of MCCB : MCC-POOL **Rated In (A)** : 50 **Model** : XT1S 160
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Name of MCCB : MCC-HWP **Rated In (A)** : 80 **Model** : XT1S 160
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Name of MCCB : MCC-LIFT3 **Rated In (A)** : 80 **Model** : XT1S 160
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	

ESSI ENERGY GROUP CO., LTD.



FIELD INSPECTION AND TEST RECORD

MOLD CASE CIRCUIT BREAKER

PROJECT : PREVENTIVE MAINTENANCE **LOCATION** : ELECTRICAL ROOM
ERECTION SITE : THE PARK NINE SUVARNABHUMI **CUBICLE NAME** : MDB.1
CUSTOMER : RAA HOLDER CO., LTD.

Name of MCCB : DBA **Rated In (A)** : 630 **Model** : T5H 630
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Name of MCCB : KITCHEN **Rated In (A)** : 160 **Model** : XT1H 160
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Name of MCCB : AC PANEL **Rated In (A)** : 400 **Model** : T5H 400
Manufacture : ABB **Protection Relay type** : TM
Protection Setting I1 = - t1 = - I2 = - t2 = -

Checking				Yes	No
1. ON-OFF Operation				<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Trip push button				<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Input / Output Connection				<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Test Protection relay				<input type="checkbox"/>	<input checked="" type="checkbox"/>
Function	Inject Current (A)	Operating Time (sec)		Result	
		Should be	As found	Pass	Not Pass
Long time				<input type="checkbox"/>	<input type="checkbox"/>
Short time				<input type="checkbox"/>	<input type="checkbox"/>

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	

ESSI ENERGY GROUP CO., LTD.



FIELD INSPECTION AND TEST RECORD

CAPACITOR BANK

PROJECT	: PREVENTIVE MAINTENANCE	LOCATION	: ELECTRICAL ROOM
ERECTION SITE	: THE PARK NINE SUVARNABHUMI	CUBICLE NAME	: CAP. BANK
CUSTOMER	: RAA HOLDER CO., LTD.		


TECHNICAL DATA

Capacitor Manufacture	NOKIAN	Power Factor Controller Mfg.	NOKIAN
Type	FL2D	Power Factor Controller Model.	N-12
Rated Power	40 kVar	Serial No.	K1522127
Rated voltage	400 V	PF.Setting	0.95
Rated frequency	50 Hz	CT. Ratio	3000/5 A
Magnetic Type	ABB UA63-30	Power Fuse Rate	100 A

VISUAL INSPECTION AND FUNCTION TEST

1. Equipment and steel frame undamaged and cleaned
2. Name plate data is compliance with drawing and specification
3. All Fastenings checked
4. Safety clearance checked

Checked



VOLTAGE MEASUREMENT

L1-L2 400 V. L2-L3 400 V. L3-L1 400 V.

MEASUREMENT

Instrument : Digital multimeter Fluke model 179

Step No.	Rate Power (kVar)	Rate Fuse (A)	Measurement Capacitance (μF)			Result
			Phase A-B	Phase B-C	Phase C-A	
1	40	100	396	396	396	PASSED
2	40	100	398	397	398	PASSED
3	40	100	398	398	398	PASSED
4	40	100	396	396	396	PASSED
5	40	100	397	397	396	PASSED
6	40	100	399	399	399	PASSED
7	40	100	397	397	397	PASSED
8	40	100	398	397	395	PASSED
9	40	100	397	397	397	PASSED
10	40	100	398	398	397	PASSED
11	40	100	398	398	398	PASSED
12	40	100	399	398	398	PASSED

Reference from Formula

$$\text{Normal Current} = \frac{\text{kVar}}{V_{L-L} \times \sqrt{3}}$$

$$\text{Rated normal current} = 57.74 \text{ A} \quad (\text{ควรมีค่าอยู่ระหว่าง } 52.0 - 63.5 \text{ A})$$

$$\text{Normal Capacitance} = 397.89 \text{ μF} \quad (\text{ควรมีค่าอยู่ระหว่าง } 358.1 - 437.7 \text{ μF})$$

Remark :

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	



ESSI ENERGY GROUP CO., LTD.

4. GROUND RESISTANCE




FIELD INSPECTION AND TEST RECORD

GROUND RESISTANCE

PROJECT : PREVENTIVE MAINTENANCE **LOCATION** : GROUND POINT
ERECTION SITE : THE PARK NINE SUVARNABHUMI
CUSTOMER : RAA HOLDER CO., LTD.

GROUNDING RESISTANCE MEASUREMENT

Instrument : METREL MI3123



Item	Location	Grounding Resistance (Ω)	Accept.
1	TR.	1.08	< 5 Ω
2	Ground Box	0.62	

Remark : _____

Responsibility	Tested by	Witnessed by
Company	ESSI ENERGY GROUP CO., LTD.	
Name		
Signature		
Date	22 February 2022	

ภาคผนวกที่ 3-10
ใบเสร็จค่าเก็บขนมูลฝอย

PARK NINE

PARK NINE (P) LTD. CO.

ใบเสร็จขายกระดาษ ☒ เงินสด ☐ หักเงินเดือน

Name/Department :

ร้านขายของเก่า

Date : 20-Jul-22

Remark :

Code	Description	Qty.	Unit	Cost	Amount
	ขวดแก้ว		กก.	1	-
	กระดาษลัง		กก.	3.5	-
	เศษกระดาษ		กก.	2	-
	ขวดพลาสติก		กก.	7	-
	น้ำมัน	1.5	ลิตร	350	525.00
	ซีเมนต์	27	ใบ	5	135.00
	กระป๋องเบียร์		กก.	30	-
					-
					-
Total					660.00

Received By :

Check By :

โชน ชื่น

ใบเสร็จขายกระดาษ ☒ เงินสด ☐ หักเงินเดือน

Name/Department :

ร้านขายของเก่า

Date : 20-Aug-22

Remark :

Code	Description	Qty.	Unit	Cost	Amount
	ขวดแก้ว	100	กก.	0.5	50.00
	กระดาษลัง	300	กก.	4	1,200.00
	พลาสติกใส	40	กก.	6	240.00
	ขวดพลาสติก	5	กก.	2	10.00
	น้ำมัน		ลิตร	350	-
	ซีเมนต์		ใบ	5	-
	กระป๋องเบียร์	2	กก.	30	60.00
					-
					-
Total					1,560.00

Received By :

Check By :

1000 บาท ย่อ 26/9/22

ใบเสร็จขายกระดาษ ☒ เงินสด ☐ หักเงินเดือน

Name/Department : ร้านรับซื้อน้ำมันเก่า Date : 26-Sep-22

Remark : _____

Code	Description	Qty.	Unit	Cost	Amount
	น้ำมันดีเซลเก่าจากเครื่องปั่นไฟ	150	กก.	7	1,050.00
					-
					-
					-
					-
					-
					-
					-
					-



Received By : [REDACTED]



ใบเสร็จขายกระดาษ ☒ เงินสด ☐ หักเงินเดือน

Name/Department : ร้านขายของเก่า Date : 11-Nov-22



Remark : _____

Code	Description	Qty.	Unit	Cost	Amount
	ขวดแก้ว	106.5	กก.	0.5	53.25
	กระดาษลัง	532.5	กก.	1.5	798.75
	ขวดพลาสติก	54.5	กก.	4	218.00
	น้ำมัน	12	บิ๊ป	120	1,440.00
	บิ๊ป	38	ใบ	1	38.00
	หนังสือ+แฟงไข+เศษกระดาษ	18	กก.	1	18.00
	อลูมิเนียม	5.5	กก.	20	110.00
Total					2,676.00


Received By : [REDACTED] Check By : [REDACTED]

ภาคผนวกที่ 3-11
ผังการติดตั้งบ่อหนองน้ำ


บ่อหนองน้ำ



SECTION "A"
SPALT 1-201



SECTION "B"
SCALE 1:40

PROJECT / โครงการ	
<p>เทศบาลตำบลเมืองสุพรรณบุรี</p> <p>THE TAMBOLAMUANG SUPHABUR</p>	
LOCATION / สถานที่ตั้ง	
<p>ถนนลาดกระบัง กรุงเทพมหานคร</p> <p>Lat 13.748333333333333 Long 100.51666666666667</p>	
<p>หมายเลข / เลขทะเบียนโครงการ</p> <p>ดาวน์โหลดเอกสาร</p>	
	
<p>1. PROJECT NAME โครงการ ถนนลาดกระบัง</p> <p>2. PROJECT LOCATION ถนนลาดกระบัง กรุงเทพมหานคร</p> <p>3. PROJECT NO. 13.748333333333333 100.51666666666667</p> <p>4. PROJECT NO. 13.748333333333333 100.51666666666667</p>	

ภาคผนวกที่ 3-12

เอกสารการตรวจสอบระบบป้องกัน และระงับอัคคีภัย

The Park Nine Hotel Suvanabhumi

No	Floor	Location	Fire Extinguisher				Status		Fire Hose Cabinet										Remark
			TYPE OF EXTINGUISHER				Normal	Abnormal	Cabinet	Safety Glass	Hose reel	Fire hose 2.5"	2 Nozzles	Axe	Valve	Cap & Chain	Signage		
			Dry Chem	Co2	Form	BF2000			Status	Status	Status	Status	Status	Status	Status	Status	Cleanliness		
Building A																			
1	B	Parking Building	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
2	G	Front toilet EDL restaurant	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
3	G	F&B store (EDL)	-	1	-	-	/												
4	G	Generator Room	1	-	-	-	/												
5	G	Front Kitchen Room	1	-	-	-	/												
6	G	Kitchen Room	-	-	2	-	/												
7	2	Electrical Room	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
8	2	Front lift meeting	-	1	-	-	/		/	/	/	/	/	/	/	/	/	/	
Building B																			
9	B	Front of fire pump room	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
10	B	Front of HK Store	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
11	B	Fire staircase Hotel side	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
12	G	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
13	G	Lobby Hotel	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
14	G	Security Office	-	-	-	1	/												
15	G	Fire Cart Security	-	1	1	-	/												
16	G	Saver room	-	-	-	1	/												
17	G	Fire staircase Hotel	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
18	G	Corridor back office	-	-	-	1	/												
19	2	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
20	2	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
21	2	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
22	3	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
23	3	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
24	3	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
25	4	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
26	4	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
27	4	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
28	5	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
29	5	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
30	5	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
31	6	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
32	6	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
33	6	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	

Equipment monthly checklist July 2022

No.	Equipment	Monthly	Check day	Check by
1	FHC Check	July	11/07/2022	Mr. Ronnanrong Mechit
2	Emergency light		24/07/2022	Mr. Samrit Kongtungmon
3	Fire exit signage		30/07/2022	Mr. Wichai Chuearak
4	Fire exit staircase		30/07/2022	Mr. Wichai Chuearak
5	Fire Fighting checklist		31/07/2022	Mr. Sophon Saenmanee
6	Rescue equipments		31/07/2022	Mr. Sophon Saenmanee
7	Fire phone and jack		31/07/2022	Mr. Sophon Saenmanee
8	Elevator speaker phone		31/07/2022	Mr. Sophon Saenmanee
9	CCTV Checklist		31/07/2022	Mr. Ronnanrong Mechit

The Park Nine Hotel Suvarnabhumi

EMERGENCY LIGHT CHECKLIST

แบบฟอร์มตรวจเช็คไฟฉุกเฉินในโรงแรม

ตรวจเช็คโดย (INSPECTOR) Mr. Samrit Kongtungmon

วันที่ (DAET) 24/07/2022

Floor	Location	Brand/ Model	Code	Quantity	Status		
					Function Lighting Indicator		Battery Status
					Lamp	AC	
					Y/N	Y/N	
7	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-01	1	/	/	Normal
	Corridor resident #725 room		EM-02	1	/	/	Normal
	Hall lift Resident		EM-03	1	/	/	Normal
	Fire staircase st-7		EM-04	1	/	/	Normal
	Hall lift hotel		EM-05	1	/	/	Normal
	Corridor hotel #702 room		EM-06	1	/	/	Normal
	Corridor hotel #708 room		EM-07	1	/	/	Normal
	Fire staircase st-4 resident		EM-08	1	/	/	Normal
	Hall lift service		EM-09	1	/	/	Normal
	Network room		EM-10	1	/	X	Charge
	Electricity room		EM-11	1	/	X	Charge
6	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-12	1	/	/	Normal
	Corridor resident #625 room		EM-13	1	/	/	Normal
	Hall lift Resident		EM-14	1	/	/	Normal
	Fire staircase st-7		EM-15	1	/	/	Normal
	Hall lift hotel		EM-16	1	/	/	Normal
	Corridor hotel #602 room		EM-17	1	/	/	Normal
	Corridor hotel #608 room		EM-18	1	/	/	Normal
	Fire staircase st-4 resident		EM-19	1	/	/	Normal
	Hall lift service		EM-20	1	/	X	Charge
	Network room		EM-21	1	/	X	Charge
	Electricity room		EM-22	1	/	X	Charge

The Park Nine Hotel Suvarnabhumi

34	7	Fire staircase Resident	2	-	-	-	/	/	/	/	/	/	/	/	/	/	/	/
35	7	Hall lift Hotel	2	-	-	-	/	/	/	/	/	/	/	/	/	/	/	/
36	7	Fire staircase Hotel	2	-	-	-	/	/	/	/	/	/	/	/	/	/	/	/
Total			57	48	3	3	3											

Floor	Fire Blanket		
	Location	Quantity	Status
			Yes No
G	Kitchen	2	/
	Fire Cart	1	/
	TOTAL	3	

The Park Nine Hotel Suvarnabhumi

2	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-56	1	/	/	Normal
	Corridor resident #225 room		EM-57	1	/	/	Normal
	Hall lift Resident		EM-58	1	/	/	Normal
	Fire staircase st-7		EM-59	1	/	/	Normal
	Hall lift hotel		EM-60	1	/	/	Normal
	Corridor hotel		EM-61	1	/	/	Normal
	Corridor hotel #208 room		EM-62	1	/	/	Normal
	Fire staircase st-4 resident		EM-63	1	/	/	Normal
	Hall lift service		EM-64	1	/	X	Charge
	Electricity room		EM-65	1	/	X	Charge
G	Fire staircase st-4 resident	Dyno/ Drs-5203	EM-66	1	/	X	Charge
	Fire staircase st-7		EM-67	1	/	/	Normal
B	Parking	Dyno/ Drs-5203	EM-68	1	/	/	Normal
	Fire staircase st-5		EM-69	1	/	X	Charge
	Fire staircase st-7		EM-70	1	/	/	Normal
	Hall toilet staff		EM-71	1	/	X	Charge
	Man toilet staff		EM-72	1	/	X	Charge
	Female toilet staff		EM-73	1	/	/	Normal
	Hall lift service		EM-74	1	/	X	Charge
	Saff canteen		EM-75	1	/	/	Normal

The Park Nine Hotel Suvarnabhumi

5	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-23	1	/	/	Normal
	Corridor resident #525 room		EM-24	1	/	/	Normal
	Hall lift Resident		EM-25	1	/	/	Normal
	Fire staircase st-7		EM-26	1	/	/	Normal
	Hall lift hotel		EM-27	1	/	/	Normal
	Corridor hotel #502 room		EM-28	1	/	/	Normal
	Corridor hotel #508 room		EM-29	1	/	/	Normal
	Fire staircase st-4 resident		EM-30	1	/	/	Normal
	Hall lift service		EM-31	1	/	/	Normal
	Network room		EM-32	1	/	X	Charge
4	Electricity room	Dyno/ Drs-5203	EM-33	1	/	X	Charge
	Fire staircase st-8 hotel		EM-34	1	/	/	Normal
	Corridor resident #425 room		EM-35	1	/	/	Normal
	Hall lift Resident		EM-36	1	/	/	Normal
	Fire staircase st-7		EM-37	1	/	/	Normal
	Hall lift hotel		EM-38	1	/	/	Normal
	Corridor hotel #402 room		EM-39	1	/	/	Normal
	Corridor hotel #408 room		EM-40	1	/	/	Normal
	Fire staircase st-4 resident		EM-41	1	/	/	Normal
	Hall lift service		EM-42	1	/	X	Charge
3	Network room	Dyno/ Drs-5203	EM-43	1	/	X	Charge
	Electricity room		EM-44	1	/	X	Charge
	Fire staircase st-8 hotel		EM-45	1	/	/	Normal
	Corridor resident #325 room		EM-46	1	/	/	Normal
	Hall lift Resident		EM-47	1	/	/	Normal
	Fire staircase st-7		EM-48	1	/	/	Normal
	Hall lift hotel		EM-49	1	/	/	Normal
	Corridor hotel #302 room		EM-50	1	/	/	Normal
	Corridor hotel #308 room		EM-51	1	/	/	Normal
	Fire staircase st-4 resident		EM-52	1	/	/	Normal
	Hall lift service		EM-53	1	/	X	Charge
	Network room		EM-54	1	/	/	Normal
	Electricity room		EM-55	1	/	/	Normal

FIRE EXIT SIGNAGE CHECKLIST

แบบฟอร์มตรวจป้ายแสงทางออกหนีไฟในโรงแรม

ตรวจเช็คโดย (Inspector by) Mr. Wichai Chuearak วันที่ (Date) 30/07/2022



Floor	Location	Code	Exit Signs Amount	Status	
				Working	Not Working
7	Fire staircase st-4 resident	EX-01	1	/	Normal
	Hall lift Resident	EX-02	1	/	Normal
	Front lift resident	EX-03	1	/	Normal
	Fire staircase st-7	EX-04	1	/	Normal
	Hall lift hotel	EX-05	1	/	Normal
6	Corridor hotel #702 room	EX-06	1	/	Normal
	Front fire staircase st-8 hotel	EX-07	1	/	Normal
	Fire staircase st-4 resident	EX-08	1	/	Normal
	Hall lift Resident	EX-09	1	/	Normal
	Front lift resident	EX-10	1	/	Normal
5	Fire staircase st-7	EX-11	1	/	Normal
	Hall lift hotel	EX-12	1	/	Normal
	Corridor hotel #602 room	EX-13	1	/	Normal
	Front fire staircase st-8 hotel	EX-14	1	/	Normal
	Fire staircase st-4 resident	EX-15	1	/	Normal
4	Hall lift Resident	EX-16	1	/	Normal
	Front lift resident	EX-17	1	/	Normal
	Fire staircase st-7	EX-18	1	/	Normal
	Hall lift hotel	EX-19	1	/	Normal
	Corridor hotel #502 room	EX-20	1	/	Normal
3	Front fire staircase st-8 hotel	EX-21	1	/	Normal
	Fire staircase st-4 resident	EX-22	1	/	Normal
	Hall lift Resident	EX-23	1	/	Normal
	Front lift resident	EX-24	1	/	Normal
	Fire staircase st-7	EX-25	1	/	Normal
2	Hall lift hotel	EX-26	1	/	Normal
	Corridor hotel #402 room	EX-27	1	/	Normal
	Front fire staircase st-8 hotel	EX-28	1	/	Normal
	Fire staircase st-4 resident	EX-29	1	/	Normal
	Hall lift Resident	EX-30	1	/	Normal

The Park Nine Hotel Suvarnabhumi

EMERGENCY LIGHT CHECKLIST

แบบฟอร์มตรวจเช็คไฟฉุกเฉินในโรงแรม (อาคาร A)

Floor	Location	Brand/ Model	Code	Quantity	Status		
					Function Lighting indicator		
					Lamp Y/N	AC Y/N	Battery Status
G	Kitchen #1 (Entrance and Exit)	Dyno/ Drs-S203	EM-76	1	/	/	Normal
	Kitchen #2		EM-77	1	/	/	Normal
B	Car parking 1	Dyno/ Drs-S203	EM-78	1	/	X	Charge
	Car parking 2		EM-79	1	/	/	Normal
	Front entrance		EM-80	1	/	/	Normal
	Front lift		EM-81	1	/	/	Normal
Total		81					

Remark: ✓ = Yes or working
X = No or not working

Battery Status = Normal, = Charge

Emergency light not working 21 points.

FIRE EXIT STAIRCASE CHECKLIST

แบบตรวจเช็คสภาพภายในบันไดหนีไฟและบานประตูหนีไฟของ โรงแรม

ตรวจเช็คโดย (Inspect by): Mr. Wichai Chuearak

วันที่ (Date): 30/07/2022

Floor	Location	สิ่งกีดขวาง Obstructions		หลอดไฟส่องสว่าง Neon Lighting		ประตูทางหนีไฟ Fire exit door		คันผก Panic bar		คันดึงประตู Self closer		หมายเหตุ Remark
		Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
RoofTop	Fire staircase st-7	/		/		/		/		/		
7	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
6	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
5	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
4	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
3	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
2	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
G	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
B	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-5 FO Office	/		/		/		/		/		

Reported by : Mr. Wichai Chuearak
Position: Security Officer

Acknowledge by: Mr. Kathawut Ketphot










The Park Nine Hotel Suvarnabhumi







แบบฟอร์มตรวจเส้นทางออกหนีไฟในโรงแรม

Floor	Location	Code	Exit Signs Amount	Status	
				Working	Not Working
G	Front fire staircase st-8 hotel	EX-43	1	/	Normal
B	Exit to parking	EX-44	1	/	Normal
	Corridor no.01	EX-45	1	/	Normal
	Corridor no.02	EX-46	1	/	Normal
	Fire staircase st-7	EX-47	1	/	Normal
Total		47			

Reported by: Mr. Wichai Chuearak
Position: Security Officer



FIRE FIGHTING EQUIPMENT CHECKLIST						
ตรวจสอบโดย (Inspector By) <u>Mr. Sophon Saenmanee</u> วันที่ (DATE) <u>31/07/2022</u>						
No.	Equipment	Amount	Actual	Picture	Condition Yes No	REMARK
1	Fire suite	3	3		/	
2	Helmet	3	3		/	
3	Leather Glove	3	3		/	
4	Safety Mask	3	3		/	
5	Hood	3	3		/	
6	Safety Glasses	3	3		/	
7	Boot	3	3		/	

8	Fire Blanket	1	1		/	
9	Nozzles (Protek Model 366)	1	1		/	
10	Fire Hose 2.5"	2	2		/	
11	Fire Phone	1	1		/	
12	Cradle	1	1		/	
13	Megaphone	1	1		/	

Reported By: Mr. Sophon Saenmanee Acknowledge By: Mr. Kathawut Ketphot
 Position: Security Supervisor Position: Security Manager
 Date: 31/07/2022

FIRE PHONE OPERATION CHECKLIST

แบบตรวจเช็คอุปกรณ์โทรศัพท์ฉุกเฉินที่ติดตั้งในห้องโรงแรม

ตรวจเช็คโดย (Checked By): Mr. Sophon Saenmanee

วันที่ (Date): 31/07/2022

Item No. ลำดับที่	Floor ชั้น	Description/Location รายละเอียดสถานที่ตั้ง	Fire Phone Functional Checklist				Remark หมายเหตุ
			Quantity จำนวน	Obvious เสียงส่งชัดเจน	Function correct ทำงานถูกต้อง	Fire jack สภาพเต้าเสียบ	
1	7	Fire staircase st-8 resident	1	/	/	/	
2		Fire staircase st-7	1	/	/	/	
3		Hall lift serviced	1	/	/	/	
4		Front fire staircase st-4 hotel	1	/	/	/	
5	6	Fire staircase st-8 resident	1	/	/	/	
6		Fire staircase st-7	1	/	/	/	
7		Hall lift serviced	1	/	/	/	
8		Front fire staircase st-4 hotel	1	/	/	/	
9	5	Fire staircase st-8 resident	1	/	/	/	
10		Fire staircase st-7	1	/	/	/	
11		Hall lift serviced	1	/	/	/	
12		Front fire staircase st-4 hotel	1	/	/	/	
13	4	Fire staircase st-8 resident	1	/	/	/	
14		Fire staircase st-7	1	/	/	/	
15		Hall lift serviced	1	/	/	/	
16		Front fire staircase st-4 hotel	1	/	/	/	
17	3	Fire staircase st-8 resident	1	/	/	/	
18		Fire staircase st-7	1	/	/	/	
19		Hall lift serviced	1	/	/	/	
20		Front fire staircase st-4 hotel	1	/	/	/	
21	2	Fire staircase st-8 resident	1	/	/	/	
22		Fire staircase st-7	1	/	/	/	
23		Hall lift serviced	1	/	/	/	
24		Front fire staircase st-4 hotel	1	/	/	/	
25	G	Fire staircase st-7	1	/	/	/	
26		Hall lift serviced	1	/	/	/	
27	B	Fire staircase st-7	1	/	/	/	
28		Hall lift serviced	1	/	/	/	

Reported By: Mr. Sophon Saenmanee

Position: Security Supervisor

Acknowledged By: _____





SAFETY AND SECURITY DEPARTMENT

RESCUE EQUIPMENT CHECKLIST

แบบฟอร์มตรวจเช็คอุปกรณ์ช่วยเหลือที่ติดตั้งในห้องโรงแรม

วันที่ (Date): 30/07/2022

ตรวจเช็คโดย (Inspector By): Mr. Sophon Saenmanee

No.	Details Equipment	Amount	Actual	Picture	Status		Remark
					Yes	No	
1	Body Rescue Hook	1	1		/		
2	Ring Buoy	2	2		/		
3	AMBU bag size 500 ml	1	1		/		
4	AMBU bag size 250 ml	1	1		/		

Reported By: Mr. Sophon Saenmanee

Position: Security Supervisor

Acknowledged By: Mr. Kathawut Kalitbol

CCTV CHECKLIST

แบบตรวจเช็คการทำงานของระบบกล้องวงจรปิดใน โรงแรม

ตรวจเช็คโดย (Inspector By) Mr. Ronnanrong Mechit

วันที่ (Date) 31/07/2022

เวลา (Time) 23.00น.

No.	NVR No.1		Flour	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
1	1	Carpark in-out	B	/		/			/		/		
2	2	Car park 1	B	/		/			/		/		
3	3	Car park 2	B	/		/			/		/		
4	4	Staff canteen	B	/		/			/		/		
5	5	Staff toilet	B	/		/			/		/		
6	6	HK Office	B	/		/			/		/		
7	7	FO counte	G	/		/			/		/		
8	8	FO lift	G	/		/			/		/		
9	9	HR Office	G	/		/			/		/		
10	10	Back Office	G	/		/			/		/		
11	11	Lobby loun	G	/		/			/		/		
12	12	Entrance lobby	G	/		/			/		/		
13	13	Front F&B Office	G	/		/			/		/		
14	14	AC store	G	/		/			/		/		
15	15	Front security office	G	/		/			/		/		
16	16	Bell store	G	/		/			/		/		
17	17	FO office	G	/		/			/		/		
18	18	Fitness room	G	/		/			/		/		
19	19	Outdoor 1	G	/		/			/		/		
20	20	Outdoor 2	G	/		/			/		/		
21	21	Outdoor 3	G	/		/			/		/		
22	22	In out kitchen	G	/		/			/		/		
23	23	Swimming pool	G	/		/			/		/		
24	24	Receiving Aaea	G	/		/			/		/		
25	25	Out door lobby	G	/		/			/		/		
26	26	Garbags room	G	/		/			/		/		
27	27	Residence front lift	2	/		/			/		/		
28	28	Staircase St-7	2	/		/			/		/		
29	29	Hotel lift	2	/		/			/		/		
30	30	Hotel 1	2	/		/			/		/		

The Park Nine Hotel Suvarnabhumi

Date: 31/07/2022

No.	DESCRIPTION/LOCATION	ELEVATOR EMERGENCY SPEAKER PHONE CHECK LIST									REMARK/COMMENT
		Quantity	Location at Display On Emergency Phone		Obvious Control Room		Obvious In an Elevator		Obvious Operator Room		
			แสดงสถานที่ ตรงกับโทรศัพท์ฉุกเฉิน		เสียงส่งชัดเจน ห้องคอลโทรล		เสียงส่งชัดเจน ในลิฟต์		เสียงส่งชัดเจน Operator room		
ลำดับที่	คำอธิบาย/สถานที่ติดตั้ง	จำนวน	YES	NO	YES	NO	YES	NO	YES	NO	ข้อเสนอแนะ/เสนอแนะ
1	Emergency Speaker Guest Lift L-1	1	/		/		/		/		
2	Emergency Speaker Guest Lift L-2	1	/		/		/		/		
3	Emergency Speaker Guest Lift L-3	1	/		/		/		/		
4	Emergency Speaker Serviced Lift L-4	1	/		/		/		/		
5	Emergency Speaker Guest Lift L-5 (A building)	No Finished									
6	Emergency Speaker Service Lift L-6 (A building)	1	/		/		/		/		

Checked by: Mr. Sophon Saenmanee

Ackn

Position: Security Supervisor

No.	NVR No.2		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
1	1	Lift No.5	G	/		/			/		/		
2	2	Service lift	G	/		/			/		/		
3	3	Hotel lift No.1	G	/		/			/		/		
4	4	Hotel lift No.2	G	/		/			/		/		
5	5	Residence lift	G		X			X		X		X	เปลี่ยนอุปกรณ์ Power supply แล้วยังไม่ดี ภาพรบกวนกล้อง ดำเนินการ
6	6	Front lift No.5	G	/		/			/		/		
7	7	Car parking 1	B	/		/			/		/		
8	8	Car parking 2	B	/		/			/		/		
9	9	Inside edl 1	G	/		/			/		/		
10	10	Inside edl 2	G	/		/			/		/		
11	11	Inside edl 3	G	/		/			/		/		
12	12	Inside edl 4	G	/		/			/		/		
13	13	Entrance EDL	G	/		/			/		/		
14	14	Cupper	G	/		/			/		/		
15	15	Front Cupper	G	/		/			/		/		
16	16	In-front Building	G	/		/			/		/		
17	17	Toilet EDL	G	/		/			/		/		
18	18	Fountain	G	/		/			/		/		
19	19	Kitchen Room 1	G	/		/			/		/		
20	20	Kitchen Room 2	G	/		/			/		/		
21	21	Guest house 1	G	/		/			/		/		
22	22	Guest house 2	G	/		/			/		/		
23	23	Outdoor parking 1	G	/		/			/		/		
24	24	Outdoor parking 2	G	/		/			/		/		
25	25	In-out hotel	G	/		/			/		/		
26	26	Lily lift	G		X		X			X		X	ภาพไม่มีวันที่ 5/3/65 เวลา 20.57 น. รอ
27	27	Lily 1	G		X								

No.	NVR No.1		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
31	31	Hotel 2	2	/		/			/		/		
32	32	Residence 2	2	/		/			/		/		
33	30	Residence front lift	3	/		/			/		/		
34	31	Staircase St-7	3	/		/			/		/		
35	32	Hotel lift	3	/		/			/		/		
36	33	Hotel 1	3	/		/			/		/		
37	34	Hotel 2	3	/		/			/		/		
38	35	Residence 2	3	/		/			/		/		
39	36	Residence front lift	4	/		/			/		/		
40	37	Staircase St-7	4	/		/			/		/		
41	38	Hotel lift	4	/		/			/		/		
42	39	Hotel 1	4	/		/			/		/		
43	40	Hotel 2	4	/		/			/		/		
44	41	Residence 2	4	/		/			/		/		
45	42	Residence front lift	5	/		/			/		/		
46	43	Staircase St-7	5	/		/			/		/		
47	44	Hotel lift	5	/		/			/		/		
48	45	Hotel 1	5	/		/			/		/		
49	46	Hotel 2	5	/		/			/		/		
50	47	Residence 2	5	/		/			/		/		
51	48	Residence front lift	6	/		/			/		/		
52	49	Staircase St-7	6	/		/			/		/		
53	50	Hotel lift	6	/		/			/		/		
54	51	Hotel 1	6	/		/			/		/		
55	52	Hotel 2	6	/		/			/		/		
56	53	Residence 2	6	/		/			/		/		
57	54	Residence front lift	7	/		/			/		/		
58	55	Staircase St-7	7	/		/			/		/		
59	56	Hotel lift	7	/		/			/		/		
60	57	Hotel 1	7	/		/			/		/		
61	58	Hotel 2	7	/		/			/		/		
62	59	Residence 2	7	/		/			/		/		

Equipment monthly checklist August 2022

No.	Equipment	Monthly	Check day	Check by
1	FHC Check	August	7/08/2022	Mr. Wichai Chuearak
2	Emergency light		30/08/2022	Mr. Sophon Saenmanee
3	Fire exit signage		31/08/2022	Mr. Wichai Chuearak
4	Fire exit staircase		31/08/2022	Mr. Samrit Kongtungmon
5	Fire Fighting checklist		31/08/2022	Mr. Samrit Kongtungmon
6	Rescue equipments		31/08/2022	Mr. Samrit Kongtungmon
7	Fire phone and jack		31/08/2022	Mr. Kathawut Ketphot
8	Elevator speaker phone		31/08/2022	Mr. Samrit Kongtungmon
9	CCTV Checklist		31/08/2022	Mr. Kathawut Ketphot

Acknowledge By: _____
 (Mr. Chatree Nuiprasith)

Position: Group Resident Manager

Date: _____



28	28	Lily 2	2		X		X			X		X
29	29	Back meeting	2	/		/			/		/	

NVR No.	Period Time Record	Total/Day
PRN-4011 (172.20.0.2:8001)	01/07/22-31/07/22	31 Day
NVR (172.20.3.554)	01/07/22-31/07/22	31 Day
NVR03 (172.20.0.4:554)	01/07/22-31/07/22	31 Day

Reported by: Mr. Ronnanrong Mechit

Title: Security Officer

Acknowledged By: Mr. Kathawut Ketphot

Title: Security Manager

Date: 31/07/2022

*Dome Camera 69 Unit
 *Out Doors Camera 22 Unit
 Total 91 Unit



The Park Nine Hotel Suvarnabhumi

[illegible]

Floor	Fire Blanket			
	Location	Quantity	Status	
			Yes	No
G	Kitchen	2	/	
	Fire Cart	1	/	
	TOTAL	3		

Reported by: Mr. Wichai Chuearak

Position: Security Officer

Date: 7/08/2022

Acknowledge by: Mr. Kathawut Ketphol

Position: Security Manager

Date: 31/08/2022

The Park Nine Hotel Suvanabhumi

[illegible]

The Park Nine Hotel Suvarnabhumi

5	Fire staircase st-8 hotel	Dyno/ Drs-5203	FM-23	1	/	/	Normal
	Corridor resident #525 room		EM-24	1	/	/	Normal
	Hall lift Resident		FM-25	1	/	/	Normal
	Fire staircase st-7		EM-26	1	/	/	Normal
	Hall lift hotel		EM-27	1	/	/	Normal
	Corridor hotel #502 room		EM-28	1	/	/	Normal
	Corridor hotel #508 room		EM-29	1	/	/	Normal
	Fire staircase st-4 resident		EM-30	1	/	/	Normal
	Hall lift service		EM-31	1	/	/	Normal
	Network room		EM-32	1	/	X	Charge
4	Electricity room		EM-33	1	/	X	Charge
	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-34	1	/	/	Normal
	Corridor resident #425 room		EM-35	1	/	/	Normal
	Hall lift Resident		EM-36	1	/	/	Normal
	Fire staircase st-7		EM-37	1	/	/	Normal
	Hall lift hotel		EM-38	1	/	/	Normal
	Corridor hotel #402 room		EM-39	1	/	/	Normal
	Corridor hotel #408 room		EM-40	1	/	/	Normal
	Fire staircase st-4 resident		EM-41	1	/	/	Normal
	Hall lift service		EM-42	1	/	X	Charge
	Network room		EM-43	1	/	X	Charge
3	Electricity room		EM-44	1	/	X	Charge
	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-45	1	/	/	Normal
	Corridor resident #325 room		EM-46	1	/	/	Normal
	Hall lift Resident		EM-47	1	/	/	Normal
	Fire staircase st-7		EM-48	1	/	/	Normal
	Hall lift hotel		EM-49	1	/	/	Normal
	Corridor hotel #302 room		EM-50	1	/	/	Normal
	Corridor hotel #308 room		EM-51	1	/	/	Normal
	Fire staircase st-4 resident		EM-52	1	/	/	Normal
	Hall lift service		EM-53	1	/	X	Charge
	Network room		EM-54	1	/	X	Charge
	Electricity room		EM-55	1	/	X	Charge

The Park Nine Hotel Suvarnabhumi



EMERGENCY LIGHT CHECKLIST

แบบฟอร์มตรวจเช็คไฟฉุกเฉินในโรงแรม

ตรวจเช็คโดย (INSPECTOR) Mr. Sophon Saenmanee

วันที่ (DAET) 30/08/2022

Floor	Location	Brand/ Model	Code	Quantity	Status		
					Function Lighting Indicator		Battery Status
					Lamp Y/N	AC Y/N	
7	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-01	1	/	/	Normal
	Corridor resident #725 room		EM-02	1	/	/	Normal
	Hall lift Resident		EM-03	1	/	/	Normal
	Fire staircase st-7		EM-04	1	/	/	Normal
	Hall lift hotel		EM-05	1	/	/	Normal
	Corridor hotel #702 room		EM-06	1	/	/	Normal
	Corridor hotel #708 room		EM-07	1	/	/	Normal
	Fire staircase st-4 resident		EM-08	1	/	/	Normal
	Hall lift service		EM-09	1	/	/	Normal
	Network room		EM-10	1	/	X	Charge
6	Electricity room		EM-11	1	/	X	Charge
	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-12	1	/	/	Normal
	Corridor resident #625 room		EM-13	1	/	/	Normal
	Hall lift Resident		EM-14	1	X	/	Normal
	Fire staircase st-7		EM-15	1	/	/	Normal
	Hall lift hotel		EM-16	1	/	/	Normal
	Corridor hotel #602 room		EM-17	1	/	/	Normal
	Corridor hotel #608 room		EM-18	1	/	/	Normal
	Fire staircase st-4 resident		EM-19	1	/	/	Normal
	Hall lift service		EM-20	1	/	X	Charge
	Network room		EM-21	1	/	X	Charge
	Electricity room		EM-22	1	/	X	Charge

The Park Nine Hotel Suvarnabhumi



EMERGENCY LIGHT CHECKLIST

แบบฟอร์มตรวจเช็คไฟฉุกเฉินในโรงแรม (อาคาร A)

Floor	Location	Brand/ Model	Code	Quantity	Status		
					Function Lighting indicator		
					Lamp Y/N	AC Y/N	Battery Status
G	Kitchen #1 (Entrance and Exit)	Dyno/ Drs-5203	EM-76	1	/	/	Normal
	Kitchen #2		EM-77	1	/	/	Normal
B	Car parking 1	Dyno/ Drs-5203	EM-78	1	/	X	Charge
	Car parking 2		EM-79	1	/	/	Normal
	Front entrance		EM-80	1	/	/	Normal
	Front lift		EM-81	1	/	/	Normal
Total		81					

Remark: ✓ = Yes or working

X = No or not working

Battery Status = Normal, = Charge

Emergency light not working 21 points.

Reported by: Mr. Sophon Saenmanee

Position: Security Supervisor


Acknowledge by: Mr. Kathawut Keiphot Date: 31/08/2022

Position: Security Manager



The Park Nine Hotel Suvarnabhumi

2	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-56	1	/	/	Normal
	Corridor resident #225 room		EM-57	1	/	/	Normal
	Hall lift Resident		EM-58	1	/	/	Normal
	Fire staircase st-7		EM-59	1	/	/	Normal
	Hall lift hotel		EM-60	1	/	/	Normal
	Corridor hotel		EM-61	1	/	/	Normal
	Corridor hotel #208 room		EM-62	1	/	/	Normal
	Fire staircase st-4 resident		EM-63	1	/	/	Normal
	Hall lift service		EM-64	1	/	X	Charge
	Electricity room		EM-65	1	/	X	Charge
G	Fire staircase st-4 resident	Dyno/ Drs-5203	EM-66	1	/	X	Charge
	Fire staircase st-7		EM-67	1	/	/	Normal
B	Parking	Dyno/ Drs-5203	EM-68	1	/	/	Normal
	Fire staircase st-5		EM-69	1	/	X	Charge
	Fire staircase st-7		EM-70	1	/	/	Normal
	Hall toilet staff		EM-71	1	/	X	Charge
	Man toilet staff		EM-72	1	/	X	Charge
	Female toilet staff		EM-73	1	/	/	Normal
	Hall lift service		EM-74	1	/	X	Charge
	Saff canteen		EM-75	1	/	/	Normal



FIRE EXIT SIGNAGE CHECKLIST

แบบฟอร์มตรวจป้ายทางออกฉุกเฉินในโรงแรม

วันที่ (Date) 31/08/2022

ตรวจโดย (Inspector by) Mr. Samrit Kongtunamon

Floor	Location	Code	Exit Signs Amount		Status	
			Working	Not Working	Working	Not Working
7	Fire staircase st-4 resident	EX-01	1	/	Normal	Normal
	Hall lift Resident	EX-02	1	/	Normal	Normal
	Front lift resident	EX-03	1	/	Normal	Normal
	Fire staircase st-7	EX-04	1	/	Normal	Normal
	Hall lift hotel	EX-05	1	/	Normal	Normal
	Corridor hotel #702 room	EX-06	1	/	Normal	Normal
6	Front fire staircase st-8 hotel	EX-07	1	/	Normal	Normal
	Fire staircase st-4 resident	EX-08	1	/	Normal	Normal
	Hall lift Resident	EX-09	1	/	Normal	Normal
	Front lift resident	EX-10	1	/	Normal	Normal
	Fire staircase st-7	EX-11	1	/	Normal	Normal
	Hall lift hotel	EX-12	1	/	Normal	Normal
5	Corridor hotel #602 room	EX-13	1	/	Normal	Normal
	Front fire staircase st-8 hotel	EX-14	1	/	Normal	Normal
	Fire staircase st-4 resident	EX-15	1	/	Normal	Normal
	Hall lift Resident	EX-16	1	/	Normal	Normal
	Front lift resident	EX-17	1	/	Normal	Normal
	Fire staircase st-7	EX-18	1	/	Normal	Normal
4	Hall lift hotel	EX-19	1	/	Normal	Normal
	Corridor hotel #502 room	EX-20	1	/	Normal	Normal
	Front fire staircase st-8 hotel	EX-21	1	/	Normal	Normal
	Fire staircase st-4 resident	EX-22	1	/	Normal	Normal
	Hall lift Resident	EX-23	1	/	Normal	Normal
	Front lift resident	EX-24	1	/	Normal	Normal
3	Fire staircase st-7	EX-25	1	/	Normal	Normal
	Hall lift hotel	EX-26	1	/	Normal	Normal
	Corridor hotel #402 room	EX-27	1	/	Normal	Normal
	Front fire staircase st-8 hotel	EX-28	1	/	Normal	Normal
	Fire staircase st-4 resident	EX-29	1	/	Normal	Normal
	Hall lift Resident	EX-30	1	/	Normal	Normal
2	Front lift resident	EX-31	1	/	Normal	Normal
	Fire staircase st-7	EX-32	1	/	Normal	Normal
	Hall lift hotel	EX-33	1	/	Normal	Normal
	Corridor hotel #302 room	EX-34	1	/	Normal	Normal
	Front fire staircase st-8 hotel	EX-35	1	/	Normal	Normal
	Fire staircase st-4 resident	EX-36	1	/	Normal	Normal
	Hall lift Resident	EX-37	1	/	Normal	Normal
	Front lift resident	EX-38	1	/	Normal	Normal
	Fire staircase st-7	EX-39	1	/	Normal	Normal
	Hall lift hotel	EX-40	1	/	Normal	Normal
	Corridor hotel	EX-41	1	/	Normal	Normal
	Front fire staircase st-8 hotel	EX-42	1	/	Normal	Normal

แบบฟอร์มตรวจป้ายทางออกฉุกเฉินในโรงแรม

Floor	Location	Code	Exit Signs Amount		Status	
			Working	Not Working	Working	Not Working
G	Front fire staircase st-8 hotel	EX-43	1	/	Normal	Normal
B	Exit to parking	EX-44	1	/	Normal	Normal
	Corridor no.01	EX-45	1	/	Normal	Normal
	Corridor no.02	EX-46	1	/	Normal	Normal
	Fire staircase st-7	EX-47	1	/	Normal	Normal
Total	47					

Reported by: Mr. Samrit Kongtunamon

Position: Sr. Security Officer








Acknowledge by: Mr. Kalhawit Ketchphol

Position: Security Manager

FIRE FIGHTING EQUIPMENT CHECKLIST

แบบตรวจเช็คอุปกรณ์ในจุดเพลิงไหม้
ตรวจเช็คโดย (Inspector By) Mr. Samrit Kongtungmon

วันที่ (DATE) 31/08/2022

No.	Equipment	Amount	Actual	Picture	Condition		REMARK
					Yes	No	
1	Fire suite	3	3		/		
2	Helmet	3	3		/		
3	Leather Glove	3	3		/		
4	Safety Mask	3	3		/		
5	Hood	3	3		/		
6	Safety Glasses	3	3		/		
7	Boot	3	3		/		

FIRE EXIT STAIRCASE CHECKLIST

แบบตรวจเช็คสภาพภายในบันไดหนีไฟและบานประตูหนีไฟของ โรงแรม







ตรวจเช็คโดย (Inspect by): Mr. Samrit Kongtungmon

วันที่ (Date): 31/08/2022

Floor	Location	สิ่งกีดขวาง Obstructions		หลอดไฟส่องสว่าง Neon Lighting		ประตูทางหนีไฟ Fire Exit Door		คานเหล็ก Panic Bar		ก้านดึงประตู Self Closer		หมายเหตุ Remark
		Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
Rooftop	Fire staircase st-7	/		/		/		/		/		
7	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
6	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
5	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
4	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
3	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
2	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
G	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
B	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-5 FO Office	/		/		/		/		/		

Reported by : Mr. Samrit Kongtungmon
Position: Sr. Security Officer

Acknowledge by: Mr. Kathawut Ketphot
Position: Security Manager
Date: 31/08/2022

8	Fire Blanket	1	1		/		
9	Nozzles (Protek Model 366)	1	1		/		
10	Fire Hose 2.5"	2	2		/		
11	Fire Phone	1	1		/		
12	Cradle	1	1		/		
13	Megaphone	1	1		/		

Reported By: Mr. Samrit Kongtongmon
Position: Sr. Security Officer





Acknowledge By: Mr. Kathawut Ketphot
Position: Security Manager



RESCUE EQUIPMENT CHECKLIST


แบบฟอร์มตรวจสอบอุปกรณ์กู้ภัยและเครื่องมือช่วยเหลือผู้ประสบอุบัติเหตุ

ตรวจสอบโดย (Inspector By) Mr. Samrit Kongtongmon วันที่ (Date) 31/08/2022

No.	Details Equipment	Amount	Actual	Picture	Status		Remark
					Yes	No	
1	Body Rescue Hook	1	1		/		
2	Ring Buoy	2	2		/		
3	AMBU bag size 500 ml	1	1		/		
4	AMBU bag size 250 ml	1	1		/		

Reported By: Mr. Samrit Kongtongmon
Position: Sr. Security Officer

Acknowledge By: Mr. Kathawut Ketphot
Position: Security Manager
Date: 31/08/2022



The Park Nine Hotel Suvarnabhumi

Date: 31/08/2022

No.	DESCRIPTION/LOCATION	ELEVATOR EMERGENCY SPEAKER PHONE CHECK LIST									REMARK/COMMENT
		Quantity	Location at Display On Emergency Phone		Obvious Control Room		Obvious In an Elevator		Obvious Operator Room		
			แสดงสถานที่ ตรงกับโทรศัพท์ฉุกเฉิน		เสียงส่งชัดเจน ห้องคอลโทรล		เสียงส่งชัดเจน ในลิฟต์		เสียงส่งชัดเจน Operator room		
ลำดับที่	คำอธิบาย/สถานที่ติดตั้ง	จำนวน	ตรงกับโทรศัพท์ฉุกเฉิน		ห้องคอลโทรล		ในลิฟต์		Operator room		ข้อแนะนำ/เสนอแนะ
			YES	NO	YES	NO	YES	NO	YES	NO	
1	Emergency Speaker Guest Lift L-1	1	/		/		/		/		
2	Emergency Speaker Guest Lift L-2	1	/		/		/		/		
3	Emergency Speaker Guest Lift L-3	1	/		/		/		/		
4	Emergency Speaker Serviced Lift L-4	1	/		/		/		/		
5	Emergency Speaker Guest Lift L-5 (A building)	No Finished									
6	Emergency Speaker Service Lift L-6 (A building)	1	/		/		/		/		

Checked by: Mr. Samrit Kongtungmon

Acknowledged By: Mr. Kathawut Ketphot

Position: Sr. Security Officer

Title: Security Manager

Date: 31/08/2022



The Park Nine Hotel Suvarnabhumi

FIRE PHONE OPERATION CHECKLIST

แบบตรวจเช็คอุปกรณ์โทรศัพท์ฉุกเฉินที่ติดตั้งเพลิงโรงแรม

ตรวจเช็คโดย (Checked By): Mr.Kathawut Ketphot

วันที่ (Date): 31/08/2022

Item No.	Floor	Description/Location	Fire Phone Functional Checklist				Remark
			Quantity	Obvious	Function correct	Fire jack	
ลำดับที่	ชั้น	รายละเอียด/สถานที่ตั้ง	จำนวน	เสียงส่งชัดเจน	ทำงานถูกต้อง	สภาพเต้าเสียบ	หมายเหตุ
1	7	Fire staircase st-8 resident	1	/	/	/	
2		Fire staircase st-7	1	/	/	/	
3		Hall lift serviced	1	/	/	/	
4		Front fire staircase st-4 hotel	1	/	/	/	
5	6	Fire staircase st-8 resident	1	/	/	/	
6		Fire staircase st-7	1	/	/	/	
7		Hall lift serviced	1	/	/	/	
8		Front fire staircase st-4 hotel	1	/	/	/	
9	5	Fire staircase st-8 resident	1	/	/	/	
10		Fire staircase st-7	1	/	/	/	
11		Hall lift serviced	1	/	/	/	
12		Front fire staircase st-4 hotel	1	/	/	/	
13	4	Fire staircase st-8 resident	1	/	/	/	
14		Fire staircase st-7	1	/	/	/	
15		Hall lift serviced	1	/	/	/	
16		Front fire staircase st-4 hotel	1	/	/	/	
17	3	Fire staircase st-8 resident	1	/	/	/	
18		Fire staircase st-7	1	/	/	/	
19		Hall lift serviced	1	/	/	/	
20		Front fire staircase st-4 hotel	1	/	/	/	
21	2	Fire staircase st-8 resident	1	/	/	/	
22		Fire staircase st-7	1	/	/	/	
23		Hall lift serviced	1	/	/	/	
24		Front fire staircase st-4 hotel	1	/	/	/	
25	G	Fire staircase st-7	1	/	/	/	
26		Hall lift serviced	1	/	/	/	
27	B	Fire staircase st-7	1	/	/	/	
28		Hall lift serviced	1	/	/	/	

Reported By: Mr.Kathawut Ketphot

Position: Security Manager

No.	NVR No.1		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
31	31	Hotel 2	2	/		/			/		/		
32	32	Residence 2	2	/		/			/		/		
33	30	Residence front lift	3	/		/			/		/		
34	31	Staircase St-7	3	/		/			/		/		
35	32	Hotel lift	3	/		/			/		/		
36	33	Hotel 1	3	/		/			/		/		
37	34	Hotel 2	3	/		/			/		/		
38	35	Residence 2	3	/		/			/		/		
39	36	Residence front lift	4	/		/			/		/		
40	37	Staircase St-7	4	/		/			/		/		
41	38	Hotel lift	4	/		/			/		/		
42	39	Hotel 1	4	/		/			/		/		
43	40	Hotel 2	4	/		/			/		/		
44	41	Residence 2	4	/		/			/		/		
45	42	Residence front lift	5	/		/			/		/		
46	43	Staircase St-7	5	/		/			/		/		
47	44	Hotel lift	5	/		/			/		/		
48	45	Hotel 1	5	/		/			/		/		
49	46	Hotel 2	5	/		/			/		/		
50	47	Residence 2	5	/		/			/		/		
51	48	Residence front lift	6	/		/			/		/		
52	49	Staircase St-7	6	/		/			/		/		
53	50	Hotel lift	6	/		/			/		/		
54	51	Hotel 1	6	/		/			/		/		
55	52	Hotel 2	6	/		/			/		/		
56	53	Residence 2	6	/		/			/		/		
57	54	Residence front lift	7	/		/			/		/		
58	55	Staircase St-7	7	/		/			/		/		
59	56	Hotel lift	7	/		/			/		/		
60	57	Hotel 1	7	/		/			/		/		
61	58	Hotel 2	7	/		/			/		/		
62	59	Residence 2	7	/		/			/		/		

CCTV CHECKLIST

แบบตรวจเช็คการทำงานของระบบกล้องวงจรปิดใน โรงแรม

ตรวจเช็คโดย (Inspector By) Mr. Kathawut Ketphont

วันที่ (Date) 31/08/2022

เวลา (Time) 10.00 Am.

No.	NVR No.1		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
1	1	Carpark in-out	B	/		/			/		/		
2	2	Car park 1	B	/		/			/		/		
3	3	Car park 2	B	/		/			/		/		
4	4	Staff canteen	B	/		/			/		/		
5	5	Staff toilet	B	/		/			/		/		
6	6	HK Office	R	/		/			/		/		
7	7	FO counte	G	/		/			/		/		
8	8	FO lift	G	/		/			/		/		
9	9	HR Office	G	/		/			/		/		
10	10	Back Office	G	/		/			/		/		
11	11	Lobby loun	G	/		/			/		/		
12	12	Entrance lobby	G	/		/			/		/		
13	13	Front F&B Office	G	/		/			/		/		
14	14	AC store	G	/		/			/		/		
15	15	Front security office	G	/		/			/		/		
16	16	Bell store	G	/		/			/		/		
17	17	FO office	G	/		/			/		/		
18	18	Fitness room	G	/		/			/		/		
19	19	Outdoor 1	G	/		/			/		/		
20	20	Outdoor 2	G	/		/			/		/		
21	21	Outdoor 3	G	/		/			/		/		
22	22	In out kitchen	G	/		/			/		/		
23	23	Sweimming pool	G	/		/			/		/		
24	24	Receiving Aaca	G	/		/			/		/		
25	25	Out door lobby	G	/		/			/		/		
26	26	Garbags room	G	/		/			/		/		
27	27	Residence front lift	2	/		/			/		/		
28	28	Staircase St-7	2	/		/			/		/		
29	29	Hotel lift	2	/		/			/		/		
30	30	Hotel 1	2	/		/			/		/		

NVR No.	Period Time Record	Total/Day
PRN-4011 (172.20.0.2:8001)	27/07/22-31/08/22	36 Day
NVR (172.20.3.554)	27/07/22-31/08/22	36 Day
NVR03 (172.20.0.4:554)	11/07/22-31/08/22	52 Day

Reported by: Mr. Kathawut Ketphot

Title: Security Manager

Acknowledged By: Mr. Kathawut Ketphot

Title: Security Manager

Date: 31/08/2022

*Dome Camera 69 Unit
*Out Doors Camera 22 Unit
Total 91 Unit



No.	NVR No.2		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
1	1	Lift No.5	G	/		/			/		/		
2	2	Service lift	G	/		/			/		/		
3	3	Hotel lift No.1	G	/		/			/		/		
4	4	Hotel lift No.2	G	/		/			/		/		
5	5	Residence lift	G		X			X		X		X	เปลี่ยนอุปกรณ์ Power Sample แล้วยังไม่ภาพ รอเปลี่ยนอุปกรณ์ LINK
6	6	Front lift No.5	G	/		/			/		/		
7	7	Car parking 1	B	/		/			/		/		
8	8	Car parking 2	B	/		/			/		/		
9	9	Inside edl 1	G	/		/			/		/		
10	10	Inside edl 2	G	/		/			/		/		
11	11	Inside edl 3	G	/		/			/		/		
12	12	Inside edl 4	G	/		/			/		/		
13	13	Entrance EDL	G	/		/			/		/		
14	14	Cupper	G	/		/			/		/		
15	15	Front Cupper	G	/		/			/		/		
16	16	In-front Building	G	/		/			/		/		
17	17	Toilet EDL	G	/		/			/		/		
18	18	Fountain	G	/		/			/		/		
19	19	Kitchen Room 1	G	/		/			/		/		
20	20	Kitchen Room 2	G	/		/			/		/		
21	21	Guest house 1	G	/		/			/		/		
22	22	Guest house 2	G	/		/			/		/		
23	23	Outdoor parking 1	G	/		/			/		/		
24	24	Outdoor parking 2	G	/		/			/		/		
25	25	In-out hotel	G	/		/			/		/		
26	26	Lily lift	G	/		/			/		/		
27	27	Lily 1	G	/		/			/		/		
28	28	Lily 2	2	/		/			/		/		
29	29	Back meeting	2	/		/			/		/		

The Park Nine Hotel Suvanabhumi

No	Floor	Location	Fire Extinguisher				Status		Fire Hose Cabinet								Remark	
			TYPE OF EXTINGUISHER				Normal	Abnormal	Cabinet	Safety Glass	Hose reel	Fire hose 2.5"	2 Nozzles	Axe	Valve	Cap & Chain		Signage
			Dry Chem	Co2	Form	BF2000			Status	Status	Status	Status	Status	Status	Status	Status		Cleanliness
Building A									Status	Status	Status	Status	Status	Status	Status	Status	Cleanliness	
1	B	Parking Building	1	-	-	-	/		/	/	/	/	/	/	/	/	/	
2	G	Front toilet EDL restaurant	1	-	-	-	/		/	/	/	/	/	/	/	/	/	
3	G	F&B store (EDL)	-	1	-	-	/											
4	G	Generator Room	1	-	-	-	/											
5	G	Front Kitchen Room	1	-	-	-	/											
6	G	Kitchen Room	-	-	2	-	/											
7	2	Electrical Room	1	-	-	-	/											
8	2	Front lift meeting	-	1	-	-	/		/	/	/	/	/	/	/	/	/	
Building B																		
9	B	Front of fire pump room	1	-	-	-	/		/	/	/	/	/	/	/	/	/	
10	B	Front of HK Store	1	-	-	-	/		/	/	/	/	/	/	/	/	/	
11	B	Fire staircase Hotel side	1	-	-	-	/		/	/	/	/	/	/	/	/	/	
12	G	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
13	G	Lobby Hotel	1	-	-	-	/		/	/	/	/	/	/	/	/	/	
14	G	Security Office	-	-	-	1	/											
15	G	Fire Cart Security	-	1	1	-	/											
16	G	Saver room	-	-	-	1	/											
17	G	Fire staircase Hotel	1	-	-	-	/											/
18	G	Corridor back office	-	-	-	1	/											
19	2	Fire staircase Resident	2	-	-	-	/											/
20	2	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
21	2	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
22	3	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
23	3	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
24	3	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
25	4	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
26	4	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
27	4	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
28	5	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
29	5	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
30	5	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
31	6	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
32	6	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	
33	6	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	

Equipment monthly checklist September 2022

No.	Equipment	Monthly	Check day	Check by
1	FHC Check	September	21/09/2022	Mr. Kathawut Ketphot
2	Emergency light		28/09/2022	Mr. Ronnarong Mechit
3	Fire exit signage		27/09/2022	Mr. Ronnarong Mechit
4	Fire exit staircase		30/09/2022	Mr. Samrit Kongtungmon
5	Fire Fighting checklist		30/09/2022	Mr. Wichai Chuearak
6	Rescue equipments		30/09/2022	Mr. Wichai Chuearak
7	Fire phone and jack		29/09/2022	Mr. Kathawut Ketphot
8	Elevator speaker phone		30/09/2022	Mr. Ronnarong Mechit
9	CCTV Checklist		30/09/2022	Mr. Wichai Chuearak

Acknowledge By: _____

(Mr. Chatree Nuiprasith)

Position: Group Resident Manager

Date: _____

Checked by: Security Staff

The Park Nine Hotel Suvarnabhumi

EMERGENCY LIGHT CHECKLIST

แบบฟอร์มตรวจเช็คไฟฉุกเฉินในโรงแรม

ตรวจเช็คโดย (INSPECTOR) Mr. Ronnarong Mechit

วันที่ (DAET) 28/09/2022

Floor	Location	Brand/ Model	Code	Quantity	Status		
					Function Lighting indicator		
					Lamp	AC	Battery Status
					Y/N	Y/N	
7	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-01	1	/	/	Normal
	Corridor resident #725 room		EM-02	1	/	/	Normal
	Hall lift Resident		EM-03	1	/	/	Normal
	Fire staircase st-7		EM-04	1	/	/	Normal
	Hall lift hotel		EM-05	1	/	/	Normal
	Corridor hotel #702 room		EM-06	1	/	/	Normal
	Corridor hotel #708 room		EM-07	1	/	/	Normal
	Fire staircase st-4 resident		EM-08	1	/	/	Normal
	Hall lift service		EM-09	1	/	X	Charge
	Network room		EM-10	1	/	X	Charge
	Electricity room		EM-11	1	/	X	Charge
6	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-12	1	/	/	Normal
	Corridor resident #625 room		EM-13	1	/	/	Normal
	Hall lift Resident		EM-14	1	X	/	Normal
	Fire staircase st-7		EM-15	1	/	/	Normal
	Hall lift hotel		EM-16	1	/	/	Normal
	Corridor hotel #502 room		EM-17	1	/	/	Normal
	Corridor hotel #508 room		EM-18	1	/	/	Normal
	Fire staircase st-4 resident		EM-19	1	/	/	Normal
	Hall lift service		EM-20	1	/	X	Charge
	Network room		EM-21	1	/	X	Charge
	Electricity room		EM-22	1	/	X	Charge

The Park Nine Hotel Suvarnabhumi

34	7	Fire staircase Resident	2	-	-	-	/	/	/	/	/	/	/	/	/	/	/
35	7	Hall lift Hotel	2	-	-	-	/	/	/	/	/	/	/	/	/	/	/
36	7	Fire staircase Hotel	2	-	-	-	/	/	/	/	/	/	/	/	/	/	/
Total		57	48	3	3	3											

Floor	Fire Blanket			Status	
	Location	Quantity		Yes	No
G	Kitchen	2		/	
	Fire Cart	1		/	
	TOTAL	3			

Reported by: Mr. Kathawut Ketphot

Position: Security Manager

Date: 21/09/2022

Acknowledge by: Mr. Kathawut Ketphot

Position: Security Manager

Date: 30/09/2022

The Park Nine Hotel Suvarnabhumi

2	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-56	1	/	/	Normal
	Corridor resident #225 room		EM-57	1	/	/	Normal
	Hall lift Resident		EM-58	1	/	/	Normal
	Fire staircase st-7		EM-59	1	/	/	Normal
	Hall lift hotel		EM-60	1	/	/	Normal
	Corridor hotel		EM-61	1	/	/	Normal
	Corridor hotel #208 room		EM-62	1	/	/	Normal
	Fire staircase st-4 resident		EM-63	1	/	/	Normal
	Hall lift service		EM-64	1	/	X	Charge
	Electricity room		EM-65	1	/	X	Charge
G	Fire staircase st-4 resident	Dyno/ Drs-5203	EM-66	1	/	X	Charge
	Fire staircase st-7		EM-67	1	/	/	Normal
B	Parking	Dyno/ Drs-5203	EM-68	1	/	/	Normal
	Fire staircase st-5		EM-69	1	/	X	Charge
	Fire staircase st-7		EM-70	1	/	/	Normal
	Hall toilet staff		EM-71	1	/	X	Charge
	Man toilet staff		EM-72	1	/	X	Charge
	Female toilet staff		EM-73	1	/	/	Normal
	Hall lift service		EM-74	1	/	X	Charge
	Saff canteen		EM-75	1	/	/	Normal

The Park Nine Hotel Suvarnabhumi

5	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-23	1	/	/	Normal
	Corridor resident #525 room		EM-24	1	/	/	Normal
	Hall lift Resident		EM-25	1	/	/	Normal
	Fire staircase st-7		EM-26	1	/	/	Normal
	Hall lift hotel		EM-27	1	/	/	Normal
	Corridor hotel #502 room		EM-28	1	/	/	Normal
	Corridor hotel #508 room		EM-29	1	/	/	Normal
	Fire staircase st-4 resident		EM-30	1	/	/	Normal
	Hall lift service		EM-31	1	/	X	Charge
	Network room		EM-32	1	/	X	Charge
4	Electricity room	Dyno/ Drs-5203	EM-33	1	/	X	Charge
	Fire staircase st-8 hotel		EM-34	1	/	/	Normal
	Corridor resident #425 room		EM-35	1	/	/	Normal
	Hall lift Resident		EM-36	1	/	/	Normal
	Fire staircase st-7		EM-37	1	/	/	Normal
	Hall lift hotel		EM-38	1	/	/	Normal
	Corridor hotel #402 room		EM-39	1	/	/	Normal
	Corridor hotel #408 room		EM-40	1	/	/	Normal
	Fire staircase st-4 resident		EM-41	1	/	/	Normal
	Hall lift service		EM-42	1	/	X	Charge
3	Network room	Dyno/ Drs-5203	EM-43	1	/	X	Charge
	Electricity room		EM-44	1	/	X	Charge
	Fire staircase st-8 hotel		EM-45	1	/	/	Normal
	Corridor resident #325 room		EM-46	1	/	/	Normal
	Hall lift Resident		EM-47	1	/	/	Normal
	Fire staircase st-7		EM-48	1	/	/	Normal
	Hall lift hotel		EM-49	1	/	/	Normal
	Corridor hotel #302 room		EM-50	1	/	/	Normal
	Corridor hotel #308 room		EM-51	1	/	/	Normal
	Fire staircase st-4 resident		EM-52	1	/	/	Normal
	Hall lift service	Dyno/ Drs-5203	EM-53	1	/	X	Charge
	Network room		EM-54	1	/	/	Normal
	Electricity room		EM-55	1	/	/	Normal

FIRE EXIT SIGNAGE CHECKLIST

แบบฟอร์มตรวจป้ายแจ้งทางออกหนีไฟในโรงแรม

ตรวจเช็คโดย (Inspector by) Mr. Ronnarong Mechit วันที่ (Date) 27/09/2022



Floor	Location	Code	Exit Signs Amount	Status	
				Working	Not Working
7	Fire staircase st-4 resident	EX-01	1	/	Normal
	Hall lift Resident	EX-02	1	/	Normal
	Front lift resident	EX-03	1	/	Normal
	Fire staircase st-7	EX-04	1	/	Normal
	Hall lift hotel	EX-05	1	/	Normal
6	Corridor hotel #702 room	EX-06	1	/	Normal
	Front fire staircase st-8 hotel	EX-07	1	/	Normal
	Fire staircase st-4 resident	EX-08	1	/	Normal
	Hall lift Resident	EX-09	1	/	Normal
	Front lift resident	EX-10	1	/	Normal
5	Fire staircase st-7	EX-11	1	/	Normal
	Hall lift hotel	EX-12	1	/	Normal
	Corridor hotel #602 room	EX-13	1	/	Normal
	Front fire staircase st-8 hotel	EX-14	1	/	Normal
	Fire staircase st-4 resident	EX-15	1	/	Normal
4	Hall lift Resident	EX-16	1	/	Normal
	Front lift resident	EX-17	1	/	Normal
	Fire staircase st-7	EX-18	1	/	Normal
	Hall lift hotel	EX-19	1	/	Normal
	Corridor hotel #502 room	EX-20	1	/	Normal
3	Front fire staircase st-8 hotel	EX-21	1	/	Normal
	Fire staircase st-4 resident	EX-22	1	/	Normal
	Hall lift Resident	EX-23	1	/	Normal
	Front lift resident	EX-24	1	/	Normal
	Fire staircase st-7	EX-25	1	/	Normal
2	Hall lift hotel	EX-26	1	/	Normal
	Corridor hotel #402 room	EX-27	1	/	Normal
	Front fire staircase st-8 hotel	EX-28	1	/	Normal
	Fire staircase st-4 resident	EX-29	1	/	Normal
	Hall lift Resident	EX-30	1	/	Normal
1	Front lift resident	EX-31	1	/	Normal
	Fire staircase st-7	EX-32	1	/	Normal
	Hall lift hotel	EX-33	1	/	Normal
	Corridor hotel #302 room	EX-34	1	/	Normal
	Front fire staircase st-8 hotel	EX-35	1	/	Normal
0	Fire staircase st-4 resident	EX-36	1	/	Normal
	Hall lift Resident	EX-37	1	/	Normal
	Front lift resident	EX-38	1	/	Normal
	Fire staircase st-7	EX-39	1	/	Normal
	Hall lift hotel	EX-40	1	/	Normal
-1	Corridor hotel	EX-41	1	/	Normal
	Front fire staircase st-8 hotel	EX-42	1	/	Normal

The Park Nine Hotel Suvarnabhumi

EMERGENCY LIGHT CHECKLIST

แบบฟอร์มตรวจเช็คไฟฉุกเฉินในโรงแรม (อาคาร A)

Floor	Location	Brand/ Model	Code	Quantity	Status		
					Function Lighting indicator		Battery Status
					Lamp Y/N	AC Y/N	
G	Kitchen #1 (Entrance and Exit)	Dyno/ Drs-5203	EM-76	1	/	/	Normal
	Kitchen #2		EM-77	1	/	/	Normal
B	Car parking 1	Dyno/ Drs-5203	EM-78	1	/	X	Charge
	Car parking 2		EM-79	1	/	/	Normal
	Front entrance		EM-80	1	/	/	Normal
	Front lift		EM-81	1	/	/	Normal
Total		81					

Remark: ✓ = Yes or working

X = No or not working

Battery Status = Normal, = Charge

Emergency light not working 23 points.

Floor	Location	Code	Exit Signs Amount	Working	Status
G	Front fire staircase st-8 hotel	EX-43	1	/	Normal
	Exit to parking	EX-44	1	/	Normal
B	Corridor no.01	EX-45	1	/	Normal
	Corridor no.02	EX-46	1	/	Normal
	Fire staircase st-7	EX-47	1	/	Normal
Total			47		

Reported by: Mr. Romarong Mechit








Position: Security Officer







FIRE FIGHTING EQUIPMENT CHECKLIST

แบบตรวจเช็คอุปกรณ์ดับเพลิง ในโรงแรม

วันที่ (DATE) 30/09/2022

ตรวจเช็คโดย (Inspector By) Mr. Wichai Chuearak





No.	Equipment	Amount	Actual	Picture	Condition		REMARK
					Yes	No	
1	Fire suite	3	3		/		
2	Helmet	3	3		/		
3	Leather Glove	3	3		/		
4	Safety Mask	3	3		/		
5	Hood	3	3		/		
6	Safety Glasses	3	3		/		
7	Boot	3	3		/		

8	Fire Blanket	1	1		/		
9	Nozzles (Protek Model 366)	1	1		/		
10	Fire Hose 2.5"	2	2		/		
11	Fire Phone	1	1		/		
12	Cradle	1	1		/		
13	Megaphone	1	1		/		

Reported By: Mr. Wichai Chuearak

Position: Security Officer

RESCUE EQUIPMENT CHECKLIST
แบบฟอร์มตรวจสอบอุปกรณ์กู้ภัยและช่วยเหลือผู้ประสบเหตุ
ตรวจสอบโดย (Inspector By) Mr. Wichai Chuearak วันที่ (Date) 30/09/2022

No.	Details Equipment	Amount	Actual	Picture	Status		Remark
					Yes	No	
1	Body Rescue Hook	1	1		/		
2	Ring Buoy	2	2		/		
3	AMBU bag size 500 ml	1	1		/		
4	AMBU bag size 250 ml	1	1		/		

Reported By: Mr. Wichai Chuearak Acknowledge By: Mr. Kathawat Kenhot

Position: Security Officer

FIRE EXIT STAIRCASE CHECKLIST

แบบตรวจเช็คสภาพภายในบันไดหนีไฟและบานประตูหนีไฟของ โรงแรม

ตรวจเช็คโดย (Inspect by): Mr. Samrit Kongtungmon

วันที่ (Date): 30/09/2022

Floor	Location	สิ่งกีดขวาง Obstructions		หลอดไฟส่องสว่าง Neon Lighting		ประตูทางหนีไฟ Fire Exit Door		คานเหล็ก Panic Bar		ก้านตั้งประตู Self Closer		หมายเหตุ Remark
		Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
Rooftop	Fire staircase st-7	/		/		/		/		/		
7	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
6	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
5	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
4	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
3	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
2	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
G	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
B	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-5 FO Office	/		/		/		/		/		

Reported by : Mr. Samrit Kongtungmon

Position: Sr. Security Officer

Acknowledge by: Mr. Kathawut Ketphot

Position: Security Manager

The Park Nine Hotel Suvarnabhumi

FIRE PHONE OPERATION CHECKLIST

แบบตรวจเช็คอุปกรณ์โทรศัพท์ฉุกเฉินที่ติดตั้งในโรงแรม

ตรวจเช็คโดย (Checked By): Mr. Kathawut Ketphot

วันที่ (Date): 29/09/2022

Item No. ลำดับที่	Floor ชั้น	Description/Location รายละเอียด/สถานที่ตั้ง	Fire Phone Functional Checklist				Remark หมายเหตุ
			Quantity จำนวน	Obvious เสียงดังชัดเจน	Function correct ทำงานถูกต้อง	Fire jack สภาพดีเสียบ	
1	7	Fire staircase st-8 resident	1	/	/	/	
2		Fire staircase st-7	1	/	/	/	
3		Hall lift serviced	1	/	/	/	
4		Front fire staircase st-4 hotel	1	/	/	/	
5	6	Fire staircase st-8 resident	1	/	/	/	
6		Fire staircase st-7	1	/	/	/	
7		Hall lift serviced	1	/	/	/	
8		Front fire staircase st-4 hotel	1	/	/	/	
9	5	Fire staircase st-8 resident	1	/	/	/	
10		Fire staircase st-7	1	/	/	/	
11		Hall lift serviced	1	/	/	/	
12		Front fire staircase st-4 hotel	1	/	/	/	
13	4	Fire staircase st-8 resident	1	/	/	/	
14		Fire staircase st-7	1	/	/	/	
15		Hall lift serviced	1	/	/	/	
16		Front fire staircase st-4 hotel	1	/	/	/	
17	3	Fire staircase st-8 resident	1	/	/	/	
18		Fire staircase st-7	1	/	/	/	
19		Hall lift serviced	1	/	/	/	
20		Front fire staircase st-4 hotel	1	/	/	/	
21	2	Fire staircase st-8 resident	1	/	/	/	
22		Fire staircase st-7	1	/	/	/	
23		Hall lift serviced	1	/	/	/	
24		Front fire staircase st-4 hotel	1	/	/	/	
25	G	Fire staircase st-7	1	/	/	/	
26		Hall lift serviced	1	/	/	/	
27	B	Fire staircase st-7	1	/	/	/	
28		Hall lift serviced	1	/	/	/	

Reported By: Mr. Kathawut Ketphot

Position: Security Manager

CCTV CHECKLIST

แบบตรวจเช็คการทำงานของระบบกล้องวงจรปิดใน โรงแรม

ตรวจเช็คโดย (Inspector By) Mr. Wichai Chuearak

วันที่ (Date) 30/09/2022

เวลา (Time) 01.35 PM.

No.	NVR No.1		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
1	1	Carpark in-out	B	/		/			/		/		
2	2	Car park 1	B	/		/			/		/		
3	3	Car park 2	B	x		x			x		x		สายไม่มีสัญญาณ
4	4	Staff canteen	B	/		/			/		/		
5	5	Staff toilet	B	/		/			/		/		
6	6	HK Office	B	/		/			/		/		
7	7	FO counte	G	/		/			/		/		
8	8	FO lift	G	/		/			/		/		
9	9	HR Office	G	/		/			/		/		
10	10	Back Office	G	/		/			/		/		
11	11	Lobby loun	G	/		/			/		/		
12	12	Entrance lobby	G	/		/			/		/		
13	13	Front F&B Office	G	/		/			/		/		
14	14	AC store	G	/		/			/		/		
15	15	Front security office	G	/		/			/		/		
16	16	Bell store	G	/		/			/		/		
17	17	FO office	G	/		/			/		/		
18	18	Fitness room	G	/		/			/		/		
19	19	Outdoor 1	G	/		/			/		/		
20	20	Outdoor 2	G	x		x			x		x		สายไม่มีสัญญาณ
21	21	Outdoor 3	G	/		/			/		/		
22	22	In out kitchen	G	/		/			/		/		
23	23	Swimming pool	G	/		/			/		/		
24	24	Receiving Aaea	G	/		/			/		/		
25	25	Out door lobby	G	/		/			/		/		
26	26	Garbags room	G	/		/			/		/		
27	27	Residence front lift	2	/		/			/		/		
28	28	Staircase St-7	2	/		/			/		/		
29	29	Hotel lift	2	/		/			/		/		
30	30	Hotel 1	2	/		/			/		/		

The Park Nine Hotel Suvarnabhumi

Date: 28/09/2022

No.	DESCRIPTION/LOCATION	ELEVATOR EMERGENCY SPEAKER PHONE CHECK LIST								REMARK/COMMENT	
		Quantity	Location at Display On Emergency Phone		Obvious Control Room		Obvious In an Elevator		Obvious Operator Room		
ลำดับที่	คำอธิบาย/สถานที่ติดตั้ง		จำนวน	แสดงสถานที่ ตรงกับโทรศัพท์ฉุกเฉิน		เสียงส่งชัดเจน ห้องคอลโทรล		เสียงส่งชัดเจน ในลิฟต์		เสียงส่งชัดเจน Operator room	
		YES		NO	YES	NO	YES	NO	YES	NO	
1	Emergency Speaker Guest Lift L-1	1	/		/		/		/		
2	Emergency Speaker Guest Lift L-2	1	/		/		/		/		
3	Emergency Speaker Guest Lift L-3	1	/		/		/		/		
4	Emergency Speaker Serviced Lift L-4	1	/		/		/		/		
5	Emergency Speaker Guest Lift L-5 (A building)	No Finished									
6	Emergency Speaker Service Lift L-6 (A building)	1	/		/		/		/		

Checked by: Mr. Ronnarong Mechit

Position: Security Officer

No.	NVR No.2		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
1	1	Lift No.5	G	/		/			/		/		
2	2	Service lift	G	/		/			/		/		
3	3	Hotel lift No.1	G	/		/			/		/		
4	4	Hotel lift No.2	G	/		/			/		/		
5	5	Residence lift	G		X					X		X	รอเปลี่ยนอุปกรณ์ LINK สัญญาณภาพ
6	6	Front lift No.5	G	/		/			/		/		
7	7	Car parking 1	B	/		/			/		/		
8	8	Car parking 2	B	/		/			/		/		
9	9	Inside edl 1	G	/		/			/		/		
10	10	Inside edl 2	G	/		/			/		/		
11	11	Inside edl 3	G	/		/			/		/		
12	12	Inside edl 4	G	/		/			/		/		
13	13	Entrance EDL	G	/		/			/		/		
14	14	Cupper	G	/		/			/		/		
15	15	Front Cupper	G	/		/			/		/		
16	16	In-front Building	G		X					X		X	สายไม่มีสัญญาณ
17	17	Toilet EDL	G	/		/			/		/		
18	18	Fountain	G		X					X		X	สายไม่มีสัญญาณ
19	19	Kitchen Room 1	G	/		/			/		/		
20	20	Kitchen Room 2	G	/		/			/		/		
21	21	Guest house 1	G	/		/			/		/		
22	22	Guest house 2	G	/		/			/		/		
23	23	Outdoor parking 1	G	/		/			/		/		
24	24	Outdoor parking 2	G	/		/			/		/		
25	25	In-out hotel	G	/		/			/		/		
26	26	Lily lift	G	/		/			/		/		
27	27	Lily 1	G	/		/			/		/		
28	28	Lily 2	2	/		/			/		/		
29	29	Back meeting	2	/		/			/		/		

No.	NVR No.1		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
31	31	Hotel 2	2	/		/			/		/		
32	32	Residence 2	2	/		/			/		/		
33	30	Residence front lift	3	/		/			/		/		
34	31	Staircase St-7	3	/		/			/		/		
35	32	Hotel lift	3	/		/			/		/		
36	33	Hotel 1	3	/		/			/		/		
37	34	Hotel 2	3	/		/			/		/		
38	35	Residence 2	3	/		/			/		/		
39	36	Residence front lift	4	/		/			/		/		
40	37	Staircase St-7	4	/		/			/		/		
41	38	Hotel lift	4	/		/			/		/		
42	39	Hotel 1	4	/		/			/		/		
43	40	Hotel 2	4	/		/			/		/		
44	41	Residence 2	4	/		/			/		/		
45	42	Residence front lift	5	/		/			/		/		
46	43	Staircase St-7	5	/		/			/		/		
47	44	Hotel lift	5	/		/			/		/		
48	45	Hotel 1	5	/		/			/		/		
49	46	Hotel 2	5	/		/			/		/		
50	47	Residence 2	5	/		/			/		/		
51	48	Residence front lift	6	/		/			/		/		
52	49	Staircase St-7	6	/		/			/		/		
53	50	Hotel lift	6	/		/			/		/		
54	51	Hotel 1	6	/		/			/		/		
55	52	Hotel 2	6	/		/			/		/		
56	53	Residence 2	6	/		/			/		/		
57	54	Residence front lift	7	/		/			/		/		
58	55	Staircase St-7	7	/		/			/		/		
59	56	Hotel lift	7	/		/			/		/		
60	57	Hotel 1	7	/		/			/		/		
61	58	Hotel 2	7	/		/			/		/		
62	59	Residence 2	7	/		/			/		/		

Equipment monthly checklist October 2022

No.	Equipment	Monthly	Check day	Check by
1	FHC Check	October	21/10/2022	Mr. Wichai Chuearak
2	Emergency light		20/10/2022	Mr. Samrit Kongtungmon
3	Fire exit signage		28/10/2022	Mr. Sophon Saenmanee
4	Fire exit staircase		28/10/2022	Mr. Sophon Saenmanee
5	Fire Fighting checklist		31/10/2022	Mr. Ronnarong Mechit
6	Rescue equipments		31/10/2022	Mr. Ronnarong Mechit
7	Fire phone and jack		30/10/2022	Mr. Kathawut Ketphot
8	Elevator speaker phone		30/10/2022	Mr. Sophon Saenmanee
9	CCTV Checklist		31/10/2022	Mr. Wichai Chuearak

Acknowledge By: _____
(Mr. Chatree Nuiprasith)

Position: Group Resident Manager

Date: _____



NVR No.	Period Time Record	Total/Day
PRN-4011 (172.20.0.2:8001)	26/08/22-30/09/22	36 Day
NVR (172.20.3.554)	26/08/22-30/09/22	36 Day
NVR03 (172.20.0.4:554)	11/08/22-30/09/22	51 Day

*Dome Camera 69 Unit
*Out Doors Camera 22 Unit
Total 91 Unit

Reported by: Mr. Wichai Chuearak
Title: Security Officer



The Park Nine Hotel Suvanabhumi

34	7	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/
35	7	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/
36	7	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/
Total			57	48	3	3	3											

Floor	Fire Blanket			
	Location	Quantity	Status	
			Yes	No
G	Kitchen	2	/	
	Fire Cart	1	/	
	TOTAL	3		

Reported by: Mr. Wichai Chuearak

Position: Security Officer

Date: 21/10/2022

Acknowledge by: Mr. Kathawut Ketphot

Position: Security Manager

Date: 31/10/2022



The Park Nine Hotel Suvanabhumi

No	Floor	Location	Fire Extingguisher				Status		Fire Hose Cabinet									Remark	
			TYPE OF EXTINGUISHER				Normal	Abnormal	Cabinet	Safety Glass	Hose reel	Fire hose 2.5"	2 Nozzles	Axe	Valve	Cap & Chain	Signage		
			Dry Chem	Co2	Form	BF2000			Status	Status	Status	Status	Status	Status	Status	Status	Cleanliness		
Building A																			
1	B	Parking Building	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
2	G	Front toilet EDL restaurant	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
3	G	F&B store (EDL)	-	1	-	-	/												
4	G	Generator Room	1	-	-	-	/												
5	G	Front Kitchen Room	1	-	-	-	/												
6	G	Kitchen Room	-	-	2	-	/												
7	2	Electrical Room	1	-	-	-	/												
8	2	Front lift meeting	-	1	-	-	/		/	/	/	/	/	/	/	/	/	/	
Building B																			
9	B	Front of fire pump room	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
10	B	Front of IIR Store	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
11	B	Fire staircase Hotel side	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
12	G	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
13	G	Lobby Hotel	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
14	G	Security Office	-	-	-	1	/												
15	G	Fire Cart Security	-	1	1	-	/												
16	G	Saver room	-	-	-	1	/												
17	G	Fire staircase Hotel	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
18	G	Coridor back office	-	-	-	1	/												
19	2	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
20	2	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
21	2	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
22	3	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
23	3	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
24	3	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
25	4	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
26	4	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
27	4	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
28	5	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
29	5	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
30	5	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
31	6	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
32	6	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
33	6	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	



The Park Nine Hotel Suvarnabhumi

5	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-23	1	/	/	Normal
	Corridor resident #525 room		EM-24	1	/	/	Normal
	Hall lift Resident		EM-25	1	/	/	Normal
	Fire staircase st-7		EM-26	1	/	/	Normal
	Hall lift hotel		EM-27	1	/	/	Normal
	Corridor hotel #502 room		EM-28	1	/	/	Normal
	Corridor hotel #508 room		EM-29	1	/	/	Normal
	Fire staircase st-4 resident		EM-30	1	/	/	Normal
	Hall lift service		EM-31	1	/	X	Charge
	Network room		EM-32	1	/	X	Charge
4	Electricity room	Dyno/ Drs-5203	EM-33	1	/	X	Charge
	Fire staircase st-8 hotel		EM-34	1	/	/	Normal
	Corridor resident #425 room		EM-35	1	/	/	Normal
	Hall lift Resident		EM-36	1	/	/	Normal
	Fire staircase st-7		EM-37	1	/	/	Normal
	Hall lift hotel		EM-38	1	/	/	Normal
	Corridor hotel #402 room		EM-39	1	/	/	Normal
	Corridor hotel #408 room		EM-40	1	/	/	Normal
	Fire staircase st-4 resident		EM-41	1	/	/	Normal
	Hall lift service		EM-42	1	/	X	Charge
3	Network room	Dyno/ Drs-5203	EM-43	1	/	X	Charge
	Electricity room		EM-44	1	/	X	Charge
	Fire staircase st-8 hotel		EM-45	1	/	/	Normal
	Corridor resident #325 room		EM-46	1	/	/	Normal
	Hall lift Resident		EM-47	1	/	/	Normal
	Fire staircase st-7		EM-48	1	/	/	Normal
	Hall lift hotel		EM-49	1	/	/	Normal
	Corridor hotel #302 room		EM-50	1	/	/	Normal
	Corridor hotel #308 room		EM-51	1	/	/	Normal
	Fire staircase st-4 resident		EM-52	1	/	/	Normal
	Hall lift service	Dyno/ Drs-5203	EM-53	1	/	X	Charge
	Network room		EM-54	1	/	X	Charge
	Electricity room		EM-55	1	/	X	Charge

The Park Nine Hotel Suvarnabhumi



EMERGENCY LIGHT CHECKLIST

แบบฟอร์มตรวจเช็คไฟฉุกเฉินในโรงแรม

ตรวจเช็คโดย (INSPECTOR) Mr. Samrit Kongtongmon

วันที่ (DAET) 20/10/2022

Floor	Location	Brand/ Model	Code	Quantity	Status		
					Function Lighting indicator		
					Lamp Y/N	AC Y/N	Battery Status
7	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-01	1	/	/	Normal
	Corridor resident #725 room		EM-02	1	/	/	Normal
	Hall lift Resident		EM-03	1	/	/	Normal
	Fire staircase st-7		EM-04	1	/	/	Normal
	Hall lift hotel		EM-05	1	/	/	Normal
	Corridor hotel #702 room		EM-06	1	/	/	Normal
	Corridor hotel #708 room		EM-07	1	/	/	Normal
	Fire staircase st-4 resident		EM-08	1	/	/	Normal
	Hall lift service		EM-09	1	/	X	Charge
	Network room		EM-10	1	/	X	Charge
6	Electricity room	Dyno/ Drs-5203	EM-11	1	/	X	Charge
	Fire staircase st-8 hotel		EM-12	1	/	/	Normal
	Corridor resident #625 room		EM-13	1	/	/	Normal
	Hall lift Resident		EM-14	1	/	/	Normal
	Fire staircase st-7		EM-15	1	/	/	Normal
	Hall lift hotel		EM-16	1	/	/	Normal
	Corridor hotel #602 room		EM-17	1	/	/	Normal
	Corridor hotel #608 room		EM-18	1	/	/	Normal
	Fire staircase st-4 resident		EM-19	1	/	/	Normal
	Hall lift service		EM-20	1	/	X	Charge
	Network room	Dyno/ Drs-5203	EM-21	1	/	X	Charge
	Electricity room		EM-22	1	/	X	Charge

The Park Nine Hotel Suvarnabhumi

EMERGENCY LIGHT CHECKLIST

แบบฟอร์มตรวจเช็คไฟฉุกเฉินในโรงแรม (อาคาร A)



Floor	Location	Brand/ Model	Code	Quantity	Status		
					Function Lighting Indicator		
					Lamp	AC	Battery Status
					Y/N	Y/N	
G	Kitchen #1 (Entrance and Exit)	Dyno/ Drs-5203	EM-76	1	/	/	Normal
	Kitchen #2		EM-77	1	/	/	Normal
B	Car parking 1	Dyno/ Drs-5203	EM-78	1	/	X	Charge
	Car parking 2		EM-79	1	/	/	Normal
	Front entrance		EM-80	1	/	/	Normal
	Front lift		EM-81	1	/	/	Normal
Total		81					

Remark: ✓ = Yes or working

x = No or not working

Battery Status = Normal, = Charge

Emergency light not working 23 points.

Reported by: Mr. Samrit Kongtungmon

Position: Sr. Security Officer


Acknowledge by: Mr. Kathawut Ketphot Daet: 31/10/2022

Position: Security Manager



The Park Nine Hotel Suvarnabhumi

2	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-56	1	/	/	Normal
	Corridor resident #225 room		EM-57	1	/	/	Normal
	Hall lift Resident		EM-58	1	/	/	Normal
	Fire staircase st-7		EM-59	1	/	/	Normal
	Hall lift hotel		EM-60	1	/	/	Normal
	Corridor hotel		EM-61	1	/	/	Normal
	Corridor hotel #208 room		EM-62	1	/	/	Normal
	Fire staircase st-4 resident		EM-63	1	/	/	Normal
	Hall lift service		EM-64	1	/	X	Charge
	Electricity room		EM-65	1	/	X	Charge
G	Fire staircase st-4 resident	Dyno/ Drs-5203	EM-66	1	/	X	Charge
	Fire staircase st-7		EM-67	1	/	/	Normal
B	Parking	Dyno/ Drs-5203	EM-68	1	/	/	Normal
	Fire staircase st-5		EM-69	1	/	X	Charge
	Fire staircase st-7		EM-70	1	/	/	Normal
	Hall toilet staff		EM-71	1	/	X	Charge
	Man toilet staff		EM-72	1	/	X	Charge
	Female toilet staff		EM-73	1	/	/	Normal
	Hall lift service		EM-74	1	/	/	Normal
	Saff canteen		EM-75	1	/	/	Normal



FIRE EXIT SIGNAGE CHECKLIST

แบบฟอร์มตรวจป้ายทางออกหนีไฟในโรงแรม

ตรวจ/ติดตั้ง (Inspector by) Mr. Sophon Saenmaanee วันที่ (Date) 28/10/2022

Floor	Location	Code	Exit Signs		Status	
			Amount	Working	Working	Not Working
7	Fire staircase st-4 resident	EX-01	1	/		Normal
	Hall lift Resident	EX-02	1	/		Normal
	Front lift Resident	EX-03	1	/		Normal
	Fire staircase st-7	EX-04	1	/		Normal
	Hall lift hotel	EX-05	1	/		Normal
	Corridor hotel #702 room	EX-06	1	/		Normal
6	Front fire staircase st-8 hotel	EX-07	1	/		Normal
	Fire staircase st-4 resident	EX-08	1	/		Normal
	Hall lift Resident	EX-09	1	/		Normal
	Front lift Resident	EX-10	1	/		Normal
	Fire staircase st-7	EX-11	1	/		Normal
	Hall lift hotel	EX-12	1	/		Normal
5	Corridor hotel #602 room	EX-13	1	/		Normal
	Front fire staircase st-8 hotel	EX-14	1	/		Normal
	Fire staircase st-4 resident	EX-15	1	/		Normal
	Hall lift Resident	EX-16	1	/		Normal
	Front lift Resident	EX-17	1	/		Normal
	Fire staircase st-7	EX-18	1	/		Normal
4	Hall lift hotel	EX-19	1	/		Normal
	Corridor hotel #502 room	EX-20	1	/		Normal
	Front fire staircase st-8 hotel	EX-21	1	/		Normal
	Fire staircase st-4 resident	EX-22	1	/		Normal
	Hall lift Resident	EX-23	1	/		Normal
	Front lift Resident	EX-24	1	/		Normal
3	Fire staircase st-7	EX-25	1	/		Normal
	Hall lift hotel	EX-26	1	/		Normal
	Corridor hotel #402 room	EX-27	1	/		Normal
	Front fire staircase st-8 hotel	EX-28	1	/		Normal
	Fire staircase st-4 resident	EX-29	1	/		Normal
	Hall lift Resident	EX-30	1	/		Normal
2	Front lift Resident	EX-31	1	/		Normal
	Fire staircase st-7	EX-32	1	/		Normal
	Hall lift hotel	EX-33	1	/		Normal
	Corridor hotel #302 room	EX-34	1	/		Normal
	Front fire staircase st-8 hotel	EX-35	1	/		Normal
	Fire staircase st-4 resident	EX-36	1	/		Normal
	Hall lift Resident	EX-37	1	/		Normal
	Front lift Resident	EX-38	1	/		Normal
	Fire staircase st-7	EX-39	1	/		Normal
	Hall lift hotel	EX-40	1	/		Normal
	Corridor hotel	EX-41				
	Front fire staircase st-8 hotel	EX-42				

FIRE EXIT SI

แบบฟอร์มตรวจป้ายทางออกหนีไฟในโรงแรม

Floor	Location	Code	Exit Signs		Status	
			Amount	Working	Working	Not Working
G	Front fire staircase st-8 hotel	EX-43	1	/		Normal
B	Exit to parking	EX-44	1	/		Normal
	Corridor no.01	EX-45	1	/		Normal
	Corridor no.02	EX-46	1	/		Normal
	Fire staircase st-7	EX-47	1	/		Normal
Total	47					

Reported by: Mr. Sophon Saenmaanee

Position: Supervisor Security








Acknowledge by: Mr. Kathawut Kephoh

Position: Security Manager

The Park Nine Hotel Suvarnabhumi

FIRE FIGHTING EQUIPMENT CHECKLIST

แบบตรวจเช็คอุปกรณ์เพลิง ในโรงแรม
 ตรวจเช็คโดย (Inspector By) Mr. Rannarong Mechit วันที่ (DATE) 30/10/2022

No.	Equipment	Amount	Actual	Picture	Condition		REMARK
					Yes	No	
1	Fire suite	3	3		/		
2	Helmet	3	3		/		
3	Leather Glove	3	3		/		
4	Safety Mask	3	3		/		
5	Hood	3	3		/		
6	Safety Glasses	3	3		/		
7	Boot	3	3		/		

FIRE EXIT STAIRCASE CHECKLIST

แบบตรวจเช็คสภาพภายในบันไดหนีไฟและบ้านประตุนีไฟของ โรงแรม







ตรวจเช็คโดย (Inspect by): Mr. Sophon Saenmanee

วันที่ (Date): 28/10/2022

Floor	Location	สิ่งกีดขวาง		หลอดไฟส่องสว่าง		ประตูทางหนีไฟ		คานเหล็ก		ก้านดึงประตู		หมายเหตุ
		Obstructions		Neon Lighting		Fire Exit Door		Panic Bar		Self Closer		
		Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
Rooftop	Fire staircase st-7	/		/		/		/		/		
7	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
6	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
5	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
4	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
3	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
2	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
G	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
B	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-5 FO Office	/		/		/		/		/		

Reported by : Mr. Sophon Saenmanee
 Position: Security Supervisor

Acknowledge by: Mr. Kathawut Ketphot
 Position: Security Manager

8	Fire Blanket	1	1		/	
9	Nozzles (Protek Model 366)	1	1		/	
10	Fire Hose 2.5"	2	2		/	
11	Fire Phone	1	1		/	
12	Cradle	1	1		/	
13	Megaphone	1	1		/	





Reported By: Mr. Ronnarong Mechit Acknowledge By: Mr. Kathawut Kelphot
 Position: Security Officer Position: Security Manager




RESCUE EQUIPMENT CHECKLIST

แบบฟอร์มตรวจสอบอุปกรณ์กู้ภัยตามจุดตรวจในโรงแรม

ตรวจโดย (Inspector By) Mr. Ronnarong Mechit วันที่ (Date) 30/10/2022

No.	Details Equipment	Amount	Actual	Picture	Status		Remark
					Yes	No	
1	Body Rescue Hook	1	1		/		
2	Ring Buoy	2	2		/		
3	AMBU bag size 500 ml	1	1		/		
4	AMBU bag size 250 ml	1	1		/		

Reported By: Mr. Ronnarong Mechit Acknowledge By: Mr. Kathawut Kelphot
 Position: Security Officer Position: Security Manager



The Park Nine Hotel Suvarnabhumi

Date: 30/10/2022

No.	DESCRIPTION/LOCATION	ELEVATOR EMERGENCY SPEAKER PHONE CHECK LIST								REMARK/COMMENT	
		Quantity	Location at Display On Emergency Phone		Obvious Control Room		Obvious In an Elevator		Obvious Operator Room		
	คำอธิบาย/สถานที่ติดตั้ง		จำนวน	แสดงสถานที่ ตรงกับโทรศัพท์ฉุกเฉิน		เสียงส่งชัดเจน ห้องคอลโทรล		เสียงส่งชัดเจน ในลิฟต์		เสียงส่งชัดเจน Operator room	
ลำดับที่	YES	NO		YES	NO	YES	NO	YES	NO		
1	Emergency Speaker Guest Lift L-1	1	/		/		/		/		
2	Emergency Speaker Guest Lift L-2	1	/		/		/		/		
3	Emergency Speaker Guest Lift L-3	1	/		/		/		/		
4	Emergency Speaker Serviced Lift L-4	1	/		/		/		/		
5	Emergency Speaker Guest Lift L-5 (A building)	No Finished									
6	Emergency Speaker Service Lift L-6 (A building)	1	/		/		/		/		ระบบ Intercom เสียงเบา

Checked by: Mr. Sophon Saenmanee

Acknowledged By: Mr. Kathawut Ketphot

Position: Security Supervisor

Title: Security Manager

Date: 31/10/2022

The Park Nine Hotel Suvarnabhumi

FIRE PHONE OPERATION CHECKLIST

แบบตรวจเช็คอุปกรณ์โทรศัพท์ฉุกเฉินที่ดับเพลิงโรงแรม

ตรวจเช็คโดย (Checked By): Mr.Kathawut Ketphot

วันที่ (Date): 30/10/2022

Item No.	Floor	Description/Location	Fire Phone Functional Checklist				Remark
			Quantity	Obvious	Function correct	Fire jack	
ลำดับที่	ชั้น	รายละเอียด/สถานที่ตั้ง	จำนวน	เสียงส่งชัดเจน	ทำงานถูกต้อง	สภาพเคเบิล	หมายเหตุ
1	7	Fire staircase st-8 resident	1	/	/	/	
2		Fire staircase st-7	1	/	/	/	
3		Hall lift serviced	1	/	/	/	
4		Front fire staircase st-4 hotel	1	/	/	/	
5	6	Fire staircase st-8 resident	1	/	/	/	
6		Fire staircase st-7	1	/	/	/	
7		Hall lift serviced	1	/	/	/	
8		Front fire staircase st-4 hotel	1	/	/	/	
9	5	Fire staircase st-8 resident	1	/	/	/	
10		Fire staircase st-7	1	/	/	/	
11		Hall lift serviced	1	/	/	/	
12		Front fire staircase st-4 hotel	1	/	/	/	
13	4	Fire staircase st-8 resident	1	/	/	/	
14		Fire staircase st-7	1	/	/	/	
15		Hall lift serviced	1	/	/	/	
16		Front fire staircase st-4 hotel	1	/	/	/	
17	3	Fire staircase st-8 resident	1	/	/	/	
18		Fire staircase st-7	1	/	/	/	
19		Hall lift serviced	1	/	/	/	
20		Front fire staircase st-4 hotel	1	/	/	/	
21	2	Fire staircase st-8 resident	1	/	/	/	
22		Fire staircase st-7	1	/	/	/	
23		Hall lift serviced	1	/	/	/	
24		Front fire staircase st-4 hotel	1	/	/	/	
25	G	Fire staircase st-7	1	/	/	/	
26		Hall lift serviced	1	/	/	/	
27	B	Fire staircase st-7	1	/	/	/	
28		Hall lift serviced	1	/	/	/	

Reported By: Mr.Kathawut Ketphot

Position: Security Manager

No.	NVR No.1		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
31	31	Hotel 2	2	/		/			/		/		
32	32	Residence 2	2	/		/			/		/		
33	30	Residence front lift	3	/		/			/		/		
34	31	Staircase St-7	3	/		/			/		/		
35	32	Hotel lift	3	/		/			/		/		
36	33	Hotel 1	3	/		/			/		/		
37	34	Hotel 2	3	/		/			/		/		
38	35	Residence 2	3	/		/			/		/		
39	36	Residence front lift	4	/		/			/		/		
40	37	Staircase St-7	4	/		/			/		/		
41	38	Hotel lift	4	/		/			/		/		
42	39	Hotel 1	4	/		/			/		/		
43	40	Hotel 2	4	/		/			/		/		
44	41	Residence 2	4	/		/			/		/		
45	42	Residence front lift	5	/		/			/		/		
46	43	Staircase St-7	5	/		/			/		/		
47	44	Hotel lift	5	/		/			/		/		
48	45	Hotel 1	5	/		/			/		/		
49	46	Hotel 2	5	/		/			/		/		
50	47	Residence 2	5	/		/			/		/		
51	48	Residence front lift	6	/		/			/		/		
52	49	Staircase St-7	6	/		/			/		/		
53	50	Hotel lift	6	/		/			/		/		
54	51	Hotel 1	6	/		/			/		/		
55	52	Hotel 2	6	/		/			/		/		
56	53	Residence 2	6	/		/			/		/		
57	54	Residence front lift	7	/		/			/		/		
58	55	Staircase St-7	7	/		/			/		/		
59	56	Hotel lift	7	/		/			/		/		
60	57	Hotel 1	7	/		/			/		/		
61	58	Hotel 2	7	/		/			/		/		
62	59	Residence 2	7	/		/			/		/		

CCTV CHECKLIST

แบบตรวจเช็คการทำงานของระบบกล้องวงจรปิดใน โรงแรม

ตรวจเช็คโดย (Inspector By) Mr. Ronnarong Mechit

วันที่ (Date) 31/10/2022

เวลา (Time) 11:00 PM

No.	NVR No.1		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
1	1	Carpark in-out	B	/		/			/		/		
2	2	Car park 1	B	/		/			/		/		
3	3	Car park 2	B	x		x			/		x		สายไม่มีสัญญาณ
4	4	Staff canteen	B	/		/			/		/		
5	5	Staff toilet	B	/		/			/		/		
6	6	HK Office	B	/		/			/		/		
7	7	FO counte	G	/		/			/		/		
8	8	FO lift	G	/		/			/		/		
9	9	HR Office	G	/		/			/		/		
10	10	Back Office	G	/		/			/		/		
11	11	Lobby loun	G	/		/			/		/		
12	12	Entrance lobby	G	/		/			/		/		
13	13	Front F&B Office	G	/		/			/		/		
14	14	AC store	G	/		/			/		/		
15	15	Front security office	G	/		/			/		/		
16	16	Bell store	G	/		/			/		/		
17	17	FO office	G	/		/			/		/		
18	18	Fitness room	G	/		/			/		/		
19	19	Outdoor 1	G	/		/			/		/		
20	20	Outdoor 2	G	x		x			/		x		สายไม่มีสัญญาณ
21	21	Outdoor 3	G	/		/			/		/		
22	22	In out kitchen	G	/		/			/		/		
23	23	Swimming pool	G	/		/			/		/		
24	24	Receiving Aaea	G	/		/			/		/		
25	25	Out door lobby	G	/		/			/		/		
26	26	Garbags room	G	/		/			/		/		
27	27	Residence front lift	2	/		/			/		/		
28	28	Staircase St-7	2	/		/			/		/		
29	29	Hotel lift	2	/		/			/		/		
30	30	Hotel 1	2	/		/			/		/		

NVR No.	Period Time Record	Total/Day
PRN-4011 (172.20.0.2:8001)	29/09/22-31/10/22	33 Day
NVR (172.20.3.554)	28/09/22-31/10/22	34 Day
NVR03 (172.20.0.4:554)	11/09/22-31/09/22	51 Day

Reported by: Mr. Ronnarong Mechit

Title: Security Officer

Acknowledged By: Mr. Kathawut Ketphot

Title: Security Manager

*Dome Camera 69 Unit
*Out Doors Camera 22 Unit
Total 91 Unit

No.	NVR No.2		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
1	1	Lift No.5	G	/		/			/		/		
2	2	Service lift	G	/		/			/		/		
3	3	Hotel lift No.1	G	/		/			/		/		
4	4	Hotel lift No.2	G	/		/			/		/		
5	5	Residence lift	G		X					X		X	รอปเปลี่ยนอุปกรณ์ LINK สัญญาณภาพ
6	6	Front lift No.5	G	/		/			/		/		
7	7	Car parking 1	B	/		/			/		/		
8	8	Car parking 2	B	/		/			/		/		
9	9	Inside edl 1	G	/		/			/		/		
10	10	Inside edl 2	G	/		/			/		/		
11	11	Inside edl 3	G	/		/			/		/		
12	12	Inside edl 4	G	/		/			/		/		
13	13	Entrance EDL	G	/		/			/		/		
14	14	Cupper	G	/		/			/		/		
15	15	Front Cupper	G	/		/			/		/		
16	16	In-front Building	G		X					X		X	สายไม่มีสัญญาณ
17	17	Toilet EDL	G	/		/			/		/		
18	18	Fountain	G		X					X		X	สายไม่มีสัญญาณ
19	19	Kitchen Room 1	G	/		/			/		/		
20	20	Kitchen Room 2	G	/		/			/		/		
21	21	Guest house 1	G	/		/			/		/		
22	22	Guest house 2	G	/		/			/		/		
23	23	Outdoor parking 1	G	/		/			/		/		
24	24	Outdoor parking 2	G	/		/			/		/		
25	25	In-out hotel	G	/		/			/		/		
26	26	Lily lift	G	/		/			/		/		
27	27	Lily 1	G	/		/			/		/		
28	28	Lily 2	2	/		/			/		/		
29	29	Back meeting	2	/		/			/		/		

The Park Nine Hotel Suvanabhumi

No	Floor	Location	Fire Extinguisher				Status		Fire Hose Cabinet								Remark		
			TYPE OF EXTINGUISHER				Normal	Abnormal	Cabinet	Safety Glass	Hose reel	Fire hose 2.5"	2 Nozzles	Axe	Valve	Cap & Chain		Signage	
			Dry Chem	Co2	Form	BF2000			Status	Status	Status	Status	Status	Status	Status	Status		Cleanliness	
Building A									Status	Status	Status	Status	Status	Status	Status	Status	Status	Cleanliness	
1	B	Parking Building	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
2	G	Front toilet EDL restaurant	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
3	G	F&B store (EDL)	-	1	-	-	/												
4	G	Generator Room	1	-	-	-	/												
5	G	Front Kitchen Room	1	-	-	-	/												
6	G	Kitchen Room	-	-	2	-	/												
7	2	Electrical Room	1	-	-	-	/												
8	2	Front lift meeting	-	1	-	-	/												/
Building B																			
9	B	Front of fire pump room	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
10	B	Front of HK Store	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
11	B	Fire staircase Hotel side	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
12	G	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
13	G	Lobby Hotel	1	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
14	G	Security Office	-	-	-	1	/												
15	G	Fire Cart Security	-	1	1	-	/												
16	G	Saver room	-	-	-	1	/												
17	G	Fire staircase Hotel	1	-	-	-	/												/
18	G	Coridor back office	-	-	-	1	/												
19	2	Fire staircase Resident	2	-	-	-	/												/
20	2	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
21	2	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
22	3	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
23	3	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
24	3	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
25	4	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
26	4	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
27	4	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
28	5	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
29	5	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
30	5	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
31	6	Fire staircase Resident	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
32	6	Hall lift Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	
33	6	Fire staircase Hotel	2	-	-	-	/		/	/	/	/	/	/	/	/	/	/	

Equipment monthly checklist November 2022

No.	Equipment	Monthly	Check day	Check by
1	FHC Check	November	17/11/2022	Mr. Samrit Kongtungmon
2	Emergency light		30/11/2022	Mr. Sophon Saenmanee
3	Fire exit signage		29/11/2022	Mr. Ronnarong Mechit
4	Fire exit staircase		30/11/2022	Mr. Sophon Saenmanee
5	Fire Fighting checklist		29/11/2022	Mr. Ronnarong Mechit
6	Rescue equipments		29/11/2022	Mr. Ronnarong Mechit
7	Fire phone and jack		30/11/2022	Mr. Kathawut Ketphot
8	Elevator speaker phone		30/11/2022	Mr. Samrit Kongtungmon

The Park Nine Hotel Suvarnabhumi



EMERGENCY LIGHT CHECKLIST

แบบฟอร์มตรวจเช็คไฟฉุกเฉินในโรงแรม

ตรวจเช็คโดย (INSPECTOR) Mr. Sophon Saenmanee

วันที่ (DAET) 30/11/2022

Floor	Location	Brand/ Model	Code	Quantity	Status		
					Function Lighting Indicator		
					Lamp Y/N	AC Y/N	Battery Status
7	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-01	1	/	/	Normal
	Corridor resident #725 room		EM-02	1	/	/	Normal
	Hall lift Resident		EM-03	1	/	/	Normal
	Fire staircase st-7		EM-04	1	/	/	Normal
	Hall lift hotel		EM-05	1	/	/	Normal
	Corridor hotel #702 room		EM-06	1	/	/	Normal
	Corridor hotel #708 room		EM-07	1	/	/	Normal
	Fire staircase st-4 resident		EM-08	1	/	/	Normal
	Hall lift service		EM-09	1	/	X	Charge
	Network room		EM-10	1	/	X	Charge
	Electricity room		EM-11	1	/	X	Charge
6	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-12	1	/	/	Normal
	Corridor resident #625 room		EM-13	1	/	/	Normal
	Hall lift Resident		EM-14	1	/	/	Normal
	Fire staircase st-7		EM-15	1	/	/	Normal
	Hall lift hotel		EM-16	1	/	/	Normal
	Corridor hotel #602 room		EM-17	1	/	/	Normal
	Corridor hotel #608 room		EM-18	1	/	/	Normal
	Fire staircase st-4 resident		EM-19	1	/	/	Normal
	Hall lift service		EM-20	1	/	X	Charge
	Network room		EM-21	1	/	X	Charge
	Electricity room		EM-22	1	/	X	Charge

The Park Nine Hotel Suvanabhumi

34	7	Fire staircase Resident	2	-	-	-	/	/	/	/	/	/	/	/	/	/	/
35	7	Hall lift Hotel	2	-	-	-	/	/	/	/	/	/	/	/	/	/	/
36	7	Fire staircase Hotel	2	-	-	-	/	/	/	/	/	/	/	/	/	/	/
Total			57	48	3	3	3										

Floor	Fire Blanket			Status	
	Location	Quantity		Yes	No
G	Kitchen	2		/	
	Fire Cart	1		/	
	TOTAL	3			


The Park Nine Hotel Suvarnabhumi

2	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-56	1	/	/	Normal
	Corridor resident #225 room		EM-57	1	/	/	Normal
	Hall lift Resident		EM-58	1	/	/	Normal
	Fire staircase st-7		EM-59	1	/	/	Normal
	Hall lift hotel		EM-60	1	/	/	Normal
	Corridor hotel		EM-61	1	/	/	Normal
	Corridor hotel #208 room		EM-62	1	/	/	Normal
	Fire staircase st-4 resident		EM-63	1	/	/	Normal
	Hall lift service		EM-64	1	/	X	Charge
	Electricity room		EM-65	1	/	X	Charge
G	Fire staircase st-4 resident	Dyno/ Drs-5203	EM-66	1	/	X	Charge
	Fire staircase st-7		EM-67	1	/	/	Normal
B	Parking	Dyno/ Drs-5203	EM-68	1	/	/	Normal
	Fire staircase st-5		EM-69	1	/	X	Charge
	Fire staircase st-7		EM-70	1	/	/	Normal
	Hall toilet staff		EM-71	1	/	X	Charge
	Man toilet staff		EM-72	1	/	X	Charge
	Female toilet staff		EM-73	1	/	/	Normal
	Hall lift service		EM-74	1	/	X	Charge
	Saff canteen		EM-75	1	/	/	Normal



The Park Nine Hotel Suvarnabhumi

5	Fire staircase st-8 hotel	Dyno/ Drs-5203	EM-23	1	/	/	Normal
	Corridor resident #525 room		EM-24	1	/	/	Normal
	Hall lift Resident		EM-25	1	/	/	Normal
	Fire staircase st-7		EM-26	1	/	/	Normal
	Hall lift hotel		EM-27	1	/	/	Normal
	Corridor hotel #502 room		EM-28	1	/	/	Normal
	Corridor hotel #508 room		EM-29	1	/	/	Normal
	Fire staircase st-4 resident		EM-30	1	/	/	Normal
	Hall lift service		EM-31	1	/	X	Charge
	Network room		EM-32	1	/	X	Charge
4	Electricity room	Dyno/ Drs-5203	EM-33	1	/	X	Charge
	Fire staircase st-8 hotel		EM-34	1	/	/	Normal
	Corridor resident #425 room		EM-35	1	/	/	Normal
	Hall lift Resident		EM-36	1	/	/	Normal
	Fire staircase st-7		EM-37	1	/	/	Normal
	Hall lift hotel		EM-38	1	/	/	Normal
	Corridor hotel #402 room		EM-39	1	/	/	Normal
	Corridor hotel #408 room		EM-40	1	/	/	Normal
	Fire staircase st-4 resident		EM-41	1	/	/	Normal
	Hall lift service		EM-42	1	/	X	Charge
3	Network room	Dyno/ Drs 5203	EM-43	1	/	X	Charge
	Electricity room		EM-44	1	/	X	Charge
	Fire staircase st-8 hotel		EM-45	1	/	/	Normal
	Corridor resident #325 room		EM-46	1	/	/	Normal
	Hall lift Resident		EM-47	1	/	/	Normal
	Fire staircase st-7		EM-48	1	/	/	Normal
	Hall lift hotel		EM-49	1	/	/	Normal
	Corridor hotel #302 room		EM 50	1	/	/	Normal
	Corridor hotel #308 room		EM-51	1	/	/	Normal
	Fire staircase st-4 resident		EM-52	1	/	/	Normal
	Hall lift service		EM-53	1	/	X	Charge
	Network room		EM-54	1	/	X	Charge
	Electricity room		EM-55	1	/	/	Normal



FIRE EXIT SIGNAGE CHECKLIST

แบบฟอร์มตรวจป้ายแสงทางออกฉุกเฉินในโรงแรม

ตรวจเช็คโดย (Inspector by) Mr. Romarong Mechit วันที่ (Date) 29/11/2022



Floor	Location	Code	Exit Signs Amount	Status	
				Working	Not Working
7	Fire staircase st-4 resident	EX-01	1	/	Normal
	Hall lift Resident	EX-02	1	/	Normal
	Front lift resident	EX-03	1	/	Normal
	Fire staircase st-7	EX-04	1	/	Normal
	Hall lift hotel	EX-05	1	/	Normal
	Corridor hotel #702 room	EX-06	1	/	Normal
6	Front fire staircase st-8 hotel	EX-07	1	/	Normal
	Fire staircase st-4 resident	EX-08	1	/	Normal
	Hall lift Resident	EX-09	1	/	Normal
	Front lift resident	EX-10	1	/	Normal
	Fire staircase st-7	EX-11	1	/	Normal
	Hall lift hotel	EX-12	1	/	Normal
5	Corridor hotel #602 room	EX-13	1	/	Normal
	Front fire staircase st-8 hotel	EX-14	1	/	Normal
	Fire staircase st-4 resident	EX-15	1	/	Normal
	Hall lift Resident	EX-16	1	/	Normal
	Front lift resident	EX-17	1	/	Normal
	Fire staircase st-7	EX-18	1	/	Normal
4	Hall lift hotel	EX-19	1	/	Normal
	Corridor hotel #502 room	EX-20	1	/	Normal
	Front fire staircase st-8 hotel	EX-21	1	/	Normal
	Fire staircase st-4 resident	EX-22	1	/	Normal
	Hall lift Resident	EX-23	1	/	Normal
	Front lift resident	EX-24	1	/	Normal
3	Fire staircase st-7	EX-25	1	/	Normal
	Hall lift hotel	EX-26	1	/	Normal
	Corridor hotel #402 room	EX-27	1	/	Normal
	Front fire staircase st-8 hotel	EX-28	1	/	Normal
	Fire staircase st-4 resident	EX-29	1	/	Normal
	Hall lift Resident	EX-30	1	/	Normal
2	Front lift resident	EX-31	1	/	Normal
	Fire staircase st-7	EX-32	1	/	Normal
	Hall lift hotel	EX-33	1	/	Normal
	Corridor hotel #302 room	EX-34	1	/	Normal
	Front fire staircase st-8 hotel	EX-35	1	/	Normal
	Fire staircase st-4 resident	EX-36	1	/	Normal
	Hall lift Resident	EX-37	1	/	Normal
	Front lift resident	EX-38	1	/	Normal
	Fire staircase st-7	EX-39	1	/	Normal
	Hall lift hotel	EX-40	1	/	Normal
	Corridor hotel	EX-41	1	/	Normal
	Front fire staircase st-8 hotel				

FIRE

The Park Nine Hotel Suvarnabhumi

EMERGENCY LIGHT CHECKLIST

แบบฟอร์มตรวจเช็คไฟฉุกเฉินในโรงแรม (อาคาร A)

Floor	Location	Brand/ Model	Code	Quantity	Status		
					Function Lighting indicator		
					Lamp	AC	Battery Status
					Y/N	Y/N	
G	Kitchen #1 (Entrance and Exit)	Dyno/ Drs-5203	EM-76	1	/	/	Normal
	Kitchen #2		EM-77	1	/	/	Normal
B	Car parking 1	Dyno/ Drs-5203	EM-78	1	/	X	Charge
	Car parking 2		EM-79	1	/	/	Normal
	Front entrance		EM-80	1	/	/	Normal
	Front lift		EM-81	1	/	/	Normal
Total	81						

Remark: ✓ = Yes or working

X = No or not working

Battery Status = Normal, = Charge

Emergency light not working 23 points.

Reported by: Mr. Sophon Saenmanee

The Park Nine Hotel Suvarrabhum

แบบฟอร์มตรวจบ้านทางออกหนีไฟในโรงแรม

Floor	Location	Code	Exit Signs Amount	Working	Status
G	Front fire staircase st-8 hotel	EX-43	1	/	Normal
	Exit to parking	EX-44	1	/	Normal
B	Corridor no.01	EX-45	1	/	Normal
	Corridor no.02	EX-46	1	/	Normal
	Fire staircase st-7	EX-47	1	/	Normal
Total			47		

Reported by: Mr. Ronnarong Mecht
Position: Security Officer

Acknowledge by: Mr. Kathawut Ketphot
Position: Security Manager

FIRE EXIT STAIRCASE CHECKLIST

แบบตรวจเช็คสภาพภายในบันไดหนีไฟและบานประตูหนีไฟของ โรงแรม

ตรวจเช็คโดย (Inspect by): Mr. Sophon Saenmanee

วันที่ (Date): 30/11/2022

Floor	Location	สิ่งกีดขวาง Obstructions		หลอดไฟส่องสว่าง Neon Lighting		ประตูทางหนีไฟ Fire Exit Door		คานเหล็ก Panic Bar		ก้านดึงประตู Self Closer		หมายเหตุ Remark
		Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
Rooftop	Fire staircase st-7	/		/		/		/		/		
7	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
6	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
5	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
4	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
3	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
2	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-8 hotel	/		/		/		/		/		
G	Fire staircase st-4 residence	/		/		/		/		/		
	Fire staircase st-7	/		/		/		/		/		
B	Fire staircase st-7	/		/		/		/		/		
	Fire staircase st-5 FO Office	/		/		/		/		/		

Reported by: Mr. Sophon Saenmanee
Position: Security Supervisor








Acknowledge by: Mr. Kathawut Ketphot

The Park Nine Hotel Suvarnabhumi







FIRE FIGHTING EQUIPMENT CHECKLIST

แบบตรวจเช็คอุปกรณ์ผจญเพลิง ในโรงแรม
ตรวจเช็คโดย (Inspector By) Mr. Ronnarong Mechit

วันที่ (DATE) 29/11/2022

No.	Equipment	Amount	Actual	Picture	Condition		REMARK
					Yes	No	
1	Fire suite	3	3		/		
2	Helmet	3	3		/		
3	Leather Gove	3	3		/		
4	Safety Mask	3	3		/		
5	Hood	3	3		/		
6	Safety Glasses	3	3		/		
7	Boot	3	3		/		

The Park Nine Hotel Suvarnabhumi

8	Fire Blanket	1	1		/		
9	Nozzles (Protek Model 366)	1	1		/		
10	Fire Hose 2.5"	2	2		/		
11	Fire Phone	1	1		/		
12	Cradle	1	1		/		
13	Megaphone	1	1		/		

Reported By: Mr. Ronnarong Mechit

Position: Security Officer

Acknowledge By: Mr. Kathawut Ketphot

Position: Security Manager

FIRE PHONE OPERATION CHECKLIST

แบบตรวจเช็คอุปกรณ์โทรศัพท์ฉุกเฉินที่ติดตั้งเพลิงโรงแรม

ตรวจเช็คโดย (Checked By): Mr. Kathawut Ketphot

วันที่ (Date): 30/11/2022

Item No. ลำดับที่	Floor ชั้น	Description/Location รายละเอียดสถานที่ตั้ง	Fire Phone Functional Checklist				Remark หมายเหตุ
			Quantity จำนวน	Obvious เสียงดังชัดเจน	Function correct ทำงานถูกต้อง	Fire jack สภาพดีเยี่ยม	
1	7	Fire staircase st-8 resident	1	/	/	/	
2		Fire staircase st-7	1	/	/	/	
3		Hall lift serviced	1	/	/	/	
4		Front fire staircase st-4 hotel	1	/	/	/	
5	6	Fire staircase st-8 resident	1	/	/	/	
6		Fire staircase st-7	1	/	/	/	
7		Hall lift serviced	1	/	/	/	
8		Front fire staircase st-4 hotel	1	/	/	/	
9	5	Fire staircase st-8 resident	1	/	/	/	
10		Fire staircase st-7	1	/	/	/	
11		Hall lift serviced	1	/	/	/	
12		Front fire staircase st-4 hotel	1	/	/	/	
13	4	Fire staircase st-8 resident	1	/	/	/	
14		Fire staircase st-7	1	/	/	/	
15		Hall lift serviced	1	/	/	/	
16		Front fire staircase st-4 hotel	1	/	/	/	
17	3	Fire staircase st-8 resident	1	/	/	/	
18		Fire staircase st-7	1	/	/	/	
19		Hall lift serviced	1	/	/	/	
20		Front fire staircase st-4 hotel	1	/	/	/	
21	2	Fire staircase st-8 resident	1	/	/	/	
22		Fire staircase st-7	1	/	/	/	
23		Hall lift serviced	1	/	/	/	
24		Front fire staircase st-4 hotel	1	/	/	/	
25	G	Fire staircase st-7	1	/	/	/	
26		Hall lift serviced	1	/	/	/	
27	B	Fire staircase st-7	1	/	/	/	
28		Hall lift serviced	1	/	/	/	

Reported By: Mr. Kathawut Ketphot

Position: Security Manager

Acknowledged By: Mr. Kathawut Ketphot

SAFETY AND SECURITY DEPARTMENT





1

RESCUE EQUIPMENT CHECKLIST

แบบตรวจเช็คอุปกรณ์กู้ชีพที่ติดตั้งบริเวณจุดรวมสละว่าเข้าในโรงแรม

วันที่ (Date): 29/11/2022

ตรวจเช็คโดย (Inspector By): Mr. Romarong Mechai

No.	Details Equipment	Amount	Actual	Picture	Status		Remark
					Yes	No	
1	Body Rescue Hook	1	1		/		
2	Ring Buoy	2	2		/		
3	AMBU bag size 500 ml	1	1		/		
4	AMBU bag size 250 ml	1	1		/		

Reported By: Mr. Romarong Mechai

Position: Security Officer

Acknowledged By: Mr. Kathawut Ketphot

Position: Security Manager

Date: 30/11/2022

SAFETY AND SECURITY DEPARTMENT

CCTV CHECKLIST

แบบตรวจเช็คการทำงานของระบบกล้องวงจรปิดใน โรงแรม

ตรวจเช็คโดย (Inspector By) Mr. Ronnarong Mechit

วันที่ (Date) 30/11/2022

เวลา (Time) 23:00:00 PM

No.	NVR No.1		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
1	1	Carpark in-out	B	/		/			/		/		
2	2	Car park 1	B	/		/			/		/		
3	3	Car park 2	B	/		/			/		/		มีภาพใช้งานชั่วคราวรอช่างใส่กล้องคืนน้ำ
4	4	Staff canteen	B	/		/			/		/		
5	5	Staff toilet	B	/		/			/		/		
6	6	HK Office	B	/		/			/		/		
7	7	FO counte	G	/		/			/		/		
8	8	FO lift	G	/		/			/		/		
9	9	HR Office	G	/		/			/		/		
10	10	Back Office	G	/		/			/		/		
11	11	Lobby loun	G	/		/			/		/		
12	12	Entrance lobby	G	/		/			/		/		
13	13	Front F&B Office	G	/		/			/		/		
14	14	AC store	G	/		/			/		/		
15	15	Front security office	G	/		/			/		/		
16	16	Bell store	G	/		/			/		/		
17	17	FO office	G	/		/			/		/		
18	18	Fitness room	G	/		/			/		/		
19	19	Outdoor 1	G	/		/			/		/		
20	20	Outdoor 2	G	/		/			/		/		มีภาพใช้งานชั่วคราวรอช่างใส่กล้องคืนน้ำ
21	21	Outdoor 3	G	/		/			/		/		
22	22	In out kitchen	G	/		/			/		/		
23	23	Swimming pool	G	/		/			/		/		
24	24	Receiving Aaaa	G	/		/			/		/		
25	25	Out door lobby	G	/		/			/		/		
26	26	Garbags room	G	/		/			/		/		
27	27	Residence front lift	2	/		/			/		/		
28	28	Staircase St-7	2	/		/			/		/		

The Park Nine Hotel Suvarnabhumi

Date: 30/11/2022

No.	DESCRIPTION/LOCATION	ELEVATOR EMERGENCY SPEAKER PHONE CHECK LIST									REMARK/COMMENT
		Quantity	Location at Display On Emergency Phone		Obvious Control Room		Obvious In an Elevator		Obvious Operator Room		
	ลำดับที่		คำอธิบาย/สถานที่ติดตั้ง	จำนวน	แสดงสถานที่ ตรงกับโทรศัพท์ฉุกเฉิน		เสียงส่งชัดเจน ห้องคอลโทรล		เสียงส่งชัดเจน ในลิฟต์		เสียงส่งชัดเจน Operator room
			YES	NO	YES	NO	YES	NO	YES	NO	
1	Emergency Speaker Guest Lift L-1	1	/		/		/		/		
2	Emergency Speaker Guest Lift L-2	1	/		/		/		/		
3	Emergency Speaker Guest Lift L-3	1	/		/		/		/		
4	Emergency Speaker Serviced Lift L-4	1	/		/		/		/		
5	Emergency Speaker Guest Lift L-5 (A building)	No Finished									
6	Emergency Speaker Service Lift L-6 (A building)	1	/		/		/		/		

Checked by: Mr. Samrit Kongtungmon

Position: Sr. Security Officer

Acknowledged By: Mr. Kathawut Ketphot

62	59	Residence 2	7	/		/			/		/		
No.	NVR No.2		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
1	1	Lift No.5	G	/		/			/		/		
2	2	Service lift	G	/		/			/		/		
3	3	Hotel lift No.1	G	/		/			/		/		
4	4	Hotel lift No.2	G	/		/			/		/		
5	5	Residence lift	G		X					X		X	รอปเปลี่ยนอุปกรณ์ LINK สัญญาณภาพ
6	6	Front lift No.5	G	/		/			/		/		
7	7	Car parking 1	B	/		/			/		/		
8	8	Car parking 2	B	/		/			/		/		
9	9	Inside edl 1	G	/		/			/		/		
10	10	Inside edl 2	G	/		/			/		/		
11	11	Inside edl 3	G	/		/			/		/		
12	12	Inside edl 4	G	/		/			/		/		
13	13	Entrance EDL	G	/		/			/		/		
14	14	Cupper	G	/		/			/		/		
15	15	Front Cupper	G	/		/			/		/		
16	16	In-front Building	G		X					X		X	สายไม่มีสัญญาณ
17	17	Toilet EDL	G	/		/			/		/		
18	18	Fountain	G		X					X		X	ช่างตรวจสอบแล้ว กล้องเสียน้ำเข้า
19	19	Kitchen Room 1	G	/		/			/		/		
20	20	Kitchen Room 2	G	/		/			/		/		
21	21	Guest house 1	G	/		/			/		/		
22	22	Guest house 2	G	/		/			/		/		
23	23	Outdoor parking 1	G	/		/			/		/		
24	24	Outdoor parking 2	G	/		/			/		/		
25	25	In-out hotel	G	/		/			/		/		
26	26	Lily lift	G	/		/			/		/		
27	27	Lily 1	G	/		/			/		/		
28	28	Lily 2	2	/		/			/		/		

29	29	Hotel lift	2	/		/			/		/		
30	30	Hotel 1	2	/		/			/		/		
No.	NVR No.1		Floor	Video Signal		Image Status			CCTV Angle		CCTV Recording		Remark/Comment
	Channel	Location/Name		Normal	Loss	Normal	B/W	Blur	Yes	No	Yes	No	
31	31	Hotel 2	2	/		/			/		/		
32	32	Residence 2	2	/		/			/		/		
33	30	Residence front lift	3	/		/			/		/		
34	31	Staircase St-7	3	/		/			/		/		
35	32	Hotel lift	3	/		/			/		/		
36	33	Hotel 1	3	/		/			/		/		
37	34	Hotel 2	3	/		/			/		/		
38	35	Residence 2	3	/		/			/		/		
39	36	Residence front lift	4	/		/			/		/		
40	37	Staircase St-7	4	/		/			/		/		
41	38	Hotel lift	4	/		/			/		/		
42	39	Hotel 1	4	/		/			/		/		
43	40	Hotel 2	4	/		/			/		/		
44	41	Residence 2	4	/		/			/		/		
45	42	Residence front lift	5	/		/			/		/		
46	43	Staircase St-7	5	/		/			/		/		
47	44	Hotel lift	5	/		/			/		/		
48	45	Hotel 1	5	/		/			/		/		
49	46	Hotel 2	5	/		/			/		/		
50	47	Residence 2	5	/		/			/		/		
51	48	Residence front lift	6	/		/			/		/		
52	49	Staircase St-7	6	/		/			/		/		
53	50	Hotel lift	6	/		/			/		/		
54	51	Hotel 1	6	/		/			/		/		
55	52	Hotel 2	6	/		/			/		/		
56	53	Residence 2	6	/		/			/		/		
57	54	Residence front lift	7	/		/			/		/		
58	55	Staircase St-7	7	/		/			/		/		
59	56	Hotel lift	7	/		/			/		/		
60	57	Hotel 1	7	/		/			/		/		
61	58	Hotel 2	7	/		/			/		/		

29	29	Back meeting	2	/	/	/	/	/	/	
----	----	--------------	---	---	---	---	---	---	---	--

NVR No.	Period Time Record	Total/Day
PRN-4011 (172.20.0.2:8001)	25/10/22-30/11/22	37 Day
NVR (172.20.3.554)	28/10/22-30/11/22	37 Day
NVR03 (172.20.0.4:554)	7/10/22-30/11/22	55 Day

*Dome Camera 69 Unit
 *Out Doors Camera 22 Unit
 Total 91 Unit

Reported by: Mr. Ronnarong Mechit

Title: Security Officer

Acknowledged By: Mr. Kathawut Ketphot

Title: Security Manager


Date: 30/11/2022



ภาคผนวกที่ 3-13
ผังการติดตั้งถังสำรองน้ำดับเพลิง

ถังสำรองน้ำดับเพลิง *ติดตั้งอยู่ใต้พื้นลานจอดรถ*




ภาพถ่ายแบบพื้นที่แท่งน้ำสำรอง (ใต้พื้นที่จอดรถ)





ภาคผนวกที่ 3-16
กฎระเบียบการเข้าใช้บริการ

กฎระเบียบผู้พักอาศัย



ประกาศ

1. โรงแรมจะรับผิดชอบต่อการพินัยของผู้เข้าพัก กรณีเกิดความสูญหายหรือเสียหาย ดังนี้
 - 1.1 การสูญหายหรือเสียหายที่เกิดขึ้นในโรงแรม
 - 1.2 หากการพินัยที่สูญหายหรือเสียหายตามข้อ ๑.๑ เป็นประเภทเงิน ทอง ธนบัตร ตู้เงิน พินบัตร ทรัพย์สิน หรือ ของมีค่าอื่นๆ โรงแรมจะรับผิดชอบไม่เกิน ๕,๐๐๐ บาท (ห้าพันบาทถ้วน) เว้นแต่ผู้เข้าพักจะได้นำหลักฐานมาแสดงว่าได้แจ้งราคาของการพินัยนั้นไว้กับโรงแรม
2. โรงแรมขอสงวนสิทธิ์ในความรับผิดชอบ หากความสูญหายหรือเสียหายดังกล่าวเกิดขึ้น เพราะเหตุดังต่อไปนี้
 - 2.1 เหตุสุดวิสัย
 - 2.2 เหตุแห่งสภาพของการพินัยนั้นๆ
 - 2.3 เป็นความผิดของผู้เข้าพัก บริวาร หรือบุคคลที่ผู้เข้าพักให้การต้อนรับ

FIRE SAFETY AND EMERGENCY

At The Park Nine Hotel Suvarnabhumi, your safety is our primary concern. Our Fire and Safety plans are well established by our professional team. With the 24-hour-monitor system by security team and Fire Brigade, please rest assured that your stay will be well protected. In addition, while you stay here we encourage you to develop good safety habits and follow the following suggestions.

When you check into your room or residence, please familiarize yourself with the location of the fire alarm call points on your floor. Know where FIRE EXTINGUISHERS are located. It would be good to know how to operate them. A fire extinguisher is provided in the fire hose cabinet located in the corridor of each guest room floor.

In Case of Fire

If the Fire Alarm is Activated:

DO NOT panic and remain CALM

If the alarm has sounded for over two minutes or when you hear the evacuation instruction, head for the emergency stairs.

DO NOT take along with you any bulky belongings

DO NOT use the ELEVATOR. Leave the hotel to street level via nearest stairway DO NOT rush or run when evacuating with children or the elderly.

Proceed to the Assembly Point in front of the building once you exit the building. Please do not leave the Assembly Point area until your name has been verified.

Evacuated through the SMOKE

If there is smoke, use a wet cloth or towel to cover your nose and mouth. If necessary, crouch or crawl, as the smoke will usually occupy the upper area of the room. Before you open the door, feel the surface with the back of your hand. If it is hot, there may be a fire outside. If so, do not go out. Instead, place a wet towel or sheet at the base of the door. Call the Operator to request for assistance. Do not break doors or windows as the air may rush into the room to feed the fire.



FIRE SAFETY AND EMERGENCY (CONT.)

If you notice the smoke or fire

If you see smoke or fire, leave the room IMMEDIATELY and activate the fire alarm button located in the corridor. Do not attempt to put out the fire yourself.

Use of Fire Extinguisher

- 1) Take the fire extinguisher from its holder.
- 2) Break the seal.
- 3) Pull out the safety pin.
- 4) Aim the nozzle of the extinguisher at the base of the fire.
- 5) Squeeze the trigger handle.
- 6) Sweep from side to side.

Fire Evacuation Drill

The management regularly conducts a fire rehearsal every quarter. Your participation in fire drill will help you familiarize with procedure and be vital in times of emergency.

FLOOD

- At all times, keep your valuables and belongings in a safe and dry place.
- Turn off the electricity immediately. Unplug all cables from the socket and place the cables in a safe place to prevent any water contact.
- Contact the Management or Operator.
- Stay CALM and DO NOT panic

RIOTS

- In the event of such incidents where large crowds of people are gathering or marching past the Hotel building, guests are advised not to go out to the balcony to watch.
- DO NOT go to the ground floor or to the street to watch, or take photographs.
- Close all curtains in your room at night. If possible, only switch on the lights that you require.
- DO NOT shout, show gestures of support or throw anything at the crowd.



FIRE SAFETY AND EMERGENCY

- In the event of any mob rush, all our elevators will be grounded. Please lock all your doors and remain in your apartment unit you are sure that it is safe to go out. Do not go near the windows.
- The Management will activate an emergency plan at the ground level. Guests would then be asked to stay in their room. Please do not call the Operator. The Management will contact you once the situation returns to normal.
- The Management will keep you informed of any new developments.



SERVICES, FACILITIES AND POLICIES

Air conditioning

The accommodations are air-conditioned each room with individual temperature control. Should you require any assistance, please contact the extension number 0.

Airline Information

All airlines activities such as flight confirmations, bookings, amendments or cancellations can be facilitated through our Guest Services at the front desk, please contact the extension number 0.

Airport & Limousine Service

The transportation arrangement can be book or confirm with the Guest Services. Please contact extension number 0.

Baby Cot

Baby cots are available free of charge on request. Please contact our Guest Services extension 0 for assistance.

Baby – Sitting

Our Housekeeping can be arranged this service at a nominal fee, but we require at least 24-hours prior notice. Please contact at extension number 5.

Baggage

For baggage assistance or storage please contacts extension number 6.

Breakfast

The breakfast buffet available at All Day Dining EAT DRINK LOVE Bistrot located on the ground floor of Building A start daily from 06:00 - 10:30 hrs. For any inquiry please contact number 2.

Business Assistance

For your business needs, including photocopying, courier and postal services, laminating or printing is available upon request at Front Desk. Please contact our Guest Services extension number 0.



SERVICES, FACILITIES AND POLICIES (CONT.)

Check In Time and Check out Time

Check in time is 14.00 hrs. Check out time is 12:00 hrs. For any guest require late checkout or extension stays, please contact Guest Services 1 day in advance at extension number 0.

Departure

Check out time is 12:00 hrs. Please inform our Guest Services if you wish to retain your room beyond this time. Extension will be given depending on availability. If the room is available, normal tariff will be charged. On failure of the Guest to vacate the room on expiry of the period, the Hotel Management shall have the right to remove the Guest and his/her belongings from the room occupied by the Guest.

Guest's Belongings

Guests are given a key card upon registration and are particularly requested to lock the door of their rooms when going out or going to bed. For the convenience of guests, safes are provided in the room to store any valuables. Guests are kindly requested to deposit all their valuables in the in-room safe.

The hotel will be responsible only 5,000 THB for any loss/or damage to the Guest's belongings from either the Hotel room or safe or any other part of the Hotel for any cause whatsoever, including theft.

Credit Policy

All guests are required upon checking in, to make an advance payment of their accommodation equivalent to the length of stay. This advance payment may be made in cash or credit card. In addition, an incidental deposit is required in cash or credit card with your signature on the sales slip must be made.

Pet Policy

The hotel is not Pet friendly and no accept any Pet.



SERVICES, FACILITIES AND POLICIES (CONT.)

Smoking Rooms

The hotel has a non-smoking policy within its indoor public areas, rooms and suites.

Visitors

Guests may have visitors in their rooms which must be registered at the front desk. Visitors are allowed until 22.00 hrs. In case of extended visits after 22.00 hrs. The hotel will charge an additional fee of 1,800 THB per room per night as a supplement for the guest/visitor.

Child Policy

A maximum of two children under the age of 12 years old are allowed to share the room without additional charges using existing bedding (in selected rooms)

Damage to Property

Guests will be held responsible for any loss or damage to hotel property caused by themselves, their guests or any person for whom they are responsible. In case of damage caused to hotel by the guest, the guest is due to cover the cost of all damage caused to the hotel.

Personal Data Use

The guests agrees and consents that hotel may process (photocopy/scan) his/her personal documents in order to register him/her as a guest of the hotel.

Hotel Management's Rights

It is agreed that the Guest will conduct him/herself in a respectable manner, not to provide any disturbances to other guests, and will not cause any nuisance or annoyance within the Hotel premises. In case of breach of Hotel Rules and Management Policies by the Guest, the Hotel Management has the right to request any guest to vacate his/her room or other areas of the Hotel forthwith without previous notice and without assigning any reason whatsoever, and the Guest shall be bound to vacate when requested to do so. In case of the default, the Hotel Management has the right to remove luggage and belongings from the room occupied by the Guest.



SERVICES, FACILITIES AND POLICIES (CONT.)

Cheques

We regret that we do not accept personal cheque and traveler's cheque. Please contact Guest Services at extension number 0 for assistance.

Do not disturb

If you wish to have your call screened or not to be disturbed with telephone calls our Guest services will assist you. Please contact extension number 0. In addition, a "Do not disturb" request.

Drinking Water

Two bottles of complimentary drinking water are provided upon your arrival, if you require more, please contact Housekeeping service at extension 5 and we can deliver to your room as the supplement condition.

Electrical Current

Electricity supply is 220 volts, 50 cycles A.C., 110 volts transformers and adaptors are available on loan please contact extension number 0.

Extra Bed

Extra Beds are available for rental upon request at THB 1,000 net inclusive of VAT per day. Kindly contact our Guest Services at extension number 0 for assistance.

Fire Procedure

In the event of a fire, the alarm bell will active automatically all hotel premises area, in the building are equipped with heat detection and sprinkler system. Smoke detectors are located along in all rooms and corridors. A fire extinguisher is located in the fire hose cabinet. In the event of a fire, please contact our Guest Services immediately and give your location. During any emergency, please do not use the elevators. Move quickly and calmly to the nearest fire exit staircase. Please familiarize yourself with the fire-exit route attached at the back of the main door in your room and the fire evacuation procedure inside the directory. Three fire exit staircases are located on every floor in the building and these will lead to the Ground Level. Please note that these fire exit staircase doors are one-way doors and are designed for evacuation purposes only.



SERVICES, FACILITIES AND POLICIES (CONT.)

Gym

Fitness Room is located on the Ground floor beside swimming pool, provides necessary health and fitness facilities including cardiovascular and strength fitness equipment. Open daily from 006:00 - 22:00 hrs. Please contact Guest Services extension number 0 for assistance.

Housekeeping

Service is offered daily. If you wish to specific cleaning time, please contact our Housekeeping at extension number 5. To make your stay more comfortable, we pleased to provide you with extra pillows, blankets, hangers or any other household requirements. The Housekeeping Department is open daily from 07.00 - 22.00 hrs

Hair Dryer

A hairdryer is provided in every room. It can be found in the closet

IDD Call

To make an international call from your room, please dial 9 and follow by 001+ Country Code+ Area Code+ Telephone Number. IDD Call is subjected to 20 per cent surcharged. Should assistance required please contact extension number 0.

Key Card

For your security, please do not write your room number on the cards. A key card will be required to operate the in room energy and all entrance doors to access. Guest, who fails to surrender a key card upon check out, will be charged Baht 500 each plus prevailing Tax. For additional key cards, please contact our Guest Services at extension number 0.

Laundry and Dry Cleaning Services

Please complete the bill in the closet. We have arranged to provide this service through an external professional laundry provider. Please hand in before 10:00 hrs. and delivery will be made on the following day. A surcharge of 100% will be charged for same day return as the express service. Regular Service: collection before 10:00 hrs. Return before 18:00 hrs. the Next day. Express Service: collection before 10:00 hrs. Return before 19:00 hrs. Please contact our Housekeeping team at extension number 5 for laundry pick-up.

SERVICES, FACILITIES AND POLICIES (CONT.)

Meeting & Conference Room

Meeting Room are available and fully are equipped with LCD projector, visualize, sound system and internet access, it can accommodate from 10 to 250 persons depending on the room set-up plus coffee break and meeting equipment upon your request.

Restaurants, Bakery & Room Service

- "Eat Drink Love" Bistro an all day dining restaurant served you both buffet and a la carte menu, located on ground floor of Tower A. Our breakfast is serving during 06:00 - 10:30 hrs, our a la carte menu carries on until 23:00 hrs., daily. Please dial 2 for more information.

- "Shiso" a Japanese restaurant where you can find our finest sushi and authentic Japanese food from our experienced chef, adjacent to Eat Drink Love. Coming Soon.

- "Cuppers" an espresso bar and bakery store for dessert lovers. we served irresistible pastry and variety of aromatic coffee to delight your day.

Open daily from 06:00 - 20:00 hrs. Located on ground floor in front of Tower A

- "Room Service" Our Chef selected the finest Western and Asian menus that allow you to enjoy and relaxing the favorite dishes in your own room, available 24 hrs.

- "Lobby Lounge" Located at the lobby level, the lobby lounge is one of chillaxing venues where guests can enjoy Wine, Whiskies, Champagnes, Cocktails, Delicious Snacks and great house music and contemporary décor and views of white marble pool garden, Operation hours 06.00 to Midnight.

Swimming Pool

Located on level G, is opened daily from 06:00 - 21:00 hrs.

Security

CCTV and Vigilant Security officer is in operation 24/7

Safe Deposit Box

For secure your valuables, each room is equipped with a personal safe, inside the closet. The management cannot take any responsibility for valuables that may be left unattended in the room.



SERVICES, FACILITIES AND POLICIES

Sauna and Steam Room

Separate male sauna and female steam room located at Level G. next to the swimming pool. Open daily from 06:00 -21:00 hrs.

Storage

Arrangement can be made for the storage of baggage for guests departing after 12:00 hrs. check-out time by contact Guest Services extension number 0.

Wireless Internet Access

At The Park Nine Hotel Suvarnabhumi, Internet Access is complimentary for our guest. We provided Wireless Internet connection for the user in every room and the public area such as the lobby, poolside, restaurants and the function room. For any services for assistance please contact our Guest Service extension 0.

Wake-up Service

Our Telephone Operator will be delighted to provide you with a wake-up call. Please contact Guest Services extension number 0.

Umbrellas

During the rainy season, umbrellas are available on loan at Concierge Counter.



LOCAL INFORMATION FOR FOREIGNERS

Airlines Detail

For Airline Details, please contact our Guest Services at extension number 0 for more information.

Emergency Call Numbers

Police 191

Ambulance 1554

Fire 199

Tourist Police 1155

In case of any emergency in your room, please contact Guest Services at extension 0.



TRANSPORTATION

Taxi Service

Taxi in Bangkok is on metered system. The fare is started from Baht 35. It is charged according to the meter. For expressway, an additional will be accrued charged.

Tuk Tuk

Unique 3 wheels cars are commonly available in Bangkok. The fare is up to distance and bargain.

BTS

Sky Train operation hour start from 06:00 hrs. to midnight. The BTS stations are located in shopping mall and central business district.

MRT

The first metro transportation in Thailand is running from Hua Lum Phong (Train Station) to Bang Sue. The operating hour starts from 06:00 hrs. to midnight.

Airport Rail Link

Operation hours start from 05.30 hrs to midnight and running from Suvarnabhumi airport station to Phayathai interchange station for BTS Sky Train.

Airport Shuttle

Please contact the front desk to reservation for complimentary airport shuttle service, hotel to Suvarnabhumi airport.

Car Parking

Parking available upon request.



STEAM AND SAUNA ROOM

- The Sauna and Steam Room will remain open daily from 06.00 - 21.00 hrs.
The management reserves the right to direct that the facility is closed for the purpose of safety or for carrying out repairs or other works.
- The use of these facilities is restricted to Hotel's guests only.
- Users suffering from high blood pressure, heart disease or under medication should not use sauna facilities. We recommend that all users seek their doctor's advice before using these facilities.
- Children under the age of 16 years old are not permitted to use the steam and sauna facilities.
- In the interest of hygiene, all users must shower prior to using the steam and sauna rooms.
- We recommend that users should not remain in the steam and sauna for more than 15 minutes per session and should drink water regularly.



GYM & SWIMMING RULES

- No lifeguard on duty at the Swimming Pool. All children under the age of 12 years old must be accompanied by an adult at all times.
 - This Swimming Pool will remain open daily from 06:00 – 21:00 hrs. The management reserves the right to prescribe opening and closing times and to direct that the facility is closed on any occasion for the purpose of safety, private functions, carrying out repairs or other works.
 - The use of these facilities is restricted to Hotel's guests only.
 - Persons intending to swim should be properly and decently attired. Use of suntan oil sparingly is permitted. And please remove hair clips and take shower before using the pool.
 - No person is permitted to:
 - Bring pets of any kind into the premises. Play ball games, skateboard or roller skate in the pool area.
 - Enter the pool while suffering from any contagious diseases.
 - Smoke, eat or drink whilst in the pool.
 - Use large floating devices.
 - Use glassware and chinaware in the pool area.
 - Do any act that is likely to endanger, obstruct, inconvenience or annoy other users.
 - Radios, CD players, and all other audiovisual equipment are prohibited except for equipment fitted with a personal headphone for the comfort of other users. Please keep the noise level reasonable.
 - Life-saving apparatus and equipment on the premises are for emergency use only.
 - All persons using the pool do so entirely at their own risk. The management, owners and/or its agents shall not be responsible for any accident or injury which may be sustained by any person, arising directly out of, or in connection with the use of the facility or anything ancillary thereto, and whether caused by negligence or otherwise.
 - All persons using the facilities shall take care of their own belongings.
- The management, owners and/or its agents shall not be held responsible for any damage to or loss of personal belongings. Lockers are available in the changing room.

LOCAL INFORMATION FOR FOREIGNERS

Climate

Temperatures range from 29°C (84°F) to 35°C (95°F). There are three seasons in Thailand; namely the cool season (November to March) , the hot season (April to May) , and the rainy season (June to October).

Currency

We are using Thai Baht.

Banks

Banks are opened from 09:30 - 15:30 hrs., from Mondays to Fridays. Only some Banks in main shopping areas are opened on Saturday and Sunday from 11:00 - 19:00 hrs.

Government Offices

Government Offices are opened from Mondays to Fridays from 09:30 – 16:00 hrs.

Embassies

Embassy Offices are opened from Mondays to Fridays from 09:00 - 15:00 hrs. For more details please contact Guest Services at extension 0 for further assistance.

Shopping

Most shops and shopping mall are opened at 10:00 am. Many shops accept credit card. However, some shops require a minimum purchase to accept credit card.

Tipping

Tipping is not a must but it has become a normal practice to tip housekeeping staff, tour guides, etc. All major restaurants and hotels will include a 10 percent service charge. Tipping is up to one's preferences.

Airport Information

Bangkok has 2 airports Suvarnabhumi and Don Mueang Airport. Please check your plane schedule on your departure location.



ภาคผนวกที่ 3-17
บันทึกค่าน้ำสระว่ายน้

บันทึกค่าน้ำระเหยน้ำ

เดือน..... JUL 2022.....

ว/ด/ป	ค่า PH	ค่า CL	หมายเหตุ	ผู้บันทึก
1	7.5	3.0		
2	7.5	3.0		
3	7.5	3.0		
4	7.5	3.0		
5	7.5	3.0		
6	7.5	3.0		CH
7	7.5	3.0		CH
8	7.5	3.0		
9	7.5	3.0		CH
10	7.6	3.0		CH
11	7.6	3.0		CH
12	7.6	3.0		CH
13	7.6	3.0		CH
14	7.6	3.0		CH
15	7.6	3.0		
16	7.6	3.0		CH
17	7.6	3.0		CH
18	7.6	3.0		CH
19	7.6	3.0		CH
20	7.6	3.0		CH
21	7.6	3.0		CH
22	7.6	3.0		
23	7.6	3.0		CH
24	7.2	1.5		CH
25	7.2	1.5		CH
26	7.2	1.5		CH
27	7.2	1.5		CH
28	7.2	1.5		CH
29	7.2	1.5		
30	7.2	1.5		
31	7.2	1.5		

บันทึกค่าน้ำระเหยน้ำ

เดือน สิงหาคม 2565

ว/ด/ป	ค่า PH	ค่า CL	หมายเหตุ	ผู้บันทึก
1	7.7	1.5		CH
2	7.2	1.5		CH
3	7.2	1.5		CH
4	7.2	1.5		CH
5	7.2	1.5		
6	7.2	1.5		
7	7.2	1.5		
8	7.2	1.5		
9	7.2	1.5		
10	7.2	1.5		
11	7.2	1.5		
12	7.2	1.5		
13	7.2	1.5		
14	7.2	1.5		
15	7.2	1.5		
16	7.2	1.5		
17	7.2	1.5		
18	7.2	1.5		
19	7.2	1.5		CH
20	7.2	1.5		
21	7.2	1.5		
22	7.2	1.5		
23	7.2	1.5		
24	7.2	1.5		
25	7.2	1.5		
26	7.2	1.5		
27	7.2	1.5		
28	7.2	1.5		
29	7.2	1.5		
30	7.2	1.5		
31	.			

บันทึกค่าน้ำระเหยน้ำ

เดือน กันยายน 2565

ว/ด/ป	ค่า PH	ค่า CL	หมายเหตุ	ผู้บันทึก
1	7.2	1.5		
2	7.2	1.5		
3	7.2	1.5		
4	7.2	1.5		
5	7.2	1.5		
6	7.2	1.5		
7	7.2	1.5		
8	7.2	1.5		
9	7.2	1.5		
10	7.2	1.5		
11	7.1	1.5		
12	7.1	1.5		
13	7.1	1.5		
14	7.3	1.5		
15	7.3	1.5		
16	7.4	1.5		
17	7.4	1.5		
18	7.4	1.5		
19	7.2	1.5		
20	7.2	1.5		
21	7.2	1.5		
22	7.2	1.5		
23	7.2	1.5		
24	7.2	1.5		
25	7.2	1.5		
26	7.2	1.5		
27	7.2	1.5		
28	7.2	1.5		
29	7.2	1.5		
30	7.2	1.5		
31	7.2	1.5		

ว/ด/ป	ค่า PH	ค่า CL	หมายเหตุ	ผู้บันทึก
1	7.2	1.5		
2	7.2	1.5		
3	7.2	1.5		
4	7.2	1.5		
5	7.2	1.5		
6	7.2	1.5		
7	7.2	1.5		
8	7.2	1.5		
9	7.2	1.5		
10	7.2	1.5		
11	7.2	1.5		
12	7.2	1.5		
13	7.2	1.5		
14	7.2	1.5		
15	7.2	1.5		
16	7.2	1.5		
17	7.2	1.5		
18	7.2	1.5		
19	7.2	1.5		
20	7.2	1.5		
21	7.2	1.5		
22	7.2	1.5		
23	7.2	1.5		
24	7.2	1.5		
25	7.2	1.5		
26	7.2	1.5		
27	7.2	1.5		
28	7.2	1.5		
29	7.2	1.5		
30	7.2	1.5		
31	7.2	1.5		

บันทึกค่าน้ำสระว่ายน้ำ

เดือน พฤศจิกายน 2565

ว/ด/ป	ค่า PH	ค่า CL	หมายเหตุ	ผู้บันทึก
1	7.2	1.5		
2	7.2	1.5		
3	7.2	1.5		
4	7.2	1.5		
5	7.2	1.5		
6	7.2	1.5		
7	7.2	1.5		
8	7.2	1.5		
9	7.2	1.5		
10	7.2	1.5		
11	7.2	1.5		
12	7.2	1.5		
13	7.2	1.5		
14	7.2	1.5		
15	7.2	1.5		
16	7.2	1.5		
17	7.2	1.5		
18	7.2	1.5		
19	7.2	1.5		
20	7.2	1.5		
21	7.2	1.5		
22	7.2	1.5		
23	7.2	1.5		
24	7.2	1.5		
25	7.2	1.5		
26	7.2	1.5		
27	7.2	1.5		
28	7.2	1.5		
29	7.2	1.5		
30	7.2	1.5		
31				