

ภาคผนวก ข

การป้องกันและระงับอัคคีภัย

CCTV System Monthly Report								
Month of Report:		January 2023						
Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
Location: Hotel								
1	B-001	Server room (IT)	Normal	N/A	93 Days			
2	B-002	In front of Engineer office	Normal	N/A	62 Days			
3	B-003	In front of Engineer Store	Normal	N/A	62 Days			
4	B-004	Cashier Drop Safe	Normal	N/A	62 Days			
5	B-005	Cashier Account room	Normal	N/A	62 Days			
6	B-006	Finance Store	Normal	N/A	62 Days			
7	B-007	In front of Lift F1,F2	Normal	N/A	62 Days			
8	B-008	Corridor in front of Canteen	Normal	N/A	62 Days			
9	B-009	Canteen room	Normal	N/A	62 Days			
10	B-010	Canteen room	Normal	N/A	62 Days			
11	B-011	Corridor in front of Staff Locker	Normal	N/A	62 Days			
12	B-012	Corridor in front of Uniform room	Normal	N/A	62 Days			
13	B-013	Corridor in front of Staff Locker	Normal	N/A	62 Days			
14	B-014	Staff Rest room	Normal	N/A	62 Days			
15	B-015	Staff Rest room	Normal	N/A	62 Days			
16	B-016	Corridor in front of HK Office	Normal	N/A	62 Days			
17	B-017	Corridor in front of Fire pump room	Normal	N/A	62 Days			
18	B-018	HR Office	Normal	N/A	62 Days			
19	B-019	In front of Lift S1,S2	Normal	N/A	62 Days			
20	B-020	Corridor in front of Main Kitchen	Normal	N/A	62 Days			
21	B-021	Corridor in front of F&B Store	Normal	N/A	62 Days			
22	B-022	Corridor in front of F&B Office	Normal	N/A	62 Days			
23	B-023	Uniform room	Normal	N/A	62 Days			
24	L-024	Entrance Lobby drop off	Normal	N/A	62 Days			
25	L-025	Lobby drop off	Normal	N/A	62 Days			
26	L-026	360 rotating camera at Lobby drop off	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
27	L-027	Exit Lobby drop off	Normal	N/A	62 Days			
28	L-028	In front of Car parking F.L.L	Normal	N/A	62 Days			
29	L-029	In front of Car parking F.L.L 2	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
30	L-030	In front of Lift P5-P6	Normal	N/A	62 Days			
31	L-031	Entrance Lobby	Normal	N/A	62 Days			
32	L-032	Concierge room	Normal	N/A	62 Days			
33	L-033	In front of Concierge room	Normal	N/A	62 Days			
34	L-034	Stair 1 Floor L	Normal	N/A	62 Days			
35	L-035	360 rotating camera at Lobby Lounge	Normal	N/A	92 Days			
36	L-036	Lobby Lounge	Normal	N/A	62 Days			
37	L-037	Counter Front office (Right)	Normal	N/A	62 Days			
38	L-038	Office Front Department	Normal	N/A	62 Days			
39	L-039	Safe room	Normal	N/A	62 Days			
40	L-040	Counter Front office (Left)	Normal	N/A	62 Days			
41	L-041	In front of Lift P1-P4	Normal	N/A	62 Days			
42	L-042	Walkway to Parking Lift Floor L	Normal	N/A	62 Days			
43	L-043	In front of Lift PK1-2	Normal	N/A	62 Days			
44	L-044	Carpark Floor L1	Normal	N/A	62 Days			
45	L-045	Carpark Floor L2	Normal	N/A	62 Days			
46	L-046	Carpark Entrance	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
47	L-047	Gas Station	Normal	N/A	32 Days			
48	L-048	Under Retail Escalator	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
49	L-049	ST-3 Discharge Floor L	Normal	N/A	32 Days			
50	L-050	Parking for Rider under Escalator	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
51	L-051	Cashier point	Normal	N/A	32 Days			
52	L-052	Loading	Not clear	N/A	32 Days			Need to adjust focus of camera
53	L-053	Control room	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
54	L-054	In front of Control room	Normal	N/A	32 Days			
55	L-055	In front of Lift S1-2 FL.L	Normal	N/A	32 Days			
56	L-056	Time Keeper Entrance	Normal	N/A	32 Days			
57	L-057	360 rotating camera at TK	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
58	L-058	Loading Gas Station side	Normal	N/A	32 Days			
59	L-059	Parking Exit	Normal	N/A	32 Days			
60	P5-060	Lift P5	Normal	N/A	32 Days			
61	P6-061	Lift P6	Normal	N/A	32 Days			
62	P1-062	Lift P1	Normal	N/A	32 Days			
63	P2-063	Lift P2	Normal	N/A	27 Days			
64	P3-064	Lift P3	Normal	N/A	32 Days			
65	P4-065	Lift P4	Normal	N/A	32 Days			
66	P7-066	Fireman Lift 1	Normal	N/A	32 Days			
67	P8-067	Fireman Lift 2	Normal	N/A	32 Days			
68	S2-068	Service Lift 1	Normal	N/A	31 Days			
69	S1-069	Service Lift 2	Normal	N/A	32 Days			
70	M-070	In front of ST-2 FL.M	Normal	N/A	32 Days			
71	M-071	In front of ST-4 FL.M	Normal	N/A	32 Days			
72	M-072	Corridor In front of ST-3 FL.M (Retail)	Normal	N/A	32 Days			
73	M-073	In front of ST-2 FL.2 (Retail)	Normal	N/A	32 Days			
74	M-074	In front of The Coffee club (Retail)	Normal	N/A	32 Days			
75	2-075	In front of ST-4 FL.2	Normal	N/A	32 Days			
76	2-076	In front of Service Lift FL.2	Normal	N/A	32 Days			
77	2A-077	Car parking FL.2A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
78	2A-078	In front of ST-4 FL.2A	Normal	N/A	32 Days			
79	3-079	In front of ST-2 FL.3	Normal	N/A	32 Days			
80	3-080	In front of Lift Service FL.3	Normal	N/A	32 Days			
81	3-081	In front of ST-4 FL.3	Normal	N/A	31 Days			
82	3A-082	Car parking FL.3A	Normal	N/A	31 Days			
83	3A-083	In front of ST-4 FL.3A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
84	4-084	Balcony entrance	Normal	N/A	32 Days			
85	4-085	Sukhumvit Gallery	Normal	N/A	32 Days			
86	4-086	In front of Kitchen FL.4	Normal	N/A	32 Days			
87	4-087	In front of Lift P1-P4 FL.4	Normal	N/A	32 Days			
88	4-088	In front of Firman Lift FL.4	Damaged	N/A	32 Days	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
89	4-089	In front of ST-2 FL.4	Normal	N/A	32 Days			
90	4-090	Inside Market Café	Normal	N/A	32 Days			
91	4-091	In front of Service Lift FL.4	Normal	N/A	32 Days			
92	4-092	Kitchen Exit FL.4	Normal	N/A	32 Days			
93	4-093	In front of ST-4 FL.4	Normal	N/A	32 Days			
94	4A-094	Car parking FL.4A	Normal	N/A	32 Days			
95	4-095	In front of ST-4 FL.4	Normal	N/A	32 Days			
96	5-096	Foyer front of ST-1 FL.5	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
97	5-097	In front of Escalator FL.5	Normal	N/A	32 Days			
98	5-098	In front of ST-1 FL.5	Normal	N/A	32 Days			
99	5-099	360 rotating camera at foyer FL.5	Damaged	Rotating motor broken	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
100	5-100	In front of Lift P1-4	Normal	N/A	32 Days			
101	5-101	In front of ST-2 FL.5 (Foyer)	Normal	N/A	32 Days			
102	5-102	Between ST-2 and Ballroom	Normal	N/A	32 Days			
103	5-103	Ballroom	Normal	N/A	32 Days			
104	5-104	In front of BQ store	Normal	N/A	32 Days			
105	5-105	In front of service lift FL.5	Normal	N/A	32 Days			
106	5-106	In front of ST-3 FL.5	Normal	N/A	32 Days			
107	5A-107	Corridor BOH behind Ballroom	Normal	N/A	32 Days			
108	5A-108	In front of service lift FL.5A	Normal	N/A	32 Days			
109	6-109	Inside Fire Exit ST-1 FL.6	Normal	N/A	32 Days			
110	6-110	In front of Fitness	Normal	N/A	32 Days			
111	6-111	In front of Male Locker FL.6	Normal	N/A	32 Days			
112	6-112	In front of Female Locker FL.6	Normal	N/A	32 Days			
113	6-113	In front of Lift P1-4 FL.6	Normal	N/A	32 Days			
114	6-114	In front of Fireman lift Entrance FL.6	Normal	N/A	32 Days			
115	6-115	In front of Fireman Lift FL.6	Normal	N/A	32 Days			
116	6-116	Pool Bar FL.6	Normal	N/A	93 Days			
117	6-117	In front of Service lift FL.6	Normal	N/A	32 Days			
118	7-118	In front of Fireman Lift FL.7	Normal	N/A	32 Days			
119	7-119	Corridor FL.7	Normal	N/A	32 Days			
120	7-120	Corridor in front of room 706	Normal	N/A	32 Days			
121	7-121	In front of Guest Lift FL.7	Normal	N/A	32 Days			
122	8-122	In front of Fireman Lift FL.8	Normal	N/A	32 Days			
123	8-123	Corridor FL.8	Normal	N/A	32 Days			
124	8-124	Corridor in front of room 806	Normal	N/A	32 Days			
125	8-125	In front of Guest Lift FL.8	Normal	N/A	32 Days			
126	10-126	In front of Fireman Lift FL.10	Normal	N/A	32 Days			
127	9-127	Corridor FL.9	Normal	N/A	32 Days			
128	9-128	Corridor in front of room 906	Normal	N/A	32 Days			
129	9-129	In front of Guest Lift FL.9	Normal	N/A	32 Days			
130	9-130	In front of Fireman Lift FL.9	Normal	N/A	32 Days			
131	10-131	Corridor FL.10	Normal	N/A	32 Days			
132	10-132	Corridor in front of room 1006	Normal	N/A	32 Days			
133	10-133	In front of Guest Lift FL.10	Normal	N/A	32 Days			
134	11-134	In front of Fireman Lift FL.11	Normal	N/A	32 Days			
135	11-135	Corridor FL.11	Normal	N/A	32 Days			
136	11-136	Corridor in front of room 1106	Normal	N/A	32 Days			
137	11-137	in front of Guest Lift FL.11	Normal	N/A	32 Days			
138	12-138	In front of Fireman Lift FL.12	Normal	N/A	32 Days			
139	12-139	Corridor FL.12	Normal	N/A	32 Days			
140	12-140	Corridor in front of room 1206	Normal	N/A	32 Days			
141	12-141	In front of Guest Lift FL.12	Normal	N/A	32 Days			
142	14-142	In front of Fireman Lift FL.14	Normal	N/A	32 Days			
143	14-143	Corridor FL.14	Normal	N/A	32 Days			
144	14-144	Corridor in front of room 1406	Normal	N/A	32 Days			
145	14-145	In front of Guest Lift FL.14	Normal	N/A	32 Days			
146	15-146	In front of Fireman Lift FL.15	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
147	15-147	Corridor FL.15	Normal	N/A	32 Days			
148	15-148	Corridor in front of room 1506	Normal	N/A	32 Days			
149	15-149	In front of Guest Lift FL.15	Normal	N/A	32 Days			
150	16-150	In front of Fireman Lift FL.16	Normal	N/A	32 Days			
151	16-151	Corridor FL.16	Normal	N/A	32 Days			
152	16-152	Corridor in front of room1606	Normal	N/A	32 Days			
153	16-153	In front of Guest Lift FL.16	Normal	N/A	32 Days			
154	17-154	In front of Fireman Lift FL.17	Normal	N/A	32 Days			
155	17-155	Corridor FL.17	Normal	N/A	32 Days			
156	17-156	Corridor in front of room 1706	Normal	N/A	32 Days			
157	17-157	In front of Guest Lift FL.17	Normal	N/A	32 Days			
158	18-158	In front of Fireman Lift FL.18	Normal	N/A	32 Days			
159	18-159	Corridor FL.18	Normal	N/A	32 Days			
160	18-160	Corridor in front of room 1806	Normal	N/A	32 Days			
161	18-161	In front of Guest Lift FL.18	Normal	N/A	32 Days			
162	19-162	In front of Lift Fireman Lift FL.19	Normal	N/A	32 Days			
163	19-163	Corridor FL.19	Normal	N/A	32 Days			
164	19-164	In front of Guest Lift FL.19	Normal	N/A	32 Days			
165	19-165	Corridor in front of room 1906	Normal	N/A	32 Days			
166	20-166	In front of Fireman Lift FL.20	Normal	N/A	32 Days			
167	20-167	Corridor FL.20	Normal	N/A	32 Days			
168	20-168	Corridor in front of room 2006	Normal	N/A	32 Days			
169	20-169	In front of Guest Lift FL.20	Normal	N/A	32 Days			
170	21-170	In front of Fireman Lift FL.21	Normal	N/A	32 Days			
171	21-171	Corridor FL.21	Normal	N/A	32 Days			
172	21-172	Corridor in front of room 2106	Normal	N/A	32 Days			
173	21-173	In front of Guest Lift FL.21	Normal	N/A	32 Days			
174	22-174	In front of Fireman Lift FL.22	Normal	N/A	32 Days			
175	22-175	Corridor FL.22	Normal	N/A	32 Days			
176	22-176	Corridor in front of room 2206	Normal	N/A	32 Days			
177	22-197	In front of Guest Lift FL.22	Normal	N/A	32 Days			
178	23-178	In front of Fireman Lift FL.23	Normal	N/A	32 Days			
179	23-179	Corridor FL.23	Normal	N/A	32 Days			
180	23-180	Corridor in front of room 2306	Normal	N/A	32 Days			
181	23-181	In front of Guest Lift FL.23	Normal	N/A	32 Days			
182	27-182	In front of Fireman Lift FL.24	Normal	N/A	32 Days			
183	24-183	Corridor FL.24	Normal	N/A	32 Days			
184	24-184	Corridor in front of room 2406	Normal	N/A	32 Days			
185	24-185	In front of Guest Lift FL.24	Normal	N/A	32 Days			
186	25-186	In front of Fireman Lift FL.25	Normal	N/A	32 Days			
187	25-187	Corridor FL.25	Normal	N/A	32 Days			
188	25-188	Corridor in front of room 2506	Normal	N/A	32 Days			
189	25-189	In front of Guest Lift FL.25	Normal	N/A	32 Days			
190	26-190	In front of Fireman Lift FL.26	Normal	N/A	32 Days			
191	26-191	Corridor FL.26	Normal	N/A	32 Days			
192	26-192	Corridor in front of room 2606	Normal	N/A	32 Days			
193	26-193	In front of Guest Lift FL.26	Normal	N/A	32 Days			
194	27-194	In front of Fireman Lift FL.27	Normal	N/A	32 Days			
195	27-195	Corridor in front of ST-2 FL.27	Normal	N/A	32 Days			
196	27-196	Corridor FL.27	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
197	27-177	Corridor in front of room 2706	Normal	N/A	32 Days			
198	27-198	Regency Club Counter Reception	Normal	N/A	92 Days			
199	27-199	Regency Club Balcony	Normal	N/A	32 Days			
200	27-200	Regency Club in front of Kitchen	Normal	N/A	32 Days			
201	27-201	In front of Guest Lift FL.27	Normal	N/A	32 Days			
202	28-202	In front of Fireman Lift FL.28	Normal	N/A	32 Days			
203	28-203	Corridor FL.28	Normal	N/A	32 Days			
204	28-204	Corridor in front of room 2806	Normal	N/A	32 Days			
205	28-205	In front of Guest Lift FL.28	Normal	N/A	32 Days			
206	29-206	In front of Fireman Lift FL.29	Normal	N/A	32 Days			
207	29-207	In front of Guest Lift FL.29	Normal	N/A	32 Days			
208	29-208	In front of Kitchen FL.29	Normal	N/A	32 Days			
209	29-209	Balcony Kitchen side FL.29	Out of license	No license	31 Days			Planned to re-license
210	29-210	Front Balcony FL.29	Normal	N/A	31 Days			
211	29-211	Staircase up to FL.30	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
212	29-212	Spectrum Bar FL.29	Normal	N/A	93 Days			
213	29-213	Balcony Sofitel side FL.29	Out of license	No license	27 Days			Planned to re-license
214	30-214	Glass floor FL.30	Out of license	No license	27 Days			Planned to re-license
215	30-215	Spectrum FL. 30	Normal	N/A	27 Days			
216	30-216	Spectrum Bar FL.30	Normal	N/A	27 Days			
217	31-217	In front of Lift Control room FL.31	Normal	N/A	27 Days			
218	31-218	Spectrum FL.31	Normal	N/A	27 Days			

Location: Parking and Retail

1	FLM 01	In front of lift FL.M	Normal		98 Days			
2	FLM 02	Parking FL.M	Normal		98 Days			
3	FLM 03	Parking FL.M (Trendy Side)	Normal		98 Days			
4	FLM 04	Parling FL.M (Loading Side)	Damaged		98 Days	The Allez (Retail Office) acknowledged		
5	FL2 01	In front of lift FL.2	Normal		98 Days			
6	FL2 02	Parking FL.2	Normal		98 Days			
7	FL2 03	Parking FL.2 (Trendy Side)	Normal		98 Days			
8	FL2 04	Parling FL.2 (Loading Side)	Normal		98 Days			
9	FL2A 01	In front of lift FL.2A	Normal		98 Days			
10	FL2A 02	Parking FL.2A	Normal		98 Days			
11	FL2A 03	Parking FL.2A (Trendy Side)	Normal		98 Days			
12	FL2A 04	Parling FL.2A (Loading Side)	Normal		98 Days			
13	FL3 01	In front of lift FL.3	Normal		98 Days			
14	FL3 02	Parking FL.3	Normal		98 Days			
15	FL3 03	Parking FL.3 (Trendy Side)	Normal		98 Days			
16	FL3 04	Parling FL.3 (Loading Side)	Normal		98 Days			
17	FL3A 01	In front of lift FL.3A	Normal		98 Days			
18	FL3A 02	Parking FL.3A	Normal		98 Days			
19	FL3A 03	Parking FL.3A (Trendy Side)	Not clear		98 Days	The Allez (Retail Office) acknowledged		
20	FL3A 04	Parling FL.3A (Loading Side)	Normal		98 Days			
21	FL4 01	In front of lift FL.4	Normal		98 Days			
22	FL4 02	Parking FL.4	Normal		98 Days			
23	FL4 03	Parking FL.4 (Trendy Side)	Normal		98 Days			
24	FL4 04	Parling FL.4 (Loading Side)	Normal		98 Days			
25	FL4A 01	Parking FL.4A (Trendy Side)	Normal		98 Days			
26	FL4A 02	Parling FL.4A (Loading Side)	Normal		98 Days			
27	FL4A 03	Parking FL.4A	Normal		98 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
28	FL4A 04	In front of lift FL.4A	Normal		98 Days			
29	FL1 01	BOBO entrance 1	Normal		82 Days			
30	FL1 02	BOBO entrance 2	Normal		82 Days			
31	FL1 03	Under Retail Escalator	Normal		82 Days			
32	FL2 04	Retail Entrance from Parking FL.2	Normal		82 Days			
33	FL2 03	Coffee Club FL.2	Normal		82 Days			
34	FL2 06	Escalator FL.2	Normal		82 Days			
35	FL3 01	In front of lift P5, P6 FL.3	Normal		82 Days			
36	FL3 03	Let's Relax Spa FL.3	Normal		82 Days			
37	FL3 04	Escalator FL.3	Normal		82 Days			
38	FL3 05	In front of ST-1 FL.3	Normal		82 Days			
39	BTS1	Hotel Entrance from BTS	Normal		98 Days			
40	BTS2	BTS Skywalk	Normal		98 Days			
41	BTS3	BTS Entrance	Not clear		98 Days	The Allez (Retail Office) acknowledged		

Summary	
Status	Amount
Normal	241
Damaged	12
Not clear	3
Out of license	3
Total	259

Additional comments:
1. SECOM already sent the report of all damaged CCTVs and waiting for quotation to fix it.
2. Out of license CCTVs, still have camera but due to over CCTV IP point from budget requested since beginning. 3 of them were cut off only signal. Planned to re-license.
3. Comment from Khun Sammy, there must be additional CCTV at Fireman lift landing on L floor.
4. Comments from Khun Bruce and Khun Ian (Hyatt Global Security) that there must be additional CCTVs at POS system which is we miss 2 points at Market Cafe.

Checked By
(.....Anuthida K.....)
Position: Security Officer
Date...26.../...01.../...2023...

Reviewed By
(.....Panuwich T.....)
Security Manager
Date...26.../...01.../...2023...

Acknowledged By
(.....)
Chief Engineer
Date...../...../.....

Fire & Life Safety Monthly Checklist

Month/Year: January 2023

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สวมเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
31	Hot Water Tank Room	N	N	N	N/A	1	N/A	N/A	N/A	N			Hot Water Tank 1 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Hot Water Tank 2 FL.31	N	
30	Spectrum Store					1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.30	N	
29	Back Kitchen					N/A	N/A	2	N/A	N			Exit Stair ST-1 FL.29	N	
	Front Kitchen										2	N	Exit Stair ST-2 (1) FL.29	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 (2) FL.29	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	2	N	MEP FL.29	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.29	N	
	Guest Lift										1	N	Exit Stair ST-1 FL.28	N	
	Toilet										1	N	Exit Stair ST-2 FL.28	N	
28	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.28	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.28	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.27	N	
27	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.27	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.27	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.27	N	
	RC Lounge										2	N	Exit Stair ST-1 FL.26	N	
	Kitchen					1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.26	N	
26	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.26	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.26	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.25	N	
25	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.25	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.25	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.25	N	
24	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.24	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.24	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.24	N	
23	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.24	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.23	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.23	N	
22	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.23	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.23	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามแฉก	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
21	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.22	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.22	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.22	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.22	D	Battery Issue
20	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.21	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.21	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.21	N	
19	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.21	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.20	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.20	N	
18	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.20	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.20	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.19	N	
17	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.19	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.19	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.19	N	
16	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.18	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.18	D	Battery Issue
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.18	N	
15	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.18	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.17	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.17	N	
14	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.17	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.17	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.16	N	
12	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.16	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.16	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.16	N	
11	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.15	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.15	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.15	N	
10	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.15	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.14	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.14	N	
9	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.14	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.14	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.12	N	
8	ST-1	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.12	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.12	D	Battery Issue

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.12	N	
7	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.11	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.11	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.11	D	Battery Issue
6A	Cooling Tower	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.11	N	
6	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-1 FL.10	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.10	D	Test Button Issue
	ST-4										1	N	MEP FL.10	N	
	Pool Entrance (Lift)										1	N	Pantry FL.10	N	
	Pool Entrance (Fitness)										1	N	Exit Stair ST-1 FL.9	N	
	Lift S1-S2	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.9	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.9	N	
	Bar					1	N/A	N/A	N/A	N			Pantry FL.9	N	
5A	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-1 FL.8	N	
5	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-2 FL.8	N	
	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	2	N	MEP FL.8	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Pantry FL.8	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-1 FL.7	N	
	AV Room (Ballroom 4)					1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.7	N	
	Regency Ballroom										9	N	MEP FL.7	N	
	Regency 1-4										8	N	Pantry FL.7	N	
	Guest Lift										1	N	Exit Stair ST-1 FL.6A	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.6A	N	
	BQ Kitchen					N/A	N/A	3	3	N	1	N	Exit Stair ST-1 FL.6	N	
Foyer					N/A	N/A	1	1	N			Exit Stair ST-2 FL.6	N		
4A	ST-2	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-4 FL.6	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	D			MEP FL.6	N	
4A	Event Office										2	N	Front Fireman Lift FL.6	N	
4	ST-1 Sale Office	N	N	N/A	N/A	1	N/A	N/A	N/A	N	3	N	Fireman Lift Entrance FL.6	N	
	ST-2										4	N	Exit Stair ST-1 FL.5A	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.5A	N	
	ST-4										3	N	Exit Stair ST-4 FL.5A	N	
	Lift P5-P6	N	N	N	N	1	N/A	N/A	N/A	N			Corridor FL.5A	N	
	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			MEP FL.5A	N	
	Chiller Room					1	N/A	N/A	N/A	N			AV Room FL.5A	N	
	Left Kitchen					N/A	N/A	2	2	N			Exit Stair ST-1 FL.5	N	
	Right Kitchen					N/A	N/A	2	2	N			Exit Stair ST-2 FL.5	N	
	Inside Kitchen					N/A	N/A	1	1	N	2	N	Exit Stair ST-3 FL.5	N	
	MC										9	N	Exit Stair ST-4 FL.5	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
	Hostess										2	N	MEP FL.5	N	
	Toilet										1	N	BOH Regency 1 FL.5	D	Battery Issue
4PK	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	BOH Regency 2 FL.5	N	
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	BOH Regency 3 FL.5	N	
3A	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	Fireman Lift FL.5	N	
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	2	N	Service Lift FL.5	N	
3	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.4A	N	
3PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-3 FL.4A	N	
2A	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-4 FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exec. Office 1 FL.4A	N	
2	Lift Fireman	N	N	N/A	N/A	1	N/A	N/A	N/A	N			Exec. Office 2 FL.4A	N	
2PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Loading Side FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Trendy Side FL.4A	N	
M	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Electric Room FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-1 FL.4	N	
	Front MEP Room	N	N	N/A	N/A								Exit Stair ST-2 FL.4	N	
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-3 FL.4	D	Battery Issue
L	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-4 FL.4	N	
	ST-2										1	N	Exec. Office FL.4	N	
	ST-4										1	N	Chiller Room 1 FL.4	N	
	Control Room					1	N/A	N/A	N/A	N			Chiller Room 2 FL.4	N	
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.4	D	Battery Issue
	Flower Room	N	N	N/A	N/A	1	N/A	N/A	N/A	N			Fireman Lift FL.4	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Service Lift FL.4	N	
	LPG Gas Station					2	N/A	N/A	N/A	N			Loading Side FL.4	N	
	Lobby Door (S)										1	N	Trendy Side FL.4	D	Battery Issue
	Front Parking Lift										2	N	Exit Stair ST-1 FL.3A	N	
	Loading										4	N	Exit Stair ST-2 FL.3A	N	
R	ST-1 Engineer	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-4 FL.3A	N	
	ST-2 Locker	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Loading Side FL.3A	N	
	ST-3 General Store	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Trendy Side FL.3A	N	
	ST-4 Fire pump	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.3	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-3 FL.3	N	
	Canteen Kitchen					N/A	N/A	1	1	N			Exit Stair ST-4 FL.3	N	
	Learning Center					1	N/A	N/A	N/A	N			MEP FL.3	N	
	Male Locker										2	N	MDB 1 FL.3	N	
	Female Locker										2	N	MDB 2 FL.3	N	
	Canteen										4	N	Generator FL.3	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ									
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ										
5	HK										1	N	Loading Side FL.3	D	Battery Issue									
	Uniform										1	N	Trendy Side FL.3	D	Battery Issue									
	Operator										1	N	Servive Lift FL.3	N/A	Uninstalled									
	HR										1	N	Fireman Lift FL.3	N										
	GC										2	N	Exit Stair ST-1 FL.2A	N										
	Finance Office										1	N	Exit Stair ST-2 FL.2A	N										
	Engineer Office										1	N	Exit Stair ST-4 FL.2A	N										
	Engineer Workshop										2	N	Loading Side FL.2A	N										
	Front Hygene Office										2	N	Trendy Side FL.2A	N										
	Main Kitchen Corridor										2	N	Exit Stair ST-1 FL.2	N										
	Total										111				119	0	12	10		183		Exit Stair ST-2 FL.2	N	
																						Exit Stair ST-3 FL.2	N	
													Exit Stair ST-4 FL.2	N										
													MEP FL.2	N										
													Loading Side FL.2	N										
													Trendy Side FL.2	D	Battery Issue									
													Service Lift FL.2	N/A	Unable to check due to obstruction by stored items									
													Fireman Lift FL.2	N										
													Exit Stair ST-1 FL.M	N										
													Exit Stair ST-2 FL.M	N										
													Exit Stair ST-3 FL.M	N										
													Exit Stair ST-4 FL.M	N										
													Front MEP FL.M	N										
													MEP FL.M	D	Battery Issue									
													Loading Side FL.M	N										
													Trendy Side FL.M	N										
													Exit Stair ST-1 FL.L	N										
													Exit Stair ST-2 FL.L	N										
													Exit Stair ST-3 FL.L	N										
													Exit Stair ST-4 FL.L	N										
													Control Room 1 FL.L	N										
													Control Room 2 FL.L	N										
													Fireman Lift FL.L	N										
													Discharge Fireman Lift FL.L	N										
													Front Service Lift FL.L	N										
													Exit Stair ST-1 FL.B	N										
													Exit Stair ST-2 FL.B	N										

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	

Condition	Summary				
	Fire Hose Cabinet	Fire Extinguisher	Fire Blanket	Fire Exit Sign	Emergency Light
Total	111	131	10	182	214
Normal	98	130	10	182	197
Damage	0	1	0	0	15
Used	0	0	0	0	0
Lost	0	0	0	0	0
N/A	13	0	0	0	2

Exit Stair ST-3 FL.B	N	
Exit Stair ST-4 (1) FL.B	N	
Exit Stair ST-4 (2) FL.B	N	
MEP FL.B	D	Battery Issue
Fireman Lift FL.B	N	
Male Staff Locker 1	N	
Male Staff Locker 2	N	
Female Staff Locker	N	
Front HK Office FL.B	N	
Canteen 1 FL.B	N	
Canteen 2 FL.B	N	
TV Corner FL.B	N	
Corridor front Canteen	N	
Lerning Center	D	Battery Issue
HR Office	N	
Finance Office	N	
Workshop Entrance	N	
Front Cashier	N	
Front FB Office	N	
FB Office	N	
Front General Store	N	
Cold Kitchen Entrance	N	
Front Hygene Office	N	
Pump Room	N	
Compressor Room	N	
Firepump Room	N	
Server Room	N	
Total	214	

Prepared By

(Panuwich Thammathada)

Security Manager

Date 31/01/2023

Acknowledged By

(.....)

Chief Engineer

Date...../...../.....








Fire Cart Monthly Checklist

Month/Year: January 2023

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
1	Fireman Suit Cabinet		1	N	
2	Fire Cart Cabinet		1	N	
3	Fireman Suit		4 Suit	N	
4	Fireman Helmet		4 Pcs.	N	
5	Fireman Hood		N/A	N/A	Need to Order
6	SCBA		2 Set	N	200psi/250psi
7	SCBA Mask		2 Set	N	
8	Fire Fighting Nozzle		N/A	N/A	Pending
9	Fire Hose 1.5"		2 Pcs.	N	
10	Rope		2 Roll	N	

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
11	Axe		2 Pcs.	N	
12	Steel Bolt Cutter		2 Pcs.	N	
13	3-Ways Fire Hydrant Connection		1 Pcs.	N	
14	Spinal Board		1 Pcs.	N	
15	Head Immobilizer		2 Set	N	
16	Scoop Stretcher		1 Pcs.	N	
17	Oxygen Tank		2 Set	N	

Checked By

(Panuwich T.)
Security Manager
Date 17/01/2023

Reviewed By

(Panuwich T.)
Security Manager
Date 17/01/2023

Acknowledged By

(.....)
Chief Engineer
Date/...../.....

CCTV System Monthly Report								
Month of Report:		February 2023						
Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
Location: Hotel								
1	B-001	Server room (IT)	Normal	N/A	93 Days			
2	B-002	In front of Engineer office	Normal	N/A	62 Days			
3	B-003	In front of Engineer Store	Normal	N/A	62 Days			
4	B-004	Cashier Drop Safe	Normal	N/A	62 Days			
5	B-005	Cashier Account room	Normal	N/A	62 Days			
6	B-006	Finance Store	Normal	N/A	62 Days			
7	B-007	In front of Lift F1,F2	Normal	N/A	62 Days			
8	B-008	Corridor in front of Canteen	Normal	N/A	62 Days			
9	B-009	Canteen room	Normal	N/A	62 Days			
10	B-010	Canteen room	Normal	N/A	62 Days			
11	B-011	Corridor in front of Staff Locker	Normal	N/A	62 Days			
12	B-012	Corridor in front of Uniform room	Normal	N/A	62 Days			
13	B-013	Corridor in front of Staff Locker	Normal	N/A	62 Days			
14	B-014	Staff Rest room	Normal	N/A	62 Days			
15	B-015	Staff Rest room	Normal	N/A	62 Days			
16	B-016	Corridor in front of HK Office	Normal	N/A	62 Days			
17	B-017	Corridor in front of Fire pump room	Normal	N/A	62 Days			
18	B-018	HR Office	Normal	N/A	62 Days			
19	B-019	In front of Lift S1,S2	Normal	N/A	62 Days			
20	B-020	Corridor in front of Main Kitchen	Normal	N/A	62 Days			
21	B-021	Corridor in front of F&B Store	Normal	N/A	62 Days			
22	B-022	Corridor in front of F&B Office	Normal	N/A	62 Days			
23	B-023	Uniform room	Normal	N/A	62 Days			
24	L-024	Entrance Lobby drop off	Normal	N/A	62 Days			
25	L-025	Lobby drop off	Normal	N/A	62 Days			
26	L-026	360 rotating camera at Lobby drop off	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
27	L-027	Exit Lobby drop off	Normal	N/A	62 Days			
28	L-028	In front of Car parking F.L.L	Normal	N/A	62 Days			
29	L-029	In front of Car parking F.L.L 2	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
30	L-030	In front of Lift P5-P6	Normal	N/A	62 Days			
31	L-031	Entrance Lobby	Normal	N/A	62 Days			
32	L-032	Concierge room	Normal	N/A	62 Days			
33	L-033	In front of Concierge room	Normal	N/A	62 Days			
34	L-034	Stair 1 Floor L	Normal	N/A	62 Days			
35	L-035	360 rotating camera at Lobby Lounge	Normal	N/A	92 Days			
36	L-036	Lobby Lounge	Normal	N/A	62 Days			
37	L-037	Counter Front office (Right)	Normal	N/A	62 Days			
38	L-038	Office Front Department	Normal	N/A	62 Days			
39	L-039	Safe room	Normal	N/A	62 Days			
40	L-040	Counter Front office (Left)	Normal	N/A	62 Days			
41	L-041	In front of Lift P1-P4	Normal	N/A	62 Days			
42	L-042	Walkway to Parking Lift Floor L	Normal	N/A	62 Days			
43	L-043	In front of Lift PK1-2	Normal	N/A	62 Days			
44	L-044	Carpark Floor L1	Normal	N/A	62 Days			
45	L-045	Carpark Floor L2	Normal	N/A	62 Days			
46	L-046	Carpark Entrance	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
47	L-047	Gas Station	Normal	N/A	32 Days			
48	L-048	Under Retail Escalator	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
49	L-049	ST-3 Discharge Floor L	Normal	N/A	32 Days			
50	L-050	Parking for Rider under Escalator	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
51	L-051	Cashier point	Normal	N/A	32 Days			
52	L-052	Loading	Not clear	N/A	32 Days			Need to adjust focus of camera
53	L-053	Control room	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
54	L-054	In front of Control room	Normal	N/A	32 Days			
55	L-055	In front of Lift S1-2 FL.L	Normal	N/A	32 Days			
56	L-056	Time Keeper Entrance	Normal	N/A	32 Days			
57	L-057	360 rotating camera at TK	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
58	L-058	Loading Gas Station side	Normal	N/A	32 Days			
59	L-059	Parking Exit	Normal	N/A	32 Days			
60	P5-060	Lift P5	Normal	N/A	32 Days			
61	P6-061	Lift P6	Normal	N/A	32 Days			
62	P1-062	Lift P1	Normal	N/A	32 Days			
63	P2-063	Lift P2	Normal	N/A	27 Days			
64	P3-064	Lift P3	Normal	N/A	32 Days			
65	P4-065	Lift P4	Normal	N/A	32 Days			
66	P7-066	Fireman Lift 1	Normal	N/A	32 Days			
67	P8-067	Fireman Lift 2	Normal	N/A	32 Days			
68	S2-068	Service Lift 1	Normal	N/A	31 Days			
69	S1-069	Service Lift 2	Normal	N/A	32 Days			
70	M-070	In front of ST-2 FL.M	Normal	N/A	32 Days			
71	M-071	In front of ST-4 FL.M	Normal	N/A	32 Days			
72	M-072	Corridor In front of ST-3 FL.M (Retail)	Normal	N/A	32 Days			
73	M-073	In front of ST-2 FL.2 (Retail)	Normal	N/A	32 Days			
74	M-074	In front of The Coffee club (Retail)	Normal	N/A	32 Days			
75	2-075	In front of ST-4 FL.2	Normal	N/A	32 Days			
76	2-076	In front of Service Lift FL.2	Normal	N/A	32 Days			
77	2A-077	Car parking FL.2A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
78	2A-078	In front of ST-4 FL.2A	Normal	N/A	32 Days			
79	3-079	In front of ST-2 FL.3	Normal	N/A	32 Days			
80	3-080	In front of Lift Service FL.3	Normal	N/A	32 Days			
81	3-081	In front of ST-4 FL.3	Normal	N/A	31 Days			
82	3A-082	Car parking FL.3A	Normal	N/A	31 Days			
83	3A-083	In front of ST-4 FL.3A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
84	4-084	Balcony entrance	Normal	N/A	32 Days			
85	4-085	Sukhumvit Gallery	Normal	N/A	32 Days			
86	4-086	In front of Kitchen FL.4	Normal	N/A	32 Days			
87	4-087	In front of Lift P1-P4 FL.4	Normal	N/A	32 Days			
88	4-088	In front of Firman Lift FL.4	Damaged	N/A	32 Days	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
89	4-089	In front of ST-2 FL.4	Normal	N/A	32 Days			
90	4-090	Inside Market Café	Normal	N/A	32 Days			
91	4-091	In front of Service Lift FL.4	Normal	N/A	32 Days			
92	4-092	Kitchen Exit FL.4	Normal	N/A	32 Days			
93	4-093	In front of ST-4 FL.4	Normal	N/A	32 Days			
94	4A-094	Car parking FL.4A	Normal	N/A	32 Days			
95	4-095	In front of ST-4 FL.4	Normal	N/A	32 Days			
96	5-096	Foyer front of ST-1 FL.5	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
97	5-097	In front of Escalator FL.5	Normal	N/A	32 Days			
98	5-098	In front of ST-1 FL.5	Normal	N/A	32 Days			
99	5-099	360 rotating camera at foyer FL.5	Damaged	Rotating motor broken	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
100	5-100	In front of Lift P1-4	Normal	N/A	32 Days			
101	5-101	In front of ST-2 FL.5 (Foyer)	Normal	N/A	32 Days			
102	5-102	Between ST-2 and Ballroom	Normal	N/A	32 Days			
103	5-103	Ballroom	Normal	N/A	32 Days			
104	5-104	In front of BQ store	Normal	N/A	32 Days			
105	5-105	In front of service lift FL.5	Normal	N/A	32 Days			
106	5-106	In front of ST-3 FL.5	Normal	N/A	32 Days			
107	5A-107	Corridor BOH behind Ballroom	Normal	N/A	32 Days			
108	5A-108	In front of service lift FL.5A	Normal	N/A	32 Days			
109	6-109	Inside Fire Exit ST-1 FL.6	Normal	N/A	32 Days			
110	6-110	In front of Fitness	Normal	N/A	32 Days			
111	6-111	In front of Male Locker FL.6	Normal	N/A	32 Days			
112	6-112	In front of Female Locker FL.6	Normal	N/A	32 Days			
113	6-113	In front of Lift P1-4 FL.6	Normal	N/A	32 Days			
114	6-114	In front of Fireman lift Entrance FL.6	Normal	N/A	32 Days			
115	6-115	In front of Fireman Lift FL.6	Normal	N/A	32 Days			
116	6-116	Pool Bar FL.6	Normal	N/A	93 Days			
117	6-117	In front of Service lift FL.6	Normal	N/A	32 Days			
118	7-118	In front of Fireman Lift FL.7	Normal	N/A	32 Days			
119	7-119	Corridor FL.7	Normal	N/A	32 Days			
120	7-120	Corridor in front of room 706	Normal	N/A	32 Days			
121	7-121	In front of Guest Lift FL.7	Normal	N/A	32 Days			
122	8-122	In front of Fireman Lift FL.8	Normal	N/A	32 Days			
123	8-123	Corridor FL.8	Normal	N/A	32 Days			
124	8-124	Corridor in front of room 806	Normal	N/A	32 Days			
125	8-125	In front of Guest Lift FL.8	Normal	N/A	32 Days			
126	10-126	In front of Fireman Lift FL.10	Normal	N/A	32 Days			
127	9-127	Corridor FL.9	Normal	N/A	32 Days			
128	9-128	Corridor in front of room 906	Normal	N/A	32 Days			
129	9-129	In front of Guest Lift FL.9	Normal	N/A	32 Days			
130	9-130	In front of Fireman Lift FL.9	Normal	N/A	32 Days			
131	10-131	Corridor FL.10	Normal	N/A	32 Days			
132	10-132	Corridor in front of room 1006	Normal	N/A	32 Days			
133	10-133	In front of Guest Lift FL.10	Normal	N/A	32 Days			
134	11-134	In front of Fireman Lift FL.11	Normal	N/A	32 Days			
135	11-135	Corridor FL.11	Normal	N/A	32 Days			
136	11-136	Corridor in front of room 1106	Normal	N/A	32 Days			
137	11-137	in front of Guest Lift FL.11	Normal	N/A	32 Days			
138	12-138	In front of Fireman Lift FL.12	Normal	N/A	32 Days			
139	12-139	Corridor FL.12	Normal	N/A	32 Days			
140	12-140	Corridor in front of room 1206	Normal	N/A	32 Days			
141	12-141	In front of Guest Lift FL.12	Normal	N/A	32 Days			
142	14-142	In front of Fireman Lift FL.14	Normal	N/A	32 Days			
143	14-143	Corridor FL.14	Normal	N/A	32 Days			
144	14-144	Corridor in front of room 1406	Normal	N/A	32 Days			
145	14-145	In front of Guest Lift FL.14	Normal	N/A	32 Days			
146	15-146	In front of Fireman Lift FL.15	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
147	15-147	Corridor FL.15	Normal	N/A	32 Days			
148	15-148	Corridor in front of room 1506	Normal	N/A	32 Days			
149	15-149	In front of Guest Lift FL.15	Normal	N/A	32 Days			
150	16-150	In front of Fireman Lift FL.16	Normal	N/A	32 Days			
151	16-151	Corridor FL.16	Normal	N/A	32 Days			
152	16-152	Corridor in front of room1606	Normal	N/A	32 Days			
153	16-153	In front of Guest Lift FL.16	Normal	N/A	32 Days			
154	17-154	In front of Fireman Lift FL.17	Normal	N/A	32 Days			
155	17-155	Corridor FL.17	Normal	N/A	32 Days			
156	17-156	Corridor in front of room 1706	Normal	N/A	32 Days			
157	17-157	In front of Guest Lift FL.17	Normal	N/A	32 Days			
158	18-158	In front of Fireman Lift FL.18	Normal	N/A	32 Days			
159	18-159	Corridor FL.18	Normal	N/A	32 Days			
160	18-160	Corridor in front of room 1806	Normal	N/A	32 Days			
161	18-161	In front of Guest Lift FL.18	Normal	N/A	32 Days			
162	19-162	In front of Lift Fireman Lift FL.19	Normal	N/A	32 Days			
163	19-163	Corridor FL.19	Normal	N/A	32 Days			
164	19-164	In front of Guest Lift FL.19	Normal	N/A	32 Days			
165	19-165	Corridor in front of room 1906	Normal	N/A	32 Days			
166	20-166	In front of Fireman Lift FL.20	Normal	N/A	32 Days			
167	20-167	Corridor FL.20	Normal	N/A	32 Days			
168	20-168	Corridor in front of room 2006	Normal	N/A	32 Days			
169	20-169	In front of Guest Lift FL.20	Normal	N/A	32 Days			
170	21-170	In front of Fireman Lift FL.21	Normal	N/A	32 Days			
171	21-171	Corridor FL.21	Normal	N/A	32 Days			
172	21-172	Corridor in front of room 2106	Normal	N/A	32 Days			
173	21-173	In front of Guest Lift FL.21	Normal	N/A	32 Days			
174	22-174	In front of Fireman Lift FL.22	Normal	N/A	32 Days			
175	22-175	Corridor FL.22	Normal	N/A	32 Days			
176	22-176	Corridor in front of room 2206	Normal	N/A	32 Days			
177	22-197	In front of Guest Lift FL.22	Normal	N/A	32 Days			
178	23-178	In front of Fireman Lift FL.23	Normal	N/A	32 Days			
179	23-179	Corridor FL.23	Normal	N/A	32 Days			
180	23-180	Corridor in front of room 2306	Normal	N/A	32 Days			
181	23-181	In front of Guest Lift FL.23	Normal	N/A	32 Days			
182	27-182	In front of Fireman Lift FL.24	Normal	N/A	32 Days			
183	24-183	Corridor FL.24	Normal	N/A	32 Days			
184	24-184	Corridor in front of room 2406	Normal	N/A	32 Days			
185	24-185	In front of Guest Lift FL.24	Normal	N/A	32 Days			
186	25-186	In front of Fireman Lift FL.25	Normal	N/A	32 Days			
187	25-187	Corridor FL.25	Normal	N/A	32 Days			
188	25-188	Corridor in front of room 2506	Normal	N/A	32 Days			
189	25-189	In front of Guest Lift FL.25	Normal	N/A	32 Days			
190	26-190	In front of Fireman Lift FL.26	Normal	N/A	32 Days			
191	26-191	Corridor FL.26	Normal	N/A	32 Days			
192	26-192	Corridor in front of room 2606	Normal	N/A	32 Days			
193	26-193	In front of Guest Lift FL.26	Normal	N/A	32 Days			
194	27-194	In front of Fireman Lift FL.27	Normal	N/A	32 Days			
195	27-195	Corridor in front of ST-2 FL.27	Normal	N/A	32 Days			
196	27-196	Corridor FL.27	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
197	27-177	Corridor in front of room 2706	Normal	N/A	32 Days			
198	27-198	Regency Club Counter Reception	Normal	N/A	92 Days			
199	27-199	Regency Club Balcony	Normal	N/A	32 Days			
200	27-200	Regency Club in front of Kitchen	Normal	N/A	32 Days			
201	27-201	In front of Guest Lift FL.27	Normal	N/A	32 Days			
202	28-202	In front of Fireman Lift FL.28	Normal	N/A	32 Days			
203	28-203	Corridor FL.28	Normal	N/A	32 Days			
204	28-204	Corridor in front of room 2806	Normal	N/A	32 Days			
205	28-205	In front of Guest Lift FL.28	Normal	N/A	32 Days			
206	29-206	In front of Fireman Lift FL.29	Normal	N/A	32 Days			
207	29-207	In front of Guest Lift FL.29	Normal	N/A	32 Days			
208	29-208	In front of Kitchen FL.29	Normal	N/A	32 Days			
209	29-209	Balcony Kitchen side FL.29	Out of license	No license	31 Days			Waiting for the Quotation
210	29-210	Front Balcony FL.29	Normal	N/A	31 Days			
211	29-211	Staircase up to FL.30	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
212	29-212	Spectrum Bar FL.29	Normal	N/A	93 Days			
213	29-213	Balcony Sofitel side FL.29	Out of license	No license	27 Days			Waiting for the Quotation
214	30-214	Glass floor FL.30	Out of license	No license	27 Days			Waiting for the Quotation
215	30-215	Spectrum FL. 30	Normal	N/A	27 Days			
216	30-216	Spectrum Bar FL.30	Normal	N/A	27 Days			
217	31-217	In front of Lift Control room FL.31	Normal	N/A	27 Days			
218	31-218	Spectrum FL.31	Normal	N/A	27 Days			

Location: Parking and Retail

1	FLM 01	In front of lift FL.M	Normal		98 Days			
2	FLM 02	Parking FL.M	Normal		98 Days			
3	FLM 03	Parking FL.M (Trendy Side)	Normal		98 Days			
4	FLM 04	Parling FL.M (Loading Side)	Damaged		98 Days	The Allez (Retail Office) acknowledged		
5	FL2 01	In front of lift FL.2	Normal		98 Days			
6	FL2 02	Parking FL.2	Normal		98 Days			
7	FL2 03	Parking FL.2 (Trendy Side)	Normal		98 Days			
8	FL2 04	Parling FL.2 (Loading Side)	Normal		98 Days			
9	FL2A 01	In front of lift FL.2A	Normal		98 Days			
10	FL2A 02	Parking FL.2A	Normal		98 Days			
11	FL2A 03	Parking FL.2A (Trendy Side)	Normal		98 Days			
12	FL2A 04	Parling FL.2A (Loading Side)	Normal		98 Days			
13	FL3 01	In front of lift FL.3	Normal		98 Days			
14	FL3 02	Parking FL.3	Normal		98 Days			
15	FL3 03	Parking FL.3 (Trendy Side)	Normal		98 Days			
16	FL3 04	Parling FL.3 (Loading Side)	Normal		98 Days			
17	FL3A 01	In front of lift FL.3A	Normal		98 Days			
18	FL3A 02	Parking FL.3A	Normal		98 Days			
19	FL3A 03	Parking FL.3A (Trendy Side)	Not clear		98 Days	The Allez (Retail Office) acknowledged		
20	FL3A 04	Parling FL.3A (Loading Side)	Normal		98 Days			
21	FL4 01	In front of lift FL.4	Normal		98 Days			
22	FL4 02	Parking FL.4	Normal		98 Days			
23	FL4 03	Parking FL.4 (Trendy Side)	Normal		98 Days			
24	FL4 04	Parling FL.4 (Loading Side)	Normal		98 Days			
25	FL4A 01	Parking FL.4A (Trendy Side)	Normal		98 Days			
26	FL4A 02	Parling FL.4A (Loading Side)	Normal		98 Days			
27	FL4A 03	Parking FL.4A	Normal		98 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
28	FL4A 04	In front of lift FL.4A	Normal		98 Days			
29	FL1 01	BOBO entrance 1	Normal		82 Days			
30	FL1 02	BOBO entrance 2	Normal		82 Days			
31	FL1 03	Under Retail Escalator	Normal		82 Days			
32	FL2 04	Retail Entrance from Parking FL.2	Normal		82 Days			
33	FL2 03	Coffee Club FL.2	Normal		82 Days			
34	FL2 06	Escalator FL.2	Normal		82 Days			
35	FL3 01	In front of lift P5, P6 FL.3	Normal		82 Days			
36	FL3 03	Let's Relax Spa FL.3	Normal		82 Days			
37	FL3 04	Escalator FL.3	Normal		82 Days			
38	FL3 05	In front of ST-1 FL.3	Normal		82 Days			
39	BTS1	Hotel Entrance from BTS	Normal		98 Days			
40	BTS2	BTS Skywalk	Normal		98 Days			
41	BTS3	BTS Entrance	Not clear		98 Days	The Allez (Retail Office) acknowledged		

Summary	
Status	Amount
Normal	241
Damaged	12
Not clear	3
Out of license	3
Total	259

Additional comments:
1. SECOM already sent the report of all damaged CCTVs and still waiting for the final quotation to fix it.
2. Out of license CCTVs, still have camera but due to over CCTV IP point from budget requested since beginning. 3 of them were cut off only signal. Waiting for quotation to re-license.
3. Comment from Khun Sammy, there must be additional CCTV at Fireman lift landing on L floor. Already added to the next CCTV installation project together with fix list.
4. Comments from Khun Bruce and Khun Ian (Hyatt Global Security) that there must be additional CCTVs at POS system which is we miss 2 points at Market Cafe. Already added to the next CCTV installation project together with fix list.

Checked By

(.....Panuwich T.....)

Position: Security Officer

Date...26.../...02.../...2023...

Reviewed By

(.....Panuwich T.....)

Security Manager

Date...26.../...02.../...2023...

Acknowledged By

(.....)

Chief Engineer

Date...../...../.....

Fire & Life Safety Monthly Checklist

Month/Year: February 2023

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สวมเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
31	Hot Water Tank Room	N	N	N	N/A	1	N/A	N/A	N/A	N			Hot Water Tank 1 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Hot Water Tank 2 FL.31	N	
30	Spectrum Store					1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.30	N	
	Automatic Slide Door										1	N/A	Exit Stair ST-1 FL.29	N	
29	Back Kitchen					N/A	N/A	2	N/A	N			Exit Stair ST-2 (1) FL.29	N	
	Front Kitchen										2	N	Exit Stair ST-2 (2) FL.29	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.29	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Pantry FL.29	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.28	N	
	Guest Lift										1	N	Exit Stair ST-2 FL.28	N	
	Toilet										1	N	MEP FL.28	N	
28	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.28	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.27	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.27	D	Battery Issue
27	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.27	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.27	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.26	N	
	RC Lounge										2	N	Exit Stair ST-2 FL.26	N	
	Kitchen					1	N/A	N/A	N/A	N	1	N	MEP FL.26	N	
26	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.26	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.25	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.25	N	
25	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.25	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.25	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.24	N	
24	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.24	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.24	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.24	N	
23	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.23	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.23	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.23	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.23	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
22	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.22	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.22	N	
21	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.22	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.22	D	Battery Issue
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.21	N	
20	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.21	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.21	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.21	N	
19	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.20	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.20	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.20	N	
18	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.20	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.19	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.19	N	
17	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.19	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.19	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.18	N	
16	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.18	D	Battery Issue
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.18	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.18	N	
15	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.17	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.17	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.17	N	
14	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.17	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.16	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.16	N	
12	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.16	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.16	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.15	N	
11	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.15	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.15	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.15	N	
10	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.14	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.14	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.14	N	
9	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.14	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.12	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.12	N	
	ST-1	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	MEP FL.12	D	Battery Issue

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
8	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.12	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.11	N	
7	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.11	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.11	D	Battery Issue
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.11	N	
6A	Cooling Tower	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.10	N	
6	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.10	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	MEP FL.10	N	
	ST-4										1	N	Pantry FL.10	N	
	Pool Entrance (Lift)										1	N	Exit Stair ST-1 FL.9	N	
	Pool Entrance (Fitness)										1	N	Exit Stair ST-2 FL.9	N	
	Lift S1-S2	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.9	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.9	N	
	Bar					1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.8	N	
5A	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.8	N	
5	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	2	N	MEP FL.8	N	
	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	2	N	Pantry FL.8	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-1 FL.7	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.7	N	
	AV Room (Ballroom 4)					1	N/A	N/A	N/A	N			MEP FL.7	N	
	Regency Ballroom										9	N	Pantry FL.7	N	
	Regency 1-4										8	N	Exit Stair ST-1 FL.6A	N	
	Guest Lift										1	N	Exit Stair ST-2 FL.6A	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.6	N	
	BQ Kitchen					N/A	N/A	3	3	N	1	N	Exit Stair ST-2 FL.6	N	
4A	Foyer					N/A	N/A	1	1	N			Exit Stair ST-4 FL.6	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.6	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	D			Front Fireman Lift FL.6	N	
4A	Event Office										2	N	Fireman Lift Entrance FL.6	N	
4	ST-1 Sale Office	N	N	N/A	N/A	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-1 FL.5A	N	
	ST-2										4	N	Exit Stair ST-2 FL.5A	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-4 FL.5A	N	
	ST-4										3	N	Corridor FL.5A	N	
	Lift P5-P6	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.5A	N	
	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			AV Room FL.5A	N	
	Chiller Room					1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.5	N	
	Left Kitchen					N/A	N/A	2	2	N			Exit Stair ST-2 FL.5	N	
	Right Kitchen					N/A	N/A	2	2	N			Exit Stair ST-3 FL.5	N	
	Inside Kitchen					N/A	N/A	1	1	N	2	N	Exit Stair ST-4 FL.5	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
	MC										9	N	MEP FL.5	N	
	Hostess										2	N	BOH Regency 1 FL.5	N	
	Toilet										1	N	BOH Regency 2 FL.5	N	
4PK	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N			BOH Regency 3 FL.5	N	
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	Fireman Lift FL.5	N	
3A	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	Service Lift FL.5	N	
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-1 FL.4A	N	
3	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.4A	N	
3PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-3 FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-4 FL.4A	N	
2A	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exec. Office 1 FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exec. Office 2 FL.4A	N	
2	Lift Fireman	N	N	N/A	N/A	1	N/A	N/A	N/A	N			Loading Side FL.4A	N	
2PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Trendy Side FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Electric Room FL.4A	N	
M	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-1 FL.4	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-2 FL.4	N	
	Front MEP Room	N	N	N/A	N/A								Exit Stair ST-3 FL.4	D	Battery Issue
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-4 FL.4	N	
L	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exec. Office FL.4	N	
	ST-2										1	N	MARCOM Office FL.4	N	
	ST-4										1	N	Chiller Room 1 FL.4	N	
	Control Room					1	N/A	N/A	N/A	N			Chiller Room 2 FL.4	N	
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.4	N	
	Flower Room	N	N	N/A	N/A	1	N/A	N/A	N/A	N			Fireman Lift FL.4	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Service Lift FL.4	N	
	LPG Gas Station					2	N/A	N/A	N/A	N			Loading Side FL.4	N	
	Lobby Door (S)										1	N	Trendy Side FL.4	D	Battery Issue
	Front Parking Lift										2	N	Exit Stair ST-1 FL.3A	N	
	Loading										4	N	Exit Stair ST-2 FL.3A	N	
	ST-1 Engineer	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-4 FL.3A	N	
	ST-2 Locker	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Loading Side FL.3A	N	
	ST-3 General Store	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Trendy Side FL.3A	N	
	ST-4 Fire pump	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.3	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-3 FL.3	N	
	Canteen Kitchen					N/A	N/A	1	1	N			Exit Stair ST-4 FL.3	N	
	Learning Center					1	N/A	N/A	N/A	N			MEP FL.3	N	
	Male Locker										2	N	MDB 1 FL.3	N	
	Female Locker										2	N	MDB 2 FL.3	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ					
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ						
B	Canteen										4	N	Generator FL.3	N						
	HK										1	N	Loading Side FL.3	D	Battery Issue					
	Uniform										1	N	Trendy Side FL.3	D	Battery Issue					
	Operator										1	N	Serve Lift FL.3	N/A	Uninstalled					
	HR										1	N	Fireman Lift FL.3	N						
	GC										2	N	Exit Stair ST-1 FL.2A	N						
	Finance Office										1	N	Exit Stair ST-2 FL.2A	N						
	Engineer Office										1	N	Exit Stair ST-4 FL.2A	N						
	Engineer Workshop										2	N	Loading Side FL.2A	N						
	Front Hygene Office										2	N	Trendy Side FL.2A	N						
	Main Kitchen Corridor										2	N	Exit Stair ST-1 FL.2	N						
	Total	111									119	0	12	10		183		Exit Stair ST-2 FL.2	N	
																		Exit Stair ST-3 FL.2	N	
																		Exit Stair ST-4 FL.2	N	
																		MEP FL.2	N	
																		Loading Side FL.2	N	
																		Trendy Side FL.2	D	Battery Issue
																		Service Lift FL.2	N/A	Unable to check due to obstruction by stored items
																		Fireman Lift FL.2	N	
																		Exit Stair ST-1 FL.M	N	
																		Exit Stair ST-2 FL.M	N	
																		Exit Stair ST-3 FL.M	N	
																		Exit Stair ST-4 FL.M	N	
																		Front MEP FL.M	N	
																		MEP FL.M	D	Battery Issue
																		Loading Side FL.M	N	
																		Trendy Side FL.M	N	
																		Exit Stair ST-1 FL.L	N	
																		Exit Stair ST-2 FL.L	N	
																		Exit Stair ST-3 FL.L	N	
																		Exit Stair ST-4 FL.L	N	
																		Control Room 1 FL.L	N	
																		Control Room 2 FL.L	N	
																		Fireman Lift FL.L	N	
																		Discharge Fireman Lift FL.L	N	
																		Front Service Lift FL.L	N	
																		Exit Stair ST-1 FL.B	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	

Condition	Summary				
	Fire Hose Cabinet	Fire Extinguisher	Fire Blanket	Fire Exit Sign	Emergency Light
Total	111	131	10	183	215
Normal	98	130	10	183	199
Damage	0	1	0	0	14
Used	0	0	0	0	0
Lost	0	0	0	0	0
N/A	13	0	0	0	2

Exit Stair ST-2 FL.B	N	
Exit Stair ST-3 FL.B	N	
Exit Stair ST-4 (1) FL.B	N	
Exit Stair ST-4 (2) FL.B	N	
MEP FL.B	N	
Fireman Lift FL.B	N	
Male Staff Locker 1	N	
Male Staff Locker 2	N	
Female Staff Locker	N	
Front HK Office FL.B	N	
Canteen 1 FL.B	N	
Canteen 2 FL.B	N	
TV Corner FL.B	N	
Corridor front Canteen	N	
Lerning Center	D	Battery Issue
HR Office	N	
Finance Office	D	Battery Issue
Workshop Entrance	D	One night bulb is broken
Front Cashier	N	
Front FB Office	N	
FB Office	N	
Front General Store	N	
Cold Kitchen Entrance	N	
Front Hygene Office	N	
Pump Room	N	
Compressor Room	N	
Firepump Room	N	
Server Room	N	
Total	215	

Prepared By

(Panuwich Thammathada)
Security Manager
Date 26/00/2023

Acknowledged By

(.....)
Chief Engineer
Date...../...../.....








Fire Cart Monthly Checklist

Month/Year: February 2023

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
1	Fireman Suit Cabinet		1	N	
2	Fire Cart Cabinet		1	N	
3	Fireman Suit		4 Suit	N	
4	Fireman Helmet		4 Pcs.	N	
5	Fireman Hood		N/A	N/A	Need to Order
6	SCBA		2 Set	N	200psi/250psi
7	SCBA Mask		2 Set	N	
8	Fire Fighting Nozzle		N/A	N/A	Pending
9	Fire Hose 1.5"		2 Pcs.	N	
10	Rope		2 Roll	N	

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
11	Axe		2 Pcs.	N	
12	Steel Bolt Cutter		2 Pcs.	N	
13	3-Ways Fire Hydrant Connection		1 Pcs.	N	
14	Spinal Board		1 Pcs.	N	
15	Head Immobilizer		2 Set	N	
16	Scoop Stretcher		1 Pcs.	N	
17	Oxygen Tank		2 Set	N	

Checked By

(Panuwich T.)
Security Manager
Date 26/02/2023

Reviewed By

(Panuwich T.)
Security Manager
Date 26/02/2023

Acknowledged By

(.....)
Chief Engineer
Date/...../.....

CCTV System Monthly Report								
Month of Report:		March 2023						
Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
Location: Hotel								
1	B-001	Server room (IT)	Normal	N/A	92 Days			
2	B-002	In front of Engineer office	Normal	N/A	62 Days			
3	B-003	In front of Engineer Store	Normal	N/A	62 Days			
4	B-004	Cashier Drop Safe	Normal	N/A	62 Days			
5	B-005	Cashier Account room	Normal	N/A	62 Days			
6	B-006	Finance Store	Normal	N/A	62 Days			
7	B-007	In front of Lift F1,F2	Normal	N/A	62 Days			
8	B-008	Corridor in front of Canteen	Normal	N/A	62 Days			
9	B-009	Canteen room	Normal	N/A	62 Days			
10	B-010	Canteen room	Normal	N/A	62 Days			
11	B-011	Corridor in front of Staff Locker	Normal	N/A	62 Days			
12	B-012	Corridor in front of Uniform room	Normal	N/A	62 Days			
13	B-013	Corridor in front of Staff Locker	Normal	N/A	62 Days			
14	B-014	Staff Rest room	Normal	N/A	62 Days			
15	B-015	Staff Rest room	Normal	N/A	62 Days			
16	B-016	Corridor in front of HK Office	Normal	N/A	62 Days			
17	B-017	Corridor in front of Fire pump room	Normal	N/A	62 Days			
18	B-018	HR Office	Normal	N/A	62 Days			
19	B-019	In front of Lift S1,S2	Normal	N/A	62 Days			
20	B-020	Corridor in front of Main Kitchen	Normal	N/A	62 Days			
21	B-021	Corridor in front of F&B Store	Normal	N/A	62 Days			
22	B-022	Corridor in front of F&B Office	Normal	N/A	62 Days			
23	B-023	Uniform room	Normal	N/A	62 Days			
24	L-024	Entrance Lobby drop off	Normal	N/A	62 Days			
25	L-025	Lobby drop off	Normal	N/A	62 Days			
26	L-026	360 rotating camera at Lobby drop off	Damaged	Wirring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
27	L-027	Exit Lobby drop off	Normal	N/A	62 Days			
28	L-028	In front of Car parking F.I.L	Normal	N/A	61 Days			
29	L-029	In front of Car parking F.I.L 2	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
30	L-030	In front of Lift P5-P6	Normal	N/A	62 Days			
31	L-031	Entrance Lobby	Normal	N/A	62 Days			
32	L-032	Concierge room	Normal	N/A	62 Days			
33	L-033	In front of Concierge room	Normal	N/A	62 Days			
34	L-034	Stair 1 Floor L	Normal	N/A	62 Days			
35	L-035	360 rotating camera at Lobby Lounge	Normal	N/A	92 Days			
36	L-036	Lobby Lounge	Normal	N/A	62 Days			
37	L-037	Counter Front office (Right)	Normal	N/A	62 Days			
38	L-038	Office Front Department	Normal	N/A	62 Days			
39	L-039	Safe room	Normal	N/A	62 Days			
40	L-040	Counter Front office (Left)	Normal	N/A	62 Days			
41	L-041	In front of Lift P1-P4	Normal	N/A	62 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
42	L-042	Walkway to Parking Lift Floor L	Normal	N/A	62 Days			
43	L-043	In front of Lift PK1-2	Normal	N/A	62 Days			
44	L-044	Carpark Floor L1	Normal	N/A	62 Days			
45	L-045	Carpark Floor L2	Normal	N/A	62 Days			
46	L-046	Carpark Entrance	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
47	L-047	Gas Station	Normal	N/A	32 Days			
48	L-048	Under Retail Escalator	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
49	L-049	ST-3 Discharge Floor L	Normal	N/A	32 Days			
50	L-050	Parking for Rider under Escalator	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
51	L-051	Cashier point	Normal	N/A	32 Days			
52	L-052	Loading	Not clear	N/A	32 Days			Need to adjust focus of camera
53	L-053	Control room	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
54	L-054	In front of Control room	Normal	N/A	32 Days			
55	L-055	In front of Lift S1-2 FL.L	Normal	N/A	32 Days			
56	L-056	Time Keeper Entrance	Normal	N/A	32 Days			
57	L-057	360 rotating camera at TK	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
58	L-058	Loading Gas Station side	Normal	N/A	32 Days			
59	L-059	Parking Exit	Normal	N/A	32 Days			
60	P5-060	Lift P5	Normal	N/A	32 Days			
61	P6-061	Lift P6	Normal	N/A	32 Days			
62	P1-062	Lift P1	Normal	N/A	32 Days			
63	P2-063	Lift P2	Normal	N/A	32 Days			
64	P3-064	Lift P3	Normal	N/A	32 Days			
65	P4-065	Lift P4	Normal	N/A	32 Days			
66	P7-066	Fireman Lift 1	Normal	N/A	32 Days			
67	P8-067	Fireman Lift 2	Normal	N/A	31 Days			
68	S2-068	Service Lift 1	Normal	N/A	32 Days			
69	S1-069	Service Lift 2	Normal	N/A	32 Days			
70	M-070	In front of ST-2 FL.M	Normal	N/A	32 Days			
71	M-071	In front of ST-4 FL.M	Normal	N/A	32 Days			
72	M-072	Corridor In front of ST-3 FL.M (Retail)	Normal	N/A	32 Days			
73	M-073	In front of ST-2 FL.2 (Retail)	Normal	N/A	32 Days			
74	M-074	In front of The Coffee club (Retail)	Normal	N/A	32 Days			
75	2-075	In front of ST-4 FL.2	Normal	N/A	32 Days			
76	2-076	In front of Service Lift FL.2	Normal	N/A	32 Days			
77	2A-077	Car parking FL.2A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
78	2A-078	In front of ST-4 FL.2A	Normal	N/A	32 Days			
79	3-079	In front of ST-2 FL.3	Normal	N/A	32 Days			
80	3-080	In front of Lift Service FL.3	Normal	N/A	32 Days			
81	3-081	In front of ST-4 FL.3	Normal	N/A	32 Days			
82	3A-082	Car parking FL.3A	Normal	N/A	32 Days			
83	3A-083	In front of ST-4 FL.3A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
84	4-084	Balcony entrance	Normal	N/A	32 Days			
85	4-085	Sukhumvit Gallery	Normal	N/A	32 Days			
86	4-086	In front of Kitchen FL.4	Normal	N/A	32 Days			
87	4-087	In front of Lift P1-P4 FL.4	Normal	N/A	32 Days			
88	4-088	In front of Firman Lift FL.4	Damaged	N/A	32 Days	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
89	4-089	In front of ST-2 FL.4	Normal	N/A	32 Days			
90	4-090	Inside Market Café	Normal	N/A	32 Days			
91	4-091	In front of Service Lift FL.4	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
92	4-092	Kitchen Exit FL.4	Normal	N/A	32 Days			
93	4-093	In front of ST-4 FL.4	Normal	N/A	32 Days			
94	4A-094	Car parking FL.4A	Normal	N/A	32 Days			
95	4-095	In front of ST-4 FL.4	Normal	N/A	32 Days			
96	5-096	Foyer front of ST-1 FL.5	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
97	5-097	In front of Escalator FL.5	Normal	N/A	32 Days			
98	5-098	In front of ST-1 FL.5	Normal	N/A	32 Days			
99	5-099	360 rotating camera at foyer FL.5	Damaged	Rotating motor broken	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
100	5-100	In front of Lift P1-4	Normal	N/A	32 Days			
101	5-101	In front of ST-2 FL.5 (Foyer)	Normal	N/A	32 Days			
102	5-102	Between ST-2 and Ballroom	Normal	N/A	32 Days			
103	5-103	Ballroom	Normal	N/A	32 Days			
104	5-104	In front of BQ store	Normal	N/A	32 Days			
105	5-105	In front of service lift FL.5	Normal	N/A	32 Days			
106	5-106	In front of ST-3 FL.5	Normal	N/A	31 Days			
107	5A-107	Corridor BOH behind Ballroom	Normal	N/A	32 Days			
108	5A-108	In front of service lift FL.5A	Normal	N/A	32 Days			
109	6-109	Inside Fire Exit ST-1 FL.6	Normal	N/A	32 Days			
110	6-110	In front of Fitness	Normal	N/A	32 Days			
111	6-111	In front of Male Locker FL.6	Normal	N/A	32 Days			
112	6-112	In front of Female Locker FL.6	Normal	N/A	32 Days			
113	6-113	In front of Lift P1-4 FL.6	Normal	N/A	32 Days			
114	6-114	In front of Fireman lift Entrance FL.6	Normal	N/A	32 Days			
115	6-115	In front of Fireman Lift FL.6	Normal	N/A	32 Days			
116	6-116	Pool Bar FL.6	Normal	N/A	92 Days			
117	6-117	In front of Service lift FL.6	Normal	N/A	32 Days			
118	7-118	In front of Fireman Lift FL.7	Normal	N/A	32 Days			
119	7-119	Corridor FL.7	Normal	N/A	32 Days			
120	7-120	Corridor in front of room 706	Normal	N/A	32 Days			
121	7-121	In front of Guest Lift FL.7	Normal	N/A	32 Days			
122	8-122	In front of Fireman Lift FL.8	Normal	N/A	32 Days			
123	8-123	Corridor FL.8	Normal	N/A	32 Days			
124	8-124	Corridor in front of room 806	Normal	N/A	32 Days			
125	8-125	In front of Guest Lift FL.8	Normal	N/A	32 Days			
126	10-126	In front of Fireman Lift FL.10	Normal	N/A	32 Days			
127	9-127	Corridor FL.9	Normal	N/A	32 Days			
128	9-128	Corridor in front of room 906	Normal	N/A	32 Days			
129	9-129	In front of Guest Lift FL.9	Normal	N/A	32 Days			
130	9-130	In front of Fireman Lift FL.9	Normal	N/A	32 Days			
131	10-131	Corridor FL.10	Normal	N/A	32 Days			
132	10-132	Corridor in front of room 1006	Normal	N/A	32 Days			
133	10-133	In front of Guest Lift FL.10	Normal	N/A	32 Days			
134	11-134	In front of Fireman Lift FL.11	Normal	N/A	32 Days			
135	11-135	Corridor FL.11	Normal	N/A	32 Days			
136	11-136	Corridor in front of room 1106	Normal	N/A	32 Days			
137	11-137	in front of Guest Lift FL.11	Normal	N/A	32 Days			
138	12-138	In front of Fireman Lift FL.12	Normal	N/A	32 Days			
139	12-139	Corridor FL.12	Normal	N/A	32 Days			
140	12-140	Corridor in front of room 1206	Normal	N/A	32 Days			
141	12-141	In front of Guest Lift FL.12	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
142	14-142	In front of Fireman Lift FL.14	Normal	N/A	32 Days			
143	14-143	Corridor FL.14	Normal	N/A	32 Days			
144	14-144	Corridor in front of room 1406	Normal	N/A	32 Days			
145	14-145	In front of Guest Lift FL.14	Normal	N/A	32 Days			
146	15-146	In front of Fireman Lift FL.15	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
147	15-147	Corridor FL.15	Normal	N/A	32 Days			
148	15-148	Corridor in front of room 1506	Normal	N/A	32 Days			
149	15-149	In front of Guest Lift FL.15	Normal	N/A	32 Days			
150	16-150	In front of Fireman Lift FL.16	Normal	N/A	32 Days			
151	16-151	Corridor FL.16	Normal	N/A	32 Days			
152	16-152	Corridor in front of room1606	Normal	N/A	32 Days			
153	16-153	In front of Guest Lift FL.16	Normal	N/A	32 Days			
154	17-154	In front of Fireman Lift FL.17	Normal	N/A	32 Days			
155	17-155	Corridor FL.17	Normal	N/A	32 Days			
156	17-156	Corridor in front of room 1706	Normal	N/A	32 Days			
157	17-157	In front of Guest Lift FL.17	Normal	N/A	32 Days			
158	18-158	In front of Fireman Lift FL.18	Normal	N/A	32 Days			
159	18-159	Corridor FL.18	Normal	N/A	32 Days			
160	18-160	Corridor in front of room 1806	Normal	N/A	32 Days			
161	18-161	In front of Guest Lift FL.18	Normal	N/A	32 Days			
162	19-162	In front of Lift Fireman Lift FL.19	Normal	N/A	32 Days			
163	19-163	Corridor FL.19	Normal	N/A	32 Days			
164	19-164	In front of Guest Lift FL.19	Normal	N/A	32 Days			
165	19-165	Corridor in front of room 1906	Normal	N/A	32 Days			
166	20-166	In front of Fireman Lift FL.20	Normal	N/A	32 Days			
167	20-167	Corridor FL.20	Normal	N/A	32 Days			
168	20-168	Corridor in front of room 2006	Normal	N/A	32 Days			
169	20-169	In front of Guest Lift FL.20	Normal	N/A	32 Days			
170	21-170	In front of Fireman Lift FL.21	Normal	N/A	32 Days			
171	21-171	Corridor FL.21	Normal	N/A	32 Days			
172	21-172	Corridor in front of room 2106	Normal	N/A	32 Days			
173	21-173	In front of Guest Lift FL.21	Normal	N/A	32 Days			
174	22-174	In front of Fireman Lift FL.22	Normal	N/A	32 Days			
175	22-175	Corridor FL.22	Normal	N/A	32 Days			
176	22-176	Corridor in front of room 2206	Normal	N/A	32 Days			
177	22-197	In front of Guest Lift FL.22	Normal	N/A	32 Days			
178	23-178	In front of Fireman Lift FL.23	Normal	N/A	32 Days			
179	23-179	Corridor FL.23	Normal	N/A	32 Days			
180	23-180	Corridor in front of room 2306	Normal	N/A	32 Days			
181	23-181	In front of Guest Lift FL.23	Normal	N/A	32 Days			
182	27-182	In front of Fireman Lift FL.24	Normal	N/A	32 Days			
183	24-183	Corridor FL.24	Normal	N/A	32 Days			
184	24-184	Corridor in front of room 2406	Normal	N/A	32 Days			
185	24-185	In front of Guest Lift FL.24	Normal	N/A	32 Days			
186	25-186	In front of Fireman Lift FL.25	Normal	N/A	32 Days			
187	25-187	Corridor FL.25	Normal	N/A	32 Days			
188	25-188	Corridor in front of room 2506	Normal	N/A	32 Days			
189	25-189	In front of Guest Lift FL.25	Normal	N/A	32 Days			
190	26-190	In front of Fireman Lift FL.26	Normal	N/A	32 Days			
191	26-191	Corridor FL.26	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
192	26-192	Corridor in front of room 2606	Normal	N/A	32 Days			
193	26-193	In front of Guest Lift FL.26	Normal	N/A	32 Days			
194	27-194	In front of Fireman Lift FL.27	Normal	N/A	32 Days			
195	27-195	Corridor in front of ST-2 FL.27	Normal	N/A	32 Days			
196	27-196	Corridor FL.27	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
197	27-177	Corridor in front of room 2706	Normal	N/A	32 Days			
198	27-198	Regency Club Counter Reception	Normal	N/A	91 Days			
199	27-199	Regency Club Balcony	Normal	N/A	32 Days			
200	27-200	Regency Club in front of Kitchen	Normal	N/A	32 Days			
201	27-201	In front of Guest Lift FL.27	Normal	N/A	32 Days			
202	28-202	In front of Fireman Lift FL.28	Normal	N/A	32 Days			
203	28-203	Corridor FL.28	Normal	N/A	32 Days			
204	28-204	Corridor in front of room 2806	Normal	N/A	32 Days			
205	28-205	In front of Guest Lift FL.28	Normal	N/A	32 Days			
206	29-206	In front of Fireman Lift FL.29	Normal	N/A	32 Days			
207	29-207	In front of Guest Lift FL.29	Normal	N/A	32 Days			
208	29-208	In front of Kitchen FL.29	Normal	N/A	32 Days			
209	29-209	Balcony Kitchen side FL.29	Out of license	No license	31 Days			Waiting for the Quotation
210	29-210	Front Balcony FL.29	Normal	N/A	31 Days			
211	29-211	Staircase up to FL.30	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
212	29-212	Spectrum Bar FL.29	Normal	N/A	92 Days			
213	29-213	Balcony Sofitel side FL.29	Out of license	No license	32 Days			Waiting for the Quotation
214	30-214	Glass floor FL.30	Out of license	No license	32 Days			Waiting for the Quotation
215	30-215	Spectrum FL. 30	Normal	N/A	32 Days			
216	30-216	Spectrum Bar FL.30	Normal	N/A	32 Days			
217	31-217	In front of Lift Control room FL.31	Normal	N/A	32 Days			
218	31-218	Spectrum FL.31	Normal	N/A	32 Days			

Location: Parking and Retail

1	FLM 01	In front of lift FL.M	Normal		117 Days			
2	FLM 02	Parking FL.M	Normal		117 Days			
3	FLM 03	Parking FL.M (Trendy Side)	Normal		117 Days			
4	FLM 04	Parling FL.M (Loading Side)	Normal		117 Days			
5	FL2 01	In front of lift FL.2	Normal		117 Days			
6	FL2 02	Parking FL.2	Normal		117 Days			
7	FL2 03	Parking FL.2 (Trendy Side)	Normal		117 Days			
8	FL2 04	Parling FL.2 (Loading Side)	Normal		117 Days			
9	FL2A 01	In front of lift FL.2A	Normal		117 Days			
10	FL2A 02	Parking FL.2A	Normal		117 Days			
11	FL2A 03	Parking FL.2A (Trendy Side)	Normal		117 Days			
12	FL2A 04	Parling FL.2A (Loading Side)	Normal		117 Days			
13	FL3 01	In front of lift FL.3	Normal		117 Days			
14	FL3 02	Parking FL.3	Normal		117 Days			
15	FL3 03	Parking FL.3 (Trendy Side)	Normal		117 Days			
16	FL3 04	Parling FL.3 (Loading Side)	Normal		117 Days			
17	FL3A 01	In front of lift FL.3A	Normal		117 Days			
18	FL3A 02	Parking FL.3A	Normal		117 Days			
19	FL3A 03	Parking FL.3A (Trendy Side)	Not clear		117 Days	The Allez (Retail Office) acknowledged		
20	FL3A 04	Parling FL.3A (Loading Side)	Normal		117 Days			
21	FL4 01	In front of lift FL.4	Normal		98 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
22	FL4 02	Parking FL.4	Normal		98 Days			
23	FL4 03	Parking FL.4 (Trendy Side)	Normal		98 Days			
24	FL4 04	Parling FL.4 (Loading Side)	Normal		98 Days			
25	FL4A 01	Parking FL.4A (Trendy Side)	Normal		98 Days			
26	FL4A 02	Parling FL.4A (Loading Side)	Normal		98 Days			
27	FL4A 03	Parking FL.4A	Normal		98 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
28	FL4A 04	In front of lift FL.4A	Normal		98 Days			
29	FL1 01	BOBO entrance 1	Normal		83 Days			
30	FL1 02	BOBO entrance 2	Normal		83 Days			
31	FL1 03	Under Retail Escalator	Normal		83 Days			
32	FL2 04	Retail Entrance from Parking FL.2	Normal		83 Days			
33	FL2 03	Coffee Club FL.2	Normal		83 Days			
34	FL2 06	Escalator FL.2	Normal		83 Days			
35	FL3 01	In front of lift P5, P6 FL.3	Normal		83 Days			
36	FL3 03	Let's Relax Spa FL.3	Normal		83 Days			
37	FL3 04	Escalator FL.3	Normal		83 Days			
38	FL3 05	In front of ST-1 FL.3	Normal		83 Days			
39	BTS1	Hotel Entrance from BTS	Normal		98 Days			
40	BTS2	BTS Skywalk	Normal		98 Days			
41	BTS3	BTS Entrance	Not clear		98 Days	The Allez (Retail Office) acknowledged		

Summary	
Status	Amount
Normal	242
Damaged	11
Not clear	3
Out of license	3
Total	259

Additional comments:

1. SECOM already sent the report of all damaged CCTVs and still waiting for the final quotation to fix it.
2. Out of license CCTVs, still have camera but due to over CCTV IP point from budget requested since beginning. 3 of them were cut off only signal. Waiting for quotation to re-license.
3. Comment from Khun Sammy, there must be additional CCTV at Fireman lift landing on L floor. Already added to the next CCTV installation project together with fix list.
4. Comments from Khun Bruce and Khun Ian (Hyatt Global Security) that there must be additional CCTVs at POS system which is we miss 2 points at Market Cafe. Already added to the next CCTV installation project together with fix list.
5. The quotation was received on 28 February 2023. But they called to increase the price on 9 March 2023. Khun Sukhunthip (Purchasing Mgr.) asked SECOM to conduct the meeting with hotel about price increase issue.

Checked By

(.....Anuthida K.....)

Position: Security Officer
Date: 08/03/2023..

Reviewed By

(Thanakorn A)

Security Manager
Date: 28/03/2023..

Acknowledged By

(.....)

Chief Engineer
Date:/...../.....

Fire & Life Safety Monthly Checklist

Month/Year: March 2023

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
31	Hot Water Tank Room	N	N	N	N/A	1	N/A	N/A	N/A	N			Hot Water Tank 1 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Hot Water Tank 2 FL.31	N	
30	Spectrum Store					1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.30	N	
	Automatic Slide Door										1	N	Exit Stair ST-1 FL.29	N	
29	Back Kitchen					N/A	N/A	2	N/A	N			Exit Stair ST-2 (1) FL.29	N	
	Front Kitchen										2	N	Exit Stair ST-2 (2) FL.29	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.29	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Pantry FL.29	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.28	N	
	Guest Lift										1	N	Exit Stair ST-2 FL.28	N	
	Toilet										1	N	MEP FL.28	N	
28	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.28	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.27	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.27	N	
27	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.27	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.27	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.26	N	
	RC Lounge										2	N	Exit Stair ST-2 FL.26	N	
	Kitchen					1	N/A	N/A	N/A	N	1	N	MEP FL.26	N	
26	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.26	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.25	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.25	N	
25	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.25	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.25	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.24	N	
24	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.24	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.24	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.24	N	
23	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.23	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.23	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.23	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.23	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหนัคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
22	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.22	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.22	N	
21	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.22	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.22	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.21	N	
20	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.21	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.21	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.21	N	
19	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.20	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.20	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.20	N	
18	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.20	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.19	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.19	N	
17	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.19	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.19	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.18	N	
16	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.18	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.18	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.18	N	
15	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.17	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.17	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.17	N	
14	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.17	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.16	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.16	N	
12	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.16	D	Battery Issue
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.16	D	Battery Issue
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.15	N	
11	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.15	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.15	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.15	N	
10	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.14	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.14	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.14	D	Battery Issue
9	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.14	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.12	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.12	N	
	ST-1	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	MEP FL.12	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหนัคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
8	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.12	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.11	N	
7	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.11	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.11	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.11	N	
6A	Cooling Tower	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.10	N	
6	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.10	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	MEP FL.10	N	
	ST-4										1	N	Pantry FL.10	N	
	Pool Entrance (Lift)										1	N	Exit Stair ST-1 FL.9	N	
	Pool Entrance (Fitness)										1	N	Exit Stair ST-2 FL.9	N	
	Lift S1-S2	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.9	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.9	N	
	Bar					1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.8	N	
5A	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.8	N	
5	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	2	N	MEP FL.8	N	
	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	2	N	Pantry FL.8	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-1 FL.7	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.7	N	
	AV Room (Ballroom 4)					1	N/A	N/A	N/A	N			MEP FL.7	D	Battery Issue
	Regency Ballroom										9	N	Pantry FL.7	N	
	Regency 1-4										8	N	Exit Stair ST-1 FL.6A	N	
	Guest Lift										1	N	Exit Stair ST-2 FL.6A	D	Battery Issue
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.6	N	
	BQ Kitchen					N/A	N/A	3	3	N	1	N	Exit Stair ST-2 FL.6	N	
4A	Foyer					N/A	N/A	1	N/A	N			Exit Stair ST-4 FL.6	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.6	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	D			Front Fireman Lift FL.6	N	
4A	Event Office										2	N	Fireman Lift Entrance FL.6	N	
4	ST-1 Sale Office	N	N	N/A	N/A	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-1 FL.5A	N	
	ST-2										4	N	Exit Stair ST-2 FL.5A	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-4 FL.5A	N	
	ST-4										3	N	Corridor FL.5A	N	
	Lift P5-P6	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.5A	N	
	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			AV Room FL.5A	N	
	Chiller Room					1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.5	N	
	Left Kitchen					N/A	N/A	2	2	N			Exit Stair ST-2 FL.5	N	
	Right Kitchen					N/A	N/A	2	2	N			Exit Stair ST-3 FL.5	N	
	Inside Kitchen					N/A	N/A	1	1	N	2	N	Exit Stair ST-4 FL.5	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
	MC										9	N	MEP FL.5	N	
	Hostess										2	N	BOH Regency 1 FL.5	D	Battery Issue
	Toilet										1	N	BOH Regency 2 FL.5	N	
4PK	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N			BOH Regency 3 FL.5	N	
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	Fireman Lift FL.5	N	
3A	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	Service Lift FL.5	N	
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-1 FL.4A	N	
3	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.4A	N	
3PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-3 FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-4 FL.4A	N	
2A	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exec. Office 1 FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exec. Office 2 FL.4A	N	
2	Lift Fireman	N	N	N/A	N/A	1	N/A	N/A	N/A	N			Loading Side FL.4A	N	
2PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Trendy Side FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Electric Room FL.4A	N	
M	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-1 FL.4	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-2 FL.4	N	
	Front MEP Room	N	N	N/A	N/A								Exit Stair ST-3 FL.4	D	Battery Issue
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-4 FL.4	N	
L	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exec. Office FL.4	N	
	ST-2										1	N	MARCOM Office FL.4	N	
	ST-4										1	N	Chiller Room 1 FL.4	N	
	Control Room					1	N/A	N/A	N/A	N			Chiller Room 2 FL.4	N	
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.4	N	
	Flower Room	N	N	N/A	N/A	1	N/A	N/A	N/A	N			Fireman Lift FL.4	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Service Lift FL.4	N	
	LPG Gas Station					2	N/A	N/A	N/A	N			Loading Side FL.4	N	
	Lobby Door (S)										1	N	Trendy Side FL.4	N	
	Front Parking Lift										2	N	Exit Stair ST-1 FL.3A	N	
	Loading										4	N	Exit Stair ST-2 FL.3A	N	
	ST-1 Engineer	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-4 FL.3A	N	
	ST-2 Locker	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Loading Side FL.3A	N	
	ST-3 General Store	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Trendy Side FL.3A	D	Battery Issue
	ST-4 Fire pump	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.3	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-3 FL.3	N	
	Canteen Kitchen					N/A	N/A	1	1	N			Exit Stair ST-4 FL.3	N	
	Learning Center					1	N/A	N/A	N/A	N			MEP FL.3	N	
	Male Locker										2	N	MDB 1 FL.3	N	
	Female Locker										2	N	MDB 2 FL.3	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหน้มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
B	Canteen										4	N	Generator FL.3	N	
	HK										1	N	Loading Side FL.3	N	
	Uniform										1	N	Trendy Side FL.3	N	
	Operator										1	N	Servive Lift FL.3	N/A	Uninstalled
	HR										1	N	Fireman Lift FL.3	N	
	GC										2	N	Exit Stair ST-1 FL.2A	N	
	Finance Office										1	N	Exit Stair ST-2 FL.2A	N	
	Engineer Office										1	N	Exit Stair ST-4 FL.2A	N	
	Engineer Workshop										2	N	Loading Side FL.2A	N	
	Front Hygene Office										2	N	Trendy Side FL.2A	D	Battery Issue
	Main Kitchen Corridor										2	N	Exit Stair ST-1 FL.2	N	
	Total										111				119
											Exit Stair ST-3 FL.2	N			
											Exit Stair ST-4 FL.2	N			
											MEP FL.2	N			
											Loading Side FL.2	D	Battery Issue		
											Trendy Side FL.2	N			
											Servive Lift FL.2	N/A	Uninstalled		
											Fireman Lift FL.2	N			
											Exit Stair ST-1 FL.M	N			
											Exit Stair ST-2 FL.M	N			
											Exit Stair ST-3 FL.M	N			
											Exit Stair ST-4 FL.M	N			
											Front MEP FL.M	N			
											MEP FL.M	N			
											Loading Side FL.M	N			
											Trendy Side FL.M	N			
											Exit Stair ST-1 FL.L	N			
											Exit Stair ST-2 FL.L	N			
											Exit Stair ST-3 FL.L	N			
											Exit Stair ST-4 FL.L	N			
											Control Room 1 FL.L	N			
											Control Room 2 FL.L	N			
											Fireman Lift FL.L	N			
											Discharge Fireman Lift FL.L	D	Battery Issue		
											Front Service Lift FL.L	N			
											Exit Stair ST-1 FL.B	N			

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหนัคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
													Exit Stair ST-2 FL.B	N	
													Exit Stair ST-3 FL.B	N	
													Exit Stair ST-4 (1) FL.B	N	
													Exit Stair ST-4 (2) FL.B	N	
													MEP FL.B	N	
													Fireman Lift FL.B	N	
													Male Staff Locker 1	N	
													Male Staff Locker 2	N	
													Female Staff Locker	N	
													Front HK Office FL.B	N	
													Canteen 1 FL.B	N	
													Canteen 2 FL.B	N	
													TV Corner FL.B	N	
													Corridor front Canteen	N	
													Lerning Center	N	
													HR Office	N	
													Finance Office	D	Battery Issue
													Workshop Entrance	D	One light bulb is broken
													Front Cashier	N	
													Front FB Office	N	
													FB Office	N	
													Front General Store	N	
													Cold Kitchen Entrance	N	
													Front Hygene Office	N	
													Pump Room	N	
													Compressor Room	N	
													Firepump Room	N	
													Server Room	N	
													Total	215	

Condition	Summary				
	Fire Hose Cabinet	Fire Extinguisher	Fire Blanket	Fire Exit Sign	Emergency Light
Total	111	131	10	183	215
Normal	98	130	10	183	200
Damage	0	1	0	0	13
Used	0	0	0	0	0
Lost	0	0	0	0	0
N/A	13	0	0	0	2

Prepared By

(Thanakorn A)

Security Manager

Date 29/03/2023

Acknowledged By




(.....)

Chief Engineer









Fire Cart Monthly Checklist

Month/Year: March 2023

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
1	Fireman Suit Cabinet		1	N	
2	Fire Cart Cabinet		1	N	
3	Fireman Suit		4 Suit	N	
4	Fireman Helmet		4 Pcs.	N	
5	Fireman Hood		N/A	N/A	Need to Order
6	SCBA		2 Set	N	200psi/250psi
7	SCBA Mask		2 Set	N	
8	Fire Fighting Nozzle		N/A	N/A	Pending
9	Fire Hose 1.5"		2 Pcs.	N	

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
10	Rope		2 Roll	N	
11	Axe		2 Pcs.	N	
12	Steel Bolt Cutter		2 Pcs.	N	
13	3-Ways Fire Hydrant Connection		1 Pcs.	N	
14	Spinal Board		1 Pcs.	N	
15	Head Immobilizer		2 Set	N	
16	Scoop Stretcher		1 Pcs.	N	
17	Oxygen Tank		2 Set	N	

Checked By

(Jakkarin P.)
Security Supervisor
Date 05/03/2023

Reviewed By

(Thanakorn Anurak.)
Security Manager
Date 07/03/2023

Acknowledged By

(.....)
Chief Engineer
Date/...../.....

CCTV System Monthly Report								
Month of Report:		April 2023						
Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
Location: Hotel								
1	B-001	Server room (IT)	Normal	N/A	92 Days			
2	B-002	In front of Engineer office	Normal	N/A	62 Days			
3	B-003	In front of Engineer Store	Normal	N/A	62 Days			
4	B-004	Cashier Drop Safe	Normal	N/A	62 Days			
5	B-005	Cashier Account room	Normal	N/A	62 Days			
6	B-006	Finance Store	Normal	N/A	62 Days			
7	B-007	In front of Lift F1,F2	Normal	N/A	62 Days			
8	B-008	Corridor in front of Canteen	Normal	N/A	62 Days			
9	B-009	Canteen room	Normal	N/A	62 Days			
10	B-010	Canteen room	Normal	N/A	62 Days			
11	B-011	Corridor in front of Staff Locker	Normal	N/A	62 Days			
12	B-012	Corridor in front of Uniform room	Normal	N/A	62 Days			
13	B-013	Corridor in front of Staff Locker	Normal	N/A	62 Days			
14	B-014	Staff Rest room	Normal	N/A	62 Days			
15	B-015	Staff Rest room	Normal	N/A	62 Days			
16	B-016	Corridor in front of HK Office	Normal	N/A	62 Days			
17	B-017	Corridor in front of Fire pump room	Normal	N/A	62 Days			
18	B-018	HR Office	Normal	N/A	62 Days			
19	B-019	In front of Lift S1,S2	Normal	N/A	62 Days			
20	B-020	Corridor in front of Main Kitchen	Normal	N/A	62 Days			
21	B-021	Corridor in front of F&B Store	Normal	N/A	62 Days			
22	B-022	Corridor in front of F&B Office	Normal	N/A	62 Days			
23	B-023	Uniform room	Normal	N/A	62 Days			
24	L-024	Entrance Lobby drop off	Normal	N/A	62 Days			
25	L-025	Lobby drop off	Normal	N/A	62 Days			
26	L-026	360 rotating camera at Lobby drop off	Damaged	Wirring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
27	L-027	Exit Lobby drop off	Normal	N/A	62 Days			
28	L-028	In front of Car parking F.I.L	Normal	N/A	61 Days			
29	L-029	In front of Car parking F.I.L 2	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
30	L-030	In front of Lift P5-P6	Normal	N/A	62 Days			
31	L-031	Entrance Lobby	Normal	N/A	62 Days			
32	L-032	Concierge room	Normal	N/A	62 Days			
33	L-033	In front of Concierge room	Normal	N/A	62 Days			
34	L-034	Stair 1 Floor L	Normal	N/A	62 Days			
35	L-035	360 rotating camera at Lobby Lounge	Normal	N/A	92 Days			
36	L-036	Lobby Lounge	Normal	N/A	62 Days			
37	L-037	Counter Front office (Right)	Normal	N/A	62 Days			
38	L-038	Office Front Department	Normal	N/A	62 Days			
39	L-039	Safe room	Normal	N/A	62 Days			
40	L-040	Counter Front office (Left)	Normal	N/A	62 Days			
41	L-041	In front of Lift P1-P4	Normal	N/A	62 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
42	L-042	Walkway to Parking Lift Floor L	Normal	N/A	62 Days			
43	L-043	In front of Lift PK1-2	Normal	N/A	62 Days			
44	L-044	Carpark Floor L1	Normal	N/A	62 Days			
45	L-045	Carpark Floor L2	Normal	N/A	62 Days			
46	L-046	Carpark Entrance	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
47	L-047	Gas Station	Normal	N/A	32 Days			
48	L-048	Under Retail Escalator	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
49	L-049	ST-3 Discharge Floor L	Normal	N/A	32 Days			
50	L-050	Parking for Rider under Escalator	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
51	L-051	Cashier point	Normal	N/A	32 Days			
52	L-052	Loading	Not clear	N/A	32 Days			Need to adjust focus of camera
53	L-053	Control room	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
54	L-054	In front of Control room	Normal	N/A	32 Days			
55	L-055	In front of Lift S1-2 FL.L	Normal	N/A	32 Days			
56	L-056	Time Keeper Entrance	Normal	N/A	32 Days			
57	L-057	360 rotating camera at TK	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
58	L-058	Loading Gas Station side	Normal	N/A	32 Days			
59	L-059	Parking Exit	Normal	N/A	32 Days			
60	P5-060	Lift P5	Normal	N/A	32 Days			
61	P6-061	Lift P6	Normal	N/A	32 Days			
62	P1-062	Lift P1	Normal	N/A	32 Days			
63	P2-063	Lift P2	Normal	N/A	32 Days			
64	P3-064	Lift P3	Normal	N/A	32 Days			
65	P4-065	Lift P4	Normal	N/A	32 Days			
66	P7-066	Fireman Lift 1	Normal	N/A	32 Days			
67	P8-067	Fireman Lift 2	Normal	N/A	31 Days			
68	S2-068	Service Lift 1	Normal	N/A	32 Days			
69	S1-069	Service Lift 2	Normal	N/A	32 Days			
70	M-070	In front of ST-2 FL.M	Normal	N/A	32 Days			
71	M-071	In front of ST-4 FL.M	Normal	N/A	32 Days			
72	M-072	Corridor In front of ST-3 FL.M (Retail)	Normal	N/A	32 Days			
73	M-073	In front of ST-2 FL.2 (Retail)	Normal	N/A	32 Days			
74	M-074	In front of The Coffee club (Retail)	Normal	N/A	32 Days			
75	2-075	In front of ST-4 FL.2	Normal	N/A	32 Days			
76	2-076	In front of Service Lift FL.2	Normal	N/A	32 Days			
77	2A-077	Car parking FL.2A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
78	2A-078	In front of ST-4 FL.2A	Normal	N/A	32 Days			
79	3-079	In front of ST-2 FL.3	Normal	N/A	32 Days			
80	3-080	In front of Lift Service FL.3	Normal	N/A	32 Days			
81	3-081	In front of ST-4 FL.3	Normal	N/A	32 Days			
82	3A-082	Car parking FL.3A	Normal	N/A	32 Days			
83	3A-083	In front of ST-4 FL.3A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
84	4-084	Balcony entrance	Normal	N/A	32 Days			
85	4-085	Sukhumvit Gallery	Normal	N/A	32 Days			
86	4-086	In front of Kitchen FL.4	Normal	N/A	32 Days			
87	4-087	In front of Lift P1-P4 FL.4	Normal	N/A	32 Days			
88	4-088	In front of Firman Lift FL.4	Damaged	N/A	32 Days	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
89	4-089	In front of ST-2 FL.4	Normal	N/A	32 Days			
90	4-090	Inside Market Café	Normal	N/A	32 Days			
91	4-091	In front of Service Lift FL.4	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
92	4-092	Kitchen Exit FL.4	Normal	N/A	32 Days			
93	4-093	In front of ST-4 FL.4	Normal	N/A	32 Days			
94	4A-094	Car parking FL.4A	Normal	N/A	32 Days			
95	4-095	In front of ST-4 FL.4	Normal	N/A	32 Days			
96	5-096	Foyer front of ST-1 FL.5	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
97	5-097	In front of Escalator FL.5	Normal	N/A	32 Days			
98	5-098	In front of ST-1 FL.5	Normal	N/A	32 Days			
99	5-099	360 rotating camera at foyer FL.5	Damaged	Rotating motor broken	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
100	5-100	In front of Lift P1-4	Normal	N/A	32 Days			
101	5-101	In front of ST-2 FL.5 (Foyer)	Normal	N/A	32 Days			
102	5-102	Between ST-2 and Ballroom	Normal	N/A	32 Days			
103	5-103	Ballroom	Normal	N/A	32 Days			
104	5-104	In front of BQ store	Normal	N/A	32 Days			
105	5-105	In front of service lift FL.5	Normal	N/A	32 Days			
106	5-106	In front of ST-3 FL.5	Normal	N/A	31 Days			
107	5A-107	Corridor BOH behind Ballroom	Normal	N/A	32 Days			
108	5A-108	In front of service lift FL.5A	Normal	N/A	32 Days			
109	6-109	Inside Fire Exit ST-1 FL.6	Normal	N/A	32 Days			
110	6-110	In front of Fitness	Normal	N/A	32 Days			
111	6-111	In front of Male Locker FL.6	Normal	N/A	32 Days			
112	6-112	In front of Female Locker FL.6	Normal	N/A	32 Days			
113	6-113	In front of Lift P1-4 FL.6	Normal	N/A	32 Days			
114	6-114	In front of Fireman lift Entrance FL.6	Normal	N/A	32 Days			
115	6-115	In front of Fireman Lift FL.6	Normal	N/A	32 Days			
116	6-116	Pool Bar FL.6	Normal	N/A	92 Days			
117	6-117	In front of Service lift FL.6	Normal	N/A	32 Days			
118	7-118	In front of Fireman Lift FL.7	Normal	N/A	32 Days			
119	7-119	Corridor FL.7	Normal	N/A	32 Days			
120	7-120	Corridor in front of room 706	Normal	N/A	32 Days			
121	7-121	In front of Guest Lift FL.7	Normal	N/A	32 Days			
122	8-122	In front of Fireman Lift FL.8	Normal	N/A	32 Days			
123	8-123	Corridor FL.8	Normal	N/A	32 Days			
124	8-124	Corridor in front of room 806	Normal	N/A	32 Days			
125	8-125	In front of Guest Lift FL.8	Normal	N/A	32 Days			
126	10-126	In front of Fireman Lift FL.10	Normal	N/A	32 Days			
127	9-127	Corridor FL.9	Normal	N/A	32 Days			
128	9-128	Corridor in front of room 906	Normal	N/A	32 Days			
129	9-129	In front of Guest Lift FL.9	Normal	N/A	32 Days			
130	9-130	In front of Fireman Lift FL.9	Normal	N/A	32 Days			
131	10-131	Corridor FL.10	Normal	N/A	32 Days			
132	10-132	Corridor in front of room 1006	Normal	N/A	32 Days			
133	10-133	In front of Guest Lift FL.10	Normal	N/A	32 Days			
134	11-134	In front of Fireman Lift FL.11	Normal	N/A	32 Days			
135	11-135	Corridor FL.11	Normal	N/A	32 Days			
136	11-136	Corridor in front of room 1106	Normal	N/A	32 Days			
137	11-137	in front of Guest Lift FL.11	Normal	N/A	32 Days			
138	12-138	In front of Fireman Lift FL.12	Normal	N/A	32 Days			
139	12-139	Corridor FL.12	Normal	N/A	32 Days			
140	12-140	Corridor in front of room 1206	Normal	N/A	32 Days			
141	12-141	In front of Guest Lift FL.12	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
142	14-142	In front of Fireman Lift FL.14	Normal	N/A	32 Days			
143	14-143	Corridor FL.14	Normal	N/A	32 Days			
144	14-144	Corridor in front of room 1406	Normal	N/A	32 Days			
145	14-145	In front of Guest Lift FL.14	Normal	N/A	32 Days			
146	15-146	In front of Fireman Lift FL.15	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
147	15-147	Corridor FL.15	Normal	N/A	32 Days			
148	15-148	Corridor in front of room 1506	Normal	N/A	32 Days			
149	15-149	In front of Guest Lift FL.15	Normal	N/A	32 Days			
150	16-150	In front of Fireman Lift FL.16	Normal	N/A	32 Days			
151	16-151	Corridor FL.16	Normal	N/A	32 Days			
152	16-152	Corridor in front of room1606	Normal	N/A	32 Days			
153	16-153	In front of Guest Lift FL.16	Normal	N/A	32 Days			
154	17-154	In front of Fireman Lift FL.17	Normal	N/A	32 Days			
155	17-155	Corridor FL.17	Normal	N/A	32 Days			
156	17-156	Corridor in front of room 1706	Normal	N/A	32 Days			
157	17-157	In front of Guest Lift FL.17	Normal	N/A	32 Days			
158	18-158	In front of Fireman Lift FL.18	Normal	N/A	32 Days			
159	18-159	Corridor FL.18	Normal	N/A	32 Days			
160	18-160	Corridor in front of room 1806	Normal	N/A	32 Days			
161	18-161	In front of Guest Lift FL.18	Normal	N/A	32 Days			
162	19-162	In front of Lift Fireman Lift FL.19	Normal	N/A	32 Days			
163	19-163	Corridor FL.19	Normal	N/A	32 Days			
164	19-164	In front of Guest Lift FL.19	Normal	N/A	32 Days			
165	19-165	Corridor in front of room 1906	Normal	N/A	32 Days			
166	20-166	In front of Fireman Lift FL.20	Normal	N/A	32 Days			
167	20-167	Corridor FL.20	Normal	N/A	32 Days			
168	20-168	Corridor in front of room 2006	Normal	N/A	32 Days			
169	20-169	In front of Guest Lift FL.20	Normal	N/A	32 Days			
170	21-170	In front of Fireman Lift FL.21	Normal	N/A	32 Days			
171	21-171	Corridor FL.21	Normal	N/A	32 Days			
172	21-172	Corridor in front of room 2106	Normal	N/A	32 Days			
173	21-173	In front of Guest Lift FL.21	Normal	N/A	32 Days			
174	22-174	In front of Fireman Lift FL.22	Normal	N/A	32 Days			
175	22-175	Corridor FL.22	Normal	N/A	32 Days			
176	22-176	Corridor in front of room 2206	Normal	N/A	32 Days			
177	22-197	In front of Guest Lift FL.22	Normal	N/A	32 Days			
178	23-178	In front of Fireman Lift FL.23	Normal	N/A	32 Days			
179	23-179	Corridor FL.23	Normal	N/A	32 Days			
180	23-180	Corridor in front of room 2306	Normal	N/A	32 Days			
181	23-181	In front of Guest Lift FL.23	Normal	N/A	32 Days			
182	27-182	In front of Fireman Lift FL.24	Normal	N/A	32 Days			
183	24-183	Corridor FL.24	Normal	N/A	32 Days			
184	24-184	Corridor in front of room 2406	Normal	N/A	32 Days			
185	24-185	In front of Guest Lift FL.24	Normal	N/A	32 Days			
186	25-186	In front of Fireman Lift FL.25	Normal	N/A	32 Days			
187	25-187	Corridor FL.25	Normal	N/A	32 Days			
188	25-188	Corridor in front of room 2506	Normal	N/A	32 Days			
189	25-189	In front of Guest Lift FL.25	Normal	N/A	32 Days			
190	26-190	In front of Fireman Lift FL.26	Normal	N/A	32 Days			
191	26-191	Corridor FL.26	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
192	26-192	Corridor in front of room 2606	Normal	N/A	32 Days			
193	26-193	In front of Guest Lift FL.26	Normal	N/A	32 Days			
194	27-194	In front of Fireman Lift FL.27	Normal	N/A	32 Days			
195	27-195	Corridor in front of ST-2 FL.27	Normal	N/A	32 Days			
196	27-196	Corridor FL.27	Normal	N/A	32 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
197	27-177	Corridor in front of room 2706	Normal	N/A	32 Days			
198	27-198	Regency Club Counter Reception	Normal	N/A	91 Days			
199	27-199	Regency Club Balcony	Normal	N/A	32 Days			
200	27-200	Regency Club in front of Kitchen	Normal	N/A	32 Days			
201	27-201	In front of Guest Lift FL.27	Normal	N/A	32 Days			
202	28-202	In front of Fireman Lift FL.28	Normal	N/A	32 Days			
203	28-203	Corridor FL.28	Normal	N/A	32 Days			
204	28-204	Corridor in front of room 2806	Normal	N/A	32 Days			
205	28-205	In front of Guest Lift FL.28	Normal	N/A	32 Days			
206	29-206	In front of Fireman Lift FL.29	Normal	N/A	32 Days			
207	29-207	In front of Guest Lift FL.29	Normal	N/A	32 Days			
208	29-208	In front of Kitchen FL.29	Normal	N/A	32 Days			
209	29-209	Balcony Kitchen side FL.29	Out of license	No license	31 Days			Waiting for the Quotation
210	29-210	Front Balcony FL.29	Normal	N/A	31 Days			
211	29-211	Staircase up to FL.30	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
212	29-212	Spectrum Bar FL.29	Normal	N/A	92 Days			
213	29-213	Balcony Sofitel side FL.29	Out of license	No license	32 Days			Waiting for the Quotation
214	30-214	Glass floor FL.30	Out of license	No license	32 Days			Waiting for the Quotation
215	30-215	Spectrum FL. 30	Normal	N/A	32 Days			
216	30-216	Spectrum Bar FL.30	Normal	N/A	32 Days			
217	31-217	In front of Lift Control room FL.31	Normal	N/A	32 Days			
218	31-218	Spectrum FL.31	Normal	N/A	32 Days			

Location: Parking and Retail

1	FLM 01	In front of lift FL.M	Normal		117 Days			
2	FLM 02	Parking FL.M	Normal		117 Days			
3	FLM 03	Parking FL.M (Trendy Side)	Normal		117 Days			
4	FLM 04	Parling FL.M (Loading Side)	Normal		117 Days			
5	FL2 01	In front of lift FL.2	Normal		117 Days			
6	FL2 02	Parking FL.2	Normal		117 Days			
7	FL2 03	Parking FL.2 (Trendy Side)	Normal		117 Days			
8	FL2 04	Parling FL.2 (Loading Side)	Normal		117 Days			
9	FL2A 01	In front of lift FL.2A	Normal		117 Days			
10	FL2A 02	Parking FL.2A	Normal		117 Days			
11	FL2A 03	Parking FL.2A (Trendy Side)	Normal		117 Days			
12	FL2A 04	Parling FL.2A (Loading Side)	Normal		117 Days			
13	FL3 01	In front of lift FL.3	Normal		117 Days			
14	FL3 02	Parking FL.3	Normal		117 Days			
15	FL3 03	Parking FL.3 (Trendy Side)	Normal		117 Days			
16	FL3 04	Parling FL.3 (Loading Side)	Normal		117 Days			
17	FL3A 01	In front of lift FL.3A	Normal		117 Days			
18	FL3A 02	Parking FL.3A	Normal		117 Days			
19	FL3A 03	Parking FL.3A (Trendy Side)	Not clear		117 Days	The Allez (Retail Office) acknowledged		
20	FL3A 04	Parling FL.3A (Loading Side)	Normal		117 Days			
21	FL4 01	In front of lift FL.4	Normal		98 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
22	FL4 02	Parking FL.4	Normal		98 Days			
23	FL4 03	Parking FL.4 (Trendy Side)	Normal		98 Days			
24	FL4 04	Parling FL.4 (Loading Side)	Normal		98 Days			
25	FL4A 01	Parking FL.4A (Trendy Side)	Normal		98 Days			
26	FL4A 02	Parling FL.4A (Loading Side)	Normal		98 Days			
27	FL4A 03	Parking FL.4A	Normal		98 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
28	FL4A 04	In front of lift FL.4A	Normal		98 Days			
29	FL1 01	BOBO entrance 1	Normal		83 Days			
30	FL1 02	BOBO entrance 2	Normal		83 Days			
31	FL1 03	Under Retail Escalator	Normal		83 Days			
32	FL2 04	Retail Entrance from Parking FL.2	Normal		83 Days			
33	FL2 03	Coffee Club FL.2	Normal		83 Days			
34	FL2 06	Escalator FL.2	Normal		83 Days			
35	FL3 01	In front of lift P5, P6 FL.3	Normal		83 Days			
36	FL3 03	Let's Relax Spa FL.3	Normal		83 Days			
37	FL3 04	Escalator FL.3	Normal		83 Days			
38	FL3 05	In front of ST-1 FL.3	Normal		83 Days			
39	BTS1	Hotel Entrance from BTS	Normal		98 Days			
40	BTS2	BTS Skywalk	Normal		98 Days			
41	BTS3	BTS Entrance	Not clear		98 Days	The Allez (Retail Office) acknowledged		

Summary	
Status	Amount
Normal	242
Damaged	11
Not clear	3
Out of license	3
Total	259

Additional comments:

1. SECOM already sent the report of all damaged CCTVs and still waiting for the final quotation to fix it.
2. Out of license CCTVs, still have camera but due to over CCTV IP point from budget requested since beginning. 3 of them were cut off only signal. Waiting for quotation to re-license.
3. Comment from Khun Sammy, there must be additional CCTV at Fireman lift landing on L floor. Already added to the next CCTV installation project together with fix list.
4. Comments from Khun Bruce and Khun Ian (Hyatt Global Security) that there must be additional CCTVs at POS system which is we miss 2 points at Market Cafe. Already added to the next CCTV installation project together with fix list.
5. The quotation was received on 28 February 2023. But they called to increase the price on 9 March 2023. Khun Sukhunthip (Purchasing Mgr.) asked SECOM to conduct the meeting with hotel about price increase issue.

Checked By

(.....Sompong L.....)

Position: Security Officer

Date: 27/03/2023

Reviewed By

(Thanakorn A)

Security Manager

Date: 28/04/2023

Acknowledged By

(.....)

Chief Engineer

Date:/...../.....

Fire & Life Safety Monthly Checklist

Month/Year: April 2023

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
31	Hot Water Tank Room	N	N	N	N/A	1	N/A	N/A	N/A	N			Hot Water Tank 1 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Hot Water Tank 2 FL.31	N	
30	Spectrum Store					1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.30	N	
	Automatic Slide Door										1	N	Exit Stair ST-1 FL.29	N	
29	Back Kitchen					N/A	N/A	2	N/A	N			Exit Stair ST-2 (1) FL.29	N	
	Front Kitchen										2	N	Exit Stair ST-2 (2) FL.29	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.29	D	Battery Issue
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Pantry FL.29	D	Battery Issue
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.28	N	
	Guest Lift										1	N	Exit Stair ST-2 FL.28	N	
	Toilet										1	N	MEP FL.28	N	
28	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.28	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.27	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.27	N	
27	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.27	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.27	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.26	N	
	RC Lounge										2	N	Exit Stair ST-2 FL.26	N	
	Kitchen					1	N/A	N/A	N/A	N	1	N	MEP FL.26	N	
26	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.26	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.25	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.25	N	
25	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.25	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.25	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.24	N	
24	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.24	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.24	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.24	N	
23	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.23	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.23	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.23	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.23	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
22	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.22	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.22	N	
21	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.22	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.22	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.21	N	
20	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.21	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.21	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.21	N	
19	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.20	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.20	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.20	N	
18	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.20	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.19	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.19	N	
17	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.19	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.19	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.18	N	
16	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.18	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.18	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.18	N	
15	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.17	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.17	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.17	N	
14	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.17	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.16	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.16	N	
12	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.16	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.16	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.15	N	
11	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.15	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.15	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.15	N	
10	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.14	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.14	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.14	D	Battery Issue
9	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.14	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.12	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.12	N	
	ST-1	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	MEP FL.12	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
8	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.12	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.11	N	
7	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.11	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.11	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.11	N	
6A	Cooling Tower	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.10	N	
6	ST-1	D	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.10	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	MEP FL.10	N	
	ST-4										1	N	Pantry FL.10	N	
	Pool Entrance (Lift)										1	N	Exit Stair ST-1 FL.9	N	
	Pool Entrance (Fitness)										1	N	Exit Stair ST-2 FL.9	N	
	Lift S1-S2	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.9	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.9	N	
	Bar					1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.8	N	
5A	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.8	N	
5	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	2	N	MEP FL.8	N	
	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	2	N	Pantry FL.8	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-1 FL.7	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.7	N	
	AV Room (Ballroom 4)					1	N/A	N/A	N/A	N			MEP FL.7	N	
	Regency Ballroom										9	N	Pantry FL.7	N	
	Regency 1-4										8	N	Exit Stair ST-1 FL.6A	N	
	Guest Lift										1	N	Exit Stair ST-2 FL.6A	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.6	N	
	BQ Kitchen					N/A	N/A	3	3	N	1	N	Exit Stair ST-2 FL.6	N	
4A	Foyer					N/A	N/A	1	N/A	N			Exit Stair ST-4 FL.6	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.6	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N			Front Fireman Lift FL.6	N	
4A	Event Office										2	N	Fireman Lift Entrance FL.6	N	
4	ST-1 Sale Office	N	N	N/A	N/A	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-1 FL.5A	N	
	ST-2										4	N	Exit Stair ST-2 FL.5A	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-4 FL.5A	N	
	ST-4										3	N	Corridor FL.5A	N	
	Lift P5-P6	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.5A	N	
	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			AV room FL.5A	N	
	Chiller Room					1	N/A	N/A	N/A	N			Pump Room FL.5A	D	Battery Issue
	Left Kitchen					N/A	N/A	2	2	N			Exit Stair ST-1 FL.5	N	
	Right Kitchen					N/A	N/A	2	2	D 1			Exit Stair ST-2 FL.5	N	
	Inside Kitchen					N/A	N/A	1	1	N	2	N	Exit Stair ST-3 FL.5	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ	
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ		
	MC											9	N	Exit Stair ST-4 FL.5	N	Battery Issue
	Hostess											2	N	MEP FL.5	N	
	Toilet											1	N	BOH Regency 1 FL.5	D	
4PK	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N			BOH Regency 2 FL.5	N		
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	BOH Regency 3 FL.5	N		
3A	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	Fireman Lift FL.5	N		
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	2	N	Service Lift FL.5	N		
3	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.4A	N		
3PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.4A	N		
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-3 FL.4A	N		
2A	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-4 FL.4A	N		
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exec. Office 1 FL.4A	N		
2	Lift Fireman	D	N	N/A	N/A	1	N/A	N/A	N/A	N			Exec. Office 2 FL.4A	N		
2PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Loading Side FL.4A	N		
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Trendy Side FL.4A	N		
M	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Electric Room 1 FL.4A	N	Battery Issue	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Electric Room 2 FL.4A	D		
	Front MEP Room	N	N	N/A	N/A									Exit Stair ST-1 FL.4		N
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.4	N		
L	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-3 FL.4	N	Battery Issue	
	ST-2											1	N	Exit Stair ST-4 FL.4		N
	ST-4											1	N	Exec. Office FL.4		N
	Control Room					1	N/A	N/A	N/A	N			MARCOM Office FL.4	N		
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			Chiller Room 1 FL.4	N		
	Flower Room	N	N	N/A	N/A	1	N/A	N/A	N/A	N			Chiller Room 2 FL.4	N		
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.4	N		
	LPG Gas Station					2	N/A	N/A	N/A	N			Fireman Lift FL.4	N		
	Lobby Door (S)											1	N	Service Lift FL.4		D
	Front Parking Lift											2	N	Loading Side FL.4		N
	Loading											4	N	Trendy Side FL.4		D
	ST-1 Engineer	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-1 FL.3A	N	Battery Issue	
	ST-2 Locker	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-2 FL.3A	N		
	ST-3 General Store	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-4 FL.3A	N		
	ST-4 Fire pump	N	N		N	1	N/A	N/A	N/A	N			Loading Side FL.3A	N		
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Trendy Side FL.3A	D		
	Canteen Kitchen					N/A	N/A	1	1	N			Exit Stair ST-2 FL.3	N		
	Learning Center					1	N/A	N/A	N/A	N			Exit Stair ST-3 FL.3	N		
	Male Locker											2	N	Exit Stair ST-4 FL.3		N
	Female Locker											2	N	MEP FL.3		N

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหน้มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ	
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ		
B	Canteen									4	N	MDB 1 FL.3	N			
	HK									1	N	MDB 2 FL.3	N			
	Uniform									1	N	Generator FL.3	N			
	Operator									1	N	Loading Side FL.3	N			
	HR									1	N	Trendy Side FL.3	N			
	GC									2	N	Servive Lift FL.3	N			
	Finance Office									1	N	Fireman Lift FL.3	N			
	Engineer Office									1	N	Exit Stair ST-1 FL.2A	N			
	Engineer Workshop									2	N	Exit Stair ST-2 FL.2A	N			
	Front Hygene Office									2	N	Exit Stair ST-4 FL.2A	N			
	Main Kitchen Corridor									2	N	Loading Side FL.2A	N			
	Total		111				119	0	12	9	183		Trendy Side FL.2A	N		
														Exit Stair ST-1 FL.2	N	
														Exit Stair ST-2 FL.2	N	
														Exit Stair ST-3 FL.2	N	
														Exit Stair ST-4 FL.2	N	
														MEP FL.2	N	
														Loading Side FL.2	D	Battery Issue
														Trendy Side FL.2	N	
														Servive Lift FL.2	N/A	Uninstalled
														Fireman Lift FL.2	N	
														Exit Stair ST-1 FL.M	N	
														Exit Stair ST-2 FL.M	N	
														Exit Stair ST-3 FL.M	N	
														Exit Stair ST-4 FL.M	N	
														Front MEP FL.M	N	
														MEP FL.M	N	
														Loading Side FL.M	N	
														Trendy Side FL.M	N	
														Exit Stair ST-1 FL.L	N	
														Exit Stair ST-2 FL.L	N	
														Exit Stair ST-3 FL.L	N	
														Exit Stair ST-4 FL.L	N	
														Control Room 1 FL.L	N	
														Control Room 2 FL.L	N	
														Fireman Lift FL.L	N	
														Discharge Fireman Lift FL.L	D	Battery Issue

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหน้คลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
													Front Service Lift FL.L	N	
													Exit Stair ST-1 FL.B	N	
													Exit Stair ST-2 FL.B	N	
													Exit Stair ST-3 FL.B	N	
													Exit Stair ST-4 (1) FL.B	N	
													Exit Stair ST-4 (2) FL.B	N	
													MEP FL.B	N	
													Fireman Lift FL.B	N	
													Male Staff Locker 1	N	
													Male Staff Locker 2	N	
													Female Staff Locker	N	
													Front HK Office FL.B	N	
													Canteen 1 FL.B	N	
													Canteen 2 FL.B	N	
													TV Corner FL.B	N	
													Corridor front Canteen	N	
													Lerning Center	N	
													HR Office	N	
													Finance Office	D	Battery Issue
													Workshop Entrance	D	One light bulb is broken
													Front Cashier	N	
													Front FB Office	N	
													FB Office	N	
													Front General Store	N	
													Cold Kitchen Entrance	N	
													Front Hygene Office	N	
													Pump Room	N	
													Compressor Room	N	
													Firepump Room	N	
													Server Room	N	
													Total	217	

Condition	Summary				
	Fire Hose Cabinet	Fire Extinguisher	Fire Blanket	Fire Exit Sign	Emergency Light
Total	111	131	10	183	217
Normal	99	130	10	183	203
Damage	2	1	0	0	13
Used	0	0	0	0	0
Lost	0	0	0	0	0
N/A	13	0	0	0	1

Prepared By

(Thanakorn A)

Security Manager
Date 28/04/2023

Acknowledged By










(.....)

Chief Engineer









Fire Cart Monthly Checklist

Month/Year: ___April___2023___

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
1	Fireman Suit Cabinet		1		
2	Fire Cart Cabinet		1		
3	Fireman Suit		4 Suit		
4	Fireman Helmet		4 Pcs.		
5	Fireman Hood		N/A	N/A	Need to Order
6	SCBA		2 Set		200psi/240psi
7	SCBA Mask		2 Set		
8	Fire Fighting Nozzle		N/A	N/A	Pending
9	Fire Hose 1.5"		2 Pcs.		

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
10	Rope		2 Roll		
11	Axe		2 Pcs.		
12	Steel Bolt Cutter		2 Pcs.		
13	3-Ways Fire Hydrant Connection		1 Pcs.		
14	Spinal Board		1 Pcs.		
15	Head Immobilizer		2 Set		
16	Scoop Stretcher		1 Pcs.		
17	Oxygen Tank		2 Set		

Checked By
(Saran)
Team Leader Security
Date 1/04/ 2023

Reviewed By
(Thanakorn A)
Security Manager
Date 28 / 04 / 2023

Acknowledged By
(.....)
Chief Engineer
Date/...../.....

CCTV System Monthly Report								
Month of Report:		May 2023						
Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
Location: Hotel								
1	B-001	Server room (IT)	Normal	N/A	92 Days			
2	B-002	In front of Engineer office	Normal	N/A	62 Days			
3	B-003	In front of Engineer Store	Normal	N/A	62 Days			
4	B-004	Cashier Drop Safe	Normal	N/A	62 Days			
5	B-005	Cashier Account room	Normal	N/A	62 Days			
6	B-006	Finance Store	Normal	N/A	62 Days			
7	B-007	In front of Lift F1,F2	Normal	N/A	62 Days			
8	B-008	Corridor in front of Canteen	Normal	N/A	62 Days			
9	B-009	Canteen room	Normal	N/A	62 Days			
10	B-010	Canteen room	Normal	N/A	62 Days			
11	B-011	Corridor in front of Staff Locker	Normal	N/A	62 Days			
12	B-012	Corridor in front of Uniform room	Normal	N/A	62 Days			
13	B-013	Corridor in front of Staff Locker	Normal	N/A	62 Days			
14	B-014	Staff Rest room	Normal	N/A	62 Days			
15	B-015	Staff Rest room	Normal	N/A	62 Days			
16	B-016	Corridor in front of HK Office	Normal	N/A	62 Days			
17	B-017	Corridor in front of Fire pump room	Normal	N/A	62 Days			
18	B-018	HR Office	Normal	N/A	62 Days			
19	B-019	In front of Lift S1,S2	Normal	N/A	62 Days			
20	B-020	Corridor in front of Main Kitchen	Normal	N/A	62 Days			
21	B-021	Corridor in front of F&B Store	Normal	N/A	62 Days			
22	B-022	Corridor in front of F&B Office	Normal	N/A	62 Days			
23	B-023	Uniform room	Normal	N/A	62 Days			
24	L-024	Entrance Lobby drop off	Normal	N/A	62 Days			
25	L-025	Lobby drop off	Normal	N/A	62 Days			
26	L-026	360 rotating camera at Lobby drop off	Damaged	Wirring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
27	L-027	Exit Lobby drop off	Normal	N/A	62 Days			
28	L-028	In front of Car parking F.I.L	Normal	N/A	61 Days			
29	L-029	In front of Car parking F.I.L 2	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
30	L-030	In front of Lift P5-P6	Normal	N/A	62 Days			
31	L-031	Entrance Lobby	Normal	N/A	62 Days			
32	L-032	Concierge room	Normal	N/A	62 Days			
33	L-033	In front of Concierge room	Normal	N/A	62 Days			
34	L-034	Stair 1 Floor L	Normal	N/A	62 Days			
35	L-035	360 rotating camera at Lobby Lounge	Normal	N/A	92 Days			
36	L-036	Lobby Lounge	Normal	N/A	61 Days			
37	L-037	Counter Front office (Right)	Normal	N/A	62 Days			
38	L-038	Office Front Department	Normal	N/A	62 Days			
39	L-039	Safe room	Normal	N/A	62 Days			
40	L-040	Counter Front office (Left)	Normal	N/A	92 Days			
41	L-041	In front of Lift P1-P4	Normal	N/A	62 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
42	L-042	Walkway to Parking Lift Floor L	Normal	N/A	62 Days			
43	L-043	In front of Lift PK1-2	Normal	N/A	62 Days			
44	L-044	Carpark Floor L1	Normal	N/A	62 Days			
45	L-045	Carpark Floor L2	Normal	N/A	62 Days			
46	L-046	Carpark Entrance	Normal	N/A	32 Days			
47	L-047	Gas Station	Normal	N/A	32 Days			
48	L-048	Under Retail Escalator	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
49	L-049	ST-3 Discharge Floor L	Normal	N/A	31 Days			
50	L-050	Parking for Rider under Escalator	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
51	L-051	Cashier point	Normal	N/A	31 Days			
52	L-052	Loading	Not clear	N/A	31 Days			Need to adjust focus of camera
53	L-053	Control room	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
54	L-054	In front of Control room	Normal	N/A	31 Days			
55	L-055	In front of Lift S1-2 FL.L	Normal	N/A	31 Days			
56	L-056	Time Keeper Entrance	Normal	N/A	31 Days			
57	L-057	360 rotating camera at TK	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
58	L-058	Loading Gas Station side	Normal	N/A	31 Days			
59	L-059	Parking Exit	Normal	N/A	31 Days			
60	P5-060	Lift P5	Normal	N/A	31 Days			
61	P6-061	Lift P6	Normal	N/A	31 Days			
62	P1-062	Lift P1	Normal	N/A	31 Days			
63	P2-063	Lift P2	Normal	N/A	31 Days			
64	P3-064	Lift P3	Normal	N/A	31 Days			
65	P4-065	Lift P4	Normal	N/A	31 Days			
66	P7-066	Fireman Lift 1	Normal	N/A	31 Days			
67	P8-067	Fireman Lift 2	Normal	N/A	31 Days			
68	S2-068	Service Lift 1	Normal	N/A	31 Days			
69	S1-069	Service Lift 2	Normal	N/A	31 Days			
70	M-070	In front of ST-2 FL.M	Normal	N/A	31 Days			
71	M-071	In front of ST-4 FL.M	Normal	N/A	31 Days			
72	M-072	Corridor In front of ST-3 FL.M (Retail)	Normal	N/A	31 Days			
73	M-073	In front of ST-2 FL.2 (Retail)	Normal	N/A	31 Days			
74	M-074	In front of The Coffee club (Retail)	Normal	N/A	31 Days			
75	2-075	In front of ST-4 FL.2	Normal	N/A	31 Days			
76	2-076	In front of Service Lift FL.2	Normal	N/A	31 Days			
77	2A-077	Car parking FL.2A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
78	2A-078	In front of ST-4 FL.2A	Normal	N/A	31 Days			
79	3-079	In front of ST-2 FL.3	Normal	N/A	31 Days			
80	3-080	In front of Lift Service FL.3	Normal	N/A	31 Days			
81	3-081	In front of ST-4 FL.3	Normal	N/A	31 Days			
82	3A-082	Car parking FL.3A	Normal	N/A	31 Days			
83	3A-083	In front of ST-4 FL.3A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
84	4-084	Balcony entrance	Normal	N/A	31 Days			
85	4-085	Sukhumvit Gallery	Normal	N/A	31 Days			
86	4-086	In front of Kitchen FL.4	Normal	N/A	31 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
87	4-087	In front of Lift P1-P4 FL.4	Normal	N/A	31 Days			
88	4-088	In front of Firman Lift FL.4	Damaged	N/A	31 Days	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
89	4-089	In front of ST-2 FL.4	Normal	N/A	31 Days			
90	4-090	Inside Market Café	Normal	N/A	31 Days			
91	4-091	In front of Service Lift FL.4	Normal	N/A	31 Days			
92	4-092	Kitchen Exit FL.4	Normal	N/A	31 Days			
93	4-093	In front of ST-4 FL.4	Normal	N/A	3 Days			
94	4A-094	Car parking FL.4A	Normal	N/A	31 Days			
95	4-095	In front of ST-4 FL.4	Normal	N/A	31 Days			
96	5-096	Foyer front of ST-1 FL.5	Normal	N/A	31 Days			
97	5-097	In front of Escalator FL.5	Normal	N/A	31 Days			
98	5-098	In front of ST-1 FL.5	Normal	N/A	31 Days			
99	5-099	360 rotating camera at foyer FL.5	Damaged	Rotating motor broken	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
100	5-100	In front of Lift P1-4	Normal	N/A	31 Days			
101	5-101	In front of ST-2 FL.5 (Foyer)	Normal	N/A	31 Days			
102	5-102	Between ST-2 and Ballroom	Normal	N/A	31 Days			
103	5-103	Ballroom	Normal	N/A	31 Days			
104	5-104	In front of BQ store	Normal	N/A	31 Days			
105	5-105	In front of service lift FL.5	Normal	N/A	31 Days			
106	5-106	In front of ST-3 FL.5	Normal	N/A	31 Days			
107	5A-107	Corridor BOH behind Ballroom	Normal	N/A	31 Days			
108	5A-108	In front of service lift FL.5A	Normal	N/A	31 Days			
109	6-109	Inside Fire Exit ST-1 FL.6	Normal	N/A	31 Days			
110	6-110	In front of Fitness	Normal	N/A	31 Days			
111	6-111	In front of Male Locker FL.6	Normal	N/A	31 Days			
112	6-112	In front of Female Locker FL.6	Normal	N/A	31 Days			
113	6-113	In front of Lift P1-4 FL.6	Normal	N/A	31 Days			
114	6-114	In front of Fireman lift Entrance FL.6	Normal	N/A	31 Days			
115	6-115	In front of Fireman Lift FL.6	Normal	N/A	31 Days			
116	6-116	Pool Bar FL.6	Normal	N/A	91 Days			
117	6-117	In front of Service lift FL.6	Normal	N/A	31 Days			
118	7-118	In front of Fireman Lift FL.7	Normal	N/A	31 Days			
119	7-119	Corridor FL.7	Normal	N/A	31 Days			
120	7-120	Corridor in front of room 706	Normal	N/A	31 Days			
121	7-121	In front of Guest Lift FL.7	Normal	N/A	31 Days			
122	8-122	In front of Fireman Lift FL.8	Normal	N/A	31 Days			
123	8-123	Corridor FL.8	Normal	N/A	31 Days			
124	8-124	Corridor in front of room 806	Normal	N/A	31 Days			
125	8-125	In front of Guest Lift FL.8	Normal	N/A	31 Days			
126	10-126	In front of Fireman Lift FL.10	Normal	N/A	31 Days			
127	9-127	Corridor FL.9	Normal	N/A	31 Days			
128	9-128	Corridor in front of room 906	Normal	N/A	31 Days			
129	9-129	In front of Guest Lift FL.9	Normal	N/A	31 Days			
130	9-130	In front of Fireman Lift FL.9	Normal	N/A	31 Days			
131	10-131	Corridor FL.10	Normal	N/A	31 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
132	10-132	Corridor in front of room 1006	Normal	N/A	31 Days			
133	10-133	In front of Guest Lift FL.10	Normal	N/A	31 Days			
134	11-134	In front of Fireman Lift FL.11	Normal	N/A	31 Days			
135	11-135	Corridor FL.11	Normal	N/A	31 Days			
136	11-136	Corridor in front of room 1106	Normal	N/A	31 Days			
137	11-137	in front of Guest Lift FL.11	Normal	N/A	31 Days			
138	12-138	In front of Fireman Lift FL.12	Normal	N/A	31 Days			
139	12-139	Corridor FL.12	Normal	N/A	31 Days			
140	12-140	Corridor in front of room 1206	Normal	N/A	31 Days			
141	12-141	In front of Guest Lift FL.12	Normal	N/A	31 Days			
142	14-142	In front of Fireman Lift FL.14	Normal	N/A	31 Days			
143	14-143	Corridor FL.14	Normal	N/A	31 Days			
144	14-144	Corridor in front of room 1406	Normal	N/A	31 Days			
145	14-145	In front of Guest Lift FL.14	Normal	N/A	31 Days			
146	15-146	In front of Fireman Lift FL.15	Normal	N/A	31 Days			
147	15-147	Corridor FL.15	Normal	N/A	31 Days			
148	15-148	Corridor in front of room 1506	Normal	N/A	31 Days			
149	15-149	In front of Guest Lift FL.15	Normal	N/A	31 Days			
150	16-150	In front of Fireman Lift FL.16	Normal	N/A	31 Days			
151	16-151	Corridor FL.16	Normal	N/A	31 Days			
152	16-152	Corridor in front of room1606	Normal	N/A	31 Days			
153	16-153	In front of Guest Lift FL.16	Normal	N/A	31 Days			
154	17-154	In front of Fireman Lift FL.17	Normal	N/A	31 Days			
155	17-155	Corridor FL.17	Normal	N/A	31 Days			
156	17-156	Corridor in front of room 1706	Normal	N/A	31 Days			
157	17-157	In front of Guest Lift FL.17	Normal	N/A	31 Days			
158	18-158	In front of Fireman Lift FL.18	Normal	N/A	31 Days			
159	18-159	Corridor FL.18	Normal	N/A	31 Days			
160	18-160	Corridor in front of room 1806	Normal	N/A	31 Days			
161	18-161	In front of Guest Lift FL.18	Normal	N/A	31 Days			
162	19-162	In front of Lift Fireman Lift FL.19	Normal	N/A	31 Days			
163	19-163	Corridor FL.19	Normal	N/A	31 Days			
164	19-164	In front of Guest Lift FL.19	Normal	N/A	31 Days			
165	19-165	Corridor in front of room 1906	Normal	N/A	31 Days			
166	20-166	In front of Fireman Lift FL.20	Normal	N/A	31 Days			
167	20-167	Corridor FL.20	Normal	N/A	31 Days			
168	20-168	Corridor in front of room 2006	Normal	N/A	31 Days			
169	20-169	In front of Guest Lift FL.20	Normal	N/A	31 Days			
170	21-170	In front of Fireman Lift FL.21	Normal	N/A	31 Days			
171	21-171	Corridor FL.21	Normal	N/A	31 Days			
172	21-172	Corridor in front of room 2106	Normal	N/A	31 Days			
173	21-173	In front of Guest Lift FL.21	Normal	N/A	31 Days			
174	22-174	In front of Fireman Lift FL.22	Normal	N/A	31 Days			
175	22-175	Corridor FL.22	Normal	N/A	31 Days			
176	22-176	Corridor in front of room 2206	Normal	N/A	31 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
177	22-197	In front of Guest Lift FL.22	Normal	N/A	31 Days			
178	23-178	In front of Fireman Lift FL.23	Normal	N/A	31 Days			
179	23-179	Corridor FL.23	Normal	N/A	31 Days			
180	23-180	Corridor in front of room 2306	Normal	N/A	31 Days			
181	23-181	In front of Guest Lift FL.23	Normal	N/A	31 Days			
182	27-182	In front of Fireman Lift FL.24	Normal	N/A	31 Days			
183	24-183	Corridor FL.24	Normal	N/A	31 Days			
184	24-184	Corridor in front of room 2406	Normal	N/A	31 Days			
185	24-185	In front of Guest Lift FL.24	Normal	N/A	31 Days			
186	25-186	In front of Fireman Lift FL.25	Normal	N/A	31 Days			
187	25-187	Corridor FL.25	Normal	N/A	31 Days			
188	25-188	Corridor in front of room 2506	Normal	N/A	31 Days			
189	25-189	In front of Guest Lift FL.25	Normal	N/A	31 Days			
190	26-190	In front of Fireman Lift FL.26	Normal	N/A	31 Days			
191	26-191	Corridor FL.26	Normal	N/A	31 Days			
192	26-192	Corridor in front of room 2606	Normal	N/A	31 Days			
193	26-193	In front of Guest Lift FL.26	Normal	N/A	31 Days			
194	27-194	In front of Fireman Lift FL.27	Normal	N/A	31 Days			
195	27-195	Corridor in front of ST-2 FL.27	Normal	N/A	31 Days			
196	27-196	Corridor FL.27	Normal	N/A	31 Days			
197	27-177	Corridor in front of room 2706	Normal	N/A	31 Days			
198	27-198	Regency Club Counter Reception	Normal	N/A	91 Days			
199	27-199	Regency Club Balcony	Normal	N/A	31 Days			
200	27-200	Regency Club in front of Kitchen	Normal	N/A	31 Days			
201	27-201	In front of Guest Lift FL.27	Normal	N/A	31 Days			
202	28-202	In front of Fireman Lift FL.28	Normal	N/A	31 Days			
203	28-203	Corridor FL.28	Normal	N/A	31 Days			
204	28-204	Corridor in front of room 2806	Normal	N/A	31 Days			
205	28-205	In front of Guest Lift FL.28	Normal	N/A	31 Days			
206	29-206	In front of Fireman Lift FL.29	Normal	N/A	31 Days			
207	29-207	In front of Guest Lift FL.29	Normal	N/A	31 Days			
208	29-208	In front of Kitchen FL.29	Normal	N/A	31 Days			
209	29-209	Balcony Kitchen side FL.29	Out of license	No license	31 Days			Planned to re-license
210	29-210	Front Balcony FL.29	Normal	N/A	31 Days			
211	29-211	Staircase up to FL.30	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
212	29-212	Spectrum Bar FL.29	Normal	N/A	92 Days			
213	29-213	Balcony Sofitel side FL.29	Out of license	No license	31 Days			Planned to re-license
214	30-214	Glass floor FL.30	Out of license	No license	31 Days			Planned to re-license
215	30-215	Spectrum FL. 30	Normal	N/A	31 Days			
216	30-216	Spectrum Bar FL.30	Normal	N/A	31 Days			
217	31-217	In front of Lift Control room FL.31	Normal	N/A	31 Days			
218	31-218	Spectrum FL.31	Normal	N/A	31 Days			

Location: Parking and Retail

1	FLM 01	In front of lift FL.M	Normal		100 Days			
---	--------	-----------------------	--------	--	----------	--	--	--

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
2	FLM 02	Parking FL.M	Normal		100 Days			
3	FLM 03	Parking FL.M (Trendy Side)	Normal		100 Days			
4	FLM 04	Parling FL.M (Loading Side)	Normal		100 Days			
5	FL2 01	In front of lift FL.2	Normal		100 Days			
6	FL2 02	Parking FL.2	Normal		100 Days			
7	FL2 03	Parking FL.2 (Trendy Side)	Normal		100 Days			
8	FL2 04	Parling FL.2 (Loading Side)	Normal		100 Days			
9	FL2A 01	In front of lift FL.2A	Normal		100 Days			
10	FL2A 02	Parking FL.2A	Normal		100 Days			
11	FL2A 03	Parking FL.2A (Trendy Side)	Normal		100 Days			
12	FL2A 04	Parling FL.2A (Loading Side)	Normal		100 Days			
13	FL3 01	In front of lift FL.3	Normal		100 Days			
14	FL3 02	Parking FL.3	Normal		100 Days			
15	FL3 03	Parking FL.3 (Trendy Side)	Normal		100 Days			
16	FL3 04	Parling FL.3 (Loading Side)	Normal		100 Days			
17	FL3A 01	In front of lift FL.3A	Normal		100 Days			
18	FL3A 02	Parking FL.3A	Normal		100 Days			
19	FL3A 03	Parking FL.3A (Trendy Side)	Not clear		100 Days	The Allez (Retail Office) acknowledged		
20	FL3A 04	Parling FL.3A (Loading Side)	Normal		100 Days			
21	FL4 01	In front of lift FL.4	Normal		35 Days			
22	FL4 02	Parking FL.4	Normal		35 Days			
23	FL4 03	Parking FL.4 (Trendy Side)	Normal		35 Days			
24	FL4 04	Parling FL.4 (Loading Side)	Normal		35 Days			
25	FL4A 01	Parking FL.4A (Trendy Side)	Normal		35 Days			
26	FL4A 02	Parling FL.4A (Loading Side)	Normal		35 Days			
27	FL4A 03	Parking FL.4A	Not clear		35 Days	The Allez (Retail Office) acknowledged		
28	FL4A 04	In front of lift FL.4A	Normal		35 Days			
29	FL1 01	BOBO entrance 1	Normal		80 Days			
30	FL1 02	BOBO entrance 2	Normal		80 Days			
31	FL1 03	Under Retail Escalator	Normal		80 Days			
32	FL2 04	Retail Entrance from Parking FL.2	Normal		80 Days			
33	FL2 03	Coffee Club FL.2	Normal		80 Days			
34	FL2 06	Escalator FL.2	Normal		80 Days			
35	FL3 01	In front of lift P5, P6 FL.3	Normal		80 Days			
36	FL3 03	Let's Relax Spa FL.3	Normal		80 Days			
37	FL3 04	Escalator FL.3	Normal		80 Days			
38	FL3 05	In front of ST-1 FL.3	Normal		80 Days			
39	BTS1	Hotel Entrance from BTS	Normal		35 Days			
40	BTS2	BTS Skywalk	Normal		35 Days			
41	BTS3	BTS Entrance	Not clear		35 Days	The Allez (Retail Office) acknowledged		
42	LIFT 01	Lift Parking	Normal		35 Days			
43	LIFT 02	Lift Parking	Normal		35 Days			

Summary	
Status	Amount
Normal	243

Additional comments:

1. SECOM already sent the report of all damaged CCTVs and waiting for quotation to fix it.
2. Out of license CCTVs, still have camera but due to over CCTV IP point from budget requested since beginning. 3 of them were cut off only signal. Planned to re-license.

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
	Damaged	11		3. Comment from Khun Sammy, there must be additional CCTV at Fireman lift landing on L floor.....				
	Not clear	4		4. Comments from Khun Bruce and Khun Ian (Hyatt Global Security) that there must be additional CCTVs at PQS.....				
	Out of license	3		system which is we miss 2 points at Market Cafe.....				
	Total	261						

Checked By
 (.....Anuthida K.....)
 Position: Security Officer
 Date...15.../...5.../...2023...

Reviewed By
 (.....)
 Security Manager
 Date....30.../...5.../...2023...

Acknowledged By
 (.....)
 Chief Engineer
 Date...../...../.....

Fire & Life Safety Monthly Checklist

Month/Year: April 2023

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
31	Hot Water Tank Room	N	N	N	N/A	1	N/A	N/A	N/A	N			Hot Water Tank 1 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Hot Water Tank 2 FL.31	N	
30	Spectrum Store					1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.30	N	
	Automatic Slide Door										1	N	Exit Stair ST-1 FL.29	N	
29	Back Kitchen					N/A	N/A	2	N/A	N			Exit Stair ST-2 (1) FL.29	N	
	Front Kitchen										2	N	Exit Stair ST-2 (2) FL.29	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.29	D	Battery Issue
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Pantry FL.29	D	Battery Issue
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.28	N	
	Guest Lift										1	N	Exit Stair ST-2 FL.28	N	
	Toilet										1	N	MEP FL.28	N	
28	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.28	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.27	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.27	N	
27	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.27	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.27	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.26	N	
	RC Lounge										2	N	Exit Stair ST-2 FL.26	N	
	Kitchen					1	N/A	N/A	N/A	N	1	N	MEP FL.26	N	
26	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.26	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.25	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.25	N	
25	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.25	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.25	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.24	N	
24	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.24	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.24	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.24	N	
23	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.23	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.23	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.23	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.23	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
22	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.22	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.22	N	
21	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.22	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.22	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.21	N	
20	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.21	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.21	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.21	N	
19	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.20	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.20	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.20	N	
18	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.20	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.19	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.19	N	
17	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.19	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.19	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.18	N	
16	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.18	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.18	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.18	N	
15	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.17	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.17	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.17	N	
14	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.17	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.16	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.16	N	
12	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.16	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.16	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.15	N	
11	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.15	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.15	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.15	N	
10	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.14	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.14	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.14	D	Battery Issue
9	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.14	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.12	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.12	N	
	ST-1	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	MEP FL.12	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหนัคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
8	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.12	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.11	N	
7	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.11	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.11	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.11	N	
6A	Cooling Tower	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.10	N	
6	ST-1	D	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.10	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	MEP FL.10	N	
	ST-4										1	N	Pantry FL.10	N	
	Pool Entrance (Lift)										1	N	Exit Stair ST-1 FL.9	N	
	Pool Entrance (Fitness)										1	N	Exit Stair ST-2 FL.9	N	
	Lift S1-S2	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.9	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.9	N	
	Bar					1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.8	N	
5A	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.8	N	
5	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	2	N	MEP FL.8	N	
	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	2	N	Pantry FL.8	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-1 FL.7	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.7	N	
	AV Room (Ballroom 4)					1	N/A	N/A	N/A	N			MEP FL.7	D	Battery Issue
	Regency Ballroom										9	N	Pantry FL.7	N	
	Regency 1-4										8	N	Exit Stair ST-1 FL.6A	N	
	Guest Lift										1	N	Exit Stair ST-2 FL.6A	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.6	N	
	BQ Kitchen					N/A	N/A	3	3	N	1	N	Exit Stair ST-2 FL.6	N	
4A	Foyer					N/A	N/A	1	N/A	N			Exit Stair ST-4 FL.6	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.6	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N			Front Fireman Lift FL.6	N	
4A	Event Office										2	N	Fireman Lift Entrance FL.6	N	
4	ST-1 Sale Office	N	N	N/A	N/A	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-1 FL.5A	N	
	ST-2										4	N	Exit Stair ST-2 FL.5A	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-4 FL.5A	N	
	ST-4										3	N	Corridor FL.5A	N	
	Lift P5-P6	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.5A	N	
	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			AV room FL.5A	N	
	Chiller Room					1	N/A	N/A	N/A	N			Pump Room FL.5A	D	Battery Issue
	Left Kitchen					N/A	N/A	2	2	N			Exit Stair ST-1 FL.5	D	Battery Issue
	Right Kitchen					N/A	N/A	2	2	D 1			Exit Stair ST-2 FL.5	N	
	Inside Kitchen					N/A	N/A	1	1	N	2	N	Exit Stair ST-3 FL.5	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหนคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ	
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ		
	MC										9	N	Exit Stair ST-4 FL.5	N		
	Hostess										2	N	MEP FL.5	N		
	Toilet										1	N	BOH Regency 1 FL.5	D	Battery Issue	
4PK	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N			BOH Regency 2 FL.5	N		
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	BOH Regency 3 FL.5	N		
3A	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	Fireman Lift FL.5	N		
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	Service Lift FL.5	N		
3	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.4A	N		
3PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.4A	N		
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-3 FL.4A	N		
2A	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-4 FL.4A	N		
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exec. Office 1 FL.4A	N		
2	Lift Fireman	D	N	N/A	N/A	1	N/A	N/A	N/A	N			Exec. Office 2 FL.4A	N		
2PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Loading Side FL.4A	N		
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Trendy Side FL.4A	N		
M	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Electric Room 1 FL.4A	N		
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Electric Room 2 FL.4A	D	Battery Issue	
	Front MEP Room	N	N	N/A	N/A									Exit Stair ST-1 FL.4	N	
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.4	N		
L	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-3 FL.4	N		
	ST-2										1	N	Exit Stair ST-4 FL.4	D	Battery Issue	
	ST-4										1	N	Exec. Office FL.4	N		
	Control Room					1	N/A	N/A	N/A	N			MARCOM Office FL.4	N		
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			Chiller Room 1 FL.4	N		
	Flower Room	N	N	N/A	N/A	1	N/A	N/A	N/A	N			Chiller Room 2 FL.4	N		
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.4	N		
	LPG Gas Station					2	N/A	N/A	N/A	N			Fireman Lift FL.4	N		
	Lobby Door (S)										1	N	Service Lift FL.4	N		
	Front Parking Lift										2	N	Loading Side FL.4	D	Battery Issue	
	Loading										4	N	Trendy Side FL.4	D	Battery Issue	
	ST-1 Engineer	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-1 FL.3A	N		
	ST-2 Locker	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-2 FL.3A	N		
	ST-3 General Store	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-4 FL.3A	N		
	ST-4 Fire pump	N	N	N	N	1	N/A	N/A	N/A	N			Loading Side FL.3A	N		
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Trendy Side FL.3A	D	Battery Issue	
	Canteen Kitchen					N/A	N/A	1	1	N			Exit Stair ST-2 FL.3	N		
	Learning Center					1	N/A	N/A	N/A	N			Exit Stair ST-3 FL.3	N		
	Male Locker										2	N	Exit Stair ST-4 FL.3	N		
	Female Locker										2	N	MEP FL.3	N		

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหน้มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
B	Canteen									4	N	MDB 1 FL.3	N		
	HK									1	N	MDB 2 FL.3	N		
	Uniform									1	N	Generator FL.3	N		
	Operator									1	N	Loading Side FL.3	N		
	HR									1	N	Trendy Side FL.3	N		
	GC									2	N	Servive Lift FL.3	N		
	Finance Office									1	N	Fireman Lift FL.3	N		
	Engineer Office									1	N	Exit Stair ST-1 FL.2A	N		
	Engineer Workshop									1	N	Exit Stair ST-2 FL.2A	N		
	Front Hygene Office									2	N	Exit Stair ST-4 FL.2A	N		
	Main Kitchen Corridor									2	N	Loading Side FL.2A	N		
	Total									111				119	0
													Exit Stair ST-1 FL.2	N	
													Exit Stair ST-2 FL.2	N	
													Exit Stair ST-3 FL.2	N	
													Exit Stair ST-4 FL.2	N	
													MEP FL.2	N	
													Loading Side FL.2	D	Battery Issue
													Trendy Side FL.2	N	
													Servive Lift FL.2	N/A	Uninstalled
													Fireman Lift FL.2	N	
													Exit Stair ST-1 FL.M	N	
													Exit Stair ST-2 FL.M	N	
													Exit Stair ST-3 FL.M	N	
													Exit Stair ST-4 FL.M	N	
													Front MEP FL.M	N	
													MEP FL.M	N	
													Loading Side FL.M	N	
													Trendy Side FL.M	N	
													Exit Stair ST-1 FLL	N	
													Exit Stair ST-2 FLL	N	
													Exit Stair ST-3 FLL	N	
													Exit Stair ST-4 FLL	N	
													Control Room 1 FLL	N	
													Control Room 2 FLL	N	
													Fireman Lift FLL	N	
													Discharge Fireman Lift FLL	D	Battery Issue

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหน้คลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
													Front Service Lift FL.L	N	
													Exit Stair ST-1 FL.B	N	
													Exit Stair ST-2 FL.B	N	
													Exit Stair ST-3 FL.B	N	
													Exit Stair ST-4 (1) FL.B	N	
													Exit Stair ST-4 (2) FL.B	N	
													MEP FL.B	N	
													Fireman Lift FL.B	N	
													Male Staff Locker 1	N	
													Male Staff Locker 2	N	
													Female Staff Locker	N	
													Front HK Office FL.B	N	
													Canteen 1 FL.B	N	
													Canteen 2 FL.B	N	
													TV Corner FL.B	N	
													Corridor front Canteen	N	
													Lerning Center	N	
													HR Office	N	
													Finance Office	D	Battery Issue
													Workshop Entrance	D	One light bulb is broken
													Front Cashier	N	
													Front FB Office	N	
													FB Office	N	
													Front General Store	N	
													Cold Kitchen Entrance	N	
													Front Hygene Office	N	
													Pump Room	N	
													Compressor Room	N	
													Firepump Room	N	
													Server Room	N	
													Total	217	

Condition	Summary				
	Fire Hose Cabinet	Fire Extinguisher	Fire Blanket	Fire Exit Sign	Emergency Light
Total	111	131	10	183	217
Normal	99	130	10	183	199
Damage	2	1	0	0	17
Used	0	0	0	0	0
Lost	0	0	0	0	0
N/A	13	0	0	0	1

Prepared By

(Thanakorn A)

Security Manager
Date 30/05/2023

Acknowledged By










(.....)

Chief Engineer









Fire Cart Monthly Checklist

Month/Year: 15 May2023

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
1	Fireman Suit Cabinet		1		
2	Fire Cart Cabinet		1		
3	Fireman Suit		4 Suit		
4	Fireman Helmet		4 Pcs.		
5	Fireman Hood		N/A	N/A	Need to Order
6	SCBA		2 Set		200psi/240psi
7	SCBA Mask		2 Set		
8	Fire Fighting Nozzle		N/A	N/A	Pending
9	Fire Hose 1.5"		2 Pcs.		

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
10	Rope		2 Roll		
11	Axe		2 Pcs.		
12	Steel Bolt Cutter		2 Pcs.		
13	3-Ways Fire Hydrant Connection		1 Pcs.		
14	Spinal Board		1 Pcs.		
15	Head Immobilizer		2 Set		
16	Scoop Stretcher		1 Pcs.		
17	Oxygen Tank		2 Set		

Checked By
(Jakkarin P.)
Team Leader Security
Date 15/05/ 2023

Reviewed By
(Thanakorn A)
Security Manager
Date 15/05/ 2023

Acknowledged By
(.....)
Chief Engineer
Date/...../.....

CCTV System Monthly Report

CCTV System Monthly Report								
Month of Report:		June 2023						
Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
Location: Hotel								
1	B-001	Server room (IT)	Normal	N/A	92 Days			
2	B-002	In front of Engineer office	Normal	N/A	62 Days			
3	B-003	In front of Engineer Store	Normal	N/A	62 Days			
4	B-004	Cashier Drop Safe	Normal	N/A	62 Days			
5	B-005	Cashier Account room	Normal	N/A	62 Days			
6	B-006	Finance Store	Normal	N/A	62 Days			
7	B-007	In front of Lift F1,F2	Normal	N/A	62 Days			
8	B-008	Corridor in front of Canteen	Normal	N/A	62 Days			
9	B-009	Canteen room	Normal	N/A	62 Days			
10	B-010	Canteen room	Normal	N/A	62 Days			
11	B-011	Corridor in front of Staff Locker	Normal	N/A	62 Days			
12	B-012	Corridor in front of Uniform room	Normal	N/A	62 Days			
13	B-013	Corridor in front of Staff Locker	Normal	N/A	62 Days			
14	B-014	Staff Rest room	Normal	N/A	62 Days			
15	B-015	Staff Rest room	Normal	N/A	62 Days			
16	B-016	Corridor in front of HK Office	Normal	N/A	62 Days			
17	B-017	Corridor in front of Fire pump room	Normal	N/A	62 Days			
18	B-018	HR Office	Normal	N/A	62 Days			
19	B-019	In front of Lift S1,S2	Normal	N/A	62 Days			
20	B-020	Corridor in front of Main Kitchen	Normal	N/A	62 Days			
21	B-021	Corridor in front of F&B Store	Normal	N/A	62 Days			
22	B-022	Corridor in front of F&B Office	Normal	N/A	62 Days			
23	B-023	Uniform room	Normal	N/A	62 Days			
24	L-024	Entrance Lobby drop off	Normal	N/A	62 Days			
25	L-025	Lobby drop off	Normal	N/A	62 Days			
26	L-026	360 rotating camera at Lobby drop off	Damaged	Wirring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
27	L-027	Exit Lobby drop off	Normal	N/A	62 Days			
28	L-028	In front of Car parking F.I.L	Normal	N/A	61 Days			
29	L-029	In front of Car parking F.I.L 2	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
30	L-030	In front of Lift P5-P6	Normal	N/A	62 Days			
31	L-031	Entrance Lobby	Normal	N/A	62 Days			
32	L-032	Concierge room	Normal	N/A	62 Days			
33	L-033	In front of Concierge room	Normal	N/A	62 Days			
34	L-034	Stair 1 Floor L	Normal	N/A	62 Days			
35	L-035	360 rotating camera at Lobby Lounge	Normal	N/A	92 Days			
36	L-036	Lobby Lounge	Normal	N/A	61 Days			
37	L-037	Counter Front office (Right)	Normal	N/A	62 Days			
38	L-038	Office Front Department	Normal	N/A	62 Days			
39	L-039	Safe room	Normal	N/A	62 Days			
40	L-040	Counter Front office (Left)	Normal	N/A	92 Days			
41	L-041	In front of Lift P1-P4	Normal	N/A	62 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
42	L-042	Walkway to Parking Lift Floor L	Normal	N/A	62 Days			
43	L-043	In front of Lift PK1-2	Normal	N/A	62 Days			
44	L-044	Carpark Floor L1	Normal	N/A	62 Days			
45	L-045	Carpark Floor L2	Normal	N/A	62 Days			
46	L-046	Carpark Entrance	Normal	N/A	32 Days			
47	L-047	Gas Station	Normal	N/A	32 Days			
48	L-048	Under Retail Escalator	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
49	L-049	ST-3 Discharge Floor L	Normal	N/A	31 Days			
50	L-050	Parking for Rider under Escalator	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
51	L-051	Cashier point	Normal	N/A	31 Days			
52	L-052	Loading	Not clear	N/A	31 Days			Need to adjust focus of camera
53	L-053	Control room	Damaged	Wiring cable issue	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
54	L-054	In front of Control room	Normal	N/A	31 Days			
55	L-055	In front of Lift S1-2 FL.L	Normal	N/A	31 Days			
56	L-056	Time Keeper Entrance	Normal	N/A	31 Days			
57	L-057	360 rotating camera at TK	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
58	L-058	Loading Gas Station side	Normal	N/A	31 Days			
59	L-059	Parking Exit	Normal	N/A	31 Days			
60	P5-060	Lift P5	Normal	N/A	31 Days			
61	P6-061	Lift P6	Normal	N/A	31 Days			
62	P1-062	Lift P1	Normal	N/A	31 Days			
63	P2-063	Lift P2	Normal	N/A	31 Days			
64	P3-064	Lift P3	Normal	N/A	31 Days			
65	P4-065	Lift P4	Normal	N/A	31 Days			
66	P7-066	Fireman Lift 1	Normal	N/A	31 Days			
67	P8-067	Fireman Lift 2	Normal	N/A	31 Days			
68	S2-068	Service Lift 1	Normal	N/A	31 Days			
69	S1-069	Service Lift 2	Normal	N/A	31 Days			
70	M-070	In front of ST-2 FL.M	Normal	N/A	31 Days			
71	M-071	In front of ST-4 FL.M	Normal	N/A	31 Days			
72	M-072	Corridor In front of ST-3 FL.M (Retail)	Normal	N/A	31 Days			
73	M-073	In front of ST-2 FL.2 (Retail)	Normal	N/A	31 Days			
74	M-074	In front of The Coffee club (Retail)	Normal	N/A	31 Days			
75	2-075	In front of ST-4 FL.2	Normal	N/A	31 Days			
76	2-076	In front of Service Lift FL.2	Normal	N/A	31 Days			
77	2A-077	Car parking FL.2A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
78	2A-078	In front of ST-4 FL.2A	Normal	N/A	31 Days			
79	3-079	In front of ST-2 FL.3	Normal	N/A	31 Days			
80	3-080	In front of Lift Service FL.3	Normal	N/A	31 Days			
81	3-081	In front of ST-4 FL.3	Normal	N/A	31 Days			
82	3A-082	Car parking FL.3A	Normal	N/A	31 Days			
83	3A-083	In front of ST-4 FL.3A	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
84	4-084	Balcony entrance	Normal	N/A	31 Days			
85	4-085	Sukhumvit Gallery	Normal	N/A	31 Days			
86	4-086	In front of Kitchen FL.4	Normal	N/A	31 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
87	4-087	In front of Lift P1-P4 FL.4	Normal	N/A	31 Days			
88	4-088	In front of Firman Lift FL.4	Damaged	N/A	31 Days	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
89	4-089	In front of ST-2 FL.4	Normal	N/A	31 Days			
90	4-090	Inside Market Café	Normal	N/A	31 Days			
91	4-091	In front of Service Lift FL.4	Normal	N/A	31 Days			
92	4-092	Kitchen Exit FL.4	Normal	N/A	31 Days			
93	4-093	In front of ST-4 FL.4	Normal	N/A	3 Days			
94	4A-094	Car parking FL.4A	Normal	N/A	31 Days			
95	4-095	In front of ST-4 FL.4	Normal	N/A	31 Days			
96	5-096	Foyer front of ST-1 FL.5	Normal	N/A	31 Days			
97	5-097	In front of Escalator FL.5	Normal	N/A	31 Days			
98	5-098	In front of ST-1 FL.5	Normal	N/A	31 Days			
99	5-099	360 rotating camera at foyer FL.5	Damaged	Rotating motor broken	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
100	5-100	In front of Lift P1-4	Normal	N/A	31 Days			
101	5-101	In front of ST-2 FL.5 (Foyer)	Normal	N/A	31 Days			
102	5-102	Between ST-2 and Ballroom	Normal	N/A	31 Days			
103	5-103	Ballroom	Normal	N/A	31 Days			
104	5-104	In front of BQ store	Normal	N/A	31 Days			
105	5-105	In front of service lift FL.5	Normal	N/A	31 Days			
106	5-106	In front of ST-3 FL.5	Normal	N/A	31 Days			
107	5A-107	Corridor BOH behind Ballroom	Normal	N/A	31 Days			
108	5A-108	In front of service lift FL.5A	Normal	N/A	31 Days			
109	6-109	Inside Fire Exit ST-1 FL.6	Normal	N/A	31 Days			
110	6-110	In front of Fitness	Normal	N/A	31 Days			
111	6-111	In front of Male Locker FL.6	Normal	N/A	31 Days			
112	6-112	In front of Female Locker FL.6	Normal	N/A	31 Days			
113	6-113	In front of Lift P1-4 FL.6	Normal	N/A	31 Days			
114	6-114	In front of Fireman lift Entrance FL.6	Normal	N/A	31 Days			
115	6-115	In front of Fireman Lift FL.6	Normal	N/A	31 Days			
116	6-116	Pool Bar FL.6	Normal	N/A	91 Days			
117	6-117	In front of Service lift FL.6	Normal	N/A	31 Days			
118	7-118	In front of Fireman Lift FL.7	Normal	N/A	31 Days			
119	7-119	Corridor FL.7	Normal	N/A	31 Days			
120	7-120	Corridor in front of room 706	Normal	N/A	31 Days			
121	7-121	In front of Guest Lift FL.7	Normal	N/A	31 Days			
122	8-122	In front of Fireman Lift FL.8	Normal	N/A	31 Days			
123	8-123	Corridor FL.8	Normal	N/A	31 Days			
124	8-124	Corridor in front of room 806	Normal	N/A	31 Days			
125	8-125	In front of Guest Lift FL.8	Normal	N/A	31 Days			
126	10-126	In front of Fireman Lift FL.10	Normal	N/A	31 Days			
127	9-127	Corridor FL.9	Normal	N/A	31 Days			
128	9-128	Corridor in front of room 906	Normal	N/A	31 Days			
129	9-129	In front of Guest Lift FL.9	Normal	N/A	31 Days			
130	9-130	In front of Fireman Lift FL.9	Normal	N/A	31 Days			
131	10-131	Corridor FL.10	Normal	N/A	31 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
132	10-132	Corridor in front of room 1006	Normal	N/A	31 Days			
133	10-133	In front of Guest Lift FL.10	Normal	N/A	31 Days			
134	11-134	In front of Fireman Lift FL.11	Normal	N/A	31 Days			
135	11-135	Corridor FL.11	Normal	N/A	31 Days			
136	11-136	Corridor in front of room 1106	Normal	N/A	31 Days			
137	11-137	in front of Guest Lift FL.11	Normal	N/A	31 Days			
138	12-138	In front of Fireman Lift FL.12	Normal	N/A	31 Days			
139	12-139	Corridor FL.12	Normal	N/A	31 Days			
140	12-140	Corridor in front of room 1206	Normal	N/A	31 Days			
141	12-141	In front of Guest Lift FL.12	Normal	N/A	31 Days			
142	14-142	In front of Fireman Lift FL.14	Normal	N/A	31 Days			
143	14-143	Corridor FL.14	Normal	N/A	31 Days			
144	14-144	Corridor in front of room 1406	Normal	N/A	31 Days			
145	14-145	In front of Guest Lift FL.14	Normal	N/A	31 Days			
146	15-146	In front of Fireman Lift FL.15	Normal	N/A	31 Days			
147	15-147	Corridor FL.15	Normal	N/A	31 Days			
148	15-148	Corridor in front of room 1506	Normal	N/A	31 Days			
149	15-149	In front of Guest Lift FL.15	Normal	N/A	31 Days			
150	16-150	In front of Fireman Lift FL.16	Normal	N/A	31 Days			
151	16-151	Corridor FL.16	Normal	N/A	31 Days			
152	16-152	Corridor in front of room1606	Normal	N/A	31 Days			
153	16-153	In front of Guest Lift FL.16	Normal	N/A	31 Days			
154	17-154	In front of Fireman Lift FL.17	Normal	N/A	31 Days			
155	17-155	Corridor FL.17	Normal	N/A	31 Days			
156	17-156	Corridor in front of room 1706	Normal	N/A	31 Days			
157	17-157	In front of Guest Lift FL.17	Normal	N/A	31 Days			
158	18-158	In front of Fireman Lift FL.18	Normal	N/A	31 Days			
159	18-159	Corridor FL.18	Normal	N/A	31 Days			
160	18-160	Corridor in front of room 1806	Normal	N/A	31 Days			
161	18-161	In front of Guest Lift FL.18	Normal	N/A	31 Days			
162	19-162	In front of Lift Fireman Lift FL.19	Normal	N/A	31 Days			
163	19-163	Corridor FL.19	Normal	N/A	31 Days			
164	19-164	In front of Guest Lift FL.19	Normal	N/A	31 Days			
165	19-165	Corridor in front of room 1906	Normal	N/A	31 Days			
166	20-166	In front of Fireman Lift FL.20	Normal	N/A	31 Days			
167	20-167	Corridor FL.20	Normal	N/A	31 Days			
168	20-168	Corridor in front of room 2006	Normal	N/A	31 Days			
169	20-169	In front of Guest Lift FL.20	Normal	N/A	31 Days			
170	21-170	In front of Fireman Lift FL.21	Normal	N/A	31 Days			
171	21-171	Corridor FL.21	Normal	N/A	31 Days			
172	21-172	Corridor in front of room 2106	Normal	N/A	31 Days			
173	21-173	In front of Guest Lift FL.21	Normal	N/A	31 Days			
174	22-174	In front of Fireman Lift FL.22	Normal	N/A	31 Days			
175	22-175	Corridor FL.22	Normal	N/A	31 Days			
176	22-176	Corridor in front of room 2206	Normal	N/A	31 Days			

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
177	22-197	In front of Guest Lift FL.22	Normal	N/A	31 Days			
178	23-178	In front of Fireman Lift FL.23	Normal	N/A	31 Days			
179	23-179	Corridor FL.23	Normal	N/A	31 Days			
180	23-180	Corridor in front of room 2306	Normal	N/A	31 Days			
181	23-181	In front of Guest Lift FL.23	Normal	N/A	31 Days			
182	27-182	In front of Fireman Lift FL.24	Normal	N/A	31 Days			
183	24-183	Corridor FL.24	Normal	N/A	31 Days			
184	24-184	Corridor in front of room 2406	Normal	N/A	31 Days			
185	24-185	In front of Guest Lift FL.24	Normal	N/A	31 Days			
186	25-186	In front of Fireman Lift FL.25	Normal	N/A	31 Days			
187	25-187	Corridor FL.25	Normal	N/A	31 Days			
188	25-188	Corridor in front of room 2506	Normal	N/A	31 Days			
189	25-189	In front of Guest Lift FL.25	Normal	N/A	31 Days			
190	26-190	In front of Fireman Lift FL.26	Normal	N/A	31 Days			
191	26-191	Corridor FL.26	Normal	N/A	31 Days			
192	26-192	Corridor in front of room 2606	Normal	N/A	31 Days			
193	26-193	In front of Guest Lift FL.26	Normal	N/A	31 Days			
194	27-194	In front of Fireman Lift FL.27	Normal	N/A	31 Days			
195	27-195	Corridor in front of ST-2 FL.27	Normal	N/A	31 Days			
196	27-196	Corridor FL.27	Normal	N/A	31 Days			
197	27-177	Corridor in front of room 2706	Normal	N/A	31 Days			
198	27-198	Regency Club Counter Reception	Normal	N/A	91 Days			
199	27-199	Regency Club Balcony	Normal	N/A	31 Days			
200	27-200	Regency Club in front of Kitchen	Normal	N/A	31 Days			
201	27-201	In front of Guest Lift FL.27	Normal	N/A	31 Days			
202	28-202	In front of Fireman Lift FL.28	Normal	N/A	31 Days			
203	28-203	Corridor FL.28	Normal	N/A	31 Days			
204	28-204	Corridor in front of room 2806	Normal	N/A	31 Days			
205	28-205	In front of Guest Lift FL.28	Normal	N/A	31 Days			
206	29-206	In front of Fireman Lift FL.29	Normal	N/A	31 Days			
207	29-207	In front of Guest Lift FL.29	Normal	N/A	31 Days			
208	29-208	In front of Kitchen FL.29	Normal	N/A	31 Days			
209	29-209	Balcony Kitchen side FL.29	Out of license	No license	31 Days			Planned to re-license
210	29-210	Front Balcony FL.29	Normal	N/A	31 Days			
211	29-211	Staircase up to FL.30	Damaged	Out of order	-	SECOM team already came to do PM	21-23/11/2022	Waiting for the Quotation
212	29-212	Spectrum Bar FL.29	Normal	N/A	92 Days			
213	29-213	Balcony Sofitel side FL.29	Out of license	No license	31 Days			Planned to re-license
214	30-214	Glass floor FL.30	Out of license	No license	31 Days			Planned to re-license
215	30-215	Spectrum FL. 30	Normal	N/A	31 Days			
216	30-216	Spectrum Bar FL.30	Normal	N/A	31 Days			
217	31-217	In front of Lift Control room FL.31	Normal	N/A	31 Days			
218	31-218	Spectrum FL.31	Normal	N/A	31 Days			

Location: Parking and Retail

1	FLM 01	In front of lift FL.M	Normal		100 Days			
---	--------	-----------------------	--------	--	----------	--	--	--

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
2	FLM 02	Parking FL.M	Normal		100 Days			
3	FLM 03	Parking FL.M (Trendy Side)	Normal		100 Days			
4	FLM 04	Parling FL.M (Loading Side)	Normal		100 Days			
5	FL2 01	In front of lift FL.2	Normal		100 Days			
6	FL2 02	Parking FL.2	Normal		100 Days			
7	FL2 03	Parking FL.2 (Trendy Side)	Normal		100 Days			
8	FL2 04	Parling FL.2 (Loading Side)	Normal		100 Days			
9	FL2A 01	In front of lift FL.2A	Normal		100 Days			
10	FL2A 02	Parking FL.2A	Normal		100 Days			
11	FL2A 03	Parking FL.2A (Trendy Side)	Normal		100 Days			
12	FL2A 04	Parling FL.2A (Loading Side)	Normal		100 Days			
13	FL3 01	In front of lift FL.3	Normal		100 Days			
14	FL3 02	Parking FL.3	Normal		100 Days			
15	FL3 03	Parking FL.3 (Trendy Side)	Normal		100 Days			
16	FL3 04	Parling FL.3 (Loading Side)	Normal		100 Days			
17	FL3A 01	In front of lift FL.3A	Normal		100 Days			
18	FL3A 02	Parking FL.3A	Normal		100 Days			
19	FL3A 03	Parking FL.3A (Trendy Side)	Not clear		100 Days	The Allez (Retail Office) acknowledged		
20	FL3A 04	Parling FL.3A (Loading Side)	Normal		100 Days			
21	FL4 01	In front of lift FL.4	Normal		35 Days			
22	FL4 02	Parking FL.4	Normal		35 Days			
23	FL4 03	Parking FL.4 (Trendy Side)	Normal		35 Days			
24	FL4 04	Parling FL.4 (Loading Side)	Normal		35 Days			
25	FL4A 01	Parking FL.4A (Trendy Side)	Normal		35 Days			
26	FL4A 02	Parling FL.4A (Loading Side)	Normal		35 Days			
27	FL4A 03	Parking FL.4A	Not clear		35 Days	The Allez (Retail Office) acknowledged		
28	FL4A 04	In front of lift FL.4A	Normal		35 Days			
29	FL1 01	BOBO entrance 1	Normal		80 Days			
30	FL1 02	BOBO entrance 2	Normal		80 Days			
31	FL1 03	Under Retail Escalator	Normal		80 Days			
32	FL2 04	Retail Entrance from Parking FL.2	Normal		80 Days			
33	FL2 03	Coffee Club FL.2	Normal		80 Days			
34	FL2 06	Escalator FL.2	Normal		80 Days			
35	FL3 01	In front of lift P5, P6 FL.3	Normal		80 Days			
36	FL3 03	Let's Relax Spa FL.3	Normal		80 Days			
37	FL3 04	Escalator FL.3	Normal		80 Days			
38	FL3 05	In front of ST-1 FL.3	Normal		80 Days			
39	BTS1	Hotel Entrance from BTS	Normal		35 Days			
40	BTS2	BTS Skywalk	Normal		35 Days			
41	BTS3	BTS Entrance	Not clear		35 Days	The Allez (Retail Office) acknowledged		
42	LIFT 01	Lift Parking	Normal		35 Days			
43	LIFT 02	Lift Parking	Normal		35 Days			

Summary	
Status	Amount
Normal	243

Additional comments:

1. The quotation was received, total price including repair, replace, additional CCTV and upgrade server is THB 930,498.25 (including Vat)

Camera No.	Camera ID.	Installed Location	Camera Status	Status Description	Recording Duration	Maintenance Notification	Notification Date	Remarks
	Damaged	11		2. Out of license CCTVs, still have camera but due to over CCTV IP point from budget requested since beginning. 3 of them were cut off only signal. Planned to re-license.				
	Not clear	4						
	Out of license	3						
	Total	261						

Checked By
 (.....Sompong L.....)
 Position: Security Officer
 Date..22../..6../..2023..

Reviewed By
 (Thanakorn Anurak)
 Security Manager
 Date....28../..6../..2023..

Acknowledged By
 (.....)
 Chief Engineer
 Date...../...../.....

Fire & Life Safety Monthly Checklist

Month/Year: June 2023

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหน้คลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
31	Hot Water Tank Room	N	N	N	N/A	1	N/A	N/A	N/A	N			Hot Water Tank 1 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Hot Water Tank 2 FL.31	N	
30	Spectrum Store					1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.31	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.30	N	
	Automatic Slide Door										1	N	Exit Stair ST-1 FL.29	N	
29	Back Kitchen					N/A	N/A	2	N/A	N			Exit Stair ST-2 (1) FL.29	N	
	Front Kitchen										2	N	Exit Stair ST-2 (2) FL.29	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.29	D	Battery Issue
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Pantry FL.29	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.28	N	
	Guest Lift										1	N	Exit Stair ST-2 FL.28	N	
	Toilet										1	N	MEP FL.28	N	
28	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.28	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.27	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.27	N	
27	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.27	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.27	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.26	N	
	RC Lounge										2	N	Exit Stair ST-2 FL.26	N	
	Kitchen					1	N/A	N/A	N/A	N	1	N	MEP FL.26	N	
26	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.26	D	Battery Issue
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.25	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.25	N	
25	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.25	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.25	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.24	N	
24	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.24	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.24	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.24	N	
23	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.23	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.23	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.23	N	
	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.23	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าห่มคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออกไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
22	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.22	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.22	N	
21	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.22	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.22	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.21	N	
20	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.21	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.21	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.21	N	
19	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.20	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.20	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.20	N	
18	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.20	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.19	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.19	N	
17	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.19	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.19	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.18	N	
16	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.18	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.18	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.18	N	
15	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.17	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.17	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.17	N	
14	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.17	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.16	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.16	N	
12	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.16	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.16	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.15	N	
11	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.15	D	Battery Issue
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.15	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.15	N	
10	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.14	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.14	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.14	N	
9	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.14	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-1 FL.12	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.12	N	
	ST-1	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	MEP FL.12	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหนัคลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
8	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.12	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.11	N	
7	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-2 FL.11	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	MEP FL.11	N	
	Pantry	N	N	N	N	1	N/A	N/A	N/A	N			Pantry FL.11	N	
6A	Cooling Tower	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.10	N	
6	ST-1	D	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.10	N	
	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	MEP FL.10	N	
	ST-4										1	N	Pantry FL.10	N	
	Pool Entrance (Lift)										1	N	Exit Stair ST-1 FL.9	N	
	Pool Entrance (Fitness)										1	N	Exit Stair ST-2 FL.9	N	
	Lift S1-S2	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.9	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Pantry FL.9	N	
	Bar					1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.8	N	
5A	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.8	N	
5	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	2	N	MEP FL.8	N	
	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	2	N	Pantry FL.8	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-1 FL.7	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.7	N	
	AV Room (Ballroom 4)					1	N/A	N/A	N/A	N			MEP FL.7	D	Battery Issue
	Regency Ballroom										9	N	Pantry FL.7	N	
	Regency 1-4										8	N	Exit Stair ST-1 FL.6A	N	
	Guest Lift										1	N	Exit Stair ST-2 FL.6A	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.6	N	
						N/A	N/A	3	3	N	1	N	Exit Stair ST-2 FL.6	N	
4A	ST-2	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.6	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N			Front Fireman Lift FL.6	D	Battery Issue
4A	Event Office										2	N	Fireman Lift Entrance FL.6	N	
4	ST-1 Sale Office	N	N	N/A	N/A	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-1 FL.5A	N	
	ST-2										4	N	Exit Stair ST-2 FL.5A	N	
	ST-3	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-4 FL.5A	N	
	ST-4										3	N	Corridor FL.5A	N	
	Lift P5-P6	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.5A	N	
	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			AV room FL.5A	N	
	Chiller Room					1	N/A	N/A	N/A	N			Pump Room FL.5A	D	Battery Issue
	Left Kitchen					N/A	N/A	2	2	N			Exit Stair ST-1 FL.5	D	Battery Issue
	Right Kitchen					N/A	N/A	2	2	D 1			Exit Stair ST-2 FL.5	N	
	Inside Kitchen					N/A	N/A	1	1	N	2	N	Exit Stair ST-3 FL.5	D	Battery Issue

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหน้คลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
	MC										9	N	Exit Stair ST-4 FL.5	N	
	Hostess										2	N	MEP FL.5	N	
	Toilet										1	N	BOH Regency 1 FL.5	N	
4PK	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N			BOH Regency 2 FL.5	N	
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	BOH Regency 3 FL.5	N	
3A	ST-2	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	Fireman Lift FL.5	D	Battery Issue
	ST-4	N	N	N/A	N/A	1	N/A	N/A	N/A	N	1	N	Service Lift FL.5	N	
3	Lift Fireman	N	N	N	N/A	1	N/A	N/A	N/A	N			Exit Stair ST-1 FL.4A	N	
3PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-2 FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-3 FL.4A	N	
2A	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-4 FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exec. Office 1 FL.4A	N	
2	Lift Fireman	D	N	N/A	N/A	1	N/A	N/A	N/A	N			Exec. Office 2 FL.4A	N	
2PK	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Loading Side FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Trendy Side FL.4A	N	
M	ST-2	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Electric Room 1 FL.4A	N	
	ST-4	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Electric Room 2 FL.4A	N	
	Front MEP Room	N	N	N/A	N/A								Exit Stair ST-1 FL.4	N	
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			Exit Stair ST-2 FL.4	N	
L	ST-1	N	N	N	N	1	N/A	N/A	N/A	N	1	N	Exit Stair ST-3 FL.4	N	
	ST-2										1	N	Exit Stair ST-4 FL.4	D	Battery Issue
	ST-4										1	N	Exec. Office FL.4	N	
	Control Room					1	N/A	N/A	N/A	N			MARCOM Office FL.4	N	
	Parking	N	N	N	N	1	N/A	N/A	N/A	N			Chiller Room 1 FL.4	N	
	Flower Room	N	N	N/A	N/A	1	N/A	N/A	N/A	N			Chiller Room 2 FL.4	N	
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			MEP FL.4	N	
	LPG Gas Station					2	N/A	N/A	N/A	N			Fireman Lift FL.4	N	
	Lobby Door (S)										1	N	Service Lift FL.4	N	
	Front Parking Lift										2	N	Loading Side FL.4	N	
	Loading										4	N	Trendy Side FL.4	N	
	ST-1 Engineer	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-1 FL.3A	N	
	ST-2 Locker	N	N	N	N	1	N/A	N/A	N/A	N	2	N	Exit Stair ST-2 FL.3A	N	
	ST-3 General Store	N	N	N	N	1	N/A	N/A	N/A	N	3	N	Exit Stair ST-4 FL.3A	N	
	ST-4 Fire pump	N	N	N	N	1	N/A	N/A	N/A	N			Loading Side FL.3A	D	Battery Issue
	Lift Fireman	N	N	N	N	1	N/A	N/A	N/A	N			Trendy Side FL.3A	N	
	Canteen Kitchen					N/A	N/A	1	1	N			Exit Stair ST-2 FL.3	N	
	Learning Center					1	N/A	N/A	N/A	N			Exit Stair ST-3 FL.3	N	
	Bekery kitchen					N/A	N/A	1	1	N			Exit Stair ST-4 FL.3	N	
	Male Locker										2	N	MEP FL.3	N	
	Female Locker										2	N	MDB 1 FL.3	N	

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหน้คลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
B	Canteen									4	N	MDB 2 FL.3	N		
	HK									1	N	Generator FL.3	N		
	Uniform									1	N	Loading Side FL.3	N		
	Operator									1	N	Trendy Side FL.3	N		
	HR									1	N	Servive Lift FL.3	N		
	GC									2	N	Fireman Lift FL.3	N		
	Finance Office									1	N	Exit Stair ST-1 FL.2A	N		
	Engineer Office									1	N	Exit Stair ST-2 FL.2A	N		
	Engineer Workshop									1	N	Exit Stair ST-4 FL.2A	N		
	Front Hygene Office									2	N	Loading Side FL.2A	N		
	Main Kitchen Corridor									2	N	Trendy Side FL.2A	D	Battery Issue	
	Total									111				119	0
												Exit Stair ST-2 FL.2	N		
											Exit Stair ST-3 FL.2	N			
											Exit Stair ST-4 FL.2	N			
											MEP FL.2	N			
											Loading Side FL.2	N			
											Trendy Side FL.2	N			
											Servive Lift FL.2	N/A	Uninstalled		
											Fireman Lift FL.2	N			
											Exit Stair ST-1 FL.M	N			
											Exit Stair ST-2 FL.M	D	Battery Issue		
											Exit Stair ST-3 FL.M	N			
											Exit Stair ST-4 FL.M	N			
											Front MEP FL.M	N			
											MEP FL.M	N			
											Loading Side FL.M	N			
											Trendy Side FL.M	N			
											Exit Stair ST-1 FL.L	N			
											Exit Stair ST-2 FL.L	N			
											Exit Stair ST-3 FL.L	N			
											Exit Stair ST-4 FL.L	N			
											Control Room 1 FL.L	N			
											Control Room 2 FL.L	N			
											Fireman Lift FL.L	N			
											Discharge Fireman Lift FL.L	N			
											Front Service Lift FL.L	N			

N = Normal D = Damage U = Used L = Lost N/A = Not Applicable

Floor ชั้น	Location สถานที่	Fire Hose Cabinet ตู้ดับเพลิง				Extinguisher ถังดับเพลิง			Fire Blanket ผ้าหน้คลุมเพลิง	Condition สภาพ	Fire Exit Sign ป้ายทางหนีไฟ	Condition สภาพ	Emergency Light ไฟฉุกเฉิน		Status/Remark สถานะ/หมายเหตุ
		Cabinet Condition สภาพตู้	Hose Reel สายดับเพลิง	Hydrant ข้อต่อ สามเร็ว	Brass Cap ฝาทอง เหลือง	Dry Chemical ผงเคมีแห้ง	CO2 คาร์บอนไดออก ไซด์	Foam โฟม					Location สถานที่	Condition สภาพ	
													Exit Stair ST-1 FL.B	N	
													Exit Stair ST-2 FL.B	N	
													Exit Stair ST-3 FL.B	N	
													Exit Stair ST-4 (1) FL.B	N	
													Exit Stair ST-4 (2) FL.B	N	
													MEP FL.B	N	
													Fireman Lift FL.B	N	
													Male Staff Locker 1	N	
													Male Staff Locker 2	N	
													Female Staff Locker	N	
													Front HK Office FL.B	N	
													Canteen 1 FL.B	N	
													Canteen 2 FL.B	N	
													TV Corner FL.B	N	
													Corridor front Canteen	N	
													Lerning Center	N	
													HR Office	N	
													Finance Office	D	Battery Issue
													Workshop Entrance	N	
													Front Cashier	N	
													Front FB Office	N	
													FB Office	N	
													Front General Store	N	
													Cold Kitchen Entrance	N	
													Front Hygene Office	N	
													Pump Room	N	
													Compressor Room	N	
													Firepump Room	N	
													Server Room	N	
													Total	216	

Condition	Summary				
	Fire Hose Cabinet	Fire Extinguisher	Fire Blanket	Fire Exit Sign	Emergency Light
Total	111	132	11	181	216
Normal	99	130	11	181	202
Damage	2	1	0	0	14
Used	0	0	0	0	0
Lost	0	0	0	0	0
N/A	13	0	0	0	1

Prepared By

(Thanakorn A)
Security Manager
Date 28/06/2023



Acknowledged By

(.....)
Chief Engineer









Fire Cart Monthly Checklist

Month/Year: June 2023

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
1	Fireman Suit Cabinet		1	N	
2	Fire Cart Cabinet		1	N	
3	Fireman Suit		4 Suit	N	
4	Fireman Helmet		4 Pcs.	N	
5	Fireman Hood		N/A	N/A	Need to Order
6	SCBA		2 Set	N	200psi/240psi
7	SCBA Mask		2 Set	N	
8	Fire Fighting Nozzle		N/A	N/A	Pending
9	Fire Hose 1.5"		2 Pcs.	N	

N = Normal D = Damage L = Lost N/A = Not Applicable

No. ลำดับ	Equipment อุปกรณ์	Picture รูป	Quantity จำนวน	Status สถานะ	Remark หมายเหตุ
10	Rope		2 Roll	N	
11	Axe		2 Pcs.	N	
12	Steel Bolt Cutter		2 Pcs.	N	
13	3-Ways Fire Hydrant Connection		1 Pcs.	N	
14	Spinal Board		1 Pcs.	N	
15	Head Immobilizer		2 Set	N	
16	Scoop Stretcher		1 Pcs.	N	
17	Oxygen Tank		2 Set	N	

Checked By

(Jakkarin P.)
Security Supervisor
Date 10/06/2023

Reviewed By

(Thanakorn Anurak.)
Security Manager
Date 28/06/2023

Acknowledged By

(.....)
Chief Engineer
Date/...../.....