

ผลการตรวจวัดคุณภาพอากาศภายในอาคาร

Report No. : 2022-5005489/ 001 (Page 1 of 1) Issued date: October 26, 2022

CLIENT : GRANDE ASSET HOTELS AND PROPERTY PUBLIC COMPANY LIMITED
CONTACT : Khun Suwit Polrachom
ADDRESS : 1 Soi Sukhumvit 13 (Sang Chan), Sukhumvit Road, Klongtoey Nue, Wattana, Bangkok 10110
 Tel.02-098-1262 Email: suwit.polrachom@hyatt.com

Analysis Report

SAMPLE DESIGNATED AS : Indoor Air Quality
SAMPLING LOCATION : Lobby on 1st Floor at Hyatt Regency Bangkok
SAMPLING DATE: October 14, 2022

Parameters	Units	Results		Standard*
		10:05 hrs.	13:51 hrs.	
1. Temperature	°C	22.6	22.3	24.0 -26.0
2. Relative Humidity	%RH	74.1	75.0	<70
3. Carbon dioxide (CO ₂)	ppm	84(566)	95(577)	700 above outdoor
4. Carbon monoxide (CO)	ppm	0.0	3.4	<9
5. Formaldehyde	ppm	0.00	0.00	<0.1
6. Ozone	ppm	0.00	0.00	<0.1
7. Total VOCs	ppm	0.00	0.00	<3
8. Particulate matter less than 2.5 micron (PM-2.5)	µg/m ³	6.05	9.80	<35
9. Particulate matter less than 10 micron (PM-10)	µg/m ³	30.65	41.98	<50
10. Total Bacteria (Airborne)	CFU/m ³	90		<500
11. Yeast & Mold (Airborne)	CFU/m ³	Not Detected		<500

Remark: - Outdoor on October 14, 2022; Temperature is 29.2 °C, Relative Humidity is 61.9 %RH and Carbon dioxide is 482 ppm.
Source: * Code of Practice for Indoor air quality for air-conditioned building; Singapore Standard SS 554:2009



 (Thepsan Yommana)
 Technical Manager

TY/CG/PPT/PPT

This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

E 253964

SGS (Thailand) Limited | Environment, Health and Safety 100 Nanglinchee Road Chongnonsee Yannawa Bangkok 10120
 t +66 (0)2 678 18 13 f +66 (0)2 678 06 22 www.sgs.com

Report No. : 2022-5005489/ 002 (Page 1 of 1) Issued date: October 26, 2022

CLIENT : GRANDE ASSET HOTELS AND PROPERTY PUBLIC COMPANY LIMITED
CONTACT : Khun Suwit Polrachom
ADDRESS : 1 Soi Sukhumvit 13 (Sang Chan), Sukhumvit Road, Klongtoey Nue, Wattana, Bangkok 10110
 Tel.02-098-1262 Email: suwit.polrachom@hyatt.com

Analysis Report

SAMPLE DESIGNATED AS : Indoor Air Quality
SAMPLING LOCATION : Restaurant on 4th Floor at Hyatt Regency Bangkok
SAMPLING DATE: October 14, 2022

Parameters	Units	Results		Standard*
		10:39 hrs.	14:05 hrs.	
1. Temperature	°C	23.7	23.9	24.0 -26.0
2. Relative Humidity	%RH	75.6	73.1	<70
3. Carbon dioxide (CO ₂)	ppm	51(533)	26(456)	700 above outdoor
4. Carbon monoxide (CO)	ppm	3.3	0.0	<9
5. Formaldehyde	ppm	0.00	0.00	<0.1
6. Ozone	ppm	0.00	0.00	<0.1
7. Total VOCs	ppm	0.00	0.00	<3
8. Particulate matter less than 2.5 micron (PM-2.5)	µg/m ³	8.95	8.60	<35
9. Particulate matter less than 10 micron (PM-10)	µg/m ³	34.59	29.24	<50
10. Total Bacteria (Airborne)	CFU/m ³	70		<500
11. Yeast & Mold (Airborne)	CFU/m ³	10		<500

Remark: - Outdoor on October 14, 2022; Temperature is 29.2 °C, Relative Humidity is 61.9 %RH and Carbon dioxide is 482 ppm.
Source: * Code of Practice for Indoor air quality for air-conditioned building; Singapore Standard SS 554:2009


 TY/CG/PPT/PPT
 (Thepsan Yommana)
 Technical Manager

This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

E 253965

SGS (Thailand) Limited | Environment, Health and Safety 100 Nanglinchee Road Chongnonsee Yannawa Bangkok 10120
 t +66 (0)2 678 18 13 f +66 (0)2 678 06 22 www.sgs.com

Report No. : 2022-5005489/ 003 (Page 1 of 1) Issued date: October 26, 2022

CLIENT : GRANDE ASSET HOTELS AND PROPERTY PUBLIC COMPANY LIMITED
CONTACT : Khun Suwit Polrachom
ADDRESS : 1 Soi Sukhumvit 13 (Sang Chan), Sukhumvit Road, Klongtoey Nue, Wattana, Bangkok 10110
 Tel.02-098-1262 Email: suwit.polrachom@hyatt.com

Analysis Report

SAMPLE DESIGNATED AS : Indoor Air Quality **SAMPLING DATE:** October 14, 2022
SAMPLING LOCATION : Buffet line of restaurant on 4th Floor at Hyatt Regency Bangkok

Parameters	Units	Results		Standard*
		10:26 hrs.	13:58 hrs.	
1. Temperature	°C	23.9	23.1	24.0 -26.0
2. Relative Humidity	%RH	71.5	73.3	<70
3. Carbon dioxide (CO ₂)	ppm	108(590)	15(467)	700 above outdoor
4. Carbon monoxide (CO)	ppm	0.0	3.2	<9
5. Formaldehyde	ppm	0.00	0.00	<0.1
6. Ozone	ppm	0.00	0.00	<0.1
7. Total VOCs	ppm	0.00	0.00	<3
8. Particulate matter less than 2.5 micron (PM-2.5)	µg/m ³	12.77	8.95	<35
9. Particulate matter less than 10 micron (PM-10)	µg/m ³	35.65	38.90	<50
10. Total Bacteria (Airborne)	CFU/m ³	130		<500
11. Yeast & Mold (Airborne)	CFU/m ³	Not Detected		<500

Remark: - Outdoor on October 14, 2022; Temperature is 29.2 °C, Relative Humidity is 61.9 %RH and Carbon dioxide is 482 ppm.
Source: * Code of Practice for Indoor air quality for air-conditioned building; Singapore Standard SS 554:2009


 (Thepsan Yommana)
 Technical Manager

TY/CG/PPT/PPT

This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

E 253966

SGS (Thailand) Limited | Environment, Health and Safety 100 Nanglinchee Road Chongnonsee Yannawa Bangkok 10120
 t +66 (0)2 678 18 13 f +66 (0)2 678 06 22 www.sgs.com

Report No. : 2022-5005489/ 004 (Page 1 of 1) Issued date: October 26, 2022

CLIENT : GRANDE ASSET HOTELS AND PROPERTY PUBLIC COMPANY LIMITED
CONTACT : Khun Suwit Polrachom
ADDRESS : 1 Soi Sukhumvit 13 (Sang Chan), Sukhumvit Road, Klongtoey Nue, Wattana, Bangkok 10110
 Tel.02-098-1262 Email: suwit.polrachom@hyatt.com

Analysis Report

SAMPLE DESIGNATED AS : Indoor Air Quality
SAMPLING LOCATION : Ballroom on 5th Floor at Hyatt Regency Bangkok
SAMPLING DATE: October 14, 2022

Parameters	Units	Results		Standard*
		11:10 hrs.	14:30 hrs.	
1. Temperature	°C	25.7	25.4	24.0 -26.0
2. Relative Humidity	%RH	68.0	67.3	<70
3. Carbon dioxide (CO ₂)	ppm	21(461)	6(476)	700 above outdoor
4. Carbon monoxide (CO)	ppm	0.0	3.5	<9
5. Formaldehyde	ppm	0.00	0.00	<0.1
6. Ozone	ppm	0.00	0.00	<0.1
7. Total VOCs	ppm	0.00	0.00	<3
8. Particulate matter less than 2.5 micron (PM-2.5)	µg/m ³	9.81	11.82	<35
9. Particulate matter less than 10 micron (PM-10)	µg/m ³	38.28	41.81	<50
10. Total Bacteria (Airborne)	CFU/m ³	70		<500
11. Yeast & Mold (Airborne)	CFU/m ³	40		<500

Remark: - Outdoor on October 14, 2022; Temperature is 29.2 °C, Relative Humidity is 61.9 %RH and Carbon dioxide is 482 ppm.
Source: * Code of Practice for Indoor air quality for air-conditioned building; Singapore Standard SS 554:2009


 (Thepsan Yommana)
 Technical Manager

TY/CG/PPT/PPT

This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

E 253967

SGS (Thailand) Limited | Environment, Health and Safety 100 Nanglinchee Road Chongnonsee Yannawa Bangkok 10120
 t +66 (0)2 678 18 13 f +66 (0)2 678 06 22 www.sgs.com

Report No. : 2022-5005489/ 005 (Page 1 of 1) **Issued date:** October 26, 2022

CLIENT : GRANDE ASSET HOTELS AND PROPERTY PUBLIC COMPANY LIMITED
CONTACT : Khun Suwit Polrachom
ADDRESS : 1 Soi Sukhumvit 13 (Sang Chan), Sukhumvit Road, Klongtoey Nue, Wattana, Bangkok 10110
 Tel.02-098-1262 Email: suwit.polrachom@hyatt.com

Analysis Report

SAMPLE DESIGNATED AS : Indoor Air Quality
SAMPLING LOCATION : 27th Floor at Hyatt Regency Bangkok

SAMPLING DATE: October 14, 2022

Parameters	Units	Results		Standard*
		10:55 hrs.	14:30 hrs.	
1. Temperature	°C	24.8	25.4	24.0 -26.0
2. Relative Humidity	%RH	68.9	67.9	<70
3. Carbon dioxide (CO ₂)	ppm	46(528)	31(451)	700 above outdoor
4. Carbon monoxide (CO)	ppm	0.0	3.8	<9
5. Formaldehyde	ppm	0.00	0.00	<0.1
6. Ozone	ppm	0.00	0.00	<0.1
7. Total VOCs	ppm	0.00	0.00	<3
8. Particulate matter less than 2.5 micron (PM-2.5)	µg/m ³	10.84	9.87	<35
9. Particulate matter less than 10 micron (PM-10)	µg/m ³	82.55	43.54	<50
10. Total Bacteria (Airborne)	CFU/m ³	90		<500
11. Yeast & Mold (Airborne)	CFU/m ³	Not Detected		<500

Remark: - Outdoor on October 14, 2022; Temperature is 29.2 °C, Relative Humidity is 61.9 %RH and Carbon dioxide is 482 ppm.

Source: * Code of Practice for Indoor air quality for air-conditioned building; Singapore Standard SS 554:2009

TY/CG/PPT/PPT



Thepsan
 (Thepsan Yommana)
 Technical Manager

This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

E 253968

SGS (Thailand) Limited | Environment, Health and Safety 100 Nanglinchee Road Chongnonsee Yannawa Bangkok 10120
 t +66 (0)2 678 18 13 f +66 (0)2 678 06 22 www.sgs.com