# ภาคผนวก ข
# เอกสารประกอบผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม



# ภาคผนวก ข-1

ภาพประกอบผลการปฏิบัติตามมาตรการป้องกัน
และแก้ไขผลกระทบสิ่งแวดล้อม






**รูปที่ 1 ป้ายจำกัดความเร็ว**




**รูปที่ 2 สันนูนเพื่อลดความเร็ว**







**รูปที่ 3 ถนนภายในโครงการ**




**รูปที่ 4 ป้ายห้ามติดเครื่องยนต์ทิ้งไว้ภายในบริเวณที่จอดรถ**




**รูปที่ 5 เจ้าหน้าที่อำนวยความสะดวกในการจราจรบริเวณทางเข้า-ออกโครงการ**













**รูปที่ 6 พื้นที่สีเขียว**







**รูปที่ 7 ระบบบำบัดน้ำเสีย**




**รูปที่ 8 ถังสำรองน้ำชั้นหลังคา**




**รูปที่ 9 ป้ายรณรงค์การใช้น้ำอย่างประหยัด**




**รูปที่ 10 ถังรองรับมูลฝอย บริเวณห้องพักและห้องน้ำ**








**รูปที่ 11 ถังรองรับมูลฝอย บริเวณโครงการ**







**รูปที่ 12 ห้องพักมูลฝอยรวมของโครงการ**







**รูปที่ 13 แม่บ้านคอยดูแลรักษาความสะอาดของโครงการ**

**รูปที่ 14 เจ้าหน้าที่ดูแลรักษาพื้นที่สีเขียวของโครงการ**




**รูปที่ 15 เครื่องกำเนิดไฟฟ้าฉุกเฉิน**





**รูปที่ 16 ไฟฉุกเฉิน**




**รูปที่ 17 ป้ายรณรงค์การใช้ไฟฟ้า**




**รูปที่ 18 ป้ายประชาสัมพันธ์เรื่องการอนุรักษ์พลังงาน**




**รูปที่ 19 ระบบท่อยืน (Fire Stand Pipe)**




**รูปที่ 20 ตู้เก็บสายฉีดน้ำดับเพลิง**




**รูปที่ 21 ถังดับเพลิงเคมี**




**รูปที่ 22 หัวรับน้ำดับเพลิง**




**รูปที่ 23 บันไดหนีไฟ และป้ายแสดงเส้นทางหนีไฟ**




**รูปที่ 24 ระบบควบคุมแจ้งเตือนเพลิงไหม้ (Fire Alarm Control Panel)**




**รูปที่ 25 เครื่องตรวจจับควัน (Smoke Detector)**




**รูปที่ 26 หัวฉีดน้ำอัตโนมัติ**




**รูปที่ 27 กริ่งสัญญาณเตือนภัย**
**(Fire Alarm Bell)**




**รูปที่ 28 เครื่องแจ้งเหตุโดยใช้มือดึง**
**(Manual Pull Station)**








**รูปที่ 29 พื้นที่หนีไฟทางอากาศ**




**รูปที่ 30 ป้ายแสดงจุดรวมพล**




**รูปที่ 31 ป้ายแนะนำการใช้อุปกรณ์**




**รูปที่ 32 แผนผังแสดงเส้นทางหนีไฟ**




**รูปที่ 33 ตู้เก็บอุปกรณ์และชุดดับเพลิง**








**รูปที่ 34 ช่องระบายอากาศ**




**รูปที่ 35 ป้ายสัญญาณจราจร**




**รูปที่ 36 การทำความสะอาดถนนบริเวณโครงการ**







**รูปที่ 37 รางระบายน้ำ บริเวณโครงการ**

# ภาคผนวก ข-2

เอกสารการตรวจสอบการทำงาน
ของระบบบำบัดน้ำเสียของโครงการ



Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY MONTH มกราคม 66

AERATOR PUMP ~~1~~ 2 3 TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Testing Timer Operate | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 3 | Check Air Inlet Filter | | | | | | |
| | 4 | Check Chain | | | | | | |
| | 5 | Check Piping And Valves | | | | | | |
| 6 Month Jun,Dec | 6 | Check Oil Lubricate | | | | | | |
| | 7 | Cleanning In The Tank | | | | | | |
| | 8 | Cleanning And Painting Piping | | | | | | |
| | 9 | Check Terminal In Tank | | | | | | |
| | 10 | Fitting CB And Busbar | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED GREASES

R = REPAIR P = REPLACED

NOTE .....

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

MONTH ..... 1 มีนาคม 2566

AERATOR PUMP ..1,2,3..

TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Testing Timer Operate | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 3 | Check Air Inlet Filter | | | | | | |
| | 4 | Check Chain | | | | | | |
| | 5 | Check Piping And Valves | | | | | | |
| 6 Month Jun,Dec | 6 | Check Oil Lubricate | | | | | | |
| | 7 | Cleanning In The Tank | | | | | | |
| | 8 | Cleanning And Painting Piping | | | | | | |
| | 9 | Check Terminal In Tank | | | | | | |
| | 10 | Fitting CB And Busbar | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED GREASES

R = REPAIR P = REPLACED

NOTE .....

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY MONTH มีนาคม 66

AERATOR PUMP 1,2,3 TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Testing Timer Operate | | | | | ✓ | |
| 3 Month | 3 | Check Air Inlet Filter | | | | | ✓ | |
| | 4 | Check Chain | | | | | ✓ | |
| Mar,Jun,Sep,Dec | 5 | Check Piping And Valves | | | | | ✓ | |
| 6 Month | 6 | Check Oil Lubricate | | | | | | |
| | 7 | Cleanning In The Tank | | | | | | |
| | 8 | Cleanning And Painting Piping | | | | | | |
| | 9 | Check Terminal In Tank | | | | | | |
| Jun,Dec | 10 | Fitting CB And Busbar | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED GREASES

R = REPAIR P = REPLACED

NOTE .....

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY MONTH ธันวาคม 66

AERATOR PUMP 1,2,3 TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Testing Timer Operate | | | | | ✓ | |
| 3 Month | 3 | Check Air Inlet Filter | | | | | | |
| | 4 | Check Chain | | | | | | |
| Mar,Jun,Sep,Dec | 5 | Check Piping And Valves | | | | | | |
| 6 Month | 6 | Check Oil Lubricate | | | | | | |
| | 7 | Cleanning In The Tank | | | | | | |
| | 8 | Cleanning And Painting Piping | | | | | | |
| | 9 | Check Terminal In Tank | | | | | | |
| Jun,Dec | 10 | Fitting CB And Busbar | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED GREASES

R = REPAIR P = REPLACED

NOTE .....

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY [redacted] RECHEC [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY MONTH มิ.ย. 66

AERATOR PUMP 1,2,3 TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Testing Timer Operate | | | | | ✓ | |
| 3 Month | 3 | Check Air Inlet Filter | | | | | | |
| | 4 | Check Chain | | | | | | |
| Mar,Jun,Sep,Dec | 5 | Check Piping And Valves | | | | | | |
| 6 Month | 6 | Check Oil Lubricate | | | | | | |
| | 7 | Cleanning In The Tank | | | | | | |
| | 8 | Cleanning And Painting Piping | | | | | | |
| | 9 | Check Terminal In Tank | | | | | | |
| Jun,Dec | 10 | Fitting CB And Busbar | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED GREASES

R = REPAIR P = REPLACED

NOTE .....

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY MONTH สิงหาคม 66

AERATOR PUMP 1,2,3 TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Testing Timer Operate | | | | | ✓ | |
| 3 Month | 3 | Check Air Inlet Filter | | | | | ✓ | |
| | 4 | Check Chain | | | | | ✓ | |
| Mar,Jun,Sep,Dec | 5 | Check Piping And Valves | | | | | ✓ | |
| 6 Month | 6 | Check Oil Lubricate | | | | | ✓ | |
| | 7 | Cleanning In The Tank | ✓ | | | | | |
| | 8 | Cleanning And Painting Piping | ✓ | | | | | |
| | 9 | Check Terminal In Tank | ✓ | | | | | |
| Jun,Dec | 10 | Fitting CB And Busbar | | | | | ✓ | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED GREASES

R = REPAIR P = REPLACED

NOTE .....

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY [redacted] .....

RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EFFLUENT PUMP..... 1-2

MONTH ..มกราคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | ✓ | ✓ | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | 3 | Fitting All Inside Panel Control | | | ✓ | | | |
| | 4 | Testing Overload | | | ✓ | | ✓ | |
| | 5 | Testing Timer Operation | | ✓ | | | ✓ | |
| | 6 | Check Sludge Level In The Tank | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | | | | | | |
| | 8 | Check Guide Well | | | | | | |
| | 9 | Check Piping And Valve | | | | | | |
| 6 Month Jun,Dec | 10 | Check Oil Lubrication | | | | | | |
| | 11 | Cleanning All In The Tank | | | | | | |
| | 12 | Cleanning And Painting Pump&Piping | | | | | | |
| | 13 | Check Therminal In Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EFFLUENT PUMP..... 1-2

MONTH .....
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | | |
| | 2 | Cleanning Overall Inside Panel Control | | | | | | |
| | 3 | Fitting All Inside Panel Control | | | | | | |
| | 4 | Testing Overload | | | | | | |
| | 5 | Testing Timer Operation | | | | | | |
| | 6 | Check Sludge Level In The Tank | | | | | | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | | | | | | |
| | 8 | Check Guide Well | | | | | | |
| | 9 | Check Piping And Valve | | | | | | |
| 6 Month Jun,Dec | 10 | Check Oil Lubrication | | | | | | |
| | 11 | Cleanning All In The Tank | | | | | | |
| | 12 | Cleanning And Painting Pump&Piping | | | | | | |
| | 13 | Check Therminal In Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY . [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EFFLUENT PUMP..1-2

MONTH ..มีนาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | ✓ | ✓ | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | 3 | Fitting All Inside Panel Control | | | | | ✓ | |
| | 4 | Testing Overload | | | | | ✓ | |
| | 5 | Testing Timer Operation | | ✓ | | | ✓ | |
| | 6 | Check Sludge Level In The Tank | | | ✓ | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | ✓ | | | | | |
| | 8 | Check Guide Well | | | | | ✓ | |
| | 9 | Check Piping And Valve | | | | | ✓ | |
| 6 Month Jun,Dec | 10 | Check Oil Lubrication | | | | | | |
| | 11 | Cleanning All In The Tank | | | | | | |
| | 12 | Cleanning And Painting Pump&Piping | | | | | | |
| | 13 | Check Therminal In Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....
RECORD BY ..[redacted]. RECHECK BY [redacted].....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EFFLUENT PUMP 1-2

MONTH 12/29/8/24 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | ✓ | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | 3 | Fitting All Inside Panel Control | | ✓ | | | ✓ | |
| | 4 | Testing Overload | | | ✓ | | | |
| | 5 | Testing Timer Operation | | | | | ✓ | |
| | 6 | Check Sludge Level In The Tank | | ✓ | | | | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | | | | | | |
| | 8 | Check Guide Well | | | | | | |
| | 9 | Check Piping And Valve | | | | | | |
| 6 Month Jun,Dec | 10 | Check Oil Lubrication | | | | | | |
| | 11 | Cleanning All In The Tank | | | | | | |
| | 12 | Cleanning And Painting Pump&Piping | | | | | | |
| | 13 | Check Therminal In Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] .....

RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EFFLUENT PUMP 1-2

MONTH พฤศจิกายน 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | | ✓ | | | | |
| | 3 | Fitting All Inside Panel Control | | | | | ✓ | |
| | 4 | Testing Overload | | | ✓ | | ✓ | |
| | 5 | Testing Timer Operation | | ✓ | | | ✓ | |
| | 6 | Check Sludge Level In The Tank | | | ✓ | | | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | | | | | | |
| | 8 | Check Guide Well | | | | | | |
| | 9 | Check Piping And Valve | | | | | | |
| 6 Month Jun,Dec | 10 | Check Oil Lubrication | | | | | | |
| | 11 | Cleanning All In The Tank | | | | | | |
| | 12 | Cleanning And Painting Pump&Piping | | | | | | |
| | 13 | Check Therminal In Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY .....

RECHECK BY .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EFFLUENT PUMP 1-2

MONTH มีนาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | | ✓ | | | ✓ | |
| | 3 | Fitting All Inside Panel Control | | | ✓ | | ✓ | |
| | 4 | Testing Overload | | | ✓ | | ✓ | |
| | 5 | Testing Timer Operation | | | | | ✓ | |
| | 6 | Check Sludge Level In The Tank | | | ✓ | | | |
| 3 Month<br>Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | | | ✓ | | | |
| | 8 | Check Guide Well | | | | | ✓ | |
| | 9 | Check Piping And Valve | | ✓ | | | ✓ | |
| 6 Month<br>Jun,Dec | 10 | Check Oil Lubrication | | | | | ✓ | |
| | 11 | Cleanning All In The Tank | | | ✓ | | | |
| | 12 | Cleanning And Painting Pump&Piping | | | | | ✓ | |
| | 13 | Check Therminal In Tank | | ✓ | | | ✓ | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
RETURN SLUDGE PUMP..1,2..

MONTH 21/07/21 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | / | |
| | 2 | Cleanning Overall Inside Panel Control | | / | | | | |
| | 3 | Fitting All Inside Panel Control | | | | | / | |
| | 4 | Testing Overload | | | | | / | |
| | 5 | Testing Timer Operation | | | | | / | |
| | 6 | Check Sludge Level In The Tank | | | | | / | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | | | | | | |
| | 8 | Check Guide Well | | | | | | |
| | 9 | Check Piping And Valve | | | | | | |
| 6 Month Jun,Dec | 10 | Check Oil Lubrication | | | | | | |
| | 11 | Cleanning All In The Tank | | | | | | |
| | 12 | Cleanning And Painting Pump&Piping | | | | | | |
| | 13 | Check Therminal In Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
RETURN SLUDGE PUMP 1,2

MONTH กุมภาพันธ์ 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | 3 | Fitting All Inside Panel Control | | | | | ✓ | |
| | 4 | Testing Overload | | | | | ✓ | |
| | 5 | Testing Timer Operation | | | | | ✓ | |
| | 6 | Check Sludge Level In The Tank | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | | | | | | |
| | 8 | Check Guide Well | | | | | | |
| | 9 | Check Piping And Valve | | | | | | |
| 6 Month Jun,Dec | 10 | Check Oil Lubrication | | | | | | |
| | 11 | Cleanning All In The Tank | | | | | | |
| | 12 | Cleanning And Painting Pump&Piping | | | | | | |
| | 13 | Check Therminal In Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
RETURN SLUDGE PUMP...1/2...

MONTH ...มีนาคม '66...
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | 3 | Fitting All Inside Panel Control | | | | | ✓ | |
| | 4 | Testing Overload | | | | | ✓ | |
| | 5 | Testing Timer Operation | | | | | ✓ | |
| | 6 | Check Sludge Level In The Tank | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | ✓ | | | | | |
| | 8 | Check Guide Well | | | | | ✓ | |
| | 9 | Check Piping And Valve | | | | | ✓ | |
| 6 Month Jun,Dec | 10 | Check Oil Lubrication | | | | | | |
| | 11 | Cleanning All In The Tank | | | | | | |
| | 12 | Cleanning And Painting Pump&Piping | | | | | | |
| | 13 | Check Therminal In Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....
RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
RETURN SLUDGE PUMP....1,2....

MONTH ....12 ธันวาคม 66....
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | 3 | Fitting All Inside Panel Control | | | | | ✓ | |
| | 4 | Testing Overload | | | | | ✓ | |
| | 5 | Testing Timer Operation | | | | | ✓ | |
| | 6 | Check Sludge Level In The Tank | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | | | | | | |
| | 8 | Check Guide Well | | | | | | |
| | 9 | Check Piping And Valve | | | | | | |
| 6 Month Jun,Dec | 10 | Check Oil Lubrication | | | | | | |
| | 11 | Cleanning All In The Tank | | | | | | |
| | 12 | Cleanning And Painting Pump&Piping | | | | | | |
| | 13 | Check Therminal In Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY ..[redacted]..

RECHECK BY ...[redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
RETURN SLUDGE PUMP.....

MONTH มีนาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | 3 | Fitting All Inside Panel Control | | | | | ✓ | |
| | 4 | Testing Overload | | | | | ✓ | |
| | 5 | Testing Timer Operation | | | | | ✓ | |
| | 6 | Check Sludge Level In The Tank | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | | | | | | |
| | 8 | Check Guide Well | | | | | | |
| | 9 | Check Piping And Valve | | | | | | |
| 6 Month Jun,Dec | 10 | Check Oil Lubrication | | | | | | |
| | 11 | Cleanning All In The Tank | | | | | | |
| | 12 | Cleanning And Painting Pump&Piping | | | | | | |
| | 13 | Check Therminal In Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
RETURN SLUDGE PUMP 1/2

MONTH มิถุนายน 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | 3 | Fitting All Inside Panel Control | | | | | ✓ | |
| | 4 | Testing Overload | | | | | ✓ | |
| | 5 | Testing Timer Operation | | | | | ✓ | |
| | 6 | Check Sludge Level In The Tank | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning & Check Shake Valve | ✓ | | | | | |
| | 8 | Check Guide Well | | | | | ✓ | |
| | 9 | Check Piping And Valve | | | | | ✓ | |
| 6 Month | 10 | Check Oil Lubrication | | | | | ✓ | |
| | 11 | Cleanning All In The Tank | ✓ | | | | | |
| | 12 | Cleanning And Painting Pump&Piping | ✓ | | | | | |
| Jun,Dec | 13 | Check Therminal In Tank | | | | ✓ | ✓ | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....
RECORD B[redacted]..... RECHECK BY [redacted].....

# ภาคผนวก ข-3

ใบเสร็จรับเงินค่าธรรมเนียมการดูดไขมัน



L&H Property Co.,Ltd.
100 Wireless Road, Lumpini, Patumwan, Bangkok 10330, Thailand.
Tel. +66 2 055 9000 Fax. +66 2 055 9009
Tax ID : 0105548017097 Branch : 00003

# ใบสั่งจาย

เลขที่ใบสั่งจาย : PVHP303660214

วันที่บันทึก : 03/03/2566

โครงการที่สั่งจาย : HP303 - GCP-PC

แผนก : Engineering Department

จาย : บริษัท จีพีเอ เอ็นไวรอนเมนทอล แอนด์ เซฟตี้ เซอร์วิสเซส จำกัด

ประเภทการจาย : ทั่วไป

| ลำดับที่ | รายการสั่งจาย | รหัสบัญชี | จำนวนเงิน | Vat | รวมจำนวนเงิน |
|---|---|---|---|---|---|
| 1 | ค่าวัสดุอุปกรณ์ & ค่าจ้างเหมา - ระบบประปาสุขาภิบาล ดูดไขมันและกากตะกอน Septic ชั้น L และ P4 | 50813 : R&M Exp. Utilities System | [redacted] | | |
| | | รวม : | | | |

[redacted]

นาย มโนรส กำแก้ว
Engineer Manager

นาย มโนรส กำแก้ว
Engineer Manager

นาย อนนท์ กงศิริขันธ์
General Manager

# ภาคผนวก ข-4

เอกสารการตรวจสอบท่อประปา

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
COLD WATER PUMP ..... NO. 1, 2

MONTH ..... มกราคม 06
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | ✓ | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | ✓ | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Testing Floatless Operation | | ✓ | | | | |
| 3 Month Mar,Jun,Sep,Dec | 3 | Check&Cleaned Strainer | | | | | | |
| | 4 | Check Package Seal | | | | | | |
| | 5 | Check Coupling & Alignment | | | | | | |
| | 6 | Check Piping & Valve | | | | | | |
| | 7 | Check Shake Valve | | | | | | |
| 6 Month Jun,Dec | 8 | Check & Cleanning Foot Valve | | | | | | |
| | 9 | Check Pressure Gauge | | | | | | |
| | 10 | Cleanning And Painting Pump&Pipes | | | | | | |
| | 11 | Check Therminal In Tank | | | | | | |
| 1 Year | 12 | Cleanning All In The Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] ...

RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
COLD WATER PUMP NO. 1, 2

MONTH กุมภาพันธ์ 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | ✓ | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | ✓ | | ✓ | |
| | | Fitting All Inside Panel Control | ✓ | | ✓ | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Testing Floatless Operation | | | | ✓ | | |
| 3 Month Mar,Jun,Sep,Dec | 3 | Check&Cleaned Strainer | | | | | | |
| | 4 | Check Package Seal | | | | | | |
| | 5 | Check Coupling & Alignment | | | | | | |
| | 6 | Check Piping & Valve | | | | | | |
| | 7 | Check Shake Valve | | | | | | |
| 6 Month Jun,Dec | 8 | Check & Cleanning Foot Valve | | | | | | |
| | 9 | Check Pressure Gauge | | | | | | |
| | 10 | Cleanning And Painting Pump&Pipes | | | | | | |
| | 11 | Check Therminal In Tank | | | | | | |
| 1 Year | 12 | Cleanning All In The Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
COLD WATER PUMP ..... NO. 1, 2

MONTH ..... มีนาคม/66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | ✓ | | | ✓ | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | ✓ | | | | |
| | 2 | Testing Floatless Operation | | | ✓ | | | |
| 3 Month Mar,Jun,Sep,Dec | 3 | Check&Cleaned Strainer | | | | | ✓ | |
| | 4 | Check Package Seal | | | | | ✓ | |
| | 5 | Check Coupling & Alignment | | | ✓ | | | |
| | 6 | Check Piping & Valve | | ✓ | | | | |
| | 7 | Check Shake Valve | | | | | ✓ | |
| 6 Month Jun,Dec | 8 | Check & Cleanning Foot Valve | | | | | | |
| | 9 | Check Pressure Gauge | | | | | | |
| | 10 | Cleanning And Painting Pump&Pipes | | | | | | |
| | 11 | Check Therminal In Tank | | | | | | |
| 1 Year | 12 | Cleanning All In The Tank | | | | | | |

N = NORMAL  UN = UNORMAL  C = CLEANNING  A = ADJUST&ADDED
R = REPAIR  P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....
RECORD BY . [redacted]  RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
COLD WATER PUMP ..... NO. 1,2

MONTH ..... มกราคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | ✓ | | ✓ | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | | Fitting All Inside Panel Control | | ✓ | | | | |
| | | Testing Overload | | | ✓ | | ✓ | |
| | 2 | Testing Floatless Operation | | | | ✓ | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 3 | Check&Cleaned Strainer | | | | | | |
| | 4 | Check Package Seal | | | | | | |
| | 5 | Check Coupling & Alignment | | | | | | |
| | 6 | Check Piping & Valve | | | | | | |
| | 7 | Check Shake Valve | | | | | | |
| 6 Month Jun,Dec | 8 | Check & Cleanning Foot Valve | | | | | | |
| | 9 | Check Pressure Gauge | | | | | | |
| | 10 | Cleanning And Painting Pump&Pipes | | | | | | |
| | 11 | Check Therminal In Tank | | | | | | |
| 1 Year | 12 | Cleanning All In The Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY .... [redacted] RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
COLD WATER PUMP ..NO. 1, 2

MONTH ..มิถุนายน 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | ✓ | ✓ | ✓ | |
| | | Cleanning Overall Inside Panel Control | | ✓ | | | ✓ | |
| | | Fitting All Inside Panel Control | | | ✓ | | | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Testing Floatless Operation | | | ✓ | | | |
| 3 Month Mar,Jun,Sep,Dec | 3 | Check&Cleaned Strainer | | | ✓ | | | |
| | 4 | Check Package Seal | | | | | ✓ | |
| | 5 | Check Coupling & Alignment | | ✓ | | | ✓ | |
| | 6 | Check Piping & Valve | | | | | ✓ | |
| | 7 | Check Shake Valve | | | | | ✓ | |
| 6 Month Jun,Dec | 8 | Check & Cleanning Foot Valve | | | ✓ | | | |
| | 9 | Check Pressure Gauge | | ✓ | | | | |
| | 10 | Cleanning And Painting Pump&Pipes | | ✓ | | | | |
| | 11 | Check Therminal In Tank | | ✓ | | | ✓ | |
| 1 Year | 12 | Cleanning All In The Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY .. [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
COLD WATER PUMP ..NO:1,2

MONTH ..พฤศจิกายน 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | | Fitting All Inside Panel Control | | ✓ | | | | |
| | | Testing Overload | | | ✓ | | ✓ | |
| | 2 | Testing Floatless Operation | | ✓ | | | | |
| 3 Month Mar,Jun,Sep,Dec | 3 | Check&Cleaned Strainer | | | | | | |
| | 4 | Check Package Seal | | | | | | |
| | 5 | Check Coupling & Alignment | | | | | | |
| | 6 | Check Piping & Valve | | | | | | |
| | 7 | Check Shake Valve | | | | | | |
| 6 Month Jun,Dec | 8 | Check & Cleanning Foot Valve | | | | | | |
| | 9 | Check Pressure Gauge | | | | | | |
| | 10 | Cleanning And Painting Pump&Pipes | | | | | | |
| | 11 | Check Therminal In Tank | | | | | | |
| 1 Year | 12 | Cleanning All In The Tank | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY MONTH ..... 2 กรกฎาคม 66

GROUND TANK TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | ✓ | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | | | | ✓ | | |
| | 3 | Fitting All Inside Panel Control | | | | | ✓ | |
| | 4 | Testing Floatless Operation | ✓ | | | | | |
| 3 Month | 5 | Check Coupling & Alignment | | | | | | |
| Mar,Jun,Sep,Dec | 6 | Check Piping & Valve | | | | | | |
| | 7 | Check Shake Valve | | | | | | |
| 6 Month | 8 | Check & Cleanning Foot Valve | | | | | | |
| | 9 | Cleanning And Painting Pump&Pipes | | | | | | |
| Jun,Dec | 10 | Check Therminal In Tank | | | | | | |
| 1 Year | 11 | Cleanning All In The Tank | | | | | | |

R = REPAIR P = REPLACED

NOTE .....

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY ... [redacted] RECHECK BY [redacted] ....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY MONTH ก.พ. 66

GROUND TANK TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | | ✓ | | | | |
| | 3 | Fitting All Inside Panel Control | | | ✓ | | ✓ | |
| | 4 | Testing Floatless Operation | | | | | ✓ | |
| 3 Month | 5 | Check Coupling & Alignment | | | | | | |
| Mar,Jun,Sep,Dec | 6 | Check Piping & Valve | | | | | | |
| | 7 | Check Shake Valve | | | | | | |
| 6 Month | 8 | Check & Cleanning Foot Valve | | | | | | |
| | 9 | Cleanning And Painting Pump&Pipes | | | | | | |
| Jun,Dec | 10 | Check Therminal In Tank | | | | | | |
| 1 Year | 11 | Cleanning All In The Tank | | | | | | |

R = REPAIR P = REPLACED

NOTE .....5.....

ตรวจเช็คตามระยะ

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY [redacted] RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY MONTH ..... มีนาคม 66

GROUND TANK TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | ✓ | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | | | ✓ | | | |
| | 3 | Fitting All Inside Panel Control | | | | | ✓ | |
| | 4 | Testing Floatless Operation | | | ✓ | | | |
| 3 Month | 5 | Check Coupling & Alignment | | | | ✓ | | |
| Mar,Jun,Sep,Dec | 6 | Check Piping & Valve | | | | | ✓ | |
| | 7 | Check Shake Valve | | | | | ✓ | |
| 6 Month | 8 | Check & Cleanning Foot Valve | | | | | | |
| | 9 | Cleanning And Painting Pump&Pipes | | | | | | |
| Jun,Dec | 10 | Check Therminal In Tank | | | | | | |
| 1 Year | 11 | Cleanning All In The Tank | | | | | | |

R = REPAIR P = REPLACED

NOTE .....

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY MONTH ..... 6 มิถุนายน 66

GROUND TANK TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | 3 | Fitting All Inside Panel Control | | | | ✓ | | |
| | 4 | Testing Floatless Operation | | ✓ | | | | |
| 3 Month | 5 | Check Coupling & Alignment | | | ✓ | | | |
| Mar,Jun,Sep,Dec | 6 | Check Piping & Valve | | | | | | |
| | 7 | Check Shake Valve | | | | | | |
| 6 Month | 8 | Check & Cleanning Foot Valve | | | | | | |
| | 9 | Cleanning And Painting Pump&Pipes | | | | | | |
| Jun,Dec | 10 | Check Therminal In Tank | | | | | | |
| 1 Year | 11 | Cleanning All In The Tank | | | | | | |

R = REPAIR P = REPLACED

NOTE .....

ตรวจเช็คความสะอาดและอุปกรณ์ต่างๆ ✓

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY MONTH ..... พ.ย. 66

GROUND TANK TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | 3 | Fitting All Inside Panel Control | | | ✓ | | | |
| | 4 | Testing Floatless Operation | | | ✓ | | | |
| 3 Month Mar,Jun,Sep,Dec | 5 | Check Coupling & Alignment | | | | | | |
| | 6 | Check Piping & Valve | | | | | | |
| | 7 | Check Shake Valve | | | | | | |
| 6 Month Jun,Dec | 8 | Check & Cleanning Foot Valve | | | | | | |
| | 9 | Cleanning And Painting Pump&Pipes | | | | | | |
| | 10 | Check Therminal In Tank | | | | | | |
| 1 Year | 11 | Cleanning All In The Tank | | | | | | |

R = REPAIR P = REPLACED

NOTE .....

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY .... [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY MONTH มีนาคม 66

GROUND TANK TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | 2 | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | 3 | Fitting All Inside Panel Control | | | | | ✓ | |
| | 4 | Testing Floatless Operation | | | | | ✓ | |
| 3 Month | 5 | Check Coupling & Alignment | | ✓ | | | | |
| Mar,Jun,Sep,Dec | 6 | Check Piping & Valve | | | ✓ | | | |
| | 7 | Check Shake Valve | | | | | ✓ | |
| 6 Month | 8 | Check & Cleanning Foot Valve | | | | | ✓ | |
| | 9 | Cleanning And Painting Pump&Pipes | | | ✓ | | | |
| Jun,Dec | 10 | Check Therminal In Tank | ✓ | | | | ✓ | |
| 1 Year | 11 | Cleanning All In The Tank | | | | | | |

R = REPAIR P = REPLACED

NOTE .....

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY MONTH ..... มกราคม 67

SHAFT SANITERY SYSTEM TIME .....

| Foor | RISER COLD WATER UP | RISER COLD WATER DOWN | RISER FIRE WATER | PRV | FL DAIN |
|---|---|---|---|---|---|
| 31 | N | N | N | N | N |
| 30 | N | N | N | N | N |
| 29 | N | N | N | N | N |
| 28 | N | N | N | N | N |
| 27 | N | N | N | N | N |
| 26 | N | N | N | N | N |
| 25 | N | N | N | N | N |
| 23 | N | N | N | N | N |
| 22 | N | N | N | N | N |
| 21 | N | N | N | N | N |
| 20 | N | N | N | N | N |
| 19 | N | N | N | N | N |
| 18 | N | N | N | N | N |
| 17 | N | N | N | N | N |
| 16 | N | N | N | N | N |
| 15 | N | N | N | N | N |
| 12 | N | N | N | N | N |
| 11 | N | N | N | N | N |
| 10 | N | N | N | N | N |
| 9 | N | N | N | N | N |
| 8 | N | N | N | N | N |
| 7 | N | N | N | N | N |
| 6 | N | N | N | N | N |
| 5 | N | N | N | N | N |
| 3 | N | N | N | N | N |
| F | N | N | N | N | N |
| M | N | N | N | N | N |
| L | N | N | N | N | N |
| P1 | N | N | N | N | N |
| P2 | N | N | N | N | N |
| P3 | N | N | N | N | N |
| P4 | N | N | N | N | N |

N = NORMAL UN = UNORMAL C = CLENNING A = ADJUST&ADDED

RECORD BY... [redacted] CHECK BY... [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY MONTH .....กุมภาพันธ์ 66.....

SHAFT SANITERY SYSTEM TIME .....

| Foor | RISER COLD WATER UP | RISER COLD WATER DOWN | RISER FIRE WATER | PRV | FL DAIN |
|---|---|---|---|---|---|
| 31 | N | N | N | N | N |
| 30 | N | N | N | N | N |
| 29 | N | N | N | N | N |
| 28 | N | N | N | N | N |
| 27 | N | N | N | N | N |
| 26 | N | N | N | N | N |
| 25 | N | N | N | N | N |
| 23 | N | N | N | N | N |
| 22 | N | N | N | N | N |
| 21 | N | N | N | N | N |
| 20 | N | N | N | N | N |
| 19 | N | N | N | N | N |
| 18 | N | N | N | N | N |
| 17 | N | N | N | N | N |
| 16 | N | N | N | N | N |
| 15 | N | N | N | N | N |
| 12 | N | N | N | N | N |
| 11 | N | N | N | N | N |
| 10 | N | N | N | N | N |
| 9 | N | N | N | N | N |
| 8 | N | N | N | N | N |
| 7 | N | N | N | N | N |
| 6 | N | N | N | N | N |
| 5 | N | N | N | N | N |
| 3 | N | N | N | N | N |
| F | N | N | N | N | N |
| M | N | N | N | N | N |
| L | N | N | N | N | N |
| P1 | N | N | N | N | N |
| P2 | N | N | N | N | N |
| P3 | N | N | N | N | N |
| P4 | N | N | N | N | N |

N = NORMAL UN = UNORMAL C = CLENNING A = ADJUST&ADDED

RECORD BY [redacted] RECHECK BY..... [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY MONTH ..... มีนาคม 66

SHAFT SANITERY SYSTEM TIME .....

| Foor | RISER COLD WATER UP | RISER COLD WATER DOWN | RISER FIRE WATER | PRV | FL DAIN |
|---|---|---|---|---|---|
| 31 | N | N | N | N | N |
| 30 | N | N | N | N | N |
| 29 | N | N | N | N | N |
| 28 | N | N | N | N | N |
| 27 | N | N | N | N | N |
| 26 | N | N | N | N | N |
| 25 | N | N | N | N | N |
| 23 | N | N | N | N | N |
| 22 | N | N | N | N | N |
| 21 | N | N | N | N | N |
| 20 | N | N | N | N | N |
| 19 | N | N | N | N | N |
| 18 | N | N | N | N | N |
| 17 | N | N | N | N | N |
| 16 | N | N | N | N | N |
| 15 | N | N | N | N | N |
| 12 | N | N | N | N | N |
| 11 | N | N | N | N | N |
| 10 | N | N | N | N | N |
| 9 | N | N | N | N | N |
| 8 | N | N | N | N | N |
| 7 | N | N | N | N | N |
| 6 | N | N | N | N | N |
| 5 | N | N | N | N | N |
| 3 | N | N | N | N | N |
| F | N | N | N | N | N |
| M | N | N | N | N | N |
| L | N | N | N | N | N |
| P1 | N | N | N | N | N |
| P2 | N | N | N | N | N |
| P3 | N | N | N | N | N |
| P4 | N | N | N | N | N |

N = NORMAL UN = UNORMAL C = CLENNING A = ADJUST& ADDED

RECORD BY.[redacted] RECHECK BY.[redacted].....

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY MONTH .....มีนาคม 66

SHAFT SANITERY SYSTEM TIME .....

| Foor | RISER COLD WATER UP | RISER COLD WATER DOWN | RISER FIRE WATER | PRV | FL DAIN |
|---|---|---|---|---|---|
| 31 | N | N | N | N | N |
| 30 | N | N | N | N | N |
| 29 | N | N | N | N | N |
| 28 | N | N | N | N | N |
| 27 | N | N | N | N | N |
| 26 | N | N | N | N | N |
| 25 | N | N | N | N | N |
| 23 | N | N | N | N | N |
| 22 | N | N | N | N | N |
| 21 | N | N | N | N | N |
| 20 | N | N | N | N | N |
| 19 | N | N | N | N | N |
| 18 | N | N | N | N | N |
| 17 | N | N | N | N | N |
| 16 | N | N | N | N | N |
| 15 | N | N | N | N | N |
| 12 | N | N | N | N | N |
| 11 | N | N | N | N | N |
| 10 | N | N | N | N | N |
| 9 | N | N | N | N | N |
| 8 | N | N | N | N | N |
| 7 | N | N | N | N | N |
| 6 | N | N | N | N | N |
| 5 | N | N | N | N | N |
| 3 | N | N | N | N | N |
| F | N | N | N | N | N |
| M | N | N | N | N | N |
| L | N | N | N | N | N |
| P1 | N | N | N | N | N |
| P2 | N | N | N | N | N |
| P3 | N | N | N | N | N |
| P4 | N | N | N | N | N |

N = NORMAL UN = UNORMAL C = CLENNING A = ADJUST&ADDED

RECORD BY.. [redacted] RECHECK BY. [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY MONTH ..... พฤษภาคม 66

SHAFT SANITERY SYSTEM TIME .....

| Foor | RISER COLD WATER UP | RISER COLD WATER DOWN | RISER FIRE WATER | PRV | FL DAIN |
|---|---|---|---|---|---|
| 31 | N | N | N | N | N |
| 30 | N | N | N | N | N |
| 29 | N | N | N | N | N |
| 28 | N | N | N | N | N |
| 27 | N | N | N | N | N |
| 26 | N | N | N | N | N |
| 25 | N | N | N | N | N |
| 23 | N | N | N | N | N |
| 22 | N | N | N | N | N |
| 21 | N | N | N | N | N |
| 20 | N | N | N | N | N |
| 19 | N | N | N | N | N |
| 18 | N | N | N | N | N |
| 17 | N | N | N | N | N |
| 16 | N | N | N | N | N |
| 15 | N | N | N | N | N |
| 12 | N | N | N | N | N |
| 11 | N | N | N | N | N |
| 10 | N | N | N | N | N |
| 9 | N | N | N | N | N |
| 8 | N | N | N | N | N |
| 7 | N | N | N | N | N |
| 6 | N | N | N | N | N |
| 5 | N | N | N | N | N |
| 3 | N | N | N | N | N |
| F | N | N | N | N | N |
| M | N | N | N | N | N |
| L | N | N | N | N | N |
| P1 | N | N | N | N | N |
| P2 | N | N | N | N | N |
| P3 | N | N | N | N | N |
| P4 | N | N | N | N | N |

N = NORMAL UN = UNORMAL C = CLENNING A = ADJUST&ADDED

RECORD BY. [redacted] RECHECK BY... [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY MONTH ..... มีนาคม 66

SHAFT SANITERY SYSTEM TIME .....

| Foor | RISER COLD WATER UP | RISER COLD WATER DOWN | RISER FIRE WATER | PRV | FL DAIN |
|---|---|---|---|---|---|
| 31 | N | N | N | N | N |
| 30 | N | N | N | N | N |
| 29 | N | N | N | N | N |
| 28 | N | N | N | N | N |
| 27 | N | N | N | N | N |
| 26 | N | N | N | N | N |
| 25 | N | N | N | N | N |
| 23 | N | N | N | N | N |
| 22 | N | N | N | N | N |
| 21 | N | N | N | N | N |
| 20 | N | N | N | N | N |
| 19 | N | N | N | N | N |
| 18 | N | N | N | N | N |
| 17 | N | N | N | N | N |
| 16 | N | N | N | N | N |
| 15 | N | N | N | N | N |
| 12 | N | N | N | N | N |
| 11 | N | N | N | N | N |
| 10 | N | N | N | N | N |
| 9 | N | N | N | N | N |
| 8 | N | N | N | N | N |
| 7 | N | N | N | N | N |
| 6 | N | N | N | N | N |
| 5 | N | N | N | N | N |
| 3 | N | N | N | N | N |
| F | N | N | N | N | N |
| M | N | N | N | N | N |
| L | N | N | N | N | N |
| P1 | N | N | N | N | N |
| P2 | N | N | N | N | N |
| P3 | N | N | N | N | N |
| P4 | N | N | N | N | N |

N = NORMAL UN = UNORMAL C = CLENNING A = ADJUST&ADDED

RECORD BY. [redacted] RECHECK BY. [redacted] .....

# ภาคผนวก ข-5

ใบเสร็จรับเงินค่าธรรมเนียมการจัดเก็บมูลฝอย



# หลักฐานการรับเงิน

ข้าพเจ้า (นาย / นาง / นางสาว) [redacted]

ที่อยู่ [redacted]

บัตรประจำตัวประชาชนเลขที่ [redacted] บัตรประจำตัวผู้เสียภาษีเลขที่ _____

ได้รับเงินค่า บริการเก็บขยะ เดือน มกราคม 2566

เป็นจำนวนเงิน [redacted] บาท ( [redacted] )

หัก อัตราภาษี 3 % เป็นจำนวนเงิน [redacted] บาท ( [redacted] )

จำนวนเงิน สุทธิทั้งสิ้น [redacted] บาท ( [redacted] )

◯ หักภาษีจากผู้มีเงินได้

◯ บริษัท รับภาระภาษี

◯ เงินสด

◯ เช็คธนาคาร _____ สาขา _____

เลขที _____ ลงวันที _____

จาก "บริษัท แอล แอนด์ เอช พร็อพเพอร์ตี้ จำกัด" เรียบร้อยแล้ว

ลงชื่อ [redacted]

( _____ )

หมายเหตุ : แนบสำเนาบัตรประจำตัวประชาชน

[redacted]

# หลักฐานการรับเงิน

ข้าพเจ้า (นาย / นาง / นางสาว) [redacted]

ที่อยู่ [redacted]

บัตรประจำตัวประชาชนเลขที่ [redacted] บัตรประจำตัวผู้เสียภาษีเลขที่ _____

ได้รับเงินค่า บริการเก็บขยะ เดือน กุมภาพันธ์ 2566

เป็นจำนวนเงิน [redacted] บาท ( [redacted] )

หัก อัตราภาษี 3 % เป็นจำนวนเงิน [redacted] บาท ( [redacted] )

จำนวนเงิน สุทธิทั้งสิ้น [redacted] บาท ( [redacted] )

◯ หักภาษีจากผู้มีเงินได้

◯ บริษัท รับภาระภาษี

◯ เงินสด

◯ เช็คธนาคาร _____ สาขา _____

เลขที่ _____ ลงวันที่ _____

จาก "บริษัท แอล แอนด์ เอช พร็อพเพอร์ตี้ จำกัด" เรียบร้อยแล้ว

ลงชื่อ [redacted]

( _____ )

หมายเหตุ : แนบสำเนาบัตรประจำตัวประชาชน

[redacted]

# หลักฐานการรับเงิน

ข้าพเจ้า (นาย / นาง / นางสาว) [redacted]

ที่อยู่ [redacted]

บัตรประจำตัวประชาชนเลขที่ [redacted] บัตรประจำตัวผู้เสียภาษีเลขที่ _____

ได้รับเงินค่า บริการเก็บขยะ เดือน มีนาคม 2566

เป็นจำนวนเงิน [redacted] บาท ( [redacted] )

หัก อัตราภาษี 3 % เป็นจำนวนเงิน [redacted] บาท ( [redacted] )

จำนวนเงิน สุทธิทั้งสิ้น [redacted] บาท ( [redacted] )

◯ หักภาษีจากผู้มีเงินได้ [redacted]

◯ บริษัท รับภาระภาษี

◯ เงินสด

◯ เช็คธนาคาร _____ สาขา _____

เลขที _____ ลงวันที _____

จาก "บริษัท แอล แอนด์ เอช พร็อพเพอร์ตี้ จำกัด" เรียบร้อยแล้ว

ลงชื่อ [redacted]

( _____ )

หมายเหตุ : แนบสำเนาบัตรประจำตัวประชาชน

# หลักฐานการรับเงิน

ข้าพเจ้า (นาย / นาง / นางสาว) [redacted]

ที่อยู่ [redacted]

บัตรประจำตัวประชาชนเลขที่ [redacted] บัตรประจำตัวผู้เสียภาษีเลขที่ _____

ได้รับเงินค่า บริการเก็บขยะ เดือน กุมภาพันธ์ 2566

เป็นจำนวนเงิน [redacted] บาท ( [redacted] )

หัก อัตราภาษี 3 % เป็นจำนวนเงิน [redacted] บาท ( [redacted] )

จำนวนเงิน สุทธิทั้งสิ้น [redacted] บาท ( [redacted] )

◯ หักภาษีจากผู้มีเงินได้

◯ บริษัท รับภาระภาษี

◯ เงินสด

◯ เช็คธนาคาร _____ สาขา _____

เลขที่ _____ ลงวันที่ _____

จาก "บริษัท แอล แอนด์ เอช พร็อพเพอร์ตี้ จำกัด" เรียบร้อยแล้ว

ลงชื่อ [redacted]

หมายเหตุ : แนบสำเนาบัตรประจำตัวประชาชน

[redacted]

# หลักฐานการรับเงิน

ข้าพเจ้า (นาย / นาง / นางสาว) [redacted]

ที่อยู่ [redacted]

บัตรประจำตัวประชาชนเลขที่ [redacted] บัตรประจำตัวผู้เสียภาษีเลขที่ _____

ได้รับเงินค่า บริการเก็บขยะ เดือน พฤษภาคม 2566

เป็นจำนวนเงิน [redacted] บาท ( [redacted] )

หัก อัตราภาษี 3 % เป็นจำนวนเงิน [redacted] บาท ( [redacted] )

จำนวนเงิน สุทธิทั้งสิ้น [redacted] บาท ( [redacted] )

○ หักภาษีจากผู้มีเงินได้

○ บริษัท รับภาระภาษี

○ เงินสด

○ เช็คธนาคาร _____ สาขา _____

เลขที _____ ลงวันที _____

จาก "บริษัท แอล แอนด์ เอช พร็อพเพอร์ตี้ จำกัด" เรียบร้อยแล้ว

ลงชื่อ [redacted]

( _____ )

หมายเหตุ : แนบสำเนาบัตรประจำตัวประชาชน

[redacted]

# ภาคผนวก ข-6

เอกสารการตรวจสอบอุปกรณ์ป้องกันและเตือนอัคคีภัย



Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

MONTH มกราคม 66.

EMERGENCY LIGHT SYSTEM

TIME .....

| Foor | SF 1 | | | | | SF 2 | | | | | SF 3 | | | | | SF 4 | | | | | โถงทางเดิน | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Charge | LAMP | | LAMP | | LAMP | | LAMP | | LAMP | |
| | | | | R | L | | | | R | L | | | | R | L | | | | R | L | | R | L | R | L | R | L | R | L | R | L | R | L |
| Roof | 2 | | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 31 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 30 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 29 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| 28 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 27 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 26 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 25 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | | 2 | 2 | 2 | | | | | | | |
| 23 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| 22 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 21 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 20 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 19 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 18 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| 17 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 16 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 15 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 12 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 11 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| 10 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 9 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 8 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 7 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 6 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| 5 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 3 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| F | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| F | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| F | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| M | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| L | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P1 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P3 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P4 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| Substation room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Generator room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Booster pump room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Water pump room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| CCTV room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Engineer room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Office Room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Life พนักงาน | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Life ลูกค้า | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| ร้าน อาหาร | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |

RECORD BY: [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

EMERGENCY LIGHT SYSTEM

MONTH ....กุมภาพันธ์ 66....

TIME .....

| Foor | SF 1 | | | | | SF 2 | | | | | SF 3 | | | | | SF 4 | | | | | โถงทางเดิน | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Charge | LAMP | | LAMP | | LAMP | | LAMP | | |
| | | | | R | L | | | | R | L | | | | R | L | | | | R | L | | R | L | R | L | R | L | R | L | R | L |
| Roof | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 31 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 30 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 29 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | |
| 28 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 27 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 26 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 25 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 23 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | |
| 22 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 21 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 20 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 19 | 2 | 2 | 2 | 2 | | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 18 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | |
| 17 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 16 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 15 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 12 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 11 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | |
| 10 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 9 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 8 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 7 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 6 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | |
| 5 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| 3 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| F | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| F | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | |
| F | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | |
| M | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | |
| L | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P1 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P3 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P4 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| Substation room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | |
| Generator room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | |
| Booster pump room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | |
| Water pump room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | |
| CCTV room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | |
| Engineer room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | |
| Office Room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | |
| Life พนักงาน | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | |
| Life ลูกค้า | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | |
| ร้าน อาหาร | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | |

RECORD BY [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

MONTH ธันวาคม 66.

EMERGENCY LIGHT SYSTEM

TIME .....

| Foor | SF 1 | | | | | SF 2 | | | | | SF 3 | | | | | SF 4 | | | | | โถงทางเดิน | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Charge | LAMP | | LAMP | | LAMP | | LAMP | | LAMP | |
| | | | | R | L | | | | R | L | | | | R | L | | | | R | L | | R | L | R | L | R | L | R | L | R | L | R | L |
| Roof | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 31 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 30 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 29 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| 28 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 27 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 26 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 25 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 23 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| 22 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 21 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 20 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 19 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 18 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| 17 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 16 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 15 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 12 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 11 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| 10 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 9 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 8 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 7 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 6 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| 5 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| 3 | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| F | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| F | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | | | | | | | |
| F | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| M | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | |
| L | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P1 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P3 | 2 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P4 | 2 | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | | | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| Substation room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Generator room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Booster pump room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Water pump room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| CCTV room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Engineer room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Office Room | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Life พนักงาน | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| Life ลูกค้า | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |
| ร้าน อาหาร | | | | | | 2 | 2 | 2 | 2 | 2 | | | | | | | | | | | | | | | | | | | | | | |

RECORD [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

MONTH ..... 1สิงหาคม 66.

EMERGENCY LIGHT SYSTEM

TIME .....

| Foor | SF 1 | | | | | SF 2 | | | | | SF 3 | | | | | SF 4 | | | | | โถงทางเดิน | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Charge | LAMP | | LAMP | | LAMP | | LAMP | | LAMP | | LAMP | |
| | | | | R | L | | | | R | L | | | | R | L | | | | R | L | | R | L | R | L | R | L | R | L | R | L | R | L |
| Roof | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| 31 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 30 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 29 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 28 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 27 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 26 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 25 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 23 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 22 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 21 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 20 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 19 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 18 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 17 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 16 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 15 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 12 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 11 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 10 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 9 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 8 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 7 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 6 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 5 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 3 | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| F | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| F | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| F | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| M | N | N | N | N | | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| L | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P1 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P2 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P3 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P4 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| Substation room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Generator room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Booster pump room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Water pump room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| CCTV room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Engineer room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Office Room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Life พนักงาน | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Life ลูกค้า | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| ร้าน อาหาร | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |

RECORD BY: [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

EMERGENCY LIGHT SYSTEM

MONTH ..... พฤศจิกายน 2566

TIME .....

| Foor | SF 1 | | | | | SF 2 | | | | | SF 3 | | | | | SF 4 | | | | | โถงทางเดิน | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Charge | LAMP | | LAMP | | LAMP | | LAMP | | LAMP | | LAMP | |
| | | | | R | L | | | | R | L | | | | R | L | | | | R | L | | R | L | R | L | R | L | R | L | R | L | R | L | R | L |
| Roof | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 31 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 30 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 29 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | | | | | | | | | | |
| 28 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 27 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 26 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 25 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 23 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 22 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 21 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 20 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 19 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 18 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 17 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 16 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 15 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 12 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 11 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 10 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 9 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 8 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 7 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 6 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 5 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 3 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| F | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| F | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| F | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| M | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| L | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P1 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P2 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P3 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P4 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N | N |
| Substation room | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Generator room | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Booster pump room | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Water pump room | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | | | |
| CCTV room | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Engineer room | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Office Room | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Life พนักงาน | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Life ลูกค้า | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | | | |
| ร้าน อาหาร | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | | | |

RECORD B[redacted]

RECHECK B[redacted]

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

มิถุนายน 2566

SYSTEM & SAFETY

MONTH .....

EMERGENCY LIGHT SYSTEM

TIME .....

| Foor | SF 1 | | | | | SF 2 | | | | | SF 3 | | | | | SF 4 | | | | | โถงทางเดิน | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Ready | Charge | S.W | LAMP | | Charge | LAMP | | LAMP | | LAMP | | LAMP | | LAMP | | LAMP | |
| | | | | R | L | | | | R | L | | | | R | L | | | | R | L | | R | L | R | L | R | L | R | L | R | L | R | L | R | L |
| Roof | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| 31 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 30 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 29 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 28 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 27 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 26 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 25 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 23 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 22 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 21 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 20 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 19 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 18 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 17 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 16 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 15 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 12 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 11 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 10 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 9 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 8 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 7 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 6 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| 5 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| 3 | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| F | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| F | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| F | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | N | N | N | N | N | | | | | | | | | |
| M | N | N | N | N | N | | | | | | | | | | | N | N | N | N | N | | N | N | N | N | | | | | | | | | |
| L | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P1 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P2 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P3 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| P4 | N | N | N | N | N | N | N | N | N | N | N | N | N | N | N | | | | | | | N | N | N | N | N | N | N | N | N | N | N | N | N |
| Substation room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Generator room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Booster pump room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Water pump room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| CCTV room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Engineer room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Office Room | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Life พนักงาน | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| Life ลูกค้า | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |
| ร้าน อาหาร | | | | | | N | N | N | N | N | | | | | | | | | | | | | | | | | | | | | | | | |

RECORD BY: [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY — MONTH ..... มีนาคม 66

FIRE POTECTION SYSTEM — TIME .....

| Foor | FHC (Corridor) | | | | FHC (Service Lift Area) | | | | Fire Pipe | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Fire Test | Flow switch | Supervisory valve |
| Roof | | | | | | | | | | | |
| 31 | | | | | | | | | | | |
| 30 | | | | | | | | | | | |
| 29 | | | | | | | | | | | |
| 28 | | | | | | | | | | | |
| 27 | | | | | | | | | | | |
| 26 | | | | | | | | | | | |
| 25 | | | | | | | | | | | |
| 23 | | | | | | | | | | | |
| 22 | | | | | | | | | | | |
| 21 | | | | | | | | | | | |
| 20 | | | | | | | | | | | |
| 19 | | | | | | | | | | | |
| 18 | | | | | | | | | | | |
| 17 | | | | | | | | | | | |
| 16 | | | | | | | | | | | |
| 15 | | | | | | | | | | | |
| 12 | | | | | | | | | | | |
| 11 | | | | | | | | | | | |
| 10 | | | | | | | | | | | |
| 9 | | | | | | | | | | | |
| 8 | | | | | | | | | | | |
| 7 | | | | | | | | | | | |
| 6 | | | | | | | | | | | |
| 5 | | | | | | | | | | | |
| 3 | | | | | | | | | | | |
| F | | | | | | | | | | | |
| M | | | | | | | | | | | |
| L | | | | | | | | | | | |
| P1 | | | | | | | | | | | |
| P2 | | | | | | | | | | | |
| P3 | | | | | | | | | | | |
| P4 | | | | | | | | | | | |
| Lift room | | | | | | | | | | | |
| Booster pump room | | | | | | | | | | | |
| Transformer room | | | | | | | | | | | |
| Swimming pool room | | | | | | | | | | | |
| Water pump room | | | | | | | | | | | |
| Generator room | | | | | | | | | | | |

RECORD BY: [redacted]

RECHECK BY: [redacted]

# Grande Center Point Hotel Ploenchit Bangkok

## MONTHLY REPORT

SYSTEM & SAFETY — MONTH .....

FIRE POTECTION SYSTEM — TIME .....

| Foor | FHC (Corridor) | | | | FHC (Service Lift Area) | | | | Fire Pipe | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Fire Test | Flow switch | Supervisory valve |
| Roof | | | | | | | | | | | |
| 31 | | | | | | | | | | | |
| 30 | | | | | | | | | | | |
| 29 | | | | | | | | | | | |
| 28 | | | | | | | | | | | |
| 27 | | | | | | | | | | | |
| 26 | | | | | | | | | | | |
| 25 | | | | | | | | | | | |
| 23 | | | | | | | | | | | |
| 22 | | | | | | | | | | | |
| 21 | | | | | | | | | | | |
| 20 | | | | | | | | | | | |
| 19 | | | | | | | | | | | |
| 18 | | | | | | | | | | | |
| 17 | | | | | | | | | | | |
| 16 | | | | | | | | | | | |
| 15 | | | | | | | | | | | |
| 12 | | | | | | | | | | | |
| 11 | | | | | | | | | | | |
| 10 | | | | | | | | | | | |
| 9 | | | | | | | | | | | |
| 8 | | | | | | | | | | | |
| 7 | | | | | | | | | | | |
| 6 | | | | | | | | | | | |
| 5 | | | | | | | | | | | |
| 3 | | | | | | | | | | | |
| F | | | | | | | | | | | |
| M | | | | | | | | | | | |
| L | | | | | | | | | | | |
| P1 | | | | | | | | | | | |
| P2 | | | | | | | | | | | |
| P3 | | | | | | | | | | | |
| P4 | | | | | | | | | | | |
| Lift room | | | | | | | | | | | |
| Booster pump room | | | | | | | | | | | |
| Transformer room | | | | | | | | | | | |
| Swimming pool room | | | | | | | | | | | |
| Water pump room | | | | | | | | | | | |
| Generator room | | | | | | | | | | | |

RECORD B[redacted] .....

RECHECK BY:.....[redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY — MONTH สิงหาคม 66

FIRE POTECTION SYSTEM — TIME .....

| Foor | FHC (Corridor) | | | | FHC (Service Lift Area) | | | | Fire Pipe | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Fire Test | Flow switch | Supervisory valve |
| Roof | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 31 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 30 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 29 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 28 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 27 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 26 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 25 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 23 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 22 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 21 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 20 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 19 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 18 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 17 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 16 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 15 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 12 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 11 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 10 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 9 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 8 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 7 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 6 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 5 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| 3 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| F | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| M | | | | | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| L | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P1 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P3 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| P4 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 |
| Lift room | | | | | | | 2 | 2 | | | |
| Booster pump room | | | | | | | 2 | 2 | | | |
| Transformer room | | | | | | | 2 | 2 | | | |
| Swimming pool room | | | | | | | 2 | 2 | | | |
| Water pump room | | | | | | | 2 | 2 | | | |
| Generator room | | | | | | | 2 | 2 | | | |

RECORD BY:[redacted]

RECHECK BY:[redacted]

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

FIRE POTECTION SYSTEM

MONTH ..... มกราคม 2566

TIME .....

| Foor | FHC (Corridor) | | | | FHC (Service Lift Area) | | | | Fire Pipe | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Fire Test | Flow switch | Supervisory valve |
| Roof | | | | | N | N | N | N | N | N | N |
| 31 | N | N | N | N | N | N | N | N | N | N | N |
| 30 | N | N | N | N | N | N | N | N | N | N | N |
| 29 | N | N | N | N | N | N | N | N | N | N | N |
| 28 | N | N | N | N | N | N | N | N | N | N | N |
| 27 | N | N | N | N | N | N | N | N | N | N | N |
| 26 | N | N | N | N | N | N | N | N | N | N | N |
| 25 | N | N | N | N | N | N | N | N | N | N | N |
| 23 | N | N | N | N | N | N | N | N | N | N | N |
| 22 | N | N | N | N | N | N | N | N | N | N | N |
| 21 | N | N | N | N | N | N | N | N | N | N | N |
| 20 | N | N | N | N | N | N | N | N | N | N | N |
| 19 | N | N | N | N | N | N | N | N | N | N | N |
| 18 | N | N | N | N | N | N | N | N | N | N | N |
| 17 | N | N | N | N | N | N | N | N | N | N | N |
| 16 | N | N | N | N | N | N | N | N | N | N | N |
| 15 | N | N | N | N | N | N | N | N | N | N | N |
| 12 | N | N | N | N | N | N | N | N | N | N | N |
| 11 | N | N | N | N | N | N | N | N | N | N | N |
| 10 | N | N | N | N | N | N | N | N | N | N | N |
| 9 | N | N | N | N | N | N | N | N | N | N | N |
| 8 | N | N | N | N | N | N | N | N | N | N | N |
| 7 | N | N | N | N | N | N | N | N | N | N | N |
| 6 | N | N | N | N | N | N | N | N | N | N | N |
| 5 | N | N | N | N | N | N | N | N | N | N | N |
| 3 | N | N | N | N | N | N | N | N | N | N | N |
| F | N | N | N | N | N | N | N | N | N | N | N |
| M | | | N | N | N | N | N | N | N | N | N |
| L | N | N | N | N | N | N | N | N | N | N | N |
| P1 | N | N | N | N | N | N | N | N | N | N | N |
| P2 | N | N | N | N | N | N | N | N | N | N | N |
| P3 | N | N | N | N | N | N | N | N | N | N | N |
| P4 | N | N | N | N | N | N | N | N | N | N | N |
| Lift room | | | | | | | N | N | | | |
| Booster pump room | | | | | | | N | N | | | |
| Transformer room | | | | | | | N | N | | | |
| Swimming pool room | | | | | | | N | N | | | |
| Water pump room | | | | | | | N | N | | | |
| Generator room | | | | | | | N | N | | | |

RECORD BY:.. [redacted]

RECHECK BY:..... [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

FIRE POTECTION SYSTEM

MONTH ..... พฤศจิกายน 2566

TIME .....

| Foor | FHC (Corridor) | | | | FHC (Service Lift Area) | | | | Fire Pipe | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Fire Test | Flow switch | Supervisory valve |
| Roof | | | | | N | N | N | N | N | N | N |
| 31 | N | N | N | N | N | N | N | N | N | N | N |
| 30 | N | N | N | N | N | N | N | N | N | N | N |
| 29 | N | N | N | N | N | N | N | N | N | N | N |
| 28 | N | N | N | N | N | N | N | N | N | N | N |
| 27 | N | N | N | N | N | N | N | N | N | N | N |
| 26 | N | N | N | N | N | N | N | N | N | N | N |
| 25 | N | N | N | N | N | N | N | N | N | N | N |
| 23 | N | N | N | N | N | N | N | N | N | N | N |
| 22 | N | N | N | N | N | N | N | N | N | N | N |
| 21 | N | N | N | N | N | N | N | N | N | N | N |
| 20 | N | N | N | N | N | N | N | N | N | N | N |
| 19 | N | N | N | N | N | N | N | N | N | N | N |
| 18 | N | N | N | N | N | N | N | N | N | N | N |
| 17 | N | N | N | N | N | N | N | N | N | N | N |
| 16 | N | N | N | N | N | N | N | N | N | N | N |
| 15 | N | N | N | N | N | N | N | N | N | N | N |
| 12 | N | N | N | N | N | N | N | N | N | N | N |
| 11 | N | N | N | N | N | N | N | N | N | N | N |
| 10 | N | N | N | N | N | N | N | N | N | N | N |
| 9 | N | N | N | N | N | N | N | N | N | N | N |
| 8 | N | N | N | N | N | N | N | N | N | N | N |
| 7 | N | N | N | N | N | N | N | N | N | N | N |
| 6 | N | N | N | N | N | N | N | N | N | N | N |
| 5 | N | N | N | N | N | N | N | N | N | N | N |
| 3 | N | N | N | N | N | N | N | N | N | N | N |
| F | N | N | N | N | N | N | N | N | N | N | N |
| M | | | N | N | N | N | N | N | N | N | N |
| L | N | N | N | N | N | N | N | N | N | N | N |
| P1 | N | N | N | N | N | N | N | N | N | N | N |
| P2 | N | N | N | N | N | N | N | N | N | N | N |
| P3 | N | N | N | N | N | N | N | N | N | N | N |
| P4 | N | N | N | N | N | N | N | N | N | N | N |
| Lift room | | | | | | | N | N | | | |
| Booster pump room | | | | | | | N | N | | | |
| Transformer room | | | | | | | N | N | | | |
| Swimming pool room | | | | | | | N | N | | | |
| Water pump room | | | | | | | N | N | | | |
| Generator room | | | | | | | N | N | | | |

RECORD BY:... [redacted]

RECHECK BY:... [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY — MONTH มิถุนายน 2566

FIRE POTECTION SYSTEM — TIME

| Foor | FHC (Corridor) | | | | FHC (Service Lift Area) | | | | Fire Pipe | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Hose Real | Hose Valve | Fire Extinguisher Weight(Kg) | Fire Extinguisher Gauge | Fire Test | Flow switch | Supervisory valve |
| Roof | | | | | | | | | | | |
| 31 | | | | | | | | | | | |
| 30 | | | | | | | | | | | |
| 29 | | | | | | | | | | | |
| 28 | | | | | | | | | | | |
| 27 | | | | | | | | | | | |
| 26 | | | | | | | | | | | |
| 25 | | | | | | | | | | | |
| 23 | | | | | | | | | | | |
| 22 | | | | | | | | | | | |
| 21 | | | | | | | | | | | |
| 20 | | | | | | | | | | | |
| 19 | | | | | | | | | | | |
| 18 | | | | | | | | | | | |
| 17 | | | | | | | | | | | |
| 16 | | | | | | | | | | | |
| 15 | | | | | | | | | | | |
| 12 | | | | | | | | | | | |
| 11 | | | | | | | | | | | |
| 10 | | | | | | | | | | | |
| 9 | | | | | | | | | | | |
| 8 | | | | | | | | | | | |
| 7 | | | | | | | | | | | |
| 6 | | | | | | | | | | | |
| 5 | | | | | | | | | | | |
| 3 | | | | | | | | | | | |
| F | | | | | | | | | | | |
| M | | | | | | | | | | | |
| L | | | | | | | | | | | |
| P1 | | | | | | | | | | | |
| P2 | | | | | | | | | | | |
| P3 | | | | | | | | | | | |
| P4 | | | | | | | | | | | |
| Lift room | | | | | | | | | | | |
| Booster pump room | | | | | | | | | | | |
| Transformer room | | | | | | | | | | | |
| Swimming pool room | | | | | | | | | | | |
| Water pump room | | | | | | | | | | | |
| Generator room | | | | | | | | | | | |

RECORD BY: [redacted]

RECHECK BY: [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH มกราคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| | 1 | Cleanning Pump Frame & Oil Clean | | | | | ✓ | |
| | 2 | Control System | | | | | ✓ | |
| | | Test Control System | | | ✓ | | ✓ | |
| | | Fitting All Inside Panel | | | | | ✓ | |
| | | Testing Operation Time Delay | ✓ | | | | ✓ | |
| 1 Month | 3 | Check Oil Level | | | ✓ | | | |
| | 4 | Check Water Level In Coolant | | | | | ✓ | |
| | 5 | Check Condensate Water Of Battery | | | | | ✓ | |
| | 6 | Check Fuel Pipes | | | | | ✓ | |
| | 7 | Check Leakage Every Jointes | | | | | | |
| | 8 | Check Exhaust Pipe | | | | | | |
| 3 Month | 9 | Check Engine Oil | | | | | | |
| | 10 | Check Air Filter | | | | | | |
| Mar,Jun,Sep,Dec | 11 | Check Water Color In Coolant | | | | | | |
| | 12 | Adjusting Alignment | | | | | | |
| | 13 | Check/Changed Beltes | | | | | | |
| | 14 | Changed Water In Coolant | | | | | | |
| 6 Month | 15 | Changed Engine Oil | | | | | | |
| | 16 | Changed Air Filter | | | | | | |
| | 17 | Changed Oil Filter | | | | | | |
| | 18 | Changed Fuel Filter | | | | | | |
| Jun,Dec | 19 | Painting Overall | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....
RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH ..... กุมภาพันธ์ 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| | 1 | Cleanning Pump Frame & Oil Clean | / | | | | / | |
| | 2 | Control System | | | / | | / | |
| | | Test Control System | | | | | / | |
| | | Fitting All Inside Panel | | / | | | / | |
| | | Testing Operation Time Delay | | | | | / | |
| 1 Month | 3 | Check Oil Level | | | | | / | |
| | 4 | Check Water Level In Coolant | | | / | | | |
| | 5 | Check Condensate Water Of Battery | | | | | / | |
| | 6 | Check Fuel Pipes | | | | | / | |
| | 7 | Check Leakage Every Jointes | | | | | | |
| | 8 | Check Exhaust Pipe | | | | | | |
| 3 Month | 9 | Check Engine Oil | | | | | | |
| | 10 | Check Air Filter | | | | | | |
| Mar,Jun,Sep,Dec | 11 | Check Water Color In Coolant | | | | | | |
| | 12 | Adjusting Alignment | | | | | | |
| | 13 | Check/Changed Beltes | | | | | | |
| | 14 | Changed Water In Coolant | | | | | | |
| 6 Month | 15 | Changed Engine Oil | | | | | | |
| | 16 | Changed Air Filter | | | | | | |
| | 17 | Changed Oil Filter | | | | | | |
| | 18 | Changed Fuel Filter | | | | | | |
| Jun,Dec | 19 | Painting Overall | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....
RECORD BY .[redacted]..... RECHECK BY .[redacted].....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH ..... ๔ มกราคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| | 1 | Cleanning Pump Frame & Oil Clean | / | | | | / | |
| | 2 | Control System | | | | | / | |
| | | Test Control System | | | | | / | |
| | | Fitting All Inside Panel | | | | | / | |
| | | Testing Operation Time Delay | | / | | | / | |
| 1 Month | 3 | Check Oil Level | | | | | / | |
| | 4 | Check Water Level In Coolant | | | | | / | |
| | 5 | Check Condensate Water Of Battery | | | | | / | |
| | 6 | Check Fuel Pipes | | | | | / | |
| | 7 | Check Leakage Every Jointes | | / | / | | | |
| | 8 | Check Exhaust Pipe | | | | | / | |
| 3 Month | 9 | Check Engine Oil | | | | | / | |
| | 10 | Check Air Filter | | | | | / | |
| Mar,Jun,Sep,Dec | 11 | Check Water Color In Coolant | | | | | / | |
| | 12 | Adjusting Alignment | | | | | | |
| | 13 | Check/Changed Beltes | | | | | | |
| | 14 | Changed Water In Coolant | | | | | | |
| 6 Month | 15 | Changed Engine Oil | | | | | | |
| | 16 | Changed Air Filter | | | | | | |
| | 17 | Changed Oil Filter | | | | | | |
| | 18 | Changed Fuel Filter | | | | | | |
| Jun,Dec | 19 | Painting Overall | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH ..... 12 ก.ย. 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| | 1 | Cleanning Pump Frame & Oil Clean | / | | | | / | |
| | 2 | Control System | | | | | / | |
| | | Test Control System | | / | | | / | |
| | | Fitting All Inside Panel | | | | | / | |
| | | Testing Operation Time Delay | | | / | | / | |
| 1 Month | 3 | Check Oil Level | | | | | / | |
| | 4 | Check Water Level In Coolant | | | | | / | |
| | 5 | Check Condensate Water Of Battery | | | / | | / | |
| | 6 | Check Fuel Pipes | | | | | / | |
| | 7 | Check Leakage Every Jointes | | | | | | |
| | 8 | Check Exhaust Pipe | | | | | | |
| 3 Month | 9 | Check Engine Oil | | | | | | |
| | 10 | Check Air Filter | | | | | | |
| Mar,Jun,Sep,Dec | 11 | Check Water Color In Coolant | | | | | | |
| | 12 | Adjusting Alignment | | | | | | |
| | 13 | Check/Changed Beltes | | | | | | |
| | 14 | Changed Water In Coolant | | | | | | |
| 6 Month | 15 | Changed Engine Oil | | | | | | |
| | 16 | Changed Air Filter | | | | | | |
| | 17 | Changed Oil Filter | | | | | | |
| | 18 | Changed Fuel Filter | | | | | | |
| Jun,Dec | 19 | Painting Overall | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....
RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH พฤษภาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Cleanning Pump Frame & Oil Clean | | | | | ✓ | |
| | 2 | Control System | | | | | ✓ | |
| | | Test Control System | | | | | ✓ | |
| | | Fitting All Inside Panel | | | ✓ | | ✓ | |
| | | Testing Operation Time Delay | | | | | ✓ | |
| | 3 | Check Oil Level | | | | | ✓ | |
| | 4 | Check Water Level In Coolant | | | | | ✓ | |
| | 5 | Check Condensate Water Of Battery | | | | | ✓ | |
| | 6 | Check Fuel Pipes | | | ✓ | | | |
| 3 Month<br>Mar,Jun,Sep,Dec | 7 | Check Leakage Every Jointes | | | | | | |
| | 8 | Check Exhaust Pipe | | | | | | |
| | 9 | Check Engine Oil | | | | | | |
| | 10 | Check Air Filter | | | | | | |
| | 11 | Check Water Color In Coolant | | | | | | |
| 6 Month<br>Jun,Dec | 12 | Adjusting Alignment | | | | | | |
| | 13 | Check/Changed Beltes | | | | | | |
| | 14 | Changed Water In Coolant | | | | | | |
| | 15 | Changed Engine Oil | | | | | | |
| | 16 | Changed Air Filter | | | | | | |
| | 17 | Changed Oil Filter | | | | | | |
| | 18 | Changed Fuel Filter | | | | | | |
| | 19 | Painting Overall | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] ... RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH มีนาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| | 1 | Cleanning Pump Frame & Oil Clean | | | | | ✓ | |
| | 2 | Control System | | | | | ✓ | |
| | | Test Control System | | | | | ✓ | |
| | | Fitting All Inside Panel | | | ✓ | | | |
| | | Testing Operation Time Delay | | ✓ | | | ✓ | |
| 1 Month | 3 | Check Oil Level | | | | | ✓ | |
| | 4 | Check Water Level In Coolant | | | | | ✓ | |
| | 5 | Check Condensate Water Of Battery | | | | | ✓ | |
| | 6 | Check Fuel Pipes | | | | | ✓ | |
| | 7 | Check Leakage Every Jointes | | | ✓ | | | |
| | 8 | Check Exhaust Pipe | | | | | ✓ | |
| 3 Month | 9 | Check Engine Oil | | | | | ✓ | |
| | 10 | Check Air Filter | | | | | ✓ | |
| Mar,Jun,Sep,Dec | 11 | Check Water Color In Coolant | | | ✓ | | | |
| | 12 | Adjusting Alignment | | | | | ✓ | |
| | 13 | Check/Changed Beltes | | | | | ✓ | |
| | 14 | Changed Water In Coolant | | | | | ✓ | |
| 6 Month | 15 | Changed Engine Oil | | | ✓ | | | |
| | 16 | Changed Air Filter | | ✓ | | | | |
| | 17 | Changed Oil Filter | | | | | ✓ | |
| | 18 | Changed Fuel Filter | | | | | ✓ | |
| Jun,Dec | 19 | Painting Overall | | | | | ✓ | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....
RECORD BY [redacted] RECHECK BY [redacted]

# ภาคผนวก ข-7

เอกสารการตรวจสอบระบบระบายอากาศ

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH มกราคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | | Fitting All Inside Panel Control | | | ✓ | | ✓ | |
| | | Testing Overload | | | ✓ | | ✓ | |
| | 2 | Check Timer Operation | | | | | ✓ | |
| | 3 | Check Motor& Blower | | ✓ | | | | |
| | 4 | Check Bearing | | | | | ✓ | |
| | 5 | Check&Cleaned Frame | | | | | ✓ | |
| | 6 | Check & Fitting Support | | ✓ | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning Air Grill Return | | | | | | |
| | 8 | Cleanning Relief Damper | | | | | | |
| | 9 | Cleanning Supply Damperes | | | | | | |
| | 10 | Added Grease The Damper Motordrive | | | | | | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....

COMMENT .....
.....
.....
.....

RECORD BY [redacted] .

RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH ..... กุมภาพันธ์ 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | ✓ | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | | Fitting All Inside Panel Control | | | ✓ | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Check Timer Operation | | | ✓ | | ✓ | |
| | 3 | Check Motor& Blower | | | ✓ | | | |
| | 4 | Check Bearing | | | | | ✓ | |
| | 5 | Check&Cleaned Frame | | | | | ✓ | |
| | 6 | Check & Fitting Support | | | ✓ | | | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning Air Grill Return | | | | | | |
| | 8 | Cleanning Relief Damper | | | | | | |
| | 9 | Cleanning Supply Damperes | | | | | | |
| | 10 | Added Grease The Damper Motordrive | | | | | | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....

COMMENT .....
.....
.....
.....

RECORD BY [redacted] .....

RECHECK B [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH มีนาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| | 1 | Testing Control System | | | | | / | |
| | | Cleanning Overall Inside Panel Control | | | | | / | |
| | | Fitting All Inside Panel Control | | | | | / | |
| | | Testing Overload | | | | | / | |
| | 2 | Check Timer Operation | | | / | | / | |
| 1 Month | 3 | Check Motor& Blower | | | / | | | |
| | 4 | Check Bearing | | | | | / | |
| | 5 | Check&Cleaned Frame | | | | | | |
| | 6 | Check & Fitting Support | | | / | | | |
| | 7 | Cleanning Air Grill Return | | / | | | | |
| | 8 | Cleanning Relief Damper | | | | | / | |
| 3 Month | 9 | Cleanning Supply Damperes | | | | | / | |
| Mar,Jun,Sep,Dec | 10 | Added Grease The Damper Motordrive | | / | | | | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | | | / | |
| | 10 | Cleanning Motor & Blower | | | | | | |
| 6 Month | 11 | Cleanning Inside Hood Duct | | | | | | |
| Jun,Dec | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH ..... มีนาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | / | |
| | | Cleanning Overall Inside Panel Control | | | / | | | |
| | | Fitting All Inside Panel Control | | | | | / | |
| | | Testing Overload | | | | / | / | |
| | 2 | Check Timer Operation | | / | | | / | |
| | 3 | Check Motor& Blower | | | | | / | |
| | 4 | Check Bearing | | | / | | | |
| | 5 | Check&Cleaned Frame | | | | | / | |
| | 6 | Check & Fitting Support | | | | | / | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning Air Grill Return | | | | | | |
| | 8 | Cleanning Relief Damper | | | | | | |
| | 9 | Cleanning Supply Damperes | | | | | | |
| | 10 | Added Grease The Damper Motordrive | | | | | | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH ..พฤศจิกายน 66..
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| | 1 | Testing Control System | | / | | | / | |
| | | Cleanning Overall Inside Panel Control | | | / | | / | |
| | | Fitting All Inside Panel Control | | | | | / | |
| | | Testing Overload | | | | | / | |
| | 2 | Check Timer Operation | | | / | | | |
| 1 Month | 3 | Check Motor& Blower | | | | | / | |
| | 4 | Check Bearing | | | | | / | |
| | 5 | Check&Cleaned Frame | | | / | | | |
| | 6 | Check & Fitting Support | | | | | / | |
| | 7 | Cleanning Air Grill Return | | | | | | |
| | 8 | Cleanning Relief Damper | | | | | | |
| 3 Month | 9 | Cleanning Supply Damperes | | | | | | |
| Mar,Jun,Sep,Dec | 10 | Added Grease The Damper Motordrive | | | | | | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| | 10 | Cleanning Motor & Blower | | | | | | |
| 6 Month | 11 | Cleanning Inside Hood Duct | | | | | | |
| Jun,Dec | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY .. [redacted] ..

RECHECK BY .. [redacted] ...

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH ..... ธันวาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | / | |
| | | Cleanning Overall Inside Panel Control | | | / | | / | |
| | | Fitting All Inside Panel Control | | | | | / | |
| | | Testing Overload | | | / | | / | |
| | 2 | Check Timer Operation | | | | | / | |
| | 3 | Check Motor& Blower | | | | | / | |
| | 4 | Check Bearing | | | | | / | |
| | 5 | Check&Cleaned Frame | | | | | / | |
| | 6 | Check & Fitting Support | | | / | | / | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning Air Grill Return | | / | | | | |
| | 8 | Cleanning Relief Damper | | | | | / | |
| | 9 | Cleanning Supply Damperes | | | | | / | |
| | 10 | Added Grease The Damper Motordrive | | | | | / | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | / | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
PRESSURIZE FAN ..... NO. 1-5

MONTH ..... มกราคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | | Fitting All Inside Panel Control | | | ✓ | | | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Check Timer Operation | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Bearing | | | ✓ | | | |
| | 5 | Check&Cleaned Frame | | ✓ | | | | |
| | 6 | Check & Fitting Support | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning Air Grill Return | | | | | | |
| | 8 | Cleanning Relief Damper | | | | | | |
| | 9 | Cleanning Supply Damperes | | | | | | |
| | 10 | Added Grease The Damper Motordrive | | | | | | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....

COMMENT .....
.....
.....
.....

RECORD BY .. [redacted] RECHECK BY .. [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
PRESSURIZE FAN ..NO. 1-5

MONTH .....กุมภาพันธ์ 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | | Fitting All Inside Panel Control | | | ✓ | | | |
| | | Testing Overload | | | ✓ | | ✓ | |
| | 2 | Check Timer Operation | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Bearing | | | | | ✓ | |
| | 5 | Check&Cleaned Frame | | ✓ | ✓ | | | |
| | 6 | Check & Fitting Support | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning Air Grill Return | | | | | | |
| | 8 | Cleanning Relief Damper | | | | | | |
| | 9 | Cleanning Supply Damperes | | | | | | |
| | 10 | Added Grease The Damper Motordrive | | | | | | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....

COMMENT .....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
PRESSURIZE FAN ..... NO. 1-5

MONTH ..... มีนาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Check Timer Operation | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | ✓ | | | |
| | 4 | Check Bearing | | | ✓ | | | |
| | 5 | Check&Cleaned Frame | | | | | ✓ | |
| | 6 | Check & Fitting Support | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning Air Grill Return | | | ✓ | | ✓ | |
| | 8 | Cleanning Relief Damper | | ✓ | | | | |
| | 9 | Cleanning Supply Damperes | | | | | ✓ | |
| | 10 | Added Grease The Damper Motordrive | | ✓ | | | | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | ✓ | | ✓ | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....

COMMENT .....
.....
.....
.....

RECORD BY [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
PRESSURIZE FAN .....NO. 1-5

MONTH ..... 02/2/24 bb
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Check Timer Operation | | | ✓ | | | |
| | 3 | Check Motor& Blower | | ✓ | | | | |
| | 4 | Check Bearing | | ✓ | | | | |
| | 5 | Check&Cleaned Frame | | | ✓ | | ✓ | |
| | 6 | Check & Fitting Support | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning Air Grill Return | | | | | | |
| | 8 | Cleanning Relief Damper | | | | | | |
| | 9 | Cleanning Supply Damperes | | | | | | |
| | 10 | Added Grease The Damper Motordrive | | | | | | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY .... [redacted] RECHECK BY . [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
PRESSURIZE FAN ..NO. 1-5

MONTH ..มีนาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | ✓ | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | | Fitting All Inside Panel Control | | | ✓ | | | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Check Timer Operation | | | ✓ | | ✓ | |
| | 3 | Check Motor& Blower | | | ✓ | | | |
| | 4 | Check Bearing | | | | | ✓ | |
| | 5 | Check&Cleaned Frame | | | | | ✓ | |
| | 6 | Check & Fitting Support | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Cleanning Air Grill Return | | | | | | |
| | 8 | Cleanning Relief Damper | | | | | | |
| | 9 | Cleanning Supply Damperes | | | | | | |
| | 10 | Added Grease The Damper Motordrive | | | | | | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....

.....

.....

.....

COMMENT .....

.....

.....

.....

RECORD BY .. [redacted]

RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
PRESSURIZE FAN ...NO 1 - 5

MONTH ...มิถุนายน...
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | | | | ✓ | |
| | | Fitting All Inside Panel Control | | | ✓ | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Check Timer Operation | | | | | ✓ | |
| 1 Month | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Bearing | | | | | ✓ | |
| | 5 | Check&Cleaned Frame | | | ✓ | | | |
| | 6 | Check & Fitting Support | | | ✓ | | ✓ | |
| | 7 | Cleanning Air Grill Return | | | ✓ | | | |
| | 8 | Cleanning Relief Damper | | | | | ✓ | |
| 3 Month | 9 | Cleanning Supply Damperes | | | | | ✓ | |
| Mar,Jun,Sep,Dec | 10 | Added Grease The Damper Motordrive | | | ✓ | | | |
| | 11 | Tighting All Bolt/Nut Motor & Blower | | | ✓ | | ✓ | |
| | 10 | Cleanning Motor & Blower | | | ✓ | | | |
| 6 Month | 11 | Cleanning Inside Hood Duct | | | | | ✓ | |
| Jun,Dec | 12 | Cleanning & Painting | | | ✓ | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....

COMMENT .....
.....
.....
.....

RECORD BY [redacted] .....

RECHECK BY ... [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
MAKE UP MOTOR FAN NO. 1, 2

MONTH มกราคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| | 8 | Check & Fitting Support | | | | | | |
| | 9 | Cleanning Air Grill Return & Supply | | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....

COMMENT .....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
MAKE UP MOTOR FAN NO. 1-2

MONTH ..... มกราคม ธ.ค. 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| | 8 | Check & Fitting Support | | | | | | |
| | 9 | Cleanning Air Grill Return & Supply | | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] ...

RECHECK B[redacted] ...

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
MAKE UP MOTOR FAN NO. 1-2

MONTH สิงหาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | ✓ | |
| | 8 | Check & Fitting Support | | | | | ✓ | |
| | 9 | Cleanning Air Grill Return & Supply | ✓ | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....

COMMENT .....

RECORD BY [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
MAKE UP MOTOR FAN NO. 1 - 2

MONTH 12 มิถุนายน 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| | 8 | Check & Fitting Support | | | | | | |
| | 9 | Cleanning Air Grill Return & Supply | | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....

COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK B [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
MAKE UP MOTOR FAN NO. 1-2

MONTH พฤษภาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| | 8 | Check & Fitting Support | | | | | | |
| | 9 | Cleanning Air Grill Return & Supply | | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....

COMMENT .....

RECORD BY [redacted] .....

RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
MAKE UP MOTOR FAN NO. 1-2

MONTH สิงหาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | ✓ | |
| | 8 | Check & Fitting Support | | | | | ✓ | |
| | 9 | Cleanning Air Grill Return & Supply | ✓ | | | | | |
| 6 Month Jun,Dec | 10 | Cleanning Motor & Blower | ✓ | | | | | |
| | 11 | Cleanning Inside Hood Duct | ✓ | | | | | |
| | 12 | Cleanning & Painting | ✓ | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EXHAUST MOTOR FAN NO. 1-8

MONTH มกราคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| | 8 | Check & Fitting Support | | | | | | |
| | 9 | Cleanning Air Grill Return & Supply | | | | | | |
| 6 Month | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EXHAUST MOTOR FAN NO. 1-8

MONTH กุมภาพันธ์ 66.
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| | 8 | Check & Fitting Support | | | | | | |
| | 9 | Cleanning Air Grill Return & Supply | | | | | | |
| 6 Month | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....

COMMENT .....

RECORD BY [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EXHAUST MOTOR FAN NO. 1-8

MONTH มีนาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | | ✓ | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | ✓ | |
| | 8 | Check & Fitting Support | | | | | ✓ | |
| | 9 | Cleanning Air Grill Return & Supply | | ✓ | | | | |
| 6 Month | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....

COMMENT .....

RECORD BY [redacted]

RECHECK BY [redacted]

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EXHAUST MOTOR FAN NO. 1-8

MONTH 12/มีนาคม 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| | 8 | Check & Fitting Support | | | | | | |
| | 9 | Cleanning Air Grill Return & Supply | | | | | | |
| 6 Month | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] .....

RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EXHAUST MOTOR FAN NO. 1-8

MONTH กันยายน 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month Mar,Jun,Sep,Dec | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | | |
| | 8 | Check & Fitting Support | | | | | | |
| | 9 | Cleanning Air Grill Return & Supply | | | | | | |
| 6 Month | 10 | Cleanning Motor & Blower | | | | | | |
| | 11 | Cleanning Inside Hood Duct | | | | | | |
| | 12 | Cleanning & Painting | | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....
.....
.....
.....
COMMENT .....
.....
.....
.....

RECORD BY [redacted] .....

RECHECK BY [redacted] .....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
EXHAUST MOTOR FAN NO. 1-8

MONTH กันยายน 66
TIME .....

| TIME | ITEM | DESCRIPTION MAINTENANCE | WORKING REMARKS | | | WORKING RESULT | | |
|---|---|---|---|---|---|---|---|---|
| | | | C | A | R | P | N | UN |
| 1 Month | 1 | Testing Control System | | | | | ✓ | |
| | | Cleanning Overall Inside Panel Control | ✓ | | | | | |
| | | Fitting All Inside Panel Control | | | | | ✓ | |
| | | Testing Overload | | | | | ✓ | |
| | 2 | Added Grease | | | | | ✓ | |
| | 3 | Check Motor& Blower | | | | | ✓ | |
| | 4 | Check Belt | | | | | ✓ | |
| | 5 | Check Bearing | | | | | ✓ | |
| | 6 | Check&Cleaned Frame | | | | | ✓ | |
| 3 Month | 7 | Tighting All Bolt/Nut Motor & Blower | | | | | ✓ | |
| | 8 | Check & Fitting Support | | | | | ✓ | |
| Mar,Jun,Sep,Dec | 9 | Cleanning Air Grill Return & Supply | ✓ | | | | | |
| 6 Month | 10 | Cleanning Motor & Blower | ✓ | | | | | |
| | 11 | Cleanning Inside Hood Duct | ✓ | | | | | |
| | 12 | Cleanning & Painting | ✓ | | | | | |

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE .....

COMMENT .....

RECORD BY [redacted]

RECHECK BY [redacted]