

HOMA Si Racha

ENGINEERING DEPARTMENT

Log Sheet: Check the gutter system (ตรวจเช็คระบบรางน้ำ)

Month: January

Date	บ่อพักน้ำ	รางระบายน้ำ	บ่อดักขยะ											Remark หมายเหตุ	ENG Supervisor ผู้ตรวจสอบ
1	/	/	/												
2	/	/	/												
3	/	/	/												
4	/	/	/												
5	/	/	/												
6	/	/	/												
7	/	/	/												
8	/	/	/												
9	/	/	/												
10	/	/	/												
11	/	/	/												
12	/	/	/												
13	/	/	/												
14	/	/	/												
15	/	/	/												
16	/	/	/												
17	/	/	/												
18	/	/	/												
19	/	/	/												
20	/	/	/												
21	/	/	/												
22	/	/	/												
23	/	/	/												
24	/	/	/												
25	/	/	/												
26	/	/	/												
27	/	/	/												
28	/	/	/												
29	/	/	/												
30	/	/	/												
31	/	/	/												

Remark: / คือปกติ, X คือไม่ปกติ

HOMA Si Racha

ENGINEERING DEPARTMENT

Log Sheet: Check the gutter system (ตรวจเช็คระบบรางน้ำ)

Month: February 2023

Date	บ่อพักน้ำ	รางระบายน้ำ	บ่อตกขยะ											Remark หมายเหตุ	ENG Supervisor ผู้ตรวจสอบ
1	/	/	/												
2	/	/	/												
3	/	/	/												
4	/	/	/												
5	/	/	/												
6	/	/	/												
7	/	/	/												
8	/	/	/												
9	/	/	/												
10	/	/	/												
11	/	/	/												
12	/	/	/												
13	/	/	/												
14	/	/	/												
15	/	/	/												
16	/	/	/												
17	/	/	/												
18	/	/	/												
19	/	/	/												
20	/	/	/												
21	/	/	/												
22	/	/	/												
23	/	/	/												
24	/	/	/												
25	/	/	/												
26	/	/	/												
27	/	/	/												
28	/	/	/												

Remark: / คือปกติ, X คือไม่ปกติ

HOMA Si Racha

ENGINEERING DEPARTMENT

Log Sheet: Check the gutter system (ตรวจเช็คระบบรางน้ำ)

Month: March 2023

Date	บ่อพักน้ำ	รางระบายน้ำ	บ่อตกขยะ											Remark หมายเหตุ	ENG Supervisor ผู้ตรวจสอบ
1	/	/	/												
2	/	/	/												
3	/	/	/												
4	/	/	/												
5	/	/	/												
6	/	/	/												
7	/	/	/												
8	/	/	/												
9	/	/	/												
10	/	/	/												
11	/	/	/												
12	/	/	/												
13	/	/	/												
14	/	X	/										มีเศษใบไม้เล็กๆ ให้ช่างจึงทำความสะอาด		
15	/	/	/												
16	/	/	/												
17	/	/	/												
18	/	/	/												
19	/	/	/												
20	/	/	/												
21	/	/	/												
22	/	/	/												
23	/	/	/												
24	/	/	/												
25	/	/	/												
26	/	/	/												
27	/	X	/										มีเศษใบไม้เล็กๆ ให้ช่างจึงทำความสะอาด		
28	/	/	/												
29	/	/	/												
30	/	/	/												
31	/	/	/												

Remark: / คือปกติ, X คือไม่ปกติ

HOMA Si Racha

ENGINEERING DEPARTMENT

Log Sheet: Check the gutter system (ตรวจเช็คระบบรางน้ำ)

Month: April 2023

Date	บ่อพักน้ำ	รางระบายน้ำ	บ่อตกขยะ											Remark หมายเหตุ	ENG Supervisor ผู้ตรวจสอบ
1	/	/	/												
2	/	/	/												
3	/	/	/												
4	/	/	/												
5	/	/	/												
6	/	/	/												
7	/	/	/												
8	/	/	/												
9	/	/	/												
10	/	/	/												
11	/	/	/												
12	/	/	/												
13	/	/	/												
14	/	/	/												
15	/	/	/												
16	/	/	/												
17	/	/	/												
18	/	/	/												
19	/	/	/												
20	/	/	/												
21	/	/	/												
22	/	/	/												
23	/	/	/												
24	/	/	/												
25	/	/	/												
26	/	/	/												
27	/	/	/												
28	/	/	/												
29	/	/	/												
30	/	/	/												

Remark: / คือปกติ, X คือไม่ปกติ

HOMA Si Racha

ENGINEERING DEPARTMENT

Log Sheet: Check the gutter system (ตรวจเช็คระบบรางน้ำ)

Month: May 2023

Date	บ่อพักน้ำ	รางระบายน้ำ	บ่อตกขยะ											Remark หมายเหตุ	ENG Supervisor ผู้ตรวจสอบ
1	/	/	/												
2	/	X	X											มีเศษขยะและไม้ จึงทำความสะอาด	
3	/	/	/												
4	/	/	/												
5	/	/	/												
6	/	/	/												
7	/	/	/												
8	/	/	/												
9	/	/	/												
10	/	/	/												
11	/	/	/												
12	/	/	/												
13	/	/	/												
14	/	/	/												
15	/	/	/												
16	/	/	/												
17	/	/	/												
18	/	/	/												
19	/	/	/												
20	/	/	/												
21	/	/	/												
22	/	/	/												
23	/	X	/											มีเศษขยะและไม้ จึงทำความสะอาด	
24	/	/	/												
25	/	/	/												
26	/	/	/												
27	/	/	/												
28	/	/	/												
29	/	/	/												
30	/	/	/												
31	/	/	/												

Remark: / คือปกติ, X คือไม่ปกติ

HOMA Si Racha

ENGINEERING DEPARTMENT

Log Sheet: Check the gutter system (ตรวจเช็คระบบรางน้ำ)

Month: June 2023

Date	บ่อพักน้ำ	รางระบายน้ำ	ปลั๊กขยะ											Remark หมายเหตุ	ENG Supervisor ผู้ตรวจสอบ
1	/	/	/												
2	/	/	/												
3	/	/	/												
4	/	/	/												
5	/	/	/												
6	/	/	/												
7	/	/	/												
8	/	/	/												
9	/	/	/												
10	/	/	/												
11	/	/	/												
12	/	/	/												
13	/	/	/												
14	/	/	/												
15	/	/	/												
16	/	/	/												
17	/	/	/												
18	/	/	/												
19	/	/	/												
20	/	/	/												
21	/	/	/												
22	/	/	/												
23	/	/	/												
24	/	/	/												
25	/	/	/												
26	/	/	/												
27	/	/	/												
28	/	/	/												
29	/	/	/												
30	/	X	/											มีเศษใบไม้เล็ก จึงทำความสะอาด	

Remark: / คือปกติ, X คือไม่ปกติ