

เดือนมกราคม 2566

Engineering Department

Fix air conditioning in guest room

Room no. 8031: Change air conditioning's fan motor



Engineering Department

Install additional set of CCTV camera and signal cable
at parking B2 Level



เดือนกุมภาพันธ์ 2566

Engineering Department

Fix air conditioning in guest room

Room no. 5002: Change air conditioning's compressor air

Room no. 8031 & 4031: Change air conditioning's fan motor



Engineering Department

Maintenance & clean air condition's fan coil unit
in guest room, total 26 rooms



Engineering Department

Change waste water treatment tank's float set to control water level



เดือนมีนาคม 2566

Engineering Department

Fix air conditioning in guest room

Room no. 8035: Change air conditioning's compressor air

Room no. 6003 & 8009: Change air conditioning's fan motor



Engineering Department

Maintenance & clean air condition's fan coil unit
in guest room, total 31 rooms



Engineering Department

Repair hot water pipe leak (PPR pipe) and change pipe
at roof top by contractor

Before



After



Engineering Department



เดือนเมษายน 2566

Engineering Department

Clean air condition's fan coil unit
in guest room, total 24 rooms



Engineering Department

Fix air conditioning in guest room

Room no. 6008: Change air conditioning's compressor air

Room no. 6002, 6005 & 8022: Change air conditioning's fan motor

Room no.5001 & 6005: Fix air conditioning due to not cool



Engineering Department

Replace new sump pump of waste water treatment tank



Engineering Department

Repair and replace 2 pipes for sump pump
in waste water treatment tank

Before



Engineering Department

Repair & clean Pressure reducing valve (PRV) of guest room 3023 & 3025
due to low water pressure



เดือนพฤษภาคม 2566

Engineering Department

Fix air conditioning in guest room

Room no. 6006: Change air conditioning's compressor air



Engineering Department

Fix air conditioning in guest room

Room no.8005,6027,6023,5009 & 5025: Fix air conditioning due to not cool



Engineering Department

Replace new Check valve of Hot water system at roof top



Engineering Department

Waste Removal & Clean Grease trap tank and Septic tank at B2 by Wanadol Company



Engineering Department


Waste Removal & Clean Effluent tank at B2 by Wanadol Company



เดือนมิถุนายน 2566

Engineering Department

ขกAerotor pump No.1 (ใช้ผลิตอากาศระบบบำบัดน้ำเสีย) ซึ่งทำการตรวจเช็คและทำความสะอาด



Engineering Department

ขกAerotor pump No.2 (ปั๊มเติมอากาศระบบน้ำบาดิน้ำเสีย) ซึ่งทำการตรวจเช็คและทำความสะอาด

Before




After



Engineering Department

ขกAerotor pump No.3 (ปั๊มเติมอากาศระบบน้ำบาดิน้ำเสีย) ซึ่งทำการตรวจเช็คและทำความสะอาด

Before



After



Engineering Department

Maintenance & clean air conditioning VRV System

Condensing unit 5 sets



Engineering Department

Fix Heat pump (Hot water system)

