

เอกสารแนบที่ 7

บันทึกการตรวจสอบระบบป้องกันและแจ้งเตือนอัคคีภัย

STAY

Emergency Lighting Testing

Monthly 2023


No.	Building	Location	INDICATOR LAMP						Testing		Power Supply Test		Remark
			AC		CHARGE / FULL		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
1	Building A	In front of the fire room, 1st floor	/		/		/		/		/		{ Unit
2	Building B	In front of the fire room, 1st floor	/		/		/		/		/		
3	Building C	Panty room 1st floor		/		/		/		/		/	
4		In front of the fire room, 2nd floor	/		/		/		/		/		{ Unit
5		Staircase 1st floor	/		/		/		/		/		
6		Staircase 2nd floor	/		/		/		/		/		
7		Panty room 3rd floor	/		/		/		/		/		{ Unit
8	Building D	Panty room 1st floor											
9		Staircase 1st floor	/		/		/		/		/		
10		In front of the fire room, 2nd floor	/		/		/		/		/		{ Unit
11		Staircase 2nd floor	/		/		/		/		/		
12		Panty room 3rd floor		/		/		/		/		/	
13	Building E	Panty room 1st floor											{ Unit
14		Staircase 1st floor	/		/		/		/		/		
15		In front of the fire room, 2nd floor		/		/		/		/		/	
16		Staircase 2nd floor	/		/		/		/		/		{ Unit
17		Panty room 3rd floor		/		/		/		/		/	
18	Building F	Panty room 1st floor		/		/		/		/		/	
19		Staircase 1st floor	/		/		/		/		/		{ Unit
20		Staircase 2nd floor	/		/		/		/		/		
21		In front of the fire room, 2nd floor		/		/		/		/		/	
22		Panty room 3rd floor	/		/		/		/		/		{ Unit
23	Building G	In front of the fire room, 1st floor	/		/		/		/		/		
24	Building H	In front of the fire room, 1st floor	/		/		/		/		/		
25		YOGA fire room	/		/		/		/		/		{ Unit
26		In front of the Wine	/		/		/		/		/		
27		In front of Kids club	/		/		/		/		/		
28		Security room	/		/		/		/		/		{ Unit
29		Office FB room	/		/		/		/		/		
30		In front of Store FB room	/		/		/		/		/		
31		In front of Store HR room	/		/		/		/		/		{ Unit
32		Canteen room 1	/		/		/		/		/		
33		Canteen room 2	/		/		/		/		/		

STAY

Emergency Lighting Testing

Monthly 2023

No.	Building	Location	INDICATOR LAMP						Testing		Power Supply Test		Remark
			AC		CHARGE / FULL		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
34		Front Security room	/		/		/		/		/		✓
35		In front of toilet basement	/		/		/		/		/		✓
36		In front of freezer room No.35	/		/		/		/		/		✓
37		In front of Pump room door#1		/		/		/		/		/	✓
38		Pump room door#2		/		/		/		/		/	✓
39		Butcher room	/		/		/		/		/		✓
40		Staircase MK	/		/		/		/		/		✓
41	Fitness	Fire room, 1st floor	/		/		/		/		/		✓
42		Staircase 1st floor	/		/		/		/		/		✓
43		Fire room, 2nd floor	/		/		/		/		/		✓
44		Staircase 2nd floor	/		/		/		/		/		✓
45		Fire room, 3rd floor	/		/		/		/		/		✓
46	Spa	Fire room, 1st floor	/		/		/		/		/		✓
47		Behind kitchen 1st floor	/		/		/		/		/		✓
48		Fire room, 2nd floor	/		/		/		/		/		✓
49		Head Spa room 2nd floor	/		/		/		/		/		✓
50													

Check By : 

Approve By :



Fire Exit

Monthly January 2023

No.	Building	Location	INDICATOR LAMP				Testing		Power Supply Test		Remark
			AC		FAIL		Yes	No	Yes	No	
			Yes	No	Yes	No					
1	Building A	Front room A101	/		/		/		/		
2		Front room A102	/		/		/		/		
3		Front room A201	/		/		/		/		
4		Front room A202	/		/		/		/		
5	Building B	Front room B101	/		/		/		/		
6		Front room B102	/		/		/		/		
7		Front room B201	/		/		/		/		
8		Front room B202	/		/		/		/		
9	Building C	Front lift 1st floor	/		/		/		/		
10		Front room C101	/		/		/		/		
11		Front room C105	/		/		/		/		
12		Front room C106	/		/		/		/		
13		Front lift 2nd floor	/		/		/		/		
14		Front room C201	/		/		/		/		
15		Front room C206	/		/		/		/		
16		Front lift 3rd floor	/		/		/		/		
17		Front room C302	/		/		/		/		
18		Front room C304	/		/		/		/		
19	Building D	Front lift 1st floor	/		/		/		/		
20		Front room D101	/		/		/		/		
21		Front room D104	/		/		/		/		
22		Front lift 2nd floor	/		/		/		/		
23		Front room D201	/		/		/		/		
24		Front room D205	/		/		/		/		
25		Front lift 3rd floor	/		/		/		/		
26		Front room D301	/		/		/		/		
27		Front room D305	/		/		/		/		
28	Building E	Front lift 1st floor	/		/		/		/		
29		Front room E101	/		/		/		/		
30		Front room E104	/		/		/		/		
31		Front lift 2nd floor	/		/		/		/		
32		Front room E201	/		/		/		/		
33		Front room E206	/		/		/		/		



Fire Exit

Monthly January 2023

34		Front lift 3rd floor	/		/		/		/		
35		Front room E301	/		/		/		/		
36		Front room E305	/		/		/		/		
37	Building F	Front room F105	/		/		/		/		
38		Front shop 1st floor	/		/		/		/		
39		Front shop 2nd floor	/		/		/		/		
40		Front room F205	/		/		/		/		
41		Front lift 3rd floor	/		/		/		/		
42		Front room F303	/		/		/		/		
43	Building G	Front room G101	/		/		/		/		
44		Front room G102	/		/		/		/		
45		Front room G201	/		/		/		/		
46		Front room G202	/		/		/		/		
47	Building H	Front room H101	/		/		/		/		
48		Front room H102	/		/		/		/		
49		Front room H201	/		/		/		/		
50		Front room H202	/		/		/		/		

Check By :

Approve By :

STAY

STAY HOTEL & RESORTS

Emergency Lighting Testing

Monthly กุมภาพันธ์ 2023

No.	Building	Location	INDICATOR LAMP						Testing		Power Supply Test		Remark
			AC		CHARGE / FULL		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
1	Building A	In front of the fire room, 1st floor	✓		✓		✓		✓		✓		ปกติ
2	Building B	In front of the fire room, 1st floor		✓		✓		✓	✓		✓		แบตเตอรี่ใกล้หมด
3	Building C	Panty room 1st floor	✓			✓		✓		✓		✓	ปกติ
4		In front of the fire room, 2nd floor	✓			✓		✓		✓		✓	ปกติ
5		Staircase 1st floor		✓		✓		✓	✓		✓		แบตเตอรี่ใกล้หมด
6		Staircase 2nd floor		✓		✓		✓	✓		✓		แบตเตอรี่ใกล้หมด
7		Panty room 3rd floor		✓		✓		✓	✓		✓		แบตเตอรี่ใกล้หมด
8	Building D	Panty room 1st floor		✓		✓		✓	✓		✓		แบตเตอรี่ใกล้หมด
9		Staircase 1st floor	✓		✓		✓		✓		✓		ปกติ
10		In front of the fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
11		Staircase 2nd floor		✓		✓		✓	✓		✓		แบตเตอรี่ใกล้หมด
12		Panty room 3rd floor	✓		✓		✓		✓		✓		ปกติ
13	Building E	Panty room 1st floor	✓		✓		✓		✓		✓		ปกติ
14		Staircase 1st floor		✓		✓		✓	✓		✓		แบตเตอรี่ใกล้หมด
15		In front of the fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
16		Staircase 2nd floor	✓		✓		✓		✓		✓		ปกติ
17		Panty room 3rd floor		✓		✓		✓	✓		✓		แบตเตอรี่ใกล้หมด
18	Building F	Panty room 1st floor	✓		✓		✓		✓		✓		ปกติ
19		Staircase 1st floor	✓		✓		✓		✓		✓		ปกติ
20		Staircase 2nd floor	✓		✓		✓		✓		✓		ปกติ
21		In front of the fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
22		Panty room 3rd floor	✓		✓		✓		✓		✓		ปกติ
23	Building G	In front of the fire room, 1st floor	✓		✓		✓		✓		✓		ปกติ
24	Building H	In front of the fire room, 1st floor	✓		✓		✓		✓		✓		ปกติ
25		YOGA fire room	✓		✓		✓		✓		✓		ปกติ
26		In front of the Wine		✓		✓		✓	✓		✓		แบตเตอรี่ใกล้หมด
27		In front of Kids club	✓		✓		✓		✓		✓		ปกติ
28		Security room	✓		✓		✓		✓		✓		ปกติ
29		Office FB room	✓		✓		✓		✓		✓		ปกติ
30		In front of Store FB room	✓		✓		✓		✓		✓		ปกติ
31		In front of Store HR room	✓		✓		✓		✓		✓		ปกติ
32		Canteen room 1	✓		✓		✓		✓		✓		ปกติ
33		Canteen room 2	✓		✓		✓		✓		✓		ปกติ

STAY

STAY HOTEL & RESORTS

Emergency Lighting Testing

Monthly กุมภาพันธ์ 2023

No.	Building	Location	INDICATOR LAMP						Testing		Power Supply Test		Remark
			AC		CHARGE / FULL		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
34		Front Security room	✓		✓		✓		✓		✓		ปกติ
35		In front of toilet basement	✓		✓		✓		✓		✓		ปกติ
36		In front of freezer room No.35	✓		✓		✓		✓		✓		ปกติ
37		in front of Pump room door#1		✓		✓		✓	✓			✓	แบตเตอรี่ใกล้หมด
38		Pump room door#2	✓		✓		✓		✓		✓		ปกติ
39		Butcher room	✓		✓		✓		✓		✓		ปกติ
40		Staircase MK	✓		✓		✓		✓		✓		ปกติ
41	Fitness	Fire room, 1st floor		✓		✓		✓	✓			✓	แบตเตอรี่ใกล้หมด
42		Staircase 1st floor		✓		✓		✓	✓			✓	แบตเตอรี่ใกล้หมด
43		Fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
44		Staircase 2nd floor	✓		✓		✓		✓		✓		ปกติ
45		Fire room, 3rd floor		✓		✓		✓	✓			✓	แบตเตอรี่ใกล้หมด
46	Spa	Fire room, 1st floor		✓		✓		✓	✓			✓	แบตเตอรี่ใกล้หมด
47		Behind kitchen 1st floor		✓		✓		✓	✓			✓	แบตเตอรี่ใกล้หมด
48		Fire room, 2nd floor		✓		✓		✓	✓			✓	แบตเตอรี่ใกล้หมด
49		Head Spa room 2nd floor	✓		✓		✓		✓		✓		ปกติ
50													

Check By : [REDACTED]


Approve By : [REDACTED]



Fire Exit

Monthly มิถุนายน 2022

No.	Building	Location	INDICATOR LAMP				Testing		Power Supply Test		Remark
			AC		FAIL		Yes	No	Yes	No	
			Yes	No	Yes	No					
1	Building A	Front room A101	✓		✓		✓		✓		ปกติ
2		Front room A102	✓		✓		✓		✓		ปกติ
3		Front room A201	✓		✓		✓		✓		ปกติ
4		Front room A202	✓		✓		✓		✓		ปกติ
5	Building B	Front room B101	✓		✓		✓		✓		ปกติ
6		Front room B102	✓		✓		✓		✓		ปกติ
7		Front room B201	✓		✓		✓		✓		ปกติ
8		Front room B202	✓		✓		✓		✓		ปกติ
9	Building C	Front lift 1st floor	✓		✓		✓		✓		ปกติ
10		Front room C101	✓		✓		✓		✓		ปกติ
11		Front room C105	✓		✓		✓		✓		ปกติ
12		Front room C106	✓		✓		✓		✓		ปกติ
13		Front lift 2nd floor	✓		✓		✓		✓		ปกติ
14		Front room C201	✓		✓		✓		✓		ปกติ
15		Front room C206	✓		✓		✓		✓		ปกติ
16		Front lift 3rd floor	✓		✓		✓		✓		ปกติ
17		Front room C302	✓		✓		✓		✓		ปกติ
18		Front room C304	✓		✓		✓		✓		ปกติ
19	Building D	Front lift 1st floor	✓		✓		✓		✓		ปกติ
20		Front room D101	✓		✓		✓		✓		ปกติ
21		Front room D104	✓		✓		✓		✓		ปกติ
22		Front lift 2nd floor	✓		✓		✓		✓		ปกติ
23		Front room D201	✓		✓		✓		✓		ปกติ
24		Front room D205	✓		✓		✓		✓		ปกติ
25		Front lift 3rd floor	✓		✓		✓		✓		ปกติ
26		Front room D301	✓		✓		✓		✓		ปกติ
27		Front room D305	✓		✓		✓		✓		ปกติ
28	Building E	Front lift 1st floor	✓		✓		✓		✓		ปกติ
29		Front room E101	✓		✓		✓		✓		ปกติ
30		Front room E104	✓		✓		✓		✓		ปกติ
31		Front lift 2nd floor	✓		✓		✓		✓		ปกติ
32		Front room E201	✓		✓		✓		✓		ปกติ



Fire Exit

Monthly มิถุนายน 2022

33		Front room E206	✓		✓		✓		✓		ปกติ
34		Front lift 3rd floor	✓		✓		✓		✓		ปกติ
35		Front room E301	✓		✓		✓		✓		ปกติ
36		Front room E305	✓		✓		✓		✓		ปกติ
37	Building F	Front room F105	✓		✓		✓		✓		ปกติ
38		Front shop 1st floor	✓		✓		✓		✓		ปกติ
39		Front shop 2nd floor	✓		✓		✓		✓		ปกติ
40		Front room F205	✓		✓		✓		✓		ปกติ
41		Front lift 3rd floor	✓		✓		✓		✓		ปกติ
42		Front room F303	✓		✓		✓		✓		ปกติ
43	Building G	Front room G101	✓		✓		✓		✓		ปกติ
44		Front room G102	✓		✓		✓		✓		ปกติ
45		Front room G201	✓		✓		✓		✓		ปกติ
46		Front room G202	✓		✓		✓		✓		ปกติ
47	Building H	Front room H101	✓		✓		✓		✓		ปกติ
48		Front room H102	✓		✓		✓		✓		ปกติ
49		Front room H201	✓		✓		✓		✓		ปกติ
50		Front room H202	✓		✓		✓		✓		ปกติ

Check By : XXXXXXXXXX

Approve By :

Fire Exit

Monthly ... 2023

No.	Building	Location	INDICATOR LAMP				Testing		Power Supply Test		Remark	
			AC		FAIL							
			Yes	No	Yes	No	Yes	No	Yes	No		
1	Building A	Front room A101	✓		/		/		/		ปกติ	
2		Front room A102	/		/		/		/		ปกติ	
3		Front room A201	/		/		/		/		ปกติ	
4		Front room A202	/		/		/		/		ปกติ	
5	Building B	Front room B101	/		/		/		/		ปกติ	
6		Front room B102	/		/		/		/		ปกติ	
7		Front room B201	/		/		/		/		ปกติ	
8		Front room B202	/		/		/		/		ปกติ	
9	Building C	Front lift 1st floor	/		/		/		/		ปกติ	
10		Front room C101	/		/		/		/		ปกติ	
11		Front room C105	✓		/		/		/		ปกติ	
12		Front room C106	/		/		/		/		ปกติ	
13		Front lift 2nd floor	/		/		/		/		ปกติ	
14		Front room C201	/		/		/		/		ปกติ	
15		Front room C206	/		/		/		/		ปกติ	
16		Front lift 3rd floor	/		/		/		/		ปกติ	
17		Front room C302	/		/		/		/		ปกติ	
18		Front room C304	/		/		/		/		ปกติ	
19		Building D	Front lift 1st floor	/		/		/		/		ปกติ
20			Front room D101	/		/		/		/		ปกติ
21	Front room D104		/		/		/		/		ปกติ	
22	Front lift 2nd floor		/		/		/		/		ปกติ	
23		Front room D201	/		/		/		/		ปกติ	
24		Front room D205	/		/		/		/		ปกติ	
25		Front lift 3rd floor	/		/		/		/		ปกติ	
26		Front room D301	/		/		/		/		ปกติ	
27		Front room D305	/		/		/		/		ปกติ	
28		Building E	Front lift 1st floor	/		/		/		/		ปกติ
29			Front room E101	/		/		/		/		ปกติ
30			Front room E104	/		/		/		/		ปกติ
31	Front lift 2nd floor		/		/		/		/		ปกติ	
32		Front room E201	/		/		/		/		ปกติ	

Fire Exit

Monthly ... 2023

33		Front room E206	/		/		/		/		ปกติ
34		Front lift 3rd floor	/		/		/		/		ปกติ
35		Front room E301	/		/		/		/		ปกติ
36		Front room E305	/		/		/		/		ปกติ
37	Building F	Front room F105	/		/		/		/		test แล้ว
38		Front shop 1st floor	/		/		/		/		ปกติ
39		Front shop 2nd floor	/		/		/		/		ปกติ
40		Front room F205	/		/		/		/		not test แล้ว
41		Front lift 3rd floor	/		/		/		/		ปกติ
42		Front room F303	/		/		/		/		not test แล้ว
43	Building G	Front room G101	/		/		/		/		ปกติ
44		Front room G102	/		/		/		/		ปกติ
45		Front room G201	/		/		/		/		not test แล้ว
46		Front room G202	/		/		/		/		ปกติ
47	Building H	Front room H101	/		/		/		/		ปกติ
48		Front room H102	/		/		/		/		ปกติ
49		Front room H201	/		/		/		/		ปกติ
50		Front room H202	/		/		/		/		ปกติ

Check By :

Approve By :

Emergency Lighting Testing

Monthly

No.	Building	Location	INDICATOR LAMP						Testing		Power Supply Test		Remark
			AC		CHARGE / FULL		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
1	Building A	In front of the fire room, 1st floor	✓		✓		✓		✓		✓		ปกติ
2	Building B	In front of the fire room, 1st floor		✓		✓		✓			✓		ปกติ
3	Building C	Panty room 1st floor	✓		✓		✓		✓		✓		ปกติ
4		In front of the fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
5		Staircase 1st floor		✓		✓		✓	✓			✓	ปกติ
6		Staircase 2nd floor		✓		✓		✓	✓			✓	ปกติ
7		Panty room 3rd floor		✓		✓		✓	✓			✓	ปกติ
8	Building D	Panty room 1st floor		✓		✓		✓	✓			✓	ปกติ
9		Staircase 1st floor	✓		✓		✓		✓		✓		ปกติ
10		In front of the fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
11		Staircase 2nd floor		✓		✓		✓	✓			✓	ปกติ
12		Panty room 3rd floor	✓		✓		✓		✓		✓		ปกติ
13	Building E	Panty room 1st floor	✓		✓		✓		✓		✓		ปกติ
14		Staircase 1st floor		✓		✓		✓	✓			✓	ปกติ
15		In front of the fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
16		Staircase 2nd floor	✓		✓		✓		✓		✓		ปกติ
17		Panty room 3rd floor		✓		✓		✓	✓			✓	ปกติ
18	Building F	Panty room 1st floor	✓		✓		✓		✓		✓		ปกติ
19		Staircase 1st floor	✓		✓		✓		✓		✓		ปกติ
20		Staircase 2nd floor	✓		✓		✓		✓		✓		ปกติ
21		In front of the fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
22		Panty room 3rd floor	✓		✓		✓		✓		✓		ปกติ
23	Building G	In front of the fire room, 1st floor	✓		✓		✓		✓		✓		ปกติ
24	Building H	In front of the fire room, 1st floor	✓		✓		✓		✓		✓		ปกติ
25		YOGA fire room	✓		✓		✓		✓		✓		ปกติ
26		In front of the Wine		✓		✓		✓	✓			✓	ปกติ
27		In front of Kids club	✓		✓		✓		✓		✓		ปกติ
28		Security room	✓		✓		✓		✓		✓		ปกติ
29		Office FB room	✓		✓		✓		✓		✓		ปกติ
30		In front of Store FB room	✓		✓		✓		✓		✓		ปกติ
31		In front of Store HR room	✓		✓		✓		✓		✓		ปกติ
32		Canteen room 1	✓		✓		✓		✓		✓		ปกติ
33		Canteen room 2	✓		✓		✓		✓		✓		ปกติ

Emergency Lighting Testing

Monthly

No.	Building	Location	INDICATOR LAMP						Testing		Power Supply Test		Remark
			AC		CHARGE / FULL		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
34		Front Security room	/		/		/		/		/		ปกติ
35		in front of toilet basement	/		/		/		/		/		ปกติ
36		In front of freezer room No.35	/		/		/		/		/		ปกติ
37		In front of Pump room door#1		/		/	/	/	/		/		ปกติ
38		Pump room door#2	/		/		/		/		/		ปกติ
39		Butcher room	/		/		/		/		/		ปกติ
40		Staircase MK	/		/		/		/		/		ปกติ
41	Fitness	Fire room, 1st floor		/		/	/	/	/		/		ปกติ
42		Staircase 1st floor		/		/	/	/	/		/		ปกติ
43		Fire room, 2nd floor	/		/		/		/		/		ปกติ
44		Staircase 2nd floor	/		/		/		/		/		ปกติ
45		Fire room, 3rd floor		/		/	/	/	/		/		ปกติ
46	Spa	Fire room, 1st floor		/		/	/	/	/		/		ปกติ
47		Behind kitchen 1st floor		/		/	/	/	/		/		ปกติ
48		Fire room, 2nd floor		/		/	/	/	/		/		ปกติ
49		Head Spa room 2nd floor	/		/		/		/		/		ปกติ
50													

Check By :

Approve By :

Fire Exit

Monthly... 19/01/2023

No.	Building	Location	INDICATOR LAMP				Testing		Power Supply Test		Remark
			AC		FAIL		Yes	No	Yes	No	
			Yes	No	Yes	No					
1	Building A	Front room A101	/		/		/		/		ปกติ
2		Front room A102	/		/		/		/		ปกติ
3		Front room A201	/		/		/		/		ปกติ
4		Front room A202	/		/		/		/		ปกติ
5	Building B	Front room B101	/		/		/		/		ปกติ
6		Front room B102	/		/		/		/		ปกติ
7		Front room B201	/		/		/		/		ปกติ
8		Front room B202	/		/		/		/		ปกติ
9	Building C	Front lift 1st floor	/		/		/		/		ปกติ
10		Front room C101	/		/		/		/		ปกติ
11		Front room C105	/		/		/		/		ปกติ
12		Front room C106	/		/		/		/		ปกติ
13		Front lift 2nd floor	/		/		/		/		ปกติ
14		Front room C201	/		/		/		/		ปกติ
15		Front room C206	/		/		/		/		ปกติ
16		Front lift 3rd floor	/		/		/		/		ปกติ
17		Front room C302	/		/		/		/		ปกติ
18		Front room C304	/		/		/		/		ปกติ
19	Building D	Front lift 1st floor	/		/		/		/		ปกติ
20		Front room D101	/		/		/		/		ปกติ
21		Front room D104	/		/		/		/		ปกติ
22		Front lift 2nd floor	/		/		/		/		ปกติ
23		Front room D201	/		/		/		/		ปกติ
24		Front room D205	/		/		/		/		ปกติ
25		Front lift 3rd floor	/		/		/		/		ปกติ
26		Front room D301	/		/		/		/		ปกติ
27		Front room D305	/		/		/		/		ปกติ
28	Building E	Front lift 1st floor	/		/		/		/		ปกติ
29		Front room E101	/		/		/		/		ปกติ
30		Front room E104	/		/		/		/		ปกติ
31		Front lift 2nd floor	/		/		/		/		ปกติ
32		Front room E201	/		/		/		/		ปกติ

Fire Exit

Monthly... 19/01/2023

33		Front room E206	/		/		/		/		ปกติ
34		Front lift 3rd floor	/		/		/		/		ปกติ
35		Front room E301	/		/		/		/		ปกติ
36		Front room E305	/		/		/		/		ปกติ
37	Building F	Front room F105	/		/		/		/		ปกติ
38		Front shop 1st floor	/		/		/		/		ปกติ
39		Front shop 2nd floor	/		/		/		/		ปกติ
40		Front room F205	/		/		/		/		ปกติ
41		Front lift 3rd floor	/		/		/		/		ปกติ
42		Front room F303	/		/		/		/		ปกติ
43	Building G	Front room G101	/		/		/		/		ปกติ
44		Front room G102	/		/		/		/		ปกติ
45		Front room G201	/		/		/		/		ปกติ
46		Front room G202	/		/		/		/		ปกติ
47	Building H	Front room H101	/		/		/		/		ปกติ
48		Front room H102	/		/		/		/		ปกติ
49		Front room H201	/		/		/		/		ปกติ
50		Front room H202	/		/		/		/		ปกติ

Check By :

Approve By :



Emergency Lighting Testing

Monthly ๒๕๖๕ ๒๐๒๓

No.	Building	Location	INDICATOR LAMP						Testing		Power Supply Test		Remark
			AC		CHARGE / FULL		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
1	Building A	In front of the fire room, 1st floor	/		/		/		/		/		ผ่าน
2	Building B	In front of the fire room, 1st floor	/		/		/		/		/		ผ่าน
3	Building C	Panty room 1st floor	/		/		/		/		/		ผ่าน
4		In front of the fire room, 2nd floor	/		/		/		/		/		ผ่าน
5		Staircase 1st floor		/		/		/			/		ผ่าน
6		Staircase 2nd floor		/		/		/			/		ผ่าน
7		Panty room 3rd floor		/		/		/			/		ผ่าน
8	Building D	Panty room 1st floor		/		/		/			/		ผ่าน
9		Staircase 1st floor	/		/		/		/		/		ผ่าน
10		In front of the fire room, 2nd floor	/		/		/		/		/		ผ่าน
11		Staircase 2nd floor		/		/		/			/		ผ่าน
12		Panty room 3rd floor	/		/		/		/		/		ผ่าน
13	Building E	Panty room 1st floor	/		/		/		/		/		ผ่าน
14		Staircase 1st floor		/		/		/			/		ผ่าน
15		In front of the fire room, 2nd floor	/		/		/		/		/		ผ่าน
16		Staircase 2nd floor	/		/		/		/		/		ผ่าน
17		Panty room 3rd floor		/		/		/			/		ผ่าน
18	Building F	Panty room 1st floor	/		/		/		/		/		ผ่าน
19		Staircase 1st floor	/		/		/		/		/		ผ่าน
20		Staircase 2nd floor	/		/		/		/		/		ผ่าน
21		In front of the fire room, 2nd floor	/		/		/		/		/		ผ่าน
22		Panty room 3rd floor	/		/		/		/		/		ผ่าน
23	Building G	In front of the fire room, 1st floor	/		/		/		/		/		ผ่าน
24	Building H	In front of the fire room, 1st floor	/		/		/		/		/		ผ่าน
25		YOGA fire room	/		/		/		/		/		ผ่าน
26		In front of the Wine		/		/		/			/		ผ่าน
27		In front of Kids club	/		/		/		/		/		ผ่าน
28		Security room	/		/		/		/		/		ผ่าน
29		Office FB room	/		/		/		/		/		ผ่าน
30		In front of Store FB room	/		/		/		/		/		ผ่าน
31		In front of Store HR room	/		/		/		/		/		ผ่าน
32		Canteen room 1	/		/		/		/		/		ผ่าน
33		Canteen room 2	/		/		/		/		/		ผ่าน



Emergency Lighting Testing

Monthly ๒๕๖๕ ๒๐๒๓

No.	Building	Location	INDICATOR LAMP						Testing		Power Supply Test		Remark
			AC		CHARGE / FULL		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
34		Front Security room	/		/		/		/		/		ผ่าน
35		In front of toilet basement	/		/		/		/		/		ผ่าน
36		In front of freezer room No.35	/		/		/		/		/		ผ่าน
37		In front of Pump room door#1		/		/		/			/		ผ่าน
38		Pump room door#2	/		/		/		/		/		ผ่าน
39		Butcher room	/		/		/		/		/		ผ่าน
40		Staircase MK	/		/		/		/		/		ผ่าน
41	Fitness	Fire room, 1st floor		/		/		/			/		ผ่าน
42		Staircase 1st floor		/		/		/			/		ผ่าน
43		Fire room, 2nd floor	/		/		/		/		/		ผ่าน
44		Staircase 2nd floor	/		/		/		/		/		ผ่าน
45		Fire room, 3rd floor		/		/		/			/		ผ่าน
46	Spa	Fire room, 1st floor		/		/		/			/		ผ่าน
47		Behind kitchen 1st floor		/		/		/			/		ผ่าน
48		Fire room, 2nd floor		/		/		/			/		ผ่าน
49		Head Spa room 2nd floor	/		/		/		/		/		ผ่าน
50													

Check By :

Appove By :

Fire Exit

Monthly ๑๑/๑๒/๒๕๖๓ 2023

No.	Building	Location	INDICATOR LAMP				Testing		Power Supply Test		Remark
			AC		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	
1	Building A	Front room A101	/		/		/		/		ปกติ
2		Front room A102	/		/		/		/		ปกติ
3		Front room A201	/		/		/		/		ปกติ
4		Front room A202	/		/		/		/		ปกติ
5	Building B	Front room B101	/		/		/		/		ปกติ
6		Front room B102	/		/		/		/		ปกติ
7		Front room B201	/		/		/		/		ปกติ
8		Front room B202	/		/		/		/		ปกติ
9	Building C	Front lift 1st floor	/		/		/		/		ปกติ
10		Front room C101	/		/		/		/		ปกติ
11		Front room C105	/		/		/		/		ปกติ
12		Front room C106	/		/		/		/		ปกติ
13		Front lift 2nd floor	/		/		/		/		ปกติ
14		Front room C201	/		/		/		/		ปกติ
15		Front room C206	/		/		/		/		ปกติ
16		Front lift 3rd floor	/		/		/		/		ปกติ
17		Front room C302	/		/		/		/		ปกติ
18		Front room C304	/		/		/		/		ปกติ
19	Building D	Front lift 1st floor	/		/		/		/		ปกติ
20		Front room D101	/		/		/		/		ปกติ
21		Front room D104	/		/		/		/		ปกติ
22		Front lift 2nd floor	/		/		/		/		ปกติ
23		Front room D201	/		/		/		/		ปกติ
24		Front room D205	/		/		/		/		ปกติ
25		Front lift 3rd floor	/		/		/		/		ปกติ
26		Front room D301	/		/		/		/		ปกติ
27		Front room D305	/		/		/		/		ปกติ
28	Building E	Front lift 1st floor	/		/		/		/		ปกติ
29		Front room E101	/		/		/		/		ปกติ
30		Front room E104	/		/		/		/		ปกติ
31		Front lift 2nd floor	/		/		/		/		ปกติ
32		Front room E201	/		/		/		/		ปกติ

Fire Exit

Monthly ๑๑/๑๒/๒๕๖๓ 2023

33		Front room E206	/	/	/	/	/	/	/	/	ปกติ
34		Front lift 3rd floor	/	/	/	/	/	/	/	/	ปกติ
35		Front room E301	/	/	/	/	/	/	/	/	ปกติ
36		Front room E305	/	/	/	/	/	/	/	/	ปกติ
37	Building F	Front room F105	/	/	/	/	/	/	/	/	ปกติ (หมายเหตุ)
38		Front shop 1st floor	/	/	/	/	/	/	/	/	ปกติ
39		Front shop 2nd floor	/	/	/	/	/	/	/	/	ปกติ
40		Front room F205	/	/	/	/	/	/	/	/	ปกติ (หมายเหตุ)
41		Front lift 3rd floor	/	/	/	/	/	/	/	/	ปกติ
42		Front room F303	/	/	/	/	/	/	/	/	ปกติ (หมายเหตุ)
43	Building G	Front room G101	/	/	/	/	/	/	/	/	ปกติ
44		Front room G102	/	/	/	/	/	/	/	/	ปกติ
45		Front room G201	/	/	/	/	/	/	/	/	ปกติ (หมายเหตุ)
46		Front room G202	/	/	/	/	/	/	/	/	ปกติ
47	Building H	Front room H101	/	/	/	/	/	/	/	/	ปกติ
48		Front room H102	/	/	/	/	/	/	/	/	ปกติ
49		Front room H201	/	/	/	/	/	/	/	/	ปกติ
50		Front room H202	/	/	/	/	/	/	/	/	ปกติ

Check By :

Approve By :

STAY

Emergency Lighting Testing

Monthly 2023

No.	Building	Location	INDICATOR LAMP						Testing		Power Supply Test		Remark
			AC		CHARGE / FULL		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
1	Building A	In front of the fire room, 1st floor	✓		✓		✓		✓		✓		ปกติ
2	Building B	In front of the fire room, 1st floor	✓		✓		✓		✓		✓		ปกติ
3	Building C	Panty room 1st floor	✓		✓		✓		✓		✓		ปกติ
4		In front of the fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
5		Staircase 1st floor		✓		✓		✓				✓	ปกติ
6		Staircase 2nd floor		✓		✓		✓				✓	
7		Panty room 3rd floor		✓		✓		✓				✓	
8	Building D	Panty room 1st floor		✓		✓		✓				✓	
9		Staircase 1st floor	✓		✓		✓		✓		✓		ปกติ
10		In front of the fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
11		Staircase 2nd floor		✓		✓		✓				✓	ปกติ
12		Panty room 3rd floor	✓		✓		✓		✓		✓		ปกติ
13	Building E	Panty room 1st floor	✓		✓		✓		✓		✓		ปกติ
14		Staircase 1st floor		✓		✓		✓				✓	ปกติ
15		In front of the fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
16		Staircase 2nd floor	✓		✓		✓		✓		✓		ปกติ
17		Panty room 3rd floor		✓		✓		✓				✓	ปกติ
18	Building F	Panty room 1st floor	✓		✓		✓		✓		✓		ปกติ
19		Staircase 1st floor	✓		✓		✓		✓		✓		
20		Staircase 2nd floor	✓		✓		✓		✓		✓		
21		In front of the fire room, 2nd floor	✓		✓		✓		✓		✓		
22		Panty room 3rd floor	✓		✓		✓		✓		✓		ปกติ
23	Building G	In front of the fire room, 1st floor	✓		✓		✓		✓		✓		
24	Building H	In front of the fire room, 1st floor	✓		✓		✓		✓		✓		ปกติ
25		YOGA fire room	✓		✓		✓		✓		✓		
26		In front of the Wine		✓		✓		✓				✓	
27		In front of Kids club	✓		✓		✓		✓		✓		
28		Security room	✓		✓		✓		✓		✓		ปกติ
29		Office FB room	✓		✓		✓		✓		✓		
30		In front of Store FB room	✓		✓		✓		✓		✓		
31		In front of Store HR room	✓		✓		✓		✓		✓		
32		Canteen room 1	✓		✓		✓		✓		✓		ปกติ
33		Canteen room 2	✓		✓		✓		✓		✓		

STAY

Emergency Lighting Testing

Monthly 2023

No.	Building	Location	'INDICATOR LAMP						Testing		Power Supply Test		Remark
			AC		CHARGE / FULL		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
34		Front Security room	✓		✓		✓		✓		✓		ปกติ
35		In front of toilet basement	✓		✓		✓		✓		✓		ปกติ
36		In front of freezer room No.35	✓		✓		✓		✓		✓		ปกติ
37		In front of Pump room door#1		✓		✓		✓				✓	ผิดปกติ
38		Pump room door#2	✓		✓		✓		✓		✓		ปกติ
39		Butcher room	✓		✓		✓		✓		✓		ปกติ
40		Staircase MK	✓				✓		✓		✓		ปกติ
41	Fitness	Fire room, 1st floor		✓		✓		✓				✓	ผิดปกติ
42		Staircase 1st floor		✓		✓		✓		✓		✓	ผิดปกติ
43		Fire room, 2nd floor	✓		✓		✓		✓		✓		ปกติ
44		Staircase 2nd floor	✓		✓		✓		✓		✓		ปกติ
45		Fire room, 3rd floor		✓		✓		✓				✓	
46	Spa	Fire room, 1st floor		✓		✓		✓				✓	} ผิดปกติ
47		Behind kitchen 1st floor		✓		✓		✓				✓	
48		Fire room, 2nd floor		✓		✓		✓				✓	
49		Head Spa room 2nd floor	✓		✓		✓		✓		✓		ปกติ
50													

Check By :

Approve By :

STAY

SUNSHINE
HOTEL & RESORTS

Emergency Lighting Testing

Monthly June 2022

No.	Building	Location	INDICATOR LAMP						Testing		Power Supply Test		Remark	
			AC		CHARGE / FULL		FAIL							
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No		
1	Building A	In front of the fire room, 1st floor	✓			✓		✓				✓		แบตเตอรี่เต็ม
2	Building B	In front of the fire room, 1st floor	✓			✓		✓				✓		แบตเตอรี่เต็ม
3	Building C	Panty room 1st floor	✓			✓		✓				✓		ปกติ
4		In front of the fire room, 2nd floor		✓		✓		✓			✓		✓	แบตเตอรี่เต็ม
5		Staircase 1st floor	✓			✓		✓				✓		ปกติ
6		Staircase 2nd floor	✓			✓		✓				✓		แบตเตอรี่เต็ม
7		Panty room 3rd floor	✓			✓		✓				✓		แบตเตอรี่เต็ม
8	Building D	Panty room 1st floor		✓		✓		✓			✓		✓	แบตเตอรี่เต็ม
9		Staircase 1st floor	✓			✓		✓				✓		ปกติ
10		In front of the fire room, 2nd floor	✓			✓		✓				✓		ปกติ
11		Staircase 2nd floor	✓			✓		✓				✓		แบตเตอรี่เต็ม
12		Panty room 3rd floor	✓			✓		✓				✓		ปกติ
13	Building E	Panty room 1st floor	✓			✓		✓				✓		แบตเตอรี่เต็ม
14		Staircase 1st floor	✓			✓		✓				✓		แบตเตอรี่เต็ม
15		In front of the fire room, 2nd floor	✓			✓		✓				✓		แบตเตอรี่เต็ม
16		Staircase 2nd floor	✓			✓		✓				✓		ปกติ
17		Panty room 3rd floor		✓		✓		✓			✓		✓	แบตเตอรี่เต็ม
18	Building F	Panty room 1st floor	✓			✓		✓				✓		ปกติ
19		Staircase 1st floor	✓			✓		✓				✓		แบตเตอรี่เต็ม
20		Staircase 2nd floor	✓			✓		✓				✓		แบตเตอรี่เต็ม
21		In front of the fire room, 2nd floor	✓			✓		✓				✓		ปกติ
22		Panty room 3rd floor	✓			✓		✓				✓		ปกติ
23	Building G	In front of the fire room, 1st floor	-	-	-	-	-	-	-	-	-	-	-	ไฟไม่ติด
24	Building H	In front of the fire room, 1st floor	✓			✓		✓				✓		ปกติ
25		YOGA fire room	✓			✓		✓				✓		แบตเตอรี่เต็ม
26		In front of the Wine	✓			✓		✓				✓		แบตเตอรี่เต็ม
27		In front of Kids club	-	-	-	-	-	-	-	-	-	-	-	ไฟไม่ติด
28		Security room	✓			✓		✓				✓		ปกติ
29		Office FB room	✓			✓		✓				✓		แบตเตอรี่เต็ม
30		In front of Store FB room												
31		In front of Store HR room		✓		✓		✓				✓		แบตเตอรี่เต็ม
32		Canteen room 1	✓			✓		✓				✓		แบตเตอรี่เต็ม
33		Canteen room 2	✓			✓		✓				✓		ปกติ

STAY

SUNSHINE
HOTEL & RESORTS

Emergency Lighting Testing

Monthly June 2022

No.	Building	Location	INDICATOR LAMP						Testing		Power Supply Test		Remark
			AC		CHARGE / FULL		FAIL						
			Yes	No	Yes	No	Yes	No	Yes	No	Yes	No	
34		Front Security room	✓		✓		✓		✓		✓		ปกติ
35		In front of toilet basement	✓		✓		✓		✓		✓		ปกติ
36		In front of freezer room No.35	✓		✓		✓		✓		✓		แบตเตอรี่เต็ม
37		In front of Pump room door#1	✓		✓		✓		✓		✓		ปกติ
38		Pump room door#2	✓		✓		✓		✓		✓		แบตเตอรี่เต็ม
39		Butcher room											
40		Staircase MK	✓		✓		✓		✓		✓		ปกติ
41	Fitness	Fire room, 1st floor		✓		✓		✓		✓		✓	ไฟไม่ติด
42		Staircase 1st floor		✓		✓		✓		✓		✓	แบตเตอรี่เต็ม
43		Fire room, 2nd floor	-	-	-	-	-	-	-	-	-	-	ไฟไม่ติด
44		Staircase 2nd floor	✓		✓		✓		✓		✓		แบตเตอรี่เต็ม
45		Fire room, 3rd floor	-	-	-	-	-	-	-	-	-	-	ไฟไม่ติด
46	Spa	Fire room, 1st floor	✓		✓		✓		✓		✓		แบตเตอรี่เต็ม
47		Behind kitchen 1st floor	✓		✓		✓		✓		✓		แบตเตอรี่เต็ม
48		Fire room, 2nd floor	✓		✓		✓		✓		✓		แบตเตอรี่เต็ม
49		Head Spa room 2nd floor	-	-	-	-	-	-	-	-	-	-	ไฟไม่ติด
50													

Check By : [Signature]

Approve By : [Signature]

Fire Exit

STAY

Monthly 2023

No.	Building	Location	INDICATOR LAMP				Testing		Power Supply Test		Remark
			AC		FAIL		Yes	No	Yes	No	
			Yes	No	Yes	No					
1	Building A	Front room A101	✓		✓		✓		✓		ปกติ
2		Front room A102	✓			✓	✓			✓	ทดสอบแล้วด้วย
3		Front room A201	✓		✓		✓		✓		ปกติ
4		Front room A202	✓		✓		✓		✓		ปกติ
5	Building B	Front room B101	✓		✓		✓		✓		ปกติ
6		Front room B102	✓		✓		✓		✓		ปกติ
7		Front room B201	✓		✓		✓		✓		ปกติ
8		Front room B202	✓		✓		✓		✓		ปกติ
9	Building C	Front lift 1st floor	✓		✓		✓		✓		ปกติ
10		Front room C101	✓		✓		✓		✓		ปกติ
11		Front room C105	✓		✓		✓		✓		ปกติ
12		Front room C106	✓		✓		✓		✓		ปกติ
13		Front lift 2nd floor	✓		✓		✓		✓		ปกติ
14		Front room C201	✓		✓		✓		✓		ปกติ
15		Front room C206	✓		✓		✓		✓		ปกติ
16		Front lift 3rd floor	✓			✓	✓			✓	ทดสอบแล้วด้วย
17		Front room C302	✓			✓	✓			✓	ทดสอบแล้วด้วย
18		Front room C304	-	-	-	-	-	-	-	-	ไม่พบ
19	Building D	Front lift 1st floor	✓		✓		✓		✓		ปกติ
20		Front room D101	✓		✓		✓		✓		ปกติ
21		Front room D104	✓		✓		✓		✓		ปกติ
22		Front lift 2nd floor	✓		✓		✓		✓		ปกติ
23		Front room D201	✓		✓		✓		✓		ปกติ
24		Front room D205	✓			✓	✓			✓	ทดสอบแล้วด้วย
25		Front lift 3rd floor	✓		✓		✓		✓		ปกติ
26		Front room D301	✓		✓		✓		✓		ปกติ
27		Front room D305	✓		✓		✓		✓		ปกติ
28	Building E	Front lift 1st floor	✓		✓		✓		✓		ปกติ
29		Front room E101	✓		✓		✓		✓		ปกติ
30		Front room E104	✓		✓		✓		✓		ปกติ
31		Front lift 2nd floor	✓		✓		✓		✓		ปกติ
32		Front room E201	✓		✓		✓		✓		ปกติ
33		Front room E206	✓		✓		✓		✓		ปกติ
34		Front lift 3rd floor	✓		✓		✓		✓		ปกติ
35		Front room E301	✓		✓		✓		✓		ปกติ
36		Front room E305	✓		✓		✓		✓		ปกติ

Fire Exit

STAY

Monthly 2023

37	Building F	Front room F105	✓		✓		✓		✓		ปกติ
38		Front shop 1st floor	✓		✓		✓		✓		ปกติ
39		Front shop 2nd floor	✓		✓		✓		✓		ปกติ
40		Front room F205	✓		✓		✓		✓		ปกติ
41		Front lift 3rd floor	✓		✓		✓		✓		ปกติ
42		Front room F303	✓		✓		✓		✓		ปกติ
43	Building G	Front room G101	✓		✓		✓		✓		ปกติ
44		Front room G102	✓		✓		✓		✓		ปกติ
45		Front room G201	✓		✓		✓		✓		ปกติ
46		Front room G202	✓		✓		✓		✓		ปกติ
47	Building H	Front room H101	✓		✓		✓		✓		ปกติ
48		Front room H102	✓		✓		✓		✓		ปกติ
49		Front room H201	✓		✓		✓		✓		ปกติ
50		Front room H202	✓		✓		✓		✓		ปกติ

Check By :

Approve By :