

ภาคผนวก ซ-2

การตรวจสอบอุปกรณ์ดับเพลิง



Travelodge

SUKHUMVIT 11

TRAVELODGE SUKHUMVIT
ENGINEERING DEPARTMENT
EXTINGUISHERS CHECKLIST


Tower A			Tower B		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room	195	/	Roof FHC (1)	195	/
FL.8 FHC	195	/	Roof FHC (2)	195	/
FL.7 corridor	100	/	FL.8 FHC 2801	195	/
FL.7 FHC	195	/	FL.8 FHC 2821	195	/
FL.6 corridor	100	/	FL.8 staff lift	100	/
FL.6 FHC	195	/	FL.7 FHC 2701	195	/
FL.5 corridor	100	/	FL.7 FHC 2721	195	/
FL.5 FHC	195	/	FL.7 staff lift	100	/
FL.4 corridor	100	/	FL.6 FHC 2601	195	/
FL.4 FHC	CO2	/	FL.6 FHC 2621	195	/
FL.3 corridor	100	/	FL.6 staff lift	100	/
FL.3 FHC	195	/	FL.5 FHC 2501	195	/
FL.2 corridor	100	/	FL.5 FHC 2521	195	/
FL.2 FHC	CO2	/	FL.5 staff lift	100	/
FL.G FHC security	195	/	FL.4 FHC 2401	195	/
FL.G FHC restaurant	195	/	FL.4 FHC 2421	195	/
FL.B1 FHC	195	/	FL.4 staff lift	100	/
FL.B1 kitchen (1)	100	/	FL.3 FHC 2301	195	/
FL.B1 kitchen (2)	100	/	FL.3 FHC 2321	195	/
FL.B1 staff lift	100	/	FL.3 staff lift	100	/
FL.B2 staff lift	100	/	FL.2 FHC 2201	195	/
FL.B2 FHC	195	/	FL.2 FHC 2221	100	/
FL.B2 FHC fire pump	195	/	FL.2 staff lift	100	/
Generator room	CO2	/	FL.G FHC Lobby	195	/
MDB Room	CO2	/	FHC front office	195	/
no B Room	CO2	/	FL.B1 FHC Car park	195/195	/
			FL.B2 FHC Car park	195/195	/

Checked By Supervisor		Date	6/7/23
Approve By Chief Engineer		Date	


Tower A			Tower B		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room	195	/	Roof FHC (1)	195	/
FL.8 FHC	195	/	Roof FHC (2)	195	/
FL.7 corridor	100	/	FL.8 FHC 2801	195	/
FL.7 FHC	195	/	FL.8 FHC 2821	100	/
FL.6 corridor	100	/	FL.8 staff lift	195	/
FL.6 FHC	100	/	FL.7 FHC 2701	195	/
FL.5 corridor	195	/	FL.7 FHC 2721	195	/
FL.5 FHC	100	/	FL.7 staff lift	100	/
FL.4 corridor	CO2	/	FL.6 FHC 2601	195	/
FL.4 FHC	100	/	FL.6 FHC 2621	195	/
FL.3 corridor	195	/	FL.6 staff lift	100	/
FL.3 FHC	100	/	FL.5 FHC 2501	195	/
FL.2 corridor	100	/	FL.5 FHC 2521	195	/
FL.2 FHC	CO2	/	FL.5 staff lift	100	/
FL.G FHC security	195	/	FL.4 FHC 2401	195	/
FL.G FHC restaurent	195	/	FL.4 FHC 2421	195	/
FL.B1 FHC	195	/	FL.4 staff lift	195	/
FL.B1 kitchen (1)	195	/	FL.3 FHC 2301	195	/
FL.B1 kitchen (2)	100	/	FL.3 FHC 2321	195	/
FL.B1 staff lift	100	/	FL.3 staff lift	100	/
FL.B2 staff lift	100	/	FL.2 FHC 2201	195	/
FL.B2 FHC	100	/	FL.2 FHC 2221	100	/
FL.B2 FHC fire pump	195	/	FL.2 staff lift	100	/
Generator room	CO2	/	FL.G FHC Lobby	195	/
MDB Room	CO2	/	FHC front office	195	/
MDB Room	CO2	/	FL.B1 FHC Car park	195 / 195	/
			FL.B2 FHC Car park	195 / 195	/

Checked By Supervisor	<i>Bodan</i>	Date	8 / 4 / 23
Approve By Chief Engineer		Date	

Tower A			Tower B		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room	195	/	Roof FHC (1)	195	/
FL.8 FHC	195	/	Roof FHC (2)	195	/
FL.7 corridor	100	/	FL.8 FHC 2801	195	/
FL.7 FHC	195	/	FL.8 FHC 2821	195	/
FL.6 corridor	100	/	FL.8 staff lift	100	/
FL.6 FHC	100	/	FL.7 FHC 2701	195	/
FL.5 corridor	195	/	FL.7 FHC 2721	195	/
FL.5 FHC	100	/	FL.7 staff lift	100	/
FL.4 corridor	100	/	FL.6 FHC 2601	195	/
FL.4 FHC	100	/	FL.6 FHC 2621	195	/
FL.3 corridor	195	/	FL.6 staff lift	195	/
FL.3 FHC	100	/	FL.5 FHC 2501	195	/
FL.2 corridor	100	/	FL.5 FHC 2521	195	/
FL.2 FHC	195	/	FL.5 staff lift	195	/
FL.G FHC security	195	/	FL.4 FHC 2401	195	/
FL.G FHC restaurant	100	/	FL.4 FHC 2421	195	/
FL.B1 FHC	100	/	FL.4 staff lift	100	/
FL.B1 kitchen (1)	100	/	FL.3 FHC 2301	195	/
FL.B1 kitchen (2)	100	/	FL.3 FHC 2321	195	/
FL.B1 staff lift	100	/	FL.3 staff lift	100	/
FL.B2 staff lift	195	/	FL.2 FHC 2201	195	/
FL.B2 FHC	100	/	FL.2 FHC 2221	100	/
FL.B2 FHC fire pump	100	/	FL.2 staff lift	100	/
Generator room	100	/	FL.G FHC Lobby	195	/
MDB Room	100	/	FHC front office	195	/
			FL.B1 FHC Car park	195/195	/
			FL.B2 FHC Car park	195/195	/

Checked By Supervisor		Date	8/9/23
Approve By Chief Engineer		Date	


Tower A			Tower B		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room	195	/	Roof FHC (1)	195	/
FL.8 FHC	195	/	Roof FHC (2)	195	/
FL.7 corridor	100	/	FL.8 FHC 2801	195	/
FL.7 FHC	195	/	FL.8 FHC 2821	195	/
FL.6 corridor	100	/	FL.8 staff lift	100	/
FL.6 FHC	195	/	FL.7 FHC 2701	195	/
FL.5 corridor	100	/	FL.7 FHC 2721	195	/
FL.5 FHC	195	/	FL.7 staff lift	100	/
FL.4 corridor	100	/	FL.6 FHC 2601	195	/
FL.4 FHC	CO2	/	FL.6 FHC 2621	195	/
FL.3 corridor	100	/	FL.6 staff lift	100	/
FL.3 FHC	195	/	FL.5 FHC 2501	195	/
FL.2 corridor	100	/	FL.5 FHC 2521	195	/
FL.2 FHC	CO2	/	FL.5 staff lift	100	/
FL.G FHC security	195	/	FL.4 FHC 2401	195	/
FL.G FHC restaurant	195	/	FL.4 FHC 2421	195	/
FL.B1 FHC	195	/	FL.4 staff lift	100	/
FL.B1 kitchen (1)	100	/	FL.3 FHC 2301	195	/
FL.B1 kitchen (2)	100	/	FL.3 FHC 2321	195	/
FL.B1 staff lift	100	/	FL.3 staff lift	100	/
FL.B2 staff lift	100	/	FL.2 FHC 2201	195	/
FL.B2 FHC	195	/	FL.2 FHC 2221	100	/
FL.B2 FHC fire pump	195	/	FL.2 staff lift	100	/
Generator room	CO2	/	FL.G FHC Lobby	195	/
MDB Room	CO2	/	FHC front office	195	/
MDB room	CO2	/	FL.B1 FHC Car park	195/195	/
			FL.B2 FHC Car park	195/195	/

Checked By Supervisor		Date	6/10/23
Approve By Chief Engineer		Date	

Tower A			Tower B		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room	195	/	Roof FHC (1)	195	/
FL.8 FHC	195	/	Roof FHC (2)	195	/
FL.7 corridor	100	/	FL.8 FHC 2801	195	/
FL.7 FHC	195	/	FL.8 FHC 2821	195	/
FL.6 corridor	100	/	FL.8 staff lift	100	/
FL.6 FHC	195	/	FL.7 FHC 2701	195	/
FL.5 corridor	100	/	FL.7 FHC 2721	195	/
FL.5 FHC	195	/	FL.7 staff lift	100	/
FL.4 corridor	100	/	FL.6 FHC 2601	195	/
FL.4 FHC	CO2	/	FL.6 FHC 2621	195	/
FL.3 corridor	100	/	FL.6 staff lift	100	/
FL.3 FHC	195	/	FL.5 FHC 2501	195	/
FL.2 corridor	100	/	FL.5 FHC 2521	195	/
FL.2 FHC	CO2	/	FL.5 staff lift	100	/
FL.G FHC security	195	/	FL.4 FHC 2401	195	/
FL.G FHC restaurant	195	/	FL.4 FHC 2421	195	/
FL.B1 FHC	195	/	FL.4 staff lift	100	/
FL.B1 kitchen (1)	100	/	FL.3 FHC 2301	195	/
FL.B1 kitchen (2)	100	/	FL.3 FHC 2321	195	/
FL.B1 staff lift	100	/	FL.3 staff lift	100	/
FL.B2 staff lift	100	/	FL.2 FHC 2201	195	/
FL.B2 FHC	195	/	FL.2 FHC 2221	100	/
FL.B2 FHC fire pump	195	/	FL.2 staff lift	100	/
Generator room	CO2	/	FL.G FHC Lobby	195	/
MDB Room	CO2	/	FHC front office	195	/
MOB Room	CO2	/	FL.B1 FHC Car park	195/195	/
			FL.B2 FHC Car park	195/195	/

Checked By Supervisor	<i>13092W</i>	Date	5/11/23
Approve By Chief Engineer		Date	

Tower A			Tower B		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room	195	/	Roof FHC (1)	195	/
FL.8 FHC	195	/	Roof FHC (2)	195	/
FL.7 corridor	100	/	FL.8 FHC 2801	195	/
FL.7 FHC	195	/	FL.8 FHC 2821	195	/
FL.6 corridor	100	/	FL.8 staff lift	100	/
FL.6 FHC	195	/	FL.7 FHC 2701	195	/
FL.5 corridor	100	/	FL.7 FHC 2721	195	/
FL.5 FHC	195	/	FL.7 staff lift	100	/
FL.4 corridor	100	/	FL.6 FHC 2601	195	/
FL.4 FHC	CO2	/	FL.6 FHC 2621	195	/
FL.3 corridor	100	/	FL.6 staff lift	100	/
FL.3 FHC	195	/	FL.5 FHC 2501	195	/
FL.2 corridor	100	/	FL.5 FHC 2521	195	/
FL.2 FHC	CO2	/	FL.5 staff lift	100	/
FL.G FHC security	195	/	FL.4 FHC 2401	195	/
FL.G FHC restaurant	195	/	FL.4 FHC 2421	195	/
FL.B1 FHC	195	/	FL.4 staff lift	100	/
FL.B1 kitchen (1)	100	/	FL.3 FHC 2301	195	/
FL.B1 kitchen (2)	100	/	FL.3 FHC 2321	195	/
FL.B1 staff lift	100	/	FL.3 staff lift	100	/
FL.B2 staff lift	100	/	FL.2 FHC 2201	195	/
FL.B2 FHC	195	/	FL.2 FHC 2221	100	/
FL.B2 FHC fire pump	195	/	FL.2 staff lift	100	/
Generator room	CO2	/	FL.G FHC Lobby	195	/
MDB Room	CO2	/	FHC front office	195	/
MEB Room	CO2	/	FL.B1 FHC Car park	195/195	/
			FL.B2 FHC Car park	195/195	/

Checked By Supervisor		Date	5/12/66
Approve By Chief Engineer		Date	7/12/66