

ภาคผนวก ข-5

ใบเสร็จรับเงินค่าธรรมเนียมการจัดเก็บมูลฝอย





L&H Property Co.,Ltd.

100 Wireless Road, Lumpini, Patumwan, Bangkok 10330, Thailand.

Tel. +66 2 055 9000 Fax. +66 2 055 9009

Tax ID : 0105548017097 Branch : 00003

ใบสั่งจ่าย

วันที่พิมพ์ : 03/07/2566, 16:07

เลขที่ใบสั่งจ่าย : PVHP303660574

โครงการที่สั่งจ่าย : HP303 - GCP-PC

จ่าย : นายเกษม มณฑาสูข

วันที่บันทึก : 03/07/2566

แผนก : Executive Office (Admin., Inventory, ช่างไม้, IT)


ประเภทการจ่าย : สัญญา

เลขที่เอกสาร	งวดที่	รายการสั่งจ่าย	รหัสบัญชี	จำนวนเงิน	Vat	รวมจำนวนเงิน
JOHP303660003	7	ค่าบริการเก็บขยะ งวดที่ 7 กรกฎาคม 2566	50238 : Waste Collection Fee	5,000.00	0	5,000.00
			รวม :	5,000.00	0	5,000.00



นาย อัครเดช พันธขาว

Inventory Officer



นาย อนนทร คงศิริพันธ์

General Manager



L&H Property Co.,Ltd.

100 Wireless Road, Lumpini, Patumwan, Bangkok 10330, Thailand.

Tel. +66 2 055 9000 Fax. +66 2 055 9009

Tax ID : 0105548017097 Branch : 00003

ใบสั่งจ่าย

วันที่พิมพ์ : 02/08/2566, 17:55

เลขที่ใบสั่งจ่าย : PVHP303660664

โครงการที่สั่งจ่าย : HP303 - GCP-PC

จ่าย : นายเกษม มณฑาสุข

วันที่บันทึก : 02/08/2566

แผนก : Executive Office (Admin., Inventory, ช่างไม้, IT)


ประเภทการจ่าย : สัญญา

เลขที่เอกสาร	งวดที่	รายการสั่งจ่าย	รหัสบัญชี	จำนวนเงิน	Vat	รวมจำนวนเงิน
JOHP303660003	8	ค่าบริการเก็บขยะ งวดที่ 8 สิงหาคม 2566	50238 : Waste Collection Fee	5,000.00	0	5,000.00
			รวม :	5,000.00	0	5,000.00



นาย อัครเดช พันธขาว

Inventory Officer



นาย อนนทร์ คงศิริพันธ์

General Manager



L&H Property Co.,Ltd.

100 Wireless Road, Lumpini, Patumwan, Bangkok 10330, Thailand.

Tel. +66 2 055 9000 Fax. +66 2 055 9009

Tax ID : 0105548017097 Branch : 00003

ใบสั่งจ่าย

วันที่พิมพ์ : 01/09/2566, 13:58

เลขที่ใบสั่งจ่าย : PVHP303660751

โครงการที่สั่งจ่าย : HP303 - GCP-PC

จ่าย : นายเกษม มณฑาสูข

วันที่บันทึก : 01/09/2566

แผนก : Executive Office (Admin., Inventory, ช่างไม้, IT)

ประเภทการจ่าย : สัญญา

เลขที่เอกสาร	งวดที่	รายการสั่งจ่าย	รหัสบัญชี	จำนวนเงิน	Vat	รวมจำนวนเงิน
JOHP303660003	9	ค่าบริการเก็บขยะ งวดที่ 9 กันยายน 2566	50238 : Waste Collection Fee	5,000.00	0	5,000.00
			รวม :	5,000.00	0	5,000.00



นาย อัครเดช พันธะขาว

Inventory Officer



นาย อนนทร คงศิริจันทร์

General Manager



L&H Property Co.,Ltd.

100 Wireless Road, Lumpini, Patumwan, Bangkok 10330, Thailand.

Tel. +66 2 055 9000 Fax. +66 2 055 9009

Tax ID : 0105548017097 Branch : 00003

ใบส่งจ่าย

วันที่พิมพ์ : 02/10/2566, 12:47

เลขที่ใบส่งจ่าย : PVHP303660828

โครงการที่ส่งจ่าย : HP303 - GCP-PC

จ่าย : นายเกษม มณฑาสุข

วันที่บันทึก : 02/10/2566

แผนก : Executive Office (Admin., Inventory, ช่างไม้, IT)

ประเภทการจ่าย : สัญญา

เลขที่เอกสาร	งวดที่	รายการส่งจ่าย	รหัสบัญชี	จำนวนเงิน	Vat	รวมจำนวนเงิน
JOHP303660003	10	ค่าบริการเก็บขยะ งวดที่ 10 ตุลาคม 2566	50238 : Waste Collection Fee	5,000.00	0	5,000.00
			รวม :	5,000.00	0	5,000.00



นาย อัครเดช พันธขาว

Inventory Officer



นาย อนนทร กงศิริพันธ์

General Manager



L&H Property Co.,Ltd.

100 Wireless Road, Lumpini, Patumwan, Bangkok 10330, Thailand.

Tel. +66 2 055 9000 Fax. +66 2 055 9009

Tax ID : 0105548017097 Branch : 00003

ใบสั่งจ่าย

วันที่พิมพ์ : 01/11/2566, 17:45

เลขที่ใบสั่งจ่าย : PVHP303660934

วันที่บันทึก : 01/11/2566

โครงการที่สั่งจ่าย : HP303 - GCP-PC

แผนก : Executive Office (Admin., Inventory, ช่างไม้, IT)

จ่าย : นายเกษม มณฑาสูข

ประเภทการจ่าย : สัญญา

เลขที่เอกสาร	งวดที่	รายการสั่งจ่าย	รหัสบัญชี	จำนวนเงิน	Vat	รวมจำนวนเงิน
JOHP303660003	11	ค่าบริการเก็บขยะ งวดที่ 11 พฤศจิกายน 2566	50238 : Waste Collection Fee	5,000.00	0	5,000.00
			รวม :	5,000.00	0	5,000.00



นาย อัครเดช พันธุ์ขาว

Inventory Officer



นาย อนนทร์ กงศิริพันธ์

General Manager

หลักฐานการรับเงิน

ข้าพเจ้า (นาย / นาง / นางสาว) _____

ที่อยู่ _____

บัตรประจำตัวประชาชนเลขที่ _____

บัตรประจำตัวผู้เสียภาษีเลขที่ _____

ได้รับเงินค่า

บริการเก็บขยะ เดือน กรกฎาคม 2566

เป็นจำนวนเงิน _____ บาท

(_____)

หัก อัตราภาษี _____ %

เป็นจำนวนเงิน _____ บาท

(_____)

จำนวนเงิน สุทธิทั้งสิ้น _____ บาท

(_____)

☐ หักภาษีจากผู้มีเงินได้

☐ บริษัท รับภาระภาษี

☐ เงินสด

☐ เช็คธนาคาร

สาขา _____

เลขที่ _____

ลงวันที่ _____

จาก “บริษัท แอล แอนด์ เอช พร็อพเพอร์ตี้ จำกัด” เรียบร้อยแล้ว

ลงชื่อ _____

(_____)

หมายเหตุ : แนบสำเนาบัตรประจำตัวประชาชน

PV HP303 660579



บัตรประจำตัวประชาชน Thai National ID Card

เลขประจำตัวประชาชน
Identification Number

ชื่อตัวและชื่อสกุล

Name Mr. Kasem

Last name Monthasuk

เกิดวันที่ 28 ธ.ค. 2513

Date of Birth 28 Dec. 1970

ศาสนา พุทธ

ที่อยู่ 64/99 หมู่ที่ 3 ต.บางคูวัด อ.บางบัวทอง

จ.นนทบุรี

17 พ.ค. 2565

วันออกบัตร

17 May 2022

Date of Issue

นายสมศักดิ์ จงจิระ

เจ้าพนักงานออกบัตร

27 ธ.ค. 2573

วันบัตรหมดอายุ

27 Dec. 2030

Date of Expiry

สีทอง



ภาคผนวก ข-6

เอกสารการตรวจสอบอุปกรณ์ป้องกันและเตือนอัคคีภัย



Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

MONTH กรกฎาคม 66

EMERGENCY LIGHT SYSTEM

TIME

Floor	SF 1					SF 2					SF 3					SF 4					โถงทางเดิน												
	Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Charge	LAMP		LAMP		LAMP		LAMP		LAMP		LAMP	
				R	L				R	L				R	L				R	L		R	L	R	L	R	L	R	L	R	L	R	L
Roof	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
31	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
30	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
29	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
28	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
27	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
26	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
25	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
23	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
22	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
21	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
20	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
19	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
18	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
17	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
16	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
15	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
12	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
11	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
10	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
F	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
F	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
F	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
M	✓	✓	✓	✓	✓											✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
P1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
P2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		

RECORD BY:.....

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

MONTH ธันวาคม 66

EMERGENCY LIGHT SYSTEM

TIME

Floor	SF 1				SF 2				SF 3				SF 4				โถงทางเดิน											
	Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Charge	LAMP		LAMP		LAMP		LAMP		LAMP		LAMP	
				R	L				R	L				R	L		R	L	R	L	R	L	R	L	R	L	R	L
Roof	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
31	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
30	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
29	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
28	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
27	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
26	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
25	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
23	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
22	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
21	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
20	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
19	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
18	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
17	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
16	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
15	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
12	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
11	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
10	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
F	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
F	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
F	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
M	✓	✓	✓	✓	✓									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
P1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
P2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
P3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
P4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Substation room						✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Generator room						✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Booster pump room						✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Water pump room						✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
CCTV room						✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Engineer room						✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Office Room						✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Life พนักงาน						✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Life ลูกค้า						✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
ร้านอาหาร						✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓

RECORD BY:.....

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

MONTH มิถุนายน 66

EMERGENCY LIGHT SYSTEM

TIME

Floor	SF 1				SF 2				SF 3				SF 4				โถงทางเดิน												
	Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Charge	LAMP		LAMP	LAMP	LAMP	LAMP	LAMP	LAMP	LAMP	LAMP	LAMP	LAMP	LAMP
				R	L				R	L				R	L		R	L	R	L	R	L	R	L	R	L	R	L	R
Roof	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
31	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
30	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
29	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
28	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
27	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
26	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
25	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
23	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
22	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
21	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
20	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
19	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
18	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
17	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
16	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
15	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
12	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
11	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
10	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
9	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
8	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
7	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
6	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
5	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
3	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
F	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
F	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
F	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
M	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
L	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
P1	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
P2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
P3	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
P4	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
Substation room					2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
Generator room					2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
Booster pump room					2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
Water pump room					2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
CCTV room					2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
Engineer room					2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
Office Room					2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
Life พนักงาน					2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
Life ลูกค้า					2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
ร้าน อาหาร					2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2

RECORD BY:.....

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

MONTH กุมภาพันธ์ 66

EMERGENCY LIGHT SYSTEM

TIME

Floor	SF 1					SF 2					SF 3					SF 4					โถงทางเดิน												
	Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Charge	LAMP		LAMP		LAMP		LAMP		LAMP		LAMP	
				R	L				R	L				R	L				R	L		R	L	R	L	R	L	R	L	R	L	R	L
Roof	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
31	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
30	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
29	N	N	N	N	N											N	N	N	N	N	N	N	N	N	N								
28	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
27	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
26	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
25	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
23	N	N	N	N	N											N	N	N	N	N	N	N	N	N	N								
22	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
21	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
20	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
19	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
18	N	N	N	N	N											N	N	N	N	N	N	N	N	N	N								
17	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
16	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
15	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
12	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
11	N	N	N	N	N											N	N	N	N	N	N	N	N	N	N								
10	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
9	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
8	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
7	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
6	N	N	N	N	N											N	N	N	N	N	N	N	N	N	N								
5	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
3	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
F	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
F	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
F	N	N	N	N	N											N	N	N	N	N	N	N	N	N	N								
M	N	N	N	N	N											N	N	N	N	N		N	N	N	N	N							
L	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
P1	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
P2	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
P3	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
P4	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
Substation room						N	N	N	N	N																							
Generator room						N	N	N	N	N																							
Booster pump room						N	N	N	N	N																							
Water pump room						N	N	N	N	N																							
CCTV room						N	N	N	N	N																							
Engineer room						N	N	N	N	N																							
Office Room						N	N	N	N	N																							
Life พนักงาน						N	N	N	N	N																							
Life ลูกค้า						N	N	N	N	N																							
ร้านอาหาร						N	N	N	N	N																							

RECORD BY [REDACTED]

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

MONTH

พฤษภาคม 66

EMERGENCY LIGHT SYSTEM

TIME

Floor	SF 1				SF 2				SF 3				SF 4				โถงทางเดิน													
	Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Charge	LAMP		LAMP		LAMP		LAMP		LAMP		LAMP			
				R	L				R	L				R	L		R	L	R	L	R	L	R	L	R	L	R	L		
Roof	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
31	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
30	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
29	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
28	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
27	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
26	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
25	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
23	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
22	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
21	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
20	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
19	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
18	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
17	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
16	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
15	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
12	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
11	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
10	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
9	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
8	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
7	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
6	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
5	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
3	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
F	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
F	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
F	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
M	2	2	2	2	2									2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
L	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
P1	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
P2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
P3	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
P4	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	
Substation room						2	2	2	2	2	2	2	2					2	2	2	2	2	2	2	2	2	2	2	2	2
Generator room						2	2	2	2	2	2	2	2					2	2	2	2	2	2	2	2	2	2	2	2	2
Booster pump room						2	2	2	2	2	2	2	2					2	2	2	2	2	2	2	2	2	2	2	2	2
Water pump room						2	2	2	2	2	2	2	2					2	2	2	2	2	2	2	2	2	2	2	2	2
CCTV room						2	2	2	2	2	2	2	2					2	2	2	2	2	2	2	2	2	2	2	2	2
Engineer room						2	2	2	2	2	2	2	2					2	2	2	2	2	2	2	2	2	2	2	2	2
Office Room						2	2	2	2	2	2	2	2					2	2	2	2	2	2	2	2	2	2	2	2	2
Life พนักงาน						2	2	2	2	2	2	2	2					2	2	2	2	2	2	2	2	2	2	2	2	2
Life ลูกค้า						2	2	2	2	2	2	2	2					2	2	2	2	2	2	2	2	2	2	2	2	2
ร้าน อาหาร						2	2	2	2	2	2	2	2					2	2	2	2	2	2	2	2	2	2	2	2	2

RECORD BY: [REDACTED]

RECHECK BY:

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

MONTH ธันวาคม
TIME

SYSTEM & SAFETY

EMERGENCY LIGHT SYSTEM

Floor	SF 1					SF 2					SF 3					SF 4					โถงทางเดิน															
	Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Ready	Charge	S.W	LAMP		Charge	LAMP		LAMP		LAMP		LAMP		LAMP		LAMP				
				R	L				R	L				R	L				R	L		R	L	R	L	R	L	R	L	R	L	R	L	R	L	R
Roof	N	N	N	N	N																	N	N	N	N	N	N	N	N	N	N	N	N			
31	N	N	N	N	N																	N	N	N	N	N	N	N	N	N	N	N	N			
30	N	N	N	N	N																	N	N	N	N	N	N	N	N	N	N	N	N			
29	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
28	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
27	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
26	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
25	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
23	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
22	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
21	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
20	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
19	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
18	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
17	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
16	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
15	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
12	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
11	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
10	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
9	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
8	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
7	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
6	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
5	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
3	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
F	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
F	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
F	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
M	N	N	N	N	N																N	N	N	N	N	N	N	N	N	N	N	N	N			
L	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N			
P1	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N			
P2	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N			
P3	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N			
P4	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N			
Substation room					N	N	N	N	N																											
Generator room					N	N	N	N	N																											
Booster pump room					N	N	N	N	N																											
Water pump room					N	N	N	N	N																											
CCTV room					N	N	N	N	N																											
Engineer room					N	N	N	N	N																											
Office Room					N	N	N	N	N																											
Life พนักงาน					N	N	N	N	N																											
Life ลูกค้า					N	N	N	N	N																											
ร้านอาหาร					N	N	N	N	N																											

RECORD BY:.....

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY
FIRE POTECTION SYSTEM

MONTH มกราคม ๖๖
TIME

Floor	FHC (Corridor)				FHC (Service Lift Area)				Fire Pipe		
	Hose Real	Hose Valve	Fire Extinguisher		Hose Real	Hose Valve	Fire Extinguisher		Fire Test	Flow switch	Supervisory valve
			Weight(Kg)	Gauge			Weight(Kg)	Gauge			
Roof											
31											
30											
29											
28											
27											
26											
25											
23											
22											
21											
20											
19											
18											
17											
16											
15											
12											
11											
10											
9											
8											
7											
6											
5											
3											
F											
M											
L											
P1											
P2											
P3											
P4											
Lift room											
Booster pump room											
Transformer room											
Swimming pool room											
Water pump room											
Generator room											

RECORD BY: [REDACTED]

RECHECK BY:

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

MONTH June 2021

FIRE POTECTION SYSTEM

TIME

Floor	FHC (Corridor)				FHC (Service Lift Area)				Fire Pipe		
	Hose Real	Hose Valve	Fire Extinguisher		Hose Real	Hose Valve	Fire Extinguisher		Fire Test	Flow switch	Supervisory valve
			Weight(Kg)	Gauge			Weight(Kg)	Gauge			
Roof											
31	22	22	22	22	22	22	22	22	22	22	22
30	22	22	22	22	22	22	22	22	22	22	22
29	22	22	22	22	22	22	22	22	22	22	22
28	22	22	22	22	22	22	22	22	22	22	22
27	22	22	22	22	22	22	22	22	22	22	22
26	22	22	22	22	22	22	22	22	22	22	22
25	22	22	22	22	22	22	22	22	22	22	22
23	22	22	22	22	22	22	22	22	22	22	22
22	22	22	22	22	22	22	22	22	22	22	22
21	22	22	22	22	22	22	22	22	22	22	22
20	22	22	22	22	22	22	22	22	22	22	22
19	22	22	22	22	22	22	22	22	22	22	22
18	22	22	22	22	22	22	22	22	22	22	22
17	22	22	22	22	22	22	22	22	22	22	22
16	22	22	22	22	22	22	22	22	22	22	22
15	22	22	22	22	22	22	22	22	22	22	22
12	22	22	22	22	22	22	22	22	22	22	22
11	22	22	22	22	22	22	22	22	22	22	22
10	22	22	22	22	22	22	22	22	22	22	22
9	22	22	22	22	22	22	22	22	22	22	22
8	22	22	22	22	22	22	22	22	22	22	22
7	22	22	22	22	22	22	22	22	22	22	22
6	22	22	22	22	22	22	22	22	22	22	22
5	22	22	22	22	22	22	22	22	22	22	22
3	22	22	22	22	22	22	22	22	22	22	22
F	22	22	22	22	22	22	22	22	22	22	22
M	22	22	22	22	22	22	22	22	22	22	22
L	22	22	22	22	22	22	22	22	22	22	22
P1	22	22	22	22	22	22	22	22	22	22	22
P2	22	22	22	22	22	22	22	22	22	22	22
P3	22	22	22	22	22	22	22	22	22	22	22
P4	22	22	22	22	22	22	22	22	22	22	22
Lift room							22	22			
Booster pump room							22	22			
Transformer room							22	22			
Swimming pool room							22	22			
Water pump room							22	22			
Generator room							22	22			

RECORD BY:.....

RECHECK BY:.....

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

MONTH มิถุนายน 66

FIRE POTECTION SYSTEM

TIME

Floor	FHC (Corridor)				FHC (Service Lift Area)				Fire Pipe		
	Hose Real	Hose Valve	Fire Extinguisher		Hose Real	Hose Valve	Fire Extinguisher		Fire Test	Flow switch	Supervisory valve
			Weight(Kg)	Gauge			Weight(Kg)	Gauge			
Roof											
31											
30											
29											
28											
27											
26											
25											
23											
22											
21											
20											
19											
18											
17											
16											
15											
12											
11											
10											
9											
8											
7											
6											
5											
3											
F											
M											
L											
P1											
P2											
P3											
P4											
Lift room											
Booster pump room											
Transformer room											
Swimming pool room											
Water pump room											
Generator room											

RECORD BY:.....

RECHECK BY:.....

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY
FIRE POTECTION SYSTEM

MONTH May 2022
TIME 66

Floor	FHC (Corridor)				FHC (Service Lift Area)				Fire Pipe		
	Hose Real	Hose Valve	Fire Extinguisher		Hose Real	Hose Valve	Fire Extinguisher		Fire Test	Flow switch	Supervisory valve
			Weight(Kg)	Gauge			Weight(Kg)	Gauge			
Roof											
31											
30											
29											
28											
27											
26											
25											
23											
22											
21											
20											
19											
18											
17											
16											
15											
12											
11											
10											
9											
8											
7											
6											
5											
3											
F											
M											
L											
P1											
P2											
P3											
P4											
Lift room											
Booster pump room											
Transformer room											
Swimming pool room											
Water pump room											
Generator room											

RECORD BY:

RECHECK BY:

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

FIRE POTECTION SYSTEM

MONTH พฤษภาคม ๒๕๖๒

TIME

Floor	FHC (Corridor)				FHC (Service Lift Area)				Fire Pipe		
	Hose Real	Hose Valve	Fire Extinguisher		Hose Real	Hose Valve	Fire Extinguisher		Fire Test	Flow switch	Supervisory valve
			Weight(Kg)	Gauge			Weight(Kg)	Gauge			
Roof											
31											
30											
29											
28											
27											
26											
25											
23											
22											
21											
20											
19											
18											
17											
16											
15											
12											
11											
10											
9											
8											
7											
6											
5											
3											
F											
M											
L											
P1											
P2											
P3											
P4											
Lift room											
Booster pump room											
Transformer room											
Swimming pool room											
Water pump room											
Generator room											

RECORD BY: [REDACTED]

RECHECK BY:

Grande Center Point Hotel Ploenchit Bangkok

MONTHLY REPORT

SYSTEM & SAFETY

MONTH ๖๕๖๖๖๖ ๖๖

FIRE POTECTION SYSTEM

TIME

Floor	FHC (Corridor)				FHC (Service Lift Area)				Fire Pipe		
	Hose Real	Hose Valve	Fire Extinguisher		Hose Real	Hose Valve	Fire Extinguisher		Fire Test	Flow switch	Supervisory valve
			Weight(Kg)	Gauge			Weight(Kg)	Gauge			
Roof											
31											
30											
29											
28											
27											
26											
25											
23											
22											
21											
20											
19											
18											
17											
16											
15											
12											
11											
10											
9											
8											
7											
6											
5											
3											
F											
M											
L											
P1											
P2											
P3											
P4											
Lift room											
Booster pump room											
Transformer room											
Swimming pool room											
Water pump room											
Generator room											

RECORD BY:.....

RECHECK BY:.....

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH May 2018
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS			WORKING RESULT		
			C	A	R	P	N	UN
1 Month	1	Cleanning Pump Frame & Oil Clean					✓	
	2	Control System					✓	
		Test Control System					✓	
		Fitting All Inside Panel					✓	
		Testing Operation Time Delay					✓	
	3	Check Oil Level						
	4	Check Water Level In Coolant						
	5	Check Condensate Water Of Battery						
3 Month Mar,Jun,Sep,Dec	6	Check Fuel Pipes						
	7	Check Leakage Every Jointes						
	8	Check Exhaust Pipe						
	9	Check Engine Oil						
	10	Check Air Filter						
6 Month Jun,Dec	11	Check Water Color In Coolant						
	12	Adjusting Alignment						
	13	Check/Changed Beltes						
	14	Changed Water In Coolant						
	15	Changed Engine Oil						
	16	Changed Air Filter						
	17	Changed Oil Filter						
	18	Changed Fuel Filter						
	19	Painting Overall						

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE

COMMENT

RECORD BY XXXXXXXXXX

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH Dec 2016

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS						WORKING RESULT	
			C	A	R	P	N	UN		
1 Month	1	Cleanning Pump Frame & Oil Clean								
	2	Control System								
		Test Control System								
		Fitting All Inside Panel								
		Testing Operation Time Delay								
	3	Check Oil Level								
	4	Check Water Level In Coolant								
	5	Check Condensate Water Of Battery								
3 Month Mar,Jun,Sep,Dec	6	Check Fuel Pipes								
	7	Check Leakage Every Jointes								
	8	Check Exhaust Pipe								
	9	Check Engine Oil								
	10	Check Air Filter								
6 Month Jun,Dec	11	Check Water Color In Coolant								
	12	Adjusting Alignment								
	13	Check/Changed Beltes								
	14	Changed Water In Coolant								
	15	Changed Engine Oil								
	16	Changed Air Filter								
	17	Changed Oil Filter								
	18	Changed Fuel Filter								
	19	Painting Overall								

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

COMMENT

RECORD BY 

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH May 2016
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS						WORKING RESULT	
			C	A	R	P	N	UN		
1 Month	1	Cleanning Pump Frame & Oil Clean					✓			
	2	Control System					✓			
		Test Control System					✓			
		Fitting All Inside Panel					✓			
		Testing Operation Time Delay					✓			
	3	Check Oil Level					✓			
	4	Check Water Level In Coolant					✓			
	5	Check Condensate Water Of Battery					✓			
3 Month Mar,Jun,Sep,Dec	6	Check Fuel Pipes					✓			
	7	Check Leakage Every Jointes					✓			
	8	Check Exhaust Pipe					✓			
	9	Check Engine Oil					✓			
	10	Check Air Filter					✓			
6 Month Jun,Dec	11	Check Water Color In Coolant					✓			
	12	Adjusting Alignment								
	13	Check/Changed Beltes								
	14	Changed Water In Coolant								
	15	Changed Engine Oil								
	16	Changed Air Filter								
	17	Changed Oil Filter								
	18	Changed Fuel Filter								
	19	Painting Overall								

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

COMMENT

RECORD BY XXXXXXXXXX

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH May 66
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS					WORKING RESULT	
			C	A	R	P	N	UN	
1 Month	1	Cleanning Pump Frame & Oil Clean							
	2	Control System							
		Test Control System							
		Fitting All Inside Panel							
		Testing Operation Time Delay							
	3	Check Oil Level							
	4	Check Water Level In Coolant							
	5	Check Condensate Water Of Battery							
3 Month Mar,Jun,Sep,Dec	6	Check Fuel Pipes							
	7	Check Leakage Every Jointes							
	8	Check Exhaust Pipe							
	9	Check Engine Oil							
	10	Check Air Filter							
6 Month Jun,Dec	11	Check Water Color In Coolant							
	12	Adjusting Alignment							
	13	Check/Changed Beltes							
	14	Changed Water In Coolant							
	15	Changed Engine Oil							
	16	Changed Air Filter							
	17	Changed Oil Filter							
	18	Changed Fuel Filter							
	19	Painting Overall							

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED

R = REPAIR P = REPLACED

NOTE

COMMENT

RECORD BY XXXXXXXXXX RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH พฤษภาคม ๕๖
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS					WORKING RESULT	
			C	A	R	P	N	UN	
1 Month	1	Cleanning Pump Frame & Oil Clean					/		
	2	Control System					/		
		Test Control System					/		
		Fitting All Inside Panel					/		
		Testing Operation Time Delay					/		
	3	Check Oil Level							
	4	Check Water Level In Coolant							
	5	Check Condensate Water Of Battery							
3 Month Mar,Jun,Sep,Dec	6	Check Fuel Pipes							
	7	Check Leakage Every Jointes							
	8	Check Exhaust Pipe							
	9	Check Engine Oil							
	10	Check Air Filter							
6 Month Jun,Dec	11	Check Water Color In Coolant							
	12	Adjusting Alignment							
	13	Check/Changed Beltes							
	14	Changed Water In Coolant							
	15	Changed Engine Oil							
	16	Changed Air Filter							
	17	Changed Oil Filter							
	18	Changed Fuel Filter							
	19	Painting Overall							

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

COMMENT

RECORD BY 

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
GENERATOR

MONTH June 66
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS			WORKING RESULT		
			C	A	R	P	N	UN
1 Month	1	Cleanning Pump Frame & Oil Clean					/	
	2	Control System					/	
		Test Control System					/	
		Fitting All Inside Panel					/	
		Testing Operation Time Delay					/	
	3	Check Oil Level					/	
	4	Check Water Level In Coolant					/	
	5	Check Condensate Water Of Battery					/	
3 Month	6	Check Fuel Pipes					/	
	7	Check Leakage Every Jointes					/	
	8	Check Exhaust Pipe					/	
	9	Check Engine Oil					/	
	10	Check Air Filter					/	
Mar,Jun,Sep,Dec	11	Check Water Color In Coolant					/	
6 Month	12	Adjusting Alignment					/	
	13	Check/Changed Beltes					/	
	14	Changed Water In Coolant					/	
	15	Changed Engine Oil					/	
	16	Changed Air Filter					/	
	17	Changed Oil Filter					/	
	18	Changed Fuel Filter					/	
	Jun,Dec	19	Painting Overall					/

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

COMMENT

RECORD BY 

RECHECK BY

ภาคผนวก ข-7

เอกสารการตรวจสอบระบบระบายอากาศ



Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH May 11
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS					WORKING RESULT	
			C	A	R	P	N	UN	
1 Month	1	Testing Control System					/		
		Cleanning Overall Inside Panel Control					/		
		Fitting All Inside Panel Control					/		
		Testing Overload					/		
	2	Check Timer Operation							
	3	Check Motor& Blower							
	4	Check Bearing							
	5	Check&Cleaned Frame							
3 Month Mar,Jun,Sep,Dec	6	Check & Fitting Support							
	7	Cleanning Air Grill Return							
	8	Cleanning Relief Damper							
	9	Cleanning Supply Damperes							
	10	Added Grease The Damper Motordrive							
	11	Tighting All Bolt/Nut Motor & Blower							
6 Month Jun,Dec	10	Cleanning Motor & Blower							
	11	Cleanning Inside Hood Duct							
	12	Cleanning & Painting							

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE

.....

.....

.....

COMMENT

.....

.....

.....

RECORD BY 

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH May 2016
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS				WORKING RESULT	
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control					/	
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Check Timer Operation						
	3	Check Motor& Blower						
	4	Check Bearing						
	5	Check&Cleaned Frame						
3 Month Mar,Jun,Sep,Dec	6	Check & Fitting Support						
	7	Cleanning Air Grill Return						
	8	Cleanning Relief Damper						
	9	Cleanning Supply Damperes						
	10	Added Grease The Damper Motordrive						
	11	Tighting All Bolt/Nut Motor & Blower						
6 Month Jun,Dec	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY 

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH *March 2016*
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS			WORKING RESULT		
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control					/	
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Check Timer Operation					/	
	3	Check Motor& Blower					/	
	4	Check Bearing					/	
	5	Check&Cleaned Frame					/	
3 Month Mar,Jun,Sep,Dec	6	Check & Fitting Support					/	
	7	Cleanning Air Grill Return						
	8	Cleanning Relief Damper						
	9	Cleanning Supply Damperes						
6 Month Jun,Dec	10	Added Grease The Damper Motordrive						
	11	Tighting All Bolt/Nut Motor & Blower						
	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE

COMMENT

RECORD BY 

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH NOV 66
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS				WORKING RESULT	
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control					/	
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Check Timer Operation						
	3	Check Motor& Blower						
	4	Check Bearing						
	5	Check&Cleaned Frame						
3 Month Mar,Jun, Sep,Dec	6	Check & Fitting Support						
	7	Cleanning Air Grill Return						
	8	Cleanning Relief Damper						
	9	Cleanning Supply Damperes						
	10	Added Grease The Damper Motordrive						
	11	Tighting All Bolt/Nut Motor & Blower						
6 Month Jun,Dec	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL

UN = UNORMAL

C = CLEANING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY 

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH *Apr*
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS				WORKING RESULT	
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control					/	
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Check Timer Operation						
	3	Check Motor& Blower						
	4	Check Bearing						
	5	Check&Cleaned Frame						
3 Month Mar,Jun,Sep,Dec	6	Check & Fitting Support						
	7	Cleanning Air Grill Return						
	8	Cleanning Relief Damper						
	9	Cleanning Supply Damperes						
	10	Added Grease The Damper Motordrive						
	11	Tighting All Bolt/Nut Motor & Blower						
6 Month Jun,Dec	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE

COMMENT

RECORD BY 

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
SMOKE FAN

MONTH Aug
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS				WORKING RESULT	
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control					/	
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Check Timer Operation					/	
	3	Check Motor& Blower					/	
	4	Check Bearing					/	
	5	Check&Cleaned Frame					/	
	6	Check & Fitting Support					/	
3 Month Mar,Jun,Sep,Dec	7	Cleanning Air Grill Return					/	
	8	Cleanning Relief Damper					/	
	9	Cleanning Supply Damperes					/	
	10	Added Grease The Damper Motordrive					/	
	11	Tighting All Bolt/Nut Motor & Blower					/	
6 Month Jun,Dec	10	Cleanning Motor & Blower					/	
	11	Cleanning Inside Hood Duct					/	
	12	Cleanning & Painting					/	

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE

COMMENT

RECORD BY [REDACTED] RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
PRESSURIZE FAN

MONTH 15/09/2016
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS				WORKING RESULT	
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control	/					
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Check Timer Operation					/	
	3	Check Motor& Blower					/	
	4	Check Bearing					/	
	5	Check&Cleaned Frame					/	
3 Month Mar,Jun,Sept,Dec	6	Check & Fitting Support					/	
	7	Cleanning Air Grill Return						
	8	Cleanning Relief Damper						
	9	Cleanning Supply Damperes						
	10	Added Grease The Damper Motordrive						
	11	Tighting All Bolt/Nut Motor & Blower						
6 Month Jun,Dec	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL UN = UNORMAL C = CLEANING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
PRESSURIZE FAN

MONTH ๓๐ มกราคม ๖๖
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS						WORKING RESULT
			C	A	R	P	N	UN	
1 Month	1	Testing Control System					/		
		Cleanning Overall Inside Panel Control	/						
		Fitting All Inside Panel Control			/				
		Testing Overload					/		
	2	Check Timer Operation					/		
	3	Check Motor& Blower					/		
	4	Check Bearing					/		
	5	Check&Cleaned Frame					/		
	6	Check & Fitting Support					/		
3 Month Mar,Jun,Sep,Dec	7	Cleanning Air Grill Return							
	8	Cleanning Relief Damper							
	9	Cleanning Supply Damperes							
	10	Added Grease The Damper Motordrive							
	11	Tighting All Bolt/Nut Motor & Blower							
6 Month Jun,Dec	10	Cleanning Motor & Blower							
	11	Cleanning Inside Hood Duct							
	12	Cleanning & Painting							

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE

.....

.....

.....

COMMENT

.....

.....

.....

RECORD BY
RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
PRESSURIZE FAN


MONTH March
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS					WORKING RESULT	
			C	A	R	P	N	UN	
1 Month	1	Testing Control System					/		
		Cleanning Overall Inside Panel Control	/						
		Fitting All Inside Panel Control					/		
		Testing Overload					/		
	2	Check Timer Operation					/		
	3	Check Motor& Blower					/		
	4	Check Bearing					/		
	5	Check&Cleaned Frame					/		
3 Month Mar,Jun,Sep,Dec	6	Check & Fitting Support					/		
	7	Cleanning Air Grill Return					/		
	8	Cleanning Relief Damper					/		
	9	Cleanning Supply Damperes					/		
6 Month Jun,Dec	10	Added Grease The Damper Motordrive					/		
	11	Tighting All Bolt/Nut Motor & Blower							
	10	Cleanning Motor & Blower							
	11	Cleanning Inside Hood Duct							
	12	Cleanning & Painting							

N = NORMAL UN = UNORMAL C = CLEANING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE

COMMENT

RECORD BY .. 

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
PRESSURIZE FAN

MONTH april 66
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS				WORKING RESULT	
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control					/	
		Fitting All Inside Panel Control		/				
		Testing Overload	/					
	2	Check Timer Operation					/	
	3	Check Motor& Blower					/	
	4	Check Bearing					/	
	5	Check&Cleaned Frame					/	
3 Month Mar,Jun,Sep,Dec	6	Check & Fitting Support					/	
	7	Cleanning Air Grill Return						
	8	Cleanning Relief Damper						
	9	Cleanning Supply Damperes						
	10	Added Grease The Damper Motordrive						
	11	Tighting All Bolt/Nut Motor & Blower						
6 Month Jun,Dec	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL UN = UNORMAL C = CLEANING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY 

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY
PRESSURIZE FAN

MONTH 66
TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS			WORKING RESULT		
			C	A	R	P	N	UN
1 Month	1	Testing Control System					✓	
		Cleanning Overall Inside Panel Control					✓	
		Fitting All Inside Panel Control					✓	
		Testing Overload	✓					
	2	Check Timer Operation					✓	
	3	Check Motor& Blower					✓	
	4	Check Bearing					✓	
	5	Check&Cleaned Frame					✓	
3 Month Mar,Jun,Sep,Dec	6	Check & Fitting Support					✓	
	7	Cleanning Air Grill Return						
	8	Cleanning Relief Damper						
	9	Cleanning Supply Damperes						
6 Month Jun,Dec	10	Added Grease The Damper Motordrive						
	11	Tighting All Bolt/Nut Motor & Blower						
	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL UN = UNORMAL C = CLEANNING A = ADJUST&ADDED
R = REPAIR P = REPLACED

NOTE

COMMENT

RECORD BY
RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

PRESSURIZE FAN

MONTH *January 66*

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS				WORKING RESULT	
			C	A	R	P	N	UN
1 Month	1	Testing Control System					<i>/</i>	
		Cleanning Overall Inside Panel Control					<i>/</i>	
		Fitting All Inside Panel Control	<i>/</i>					
		Testing Overload					<i>/</i>	
	2	Check Timer Operation					<i>/</i>	
	3	Check Motor& Blower					<i>/</i>	
	4	Check Bearing					<i>/</i>	
	5	Check&Cleaned Frame					<i>/</i>	
3 Month Mar,Jun,Sep,Dec	6	Check & Fitting Support					<i>/</i>	
	7	Cleanning Air Grill Return					<i>/</i>	
	8	Cleanning Relief Damper					<i>/</i>	
	9	Cleanning Supply Damperes					<i>/</i>	
	10	Added Grease The Damper Motordrive					<i>/</i>	
	11	Tighting All Bolt/Nut Motor & Blower					<i>/</i>	
6 Month Jun,Dec	10	Cleanning Motor & Blower	<i>/</i>				<i>/</i>	
	11	Cleanning Inside Hood Duct			<i>/</i>		<i>/</i>	
	12	Cleanning & Painting					<i>/</i>	

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

COMMENT

RECORD BY *[Signature]* ..

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

MAKE UP MOTOR FAN NO.....

MONTH มกราคม 66

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS					WORKING RESULT	
			C	A	R	P	N	UN	
1 Month	1	Testing Control System					✓		
		Cleanning Overall Inside Panel Control	✓						
		Fitting All Inside Panel Control		✓			✓		
		Testing Overload					✓		
	2	Added Grease					✓		
	3	Check Motor& Blower					✓		
	4	Check Belt					✓		
	5	Check Bearing					✓		
	6	Check&Cleaned Frame					✓		
3 Month Mar,Jun,Sep,Dec	7	Tighting All Bolt/Nut Motor & Blower							
	8	Check & Fitting Support							
	9	Cleanning Air Grill Return & Supply							
6 Month Jun,Dec	10	Cleanning Motor & Blower							
	11	Cleanning Inside Hood Duct							
	12	Cleanning & Painting							

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY  RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

MONTH *ธันวาคม 66*

MAKE UP MOTOR FAN NO.....

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS						WORKING RESULT	
			C	A	R	P	N	UN		
1 Month	1	Testing Control System					✓			
		Cleanning Overall Inside Panel Control	✓				✓			
		Fitting All Inside Panel Control		✓			✓			
		Testing Overload					✓			
	2	Added Grease					✓			
	3	Check Motor& Blower					✓			
	4	Check Belt					✓			
	5	Check Bearing					✓			
	6	Check&Cleaned Frame					✓			
3 Month Mar,Jun,Sep,Dec	7	Tighting All Bolt/Nut Motor & Blower								
	8	Check & Fitting Support								
	9	Cleanning Air Grill Return & Supply								
6 Month Jun,Dec	10	Cleanning Motor & Blower								
	11	Cleanning Inside Hood Duct								
	12	Cleanning & Painting								

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY *[Signature]*

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

MONTH January 66

MAKE UP MOTOR FAN NO.....

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS			WORKING RESULT		
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control					/	
		Fitting All Inside Panel Control					/	
		Testing Overload	/					
	2	Added Grease					/	
	3	Check Motor& Blower					/	
	4	Check Belt					/	
	5	Check Bearing					/	
3 Month Mar,Jun,Sep,Dec	6	Check&Cleaned Frame					/	
	7	Tighting All Bolt/Nut Motor & Blower					/	
	8	Check & Fitting Support					/	
6 Month Jun,Dec	9	Cleanning Air Grill Return & Supply					/	
	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL

UN = UNORMAL

C = CLEANING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY [REDACTED] RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

MAKE UP MOTOR FAN NO.....

MONTH *April 66*

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS						WORKING RESULT
			C	A	R	P	N	UN	
1 Month	1	Testing Control System					/		
		Cleanning Overall Inside Panel Control					/		
		Fitting All Inside Panel Control					/		
		Testing Overload	/				/		
	2	Added Grease					/		
	3	Check Motor& Blower					/		
	4	Check Belt					/		
	5	Check Bearing					/		
	6	Check&Cleaned Frame					/		
3 Month Mar,Jun,Sep,Dec	7	Tighting All Bolt/Nut Motor & Blower							
	8	Check & Fitting Support							
	9	Cleanning Air Grill Return & Supply							
6 Month Jun,Dec	10	Cleanning Motor & Blower							
	11	Cleanning Inside Hood Duct							
	12	Cleanning & Painting							

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY *[Signature]*

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

MAKE UP MOTOR FAN NO.....

MONTH *พฤษภาคม 66*

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS					WORKING RESULT
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control	/				/	
		Fitting All Inside Panel Control	/				/	
		Testing Overload					/	
	2	Added Grease					/	
	3	Check Motor& Blower					/	
	4	Check Belt					/	
	5	Check Bearing					/	
	6	Check&Cleaned Frame					/	
3 Month Mar,Jun,Sep,Dec	7	Tighting All Bolt/Nut Motor & Blower						
	8	Check & Fitting Support						
	9	Cleanning Air Grill Return & Supply						
6 Month Jun,Dec	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY 

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

MAKE UP MOTOR FAN NO.....

MONTH *June 66*

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS				WORKING RESULT	
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control					/	
		Fitting All Inside Panel Control	/				/	
		Testing Overload		/			/	
	2	Added Grease		/			/	
	3	Check Motor& Blower					/	
	4	Check Belt					/	
	5	Check Bearing					/	
	6	Check&Cleaned Frame					/	
3 Month Mar,Jun,Sep,Dec	7	Tighting All Bolt/Nut Motor & Blower					/	
	8	Check & Fitting Support					/	
	9	Cleanning Air Grill Return & Supply					/	
6 Month Jun,Dec	10	Cleanning Motor & Blower					/	
	11	Cleanning Inside Hood Duct					/	
	12	Cleanning & Painting					/	

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY  RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

EXHAUST MOTOR FAN NO.....

MONTH

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS			WORKING RESULT		
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control	/					
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Added Grease					/	
	3	Check Motor& Blower					/	
	4	Check Belt					/	
	5	Check Bearing					/	
	6	Check&Cleaned Frame					/	
3 Month Mar,Jun,Sep,Dec	7	Tighting All Bolt/Nut Motor & Blower						
	8	Check & Fitting Support						
	9	Cleanning Air Grill Return & Supply						
6 Month	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

.....

RECORD BY

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

EXHAUST MOTOR FAN NO.....

MONTH *February 66*

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS			WORKING RESULT		
			C	A	R	P	N	UN
1 Month	1	Testing Control System	/				/	
		Cleanning Overall Inside Panel Control	/					
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Added Grease					/	
	3	Check Motor& Blower					/	
	4	Check Belt					/	
	5	Check Bearing					/	
	6	Check&Cleaned Frame					/	
3 Month Mar,Jun,Sep,Dec	7	Tighting All Bolt/Nut Motor & Blower						
	8	Check & Fitting Support						
	9	Cleanning Air Grill Return & Supply						
6 Month	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL

UN = UNORMAL

C = CLEANING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY *[Signature]*

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

EXHAUST MOTOR FAN NO.....

MONTH *Therera 66*

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS			WORKING RESULT		
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control	/					
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Added Grease					/	
	3	Check Motor& Blower					/	
	4	Check Belt					/	
	5	Check Bearing					/	
	6	Check&Cleaned Frame					/	
3 Month Mar,Jun,Sep,Dec	7	Tighting All Bolt/Nut Motor & Blower					/	
	8	Check & Fitting Support					/	
	9	Cleanning Air Grill Return & Supply	/					
6 Month	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY 

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

EXHAUST MOTOR FAN NO.....

MONTH May 66

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS			WORKING RESULT		
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control	/					
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Added Grease					/	
	3	Check Motor& Blower					/	
	4	Check Belt					/	
	5	Check Bearing					/	
	6	Check&Cleaned Frame					/	
3 Month Mar,Jun,Sep,Dec	7	Tighting All Bolt/Nut Motor & Blower						
	8	Check & Fitting Support						
	9	Cleanning Air Grill Return & Supply						
6 Month	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

.....

RECORD BY

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

EXHAUST MOTOR FAN NO.....

MONTH *September 66*

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS			WORKING RESULT		
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control	/					
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Added Grease					/	
	3	Check Motor& Blower					/	
	4	Check Belt					/	
	5	Check Bearing					/	
	6	Check&Cleaned Frame					/	
3 Month Mar,Jun,Sep,Dec	7	Tighting All Bolt/Nut Motor & Blower						
	8	Check & Fitting Support						
	9	Cleanning Air Grill Return & Supply						
6 Month	10	Cleanning Motor & Blower						
	11	Cleanning Inside Hood Duct						
	12	Cleanning & Painting						

N = NORMAL

UN = UNORMAL

C = CLEANNING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE

.....

.....

COMMENT

.....

.....

RECORD BY *[Signature]*

RECHECK BY

Grande Center Point Hotel Ploenchit Bangkok

MAINTENANCE REPORT

SYSTEM & SAFETY

EXHAUST MOTOR FAN NO.....

MONTH *February .66*

TIME

TIME	ITEM	DESCRIPTION MAINTENANCE	WORKING REMARKS			WORKING RESULT		
			C	A	R	P	N	UN
1 Month	1	Testing Control System					/	
		Cleanning Overall Inside Panel Control	/					
		Fitting All Inside Panel Control					/	
		Testing Overload					/	
	2	Added Grease					/	
	3	Check Motor& Blower					/	
	4	Check Belt					/	
	5	Check Bearing					/	
	6	Check&Cleaned Frame					/	
3 Month	7	Tighting All Bolt/Nut Motor & Blower					/	
	8	Check & Fitting Support					/	
Mar,Jun,Sep,Dec	9	Cleanning Air Grill Return & Supply	/					
6 Month	10	Cleanning Motor & Blower	/					
	11	Cleanning Inside Hood Duct	/					
	12	Cleanning & Painting	/					

N = NORMAL

UN = UNORMAL

C = CLEANING

A = ADJUST&ADDED

R = REPAIR

P = REPLACED

NOTE


.....

.....

COMMENT

.....

.....

RECORD BY 

RECHECK BY

ภาคผนวก ข-8

เอกสารแนวทางการฝึกซ้อมดับเพลิงประจำปีพ.ศ.2566



แนวทางการฝึกซ้อมดับเพลิงและซ้อมหนีไฟ

การจำลองเหตุการณ์เหตุเพลิงไหม้



ช่วงเวลา 1 นาทีครึ่ง
สามารถรับรู้จากได้กลิ่นและมองเห็น

เวลา 1 นาทีครึ่ง
Smoke Detector เริ่มตรวจจับควันได้



เดินทางถึงที่เกิดเหตุ ใช้เวลา 1 นาที
คว้นเริ่มจะเป็นอุปสรรคในการดับเพลิง
การดับเพลิงอาจต้องใช้สายฉีดน้ำ เสียหายมากขึ้น

เวลา 3 นาทีครึ่ง
Heat Detector เริ่มตรวจจับความร้อนได้
คว้นและความร้อนเป็นอุปสรรคต่อการดับเพลิงมาก



เดินทาง 2.10 นาที
Sprinkler ทำงาน อุณหภูมิสูง 100 องศา
คว้นเยอะ การดับเพลิงต้องใช้สายฉีดน้ำ
เกิดความเสียหายมากกว่า

เดินทาง 3 นาที
อุณหภูมิสูง 600 องศา ไม่สามารถเข้าใกล้ที่เกิดเหตุได้
การดับเพลิงยากขึ้น ถ้าไม่มี ชุดพจญเพลิง และ
หน้ากากป้องกันคว้นไฟ

แนวทางการฝึกซ้อมดับเพลิงและซ้อมหนีไฟ



ขั้นตอนการฝึกซ้อมดับเพลิงและซ้อมหนีไฟ

1. สมมติเหตุการณ์เพลิงไหม้ ห้องพัก No..... (บริเวณที่เสี่ยงต่อการเกิดอัคคีภัย)
2. กรณี **Smoke Detector** จับสัญญาณได้ หรือ **ผู้พบเหตุ** กด Pulldown แจ้งเหตุสัญญาณแจ้งที่ห้องควบคุม (Control Room)
3. เจ้าหน้าที่ **สื่อสารแจ้งผู้เกี่ยวข้อง** ทีม A, ทีม B และแผนกดับเพลิง เพื่อไปที่เกิดเหตุให้เร็วที่สุด
ทีม **A** เดินทางโดยลิฟต์โดยสาร พร้อมถังดับเพลิง
ทีม **B** เดินทางโดยลิฟต์ดับเพลิง พร้อมถังดับเพลิง-อุปกรณ์ดับเพลิง-กุญแจที่จำเป็น
4. เจ้าหน้าที่สื่อสารแจ้ง **พนักงานแผนกดับเพลิง** เข้าตรวจสอบและดับเพลิงขั้นต้น **สำคัญมาก** เพราะสามารถเข้าถึงที่เกิดเหตุได้เร็วที่สุด และมีกุญแจเข้าห้องได้
5. เจ้าหน้าที่ต้องเดินทางถึงที่เกิดเหตุ ภายใน เวลา **2 – 3 นาที** (ก่อนสปริงเกอร์แตก) ถ้ามาถึงภายในเวลาที่กำหนด จะสามารถดับเพลิงขั้นต้นได้ง่าย โดยใช้ถังดับเพลิง
6. เจ้าหน้าที่มาถึงที่เกิดเหตุ ทำการดับเพลิงขั้นต้น – ขั้นรุนแรง ตามระยะเวลาที่เข้าถึง
7. เจ้าหน้าที่พบว่าเพลิงขั้นรุนแรง ไม่สามารถควบคุมเพลิงได้โดยง่าย ให้แจ้ง GM เพื่อสั่งแผนอพยพหนีไฟ แจ้งให้สัญญาณ General Alarm พร้อมโทรแจ้ง **199**
8. พนักงานทุกแผนกเมื่อได้ยินสัญญาณเตือนภัยดัง ปฏิบัติตามแผนอพยพ มายังจุดรวมพลให้เร็วที่สุด เช็ดยอด หากมีผู้ติดค้างในอาคารให้แจ้ง GM เพื่อแจ้งพนักงานดับเพลิง เข้าช่วยเหลือต่อไป
9. พนักงานรักษาความปลอดภัยควบคุมพื้นที่ จัดจราจรด้านหน้าอาคาร ควบคุมเส้นทางเข้าออกภายในอาคาร ไม่อนุญาตให้บุคคลภายนอกที่ไม่เกี่ยวข้องเข้าภายในอาคาร เด็ดขาด
10. หากควบคุมเพลิงได้ ให้เจ้าหน้าที่ ลงมาแจ้ง GM ที่จุดรวมพล
11. เจ้าหน้าที่เตรียมข้อมูลให้เจ้าหน้าที่ดับเพลิง และพาไปที่เกิดเหตุ (ถ้าไม่สามารถดับเพลิงได้)
12. สรุปประเมินผลการฝึกอบรม