



Accreditation No. 1031/47

Analysis / Test Report

Client : Krabinakharin Co., Ltd.
1, Pisanpop Rd., Pak-Nam, Mueang Krabi, Krabi Thailand 81000
P/O : 5PO6602-0006
Project Name : โรงพยาบาลกระบี่นครินทร์ อินเตอร์เนชั่นแนล
Project Location : Water Testing

Lot ID: 2322318

Date Received : May 24, 2023

Date Reported : Jun 12, 2023

Report Number : 2579479-1

Page 1 of 3

Sample Number 2322318-1
Sampled Date May 23, 2023 11:00 AM
Sample Description Consumption Water
Location Cooling Tower
Date Analysis Commenced May 25, 2023
Condition of Sample Contained in two plastic bottles, sample containers comply to pretreatment - preservation standards (APHA, USEPA)

Analyte	Unit	LOD	LOQ (LOR)	Result	Method	Testing Location
Microbiological Testing						
<i>Legionella spp.</i>	CFU/L	-	-	<1	ISO 11731 (2017)	Bangkok

Note : Microbiological Testing Result <1 mean Bacteria not found in agar plate.

Remark :

- LOD : Limit of Detection
- "<" : Lower than LOQ (Limit of Quantitation) / LOR (Limit of Reporting)
- Analyte(s) marked * is/are not included in scope of Accreditation ISO/IEC 17025.
- The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025.

The above results are valid only for the analyzed/tested sample(s) as indicated in this report. No part of this report or certificate may be reproduced in any form without written consent from the Laboratory. ALS Laboratory Group (Thailand) strongly recommends that this report is not reproduced except in full.

Approved by

Suwannee Chuamkeaw
Section Head

ADDRESS 104 Phatthanakan 40, Phatthanakan Rd., Khwaeng Phatthanakan, Khet Suan Luang, Bangkok 10250 Thailand | PHONE +66 0 2760 3000 | FAX +66 0 2760 3197
ALS LABORATORY GROUP (THAILAND) CO., LTD. An ALS Limited Company

Life Sciences

www.alsglobal.com

RIGHT SOLUTIONS RIGHT PARTNER



Accreditation No. 1031/47

Analysis / Test Report

Client : Krabinakharin Co., Ltd.
1, Pisanpop Rd., Pak-Nam, Mueang Krabi, Krabi Thailand 81000
P/O : 5PO6602-0006
Project Name : โรงพยาบาลกระบี่นครินทร์ อินเตอร์เนชั่นแนล
Project Location : Water Testing

Lot ID: 2322318

Date Received : May 24, 2023

Date Reported : Jun 12, 2023

Report Number : 2579479-1

Page 2 of 3

Sample Number 2322318-2
Sampled Date May 23, 2023 11:20 AM
Sample Description Consumption Water
Location Chiller
Date Analysis Commenced May 25, 2023
Condition of Sample Contained in two plastic bottles, sample containers comply to pretreatment - preservation standards (APHA, USEPA)

Analyte	Unit	LOD	LOQ (LOR)	Result	Method	Testing Location
Microbiological Testing						
<i>Legionella spp.</i>	CFU/L	-	-	<1	ISO 11731 (2017)	Bangkok

Note : Microbiological Testing Result <1 mean Bacteria not found in agar plate.

Remark :

- LOD : Limit of Detection
- "<" : Lower than LOQ (Limit of Quantitation) / LOR (Limit of Reporting)
- Analyte(s) marked * is/are not included in scope of Accreditation ISO/IEC 17025.
- The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025.

The above results are valid only for the analyzed/tested sample(s) as indicated in this report. No part of this report or certificate may be reproduced in any form without written consent from the Laboratory. ALS Laboratory Group (Thailand) strongly recommends that this report is not reproduced except in full.

Approved by

Suwannee Chuamkeaw
Section Head

ADDRESS 104 Phatthanakan 40, Phatthanakan Rd., Khwaeng Phatthanakan, Khet Suan Luang, Bangkok 10250 Thailand | PHONE +66 0 2760 3000 | FAX +66 0 2760 3197
ALS LABORATORY GROUP (THAILAND) CO., LTD. An ALS Limited Company

Life Sciences

www.alsglobal.com

RIGHT SOLUTIONS RIGHT PARTNER



Accreditation No. 1031/47

Analysis / Test Report

Client : Krabinakharin Co., Ltd.
1, Pisanpop Rd., Pak-Nam, Mueang Krabi, Krabi Thailand 81000
P/O : 5PO6602-0006
Project Name : โรงพยาบาลกระบี่นครินทร์ อินเตอร์เนชั่นแนล
Project Location : Water Testing

Lot ID: 2322318

Date Received : May 24, 2023

Date Reported : Jun 12, 2023

Report Number : 2579479-1

Page 3 of 3

Sample Number 2322318-3
Sampled Date May 23, 2023 11:30 AM
Sample Description Consumption Water
Location จุดใกล้สุดของระบบ Cooling Tower
Date Analysis Commenced May 25, 2023
Condition of Sample Contained in one plastic bottle (client container), refrigerated

Analyte	Unit	LOD	LOQ (LOR)	Result	Method	Testing Location
Microbiological Testing						
<i>Legionella spp.</i>	CFU/L	-	-	<1	ISO 11731 (2017)	Bangkok

Note : Microbiological Testing Result <1 mean Bacteria not found in agar plate.

Remark :

- LOD : Limit of Detection
- "<" : Lower than LOQ (Limit of Quantitation) / LOR (Limit of Reporting)
- Analyte(s) marked * is/are not included in scope of Accreditation ISO/IEC 17025.
- The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025.

The above results are valid only for the analyzed/tested sample(s) as indicated in this report. No part of this report or certificate may be reproduced in any form without written consent from the Laboratory. ALS Laboratory Group (Thailand) strongly recommends that this report is not reproduced except in full.

Approved by

Suwannee Chuamkeaw
Section Head

ADDRESS 104 Phatthanakan 40, Phatthanakan Rd., Khwaeng Phatthanakan, Khet Suan Luang, Bangkok 10250 Thailand | PHONE +66 0 2760 3000 | FAX +66 0 2760 3197
ALS LABORATORY GROUP (THAILAND) CO., LTD. An ALS Limited Company

Life Sciences

www.alsglobal.com

RIGHT SOLUTIONS RIGHT PARTNER