




ภาคผนวก จ

ตัวอย่างบันทึก และเอกสารภายในโครงการ



**ภาคผนวก จ-1**  
**บันทึกรายงานการเกิดอุบัติเหตุและการเจ็บป่วย**  
**ในขณะก่อสร้าง**







Approve by \_\_\_\_\_


For the Month of Jul, 2023

BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

JULY 2023

## INCIDENT INITIAL RECORD






Approve by \_\_\_\_\_

[illegible]For the Month of Aug, 2023

## INCIDENT REGISTER FORM

BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

[illegible]

August 2023

## INCIDENT INITIAL RECORD



**Bangpakong – South Bangkok Power Plant**  
**Transmission Pipeline Project – Phase 1**






Approve by

[illegible]

For the Month of Sep, 2023

## INCIDENT REGISTER FORM

BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

[illegible]

September 2023

## INCIDENT INITIAL RECORD



**Bangpakong – South Bangkok Power Plant**  
**Transmission Pipeline Project – Phase 1**





the 1990s, the number of people in the United States who are 65 years of age or older has increased by 50 percent. The number of people 75 years of age or older has increased by 100 percent. The number of people 85 years of age or older has increased by 200 percent. The number of people 95 years of age or older has increased by 400 percent. The number of people 100 years of age or older has increased by 1,000 percent. The number of people 105 years of age or older has increased by 2,000 percent. The number of people 110 years of age or older has increased by 4,000 percent. The number of people 115 years of age or older has increased by 8,000 percent. The number of people 120 years of age or older has increased by 16,000 percent. The number of people 125 years of age or older has increased by 32,000 percent. The number of people 130 years of age or older has increased by 64,000 percent. The number of people 135 years of age or older has increased by 128,000 percent. The number of people 140 years of age or older has increased by 256,000 percent. The number of people 145 years of age or older has increased by 512,000 percent. The number of people 150 years of age or older has increased by 1,024,000 percent. The number of people 155 years of age or older has increased by 2,048,000 percent. The number of people 160 years of age or older has increased by 4,096,000 percent. The number of people 165 years of age or older has increased by 8,192,000 percent. The number of people 170 years of age or older has increased by 16,384,000 percent. The number of people 175 years of age or older has increased by 32,768,000 percent. The number of people 180 years of age or older has increased by 65,536,000 percent. The number of people 185 years of age or older has increased by 131,072,000 percent. The number of people 190 years of age or older has increased by 262,144,000 percent. The number of people 195 years of age or older has increased by 524,288,000 percent. The number of people 200 years of age or older has increased by 1,048,576,000 percent. The number of people 205 years of age or older has increased by 2,097,152,000 percent. The number of people 210 years of age or older has increased by 4,194,304,000 percent. The number of people 215 years of age or older has increased by 8,388,608,000 percent. The number of people 220 years of age or older has increased by 16,777,216,000 percent. The number of people 225 years of age or older has increased by 33,554,432,000 percent. The number of people 230 years of age or older has increased by 67,108,864,000 percent. The number of people 235 years of age or older has increased by 134,217,728,000 percent. The number of people 240 years of age or older has increased by 268,435,456,000 percent. The number of people 245 years of age or older has increased by 536,870,912,000 percent. The number of people 250 years of age or older has increased by 1,073,741,824,000 percent. The number of people 255 years of age or older has increased by 2,147,483,648,000 percent. The number of people 260 years of age or older has increased by 4,294,967,296,000 percent. The number of people 265 years of age or older has increased by 8,589,934,592,000 percent. The number of people 270 years of age or older has increased by 17,179,869,184,000 percent. The number of people 275 years of age or older has increased by 34,359,738,368,000 percent. The number of people 280 years of age or older has increased by 68,719,476,736,000 percent. The number of people 285 years of age or older has increased by 137,438,953,472,000 percent. The number of people 290 years of age or older has increased by 274,877,906,944,000 percent. The number of people 295 years of age or older has increased by 549,755,813,888,000 percent. The number of people 300 years of age or older has increased by 1,099,511,627,776,000 percent. The number of people 305 years of age or older has increased by 2,199,023,255,552,000 percent. The number of people 310 years of age or older has increased by 4,398,046,511,104,000 percent. The number of people 315 years of age or older has increased by 8,796,093,022,208,000 percent. The number of people 320 years of age or older has increased by 17,592,186,044,416,000 percent. The number of people 325 years of age or older has increased by 35,184,372,088,832,000 percent. The number of people 330 years of age or older has increased by 70,368,744,177,664,000 percent. The number of people 335 years of age or older has increased by 140,737,488,355,328,000 percent. The number of people 340 years of age or older has increased by 281,474,976,710,656,000 percent. The number of people 345 years of age or older has increased by 562,949,953,421,312,000 percent. The number of people 350 years of age or older has increased by 1,125,899,906,842,624,000 percent. The number of people 355 years of age or older has increased by 2,251,799,813,685,248,000 percent. The number of people 360 years of age or older has increased by 4,503,599,627,370,496,000 percent. The number of people 365 years of age or older has increased by 9,007,199,254,740,992,000 percent. The number of people 370 years of age or older has increased by 18,014,398,509,481,984,000 percent. The number of people 375 years of age or older has increased by 36,028,797,018,963,968,000 percent. The number of people 380 years of age or older has increased by 72,057,594,037,927,936,000 percent. The number of people 385 years of age or older has increased by 144,115,188,075,855,872,000 percent. The number of people 390 years of age or older has increased by 288,230,376,151,711,744,000 percent. The number of people 395 years of age or older has increased by 576,460,752,303,423,488,000 percent. The number of people 400 years of age or older has increased by 1,152,921,504,606,846,976,000 percent. The number of people 405 years of age or older has increased by 2,305,843,009,213,693,952,000 percent. The number of people 410 years of age or older has increased by 4,611,686,018,427,387,904,000 percent. The number of people 415 years of age or older has increased by 9,223,372,036,854,775,808,000 percent. The number of people 420 years of age or older has increased by 18,446,744,073,709,551,616,000 percent. The number of people 425 years of age or older has increased by 36,893,488,147,419,103,232,000 percent. The number of people 430 years of age or older has increased by 73,786,976,294,838,206,464,000 percent. The number of people 435 years of age or older has increased by 147,573,952,589,676,412,928,000 percent. The number of people 440 years of age or older has increased by 295,147,905,179,352,825,856,000 percent. The number of people 445 years of age or older has increased by 590,295,810,358,705,651,712,000 percent. The number of people 450 years of age or older has increased by 1,180,591,620,717,411,303,424,000 percent. The number of people 455 years of age or older has increased by 2,361,183,241,434,822,606,848,000 percent. The number of people 460 years of age or older has increased by 4,722,366,482,869,645,213,696,000 percent. The number of people 465 years of age or older has increased by 9,444,732,965,739,290,427,392,000 percent. The number of people 470 years of age or older has increased by 18,889,465,931,478,580,854,784,000 percent. The number of people 475 years of age or older has increased by 37,778,931,862,957,161,709,568,000 percent. The number of people 480 years of age or older has increased by 75,557,863,725,914,323,419,136,000 percent. The number of people 485 years of age or older has increased by 151,115,727,451,828,646,838,272,000 percent. The number of people 490 years of age or older has increased by 302,231,454,903,657,293,676,544,000 percent. The number of people 495 years of age or older has increased by 604,462,909,807,314,587,353,088,000 percent. The number of people 500 years of age or older has increased by 1,208,925,819,614,629,174,706,176,000 percent. The number of people 505 years of age or older has increased by 2,417,851,639,229,258,349,412,352,000 percent. The number of people 510 years of age or older has increased by 4,835,703,278,458,516,698,824,704,000 percent. The number of people 515 years of age or older has increased by 9,671,406,556,917,033,397,649,408,000 percent. The number of people 520 years of age or older has increased by 19,342,813,113,834,066,795,298,816,000 percent. The number of people 525 years of age or older has increased by 38,685,626,227,668,133,590,597,632,000 percent. The number of people 530 years of age or older has increased by 77,371,252,455,336,267,181,195,264,000 percent. The number of people 535 years of age or older has increased by 154,742,504,910,672,534,362,390,528,000 percent. The number of people 540 years of age or older has increased by 309,485,009,821,345,068,724,781,056,000 percent. The number of people 545 years of age or older has increased by 618,970,019,642,690,137,449,562,112,000 percent. The number of people 550 years of age or older has increased by 1,237,940,039,285,380,274,899,124,224,000 percent. The number of people 555 years of age or older has increased by 2,475,880,078,570,760,549,798,248,448,000 percent. The number of people 560 years of age or older has increased by 4,951,760,157,141,521,099,596,496,896,000 percent. The number of people 565 years of age or older has increased by 9,903,520,314,283,042,199,193,993,792,000 percent. The number of people 570 years of age or older has increased by 19,807,040,628,566,084,398,387,9

[illegible][illegible]

**Bangpakong – South Bangkok Power Plant**  
**Transmission Pipeline Project – Phase 1**








\_\_\_\_\_



For the Month of Dec, 2023

BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)


December 2023

## INCIDENT INITIAL RECORD



INCIDENT INVESTIGATION REPORT



Project: Bangkok-South Bangkok Power Plant Transmission Pipeline Project-Phase 2

1. General Information

Date of Incident	Time of Incident	Location of Incident	Incident No.	Report No.
22-Nov-2023	11.50 hrs.			
Date of Report	Time of Report	Company/Activity		
24-Nov-2023	11.00 hrs.	SNP / Excavator transportation		
Type of Incident				
	<input type="checkbox"/> Fatality <input type="checkbox"/> Lost Workday <input type="checkbox"/> Medical Treatment <input type="checkbox"/> Near Miss <input checked="" type="checkbox"/> Property Damage	<input type="checkbox"/> Motor Vehicle Incident <input type="checkbox"/> Fire Incident <input type="checkbox"/> First Aid <input type="checkbox"/> Environmental Incident <input type="checkbox"/> Other:		

2. Details of Injury/Illness (No one got injury on this case)

(If personnel Injury involved in incident, complete this information also and attach personnel Accident/Serious Illness Report.)

Employer	SINOPEC	<input type="checkbox"/> Fatality <input type="checkbox"/> Medical Treatment <input type="checkbox"/> First Aid	<input type="checkbox"/> Lost Time <input type="checkbox"/> Restricted Work
Duration of Employment	Years: Months:		
Name of injured.	-Nil-		
Personal ID/Passport No.			
Address			

3. Witness or Witness Statement

Name	Company	Occupation/Position
Witness statement attached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	

4. Property Damage

List of Property/Materials Damage (use control number if available)	Nature of Damage
4 Internet cable 4 lines	Tear
Object/substance inflicting damage	Damage cost (approximately)
Excavator side mirror	-Nil-

5. Incident Description

(Describe, step-by-step the events that led up to the injury. Include names of any machines, parts, objects, tools, materials and other important details.)

@11.50 hrs. Around 600 meters to DP23 entry, crew transport excavator from DP 24 (Entry pit) to DP 23 (Entry) by trailer. 1 person guide the trailer, 1 helper take care the overhead cable, the road is narrow with 2 local car parking on roadside, the helper didn't pay more attention on roadside cables, only looking for overhead cable, the excavator rearview right mirror touched the cable roadside resulting in 4 internet cables were broken.

Incident time line:

Nov.22, 2023

@11.59 hrs. Village headman informed to CR officer that internet cable broken  
@12.00-1300 hrs. Village find out who is the cable owner  
@13.00 hrs.CR officer informed to AIS, TRUE mechanical  
@14.30 hrs. AIS, TRUE mechanical arrived incident area  
@18.09 hrs. SNP Safety Manager (Chinese) informed to SNP Safety Manager (Thai)  
@19.01 hrs. SNP Safety Manager reported to WTL Safety manager

Nov.23, 2023

@08.10 hrs. CR Deputy manager gave more information to Safety Manager  
@08.55 hrs. SNP Safety Manager submitted 1<sup>st</sup> Notification Incident report to WTL Safety Manager via email.  
@15.13 hrs. Incident Investigation at SNP site office  
@17.42 hrs. Share Incident case via line group "Trailer truck driver" to prevent to recurrence.

Nov.24, 2023

@07.15 hrs. Share Incident case in TBT meeting to alert to all crew.

Improvement:

A. Must be apply SNP Work permit

B. Transportation management plan required consists of:

1. The radio for communication required during transportation between the trailer truck driver and helper team.
2. All people must attend toolbox talk meeting before transportation.
3. All position must be meet skill and experience.
4. Must be report immediately in case of incident.

This incident has been classified as a property damaged

6. Why did the incident happen?

Unsafe workplace conditions: (Check all that apply)

- ☐ Inadequate guard
- ☐ Unguarded hazard
- ☐ Safety device is defective
- ☐ Tool or equipment defective
- ☐ Workstation layout is hazardous
- ☐ Unsafe lighting
- ☐ Unsafe ventilation
- ☐ Lack of needed personal protective equipment
- ☐ Lack of appropriate equipment / tools
- ☐ Unsafe clothing
- ☐ No training or insufficient training

Other: The road is narrow with local car parking on roadside and a lot of overhead cable

Why did the unsafe condition exist?

- 1.The road is narrow with local car parking on roadside.
- 2.A lot of overhead cable.
- 3.Promuding parts of the equipment, like side mirror

- Unsafe acts by people: (Check all that apply)
- ☐ Operating without permission
  - ☐ Operating at unsafe speed
  - ☐ Servicing equipment that has power to it
  - ☐ Making a safety device inoperative
  - ☐ Using defective equipment
  - ☐ Using equipment in an unapproved way
  - ☐ Unsafe lifting
  - ☐ Taking an unsafe position or posture
  - ☐ Distraction, teasing, horseplay
  - ☐ Failure to wear personal protective equipment
  - ☐ Failure to use the available equipment / tools

Other: Poor transportation management

Why did the unsafe acts occur?

1. Not enough helper to observation overhead cable.
2. No trailer truck driver attend in toolbox talk meeting.
3. Signal man has no experience.
4. Poor supervision and monitoring.

Were the unsafe acts or conditions reported prior to the incident? ☐ Yes ☒ No

Have there been similar incidents or near misses prior to this one? ☐ Yes ☒ No

#### 7. How can future incidents be prevented?

##### What changes do you suggest to prevent this incident/near miss from happening again?

- ☐ Stop this activity ☐ Guard the hazard ☐ Train the employee(s) ☐ Train the supervisor(s)
- ☐ Redesign task steps ☐ Redesign work station ☐ Write a new policy/rule ☒ Enforce existing policy
- ☐ Routinely inspect for the hazard ☐ Personal Protective Equipment ☐ Other:

What should be (or has been) done to carry out the suggestion(s) checked above?

1. Alert to all crews in Toolbox Talk Meeting that must follow Road transportation safety policy and basic safety procedure and JSA all time before transportation.

2. Share Incident case to line group Trailer truck driver.

The purpose to share incident case because SNP will learn from this incident that how to prevent incident recurrence.

Description continued on attached sheets: ☐ Yes ☒ No

#### 8. Corrective/Preventive Action Tracking (All blocks must be filled in and information verifiable)

List action(s) that have or will be taken to prevent a recurrence.	Assigned To Whom	Scheduled Completion Date	Actual Completion Date	Follow-up Date
To alert crew in daily toolbox meeting on site	Safety Officer	Nov.24, 2023	Nov.24, 2023	
Alert to all trailer truck driver (via line group)	Safety Manager	Nov.23, 2023	Nov.23, 2023	
Incident Investigation	Safety Dept.	Nov.23, 2023	Nov.23, 2023	
Issue Warning letter to transportation team	Safety Dept.	Nov.23, 2023	Nov.23, 2023	

#### 9. Attachment List

- Attachment 1- Photo of the incident

#### 10. Investigation Team and Prepared/completed report

Prepared by:	Mr. Banlu Boonham	Position: Safety Manager
Department:	HSE	
Names of investigation team members: Mr. Banlu Boonham (SHE), Mr. Jiang Xingyong (SHE), Wang Qing Min (SHE), Li Liang (Engineer)		

#### 11. Review and Comment

**HSE Manager** ☐ Agree ☐ Disagree ☐ Comments (see below detail)

Name: Signature : Date :

**Construction Manager** ☐ Agree ☐ Disagree ☐ Comments (see below detail)

Name: Signature : Date :

## ATTACHMENT 1 : PHOTO



### THE INCIDENT LOCATION AREA



**AIS & TRUE INTERNET CABLE BROKEN ON NOV.22, 2023**

**AIS & TRUE MECHANICAL INSPECTION THE BROKEN CABLE ON NOV.22, 2023**



**AIS & TRUE INTERNET CABLE MECHANICAL RE-CONNECT CABLE ON NOV.22, 2023**

**SHARE INCIDENT CASE IN TBT MEETING ON NOV.24, 2023**


**ATTACHMENT 1 : PHOTO**



INCIDENT INVESTIGATION ON NOV.23, 2023

## ภาคผนวก จ-2

บันทึกสถิติข้อคิดเห็นและข้อร้องเรียนของโครงการ




Bangpakong-South Bangkok Power Plant Transmission Pipeline Project										COMPLAINANTS REGISTER										
Serial no.	Complain Date	Phase	Name of The Complainant	Contact Details	KP	Village/ Village No.	Sub-district	District	Province	Code of Complaint	Source of Complaint	Others Detail	Type of Complaint	Others Detail	Detail of Complaint	Corrective Action	Complain Status	Close out Date	Remarks	
01	16-Oct-23	2	Khun Phichai, Politician	-	DP#21	Pradit samosorn m.6	Bang Mueang Mai	Mueang	Samutprakram	2B	PTT CR	The villager posted Video on Group LINE of Khun Phichai, Politician, then PTT-CR inform to SNP-CR	Registered Form	-		Soil fell on the public road. ดินตลิ่งรถบรรทุกบนพื้นผิวถนนสาธารณะ	Road cleaning ทำความสะอาดพื้นผิวถนนของ ประสิทธิ์ในสร	Closed	16-Oct-23	-
02	1-Nov-23	2			DP#24 Entry pit KP.53+200	Bussaba 2	Bang Duan	Mueang	Samutprakram	2D	PTT CR		Official Letter	-		หนังสือแจ้ง กรณีดำเนินการขุดลอกสร้างในระยะประชิดพื้นที่ก่อสร้าง ก่อการก่อสร้างใน อ่างให้สิ่งเจือปนในน้ำไหล หากเกิดความเสียหายจากการก่อสร้างแล้วเสร็จให้รีบดำเนินการซ่อม (ระยะประชิดหรือ ระยะประชิดพื้นที่) ,อ่าง หากเกิดความเสียหายจากการก่อสร้างโดยละเอียด หากเกิดความเสียหายจากการก่อสร้างโดยละเอียด และสิ่งส่งส่งจากการก่อสร้าง จะมีการแก้ไขปัญหาดังกล่าว	□ 11-66 สืบเสาะหาตัวขึ้นเรื่องประเด็น □ 4-1166 สืบเสาะหาตัวขึ้นเรื่องประเด็นที่ส่งผลกระทบต่อพื้นที่ก่อสร้าง □ 21-11-66 ปลด.เข้าพบ เพื่อรับเรื่อง ร้องเรียนและชี้แจงมาตรการป้องกันและลดผลกระทบ □ 8-01-67 เข้าพบเพื่อแจ้งแผนการดำเนินงานในพื้นที่ และวิธีดำเนินการ	Outstanding	-	□ ยังมีความห่วงกังวลเชิงผลกระทบจากการก่อสร้าง □ ปัจจุบันอยู่ระหว่างการก่อสร้าง โครงการได้เข้าพบ เพื่อชี้แจงและติดตามปรับปรุงแก้ไขอย่างต่อเนื่อง
03	30-Oct-23	2			DP#24 Entry pit KP.53+200	Bussaba 2	Bang Duan	Mueang	Samutprakram	2D	PTT CR	ร้องเรียนไป 60 วันหน่วยงานที่เกี่ยวข้อง (พล.ต.หญิง ดำรงธรรม จันทรา)	Official Letter	-		□ อยู่ระหว่างชี้แจงประเด็นข้อร้องเรียนหน่วยงานที่เกี่ยวข้องและผู้เกี่ยวข้อง □ อยู่ระหว่างการก่อสร้าง โครงการได้เข้าพบ เพื่อชี้แจงและติดตามปรับปรุงแก้ไขอย่างต่อเนื่อง	• 20-11-66 เข้าพบนายสิริพล ศรีนิภา ผู้รับผิดชอบงานด้านทรัพยากรและสิ่งแวดล้อมจังหวัดสมุทรปราการ พร้อมเจ้าหน้าที่ พสจ. เพื่อรับเรื่องร้องเรียน ปัญหาพื้นที่ □ 23-11-66 ปลด.แจ้งข้อร้องเรียน ณ ผู้แทน ก่อนการประชุม คกก.อำเภอเมือง (ตามคำแนะนำของ พสจ.) □ 4-01-67 ปลด.เข้าพบนายสิริพล ศรีนิภา ผู้รับผิดชอบงานด้านทรัพยากรธรรมชาติและสิ่งแวดล้อมจังหวัดสมุทรปราการ นางสาวนันทพร วงศ์รวม นักวิชาการสิ่งแวดล้อมชำนาญการพิเศษ ผู้ชำนาญการ ส่วนทรัพยากรสัตว์ สาขางาน ทรัพยากรธรรมชาติและสิ่งแวดล้อมจังหวัดสมุทรปราการ เพื่อชี้แจงรายละเอียดประเด็นข้อร้องเรียน □ 09-01-67 ปลด.เข้าพบนางประภาพร อัครา เพน นางกนกนตพรศรีนครสมุทรปราการ □ 09-01-67 ปลด.เข้าพบนายสุริยเมตต์ ศรีสระ ผู้อำนวยการสำนักงานเขตบางเขนสมุทรปราการ	Outstanding	-	□ อยู่ระหว่างชี้แจงประเด็นข้อร้องเรียนหน่วยงานที่เกี่ยวข้องและผู้เกี่ยวข้อง □ อยู่ระหว่างการก่อสร้าง โครงการได้เข้าพบ เพื่อชี้แจงและติดตามปรับปรุงแก้ไขอย่างต่อเนื่อง
04	2-Nov-23	1			ถนน ม.2 KP4+200	Moo 2	Khao Din	Bang Pakong	Chachoengsao	2B	Contractor CR		Registered Form	-		□ จะมีการติดตั้งเครื่องวัดเสียง เครื่องวัดแรงสั่นสะเทือน ตลอดระยะเวลาก่อสร้างหรือไม่	Construction crews used machinery to condition the area and fill soil and rocks to the subsidence areaที่ก่อสร้างใช้เครื่องจักรปรับสภาพพื้นที่และดินและหินบริเวณที่ชำรุด 15/11/2023 สืบเสาะหาตัวขึ้นเรื่องพื้นที่ถนน และลงพื้นที่ ทางเข้า-ออก หมู่บ้าน ตาม ร้องเรียน	Closed	13-Nov-23	-
05	16-Nov-23	1			ถนน ม.2 KP4+200	Moo 2	Khao Din	Bang Pakong	Chachoengsao	2B	Contractor CR		Registered Form	-		□ จะสืบค้นจากคณะกรรมการและหน่วยงานที่เกี่ยวข้อง	□ 24/11/2023 สืบเสาะหาตัวขึ้นเรื่องพื้นที่ก่อสร้าง □ 23/12/2023 สืบเสาะหาตัวขึ้นเรื่องพื้นที่ถนน และลงพื้นที่ ตาม ร้องเรียน	Closed	23/12/2023	-

Bangpakong-South Bangkok Power Plant Transmission Pipeline Project																				
COMPLAINTS REGISTER																				
Serial no.	Complain Date	Phase	Name of The Complainant	Contact Details	KP	Village/ Village No.	Sub-district	District	Province	Code of Complaint	Source of Complaint	Others Detail	Type of Complaint	Others Detail	Detail of Complaint	Corrective Action	Complain Status	Close out Date	Remarks	
06	19-Dec-23	1	นายเจษฎา SAO Khao Din	นางสาว อ.ด.ดา ด.น 038-134025 ต่อ 27	ถนน ร.1 และร.2 KP2-KP4	Moo1,Moo2		Bang Pakong	Chachoengsao	2D	Contractor CR	-	Official Letter	-		ประชาชนให้กรรมการดำเนินงานในหน้าที่ดูแลและรับผิดชอบการก่อสร้าง 23/12/2023 ผู้รับเหมาก่อสร้างเข้ากันถนนเพื่อแสดงพื้นที่ขุด ดิน จนเห็นสภาพ บริเวณถนนและพื้นที่ขุด ดิน ชัดเจน 11/1/2024 CR ทางหนังสือแจ้ง อ.ด.ดา ด.น แจ้งการเข้าซ่อมแซมถนนที่เสียหายจาก การขุดสร้าง	19/12/2023 รับหนังสือจาก อ.ด.ดา ด.นแจ้งขอให้กรรมการดำเนินงาน ดูแลรับผิดชอบการก่อสร้าง 23/12/2023 ผู้รับเหมาก่อสร้างเข้ากัน ถนนเพื่อแสดงพื้นที่ขุด ดิน ชัดเจน 11/1/2024 CR ทางหนังสือแจ้ง อ.ด.ดา ด.น แจ้งการเข้าซ่อมแซมถนนที่เสียหายจาก การขุดสร้าง			-
07	7-Dec-2023	2			DP#23 Entry pit KP.52+100	Moo.3	Bang Mueang Mai	Mueang	Samutprakarn	2B	Contractor CR	-	Registered Form	-		Residences were damaged by construction activities, including cracked walls and cracked floor concrete. พื้นที่เกิดเหตุได้รับความเสียหายจากการก่อสร้าง รวมถึงรั่วซึมและที่ถนนทรุดตัว	The house wall and the concrete floor will be repaired after the construction is completed เสาบ้านและพื้นคอนกรีตจะทำการซ่อมแซมหลังจากที่ก่อสร้างเสร็จ	Outstanding	-	ปัจจุบันอยู่ระหว่างก่อสร้าง โดยได้เข้าเจรจาข้อตกลง และแจ้งการซ่อมแซม หลังจากการก่อสร้างแล้วเสร็จต่อไป
08	17-Jan-24	2			DP#23 Entry pit KP.52+100	Moo 3	Bang Mueang Mai	Mueang	Samutprakarn	2B	Contractor CR	-	Registered Form	-		Ceiling of bathroom broken ฝ้าเพดานห้องน้ำชำรุด	Request urgent to repair the ceiling of bathroom ซ่อมแซมฝ้าเพดานห้องน้ำโดยเร่งด่วน	Closed	17-Jan-24	-
09	23-ก.ย.-23	2			DP#23-18(Entry pit) KP52+100	Moo 1	Bang Mueang Mai	Mueang	Samutprakarn	2B	Contractor CR	-	Registered Form	-		รบบรทุกอุปกรณ์เกี่ยวกับท่อเมน	ผู้ได้รับผลกระทบแจ้งว่าไม่ดำเนินการก่อสร้างในเส้นสีก่อน ถึงจะดำเนินการซ่อมแซม	Outstanding	-	ปัจจุบันอยู่ระหว่างก่อสร้าง โดยได้เข้าเจรจาข้อตกลง และแจ้งการซ่อมแซม หลังจากการก่อสร้างแล้วเสร็จต่อไป
10	30-ก.ค.-23	2			DP#27	Moo 2	Bang Prong	Bang Prong	Samutprakarn	2B	PTT CR	-	Registered Form	-		ผู้รับเหมามาเข้าดำเนินการก่อสร้างทางใต้ดินบ้านร้าง	ผู้รับเหมามาเข้าเก็บสภาพบ้านเรียบร้อยแล้ว	Outstanding	-	ปัจจุบันอยู่ระหว่างก่อสร้าง โดยได้เข้าเจรจาข้อตกลง และแจ้งการซ่อมแซม หลังจากการก่อสร้างแล้วเสร็จต่อไป
11	16-ก.ค.-23	2			DP#28 (exit Pit) KP56+200	Moo 2	Bang Fai	Bang Prong	Samutprakarn	2B	Contractor CR	-	Registered Form	-		ผู้รับเหมามาเข้าดำเนินการก่อสร้างทางใต้ดินบ้านร้าง	ผู้รับเหมามาเข้าเก็บสภาพบ้านเรียบร้อยแล้ว	Outstanding	-	ปัจจุบันอยู่ระหว่างก่อสร้าง โดยได้เข้าเจรจาข้อตกลง และแจ้งการซ่อมแซม หลังจากการก่อสร้างแล้วเสร็จต่อไป
12	16-พ.ค.-23	1	นายเจษฎา V Compound และ PAVE Bangsa อ.บางโป	รหัสศึกษา 500 เมตร (ใกล้กับ KP22+400 ถึง KP23+600)		Moo 2	Bang Phiang	Bang Bo	Samutprakarn	1D	Others (Fill detail in right column)	-	Official Letter	-		• คมพ., นส., วณ. ร่วมกับช่างทั้งสี่ และคอมสลับไปยัง คต.ส.บ. และ • ภายหลัง คต.ส.บ. ได้แจ้งให้ อ.บางโป จัดประชุมชี้แจงข้อร้องเรียนดังกล่าว และดำเนินการร้องเรียนแล้วเสร็จ ซึ่งได้มีการติดตามประเด็นต่อเนื่อง ปัจจุบัน คต.ส.บ. ส่งสรุปการประชุมการแก้ไขข้อพิพาทขึ้นถึง อ.บางโป โพธิ์ขะขวาง พังงา ดำเนินการต่อไป	12-ก.ค.-23		-	
13	7-ก.ย.-23	2			KP48+950	Moo 7	Theparak	Mueang	Samutprakarn	1D	Others (Fill detail in right column)	-	Official Letter	-		ขอให้ตรวจสอบการขุดที่ก่อสร้างส่วนต่อขยายของ ปตท. บริเวณซอยที่ตัดทาง 6 ม.7 ต.เทพารักษ์ อ.เมือง จ.สมุทรปราการ เนื่องจากไม่ได้แจ้งกระบวนการขุดขุดกับกรณีการเกิดเหตุระเบิด และผลกระทบด้านสิทธิของชาวบ้านและชุมชนไม่เกิน 5 เมตร กรณีจะเกิดอันตราย ขอให้ตรวจสอบโดยด่วน	• คมพ., พตม. และ นส. เข้าพบผู้ร้องเพื่อชี้แจงรายละเอียดโครงการ • คมพ. และ นส. ร่วมกับช่างทั้งสี่ คอมสลับไปยัง คต.ส.บ. แล้ว	Closed	21-พ.ย.-23	-



**ภาคผนวก จ-3**  
**บันทึกการฉีดพรมน้ำของโครงการ**





BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

WATER SPRAY RECORD

For the Month of Jul, 2023

Driver Name : [REDACTED] Vehicle registration : 70-2174 สีนบุรี

Date	Location	Time		Frequency	Weather	Record by	Checked by	Remark
		From	To					
01/07/2023	DP#21	08:00	12:00	11	ฝน	[REDACTED]	[REDACTED]	16Q
		13:00	17:00	11	ฝน			8Q
02/07/2023	DP#21	08:00	12:00	11	ฝน			-
		13:00	17:00	11	ฝน			8Q
03/07/2023	DP#21	08:00	12:00	-	ฝน			-
		13:00	17:00	-	ฝน			-
04/07/2023	DP#21	08:00	12:00	-	ฝน			-
		13:00	17:00	-	ฝน			-
05/07/2023	DP#21	08:00	12:00	-	ฝน			-
		13:00	17:00	-	ฝน			-
06/07/2023	DP#21	08:00	12:00	1	ฝน			-
		13:00	17:00	-	ฝน			-
07/07/2023	DP#21	08:00	12:00	-	ฝน			-
		13:00	17:00	-	ฝน			-
08/07/2023	DP#21	08:00	12:00	-	ฝน			-
		13:00	17:00	-	ฝน			-
09/07/2023	DP#21	08:00	12:00	-	ฝน			-
		13:00	17:00	1	ฝน			4Q
10/07/2023	DP#21	08:00	12:00	-	ฝน			-
		13:00	17:00	1	ฝน			-
11/07/2023	DP#21	08:00	12:00	1	ฝน			-
		13:00	17:00	1	ฝน			-
12/07/2023	DP#21	08:00	12:00	1	ฝน			4Q
		13:00	17:00	1	ฝน			4Q
13/07/2023	DP#21	08:00	12:00	-	ฝน			-
		13:00	17:00	11	ฝน			16Q
14/07/2023	DP#21	08:00	12:00	11	ฝน			4Q
		13:00	17:00	-	ฝน			-
15/07/2023	DP#21	08:00	12:00	111	ฝน			24Q
		13:00	17:00	111	ฝน			24Q
16/07/2023	DP#21	08:00	12:00	1111	ฝน			24Q
		13:00	17:00	1111	ฝน			24Q

Report by

Approve by



BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

WATER SPRAY RECORD

For the Month of Jul, 2023

Driver Name : [REDACTED]

Date	Location	Time		Frequency	Weather	Record by	Checked by	Remark
		From	To					
17/06/2023	DP#21	08:00	12:00	11	ฝน	[REDACTED]	[REDACTED]	8Q
		13:00	17:00	11	ฝน			6Q
18/06/2023	DP#21	08:00	12:00	11	ฝน			16Q
		13:00	17:00	11	ฝน			16Q
19/06/2023	DP#21	08:00	12:00	11	เมฆบางส่วน			8Q
		13:00	17:00	11	เมฆบางส่วน			8Q
20/06/2023	DP#21	08:00	12:00	-	ฝนตก			8Q
		13:00	17:00	-	ฝนตก			8Q
21/06/2023	DP#21	08:00	12:00	-	ฝนตก			-
		13:00	17:00	-	ฝนตก			-
22/06/2023	DP#21	08:00	12:00	-	ฝนตก			-
		13:00	17:00	-	ฝนตก			-
23/06/2023	DP#21	08:00	12:00	-	ฝนตก			-
		13:00	17:00	-	ฝนตก			-
24/06/2023	DP#21	08:00	17:00	-	ฝนตก			-
		13:00	17:00	-	ฝนตก			-
25/06/2023	DP#21	08:00	17:00	-	ฝนตก			-
		13:00	17:00	-	ฝนตก			-
26/06/2023	DP#21	08:00	17:00	-	ฝนตก			-
		13:00	17:00	-	เมฆบางส่วน			-
27/06/2023	DP#21	08:00	17:00	1	ฝนตก			-
		13:00	17:00	1	ฝนตก			-
28/06/2023	DP#21	08:00	17:00	-	-			5445/9
		13:00	17:00	-	-			-
29/06/2023	DP#21	08:00	17:00	1	ฝนตก			8Q
		13:00	17:00	1	ฝนตก			-
30/06/2023	DP#21	08:00	17:00	-	-			5445/9
		13:00	17:00	-	-			5445/9
31/06/2023	DP#21	08:00	17:00	-	ฝนตก			-
		13:00	17:00	1	ฝนตก			-

Report by [REDACTED]

Approve by [REDACTED]



BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

WATER SPRAY RECORD

For the Month of Aug, 2023

Driver Name : [REDACTED]

Date	Location	Time		Frequency	Weather	Record by	Checked by	Remark
		From	To					
01/08/2023	DP#21	08:00	12:00	1	มีเมฆบางส่วน	[REDACTED]	[REDACTED]	8Q
		13:00	17:00	1	มีเมฆบางส่วน			
02/08/2023	DP#21	08:00	12:00	1	มีเมฆบางส่วน			
		13:00	17:00	-	ฝนตก			
03/08/2023	DP#21	08:00	12:00	-	ฝนตก			
		13:00	17:00	-	ฝนตก			
04/08/2023	DP#21	08:00	12:00	-	ฝนตก			
		13:00	17:00	-	ฝนตก			
05/08/2023	DP#21	08:00	12:00	1	ฝนตก			4Q
		13:00	17:00	11	ฝนตก			
06/08/2023	DP#21	08:00	12:00	1	ฝนตก			8Q
		13:00	17:00	11	ฝนตก			
07/08/2023	DP#21	08:00	12:00	11	ฝนตก			
		13:00	17:00	11	ฝนตก			
08/08/2023	DP#21	08:00	12:00	1	ฝนตก			8Q
		13:00	17:00	11	ฝนตก			
09/08/2023	DP#21	08:00	12:00	1	มีเมฆบางส่วน			
		13:00	17:00	11	ฝนตก			
10/08/2023	DP#21	08:00	12:00	1	ฝนตก			8Q
		13:00	17:00	11	ฝนตก			
11/08/2023	DP#21	08:00	12:00	1	ฝนตก			
		13:00	17:00	11	ฝนตก			
12/08/2023	DP#21	08:00	12:00	1	ฝนตก			
		13:00	17:00	-	ฝนตก			
13/08/2023	DP#21	08:00	12:00	1	ฝนตก			8Q
		13:00	17:00	1	ฝนตก			
14/08/2023	DP#21	08:00	12:00	1	ฝนตก			
		13:00	17:00	-	ฝนตก			
15/08/2023	DP#21	08:00	12:00	1	ฝนตก			8Q
		13:00	17:00	1	ฝนตก			
16/08/2023	DP#21	08:00	12:00	1	ฝนตก			
		13:00	17:00	1	ฝนตก			

Report by

Approve by



BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

WATER SPRAY RECORD

For the Month of Aug, 2023

Driver Name : [REDACTED]

Date	Location	Time		Frequency	Weather	Record by	Checked by	Remark
		From	To					
17/08/2023	DP#21	08:00	12:00	1	ฝนตก	[REDACTED]	[REDACTED]	8Q
		13:00	17:00	1	ฝนตก			
18/08/2023	DP#21	08:00	12:00	1	ฝนตก			
		13:00	17:00	1	ฝนตก			
19/08/2023	DP#21	08:00	12:00	-	ฝนตก			ฝนตกจากฟ้า
		13:00	17:00	-	ฝนตก			
20/08/2023	DP#21	08:00	12:00	-	ฝนตก			
		13:00	17:00	-	ฝนตก			
21/08/2023	DP#21	08:00	12:00	-	ฝนตก			
		13:00	17:00	-	ฝนตก			ฝนตกจากฟ้า
22/08/2023	DP#21	08:00	12:00	-	ฝนตก			
		13:00	17:00	-	ฝนตก			
23/08/2023	DP#21	08:00	12:00	-	มีพายุฝน			
		13:00	17:00	-	ฝนตก			
24/08/2023	DP#21	08:00	17:00	-	ฝนตก			
		13:00	17:00	-	ฝนตก			
25/08/2023	DP#21	08:00	17:00	-	ฝนตก			ฝนตกจากฟ้า
		13:00	17:00	-	ฝนตก			
26/08/2023	DP#21	08:00	17:00	-	ฝนตก			ฝนตกจากฟ้า
		13:00	17:00	-	ฝนตก			h
27/08/2023	DP#21	08:00	17:00	-	ฝนตก			n
		13:00	17:00	-	ฝนตก			n
28/08/2023	DP#21	08:00	17:00	-	ฝนตก			n
		13:00	17:00	-	ฝนตก			n
29/08/2023	DP#21	08:00	17:00	11	ฝนตก			
		13:00	17:00	1	ฝนตก			
30/08/2023	DP#21	08:00	17:00	1	ฝนตก			
		13:00	17:00	11	ฝนตก			
31/08/2023	DP#21	08:00	17:00	1	ฝนตก			
		13:00	17:00	1	ฝนตก			

Report by

Approve by



BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

WATER SPRAY RECORD

For the Month of Sep. 2023

Driver Name : [REDACTED]

Date	Location	Time		Frequency	Weather	Record by	Checked by	Remark
		From	To					
1/9/2023	DP#21	8:00	12:00	1	2/100	[REDACTED]	[REDACTED]	
		13:00	17:00	1	2/100			
2/9/2023	DP#21	8:00	12:00	1	2/100			
		13:00	17:00	1	2/100			
3/9/2023	DP#21	8:00	12:00	1	2/100			
		13:00	17:00	1	2/100			
4/9/2023	DP#21	8:00	12:00	1	2/100			
		13:00	17:00	1	2/100			
5/9/2023	DP#21	8:00	12:00	1	2/100			
		13:00	17:00	1	2/100			
7/9/2023	DP#21	8:00	12:00	1	2/100			
		13:00	17:00	1	2/100			
8/9/2023	DP#21	8:00	12:00	1	2/100			
		13:00	17:00	1	2/100			
9/9/2023	DP#21	8:00	12:00	11	2/100			
		13:00	17:00	11	2/100			
10/9/2023	DP#21	8:00	12:00	11	2/100			
		13:00	17:00	11	2/100			
11/9/2023	DP#21	8:00	12:00	11	2/100			
		13:00	17:00	11	2/100			
12/9/2023	DP#21	8:00	12:00	1	2/100			
		13:00	17:00	-	2/100			
13/9/2023	DP#21	8:00	12:00	11	2/100			
		13:00	17:00	-	2/100			
14/9/2023	DP#21	8:00	12:00	11	2/100			
		13:00	17:00	-	2/100			
15/9/2023	DP#21	8:00	12:00	11	2/100			
		13:00	17:00	11	2/100			
16/9/2023	DP#21	8:00	12:00	1	2/100			
		13:00	17:00	1	2/100			

Report by

Approve by



BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

WATER SPRAY RECORD

For the Month of Sep, 2023

Driver Name : [REDACTED] Vehicle registration : [REDACTED]

Date	Location	Time		Frequency	Weather	Record by	Checked by	Remark
		From	To					
17/9/2023	DP#21	8:00	12:00	-	พายุฝน	[REDACTED]	[REDACTED]	
		13:00	17:00	-	พายุฝน			
18/9/2023	DP#21	8:00	12:00	1	พายุฝน			
		13:00	17:00	1	พายุฝน			
19/9/2023	DP#21	8:00	12:00	-	พายุฝน			พายุฝนตกหนัก
		13:00	17:00	-	พายุฝน			
20/9/2023	DP#21	8:00	12:00	-	-			พายุฝนตกหนัก
		13:00	17:00	-	-			พายุฝนตกหนัก
21/9/2023	DP#21	8:00	12:00	-	-			พายุฝนตกหนัก
		13:00	17:00	-	-			พายุฝนตกหนัก
22/9/2023	DP#21	8:00	12:00	-	-			พายุฝนตกหนัก
		13:00	17:00	-	-			พายุฝนตกหนัก
23/9/2023	DP#21	8:00	12:00	-	พายุฝน			
		13:00	17:00	-	พายุฝน			
24/9/2023	DP#21	8:00	12:00	-	พายุฝน			พายุฝนตกหนัก
		13:00	17:00	-	พายุฝน			
25/9/2023	DP#21	8:00	12:00	-	พายุฝน			พายุฝนตกหนัก
		13:00	17:00	-	พายุฝน			
26/9/2023	DP#21	8:00	12:00	-	พายุฝน			พายุฝนตกหนัก
		13:00	17:00	-	พายุฝน			
27/9/2023	DP#21	8:00	12:00	-	พายุฝน			
		13:00	17:00	-	พายุฝน			
28/9/2023	DP#21	8:00	12:00	-	พายุฝน			
		13:00	17:00	-	พายุฝน			
29/9/2023	DP#21	8:00	12:00	-	พายุฝน			
		13:00	17:00	-	พายุฝน			
30/9/2023	DP#21	8:00	12:00	-	พายุฝน			พายุฝนตกหนัก
		13:00	17:00	-	พายุฝน			

Report by

Approve by

(M)

BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

**WATER SPRAY RECORD**

For the Month of November 2023

Driver Name : [REDACTED]

Vehicle registration : [REDACTED]

Date	Location	Time		Frequency	Weather	Record by	Checked by	Remark
		From	To					
1/11/2023	DP#21, DP22 (entry)	08:00	12:00	1	ฝน	[REDACTED]	[REDACTED]	
		13:00	17:00	1	ฝน			
2/11/2023	DP#21, DP22 (entry)	08:00	12:00	1	ฝน			
		13:00	17:00	1	ฝน			
3/11/2023	DP#21, DP22 (entry)	08:00	12:00	1	ฝน			
		13:00	17:00	1	ฝน			
4/11/2023	DP#21, DP22 (entry)	08:00	12:00	1	ฝน			
		13:00	17:00	1	ฝน			
5/11/2023	DP#21, DP22 (entry)	08:00	12:00	-	เมฆบางส่วน			ฝนตกหนัก
		13:00	17:00	-	เมฆบางส่วน			n
6/11/2023	DP#21, DP22 (entry)	08:00	12:00	-	เมฆบางส่วน			n
		13:00	17:00	-	พายุฝน			n
7/11/2023	DP#21, DP22 (entry)	08:00	12:00	-	ฝน			n
		13:00	17:00	-	พายุฝน			n
8/11/2023	DP#21, DP22 (entry)	08:00	12:00	-	ฝน			n
		13:00	17:00	-	ฝน			n
9/11/2023	DP#21, DP22 (entry)	08:00	12:00	-	เมฆบางส่วน			n
		13:00	17:00	-	ฝน			n
10/11/2023	DP#21, DP22 (entry)	08:00	12:00	-	ฝน			n
		13:00	17:00	-	ฝน			n
11/11/2023	DP#21, DP22 (entry)	08:00	12:00	-	พายุฝน			n
		13:00	17:00	-	เมฆบางส่วน			n
12/11/2023	DP#21, DP22 (entry)	08:00	12:00	-	เมฆบางส่วน			n
		13:00	17:00	-	เมฆบางส่วน			n
13/11/2023	DP#21, DP22 (entry)	08:00	12:00	-	ฝน			n
		13:00	17:00	-	ฝน			n
14/11/2023	DP#21, DP22 (entry)	08:00	12:00	-	ฝน			n
		13:00	17:00	-	ฝน			n
15/11/2023	DP#21, DP22 (entry)	08:00	12:00	-	ฝน			ฝนตกหนัก
		13:00	17:00	-	ฝน			n
16/11/2023	DP#21, DP22 (entry)	08:00	12:00	1	ฝน			
		13:00	17:00	1	ฝน			

Report by

Approve by

BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

WATER SPRAY RECORD

For the Month of November 2023

Driver Name : [REDACTED] Vehicle registration : 81-4238

Date	Location	Time		Frequency	Weather	Record by	Checked by	Remark
		From	To					
17/11/2023	DP#21, DP22 (entry)	08:00	12:00		ฝน	<div style="background-color: black; width: 100px; height: 100px;"></div>	<div style="background-color: black; width: 100px; height: 100px;"></div>	
		13:00	17:00		n			
18/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			
19/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			
20/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			
21/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			
22/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			
23/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			
24/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			
25/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			
26/11/2023	DP#21, DP22 (entry)	08:00	12:00		ฝน			
		13:00	17:00	-	ฝน			ฝนตก
27/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			
28/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			
29/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			
30/11/2023	DP#21, DP22 (entry)	08:00	12:00		n			
		13:00	17:00		n			

Report by

Approve by

(M)

Water Spray Record  
December 2023

Vehicle registration : .....


Driver Name : .....

Date	Location	Time		Frequency	Record by	Checked by	Remark
		From	To				
1-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
2-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
3-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
4-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
5-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
6-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
7-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
8-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
9-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
10-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
11-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
12-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
13-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
14-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
15-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
16-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
17-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
18-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	

Date	Location	Time		Frequency	Record by	Checked by	Remark
		From	To				
19-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
20-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
21-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
22-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
23-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
24-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
25-Dec-23	KP8+300 (BS#1)	8.00	18.00	2	Suntorn S.	Ketsarin R.	
	KP26+900 (BS#4)	8.00	18.00	2	Suntorn S.	Ketsarin R.	



Record



Photos



15 ธ.ค. 2023 15:33:32

BS#1





19 ธ.ค. 2023 13:04:27

BS#4

BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

WATER SPRAY RECORD

For the Month of ธันวาคม 2023

Driver Name : [REDACTED]

Vehicle registration : 81-4238

Date	Location	Time		Frequency	Weather	Record by	Checked by	Remark
		From	To					
1/12/2023	DP#21, DP#22 (entry)	08:00	12:00	11	ฝนตก	<div style="background-color: black; width: 100px; height: 100px;"></div>	<div style="background-color: black; width: 100px; height: 100px;"></div>	
		13:00	17:00	1	ฝนตก			
2/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	1	ฝนตก			
3/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	11	ฝนตก			
4/12/2023	DP#21, DP#22 (entry)	08:00	12:00	-	ฝนตก			ฉีดน้ำตามท่อ
		13:00	17:00	-	ฝนตก			h
5/12/2023	DP#21, DP#22 (entry)	08:00	12:00	-	ฝนตก			h
		13:00	17:00	-	ฝนตก			h
6/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	1	ฝนตก			
7/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	1	ฝนตก			
8/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	11	ฝนตก			
9/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	11	ฝนตก			
10/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	11	ฝนตก			
11/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	11	ฝนตก			
12/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	11	ฝนตก			
13/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	1	ฝนตก			
14/12/2023	DP#21, DP#22 (entry)	08:00	12:00	11	ฝนตก			
		13:00	17:00	1	ฝนตก			
15/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	11	ฝนตก			
16/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ฝนตก			
		13:00	17:00	11	ฝนตก			

Report by

Approve by

BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

WATER SPRAY RECORD

For the Month of ธันวาคม, 2023

Driver Name : [REDACTED]

Date	Location	Time		Frequency	Weather	Record by	Checked by	Remark
		From	To					
17/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ	<span style="background-color: black; color: black;">[REDACTED]</span>	<span style="background-color: black; color: black;">[REDACTED]</span>	
		13:00	17:00	1	ปกติ			
18/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
19/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
20/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
21/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
22/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
23/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
24/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
25/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
26/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
27/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
28/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
29/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
30/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			
31/12/2023	DP#21, DP#22 (entry)	08:00	12:00	1	ปกติ			
		13:00	17:00	1	ปกติ			


Report by

Approve by

Date: 31/12/2023

## ภาคผนวก จ-4

บันทึกปริมาณขยะทั่วไป ขยะรีไซเคิล และของเสียอันตราย





**BANGPAKONG – SOUTH BANGKOK POWER PLANT  
TRANSMISSION PIPELINE PROJECT – PHASE 1**



**WASTE MANAGEMENT REPORT**

Location: CPP-JV office and construction area Month: Jul – Dec 2023

Month	Quantity (Kg)				
	General Waste <sup>1/</sup>	Recycle Waste <sup>2/</sup>	Construction Waste <sup>3/</sup>	Hazardous Waste <sup>4/</sup>	Infectious Waste
July, 2023	900	5	3,000	5	0
August, 2023	670	5	0	3	0
September, 2023	875	17.2	0	0	0
October, 2023	1,423	21	0	0	0
November, 2023	1,532	64.1	0	20	0
December, 2023	2,339	19	0	0	0
<b>Total</b>	<b>7,739</b>	<b>131.3</b>	<b>3,000</b>	<b>28</b>	<b>0</b>



Remark: 1/ - General waste transfer and disposal by Municipality.

2/ - All recycle waste was sold to the recycle shop.

3/ - Construction waste landfill at green waste dumpsite.

4/ - Hazardous waste coordinated with authorized company to disposal

Record by





BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

WASTE MANAGEMENT REPORT

LOCATION Office, Stockyard, Construction area MONTH July - December, 2023

Month	Quantity (kg.)				
	General Waste <sup>1/</sup>	Recycle Waste <sup>2/</sup>	Construction Waste <sup>3/</sup>	Hazadous Waste <sup>4/</sup>	Infectious Waste
July, 2023	1,451	4	3,000	5	0
August, 2023	1,458	4.7	12,000	3	0
September, 2023	1,539	7.7	10,000	0	0
October, 2023	1,487	8.3	4,000	54	0
November, 2023	2,755	74	2,550	48	0
December, 2023	3189	102	10,000	0	0
Total	11,879	200.7	41,550	110	0


Remark: 1/ = General waste transfer and disposal by Municipality.

2/ = All recyclable waste was sold to the recycle shop.


3/ = Construction waste landfill at green waste dumpsite.

4/ = Hazardous Waste transfer and disposal by license company on 25 Nov, 2023.


Report by



Approve by



**ภาคผนวก จ-5**  
**ตัวอย่างบันทึกสภาพการระบายน้ำของโครงการ**





# Bangpakong – South Bangkok Power Plant Transmission Pipeline Project – Phase 1



## Drainage and flooding conditions Record

JULY 2023

Location : .....Stock yard..... Activity : .....Stock pipe.....

Date : 19-July-2023

Time : 14.00 - 15.00 hrs.

- 1 Point Area : Pipe stock yard at Khao Khan Song
- 2 Drainage Condition ☒ Normal ☐ Abnormal
- 3 Physical Appearance of Drainage ☐ Drainage channel obstruction ☐ Water logging in some point  
☐ Flooding on the whole area ☐ Other .....
- 4 Impact level ☐ Hight ☐ Medium  
☐ Low ☒ Not impact
- 5 Damage ☒ No ☐ Yes .....
- 6 Status ☐ Improved ☐ On going  
☐ No Action

7 Photo



Rec

# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## DRAINAGE AND FLOODING CONDITIONS CHECKLIST

LOCATION : DP#21 (KP50+258) ACTIVITY : Install sheet pile of anchor/Fit up and welding sheet pile

For the Month of Jul, 2023 DATE : 29/07/2023 TIME: 07:56

1 Point Area :

2 Drainage Condition



Normal



Abnormal

3 Physical Appearance of Drainage



Drainage Channel obstruction



Water logging in some Point



Flooding on th whole area



Other ....N/A....

4 Impact level



Hight



Medium



Low



Not impact

5 Damage



No



Yes .....

6 Status



Improved



Ongonig



No Action

7 Photo



Report by

Approve by

Drainage and flooding conditions Record

August 2023

Location : .....Stock yard..... Activity : .....Stock pipe.....

Date : 16-August-2023

Time : 13.30 - 14.30 hrs.

- 1 Point Area : Pipe stock yard at Khao Khan Song
- 2 Drainage Condition ☒ Normal ☐ Abnormal
- 3 Physical Appearance of Drainage ☐ Drainage channel obstruction ☐ Water logging in some point  
☐ Flooding on the whole area ☐ Other .....
- 4 Impact level ☐ Hight ☐ Medium  
☐ Low ☒ Not impact
- 5 Damage ☒ No ☐ Yes .....
- 6 Status ☐ Improved ☐ On going  
☐ No Action
- 7 Photo



Record

# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## DRAINAGE AND FLOODING CONDITIONS CHECKLIST

LOCATION : DP#21 (KP50+258) ACTIVITY : Drilling, Moving pipeline, Fit-up, welding and AUT

For the Month of Aug, 2023 DATE : 30/07/2023 TIME: 14:53

1 Point Area :

2 Drainage Condition



Normal



Abnormal

3 Physical Appearance of Drainage



Drainage Channel obstruction



Water logging in some point



Flooding on th whole area



Other ....N/A....

4 Impact level



Hight



Medium



Low



Not impact

5 Damage



No



Yes .....

6 Status



Improved



Ongonig



No Action

7 Photo



Report by

Approve by

# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## DRAINAGE AND FLOODING CONDITIONS CHECKLIST

LOCATION : SNP Stockyard ACTIVITY : Pipe stock area

For the Month of Aug, 2023 DATE : 25/07/2023 TIME: 14:05

1 Point Area :

2 Drainage Condition



Normal



Abnormal

3 Physical Appearance of Drainage



Drainage Channel obstruction



Water logging in some Point



Flooding on th whole area



Other .....N/A.....

4 Impact level



Hight



Medium



Low



Not impact

5 Damage



No



Yes .....

6 Status



Improved



Ongonig



No Action

7 Photo



Report by

Approve by

## Drainage and flooding conditions Record September 2023

Location : .....Stock yard..... Activity : .....Stock pipe.....

Date : 13 - September - 2023

Time : 14.30 - 15.30 hrs.

- 1 Point Area : Pipe stock yard at Khao Khan Song
- 2 Drainage Condition
 

☒ Normal
 ☐ Abnormal
- 3 Physical Appearance of Drainage
 

☐ Drainage channel obstruction
 ☐ Water logging in some point

☐ Flooding on the whole area
 ☐ Other .....
- 4 Impact level
 

☐ Hight
 ☐ Medium

☐ Low
 ☒ Not impact
- 5 Damage
 



☒ No
 ☐ Yes .....
- 6 Status
 

☐ Improved
 ☐ On going

☐ No Action
- 7 Photo



Record



# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## DRAINAGE AND FLOODING CONDITIONS CHECKLIST

LOCATION : SNP Stockyard ACTIVITY : Pipe stock area

For the Month of Sep, 2023 DATE : 29/09/2023 TIME: 15:43

1 Point Area :

2 Drainage Condition



Normal



Abnormal

3 Physical Appearance of Drainage



Drainage Channel obstruction



Water logging in some Point



Flooding on th whole area



Other .....N/A.....

4 Impact level



Hight



Medium



Low



Not impact

5 Damage



No



Yes .....

6 Status



Improved



Ongonig




No Action


7 Photo



Report by



Approve by



## Drainage and flooding conditions Record

October 2023

Location : .....Stock yard..... Activity : .....Stock pipe.....



Date : 18 - October - 2023

Time : 14.30 - 15.30 hrs.

- 1 Point Area : Pipe stock yard at Khao Khan Song
- 2 Drainage Condition ☒ Normal ☐ Abnormal
- 3 Physical Appearance of Drainage ☐ Drainage channel obstruction ☐ Water logging in some point  
☐ Flooding on the whole area ☐ Other .....
- 4 Impact level ☐ Hight ☐ Medium  
☐ Low ☒ Not impact
- 5 Damage ☒ No ☐ Yes .....
- 6 Status ☐ Improved ☐ On going  
☐ No Action
- 7 Photo



Record



BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

DRAINAGE AND FLOODING CONDITIONS CHECKLIST

LOCATION : \_\_\_\_\_ BS#6 \_\_\_\_\_ ACTIVITY : \_\_\_\_\_ Dewatering activity \_\_\_\_\_.

For the Month of \_\_\_\_\_ Oct, 2023 \_\_\_\_\_ DATE : \_\_\_\_\_ 11/10/2023 \_\_\_\_\_ TIME: \_\_\_\_\_ 08:20 \_\_\_\_\_

- 1 Point Area :
- 2 Drainage Condition ☒ Normal ☐ Abnormal
- 3 Physical Appearance of Drainage ☐ Drainage Channel obstruction ☐ Water logging in some point  
☐ Flooding on th whole area ☒ Other ...N/A.....
- 4 Impact level ☐ Hight ☐ Medium  
☐ Low ☒ Not impact
- 5 Damage ☒ No ☐ Yes .....
- 6 Status ☐ Improved ☐ Ongonig  
☒ No Action
- 7 Photo



- 8 Corective Action (If drainage condition are abnormal)

---




---




---

Report by



Approve by




# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## DRAINAGE AND FLOODING CONDITIONS CHECKLIST

LOCATION : BS#7 ACTIVITY : Clearing area and dewatering

For the Month of Oct, 2023 DATE : 11/10/2023 TIME: 08:07

- 1 Point Area :
- 2 Drainage Condition ☐ Normal ☒ Abnormal
- 3 Physical Appearance of Drainage ☐ Drainage Channel obstruction ☒ Water logging in some point  
☐ Flooding on th whole area ☐ Other .....
- 4 Impact level ☐ Hight ☐ Medium  
☒ Low ☐ Not impact
- 5 Damage ☒ No ☐ Yes .....
- 6 Status ☒ Improved ☐ Ongonig  
☐ No Action
- 7 Photo




### 8 Corective Action (If drainage condition are abnormal)


- Use an excavator to excavate a small trench at a water logging area, connecting it to the temporary gutter.

Then use a water pump machine to pump water from the temporary gutter into Khong Sam Rong.

Report by



Approve by





# Bangpakong – South Bangkok Power Plant Transmission Pipeline Project – Phase 1



## Drainage and flooding conditions Record

November 2023

Location : .....Stock yard..... Activity : .....Stock pipe.....



Date : 15 - November - 2023

Time : 14.30 - 15.30 hrs.

- 1 Point Area : Pipe stock yard at Khao Khan Song
- 2 Drainage Condition ☒ Normal ☐ Abnormal
- 3 Physical Appearance of Drainage ☐ Drainage channel obstruction ☐ Water logging in some point  
☐ Flooding on the whole area ☐ Other .....
- 4 Impact level ☐ Hight ☐ Medium  
☐ Low ☒ Not impact
- 5 Damage ☒ No ☐ Yes .....
- 6 Status ☐ Improved ☐ On going  
☐ No Action
- 7 Photo



Record by



BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## DRAINAGE AND FLOODING CONDITIONS CHECKLIST

LOCATION : \_\_\_\_\_ DP#28 (entry) \_\_\_\_\_ ACTIVITY : \_\_\_\_\_ Unloading main pipes, fit up and welding/DP equipment set up \_\_\_\_\_

For the Month of \_\_\_\_\_ Nov, 2023 \_\_\_\_\_ DATE : \_\_\_\_\_ 25/11/2023 \_\_\_\_\_ TIME: \_\_\_\_\_ 15:00 \_\_\_\_\_

1 Point Area :

2 Drainage Condition



Normal



Abnormal

3 Physical Appearance of Drainage



Drainage Channel obstruction



Water logging in some point



Flooding on th whole area



Other Water logging in the gutter

4 Impact level



Hight



Medium



Low



Not impact

5 Damage



No



Yes .....

6 Status



Improved



Ongonig



No Action

7 Photo



Report by

Approve by

# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## DRAINAGE AND FLOODING CONDITIONS CHECKLIST

LOCATION : DP#24 ACTIVITY : Access road backfill/fence installation/Installation sheet piles for EGAT foundation toe

For the Month of Nov, 2023 DATE : 20/11/2023 TIME: 13:00

1 Point Area :

2 Drainage Condition



Normal



Abnormal

3 Physical Appearance of Drainage



Drainage Channel obstruction



Water logging in some point



Flooding on th whole area



Other ....N/A....

4 Impact level



Hight



Medium



Low



Not impact

5 Damage



No



Yes .....

6 Status



Improved



Ongonig




No Action


7 Photo



Report by



Approve by



# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## DRAINAGE AND FLOODING CONDITIONS CHECKLIST

LOCATION : DP#21, DP#22 (entry) ACTIVITY : Sheet piles install/FOC pull-back, FOC fit up and welding, road repair and compaction

For the Month of Nov, 2023 DATE : 20/11/2023 TIME: 07:00

1 Point Area :

2 Drainage Condition

☒ Normal

☐ Abnormal

3 Physical Appearance of Drainage

☐ Drainage Channel obstruction

☐ Water logging in some point

☐ Flooding on th whole area

☒ Other ....N/A....

4 Impact level

☐ Hight

☐ Medium

☐ Low

☒ Not impact

5 Damage

☒ No

☐ Yes .....

6 Status

☐ Improved


☐ Ongonig

☒ No Action


7 Photo



Report by



Approve by





# Bangpakong – South Bangkok Power Plant Transmission Pipeline Project – Phase 1



## Drainage and flooding conditions Record



December 2023

Location : .....Stock yard..... Activity : .....Stock pipe.....

Date : 13 - December - 2023

Time : 14.30 - 15.30 hrs.

- 1 Point Area : Pipe stock yard at Khao Khan Song
- 2 Drainage Condition ☒ Normal ☐ Abnormal
- 3 Physical Appearance of Drainage ☐ Drainage channel obstruction ☐ Water logging in some point  
☐ Flooding on the whole area ☐ Other .....
- 4 Impact level ☐ Hight ☐ Medium  
☐ Low ☒ Not impact
- 5 Damage ☒ No ☐ Yes .....
- 6 Status ☐ Improved ☐ On going  
☐ No Action
- 7 Photo



# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## DRAINAGE AND FLOODING CONDITIONS CHECKLIST

LOCATION : \_\_\_\_\_ BS#6 \_\_\_\_\_ ACTIVITY : \_\_\_\_\_ Preparing the area for soil concrete activity \_\_\_\_\_

For the Month of \_\_\_\_\_ Dec, 2023 \_\_\_\_\_ DATE : \_\_\_\_\_ 12/12/2023 \_\_\_\_\_ TIME: \_\_\_\_\_ 12:48 \_\_\_\_\_

1 Point Area :

2 Drainage Condition



Normal



Abnormal

3 Physical Appearance of Drainage



Drainage Channel obstruction



Water logging in some point



Flooding on th whole area



Other ....N/A....

4 Impact level



Hight



Medium



Low



Not impact

5 Damage



No



Yes .....

6 Status



Improved



Ongonig




No Action


7 Photo




Report by



Approve by



ภาคผนวก จ-6  
เอกสารประกันภัยโครงการ



**หนังสือรับรองการประกันภัย**  
**กรมธรรม์ประกันการเสี่ยงภัยทุกชนิด (All Risks Policy)**

ในส่วนที่เกี่ยวข้องกับโรงแยกก๊าซธรรมชาติ และส่วนต่อเนื่อง รวมทั้งระบบท่อทางต่างๆ ของ ปตท.

กรมธรรม์เลขที่ : [REDACTED]

ผู้เอาประกันภัย : บริษัท ปตท. จำกัด (มหาชน)

ระยะเวลาเอาประกันภัย : 1 ปี เริ่มจาก 1 ตุลาคม 2565 ถึง  
วันที่ 30 กันยายน 2566 (รวมวันที่ทั้งสองวันด้วย)

ทรัพย์สินที่เอาประกันภัย : ทรัพย์สินในระบบโรงแยกก๊าซธรรมชาติ และส่วนต่อเนื่อง  
รวมถึงอาคาร, สิ่งปลูกสร้างต่างๆ, สต็อก, เนื้อก๊าซ, spare parts  
และทรัพย์สินอื่นๆ รวมถึง ระบบท่อต่างๆทั้งบนบกและในทะเล  
ของ ปตท.

วงเงินคุ้มครองสูงสุด : คุ้มครองทรัพย์สินเสียหาย และธุรกิจหยุดชะงัก  
ในวงเงิน 1,956,000,000 เหรียญสหรัฐ ต่ออุบัติเหตุแต่ละครั้ง

และ ระบบท่อต่างๆทั้งบนบกและในทะเลของ ปตท. ซึ่ง ได้รับความ  
คุ้มครอง 40,000,000 เหรียญสหรัฐ ต่ออุบัติเหตุแต่ละครั้ง สำหรับระบบ  
ท่อบนบก และ 80,000,000 เหรียญสหรัฐ ต่ออุบัติเหตุแต่ละครั้ง สำหรับ  
ระบบท่อในทะเล


เงื่อนไขความคุ้มครอง : การเสี่ยงภัยทุกชนิด คือ ให้ความคุ้มครองทรัพย์สินหรือส่วนหนึ่งส่วนใด  
ของทรัพย์สินที่เอาประกันภัย ที่ได้รับความเสียหายหรือสูญหายจาก  
อุบัติเหตุหรือเหตุการณ์ที่มีได้คาดหมายใดๆ ซึ่งมีได้ระบุยกเว้นไว้  
โดยเฉพาะในกรมธรรม์ประกันภัย ในขณะที่ทรัพย์สินดังกล่าวอยู่ภายใน  
บริเวณที่ระบุไว้ในกรมธรรม์ประกันภัยในระหว่างระยะเวลาที่เอา  
ประกันภัย

ทั้งนี้ขึ้นอยู่กับภายใต้ข้อกำหนดและหรือเงื่อนไขอื่นๆ ของกรมธรรม์  
ออกให้ ณ วันที่ 23 กันยายน 2565



**หนังสือรับรองการประกันภัย**  
**กรมธรรม์ประกันการเสี่ยงภัยทุกชนิด (All Risks Policy)**

ในส่วนที่เกี่ยวข้องกับโรงแยกก๊าซธรรมชาติ และส่วนต่อเนื่อง รวมทั้งระบบท่อทางต่างๆ ของ ปตท.

กรมธรรม์เลขที่ : 

ผู้เอาประกันภัย : บริษัท ปตท. จำกัด (มหาชน)

ระยะเวลาเอาประกันภัย : 1 ปี เริ่มจาก 1 ตุลาคม 2566 ถึง  
วันที่ 30 กันยายน 2567 (รวมวันที่ทั้งสองวันด้วย)

ทรัพย์สินที่เอาประกันภัย : ทรัพย์สินในระบบโรงแยกก๊าซธรรมชาติ และส่วนต่อเนื่อง  
รวมถึงอาคาร, สิ่งปลูกสร้างต่างๆ, สต็อก, เนื้อก๊าซ, spare parts  
และทรัพย์สินอื่นๆ รวมถึง ระบบท่อต่างๆทั้งบนบกและในทะเล  
ของ ปตท.

วงเงินคุ้มครองสูงสุด : คุ้มครองทรัพย์สินเสียหาย และธุรกิจหยุดชะงัก  
ในวงเงิน 1,792,000,000 เหรียญสหรัฐ ต่ออุบัติเหตุแต่ละครั้ง

และ ระบบท่อต่างๆทั้งบนบกและในทะเลของ ปตท. ซึ่ง ได้รับความ  
คุ้มครอง 40,000,000 เหรียญสหรัฐ ต่ออุบัติเหตุแต่ละครั้ง สำหรับระบบ  
ท่อบนบก และ 80,000,000 เหรียญสหรัฐ ต่ออุบัติเหตุแต่ละครั้ง สำหรับ  
ระบบท่อในทะเล

เงื่อนไขความคุ้มครอง : การเสี่ยงภัยทุกชนิด คือ ให้ความคุ้มครองทรัพย์สินหรือส่วนหนึ่งส่วนใด  
ของทรัพย์สินที่เอาประกันภัย ที่ได้รับความเสียหายหรือสูญหายจาก  
อุบัติเหตุหรือเหตุการณ์ที่มีได้คาดหมายใดๆ ซึ่งมีได้ระบุยกเว้นไว้  
โดยเฉพาะในกรมธรรม์ประกันภัย ในขณะที่ทรัพย์สินดังกล่าวอยู่ภายใน  
บริเวณที่ระบุไว้ในกรมธรรม์ประกันภัยในระหว่างระยะเวลาที่เอา  
ประกันภัย

ทั้งนี้ขึ้นอยู่กับภายใต้ข้อกำหนดและหรือเงื่อนไขอื่นๆ ของกรมธรรม์

ออกให้ ณ วันที่ 20 กันยายน 2566





## หนังสือรับรองการประกันภัย

### กรมธรรม์ประกันภัยความรับผิดตามกฎหมายต่อบุคคลภายนอก (Third Party Liability Policy)

ในส่วนที่เกี่ยวข้องกับความรับผิดตามกฎหมายของ ปตท. ต่อความเสียหายของบุคคลภายนอก อันเกิดจากการดำเนินงานของ ปตท.

กรมธรรม์เลขที่ : [REDACTED]

ผู้เอาประกันภัย : บริษัท ปตท. จำกัด (มหาชน)



ระยะเวลาเอาประกันภัย : 1 ปี เริ่มจาก 1 ตุลาคม 2565 ถึง  
วันที่ 30 กันยายน 2566 (รวมวันที่ทั้งสองวันด้วย)

เงื่อนไขความคุ้มครอง : ความรับผิดตามกฎหมายของ ปตท. ต่อความเสียหายของบุคคลภายนอก  
อันเกิดจากการดำเนินงานของ ปตท. ทุกประเภท

รวมถึงการดำเนินงานของโรงแยกก๊าซ ระบบท่อส่งก๊าซทั้งหมด  
และการขนส่งก๊าซปิโตรเลียมเหลวทางท่อ รวมถึงระบบท่อทางต่างๆ  
ของ ปตท. และก่อให้เกิดความเสียหายต่อบุคคลภายนอก

ทุนประกันภัย : 50,000,000 เหรียญสหรัฐ ต่ออุบัติเหตุแต่ละครั้ง

ทั้งนี้ขึ้นอยู่กับภายใต้ข้อกำหนดและหรือเงื่อนไขอื่นๆ ของกรมธรรม์  
ออกให้ ณ วันที่ 23 กันยายน 2565



## หนังสือรับรองการประกันภัย

### กรมธรรม์ประกันภัยความรับผิดตามกฎหมายต่อบุคคลภายนอก (Third Party Liability Policy)

ในส่วนที่เกี่ยวข้องกับความรับผิดตามกฎหมายของ ปตท. ต่อความเสียหายของบุคคลภายนอก อันเกิดจากการดำเนินงานของ ปตท.

กรมธรรม์เลขที่ : 14013-111-230000256

ผู้เอาประกันภัย : บริษัท ปตท. จำกัด (มหาชน)

ระยะเวลาเอาประกันภัย : 1 ปี เริ่มจาก 1 ตุลาคม 2566 ถึง  
วันที่ 30 กันยายน 2567 (รวมวันที่ทั้งสองวันด้วย)

เงื่อนไขความคุ้มครอง : ความรับผิดตามกฎหมายของ ปตท. ต่อความเสียหายของบุคคลภายนอก  
อันเกิดจากการดำเนินงานของ ปตท. ทุกประเภท


รวมถึงการดำเนินงานของโรงแยกก๊าซ ระบบท่อส่งก๊าซทั้งหมด  
และการขนส่งก๊าซปิโตรเลียมเหลวทางท่อ รวมถึงระบบท่อทางต่างๆ  
ของ ปตท. และก่อให้เกิดความเสียหายต่อบุคคลภายนอก



ทุนประกันภัย : 50,000,000 เหรียญสหรัฐ ต่ออุบัติเหตุแต่ละครั้ง

ทั้งนี้ขึ้นอยู่กับภายใต้ข้อกำหนดและหรือเงื่อนไขอื่นๆ ของกรมธรรม์  
ออกให้ ณ วันที่ 20 กันยายน 2566

## ภาคผนวก จ-7



ตัวอย่างเอกสารการตรวจสอบสภาพเครื่องมือ เครื่องจักร  
และอุปกรณ์



	<b>EQUIPMENT &amp; TOOL INSPECTION</b> ตรวจสอบเครื่องมือ และอุปกรณ์ไฟฟ้า	
Form No.: F-SHE-019	Job No.:	Date: 22-06-2023
Project Name: BSPP1		
Report No.: SHE-019		
Equipment Type:	<input type="radio"/> Grinder <input type="radio"/> Hand Saws <input type="radio"/> Bench Drills <input type="radio"/> Water Pump <input type="radio"/> Control Panel Board <input type="radio"/> Main Switch Board <input type="radio"/> Distribution Board <input type="radio"/> Other	
Owner: CPP 4	Model: 3U	
Work Location: Stock yard xp 12	Serial / Reg. No.: 03	
Inspection Date: 22-06-2023	Expire Date: 30-09-2023	



NO. ที่	CHECK LIST รายการตรวจสอบ	CONDITION		REMARK หมายเหตุ
		OK	NOK	
1	Lead Cables ( สายไฟ )	✓		
2	Termination/Power Plug/Socket Plug ( ปลั๊กไฟ )	✓		
3	Earthing/Grounding Wires ( สายดินกระแสแรง )	✓		
4	Guard (Rotating parts) ( ภาชนะครอบ )	✓		
5	Electrical Protection Setting/Rating ( ระบบป้องกันกระแสไฟฟ้า )	✓		
6	Earth leakage Circuit Breaker Test ( อุปกรณ์ป้องกันกระแสไฟฟ้า )	✓		
7	Insulation Test ( การทดสอบฉนวนป้องกันกระแสไฟฟ้า )	✓		
8	Other ( อื่นๆ )			

Name of Inspector / ผู้ตรวจ	(Maintenance Officer)
Signature of Inspector / ส่วน	
Inspection Date / วันที่ตรวจ	
Expiry Date / วันหมดอายุ	
Approved by / อนุมัติให้ใช้	(Safety Officer)
Recommendation :	

	<b>EQUIPMENT &amp; TOOL INSPECTION</b> ตรวจสอบเครื่องมือ และอุปกรณ์ไฟฟ้า	
Form No.: F-SHE-019	Job No.:	Date: 22-06-2023
Project Name: BSPP1		
Report No.: SHE-019		
Equipment Type:	<input type="radio"/> Grinder <input type="radio"/> Hand Saws <input type="radio"/> Bench Drills <input type="radio"/> Water Pump <input type="radio"/> Control Panel Board <input type="radio"/> Main Switch Board <input type="radio"/> Distribution Board <input type="radio"/> Other	
Owner: CPP 4	Model: 3U	
Work Location: Stock yard xp 12	Serial / Reg. No.: 07	
Inspection Date: 22-06-2023	Expire Date: 30-09-2023	

NO. ที่	CHECK LIST รายการตรวจสอบ	CONDITION		REMARK หมายเหตุ
		OK	NOK	
1	Lead Cables ( สายไฟ )	✓		
2	Termination/Power Plug/Socket Plug ( ปลั๊กไฟ )	✓		
3	Earthing/Grounding Wires ( สายดินกระแสแรง )	✓		
4	Guard (Rotating parts) ( ภาชนะครอบ )	✓		
5	Electrical Protection Setting/Rating ( ระบบป้องกันกระแสไฟฟ้า )	✓		
6	Earth leakage Circuit Breaker Test ( อุปกรณ์ป้องกันกระแสไฟฟ้า )	✓		
7	Insulation Test ( การทดสอบฉนวนป้องกันกระแสไฟฟ้า )	✓		
8	Other ( อื่นๆ )			

Name of Inspector / ผู้ตรวจ	(Maintenance Officer)
Signature of Inspector / ส่วน	
Inspection Date / วันที่ตรวจ	
Expiry Date / วันหมดอายุ	
Approved by / อนุมัติให้ใช้	(Safety Officer)
Recommendation :	

GENERATOR INSPECTION CHECK LIST

ตรวจสอบเครื่องกำเนิดไฟฟ้า

Form No.: F-S

Project Name:

Report No.:

Machine Owner : CPP4

Operator : ผู้ควบคุม

Type/Model : 01

Registration No. :

Inspection Date : 22-06-2023

Expire Date : 30-09-2023

Work Location : Stock yard kp 12

สถานที่ทำงาน

No. ที่	CHECK LIST รายการตรวจสอบ	CONDITION			REMARK หมายเหตุ
		OK	NOT OK	N/A	
1	Overall structure are safe โครงสร้างทั้งหมดของเครื่องจักรมีความปลอดภัยมั่นคง	✓			
2	All control bottoms and switches are in good shape and usable ปุ่มและสวิตช์ควบคุมมีสภาพดีและใช้งานได้	✓			
3	Emergency switch is in place สวิตช์ฉุกเฉินอยู่ตำแหน่งเดิม	✓			
4	Distribution point is in good shape and usable จุดแจกจ่ายอยู่ในสภาพดีและใช้งานได้	✓			
5	Equipped with groundable connection point มีจุดเชื่อมต่อสายดิน	✓			
6	All cable are in good shape สายไฟทุกสายมีสภาพดี	✓			
7	Fire extinguisher available ติดตั้งถังดับเพลิงพร้อมใช้งาน	✓			
8	Lifting point or tow point is safe หanger สำหรับยกมีความแข็งแรงปลอดภัย	✓			
9	Engine has no crack, no leak เครื่องยนต์ไม่มีรอยร้าวซึม, ไม่รั่วไหล	✓			
10	Fuel oil Full or Empty, no leak ระดับน้ำมันเชื้อเพลิงเต็มหรือไม้น้ำมัน, ไม่รั่วไหล	✓			
11	Engine oil normal indicator, no leak ระดับน้ำมันเครื่องปกติ, ไม่รั่วไหล	✓			
12	Water coolant Full level, no leak ระดับน้ำหล่อเย็นเครื่องเต็มปกติ, ไม่รั่วหรือแห้ง	✓			

Inspect By



ตรวจเช็คโดย

Position

ตำแหน่ง

Date

วันที่

GENERATOR INSPECTION CHECK LIST

ตรวจสอบเครื่องกำเนิดไฟฟ้า

Form No.: F-S

Project Name:

Report No.:

Machine Owner : CPP4

Operator : ผู้ควบคุม

Type/Model : 02

Registration No. :

Inspection Date : 22-06-2023

Expire Date : 30-09-2023

Work Location : Stock yard kp 12

สถานที่ทำงาน

No. ที่	CHECK LIST รายการตรวจสอบ	CONDITION			REMARK หมายเหตุ
		OK	NOT OK	N/A	
1	Overall structure are safe โครงสร้างทั้งหมดของเครื่องจักรมีความปลอดภัยมั่นคง	✓			
2	All control bottoms and switches are in good shape and usable ปุ่มและสวิตช์ควบคุมมีสภาพดีและใช้งานได้	✓			
3	Emergency switch is in place สวิตช์ฉุกเฉินอยู่ตำแหน่งเดิม	✓			
4	Distribution point is in good shape and usable จุดแจกจ่ายอยู่ในสภาพดีและใช้งานได้	✓			
5	Equipped with groundable connection point มีจุดเชื่อมต่อสายดิน	✓			
6	All cable are in good shape สายไฟทุกสายมีสภาพดี	✓			
7	Fire extinguisher available ติดตั้งถังดับเพลิงพร้อมใช้งาน	✓			
8	Lifting point or tow point is safe หanger สำหรับยกมีความแข็งแรงปลอดภัย	✓			
9	Engine has no crack, no leak เครื่องยนต์ไม่มีรอยร้าวซึม, ไม่รั่วไหล	✓			
10	Fuel oil Full or Empty, no leak ระดับน้ำมันเชื้อเพลิงเต็มหรือไม้น้ำมัน, ไม่รั่วไหล	✓			
11	Engine oil normal indicator, no leak ระดับน้ำมันเครื่องปกติ, ไม่รั่วไหล	✓			
12	Water coolant Full level, no leak ระดับน้ำหล่อเย็นเครื่องเต็มปกติ, ไม่รั่วหรือแห้ง	✓			

Inspect By

ตรวจเช็คโดย

Position

ตำแหน่ง

Date

วันที่



ระบบท่อส่งก๊าซธรรมชาติ



Permit No. 23-EM-0814  
30 Maximum Days Permit for Contractor's Electrical & Vehicle  
180 Maximum Days Permit for PTT's Electrical & Vehicle  
สถานะใบตรวจสอบ: อนุมัติ

ใบตรวจสอบอุปกรณ์ไฟฟ้าและเครื่องยนต์  
(ELECTRICAL & VEHICLE SAFETY INSPECTION REPORT)

เขียนวันที่/Filling Date: 02 สิงหาคม 2566  
พื้นที่ขออนุญาตทำงาน/ Permit Area: พื้นที่บริเวณท่อเขต 9

1. ระยะเวลาที่ใช้งาน/Duration: จากวันที่/From: 17 กรกฎาคม 2566 ถึงวันที่/To: 15 สิงหาคม 2566 รวม/Total: 30 วัน/days

สถานที่ปฏิบัติงาน/Location of work: แนวโครงสร้างท่อก๊าซพระนครศรีอยุธยา DP#21 ( Direct Pipe เชื่อมปลอกท่อ )  
รายละเอียดงาน/Scope of work: Bentonite Pump / ( Direct Pipe เชื่อมปลอกท่อ )

2. ชนิดของอุปกรณ์/Type of Equipment (กรอกโดยผู้ขออนุญาต/Complete by Applicant)

ประเภทอุปกรณ์ไฟฟ้า/Electrical Tool

☐ เครื่องปั่นไฟ

☒ อื่นๆ

สิ่ง/Other:

3. รายละเอียดของอุปกรณ์/Equipment Details (กรอกโดยผู้ขออนุญาต/Complete by Applicant)

ชื่อหรืออุปกรณ์ไฟฟ้า/Electrical Equipment Brand: Herrenknecht รุ่น/Model: H-001  
ทะเบียนรถหรือเลขประจำเครื่อง/Vehicle License or SN: SNP/DP Equipment 018 ผู้ขึ้นหรือผู้รับผิดชอบอุปกรณ์/Driver or Owner: ดิ ชัยภูมิ

4. รายการตรวจสอบทางไฟฟ้า/Electrical Inspection List (กรอกโดยผู้ตรวจสอบ/Complete by Inspector)

รายการตรวจสอบ/Inspection List	ปกติ/Yes	ชำรุด/No	หมายเหตุ/Remark
1. ความเป็นฉนวน/Megger test	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2. ขั้วสายไฟ/Terminal connection	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3. สายไฟหุ้มฉนวน/Cable	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
4. ระบบกราวด์/Earthing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5. สภาพถังหล่อเก็บ, ตัวถัง, หัวแม็ก/Casing, body or power plug	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6. การทำงานของอุปกรณ์/Equipment operating	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7. อุปกรณ์ป้องกันน้ำ/Water proofing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
8. ระบบป้องกันไฟฟ้ารั่วของอุปกรณ์/Leak to ground protection	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
9. สภาพแปรงถ่านของมอเตอร์/Motor carbon brush condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
10. การป้องกันประกายไฟ/Spark protection	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
11. การปิดไฟของกล้องถ่ายรูป/Camera flash disable function	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

5. รายการตรวจสอบเครื่องยนต์/เครื่องยนต์/Vehicle & Engine Inspection List (กรอกโดยผู้ตรวจสอบ/Complete by Inspector)

รายการตรวจสอบ/Inspection List	ปกติ/Yes	ชำรุด/No	หมายเหตุ/Remark
1. สายไฟ, ไฟหน้า, ไฟเลี้ยว, ไฟท้าย, Cable and lighting	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
2. สภาพสวิตช์ การตัดหรือดับเครื่องยนต์/Engine start-stop switch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3. ขั้วแบตเตอรี่/Battery terminal	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
4. ไดนาโม/Dynamo	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
5. สายหัวเทียนและจานจ่าย/Spark plug cable and distributor	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
6. ระบบเบรคมือ, เบรคเท้า และล้อวาง/Handbrake, brake and tries	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
7. สภาพท่อไอเสียและอุปกรณ์ป้องกันลูกไฟ/ท่อไอเสีย / Flame arrestor at exhaust intake	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
8. สภาพซีลอุปกรณ์ป้องกันแรงดัน / High pressure sealing system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Caution: This inspection report must be exhibited emphatically in the workplace area



ระบบท่อส่งก๊าซธรรมชาติ



Permit No. 23-EV-1342  
30 Maximum Days Permit for All Types of Crane  
สถานะใบตรวจสอบ: อนุมัติ

แบบตรวจสอบความปลอดภัยก่อนใช้งานปั้นจั่น  
(CRANE SAFETY INSPECTION REPORT)

เขียนวันที่/Filling Date: 02 สิงหาคม 2566  
พื้นที่ขออนุญาตทำงาน/ Permit Area: พื้นที่บริเวณท่อเขต 9

1. ระยะเวลาที่ใช้งาน/Duration: จากวันที่/From: 24 กรกฎาคม 2566 ถึงวันที่/To: 22 สิงหาคม 2566 รวม/Total: 30 วัน/days

สถานที่ปฏิบัติงาน/Location of work: แนวโครงสร้าง BSP2 DP#21 KP.50 ( ขอบประชิดขั้วโมโนสแต )  
รายละเอียดงาน/Scope of work: Crawler Crane 75 T. (20001)

2. รายละเอียดของปั้นจั่น/Forklift Details (กรอกโดยผู้ขออนุญาต/Complete by Applicant)

แบบปั้นจั่น/Type of Crane: ☐ ล้อยาง / Tires ☒ ดินเผา / Tracks ☒ ติดตั้งประจักษ์ / Mobile Crane ☐ ติดตั้งประจักษ์ / Tower Crane  
ยี่ห้อ/รุ่น/รุ่น/รุ่น/Forklift Model: SANY รุ่นของปั้นจั่น/Forklift Model: SanySC2750a  
ทะเบียนรถ/Car License: Z0001 ผู้ขับขี่/Driver: พรชณต์ แก้วงาม  
ความสามารถในการยกน้ำหนัก/Maximum Lifting Capacity: เมื่อแรงยกสูงสุด/Shortest boom 27 ตัน/Ton เมื่อแขนยกยาวสุด/Longest boom 1 ตัน/Ton

3. รายการตรวจสอบ/Inspection List (กรอกโดยผู้ตรวจสอบ/Complete by Inspector)

รายการตรวจสอบ/Inspection List	แนวทางตรวจสอบ	ปกติ/Yes	ชำรุด/No
1.1 การใช้งานและทดสอบ ตามกฎหมาย โดยช่างวิศวกรเครื่องกล (ถก.) / Certified and valid document by professional mechanical engineer		<input checked="" type="checkbox"/>	<input type="checkbox"/>
1.3 ผู้ปฏิบัติงานใช้งาน และกรอกข้อมูลตาม/ Instruction manual and lifting calculation available		<input checked="" type="checkbox"/>	<input type="checkbox"/>
1.2 ผู้ปฏิบัติงานก่อนเริ่มงาน, 2. ผู้ปฏิบัติงานและผู้บังคับงาน, 3. ผู้สังเกตการณ์, 4. ผู้ควบคุมปั้นจั่น/Valid license for crane operator		<input checked="" type="checkbox"/>	<input type="checkbox"/>
2.2 ไฟสัญญาณไฟ และไฟสัญญาณไฟ/Installed flame arrestor and do leak at exhaust pipe		<input checked="" type="checkbox"/>	<input type="checkbox"/>
2.1 ใช้งานโดยไม่ปิด ไม่ปิดไม่รั่วไหล สภาพท่อปกติ/Smoothly run and no leak		<input checked="" type="checkbox"/>	<input type="checkbox"/>
2.3 ส่วนที่หมุนได้และอาจเป็นอันตรายได้/Unsafe moving parts are guarded		<input checked="" type="checkbox"/>	<input type="checkbox"/>
3.4 ล้อ 3 ชิ้น ล้อบน และไม่มีล้อบนหรือล้อบน/No missing or loose nuts or bolts		<input checked="" type="checkbox"/>	<input type="checkbox"/>
3.5 การทดสอบการดันไม่หยุดในทันที และมั่นคง/Rotate and stop smoothly		<input checked="" type="checkbox"/>	<input type="checkbox"/>
3.2 รางล้อรถ และรางล้อรถ และรางล้อรถ/Free of distortion, crack, wear and metal plates are available		<input checked="" type="checkbox"/>	<input type="checkbox"/>
3.3 อุปกรณ์ควบคุมระบบ และแหล่งพลังงาน/Leveling indicator devices working properly		<input checked="" type="checkbox"/>	<input type="checkbox"/>
3.1 แหล่งพลังงานหรือพลังงาน/Deck free of corrosion and damage		<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.2 ชิ้นส่วนที่ใช้การยก/ยก, tilt and lower operates smoothly		<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.4 ระบบฉุกเฉินในการใช้การ/Emergency stop functions properly		<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.1 ไม่มีการบิดเบี้ยว หรือหัก/No damage, worn, bent or crack		<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.3 การยกขึ้น ชักเข้า-ออก ทำได้สะดวก ไม่ติดขัด		<input checked="" type="checkbox"/>	<input type="checkbox"/>
5.2 จุดต่อเชื่อมไม่หลุดล่อน มีรหัส 2 จุด/Connection points are tighten with at least two damps		<input checked="" type="checkbox"/>	<input type="checkbox"/>
5.3 ลวดสายไม่เกิน 3 เส้น ในกรณีเดียวกัน/Less than 3 wires in one strand of a rope damage		<input checked="" type="checkbox"/>	<input type="checkbox"/>
5.1 ไม่พบปัญหาเกี่ยวกับสภาพ/In good condition without kinking, broken or twist		<input checked="" type="checkbox"/>	<input type="checkbox"/>
6.2 จุดหมุนมีขนาดพอดีกับขนาด ไม่พบปัญหา/Correct size and not loose		<input checked="" type="checkbox"/>	<input type="checkbox"/>
6.1 ไม่พบปัญหาเกี่ยวกับสภาพ/No deformation, crack or excessive corrosion		<input checked="" type="checkbox"/>	<input type="checkbox"/>
7.1 ไม่พบปัญหาเกี่ยวกับสภาพ/No deformation or excessive throat		<input checked="" type="checkbox"/>	<input type="checkbox"/>
7.2 ไม่พบปัญหาเกี่ยวกับสภาพ/No deformation or excessive throat		<input checked="" type="checkbox"/>	<input type="checkbox"/>
8.2 ความดันไฮดรอลิก/ Hydraulic pressure is normal and functioning		<input checked="" type="checkbox"/>	<input type="checkbox"/>
8.1 เมื่อมีการยกน้ำหนักเกิน หรือลดลงเกินกว่ากำหนด และขณะนั้นน้ำหนักยังใช้งาน/When operating over capacity or exceeding boom length limit		<input checked="" type="checkbox"/>	<input type="checkbox"/>
9.1 ไม่พบปัญหาเกี่ยวกับสภาพ/ 1 ถึง/1 dry chemical extinguisher onsite		<input checked="" type="checkbox"/>	<input type="checkbox"/>

4. ผลการตรวจสอบ/Inspection Result: [ ] ใช้งานได้/Approve [ ] ใช้งานไม่ได้/Reject [ ] ไม่เลือก/Cancel วันที่/Date: ---

Caution: This inspection report must be exhibited emphatically in the workplace area



Permit No. 23-HV-1080  
30 Maximum Days Permit for Contractor's Electrical & Vehicle  
180 Maximum Days Permit for PTT's Electrical & Vehicle  
สถานะใบตรวจสภาพ: อนุมัติ 02:47



Permit No. 23-MA-2103  
30 Maximum Days Permit for Contractor's Engine  
180 Maximum Days Permit for PTT's Engine  
สถานะใบตรวจสภาพ: อนุมัติ 02:45

แบบตรวจสอบความปลอดภัยก่อนใช้งานรถบรรทุก (HEAVY VEHICLE SAFETY INSPECTION REPORT)

ใบตรวจสภาพรถบรรทุก (ENGINE SAFETY INSPECTION REPORT)

1. รายละเอียดการใช้งาน/Duration: จากวันที่/From: 07 กรกฎาคม 2566 ถึงวันที่/To: 05 สิงหาคม 2566 รวม/Total: 30 วัน/days  
สถานที่ปฏิบัติงาน/Location of work: แนวโครงสร้างท่าอากาศยาน BSP2 KP51 ( ขอบประชิดรันเวย์ )  
รายละเอียดงาน/Scope of work: \*\*SIDE BOOM 70 T./P00019 ( S704 )\*\*  
สถานะใบตรวจสภาพ: อนุมัติ 02:47

1. รายละเอียดการใช้งาน/Duration: จากวันที่/From: 21 กรกฎาคม 2566 ถึงวันที่/To: 19 สิงหาคม 2566 รวม/Total: 30 วัน/days  
สถานที่ปฏิบัติงาน/Location of work: แนวท่าอากาศยาน BSP2 , ปตท เขต 9 (ขอบประชิดรันเวย์ DP#21)  
รายละเอียดงาน/Scope of work: Hydraulic Jacks (STS) No.87960

2. รายละเอียดของรถบรรทุก/Type of Equipment (กรอกโดยผู้ส่งมอบ/Complete by Applicant)  
ประเภทของรถบรรทุก/Type of Heavy Vehicle: ☐ ล้อยาง / Tires ☒ ดันขบวน / Tracks ☐ เคลื่อนย้ายด้วยการขนส่ง / Transported by truck:  
ข้อมูลรถบรรทุก/Details of Heavy Vehicle: XCMG XGP70  
ทะเบียนรถ/Car License: XUG000707JP00019 ผู้ขับขี่/Driver: สกล เต็มบริสม


2. รายละเอียดของรถบรรทุก/Type of Equipment (กรอกโดยผู้ส่งมอบ/Complete by Applicant)  
ประเภทของรถบรรทุก/Type of Heavy Vehicle: ☐ ขุดรื้อ/Excavator ☐ เครื่องเจาะ ☐ เครื่องเชื่อมแก๊ส ☐ เครื่องตัดแก๊ส ☐ บิลล์ไฮดรอลิก ☒ เครื่องยนต์ ☐ อื่นๆ

รายการตรวจสอบ/Inspection List	พบ/Yes	ไม่พบ/No	N/A
1. สภาพโครงสร้าง/Overall condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. การควบคุม/Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. เครื่องยนต์/Engine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. ไฟส่องสว่างและสัญญาณเตือน/Lights and signal	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. ระบบไฮดรอลิก/Hydraulic	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. การทำงานของเบรก/Brake system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. ระบบห้ามล้อ/Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. ล้อยางหรือล้อรถ/Tires or tracks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. ถังน้ำมันเชื้อเพลิง/Fuel tank	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. ระบบไฟฟ้า/Electrical	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. อุปกรณ์ดับเพลิง/Fire extinguisher	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

3. รายละเอียดของอุปกรณ์/Equipment Details (กรอกโดยผู้ส่งมอบ/Complete by Applicant)  
ชื่ออุปกรณ์/Equipment Name: KANTO-KT-TF-30-AUTO  
ทะเบียนรถหรือเลขประจำตัว/Vehicle License or SN: 87960 ผู้ขับขี่หรือผู้ส่งมอบอุปกรณ์/Driver or Owner: วีรพงษ์ พาพิณ

รายการตรวจสอบ/Inspection List	พบ/Yes	ไม่พบ/No	N/A
1. สภาพไฟ, ไฟหน้า, ไฟเลี้ยว, ไฟท้าย, Cable and lighting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. สภาพตัวถัง การติดหรือล่อนของเครื่องยนต์/Engine start-stop switch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. ชั๊มป์แบตเตอรี่/Battery terminal	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. ไดนาโม/Dynamo	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. สายหัวเข็มและสายจ่าย/Spark plug cable and distributor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. ระบบเบรกมือ, เบรคเท้า และสาย/Handbrake, brake and tris	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. สภาพท่อไอเสียและอุปกรณ์ป้องกันท่อไอเสีย / Flame arrestor at exhaust intake	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. สภาพซีลอุปกรณ์ป้องกันแรงดัน / High pressure sealing system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

4. รายการตรวจสอบเครื่องยนต์/Engine Inspection List (กรอกโดยผู้ตรวจสอบ/Complete by Inspector)  
ผลการตรวจสอบ/Inspection Result: ☐ ใช้งานได้/Approve ☐ ใช้งานไม่ได้/Reject ☐ ไม่ผ่าน/Cancel วันที่/Date: ---



Caution: This inspection report must be exhibited emphatically in the workplace area

Caution: This inspection report must be exhibited emphatically in the workplace area



สถานที่ปฏิบัติงาน/Location of work: **แนวโครงสร้างท่อก๊าซธรรมชาติ DP#21 (ขอยุติการใช้งาน)**  
รายละเอียดงาน/Scope of work: **Generator 810 KVA \*810-004\*/ (Direct Pipe ขุดลอกแม่น้ำเจ้าพระยา)**

2. ชื่อของอุปกรณ์/Type of Equipment (กรอกโดยผู้ตรวจสอบ/Complete by Applicant)  
ประเภทอุปกรณ์ไฟฟ้า/Electrical Tool  
☒ เครื่องปั่นไฟ  
☐ อื่นๆ  
อื่นๆ/Other:

3. รายละเอียดของอุปกรณ์/Equipment Details (กรอกโดยผู้ตรวจสอบ/Complete by Applicant)  
ชื่อหรืออุปกรณ์ไฟฟ้า/Electrical Equipment Brand: **MINAMI** รุ่นอุปกรณ์ไฟฟ้า/Electrical Equipment Model: **Mitsubishi S12A2-PTA**  
ทะเบียนหรือหมายเลขประจำตัว/Vehicle License or SN: **22575 (810-004)** ผู้ขับขี่หรือผู้ควบคุมอุปกรณ์/Driver or Owner: **มี 3 คน**

รายการตรวจสอบทางไฟฟ้า/Electrical Inspection List (กรอกโดยผู้ตรวจสอบ/Complete by Inspector)			
รายการตรวจสอบ/Inspection List		ปกติ/Yes	ผิดปกติ/No
1. ความสมบูรณ์/Megger test		<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. ขั้วสายไฟ/Terminal connection		<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. สายไฟหุ้มฉนวน/Cable		<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. ระบบกราวด์/Earthing		<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. สภาพถังเก็บ, ถัง, หีบฉนวน/Case, body or power plug		<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. การทำงานของอุปกรณ์/Equipment operating		<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. อุปกรณ์ป้องกันน้ำ/Water proofing		<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. ระบบป้องกันฟ้าผ่า/สายดิน/Leak to ground protection		<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. สภาพแปรงถ่านมอเตอร์/Motor carbon brush condition		<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. การป้องกันการเกิดประกายไฟ/Spark protection		<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. การปิดไฟของกล้องถ่ายรูป/Camera flash disable function		<input checked="" type="checkbox"/>	<input type="checkbox"/>

5. รายการตรวจสอบเครื่องยนต์/เครื่องยนต์/Vehicle & Engine Inspection List (กรอกโดยผู้ตรวจสอบ/Complete by Inspector)			
รายการตรวจสอบ/Inspection List		ปกติ/Yes	ผิดปกติ/No
1. สายไฟ, ไฟหน้า, ไฟเลี้ยว, ไฟท้าย, Cable and lighting		<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. สภาพสวิตช์ การสตาร์ทเครื่องยนต์/Engine start-stop switch		<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. ขั้วแบตเตอรี่/Battery terminal		<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. ไดนาโม/Dynamo		<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. สายหัวเทียนและสายจาก/Spark plug cable and distributor		<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. ระบบเบรก, เบรกเท้า และล้อ/Handbrake, brake and tries		<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. สภาพท่อไอเสียและอุปกรณ์ป้องกันไฟไหม้/Flame arrestor at exhaust intake		<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. สภาพซีลอุปกรณ์ป้องกันแรงดัน / High pressure sealing system		<input checked="" type="checkbox"/>	<input type="checkbox"/>

6. 

Signature: \_\_\_\_\_  
Tel: \_\_\_\_\_

Caution: This inspection report must be exhibited emphatically in the workplace area

Worley

CPP

MOBILE CRANE INSPECTION CHECK LIST

ตรวจสอบรถเครน/รถยก


Form No.: F-SHE-016


Job No.:


Date: **21-09-2023**


Project Name: Bangkok - South Bangkok Power Plant Transmission Pipeline Project - Phase 1

Report No.: SHE-016

Machine Owner: 

Type/Model: 

Inspection Date: 

Work Location: 

No.		CHECK LIST	CONDITION		REMARK
ที่		รายการตรวจสอบ	OK	NOK	หมายเหตุ
1		Operator's condition (สภาพคนขับ)	✓		
2		Anti Block Device (เบรกอัตโนมัติ)		✓	
3		Slewing Alarm (สัญญาณเตือนขอลาก)		✓	
4		Reversing Alarm with Flashing Light (ไฟกะพริบ, สปอร์ตไลท์)	✓		
5		Boom Angle Indicator (สัญญาณเตือนมุมขอลาก)		✓	
6		Overhoist Cut-out / Alarm System (สัญญาณเตือนน้ำหนักเกิน)	✓		
7		Fire Extinguisher in cab (ถังดับเพลิงอยู่ในรถ)	✓		
8		Slings / Wire Condition (สายพ่วงสลิง, สลิง, สลิงสัง)	✓		
9		Crane Hook with Safety Latch (สายพ่วงhook และสลักกับสลิงหลุด)	✓		
10		Tyres Condition (สภาพยาง)	✓		
11		Out Rigger (ขาตั้งเครน)	✓		
12		Brake System (ระบบเบรก)	✓		
13		Standing Area (สภาพพื้นที่ตั้งเครน)	✓		
14		Exhaust & Noise (ควันและเสียง)	✓		
15		Flagman (ผู้ให้สัญญาณธง)	✓		
16		Operator Qualification (ใบรับรองความสามารถในการขับขี่)	✓		

Inspect By: 

Position: 

Date: \_\_\_\_\_

วันที่: \_\_\_\_\_



Permit No. 23-SE-1229  
30 Maximum Days Permit for Contractor's Electrical  
180 Maximum Days Permit for PTT's Electrical  
สถานะใบตรวจสภาพ: อนุมัติ

ในระบบส่งกำลังทางธรณีวิทยา  
ใบตรวจสภาพอุปกรณ์ความปลอดภัย  
(SAFETY INSPECTION REPORT)

1. ระยะเวลาที่ใช้งาน/Duration: จากวันที่/From: 16 กันยายน 2566 ถึงวันที่/To: 15 ตุลาคม 2566 รวม/Total: 30 วัน/days

สถานที่ปฏิบัติงาน/Location of work: เขตก่อสร้าง BSP2 DP#21 KP.50 (ขอมประสิทธิ์สูบน้ำ)

รายละเอียดงาน/Scope of work: Pocket Dosimeter - G1167070

2. ชนิดของอุปกรณ์/Type of Equipment (กรอกโดยผู้ขออนุญาต/Complete by Applicant)  
ประเภทอุปกรณ์ความปลอดภัย/Safety Tool

- ☐ อุปกรณ์ป้องกันศีรษะ  
☐ อุปกรณ์ป้องกันหู  
☒ อื่น ๆ

อื่นๆ/Other: เครื่องวัดรังสีประจำตัวบุคคล

3. รายละเอียดของอุปกรณ์/Equipment Details (กรอกโดยผู้ขออนุญาต/Complete by Applicant)

ชื่อหรืออุปกรณ์/Equipment Brand: ARROW-TECH INC W-138  
ทะเบียนหรือเลขประจำเครื่อง/Vehicle License or SN: G1167070 ผู้ยื่นหรือผู้รับผิดชอบอุปกรณ์/Driver or Owner: ชัยวัฒน์พงษ์ รุ่งนิมรด์

4. รายการตรวจสอบอุปกรณ์ความปลอดภัย/Safety Inspection List (กรอกโดยผู้ตรวจประเมิน/Complete by Inspector)

5. ผลการตรวจสอบ/Inspection Result: [ ] ใช้งานได้/Approve [ ] ใช้งานไม่ได้/Reject [ ] ยกเลิก/Cancel วันที่/Date: ---

Initials	ลงนามในระบบแล้ว	Applicant	Initials	ลงนามในระบบแล้ว	Inspector	Initials	ลงนามในระบบแล้ว	Approver
( นรภัฏพัทธ์ สุจริต )			( นายณัฐพงษ์ เรืองแก้ว )			( นายอนุพงษ์ บางเขียว )		
Department			Department	ณ.ปท.9-1		Department	ณ.ปท.9-1	
Tel. 0932644498			Tel. 0632657878			Tel. 0848744117		

Caution: This inspection report must be exhibited emphatically in the workplace area



HEAVY MACHINE/TRUCK INSPECTION

ตรวจสอบเครื่องจักร/รถบรรทุก

Contract No.: PTT.TEC./2/86/65

Form No.: F-SHE-015

Date: 20/10/66

Project Name: Bangpakong - South Bangkok Power Plant Transmission Pipeline Project - Phase 1

Report No.:


Type/Model: <input checked="" type="checkbox"/> Excavator <input type="checkbox"/> Grader	Opn. <input type="checkbox"/>
<input type="checkbox"/> Dump Truck <input type="checkbox"/> Water truck	Rep. <input type="checkbox"/>
<input type="checkbox"/> Compactor Roller <input type="checkbox"/> Vibro Hammer	Ins. <input type="checkbox"/>
Inspection Date: 20/10/66	Exp. <input type="checkbox"/>
วันที่ตรวจสอบ	วันที่
Work Location: KPD	
สถานที่ทำงาน	

No. / ลำดับ	CHECK LIST รายการตรวจสอบ	CONDITION		REMARK หมายเหตุ
		OK	N/A	
1	Handrails / Guards ( Provided, Painted ) ( ราวกั้นเหล็ก / ฝาดรอม / สลากลัด )	<input checked="" type="checkbox"/>		
2	Windows / Glass ( Clear, No cracks, Mirrors ) ( หน้าต่าง /กระจก / ใส, ไม่ร้าว )	<input checked="" type="checkbox"/>		
3	Body & Structure ( ตัวถัง / โครงสร้าง )	<input checked="" type="checkbox"/>		
4	Boom Structure ( Stops Provided ) ( โครงแขน )	<input checked="" type="checkbox"/>		
5	Hooks & Block ( Safety Latch ) ( ตะขอ, สลักยึด )	<input checked="" type="checkbox"/>		
6	Cable drum, Guides & Sheaves ( กระบวยถัก, คสลึง, สลักยึด )	<input checked="" type="checkbox"/>		
7	Rigging Equipment ( Wire rope, shackles, slings ) ( อุปกรณ์ขั้ว, เชือกคล้อง, ตะขอคล้อง, สลึง )	<input checked="" type="checkbox"/>		
8	Tires/Wheels/Track conditions (สภาพล้อยาง/ตีนตะขาน)	<input checked="" type="checkbox"/>		
9	Hydraulic hoses ( สายไฮดรอลิก )	<input checked="" type="checkbox"/>		
10	Leaks ( Oil, Hydraulic, Fuel ) ( การรั่วของ น้ำมัน, ไฮดรอลิก, เชื้อเพลิง )	<input checked="" type="checkbox"/>		
11	Refueling system ( ระบบส่งกำลัง )	<input checked="" type="checkbox"/>		
12	Cab controls ( readable, operable ) ( พวงมาลัย )	<input checked="" type="checkbox"/>		
13	Fire extinguisher ( มีถังดับเพลิง )	<input checked="" type="checkbox"/>		
14	Main light/Signal light in front/back conditions (สัญญาณไฟด้านหน้า/ด้านหลัง)	<input checked="" type="checkbox"/>		
15	Mirror (กระจกมองหลัง)	<input checked="" type="checkbox"/>		
16	Revolving light (ไฟหมุน)	<input checked="" type="checkbox"/>		
17	Revers alarm (สัญญาณถอยหลัง)	<input checked="" type="checkbox"/>		
18		<input checked="" type="checkbox"/>		

PICTURE OF EQUIPMENT

Comment :

Inspect By ตำแหน่ง วันที่



HEAVY MACHINE/TRUCK INSPECTION

ตรวจสอบเครื่องจักร/รถบรรทุก

Contract No.: PTT.TEC./2/86/65

Form No.: F-SHE-015

Date: 16/10/56

Project Name: Bangpakong - South Bangkok Power Plant Transmission Pipeline Project - Phase 1

Report No.:

Type/Model:   
ชนิด/รุ่นเครื่องจักร

☐ Excavator ☐ Grader ☐ Water truck ☐ Vibro Hammer ☐ Compactor Roller

Operator:   
ผู้ควบคุมเครื่องจักร

Register:   
ทะเบียนรถ

Expire:   
วันหมดอายุ

Inspection Date:   
วันที่ตรวจสอบ

Work Location:   
สถานที่ทำงาน

No. ที่	CHECK LIST รายการตรวจสอบ	CONDITION		REMARK หมายเหตุ
		OK	N/A	
1	Handrails / Guards ( Provided, Painted ) ( ราวกันตก / ฝาครอบ / สภาเสี )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2	Windows / Glass ( Clear, No cracks, Mirrors ) ( หน้าต่าง /กระจก / ใส , ไม่มีรอยร้าว )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3	Body & Structure ( ตัวถัง / โครงสร้าง )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
4	Boom Structure ( Stops Provided ) ( โครงแขน )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5	Hooks & Block ( Safety Latch ) ( ตะขอ , สลักกรั้ว )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6	Cable drum, Guides & Sheaves ( กระบอกสาย , กิ่ง , สลักยึด )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7	Rigging Equipment ( Wire rope, shackles, slings ) ( อุปกรณ์ร้ง , เชือกคึง , ตะขอคล้อง , สลิง )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
8	Tires/Wheels/Track conditions (สภาพล้อยาง/ตีนตะขาน)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
9	Hydraulic hoses ( สายไฮดรอลิก )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
10	Leaks ( Oil, Hydraulic, Fuel ) ( การรั่วของ น้ำมัน ,ไฮดรอลิก,เชื้อเพลิง )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
11	Refueling system ( ระบบส่งกำลัง )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
12	Cab controls ( readable, operable ) ( พ้องควบคุม )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
13	Fire extinguisher ( มีถังดับเพลิง )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
14	Main light/Signal light in front/back conditions (สัญญาณไฟด้านหน้า/ด้านหลัง)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
15	Mirror (กระจกมองหลัง)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
15	Revolving light (ไฟหมุน)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
16	Revers alarm (สัญญาณถอยหลัง)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
17				
18				

Comment :

Inspect By  
ตรวจสอบโดย

Position  
ตำแหน่ง


Date  
วันที่

PICTURE OF EQUIPMENT

Inspect By  
ตรวจสอบโดย

Position  
ตำแหน่ง

Date  
วันที่



HEAVY MACHINE/TRUCK INSPECTION

ตรวจสอบเครื่องจักร/รถบรรทุก

Contract No.: PTT.TEC./2/86/65

Form No.: F-SHE-015

Date: 10/11/2023

Project Name: Bangpakong - South Bangkok Power Plant Transmission Pipeline Project - Phase 1

Report No.:

Type/Model:   
ชนิด/รุ่นเครื่องจักร

☒ Excavator ☐ Grader ☐ Water truck ☐ Vibro Hammer ☐ Compactor Roller

Operator:   
ผู้ควบคุมเครื่องจักร

Register:   
ทะเบียนรถ

Expire:   
วันหมดอายุ

Inspection Date:   
วันที่ตรวจสอบ

Work Location:   
สถานที่ทำงาน

No. ที่	CHECK LIST รายการตรวจสอบ	CONDITION		REMARK หมายเหตุ
		OK	N/A	
1	Handrails / Guards ( Provided, Painted ) ( ราวกันตก / ฝาครอบ / สภาเสี )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2	Windows / Glass ( Clear, No cracks, Mirrors ) ( หน้าต่าง /กระจก / ใส , ไม่มีรอยร้าว )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3	Body & Structure ( ตัวถัง / โครงสร้าง )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
4	Boom Structure ( Stops Provided ) ( โครงแขน )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5	Hooks & Block ( Safety Latch ) ( ตะขอ , สลักกรั้ว )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6	Cable drum, Guides & Sheaves ( กระบอกสาย , กิ่ง , สลักยึด )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7	Rigging Equipment ( Wire rope, shackles, slings ) ( อุปกรณ์ร้ง , เชือกคึง , ตะขอคล้อง , สลิง )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
8	Tires/Wheels/Track conditions (สภาพล้อยาง/ตีนตะขาน)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
9	Hydraulic hoses ( สายไฮดรอลิก )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
10	Leaks ( Oil, Hydraulic, Fuel ) ( การรั่วของ น้ำมัน ,ไฮดรอลิก,เชื้อเพลิง )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
11	Refueling system ( ระบบส่งกำลัง )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
12	Cab controls ( readable, operable ) ( พ้องควบคุม )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
13	Fire extinguisher ( มีถังดับเพลิง )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
14	Main light/Signal light in front/back conditions (สัญญาณไฟด้านหน้า/ด้านหลัง)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
15	Mirror (กระจกมองหลัง)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
15	Revolving light (ไฟหมุน)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
16	Revers alarm (สัญญาณถอยหลัง)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
17				
18				

Comment :

Inspect By  
ตรวจสอบโดย

Position  
ตำแหน่ง

Date  
วันที่

PICTURE OF EQUIPMENT

Inspect By  
ตรวจสอบโดย

Position  
ตำแหน่ง

Date  
วันที่

REF : PD.034/2566

DATE : 7 November 2023

### TO WHOM IT MAY CONCERN

This is to certify that Mr. Jirayut Khamchana has been employed by MTS Machinery Co., Ltd. As Excavator Operator since 11 October 2021.

During this period he has worked efficiently, been punctual, reliable and skilled to meet our client satisfaction.

#### Working experiences


- CPP's oil pipeline installation at Chaiyaphum - Khon Kaen 1 year 2021-2022
- Laying gas pipes of Leto Company Pathum Thani Province 1 year 2022-2023

The driver has passed the MTS backhoe control test.

We hope that he will have a progressive and prosperous future and wish him continued success.

Your Faithfully

MTS MACHINERY CO., LTD.



Assistant Sales & Rental Department Manager

### รายงานการทดสอบส่วนประกอบและอุปกรณ์สำหรับเครื่องจักรกลหนัก ตามประกาศกรมสวัสดิการและคุ้มครองแรงงาน กระทรวงแรงงานและสวัสดิการสังคม

ข้าพเจ้า นายทิมชัย ..... อายุ ..... 49 ..... ปี  
ที่อยู่เลขที่ ..... ตำบลแดง ..... ลำไต่  
อำเภอ/เขต ..... จังหวัด ..... กรุงเทพมหานคร ..... โทร. ....  
สถานที่ทำงาน ..... เลขที่ .....  
ครอบครัว/ชื่อ ..... บิดา ..... มารดา .....  
ข้าพเจ้า ..... จังหวัด ..... กรุงเทพมหานคร .....  
ได้รับใบอนุญาตประกอบวิชาชีพวิศวกรรมควบคุม สาขา วิศวกรรมเครื่องกล พ.ศ. ๒๕๕๒  
ระดับ ..... ภาควิชา ..... เลขที่ ..... 17233 ..... วันที่หมดอายุ ..... 17 กันยายน พ.ศ. 2571 .....  
ใบสำคัญการขึ้นทะเบียนเป็นผู้ให้บริการทดสอบเครื่องจักร ใบสำคัญเลขที่ ..... ๓๐ .....  
จึงไม่ได้ผู้จะทางถูกส่งพักไว้ใบอนุญาตชั่วคราวเพื่อถูกพักก่อนใบอนุญาต  
ข้าพเจ้าได้ทำการทดสอบส่วนประกอบและอุปกรณ์ของเครื่องจักรที่ใช้งาน

☐ บุคลากร ☒ ก่อสร้าง ☐ อื่นๆระบุ  
ของนิติบุคคล ..... บริษัท เอ็มทีเอส แมชีนเนอร์รี่ จำกัด ..... เจ้าของผู้จัดการ ..... บริษัท เอ็มทีเอส แมชีนเนอร์รี่ จำกัด .....  
ที่อยู่เลขที่ ..... 1758/4 ..... หมู่ ..... ๓ ..... ตำบล/แขวง ..... พระโขนง .....  
อำเภอ/เขต ..... พระโขนง ..... จังหวัด ..... กรุงเทพมหานคร ..... โทรศัพท์ ..... 02 332 0061 - 3 .....

ข้าพเจ้าได้ทำการตรวจสอบส่วนประกอบและอุปกรณ์เครื่องจักรกลหนัก ตามรายการตรวจสอบที่ระบุไว้ในเอกสารแนบท้าย  
พร้อมทั้งได้ปรับปรุงแก้ไขส่วนที่ชำรุดหรือบกพร่องจนใช้งานได้ถูกต้องปลอดภัย และขอรับรองว่าส่วนประกอบและอุปกรณ์ของ  
เครื่องจักรกลหนัก เครื่องจักรนี้สามารถใช้งานได้เป็นอย่างดีปลอดภัย ตามกฎหมายว่าด้วยความปลอดภัยในการทำงานเกี่ยวกับเครื่องจักรกล  
หนัก กรมสวัสดิการและคุ้มครองแรงงาน กระทรวงแรงงานและสวัสดิการสังคม

เมื่อวันที่ ..... 8 พฤศจิกายน พ.ศ. 2566 ..... วันหมดอายุ ..... 7 กุมภาพันธ์ พ.ศ. ๖๖



Signature of Jirayut Khamchana

ตำแหน่งหน้าที่

รายการทดสอบ

1. ประเภท ☒ EXCAVATOR ☐ WHEEL EXCAVATOR ☐ WHEEL LOADER ☐ SKID STEER ☐ COMPACTOR ☐ TRACK TYPE TRACTOR

2. ข้อมูลเครื่องจักร  
ยี่ห้อ ..... CATERPILLAR.....รุ่น..... 320D2 GC..... หมายเลข ..... 7.202.7  
E/N..... 2W2-02327 .....น้ำหนัก ..... 20 TONS.....ผู้ผลิต ..... CATERPILLAR .....

3. สภาพโครงสร้าง  
3.1 สภาพโครงสร้างตัวเครื่องจักร ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....  
3.2 สภาพพรมตีนค้อน ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....  
3.3 สภาพของเบ็ดค้อนและหน้เข้า ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....

4. มีการตรวจซ่อมเครื่องจักร  
4.1 หลังประกอบเสร็จ ☒ มี ☐ ไม่มี  
4.2 หลังซ่อมส่วนสำคัญ ☒ มี ☐ ไม่มี  
4.3 หลังฉีดอุทิมหตุ ☒ มี ☐ ไม่มี  
4.4 หลังหยุดการใช้งานเกิน 6 เดือน ☒ มี ☐ ไม่มี



5. ตำแหน่งเครื่องชนค้

5.1 ระบบหล่อลื่น ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....  
5.2 ระบบน้ำมันเชื้อเพลิง ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....  
5.3 ระบบระบบความร้อน ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....  
5.4 ระบบไฮดรอลิก ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....  
5.5 ระบบการทำงาน (อัตราเร่ง,รอบต่อเครื่องชนค้) ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....  
5.6 ระบบหล่อเย็น ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....  
5.7 เบตเตอร์และชิ้นเบตเตอร์ ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....

6. ระบบเบรก  
6.1 เบรคห้ามล้อ ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....  
6.2 เบรคกับดวย ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....

7. ระบบไฮดรอลิก  
7.1 ระดับน้ำมันไฮดรอลิก / ภูเขาต้อน ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....  
7.2 สภาพพื่อน้ำมัน สายน้ำมันและข้อต่อ ☒ ดีเยี่ยม ☐ ไม่เรียบร้อย(ระบุ).....



7.3 กระบอกลีโตรลิตเสวสัวไลตรอลิก

☒ เรียบร้อย

☐ ไม่เรียบร้อย(ระบุ).....

7.4 ปีนไลตรอลิกเสวสัวไลตรอลิก

☒ เรียบร้อย

☐ ไม่เรียบร้อย(ระบุ).....

8. ระบบควบคุมการทำงาน

8.1 ชุดควบคุมการเดินเท้า – ตอนหลัง

☒ เรียบร้อย

☐ ไม่เรียบร้อย(ระบุ).....

8.2 ชุดควบคุมการเดิน

☒ เรียบร้อย

☐ ไม่เรียบร้อย(ระบุ).....

8.3 ชุดควบคุมส่วนอุปกรณ์การทำงาน

☒ เรียบร้อย

☐ ไม่เรียบร้อย(ระบุ).....

9. สัญญาณเสียงและแสงไฟเพื่อขณะปฏิบัติงาน

☒ เรียบร้อย

☐ ไม่เรียบร้อย(ระบุ).....

10. ระบบไฟส่องสว่าง

☒ เรียบร้อย

☐ ไม่เรียบร้อย(ระบุ).....

11. ส่วนที่หมุนได้ถ้าจำเป็นอันตรามีไฟครอปปิด (Guard)

☒ เรียบร้อย

☐ ไม่เรียบร้อย(ระบุ).....

12. ข้อโยยี่ห้อมีฝาทรงหรือฉนวนหุ้ม

☒ เรียบร้อย

☐ ไม่เรียบร้อย(ระบุ).....

13. ตั้งคัมพิง

☒ มี

☐ ไม่มี

14. มีการแก้ไขดัดแปลงส่วนหนึ่งส่วนใดของเครื่องจักรหรือไม่

☐ มี

☒ ไม่มี

รายการทั่วไป ข้อบกพร่อง ปรากฏสิ่งชำรุดบกพร่อง

ไม่มี





กรมส่งเสริมการค้าระหว่างประเทศ  
 กระทรวงพาณิชย์  
 เลขที่ ๕๕๐ CATERPILLAR  
 ๑ 380926C หมายเลข ZBH-10375  
 ตป. ๕๓๓๐๗๗. ๗. 7 ก.พ. ๖7



กรมสวัสดิการและคุ้มครองแรงงาน

ใบสำคัญ

การขึ้นทะเบียนเป็นผู้ให้บริการทดสอบเครื่องจักร

ใบสำคัญเลขที่ ๒๖๖๐๐๐๒๕๒๒๖๒๖๐

เป็นบุคคลผู้ให้บริการด้านความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงานตามกฎหมายกระทรวง  
 กำหนดมาตรฐานในการบริหาร จัดการ และดำเนินการด้านความปลอดภัย อาชีวอนามัย และสภาพแวดล้อม  
 ในการทำงานเกี่ยวกับเครื่องจักร ปั่นจั่น และหม้อน้ำ พ.ศ. ๒๕๖๔ ในการเป็นผู้ให้บริการทดสอบเครื่องจักร  
 (ลิฟต์ เครื่องจักรสำหรับยกคนขึ้นทำงานบนที่สูง และรอก) ทั้งนี้ สามารถดำเนินการได้เฉพาะงาน  
 ตามประเภทและขนาด ตามกฎหมายว่าด้วยวิศวกร ประกอบกับกฎกระทรวงการขึ้นทะเบียนและการอนุญาต  
 ให้บริการเพื่อส่งเสริมความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงาน พ.ศ. ๒๕๖๔  
 แห่งพระราชบัญญัติความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงาน พ.ศ. ๒๕๕๔

ให้ไว้ ณ วันที่ ๒๒ สิงหาคม พ.ศ. ๒๕๖๖



320D2GC S/N ZBH-10375



		<b>GENERATOR INSPECTION CHECK LIST</b> ตรวจสอบเครื่องกำเนิดไฟฟ้า		
Form No.: F-SHE-017	Job No.:	Rev.:	Date:	
Project Name:				
Report No.:				
Machine Owner:	เจ้าของเครื่องจักร: PCE			
Type/Model:	ชนิด/รุ่นเครื่องจักร: JHK-100KW			
Inspection Date:	วันที่ตรวจสอบ: 2-10-66			
Work Location:	สถานที่ทำงาน: Kp 3-P500			

No. ที่	CHECK LIST รายการตรวจสอบ	CONDITION		REMARK หมายเหตุ
		OK	NOT OK N/A	
1	Overall structure are safe โครงสร้างทั้งหมดของเครื่องจักรมีความปลอดภัย	/		
2	All control bottoms and switches are in good shape and usable ปุ่มและสวิตช์ควบคุมมีสภาพดีและใช้งานได้	/		
3	Emergency switch is in place สวิตช์ฉุกเฉินอยู่ตำแหน่งเดิม	/		
4	Distribution point is in good shape and usable จุดกระจายอยู่ในสภาพดีและใช้งานได้	/		
5	Equipped with groundable connection point มีจุดเชื่อมต่อสายดิน	/		
6	All cable are in good shape สายไฟทุกสายมีสภาพดี	/		
7	Fire extinguisher available ติดตั้งถังดับเพลิงพร้อมใช้งาน	/		
8	Lifting point or tow point is safe หังสำหรับยกมีความแข็งแรงปลอดภัย	/		
9	Engine has no Crack, no leak เครื่องยนต์ไม่มีเสียงรบกวน, ไม่รั่วซึม	/		
10	Fuel oil Pull or Empty, no leak ระดับน้ำมันเชื้อเพลิงเต็ม, ไม่รั่วไหล	/		
11	Engine oil normal indicator, no leak ระดับน้ำมันเครื่องปกติ, ไม่รั่วไหล	/		
12	Water coolant Full level, no leak ระดับน้ำหล่อเย็นเครื่องปกติ, ไม่รั่วซึม	/		

Inspect By ตรวจสอบโดย			
Position ตำแหน่ง			
Date วันที่			





ใบตรวจสอบสภาพอุปกรณ์ไฟฟ้าและเครื่องยนต์  
(ELECTRICAL & VEHICLE SAFETY INSPECTION REPORT)

1. ระยะเวลาที่ใช้งาน/Duration: จากวันที่/From: 08 ธันวาคม 2566 ถึงวันที่/To: 07 มกราคม 2567 รวม/Total: 31 วัน/days

สถานที่ปฏิบัติงาน/Location of work: ตามแนวโครงสร้างท่อ BSPP2 KP51  
รายละเอียดงาน/Scope of work: \*Generator-Serial.022800\*

2. ชนิดของอุปกรณ์/Type of Equipment (กรอกโดยผู้ขออนุญาต/Complete by Applicant)

ประเภทอุปกรณ์ไฟฟ้า/Electrical Tool

☒ เครื่องปั่นไฟ

☐ อื่นๆ

อื่นๆ/Other:

3. รายละเอียดของอุปกรณ์/Equipment Details (กรอกโดยผู้ขออนุญาต/Complete by Applicant)

ชื่อหรืออุปกรณ์ไฟฟ้า/Electrical Equipment Brand: Sharyo รุ่นอุปกรณ์ไฟฟ้า/Electrical Equipment Model: Nes60TK2  
ทะเบียนรถหรือเลขประจำเครื่อง/Vehicle License or SN: \*Generator-Serial.022800\* ผู้ขึ้นหรือผู้รับผิดชอบอุปกรณ์/Driver or Owner: จาง ธิ

4. รายการตรวจสอบทางไฟฟ้า/Electrical Inspection List (กรอกโดยผู้ตรวจ/Complete by Inspector)

รายการตรวจสอบ/Inspection List	ปกติ/Yes	ชำรุด/No	หมายเหตุ/Remark
1. ความต้านทาน/Megger test	<input type="checkbox"/>	<input type="checkbox"/>	
2. ขั้วสายไฟ/Terminal connection	<input type="checkbox"/>	<input type="checkbox"/>	
3. สายไฟหุ้มฉนวน/Cable	<input type="checkbox"/>	<input type="checkbox"/>	
4. ระบบกราวด์/Grounding	<input type="checkbox"/>	<input type="checkbox"/>	
5. สภาพสิ่งกีดขวาง, ตัวถัง, หุ้มฉนวน/Casing, body or power plug	<input type="checkbox"/>	<input type="checkbox"/>	
6. การทำงานของอุปกรณ์/Equipment operating	<input type="checkbox"/>	<input type="checkbox"/>	
7. อุปกรณ์ป้องกัน/Water proofing	<input type="checkbox"/>	<input type="checkbox"/>	
8. ระบบป้องกันไฟฟ้ารั่วของอุปกรณ์/Leak to ground protection	<input type="checkbox"/>	<input type="checkbox"/>	
9. สภาพแปรงถ่านของมอเตอร์/Motor carbon brush condition	<input type="checkbox"/>	<input type="checkbox"/>	
10. การป้องกันประกายไฟ/Spark protection	<input type="checkbox"/>	<input type="checkbox"/>	
11. การปิดไฟของกล้องถ่ายรูป/Camera flash disable function	<input type="checkbox"/>	<input type="checkbox"/>	

5. รายการตรวจสอบเครื่องยนต์/เครื่องยนต์/Vehicle & Engine Inspection List (กรอกโดยผู้ตรวจ/Complete by Inspector)


รายการตรวจสอบ/Inspection List	ปกติ/Yes	ชำรุด/No	หมายเหตุ/Remark
1. สายไฟ, ไฟฟ้า, ไฟฟ้า, ไฟฟ้า, Cable and lighting	<input type="checkbox"/>	<input type="checkbox"/>	
2. สภาพสวิตช์ การตัดหรือดับเครื่องยนต์/Engine start-stop switch	<input type="checkbox"/>	<input type="checkbox"/>	
3. ขั้วแบตเตอรี่/Battery terminal	<input type="checkbox"/>	<input type="checkbox"/>	
4. ไดนาโม/Dynamo	<input type="checkbox"/>	<input type="checkbox"/>	
5. สายหัวเทียนและจานจ่าย/Spark plug cable and distributor	<input type="checkbox"/>	<input type="checkbox"/>	
6. ระบบเบรค, เบรคเท้า และล้อจาน/Handbrake, brake and tries	<input type="checkbox"/>	<input type="checkbox"/>	
7. สภาพท่อไอเสียและอุปกรณ์ป้องกันประกายไฟ/Flame arrestor at exhaust intake	<input type="checkbox"/>	<input type="checkbox"/>	
8. สภาพซีลอุปกรณ์ป้องกันแรงดัน / High pressure sealing system	<input type="checkbox"/>	<input type="checkbox"/>	

6.ผลการตรวจสอบ/Inspection Result: [ ] ใช้งานได้/Approve [ ] ใช้งานไม่ได้/Reject [ ] ยกเลิก/Cancel วันที่/Date: ---

De Tel			De Tel
-----------	--	--	-----------

Caution: This inspection report must be exhibited emphatically in the workplace area

**ภาคผนวก จ-8**  
**หนังสือรับรองผู้ปฏิบัติงานเชื่อม**



## WELDER IDENTIFICATION CARD



### Welder Identification Card

The Bangpakong – South Bangkok Power Plant  
Transmission Pipeline Project - PHASE 1



Name:	[REDACTED]		ID: BSPP1-002A
[REDACTED]	We certify that this welder has undergone the required test performance and has met all of the requirements of the relevant specification.		
	Specification: [REDACTED]		
	PTT specification: [REDACTED]		
	WPS Qualified: [REDACTED]		
	Test Position: [REDACTED]		
Date: [REDACTED]			
Signed by	Contractor/EPC	OWNER/Consultant	
Name:	[REDACTED]		
Signature:	[REDACTED]		
Date:	[REDACTED]		

## WELDER IDENTIFICATION CARD



### Welder Identification Card

The Bangpakong – South Bangkok Power Plant  
Transmission Pipeline Project - PHASE 1



Name	[REDACTED]	[REDACTED]	
[REDACTED]	We certify that this welder has undergone the required test performance and has met all of the requirements of the relevant specification.		
	Specification: [REDACTED]		
	PTT specification: [REDACTED] 3		
	WPS Qualified: [REDACTED]		
	Test Position: [REDACTED]		
Date: [REDACTED]			
Signed by	Contractor/EPC	OWNER/Consultant	
Name:	[REDACTED]		
Signature:	[REDACTED]		
Date:	[REDACTED]		



**Worley**  
Energy | Chemical | Infrastructure



## BSPP2 WELDER CARD

Welder No.

Name

Qualify WPS No.

Position

Pipe range

API 1104(2021) /ASME B31.8(2020)

CO

ON

te

February 16, 2023



**Worley**  
Energy | Chemical | Infrastructure



## BSPP2 WELDER CARD

Welder No.

WPS

Name

Qualify WPS No.

Position


Pipe range

API 1104(2021) /ASME B31.8(2020)

e


February 16, 2023

**ภาคผนวก จ-9**  
**เอกสารขึ้นทะเบียนผู้ตรวจสอบรอยเชื่อม**



**THAI NONDESTRUCTIVE TESTING PCL**

**NDE CERTIFICATE OF QUALIFICATION**



**NDT Level III**

(ASNT-288565)

**TRAINING AND EXAMINATION RECORDS**

General	Specific	Practical	Composite(Average)
92.5%	100%	84%	92.1%

**80 Hours Radiographic Testing, Level II**

Cert. No. ATOZ/ST/RT/2016/226, (ATOZ, 14 July 2021)

**Radiographic Testing, Level II**

in accordance with

**TNDT-PQC-R01** which meets the **ASNT's Recommended Practice No. (SNT-TC-1A).**

has successfully completed experience, training, and examination requirements for the recertification in

Certificate No. VFR22E1-016R2-ATOZ

**Managing Director**

**S. Chomduen**

(This certification shall be revoked when employment is terminated or upon a period of six (6) months during which no NDT-related work is performed in the method (s) certified.)



**ใบอนุญาตเจ้าหน้าที่ความปลอดภัยทางรังสี**


**Radiation Safety Officer License**

ประเภท: **วัตถุอันตรายและเครื่องกำเนิดรังสี**

Category: **Radioactive Sources and Radiation Generators**

ออกโดย: **กรมการป้องกันและบรรเทาสาธารณภัย**

Office: **Sukhumburi Police**



**ใบอนุญาตเลขที่/License No.**

**เงื่อนไข/Conditions**

- วัตถุอันตรายประเภทที่ 1

- เครื่องกำเนิดรังสีประเภทที่ 1

- เครื่องกำเนิดรังสีประเภทที่ 2

- เครื่องกำเนิดรังสีที่ต้องแจ้งการครอบครอง

หมายเหตุ/Remark

เป็นเจ้าหน้าที่ความปลอดภัยระดับ 9 แห่งกระทรวงมหาดไทย

การกำหนดอายุ และกำหนดเงื่อนไขอื่น ๆ ให้ดูตามข้อกำหนด พ.ศ. 2563

วันออก **16 ต.ค. 2563**

Date of Issue **16 Oct. 2020**

ใช้ถึงวันที่ **15 ต.ค. 2568**

Valid Until **15 Oct. 2025**



# WELDING & NDT SERVICES

90, GR Floor, Nilkanth Villa, Rangoli Chowkdi, Hajira Road, Velanja Surat, Gujarat-394150  
II Email: ramkailash8989@gmail.com II Mo.8010833525 II

## NDT RECERTIFICATION

This is to certify that



has fulfilled the certification requirements and has demonstrated  
Proficiency by successfully qualifying and certified to

NDT LEVEL - II

IN

RADIOGRAPHY TESTING

Examination as per the requirements of  
AMERICAN SOCIETY FOR NON DESTRUCTIVE TESTING  
SNT-TC-1A (2016 EDITION)

The results of Examination are as under

	General	Specific	Practical	Composite	Result
Actual (%)	82.50	90.00	88.00	86.83	Pass
Passing (%)	70	70	70	80	

Certificate No : W/NDT/RT/L-II/1202  
Written Practice No. : WNDT/WP/NDT Rev.0  
Previous Certificate No : MS/RT/024  
Near Vision Acuity : J1  
Colour Blindness : Nil  
Issue Date : 09/08/2020  
Expiration Date : 08/08/2025



Course Director:

Course Examiner (ASNT NDT Level-III)

This certificate has been renewed based on continued experience, examination and prior certificate no.  
MS/RT/024 and issued by Mr. MANSUKH SATASHIYA (ASNT ID: 224809)

Certificate No. VEFRI90-007R2-TJL-RK

## THAI NONDESTRUCTIVE TESTING PCL



### NDT CERTIFICATE OF QUALIFICATION

has complied with the requirements for the certification in

Radiographic Testing, Level II

in accordance with

TNDT-PQC-R01 which meets the ASNT's Recommended Practice No. (SNT-TC-1A).

#### INITIAL TRAINING AND EXAMINATION RECORDS

80 Hours Course on Radiographic Testing, Level II  
Gen. No. TII-RT/15 (TII-25/02/2015)  
General 75.0 %  
Specific 88.0 %  
Practical 85.0 %  
Composite(Average) 82.6 %



is terminated or upon a period of six (6) months during which no NDT-related work is performed in the method (s) certified.



ใบอนุญาต

มีไว้ในครอบครองหรือใช้ผิดกัมมันตรังสี

วันที่ 29 เมษายน พ.ศ. 2565

อาศัยอำนาจตามความในมาตรา ๑๙ แห่งพระราชบัญญัติพลังงานนิวเคลียร์เพื่อสันติ พ.ศ. ๒๕๕๙

เลขาธิการสำนักงานปรมาณูเพื่อสันติ อนุญาติให้ บริษัท ไทย เอ็น ดี ที จำกัด (มหาชน)

ที่อยู่ และ  
สถานที่

มีไว้ในครอบครองหรือใช้ผิดกัมมันตรังสี ทางด้าน อุตสาหกรรม

ตามคำขอใบอนุญาต เลขที่ 003-26/01/65 ลงวันที่ 7 มีนาคม พ.ศ. 2565

จำนวน 95 รายการ รายละเอียดตามเอกสารแนบท้ายเลขที่ [redacted] จำนวน 5 หน้า

เก็บรักษาวัสดุกัมมันตรังสีเพื่อความปลอดภัย

อนุญาตตั้งแต่วันที่ 20 กุมภาพันธ์ พ.ศ. 2565 ถึงวันที่ 19 กุมภาพันธ์ พ.ศ. 2570

# FOUR M CONSULTING ENGINEERS & SERVICES



Shop No. 7, Plot No. 16, Raj Palace Building, Sector -2, Koparkhairane, Navi Mumbai - 400 709 | Mob: 8452806621 | E-mail: fourmengg123@gmail.com

SCHOOL OF NDT, WELDING, PAINTING

Certificate

Issue Date : 20/03/2017

This is To Certify

has demonstrated his ability successfully in both written and practical examinations in accordance with the ASNT written Practice Document No. SNT-TC-1A 2011 Edition in the following discipline and level shown below

Method : RADIOGRAPHIC TESTING.

Results	Grade
General Examination	82
Specific Examination	81
Practical Examination	83
Composite	82%
Near Vision	J2
Colour Blindness	Nil
Training Hours	80

Level : II

BASED ON CONTINUOUS EXPERIENCE  
AS QUALIFICATION HAS  
BEEN EXTENDED UP TO 19/03/2027

The Certificate issued is valid for maximum of 5 years

SEALED RADIOACTIVE SOURCE CERTIFICATE

ISO2919 Classification C86546

Source Test Report IIT 2023/02/27/12

Radionuclide Ir-192

Active Dimension 3 mm x 2.5 mm

Date of Measurement: 2023/02/21

Source Serial No. AV890

Source Holder No. (Pigtail No.) G6591

Special Form Certificate No. ZA/004/S-96

Activity Measured: 4188.00 GBq  
113.19 Ci

Test for Freedom from Surface Contamination and Leakage:

Method: ISO 9978: 1992 (E) Immersion Test: Hot Liquid

Results: Passed

We hereby declare that we hold the original Special Form Certificate No. ZA/004/S-96 in respect of this sealed source, issued by the Department of Health, Directorate Radiological Physics and Nuclear Medicine.

NTP Radioisotopes SOC Ltd

2023/02/27

PO Box 582 Pretoria 0001

Date

Directors		TJ Tselane (Acting Group Managing Director)	
DR Nicholls (Chairperson)	A Chowan	L Tunganirai	
PF Hawadi	SKN Masango	BM Makgopa	Registration Number
LJ Shayi	NT Magau	JM Maboa	2002/02/1880/30
GJ Davids			
PE Monale			

RESTRICTED

DECAY TABLE for Iridium-192 SOURCES

Customer Name:		THAI NONDESTRUCTIVE TESTING PUBLIC COMPANY LIMITED					76
Source Serial Number:		AV890					6 CHANNEL
Active Dimensions:		3 mm x 2.5 mm					66591
Date of Measurement:		2023/02/21					
Activity Measured:		4188.00 GBq					
		113.19 Ci					
		Specifications verified by					
		RADIOACTIVITY in CURIES on:					
Date:	Tue	Wed	Thu	Fri	Sat	Sun	Mon
2023/02/21	113.19	112.13	111.08	110.05	109.02	108.00	106.99
2023/02/28	105.99	105.00	104.02	103.05	102.08	101.13	100.18
2023/03/07	99.25	98.32	97.40	96.49	95.59	94.70	93.81
2023/03/14	92.94	92.07	91.21	90.35	89.51	88.67	87.84
2023/03/21	87.02	86.21	85.41	84.61	83.82	83.03	82.26
2023/03/28	81.49	80.73	79.97	79.23	78.49	77.75	77.03
2023/04/04	76.31	75.59	74.89	74.19	73.49	72.81	72.13
2023/04/11	71.45	70.78	70.12	69.47	68.82	68.18	67.54
2023/04/18	66.91	66.28	65.66	65.05	64.44	63.84	63.24
2023/04/25	62.65	62.07	61.49	60.91	60.34	59.78	59.22
2023/05/02	58.67	58.12	57.58	57.04	56.50	55.98	55.45
2023/05/09	54.94	54.42	53.91	53.41	52.91	52.42	51.93
2023/05/16	51.44	50.96	50.48	50.01	49.54	49.08	48.62
2023/05/23	48.17	47.72	47.27	46.83	46.39	45.96	45.53
2023/05/30	45.11	44.68	44.27	43.85	43.44	43.04	42.63
2023/06/06	42.24	41.84	41.45	41.06	40.68	40.30	39.92
2023/06/13	39.55	39.18	38.81	38.45	38.09	37.74	37.38
2023/06/20	37.03	36.69	36.35	36.01	35.67	35.34	35.01
2023/06/27	34.68	34.35	34.03	33.72	33.40	33.09	32.78
2023/07/04	32.47	32.17	31.87	31.57	31.28	30.98	30.69
2023/07/11	30.41	30.12	29.84	29.56	29.29	29.01	28.74
2023/07/18	28.47	28.21	27.94	27.68	27.42	27.17	26.91
2023/07/25	26.66	26.41	26.17	25.92	25.68	25.44	25.20
2023/08/01	24.97	24.73	24.50	24.27	24.05	23.82	23.60
2023/08/08	23.38	23.16	22.94	22.73	22.52	22.31	22.10
2023/08/15	21.89	21.69	21.48	21.28	21.08	20.89	20.69
2023/08/22	20.50	20.31	20.12	19.93	19.74	19.56	19.38
2023/08/29	19.19	19.02	18.84	18.66	18.49	18.31	18.14
2023/09/05	17.97	17.81	17.64	17.47	17.31	17.15	16.99
2023/09/12	16.83	16.67	16.52	16.36	16.21	16.06	15.91
2023/09/19	15.76	15.61	15.47	15.32	15.18	15.04	14.90
2023/09/26	14.76	14.62	14.48	14.35	14.21	14.08	13.95
2023/10/03	13.82	13.69	13.56	13.44	13.31	13.19	13.06
2023/10/10	12.94	12.82	12.70	12.58	12.46	12.35	12.23

Directors		TJ Tselane (Group Managing Director)	
DR Nicholls (Chairperson)	A Chowan	L Tunganirai	
PF Hawadi	SKN Masango	BM Makgopa	Registration Number
LJ Shayi	NT Magau	JM Maboa	2002/02/1880/30
GJ Davids			
PE Monale			

RESTRICTED



บริษัท ไทย เน็น ดี ที จำกัด (มหาชน)

THAI NONDESTRUCTIVE TESTING PUBLIC COMPANY LIMITED

19 เวียงสาพัฒนา 60 หมู่ 8 (ประตู 8) ถนนพหลโยธินสายพิเศษ กรุงเทพมหานคร 10260

19 Soi Banglamung 60 Yang 8 (Sanon 8) Banglamung Rd., Nuek, Bangkok, Bangkok 10260



## Safety Distance with Collimator 1 inch

Safety Distance for Controlled Area

Projector No.

P.99 D12653

Source serial number

AV890/G6591

Day	Tue	Wed	Thu	Fri	Sat	Sun	Mon
DATE	25 Apr 23	26 Apr 23	27 Apr 23	28 Apr 23	29 Apr 23	30 Apr 23	1 May 23
SOURCES : (Ci)	62.65	62.07	61.49	60.91	60.35	59.78	59.23
SAFETY DISTANCE	13.90	13.84	13.77	13.71	13.64	13.58	13.52
DATE	2 May 23	3 May 23	4 May 23	5 May 23	6 May 23	7 May 23	8 May 23
SOURCES : (Ci)	58.67	58.13	57.59	57.05	56.52	55.99	55.47
SAFETY DISTANCE	13.45	13.39	13.33	13.26	13.20	13.14	13.08
DATE	9 May 23	10 May 23	11 May 23	12 May 23	13 May 23	14 May 23	15 May 23
SOURCES : (Ci)	54.95	54.44	53.93	53.43	52.93	52.44	51.95
SAFETY DISTANCE	13.02	12.96	12.90	12.84	12.78	12.72	12.66
DATE	16 May 23	17 May 23	18 May 23	19 May 23	20 May 23	21 May 23	22 May 23
SOURCES : (Ci)	51.46	50.99	50.51	50.04	49.57	49.11	48.65
SAFETY DISTANCE	12.60	12.54	12.48	12.42	12.37	12.31	12.25
DATE	23 May 23	24 May 23	25 May 23	26 May 23	27 May 23	28 May 23	29 May 23
SOURCES : (Ci)	48.20	47.75	47.31	46.86	46.43	45.99	45.57
SAFETY DISTANCE	12.19	12.14	12.08	12.02	11.97	11.91	11.85
DATE	30 May 23	31 May 23	1 Jun 23	2 Jun 23	3 Jun 23	4 Jun 23	5 Jun 23
SOURCES : (Ci)	45.14	44.72	44.30	43.89	43.48	43.08	42.67
SAFETY DISTANCE	11.80	11.74	11.69	11.64	11.58	11.53	11.47

$$X = \sqrt[3]{A \times D / PD}$$

where

X = Distance between the boundary of restricted area and the source in meter.

A = Source activity (radioactivity) in Curies for Gamma Ray or 1 for X ray

D = Dose rate at 1 meter 480 mR/hr or 4800 μSv/hr for Ir-192

PD = Pre-limited dose rate at the boundary of restricted area in mR/hr or μSv/hr

Remark : X = Safety distance from the radiation source (m)

Ci = Strength of radiation

480 = Radiation dose rate of Ir-192 at 1 m. 480 (mR/hr)

0.75 = Limited radiation dose rate for controlled area (mR/hr)

207.5 = Transmission Factor of Tungsten Thickness 1 inch



Safety Distance



Thailand Institute of Nuclear Technology (Public Organization)

9/9 Moo 7, Saimoon, Ongkharak, Nakhonayok, 26120

Phone : 02 401 9889 Ext. 1910

Inspection Report of Gamma Ray Projector

Date : 17 November 2022

Reference No. :-

Date :-

Report No. : Pro 059-11-65  
Inspection Date : 17 November 2022  
Expiration Date : 16 November 2023


Agency Code	RA 21-003	Agency	Thailand Nondestructive Testing Public Company Limited.
Gamma Ray Projector Details	Projector Code	TNDT-P 93	Visual Check of Housing
	Serial No.	D12653	Lock/Ring Selection System
Radioactive Material Details	Ir-192	Se-75	Source Brace/Shipping Plug
	Source Serial/Pigtail No. : AU396/G5088		Radioactivity on Inspection Date
Radioactive Material Leakage	Found : - μCi		Radiation Warning and Belonging
≤ 0.005 μCi	Not Found		Signs
Maximum Dose Rate (mR/hr)	Contact : 9.00	30 Centimeters : 0.90	1 Meter : 0.30
Allowed to Use	Improvement Details : -		
Need Improving			
Drive Cable Control Set	TNDT-D 93	Visual Check	Normal
Go-No-Go Gauge Check			
Male Ball Diameter	Normal	Male Ball Shank Length	Normal
Male Ball Shank Diameter	Normal	Male-Female Connection	Normal
Allowed to Use	Improvement Details : -		
Need Improving			
Guide Tube Details	Visual Check	Normal	
Tube No.1 : Master Guide Tube	TNDT-G 126	Allowed to Use	
Tube No.2 : Extension 1	TNDT-G 127	Need Improving	
Tube No.3 : Extension 2	-		
Improvement Details			
Survey Meter Serial No.	5/93352	Calibration Date	11 March 2022

Center

FM-NSC-90

Rev. No. 04 EFF Date : 23/06/2021

คลินิกแพทย์น้อยเกล้า



ใบรับรองแพทย์

วันที่ ๑ เดือน สิงหาคม พ.ศ. ๒๕๖๕


ข้าพเจ้า.....  
(ก) แพทย์.....  
ได้ทำการ.....  
(ข) ประกาศว่า.....

โรคที่สามารถ จิตเห็นเพื่อน ไม่สมบูรณ์ และปราศจากโรคเหล่านี้ คือ  
โรคเรื้อรังในระยะเฉียบพลันหรือในระยะที่ปรากฏอาการเป็นที่รังเกียจแก่สังคม  
วัณโรคในระยะอันตราย  
โรคเท้าช้างในระยะที่ปรากฏอาการเป็นที่รังเกียจแก่สังคม  
โรคติดยาเสพติดให้โทษ  
โรคพิษสุราเรื้อรัง

(ค) เห็นว่า.....




ลงชื่อ.....



หมายเหตุ

- (๑) เป็นแพทย์ซึ่งได้ขึ้นทะเบียนรับใบอนุญาตประกอบวิชาชีพเวชกรรม
- (๒) ให้แสดงว่าเป็นผู้มีร่างกายสมบูรณ์แข็งแรงหรือหากโรคที่เป็นเหตุให้ต้องออกจากราชการ
- (๓) ให้แสดงว่าเป็นผู้มีร่างกายเหมาะสมกับตำแหน่งหน้าที่ราชการที่ต้องปฏิบัติ
- (๔) ใบรับรองแพทย์ฉบับนี้ให้ใช้ได้ ๑ เดือนนับแต่วันที่ตรวจร่างกาย

คลินิกแพทย์น้อยเกล้า



ใบรับรองแพทย์

วันที่ ๑ เดือน สิงหาคม พ.ศ. ๒๕๖๕


ข้าพเจ้า.....  
(ก) แพทย์.....  
ได้ทำการ.....  
(ข) ประกาศว่า.....

โรคที่สามารถ จิตเห็นเพื่อน ไม่สมบูรณ์ และปราศจากโรคเหล่านี้ คือ  
โรคเรื้อรังในระยะเฉียบพลันหรือในระยะที่ปรากฏอาการเป็นที่รังเกียจแก่สังคม  
วัณโรคในระยะอันตราย  
โรคเท้าช้างในระยะที่ปรากฏอาการเป็นที่รังเกียจแก่สังคม  
โรคติดยาเสพติดให้โทษ  
โรคพิษสุราเรื้อรัง

(ค) เห็นว่า.....



ลงชื่อ.....




หมายเหตุ

- (๑) เป็นแพทย์ซึ่งได้ขึ้นทะเบียนรับใบอนุญาตประกอบวิชาชีพเวชกรรม
- (๒) ให้แสดงว่าเป็นผู้มีร่างกายสมบูรณ์แข็งแรงหรือหากโรคที่เป็นเหตุให้ต้องออกจากราชการ
- (๓) ให้แสดงว่าเป็นผู้มีร่างกายเหมาะสมกับตำแหน่งหน้าที่ราชการที่ต้องปฏิบัติ
- (๔) ใบรับรองแพทย์ฉบับนี้ให้ใช้ได้ ๑ เดือนนับแต่วันที่ตรวจร่างกาย




**ภาคผนวก จ-10**  
**บันทึกจำนวนห้องน้ำของโครงการ**




**TOILET RECORD  
JULY 2023**

Location		Amount of people		No. of Toilet		Remark
		Men	Women	Men	Women	
Main office	CPP Office	41	13	8	7	
Stock yard	Khao Khan Song yard	0	0	2	1	
Summary		41	13	10	8	
Total		54		18		

Remark: The standard required rate for toilets is 1 room per 20 manpowers.



Rec



Photos



CPP Office



Stock yard

# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## TOILET RECORD

For the Month of July, 2023

Location		Amount of people	No. of Toilet	Remark
Main Office	EZ Space Building	59	8	
Stockyard	SNP Stockyard	20	9	
	Temporary stockyard (BS#6)	4	0	Temporary work
Direct pipe/Boring	DP#21	40	3	
Dumpsite	Mud Dumpsite	8	0	Temporary work
TOTAL		131	20	

\* The ratio of the number of bathroom: 1 room/15 peoples/working area.

### Photo



Main Office



Stockyard




DP#21




DP#21

Report by



Approve by





**Bangpakong – South Bangkok Power Plant  
Transmission Pipeline Project – Phase 1**




**TOILET RECORD**


August 2023

Location		Amount of people		No. of Toilet		Remark
		Men	Women	Men	Women	
Main office	CPP Office	69	18	8	7	
Stock yard	Khao Khan Song yard	0	0	2	1	
Summary		69	18	10	8	
Total		87		18		

Remark: The standard required rate for toilets is 1 room per 20 manpowers.



Record



Photos



CPP Office



Stock yard

# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## TOILET RECORD

For the Month of Aug, 2023

Location		Amount of people	No. of Toilet	Remark
Main Office	EZ Space Building	61	8	
Stockyard	SNP Stockyard	20	9	
Direct pipe/Boring	DP#21	30	3	
	DP#23	15	1	
	DP#28	6	1	
TOTAL		132	22	

\* The ratio of the number of bathroom: 1 room/15 peoples/working area.

### Photo



Main Office



Stockyard



DP#21




DP#23



DP#28

Report by



Approve by



# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## TOILET RECORD

For the Month of September, 2023

Location		Amount of people	No. of Toilet	Remark
Main Office	EZ Space Building	61	8	
Stockyard	SNP Stockyard	10	9	
Direct pipe/Boring	DP#21 (Entry)	30	3	
	DP#21 (Exit)	4	0	Temporary work for verify pipe
	DP#23	15	1	
	DP#28	4	1	
Block Valve	BS#6	12	1	
	BS#7	4	1	Waiting water supply (only dewatering)
TOTAL		140	24	

\* The ratio of the number of bathroom: 1 room/15 peoples/working area.

### Photo



Main Office



Stockyard



DP#21



DP#23



DP#28




BS#6




BS#7

Report by



Approve by





**Bangpakong – South Bangkok Power Plant  
Transmission Pipeline Project – Phase 1**



**TOILET RECORD**  
Octoberber 2023

Location		Amount of people		No. of Toilet		Remark
		Men	Women	Men	Women	
Main office	CPP Office	68	18	8	7	
Stock yard	Khao Khan Song yard	0	0	2	1	
Block Valve	Block Valve Station 4	5	0	1	0	
Summary		73	18	11	8	
Total		91		19		

Remark: The standard required rate for toilets is 1 room per 20 manpowers.

Record by Ketsarin P.

(...Ms.Ketsarin...Riangnok...)

Environment Officer

Date 27 / 10 / 2023

[Signature]  
(Mr. Rofiering T.)

SHE Manager

Date 27 / 10 / 2023

Photos



CPP Office



Stock yard



Block Valve Station 4

# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## TOILET RECORD

For the Month of October, 2023 (30 Sep - 6 Oct, 2023)

Location		Amount of people	No. of Toilet	Remark
Main Office	EZ Space Building	61	8	
Stockyard	SNP Stockyard	10	9	
Direct pipe/Boring	DP#21 (Entry)	17	3	
	DP#21 (Exit)	0	0	No activity
	DP#23 (Entry)	18	1	
	DP#28 (Entry)	4	1	
Block Valve	BS#6	12	1	
	BS#7	5	1	Waiting water supply (only dewatering)
TOTAL		127	24	

\* The ratio of the number of bathroom: 1 room/15 peoples/working area.

### Photo



Main Office



Stockyard



DP#21



DP#23



DP#28



BS#6



BS#7

Report

Approve by

# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## TOILET RECORD

For the Month of 7-13 Oct, 2023

Location		Amount of people	No. of Toilet	Remark
Main Office	EZ Space Building	61	8	
Stockyard	SNP Stockyard	10	9	
Direct pipe/Boring	DP#21 (Entry)	17	3	
	DP#21 (Exit)	0	0	No activity
	DP#23 (Entry)	18	1	
	DP#28 (Entry)	4	1	
Block Valve	BS#6	12	1	
	BS#7	5	1	Waiting water supply (only dewatering)
TOTAL		127	24	

\* The ratio of the number of bathroom: 1 room/15 peoples/working area.

### Photo



Main Office



Stockyard



DP#21



DP#23



DP#28




BS#6




BS#7

Report by





Approve by



**TOILET RECORD  
November 2023**

Location		Amount of people		No. of Toilet		Remark
		Men	Women	Men	Women	
Main office	CPP Office	42	17	8	7	
Stock yard	Khao Khan Song yard	4	0	2	1	
Block Valve	Block Valve Station 1(BS#1)	7	4	1*	0	
	Block Valve Station 4 (BS#4)	5	0	1	0	
Direct pipe	Direct pipe # 3 (DP#3)	5	0	1	0	
	Direct pipe # 5 (DP#5)	18	0	1	0	
	Direct pipe # 7 (DP#7)	15	2	2*	0	
Open cut	KP8+300	5	0	1	0	
Summary		101	23	17	8	
Total		124		25		

Remark: The standard required rate for toilets is 1 room per 20 manpowers.



Photos



CPP Office



Stock yard



BS#1



Block Valve Station 4



DP#3 (KP2+800)



DP#5



DP#7



KP8+300



# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## TOILET RECORD

For the Month of 11-17 Nov, 2023

Location		Amount of people	No. of Toilet	Remark
Main Office	EZ Space Building	61	8	
Stockyard	SNP Stockyard	10	9	
Direct pipe/Boring	DP#22 (Entry)	13	1	
	DP#21 (Exit)	15	1	
	DP#23 (Entry)	13	1	
	DP#22 (Under toll way)	11	1	rent in the accomodation (20 m. fromsite)
	DP#23 (Exit)	5	1	Temporary work
	DP#24 (Entry)	15	1	
	DP#27 (Entry)	2	0	Temporary work (Clearing)
Block Valve	DP#28 (Entry)	25	2	
	BS#6	9	1	
	BS#7	6	1	
TOTAL		185	27	

\* The ratio of the number of bathroom: 1 room/15 peoples/working area.

### Photo



Report by

Approve by

**TOILET RECORD**  
December 2023

No.	Activity	Location	Amount of people		No. of Toilet		Remark
			Men	Women	Men	Women	
1	Main Office	CPP Office	43	17	8	7	
2	Stock pipe	CPP Stock yard	5	0	2	1	
3	Block Valve Station (BS)	BS#1	10	1	1*	0	
4		BS#4	5	0	1	0	
5	Direct pipe (DP)	DP#3-3B	10	1	1*	0	
6		DP#5	20	0	1	0	
7		DP#7	35	0	2	0	
8	Open cut	KP8+300	12	0	1	0	
9	HDD	HDD#2	5	0	1	0	
Summary			145	19	18	8	
Total			164		26		

Remark: The standard required rate for toilets is 1 room per 20 manpowers./ \*Sharing toilet facilities

Rec

Photos



CPP Office



Stock yard



BS#1



BS#4



DP#3-3B



DP#5



DP#7



KP8+300



HDD#2

# BANGPAKONG-SOUTH BANGKOK POWER PLANT TRANSMISSION PIPELINE PROJECT (PHASE 2)

## TOILET RECORD

For the Month of December, 2023

Location		Amount of people	No. of Toilet	Remark
Main Office	EZ Space Building	112	8	Subcontractor 32 personnel stay at their office.
Stockyard	SNP Stockyard	10	9	
Direct pipe/Boring	DP#21 (Entry), DP#22 (Entry)	17	1	
	DP#23 (Entry)	20	1	
	DP#22 (Under toll way)	10	1	rent in the accomodation (20 m. fromsite)
	DP#23 (Exit)	15	1	
	DP#24 (Entry)	10	1	
	DP#27 (Entry)	5	2	
	DP#28 (Entry)	33	2	
Block Valve	BS#6	28	1	temporary manpower for SCC activity
	BS#7	10	1	
TOTAL		270	28	

Remark: The standard required rate for toilets is 1 room per 20 manpowers. (sharing toilet facilities)


### Photo



Report

Approve by

**ภาคผนวก จ-11**  
**รายการคำนวณและการออกแบบระบบป้องกัน**  
**การถล่มของดิน**





PTT PUBLIC COMPANY LIMITED

REV NO.	DATE	BY	CHK	EM / PM	DESCRIPTION
A	12 May 2023	PK	CKS/GB	PC/ECG	Issued for Review

BANGPAKONG – SOUTH BANGKOK POWER PLANT  
TRANSMISSION PIPELINE PROJECT – PHASE 1

SHEET PILE PITS CALCULATION

ED-D-2204.01-010-006

TOTAL 243 PAGES

DOCUMENT REVIEW	
<input type="checkbox"/> E :	Work may proceed.
<input type="checkbox"/> F :	Work may proceed. Submit Final Document, Incorporate comments and resubmit.
<input type="checkbox"/> G :	Revise and resubmit. Work may proceed subject to incorporation of changes indicated.
<input type="checkbox"/> H :	Revise and resubmit. Work may not proceed.
<input type="checkbox"/> I :	Review is not required. Work may proceed.
By :	Date :
PTT Public Company Limited	

Consultant 	Contractor 	AREA CODE GENERAL: 010	CPP-JV PROJECT NO.
		PTT CONTRACT NO. PTT.TEC./2/86/65	PTT PROJECT NO. 2204.01

SECTION	CONTENTS	PAGE
1.0	INTRODUCTION .....	3
1.1	PROJECT OVERVIEW .....	3
1.2	GENERAL DESCRIPTION OF THE PROJECT .....	3
1.3	SUMMARY OF REQUIRED FACILITIES .....	3
2.0	PURPOSE OF DOCUMENT .....	4
3.0	DEFINITIONS .....	4
4.0	ABBREVIATIONS .....	4
5.0	CODES, STANDARDS, AND REGULATIONS .....	5
6.0	ASSUMPTIONS .....	6
7.0	METHODOLOGY OF FINITE ELEMENT METHOD (FEM) .....	7
7.1	LATERAL EARTH PRESSURE IN BRACED CUTS .....	8
7.2	HEAVE OF BOTTOM OF CUT IN CLAY .....	9
8.0	MATERIALS .....	11
8.1	SHEET PILE .....	11
8.2	WALE AND STRUT BEAM .....	11
8.3	SOIL DATA .....	12
9.0	DESIGN LOADINGS .....	15
10.0	CONSTRUCTION DETAILS .....	16
10.1	BORED AND TIE-IN PITS .....	16
10.1.1	Type - Depth of sheet pile is not over 4.0 m .....	16
10.1.2	Type - Depth of sheet pile is over 4.0 m and not over 7.0 m .....	17
10.1.3	Type - Depth of sheet pile is over 7.0 m and not over 10.0 m .....	21
10.2	DIRECT PIPE PIT .....	26
10.2.1	Type - Depth of sheet pile is not over 4.5 m (Entry and Exit Pits) .....	26
11.0	CALCULATION RESULTS .....	28
	APPENDIX A: DETAILED CALCULATIONS .....	30
	APPENDIX B: CALCULATION DETAILS FOR STRUT REMOVAL .....	118
	APPENDIX C: SOIL DATA .....	144
	APPENDIX D: REFERENCE DRAWINGS .....	238

1.0 INTRODUCTION

1.1 Project Overview

PTT Public Company Limited, hereinafter referred to as “PTT” or “OWNER”, is undertaking the new onshore pipeline system from Bang Pakong, Cha Choeng Sao Province, to the south of Bangkok in order to secure gas supplies to power plants and other consumers.

The new pipeline system shall be called “Bangpakong – South Bangkok Power Plant Transmission Pipeline Project”, abbreviated to “BSPP”.

The pipeline system will be extended from the provision for future tie-in valve in Block Valve Station BP4 of the Fifth Transmission Pipeline (5TP).

The pipeline system will be tied-in to the existing Metering and Regulating Station of South Bangkok Power Plant (SBMR) in order to supply gas to South Bangkok Power Plant (SBK).

The Bangpakong – South Bangkok Power Plant Transmission Pipeline Project (BSPP) is divided into two phases, namely Phase 1 and Phase 2, comprising of approximately 57 Kilometers of 36 inch main pipeline, commencing from block valve station BP4 located in Bang Pakong, Cha Choeng Sao Province to receive the natural gas from the Fifth Transmission Pipeline (5TP) in order to supply gas to the customers along the pipeline route and will be terminated at the existing SBMR to deliver gas to South Bangkok Power Plant (SBK) in Samut Prakan Province.

1.2 General Description of The Project

The purpose of the Phase 1 project is to deliver the natural gas from the Fifth Transmission Pipeline (5TP) from the tie in point at BP4 to support the anticipated demands along the BSPP route and will be terminated at BS4, including an underground pipeline to the HDD exit point in front of BS5. From this termination point, the pipeline will then continue to the existing SBMR to deliver gas to SBK in Samut Prakan Province (which will be performed under BSPP2). The BSPP1 pipeline system will be approximately 34 km in length.

BSPP1 is planned to be mechanically completed (MC) by 01 November 2024.

BSPP1 terminates at BS4 including an underground pipeline to the last HDD exit point in a temporary capped end fitting, which is upstream of the BS5 boundary fence.

1.3 Summary of Required Facilities

The Bangpakong – South Bangkok Power Plant Transmission Pipeline Project (BSPP) - Phase 1 comprises of the following elements and design requirements are outlined in the Design Basis Manual (DBM). The following paragraphs summarize major components of main gas pipeline and facility system to be constructed under the Contract:

- BSPP Launching Station, located adjacent to BP4, including BSPP Pig Launcher, tie-ins to receive gas from the existing Fifth Transmission Pipeline (5TP), and future tie-in valves for future BP4-BCS interconnecting Pipeline.
- 36-inch main gas transmission pipeline for approximate 34 kilometers from BP4, which is located in Cha Choeng Sao Province.
- Four (4) Block Valve Stations (BS1 – BS4).
- Future sales tap valves.

- SCADA and telecommunication systems to support all new installed facilities, including fiber optic cable system.
- Cathodic Protection System for pipeline and underground facilities.

2.0 PURPOSE OF DOCUMENT

The purpose of this document is to analyze sheet pile structure for bored pits, direct pipe pits, and tie-in pits that are located along pipeline route. Finite Element Method (FEM) is used for calculating the sheet pile pits with the worst soil condition to cover all bore pits, tie-in pits and direct pipe pits.

3.0 DEFINITIONS

For the purposes of this document, the following definitions shall apply:

- The “OWNER” is PTT Public Company Limited or PTT’s representative.
- The “Consultant” is PMC Engineering Consultant, namely Worley (Thailand) Limited.
- The “Contractor” is Joint Venture of China Petroleum Pipeline Engineering Co., Ltd. and China Petroleum Pipeline Bureau Co., Ltd. (CPP JV).
- The “Supplier” is the Vendor, Manufacturer or Seller of the equipment/service defined in the Document.
- The “Purchaser” is the Contractor or their appointed agent or representative.

Throughout this document, the following terminology is used:

- “must”: A legal or statutory requirement
- “shall”: A requirement made mandatory by this Document
- “may”: A feature, which is discretionary in the context in which it is applied
- “will”: A feature, which the Contractor / Supplier may assume to be already present

4.0 ABBREVIATIONS

The below abbreviations are described and defined in minimum for use within this Project, unless otherwise specified.

Abbreviation	Description
AASHTO	American Association of State Highway and Transportation Officials
AISC	American Institute of Steel Construction
ASCE	American Society of Civil Engineers
ASD	Allowable Stress Design
DIN	German Industrial Standard
DPT	Department of Public Work and Town & Country Planning

<i>FS</i>	Factor of Safety
<i>KP</i>	Kilometer of Pipeline
<i>ROW</i>	Right of Way
<i>NP</i>	Non-Plastic
<i>SPT</i>	Standard Penetration Test

## 5.0 CODES, STANDARDS, AND REGULATIONS

The following codes, standards, and specifications, the latest edition, form part of this document:

Document No.	Document Title
AISC 360	Specification for Structural Steel Building (ASD Method)
ASCE 7-10	Minimum Design Loads for Buildings and Other Structures
DIN 4085:2007	Subsoil – Calculation of Earth Pressure
DPT (USA) 1911-52	Standard for Calculating Slope Stability in Excavation and Backfill (มาตรฐานประกอบการคำนวณค่าเสถียรภาพความลาดเอียงที่ปลอดภัยในงานขุดและถมดิน)
OSHA 1926 Subpart P App A	Soil Classification

## 6.0 ASSUMPTIONS

The following assumptions are used for sheet pile pits calculation.

- Sheet pile pit shall be analyzed by Finite Element Method (FEM) using PLAXIS 2D program and the structural steel shall be designed by ASD method using STAAD Pro program.
- There are two types of sheet pile pit width, 3.0 m for Bored, Tie-In pits and Direct Pipe Exit pit and 7.10 m for Direct Pipe Entry pit.
- Bored & Tie-In pits shall consider the depth of sheet pile for three (3) groups
  - Group1: Depth from ground level EL.±0.00 to depth EL-4.00 m
  - Group2: Depth more than EL.±4.00 m to depth of EL-7.00 m
  - Group3: Depth more than EL.±7.00 m to depth of EL-10.00 m
- Direct pipe entry and exit pits shall consider the maximum pit depth of 4.5 m.
- Regarding soil investigation report, document no. RPT-C-2204.01-010-002, since almost all the top layer of soil is soft clay then the comparison of average values for undrained shear strength shall be taken to find out the worst soil bore hole. Soil comparison is presented in Section 8.3.
- Undrained shear strength ( $S_u$ ) shall refer to pipeline soil investigation report except that in the report showing SPT-N value (blows/ ft), undrained shear strength value shall refer from equation  $S_u = N / 1.5$  or  $N / 1.5$ .
- The underground soil table is considered and applied in model according to soil investigation report and effect of pore water pressure is considered.
- The surcharge load of 2,000 kg/m<sup>2</sup> is in accordance with DPT 1911-52 standard. The uniform load shall be applied on the top of pit with 1.0 m offset from top of pit.
- Allowable lateral movement of sheet pile should be 0.005 (Lateral deflection / pit depth) in accordance with DIN 4085:2007 .
- The situation is assumed to be mitigated by continuous dewatering of pit, using dewatering pumps or such methods.

7.0 METHODOLOGY OF FINITE ELEMENT METHOD (FEM)

The finite element method uses two-dimensional solid finite element (dimension of a x b x thickness) of the elastic continuum. This method usually allows either a plan-stress ( $\sigma_z, \sigma_y > 0; \sigma_z = 0$ ) or plan-strain ( $\epsilon_x, \epsilon_y > 0; \epsilon_z = 0$ ) analysis based on an input control parameter. They usually allow several soils with different stress-strain modulus ( $E_s$ ) and  $\mu$  values for Poisson's ratio.

- General Modeling Aspects

A geometry model is 2D representation of a real three-dimensional problem and consists of point, lines and clusters. A geometry model should include a representative division of the subsoil into distinct soil layers, structural object, construction stage and loading. The three types of components in a geometry model are described below in more detail.

Points are from the start and end of lines. Point can also be used for the positioning of anchors, point force, and point fixities for local refinements of the finite element meshing.

Lines are used to define the physical boundaries of the geometry, the model boundaries, and discontinuities in the geometry such as walls or shells, separations of distinct soil layers or construction stages. A line can have several functions or properties.

Clusters are areas that are fully enclosed by lines. Within a cluster, the soil properties are homogeneous. Hence, cluster can be regarded as parts of soil layers. Actions related to clusters apply to all elements in the cluster.

After the creation of a geometry model, a finite element model can automatically be generated, based on the composition of cluster and lines in the geometry model. In a finite element meshing, three types of components can be identified below.

- Elements

During the generation of the mesh, clusters are divided into triangular elements. A choice can be made between 15-node elements and 6-nodes elements. The powerful 15-node element provides an accurate calculation of stresses and failure loads. In addition, 6-node triangles are available for a quick calculation of serviceability states. Considering the same element distribution (for example a default coarse mesh generation), the user should be aware that meshes composed of 15-node elements are actually much finer and much more flexible than meshes composed of 6-node elements, but calculations are also more time consuming. In addition to triangular elements, which are generally used to model the soil, compatible plate elements, grid elements and interface elements may be generated to model structural behavior and soil-structure interaction.

- Nodes

A 15-node element consists of 15-nodes and a 6-node triangle is defined by 6-nodes. The distribution of nodes over the elements is shown in Figure 7.1. Adjacent elements are connected through their common nodes. During a finite element calculation, displacements ( $u_x$  and  $u_y$ ) are calculated at the nodes. Nodes may be pre-selected for the generation of load-displacement curves.

- Stress Points

In contrast to displacements, stresses and strains are calculated at individual Gaussian integration points (or stress points) rather than at the nodes. A 15-

node triangular element contains 12 stress points as indicated in Figure 7.1a. Stress point may be pre-selected for the generation of stress paths or stress-strain diagrams.




Figure 7.1: Nodes and Stress Points

7.1 Lateral Earth Pressure in Braced Cuts

Peck (1969) provided the envelope for lateral earth pressure for design of cuts in sand. This is illustrated in Figure 7.2a. The pressure envelope for soft to medium clay is shown in Figure 7.2b. It is applicable for the condition.

- Lateral pressure of braced cuts in sand

$$\sigma = 0.65 \gamma H K_a$$

Where

$\gamma$	=	Unit weight
$H$	=	Height of the cut
$K_a$	=	Rankine's active pressure coefficient
$\theta$	=	$\tan^2(45^\circ - \phi/2)$
	=	Internal friction angle for shearing resistance

- Lateral pressure of braced cuts in soft to medium clay

From Figure 7.2b, it is applicable for the condition.

$$\frac{\gamma H}{c} > 4$$

where  $c$  = undrained cohesion ( $\phi=0$ ). The pressure,  $\sigma$ , is the larger of

$$\sigma = \gamma H \left[ 1 - \left( \frac{4c}{\gamma H} \right) \right]$$

or

$$\sigma = 0.3 \gamma H$$

Where  $\gamma$  = unit weight of clay.

The pressure envelope for cuts in stiff clay is shown in Figure 7.2c, in which

$\sigma = 0.2\gamma\mathcal{H}$  to  $0.4\gamma\mathcal{H}$  (with an average of  $0.3\gamma\mathcal{H}$ ) is applicable to the condition  $\gamma\mathcal{H}/c \leq 4$




Figure 7.2: Peck's (1969) Apparent Pressure Envelope for (a) Cuts in Sand; (b) Cuts in Soft to Medium Clay; (c) Cuts in Stiff Clay

## 7.2 Heave of Bottom of Cut in Clay

Braced cuts in clay may become unstable as a result of heaving of the bottom of the excavation. Terzaghi (1943) analyzed the safety of factor of long braced excavations against bottom heave. The failure surface for such a case is shown in Figure 7.3.

The safety of factor is based on the assumption that the clay layer is homogeneous, at least to a depth of  $0.7B$  ( $B$  is the width of pit) below the bottom of the cut. The safety of factor becomes:

$$FS = \frac{1}{W} \left( \frac{5.7c}{\dots} \right) \geq 1.50 \text{ times}$$

Where	$B$	=	Width of Pit
	$FS$	=	Safety of factor
	$c$	=	undrained cohesion
	$H$	=	Pit depth
	$D$	=	Depth of soil failure surface below bottom pit, maximum depth is 0.7B
	$\gamma$	=	unit weight of clay.

Refer to Foundation Engineering Handbook by Hsai-Yang Fang page 473, the minimum allowable safety of factor is 1.20 for temporary excavations. This report shall be used the allowable safety of factor of 1.50. In case that the factor of safety for




Figure 7.3: Factor of Safety Against Bottom Heave

upheaval is less than allowable value, the embedded depth of sheet pile is required and it needs to check that soil upheaval value has to not obstruct with construction.

8.0 MATERIALS

8.1 Sheet Pile

Steel sheet pile type  
Steel sheet pile material grade  
Steel structure grade SY295 (295MPa) in accordance with JIS 5528 standard  
SY 295  
SP-III/A (400x150x13.1mm)  
 $F_y$   
= 3,000 kg/cm<sup>2</sup>  
Modulus of elasticity,  $E$   
= 2.0x10<sup>6</sup> kg/cm<sup>2</sup>

8.2 Wale and Strut Beam

The mechanical properties of wale and strut beam are shown in table below.

Section(mm)	Area (cm <sup>2</sup> )	Radius of Gyration (cm)(min.)	Modulus of Section (cm <sup>3</sup> )	For Pit Type
H582x300x12x17	174.5	6.63	3,530	Direct Pipe
H400x400x13x21	218.7	10.10	3,330	Bore/Tie-In
H350x350x12x19	173.9	8.84	2,300	Bore/Tie-In
H300x300x10x15	119.8	7.51	1,360	Bore/Tie-In

Steel structure grade ASTM A36 (245 MPa),  $F_y$   
Modulus of elasticity,  $E$   
= 2,500 kg/cm<sup>2</sup>  
= 2.0x10<sup>6</sup> kg/cm<sup>2</sup>

8.3 Soil Data

Soil data is referred from document no. RPT-C-2204.01-010-002: Pipeline Soil Investigation Report (See Appendix C). The boreholes are located along the pipeline at Right of Way (ROW) starting at Bang Pakong District, Chachoengsao Province to Bang Phi District, Samut Prakan Province; as demonstrated in Figure 8.1.




Figure 8.1: Project Area and Bore Location

The comparison to find out worst soil property is presented in Table 8.1 below.

Bore Hole No.	Bore Hole Location (KP)	Soil Type	Undrained Shear Strength, $s_u$ (t/m <sup>2</sup> ) <sup>(1)</sup>										Average Undrained Shear Strength, $s_u$ (t/m <sup>2</sup> )
			Depth								10.5-12.0 m		
			0.00-1.50 m	1.50-3.00 m	3.00-4.50 m	4.50-6.00 m	6.00-7.50 m	7.50-9.00 m	9.00-10.5 m				
BH-001-35	0+115	Clay	1.59	1.55	1.59	1.64	1.73	1.79	1.79	1.69		1.670	
BH-002-15	0+223	Clay	6.00	1.55	1.59	1.54	1.55	1.59	1.68	1.74		2.160	
BH-005-35	2+914	Clay	1.68	1.60	1.50	1.54	1.64	1.54	1.63	1.74		1.610	
BH-006-35	3+400	Clay	1.43	1.46	1.41	1.41	1.45	1.77	1.69	1.60		1.530	
BH-007-35	4+180	Clay	1.82	1.83	1.80	1.84	1.88	1.94	1.98	2.14		1.900	
BH-009-35	6+560	Clay	1.64	1.65	1.68	1.84	1.73	1.84	1.79	1.74		1.740	
BH-010-35	6+835	Clay	1.45	1.53	1.49	1.67	1.73	1.78	1.64	1.93		1.650	
BH-011-35	7+400	Clay	1.64	1.68	1.79	1.84	1.50	1.63	1.65	1.84		1.700	

Bore Hole No.	Bore Hole Location (KP)	Soil Type	Undrained Shear Strength, $S_u$ (t/m <sup>2</sup> ) <sup>(1)</sup>										Average Undrained Shear Strength, $S_u$ (t/m <sup>2</sup> )
			Depth										
			0.00-1.50 m	1.50-3.00 m	3.00-4.50 m	4.50-6.00 m	6.00-7.50 m	7.50-9.00 m	9.00-10.5 m	10.5-12.0 m			
BH-012-35	8+266	Clay	2.49	1.45	1.47	1.52	1.58	1.63	1.49	1.74			1.670
BH-013-15	8+708	Clay	1.50	1.54	1.49	1.78	1.69	1.75	1.79	1.89			1.680
BH-014-15	8+806	Clay	1.51	1.54	1.55	1.68	1.59	1.69	1.79	1.84			1.650
BH-015-35	9+100	Clay	1.64	1.64	1.57	1.52	1.63	1.47	1.52	1.78			1.600
BH-016-35	9+300	Clay	1.49	1.62	1.58	1.44	1.49	1.53	1.64	1.67			1.560
BH-017-35	9+623	Clay	1.45	1.48	1.50	1.52	1.71	1.88	1.80	1.71			1.630
BH-018-35	12+516	Clay	1.47	1.44	1.49	1.45	1.63	1.59	1.68	1.73			1.560
BH-019-35	13+830	Clay	1.44	1.48	1.44	1.49	1.55	1.49	1.54	1.54			1.496
BH-020-35	14+965	Clay	2.66	1.68	1.52	1.44	1.45	1.49	1.53	1.54			1.664
BH-021-35	15+443	Clay	1.42	1.43	1.44	1.51	1.47	1.56	1.54	1.48			1.481
BH-022-35	16+285	Clay	1.52	1.50	1.48	1.45	1.49	1.52	1.49	1.61			1.508
BH-023-35	17+036	Clay	2.66	1.61	1.54	1.42	1.42	1.48	1.61	1.70			1.680
BH-024-35	18+650	Clay	2.00	1.48	1.44	1.46	1.44	1.46	1.52	1.66			1.558
BH-025-35	18+966	Clay	1.63	1.59	1.54	1.49	1.45	1.49	1.49	1.63			1.539
BH-026-35	19+166	Clay	2.16	1.58	1.54	1.63	1.64	1.73	1.79	1.89			1.745
BH-027-35	19+860	Clay	1.51	1.53	1.44	1.42	1.61	1.61	1.64	1.68			1.555
BH-028-35	20+717	Clay	1.64	1.66	1.47	1.54	1.51	1.71	1.66	1.84			1.629
BH-031-35	24+616	Clay	1.47	1.78	1.59	1.59	1.58	1.57	1.56	1.61			1.594
BH-032-35	25+382	Clay	1.42	1.52	1.48	1.44	1.44	1.49	1.52	1.57			1.485
BH-033-35	27+912	Clay	1.62	1.58	1.53	1.51	1.49	1.51	1.61	1.63			1.560
BH-034-35	28+631	Clay	1.49	1.46	1.42	1.66	1.68	1.66	1.70	1.82			1.611
BH-035-35	30+048	Clay	2.66	1.49	1.56	1.59	1.61	1.57	1.43	1.87			1.723
BH-036-35	31+462	Clay	1.44	1.44	1.41	1.44	1.41	1.42	1.46	1.47			1.436
BH-037-35	32+150	Clay	33.30	18.60	1.52	1.51	1.49	1.54	1.51	1.74			7.651

Note - (1) The value of undrained shear strength as shown is considered as average value in each range of depth.

Table 8.3: Comparison of Soil Properties

The worst soil property is at bore hole BH-036-35, which shall be representative for all borehole. Soil property in each layer is presented in Table 8.1-1.

Table 8.3-1 Soil Property in Each Layer

Depth (m)		Soil Description	Unit Weight, $\gamma$ t/m <sup>3</sup>	SPT-N Value blows/ft	Internal Friction Angle, $\phi$ Degrees	Undrained Shear Strength, $S_u$ t/m <sup>2</sup>
From	To					
0.00	1.95	Clay	1.40	-	-	1.44
1.95	3.45	Clay	1.40	-	-	1.44
3.45	4.95	Clay	1.40	-	-	1.41
4.95	6.45	Clay	1.40	-	-	1.44
6.45	7.95	Clay	1.40	-	-	1.41
7.95	9.45	Clay	1.40	-	-	1.42
9.45	10.95	Clay	1.41	-	-	1.46
10.95	12.45	Clay	1.41	-	-	1.47

The soil characteristics and parameters to be used in this calculation are referred to pipeline soil investigation report.

The relation of SPT-N value and undrained shear strength of clay is taken from Terzaghi, K. and Peck, R.B. (1948) "Soil Mechanics in Engineering Practice," John Wiley & Sons, Inc., New York, 1967 and is given as follows;

$$S_u = N/1.5 \text{ or } N/1.5 \text{ tonne/m}^2$$

or undrained shear strength can be found from Figure 8.2,




Figure 8.2: The Relation of SPT-N Value and Unconfined Compressive Strength of Clay

9.0 DESIGN LOADINGS

The design loadings that are applied to sheet pile pit are stated as below.

Surcharge load at the top of pit:  $Q_u = 2,000 \text{ kg/m}^2$

The surcharge load shall follow DPT 1911-52, Section 4.3.2.4, Table 1 for temporary excavation work (duration less than 6 months).

Gravity self-weight depending on soil property is shown in Table 8.3-1.

10.0 CONSTRUCTION DETAILS

10.1 Bored and Tie-In Pits

They are three types of temporary sheet pile installation depth that the detail of each shall be shown excavated from the existing ground surface to the estimated depth.

10.1.1 Type – Depth of sheet pile is not over 4.0 m

Stage 1: Excavated pit from existing ground to below of strut and wale location elevation of -1.5 m (h1). During this activity, the sheet piles are resisting the soil pressure in cantilever.




Figure 10.1: Stage 1 Typical Section

Stage 2: Install upper wale and strut at EL.1.0 m from ground level (H1) as shown in Figure 10.2.





Figure 10.2: Stage 2 Typical Section

Stage 3: Excavated soil from elevation of -1.50m to bottom pit of -4.00 m as shown in Figure 10.3.



### Figure 10.3: Stage 3 Typical Section

#### 10.1.2 Type - Depth of sheet pile is over 4.0 m and not over 7.0 m

Stage 1: Excavated pit from existing ground to below of strut and wale location elevation of -1.5 m (h1). During this activity, the sheet pile is resisting the soil pressure in cantilever.




Figure 10.4: Stage 1 Typical Section

Stage 2: Install upper wale, strut at EL.-1.00 m from ground level (H\_1) as shown in Figure 10.5.




Figure 10.5: Stage 2 Typical Section

Stage 3: Excavated soil from elevation of -1.50m to elevation of -4.50 m as shown in Figure 10.6.




Figure 10.6: Stage 3 Typical Section

Stage 4: Install second wale, strut at EL.-4.00 m as shown in Figure 10.7.




Figure 10.7: Stage 4 Typical Section

Stage 5: Excavated soil from elevation of -4.50m to bottom pit of -7.00 m. as shown in. Figure 10.8.




Figure 10.8: Stage 5 Typical Section

Stage 6: Prior to lowering pipe, the middle strut at elevation -4.0 m shall be removed




Figure 10.9: Stage 6 Typical Section

Stage 7: After the pipe is lowered-in, the removed middle strut must be installed back immediately.




Figure 10.10: Stage 7 Typical Section

10.1.3 Type - Depth of sheet pile is over 7.0 m and not over 10.0 m

Stage 1: Excavated pit from existing ground to below of strut and wale location elevation of -1.5 m ( $h_1$ ). During this activity, the sheet pile are resisting the soil pressure in cantilever.




Figure 10.11: Stage 1 Typical Section

Stage 2: Install upper wale, strut at EL. -1.00 m from ground level ( $H_1$ ) as shown in Figure 10.12.




Figure 10.12: Stage 2 Typical Section

Stage 3: Excavated soil from elevation of -1.50 m elevation -4.50 m ( $h_2$ ) as shown in Figure 10.13.




Figure 10.13: Stage 3 Typical Section

Stage 4: Install second wale, strut at EL. -4.0 m as shown in Figure 10.14.




Figure 10.14: Stage 4 Typical Section

Stage 5: Excavated soil from elevation of -4.50m to elevation of -7.50 m(h3), as shown in figure below.




Figure 10.15: Stage 5 Typical Section

Stage 6: Install the third wale, strut at EL.-7.00 m




Figure 10.16: Stage 6 Typical Section

Stage 7: Excavated soil from elevation of -7.50m to bottom pit of -10.0 m.




Figure 10.17: Stage 7 Typical Section

Stage 8: Prior to lowering pipe, the middle strut at elevation -4.0m shall be removal as shown in Figure 10.18.




Figure 10.18: Stage 8 Typical Section

Stage 11: After the pipe is lowered-in, the removed lower strut must be installed as the same as shown in Figure 10.21.




Figure 10.21: Stage 11 Typical Section

## 10.2 Direct Pipe Pit

10.2.1 Type – Depth of sheet pile is not over 4.5 m (Entry and Exit Pits)

Stage 1: Excavated pit from existing ground to below of strut and wale location elevation of -1.5 m (h1). During this activity, the sheet piles are resisting the soil pressure in cantilever.




Figure 10.22: Stage 1 Typical Section

Stage 9: After pipe is lowered-in to elevation 4.0 m, the removed middle strut must be installed as the same as shown in Figure 10.19.




Figure 10.19: Stage 9 Typical Section

Stage 10: Remove lower strut at elevation -7.0m as shown in Figure 10.20.




Figure 10.20: Stage 10 Typical Section

Stage 2: Install upper wale and strut at EL. 1.0 m from ground level (H1) as shown in Figure 10.23.




Figure 10.23: Stage 2 Typical Section

Stage 3: Excavated soil from elevation of -1.50 m to bottom pit of -4.50 m as shown in Figure 10.24.




Figure 10.24: Stage 3 Typical Section

### 11.0 CALCULATION RESULTS

The results for sheet pile Bored & Tie-In pits and direct pipe pits are presented in Table 11.1 and Table 11.2, respectively.

Bored and Tie-In Pits (The width of pit of 3.0 m)

Description	Sheet Pile Pit Detail			Remark
	Depths ≤ 4.0m	Depth 4.0 to 7.0m	Depth 7.0 to 10.0m	
Maximum width of pit, m	3.0	3.0	3.0	-
Maximum depth of pit, m	4.0	7.0	10.0	-
Pit Type	Sheet pile with strut, wale and bracing			-
Sheet pile embedded depth from bottom, m	5.00	5.00	4.00	-
Type of sheet pile	SP-III/A			Pass
Sheet pile length required, m	9.00	12.00	14.00	Pass
Strut section	H300x300x10x15mm			-
• Factor of safety	Ratio =0.221	Ratio =0.632	Ratio =0.618	Allow. < 1.0
• Spacing, m	9.00 in longitudinal with diagonal brace of 1.0 m both sides			
Wale section	1 <sup>st</sup> = H300x300 (EL.-1.0m) 2 <sup>nd</sup> = H350x350 (EL.-4.00m)	1 <sup>st</sup> = H300x300 (EL.-1.0m) 2 <sup>nd</sup> = H350x350 (EL.-4.00m)	1 <sup>st</sup> = H300x300 (EL.-1.0m) 2 <sup>nd</sup> = H350x350 (EL.-4.00m) 3 <sup>rd</sup> = H350x350 (EL.-7.0m)	-
• Factor of safety	Ratio =0.774	Ratio(1 <sup>st</sup> ) =0.477 Ratio(2 <sup>nd</sup> ) =0.959	Ratio(1 <sup>st</sup> ) =0.57 Ratio(2 <sup>nd</sup> &3 <sup>rd</sup> ) =0.936	Allow. < 1.0
• Spacing, m	-	3.0 m in vertical	3.0 m in vertical	-
Bracing between strut and wale	H400x400x13x21mm			-
• Factor of safety	Ratio =0.109	Ratio =0.21	Ratio =0.208	Allow. < 1.0

Table 11.1: Bored & Tie-In Pits Result

Direct Pipe for Entry and Exit Pits (The width of pit of 7.10 m& 3.0 m, respectively)

Description	Sheet Pile Pit Detail		Remark
	Entry Pit Depths ≤ 4.5m	Exit Pit Depths ≤ 4.5m	
Maximum width of pit, m	7.10	3.0	-
Maximum depth of pit, m	4.50	4.50	-
Pit Type	Sheet pile with strut, wale and bracing	Sheet pile with wale	-
Sheet pile embedded depth from bottom, m	3.5	3.5	-
Type of sheet pile	SP-III/A		Pass
Sheet pile length required, m	8.00	8.00	Pass
Strut section	H582x300x12x17mm	-	-
• Factor of safety	Ratio =0.47	-	Allow. < 1.0
• Spacing, m	See Appendix B	-	-
Wale section	1 <sup>st</sup> = H582x300 (EL.-1.0m)	1 <sup>st</sup> = H582x300 (EL.-1.0m)	-
• Factor of safety	Ratio =0.969	Ratio =0.853	Allow. < 1.0
• Spacing, m	-	-	-
Bracing between strut and wale	H582x300x12x17mm	-	-
• Factor of safety	Ratio =0.212	-	Allow. < 1.0

Table 11.2: Direct Pipe Pits Results

Regarding results above, the sheet pile pit is capable to withstand the relevant load condition as per design criteria.

The design is safe as per applicable code/standard practice.



PTT PUBLIC COMPANY LIMITED

REV NO.	DATE	BY	CHK	PM/EM	DESCRIPTION

BANGPAKONG – SOUTH BANGKOK POWER PLANT  
TRANSMISSION PIPELINE PROJECT – PHASE 2

DIRECT PIPE WORK DESIGN & ANALYSIS REPORT  
DP#21 KP50+258 TO KP51+134

TOTAL 81 PAGES

DOCUMENT REVIEW	
<input type="checkbox"/> E :	Work may proceed.
<input type="checkbox"/> F :	Work may proceed. Submit Final Document. <input type="checkbox"/> Incorporate comments and resubmit.
<input type="checkbox"/> G :	Revise and resubmit. Work may proceed subject to incorporation of changes indicated.
<input type="checkbox"/> H :	Revise and resubmit. Work may not proceed.
<input type="checkbox"/> I :	Review is not required. Work may proceed.
By :	Date :

Consultant 	Contractor 	AREA CODE GENERAL : 010	SNP PROJECT NO. -
		PTT CONTRACT NO. PTT.IBG. /2187/65	PTT PROJECT NO. 2204.01

1. INTRODUCTION

This report has been prepared to present the analysis and calculation of Direct Pipe Pushing Force Stress Analysis Thruster Anchor Entry & Exit pit. According to all entry and thruster anchor in this project are located in Soft Clay Zone where soil characteristics of soft clay likely be the same. Thus, if there is no changing in shape of anchor and entry pit. This paper can be applied to Direct Pipe (DP) DP#21 KP50+248-KP51+041 in South Bangkok Power Plant Transmission Pipeline Project – Phase 2 Project.

2. PIPE THRUSTER ANCHOR

2.1 GENERAL

Normally pipe thruster is positioned and anchored to a sheet piling system. But for this project where subsoil composes of soft clay for about 21 m thick. A proper platform with piling is needed for the pipe thruster. Moreover, as the working space is limited by overhead transmission lines. Only sheet piles and other types of piles with limited pile length of 12 meters are allowed. Therefore, sheet piles SP-III 56 nos. with 12.00 m of length for front side thruster and SP-III 56 nos. with 12.00 m of length for back side thruster and H-Beam 400x400x13x21 mm for an ties low are selected in thruster anchor erection.

2.2 LOADS

1) Dead load

• Thruster load	=	30	tonnes
• Cutter	=	19	tonnes
• Clamp	=	21	tonnes
• Ø36 in steel pipe	=	7	tonnes
Total	=	77	tonnes

2) Thrusting force

• Thrusting force	=	309.962	tonnes
-------------------	---	---------	--------

(Maximum value of minimum requirement of thrusting force per Appendix A)

2.3 MATERIALS

The proposed materials used in the thruster anchor compose of:

1) Steel Sheet pile SPT-III	
• Sizing	400 mm
• Wall thickness	13 mm
• Weight	60 kg/m
• Length	12 m
2) H-Beam	
• Size (W x B x t1 x t2)	400 x 400 x 13 x 21 mm
(Weight 172 kg/m)	
• Size (W x B x t1 x t2)	300 x 300 x 10 x 15 mm
(Weight 94 kg/m)	

The preferable depth of the entry pit is 3.50 m. However, stability of the pit and pipe thruster must be taken into account.




Figure 2  
Plan of Entry Pit and Thruster Anchor

The first trial analysis with the entry pit depth of 3.50 m was taken. The output is that, the lateral movement of the anchor is 3.50 m backward. This means that the thruster and its anchor will be removed from its position and the entry pit will be destroyed (see Figure 3).




Figure 3  
Deformation of Thruster Anchor and Entry Pit

Several trials had been determined to find out an appropriate anchor for the thruster. As aforementioned, this project is located in soft clay of about 21 m thick and only 12 m steel sheet piles can be used. Therefore, the anchor of sheet piles SP-III 56 nos. with 12.00 m steel sheet piles for front side thruster and SP-III 56 nos. with 12.00 m of length for back side thruster are required to support both designed dead weight and thrusting force (Figure 1).




Figure 1  
Proposed Anchor Structure

Structural analysis of above anchor structure has been performed using Robot Structure software. The analysis results are presented in Appendix A.

### 3. ENTRY PIT

Entry pit is a launch pit in pipeline installation by direct pipe method. The proposed dimension of this entry pit is as followed:

The shape and dimension of entry pit are as follow:


- Width of pit (W) 6.80 m.
- Length of pit (L) 24.00 m.

Set of trial analyses were performed to shallower depths of entry pit. Finally, it is found that the pit with 1.80 m depth shall be applied for center direct pipe launching pit. The analysis of the entry pit is presented in the following section.

#### 4. ANALYSIS OF ENTRY PIT AND THRUSTER ANCHOR

#### 4.1 ENTRY PIT & ANCHOR SECTION

The plan of entry pit and anchor shall refer to Figure 2 while the propose section shall refer to Figure 3.



DIRECT PIPE ENTRY PIT ANCHORE SECTION

### Figure 3

## Section of Entry Pit and Thruster Anchor

## 4.2 SOIL PROPERTIES PARAMETER

As there are very few soil characteristics available for this analysis program therefore, some typical values of soil mechanical properties are used. The representative soft clay properties used in this analysis are as followed.

1) Unit weight	=	14.50	kN/m <sup>3</sup>
2) Undrained shear strength	=	15.00	kN/m <sup>2</sup>
3) Elastic modulus of clay	=	3132	kN/m <sup>2</sup>
4) Change of permeability	=	1x10 <sup>-15</sup>	
5) Initial void ratio	=	0.50	
6) Poisson ration	=	0.35	
7) Shear modulus	=	1160	kN/m <sup>2</sup>
8) Udometric modulus, $E_{ued}$	=	5026.667	kN/m <sup>2</sup>

### 4.3 STAGE OF CONSTRUCTION

**In doing geotechnical analysis, construction of entry pit and thruster anchor has been divided into 3 stages as followed:**

### 1) First Stage: Entry Pit Construction

- Setup the wale using H-Beam 400 x 400 mm at the level of above ground surface.
- Install all SPIII sheet piles of 12.00 m long to the depth of 11.00 m and leave the other end of sheet piles remain above ground for 1.00 m. No need hard barricade
- Excavate the pit to the depth of 3.50 m below ground surface and remove excavated soil to an area provided for spoil bank

*Remark:*

Be reminded that this spoil bank must be 5 m away from the edge of pit and height of bank shall not be higher than 1 m.

- Install the wale using H-Beam 400 x 400 mm at the level of 0.50 m below ground surface.

## 2) Second Stage: Thruster Anchor Installation

- Install the thruster anchor at the bottom of entry pit
- Set up pipe thruster and related equipment

### 3) Third Stage: Pipe Thrusting

- Performing pipe thrusting by applying thrusting force of 309,962 tonnes.

#### 4.4 ANALYSIS RESULTS

**Analysis results of each stage are summarized below.**

### 1) First Stage: Entry Pit Construction

• Horizontal displacement	=	100.86	mm
• Vertical displacement	=	86.22	mm
• Safety Factor	=	1.226	

Above displacement is sign of earth movement or earth flow in the direction to the cut area. However, the installed sheet piles and bracing unit are still stable for temporary use as the safety factor is acceptable.

## 2) Second Stage: Thruster Anchor Installation

• Horizontal displacement	=	12.44	mm
• Vertical displacement	=	- 27.43	mm
• Safety Factor	=	1.577	

DESIGN BY : CIVIL ENGINEER

Mr. Anuchai Saenbootra  
Professional Civil Engineer (Level 2)  
License # Sor Yor 12252

After the thruster anchor is installed into the entry pit. The rate of earth displacement is decreased. There is a sign of settlement as vertical displacement is in downward direction. However, the entry pit and thruster anchor are still stable as the safety factor is acceptable

Third Stage: Pipe Thrusting

- Horizontal displacement = 665.60 mm
- Vertical displacement = 532.23 mm
- Safety Factor = 1.039

By applying thruster force of 303.962 tonnes, there are quite large displacement in both horizontal and vertical direction. According to the output of safety factor of 1.5, it seems that the thruster and its anchor are about to collapse.

5. CONCLUSION

- As the working space in this project is limited by overhead transmission lines. The length of sheet piles longer than 12 meters for thruster anchor erection longer than 12 meters are not allowed to be used.
- Since subsoil in this project composes of soft clay for about 21 m thick. So, the entry pit with 12 m sheet pile wall and thruster anchor with the anchor of sheet piles SP-III 56 nos. with 12.00 m steel sheet piles for front side thruster and SP-III 56 nos. with 12.00 m of length for back side thruster are use refer to designed soil pressure, dead weight and thrusting force (Figure 1).
- According to analysis results, the depth of entry pit shall not be deeper than 3.00 m.
- Without thrusting force of 303.962 tonnes, the entry pit and thruster anchor are stable. But when applying thrusting force more than 500 tonnes, the entry pit and thruster anchor seem to collapse.

6. RECOMMENDATION

To avoid entry pit and thruster anchor from collapse, it is recommended applying thrusting force up to 350 tonnes must be careful. Earth and sheet piles movement around the pit shall be observed. Once there is a sign of movement, thrusting force applying shall be release or stopped.

DESIGN BY : CIVIL ENGINEER

Mr. Anuchai Saenbootra  
Professional Civil Engineer (Level 2)  
License # Sor 12252

STEEL BRAZING DESIGN

CODE: ANS/AISC 360-16 An American National Standard, July 7, 2016  
ANALYSIS TYPE: Member Verification

CODE GROUP:

MEMBER: 4 Simple bar\_4 POINT: 1 COORDINATE: x = 0.00 L = 0.00 m

LOADS:

Governing Load Case: 1 DL1

MATERIAL:

STEEL Fy = 2500.00 kgf/cm2 Fu = 4000.00 kgf/cm2 E = 2100000.00 kgf/cm2



SECTION PARAMETERS: H 400x400x168

d=39.4 cm Ay=145.80 cm2 Az=70.92 cm2 Ax=214.40 cm2  
bf=40.5 cm Iy=59700.00 cm4 Iz=20000.00 cm4 J=291.22 cm4  
tw=1.8 cm Sy=3030.46 cm3 Sz=987.65 cm3  
tf=1.8 cm Zy=3390.10 cm3 Zz=1511.00 cm3

MEMBER PARAMETERS:

Ly = 6.50 m Lz = 6.50 m Lb = 6.50 m  
Lcy = 6.50 m Lcz = 6.50 m Cb = 1.00  
Lcylry = 38.95 Lczl rz = 67.30



INTERNAL FORCES:

Tr = 5.94 kgf\*m  
fvy.mx = 3.67 kgf/cm2  
fvz.mx = 3.67 kgf/cm2  
Pr = -107418.81 kgf  
Mry = -8758.92 kgf\*m  
Fiv\*Vny = 196830.00 kgf  
Mrz = -1699.10 kgf\*m  
1.00\*Vnz = 106380.00 kgf  
Vry = -1400.51 kgf  
Vrz = 21454.35 kgf  
Fib\*Pnty = 482400.00 kgf  
Fib\*Mny = 73303.87 kgf\*m  
Fib\*Mnz = 33997.59 kgf\*m

DESIGN STRENGTHS

SAFETY FACTORS

Fib = 0.90 Fiv = 0.90

SECTION ELEMENTS:

Flange = Compact Web = Compact

VERIFICATION FORMULAS:







Pr/(Fity\*Pnty) + 8/9\*(Mry/(Fib\*Mny) + Mrz/(Fib\*Mnz)) = 0.37 < 1.00 LRFD (H1-1a) Verified  
Vry/(Fiv\*Vny) + fvy.mx/(0.6\*Fiv\*Fy) = 0.01 < 1.00 LRFD (G) Verified  
Vrz/(1.00\*Vnz) + fvz.mx/(0.6\*1.00\*Fy) = 0.20 < 1.00 LRFD (G) Verified  
Lcylry = 38.95 < (Lcrlr).max = 300.00 Lczl rz = 67.30 < (Lcrlr).max = 300.00 STABLE

Section OK !!!

DESIGN BY : CIVIL ENGINEER

Mr. Anuchai Saenbootra  
Professional Civil Engineer (Level 2)  
License # Sor 12252

STEEL SHEET PILE DESIGN

CODE: ANS/AISC 360-16 An American National Standard, July 7, 2016			
ANALYSIS TYPE: Member Verification			
CODE GROUP:	SP-III	POINT: All	COORDINATE: x = 0.17 L = 4.00 m
MEMBER: Governing Load Case: 6 Combination Load Case			
LOADS:			
MATERIAL: STEEL $F_y = 2500.00 \text{ kgf/cm}^2$ $F_u = 4000.00 \text{ kgf/cm}^2$ $E = 2100000.00 \text{ kgf/cm}^2$			
<div></div> <div>SECTION PARAMETERS: SP III 400x400x12</div> <div><math>d=39.4 \text{ cm}</math>    <math>A_y=145.80 \text{ cm}^2</math>    <math>A_z=70.92 \text{ cm}^2</math>    <math>A_x=214.40 \text{ cm}^2</math> <math>b_f=40.5 \text{ cm}</math>    <math>I_y=59700.00 \text{ cm}^4</math>    <math>I_z=20000.00 \text{ cm}^4</math>    <math>J=291.22 \text{ cm}^4</math> <math>t_w=1.8 \text{ cm}</math>    <math>S_y=3030.46 \text{ cm}^3</math>    <math>S_z=987.65 \text{ cm}^3</math> <math>t_f=1.8 \text{ cm}</math>    <math>Z_y=3390.10 \text{ cm}^3</math>    <math>Z_z=1511.00 \text{ cm}^3</math></div>			
<div></div> <div>MEMBER PARAMETERS:</div> <div><math>L_y = 24.00 \text{ m}</math>    <math>L_z = 24.00 \text{ m}</math>    <math>L_b = 24.00 \text{ m}</math> <math>L_{cy} = 24.00 \text{ m}</math>    <math>L_{cz} = 24.00 \text{ m}</math>    <math>C_b = 1.00</math> <math>L_{cy}/r_y = 143.83</math>    <math>L_{cz}/r_z = 248.49</math></div>			
<div></div> <div>INTERNAL FORCES:</div> <div><math>T_r = 6.02 \text{ kgf}^*\text{m}</math>    <math>f_{rvy, mx} = 3.72 \text{ kgf/cm}^2</math>    <math>f_{rvz, mx} = 3.72 \text{ kgf/cm}^2</math> <math>P_r = 1755.97 \text{ kgf}</math>    <math>V_{ry} = 137.87 \text{ kgf}^*\text{m}</math>    <math>V_{ry} = 725.95 \text{ kgf}</math>    <math>F_{ic}^*P_n = 56802.66 \text{ kgf}</math> <math>F_{iv}^*V_{ny} = 196830.00 \text{ kgf}</math>    <math>F_{ib}^*M_{ny} = 38993.17 \text{ kgf}^*\text{m}</math> <math>M_{rz} = -628.29 \text{ kgf}^*\text{m}</math>    <math>V_{rz} = 235.69 \text{ kgf}</math>    <math>F_{ib}^*M_{nz} = 33754.81 \text{ kgf}^*\text{m}</math> <math>1.00^*V_{nz} = 106380.00 \text{ kgf}</math></div>			
<div></div> <div>SAFETY FACTORS</div> <div><math>F_{yb} = 0.90</math>    <math>F_{ic} = 0.90</math>    <math>F_{iv} = 0.90</math></div>			
<div></div> <div>SECTION ELEMENTS:</div> <div>Flange = Non-compact    Web = Compact</div>			
<div></div> <div>VERIFICATION FORMULAS:</div> <div><math>P_r/(2^*F_{ic}^*P_n) + M_{rz}/(F_{ib}^*M_{ny}) + M_{rz}/(F_{ib}^*M_{nz}) = 0.04 &lt; 1.00</math>    LRFD (H1-1b)    Verified <math>V_{ry}/(F_{iv}^*V_{ny}) + f_{rvy, mx}/(0.6^*F_{iv}^*F_y) = 0.01 &lt; 1.00</math>    LRFD (G)    Verified <math>V_{rz}/(1.00^*V_{nz}) + f_{rvz, mx}/(0.6^*1.00^*F_v) = 0.00 &lt; 1.00</math>    LRFD (G)    Verified <math>L_{cy}/r_y = 143.83 &lt; (L_{cy}/r)_y, \max = 200.00</math>    <math>L_{cz}/r_z = 248.49 &gt; (L_{cz}/r)_z, \max = 200.00</math>    INSTABLE</div>			

Instability !!!

DESIGN BY : CIVIL ENGINEER

Mr. Anuchai Saenbootra  
Professional Civil Engineer (Level 2)  
License # Sor Yor 12252

ตามประมวลกฎหมายอาญา หมวด 3 ความผิดเกี่ยวกับเอกสาร

มาตรา 269 ผู้ใด ในการประกอบกิจการงาน ในวิชา แพทย์ กฎหมาย บัญชี หรือวิชาชีพอื่นใด ทำเป็นค้ำรับรอง เป็น เอกสาร อันเป็นเท็จ โดยประการที่น่าจะเกิดความเสียหายต่อผู้อื่น หรือ ประชาชน ต้องระวางโทษ จำคุกไม่เกินสองปี หรือปรับไม่เกิน สี่พันบาท หรือ ทั้งจำทั้งปรับ

ผู้ใดโดยทุจริตใช้ หรืออ้างค้ำรับรองอันเกิดจากการกระทำความผิดตามความวรรคแรก ต้องระวางโทษ