

## ภาคผนวก ข-41

---

เอกสารการทบทวนเหตุการณ์อุบัติเหตุ/อุบัติภัย

S and L Specialty Polymers Co., Ltd.

บริษัท เอส แอนด์ แอล สเปเชียลตี้ โพลีเมอร์ จำกัด

CONTROLLED

Incident and Investigation Report Procedure

ISSUED

18 MAY 2018

S and L Specialty Polymers Co., Ltd.

SL-HSE-QP-016

Prepared by

Approved by

18 / 5 / 2018

18 May 2018

List of Changes

Created Date	Effective Date	Rev	Revised Record
18.05.2018	18.05.2018	1	1. เพิ่มการใช้เอกสาร Production Trouble Report 2. แก้ไขระยะเวลาสอบสวน ภายใน 48 ชั่วโมง

Originator	Distribution	MA	HG	FA	PD	HSE	ME	DC	BOI	PU	LO	QC	Total
HSE	No. of Copy	-	1	1	1	1	1	1	-	-	1	1	8

S and L Specialty Polymers Co., Ltd.

Quality Procedure

Document No. : SL-HSE-QP-016

Effective Date. : May. 18, 18

Rev.1

Page : 2/17

Incident and Investigation report  
procedure

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 3/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 4/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 5/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 6/17		



S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 7/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 8/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 9/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 10/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 11/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 12/17		


S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 13/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 14/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 15/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 16/17		

S and L Specialty Polymers Co., Ltd.		Quality Procedure
		Document No. : SL-HSE-QP-016
Effective Date. : May. 18, 18	Rev.1	Incident and Investigation report procedure
Page : 17/17		



## ภาคผนวก ข-42

---

เอกสารรับรองการใช้งานรถยก Forklift และการควบคุมใช้งานเครน



# NICHIYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Roongcharoen, Uthong Suvarnabhumi Rd., Bangpla, Bangkok, Samutprakarn 10540  
 Service Suvarnabhumi : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (038) 116-838-40, (081) 496-0394 Fax. (038) 116-841  
 Service Ayuthaya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-798, (081) 399-1839 Fax (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHIYU  
ELECTRIC FORKLIFT



NO. 1

Customer NIPPON EXPRESS Branch \_\_\_\_\_ Date 20-6-23 Book no. 47464  
 Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel \_\_\_\_\_  
 Truck Model FB25PN-80C-3F4708F Serial Number 257D01476 Hour Meter 816 Job Type R/T

Component	No	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	<input checked="" type="checkbox"/>	
	2	Brake Oil	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	<input checked="" type="checkbox"/>	
	4	Brake Shoe	Function/Operation	<input checked="" type="checkbox"/>	
	5	Brake pedal	Stroke/Operation	<input checked="" type="checkbox"/>	
	6	Parking Brake	Function/Operation	<input checked="" type="checkbox"/>	
Steering	7	Steering Knob/wheel	Free play/Operation	<input checked="" type="checkbox"/>	
	8	Steering Gear Case	Function/Operation	<input checked="" type="checkbox"/>	
	9	Tie-rod/Drag Link	Damage/Visual	<input checked="" type="checkbox"/>	
	10	Steering Cylinder	Oil Leak/Visual	<input checked="" type="checkbox"/>	
	11	Rear Axle	Function/Operation	<input checked="" type="checkbox"/>	
	12	Steering Chain	Lubricate,Tension/Visual	<input checked="" type="checkbox"/>	
Tire	13	Gear Case	Oil leak/Visual	<input checked="" type="checkbox"/>	
	14	Hub/Rim Bolts	Looseness/Tightening	<input checked="" type="checkbox"/>	
	15	Wheel Bearing	Noise/Operation	<input checked="" type="checkbox"/>	
	16	Front wheel	Wear,Damage/Visual	<input checked="" type="checkbox"/>	
	17	Rear wheel	Wear,Damage/Visual	<input checked="" type="checkbox"/>	
	18	Mast Shoe	Abnormal Play/Operation	<input checked="" type="checkbox"/>	
Mast Hydraulic	19	Lift Chain	Extension/Guage	<input checked="" type="checkbox"/>	
	20	Hose Pulley/Guard	Damage/Visual	<input checked="" type="checkbox"/>	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	<input checked="" type="checkbox"/>	
	22	Lift Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
	23	Tilt Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
	24	Attachment Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
Battery Charger	25	Hydraulic Oil	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
	26	Hose/Piping	Damage,Oil leak/Visual	<input checked="" type="checkbox"/>	
	27	Fork	Thickness/Measure	<input checked="" type="checkbox"/>	Measure mm, Limit mm, Standard mm.
	28	Backrest	Damage/Visual	<input checked="" type="checkbox"/>	
	29	Attachment Function	Function/Operation	<input checked="" type="checkbox"/>	
	30	Hydraulic Lever	Looseness/Operation	<input checked="" type="checkbox"/>	
Electric	31	Battery Water	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
	32	Terminal	Dirt/Visual	<input checked="" type="checkbox"/>	
	33	Battery Plug	Damage/Visual	<input checked="" type="checkbox"/>	
	34	Charger	Condition/Visual	<input checked="" type="checkbox"/>	
	35	Gas Spring	Damage/Operation	<input checked="" type="checkbox"/>	
	36	Seat/Seat belt	Damage/Visual,Operation	<input checked="" type="checkbox"/>	
Frame	37	Key Switch	Function/Operation	<input checked="" type="checkbox"/>	
	38	Horn/Buzzer	Sound/Operation	<input checked="" type="checkbox"/>	
	39	Head lamp	Function/Operation	<input checked="" type="checkbox"/>	
	40	Rear Combination Lamp	Function/Operation	<input checked="" type="checkbox"/>	
	41	Turn Signal Lamp	Function/Operation	<input checked="" type="checkbox"/>	
	42	Directional Switch	Function/Operation	<input checked="" type="checkbox"/>	
Frame	43	Micro Switch	Function/Operation	<input checked="" type="checkbox"/>	
	44	Contact	Burn/Function	<input checked="" type="checkbox"/>	
	45	Motor Brush	Thickness/Visual	<input checked="" type="checkbox"/>	Motor : Measure mm, Limit mm, Standard mm.
	46	EPS System	Function/Operation	<input checked="" type="checkbox"/>	
	47	Control System (Trv, Hyd)	Function/Operation	<input checked="" type="checkbox"/>	
	48	Others/Accessory	Function/Operation	<input checked="" type="checkbox"/>	
Frame	49	Head Guard	Damage/Visual	<input checked="" type="checkbox"/>	
	50	Chassis Frame	Damage/Visual	<input checked="" type="checkbox"/>	
	51	Lubricate	Condition/Visual	<input checked="" type="checkbox"/>	

Comments การตรวจเช็คสภาพรถ Forklift ☒ Good ☒ Need Repair ☐ A Adjust ☐ N/A

Customer Sign \_\_\_\_\_

# NICHIYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Roongcharoen, Uthong Suvarnabhumi Rd., Bangpla, Bangkok, Samutprakarn 10540  
 Service Suvarnabhumi : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (038) 116-838-40, (081) 496-0394 Fax. (038) 116-841  
 Service Ayuthaya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-798, (081) 399-1839 Fax (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHIYU  
ELECTRIC FORKLIFT



NO. 2

Customer NIPPON EXPRESS Branch \_\_\_\_\_ Date 20-6-23 Book no. 47465  
 Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel \_\_\_\_\_  
 Truck Model FB25PN-80C-3F4708F Serial Number 257D01477 Hour Meter 1012 Job Type R/T

Component	No	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	<input checked="" type="checkbox"/>	
	2	Brake Oil	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	<input checked="" type="checkbox"/>	
	4	Brake Shoe	Function/Operation	<input checked="" type="checkbox"/>	
	5	Brake pedal	Stroke/Operation	<input checked="" type="checkbox"/>	
	6	Parking Brake	Function/Operation	<input checked="" type="checkbox"/>	
Steering	7	Steering Knob/wheel	Free play/Operation	<input checked="" type="checkbox"/>	
	8	Steering Gear Case	Function/Operation	<input checked="" type="checkbox"/>	
	9	Tie-rod/Drag Link	Damage/Visual	<input checked="" type="checkbox"/>	
	10	Steering Cylinder	Oil Leak/Visual	<input checked="" type="checkbox"/>	
	11	Rear Axle	Function/Operation	<input checked="" type="checkbox"/>	
	12	Steering Chain	Lubricate,Tension/Visual	<input checked="" type="checkbox"/>	
Tire	13	Gear Case	Oil leak/Visual	<input checked="" type="checkbox"/>	
	14	Hub/Rim Bolts	Looseness/Tightening	<input checked="" type="checkbox"/>	
	15	Wheel Bearing	Noise/Operation	<input checked="" type="checkbox"/>	
	16	Front wheel	Wear,Damage/Visual	<input checked="" type="checkbox"/>	
	17	Rear wheel	Wear,Damage/Visual	<input checked="" type="checkbox"/>	
	18	Mast Shoe	Abnormal Play/Operation	<input checked="" type="checkbox"/>	
Mast Hydraulic	19	Lift Chain	Extension/Guage	<input checked="" type="checkbox"/>	
	20	Hose Pulley/Guard	Damage/Visual	<input checked="" type="checkbox"/>	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	<input checked="" type="checkbox"/>	
	22	Lift Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
	23	Tilt Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
	24	Attachment Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
Battery Charger	25	Hydraulic Oil	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
	26	Hose/Piping	Damage,Oil leak/Visual	<input checked="" type="checkbox"/>	
	27	Fork	Thickness/Measure	<input checked="" type="checkbox"/>	Measure mm, Limit mm, Standard mm.
	28	Backrest	Damage/Visual	<input checked="" type="checkbox"/>	
	29	Attachment Function	Function/Operation	<input checked="" type="checkbox"/>	
	30	Hydraulic Lever	Looseness/Operation	<input checked="" type="checkbox"/>	
Electric	31	Battery Water	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
	32	Terminal	Dirt/Visual	<input checked="" type="checkbox"/>	
	33	Battery Plug	Damage/Visual	<input checked="" type="checkbox"/>	
	34	Charger	Condition/Visual	<input checked="" type="checkbox"/>	
	35	Gas Spring	Damage/Operation	<input checked="" type="checkbox"/>	
	36	Seat/Seat belt	Damage/Visual,Operation	<input checked="" type="checkbox"/>	
Frame	37	Key Switch	Function/Operation	<input checked="" type="checkbox"/>	
	38	Horn/Buzzer	Sound/Operation	<input checked="" type="checkbox"/>	
	39	Head lamp	Function/Operation	<input checked="" type="checkbox"/>	
	40	Rear Combination Lamp	Function/Operation	<input checked="" type="checkbox"/>	
	41	Turn Signal Lamp	Function/Operation	<input checked="" type="checkbox"/>	
	42	Directional Switch	Function/Operation	<input checked="" type="checkbox"/>	
Frame	43	Micro Switch	Function/Operation	<input checked="" type="checkbox"/>	
	44	Contact	Burn/Function	<input checked="" type="checkbox"/>	
	45	Motor Brush	Thickness/Visual	<input checked="" type="checkbox"/>	Motor : Measure mm, Limit mm, Standard mm.
	46	EPS System	Function/Operation	<input checked="" type="checkbox"/>	
	47	Control System (Trv, Hyd)	Function/Operation	<input checked="" type="checkbox"/>	
	48	Others/Accessory	Function/Operation	<input checked="" type="checkbox"/>	
Frame	49	Head Guard	Damage/Visual	<input checked="" type="checkbox"/>	
	50	Chassis Frame	Damage/Visual	<input checked="" type="checkbox"/>	
	51	Lubricate	Condition/Visual	<input checked="" type="checkbox"/>	

Comments การตรวจเช็คสภาพรถ Forklift ☒ Good ☒ Need Repair ☐ A Adjust ☐ N/A

Customer Sign \_\_\_\_\_



## NICHYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Ruongtharoen, Ueb Klong Suwanmahum Rd., Banglae, Bangkok, Samutprakarn 10540  
 Service Suwanmahum : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (038) 116-838-40, (081) 498-0394 Fax. (038) 116-841  
 Service Ayuthaya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-798, (081) 399-1839 Fax. (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHYU  
ELECTRIC FORKLIFT

No. 2

Customer Nippon Express Branch \_\_\_\_\_ Date 21/09/23 Book no. 50010  
 Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel \_\_\_\_\_  
 Truck Model FB25PN-80C-3E470SE Serial Number 257D01476 Hour Meter 1125 Job Type 2/7

Component	No	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	✓	
	2	Brake Oil	Dirt,Level/Visual	✓	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	✓	
	4	Brake Shoe	Function/Operation	✓	
	5	Brake pedal	Stroke/Operation	✓	
	6	Parking Brake	Function/Operation	✓	
Steering	7	Steering Knob/wheel	Free play/Operation	✓	
	8	Steering Gear Case	Function/Operation	✓	
	9	Tie-rod/ Drag Link	Damage/Visual	✓	
	10	Steering Cylinder	Oil Leak/Visual	✓	
	11	Rear Axle	Function/Operation	✓	
	12	Steering Chain	Lubricate,Tension/Visual	✓	
e	13	Gear Case	Oil leak/Visual	✓	
	14	Hub/Rim Bolts	Looseness/Tightening	✓	
	15	Wheel Bearing	Noise/Operation	✓	
	16	Front wheel	Wear,Damage/Visual	✓	
	17	Rear wheel	Wear,Damage/Visual	✗	รอยขีดข่วน
	18	Mast Shoe	Abnormal Play/Operation	✓	
Mast Hydraulic	19	Lift Chain	Extension/Gauge	✓	
	20	Hose Pulley/Guard	Damage/Visual	✓	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	✓	
	22	Lift Cylinder	Oil leak/Visual	✓	
	23	Tilt Cylinder	Oil leak/Visual	✓	
	24	Attachment Cylinder	Oil leak/Visual	✓	
	25	Hydraulic Oil	Dirt,Level/Visual	✓	
	26	Hose/Piping	Damage,Oil leak/Visual	✓	
	27	Fork	Thickness/Measure	✓	Measure mm, Limit mm, Standard mm.
	28	Backrest	Damage/Visual	✓	
	29	Attachment Function	Function/Operation	✓	
	30	Hydraulic Lever	Looseness/Operation	✓	
Battery	31	Battery Water	Dirt,Level/Visual	✓	
	32	Terminal	Dirt/Visual	✓	
	33	Battery Plug	Damage/Visual	✓	
	34	Charger	Condition/Visual	✓	มีรอยขีดข่วน
	35	Gas Spring	Damage/Operation	✓	
	36	Seat/Seat belt	Damage/Visual,Operation	✓	
Electric	37	Key Switch	Function/Operation	✓	
	38	Horn/Buzzer	Sound/Operation	✓	
	39	Head lamp	Function/Operation	✓	
	40	Rear Combination Lamp	Function/Operation	✓	
	41	Turn Signal Lamp	Function/Operation	✓	
	42	Directional Switch	Function/Operation	✓	
	43	Micro Switch	Function/Operation	✓	
	44	Contact	Burn/Function	✓	
	45	Motor Brush	Thickness/Visual	✓	Motor : Measure mm, Limit mm, Standard mm.
	46	EPS System	Function/Operation	✓	
	47	Control System (Trv, Hyd)	Function/Operation	✓	
	48	Others/Accessory	Function/Operation	✓	
Frame	49	Head Guard	Damage/Visual	✓	
	50	Chassis Frame	Damage/Visual	✓	
	51	Lubricate	Condition/Visual	✓	

Comments ☒ Good ☒ Need Repair ☐ A Adjust ☐ - N/A

Customer Sign

## NICHYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Ruongtharoen, Ueb Klong Suwanmahum Rd., Banglae, Bangkok, Samutprakarn 10540  
 Service Suwanmahum : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (038) 116-838-40, (081) 498-0394 Fax. (038) 116-841  
 Service Ayuthaya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-798, (081) 399-1839 Fax. (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHYU  
ELECTRIC FORKLIFT

No. 1

Customer Nippon Express Branch \_\_\_\_\_ Date 21/09/23 Book no. 50009  
 Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel \_\_\_\_\_  
 Truck Model FB25PN-80C-3E470SE Serial Number 257D01476 Hour Meter 912 Job Type 2/7

Component	No	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	✓	
	2	Brake Oil	Dirt,Level/Visual	✓	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	✓	
	4	Brake Shoe	Function/Operation	✓	
	5	Brake pedal	Stroke/Operation	✓	
	6	Parking Brake	Function/Operation	✓	
Steering	7	Steering Knob/wheel	Free play/Operation	✓	
	8	Steering Gear Case	Function/Operation	✓	
	9	Tie-rod/ Drag Link	Damage/Visual	✓	
	10	Steering Cylinder	Oil Leak/Visual	✓	
	11	Rear Axle	Function/Operation	✓	
	12	Steering Chain	Lubricate,Tension/Visual	✓	
e	13	Gear Case	Oil leak/Visual	✓	
	14	Hub/Rim Bolts	Looseness/Tightening	✓	
	15	Wheel Bearing	Noise/Operation	✓	
	16	Front wheel	Wear,Damage/Visual	✓	
	17	Rear wheel	Wear,Damage/Visual	✗	รอยขีดข่วน
	18	Mast Shoe	Abnormal Play/Operation	✓	
Mast Hydraulic	19	Lift Chain	Extension/Gauge	✓	
	20	Hose Pulley/Guard	Damage/Visual	✓	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	✓	
	22	Lift Cylinder	Oil leak/Visual	✓	
	23	Tilt Cylinder	Oil leak/Visual	✓	
	24	Attachment Cylinder	Oil leak/Visual	✓	
	25	Hydraulic Oil	Dirt,Level/Visual	✓	
	26	Hose/Piping	Damage,Oil leak/Visual	✓	
	27	Fork	Thickness/Measure	✓	Measure mm, Limit mm, Standard mm.
	28	Backrest	Damage/Visual	✓	
	29	Attachment Function	Function/Operation	✓	
	30	Hydraulic Lever	Looseness/Operation	✓	
Battery	31	Battery Water	Dirt,Level/Visual	✓	
	32	Terminal	Dirt/Visual	✓	
	33	Battery Plug	Damage/Visual	✓	
	34	Charger	Condition/Visual	✓	มีรอยขีดข่วน
	35	Gas Spring	Damage/Operation	✓	
	36	Seat/Seat belt	Damage/Visual,Operation	✓	
Electric	37	Key Switch	Function/Operation	✓	
	38	Horn/Buzzer	Sound/Operation	✓	
	39	Head lamp	Function/Operation	✓	
	40	Rear Combination Lamp	Function/Operation	✓	
	41	Turn Signal Lamp	Function/Operation	✓	
	42	Directional Switch	Function/Operation	✓	
	43	Micro Switch	Function/Operation	✓	
	44	Contact	Burn/Function	✓	
	45	Motor Brush	Thickness/Visual	✓	Motor : Measure mm, Limit mm, Standard mm.
	46	EPS System	Function/Operation	✓	
	47	Control System (Trv, Hyd)	Function/Operation	✓	
	48	Others/Accessory	Function/Operation	✓	
Frame	49	Head Guard	Damage/Visual	✓	
	50	Chassis Frame	Damage/Visual	✓	
	51	Lubricate	Condition/Visual	✓	

Comments ☒ Good ☒ Need Repair ☐ A Adjust ☐ - N/A

Customer Sign



# NICHIIYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Rongcharoen, Ueb Klong Suwanmahum Rd., Bangla, Bangkok, Samutprakam 10540

Service Suwanmahum : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
Service Chonburi : Tel. (038) 116-838-40, (081) 498-0394 Fax. (038) 116-841  
Service Ayudhya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
Service Prachinburi : Tel. (037) 208-798, (081) 399-3839 Fax. (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHIIYU  
ELECTRIC FORKLIFT



Customer Nippon 8 and L Branch \_\_\_\_\_ Date 11-8-98 Book no. 55008  
Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel. \_\_\_\_\_  
Truck Model F825 PN-80C-3F4708F Serial Number 957001477 Hour Meter 1202 Job Type P/T

Component	Nº	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	<input checked="" type="checkbox"/>	
	2	Brake Oil	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	<input checked="" type="checkbox"/>	
	4	Brake Shoe	Function/Operation	<input checked="" type="checkbox"/>	
	5	Brake pedal	Stroke/Operation	<input checked="" type="checkbox"/>	
	6	Parking Brake	Function/Operation	<input checked="" type="checkbox"/>	
Steering	7	Steering Knob/wheel	Free play/Operation	<input checked="" type="checkbox"/>	
	8	Steering Gear Case	Function/Operation	<input checked="" type="checkbox"/>	
	9	Tie-rod/Drag Link	Damage/Visual	<input checked="" type="checkbox"/>	
	10	Steering Cylinder	Oil Leak/Visual	<input checked="" type="checkbox"/>	
	11	Rear Axle	Function/Operation	<input checked="" type="checkbox"/>	
	12	Steering Chain	Lubricate,Tension/Visual	<input checked="" type="checkbox"/>	
ve	13	Gear Case	Oil leak/Visual	<input checked="" type="checkbox"/>	
	14	Hub/Rim Bolts	Looseness/Tightening	<input checked="" type="checkbox"/>	
	15	Wheel Bearing	Noise/Operation	<input checked="" type="checkbox"/>	
	16	Front wheel	Wear,Damage/Visual	<input checked="" type="checkbox"/>	
	17	Rear wheel	Wear,Damage/Visual	<input checked="" type="checkbox"/>	<u>รอยขีดข่วน 18x7-8</u>
Mast Hydraulic	18	Mast Shoe	Abnormal Play/Operation	<input checked="" type="checkbox"/>	
	19	Lift Chain	Extension/Gauge	<input checked="" type="checkbox"/>	
	20	Hose Pulley/Guard	Damage/Visual	<input checked="" type="checkbox"/>	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	<input checked="" type="checkbox"/>	
	22	Lift Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
	23	Tilt Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
	24	Attachment Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
	25	Hydraulic Oil	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
	26	Hose/Piping	Damage,Oil leak/Visual	<input checked="" type="checkbox"/>	
	27	Fork	Thickness/Measure	<input checked="" type="checkbox"/>	Measure mm, Limit mm, Standard mm.
Battery	28	Backrest	Damage/Visual	<input checked="" type="checkbox"/>	
	29	Attachment Function	Function/Operation	<input checked="" type="checkbox"/>	
	30	Hydraulic Lever	Looseness/Operation	<input checked="" type="checkbox"/>	
	31	Battery Water	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
rger	32	Terminal	Dirt/Visual	<input checked="" type="checkbox"/>	
	33	Battery Plug	Damage/Visual	<input checked="" type="checkbox"/>	
	34	Charger	Condition/Visual	<input checked="" type="checkbox"/>	
	35	Gas Spring	Damage/Operation	<input checked="" type="checkbox"/>	
	36	Seat/Seat belt	Damage/Visual,Operation	<input checked="" type="checkbox"/>	
Electric	37	Key Switch	Function/Operation	<input checked="" type="checkbox"/>	
	38	Horn/Buzzer	Sound/Operation	<input checked="" type="checkbox"/>	
	39	Head lamp	Function/Operation	<input checked="" type="checkbox"/>	
	40	Rear Combination Lamp	Function/Operation	<input checked="" type="checkbox"/>	
	41	Turn Signal Lamp	Function/Operation	<input checked="" type="checkbox"/>	
	42	Directional Switch	Function/Operation	<input checked="" type="checkbox"/>	
	43	Micro Switch	Function/Operation	<input checked="" type="checkbox"/>	
	44	Contact	Burn/Function	<input checked="" type="checkbox"/>	
	45	Motor Brush	Thickness/Visual	<input checked="" type="checkbox"/>	Motor : Measure mm, Limit mm, Standard mm.
	46	EPS System	Function/Operation	<input checked="" type="checkbox"/>	
Frame	47	Control System (Trv, Hyd)	Function/Operation	<input checked="" type="checkbox"/>	
	48	Others/Accessory	Function/Operation	<input checked="" type="checkbox"/>	
	49	Head Guard	Damage/Visual	<input checked="" type="checkbox"/>	
	50	Chassis Frame	Damage/Visual	<input checked="" type="checkbox"/>	
	51	Lubricate	Condition/Visual	<input checked="" type="checkbox"/>	

Comments ☒ Good ☒ Repair ☒ A Adjust - N/A

Customer Sign

# NICHIIYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Rongcharoen, Ueb Klong Suwanmahum Rd., Bangla, Bangkok, Samutprakam 10540

Service Suwanmahum : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
Service Chonburi : Tel. (038) 116-838-40, (081) 498-0394 Fax. (038) 116-841  
Service Ayudhya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
Service Prachinburi : Tel. (037) 208-798, (081) 399-3839 Fax. (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHIIYU  
ELECTRIC FORKLIFT



Customer Nippon 8 and L Branch \_\_\_\_\_ Date 11-8-98 Book no. 55007  
Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel. \_\_\_\_\_  
Truck Model F825 PN-80C-3F4708F Serial Number 957001477 Hour Meter 964 Job Type P/T

Component	Nº	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	<input checked="" type="checkbox"/>	
	2	Brake Oil	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	<input checked="" type="checkbox"/>	
	4	Brake Shoe	Function/Operation	<input checked="" type="checkbox"/>	
	5	Brake pedal	Stroke/Operation	<input checked="" type="checkbox"/>	
	6	Parking Brake	Function/Operation	<input checked="" type="checkbox"/>	
Steering	7	Steering Knob/wheel	Free play/Operation	<input checked="" type="checkbox"/>	
	8	Steering Gear Case	Function/Operation	<input checked="" type="checkbox"/>	
	9	Tie-rod/Drag Link	Damage/Visual	<input checked="" type="checkbox"/>	
	10	Steering Cylinder	Oil Leak/Visual	<input checked="" type="checkbox"/>	
	11	Rear Axle	Function/Operation	<input checked="" type="checkbox"/>	
	12	Steering Chain	Lubricate,Tension/Visual	<input checked="" type="checkbox"/>	
ve	13	Gear Case	Oil leak/Visual	<input checked="" type="checkbox"/>	
	14	Hub/Rim Bolts	Looseness/Tightening	<input checked="" type="checkbox"/>	
	15	Wheel Bearing	Noise/Operation	<input checked="" type="checkbox"/>	
	16	Front wheel	Wear,Damage/Visual	<input checked="" type="checkbox"/>	
	17	Rear wheel	Wear,Damage/Visual	<input checked="" type="checkbox"/>	<u>รอยขีดข่วน 18x7-8</u>
Mast Hydraulic	18	Mast Shoe	Abnormal Play/Operation	<input checked="" type="checkbox"/>	
	19	Lift Chain	Extension/Gauge	<input checked="" type="checkbox"/>	
	20	Hose Pulley/Guard	Damage/Visual	<input checked="" type="checkbox"/>	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	<input checked="" type="checkbox"/>	
	22	Lift Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
	23	Tilt Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
	24	Attachment Cylinder	Oil leak/Visual	<input checked="" type="checkbox"/>	
	25	Hydraulic Oil	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
	26	Hose/Piping	Damage,Oil leak/Visual	<input checked="" type="checkbox"/>	
	27	Fork	Thickness/Measure	<input checked="" type="checkbox"/>	Measure mm, Limit mm, Standard mm.
Battery	28	Backrest	Damage/Visual	<input checked="" type="checkbox"/>	
	29	Attachment Function	Function/Operation	<input checked="" type="checkbox"/>	
	30	Hydraulic Lever	Looseness/Operation	<input checked="" type="checkbox"/>	
	31	Battery Water	Dirt,Level/Visual	<input checked="" type="checkbox"/>	
rger	32	Terminal	Dirt/Visual	<input checked="" type="checkbox"/>	
	33	Battery Plug	Damage/Visual	<input checked="" type="checkbox"/>	
	34	Charger	Condition/Visual	<input checked="" type="checkbox"/>	
	35	Gas Spring	Damage/Operation	<input checked="" type="checkbox"/>	
	36	Seat/Seat belt	Damage/Visual,Operation	<input checked="" type="checkbox"/>	
Electric	37	Key Switch	Function/Operation	<input checked="" type="checkbox"/>	
	38	Horn/Buzzer	Sound/Operation	<input checked="" type="checkbox"/>	
	39	Head lamp	Function/Operation	<input checked="" type="checkbox"/>	
	40	Rear Combination Lamp	Function/Operation	<input checked="" type="checkbox"/>	
	41	Turn Signal Lamp	Function/Operation	<input checked="" type="checkbox"/>	
	42	Directional Switch	Function/Operation	<input checked="" type="checkbox"/>	
	43	Micro Switch	Function/Operation	<input checked="" type="checkbox"/>	
	44	Contact	Burn/Function	<input checked="" type="checkbox"/>	
	45	Motor Brush	Thickness/Visual	<input checked="" type="checkbox"/>	Motor : Measure mm, Limit mm, Standard mm.
	46	EPS System	Function/Operation	<input checked="" type="checkbox"/>	
Frame	47	Control System (Trv, Hyd)	Function/Operation	<input checked="" type="checkbox"/>	
	48	Others/Accessory	Function/Operation	<input checked="" type="checkbox"/>	
	49	Head Guard	Damage/Visual	<input checked="" type="checkbox"/>	
	50	Chassis Frame	Damage/Visual	<input checked="" type="checkbox"/>	
	51	Lubricate	Condition/Visual	<input checked="" type="checkbox"/>	

Comments ☒ Good ☒ Repair ☒ A Adjust - N/A

Customer Sign



## NICHIIYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Roongcharoen, Ueb Klong Suvarnabhumi Rd., Bangpla, Bangkok, Samutprakarn 10540  
 Service Suvarnabhumi : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (038) 116-838-40, (081) 496-0394 Fax. (038) 116-841  
 Service Ayutthaya : Tel. (035) 227-965-6, (089) 444-6091 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-796, (081) 399-1839 Fax. (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHIIYU  
ELECTRIC FORKLIFT

NO. 1

Customer NIPPON S and L Branch \_\_\_\_\_ Date 14-9-28 Book no. 54364  
 Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel \_\_\_\_\_  
 Truck Model FD25PN-80C-3F470SF Serial Number 257D01476 Hour Meter 1065 Job Type R/T W/C

Component	Nº	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	✓	
	2	Brake Oil	Dirt,Level/Visual	✓	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	✓	
	4	Brake Shoe	Function/Operation	✓	
	5	Brake pedal	Stroke/Operation	✓	
	6	Parking Brake	Function/Operation	✓	
Steering	7	Steering Knob/wheel	Free play/Operation	✓	
	8	Steering Gear Case	Function/Operation	✓	
	9	Tie-rod/Drag Link	Damage/Visual	✓	
	10	Steering Cylinder	Oil Leak/Visual	✓	
	11	Rear Axle	Function/Operation	✓	
	12	Steering Chain	Lubricate,Tension/Visual	✓	
Wheel	13	Gear Case	Oil leak/Visual	✓	
	14	Hub/Rim Bolts	Looseness/Tightening	✓	
	15	Wheel Bearing	Noise/Operation	✓	
	16	Front wheel	Wear,Damage/Visual	✓	
	17	Rear wheel	Wear,Damage/Visual	✓	
Mast Hydraulic	18	Mast Shoe	Abnormal Play/Operation	✓	
	19	Lift Chain	Extension/Gauge	✓	
	20	Hose Pulley/Guard	Damage/Visual	✓	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	✓	
	22	Lift Cylinder	Oil leak/Visual	✓	
	23	Tilt Cylinder	Oil leak/Visual	✓	
	24	Attachment Cylinder	Oil leak/Visual	✓	
	25	Hydraulic Oil	Dirt,Level/Visual	✓	
	26	Hose/Piping	Damage,Oil leak/Visual	✓	
	27	Fork	Thickness/Measure	Measure mm, Limit mm, Standard mm.	
	28	Backrest	Damage/Visual	✓	
Battery	29	Attachment Function	Function/Operation	✓	
	30	Hydraulic Lever	Looseness/Operation	✓	
	31	Battery Water	Dirt,Level/Visual	✓	
	32	Terminal	Dirt/Visual	✓	
	33	Battery Plug	Damage/Visual	✓	
	34	Charger	Condition/Visual	✓	
Electric	35	Gas Spring	Damage/Operation	✓	
	36	Seat/Seat belt	Damage/Visual,Operation	✓	
	37	Key Switch	Function/Operation	✓	
	38	Horn/Buzzer	Sound/Operation	✓	
	39	Head lamp	Function/Operation	✓	
	40	Rear Combination Lamp	Function/Operation	✓	
	41	Turn Signal Lamp	Function/Operation	✓	
	42	Directional Switch	Function/Operation	✓	
	43	Micro Switch	Function/Operation	✓	
	44	Contacto	Burn/Function	✓	
	45	Motor Brush	Thickness/Visual	Motor : Measure mm, Limit mm, Standard mm.	
Frame	46	EPS System	Function/Operation	✓	
	47	Control System (Trv, Hyd)	Function/Operation	✓	
	48	Others/Accessory	Function/Operation	✓	
	49	Head Guard	Damage/Visual	✓	
	50	Chassis Frame	Damage/Visual	✓	
	51	Lubricate	Condition/Visual	✓	

Comments ☒ Good ☒ Need Repair ☒ A Adjust ☒ - N/A  
 1. ตรวจสอบเครื่องยนต์ 18x7-8 ทำงาน 2 ชั่วโมง 1 ชั่วโมง 1 ชั่วโมง 1 ชั่วโมง 1 ชั่วโมง

Customer Sign

## NICHIIYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Roongcharoen, Ueb Klong Suvarnabhumi Rd., Bangpla, Bangkok, Samutprakarn 10540  
 Service Suvarnabhumi : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (038) 116-838-40, (081) 496-0394 Fax. (038) 116-841  
 Service Ayutthaya : Tel. (035) 227-965-6, (089) 444-6091 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-796, (081) 399-1839 Fax. (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHIIYU  
ELECTRIC FORKLIFT

NO. 2

Customer NIPPON S and L Branch \_\_\_\_\_ Date 14-9-28 Book no. 54365  
 Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel \_\_\_\_\_  
 Truck Model FD25PN-80C-3F470SF Serial Number 257D01477 Hour Meter 1332 Job Type R/T W/C

Component	Nº	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	✓	
	2	Brake Oil	Dirt,Level/Visual	✓	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	✓	
	4	Brake Shoe	Function/Operation	✓	
	5	Brake pedal	Stroke/Operation	✓	
	6	Parking Brake	Function/Operation	✓	
Steering	7	Steering Knob/wheel	Free play/Operation	✓	
	8	Steering Gear Case	Function/Operation	✓	
	9	Tie-rod/Drag Link	Damage/Visual	✓	
	10	Steering Cylinder	Oil Leak/Visual	✓	
	11	Rear Axle	Function/Operation	✓	
	12	Steering Chain	Lubricate,Tension/Visual	✓	
Wheel	13	Gear Case	Oil leak/Visual	✓	
	14	Hub/Rim Bolts	Looseness/Tightening	✓	
	15	Wheel Bearing	Noise/Operation	✓	
	16	Front wheel	Wear,Damage/Visual	✓	
	17	Rear wheel	Wear,Damage/Visual	✓	
Mast Hydraulic	18	Mast Shoe	Abnormal Play/Operation	✓	
	19	Lift Chain	Extension/Gauge	✓	
	20	Hose Pulley/Guard	Damage/Visual	✓	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	✓	
	22	Lift Cylinder	Oil leak/Visual	✓	
	23	Tilt Cylinder	Oil leak/Visual	✓	
	24	Attachment Cylinder	Oil leak/Visual	✓	
	25	Hydraulic Oil	Dirt,Level/Visual	✓	
	26	Hose/Piping	Damage,Oil leak/Visual	✓	
	27	Fork	Thickness/Measure	Measure mm, Limit mm, Standard mm.	
	28	Backrest	Damage/Visual	✓	
Battery	29	Attachment Function	Function/Operation	✓	
	30	Hydraulic Lever	Looseness/Operation	✓	
	31	Battery Water	Dirt,Level/Visual	✓	
	32	Terminal	Dirt/Visual	✓	
	33	Battery Plug	Damage/Visual	✓	
	34	Charger	Condition/Visual	✓	
Electric	35	Gas Spring	Damage/Operation	✓	
	36	Seat/Seat belt	Damage/Visual,Operation	✓	
	37	Key Switch	Function/Operation	✓	
	38	Horn/Buzzer	Sound/Operation	✓	
	39	Head lamp	Function/Operation	✓	
	40	Rear Combination Lamp	Function/Operation	✓	
	41	Turn Signal Lamp	Function/Operation	✓	
	42	Directional Switch	Function/Operation	✓	
	43	Micro Switch	Function/Operation	✓	
	44	Contacto	Burn/Function	✓	
	45	Motor Brush	Thickness/Visual	Motor : Measure mm, Limit mm, Standard mm.	
Frame	46	EPS System	Function/Operation	✓	
	47	Control System (Trv, Hyd)	Function/Operation	✓	
	48	Others/Accessory	Function/Operation	✓	
	49	Head Guard	Damage/Visual	✓	
	50	Chassis Frame	Damage/Visual	✓	
	51	Lubricate	Condition/Visual	✓	

Comments ☒ Good ☒ Need Repair ☒ A Adjust ☒ - N/A  
 1. ตรวจสอบเครื่องยนต์ 18x7-8 ทำงาน 2 ชั่วโมง 1 ชั่วโมง 1 ชั่วโมง 1 ชั่วโมง 1 ชั่วโมง

Customer Sign



# NICHIYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Ruongchareon, Uthong Suvarnabhumi Rd., Bangplee, Bangplee, Samutprakarn 10540  
 Service Suvarnabhumi : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (038) 116-838-40, (081) 498-0394 Fax. (038) 116-841  
 Service Ayuthaya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-798, (081) 399-1839 Fax (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHIYU  
ELECTRIC FORKLIFT



Customer 888 Branch \_\_\_\_\_ Date 19-10-23 Book no. 50914  
 Contact Person 888 Section 888 Tel. \_\_\_\_\_  
 Truck Model 888 Serial Number 888 Hour Meter 1180 Job Type NT

Component	Nº	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	✓	
	2	Brake Oil	Dirt,Level/Visual	✓	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	✓	
	4	Brake Shoe	Function/Operation	✓	
	5	Brake pedal	Stroke/Operation	✓	
	6	Parking Brake	Function/Operation	✓	
Steering	7	Steering Knob/wheel	Free play/Operation	✓	
	8	Steering Gear Case	Function/Operation	✓	
	9	Tie-rod/Drag Link	Damage/Visual	✓	
	10	Steering Cylinder	Oil Leak/Visual	✓	
	11	Rear Axle	Function/Operation	✓	
	12	Steering Chain	Lubricate,Tension/Visual	✓	
D 2	13	Gear Case	Oil leak/Visual	✓	
	14	Hub/Rim Bolts	Looseness/Tightening	✓	
	15	Wheel Bearing	Noise/Operation	✓	
	16	Front wheel	Wear,Damage/Visual	✓	
	17	Rear wheel	Wear,Damage/Visual	✓	
Mast Hydraulic	18	Mast Shoe	Abnormal Play/Operation	✓	
	19	Lift Chain	Extension/Gauge	✓	
	20	Hose Pulley/Guard	Damage/Visual	✓	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	✓	
	22	Lift Cylinder	Oil leak/Visual	✓	
	23	Tilt Cylinder	Oil leak/Visual	✓	
	24	Attachment Cylinder	Oil leak/Visual	✓	
	25	Hydraulic Oil	Dirt,Level/Visual	✓	
	26	Hose/Piping	Damage,Oil leak/Visual	✓	
	27	Fork	Thickness/Measure	Measure <u>40</u> mm, Limit <u>37</u> mm, Standard <u>40</u> mm.	
	28	Backrest	Damage/Visual	✓	
	29	Attachment Function	Function/Operation	✓	
Battery Ch (er	30	Hydraulic Lever	Looseness/Operation	✓	
	31	Battery Water	Dirt,Level/Visual	✓	
	32	Terminal	Dirt/Visual	✓	
	33	Battery Plug	Damage/Visual	✓	
	34	Charger	Condition/Visual	✓	
	35	Gas Spring	Damage/Operation	✓	
	36	Seat/Seat belt	Damage/Visual,Operation	✓	
Electric	37	Key Switch	Function/Operation	✓	
	38	Horn/Buzzer	Sound/Operation	✓	
	39	Head lamp	Function/Operation	✓	
	40	Rear Combination Lamp	Function/Operation	✓	
	41	Turn Signal Lamp	Function/Operation	✓	
	42	Directional Switch	Function/Operation	✓	
	43	Micro Switch	Function/Operation	✓	
	44	Contact	Burn/Function	✓	
	45	Motor Brush	Thickness/Visual	Motor : Measure mm, Limit mm, Standard mm.	
	46	EPS System	Function/Operation	✓	
	47	Control System (Trv, Hyd)	Function/Operation	✓	
	48	Others/Accessory	Function/Operation	✓	
Frame	49	Head Guard	Damage/Visual	✓	
	50	Chassis Frame	Damage/Visual	✓	
	51	Lubricate	Condition/Visual	✓	

Comments ☒ Good ☒ Repair ☒ Adjust ☒ N/A

Plug Battery. PM 888 888.

Customer Sign

# NICHIYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Ruongchareon, Uthong Suvarnabhumi Rd., Bangplee, Bangplee, Samutprakarn 10540  
 Service Suvarnabhumi : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (038) 116-838-40, (081) 498-0394 Fax. (038) 116-841  
 Service Ayuthaya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-798, (081) 399-1839 Fax (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHIYU  
ELECTRIC FORKLIFT



Customer 888 Branch \_\_\_\_\_ Date 19-10-23 Book no. 50915  
 Contact Person 888 Section 888 Tel. \_\_\_\_\_  
 Truck Model 888 Serial Number 888 Hour Meter 1180 Job Type NT

Component	Nº	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	✓	
	2	Brake Oil	Dirt,Level/Visual	✓	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	✓	
	4	Brake Shoe	Function/Operation	✓	
	5	Brake pedal	Stroke/Operation	✓	
	6	Parking Brake	Function/Operation	✓	
Steering	7	Steering Knob/wheel	Free play/Operation	✓	
	8	Steering Gear Case	Function/Operation	✓	
	9	Tie-rod/Drag Link	Damage/Visual	✓	
	10	Steering Cylinder	Oil Leak/Visual	✓	
	11	Rear Axle	Function/Operation	✓	
	12	Steering Chain	Lubricate,Tension/Visual	✓	
D 2	13	Gear Case	Oil leak/Visual	✓	
	14	Hub/Rim Bolts	Looseness/Tightening	✓	
	15	Wheel Bearing	Noise/Operation	✓	
	16	Front wheel	Wear,Damage/Visual	✓	
	17	Rear wheel	Wear,Damage/Visual	✓	
Mast Hydraulic	18	Mast Shoe	Abnormal Play/Operation	✓	
	19	Lift Chain	Extension/Gauge	✓	
	20	Hose Pulley/Guard	Damage/Visual	✓	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	✓	
	22	Lift Cylinder	Oil leak/Visual	✓	
	23	Tilt Cylinder	Oil leak/Visual	✓	
	24	Attachment Cylinder	Oil leak/Visual	✓	
	25	Hydraulic Oil	Dirt,Level/Visual	✓	
	26	Hose/Piping	Damage,Oil leak/Visual	✓	
	27	Fork	Thickness/Measure	Measure <u>40</u> mm, Limit <u>37</u> mm, Standard <u>40</u> mm.	
	28	Backrest	Damage/Visual	✓	
	29	Attachment Function	Function/Operation	✓	
Battery Ch (er	30	Hydraulic Lever	Looseness/Operation	✓	
	31	Battery Water	Dirt,Level/Visual	✓	
	32	Terminal	Dirt/Visual	✓	
	33	Battery Plug	Damage/Visual	✓	
	34	Charger	Condition/Visual	✓	
	35	Gas Spring	Damage/Operation	✓	
	36	Seat/Seat belt	Damage/Visual,Operation	✓	
Electric	37	Key Switch	Function/Operation	✓	
	38	Horn/Buzzer	Sound/Operation	✓	
	39	Head lamp	Function/Operation	✓	
	40	Rear Combination Lamp	Function/Operation	✓	
	41	Turn Signal Lamp	Function/Operation	✓	
	42	Directional Switch	Function/Operation	✓	
	43	Micro Switch	Function/Operation	✓	
	44	Contact	Burn/Function	✓	
	45	Motor Brush	Thickness/Visual	Motor : Measure mm, Limit mm, Standard mm.	
	46	EPS System	Function/Operation	✓	
	47	Control System (Trv, Hyd)	Function/Operation	✓	
	48	Others/Accessory	Function/Operation	✓	
Frame	49	Head Guard	Damage/Visual	✓	
	50	Chassis Frame	Damage/Visual	✓	
	51	Lubricate	Condition/Visual	✓	

Comments ☒ Good ☒ Repair ☒ Adjust ☒ N/A

Customer Sign



## NICHYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Roongcharoen, Ueb Klong Suvarnabhumi Rd., Bangpla, Bangplae, Samutprakarn 10540.

Service Suvarnabhumi : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (036) 116-838-40, (081) 498-0394 Fax. (036) 116-841  
 Service Ayutthaya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-798, (081) 399-1839 Fax. (037) 208-799

## INSPECTION SHEET (FBR / FBRF)

NICHYU  
ELECTRIC FORKLIFT

No. 9

Customer S and L Branch \_\_\_\_\_ Date 24-11-23 Book no. 49422  
 Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel \_\_\_\_\_  
 Truck Model F825PN-80C-3F4705F Serial Number 257D01477 Hour Meter 162 Job Type R/T

Component	No	Item	Check point/Method	Result	Comments			
Brake	1	Brake Force	Function/Operation	✓				
	2	Brake Cam	Wear/Visual	✓				
	3	Brake Unit, Wire, Pedal	Function/Operation	✓				
	4	Brake Pad	Wear/Visual	✓				
	5	Brake Oil	Dirt, Level/Visual	✓				
Steering	6	Steering Knob/wheel	Free play/Operation	✓				
	7	Steering Gear Case	Oil leak/Visual	✓				
	8	Steering Linkage	Damage/Operation, Visual	✓				
	9	Steering Chain	Lubricate, Tension/Visual	✓				
Drive	10	Gear Case	Oil leak/Visual	✓				
	11	Hub/Rim Bolts	Looseness/Tightening	✓				
	12	Wheel Bearing	Noise/Operation	✓				
	13	Load wheel(Front)	Wear/Measure	✓	Measure	mm, Limit	mm, Standard	mm.
	14	Drive wheel(Rear)	Wear/Measure	✓	Measure	mm, Limit	mm, Standard	mm.
	15	Caster wheel(Rear)	Wear/Measure	✓	Measure	mm, Limit	mm, Standard	mm.
Mast Hydraulic	16	Control Linkage	Wear, Damage/Operation	✓				
	17	Mast Shoe	Abnormal Play/Operation	✓				
	18	Lift Chain	Extension/Guage	✓				
	19	Mast Guide Shaft	Damage/Visual	✓				
	20	Hose Pulley/Guard	Damage/Visual	✓				
	21	Mast Roller/Side Roller	Abnormal Play/Operation	✓				
	22	Carriage Roller	Abnormal Play/Operation	✓				
	23	Lift Cylinder	Oil leak/Visual	✓				
	24	Tilt Cylinder	Oil leak/Visual	✓				
	25	Reach Cylinder	Oil leak/Visual	✓				
	26	Attachment Cylinder	Oil leak/Visual	✓				
	27	Hydraulic Oil	Dirt, Level/Visual	✓				
	28	Hose/Piping	Damage, Leak/Visual	✓				
	29	Fork	Thickness/Measure	✓	Measure	mm, Limit	mm, Standard	mm.
Battery Charger	30	Backrest	Damage/Visual	✓				
	31	Attachment Function	Function/Operation	✓				
	32	Hydraulic Lever	Looseness/Operation	✓				
	33	Battery Water	Dirt, Level/Visual	✓				
Electric	34	Terminal	Dirt/Visual	✓				
	35	Battery Plug	Damage/Visual	✓				
	36	Charger	Condition/Visual	✓				
	37	Key Switch	Function/Operation	✓				
	38	Horn/Buzzer	Sound/Operation	✓				
	39	Head Lamp	Function/Operation	✓				
	40	Micro Switch	Function/Operation	✓				
	41	Contact	Burn/Operation	✓				
Frame	42	Motor Brush	Thickness/Measure	✓	Motor : Measure	mm, Limit	mm, Standard	mm.
	43	EPS System	Function/Operation	✓				
	44	Control System(Trv, Hyd)	Function/Operation	✓				
	45	Others/Accessory	Function/Operation	✓				
Frame	46	Head Guard	Damage/Visual	✓				
	47	Chassis Frame	Damage/Visual	✓				
	48	Lubricate	Condition/Visual	✓				

Comments ☒ Good ☒ Need Repair ☐ A Adjust ☐ - N/A

หมายเหตุ : 1. ไม่พบน้ำมันไฮดรอลิก 2. ไม่พบน้ำมันเบรก 3. ไม่พบน้ำมันหล่อลื่น

Customer Sign

## NICHYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Roongcharoen, Ueb Klong Suvarnabhumi Rd., Bangpla, Bangplae, Samutprakarn 10540.

Service Suvarnabhumi : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (036) 116-838-40, (081) 498-0394 Fax. (036) 116-841  
 Service Ayutthaya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-798, (081) 399-1839 Fax. (037) 208-799

## INSPECTION SHEET (FBR / FBRF)

NICHYU  
ELECTRIC FORKLIFT

No. 1

Customer S and L Branch \_\_\_\_\_ Date 24-11-23 Book no. 49421  
 Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel \_\_\_\_\_  
 Truck Model F825PN-80C-3F4705F Serial Number 257D01477 Hour Meter 1092 Job Type R/T

Component	No	Item	Check point/Method	Result	Comments			
Brake	1	Brake Force	Function/Operation	✓				
	2	Brake Cam	Wear/Visual	✓				
	3	Brake Unit, Wire, Pedal	Function/Operation	✓				
	4	Brake Pad	Wear/Visual	✓				
	5	Brake Oil	Dirt, Level/Visual	✓				
Steering	6	Steering Knob/wheel	Free play/Operation	✓				
	7	Steering Gear Case	Oil leak/Visual	✓				
	8	Steering Linkage	Damage/Operation, Visual	✓				
	9	Steering Chain	Lubricate, Tension/Visual	✓				
Drive	10	Gear Case	Oil leak/Visual	✓				
	11	Hub/Rim Bolts	Looseness/Tightening	✓				
	12	Wheel Bearing	Noise/Operation	✓				
	13	Load wheel(Front)	Wear/Measure	✓	Measure	mm, Limit	mm, Standard	mm.
	14	Drive wheel(Rear)	Wear/Measure	✓	Measure	mm, Limit	mm, Standard	mm.
	15	Caster wheel(Rear)	Wear/Measure	✓	Measure	mm, Limit	mm, Standard	mm.
Mast Hydraulic	16	Control Linkage	Wear, Damage/Operation	✓				
	17	Mast Shoe	Abnormal Play/Operation	✓				
	18	Lift Chain	Extension/Guage	✓				
	19	Mast Guide Shaft	Damage/Visual	✓				
	20	Hose Pulley/Guard	Damage/Visual	✓				
	21	Mast Roller/Side Roller	Abnormal Play/Operation	✓				
	22	Carriage Roller	Abnormal Play/Operation	✓				
	23	Lift Cylinder	Oil leak/Visual	✓				
	24	Tilt Cylinder	Oil leak/Visual	✓				
	25	Reach Cylinder	Oil leak/Visual	✓				
	26	Attachment Cylinder	Oil leak/Visual	✓				
	27	Hydraulic Oil	Dirt, Level/Visual	✓				
	28	Hose/Piping	Damage, Leak/Visual	✓				
	29	Fork	Thickness/Measure	✓	Measure	mm, Limit	mm, Standard	mm.
Battery Charger	30	Backrest	Damage/Visual	✓				
	31	Attachment Function	Function/Operation	✓				
	32	Hydraulic Lever	Looseness/Operation	✓				
	33	Battery Water	Dirt, Level/Visual	✓				
Electric	34	Terminal	Dirt/Visual	✓				
	35	Battery Plug	Damage/Visual	✓				
	36	Charger	Condition/Visual	✓				
	37	Key Switch	Function/Operation	✓				
	38	Horn/Buzzer	Sound/Operation	✓				
	39	Head Lamp	Function/Operation	✓				
	40	Micro Switch	Function/Operation	✓				
	41	Contact	Burn/Operation	✓				
Frame	42	Motor Brush	Thickness/Measure	✓	Motor : Measure	mm, Limit	mm, Standard	mm.
	43	EPS System	Function/Operation	✓				
	44	Control System(Trv, Hyd)	Function/Operation	✓				
	45	Others/Accessory	Function/Operation	✓				
Frame	46	Head Guard	Damage/Visual	✓				
	47	Chassis Frame	Damage/Visual	✓				
	48	Lubricate	Condition/Visual	✓				

Comments ☒ Good ☒ Need Repair ☐ A Adjust ☐ - N/A

Customer Sign



## NICHYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Roongchareon, Ueb Klong Suvarnabhumi Rd., Bangpa, Bangphee, Samutprakam 10540  
 Service Suvarnabhumi : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (038) 116-838-40, (081) 498-0394 Fax. (038) 116-841  
 Service Ayuthaya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-758, (081) 399-1839 Fax. (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHYU  
ELECTRIC FORKLIFT

Customer S and L Branch \_\_\_\_\_ Date 26-12-23 Book no. 56683  
 Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel \_\_\_\_\_  
 Truck Model F825PN-80C-3F4705F Serial Number Q57D01476 Hour Meter 1343 Job Type R/T

Component	Nº	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	✓	
	2	Brake Oil	Dirt,Level/Visual	✓	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	✓	
	4	Brake Shoe	Function/Operation	✓	
	5	Brake pedal	Stroke/Operation	✓	
	6	Parking Brake	Function/Operation	✓	
Steering	7	Steering Knob/wheel	Free play/Operation	✓	
	8	Steering Gear Case	Function/Operation	✓	
	9	Tie-rod/Drag Link	Damage/Visual	✓	
	10	Steering Cylinder	Oil Leak/Visual	✓	
	11	Rear Axle	Function/Operation	✓	
	12	Steering Chain	Lubricate,Tension/Visual	✓	
D	13	Gear Case	Oil leak/Visual	✓	
	14	Hub/Rim Bolts	Looseness/Tightening	✓	
	15	Wheel Bearing	Noise/Operation	✓	
	16	Front wheel	Wear,Damage/Visual	✓	
	17	Rear wheel	Wear,Damage/Visual	✓	
	18	Mast Shoe	Abnormal Play/Operation	✓	
Mast Hydraulic	19	Lift Chain	Extension/Guage	✓	
	20	Hose Pulley/Guard	Damage/Visual	✓	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	✓	
	22	Lift Cylinder	Oil leak/Visual	✓	
	23	Tilt Cylinder	Oil leak/Visual	✓	
	24	Attachment Cylinder	Oil leak/Visual	✓	
	25	Hydraulic Oil	Dirt,Level/Visual	✓	
	26	Hose/Piping	Damage,Oil leak/Visual	✓	
	27	Fork	Thickness/Measure	Measure mm, Limit mm, Standard mm.	
	28	Backrest	Damage/Visual	✓	
	29	Attachment Function	Function/Operation	✓	
	30	Hydraulic Lever	Looseness/Operation	✓	
Battery Charger	31	Battery Water	Dirt,Level/Visual	✓	
	32	Terminal	Dirt/Visual	✓	
	33	Battery Plug	Damage/Visual	✓	
	34	Charger	Condition/Visual	✓	
	35	Gas Spring	Damage/Operation	✓	
	36	Seat/Seat belt	Damage/Visual,Operation	✓	
Electric	37	Key Switch	Function/Operation	✓	
	38	Horn/Buzzer	Sound/Operation	✓	
	39	Head lamp	Function/Operation	✓	
	40	Rear Combination Lamp	Function/Operation	✓	
	41	Turn Signal Lamp	Function/Operation	✓	
	42	Directional Switch	Function/Operation	✓	
	43	Micro Switch	Function/Operation	✓	
	44	Contactor	Burn/Function	✓	
	45	Motor Brush	Thickness/Visual	Motor : Measure mm, Limit mm, Standard mm.	
	46	EPS System	Function/Operation	✓	
	47	Control System (Trv, Hyd)	Function/Operation	✓	
	48	Others/Accessory	Function/Operation	✓	
Frame	49	Head Guard	Damage/Visual	✓	
	50	Chassis Frame	Damage/Visual	✓	
	51	Lubricate	Condition/Visual	✓	

Comments ☒ Good ☒ NEED Repair ☐ A Adjust ☐ - N/A

Customer Sign

## NICHYU ASIA (THAILAND) CO.,LTD

HEAD OFFICE : 888/9-10 Moo 9, Soi Roongchareon, Ueb Klong Suvarnabhumi Rd., Bangpa, Bangphee, Samutprakam 10540  
 Service Suvarnabhumi : Tel. (02) 181-6723-27 Fax. (02) 181-6728  
 Service Chonburi : Tel. (038) 116-838-40, (081) 498-0394 Fax. (038) 116-841  
 Service Ayuthaya : Tel. (035) 227-965-6, (089) 444-6691 Fax. (035) 227-244  
 Service Prachinburi : Tel. (037) 208-758, (081) 399-1839 Fax. (037) 208-799

## INSPECTION SHEET (FB / FBT)

NICHYU  
ELECTRIC FORKLIFT

Customer S and L Branch \_\_\_\_\_ Date 26-12-23 Book no. 56682  
 Contact Person \_\_\_\_\_ Section \_\_\_\_\_ Tel \_\_\_\_\_  
 Truck Model F825PN-80C-3F4705F Serial Number Q57D01477 Hour Meter 1678 Job Type R/T

Component	Nº	Item	Check point/Method	Result	Comments
Brake	1	Brake Force	Function/Operation	✓	
	2	Brake Oil	Dirt,Level/Visual	✓	
	3	Brake Piping/Cylinder	Damage,Oil leak/Visual	✓	
	4	Brake Shoe	Function/Operation	✓	
	5	Brake pedal	Stroke/Operation	✓	
	6	Parking Brake	Function/Operation	✓	
Steering	7	Steering Knob/wheel	Free play/Operation	✓	
	8	Steering Gear Case	Function/Operation	✓	
	9	Tie-rod/Drag Link	Damage/Visual	✓	
	10	Steering Cylinder	Oil Leak/Visual	✓	
	11	Rear Axle	Function/Operation	✓	
	12	Steering Chain	Lubricate,Tension/Visual	✓	
D	13	Gear Case	Oil leak/Visual	✓	
	14	Hub/Rim Bolts	Looseness/Tightening	✓	
	15	Wheel Bearing	Noise/Operation	✓	
	16	Front wheel	Wear,Damage/Visual	✓	
	17	Rear wheel	Wear,Damage/Visual	✓	
	18	Mast Shoe	Abnormal Play/Operation	✓	
Mast Hydraulic	19	Lift Chain	Extension/Guage	✓	
	20	Hose Pulley/Guard	Damage/Visual	✓	
	21	Mast Roller/Side Roller	Abnormal Play/Operation	✓	
	22	Lift Cylinder	Oil leak/Visual	✓	
	23	Tilt Cylinder	Oil leak/Visual	✓	
	24	Attachment Cylinder	Oil leak/Visual	✓	
	25	Hydraulic Oil	Dirt,Level/Visual	✓	
	26	Hose/Piping	Damage,Oil leak/Visual	✓	
	27	Fork	Thickness/Measure	Measure mm, Limit mm, Standard mm.	
	28	Backrest	Damage/Visual	✓	
	29	Attachment Function	Function/Operation	✓	
	30	Hydraulic Lever	Looseness/Operation	✓	
Battery Charger	31	Battery Water	Dirt,Level/Visual	✓	
	32	Terminal	Dirt/Visual	✓	
	33	Battery Plug	Damage/Visual	✓	
	34	Charger	Condition/Visual	✓	
	35	Gas Spring	Damage/Operation	✓	
	36	Seat/Seat belt	Damage/Visual,Operation	✓	
Electric	37	Key Switch	Function/Operation	✓	
	38	Horn/Buzzer	Sound/Operation	✓	
	39	Head lamp	Function/Operation	✓	
	40	Rear Combination Lamp	Function/Operation	✓	
	41	Turn Signal Lamp	Function/Operation	✓	
	42	Directional Switch	Function/Operation	✓	
	43	Micro Switch	Function/Operation	✓	
	44	Contactor	Burn/Function	✓	
	45	Motor Brush	Thickness/Visual	Motor : Measure mm, Limit mm, Standard mm.	
	46	EPS System	Function/Operation	✓	
	47	Control System (Trv, Hyd)	Function/Operation	✓	
	48	Others/Accessory	Function/Operation	✓	
Frame	49	Head Guard	Damage/Visual	✓	
	50	Chassis Frame	Damage/Visual	✓	
	51	Lubricate	Condition/Visual	✓	

Comments ☒ Good ☒ NEED Repair ☐ A Adjust ☐ - N/A

Customer Sign



EX-KCRANES SERVICE CO.,LTD.

## SERVICE REPORT

### CUSTOMER

S and L Specialty Polymers Co., Ltd

### LOCATION

5 Phangmuang Chapoh 3-1 Road, Huaypong, Muang Rayong,  
Rayong 21150

### INSPECTION DATE

14-15 December 2023

เลขที่ 097

เลขที่ 4804



Customer name Sand L. Specialty Polymers Co., Ltd Date 14/12/2023



เลขที่ 097

เลขที่ 4806

Customer name Sand L specialty polymers co., Ltd Date 14/12/2023  
Customer address \_\_\_\_\_ Job number EX230218



เลขที่ 097

เลขที่ 4811

Customer name Sand L. specialty polymers co., Ltd

Date 15/12/2023  
15-09-2010

3  
23



NEED ATTENTION REPORT



INSPECTION SHEET

เลขที่ 097

เลขที่ 4819

Customer name Sand L. Specialty Polymers Co, Ltd Date 10/12/2023  
Customer address \_\_\_\_\_ Job number EX 230218

เลขที่ 097

เลขที่ 4818

Customer name S and L Specialty Polymers Co., Ltd Date 15/12/2023  
Job number Ex 020910

เลขที่ 097

เลขที่ 4817

Customer name S and L Specialty Polymers Co., Ltd Date 15/12/2023  
Job number Ex 020910

เลขที่ 097

เลขที่ 4816

Customer name Sand L Specialty Polymers Co., Ltd Date 14/12/2023  
Job number EX 230218

เลขที่ 097

เลขที่ 4815

Customer name Sand L Specialty Polymers Co., Ltd Date 14/12/2023  
Customer address \_\_\_\_\_ Job number EX 230218

เลขที่ 097

เลขที่ 4814

Customer name Sand L Specialty Polymers Co., Ltd Date 14/12/2023  
Customer address \_\_\_\_\_ Job number EX 020910

เลขที่ 097

เลขที่ 4813

Customer name Sand L Specialty Polymers Co., Ltd Date 14/12/2023  
Customer address \_\_\_\_\_ Job number EX 230918

เลขที่ 097

เลขที่ 4812

Customer name Sand L Specialty Polymers Co., Ltd. Date 15/12/2023

3

เลขที่ 097

เลขที่ 4810

Customer name Sand L Specialty Polymers Co., Ltd. Date 15/12/2023  
Customer address  Job number BA220218



เลขที่ 097

เลขที่ 4809

Customer name Sand L Specialty Polymers Co., Ltd Date 15/12/2023

เลขที่ 097

เลขที่ 4808

Customer name Sand L Specialty Polymers Co., Ltd. Date 15/12/2023  
Customer address Job number SK 230218

เลขที่ 097

เลขที่ 4807

Customer name Sand L Specialty Polymers Co., Ltd. Date 14/12/2023

เลขที่ 097

เลขที่ 4805

Customer name Sand L Specialty Polymers Co., Ltd. Date 14/12/2023  
Customer address \_\_\_\_\_ Job number EX 230218

# ภาคผนวก ข-43

---

แผนและผลการบำรุงรักษาท่อขนส่ง

NO.	Equipment	Tag No.	P&ID No.	Name	Type/Model	Detail	Period (year)	Last service (year)	Next service (year)	Interval	Unit	Due Date
		DR47-1-U	1027	Air Dryer	Air Dryer	Change spare part	3.00	2018	2023	3	Y	00-11-23
		DR47-1-U	1027	Air Dryer	Air Dryer	Change seal kit air cylinder	1.00	2022	2023	1	Y	1-Nov-23
249	Air Dryer	DR47-2-U	1027	Air Dryer	Air Dryer	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		DR47-2-U	1027	Air Dryer	Air Dryer	Change spare part	1.00	2022	2023	1	Y	1-Jul-24
		DR47-2-U	1027	Air Dryer	Air Dryer	Change spare part	3.00	2018	2023	3	Y	00-11-23
		DR47-2-U	1027	Air Dryer	Air Dryer	Change seal kit air cylinder	1.00	2022	2023	1	Y	1-Mar-25
250	Air Dryer	DR47-3-U	1027	Air Dryer	Air Dryer	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		DR47-3-U	1027	Air Dryer	Air Dryer	Change spare part	1.00	2022	2023	1	Y	1-Nov-25
		DR47-3-U	1027	Air Dryer	Air Dryer	Change spare part	3.00	2018	2023	3	Y	00-11-23
		DR47-3-U	1027	Air Dryer	Air Dryer	Change seal kit air cylinder	1.00	2022	2023	1	Y	1-Jul-26
251	Overhead crane	K214-D	Ware house 1	Hoist Mono rail	Overhead Crane 1.6 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K214-D	Ware house 1	Hoist Mono rail	Overhead Crane 1.6 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
252	Overhead crane	K219-1-D	Ware house 1	Hoist Mono rail	Overhead Crane 2.0 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K219-1-D	Ware house 1	Hoist Mono rail	Overhead Crane 2.0 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
253	Overhead crane	K219-2-D	Ware house 2	Hoist Mono rail	Overhead Crane 2.0 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K219-2-D	Ware house 2	Hoist Mono rail	Overhead Crane 2.0 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
254	Overhead crane	K219-3-D	Ware house 2	Hoist Mono rail	Overhead Crane 1.6 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K219-3-D	Ware house 2	Hoist Mono rail	Overhead Crane 1.6 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
255	Overhead crane	K219-4-D	Ware house 1	Hoist Mono rail	Overhead Crane 2.0 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K219-4-D	Ware house 1	Hoist Mono rail	Overhead Crane 2.0 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
256	Overhead crane	K211-1-P	Ware house 3	Hoist Mono rail	Overhead Crane 1.6 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K211-1-P	Ware house 3	Hoist Mono rail	Overhead Crane 1.6 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
257	Overhead crane	K211-2-P	Ware house 3	Hoist Mono rail	Overhead Crane 1.6 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K211-2-P	Ware house 3	Hoist Mono rail	Overhead Crane 1.6 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
258	Overhead crane	K212-P	Ware house 3	Hoist Mono rail	Overhead Crane 1.6 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K212-P	Ware house 3	Hoist Mono rail	Overhead Crane 1.6 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
259	Overhead crane	K216-1-A	Reactor house	Hoist Mono rail	Overhead Crane 3.0 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K216-1-A	Reactor house	Hoist Mono rail	Overhead Crane 3.0 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
260	Overhead crane	K216-2-A	Reactor house	Hoist Mono rail	Overhead Crane 3.0 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K216-2-A	Reactor house	Hoist Mono rail	Overhead Crane 3.0 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
261	Overhead crane	K215-1-A	Reslurry house	Hoist Mono rail	Overhead Crane 2 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K215-1-A	Reslurry house	Hoist Mono rail	Overhead Crane 2 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
262	Overhead crane	K215-2-A	Reslurry house	Hoist Mono rail	Overhead Crane 2 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K215-2-A	Reslurry house	Hoist Mono rail	Overhead Crane 2 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
263	Overhead crane	K213-A	V37 A	Hoist Mono rail	Overhead Crane 1.6 tons	PM package unit	0.25	2022	2023	3	M	1-Jun-23
		K213-A	V37 A	Hoist Mono rail	Overhead Crane 1.6 tons	Loadtest	1.00	2022	2023	1	Y	1-Jun-23
264	CL2 piping	CL2 piping	CL2 line	CL2 piping	CS and PTFE lining	Thickness inspection	1.00	2022	2023	1	Y	1-Apr-23
265	Bag Filter	S53-P	1002	Bag filter for PVC loading	4,348m3/hr Casing SUS304	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
266	Bag Filter	S52-1-P	1003	Bag filter for PVC Silo	4,000m3/hr Casing SUS304	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
267	Bag Filter	S52-2-P	1003	Bag filter for PVC Silo	4,000m3/hr Casing SUS304	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
268	Bag Filter	S52-3-P	1003	Bag filter for PVC Silo	4,000m3/hr Casing SUS304	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
269	Bag Filter	S52-4-P	1003	Bag filter for PVC Silo	4,000m3/hr Casing SUS304	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
270	Bag Filter	S31-1-P	1004	Bag filter for PVC Weighing Hopper	1,300Nm3/hr Casing SUS304	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
271	Bag Filter	S31-2-P	1004	Bag filter for PVC Weighing Hopper	1,300Nm3/hr Casing SUS304	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
272	Bag Filter	S56-D	1019	Bag filter for off spec Hopper	480Nm3/hr Casing TP340	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
273	Bag Filter	S55-D	1019	Bag filter for Truck loading	1,800Nm3/hr Casing SUS304	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
274	Bag Filter	S19-1-D	1019	Bag filter for CPVC Silo	480Nm3/hr Casing TP340	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
275	Bag Filter	S19-2-D	1019	Bag filter for CPVC Silo	480Nm3/hr Casing TP340	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
276	Bag Filter	S19-3-D	1019	Bag filter for CPVC Silo	480Nm3/hr Casing TP340	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
277	Bag Filter	S19-4-D	1019	Bag filter for CPVC Silo	480Nm3/hr Casing TP340	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
278	Mist separator	S32-1-D	1017	Mist separator	TMC-S-600	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
		S32-1-D	1017	Mist separator	TMC-S-600	Cleaning by water	3.00	2021	2024	3	Y	1-Nov-24
279	Mist separator	S32-2-D	1018	Mist separator	TMC-S-600	Visual Inspection	1.00	2022	2023	1	Y	1-Nov-23
		S32-2-D	1018	Mist separator	TMC-S-600	Cleaning by water	3.00	2021	2024	3	Y	1-Nov-24
280	Pressure control valve	PCV-332	1026	Control valve Steam line at -		Calibration set point 1.50 > 1.10 (MPaG)	1.00	2022	2023	1	Y	1-Nov-23
281	Pressure control valve	PCV-333	1026	Control valve Steam line at -		Calibration set point 1.10 > 0.80 (MPaG)	1.00	2022	2023	1	Y	1-Nov-23
282	Pressure control valve	PCV-334	1026	Control valve Steam line at -		Calibration set point 0.80 > 0.40 (MPaG)	1.00	2022	2023	1	Y	1-Nov-23



INSPECTION REPORT  
FOR  
S&L SPECIALTY POLYMERS CO., LTD.

ULTRASONIC THICKNESS MEASUREMENT  
FOR  
LINE CHLORINE GAS

INSPECTION DATE  
19-21 April 2023





PREPARED BY  
IS INDUSTRIE (THAILAND) LTD.

AUTHORIZATION...

EXAMINED/ EVALUATED BY :





WITNESSED/ APPROVED BY :





WITNESSED/ APPROVED BY :


























**INSPECTION REPORT  
FOR  
S&L SPECIALTY POLYMERS CO., LTD.**

**VISUAL EXAMINATION  
FOR  
LINE CL**

**INSPECTION DATE  
19-20 April 2023**

**PREPARED BY  
IS INDUSTRIE (THAILAND) LTD.**

PROJECT :	Pipeline Inspection	DATE:	19-20 April 2023
CLIENT :	S&L SPECIALTY POLYMERS CO., LTD.	LOCATION:	Rayong
WELDER No.:	N/A	WELDING PROCCE:	N/A
NDE METHOD:	Visual inspection	REFERENCE CODE :	API 570

