



เอกสารแนบที่ 2-19

การตรวจสอบอุปกรณ์ สายไฟฟ้า



บริษัท สุวรรณ บุดี เอ็นจิเนียริ่ง จำกัด

237/14 หมู่บ้านอัครา ถนนราษฎร์พัฒนา แขวงราษฎร์พัฒนา เขตสะพานสูง กรุงเทพมหานคร 10240

โทรศัพท์ 0-2045-0246 แฟกซ์ 0-2045-0247, E-mail : swbd.eng@gmail.com

Conditions status and meaning

1°C to 10°C **Priority N** : Normal

11°C to 20°C **Priority 1** : Minor Problem, Possible deficiency; warrants investigation

21°C to 40°C **Priority 2** : Medium problem, Indicates probable deficiency; repair as time permits

>41°C **Priority 3** : Serious Problem, Major discrepancy; repair immediately

Summary Report Thermo Scan

โรงพยาบาลเปาโล เมดิค รังสิต

Location/Plant	Cubicle/Panel ID.	Devices ID.	Descriptino	Before	Page
				Priority	No.
R Floor	LP Panel	ELCD	-	N	1
R Floor	LP Panel	LCD	-	N	2
R Floor	DB Panel	DBD	Main Breaker	N	3
R Floor	DB Panel	DBD	Feeder Breaker	N	4
R Floor	DB Panel	EDBD	Main Breaker	N	5
R Floor	DB Panel	EDBD	Feeder Breaker	N	6
R Floor	DB Panel	EDBR1	Main Breaker	N	7
R Floor	DB Panel	EDBR1	Feeder Breaker	N	8
R Floor	MDB Panel	CAP 1	Step 1-2-3	N	9
R Floor	MDB Panel	CAP 1	Step 4-5-6	N	10
R Floor	MDB Panel	CAP 1	Step 7-8-9	N	11
R Floor	MDB Panel	CAP 1	Step 10-11-12	N	12
R Floor	MDB Panel	CAP 2	Step 1-2-3	N	13
R Floor	MDB Panel	CAP 2	Step 4-5-6	N	14
R Floor	MDB Panel	CAP 2	Step 7-8-9	N	15
R Floor	MDB Panel	CAP 2	Step 10-11-12	N	16
R Floor	Transformer No.1	HV Bushing	Phase A-B	N	17
R Floor	Transformer No.1	HV Bushing	Phase B-C	N	18
R Floor	Transformer No.1	LV Bushing	Phase A-B	N	19
R Floor	Transformer No.1	LV Bushing	Phase B-C	N	20
R Floor	Transformer No.2	HV Bushing	Phase A-B	N	21
R Floor	Transformer No.2	HV Bushing	Phase B-C	N	22
R Floor	Transformer No.2	LV Bushing	Phase A-B	N	23
R Floor	Transformer No.2	LV Bushing	Phase B-C	N	24
R Floor	MDB Panel	MDB-1	Main Breaker	N	25
R Floor	MDB Panel	MDB-1	TIE Breaker	N	26
R Floor	MDB Panel	Busduct No.5 1,600A	Incoming	N	27
R Floor	MDB Panel	Busduct No.5 1,600A	Outgoing	N	28
R Floor	MDB Panel	Busduct No.1 1,000A	-	N	29



บริษัท สุวรรณ บุดี เอ็นจิเนียริ่ง จำกัด

237/14 หมู่บ้านอัครา ถนนราษฎร์พัฒนา แขวงราษฎร์พัฒนา เขตสะพานสูง กรุงเทพมหานคร 10240

โทรศัพท์ 0-2045-0246 แฟกซ์ 0-2045-0247, E-mail : swbd.eng@gmail.com

Conditions status and meaning

1°C to 10°C **Priority N** : Normal

11°C to 20°C **Priority 1** : Minor Problem, Possible deficiency; warrants investigation

21°C to 40°C **Priority 2** : Medium problem, Indicates probable deficiency; repair as time permits

>41°C **Priority 3** : Serious Problem, Major discrepancy; repair immediately

Summary Report Thermo Scan

โรงพยาบาลเปาโล เมดิค รังสิต

Location/Plant	Cubicle/Panel ID.	Devices ID.	Descriptino	Before	Page
				Priority	No.
R Floor	MDB Panel	MDB-2	Main Breaker	N	30
R Floor	MDB Panel	MDB-2	TIE Breaker	N	31
R Floor	MDB Panel	Busduct No.2 1,000A	-	N	32
R Floor	MDB Panel	Fire Protection Panel	-	N	33
R Floor	MDB Panel	Normal, Emergency Bus	-	N	34
R Floor	MDB Panel	EMDB Bus	-	N	35
R Floor	MDB Panel	Busduct No.3 1,000A	Incoming	N	36
R Floor	MDB Panel	Busduct No.3 1,000A	Outgoing	N	37
R Floor, ห้องเครื่องลิฟท์	DB Panel	MF1	-	N	38
8th Floor	DB Panel	EDB8	Main Breaker	N	39
8th Floor	DB Panel	EDB8	Outgoing Breaker	N	40
8th Floor	DB Panel	DB8	Main Breaker	N	41
8th Floor	DB Panel	DB8	Outgoing Breaker	N	42
8th Floor	LP Panel	LC8	-	N	43
8th Floor	LP Panel	LAC8	-	N	44
8th Floor	LP Panel	ELC8	-	N	45
8th Floor	LP Panel	LC8/1	-	N	46
8th Floor	LP Panel	ULCC8	-	N	47
6th Floor	DB Panel	EDB6	Main Breaker	N	48
6th Floor	DB Panel	EDB6	Outgoing Breaker	N	49
6th Floor	DB Panel	DB6	Main Breaker	N	50
6th Floor	DB Panel	DB6	Outgoing Breaker	N	51
6th Floor	LP Panel	LC6	-	N	52
6th Floor	LP Panel	LAC6	-	N	53
6th Floor	LP Panel	ELC6	-	N	54
6th Floor	LP Panel	LC6/1	-	N	55
6th Floor	LP Panel	ULCC6	-	N	56
5th Floor	DB Panel	EDB5	Main Breaker	N	57
5th Floor	DB Panel	EDB5	Outgoing Breaker	N	58



บริษัท สุวรรณ บุดี เอ็นจิเนียริง จำกัด

237/14 หมู่บ้านอัครา ถนนราษฎร์พัฒนา แขวงราษฎร์พัฒนา เขตสะพานสูง กรุงเทพมหานคร 10240

โทรศัพท์ 0-2045-0246 แฟกซ์ 0-2045-0247, E-mail : swbd.eng@gmail.com

Conditions status and meaning

1°C to 10°C **Priority N** : Normal

11°C to 20°C **Priority 1** : Minor Problem, Possible deficiency; warrants investigation

21°C to 40°C **Priority 2** : Medium problem, Indicates probable deficiency; repair as time permits

>41°C **Priority 3** : Serious Problem, Major discrepancy; repair immediately

Summary Report Thermo Scan

โรงพยาบาลเปาโล เมดิค รังสิต

Location/Plant	Cubicle/Panel ID.	Devices ID.	Descriptino	Before	Page
				Priority	No.
5th Floor	DB Panel	DB5	Main Breaker	N	59
5th Floor	DB Panel	DB5	Outgoing Breaker	N	60
5th Floor	LP Panel	LC5	-	N	61
5th Floor	LP Panel	LAC5	-	N	62
5th Floor	LP Panel	ELC5	-	N	63
5th Floor	LP Panel	LC5/1	-	N	64
5th Floor	LP Panel	ULCC5	-	N	65
4th Floor	DB Panel	EDB4	Main Breaker	N	66
4th Floor	DB Panel	EDB4	Outgoing Breaker	N	67
4th Floor	DB Panel	EDB4	Outgoing Breaker	N	68
4th Floor	DB Panel	DB4	Main Breaker	N	69
4th Floor	DB Panel	DB4	Outgoing Breaker	N	70
4th Floor	LP Panel	LC4	-	N	71
4th Floor	LP Panel	ULCC4	-	N	72
4th Floor	LP Panel	LAC4	-	N	73
4th Floor	LP Panel	ELC4	-	N	74
3rd Floor	DB Panel	DB3	Main Breaker	N	75
3rd Floor	DB Panel	DB3	Outgoing Breaker	N	76
3rd Floor	DB Panel	EDB3	Main Breaker	N	77
3rd Floor	DB Panel	EDB3	Outgoing Breaker	N	78
3rd Floor	DB Panel	EDB3	Outgoing Breaker	N	79
3rd Floor	LP Panel	ELC3	-	N	80
3rd Floor	LP Panel	ULCM3	-	N	81
3rd Floor	LP Panel	ULCC3	-	N	82
3rd Floor	LP Panel	LC3	-	N	83
3rd Floor	LP Panel	ELAC3	-	N	84
2nd Floor	DB Panel	DB2	Main Breaker	N	85
2nd Floor	DB Panel	DB2	Outgoing Breaker	N	86
2nd Floor	DB Panel	EDB 2	Main Breaker	N	87



บริษัท สวรรณ บุดี เอ็นจิเนียริง จำกัด

237/14 หมู่บ้านอัครา ถนนราษฎร์พัฒนา แขวงราษฎร์พัฒนา เขตสะพานสูง กรุงเทพมหานคร 10240

โทรศัพท์ 0-2045-0246 แฟกซ์ 0-2045-0247, E-mail : swbd.eng@gmail.com

Conditions status and meaning

1°C to 10°C **Priority N** : Normal

11°C to 20°C **Priority 1** : Minor Problem, Possible deficiency; warrants investigation

21°C to 40°C **Priority 2** : Medium problem, Indicates probable deficiency; repair as time permits

>41°C **Priority 3** : Serious Problem, Major discrepancy; repair immediately

Summary Report Thermo Scan

โรงพยาบาลเปาโล เมดิค รังสิต

Location/Plant	Cubicle/Panel ID.	Devices ID.	Descriptino	Before	Page
				Priority	No.
2nd Floor	DB Panel	EDB 2	Outgoing Breaker	N	88
2nd Floor	LP Panel	ELC2	-	N	89
2nd Floor	LP Panel	ULCM2	-	N	90
2nd Floor	LP Panel	ULCC2	-	N	91
2nd Floor	LP Panel	LAC2	-	N	92
2nd Floor	LP Panel	LC2	-	N	93
G Floor	DB Panel	DB1	Main Breaker	N	94
G Floor	DB Panel	DB1	Outgoing Breaker	N	95
G Floor	DB Panel	EDB1	Main Breaker	N	96
G Floor	DB Panel	EDB1	Outgoing Breaker	N	97
G Floor	DB Panel	EDB1	Outgoing Breaker	N	98
G Floor	DB Panel	EDB1	Outgoing Breaker	N	99
G Floor	LP Panel	ULCC1	-	N	100
G Floor	LP Panel	ULCM1	-	N	101
G Floor	LP Panel	LAC1	-	N	102
G Floor	LP Panel	LC1	-	N	103
G Floor	LP Panel	ELC1	-	N	104
B1 Floor	DB Panel	SN-1	Main Breaker	N	105
B1 Floor	DB Panel	SN-1	Outgoing Breaker	N	106
B1 Floor	DB Panel	SN-3	Main Breaker	N	107
B1 Floor	DB Panel	SN-3	Outgoing Breaker	N	108
ลานจอดรถ	DB Panel	DST1	Main Breaker	N	109
ลานจอดรถ	DB Panel	DST1	Outgoing Breaker	N	110