

Check List Alarm System

Sep-23

[illegible]

Note: Mark [✓] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Check List Alarm System

Sep-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Check List Alarm System

Sep-23

Note: Mark [✓] Normal
Mark (X) Abnormal

Check List Alarm System

Sep-23

Note: Mark [✓] Normal
Mark (X) Abnormal

Check List Alarm System

Sep-23

[illegible]

Note: Mark [✓] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Check List Alarm System

Sep-23

[illegible]

Note: Mark [✓] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Check List Alarm System

[illegible]

(2) = Emergency Light

Check List Alarm System

Sep-23

[illegible]

Note: Mark [✓] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Check List Alarm System

Sep-23

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Note: Mark [$\sqrt{\quad}$] Normal

Mark (X) Abnormal

Check List Alarm System

[illegible]

Note: Mark [✓] Normal
Mark (X) Abnormal

(1) = Fire Exit
(2) = Emergency Light

Check List Alarm System

Sep-23

Note: Mark [$\checkmark$] Normal
Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Sep-23

Note: Mark [$\sqrt{\quad}$] Normal
Mark (X) Abnormal

(2) = Emergency Light

Sep-23

(1) = Fire Exit
(2) = Emergency Light

Check List Alarm System

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Check List Alarm System

[illegible]

Mark (X) Abnormal

(2) = Emergency Light

Check List Alarm System

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Check List Alarm System

Sep-23

[illegible]

Note: Mark [✓] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light


Checklist T.V.



ตารางตรวจเช็คสัญญาณTV

ลำดับ	ชื่อรายการช่องสัญญาณ
1	hotel information
2	HBO
3	Live Sky
4	BBC
5	CNN
6	TV 5 MONDE
7	DW English
8	France 24
9	NHK world Japan
10	sports 2
11	Dubai sports 1
12	Sky Sports 1
13	Channel V
14	NGO
15	Al Jazeera English HD
16	TRT World HD
17	B4U Movies India
18	Filmax
19	xing kong จีน
20	Yemen TV
21	TV5 (ไทย)
22	Nation (ไทย)
23	Work Point(ไทย)
24	True4U (ไทย)
25	GMM (ไทย)
26	Thai PBS (ไทย)
27	CH 8 (ไทย)
28	TNN 24 (ไทย)
29	Mono 29 (ไทย)
30	MCOT (ไทย)
31	ONE (ไทย)
32	Thairath (ไทย)
33	TV3HD (ไทย)
34	Amarin (ไทย)
35	TV7HD (ไทย)
36	PPTV (ไทย)
37	NBT(ไทย)
38	JKN(ไทย)
39	Cvi

Checklist the air conditioner



BOAT LAGOON

FLOOR 1+2+3

ಪ್ರಾಚೀನ

256'6"

LS=Logoon	SL	DLX	PLS	PD	PLD	PMS
-----------	----	-----	-----	----	-----	-----

Summary Clean Air Rooms of FLOOR 1+2+3

Total Rooms	89	Rooms
Total Clean Air Rms	0	Rooms
Clean Air Rooms	0	Rooms
The rest	0	Rooms

Done	0	Rooms
Easy	0	Rooms
Medium	0	Rooms
Hard	0	Rooms

[illegible]

HOTEL WING FLOOR 4+RESORT A+B

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
440	LS	1	9/9/66		454	DLX				468	DLX				482	LS			
441	DLX				455	DLX				469	DLX				483	LS			
442	DLX				456	DLX				470	DLX				484	LS			
443	DLX				457	DLX				471	DLX				485	LS			
444	DLX				458	DLX				472	DLX								
445	DLX				459	DLX				473	DLX	1	4/9/66						
446	DLX				460	DLX				474	DLX								
447	DLX				461	DLX				475	DLX								
448	DLX				462	DLX				476	DLX								
449	DLX				463	DLX				477	DLX	1	32/9/66						
450	DLX				464	DLX				478	DLX								
451	DLX				465	DLX				479	DLX								
452	DLX				466	DLX				480	DLX								
453	DLX				467	DLX				481	DLX								
14		0	0	0	0	14		0	0	0	14		0	0	4		0	0	0

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
138	PLP				236	PLD			
221	PLS				237	PD			
222	PLS				238	PLP			
223	PLS								
224	PLS								
225	PD								
226	PD								
227	PH								
228	x								
231	PD								
232	PLD								
233	PD								
234	PLS								
235	PD								
14		0	0	0	0	3		0	0

Summary Clean Air Rooms FLOOR 4 +Resort A+B

Total Rooms	77	Rooms
Total Defective Rms	0	Rooms
Repaired Rooms	0	Rooms
The rest	0	Rooms
Done	0	Rooms
Easy	0	Rooms
Medium	0	Rooms
Hard	0	Rooms



RESORT C+D+E+F+G+H+I

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
321	PLS				421	PLS				437	PD				537	SUP	1	10/9/66	OK	635	PD	1	17/9/66	OK
322	PLS				422	PLS				438	PLD				538	PLD	1	10/9/66	OK	636	PLD	1	17/9/66	OK
323	PLS				423	PLS				521	PLS	1	10/9/66	OK	541	SUP	1	14/9/66	OK	637	PD	1	17/9/66	OK
324	PLS				424	PLS				522	PLS	1	10/9/66	OK	542	SUP	1	14/9/66	OK	638	PLD	1	17/9/66	OK
325	PD				425	PD				523	PLS	1	10/9/66	OK	621	PLS	1	17/9/66	OK	641	PH	1	17/9/66	OK
326	PD				426	PD				524	PLS	1	10/9/66	OK	622	PLS	1	17/9/66	OK	642	PH	1	17/9/66	OK
331	PD				427	PH				525	PD	1	14/9/66	OK	623	PLS	1	10/9/66	OK	721	PLS			
332	PLD				428	PH				526	PD	1	14/9/66	OK	624	PLS	1	10/9/66	OK	722	PLS			
333	PD				431	PD				531	PD	1	14/9/66	OK	625	PD	1	10/9/66	OK	723	PLS			
334	PLD				432	PLD				532	PLD	1	14/9/66	OK	626	PD	1	10/9/66	OK	724	PLS			
335	PD				433	PD				533	PD	1	14/9/66	OK	631	PD	1	17/9/66	OK	725	PD			
336	PLD				434	PLD				534	PLD	1	10/9/66	OK	632	PLS	1	17/9/66	OK	726	PD			
337	PD				435	PD				535	PD	1	14/9/66	OK	633	PD	1	17/9/66	OK	731	PD			
338	PLD				436	PLD				536	PLD	1	10/9/66	OK	634	PLD	1	17/9/66	OK	732	PLD			
14	0	0	0	0	0	14	0	0	0	14	0	0	0	0	14	0	0	0	0	14	0	0	0	0

Summary Clean Air Rooms of RESORT C+D+E+F+G+H+I

Total Rooms	106	Rooms
Total Defective Rms	0	Rooms
Repaired Rooms	0	Rooms
The rest	0	Rooms
Done	0	Rooms
Easy	0	Rooms
Medium	0	Rooms
Hard	0	Rooms

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
733	PD				932	PD				948	PH			
734	PLD				933	PLD				8		0	0	0
735	PD				934	PD								
736	PLD				935	PLD								
737	PD				936	PD								
738	PLD				937	PLD								
741	PH				938	PLD								
742	PH													
925	PMS				949	PH								
926	PMS				921	PMS								
927	PMS				922	PMS								
928	PMS				923	PMS								
929	PMS				924	PMS								
930	PMS				931	PLD								
14	0	0	0	0	14	0	0	0	0	14	0	0	0	0

Inspection report

October



shutterstock.com • 111342436

Master Checklist
Monthly Audit - Fire, Life and Safety
(to be submitted by 5th of the following month to Engineering)

2023

[illegible]

	Completion Date	Starting Date	Completion Date	Starting Date	Completion Date	Starting Date
Quaterly						
Laundry Dect Cleaning						
Kitchen Exhaust Ducts Cleaning						


Bi-Annual	Date	Date
Fire Blankets		
Evacuation Drill		

Yearly	Date
Main Fire Pump Flow Test	9/10/66
Emergency Generator Load Test for 2 hours	
Fire Water Tank Cleaning	
Fire Authority Consent Certificate	
Fire Brigade Emergency Training	
Evacuation Drill with Guest	

Director Of Engineering / Chief Engineer

Date 25 Oct - 23

Checklist GEN



12/17

TEST RUN RECORD FOR EMERGENCY GENERATOR

DATE 14/10/66 ENGINEER วิวัฒน์ วัฒนา
 GENERATOR 500KVA LOCATION ลานกิจกรรม

สภาพเครื่องก่อน TEST RUN

- ☒ ระดับน้ำมันเครื่อง (Motor Oil) เต็ม
- ☒ สภาพสายพาน (Machine Belt)
- ☒ ระดับน้ำในหม้อน้ำ (Boiler)
- ☒ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

TEST RUN

☐ ON LOAD ☒ OFF LOAD

TIME START 14.15 น. TIME STOP 14.39 น.

รายการตรวจเช็ค		บันทึก
Oil (L.)	<u>30%</u>	<u>25%</u>
Voltage (V)	L1	<u>397</u>
Voltage (V)	L2	<u>- N/A</u>
Voltage (V)	L3	<u>399</u>
Coolant Temp (°C)		<u>70</u>
Oil Pressure (bar)		<u>4.27</u>
Speed (RPM)		<u>N/A</u>
Frequency (Hz)		<u>N/A</u>
Battery (V)		<u>27.2</u>
Run Time (h)		<u>562h13m</u>

REMARK

* ตรวจ DEEP SEA ELECTRONICS
 เชื้อเพลิงในถังมี 70 ลิตร
 ควรเปลี่ยนถ่าย
 * ควรเติมน้ำมันเพิ่ม 400 ลิตร.
 * เติมน้ำมัน 400 ลิตร
20/10/66

กรมการขนส่งทางบก กองการขนส่ง
กรมการขนส่งทางบก กองการขนส่ง

วันที่	ผู้ขับขี่	รถ	km / day	OFFLOAD	หมายเหตุ	km
2	4/3/63	14.45-11.35	-	✓	ตามปกติ	100
1	4/1/63	13.40-11.30	-	✓	ตามปกติ	100
3	18/1/63	12.30-10.10	-	✓	ตามปกติ	100

















เครื่องกำเนิดไฟฟ้า 3
Generator



ENCLOSURE









DATE 14/10/66 ENGINEER *[Signature]*
GENERATOR 1000 KVA LOCATION *[Signature]*

☒	ระดับน้ำมันเครื่อง (Motor Oil)
☒	สภาพสายพาน (Machine Belt)
☒	ระดับน้ำในหม้อน้ำ (Boiler)
☒	ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

☐ ON LOAD ☒ OFF LOAD

TIME START 14.2926 TIME STOP 14.4526

รายการตรวจเช็ค	บันทึก
Oil (L.)	17800
Voltage (V)	L1 406
Voltage (V)	L2 407
Voltage (V)	L3 406
Coolant Temp (°C)	60
Oil Pressure (bar)	5.24
Speed (RPM)	1509
Frequency (Hz)	50.3
Battery (V)	27.4
Run Time (h)	201h


Handwritten table on a grid background, likely a log or inventory sheet. The table has columns for 'Date', 'Time', 'CH 1001', 'CH 1002', 'Remarks', and 'Signature'. The first three rows contain handwritten data.

Date	Time	CH 1001	CH 1002	Remarks	Signature
1. 11/1/03	2. 11/1/03				
2. 11/1/03	11/1/03				
3. 11/1/03	11/1/03				




เครื่องกำเนิดไฟฟ้า 2
Generator
















Fire extinguishing system Checklist



shutterstock.com • 1686964432

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building A

Monthly..10/2023

จุดติดตั้ง	ประเภทสารเคมี	ระดับแรงดัน(Pressure Level)	สลักนิรภัย(Safety Latch)	สายไม่ผูกขาด,อุดตัน	ไม่มีสิ่งกีดขวาง(no obstruction)	ติดตั้งไม่เกิน 1.4 M	ป้ายแสดงจุด	ความสะอาด(cleanliness)	DATE	ผู้ตรวจ	การดำเนินการกรณีผิดปกติ	ผู้รับผิดชอบ	กำหนดเสร็จ
ตึก A													
บันไดข้าง													
หน้าห้อง121 (1ถัง)	ผงเคมี-ABC								12/10				
หน้าห้อง131 (1ถัง)	ผงเคมี-ABC												
บันไดกลาง													
หน้าห้อง122 (1ถัง)	ผงเคมี-ABC								12/10				
บันไดข้าง													
หน้าห้อง124 (1ถัง)	NON-CFC								12/10				
หน้าห้อง137 (1ถัง)	ผงเคมี-ABC												
หน้าตึก													
หน้าห้อง A21 (1ถัง)	NON-CFC								12/10				
หลังตึก													
หน้าห้อง MDB (1ถัง)	ผงเคมี-ABC								12/10				

หมายเหตุ: เครื่องหมาย [V] คือ ปกติ
เครื่องหมาย [X] คือ ผิดปกติ ต้องระบุงการแก้ไข Loss Prevention Recheck.....

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building B

Monthly..10/2023

จุดติดตั้ง	ประเภทสารเคมี	ระดับแรงดัน(Pressure Level)	สลักนิรภัย(Safety Latch)	สารไม่ใช้ก๊าซชนิดอื่น	ไม่มีสิ่งกีดขวาง(no obstruction)	ติดตั้งไม่เกิน 1.4 M	ป้ายแสดงจุด	ความสะอาด(cleanliness)	DATE	ผู้ตรวจ	การดำเนินการกรณีผิดปกติ	ผู้รับผิดชอบ	กำหนดเสร็จ
ตึก B													
บันไดข้าง													
หน้าห้อง221 (1ถัง)	ผงเคมี-ABC								18/10				
หน้าห้อง231 (1ถัง)	ผงเคมี-ABC												
บันไดกลาง													
หน้าห้อง222 (2ถัง)	ผงเคมี-ABC								18/10				
หน้าห้อง233 (2ถัง)	ผงเคมี-ABC												
บันไดข้าง													
หน้าห้อง224 (1ถัง)	ผงเคมี-ABC								18/10				
หน้าห้อง237 (1ถัง)	ผงเคมี-ABC												
หน้าตึก													
หน้าห้อง20/4 (1ถัง)	ผงเคมี-ABC								18/10				
หลังตึก													
หน้าห้อง20/1-4 (2ถัง)	ผงเคมี-ABC								18/10				

หมายเหตุ:

เครื่องหมาย [✓] คือ ปกติ

เครื่องหมาย [X] คือ ผิดปกติ ต้องระงับการแก้ไข

Loss Prevention Recheck.....



NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building C

Monthly..10/2023

จุดติดตั้ง	ประเภทสารเคมี	ระดับแรงดัน(Pressure Level)	สลักนิรภัย(Safety Latch)	สายไม่ผูกขวาง, อุดตัน	ไม่มีสิ่งกีดขวาง(no obstruction)	ติดตั้งไม่เกิน 1.4 M	ป้ายแสดงจุด	ความสะอาด(cleanliness)	DATE	ผู้ตรวจ	การดำเนินการกรณีผิดปกติ	ผู้รับผิดชอบ	กำหนดเสร็จ
ตึก C													
บันไดข้าง													
หน้าห้อง321 (1ถัง)	ผงเคมี-ABC								12/10				
หน้าห้อง331 (2ถัง)	ผงเคมี-ABC												
บันไดกลาง													
หน้าห้อง322 (2ถัง)	ผงเคมี-ABC								12/10				
หน้าห้อง334 (2ถัง)	ผงเคมี-ABC												
บันไดข้าง													
หน้าห้อง324 (1ถัง)	ผงเคมี-ABC								12/10				
หน้าห้อง237 (1ถัง)	ผงเคมี-ABC												
หน้าตึก													
หน้าห้อง20/8 (1ถัง)	ผงเคมี-ABC								12/10				
หลังตึก													
หน้าห้อง20/5-8 (1ถัง)	ผงเคมี-ABC								12/10				

หมายเหตุ:

เครื่องหมาย [V] คือ ปกติ

เครื่องหมาย [X] คือ ผิดปกติ ต้องระบุการแก้ไข

Loss Prevention Recheck.....

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building D

Monthly..10/2023

จุดติดตั้ง	ประเภทสารเคมี	ระดับแรงดัน(Pressure Level)	สลักนิรภัย(Safety Latch)	สายไม่เสียหาย/อุดตัน	ไม่มีสิ่งกีดขวาง(no obstruction)	ติดตั้งไม่เกิน 1.4 M	ป้ายแสดงจุด	ความสะอาด(cleanliness)	DATE	ผู้ตรวจ	การดำเนินการกรณีผิดปกติ	ผู้รับผิดชอบ	กำหนดเสร็จ
ตึก D													
บันไดข้าง													
หน้าห้อง421 (1ถัง)	ผงเคมี-ABC	X	X	X	X	X	X	X	17/10	[Signature]			
หน้าห้อง431 (1ถัง)	ผงเคมี-ABC	X	X	X	X	X	X	X	17/10	[Signature]			
บันไดกลาง													
หน้าห้อง422 (1ถัง)	ผงเคมี-ABC								17/10	[Signature]			
หน้าห้อง434 (1ถัง)	ผงเคมี-ABC								18/10	[Signature]			
บันไดข้าง													
หน้าห้อง424 (1ถัง)	ผงเคมี-ABC								18/10	[Signature]			
หน้าห้อง437 (1ถัง)	ผงเคมี-ABC								18/10	[Signature]			
หน้าตึก													
หน้าห้อง20/12 (1ถัง)	ผงเคมี-ABC								18/10	[Signature]			
หลังตึก													
หน้าห้อง20/9-12 (2ถัง)	ผงเคมี-ABC								18/10	[Signature]			

หมายเหตุ:

เครื่องหมาย [V] คือ ปกติ

เครื่องหมาย [X] คือ ผิดปกติ ต้องระงับการแก้ไข

Loss Prevention Recheck.....

[Signature]

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building E

Monthly..10/2023

จุดติดตั้ง	ประเภทสารเคมี	ระดับแรงดัน(Pressure Level)	สลักนิรภัย(Safety Latch)	สายไม่พันขวางจุดติดตั้ง	ไม่มีสิ่งกีดขวาง(no obstruction)	ติดตั้งไม่เกิน 1.4 M	ป้ายแสดงจุด	ความสะอาด(cleanliness)	DATE	ผู้ตรวจ	การดำเนินการกรณีผิดปกติ	ผู้รับผิดชอบ	กำหนดเสร็จ
ตึก E													
บันไดข้าง													
หน้าห้อง521 (1ถัง)	ผงเคมี-ABC	X	X	X	X	X	X	X	18/10	A			
หน้าห้อง531 (1ถัง)	ผงเคมี-ABC	X	X	X	X	X	X	X					
บันไดกลาง													
หน้าห้อง522 (1ถัง)	ผงเคมี-ABC	/	/	/	/	/	/	/	18/10	A			
หน้าห้อง534 (1ถัง)	ผงเคมี-ABC	/	/	/	/	/	/	/					
บันไดข้าง													
หน้าห้อง524 (1ถัง)	ผงเคมี-ABC	/	/	/	/	/	/	/	18/10	A			
หน้าห้อง537 (1ถัง)	ผงเคมี-ABC	/	/	/	/	/	/	/					
หน้าห้อง20/16 (1ถัง)	ผงเคมี-ABC	/	/	/	/	/	/	/	18/10	A			
หน้าห้อง20/13-16 (2ถัง)	ผงเคมี-ABC	/	/	/	/	/	/	/	18/10	A			

หมายเหตุ:

เครื่องหมาย [V] คือ ปกติ

เครื่องหมาย [X] คือ ผิดปกติ ต้องระบุการแก้ไข

Loss Prevention Recheck.....

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building F

Monthly..10/2023

จุดติดตั้ง	ประเภทสารเคมี	ระดับแรงดัน(Pressure Level)	สลักนิรภัย(Safety Latch)	สายไม่ผูกขาด, อุดตัน	ไม่มีสิ่งกีดขวาง(no obstruction)	ติดตั้งไม่เกิน 1.4 M	ป้ายแสดงจุด	ความสะอาด(cleanliness)	DATE	ผู้ตรวจ	การดำเนินการกรณีผิดปกติ	ผู้รับผิดชอบ	กำหนดเสร็จ
ตึก F													
บันไดข้าง													
หน้าห้อง621 (1ถัง)	ผงเคมี-ABC								18/10				
หน้าห้อง631 (1ถัง)	ผงเคมี-ABC												
บันไดกลาง													
หน้าห้อง623 (1ถัง)	ผงเคมี-ABC								18/10				
หน้าห้อง633 (1ถัง)	ผงเคมี-ABC												
บันไดข้าง													
หน้าห้อง624 (1ถัง)	ผงเคมี-ABC								18/10				
หน้าห้อง637 (1ถัง)	ผงเคมี-ABC												
หน้าตึก													
หน้าห้อง20/20 (1ถัง)	ผงเคมี-ABC								18/10				
หลังตึก													
หน้าห้อง20/17-20 (1ถัง)	ผงเคมี-ABC								18/10				

หมายเหตุ:

เครื่องหมาย [✓] คือ ปกติ

เครื่องหมาย [X] คือ ผิดปกติ ต้องระงับการแก้ไข

Loss Prevention Recheck.....

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building G

Monthly..10/2023

จุดติดตั้ง	ประเภทสารเคมี	ระดับแรงดัน(Pressure Level)	สลักนิรภัย(Safety Latch)	สายไม่พันจากข้อต่อ	ไม่มีสิ่งกีดขวาง(no obstruction)	ติดตั้งไม่เกิน 1.4 M	ป้ายแสดงจุด	ความสะอาด(cleanliness)	DATE	ผู้ตรวจ	การดำเนินการกรณีผิดปกติ	ผู้รับผิดชอบ	กำหนดเสร็จ
ตึก G													
บันไดข้าง													
หน้าห้อง721 (1ถัง)	ผงเคมี-ABC								19/10				
หน้าห้อง731 (1ถัง)	ผงเคมี-ABC								19/10				
บันไดกลาง													
หน้าห้อง722 (1ถัง)	ผงเคมี-ABC								19/10				
หน้าห้อง733 (1ถัง)	ผงเคมี-ABC								19/10				
บันไดข้าง													
หน้าห้อง724 (1ถัง)	ผงเคมี-ABC								19/10				
หน้าห้อง737 (1ถัง)	ผงเคมี-ABC								19/10				
หน้าตึก													
หน้าห้อง20/24 (1ถัง)	ผงเคมี-ABC								19/10				
หลังตึก													
หน้าห้อง20/21-24 (2ถัง)	ผงเคมี-ABC								19/10				

หมายเหตุ:

เครื่องหมาย [V] คือ ปกติ

เครื่องหมาย [X] คือ ผิดปกติ ต้องระบุการแก้ไข

Loss Prevention Recheck.....

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Hotel Wing Floor 1, Restaurant, Lobby

Monthly..10/2023

จุดติดตั้ง	ประเภทสารเคมี	ระดับแรงดัน(Pressure Level)	สลักนิรภัย(Safety Latch)	สายไม่พันขวาง, อุดตัน	ไม่มีสิ่งกีดขวาง(no obstruction)	ติดตั้งไม่เกิน 1.4 M	ป้ายแสดงจุด	ความสะอาด(cleanliness)	DATE	ผู้ตรวจ	การดำเนินการกรณีผิดปกติ	ผู้รับผิดชอบ	กำหนดเสร็จ
ทางเข้าตึก													
บริเวณสแกนนิ้ว (2 ถัง)	ผงเคมี-ABC								14/10				
หน้าห้อง MDB (1ถัง)	ผงเคมี-ABC												
หน้าห้องบัญชี (1ถัง)	ผงเคมี-ABC												
หน้าห้องนำหญิง (1ถัง)	ผงเคมี-ABC												
ห้องครัวพนักงาน (1ถัง)	ผงเคมี-ABC												
ห้องครัวเมน (4ถัง)	ผงเคมี-ABC												
หน้าห้องควบคุมไฟฟ้า (1ถัง)	ผงเคมี-ABC												
ห้องกักตัน (2ถัง)	ผงเคมี-ABC												
หน้าลิฟท์ส่งอาหาร (1ถัง)	ผงเคมี-ABC												
ห้องใบเรือ (2ถัง)	ผงเคมี-ABC												
ห้องเก็บทรัพย์สิน(2ถัง)	ผงเคมี-ABC								12/10				
ห้อง LP 1 ถัง	ผงเคมี-ABC												

หมายเหตุ: เครื่องหมาย [V] คือ ปกติ

เครื่องหมาย [X] คือ ผิดปกติ ต้องระบุการแก้ไข

Loss Prevention Recheck.....

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Hotel Wing FLOOR 2,3

Monthly..10/2023

จุดติดตั้ง	ประเภทสารเคมี	ระดับแรงดัน(Pressure Level)	สลักนิรภัย(Safety Latch)	สายไม่ผูกขวาง(no obstruction)	ติดตั้งสูงไม่เกิน 1.4 M	ป้ายแสดงจุด	ความสะอาด(cleanliness)	DATE	ผู้ตรวจ	การดำเนินการกรณีผิดปกติ	ผู้รับผิดชอบ	กำหนดเสร็จ
FLOOR 2												
Room 242 (1ถัง)	ผงเคมี-ABC											
Room 250 (1ถัง)	ผงเคมี-ABC											
Room 256 (1ถัง)	ผงเคมี-ABC											
Room 264 (1ถัง)	ผงเคมี-ABC											
Room 272 (1ถัง)	ผงเคมี-ABC											
Room 342 (1ถัง)	ผงเคมี-ABC											
Room 348 (1ถัง)	ผงเคมี-ABC											
Room 352 (1ถัง)	ผงเคมี-ABC											
Room 358 (1ถัง)	ผงเคมี-ABC											
Room 364 (1ถัง)	ผงเคมี-ABC											
Room 372 (1ถัง)	ผงเคมี-ABC											
Room 380 (1ถัง)	ผงเคมี-ABC											

หมายเหตุ:

เครื่องหมาย [V] คือ ปกติ

เครื่องหมาย [X] คือ ผิดปกติ ต้องระบุการแก้ไข

Loss Prevention Recheck.....

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Hotel Wing FLOOR 4

Monthly..10/2023

จุดติดตั้ง	ประเภทสารเคมี	ระดับแรงดัน(Pressure Level)	สลักนิรภัย(Safety Latch)	สายไม่พันขวาง(No obstruction)	ติดตั้งไม่เกิน 1.4 M	ป้ายแสดงจุด	ความสะอาด(cleanliness)	DATE	ผู้ตรวจ	การดำเนินการกรณีผิดปกติ	ผู้รับผิดชอบ	กำหนดเสร็จ
FLOOR 4												
Room 442 (1ถัง)	ผงเคมี-ABC											
Room 448 (1ถัง)	ผงเคมี-ABC											
Room 454 (1ถัง)	ผงเคมี-ABC											
Room 460 (1ถัง)	ผงเคมี-ABC											
Room 466 (1ถัง)	ผงเคมี-ABC											
Room 474 (1ถัง)	ผงเคมี-ABC											
Room 482 (1ถัง)	ผงเคมี-ABC											

หมายเหตุ: เครื่องหมาย [✓] คือ ปกติ

เครื่องหมาย [X] คือ ผิดปกติ ต้องระบุงการแก้ไข

Loss Prevention Recheck.....

1

•

[illegible]

(1) = Fire Exit

(2) = Emergency Light

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date..... 16/10/23

Supervisor byDate.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by Date..... 11/10/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

[illegible]

Note: Mark $[\sqrt{\quad}]$ Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date 11/10/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by 16/5/23 Date 11/10/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by 16/10/23 Date..... 11/10/23

Supervisor byDate.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible byDate..... 11/10/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date.....

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date.....

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

[illegible]

Note: Mark $[\sqrt{\quad}]$ Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by behavak Date 11/10/23

Supervisor byDate.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

[illegible]

Note: Mark $[\sqrt{\quad}]$ Normal

Mark (X) Abnormal

Responsible by Wahid Date 11/10/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

[illegible]

Note: Mark $[\sqrt{\quad}]$ Normal

Mark (X) Abnormal

Responsible by Wahid Date 11/10/22

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Oct-23

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 441 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 441 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 446 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 446 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 456 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 456 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 462 (Fire Exit)	✓	✓	✓	✓	✓	11/10/23	กัญจน์	✓			
Room 462 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 473 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 473 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 479 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 479 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 484 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 484 (Emergency)	✓	✓	✓	✓	✓			✓			

Note: Mark [✓] Normal

Mark (X) Abnormal

Responsible by กัญจน์ Date 11/10/23.

Supervisor by Date.....

Check List Alarm System

[illegible]

(2) = Emergency Light

Check List Alarm System

[illegible]

(2) = Emergency Light

NH BOAT LAGOON PHUKET RESORT

Check List Alarm System

Oct-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Check List Alarm System

[illegible]

(1) = Fire Exit

(2) = Emergency Light

(2) = Emergency Light

Check List Alarm System

[illegible]

(2) = Emergency Light

(2) = Emergency Light

NH BOAT LAGOON PHUKET RESORT

Check List Alarm System

Oct-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

NH BOAT LAGOON PHUKET RESORT

Check List Alarm System

Oct-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Check List Alarm System

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Check List Alarm System

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Check List Alarm System

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Check List Alarm System

[illegible]

(2) = Emergency Light

Check List Alarm System

[illegible]

(2) = Emergency Light

Check List Alarm System

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Check List Alarm System

[illegible]

(2) = Emergency Light

Check List Alarm System

[illegible]

(2) = Emergency Light

Check List Alarm System

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Check List Alarm System

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Check List Alarm System


[illegible]

(2) = Emergency Light

Checklist T.V.



Fill the treatment pond with microorganisms




ปริมาณการใช้ไฟฟ้าและสารเคมีของระบบบำบัดน้ำเสีย ประจำเดือน ตุลาคม 2566

Marina wing

ว/ค/ป	เลขมิเตอร์ไฟเติมอากาศ บ่อบำบัดน้ำเสีย		ปริมาณการใช้ไฟฟ้า ของระบบบำบัดน้ำเสีย (หน่วย)	ปริมาณสารเคมีหรือ สารสกัดชีวภาพที่ใช้ (กิโลกรัม)
	ก่อน	หลัง		
1/10/66	29844	29871		-
2/10/66	29871	29896		-
3/10/66	29896	29928		-
4/10/66	29928	29958		-
5/10/66	29958	29987		-
6/10/66	29987	30017		-
7/10/66	30017	30046		-
8/10/66	30046	30076		-
9/10/66	30076	30106		-
10/10/66	30106	30135		-
11/10/66	30135	30165		-
12/10/66	30165	30195		-
13/10/66	30195	30224		-
14/10/66	30224	30253		-
15/10/66	30253	30283		-
16/10/66	30283	30313		-
17/10/66	30313	30343		-
18/10/66	30343	30373		-
19/10/66	30373	30402		-
20/10/66	30402	30432		-
21/10/66	30432	30461		-
22/10/66	30461	30491		-
23/10/66	30491	30521		-
24/10/66	30521	30551		-
25/10/66	30551	30580		-
26/10/66	30580	30611		-
27/10/66	30611	30641		-
28/10/66	30641	30671		-
29/10/66	30671	30700		-
30/10/66	30700	30730		-
31/10/66	30730	30760		-
รวม				

Checklist the air conditioner



BOAT LAGOON

AIR CONDITION CLEAN FILTERS/P.M.

FLOOR 1+2+3

Updated 2566 07/07/2021

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
140	FS2B				240	LS				258	DLX				340	LS				358	DLX			
141	FS2B				241	DLX				259	DLX				341	DLX				359	DLX			
142	FS2B				242	DLX				260	DLX				342	DLX				360	DLX			
143	FS2B				243	DLX				261	DLX				343	DLX	1	24/10/16 OK		361	DLX			
144	FS2B				244	DLX				262	DLX				344	DLX				362	DLX			
145	FS2B				245	DLX				263	DLX				345	DLX				363	DLX			
146	FS2B				246	FDL				264	DLX				346	DLX				364	DLX			
147	FS2B				247	DLX				265	DLX				347	DLX				365	DLX			
148	FS2B				248	DLX				266	DLX				348	DLX				366	DLX			
					249	DLX				267	DLX				349	DLX				367	DLX			
					250	DLX				268	DLX				350	DLX				368	DLX			
					251	DLX				269	DLX				351	DLX				369	DLX			
					252	DLX				270	DLX				352	DLX				370	DLX			
					253	DLX				271	DLX				353	DLX				371	DLX			
					254	DLX				272	DLX				354	DLX				372	DLX			
					255	DLX				273	DLX				355	DLX				373	DLX			
					256	DLX				274	DLX				356	DLX				374	DLX			
					257	DLX				275	LS				357	DLX				375	DLX			
9					18					18					18					18				0

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
376	DLX								
377	DLX	1	21/10/16 OK						
378	DLX								
379	DLX								
380	DLX								
381	DLX								
382	DLX								
383	LS								
8									0

FS2B=Family suite 2 beds LS=Lagoon Suite DLX PLS PD PLD PMS

Summary Clean Air Rooms of FLOOR 1+2+3

Total Rooms	89	Rooms
Total Clean Air Rms	0	Rooms
Clean Air Rooms	0	Rooms
The rest	0	Rooms
Done	0	Rooms
Easy	0	Rooms
Medium	0	Rooms
Hard	0	Rooms



HOTEL WING FLOOR 4+RESORT A+B

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	
440	LS				454	DLX				468	DLX				482	LS					121	PLS			
441	DLX				455	DLX				469	DLX	1	20/10/2018 OK		483	LS					122	PLS			
442	DLX				456	DLX				470	DLX				484	LS					123	PLS			
443	DLX				457	DLX				471	DLX				485	LS					124	PLS			
444	DLX				458	DLX				472	DLX										125	PH			
445	DLX				459	DLX				473	DLX										126	PH			
446	DLX				460	DLX				474	DLX										127	PH			
447	DLX				461	DLX				475	DLX										131	PD			
448	DLX				462	DLX				476	DLX										132	PLP			
449	DLX				463	DLX				477	DLX										133	PD			
450	DLX				464	DLX				478	DLX										134	PLD			
451	DLX				465	DLX				479	DLX										135	PD			
452	DLX				466	DLX				480	DLX										136	PLD			
453	DLX				467	DLX				481	DLX										137	PD			

Summary Clean Air Rooms FLOOR 4 +Resort A+B

Total Rooms	77	Rooms
Total Defective Rms	0	Rooms
Repaired Rooms	0	Rooms
The rest	0	Rooms
Done	0	Rooms
Easy	0	Rooms
Medium	0	Rooms
Hard	0	Rooms

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
138	PLP				236	PLD			
221	PLS				237	PD			
222	PLS				238	PLP			
223	PLS								
224	PLS								
225	PD								
226	PD	1	28/10/26	OK					
227	PH								
228	x								
231	PD								
232	PLD								
233	PD								
234	PLS								
235	PD								

RESORT C+D+E+F+G+H+I

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
321	PLS				421	PLS				437	PD				537	SUP				635	PD			
322	PLS				422	PLS				438	PLD				538	PLD				636	PLD			
323	PLS				423	PLS				521	PLS				541	SUP				637	PD			
324	PLS				424	PLS				522	PLS				542	SUP				638	PLD			
325	PD				425	PD				523	PLS				621	PLS				641	PH			
326	PD				426	PD				524	PLS				622	PLS				642	PH			
331	PD				427	PH				525	PD				623	PLS				721	PLS	1		4/10/66 OK
332	PLD				428	PH				526	PD				624	PLS				722	PLS	1		4/10/66 OK
333	PD				431	PD				531	PD				625	PD				723	PLS	1		4/10/66 OK
334	PLD				432	PLD				532	PLD				626	PD				724	PLS	1		4/10/66 OK
335	PD				433	PD				533	PD				631	PD				725	PD	1		4/10/66 OK
336	PLD				434	PLD				534	PLD				632	PLS				726	PD	1		5/10/66 OK
337	PD				435	PD				535	PD				633	PD				731	PD	1		4/10/66 OK
338	PLD				436	PLD				536	PLD				634	PLD				732	PLD	1		5/10/66 OK

14 0 0 0 0 0 14 0 0 0 0 14 0 0 0 0 14 0 0 0 0 14 0 0 0 0

Summary Clean Air Rooms of RESORT C+D+E+F+G+H+I

Total Rooms	106	Rooms
Total Defective Rms	0	Rooms
Repaired Rooms	0	Rooms
The rest	0	Rooms
Done	0	Rooms
Easy	0	Rooms
Medium	0	Rooms
Hard	0	Rooms

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
733	PD	1	5/10/66 OK	OK	939	PLD	1	7/10/66 OK	OK	932	PD	1	9/10/66 OK	OK
734	PLD	1	5/10/66 OK	OK	940	PD	1	7/10/66 OK	OK	933	PLD	1	9/10/66 OK	OK
735	PD	1	5/10/66 OK	OK	941	PLD	1	9/10/66 OK	OK	934	PD	1	8/10/66 OK	OK
736	PLD	1	5/10/66 OK	OK	942	PD	1	5/10/66 OK	OK	935	PLD	1	8/10/66 OK	OK
737	PD	1	4/10/66 OK	OK	943	PLD	1	9/10/66 OK	OK	936	PD	1	9/10/66 OK	OK
738	PLD	1	5/10/66 OK	OK	944	PD	1	7/10/66 OK	OK	937	PLD	1	9/10/66 OK	OK
741	PH	1	5/10/66 OK	OK	945	PLD	1	9/10/66 OK	OK	938	PLD	1	9/10/66 OK	OK
742	PH	1	6/10/66 OK	OK	946	PD	1	7/10/66 OK	OK	948	PH	1	8/10/66 OK	OK
925	PMS	1	7/10/66 OK	OK	949	PH	1	7/10/66 OK	OK	8		0	0	0
926	PMS	1	7/10/66 OK	OK	921	PMS	1	9/10/66 OK	OK					
927	PMS	1	7/10/66 OK	OK	922	PMS	1	9/10/66 OK	OK					
928	PMS	1	7/10/66 OK	OK	923	PMS	1	7/10/66 OK	OK					
929	PMS	1	7/10/66 OK	OK	924	PMS	1	7/10/66 OK	OK					
930	PMS	1	9/10/66 OK	OK	931	PLD	1	9/10/66 OK	OK					

14 0 0 0 0 0 14 0 0 0 0 14 0 0 0 0

Master Checklist
Monthly Audit - Fire, Life and Safety
(to be submitted by 5th of the following month to Engineering)

Year 2023

[illegible]

Quarterly	Starting Date	Completion Date	Starting Date	Completion Date	Starting Date	Completion Date
Laundry Duct Cleaning						
Kitchen Exhaust Ducts Cleaning						

Bi-Annual	Date	Date
Fire Blankets		
Evacuation Drill		

General Manager / Resort Manager

Date 7/12/23

Date _____

Signature

Director Of Engineering / Chief Engineer

Date 25 NOV - 99

Yearly	Date
Main Fire Pump Flow Test	9/19/06
Emergency Generator Load Test for 2 hours	
Fire Water Tank Cleaning	
Fire Authority Consent Certificate	
Fire Brigade Emergency Training	
Evacuation Drill with Guest	

TEST RUN RECORD FOR EMERGENCY GENERATOR

DATE 10/11/66. ENGINEER วิจิตร / 6 พฤศจิกายน 66
 GENERATOR 1000 KVA LOCATION ตึกโรงสี

สภาพเครื่องก่อน TEST RUN

- ☒ ระดับน้ำมันเครื่อง (Motor Oil)
- ☒ สภาพสายพาน (Machine Belt)
- ☒ ระดับน้ำในหม้อน้ำ (Boiler)
- ☒ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)


TEST RUN

☐ ON LOAD ☒ OFF LOAD

TIME START 14.15 น. TIME STOP 14.35 น.

รายการตรวจเช็ค		บันทึก	REMARK
Oil (L.)		<u>1790</u>	<u>1770</u>
Voltage (V)	L1	<u>405</u>	
Voltage (V)	L2	<u>405</u>	
Voltage (V)	L3	<u>405</u>	
Coolant Temp (°C)		<u>65</u>	
Oil Pressure (bar)		<u>4.89</u>	
Speed (RPM)		<u>1509</u>	
Frequency (Hz)		<u>50.3</u>	
Battery (V)		<u>27.4</u>	
Run Time (h)		<u>201.24</u>	

(241)



12/1/17

TEST RUN RECORD FOR EMERGENCY GENERATOR

DATE 10/11/66 ENGINEER สว.จ.น.ต./พ.ว.ค.ว.ร.
 GENERATOR 500KVA LOCATION ลานกิจกรรม
(CUMMINS.)

สภาพเครื่องก่อน TEST RUN

- ☒ ระดับน้ำมันเครื่อง (Motor Oil) เริ่มขึ้น
- ☒ สภาพสายพาน (Machine Belt)
- ☒ ระดับน้ำในหม้อน้ำ (Boiler)
- ☒ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

TEST RUN

☐ ON LOAD ☒ OFF LOAD

TIME START 13.55 น. TIME STOP 14.20 น.

รายการตรวจเช็ค		บันทึก
Oil (L.)	<u>95%</u>	
Voltage (V)	L1	<u>397</u>
Voltage (V)	L2	<u>N/A</u>
Voltage (V)	L3	<u>399</u>
Coolant Temp (°C)		<u>70</u>
Oil Pressure (bar)		<u>3.92</u>
Speed (RPM)		<u>-</u>
Frequency (Hz)		<u>-</u>
Battery (V)		<u>27.3</u>
Run Time (h)	<u>556.53</u>	<u>567.18</u>


REMARK
* จอแสดงผล Deep Sea เริ่ม
อ่านค่าจากจอได้


เอกสารควบคุมการเดินเครื่องจักร
เรือชื่อ XERO No. 10 SEC New, สมุทรปราการ

วันที่	ชื่อ	SMY	CM / ZND	DT/LOAD	อื่นๆ	หมายเหตุ
3	4/1/63	14-15-16-17	-	✓		เครื่อง 1
1	1/1/63	15-16-17-18	-	✓		เครื่อง 1
3	1/1/63	15-16-17-18	-	✓		เครื่อง 1









NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building A

Monthly..11/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building A													
Side Steps													
Corridor Room 121	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 131	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Central Staircase													
Corridor Room 122	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Side Steps													
Corridor Room 124	NON-CFC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	17/11/23	Santichai			
Corridor Room 137	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	17/11/23	Santichai			
Facade of Building													
Corridor Room A21	NON-CFC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Behind the Building													
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			

Remark;
☒ Normal
☐ Abnormal

Loss Prevention Check

Room Division Manager

P. Jao 2/12/23

20/11/23

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building B

Monthly..11/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building B													
Side Steps													
Corridor Room 221	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 231	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Central Staircase													
Corridor Room 222 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 233 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Side Steps													
Corridor Room 224	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
CorridorRoom 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Facade of Building													
Corridor Office 20/4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Behind the Building													
Corridor Office 20/1-4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			

Remark;

☒ Normal

☐ Abnormal

Loss Prevention Check

Room Division Manager



20/11/23

 2/12/23

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building C

Monthly..11/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building C													
Side Steps													
Corridor Room 321	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 331 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Central Staircase													
Corridor Room 322 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 334 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Side Steps													
Corridor Room 324	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Facade of Building													
Corridor Office 20/8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Behind the Building													
Corridor Office 20/5-8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			

Remark;

[☒] Normal

[☐] Abnormal

Loss Prevention Check

Room Division Manager

P. V 21/11/23

30/11/23

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building D

Monthly..11/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building D													
Side Steps													
Corridor Room 421	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	17/11/23	Santichai			
Corridor Room 431	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	17/11/23	Santichai			
Central Staircase													
Corridor Room 422	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 434	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Side Steps													
Corridor Room 424	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 437	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Facade of Building													
Corridor Office 20/12	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Behind the Building													
Corridor Office 20/9-12 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			

Remark:

[✓] Normal

[X] Abnormal

Loss Prevention Check

Room Division Manager

P. V. 21/11/2023

[Signature]
20/11/23

NH

BOAT LAGOON
PHUKET RESORT

NH BOAT LAGOON PHUKET RESORT Check List Fire Extinguisher Building E

Monthly..11/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building E													
Side Steps													
Corridor Room 521	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	17/11/23	Santichai			
Corridor Room 531	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	17/11/23	Santichai			
Central Staircase													
Corridor Room 522	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 534	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Side Steps													
Corridor Room 524	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 537	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Facade of Building													
Corridor Office 20/16	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Behind the Building													
Corridor Office 20/13-16 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			

Remark:

[✓] Normal

[X] Abnormal

Loss Prevention Check

20/11/23

Room Division Manager

P. K. 2/12/2023

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building F

Monthly..11/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building F													
Side Steps													
Corridor Room 621	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 631	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Central Staircase													
Corridor Room 623	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 633	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Side Steps													
Corridor Room 624	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 637	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Facade of Building													
Corridor Office 20/20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Behind the Building													
Corridor Office 20/17-20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			

Remark;

[☒] Normal

[☐] Abnormal

Loss Prevention Check

[Signature]
30/11/23

Room Division Manager

[Signature]

03/12/2023

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building G

Monthly..11/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building G													
Side Steps													
Corridor Room 721	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 731	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Central Staircase													
Corridor Room 722	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 733	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Side Steps													
Corridor Room 724	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Corridor Room 737	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Facade of Building													
Corridor Office 20/24	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			
Behind the Building													
Corridor Office 20/21-24 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	17/11/23	Santichai			

Remark;

[☒] Normal

[☐] Abnormal

Loss Prevention Check

Room Division Manager

02/12/2023

[Signature]
02/11/23

P. [Signature]

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Hotel Wing Floor 1, Restaurant, Lobby

Monthly..11/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
FLOOR 1													
Loading x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Accounting Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Female Locker	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Canteen Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Main Kitchen x4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Electrical Control Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Captain Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Lift Main Kitchen x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Bai-Ruer Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Baot Point Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Loss Prevention Office	NON-CFC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

Room Division Manager

02/12/2023

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Hotel Wing FLOOR 2,3

Monthly..11/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
FLOOR 2													
Corridor Room 242	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 250	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 256	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 264	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 272	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
FLOOR 3													
Corridor Room 342	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 348	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 352	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
CorridorRoom 358	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 364	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 372	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 380	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			

Remark;

[☒] Normal

[☐] Abnormal

Loss Prevention Check

Room Division Manager

02/12/2023

[Signature]
02/12/23

[Signature]

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Hotel Wing FLOOR 4

Monthly..11/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
FLOOR 4													
Corridor Room 442	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 448	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 454	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 460	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 466	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 474	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			
Corridor Room 482	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	11/11/2023	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

Room Division Manager

P. Ya

02/12/2023

[Signature]
30/11/23

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by W. J. S. M. Date 7/11/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by emsa Date 2/11/23

Supervisor byDate.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date 2/1/23.....

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

[illegible]

Note: Mark $[\sqrt{\quad}]$ Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date..... 2/11/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date..... 2/11/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by: emsa Date: 2/11/25

Supervisor byDate.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date 2/11/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

[illegible]

Note: Mark $[\sqrt{\quad}]$ Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date.....

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date.....

Supervisor byDate.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by gmsw Date 2/11/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 241 (Fire Exit)	/	/	/	/	/	2/11/23	สมิทธิ์	/			
Room 241 (Emergency)	/	/	/	/	/			/			
Room 246 (Fire Exit)	/	/	/	/	/			/			
Room 246 (Emergency)	/	/	/	/	/			/			
Room 252 (Fire Exit)	/	/	/	/	/			/			
Room 252 (Emergency)	/	/	/	/	/			/			
Room 263 (Fire Exit)	/	/	/	/	/			/			
Room 263 (Emergency)	/	/	/	/	/			/			
Room 269 (Fire Exit)	/	/	/	/	/			/			
Room 269 (Emergency)	/	/	/	/	/			/			
Room 274 (Fire Exit)	/	/	/	/	/			/			
Room 274 (Emergency)	/	/	/	/	/			/			

Note: Mark [✓] Normal

Mark (X) Abnormal

Responsible by 2/11/23 Date.....

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

Mark (X) Abnormal

Responsible by Engr. S. S. S. Date: 24/11/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Nov-23

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 441 (Fire Exit)	✓	✓	✓	✓	✓	2/11/23	สมชาย	✓			
Room 441 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 446 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 446 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 456 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 456 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 462 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 462 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 473 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 473 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 479 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 479 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 484 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 484 (Emergency)	✓	✓	✓	✓	✓			✓			

Note: Mark [✓] Normal

Mark (X) Abnormal

Responsible byสมชาย.....Date 2/11/23

Supervisor byDate.....

โศกนาฏกรรม

18/11/66



ตารางตรวจสอบเช็คสัญญาณ TV

ลำดับ	ชื่อรายการช่องสัญญาณ	วันที่	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
1	hotel information		X																														
2	HBO																																
3	Live Sky Lotus																																
4	BBC																																
5	CNN																																
6	TV 5 MONDE																																
7	DW English																																
8	France 24																																
9	NHK world Japan																																
10	sky sports 2																																
11	Dubai sports 1																																
12	Sky Sports 1																																
13	Channel V																																
14	NGO																																
15	Al Jazeera English HD																																
16	TRT World HD																																
17	B4U Movies India																																
18	Filmax																																
19	xing kong จีน																																
20	Yemen TV																																
21	TV5 (ไทย)																																
22	Nation (ไทย)																																
23	Work Point (ไทย)																																
24	True4U (ไทย)																																
25	GMM (ไทย)																																
26	Thai PBS (ไทย)																																
27	CH 8 (ไทย)																																
28	TNN 24 (ไทย)																																
29	Mono 29 (ไทย)																																
30	MCOT (ไทย)																																
31	ONE (ไทย)																																
32	Thairath (ไทย)																																
33	TV3HD (ไทย)																																
34	Amarin (ไทย)																																
35	TV7HD (ไทย)																																
36	PPTV (ไทย)																																
37	NBT (ไทย)																																
38	JKN (ไทย)																																
39	Cvi																																

Signature
16/11/2014

ปริมาณการใช้ไฟฟ้าและสารเคมีของระบบบำบัดน้ำเสีย ประจำเดือน พฤศจิกายน 66

Marina wing

ว/ค/ป	เลขมิเตอร์ไฟเติมอากาศ บ่อบำบัดน้ำเสีย		ปริมาณการใช้ไฟฟ้า ของระบบบำบัดน้ำเสีย (หน่วย)	ปริมาณสารเคมีหรือ สารสกัดชีวภาพที่ใช้ (กิโลกรัม)
	ก่อน	หลัง		
01/11/66	30760	30790		-
02/11/66	30790	30821		-
03/11/66	30821	30850		-
04/11/66	30850	30881		-
05/11/66	30881	30909		-
06/11/66	30909	30938		-
07/11/66	30938	30968		-
08/11/66	30968	30990		-
09/11/66	30990	31029		-
10/11/66	31029	31059		-
11/11/66	31059	31088		-
12/11/66	31088	31118		-
13/11/66	31118	31148		-
14/11/66	31148	31178		-
15/11/66	31178	31208		-
16/11/66	31208	31239		-
17/11/66	31239	31269		-
18/11/66	31269	31298		-
19/11/66	31298	31333		-
20/11/66	31333	31358		-
21/11/66	31358	31388		-
22/11/66	31388	31418		-
23/11/66	31418	31448		-
24/11/66	31448	31479		-
25/11/66	31479	31508		-
26/11/66	31508	31540		-
27/11/66	31540	31569		-
28/11/66	31569	31600		-
29/11/66	31600	31631		-
30/11/66	31631	31662		-
01/12/66	31662	31691		-
รวม				

*Stamp missing
✓ 30/11/66*

BOAT LAGOON

Clean Air Rooms

Updated 25/6/2024

FLOOR 1+2+3

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
140	FS2B				240	LS				258	DLX				340	LS			
141	FS2B				241	DLX				259	DLX				341	DLX			
142	FS2B				242	DLX				260	DLX				342	DLX			
143	FS2B				243	DLX				261	DLX				343	DLX			
144	FS2B				244	DLX				262	DLX				344	DLX			
145	FS2B				245	DLX				263	DLX				345	DLX			
146	FS2B				246	FDL				264	DLX				346	DLX			
147	FS2B				247	DLX				265	DLX				347	DLX			
148	FS2B				248	DLX				266	DLX				348	DLX			
					249	DLX				267	DLX				349	DLX			
					250	DLX				268	DLX				350	DLX			
					251	DLX				269	DLX				351	DLX			
					252	DLX				270	DLX				352	DLX			
					253	DLX				271	DLX				353	DLX			
					254	DLX				272	DLX				354	DLX			
					255	DLX				273	DLX				355	DLX			
					256	DLX				274	DLX				356	DLX			
					257	DLX				275	LS				357	DLX			
9					18					18					18				0

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
376	DLX								
377	DLX								
378	DLX								
379	DLX								
380	DLX								
381	DLX								
382	DLX								
383	LS								
8									0

FS2B=Family suite 2 beds LS=Logoon Su DLX PLS PD PLD PMS

Summary Clean Air Rooms of FLOOR 1+2+3

Total Rooms	89	Rooms
Total Clean Air Rms	0	Rooms
Clean Air Rooms	0	Rooms
The rest	0	Rooms
Done	0	Rooms
1 Easy	0	Rooms
2 Medium	0	Rooms
3 Hard	0	Rooms

HOTEL WING FLOOR 4+RESORT A+B

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
440	LS				454	DLX				468	DLX				482	LS			
441	DLX				455	DLX				469	DLX				483	LS			
442	DLX				456	DLX				470	DLX				484	LS			
443	DLX	✓	15/11/66		457	DLX				471	DLX				485	LS			
444	DLX	✓	15/11/66		458	DLX				472	DLX								
445	DLX	✓	15/11/66		459	DLX				473	DLX								
446	DLX				460	DLX				474	DLX								
447	DLX				461	DLX				475	DLX								
448	DLX				462	DLX				476	DLX								
449	DLX				463	DLX				477	DLX								
450	DLX				464	DLX				478	DLX								
451	DLX				465	DLX				479	DLX								
452	DLX				466	DLX				480	DLX								
453	DLX				467	DLX				481	DLX								
14		0	0	0	0	14		0	0	14		0	0	0	4		0	0	0

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
138	PLP				236	PLD			
221	PLS				237	PD			
222	PLS				238	PLP			
223	PLS								
224	PLS								
225	PD								
226	PD								
227	PH								
228	x								
231	PD								
232	PLD								
233	PD								
234	PLS								
235	PD								
14		0	0	0	0	3		0	0

Summary Clean Air Rooms FLOOR 4 +Resort A+B

Total Rooms	77	Rooms
Total Defective Rms	0	Rooms
Repaired Rooms	14	Rooms
The rest	-14	Rooms
Done	14	Rooms
1 Easy	0	Rooms
2 Medium	0	Rooms
3 Hard	0	Rooms

RESORT C+D+E+F+G+H+I

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
321	PLS	✓	21/11/66	OK	421	PLS				537	SUP				635	PD			
322	PLS	✓	21/11/66	OK	422	PLS				538	PLD				636	PLD			
323	PLS	✓	21/11/66	OK	423	PLS				541	SUP				637	PD			
324	PLS	✓	21/11/66	OK	424	PLS				542	SUP				638	PLD			
325	PD	✓	21/11/66	OK	425	PD				621	PLS				641	PH			
326	PD	✓	21/11/66	OK	426	PD				622	PLS				642	PH			
331	PD	✓	21/11/66	OK	427	PH				623	PLS				721	PLS			
332	PLD	✓	21/11/66	OK	428	PH				624	PLS				722	PLS			
333	PD	✓	21/11/66	OK	431	PD				625	PD				723	PLS			
334	PLD	✓	21/11/66	OK	432	PLD				626	PD				724	PLS			
335	PD	✓	21/11/66	OK	433	PD				631	PD				725	PD			
336	PLD	✓	21/11/66	OK	434	PLD				632	PLS				726	PD			
337	PD	✓	21/11/66	OK	435	PD				633	PD				731	PD			
338	PLD	✓	21/11/66	OK	436	PLD				634	PLD				732	PLD			

14 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0


Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
733	PD				939	PLD	✓	19/11/66	OK	932	PD	✓	19/11/66	OK
734	PLD				940	PD	✓	19/11/66	OK	933	PLD	✓	19/11/66	OK
735	PD				941	PLD	✓	19/11/66	OK	934	PD	✓	19/11/66	OK
736	PLD				942	PD	✓	19/11/66	OK	935	PLD	✓	19/11/66	OK
737	PD				943	PLD	✓	19/11/66	OK	936	PD	✓	19/11/66	OK
738	PLD				944	PD	✓	19/11/66	OK	937	PLD	✓	19/11/66	OK
741	PH				945	PLD	✓	19/11/66	OK	938	PLD	✓	19/11/66	OK
742	PH				946	PD	✓	19/11/66	OK	948	PH	✓	19/11/66	OK
925	PMS	✓	19/11/66	OK	949	PH	✓	19/11/66	OK	8		0	0	0
926	PMS	✓	19/11/66	OK	921	PMS	✓	19/11/66	OK					
927	PMS	✓	19/11/66	OK	922	PMS	✓	19/11/66	OK					
928	PMS	✓	19/11/66	OK	923	PMS	✓	19/11/66	OK					
929	PMS	✓	19/11/66	OK	924	PMS	✓	19/11/66	OK					
930	PMS	✓	19/11/66	OK	931	PLD	✓	19/11/66	OK					

14 0 0 0 0 0 0 0 0 0 0 0 0 0 0


Summary Clean Air Rooms of RESORT C+D+E+F+G+H+I


Total Rooms	106	Rooms
Total Defective Rms	0	Rooms
Repaired Rooms	0	Rooms
The rest	0	Rooms
Done	0	Rooms
1 Easy	0	Rooms
2 Medium	0	Rooms
3 Hard	0	Rooms





ช่างคอมแอร์ ๒๕๖๐๕ 443-445 15/11/66





TEST RUN RECORD FOR EMERGENCY GENERATOR

DATE 15/12/66 ENGINEER สุวิทย์ / วัฒนวิทย์
 GENERATOR 500 KVA LOCATION

สภาพเครื่องก่อน TEST RUN

- ☒ ระดับน้ำมันเครื่อง (Motor Oil)
- ☒ สภาพสายพาน (Machine Belt)
- ☒ ระดับน้ำในหม้อน้ำ (Boiler)
- ☒ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

TEST RUN


☐ ON LOAD ☒ OFF LOAD

TIME START 14.30 TIME STOP 15.30

รายการตรวจเช็ค		บันทึก
Oil (L.)		60%
Voltage (V)	L1	399
Voltage (V)	L2	-
Voltage (V)	L3	400
Coolant Temp (°C)		-
Oil Pressure (bar)		-
Speed (RPM)		-
Frequency (Hz)		-
Battery (V)		-
Run Time (h)		-

REMARK

- น้ำมันเครื่อง, เริ่มใช้ตัว
 - ดับสวิทช์น้ำมัน (ปั๊ม)
 - เครื่อง พร้อม ทดสอบ 15 นาทีแรก



รายการดูเช็ค	วันที่																															ผู้ตรวจ	
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31		
1. ดูเขี้ยวห้องเซฟ 1 (0-2 องศา)	-11	-13	-11	-10	-12	-10	-2	-17	-11	-14	-8	-8	-10	-16	-10	-4	-16	-18	-14	-15	-10	-10	-5	-19	-14	-12	-1	-7	-5	-11	-12		
ดูเขี้ยวห้องเซฟ 2 (0-2 องศา)	-5	-6	-7	-10	-5	-7	-2	-3	-6	-7	-5	-9	-9	-5	-2	2	-3	-4	-5	-6	-7	-4	-1	-8	-9	-6	-13	-4	4	1	3		
2. ครีวเบเกอร์รี 1 ดูแฟรสิ (-20 องศา)	-7	-8	-6	-6	-7	-6	-7	-7	-5	-9	-6	-13	-7	-10	-2	-3	-3	-10	-9	-10	-11	-10	-10	-10	-11	-9	-14	-9	-7	-5	-3		
3. ดูเขี้ยวเบเกอร์รี 2 (2-5 องศา)	5	3	4	6	6	6	12	6	6	8	9	4	8	4	6	12	6	12	4	9	11	4	10	4	7	12	1	7	6	10	12		
4. ดูเขี้ยวเบเกอร์รี 3 (2-5 องศา)	8	7	6	6	6	6	8	8	15	9	11	6	5	11	9	5	9	8	4	13	7	5	7	7	7	7	9	4	9	7	12	10	
5. ดูเขี้ยวปีก/เขี้ยว (15-20 องศา)	13	12	11	10	10	12	15	12	13	-2	14	2	8	20	12	11	14	12	13	11	13	11	13	9	9	9	7	11	10	14	15		
6. ดูเขี้ยวโรไทย 1 (1C-5 องศา)	13	13	11	9	11	13	12	7	8	-12	6	10	8	9	9	11	8	7	7	13	4	5	5	6	11	3	10	4	10	7	12		
7. ดูเขี้ยวโรไทย 2 (1C-5 องศา)	11	11	11	7	7	11	3	7	9	5	7	11	7	8	6	7	10	9	5	4	7	7	9	5	11	5	13	7	5	8	8		
8. ห่องเย็นครีวแมน (1-3 องศา)	13	9	9	15	9	9	14	6	7	9	9	14	10	10	12	2	8	10	7	4	4	11	7	7	7	7	7	7	9	13	17		
9. ดูเขี้ยวครีวแมน 1 (2-5 องศา)	8	7	7	5	6	7	5	2	6	9	8	14	9	11	8	1	7	10	11	9	8	7	7	6	11	3	4	7	6	8	10		
10. ดูเขี้ยวครีวแมน 2 (2-5 องศา)	10	9	7	5	6	9	13	8	6	9	10	11	11	6	8	2	4	4	2	9	8	7	8	7	15	5	8	5	5	7	10		
11. ดูเขี้ยวครีวแมน 1 (2-5 องศา)	5	3	3	3	4	3	3	5	7	4	7	9	8	5	1	2	6	6	1	7	7	5	11	3	6	3	1	5	4	8	11		
12. ดูเขี้ยวครีวแมน 2 (2-5 องศา)	16	13	14	9	10	5	3	9	10	12	17	9	15	11	9	9	11	11	9	16	14	14	10	10	9	5	4	3	7	8	6		
13. ดูเขี้ยวเฟรนฟรายครีวยุโรป (0-2 องศา)	-8	-7	-6	-11	-10	-8	-6	14	-6	-8	-4	-2	-9	5	0	-3	-8	-12	-8	-11	-9	-4	-2	-1	-4	-6	-12	-12	0	-6	-2		
14. ครีวยุโรป 1 (2-5 องศา)	3	3	5	7	6	3	3	9	5	-6	5	6	6	5	11	3	3	4	5	5	4	6	6	6	-12	6	6	6	5	9	8		
15. ดูเขี้ยวเฟรนฟรายครีวยุโรป 2 (-15-20 องศา)	-8	-7	7	0	-9	-6	-8	-9	-5	-7	-6	-9	-4	-5	-8	5	-1	-9	-8	-13	-9	-6	-6	-4	-1	-12	-12	-13	-11	-8	-9		
16. ดูเขี้ยวครีวยุโรป 3 (2-5 องศา)	5	5	5	5	5	5	4	6	6	6	4	6	7	4	6	6	7	5	6	6	6	7	4	6	6	6	5	4	4	7	7		
17. ดูเขี้ยวครีวยุโรป 4 (2-5 องศา)	0	0	0	8	0	0	2	3	8	0	2	7	3	9	7	3	10	6	7	7	5	11	4	7	1	1	3	4	5	7	8		
18. ดูเขี้ยวเฟรนฟรายครีวยุโรป 5 (-2-0 องศา)	-1	-3	-4	-1	-5	-14	-2	-14	-14	-17	-4	-6	-12	-16	-11	-8	-12	-13	-13	-13	-13	-13	-1	-15	-18	-0	-5	-3	-12	1			

ตารางตรวจเช็คสัญญาณTV

ลำดับ	ชื่อรายการช่องสัญญาณ	วันที่																														
1	hotel information	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
2	HBO	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	Live Sky	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	BBC	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	CNN	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	TV 5 MONDE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	DW English	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	France 24	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	NHK world Japan	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
10	sky sports 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
11	Dubai sports 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
12	Sky Sports 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
13	Channel V	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
14	NGO	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
15	AI Jazeera English HD	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
16	TRT World HD	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
17	B4U Movies India	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
18	Filmax	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
19	xing kong จีน	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
20	Yemen TV	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
21	TV5 (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
22	Nation (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
23	Work Point(ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
24	True4U (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
25	GMM (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
26	Thai PBS (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
27	CH 8 (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
28	TNN 24 (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
29	Mono 29 (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
30	MCOT (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
31	ONE (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
32	Thairath (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
33	TV3HD (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
34	Amarin (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
35	TV7HD (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
36	PPTV (ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
37	NBT(ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
38	JKN(ไทย)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
39	Cvi	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓

1/12/2562
 2/12/2562
 3/12/2562
 4/12/2562
 5/12/2562
 6/12/2562
 7/12/2562
 8/12/2562
 9/12/2562
 10/12/2562
 11/12/2562
 12/12/2562
 13/12/2562
 14/12/2562
 15/12/2562
 16/12/2562
 17/12/2562
 18/12/2562
 19/12/2562
 20/12/2562
 21/12/2562
 22/12/2562
 23/12/2562
 24/12/2562
 25/12/2562
 26/12/2562
 27/12/2562
 28/12/2562
 29/12/2562
 30/12/2562
 31/12/2562

ปริมาณการใช้ไฟฟ้าและสารเคมีของระบบบำบัดน้ำเสีย ประจำเดือน ธันวาคม 66

Marina wing

ว/ด/ป	เลขมิเตอร์ไฟเดิมอากาศ บ่อบำบัดน้ำเสีย		ปริมาณการใช้ไฟฟ้า ของระบบบำบัดน้ำเสีย (หน่วย)	ปริมาณสารเคมีหรือ สารสกัดชีวภาพที่ใช้ (กิโลกรัม)
	ก่อน	หลัง		
01/12/66	31662	31691	0	-
02/12/66	31691	31721	0	-
03/12/66	31721	31752	0	-
04/12/66	31752	31783	0	-
05/12/66	31783	31812	0	-
06/12/66	31812	31842	0	-
07/12/66	31842	31873	0	-
08/12/66	31873	31904	0	-
09/12/66	31904	31933	0	-
10/12/66	31933	31964	0	-
11/12/66	31964	31993	0	-
12/12/66	31993	32023	0	-
13/12/66	32023	32053	0	-
14/12/66	32053	32084	0	-
15/12/66	32084	32115	0	-
16/12/66	32115	32145	0	-
17/12/66	32145	32175	0	-
18/12/66	32175	32207	0	-
19/12/66	32207	32236	0	-
20/12/66	32236	32264	0	-
21/12/66	32264	32295	0	-
22/12/66	32295	32325	0	-
23/12/66	32325	32356	0	-
24/12/66	32356	32387	0	-
25/12/66	32387	32417	0	-
26/12/66	32417	32448	0	-
27/12/66	32448	32478	0	-
28/12/66	32478	32508	0	-
29/12/66	32508	32539	0	-
30/12/66	32539	32579	0	-
31/12/66	32579	32609	0	-
รวม			0	0



ATOM CHEMTECH CO., LTD.

รายงานการบริการขัดสระว่ายน้ำ

วันที่

เวลา

8/12/66

21:00 ชม.

เรียน

โรงแรม

โรงแรมเชียงใหม่

มท. 12

อ.

บริษัท อะตอม เคมีเทค จำกัด ได้จัดส่งเจ้าหน้าที่เข้ามาทำการปฏิบัติงานขัดสระน้ำในสระ
ว่ายน้ำของโรงแรมและ เติมน้ำป้องกันตะไคร่น้ำพิเศษ เป็นการบริการเพิ่มเติมสำหรับโรงแรมลูกค้าที่ใช้
บริการผลิตภัณฑ์ **MASTERCHLO - A** และ **EXTRA - CLEAR** ในระบบบำบัดน้ำสระว่ายน้ำของ
บริษัทฯ โดยไม่มีการคิดค่าใช้จ่ายใดๆทั้งสิ้น

สระว่ายน้ำ

สระน้ำ

สารป้องกันตะไคร่น้ำที่ใช้เติม

1.

จำนวนที่เติม

กก.

2.

จำนวนที่เติม

กก.

ขอแสดงความนับถือ

บริษัท อะตอม เคมีเทค จำกัด

ผู้ปฏิบัติงาน

เจ้าหน้าที่โรงแรม

อ. - อ. - อ.

อ. - อ.

ATOM CHEMTECH CO., LTD

65/14 MOO. 1 Tambol Kohkaew, Amphur Muang, Phuket 83000 Thailand Tel. 076 - 377855, (085)8880036,

BOAT LAGOON

AIR CONDITION CLEAN FILTERS/P.M.

FLOOR 1+2+3

Updated 2566

24/02/2024

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
140	FS2B				240	LS				258	DLX				340	LS				358	DLX			
141	FS2B				241	DLX				259	DLX				341	DLX				359	DLX			
142	FS2B				242	DLX				260	DLX				342	DLX				360	DLX			
143	FS2B				243	DLX				261	DLX				343	DLX				361	DLX			
144	FS2B				244	DLX				262	DLX				344	DLX				362	DLX			
145	FS2B				245	DLX				263	DLX				345	DLX				363	DLX			
146	FS2B				246	FDL				264	DLX				346	DLX				364	DLX			
147	FS2B				247	DLX				265	DLX				347	DLX				365	DLX			
148	FS2B				248	DLX				266	DLX				348	DLX				366	DLX			
					249	DLX				267	DLX				349	DLX				367	DLX			
					250	DLX				268	DLX				350	DLX				368	DLX			
					251	DLX				269	DLX				351	DLX				369	DLX			
					252	DLX				270	DLX				352	DLX				370	DLX			
					253	DLX				271	DLX				353	DLX				371	DLX			
					254	DLX				272	DLX				354	DLX				372	DLX			
					255	DLX				273	DLX				355	DLX				373	DLX			
					256	DLX				274	DLX				356	DLX				374	DLX			
					257	DLX				275	LS				357	DLX				375	DLX			
9		0	0	0	0	18			0	18		0	0	0	0	18			0	18		0	0	0

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
376	DLX								
377	DLX								
378	DLX								
379	DLX								
380	DLX								
381	DLX								
382	DLX								
383	LS								
8		0	0	0	0	0	0	0	0


FS2B=Family suite 2 beds

LS=Lagoon SL DLX PLS

PLD PMS

Summary Clean Air Rooms of FLOOR 1+2+3

Total Rooms	89	Rooms
Total Clean Air Rms	0	Rooms
Clean Air Rooms	0	Rooms
The rest	0	Rooms
Done	0	Rooms
Easy	0	Rooms
Medium	0	Rooms
Hard	0	Rooms




RESORT C+D+E+F+G+H+I

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
321	PLS				421	PLS				437	PD				537	SUP			
322	PLS				422	PLS				438	PLD				538	PLD			
323	PLS				423	PLS				521	PLS				541	SUP			
324	PLS				424	PLS				522	PLS				542	SUP			
325	PD				425	PD				523	PLS				621	PLS			
326	PD				426	PD				524	PLS				622	PLS			
331	PD				427	PH				525	PD				623	PLS			
332	PLD				428	PH				526	PD				624	PLS			
333	PD				431	PD				531	PD				625	PD			
334	PLD				432	PLD				532	PLD				626	PD			
335	PD				433	PD				533	PD				631	PD			
336	PLD				434	PLD				534	PLD				632	PLS			
337	PD				435	PD				535	PD				633	PD			
338	PLD				436	PLD				536	PLD				634	PLD			
14	0	0	0	0	14	0	0	0	0	14	0	0	0	0	14	0	0	0	0

Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC	Room No.	Rm Type	Room Status	Working Date	QC
733	PD				939	PLD				932	PD			
734	PLD				940	PD				933	PLD			
735	PD				941	PLD				934	PD			
736	PLD				942	PD				935	PLD			
737	PD				943	PLD				936	PD			
738	PLD				944	PD				937	PLD			
741	PH				945	PLD				938	PLD			
742	PH				946	PD				948	PH			
925	PMS				949	PH				8		0	0	0
926	PMS				921	PMS								
927	PMS				922	PMS								
928	PMS				923	PMS								
929	PMS				924	PMS								
930	PMS				931	PLD								
14	0	0	0	0	14	0	0	0	0	14	0	0	0	0

Summary Clean Air Rooms of RESORT C+D+E+F+G+H+I

Total Rooms	106	Rooms
Total Defective Rms	0	Rooms
Repaired Rooms	0	Rooms
The rest	0	Rooms
Done	0	Rooms
Easy	0	Rooms
2 Medium	0	Rooms
3 Hard	0	Rooms



NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Dec-23

[illegible]

Note: Mark $[\sqrt{\quad}]$ Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by W. J. W. S. Date 6/12/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Dec-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by W. W. W. Date 6/12/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Dec-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date 6/12/27

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Dec-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Ujwal Date 6/12/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Dec-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Date..... 6/10/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Dec-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by 6/12/23 Date.....

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Dec-23

[illegible]

Note: Mark [$\sqrt{\quad}$] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Wing Date 6/12/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Dec-23

[illegible]

Note: Mark $[\sqrt{\quad}]$ Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible byking..... Date: 6/12/23.....

Supervisor byDate.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Dec-23

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 241 (Fire Exit)	✓	✓	✓	✓	✓	6/12/23	6/12/23	✓			
Room 241 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 246 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 246 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 252 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 252 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 263 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 263 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 269 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 269 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 274 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 274 (Emergency)	✓	✓	✓	✓	✓			✓			

Note: Mark [✓] Normal

Mark (X) Abnormal

Responsible by 6/12/23 Date.....

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Dec-23

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 341 (Fire Exit)	✓	✓	✓	✓	✓	6/12/23	WINS	✓			
Room 341 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 346 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 346 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 355 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 355 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 360 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 360 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 371 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 371 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 377 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 377 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 382 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 382 (Emergency)	✓	✓	✓	✓	✓			✓			

Note: Mark [✓] Normal

Mark (X) Abnormal

Responsible by WINS Date 6/12/23

Supervisor by Date.....

NH BOAT LAGOON PHUKET RESORT

Check List emergency light

Dec-23

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 441 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 441 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 446 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 446 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 456 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 456 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 462 (Fire Exit)	✓	✓	✓	✓	✓	6/12/23	๒๖๓๔๕	✓			
Room 462 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 473 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 473 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 479 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 479 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 484 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 484 (Emergency)	✓	✓	✓	✓	✓			✓			

Note:Mark [✓] Normal

Mark (X) Abnormal

Responsible by๒๖๓๔๕.....Date:6/12/23

Supervisor byDate:.....

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building A

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building A													
Side Steps													
Corridor Room 121	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 131	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Central Staircase													
Corridor Room 122	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Side Steps													
Corridor Room 124	NON-CFC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	21/12/23	Santichai			
Corridor Room 137	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	21/12/23	Santichai			
Facade of Building													
Corridor Room A21	NON-CFC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Behind the Building													
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			

Remark;

[☒] Normal

[☒] Abnormal

Loss Prevention Check

Front Office Manager

P. J. 08/11/2023

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building B

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building B													
Side Steps													
Corridor Room 221	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 231	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Central Staircase													
Corridor Room 222 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 233 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Side Steps													
Corridor Room 224	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
CorridorRoom 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Facade of Building													
Corridor Office 20/4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Behind the Building													
Corridor Office 20/1-4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

Front Office Manager




NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building C

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building C													
Side Steps													
Corridor Room 321	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 331 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Central Staircase													
Corridor Room 322 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 334 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Side Steps													
Corridor Room 324	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Facade of Building													
Corridor Office 20/8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Behind the Building													
Corridor Office 20/5-8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

Front Office Manager

P. V.

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building D

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building D													
Side Steps													
Corridor Room 421	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	21/12/23	Santichai			
Corridor Room 431	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	21/12/23	Santichai			
Central Staircase													
Corridor Room 422	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 434	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Side Steps													
Corridor Room 424	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 437	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Facade of Building													
Corridor Office 20/12	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Behind the Building													
Corridor Office 20/9-12 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			

Remark:

[✓] Normal

[X] Abnormal

Loss Prevention Check

Front Office Manager

P. J.

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building E

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building E													
Side Steps													
Corridor Room 521	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	21/12/23	Santichai			
Corridor Room 531	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	21/12/23	Santichai			
Central Staircase													
Corridor Room 522	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 534	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Side Steps													
Corridor Room 524	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 537	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Facade of Building													
Corridor Office 20/16	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Behind the Building													
Corridor Office 20/13-16 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			

Remark:

[☒] Normal

[☐] Abnormal

Loss Prevention Check

Front Office Manager

P. J.

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building F

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building F													
Side Steps													
Corridor Room 621	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 631	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Central Staircase													
Corridor Room 623	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 633	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Side Steps													
Corridor Room 624	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 637	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Facade of Building													
Corridor Office 20/20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Behind the Building													
Corridor Office 20/17-20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			

Remark;

[☒] Normal

[☒] Abnormal

Loss Prevention Check

Front Office Manager

P. J.

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Building G

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building G													
Side Steps													
Corridor Room 721	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 731	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Central Staircase													
Corridor Room 722	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 733	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Side Steps													
Corridor Room 724	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Corridor Room 737	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Facade of Building													
Corridor Office 20/24	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			
Behind the Building													
Corridor Office 20/21-24 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	21/12/23	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

Front Office Manager

P. J.



BOAT LAGOON
PHUKET RESORT

NH BOAT LAGOON PHUKET RESORT

Check List Fire Extinguisher Building G

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building H													
Side Steps													
Corridor Room 925	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			
Corridor Room 933	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			
Side Steps													
Corridor Room 924	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			
Corridor Room 927	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			
Facade of Building													
Corridor Office 20/26	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			
Behind the Building													
Corridor Office 20/25-26 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

Front Office Manager

P. J.

NH

BOAT LAGOON
PHUKET RESORT

NH BOAT LAGOON PHUKET RESORT Check List Fire Extinguisher Building G

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building 1													
Side Steps													
Corridor Room 923	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			
Corridor Room 935	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			
Side Steps													
Corridor Room 936	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			
Corridor Room 949	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			
Facade of Building													
Corridor Office 20/27	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			
Behind the Building													
Corridor Office 20/26-27 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/12/23	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

Front Office Manager

P. J.

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Hotel Wing Floor 1, Restaurant, Lobby

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
FLOOR 1													
Loading x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Accounting Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Female Locker	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Canteen Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Main Kitchen x4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Electrical Control Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Captain Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Lift Main Kitchen x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Bai-Ruer Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Baot Point Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Loss Prevention Office	NON-CFC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

Front Office Manager

P. 72

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Hotel Wing FLOOR 2,3

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
FLOOR 2													
Corridor Room 242	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 250	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 256	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 264	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 272	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
FLOOR 3													
Corridor Room 342	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 348	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 352	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
CorridorRoom 358	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 364	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 372	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 380	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			

Remark;

[☒] Normal

[☒] Abnormal

Loss Prevention Check

Front Office Manager

P. J.

NH BOAT LAGOON PHUKET RESORT
Check List Fire Extinguisher Hotel Wing FLOOR 4

Monthly..12/2023

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
FLOOR 4													
Corridor Room 442	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 448	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 454	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 460	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 466	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 474	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			
Corridor Room 482	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	13/12/2023	Santichai			

Remark;

[☒] Normal

[☐] Abnormal

Loss Prevention Check

Front Office Manager

