

ผลการตรวจวัดคุณภาพอากาศภายในอาคาร

Report No. : 2023-500000353/001 (Page 1 of 5) Issued date: December 13, 2023

CLIENT : GRANDE ASSET HOTELS AND PROPERTY PUBLIC COMPANY LIMITED
CONTACT : Khun Suwit Polrachom
ADDRESS : 1 Soi Sukhumvit 13 (Sang Chan), Sukhumvit Road, Klongtoey Nue, Wattana, Bangkok 10110
 Tel.02-098-1262 Email: suwit.polrachom@hyatt.com

Analysis Report

SAMPLE DESIGNATED AS : Indoor Air Quality
SAMPLING LOCATION : Station #1 Lobby ชั้น 1

SAMPLING DATE: December 8, 2023

Parameters	Units	Results		Standard*	
		08:57 hrs.	15:02 hrs.	SS 554:2009	SS 554:2016
1. Temperature	°C	23.1	26.0	24.0 -26.0	23.0 -25.0
2. Relative Humidity	%RH	73.0	64.9	<70	<70
3. Carbon dioxide (CO ₂)	ppm	127 (530)	156 (559)	700 above outdoor	700 above outdoor
4. Carbon monoxide (CO)	ppm	0.0	0.0	<9	<9
5. Formaldehyde	ppm	0.00	0.00	<0.1	<0.08
6. Ozone	ppm	0.00	0.00	<0.1	<0.05
7. Total VOCs	ppm	0.00	0.00	<3	<1
8. Particulate matter less than 2.5 micron (PM-2.5)	µg/m ³	8.78	11.98	<35	<37.5
9. Particulate matter less than 10 micron (PM-10)	µg/m ³	14.33	20.81	<50	-
10. Total Bacteria (Airborne)	CFU/m ³	40		<500	<1,000
11. Yeast & Mold (Airborne)	CFU/m ³	Not Detected		<500	-

Remark: - Outdoor on December 8, 2023; Temperature is 29.2 °C, Relative Humidity is 66.5 %RH and Carbon dioxide is 403 ppm.
Source: * Code of Practice for Indoor air quality for air-conditioned building; Singapore Standard SS 554

Thepsan Y.
 (Thepsan Yommana)
 Technical Manager

SGS (THAILAND) LIMITED

TY/TT/PPT/PPT



This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

E 273029

Report No. : 2023-500000353/001 (Page 2 of 5) Issued date: December 13, 2023

CLIENT : GRANDE ASSET HOTELS AND PROPERTY PUBLIC COMPANY LIMITED
CONTACT : Khun Suwit Polrachom
ADDRESS : 1 Soi Sukhumvit 13 (Sang Chan), Sukhumvit Road, Klongtoey Nue, Wattana, Bangkok 10110
 Tel.02-098-1262 Email: suwit.polrachom@hyatt.com

Analysis Report

SAMPLE DESIGNATED AS : Indoor Air Quality

SAMPLING DATE: December 8, 2023

SAMPLING LOCATION : Station #2 Restaurant ชั้น 4

Parameters	Units	Results		Standard*	
		09:44 hrs.	14:32 hrs.	SS 554:2009	SS 554:2016
1. Temperature	°C	24.8	25.4	24.0 -26.0	23.0 -25.0
2. Relative Humidity	%RH	68.0	61.9	<70	<70
3. Carbon dioxide (CO ₂)	ppm	125 (528)	93 (496)	700 above outdoor	700 above outdoor
4. Carbon monoxide (CO)	ppm	0.0	0.0	<9	<9
5. Formaldehyde	ppm	0.00	0.00	<0.1	<0.08
6. Ozone	ppm	0.00	0.00	<0.1	<0.05
7. Total VOCs	ppm	0.00	0.00	<3	<1
8. Particulate matter less than 2.5 micron (PM-2.5)	µg/m ³	10.28	9.88	<35	<37.5
9. Particulate matter less than 10 micron (PM-10)	µg/m ³	12.53	17.32	<50	-
10. Total Bacteria (Airborne)	CFU/m ³	20		<500	<1,000
11. Yeast & Mold (Airborne)	CFU/m ³	20		<500	-

Remark: - Outdoor on December 8, 2023; Temperature is 29.2 °C, Relative Humidity is 66.5 %RH and Carbon dioxide is 403 ppm.

Source: * Code of Practice for Indoor air quality for air-conditioned building; Singapore Standard SS 554

Thepsan Y.
 (Thepsan Yommana)
 Technical Manager

SGS (THAILAND) LIMITED

TY/TT/PPT/PPT



This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

E 273030

Report No. : 2023-500000353/001 (Page 3 of 5) Issued date: December 13, 2023

CLIENT : GRANDE ASSET HOTELS AND PROPERTY PUBLIC COMPANY LIMITED
CONTACT : Khun Suwit Polrachom
ADDRESS : 1 Soi Sukhumvit 13 (Sang Chan), Sukhumvit Road, Klongtoey Nue, Wattana, Bangkok 10110
 Tel.02-098-1262 Email: suwit.polrachom@hyatt.com

Analysis Report

SAMPLE DESIGNATED AS : Indoor Air Quality

SAMPLING DATE: December 8, 2023

SAMPLING LOCATION : Station #3 Buffer line ชั้น 4

Parameters	Units	Results		Standard*	
		10:53 hrs.	14:38 hrs.	SS 554:2009	SS 554:2016
1. Temperature	°C	27.1	25.7	24.0 -26.0	23.0 -25.0
2. Relative Humidity	%RH	61.3	63.8	<70	<70
3. Carbon dioxide (CO ₂)	ppm	169 (572)	88 (491)	700 above outdoor	700 above outdoor
4. Carbon monoxide (CO)	ppm	0.0	0.0	<9	<9
5. Formaldehyde	ppm	0.00	0.00	<0.1	<0.08
6. Ozone	ppm	0.00	0.00	<0.1	<0.05
7. Total VOCs	ppm	0.00	0.00	<3	<1
8. Particulate matter less than 2.5 micron (PM-2.5)	µg/m ³	12.12	11.24	<35	<37.5
9. Particulate matter less than 10 micron (PM-10)	µg/m ³	16.32	14.96	<50	-
10. Total Bacteria (Airborne)	CFU/m ³	10		<500	<1,000
11. Yeast & Mold (Airborne)	CFU/m ³	Not Detected		<500	-

Remark: - Outdoor on December 8, 2023; Temperature is 29.2 °C, Relative Humidity is 66.5 %RH and Carbon dioxide is 403 ppm.

Source: * Code of Practice for Indoor air quality for air-conditioned building; Singapore Standard SS 554

TY/TT/PPT/PPT

SGS (THAILAND) LIMITED



Thepsan Y.
 (Thepsan Yommana)
 Technical Manager

This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

E 273031

Report No. : 2023-500000353/001 (Page 4 of 5) Issued date: December 13, 2023

CLIENT : GRANDE ASSET HOTELS AND PROPERTY PUBLIC COMPANY LIMITED
CONTACT : Khun Suwit Polrachom
ADDRESS : 1 Soi Sukhumvit 13 (Sang Chan), Sukhumvit Road, Klongtoey Nue, Wattana, Bangkok 10110
 Tel.02-098-1262 Email: suwit.polrachom@hyatt.com

Analysis Report

SAMPLE DESIGNATED AS : Indoor Air Quality

SAMPLING DATE: December 8, 2023

SAMPLING LOCATION : Station #4 Ballroom ชั้น 5

Parameters	Units	Results		Standard*	
		09:14 hrs.	14:44 hrs.	SS 554:2009	SS 554:2016
1. Temperature	°C	25.3	25.3	24.0 -26.0	23.0 -25.0
2. Relative Humidity	%RH	68.6	61.0	<70	<70
3. Carbon dioxide (CO ₂)	ppm	96 (499)	10 (413)	700 above outdoor	700 above outdoor
4. Carbon monoxide (CO)	ppm	0.0	0.0	<9	<9
5. Formaldehyde	ppm	0.00	0.00	<0.1	<0.08
6. Ozone	ppm	0.00	0.00	<0.1	<0.05
7. Total VOCs	ppm	0.00	0.00	<3	<1
8. Particulate matter less than 2.5 micron (PM-2.5)	µg/m ³	14.53	13.67	<35	<37.5
9. Particulate matter less than 10 micron (PM-10)	µg/m ³	27.78	21.37	<50	-
10. Total Bacteria (Airborne)	CFU/m ³	30		<500	<1,000
11. Yeast & Mold (Airborne)	CFU/m ³	Not Detected		<500	-

Remark: - Outdoor on December 8, 2023; Temperature is 29.2 °C, Relative Humidity is 66.5 %RH and Carbon dioxide is 403 ppm.

Source: * Code of Practice for Indoor air quality for air-conditioned building; Singapore Standard SS 554

TY/TT/PPT/PPT

SGS (THAILAND) LIMITED



Thepsan Y.
 (Thepsan Yommana)
 Technical Manager

This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

E 273032

Report No. : 2023-500000353/001 (Page 5 of 5) Issued date: December 13, 2023

CLIENT : GRANDE ASSET HOTELS AND PROPERTY PUBLIC COMPANY LIMITED
CONTACT : Khun Suwit Polrachom
ADDRESS : 1 Soi Sukhumvit 13 (Sang Chan), Sukhumvit Road, Klongtoey Nue, Wattana, Bangkok 10110
 Tel.02-098-1262 Email: suwit.polrachom@hyatt.com

Analysis Report

SAMPLE DESIGNATED AS : Indoor Air Quality
SAMPLING LOCATION : Station #5 ชั้น 27

SAMPLING DATE: December 8, 2023

Parameters	Units	Results		Standard*	
		09:29 hrs.	14:50 hrs.	SS 554:2009	SS 554:2016
1. Temperature	°C	25.2	24.5	24.0 -26.0	23.0 -25.0
2. Relative Humidity	%RH	71.4	74.6	<70	<70
3. Carbon dioxide (CO ₂)	ppm	162 (565)	15 (418)	700 above outdoor	700 above outdoor
4. Carbon monoxide (CO)	ppm	0.0	0.0	<9	<9
5. Formaldehyde	ppm	0.00	0.00	<0.1	<0.08
6. Ozone	ppm	0.00	0.00	<0.1	<0.05
7. Total VOCs	ppm	0.00	0.00	<3	<1
8. Particulate matter less than 2.5 micron (PM-2.5)	µg/m ³	22.04	14.98	<35	<37.5
9. Particulate matter less than 10 micron (PM-10)	µg/m ³	31.20	19.57	<50	-
10. Total Bacteria (Airborne)	CFU/m ³	20		<500	<1,000
11. Yeast & Mold (Airborne)	CFU/m ³	50		<500	-

Remark: - Outdoor on December 8, 2023; Temperature is 29.2 °C, Relative Humidity is 66.5 %RH and Carbon dioxide is 403 ppm.
Source: * Code of Practice for Indoor air quality for air-conditioned building; Singapore Standard SS 554

TY/TT/PPT/PPT

SGS (THAILAND) LIMITED



Thepsan Y.
 (Thepsan Yommana)
 Technical Manager

This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

E 273033