

เอกสารแนบ 6
ผลการตรวจวัดคุณภาพน้ำใช้

Analysis/Test Report

Customer Name : บริษัท จี แอนด์ พี แอสเซ็ท โฮลดิ้ง จำกัด

Address : 489 ถนนสุขุมวิท แขวงคลองเตยเหนือ เขตวัฒนา กรุงเทพมหานคร 10110

Sampling Site : Radisson Blu Plaza Bangkok

Sample Type : น้ำใช้

Sampling by : บริษัท เทสท์ เทค จำกัด

Sampling Method : Grab

Sampling Date : 05/02/2567

Sampling Time : 11:25 น.

Received Date : 05/02/2567

Analytical Date : 05 - 16/02/2567

Report Date : 19/02/2567

Report No. : R03976/67

| Parameters | Unit | Method | TW02832 /67 |
|------------------------|-------|------------------|------------------|
| | | | Underground Tank |
| <i>Legionella spp.</i> | CFU/L | ISO 11731 : 2017 | not detected |
| Sample Condition | | Observation | ใส |

Analyst

19/02/2567

Technical Manager

19/02/2567

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025

Analysis/Test Report

Customer Name : บริษัท จี แอนด์ พี แอสเซ็ท โฮลดิ้ง จำกัด

Address : 489 ถนนสุขุมวิท แขวงคลองเตยเหนือ เขตวัฒนา กรุงเทพมหานคร 10110

Sampling Site : Radisson Blu Plaza Bangkok

Sample Type : น้ำใช้

Sampling by : บริษัท เทสต์ เทค จำกัด

Sampling Method : Grab

Sampling Date : 05/02/2567

Sampling Time : 11:10 น.

Received Date : 05/02/2567

Analytical Date : 05 - 16/02/2567

Report Date : 19/02/2567

Report No. : R03977/67

| Parameters | Unit | Method | TW02833 /67 |
|------------------------|-------|------------------|---------------------|
| | | | Guest Room (1920) |
| <i>Legionella spp.</i> | CFU/L | ISO 11731 : 2017 | not detected |
| Sample Condition | | Observation | ใส |

Analyst

19/02/2567

Technical Manager

19/02/2567

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025

Analysis/Test Report

Customer Name : บริษัท จี แอนด์ พี แอสเซ็ท โฮลดิ้ง จำกัด

Address : 489 ถนนสุขุมวิท แขวงคลองเตยเหนือ เขตวัฒนา กรุงเทพมหานคร 10110

Sampling Site : Radisson Blu Plaza Bangkok

Sample Type : น้ำใช้

Sampling by : บริษัท เทสต์ เทค จำกัด

Sampling Method : Grab

Sampling Date : 05/02/2567

Sampling Time : 11:20 น.

Received Date : 05/02/2567

Analytical Date : 05 - 16/02/2567

Report Date : 19/02/2567

Report No. : R03978/67

| Parameters | Unit | Method | TW02834 /67 |
|------------------------|-------|------------------|-----------------------|
| | | | Cooling Water |
| <i>Legionella spp.</i> | CFU/L | ISO 11731 : 2017 | 2.1 x 10 ⁴ |
| Sample Condition | | Observation | ใส |

Analyst

19/02/2567

Technical Manager

19/02/2567

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025