

ภาคผนวกที่ 20

การจัดการน้ำฝนปนเปื้อน

RAIN WATER TANK

135


AN OVERVIEW

RO/BIO SD-110

DIKE SYSTEM




OIL SEP. PIT & BIO TREAT. WATER PIT

W.W TANK/ DIKE TREND



PIT PUMP	PUMP STATUS	PIT LEVEL
AN AREA2-1 AP-962	STOP	17.1 %
AN AREA1-1 AP-942	STOP	14.2 %
MMA AREA MP-950	STOP	30.3 %
AMS AREA MP-970	STOP	35.0 %
WWI AREA WP-912	STOP	15.5 %
OIL SEPARATION ZP-932A ZP-932B	STOP STOP	

PIT PUMP	PUMP STATUS	PIT LEVEL
AN AREA2-2 AP-932	STOP	11.7 %
AN AREA1-2 AP-952	STOP	13.4 %
ACH AREA HP-922	STOP	8.9 %
AIR COMPRESSOR MP-980	STOP	20.5 %
TANK YARD TP-912	STOP	12.8 %



ตัวอย่างผลการตรวจวัดคุณภาพน้ำบริเวณบ่อบำบัดน้ำทิ้งจาก UD-910 ของบริษัท พีทีที อาซาฮี เคมิคอล จำกัด

UD-910

In Process Result Report

AN/RO/BIO					
UD-910					
SAMPLE NAME	SAMPLE POINT	SAMPLING DATE	pH	COD(Cr)	T-CN
			pH	COD(Cr) (mg/l)	T-CN (mg/l)
			5.5-9.0	750 Max	0.2 Max
UD-910	UD-910	01/06/2024 5:00	7.2	37	<0.01