

ภาคผนวกที่ 7

---

Checklist อุปกรณ์ดับเพลิง  
ประจำเดือนมกราคม-มิถุนายน 2567

### Check List emergency light

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Responsible by ..... Date 5/1/24

Supervisor by [Signature] Date 1/2/67

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Jan-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Building B	/	/	/	/	/	5/1/24		/			
221 Fire Exit	/	/	/	/	/			/			
225 Emergency	/	/	/	/	/		16/7/24	/			
233 Emergency	/	/	/	/	/			/			
224 Fire Exit	/	/	/	/	/			/			

Note: Mark [✓] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by ..... 16/7/24 ..... Date..... 5/1/24

Supervisor by ..... 16/7/24 ..... Date..... 7/1/24

### Check List emergency light

[illegible]

Supervisor by [Signature] Date 12/02



# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Jan-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Building D											
421 Fire Exit	/	/	/	/	/	4/1/24		/			
426 Emergency Fire Exit	/	/	/	/	/			/			
436 Emergency	/	/	/	/	/			/			
429 Fire Exit	/	/	/	/	/			/			
								/			

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by win 245 Date 4/1/24

Supervisor by Boon Date 1/2/24

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Jan-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Building E											
521 Fire Exit	/	/	/	/	/	} 4/1/24					
526 Emergency Fire Exit	/	/	/	/	/						
538 Emergency	/	/	/	/	/						
524 Fire Exit	/	/	/	/	/						

Note: Mark [ ✓ ] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Wai Sub Date 4/1/24

Supervisor by B. D. Sub Date 2/2/24

## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

Jan-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by banjars Date 4/1/24

Supervisor by *[Signature]* Date 1/2/17

NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

Jan-24

[illegible]

Note:Mark [ ✓ ] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by Wang Date. 4/1/24

Supervisor by B. B. B. Date 11/2/17

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Jan-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Bai rure 1 (Fire Exit)	/	/	/	/	/	} 4/1/24		✓			
Bai rure 1 (Emergency)	/	/	/	/	/			✓			
Bai rure 2 (Fire Exit)	/	/	/	/	/		10/2/24	✓			
Bai rure 2 (Emergency)	/	/	/	/	/			✓			

Note: Mark [ ✓ ] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by 10/2/24 Date 4/1/24

Supervisor by 1/2/24 Date 1/2/24



# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Jan-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 241 (Fire Exit)	✓	✓	✓	✓	✓	6/1/24		✓			
Room 241 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 246 (Fire Exit)	✓		✓	✓	✓			✓			
Room 246 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 252 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 252 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 263 (Fire Exit)	✓	✓	✓	✓	✓		6/1/24	✓			
Room 263 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 269 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 269 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 274 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 274 (Emergency)	✓	✓	✓	✓	✓			✓			

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

Responsible by 6/1/24 Date 6/1/24

Supervisor by 6/1/24 Date 1/2/24



# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Jan-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 341 (Fire Exit)	/	/	/	/	/	6/1/24		/			
Room 341 (Emergency)	/	/	/	/	/			/			
Room 346 (Fire Exit)	/	/	/	/	/			/			
Room 346 (Emergency)	/	/	/	/	/			/			
Room 355 (Fire Exit)	/	/	/	/	/			/			
Room 355 (Emergency)	/	/	/	/	/			/			
Room 360 (Fire Exit)	/	/	/	/	/		windus	/			
Room 360 (Emergency)	/	/	/	/	/			/			
Room 371 (Fire Exit)	/	/	/	/	/			/			
Room 371 (Emergency)	/	/	/	/	/			/			
Room 377 (Fire Exit)	/	/	/	/	/			/			
Room 377 (Emergency)	/	/	/	/	/			/			
Room 382 (Fire Exit)	/	/	/	/	/			/			
Room 382 (Emergency)	/	/	/	/	/			/			

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

Responsible by windus Date 6/1/24

Supervisor by Bob Date 1/2/24

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Jan-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 441 (Fire Exit)	/	/	/	/	/	6/1/24		/			
Room 441 (Emergency)	/	/	/	/	/			/			
Room 446 (Fire Exit)	/	/	/	/	/			/			
Room 446 (Emergency)	/	/	/	/	/			/			
Room 456 (Fire Exit)	/	/	/	/	/			/			
Room 456 (Emergency)	/	/	/	/	/			/			
Room 462 (Fire Exit)	/	/	/	/	/			/			
Room 462 (Emergency)	/	/	/	/	/		6/1/24	/			
Room 473 (Fire Exit)	/	/	/	/	/			/			
Room 473 (Emergency)	/	/	/	/	/			/			
Room 479 (Fire Exit)	/	/	/	/	/			/			
Room 479 (Emergency)	/	/	/	/	/			/			
Room 484 (Fire Exit)	/	/	/	/	/			/			
Room 484 (Emergency)	/	/	/	/	/			/			

Note: Mark [ / ] Normal

Mark (X) Abnormal

Responsible by ..... 6/1/24

Supervisor by ..... 1/2/24

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building A

Monthly..01/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building A													
Side Steps													
Corridor Room 121	Chemical Powder-ABC	√	√	√	√	√	√	√	24/01/24	Santichai			
Corridor Room 131	Chemical Powder-ABC	√	√	√	√	√	√	√	24/01/24	Santichai			
Central Staircase													
Corridor Room 122	Chemical Powder-ABC	√	√	√	√	√	√	√	24/01/24	Santichai			
Side Steps													
Corridor Room 124	NON-CFC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	24/01/24	Santichai			Dismantled
Corridor Room 137	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	24/01/24	Santichai			Dismantled
Facade of Building													
Corridor Room A21	NON-CFC	√	√	√	√	√	√	√	24/01/24	Santichai			
Behind the Building													
Corridor MDB Room	Chemical Powder-ABC	√	√	√	√	√	√	√	24/01/24	Santichai			

Remark;

[ √ ] Normal

[ X ] Abnormal

Loss Prevention Check

People & Culture Manager

01 N.W. 2567

01/02/24

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building B

Monthly..01/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building B</b>													
<b>Side Steps</b>													
Corridor Room 221	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 231	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 222 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 233 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
<b>Side Steps</b>													
Corridor Room 224	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Facade of Building													
Corridor Office 20/4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Behind the Building													
Corridor Office 20/1-4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

*[Signature]*  
01/02/24

People & Culture Manager

*[Signature]*

01 N.W. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building C

Monthly..01/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building C</b>													
<b>Side Steps</b>													
Corridor Room 321	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 331 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 322 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 334 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
<b>Side Steps</b>													
Corridor Room 324	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Facade of Building													
Corridor Office 20/8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Behind the Building													
Corridor Office 20/5-8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			

Remark;


[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
01/02/24

People & Culture Manager

 01 P.W. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building D

Monthly..01/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building D													
Side Steps													
Corridor Room 421	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	24/01/24	Santichai			Dismantled
Corridor Room 431	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	24/01/24	Santichai			Dismantled
Central Staircase													
Corridor Room 422	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 434	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Side Steps													
Corridor Room 424	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 437	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Facade of Building													
Corridor Office 20/12	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Behind the Building													
Corridor Office 20/9-12 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

*[Signature]*  
21/02/24

People & Culture Manager

*[Signature]* 01 P.W. 2567



# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building E

Monthly..01/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building E													
Side Steps													
Corridor Room 521	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	24/01/24	Santichai			Dismantled
Corridor Room 531	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	24/01/24	Santichai			Dismantled
Central Staircase													
Corridor Room 522	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 534	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Side Steps													
Corridor Room 524	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 537	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Facade of Building													
Corridor Office 20/16	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Behind the Building													
Corridor Office 20/13-16 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

People & Culture Manager

01 N.W. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building F

Monthly..01/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building F													
Side Steps													
Corridor Room 621	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 631	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Central Staircase													
Corridor Room 623	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 633	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Side Steps													
Corridor Room 624	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 637	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Facade of Building													
Corridor Office 20/20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Behind the Building													
Corridor Office 20/17-20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

People & Culture Manager

01 N.W. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building G

Monthly..01/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building G													
Side Steps													
Corridor Room 721	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 731	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Central Staircase													
Corridor Room 722	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 733	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Side Steps													
Corridor Room 724	Chemical Powder-ABC	X	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			Pressure down
Corridor Room 737	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Facade of Building													
Corridor Office 20/24	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Behind the Building													
Corridor Office 20/21-24 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

*[Signature]*  
01/02/24

People & Culture Manager

*[Signature]*

01 N.W. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building G

Monthly..01/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building H													
Side Steps													
Corridor Room 925	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 933	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Side Steps													
Corridor Room 924	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 927	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Facade of Building													
Corridor Office 20/26	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Behind the Building													
Corridor Office 20/25-26 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

  
01/02/24

People & Culture Manager



01 P.W. 2557

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building G

Monthly..01/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building I													
Side Steps													
Corridor Room 923	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 935	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Side Steps													
Corridor Room 936	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 949	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Facade of Building													
Corridor Office 20/27	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Behind the Building													
Corridor Office 20/26-27 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

  
01/02/24

People & Culture Manager



01 N.W. 25<sup>th</sup>

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing Floor 1, Restaurant, Lobby

Monthly..01/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 1</b>													
Loading x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Accounting Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Female Locker	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Canteen Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Main Kitchen x4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Electrical Control Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Captain Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Lift Main Kitchen x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Bai-Ruer Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Boat Point Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Loss Prevention Office	NON-CFC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Generator Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

People & Culture Manager

01 N.W. 2567



## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Hotel Wing FLOOR 2,3

Monthly..01/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 2</b>													
Corridor Room 242	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 250	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 256	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 264	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 272	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
<b>FLOOR 3</b>													
Corridor Room 342	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 348	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 352	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 358	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 364	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 372	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 380	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

  
01/02/24

People & Culture Manager



01 P.W. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing FLOOR 4/White House Meeting Room

Monthly..01/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
FLOOR 4													
Corridor Room 442	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 448	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 454	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 460	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 466	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 474	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
Corridor Room 482	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
White House Meeting Room01	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
White House Meeting Room02	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
White House Meeting Room03	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
White House Meeting Room04	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
White House Meeting Room05	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			
White House Meeting Room KC x3	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	24/01/24	Santichai			

Remark;


[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
01/02/24

People & Culture Manager

 01 P.W. 2567

ทำความสะอาดห้องควบคุมไฟฟ้าย่อย 1 SDB



1/2/67

ทำความสะอาดห้องควบคุมไฟฟ้า 2 MDB




สะอาด  
1/2/58



ทำความสะอาดห้องควบคุมไฟฟ้า 3 MDB



เช็คแล้ว  
11/2/67



## ATOM CHEMTECH CO., LTD.

PKT67/0048

วันที่ 15 มกราคม 2567

เรื่อง ขออนุญาตเข้าปฏิบัติงานทำความสะอาดสระว่ายน้ำ  
เรียน Engineer Department  
NH Boat Lagoon Phuket Resort

บริษัท อะตอม เคมีเทค จำกัด ได้เข้าดูและระบบน้ำสระว่ายน้ำของโรงแรม NH Boat Lagoon Phuket Resort และเพื่อให้เป็นไปตามเงื่อนไขบริการหลังการขาย ดังนั้น

ทางทีมงานของบริษัท อะตอม เคมีเทค จำกัด ขออนุญาตเข้าไปปฏิบัติงานทำความสะอาดสระว่ายน้ำในวันที่ 19 มกราคม พ.ศ. 2567 เวลา 21.00 น. เป็นต้นโดยมีพนักงานเข้าดำเนินงาน 3-4 คน หรือตามแต่เจ้าหน้าที่ของโรงแรมสะดวก เพื่อเข้าไปปรับสภาพน้ำสระว่ายน้ำ และทำความสะอาดสระว่ายน้ำให้พร้อมต่อการใช้งานอย่างมีประสิทธิภาพ ซึ่งการบริการเหล่านี้ก็เป็นส่วนหนึ่งในบริการหลังการขายของบริษัทฯ ทางบริษัทต้องขอให้โรงแรมแจ้งกับผู้ใช้บริการด้วย เพื่อความสะดวกของผู้ปฏิบัติงานและความปลอดภัยของผู้มาใช้บริการ

บริษัทฯ มั่นใจเป็นอย่างยิ่งว่าสินค้าและบริการของบริษัท อะตอม เคมีเทค จำกัด โดยการควบคุมของวิศวกร (เคมี) นักวิทยาศาสตร์ (เคมี) และนักวิทยาศาสตร์ (สิ่งแวดล้อม) นำความรู้และประสบการณ์ในการดำเนินธุรกิจของบริษัทฯ ซึ่งจะช่วยก่อให้เกิดประโยชน์ต่อกิจการของท่านด้วยค่าใช้จ่ายที่เหมาะสม รวมทั้งการบริการที่สะดวก รวดเร็ว ที่ท่านสามารถเรียกใช้บริการของบริษัทฯ ซึ่งมีที่ตั้งสำนักงานอยู่ ณ เลขที่ 65/14 ม.1 ต.เกาะแก้ว อ.เมืองภูเก็ต จ.ภูเก็ต 83000 โทรศัพท์ (076) 377855, (085) 8880036, (085) 8340036 โทรสาร (076) 239191 E-Mail : [ATOM\\_CHEMTECH@YAHOO.CO.TH](mailto:ATOM_CHEMTECH@YAHOO.CO.TH), [JOJOBAROIL2005QHOTMAIL.COM](mailto:JOJOBAROIL2005QHOTMAIL.COM)

บริษัทฯ ขอขอบคุณทุกท่านที่ให้โอกาสทางบริษัทฯ เข้าไปบริการท่านในวันนี้

จึงเรียนมาเพื่อขออนุญาต



ขอแสดงความนับถือ  
บริษัท อะตอม เคมีเทค จำกัด

( นายเตชวัน อ่องแสง )

ฝ่ายขายเคมีภัณฑ์

โทรศัพท์ 095-548-8830

ATOM CHEMTECH CO., LTD

65/14 MOO 1 TAMBOL KOHKAWE, AMPHUR MUANG, PHUKET, 83000 THAILAND. TEL: (076)377855, (085) 8880036, (085) 8340036, FAX: (076)630036





ATOM CHEMTECH CO., LTD.

รายงานการบริการขัดสระว่ายน้ำ

วันที่ 19/1/67  
เวลา 21.00 น.

เรียน คุณน้ำอ้วน  
โรงแรม โชคกลาง

บริษัท อะตอม เคมีเทค จำกัด ได้จัดส่งเจ้าหน้าที่เข้ามาทำการปฏิบัติงานขัดสระโครน้ำในสระ  
ว่ายน้ำของโรงแรมและ เติมสารป้องกันตะโครน้ำพิเศษ เป็นการบริการเพิ่มเติมสำหรับโรงแรมลูกค้าที่ใช้  
บริการผลิตภัณฑ์ **MASTERCHLO - A** และ **EXTRA - CLEAR** ในระบบบำบัดน้ำสระว่ายน้ำของ  
บริษัทฯ โดยไม่มีการคิดค่าใช้จ่ายใดๆทั้งสิ้น

สระว่ายน้ำ ส. 1 สระ

สารป้องกันตะโครน้ำที่ใช้เติม :

1. คัลคลอรีน 90% จำนวนที่เติม 5 กก.
2. \_\_\_\_\_ จำนวนที่เติม \_\_\_\_\_ กก.

ขอแสดงความนับถือ  
บริษัท อะตอม เคมีเทค จำกัด

ผู้ปฏิบัติงาน ส/า + กาน + ชิว เจ้าหน้าที่โรงแรม อนุสรณ์ แก้วแก้ว

19/1/67

ATOM CHEMTECH CO., LTD

ทห

BOAT LAGOON  
PHUKET RESORT

บันทึกการตรวจสอบสภาพหัวจ่ายน้ำดับเพลิง

รายละเอียดของหัวจ่ายดับเพลิง

รหัส		ขนาดหัวจ่าย				สถานที่ติดตั้ง				
วันที่ตรวจ	หมายเลขตู้	เกณฑ์การตรวจสอบ								ผู้ตรวจ
		วาวว/ประกัน (การรั่วซึม)		ตู้ดับเพลิง หัวฉีด/สายน้ำ		การจ่ายน้ำ		สิ่งกีดขวาง		
		ปกติ	ชำรุด	ปกติ	ชำรุด	ปกติ	ไม่ปกติ	มี	ไม่มี	
	1	/		/		/			/	1๖๖
	2	/		/		/			/	1๖๖
	3	/		/		/			/	1๖๖
	4	/		/		/			/	1๖๖
	5	/		/		/			/	1๖๖
	6	/		/		/			/	1๖๖
	7	/		/		/			/	1๖๖
	8	/		/		/			/	1๖๖
	9	/		/		/			/	1๖๖
	10	/		/		/			/	1๖๖
	11	/		/		/			/	1๖๖
	12	/		/		/			/	1๖๖
	14		/	/		/			/	1๖๖
	15	/		/		/			/	1๖๖
	16	/		/		/			/	1๖๖
	17	/		/		/			/	1๖๖
	18	/		/		/			/	1๖๖
	19	/		/		/			/	1๖๖
	20	/		/		/			/	1๖๖
	21	/		/		/			/	1๖๖
	22	/		/		/			/	1๖๖
	23	/		/		/			/	1๖๖
	24	/		/		/			/	1๖๖
	25	/		/		/			/	1๖๖
	26	/		/		/			/	1๖๖
	29	/		/		/			/	1๖๖
	28	/		/		/			/	1๖๖
	29	/		/		/			/	1๖๖
									</	

ภาพหัวจ่ายน้ำดับเพลิง อุปกรณ์ และตู้ดับเพลิง



รายละเอียดการชำรุด

ชำรุด #14

สาเหตุการชำรุด

(✓)ใช้งาน

( )หมดอายุ

( )อื่นๆ

ผู้รายงาน

วชิษฐ์ วิชา

ตำแหน่ง

ช่าง 1103

วันที่

10/01/67

ข้อปฏิบัติ

ตรวจสอบสภาพหัวจ่ายน้ำดับเพลิง ทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้เจป.ทันที

1/2/67

# NH

BOAT LAGOON  
PHUKET RESORT

## บันทึกการตรวจสอบระบบสัญญาณแจ้งเหตุฉุกเฉิน

### รายละเอียดของสัญญาณแจ้งเหตุฉุกเฉิน

รหัส

สถานที่ติดตั้ง

#### เกณฑ์การตรวจสอบ

วันที่ตรวจ	สภาพจุดติดตั้ง		ปุ่มควบคุม		การส่งสัญญาณ		แหล่งจ่ายไฟสำรอง		สิ่งกีดขวาง		ผู้ตรวจ
	ปกติ	ชำรุด	ปกติ	ชำรุด	ปกติ	ไม่ปกติ	ปกติ	ไม่ปกติ	มี	ไม่มี	
1	✓		✓		✓		✓			✓	12/5
2											
3	✓		✓		✓		✓			✓	12/5
4	✓		✓		✓		✓			✓	12/5
5											
6	✓		✓		✓		✓			✓	12/5
7	✓		✓		✓		✓			✓	12/5
8	✓		✓		✓		✓			✓	12/5
9	✓		✓		✓		✓			✓	12/5
10	✓		✓		✓		✓			✓	12/5
11	✓		✓		✓		✓			✓	12/5
12	✓		✓		✓		✓			✓	12/5
14											
15	✓		✓		✓		✓			✓	12/5
16	✓		✓		✓		✓			✓	12/5
17											
18	✓		✓		✓		✓			✓	12/5
19	✓		✓		✓		✓			✓	12/5
20	✓		✓		✓		✓			✓	12/5
21	✓		✓		✓		✓			✓	12/5
22	✓		✓		✓		✓			✓	12/5
23	✓		✓		✓		✓			✓	12/5
24	✓		✓		✓		✓			✓	12/5
25	✓		✓		✓		✓			✓	12/5
26	✓		✓		✓		✓			✓	12/5
27	✓		✓		✓		✓			✓	12/5
28											
29	✓		✓		✓		✓			✓	12/5

#### รายละเอียดการชำรุด



กระดิ่งสัญญาณ



ปุ่มควบคุม

สาเหตุการชำรุด

( ) ใช้งาน

( ) หมดอายุ

( ) อื่นๆ

ผู้รายงาน

ตำแหน่ง

วันที่

วิรัตน์ จันท

ช่าง 1103

10/11/67

#### ข้อปฏิบัติ

ตรวจสอบสัญญาณแจ้งเหตุฉุกเฉินทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้ป.ทันที

วิรัตน์ 1/2/67



**ท.ห.**

BOAT LAGOON  
PHUKET RESORT

## บันทึกการตรวจสอบปั้มน้ำดับเพลิง

รายละเอียดเครื่องสูบน้ำดับเพลิง (Electrical Fire Pump)

รหัส	ชนิด	ขนาด	สถานที่ติดตั้ง
TH-DE250M-2	motor pump	55 KW	Pump Room 2

หัวข้อ	เกณฑ์การตรวจสอบ	ปกติ	ไม่ปกติ	หมายเหตุ
1	ตรวจสอบสภาพ seal เครื่องสูบน้ำ	✓		
2	ประเก็นหน้าวาล์วต่างๆ	✓		
3	วาล์วทางดูด (foot valve)	✓		
4	วาล์วทางดันจ่าย (discharge valve)	✓		
5	หลอดไฟสวิตช์หน้าตู้	✓		หลอดไฟ power ตก
6	ระดับความดันสั่งงานของ Pressure switch			ระบุ 60 Psi
7	ระดับความดันของเครื่องสูบน้ำขณะทำงาน	✓		ระบุ 120 Psi
8	ระดับความดันหยุดการทำงานของ Pressure switch	✓		ระบุ 80 Psi
9	ระดับเสียงมอเตอร์ขณะทำงาน	✓		
10	หน้าตู้ควบคุม (Auto start function On/off)	✓		auto
11	สภาพการทำงานมอเตอร์โดยรวม	✓		
12	อื่นๆ ระบุ	-	-	-

รายละเอียดการชำรุด	สาเหตุการชำรุด
หลอดไฟดวงกลาง (Power) หลอดหลอดกลางใช้งาน	( ) ใช้งาน (✓) หมดอายุ
	( ) อื่นๆ โปรดระบุ.....
ผู้รายงาน	ช่างซ่อม รัตติ
ตำแหน่ง	technician supervisor
วันที่	15/1/67

ข้อปฏิบัติ

ตรวจสอบเครื่องสูบน้ำดับเพลิง ทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จ.ป.ทันที

1/2/67

## Fire Pump(Pump room 2) 15/01/2567



15





# TEST RUN RECORD FOR EMERGENCY GENERATOR

DATE 17/1/67

ENGINEER วิศวกร ร.ก.โธ

GENERATOR 400 KVA

LOCATION ตึก 135 ชั้น

## สภาพเครื่องก่อน TEST RUN

- ☒ ระดับน้ำมันเครื่อง (Motor Oil)
- ☒ สภาพสายพาน (Machine Bell)
- ☒ ระดับน้ำในหม้อน้ำ (Boiler)
- ☒ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

## TEST RUN

☐ ON LOAD

☒ OFF LOAD

TIME START 13.30

TIME STOP 14.00 น.

รายการตรวจเช็ค	บันทึก
Oil (L.)	1040
Voltage (V) L1	230
Voltage (V) L2	230
Voltage (V) L3	230
Coolant Temp (°C)	60°
Oil Pressure (bar)	4.5 bar
Speed (RPM)	1500
Frequency (Hz)	51
Battery (V)	28 V
Run Time (h)	01077

REMARK

1/2/67

Generator 1









## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building A

Monthly..02/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building A</b>													
Side Steps													
Corridor Room 121	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 131	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 122	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Side Steps													
Corridor Room 124	NON-CFC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	27/02/24	Santichai			Dismantled
Corridor Room 137	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	27/02/24	Santichai			Dismantled
Facade of Building													
Corridor Room A21	NON-CFC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Behind the Building													
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

  
28/02/2024

People & Culture Manager



29 N.W. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building B

Monthly..02/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building B</b>													
Side Steps													
Corridor Room 221	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 231	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 222 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 233 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Side Steps													
Corridor Room 224	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Facade of Building													
Corridor Office 20/4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Behind the Building													
Corridor Office 20/1-4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

  
28/02/2024

People & Culture Manager



29 N.W. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building C

Monthly..02/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building C</b>													
Side Steps													
Corridor Room 321	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 331 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 322 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 334 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Side Steps													
Corridor Room 324	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Facade of Building													
Corridor Office 20/8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Behind the Building													
Corridor Office 20/5-8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			

Remark;


[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
28/02-2024

People & Culture Manager

  
29 Feb. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building D

Monthly..02/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building D</b>													
Side Steps													
Corridor Room 421	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	27/02/24	Santichai			Dismantled
Corridor Room 431	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	27/02/24	Santichai			Dismantled
<b>Central Staircase</b>													
Corridor Room 422	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 434	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Side Steps													
Corridor Room 424	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 437	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Facade of Building													
Corridor Office 20/12	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Behind the Building													
Corridor Office 20/9-12 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			

Remark;

[ ☒ ] Normal

[ ☐ ] Abnormal

Loss Prevention Check

  
28/02/2024

People & Culture Manager



29 N.W. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building E

Monthly..02/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building E</b>													
Side Steps													
Corridor Room 521	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	27/02/24	Santichai			Dismantled
Corridor Room 531	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	27/02/24	Santichai			Dismantled
<b>Central Staircase</b>													
Corridor Room 522	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 534	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Side Steps													
Corridor Room 524	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 537	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Facade of Building													
Corridor Office 20/16	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Behind the Building													
Corridor Office 20/13-16 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

People & Culture Manager

29 Feb. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building F

Monthly..02/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building F													
Side Steps													
Corridor Room 621	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 631	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Central Staircase													
Corridor Room 623	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 633	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Side Steps													
Corridor Room 624	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 637	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Facade of Building													
Corridor Office 20/20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Behind the Building													
Corridor Office 20/17-20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	v	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

25/02/2024

People & Culture Manager

29 P.W. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building G

Monthly..02/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building G													
Side Steps													
Corridor Room 721	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 731	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Central Staircase													
Corridor Room 722	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Corridor Room 733	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Side Steps													
Corridor Room 724	Chemical Powder-ABC	X	✓	✓	✓	✓	✓	✓	27/02/24	Santichai	27/02/24		Pressure down
Corridor Room 737	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Facade of Building													
Corridor Office 20/24	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			
Behind the Building													
Corridor Office 20/21-24 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	27/02/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

People & Culture Manager

29 N.W. 2567

# **NH BOAT LAGOON PHUKET RESORT** **Check List Fire Extinguisher Building G**

Monthly..02/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building H													
Side Steps													
Corridor Room 925	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
Corridor Room 933	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
Side Steps													
Corridor Room 924	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
Corridor Room 927	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
Facade of Building													
Corridor Office 20/26	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
Behind the Building													
Corridor Office 20/25-26 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

*[Signature]*  
28/02/2024

People & Culture Manager

*[Signature]*

29 N.W. 2567



## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building G

Monthly..02/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building I													
Side Steps													
Corridor Room 923	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
Corridor Room 935	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
Side Steps													
Corridor Room 936	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
Corridor Room 949	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
Facade of Building													
Corridor Office 20/27	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
Behind the Building													
Corridor Office 20/26-27 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			

Remark:

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

*[Signature]*  
28/02/2024

People & Culture Manager

*[Signature]*

29 A.W. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing Floor 1,Restaurant,Lobby

Monthly..02/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 1</b>													
Loading x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Accounting Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Female Locker	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Canteen Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Main Kitchen x4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Electrical Control Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Captain Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Lift Main Kitchen x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Bai-Ruer Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Boat Point Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Loss Prevention Office	NON-CFC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Generator Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Gas Store	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

*[Signature]*  
26/02/24

People & Culture Manager

*[Signature]*

29 P.W. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Hotel Wing FLOOR 2,3

Monthly..02/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 2</b>													
Corridor Room 242	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 250	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 256	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 264	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 272	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
<b>FLOOR 3</b>													
Corridor Room 342	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 348	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 352	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 358	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 364	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 372	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 380	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			

Remark;


[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
26/02/2024

People & Culture Manager

  
29 N.W. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing FLOOR 4/White House Meeting Room

Monthly..02/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 4</b>													
Corridor Room 442	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 448	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 454	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 460	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 466	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 474	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
Corridor Room 482	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	26/02/24	Santichai			
White House Meeting Room01	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
White House Meeting Room02	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
White House Meeting Room03	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
White House Meeting Room04	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
White House Meeting Room05	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			
White House Meeting Room KC x3	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/02/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

*[Signature]*  
28/02/2024

People & Culture Manager

*[Signature]*

29 N.W. 2567

บันทึกการตรวจสอบระบบสัญญาณแจ้งเหตุฉุกเฉิน

รายละเอียดของสัญญาณแจ้งเหตุฉุกเฉิน

รหัส

สถานที่ติดตั้ง

วันที่ตรวจ	เกณฑ์การตรวจสอบ										ผู้ตรวจ
	สภาพจุดติดตั้ง		ปุ่มควบคุม		การส่งสัญญาณ		แหล่งจ่ายไฟสำรอง		สิ่งกีดขวาง		
	ปกติ	ชำรุด	ปกติ	ชำรุด	ปกติ	ไม่ปกติ	ปกติ	ไม่ปกติ	มี	ไม่มี	
1	✓		✓		✓		✓			✓	
2											
3	✓		✓		✓		✓			✓	
4	✓		✓		✓		✓			✓	
5											
6	✓		✓		✓		✓			✓	
7	✓		✓		✓		✓			✓	
8	✓		✓		✓		✓			✓	
9	✓		✓		✓		✓			✓	
10	✓		✓		✓		✓			✓	
11	✓		✓		✓		✓			✓	
12	✓		✓		✓		✓			✓	
13	✓		✓		✓		✓			✓	
14	✓		✓		✓		✓			✓	
15	✓		✓		✓		✓			✓	
16	✓		✓		✓		✓			✓	
17											
18	✓		✓		✓		✓			✓	
19	✓		✓		✓		✓			✓	
20	✓		✓		✓		✓			✓	
21	✓		✓		✓		✓			✓	
22	✓		✓		✓		✓			✓	
23	✓		✓		✓		✓			✓	
24	✓		✓		✓		✓			✓	
25	✓		✓		✓		✓			✓	
26	✓		✓		✓		✓			✓	
27	✓		✓		✓		✓			✓	
28											
29	✓		✓		✓		✓			✓	
30											

รายละเอียดการชำรุด



กระดิ่งสัญญาณ



ปุ่มควบคุม

สาเหตุการชำรุด

( ) ใช้งาน

( ) หมดอายุ

( ) อื่นๆ

ผู้รายงาน

ตำแหน่ง

วันที่

นาย วัชรินทร์ วัชรินทร์

หัวหน้างานช่างไฟฟ้า

20/2/67

ข้อปฏิบัติ

ตรวจสอบสัญญาณแจ้งเหตุฉุกเฉินทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที





### รายละเอียดของหัวจ่ายดับเพลิง

รหัส

ขนาดหัวจ่าย

สถานที่ติดตั้ง

[illegible]

ภาพหัวจ่ายน้ำดับเพลิง อุปกรณ์ และตู้ดับเพลิง

### รายละเอียดการชำระ

เปิดทำการ วัน ๑๔ มีนาคม ๒๕๖๓  
เปิดดำเนินการ ๑๕ มีนาคม ๒๕๖๓

สาเหตุการชำรุด  
(๖) ใช้งาน

(✓)หมดอายุ

( ) อื่นๆ

ผู้รายงาน  
ตำแหน่ง  
วันที่

เลขาฯ กสอ  
โทรสารมายัง กสอ  
20/2/67



## ข้อปฏิบัติ

ตรวจสภาพหัวจ่ายน้ำดับเพลิง ทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที





## TEST RUN RECORD FOR EMERGENCY GENERATOR

GATE 15/02/2567 ENGINEER วิศวกร ช่าง  
GENERATOR 1000 KVA LOCATION 3 กอ. 7

### สภาพเครื่องก่อน TEST RUN

- |                                     |                                    |
|-------------------------------------|------------------------------------|
| <input checked="" type="checkbox"/> | ระดับน้ำมันเครื่อง (Motor Oil)     |
| <input checked="" type="checkbox"/> | สภาพสายพาน (Machine Belt)          |
| <input checked="" type="checkbox"/> | ระดับน้ำในหม้อน้ำ (Boiler)         |
| <input checked="" type="checkbox"/> | ระดับน้ำกลั่นในแบตเตอรี่ (Battery) |

## TEST RUN

☐ ON LOAD      ☐ OFF LOAD

TIME START ..... TIME STOP .....

รายการตรวจเช็ค		บันทึก
Oil (L.)		1800 L
Voltage (V)	L1	0
Voltage (V)	L2	0
Voltage (V)	L3	0
Coolant Temp (°C)		0
Oil Pressure (bar)		0
Speed (RPM)		0
Frequency (Hz)		0
Battery (V)		27.4
Run Time (h)		201h25m

REMARK

การหาพื้นที่ผิวทั้งหมด 11 รูปที่เหมือนกัน + หักด้วย

53070









# Unithai - Southern Co., Ltd

FR-UTS-201

59/3-4 MOO 6, THEPKRASATRI ROAD, TAMBON RASDA, AMPHOE MUANG.

PHUKET 83000 <http://www.unithaisouthern.co.th/> / Email: [unithaisouthern@hotmail.com](mailto:unithaisouthern@hotmail.com)

TELEPHONE : 076-222770-1, FAX : 076-222772 (AUTOMATIC)

## Service Report

ลักษณะงาน/The project :

ติดตั้ง FM 200

วันที่เริ่มงาน/Start Date :

4/3/67

ถึงวันที่/To Date :

4/3/67

ลูกค้า/Customer :

ไม้ก่อกอง

ติดต่อ/Contact :

โทร./Tel. :

มือถือ/Mobile :

เอกสารที่ต้องเตรียม :

☐ Drawing

☐ Check List

☐ อื่นๆ

รายละเอียดของงาน/Details of the work :

- ได้ทำการติดตั้ง FM 200 พร้อม Test 5221 มาแล้ว ใช้งานได้ปกติ  
- ได้ทำการถอดกล่อง Manual ให้ใช้จากทางลูกค้า 50903 (กล่องควบคุม Manual)  
ลาติดตั้งแล้ว

วิธีการแก้ไข:

หมายเหตุ/Remark :

ผู้ให้บริการ/Service :

*[Signature]*

Date 4 / 3 / 67

ผู้รับบริการ/Customer :

*[Signature]*

Date 4 / 3 / 67





งานทำความสะอาดห้องควบคุมไฟฟ้าย่อย 1 SDB



งานทำความสะอาดห้องควบคุมไฟฟ้า 2 MDB





งานทำความสะอาดห้องควบคุมไฟฟ้า 3 MDB



งานทำความสะอาดห้องควบคุมไฟฟ้า 1 MDB





## บันทึกการตรวจสอบปั้มน้ำดับเพลิง

รายละเอียดเครื่องสูบน้ำดับเพลิง (Electrical Fire Pump)

รหัส	ชนิด	ขนาด	สถานที่ติดตั้ง
TW-PF250M-2	motor pump	55 KW	Pump Room 2

หัวข้อ	เกณฑ์การตรวจสอบ	ปกติ	ไม่ปกติ	หมายเหตุ
1	ตรวจสอบสภาพ seal เครื่องสูบน้ำ	✓		
2	ประเก็นหน้าวาล์วต่างๆ	✓		
3	วาล์วทางดูด (foot valve)	✓		
4	วาล์วทางจ่าย (discharge valve)	✓		
5	หลอดไฟสวิตช์หน้าตู้		✓	หลอดไฟ Power ขาด
6	ระดับความดันสั่งงานของ Pressure switch	✓		ระบุ 60 PSI
7	ระดับความดันของเครื่องสูบน้ำขณะทำงาน	✓		ระบุ 120 PSI
8	ระดับความดันหยุดการทำงานของ Pressure switch	✓		ระบุ 80 PSI
9	ระดับเสียงมอเตอร์ขณะทำงาน	✓		
10	หน้าตู้ควบคุม (Auto start function On/off)	✓		auto
11	สภาพการทำงานมอเตอร์โดยรวม	✓		
12	อื่นๆ ระบุ			

รายละเอียดการชำรุด

หลอดไฟสวิตช์หน้าตู้ (Power)  
(กำลัง 100w)

สาเหตุการชำรุด

( ) ใช้งาน

(✓) หมดอายุ

( ) อื่นๆ โปรดระบุ.....

ผู้รายงาน

นายสมศักดิ์ ใจดี

ตำแหน่ง

ช่างเทคนิคช่างทั่วไป

วันที่

15/02/24

ข้อปฏิบัติ

ตรวจสอบเครื่องสูบน้ำดับเพลิง ทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที













### Check List emergency light

[illegible]

(2) = Emergency Light

Supervisor by Wanda Tate Date 8/9/67

### Check List emergency light

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Responsible by W. N. S. Date 23/3/67

Supervisor by benzoni jayce Date 29/3/67

### Check List emergency light

[illegible]

(2) = Emergency Light

Supervisor by బొమ్మిడి నవీన్ Date 29/9/27

NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

Mar-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by Yusuf Date 23/3/27

Supervisor by Benjamin S. S. S. Date 28/9/27



### Check List emergency light

[illegible]

(1) = Fire Exit

(2) = Emergency Light

Responsible by ..... Date.....

Supervisor by betwys gwe Date 29/3/27



## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

Mar-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by ..... 21/10/17 ..... Date 23/3/17

Supervisor by                      Date 22/3/67

## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

Mar-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by unna Date 23/8/67

Supervisor by சென்னை கல்வி Date 23/3/67

Mar-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by g. nora Date 2/3/167

Supervisor by                      Date 23/3/67

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Mar-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 241 (Fire Exit)	/	/	/	/	/			/			
Room 241 (Emergency)	/	/	/	/	/			/			
Room 246 (Fire Exit)	/	/	/	/	/			/			
Room 246 (Emergency)	/	/	/	/	/			/			
Room 252 (Fire Exit)	/	/	/	/	/			/			
Room 252 (Emergency)	/	/	/	/	/			/			
Room 263 (Fire Exit)	/	/	/	/	/	23/3/67	สมชาย	/			
Room 263 (Emergency)	/	/	/	/	/			/			
Room 269 (Fire Exit)	/	/	/	/	/			/			
Room 269 (Emergency)	/	/	/	/	/			/			
Room 274 (Fire Exit)	/	/	/	/	/			/			
Room 274 (Emergency)	/	/	/	/	/			/			
Room 247 (Fire Exit)	/	/	/	/	/			/			
Room 247 (Fire Emergency)	/	/	/	/	/			/			

Note: Mark [ / ] Normal

Mark (X) Abnormal

Responsible by สมชาย Date 23/3/67

Supervisor by สมชาย Date 23/3/67



# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Mar-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 341 (Fire Exit)	/	/	/	/	/	23/3/67	gndon	/			
Room 341 (Emergency)	/	/	/	/	/			/			
Room 346 (Fire Exit)	/	/	/	/	/			/			
Room 346 (Emergency)	/	/	/	/	/			/			
Room 355 (Fire Exit)	/	/	/	/	/			/			
Room 355 (Emergency)	/	/	/	/	/			/			
Room 360 (Fire Exit)	/	/	/	/	/			/			
Room 360 (Emergency)	/	/	/	/	/			/			
Room 371 (Fire Exit)	/	/	/	/	/			/			
Room 371 (Emergency)	/	/	/	/	/			/			
Room 377 (Fire Exit)	/	/	/	/	/			/			
Room 377 (Emergency)	/	/	/	/	/			/			
Room 382 (Fire Exit)	/	/	/	/	/			/			
Room 382 (Emergency)	/	/	/	/	/			/			

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

Responsible by ..... gndon ..... Date 23/3/67

Supervisor by ..... gndon ..... Date 23/3/67



# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Mar-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 441 (Fire Exit)	/	/	/	/	/			/			
Room 441 (Emergency)	/	/	/	/	/			/			
Room 446 (Fire Exit)	/	/	/	/	/			/			
Room 446 (Emergency)	/	/	/	/	/			/			
Room 456 (Fire Exit)	/	/	/	/	/			/			
Room 456 (Emergency)	/	/	/	/	/			/			
Room 462 (Fire Exit)	/	/	/	/	/	23/3/17	สมชาย	/			
Room 462 (Emergency)	/	/	/	/	/			/			
Room 473 (Fire Exit)	/	/	/	/	/			/			
Room 473 (Emergency)	/	/	/	/	/			/			
Room 479 (Fire Exit)	/	/	/	/	/			/			
Room 479 (Emergency)	/	/	/	/	/			/			
Room 484 (Fire Exit)	/	/	/	/	/			/			
Room 484 (Emergency)	/	/	/	/	/			/			

Note: Mark [✓] Normal

Mark (X) Abnormal

Responsible by ..... สมชาย ..... Date 23/3/17

Supervisor by ..... สมชาย ..... Date 23/3/17

**NH BOAT LAGOON PHUKET RESORT**  
**Check List Fire Extinguisher Building A**

**Monthly..03/2024**


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building A</b>													
Side Steps													
Corridor Room 121	Chemical Powder-ABC	√	√	√	√	√	√	√	28/03/24	Santichai			
Corridor Room 131	Chemical Powder-ABC	√	√	√	√	√	√	√	28/03/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 122	Chemical Powder-ABC	√	√	√	√	√	√	√	28/03/24	Santichai			
Side Steps													
Corridor Room 124	NON-CFC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	28/03/24	Santichai			Dismantled
Corridor Room 137	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	28/03/24	Santichai			Dismantled
Facade of Building													
Corridor Room A21	NON-CFC	√	√	√	√	√	√	√	28/03/24	Santichai			
Behind the Building													
Corridor MDB Room	Chemical Powder-ABC	√	√	√	√	√	√	√	28/03/24	Santichai			

Remark;

[ **√** ] Normal

[ **X** ] Abnormal

Loss Prevention Check

  
30/3/24

People & Culture Manager



## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building B

Monthly..03/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building B</b>													
Side Steps													
Corridor Room 221	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 231	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 222 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 233 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Side Steps													
Corridor Room 224	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Facade of Building													
Corridor Office 20/4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Behind the Building													
Corridor Office 20/1-4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

*[Signature]*  
31/3/24

People & Culture Manager

- 1 (U.U. 2567)

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building C

Monthly..03/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building C</b>													
Side Steps													
Corridor Room 321	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 331 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 322 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 334 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Side Steps													
Corridor Room 324	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Facade of Building													
Corridor Office 20/8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Behind the Building													
Corridor Office 20/5-8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			

Remark;


[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
30/3/24

People & Culture Manager

  
- 1 W.U. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building D

Monthly..03/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building D</b>													
<b>Side Steps</b>													
Corridor Room 421	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	28/03/24	Santichai			Dismantled
Corridor Room 431	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	28/03/24	Santichai			Dismantled
<b>Central Staircase</b>													
Corridor Room 422	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 434	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
<b>Side Steps</b>													
Corridor Room 424	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 437	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Facade of Building													
Corridor Office 20/12	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Behind the Building													
Corridor Office 20/9-12 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check



People & Culture Manager





## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building E

Monthly..03/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building E</b>													
<b>Side Steps</b>													
Corridor Room 521	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	28/03/24	Santichai			Dismantled
Corridor Room 531	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	28/03/24	Santichai			Dismantled
<b>Central Staircase</b>													
Corridor Room 522	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 534	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
<b>Side Steps</b>													
Corridor Room 524	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 537	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Facade of Building													
Corridor Office 20/16	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Behind the Building													
Corridor Office 20/13-16 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			

Remark;

[ **✓** ] Normal

[ **X** ] Abnormal

Loss Prevention Check



People & Culture Manager



- 1 B.B. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building F

Monthly..03/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building F</b>													
Side Steps													
Corridor Room 621	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 631	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 623	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 633	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Side Steps													
Corridor Room 624	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 637	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Facade of Building													
Corridor Office 20/20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Behind the Building													
Corridor Office 20/17-20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

People & Culture Manager

- 1 W.U. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building G

Monthly..03/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building G													
Side Steps													
Corridor Room 721	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 731	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Central Staircase													
Corridor Room 722	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 733	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Side Steps													
Corridor Room 724	Chemical Powder-ABC	X	✓	✓	✓	✓	✓	✓	28/03/24	Santichai	27/02/24		Pressure down
Corridor Room 737	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Facade of Building													
Corridor Office 20/24	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Behind the Building													
Corridor Office 20/21-24 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			

Remark;


[✓] Normal

[X] Abnormal

Loss Prevention Check

  
28/03/24

People & Culture Manager

  
- 1 W.O. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building G

Monthly..03/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building H													
Side Steps													
Corridor Room 925	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 933	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Side Steps													
Corridor Room 924	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Corridor Room 927	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Facade of Building													
Corridor Office 20/26	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
Behind the Building													
Corridor Office 20/25-26 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
20/3/24

People & Culture Manager



- 1 W.O. 2567



# **NH BOAT LAGOON PHUKET RESORT** **Check List Fire Extinguisher Building G**

**Monthly..03/2024**


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building I													
Side Steps													
Corridor Room 923	Chemical Powder-ABC	√	√	√	√	√	√	√	28/03/24	Santichai			
Corridor Room 935	Chemical Powder-ABC	√	√	√	√	√	√	√	28/03/24	Santichai			
Side Steps													
Corridor Room 936	Chemical Powder-ABC	√	√	√	√	√	√	√	28/03/24	Santichai			
Corridor Room 949	Chemical Powder-ABC	√	√	√	√	√	√	√	28/03/24	Santichai			
Facade of Building													
Corridor Office 20/27	Chemical Powder-ABC	√	√	√	√	√	√	√	28/03/24	Santichai			
Behind the Building													
Corridor Office 20/26-27 x2	Chemical Powder-ABC	√	√	√	√	√	√	√	28/03/24	Santichai			

Remark;

[ **√** ] Normal

[ **X** ] Abnormal

Loss Prevention Check



People & Culture Manager



- 1 W.O. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Hotel Wing Floor 1, Restaurant, Lobby

Monthly..03/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 1</b>													
Loading x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Accounting Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Female Locker	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Canteen Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			Fire Blanket x1
Main Kitchen x2	Chemical -ABCDK	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			Fire Blanket x2
Electrical Control Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Captain Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Lift Main Kitchen x2	Chemical Powder-AK	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Bai-Ruer Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Boat Point Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Loss Prevention Office	NON-CFC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Generator Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Gas Store	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check



People & Culture Manager



**NH BOAT LAGOON PHUKET RESORT**  
**Check List Fire Extinguisher Hotel Wing FLOOR 2,3**

**Monthly..03/2024**


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 2</b>													
Corridor Room 242	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 250	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 256	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 264	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 272	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
<b>FLOOR 3</b>													
Corridor Room 342	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 348	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 352	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 358	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 364	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 372	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 380	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			

Remark;


[✓] Normal

[X] Abnormal

Loss Prevention Check



People & Culture Manager



# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing FLOOR 4/White House Meeting Room

Monthly..03/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 4</b>													
Corridor Room 442	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 448	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 454	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 460	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 466	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 474	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
Corridor Room 482	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/03/24	Santichai			
White House Meeting Room01	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
White House Meeting Room02	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
White House Meeting Room03	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
White House Meeting Room04	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
White House Meeting Room05	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			
White House Meeting Room KC x3	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/03/24	Santichai			Fire Blanket x2

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

*[Signature]*  
28/3/24

People & Culture Manager

*[Signature]*



ท.ห.

BOAT LAGOON  
PHUKET RESORT

## บันทึกการตรวจสอบปั้มน้ำดับเพลิง

รายละเอียดเครื่องสูบน้ำดับเพลิง (Electrical Fire Pump)

รหัส	ชนิด	ขนาด	สถานที่ติดตั้ง
TW-PF250M-2	ขม.1205	55 KW	ข.04

หัวข้อ	เกณฑ์การตรวจสอบ	ปกติ	ไม่ปกติ	หมายเหตุ
1	ตรวจสอบสภาพ seal เครื่องสูบน้ำ		✓	seal น้ำรั่วข้าง
2	ประเก็นหน้าวาล์วต่างๆ	✓		
3	วาล์วทางดูด (foot valve)	✓		
4	วาล์วทางดันจ่าย (discharge valve)	✓		
5	หลอดไฟสวิตช์หน้าตู้	✓		
6	ระดับความดันสั่งงานของ Pressure switch	✓		ระบุ 90
7	ระดับความดันของเครื่องสูบน้ำขณะทำงาน	✓		ระบุ 80-100
8	ระดับความดันหยุดการทำงาน Pressure switch	✓		ระบุ 120
9	ระดับเสียงมอเตอร์ขณะทำงาน	✓		
10	หน้าตู้ควบคุม (Auto start function On/off)	✓		
11	สภาพการทำงานมอเตอร์โดยรวม	✓		
12	อื่นๆ ระบุ			

รายละเอียดการชำรุด

seal ชำรุด (น้ำรั่วข้าง)

สาเหตุการชำรุด

( ) ใช้งาน (✓) หมดอายุ  
( ) อื่นๆ โปรดระบุ.....

ผู้รายงาน	นายสมชาย
ตำแหน่ง	หัวหน้างานช่างไฟฟ้า
วันที่	27/3/67

ข้อปฏิบัติ

ตรวจสอบเครื่องสูบน้ำดับเพลิง ทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที







## TEST RUN RECORD FOR EMERGENCY GENERATOR

DATE 24/3/67 ENGINEER สมชาย  
 GENERATOR 500 KVA LOCATION ลานกิจกรรม

### สภาพเครื่องก่อน TEST RUN

- ☒ ระดับน้ำมันเครื่อง (Motor Oil)
- ☒ สภาพสายพาน (Machine Belt)
- ☒ ระดับน้ำในหม้อน้ำ (Boiler)
- ☒ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

### TEST RUN

☐ ON LOAD ☒ OFF LOAD

TIME START 14.00 TIME STOP 15.00

รายการตรวจเช็ค		บันทึก
Oil (L.)		400 L
Voltage (V)	L1	230
Voltage (V)	L2	-
Voltage (V)	L3	229
Coolant Temp (°C)		70
Oil Pressure (bar)		3.58
Speed (RPM)		-
Frequency (Hz)		-
Battery (V)		27.1
Run Time (h)		587 h

### REMARK

น้ำมัน ๑๐๐ ลิตร ใช้ ๑๐๐ ลิตร







DATE 25/3/67 ENGINEER W. S. S.  
GENERATOR 1000 KVA LOCATION 320 Km





✓	ระดับน้ำมันเครื่อง (Motor Oil)
✓	สภาพสายพาน (Machine Bell)
✓	ระดับน้ำในหม้อน้ำ (Boiler)
✓	ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

☐ ON LOAD      ☒ OFF LOAD

TIME START ..... 16.10 ..... TIME STOP ..... 15.26 .....

รายการตรวจเช็ค		บันทึก
Oil (L.)		1800
Voltage (V)	L1	234
Voltage (V)	L2	234
Voltage (V)	L3	234
Coolant Temp (°C)		63
Oil Pressure (bar)		5.17
Speed (RPM)		1509
Frequency (Hz)		50.2
Battery (V)		27.4
Run Time (h)		2024.40m

REMARK





## TEST RUN RECORD FOR EMERGENCY GENERATOR

DATE 25/3/67 ENGINEER W. J. S. J.  
GENERATOR 400 KVA LOCATION near Hotel

สภาพเครื่องก่อน TEST RUN

- |                                     |                                    |
|-------------------------------------|------------------------------------|
| <input checked="" type="checkbox"/> | ระดับน้ำมันเครื่อง (Motor Oil)     |
| <input checked="" type="checkbox"/> | สภาพสายพาน (Machine Belt)          |
| <input checked="" type="checkbox"/> | ระดับน้ำในหม้อน้ำ (Boiler)         |
| <input checked="" type="checkbox"/> | ระดับน้ำกลั่นในแบตเตอรี่ (Battery) |

## TEST RUN

☐ ON LOAD      ☒ OFF LOAD

TIME START 15.20 TIME STOP 16.00

รายการตรวจเช็ค		บันทึก
Oil (L.)		10.5
Voltage (V)	L1	230
Voltage (V)	L2	230
Voltage (V)	L3	230
Coolant Temp (°C)		60
Oil Pressure (bar)		4
Speed (RPM)		1502
Frequency (Hz)		52
Battery (V)		28
Run Time (h)		1078.7h

REMARK

1





# NH

BOAT LAGOON  
PHUKET RESORT

## บันทึกการตรวจสอบระบบสัญญาณแจ้งเหตุฉุกเฉิน

### รายละเอียดของสัญญาณแจ้งเหตุฉุกเฉิน

รหัส

สถานที่ติดตั้ง

Hotel

วันที่ตรวจ 21/03/67	เกณฑ์การตรวจสอบ										ผู้ตรวจ
	สภาพจุดติดตั้ง		ปุ่มควบคุม		การส่งสัญญาณ		แหล่งจ่ายไฟสำรอง		สิ่งกีดขวาง		
	ปกติ	ชำรุด	ปกติ	ชำรุด	ปกติ	ไม่ปกติ	ปกติ	ไม่ปกติ	มี	ไม่มี	
1	✓		✓		✓		✓			✓	อนันต์
2											
3	✓		✓		✓		✓			✓	
4	✓		✓		✓		✓			✓	
5											
6	✓		✓		✓		✓			✓	
7	✓		✓		✓		✓			✓	
8	✓		✓		✓		✓			✓	
9	✓		✓		✓		✓			✓	
10	✓		✓		✓		✓			✓	
11	✓		✓		✓		✓			✓	
12	✓		✓		✓		✓			✓	
13	✓		✓		✓		✓			✓	
14	✓		✓		✓		✓			✓	
15	✓		✓		✓		✓			✓	
16	✓		✓		✓		✓			✓	
17											
18	✓		✓		✓		✓			✓	
19	✓		✓		✓		✓			✓	
20	✓		✓		✓		✓			✓	
21	✓		✓		✓		✓			✓	
22	✓		✓		✓		✓			✓	
23	✓		✓		✓		✓			✓	
24	✓		✓		✓		✓			✓	
25	✓		✓		✓		✓			✓	
26	✓		✓		✓		✓			✓	
27	✓		✓		✓		✓			✓	
28											
29	✓		✓		✓		✓			✓	

### รายละเอียดการชำรุด



กระดิ่งสัญญาณ



ปุ่มควบคุม

สาเหตุการชำรุด

( ) ใช้งาน

( ) หมดอายุ

( ) อื่นๆ

ผู้รายงาน

ตำแหน่ง


วันที่

ได้ส่งให้ช่าง  
ซ่อมแซมแล้ว  
22/3/67

### ข้อปฏิบัติ

ตรวจสอบสัญญาณแจ้งเหตุฉุกเฉินทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที





ชื่อลูกค้า Boat Lagoon Phuket Resort		เลขที่	
ที่อยู่		วันที่	19/03/2567
ติดต่อ		โทร	
ประเภทสินค้า Fire Alarm		แฟกซ์	
		<input type="checkbox"/> ระยะรับประกัน	<input type="checkbox"/> หมดรับประกัน
อาการที่แจ้ง			
PM ระบบ Fire Alarm			
ผลการตรวจสอบแก้ไข			
ทดสอบการทำงานของระบบ Fire Alarm และ Smoke Detector และ Manual Pull Station ของบริเวณ Corridor ชั้น 2,3 และ 4 (ทั้งหมด 90 ตัว) และสัญญาณไฟสัญญาณอยู่ 3 ตัว ดังนี้ 1.) smoke หน้าห้อง 461 เสียบ , 2.) smoke หน้าห้อง 265 เสียบ , 3.) smoke หน้าห้อง 267 เสียบ			
วิธีการแก้ไข			
ถอดเปลี่ยน smoke ที่ เสียบ ทั้ง 3 ตัว			
หมายเหตุ			
<input type="checkbox"/> ค่าบริการ บาท			
<input type="checkbox"/> ค่าอุปกรณ์ บาท			
<input type="checkbox"/> รับซ่อมอุปกรณ์ซ่อม		ผู้รับเงิน	
ลงชื่อ		ลงชื่อ	
19/3/24		19/03/67	
ลูกค้า		ช่างเทคนิค	
เริ่มเวลา 09.45 น.		เลิกงาน 16.25 น.	







บริษัท วีทีเอส เทคโนโลยี โซลูชั่น จำกัด

VTS TECHNOLOGY SOLUTION CO., LTD.

สำนักงานใหญ่ : 135/104 หมู่ที่ 5 ตำบลรัชฎา อำเภอเมือง จังหวัดภูเก็ต 83000

Tax.ID 0835552019691

## ใบรายงาน Service & Maintenance

เลขที่	
ชื่อลูกค้า <u>Boat Lagoon Phuket Resort</u>	วันที่ <u>20/03/2567</u>
ที่อยู่	แจ้งซ่อมวันที่
ติดต่อ	โทร
ประเภทสินค้า <u>Fire Alarm</u>	<input type="checkbox"/> ระบุรับประกัน <input type="checkbox"/> หมดรับประกัน
อาการที่แจ้ง	
<u>PM ระบบ Fire Alarm</u>	
<b>ผลการตรวจสอบแก้ไข</b>	
<u>ทดสอบการทำงานของระบบ Fire Alarm บริเวณ Lobby, Office และพื้นที่ส่วนกลาง รวมถึงอัปเดตตู้</u>	
<u>หน่วย 140, 142, 144, 145, 146, 147, 251, 252, 253, 255, 257, 275, 354, 360, 363, 374</u>	
<u>353, 446, 464, 465, 466, 469, 483, 485 รวมทั้งหมด 104 ตัว</u>	
<b>วิธีการแก้ไข</b>	
<b>หมายเหตุ</b>	
<input type="checkbox"/> ค่าบริการ	บาท
<input type="checkbox"/> ค่าอุปกรณ์	บาท
<input type="checkbox"/> รับซ่อมอุปกรณ์ซ่อม	ผู้รับเงิน
ลงชื่อ	ลงชื่อ
<u>[Signature]</u>	<u>[Signature]</u>
<u>20/3/2024</u>	<u>20/03/67</u>
ลูกค้า	ช่างเทคนิค
เริ่มเวลา <u>09.10</u> น.	เลิกงาน <u>15.45</u> น.



## ใบรายงาน Service & Maintenance

เลขที่	
ชื่อลูกค้า <u>Boat Lagoon Phuket Resort</u>	วันที่ <u>21/03/2567</u>
ที่อยู่	แจ้งซ่อมวันที่
ติดต่อ	โทร
ประเภทสินค้า <u>Fire Alarm</u>	<input type="checkbox"/> ระบุรับประกัน <input type="checkbox"/> หมดรับประกัน
อาการที่แจ้ง	
<u>PM ระบบ Fire Alarm</u>	
ผลการตรวจสอบแก้ไข	
<p>ทดสอบการทำงานของระบบ Fire Alarm บริเวณห้องประชุม , ลิฟต์ , ห้องผู้บริหาร และ corridor หน้าห้องพัก</p> <p>ชั้น 1 รวมถึงห้องพัก ดังต่อไปนี้ 141, 148, 240, 241, 242, 243, 254, 256, 272, 273, 340, 341, 342, 343, 344, 345, 346, 348, 353, 354, 357, 361, 364, 372, 440, 447, 449, 454, 455, 457, 467, 468, 470, 471, 472, 473, 475 รวมทั้งหมด 37 ห้อง (50 ตัว) และอุปกรณ์ส่วนกลาง 46 ตัว ทั้งหมดเป็น 96 ตัว ตรวจ Smoke Detector ชำรุด 3 ตัว 1) FB Office, 2) Fitness, 3) corridor</p>	
วิธีการแก้ไข	
<u>เปลี่ยนอุปกรณ์ที่ชำรุด 3 ตัวให้กลับมามีประสิทธิภาพ</u>	
หมายเหตุ	
<p>รวม 3 วัน เข้าทดสอบ ทดสอบในห้องพักได้ทั้งหมด 61 ห้อง</p> <p>และพื้นที่ส่วนกลางทั้งหมดที่มารักษาได้ จะเปลี่ยนกลางที่ส่ง ส่งไปได้อีกด้วย</p>	
<input type="checkbox"/> ค่าบริการ _____ บาท <input type="checkbox"/> ค่าอุปกรณ์ _____ บาท <input type="checkbox"/> รับซ่อมอุปกรณ์ซ่อม	<p>ผู้รับเงิน</p> <p>ลงชื่อ _____</p> <p>21/03/67</p> <p>ช่างเทคนิค</p>
<p>ลงชื่อ _____</p> <p>ลูกค้า</p>	<p>ลงชื่อ _____</p> <p>21/03/67</p> <p>ช่างเทคนิค</p>
<p>เริ่มเวลา <u>09.30</u> น. เลิกงาน <u>15.50</u> น.</p>	







บันทึกการตรวจสอบสภาพน้ำจายน้ำดับเพลิง

**รายละเอียดของหัวจ่ายดับเพลิง**

**รหัส**

ขนาดหัวจ่าย

สถานที่ติดตั้ง

## Note

วันที่ตรวจ	หมายเลขตู้	เกณฑ์การตรวจสอบ								ผู้ตรวจ
		วาวว/ประกัน (การรั่วซึม)		ตู้ดับเพลิง หัวฉีด/สายน้ำ		การจ่ายน้ำ		สิ่งกีดขวาง		
		ปกติ	ชำรุด	ปกติ	ชำรุด	ปกติ	ไม่ปกติ	มี	ไม่มี	
21/03/25	1	✓		✓		✓			✓	ผ่าน
	2	✓		✓		✓			✓	
	3	✓		✓		✓			✓	
	4	✓		✓		✓			✓	
	5	✓		✓		✓			✓	
	6	✓		✓		✓			✓	
	7	✓		✓		✓			✓	
	8	✓		✓		✓			✓	
	9	✓		✓		✓			✓	
	10	✓		✓		✓			✓	
	11	✓		✓		✓			✓	
	12	✓		✓		✓			✓	
	13									
	14		/	✓		✓			✓	
	15	✓		✓		✓			✓	
	16	✓		✓		✓			✓	
	17	✓		✓		✓			✓	
	18	✓		✓		✓			✓	
	19	✓		✓		✓			✓	
	20	✓		✓		✓			✓	
	21	✓		✓		✓			✓	
	22	✓		✓		✓			✓	
	23	✓		✓		✓			✓	
	24		/	✓		✓			✓	
	25	✓		✓		✓			✓	
	26	✓		✓		✓			✓	
	27	✓		✓		✓			✓	
	28	✓		✓		✓			✓	
	29	✓		✓		✓			✓	
ภาพหัวจ่ายน้ำดับเพลิง อุปกรณ์ และตู้ดับเพลิง										

ภาพหัวจ่ายน้ำดับเพลิง อุปกรณ์ และตู้ดับเพลิง

### รายละเอียดการชำระ

เลข 14 ตัวต่อจากเลข 12 คือ 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846

สาเหตุการขาด

( ) ใช้งาน

(✓)หมดอายุ

( ) อื่นๆ

---

ผู้รายงาน

ตำแหน่ง

วันที่

10/10/1967  
 22/3/67



**ข้อปฏิบัติ**

ตรวจสอบและลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที



## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building A

Monthly..04/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building A													
Side Steps													
Corridor Room 121	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Corridor Room 131	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Central Staircase													
Corridor Room 122	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Side Steps													
Corridor Room 124	NON-CFC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/04/24	Santichai			Dismantled
Corridor Room 137	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/04/24	Santichai			Dismantled
Facade of Building													
Corridor Room A21	NON-CFC	√	√	√	√	√	√	√	30/04/24	Santichai			
Behind the Building													
Corridor MDB Room	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			

Remark;

[√] Normal

[X] Abnormal

Loss Prevention Check

*[Signature]*  
80/04/24

People & Culture Manager

*[Signature]*

02 W.A. 2024



## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building B

Monthly..04/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building B													
Side Steps													
Corridor Room 221	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Corridor Room 231	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Central Staircase													
Corridor Room 222 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Corridor Room 233 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Side Steps													
Corridor Room 224	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Facade of Building													
Corridor Office 20/4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Behind the Building													
Corridor Office 20/1-4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
30/04/24

People & Culture Manager

 02 MAR 2024

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building C

Monthly..04/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building C													
Side Steps													
Corridor Room 321	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Corridor Room 331 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Central Staircase													
Corridor Room 322 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Corridor Room 334 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Side Steps													
Corridor Room 324	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Facade of Building													
Corridor Office 20/8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Behind the Building													
Corridor Office 20/5-8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
30/04/24

People & Culture Manager



02 M.A. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building D

Monthly..04/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building D													
Side Steps													
Corridor Room 421	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/04/24	Santichai			Dismantled
Corridor Room 431	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/04/24	Santichai			Dismantled
Central Staircase													
Corridor Room 422	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Corridor Room 434	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Side Steps													
Corridor Room 424	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Corridor Room 437	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Facade of Building													
Corridor Office 20/12	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Behind the Building													
Corridor Office 20/9-12 x2	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			

Remark;

[ ☒ ] Normal

[ ☐ ] Abnormal

Loss Prevention Check

  
30/04/24

People & Culture Manager



02 W.A. 2567



# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building E

Monthly..04/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building E													
Side Steps													
Corridor Room 521	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/04/24	Santichai			Dismantled
Corridor Room 531	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/04/24	Santichai			Dismantled
Central Staircase													
Corridor Room 522	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Corridor Room 534	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Side Steps													
Corridor Room 524	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Corridor Room 537	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Facade of Building													
Corridor Office 20/16	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Behind the Building													
Corridor Office 20/13-16 x2	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			

Remark;

[ ☒ ] Normal

[ ☐ ] Abnormal

Loss Prevention Check

  
30/04/24

People & Culture Manager

 02 W.A. 2567



## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building F

Monthly..04/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building F													
Side Steps													
Corridor Room 621	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Corridor Room 631	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Central Staircase													
Corridor Room 623	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Corridor Room 633	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Side Steps													
Corridor Room 624	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Corridor Room 637	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Facade of Building													
Corridor Office 20/20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Behind the Building													
Corridor Office 20/17-20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
30/04/24

People & Culture Manager

 02 W.A. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building G

Monthly..04/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building G													
Side Steps													
Corridor Room 721	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Corridor Room 731	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Central Staircase													
Corridor Room 722	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Corridor Room 733	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Side Steps													
Corridor Room 724	Chemical Powder-ABC	X	√	√	√	√	√	√	30/04/24	Santichai	27/02/24		Pressure down
Corridor Room 737	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Facade of Building													
Corridor Office 20/24	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Behind the Building													
Corridor Office 20/21-24 x2	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			

Remark;

[ √ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
30/04/24

People & Culture Manager

 02 M.A. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building G

Monthly..04/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building H													
Side Steps													
Corridor Room 925	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Corridor Room 933	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Side Steps													
Corridor Room 924	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Corridor Room 927	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Facade of Building													
Corridor Office 20/26	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			
Behind the Building													
Corridor Office 20/25-26 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/04/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
30/04/24

People & Culture Manager

 02 M.A. 2567



**NH BOAT LAGOON PHUKET RESORT**  
**Check List Fire Extinguisher Building G**

**Monthly..04/2024**

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building I													
Side Steps													
Corridor Room 923	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Corridor Room 935	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Side Steps													
Corridor Room 936	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Corridor Room 949	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Facade of Building													
Corridor Office 20/27	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			
Behind the Building													
Corridor Office 20/26-27 x2	Chemical Powder-ABC	√	√	√	√	√	√	√	30/04/24	Santichai			

Remark;


[√] Normal

[X] Abnormal

Loss Prevention Check

  
30/04/24

People & Culture Manager

  
02 W.A. 2567



# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing Floor 1, Restaurant, Lobby

Monthly..04/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
FLOOR 1													
Loading x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Accounting Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Female Locker	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Canteen Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			Fire Blanket x1
Main Kitchen x2	Chemical -ABCDK	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			Fire Blanket x2
Electrical Control Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Captain Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Lift Main Kitchen x2	Chemical Powder-AK	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Bai-Ruer Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Boat Point Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Loss & Prevention Office	NON-CFC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Generator Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Gas Store	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss Prevention Check

  
29/04/24

People & Culture Manager

 02 W.A. 2567

**NH BOAT LAGOON PHUKET RESORT**  
**Check List Fire Extinguisher Hotel Wing FLOOR 2,3**

**Monthly..04/2024**


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 2</b>													
Corridor Room 242	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 250	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 256	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 264	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 272	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
<b>FLOOR 3</b>													
Corridor Room 342	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 348	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 352	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
CorridorRoom 358	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 364	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 372	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 380	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

  
30/04/24

People & Culture Manager

 02 W.A. 2567



# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing FLOOR 4/White House Meeting Room

Monthly..04/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
FLOOR 4													
Corridor Room 442	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 448	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 454	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 460	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 466	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 474	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
Corridor Room 482	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
White House Meeting Room01	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
White House Meeting Room02	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
White House Meeting Room03	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
White House Meeting Room04	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
White House Meeting Room05	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			
White House Meeting Room KC x3	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	25/04/24	Santichai			Fire Blanket x2

Remark;

[✓] Normal

[X] Abnormal

Loss Prevention Check

*[Signature]*  
30/04/24

People & Culture Manager

*[Signature]*

02 W.A. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

Apr-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by

Supervisor by \_\_\_\_\_

Date

.Date



## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

Apr-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by

Supervisor by \_\_\_\_\_

Date.....05/4/

Date: 2/5/8

Apr-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by Qamar ul Huda Date 25/4/67

Supervisor by Leinhardt T. N. K. e Date 2/5/67

### Check List emergency light

[illegible]

(2) = Emergency Light

Supervisor by సీనియర్ ఇంజనీర్ Date 2/5/67

## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

Apr-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by Adnan Sidiq Date 27/4/67

Supervisor by பெரியசாமி சகலா Date 15/67



## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

Apr-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by

Supervisor by \_\_\_\_\_

Responsible by Syner Datt Date 27/4/67

Supervisor by revised 5/15/67 Date 2/15/67

NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

Apr-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by Samer S. S. S. Date 27/4/67.

Supervisor by Wing Commander S. S. S. S. Date 21/5/67

## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

Apr-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by APB Date 26/3/07

Supervisor by leindan [Signature] Date 2/3/07

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Apr-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 241 (Fire Exit)	✓	✓	✓	✓	✓	25/01/67	มณฑิระ วัฒนศิริ	✓			
Room 241 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 246 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 246 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 252 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 252 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 263 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 263 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 269 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 269 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 274 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 274 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 247 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 247 (Emergency)	✓	✓	✓	✓	✓			✓			

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

Responsible by ..... มณฑิระ วัฒนศิริ ..... Date 25/01/67

Supervisor by ..... วัฒนศิริ วัฒนศิริ ..... Date 2/5/67



# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Apr-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 341 (Fire Exit)	✓	✓	✓	✓	✓	15/01/67	Dharmak	✓			
Room 341 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 346 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 346 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 355 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 355 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 360 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 360 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 371 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 371 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 377 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 377 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 382 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 382 (Emergency)	✓	✓	✓	✓	✓			✓			

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

Responsible by ..... Date 15/01/67

Supervisor by ..... Date 2/5/67

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

Apr-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 441 (Fire Exit)	✓	✓	✓	✓	✓	25/01/67	Dhansin	✓			
Room 441 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 446 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 446 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 456 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 456 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 462 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 462 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 473 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 473 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 479 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 479 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 484 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 484 (Emergency)	✓	✓	✓	✓	✓			✓			

Note: Mark [✓] Normal

Mark (X) Abnormal

Responsible by ..... Dhansin ..... Date 25/01/67

Supervisor by ..... Saisak Sae ..... Date 2/5/67

## TEST RUN RECORD FOR EMERGENCY GENERATOR

GATE ..... 20/4/62 ..... ENGINEER ..... นาย .....  
 GENERATOR ..... 800 KVA ..... LOCATION ..... ข. 195 .....

### สภาพเครื่องก่อน TEST RUN

- ☒ ระดับน้ำมันเครื่อง (Motor Oil)  
☒ สภาพสายพาน (Machine Belt)  
☒ ระดับน้ำในหม้อน้ำ (Boiler)  
☒ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

### TEST RUN

☐ ON LOAD ☒ OFF LOAD

TIME START ..... 13:30 ..... TIME STOP ..... 14:30 .....

รายการตรวจเช็ค		บันทึก	REMARK
Oil (L.)		10.5	
Voltage (V)	L1	233	
Voltage (V)	L2	233	
Voltage (V)	L3	232	
Coolant Temp (°C)		60	
Oil Pressure (bar)		4	
Speed (RPM)		1500	
Frequency (Hz)		50	
Battery (V)		28	
Run Time (h)		107.5h	





บันทึกการตรวจสอบปั้มน้ำดับเพลิง

รายละเอียดเครื่องสูบน้ำดับเพลิง (Electrical Fire Pump)  
รหัส: TU-1500m-2    ชนิด: 30HP    ขนาด: 15-16KW    สถานที่ติดตั้ง: บ่อ 4

หัวข้อ	เกณฑ์การตรวจสอบ	ปกติ	ไม่ปกติ	หมายเหตุ
1	ตรวจสอบสภาพ seal เครื่องสูบน้ำ	/		
2	ประเก็นหน้าวาล์วต่างๆ	/		
3	วาล์วทางด้านดูด (foot valve)	/		
4	วาล์วทางด้านจ่าย (discharge valve)	/		
5	หลอดไฟสวิตช์หน้าตู้		/	ฉนวนชำรุด
6	ระดับความดันสั่งงานของ Pressure switch		/	ระบบ
7	ระดับความดันของเครื่องสูบน้ำขณะทำงาน		/	ระบบ
8	ระดับความดันหยุดการทำงานของ Pressure switch		/	ระบบ
9	ระดับเสียงมอเตอร์ขณะทำงาน		/	เสียงดัง
10	หน้าตู้ควบคุม (Auto start function On/off)	/		
11	สภาพการทำงานมอเตอร์โดยรวม	/		
12	อื่นๆ ระบบ		/	ใบรณกอส 16

รายละเอียดการชำรุด  
พบรอยรั่วที่ตู้ควบคุม

สาเหตุการชำรุด  
( ) ใช้งาน ( ) หมดอายุ  
( ) อื่นๆ โปรดระบุ.....  
ผู้รายงาน: วิศวกร  
ตำแหน่ง: วิศวกร  
วันที่: 25/4/67

ข้อปฏิบัติ  
ตรวจสอบเครื่องสูบน้ำดับเพลิง ทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง  
หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที





**บันทึกการตรวจสอบระบบสัญญาณแจ้งเหตุฉุกเฉิน**

รายละเอียดของสัญญาณแจ้งเหตุฉุกเฉิน

รหัส

### สถานที่ติดตั้ง

วันที่ตรวจ 18/04/67	เกณฑ์การตรวจสอบ										ผู้ตรวจ
	สภาพจุดติดตั้ง		ปุ่มควบคุม		การส่งสัญญาณ		แหล่งจ่ายไฟสำรอง		สิ่งกีดขวาง		
	ปกติ	ชำรุด	ปกติ	ชำรุด	ปกติ	ไม่ปกติ	ปกติ	ไม่ปกติ	มี	ไม่มี	
1	/		/		/		/			/	
2											
3	/		/		/		/			/	
4	/		/		/		/			/	
5	/		/		/		/			/	
6	/		/		/		/			/	
7	/		/		/		/			/	
8	/		/		/		/			/	
9	/		/		/		/			/	
10	/		/		/		/			/	
11	/		/		/		/			/	
12	/		/		/		/			/	
13											
14											
15	/		/		/		/			/	
16	/		/		/		/			/	
17											
18	/		/		/		/			/	
19	/		/		/		/			/	
20	/		/		/		/			/	
21	/		/		/		/			/	
22	/		/		/		/			/	
23	/		/		/		/			/	
24	/		/		/		/			/	
25	/		/		/		/			/	
26	/		/		/		/			/	
27	/		/		/		/			/	
28											
29	/		/		/		/			/	
			/		/		/			/	



กระตังสัญญาณ



ปุ่มควบคุม

รายละเอียดการชำระ

สาเหตุการขาด
--------------

( ) ไข้งาน

( )หมดอายุ

( ) อื่นๆ

ผู้รายงาน

ตำแหน่ง

วันที่

**ข้อปฏิบัติ**

ตรวจสอบสัญญาจ้างเหตฉุกเฉิน**ทุกเดือน** และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที







## TEST RUN RECORD FOR EMERGENCY GENERATOR

GATE 261A/67 ENGINEER mark  
 GENERATOR 1000 KVA LOCATION 3,50m5

### สภาพเครื่องก่อน TEST RUN

- ☒ ระดับน้ำมันเครื่อง (Motor Oil)
- ☒ สภาพสายพาน (Machine Bell)
- ☒ ระดับน้ำในหม้อน้ำ (Boiler)
- ☒ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

### TEST RUN

☐ ON LOAD ☒ OFF LOAD

TIME START 16.19 TIME STOP 17.28

รายการตรวจเช็ค		บันทึก
Oil (L.)		1800
Voltage (V)	L1	236
Voltage (V)	L2	236
Voltage (V)	L3	236
Coolant Temp (°C)		63
Oil Pressure (bar)		0.14
Speed (RPM)		1509
Frequency (Hz)		50.2
Battery (V)		27.4
Run Time (h)		20440

REMARK

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....



## TEST RUN RECORD FOR EMERGENCY GENERATOR

GATE 266/167 ENGINEER กฤษ  
 GENERATOR 500 kVA LOCATION ต.น.ก.อ.ส.ส.อ.

### สภาพเครื่องก่อน TEST RUN

- ☒ ระดับน้ำมันเครื่อง (Motor Oil)
- ☒ สภาพสายพาน (Machine Belt)
- ☒ ระดับน้ำในหม้อน้ำ (Boiler)
- ☒ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

### TEST RUN


☐ ON LOAD ☒ OFF LOAD

TIME START 14:20 TIME STOP 15:25

รายการตรวจเช็ค		บันทึก
Oil (L.)		400 L
Voltage (V)	L1	290
Voltage (V)	L2	-
Voltage (V)	L3	292
Coolant Temp (°C)		70
Oil Pressure (bar)		4.56
Speed (RPM)		-
Frequency (Hz)		-
Battery (V)		27.0
Run Time (h)		52h

### REMARK

ไม่พบปัญหา





ทห

BOAT LAGOON  
PHUKET RESORT

บันทึกการตรวจสอบสภาพหัวจ่ายน้ำดับเพลิง

รายละเอียดของหัวจ่ายดับเพลิง

รหัส		ขนาดหัวจ่าย		สถานที่ติดตั้ง						
วันที่ตรวจ	หมายเลขตู้	เกณฑ์การตรวจสอบ								ผู้ตรวจ
		วาวว/ประเก็น (การรั่วซึม)		ตู้ดับเพลิง หัวฉีด/สายน้ำ		การจ่ายน้ำ		สิ่งกีดขวาง		
		ปกติ	ชำรุด	ปกติ	ชำรุด	ปกติ	ไม่ปกติ	มี	ไม่มี	
7/10/67	1	/		/		/			/	สุวิทย์
	2	/		/		/			/	
	3	/		/		/			/	
	4	/		/		/			/	
	5	/		/		/			/	
	6	/		/		/			/	
	7	/		/		/			/	
	8	/		/		/			/	
	9	/		/		/			/	
	10	/		/		/			/	
	11	/		/		/			/	
	12	/		/		/			/	
	13	/		/		/			/	
	14	/		/		/			/	
	15	/		/		/			/	
	16	/		/		/			/	
	17	/		/		/			/	
	18	/		/		/			/	
	19	/		/		/			/	
	20	/		/		/			/	
	21	/		/		/			/	
	22	/		/		/			/	
	23	/		/		/			/	
	24	/	/	/		/			/	
	25	/		/		/			/	
	26	/		/		/			/	
	27	/		/		/			/	
	28	/		/		/			/	
	29	/		/		/			/	สุวิทย์
ภาพหัวจ่ายน้ำดับเพลิง อุปกรณ์ และตู้ดับเพลิง										
รวมคะแนนการตรวจสอบ										

ภาพหัวจ่ายน้ำดับเพลิง อุปกรณ์ และตู้ดับเพลิง



รายละเอียดการชำรุด

กลุ่มหมอก 24 มีสภาพดีไม่มีชำรุดเสียหาย  
เจ้าหน้าที่ตรวจ

สาเหตุการชำรุด

( ) ใช้งาน

( ) หมดอายุ

( ) อื่นๆ

ผู้รายงาน

ตำแหน่ง

วันที่

สุวิทย์ เกษม

ช่างไฟฟ้า

7/10/67

ข้อปฏิบัติ

ตรวจสอบสภาพหัวจ่ายน้ำดับเพลิง ทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที



## NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

May-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by gman 5572 Date 30/5/67

Supervisor by Winters Date 3/21/67

## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

May-24

[illegible]

Note:Mark [ ✓ ] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by

Responsible by gymnast bawls Date 30/5/67

Supervisor by \_\_\_\_\_

Supervisor by 10/1/07 Date 3/15/07



## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

May-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by

Supervisor by \_\_\_\_\_

Date.....

Date 31/5

## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

May-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by গণনা সিস্টেম Date ২০/১/১৭

Supervisor by .....Date 92/5/67

## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

May-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by สมชาย ใจดี Date 30/5/67

Supervisor by 12/20/05 Date 3/15/07

## NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

May-24

[illegible]

Note:Mark [ ✓ ] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by gordon <sup>597</sup> <sub>597</sub> Date 30/5/67

Supervisor by Leni Wank Date 31/5/67



## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

May-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by

Supervisor by \_\_\_\_\_

.....Date 30/4/67

revised Date: 9/15/67

NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

May-24

[illegible]

Note:Mark [ ✓ ] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by gmm gnt Date 30/5/67

Supervisor by                      Date 37/5/67

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

May-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 241 (Fire Exit)	/	/	/	/	/			/			
Room 241 (Emergency)	/	/	/	/	/			/			
Room 246 (Fire Exit)	/	/	/	/	/			/			
Room 246 (Emergency)	/	/	/	/	/			/			
Room 252 (Fire Exit)	/	/	/	/	/			/			
Room 252 (Emergency)	/	/	/	/	/	30/5/67	gndor	/			
Room 263 (Fire Exit)	/	/	/	/	/			/			
Room 263 (Emergency)	/	/	/	/	/			/			
Room 269 (Fire Exit)	/	/	/	/	/			/			
Room 269 (Emergency)	/	/	/	/	/			/			
Room 274 (Fire Exit)	/	/	/	/	/			/			
Room 274 (Emergency)	/	/	/	/	/			/			
Room 247 (Fire Exit)	/	/	/	/	/			/			
Room 247 (Emergency)	/	/	/	/	/			/			

Note:Mark [ √ ] Normal

Mark (X) Abnormal

Responsible by .....gndor 30/5/67

Supervisor by .....wirod 31/5/67

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

May-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 341 (Fire Exit)	/	/	/	/	/	30/5/67	gmon	/			
Room 341 (Emergency)	/	/	/	/	/			/			
Room 346 (Fire Exit)	/	/	/	/	/			/			
Room 346 (Emergency)	/	/	/	/	/			/			
Room 355 (Fire Exit)	/	/	/	/	/			/			
Room 355 (Emergency)	/	/	/	/	/			/			
Room 360 (Fire Exit)	/	/	/	/	/			/			
Room 360 (Emergency)	/	/	/	/	/			/			
Room 371 (Fire Exit)	/	/	/	/	/			/			
Room 371 (Emergency)	/	/	/	/	/			/			
Room 377 (Fire Exit)	/	/	/	/	/			/			
Room 377 (Emergency)	/	/	/	/	/			/			
Room 382 (Fire Exit)	✓	✓	✓	✓	✓			/			
Room 382 (Emergency)	✓	✓	✓	✓	✓			/			

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

Responsible by gmon 555 Date 30/5/67  
 Supervisor by Leinab Date 31/5/67



# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

May-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 441 (Fire Exit)	✓	✓	✓	✓	✓	30/5/67	สมชาย	✓			
Room 441 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 446 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 446 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 456 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 456 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 462 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 462 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 473 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 473 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 479 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 479 (Emergency)	✓	✓	✓	✓	✓			✓			
Room 484 (Fire Exit)	✓	✓	✓	✓	✓			✓			
Room 484 (Emergency)	✓	✓	✓	✓	✓			✓			

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

Responsible by

สมชาย 30/5/67

Supervisor by

31/5/67

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building A

Monthly..05/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building A</b>													
Side Steps													
Corridor Room 121	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 131	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Central Staircase													
Corridor Room 122	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Side Steps													
Corridor Room 124	NON-CFC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/05/24	Santichai			Dismantled
Corridor Room 137	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/05/24	Santichai			Dismantled
Facade of Building													
Corridor Room A21	NON-CFC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Behind the Building													
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss & Prevention Check

*AS*  
*30/05/24*

People & Culture Manager

*hon*

05 มิ.ย. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building B

Monthly..05/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building B</b>													
Side Steps													
Corridor Room 221	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 231	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 222 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 233 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Side Steps													
Corridor Room 224	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Facade of Building													
Corridor Office 20/4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Behind the Building													
Corridor Office 20/1-4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss & Prevention Check

*[Signature]*  
20/05/24

People & Culture Manager

*[Signature]*

05.05.2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building C

Monthly..05/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building C</b>													
Side Steps													
Corridor Room 321	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 331 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 322 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 334 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Side Steps													
Corridor Room 324	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Facade of Building													
Corridor Office 20/8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Behind the Building													
Corridor Office 20/5-8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

  
00/05/24

People & Culture Manager



05 0.0. 2567



## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building D

Monthly..05/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building D</b>													
<b>Side Steps</b>													
Corridor Room 421	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/05/24	Santichai			Dismantled
Corridor Room 431	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/05/24	Santichai			Dismantled
<b>Central Staircase</b>													
Corridor Room 422	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 434	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
<b>Side Steps</b>													
Corridor Room 424	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 437	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
<b>Facade of Building</b>													
Corridor Office 20/12	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
<b>Behind the Building</b>													
Corridor Office 20/9-12 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			

Remark;


[ **✓** ] Normal

[ **X** ] Abnormal

Loss & Prevention Check

  
30/5/24

People & Culture Manager

 05.05.2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building E

Monthly..05/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building E</b>													
Side Steps													
Corridor Room 521	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/05/24	Santichai			Dismantled
Corridor Room 531	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/05/24	Santichai			Dismantled
<b>Central Staircase</b>													
Corridor Room 522	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 534	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Side Steps													
Corridor Room 524	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 537	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Facade of Building													
Corridor Office 20/16	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Behind the Building													
Corridor Office 20/13-16 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

*AS*  
*00/05/24*

People & Culture Manager

*1000*  
05.08.2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building F

Monthly..05/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building F													
Side Steps													
Corridor Room 621	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 631	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Central Staircase													
Corridor Room 623	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 633	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Side Steps													
Corridor Room 624	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 637	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Facade of Building													
Corridor Office 20/20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Behind the Building													
Corridor Office 20/17-20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

*[Signature]*  
0015/24

People & Culture Manager

*[Signature]*

05 มิ.ย. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building G

Monthly..05/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building G													
Side Steps													
Corridor Room 721	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 731	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Central Staircase													
Corridor Room 722	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 733	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Side Steps													
Corridor Room 724	Chemical Powder-ABC	X	✓	✓	✓	✓	✓	✓	30/05/24	Santichai	27/02/24		Pressure down
Corridor Room 737	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Facade of Building													
Corridor Office 20/24	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Behind the Building													
Corridor Office 20/21-24 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

  
30/3/24

People & Culture Manager



05 ส.อ. 2567



# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building G

Monthly..05/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building H													
Side Steps													
Corridor Room 925	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 933	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Side Steps													
Corridor Room 924	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 927	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Facade of Building													
Corridor Office 20/26	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Behind the Building													
Corridor Office 20/25-26 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

*[Signature]*  
30/5/24

People & Culture Manager

*[Signature]*

05.08.2024

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building G

Monthly..05/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building I													
Side Steps													
Corridor Room 923	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 935	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Side Steps													
Corridor Room 936	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Corridor Room 949	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Facade of Building													
Corridor Office 20/27	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			
Behind the Building													
Corridor Office 20/26-27 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/05/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss & Prevention Check

*AS*  
30/5/24

People & Culture Manager

*Pro*

05 ส.ค. 2567

**NH BOAT LAGOON PHUKET RESORT**  
**Check List Fire Extinguisher Hotel Wing Floor 1, Restaurant, Lobby**

Monthly..05/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 1</b>													
Loading x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Accounting Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Female Locker	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Canteen Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			Fire Blanket x1
Main Kitchen x2	Chemical -ABCDK	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			Fire Blanket x2
Electrical Control Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Captain Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Lift Main Kitchen x2	Chemical Powder-AK	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Bai-Ruer Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Boat Point Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Loss & Prevention Office	NON-CFC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Generator Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Gas Store	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss & Prevention Check

  
30/5/24

People & Culture Manager



05 มิ.ย. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing FLOOR 2,3

Monthly..05/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 2</b>													
Corridor Room 242	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 250	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 256	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 264	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 272	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Front Office	Chemical Powder-ABC	X	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			Pressure down
<b>FLOOR 3</b>													
Corridor Room 342	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 348	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 352	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 358	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 364	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 372	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 380	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss & Prevention Check

*[Signature]*  
30/5/24

People & Culture Manager

*[Signature]*

05 0.0. 2567



# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing FLOOR 4/White House Meeting Room

Monthly..05/2024


Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 4</b>													
Corridor Room 442	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 448	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 454	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 460	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 466	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 474	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
Corridor Room 482	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
White House Meeting Room01	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
White House Meeting Room02	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
White House Meeting Room03	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
White House Meeting Room04	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
White House Meeting Room05	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			
White House Meeting Room KC x3	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	29/05/24	Santichai			Fire Blanket x2

Remark;


[ **V** ] Normal

[ **X** ] Abnormal

Loss & Prevention Check

  
20/5/24

People & Culture Manager



05 ส.อ. 2567

**ทห**

BOAT LAGOON  
PHUKET RESORT

## บันทึกการตรวจสอบปั้มน้ำดับเพลิง

รายละเอียดเครื่องสูบน้ำดับเพลิง (Electrical Fire Pump)

รหัส	ชนิด	ขนาด	สถานที่ติดตั้ง
400802	TU-DF250M-2	5.5 kW	ชั้นที่ 10

หัวข้อ	เกณฑ์การตรวจสอบ	ปกติ	ไม่ปกติ	หมายเหตุ
1	ตรวจสอบสภาพ seal เครื่องสูบน้ำ	✓		
2	ประเก็นหน้าวาล์วต่างๆ	✓		
3	วาล์วทางด้านดูด (foot valve)	✓		
4	วาล์วทางด้านจ่าย (discharge valve)	✓		
5	หลอดไฟสวิตช์หน้าตู้	✓		
6	ระดับความดันสั่งงานของ Pressure switch	✓		ระบุ
7	ระดับความดันของเครื่องสูบน้ำขณะทำงาน		✓	ระบุ
8	ระดับความดันหยุดการทำงานของ Pressure switch		✓	ระบุ
9	ระดับเสียงมอเตอร์ขณะทำงาน		✓	
10	หน้าตู้ควบคุม (Auto start function On/off)	✓		
11	สภาพการทำงานมอเตอร์โดยรวม		✓	
12	อื่นๆ ระบุ			

รายละเอียดการชำรุด

เมื่อก่อนเมื่อก่อน ไม่ชำรุด ทนแรง 5 ตัน 5009  
20120512 (กรณีฉุกเฉิน)

สาเหตุการชำรุด

(✓)ใช้งาน (✓)หมดอายุ  
( )อื่นๆโปรดระบุ.....

ผู้รายงาน ดนตรีโก หักทวิ  
ตำแหน่ง วิศวกร  
วันที่ 23/05/67

ข้อปฏิบัติ

ตรวจสอบเครื่องสูบน้ำดับเพลิง ทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จ.ป.ทันที





# TEST RUN RECORD FOR EMERGENCY GENERATOR

DATE 25/5/67 ENGINEER เอนจิเนียร์  
GENERATOR 800 KVA LOCATION R 135 ไอเดีย

## สภาพเครื่องก่อน TEST RUN

- ☒ ระดับน้ำมันเครื่อง (Motor Oil)
- ☒ สภาพสายพาน (Machine Belt)
- ☒ ระดับน้ำในหม้อน้ำ (Boiler)
- ☒ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

## TEST RUN

☒ ON LOAD ☐ OFF LOAD

TIME START 13.30 TIME STOP 14.30

รายการตรวจเช็ค		บันทึก
Oil (L.)		<u>1050</u>
Voltage (V)	L1	<u>400</u>
Voltage (V)	L2	<u>400</u>
Voltage (V)	L3	<u>400</u>
Coolant Temp (°C)		<u>65</u>
Oil Pressure (bar)		<u>4</u>
Speed (RPM)		<u>1500</u>
Frequency (Hz)		<u>52</u>
Battery (V)		<u>28</u>
Run Time (h)		<u>1090.1</u>

REMARK

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....



## TEST RUN RECORD FOR EMERGENCY GENERATOR

DATE 29/5/67 ENGINEER วิน พันธ์  
GENERATOR 500KVA LOCATION หมู่ที่ ๑๓ ตำบล

## สภาพเครื่องก่อน TEST RUN

- |                                     |                                    |
|-------------------------------------|------------------------------------|
| <input checked="" type="checkbox"/> | ระดับน้ำมันเครื่อง (Motor Oil)     |
| <input checked="" type="checkbox"/> | สภาพสายพาน (Machine Belt)          |
| <input checked="" type="checkbox"/> | ระดับน้ำในหม้อน้ำ (Boiler)         |
| <input checked="" type="checkbox"/> | ระดับน้ำกลั่นในแบตเตอรี่ (Battery) |

## TEST RUN

☒ ON LOAD      ☐ OFF LOAD

TIME START 18.46 TIME STOP 14.25

รายการตรวจเช็ค		บันทึก
Oil (L.)		25%
Voltage (V)	L1	997
Voltage (V)	L2	-
Voltage (V)	L3	404
Coolant Temp (°C)		70.
Oil Pressure (bar)		9.23
Speed (RPM)		-
Frequency (Hz)		-
Battery (V)		27.2
Run Time (h)		-

REMARK

ความสูง น้ำหนัก ไม่สามารถ  
วัดได้ ขณะวัด

เดือนมีนาคม 2001

251 → 727

## TEST RUN RECORD FOR EMERGENCY GENERATOR

DATE 22/5/67 ENGINEER ชุตาน  
 GENERATOR 1000 KVA LOCATION 3508th

### สภาพเครื่องก่อน TEST RUN

- ☒ ระดับน้ำมันเครื่อง (Motor Oil)
- ☒ สภาพสายพาน (Machine Belt)
- ☒ ระดับน้ำในหม้อน้ำ (Boiler)
- ☒ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

### TEST RUN

☐ ON LOAD ☐ OFF LOAD



TIME START ..... TIME STOP .....

รายการตรวจเช็ค		บันทึก
Oil (L.)		17.20
Voltage (V)	L1	-
Voltage (V)	L2	-
Voltage (V)	L3	-
Coolant Temp (°C)		-
Oil Pressure (bar)		-
Speed (RPM)		-
Frequency (Hz)		-
Battery (V)		-
Run Time (h)		-


### REMARK

ทำงานปกติ และ ใช้น้ำกลั่น

















บันทึกการตรวจสอบระบบสัญญาณแจ้งเหตุฉุกเฉิน

รายละเอียดของสัญญาณแจ้งเหตุฉุกเฉิน

รหัส

สถานที่ติดตั้ง

วันที่ตรวจ	เกณฑ์การตรวจสอบ										ผู้ตรวจ
	สภาพจุดติดตั้ง		ปุ่มควบคุม		การส่งสัญญาณ		แหล่งจ่ายไฟสำรอง		สิ่งกีดขวาง		
	ปกติ	ชำรุด	ปกติ	ชำรุด	ปกติ	ไม่ปกติ	ปกติ	ไม่ปกติ	มี	ไม่มี	
22/5/66											
1	✓		✓		✓		✓			✓	
2											
3	✓		✓		✓		✓			✓	
4	✓		✓		✓		✓			✓	
5	✓		✓		✓		✓			✓	
6	✓		✓		✓		✓			✓	
7	✓		✓		✓		✓			✓	
8	✓		✓		✓		✓			✓	
9	✓		✓		✓		✓			✓	
10	✓		✓		✓		✓			✓	
11	✓		✓		✓		✓			✓	
12	✓		✓		✓		✓			✓	
13											
14											
15	✓		✓		✓		✓			✓	
16	✓		✓		✓		✓			✓	
17											
18	✓		✓		✓		✓			✓	
19	✓		✓		✓		✓			✓	
20	✓		✓		✓		✓			✓	
21	✓		✓		✓		✓			✓	
22	✓		✓		✓		✓			✓	
23	✓		✓		✓		✓			✓	
24	✓		✓		✓		✓			✓	
25	✓		✓		✓		✓			✓	
26	✓		✓		✓		✓			✓	
27	✓		✓		✓		✓			✓	
28											
29	✓		✓		✓		✓			✓	

รายละเอียดการชำรุด



กระดิ่งสัญญาณ



ปุ่มควบคุม

สาเหตุการชำรุด

( ) ใช้งาน

( ) หมดอายุ

( ) อื่นๆ

ผู้รายงาน

ตำแหน่ง


วันที่

อ.ก. วิชาพร หักทอ  
ช่างไฟฟ้า  
22/05/17

ข้อปฏิบัติ

ตรวจสอบสัญญาณแจ้งเหตุฉุกเฉินทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้ป.ทันที





นท

BOAT LAGOON  
PHUKET RESORT

บันทึกการตรวจสอบสภาพหัวจ่ายน้ำดับเพลิง

รายละเอียดของหัวจ่ายน้ำดับเพลิง

รหัส		ขนาดหัวจ่าย				สถานที่ติดตั้ง				
วันที่ตรวจ	หมายเลขตู้	เกณฑ์การตรวจสอบ								ผู้ตรวจ
		วาวว/ประเก็น (การรั่วซึม)		ตู้ดับเพลิง หัวฉีด/สายน้ำ		การจ่ายน้ำ		สิ่งกีดขวาง		
		ปกติ	ชำรุด	ปกติ	ชำรุด	ปกติ	ไม่ปกติ	มี	ไม่มี	
๑๑/๗/๖๔	1	✓		✓		✓			✓	
	2	✓		✓		✓			✓	
	3									
	4	✓		✓		✓			✓	
	5	✓		✓		✓			✓	
	6	✓		✓		✓			✓	
	7	✓		✓		✓			✓	
	8	✓		✓		✓			✓	
	9	✓		✓		✓			✓	
	10	✓		✓		✓			✓	
	11	✓		✓		✓			✓	
	12	✓		✓		✓			✓	
	13	✓		✓		✓			✓	
	14	✓		✓		✓			✓	
	15	✓		✓		✓			✓	
	16	✓		✓		✓			✓	
	17	✓		✓		✓			✓	
	18	✓		✓		✓			✓	
	19	✓		✓		✓			✓	
	20	✓		✓		✓			✓	
	21	✓		✓		✓			✓	
	22	✓		✓		✓			✓	
	23	✓		✓		✓			✓	
	24		✓	✓		✓			✓	
	25	✓		✓		✓			✓	
	26	✓		✓		✓			✓	
	27	✓		✓		✓			✓	
	28	✓		✓		✓			✓	
	29	✓		✓		✓			✓	
ภาพหัวจ่ายน้ำดับเพลิง อุปกรณ์ และตู้ดับเพลิง										

ภาพหัวจ่ายน้ำดับเพลิง อุปกรณ์ และตู้ดับเพลิง



รายละเอียดการชำรุด

ตู้หมายเลข 24 มีรอยร้าวที่หัวฉีด  
แก้ไขแล้ว

สาเหตุการชำรุด

( ) ใช้งาน

( ) หมดอายุ

(x) อื่นๆ

ผู้รายงาน

ตำแหน่ง

วันที่

7 อุบลรัตน์ แก้วท้อ  
ช่างไฟฟ้า  
22/05/67

ข้อปฏิบัติ

ตรวจสอบสภาพหัวจ่ายน้ำดับเพลิง ทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที







Global Marine Tech Co.,Ltd.

58/115 Moo 6 Phoemsin thani village T.Ratsada, A.Muangphuket, Phuket 83000 Thailand

Tel : 66(0)76 373 024

Fax : 66(0)76 373 025

Tax ID : 0835555000220

Email: info@gmthkt.com

## DELIVERY ORDER / ใบส่งของ

Customer : Khun Suriyan

Company : Phuket Boat Lagoon.

Address : 22/1 Moo 2, Thepkasatri Rd., T.Kohkaew, A.Muang, Phuket 83110

Tel. : 076-239888

Fax : 076-239255

Subject : [Spare part] Service Preventive Maintenance Generator Cummins KTA19-G4 SN:41196000/500 KVA.

Quotation No. : GMT2403-036 PU

PO No. : HBLP24004330

Delivery Date : 28-05-2024

Mobile :

We thank you for your inquiry and we are pleased to provide quotation as per the following details :

Item	Part No.	Description	Qty	
1		Fuel Filter.	2	EA
2		Coolant Filter.	1	EA
3		Lube Filter No.1.	2	EA
4		Lube Filter No.2.	1	EA
5		Air Filter.	1	EA
6		Engine Oil 15W-40.	52	Liter
7		Coolant.	1	Lot

Please send email to info@gmthkt.com for queries with this account.

### REMITTANCE ADVICE

Delivery By



Receive By

58/115 Moo 6 Phoemsin thani village T.Ratsada, A.Muangphuket, Phuket 83000 Thailand  
Tel: +66 076 373 024 Fax: +66 076 373 025 Email: Sales1@gmthkt.com http: www.gmthkt.com





Global Marine Tech Co.,Ltd.

58/115 Phoemsin Thani Village Moo 6 T.Ratsada, A.Muangphuket, Phuket 83000 THAILAND

Tel: 66(0)76-373 024

Fax: 66(0)76-373 025

Tax ID : 0835555000220

Email: info@gmthkt.com

1/1

## Preventive Maintenance Work Order

Customer : Khun Suriyan

Work Order No. : WO2405-034 PU

Company : Phuket Boat Lagoon.

Quotation No. : GMT2403-036 PU

Address : 22/1 Moo 2, Thepkasattri Road, Kaokaew,Muang Phuket 83110

PO No. : HBLP240004330

Tel. : 076 239 888


Fax :

Date of Service : 28-05-2024

Mobile : 082-2797177

E-mail :

Item	QTY	Description
		<p><u>Service Preventive Maintenance Cummins KTA19-G4/500 KVA.</u></p> <ul style="list-style-type: none"><li>- Check engine control.</li><li>- Check external cooling pipes.</li><li>- Check engine and external engine exhaust system.</li><li>- Check external leak.</li><li>- Check coolant pump, Battery condition, And charger systems.</li><li>- Check clean up air filter.</li><li>- Inspection vibration damper, Belt condition.</li><li>- Check engine lube oil, Fuel filter, Coolant filter.</li><li>- Check fuel system.</li><li>- Check exhaust line.</li><li>- Check the electric system.</li><li>- Check engine following periodical maintenance table.</li><li>- Test run engine.</li><li>- Check function of generator.</li><li>- Provide Report.</li></ul>

  
Customer Name



  
Service Engineer  
(Global Marine Tech Co.,Ltd.)

58/115 Moo 6 Phoemsin thani village T.Ratsada, A.Muangphuket, Phuket 83000 Thailand

Tel: +66 076 373 024 Fax: +66 076 373 025 Email: Sales1@gmthkt.com http: www.gmthkt.com



Global Marine Tech Co.,Ltd.

58/115 Moo 6 Phoemsin thani village T.Ratsada, A.Muangphuket, Phuket 83000 Thailand

Tel : 66(0)76 373 024

Fax : 66(0)76 373 025

Tax ID : 0835555000220

Email: info@gmthkt.com

## DELIVERY ORDER / ใบส่งของ

Customer : Khun Suriyan

Quotation No. : GMT2403-035 PU

Company : Phuket Boat Lagoon.

PO No. : HBLP24004240

Address : 22/1 Moo 2, Thepkasattri Rd., T.Kohkaew, A.Muang, Phuket 83110

Delivery Date : 28-05-2024

Tel. : 076-239888

Fax : 076-239255

Mobile :

Subject : [Spare part] Service Preventive Maintenance Generator Cummins KTA38-G2A SN:41246531/1000 KVA.


We thank you for your inquiry and we are pleased to provide quotation as per the following details :

Item	Part No.	Description	Qty
1		Fuel Filter.	2 EA
2		Coolant Filter.	4 EA
3		Oil Filter No. 1	4 EA
4		Oil Filter No. 2	2 EA
5		Air Filter.	2 EA
6		Engine Oil.	126 Liter
7		Coolant.	1 Lot

Please send email to info@gmthkt.com for queries with this account.

### REMITTANCE ADVICE

Delivery By





Receive By



Global Marine Tech Co., Ltd.

58/115 Moo 6 Phoemsin thani village T.Ratsada, A.Muangphuket, Phuket 83000 Thailand

Tel: +66 076 373 024 Fax: +66 076 373 025 Email: Sales1@gmthkt.com http: www.gmthkt.com





Global Marine Tech Co.,Ltd.

58/115 Phoemsin Thani Village Moo 6 T.Ratsada, A.Muangphuket, Phuket 83000 THAILAND

Tel: 66(0)76-373 024

Fax: 66(0)76-373 025

Tax ID : 0835555000220

Email: info@gmthkt.com

1/1

## Preventive Maintenance Work Order

Customer : Khun Suriyan

Work Order No. : WO2405-035 PU

Company : Phuket Boat Lagoon.

Quotation No. : GMT2405-035 PU

Address : 22/1 Moo 2, Thepkasattri Road, Kaokaew,Muang Phuket 83110

PO No. : HBLP24004240

Tel. : 076 239 888


Fax :

Date of Service : 26-05-2023

Mobile : 082-2797177

E-mail :

Item	QTY	Description
		<p><u>Service Preventive Maintenance Cummins KTA38-G2A/1000 KVA.</u></p> <ul style="list-style-type: none"><li>- Check engine control.</li><li>- Check external cooling pipes.</li><li>- Check engine and external engine exhaust system.</li><li>- Check external leak.</li><li>- Check coolant pump, Battery condition, And charger systems.</li><li>- Check clean up air filter.</li><li>- Inspection vibration damper, Belt condition.</li><li>- Check engine lube oil, Fuel filter, Coolant filter.</li><li>- Check fuel system.</li><li>- Check exhaust line.</li><li>- Check the electric system.</li><li>- Check engine following periodical maintenance table.</li><li>- Test run engine.</li><li>- Check function of generator.</li><li>- Provide Report.</li></ul>

  
Customer Name



  
Service Engineer  
(Global Marine Tech Co.,Ltd.)



Global Marine Tech Co.,Ltd.

58/115 Moo 6 Phoemsin thani village T.Ratsada, A.Muangphuket, Phuket 83000 Thailand

Tel : 66(0)76 373 024

Fax : 66(0)76 373 025

Tax ID : 0835555000220

Email: info@gmthkt.com

## DELIVERY ORDER / ใบส่งของ

Customer : Khun Suriyan

Company : Phuket Boat Lagoon.

Address : 22/1 Moo 2, Thepkasattri Rd., T.Kohkaew, A.Muang, Phuket 83110

Tel. : 076-239888

Fax : 076-239255

Subject : [Spare part] Service Preventive Maintenance Generator Perkins 3012-TAG2

Quotation No. : GMT2403-034 PU

PO No. : HBLP24004210

Delivery Date : 28-05-2024

Mobile :

We thank you for your inquiry and we are pleased to provide quotation as per the following details :

Item	Part No.	Description	Qty
1		Fuel Filter.	2 EA
2		Lube Filter.	3 EA
3		Air Filter.	2 EA
4		Engine Oil 15W-40.	78 Liter
5		Coolant.	1 Lot

Please send email to info@gmthkt.com for queries with this account.

### REMITTANCE ADVICE

Delivery By



Receive By

58/115 Moo 6 Phoemsin thani village T.Ratsada, A.Muangphuket, Phuket 83000 Thailand

Tel: +66 076 373 024 Fax: +66 076 373 025 Email: Sales1@gmthkt.com http: www.gmthkt.com



Global Marine Tech Co.,Ltd.

58/115 Phoemsin Thani Village Moo 6 T.Ratsada, A.Muangphuket, Phuket 83000 THAILAND

Tel: 66(0)76-373 024

Fax: 66(0)76-373 025

Tax ID : 083555500220

Email: info@gmthkt.com

1/1

## Preventive Maintenance Work Order

Customer : Khun Suriyan  
Company : Phuket Boat Lagoon.  
Address : 22/1 Moo 2, Thepkasattri Road, Kaokaew,Muang Phuket 83110  
Tel. : 076 239 888 Fax :  
Mobile : 082-2797177

Work Order No. : WO2405-033 PU  
Quotation No. : GMT2403-034 PU  
PO No. : HBLP24004240  
Date of Service : 28-05-2024  
E-mail :

Item	QTY	Description
		<p><b>Service Preventive Maintenance Generator Perkins 3012-TAG2</b></p> <ul style="list-style-type: none"><li>- Check engine control.</li><li>- Check external cooling pipes.</li><li>- Check engine and external engine exhaust system.</li><li>- Check external leak.</li><li>- Check coolant pump, Battery condition, And charger systems.</li><li>- Check clean up air filter.</li><li>- Inspection vibration damper, Belt condition.</li><li>- Check engine lube oil, Fuel filter, Coolant filter.</li><li>- Check fuel system.</li><li>- Check exhaust line.</li><li>- Check the electric system.</li><li>- Check engine following periodical maintenance table.</li><li>- Test run engine.</li><li>- Check function of generator.</li><li>- Check list Report.</li></ul>

Customer Name



Service Engineer  
(Global Marine Tech Co.,Ltd.)

Global Marine Tech Co., Ltd.

58/115 Moo 6 Phoemsin thani village T.Ratsada, A.Muangphuket, Phuket 83000 Thailand

Tel: +66 076 373 024 Fax: +66 076 373 025 Email: Sales1@gmthkt.com http: www.gmthkt.com



**Global Marine**58/115 Phoemsin Thani Village, Moo 6 T.  
Tel. 076 373 024 Fax. 076**SERVICE AND INSP**

Customer: Phuket Boat Lagoon

Customer Address: 12/1 Mos 2, Thepkasitvi Rd, Thawakave A. Muang Phuket 83110

Generator model: 01300906

S/N 0139173/01

DATE: 28-05-22

Alternator model: STAMFORD

S/N 0139173/01

Engine Hour: 1080 h

Engine model: SD12-TAG2A

S/N 50612029-01213

Controller Model:

Item	Description	Check	Clean		
1	ระบบหล่อเย็น (Cooling System)				
1.1	ตรวจสอบระดับน้ำในหม้อน้ำ (Top up). ตรวจสอบสภาพหม้อน้ำ				
1.2	ตรวจสอบความตึงของ Belt Tension. Thermostat Housing				
1.3	ตรวจสอบการทำงานของปั๊มน้ำหล่อเย็น. ระบายน้ำ Radiator. Water pump				
1.4	ตรวจสอบคุณภาพน้ำหล่อเย็น (Coolant Filter)				
2	ระบบหล่อลื่น (Lubrication System)				
2.1	ตรวจสอบระดับน้ำมันหล่อลื่น Dipstick (H <input checked="" type="checkbox"/> / M <input type="checkbox"/> / L <input type="checkbox"/> )				
2.2	ตรวจสอบสภาพของ Oil Filter และการทำงานของปั๊มน้ำมันหล่อลื่น				
2.3	ตรวจสอบสภาพของสายลม. ถังน้ำมันเชื้อเพลิง. ท่อลม Breather pipe. Oil Sampling Point. Filter Cap.				
2.4	ตรวจสอบความข้นหนืด (Grease for Cooling pump)				
2.5	ตรวจสอบความตึงของสายพานพาน้ำมัน (Belt Tension / Grease)				
2.6	ตรวจสอบการหล่อลื่น (Grease for Alternator)				
3	ระบบน้ำมันเชื้อเพลิง (Fuel System)				
3.1	ตรวจสอบระดับน้ำมันเชื้อเพลิงในถัง (F <input type="checkbox"/> / M <input checked="" type="checkbox"/> / E <input type="checkbox"/> ) 1150703				
3.2	ตรวจสอบสภาพของ Primary Fuel Filter และการทำงานของปั๊มน้ำมันเชื้อเพลิง				
3.3	ตรวจสอบสภาพของ Secondary Fuel Filter และการทำงานของปั๊มน้ำมันเชื้อเพลิง				
3.4	ตรวจสอบสภาพของ Fuel Injection Pump. Relief Valve. Fuel Lift Pump				
3.5	ตรวจสอบสภาพของ Governor. Throttle Lever. Governor Weights				
4	ระบบอากาศ (Air System & Exhaust System)				
4.1	ตรวจสอบสภาพของ Air Filter Component				
4.2	ตรวจสอบสภาพของ Turbocharger. Inter manifold. Exhaust Manifold				
5	ระบบไฟฟ้า (Electric System)				
5.1	ตรวจสอบสภาพของสายไฟและจุดต่อสายไฟตามจุดต่างๆ				
5.2	DC : ตรวจสอบสภาพของแบตเตอรี่, ขั้วแบตเตอรี่ สายไฟ และ สาย Ground				
5.3	DC : ตรวจสอบระดับน้ำกรดในแบตเตอรี่ ระบบ (Top up) (F <input type="checkbox"/> / M <input checked="" type="checkbox"/> / E <input type="checkbox"/> )				
5.4	AC : ตรวจสอบสภาพและการทำงานของ Circuit Breaker				
5.5	ตรวจสอบการทำงานของ Battery Charger				
6	Control Panel Functional Operation				
6.1	ทดสอบหลอดไฟ LED และสัญญาณเตือน (Lamp Test / Reset)				
6.2	ทดสอบความดันน้ำมันเครื่อง (PSI) (1-5 BAR)				
6.3	ทดสอบอุณหภูมิหม้อน้ำ (60 °C) (140 °F)				
6.4	ทดสอบความเร็วรอบ (1800 rpm) (ความถี่ 30 Hz)				
6.5	ทดสอบ Battery Charging (DC 28.4 Volt) (กระแส 2.5 Amp)				
6.6	การทำงานของสัญญาณเตือนการระบุมหาในตู้ต่างๆ (Alarm Status)				
6.7	การทำงานของ Emergency Push button switch				
6.8	การทำงานของ AC Volt & Amp Selector				
6.9	การทำงานของ Start Manual Run Auto และ Stop				
7	ระบบกันเสียง (Soundproof System)				
7.1	ระบบกันเสียง				
7.2	หม้อน้ำ (Sound attenuated Enclosure)				
8	การทดสอบเครื่องกำเนิดไฟฟ้า	ค่าแรงดันไฟฟ้า(Volt)			
	ค่าแรงดันไฟฟ้าที่ทำการวัด	L1-N	L2-N	L3-N	L1-L2
8.1	สภาวะไม่โหลด (No Load)	230	230	230	400
8.2	สภาวะมีโหลด (Load)				

D:\www



tsada, A.Muangphuket, Phuket 83000 Thailand  
3 025 E-mail : info@gmthkt.com

## CONCLUSION REPORT

Customer Phone : 091 2312054

Project :


☐ Pre-Delivery

#### ☐ Commissioning

S/N : ☒ Preventive maintenance / 810 KVA

[illegible]






Global Marine  
Service & Inspection  
Inc. Co., Ltd.  
Wilmington, Delaware

[illegible]

မြို့တော်အကျဉ်းချုပ်





## Perkins 800kva 28-05-2024





**Global Marine**58/115 Phoemsin Thani Village, Moo 6 T.  
Tel. 076 373 024 Fax. 076**SERVICE AND INSPECTION**

Customer : Phuket Boat Lagoon

Customer Address : 22/1 Moo 2 Thepkasitthi Rd, T.kohkarn A. Muay Phuket 83110

Generator model : TCI600T

S/N TCI060T000000

DATE : 22-11-22

Alternator model :

S/N 2171031701

Engine Hour : 203 h

Engine model : KTA38-G2A

S/N M244431

Controller Model :

Item	Description	Check	Clean		
1	ระบบหล่อเย็น (Cooling System)				
1.1	ตรวจสอบระดับน้ำในหม้อน้ำ (Top up) ตรวจสอบสภาพของพัดลม	/			
1.2	ตรวจสอบความตึง Belt Tension, Thermostat Housing	/			
1.3	ตรวจสอบสภาพของท่อรั่วซึมของหม้อน้ำ, วาล์ว, หม้อน้ำ Radiator, Water pump	/			
1.4	ตรวจสอบสภาพของน้ำหล่อเย็น (Coolant Filter)	/			
2	ระบบหล่อลื่น (Lubrication System)				
2.1	ตรวจสอบระดับน้ำมันหล่อลื่น Dipstick (H: <input type="checkbox"/> / M: <input type="checkbox"/> / L: <input type="checkbox"/> )	/			
2.2	ตรวจสอบสภาพของ Oil Filter และการรั่วซึมของน้ำมันหล่อลื่นตามจุดต่าง	/			
2.3	ตรวจสอบสภาพของท่อลมหายใจ, ถังน้ำมันเชื้อเพลิง, ท่อลมหายใจ Breather pipe, Oil Sampling Point, Filter Cap	/			
2.4	ตรวจสอบการฉาบมัน (Grease for Cooling pump)	/			
2.5	ตรวจสอบการตึงของสายพานพาน้ำมัน (Belt Tension / Grease)	/			
2.6	ตรวจสอบการฉาบมัน (Grease for Alternator)	/			
3	ระบบน้ำมันเชื้อเพลิง (Fuel System)				
3.1	ตรวจสอบระดับน้ำมันเชื้อเพลิงในถัง (F: <input type="checkbox"/> / M: <input type="checkbox"/> / E: <input type="checkbox"/> )	/			
3.2	ตรวจสอบสภาพของ Primary Fuel Filter และการรั่วซึมของน้ำมันเชื้อเพลิง	/			
3.3	ตรวจสอบสภาพของ Secondary Fuel Filter และการรั่วซึมของน้ำมันเชื้อเพลิง	/			
3.4	ตรวจสอบสภาพของ Fuel Injection Pump, Relief Valve, Fuel Lift Pump	/			
3.5	ตรวจสอบสภาพของ Governor, Throttle Lever, Governor Weights	/			
4	ระบบอากาศ (Air System & Exhaust System)				
4.1	ตรวจสอบสภาพของ Air Filter Component	/			
4.2	ตรวจสอบสภาพของ Turbocharger, Inter manifold, Exhaust Manifold	/			
5	ระบบไฟฟ้า (Electric System)				
5.1	ตรวจสอบสภาพของสายไฟและจุดต่อสายไฟตามจุดต่าง	/			
5.2	DC : ตรวจสอบสภาพของแบตเตอรี่, ขั้วแบตเตอรี่ สายไฟ และ สาย Ground	/			
5.3	DC : ตรวจสอบระดับน้ำกรดในแบตเตอรี่ ระดับ (Top up) (F: <input type="checkbox"/> / M: <input type="checkbox"/> / E: <input type="checkbox"/> )	/			
5.4	AC : ตรวจสอบสภาพและการทำงานของ Circuit Breaker	/			
5.5	ตรวจสอบการชาร์จแบตเตอรี่ Battery Charger	/			
6	Control Panel Functional Operation				
6.1	ทดสอบหลอดไฟ LED แผงควบคุม (Lamp Test / Reset)	/			
6.2	ตรวจสอบความดันน้ำมันเชื้อเพลิง (PSI) (Bar)	/			
6.3	ตรวจสอบอุณหภูมิของหม้อน้ำ (°C) (°F)	/			
6.4	ตรวจสอบความเร็วรอบ (rpm) (ความถี่ Hz)	/			
6.5	ตรวจสอบ Battery Charging (DC Volt) (กระแส Amp)	/			
6.6	การทำงานของสัญญาณเตือนและระบบป้องกันส่วนต่างๆ (Alarm Status)	/			
6.7	การทำงานของปุ่ม Emergency Push button switch	/			
6.8	การทำงานของสวิตช์ AC Volt & Amp Selector	/			
6.9	การทำงานของสวิตช์ Start/Run Manual Run/Stop	/			
7	ระบบกันเสียง (Soundproof System)				
7.1	ระดับความดัง				
7.2	ผนังห้อง (Sound attenuated Enclosure)				
8	การทดสอบเครื่องกำเนิดไฟฟ้า	ค่าแรงดันไฟฟ้า(Volt)			
	ค่าแรงดันไฟฟ้าที่การวัด	L1-N	L2-N	L3-N	L1-L2
8.1	สถานะไม่มีโหลด (No Load)	234	234	234	400
8.2	สถานะมีโหลด (Load)				

Remark :



usada, A.Muangphuket, Phuket 83000 Thailand  
3 025 E-mail : info@gmthkt.com

## ATION REPORT

Project :

Quotation NO: GHT 2403-035 PA

☐ Pre-Delivery☐ Commissioning

S/N : ☐ Preventive maintenance / 940 KVA

[illegible]





Global Marine Tech Co., Ltd.  
Service & Inspection Acknowledgment Form

No. of Man	Person	Service HR.	
		Start	Stop
Working time	hrs.		
Over time	hrs.		

ตารางการตรวจเช็คแบตเตอรี่ประจำเดือน

แบตเตอรี่แต่ละเครื่อง	กำลังไฟ	+	+	+	+	+	สถานะ	หมายเหตุ
แบตเตอรี่ NO. 1	13.6 V	12.86	13.06	12.86	12.26	12.26	2.750	
แบตเตอรี่ NO. 2	13.6 V	12.86	12.86	12.86	12.26	12.26	3.000	
แบตเตอรี่ NO. ....								
แบตเตอรี่ NO. ....								
แบตเตอรี่ NO. ....								
แบตเตอรี่ NO. ....								
แบตเตอรี่ NO. ....								
แบตเตอรี่ NO. ....								
แบตเตอรี่ NO. ....								
แบตเตอรี่ NO. ....								
แบตเตอรี่ NO. ....								


ค่าของน้ำหนักแบตเตอรี่  
1100 - 1200 = 300  
1200 - 1250 = 100  
1250 - 1300 = 50



ผู้ตรวจเช็ค


13.6 V 3.000

แบตเตอรี่ 94-b-6  
น้ำหนักแบตเตอรี่ 300  
น้ำหนักแบตเตอรี่ 100  
น้ำหนักแบตเตอรี่ 50





# Cummins 1000kva 28-05-2024





**Global Marine**58/115 Phoemsin Thani Village, Moo 6  
Tel. 076 373 024 Fax. 07**SERVICE AND INSPECTION**

Customer : Phuket Boat Lagoon  
 Customer Address : 22/1 Moo 2, Thepkasornwong Rd. T. Kohkaww, A. Muang Phuket 83000  
 Generator model : 425-5005 S/N 4250051001231 DATE : 28-05-24  
 Alternator model : STAMFORD S/N X13KA64650 Engine Hour : 5856 Hrs  
 Engine model : KTA19-64 S/N 411A6000 Controller Model : D20050X

Item	Description	Check	Clean
1	ระบบหล่อเย็น (Cooling System)		
1.1	ตรวจสอบระดับน้ำหล่อเย็น (Top up) ตรวจสอบสายพานพาน้ำ	/	
1.2	ตรวจสอบความตึงเครียด Belt Tension, Thermostat housing	/	
1.3	ตรวจสอบสภาพของถังน้ำหล่อเย็น, พัดลม, ถังน้ำ Radiator, Water pump	/	
1.4	ตรวจสอบการกรองน้ำหล่อเย็น (Coolant Filter)	/	
2	ระบบหล่อลื่น (Lubrication System)		
2.1	ตรวจสอบระดับน้ำมันหล่อลื่น Dipstick (H / M / L)	/	
2.2	ตรวจสอบการกรอง Oil Filter และหาวิธีเปลี่ยนน้ำมันหล่อลื่นตามกำหนด	/	
2.3	ตรวจสอบการปล่อยลมหายใจ, สายน้ำหายใจ, ท่อลมหายใจ Breather pipe, Oil Sampling Point, Filter Cap	/	
2.4	ตรวจสอบจารบีปั๊ม (Grease for Cooling pump)	/	
2.5	ตรวจสอบความตึงเครียดสายพานพาน้ำ (Belt Tension / Grease)	/	
2.6	ตรวจสอบจารบีปั๊ม (Grease for Alternator)	/	
3	ระบบน้ำมันเชื้อเพลิง (Fuel System)		
3.1	ตรวจสอบระดับน้ำมันเชื้อเพลิงในถัง (F / M / E)	/	
3.2	ตรวจสอบการกรอง Primary Fuel Filter และหาวิธีเปลี่ยนน้ำมันเชื้อเพลิง	/	
3.3	ตรวจสอบการกรอง Secondary Fuel Filter และหาวิธีเปลี่ยนน้ำมันเชื้อเพลิง	/	
3.4	ตรวจสอบการกรอง Fuel Injection Pump, Relief Valve, Fuel Lift Pump	/	
3.5	ตรวจสอบการกรอง Governor, Throttle Lever, Governor Weights	/	
4	ระบบอากาศ (Air System & Exhaust System)		
4.1	ตรวจสอบการกรอง Air Filter Component	/	
4.2	ตรวจสอบการกรอง Turbocharger, Inter manifold, Exhaust Manifold	/	
5	ระบบไฟฟ้า (Electric System)		
5.1	ตรวจสอบการเชื่อมต่อสายไฟและจุดต่อสายไฟตามจุดต่างๆ	/	
5.2	DC : ตรวจสอบการเชื่อมต่อสายไฟ, สายไฟ และ สาย Ground	/	
5.3	DC : ตรวจสอบการเชื่อมต่อสายไฟในแบตเตอรี่ (Top up) (F / M / E)	/	
5.4	AC : ตรวจสอบการเชื่อมต่อสายไฟในตู้ Circuit Breaker	/	
5.5	ตรวจสอบการเชื่อมต่อสายไฟของ Battery Charger	/	
6	Control Panel Functional Operation		
6.1	ทดสอบหลอดไฟ LED และสัญญาณเตือน (Alarm Test / Reset)	/	
6.2	ทดสอบระดับน้ำเชื้อเพลิง (PSI) (4.5 BAR)	/	
6.3	ทดสอบอุณหภูมิของน้ำ (60 °C) (°F)	/	
6.4	ทดสอบความเร็วรอบ (rpm) (การหมุน 520 Hz)	/	
6.5	ทดสอบ Battery Charging (DC) (V) (A) (กระแส 15.0 Amp)	/	
6.6	การแจ้งเตือนระดับน้ำเชื้อเพลิง/การเตือนภัยในตู้ควบคุม (Alarm Status)	/	
6.7	การแจ้งเตือนฉุกเฉิน Emergency Push button switch	/	
6.8	การเลือกแรงดันไฟฟ้า AC Volt & Amp Selector	/	
6.9	การเลือกโหมดการทำงาน Start man / Manual Run และ Auto และ Stop	/	
7	ระบบกันเสียง (Soundproof System)		
7.1	ระดับความดัง		
7.2	ตู้กันเสียง (Sound attenuated Enclosure)		

การทดสอบเครื่องกำเนิดไฟฟ้า		ค่าแรงดันไฟฟ้า(Volt)			
ค่าแรงดันไฟฟ้าที่การวัด		L1-N	L2-N	L3-N	L1-L2
8.1	สถานะไม่โหลด (No Load)	230	230	230	400
8.2	สถานะโหลด (Load)				

Remark : \* \* \* \* \*



atsada, A.Muangphuket, Phuket 83000 Thailand  
73 025 E-mail : info@gmthkt.com

CTION REPORT

Project :

Quotation No: GMT2403-036 PU

☐ Pre-Delivery☐ Commissioning

S/N : 7390 ☒ Preventive maintenance / 300 KVA

[illegible]





Global Marine Tech Co., Ltd.  
Service & Inspection Acknowledgment Form

No. of Man	Person	Service HR.	
Working time	hrs.	Start	Stop
Over time	hrs.		


ตารางการตรวจเช็คแบตเตอรี่ประจำเดือน

แบตเตอรี่แต่ละเครื่อง	กำลังไฟ	ค่า 1	ค่า 2	ค่า 3	ค่า 4	ค่า 5	ค่า 6	สถานะ	หมายเหตุ
แบตเตอรี่ NO. 1	13.3	19.50	19.50	19.50	19.50	19.50	19.50		
แบตเตอรี่ NO. 2	13.3	19.50	19.50	19.50	19.50	19.50	19.50		
แบตเตอรี่ NO. 3									
แบตเตอรี่ NO. 4									
แบตเตอรี่ NO. 5									
แบตเตอรี่ NO. 6									
แบตเตอรี่ NO. 7									
แบตเตอรี่ NO. 8									
แบตเตอรี่ NO. 9									
แบตเตอรี่ NO. 10									
แบตเตอรี่ NO. 11									
แบตเตอรี่ NO. 12									
แบตเตอรี่ NO. 13									
แบตเตอรี่ NO. 14									
แบตเตอรี่ NO. 15									

ค่าของน้ำหนักแบตเตอรี่  
1100 - 1200 = ค่า  
1200 - 1250 = 1 กค  
1250 - 1300 = 2




ผู้ตรวจเช็ค





Cummins 500 kva 28-05-2024



## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

May-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by guntan Date 27/6/67

Supervisor by Carina Date 27/6/67



May-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by 4/10/67 Date 27/6/67

Supervisor by Leinard Date 27/1/67

May-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by gymon Date 27/6/67

Supervisor by Carina Date 27/6/67

## May-24

Supervisor by                      Date 27/6/07

## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

May-24

[illegible]

Note:Mark [ ✓ ] Normal

(1) = Fire Exit

Mark (X) Abnormal

(2) = Emergency Light

Responsible by W. M. M. M. Date 27/6/67

Supervisor by W. J. J. Date 27/6/67



May-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by gmdn Date 27/6/07

Supervisor by Leirwaik Date 2/16/67

## NH BOAT LAGOON PHUKET RESORT

### Check List emergency light

May-24

[illegible]

Note:Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by upm Date 27/6/67

Supervisor by Winters Date 27/6/67

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

May-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Bai rure 1 (Fire Exit)	✓	✓	✓	✓	✓	27/6/67	synon	✓		✓	
Bai rure 1 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Bai rure 2 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Bai rure 2 (Emergency)	✓	✓	✓	✓	✓			✓		✓	

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

(1) = Fire Exit

(2) = Emergency Light

Responsible by .....synon.....Date 27/6/67

Supervisor by .....synon.....Date 27/6/67



# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

May-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 241 (Fire Exit)	✓	✓	✓	✓	✓	27/6/67	gnor	✓		✓	
Room 241 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 246 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 246 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 252 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 252 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 263 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 263 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 269 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 269 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 274 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 274 (Emergency)	✓	✓	✓	✓	✓			✓		✓	

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

Responsible by gnor Date 27/6/67

Supervisor by gnor Date 27/6/67

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

May-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 341 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 341 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 346 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 346 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 355 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 355 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 360 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 360 (Emergency)	✓	✓	✓	✓	✓	27/6/67	gman	✓		✓	
Room 371 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 371 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 377 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 377 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 382 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 382 (Emergency)	✓	✓	✓	✓	✓			✓		✓	

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

Responsible by gman Date 27/6/67

Supervisor by leis Bais Date 27/6/67

# NH BOAT LAGOON PHUKET RESORT

## Check List emergency light

May-24

installation point	Power	Light	Battery	Switch	Cleanliness	Date	Inspector	Normal	Abnormal	Done	Note
Room 441 (Fire Exit)	✓	✓	✓	✓	✓	27/6/67	gnoon	✓		✓	
Room 441 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 446 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 446 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 456 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 456 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 462 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 462 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 473 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 473 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 479 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 479 (Emergency)	✓	✓	✓	✓	✓			✓		✓	
Room 484 (Fire Exit)	✓	✓	✓	✓	✓			✓		✓	
Room 484 (Emergency)	✓	✓	✓	✓	✓			✓		✓	

Note: Mark [ ✓ ] Normal

Mark (X) Abnormal

Responsible by .....gnoon.....Date 27/6/67

Supervisor by .....win 325.....Date 27/6/67



## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building A

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building A</b>													
Side Steps													
Corridor Room 121	Chemical Powder-ABC	√	√	√	√	√	√	√	30/06/24	Santichai			
Corridor Room 131	Chemical Powder-ABC	√	√	√	√	√	√	√	30/06/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 122	Chemical Powder-ABC	√	√	√	√	√	√	√	30/06/24	Santichai			
Side Steps													
Corridor Room 124	NON-CFC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/06/24	Santichai			Dismantled
Corridor Room 137	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/06/24	Santichai			Dismantled
Facade of Building													
Corridor Room A21	NON-CFC	√	√	√	√	√	√	√	30/06/24	Santichai			
Behind the Building													
Corridor MDB Room	Chemical Powder-ABC	√	√	√	√	√	√	√	30/06/24	Santichai			

Remark;

[ √ ] Normal

[ X ] Abnormal

Loss & Prevention Check

People & Culture Manager

02 N.A. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building B

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building B</b>													
Side Steps													
Corridor Room 221	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Corridor Room 231	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
<b>Central Staircase</b>													
Corridor Room 222 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Corridor Room 233 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Side Steps													
Corridor Room 224	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Facade of Building													
Corridor Office 20/4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Behind the Building													
Corridor Office 20/1-4	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating

Remark;

[✓] Normal

[X] Abnormal

Loss & Prevention Check

People & Culture Manager

02 A.A. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building C

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building C</b>													
Side Steps													
Corridor Room 321	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Corridor Room 331 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
<b>Central Staircase</b>													
Corridor Room 322 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Corridor Room 334 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Side Steps													
Corridor Room 324	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Corridor Room 237	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Facade of Building													
Corridor Office 20/8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Behind the Building													
Corridor Office 20/5-8	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

People & Culture Manager

02.09.2567



# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building D

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building D</b>													
Side Steps													
Corridor Room 421	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/06/24	Santichai			Dismantled
Corridor Room 431	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/06/24	Santichai			Dismantled
<b>Central Staircase</b>													
Corridor Room 422	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Corridor Room 434	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Side Steps													
Corridor Room 424	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Corridor Room 437	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Facade of Building													
Corridor Office 20/12	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Behind the Building													
Corridor Office 20/9-12 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

People & Culture Manager

02.06.2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building E

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building E</b>													
Side Steps													
Corridor Room 521	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/06/24	Santichai			Dismantled
Corridor Room 531	Chemical Powder-ABC	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30/06/24	Santichai			Dismantled
<b>Central Staircase</b>													
Corridor Room 522	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Corridor Room 534	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Side Steps													
Corridor Room 524	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Corridor Room 537	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Facade of Building													
Corridor Office 20/16	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating
Behind the Building													
Corridor Office 20/13-16 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			Renovating

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

People & Culture Manager

02 A.A. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building F

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>Building F</b>													
Side Steps													
Corridor Room 621	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Corridor Room 631	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
<b>Central Staircase</b>													
Corridor Room 623	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Corridor Room 633	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Side Steps													
Corridor Room 624	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Corridor Room 637	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Facade of Building													
Corridor Office 20/20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Behind the Building													
Corridor Office 20/17-20	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

People & Culture Manager

02 A.A. 2567



# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Building G

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building G													
Side Steps													
Corridor Room 721	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Corridor Room 731	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Central Staircase													
Corridor Room 722	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Corridor Room 733	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Side Steps													
Corridor Room 724	Chemical Powder-ABC	X	✓	✓	✓	✓	✓	✓	30/06/24	Santichai	27/02/24		Pressure down
Corridor Room 737	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Facade of Building													
Corridor Office 20/24	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			
Behind the Building													
Corridor Office 20/21-24 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	30/06/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

People & Culture Manager

02 N.A. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building G

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building H													
Side Steps													
Corridor Room 925	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			
Corridor Room 933	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			
Side Steps													
Corridor Room 924	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			
Corridor Room 927	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			
Facade of Building													
Corridor Office 20/26	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			
Behind the Building													
Corridor Office 20/25-26 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

People & Culture Manager

02 A.A. 2567

## NH BOAT LAGOON PHUKET RESORT

### Check List Fire Extinguisher Building G

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
Building I													
Side Steps													
Corridor Room 923	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			
Corridor Room 935	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			
Side Steps													
Corridor Room 936	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			
Corridor Room 949	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			
Facade of Building													
Corridor Office 20/27	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			
Behind the Building													
Corridor Office 20/26-27 x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	1/6/2024	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss & Prevention Check

People & Culture Manager

02 N.A. 2567



# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing Floor 1, Restaurant, Lobby

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 1</b>													
Loading x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor MDB Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Accounting Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Female Locker	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Canteen Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			Fire Blanket x1
Main Kitchen x2	Chemical -ABCDK	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			Fire Blanket x2
Electrical Control Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	X	28/06/24	Santichai			
Captain Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
F&B office x1/Pool barx1	Chemical Powder-AK	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			Fire Blanket x1
Bal-Ruer Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Boat Point Room	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Loss & Prevention Office	NON-CFC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Generator Room x2	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Gas Store	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

*Handwritten signature*  
28/6/24

People & Culture Manager

*Handwritten signature*  
02 JUN 2024

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing FLOOR 2,3

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 2</b>													
Corridor Room 242	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 250	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 256	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 264	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 272	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Front Office	Chemical Powder-ABC	X	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			Pressure down
<b>FLOOR 3</b>													
Corridor Room 342	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 348	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 352	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 358	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 364	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 372	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 380	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			

Remark;

[✓] Normal

[X] Abnormal

Loss & Prevention Check

15 30/6/24

People & Culture Manager



02 H.M. 2567

# NH BOAT LAGOON PHUKET RESORT

## Check List Fire Extinguisher Hotel Wing FLOOR 4/White House Meeting Room

Monthly..06/2024

Installation Point	Chemical Type	Pressure Level	Safety Latch	Fire Hose	Obstruction	Install no more than 1.4 m.	Point Display Sign	Cleanliness	Checked Date	Inspector	Work Order No.	PR No.	Remark
<b>FLOOR 4</b>													
Corridor Room 442	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 448	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 454	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 460	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 466	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 474	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
Corridor Room 482	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
White House Meeting Room01	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
White House Meeting Room02	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
White House Meeting Room03	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
White House Meeting Room04	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
White House Meeting Room05	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			
White House Meeting Room KC x3	Chemical Powder-ABC	✓	✓	✓	✓	✓	✓	✓	28/06/24	Santichai			Fire Blanket x2

Remark;

[ ✓ ] Normal

[ X ] Abnormal

Loss & Prevention Check

People & Culture Manager

02 N.A. 2557



**บันทึกการตรวจสอบสภาพหัวจ่ายน้ำดับเพลิง**

รายละเอียดของหัวจ่ายดับเพลิง

[illegible]

### รายละเอียดการชำระ

19	$2\frac{4}{5}$	$2\frac{4}{5}$	$2\frac{4}{5}$	$2\frac{4}{5}$
21	$2\frac{4}{5}$	$2\frac{4}{5}$	$2\frac{4}{5}$	$2\frac{4}{5}$

สาเหตุการชำรุด  
(✓)ใช้งาน

(✓)หมดอายุ

( ) อื่นๆ

---

ผู้รายงาน

ตำแหน่ง

วันที่

รวม ๒๖/๐๖/๕๗

**ข้อปฏิบัติ**

ตรวจสภาพหัวจ่ายน้ำดับเพลิง ทดเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที





บันทึกการตรวจสอบระบบสัญญาณแจ้งเหตุฉุกเฉิน

รายละเอียดของสัญญาณแจ้งเหตุฉุกเฉิน

รหัส

สถานที่ติดตั้ง

วันที่ตรวจ	เกณฑ์การตรวจสอบ										ผู้ตรวจ
	สภาพจุดติดตั้ง		ปุ่มควบคุม		การส่งสัญญาณ		แหล่งจ่ายไฟสำรอง		สิ่งกีดขวาง		
	ปกติ	ชำรุด	ปกติ	ชำรุด	ปกติ	ไม่ปกติ	ปกติ	ไม่ปกติ	มี	ไม่มี	
1	✓		✓		✓		✓			✓	
2											
3	✓		✓		✓		✓			✓	
4	✓		✓		✓		✓			✓	
5	✓		✓		✓		✓			✓	
6	✓		✓		✓		✓			✓	
7	✓		✓		✓		✓			✓	
8	✓		✓		✓		✓			✓	
9	✓		✓		✓		✓			✓	
10	✓		✓		✓		✓			✓	
11	✓		✓		✓		✓			✓	
12	✓		✓		✓		✓			✓	
13											
14											
15	✓		✓		✓		✓			✓	
16	✓		✓		✓		✓			✓	
17											
18	✓		✓		✓		✓			✓	
19	✓		✓		✓		✓			✓	
20	✓		✓		✓		✓			✓	
21	✓		✓		✓		✓			✓	
22	✓		✓		✓		✓			✓	
23	✓		✓		✓		✓			✓	
24	✓		✓		✓		✓			✓	
25	✓		✓		✓		✓			✓	
26	✓		✓		✓		✓			✓	
27	✓		✓		✓		✓			✓	
28											
29	✓		✓		✓		✓			✓	

รายละเอียดการชำรุด



กระดิ่งสัญญาณ



ปุ่มควบคุม

สาเหตุการชำรุด

( ) ใช้งาน

( ) หมดอายุ

( ) อื่นๆ

ผู้รายงาน

ตำแหน่ง

วันที่

ธนสิทธิ์ แก้วท้าว  
ช่างไฟฟ้า  
26/06/67

ข้อปฏิบัติ

ตรวจสอบสัญญาณแจ้งเหตุฉุกเฉินทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง

หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที







บันทึกการตรวจสอบปั้มน้ำดับเพลิง

รายละเอียดเครื่องสูบน้ำดับเพลิง (Electrical Fire Pump)


รหัส	ชนิด	ขนาด	สถานที่ติดตั้ง
๔๐๐๔๐๑	TU-PF250m2	55 kW	ชั้น ๖ บ่อ 4

หัวข้อ	เกณฑ์การตรวจสอบ	ปกติ	ไม่ปกติ	หมายเหตุ
1	ตรวจสอบสภาพ seal เครื่องสูบน้ำ	✓		
2	ประเก็นหน้าวาล์วต่างๆ	✓		
3	วาล์วทางด้านดูด (foot valve)	✓		
4	วาล์วทางด้านจ่าย (discharge valve)	✓		
5	หลอดไฟสวิตช์หน้าตู้	✓		
6	ระดับความดันสั่งงานของ Pressure switch	✓		ระบุ 40 PSI
7	ระดับความดันของเครื่องสูบน้ำขณะทำงาน	✓		ระบุ 120 PSI
8	ระดับความดันหยุดการทำงานของ Pressure switch	✓		ระบุ 110 PSI
9	ระดับเสียงมอเตอร์ขณะทำงาน	✓		
10	หน้าตู้ควบคุม (Auto start function On/off)	✓		
11	สภาพการทำงานมอเตอร์โดยรวม	✓		
12	อื่นๆ ระบุ			

รายละเอียดการชำรุด	สาเหตุการชำรุด
	( ) ใช้งาน ( ) หมดอายุ
	( ) อื่นๆ โปรดระบุ.....
	ผู้รายงาน
ตำแหน่ง	๓๖๐ ไฟฟ้า
วันที่	๒๗/๐๖/๖๗

ข้อปฏิบัติ  
ตรวจสอบเครื่องสูบน้ำดับเพลิง ทุกเดือน และลงชื่อกำกับด้วยตัวบรรจง  
หากพบสิ่งผิดปกติให้ดำเนินการแก้ไขทันที หากไม่สามารถแก้ไขได้ ให้บันทึกความผิดปกตินั้น และส่งเอกสารนี้ให้จป.ทันที







# TEST RUN RECORD FOR EMERGENCY GENERATOR

GATE ..... 7/7/67 ..... ENGINEER ..... ไม้จั่น .....  
 GENERATOR ..... 1000 KVA ..... LOCATION ..... 350m .....

## สภาพเครื่องก่อน TEST RUN

- ☐ ระดับน้ำมันเครื่อง (Motor Oil)  
☐ สภาพสายพาน (Machine Belt)  
☐ ระดับน้ำในหม้อน้ำ (Boiler)  
☐ ระดับน้ำกลั่นในแบตเตอรี่ (Battery)

## TEST RUN

☒ ON LOAD ☐ OFF LOAD

TIME START ..... 13.20 ..... TIME STOP ..... 14.00 .....

รายการตรวจเช็ค		บันทึก
Oil (L.)		1400L
Voltage (V)	L1	233
Voltage (V)	L2	234
Voltage (V)	L3	233
Coolant Temp (°C)		71
Oil Pressure (bar)		4.52
Speed (RPM)		1509
Frequency (Hz)		50.4
Battery (V)		27.4
Run Time (h)		209h 3m

REMARK

.....  
 .....  
 .....  
 .....  
 .....  
 .....  
 .....  
 .....  
 .....  
 .....



