

## **7.9 ตัวอย่างเอกสารการตรวจสอบทำความสะอาดและ ปรับแต่งระบบปรับอากาศภายในอาคาร**



Monthly Plan	Monthly Completed
2 Mmonth plan	2 Mmonth Completed
Quarterly Plan	Quarterly Completed
Bi Yearly Plan	Bi Yearly Completed
Annaully Plan	Annaully Completed

**Year 2024 PM by PLE contractor**

[illegible]







บริษัท เพาเวอร์ไลน์ เอ็นจิเนียริง จำกัด (มหาชน)  
POWER LINE ENGINEERING PUBLIC COMPANY LIMITED

FM-ENG-52

วันที่บังคับใช้: 27 / 12 / 42

แก้ไขครั้งที่: 0

## ใบสั่งงาน JOB ORDER

เลขที่  
No. **5567**

☐ ซ่อม  
Repair

☒ ตรวจสอบ  
Check

### แผนกบริการ (SERVICE DEPT.)

ชื่อลูกค้า  
Name of Customer: **โพลีplast**

วันที่  
Date: **19/12/67**

เวลาเข้า  
Time in: **09.25**

เวลาออก  
Time out: **15.00**

ที่อยู่  
Address:

โทรศัพท์  
Tel:

ชื่อโครงการ  
Project name:

บุคคลที่ติดต่อ  
Contacted name:

สถานที่ตั้งโครงการ  
Location:

**บจก.กรู**

ประวัติเครื่อง  
Detail of Machine:

รายละเอียดการตรวจซ่อม  
Detail of Repair:

**แก้ไขดินทรปรมาของโรงบำบัด ชั้น 2 โดยทรโพลีplast**

ผลการตรวจเช็คเครื่อง  
Pre-repair Check:

**แก้ไขดินทรปรมา โดยทร ลตอ  
ผลิต ๓๐๕ ทำความสะอาด  
11.๒ จุดต่อเมตรทุกตัว ชั้น 2,  
ชั้น 2, 9 ตัว  
ชั้น 2 2 ตัว**

อะไหล่ที่เปลี่ยน  
Parts Replaced

จำนวน Q'ty	รายการ Description	หน่วยละ Unit Price	รวมเงิน Total Price

ค่าบริการ  
Service charge

ภาษีมูลค่าเพิ่ม  
Vat 7%

รวมเงินทั้งหมด  
Total

หมายเหตุ  
Comments:

ตรวจโดย  
Approval:

รับรองว่าได้ตรวจซ่อมเครื่องเสร็จแล้ว  
Certified that the reparation has been satisfactorily completed.

ลายมือชื่อช่างซ่อม

Technician's Signature .....

ลายมือชื่อลูกค้า

Customer's Signature .....





บริษัท เพาเวอร์ไลน์ เอ็นจิเนียริง จำกัด (มหาชน)  
POWER LINE ENGINEERING PUBLIC COMPANY LIMITED

FM-ENG-52

วันที่บังคับใช้: 27 / 12 / 42

แก้ไขครั้งที่ : 0

## ใบสั่งงาน JOB ORDER

เลขที่  
No. 5564

☐ ซ่อม  
Repair

☒ ตรวจสอบ  
Check

### แผนกบริการ (SERVICE DEPT.)

ชื่อลูกค้า  
Name of Customer: บริษัท...

วันที่  
Date: 20/2/62

เวลาเข้า  
Time in: 09.55

เวลาออก  
Time out: 15.00

ที่อยู่  
Address:

โทรศัพท์  
Tel:

ชื่อโครงการ  
Project name:

บุคคลที่ติดต่อ  
Contacted name:

สถานที่ตั้งโครงการ  
Location: บริษัท...

ประวัติเครื่อง  
Detail of Machine:

รายละเอียดการตรวจสอบ  
Detail of Repair:

แก้ไขมอเตอร์ปั๊มระบบปรับอากาศโครงการ...

ผลการตรวจสอบเครื่อง  
Pre-repair Check:

ฉีด PM ระบบปรับอากาศโดย  
สอศ. 6 มอเตอร์ ทำความสะอาด  
11.2 จุด มอเตอร์รวม 4, 5, 6  
7, 8  
ชิ้น 4 = 2 ตัว  
ชิ้น 5 = 2 ตัว  
ชิ้น 6 = 2 ตัว  
ชิ้น 7 = 2 ตัว  
ชิ้น 8 = 2 ตัว

อะไหล่ที่เปลี่ยน  
Parts Replaced

จำนวน Q'ty	รายการ Description	หน่วยละ Unit Price	รวมเงิน Total Price

ค่าบริการ  
Service charge  
ภาษีมูลค่าเพิ่ม  
Vat 7%  
รวมเงินทั้งหมด  
Total

หมายเหตุ  
Comments:

ตรวจโดย  
Approval:

รับรองว่าได้ตรวจสอบเครื่องเสร็จแล้ว  
Certified that the reparation has been satisfactorily completed.

ลายมือชื่อช่างซ่อม  
Technician's Signature

ลายมือชื่อลูกค้า  
Customer's Signature



ใบสั่งงาน  
JOB ORDER

เลขที่ 5568  
No.

☐ซ่อม  
Repair

☐ ตรวจสอบเช็ค  
Check

**แผนกบริการ  
(SERVICE DEPT.)**

ชื่อลูกค้า  
Name of Customer: โพรเซสซิง

วันที่  
Date: ๑๑/๑/๖๒

เวลาเข้า  
Time in: 09 55

เวลาออก  
Time out: 15 min

ที่อยู่  
Address:

โทรศัพท์  
Tel:

ชื่อโครงการ  
Project name:

บุคคลที่ติดต่อ  
Contacted name:

สถานที่ตั้งโครงการ  
Location:

**ประวัติเครื่อง**  
**Detail of Machine:**

**รายละเอียดการตรวจซ่อม**  
**Detail of Repair:**

[illegible]

ผลการตรวจเช็คเครื่อง  
Pre-repair Check:

อะไหล่ที่เปลี่ยน  
Parts Replaced

90671906603704000000  
 106003 2000000000000000  
 6600000000000000 9, 10, 11  
 12, 12A

Sub 9	2	2	0.7
Sub 10	2	1	0.7
Sub 11	2	1	0.7
Sub 12	2	2	0.7
Sub 12A	2	2	0.7

จำนวน Q'ty	รายการ Description	หน่วยละ Unit Price	รวมเงิน Total Price
---------------	-----------------------	-----------------------	------------------------

[illegible]

ค่าบริการ	Service charge
ภาษีมูลค่าเพิ่ม	Vat 7%
รวมเงินทั้งหมด	Total

หมายเหตุ  
Comments:

ตรวจสอบโดย  
Approval:

รับรองว่าได้ตรวจซ่อมเครื่องเสร็จแล้ว

**Certified that the reparation has been satisfactorily completed.**

## ลายมือชื่อช่างซ่อม

**Technician's Signature**

ลายมือชื่อลูกค้า

**Customer's Signature .....**



ใบสั่งงาน  
JOB ORDER

เลขที่ 5569  
No.

ซ่อม  
Repair

☒ ตรวจเช็ค  
Check

แผนกบริการ  
(SERVICE DEPT.)

ชื่อลูกค้า  
Name of Customer: ทรัพย์ชัย

วันที่  
Date: 22/2/67

เวลาเข้า  
Time in: 10.15

เวลาออก  
Time out: 1500

ที่อยู่  
Address:

โทรศัพท์  
Tel:

ชื่อโครงการ  
Project name:

บุคคลที่ติดต่อ  
Contacted name:

สถานที่ตั้งโครงการ  
Location:

ประวัติเครื่อง  
Detail of Machine:

รายละเอียดการตรวจซ่อม  
Detail of Repair:

นางชอมน

ผลการตรวจเช็คเครื่อง  
Pre-repair Check:

**อะไหล่ที่เปลี่ยน**  
**Parts Replaced**

[illegible]

จำนวน  
Q'ty

## รายการ Description

หน่วยละ  
Unit Price

รวมเงิน  
Total Price

ค่าบริการ  
Service charge

ภาษีมูลค่าเพิ่ม  
Vat 7%

รวมเงินทั้งหมด  
Total

หมายเหตุ  
Comments:

ตรวจโดย  
Approval:

รับรองว่าได้ตรวจซ่อมเครื่องเสร็จแล้ว

**Certified that the reparation has been satisfactorily completed.**

ลายมือชื่อช่างซ่อม  
Technician's Signature

ลายมือชื่อลูกค้า  
Customer's Signature .....





วันที่บังคับใช้: 27 / 12 / 42

แก้ไขครั้งที่ : 0

ใบสั่งงาน  
JOB ORDER

เลขที่ 5651  
No.

ซ่อม  
Repair

☒ ตรวจสอบ ✓  
Check

แผนกบริการ  
(SERVICE DEPT.)

ชื่อลูกค้า  
Name of Customer:

วันที่  
Date:

เวลาเข้า  
Time in:

เวลาออก  
Time out:

ที่อยู่  
Address:

โทรศัพท์  
Tel:

ชื่อโครงการ  
Project name:

บุคคลที่ติดต่อ  
Contacted name:

สถานที่ตั้งโครงการ  
Location:

**ประวัติเครื่อง**  
**Detail of Machine:**

**รายละเอียดการตรวจซ่อม**  
**Detail of Repair:**

ผลการตรวจเช็คเครื่อง  
Pre-repair Check:

**อะไหล่ที่เปลี่ยน**  
**Parts Replaced**

จำนวน  
Q'ty

รายการ	Description
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...
66	...
67	...
68	...
69	...
70	...
71	...
72	...
73	...
74	...
75	...
76	...
77	...
78	...
79	...
80	...
81	...
82	...
83	...
84	...
85	...
86	...
87	...
88	...
89	...
90	...
91	...
92	...
93	...
94	...
95	...
96	...
97	...
98	...
99	...
100	...

Unit Pr

**รวมเงิน**  
**Total Price**

[illegible]

ค่าบริการ  
Service charge

ภาษีมูลค่าเพิ่ม  
Vat 7%

รวมเงินทั้งหมด  
Total

หมายเหตุ  
Comments:

ตรวจโดย  
Approval:

รับรองว่าได้ตรวจซ่อมเครื่องเสร็จแล้ว  
Certified that the reparation has been satisfactorily completed.

ลายมือชื่อช่างซ่อม  
Technician's Signature

ลายมือชื่อลูกค้า  
Customer's Signature .....





วันที่บังคับใช้: 27 / 12 / 42

แก้ไขครั้งที่ : 0

ใบสั่งงาน  
JOB ORDER

เลขที่ 5653  
No.

☐ซ่อม  
Repair

☐ ตรวจสอบ ✓  
Check

แผนกบริการ  
(SERVICE DEPT.)

ชื่อลูกค้า  
Name of Customer:

วันที่  
Date:

เวลาเข้า  
Time in:

เวลาออก  
Time out:

ที่อยู่  
Address:

โทรศัพท  
Tel:

ชื่อโครงการ  
Project name:

บุคคลที่ติดต่อ  
Contacted name:

สถานที่ตั้งโครงการ  
Location:

ประวัติเครื่อง  
Detail of Machine:

รายละเอียดการตรวจซ่อม  
Detail of Repair:

วันที่ 14/4/25 P.M.S: NAB Normal วันที่ 21-28

ผลการตรวจเช็คเครื่อง  
Pre-repair Check:

**อะไหล่ที่เปลี่ยน**  
**Parts Replaced**

จำนวน  
Q'ty

## รายการ Description

หน่วยละ  
Unit Price

รวมเงิน  
Total Price

Q'ty	
1000	1000

00126748112

ตุลาคม ๒๕๖๓

ក្នុងរយៈពេល ៥ ឆ្នាំ ទៀងទាត់បាន ៧៩៧៦

ค่าบริการ  
Service charge

ภาษีมูลค่าเพิ่ม  
Vat 7%

รวมเงินทั้งหมด  
Total

หมายเหตุ  
Comments:

ตรวจโดย  
Approval:

รับรองว่าได้ตรวจซ่อมเครื่องเสร็จแล้ว

**Certified that the reparation has been satisfactorily completed.**

ลายมือชื่อช่างซ่อม  
Technician's Signature

\_\_\_\_\_



ใบสั่งงาน  
JOB ORDER

เลขที่  
No. 5655

☐ ซ่อม  
Repair

☒ ตรวจเช็ค  
Check

แผนกบริการ  
(SERVICE DEPT.)

ชื่อลูกค้า  
Name of Customer: ไพรัช  
วันที่  
Date: 11/3/2567 เวลาเข้า  
Time in: 10:05 เวลาออก  
Time out: 15:00

ที่อยู่  
Address: โทรศัพท์  
Tel: ชื่อโครงการ  
Project name: ไพรัช

บุคคลที่ติดต่อ  
Contacted name: สถานที่ตั้งโครงการ  
Location: ไพรัช

ประวัติเครื่อง  
Detail of Machine:

รายละเอียดการตรวจซ่อม  
Detail of Repair: เบ็ดตัว P.M. ระบุรายการ 29, 30, 31, 32, 33 (5 ปี)

ผลการตรวจเช็คเครื่อง  
Pre-repair Check:

ไพรัช P.M. ระบุรายการ  
29, 30, 31, 32, 33  
จำนวน 5 ปี  
โครงการออดิฟิเคอร์ 00021 ท. 2562-010  
และ ติดตั้ง เอนไซม์ในรถบรรทุกคันนี้  
ถึง 2562 5 ปี  
ใช้ใบได้ 2562

อะไหล่ที่เปลี่ยน  
Parts Replaced

จำนวน Q'ty	รายการ Description	หน่วยละ Unit Price	รวมเงิน Total Price

ค่าบริการ  
Service charge  
ภาษีมูลค่าเพิ่ม  
Vat 7%  
รวมเงินทั้งหมด  
Total

หมายเหตุ  
Comments:


ตรวจโดย  
Approval:

รับรองว่าได้ตรวจซ่อมเครื่องเสร็จแล้ว  
Certified that the reparation has been satisfactorily completed.

ลายมือชื่อช่างซ่อม  
Technician's Signature

ลายมือชื่อลูกค้า  
Customer's Signature





บริษัท เพาเวอร์ไลน์ เอ็นจิเนียริง จำกัด (มหาชน)  
POWER LINE ENGINEERING PUBLIC COMPANY LIMITED

FM-ENG-52

วันที่บังคับใช้: 27/12/42

แก้ไขครั้งที่ : 0

## ใบสั่งงาน JOB ORDER

เลขที่  
No. **5656**

☐ ซ่อม  
Repair

☒ ตรวจสอบ  
Check

### แผนกบริการ (SERVICE DEPT.)

ชื่อลูกค้า  
Name of Customer:

โพรซีเอ็ม

วันที่  
Date:

4/3/2567

เวลาเข้า  
Time in:

09:10

เวลาออก  
Time out:

15:00

ที่อยู่  
Address:

โทรศัพท์  
Tel:

ชื่อโครงการ  
Project name:

โพรซีเอ็ม

บุคคลที่ติดต่อ  
Contacted name:

สถานที่ตั้งโครงการ  
Location:

บริเวณ

ประวัติเครื่อง  
Detail of Machine:

รายละเอียดการตรวจซ่อม  
Detail of Repair:

โพรซีเอ็ม ตรวจสอบระบบไฟฟ้า 34-38 (บริเวณ 5)

ผลการตรวจเช็คเครื่อง  
Pre-repair Check:

พบการชำรุดของระบบไฟฟ้า  
21 ทำตามคำแนะนำและดูแล  
เดินไฟระบบใหม่  
34, 35, 36, 37, 38  
เป็นจำนวน 5

อะไหล่ที่เปลี่ยน  
Parts Replaced

จำนวน Q'ty	รายการ Description	หน่วยละ Unit Price	รวมเงิน Total Price

ค่าบริการ  
Service charge

ภาษีมูลค่าเพิ่ม  
Vat 7%

รวมเงินทั้งหมด  
Total

หมายเหตุ  
Comments:

ตรวจโดย  
Approval:

รับรองว่าได้ตรวจซ่อมเครื่องเสร็จแล้ว

Certified that the reparation has been satisfactorily completed.

ลายมือชื่อช่างซ่อม  
Technician's Signature

ลายมือชื่อลูกค้า  
Customer's Signature



Customer's Signature .....











ใบสั่งงาน  
JOB ORDER

เลขที่ 5577  
No.

☐ซ่อม  
Repair

☐ ตรวจเช็ค  
Check

**แผนกบริการ  
(SERVICE DEPT.)**

ชื่อลูกค้า  
Name of Customer: นางสาวสุวิมล วัฒนศิริ

วันที่  
Date: 14/3/67

เวลาเข้า  
Time in:

เวลาออก  
Time out:

ที่อยู่  
Address:

โทรศัพท์  
Tel:

ชื่อโครงการ  
Project name:

บุคคลที่ติดต่อ  
Contacted name:

สถานที่ตั้งโครงการ  
Location:

**ประวัติเครื่อง**  
**Detail of Machine:**

**รายละเอียดการตรวจซ่อม**  
**Detail of Repair:**

เจ้าพนักงานพรตราชวิทยาลัยกรมตำรวจ

ผลการตรวจเช็คเครื่อง  
Pre-repair Check:

อะไหล่ที่เปลี่ยน  
Parts Replaced

[illegible]

จำนวน Q'ty	รายการ Description	หน่วยละ Unit Price	รวมเงิน Total Price
ค่าบริการ Service charge			
ภาษีมูลค่าเพิ่ม Vat 7%			
รวมเงินทั้งหมด Total			

หมายเหตุ  
Comments:

ตรวจโดย  
Approval:

รับรองว่าได้ตรวจซ่อมเครื่องเสร็จแล้ว  
Certified that the reparation has been satisfactorily completed.

ลายมือชื่อช่างซ่อม  
Technician's Signature

ลายมือชื่อลูกค้า  
Customer's Signature .....



ลายมือชื่อลูกค้า  
Customer's Sig



<div style="float: right;">ใบสั่งงาน</div> <div style="clear: both;"></div> <b>JOB ORDER</b>				
เลขที่ No.	<b>5580</b>	<input type="checkbox"/> ซ่อม Repair	<input checked="" type="checkbox"/> ตรวจเช็ค Check	
<b>แผนกบริการ</b> <b>(SERVICE DEPT.)</b>				
ชื่อลูกค้า Name of Customer:	<b>โพรเซสเซอร์</b>	วันที่ Date:	<b>20/3/67</b>	เวลาเข้า Time in:
ที่อยู่ Address:		โทรศัพท์ Tel:		ชื่อโครงการ Project name:
บุคคลที่ติดต่อ Contacted name:	สถานที่ตั้งโครงการ Location: <b>บริษัท...</b>			
ประวัติเครื่อง Detail of Machine:				
รายละเอียดการตรวจซ่อม Detail of Repair:	<b>ได้ส่งปมระบบปรับอัตโนมัติโดยโพรเซสเซอร์</b>			
ผลการตรวจเช็คเครื่อง Pre-repair Check:	อะไหล่ที่เปลี่ยน Parts Replaced			
<b>บ้ำปมระบบปรับอัตโนมัติโดยปม</b> <b>ขดลวดมอเตอร์ มอเตอร์ความถี่=๓๐</b> <b>๖๖๕ ตรวจสอบ เบ็ดของมอเตอร์แบบคาล</b> <b>๖๖๕ มอเตอร์ไฟฟ้าตัวเล็ก ดูดน้ำ</b> <b>๖๖๕ บัดรีด</b> <b>ชิ้น หัวลิฟท์ ๗3 : ๑ ตัว</b> <b>ชิ้น 3 พิตาน</b> : 3 ตัว	จำนวน Q'ty	รายการ Description	หน่วยละ Unit Price	รวมเงิน Total Price
		ค่าบริการ Service charge		
		ภาษีมูลค่าเพิ่ม Vat 7%		
		รวมเงินทั้งหมด Total		
หมายเหตุ Comments:	ตรวจโดย Approval:			
รับรองว่าได้ตรวจซ่อมเครื่องเสร็จแล้ว Certified that the reparation has been satisfactorily completed.				
ลายมือชื่อช่าง Technician's Signature .....		ลายมือชื่อลูกค้า Customer's Signature .....		

[illegible]





## Productivity Report

### Four Seasons Hotel Bangkok at Chao Phraya River

| Date From: 01/02/24 08:00:00 AM | Date To: 23/05/24 05:00:00 PM | Issue: Air Handler PM-QTR | Dept. Responsible: Engineering PM

Order #	Issue	Room/Eq	Reported Date	Person First Start	Person Last Stop	Labor Time	Labor Cost
---------	-------	---------	---------------	--------------------	------------------	------------	------------

#### Engineering

##### Person: Chaியasit Tonchai

668375	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 06/03/24 12:00:24 AM 07 (3010)	06/03/24 08:00:58 AM	06/03/24 08:09:21 AM	8 min(s)23 sec(s)	.00
668376	Air Handler PM-QTR	EQ - F - B - A - F / 3 - 06/03/24 12:00:24 AM 02 (3012)	06/03/24 08:01:06 AM	06/03/24 08:09:19 AM	8 min(s)13 sec(s)	.00
668377	Air Handler PM-QTR	EQ - F - B - PAU - F / 06/03/24 12:00:24 AM 2 - 01 (3019)	06/03/24 08:01:06 AM	06/03/24 08:09:17 AM	8 min(s)11 sec(s)	.00
668378	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 06/03/24 12:00:24 AM 03 (3006)	06/03/24 08:00:58 AM	06/03/24 08:09:15 AM	8 min(s)17 sec(s)	.00
668379	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 06/03/24 12:00:24 AM 04 (3007)	06/03/24 08:01:06 AM	06/03/24 08:09:12 AM	8 min(s)6 sec(s)	.00
668380	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 06/03/24 12:00:24 AM 06 (3009)	06/03/24 08:01:06 AM	06/03/24 08:09:10 AM	8 min(s)4 sec(s)	.00
673691	Air Handler PM-QTR	EQ - F - E - PAU - F / 12/03/24 01:00:34 AM LG - 03 (3059)	12/03/24 01:00:34 AM	12/03/24 09:04:39 AM	8 hr(s) 4 min(s)5 sec(s)	.00

##### Chaியasit Tonchai:

***totals:* 8 hr(s) 53 min(s)19 sec(s)**

**7 Orders; Avg.Response Time is 0 sec; Total Labor is 8 hr(s) 53 min(s)19 sec(s)**

***Averages:* 1 hr(s) 16 min(s)11 sec(s)**

##### Person: Phornchai Samaaphat

654798	Air Handler PM-QTR	EQ - F - C - A - F / 2 - 01 (3038)	19/02/24 12:00:14 AM	22/02/24 10:54:47 AM	22/02/24 10:55:51 AM	1 min(s)1 sec(s)	.00
654799	Air Handler PM-QTR	EQ - F - C - A - F / 2 - 02 (3039)	19/02/24 12:00:14 AM	22/02/24 10:57:40 AM	22/02/24 10:58:24 AM	44 sec(s)	.00
654800	Air Handler PM-QTR	EQ - F - C - PAU - F / 19/02/24 12:00:14 AM 2 - 01 (3041)	19/02/24 12:00:14 AM	22/02/24 10:56:55 AM	22/02/24 10:57:28 AM	33 sec(s)	.00
654801	Air Handler PM-QTR	EQ - F - C - PAU - F / 19/02/24 12:00:14 AM 2 - 02 (3042)	19/02/24 12:00:14 AM	22/02/24 10:56:06 AM	22/02/24 10:56:44 AM	38 sec(s)	.00
655750	Air Handler PM-QTR	EQ - F - W - A - F / LG - 01 (701051)	20/02/24 12:00:00 AM	22/02/24 10:41:44 AM	22/02/24 10:51:23 AM	9 min(s)39 sec(s)	.00
655751	Air Handler PM-QTR	EQ - F - W - A - F / LG - 02 (701052)	20/02/24 12:00:00 AM	22/02/24 10:51:37 AM	22/02/24 10:52:57 AM	1 min(s)20 sec(s)	.00
655752	Air Handler PM-QTR	EQ - F - W - HC - PAU - F / LG - 01 (3082)	20/02/24 12:00:00 AM	22/02/24 10:53:41 AM	22/02/24 10:54:23 AM	42 sec(s)	.00
658297	Air Handler PM-QTR	EQ - F - E - A - F / LG1 - 01 (3054)	23/02/24 12:00:37 AM	26/02/24 02:19:30 PM	26/02/24 02:21:44 PM	2 min(s)14 sec(s)	.00
658298	Air Handler PM-QTR	EQ - F - E - A - F / LG - 06 (3053)	23/02/24 12:00:37 AM	26/02/24 02:21:56 PM	26/02/24 02:22:21 PM	25 sec(s)	.00
658299	Air Handler PM-QTR	EQ - F - E - A - F / LG - 05 (3052)	23/02/24 12:00:37 AM	26/02/24 02:22:33 PM	26/02/24 02:23:04 PM	31 sec(s)	.00



# Productivity Report

## Four Seasons Hotel Bangkok at Chao Phraya River

| Date From: 01/02/24 08:00:00 AM | Date To: 23/05/24 05:00:00 PM | Issue: Air Handler PM-QTR | Dept. Responsible: Engineering PM

Order #	Issue	Room/Eq	Reported Date	Person First Start	Person Last Stop	Labor Time	Labor Cost
<b>Engineering</b>							
658300	Air Handler PM-QTR	EQ - F - E - A - F / LG - 04 (3051)	23/02/24 12:00:37 AM	26/02/24 02:23:17 PM	26/02/24 02:24:00 PM	43 sec(s)	.00
658301	Air Handler PM-QTR	EQ - F - E - A - F / LG - 03 (3050)	23/02/24 12:00:37 AM	26/02/24 02:24:13 PM	26/02/24 02:24:39 PM	26 sec(s)	.00
658302	Air Handler PM-QTR	EQ - F - E - A - F / LG - 01 (3048)	23/02/24 12:00:37 AM	26/02/24 02:24:54 PM	26/02/24 02:25:22 PM	28 sec(s)	.00
667628	Air Handler PM-QTR	EQ - F - B - PAU - F / LG - 01 (3016)	05/03/24 12:00:19 AM	19/03/24 10:22:07 AM	19/03/24 10:24:46 AM	2 min(s)39 sec(s)	.00
667629	Air Handler PM-QTR	EQ - F - B - PAU - F / LG - 03 (3018)	05/03/24 12:00:19 AM	19/03/24 10:50:37 AM	19/03/24 10:51:12 AM	35 sec(s)	.00
667630	Air Handler PM-QTR	EQ - F - B - PAU - F / 2 - 02 (3020)	05/03/24 12:00:19 AM	19/03/24 10:49:39 AM	19/03/24 10:50:08 AM	29 sec(s)	.00
667631	Air Handler PM-QTR	EQ - F - B - PAU - F / 2 - 03 (3021)	05/03/24 12:00:19 AM	19/03/24 10:48:27 AM	19/03/24 10:49:24 AM	57 sec(s)	.00
667632	Air Handler PM-QTR	EQ - F - B - PAU - F / 2 - 04 (3022)	05/03/24 12:00:19 AM	19/03/24 10:47:34 AM	19/03/24 10:48:03 AM	29 sec(s)	.00
667633	Air Handler PM-QTR	EQ - F - B - PAU - F / 2 - 05 (3023)	05/03/24 12:00:19 AM	19/03/24 10:45:36 AM	19/03/24 10:46:10 AM	34 sec(s)	.00
667634	Air Handler PM-QTR	EQ - F - C - HC - PAU - F / 2 - 01 (3083)	05/03/24 12:00:19 AM	19/03/24 10:44:40 AM	19/03/24 10:45:21 AM	41 sec(s)	.00
667635	Air Handler PM-QTR	EQ - F - E - A - F / 2 - 05/03/24 12:00:19 AM 01 (3055)	05/03/24 12:00:19 AM	19/03/24 10:43:47 AM	19/03/24 10:44:16 AM	29 sec(s)	.00
667636	Air Handler PM-QTR	EQ - F - E - A - F / 2 - 05/03/24 12:00:19 AM 02 (3056)	05/03/24 12:00:19 AM	19/03/24 10:41:54 AM	19/03/24 10:42:41 AM	47 sec(s)	.00
667637	Air Handler PM-QTR	EQ - F - E - PAU - F / LG - 01 (3057)	05/03/24 12:00:19 AM	19/03/24 10:38:11 AM	19/03/24 10:38:37 AM	26 sec(s)	.00
667638	Air Handler PM-QTR	EQ - F - E - PAU - F / LG - 02 (3058)	05/03/24 12:00:19 AM	19/03/24 10:36:09 AM	19/03/24 10:37:59 AM	1 min(s)50 sec(s)	.00
668367	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 06/03/24 12:00:24 AM 02 (3005)	06/03/24 12:00:24 AM	19/03/24 10:25:55 AM	19/03/24 10:26:23 AM	28 sec(s)	.00
668368	Air Handler PM-QTR	EQ - F - B - A - F / 3 - 06/03/24 12:00:24 AM 01 (3011)	06/03/24 12:00:24 AM	19/03/24 10:25:07 AM	19/03/24 10:25:40 AM	33 sec(s)	.00
668369	Air Handler PM-QTR	EQ - F - B - A - F / LG - 01 (3001)	06/03/24 12:00:24 AM	19/03/24 11:02:55 AM	19/03/24 11:03:19 AM	24 sec(s)	.00
668370	Air Handler PM-QTR	EQ - F - B - A - F / LG - 02 (3002)	06/03/24 12:00:24 AM	19/03/24 10:58:43 AM	19/03/24 11:01:28 AM	2 min(s)45 sec(s)	.00
668371	Air Handler PM-QTR	EQ - F - B - A - F / LG - 03 (3003)	06/03/24 12:00:24 AM	19/03/24 10:58:14 AM	19/03/24 10:58:34 AM	20 sec(s)	.00
668372	Air Handler PM-QTR	EQ - F - S - A - F / LG1 - 03 (3078)	06/03/24 12:00:24 AM	19/03/24 10:57:42 AM	19/03/24 10:58:05 AM	23 sec(s)	.00

# Productivity Report

## Four Seasons Hotel Bangkok at Chao Phraya River

| Date From: 01/02/24 08:00:00 AM | Date To: 23/05/24 05:00:00 PM | Issue: Air Handler PM-QTR | Dept. Responsible: Engineering PM

Order #	Issue	Room/Eq	Reported Date	Person First Start	Person Last Stop	Labor Time	Labor Cost
<b>Engineering</b>							
668373	Air Handler PM-QTR	EQ - F - S - A - F / 4 - 06/03/24 12:00:24 AM 01 (3079)	19/03/24 10:56:06 AM	19/03/24 10:56:30 AM		24 sec(s)	.00
668374	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 06/03/24 12:00:24 AM 05 (3008)	19/03/24 10:55:11 AM	19/03/24 10:55:55 AM		44 sec(s)	.00
668375	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 06/03/24 12:00:24 AM 07 (3010)	19/03/24 10:54:25 AM	19/03/24 10:54:46 AM		21 sec(s)	.00
668376	Air Handler PM-QTR	EQ - F - B - A - F / 3 - 06/03/24 12:00:24 AM 02 (3012)	19/03/24 10:53:41 AM	19/03/24 10:54:11 AM		30 sec(s)	.00
668377	Air Handler PM-QTR	EQ - F - B - PAU - F / 06/03/24 12:00:24 AM 2 - 01 (3019)	19/03/24 10:53:12 AM	19/03/24 10:53:29 AM		17 sec(s)	.00
668378	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 06/03/24 12:00:24 AM 03 (3006)	19/03/24 10:52:43 AM	19/03/24 10:53:01 AM		18 sec(s)	.00
668379	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 06/03/24 12:00:24 AM 04 (3007)	19/03/24 10:52:04 AM	19/03/24 10:52:30 AM		26 sec(s)	.00
668380	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 06/03/24 12:00:24 AM 06 (3009)	19/03/24 10:51:23 AM	19/03/24 10:51:53 AM		30 sec(s)	.00
669257	Air Handler PM-QTR	EQ - F - W - A - F / 2 07/03/24 12:00:59 AM - 01 (3031)	19/03/24 10:29:47 AM	19/03/24 10:30:16 AM		29 sec(s)	.00
669258	Air Handler PM-QTR	EQ - F - B - PAU - F / 07/03/24 12:00:59 AM LG - 02 (3017)	19/03/24 10:29:06 AM	19/03/24 10:29:37 AM		31 sec(s)	.00
669260	Air Handler PM-QTR	EQ - F - W - A - F / 2 07/03/24 12:00:59 AM - 02 (3032)	19/03/24 10:28:23 AM	19/03/24 10:28:56 AM		33 sec(s)	.00
669261	Air Handler PM-QTR	EQ - F - W - A - F / 07/03/24 12:00:59 AM 11 - 01 (3033)	19/03/24 10:27:27 AM	19/03/24 10:28:13 AM		46 sec(s)	.00
669262	Air Handler PM-QTR	EQ - F - W - A - F / 07/03/24 12:00:59 AM 11 - 02 (3034)	19/03/24 10:26:33 AM	19/03/24 10:27:14 AM		41 sec(s)	.00
672507	Air Handler PM-QTR	EQ - F - W - PAU - F 11/03/24 01:00:25 AM / LG - 02 (3036)	19/03/24 11:11:07 AM	19/03/24 11:11:24 AM		17 sec(s)	.00
672508	Air Handler PM-QTR	EQ - F - W - PAU - F 11/03/24 01:00:25 AM / LG - 01 (3035)	19/03/24 11:10:28 AM	19/03/24 11:10:57 AM		29 sec(s)	.00
672509	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 11/03/24 01:00:25 AM 01 (3004)	19/03/24 11:09:08 AM	19/03/24 11:10:19 AM		1 min(s)11 sec(s)	.00
673689	Air Handler PM-QTR	EQ - F - E - PAU - F / 12/03/24 01:00:34 AM LG1 - 02 (3061)	19/03/24 11:12:10 AM	19/03/24 11:12:32 AM		22 sec(s)	.00
673690	Air Handler PM-QTR	EQ - F - E - PAU - F / 12/03/24 01:00:34 AM LG1 - 01 (3060)	19/03/24 11:11:34 AM	19/03/24 11:12:01 AM		27 sec(s)	.00
673691	Air Handler PM-QTR	EQ - F - E - PAU - F / 12/03/24 01:00:34 AM LG - 03 (3059)	19/03/24 10:46:32 AM	19/03/24 10:47:19 AM		47 sec(s)	.00
708895	Air Handler PM-QTR	EQ - F - C - A - F / 2 15/04/24 01:00:22 AM - 01 (3038)	13/05/24 03:40:41 PM	13/05/24 03:43:23 PM		2 min(s)42 sec(s)	.00
708896	Air Handler PM-QTR	EQ - F - C - A - F / 2 15/04/24 01:00:22 AM - 02 (3039)	13/05/24 03:44:23 PM	13/05/24 03:44:49 PM		26 sec(s)	.00



# Productivity Report

## Four Seasons Hotel Bangkok at Chao Phraya River

| Date From: 01/02/24 08:00:00 AM | Date To: 23/05/24 05:00:00 PM | Issue: Air Handler PM-QTR | Dept. Responsible: Engineering PM

Order #	Issue	Room/Eq	Reported Date	Person First Start	Person Last Stop	Labor Time	Labor Cost
<b>Engineering</b>							
708897	Air Handler PM-QTR	EQ - F - C - PAU - F / 2 - 01 (3041)	15/04/24 01:00:22 AM	13/05/24 03:43:39 PM	13/05/24 03:44:10 PM	31 sec(s)	.00
708898	Air Handler PM-QTR	EQ - F - C - PAU - F / 2 - 02 (3042)	15/04/24 01:00:22 AM	08/05/24 04:07:49 PM	08/05/24 04:10:27 PM	2 min(s)38 sec(s)	.00
710023	Air Handler PM-QTR	EQ - F - W - A - F / LG - 02 (701052)	16/04/24 01:00:01 AM	13/05/24 03:46:30 PM	13/05/24 03:46:56 PM	26 sec(s)	.00
710024	Air Handler PM-QTR	EQ - F - W - HC - PAU - F / LG - 01 (3082)	16/04/24 01:00:01 AM	13/05/24 03:45:04 PM	13/05/24 03:46:19 PM	1 min(s)15 sec(s)	.00
715988	Air Handler PM-QTR	EQ - F - E - A - F / LG1 - 01 (3054)	22/04/24 01:00:28 AM	13/05/24 04:02:37 PM	13/05/24 04:03:05 PM	28 sec(s)	.00
715989	Air Handler PM-QTR	EQ - F - E - A - F / LG - 06 (3053)	22/04/24 01:00:28 AM	13/05/24 03:51:36 PM	13/05/24 03:52:09 PM	33 sec(s)	.00
715990	Air Handler PM-QTR	EQ - F - E - A - F / LG - 05 (3052)	22/04/24 01:00:28 AM	13/05/24 03:51:04 PM	13/05/24 03:51:25 PM	21 sec(s)	.00
715991	Air Handler PM-QTR	EQ - F - E - A - F / LG - 04 (3051)	22/04/24 01:00:28 AM	13/05/24 03:50:32 PM	13/05/24 03:50:52 PM	20 sec(s)	.00
715995	Air Handler PM-QTR	EQ - F - E - A - F / LG - 03 (3050)	22/04/24 01:00:28 AM	13/05/24 03:48:26 PM	13/05/24 03:49:21 PM	55 sec(s)	.00
715996	Air Handler PM-QTR	EQ - F - E - A - F / LG - 01 (3048)	22/04/24 01:00:28 AM	13/05/24 03:47:29 PM	13/05/24 03:47:57 PM	28 sec(s)	.00
726304	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 01/05/24 01:00:40 AM 02 (3005)	01/05/24 01:00:40 AM	13/05/24 04:22:44 PM	13/05/24 04:23:03 PM	19 sec(s)	.00
726305	Air Handler PM-QTR	EQ - F - B - A - F / 3 - 01/05/24 01:00:40 AM 01 (3011)	01/05/24 01:00:40 AM	13/05/24 04:22:15 PM	13/05/24 04:22:33 PM	18 sec(s)	.00
726306	Air Handler PM-QTR	EQ - F - B - A - F / LG - 01 (3001)	01/05/24 01:00:40 AM	13/05/24 04:21:31 PM	13/05/24 04:21:55 PM	24 sec(s)	.00
726307	Air Handler PM-QTR	EQ - F - B - A - F / LG - 02 (3002)	01/05/24 01:00:40 AM	13/05/24 04:20:38 PM	13/05/24 04:21:19 PM	41 sec(s)	.00
726308	Air Handler PM-QTR	EQ - F - B - A - F / LG - 03 (3003)	01/05/24 01:00:40 AM	13/05/24 04:18:00 PM	13/05/24 04:18:33 PM	33 sec(s)	.00
726309	Air Handler PM-QTR	EQ - F - S - A - F / LG1 - 03 (3078)	01/05/24 01:00:40 AM	13/05/24 04:17:22 PM	13/05/24 04:17:44 PM	22 sec(s)	.00
726310	Air Handler PM-QTR	EQ - F - S - A - F / 4 - 01/05/24 01:00:40 AM 01 (3079)	01/05/24 01:00:40 AM	13/05/24 04:15:31 PM	13/05/24 04:15:54 PM	23 sec(s)	.00
726311	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 01/05/24 01:00:40 AM 05 (3008)	01/05/24 01:00:40 AM	13/05/24 04:14:57 PM	13/05/24 04:15:19 PM	22 sec(s)	.00
726312	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 01/05/24 01:00:40 AM 07 (3010)	01/05/24 01:00:40 AM	13/05/24 04:14:28 PM	13/05/24 04:14:47 PM	19 sec(s)	.00
726313	Air Handler PM-QTR	EQ - F - B - A - F / 3 - 01/05/24 01:00:40 AM 02 (3012)	01/05/24 01:00:40 AM	13/05/24 04:13:36 PM	13/05/24 04:13:58 PM	22 sec(s)	.00

# Productivity Report

## Four Seasons Hotel Bangkok at Chao Phraya River

| Date From: 01/02/24 08:00:00 AM | Date To: 23/05/24 05:00:00 PM | Issue: Air Handler PM-QTR | Dept. Responsible: Engineering PM

Order #	Issue	Room/Eq	Reported Date	Person First Start	Person Last Stop	Labor Time	Labor Cost
<b>Engineering</b>							
726314	Air Handler PM-QTR	EQ - F - B - PAU - F / 2 - 01 (3019)	01/05/24 01:00:40 AM	13/05/24 04:13:06 PM	13/05/24 04:13:24 PM	18 sec(s)	.00
726315	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 03 (3006)	01/05/24 01:00:40 AM	13/05/24 04:12:38 PM	13/05/24 04:12:54 PM	16 sec(s)	.00
726316	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 04 (3007)	01/05/24 01:00:40 AM	13/05/24 04:12:03 PM	13/05/24 04:12:25 PM	22 sec(s)	.00
726317	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 06 (3009)	01/05/24 01:00:40 AM	13/05/24 04:11:34 PM	13/05/24 04:11:53 PM	19 sec(s)	.00
727755	Air Handler PM-QTR	EQ - F - W - A - F / 2 - 01 (3031)	02/05/24 01:00:05 AM	13/05/24 04:26:49 PM	13/05/24 04:27:17 PM	28 sec(s)	.00
727756	Air Handler PM-QTR	EQ - F - B - PAU - F / LG - 02 (3017)	02/05/24 01:00:05 AM	13/05/24 04:26:14 PM	13/05/24 04:26:39 PM	25 sec(s)	.00
727758	Air Handler PM-QTR	EQ - F - W - A - F / 2 - 02 (3032)	02/05/24 01:00:05 AM	13/05/24 04:24:28 PM	13/05/24 04:25:00 PM	32 sec(s)	.00
727759	Air Handler PM-QTR	EQ - F - W - A - F / 11 - 01 (3033)	02/05/24 01:00:05 AM	13/05/24 04:23:46 PM	13/05/24 04:24:19 PM	33 sec(s)	.00
727760	Air Handler PM-QTR	EQ - F - W - A - F / 11 - 02 (3034)	02/05/24 01:00:05 AM	13/05/24 04:23:13 PM	13/05/24 04:23:37 PM	24 sec(s)	.00
733840	Air Handler PM-QTR	EQ - F - E - PAU - F / LG - 02 (3058)	07/05/24 01:00:03 AM	13/05/24 04:50:19 PM	13/05/24 04:50:58 PM	39 sec(s)	.00
733841	Air Handler PM-QTR	EQ - F - E - PAU - F / LG - 01 (3057)	07/05/24 01:00:03 AM	13/05/24 04:49:36 PM	13/05/24 04:50:00 PM	24 sec(s)	.00
733842	Air Handler PM-QTR	EQ - F - S - A - F / 02 (3080)	07/05/24 01:00:03 AM	13/05/24 04:48:54 PM	13/05/24 04:49:20 PM	26 sec(s)	.00
733843	Air Handler PM-QTR	EQ - F - S - HC - PAU - F / 4 - 02 (3085)	07/05/24 01:00:03 AM	13/05/24 04:48:14 PM	13/05/24 04:48:39 PM	25 sec(s)	.00
733844	Air Handler PM-QTR	EQ - F - S - HC - PAU - F / 4 - 01 (3084)	07/05/24 01:00:03 AM	13/05/24 04:47:31 PM	13/05/24 04:48:00 PM	27 sec(s)	.00
733845	Air Handler PM-QTR	EQ - F - S - PAU - F / LG1 - 01 (3081)	07/05/24 01:00:03 AM	13/05/24 04:46:41 PM	13/05/24 04:47:09 PM	28 sec(s)	.00
733846	Air Handler PM-QTR	EQ - F - S - A - F / LG1 - 02 (3077)	07/05/24 01:00:03 AM	13/05/24 04:45:13 PM	13/05/24 04:45:49 PM	36 sec(s)	.00
733847	Air Handler PM-QTR	EQ - F - S - A - F / LG1 - 01 (3076)	07/05/24 01:00:03 AM	13/05/24 04:44:19 PM	13/05/24 04:44:57 PM	38 sec(s)	.00
733848	Air Handler PM-QTR	EQ - F - S - A - F / LG - 02 (3075)	07/05/24 01:00:03 AM	13/05/24 04:43:24 PM	13/05/24 04:44:02 PM	38 sec(s)	.00
733849	Air Handler PM-QTR	EQ - F - S - A - F / LG - 01 (3074)	07/05/24 01:00:03 AM	13/05/24 04:42:27 PM	13/05/24 04:43:05 PM	38 sec(s)	.00
733850	Air Handler PM-QTR	EQ - F - E - A - F / 2 - 02 (3056)	07/05/24 01:00:03 AM	13/05/24 04:41:40 PM	13/05/24 04:42:09 PM	29 sec(s)	.00



# Productivity Report

## Four Seasons Hotel Bangkok at Chao Phraya River

| Date From: 01/02/24 08:00:00 AM | Date To: 23/05/24 05:00:00 PM | Issue: Air Handler PM-QTR | Dept. Responsible: Engineering PM

Order #	Issue	Room/Eq	Reported Date	Person First Start	Person Last Stop	Labor Time	Labor Cost
<b>Engineering</b>							
733851	Air Handler PM-QTR	EQ - F - E - A - F / 2 - 07/05/24 01:00:03 AM 01 (3055)	13/05/24 04:40:26 PM	13/05/24 04:41:09 PM		43 sec(s)	.00
733852	Air Handler PM-QTR	EQ - F - C - HC - PAU - F / 2 - 01 (3083)	07/05/24 01:00:03 AM	13/05/24 04:39:27 PM	13/05/24 04:40:08 PM	41 sec(s)	.00
733853	Air Handler PM-QTR	EQ - F - B - PAU - F / 07/05/24 01:00:03 AM 2 - 05 (3023)	13/05/24 04:38:41 PM	13/05/24 04:39:14 PM		33 sec(s)	.00
733854	Air Handler PM-QTR	EQ - F - B - PAU - F / 07/05/24 01:00:03 AM 2 - 04 (3022)	13/05/24 04:36:51 PM	13/05/24 04:37:19 PM		28 sec(s)	.00
733855	Air Handler PM-QTR	EQ - F - B - PAU - F / 07/05/24 01:00:03 AM 2 - 03 (3021)	13/05/24 04:36:00 PM	13/05/24 04:36:26 PM		26 sec(s)	.00
733856	Air Handler PM-QTR	EQ - F - B - PAU - F / 07/05/24 01:00:03 AM 2 - 02 (3020)	13/05/24 04:35:21 PM	13/05/24 04:35:48 PM		27 sec(s)	.00
733857	Air Handler PM-QTR	EQ - F - B - PAU - F / 07/05/24 01:00:03 AM LG - 03 (3018)	13/05/24 04:34:39 PM	13/05/24 04:35:09 PM		30 sec(s)	.00
733858	Air Handler PM-QTR	EQ - F - B - PAU - F / 07/05/24 01:00:03 AM LG - 01 (3016)	13/05/24 04:33:30 PM	13/05/24 04:33:55 PM		25 sec(s)	.00
739288	Air Handler PM-QTR	EQ - F - W - PAU - F / LG - 02 (3036)	13/05/24 01:00:34 AM	13/05/24 04:56:28 PM	13/05/24 04:57:10 PM	42 sec(s)	.00
739289	Air Handler PM-QTR	EQ - F - W - PAU - F / LG - 01 (3035)	13/05/24 01:00:34 AM	13/05/24 04:55:33 PM	13/05/24 04:56:17 PM	44 sec(s)	.00
739290	Air Handler PM-QTR	EQ - F - B - A - F / 2 - 13/05/24 01:00:34 AM 01 (3004)	13/05/24 04:54:05 PM	13/05/24 04:54:53 PM		48 sec(s)	.00
740134	Air Handler PM-QTR	EQ - F - E - PAU - F / 14/05/24 01:00:28 AM LG1 - 02 (3061)	14/05/24 01:30:02 PM	14/05/24 01:30:30 PM		28 sec(s)	.00
740135	Air Handler PM-QTR	EQ - F - E - PAU - F / 14/05/24 01:00:28 AM LG1 - 01 (3060)	14/05/24 01:29:34 PM	14/05/24 01:29:53 PM		19 sec(s)	.00
740136	Air Handler PM-QTR	EQ - F - E - PAU - F / 14/05/24 01:00:28 AM LG - 03 (3059)	14/05/24 01:28:45 PM	14/05/24 01:29:17 PM		32 sec(s)	.00
<b>Phornchai Samaaphat:</b>						<b><i>totals:</i> 1 hr(s) 16 min(s)33 sec (s)</b>	<b>.00</b>
105 Orders; Avg.Response Time is 257 hr(s) 28 min(s)11 sec(s); Total Labor is 1 hr(s) 16 min(s)33 sec(s)						<b><i>Averages:</i> 44 sec(s)</b>	<b>.00</b>
<b>Engineering</b>						<b><i>totals:</i> 10 hr(s) 9 min(s)52 sec (s)</b>	<b>.00</b>
						<b><i>Averages:</i> 5 min(s)27 sec(s)</b>	<b>.00</b>
						<b><i>totals:</i> 10 hr(s) 9 min(s)52 sec (s)</b>	<b>.00</b>
						<b><i>Averages:</i> 5 min(s)27 sec(s)</b>	<b>.00</b>

## ***Productivity Report***

### Four Seasons Hotel Bangkok at Chao Phraya River

---

| Date From: 01/02/24 08:00:00 AM | Date To: 23/05/24 05:00:00 PM | Issue: Air Handler PM-QTR | Dept. Responsible: Engineering PM



Preventive Maintenance					4																																
No.	Unit Code	Room	Description Preventive Maintenance	DONE DATE	By	April																															
1	C(R)-F-F/LG-25	Purchasing Manager	Receiving	14/4/24		3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30				
2	C(R)-F-F/LG-26	Purchasing Office	Receiving	14/4/24																																	
3	C(R)-F-F/LG-27	Receiving	Receiving	14/4/24																																	
4	C(R)-F-F/LG-32	Corridor Wide	Receiving	16/4/24																																	
5	C(R)-F-F/LG-24	Receiving Wash	Receiving	14/4/24																																	
6	C(R)-F-F/LG-23	General store	Receiving	21/4/24																																	
7	C(R)-F-F/LG-22	Dry store	Receiving	16/4/24																																	
8	C(R)-F-F/LG-21	Beverag store	Receiving	21/4/24																																	
9	C(R)-F-F/LG-20	Meat treparation	Receiving	20/4/24																																	
10	C(R)-F-F/LG-19	Seafood	Receiving	14/4/24																																	
11	C(R)-F-F/LG-18	veg/fruit prep(CR-07)	Receiving	14/4/24																																	
12	C(R)-F-F/LG-30	Corridor Wide	Receiving	16/4/24																																	
13	C(R)-F-F/LG-31	Corridor Wide	Receiving	14/4/24																																	
14	C(R)-F-F/LG-37	Corridor Wide	Receiving	14/4/24																																	
15	C(R)-F-F/LG-17	Corridor Wide	Receiving	14/4/24																																	
16	C(R)-F-F/LG-10	Bakery	BAKERY	14/4/24																																	
17	C(R)-F-F/LG-11	Chocolas room	BAKERY	13/4/24																																	
18	C(R)-F-F/LG-12	Pasttry	BAKERY	14/4/24																																	
19	C(R)-F-F/LG-19	Bakery	BAKERY	14/4/24																																	
20	C(R)-F-F/LG-08	Pot/pan wash	BAKERY	14/4/24																																	
21	C(R)-F-F/LG-28	Corridor Wide	BAKERY	14/4/24																																	
22	C(R)-F-F/LG-29	Corridor Wide	BAKERY	16/4/24																																	
23	C(R)-F-F/LG-13	Chef office	MAIN KITCHEN	14/4/24																																	
24	C(R)-F-F/LG-14	Executive chef	MAIN KITCHEN	20/4/24																																	
25	C(R)-F-F/LG-15	Room service1	MAIN KITCHEN	21/4/24																																	
26	C(R)-F-F/LG-16	Room service2	MAIN KITCHEN	26/4/24																																	
27	C(R)-F-F/LG-35	Corridor Wide/chef	MAIN KITCHEN	14/4/24																																	
28	C(R)-F-F/LG-36	Corridor Wide/chef	MAIN KITCHEN	14/4/24																																	
29	C(R)-F-F/LG-01	Dish Wash mainkitchen	MAIN KITCHEN	14/4/24																																	
30	C(R)-F-F/LG-02	Steward store	MAIN KITCHEN	14/4/24																																	
31	C(R)-F-F/LG-03	Service station	MAIN KITCHEN	15/4/24																																	
32	C(R)-F-F/LG-04	Cooking area	MAIN KITCHEN	14/4/24																																	
33	C(R)-F-F/LG-05	Cooking area	MAIN KITCHEN	14/4/24																																	
34	C(R)-F-F/LG-06	Service station	MAIN KITCHEN	14/4/24																																	
35	C(R)-F-F/LG-07	Coold kitchen	MAIN KITCHEN	20/4/24																																	
36	C(R)-F-F/LG-33	Corridor Wide	MAIN KITCHEN	23/4/24																																	
37	C(R)-F-F/LG-34	Corridor Wide	MAIN KITCHEN	14/4/24																																	
38	C(R)-F-F/LG-01	Cooking area	BQ KITCHEN	14/4/24																																	
39	C(R)-F-F/LG-02	Cooking area	BQ KITCHEN	14/4/24																																	
40	C(R)-F-F/LG-03	Pot/pan wash	BQ KITCHEN	14/4/24																																	
41	C(R)-F-F/LG-04	CR-14 Area	BQ KITCHEN	14/4/24																																	
42	C(R)-F-F/LG-05	Cooking area	BQ KITCHEN	14/4/24																																	
43	C(R)-F-F/LG-06	Coold kitchen BQ area	BQ KITCHEN	14/4/24																																	
44	C(R)-F-F/LG-07	Steward store	BQ KITCHEN	14/4/24																																	
45	C(R)-F-F/LG-08	Dish wash	BQ KITCHEN	14/4/24																																	
46	C(R)-F-F/LG-09	Service station	BQ KITCHEN	14/4/24																																	
47	C(R)-F-F/LG-10	Service station	BQ KITCHEN	14/4/24																																	
48	C(R)-F-F/LG-11	Room AV	Room AV FIZ	14/4/24																																	
49	C-F-F/LG-01	COTE Service station	Cote	23/4/24																																	
50	C-F-F/LG-02	COTE Cooking area	Cote	19/4/24																																	
51	C-F-F/LG-04	Coold kitchen	Cote	19/4/24																																	
52	C-F-F/LG-05	STORE	Cote	14/4/24																																	
53	C-F-F/LG-15	Staff canteen 2 (CANTEEN)	Staff canteen	14/4/24																																	
54	C-F-F/LG-16	Staff Kitchen (CANTEEN)	Staff canteen	14/4/24																																	
55	C-F-F/LG-14	Staff canteen 1 (CANTEEN)	Staff canteen	14/4/24																																	
56	C-F-F/LG-17	Dish wash 1 (CANTEEN)	Staff canteen	14/4/24																																	
57	C-F-F/LG-18	Dish wash 2 (CANTEEN)	Staff canteen	14/4/24																																	
Total FCU = 57																																					

Total FCU = 57

Remark

D : Daily  
W : Weekly  
M : Monthly  
Q : Quarterly  
S : Semi - Yearly  
Y : Yearly  
B : 2 Monthly

B : 2



Capella Bangkok

HOTEL Floor LL, RECEIVING 1

## PREVENTIVE MAINTENANCE YEAR 2024

 NORMAL = N  
 AB NORMAL = AB

1,8

## AIR CONDITION SYSTEM FAN COIL UNIT

Month	EQUIPMENTS NAME TASK	C-F-F/LG-25 Purchasing manager	C-F-F/LG-26 Purchasing office	C-F-F/LG-27 Receiving	C-F-F/LG-32 Corridor Wide	C-F-F/LG-24 Receiving washing area	C-F-F/LG-23 General store	C-F-F/LG-22 Dry food store	C-F-F/LG-21 Beverage store
M	1. Cleaning strainer ล้างสแตนเนอร์	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No
	2. Test operation of thermostat ทดสอบการทำงานของเทอร์โมสตาท	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB
	3. Test operation of motorized valve ทดสอบการทำงานของมอเตอร์ไคร์ฟวาล์ว	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB
	4. Check noise and vibration of motor ตรวจสอบเสียงและการสั่นสะเทือนของมอเตอร์	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB
	5. Check temperature of motor (Hot ,Normal) ตรวจเช็คอุณหภูมิของมอเตอร์	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB
	6. Cleaning air filter ทำความสะอาดแผ่นกรองอากาศ	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No
	7. Check lubrication of motor ตรวจสอบการหล่อลื่นของมอเตอร์(เสียงผิดปกติ)	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No
	8. Check body of unit and Check nut and bolt ตรวจสอบตัวถังของเครื่องและตรวจสอบน็อตและสกรู	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB
	9. Cleaning water tray and drainage pipe ทำความสะอาดถาดรองน้ำและท่อระบายน้ำ	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No
	10. Check fan speed ( Hi/Lo/Med ) เช็คสปีดของมอเตอร์ (Hi-Med-Low)	Hi N / AB Low N / AB Med N / AB	Hi N / AB Low N / AB Med N / AB	Hi N / AB Low N / AB Med N / AB	Hi N / AB Low N / AB Med N / AB	Hi N / AB Low N / AB Med N / AB	Hi N / AB Low N / AB Med N / AB	Hi N / AB Low N / AB Med N / AB	Hi N / AB Low N / AB Med N / AB
	11. Measurement of motor voltage (Voltage) วัดค่าแรงดันของมอเตอร์ (L-N)	L 220 V	L 220 V	L 220 V	L 220 V	L 220 V	L 220 V	L 220 V	L 220 V
	12. Insulation pipe ฉนวนหุ้มท่อ	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB
	13. Check cable to junction box of motor ตรวจเช็คจุดต่อสายไฟฟ้าของมอเตอร์	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB
	14. Cleaning coil of unit ล้างคอยล์ของตัวแอร์	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No
Remark : หมายเหตุ									

D: Daily ประจำวัน/ W:Weekly สัปดาห์/ M:Monthly เดือน/ Q:Quarterly 3 เดือน





HOTEL Floor LL, BAKERY

AIR CONDITION SYSTEM FAN COIL UNIT

	EQUIPMENTS NAME	C-(R)-F-F/LG-10	C-(R)-F-F/LG-11	C-(R)-F-F/LG-12	C-(R)-F-F/LG-19	C-(R)-F-F/LG-08	C-(R)-F-F/LG-28	C-(R)-F-F/LG-29
Monthly	TASK	Bakery	Chocolat room	Pastry	Bakery	Pot/pan wash	Corridor Wide	Corridor Wide
M	1. Cleanning straner ล้างสแตนเนอร์	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>
	2. Test operation of thermostat ทดสอบการทำงานของเทอร์โมสตาท	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>
	3. Test operation of motorized valve ทดสอบการทำงานของมอเตอร์ไคร์ฟวาล์ว	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>
	4. Check noise and vibration of motor ตรวจสอบเสียงและการสั่นสะเทือนของมอเตอร์	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>
	5. Check temperature of motor (Hot ,Normal) ตรวจเช็คอุณหภูมิของมอเตอร์	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>
	6. Cleaning air filter ทำความสะอาดแผ่นกรองอากาศ	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>
	7. Check lubrication of motor ตรวจสอบการหล่อลื่นของมอเตอร์(เสียงผิดปกติ)	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>
	8. Check body of unit and Check nut and bolt ตรวจสอบตัวถังของเครื่องและตรวจสอบน็อตและสกรู	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>
	9. Cleaning water tray and drainage pipe ทำความสะอาดถาดรองน้ำและท่อระบายน้ำ	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>
	10. Chec fan speed ( Hi/Low/Med ) เช็คสปีดของมอเตอร์ (Hi-Med-Low)	Hi N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Hi N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Hi N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Hi N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Hi N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Hi N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Hi N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>
		Low N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Low N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Low N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Low N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Low N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Low N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Low N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>
		Med N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Med N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Med N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Med N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Med N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Med N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	Med N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>
	12. In sulation pipe ฉนวนหุ้มท่อ	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>
	13. Check cable to junction box of motor ตรวจเช็คตู้ต่อสายไฟฟ้าของมอเตอร์	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input checked="" type="checkbox"/>
	14. Cleaning coil of unit ล้างคอยล์ของตัวแอร์	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/>
Remark : หมายเหตุ								
D: Daily ประจำวัน/ W:Weekly สัปดาห์/ M:Monthly เดือน/ Q:Quarterly 3 เดือน								



LL MAIN KITCHEN

CAPELLA  
Capella Bangkok

MONTH \_\_\_\_\_

# PREVENTIVE MAINTENANCE YEAR 2024

HOTEL Floor: LL, MAIN KITCHEN, CORRIDOR, ROOMSERVICE

NORMAL = N  
AB NORMAL = AB

AIR CONDITION SYSTEM FAN COIL UNIT

23.29

MONTH	EQUIPMENTS NAME	HOTEL Floor: LL, MAIN KITCHEN, CORRIDOR, ROOMSERVICE							AIR CONDITION SYSTEM FAN COIL UNIT		
		C-(R)-F-F/LG-13 Chef office	C-(R)-F-F/LG-14 Executive Chef	C-(R)-F-F/LG-15 Room service 1	C-(R)-F-F/LG-16 Room service 2	C-(R)-F-F/LG-35 Corridor wide/chef	C-(R)-F-F/LG-36 Corridor wide/chef	C-(R)-F-F/LG-01 Dishwashing main kitchen			
M	1. Cleaning strainer ล้างสแตนเบอร์	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No			
	2. Test operation of thermostat ทดสอบการทำงานของเทอร์โมสตาท	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB			
	3. Test operation of motorized valve ทดสอบการทำงานของมอเตอร์ไควล์ว	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB			
	4. Check noise and vibration of motor ตรวจสอบเสียงและการสั่นสะเทือนของมอเตอร์	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB			
	5. Check temperature of motor (Hot, Normal) ตรวจเช็คอุณหภูมิของมอเตอร์	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB			
	6. Cleaning air filter ทำความสะอาดแผ่นกรองอากาศ	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No			
	7. Check lubrication of motor ตรวจสอบการหล่อลื่นของมอเตอร์ (เสียงผิดปกติ)	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB			
	8. Check body of unit and Check nut and bolt ตรวจสอบตัวถังของเครื่องและตรวจสอบน็อตและสกรู	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB			
	9. Cleaning water tray and drainage pipe ทำความสะอาดถาดรองน้ำและท่อระบายน้ำ	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No			
	10. Check fan speed (Hi/Lo/Med) เช็คสปีดของมอเตอร์ (Hi-Med-Low)	Low N / AB Med N / AB Hi N / AB	Low N / AB Med N / AB Hi N / AB	Low N / AB Med N / AB Hi N / AB	Low N / AB Med N / AB Hi N / AB	Low N / AB Med N / AB Hi N / AB	Low N / AB Med N / AB Hi N / AB	Low N / AB Med N / AB Hi N / AB			
	11. Measurement of motor voltage (Voltage) วัดค่าแรงดันของมอเตอร์ (L-N)	220 v	220 v	220 v	220 v	220 v	220 v	220 v			
	12. In sulation pipe ฉนวนหุ้มท่อ	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB			
	13. Check cable to junction box of motor ตรวจเช็คจุดต่อสายไฟฟ้าของมอเตอร์	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB	N / AB			
	14. Cleaning coil of unit ล้างคอยล์ของตัวแอร์	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No			

Remark :  
หมายเหตุ



# PREVENTIVE MAINTENANCE YEAR 2024

30,37

HOTEL Floor LL, MAINKITCHEN

AIR CONDITION SYSTEM FAN COIL UNIT

	EQUIPMENTS NAME	C-(R)-F-F/LG-02	C-(R)-F-F/LG-03	C-(R)-F-F/LG-04	C-(R)-F-F/LG-05	C-(R)-F-F/LG-06	C-(R)-F-F/LG-07	C-(R)-F-F/LG-33	C-(R)-F-F/LG-34
Monthly	TASK	STTEWORD STORE	Service station	Cooking area	Cooking area	Service station	Coold kitchen	Corridor Wide	Corridor Wide
M	1. Cleaning straner ล้างสแตนเนอร์	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	2. Test operation of thermostat ทดสอบการทำงานของเทอร์โมสตัท	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	3. Test operation of motorized valve ทดสอบการทำงานของมอเตอร์ไควล์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	4. Check noise and vibration of motor ตรวจสอบเสียงและการสั่นสะเทือนของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	5. Check temperature of motor (Hot ,Normal) ตรวจเช็คอุณหภูมิของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	6. Cleaning air filter ทำความสะอาดแผ่นกรองอากาศ	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	7. Check lubrication of motor ตรวจสอบการหล่อลื่นของมอเตอร์(เสียงผิดปกติ)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	8. Check body of unit and Check nut and bolt ตรวจสอบตัวถังของเครื่องและตรวจสอบน็อตและสกรู	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	9. Cleaning water tray and drainage pipe ทำความสะอาดถาดรองน้ำและท่อระบายน้ำ	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	10. Chec fan speed ( Hi/Low/Med ) เช็คสปีดของมอเตอร์ (Hi-Med-Low)	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>
	11. Measurement of motor voltage (Voltage) วัดค่าแรงดันของมอเตอร์ (L-N)	L <input checked="" type="checkbox"/> v	L <input checked="" type="checkbox"/> v	L <input checked="" type="checkbox"/> v	L <input checked="" type="checkbox"/> v	L <input checked="" type="checkbox"/> v	L <input checked="" type="checkbox"/> v	L <input checked="" type="checkbox"/> v	L <input checked="" type="checkbox"/> v
	12. In sulation pipe ฉนวนหุ้มท่อ	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	13. Check cable to junction box of motor ตรวจเช็คจุดต่อสายไฟฟ้าของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	14. Cleaning coil of unit ล้างคอยล์ของตัวแอร์	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Remark :									

หมายเหตุ

D: Daily ประจำวัน/ W:Weekly สัปดาห์/ M:Monthly เดือน/ Q:Quarterly 3 เดือน



HOTEL Floor: LG BQ KITCHEN

	EQUIPMENT NAME	C(R)-F-F/LG-01	C(R)-F-F/LG-02	C(R)-F-F/LG-03	C(R)-F-F/LG-04	C(R)-F-F/LG-05
Monthly	TASK	Cooking area	Cooking area	Pot/pan wash	CR-14 Area	Cooking area
	1. Cleaning strainer ล้างสแตนเนอร์	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	2. Test operation of thermostat ทดสอบการทำงานของเทอร์โมสตัท	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	3. Test operation of motorized valve ทดสอบการทำงานของมอเตอร์ไดรฟ์วาล์ว	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	4. Check noise and vibration of motor ตรวจสอบเสียงและการสั่นสะเทือนของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	5. Check temperature of motor (Hot ,Normal) ตรวจเช็คอุณหภูมิของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	6. Cleaning air filter ทำความสะอาดแผ่นกรองอากาศ	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	7. Check lubrication of motor ตรวจสอบการหล่อลื่นของมอเตอร์(เสียงผิดปกติ)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
M	8. Check body of unit and Check nut and bolt ตรวจสอบตัวถังของเครื่องและตรวจสอบน็อตและสกรู	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	9. Cleaning water tray and drainage pipe ทำความสะอาดถาดรองน้ำและท่อนำระบายน้ำ	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	10. Check fan speed ( Hi/Low/Med ) เช็คสปีดของมอเตอร์ (Hi-Med-Low)	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>
	11. Measurement of motor voltage (Voltage) วัดค่าแรงดันของมอเตอร์ (L-N)	L <input checked="" type="checkbox"/> V <input type="checkbox"/>	L <input checked="" type="checkbox"/> V <input type="checkbox"/>	L <input checked="" type="checkbox"/> V <input type="checkbox"/>	L <input checked="" type="checkbox"/> V <input type="checkbox"/>	L <input checked="" type="checkbox"/> V <input type="checkbox"/>
	12. Insulation pipe ฉนวนหุ้มท่อ	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	13. Check cable to junction box of motor ตรวจเช็คจุดต่อสายไฟฟ้าของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	14. Cleaning coil of unit ล้างคอยล์ของตัวแอร์	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Remark : หมายเหตุ						
D: Daily ประจำวัน/ W:Weekly สัปดาห์/ M:Monthly เดือน/ Q:Quarterly 3 เดือน						

MONTH \_\_\_\_\_

AIR CONDITION SYSTEM FAN COIL UNIT

NORMAL = N  
AB NORMAL = AB

PREVENTIVE MAINTENANCE YEAR 2024

NORMAL = N  
AB NORMAL = AB  
43,48

Monthly	EQUIPMENT NAME TASK	C(R)-F-F/LG-06 Coolid kitchen BQ area	C(R)-F-F/LG-07 Steward store	C(R)-F-F/LG-08 Dish wash	C(R)-F-F/LG-09 Service station	C(R)-F-F/LG-10 Service station	C(R)-F-F/LG-11 Room AV
	1. Cleaning strainer ล้างสแตนเนอร์	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	2. Test operation of thermostat ทดสอบการทำงานของเทอร์โมสตัท	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	3. Test operation of motorized valve ทดสอบการทำงานของมอเตอร์ไคร์ฟวาล์ว	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	4. Check noise and vibration of motor ตรวจสอบเสียงและการสั่นสะเทือนของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	5. Check temperature of motor (Hot ,Normal) ตรวจเช็คอุณหภูมิของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	6. Cleaning air filter ทำความสะอาดแผ่นกรองอากาศ	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	7. Check lubrication of motor ตรวจสอบการหล่อลื่นของมอเตอร์(เสียงผิดปกติ)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
M	8. Check body of unit and Check nut and bolt ตรวจสอบตัวถังของเครื่องและตรวจสอบน็อตและสกรู	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	9. Cleaning water tray and drainage pipe ทำความสะอาดถาดรองน้ำและท่อระบายน้ำ	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	10. Check fan speed ( Hi/Low/Med ) เช็คสปีดของมอเตอร์ (Hi-Med-Low)	Low N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Med N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Hi N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	Low N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Med N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Hi N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	Low N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Med N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Hi N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	Low N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Med N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Hi N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	Low N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Med N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Hi N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	Low N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Med N <input checked="" type="checkbox"/> AB <input type="checkbox"/> Hi N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	11. Measurement of motor voltage (Voltage) วัดค่าแรงดันของมอเตอร์ (L-N)	L 220 V	L 220 V	L 220 V	L 220 V	L 220 V	L 220 V
	12. Insulation pipe ฉนวนหุ้มท่อ	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	13. Check cable to junction box of motor ตรวจเช็คจุดต่อสายไฟฟ้าของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	14. Cleaning coil of unit ล้างคอยล์ของตัวแอร์	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

Remark :

หมายเหตุ

D: Daily ประจำวัน/ W: Weekly สัปดาห์/ M: Monthly เดือน/ Q: Quarterly 3 เดือน



HOTEL FLOOR LL,2 COTE KITCHEN

	EQUIPMENTS NAME	C-F-F/LG-01	C-F-F/LG-02	C-F-F/LG-03	C-F-F/LG-04
Monthly	TASK	cote service station	cote cooking area	Coold kitchen cote	store cote
M	1. Cleanning straner ล้างสแตนเนอร์	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	2. Test operation of thermostat ทดสอบการทำงานของเทอร์โมสตัท	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	3. Test operation of motorized valve ทดสอบการทำงานของมอเตอร์ไทร์ฟาล์ว	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	4. Check noise and vibration of motor ตรวจสอบเสียงและการสั่นสะเทือนของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	5. Check temperature of motor (Hot ,Normal) ตรวจเช็คอุณหภูมิของมอเตอร์	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	6. Cleaning air filter ทำความสะอาดแผ่นกรองอากาศ	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	7. Check lubrication of motor ตรวจสอบการหล่อลื่นของมอเตอร์(เลียงฟิคปกติ)	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	8. Check body of unit and Check nut and bolt ตรวจสอบตัวถังของเครื่องและตรวจสอบน็อตและสกรู	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	9. Cleaning water tray and drainage pipe ทำความสะอาดถาดรองน้ำและท่อระบายน้ำ	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	10. Chec fan speed ( Hi/Low/Med ) เช็คสปีดของมอเตอร์ (Hi-Med-Low)	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>
	11. Measurement of motor voltage (Voltage) วัดค่าแรงดันของมอเตอร์ (L-N)	L <input type="checkbox"/>	L <input type="checkbox"/>	L <input type="checkbox"/>	L <input type="checkbox"/>
	12. In sulation pipe ฉนวนหุ้มท่อ	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	13. Check cable to junction box of motor ตรวจเช็คจุดต่อสายไฟฟ้าของมอเตอร์	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	14. Cleaning coil of unit ล้างคอยล์ของตัวแอร์				
Remark : หมายเหตุ					
D: Daily ประจำวัน/ W:Weekly สัปดาห์/ M:Monthly เดือน/ Q:Quarterly 3 เดือน					



NORMAL = N

AB NORMAL= AB

HOTEL Floor:LL FCU STAFF CANTEEN UNIT

AIR CONDITION SYSTEM FAN COIL UNIT

	EQUIPMENTS NAME	C-F-F/LG-14	C-F-F/LG-15	C-F-F/LG-16	C-F-F/LG-17	C-F-F/LG-18
	TASK	Staff canteen1	Staff canteen2	Staff kitchen	Dishwashing 1	Dishwashing 2
Monthly	1. Cleaning strainer ล้างสแตนเนอร์	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
M	2. Test operation of thermostat ทดสอบการทำงานของเทอร์โมสตาท	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	3. Test operation of motorized valve ทดสอบการทำงานของมอเตอร์ไคร์ฟาล์ว	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	4. Check noise and vibration of motor ตรวจสอบเสียงและการสั่นสะเทือนของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	5. Check temperature of motor (Hot ,Normal) ตรวจเช็คอุณหภูมิของมอเตอร์	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	6. Cleaning air filter ทำความสะอาดแผ่นกรองอากาศ	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	7. Check lubrication of motor ตรวจสอบการหล่อลื่นของมอเตอร์(เสียงผิดปกติ)	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	8. Check body of unit and Check nut and bolt ตรวจสอบตัวถังของเครื่องและตรวจสอบน็อตและสกรู	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	9. Cleaning water tray and drainage pipe ทำความสะอาดถาดรองน้ำและท่อระบายน้ำ	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	10. Check fan speed ( Hi/Low/Med ) เช็คสปีดของมอเตอร์ (Hi-Med-Low)	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>	Hi <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Low <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/> Med <input checked="" type="checkbox"/> N <input type="checkbox"/> AB <input type="checkbox"/>
	12. Insulation pipe ฉนวนหุ้มท่อ	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>	N <input checked="" type="checkbox"/> AB <input type="checkbox"/>
	13. Check cable to junction box of motor ตรวจเช็คจุดต่อสายไฟฟ้าของมอเตอร์	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	14. Cleaning coil of unit ล้างคอยล์ของตัวแอร์	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Remark :	หมายเหตุ					
<p>D: Daily ประจำวัน/ W:Weekly สัปดาห์/ M:Monthly เดือน/ Q:Quarterly 3 เดือน</p>						

#### 7.10 ตัวอย่างคู่มือการอนุรักษ์พลังงานให้กับผู้พักอาศัย





# Energy Efficiency Manual

คู่มืออนุรักษ์พลังงาน

## คำนำ



โลกกำลังเผชิญสภาวะวิกฤตพลังงานและสภาวะโลกร้อน การใช้พลังงานอย่างฟุ่มเฟือยและไม่ถูกวิธี

ก็เป็นสาเหตุหนึ่งที่จะทำให้เกิดสภาพการณ์นี้

ในปี 2551 มีการประเมินว่าปริมาณการใช้ไฟฟ้าจะสูงกว่าปีที่ผ่านมา โดยคาดว่าจะมีระดับสูงถึง 23,957 เมกะวัตต์

พวกเราต้องแบกภาระค่าใช้จ่ายด้านพลังงานเพิ่มขึ้น


ในขณะที่ประเทศไทยสูญเสียเงินตราในการนำเข้าพลังงาน โดยเฉพาะน้ำมันจากต่างประเทศ ซึ่งคาดว่าจะต้องนำเข้า  
น้ำมันกว่า 700,000 ล้านบาท

นับวันวิกฤตการณ์นี้ทวีความรุนแรงหากแต่ละคนแต่ละครอบครัวลงมือประหยัดพลังงานตามคำแนะนำ  
ในคู่มือเล่มนี้ก็จะช่วยลดค่าใช้จ่ายของตนเองและช่วยเศรษฐกิจของประเทศ...





# สารบัญ



หลอดไฟ



เครื่องปรับอากาศ



วิธีประหยัดน้ำ



วิธีประหยัดน้ำมัน



#### 7.11 ตัวอย่างเอกสารการตรวจสอบอุปกรณ์ดับเพลิง และทางหนีไฟ



# FIRE EXTINGUISHER(TYPE K)/FIRE BLANKET

DATE 22/01/2024

LOCATON	WET CHEMICAL		FIRE BLANKET		REMARK
	AVAILABLE	STATUS	AVAILABLE	STATUS	
Ballroom Kitchen	3	/	2	/	
Conservatory Kitchen	3	/	2	/	
B/P Kitchen	3	/	1	/	
RIVA Kitchen	3	/	2	/	
BKK Kitchen	2	/	2	/	
YTY Kitchen	2	/	1	/	
MAIN Kitchen	0	0	0	0	Set Co2 สำรองแทนถัง k Recharge
BAKERRY Kitchen	1	/	0	0	
GRILL ROOM Kitchen	1	/	0	0	
IRD Kitchen	1	/	1	/	
SOI 64 Kitchen	1	/	2	/	
Riverfront Kitchen	3	/	2	/	
The lounge	0	0	1	/	
Fire card No . 1	0	0	1	/	
Fire card No . 2 set up H/S 9,10 B1	0	0	1	/	Fire Blanket For car
SKY LOUNGE FSR	0	0	1	/	
Cabinet of ammunition No.1 (H/S 1/2)	0	0	0	0	
Cabinet of ammunition No.2(H/S 7/8)	0	0	0	0	
Cabinet of ammunition No.3(H/S 9/10)	0	0	0	0	
Cabinet of ammunition No.4 Residence	0	0	0	0	
STOREROOM B2	0	0	3	0	
TOTAL	3		22		

Note ส่งถัง Type K ไปเติม 2 ถัง วันที่ 20/02/24

CHECKED BY Am  
DIRECTOR SECURITY

22/01/2024

# FIRE EXTINGUISHER HOTEL CHECKLIST (2. Palm Court Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
<b>ROOFTOP</b>						
FHC on Rooftop stair 4	1	0	1	0	0	
FHC on Rooftop St 06	1	0	1	0	0	
<b>FLOOR 3</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 2</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 1</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
FHC No.7 Luggage store	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 1L</b>						
FHC No.1 Motorcycler Parking	1	1	1	1	0	
FHC No.2 Florist Room(Sai 2)	1	1	1	1	0	
FHC No.3 Room 308	1	1	1	1	0	
FHC No.4 next to fire exit stair 1	1	1	1	1	0	
FHC No.5 next to fire exit stair	1	1	1	1	0	
FHC No.6 Salon Area	1	1	1	1	0	
FHC No.7 Reception Area	1	1	1	1	0	
FHC No.8 Male Locker Area	1	1	1	1	0	
FHC No.9 next to fire exit stair 3	1	1	1	1	0	
FHC No.10 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.11 Generator Room	1	1	1	1	0	
FHC No.12 Near Restroom Sai 64	1	1	1	1	0	
FHC No.13 Luggage store	1	1	1	1	0	
FHC No.14 next to fire exit stair 5	1	1	1	1	0	
FHC No.15 next to fire exit stair 7	1	1	1	1	0	
EE Room next to stair 1	1	1	1	1	0	
EE Room next to stair 3	1	1	1	1	0	
Novac NO.1 IT Room	0	0	0	0	0	
Novac NO.2 EE Room	0	0	0	0	0	
Novac No.3 Main Power Room	0	0	0	0	2	
Security Office	0	0	0	0	4	
Laundry Area	0	0	0	1	0	
Housekeeping Office	0	0	0	1	0	
<b>Floor B1</b>						
FHC No.B1A	1	1	1	1	0	
FHC No.2 next to fire exit stair 6	1	1	1	1	0	
FHC No.3 Store(Pumproom)(st11) B1E	1	1	1	1	0	
FHC No.4 next to fire exit stair 1	1	1	1	1	0	
FHC No.5 Pillar A4 B1E	1	1	1	1	0	
FHC No.6 next to fire exit stair 3	1	1	1	1	0	
FHC No.7 next to fire exit stair 4	1	1	1	1	0	
FHC No.8 B1D near B1B	1	1	1	1	0	
FHC No.9 Motorcycler Parking	1	1	1	1	0	
FHC No.10 CP 1/2	1	1	1	1	0	
FHC No.11 B1A	1	1	1	1	0	
FHC No.12 B1A	1	1	1	1	0	
ENG Work shop	0	0	0	6	2	
<b>Floor B2</b>						
FHC No.B2B(Pillar S13)	1	1	1	1	0	
FHC No.2 next to fire exit stair 6	1	1	1	1	0	
FHC No.3 next to fire exit stair 1	1	1	1	1	0	
FHC No.4 B2 Pillar B4	1	1	1	1	0	
FHC No.5 Pillar A4 B1E Pillar U1	1	1	1	1	0	
FHC No.6 B2B next to fire exit stair 17	1	1	1	1	0	
FHC No.7 B2B Pillar U1	1	1	1	1	0	
FHC No.8 B2B Chiller Room	1	1	1	1	0	
FHC No.9 next to fire exit stair 4	1	1	1	1	0	
FHC No.10 CP 1/2	1	1	1	1	0	
FHC No.11 B2B Pillar T9	1	1	1	1	0	
Store Security	0	0	0	6	1	
<b>Out side</b>						
Gas Station	0	0	0	6	0	
Main Entrance	0	0	0	2	0	
<b>TOTAL</b>	<b>61</b>	<b>61</b>	<b>61</b>	<b>86</b>	<b>15</b>	

Main Entrance ติดตั้ง CO2 ของส่วนกลาง 3 ถัง

Date 13/02/2024  
CHECKED BY Annan  
DIRECTOR SECURITY

24

# FIRE EXTINGUISHER HOTEL CHECKLIST (1. Ballroom Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
ROOFTOP						
FHC on Rooftop stair 7	1	1	1	1	0	
FLOOR 3						
FHC No.1 In front of Lift H.S 9/10	1	1	1	1	0	
FHC No.2 Near Rest room Guest	1	1	1	1	0	
FHC No.3 next to fire exit stair 8	1	1	1	1	0	
FHC No.4 In front of BQ Store	1	1	1	1	0	
Floor 2						
FHC No.1 In front of Lift H.S 9/10	1	1	1	1	0	
FHC No.2 AHU Room	1	1	1	1	0	
FHC No.3 next to fire exit stair 8	1	1	1	1	0	
FHC No.4 In front of Excome Office	1	1	1	1	0	
Floor L						
FHC No.1 In front of Lift H.S 9/10	1	1	1	1	0	
FHC No.2 Bar Ballroom Area	1	1	1	1	0	
FHC No.3 Bar Ballroom Area	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	1	
FHC No.5 In front of Terrest Ballroom	1	1	1	1	1	
FHC No.6 In front of Door 2	1	1	1	1	0	
FHC No.7 F/O Counter	1	1	1	1	0	
Floor LL						
FHC No.1 In front of Lift H.S 9/10	1	1	1	1	0	
FHC No.2 Carpark (Near CP 4)	1	1	1	1	0	
FHC No.3 ชั่งหาตู้ไม่เจอ	1	1	1	1	0	
FHC No.4 ชั่งหาตู้ไม่เจอ	1	1	1	1	0	
FHC No.5 Door 9 St 19	1	1	1	1	0	
FHC No.6 Art Space (CP 4)	1	1	1	1	0	
FHC No.7 Art Space (Door 6)	1	1	1	1	0	
FHC No.8 Art Space (In side St 18)	1	1	1	1	0	
Floor B1						
FHC No.1 In front H/S 9/10	1	1	1	1	0	
FHC No.2 EV CHARGER	1	1	1	1	1	
FHC No.3 next to fire exit stair 18	1	1	1	1	0	
FHC No.4 next to fire exit stair 19	1	1	1	1	0	
TOTAL	28	28	28	28	3	

## Note

FL LL มีตู้ FHC 1 ตู้ SAITO ยังไม่มีหมายเลขตู้ (No.3/4) ไม่มี ข้อต่อ มีถัง Dry 1 ถัง

Date 13/02/2024  
CHECKED BY Amnar  
DIRECTOR SECURITY

01/12024



FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 15				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 14				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 12 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 12				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.3	1	1		
FLOOR 11				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	0	FHC IN GUEST ROOM	
FLOOR 10				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 9				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0		
FLOOR 8				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 7				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 6				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 5				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 4				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 3				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 Facility Office	1	0		
FLOOR 2				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 1				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 OFFICE AREA	1	1		
FLOOR 1L				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 Pet Grooming	1	0		
FHC No.5 ยิงหาตู้ไมโคร	1	0		
FHC No.6 ENG Office	1	0		
FHC No.7 Loading area	1	0		
FLOOR B1				

FHC No.1 RST.2	1	0		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	0		
FHC No.4 Door2	1	0		
FHC No.5 B1C Pillar A13	1	0		
FHC No.6 B1C Pillar F14	1	0		
FHC No.7 B1C Pillar M14	1	0		
FHC No.8 Fanroom	1	0		
Total	214	130		

FHC IN ROOM GUEST	
Room Number	Floor
8	69
11	66-67
26	62-63
27	60-61
28	60-61
324	10-11

ALL FIRE EXTINGUISHER		
LOCATION	DRY CHEMICAL	CO2
HOTEL	219	38
RESSIDENCE	214	130
TOTAL	433	168

total 5 Room
--------------

Date 23/02/2024

Checked by Amna  
DIRECTOR SECURITY

20/11/2024

FHC No.3 RST.1	1	1		
FLOOR 34				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 32 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 32				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 31				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 30				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 29				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 28				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 27				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 26				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 25				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 24				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 22 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 22				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 21				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 20				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 19				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 18				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 17				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 16				



FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 52				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 51				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 50				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 49				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 48				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 47				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 46				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 45				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 43 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 43				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 42				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 41				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
Fire Pump Room	1	0		
FLOOR 40				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 39				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 38				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 37				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 36				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 35				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		

# FIRE EXTINGUISHER HOTEL CHECKLIST (3.Cascade Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
Rooflop						
FHC on Rooflop	1	0	1	0	0	
Floor 13						
FHC No.1 next to fire exit stair 11	1	1	1	1	0	
FHC No.2 EE Room	1	1	1	1	1	
FHC No.3 next to fire exit stair 12	1	1	1	1	0	
Floor 12						
FHC No.1 Near Fire Exit Stair 11	1	1	1	1	0	
FHC No.2 IN front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Next to Fire Exit Stair 12	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Floor 11						
FHC No.1 Near Fire Exit Stair 11	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.4 next to Fire Exit stair 13	1	1	1	1	0	
FHC No.5 In front of AHU Room	1	1	1	1	0	
FHC No.6 next to Fire Exit stair 15	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Floor 10						
FHC No.1 next to Fire exit stair 11	1	1	1	1	0	
FHC No.2 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire exit stair 12	1	1	1	1	0	
FHC No.4 next to fire exit stair 13	1	1	1	1	0	
FHC No.5 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.6 near fire exit stair 15	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
AHU Room	0	0	0	0	1	
Floor 9						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 8						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 7						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 6						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 5						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	



FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 4						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 3						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 2						
FHC No.1 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.2 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 13	1	1	1	1	0	
FHC No.4 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.5 next to Fire Exit stair 15	1	1	1	1	0	
FHC No.6 next to Fire Exit stair 15	1	1	1	1	0	
In front of Room 202	1	1	1	1	0	
Floor L						
FHC No.1 front of YTY Resterance	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.4 next to Fire exit stair 13	1	1	1	1	0	
FHC No.5 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.6 In front of Lift HP.9	1	1	1	1	0	
FHC No.7 In front of stair 20	1	1	1	1	0	
Floor LL						
FHC No.1 Carpark LL[W1]	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Office Executive/Sale	1	1	1	1	0	
FHC No.4 Office Reservation	1	1	1	1	0	
FHC No.5 Carpark LL[U1]	1	1	1	1	0	
FHC No.6 next to Fire exit stair 13	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 Door Gate 3	1	1	1	1	0	
FHC No.9 In front of stair 20	1	1	1	1	0	
FHC No.10 ยืนทางบันได	0	0	0	0	0	
Floor B1						
FHC No.1 Carpark B1C[M4]	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Carpark B1C[M4]	1	1	1	1	0	
FHC No.4 In front of Lift HS 5,6	1	1	1	1	0	
TOTAL	99	98	100	100	19	

Date 13/02/2024

CHECKED BY Amn  
DIRECTOR SECURITY

2/01/2024



## SAMMARY

Location	Fire Cabinet	Fire Hose Reel	Brass Valve
Ballroom Building	28	28	28
Palm court Building	64	64	64
Cascade Building	99	98	100
Keep in Store	0	0	0
Waiting for refill/Broken	0	0	0
Total	191	190	192

Discard DRY=4 Pcs[27/07/2023] Discard DRY=1Pcs[26/09/23] Disc

Date 23/02/2024

CHECKED BY Amnart

DIRECTOR SECURITY

ang

22/10/2024

Dry Chemical	CO2	Remark
27	2	
92	14	
100	19	
0	0	
0	0	
<b>219</b>	<b>36</b>	

ard DRY=4[23/02/24] Total =9

**FIRE EXTINGUISHER(TYPE K)/FIRE BLANKET**

DATE 23/02/2024

LOCATON	WET CHEMICAL		FIRE BLANKET		REMARK
	AVAILABLE	STATUS	AVAILABLE	STATUS	
Ballroom Kitchen	3	/	2	/	
Conservatory Kitchen	3	/	2	/	
B/P Kitchen	3	/	1	/	
RIVA Kitchen	3	/	2	/	
BKK Kitchen	2	/	2	/	
YTY Kitchen	2	/	1	/	
MAIN Kitchen	0	0	0	0	Set Co2 สำรองแทนถัง k Recharge
BAKERRY Kitchen	1	/	0	0	
GRILL ROOM Kitchen	1	/	0	0	
IRD Kitchen	1	/	1	/	
SOI 64 Kitchen	1	/	2	/	
Riverfront Kitchen	3	/	2	/	
The lounge	0	0	1	/	
Fire card No . 1	0	0	1	/	
Fire card No . 2 set up H/S 9,10 B1	0	0	1	/	Fire Blanket For car
SKY LOUNGE FSR	0	0	1	/	
Cabinet of ammunition No.1 (H/S 1/2)	0	0	0	0	
Cabinet of ammunition No.2(H/S 7/8)	0	0	0	0	
Cabinet of ammunition No.3(H/S 9/10)	0	0	0	0	
Cabinet of ammunition No.4 Residence	0	0	0	0	
STOREROOM B2	0	0	3	0	
TOTAL	3		22		

Note ส่งถัง Type K ไปเติม 2 ถัง วันที่ 20/02/24

CHECKED BY Ar [redacted] /S. [redacted] /Boontiang  
DIRECTOR SEC [redacted] 23/02/2024



# FIRE EXTINGUISHER HOTEL CHECKLIST (3.Cascade Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
<b>Rooftop</b>						
FHC on Rooftop	1	0	1	0	0	
<b>Floor 13</b>						
FHC No.1 next to fire exit stair 11	1	1	1	1	0	
FHC No.2 EE Room	1	1	1	1	1	
FHC No.3 next to fire exit stair 12	1	1	1	1	0	
<b>Floor 12</b>						
FHC No.1 Near Fire Exit Stair 11	1	1	1	1	0	
FHC No.2 in front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Next to Fire Exit Stair 12	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
<b>Floor 11</b>						
FHC No.1 Near Fire Exit Stair 11	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.4 next to Fire Exit stair 13	1	1	1	1	0	
FHC No.5 In front of AHU Room	1	1	1	1	0	
FHC No.6 next to Fire Exit stair 15	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
<b>Floor 10</b>						
FHC No.1 next to Fire exit stair 11	1	1	1	1	0	
FHC No.2 in front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire exit stair 12	1	1	1	1	0	
FHC No.4 next to fire exit stair 13	1	1	1	1	0	
FHC No.5 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.6 near fire exit stair 15	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
AHU Room	0	0	0	0	1	
<b>Floor 9</b>						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 in front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
<b>Floor 8</b>						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 in front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
<b>Floor 7</b>						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 in front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
<b>Floor 6</b>						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 in front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
<b>Floor 5</b>						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 in front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	

FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 4						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 3						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 2						
FHC No.1 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.2 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 13	1	1	1	1	0	
FHC No.4 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.5 next to Fire Exit stair 15	1	1	1	1	0	
FHC No.6 next to Fire Exit stair 15	1	1	1	1	0	
In Front of Room 202	1	1	1	1	0	
Floor L						
FHC No.1 front of YTY Resterance	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.4 next to Fire exit stair 13	1	1	1	1	0	
FHC No.5 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.6 In Front of Lift HP-9	1	1	1	1	0	
FHC No.7 In front of stair 20	1	1	1	1	0	
Floor LL						
FHC No.1 Carpark LL[W1]	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Office Executive/Sale	1	1	1	1	0	
FHC No.4 Office Reservation	1	1	1	1	0	
FHC No.5 Carpark LL[U1]	1	1	1	1	0	
FHC No.6 next to Fire exit stair 13	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 Door Gate 3	1	1	1	1	0	
FHC No.9 In front of stair 20	1	1	1	1	0	
FHC No.10 ห้องประชุม	0	0	0	0	0	
Floor B1						
FHC No.1 Carpark B1C[M4]	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Carpark B1C[L4]	1	1	1	1	0	
FHC No.4 In front of Lift HS 5,6	1	1	1	1	0	
TOTAL	99	98	100	100	19	

Date 13/02/2024

CHECKED BY Amnar  
DIRECTOR SECURITY

ang

23/02/2024

# FIRE EXTINGUISHER HOTEL CHECKLIST (2. Palm Court Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
<b>ROOFTOP</b>						
FHC on Rooftop stair 4	1	0	1	0	0	
FHC on Rooftop St 06	1	0	1	0	0	
<b>FLOOR 3</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 2</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 1</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
FHC No.7 Luggage store	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor LL</b>						
FHC No.1 Motorcycler Parking	1	1	1	1	0	
FHC No.2 Florist Room(Sai 2)	1	1	1	1	0	
FHC No.3 Room 308	1	1	1	1	0	
FHC No.4 next to fire exit stair 1	1	1	1	1	0	
FHC No.5 next to fire exit stair	1	1	1	1	0	
FHC No.6 Salon Area	1	1	1	1	0	
FHC No.7 Reception Area	1	1	1	1	0	
FHC No.8 Male Locker Area	1	1	1	1	0	
FHC No.9 next to fire exit stair 3	1	1	1	1	0	
FHC No.10 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.11 Generator Room	1	1	1	1	0	
FHC No.12 Near Restroom Sai 64	1	1	1	1	0	
FHC No.13 Luggage store	1	1	1	1	0	
FHC No.14 next to fire exit stair 5	1	1	1	1	0	
FHC No.15 next to fire exit stair 17	1	1	1	1	0	
EE Room next to stair 1	1	1	1	1	0	
EE Room next to stair 3	1	1	1	1	0	
Novac No.1 IT Room	0	0	0	0	0	
Novac No.2 EE Room	0	0	0	0	0	
Novac No.3 Main Power Room	0	0	0	0	0	
Security Office	0	0	0	1	2	
Laundry Area	0	0	0	0	4	
Housekeeping Office	0	0	0	1	0	
<b>Floor B1</b>						
FHC No.B1A	1	1	1	1	0	
FHC No.2 next to fire exit stair 6	1	1	1	1	0	
FHC No.3 Store(Pumproom)(st1) B1E	1	1	1	1	0	
FHC No.4 next to fire exit stair 1	1	1	1	1	0	
FHC No.5 Pillar A4 B1E	1	1	1	1	0	
FHC No.6 next to fire exit stair 3	1	1	1	1	0	
FHC No.7 next to fire exit stair 4	1	1	1	1	0	
FHC No.8 B1D near B1B	1	1	1	1	0	
FHC No.9 Motorcycler Parking	1	1	1	1	0	
FHC No.10 CP 1/2	1	1	1	1	0	
FHC No.11 B1A	1	1	1	1	0	
FHC No.12 B1A	1	1	1	1	0	
ENG Work shop	0	0	0	6	2	
<b>Floor B2</b>						
FHC No.B2B(Pillar S13)	1	1	1	1	0	
FHC No.2 next to fire exit stair 6	1	1	1	1	0	
FHC No.3 next to fire exit stair 1	1	1	1	1	0	
FHC No.4 B2 Pillar B4	1	1	1	1	0	
FHC No.5 Pillar A4 B1E Pillar U1	1	1	1	1	0	
FHC No.6 B2B next to fire exit stair 17	1	1	1	1	0	
FHC No.7 B2B Pillar U1	1	1	1	1	0	
FHC No.8 B2B Chiller Room	1	1	1	1	0	
FHC No.9 next to fire exit stair 4	1	1	1	1	0	
FHC No.10 CP 1/2	1	1	1	1	0	
FHC No.11 B2B Pillar T9	1	1	1	1	0	
Store Security	0	0	0	6	1	
<b>Out side</b>						
Gas Station	0	0	0	6	0	
Main Entrance	0	0	0	2	0	
<b>TOTAL</b>	<b>61</b>	<b>61</b>	<b>61</b>	<b>86</b>	<b>15</b>	

Main Entrance ติดตั้ง CO2 ของส่วนกลาง 3 ตัว

Date 13/02//2024

CHECKED BY Annart/Sukhoon/Bontien

DIRECTOR SECURITY



# FIRE EXTINGUISHER HOTEL CHECKLIST (1. Ballroom Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
ROOFTOP						
FHC on Rooftop stair 7	1	1	1	1	0	
FLOOR 3						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Near Rest room Guest	1	1	1	1	0	
FHC No.3 next to fire exit stair 8	1	1	1	1	0	
FHC No.4 In front of BQ Store	1	1	1	1	0	
Floor 2						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 AHU Room	1	1	1	1	0	
FHC No.3 next to fire exit stair 8	1	1	1	1	0	
FHC No.4 In front of Excome Office	1	1	1	1	0	
Floor L						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Bar Ballroom Area	1	1	1	1	0	
FHC No.3 Bar Ballroom Area	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	1	
FHC No.5 In front of Terrest Ballroom	1	1	1	1	1	
FHC No.6 In front of Door 2	1	1	1	1	0	
FHC No.7 F/O Counter	1	1	1	1	0	
Floor LL						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Carpark (Near CP 4)	1	1	1	1	0	
FHC No.3 ยังหาตู้ไม่เจอ	1	1	1	1	0	
FHC No.4 ยังหาตู้ไม่เจอ	1	1	1	1	0	
FHC No.5 Door 9 St 19	1	1	1	1	0	
FHC No.6 Art Space (CP 4)	1	1	1	1	0	
FHC No.7 Art Space (Door 6)	1	1	1	1	0	
FHC No.8 Art Space (In side St 18)	1	1	1	1	0	
Floor B1						
FHC No.1 In front H/S 9/10	1	1	1	1	0	
FHC No.2 EV CHARGER	1	1	1	1	1	
FHC No.3 next to fire exit stair 18	1	1	1	1	0	
FHC No.4 next to fire exit stair 19	1	1	1	1	0	
TOTAL	28	28	28	28	3	

## Note

FL LL มีตู้ FHC 1 ตู้ที่ SAITO ยังไม่มีหมายเลข (No.3/4) ไม่มี ข้อต่อ มีถัง Dry 1 ถัง

Date 13/02/2024

CHECKED BY Amnart/S

DIRECTOR SECURITY ...

## SAMMARY

Location	Fire Cabinet	Fire Hose Reel	Brass Valve
Ballroom Building	28	28	28
Palm court Building	64	64	64
Cascade Building	99	98	100
Keep in Store	0	0	0
Waiting for refill/Broken	0	0	0
Total	191	190	192

Discard DRY=4 Pcs[27/07/2023] Discard DRY=1Pcs[26/09/23] Disc

Date 23/07/2024

CHECKED BY

DIRECTOR :

.....

Dry Chemical	CO2	Remark
27	2	
92	14	
100	19	
0	0	
0	0	
<b>219</b>	<b>36</b>	

ard DRY=4[23/02/24] Total =9



## B/A CONTROL BOARD

### FSH

NUMBER	REFILL DATE	EXPIRE DATE	TANK SIZE	BAR	USAGE TIME	REMARK
B/A No.1	12/7/2022	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
B/A No.2	12/7/2022	N/A	6.8 L	150	15.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว

### FSR

B/A No.1	8/8/2023	N/A	6.8 L	230	29 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
B/A No.2	8/8/2023	N/A	6.8 L	150	15.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว

### SPARE

SPARE No.1	21/10/2320	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
SPARE No.2	21/10/2320	N/A	6.8 L	0		
SPARE No.3	21/10/2320	N/A	6.8 L	0		

Date 23/02/2024

CHECKED BY Amn

DIRECTOR SECURITY



## FIRE EXTINGUISHER RESIDENCES CHECK LIST

MONTH: FEB, 2024

LOCATION	DRY	CO2	NOTE	DATE
ROOFTOP				
FHC	0	2		
FLOOR 69				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	1		
FLOOR 68				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 67				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 66				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 65				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 64				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 63				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 62				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 61				
FHC No.1 RST.2	0	0		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 60				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 59				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 58				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 57				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 56				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 55				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 54				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 53				
FHC No.1 RST.2	1	1		

FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 52				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 51				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 50				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 49				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 48				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 47				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 46				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 45				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 43 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 43				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 42				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 41				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
Fire Pump Room	1	0		
FLOOR 40				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 39				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 38				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 37				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 36				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 35				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		



FHC No.3 RST.1	1	1		
FLOOR 34				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 32 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 32				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 31				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 30				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 29				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 28				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 27				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 26				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 25				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 24				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 22 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 22				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 21				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 20				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 19				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 18				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 17				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 16				

FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 15				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 14				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 12 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 12				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 11				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	0	FHC IN GUEST ROOM	
FLOOR 10				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 9				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0		
FLOOR 8				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 7				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 6				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 5				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 4				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 3				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 Facility Office	1	0		
FLOOR 2				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 1				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 OFFICE AREA	1	1		
FLOOR 1L				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 Pet Grooming	1	0		
FHC No.5 Storage	1	0		
FHC No.6 ENG Office	1	0		
FHC No.7 Loading area	1	0		
FLOOR B1				

FHC No.1 RST.2	1	0		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	0		
FHC No.4 Door2	1	0		
FHC No.5 B1C Pillar A13	1	0		
FHC No.6 B1C Pillar F14	1	0		
FHC No.7 B1C Pillar M14	1	0		
FHC No.8 Fanroom	1	0		
Total	214	130		

FHC IN ROOM GUEST	
Room Number	Floor
8	69
11	66-67
26	62-63
27	60-61
28	60-61
324	10-11

ALL FIRE EXTINGUISHER		
LOCATION	DRY CHEMICAL	CO2
HOTEL	219	38
RESSIDENCE	214	130
TOTAL	433	168

total 5 Room
--------------

Date 23/02/2024

Checked by

DIRECTOR SEC



FIRE EXTINGUISHER(TYPE K)/FIRE BLANKET

DATE 03/03/2024

LOCATON	WET CHEMICAL		FIRE BLANKET		REMARK
	AVAILABLE	STATUS	AVAILABLE	STATUS	
Ballroom Kitchen	3	/	2	/	
Conservatory Kitchen	3	/	2	/	
B/P Kitchen	3	/	1	/	
RIVA Kitchen	3	/	2	/	
BKK Kitchen	2	/	2	/	
YTY Kitchen	2	/	1	/	
MAIN Kitchen	1	0	0	0	
BAKERRY Kitchen	1	/	0	0	
GRILL ROOM Kitchen	1	/	0	0	
IRD Kitchen	1	/	1	/	
SOI 64 Kitchen	1	/	2	/	
Riverfront Kitchen	3	/	2	/	
The lounge	0	0	1	/	
Fire card No . 1	0	0	1	/	
Fire card No . 2 set up H/S 9,10 B1	0	0	1	/	Fire Blanket For car
SKY LOUNGE FSR	0	0	1	/	
Cabinet of ammunition No.1 (H/S 1/2)	0	0	0	0	
Cabinet of ammunition No.2(H/S 7/8)	0	0	0	0	
Cabinet of ammunition No.3(H/S 9/10)	0	0	0	0	
Cabinet of ammunition No.4 Residence	0	0	0	0	
STOREROOM B2	0	0	3	0	
TOTAL	24		22		

ถัง type K รวมเต็ม 1 ถัง

CHECKED BY  
FIRE DETECTOR SECTION

## FIRE EXTINGUISHER HOTEL CHECKLIST (1. Ballroom Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
ROOFTOP						
FHC on Rooftop stair 7	1	1	1	1	0	
FLOOR 3						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Near Rest room Guest	1	1	1	1	0	
FHC No.3 next to fire exit stair 8	1	1	1	1	0	
FHC No.4 In front of BQ Store	1	1	1	1	0	
Floor 2						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 AHU Room	1	1	1	1	0	
FHC No.3 next to fire exit stair 8	1	1	1	1	0	
FHC No.4 In front of Excome Office	1	1	1	1	0	
Floor L						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Bar Ballroom Area	1	1	1	1	0	
FHC No.3 Bar Ballroom Area	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	1	
FHC No.5 In front of Terrest Ballroom	1	1	1	1	1	
FHC No.6 In front of Door 2	1	1	1	1	0	
FHC No.7 F/O Counter	1	1	1	1	0	
Floor LL						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Carpark (Near CP 4)	1	1	1	1	0	
FHC No.3 ยังหาตู้ไม่เจอ	1	1	1	1	0	
FHC No.4 ยังหาตู้ไม่เจอ	1	1	1	1	0	
FHC No.5 Door 9 St 19	1	1	1	1	0	
FHC No.6 Art Space (CP 4)	1	1	1	1	0	
FHC No.7 Art Space ( Door 6)	1	1	1	1	0	
FHC No.8 Art Space ( In side St 18)	1	1	1	1	0	
Floor B1						
FHC No.1 In front H/S 9/10	1	1	1	1	0	
FHC No.2 EV CHARGER	1	1	1	1	1	
FHC No.3 next to fire exit stair 18	1	1	1	1	0	
FHC No.4 next to fire exit stair 19	1	1	1	1	0	
TOTAL	28	28	28	28	3	

**Note**

FL LL มีตู้ FHC 1 ตู้ที่ SAITO ยังไม่มีหมายเลขตู้ (No.3/4) ไม่มี ข้อต่อ มีถัง Dry 1 ถัง

Date 03/03/2024  
CHECKED BY Amn  
DIRECTOR SECURITY



# FIRE EXTINGUISHER HOTEL CHECKLIST (2. Palm Court Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
<b>ROOFTOP</b>						
FHC on Rooftop stair 4	1	0	1	0	0	
FHC on Rooftop St 06	1	0	1	0	0	
<b>FLOOR 3</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 2</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor L</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
FHC No.7 Luggage store	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor LL</b>						
FHC No.1 Motorcycler Parking	1	1	1	1	0	
FHC No.2 Florist Room(Sol 2)	1	1	1	1	0	
FHC No.3 Room 308	1	1	1	1	0	
FHC No.4 next to fire exit stair 1	1	1	1	1	0	
FHC No.5 next to fire exit stair	1	1	1	1	0	
FHC No.6 Salon Area	1	1	1	1	0	
FHC No.7 Reception Area	1	1	1	1	0	
FHC No.8 Male Locker Area	1	1	1	1	0	
FHC No.9 next to fire exit stair 3	1	1	1	1	0	
FHC No.10 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.11 Generator Room	1	1	1	1	0	
FHC No.12 Near Restroom Sol 64	1	1	1	1	0	
FHC No.13 Luggage store	1	1	1	1	0	
FHC No.14 next to fire exit stair 5	1	1	1	1	0	
FHC No.15 next to fire exit stair 17	1	1	1	1	0	
EE Room next to stair 1	1	1	1	1	0	
EE Room next to stair 3	1	1	1	1	0	
Novac No.1 IT Room	0	0	0	0	0	
Novac No.2 EE Room	0	0	0	0	0	
Novac No.3 Main Power Room	0	0	0	0	0	
Security Office	0	0	0	1	2	
Laundry Area	0	0	0	0	4	
Housekeeping Office	0	0	0	1	0	
<b>Floor B1</b>						
FHC No.B1A	1	1	1	1	0	
FHC No.2 next to fire exit stair 6	1	1	1	1	0	
FHC No.3 Store(Pumproom)(st1) B1E	1	1	1	1	0	
FHC No.4 next to fire exit stair 1	1	1	1	1	0	
FHC No.5 Pillar A4 B1E	1	1	1	1	0	
FHC No.6 next to fire exit stair 3	1	1	1	1	0	
FHC No.7 next to fire exit stair 4	1	1	1	1	0	
FHC No.8 B1D near B1B	1	1	1	1	0	
FHC No.9 Motorcycler Parking	1	1	1	1	0	
FHC No.10 CP 1/2	1	1	1	1	0	
FHC No.11 B1A	1	1	1	1	0	
FHC No.12 B1A	1	1	1	1	0	
ENG Work shop	0	0	0	6	2	
<b>Floor B2</b>						
FHC No.B2B(Pillar S13)	1	1	1	1	0	
FHC No.2 next to fire exit stair 6	1	1	1	1	0	
FHC No.3 next to fire exit stair 1	1	1	1	1	0	
FHC No.4 B2 Pillar B4	1	1	1	1	0	
FHC No.5 Pillar A4 B1E Pillar U1	1	1	1	1	0	
FHC No.6 B2B next to fire exit stair 17	1	1	1	1	0	
FHC No.7 B2B Pillar U1	1	1	1	1	0	
FHC No.8 B2B Chiller Room	1	1	1	1	0	
FHC No.9 next to fire exit stair 4	1	1	1	1	0	
FHC No.10 CP 1/2	1	1	1	1	0	
FHC No.11 B2B Pillar T9	1	1	1	1	0	
Store Security	0	0	0	6	1	
<b>Out side</b>						
Gass Station	0	0	0	6	0	
Main Entrance	0	0	0	2	0	
<b>TOTAL</b>	<b>61</b>	<b>61</b>	<b>61</b>	<b>86</b>	<b>15</b>	

Main Entrance ติดตั้ง CO2 ของส่วนกลาง 3 ตัว

Date 03/03/202

CHECKED BY Amn

DIRECTOR SECURI



## FIRE EXTINGUISHER HOTEL CHECKLIST (3.Cascade Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
Rooftop						
FHC on Rooftop	1	0	1	0	0	
Floor 13						
FHC No.1 next to fire exit stair 11	1	1	1	1	0	
FHC No.2 EE Room	1	1	1	1	1	
FHC No.3 next to fire exit stair 12	1	1	1	1	0	
Floor 12						
FHC No.1 Near Fire Exit Stair 11	1	1	1	1	0	
FHC No.2 IN front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Next to Fire Exit Stair 12	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Floor 11						
FHC No.1 Near Fire Exit Stair 11	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.4 next to Fire Exit stair 13	1	1	1	1	0	
FHC No.5 In front of AHU Room	1	1	1	1	0	
FHC No.6 next to Fire Exit stair 15	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Floor 10						
FHC No.1 next to Fire exit stair 11	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire exit stair 12	1	1	1	1	0	
FHC No.4 next to fire exit stair 13	1	1	1	1	0	
FHC No.5 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.6 near fire exit stair 15	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
AHU Room	0	0	0	0	1	
Floor 9						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 8						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 7						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 6						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 5						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1			0	
FHC No.6 near fire exit stair 14	1	1			0	

FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7.8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 4						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In front of Lift HS 7.8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7.8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 3						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In front of Lift HS 7.8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7.8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 2						
FHC No.1 In front of Lift HS 7.8	1	1	1	1	0	
FHC No.2 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 13	1	1	1	1	0	
FHC No.4 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.5 next to Fire Exit stair 15	1	1	1	1	0	
FHC No.6 next to Fire Exit stair 15	1	1	1	1	0	
In front of Room 202	1	1	1	1	0	
Floor L						
FHC No.1 front of YTY Resterance	1	1	1	1	0	
FHC No.2 In front of Lift HS 7.8	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.4 next to Fire exit stair 13	1	1	1	1	0	
FHC No.5 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.6 In front of Lift HP.9	1	1	1	1	0	
FHC No.7 In front of stair 20	1	1	1	1	0	
Floor LL						
FHC No.1 Carpark LL[W1]	1	1	1	1	0	
FHC No.2 In front of Lift HS 7.8	1	1	1	1	0	
FHC No.3 Office Executive/Sale	1	1	1	1	0	
FHC No.4 Office Reservation	1	1	1	1	0	
FHC No.5 Carpark LL[U1]	1	1	1	1	0	
FHC No.6 next to Fire exit stair 13	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 Door Gate 3	1	1	1	1	0	
FHC No.9 In front of stair 20	1	1	1	1	0	
FHC No.10 รั้วหน้าอาคาร	0	0	0	0	0	
Floor B1						
FHC No.1 Carpark B1C[M4]	1	1	1	1	0	
FHC No.2 In front of Lift HS 7.8	1	1	1	1	0	
FHC No.3 Carpark B1C[I4]	1	1	1	1	0	
FHC No.4 In front of Lift HS 5,6	1	1	1	1	0	
TOTAL	99	98	100	100	19	

Date 03/03/2024

CHECKED BY Amr

DIRECTOR SECUR

## SAMMARY

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
Ballroom Building	28	28	28	27	2	
Palm court Building	64	64	64	92	14	
Cascade Building	99	98	100	100	19	
Keep in Store	0	0	0	0	0	
Waiting for refill/Broken	0	0	0	0	0	
Total	191	190	192	219	36	

Discard DRY=4 Pcs[27/07/2023] Discard DRY=1Pcs[26/09/23] Discard DRY=5[23/02/24] Total =10

Date 03/03/2024

CHECKED BY A

DIRECTOR SEC



### B/A CONTROL BOARD

#### FSH

NUMBER	REFILL DATE	EXPIRE DATE	TANK SIZE	BAR	USAGE TIME	REMARK
B/A No.1	7/12/2022	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
B/A No.2	7/12/2022	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว

#### FSR

B/A No.1	8/8/2023	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
B/A No.2	8/8/2023	N/A	6.8 L	150	15.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว

#### SPARE

SPARE No.1	10/21/2320	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
SPARE No.2	10/21/2320	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
SPARE No.3	10/21/2320	N/A	6.8 L	150	15.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว

Date 25/03/2

CHECKED BY A

DIRECTOR SEC



## FIRE EXTINGUISHER RESIDENCES CHECK LIST

MONTH: Mar,2024

LOCATION	DRY	CO2	NOTE	DATE
ROOFTOP				
FHC	0	2		
FLOOR 69				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	1		
FLOOR 68				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 67				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 66				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 65				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 64				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 63				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 62				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 61				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 60				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 59				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 58				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 57				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 56				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 55				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 54				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 53				
FHC No.1 RST.2	1	1		

FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 52				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 51				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 50				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 49				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 48				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 47				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 46				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 45				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 43 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 43				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 42				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 41				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
Fire Pump Room	1	0		
FLOOR 40				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 39				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 38				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 37				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 36				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 35				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		



FHC No.3 RST.1	1	1		
FLOOR 34				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 32 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 32				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 31				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 30				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 29				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 28				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 27				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 26				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 25				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 24				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 22 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 22				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 21				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 20				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 19				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 18				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 17				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 16				

[illegible]

FHC No.1 RST.2	1	0		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	0		
FHC No.4 Door2	1	0		
FHC No.5 B1C Pillar A13	1	0		
FHC No.6 B1C Pillar F14	1	0		
FHC No.7 B1C Pillar M14	1	0		
FHC No.8 Fanroom	1	0		
Total	214	130		

FHC IN ROOM GUEST	
Room Number	Floor
8	69
11	66-67
26	62-63
27	60-61
28	60-61
324	10-11

ALL FIRE EXTINGUISHER		
LOCATION	DRY CHEMICAL	CO2
HOTEL	219	38
RESSIDENCE	214	130
TOTAL	433	168

Total Rooms

Date 25/0

Checked

DIRECTOR



FIRE EXTINGUISHER(TYPE K)/FIRE BLANKET

DATE 05/04/2024

LOCATON	WET CHEMICAL		FIRE BLANKET		REMARK
	AVAILABLE	STATUS	AVAILABLE	STATUS	
Ballroom Kitchen	3	/	2	/	
Conservatory Kitchen	3	/	2	/	
B/P Kitchen	3	/	1	/	
RIVA Kitchen	3	/	2	/	
BKK Kitchen	2	/	2	/	
YTY Kitchen	2	/	1	/	
MAIN Kitchen	1	0	0	0	
BAKERRY Kitchen	1	/	0	0	
GRILL ROOM Kitchen	1	/	0	0	
IRD Kitchen	1	/	1	/	
SOI 64 Kitchen	1	/	2	/	
Riverfront Kitchen	3	/	2	/	
Fire Lounge	0	0	1	/	
Fire card No . 1	0	0	1	/	
Fire card No . 2 set up H/S 9,10 B1	0	0	1	/	Fire Blanket For car
SKY LOUNGE FSR	0	0	1	/	
Cabinet of ammunition No.1 (H/S 1/2)	0	0	0	0	
Cabinet of ammunition No.2(H/S 7/8)	0	0	0	0	
Cabinet of ammunition No.3(H/S 9/10)	0	0	0	0	
Cabinet of ammunition No.4 Residence	0	0	0	0	
STOREROOM B2	0	0	3	0	
TOTAL	24		22		

ถัง type K รอเติม 1 ถัง

CHECK  
ECT



# FIRE EXTINGUISHER HOTEL CHECKLIST (1. Ballroom Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
<b>ROOFTOP</b>						
FHC on Rooftop stair 7	1	1	1	1	0	
<b>FLOOR 3</b>						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Near Rest room Guest	1	1	1	1	0	
FHC No.3 next to fire exit stair 8	1	1	1	1	0	
FHC No.4 In front of BQ Store	1	1	1	1	0	
<b>Floor 2</b>						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 AHU Room	1	1	1	1	0	
FHC No.3 next to fire exit stair 8	1	1	1	1	0	
FHC No.4 In front of Excome Office	1	1	1	1	0	
<b>Floor L</b>						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Bar Ballroom Area	1	1	1	1	0	
FHC No.3 Bar Ballroom Area	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	1	
FHC No.5 In front of Terrest Ballroom	1	1	1	1	1	
FHC No.6 In front of Door 2	1	1	1	1	0	
FHC No.7 F/O Counter	1	1	1	1	0	
<b>Floor LL</b>						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Carpark (Near CP 4)	1	1	1	1	0	
FHC No.3 ยิงหาตู้ไม่เจอ	1	1	1	1	0	
FHC No.4 ยิงหาตู้ไม่เจอ	1	1	1	1	0	
FHC No.5 Door 9 St 19	1	1	1	1	0	
FHC No.6 Art Space (CP 4)	1	1	1	1	1	
FHC No.7 Art Space (Door 6)	1	1	1	1	0	
FHC No.8 Art Space (In side St 18)	1	1	1	1	0	
<b>Floor B1</b>						
FHC No.1 In front H/S 9/10	1	1	1	1	0	
FHC No.2 EV CHARGER	1	1	1	1	1	
FHC No.3 next to fire exit stair 18	1	1	1	1	0	
FHC No.4 next to fire exit stair 19	1	1	1	1	0	
<b>TOTAL</b>	<b>28</b>	<b>28</b>	<b>28</b>	<b>28</b>	<b>4</b>	

**Note**

FL LL มีตู้ FHC 1 ตู้ที่ SAITO ยิงไม่พบหมายเลขตู้ (No.3/4) ไม่มี ข้อต่อ มีถัง Dry 1 ถัง



## FIRE EXTINGUISHER HOTEL CHECKLIST (2. Palm Court Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
<b>ROOFTOP</b>						
FHC on Rooftop stair 4	1	0	1	0	0	
FHC on Rooftop S106	1	0	1	0	0	
<b>FLOOR 3</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 2</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 1</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
FHC No.7 Luggage store	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 11</b>						
FHC No.1 Motorcycler Parking	1	1	1	1	0	
FHC No.2 Florist Room(Sol 2)	1	1	1	1	0	
FHC No.3 Room 308	1	1	1	1	0	
FHC No.4 next to fire exit stair 1	1	1	1	1	0	
FHC No.5 next to fire exit stair	1	1	1	1	0	
FHC No.6 Salon Area	1	1	1	1	0	
FHC No.7 Reception Area	1	1	1	1	0	
FHC No.8 Male Locker Area	1	1	1	1	0	
FHC No.9 next to fire exit stair 3	1	1	1	1	0	
FHC No.10 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.11 Generator Room	1	1	1	1	0	
FHC No.12 Near Restroom Sol 64	1	1	1	1	0	
FHC No.13 Luggage store	1	1	1	1	0	
FHC No.14 next to fire exit stair 5	1	1	1	1	0	
FHC No.15 next to fire exit stair 17	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
Novac No.1 IT Room	0	0	0	0	0	
Novac No.2 EE Room	0	0	0	0	0	
Novac No.3 Main Power Room	0	0	0	0	0	
Security Office	0	0	0	0	1	
Laundry Area	0	0	0	0	4	
Housekeeping Office	0	0	0	1	0	
<b>Floor B1</b>						
FHC No.1 B1A	1	1	1	1	0	
FHC No.2 next to fire exit stair 6	1	1	1	1	0	
FHC No.3 Store(Pumproom)(st1) B1E	1	1	1	1	0	
FHC No.4 next to fire exit stair 1	1	1	1	1	0	
FHC No.5 Pillar A4 B1E	1	1	1	1	0	
FHC No.6 next to fire exit stair 3	1	1	1	1	0	
FHC No.7 next to fire exit stair 4	1	1	1	1	0	
FHC No.8 B1D near B1B	1	1	1	1	0	
FHC No.9 Motorcycler Parking	1	1	1	1	0	
FHC No.10 CP 1/2	1	1	1	1	0	
FHC No.11 B1A	1	1	1	1	0	
FHC No.12 B1A	1	1	1	1	0	
ENG Work shop	0	0	0	6	2	
<b>Floor B2</b>						
FHC No.B2B(Pillar S13)	1	1	1	1	0	
FHC No.2 next to fire exit stair 6	1	1	1	1	0	
FHC No.3 next to fire exit stair 1	1	1	1	1	0	
FHC No.4 B2 Pillar B4	1	1	1	1	0	
FHC No.5 Pillar A4 B1E Pillar U1	1	1	1	1	0	
FHC No.6 B2B next to fire exit stair 17	1	1	1	1	0	
FHC No.7 B2B Pillar U1	1	1	1	1	0	
FHC No.8 B2B Chiller Room	1	1	1	1	0	
FHC No.9 next to fire exit stair 4	1	1	1	1	0	
FHC No.10 CP 1/2	1	1	1	1	0	
FHC No.11 B2B Pillar T9	1	1	1	1	0	
Store Security	0	0	0	4	1	
<b>Out side</b>						
Gas Station	0	0	0	6	0	
Main Entrance	0	0	0	2	0	
				86	15	

คิดตั้ง CO2 ของส่วนกลาง 3 ตัน



## FIRE EXTINGUISHER HOTEL CHECKLIST (3.Cascade Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
Rooflop						
FHC on Rooflop	1	0	1	0	0	
Floor 13						
FHC No.1 next to fire exit stair 11	1	1	1	1	0	
FHC No.2 EE Room	1	1	1	1	1	
FHC No.3 next to fire exit stair 12	1	1	1	1	0	
Floor 12						
FHC No.1 Near Fire Exit Stair 11	1	1	1	1	0	
FHC No.2 IN front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Next to Fire Exit Stair 12	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Floor 11						
FHC No.1 Near Fire Exit Stair 11	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.4 next to Fire Exit stair 13	1	1	1	1	0	
FHC No.5 In front of AHU Room	1	1	1	1	0	
FHC No.6 next to Fire Exit stair 15	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Floor 10						
FHC No.1 next to Fire exit stair 11	1	1	1	1	0	
FHC No.2 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire exit stair 12	1	1	1	1	0	
FHC No.4 next to fire exit stair 13	1	1	1	1	0	
FHC No.5 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.6 near fire exit stair 15	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
AHU Room	0	0	0	0	1	
Floor 9						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 8						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 7						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 6						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 5						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	

FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 4						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 in front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 in front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 3						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 in front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 in front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 2						
FHC No.1 in front of Lift HS 7,8	1	1	1	1	0	
FHC No.2 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 13	1	1	1	1	0	
FHC No.4 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.5 next to Fire Exit stair 15	1	1	1	1	0	
FHC No.6 next to Fire Exit stair 15	1	1	1	1	0	
In front of Room 202	1	1	1	1	0	
Floor 1						
FHC No.1 front of YTY Resterance	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.4 next to Fire exit stair 13	1	1	1	1	0	
FHC No.5 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.6 In front of Lift HP.9	1	1	1	1	0	
FHC No.7 In front of stair 20	1	1	1	1	0	
Floor LL						
FHC No.1 Carpark LL[W1]	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Office Executive/Sale	1	1	1	1	0	
FHC No.4 Office Reservation	1	1	1	1	0	
FHC No.5 Carpark LL[U1]	1	1	1	1	0	
FHC No.6 next to Fire exit stair 13	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 Door Gate 3	1	1	1	1	0	
FHC No.9 In front of stair 20	1	1	1	1	0	
FHC No.10 ลิ้นชักไฟไหม้	0	0	0	0	0	
Floor B1						
FHC No.1 Carpark B1C[M4]	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Carpark B1C[I4]	1	1	1	1	0	
FHC No.4 In front of Lift HS 5,6	1	1	1	1	0	
TOTAL	99	98	100	100	19	


Date 05/04/  
CHECKED BY  
DIRECTOR S

SAMMARY

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
Ballroom Building	28	28	28	27	4	
Palm court Building	64	64	64	92	14	
Cascade Building	99	98	100	100	19	
Keep in Store	0	0	0	0	0	
Waiting for refill/Broken	0	0	0	0	0	
Total	191	190	192	219	38	

Discard DRY=4 Pcs[27/07/2023] Discard DRY=1Pcs[26/09/23] Discard DRY=5[23/02/24] Total =10

Date 05/  
CHECKED  
DIRECTO





**FIRE EXTINGUISHER RESIDENCES CHECK LIST**

MONTH: Apr,2024

LOCATION	DRY	CO2	NOTE	DATE
<b>ROOFTOP</b>				
FHC	0	2		
<b>FLOOR 69</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	1		
<b>FLOOR 68</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 67</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
<b>FLOOR 66</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
<b>FLOOR 65</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 64</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 63</b>				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 62</b>				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 61</b>				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
<b>FLOOR 60</b>				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
<b>FLOOR 59</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 58</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 57</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 56</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		

FHC No.3 RST.1	1	1		
FLOOR 55				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 54				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 53				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 52				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 51				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 50				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 49				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 48				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 47				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 46				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 45				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 43 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 43				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 42				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 41				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
Fire Pump Room	1	0		
FLOOR 40				

FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 39				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 38				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 37				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 36				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 35				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 34				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 32 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 32				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 31				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 30				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 29				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 28				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 27				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 26				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 25				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		



FLOOR 24				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 22 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 22				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 21				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 20				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 19				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 18				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 17				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 16				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 15				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 14				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 12 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 12				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.3	1	1		
FLOOR 11				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	0	FHC IN GUEST ROOM	
FLOOR 10				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 9				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		

FHC No.3 RST.1	0	0		
<b>FLOOR 8</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 7</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 6</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 5</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 4</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 3</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 Facility Office	1	0		
<b>FLOOR 2</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 1</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 OFFICE AREA	1	1		
FHC No.5 B/Q STORE	1	0		
<b>FLOOR 1L</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 Pet Grooming	1	0		
FHC No.5 ยิงหาตุไม่เจอ	1	0		
FHC No.6 ENG Office	1	0		
FHC No.7 Loading area	2	0		
<b>FLOOR B1</b>				
FHC No.1 RST.2	1	0		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	0		
FHC No.4 Door2	1	0		
FHC No.5 B1C Pillar A13	1	0		
FHC No.6 B1C Pillar F14	1	0		
FHC No.7 B1C Pillar M14	1	0		
FHC No.8 Fanroom	1	0		
<b>Total</b>	<b>214</b>	<b>130</b>		

FHC IN ROOM GUEST	
Room Number	Floor
8	69
11	66-67
26	62-63
27	60-61
28	60-61
324	10-11

total 5 Room
--------------

ALL FIRE EXTINGUSHER		
LOCATION	DRY CHEMICAL	CO2
HOTEL	219	38
RESIDENCE	214	130
TOTAL	433	168





B/A CONTROL BOARD

FSH

NUMBER	REFILL DATE	EXPIRE DATE	TANK SIZE	BAR	USAGE TIME	REMARK
B/A No.1	29/02/2024	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
B/A No.2	29/02/2024	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว

FSR

B/A No.1	29/02/2024	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
B/A No.2	29/02/2024	N/A	6.8 L	150	15.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว

SPARE

SPARE No.1	29/02/2024	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
SPARE No.2	29/02/2024	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
SPARE No.3	29/02/2024	N/A	6.8 L	150	15.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว

Da  
CHI  
DIR



### FIRE EXTINGUISHER(GREEN CHEMICAL)

LOCATON	GREEN CHEMICAL	
	AVAILABLE	STATUS
Server room in IT office	1	/
Finances Fire hose reel cabinet.	1	/
S&M Fire hose reel cabinet.	1	/
MDB room	1	/
IRD kitchen	1	/
Main Kitchen	1	/
Soi 64 kitchen	1	/
Fire control room	1	/
Front office	1	/
Lobby area	1	/
Gate 2 (Ballroom)	1	/
Lobby lounge	1	/
YTY kitchen	1	/
BKK kitchen	1	/
RIVA kitchen	1	/
Palmier kitchen	1	/
Art space area	1	/
Chiller room (Electrical control room).	1	/
B1 Residence	1	/
Spare [store Security]	1	/
Total	20	

FIRE EXTINGUISHER(TYPE K)/FIRE BLANKET

DATE 16/05/2024

LOCATON	WET CHEMICAL		FIRE BLANKET		REMARK
	AVAILABLE	STATUS	AVAILABLE	STATUS	
Ballroom Kitchen	3	/	2	/	
Conservatory Kitchen	3	/	2	/	
B/P Kitchen	3	/	1	/	
RIVA Kitchen	3	/	2	/	
BKK Kitchen	2	/	2	/	
YTY Kitchen	2	/	1	/	
MAIN Kitchen	1	0	0	0	
BAKERRY Kitchen	1	/	0	0	
GRILL ROOM Kitchen	1	/	0	0	
IRD Kitchen	1	/	1	/	
SOI 64 Kitchen	1	/	2	/	
Riverfront Kitchen	3	/	2	/	
Tr lounge	0	0	1	/	
Fire Card No . 1	0	0	1	/	
Fire card No . 2 set up H/S 9,10 B1	0	0	1	/	Fire Blanket For car
SKY LOUNGE FSR	0	0	1	/	
Cabinet of ammunition No.1 (H/S 1/2)	0	0	0	0	
Cabinet of ammunition No.2(H/S 7/8)	0	0	0	0	
Cabinet of ammunition No.3(H/S 9/10)	0	0	0	0	
Cabinet of ammunition No.4 Residence	0	0	0	0	
STOREROOM B2	0	0	3	0	
TOTAL	24		22		

ถัง type K รอเติม 1 ถัง

CHECK  
RECEIVED





## FIRE EXTINGUISHER HOTEL CHECKLIST (1. Ballroom Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
<b>ROOFTOP</b>						
FHC on Rooftop stair 7	1	1	1	1	0	
<b>FLOOR 3</b>						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Near Rest room Guest	1	1	1	1	0	
FHC N0.3 next to fire exit stair 8	1	1	1	1	0	
FHC No.4 In front of BQ Store	1	1	1	1	0	
<b>Floor 2</b>						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 AHU Room	1	1	1	1	0	
FHC N0.3 next to fire exit stair 8	1	1	1	1	0	
FHC No.4 In front of Excome Office	1	1	1	1	0	
<b>Floor L</b>						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Bar Ballroom Area	1	1	1	1	0	
FHC N0.3 Bar Ballroom Area	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	1	
FHC No.5 In front of Terrest Ballroom	1	1	1	1	1	
FHC No.6 In front of Door 2	1	1	1	1	0	
FHC N0.7 F/O Counter	1	1	1	1	0	
<b>Floor LL</b>						
FHC No.1 In front of Lift H,S 9/10	1	1	1	1	0	
FHC No.2 Carpark (Near CP 4)	1	1	1	1	0	
FHC N0.3 ยังหาตู้ไม่เจอ	1	1	1	1	0	
FHC No.4 ยังหาตู้ไม่เจอ	1	1	1	1	0	
FHC No.5 Door 9 St 19	1	1	1	1	0	
FHC No.6 Art Space (CP 4)	1	1	1	1	1	
FHC N0.7 Art Space ( Door 6)	1	1	1	1	0	
FHC N0.8 Art Space ( In side St 18)	1	1	1	1	0	
<b>Floor B1</b>						
FHC No.1 In front H/S 9/10	1	1	1	1	0	
FHC No.2 EV CHARGER	1	1	1	1	1	
FHC N0.3 next to fire exit stair 18	1	1	1	1	0	
FHC No.4 next to fire exit stair 19	1	1	1	1	0	
<b>TOTAL</b>	<b>28</b>	<b>28</b>	<b>28</b>	<b>28</b>	<b>4</b>	

**Note**

FL LL ที่ตู้ FHC 1 ตู้ที่ SAITO ยังไม่มีหมายเลขตู้ (No.3/4) ไม่มี ข้อต่อ มีถัง Dry 1 ถัง



## FIRE EXTINGUISHER HOTEL CHECKLIST (2. Palm Court Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
<b>ROOFTOP</b>						
FHC on Rooftop stair 4	1	0	1	0	0	
FHC on Rooftop St 06	1	0	1	0	0	
<b>FLOOR 3</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 2</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 1</b>						
FHC No.1 In front of Lift H.S 1,2	1	1	1	1	0	
FHC No.2 next to fire exit stair 1	1	1	1	1	0	
FHC No.3 next to fire exit stair 2	1	1	1	1	0	
FHC No.4 next to fire exit stair 3	1	1	1	1	0	
FHC No.5 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.6 next to fire exit stair 5	1	1	1	1	0	
FHC No.7 Luggage store	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
<b>Floor 11</b>						
FHC No.1 Motorcycler Parking	1	1	1	1	0	
FHC No.2 Florist Room(Sol 2)	1	1	1	1	0	
FHC No.3 Room 308	1	1	1	1	0	
FHC No.4 next to fire exit stair 1	1	1	1	1	0	
FHC No.5 next to fire exit stair	1	1	1	1	0	
FHC No.6 Salon Area	1	1	1	1	0	
FHC No.7 Reception Area	1	1	1	1	0	
FHC No.8 Male Locker Area	1	1	1	1	0	
FHC No.9 next to fire exit stair 3	1	1	1	1	0	
FHC No.10 In front of Lift H.S 3,4	1	1	1	1	0	
FHC No.11 General Room	1	1	1	1	0	
FHC No.12 Near Restroom Sol 64	1	1	1	1	0	
FHC No.13 Luggage store	1	1	1	1	0	
FHC No.14 next to fire exit stair 5	1	1	1	1	0	
FHC No.15 next to fire exit stair 17	1	1	1	1	0	
EE Room next to stair 1	0	0	0	0	1	
EE Room next to stair 3	0	0	0	0	1	
Novac No.1 IT Room	0	0	0	0	0	
Novac No.2 EE Room	0	0	0	0	0	
Novac No.3 Main Power Room	0	0	0	0	0	
Security Office	0	0	0	0	1	
Laundry Area	0	0	0	0	4	
Housekeeping Office	0	0	0	1	0	
<b>Floor B1</b>						
FHC No.1 B1A	1	1	1	1	0	
FHC No.2 next to fire exit stair 6	1	1	1	1	0	
FHC No.3 Store(Pumproom)(st1) B1E	1	1	1	1	0	
FHC No.4 next to fire exit stair 1	1	1	1	1	0	
FHC No.5 Pillar A4 B1E	1	1	1	1	0	
FHC No.6 next to fire exit stair 3	1	1	1	1	0	
FHC No.7 next to fire exit stair 4	1	1	1	1	0	
FHC No.8 B1D near B1B	1	1	1	1	0	
FHC No.9 Motorcycler Parking	1	1	1	1	0	
FHC No.10 CP 1/2	1	1	1	1	0	
FHC No.11 B1A	1	1	1	1	0	
FHC No.12 B1A	1	1	1	1	0	
ENG Work shop	0	0	0	6	2	
<b>Floor B2</b>						
FHC No.828(Pillar S13)	1	1	1	1	0	
FHC No.2 next to fire exit stair 6	1	1	1	1	0	
FHC No.3 next to fire exit stair 1	1	1	1	1	0	
FHC No.4 B2 Pillar B4	1	1	1	1	0	
FHC No.5 Pillar A4 B1E Pillar U1	1	1	1	1	0	
FHC No.6 B28 next to fire exit stair 17	1	1	1	1	0	
FHC No.7 B28 Pillar U1	1	1	1	1	0	
FHC No.8 B28 Chiller Room	1	1	1	1	0	
FHC No.9 next to fire exit stair 4	1	1	1	1	0	
FHC No.10 CP 1/2	1	1	1	1	0	
FHC No.11 B28 Pillar T9	1	1	1	1	0	
Store Security	0	0	0	4	1	
<b>Out side</b>						
Gas Station	0	0	0	6	0	
Main Entrance	0	0	0	2	0	
<b>TOTAL</b>	<b>61</b>	<b>61</b>	<b>61</b>	<b>86</b>	<b>15</b>	

Main Entrance ติดตั้ง CO2 ของส่วนกลาง 3 ตัว

FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 4						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 in Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 3						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 in Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 2						
FHC No.1 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.2 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 13	1	1	1	1	0	
FHC No.4 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.5 next to Fire Exit stair 15	1	1	1	1	0	
FHC No.6 next to Fire Exit stair 15	1	1	1	1	0	
In Front of Room 202	1	1	1	1	0	
Floor L						
FHC No.1 front of YTY Resterance	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.4 next to Fire exit stair 13	1	1	1	1	0	
FHC No.5 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.6 In Front of Lift HP.9	1	1	1	1	0	
FHC No.7 In front of stair 20	1	1	1	1	0	
Floor LL						
FHC No.1 Carpark LL[W1]	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Office Executive/Sale	1	1	1	1	0	
FHC No.4 Office Reservation	1	1	1	1	0	
FHC No.5 Carpark LL[U1]	1	1	1	1	0	
FHC No.6 next to Fire exit stair 13	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 Door Gate 3	1	1	1	1	0	
FHC No.9 In front of stair 20	1	1	1	1	0	
FHC No.10 ห้องวางลิ้นชัก	0	0	0	0	0	
Floor B1						
FHC No.1 Carpark B1C[M4]	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Carpark B1C[M4]	1	1	1	1	0	
FHC No.4 In front of Lift HS 5,6	1	1	1	1	0	
TOTAL	99	98	100	100	19	

Date 16/05/2019  
CHECKED BY  
DIRECTOR



## FIRE EXTINGUISHER HOTEL CHECKLIST (3.Cascade Building)

Location	Fire Cabinet	Fire Hose Reel	Brass Valve	Dry Chemical	CO2	Remark
Rooflap						
FHC on Rooftop	1	0	1	0	0	
Floor 13						
FHC No.1 next to fire exit stair 11	1	1	1	1	0	
FHC No.2 EE Room	1	1	1	1	1	
FHC No.3 next to fire exit stair 12	1	1	1	1	0	
Floor 12						
FHC No.1 Near Fire Exit Stair 11	1	1	1	1	0	
FHC No.2 IN front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 Next to Fire Exit Stair 12	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Floor 11						
FHC No.1 Near Fire Exit Stair 11	1	1	1	1	0	
FHC No.2 In front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire Exit Stair 12	1	1	1	1	0	
FHC No.4 next to Fire Exit stair 13	1	1	1	1	0	
FHC No.5 In front of AHU Room	1	1	1	1	0	
FHC No.6 next to Fire Exit stair 15	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Floor 10						
FHC No.1 next to Fire exit stair 11	1	1	1	1	0	
FHC No.2 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.3 next to Fire exit stair 12	1	1	1	1	0	
FHC No.4 next to fire exit stair 13	1	1	1	1	0	
FHC No.5 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.6 near fire exit stair 15	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
AHU Room	0	0	0	0	1	
Floor 9						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 8						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 7						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 6						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	
FHC No.7 In front of Lift HS 5,6	1	1	1	1	0	
FHC No.8 In front of Lift HS 5,6	1	1	1	1	0	
Maid pantry Lift HS 7,8 (R1)	0	0	0	0	1	
Shaft room	0	0	0	0	1	
Floor 5						
FHC No.1 next to Fire exit stair 10	1	1	1	1	0	
FHC No.2 next to Fire exit stair 11	1	1	1	1	0	
FHC No.3 In Front of Lift HS 7,8	1	1	1	1	0	
FHC No.4 next to Fire exit stair 12	1	1	1	1	0	
FHC No.5 next to fire exit stair 13	1	1	1	1	0	
FHC No.6 near fire exit stair 14	1	1	1	1	0	

**FIRE EXTINGUISHER RESIDENCES CHECK LIST**

MONTH: MAY,2024

LOCATION	DRY	CO2	NOTE	DATE
<b>ROOFTOP</b>				
FHC	0	2		
<b>FLOOR 69</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	1		
<b>FLOOR 68</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 67</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
<b>FLOOR 66</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
<b>FLOOR 65</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 64</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 63</b>				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 62</b>				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 61</b>				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
<b>FLOOR 60</b>				
FHC No.1 RST.2	0	0	FHC IN GUEST ROOM	
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
<b>FLOOR 59</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 58</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 57</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 56</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		

FHC No.3 RST.1	1	1		
<b>FLOOR 55</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 54</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 53</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 52</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 51</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 50</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 49</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 48</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 47</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 46</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 45</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 43 A</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 43</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 42</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
<b>FLOOR 41</b>				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
Fire Pump Room	1	0		
<b>FLOOR 40</b>				



FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 39				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 38				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 37				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 36				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 35				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 34				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 32 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 32				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 31				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 30				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 29				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 28				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 27				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 26				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 25				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		

FLOOR 24				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 22 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 22				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 21				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 20				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 19				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 18				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 17				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 16				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 15				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 14				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 12 A				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 12				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.3	1	1		
FLOOR 11				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	0	FHC IN GUEST ROOM	
FLOOR 10				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	0	0	FHC IN GUEST ROOM	
FLOOR 9				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		


FHC No.3 RST.1	0	0		
FLOOR 8				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 7				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 6				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 5				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 4				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR 3				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 Facility Office	1	0		
FLOOR 2				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FLOOR L				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 OFFICE AREA	1	1		
FHC No.5 B/Q STORE	1	0		
FLOOR LL				
FHC No.1 RST.2	1	1		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	1		
FHC No.4 Pet Grooming	1	0		
FHC No.5 ยั้งหาตุ้มไม่เจอ	1	0		
FHC No.6 ENG Office	1	0		
FHC No.7 Loading area	2	0		
FLOOR B1				
FHC No.1 RST.2	1	0		
FHC No.2 FML	1	0		
FHC No.3 RST.1	1	0		
FHC No.4 Door2	1	0		
FHC No.5 B1C Pillar A13	1	0		
FHC No.6 B1C Pillar F14	1	0		
FHC No.7 B1C Pillar M14	1	0		
FHC No.8 Fanroom	1	0		
Total	214	130		



FHC IN ROOM GUEST	
Room Number	Floor
8	69
11	66-67
26	62-63
27	60-61
28	60-61
324	10-11

total 5 Room
--------------

ALL FIRE EXTINGUSHER		
LOCATION	DRY CHEMICAL	CO2
HOTEL	219	38
RESIDENCE	214	130
TOTAL	433	168



**B/A CONTROL BOARD****FSH**

NUMBER	REFILL DATE	EXPIRE DATE	TANK SIZE	BAR	USAGE TIME	REMARK
B/A No.1	29/02/2024	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
B/A No.2	29/02/2024	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว

**FSR**

B/A No.1	29/02/2024	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
B/A No.2	29/02/2024	N/A	6.8 L	150	15.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว

**SPARE**

SPARE No.1	29/02/2024	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
SPARE No.2	29/02/2024	N/A	6.8 L	250	32.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว
SPARE No.3	29/02/2024	N/A	6.8 L	150	15.5 Minute	ลบ 10 นาที เพื่อ Safety Factor แล้ว



# Annual testing the fire hose and fire nozzle of 2024



Under the provisions of the standard for testing fire hoses and fire nozzles (reducing pressure type) of the fire fighter team annually, on January 11, 2024, at 15:00, the FLS manager and technician team jointly tested the fire hoses of the hotel. The test results and details are as follows:

**Fire hose specifications: Quick-joint valve type, size 1.5 inches, length 30 meters, quantity 3.**

**Test results:**

- All 3 fire hoses withstand pressure and do not leak throughout the length.
  - They function normally without any defects. ✓
- The hose connectors for all three hoses withstand pressure and do not leak.
  - They function normally without any defects. ✓
- The hoses can be moved during pressurization without any issues.
  - They function normally without any defects. ✓



**Fire nozzle specifications: Pressure-reducing type, quantity 2. And functional test results:**



- The open/close valve function operates normally without any defects. ✓
- The water curtain size adjustment function operates normally without any defects. ✓
- The water flow rate adjustment function operates normally without any defects. ✓





# FIRE PROTECTING AND FIRE EQUIPMENT CHECKLIST



CAPELLA  
BANGKOK

Monthly: April, 2024

LEVEL	LOCATION	TYPE	FIRE HOSE CABINET	DRY CHEMICAL	CO2	CLASS K	FIRE BLANKET	STATUS		ADDITIONAL & COMMENT	CHECK: BY
								YES	NO		
Roof top floor	ROOFTOP HELIPAD FLOOR	FHB	1					✓			
	FHC - 11 - 01	FHC/FE	1	1				✓			
	FHC - 11 - 02	FHC/FE	1	1				✓			
	FHC - 11 - 03	FHC/FE	1	1				✓			
	EE ROOM	CO2			1			✓			
10th floor	FHC - 10 - 01	FHC/FE	1	1				✓			
	FHC - 10 - 02	FHC/FE	1	1				✓			
	FHC - 10 - 03	FHC/FE	1	1				✓			
	SHAFT ROOM BETWEEN 1009-1010	FIRE EXTINGUISHER		1				✓			
	SHAFT ROOM BETWEEN 1003-1005	FIRE EXTINGUISHER		1				✓			
	EE ROOM BOH	CO2			1			✓			
9th floor	FHC - 9 - 01	FHC/FE	1	1				✓			
	FHC - 9 - 02	FHC/FE	1	1				✓			
	FHC - 9 - 03	FHC/FE	1	1				✓			
	SHAFT ROOM BETWEEN 908-909	FIRE EXTINGUISHER		1				✓			
	SHAFT ROOM BETWEEN 903-905	FIRE EXTINGUISHER		1				✓			
	EE ROOM BOH	CO2			1			✓			
8th floor	FHC - 8 - 01	FHC/FE	1	1				✓			
	FHC - 8 - 02	FHC/FE	1	1				✓			
	FHC - 8 - 03	FHC/FE	1	1				✓			
	SHAFT ROOM BETWEEN 808-809	FIRE EXTINGUISHER		1				✓			
	SHAFT ROOM BETWEEN 802-803	FIRE EXTINGUISHER		1				✓			
	EE ROOM BOH	CO2			1			✓			
7th floor	FHC - 7 - 01	FHC/FE	1	1				✓			
	FHC - 7 - 02	FHC/FE	1	1				✓			
	FHC - 7 - 03	FHC/FE	1	1				✓			
	SHAFT ROOM BETWEEN 708-709	FIRE EXTINGUISHER		1				✓			
	SHAFT ROOM BETWEEN 702-703	FIRE EXTINGUISHER		1				✓			
	EE ROOM BOH	CO2			1			✓			

# FIRE PROTECTING AND FIRE EQUIPMENT CHECKLIST

Monthly: April, 2024

LEVEL	LOCATION	TYPE	FIRE HOSE CABINET	DRY CHEMICAL	CO2	CLASS K	FIRE BLANKET	STATUS		ADDITIONAL & COMMENT	CHECK: BY
								YES	NO		
6th floor	FHC - 6 - 01	FHC/FE	1	1				✓			
	FHC - 6 - 02	FHC/FE	1	1				✓			
	FHC - 6 - 03	FHC/FE	1	1				✓			
	SHAFT ROOM BETWEEN 608-609	FIRE EXTINGUISHER		1				✓			
	SHAFT ROOM BETWEEN 602-603	FIRE EXTINGUISHER		1				✓			
	EE ROOM BOH	CO2			1			✓			
5th floor	FHC - 5 - 01	FHC/FE	1	1				✓			
	FHC - 5 - 02	FHC/FE	1	1				✓			
	FHC - 5 - 03	FHC/FE	1	1				✓			
	SHAFT ROOM BETWEEN 509-510	FIRE EXTINGUISHER		1				✓			
	SHAFT ROOM BETWEEN 503-505	FIRE EXTINGUISHER		1				✓			
	EE ROOM BOH	CO2			1			✓			
4th floor	FHC - 4 - 01	FHC/FE	1	1				✓			
	FHC - 4 - 02	FHC/FE	1	1				✓			
	FHC - 4 - 03	FHC/FE	1	1				✓			
	SHAFT ROOM BETWEEN 409-410	FIRE EXTINGUISHER		1				✓			
	SHAFT ROOM BETWEEN 403-405	FIRE EXTINGUISHER		1				✓			
	EE ROOM BOH	CO2			1			✓			
3rd floor	FHC - 3 - 01	FHC/FE	1	1				✓			
	FHC - 3 - 02	FHC/FE	1	1				✓			
	FHC - 3 - 03	FHC/FE	1	1				✓			
	SHAFT ROOM BETWEEN 309-310	FIRE EXTINGUISHER		1				✓			
	SHAFT ROOM BETWEEN 303-305	FIRE EXTINGUISHER		1				✓			
	EE ROOM BOH	CO2			1			✓			



# FIRE PROTECTING AND FIRE EQUIPMENT CHECKLIST

Monthly: April, 2024

LEVEL	LOCATION	TYPE	FIRE HOSE CABINET	DRY CHEMICAL	CO2	CLASS K	FIRE BLANKET	STATUS		ADDITIONAL & COMMENT	CHECK: BY
								YES	NO		
2nd floor	FHC - 2 - 1/6 R210	FHC/FE	1	1				✓			
	FHC - 2 - 2/6 R206	FHC/FE	1	1				✓			
	FHC - 2 - 3/6 COTE	FHC/FE	1	1				✓			
	FHC - 2 - 4/6 TOILET	FHC/FE	1	1				✓			
	FHC - 2 - 5/6 ATELIER 1	FHC/FE	1	1				✓			
	HK PANTRY(ZONE ST5)	FIRE EXTINGUISHER		1				✓			
	COTE KITCHEN	CLASS K				1		✓			
	INFRONT OF COTE KITCHEN	CLASS K				1		✓			
	SHAFT ROOM BETWEEN 208-209	FIRE EXTINGUISHER		1				✓			
	EE ROOM BOH	CO2			1			✓			
	COTE KITCHEN	FIRE BLANKET					1	✓			
LOBBY LEVEL	FHC - L - 1/6 SA4	FHC/FE	1	1				✓			
	FHC- L - 2/6 POOL AREA	FHC/FE	1	1				✓			
	FHC - L -3/6 LIVING ROOM	FHC/FE	1	1				✓			
	FHC - L - 4/6 IN FRONT OF FRONT DEPT	FHC/FE	1	1				✓			
	FHC - L - 5/6 SA7 STELLA	FHC/FE	1	1				✓			
	FHC- L - 6/6 TOILET SA3	FHC/FE	1	1				✓			
	SHAFT ROOM BETWEEN 109-110	FIRE EXTINGUISHER		1				✓			
	HK PANTRY ZONE ST5	FIRE EXTINGUISHER		1				✓			
	EE ROOM BOH	CO2			1			✓			
	FO OFFICE	FIRE EXTINGUISHER		1				✓			
	FO CORRIDOR	FIRE EXTINGUISHER		1				✓			
	FHC - L -06 BQ WASH	FHC/FE	1	1				✓			
	FHC - L -07 BQ STORE	FHC/FE	1	1				✓			
	FHC - L -08 SALON BALLROOM	FHC/FE	1	1				✓			
	BQ KITCHEN	CLASS K				1		✓			
	BQ KITCHEN	FIRE BLANKET					1	✓			

# FIRE PROTECTING AND FIRE EQUIPMENT CHECKLIST

Monthly: April, 2024

LEVEL	LOCATION	TYPE	FIRE HOSE CABINET	DRY CHEMICAL	CO2	CLASS K	FIRE BLANKET	STATUS		ADDITIONAL & COMMENT	CHECK: BY
								YES	NO		
LOWER LOBBY	FHC - LL - 1/12 VILLA 8	FHC/FE	1	1				1			
	FHC - LL - 2/12 IN FRONT FIRE PUMP ROOM	FHC/FE	1	1				1			
	FHC - LL - 3/12 COOLING TOWER AREA	FHC/FE	1	1				1			
	FHC - LL - 4/12 IN FRONT OF VILLA1	FHC/FE	1	1				1			
	FHC - LL - 5/12 IN FRONT OF FINACE ROOM	FHC/FE	1	1				1			
	FHC - LL - 6/12 SA2	FHC/FE	1	1				1			
	FHC - LL - 7/12 IN FRONT UNIFORM ROOM	FHC/FE	1	1				1			
	FHC - LL - 8/12 IN FRONT OF AHU ROOM	FHC/FE	1	1				1			
	FHC - LL - 9/12 GENERATER ROOM	FHC/FE	1	1				1			
	FHC - LL - 10/12 PHRA NAKHORN	FHC/FE	1	1				1			
	FHC - LL - 11/12 MAIN KITCHEN	FHC/FE	1	1				1			
	FHC - LL - 12/12 LOADING AREA	FHC/FE	1	1				1			
	EXECUTIVE OFFICE	FHC/FE	1	1				1			
	AURIGA SPA	FHC/FE	1	1				1			
	FHL - LL - 5 WALK WAY TO LIFT BQ	FHC/FE	1	1				1			
	EXECUTIVE OFFICE	FIRE EXTINGUISHER		1				1			
	FB OFFICE	FIRE EXTINGUISHER		1				1			
	SALE OFFICE	FIRE EXTINGUISHER		1				1			
	ENGINEERING OFFICE	FIRE EXTINGUISHER		1				1			
	FINANCE OFFICE	FIRE EXTINGUISHER		1				1			
	HR OFFICE	FIRE EXTINGUISHER		1				1			
	IT OFFICE	FIRE EXTINGUISHER		1				1			
	SERVER ROOM	FIRE EXTINGUISHER		1				1			
	101 KITCHEN	CLASS K				1		1			
	HK OFFICE	FIRE EXTINGUISHER	1					1			
	COMMUNICATION ROOM	FIRE EXTINGUISHER	1	5	4	7		1		Type K was broken = 1 tank	



# FIRE PROTECTING AND FIRE EQUIPMENT CHECKLIST

Monthly: April, 2024

LEVEL	LOCATION	TYPE	FIRE HOSE CABINET	DRY CHEMICAL	CO2	CLASS K	FIRE BLANKET	STATUS		ADDITIONAL & COMMENT	CHECK: BY
								YES	NO		
LOWER LOBBY	LP OFFICE	FIRE EXTINGUISHER		1				✓			
	TRAINING ROOM	FIRE EXTINGUISHER		1				✓			
	IN FRONT OF IT OFFICE	CO2			1			✓			
	IN FRONT OF EE ROOM	CO2			1			✓			
	IN FRONT OF LP OFFICE	CO2			1			✓			
	MAIN KITCHEN DOOR 05	CLASS K				1		✓			
	MAIN KITCHEN DOOR 05	CO2			1			✓			
	MAIN KITCHEN DOOR 03 (COLD KITCHEN)	CLASS K				1		✓			
	MAIN KITCHEN DOOR 03 (COLD KITCHEN)	CO2			1			✓			
	MAIN KITCHEN DOOR 01 (BEKERY)	CLASS K				1		✓			
	MAIN KITCHEN DOOR 01 (BEKERY)	CO2			1			✓			
	MAIN KITCHEN DOOR 04	CLASS K				1		✓			
	MAIN KITCHEN DOOR 04	CO2			1			✓			
	FREEZER CORRIDOR	CLASS K				1		✓			
	PRE VEGETABLE CORRIDOR	CLASS K				1		✓			
	BUTCHER	CLASS K				1		✓			
	BEVERAGE STORE	CLASS K				1		✓			
	DRY STORE	CLASS K				1		✓			
	IN FRONT PURCHASING OFFICE	CLASS K / DRY			1	1		✓			
	IN FRONT OF AHU ROOM	FIRE EXTINGUISHER		1				✓			
	FIRE CART OF CABINET	FIRE EXTINGUISHER		1				✓			
	IN FRONT OF COMMUNICATION ROOM	CO2			1			✓			
	101 KITCHEN	FIRE BLANKET					1	✓			
	MAIN KITCHEN	FIRE BLANKET					1	✓			
	FIRE CART OF CABINET	FIRE BLANKET					1	✓		2 Used	
	Cooling Room	FIRE EXTINGUISHER		1				✓			

# FIRE PROTECTING AND FIRE EQUIPMENT CHECKLIST

Monthly: April, 2024

LEVEL	LOCATION	TYPE	FIRE HOSE CABINET	DRY CHEMICAL	CO2	CLASS K	FIRE BLANKET	STATUS		ADDITIONAL & COMMENT	CHECK: BY
								YES	NO		
								✓			
BASEMENT 1	FHC - B1 - 1/10 SA4	FHC/FE	1					✓			
	FHC - B1 - 2/10 SA1	FHC/FE	1					✓			
	FHC - B1 - 3/10 PARKING B8	FHC/FE	1					✓			
	FHC - B1 - 4/10 BACK OF NEW DRIVER ROOM	FHC/FE	1					✓			
	FHC - B1 - 5/10 IN FRONT EXIT SA2	FHC/FE	1					✓			
	FHC - B1 - 6/10 PARKING A3	FHC/FE	1					✓			
	FHC - B1 - 7/10 INFRONT TOLIET	FHC/FE	1					✓			
	FHC - B1 - 8/10 SA7	FHC/FE	1					✓			
	FHC - B1 - 9/10 SA3	FHC/FE	1					✓			
	FHC - B1 - 10/10 Fan Room1	FHC/FE	1					✓			
	EE ROOM	CO2			1			✓			
	PARKING ZONE B5	FIRE EXTINGUISHER		1				✓			
	PARKING ZONE D3	FIRE EXTINGUISHER		1				✓			
	PARKING ZONE F10	FIRE EXTINGUISHER		1				✓			
	LILLY POND ROOM	FIRE EXTINGUISHER		1				✓			
	Fan Room 1	FIRE EXTINGUISHER		1				✓			
	Fan Room 2	FIRE EXTINGUISHER		1				✓			
	CHILLER PLANT ROOM	FIRE EXTINGUISHER		1				✓			
	AT WALL B1 CHILLER ROOM	FIRE EXTINGUISHER		1				✓			
Total			FIRE HOSE CABINET	DRY CHEMICAL	CO2	CLASS K	FIRE BLANKET				
			67	111	24	22	7				

Remark:

	CO2 Standby at Communication Room & .....	4 tanks
	Dry Chemical Stanby Communication Room & .....	5 tanks
	Type K Standby at Communication Room & .....	7 tanks Proper fu use / 1 tank broken

FIRE PROTECTING AND FIRE EQUIPMENT CHECKLIST



Monthly: April, 2024

LEVEL	LOCATION	TYPE	FIRE HOSE CABINET	DRY CHEMICAL	CO2	CLASS K	FIRE BLANKET	STATUS		ADDITIONAL & COMMENT	CHECK: BY
								YES	NO		

Checked by: [redacted] And [redacted] Date: 20 / 4 / 2024.  
Senior Loss Prevention Supervisor Loss Prevention Officer

10-20/04/24

Verified by: [redacted] Date: 29 / 4 / 2024  
Director of Loss Prevention

