


ภาคผนวก ช-3

การตรวจสอบอุปกรณ์ดับเพลิง

Tower A			Tower B		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room	—	ตรวจสอบเสร็จสิ้น	Roof FHC (1)	195	/
FL.8 FHC	195	/	Roof FHC (2)	195	/
FL.7 corridor	100	/	FL.8 FHC 2801	195	/
FL.7 FHC	195	/	FL.8 FHC 2821	195	/
FL.6 corridor	100	/	FL.8 staff lift	100	/
FL.6 FHC	195	/	FL.7 FHC 2701	195	/
FL.5 corridor	100	/	FL.7 FHC 2721	195	/
FL.5 FHC	195	/	FL.7 staff lift	100	/
FL.4 corridor	100	/	FL.6 FHC 2601	195	/
FL.4 FHC	CO2	/	FL.6 FHC 2621	195	/
FL.3 corridor	100	/	FL.6 staff lift	100	/
FL.3 FHC	195	/	FL.5 FHC 2501	195	/
FL.2 corridor	100	/	FL.5 FHC 2521	195	/
FL.2 FHC	CO2	/	FL.5 staff lift	100	/
FL.G FHC security	195	/	FL.4 FHC 2401	195	/
FL.G FHC restaurant	195	/	FL.4 FHC 2421	195	/
FL.B1 FHC	195	/	FL.4 staff lift	100	/
FL.B1 kitchen (1)	100	/	FL.3 FHC 2301	195	/
FL.B1 kitchen (2)	100	/	FL.3 FHC 2321	195	/
FL.B1 staff lift	100	/	FL.3 staff lift	100	/
FL.B2 staff lift	100	/	FL.2 FHC 2201	195	/
FL.B2 FHC	195	/	FL.2 FHC 2221	100	/
FL.B2 FHC fire pump	195	/	FL.2 staff lift	100	/
Generator room	CO2	/	FL.G FHC Lobby	195	/
MDB Room	CO2	/	FHC front office	195	/
MDB Room	CO2	/	FL.B1 FHC Car park	195/195	/
			FL.B2 FHC Car park	195/195	/

Checked By Supervisor		Date	5/1/24
Approve By Chief Engineer		Date	10/7/20

Tower A B			Tower B A		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room	—	705/03/02/03/18	Roof FHC (1)	195	/
FL.8 FHC	195	/	Roof FHC (2)	195	/
FL.7 corridor	100	/	FL.8 FHC 2801	195	/
FL.7 FHC	195	/	FL.8 FHC 2821	195	/
FL.6 corridor	100	/	FL.8 staff lift	100	/
FL.6 FHC	195	/	FL.7 FHC 2701	195	/
FL.5 corridor	100	/	FL.7 FHC 2721	195	/
FL.5 FHC	195	/	FL.7 staff lift	100	/
FL.4 corridor	100	/	FL.6 FHC 2601	195	/
FL.4 FHC	Co2	/	FL.6 FHC 2621	195	/
FL.3 corridor	100	/	FL.6 staff lift	100	/
FL.3 FHC	195	/	FL.5 FHC 2501	195	/
FL.2 corridor	100	/	FL.5 FHC 2521	195	/
FL.2 FHC	Co2	/	FL.5 staff lift	100	/
FL.G FHC security	195	/	FL.4 FHC 2401	195	/
FL.G FHC restaurent	195	/	FL.4 FHC 2421	195	/
FL.B1 FHC	195	/	FL.4 staff lift	100	/
FL.B1 kitchen (1)	100	/	FL.3 FHC 2301	195	/
FL.B1 kitchen (2)	100	/	FL.3 FHC 2321	195	/
FL.B1 staff lift	100	/	FL.3 staff lift	100	/
FL.B2 staff lift	100	/	FL.2 FHC 2201	195	/
FL.B2 FHC	195	/	FL.2 FHC 2221	100	/
FL.B2 FHC fire pump	195	/	FL.2 staff lift	100	/
Generator room	Co2	/	FL.G FHC Lobby	195	/
MDB Room	Co2	/	FHC front office	195	/
MDB Room	Co2	/	FL.B1 FHC Car park	195/195	/
			FL.B2 FHC Car park	195/195	/

Checked By Supervisor	Tom	Date	7/2/2024
Approve By Chief Engineer		Date	7/2/24

Tower <i>A B</i>			Tower <i>B A</i>		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room	—	<i>5/5/10/1/2021/2021</i>	Roof FHC (1)	<i>195</i>	✓
FL.8 FHC	<i>195</i>	✓	Roof FHC (2)	<i>195</i>	✓
FL.7 corridor	<i>100</i>	✓	FL.8 FHC 2801	<i>195</i>	✓
FL.7 FHC	<i>195</i>	✓	FL.8 FHC 2821	<i>195</i>	✓
FL.6 corridor	<i>100</i>	✓	FL.8 staff lift	<i>100</i>	✓
FL.6 FHC	<i>195</i>	✓	FL.7 FHC 2701	<i>195</i>	✓
FL.5 corridor	<i>100</i>	✓	FL.7 FHC 2721	<i>195</i>	✓
FL.5 FHC	<i>195</i>	✓	FL.7 staff lift	<i>100</i>	✓
FL.4 corridor	<i>100</i>	✓	FL.6 FHC 2601	<i>195</i>	✓
FL.4 FHC	<i>Co2</i>	✓	FL.6 FHC 2621	<i>195</i>	✓
FL.3 corridor	<i>100</i>	✓	FL.6 staff lift	<i>100</i>	✓
FL.3 FHC	<i>195</i>	✓	FL.5 FHC 2501	<i>195</i>	✓
FL.2 corridor	<i>100</i>	✓	FL.5 FHC 2521	<i>195</i>	✓
FL.2 FHC	<i>Co2</i>	✓	FL.5 staff lift	<i>100</i>	✓
FL.G FHC security	<i>195</i>	✓	FL.4 FHC 2401	<i>195</i>	✓
FL.G FHC restaurant	<i>195</i>	✓	FL.4 FHC 2421	<i>195</i>	✓
FL.B1 FHC	<i>195</i>	✓	FL.4 staff lift	<i>100</i>	✓
FL.B1 kitchen (1)	<i>100</i>	✓	FL.3 FHC 2301	<i>195</i>	✓
FL.B1 kitchen (2)	<i>100</i>	✓	FL.3 FHC 2321	<i>195</i>	✓
FL.B1 staff lift	<i>100</i>	✓	FL.3 staff lift	<i>100</i>	✓
FL.B2 staff lift	<i>100</i>	✓	FL.2 FHC 2201	<i>195</i>	✓
FL.B2 FHC	<i>195</i>	✓	FL.2 FHC 2221	<i>100</i>	✓
FL.B2 FHC fire pump	<i>195</i>	✓	FL.2 staff lift	<i>100</i>	✓
Generator room	<i>Co2</i>	✓	FL.G FHC Lobby	<i>195</i>	✓
MDB Room	<i>Co2</i>	✓	FHC front office	<i>195</i>	✓
<i>MDB Room.</i>	<i>Co2</i>	✓	FL.B1 FHC Car park	<i>195/195</i>	
			FL.B2 FHC Car park	<i>195/195</i>	

Checked By Supervisor	<i>Tom</i>	Date	<i>3/3/24</i>
Approve By Chief Engineer	<i>[Signature]</i>	Date	<i>3/3/24</i>

Tower A <i>B</i>			Tower B <i>A</i>		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room		<i>90% 195 PSI</i>	Roof FHC (1)	<i>195</i>	
FL.8 FHC	<i>195</i>	<i>/</i>	Roof FHC (2)	<i>195</i>	
FL.7 corridor	<i>100</i>	<i>/</i>	FL.8 FHC 2801	<i>195</i>	
FL.7 FHC	<i>195</i>	<i>/</i>	FL.8 FHC 2821	<i>195</i>	
FL.6 corridor	<i>100</i>	<i>/</i>	FL.8 staff lift	<i>100</i>	
FL.6 FHC	<i>195</i>	<i>/</i>	FL.7 FHC 2701	<i>195</i>	
FL.5 corridor	<i>100</i>	<i>/</i>	FL.7 FHC 2721	<i>195</i>	
FL.5 FHC	<i>195</i>	<i>/</i>	FL.7 staff lift	<i>100</i>	
FL.4 corridor	<i>100</i>	<i>/</i>	FL.6 FHC 2601	<i>195</i>	
FL.4 FHC	<i>102</i>	<i>/</i>	FL.6 FHC 2621	<i>195</i>	
FL.3 corridor	<i>100</i>	<i>/</i>	FL.6 staff lift	<i>100</i>	
FL.3 FHC	<i>195</i>	<i>/</i>	FL.5 FHC 2501	<i>195</i>	
FL.2 corridor	<i>100</i>	<i>/</i>	FL.5 FHC 2521	<i>195</i>	
FL.2 FHC	<i>102</i>	<i>/</i>	FL.5 staff lift	<i>100</i>	
FL.G FHC security	<i>195</i>	<i>/</i>	FL.4 FHC 2401	<i>195</i>	
FL.G FHC restaurant	<i>195</i>	<i>/</i>	FL.4 FHC 2421	<i>195</i>	
FL.B1 FHC	<i>195</i>	<i>/</i>	FL.4 staff lift	<i>100</i>	
FL.B1 kitchen (1)	<i>100</i>	<i>/</i>	FL.3 FHC 2301	<i>195</i>	
FL.B1 kitchen (2)	<i>100</i>	<i>/</i>	FL.3 FHC 2321	<i>195</i>	
FL.B1 staff lift	<i>100</i>	<i>/</i>	FL.3 staff lift	<i>100</i>	
FL.B2 staff lift	<i>100</i>	<i>/</i>	FL.2 FHC 2201	<i>195</i>	
FL.B2 FHC	<i>195</i>	<i>/</i>	FL.2 FHC 2221	<i>100</i>	
FL.B2 FHC fire pump	<i>195</i>	<i>/</i>	FL.2 staff lift	<i>100</i>	
Generator room	<i>102</i>	<i>/</i>	FL.G FHC Lobby	<i>195</i>	
MDB Room	<i>102</i>	<i>/</i>	FHC front office	<i>195</i>	
<i>M.D.B Room</i>	<i>102</i>	<i>/</i>	FL.B1 FHC Car park	<i>195/195</i>	
		<i>/</i>	FL.B2 FHC Car park	<i>195/195</i>	



Checked By Supervisor	<i>ton</i>	Date	<i>4/4/20</i>
Approve By Chief Engineer	<i>[Signature]</i>	Date	<i>2/2/20</i>

**Travelodge**

SUKHUMVIT 11

TRAVELODGE SUKHUMVIT
ENGINEERING DEPARTMENT
EXTINGUISHERS CHECKLIST

Tower A B			Tower B A		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room	—	ถังดับเพลิงไม่พร้อม	Roof FHC (1)	195	
FL.8 FHC	195	/	Roof FHC (2)	195	
FL.7 corridor	100	/	FL.8 FHC 2801	195	
FL.7 FHC	195	/	FL.8 FHC 2821	195	
FL.6 corridor	100	/	FL.8 staff lift	100	
FL.6 FHC	195	/	FL.7 FHC 2701	195	
FL.5 corridor	100	/	FL.7 FHC 2721	195	
FL.5 FHC	195	/	FL.7 staff lift	100	
FL.4 corridor	100	/	FL.6 FHC 2601	195	
FL.4 FHC	Co2	/	FL.6 FHC 2621	195	
FL.3 corridor	100	/	FL.6 staff lift	100	
FL.3 FHC	195	/	FL.5 FHC 2501	195	
FL.2 corridor	100	/	FL.5 FHC 2521	195	
FL.2 FHC	Co2	/	FL.5 staff lift	100	
FL.G FHC security	195	/	FL.4 FHC 2401	195	
FL.G FHC restaurant	195	/	FL.4 FHC 2421	195	
FL.B1 FHC	195	/	FL.4 staff lift	100	
FL.B1 kitchen (1)	100	/	FL.3 FHC 2301	195	
FL.B1 kitchen (2)	100	/	FL.3 FHC 2321	195	
FL.B1 staff lift	100	/	FL.3 staff lift	100	
FL.B2 staff lift	100	/	FL.2 FHC 2201	195	
FL.B2 FHC	195	/	FL.2 FHC 2221	100	
FL.B2 FHC fire pump	195	/	FL.2 staff lift	100	
Generator room	Co2	/	FL.G FHC Lobby	195	
MDB Room	Co2	/	FHC front office	195	
MDB Room	Co2	/	FL.B1 FHC Car park	195/195	
			FL.B2 FHC Car park	195/195	

Checked By Supervisor		Date	5/5/24
Approve By Chief Engineer		Date	11/11/24

Tower A B			Tower B A		
Locations	Pressure Psi.	Remark	Locations	Pressure Psi.	Remark
FL.8 FHC Pump room	—	Handwritten note	Roof FHC (1)	195	
FL.8 FHC	195	/	Roof FHC (2)	195	
FL.7 corridor	100	/	FL.8 FHC 2801	195	
FL.7 FHC	195	/	FL.8 FHC 2821	195	
FL.6 corridor	100	/	FL.8 staff lift	100	
FL.6 FHC	195	/	FL.7 FHC 2701	195	
FL.5 corridor	100	/	FL.7 FHC 2721	195	
FL.5 FHC	195	/	FL.7 staff lift	100	
FL.4 corridor	100	/	FL.6 FHC 2601	195	
FL.4 FHC	CO2	/	FL.6 FHC 2621	195	
FL.3 corridor	100	/	FL.6 staff lift	100	
FL.3 FHC	195	/	FL.5 FHC 2501	195	
FL.2 corridor	100	/	FL.5 FHC 2521	195	
FL.2 FHC	CO2	/	FL.5 staff lift	100	
FL.G FHC security	195	/	FL.4 FHC 2401	195	
FL.G FHC restaurant	195	/	FL.4 FHC 2421	195	
FL.B1 FHC	195	/	FL.4 staff lift	100	
FL.B1 kitchen (1)	100	/	FL.3 FHC 2301	195	
FL.B1 kitchen (2)	100	/	FL.3 FHC 2321	195	
FL.B1 staff lift	100	/	FL.3 staff lift	100	
FL.B2 staff lift	100	/	FL.2 FHC 2201	195	
FL.B2 FHC	195	/	FL.2 FHC 2221	100	
FL.B2 FHC fire pump	195	/	FL.2 staff lift	100	
Generator room	CO2	/	FL.G FHC Lobby	195	
MDB Room	CO2	/	FHC front office	195	
MDB Room	CO2	/	FL.B1 FHC Car park	195 / 195	
			FL.B2 FHC Car park	195 / 195	

Checked By Supervisor		Date	2/6/24
Approve By Chief Engineer		Date	2/6/24