

ภาคผนวกที่ 18

---

เอกสารตรวจสอบระบบป้องกันอัคคีภัย  
ประจำเดือนมกราคม-มิถุนายน 2567

## Centara Korat Fire Emergency Light inspection Log

No	Date/Month/Year	Floor	Location	Battery	Power Button	Condition	Amount	Inspector	Remarks
1	7-Jan-24	Rooftop	EXHAUST FAN	Yes	Yes	In good condition	2	Mr.Phanuwat S	
2	7-Jan-24	Rooftop	FIRE EXIT STAIR ST 3-ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
3	7-Jan-24	Floor 21	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
4	7-Jan-24	Floor 20	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
5	7-Jan-24	Floor 20	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
6	7-Jan-24	Floor 20	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
7	7-Jan-24	Floor 20	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
8	7-Jan-24	Floor 20	MAN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
9	7-Jan-24	Floor 20	WOMEN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
10	7-Jan-24	Floor 20	STORAGE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
11	7-Jan-24	Floor 20	KITCHEN PICANTE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
12	7-Jan-24	Floor 19	PANTRY HK	Yes	Yes	In good condition	2	Mr.Phanuwat S	
13	7-Jan-24	Floor 19	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
14	7-Jan-24	Floor 19	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
15	7-Jan-24	Floor 19	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
16	7-Jan-24	Floor 19	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
17	7-Jan-24	Floor 19	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
18	7-Jan-24	Floor 18	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
19	7-Jan-24	Floor 18	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
20	7-Jan-24	Floor 18	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
21	7-Jan-24	Floor 18	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
22	7-Jan-24	Floor 17	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
23	7-Jan-24	Floor 17	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
24	7-Jan-24	Floor 17	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
25	7-Jan-24	Floor 17	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
26	7-Jan-24	Floor 16	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
27	7-Jan-24	Floor 16	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
28	7-Jan-24	Floor 16	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
29	7-Jan-24	Floor 16	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
30	7-Jan-24	Floor 15	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
31	7-Jan-24	Floor 15	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
32	7-Jan-24	Floor 15	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
33	7-Jan-24	Floor 15	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
34	7-Jan-24	Floor 14	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
35	7-Jan-24	Floor 14	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
36	7-Jan-24	Floor 14	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
37	7-Jan-24	Floor 14	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
38	7-Jan-24	Floor 12	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
39	7-Jan-24	Floor 12	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	

87	7-Jan-24	Floor 3	COORDINATOR STAFF	Yes	Yes	In good condition	4	Mr.Phanuwat S	
88	7-Jan-24	Floor 3	EE -ROOM IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
89	7-Jan-24	Floor 3	CDU IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
90	7-Jan-24	Floor 3	LINEN ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
91	7-Jan-24	Floor 3	CDU ROOM OUTSIDE	Yes	Yes	In good condition	2	Mr.Phanuwat S	
92	7-Jan-24	Floor 3	FEMALE LOCKER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
93	7-Jan-24	Floor 2	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
94	7-Jan-24	Floor 2	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
95	7-Jan-24	Floor 2	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
96	7-Jan-24	Floor 2	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
97	7-Jan-24	Floor 2	BACK OF BQ AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	
98	7-Jan-24	Floor G	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
99	7-Jan-24	Floor G	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
100	7-Jan-24	Floor G	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
101	7-Jan-24	Floor G	LOADING AREA	Yes	Yes	In good condition	1	Mr.Phanuwat S	
102	7-Jan-24	Floor G	RECEIVING	Yes	Yes	In good condition	1	Mr.Phanuwat S	
103	7-Jan-24	Floor G	CCTV CHECK POINT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
104	7-Jan-24	Floor G	MDB ROOM	Yes	Yes	In good condition	3	Mr.Phanuwat S	
105	7-Jan-24	Floor G	STORE FB	Yes	Yes	In good condition	1	Mr.Phanuwat S	
106	7-Jan-24	Floor G	STORE KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
107	7-Jan-24	Floor G	BUTCHER ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
108	7-Jan-24	Floor G	COLD KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
109	7-Jan-24	Floor G	MAIN KITCHEN	Yes	Yes	In good condition	4	Mr.Phanuwat S	
110	7-Jan-24	Floor G	SHOW KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	7-Jan-24	Floor G	WASHING ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
112	7-Jan-24	Floor G	DESERT CONNER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
113	7-Jan-24	Floor G	LUGGAGE ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	7-Jan-24	Basement floor	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
115	7-Jan-24	Basement floor	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
116	7-Jan-24	Basement floor	FIRE PUMP AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	
Total							133		

Checked By...

Position...

Date Checked ...

*Signature*  
Security Supervisor  
7/1/24

Acknowledge By...

Position...

Date Checked ...

*Signature*  
Security Manager  
9-1-24

## Centara Korat Fire Emergency Light inspection Log

No	Date/Month/Year	Floor	Location	Battery	Power Button	Condition	Amount	Inspector	Remarks
1	1-Feb-24	Rooftop	EXHAUST FAN	Yes	Yes	In good condition	2	Mr.Phanuwat S	
2	1-Feb-24	Rooftop	FIRE EXIT STAIR ST 3-ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
3	1-Feb-24	Floor 21	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
4	1-Feb-24	Floor 20	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
5	1-Feb-24	Floor 20	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
6	1-Feb-24	Floor 20	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
7	1-Feb-24	Floor 20	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
8	1-Feb-24	Floor 20	MAN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
9	1-Feb-24	Floor 20	WOMEN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
10	1-Feb-24	Floor 20	STORAGE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
11	1-Feb-24	Floor 20	KITCHEN PICANTE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
12	1-Feb-24	Floor 19	PANTRY HK	Yes	Yes	In good condition	2	Mr.Phanuwat S	
13	1-Feb-24	Floor 19	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
14	1-Feb-24	Floor 19	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
15	1-Feb-24	Floor 19	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
16	1-Feb-24	Floor 19	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
17	1-Feb-24	Floor 19	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
18	1-Feb-24	Floor 18	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
19	1-Feb-24	Floor 18	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
20	1-Feb-24	Floor 18	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
21	1-Feb-24	Floor 18	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
22	1-Feb-24	Floor 17	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
23	1-Feb-24	Floor 17	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
24	1-Feb-24	Floor 17	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
25	1-Feb-24	Floor 17	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
26	1-Feb-24	Floor 16	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
27	1-Feb-24	Floor 16	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
28	1-Feb-24	Floor 16	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
29	1-Feb-24	Floor 16	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
30	1-Feb-24	Floor 15	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
31	1-Feb-24	Floor 15	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
32	1-Feb-24	Floor 15	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
33	1-Feb-24	Floor 15	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
34	1-Feb-24	Floor 14	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
35	1-Feb-24	Floor 14	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
36	1-Feb-24	Floor 14	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
37	1-Feb-24	Floor 14	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
38	1-Feb-24	Floor 12	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
39	1-Feb-24	Floor 12	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	

87	1-Feb-24	Floor 3	COORIDOR STAFF	Yes	Yes	In good condition	4	Mr.Phanuwat S	
88	1-Feb-24	Floor 3	EE -ROOM IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
89	1-Feb-24	Floor 3	CDU IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
90	1-Feb-24	Floor 3	LINEN ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
91	1-Feb-24	Floor 3	CDU ROOM OUTSIDE	Yes	Yes	In good condition	2	Mr.Phanuwat S	
92	1-Feb-24	Floor 3	FEMAIL LOCKER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
93	1-Feb-24	Floor 2	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
94	1-Feb-24	Floor 2	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
95	1-Feb-24	Floor 2	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
96	1-Feb-24	Floor 2	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
97	1-Feb-24	Floor 2	BACK OF BQ AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	
98	1-Feb-24	Floor G	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
99	1-Feb-24	Floor G	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
100	1-Feb-24	Floor G	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
101	1-Feb-24	Floor G	LOADING ATREA	Yes	Yes	In good condition	1	Mr.Phanuwat S	
102	1-Feb-24	Floor G	RECCRIVEING	Yes	Yes	In good condition	1	Mr.Phanuwat S	
103	1-Feb-24	Floor G	CCTV CHECK POINT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
104	1-Feb-24	Floor G	MDB ROOM	Yes	Yes	In good condition	3	Mr.Phanuwat S	
105	1-Feb-24	Floor G	STORE FB	Yes	Yes	In good condition	1	Mr.Phanuwat S	
106	1-Feb-24	Floor G	STORE KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
107	1-Feb-24	Floor G	BHUTCHER ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
108	1-Feb-24	Floor G	COLD KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
109	1-Feb-24	Floor G	MAIN KITCHEN	Yes	Yes	In good condition	4	Mr.Phanuwat S	
110	1-Feb-24	Floor G	SHOW KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	1-Feb-24	Floor G	WAHSING ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
112	1-Feb-24	Floor G	DESERT CONNER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
113	1-Feb-24	Floor G	LUGGAGE ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	1-Feb-24	Basement floor	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
115	1-Feb-24	Basement floor	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
116	1-Feb-24	Basement floor	FIRE PUMB AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	
Total							133		

Checked By...

Position...

Date Checked .....

*Signature*  
*Security Supervisor*  
*1/2/24*

Acknowledge By...

Position.....

Date Checked .....

*Signature*  
*Security Manager*  
*1-2-24*

## Centara Korat Fire Emergency Light inspection Log

No	Date/Month/Year	Floor	Location	Battery	Power Button	Condition	Amount	Inspector	Remarks
1	3-Mar-24	Rooftop	EXHAUST FAN	Yes	Yes	In good condition	2	Mr.Phanuwat S	
2	3-Mar-24	Rooftop	FIRE EXIT STAIR ST 3-ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
3	3-Mar-24	Floor 21	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
4	3-Mar-24	Floor 20	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
5	3-Mar-24	Floor 20	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
6	3-Mar-24	Floor 20	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
7	3-Mar-24	Floor 20	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
8	3-Mar-24	Floor 20	MAN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
9	3-Mar-24	Floor 20	WOMEN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
10	3-Mar-24	Floor 20	STORAGE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
11	3-Mar-24	Floor 20	KITCHEN PICANTE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
12	3-Mar-24	Floor 19	PANTRY HK	Yes	Yes	In good condition	2	Mr.Phanuwat S	
13	3-Mar-24	Floor 19	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
14	3-Mar-24	Floor 19	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
15	3-Mar-24	Floor 19	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
16	3-Mar-24	Floor 19	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
17	3-Mar-24	Floor 19	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
18	3-Mar-24	Floor 18	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
19	3-Mar-24	Floor 18	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
20	3-Mar-24	Floor 18	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
21	3-Mar-24	Floor 18	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
22	3-Mar-24	Floor 17	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
23	3-Mar-24	Floor 17	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
24	3-Mar-24	Floor 17	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
25	3-Mar-24	Floor 17	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
26	3-Mar-24	Floor 16	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
27	3-Mar-24	Floor 16	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
28	3-Mar-24	Floor 16	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
29	3-Mar-24	Floor 16	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
30	3-Mar-24	Floor 15	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
31	3-Mar-24	Floor 15	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
32	3-Mar-24	Floor 15	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
33	3-Mar-24	Floor 15	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
34	3-Mar-24	Floor 14	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
35	3-Mar-24	Floor 14	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
36	3-Mar-24	Floor 14	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
37	3-Mar-24	Floor 14	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
38	3-Mar-24	Floor 12	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
39	3-Mar-24	Floor 12	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	

87	3-Mar-24	Floor 3	COORIDOR STAFF	Yes	Yes	In good condition	4	Mr.Phanuwat S	
88	3-Mar-24	Floor 3	EE -ROOM IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
89	3-Mar-24	Floor 3	CDU IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
90	3-Mar-24	Floor 3	LINEN ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
91	3-Mar-24	Floor 3	CDU ROOM OUTSIDE	Yes	Yes	In good condition	2	Mr.Phanuwat S	
92	3-Mar-24	Floor 3	FEMAIL LOCKER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
93	3-Mar-24	Floor 2	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
94	3-Mar-24	Floor 2	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
95	3-Mar-24	Floor 2	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
96	3-Mar-24	Floor 2	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
97	3-Mar-24	Floor 2	BACK OF BQ AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	
98	3-Mar-24	Floor G	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
99	3-Mar-24	Floor G	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
100	3-Mar-24	Floor G	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
101	3-Mar-24	Floor G	LOADING ATREA	Yes	Yes	In good condition	1	Mr.Phanuwat S	
102	3-Mar-24	Floor G	RECCRIVEING	Yes	Yes	In good condition	1	Mr.Phanuwat S	
103	3-Mar-24	Floor G	CCTV CHECK POINT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
104	3-Mar-24	Floor G	MDB ROOM	Yes	Yes	In good condition	3	Mr.Phanuwat S	
105	3-Mar-24	Floor G	STORE FB	Yes	Yes	In good condition	1	Mr.Phanuwat S	
106	3-Mar-24	Floor G	STORE KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
107	3-Mar-24	Floor G	BHUTCHER ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
108	3-Mar-24	Floor G	COLD KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
109	3-Mar-24	Floor G	MAIN KITCHEN	Yes	Yes	In good condition	4	Mr.Phanuwat S	
110	3-Mar-24	Floor G	SHOW KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	3-Mar-24	Floor G	WAHSING ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
112	3-Mar-24	Floor G	DESERT CONNER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
113	3-Mar-24	Floor G	LUGGAGE ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	3-Mar-24	Basement floor	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
115	3-Mar-24	Basement floor	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
116	3-Mar-24	Basement floor	FIRE PUMB AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	
Total							133		

Checked By... *Mr. J. J. J.*  
 Position... *Security Supervisor*  
 Date Checked... *3-Mar-2024*

Acknowledge By... *Mr. J. J. J.*  
 Position... *Security Manager*  
 Date Checked... *3-Mar-2024*

## Centara Korat Fire Emergency Light inspection Log

No	Date/Month/Year	Floor	Location	Battery	Power Button	Condition	Amount	Inspector	Remarks
1	4-Apr-24	Rooftop	EXHAUST FAN	Yes	Yes	In good condition	2	Mr.Phanuwat S	
2	4-Apr-24	Rooftop	FIRE EXIT STAIR ST 3-ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
3	4-Apr-24	Floor 21	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
4	4-Apr-24	Floor 20	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
5	4-Apr-24	Floor 20	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
6	4-Apr-24	Floor 20	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
7	4-Apr-24	Floor 20	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
8	4-Apr-24	Floor 20	MAN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
9	4-Apr-24	Floor 20	WOMEN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
10	4-Apr-24	Floor 20	STORAGE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
11	4-Apr-24	Floor 20	KITCHEN PICANTE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
12	4-Apr-24	Floor 19	PANTRY HK	Yes	Yes	In good condition	2	Mr.Phanuwat S	
13	4-Apr-24	Floor 19	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
14	4-Apr-24	Floor 19	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
15	4-Apr-24	Floor 19	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
16	4-Apr-24	Floor 19	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
17	4-Apr-24	Floor 19	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
18	4-Apr-24	Floor 18	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
19	4-Apr-24	Floor 18	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
20	4-Apr-24	Floor 18	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
21	4-Apr-24	Floor 18	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
22	4-Apr-24	Floor 17	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
23	4-Apr-24	Floor 17	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
24	4-Apr-24	Floor 17	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
25	4-Apr-24	Floor 17	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
26	4-Apr-24	Floor 16	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
27	4-Apr-24	Floor 16	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
28	4-Apr-24	Floor 16	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
29	4-Apr-24	Floor 16	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
30	4-Apr-24	Floor 15	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
31	4-Apr-24	Floor 15	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
32	4-Apr-24	Floor 15	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
33	4-Apr-24	Floor 15	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
34	4-Apr-24	Floor 14	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
35	4-Apr-24	Floor 14	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
36	4-Apr-24	Floor 14	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
37	4-Apr-24	Floor 14	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
38	4-Apr-24	Floor 12	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	



86	4-Apr-24	Floor 3	WASHING ROOM CANTEEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
87	4-Apr-24	Floor 3	COORIDOR STAFF	Yes	Yes	In good condition	4	Mr.Phanuwat S	
88	4-Apr-24	Floor 3	EE -ROOM IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
89	4-Apr-24	Floor 3	CDU IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
90	4-Apr-24	Floor 3	LINEN ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
91	4-Apr-24	Floor 3	CDU ROOM OUTSIDE	Yes	Yes	In good condition	2	Mr.Phanuwat S	
92	4-Apr-24	Floor 3	FEMAIL LOCKER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
93	4-Apr-24	Floor 2	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
94	4-Apr-24	Floor 2	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
95	4-Apr-24	Floor 2	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
96	4-Apr-24	Floor 2	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
97	4-Apr-24	Floor 2	BACK OF BQ AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	
98	4-Apr-24	Floor G	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
99	4-Apr-24	Floor G	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
100	4-Apr-24	Floor G	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
101	4-Apr-24	Floor G	LOADING ATREA	Yes	Yes	In good condition	1	Mr.Phanuwat S	
102	4-Apr-24	Floor G	RECCRIVEING	Yes	Yes	In good condition	1	Mr.Phanuwat S	
103	4-Apr-24	Floor G	CCTV CHECK POINT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
104	4-Apr-24	Floor G	MDB ROOM	Yes	Yes	In good condition	3	Mr.Phanuwat S	
105	4-Apr-24	Floor G	STORE FB	Yes	Yes	In good condition	1	Mr.Phanuwat S	
106	4-Apr-24	Floor G	STORE KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
107	4-Apr-24	Floor G	BHUTCHER ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
108	4-Apr-24	Floor G	COLD KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
109	4-Apr-24	Floor G	MAIN KITCHEN	Yes	Yes	In good condition	4	Mr.Phanuwat S	
110	4-Apr-24	Floor G	SHOW KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	4-Apr-24	Floor G	WAHSING ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
112	4-Apr-24	Floor G	DESERT CONNER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
113	4-Apr-24	Floor G	LUGGAGE ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	4-Apr-24	Basement floor	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
115	4-Apr-24	Basement floor	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
116	4-Apr-24	Basement floor	FIRE PUMB AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	
Total							133		

Checked By.....  
 Position.....  
 Date Checked.....

Acknowledge By.....  
 Position.....  
 Date Checked.....

## Centara Korat Fire Emergency Light inspection Log

No	Date/Month/Year	Floor	Location	Battery	Power Button	Condition	Amount	Inspector	Remarks
1	1-May-24	Rooftop	EXUAST FAN	Yes	Yes	In good condition	2	Mr.Phanuwat S	
2	1-May-24	Rooftop	FIRE EXIT STAIR ST 3-ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
3	1-May-24	Floor 21	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
4	1-May-24	Floor 20	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
5	1-May-24	Floor 20	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
6	1-May-24	Floor 20	FIRE EXIT STAIR ST 1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
7	1-May-24	Floor 20	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
8	1-May-24	Floor 20	MAN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
9	1-May-24	Floor 20	WOMEN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
10	1-May-24	Floor 20	STORAGE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
11	1-May-24	Floor 20	KITCHEN PICANTE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
12	1-May-24	Floor 19	PANTRY HK	Yes	Yes	In good condition	2	Mr.Phanuwat S	
13	1-May-24	Floor 19	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
14	1-May-24	Floor 19	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
15	1-May-24	Floor 19	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
16	1-May-24	Floor 19	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
17	1-May-24	Floor 19	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
18	1-May-24	Floor 18	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
19	1-May-24	Floor 18	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
20	1-May-24	Floor 18	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
21	1-May-24	Floor 18	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
22	1-May-24	Floor 17	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
23	1-May-24	Floor 17	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
24	1-May-24	Floor 17	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
25	1-May-24	Floor 17	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
26	1-May-24	Floor 16	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
27	1-May-24	Floor 16	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
28	1-May-24	Floor 16	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
29	1-May-24	Floor 16	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
30	1-May-24	Floor 15	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
31	1-May-24	Floor 15	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
32	1-May-24	Floor 15	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
33	1-May-24	Floor 15	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
34	1-May-24	Floor 14	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
35	1-May-24	Floor 14	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
36	1-May-24	Floor 14	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
37	1-May-24	Floor 14	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
38	1-May-24	Floor 12	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	

86	1-May-24	Floor 3	WASHING ROOM CANTEEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
87	1-May-24	Floor 3	COORIDOR STAFF	Yes	Yes	In good condition	4	Mr.Phanuwat S	
88	1-May-24	Floor 3	EE -ROOM IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
89	1-May-24	Floor 3	CDU IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
90	1-May-24	Floor 3	LINEN ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
91	1-May-24	Floor 3	CDU ROOM OUTSIDE	Yes	Yes	In good condition	2	Mr.Phanuwat S	
92	1-May-24	Floor 3	FEMAIL LOCKER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
93	1-May-24	Floor 2	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
94	1-May-24	Floor 2	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
95	1-May-24	Floor 2	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
96	1-May-24	Floor 2	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
97	1-May-24	Floor 2	BACK OF BQ AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	
98	1-May-24	Floor G	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
99	1-May-24	Floor G	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
100	1-May-24	Floor G	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
101	1-May-24	Floor G	LOADING ATREA	Yes	Yes	In good condition	1	Mr.Phanuwat S	
102	1-May-24	Floor G	RECCRIEING	Yes	Yes	In good condition	1	Mr.Phanuwat S	
103	1-May-24	Floor G	CCTV CHECK POINT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
104	1-May-24	Floor G	MDB ROOM	Yes	Yes	In good condition	3	Mr.Phanuwat S	
105	1-May-24	Floor G	STORE FB	Yes	Yes	In good condition	1	Mr.Phanuwat S	
106	1-May-24	Floor G	STORE KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
107	1-May-24	Floor G	BHUTCHER ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
108	1-May-24	Floor G	COLD KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
109	1-May-24	Floor G	MAIN KITCHEN	Yes	Yes	In good condition	4	Mr.Phanuwat S	
110	1-May-24	Floor G	SHOW KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	1-May-24	Floor G	WAHSING ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
112	1-May-24	Floor G	DESERT CONNER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
113	1-May-24	Floor G	LUGGAGE ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	1-May-24	Basement floor	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
115	1-May-24	Basement floor	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
116	1-May-24	Basement floor	FIRE PUMB AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	
Total							133		

Checked By... 265016 11610E  
 Position... Security Supervisor  
 Date Checked... 1-May-2024

Acknowledge By... [Signature]  
 Position... Security Manager  
 Date Checked... 1-May-2024

## Centara Korat Fire Emergency Light inspection Log

No	Date/Month/Year	Floor	Location	Battery	Power Button	Condition	Amount	Inspector	Remarks
1	1/6/2024	Rooftop	EXHAUST FAN	Yes	Yes	In good condition	2	Mr.Phanuwat S	
2	1/6/2024	Rooftop	FIRE EXIT STAIR ST 3-ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
3	1/6/2024	Floor 21	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
4	1/6/2024	Floor 20	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
5	1/6/2024	Floor 20	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
6	1/6/2024	Floor 20	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
7	1/6/2024	Floor 20	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
8	1/6/2024	Floor 20	MAN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
9	1/6/2024	Floor 20	WOMEN TOILET	Yes	Yes	In good condition	1	Mr.Phanuwat S	
10	1/6/2024	Floor 20	STORAGE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
11	1/6/2024	Floor 20	KITCHEN PICANTE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
12	1/6/2024	Floor 19	PANTRY HK	Yes	Yes	In good condition	2	Mr.Phanuwat S	
13	1/6/2024	Floor 19	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
14	1/6/2024	Floor 19	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
15	1/6/2024	Floor 19	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
16	1/6/2024	Floor 19	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
17	1/6/2024	Floor 19	FIRE EXIT STAIR ST3	Yes	Yes	In good condition	1	Mr.Phanuwat S	
18	1/6/2024	Floor 18	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
19	1/6/2024	Floor 18	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
20	1/6/2024	Floor 18	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
21	1/6/2024	Floor 18	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
22	1/6/2024	Floor 17	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
23	1/6/2024	Floor 17	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
24	1/6/2024	Floor 17	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
25	1/6/2024	Floor 17	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
26	1/6/2024	Floor 16	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
27	1/6/2024	Floor 16	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
28	1/6/2024	Floor 16	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
29	1/6/2024	Floor 16	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
30	1/6/2024	Floor 15	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
31	1/6/2024	Floor 15	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
32	1/6/2024	Floor 15	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
33	1/6/2024	Floor 15	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
34	1/6/2024	Floor 14	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
35	1/6/2024	Floor 14	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
36	1/6/2024	Floor 14	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
37	1/6/2024	Floor 14	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
38	1/6/2024	Floor 12	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
39	1/6/2024	Floor 12	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
40	1/6/2024	Floor 12	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
41	1/6/2024	Floor 12	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
42	1/6/2024	Floor 11	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
43	1/6/2024	Floor 11	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
44	1/6/2024	Floor 11	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	

45	1/6/2024	Floor 11	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
46	1/6/2024	Floor 10	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
47	1/6/2024	Floor 10	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
48	1/6/2024	Floor 10	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
49	1/6/2024	Floor 10	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
50	1/6/2024	Floor 9	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
51	1/6/2024	Floor 9	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
52	1/6/2024	Floor 9	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
53	1/6/2024	Floor 9	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
54	1/6/2024	Floor 8	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
55	1/6/2024	Floor 8	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
56	1/6/2024	Floor 8	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
57	1/6/2024	Floor 8	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
58	1/6/2024	Floor 7	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
59	1/6/2024	Floor 7	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
60	1/6/2024	Floor 7	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
61	1/6/2024	Floor 7	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
62	1/6/2024	Floor 6	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
63	1/6/2024	Floor 6	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
64	1/6/2024	Floor 6	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
65	1/6/2024	Floor 6	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
66	1/6/2024	Floor 5	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
67	1/6/2024	Floor 5	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
68	1/6/2024	Floor 5	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
69	1/6/2024	Floor 5	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
70	1/6/2024	Floor 4	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
71	1/6/2024	Floor 4	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
72	1/6/2024	Floor 4	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
73	1/6/2024	Floor 4	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
74	1/6/2024	Floor 3	EE-ROOM	Yes	Yes	In good condition	2	Mr.Phanuwat S	
75	1/6/2024	Floor 3	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
76	1/6/2024	Floor 3	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
77	1/6/2024	Floor 3	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
78	1/6/2024	Floor 3	ENGINEERING ROOM	Yes	Yes	In good condition	3	Mr.Phanuwat S	
79	1/6/2024	Floor 3	HK OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
80	1/6/2024	Floor 3	AC STORAGE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
81	1/6/2024	Floor 3	UNIFORM ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
82	1/6/2024	Floor 3	MAN LOCKER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
83	1/6/2024	Floor 3	CCTV ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
84	1/6/2024	Floor 3	FRIST AID ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
85	1/6/2024	Floor 3	CANTEEN ROOM	Yes	Yes	In good condition	2	Mr.Phanuwat S	
86	1/6/2024	Floor 3	WASHING ROOM CANTEEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
87	1/6/2024	Floor 3	COORDINATOR STAFF	Yes	Yes	In good condition	4	Mr.Phanuwat S	
88	1/6/2024	Floor 3	EE -ROOM IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
89	1/6/2024	Floor 3	CDU IN OFFICE	Yes	Yes	In good condition	1	Mr.Phanuwat S	
90	1/6/2024	Floor 3	LINEN ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
91	1/6/2024	Floor 3	CDU ROOM OUTSIDE	Yes	Yes	In good condition	2	Mr.Phanuwat S	
92	1/6/2024	Floor 3	FEMALE LOCKER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
93	1/6/2024	Floor 2	EE-ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
94	1/6/2024	Floor 2	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
95	1/6/2024	Floor 2	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
96	1/6/2024	Floor 2	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
97	1/6/2024	Floor 2	BACK OF BQ AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	

98	1/6/2024	Floor G	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
99	1/6/2024	Floor G	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
100	1/6/2024	Floor G	FIRE EXIT STAIR ST2	Yes	Yes	In good condition	1	Mr.Phanuwat S	
101	1/6/2024	Floor G	LOADING ATREA	Yes	Yes	In good condition	1	Mr.Phanuwat S	
102	1/6/2024	Floor G	RECCRIVEING	Yes	Yes	In good condition	1	Mr.Phanuwat S	
103	1/6/2024	Floor G	CCTV CHECK POINT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
104	1/6/2024	Floor G	MDB ROOM	Yes	Yes	In good condition	3	Mr.Phanuwat S	
105	1/6/2024	Floor G	STORE FB	Yes	Yes	In good condition	1	Mr.Phanuwat S	
106	1/6/2024	Floor G	STORE KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
107	1/6/2024	Floor G	BHUTCHER ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
108	1/6/2024	Floor G	COLD KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
109	1/6/2024	Floor G	MAIN KITCHEN	Yes	Yes	In good condition	4	Mr.Phanuwat S	
110	1/6/2024	Floor G	SHOW KITCHEN	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	1/6/2024	Floor G	WAHSING ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
112	1/6/2024	Floor G	DESERT CONNER	Yes	Yes	In good condition	1	Mr.Phanuwat S	
113	1/6/2024	Floor G	LUGGAGE ROOM	Yes	Yes	In good condition	1	Mr.Phanuwat S	
111	1/6/2024	Basement floor	IN FRONT OF FIRE MAN LIFT	Yes	Yes	In good condition	1	Mr.Phanuwat S	
115	1/6/2024	Basement floor	FIRE EXIT STAIR ST1	Yes	Yes	In good condition	1	Mr.Phanuwat S	
116	1/6/2024	Basement floor	FIRE PUMB AREA	Yes	Yes	In good condition	2	Mr.Phanuwat S	
						Total	133		

Checked By.....

Position.....

Date Checked .....

Acknowledge By.....

Position.....

Date Checked .....

ภาคผนวกที่ 19

---

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

## รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : บริษัท ซีพีเอ็น เอสเตท จำกัด

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 880

หมู่ที่ :

ซอย :

ถนน : มิตรภาพ-หนองคาย

แขวง/ตำบล : ในเมือง

เขต/ตำบล : เมืองนครราชสีมา

จังหวัด : นครราชสีมา

โทรศัพท์ : 044-251234

โทรสาร : 044251279

มี : บริษัท ซีพีเอ็น เอสเตท จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 218

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 109/2565

ออกให้โดย :

หมดอายุ : 06/09/2570

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน มกราคม พ.ศ. 2567  
ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายสมฤกษ์ อริยศิริกุล เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ \_\_\_\_\_ ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ \_\_\_\_\_ หมดอายุ \_\_\_\_\_

ออกให้โดย \_\_\_\_\_

ลงชื่อ \_\_\_\_\_ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ \_\_\_\_\_ หมดอายุ \_\_\_\_\_

ออกให้โดย \_\_\_\_\_

### 2. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

1. ระบบบำบัดน้ำเสียแบบแอกทิเวเตดสลัดจ์ (Activated Sludge Process)

210.00 ลบ.ม./วัน

(2) การทำงานของระบบบำบัดน้ำเสีย

[ X ] แบบต่อเนื่อง ชั่วโมง/วัน

[ ] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[ X ] เครื่องสูบน้ำ

[ X ] ระบบเติมอากาศ

[ ] เครื่องกวน/ผสมน้ำเสีย

[ ] เครื่องกวน/ผสมสารเคมี

[ X ] เครื่องสูบลำโพง

[ ] อื่นๆ

[ ] อื่นๆ

[ ] อื่นๆ



(4) แหล่งรองรับน้ำทิ้ง (ระบุ) น้ำที่บำบัดแล้วระบายทิ้งคลองสาธารณะ

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

(1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 12,325.000 หน่วย

(2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 4,761.000 ลบ.ม.

(3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 3,808.800 ลบ.ม.

(4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย [ X ] ระบายทุกวัน  
[ ] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน  
[ ] ไม่ระบายเลย

(5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย  
1. 0.000 กิโลกรัม

(6) การทำงานของระบบบำบัดน้ำเสีย

ระบบบำบัดน้ำเสีย [ X ] ปกติ [ ] ผิดปกติ

เครื่องสูบน้ำ [ X ] ปกติ [ ] ผิดปกติ

ระบบเติมอากาศ [ X ] ปกติ [ ] ผิดปกติ

เครื่องสูบตะกอน [ X ] ปกติ [ ] ผิดปกติ

(7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม

(8) ปัญหา อุปสรรค และแนวทางแก้ไข

คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง ให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖

๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

## รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : บริษัท ซีพีเอ็น เอสเตท จำกัด

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 880

หมู่ที่ :

ซอย :

ถนน : มิตรภาพ-หนองคาย

แขวง/ตำบล : ในเมือง

เขต/ตำบล : เมืองนครราชสีมา

จังหวัด : นครราชสีมา

โทรศัพท์ : 044-251234

โทรสาร : 044251279

มี : บริษัท ซีพีเอ็น เอสเตท จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 218

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 109/2565

ออกให้โดย :

หมดอายุ : 06/09/2570

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน กุมภาพันธ์ พ.ศ. 2567  
ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายสมฤกษ์ อริญหิรัญ เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ \_\_\_\_\_ ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ \_\_\_\_\_ หมดอายุ \_\_\_\_\_

ออกให้โดย \_\_\_\_\_

ลงชื่อ \_\_\_\_\_ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ \_\_\_\_\_ หมดอายุ \_\_\_\_\_

ออกให้โดย \_\_\_\_\_

### 2. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

1. ระบบบำบัดน้ำเสียแบบแอกทิเวเตดสลัดจ์ (Activated Sludge Process)

210.00 ลบ.ม./วัน

(2) การทำงานของระบบบำบัดน้ำเสีย

[ X ] แบบต่อเนื่อง ชั่วโมง/วัน

[ ] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[ X ] เครื่องสูบน้ำ

[ X ] ระบบเติมอากาศ

[ ] เครื่องกวน/ผสมน้ำเสีย

[ ] เครื่องกวน/ผสมสารเคมี

[ X ] เครื่องสูบลำโพง

[ ] อื่นๆ

[ ] อื่นๆ

[ ] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ) น้ำที่บำบัดแล้วระบายทิ้งคลองสาธารณะ

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

(1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 11,589.900 หน่วย

(2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 4,208.000 ลบ.ม.

(3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 3,366.400 ลบ.ม.

(4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย [ X ] ระบายทุกวัน  
[ ] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน  
[ ] ไม่ระบายเลย

(5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย  
1. 0.000 กิโลกรัม

(6) การทำงานของระบบบำบัดน้ำเสีย

ระบบบำบัดน้ำเสีย [ X ] ปกติ [ ] ผิดปกติ

เครื่องสูบน้ำ [ X ] ปกติ [ ] ผิดปกติ

ระบบเติมอากาศ [ X ] ปกติ [ ] ผิดปกติ

เครื่องสูบตะกอน [ X ] ปกติ [ ] ผิดปกติ

(7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม

(8) ปัญหา อุปสรรค และแนวทางแก้ไข

คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง

ให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน

ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท

หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖

๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน

โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกิน

หนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

## รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : บริษัท ซีพีเอ็น เอสเตท จำกัด

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 880

หมู่ที่ :

ซอย :

ถนน : มิตรภาพ-หนองคาย

แขวง/ตำบล : ในเมือง

เขต/ตำบล : เมืองนครราชสีมา

จังหวัด : นครราชสีมา

โทรศัพท์ : 044-251234

โทรสาร : 044251279

มี : บริษัท ซีพีเอ็น เอสเตท จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 218

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 109/2565

ออกให้โดย :

หมดอายุ : 06/09/2570

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน มีนาคม พ.ศ. 2567  
ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นาย สมฤกษ์ อริยศิริกุล เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ \_\_\_\_\_ ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ \_\_\_\_\_ หมดอายุ \_\_\_\_\_

ออกให้โดย \_\_\_\_\_

ลงชื่อ \_\_\_\_\_ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ \_\_\_\_\_ หมดอายุ \_\_\_\_\_

ออกให้โดย \_\_\_\_\_

### 2. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

1. ระบบบำบัดน้ำเสียแบบแอกทิเวเตดสลัดจ์ (Activated Sludge Process)

210.00 ลบ.ม./วัน

(2) การทำงานของระบบบำบัดน้ำเสีย

[ X ] แบบต่อเนื่อง ชั่วโมง/วัน

[ ] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[ X ] เครื่องสูบน้ำ

[ X ] ระบบเติมอากาศ

[ ] เครื่องกวน/ผสมน้ำเสีย

[ ] เครื่องกวน/ผสมสารเคมี

[ X ] เครื่องสูบลำโพง

[ ] อื่นๆ

[ ] อื่นๆ

[ ] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ) น้ำที่บำบัดแล้วระบายทิ้งคลองสาธารณะ

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

(1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 12,253.200 หน่วย

(2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 4,997.000 ลบ.ม.

(3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 3,997.600 ลบ.ม.

(4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย [ X ] ระบายทุกวัน  
[ ] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน  
[ ] ไม่ระบายเลย

(5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย  
1. 0.000 กิโลกรัม

(6) การทำงานของระบบบำบัดน้ำเสีย

ระบบบำบัดน้ำเสีย [ X ] ปกติ [ ] ผิดปกติ

เครื่องสูบน้ำ [ X ] ปกติ [ ] ผิดปกติ

ระบบเติมอากาศ [ X ] ปกติ [ ] ผิดปกติ

เครื่องสูบตะกอน [ X ] ปกติ [ ] ผิดปกติ

(7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม

(8) ปัญหา อุปสรรค และแนวทางแก้ไข

คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง

ให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน

ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท

หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖

๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน

โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกิน

หนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

## รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : บริษัท ซีพีเอ็น เอสเตท จำกัด

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 880

หมู่ที่ :

ซอย :

ถนน : มิตรภาพ-หนองคาย

แขวง/ตำบล : ในเมือง

เขต/ตำบล : เมืองนครราชสีมา

จังหวัด : นครราชสีมา

โทรศัพท์ : 044-251234

โทรสาร : 044251279

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป

จำนวนห้อง : 218

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 109/2565

ออกให้โดย :

หมดอายุ : 06/09/2570

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน เมษายน พ.ศ. 2567  
ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายสมฤกษ์ อริยศิริกุล เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ \_\_\_\_\_ ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ \_\_\_\_\_ หมดอายุ \_\_\_\_\_

ออกให้โดย \_\_\_\_\_

ลงชื่อ \_\_\_\_\_ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ \_\_\_\_\_ หมดอายุ \_\_\_\_\_

ออกให้โดย \_\_\_\_\_

### 2. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

1. ระบบบำบัดน้ำเสียแบบแอกทิเวเตดสลัดจ์ (Activated Sludge Process)

ความสามารถในการบำบัดน้ำเสีย

210.00 ลบ.ม./วัน

(2) การทำงานของระบบบำบัดน้ำเสีย

[ X ] แบบต่อเนื่อง ชั่วโมง/วัน

[ ] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[ X ] เครื่องสูบน้ำ

[ X ] ระบบเติมอากาศ

[ ] เครื่องกวน/ผสมน้ำเสีย

[ ] เครื่องกวน/ผสมสารเคมี

[ X ] เครื่องสูบละกอน

[ ] อื่นๆ

[ ] อื่นๆ

[ ] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ) น้ำที่บำบัดแล้วระบายทิ้งคลองสาธารณะ

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

(1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 11,765.900 หน่วย

(2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 5,032.000 ลบ.ม.

(3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 4,025.600 ลบ.ม.

(4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย [ X ] ระบายทุกวัน  
[ ] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน  
[ ] ไม่ระบายเลย

(5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย  
1. 0.000 กิโลกรัม

(6) การทำงานของระบบบำบัดน้ำเสีย

ระบบบำบัดน้ำเสีย [ X ] ปกติ [ ] ผิดปกติ

เครื่องสูบน้ำ [ X ] ปกติ [ ] ผิดปกติ

ระบบเติมอากาศ [ X ] ปกติ [ ] ผิดปกติ

เครื่องสูบตะกอน [ X ] ปกติ [ ] ผิดปกติ

(7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม

(8) ปัญหา อุปสรรค และแนวทางแก้ไข

คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง

ให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน

ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท

หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖

๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน

โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกิน

หนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

## รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : บริษัท ซีพีเอ็น เอสเตท จำกัด

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 880

หมู่ที่ :

ซอย :

ถนน : มิตรภาพ-หนองคาย

แขวง/ตำบล : ในเมือง

เขต/ตำบล : เมืองนครราชสีมา

จังหวัด : นครราชสีมา

โทรศัพท์ : 044-251234

โทรสาร : 044251279

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป

จำนวนห้อง : 218

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 109/2565

ออกให้โดย :

หมดอายุ : 06/09/2570

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน พฤษภาคม พ.ศ. 2567 ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายสมฤกษ์ อริญหิรัญ เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ \_\_\_\_\_ ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ \_\_\_\_\_ หมดอายุ \_\_\_\_\_

ออกให้โดย \_\_\_\_\_

ลงชื่อ \_\_\_\_\_ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ \_\_\_\_\_ หมดอายุ \_\_\_\_\_

ออกให้โดย \_\_\_\_\_

### 2. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

1. ระบบบำบัดน้ำเสียแบบแอกทิเวเตดสลัดจ์ (Activated Sludge Process)

ความสามารถในการบำบัดน้ำเสีย

210.00 ลบ.ม./วัน

(2) การทำงานของระบบบำบัดน้ำเสีย

[ X ] แบบต่อเนื่อง ชั่วโมง/วัน

[ ] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[ X ] เครื่องสูบน้ำ

[ X ] ระบบเติมอากาศ

[ ] เครื่องกวน/ผสมน้ำเสีย

[ ] เครื่องกวน/ผสมสารเคมี

[ X ] เครื่องสูบละกอน

[ ] อื่นๆ

[ ] อื่นๆ

[ ] อื่นๆ



- (4) แหล่งรองรับน้ำทิ้ง (ระบุ) น้ำที่บำบัดแล้วทิ้งคลองสาธารณะ
- (5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด

### 3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 12,160.500 หน่วย
- (2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 4,973.000 ลบ.ม.
- (3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 3,978.400 ลบ.ม.
- (4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย
- [ X ] ระบายทุกวัน
- [ ] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน
- [ ] ไม่ระบายเลย
- (5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย
1. 0.000 กิโลกรัม
- (6) การทำงานของระบบบำบัดน้ำเสีย
- ระบบบำบัดน้ำเสีย [ X ] ปกติ [ ] ผิดปกติ
- เครื่องสูบน้ำ [ X ] ปกติ [ ] ผิดปกติ
- ระบบเติมอากาศ [ X ] ปกติ [ ] ผิดปกติ
- เครื่องสูบตะกอน [ X ] ปกติ [ ] ผิดปกติ
- (7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม
- (8) ปัญหา อุปสรรค และแนวทางแก้ไข

- คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง ให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗