

---

การตรวจสอบสถานที่เก็บรักษาวัตถุอันตราย และรายงานการเก็บรักษาวัตถุประจำปีตามรอบกฎหมาย

**ประเภทเอกสาร**

บัญชี คัดทำ รายการ เบ็ดเสร็จ จำนวน

---

**เลขประจำตัวผู้เสียภาษี**

3038899970

---

**สถานที่ให้บริการหรือผู้รับบริการ**

เขตที่ 0	หมู่ ๓	ตำบล -
ถนน เลี้ยวตรงจากวัด-1	แขวงบ้านหลวง	เขต/อำเภอ เมืองพะเยา
จังหวัด พะเยา	รหัสไปรษณีย์ 21150	โทรศัพท์ 030-974-800
โทรศัพท์ 030-974-801	E-mail chusaka@gttac.com	
เลขทะเบียนโรงงาน 72140000125915	สิทธิ์ GPS	

---

**สถานะให้บริการ:** ☒ เป็นของหน่วยงาน  
☐ เป็นของผู้รับจ้างเหมา

ยื่นด้วยวิธีใด  ยื่นด้วยวิธีใด

---

**ข้อมูลเพิ่มเติมในการให้บริการ:** ☐ เป็นของหน่วยงาน ☐ รับจ้างรับ

---

จำนวนคนงานทั้งหมดของสถานประกอบการ 239 คน

จำนวนคนงานทั้งหมดที่เกี่ยวข้องกับสถานที่ให้บริการหรือผู้รับจ้าง 17 คน

[illegible][illegible]

รายงานความปลอดภัยการเก็บรักษาวัตถุดิบตราประจำปี

จำนวนประจำปี 2566

**การเกิดอุบัติเหตุ**

ภายในปีที่ผ่านมามีการเกิดอุบัติเหตุขึ้นหรือไม่ ☒ ไม่ดี ☐ ดี (ถ้ามีโปรดตอบคำถามด้านล่าง)

**5.1 ประเภทของการเกิดอุบัติเหตุ**

☐ สัตว์กัด  
☐ ไฟฟ้าลัดวงจร  
☐ สิ่งๆ ระบุ \_\_\_\_\_

☐ ทกรั่วไหล  
☐ อุบัติเหตุจมน้ำทะเล

**5.2 ความเสียหายจากการเกิดอุบัติเหตุร้ายแรง หรือการประสะสมอันตรายจากการทำงาน**

☐ มีผู้เสียชีวิต จำนวน \_\_\_\_\_ ราย

☐ มีบาดเจ็บ/เจ็บป่วย จำนวน \_\_\_\_\_ ราย

☐ ทรัพย์สินเสียหาย จำนวน \_\_\_\_\_ บาท

☐ มีการหยุดการผลิต ระหว่างเวลา \_\_\_\_\_ วัน

**5.3 รายละเอียดการเกิดอุบัติเหตุ พร้อมแนบไฟล์รูปประกอบ (ถ้ามี)**

ไฟล์แนบ (หมายเหตุไฟล์ต้นฉบับ) :

**5.4 การดำเนินการแก้ไขและป้องกันกาเกิดซ้ำ**

ไฟล์แนบ (หมายเหตุไฟล์ต้นฉบับ) :

กลับไปหน้าก่อน

ถัดไป

รายงานความปลอดภัยการเก็บรักษาวัตถุอันตรายประจำปี

ข้อมูลสถานที่เก็บรักษาวัตถุอันตราย

ลำดับ	ชื่อสถานที่	สถานะ	จัดการ
1	Chemical Warehouse	รายงานแล้ว	<a href="#">คลิกเพื่อดูรายงาน</a>

กลับหน้าหลัก

ต่อไป


หมายเหตุ : กรุณารายงานข้อมูลสถานที่เก็บรักษาวัตถุอันตราย ก่อนจะคลิกรายการต่อไป

## Chemical Storage Area Patrol Report (Quarterly)

Location : Chemical Warehouse

Date : 5-Sep-24

Patrol by : Mr.Thanakorn(SS) , Mr.Praphot (LT) and Mr.Apirak Apirak (LT)

Item	Detail	Result			Remark
		Yes	No	N/A	
1	<b>Wall</b>				
	* No Cracks.	/			
	* Tidy and Clean Wall.	/			
2	<b>Floor</b>				
	* No cracks.	/			
	* No chemical spillage.	/			
	* Tidy and Clean floor.	/			
3	<b>Door and Exit</b>				
	* No obstruction and clearly signs.	/			
	* Easy to open the door from inside and no locked.	/			
	* There are emergency lighting , signs and no obstruction.	/			
	* Inspection as schedule.	/			Emergency lighting : Refer to 3M Inspection by MT unit
	* Alarm equipment of door are good condition and ready for use.			/	
	* Good Condition , No damage.	/			
4	<b>Roof</b>				
	* No leakage.	/			
	* Tidy and Clean.	/			
5	<b>Ventilation</b>				
	* Ventilation system is good condition and clean.		/		
6	<b>Electric System , ER Lighting , Electric Equipment</b>				
	* The electric system & equipment is Explosion Proof type (for storage & loading area of Flammable substance)	/			
	* Grounding system / short circuit prevention system are good condition.	/			
7	<b>Lightning Protection</b>				
	* Lightning rod shall be installed at the building and are good condition.	/			
	* Inspection as schedule.	/			Refer to 1Y Inspection by MT unit
8	<b>Alarm System</b>				
	* Smoke / Gas detector and Fire Alarm are good condition.	/			
	* Inspection as schedule.	/			Refer to 3M Inspection by MT unit
9	<b>Fire Fighting System</b>				
	<b>9.1 Fire Extinguisher</b>				
	* There are Fire Extinguisher (12 kgs.) at least 1 ea. (200 m2) and 2 Fire Extinguisher (50 lbs) for Flammable liquid storage area.	/			
	<i>Remark : There are 2 Dry Chemical - Fire Extinguisher (20 lbs) and 2 Wheel Dry Chemical - Fire Extinguisher (50 lbs)</i>				

## Chemical Storage Area Patrol Report (Quarterly)

Location : Chemical Warehouse

Date : 5-Sep-24

Patrol by : Mr.Thanakorn(SS) , Mr.Praphot (LT) and Mr.Apirak Apirak (LT)

Item	Detail	Result			Remark
		Yes	No	N/A	
	* Inspection as schedule.	/			Refer to 1M Inspection by SS unit;
	* There is fire extinguisher Layout , and signs.	/			
	* Layout of Fire Extinguisher is up date , and good condition.	/			
	* Fire extinguishers shall be installed in appropriate place and easy to use.	/			
	<b>9.2 Fire Water System</b>				
	* Inspection as schedule.	/			Refer to 1M Inspection by SS unit
	* No obstruction and easy to use.	/			
<b>10</b>	<b>Fire Fighting Water Storage System</b>				
	* Drainage system is empty and good condition.	/			
<b>11</b>	<b>Chemical storage area</b>				
	* Clearly indentify and display chemical label on package/container.	/			
	* No keep chemical on the walkway.	/			
	* Package / Container are good condition.	/			
	* Clearly identify of Traffic route , walkway , and chemical storage area.	/			
	* All chemical store comply with DIW laws.	/			
	* No use wood pallet with Oxidizing chemical.			/	There wasn't Oxidizing chemical.
	* No keep combustible material in the same place with Oxidizing chemical.			/	There wasn't Oxidizing chemical.
<b>12</b>	<b>Safety Shower , Eye Wash station and Spill Kit Station</b>				
	* Good condition and ready for use.	/			
	* Inspection as schedule.	/			Refer to 1M Inspection by SS unit
	* No obstruction and easy to use.	/			
<b>13</b>	<b>Forklift</b>				
	* Good condition.	/			
	* Inspection as schedule.	/			Refer to Daily Inspection by LT unit
<b>14</b>	<b>SDS</b>				
	* There are SDS of all Chemical. (except : Waste)	/			