

ภาคผนวก ค

เอกสารการปฏิบัติตามมาตรการป้องกันและลดผลกระทบสิ่งแวดล้อม

- ค1 ใบเสร็จการเก็บขยะ
- ค2 ใบเสร็จการขายของเก่า
- ค3 ใบเสร็จกำจัดปฏิกูล
- ค4 เอกสารตรวจสอบตู้ Fire hose cabinet
- ค5 เอกสารตรวจสอบกล่องปฐมพยาบาล
- ค6 เอกสารตรวจสอบบันไดหนีไฟ Exit Door
- ค7 เอกสารตรวจสอบประตูหนีไฟ
- ค8 เอกสารทดสอบสัญญาณ Fire Alarm
- ค9 เอกสารตรวจสอบถังดับเพลิง Extinguisher
- ค10 เอกสารตรวจสอบกล้อง CCTV
- ค11 บันทึกการทดสอบปั้มน้ำดับเพลิง Fire Pump
- ค12 บันทึกการตรวจสอบส้วม
- ค13 บันทึกการทดสอบเครื่องกำเนิดไฟฟ้า
- ค14 เอกสารตรวจสอบอุปกรณ์ดับเพลิง
- ค15 เอกสารตรวจสอบท่อระบายน้ำ
- ค16 เอกสารตรวจสอบไฟฉุกเฉิน
- ค17 เอกสารตรวจสอบแสงสว่างในอาคาร
- ค18 เอกสารตรวจสอบความร้อน
- ค 19 เอกสารตรวจสอบบันทึกLPG
- ค 20 เอกสารตรวจสอบบันทึกถังดับเพลิง
- ค 21 เอกสารตรวจสอบบันทึกน้ำประปา
- ค 22 เอกสารตรวจสอบอุปกรณ์ท่อดับเพลิง
- ค 23 เอกสารตรวจสอบบันทึกข้อมูลห้องเย็น และ แช่แข็ง
- ค 24 ทส.1ทส.2



ภาคผนวก ค1

ใบเสร็จการเก็บขยะ



ใบเสร็จรับเงินค่ามูลฝอย

สำนักงาน

เล่มที่ 777

เลขที่ 10

เทศบาลนครเชียงใหม่

ได้รับเงินค่ามูลฝอยอัตรา 300 ลิตร 1 เดือน

ประจำเดือน พฤษภาคม ๒๕๖๗ จาก บริษัท ต้นบ่อ จำกัด (เมืองเก่า)

บ้านเลขที่ 171 ถนน ห้วยแก้ว ตำบล หนอง

อำเภอ เมืองเชียงใหม่ เป็นเงิน 600 - บาท

แล้ว แก้ววันที่ ๒๖/๗/๖๗

ทศน

(นางสาววิไล ใจรัก)

เจ้าพนักงานจัดเก็บรายได้ส่วนกลาง

ผู้รับเงิน

สมทบบุญ

ใบเสร็จรับเงินค่ามูลฝอย

สำนักงาน

เล่มที่ 784 เลขที่ 20

เทศบาลนครเชียงใหม่

ได้รับเงินค่ามูลฝอยอัตรา 300 ลิตร 1 เดือน

ประจำเดือน สิงหาคม 2567 จาก มจก. คันทอง (Eastin)

บ้านเลขที่ 171 ถนน รัชชูปถัมภ์ ตำบล สันกำแพง

อำเภอเมืองเชียงใหม่ เป็นเงิน 600.- บาท

ไว้แล้ว เมื่อวันที่ 30/8/67 (นครทองมา ถิ่น)

8 (นายอนุกร แฉ่นศรี) ผู้รับเงิน

(นางกมลวรรณ ศรีวิชัย) สมทบบัญชี

หัวหน้างานจัดเก็บรายได้ศรีวิชัย

ใบเสร็จรับเงินค่ามูลฝอย

สำนักงาน

เล่มที่

814

เลขที่

6

เทศบาลนครเชียงใหม่

ได้รับเงินค่ามูลฝอยอัตรา 300 ลิตร 4 เดือน

ประจำเดือน พฤศจิกายน 2567 จาก ช่าง. ตันนง (Eastin)

บ้านเลขที่ 171 ถนน ห้วยแก้ว ตำบล สันกำแพง

อำเภอ เมืองเชียงใหม่ เป็นเงิน 600.- บาท สิบสอง

ไว้แล้ว เมื่อวันที่ 29/11/67 (นางสาว อรุณรัตน์) สิบห้า

8m

(นางสาว อรุณรัตน์ ศรีวิชัย)

ผู้รับเงิน

สมพงษ์ ภูษ

เจ้าพนักงานจัดเก็บรายได้ชำนาญงาน

สำนักงาน

เล่มที่

814

เลขที่

5

ได้รับเงินค่ามรดกปล่อยอัตราร้อยละ ๓๐๐ ลิตร 1 เดือน
ประจำเดือน ตุลาคม ๒๕๖๗ จาก มหาดินนา (Eastin)
บ้านเลขที่ 171 ถนน หัวขแก้ว ตำบล สว่าง
อำเภอเมืองเชียงใหม่ เป็นเงิน 600.- บาท สว่าง
ไว้แล้ว แก่วันนี้ 29/11/67 (ช.ค.ส.ม.)

ได้รับเงินค่ามูลฝอยอัตรา.....ลิตร.....เดือน

ประจำเดือน ตุลาคม 2567 จาก ผด. ตันขุม (Eastin)

บ้านเลขที่ 171 ถนน หัวขี้แก้ว ตำบล

อำเภอ เมืองเชียงใหม่ เป็นเงิน 600.- บาท สตางค์

ไว้แล้ว เมื่อวันที่ 29/11/67 (ชก. ๑๕๓๓๓๓)

.....

เจ้าพนักงานจัดเก็บรายได้ชำนาญงาน

ภาคผนวก ค2
ใบเสร็จการขายของเก่า





ឃ្លាឃ្លង

วันที่ 19/7/25

[illegible]

ลายเซ็นร้านค้า

ผู้รับเงิน



วันที่ 5/8/29

ลายเซ็นร้านค้า _____

ผู้รับเงิน _____



วันที่ 6/9/24

ตายเช่นร้านค้า

២២ ឆ
 ជួបរង

Wahne



Summary Report_ขายตู้เย็น Mini Bar เก้า

วันที่ 05/09/2024

ลำดับ	รายชื่อ (ผู้ซื้อ)	ราคา	จำนวน	รวม
1	โด้ Security	500.00	1	500.00
2	พิสิทธิ์ Security	500.00	1	500.00
3	โด้ Security	500.00	1	500.00
4	ประเวศ Steward	500.00	1	500.00
5	เคน Security	500.00	2	1,000.00
6	เจน Engineering	500.00	1	500.00
7	ฟิล์ม Kitchen	500.00	1	500.00
8	อคม Kitchen	500.00	1	500.00
			รวมเป็นเงิน	4,500.00



วันที่ 13/๑/24

รวมเป็นเงิน

1094.8

250

Figure 1



วันที่ 27/9/24

รวมเป็นเงิน

ผู้รับเงิน

1291.50

215

A handwritten signature, possibly 'S', is written on a set of three horizontal lines. The signature is formed by a single continuous stroke that loops around and crosses itself.



ឃ្លាឃ្លង

วันที่ 14/10/24

[illegible]

รวมเป็นเงิน

ลายเซ็นผู้ขาย

ผู้รับเงิน




วันที่ 4/11/24

รวมเป็นเงิน

អ្នកប្រគល់ទុក

ជួនរំលង



အိမ်

[illegible]




วันที่ 20/9/24

รวมเป็นเงิน~~1044.8~~

ลายเซ็นผู้ขาย

ជូនរូបរាង

2





วันที่ 6/๑/24

[illegible]

รวมเป็นเงิน

510.5

๑. ๒. ๓. ๔. ๕. ๖. ๗. ๘. ๙. ๑๐. ๑๑. ๑๒. ๑๓. ๑๔. ๑๕. ๑๖. ๑๗. ๑๘. ๑๙. ๒๐. ๒๑. ๒๒. ๒๓. ๒๔. ๒๕. ๒๖. ๒๗. ๒๘. ๒๙. ๓๐. ๓๑. ๓๒. ๓๓. ๓๔. ๓๕. ๓๖. ๓๗. ๓๘. ๓๙. ๔๐. ๔๑. ๔๒. ๔๓. ๔๔. ๔๕. ๔๖. ๔๗. ๔๘. ๔๙. ๕๐. ๕๑. ๕๒. ๕๓. ๕๔. ๕๕. ๕๖. ๕๗. ๕๘. ๕๙. ๖๐. ๖๑. ๖๒. ๖๓. ๖๔. ๖๕. ๖๖. ๖๗. ๖๘. ๖๙. ๗๐. ๗๑. ๗๒. ๗๓. ๗๔. ๗๕. ๗๖. ๗๗. ๗๘. ๗๙. ๘๐. ๘๑. ๘๒. ๘๓. ๘๔. ๘๕. ๘๖. ๘๗. ๘๘. ๘๙. ๙๐. ๙๑. ๙๒. ๙๓. ๙๔. ๙๕. ๙๖. ๙๗. ๙๘. ๙๙. ๑๐๐.



ជូនប្រាក់

วันที่ ๑๕/๘/๕๔



วันที่ 16/8/256

ជួបរឹបរឹប

22



4/2/20



วันที่ 26/7/2๕

ผู้รับเงิน

ภาคผนวก ค3

ใบเสร็จทำจัดปฏิทิน



ใบเสร็จรับเงิน/ใบกำกับภาษี

บริษัท เชียงใหม่การจัดปฏิกูล จำกัด (สำนักงานใหญ่)

เลขที่ 336/3 ถนนเจริญประเทศ ตำบลช้างคลาน อำเภอเมืองเชียงใหม่ จังหวัดเชียงใหม่ 50100
โทร. 053-820409, 053-281533, 053-818446 แฟกซ์. 053-818446

เล่มที่ **094** เลขประจำตัวผู้เสียภาษี 050 5525000 291 เลขที่ **4665**
อัตราภาษี ☒ ร้อยละ 7% ☐ อัตราศูนย์

วันที่ 30 เดือน สิงหาคม พ.ศ. 2567

นาม บริษัท ชันบุญ จำกัด

ที่อยู่ 111 ถ. นววิทย์ ต. ทุ่งนา ต. เมือง จ. เชียงใหม่ 50200

เลขประจำตัวผู้เสียภาษีอากร 010 5552003127

☐ สำนักงานใหญ่ ☒ สำนักงานสาขาเลขที่ 00002

ลำดับ ที่	รายการ	จำนวน	ราคาต่อหน่วย	จำนวนเงิน	
				บาท	สต.
1.	ค่ากำจัดปฏิกูล	1	1,600 -	3,600	-
2.	ค่ากำจัดปฏิกูล (ไผ่)	1	2,000 -	2,000	-
รวมราคาทั้งสิ้น				3,600	-
จำนวนภาษีมูลค่าเพิ่ม				282	-
จำนวนเงินรวมทั้งสิ้น				3,882	-

จำนวนเงินรวมทั้งสิ้น
(ตัวอักษร)

- สามพันแปดร้อยเก้าสิบสอง บาทถ้วน -

ลงชื่อ.....ผู้ส่งจ่าย

ลงชื่อ.....รับเงิน

ใบเสร็จรับเงิน/ใบกำกับภาษี

บริษัท เชียงใหม่การจัดปฏิกูล จำกัด (สำนักงานใหญ่)

เลขที่ 336/3 ถนนเจริญประเทศ ตำบลช้างคลาน อำเภอเมืองเชียงใหม่ จังหวัดเชียงใหม่ 50100
โทร. 053-820409, 053-281533, 053-818446 แฟกซ์. 053-818446

เล่มที่ **096** เลขประจำตัวผู้เสียภาษี 050 5525000 291 เลขที่ **4761**
อัตราภาษี ☒ ร้อยละ 7% ☐ อัตราศูนย์

วันที่ 11 เดือน ตุลาคม พ.ศ. 2567

นาม บริษัท พันบุญ จำกัด

ที่อยู่ 171 ถ.วิทยากร ต.สุเทพ อ.เมืองเชียงใหม่ จ.เชียงใหม่ 50200

เลขประจำตัวผู้เสียภาษีอากร 0105552003927

☐ สำนักงานใหญ่ ☒ สำนักงานสาขาเลขที่ 00002

ลำดับ ที่	รายการ	จำนวน	ราคาต่อหน่วย	จำนวนเงิน	
				บาท	สต.
1.	ค่ากำจัดปฏิกูล	1	1,600 -	3,600	-
2.	ค่ากำจัดปฏิกูล (ไขมัน)	1	2,000 -	2,000	-
รวมราคาทั้งสิ้น				3,600	-
จำนวนภาษีมูลค่าเพิ่ม				252	-
จำนวนเงินรวมทั้งสิ้น				3,852	-

จำนวนเงินรวมทั้งสิ้น
(ตัวอักษร)

- สามพันแปดร้อยห้าสิบสอง บาทถ้วน -

ลงชื่อ.....ผู้ส่งจ่าย

ลงชื่อ อภยา.....ผู้รับเงิน

ใบเสร็จรับเงิน/ใบกำกับภาษี

บริษัท เชียงใหม่การจัดปฏิกูล จำกัด (สำนักงานใหญ่)

เลขที่ 336/3 ถนนเจริญประเทศ ตำบลช้างคลาน อำเภอเมืองเชียงใหม่ จังหวัดเชียงใหม่ 50100
โทร. 053-820409, 053-281533, 053-818446 แฟกซ์. 053-818446

เล่มที่ **097**

เลขประจำตัวผู้เสียภาษี 050 5525000 291

เลขที่ **4831**

อัตราภาษี ☒ ร้อยละ 7% ☐ อัตราศูนย์

วันที่ 7 เดือน พฤษภาคม พ.ศ. 2567

นาม บริษัท สันบุญ จำกัด

ที่อยู่ 171 ถ.หน่วยแก้ว ต.สุเทพ อ.เมือง จ.เชียงใหม่ 50200

เลขประจำตัวผู้เสียภาษีอากร 0105552003127

☐ สำนักงานใหญ่ ☒ สำนักงานสาขาเลขที่ 00002

ลำดับ ที่	รายการ	จำนวน	ราคาต่อหน่วย	จำนวนเงิน	
				บาท	สต.
1.	ค่ากำจัดปฏิกูล	1	1,600 -	3,600	-
2.	ค่ากำจัดปฏิกูล (ไถ่)	1	2,000 -	2,000	-
รวมราคาทั้งสิ้น				3,600	-
จำนวนภาษีมูลค่าเพิ่ม				252	-
จำนวนเงินรวมทั้งสิ้น				3,852	-

จำนวนเงินรวมทั้งสิ้น
(ตัวอักษร)

- สามพันแปดร้อยห้าสิบสองบาทถ้วน -

ลงชื่อ.....ผู้ส่งจ่าย

ลงชื่อ จรรยา.....ผู้รับเงิน

ภาคผนวก ค4

เอกสารตรวจสอบตู้ Fire hose cabinet



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-B-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close		/											
	No leakage from valve		/											
	No leakage from fire hose/reel		/											
	Water pressure level by setting		/											
	General testing		/											
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Patchayaporn	Patchayaporn	Pasit	Pasit	Banbhot	Banbhot	Patchayaporn	Patchayaporn	Pasit	Pasit	

23/02

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-B-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close		/											
	No leakage from valve		/											
	No leakage from fire hose/reel		/											
	Water pressure level by setting		/											
	General testing		/											
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pattayamon	Pattayamon	Pasit	Pasit	Banbhot	Banbhot	Pattayamon	Pattayamon	Pasit	Pasit	

23/02

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-B-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close		/											
	No leakage from valve		/											
	No leakage from fire hose/reel		/											
	Water pressure level by setting		/											
	General testing		/											
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Ban bhot	Ban bhot	Pasit	Pasit	Pasit	Pasit	Pasit	Pasit	Pasit	Pasit	Pasit	Pasit	

23/02/2024

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-B-05 (Front of Fire)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close		/											
	No leakage from valve		/											
	No leakage from fire hose/reel		/											
	Water pressure level by setting		/											
	General testing		/											
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	

92/61

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-G-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/		/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/		/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/		/	/	/	/	/	/	/	/	/	/	
	Valve condition	/		/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/		/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/		/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/		/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close													
	No leakage from valve													
	No leakage from fire hose/reel													
	Water pressure level by setting													
	General testing													
Keeping after rest	Keeping propery	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propery	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	P.erdchayana	P.erdchayana	Basit	Basit	Banbhot	Banbhot	P.erdchayana	P.erdchayana	Basit	Basit	



Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close													
	No leakage from valve													
	No leakage from fire hose/reel													
	Water pressure level by setting													
	General testing													
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		banbhot	banbhot	Pas/12	Pas/12	Pas/12	Pas/12	banbhot	banbhot	Pas/12	Pas/12	Pas/12	Pas/12	

G
23/2/24



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-G-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close	x	/											
	No leakage from valve	x	/											
	No leakage from fire hose/reel	x	/											
	Water pressure level by setting	x	/											
	General testing	x	/											
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Pass 1/2	Barbhot	Pass 1/2	Pass 1/2	Pass 1/2	Pass 1/2	Barbhot	Pass 1/2	Barbhot	Pass 1/2	Pass 1/2	Pass 1/2	

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-1-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close									/				
	No leakage from valve									/				
	No leakage from fire hose/reel									/				
	Water pressure level by setting									/				
	General testing									/				
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pattayarat	Pattayarat	Pasit	Pasit	Banbhot	Banbhot	Pattayarat	Pattayarat	Pasit	Pasit	

8/19/24

1
W2024



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-1-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close										/			
	No leakage from valve										/			
	No leakage from fire hose/reel										/			
	Water pressure level by setting										/			
	General testing										/			
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Patchayama	Patchayama	Pasit	Pasit	Banbhot	Banbhot	Patchayama	Patchayama	Pasit	Pasit	

8/9/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-1-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Pipe system cleanness	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	No leakage from pipe system	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Valve condition	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Joint connect with pipe and hose reel	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Fire Hose & Fire reel	No damage / lacerate	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Good condition no dry-crisp	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Joint connect with pipe is durable pull-easily	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Condition or warer nozzle pull out easily	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Spray Testing	Valve easy to open and close									✓				
	No leakage from valve									✓				
	No leakage from fire hose/reel									✓				
	Water pressure level by setting									✓				
	General testing									✓				
Keeping after rest	Keeping propey	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Roll up propey	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Nozzle	Good condition-not break	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Fire extinguisher	Card checked	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Good condition	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Hydrant	Chain / Cover	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Inspector		Banbhot	Banbhot	Pasit	Pasit	Pasit	Pasit	Banbhot	Banbhot	Pasit	Pasit	Pasit	Pasit	

8/12/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-2-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close							/						
	No leakage from valve							/						
	No leakage from fire hose/reel							/						
	Water pressure level by setting							/						
	General testing							/						
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Paidyana	Paidyana	Paidyana	Paidyana	Paidyana	Paidyana	Paidyana	Paidyana	Paidyana	Paidyana	

8/7/24

2
WUWUWU



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-2-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Pipe system cleanness	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	No leakage from pipe system	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Valve condition	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Joint connect with pipe and hose reel	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Fire Hose & Fire reel	No damage / lacerate	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Good condition no dry-crisp	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Joint connect with pipe is durable pull-easily	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Condition or warer nozzle pull out easily	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Spray Testing	Valve easy to open and close							✓						
	No leakage from valve							✓						
	No leakage from fire hose/reel							✓						
	Water pressure level by setting							✓						
	General testing							✓						
Keeping after rest	Keeping propey	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Roll up propey	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Nozzle	Good condition-not break	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Fire extinguisher	Card checked	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Good condition	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Hydrant	Chain / Cover	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Inspector		Banbhot	Banbhot	Pattayarn	Pattayarn	Pasit	Pasit	Banbhot	Banbhot	Pattayarn	Pattayarn	Pasit	Pasit	

8/17/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-2-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close							/						
	No leakage from valve							/						
	No leakage from fire hose/reel							/						
	Water pressure level by setting							/						
	General testing							/						
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	

8/17/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-3-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close							/						
	No leakage from valve							/						
	No leakage from fire hose/reel							/						
	Water pressure level by setting							/						
	General testing							/						
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pachayarat	Pachayarat	Pasit	Pasit	Banbhot	Banbhot	Pachayarat	Pachayarat	Pasit	Pasit	

8/12/24

3
winny



EASTIN
TAN HOTEL
CHIANG MAI

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-3-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close							/				X		
	No leakage from valve							/				X		
	No leakage from fire hose/reel							/						
	Water pressure level by setting							/						
	General testing							/						
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Patchayaporn	Patchayaporn	Pasit	Pasit	Banbhot	Banbhot	Patchayaporn	Patchayaporn	Pasit	Pasit	

8/17/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-3-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close							/						
	No leakage from valve							/						
	No leakage from fire hose/reel							/						
	Water pressure level by setting							/						
	General testing							/						
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pachayarn	Pachayarn	Pasit	Pasit	Banbhot	Banbhot	Pachayarn	Pachayarn	Pasit	Pasit	

8/7/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-4-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close							/						
	No leakage from valve							/						
	No leakage from fire hose/reel							/						
	Water pressure level by setting							/						
	General testing							/						
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Ban bhot	Ban bhot	Pasit	Pasit	Pasit	Pasit	Pasit	Ban bhot	Ban bhot	Pasit	Pasit	Pasit	

30-07-2024

4 พฤศจิกายน



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-4-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from valve	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from fire hose/reel	/	/	/	/	/	/	/	/	/	/	/	/	
	Water pressure level by setting	/	/	/	/	/	/	/	/	/	/	/	/	
	General testing	/	/	/	/	/	/	/	/	/	/	/	/	
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pantchayarat	Pantchayarat	Prasit	Prasit	Banbhot	Banbhot	Pantchayarat	Pantchayarat	Prasit	Prasit	

30-07-2024

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-4-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close							/						
	No leakage from valve							/						
	No leakage from fire hose/reel							/						
	Water pressure level by setting							/						
	General testing							/						
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pachayarat	Pachayarat	Pasit	Pasit	Banbhot	Banbhot	Pachayarat	Pachayarat	Pasit	Pasit	

20-07-2024



Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close							/	/					
	No leakage from valve							/	/					
	No leakage from fire hose/reel							/	/					
	Water pressure level by setting							/	/					
	General testing							/	/					
Keeping after rest	Keeping propery	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propery	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pattayapant	Pattayapant	Pasit	Pasit	Banbhot	Banbhot	Pattayapant	Pattayapant	Pasit	Pasit	

30/9/24

5 WITNESS



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-5-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close							/						
	No leakage from valve							/						
	No leakage from fire hose/reel							/						
	Water pressure level by setting							/						
	General testing							/						
Keeping after rest	Keeping propery	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propery	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pontchayarat	Pontchayarat	Prasit	Prasit	Banbhot	Banbhot	Pontchayarat	Pontchayarat	Prasit	Prasit	

30/4/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-5-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close							/						
	No leakage from valve							/						
	No leakage from fire hose/reel							/						
	Water pressure level by setting							/						
	General testing							/						
Keeping after rest	Keeping property	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up property	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pasit	Pasit	Pasit	Pasit	Banbhot	Banbhot	Pasit	Pasit	Pasit	Pasit	

30/07/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-6-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close								/					
	No leakage from valve								/					
	No leakage from fire hose/reel								/					
	Water pressure level by setting								/					
	General testing								/					
Keeping after rest	Keeping propery	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propery	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pattayaporn	Pattayaporn	Prasit	Prasit	Banbhot	Banbhot	Pattayaporn	Pattayaporn	Prasit	Prasit	

02/09/24

6
with 9m



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-6-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close								/					
	No leakage from valve								/					
	No leakage from fire hose/reel								/					
	Water pressure level by setting								/					
	General testing								/					
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		banbot	banbot	Patchayarat	Patchayarat	Prasit	Prasit	banbot	banbot	Patchayarat	Patchayarat	Patchayarat	Prasit	Prasit

62/08/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-6-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close								/					
	No leakage from valve								/					
	No leakage from fire hose/reel								/					
	Water pressure level by setting								/					
	General testing								/					
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pachayant	Pachayant	Prasit	Prasit	Banbhot	Banbhot	Pachayant	Pachayant	Prasit	Prasit	

02/08/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-7-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close								/					
	No leakage from valve								/					
	No leakage from fire hose/reel								/					
	Water pressure level by setting								/					
	General testing								/					
Keeping after rest	Keeping property	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up property	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	P. Sathayapant	P. Sathayapant	Pasit	Pasit	Banbhot	Banbhot	P. Sathayapant	P. Sathayapant	Pasit	Pasit	

09/05/24

9/10/24



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-7-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close								/					
	No leakage from valve								/					
	No leakage from fire hose/reel								/					
	Water pressure level by setting								/					
	General testing								/					
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Bombhot	Bombhot	Pasit	Pasit	Pasit	Pasit	Bombhot	Bombhot	Pasit	Pasit	Pasit	Pasit	

09/10/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-7-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close								/					
	No leakage from valve								/					
	No leakage from fire hose/reel								/					
	Water pressure level by setting								/					
	General testing								/					
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	

09/09/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-8-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Pipe system cleanness	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	No leakage from pipe system	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Valve condition	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Joint connect with pipe and hose reel	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Fire Hose & Fire reel	No damage / lacerate	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Good condition no dry-crisp	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Joint connect with pipe is durable pull-easily	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Condition or warer nozzle pull out easily	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Spray Testing	Valve easy to open and close								✓					
	No leakage from valve								✓					
	No leakage from fire hose/reel								✓					
	Water pressure level by setting								✓					
	General testing								✓					
Keeping after rest	Keeping propey	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Roll up propey	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Nozzle	Good condition-not break	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Fire extinguisher	Card checked	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Good condition	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Hydrant	Chain / Cover	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Inspector		Barbhot	Barbhot	Barbhot	Barbhot	Barbhot	Barbhot	Barbhot	Barbhot	Barbhot	Barbhot	Barbhot	Barbhot	

14/08/24

8 WIT 2024



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-8-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close								/					
	No leakage from valve								/					
	No leakage from fire hose/reel								/					
	Water pressure level by setting								/					
	General testing								/					
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pantchayarn	Pantchayarn	Prasit	Prasit	Banbhot	Banbhot	Pantchayarn	Pantchayarn	Prasit	Prasit	

14/08/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-8-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close													
	No leakage from valve													
	No leakage from fire hose/reel													
	Water pressure level by setting													
	General testing													
Keeping after rest	Keeping propery	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propery	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pantchaynant	Pantchaynant	Pasit	Pasit	Banbhot	Banbhot	Pantchaynant	Pantchaynant	Pasit	Pasit	

14/8/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-9-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close								/					
	No leakage from valve								/					
	No leakage from fire hose/reel								/					
	Water pressure level by setting								/					
	General testing								/					
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Paidimpran	Paidimpran	Prasit	Prasit	Banbhot	Banbhot	Paidimpran	Paidimpran	Prasit	Prasit	

23/08/24

9
2024/08/24



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-9-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close								/					
	No leakage from valve								/					
	No leakage from fire hose/reel								X					พบการรั่วซึม
	Water pressure level by setting								/					
	General testing								/					
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pasit	Pasit	Pasit	Pasit	Banbhot	Banbhot	Pasit	Pasit	Pasit	Pasit	

22/08/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-9-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Pipe system cleanness	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	No leakage from pipe system	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Valve condition	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Joint connect with pipe and hose reel	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Fire Hose & Fire reel	No damage / lacerate	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Good condition no dry-crisp	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Joint connect with pipe is durable pull-easily	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Condition or warer nozzle pull out easily	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Spray Testing	Valve easy to open and close								✓					
	No leakage from valve								✓					
	No leakage from fire hose/reel								✓					
	Water pressure level by setting								✓					
	General testing								✓					
Keeping after rest	Keeping propey	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Roll up propey	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Nozzle	Good condition-not break	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Fire extinguisher	Card checked	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Good condition	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Hydrant	Chain / Cover	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Inspector		Banbhot	Banbhot	Pasit	Pasit	Pasit	Pasit	Banbhot	Banbhot	Pasit	Pasit	Pasit	Pasit	

23/08/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-10-01 (Front of Fire)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close								/	/				
	No leakage from valve								/	/				
	No leakage from fire hose/reel								/	/				
	Water pressure level by setting								/	/				
	General testing								/	/				
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover			/	/	/	/	/	/	/	/	/	/	
Inspector				Pattana		Basit	Basit	Basit	Basit	Basit	Basit	Basit	Basit	

23/08/24

ภาคผนวก ค5

เอกสารตรวจสอบบกล่องปฐมพยาบาล





FIRST AID BOX CHECKLIST

Location :

Date of Inspection :

No	Item	Available		Quantity
		Yes	No	
First Aid Instrument				
1	น้ำเกลือ 500 ml (Sodium Chloride 500 ml)	/		1 Bottle
2	น้ำเกลือ 1,000 ml (Sodium Chloride 1,000 ml)	/		1 Bottle
3	แอลกอฮอล์ 30 cc (Ethhyl Alcohol 30 cc)	/		1 Bottle
4	เบตาดีน 15 cc (Betadine Solution 15 cc)	/		1 Bottle
5	เจลประคบ ร้อน - เย็น (Hot/Cold Gel Pack)	/		1 Packets
6	ถุงมือยาง ไซส์ M (Examination gloves Size M)	/		1 Packets
7	น้ำยาล้างตา 110 ml (Eye Wash 110 ml)	/		1 Bottle
8	แอมโมเนียหอม 30 ml (Aromatic Ammonia Spirit 30 ml)	/		1 Bottle
Dressing & Bandage				
9	สำลีชนิดก้อน (Cotton Wool)	/		1 Packets
10	สำลีชนิดก้าน (Cotton Bud)	/		90 Sticks
16	ผ้ารัดกล้ามเนื้อ 3 นิ้ว x 5 หลา (Elastic Bandage 3" x 5yd)	/		1 Roll
17	ผ้าคล้องแขน (Arm Sling)	/		1 Pc
18	พลาสเตอร์ยา ชนิดผ้า (Fabric Strip Plasters)	/		100 Pcs
19	พลาสเตอร์ยา ชนิดกันน้ำ (Waterproof Plaster)	/		60 Pcs
OTC Medicines				
20	คาลาไมย โลชั่น 60 ml (Cadramine lotion 60 ml)	/		1 Bottle
21	ยารักษาแผลน้ำร้อนลวก (Burn Care)	/		1 Packets
22	ยารลดไข้ (Fever Reducer)	/		
23	ยาแก้แพ้ (Antihistamine)	/		1 Packets
24	เกลือแร่ ORS (ORS powder)	/		19 Packets
25	ยาธาตุน้ำขาว 50 ml (Salol et Menthol Mixture 50 ml)	/		1 Bottles
26	ยาผงต้านรักษาอาการท้องเสีย (Antidiarrheal)	/		3 Packets
27	Ponstan500	/		1 Tablets
28	ยาธาตุน้ำแดง (Stomachic Mixture)	/		1 Bottles
29	ยาลดกรดในกระเพาะอาหาร (Antacid)	/		1 Packets
30	ยาหม่องขี้ผึ้งแก้ปวดบวม (Analgesic Balm)	/		1 Bottles
31	Counterpain สูตรร้อน	/		1 Bottles
32	Counterpain สูตรเย็น	/		1 Bottles
33	แซมบัค (ZamBuk Ointment Balm)	/		1 Bottles
Other				
34	กระเป๋าน้ำร้อนไฟฟ้า/ถุงน้ำร้อน (Hot Water Bag)	/		1 piece
35	กรรไกร (Scissors)	/		1 Scissor
36	ปรอทวัดไข้ (Thermometer)	/		
37	ปากคีบปลายทู่ (Forceps Round End)	/		

Checked by : Prassit Inta...(Security Supervisor)...

Date : ...03 July...2024.....

Verified by : Prasit...Inta.....(Security Supervisor)...

Date03 July2024....

อุปกรณ์ที่ต้องการเพิ่มเติม (ของยังครบ)





FIRST AID BOX CHECKLIST

Location : Officer Security

Date of Inspection : 03/08/2024

No	Item	Available		Quantity
		Yes	No	
First Aid Instrument				
1	น้ำเกลือ 500 ml (Sodium Chloride 500 ml)	/		1 Bottle
2	น้ำเกลือ 1,000 ml (Sodium Chloride 1,000 ml)		/	1 Bottle
3	แอลกอฮอล์ 30 cc (Ethhyl Alcohol 30 cc)	/		1 Bottle
4	เบตาดีน 15 cc (Betadine Solution 15 cc)	/		1 Bottle
5	เจลประคบ ร้อน - เย็น (Hot/Cold Gel Pack)	/		1 Packets
6	ถุงมือยาง ไซส์ M (Examination gloves Size M)	/		1 Packets
7	น้ำยาล้างตา 110 ml (Eye Wash 110 ml)	/		1 Bottle
8	แอมโมเนียหอม 30 ml (Aromatic Ammonia Spirit 30 ml)	/		1 Bottle
Dressing & Bandage				
9	สำลีชนิดก้อน (Cotton Wool)	/		1 Packets
10	สำลีชนิดก้าน (Cotton Bud)	/		90 Sticks
16	ผ้ารัดกล้ามเนื้อ 3 นิ้ว x 5 หลา (Elastic Bandage 3" x 5yd)	/		1 Roll
17	ผ้าคล้องแขน (Arm Sling)	/		1 Pc
18	พลาสเตอร์ยา ชนิดผ้า (Fabric Strip Plasters)	/		100 Pcs
19	พลาสเตอร์ยา ชนิดกันน้ำ (Waterproof Plaster)	/		60 Pcs
OTC Medicines				
20	คาลามาย โลชั่น 60 ml (Cadramine lotion 60 ml)	/		1 Bottle
21	ขี้ผึ้งแผลน้ำร้อนลวก (Burn Care)	/		1 Packets
22	ยาบรรเทาไข้ (Fever Reducer)	/		
23	ยาแก้แพ้ (Antihistamine)	/		1 Packets
24	เกลือแร่ ORS (ORS powder)	/		19 Packets
25	ยาธาตุน้ำขาว 50 ml (Salol et Menthol Mixture 50 ml)		/	1 Bottles
26	ยาผงต้านรักษาอาการท้องเสีย (Antidiarrheal)	/		3 Packets
27	Ponstan500	/		1 Tablets
28	ยาธาตุน้ำแดง (Stomachic Mixture)	/		1 Bottles
29	ยาลดกรดในกระเพาะอาหาร (Antacid)	/		1 Packets
30	ยาหม่องขี้ผึ้งแก้ปวดบวม (Analgesic Balm)	/		1 Bottles
31	Counterpain สูตรร้อน	/		1 Bottles
32	Counterpain สูตรเย็น	/		1 Bottles
33	แซมบัค (ZamBuk Ointment Balm)	/		1 Bottles
Other				
34	กระเป๋าน้ำร้อนไฟฟ้า/ถุงน้ำร้อน (Hot Water Bag)	/		1 piece
35	กรรไกร (Scissors)	/		1 Scissor
36	ปรอทวัดไข้ (Thermometer)	/		
37	ปากคีบปลายทู่ (Forceps Round End)	/		

อุปกรณ์ที่ต้องการเพิ่มเติม



Checked by : Prassit Inta...(Security Supervisor)...

Date : ...03 August...2024.....

Verified by : Prasit...Inta.....(Security Supervisor)...

Date ..003 August2024....



FIRST AID BOX CHECKLIST

Location : Officer Security

Date of Inspection : 02/09/2024

No	Item	Available		Quantity
		Yes	No	
First Aid Instrument				
1	น้ำเกลือ 500 ml (Sodium Chloride 500 ml)	/		1 Bottle
2	น้ำเกลือ 1,000 ml (Sodium Chloride 1,000 ml)		/	1 Bottle
3	แอลกอฮอล์ 30 cc (Ethhyl Alcohol 30 cc)	/		1 Bottle
4	เบตาดีน 15 cc (Betadine Solution 15 cc)	/		1 Bottle
5	เจลประคบ ร้อน - เย็น (Hot/Cold Gel Pack)	/		1 Packets
6	ถุงมือยาง ไซส์ M (Examination gloves Size M)	/		1 Packets
7	น้ำยาล้างตา 110 ml (Eye Wash 110 ml)	/		1 Bottle
8	แอมโมเนียหอม 30 ml (Aromatic Ammonia Spirit 30 ml)	/		1 Bottle
Dressing & Bandage				
9	สำลีชนิดก้อน (Cotton Wool)	/		1 Packets
10	สำลีชนิดก้าน (Cotton Bud)	/		90 Sticks
16	ผ้ารัดกล้ามเนื้อ 3 นิ้ว x 5 หลา (Elastic Bandage 3" x 5yd)	/		1 Roll
17	ผ้าคล้องแขน (Arm Sling)	/		1 Pc
18	พลาสเตอร์ยา ชนิดผ้า (Fabric Strip Plasters)	/		100 Pcs
19	พลาสเตอร์ยา ชนิดกันน้ำ (Waterproof Plaster)	/		60 Pcs
OTC Medicines				
20	คาลามาย โลชั่น 60 ml (Cadramine lotion 60 ml)	/		1 Bottle
21	ยารักษาแผลน้ำร้อนลวก (Burn Care)	/		1 Packets
22	ยาบรรเทาไข้ (Fever Reducer)	/		
23	ยาแก้แพ้ (Antihistamine)	/		1 Packets
24	เกลือแร่ ORS (ORS powder)	/		19 Packets
25	ยาชาดูน้ำขาว 50 ml (Salol et Menthol Mixture 50 ml)		/	1 Bottles
26	ยาผงต้านรักษาอาการท้องเสีย (Antidiarrheal)	/		3 Packets
27	Ponstan500	/		1 Tablets
28	ยาชาดูน้ำแดง (Stomachic Mixture)	/		1 Bottles
29	ยาลดกรดในกระเพาะอาหาร (Antacid)	/		1 Packets
30	ยาหม่องขี้ผึ้งแก้ปวดบวม (Analgesic Balm)	/		1 Bottles
31	Counterpain สูตรร้อน	/		1 Bottles
32	Counterpain สูตรเย็น	/		1 Bottles
33	แซมบัค (ZamBuk Ointment Balm)	/		1 Bottles
Other				
34	กระเป๋าน้ำร้อนไฟฟ้า/ถุงน้ำร้อน (Hot Water Bag)	/		1 piece
35	กรรไกร (Scissors)	/		1 Scissor
36	ปรอทวัดไข้ (Thermometer)	/		
37	ปากคีบปลายทู่ (Forceps Round End)	/		

อุปกรณ์ที่ต้องการเพิ่มเติม



Checked by : Banboht Sunyaphap ...(Security Officer)...

Date : ...02 September...2024.....

Verified by : Prasit...Inta.....(Security Supervisor)...

Date ..004 September2024....



FIRST AID BOX CHECKLIST

Location : Officer Security

Date of Inspection : 02/10/2024

No	Item	Available		Quantity
		Yes	No	
First Aid Instrument				
1	น้ำเกลือ 500 ml (Sodium Chloride 500 ml)	/		1 Bottle
2	น้ำเกลือ 1,000 ml (Sodium Chloride 1,000 ml)		/	1 Bottle
3	แอลกอฮอล์ 30 cc (Ethhyl Alcohol 30 cc)	/		1 Bottle
4	เบตาดีน 15 cc (Betadine Solution 15 cc)	/		1 Bottle
5	เจลประคบ ร้อน - เย็น (Hot/Cold Gel Pack)	/		1 Packets
6	ถุงมือยาง ไซส์ M (Examination gloves Size M)	/		1 Packets
7	น้ำยาล้างตา 110 ml (Eye Wash 110 ml)	/		1 Bottle
8	แอมโมเนียหอม 30 ml (Aromatic Ammonia Spirit 30 ml)	/		1 Bottle
Dressing & Bandage				
9	สำลีชนิดก้อน (Cotton Wool)	/		1 Packets
10	สำลีชนิดก้าน (Cotton Bud)	/		90 Sticks
16	ผ้ารัดกล้ามเนื้อ 3 นิ้ว x 5 หลา (Elastic Bandage 3" x 5yd)	/		1 Roll
17	ผ้าคล้องแขน (Arm Sling)	/		1 Pc
18	พลาสเตอร์ยา ชนิดผ้า (Fabric Strip Plasters)	/		100 Pcs
19	พลาสเตอร์ยา ชนิดกันน้ำ (Waterproof Plaster)	/		60 Pcs
OTC Medicines				
20	คาลาไมย โลชั่น 60 ml (Cadramine lotion 60 ml)	/		1 Bottle
21	ยารักษาแผลน้ำร้อนลวก (Burn Care)	/		1 Packets
22	ยาบรรเทาไข้ (Fever Reducer)	/		
23	ยาแก้แพ้ (Antihistamine)	/		1 Packets
24	เกลือแร่ ORS (ORS powder)	/		19 Packets
25	ยาธาตุน้ำขาว 50 ml (Salol et Menthol Mixture 50 ml)	/		1 Bottles
26	ยาผงถ่านรักษาอาการท้องเสีย (Antidiarrheal)	/		3 Packets
27	Ponstan500	/		1 Tablets
28	ยาธาตุน้ำแดง (Stomachic Mixture)	/		1 Bottles
29	ยาลดกรดในกระเพาะอาหาร (Antacid)	/		1 Packets
30	ยาหม่องขี้ผึ้งแก้ปวดบวม (Analgesic Balm)	/		1 Bottles
31	Counterpain สูตรร้อน	/		1 Bottles
32	Counterpain สูตรเย็น	/		1 Bottles
33	แซมบู๊ด (ZamBuk Oinment Balm)	/		1 Bottles
Other				
34	กระเป๋าน้ำร้อนไฟฟ้า/ถุงน้ำร้อน (Hot Water Bag)	/		1 piece
35	กรรไกร (Scissors)	/		1 Scissor
36	ปรอทวัดไข้ (Thermometer)	/		
37	ปากคีบปลายทู่ (Forceps Round End)	/		

อุปกรณ์ที่ต้องการเพิ่มเติม

- 1 ผ้าก๊อชใยสังเคราะห์ 2 นิ้ว
- 2 พลาสเตอร์ยา ชนิดผ้า
- 3 พลาสเตอร์ยา ชนิดกันน้ำ
- 4 สำลีชนิดก้อน
- 4 ยาแก้แพ้



Checked by : Banboht Sunyaphap ...(Security Officer)...

Date : ...02 October...2024.....

Verified by : Prasit...Inta.....(Security Supervisor)...

Date ..004 October2024....



FIRST AID BOX CHECKLIST

Location : Officer Security

Date of Inspection : 02/11/2024

No	Item	Available		Quantity
		Yes	No	
First Aid Instrument				
1	น้ำเกลือ 500 ml (Sodium Chloride 500 ml)	/		1 Bottle
2	น้ำเกลือ 1,000 ml (Sodium Chloride 1,000 ml)		/	1 Bottle
3	แอลกอฮอล์ 30 cc (Ethhyl Alcohol 30 cc)	/		1 Bottle
4	เบตาดีน 15 cc (Betadine Solution 15 cc)	/		1 Bottle
5	เจลประคบ ร้อน - เย็น (Hot/Cold Gel Pack)	/		1 Packets
6	ถุงมือยาง ไซส์ M (Examination gloves Size M)	/		1 Packets
7	น้ำยาล้างตา 110 ml (Eye Wash 110 ml)	/		1 Bottle
8	แอมโมเนียหอม 30 ml (Aromatic Ammonia Spirit 30 ml)	/		1 Bottle
Dressing & Bandage				
9	สำลีชนิดก้อน (Cotton Wool)	/		1 Packets
10	สำลีชนิดก้าน (Cotton Bud)	/		90 Sticks
16	ผ้ารัดกล้ามเนื้อ 3 นิ้ว x 5 หลา (Elastic Bandage 3" x 5yd)	/		1 Roll
17	ผ้าคล้องแขน (Arm Sling)	/		1 Pc
18	พลาสเตอร์ยา ชนิดผ้า (Fabric Strip Plasters)	/		100 Pcs
19	พลาสเตอร์ยา ชนิดกันน้ำ (Waterproof Plaster)	/		60 Pcs
OTC Medicines				
20	คาลามาย โลชั่น 60 ml (Cadramine lotion 60 ml)	/		1 Bottle
21	ยารักษาแผลน้ำร้อนลวก (Burn Care)	/		1 Packets
22	ยาบรรเทาไข้ (Fever Reducer)	/		
23	ยาแก้แพ้ (Antihistamine)	/		1 Packets
24	เกลือแร่ ORS (ORS powder)	/		19 Packets
25	ยาชาดูน้ำขาว 50 ml (Salol et Menthol Mixture 50 ml)		/	1 Bottles
26	ยาผงต้านรักษาอาการท้องเสีย (Antidiarrheal)	/		3 Packets
27	Ponstan500	/		1 Tablets
28	ยาชาดูน้ำแดง (Stomachic Mixture)	/		1 Bottles
29	ยาลดกรดในกระเพาะอาหาร (Antacid)	/		1 Packets
30	ยาหม่องขี้ผึ้งแก้ปวดบวม (Analgesic Balm)	/		1 Bottles
31	Counterpain สูตรร้อน	/		1 Bottles
32	Counterpain สูตรเย็น	/		1 Bottles
33	แซมบูค (ZamBuk Ointment Balm)	/		1 Bottles
Other				
34	กระเป๋าน้ำร้อนไฟฟ้า/ถุงน้ำร้อน (Hot Water Bag)	/		1 piece
35	กรรไกร (Scissors)	/		1 Scissor
36	ปรอทวัดไข้ (Thermometer)	/		
37	ปากคีบปลายทู่ (Forceps Round End)	/		

อุปกรณ์ที่ต้องการเพิ่มเติม



Checked by : Prachayarat Thongdee ...(Security Officer)...

Date : ...02 November...2024.....

Verified by : Prasit...Inta.....(Security Supervisor)...

Date ..006 November2024....



FIRST AID BOX CHECKLIST

Location : Officer Security

Date of Inspection : 03/12/2024

No	Item	Available		Quantity
		Yes	No	
First Aid Instrument				
1	น้ำเกลือ 500 ml (Sodium Chloride 500 ml)	/		3 Bottle
2	น้ำเกลือ 1,000 ml (Sodium Chloride 1,000 ml)		/	- Bottle
3	แอลกอฮอล์ 30 cc (Ethhyl Alcohol 30 cc)	/		1 Bottle
4	เบตาดีน 15 cc (Betadine Solution 15 cc)	/		1 Bottle
5	เจลประคบ ร้อน - เย็น (Hot/Cold Gel Pack)	/		1 Packets
6	ถุงมือยาง ไซส์ M (Examination gloves Size M)	/		1 Packets
7	น้ำยาล้างตา 110 ml (Eye Wash 110 ml)	/		1 Bottle
8	แอมโมเนียหอม 30 ml (Aromatic Ammonia Spirit 30 ml)	/		1 Bottle
Dressing & Bandage				
9	สำลีชนิดก้อน (Cotton Wool)	/		1 Packets
10	สำลีชนิดก้าน (Cotton Bud)	/		60 Sticks
16	ผ้ารัดกล้ามเนื้อ 3 นิ้ว x 5 หลา (Elastic Bandage 3" x 5yd)	/		1 Roll
17	ผ้าคล้องแขน (Arm Sling)	/		1 Pc
18	พลาสเตอร์ยา ชนิดผ้า (Fabric Strip Plasters)	/		100 Pcs
19	พลาสเตอร์ยา ชนิดกันน้ำ (Waterproof Plaster)	/		60 Pcs
OTC Medicines				
20	คาลามาย โลชั่น 60 ml (Cadramine lotion 60 ml)	/		1 Bottle
21	ยารักษาแผลน้ำร้อนลวก (Burn Care)	/		1 Packets
22	ยารลดไข้ (Fever Reducer)	/		
23	ยาแก้แพ้ (Antihistamine)	/		1 Packets
24	เกลือแร่ ORS (ORS powder)	/		15 Packets
25	ยาชาดูน้ำขาว 50 ml (Salol et Menthol Mixture 50 ml)	/		1 Bottles
26	ยาผงต้านรักษาอาการท้องเสีย (Antidiarrheal)	/		2 Packets
27	Ponstan500	/		2 Tablets
28	ยาชาดูน้ำแดง (Stomachic Mixture)	/		1 Bottles
29	ยาลดกรดในกระเพาะอาหาร (Antacid)	/		1 Packets
30	ยาหม่องขี้ผึ้งแก้ปวดบวม (Analgesic Balm)		/	1 Bottles
31	Counterpain สูตรร้อน	/		2 Bottles
32	Counterpain สูตรเย็น	/		1 Bottles
33	แซมบัค (ZamBuk Ointment Balm)		/	- Bottles
Other				
34	กระเป๋าน้ำร้อนไฟฟ้า/ถุงน้ำร้อน (Hot Water Bag)	/		1 piece
35	กรรไกร (Scissors)	/		1 Scissor
36	ปรอทวัดไข้ (Thermometer)		/	
37	ปากคีบปลายทู่ (Forceps Round End)	/		

Checked by : Pratchayarat Thongdee ...(Security Officer)...

Date : ...03 December...2024.....

Verified by : Prasit...Inta.....(Security Supervisor)...

Date ..005 December2024.....

อุปกรณ์ที่ต้องการเพิ่มเติม

- 1 ขาชาดูน้ำขาว 2 ขวด
- 2 พาราเซตามอล 500 มิลลิกรัม 2 ขวด
- 3 Counterpain 1 เข็ม
- 4 แซมบัค 1



























ภาคผนวก ค6

เอกสารตรวจสอบบันไดหนีไฟ Exit Door





Fire Staircases Monthly Inspection in July 2024

Floor	Staircases 1 (Southern)	Condition Good or Not ? Yes or No	Remark	Staircases 2 (Northern)	Condition Good or Not ? Yes or No	Remark
10		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
9		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
8		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
7		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
6		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
5		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
4		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
3		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
2		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
1		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
G		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
B		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง

Checked by: Mr.Prachayarat Thongdee (Security Officer) Checking date: 01 July 2024

























Verified by: Mr. Prasit Inta (Security Supervisor) Verified date: 04 July 2024



Verified by: Mr. Prasit Inta (Security Supervisor)	Verified date: 03 August 2024



Fire Staircases Monthly Inspection in September 2024

Floor	Staircases 1 (Southern)	Condition Good or Not ? Yes or No	Remark	Staircases 2 (Northern)	Condition Good or Not ? Yes or No	Remark
10		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
9		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
8		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
7		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
6		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
5		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
4		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
3		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
2		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
1		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
G		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
B		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง

Checked by: Mr. Prasit Inta (Security Supervisor)


















Checking date: 04 September 2024

Verified by: Mr. Prasit Inta (Security Supervisor)

Verified date: 04 September 2024



Fire Staircases Monthly Inspection in October 2024

Floor	Staircases 1 (Southern)	Condition Good or Not ? Yes or No	Remark	Staircases 2 (Northern)	Condition Good or Not ? Yes or No	Remark
10		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
9		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
8		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
7		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
6		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
5		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
4		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
3		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
2		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
1		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
G		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
B		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง

Checked by: Mr. Prasit Inta (Security Supervisor)

Checking date: 02 October 2024

Verified by: Mr. Prasit Inta (Security Supervisor)

Verified date: 02 October 2024



Fire Staircases Monthly Inspection in November 2024

Floor	Staircases 1 (Southern)	Condition Good or Not ? Yes or No	Remark	Staircases 2 (Northern)	Condition Good or Not ? Yes or No	Remark
10		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
9		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
8		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
7		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
6		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
5		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
4		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
3		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
2		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
1		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
G		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
B		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง

Checked by: Mr. Banhot Sunyaphap (Security Officer)

Checking date: 03 November 2024

Verified by: Mr. Prasit Inta (Security Supervisor)

Verified date: 06 November 2024



Fire Staircases Monthly Inspection in December 2024

Floor	Staircases 1 (Southern)	Condition Good or Not ? Yes or No	Remark	Staircases 2 (Northern)	Condition Good or Not ? Yes or No	Remark
10		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
9		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
8		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
7		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
6		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
5		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
4		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
3		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
2		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
1		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
G		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง
B		✓	สะอาด ไม่มีสิ่งกีดขวาง		✓	สะอาด ไม่มีสิ่งกีดขวาง

Checked by: Mr. Banhot Sunyaphap (Security Officer)

Checking date: 02 December 2024

Verified by: Mr. Prasit Inta (Security Supervisor)

Verified date: 05 December 2024

ภาคผนวก ค7

เอกสารตรวจสอบประตุน้ำไฟ





Exit Lighting Inspection

Month : July 2024

Overview Inspection Report

No.	Description		Checklist		
	Building	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
1	Front of Engineer Department	1	✓		
2	Front of Entrance	1	✓		
3	Front of Exit Door	1	✓		
4	Front of Exit Way	1	✓		
	Gst Floor.	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
5	Entrance eascalator	1	✓		
6	Entrance to locker	1	✓		
7	Locker Exit	1	✓		
8	Front of restroom	1	✓		
9	Exit way besside restroom	1	✓		
10	Front of exit door	1	✓		
	1st Floor.	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
11	Entrance lobby	1	✓		
12	T-Café	1	✓		
13	Bar behind fron desk	1	✓		
14	Exit Door (Pool)	1	✓		
15	Front of waterfall	1	✓		
16	Front of T-station	1	✓		
	2nd Floor.	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
17	Exit Door บันไดหนีไฟ(ฝั่งPool)	1	✓		
18	ExitDoor บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
	Floor Inspection	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
26	Exit Door Floor.3 บันไดหนีไฟ(ฝั่งPool)	1	✓		
27	Exit Door Floor.3 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
28	Exit Door Floor.4 บันไดหนีไฟ(ฝั่งPool)	1	✓		
29	Exit Door Floor.4 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
30	Exit Door Floor.5 บันไดหนีไฟ(ฝั่งPool)	1	✓		
31	Exit Door Floor.5 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
32	Exit Door Floor.6 บันไดหนีไฟ(ฝั่งPool)	1	✓		
33	Exit Door Floor.6 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
34	Exit Door Floor.7 บันไดหนีไฟ(ฝั่งPool)	1	✓		
35	Exit Door Floor.7 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
36	Exit Door Floor.8 บันไดหนีไฟ(ฝั่งPool)	1	✓		
37	Exit Door Floor.8 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
38	Exit Door Floor.9 บันไดหนีไฟ(ฝั่งPool)	1	✓		
39	Exit Door Floor.9 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
40	Exit Door Rooftop บันไดหนีไฟ(ฝั่งPool)	1	✓		
41	Exit Door Rooftop บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
	Roof top Floor Inspection	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
	Other Focus EHCM	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ

REMARK : รวมทั้งหมด 41 จุด ปกติ 41 จุด *เสีย 0 จุด

Inspection by 1.

Inspection by 2.

Verify by Chief ENG/Asst.Chief ENG(Engineering)

Inspection by General Manager



Exit Lighting Inspection

Month : August 2024

Overview Inspection Report

No.	Description		Checklist		
๒๕๖	Building	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
1	Front of Engineer Department	1	✓		
2	Front of Entrance	1	✓		
3	Front of Exit Door	1	✓		
4	Front of Exit Way	1	✓		
	Gst Floor.	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
5	Entrance eascalator	1	✓		
6	Entrance to locker	1	✓		
7	Locker Exit	1	✓		
8	Front of restroom	1	✓		
9	Exit way beside restroom	1	✓		
10	Front of exit door	1	✓		
	1st Floor.	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
11	Entrance lobby	1	✓		
12	T-Café	1	✓		
13	Bar behind fron desk	1	✓		
14	Exit Door (Pool)	1	✓		
15	Front of waterfall	1	✓		
16	Front of T-station	1	✓		
	2nd Floor.	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
17	Exit Door บันไดหนีไฟ(ฝั่งPool)	1	✓		
18	ExitDoor บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
	Floor Inspection	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
26	Exit Door Floor.3 บันไดหนีไฟ(ฝั่งPool)	1	✓		
27	Exit Door Floor.3 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
28	Exit Door Floor.4 บันไดหนีไฟ(ฝั่งPool)	1	✓		
29	Exit Door Floor.4 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
30	Exit Door Floor.5 บันไดหนีไฟ(ฝั่งPool)	1	✓		
31	Exit Door Floor.5 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
32	Exit Door Floor.6 บันไดหนีไฟ(ฝั่งPool)	1	✓		
33	Exit Door Floor.6 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
34	Exit Door Floor.7 บันไดหนีไฟ(ฝั่งPool)	1	✓		
35	Exit Door Floor.7 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
36	Exit Door Floor.8 บันไดหนีไฟ(ฝั่งPool)	1	✓		
37	Exit Door Floor.8 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
38	Exit Door Floor.9 บันไดหนีไฟ(ฝั่งPool)	1	✓		
39	Exit Door Floor.9 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
40	Exit Door Rooftop บันไดหนีไฟ(ฝั่งPool)	1	✓		
41	Exit Door Rooftop บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
	Roof top Floor Inspection	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
	Other Focus EHCM	จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ

REMARK : รวมทั้งหมด 41 จุด ปกติ 41 จุด *เสีย 0 จุด

Inspection by 1.

Inspection by 2.

Verify by Chief ENG/Asst. Chief ENG(Engineering)

Inspection by General Manager



Exit Lighting Inspection

Month : September 2024

Overview Inspection Report

No.	Description		Checklist		
Building		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
1	Front of Engineer Department	1	✓		
2	Front of Entrance	1	✓		
3	Front of Exit Door	1	✓		
4	Front of Exit Way	1	✓		
Gst Floor.		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
๕	Entrance eascalator	1	✓		
๕ก	Entrance to locker	1	✓		
๕ข	Locker Exit	1	✓		
8	Front of restroom	1	✓		
9	Exit way besside restroom	1	✓		
10	Front of exit door	1	✓		
1st Floor.		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
11	Entrance lobby	1	✓		
12	T-Café	1	✓		
13	Bar behind fron desk	1	✓		
14	Exit Door (Pool)	1	✓		
15	Front of waterfall	1	✓		
16	Front of T-station	1	✓		
2nd Floor.		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
17	Exit Door บันไดหนีไฟ(ฝั่งPool)	1	✓		
18	ExitDoor บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
Floor Inspection		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
26	Exit Door Floor.3 บันไดหนีไฟ(ฝั่งPool)	1	✓		
27	Exit Door Floor.3 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
28	Exit Door Floor.4 บันไดหนีไฟ(ฝั่งPool)	1	✓		
29	Exit Door Floor.4 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
30	Exit Door Floor.5 บันไดหนีไฟ(ฝั่งPool)	1	✓		
31	Exit Door Floor.5 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
32	Exit Door Floor.6 บันไดหนีไฟ(ฝั่งPool)	1	✓		
33	Exit Door Floor.6 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
34	Exit Door Floor.7 บันไดหนีไฟ(ฝั่งPool)	1	✓		
35	Exit Door Floor.7 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
36	Exit Door Floor.8 บันไดหนีไฟ(ฝั่งPool)	1	✓		
37	Exit Door Floor.8 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
38	Exit Door Floor.9 บันไดหนีไฟ(ฝั่งPool)	1	✓		
39	Exit Door Floor.9 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
40	Exit Door Rooftop บันไดหนีไฟ(ฝั่งPool)	1	✓		
41	Exit Door Rooftop บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
Roof top Floor Inspection		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
Other Focus EHCM		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ

REMARK : รวมทั้งหมด 41 จุด ปกติ 41 จุด *เสีย 0 จุด

Inspection by 1.

๙/๐๙๒๕

Inspection by 2.

Verify by Chief ENG/Asst. Chief ENG(Engineering)

Inspection by General Manager



Exit Lighting Inspection

Month : November 2024

Overview Inspection Report

No.	Description		Checklist		
Building		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
1	Front of Engineer Department	1	✓		
2	Front of Entrance	1	✓		
3	Front of Exit Door	1	✓		
4	Front of Exit Way	1	✓		
Gst Floor.		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
๘	Entrance eascalator	1	✓		
๘.๗	Entrance to locker	1	✓		
๗.๗.๗	Locker Exit	1	✓		
8	Front of restroom	1	✓		
9	Exit way besside restroom	1	✓		
10	Front of exit door	1	✓		
1st Floor.		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
11	Entrance lobby	1	✓		
12	T-Café	1	✓		
13	Bar behind fron desk	1	✓		
14	Exit Door (Pool)	1	✓		
15	Front of waterfall	1	✓		
16	Front of T-station	1	✓		
2nd Floor.		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
17	Exit Door บันไดหนีไฟ(ฝั่งPool)	1	✓		
18	ExitDoor บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
Floor Inspection		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
26	Exit Door Floor.3 บันไดหนีไฟ(ฝั่งPool)	1	✓		
27	Exit Door Floor.3 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
28	Exit Door Floor.4 บันไดหนีไฟ(ฝั่งPool)	1	✓		
29	Exit Door Floor.4 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
30	Exit Door Floor.5 บันไดหนีไฟ(ฝั่งPool)	1	✓		
31	Exit Door Floor.5 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
32	Exit Door Floor.6 บันไดหนีไฟ(ฝั่งPool)	1	✓		
33	Exit Door Floor.6 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
34	Exit Door Floor.7 บันไดหนีไฟ(ฝั่งPool)	1	✓		
35	Exit Door Floor.7 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
36	Exit Door Floor.8 บันไดหนีไฟ(ฝั่งPool)	1	✓		
37	Exit Door Floor.8 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
38	Exit Door Floor.9 บันไดหนีไฟ(ฝั่งPool)	1	✓		
39	Exit Door Floor.9 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
40	Exit Door Rooftop บันไดหนีไฟ(ฝั่งPool)	1	✓		
41	Exit Door Rooftop บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
Roof top Floor Inspection		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
Other Focus EHCM		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ

REMARK : รวมทั้งหมด 41 จุด ปกติ 41 จุด *เสีย 0 จุด

Inspection by 1.

๗๖๖๗

Inspection by 2.

Verify by Chief ENG/Asst.Chief ENG(Engineering)

๗๖๖๗

Inspection by General Manager



Exit Lighting Inspection

Month : October 2024

Overview Inspection Report

No.	Description		Checklist		
Building		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
1	Front of Engineer Department	1	✓		
2	Front of Entrance	1	✓		
3	Front of Exit Door	1	✓		
4	Front of Exit Way	1	✓		
Gst Floor.		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
5	Entrance eascalator	1	✓		
6	Entrance to locker	1	✓		
7	Locker Exit	1	✓		
8	Front of restroom	1	✓		
9	Exit way besside restroom	1	✓		
10	Front of exit door	1	✓		
1st Floor.		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
11	Entrance lobby	1	✓		
12	T-Café	1	✓		
13	Bar behind fron desk	1	✓		
14	Exit Door (Pool)	1	✓		
15	Front of waterfall	1	✓		
16	Front of T-station	1	✓		
2nd Floor.		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
17	Exit Door บันไดหนีไฟ(ฝั่งPool)	1	✓		
18	ExitDoor บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
Floor Inspection		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
26	Exit Door Floor.3 บันไดหนีไฟ(ฝั่งPool)	1	✓		
27	Exit Door Floor.3 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
28	Exit Door Floor.4 บันไดหนีไฟ(ฝั่งPool)	1	✓		
29	Exit Door Floor.4 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
30	Exit Door Floor.5 บันไดหนีไฟ(ฝั่งPool)	1	✓		
31	Exit Door Floor.5 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
32	Exit Door Floor.6 บันไดหนีไฟ(ฝั่งPool)	1	✓		
33	Exit Door Floor.6 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
34	Exit Door Floor.7 บันไดหนีไฟ(ฝั่งPool)	1	✓		
35	Exit Door Floor.7 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
36	Exit Door Floor.8 บันไดหนีไฟ(ฝั่งPool)	1	✓		
37	Exit Door Floor.8 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
38	Exit Door Floor.9 บันไดหนีไฟ(ฝั่งPool)	1	✓		
39	Exit Door Floor.9 บันไดหนีไฟ(ฝั่งKitchen)	1	✓		
Roof top Floor Inspection		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ
Other Focus EHCM		จำนวน/หลอด	ปกติ/หลอด	ไม่ปกติ/หลอด	หมายเหตุ

REMARK : รวมทั้งหมด 39 เครื่อง ปกติ เครื่อง *เสีย เครื่อง

Inspection by 1.

Inspection by 2.

Verify by Chief ENG/Asst. Chief ENG(Engineering)

Inspection by General Manager

ภาคผนวก ค8

เอกสารทดสอบสัญญาณ Fire Alarm





FIRE ALARM TESTING CHECKLIST

Activated by: ☒ Automatic System ☐ Manual System


Date: 01 July 2024 Time: 14.00 hrs.

STEP Testing

1. Select location as required (Floor#5)
 - Room 407 - Room 523-2
 - Room 522 - Room 624-1
 - Room 523-1 - Room 624-2
 2. Using smoke detector tester spray, direct spraying to smoke detector.
 3. Waiting smoke detector activate, light blinking green to be red.
 4. Fire alarm control panel (FCP) at Control room is status checking.
 5. Graphic annunciator status checking.
 6. Let other devices responding, strobe light, buzzer, evacuation announcement 2 languages. (Chose silence mode to all sound active)
 7. Log record by Staff prepared in area.
 8. Reset alarm back to normal operation.
-

Room 407


Location / Dectector
activated



Fire Control Panel



Annunciator



Room 522


Location / Dectector
activated



Fire Control Panel





Annunciator



Room 523-1


Location / Dectector
activated



Fire Control Panel





Annunciator



Room 523-2


Location / Dectector
activated



Fire Control Panel




Annunciator




Room 624-1


Location / Dectector
activated



Fire Control Panel



Annunciator



Floor	Location	Public Area	Strobe light	Bell	Pull Alarm	Remark
4	Room 407	-	YES	-	-	
4	Room 522	-	YES	-	-	
4	Room 523-1	-	YES	-	-	
4	Room 523-2	-	YES	-	-	
5	Room 624-1	-	YES	-	-	

FCP	LED	Buzzer	Power		AC		Trouble		Alarm		Disable	
			On	Off	On	Off	On	Off	On	Off	On	Off
DZ4#5 (407)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ5#21 (522)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ5#25 (523-1)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ5#24 (523-2)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ6#22 (624)	YES	YES	/	-	/	-	/	-	/	-	-	/

Tested by: Mr. Banbhot Sunyaphap (Security Officer)

Mr.Adipong Pareesen (Security Supervisor)

(01 July 2024)

Report by: Mr. Prasit Inta (Security Supervisor)

(03 July 2024)



FIRE ALARM TESTING CHECKLIST

Activated by: ☒ Automatic System ☐ Manual System



Date: 01 August 2024 Time: 17.40 hrs.

STEP Testing

1. Select location as required (Floor# B & Floor# G)
 - Fire Staircases B ST-1 - Fire Staircases G ST-2
 - Fire Staircases B ST-2
 - Fire Staircases G ST-1
 2. Using smoke detector tester spray, direct spraying to smoke detector.
 3. Waiting smoke detector activate, light blinking green to be red.
 4. Fire alarm control panel (FCP) at Control room is status checking.
 5. Graphic annunciator status checking.
 6. Let other devices responding, strobe light, buzzer, evacuation announcement 2 languages. (Chose silence mode to all sound active)
 7. Log record by Staff prepared in area.
 8. Reset alarm back to normal operation.
-

Fire Staircases B ST1


Location / Dectector
activated



Fire Control Panel




Annunciator



Fire Staircases B ST2


**Location / Dectector
activated**



Fire Control Panel



Annunciator



Fire Staircases G ST1


**Location / Dectector
activated**



Fire Control Panel




Annunciator



Fire Staircases G ST2


Location / Dectector
activated



Fire Control Panel



Annunciator



Floor	Location	Public Area	Strobe light	Bell	Pull Alarm	Remark
B	Fire Staircases B ST1	YES	YES	-	-	
B	Fire Staircases B ST2	YES	YES	-	-	
G	Fire Staircases G ST1	YES	YES	-	-	
G	Fire Staircases G ST2	YES	YES	-	-	

FCP	LED	Buzzer	Power		AC		Trouble		Alarm		Disable	
			On	Off	On	Off	On	Off	On	Off	On	Off
DZB#2 (B ST1)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZB#1 (B ST2)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZB#2 (G ST1)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZB#1 (G ST2)	YES	YES	/	-	/	-	/	-	/	-	-	/

Tested by: Mr. Banbhot Sunyaphap (Security Officer)

Mr. Supanut Sikanta (Security Officer)

Report by: Mr. Banbhot Sunyaphap (Security Officer))

(01 August 2024)

Verified by: Mr. Prasit Inta (Security Supervisor)

(3 August 2024)



FIRE ALARM TESTING CHECKLIST

Activated by: ☐ / Automatic System ☐ Manual System

Date: 02 September 2024 Time: 14.00 hrs.

STEP Testing

1. Select location as required (Floor. 3-4-5-6-7)
 - Room 315 - Room 622
 - Room 418 - Room 720
 - Room 518
 2. Using smoke detector tester spray, direct spraying to smoke detector.
 3. Waiting smoke detector activate, light blinking green to be red.
 4. Fire alarm control panel (FCP) at Control room is status checking.
 5. Graphic annunciator status checking.
 6. Let other devices responding, strobe light, buzzer, evacuation announcement 2 languages. (Chose silence mode to all sound active)
 7. Log record by Staff prepared in area.
 8. Reset alarm back to normal operation.
-

Room 315


Location / Dectector
activated



Fire Control Panel




Annunciator



Room 418


Location / Dectector
activated



Fire Control Panel



Annunciator



Room 518


Location / Dectector
activated



Fire Control Panel



Annunciator



Room 622


Location / Dectector
activated



Fire Control Panel



Annunciator



Room 720


Location / Dectector
activated



Fire Control Panel



Annunciator



Floor	Location	Public Area	Strobe light	Bell	Pull Alarm	Remark
3	Room 315	-	YES	-	-	
4	Room 418	-	YES	-	-	
5	Room 518	-	YES	-	-	
6	Room 622	-	YES	-	-	
7	Room 720	-	YES	-	-	

FCP	LED	Buzzer	Power		AC		Trouble		Alarm		Disable	
			On	Off	On	Off	On	Off	On	Off	On	Off
DZ3#2 (315)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ4#19 (418)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ5#19 (518)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ6#21 (622)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ7#21 (720)	YES	YES	/	-	/	-	/	-	/	-	-	/

Tested by: Mr. Banbhot Sunyaphap (Security Officer)
 Mr. Adipong Pareesen (Security Supervisor)
Report by: Mr. Banbhot Sunyaphap (Security Officer))
 (02 September 2024)
Verified by: Mr. Prasit Inta (Security Supervisor)
 (04 September 2024)



FIRE ALARM TESTING CHECKLIST

Activated by: ☒ Automatic System ☐ Manual System

Date: 07 October 2024 Time: 14.00 hrs.

STEP Testing

1. Select location as required (Floor#4/5/7)
 - Room 417 - Room 707
 - Room 511 - Room 710
 - Room 521 - Room 711
 2. Using smoke detector tester spray, direct spraying to smoke detector.
 3. Waiting smoke detector activate, light blinking green to be red.
 4. Fire alarm control panel (FCP) at Control room is status checking.
 5. Graphic annunciator status checking.
 6. Let other devices responding, strobe light, buzzer, evacuation announcement 2 languages. (Chose silence mode to all sound active)
 7. Log record by Staff prepared in area.
 8. Reset alarm back to normal operation.
-

Room 417


Location / Dectector
activated



Fire Control Panel




Annunciator



Room 511


Location / Dectector
activated



Fire Control Panel




Annunciator



Room 521


Location / Dectector
activated



Fire Control Panel




Annunciator



Room 707


Location / Dectector
activated



Fire Control Panel



Annunciator



Room 710


Location / Dectector
activated



Fire Control Panel




Annunciator



Room 711


**Location / Dectector
activated**



Fire Control Panel



Annunciator



Floor	Location	Public Area	Strobe light	Bell	Pull Alarm	Remark
4	Room 417	-	YES	-	-	
5	Room 511	-	YES	-	-	
5	Room 521	-	YES	-	-	
7	Room 707	-	YES	-	-	
7	Room 710	-	YES	-	-	
7	Room 711	-	YES	-	-	

FCP	LED	Buzzer	Power		AC		Trouble		Alarm		Disable	
			On	Off	On	Off	On	Off	On	Off	On	Off
DZ4#18 (417)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ5#3 (511)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ5#26 (521)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ7#6 (707)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ7#15 (710)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ7#4 (711)	YES	YES	/	-	/	-	/	-	/	-	-	/

Tested by: Mr. Pratchayarat Thongdee (Security Officer)

Mr . Supanut Sikanta (Security Officer)

(07 October 2024)

Report by: Mr. Prasit Inta (Security Supervisor)

(07 October 2024)



FIRE ALARM TESTING CHECKLIST

Activated by: ☒ Automatic System ☐ Manual System

Date: 04 November 2024 Time: 14.00 hrs.

STEP Testing

1. Select location as required (Floor. 4-6-7)
 - Room 402 - Room 615/2
 - Room 602 - Room 707
 - Room 615/1
 2. Using smoke detector tester spray, direct spraying to smoke detector.
 3. Waiting smoke detector activate, light blinking green to be red.
 4. Fire alarm control panel (FCP) at Control room is status checking.
 5. Graphic annunciator status checking.
 6. Let other devices responding, strobe light, buzzer, evacuation announcement 2 languages. (Chose silence mode to all sound active)
 7. Log record by Staff prepared in area.
 8. Reset alarm back to normal operation.
-

Room 402


Location / Dectector
activated



Fire Control Panel




Annunciator



Room 602


Location / Detector
activated



Fire Control Panel



Annunciator



Room 615/1


Location / Dectector
activated



Fire Control Panel



Annunciator



Room 615/2


Location / Dectector
activated



Fire Control Panel




Annunciator



Room 707


Location / Detector activated



Fire Control Panel



Annunciator



Floor	Location	Public Area	Strobe light	Bell	Pull Alarm	Remark
4	Room 402	-	YES	-	-	
6	Room 602	-	YES	-	-	
6	Room 615/1	-	YES	-	-	
6	Room 615/2	-	YES	-	-	
7	Room 707	-	YES	-	-	

FCP	LED	Buzzer	Power		AC		Trouble		Alarm		Disable	
			On	Off	On	Off	On	Off	On	Off	On	Off
DZ4#10 (402)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ6#10 (602)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ6#2 (605/1)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ6#2 (615/2)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZ7#6 (707)	YES	YES	/	-	/	-	/	-	/	-	-	/

Tested by: Mr. Pratchayarat Thongdee (Security officer)
 Mr. Adipong Pareesen (Security Supervisor)
Report by: Mr. Prasit Inta (Security Supervisor)
 (04 November 2024)
Verified by: Mr. Prasit Inta (Security Supervisor)
 (04 November 2024)



FIRE ALARM TESTING CHECKLIST

Activated by: ☒ Automatic System ☐ Manual System


Date: 03 December 2024 Time: 16.30 hrs.

STEP Testing

1. Select location as required (Floor.B)
 - Canteen Room
 - Lift service B
 - Lift staff B
 - Fire staircase 2 B
 2. Using smoke detector tester spray, direct spraying to smoke detector.
 3. Waiting smoke detector activate, light blinking green to be red.
 4. Fire alarm control panel (FCP) at Control room is status checking.
 5. Graphic annunciator status checking.
 6. Let other devices responding, strobe light, buzzer, evacuation announcement 2 languages. (Chose silence mode to all sound active)
 7. Log record by Staff prepared in area.
 8. Reset alarm back to normal operation.
-

Canteen Room


**Location / Dectector
activated**



Fire Control Panel




Annunciator



Lift service B


**Location / Dectector
activated**



Fire Control Panel



Annunciator



Lift staff B


**Location / Dectector
activated**



Fire Control Panel





Annunciator



Fire staircase 2 B


**Location / Dectector
activated**



Fire Control Panel



Annunciator



Floor	Location	Public Area	Strobe light	Bell	Pull Alarm	Remark
B	Canteen Room	-	YES	-	-	
B	Lift service B	-	YES	-	-	
B	Lift staff B	-	YES	-	-	
B	Fire staircase 2 B	-	YES	-	-	โซนกรู๊ป

FCP	LED	Buzzer	Power		AC		Trouble		Alarm		Disable	
			On	Off	On	Off	On	Off	On	Off	On	Off
DZB#3 (Canteen)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZB#7 (Lift service B)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZB#8 (Lift staff B)	YES	YES	/	-	/	-	/	-	/	-	-	/
DZB#1 (Fire staircase 2 B)	YES	YES	/	-	/	-	/	-	/	-	-	/

Tested by: Mr. Prasit Inta
Mr. Adipong Pareesen

Report by: Mr. Prasit Inta
(03 December 2024)

Verified by: Mr. Prasit Inta
(03 December 2024)

(Security Supervisor)

(Security Supervisor)

(Security Supervisor)

(Security Supervisor)

ภาคผนวก ค9

เอกสารตรวจสอบถังดับเพลิง Extinguisher





Fire Pump Rooms Check list

DATE	Time Check (06:00<T<08.00 hrs.)								Time Check (14:00<T<16.00 hrs.)							
	Fire Pump		Water Tank		Sump Pump		Record By	Fire Pump		Water Tank		Sump Pump		Record By		
	Battery	Plant	อุปกรณ์	ระดับน้ำ	วาล์ว	มอเตอร์		อุปกรณ์	Battery	Plant	อุปกรณ์	ระดับน้ำ	วาล์ว		มอเตอร์	อุปกรณ์
	จลนวัต (V)	สถานะ/เงื่อนไข	พารามิเตอร์	ระดับน้ำ (H ₁ ,H ₂ ,L)	พารามิเตอร์	สถานะ/เงื่อนไข		พารามิเตอร์	จลนวัต (V)	สถานะ/เงื่อนไข	พารามิเตอร์	ระดับน้ำ (H ₁ ,H ₂ ,L)	พารามิเตอร์		สถานะ/เงื่อนไข	พารามิเตอร์
1	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
2	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
3	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
4	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
5	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
6	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
7	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
8	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
9	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
10	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
11	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
12	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
13	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
14	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
15	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
16	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
17	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
18	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
19	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
20	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
21	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
22	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
23	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
24	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
25	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
26	10.8/13.5	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
27	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
28	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
29	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13.0	✓	✓	N	✓	✓	✓	ม.ก.ม.
30	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.
31	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.	12.7/13	✓	✓	N	✓	✓	✓	ม.ก.ม.

Note;

Review by Technical Supervisor

Signature

Date

31/7/24

Verify by Chief

Signature

Date

31/7/24



Fire Pump Rooms Check list

DATE	Time Check (06:00<T<08.00 hrs.)								Record By	Time Check (14:00<T<16.00 hrs.)								Record By
	Fire Pump			Water Tank		Sump Pump				Fire Pump			Water Tank		Sump Pump			
	Battery	Plant	อุปกรณ์	ระดับน้ำ	วาล์ว	มอเตอร์	อุปกรณ์	Battery		Plant	อุปกรณ์	ระดับน้ำ	วาล์ว	มอเตอร์	อุปกรณ์			
	จลนพลวัต (V)	สถานะ/เตรียมพร้อม	ทำงานปกติ	ระดับน้ำ (H,N,L)	ทำงานปกติ	สถานะ/เตรียมพร้อม	ทำงานปกติ	จลนพลวัต (V)		สถานะ/เตรียมพร้อม	ทำงานปกติ	ระดับน้ำ (H,N,L)	ทำงานปกติ	สถานะ/เตรียมพร้อม	ทำงานปกติ			
1	0.1/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	Ball		
2	01/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	Ball		
3	01/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	Ball		
4	01/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	Ball		
5	01/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	Ball		
6	01/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	Ball		
7	01/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	Ball		
8	01/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	Ball		
9	01/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	Ball		
10	01/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	on		
11	01/13.0	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	on		
12	01/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	on		
13	01/13	/	/	N	/	/	/	ก	01/13	/	/	N	/	/	/	Ball		
14	01/13	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
15	12.8/13	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
16	12.8/13.0	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
17	12.8/13.0	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
18	12.8/13	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	on		
19	12.8/13	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	on		
20	12.8/13	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
21	12.8/13	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
22	12.8/13	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
23	12.8/13.0	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
24	12.8/13	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
25	12.8/13.0	/	/	N	/	/	/	ก	12.8/13.0	/	/	N	/	/	/	on		
26	12.8/13.0	/	/	N	/	/	/	ก	12.8/13.0	/	/	N	/	/	/	on		
27	12.8/13.0	/	/	N	/	/	/	ก	12.8/13.0	/	/	N	/	/	/	Ball		
28	12.8/13	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
29	12.8/13	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
30	12.8/13.0	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		
31	12.8/13	/	/	N	/	/	/	ก	12.8/13	/	/	N	/	/	/	Ball		

Note: Battery No. 1 (Alarm Fail) : 27/07/2024

14/8/24 battery 1

Review by Technical Supervisor

Signature

Date

Verify by Chief ENG/Asst.Chief ENG(Engineering)

Signature

Date



Fire Pump Rooms Check list

DATE	Time Check (06:00<T<08.00 hrs.)								Time Check (14:00<T<16.00 hrs.)									
	Fire Pump			Water Tank		Sump Pump			Record By	Fire Pump			Water Tank		Sump Pump			Record By
	Battery	Plant	อุปกรณ์	ระดับน้ำ	การวัด	อุปกรณ์	อุปกรณ์	Battery		Plant	อุปกรณ์	ระดับน้ำ	การวัด	อุปกรณ์	อุปกรณ์			
	จลนวัต (V)	สถานะ/เงื่อนไข	พารามิเตอร์	ระดับน้ำ (H ₁ ,H ₂ ,L)	พารามิเตอร์	สถานะ/เงื่อนไข	พารามิเตอร์	จลนวัต (V)		สถานะ/เงื่อนไข	พารามิเตอร์	ระดับน้ำ (H ₁ ,H ₂ ,L)	พารามิเตอร์	สถานะ/เงื่อนไข	พารามิเตอร์			
1	12.7/13.0	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
2	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
3	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
4	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	Ban		
5	12.8/13.0	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	Ban		
6	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	Ban		
7	12.7/13.0	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
8	12.7/13.0	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
9	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
10	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
11	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	Ban		
12	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	Ban		
13	12.7/13.0	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	Ban		
14	12.7/13.0	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
15	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
16	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
17	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
18	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	Ban		
19	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	Ban		
20	12.7/13.0	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	Ban		
21	12.7/13.0	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
22	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
23	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
24	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
25	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13.0	✓	✓	N	✓	✓	✓	CK		
26	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	Ban		
27	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	Ban		
28	12.7/13.0	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	CK		
29	12.7/13.0	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	CK		
30	12.7/13	✓	✓	N	✓	✓	✓	CK	12.7/13	✓	✓	N	✓	✓	✓	CK		
31																		

Note;

Review by Technical Supervisor

Signature

Date

Verify by Chief

Signature

Date

CK
30/9/24



Fire Pump Rooms Check list

DATE	Time Check (06:00<T<08.00 hrs.)								Time Check (14:00<T<16.00 hrs.)									
	Fire Pump			Water Tank		Sump Pump			Record By	Fire Pump			Water Tank		Sump Pump			Record By
	Battery	Plant	อุปกรณ์	ระดับน้ำ	วาล์ว	มอเตอร์	อุปกรณ์	Battery		Plant	อุปกรณ์	ระดับน้ำ	วาล์ว	มอเตอร์	อุปกรณ์			
	จลนพลวัต (V)	สถานะ/เงื่อนไข	ทำงานปกติ	ระดับน้ำ (H,M,L)	ทำงานปกติ	สถานะ/เงื่อนไข	ทำงานปกติ	จลนพลวัต (V)		สถานะ/เงื่อนไข	ทำงานปกติ	ระดับน้ำ (H,M,L)	ทำงานปกติ	สถานะ/เงื่อนไข	ทำงานปกติ			
1	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
2	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
3	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
4	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
5	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
6	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
7	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
8	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
9	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
10	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
11	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
12	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
13	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
14	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
15	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
16	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
17	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
18	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
19	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
20	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
21	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
22	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
23	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
24	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
25	12.7/13.0	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
26	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13	✓	✓	N	✓	✓	✓	✓	✓	
27	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
28	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
29	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
30	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13.0	✓	✓	N	✓	✓	✓	✓	✓	
31	12.7/13	✓	✓	N	✓	✓	✓	✓	12.7/13	✓	✓	N	✓	✓	✓	✓	✓	

Note;

Review by Technical Supervisor

Signature

Date

Verify by Chief ENG/Asst. Chief ENG(Engineering)

Signature

Date



November

Fire Pump Rooms Check list

DATE	Time Check (06:00<T<08.00 hrs.)								Record By	Time Check (14:00<T<16.00 hrs.)								Record By
	Fire Pump			Water Tank		Sump Pump				Fire Pump			Water Tank		Sump Pump			
	Battery	Plant	อุปกรณ์	ระดับน้ำ	วาล์ว	มอเตอร์	อุปกรณ์	Battery		Plant	อุปกรณ์	ระดับน้ำ	วาล์ว	มอเตอร์	อุปกรณ์			
	จุดตรวจ (V)	สถานะ/เงื่อนไข	ทำงานปกติ	ระดับน้ำ (H,M,L)	ทำงานปกติ	สถานะ/เงื่อนไข	ทำงานปกติ	จุดตรวจ (V)		สถานะ/เงื่อนไข	ทำงานปกติ	ระดับน้ำ (H,M,L)	ทำงานปกติ	สถานะ/เงื่อนไข	ทำงานปกติ			
1	12.7/12.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
2	12.7/13.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
3	12.7/13.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
4	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
5	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
6	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
7	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
8	12.7/13.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
9	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
10	12.7/13.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
11	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
12	12.7/13.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
13	12.7/13.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
14	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
15	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
16	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
17	12.7/13.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
18	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
19	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
20	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
21	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
22	12.7/13.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
23	12.7/13.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
24	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
25	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
26	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
27	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
28	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
29	12.7/13.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		
30	12.7/13.0	✓	✓	N	✓	✓	✓	พ.อ.สมชาย	12.7/13	✓	✓	N	✓	✓	✓	พ.อ.สมชาย		

Note;

Review by Technical Supervisor

Signature

Date

Verify by Chief ENG/Asst.Chief ENG(Engineering)

Signature

Date

ภาคผนวก ค10

เอกสารตรวจสอบกล้อง CCTV





EASTIN
TAN HOTEL
CHIANG MAI

CCTV SYSTEM CHECKLIST

(SUMMARY MONTHLY) Date Checked 03 July 2024

No.	Floor/Location		Camera Condition				DVR 1-4		Monitor	
			Cleared		Signal		Recording			
			Yes	No	Yes	No	Yes	Day	Clear	Unclear
DVR 1										
1	B	Parking B 8-22	/		/		/	53	/	
2	B	Parking B1-7	/		/		/	53	/	
3	B	Elevator B floor	/		/		/	53	/	
4	B	Entrance office B	/		/		/	53	/	
5	G	Guard House	/		/		/	53	/	
6	G	Garbage room	/		/		/	53	/	
7	G	Parking G floor	/		/		/	53	/	
8	G	Receiving	/		/		/	53	/	
9	G	Lift Lobby G fl.	/		/		/	53	/	
10	G	Finger Point	/		/		/	53	/	
11	G	Entrance G floor	/		/		/	53	/	
12	G	Escalator	/		/		/	53	/	
13	G	Main entrance	/		/		/	53	/	
14	1	Platform	/		/		/	53	/	
15	1	Kitchen	/		/		/	53	/	
16	1	T-Station 1	/		/		/	53	/	
DVR 2										
1	1	T-Station 2	/		/		/	45	/	
2	1	T-Station entrance	/		/		/	45	/	
3	1	Lobby	/		/		/	45	/	
4	1	Reception	/		/		/	45	/	
5	1	T-Café	/		/		/	45	/	
6	2	T-Quarter	/		/		/	45	/	
7	2	T-Quarter storage	/		/		/	45	/	
8	2	Gallery	/		/		/	45	/	
9	2	Gym	/		/		/	45	/	
10	2	Steam, Sauna	/		/		/	45	/	
11	2	Pool 1	/		/		/	45	/	
12	2	Pool 2	/		/		/	45	/	
13	3	3 rd fl. (FST 1)	/		/		/	45	/	
14	3	3 rd fl. (Lift lobby)	/		/		/	45	/	
15	3	3 rd fl. (FST 2)	/		/		/	45	/	
16	4	4 th fl. (FST 1)	/		/		/	45	/	
DVR 3										
1	4	4 th fl. (Lift lobby)	/		/		/	109	/	
2	4	4 th fl. (FST 2)	/		/		/	109	/	
3	5	5 th fl. (FST 1)	/		/		/	109	/	
4	5	5 th fl. (Lift lobby)	/		/		/	109	/	
5	5	5 th fl. (FST 2)	/		/		/	109	/	
6	6	6 th fl. (FST 1)	/		/		/	109	/	
7	6	6 th fl. (Lift lobby)	/		/		/	109	/	
8	6	6 th fl. (FST 2)	/		/		/	109	/	
9	7	7 th fl. (FST 1)	/		/		/	109	/	
10	7	7 th fl. (Lift lobby)	/		/		/	109	/	
11	7	7 th fl. (FST 2)	/		/		/	109	/	
12	8	8 th fl. (FST 1)	/		/		/	109	/	
13	8	8 th fl. (FST 2)	/		/		/	109	/	
14	9	9 th fl. (FST 1)	/		/		/	109	/	
15	9	9 th fl. (FST 2)	/		/		/	109	/	

CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 03 July 2024

4 Monitors

Monitor 1: 16 cameras, New installed on 30 JAN 2021




CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 03 July 2024

Monitor 2: 16 cameras New installed on 31 JAN 2021



CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 03 July 2024

Monitor 3: 16 cameras New installed on 31 JAN 2021
New monitor was changed a new one on 03 July 2023



Monitor 4: 10 Camera no.1-5 New installed on 11 FEB 2021
: Camera no.6-7 New installed on 14 FEB 2021
: Camera no.8-9 New installed on 03 MAR 2021
: Camera no.10 New installed on 12 OCT 2022

CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 03 July 2024



All DVR 1-4

Repairing and Maintenance:

- The monitor no.3 of DVR 3 has been changed a new one on 03 July 2023.
- The monitor is clearly.

Checked by: Mr.Prasit Inta (Security Supervisor) Date: 03 July 2024

Review by: Mr. Prasit Inta (Security Supervisor) Date: 03 July 2024



EASTIN
TAN HOTEL
CHIANG MAI

CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 03 August 2024

No.	Floor/Location		Camera Condition				DVR 1-4		Monitor	
			Cleared		Signal		Recording			
			Yes	No	Yes	No	Yes	Day	Clear	Unclear
DVR 1										
1	B	Parking B 8-22	/		/		/	53	/	
2	B	Parking B1-7	/		/		/	53	/	
3	B	Elevator B floor	/		/		/	53	/	
4	B	Entrance office B	/		/		/	53	/	
5	G	Guard House	/		/		/	53	/	
6	G	Garbage room	/		/		/	53	/	
7	G	Parking G floor	/		/		/	53	/	
8	G	Receiving	/		/		/	53	/	
9	G	Lift Lobby G fl.	/		/		/	53	/	
10	G	Finger Point	/		/		/	53	/	
11	G	Entrance G floor	/		/		/	53	/	
12	G	Escalator	/		/		/	53	/	
13	G	Main entrance	/		/		/	53	/	
14	1	Platform	/		/		/	53	/	
15	1	Kitchen	/		/		/	53	/	
16	1	T-Station 1	/		/		/	53	/	
DVR 2										
1	1	T-Station 2	/		/		/	34	/	
2	1	T-Station entrance	/		/		/	34	/	
3	1	Lobby	/		/		/	34	/	
4	1	Reception	/		/		/	34	/	
5	1	T-Café	/		/		/	34	/	
6	2	T-Quarter	/		/		/	34	/	
7	2	T-Quarter storage	/		/		/	34	/	
8	2	Gallery	/		/		/	34	/	
9	2	Gym	/		/		/	34	/	
10	2	Steam, Sauna	/		/		/	34	/	
11	2	Pool 1	/		/		/	34	/	
12	2	Pool 2	/		/		/	34	/	
13	3	3 rd fl. (FST 1)	/		/		/	34	/	
14	3	3 rd fl. (Lift lobby)	/		/		/	34	/	
15	3	3 rd fl. (FST 2)	/		/		/	34	/	
16	4	4 th fl. (FST 1)	/		/		/	34	/	
DVR 3										
1	4	4 th fl. (Lift lobby)	/		/		/	108	/	
2	4	4 th fl. (FST 2)	/		/		/	108	/	
3	5	5 th fl. (FST 1)	/		/		/	108	/	
4	5	5 th fl. (Lift lobby)	/		/		/	108	/	
5	5	5 th fl. (FST 2)	/		/		/	108	/	
6	6	6 th fl. (FST 1)	/		/		/	108	/	
7	6	6 th fl. (Lift lobby)	/		/		/	108	/	
8	6	6 th fl. (FST 2)	/		/		/	108	/	
9	7	7 th fl. (FST 1)	/		/		/	108	/	
10	7	7 th fl. (Lift lobby)	/		/		/	108	/	
11	7	7 th fl. (FST 2)	/		/		/	108	/	
12	8	8 th fl. (FST 1)	/		/		/	108	/	
13	8	8 th fl. (FST 2)	/		/		/	108	/	
14	9	9 th fl. (FST 1)	/		/		/	108	/	
15	9	9 th fl. (FST 2)	/		/		/	108	/	

CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 03 August 2024

4 Monitors

Monitor 1: 16 cameras, New installed on 30 JAN 2021





EASTIN
TAN HOTEL
CHIANG MAI

CCTV SYSTEM CHECKLIST

(SUMMARY MONTHLY) Date Checked 03 August 2024

Monitor 2: 16 cameras New installed on 31 JAN 2021



CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 03 August 2024

Monitor 3: 16 cameras New installed on 31 JAN 2021
New monitor was changed a new one on 03 July 2023



Monitor 4: 10 Camera no.1-5 New installed on 11 FEB 2021
: Camera no.6-7 New installed on 14 FEB 2021
: Camera no.8-9 New installed on 03 MAR 2021
: Camera no.10 New installed on 12 OCT 2022

CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 03 August 2024



All DVR 1-4

Repairing and Maintenance:

- The monitor no.3 of DVR 3 has been changed a new one on 03 July 2023.
- The monitor is clearly.

Checked by: Mr.Prasit Inta (Security Supervisor) Date: 03 August 2024

Review by: Mr. Prasit Inta (Security Supervisor) Date: 03 August 2024


CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 02 September 2024

No.	Floor/Location		Camera Condition				DVR 1-4		Monitor	
			Cleared		Signal		Recording			
			Yes	No	Yes	No	Yes	Day	Clear	Unclear
DVR 1										
1	B	Parking B 8-22	/		/		/	54	/	
2	B	Parking B1-7	/		/		/	54	/	
3	B	Elevator B floor	/		/		/	54	/	
4	B	Entrance office B	/		/		/	54	/	
5	G	Guard House	/		/		/	54	/	
6	G	Garbage room	/		/		/	54	/	
7	G	Parking G floor	/		/		/	54	/	
8	G	Receiving	/		/		/	54	/	
9	G	Lift Lobby G fl.	/		/		/	54	/	
10	G	Finger Point	/		/		/	54	/	
11	G	Entrance G floor	/		/		/	54	/	
12	G	Escalator	/		/		/	54	/	
13	G	Main entrance	/		/		/	54	/	
14	1	Platform	/		/		/	54	/	
15	1	Kitchen	/		/		/	54	/	
16	1	T-Station 1	/		/		/	54	/	
DVR 2										
1	1	T-Station 2	/		/		/	66	/	
2	1	T-Station entrance	/		/		/	66	/	
3	1	Lobby	/		/		/	66	/	
4	1	Reception	/		/		/	66	/	
5	1	T-Café	/		/		/	66	/	
6	2	T-Quarter	/		/		/	66	/	
7	2	T-Quarter storage	/		/		/	66	/	
8	2	Gallery	/		/		/	66	/	
9	2	Gym	/		/		/	66	/	
10	2	Steam, Sauna	/		/		/	66	/	
11	2	Pool 1	/		/		/	66	/	
12	2	Pool 2	/		/		/	66	/	
13	3	3 rd fl. (FST 1)	/		/		/	66	/	
14	3	3 rd fl. (Lift lobby)	/		/		/	66	/	
15	3	3 rd fl. (FST 2)	/		/		/	66	/	
16	4	4 th fl. (FST 1)	/		/		/	66	/	
DVR 3										
1	4	4 th fl. (Lift lobby)	/		/		/	112	/	
2	4	4 th fl. (FST 2)	/		/		/	112	/	
3	5	5 th fl. (FST 1)	/		/		/	112	/	
4	5	5 th fl. (Lift lobby)	/		/		/	112	/	
5	5	5 th fl. (FST 2)	/		/		/	112	/	
6	6	6 th fl. (FST 1)	/		/		/	112	/	
7	6	6 th fl. (Lift lobby)	/		/		/	112	/	
8	6	6 th fl. (FST 2)	/		/		/	112	/	
9	7	7 th fl. (FST 1)	/		/		/	112	/	
10	7	7 th fl. (Lift lobby)	/		/		/	112	/	
11	7	7 th fl. (FST 2)	/		/		/	112	/	
12	8	8 th fl. (FST 1)	/		/		/	112	/	
13	8	8 th fl. (FST 2)	/		/		/	112	/	
14	9	9 th fl. (FST 1)	/		/		/	112	/	
15	9	9 th fl. (FST 2)	/		/		/	112	/	
16	10	10 th fl.	/		/		/	112	/	

CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 02 September 2024

4 Monitors

Monitor 1: 16 cameras, New installed on 30 JAN 2021



Monitor 2: 16 cameras New installed on 31 JAN 2021



Monitor 3: 16 cameras New installed on 31 JAN 2021
New monitor was changed a new one on 03 July 2023



Monitor 4: 10 Camera no.1-5 New installed on 11 FEB 2021

: Camera no.6-7 New installed on 14 FEB 2021

: Camera no.8-9 New installed on 03 MAR 2021

: Camera no.10 New installed on 12 OCT 2022

CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 02 September 2024



All DVR 1-4

Repairing and Maintenance:

- The monitor no.3 of DVR 3 has been changed a new one on 03 July 2023.
- The monitor is clearly.

Checked by: Mr.Banbhot Sunyaphap (Security Officer) Date: 02 September 2024

Review by: Mr. Prasit Inta (Security Supervisor) Date: 04 September 2024

CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 02 October 2024

No.	Floor/Location		Camera Condition				DVR 1-4		Monitor	
			Cleared		Signal		Recording			
			Yes	No	Yes	No	Yes	Day	Clear	Unclear
DVR 1										
1	B	Parking B 8-22	/		/		/	54	/	
2	B	Parking B1-7	/		/		/	54	/	
3	B	Elevator B floor	/		/		/	54	/	
4	B	Entrance office B	/		/		/	54	/	
5	G	Guard House	/		/		/	54	/	
6	G	Garbage room	/		/		/	54	/	
7	G	Parking G floor	/		/		/	54	/	
8	G	Receiving	/		/		/	54	/	
9	G	Lift Lobby G fl.	/		/		/	54	/	
10	G	Finger Point	/		/		/	54	/	
11	G	Entrance G floor	/		/		/	54	/	
12	G	Escalator	/		/		/	54	/	
13	G	Main entrance	/		/		/	54	/	
14	1	Platform	/		/		/	54	/	
15	1	Kitchen	/		/		/	54	/	
16	1	T-Station 1	/		/		/	54	/	
DVR 2										
1	1	T-Station 2	/		/		/	66	/	
2	1	T-Station entrance	/		/		/	66	/	
3	1	Lobby	/		/		/	66	/	
4	1	Reception	/		/		/	66	/	
5	1	T-Café	/		/		/	66	/	
6	2	T-Quarter	/		/		/	66	/	
7	2	T-Quarter storage	/		/		/	66	/	
8	2	Gallery	/		/		/	66	/	
9	2	Gym	/		/		/	66	/	
10	2	Steam, Sauna	/		/		/	66	/	
11	2	Pool 1	/		/		/	66	/	
12	2	Pool 2	/		/		/	66	/	
13	3	3 rd fl. (FST 1)	/		/		/	66	/	
14	3	3 rd fl. (Lift lobby)	/		/		/	66	/	
15	3	3 rd fl. (FST 2)	/		/		/	66	/	
16	4	4 th fl. (FST 1)	/		/		/	66	/	
DVR 3										
1	4	4 th fl. (Lift lobby)	/		/		/	112	/	
2	4	4 th fl. (FST 2)	/		/		/	112	/	
3	5	5 th fl. (FST 1)	/		/		/	112	/	
4	5	5 th fl. (Lift lobby)	/		/		/	112	/	
5	5	5 th fl. (FST 2)	/		/		/	112	/	
6	6	6 th fl. (FST 1)	/		/		/	112	/	
7	6	6 th fl. (Lift lobby)	/		/		/	112	/	
8	6	6 th fl. (FST 2)	/		/		/	112	/	
9	7	7 th fl. (FST 1)	/		/		/	112	/	
10	7	7 th fl. (Lift lobby)	/		/		/	112	/	
11	7	7 th fl. (FST 2)	/		/		/	112	/	
12	8	8 th fl. (FST 1)	/		/		/	112	/	
13	8	8 th fl. (FST 2)	/		/		/	112	/	
14	9	9 th fl. (FST 1)	/		/		/	112	/	
15	9	9 th fl. (FST 2)	/		/		/	112	/	
16	10	10 th fl.	/		/		/	112	/	

[illegible]

CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 02 October 2024

4 Monitors

Monitor 1: 16 cameras, New installed on 30 JAN 2021



CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 02 October 2024

Monitor 2: 16 cameras New installed on 31 JAN 2021



Monitor 3: 16 cameras New installed on 31 JAN 2021
New monitor was changed a new one on 03 July 2023



Monitor 4: 10 Camera no.1-5 New installed on 11 FEB 2021

: Camera no.6-7 New installed on 14 FEB 2021

: Camera no.8-9 New installed on 03 MAR 2021

: Camera no.10 New installed on 12 OCT 2022



All DVR 1-4

Repairing and Maintenance:

- The monitor no.3 of DVR 3 has been changed a new one on 03 July 2023.
- The monitor is clearly.

Checked by: Mr.Banbhot Sunyaphap (Security Officer) Date: 02 October 2024

Review by: Mr. Prasit Inta (Security Supervisor) Date: 04 October 2024


CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 02 November 2024

No.	Floor/Location		Camera Condition				DVR 1-4		Monitor	
			Cleared		Signal		Recording			
			Yes	No	Yes	No	Yes	Day	Clear	Unclear
DVR 1										
1	B	Parking B 8-22	/		/		/	54	/	
2	B	Parking B1-7	/		/		/	54	/	
3	B	Elevator B floor	/		/		/	54	/	
4	B	Entrance office B	/		/		/	54	/	
5	G	Guard House	/		/		/	54	/	
6	G	Garbage room	/		/		/	54	/	
7	G	Parking G floor	/		/		/	54	/	
8	G	Receiving	/		/		/	54	/	
9	G	Lift Lobby G fl.	/		/		/	54	/	
10	G	Finger Point	/		/		/	54	/	
11	G	Entrance G floor	/		/		/	54	/	
12	G	Escalator	/		/		/	54	/	
13	G	Main entrance	/		/		/	54	/	
14	1	Platform	/		/		/	54	/	
15	1	Kitchen	/		/		/	54	/	
16	1	T-Station 1	/		/		/	54	/	
DVR 2										
1	1	T-Station 2	/		/		/	66	/	
2	1	T-Station entrance	/		/		/	66	/	
3	1	Lobby	/		/		/	66	/	
4	1	Reception	/		/		/	66	/	
5	1	T-Café	/		/		/	66	/	
6	2	T-Quarter	/		/		/	66	/	
7	2	T-Quarter storage	/		/		/	66	/	
8	2	Gallery	/		/		/	66	/	
9	2	Gym	/		/		/	66	/	
10	2	Steam, Sauna	/		/		/	66	/	
11	2	Pool 1	/		/		/	66	/	
12	2	Pool 2	/		/		/	66	/	
13	3	3 rd fl. (FST 1)	/		/		/	66	/	
14	3	3 rd fl. (Lift lobby)	/		/		/	66	/	
15	3	3 rd fl. (FST 2)	/		/		/	66	/	
16	4	4 th fl. (FST 1)	/		/		/	66	/	
DVR 3										
1	4	4 th fl. (Lift lobby)	/		/		/	112	/	
2	4	4 th fl. (FST 2)	/		/		/	112	/	
3	5	5 th fl. (FST 1)	/		/		/	112	/	
4	5	5 th fl. (Lift lobby)	/		/		/	112	/	
5	5	5 th fl. (FST 2)	/		/		/	112	/	
6	6	6 th fl. (FST 1)	/		/		/	112	/	
7	6	6 th fl. (Lift lobby)	/		/		/	112	/	
8	6	6 th fl. (FST 2)	/		/		/	112	/	
9	7	7 th fl. (FST 1)	/		/		/	112	/	
10	7	7 th fl. (Lift lobby)	/		/		/	112	/	
11	7	7 th fl. (FST 2)	/		/		/	112	/	
12	8	8 th fl. (FST 1)	/		/		/	112	/	
13	8	8 th fl. (FST 2)	/		/		/	112	/	
14	9	9 th fl. (FST 1)	/		/		/	112	/	
15	9	9 th fl. (FST 2)	/		/		/	112	/	
16	10	10 th fl.	/		/		/	112	/	

[illegible]


4 Monitors

Monitor 1: 16 cameras, New installed on 30 JAN 2021



CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 02 November 2024

Monitor 2: 16 cameras New installed on 31 JAN 2021




Monitor 3: 16 cameras New installed on 31 JAN 2021
New monitor was changed a new one on 03 July 2023



Monitor 4: 10 Camera no.1-5 New installed on 11 FEB 2021
: Camera no.6-7 New installed on 14 FEB 2021
: Camera no.8-9 New installed on 03 MAR 2021
: Camera no.10 New installed on 12 OCT 2022

CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 02 November 2024



All DVR 1-4

Repairing and Maintenance:

- The monitor no.3 of DVR 3 has been changed a new one on 03 July 2023.
- The monitor is clearly.

Checked by: Mr.Pratchayarat Thongdee (Security Officer) Date: 02 November 2024

Review by: Mr. Prasit Inta (Security Supervisor) Date: 06 November 2024

CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 02 December 2024

No.	Floor/Location		Camera Condition				DVR 1-4		Monitor	
			Cleared		Signal		Recording			
			Yes	No	Yes	No	Yes	Day	Clear	Unclear
DVR 1										
1	B	Parking B 8-22	/		/		/	54	/	
2	B	Parking B1-7	/		/		/	54	/	
3	B	Elevator B floor	/		/		/	54	/	
4	B	Entrance office B	/		/		/	54	/	
5	G	Guard House	/		/		/	54	/	
6	G	Garbage room	/		/		/	54	/	
7	G	Parking G floor	/		/		/	54	/	
8	G	Receiving	/		/		/	54	/	
9	G	Lift Lobby G fl.	/		/		/	54	/	
10	G	Finger Point	/		/		/	54	/	
11	G	Entrance G floor	/		/		/	54	/	
12	G	Escalator	/		/		/	54	/	
13	G	Main entrance	/		/		/	54	/	
14	1	Platform	/		/		/	54	/	
15	1	Kitchen	/		/		/	54	/	
16	1	T-Station 1	/		/		/	54	/	
DVR 2										
1	1	T-Station 2	/		/		/	66	/	
2	1	T-Station entrance	/		/		/	66	/	
3	1	Lobby	/		/		/	66	/	
4	1	Reception	/		/		/	66	/	
5	1	T-Café	/		/		/	66	/	
6	2	T-Quarter	/		/		/	66	/	
7	2	T-Quarter storage	/		/		/	66	/	
8	2	Gallery	/		/		/	66	/	
9	2	Gym	/		/		/	66	/	
10	2	Steam, Sauna	/		/		/	66	/	
11	2	Pool 1	/		/		/	66	/	
12	2	Pool 2	/		/		/	66	/	
13	3	3 rd fl. (FST 1)	/		/		/	66	/	
14	3	3 rd fl. (Lift lobby)	/		/		/	66	/	
15	3	3 rd fl. (FST 2)	/		/		/	66	/	
16	4	4 th fl. (FST 1)	/		/		/	66	/	
DVR 3										
1	4	4 th fl. (Lift lobby)	/		/		/	112	/	
2	4	4 th fl. (FST 2)	/		/		/	112	/	
3	5	5 th fl. (FST 1)	/		/		/	112	/	
4	5	5 th fl. (Lift lobby)	/		/		/	112	/	
5	5	5 th fl. (FST 2)	/		/		/	112	/	
6	6	6 th fl. (FST 1)	/		/		/	112	/	
7	6	6 th fl. (Lift lobby)	/		/		/	112	/	
8	6	6 th fl. (FST 2)	/		/		/	112	/	
9	7	7 th fl. (FST 1)	/		/		/	112	/	
10	7	7 th fl. (Lift lobby)	/		/		/	112	/	
11	7	7 th fl. (FST 2)	/		/		/	112	/	
12	8	8 th fl. (FST 1)	/		/		/	112	/	
13	8	8 th fl. (FST 2)	/		/		/	112	/	
14	9	9 th fl. (FST 1)	/		/		/	112	/	
15	9	9 th fl. (FST 2)	/		/		/	112	/	
16	10	10 th fl.	/		/		/	112	/	

4 Monitors

Monitor 1: 16 cameras, New installed on 30 JAN 2021



Monitor 2: 16 cameras New installed on 31 JAN 2021



CCTV SYSTEM CHECKLIST
(SUMMARY MONTHLY) Date Checked 02 December 2024

Monitor 3: 16 cameras New installed on 31 JAN 2021
New monitor was changed a new one on 03 July 2023




Monitor 4: 10 Camera no.1-5 New installed on 11 FEB 2021

: Camera no.6-7 New installed on 14 FEB 2021

: Camera no.8-9 New installed on 03 MAR 2021

: Camera no.10 New installed on 12 OCT 2022



All DVR 1-4

Repairing and Maintenance:

- The monitor no.3 of DVR 3 has been changed a new one on 03 July 2023.
- The monitor is clearly.

Checked by: Mr.Pratchayarat Thongdee (Security Officer) Date: 02 December 2024

Review by: Mr. Prasit Inta (Security Supervisor) Date: 05 December 2024

ภาคผนวก ค 11

บันทึกการทดสอบปั้มนดับเพลิง Fire Pump



Fire pump weekly test run report



TECHNICAL DATA

Unit Type : FIRE PUMP ENGINE

Brand: PATTERSON FIRE PUMP

TYPE : HORIZONTAL SPILT CASE SINGLE STARE

MOD: 5x4x12 SSC

Serial No. : FP-C0124559

RPM : 3000

Location : PUMP ROOM

PUMP : JOHN DEERE

GPM : 750

Rate Rang PSI : 88-207 Max 400

Kw , HP : 108,145

Month : July 2024

EASTIN TAN HOTEL CHIANGMAI									
Date check		3/7/24	10/7/24	17/7/24	24/7/24	31/7/24	Note		
Before start engine									
Fuel litres // ระดับน้ำมันเชื้อเพลิง (3/4)		540	640	540	540	540			
Oil engine // ระดับน้ำมันหล่อลื่น		OK	OK	OK	OK	OK			
Water coolant / ระดับน้ำหล่อเย็น		OK	OK	OK	OK	OK			
Distill water/ระดับน้ำกลั่นแบตเตอรี่(ท่วมแผ่นธาตุ)		OK	OK	OK	OK	OK			
DC Volt	Battery 1	13.0	13.0	13.0	13.0	13.0			
	Battery 2	13.4	13.4	13.4	13.4	13.4			
Water leak / น้ำรั่ว		NO	NO	NO	NO	NO			
Oil leak / น้ำมันรั่ว		NO	NO	NO	NO	NO			
Clean housing / ทำความสะอาดเครื่อง		OK	OK	OK	OK	OK			
Test run									
Easy to start		OK	OK	OK	OK	OK			
Oil pressure PSI / แรงดันน้ำมันหล่อลื่น		76	75	75	75	75			
Oil temp. / อุณหภูมิน้ำมันหล่อลื่น		175	175	175	175	175			
Coolant / ระบบหล่อเย็น		OK	OK	OK	OK	OK			
RPM/min / ความเร็วรอบเครื่องยนต์ 3,000 RPM.		3100	3100	3100	3100	3100			
Water Supply / แรงดันน้ำออก.....PSI		180	180	180	180	180			
Period (Min.)/จำนวนเวลา(นาที)		10	10	10	10	10			
After test run									
Switch in auto / เช็ควาล์วสวิตช์ ออโต้		OK	OK	OK	OK	OK			
Engine running hrs / ชั่วโมงการทำงาน		30.00	30.00	30.00	30.42	30.00			
Alarm fault / สถานะ อาราม		OK	OK	OK	OK	OK			
En.Sign / ลงชื่อ									

Note;

Verify by Chief ENG/Asst.Chief ENG(Engineering)

Signature

Date

31/8/24

Fire pump weekly test run report



TECHNICAL DATA

Unit Type : FIRE PUMP ENGINE

Brand:PATTERSON FIRE PUMP

TYPE :HORIZONTAL SPILT CASE SINGLE STARE

MOD:5x4x12 SSC

Serial No. :FP-C0124559

RPM :3000

Location : PUMP ROOM

PUMP : JOHN DEERE

GPM : 750

Rate Rang PSI : 88-207 Max 400

Kw , HP : 108,145

Month : August 2024

EASTIN TAN HOTEL CHIANGMAI									
Date check		8/24	14/8/24	21/8/24	28/8/24				Note
Before start engine									
Fuel litres // ระดับน้ำมันเชื้อเพลิง (3/4)		520	520	520	520				
Oil engine // ระดับน้ำมันหล่อลื่น		OK	OK	OK	OK				
Water coolant / ระดับน้ำหล่อเย็น		OK	OK	OK	OK				
Distill water/ระดับน้ำกลั่นแบตเตอรี่(ท่วมแผ่นธาตุ)		OK	OK	OK	OK				
DC Volt	Battery 1	12.8	12.8	12.9	12.8				
	Battery 2	13.0	13.0	13.0	13.0				
Water leak / น้ำรั่ว		OK	OK	OK	OK				
Oil leak / น้ำมันรั่ว		OK	OK	OK	OK				
Clean housing / ทำความสะอาดเครื่อง		OK	OK	OK	OK				
Test run									
Easy to start		OK	OK	OK	OK				
Oil pressure PSI / แรงดันน้ำมันหล่อลื่น		75	75	75	75				
Oil temp. / อุณหภูมิน้ำมันหล่อลื่น		175	175	175	175				
Coolant / ระบบหล่อเย็น		OK	OK	OK	OK				
RPM/min / ความเร็วรอบเครื่องยนต์ 3,000 RPM.		3100	3100	3100	3100				
Water Supply / แรงดันน้ำออก.....PSI		171	171	170	175				
Period (Min.)/จำนวนเวลา(นาที)		10	10	10	10				
After test run									
Switch in auto / เช็คตำแหน่งสวิตช์ ออโต้		OK	OK	OK	OK				
Engine running hrs / ชั่วโมงการทำงาน		34.2	34.3	34.5	34.6				
Alarm fault / สถานะ อาราม		OK	OK	OK	OK				
En.Sign / ลงชื่อ		24/8	24/8	24/8	24/8				

Note;

Verify by Chief ENG/Asst.Chief ENG(Engineering)	
Signature	
Date	

Fire pump weekly test run report

TECHNICAL DATA

Unit Type : FIRE PUMP ENGINE

Brand:PATTERSON FIRE PUMP

TYPE :HORIZOTAL SPILIT CASE SINGLE STARE

MOD:5x4x12 SSC

Serial No. :FP-C0124559

RPM :3000

Location : PUMP ROOM

PUMP : JOHN DEERE

GPM : 750

Rate Rang PSI : 88-207 Max 400

Kw , HP : 108,145



Month : September 2024

EASTIN TAN HOTEL CHIANGMAI									
Date check		09/09/24	11/09/24	14/09/24	25/09/24				Note
Before start engine									
Fuel litres // ระดับน้ำมันเชื้อเพลิง (3/4)		520	920	520	520				
Oil engine // ระดับน้ำมันหล่อลื่น		OK	OK	OK	OK				
Water coolant / ระดับน้ำหล่อเย็น		OK	OK	OK	OK				
Distill water/ระดับน้ำกลั่นแบบเคอร์(ท่วมแผ่นธาตุ)		OK	OK	OK	OK				
DC Volt	Battery 1	12.8	12.8	12.8	12.8				
	Battery 2	13.0	13.0	13.0	13.0				
Water leak / น้ำรั่ว		NO	NO	NO	NO				
Oil leak / น้ำมันรั่ว		NO	NO	NO	NO				
Clean housing / ทำความสะอาดเครื่อง		OK	OK	OK	OK				
Test run									
Easy to start		OK	OK	OK	OK				
Oil pressure PSI / แรงดันน้ำมันหล่อลื่น		70	70	70	70				
Oil temp. / อุณหภูมิน้ำมันหล่อลื่น		180	180	180	180				
Coolant / ระบบหล่อเย็น		OK	OK	OK	OK				
RPM/min / ความเร็วรอบเครื่องยนต์ 3,000 RPM.		3100	3100	3100	3100				
Water Supply / แรงดันน้ำออก.....PSI		180	180	180	180				
Period (Min.)/จำนวนเวลา(นาที)		10	10	10	10				
After test run									
Switch in auto / เช็กด้าแห่งสวิตช์ ออโต้		OK	OK	OK	OK				
Engine running hrs / ชั่วโมงการทำงาน		342	344	344	345				
Alarm fault / สถานะ อาราม		OK	OK	OK	OK				
En.Sign / ลงชื่อ		Kae	ด้าวิน	OK	OK				

Note;

Verify by Chief ENG/Asst.Chief ENG(Engineering)

Signature

Date

[Signature]
30/9/24

Fire pump weekly test run report



TECHNICAL DATA

Unit Type : FIRE PUMP ENGINE

Brand: PATTERSON FIRE PUMP

TYPE : HORIZONTAL SPILT CASE SINGLE STARE

MOD: 5x4x12 SSC

Serial No. : FP-C0124559

RPM : 3000

Location : PUMP ROOM

PUMP : JOHN DEERE

GPM : 750

Rate Rang PSI : 88-207 Max 400

Kw , HP : 108, 145

Month : October

EASTIN TAN HOTEL CHIANGMAI									
Date check		2/10/24	9/10/24	16/10/24	23/10/24	30/10/24			Note
Before start engine									
Fuel litres // ระดับน้ำมันเชื้อเพลิง (3/4)		520	520	520	520	520			
Oil engine // ระดับน้ำมันหล่อลื่น		OK	OK	OK	OK	OK			
Water coolant / ระดับน้ำหล่อเย็น		OK	OK	OK	OK	OK			
Distill water/ระดับน้ำกลั่นแบตเตอรี่(ท่วมแผ่นธาตุ)		OK	OK	OK	OK	OK			
DC Volt	Battery 1	12.8	12.8	12.8	12.8	12.8			
	Battery 2	13.0	13.0	13.0	13.0	13.0			
Water leak / น้ำรั่ว		OK	OK	OK	OK	OK			
Oil leak / น้ำมันรั่ว		OK	OK	OK	OK	OK			
Clean housing / ทำความสะอาดเครื่อง		OK	OK	OK	OK	OK			
Test run									
Easy to start		OK	OK	OK	OK	OK			
Oil pressure PSI / แรงดันน้ำมันหล่อลื่น		75	70	75	75	75			
Oil temp. / อุณหภูมิน้ำมันหล่อลื่น		180	180	180	180	180			
Coolant / ระบบหล่อเย็น		OK	OK	OK	OK	OK			
RPM/min / ความเร็วรอบเครื่องยนต์ 3,000 RPM.		3100	3100	3100	3100	3100			
Water Supply / แรงดันน้ำออก.....PSI		180	180	180	180	180			
Period (Min.) / จำนวนเวลา(นาที)		10	10	10	10	10			
After test run									
Switch in auto / เช็คตำแหน่งสวิตช์ ออโต้		OK	OK	OK	OK	OK			
Engine running hrs / ชั่วโมงการทำงาน		349	348	350	352	352			
Alarm fault / สถานะ อาราม		OK	OK	OK	OK	OK			
En.Sign / ลงชื่อ		จ.จ.ร.ม.	จ.จ.ร.ม.	จ.จ.ร.ม.	จ.จ.ร.ม.	จ.จ.ร.ม.			

Note;

Verify by Chief ENG/Asst.Chief ENG(Engineering)

Signature

Date

[Signature]
31/10/24

Fire pump weekly test run report



TECHNICAL DATA

Unit Type : FIRE PUMP ENGINE

Brand:PATTERSON FIRE PUMP

TYPE :HORIZOTAL SPILIT CASE SINGLE STARE

MOD:5x4x12 SSC

Serial No. :FP-C0124559

RPM :3000

Location : PUMP ROOM

PUMP : JOHN DEERE

GPM : 750

Rate Rang PSI : 88-207 Max 400

Kw , HP : 108,145

Month : November


EASTIN TAN HOTEL CHIANGMAI								
Date check								Note
		6/11/25	13/11/25	20/11/25	27/11/25			
Before start engine								
Fuel litres / ระดับน้ำมันเชื้อเพลิง (3/4)		390	390	390	390			
Oil engine / ระดับน้ำมันหล่อลื่น		OK	OK	OK	OK			
Water coolant / ระดับน้ำหล่อเย็น		OK	OK	OK	OK			
Distill water/ระดับน้ำกลั่นแบตเตอรี่(ท่วมแผ่นธาตุ)		OK	OK	OK	OK			
DC Volt	Battery 1	13.8	12.6	12.8	12.0			
	Battery 2	13.8	13.0	13.0	13.0			
Water leak / น้ำรั่ว		OK	OK	OK	OK			
Oil leak / น้ำมันรั่ว		OK	OK	OK	OK			
Clean housing / ทำความสะอาดเครื่อง		OK	OK	OK	OK			
Test run								
Easy to start		OK	OK	OK	OK			
Oil pressure PSI / แรงดันน้ำมันหล่อลื่น		75	75	75	75			
Oil temp. / อุณหภูมิน้ำมันหล่อลื่น		185	140	185	140			
Coolant / ระบบหล่อเย็น		OK	OK	OK	OK			
RPM/min / ความเร็วรอบเครื่องยนต์ 3,000 RPM.		3100	3105	3105	3105			
Water Supply / แรงดันน้ำออก.....PSI		180	140	180	140			
Period (Min.)/จำนวนเวลา(นาที)		10	10	10	10			
After test run								
Switch in auto / เช็คน้ำมันสวิตช์ อัตโนมัติ		OK	OK	OK	OK			
Engine running hrs / ชั่วโมงการทำงาน		355	355	355	355			
Alarm fault / สถานะ อาราม		OK	OK	OK	OK			
En.Sign / ลงชื่อ		OK	OK	OK	OK			

Note;

Verify by Chief ENG/Asst.Chief ENG(Engineering)

Signature

Date


30/11/25

ภาคผนวก ค12

บันทึกการตรวจสอบสระว่ายน้ำ





July 2024

Swimming pool Log Sheet

DATE	Morning Shift				Afternoon Shift					
	Time Check (07:00<T<09.00 hrs.)				Time Check (18:00<T<20.00 hrs.)			Pool Chemical Dosage on Time (18:00<T<20.00 hrs.)		Record by
	PH	CL	สภาพน้ำในสระ	Record by	PH	CL	สภาพน้ำในสระ			
	(7.2-7.6)	(1-3)	Yes / No		(7.2-7.6)	(1-3)	Yes / No	Chlorine (mg.)	Soda ADD (mg.)	
1	7.4	3.0	Yes	มีทองพ	7.4	3	Yes	-	-	lu
2	7.4	3.0	Yes	มีทองพ	7.4	3	Yes	-	-	lu
3	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	lu
4	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	an
5	7.4	3.0	Yes	มีทองพ	7.4	3	Yes	-	-	an
6	7.4	3.2	Yes	มีทองพ	7.4	2	Yes	5 ลิ้น	-	an 2 ลิ้น
7	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	an
8	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	lu
9	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	lu
10	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	lu
11	7.4	3.0	Yes	มีทองพ	7.4	3	Yes	-	-	lu
12	7.4	3.0	Yes	มีทองพ	7.4	2	Yes	5 ลิ้น	-	an 2 ลิ้น
13	7.4	3.0	Yes	มีทองพ	7.4	3	Yes	-	-	an
14	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	an
15	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	an
16	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	lu
17	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	lu
18	7.4	3	Yes	มีทองพ	7.4	2	Yes	-	-	an
19	7.4	3.0	Yes	มีทองพ	7.4	2	Yes	5 ลิ้น	-	an 2 ลิ้น
20	7.4	3.0	Yes	มีทองพ	7.4	3	Yes	-	-	an
21	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	an
22	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	an
23	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	lu
24	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	lu
25	7.4	3	Yes	มีทองพ	7.4	3	Yes	5 ลิ้น	-	an
26	7.2	3	Yes	มีทองพ	7.4	3	Yes	-	-	an
27	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	an 2 ลิ้น
28	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	an
29	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	an
30	7.4	2	Yes	มีทองพ	7.4	0.5	Yes	300 กรัม	-	lu
31	7.4	3	Yes	มีทองพ	7.4	3	Yes	-	-	lu

Note;

Review by

Signature

August



Swimming pool Log Sheet

DATE	Morning Shift				Afternoon Shift					
	Time Check (07:00<T<09.00 hrs.)				Time Check (18:00<T<20.00 hrs.)			Pool Chemical Dosage on Time (18:00<T<20.00 hrs.)		Record by
	PH	CL	สภาพน้ำในสระ	Record by	PH	CL	สภาพน้ำในสระ			
								(7.2-7.6)	(1-3)	
1	7.4	3	yes	[Signature]	7.4	3	yes	-	-	Ball
2	1.3	3	yes	[Signature]	7.4	0.5	yes	300 กรัม	-	Ball 100 กรัม
3	7.4	3	yes	[Signature]	7.4	3	yes	-	-	Ball
4	7.4	3	yes	[Signature]	7.4	3	yes	-	-	Ball
5	7.4	3	yes	[Signature]	7.4	3	yes	-	-	Ball
6	7.4	3	yes	[Signature]	7.4	0.5	yes	200 กรัม	-	Ball
7	7.4	3	yes	[Signature]	7.4	3	yes	-	-	Ball
8	7.4	3	yes	[Signature]	7.4	3	yes	200 กรัม	-	Ball 100 กรัม
9	7.4	3.0	yes	Monitor	7.4	3	yes	-	-	Ball
10	7.4	3	yes	[Signature]	7.4	3	yes	-	-	on
11	7.4	3.0	yes	Monitor	7.4	3	yes	-	-	on
12	7.4	3	yes	[Signature]	7.4	3	yes	-	-	on
13	7.4	1	yes	[Signature]	7.4	3	yes	300 กรัม	-	Ball
14	7.4	3	yes	[Signature]	7.4	3	yes	-	-	Ball
15	7.4	3	yes	[Signature]	7.4	1.5	yes	200 กรัม	-	Ball 100 กรัม
16	7.4	3.0	yes	Monitor	7.4	3	yes	-	-	Ball
17	7.4	3.0	yes	Monitor	7.4	3	yes	-	-	Ball
18	7.4	3	yes	[Signature]	7.4	3	yes	-	-	on
19	7.4	3	yes	[Signature]	7.4	2	yes	200 กรัม	-	on
20	7.4	3	yes	[Signature]	7.4	3	yes	-	-	Ball
21	7.4	3	yes	[Signature]	7.4	3	yes	-	-	Ball
22	7.4	3	yes	[Signature]	7.4	2	yes	200 กรัม	-	Ball 100 กรัม
23	7.4	3.0	yes	Monitor	7.4	3	yes	-	-	Ball
24	7.4	3	yes	[Signature]	7.4	3	yes	-	-	Ball
25	7.4	3.0	yes	Monitor	7.4	3.0	yes	-	-	on
26	7.4	3.0	yes	Monitor	7.4	3	yes	-	-	Ball
27	7.4	3.0	yes	Monitor	7.4	1	yes	300 กรัม	-	Ball
28	7.4	3	yes	[Signature]	7.4	3	yes	-	-	Ball
29	7.4	3	yes	[Signature]	7.4	3	yes	100 กรัม	-	Ball 100 กรัม
30	7.4	3.0	yes	Monitor	7.4	3	yes	-	-	Ball
31	7.4	3	yes	[Signature]	7.4	3	yes	-	-	Ball

Note;

Review by

Signature



September

Swimming pool Log Sheet

DATE	Morning Shift				Afternoon Shift					
	Time Check (07:00<T<09.00 hrs.)				Time Check (18:00<T<20.00 hrs.)			Pool Chemical Dosage on Time (18:00<T<20.00 hrs.)		Record by
	PH	CL	สภาพน้ำในสระ	Record by	PH	CL	สภาพน้ำในสระ			
	(7.2-7.6)	(1-3)	Yes / No		(7.2-7.6)	(1-3)	Yes / No	Chlorine (mg.)	Soda ADD (mg.)	
1	7.2	3	yes		7.2	1	yes	2 กรัม	-	lu
2	7.2	3	yes		7.2	3	yes	-	-	lu
3	7.2	3	yes		7.2	3	yes	-	-	lu
4	7.2	3	yes		7.2	3	yes	-	-	Ban
5	7.2	3.0	yes	พอรณ	7.2	2	yes	100 กรัม	-	Ban
6	7.2	3	yes		7.2	3	yes	-	-	Ban
7	7.2	3	yes	พอรณ	7.2	3	yes	-	-	lu
8	7.2	3.0	yes	พอรณ	7.2	3	yes	200 กรัม	-	lu
9	7.2	3	yes		7.2	3	yes	-	-	lu
10	7.2	3	yes		7.2	3	yes	-	-	lu
11	7.2	3	yes		7.2	3	yes	-	-	Ban
12	7.2	3	yes		7.2	3	yes	-	-	Ban
13	7.2	3.0	yes	พอรณ	7.2	3	yes	-	-	Ban
14	7.2	3.0	yes	พอรณ	7.2	3	yes	-	-	lu
15	7.2	3.2	yes		7.2	1	yes	200 กรัม	-	lu
16	7.2	2	yes		7.2	2	yes	200 กรัม	-	lu
17	7.2	3	yes		7.2	3	yes	-	-	lu
18	7.2	3	yes		7.2	3	yes	-	-	Ban
19	7.2	3	yes		7.2	3	yes	-	-	Ban
20	7.2	3.0	yes	พอรณ	7.2	3	yes	-	-	Ban
21	7.2	3.0	yes	พอรณ	7.2	3	yes	-	-	lu
22	7.2	2	yes		7.2	1	yes	-	-	lu
23	7.2	3	yes		7.2	3	yes	200 กรัม	-	lu
24	7.2	3	yes		7.2	3	yes	-	-	lu
25	7.2	3	yes		7.2	3	yes	-	-	lu
26	7.2	3	yes		7.2	3	yes	-	-	Ban
27	7.2	3	yes		7.2	3	yes	-	-	Ban
28	7.2	3	yes	lu	7.2	3	yes	-	-	an
29	7.2	3	yes	lu	7.2	3	yes	-	-	an
30	7.2	3	yes		7.2	3	yes	-	-	an
31										

Note;

Review by

Signature



October

Swimming pool Log Sheet

DATE	Morning Shift				Afternoon Shift					
	Time Check (07:00<T<09.00 hrs.)				Time Check (18:00<T<20.00 hrs.)		Pool Chemical Dosage on Time (18:00<T<20.00 hrs.)		Record by	
	PH	CL	สภาพน้ำในสระ	Record by	PH	CL				สภาพน้ำในสระ
	(7.2-7.6)	(1-3)	Yes / No		(7.2-7.6)	(1-3)	Yes / No	Chlorine (mg.)		Soda ADD (mg.)
1	7.2	3	yes	Ch	7.2	3	yes	-	-	en
2	7.2	3	yes	Ch	7.2	3	yes	-	-	en
3	7.2	3.0	yes	Not record	7.2	3	yes	-	-	on
4	7.2	3.0	yes	Not record	7.2	3	yes	1/2 ลิตร	-	on งดใส่ยา
5	7.2	3	yes	BH	7.2	3	yes	-	-	on
6	7.2	3	yes	Ch	7.2	3	yes	-	-	an
7	7.2	3	yes	Ch	7.2	3	yes	-	-	an
8	7.2	3	yes	Ch	7.2	3	yes	-	-	en
9	7.2	3	yes	Ch	7.2	3	yes	-	-	en
10	7.2	2	yes	Ch	7.2	2	yes	-	-	on
11	7.2	3.0	yes	Not record	7.2	2	yes	-	-	on
12	7.2	3.0	yes	Not record	7.2	2	yes	1/2 ลิตร	-	on งดใส่ยา
13	7.2	3	yes	Ch	7.2	3	yes	-	-	on
14	7.2	3	yes	Ch	7.2	3	yes	-	-	an
15	7.2	3	yes	Ch	7.2	3	yes	-	-	en
16	7.2	3.0	yes	Not record	7.2	3	yes	-	-	en
17	7.2	3.0	yes	Not record	7.2	3	yes	-	-	an
18	7.2	3.0	yes	Not record	7.2	2	yes	-	-	on
19	7.2	3.0	yes	en	7.2	2	yes	1/2 ลิตร	-	on งดใส่ยา
20	7.2	3.0	yes	en	7.2	3	yes	-	-	on
21	7.2	3.0	yes	Not record	7.2	3	yes	-	-	an
22	7.2	3.0	yes	Not record	7.2	3	yes	-	-	en
23	7.2	3.0	yes	Not record	7.2	3	yes	-	-	en
24	7.2	3.0	yes	Not record	7.2	3	yes	-	-	an
25	7.2	3.0	yes	Not record	7.2	3	yes	-	-	an
26	7.2	3.2	yes	Ch	7.2	2	yes	1/2 ลิตร	-	an
27	7.2	3	yes	Ch	7.2	3	yes	-	-	an
28	7.2	3	yes	Ch	7.2	3	yes	-	-	en
29	7.2	3	yes	Ch	7.2	3	yes	-	-	en
30	7.2	3	yes	Ch	7.2	3	yes	-	-	en
31	7.2	3	yes	Ch	7.2	3	yes	-	-	BH

Note;

Review by

Signature



Swimming pool Log Sheet

DATE	Morning Shift				Afternoon Shift					
	Time Check (07:00<T<09.00 hrs.)				Time Check (18:00<T<20.00 hrs.)			Pool Chemical Dosage on Time (18:00<T<20.00 hrs.)		Record by
	PH	CL	สภาพน้ำในสระ	Record by	PH	CL	สภาพน้ำในสระ			
	(7.2-7.6)	(1-3)	Yes / No		(7.2-7.6)	(1-3)	Yes / No	Chlorine (mg.)	Soda ADD (mg.)	
1	7.2	3.0	Yes	พอรณ	7.2	3	Yes	-	-	Ball
2	7.2	3.0	Yes	พอรณ	7.2	3	Yes	300 กรัม	-	Ball ๑๓.๕๕
3	7.2	3.0	Yes	ณ	7.2	3	Yes	-	-	Ball
4	7.2	3	Yes	ณ	7.2	3	Yes	-	-	on
5	7.2	3	Yes	ณ	7.2	3	Yes	-	-	on
6	7.2	3	Yes	ณ	7.2	3	Yes	-	-	Ball
7	7.2	3	Yes	ณ	7.2	3	Yes	-	-	Ball
8	7.2	3.0	Yes	พอรณ	7.2	3	Yes	-	-	Ball
9	7.2	3	Yes	ณ	7.2	3	Yes	-	-	Ball
10	7.2	3.0	Yes	พอรณ	7.2	3	Yes	-	-	on
11	7.2	2	Yes	ณ	7.2	2	Yes	300 กรัม	-	on
12	7.2	3	Yes	ณ	7.2	3	Yes	-	-	on
13	7.2	3	Yes	ณ	7.2	3	Yes	-	-	Ball
14	7.2	3	Yes	ณ	7.2	3	Yes	100 กรัม	-	Ball ๑๓.๕๕
15	7.2	3.0	Yes	พอรณ	7.2	3	Yes	-	-	Ball
16	7.2	3	Yes	ณ	7.2	3	Yes	-	-	Ball
17	7.2	3.0	Yes	พอรณ	7.2	3	Yes	-	-	Ball
18	7.2	3	Yes	ณ	7.2	3	Yes	-	-	Ball
19	7.2	3	Yes	ณ	7.2	3	Yes	-	-	on
20	7.2	3	Yes	ณ	7.2	3	Yes	-	-	on
21	7.2	2	Yes	ณ	7.2	2	Yes	-	-	on
22	7.2	3.0	Yes	พอรณ	7.2	2	Yes	๓๐๐ กรัม	-	on
23	7.2	3.0	Yes	พอรณ	7.2	3	Yes	-	-	on
24	7.2	3	Yes	ณ	7.2	3	Yes	-	-	on
25	7.2	3	Yes	ณ	7.2	2	Yes	-	-	Ball
26	7.2	2	Yes	ณ	7.2	2	Yes	-	-	Ball
27	7.2	1	Yes	ณ	7.2	1	Yes	300 กรัม	-	Ball
28	7.2	3	Yes	ณ	7.2	3	Yes	-	-	Ball ๑๓.๕๕
29	7.2	3.0	Yes	พอรณ	7.2	3	Yes	-	-	Ball
30	7.2	3	Yes	ณ	7.2	3	Yes	-	-	on
31										

Note;

Review by

Signature

ภาคผนวก ค13

บันทึกการทดสอบเครื่องกำเนิดไฟฟ้า





MDB Rooms Check List


DATE	Time Check (06:00<T<08.00 hrs.)							Time Check (14:00<T<16.00 hrs.)						
	Generator Room				MDB Room			Generator Room				MDB Room		
	Battery	Main CB	Plant	อุปกรณ์	Plant	อุปกรณ์	Record By	Battery	Main CB	Plant	อุปกรณ์	Plant	อุปกรณ์	Record By
	จดหน่วย (V)	ปกติ ON	สภาวะ/เงื่อนไข	ทำงานปกติ	สภาวะ/เงื่อนไข	ทำงานปกติ		จดหน่วย (V)	ปกติ ON	สภาวะ/เงื่อนไข	ทำงานปกติ	สภาวะ/เงื่อนไข	ทำงานปกติ	
1	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
2	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
3	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
4	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
5	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
6	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
7	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
8	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
9	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
10	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
11	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
12	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
13	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
14	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
15	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
16	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
17	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
18	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
19	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
20	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
21	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
22	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
23	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
24	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
25	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
26	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
27	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
28	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
29	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
30	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ
31	27.0	✓	✓	✓	✓	✓	นพพร	27.0	✓	✓	✓	✓	✓	นพ

Note;

Review by Technical Supervisor

Signature


Date


31/7/24

Verify by Chief ENG/Asst.Chief ENG(Engineering)

Signature

Date


31/7/24



MDB Rooms Check List

DATE	Time Check (06:00<T<08.00 hrs.)							Time Check (14:00<T<16.00 hrs.)						
	Generator Room				MDB Room			Generator Room				MDB Room		
	Battery	Main CB	Plant	อุปกรณ์	Plant	อุปกรณ์	Record By	Battery	Main CB	Plant	อุปกรณ์	Plant	อุปกรณ์	Record By
	จดหน่วย (V)	ปกติ ON	สถานะ/เตรียมพร้อม	ทำงานปกติ	สถานะ/เตรียมพร้อม	ทำงานปกติ		จดหน่วย (V)	ปกติ ON	สถานะ/เตรียมพร้อม	ทำงานปกติ	สถานะ/เตรียมพร้อม	ทำงานปกติ	
1	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
2	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
3	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
4	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
5	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
6	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
7	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
8	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
9	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
10	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
11	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
12	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
13	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
14	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
15	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
16	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
17	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
18	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
19	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
20	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
21	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
22	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
23	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
24	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
25	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
26	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
27	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
28	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
29	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
30	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali
31	27.0	/	/	/	/	/	ดี	27.0	/	/	/	/	/	Bali

Note: 24/08/2024 : ตรวจสอบเวลาประจักษ์ 10:00 น. , สถานะ อุปกรณ์ประจักษ์ระบบไฟฟ้าอาคาร (O&B) ทุกอย่างปกติ
20/08/2024 : ตรวจสอบ PAKORIN Technical and Supply Limited Partner. 19/08/2024 PM 13:20-16:00 น. (13:20 น. + PM 16:00 น.)

Review by Technical Supervisor
Signature
Date

Verify by Chief ENG/Asst.Chief ENG(Engineering)
Signature
Date



MDB Rooms Check List

DATE	Time Check (06:00<T<08.00 hrs.)							Time Check (14:00<T<16.00 hrs.)						
	Generator Room				MDB Room			Generator Room				MDB Room		
	Battery	Main CB	Plant	อุปกรณ์	Plant	อุปกรณ์	Record By	Battery	Main CB	Plant	อุปกรณ์	Plant	อุปกรณ์	Record By
	จลนพลวัต (V)	ปกติ ON	สถานะ/เงื่อนไข	ทำงานปกติ	สถานะ/เงื่อนไข	ทำงานปกติ		จลนพลวัต (V)	ปกติ ON	สถานะ/เงื่อนไข	ทำงานปกติ	สถานะ/เงื่อนไข	ทำงานปกติ	
1	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
2	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
3	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
4	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
5	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
6	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
7	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
8	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
9	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
10	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
11	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
12	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
13	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
14	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
15	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
16	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
17	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
18	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
19	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
20	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
21	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
22	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
23	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
24	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
25	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
26	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
27	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
28	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
29	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
30	27.0	/	/	/	/	/	(Signature)	27.0	/	/	/	/	/	(Signature)
31														

Note;

Review by Technical Supervisor

Signature _____

Date _____

Verify by Chief ENG/Asst.Chief ENG(Engineering)

Signature _____

Date _____



MDB Rooms Check List

DATE	Time Check (06:00<T<08.00 hrs.)							Time Check (14:00<T<16.00 hrs.)						
	Generator Room				MDB Room			Generator Room				MDB Room		
	Battery	Main CB	Plant	อุปกรณ์	Plant	อุปกรณ์	Record By	Battery	Main CB	Plant	อุปกรณ์	Plant	อุปกรณ์	Record By
	จลนพลวัต (V)	ปกติ ON	สถานะ/เงื่อนไข	ทำงานปกติ	สถานะ/เงื่อนไข	ทำงานปกติ		จลนพลวัต (V)	ปกติ ON	สถานะ/เงื่อนไข	ทำงานปกติ	สถานะ/เงื่อนไข	ทำงานปกติ	
1	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
2	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
3	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
4	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
5	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
6	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
7	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
8	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
9	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
10	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
11	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
12	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
13	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
14	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
15	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
16	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
17	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
18	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
19	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
20	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
21	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
22	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
23	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
24	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
25	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
26	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
27	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
28	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
29	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
30	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]
31	27.0	/	/	/	/	/	[Signature]	27.0	/	/	/	/	/	[Signature]

Note;

Review by Technical Supervisor	
Signature	
Date	

Verify by Chief ENG/Asst.Chief ENG(Engineering)	
Signature	
Date	



MDB Rooms Check List

DATE	Time Check (06:00<T<08.00 hrs.)							Time Check (14:00<T<16.00 hrs.)						
	Generator Room				MDB Room			Generator Room				MDB Room		
	Battery	Main CB	Plant	อุปกรณ์	Plant	อุปกรณ์	Record By	Battery	Main CB	Plant	อุปกรณ์	Plant	อุปกรณ์	Record By
	จดหน่วย (V)	ปกติ ON	สถานะ/ เรียบร้อย	ทำงานปกติ	สถานะ/ เรียบร้อย	ทำงานปกติ		จดหน่วย (V)	ปกติ ON	สถานะ/ เรียบร้อย	ทำงานปกติ	สถานะ/ เรียบร้อย	ทำงานปกติ	
1	27.0	✓	✓	✓	✓	✓	พชรพร	27.0	/	/	/	/	/	Ban
2	27.0	✓	✓	✓	✓	✓	พชรพร	27.0	/	/	/	/	/	Ban
3	27.0	✓	✓	/	/	/	ณ	27.0	/	/	/	/	/	Ban
4	27.0	/	✓	✓	✓	/	ณ	27.0	/	/	/	/	/	on
5	27.0	/	✓	/	✓	/	ณ	27.0	/	/	/	/	/	on
6	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	Ban
7	27.0	/	✓	✓	✓	/	ณ	27.0	/	/	/	/	/	Ban
8	27.0	✓	✓	✓	✓	✓	พชรพร	27.0	/	/	/	/	/	Ban
9	27.0	✓	✓	✓	✓	✓	พชรพร	27.0	/	/	/	/	/	Ban
10	27.0	✓	✓	✓	✓	✓	พชรพร	27.0	/	/	/	/	/	on
11	27.0	/	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	on
12	27.0	/	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	on
13	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	Ban
14	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	Ban
15	27.0	✓	✓	✓	✓	✓	พชรพร	27.0	/	/	/	/	/	Ban
16	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	Ban
17	27.0	✓	✓	✓	✓	✓	พชรพร	27.0	/	/	/	/	/	Ban
18	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	Ban
19	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	on
20	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	on
21	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	on
22	27.0	✓	✓	✓	✓	✓	พชรพร	27.0	/	/	/	/	/	on
23	27.0	✓	✓	✓	✓	✓	พชรพร	27.0	/	/	/	/	/	on
24	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	on
25	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	Ban
26	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	Ban
27	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	Ban
28	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	Ban
29	27.0	✓	✓	✓	✓	✓	พชรพร	27.0	/	/	/	/	/	Ban
30	27.0	✓	✓	✓	✓	✓	ณ	27.0	/	/	/	/	/	on
31														

Note;

Review by Technical Supervisor	
Signature	
Date	

Verify by Chief ENG/Asst.Chief ENG(Engineering)	
Signature	
Date	

ภาคผนวก ค14

เอกสารตรวจสอบอุปกรณ์ดับเพลิง



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-B-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close		/											
	No leakage from valve		/											
	No leakage from fire hose/reel		/											
	Water pressure level by setting		/											
	General testing		/											
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Patchayaporn	Patchayaporn	Pasit	Pasit	Banbhot	Banbhot	Patchayaporn	Patchayaporn	Pasit	Pasit	

23/02

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-B-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close		/											
	No leakage from valve		/											
	No leakage from fire hose/reel		/											
	Water pressure level by setting		/											
	General testing		/											
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pattayamon	Pattayamon	Pasit	Pasit	Banbhot	Banbhot	Pattayamon	Pattayamon	Pasit	Pasit	

23/02

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-B-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close		/											
	No leakage from valve		/											
	No leakage from fire hose/reel		/											
	Water pressure level by setting		/											
	General testing		/											
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Ban bhot	Ban bhot	Pasit	Pasit	Pasit	Pasit	Pasit	Pasit	Pasit	Pasit	Pasit	Pasit	

23/02/2024

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-B-05 (Front of Fire)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close		/											
	No leakage from valve		/											
	No leakage from fire hose/reel		/											
	Water pressure level by setting		/											
	General testing		/											
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	Banbhot	

92/61

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-G-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/		/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/		/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/		/	/	/	/	/	/	/	/	/	/	
	Valve condition	/		/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/		/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/		/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/		/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close													
	No leakage from valve													
	No leakage from fire hose/reel													
	Water pressure level by setting													
	General testing													
Keeping after rest	Keeping propery	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propery	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	P.erdchayana	P.erdchayana	Basit	Basit	Banbhot	Banbhot	P.erdchayana	P.erdchayana	Basit	Basit	



Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close													
	No leakage from valve													
	No leakage from fire hose/reel													
	Water pressure level by setting													
	General testing													
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pas/2	Pas/2	Pas/2	Pas/2	Banbhot	Banbhot	Pas/2	Pas/2	Pas/2	Pas/2	

G
23/2/24



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-G-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close	x	/											
	No leakage from valve	x	/											
	No leakage from fire hose/reel	x	/											
	Water pressure level by setting	x	/											
	General testing	x	/											
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Pass 1/2	Barbhot	Pass 1/2	Pass 1/2	Pass 1/2	Pass 1/2	Barbhot	Pass 1/2	Barbhot	Pass 1/2	Pass 1/2	Pass 1/2	

23/2

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-1-01 (Front of Fire Staircase 1)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close									/				
	No leakage from valve									/				
	No leakage from fire hose/reel									/				
	Water pressure level by setting									/				
	General testing									/				
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Pattayarat	Pattayarat	Prasit	Prasit	Banbhot	Banbhot	Pattayarat	Pattayarat	Prasit	Prasit	

8/19/24

1
W2024



FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-1-02 (Front of Fire Staircase 2)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	/	/	/	/	/	/	/	/	/	/	/	/	
	Pipe system cleanness	/	/	/	/	/	/	/	/	/	/	/	/	
	No leakage from pipe system	/	/	/	/	/	/	/	/	/	/	/	/	
	Valve condition	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe and hose reel	/	/	/	/	/	/	/	/	/	/	/	/	
Fire Hose & Fire reel	No damage / lacerate	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition no dry-crisp	/	/	/	/	/	/	/	/	/	/	/	/	
	Joint connect with pipe is durable pull-easily	/	/	/	/	/	/	/	/	/	/	/	/	
	Condition or warer nozzle pull out easily	/	/	/	/	/	/	/	/	/	/	/	/	
Spray Testing	Valve easy to open and close										/			
	No leakage from valve										/			
	No leakage from fire hose/reel										/			
	Water pressure level by setting										/			
	General testing										/			
Keeping after rest	Keeping propey	/	/	/	/	/	/	/	/	/	/	/	/	
	Roll up propey	/	/	/	/	/	/	/	/	/	/	/	/	
Nozzle	Good condition-not break	/	/	/	/	/	/	/	/	/	/	/	/	
Fire extinguisher	Card checked	/	/	/	/	/	/	/	/	/	/	/	/	
	Good condition	/	/	/	/	/	/	/	/	/	/	/	/	
Hydrant	Chain / Cover	/	/	/	/	/	/	/	/	/	/	/	/	
Inspector		Banbhot	Banbhot	Patchayama	Patchayama	Pasit	Pasit	Banbhot	Banbhot	Patchayama	Patchayama	Pasit	Pasit	

8/9/24

FIRE HOSE CABINET MONTHLY INSPECTION 2024 FHC-1-03 (Front of Fire Staircase 3)

Topic Checking	Item Checking	January	February	March	April	May	June	July	August	September	October	November	December	Remark
Main pipe warmer supply	Pipe joint welder is durable	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Pipe system cleanness	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	No leakage from pipe system	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Valve condition	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Joint connect with pipe and hose reel	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Fire Hose & Fire reel	No damage / lacerate	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Good condition no dry-crisp	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Joint connect with pipe is durable pull-easily	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Condition or warer nozzle pull out easily	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Spray Testing	Valve easy to open and close									✓				
	No leakage from valve									✓				
	No leakage from fire hose/reel									✓				
	Water pressure level by setting									✓				
	General testing									✓				
Keeping after rest	Keeping propery	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Roll up propery	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Nozzle	Good condition-not break	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Fire extinguisher	Card checked	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Good condition	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Hydrant	Chain / Cover	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Inspector		Banbhot	Banbhot	Pasit	Pasit	Pasit	Pasit	Banbhot	Banbhot	Pasit	Pasit	Pasit	Pasit	

8/12/24