

**ภาคผนวกที่ 3 รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม
(ตั้งแต่เดือน กรกฎาคม-ธันวาคม 2567)**

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



บริษัท วิศวกรรมเคมี จำกัด
Thai Chemical & Engineering Co., Ltd.

จัดทำที่ : บ.วิศวกรรมเคมี จำกัด
วันที่ 8 กรกฎาคม 2567

บริษัท หัวหิน วิลเลจ จำกัด (โรงแรมอนันตราหัวหิน)
43/1 ถนน เพชรเกษม อำเภอ หัวหิน
จ.ประจวบคีรีขันธ์ 77110

เรื่อง รายงานผลวิเคราะห์คุณภาพน้ำประจำเดือน มิถุนายน 2567
เรียน คุณโอเลียง ชีมี้อง
เอกสารแนบ ผลวิเคราะห์คุณภาพน้ำประจำเดือน

ตามที่บริษัท วิศวกรรมเคมี จำกัด ได้รับมอบหมายให้เก็บตัวอย่างน้ำ เพื่อทำการวิเคราะห์คุณภาพน้ำ
ภายในโรงแรม และระบบหล่อเย็น ที่โรงแรม อนันตรา รีสอร์ท แอนด์ สปา หัวหิน โดยทำการเก็บตัวอย่างน้ำ
ประจำเดือน มิถุนายน 2567 ตั้งแต่วันที่ 28 มิถุนายน 2567 ตัวอย่างน้ำดังนี้

ผลวิเคราะห์เชื้อในระบบ

ตัวอย่างน้ำ	Legionella CFU/Liter	Legionella CFU/ml	Total Coliform	มาตรฐาน Total Coliform	E.Coli	มาตรฐาน E.Coli
1.) บ่อน้ำดิบ	200	0.2	7.8	< 2.2	Negative	Negative
2.) บ่อประปา 5 เหลี่ยม	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
3.) เครื่องทำน้ำแข็ง จุด 1	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
4.) เครื่องทำน้ำแข็ง จุด 2	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
5.) เครื่องทำน้ำแข็ง จุด 3	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
6.) น้ำเย็นห้องพักแขก 402	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
7.) น้ำร้อนห้องพักแขก 402	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
8.) น้ำประปาห้องครัว	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
9.) ถาด Cooling	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
10.) Main Pool	Not Detected	Not Detected	< 2	<10	Negative	Negative
11.) Lagoon Pool	Not Detected	Not Detected	< 2	<10	Negative	Negative

“สร้างความพึงพอใจให้ลูกค้า พัฒนาคุณภาพบริการและผลิตภัณฑ์ สร้างสรรค์บุคลากร”

1048/2 ถนนสุขุมวิท 66/1 แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพฯ 10260 Tel : (66) 0 2744 9911 Fax : (66) 0 2393 0165
1048/2 Sukhumvit 66/1 Road, Prakanong Tai, Prakanong, Bangkok 10260 www.tcesolutions.com E-mail : contact@tcesolutions.com

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



บริษัท วิศวกรรมเคมี จำกัด
Thai Chemical & Engineering Co., Ltd.

ระดับความรุนแรงของเชื้อ Legionella

CFU/ml			ระดับความ น่ากังวล	สิ่งที่ควรปฏิบัติ
น้ำจากหอหล่อเย็น Cooling Tower	น้ำสำหรับ อุปโภค / บริโภค	เครื่องทำความชื้น / เครื่องทำให้เกิดหมอก		
< 1	-	-	ต่ำ	ทบทวนแผนการบำรุงรักษา ให้มีการปฏิบัติเป็นประจำ
1 - 9	< 1	-	น้อย	วิเคราะห์ติดตามผลอย่าง ต่อเนื่อง
10 - 99	1 - 9	<1	ปานกลาง	ทบทวนและตรวจลักษณะ ของอาคารที่อาจเสี่ยงต่อการ ติดเชื้อ
100 - 999	10 - 99	1 - 9	ค่อนข้างสูง	ทำความสะอาดระบบโดยใช้ สารเคมีที่มีความสามารถในการ ฆ่าเชื้อจุลินทรีย์
$\geq 1,000$	>100	>10	มีความรุนแรงสูง	ใช้สารเคมีซึ่งมีความสามารถ ฆ่าเชื้อจุลินทรีย์ชนิดนี้ ใน กระบวนการทำความสะอาด โดยทันที

“สร้างความพึงพอใจให้ลูกค้า พัฒนาคุณภาพบริการและผลิตภัณฑ์ สร้างสรรค์บุคลากร”

1048/2 ถนนสุขุมวิท 66/1 แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพฯ 10260 Tel : (66) 0 2744 9911 Fax : (66) 0 2393 0165
1048/2 Sukhumvit 66/1 Road, Prakanong Tai, Prakanong, Bangkok 10260 www.scesolutions.com E-mail : contact@scsolutions.com

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567

	บริษัท วิศวกรรมเคมี จำกัด THAI CHEMICAL & ENGINEERING CO., LTD.	
	1048/2 ซ.สุขุมวิท 66/1 อ.สุขุมวิท แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพฯ 10260 โทร. 0-2744-9911 แฟกซ์ 0-2393-0165 1048/2 Soi Sukhumvit 66/1, Sukhumvit Rd., Prakanong Tai, Prakanong, Bangkok 10260 TEL. 0-2744-9911 FAX 0-2393-0165	

ANALYSIS REPORT				
REF. NO.	WP/PK 4714/67		October 02, 2024	
APPLICANT	:	หัวหิน วิลเลจ		
COMMODITY	:	บ่อน้ำดิบ		
SAMPLING DATE	:	September 25, 2024	Received Date : September 26, 2024	
ANALYSIS RESULT (S)	:			

Items	Unit	Result	Standard	Analysis Method
Total Coliform	MPN/100 ml	7.8	< 2.2	Multiple tube technique
E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique

Remark :

บ่อน้ำดิบ : พบเชื้อ Total Coliform Bacteria สูงเกินเกณฑ์มาตรฐาน ควรทำความสะอาดบ่ออย่างสม่ำเสมอ เพื่อปราศจากเชื้อโรคในระบบ

TR/lc This report applies to client's self-drawn sample only.

Analyzed by จุฑาทิพย์ นวกุลวณ Approved by ศุภณัฐ พงษ์พานิช

F-QC-04-08 Rev. 3

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



Test Report 6024697

Date : 8-Oct-2024

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.4715/67 = บ่อประปา 5 เหลี่ยม
 Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6339022
 Sample Condition : Water appears transparent contained in a glass bottle sealed with a plastic lid and kept at a cool temperature.
 Qty.Submitted : 1 bottle x 1 L.
 Date Received : 26-Sep-2024 Date Commenced : 27-Sep-2024

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
 SGS (Thailand) Ltd.

Jirapan Vilaipol
 Microbiology Laboratory Manager

***** End of Report *****

5736410
 Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
 Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
 Publish or advertisement of the result of this document is prohibited, unless prior written approval of the Company.
 Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
 WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
 t +66 (0)2 683 05 41, 294 74 85-90 f +66 (0)2 294 74 84, 683 07 58 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง ธันวาคม 2567



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6024696

Date : 8-Oct-2024

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.4716/67 = เครื่องทำน้ำแข็ง ชุด 1
Sample Description : Ice

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6339023
Sample Condition : Ice sample is contained in a sterile plastic zip bag and kept at below freezing temperature.
Qty.Submitted : 1 bag
Date Received : 26-Sep-2024 Date Commenced : 27-Sep-2024

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

5726409
*Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was/were drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited | Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41, 294 74 85-90 f +66 (0)2 294 74 84, 683 07 58 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6024695

Date : 8-Oct-2024

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.4717/67 = เครื่องทำน้ำแข็ง จด 2
Sample Description : Ice

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6339024
Sample Condition : Ice sample is contained in a sterile plastic zip bag and kept at below freezing temperature.
Qty.Submitted : 1 bag
Date Received : 26-Sep-2024 Date Commenced : 27-Sep-2024

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.

Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited | Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41, 294 74 85-90 f +66 (0)2 294 74 84, 683 07 58 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6024694

Date : 8-Oct-2024

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.4718/67 = เครื่องทำน้ำแข็ง จด 3
Sample Description : Ice

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6339025
Sample Condition : Ice sample is contained in a sterile plastic zip bag and kept at below freezing temperature.

Qty.Submitted : 1 bag
Date Received : 26-Sep-2024 Date Commenced : 27-Sep-2024

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

5726407
Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41, 294 74 85-90 f +66 (0)2 294 74 84, 683 07 58 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6024693

Date : 8-Oct-2024

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.4719/67 = น้ำเย็นห้องรับแขก No.402
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6339026
Sample Condition : Water appears transparent contained in a glass bottle sealed with a plastic lid and kept at a cool temperature. Sediment is showing at the bottom of the bottle.
Qty.Submitted : 1 bottle x 1 L.
Date Received : 26-Sep-2024 Date Commenced : 27-Sep-2024

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

5726406
Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited | Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41, 294 74 85-90 f +66 (0)2 294 74 84, 683 07 58 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6024692

Date : 8-Oct-2024

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.4720/67 = น้ำร้อนห้องรับแขก No.402
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6339027
Sample Condition : Water appears transparent contained in a glass bottle sealed with a plastic lid and kept at a cool temperature.
Qty.Submitted : 1 bottle x 1 L.
Date Received : 26-Sep-2024 Date Commenced : 27-Sep-2024

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.

Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited | Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41, 294 74 85-90 f +66 (0)2 294 74 84, 683 07 58 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6024688

Date : 8-Oct-2024

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.4724/67 = น้ำประปาห้องครัว
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6339031
Sample Condition : Water appears transparent contained in a glass bottle sealed with a plastic lid and kept at a cool temperature.
Qty.Submitted : 1 bottle x 1 L.
Date Received : 26-Sep-2024 Date Commenced : 27-Sep-2024

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such Information.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 58, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41, 294 74 85-90 f +66 (0)2 294 74 84, 683 07 58 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6024691

Date : 8-Oct-2024

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.4721/67 = ภาต Cooling
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6339028
Sample Condition : Water appears transparent contained in a glass bottle sealed with a plastic lid and kept at a cool temperature. Sediment is showing at the bottom of the bottle.
Qty.Submitted : 1 bottle x 1 L.
Date Received : 26-Sep-2024 Date Commenced : 27-Sep-2024

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

5726404
*Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6024690

Date : 8-Oct-2024

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.4722/67 = Main Pool
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6339029
Sample Condition : Water appears transparent contained in a glass bottle sealed with a plastic lid and kept at a cool temperature.
Qty.Submitted : 1 bottle x 1 L.
Date Received : 26-Sep-2024 Date Commenced : 27-Sep-2024

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

5726403
*Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41, 294 74 85-90 f +66 (0)2 294 74 84, 683 07 58 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6024689

Date : 8-Oct-2024

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.4723/67 = Lagoon Pool
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6339030
Sample Condition : Water appears transparent contained in a glass bottle sealed with a plastic lid and kept at a cool temperature.
Qty.Submitted : 1 bottle x 1 L.
Date Received : 26-Sep-2024 Date Commenced : 27-Sep-2024

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

5726402
"Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information."
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) were said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41, 294 74 85-90 f +66 (0)2 294 74 84, 683 07 58 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2567



Test Report 6024698

Date : 8-Oct-2024

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.4714/67 = บ่อน้ำดิน
 Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6339021
 Sample Condition : Water appears transparent contained in a glass bottle sealed with a plastic lid and kept at a cool temperature. Sediment is showing at the bottom of the bottle.
 Qty.Submitted : 1 bottle x 1 L.
 Date Received : 26-Sep-2024 Date Commenced : 27-Sep-2024

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	200	CFU/1000mL

Signed for and on behalf of
 SGS (Thailand) Ltd.

Jirapan Vilaipol
 Microbiology Laboratory Manager


***** End of Report *****

5726411
 "Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information."
 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
 Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
 Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
 Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
 WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited | Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 58, Chong Nonsi, Yan Nawa, Bangkok 10120
 t +66 (0)2 683 05 41, 294 74 85-90 f +66 (0)2 294 74 84, 683 07 58 www.sgs.com




Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2567

	<p>บริษัท วิศวกรรมเคมี จำกัด</p> <p>THAI CHEMICAL & ENGINEERING CO., LTD.</p> <p>1048 2 ซ.สุขุมวิท 66-1 ต.สุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10260 โทร. 0-2744-9911 แฟกซ์ 0-2393-0165</p> <p>1048 2 Soi Sukhumvit 66-1, Sukhumvit Rd., Prakanong Tai, Prakanong, Bangkok 10260 TEL: 0-2744-9911 FAX: 0-2393-0165</p>																
ANALYSIS REPORT																	
REF. NO.	WP/PK 6361/67	December 23, 2024															
APPLICANT	: Anantara Hua Hin Resort & Spa																
COMMODITY	: น้ำร้อน ห้องรับแขก No.206																
SAMPLING DATE	: December 16, 2024	Received Date : December 17, 2024															
ANALYSIS RESULT (S)	:																
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 25%;">Items</th> <th style="width: 15%;">Unit</th> <th style="width: 15%;">Result</th> <th style="width: 15%;">Standard</th> <th style="width: 30%;">Analysis Method</th> </tr> </thead> <tbody> <tr> <td>Total Coliform</td> <td>MPN/100 ml</td> <td style="text-align: center;">< 2</td> <td style="text-align: center;">< 2.2</td> <td>Multiple tube technique</td> </tr> <tr> <td>E.Coli</td> <td>MPN/100 ml</td> <td style="text-align: center;">Negative</td> <td style="text-align: center;">Negative</td> <td>Multiple tube technique</td> </tr> </tbody> </table>			Items	Unit	Result	Standard	Analysis Method	Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique	E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique
Items	Unit	Result	Standard	Analysis Method													
Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique													
E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique													
Remark :																	
<p>คุณภาพน้ำอยู่ในเกณฑ์มาตรฐาน</p>																	
<p>This report applies to client's self-drawn sample only.</p>																	
TR/le	Analyzed by..... <u>กาญจนา ทัพพเหล็ก</u>																
	Approved by..... <u>สิริณัฐวิทย์ พงษ์สารเดช</u>																



F-OC-04-08 Rev. 3

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2567

	บริษัท วิศวกรรมเคมี จำกัด THAI CHEMICAL & ENGINEERING CO., LTD. <small>104X2 ซ.สุขุมวิท 66-1 อ.สุขุมวิท แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพฯ 10260 โทร. 0-2744-9911 แฟกซ์ 0-2393-0165</small> <small>104X2 Soi Sukhumvit 66-1, Sukhumvit Rd., Prakanong, Soi, Prakanong, Bangkok 10260 TEL. 0-2744-9911 FAX 0-2393-0165</small>																
ANALYSIS REPORT																	
REF. NO.	WP/PK 6364/67	December 23, 2024															
APPLICANT	:	Anantara Hua Hin Resort & Spa															
COMMODITY	:	Lagoon Pool															
SAMPLING DATE	:	December 16, 2024 Received Date : December 17, 2024															
ANALYSIS RESULT (S)	:																
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 25%;">Items</th> <th style="width: 15%;">Unit</th> <th style="width: 15%;">Result</th> <th style="width: 15%;">Standard</th> <th style="width: 30%;">Analysis Method</th> </tr> </thead> <tbody> <tr> <td>Total Coliform</td> <td>MPN/100 ml</td> <td style="text-align: center;">< 2</td> <td style="text-align: center;">< 10</td> <td>Multiple tube technique</td> </tr> <tr> <td>E.Coli</td> <td>MPN/100 ml</td> <td style="text-align: center;">Negative</td> <td style="text-align: center;">Negative</td> <td>Multiple tube technique</td> </tr> </tbody> </table>			Items	Unit	Result	Standard	Analysis Method	Total Coliform	MPN/100 ml	< 2	< 10	Multiple tube technique	E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique
Items	Unit	Result	Standard	Analysis Method													
Total Coliform	MPN/100 ml	< 2	< 10	Multiple tube technique													
E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique													
Remark : <div style="text-align: center; margin-top: 20px;"> คุณภาพน้ำอยู่ในเกณฑ์มาตรฐาน </div>																	
This report applies to client's self-drawn sample only.																	
TR/le																	
Analyzed by		Approved by 															


F-QC-04-08 Rev. 3

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2567

		บริษัท วิศวกรรมเคมี จำกัด THAI CHEMICAL & ENGINEERING CO., LTD. 10482 ซ.สุขุมวิท 66/1 ต.สุขุมวิท แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพมหานคร 10260 โทร. 0-2744-9911 แฟกซ์ 0-2393-0165 10482 Soi Sukhumvit 66/1, Sukhumvit Rd., Prakanong Tai, Prakanong, Bangkok 10260 TEL. 0-2744-9911 FAX 0-2393-0165																	
ANALYSIS REPORT																			
REF. NO.	WP/PK 6357/67		December 23, 2024																
APPLICANT	:	Anantara Hua Hin Resort & Spa																	
COMMODITY	:	เครื่องทำน้ำแข็ง จุด 1																	
SAMPLING DATE	:	December 16, 2024	Received Date : December 17, 2024																
ANALYSIS RESULT (S)	:																		
<table border="1"> <thead> <tr> <th>Items</th> <th>Unit</th> <th>Result</th> <th>Standard</th> <th>Analysis Method</th> </tr> </thead> <tbody> <tr> <td>Total Coliform</td> <td>MPN/100 ml</td> <td>< 2</td> <td>< 2.2</td> <td>Multiple tube technique</td> </tr> <tr> <td>E.Coli</td> <td>MPN/100 ml</td> <td>Negative</td> <td>Negative</td> <td>Multiple tube technique</td> </tr> </tbody> </table>					Items	Unit	Result	Standard	Analysis Method	Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique	E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique
Items	Unit	Result	Standard	Analysis Method															
Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique															
E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique															
Remark :																			
คุณภาพน้ำอยู่ในเกณฑ์มาตรฐาน																			
This report applies to client's self-drawn sample only.																			
TR/lc																			
Analyzed by	กัญญา ลาภเหล็ก		Approved by  พลเอกประยุทธ์ จันทร์โอชา																



F-QC-04-08 Rev. 3

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2567

	<p>บริษัท วิศวกรรมเคมี จำกัด THAI CHEMICAL & ENGINEERING CO., LTD. 1048/2 ซ.สุขุมวิท 66-1 น.สุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ 10260 โทร. 0-2744-9911 แฟกซ์ 0-2793-0165 1048/2 Soi Sukhumvit 66-1, Sukhumvit Rd., Prakanong Tai, Prakanong, Bangkok 10260 TEL: 0-2744-9911 FAX: 0-2793-0165</p>																
ANALYSIS REPORT																	
REF. NO.	WP/PK 6358/67	December 23, 2024															
APPLICANT COMMODITY	: Anantara Hua Hin Resort & Spa : เครื่องทำน้ำแข็ง จุด 2																
SAMPLING DATE ANALYSIS RESULT (S)	: December 16, 2024 Received Date : December 17, 2024 :																
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 20%;">Items</th> <th style="width: 15%;">Unit</th> <th style="width: 15%;">Result</th> <th style="width: 15%;">Standard</th> <th style="width: 35%;">Analysis Method</th> </tr> </thead> <tbody> <tr> <td>Total Coliform</td> <td>MPN/100 ml</td> <td>< 2</td> <td>< 2.2</td> <td>Multiple tube technique</td> </tr> <tr> <td>E.Coli</td> <td>MPN/100 ml</td> <td>Negative</td> <td>Negative</td> <td>Multiple tube technique</td> </tr> </tbody> </table>			Items	Unit	Result	Standard	Analysis Method	Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique	E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique
Items	Unit	Result	Standard	Analysis Method													
Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique													
E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique													
Remark :																	
คุณภาพน้ำอยู่ในเกณฑ์มาตรฐาน																	
This report applies to client's self-drawn sample only.																	
TR/lc Analyzed by	ภาณุมาศ ลาภพรัตน์ Approved by																




F-QC-04-08 Rev. 3

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2567

		<p>บริษัท วิศวกรรมเคมี จำกัด</p> <p>THAI CHEMICAL & ENGINEERING CO., LTD.</p> <p>1048/2 ซ.สุขุมวิท 66/1 อ.สุขุมวิท เขตวัฒนา กรุงเทพมหานคร 10260 โทร. 0-2744-9911 แฟกซ์ 0-2393-0165</p> <p>1048/2 Soi Sukhumvit 66/1, Sukhumvit Rd., Prakanong Tai, Prakanong, Bangkok 10260 TEL. 0-2744-9911 FAX 0-2393-0165</p>																	
<p>ANALYSIS REPORT</p>																			
REF. NO.	WP/PK 6365/67		December 23, 2024																
APPLICANT	:	Anantara Hua Hin Resort & Spa																	
COMMODITY	:	น้ำประปา ห้องครัว 1																	
SAMPLING DATE	:	December 16, 2024	Received Date : December 17, 2024																
ANALYSIS RESULT (S)	:																		
<table border="1"> <thead> <tr> <th>Items</th> <th>Unit</th> <th>Result</th> <th>Standard</th> <th>Analysis Method</th> </tr> </thead> <tbody> <tr> <td>Total Coliform</td> <td>MPN/100 ml</td> <td>< 2</td> <td>< 2.2</td> <td>Multiple tube technique</td> </tr> <tr> <td>E.Coli</td> <td>MPN/100 ml</td> <td>Negative</td> <td>Negative</td> <td>Multiple tube technique</td> </tr> </tbody> </table>					Items	Unit	Result	Standard	Analysis Method	Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique	E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique
Items	Unit	Result	Standard	Analysis Method															
Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique															
E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique															
<p>Remark :</p> <p style="text-align: center;">คุณภาพน้ำอยู่ในเกณฑ์มาตรฐาน</p>																			
<p style="text-align: center;">This report applies to client's self-drawn sample only.</p>																			
TR/lc																			
Analyzed by...	กานดา ดิษฐกุล		Approved by... 																


F-QC-04-08 Rev. 3

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2567

	<p>บริษัท วิศวกรรมเคมี จำกัด</p> <p>THAI CHEMICAL & ENGINEERING CO., LTD.</p> <p>1048/2 ซ.สุขุมวิท 66/1 อ.สุขุมวิท แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพฯ 10260 โทร. 0-2744-9911 แฟกซ์ 0-2393-0165</p> <p>1048/2 Soi Sukhumvit 66/1, Sukhumvit Rd., Prakanong Tai, Prakanong, Bangkok 10260 TEL. 0-2744-9911 FAX 0-2393-0165</p>																
ANALYSIS REPORT																	
REF. NO.	WP/PK 6366/67	December 23, 2024															
APPLICANT	: Anantara Hua Hin Resort & Spa																
COMMODITY	: น้ำประปา ห้องครัว 2																
SAMPLING DATE	: December 16, 2024	Received Date : December 17, 2024															
ANALYSIS RESULT (S)	:																
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 25%;">Items</th> <th style="width: 15%;">Unit</th> <th style="width: 15%;">Result</th> <th style="width: 15%;">Standard</th> <th style="width: 30%;">Analysis Method</th> </tr> </thead> <tbody> <tr> <td>Total Coliform</td> <td>MPN/100 ml</td> <td style="text-align: center;">< 2</td> <td style="text-align: center;">< 2.2</td> <td>Multiple tube technique</td> </tr> <tr> <td>E.Coli</td> <td>MPN/100 ml</td> <td style="text-align: center;">Negative</td> <td style="text-align: center;">Negative</td> <td>Multiple tube technique</td> </tr> </tbody> </table>			Items	Unit	Result	Standard	Analysis Method	Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique	E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique
Items	Unit	Result	Standard	Analysis Method													
Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique													
E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique													
Remark : <div style="text-align: center; margin-top: 20px;"> <p>คุณภาพน้ำอยู่ในเกณฑ์มาตรฐาน</p> </div>																	
<p>This report applies to client's self-drawn sample only.</p>																	
TR/IC																	
Analyzed by		Approved by 															


F-QC-04-08 Rev. 3

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2567

	<p>บริษัท วิศวกรรมเคมี จำกัด</p> <p>THAI CHEMICAL & ENGINEERING CO., LTD.</p> <p>1048/2 ซ.สุขุมวิท 66-1 อ.สุขุมวิท แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพฯ 10260 โทร. 0-2744-9911 แฟกซ์ 0-2393-0165</p> <p>1048/2 Soi Sukhumvit 66/1, Sukhumvit Rd., Prakanong Tai, Prakanong, Bangkok 10260 TEL. 0-2744-9911 FAX 0-2393-0165</p>																
ANALYSIS REPORT																	
REF. NO.	WP/PK 6360/67	December 23, 2024															
APPLICANT	: Anantara Hua Hin Resort & Spa																
COMMODITY	: น้ำเย็น ห้องรับแขก No.206																
SAMPLING DATE	: December 16, 2024	Received Date : December 17, 2024															
ANALYSIS RESULT (S) :																	
<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th style="width: 25%;">Items</th> <th style="width: 15%;">Unit</th> <th style="width: 15%;">Result</th> <th style="width: 15%;">Standard</th> <th style="width: 30%;">Analysis Method</th> </tr> </thead> <tbody> <tr> <td>Total Coliform</td> <td>MPN/100 ml</td> <td>< 2</td> <td>< 2.2</td> <td>Multiple tube technique</td> </tr> <tr> <td>E.Coli</td> <td>MPN/100 ml</td> <td>Negative</td> <td>Negative</td> <td>Multiple tube technique</td> </tr> </tbody> </table>			Items	Unit	Result	Standard	Analysis Method	Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique	E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique
Items	Unit	Result	Standard	Analysis Method													
Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique													
E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique													
Remark :																	
คุณภาพน้ำอยู่ในเกณฑ์มาตรฐาน																	
<p style="text-align: center;">This report applies to client's self-drawn sample only.</p>																	
TR/ic	Analyzed by... <u>ณัฏฐา ลาเหล็ก</u>																
Approved by	<u>ศุภณัฐ วัฒนวิทย์</u>																




F-QC-04-08 Rev. 3

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2567

	<p>บริษัท วิศวกรรมเคมี จำกัด THAI CHEMICAL & ENGINEERING CO., LTD. 1048/2 ซ.สุขุมวิท 66/1 อ.สุขุมวิท แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพฯ 10260 โทร. 0-2744-9911 แฟกซ์ 0-2393-0165 1048/2 Soi Sukhumvit 66-1, Sukhumvit Rd., Prakong Tai, Prakanong, Bangkok 10260 TEL. 0-2744-9911 FAX 0-2393-0165</p>																
ANALYSIS REPORT																	
REF. NO.	WP/PK 6356/67	December 23, 2024															
APPLICANT	:	Anantara Hua Hin Resort & Spa															
COMMODITY	:	บ่อประปา 5 เหลี่ยม															
SAMPLING DATE	:	December 16, 2024 Received Date : December 17, 2024															
ANALYSIS RESULT (S) :																	
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 25%;">Items</th> <th style="width: 15%;">Unit</th> <th style="width: 15%;">Result</th> <th style="width: 15%;">Standard</th> <th style="width: 30%;">Analysis Method</th> </tr> </thead> <tbody> <tr> <td>Total Coliform</td> <td>MPN/100 ml</td> <td style="text-align: center;">< 2</td> <td style="text-align: center;">< 2.2</td> <td>Multiple tube technique</td> </tr> <tr> <td>E.Coli</td> <td>MPN/100 ml</td> <td style="text-align: center;">Negative</td> <td style="text-align: center;">Negative</td> <td>Multiple tube technique</td> </tr> </tbody> </table>			Items	Unit	Result	Standard	Analysis Method	Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique	E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique
Items	Unit	Result	Standard	Analysis Method													
Total Coliform	MPN/100 ml	< 2	< 2.2	Multiple tube technique													
E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique													
Remark :																	
<p>คุณภาพน้ำอยู่ในเกณฑ์มาตรฐาน</p>																	
<p>This report applies to client's self-drawn sample only.</p>																	
<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p>TR/1c</p> <p>Analyzed by... <u>กมลจรรยา ลาพิณพงศ์</u></p> </div> <div style="width: 45%; text-align: right;"> <p>Approved by... <u>ศุภณัฐ วัฒนวิเศษกุล</u></p> </div> </div>																	



F-QC-04-08 Rev. 3

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2567

	<p align="center">บริษัท วิศวกรรมเคมี จำกัด THAI CHEMICAL & ENGINEERING CO., LTD. 1948/2 ซ.สุขุมวิท 66-1 ก.สุขุมวิท แขวงจตุรัส เขตจตุรัส กรุงเทพมหานคร 10260 โทร. 0-2744-9911 แฟกซ์ 0-2393-0165 1048/2 Soi Sukhumvit 66-1 Sukhumvit Rd., Prakanong Tai, Prakanong, Bangkok 10260 TEL. 0-2744-9911 FAX 0-2393-0165</p>																
ANALYSIS REPORT																	
REF. NO.	WP/PK 6362/67	December 23, 2024															
APPLICANT	: Anantara Hua Hin Resort & Spa																
COMMODITY	: น้ำ Cooling																
SAMPLING DATE	: December 16, 2024	Received Date : December 17, 2024															
ANALYSIS RESULT (S)	:																
<table border="1"> <thead> <tr> <th>Items</th> <th>Unit</th> <th>Result</th> <th>Standard</th> <th>Analysis Method</th> </tr> </thead> <tbody> <tr> <td>Total Coliform</td> <td>MPN/100 ml</td> <td>7.8</td> <td>< 2.2</td> <td>Multiple tube technique</td> </tr> <tr> <td>E.Coli</td> <td>MPN/100 ml</td> <td>Negative</td> <td>Negative</td> <td>Multiple tube technique</td> </tr> </tbody> </table>	Items	Unit	Result	Standard	Analysis Method	Total Coliform	MPN/100 ml	7.8	< 2.2	Multiple tube technique	E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique		
Items	Unit	Result	Standard	Analysis Method													
Total Coliform	MPN/100 ml	7.8	< 2.2	Multiple tube technique													
E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique													
Remark :																	
<p align="center">พบเชื้อ Total Coliform Bacteria สูงเกินเกณฑ์มาตรฐาน ควรตรวจสอบและทำความสะอาดระบบ เพื่อปราศจากเชื้อโรค.</p>																	
<p align="center">This report applies to client's self-drawn sample only.</p>																	
TR/c																	
Analyzed by.....		Approved by..... 															

F-QC-04-05 Rev. 3

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2567

	<p>บริษัท วิศวกรรมเคมี จำกัด THAI CHEMICAL & ENGINEERING CO., LTD. 1048 2 ซ.สุขุมวิท 60-1 อ.สุขุมวิท แขวงจตุจักร เขตจตุจักร กรุงเทพฯ 10260 โทร. 0-2744-9911 แฟกซ์ 0-2393-0165 1048 2 Soi Sukhumvit 60-1, Sukhumvit Rd., Prakanong, Bangkok 10260 TEL. 0-2744-9911 FAX 0-2393-0165</p>																
ANALYSIS REPORT																	
REF. NO.	WP/PK 6363/67	December 23, 2024															
APPLICANT	: Anantara Hua Hin Resort & Spa																
COMMODITY	: Main Pool																
SAMPLING DATE	: December 16, 2024	Received Date : December 17, 2024															
ANALYSIS RESULT (S)	:																
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 25%;">Items</th> <th style="width: 15%;">Unit</th> <th style="width: 15%;">Result</th> <th style="width: 15%;">Standard</th> <th style="width: 30%;">Analysis Method</th> </tr> </thead> <tbody> <tr> <td>Total Coliform</td> <td>MPN/100 ml</td> <td style="text-align: center;">< 2</td> <td style="text-align: center;">< 10</td> <td>Multiple tube technique</td> </tr> <tr> <td>E.Coli</td> <td>MPN/100 ml</td> <td style="text-align: center;">Negative</td> <td style="text-align: center;">Negative</td> <td>Multiple tube technique</td> </tr> </tbody> </table>			Items	Unit	Result	Standard	Analysis Method	Total Coliform	MPN/100 ml	< 2	< 10	Multiple tube technique	E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique
Items	Unit	Result	Standard	Analysis Method													
Total Coliform	MPN/100 ml	< 2	< 10	Multiple tube technique													
E.Coli	MPN/100 ml	Negative	Negative	Multiple tube technique													
Remark : <div style="text-align: center; margin-top: 20px;"> <p>คุณภาพน้ำอยู่ในเกณฑ์มาตรฐาน</p> </div>																	
This report applies to client's self-drawn sample only.																	
TR/c																	
Analyzed by.....	ภาณุชนา สานเหล็ก	Approved by..... <div style="text-align: center;">  <p>สมศักดิ์ สดสมการสง</p> </div>															

F-QC-04-06 Rev. 3