

ภาคผนวกที่ 2

เอกสารประกอบการปฏิบัติตามมาตรการฯ

| | |
|----------------|--|
| เอกสารแนบ 2-1 | สำเนาหนังสือนำส่งรายงานผลการปฏิบัติตามมาตรการฯ รอบ 2/2567 ระหว่างเดือนกรกฎาคม-ธันวาคม 2567 |
| เอกสารแนบ 2-2 | เกณฑ์ในการรับกำจัดของเสีย |
| เอกสารแนบ 2-3 | เกณฑ์ในการป้อนของเสียเข้าสู่เตาเผา |
| เอกสารแนบ 2-4 | ตัวอย่างผลการวิเคราะห์ตัวอย่างของเสียก่อนรับกำจัด |
| เอกสารแนบ 2-5 | สำเนานำส่งผลการตรวจสอบของเสียอันตรายที่ Mixing แล้ว และถ่ายต่อ กนอ. |
| เอกสารแนบ 2-6 | ตัวอย่างผลการวิเคราะห์ตัวอย่างที่ Mixing แล้ว |
| เอกสารแนบ 2-7 | ตัวอย่างรายงานบันทึกการตรวจสอบข้อมูลของเสียเบื้องต้น |
| เอกสารแนบ 2-8 | ตัวอย่างตารางและบันทึกการเข้าออกของรถเก็บขนของเสีย |
| เอกสารแนบ 2-9 | การฝึกอบรมก่อนเริ่มงาน |
| เอกสารแนบ 2-10 | Toolbox Talk ก่อนเริ่มปฏิบัติงาน |
| เอกสารแนบ 2-11 | รายงานการปฏิบัติงานของแผนกเก็บกากของเสีย |
| เอกสารแนบ 2-12 | เอกสารขั้นตอนการจัดการของเสียเข้าสู่ห้องเผาและบันทึกการควบคุมความเหมาะสมของค่าความร้อนของการเผาขยะในเตาเผา |
| เอกสารแนบ 2-13 | ตัวอย่างรายงานการตรวจสอบการทำงานของเครื่องจักร หรือ Daily Report |
| เอกสารแนบ 2-14 | แผนผังพื้นที่สีเขียวภายในโครงการ |
| เอกสารแนบ 2-15 | ผลการทดสอบประสิทธิภาพถ่านกัมมันต์ |
| เอกสารแนบ 2-16 | แผนการซ่อมบำรุง ประจำปี 2568 |
| เอกสารแนบ 2-17 | ผลการสอบเทียบ CEMS ประจำปี 2568 |
| เอกสารแนบ 2-18 | เกณฑ์รับน้ำเสียของนิคม |
| เอกสารแนบ 2-19 | เอกสารการจัดทำโครงการอนุรักษ์การไถ่คืน |
| เอกสารแนบ 2-20 | ระบบตรวจสอบเส้นทางการขนส่งของเสีย |
| เอกสารแนบ 2-21 | เอกสาร Contractor Safety Rule |
| เอกสารแนบ 2-22 | เอกสาร Safety Talk |
| เอกสารแนบ 2-23 | ตัวอย่างเอกสารระบบใบกำกับการขนส่งขยะของโครงการ (Waste Manifest) |
| เอกสารแนบ 2-24 | รายงานการตรวจสภาพยานพาหนะ |
| เอกสารแนบ 2-25 | บันทึกการคัดแยกของเสีย |
| เอกสารแนบ 2-26 | ผลการวิเคราะห์ลักษณะสมบัติของทรายและเถ้าหนักก่อนส่งกำจัด |
| เอกสารแนบ 2-27 | ผลการวิเคราะห์ลักษณะสมบัติของเถ้าลอย |

ภาคผนวกที่ 2 (ต่อ)

เอกสารประกอบการปฏิบัติตามมาตรการฯ

| | | |
|-----------|------|---|
| เอกสารแนบ | 2-28 | หนังสือแจ้งผลการพิจารณาการขออนุญาตให้นำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว ออกนอกบริเวณโรงงาน (สก.2/กอ.1) |
| เอกสารแนบ | 2-29 | กิจกรรมชุมชนสัมพันธ์ |
| เอกสารแนบ | 2-30 | เอกสารจัดตั้งคณะกรรมการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม |
| เอกสารแนบ | 2-31 | ขั้นตอนการรับเรื่องร้องเรียนและเอกสารแจ้งตอบกลับเรื่องร้องเรียน จากหน่วยงานราชการ ระหว่างปี 2567-2568 |
| เอกสารแนบ | 2-32 | นโยบายด้านอาชีวอนามัยและความปลอดภัย |
| เอกสารแนบ | 2-33 | เอกสารแต่งตั้งคณะกรรมการบริหารความปลอดภัย |
| เอกสารแนบ | 2-34 | บันทึกการตรวจสอบความปลอดภัยในพื้นที่ทำงาน |
| เอกสารแนบ | 2-35 | คู่มือความปลอดภัยและกฎระเบียบด้านความปลอดภัย |
| เอกสารแนบ | 2-36 | แผนงานด้านอาชีวอนามัยและความปลอดภัยในการทำงาน ประจำปี 2568 |
| เอกสารแนบ | 2-37 | ขั้นตอนการปฏิบัติการกรณีฉุกเฉิน |
| เอกสารแนบ | 2-38 | ผลการซ้อมดับเพลิงภายใน ประจำปี 2567 |
| เอกสารแนบ | 2-39 | ผลการซ้อมสารเคมีรั่วไหล ประจำปี 2567 |
| เอกสารแนบ | 2-40 | บันทึกสถิติอุบัติเหตุ ระหว่างปี 2565-2568 (ย้อนหลัง 3 ปี) |
| เอกสารแนบ | 2-41 | แบบแจ้งรายละเอียดของสารเคมีอันตรายในสถานประกอบการ (สอ.1) ประจำปี 2568 |
| เอกสารแนบ | 2-42 | มาตรการความปลอดภัยเกี่ยวกับท่อส่งก๊าซและการจัดเก็บ |
| เอกสารแนบ | 2-43 | เอกสารขอเข้าทำงานในพื้นที่โครงการฯ |
| เอกสารแนบ | 2-44 | ผลการตรวจสอบสุขภาพย้อนหลัง ระหว่างปี 2563-2567 (ย้อนหลัง 5 ปี) |
| เอกสารแนบ | 2-45 | เอกสารการตรวจสอบบ่อน้ำใต้ดิน ปี พ.ศ. 2560 |
| เอกสารแนบ | 2-46 | หนังสือนำส่งรายงานผลการตรวจวัดและวิเคราะห์สภาวะการทำงานเกี่ยวกับแสงสว่าง (รสส.2) |
| เอกสารแนบ | 2-47 | Noise Contour Map ปี พ.ศ. 2566 |
| เอกสารแนบ | 2-48 | รายงานสมดุลการผลิตไฟฟ้า |
| เอกสารแนบ | 2-49 | รายงานสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว (สำหรับผู้ก่อกำเนิด) ประจำปี 2568 (สก.3/รง.9) |
| เอกสารแนบ | 2-50 | แผนตรวจวัดคุณภาพสิ่งแวดล้อม |
| เอกสารแนบ | 2-51 | จดหมายนำส่งรายงานน้ำใต้ดิน |
| เอกสารแนบ | 2-52 | การซ้อมดับเพลิงร่วมกับหน่วยงานภายนอก ประจำปี 2567 |
| เอกสารแนบ | 2-53 | เอกสารการดำเนินกิจกรรมส่งเสริมสุขภาพของพนักงาน |

ภาคผนวกที่ 2 (ต่อ)

เอกสารประกอบการปฏิบัติตามมาตรการฯ

- เอกสารแนบ 2-54 ข้อมูลสุขภาพประชาชน จากตำบลบางปูใหม่ อำเภอเมืองสมุทรปราการ จังหวัดสมุทรปราการ ระหว่างปี 2565-2568
- เอกสารแนบ 2-55 เอกสารการตรวจประเมินมาตรฐานการดำเนินงานของผู้ขนส่งของเสียจากการสาธารณสุขเข้ามากำจัด
- เอกสารแนบ 2-56 เอกสารการตรวจประเมินมาตรฐานวิธีการตรวจสอบสุขภาพของสถานบริการสาธารณสุข

เอกสารแนบ 2-1


สำเนาหนังสือนำเสนอรายงานผลการปฏิบัติตามมาตรการป้องกัน

และแก้ไขผลกระทบสิ่งแวดล้อม (ระยะดำเนินการ)

ครั้งที่ 2/2567 ระหว่างเดือนกรกฎาคม-ธันวาคม พ.ศ. 2567



ที่ ๒๐๒๕-๐๑๓/WMS/MD/EN



วันที่ ๓๐ มกราคม พ.ศ. ๒๕๖๘

เรื่อง รายงานผลการปฏิบัติตามรายงานการประเมินผลกระทบสิ่งแวดล้อม สำหรับโครงการ กิจการ หรือการดำเนินการที่ อาจมีผลกระทบต่อทรัพยากรธรรมชาติ คุณภาพสิ่งแวดล้อม สุขภาพอนามัย คุณภาพชีวิต ของประชาชนในชุมชน อย่างรุนแรง โครงการโรงงานปรับปรุงคุณภาพของเสียรวม (ส่วนขยายครั้งที่ ๑) ประจำเดือน กรกฎาคม - ธันวาคม ๒๕๖๗ ของบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

เรียน เลขาธิการสำนักงานคณะกรรมการกำกับกิจการพลังงาน

สิ่งที่แนบมาด้วย

รายงานผลการปฏิบัติตามรายงานการประเมินผลกระทบสิ่งแวดล้อมฯ ประจำเดือน กรกฎาคม - ธันวาคม ๒๕๖๗ ของ บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด จำนวน ๑ ฉบับ และ CD บันทึกรายงานฯ จำนวน ๑ แผ่น

ด้วย บริษัทบางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด ได้รับใบอนุญาตผลิตไฟฟ้า เลขที่ กกพ ๐๑-๑(๑)/๕๕-๒๒๐ ให้ประกอบกิจการผลิตไฟฟ้าที่มีกำลังการผลิตติดตั้งไม่เกิน ๑๐ เมกะวัตต์ ตามพระราชบัญญัติการประกอบกิจการพลังงาน พ.ศ. ๒๕๔๐ และบริษัทต้องจัดทำรายงานผลการปฏิบัติตามรายงานการประเมินผลกระทบสิ่งแวดล้อมฯ ตามที่คณะกรรมการกำกับกิจการพลังงาน (กกพ.) กำหนด รวมถึงต้องปฏิบัติตามประกาศ กกพ. เรื่องหลักเกณฑ์ วิธีการและเงื่อนไขการจัดทำและ ส่งข้อมูลเกี่ยวกับการประกอบกิจการพลังงาน พ.ศ. ๒๕๖๑ นั้น

บริษัทฯ ได้มอบหมายให้ บริษัท ยูโนเด็ค แอนนาลิสต์ แอนด์ เอ็นจิเนียริ่ง คอนซัลแตนท์ จำกัด ดำเนินการตรวจวัด คุณภาพสิ่งแวดล้อมและจัดทำรายงานฯ ซึ่งบัดนี้ได้ดำเนินการจนเสร็จสิ้นแล้ว จึงขอจัดส่งรายงานตามเอกสารแนบ หากท่าน ต้องการข้อมูลเพิ่มเติม กรุณาติดต่อ [redacted] ที่หมายเลขโทรศัพท์เคลื่อนที่ [redacted]


จึงเรียนมาเพื่อโปรดพิจารณา

ขอแสดงความนับถือ



กรรมการผู้จัดการ

ในนามของบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด



เลขที่ 2025-012/BPEC/MD/EN

วันที่ 30 มกราคม 2568

เรื่อง รายงานผลการปฏิบัติตามรายงานการประเมินผลกระทบสิ่งแวดล้อม สำหรับโครงการ กิจการ หรือการ ดำเนินการที่อาจมีผลกระทบต่อทรัพยากรธรรมชาติ คุณภาพสิ่งแวดล้อม สุขภาพอนามัย คุณภาพชีวิต ของ ประชาชนในชุมชนอย่างรุนแรง โครงการโรงงานปรับปรุงคุณภาพของเสียรวม (ส่วนขยายครั้งที่ 1) ประจำเดือน กรกฎาคม - ธันวาคม 2567 ของบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

เรียน ผู้อำนวยการสำนักงานนิคมอุตสาหกรรมบางปู

อ้างถึง แจ้งผลการพิจารณารายงานการประเมินผลกระทบสิ่งแวดล้อมฯ ตามหนังสือเลขที่ พส 1010.3/9386 ลง วันที่ 9 กรกฎาคม 2567 โดยคณะกรรมการผู้ชำนาญการสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและ สิ่งแวดล้อม

สิ่งที่แนบมาด้วย รายงานผลการปฏิบัติตามรายงานการประเมินผลกระทบสิ่งแวดล้อมฯ ประจำเดือนกรกฎาคม - ธันวาคม 2567 ของ บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด จำนวน 3 ฉบับ และ CD บันทึกรายงานฯ จำนวน 4 แผ่น

ตามหนังสือที่อ้างถึง บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด จะต้องปฏิบัติตามมาตรการ ป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม และมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อมตามที่เสนอไว้ พร้อมทั้งต้อง จัดส่งรายงานดังกล่าวให้แก่ การนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อม จังหวัดสมุทรปราการ และสำนักงานนโยบายและแผนทรัพยากรธรรมชาติและ (สผ.) ทราบทุก 6 เดือน นั้น

บริษัทฯ ได้มอบหมายให้ บริษัท ยูโนเด็ค แอนนาลิสต์ แอนด์ เอ็นจิเนียริ่ง คอนซัลแตนท์ จำกัด ดำเนินการ ตรวจวัดคุณภาพสิ่งแวดล้อมและจัดทำรายงานฯ ซึ่งบัดนี้ได้ดำเนินการจนเสร็จสิ้นแล้ว จึงขอจัดส่งรายงานตามเอกสารแนบ หากท่านต้องการข้อมูลเพิ่มเติม กรุณาติดต่อ [redacted] ที่หมายเลขโทรศัพท์เคลื่อนที่ [redacted]


จึงเรียนมาเพื่อโปรดพิจารณา

ขอแสดงความนับถือ



กรรมการผู้จัดการ

ในนามของบริษัทบางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด



เอกสารแนบ 2-2

เกณฑ์ในการรับกำจัดของเสีย

| | | |
|---|-------------------|-----------------------------|
| Standard Operating Procedure | | Doc. No : 05-EN-S015 |
| Subject: Pre-Acceptance Decision of E-Quotes System | | Page: 1 of 7 |
| Prepared by: EN Dept. | Date: 26 May 2020 | Effective Date: 1 June 2020 |
| Approved by: [Signature] | | Revision: 0 |
| Authorization: [Signature] | Date: 26/5/2020 | Copy No.: |

Change Control

[illegible]

| | |
|--|------------------------------------|
| Standard Operating Procedure | Doc. No.: 05-EN-S015 |
| Subject: Pre-Acceptance Decision of E-Quotes System | Page: 2 of 7 |
| Prepared by: EN Dept. | Date: 26 May 2020 |
| Approved by: [Redacted] | Effective Date: 1 June 2020 |
| | Revision: 0 |

1. Purpose

- 1.1 To provide appropriately "Pre-Acceptance Standard Procedure' for waste propose to dispose at BPEC site
- 1.2 To set up criteria of Pre-Acceptance Decision Process for incoming waste to BPEC site
- 1.3 To ensure that all incoming waste shall be properly disposed onsite and not have the pollution to environment.
- 1.4 To ensure only permitted waste is accepted for on-site management.

2. Scope and Application

This policy shall be applied for incoming waste acceptance decision which will explain the pre-acceptance decision procedure prior to accept waste and also provide documentation for waste acceptance process.

3. Associated Document

Pre-acceptance process (Flowchart 1)

- | | |
|---------------|---|
| 02-SC-F002/06 | Waste Profile Form (Attachment 1) |
| 05-EN-F003/01 | Waste Sample Label (Attachment 2) |
| 02-LA-F023/03 | Analysis Request Form (Attachment 3) |
| 05-EN-F031/01 | Pre Acceptance Criteria (Attachment 4) |
| 05-EN-F032/00 | Assessment of Finger Print Test Result (FPT) (Attachment 5) |
| 05-EN-F033/00 | Assessment of Heavy Metal (Attachment 6) |

4. Working Procedure

Prior to accepting waste to dispose at BPEC site, Pre-Acceptance Process must apply as follow;

- 4.1 A representative of Sales and Customer Service Department (SC) shall visit the Waste Generator Site:
- 4.1.1 To record and complete customer detail in Customer Profile Form and waste qualification in Waste Profile Form (attachment 1) for each Waste Generator as follow Customer Profile and Waste Profile Procedure (02-SC-S001). Customer must provide all details of company's process, waste generated source, chemical list using and Material Safety Data Sheet for all chemical used in process.

| | |
|---|----------------------|
| Standard Operating Procedure | Doc. No.: 05-EN-S015 |
| Subject: Pre-Acceptance Decision of E-Quotes System | Page: 3 of 7 |
| Prepared by: EN Dept. | Date: 26 May 2020 |
| Effective Date: 1 June 2020 | |
| Approved by: [REDACTED] | Revision: 0 |

4.1.2 Sampling waste to follow the Work Instruction for Waste Sampling and post Waste Sample Label (attachment 2).

- 4.2 EN shall analyze the wastes, specify parameters for analysis before accepting waste and verify the code as 6 digits follow the MOI Notification B.E.2548 subject: Disposal of Wastes or Unusable Materials or waste code under DMF announcement B.E.2556 or hazardous substance act B.E.2548.

4.3.1 In case of no need the lab analysis result EN shall specify waste disposal / treatment method following to factory license at each facility such as

- Incineration (074)
- Haz waste incinerator (075)
- Fuel Blending (042)
- Regeneration of metal and metal compound (052)
- Send to external disposal facilities such as industrial waste to energy, cement kiln, recycle company, Sanitary landfill, Hazardous waste landfill, etc.

4.3.2 In case of lab analysis result is needed; parameter is specify by each disposal method or Waste Type for example:

4.3.2.1 Dispose at Landfill (for ESBEC)

- Solid waste categorized in Non-Hazardous Waste still is required for Bulk Density analysis or necessary parameters unless SC can evaluate and mention in waste profile.
- Sludge waste shall be analyzed Physical typically (FPT), Moisture Content, and Bulk Density. If the waste had contaminated as classified in supplement II of MOI notification it shall be analyzed the contaminant by Total Threshold Limit Concentration (TTLC) and Soluble Threshold Limit Concentration (STLC) method as specified by the standard requirement of MOI Notification B.E.2548.

4.3.2.2 Fuel Blending for alternative fuel or raw material

- Solid, Sludge or liquid Must analyze waste characteristics as attachment 4 (05-EN-F031/01)

4.3.2.3 Incinerator

- Solid, Sludge or liquid Must analyze waste characteristics as attachment 4 (05-EN-F031/01)

4.3.2.4 Other methods

4.4 Sampling Testing Procedure

- 4.4.1 Sale and Customer Service Department (SC) shall send sample to Laboratory directly

| | |
|---|----------------------|
| Standard Operating Procedure | Doc. No.: 05-EN-S015 |
| Subject: Pre-Acceptance Decision of E-Quotes System | Page: 4 of 7 |
| Prepared by: EN Dept. | Date: 26 May 2020 |
| Effective Date: 1 June 2020 | |
| Approved by: [REDACTED] | Revision: 0 |

4.4.2 Sale and Customer Service Department (SC) shall fill detail of customer and waste into Analysis Request Form (attachment 3)

4.4.3 EN for fill in parameters and send authorized to approval after that it's will be sent to Laboratory.

**** The consideration of customers' waste receiving will be based on the analysis result from the laboratory of West Management Siam Company Limited only. The sales representative will collect samples to send to analyse the physical characteristics and / or other parameters according to the Environment request in which the analysis results will be completed within 10 working days, in case of necessity the company's laboratories can consider sending samples for analysis to external laboratories that have working standards as required by the company. However, customers or sales personnel are not able to send samples directly to external laboratories. Due to the company will certify the analysis results that have been considered and approved by the company's laboratory only.

4.4.4 Laboratory staff shall complete record of the date, time, customer name, waste name, waste profile, laboratory name, parameters needed to analyze and Sample ID when the sample is submitted to the Laboratory on the Analysis Requisition Form and Log Book.

4.4.5 After analysis completion, the laboratory shall send the result of testing to EN

4.5 Pre-Acceptance Decision Request

4.5.1 SC fill in information from waste profile form into PA request of E-Quotes system

4.5.2 PA Decision process

4.5.2.1 Responsible Operation Department shall consider accepting or denying from PA request information plus laboratory result (if needed)

- In case of accept, OP to record consideration result and record operation cost and minimum processing cost.
- In case of deny, OP to record consideration result and additional information needed.

4.5.2.2 Environmental Department (EN)

- Consider from laboratory result as criteria indicated in MOI Notification B.E. 2548 Subject Disposal of Wastes or Unusable Materials and/or Criteria for Unusable Material for alternative fuel for cement kiln or other incinerator where approved by DIW include with comment from Operation Department.

- EN completed P/A Request form and PA Decision Form in E-Quote system which will be recorded for further reference.

| | |
|---|----------------------|
| Standard Operating Procedure | Doc. No.: 05-EN-S015 |
| Subject: Pre-Acceptance Decision of E-Quotes System | Page: 5 of 7 |
| Prepared by: EN Dept. | Date: 26 May 2020 |
| Effective Date: 1 June 2020 | |
| Approved by: [REDACTED] | Revision: 0 |

4.5.3 PA Decision Process

4.5.3.1 In case of accept

- SC keeps PA report with customer profile
- SC access into E-Quote process to issue quotation to customer for commercial process then customer process on Waste Stream Permit process
- SC informs WSP result to EN with WSP number and permit date

4.5.3.2 In case of deny, EN propose the decision result to site compliance committee for consideration

- In case that committee approved, 4.5.3.1 will be applied
- In case of deny, EN to record result of consideration, SC informs to customer

After the P/A Decision Form is finalized and approved, EN shall send P/A Decision Form is approved to SC by e-mail. EN will copy P/A Decision Form for related department (BP in case of wastewater and TN in case waste needed for solid or liquid blending process) for keeping as data base.

4.5.4 If detail or information of customer profile and waste profile is not sufficient for waste acceptance decision including if EN still not receive MSDS of chemical, Lab testing result and other related documents as EN required, EN shall hold process until receive sufficient data and EN will also give a delay reason back to SC.

4.6 Waste Acceptance decision thru E-Quote system shall be considered by responsible person (refer to PA flow chart)

- In case of emergency request or long period of consideration, SC can request for committee meeting to consider
- EN will record result of the meeting for reference

EN will start consideration process once needed information fully submit including lab analysis result and others as requested.

4.7 If Customer has changed a waste generated process or waste quality change, PA must be re-evaluated.

4.8 PA decision will be alerted annually for further review and information update.

4.9 Waste acceptance decision shall be depending on assessment of Pre Acceptance Criteria (Attachment 4), Finger Print Test Result (Attachment 5) and Heavy Metal concentration (Attachment 6) and/or depend on decision of EN or Operator Team in case by case.

4.10 The Off Spec case shall be considered by the committee; however result of consideration need to follow specific law and regulations and WSP that already approved. EN to record off spec report and distribute to all concerned for further process.

| | |
|---|----------------------|
| Standard Operating Procedure | Doc. No.: 05-EN-S015 |
| Subject: Pre-Acceptance Decision of E-Quotes System | Page: 6 of 7 |
| Prepared by: EN Dept. | Date: 26 May 2020 |
| Effective Date: 1 June 2020 | |
| Approved by: [REDACTED] | Revision: 0 |

4.11 PA revision will be expire same day as WSP which already approved by DIW

4.12 E Quote system will alert 60 days prior to expire date of PA

- SC revises PA for renewal consideration within 15 days from the alarm date.
- EN informs WR to take sampling from next shipment of customer for laboratory analysis.

- Laboratory analyse the sample and inform result to EN.

- Get into consideration system following no.4.5

4.12.1 PA period of Commercial waste is 3 years


4.12.2 PA period of Industrial waste is 1 year.

5 References

- 5.1 02-SC-S001, Customer Profile and Waste Profile
- 5.2 MOI Notification B.E. 2548 Subject Disposal of Wastes or Unusable Materials
- 5.3 MOI Notification B.E. 2556 Subject Hazardous Substance List
- 5.4 DMF Notification B.E.2556 Subject Oil & Gas Waste Management
- 5.5 IEAT Notification No.79/2554 Subject Method of Commercial Waste and Industrial Waste Management from Industrial Estate
- 5.6 Public Health Act 2535 and (No. 2) B.E. 2550.
- 5.7 Hazardous Waste Pre Acceptance Procedure


6. Glossary

- FPT : Finger Print Test
- P/A : Pre-acceptance Decision

| | |
|--|-----------------------------|
| Standard Operating Procedure | Doc. No.: 05-EN-S015 |
| Subject: Pre-Acceptance Decision of E-Quotes System | Page: 7 of 7 |
| Prepared by: EN Dept. Date: 26 May 2020 | Effective Date: 1 June 2020 |
| Approved by:  | Revision: 0 |

7. Definition

- 7.1 Industrial Non-Hazardous Waste: Waste or unusable material from manufacturing process including wastewater sludge, process sludge, process waste, scrap, etc. that has the characteristic as per indicated in MOI Notification No. 1 B.E. 2541 Subject Disposal of Wastes or Unusable Materials.
- 7.2 Hazardous Waste: Waste or unusable material from manufacturing process that has characteristic or generation process as per indicated in MOI Notification No. 6 B.E. 2540 Subject Disposal of Wastes or Unusable Materials.
- 7.3 Commercial Waste: Waste such as paper, food waste, plastic bag, food container, part of animal or waste that has the characteristic as per Public Health Act B.E. 2535 such waste shall not occur from production or manufacturing process and not contaminate with hazardous waste.
- 7.4 Recycling Materials: The materials that can be recyclable such as cardboard, aluminum can, plastic, glass, paper etc., from Industrial, Commercial and Municipal Solid Waste segregation or buy from Industrial Waste.
- 7.5 E-quotes: Program for support anything of waste from customer such as Pre-Acceptance Decision process, Customer Profile and Waste Profile etc.

| | |
|---|--|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-EN-S015T |
| เรื่อง: ขั้นตอนการตัดสินใจก่อนรับกำจัด/บำบัดของเสีย โดยระบบอิเล็กทรอนิกส์ | หน้าที่: 1 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกสิ่งแวดล้อม | วันที่: 26 พ.ค. 63 วันที่มีผลบังคับใช้: 1 มิ.ย. 63 |
| อนุมัติโดย:  | แก้ไขครั้งที่: 0 |
| ผู้มีอำนาจ: | วันที่: 26/5/2020 สำเนาที่: |

การเปลี่ยนแปลงเอกสาร

[illegible]

| | |
|---|---------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-EN-S014T |
| เรื่อง: ขั้นตอนการตัดสินใจก่อนรับกำจัด/บำบัดของเสีย โดยระบบอิเล็กทรอนิกส์ | หน้าที่: 2 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกสิ่งแวดล้อม วันที่: 26 พ.ค. 63 | วันที่มีผลบังคับใช้: 1 มิ.ย. 63 |
| อนุมัติโดย: [REDACTED] | แก้ไขครั้งที่: 0 |

1. วัตถุประสงค์

- 1.1 เพื่อให้มีขั้นตอนการปฏิบัติงานในการตัดสินใจก่อนรับกากของเสียเข้ามากำจัด/บำบัดภายในโครงการ
- 1.2 เพื่อกำหนดเกณฑ์การตัดสินใจรับกากของเสียเข้ามากำจัด/บำบัดภายในโครงการ
- 1.3 เพื่อให้มั่นใจว่าของเสียทุกชนิดในโครงการ จะถูกกำจัด/บำบัดอย่างเหมาะสมและไม่ก่อให้เกิดมลพิษต่อสิ่งแวดล้อม
- 1.4 เพื่อให้มั่นใจว่าโครงการฯ รับกำจัด/บำบัดเฉพาะของเสียที่ได้รับอนุญาตเท่านั้น

2. ขอบเขตและการใช้งาน

นโยบายนี้ใช้เพื่อประกอบการตัดสินใจก่อนรับกำจัด/บำบัดของเสียของโครงการฯ รวมถึงเอกสารที่ใช้ประกอบการตัดสินใจรับกำจัด/บำบัดของเสียของโครงการฯ ด้วย

3. เอกสารที่เกี่ยวข้อง

- 3.1 ขั้นตอนการตัดสินใจก่อนรับกำจัด/บำบัดของเสีย (แผนผัง 1)
- 3.2 02-SC-F002/06 ข้อมูลของสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว Waste Profile Form (เอกสารแนบ 1)
- 3.3 05-EN-F003/01 ฉลากข้อมูลตัวอย่างของเสีย (เอกสารแนบ 2)
- 3.4 02-LA-F023/03 แบบคำร้องขอวิเคราะห์ตัวอย่าง (เอกสารแนบ 3)
- 3.5 05-EN-F031/01 ขอบเขตการตัดสินใจรับกากของเสีย (เอกสารแนบ 4)
- 3.6 05-EN-F032/00 การประเมินผลการวิเคราะห์ของเสียด้วยวิธี Finger Print Test (FPT) (เอกสารแนบ 5)
- 3.7 05-EN-F033/00 การประเมินผลการวิเคราะห์ของเสียโดยค่าโลหะหนัก (เอกสารแนบ 6)

4. ขั้นตอนการปฏิบัติ

ขั้นตอนการดำเนินงานก่อนการตัดสินใจรับของเสียเข้ามาบำบัดและกำจัด/บำบัดยังโครงการฯ มีดังต่อไปนี้

4.1 ตัวแทนแผนกขายเข้าพบผู้ประกอบการ (ลูกค้า) เพื่อ

4.1.1 รับข้อมูลลูกค้า และรายละเอียดการกำเนิดของเสียและคุณลักษณะของเสีย โดยบันทึกข้อมูลลูกค้าลงในแบบบันทึกข้อมูลลูกค้าและให้ลูกค้าบันทึกข้อมูลของสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว (เอกสารแนบ 1) ตามมาตรฐานการปฏิบัติงาน เรื่อง แฟ้มข้อมูลลูกค้าและข้อมูลของสิ่งปฏิกูลและวัสดุที่ไม่ใช่แล้ว (02-SC-F002) โดย ลูกค้าต้องจัดเตรียมข้อมูลในส่วนของการประเมินผลและการประเมินการก่อเกิดของเสียอย่างละเอียด รวมถึงสารเคมีและเอกสารข้อมูลความปลอดภัยของวัตถุดิบและสารเคมีต่าง ๆ ที่ใช้ในกระบวนการผลิตและก่อเกิดของเสียและข้อมูลอื่น ๆ ตามที่ระบุไว้ พร้อมทั้งลงนามรับรองความถูกต้องของข้อมูลดังกล่าว

4.1.2 ทำการเก็บตัวอย่างของเสียตามมาตรฐานวิธีปฏิบัติเกี่ยวกับขั้นตอนการเก็บตัวอย่าง (เอกสารวิธีการและขั้นตอนการเก็บตัวอย่าง) เพื่อทำการวิเคราะห์ พร้อมทั้งทำการติดฉลากข้อมูลตัวอย่างของเสีย (เอกสารแนบ 2)

| | |
|---|---------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-EN-S014T |
| เรื่อง: ขั้นตอนการตัดสินใจก่อนรับกำจัด/บำบัดของเสีย โดยระบบอิเล็กทรอนิกส์ | หน้าที่: 3 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกสิ่งแวดล้อม วันที่: 26 พ.ค. 63 | วันที่มีผลบังคับใช้: 1 มิ.ย. 63 |
| อนุมัติโดย: [REDACTED] | แก้ไขครั้งที่: 0 |

4.2 แผนกสิ่งแวดล้อมฯ พิจารณาความเป็นอันตรายและตรวจสอบความถูกต้องของรหัสของเสีย 6 หลัก หรือ กำหนดรหัสของเสีย 6 หลัก ตามประกาศกระทรวงอุตสาหกรรม เรื่อง การกำจัด/บำบัดสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว พ.ศ.2548 หรือ ประเภทของเสียอันตรายจากสถานประกอบการปิโตรเลียม หรือ ประเภทของวัตถุอันตรายตามประกาศกระทรวงอุตสาหกรรม บัญชีรายชื่อวัตถุอันตราย พ.ศ. 2556 พร้อมทั้งระบุวิธีการกำจัด/บำบัดเบื้องต้น พร้อมทั้งพิจารณาความจำเป็นในการวิเคราะห์ตัวอย่าง

4.3 แผนกปฏิบัติการ พิจารณาเบื้องต้นถึงความจำเป็นในการวิเคราะห์ตัวอย่างเพื่อประกอบการตัดสินใจในการรับบำบัด/กำจัด รวมถึงพิจารณาวิธีการบำบัด/กำจัด ที่เหมาะสมกับของเสียชนิดนั้นๆ

4.3.1 กรณีผลการพิจารณาข้อมูลของเสียเบื้องต้นไม่ต้องทำการวิเคราะห์ตัวอย่าง

แผนกสิ่งแวดล้อมระบุวิธีการกำจัด/บำบัดที่เหมาะสม ตามใบอนุญาตประกอบการกิจการ เช่น

- วิธีการเผาทำลายในเตาเผาขยะทั่วไป (074)

- วิธีเผาทำลายในเตาเผาสำหรับของเสียอันตราย (075)

- วิธีการทำเชื้อเพลิงผสม (042)

- กระบวนการนำโลหะกลับมาใช้ใหม่ (052)

- นำกลับมาใช้ประโยชน์อื่นด้วยวิธีการอื่นๆ (049) เป็นต้น หรือ

- ส่งไปกำจัด/บำบัด ยังผู้ให้บริการภายนอกโครงการฯ เช่น โรงงานผลิตปูนซีเมนต์, บริษัทรีไซเคิล, หลุมฝังกลบตามหลักสุขาภิบาล และหลุมฝังกลบกากอุตสาหกรรมอันตราย เป็นต้น

4.3.2 กรณีผลการพิจารณาข้อมูลของเสียเบื้องต้น ระบุให้ทำการวิเคราะห์ตัวอย่าง การกำหนดพารามิเตอร์ที่ต้องทำการวิเคราะห์ขึ้นอยู่กับวิธีการกำจัด/บำบัดของเสีย นั้น เช่น

4.3.2.1 วิธีการฝังกลบ (สำหรับ ESBEC)

- ของเสียที่มีลักษณะเป็นของแข็ง ให้วิเคราะห์ความหนาแน่น หรือพารามิเตอร์อื่นๆ ที่แผนกขายและลูกค้าสัมพันธ์ พิจารณาว่าเป็นสำหรับใช้เป็นข้อมูลในการเสนอราคากำจัดแก่ลูกค้า

- ของเสียที่มีลักษณะกึ่งของแข็ง ให้วิเคราะห์ลักษณะทางกายภาพ (FPT), ปริมาณความชื้น และความหนาแน่น และหากของเสียดังกล่าวมีสิ่งเจือปนตามที่กำหนดในภาคผนวกที่ 2 แบบท้ายประกาศกระทรวงอุตสาหกรรม เรื่อง การกำจัดสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว พ.ศ. 2548 เป็นองค์ประกอบ ให้วิเคราะห์ค่าสิ่งเจือปนนั้นๆ โดยวิธีการวิเคราะห์ความเข้มข้นของสิ่งเจือปน โดยอ้างอิงมาตรฐานตามประกาศฉบับดังกล่าว

| | |
|---|---------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-EN-S014T |
| เรื่อง: ขั้นตอนการตัดสินใจก่อนรับกำจัด/บำบัดของเสีย โดยระบบอิเล็กทรอนิกส์ | หน้าที่: 4 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกสิ่งแวดล้อม วันที่: 26 พ.ค. 63 | วันที่มีผลบังคับใช้: 1 มิ.ย. 63 |
| อนุมัติโดย: [REDACTED] | แก้ไขครั้งที่: 0 |

4.3.2.2 วิธีการทำเชื้อเพลิงผสม

- ทั้งของเสียที่มีลักษณะเป็นของแข็ง หรือ ของเหลว หรือของกึ่งแข็งกึ่งเหลว ให้วิเคราะห์คุณลักษณะของเสีย ตามเอกสารแนบ 4 (05-EN-F031/01)

4.3.2.3 วิธีการเผาในเตาเผาของเสีย

- ทั้งของเสียที่มีลักษณะเป็นของแข็ง / ของเหลว และที่มีลักษณะเป็นของกึ่งแข็งกึ่งเหลว ให้วิเคราะห์คุณลักษณะของเสีย ตามเอกสารแนบ 4 (05-EN-F031/01)

4.3.2.4 การกำจัด/บำบัด ด้วยวิธีการอื่นๆ ที่ต้องการผลการวิเคราะห์ เพื่อประกอบการพิจารณา

4.4 การส่งตัวอย่างวิเคราะห์

4.4.1 แผนกขายและลูกค้าสัมพันธ์จะส่งตัวอย่างไปเก็บที่ห้องปฏิบัติการวิเคราะห์โดยตรง

4.4.2 แผนกขายและลูกค้าสัมพันธ์ ทำการกรอกรายละเอียดเกี่ยวกับลูกค้าและกากของเสียลงในแบบคำร้องขอวิเคราะห์ตัวอย่าง

4.4.3 แผนกสิ่งแวดล้อมฯ ระบุพารามิเตอร์ที่ต้องการวิเคราะห์ (เอกสารแนบ 3) และจัดส่งเอกสารพร้อมส่งสำเนาทางอีเมลให้กับแผนกห้องปฏิบัติการวิเคราะห์

*** การพิจารณารับของเสียของลูกค้า นั้น จะอ้างอิงจากผลวิเคราะห์จากห้องปฏิบัติการฯ ของทางบริษัท เวสท์ แมเนจเม้นท์ สยาม จำกัด เท่านั้น โดยทางผู้แทนขายจะเป็นผู้เก็บตัวอย่างเพื่อส่งทำการวิเคราะห์ลักษณะทางกายภาพและ/หรือพารามิเตอร์อื่นๆ ตามที่แผนกสิ่งแวดล้อมฯ เห็นว่าเหมาะสม โดยผลการวิเคราะห์ จะแล้วเสร็จภายใน 10 วันทำการ สำหรับในกรณีที่มีความจำเป็น ห้องปฏิบัติการฯ ของบริษัทฯ สามารถพิจารณาในการส่งตัวอย่างไปวิเคราะห์ยังห้องปฏิบัติการภายนอกที่มีมาตรฐานในการทำงานตามที่บริษัทฯ กำหนดได้ ทั้งนี้ลูกค้าหรือเจ้าหน้าที่ฝ่ายขายไม่สามารถส่งตัวอย่างไปยังห้องปฏิบัติการภายนอกได้โดยตรงได้ เนื่องจากบริษัทฯ จะรับรองผลการวิเคราะห์ที่ผ่านการพิจารณาและรับรองจากห้องปฏิบัติการของทางบริษัทฯ เท่านั้น

4.4.4 ห้องปฏิบัติการรับตัวอย่างและเอกสารต่างๆ และทำการลงบันทึกวันที่รับตัวอย่างของเสีย ชื่อลูกค้า ชื่อกากของเสีย หมายเลขของเสีย ชื่อห้องปฏิบัติการ รายการของเสียที่ต้องการวิเคราะห์ และหมายเลขตัวอย่างทั้งในแบบรายการวิเคราะห์ตัวอย่างและบันทึกการรับตัวอย่างของเสีย

4.4.5 เมื่อทำการวิเคราะห์แล้วเสร็จ ห้องปฏิบัติการฯ จะส่งผลการวิเคราะห์ให้แผนกสิ่งแวดล้อมฯ เพื่อแนบในระบบ E-quote

| | |
|---|---------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-EN-S014T |
| เรื่อง: ขั้นตอนการตัดสินใจก่อนรับกำจัด/บำบัดของเสีย โดยระบบอิเล็กทรอนิกส์ | หน้าที่: 5 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกสิ่งแวดล้อม วันที่: 26 พ.ค. 63 | วันที่มีผลบังคับใช้: 1 มิ.ย. 63 |
| อนุมัติโดย: [REDACTED] | แก้ไขครั้งที่: 0 |

4.5 การยื่นขอรับพิจารณาของเสียเข้ามาบำบัด / กำจัด ในโครงการฯ

4.5.1 เจ้าหน้าที่ฝ่ายขาย นำเข้าข้อมูลจากรายละเอียดการกำเนิดของเสียและคุณลักษณะของเสีย (Waste Profile Form) ที่ได้รับจากลูกค้า (เอกสารแนบ 2) เข้าสู่ระบบการขอรับพิจารณา

4.5.2 ขั้นตอนการตัดสินใจรับกำจัด / บำบัดของเสีย

4.5.2.1 แผนกปฏิบัติการ ทำการพิจารณาข้อมูลของเสียและผลการวิเคราะห์ (ในกรณีที่มี)

- กรณีที่สามารถรับได้ แผนกปฏิบัติการบันทึกผลการพิจารณาและให้ข้อมูลราคากำจัด / บำบัด

- กรณีไม่สามารถรับได้ แผนกปฏิบัติการบันทึกเหตุผลที่ไม่สามารถรับได้หรือระบุข้อมูลที่ต้องการเพิ่มเติม

4.5.2.2 แผนกสิ่งแวดล้อมฯ

- พิจารณาจากผลการวิเคราะห์ตามประกาศกระทรวงอุตสาหกรรม เรื่อง การกำจัด/บำบัดสิ่งปฏิกูลหรือ วัสดุที่ไม่ใช้แล้ว พ.ศ.2548 และ/หรือเกณฑ์การกำหนดองค์ประกอบของวัสดุที่ไม่ใช้แล้วที่จะนำไปกำจัด/บำบัด โดยวิธีการที่ถูกต้องและเหมาะสม ร่วมกับผลการพิจารณาจากแผนกปฏิบัติการ

- ดำเนินการทำการตัดสินใจก่อนรับกำจัด / บำบัดของเสียหรือแบบ P/A ผ่านระบบ E-quotes โดยแบบ P/A จะถูกบันทึกเพื่อเป็นหลักฐานการรับของเสียในระบบ และเป็นเอกสารอ้างอิงคุณลักษณะของของเสียจากการพิจารณารับของเสียของหน่วยงานที่เกี่ยวข้อง

4.5.3 การดำเนินการจากผลการพิจารณารับของเสียเข้ามาบำบัด / กำจัด ในโครงการฯ

4.5.3.1 กรณีอนุมัติรับของเสียเข้ามาบำบัด / กำจัด ในโครงการฯ

- แผนกขายและลูกค้าสัมพันธ์จัดเก็บแบบ P/A ไว้ที่แฟ้มข้อมูลลูกค้า

- แผนกขายและลูกค้าสัมพันธ์จัดทำใบเสนอราคาผ่านระบบ E-quote นำส่งผู้ประกอบการเพื่อพิจารณา

- แผนกขายและลูกค้าสัมพันธ์ แจ้งผลการพิจารณารับของเสีย พร้อมรายละเอียดการยื่นขออนุญาตนำของเสียออกนอกโรงงานโดยผ่านระบบอิเล็กทรอนิกส์

4.5.3.2 กรณีที่แผนกสิ่งแวดล้อมฯ พิจารณาไม่อนุมัติรับของเสียเข้ามาบำบัด / กำจัด ในโครงการฯ แผนกสิ่งแวดล้อมฯ นำผลการพิจารณาเข้าที่ประชุมคณะกรรมการด้านกฎหมายและธรรมาภิบาลของโครงการ

- กรณีที่คณะกรรมการฯ พิจารณาอนุมัติรับฯ ให้ปฏิบัติตามข้อ 4.5.3.1

| | |
|---|---------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-EN-S014T |
| เรื่อง: ขั้นตอนการตัดสินใจก่อนรับกำจัด/บำบัดของเสีย โดยระบบอิเล็กทรอนิกส์ | หน้าที่: 6 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกสิ่งแวดล้อม วันที่: 26 พ.ค. 63 | วันที่มีผลบังคับใช้: 1 มิ.ย. 63 |
| อนุมัติโดย: [REDACTED] | แก้ไขครั้งที่: 0 |

- กรณีไม่อนุมัติรับ แผนกสิ่งแวดล้อมบันทึกผลการพิจารณา โดยแผนกขายและลูกค้าสัมพันธ์ แจ้งผลการพิจารณารับของเสียให้ลูกค้ารับทราบ

4.6 รายการของเสียที่ยื่นเข้ารับพิจารณาผ่านระบบ E-Quote จะได้รับการพิจารณาโดยผู้รับผิดชอบในส่วนที่เกี่ยวข้องกับการทำงานของส่วนงานนั้นๆ (อ้างอิงตามแผนผังขั้นตอนการรับของเสีย)

- ในกรณีของเสียที่ต้องการเข้ารับการพิจารณาเร่งด่วน หรือรอการพิจารณาเกินระยะเวลาดำเนินการปกติ ให้แผนกขายและลูกค้าสัมพันธ์ทำการแจ้งขอเข้าพิจารณาจากการประชุมคณะกรรมการฯ เป็นกรณีพิเศษ ซึ่งคณะกรรมการฯ ดังกล่าวประกอบด้วยผู้แทนจากแผนกขายและลูกค้าสัมพันธ์ แผนกสิ่งแวดล้อม แผนกปฏิบัติการ ฝ่ายบริหารจัดการโรงงาน ผู้จัดการทั่วไป บัญชีและอื่นๆ

- หลังจากการพิจารณา แผนกสิ่งแวดล้อม ทำการบันทึกผลการพิจารณาในระบบ E-quote

หากข้อมูลของเสียและลักษณะของเสียมีรายละเอียดไม่เพียงพอต่อการพิจารณาตัดสินใจรับ รวมทั้งหากแผนกสิ่งแวดล้อมไม่ได้รับเอกสารข้อมูลความปลอดภัยของของเสีย ผลการวิเคราะห์ตัวอย่าง รวมถึงเอกสารต่างๆ ที่เกี่ยวข้องตามที่แผนกสิ่งแวดล้อมร้องขอเพิ่มเติม แผนกสิ่งแวดล้อมจะยังไม่ทำการพิจารณารับกากของเสีย จนกว่าจะได้รับรายละเอียดต่างๆ อย่างครบถ้วน ซึ่งแผนกสิ่งแวดล้อมจะแจ้งเหตุผลกลับไปยังแผนกขายและลูกค้าสัมพันธ์ เพื่อดำเนินการต่อไป และจะถือว่าลูกค้านั้นๆ ยังไม่ได้รับขอแบบ P/A จนกว่าจะดำเนินการตามเหตุผลที่แจ้งไว้จนแล้วเสร็จ

4.7 หากผู้ประกอบการมีการเปลี่ยนแปลงกระบวนการผลิต หรือลักษณะของของเสียมีการเปลี่ยนแปลงไปจากเดิม จะต้องดำเนินการตัดสินใจตามขั้นตอนก่อนรับกำจัด/บำบัดของเสียใหม่ทั้งหมด

4.8 แบบการตัดสินใจรับกากของเสีย โดยระบบอิเล็กทรอนิกส์นั้น จะถูกแจ้งเตือนโดยระบบทุกๆ 1 ปี เพื่อให้ดำเนินการแก้ไข และปรับปรุงให้ทันสมัยอยู่เสมอ

4.9 การประเมินของเสียที่จะรับเข้าดำเนินการในโครงการฯ ขึ้นอยู่กับขอบเขตการตัดสินใจรับกากของเสีย (เอกสารแนบ 4), การประเมินผลการวิเคราะห์ของเสียด้วยวิธี Finger Print Test (เอกสารแนบ 5) และการประเมินผลการวิเคราะห์ของเสียโดยค่าโลหะหนัก (เอกสารแนบ 6) และหรือ ขึ้นอยู่กับการตัดสินใจของผู้ที่รับดำเนินการบำบัด/กำจัด/บำบัดของเสียนั้นๆ แล้วแต่กรณีไป

4.10 กรณีของเสียที่ผู้ประกอบการส่งมากำจัด/บำบัด ไม่ตรงตามที่ยื่นพิจารณาไว้ (Off spec) จะต้องมีการพิจารณาการจัดการของเสียนั้นโดยคณะกรรมการฯ โดยผลของการพิจารณานั้นต้องไม่ขัดแย้งกับใบอนุญาตของเสียออกนอกโรงงานของผู้ประกอบการ แผนกสิ่งแวดล้อมจัดทำเอกสารรายงานที่ไม่สอดคล้อง (Off-spec report) จัดส่งให้ผู้ที่เกี่ยวข้องเพื่อดำเนินการต่อไป

| | |
|---|---------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-EN-S014T |
| เรื่อง: ขั้นตอนการตัดสินใจก่อนรับกำจัด/บำบัดของเสีย โดยระบบอิเล็กทรอนิกส์ | หน้าที่: 7 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกสิ่งแวดล้อม วันที่: 26 พ.ค. 63 | วันที่มีผลบังคับใช้: 1 มิ.ย. 63 |
| อนุมัติโดย: [REDACTED] | แก้ไขครั้งที่: 0 |

4.11 ในกรณีมีการปรับแก้ P/A หรือพิจารณาใหม่ ให้ระบุวันที่จัดทำ P/A ให้ตรงกับวันที่ของ WSP ที่ได้รับการอนุญาตจากกรมโรงงานอุตสาหกรรมแล้ว

4.12 ระบบ E-Quote จะทำการแจ้งเตือนล่วงหน้าเป็นเวลา 60 วัน ก่อนผลการตัดสินใจรับกำจัด/บำบัดของเสียจะหมดอายุ

- แผนกขายและลูกค้าสัมพันธ์ ดำเนินการแก้ไข PA ในระบบเพื่อเข้ารับการพิจารณาต่อไป ภายใน 15 วัน นับจากวันที่ระบบแจ้งเตือน

- แผนกสิ่งแวดล้อมแจ้งให้แผนกรับของเสีย เก็บตัวอย่างจากเที่ยวการขนส่งในรอบถัดไป (TRO) ของผู้ประกอบการเพื่อส่งวิเคราะห์

- แผนกปฏิบัติการวิเคราะห์ ทำการวิเคราะห์และยื่นผลการวิเคราะห์ให้ทางแผนกสิ่งแวดล้อมรับทราบและบันทึกผลในระบบต่อไป

- เข้ารับการพิจารณาตามกระบวนการพิจารณารับของเสีย ตามข้อ 4.5

4.12.1 กรณีของเสียเป็นขยะมูลฝอยจากโรงงานอุตสาหกรรม ผลการพิจารณารับของเสียจะมีอายุ 3 ปี

4.12.2 กรณีของเสียเป็นขยะอุตสาหกรรม ผลการพิจารณารับของเสียจะมีอายุ 1 ปี

5. เอกสารอ้างอิง

5.1 แฟ้มข้อมูลลูกค้าและข้อมูลของสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว

5.2 ประกาศกระทรวงอุตสาหกรรม เรื่อง การกำจัด/บำบัดสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว พ.ศ. 2548

5.3 ประกาศกระทรวงอุตสาหกรรม เรื่อง บัญชีรายชื่อวัตถุอันตราย พ.ศ. 2556

5.4 ประกาศกรมเชื้อเพลิงธรรมชาติ เรื่อง กำหนดมาตรการการจัดการของเสียจากสถานประกอบกิจการปิโตรเลียม พ.ศ. 2556

5.5 ประกาศกรมนิคมอุตสาหกรรมแห่งประเทศไทยที่ 79/2554 เรื่องวิธีปฏิบัติเกี่ยวกับการจัดการกากอุตสาหกรรม มูลฝอย และสิ่งปฏิกูลที่เกิดขึ้นในนิคมอุตสาหกรรม

5.6 พระราชบัญญัติการสาธารณสุข พ.ศ. 2535 และ พระราชบัญญัติการสาธารณสุข (ฉบับที่ 2) พ.ศ. 2550

5.7 ขั้นตอนการพิจารณารับกากของเสียอันตราย

| | |
|---|---------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-EN-S014T |
| เรื่อง: ขั้นตอนการตัดสินใจก่อนรับกำจัด/บำบัดของเสีย โดยระบบอิเล็กทรอนิกส์ | หน้าที่: 8 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกสิ่งแวดล้อม วันที่: 26 พ.ค. 63 | วันที่มีผลบังคับใช้: 1 มิ.ย. 63 |
| อนุมัติโดย: [Signature] | แก้ไขครั้งที่: 0 |

6. ประมวลคำศัพท์


P/A : Pre-Acceptance Decision, แบบการตัดสินใจก่อนรับกำจัด/บำบัดของเสีย

FPT : Finger Print Test, การวิเคราะห์ลักษณะทางกายภาพ

7. คำนิยาม

- 7.1 ของเสียไม่อันตราย หมายถึงสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้วที่เกิดจากการประกอบกิจการโรงงาน รวมถึงของเสียจากวัตถุดิบ ของเสียที่เกิดขึ้นในกระบวนการผลิต ของเสียที่เป็นผลิตภัณฑ์เสื่อมคุณภาพ และน้ำทิ้งที่มีองค์ประกอบหรือมีคุณลักษณะที่ไม่เป็นอันตราย ของเสียดังกล่าวต้องไม่มีองค์ประกอบ หรือปนเปื้อนสารอันตราย หรือมีคุณสมบัติที่เป็นอันตรายตามที่กำหนดในภาคผนวกที่ 2 แนบท้ายประกาศกระทรวงอุตสาหกรรม พ.ศ. 2548
- 7.2 ของเสียอันตราย หมายถึงสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว ที่มีองค์ประกอบหรือปนเปื้อนสารอันตรายมีคุณลักษณะที่เป็นอันตราย ตามที่กำหนดในภาคผนวกที่ 2 แนบท้ายประกาศกระทรวงอุตสาหกรรม พ.ศ. 2548
- 7.3 มูลฝอย หมายถึง เศษกระดาษ เศษผ้า เศษอาหาร เศษสินค้า เศษวัตถุ ถุงพลาสติก ภาชนะใส่อาหาร เถ้า มูลสัตว์ ขากสัตว์ หรือสิ่งอื่นใดที่เก็บกวาดจากถนน ตลาด ที่เลี้ยงสัตว์ หรือที่อื่น และหมายความรวมถึงมูลฝอยติดเชื้อ มูลฝอยที่เป็นพิษหรืออันตรายจากชุมชน
- 7.4 วัสดุรีไซเคิลได้ หมายถึง วัสดุที่สามารถนำมารีไซเคิลได้ เช่น กระดาษแข็ง, กระป๋องอลูมิเนียม, พลาสติก, แก้ว, กระดาษ เป็นต้น ซึ่งมาจากการคัดแยกจากโรงงานอุตสาหกรรม, ขยะมูลฝอย, ขยะชุมชน หรือรับซื้อจากของเสียอุตสาหกรรม
- 7.5 E-quotes หมายถึง โปรแกรมเพื่อดำเนินการทุกอย่างเกี่ยวกับกากของเสียของลูกค้า เช่น แบบการตัดสินใจรับกากของเสีย, ข้อมูลลูกค้า, ข้อมูลกากของเสีย เป็นต้น


Pre-Acceptance Waste Flow Diagram



Remarks:

- PA process to covers external waste handling for treatment, disposal, possession, decontamination.
- PA for transfer station to be remarked for further management or destination. transfer waste is responsible by TD
- *** need confirm quotation from destination to set up as operation cost of transfer station
- PA permit will be expired the same date of WSP. (WSP will be main permit to consider expired date) only industrial waste (export waste need to be rely on export permit and WSP only apply for domestic waste)
- CS to provide WSP permit information to EN to fill in expire date
- PA to be rejected (not accept) automatically in case of waste characteristic change (lab result change).
- Consideration and comment from each step need to forward to further process and CS/Sale to submit more information except comment regard to legal opinion from EN which not needs to argue
- Non-response PA request to be automatically deleted within 6 months
- in case of non response PA, ENVI will click on holding so CS/Sales need to consider for further process

PA Renewal



Remark:

- Commercial waste P/A, expiration period 3 years
 - Industrial waste and Non-factory customer, expiration period 1 year
- update with WSP permit

Attachment 1

เอกสารแนบ 1

Per-acceptance process

ขั้นตอนการตัดสินใจก่อนรับกำจัด/บำบัดของเสีย

WMS a member of DOWA 02-SC-F002/06 WASTE PROFILE FORM Waste Profile No. Fill out separate profile for each waste type / photo copy this form as necessary กรุณาแยกกรอกแบบฟอร์มตามประเภทของสิ่งปฏิกูล (หนึ่งแบบฟอร์มสำหรับสิ่งปฏิกูลหนึ่งประเภท) 1.1 สถานที่ก่อกำเนิดของเสีย (Sources of Waste Generation) ชื่อสถานประกอบการ (Facility Name) ที่อยู่ (Address) เลขที่ No หมู่ที่/Moo ถนน/Road ตำบล/Tambon อำเภอ/Ampher จังหวัด/Province รหัสไปรษณีย์/Post Code นิคมอุตสาหกรรม (Industrial Estate) ชื่อผู้ติดต่อ (Contact person) ตำแหน่ง (Position) Phone Fax E-mail เลขทะเบียนโรงงาน (Factory ID) ประเภทมาตรฐานอุตสาหกรรม (TSIC) ประเภทของกิจการ (Business Description) เลขประจำตัว 13 หลัก (DIW-G) 1.2 ข้อมูลทางบัญชี (Billing Information) ชื่อในการเรียกเก็บเงิน (Billing Company Name) ที่อยู่ในการเรียกเก็บเงิน (Billing Address) เลขที่ No หมู่ที่/Moo ถนน/Road ตำบล/T อำเภอ/Ampher จังหวัด/Province รหัสไปรษณีย์/Post Code ผู้ดูแลด้านบัญชี (Billing Contact) ตำแหน่ง (Position) Phone Fax E-mail 2. ข้อมูลของเสีย (Waste Information) ชื่อของเสีย (Waste Name) ชื่อทางเทคนิค (Technical Name) if any แหล่งที่มา (Waste Origin) กระบวนการผลิต (Process) วัสดุไม่ได้คุณภาพ (Off Spec Material) การซ่อมบำรุง (Maintenance) กระบวนการบำบัด (Treatment Process) การทำความสะอาด (Cleaning) อื่นๆ (Others) อธิบายกระบวนการที่ทำให้เกิดวัสดุที่ไม่ใช่แล้ว (General Description of Waste Generation Process) หมายเหตุเพิ่มเติมในภาคผนวก 3. ข้อมูลการปฏิบัติตามข้อกำหนด (Compliance Information) ต้องการ (Yes) ไม่ต้องการ (No) **WSP Number: **WSP Expire Date: ** Fill in after WSP approve 4. ข้อมูลการปฏิบัติตามข้อกำหนด (Compliance Information) Waste Code according to MOI notification year 2548 วัสดุของเสีย/Waste Code รายละเอียด/Description ขยะที่ยกเว้นไม่ต้องปฏิบัติตาม ประกาศกระทรวงฯ เรื่องการกำจัดสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว พ.ศ. 2548 ได้แก่ Wastes that not required to comply with MOI notification Year 2548 as shown below สิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วที่เป็นอันตรายจากสำนักงาน บ้านพักอาศัย และโรงพยาบาลในบริเวณโรงงาน (หมวดข้อ 5.1)

WMS a member of DOWA 02-SC-F002/06 WASTE PROFILE FORM Waste Profile No. Fill out separate profile for each waste type / photo copy this form as necessary กรุณาแยกกรอกแบบฟอร์มตามประเภทของสิ่งปฏิกูล (หนึ่งแบบฟอร์มสำหรับสิ่งปฏิกูลหนึ่งประเภท) Non-haz waste or unused materials from offices, residences and canteens in the factory area (Cat 1, Sect 5.1) สิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วที่มีกฎหมายควบคุมเฉพาะ: ขยะย่อยตามกฎหมายว่าด้วยสาธารณสุข (หมวด 1 ข้อ 5.2.2) Unused materials or materials that specifically controlled: Solid waste under Public Health Act (Sect1, Article 5.2.2) วัสดุรีไซเคิล Recyclable Materials สิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วที่มีกฎหมายควบคุมเฉพาะอื่นๆ (โปรดระบุ) Unused materials or materials that are specifically controlled by other laws: Please specify 2.2.2 ประเภทของเสียอันตรายจากสถานประกอบการปิโตรเลียม Waste from Oil&Gas Process วัสดุของเสีย/Waste Code รายละเอียด/Description 2.2.3 ประเภทของวัตถุอันตรายตามประกาศกระทรวงอุตสาหกรรม บัญชีรายชื่อวัตถุอันตราย พ.ศ. 2556 Hazardous Substance วัสดุของเสีย/Waste Code รายละเอียด/Description ใส่ข้อมูลได้ทั้ง 2.2.1 / 2.2.2 / 2.2.3 ในกรณีที่เลือก 2.2.1 ให้เลือกว่ามี หรือ ไม่มีรหัสการจัดตามประกาศปี 48 Able to select 2.2.1 / 2.2.2 / 2.2.3 if apply all (in case of 2.2.1 please select whether that waste fall on MOI notification or not) 3. ข้อมูลการปฏิบัติตามข้อกำหนด (Material Composition) สรุทางเคมี (Chemical Formula) CAS No. สัดส่วน % (Content) 4. ข้อมูลการปฏิบัติตามข้อกำหนด (Waste Characteristics) ความเป็นเนื้อเดียวกัน (Homogenous) ใช่ (Yes) ไม่ (No) พีเอช (pH): ลักษณะของเสียหรือวัสดุ (State) ของแข็ง (Solid) ขนาด (Max. size, mm.) การฟุ้งกระจาย (Dust Generation) ใช่ (Yes) ไม่ (No) แห้ง (Dry solid) > 150 5 - 50 วัสดุแปลกปลอม (Foreign Bodies) ใช่ (Yes) ไม่ (No) เปียก (Wet Solid) 150 - 50 < 5 ความเหนียว (Stickiness) ใช่ (Yes) ไม่ (No) ฝุ่น / ผง (Powder) 5. ข้อมูลการปฏิบัติตามข้อกำหนด (Waste Characteristics) โคลน (Pasty / Sludge) วัสดุแปลกปลอม (Foreign Bodies) ใช่ (Yes) ไม่ (No) สูบได้ (Pumpable) ความเหนียว (Stickiness) ใช่ (Yes) ไม่ (No) สูบไม่ได้ (Unpumpable) อนุภาค (Particles) ใช่ (Yes) ไม่ (No) 6. ข้อมูลการปฏิบัติตามข้อกำหนด (Waste Characteristics) ของเหลว (Liquid) % ความหนืด (Viscosity) > 10 (Aqueous) ใช่ (Yes) ไม่ (No) น้ำ (Aqueous) อิมัลชัน (Emulsion) อนุภาค (Particles) ใช่ (Yes) ไม่ (No) สารเคมี (Chemical) แยกชั้น (Multi phases) การตกตะกอน (Sedimentation) ใช่ (Yes) ไม่ (No) 7. ข้อมูลการปฏิบัติตามข้อกำหนด (Waste Characteristics) กลิ่น (Odor) รุนแรง (Strong) ปานกลาง (Moderate) ไม่มี (None) สี (Color): ลักษณะอื่นๆ (Other characteristics): การติดไฟ (Combustibility) ไม่ติดไฟ (Incombustible) ติดไฟ (Combustible) จุดวาบไฟต่ำ (Low flash point)

WASTE PROFILE FORM

Waste Profile No. _____

Fill out separate profile for each waste type / photo copy this form as necessary

กรุณาแยกกรอกแบบฟอร์มตามประเภทของสิ่งปฏิกูล (หนึ่งแบบฟอร์มสำหรับสิ่งปฏิกูลหนึ่งประเภท)

การเกิดก๊าซ (Gas Generation) ☐ ไม่เกิด (None) ☐ HF ☐ HCl ☐ NH₃ ☐ HCN ☐ SO₂ ☐ NO₂ ☐ H₂ ☐ Other _____

ความเป็นพิษ (Toxicity) ☐ ไม่มี (None) ☐ ตา (Eye) ☐ ผิวหนัง (Skin) ☐ การหายใจ (Inhalation) ☐ การระเบิด (Explosive) ☐ Other _____

การกัดกร่อน (Corrosivity) ☐ ไม่มี (None) ☐ เหล็ก (Iron) ☐ ยาง (Rubber) ☐ พลาสติก (Plastic) ☐ พีวีซี (PVC) ☐ Other _____

การเกิดปฏิกิริยา (Reactivity) ☐ ไม่มี (None) ☐ ของเสีย (Waste) ☐ กรด (Acid) ☐ ด่าง (Alkali) ☐ สารอินทรีย์ (Organic) ☐ Other _____

การเกิดปฏิกิริยาดังตัวเอง (Self-reaction) ☐ ไม่มี (None) ☐ เมื่อถูกจัดเก็บเป็นเวลานาน (Change overtime) ☐ เมื่ออุณหภูมิเปลี่ยน (Change overtemp)

การเกิดปฏิกิริยาที่อันตราย (Hazardous Reaction)

การกรอก Y = ใช่ หรือ N = ไม่ (Please complement with Y : Yes or N : No)

| การสัมผัส (Exposure to) : | เกิดไอที่เป็นพิษ (Toxic vapor) | การลุกไหม้ (Heating/Ignition) | การระเบิด (Explosion) | การเกิดโพลิเมอร์ (Polymerization) | การเป็นของแข็ง (Solidification) |
|--------------------------------|--------------------------------|-------------------------------|-----------------------|-----------------------------------|---------------------------------|
| อุณหภูมิสูง (High Temperature) | | | | | |
| ความดันสูง (High Pressure) | | | | | |
| การสัมผัสกับ (Contact with) : | | | | | |
| น้ำ (Water) | | | | | |
| อากาศ (Air) | | | | | |
| กรด (Acid) | | | | | |
| ด่าง (Alkaline Solution) | | | | | |
| ออกซิไดซ์ (Oxidants) | | | | | |
| รีดิวซ์ (Reductants) | | | | | |
| อื่นๆ (Others) | | | | | |

การป้องกันอันตรายส่วนบุคคล (Safety Information)

อุปกรณ์ป้องกันอันตรายส่วนบุคคล (PPE) :

| หน้ากากป้องกัน (Protection Mask) | แว่นตาป้องกัน (Safety Glasses) | ถุงมือป้องกัน (Safety Gloves) | ชุดป้องกันสารเคมี (Chemical-Resistance Cloths) | รองเท้าป้องกัน (Safety Shoe) |
|---|--|--|--|--|
| <input type="checkbox"/>  | <input type="checkbox"/>  | <input type="checkbox"/>  | <input type="checkbox"/>  | <input type="checkbox"/>  |

ข้อมูลเพิ่มเติมในการเลือกใช้ PPE (Additional information for PPE selection) :

การปฐมพยาบาล (First Aid) :

สัมผัสดวงตา (Eye Contact)

สัมผัสผิวหนัง (Skin Contact)

หายใจเข้าไป (Inhalation)

กลืนกินเข้าไป (Ingestion)

อื่นๆ (Others)

ข้อแนะนำเมื่อเกิดเหตุเพลิงไหม้ (Fire Instruction) :

สารดับเพลิง (Extinguishing media)

☐ น้ำ (Water) ☐ โฟม (Foam) ☐ เกล็ดแห้ง (Dry Chemical) ☐ คาร์บอนไดออกไซด์ (CO₂) ☐ ทราย (Inert material)

WASTE PROFILE FORM

Waste Profile No. _____

Fill out separate profile for each waste type / photo copy this form as necessary

กรุณาแยกกรอกแบบฟอร์มตามประเภทของสิ่งปฏิกูล (หนึ่งแบบฟอร์มสำหรับสิ่งปฏิกูลหนึ่งประเภท)

สารเคมีจากการสลายตัว (Combustion Products) _____

ขั้นตอนที่ไม่ควรกระทำ (Inappropriate Measures) _____

ข้อมูลความเสี่ยงเฉพาะ (Specific Risk Instruction) _____

ข้อแนะนำเมื่อเกิดเหตุรั่วไหล (Spill Instruction) : _____

การป้องกันบุคคลที่เกี่ยวข้อง (Protection of Persons) _____

ข้อควรระวังเบื้องต้น (Personal Precaution) _____






การทำความสะอาด (Clean-up Procedure) _____

การกำจัด (Elimination Procedure) _____

ข้อควรระวังสำหรับสิ่งแวดล้อม (Environmental Precaution)

☐ มีผลกระทบต่อน้ำและสิ่งมีชีวิต ☐ มีผลกระทบต่อนดินและสิ่งมีชีวิต ☐ มีผลกระทบต่อดังอากาศ

การติดป้ายเตือน (Hazardous Label)

| | | | | |
|---|---|--|---|--|
| <input type="checkbox"/>  ของเหลวไวไฟ | <input type="checkbox"/>  สารที่สัมผัสกับผิวหนัง ก่อให้เกิดแผลไหม้ | <input type="checkbox"/>  ความเป็นพิษเฉียบพลัน ทางปาก ผิวหนัง การสูด ดมหายใจเข้าไป | <input type="checkbox"/>  สารกัดกร่อนโลหะ การติดกร่อนโลหะ ตามเนื้อผิวสัมผัส | <input type="checkbox"/>  วัตถุอันตราย ระเบิด |
|---|---|--|---|--|

การขนส่งและการเก็บรักษา (Transportation and Storage)

ความถี่ในการส่งมอบ (Delivery Frequency) : ☐ ส่งสม่ำเสมอ (Regular) ☐ เป็นครั้งคราว (Periodic)

ปริมาณ (Volume) _____ ต่อเดือน (TPM) _____ ต่อปี (TPY)

ปริมาณทั้งหมด (Total volume) _____ ตัน

หมายเหตุ : ในการเพิ่มปริมาณของเสียไม่เท่ากับทุกเดือนเนื่องจากปริมาณของเสียที่เกิดขึ้นในแต่ละเดือนเพื่อการจัดการขยะ

| เดือน (Month) | JAN | FEB | MAR | APR | MAY | JUN | JUL | AUG | SEP | OCT | NOV | DEC |
|---------------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| ตัน (Ton) > | | | | | | | | | | | | |

การกำหนดเวลาจัดเก็บ (Pickup Condition)

เวลาจัดเก็บ (Pick Up Time) ☐ Morning (07:00 - 12:00) ☐ Afternoon (12:00 - 17:00) ☐ Night Time (17:00 - 07:00) ☐ Others.....

วันจัดเก็บ (Pick Up Date) ☐ ทุกวัน (Everyday) ☐ วันเว้นวัน (Every Other Day) ☐ ทุกอาทิตย์ (Every Week)

☐ ทุกสองอาทิตย์ (Every 2 Weeks) ☐ ทุกเดือน (Every Month) ☐ รอเต็ม (Wait Until Full)

สถานการณ์ปัจจุบัน (Current Status)


สต็อก (Stock) ☐ ไม่มี (None) ☐ มี / ปริมาณ (Yes / quantity) _____ ตัน (Ton)


การจัดการในปัจจุบัน (Current waste management) _____ ผู้จัดการของเสียในปัจจุบัน (Current waste processor)

ราคาค่าจัดการในปัจจุบัน (Current waste processing price) _____ ค่าจัดการของเสียที่ต้องการ (Desired unit price)

การบรรจุและการขนส่ง (Containments & Transportation) :

| การจัดเก็บที่หน้างาน (Site Containment) | | การขนส่ง (Transportation Mode) | |
|--|--|--|--|
| <input type="checkbox"/> ถุง (Bag) | <input type="checkbox"/> Silo | <input type="checkbox"/> รถ 6 ล้อ (6 Wheels truck) | <input type="checkbox"/> รถแทงเกอร์ (Tanker Truck) |
| <input type="checkbox"/> กระสอบ (Sack) | <input type="checkbox"/> ถัง 1 ลบ.ม. (IBC) | <input type="checkbox"/> รถ 10 ล้อ (10 Wheels truck) | <input type="checkbox"/> รถเซมิเทรเลอร์ (Semi trailer) |
| <input type="checkbox"/> ถุงจัมโบ้ (Jumbo bag) | <input type="checkbox"/> ตลับปากกว้าง (Drum - Large) | <input type="checkbox"/> รถขนาดใหญ่ (Bulky truck) | <input type="checkbox"/> รถฟูลเทรเลอร์ (Full trailer) |



a member of


02-SC-F002/06

WASTE PROFILE FORM

Waste Profile No.

Fill out separate profile for each waste type / photo copy this form as necessary
 กรุณาแยกกรอกแบบฟอร์มตามประเภทของสิ่งปฏิกูล (หนึ่งแบบฟอร์มสำหรับสิ่งปฏิกูลหนึ่งประเภท)

☐ Tank
 ☐ ต้มปอกแคบ (Drum-Small)
 ☐ รถเครน (Crane truck)
 ☐ รถแพลตฟอร์ม (Flat-bed trailer)

☐ อื่นๆ
 ขนาดรถ (Drum size)
 ☐ รถลากจูง (Lugger Truck)
 ☐ รถกระบะ (Pick up Truck)

☐ ที่เค้น (Return)
 ☐ รถโรลออฟ (Roll-off Truck)
 ☐ อื่นๆ

☐ ไม่คืนเค้น (Not Return)
 ☐ กระบะยกเท (Dump)
 ☐ ไม่ต้องการกระบะยกเท (Can't Dump)

ภาพระบุ (Services Container)
 ☐ Roll Off Container
 ☐ REL Container
 ☐ 18 cu.m.
 ☐ 22 cu.m.
 ☐ 30 cu.m.
 ☐ Water Tight
 ☐ 1.25 M³
☐ 1.5 M³
☐ 3 M³
☐ 5 M³

☐ Roll Off Flatbed tanker
 ☐ ISO Tank 25 M³

☐ Roll Off Compactor
 ☐ 3 M³ for Offshore

☐ Lugger Container
 ☐ 4 M³ for Oil & Gas Project

☐ Semi-trailer Tanker 30m3
 ☐ Others please specify.....

10. ขยะจะเก็บตัวอย่าง (Sample) หรือไม่ (Yes/No)
 ☐ เก็บตัวอย่าง (Yes)
 ☐ ไม่เก็บตัวอย่าง (No)

วันที่เก็บตัวอย่าง (Date of Sampling)
 ☐ สุ่มเก็บ (Spot sample)

ผู้เก็บตัวอย่าง (Sampler)
 ☐ เก็บจากสต็อกที่มีอยู่ (Ex stock) ปริมาณ (Volume)
 ตัน

จำนวนของตัวอย่าง (Number of Sample)
 ☐ เก็บแบบรวม (Composite sample)
 ☐ เก็บแบบแยก (Grab sample)

ข้อมูลเพิ่มเติม (Additional Information)*

**** กรณีไม่เก็บตัวอย่างให้แนบ SDS เพื่อประกอบการพิจารณา / attach SDS for consideration in case of no sampling

* หมายเหตุ: โปรดบรรยายและให้รายละเอียด ในกรณีที่ตัวอย่างมีแนวโน้มหรือไม่สามารถเป็นตัวแทนที่สมบูรณ์
 (Explanation of potential non-representative sample is required.)

ผู้ให้บริการเพิ่มให้เอกสารข้อมูลเชิงวิทยาศาสตร์ (Scientific Data) ให้แก่ WMS หรือหน่วยงานที่เกี่ยวข้อง (If necessary, please provide scientific data to WMS or related agency)

ชื่อ Name:
 ตำแหน่ง Position:
 วันที่ Date:

ข้าพเจ้ายืนยันและรับรองว่าข้อมูลในเอกสารข้างบนนี้และเอกสารประกอบใดๆ ในการนี้ มีความสมบูรณ์และถูกต้อง สอดคล้องกับวัตถุหรือของเสียที่จะมีการขนส่งมาให้ บริษัท เวสต์ แมเนจเม้นท์ สยาม จำกัด ในการนี้ที่มีการเปลี่ยนแปลงในกระบวนการกักเก็บวัตถุ/ของเสียข้างต้นที่ทำให้เกิดการเปลี่ยนแปลงคุณสมบัติของวัตถุหรือของเสียในเอกสารข้างบนนี้ เป็นหน้าที่ของข้าพเจ้าที่จะต้องแจ้งให้ทางบริษัท เวสต์ แมเนจเม้นท์ สยาม จำกัด ทราบ

I hereby certify that above information is correct and relevant to waste/material which will be delivered to Waste Management Siam


The modification of any process or material which result to the change of above waste/material characteristics will be duly inform to Waste Managmeent Siam Ltd.


ผู้รับรองข้อมูล Certify Person:
 ตำแหน่ง Title:
 วันที่ Date:

วิธีการกำจัดเดิม :
 ☐ นำมาใช้ใหม่/ขาย (Reuse/Sale)
 ☐ เผาในเตาเผาปูน (Co-process)
 ☐ฝังกลบ (Landfill)
 ☐ รีไซเคิล (Recycle)
 ☐ เตาเผา (Incinerator)
 ☐ อื่นๆ (Other) ระบุ (Specify)

ประเมินการเริ่มให้บริการ (Tentative first shipment schedule) :

ผู้ให้ข้อมูล Prepared by :
 ตำแหน่ง Position:
 วันที่ Date :



a member of


02-SC-F002/06

WASTE PROFILE FORM

Waste Profile No.

Fill out separate profile for each waste type / photo copy this form as necessary
 กรุณาแยกกรอกแบบฟอร์มตามประเภทของสิ่งปฏิกูล (หนึ่งแบบฟอร์มสำหรับสิ่งปฏิกูลหนึ่งประเภท)

แนวทางการดำเนินงานเบื้องต้น :
 ☐ คิดค่าบริการกำจัด (Charge)
 บาท/ตัน
 ☐ ไม่คิดค่าบริการกำจัด (Free-of-Charge)

☐ จัดซื้อเข้ามาใช้งาน (Purchase)
 บาท/ตัน
 ขนส่งโดย Transportation by
 ☐ WMS
 ☐ ลูกค้า/Customer

แนวทางการกำจัดเบื้องต้น :
 ☐ 011 - Sorting คัดแยกประเภทเพื่อจำหน่ายต่อ
 ☐ 059 นำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้วอื่นๆ กลับคืนมาใหม่
 ☐ 021 - Storage เก็บไว้ในภาชนะบรรจุ
 ☐ 065 - P-Chem treatment of wastewater บำบัดน้ำเสียด้วยวิธีการทางเคมีกายภาพ
 ☐ 041 - Alternative Fuel เชื้อเพลิงทดแทนในเตาเผาปูนซีเมนต์
 ☐ 066 - Central Wastewater treatment plant ระบบบำบัดน้ำเสียรวม
 ☐ 042 - Fuel Blending ทำเชื้อเพลิงผสมสำหรับโรงงาน 106
 ☐ 071 Sanitary landfillฝังกลบของเสียไม่อันตราย
 ☐ 043 - Burn for energy recovery เผาเพื่อเอาพลังงาน
 ☐ 072, 073 Secure landfillฝังกลบของเสียอันตราย (ไม่ปรับ/ปรับเสถียร)
 ☐ 044 - Use as co-material in cement kiln วัสดุทดแทนในเตาเผาปูน
 ☐ 074 Non-hazardous incineration เผาทำลายในเตาเผาของเสียไม่อันตราย
 ☐ 049 - Other Recycle Methods นำกลับมาใช้ประโยชน์อื่นๆ
 ☐ 075 Hazardous incineration เผาทำลายในเตาเผาของเสียอันตราย
 ☐ 052 Regeneration of Metal & Metal Compounds เข้ากระบวนการนำโลหะกลับมาใหม่
 ☐ 081 Collect and export ขนรับและส่งออกนอกประเทศ
 ☐ 053 - Acid/Base Regeneation เข้ากระบวนการคืนสภาพกรด/ด่าง
 ☐ Others บำบัดกำจัดด้วยวิธีอื่นๆ

ระยะทางจากผู้ออกเกิดไปยังปลายทางที่คาดว่าจะส่งกำจัดปามัด
 ก.ม.

(Distance from waste generator to waste processor [Km.])

แนวทางการเตรียมของเสียหรือวัสดุเบื้องต้น :
 ☐ Decanting
 ☐ Pre-culling
 ☐ Separation
 ☐ Storage
 ☐ Mixing
 ☐ Shredding
 ☐ Crushing

ผู้ประเมิน :
 ตำแหน่ง :
 วันที่ :





Evaluate by :
 Title :
 Date :





Attachment 2





เอกสารแนบ 2





Waste Profile from





ข้อมูลของสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว Waste profile from





| | | | |
|---|-----------------------|---|-----------------------|
|  a member of  05-EN-F003/01 | |  a member of  05-EN-F003/01 | |
| Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | | Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | |
| Waste Name _____ | | Waste Name _____ | |
| Remark _____ | | Remark _____ | |
| Collected by _____ | Collection Date _____ | Collected by _____ | Collection Date _____ |

| | | | |
|---|-----------------------|---|-----------------------|
|  a member of  05-EN-F003/01 | |  a member of  05-EN-F003/01 | |
| Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | | Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | |
| Waste Name _____ | | Waste Name _____ | |
| Remark _____ | | Remark _____ | |
| Collected by _____ | Collection Date _____ | Collected by _____ | Collection Date _____ |

| | | | |
|---|-----------------------|---|-----------------------|
|  a member of  05-EN-F003/01 | |  a member of  05-EN-F003/01 | |
| Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | | Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | |
| Waste Name _____ | | Waste Name _____ | |
| Remark _____ | | Remark _____ | |
| Collected by _____ | Collection Date _____ | Collected by _____ | Collection Date _____ |

| | | | |
|---|-----------------------|---|-----------------------|
|  a member of  05-EN-F003/01 | |  a member of  05-EN-F003/01 | |
| Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | | Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | |
| Waste Name _____ | | Waste Name _____ | |
| Remark _____ | | Remark _____ | |
| Collected by _____ | Collection Date _____ | Collected by _____ | Collection Date _____ |

| | | | |
|---|-----------------------|---|-----------------------|
|  a member of  05-EN-F003/01 | |  a member of  05-EN-F003/01 | |
| Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | | Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | |
| Waste Name _____ | | Waste Name _____ | |
| Remark _____ | | Remark _____ | |
| Collected by _____ | Collection Date _____ | Collected by _____ | Collection Date _____ |

| | | | |
|---|-----------------------|---|-----------------------|
|  a member of  05-EN-F003/01 | |  a member of  05-EN-F003/01 | |
| Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | | Waste Profile No. <input type="text" value="W"/> <input type="text" value="P"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> | |
| Waste Name _____ | | Waste Name _____ | |
| Remark _____ | | Remark _____ | |
| Collected by _____ | Collection Date _____ | Collected by _____ | Collection Date _____ |

BPEC ANALYSIS REQUEST FORM (แบบคำร้องขอการวิเคราะห์ตัวอย่าง) (No need Cert)

Lab Sample No.(หมายเลขตัวอย่าง)

Report No.(หมายเลขรายงานผล)

Company Name (ชื่อลูกค้า)

Address (ที่อยู่)

Waste Name (ชื่อกากของเสีย)

Waste Profile No.(หมายเลขกากของเสีย)

Manifest No. (หมายเลขใบกำกับการขนส่ง)

Requested by (ผู้เก็บตัวอย่าง)

Date (วันที่)

Time (เวลา)

Submitted by (ผู้ส่งตัวอย่าง)

Date (วันที่)

Time (เวลา)

Received Sample by (รับตัวอย่างโดย)

Date (วันที่)

Time (เวลา)

Attachment 3

เอกสารแนบ 3

Analysis Request from
แบบคำร้องขอวิเคราะห์ตัวอย่าง

| TEST | ANALYSIS REQUISITION | Method/ Equipment | TEST | ANALYSIS REQUISITION | Method/ Equipment |
|--|----------------------|--|--|----------------------|-----------------------|
| 1. Screening Test of waste | | | 3. Water / Wastewater | | |
| Finger Print Test | | | Ammonia แอมโมเนีย | | Photometer |
| Physical Appearance | | | BOD บีโอดี | | Titrimetric |
| Color สี | | Visual inspect | COD ซีโอดี | | Colorimetric |
| Turbidity ความขุ่น | | Visual inspect | Chloride คลอไรด์ | | Titration |
| Viscosity ความหนืด | | Visual inspect | Color สี | | Photometer |
| Layering การแยกชั้น | | Visual inspect | Conductivity ความนำไฟฟ้า | | Conductivity meter |
| Oder กลิ่น | | Inhalation | Cyanide ไซยาไนด์ | | |
| State สถานะ | | Visual inspect | MLSS | | Dried 103-105 °C |
| pH ความเป็นกรด-ด่าง | | pH Paper | MLVSS | | Dried 550 °C |
| Temperature อุณหภูมิ | | Thermometer | Nitrate-Nitrogen ไนเตรท | | |
| Stability & Miscibility ความเสถียร | | | Nitrite-Nitrogen ไนไตรท์ | | |
| Air อากาศ | | Exposure | Oil & Grease น้ำมันและไขมัน | | Partition-Gravimetric |
| Water น้ำ | | Mixture | pH ความเป็นกรด-ด่าง | | pH meter |
| Oil น้ำมัน | | Mixture | Phosphate | | Photometer |
| Base ด่าง | | Mixture | Phosphorus | | Photometer |
| Acid กรด | | Mixture | Salinity ความเค็ม | | |
| Oxidizer ออกซิไดซ์ | | KI starch paper | Sulfide ซัลไฟด์ | | |
| Ignitability Potential จุดติดไฟ | | Alcohol burner | SS สารแขวนลอย | | Dried 103-105 °C |
| Cyanide ไซยาไนด์ | | Cyanide test kit | TDS ของแข็งละลาย | | Dried 180 °C |
| Sulfide ซัลไฟด์ | | Lead acetate paper | Total Hardness ความกระด้าง | | Photometer |
| Polymerize พอลิเมอร์ไรซ์ | | Triethylamine | TKN | | |
| Flash Point การจุดติดไฟ | | Flash Point machine | Acidity สภาพกรด | | Titration |
| Bulk density ความหนาแน่น | | Analytical Balance | Alkalinity สภาพด่าง | | Titration |
| Heating Value ค่าความร้อน | | Calorimeter | | | |
| Moisture Content ความชื้น | | Dried 103-105 °C | 4. Metals Analysis | | ICP |
| Ash Content ปริมาณเถ้า | | Dried 500 °C | | | |
| 2. Solid / Semi-Solid Waste | | | 5. Other | | |
| Chloride คลอไรด์ | | Titration | | | |
| pH ความเป็นกรด-ด่าง | | pH meter | | | |
| | | | | | |
| | | | | | |
| Remark : <input type="checkbox"/> Can analysis <input type="checkbox"/> Cannot analysis <input type="checkbox"/> Waiting equipment and chemical <input type="checkbox"/> No equipment | | | Remark : Sample after tested (ตัวอย่าง/ภาชนะที่ส่งทดสอบ (หมายเหตุ) <input type="checkbox"/> Sample return (ขอรับตัวอย่างคืน) <input type="checkbox"/> Container return only (ขอคืนภาชนะบรรจุ) <input type="checkbox"/> No return (ไม่รับคืน) | | |
| Reason for test <input type="checkbox"/> DIW Compliance <input type="checkbox"/> ISO 14000 Compliance | | | <input type="checkbox"/> Other _____ | | |
| เหตุผลเพื่อขอวิเคราะห์ <input type="checkbox"/> EIA Compliance | | | | | |
| Requested By : (ผู้ขอ) Date. / วันที่ : | | Verified By : (ตรวจสอบโดย) Date. / วันที่ : | Approved By : (อนุมัติโดย) Date. / วันที่ : | | |
| For Laboratory <input type="checkbox"/> Test at LAB-BPEC <input type="checkbox"/> Send analysis to sub-contract in parameter _____ | | | Acknowledged By : (รับทราบโดย) Chemist Date. / วันที่ : | | |

Pre Acceptance Criteria

| Treatment Method | Parameters | Standard | Unit |
|--|---------------------------------------|----------------|--------------------|
| Non-Haz Incinerator - 074 | | | |
| Wastewater | | | |
| 1. Physical & Chemical Properties | | | |
| | pH | 2.5-12.5 | - |
| | Chloride content | ≤ 1 | % by wt |
| | Flash point | ≥ 60 | °C |
| | Ignitability compressed gas | >2.81 at 21 °C | kg/cm ² |
| | LD ₅₀ (Actue oral for rat) | ≥ 2,500 | mg/kg |
| | Sulfide | ≤ 1 | % by wt |
| | Sulfur content | ≤ 1 | % by wt |
| 2. Heavy metal content | | | |
| 2.1 Total Threshold Limit Concentration (TTLC) | | | |
| | Arsenic (As) | < 500 | mg/kg |
| | Barium (Ba) | < 10,000 | mg/kg |
| | Beryllium (Be) | < 75 | mg/kg |
| | Cadmium (Cd) | < 100 | mg/kg |
| | Chromium VI (Cr ⁶⁺) | < 500 | mg/kg |
| | Chromium VIII (Cr ³⁺) | < 2,500 | mg/kg |
| | Cobalt (Co) | < 8,000 | mg/kg |
| | Copper (Cu) | < 2,500 | mg/kg |
| | Lead (Pb) | < 1,000 | mg/kg |
| | Mercury (Hg) | < 20 | mg/kg |
| | Molybdenum (Mo) | < 3,500 | mg/kg |
| | Zinc (Zn) | < 5,000 | mg/kg |
| | Nickel (Ni) | < 2,000 | mg/kg |
| | Silver (Ag) | < 500 | mg/kg |
| | Thallium (Tl) | < 700 | mg/kg |
| | Vanadium (Va) | < 2,400 | mg/kg |
| | Selenium (Se) | < 100 | mg/kg |
| 2.2 Soluble Threshold Limit Concentration (STLC) | | | |
| | Arsenic (As) | < 5.0 | mg/L |
| | Barium (Ba) | < 100 | mg/L |
| | Beryllium (Be) | < 0.75 | mg/L |
| | Cadmium (Cd) | < 1.0 | mg/L |
| | Chromium VI (Cr ⁶⁺) | < 5.0 | mg/L |
| | Chromium VIII (Cr ³⁺) | < 5.0 | mg/L |
| | Cobalt (Co) | < 80 | mg/L |
| | Copper (Cu) | < 25 | mg/L |
| | Lead (Pb) | < 5.0 | mg/L |
| | Mercury (Hg) | < 0.2 | mg/L |
| | Molybdenum (Mo) | < 350 | mg/L |
| | Zinc (Zn) | < 250 | mg/L |
| | Nickel (Ni) | < 20 | mg/L |
| | Silver (Ag) | < 5.0 | mg/L |
| | Thallium (Tl) | < 7.0 | mg/L |
| | Vanadium (Va) | < 24 | mg/L |
| | Selenium (Se) | < 1.0 | mg/L |
| Sludge/Solid | | | |
| 1. Physical & Chemical Properties | | | |
| | pH | ≤ 1 | - |
| | Chloride content | ≤ 1 | % by wt |
| | Moisture content | 28.0 | % |
| | Volatile content | 58.6 | % |
| | Gravity | 0.18 | ton/m ³ |
| | Heating value | 3,600 | kcal/kg |
| | Flash point | ≥ 60 | °C |
| | Ignitability compressed gas | >2.81 at 21 °C | kg/cm ² |
| | LD ₅₀ (Actue oral for rat) | ≥ 2,500 | mg/kg |
| | Sulfide | ≤ 1 | % by wt |
| | Sulfur content | ≤ 1 | % by wt |
| 2. Heavy metal content | | | |
| 2.1 Total Threshold Limit Concentration (TTLC) | | | |
| | Arsenic (As) | < 500 | mg/kg |
| | Barium (Ba) | < 10,000 | mg/kg |
| | Beryllium (Be) | < 75 | mg/kg |
| | Cadmium (Cd) | < 100 | mg/kg |
| | Chromium VI (Cr ⁶⁺) | < 500 | mg/kg |
| | Chromium VIII (Cr ³⁺) | < 2,500 | mg/kg |
| | Cobalt (Co) | < 8,000 | mg/kg |
| | Copper (Cu) | < 2,500 | mg/kg |

Attachment 4

เอกสารแนบ 4

Per Acceptance Criteria

ขอขอบการตัดสินใจรับจากของเสีย

Pre Acceptance Criteria

| Treatment Method | Parameters | Standard | Unit |
|---|----------------------|----------|-------|
| | Lead (Pb) | < 1,000 | mg/kg |
| | Mercury (Hg) | < 20 | mg/kg |
| | Molybdenum (Mo) | < 3,500 | mg/kg |
| | Zinc (Zn) | < 5,000 | mg/kg |
| | Nickel (Ni) | < 2,000 | mg/kg |
| | Silver (Ag) | < 500 | mg/kg |
| | Thallium (Tl) | < 700 | mg/kg |
| | Vanadium (Va) | < 2,400 | mg/kg |
| | Selenium (Se) | < 100 | mg/kg |
| 2.2 Soluble Threshold Limit Concentration (STLC) | | | |
| | Arsenic (As) | < 5.0 | mg/L |
| | Barium (Ba) | < 100 | mg/L |
| | Beryllium (Be) | < 0.75 | mg/L |
| | Cadmium (Cd) | < 1.0 | mg/L |
| | Chromium VI (Cr6+) | < 5.0 | mg/L |
| | Chromium VIII (Cr3+) | < 5.0 | mg/L |
| | Cobalt (Co) | < 80 | mg/L |
| | Copper (Cu) | < 25 | mg/L |
| | Lead (Pb) | < 5.0 | mg/L |
| | Mercury (Hg) | < 0.2 | mg/L |
| | Molybdenum (Mo) | < 350 | mg/L |
| | Zinc (Zn) | < 250 | mg/L |
| | Nickel (Ni) | < 20 | mg/L |
| | Silver (Ag) | < 5.0 | mg/L |
| | Thallium (Tl) | < 7.0 | mg/L |
| | Vanadium (Va) | < 24 | mg/L |
| | Selenium (Se) | < 1.0 | mg/L |

Refer Notification of the Ministry of Industry on Disposal of waste or unusable materials B.E.2548

Prepared by _____

Reviewed by _____

Reviewed by _____

Approved by _____

Attachment 5

เอกสารแนบ 5

Assessment of Finger Print Test Result (FPT)

การประเมินผลการวิเคราะห์ลายนิ้วมือ Finger Print Test (FPT)

Attachment 6
เอกสารแนบ 6

Assessment of Heavy Metal
การประเมินผลภาวะโลหะหนักของเสียโดยค่าโลหะหนัก

Important: This document is the property of Waste Management Siam Ltd. The use of this information is illegal unless you have the written consent of a designate General Manager of Waste Management Siam Ltd.'s organization

[illegible]

Assessment of Heavy Metal

การประเมินผลการวิเคราะห์ของเสียโดย ค่าโลหะหนัก

| Parameter/สาร | TTLC (mg/kg)/ค่าความเข้มข้นทั้งหมดของสิ่งเจือปน* | STLC (mg/l)/ค่าความเข้มข้นของสารจากการสกัดน้ำ* | Remark/ หมายเหตุ |
|-------------------------------------|--|--|------------------|
| Antimony แอนติโมนี | 500 | - | |
| Arsenic สารหนู | 500 | 5 | |
| Barium แบเรียม | 10,000 | 100 | |
| Beryllium เบริลเลียม | 75 | 0.75 | |
| Cadmium แคดเมียม | 100 | 1 | |
| Chromium IV โครเมียมเฮกซะวาเลนต์ | 500 | 5 | |
| Chromium III โครเมียมไตรวาเลนต์ | 2,500 | 5 | |
| Cobalt โคบอลต์ | 8,000 | 80 | |
| Copper ทองแดง | 2,500 | 25 | |
| Lead ตะกั่ว | 1,000 | 5 | |
| Mercury ปรอท | 20 | 0.2 | |
| Molybdenum โมลิบดีนัม | 3,500 | 350 | |
| Nickel นิกเกิล | 2,000 | 20 | |
| Selenium ซีลีเนียม | 100 | 1 | |
| Silver เงิน | 500 | 5 | |
| Thallium ทาลเลียม | 700 | 7 | |
| Vanadium วานาเดียม | 2,400 | 24 | |
| Zinc สังกะสี | 5,000 | 250 | |

* Stanadard as MOI Notification B.E. 2548 Subject Disposal of wastes or unusable materials

มาตรฐานตามประกาศกระทรวงอุตสาหกรรม เรื่องการกำจัดสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว พ.ศ. 2548

เอกสารแนบ 2-3

เกณฑ์ในการป้อนของเสียเข้าสู่เตาเผา

ตารางที่ 2.2.1-6 เกณฑ์ในการรับของเสียที่เป็นอันตรายของโครงการฯ (Acceptance Criteria) ภายหลังการ
ดำเนินโครงการฯ ส่วนขยาย

| ลำดับ ที่ | ดัชนี | หน่วย | เกณฑ์กำหนด ของเสียที่เป็นของแข็ง | เกณฑ์กำหนด ของเสียที่เป็นของเหลว |
|---|--|----------|-------------------------------------|-------------------------------------|
| 1. ลักษณะทางกายภาพและเคมี (Physical & Chemical Properties) | | | | |
| 1. | ความเป็นกรด-ด่าง (pH) | - | 0-14 | 0-14 |
| 2. | จุดวาบไฟ (Flash point) | °C | N/A | N/A |
| 3. | ค่าความร้อน (Gross Calorific Value) | %kcal/kg | N/A | N/A |
| 4. | ค่าความชื้น (Moisture) | % | ≤80 | N/A |
| 5. | สารประกอบซัลเฟอร์ (Sulfur content) | % | ≤30 | ≤30 |
| 6. | สารประกอบคลอไรด์ (Chloride content) | % | ≤30 | ≤30 |
| 2. โลหะหนัก (Heavy metal content) | | | | |
| 1. | สารหนู (As) | mg/kg | 15,000 | 15,000 |
| 2. | โครเมียมทั้งหมด (Total Cr) | mg/kg | N/A | N/A |
| 3. | โครเมียมเฮกซะวาเลนต์ (Cr ⁶⁺) | mg/kg | 15,000 | 15,000 |
| 4. | โครเมียมไตรวาเลนต์ (Cr ³⁺) | mg/kg | 75,000 | 75,000 |
| 5. | แคดเมียม (Cd) | mg/kg | 3,000 | 3,000 |
| 6. | ทองแดง (Cu) | mg/kg | 75,000 | 75,000 |
| 7. | ตะกั่ว (Pb) | mg/kg | 30,000 | 30,000 |
| 8. | สังกะสี (Zn) | mg/kg | 150,000 | 150,000 |
| 9. | เทลลูเรียม (Te) | mg/kg | 21,000 | 21,000 |
| 10. | วานาเดียม (Va) | mg/kg | 72,000 | 72,000 |
| 11. | นิกเกิล (Ni) | mg/kg | 60,000 | 60,000 |
| 12. | ปรอท (Hg) | mg/kg | 600 | 600 |
| 13. | ซีลีเนียม (Se) | mg/kg | 3,000 | 3,000 |
| 14. | แบเรียม (Ba) | mg/kg | 300,000 | 300,000 |
| 15. | เบริเลียม (Be) | mg/kg | 2,250 | 2,250 |
| 16. | แมงกานีส (Mn) | mg/kg | N/A | N/A |
| 17. | พลวง (Sb) | mg/kg | 15,000 | 15,000 |
| 18. | เงิน (Ag) | mg/kg | 15,000 | 15,000 |
| 19. | โคบอลต์ (Co) | mg/kg | 240,000 | 240,000 |
| 20. | โมลิบดีนัม (Mo) | mg/kg | 240,000 | 240,000 |

ที่มา : บริษัท บางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด, 2562

| Treatment Method | Parameters | Standard | Unit |
|---|---------------------------------------|----------------|--------------------|
| Non-Haz Incinerator - 074 | | | |
| Wastewater | | | |
| 1. Physical & Chemical Properties | | | |
| | pH | 2.5-12.5 | - |
| | Chloride content | ≤ 1 | % by wt |
| | Flash point | ≥ 60 | °C |
| | Ignitability compressed gas | >2.81 at 21 °C | kg/cm ² |
| | LD ₅₀ (Actue oral for rat) | ≥ 2,500 | mg/kg |
| | Sulfide | ≤ 1 | % by wt |
| | Sulfur content | ≤ 1 | % by wt |
| 2. Heavy metal content | | | |
| 2.1 Total Threshold Limit Concentration (TTLc) | | | |
| | Arsenic (As) | < 500 | mg/kg |
| | Barium (Ba) | < 10,000 | mg/kg |
| | Beryllium (Be) | < 75 | mg/kg |
| | Cadmium (Cd) | < 100 | mg/kg |
| | Chromium VI (Cr ⁶⁺) | < 500 | mg/kg |
| | Chromium VIII (Cr ³⁺) | < 2,500 | mg/kg |
| | Cobalt (Co) | < 8,000 | mg/kg |
| | Copper (Cu) | < 2,500 | mg/kg |
| | Lead (Pb) | < 1,000 | mg/kg |
| | Mercury (Hg) | < 20 | mg/kg |
| | Molybdenum (Mo) | < 3,500 | mg/kg |
| | Zinc (Zn) | < 5,000 | mg/kg |
| | Nickel (Ni) | < 2,000 | mg/kg |
| | Silver (Ag) | < 500 | mg/kg |
| | Thallium (Ti) | < 700 | mg/kg |
| | Vanadium (Va) | < 2,400 | mg/kg |
| | Selenium (Se) | < 100 | mg/kg |
| 2.2 Soluble Threshold Limit Concentration (STLC) | | | |
| | Arsenic (As) | < 5.0 | mg/L |
| | Barium (Ba) | < 100 | mg/L |
| | Beryllium (Be) | < 0.75 | mg/L |
| | Cadmium (Cd) | < 1.0 | mg/L |
| | Chromium VI (Cr ⁶⁺) | < 5.0 | mg/L |
| | Chromium VIII (Cr ³⁺) | < 5.0 | mg/L |
| | Cobalt (Co) | < 80 | mg/L |
| | Copper (Cu) | < 25 | mg/L |
| | Lead (Pb) | < 5.0 | mg/L |
| | Mercury (Hg) | < 0.2 | mg/L |
| | Molybdenum (Mo) | < 350 | mg/L |
| | Zinc (Zn) | < 250 | mg/L |
| | Nickel (Ni) | < 20 | mg/L |
| | Silver (Ag) | < 5.0 | mg/L |
| | Thallium (Ti) | < 7.0 | mg/L |
| | Vanadium (Va) | < 24 | mg/L |
| | Selenium (Se) | < 1.0 | mg/L |
| Sludge/Solid | | | |
| 1. Physical & Chemical Properties | | | |
| | pH | ≤ 1 | - |
| | Chloride content | ≤ 1 | % by wt |
| | Moisture content | 28.0 | % |
| | Volatile content | 58.6 | % |
| | Gravity | 0.18 | ton/m ³ |
| | Heating value | 3,600 | kcal/kg |
| | Flash point | ≥ 60 | °C |
| | Ignitability compressed gas | >2.81 at 21 °C | kg/cm ² |
| | LD ₅₀ (Actue oral for rat) | ≥ 2,500 | mg/kg |
| | Sulfide | ≤ 1 | % by wt |
| | Sulfur content | < 1 | % by wt |
| 2. Heavy metal content | | | |
| 2.1 Total Threshold Limit Concentration (TTLc) | | | |
| | Arsenic (As) | < 500 | mg/kg |
| | Barium (Ba) | < 10,000 | mg/kg |
| | Beryllium (Be) | < 75 | mg/kg |
| | Cadmium (Cd) | < 100 | mg/kg |
| | Chromium VI (Cr ⁶⁺) | < 500 | mg/kg |
| | Chromium VIII (Cr ³⁺) | < 2,500 | mg/kg |
| | Cobalt (Co) | < 8,000 | mg/kg |
| | Copper (Cu) | < 2,500 | mg/kg |

Pre Acceptance Criteria

| Treatment Method | Parameters | Standard | Unit |
|---|----------------------|----------|-------|
| | Lead (Pb) | < 1,000 | mg/kg |
| | Mercury (Hg) | < 20 | mg/kg |
| | Molybdenum (Mo) | < 3,500 | mg/kg |
| | Zinc (Zn) | < 5,000 | mg/kg |
| | Nickel (Ni) | < 2,000 | mg/kg |
| | Silver (Ag) | < 500 | mg/kg |
| | Thallium (Tl) | < 700 | mg/kg |
| | Vanadium (Va) | < 2,400 | mg/kg |
| | Selenium (Se) | < 100 | mg/kg |
| 2.2 Soluble Threshold Limit Concentration (STLC) | | | |
| | Arsenic (As) | < 5.0 | mg/L |
| | Barium (Ba) | < 100 | mg/L |
| | Beryllium (Be) | < 0.75 | mg/L |
| | Cadmium (Cd) | < 1.0 | mg/L |
| | Chromium VI (Cr6+) | < 5.0 | mg/L |
| | Chromium VIII (Cr3+) | < 5.0 | mg/L |
| | Cobalt (Co) | < 80 | mg/L |
| | Copper (Cu) | < 25 | mg/L |
| | Lead (Pb) | < 5.0 | mg/L |
| | Mercury (Hg) | < 0.2 | mg/L |
| | Molybdenum (Mo) | < 350 | mg/L |
| | Zinc (Zn) | < 250 | mg/L |
| | Nickel (Ni) | < 20 | mg/L |
| | Silver (Ag) | < 5.0 | mg/L |
| | Thallium (Tl) | < 7.0 | mg/L |
| | Vanadium (Va) | < 24 | mg/L |
| | Selenium (Se) | < 1.0 | mg/L |

Refer Notification of the Ministry of Industry on Disposal of waste or unusable materials B.E.2548

เอกสารแนบ 2-4

ตัวอย่างผลการวิเคราะห์ตัวอย่างของเสียก่อนรับกำจัด

Test Report

Report No. : RE25-02-032_1
Revision No. : 0

Customer Name : BIC CHEMICAL CO.,LTD
Address : 177-178 Moo. 11 Kamphaengsaen Subdistrict, Kamphaengsaen District Nakhon Pathom Province 73140

Sample Description

Sample No. : LA25-01-084
Sample Name : Wastewater sludge
Waste Profile No. : WP609005
Sampling By : Korrawit Y.(P-371-A-0001)
Sampling Date : 22/01/2025
Sampling Time : 01:00 PM
Sampling Received Date : 31/01/2025
Sample Test Date : 10/02/2025
Report Date : 13/02/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.1 °C | US EPA. 9040C,9045D ^[1,2] | pH unit | 5.5 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|--------|
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | 10.0 | 0.25 | 2.00 | ≤500 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | 105 | 0.26 | 5.00 | ≤2,500 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 454 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | 31.8 | 1.30 | 2.00 | ≤1,000 |
| Nikel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | 16.8 | 0.37 | 2.00 | ≤2,000 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 3,096 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTL = Total Threshold Limit Concentration.

ND = Not detected.

LOQ = Level of Quantitation.

MDL = Method Detection Limit.

Reported By : Watcharee Suksri
Watcharee Suksri
Laboratory Staff
(P-371-A-0002)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(P-371-A-0001)

Test Report

Report No. : RE25-02-032_2
Revision No. : 0

Customer Name : BIC CHEMICAL CO.,LTD
Address : 177-178 Moo. 11 Kamphaengsaen Subdistrict, Kamphaengsaen District Nakhon Pathom Province 73140

Sample Description

Sample No. : LA25-01-084
Sample Name : Wastewater sludge
Waste Profile No. : WP609005
Sampling By : Korrawit Y.(P-371-A-0001)
Sampling Date : 22/01/2025
Sampling Time : 01:00 PM
Sampling Received Date : 31/01/2025
Sample Test Date : 10/02/2025
Report Date : 13/02/2025

| Test Parameter | Method | Method |
|----------------------------|------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | Brown | ASTM D4979-08 |
| - Color | - | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Homogeneous | |
| - Odor | Mild (Sulfur) | |
| - State | Solid (Sludge) | |
| pH | 5 | ASTM D4980-89 |
| Temperature | 25.4 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Soluble 1% and Sink 99%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Positive (Generated air bubbles) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Positive (High) | ASTM D4978-16 |

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|------|
| Heating value | ASTM D5468-02 Gross Calorific | Cal/g | 1,226 | - | - | - |
| Chloride (Cl) | EPA 9253 Titrimetric, Silver Nitrate | mg/kg | 878 | 4.00 | 5.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[1,2] | mg/kg | 10,078 | 3.77 | 10.0 | - |

Remark : ASTM = American Society for Testing and Materials.

EPA = U.S. Environmental Protection Agency.

LOQ = Level of Quantitation.

MDL = Method Detection Limit.

ND = Not detection.

Reported By : Watcharee Suksri
Watcharee Suksri
Laboratory Staff
(13 / 02 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(13 / 02 / 2025)

Test Report

Report No. : RE25-02-085_1
Revision No. : 0

Customer Name : Alliance Laundry (Thailand) Co., Ltd.
Address : 89/8 Moo 7, Tambol Klongkaeo, Amphur Banbung, Chonburi Province 20220

Sample Description

Sample No. : LA25-02-114
Sample Name : Paint Sludge
Waste Profile No. : WPH010766
Manifest No. : -
Sampling By : Kanlaya K. (๓-212-๓-0003)

Sampling Date : 07/02/2025
Sampling Time : -
Sampling Received Date : 13/02/2025
Sample Test Date : 13/02/2025
Report Date : 28/02/2025

| Test Parameter* | Method | Unit | Result |
|--|---------------------------------|---------|--------|
| Heating Value (Gross Calorific Value) | Bomb Calorimetry ^[4] | kcal/kg | 4,645 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|--------|
| Arsenic (As) | Digestion, ICP Method ^[1, 2] | mg/kg | 5.07 | 0.90 | 5.00 | ≤500 |
| Cadmium (Cd) | Digestion, ICP Method ^[1, 2] | mg/kg | ND | 0.50 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[1, 2] | mg/kg | 4.71 | 0.40 | 2.00 | ≤2,500 |
| Copper (Cu) | Digestion, ICP Method ^[1, 2] | mg/kg | ND | 1.20 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[1, 2] | mg/kg | 2.49 | 1.40 | 2.00 | ≤1,000 |
| Mercury (Hg) | Digestion, Cold-Vapor AAS Method ^[1, 3] | mg/kg | ND | 0.08 | 0.10 | ≤20 |
| Nikel (Ni) | Digestion, ICP Method ^[1, 2] | mg/kg | 2.66 | 0.30 | 2.00 | ≤2,000 |
| Zinc (Zn) | Digestion, ICP Method ^[1, 2] | mg/kg | <5.00 | 2.80 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[2] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010D, 2007

^[3] United States Environmental Protection Agency. Mercury in Solid or Semisolid Waste (Manual Cold-Vapor technique).

SW-846 Method 7471B, 2007


^[4] American Society for Testing and Materials. D5468-02, Standard Test Method for Gross Calorific and Ash Value of Waste Materials.

TTL = Total Threshold Limit Concentration.


LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : 
Chintana Imchit
Chemist
(๓-212-๓-0003)



Reviewed By : 
Thanet Saraban
Laboratory Supervisor
(๓-212-๓-0002)

Test Report

Report No. : RE25-02-085_2
Revision No. : 0

Customer Name : Alliance Laundry (Thailand) Co., Ltd.
Address : 89/8 Moo 7, Tambol Klongkaeo, Amphur Banbung, Chonburi Province 20220

Sample Description


Sample No. : LA25-02-114
Sample Name : Paint Sludge
Waste Profile No. : WPH010766
Manifest No. : -
Sampling By : Kanlaya K.

Sampling Date : 07/02/2025
Sampling Time : -
Sampling Received Date : 13/02/2025
Sample Test Date : 13/02/2025
Report Date : 28/02/2025


| Test Parameter | Method | Result |
|----------------------------|------------------|--|
| Finger print test | | |
| Physical Appearance | ASTM D4979-08 | |
| - Color | | Black |
| - Turbidity | | - |
| - Viscosity | | - |
| - Layering | | Homogeneous |
| - Odor | | Mild |
| - State | | Solid (Lump and sheet; Dry) |
| pH | ASTM D4980-89 | 6 |
| Temperature | Thermometer | 26.7 |
| Stability&Miscibility with | ASTM D5232-19 | |
| - Air | | Negative |
| - Water | | Negative (Insoluble and 100% floating) |
| - Acid | | Negative |
| - Base | | Negative |
| - Leachate | | Negative |
| Oxidizer | ASTM D4981-19 | Negative |
| Ignitability Potential | ASTM D4982-20 | Positive (Immediately) |
| Cyanide | Cyanide Test Kit | Not Available |
| Sulfide | ASTM D4978-16 | Negative |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : 
Chintana Imchit
Chemist
(28 / 02 / 2025)



Reviewed By : 
Thanet Saraban
Laboratory Supervisor
(28 / 02 / 2025)

Test Report

Report No. : RE25-02-085_3
Revision No. : 0

Customer Name : Alliance Laundry (Thailand) Co., Ltd.
Address : 89/8 Moo 7, Tambol Klongkaeo, Amphur Banbung, Chonburi Province 20220

Sample Description

| | |
|-------------------------------|-------------------------------------|
| Sample No. : LA25-02-114 | Sampling Date : 07/02/2025 |
| Sample Name : Paint Sludge | Sampling Time : - |
| Waste Profile No. : WPH010766 | Sampling Received Date : 13/02/2025 |
| Manifest No. : - | Sample Test Date : 13/02/2025 |
| Sampling By : Kanlaya K. | Report Date : 28/02/2025 |

| Test Parameter | Method | Unit | Result |
|-----------------------------|---|-------------------|--------|
| Ash Content (as received) | Dried at 700°C | %(w/w) | 38.7 |
| Bulk Density | ASTM D5057-17 Bulk Density of waste | g/cm ³ | 1.2751 |
| Chloride (Cl ⁻) | EPA 5050 and EPA 9253 Chloride by Bomb | %(w/w) | 0.07 |
| Flash Point | ASTM D3278-78 Closed cup Method | °C | >110 |
| Moisture Content | ASTM D2216-19 ; Dried overnight @ 110±5°C | %(w/w) | 3.30 |
| Sulfur (S) | Digestion, ICP Method ^[1, 2] | %(w/w) | 0.02 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.


Remark : ^[1] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. **SW-846 Method 3050B, 1996**

^[2] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. **SW-846 Method 6010D, 2007**


ASTM = American Society for Testing and Materials.

EPA = U.S. Environmental Protection Agency.

ND = Not detected.

Reported By : 
Chintana Imchit
Chemist
(28 / 02 / 2025)



Reviewed By : 
Thanet Saraban
Laboratory Supervisor
(28 / 02 / 2025)

Test Report

Report No. : RE25-04-013_1
Revision No. : 0

Customer Name : Archroma (Thailand) Co., Ltd.
Address : 851 Moo 4, Bangpoo Industrial Estate Soi12,T.Preaksa Muang Samutprakarn 10280

Sample Description

Sample No. : LA25-03-053
Sample Name : Fuel oil
Waste Profile No. : WPH611119
Sampling By : Watcharee S. (๙-371-๙-0002)

Sampling Date : 24/03/2025
Sampling Time : 10:00 AM
Sampling Received Date : 26/03/2025
Sample Test Date : 08/04/2025
Report Date : 08/04/2025

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|--------|
| Arsenic (As) | Digestion, ICP Method ^(1,2) | mg/kg | ND | 0.25 | 2.00 | ≤500 |
| Cadmium (Cd) | Digestion, ICP Method ^(1,2) | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^(1,2) | mg/kg | ND | 0.26 | 5.00 | ≤2,500 |
| Copper (Cu) | Digestion, ICP Method ^(1,2) | mg/kg | ND | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^(1,2) | mg/kg | ND | 1.30 | 2.00 | ≤1,000 |
| Nikel (Ni) | Digestion, ICP Method ^(1,2) | mg/kg | ND | 0.37 | 2.00 | ≤2,000 |
| Zinc (Zn) | Digestion, ICP Method ^(1,2) | mg/kg | ND | 3.36 | 5.00 | ≤5,000 |

| Test Parameter* | Method | Unit | Result |
|-----------------|---|------|--------|
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ⁽³⁾ | °C | 101.8 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

⁽¹⁾ United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. **SW-846 Method 3050B, 1996**

⁽²⁾ United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. **SW-846 Method 6010C, 2007**

⁽³⁾ American Society for Testing and Materials. **D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020**

TTL = Total Threshold Limit Concentration.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.

Watcharee Suksri
Laboratory Staff
(๙-371-๙-0002)



Reviewed By :

Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)

Test Report

Report No. : RE25-04-013_2
Revision No. : 0

Customer Name : Archroma (Thailand) Co., Ltd.
Address : 851 Moo 4, Bangpoo Industrial Estate Soi12,T.Preaksa Muang Samutprakarn 10280

Sample Description

Sample No. : LA25-03-053
Sample Name : Fuel oil
Waste Profile No. : WPH611119
Sampling By : Watcharee S. (๙-371-๙-0002)

Sampling Date : 24/03/2025
Sampling Time : 10:00 AM
Sampling Received Date : 26/03/2025
Sample Test Date : 08/04/2025
Report Date : 08/04/2025

| Test Parameter | Method | Method |
|----------------------------|---------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | Dark brown | ASTM D4979-08 |
| - Color | Opaque | |
| - Turbidity | Moderate | |
| - Viscosity | - | |
| - Layering | Strong (Oil) | |
| - Odor | Liquid (Single) | |
| - State | | |
| pH | 5 | ASTM D4980-89 |
| Temperature | 26.4 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Insoluble and Float 100%) | |
| - Oil | Compatibility (100% Soluble with oil) | |
| - Base | Negative | |
| - Acid | Negative | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Positive (Before 15 Sec) | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

| Test Parameter* | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Heating value | ASTM D5468-02 Gross Calorific | Cal/g | 10,552 |
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/Kg | 1,044 |
| Sulfur (S) | Digestion, ICP Method ^(1,2) | mg/Kg | 1,191 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.

Watcharee Suksri
Laboratory Staff
(08 / 04 / 2025)



Reviewed By :

Ampol Ruttanasang
Laboratory Controller
(08 / 04 / 2025)

Test Report

Report No. : RE25-05-018_1
Revision No. : 0

Customer Name : TANIO THAI CO.,LTD.
Address : BANGPOO INDUSTRIAL ESTATE, 512 MOO 4, T.PREAKSA,
A.MUANG, SAMUTPRAKARN 10280

Sample Description

Sample No. : LA25-05-006
Sample Name : Wastewater sludge
Waste Profile No. : WP609080
Sampling By : Watcharee S. (๙-371-๙-0002)

Sampling Date : 30/04/2025
Sampling Time : 02:00 PM
Sampling Received Date : 06/05/2025
Sample Test Date : 19/05/2025
Report Date : 20/05/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 26.6 °C | US EPA. 9040C,9045D ^[1,2] | pH unit | 7.8 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTLIC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|--------|
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | 18.9 | 0.25 | 2.00 | ≤500 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | <5.00 | 0.26 | 5.00 | ≤2,500 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 6.49 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | 16.0 | 1.30 | 2.00 | ≤1,000 |
| Nikel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | <2.00 | 0.37 | 2.00 | ≤2,000 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 8.48 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTLIC = Total Threshold Limit Concentration.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(๙-371-๙-0002)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)

Test Report

Report No. : RE25-05-018_2
Revision No. : 0

Customer Name : TANIO THAI CO.,LTD.
Address : BANGPOO INDUSTRIAL ESTATE, 512 MOO 4, T.PREAKSA,
A.MUANG, SAMUTPRAKARN 10280

Sample Description

Sample No. : LA25-05-006
Sample Name : Wastewater sludge
Waste Profile No. : WP609080
Sampling By : Watcharee S. (๙-371-๙-0002)

Sampling Date : 30/04/2025
Sampling Time : 02:00 PM
Sampling Received Date : 06/05/2025
Sample Test Date : 19/05/2025
Report Date : 20/05/2025

| Test Parameter | Method | Method |
|----------------------------|------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | Dark brown | ASTM D4979-08 |
| - Color | - | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Homogeneous | |
| - Odor | Strong (Sulfur) | |
| - State | Solid (Lump) | |
| pH | 6 | ASTM D4980-89 |
| Temperature | 25.6 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Insoluble and Sink 100%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Positive (Occurred air bubbles) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Positive (High) | ASTM D4978-16 |

| Test Parameter* | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Heating value | ASTM D5468-02 Gross Calorific | Cal/g | ND |
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/Kg | 1,619 |
| Sulfur (S) | Digestion, ICP Method ^[1,2] | mg/Kg | 1,238 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(20 / 05 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(20 / 05 / 2025)

Test Report

Report No. : RE25-06-021_1
Revision No. : 0

Customer Name : TDK (Thailand) Co.,Ltd. ๒3-100(5)-2/37 ๒๒
Address : 1/62 Rojana Industrial Park, Moo 5, Tambol Kanham, Amphor Uthai, Ayutthaya 13210

Sample Description

Sample No. : LA25-05-045
Sample Name : Waste water contaminated with paint
Waste Profile No. : WPH611209
Sampling By : Watcharee S. (๙-371-๙-0002)
Sampling Date : 26/05/2025
Sampling Time : 01:30 PM
Sampling Received Date : 28/05/2025
Sample Test Date : 09/06/2025
Report Date : 10/06/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.8 °C | SM 4500-H ⁺ Electrometric Method. ^[1] | pH unit | 10.6 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[2] | °C | >110 |

TTLC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|--------|
| Arsenic (As) | Digestion, ICP Method ^[3,4] | mg/kg | <2.00 | 0.25 | 2.00 | ≤500 |
| Cadmium (Cd) | Digestion, ICP Method ^[3,4] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[3,4] | mg/kg | 5.93 | 0.26 | 5.00 | ≤2,500 |
| Copper (Cu) | Digestion, ICP Method ^[3,4] | mg/kg | ND | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[3,4] | mg/kg | 7.09 | 1.30 | 2.00 | ≤1,000 |
| Nikel (Ni) | Digestion, ICP Method ^[3,4] | mg/kg | 2.33 | 0.37 | 2.00 | ≤2,000 |
| Zinc (Zn) | Digestion, ICP Method ^[3,4] | mg/kg | 76.1 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] APHA, AWWA, WEF, Standard Methods for the Examination of Water and Wastewater, 23rd Ed, Washington D.C. APHA, 2017

^[2] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[3] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[4] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTLC = Total Threshold Limit Concentration.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(๙-371-๙-0002)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)

Test Report

Report No. : RE25-06-021_2
Revision No. : 0

Customer Name : TDK (Thailand) Co.,Ltd. ๒3-100(5)-2/37 ๒๒
Address : 1/62 Rojana Industrial Park, Moo 5, Tambol Kanham, Amphor Uthai, Ayutthaya 13210

Sample Description

Sample No. : LA25-05-045
Sample Name : Waste water contaminated with paint
Waste Profile No. : WPH611209
Sampling By : Watcharee S. (๙-371-๙-0002)
Sampling Date : 26/05/2025
Sampling Time : 01:30 PM
Sampling Received Date : 28/05/2025
Sample Test Date : 09/06/2025
Report Date : 10/06/2025

| Test Parameter | Method | Method |
|----------------------------|--|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Dark gray | |
| - Turbidity | Opaque | |
| - Viscosity | Low | |
| - Layering | - | |
| - Odor | Strong (Ammonia) | |
| - State | Liquid (Multi-phase : Upper 90% Dark gray liquid and Lower 10% Dark gray sludge) | |
| pH | 10 | ASTM D4980-89 |
| Temperature | 24.5 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Soluble 90% and Sink 10%) | |
| - Oil | Non Compatibility | |
| - Base | Negative | |
| - Acid | Positive (Change color from light Dark gray to gray and Occurred air bubbles) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Positive (High) | ASTM D4978-16 |

| Test Parameter* | Method | Unit | Result |
|------------------------------|---|-------|--------|
| Heating value | ASTM D5468-02 Gross Calorific | Cal/g | ND |
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/Kg | 200 |
| Total Dissolved Solids (TDS) | Conductivity meter | mg/L | 14,150 |
| Sulfur (S) | Digestion, ICP Method ^[1,2] | mg/Kg | 5,215 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(10 / 06 / 2025)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(10 / 06 / 2025)

เอกสารแนบ 2-5

สำเนานำส่งผลการตรวจสอบของเสียอันตรายที่ Mixing แล้ว และเข้าต่อ กนอ.

ที่ 2025-043/BPEC/MD/EN

18 มีนาคม 2568

เรื่อง ขอนำส่งผลการตรวจสอบคุณสมบัติของเสียอันตรายหลังทำการผสมก่อนทำการป้อนเข้าสู่เตาเผาและผลวิเคราะห์เถ้าลอยและเถ้าหนัก

เรียน ผู้อำนวยการสำนักงานนิคมอุตสาหกรรมบางปู

สิ่งที่ส่งมาด้วย 1. รายงานผลการตรวจสอบคุณสมบัติของเสียอันตรายหลังทำการผสม (Mixing process) ก่อนทำการป้อนเข้าสู่เตาเผา ประจำเดือนกุมภาพันธ์ พ.ศ. 2568
2. เกณฑ์การพิจารณาในการป้อนของเสียเข้าสู่เตาเผา (Feeding Criteria)
3. ผลวิเคราะห์เถ้าลอยและเถ้าหนัก (Fly ash & Bottom ash)

ตามที่โครงการโรงงานปรับปรุงคุณภาพของเสียรวม (ส่วนขยาย ครั้งที่ 1) ของบริษัทบางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด ได้รับการพิจารณาเห็นชอบในรายงานการประเมินผลกระทบสิ่งแวดล้อม เมื่อวันที่ 9 กรกฎาคม พ.ศ. 2562 และได้รับอนุญาตในการประกอบกิจการดังกล่าวจาก การนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) เมื่อวันที่ 30 ตุลาคม พ.ศ. 2562 ตามความทราบแล้วนั้น ในรายงานการประเมินผลกระทบสิ่งแวดล้อมดังกล่าวระบุให้โครงการฯ ส่งผลการตรวจสอบคุณสมบัติของเสียหลังทำการผสมในแต่ละครั้ง (Batch) และผลวิเคราะห์เถ้าลอยและเถ้าหนักให้คณะกรรมการบริหารจัดการโครงการฯ ของการนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) รับทราบทุกเดือน นั้น

ทางบริษัทบางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด จึงขอนำส่งผลการตรวจสอบคุณสมบัติของเสียอันตรายหลังทำการผสม (Mixing process) และผลวิเคราะห์คุณสมบัติของเถ้าลอยและเถ้าหนัก (Fly ash & Bottom ash) ประจำเดือนกุมภาพันธ์ พ.ศ.2568 ตามสิ่งที่แนบมาด้วย หากต้องการข้อมูลเพิ่มเติม กรุณาติดต่อ [redacted] ที่หมายเลขโทรศัพท์เคลื่อนที่ [redacted]

จึงเรียนมาเพื่อโปรดพิจารณา



ขอแสดงความนับถือ



กรรมการผู้จัดการ



ที่ 2025-033/BPEC/MD/EN

24 กุมภาพันธ์ 2568

เรื่อง ขอนำส่งผลการตรวจสอบคุณสมบัติของเสียอันตรายหลังทำการผสมก่อนทำการป้อนเข้าสู่เตาเผาและผลวิเคราะห์เถ้าลอยและเถ้าหนัก

เรียน ผู้อำนวยการสำนักงานนิคมอุตสาหกรรมบางปู

สิ่งที่ส่งมาด้วย 1. รายงานผลการตรวจสอบคุณสมบัติของเสียอันตรายหลังทำการผสม (Mixing process) ก่อนทำการป้อนเข้าสู่เตาเผา ประจำเดือนมกราคม พ.ศ. 2568
2. เกณฑ์การพิจารณาในการป้อนของเสียเข้าสู่เตาเผา (Feeding Criteria)
3. ผลวิเคราะห์เถ้าลอยและเถ้าหนัก (Fly ash & Bottom ash)

ตามที่โครงการโรงงานปรับปรุงคุณภาพของเสียรวม (ส่วนขยาย ครั้งที่ 1) ของบริษัทบางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด ได้รับการพิจารณาเห็นชอบในรายงานการประเมินผลกระทบสิ่งแวดล้อม เมื่อวันที่ 9 กรกฎาคม พ.ศ. 2562 และได้รับอนุญาตในการประกอบกิจการดังกล่าวจาก การนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) เมื่อวันที่ 30 ตุลาคม พ.ศ. 2562 ตามความทราบแล้วนั้น ในรายงานการประเมินผลกระทบสิ่งแวดล้อมดังกล่าวระบุให้โครงการฯ ส่งผลการตรวจสอบคุณสมบัติของเสียหลังทำการผสมในแต่ละครั้ง (Batch) และผลวิเคราะห์เถ้าลอยและเถ้าหนักให้คณะกรรมการบริหารจัดการโครงการฯ ของการนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) รับทราบทุกเดือน นั้น

ทางบริษัทบางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด จึงขอนำส่งผลการตรวจสอบคุณสมบัติของเสียอันตรายหลังทำการผสม (Mixing process) และผลวิเคราะห์คุณสมบัติของเถ้าลอยและเถ้าหนัก (Fly ash & Bottom ash) ประจำเดือนมกราคม พ.ศ.2568 ตามสิ่งที่แนบมาด้วย หากต้องการข้อมูลเพิ่มเติม กรุณาติดต่อ [redacted] ที่หมายเลขโทรศัพท์เคลื่อนที่ [redacted]

จึงเรียนมาเพื่อโปรดพิจารณา

ขอแสดงความนับถือ



กรรมการผู้จัดการ



ที่ 2025-059/BPEC/MD/EN

20 พฤษภาคม 2568

เรื่อง ขอนำส่งผลการตรวจสอบคุณสมบัติของเสียอันตรายหลังทำการผสมก่อนทำการป้อนเข้าสู่เตาเผาและ
ผลวิเคราะห์เถ้าลอยและเถ้าหนัก

เรียน ผู้อำนวยการสำนักงานนิคมอุตสาหกรรมบางปู

สิ่งที่ส่งมาด้วย 1. รายงานผลการตรวจสอบคุณสมบัติของเสียอันตรายหลังทำการผสม (Mixing process) ก่อนทำ
การป้อนเข้าสู่เตาเผา ประจำเดือนมีนาคม พ.ศ. 2568
2. เกณฑ์การพิจารณาในการป้อนของเสียเข้าสู่เตาเผา (Feeding Criteria)
3. ผลวิเคราะห์เถ้าลอยและเถ้าหนัก (Fly ash & Bottom ash)

ตามที่โครงการโรงงานปรับปรุงคุณภาพของเสียรวม (ส่วนขยาย ครั้งที่ 1) ของบริษัทบางปู เอนไวรอนเม้นทอล คอม
เพล็กซ์ จำกัด ได้รับการพิจารณาเห็นชอบในรายงานการประเมินผลกระทบสิ่งแวดล้อม เมื่อวันที่ 9 กรกฎาคม พ.ศ. 2562
และได้รับอนุญาตในการประกอบกิจการดังกล่าวจาก การนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) เมื่อวันที่ 30 ตุลาคม
พ.ศ. 2562 ตามความทราบแล้วนั้น ในรายงานการประเมินผลกระทบสิ่งแวดล้อมดังกล่าวระบุให้โครงการฯ ส่งผลการ
ตรวจสอบคุณสมบัติของเสียหลังทำการผสมในแต่ละครั้ง (Batch) และผลวิเคราะห์เถ้าลอยและเถ้าหนักให้คณะ
กรรมการบริหารจัดการโครงการฯ ของการนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) รับทราบทุกเดือน นั้น


ทางบริษัทบางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด จึงขอนำส่งผลการตรวจสอบคุณสมบัติของเสีย
อันตรายหลังทำการผสม (Mixing process) และผลวิเคราะห์คุณสมบัติของเถ้าลอยและเถ้าหนัก (Fly ash & Bottom ash)
ประจำเดือนมีนาคม พ.ศ. 2568 ตามสิ่งที่แนบมาด้วย หากต้องการข้อมูลเพิ่มเติม กรุณาติดต่อ คุณ [REDACTED] ที่
หมายเลขโทรศัพท์เคลื่อนที่ 0 [REDACTED]

จึงเรียนมาเพื่อโปรดพิจารณา



ขอแสดงความนับถือ

กรรมการผู้จัดการ



ที่ 2025-065/BPEC/MD/EN

29 มิถุนายน 2568

เรื่อง ขอนำส่งผลการตรวจสอบคุณสมบัติของเสียอันตรายหลังทำการผสมก่อนทำการป้อนเข้าสู่เตาเผาและ
ผลวิเคราะห์เถ้าลอยและเถ้าหนัก


เรียน ผู้อำนวยการสำนักงานนิคมอุตสาหกรรมบางปู

สิ่งที่ส่งมาด้วย 1. รายงานผลการตรวจสอบคุณสมบัติของเสียอันตรายหลังทำการผสม (Mixing process) ก่อนทำ
การป้อนเข้าสู่เตาเผา ประจำเดือนเมษายน พ.ศ. 2568
2. เกณฑ์การพิจารณาในการป้อนของเสียเข้าสู่เตาเผา (Feeding Criteria)
3. ผลวิเคราะห์เถ้าลอยและเถ้าหนัก (Fly ash & Bottom ash)

ตามที่โครงการโรงงานปรับปรุงคุณภาพของเสียรวม (ส่วนขยาย ครั้งที่ 1) ของบริษัทบางปู เอนไวรอนเม้นทอล คอม
เพล็กซ์ จำกัด ได้รับการพิจารณาเห็นชอบในรายงานการประเมินผลกระทบสิ่งแวดล้อม เมื่อวันที่ 9 กรกฎาคม พ.ศ. 2562
และได้รับอนุญาตในการประกอบกิจการดังกล่าวจาก การนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) เมื่อวันที่ 30 ตุลาคม
พ.ศ. 2562 ตามความทราบแล้วนั้น ในรายงานการประเมินผลกระทบสิ่งแวดล้อมดังกล่าวระบุให้โครงการฯ ส่งผลการ
ตรวจสอบคุณสมบัติของเสียหลังทำการผสมในแต่ละครั้ง (Batch) และผลวิเคราะห์เถ้าลอยและเถ้าหนักให้คณะ
กรรมการบริหารจัดการโครงการฯ ของการนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) รับทราบทุกเดือน นั้น

ทางบริษัทบางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด จึงขอนำส่งผลการตรวจสอบคุณสมบัติของเสีย
อันตรายหลังทำการผสม (Mixing process) และผลวิเคราะห์คุณสมบัติของเถ้าลอยและเถ้าหนัก (Fly ash & Bottom ash)
ประจำเดือนเมษายน พ.ศ. 2568 ตามสิ่งที่แนบมาด้วย หากต้องการข้อมูลเพิ่มเติม กรุณาติดต่อ [REDACTED]
หมายเลขโทรศัพท์เคลื่อนที่ [REDACTED]

จึงเรียนมาเพื่อโปรดพิจารณา



ขอแสดงความนับถือ

กรรมการผู้จัดการ

ที่ 2025-067/BPEC/MD/EN

30 มิถุนายน 2568

เรื่อง ขอนำส่งผลการตรวจสอบคุณสมบัติของของเสียอันตรายหลังทำการผสมก่อนทำการป้อนเข้าสู่เตาเผาและ
ผลวิเคราะห์เถ้าลอยและเถ้าหนัก

เรียน ผู้อำนวยการสำนักงานนิคมอุตสาหกรรมบางปู

สิ่งที่ส่งมาด้วย 1. รายงานผลการตรวจสอบคุณสมบัติของของเสียอันตรายหลังทำการผสม (Mixing process) ก่อนทำ
การป้อนเข้าสู่เตาเผา ประจำเดือนพฤษภาคม พ.ศ. 2568
2. เกณฑ์การพิจารณาในการป้อนของเสียเข้าสู่เตาเผา (Feeding Criteria)
3. ผลวิเคราะห์เถ้าลอยและเถ้าหนัก (Fly ash & Bottom ash)

ตามที่โครงการโรงงานปรับปรุงคุณภาพของเสียรวม (ส่วนขยาย ครั้งที่ 1) ของบริษัทบางปู เอนไวรอนเมนทอล คอม
เพล็กซ์ จำกัด ได้รับการพิจารณาเห็นชอบในรายงานการประเมินผลกระทบสิ่งแวดล้อม เมื่อวันที่ 9 กรกฎาคม พ.ศ. 2562
และได้รับอนุญาตในการประกอบกิจการดังกล่าวจาก การนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) เมื่อวันที่ 30 ตุลาคม
พ.ศ. 2562 ตามความทราบแล้วนั้น ในรายงานการประเมินผลกระทบสิ่งแวดล้อมดังกล่าวระบุให้โครงการฯ ส่งผลการ
ตรวจสอบคุณสมบัติของของเสียหลังทำการผสมในแต่ละครั้ง (Batch) และผลวิเคราะห์เถ้าลอยและเถ้าหนักให้คณะ
กรรมการบริหารจัดการโครงการฯ ของการนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) รับทราบทุกเดือน นั้น

ทางบริษัทบางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด จึงขอนำส่งผลการตรวจสอบคุณสมบัติของของเสีย
อันตรายหลังทำการผสม (Mixing process) และผลวิเคราะห์คุณสมบัติของเถ้าลอยและเถ้าหนัก (Fly ash & Bottom ash)
ประจำเดือนพฤษภาคม พ.ศ. 2568 ตามสิ่งที่แนบมาด้วย หากต้องการข้อมูลเพิ่มเติม กรุณาติดต่อ [REDACTED] ที่
หมายเลขโทรศัพท์เคลื่อนที่ 0 [REDACTED]

จึงเรียนมาเพื่อโปรดพิจารณา

ขอแสดงความนับถือ

กรรมการผู้จัดการ



เอกสารแนบ 2-6

ตัวอย่างผลการวิเคราะห์ตัวอย่างที่ Mixing แล้ว

Test Report

Report No. : RE25-01-023_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-01-005
Sample Name : Haz. Waste Feeding (Batch 01/25)
Waste Profile No. : -
Sampling By : Korrawit Y. (9-371-9-0001)
Sampling Date : 06/01/2025
Sampling Time : 10:00 AM
Sampling Received Date : 07/01/2025
Sample Test Date : 15/01/2025
Report Date : 20/01/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 24.9 °C | US EPA. 9040C, 9045D ^[1,2] | pH unit | 7.5 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4,5] | mg/kg | 27.9 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4,5] | mg/kg | 33.4 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | <5.00 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 6.45 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4,5] | mg/kg | <2.00 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | 5.23 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4,5] | mg/kg | <2.00 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 78.3 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.


^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
Soil and Waste pH. SW-846 Method 9045D, 2004.


^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007
TTL = Total Threshold Limit Concentration. LOQ = Level of Quantitation.
ND = Not detected. MDL = Method Detection Limit.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(9-371-9-0001)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(9-371-9-0001)

Site office : 965 Moo 2 Soi 3, Bangpoo Industrial Estate, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn,
Samutprakarn, Thailand 10280 Tel: (66)-2-709-2546 Fax: (66)-2-709-2547
Bangkok office : 589/142 Central City Tower 1, 25 th Floor, Bangna-trad Road, Kwaeng Bangna, Khet Bangna, Bangkok, Thailand 10260
Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928 http://www.wms-thailand.com E-mail: info@wms-thailand.com

Test Report

Report No. : RE25-01-023_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-01-005
Sample Name : Haz. Waste Feeding (Batch 01/25)
Waste Profile No. : -
Sampling By : Korrawit Y. (9-371-9-0001)
Sampling Date : 06/01/2025
Sampling Time : 10:00 AM
Sampling Received Date : 07/01/2025
Sample Test Date : 15/01/2025
Report Date : 20/01/2025

| Test Parameter | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Heating value | ASTM D5468-02 Gross Calorific | Cal/g | 3,107 |
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/Kg | 814 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[1,2] | mg/kg | 3.85 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[1,2] | mg/kg | 1,465 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[3] | mg/kg | 0.107 | 0.002 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[2] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation),
SW-846 Method 7473, 2007.


ASTM = American Society for Testing and Materials.

LOQ = Level of Quantitation.


EPA = U.S. Environmental Protection Agency.

MDL = Method Detection Limit.

ND = Not detected.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(20 / 01 / 2025)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(20 / 01 / 2025)

Site office : 965 Moo 2 Soi 3, Bangpoo Industrial Estate, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn,
Samutprakarn, Thailand 10280 Tel: (66)-2-709-2546 Fax: (66)-2-709-2547
Bangkok office : 589/142 Central City Tower 1, 25 th Floor, Bangna-trad Road, Kwaeng Bangna, Khet Bangna, Bangkok, Thailand 10260
Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928 http://www.wms-thailand.com E-mail: info@wms-thailand.com

Test Report

Report No. : RE25-03-044_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-02-092
Sample Name : Haz. Waste Feeding (Batch 36/25)
Waste Profile No. : -
Sampling By : Korrawit Y. (๕-371-๙-0001)
Sampling Date : 28/02/2025
Sampling Time : 02:00 PM
Sampling Received Date : 28/02/2025
Sample Test Date : 10/03/2025
Report Date : 11/03/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|--|---------|--------|
| pH at 25.5 °C | US EPA. 9040C, 9045D ^[1, 2] | pH unit | 8.3 |
| Flash Point | Flash Point of Liquid by Setflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4, 5] | mg/kg | 26.3 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4, 5] | mg/kg | 48.1 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4, 5] | mg/kg | 25.3 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4, 5] | mg/kg | <2.00 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4, 5] | mg/kg | 11.3 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4, 5] | mg/kg | 3.51 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4, 5] | mg/kg | 16.3 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4, 5] | mg/kg | <2.00 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4, 5] | mg/kg | <2.00 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4, 5] | mg/kg | 107 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. **D3278-78 Standard Test Methods for Flash Point of Liquids by Setflash Close Tester, 2020**

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. **SW-846 Method 3050B, 1996**


^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. **SW-846 Method 6010C, 2007**

TTL = Total Threshold Limit Concentration.


LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(๕-371-๙-0001)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(๕-371-๙-0001)

Site office : 965 Moo 2 Soi 3, Bangpoo Industrial Estate, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn, Samutprakarn, Thailand 10280 Tel: (66)-2-709-2546 Fax: (66)-2-709-2547
Bangkok office : 589/142 Central City Tower 1, 25 th Floor, Bangna-trad Road, Kwaeng Bangna, Bangkok, Thailand 10260 Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928 http://www.wms-thailand.com E-mail: info@wms-thailand.com

Test Report

Report No. : RE25-03-044_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-02-092
Sample Name : Haz. Waste Feeding (Batch 36/25)
Waste Profile No. : -
Sampling By : Korrawit Y. (๕-371-๙-0001)
Sampling Date : 28/02/2025
Sampling Time : 02:00 PM
Sampling Received Date : 28/02/2025
Sample Test Date : 10/03/2025
Report Date : 11/03/2025

| Test Parameter* | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Heating value | ASTM D5468-02 Gross Calorific | Cal/g | 5,977 |
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/Kg | 3,345 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4, 5] | mg/kg | 8.76 | 1.55 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4, 5] | mg/kg | 2,066 | 0.25 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[3] | mg/kg | 0.013 | 0.11 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation),

SW-846 Method 7473, 2007.


ASTM = American Society for Testing and Materials.

LOQ = Level of Quantitation.


EPA = U.S. Environmental Protection Agency.

MDL = Method Detection Limit.

ND = Not detected.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(11 / 03 / 2025)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(11 / 03 / 2025)

Site office : 965 Moo 2 Soi 3, Bangpoo Industrial Estate, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn, Samutprakarn, Thailand 10280 Tel: (66)-2-709-2546 Fax: (66)-2-709-2547
Bangkok office : 589/142 Central City Tower 1, 25 th Floor, Bangna-trad Road, Kwaeng Bangna, Bangkok, Thailand 10260 Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928 http://www.wms-thailand.com E-mail: info@wms-thailand.com

Test Report

Report No. : RE25-03-075_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-03-032
Sample Name : Haz. Waste Feeding (Batch 42/25)
Waste Profile No. : -
Sampling By : Korrawit Y. (๕-371-๙-0001)

Sampling Date : 10/03/2025
Sampling Time : 10:00 AM
Sampling Received Date : 13/03/2025
Sample Test Date : 24/03/2025
Report Date : 25/03/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.4 °C | US EPA. 9040C, 9045D ^[1,2] | pH unit | 8.0 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4,5] | mg/kg | 15.9 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | <2.00 | 0.25 | 2.00 | <500 |
| Barium (Ba) | Digestion, ICP Method ^[4,5] | mg/kg | 17.5 | 0.11 | 2.00 | <10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.22 | 2.00 | <75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | <100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | 16.7 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.17 | 2.00 | <8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 15.9 | 1.29 | 2.00 | <2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | <2.00 | 1.30 | 2.00 | <1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.93 | 2.00 | <3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.37 | 2.00 | <2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4,5] | mg/kg | <2.00 | 1.04 | 2.00 | <100 |
| Silver (Ag) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.42 | 2.00 | <500 |
| Thallium (Tl) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.68 | 2.00 | <700 |
| Vanadium (V) | Digestion, ICP Method ^[4,5] | mg/kg | <2.00 | 0.68 | 2.00 | <2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 81.3 | 3.36 | 5.00 | <5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3728-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996


^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTL = Total Threshold Limit Concentration.


LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(๕-371-๙-0001)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(๕-371-๙-0001)

Test Report

Report No. : RE25-03-075_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-03-032
Sample Name : Haz. Waste Feeding (Batch 42/25)
Waste Profile No. : -
Sampling By : Korrawit Y. (๕-371-๙-0001)

Sampling Date : 10/03/2025
Sampling Time : 10:00 AM
Sampling Received Date : 13/03/2025
Sample Test Date : 24/03/2025
Report Date : 25/03/2025

| Test Parameter* | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Heating value | ASTM D5468-02 Gross Calorific | Cal/g | 4,980 |
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/Kg | 1,102 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4,5] | mg/kg | 15.7 | 1.55 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4,5] | mg/kg | 1,578 | 0.25 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[3] | mg/kg | 0.134 | 0.11 | 0.005 | <20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.


^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation),

SW-846 Method 7473, 2007.


ASTM = American Society for Testing and Materials. LOQ = Level of Quantitation.

EPA = U.S. Environmental Protection Agency. MDL = Method Detection Limit.

ND = Not detected.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(25 / 03 / 2025)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(25 / 03 / 2025)

Test Report

Report No. : RE25-05-005_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-04-028
Sample Name : Haz. Waste Feeding (Batch 70/25)
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)

Sampling Date : 23/04/2025
Sampling Time : 10:00 AM
Sampling Received Date : 24/04/2025
Sample Test Date : 09/05/2025
Report Date : 13/05/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|--|---------|--------|
| pH at 27.9 °C | US EPA. 9040C, 9045D ^[1, 2] | pH unit | 5.4 |
| Flash Point | Flash Point of Liquid by Setflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4, 5] | mg/kg | 9.40 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4, 5] | mg/kg | <2.00 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4, 5] | mg/kg | 11.1 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4, 5] | mg/kg | <5.00 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4, 5] | mg/kg | <2.00 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4, 5] | mg/kg | 7.47 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4, 5] | mg/kg | <2.00 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4, 5] | mg/kg | 405 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4, 5] | mg/kg | <2.00 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4, 5] | mg/kg | <2.00 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4, 5] | mg/kg | 52.7 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4, 5] | mg/kg | 8.75 | 3.36 | 5.00 | <5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. **D3278-78 Standard Test Methods for Flash Point of Liquids by Setflash Close Tester, 2020**

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. **SW-846 Method 3050B, 1996**

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. **SW-846 Method 6010C, 2007**

TTL = Total Threshold Limit Concentration.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(๙-371-๙-0002)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)

Site office : 965 Moo 2 Soi 3, Bangpoo Industrial Estate, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn,
Samutprakarn, Thailand 10280 Tel: (66)-2-709-2546 Fax: (66)-2-709-2547
Bangkok office : 589/142 Central City Tower 1, 25 th Floor, Bangna-trad Road, Kwaeng Bangna, Khet Bangna, Bangkok, Thailand 10260
Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928 http://www.wms-thailand.com E-mail: info@wms-thailand.com

Test Report

Report No. : RE25-05-005_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-04-028
Sample Name : Haz. Waste Feeding (Batch 70/25)
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)

Sampling Date : 23/04/2025
Sampling Time : 10:00 AM
Sampling Received Date : 24/04/2025
Sample Test Date : 09/05/2025
Report Date : 13/05/2025

| Test Parameter* | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Heating value | ASTM D5468-02 Gross Calorific | Cal/g | 4,581 |
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/Kg | 6,244 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4, 5] | mg/kg | 2.37 | 1.55 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4, 5] | mg/kg | 680 | 0.25 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[3] | mg/kg | 0.022 | 0.11 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation),
SW-846 Method 7473, 2007.

ASTM = American Society for Testing and Materials.

LOQ = Level of Quantitation.

EPA = U.S. Environmental Protection Agency.

MDL = Method Detection Limit.

ND = Not detected.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(13 / 05 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(13 / 05 / 2025)

Site office : 965 Moo 2 Soi 3, Bangpoo Industrial Estate, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn,
Samutprakarn, Thailand 10280 Tel: (66)-2-709-2546 Fax: (66)-2-709-2547
Bangkok office : 589/142 Central City Tower 1, 25 th Floor, Bangna-trad Road, Kwaeng Bangna, Khet Bangna, Bangkok, Thailand 10260
Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928 http://www.wms-thailand.com E-mail: info@wms-thailand.com

Test Report

Report No. : RE25-06-029_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-05-053
Sample Name : Haz. Waste Feeding (Batch 94/25)
Waste Profile No. : -
Sampling By : Watcharee S. (+371-9-0002)

Sampling Date : 29/05/2025
Sampling Time : 10:00 AM
Sampling Received Date : 30/05/2025
Sample Test Date : 09/06/2025
Report Date : 10/06/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.7 °C | US EPA. 9040C, 9045D ^[1,2] | pH unit | 5.1 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTLC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4,5] | mg/kg | 22.3 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4,5] | mg/kg | <2.00 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | 11.2 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4,5] | mg/kg | 2.30 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 6.27 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4,5] | mg/kg | 302 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | 12.5 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4,5] | mg/kg | 9.80 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4,5] | mg/kg | 20.1 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 14.0 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTLC = Total Threshold Limit Concentration.

ND = Not detected.

LOQ = Level of Quantitation.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(+371-9-0002)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(+371-9-0001)

Test Report

Report No. : RE25-06-029_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-05-053
Sample Name : Haz. Waste Feeding (Batch 94/25)
Waste Profile No. : -
Sampling By : Watcharee S. (+371-9-0002)

Sampling Date : 29/05/2025
Sampling Time : 10:00 AM
Sampling Received Date : 30/05/2025
Sample Test Date : 09/06/2025
Report Date : 10/06/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|-------|--------|
| Heating value | ASTM D5468-02 Gross Calorific | Cal/g | 3,725 |
| Chloride (Cl) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/kg | 7,895 |

TTLC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4,5] | mg/kg | 9.84 | 1.55 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4,5] | mg/kg | 2,124 | 0.25 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[3] | mg/kg | 0.102 | 0.11 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation).

SW-846 Method 7473, 2007.

ASTM = American Society for Testing and Materials. LOQ = Level of Quantitation.

EPA = U.S. Environmental Protection Agency. MDL = Method Detection Limit.

ND = Not detected.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(10 / 06 / 2025)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(10 / 06 / 2025)

Test Report

Report No. : RE25-06-031_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description
Sample No. : LA25-06-002
Sample Name : Haz. Waste Feeding (Batch 95/25)
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)
Sampling Date : 31/05/2025
Sampling Time : 10:00 AM
Sampling Received Date : 31/05/2025
Sample Test Date : 09/06/2025
Report Date : 10/06/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 27.9 °C | US EPA. 9040C, 9045D ^[1,2] | pH unit | 4.1 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTLC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4,5] | mg/kg | 13.5 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4,5] | mg/kg | 22.3 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | 54.2 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4,5] | mg/kg | 4.51 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 9.08 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4,5] | mg/kg | 473 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | 17.1 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4,5] | mg/kg | 10.8 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4,5] | mg/kg | 29.8 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 29.6 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTLC = Total Threshold Limit Concentration. LOQ = Level of Quantitation.
ND = Not detected. MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(๙-371-๙-0002)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)

Test Report

Report No. : RE25-06-031_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description
Sample No. : LA25-06-002
Sample Name : Haz. Waste Feeding (Batch 95/25)
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)
Sampling Date : 31/05/2025
Sampling Time : 10:00 AM
Sampling Received Date : 31/05/2025
Sample Test Date : 09/06/2025
Report Date : 10/06/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|-------|--------|
| Heating value | ASTM D5468-02 Gross Calorific | Cal/g | 3,980 |
| Chloride (Cl) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/Kg | 7,165 |

TTLC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4,5] | mg/kg | 5.85 | 1.55 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4,5] | mg/kg | 156 | 0.25 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[3] | mg/kg | 0.029 | 0.11 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation), SW-846 Method 7473, 2007.

ASTM = American Society for Testing and Materials. LOQ = Level of Quantitation.
EPA = U.S. Environmental Protection Agency. MDL = Method Detection Limit.
ND = Not detected.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(10 / 06 / 2025)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(10 / 06 / 2025)

เอกสารแนบ 2-7

ตัวอย่างรายงานบันทึกการตรวจสอบข้อมูลของเสียเบื้องต้น

การปฏิบัติงานทางของเสียอุตสาหกรรม
Random Check of Industrial Waste Receiving

| Month | Jan-25 | Company Name | Waste name | Waste Type | Manifest | Local Disposal | Inspector Signage | Remark |
|-----------|---|---|------------|------------------|----------|----------------|-------------------|--------|
| 6-Jan-25 | CRPAM Company Limited. 1040000285602 126797 | Air filter | 608611 | 31101680077310N | 074 | JF | | |
| 6-Jan-25 | NP Green Corporation Co., Ltd. 124247 | OUT OF SPEC PRODUCTS / ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 607044 | 31101680250510N | 074 | JF | | |
| 10-Jan-25 | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact / พลาสติกอัดก้อน | 607740 | 31101680250510N | 074 | JF | | |
| 10-Jan-25 | NIPRO (THAILAND) CORPORATION LTD. | Write Off Product (medical equipment) / สินค้าเสื่อมสภาพ (อุปกรณ์การแพทย์) | 606304 | 31101680250510N | 074 | JF | | |
| 10-Jan-25 | Uni-Charm (Thailand) Co., Ltd. 102110 | Industrial Non-Hazardous Waste(ถัง) / เศษของที่ไม่เป็นอันตราย (ถัง) | 601491 | 31101680249400N | 074 | JF | | |
| 10-Jan-25 | Uni-Charm (Thailand) Co., Ltd. 102110 | ผ้าอนามัย | 602730 | 311016802494140N | 074 | JF | | |
| 10-Jan-25 | DCH Aungmye (Thailand) Limited 124252 | Foam and cold gel pads. / โฟมและแผ่นเจลเย็น | 607175 | 311016802494140N | 074 | JF | | |
| 11-Jan-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | - | 074 | JF | | |
| 13-Jan-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 38307 | 074 | PD | | |
| 13-Jan-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 38309 | 074 | PD | | |
| 13-Jan-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 38308 | 074 | PD | | |
| 13-Jan-25 | TENSHO (THAILAND) CO.,LTD. 120953 | Write off products (Ceramic plates and bowls) / สินค้าเสื่อมสภาพ (จาน) | 608558 | 38310 | 074 | PD | | |
| 14-Jan-25 | Decathlon Thailand CO.,LTD. Bangkok 126834 | General waste | 608137 | 38315 | 074 | PD | | |
| 14-Jan-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 38318 | 074 | PD | | |
| 14-Jan-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 38319 | 074 | PD | | |
| 15-Jan-25 | Unilever Thai Holding Limited 100835 | Rejected product (Shampoo Plan) | 605121 | 31101680467700N | 074 | PD | | |
| 15-Jan-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 311016804627990N | 074 | PD | | |
| 16-Jan-25 | Beiersdorf (Thailand) Co.,Ltd. 100178 | Expired Packaging/บรรจุภัณฑ์ที่หมดอายุ | 605569 | 31101680487900N | 074 | PD | | |
| 16-Jan-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 31101680488150N | 074 | PD | | |
| 16-Jan-25 | Beiersdorf (Thailand) Co.,Ltd. 100178 | Expired Packaging/บรรจุภัณฑ์ที่หมดอายุ | 605569 | 31101680488150N | 074 | PD | | |
| 17-Jan-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31101680542910N | 074 | PD | | |
| 17-Jan-25 | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Personal Health care) / ผลิตภัณฑ์ที่นำไปใช้ทางการแพทย์ (เวชภัณฑ์) | 601212 | 31101680711070N | 074 | PD | | |
| 17-Jan-25 | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Pharmaceutical) / สินค้าทั่วไปไม่ทางการแพทย์ (ยา) | 605429 | 31101680711400N | 074 | PD | | |
| 17-Jan-25 | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact / พลาสติกอัดก้อน | 607740 | 3110168054340N | 074 | PD | | |
| 17-Jan-25 | Lazada Limited (Head office) 121808 | Expired products/สินค้าหมดอายุ | 606434 | 47915 | 074 | PD | | |
| 18-Jan-25 | World Pet International Co., Ltd. 121553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31101680567900N | 074 | TP | | |
| 18-Jan-25 | World Pet International Co., Ltd. 121553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31101680592430N | 074 | TP | | |
| 18-Jan-25 | World Pet International Co., Ltd. 121553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31101680592560N | 074 | TP | | |
| 18-Jan-25 | World Pet International Co., Ltd. 121553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31101680591040N | 074 | TP | | |
| 18-Jan-25 | World Pet International Co., Ltd. 121553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31101680592230N | 074 | TP | | |
| 18-Jan-25 | World Pet International Co., Ltd. 121553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31101680577600N | 074 | TP | | |
| 20-Jan-25 | Johnson & Johnson (Thailand) Co., Ltd. | Off spec goods (Lotion) / สินค้าทั่วไปไม่ทางการแพทย์ (โลชั่น) | 605064 | 31101680658110N | 074 | PD | | |
| 20-Jan-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31101680651110N | 074 | PD | | |
| 21-Jan-25 | Design Alternative Co., Ltd. 123730 | Industrial Non Hazardous waste / ของเสียจากทางที่ไม่เป็นอันตราย | 606363 | - | 074 | TP | | |
| 21-Jan-25 | Design Alternative Co., Ltd. 123730 | Industrial Non Hazardous waste / ของเสียจากทางที่ไม่เป็นอันตราย | 606363 | - | 074 | TP | | |
| 22-Jan-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31101680796660N | 074 | PD | | |
| 22-Jan-25 | NECOSMED CO.,LTD. 124691 | Non-hazardous industrial waste | 606936 | 31101680790460N | 074 | PD | | |
| 22-Jan-25 | NECOSMED CO.,LTD. 124691 | Rejected product | 606938 | - | 074 | TP | | |
| 22-Jan-25 | NECOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | - | 074 | TP | | |
| 23-Jan-25 | AB Food & Beverages (Thailand) Ltd. 101931 | Write off product / สินค้าหมดอายุ | 600910 | 31101680827880N | 074 | PD | | |
| 24-Jan-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31101680885380N | 074 | PD | | |
| 24-Jan-25 | DKSH (THAILAND) LIMITED 103982 | Expired Product (Non-hazardous medicine) | 603862 | 38483 | 074 | TP | | |
| 24-Jan-25 | SOUTHEAST ASIAN PACKAGING & CANNING LIMITED. 121490 | Packaging | 606407 | 31101680887920N | 074 | TP | | |
| 24-Jan-25 | SOUTHEAST ASIAN PACKAGING & CANNING LIMITED. 121490 | Packaging | 606407 | 31101680921170N | 074 | TP | | |
| 25-Jan-25 | World Pet International Co., Ltd. 121553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31101680921170N | 074 | PD | | |
| 25-Jan-25 | NP Green Corporation Co., Ltd. 124247 | OUT OF SPEC PRODUCTS / ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 607044 | 38758 | 074 | PD | | |
| 25-Jan-25 | NP Green Corporation Co., Ltd. 124247 | OUT OF SPEC PRODUCTS / ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 607044 | 38759 | 074 | PD | | |
| 25-Jan-25 | NP Green Corporation Co., Ltd. 124247 | OUT OF SPEC PRODUCTS / ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 607044 | 38760 | 074 | PD | | |
| 25-Jan-25 | NP Green Corporation Co., Ltd. 124247 | OUT OF SPEC PRODUCTS / ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 607044 | 38761 | 074 | PD | | |
| 27-Jan-25 | Milint Laboratories Co., Ltd. (R3-4731-1/3183) | Plastic Packaging / บรรจุภัณฑ์ที่เปื้อนพลาสติก | 603616 | 31101681001790N | 074 | PD | | |
| 27-Jan-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31101681023760N | 074 | TP | | |
| 28-Jan-25 | Nestle (Thai) Ltd. (Bangpoo) 100384 | Materials unsuitable for consumption or processing | 600073 | 31101681082520N | 074 | TP | | |
| 28-Jan-25 | NIPRO (THAILAND) CORPORATION LTD. | Off spec packaging / บรรจุภัณฑ์ที่เสื่อมสภาพ | 606307 | 31101681051340N | 074 | TP | | |
| 28-Jan-25 | NIPRO (THAILAND) CORPORATION LTD. | Off spec packaging / บรรจุภัณฑ์ที่เสื่อมสภาพ | 606307 | 31101681058470N | 074 | TP | | |
| 28-Jan-25 | NECOSMED CO.,LTD. 124691 | Non-hazardous industrial waste | 606936 | 31101681047230N | 074 | PD | | |
| 28-Jan-25 | NECOSMED CO.,LTD. 124691 | Rejected product | 606938 | 31101681047230N | 074 | TP | | |
| 28-Jan-25 | NECOSMED CO.,LTD. 124691 | Off Spec | 607084 | 31101681047230N | 074 | TP | | |
| 28-Jan-25 | NECOSMED CO.,LTD. 124691 | Air filter | 607088 | 31101681047230N | 074 | TP | | |
| 28-Jan-25 | NECOSMED CO.,LTD. 124691 | Sludge from the treatment system | 607085 | 31101681047230N | 074 | TP | | |
| 29-Jan-25 | Royal Canin (Thailand) Co., Ltd. 127801 | Write Off Product | 608545 | 38814 | 074 | TP | | |
| 29-Jan-25 | P.M.A.P. CO.,LTD. (3-106-24/6026) 122278 | Out of spec products (raw materials)/วัตถุดิบหมดอายุ | 607143 | 31101681096260N | 074 | TP | | |
| 30-Jan-25 | Unilever Thai Holding Limited 100835 | Reject product Personal care contaminated with Plastic | 608553 | 31101681184890N | 074 | TP | | |
| 31-Jan-25 | EVIA Air and Ocean (Thailand) Co., Ltd. | Off spec product / สินค้าทั่วไปไม่ทางการแพทย์ | 607123 | 38868 | 074 | TP | | |
| 31-Jan-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31101681245130N | 074 | TP | | |

การปฏิบัติงานทางของเสียอุตสาหกรรม
Random Check of Industrial Waste Receiving

| Month | Feb-25 | Company Name | Waste name | Waste Type | Manifest | Local Disposal | Inspector Signage | Remark |
|-----------|---|--|------------|-----------------|----------|----------------|-------------------|--------|
| 4-Feb-25 | NECOSMED CO.,LTD. 124691 | Non-hazardous industrial waste | 606936 | 31102680133310N | 074 | PD | | |
| 4-Feb-25 | NECOSMED CO.,LTD. 124691 | Rejected product | 606938 | - | 074 | PD | | |
| 4-Feb-25 | NECOSMED CO.,LTD. 124691 | Off Spec | 607084 | - | 074 | PD | | |
| 4-Feb-25 | NECOSMED CO.,LTD. 124691 | Air Filter | 607088 | - | 074 | PD | | |
| 4-Feb-25 | NECOSMED CO.,LTD. 124691 | Sludge from the treatment system | 607085 | 31102680133310N | 074 | PD | | |
| 5-Feb-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31102680193480N | 074 | JF | | |
| 6-Feb-25 | | Off spec Product | 007278 | 311026801160N | 074 | JF | | |
| 7-Feb-25 | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact / พลาสติกอัดก้อน | 607740 | 31102680297250N | 074 | JF | | |
| 7-Feb-25 | KGC Corporation Public Company Limited 129277 | Write off product (food and bakery) | 600009 | 31102680313590N | 074 | JF | | |
| 7-Feb-25 | Uni-Charm (Thailand) Co., Ltd. 127061 | off spec product (Baby diapers) / ผ้าอ้อมที่ไม่ได้มาตรฐาน(ผ้าอ้อมเด็ก) | 608222 | 38505 | 074 | JF | | |
| 7-Feb-25 | Johnson & Johnson (Thailand) Co.,Ltd. | Off spec goods (Lotion) / สินค้าทั่วไปไม่ทางการแพทย์ (โลชั่น) | 605064 | 31102680309860N | 074 | JF | | |
| 10-Feb-25 | AGC FLAT GLASS (THAILAND) PCL. 122733 | Commercial Waste/ขยะมูลฝอยทั่วไป | 605975 | 38575 | 074 | JF | | |
| 10-Feb-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31102680386890N | 074 | JF | | |
| 13-Feb-25 | Aviaulud Ltd. 124430 | Paper and Plastic scrap | 607495 | 31102680556800N | 074 | PD | | |
| 13-Feb-25 | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Pharmaceutical) / สินค้าทั่วไปไม่ทางการแพทย์(ยา/อุปกรณ์) | 605429 | 31102680579550N | 074 | PD | | |
| 13-Feb-25 | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Personal Health care) / ผลิตภัณฑ์ที่นำไปใช้ทางการแพทย์ (เวชภัณฑ์) | 601212 | 31102680572500N | 074 | PD | | |
| 13-Feb-25 | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Non recycle waste (Paper Scrap) / เศษที่ใช้ในการทำกระดาษที่ไม่รีไซเคิล (เศษกระดาษ) | 608904 | 31102680580010N | 074 | PD | | |
| 13-Feb-25 | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Non recycle waste (Plastic film) / ของที่ไม่สามารถที่จะรีไซเคิลได้ (พลาสติก) | 608903 | 31102680580310N | 074 | PD | | |
| 13-Feb-25 | UNILEVER THAI TRADING LTD. 123282 | Commercial waste | 606219 | 38618 | 074 | JF | | |
| 13-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102680588610N | 074 | PD | | |
| 13-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102680589070N | 074 | PD | | |
| 14-Feb-25 | Galbee Tanawatt Co.,Ltd. 103279 | Packaging | 605109 | 31102680638900N | 074 | PD | | |
| 14-Feb-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31102680631590N | 074 | PD | | |
| 14-Feb-25 | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Personal Health care) / ผลิตภัณฑ์ที่นำไปใช้ทางการแพทย์ (เวชภัณฑ์) | 601212 | 31102680655240N | 074 | PD | | |
| 14-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681021130N | 074 | PD | | |
| 14-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102680623480N | 074 | PD | | |
| 14-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681021510N | 074 | PD | | |
| 14-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681055330N | 074 | PD | | |
| 15-Feb-25 | TS Paper Pallet co.,Ltd 122232 | Paper Scrap | 605734 | 31102680914110N | 074 | JF | | |
| 15-Feb-25 | TS Paper Pallet co.,Ltd 122232 | Paper contaminated with latex | 606525 | 31102680914110N | 074 | JF | | |
| 15-Feb-25 | Unilever Thai Holding Limited 100835 | General Mixed Waste HPC | 607401 | 31102681070300N | 074 | JF | | |
| 15-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681022370N | 074 | JF | | |
| 15-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681024440N | 074 | JF | | |
| 15-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681021910N | 074 | JF | | |
| 15-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681024910N | 074 | JF | | |
| 16-Feb-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 43965 | 074 | PD | | |
| 16-Feb-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 38665 | 074 | JF | | |
| 16-Feb-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 38666 | 074 | JF | | |
| 17-Feb-25 | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Personal Health care) / ผลิตภัณฑ์ที่นำไปใช้ทางการแพทย์ (เวชภัณฑ์) | 601212 | 31102680651560N | 074 | JF | | |
| 17-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681025370N | 074 | JF | | |
| 17-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681029150N | 074 | JF | | |
| 17-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681027080N | 074 | JF | | |
| 17-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681026630N | 074 | JF | | |
| 18-Feb-25 | Abonut Laboratories Limited 103975 | Protein Supplement | 606565 | 38723 | 074 | PD | | |
| 18-Feb-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 38721 | 074 | PD | | |
| 18-Feb-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 43954 | 074 | PD | | |
| 18-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681028270N | 074 | PD | | |
| 18-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681028770N | 074 | PD | | |
| 18-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681027110N | 074 | PD | | |
| 18-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681029680N | 074 | PD | | |
| 18-Feb-25 | AB Food & Beverages (Thailand) Ltd. 101931 | Write off product / สินค้าหมดอายุ | 600910 | 31102680749600N | 074 | PD | | |
| 18-Feb-25 | DCH Aungmye (Thailand) Limited 124252 | Foam and cold gel pads / โฟมและแผ่นเจลเย็น | 607175 | 38720 | 074 | PD | | |
| 18-Feb-25 | DAEWOO PHARMA LTD. 100266 | Damaged Product & Expired Product | 605256 | 40253 | 074 | PD | | |
| 19-Feb-25 | DAEWOO PHARMA LTD. 100266 | Damaged Product & Expired Product | 605256 | 40254 | 074 | PD | | |
| 19-Feb-25 | UNILAW THAILAND CO., LTD. 100405 | Off spec consumer product / สินค้าผู้บริโภคที่ไม่ได้มาตรฐานทางการแพทย์ | 604163 | 40280 | 074 | PD | | |
| 19-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681028690N | 074 | PD | | |
| 19-Feb-25 | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าเสื่อมสภาพ | 608395 | 31102681026020N | 074 | PD | | |
| 21-Feb-25 | Danone Specialized Nutrition (Thailand) Co., Ltd. 120851 | Off spec product (Milk UHT) | 605986 | 001834 | 074 | PD | | |
| 21-Feb-25 | Danone Specialized Nutrition (Thailand) Co., Ltd. 120851 | Silica gel | 607544 | 001834 | 074 | TP | | |
| 21-Feb-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31102680912240N | 074 | TP | | |
| 21-Feb-25 | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact / พลาสติกอัดก้อน | 607740 | 3110268067640N | 074 | TP | | |
| 21-Feb-25 | Petar Lab (2517) Co., Ltd. 126993 | Gelatin Scrap | 608227 | 31102680662050N | 074 | PD | | |
| 21-Feb-25 | DCH Aungmye (Thailand) Limited 124252 | Foam and cold gel pads / โฟมและแผ่นเจลเย็น | 607175 | 40335 | 074 | PD | | |
| 21-Feb-25 | Auto alliance | Resin | 000578 | 31102680676010N | 074 | PD | | |
| 22-Feb-25 | L'oreal (Thailand) Ltd. 101283 | Expired Product (Cosmetics) / ผลิตภัณฑ์ที่เสื่อมสภาพ (เครื่องสำอาง) | 607186 | 40374 | 074 | PD | | |
| 22-Feb-25 | L'oreal (Thailand) Ltd. 101283 | Expired Product (Cosmetics) / ผลิตภัณฑ์ที่เสื่อมสภาพ (เครื่องสำอาง) | 607186 | 43665 | 074 | PD | | |
| 22-Feb-25 | L'oreal (Thailand) Ltd. 101283 | Expired Product (Cosmetics) / ผลิตภัณฑ์ที่เสื่อมสภาพ (เครื่องสำอาง) | 607186 | 40373 | 074 | PD | | |
| 22-Feb-25 | L'oreal (Thailand) Ltd. 101283 | Expired Product (Cosmetics) / ผลิตภัณฑ์ที่เสื่อมสภาพ (เครื่องสำอาง) | 607186 | 43666 | 074 | PD | | |
| 22-Feb-25 | Neutrogena/Amara city Rayong | Off Spec Products | 000975 | 31102680907060N | 074 | PD | | |
| 24-Feb-25 | Central Department Store Ltd. (Warehouse) 120998 | Out of spec product/ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 605135 | 40394 | 074 | TP | | |
| 24-Feb-25 | Central Department Store Ltd. (Warehouse) 120998 | Out of spec product/ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 605135 | 40396 | 074 | TP | | |
| 24-Feb-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 43850 | 074 | PD | | |
| 24-Feb-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 40397 | 074 | PD | | |
| 25-Feb-25 | DKSH (THAILAND) LIMITED 103982 | Expired Product (Non-hazardous medicine) | 603862 | 43740 | 074 | PD | | |
| 25-Feb-25 | DKSH (THAILAND) LIMITED 103982 | Expired Product (Non-hazardous medicine) | 603862 | 43741 | 074 | PD | | |
| 26-Feb-25 | NECOSMED CO.,LTD. 124691 | Non-hazardous industrial waste | 606936 | 31102681129860N | 074 | PD | | |
| 26-Feb-25 | NECOSMED CO.,LTD. 124691 | Rejected product | 606938 | 31102681129860N | 074 | PD | | |
| 26-Feb-25 | NECOSMED CO.,LTD. 124691 | Off Spec | 607084 | 31102681129860N | 074 | PD | | |
| 26-Feb-25 | NECOSMED CO.,LTD. 124691 | Air Filter | 607088 | 31102681129860N | 074 | PD | | |
| 26-Feb-25 | NECOSMED CO.,LTD. 124691 | Sludge from the treatment system | 607085 | 31102681129860N | 074 | PD | | |
| 26-Feb-25 | Techno Asia Co., Ltd. 125531 | Expired raw materials / วัสดุสิ้นเปลือง | 608297 | 40434 | 074 | TP | | |
| 26-Feb-25 | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31102681136200N | 074 | TP | | |
| 26-Feb-25 | Procter&Gamble Trading (Thailand) Ltd. 122343 | Expired product | 606179 | 31102681137160N | 074 | TP | | |
| 26-Feb-25 | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 40436 | 074 | PD | | |
| 26-Feb-25 | NECOSMED CO., LTD. 124691 | Heat treated | 607186 | 31102681134970N | 074 | PD | | |
| 26-Feb-25 | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Personal Health care) / ผลิตภัณฑ์ที่นำไปใช้ทางการแพทย์ (เวชภัณฑ์) | 601212 | 40484 | 074 | TP | | |
| 26-Feb-25 | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Pharmaceutical) / สินค้าทั่วไปไม่ทางการแพทย์(ยา/อุปกรณ์) | 605429 | 31102681177280N | 074 | TP | | |
| 26-Feb-25 | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Waste water from treatment | 606907 | 31102681173730N | 074 | TP | | |
| 27-Feb-25 | AGC FLAT GLASS (THAILAND) PCL. 122733 | Commercial Waste/ขยะมูลฝอยทั่วไป | 605975 | 40488 | 074 | TP | | |
| 27-Feb-25 | KGC Corporation Public Company Limited 129277 | Commercial Waste/ขยะมูลฝอยทั่วไป | 600009 | 31102681220790N | 074 | TP | | |
| 27-Feb-25 | Johnson & Johnson PTE Ltd. 1002063 | Return goods from warehouse | 602638 | 31102681253030N | 074 | TP | | |
| 27-Feb-25 | Johnson & Johnson PTE Ltd. 1002063 | Return goods from warehouse | 602638 | 31102681221060N | 074 | TP | | |
| 27-Feb-25 | Procter & Gamble Manufacturing 100287 | Expired Raw Material (Incrinator) | 605447 | 31102681255601N | 074 | TP | | |
| 27-Feb-25 | SEA L&S COMMER PRODUCT CO.LTD. 123104 | Write off Product/สินค้าหมดอายุ | 607175 | 40488 | 074 | PD | | |
| 27-Feb-25 | The Medipharma Co., Ltd. 124239 | Packaging Scrap | 607175 | 3110368034900N | 074 | TP | | |
| 27-Feb-25 | The Medipharma Co., Ltd. 124239 | Drug powder | 606598 | 31102681226350N | 074 | TP | | |

การระบุผลการรับกากของเสียอุตสาหกรรม
Random Check of Industrial Waste Receiving

| Month : | Feb-25 | | | | | | | | |
|-----------|--------|---|---|------------|------------------------|----------------|-------------------|--------|--|
| Date | Time | Company Name | Waste name | Waste Type | Manifest | Local Disposal | Inspector Signage | Remark | |
| 27-Feb-25 | | Procter & Gamble Manufacturing 100287 | Off Spec Shampoo | | 603812 31102681227000N | 074 | TP | | |
| 27-Feb-25 | | ENVIU GADUP CO.,LTD. | Write off product (Herbal medicine) | | 608549 40466 | 074 | TP | | |
| 28-Feb-25 | | Beiersdorf (Thailand) Co.,Ltd. 100178 | Expired Product | | 605568 0022339 | 074 | TP | | |
| 28-Feb-25 | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | | 608515 - | 074 | TP | | |
| 28-Feb-25 | | Beiersdorf (Thailand) Co.,Ltd. 100178 | Expired Product | | 605568 - | 074 | TP | | |
| 28-Feb-25 | | S.E.A. CONSUMER PRODUCT CO.,LTD. 123104 | Write-Off Product/สินค้าหมดอายุ | | 606112 400006 | 074 | TP | | |
| 28-Feb-25 | | SIAM INDO RESOURCES CO., LTD. 121104 | Write off products (Raw materials for food) / สินค้าสิ้นอายุ (วัตถุดิบ) | | 608963 54085 | 074 | TP | | |
| 28-Feb-25 | | SIAM INDO RESOURCES CO., LTD. 121104 | Write off products (Raw materials for food) / สินค้าสิ้นอายุ (วัตถุดิบ) | | 608963 54080 | 074 | TP | | |

การระบุผลการรับกากของเสียอุตสาหกรรม
Random Check of Industrial Waste Receiving

| Month : | Mar-25 | | | | | | | | |
|-----------|--------|--|---|------------|-------------------------|----------------|-------------------|--------|--|
| Date | Time | Company Name | Waste name | Waste Type | Manifest | Local Disposal | Inspector Signage | Remark | |
| 3-Mar-25 | | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact. / พลาสติกอัดก้อน | | 607740 3110368009200N | 074 | JP | | |
| 3-Mar-25 | | NIPRO (THAILAND) CORPORATION LTD. | Write Off Product (medical equipment) / สินค้าสิ้นอายุ (อุปกรณ์การแพทย์) | | 606304 3110368009200N | 074 | JP | | |
| 3-Mar-25 | | ZUELLIG PHARMA LTD. 103084 | Damaged Product & Expired Product | | 605256 40044 | 074 | JP | | |
| 3-Mar-25 | | Royal Canin (Thailand) Co., Ltd. 127801 | Write Off Product | | 608545 40054 | 074 | JP | | |
| 3-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | | 608515 31103680052820N | 074 | JP | | |
| 3-Mar-25 | | P.M.A.P.R. Co.,Ltd. | Off spec product | | 607143 311036800600360N | 074 | JP | | |
| 3-Mar-25 | | HP Green Corporation Co., Ltd. 123437 | OUT OF SPEC PRODUCTS / ผลิตภัณฑ์ที่อยู่นอกสเปก | | 607044 40085 | 074 | JP | | |
| 6-Mar-25 | | SANKO MACHINERY (THAILAND) CO.,LTD.102149 | Foil packaging | | 607711 40141 | 074 | JP | | |
| 6-Mar-25 | | SANKO MACHINERY (THAILAND) CO.,LTD.102149 | Expired Product | | 607712 31103680245490N | 074 | JP | | |
| 6-Mar-25 | | ZUELLIG PHARMA LTD. 103084 | Damaged Product & Expired Product | | 605256 40137 | 074 | JP | | |
| 7-Mar-25 | | Win Chance Foods Co.,Ltd. (Bangpoo) 118240 | Expired Products | | 608672 31103680336840N | 074 | JP | | |
| 7-Mar-25 | | UNILEVER THAI HOLDINGS LTD. 103344 | waste finished product | | 608842 311036803193200N | 074 | JP | | |
| 7-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | | 608515 31103680348000N | 074 | JP | | |
| 7-Mar-25 | | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact. / พลาสติกอัดก้อน | | 607740 31103680313370N | 074 | JP | | |
| 7-Mar-25 | | NIPRO (THAILAND) CORPORATION LTD. | Write Off Product (medical equipment) / สินค้าสิ้นอายุ (อุปกรณ์การแพทย์) | | 606304 31103680313370N | 074 | JP | | |
| 7-Mar-25 | | Johnson & Johnson (Thailand) Co.,Ltd. | Off spec goods (bottle) / สินค้าไม่มาตรฐาน (โบลีน) | | 605064 31103680327890N | 074 | JP | | |
| 7-Mar-25 | | Uni-Charm (Thailand) 102110 | Industrial Non-Hazardous Waste(ฟอย) / เศษขยะไม่อันตราย (ฟอย) | | 606407 31102680410420N | 074 | JP | | |
| 7-Mar-25 | | Uni-Charm (Thailand) Co., Ltd. 102110 | ฟอยฉนวน | | 606407 31103680344600N | 074 | JP | | |
| 7-Mar-25 | | SOUTHEAST ASIAN PACKAGING & CANNING LIMITED. 121490 | Packaging | | 606407 31103680352130N | 074 | JP | | |
| 8-Mar-25 | | UNILEVER THAI HOLDINGS LTD. 103344 | waste finished product | | 608842 31103680375910N | 074 | TD | | |
| 8-Mar-25 | | Unilever Thai Holding Limited 100835 | General Mixed Waste HPC | | 605603 311036803811510N | 074 | PD | | |
| 10-Mar-25 | | Beiersdorf (Thailand) Co.,Ltd. 122073 | Product Destruction | | 605683 54880 | 074 | JP | | |
| 10-Mar-25 | | Beiersdorf (Thailand) Co.,Ltd. 122073 | Product Destruction | | 605683 40196 | 074 | JP | | |
| 10-Mar-25 | | Beiersdorf (Thailand) Co.,Ltd. 122073 | Product Destruction | | 605683 40197 | 074 | JP | | |
| 10-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | | 608515 31103680465980N | 074 | JP | | |
| 11-Mar-25 | | UNILEVER THAI HOLDINGS LTD. 103344 | waste finished product | | 608842 311036804801050N | 074 | TD | | |
| 11-Mar-25 | | NECOSMED CO.,LTD. 124691 | Non-hazardous industrial waste | | 606936 31103680478160N | 074 | TD | | |
| 11-Mar-25 | | NECOSMED CO.,LTD. 124691 | Rejected product | | 606938 31103680478160N | 074 | TD | | |
| 11-Mar-25 | | NECOSMED CO.,LTD. 124691 | Off Spec | | 607084 31103680478160N | 074 | TD | | |
| 11-Mar-25 | | NECOSMED CO.,LTD. 124691 | Air filter | | 607088 31103680478160N | 074 | TD | | |
| 11-Mar-25 | | NECOSMED CO.,LTD. 124691 | Sludge from the treatment system | | 607088 31103680478160N | 074 | TD | | |
| 11-Mar-25 | | Thai Meiji Pharmaceutical Co., Ltd 123727 | Foil Scrap / เศษฟอยล์ | | 607787 31103680496930N | 074 | PD | | |
| 11-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าสิ้นอายุ (นม) | | 608395 31103680595650N | 074 | PD | | |
| 11-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าสิ้นอายุ (นม) | | 608395 002709 | 074 | PD | | |
| 11-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (Milk) / สินค้าสิ้นอายุ (นม) | | 608395 31103680595640N | 074 | PD | | |
| 12-Mar-25 | | UNILEVER THAI HOLDINGS LTD. 103344 | waste finished product | | 608842 31103680560280N | 074 | TD | | |
| 12-Mar-25 | | Unilever Thai Holding Limited 100835 | General Mixed Waste HPC | | 605603 31103680527660N | 074 | TD | | |
| 12-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | | 608515 31103680538570N | 074 | TD | | |
| 12-Mar-25 | | DCH Aungmy (Thailand) Limited 124522 | Write off product (เป็นสินค้าสิ้นอายุและบริโภค เช่น อาหารสัตว์เลี้ยง) | | 606616 40233 | 074 | PD | | |
| 12-Mar-25 | | DCH Aungmy (Thailand) Co., Ltd. 124522 | Product Destruction | | 605683 40231 | 074 | PD | | |
| 12-Mar-25 | | DCH Aungmy (Thailand) Co., Ltd. 124522 | Write off product (เป็นสินค้าสิ้นอายุและบริโภค เช่น อาหารสัตว์เลี้ยง) | | 606616 40231 | 074 | PD | | |
| 12-Mar-25 | | DHL Supply Chain (Thailand) Co.,Ltd (T-Park Wangmai 2 , Mers) 123922 | Write off product (Pet food) | | 607738 40232 | 074 | PD | | |
| 13-Mar-25 | | UNILEVER THAI HOLDINGS LTD. 103344 | waste finished product | | 608842 31103680827940N | 074 | TD | | |
| 13-Mar-25 | | Beiersdorf (Thailand) Co.,Ltd. 100178 | Expired Packaging/บรรจุภัณฑ์เสื่อมคุณภาพ | | 605569 311036808112020N | 074 | PD | | |
| 13-Mar-25 | | Beiersdorf (Thailand) Co.,Ltd. 100178 | Expired Packaging/บรรจุภัณฑ์เสื่อมคุณภาพ | | 605569 31103680811110N | 074 | PD | | |
| 13-Mar-25 | | Beiersdorf (Thailand) Co.,Ltd. 100178 | Expired Raw Material | | 605441 31103680812300N | 074 | PD | | |
| 13-Mar-25 | | Beiersdorf (Thailand) Co.,Ltd. 100178 | Expired Packaging/บรรจุภัณฑ์เสื่อมคุณภาพ | | 605569 31103680812470N | 074 | PD | | |
| 13-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606132 31103680829110N | 074 | PD | | |
| 13-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606132 31103680829190N | 074 | PD | | |
| 13-Mar-25 | | Beiersdorf (Thailand) Co., Ltd. 100178 | Expired Packaging/บรรจุภัณฑ์เสื่อมคุณภาพ | | 605569 31103680812300N | 074 | PD | | |
| 13-Mar-25 | | Beiersdorf (Thailand) Co., Ltd. 100178 | Expired Packaging/บรรจุภัณฑ์เสื่อมคุณภาพ | | 605569 - | 074 | PD | | |
| 13-Mar-25 | | Beiersdorf (Thailand) Co., Ltd. 100178 | Expired Packaging/บรรจุภัณฑ์เสื่อมคุณภาพ | | 605569 - | 074 | PD | | |
| 14-Mar-25 | | AviaULD Ltd. 124430 | Paper and Plastic scrap | | 607495 31103680872530N | 074 | TP | | |
| 14-Mar-25 | | UNILEVER THAI HOLDINGS LTD. 103344 | waste finished product | | 608842 31103680709630N | 074 | TD | | |
| 14-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606161 31103680606990N | 074 | TD | | |
| 14-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606161 31103680661030N | 074 | TD | | |
| 14-Mar-25 | | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact. / พลาสติกอัดก้อน | | 607740 31103680606970N | 074 | TD | | |
| 14-Mar-25 | | NIPRO (THAILAND) CORPORATION LTD. | Write Off Product (medical equipment) / สินค้าสิ้นอายุ (อุปกรณ์การแพทย์) | | 606304 31103680691020N | 074 | TD | | |
| 14-Mar-25 | | CHANEL (THAILAND) LIMITED 102787 | Cosmetics Waste/ของเสียจากเครื่องสำอาง | | 606200 40761 | 074 | TP | | |
| 14-Mar-25 | | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Personal Health care) / ผลิตภัณฑ์ที่ไม่สามารถบริโภคได้ (เวชภัณฑ์) | | 608904 31103681079750N | 074 | TD | | |
| 14-Mar-25 | | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Non recycle waste (Paper Scrap) / ของที่ไม่สามารถรีไซเคิลได้ (เศษกระดาษ) | | 608904 31103680991660N | 074 | TD | | |
| 14-Mar-25 | | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Non recycle waste (Plastic film) / ของที่ไม่สามารถรีไซเคิลได้ (พลาสติก) | | 608903 31103680888820N | 074 | TD | | |
| 14-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | | 608515 31103680660570N | 074 | TD | | |
| 14-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606161 31103680660970N | 074 | TD | | |
| 14-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606161 31103680661030N | 074 | TD | | |
| 14-Mar-25 | | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Personal Health care) / ผลิตภัณฑ์ที่ไม่สามารถบริโภคได้ (เวชภัณฑ์) | | 608904 31103680991660N | 074 | TD | | |
| 14-Mar-25 | | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Non recycle waste (Paper Scrap) / ของที่ไม่สามารถรีไซเคิลได้ (เศษกระดาษ) | | 608904 31103680991460N | 074 | TD | | |
| 14-Mar-25 | | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Non recycle waste (Plastic film) / ของที่ไม่สามารถรีไซเคิลได้ (พลาสติก) | | 608903 - | 074 | TD | | |
| 14-Mar-25 | | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Personal Health care) / ผลิตภัณฑ์ที่ไม่สามารถบริโภคได้ (เวชภัณฑ์) | | 608904 31103680709630N | 074 | TD | | |
| 14-Mar-25 | | AviaULD Ltd. 124430 | Paper and Plastic scrap | | 607495 31103680709630N | 074 | TD | | |
| 14-Mar-25 | | CEVA Logistics (Thailand) Ltd.(CDH2 WH) 127127 | Write off product (Fodder Product) | | 606683 40762 | 074 | TD | | |
| 14-Mar-25 | | CEVA Logistics (Thailand) Ltd.(CDH2 WH) 127127 | Write off product (Fodder Product) | | 606683 40763 | 074 | TD | | |
| 14-Mar-25 | | CEVA Logistics (Thailand) Ltd.(CDH2 WH) 127127 | Write off product (Fodder Product) | | 606683 40764 | 074 | TD | | |
| 15-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606132 31103680728450N | 074 | TD | | |
| 15-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606132 31103680728280N | 074 | TD | | |
| 15-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606132 31103680728370N | 074 | TD | | |
| 15-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606132 31103680728340N | 074 | TD | | |
| 15-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606132 31103680728750N | 074 | TD | | |
| 15-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Reject Product (Cosmetic product) / สินค้าที่ไม่สามารถบริโภคได้ (เครื่องสำอาง) | | 606131 31103680728620N | 074 | TD | | |
| 15-Mar-25 | | SSI Manufacturing (Thailand) Co.,Ltd. 100479 | Industrial Non-Hazardous waste / ของทั่วไปไม่อันตราย (เศษของแข็ง) | | 606802 31103680736850N | 074 | TD | | |
| 15-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606132 31103680773740N | 074 | TD | | |
| 15-Mar-25 | | Ekornes (Thailand) Limited (20240037425483) 128832 | General Waste | | 609021 40782 | 074 | TD | | |
| 15-Mar-25 | | Royal Canin (Thailand) Co., Ltd. 127801 | Write Off Product | | 608545 40786 | 074 | TD | | |
| 17-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | | 608515 31103680811220N | 074 | TD | | |
| 17-Mar-25 | | Uni-Charm (Thailand) 102110 | Industrial Non-Hazardous Waste(ฟอย) / เศษขยะไม่อันตราย (ฟอย) | | 601491 31103680778670N | 074 | PD | | |
| 17-Mar-25 | | Thai Meiji Pharmaceutical Co.,Ltd 123727 | Packaging paper | | 607785 31103680794030N | 074 | PD | | |
| 17-Mar-25 | | Ueno Fine Chemical Industry 100714 | Packaging from food material | | 605275 31103680812740N | 074 | PD | | |
| 17-Mar-25 | | HUIYU Public Company Limited (BANKH 1)101857 | Rejected Packaging | | 605371 31103680790900N | 074 | TD | | |
| 17-Mar-25 | | Thai Honda Co., Ltd (factory 1) 124978 | Commercial waste | | 607505 40837 | 074 | TD | | |
| 18-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd 103975 | Write off Product/สินค้าหมดอายุ | | 603825 40845 | 074 | PD | | |
| 18-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd 103975 | Write off Product/สินค้าหมดอายุ | | 603825 40851 | 074 | PD | | |
| 18-Mar-25 | | Miltot Laboratories Co., Ltd. (Building 3) (33-47(3)-4/54ฟย.) | Plastic Packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | | 606132 40853 | 074 | PD | | |
| 18-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd 103975 | Write off Product/สินค้าหมดอายุ | | 603825 40853 | 074 | PD | | |
| 18-Mar-25 | | SANKO MACHINERY (THAILAND) CO.,LTD.102149 | Foil packaging | | 607711 31103680838600N | 074 | TD | | |
| 18-Mar-25 | | SANKO MACHINERY (THAILAND) CO.,LTD.102149 | Expired Product | | 607712 31103680838600N | 074 | TD | | |
| 18-Mar-25 | | THAI OTSUKA PHARMACEUTICAL CO.,LTD. 103589 | Air Filter | | 608067 - | 074 | TD | | |
| 19-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | | 608515 31103680866200N | 074 | PD | | |
| 19-Mar-25 | | WHA Corporation Public Company Limited (unilever) 101378 | Ice-cream write off. / ไอศกรีมหมดอายุ (LTI) | | 600565 3110368095740N | 074 | PD | | |
| 19-Mar-25 | | ZUELLIG PHARMA LTD. 103084 | Damaged Product & Expired Product | | 605256 31103680925560N | 074 | PD | | |

การประเมินคุณภาพของเสียอุตสาหกรรม

Random Check of Industrial Waste Receiving

| Month | Mar-25 | | | | | | | | | |
|-----------|--------|--|--|------------|------------------|----------------|-------------------|--------|--|--|
| Date | Time | Company Name | Waste name | Waste Type | Manifest | Local Disposal | Inspector Signage | Remark | | |
| 19-Mar-25 | | Abbott Laboratories Limited 103715 | Product Destruction | 603685 | 40861 | 074 | PD | | | |
| 19-Mar-25 | | WNV Corporation Public Company Limited (Unilever) 103178 | Ice-cream write off / น้ำไอศกรีม (UIT) | 600556 | 31103680926560N | 074 | PD | | | |
| 19-Mar-25 | | WIPON CARBIDE INDUSTRIES (THAILAND) CO., LTD. | Sticker Scrap | 607032 | 311036809069780N | 074 | PD | | | |
| 20-Mar-25 | | UNILEVER THAI HOLDINGS LTD. 103344 | waste finished product | 608842 | 31103681002810N | 074 | PD | | | |
| 20-Mar-25 | | BATA (THAILAND) LIMITED (Head Office) 124213 | Write Off Product/สินค้าหมดสภาพ | 606583 | 40875 | 074 | PD | | | |
| 20-Mar-25 | | BATA (THAILAND) LIMITED (Head Office) 124213 | Write Off Product/สินค้าหมดสภาพ | 606583 | 40887 | 074 | PD | | | |
| 20-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดสภาพ | 603825 | 40882 | 074 | PD | | | |
| 20-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write Off Product/สินค้าหมดสภาพ | 603825 | 40898 | 074 | PD | | | |
| 20-Mar-25 | | ZUELLIG PHARMALTD. 103084 | Damaged Product & Expired Product | 605256 | 40881 | 074 | PD | | | |
| 20-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write Off Product/สินค้าหมดสภาพ | 603825 | 40881 | 074 | PD | | | |
| 20-Mar-25 | | SANIKO MACHINERY (THAILAND) CO., LTD. 102149 | Expired Product | 607712 | 31103680742400N | 074 | PD | | | |
| 20-Mar-25 | | ZUELLIG PHARMALTD. 103084 | Damaged Product & Expired Product | 605256 | 40880 | 074 | PD | | | |
| 21-Mar-25 | | SSL Manufacturing (Thailand) Co., Ltd. 100479 | Industrial Non-Hazardous waste / ของเสียทั่วไปอุตสาหกรรม (เศษขานวด) | 606802 | 31103681035120N | 074 | TP | | | |
| 21-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดสภาพ | 603825 | 54396 | 074 | TP | | | |
| 21-Mar-25 | | Anulud Ltd. 124430 | Paper and Plastic scrap | 607495 | 40903 | 074 | TP | | | |
| 21-Mar-25 | | That Nakorn Pattana 103301 | Expired Medicine / ยาหมดอายุ | 602558 | 54397 | 074 | TP | | | |
| 21-Mar-25 | | That Nakorn Pattana 103301 | Filter / ฟิลเตอร์จากเครื่องกรองอากาศ | 605006 | 31103681042170N | 074 | TP | | | |
| 21-Mar-25 | | That Nakorn Pattana 103301 | Culture media | 607919 | 31103681042170N | 074 | TP | | | |
| 21-Mar-25 | | Patum Vegetable Oil Co., Ltd. 121627 | Glycerine Residue / กากตะกอนกลีเซอริน | 606129 | 31103681038720N | 074 | TP | | | |
| 21-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดสภาพ | 603825 | 40903 | 074 | TP | | | |
| 21-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดสภาพ | 603825 | 54397 | 074 | TP | | | |
| 21-Mar-25 | | All Food & Beverages (Thailand) Ltd. 105931 | Write off product / สินค้าหมดอายุ | 600910 | 31103681066870N | 074 | TP | | | |
| 21-Mar-25 | | NP Green Corporation Co., Ltd. 124247 | OUT OF SPEC PRODUCTS / ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 607044 | 40942 | 074 | TP | | | |
| 21-Mar-25 | | NP Green Corporation Co., Ltd. 124247 | OUT OF SPEC PRODUCTS / ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 607044 | 40938 | 074 | TP | | | |
| 21-Mar-25 | | CEVA Air and Ocean (Thailand) Co., Ltd. 124990 | Off spec product / สินค้าไปไม่มาตรฐาน | 607123 | 40939 | 074 | TP | | | |
| 21-Mar-25 | | CEVA Air and Ocean (Thailand) Co., Ltd. 124990 | Off spec product / สินค้าไปไม่มาตรฐาน | 607123 | 40940 | 074 | TP | | | |
| 21-Mar-25 | | Kuraray (P&T) | Polymer waste 1 | 101360 | | 074 | TP | | | |
| 22-Mar-25 | | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact. / พลาสติกถักอัด | 607740 | 31103681105660N | 074 | TP | | | |
| 22-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดสภาพ | 603825 | 40947 | 074 | IF | | | |
| 22-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดสภาพ | 603825 | 59012 | 074 | IF | | | |
| 22-Mar-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดสภาพ | 603825 | 59013 | 074 | IF | | | |
| 22-Mar-25 | | World Pet International Co., Ltd. 123553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31103681034300N | 074 | IF | | | |
| 22-Mar-25 | | World Pet International Co., Ltd. 123553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31103681103770N | 074 | IF | | | |
| 22-Mar-25 | | World Pet International Co., Ltd. 123553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31103681121290N | 074 | IF | | | |
| 22-Mar-25 | | World Pet International Co., Ltd. 123553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31103681103460N | 074 | IF | | | |
| 22-Mar-25 | | World Pet International Co., Ltd. 123553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์) | 608212 | 31103681112410N | 074 | IF | | | |
| 22-Mar-25 | | AAF International (Thailand) Co., Ltd. | Air filter | 608778 | 40852 | 074 | TP | | | |
| 22-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31103681162490N | 074 | TP | | | |
| 24-Mar-25 | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 003471 | 074 | TP | | | |
| 24-Mar-25 | | Johnson & Johnson PTE Ltd. (100265) | Return goods (Powder) | 602638 | 003473 | 074 | TP | | | |
| 24-Mar-25 | | NEOCOSMED CO., LTD. 124691 | Non-hazardous industrial waste | 606936 | 003472 | 074 | TP | | | |
| 24-Mar-25 | | NEOCOSMED CO., LTD. 124691 | Rejected product | 606938 | 31103681158710N | 074 | TP | | | |
| 24-Mar-25 | | NEOCOSMED CO., LTD. 124691 | Off Spec | 607084 | 31103681158710N | 074 | TP | | | |
| 24-Mar-25 | | NEOCOSMED CO., LTD. 124691 | Air Filter | 607088 | | 074 | TP | | | |
| 24-Mar-25 | | NEOCOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | 31103681158710N | 074 | TP | | | |
| 24-Mar-25 | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 003473 | 074 | TP | | | |
| 24-Mar-25 | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 003472 | 074 | TP | | | |
| 24-Mar-25 | | EMBASSY OF JAPAN IN THAILAND 103773 | Document | 603808 | 40969 | 074 | TP | | | |
| 24-Mar-25 | | EMBASSY OF JAPAN IN THAILAND 103773 | Document | 603808 | 40962 | 074 | TP | | | |
| 24-Mar-25 | | EMBASSY OF JAPAN IN THAILAND 103773 | Document | 603808 | 40980 | 074 | TP | | | |
| 24-Mar-25 | | EMBASSY OF JAPAN IN THAILAND 103773 | Document | 603808 | 40981 | 074 | TP | | | |
| 24-Mar-25 | | Yamato-Esion (Thailand) Co., Ltd. (Factory 1) 100814 | Off-spec product | 601338 | 31103681158690N | 074 | TP | | | |
| 24-Mar-25 | | SOUTHEAST ASIAN PACKAGING & CANNING LIMITED. 121490 | Packaging | 606407 | 31103681164220N | 074 | TP | | | |
| 25-Mar-25 | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31103681232180N | 074 | TP | | | |
| 25-Mar-25 | | DKSH (THAILAND) LIMITED 103982 | Expired Product (Non-hazardous medicine) | 603862 | 59066 | 074 | TP | | | |
| 25-Mar-25 | | DKSH (THAILAND) LIMITED 103982 | Expired Product (Non-hazardous medicine) | 603862 | 40512 | 074 | TP | | | |
| 25-Mar-25 | | IDS Medical Systems (Thailand) Co., Ltd. | Medical equipment (plastic) | 607316 | 40509 | 074 | TP | | | |
| 25-Mar-25 | | Thai Meij Food Co., Ltd. 124222 | Write off product (MIK) | 606590 | 40505 | 074 | TP | | | |
| 25-Mar-25 | | DKSH (THAILAND) LIMITED 103982 | Expired Product (Non-hazardous medicine) | 603862 | 40510 | 074 | TP | | | |
| 25-Mar-25 | | CEVA Logistics (Thailand) Ltd (CDH WH) 127127 | Write off product (alcoholic beverage) / สินค้าเสื่อมสภาพ (เครื่องดื่มแอลกอฮอล์) | 604514 | | 074 | TP | | | |
| 25-Mar-25 | | Ford Motor Company (Thailand) Limited | Air Filter | 007160 | - | 074 | TP | | | |
| 26-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31103681272360N | 074 | TP | | | |
| 26-Mar-25 | | UNILEVER THAI HOLDINGS LTD. 103344 | waste finished product | 608842 | 31103681317200N | 074 | TP | | | |
| 26-Mar-25 | | Procter & Gamble Manufacturing 100287 | Expired Product (Non-hazardous medicine) | 603862 | 40528 | 074 | TP | | | |
| 26-Mar-25 | | Procter & Gamble Manufacturing 100287 | Expired product (Liquid) | 606497 | 59106 | 074 | TP | | | |
| 26-Mar-25 | | Procter & Gamble Manufacturing 100287 | Off Spec Shampoo | 603812 | 31103681329900N | 074 | TP | | | |
| 26-Mar-25 | | DKSH (THAILAND) LIMITED 103982 | Expired Product (Non-hazardous medicine) | 603862 | 59106 | 074 | TP | | | |
| 26-Mar-25 | | Procter & Gamble Manufacturing 100287 | Expired product | 606179 | 31103681326640N | 074 | TP | | | |
| 26-Mar-25 | | Patum Vegetable Oil Co., Ltd. 121627 | Glycerine Residue / กากตะกอนกลีเซอริน | 606129 | 31103681273790N | 074 | TP | | | |
| 26-Mar-25 | | DKSH (THAILAND) LIMITED 103982 | Expired Product (Non-hazardous medicine) | 603862 | | 074 | TP | | | |
| 27-Mar-25 | | Johnson & Johnson (Thailand) Co., Ltd. | Off spec goods (Lotion) / สินค้าไปไม่มาตรฐาน (โลชั่น) | 605054 | 31103681356340N | 074 | TP | | | |
| 27-Mar-25 | | AGC FLAT GLASS (THAILAND) PCL. 127793 | Commercial Waste/ขยะมูลฝอยทั่วไป | 605975 | 40539 | 074 | TP | | | |
| 27-Mar-25 | | Royal Cam (Thailand) Co., Ltd. 127803 | Write Off Product | 608545 | 40538 | 074 | TP | | | |
| 27-Mar-25 | | W.M. Chemical Industry 100734 | Off spec product | 607813 | 31103681392500N | 074 | TP | | | |
| 27-Mar-25 | | Croft Foods Co., Ltd. 124783 | Expired raw materials | 608987 | 31103681346850N | 074 | TP | | | |
| 28-Mar-25 | | UNILEVER THAI HOLDINGS LTD. 103344 | waste finished product | 608842 | 31103681427610N | 074 | TP | | | |
| 28-Mar-25 | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 003699 | 074 | PD | | | |
| 28-Mar-25 | | Johnson & Johnson PTE Ltd. (100265) | Return goods (Powder) | 608513 | 003696 | 074 | PD | | | |
| 28-Mar-25 | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31103681420530N | 074 | TP | | | |
| 28-Mar-25 | | BATA (THAILAND) LIMITED (Head Office) 124213 | Write Off Product/สินค้าเสื่อมสภาพ | 606583 | 40565 | 074 | TP | | | |
| 28-Mar-25 | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 003700 | 074 | TP | | | |
| 28-Mar-25 | | NP Green Corporation Co., Ltd. 124247 | OUT OF SPEC PRODUCTS / ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 607044 | 40561 | 074 | TP | | | |
| 28-Mar-25 | | NP Green Corporation Co., Ltd. 124247 | Expired Products (Medicines Non-Hazardous) / สินค้าหมดอายุ (ยาไม่) | 606998 | 40562 | 074 | TP | | | |

การประเมินคุณภาพของเสียอุตสาหกรรม

Random Check of Industrial Waste Receiving

| Month | Apr-25 | Date | Time | Company Name | Waste name | Waste Type | Manifest | Local Disposal | Inspector Signage | Remark |
|----------|--------|------|------|---|---|------------|-----------------|----------------|-------------------|--------|
| 1-Apr-25 | | | | AFB International (Thailand) Limited 128792 | Write off products. (Pet Food) / สินค้าเสื่อมสภาพ (อาหารสัตว์เคี้ยวเอื้อง) | 608820 | 31104680004100N | 074 | IF | |
| 1-Apr-25 | | | | AFB International (Thailand) Limited 128792 | Write off products. (Pet Food) / สินค้าเสื่อมสภาพ (อาหารสัตว์เคี้ยวเอื้อง) | 608820 | 31104680039690N | 074 | IF | |
| 2-Apr-25 | | | | Kuraray (P&T) | Polymer waste 1 | 101360 | 40622 | 074 | IF | |
| 2-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31104680103440N | 074 | IF | |
| 3-Apr-25 | | | | PREMIER MARKETING PUBLIC COMPANY LIMITED 128436 | Write off product | 608705 | 40656 | 074 | IF | |
| 4-Apr-25 | | | | Uni-Charm (Thailand) Co., Ltd. 102310 | Industrial Non-Hazardous Waste(ฟิล์ม) / เศษของใช้พลาสติก (ฟิล์ม) | 601491 | 31104680193310N | 074 | IF | |
| 4-Apr-25 | | | | Uni-Charm (Thailand) Co., Ltd. 102310 | พลาสติก | 601730 | | 074 | IF | |
| 4-Apr-25 | | | | Uni-Charm (Thailand) Co., Ltd. 102310 | Plastic and paper roll | 606945 | 31104680193310N | 074 | IF | |
| 4-Apr-25 | | | | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact. / พลาสติกถักอัด | 607740 | 31104680198980N | 074 | IF | |
| 4-Apr-25 | | | | NIPRO (THAILAND) CORPORATION LTD. | Write Off Product (medical equipment) / สินค้าเสื่อมสภาพ (อุปกรณ์ทางการแพทย์) | 606304 | 31104680198980N | 074 | IF | |
| 5-Apr-25 | | | | That Nakorn Pattana 103301 | Expired Medicine / ยาหมดอายุ | 602558 | 40714 | 074 | PD | |
| 5-Apr-25 | | | | That Nakorn Pattana 103301 | Filter / ฟิลเตอร์จากเครื่องกรองอากาศ | 605006 | 31104680258910N | 074 | PD | |
| 5-Apr-25 | | | | That Nakorn Pattana 103301 | Culture media | 607919 | 31104680258910N | 074 | PD | |
| 5-Apr-25 | | | | That Nakorn Pattana 103301 | Waste Water from Process / น้ำเสียจากกระบวนการผลิต | 602869 | 31104680258910N | 074 | PD | |
| 8-Apr-25 | | | | Best and Billion Beauty Co., Ltd. 129378 (สาคูไทโพ) | Write off product | 609062 | 40738 | 074 | PD | |
| 5-Apr-25 | | | | C.N. ONE WORK CO., LTD. 138052 | Write off product / สินค้าเสื่อมสภาพ | 608627 | | 074 | PD | |
| 8-Apr-25 | | | | Unilever Thai Holding Limited 100835 | Reject product/Personal care contaminated with Plastic | 608553 | 31104680402160N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971980N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971660N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971340N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Non-hazardous industrial waste | 606936 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Rejected product | 606938 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Off Spec | 607084 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Air Filter | 607088 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971980N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971660N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971340N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Non-hazardous industrial waste | 606936 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Rejected product | 606938 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Off Spec | 607084 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Air Filter | 607088 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971980N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971660N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971340N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Non-hazardous industrial waste | 606936 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Rejected product | 606938 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Off Spec | 607084 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Air Filter | 607088 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971980N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971660N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971340N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Non-hazardous industrial waste | 606936 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Rejected product | 606938 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Off Spec | 607084 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Air Filter | 607088 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971980N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971660N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971340N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Non-hazardous industrial waste | 606936 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Rejected product | 606938 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Off Spec | 607084 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Air Filter | 607088 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971980N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971660N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971340N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Non-hazardous industrial waste | 606936 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Rejected product | 606938 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Off Spec | 607084 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Air Filter | 607088 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971980N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971660N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971340N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Non-hazardous industrial waste | 606936 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Rejected product | 606938 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Off Spec | 607084 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Air Filter | 607088 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971980N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971660N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971340N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Non-hazardous industrial waste | 606936 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Rejected product | 606938 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Off Spec | 607084 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Air Filter | 607088 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971980N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971660N | 074 | IF | |
| 8-Apr-25 | | | | Johnson & Johnson PTE Ltd. (100265) | Return goods from warehouse | 602638 | 31104680971340N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Non-hazardous industrial waste | 606936 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Rejected product | 606938 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Off Spec | 607084 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Air Filter | 607088 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | NEOCOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | 31104680359480N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 121405 Samrong | Write off products (MIK) / สินค้าเสื่อมสภาพ | 608395 | 31104680363600N | 074 | IF | |
| 8-Apr-25 | | | | Friesland Campina (Thailand) PCL. 12140 | | | | | | |

การประเมินการรับกากของเสียอุตสาหกรรม
Random Check of Industrial Waste Receiving

| Month : Apr-25 | Date | Time | Company Name | Waste name | Waste Type | Manifest | Local Disposal | Inspector Signage | Remark |
|----------------|-----------|------|---|--|------------|-----------------|----------------|-------------------|--------|
| 28-Apr-25 | 28-Apr-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 39478 | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | AGC FLAT GLASS (THAILAND) PCL 121733 | Commercial Waste/ขยะมูลฝอยทั่วไป | 605975 | 39478 | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact / พลาสติกอัดก้อน | 607740 | 39494 | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | NIPRO (THAILAND) CORPORATION LTD. | Write Off Product (medical equipment) / สินค้าเสื่อมสภาพ (อุปกรณ์การแพทย์) | 606304 | - | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | Uni-Charm (Thailand) Co., Ltd. 124239 | Industrial Non-Hazardous Waste(ฝักร) / เศษขนมปังไม่เนื้อมัน (ฝักร) | 601491 | 31104681127190N | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | Uni-Charm (Thailand) Co., Ltd. 102110 | ผ้าขาวม้า | 602730 | 31104681128060N | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | OKSIL (THAILAND) LIMITED 103982 | Expired Product (Non-hazardous medicine) | 601862 | 44012 | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | ZUELLIG PHARMA LTD. 102084 | Damaged Product & Expired Product | 605256 | 39600 | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | UNION DRUG LABS. LTD. 102831 | Off Spec Packaging | 609067 | 31104681133210N | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | The Medipharma Co., Ltd. 124239 | Air Filter | 606718 | 31104681151140N | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | The Medipharma Co., Ltd. 124239 | Packaging Scrap | 606716 | 31104681151140N | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | The Medipharma Co., Ltd. 124239 | Drugs powder | 606598 | 31104681151140N | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | LG HOUSEHOLD & HEALTH CARE (THAILAND) LTD. 127303 | Write off product (cosmetics and skin cream) | 608334 | 44004 | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | UNILEVER THAI TRADING LTD. 123282 | Commercial Waste | 606219 | 39488 | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | Nestle/Amata city Rayong | Off Spec Products | 009375 | 31102681284280N | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | Unilever Pharmaceuticals Co., Ltd. 100401 | Expired Product/สินค้าหมดอายุ (ยาขับถ่ายที่ไม่น่าเป็นอันตราย) | 000639 | | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | AB Food & Beverages (Thailand) Ltd. 101931 | Write off product / สินค้าหมดอายุ | 600910 | 31104681223130N | 074 | TP | |
| 28-Apr-25 | 28-Apr-25 | | AB Food & Beverages (Thailand) Ltd. 101931 | Write off product / สินค้าหมดอายุ | 600910 | 31104681226610N | 074 | TP | |
| 30-Apr-25 | 30-Apr-25 | | P.M.A.P. & CO., LTD. (3-105-29/6028) | Out of spec products / ผลิตภัณฑ์ที่ไม่ได้มาตรฐานและขายแล้ว | 607604 | 44052 | 074 | TP | |
| 30-Apr-25 | 30-Apr-25 | | Procter&Gamble Trading (Thailand) Ltd. 123243 | Expired product | 606179 | 44060 | 074 | TP | |
| 30-Apr-25 | 30-Apr-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31104681300380N | 074 | TP | |
| 30-Apr-25 | 30-Apr-25 | | AB Food & Beverages (Thailand) Ltd. 101931 | Write off product / สินค้าหมดอายุ | 600910 | 31104681282560N | 074 | TP | |
| 30-Apr-25 | 30-Apr-25 | | AB Food & Beverages (Thailand) Ltd. 101931 | Write off product / สินค้าหมดอายุ | 600910 | 31104681267090N | 074 | TP | |
| 30-Apr-25 | 30-Apr-25 | | AB Food & Beverages (Thailand) Ltd. 101931 | Write off product / สินค้าหมดอายุ | 600910 | 31104681292240N | 074 | TP | |

การประเมินการรับกากของเสียอุตสาหกรรม
Random Check of Industrial Waste Receiving

| Month : May-25 | Date | Time | Company Name | Waste name | Waste Type | Manifest | Local Disposal | Inspector Signage | Remark |
|----------------|-----------|------|---|--|------------|-----------------|----------------|-------------------|--------|
| 2-May-25 | 2-May-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 44208 | 074 | JF | |
| 2-May-25 | 2-May-25 | | UNILEVER THAI TRADING LTD. 123282 | Water filtered product | 606842 | 44032 | 074 | JF | |
| 2-May-25 | 2-May-25 | | Royal Copenhagen (Thailand) Ltd. 10190000325602126454 | Foam Scrap | 607908 | 44127 | 074 | PD | |
| 2-May-25 | 2-May-25 | | Royal Copenhagen (Thailand) Ltd. 10190000325602126454 | Rubber Scrap | 607907 | 44128 | 074 | PD | |
| 2-May-25 | 2-May-25 | | Royal Copenhagen (Thailand) Ltd. 10190000325602126454 | Plastic Packaging | 608876 | 44100 | 074 | PD | |
| 3-May-25 | 3-May-25 | | Johnson & Johnson (Thailand) Co., Ltd. | Off spec goods (lotion) / สินค้าไม่มาตรฐาน (โลชั่น) | 605064 | 31105680219510N | 074 | PD | |
| 3-May-25 | 3-May-25 | | A&S Can Corporation Co., Ltd. 129305 | Write off product (Plant Amino Acids) | 609017 | 44151 | 074 | PD | |
| 3-May-25 | 3-May-25 | | A&S Can Corporation Co., Ltd. 129305 | Write off product (Plant Amino Acids) | 609017 | 44170 | 074 | PD | |
| 6-May-25 | 6-May-25 | | SANKO MACHINERY (THAILAND) CO., LTD. 102149 | Foil packaging | 607711 | 31105680186880N | 074 | PD | |
| 6-May-25 | 6-May-25 | | S.E.A. CONSUMER PRODUCT CO.LTD. 123104 | Write Off Product/สินค้าหมดอายุ | 606112 | 44177 | 074 | PD | |
| 6-May-25 | 6-May-25 | | Thai Japanese Association School 103251 | Old Document+CD / เอกสาร+CD | 602910 | | 074 | JF | |
| 6-May-25 | 6-May-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31105680194140N | 074 | JF | |
| 6-May-25 | 6-May-25 | | NECOSMED CO., LTD. 124691 | Non-hazardous industrial waste | 606936 | 31105680186360N | 074 | JF | |
| 6-May-25 | 6-May-25 | | NECOSMED CO., LTD. 124691 | Rejected product | 606938 | 31105680186360N | 074 | JF | |
| 6-May-25 | 6-May-25 | | NECOSMED CO., LTD. 124691 | Off Spec | 607084 | 31105680186360N | 074 | JF | |
| 6-May-25 | 6-May-25 | | NECOSMED CO., LTD. 124691 | Air Filter | 607088 | | 074 | JF | |
| 6-May-25 | 6-May-25 | | NECOSMED CO., LTD. 124691 | Sludge from the treatment system | 607085 | 31105680186360N | 074 | JF | |
| 7-May-25 | 7-May-25 | | Itano (Thailand) Limited (Bang Wa) 124194 | Fluorescent Lamp / หลอดไฟฟลูออโร | 608858 | 44210 | 074 | JF | |
| 7-May-25 | 7-May-25 | | SANKO MACHINERY (THAILAND) CO., LTD. 102149 | Foil packaging | 607711 | 31105680247760N | 075 | JF | |
| 7-May-25 | 7-May-25 | | SANKO MACHINERY (THAILAND) CO., LTD. 102149 | Expired Product | 607712 | 31105680247760N | 075 | JF | |
| 7-May-25 | 7-May-25 | | Unilever Thai Holding Limited 100835 | Rejected Product (Homocare) | 607604 | 3110568032910N | 074 | JF | |
| 7-May-25 | 7-May-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 44211 | 074 | JF | |
| 7-May-25 | 7-May-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31105680243400N | 074 | JF | |
| 7-May-25 | 7-May-25 | | Milott Laboratories Co., Ltd. (Building 3) (3-4731-4/5484) | Plastic packaging / บรรจุภัณฑ์ที่เป็นพลาสติก | 606132 | 31105680233410N | 074 | JF | |
| 7-May-25 | 7-May-25 | | IC QUALITY SYSTEM CO., LTD. 127525 | Infectious waste / ขยะติดเชื้อ | 604858 | | 074 | JF | |
| 8-May-25 | 8-May-25 | | Nestle Amata | Off Spec Product | 009371 | 31105680347910N | 074 | JF | |
| 8-May-25 | 8-May-25 | | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 1231 | Reject product (Pharmaceutical) / สินค้าไม่มาตรฐานยาทางการแพทย์ | 605430 | 31105680399230N | 074 | JF | |
| 8-May-25 | 8-May-25 | | Reckitt Benckiser Healthcare Manufacturing (Thailand) Ltd. 1231 | Waste water from treatment | 605429 | 31105680400100N | 074 | JF | |
| 8-May-25 | 8-May-25 | | CHANEL (THAILAND) LIMITED 102787 | Cosmetics Waste/เครื่องสำอาง กระป๋องครีม แว่นกันแดด เหล้าชา | 602050 | 44228 | 074 | JF | |
| 8-May-25 | 8-May-25 | | AGC FLAT GLASS (THAILAND) PCL 122733 | Commercial Waste/ขยะมูลฝอยทั่วไป | 605975 | 44216 | 074 | JF | |
| 8-May-25 | 8-May-25 | | Trend Intertrade Co., Ltd. 127514 | Glass scrap | 606815 | | 074 | JF | |
| 8-May-25 | 8-May-25 | | NP Green Corporation Co., Ltd. 124247 | Expired Products (Medicines Non-Hazardous) / สินค้าหมดอายุ (ยา) | 606988 | 44232 | 074 | JF | |
| 9-May-25 | 9-May-25 | | Johnson & Johnson (Thailand) Co., Ltd. | Off spec goods (lotion) / สินค้าไม่มาตรฐาน (โลชั่น) | 605064 | 31105680390180N | 074 | JF | |
| 9-May-25 | 9-May-25 | | Bk Chemical Co., Ltd. 125613 | Expire medicine (Non Penicillin) | 609013 | 31105680383400N | 074 | JF | |
| 9-May-25 | 9-May-25 | | Thai Honda Manufacturing Co., Ltd.(factory1) 124978 | Mixed Packaging + Paper | 604281 | 31105680373270N | 074 | JF | |
| 9-May-25 | 9-May-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31105680392280N | 074 | JF | |
| 14-May-25 | 14-May-25 | | Uni-Charm (Thailand) 102110 | Industrial Non-Hazardous Waste(ฝักร) / เศษขนมปังไม่เนื้อมัน (ฝักร) | 601491 | 74592 | 074 | TP | |
| 14-May-25 | 14-May-25 | | Uni-Charm (Thailand) Co., Ltd. 102110 | ผ้าขาวม้า | 602730 | 31105680541290N | 074 | TP | |
| 14-May-25 | 14-May-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31105680599530N | 074 | TP | |
| 14-May-25 | 14-May-25 | | Beiersdorf (Thailand) Co., Ltd. 122073 | Product Destruction | 605683 | 74588 | 074 | TP | |
| 14-May-25 | 14-May-25 | | ZUELLIG PHARMA LTD. 102084 | Damaged Product & Expired Product | 605256 | 74603 | 074 | TP | |
| 14-May-25 | 14-May-25 | | ZUELLIG PHARMA LTD. 102084 | Damaged Product & Expired Product | 605256 | 74602 | 074 | TP | |
| 14-May-25 | 14-May-25 | | Patum Vegetal Oil Co., Ltd. 121627 | Glycerine Residue / กากกลีเซอรีน | 606129 | 31105680542710N | 074 | TP | |
| 14-May-25 | 14-May-25 | | DCU Auriga (Thailand) Limited 124252 | Foam and cold gel pads. / โฟมและแผ่นเจลเย็น | 607175 | 74575 | 074 | TP | |
| 14-May-25 | 14-May-25 | | CDRI Air and Ocean (Thailand) Co., Ltd. 124990 | Off spec product / สินค้าไม่มาตรฐาน | 607123 | 74598 | 074 | TP | |
| 14-May-25 | 14-May-25 | | DCU Motor | Air Filter | 007160 | 31105680558800N | 074 | TP | |
| 15-May-25 | 15-May-25 | | HFC Prestige Manufacturing (Thailand) Ltd. 102923 | Off-Spec product / ผลิตภัณฑ์ที่ไม่ได้มาตรฐาน | 607215 | 31105680624080N | 074 | JF | |
| 15-May-25 | 15-May-25 | | Beiersdorf (Thailand) Co., Ltd. 122073 | Product Destruction | 605683 | 63780 | 074 | PD | |
| 15-May-25 | 15-May-25 | | Beiersdorf (Thailand) Co., Ltd. 122073 | Product Destruction | 605683 | 74617 | 074 | PD | |
| 15-May-25 | 15-May-25 | | P.M.A.P. & CO., LTD. (3-106-24/6049) | Out of spec products (raw materials) / วัตถุดิบหมดอายุ | 607143 | 31105680670590N | 074 | PD | |
| 15-May-25 | 15-May-25 | | AviutLTD Ltd. 124430 | Paper and Plastic scrap | 607495 | 31105680680570N | 074 | PD | |
| 16-May-25 | 16-May-25 | | Beiersdorf (Thailand) Co., Ltd. 100178 | Expired Packaging/บรรจุภัณฑ์เสื่อมสภาพ | 605569 | 31105680670630N | 074 | PD | |
| 16-May-25 | 16-May-25 | | l'Oréal (Thailand) Ltd. 101283 | Expired Product (Cosmetics) / ผลิตภัณฑ์เสื่อมสภาพ (เครื่องสำอาง) | 607186 | 74620 | 074 | PD | |
| 17-May-25 | 17-May-25 | | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact / พลาสติกอัดก้อน | 607740 | 31105680731620N | 074 | JF | |
| 17-May-25 | 17-May-25 | | The Medipharma Co., Ltd. 124239 | Packaging Scrap | 606598 | - | 074 | JF | |
| 17-May-25 | 17-May-25 | | The Medipharma Co., Ltd. 124239 | Drugs powder | 606598 | - | 074 | JF | |
| 17-May-25 | 17-May-25 | | NIPRO (THAILAND) CORPORATION LTD. | Off spec packaging / บรรจุภัณฑ์เสื่อมสภาพ | 606307 | 31105680730140N | 074 | JF | |
| 18-May-25 | 18-May-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31105680781050N | 074 | PD | |
| 18-May-25 | 18-May-25 | | Central Department Store Ltd. (Warehouse) | Out of spec products/สินค้าที่ไม่ได้มาตรฐาน/เสื่อมสภาพ | 605135 | 74655 | 074 | PD | |
| 18-May-25 | 18-May-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 63945 | 074 | PD | |
| 18-May-25 | 18-May-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 63946 | 074 | PD | |
| 18-May-25 | 18-May-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 74656 | 074 | PD | |
| 18-May-25 | 18-May-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 63960 | 074 | PD | |
| 18-May-25 | 18-May-25 | | World Pet International Co., Ltd. 123553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์เลี้ยง) | 608212 | 31105680781380N | 074 | PD | |
| 18-May-25 | 18-May-25 | | World Pet International Co., Ltd. 123553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์เลี้ยง) | 608212 | 31105680788460N | 074 | PD | |
| 18-May-25 | 18-May-25 | | World Pet International Co., Ltd. 123553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์เลี้ยง) | 608212 | 31105680788880N | 074 | PD | |
| 18-May-25 | 18-May-25 | | World Pet International Co., Ltd. 123553 | Write off product (Pet food) / สินค้าเสื่อมสภาพ (อาหารสัตว์เลี้ยง) | 608212 | 31105680796550N | 074 | PD | |
| 19-May-25 | 19-May-25 | | UNILEVER THAI TRADING LTD. 123282 | Commercial Waste | 606219 | 74657 | 074 | PD | |
| 20-May-25 | 20-May-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 74681 | 074 | PD | |
| 20-May-25 | 20-May-25 | | Sino-Pacific Trading (Thailand) Co., Ltd. 103975 | Write off Product/สินค้าหมดอายุ | 603825 | 74672 | 074 | PD | |
| 20-May-25 | 20-May-25 | | AAF International (Thailand) Co., Ltd. | Air filter | 608778 | 74671 | 074 | PD | |
| 20-May-25 | 20-May-25 | | AB Food & Beverages (Thailand) Ltd. 101931 | Write off product / สินค้าหมดอายุ | 600910 | 31105680856280N | 074 | PD | |
| 21-May-25 | 21-May-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31105680959230N | 074 | JF | |
| 21-May-25 | 21-May-25 | | Abbott Laboratories Limited 101715 | Product Destruction | 603685 | 74686 | 074 | JF | |
| 21-May-25 | 21-May-25 | | Royal Canin (Thailand) Co., Ltd. 127801 | Write Off Product | 608545 | 74689 | 074 | JF | |
| 21-May-25 | 21-May-25 | | ZUELLIG PHARMA LTD. 102084 | Damaged Product & Expired Product | 605256 | 74687 | 074 | JF | |
| 21-May-25 | 21-May-25 | | ZUELLIG PHARMA LTD. 102084 | Damaged Product & Expired Product | 605256 | 74688 | 074 | JF | |
| 21-May-25 | 21-May-25 | | NP Green Corporation Co., Ltd. 124247 | OUT Of SPEC PRODUCTS / ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 607044 | 74691 | 074 | JF | |
| 21-May-25 | 21-May-25 | | Kursara (P&S) | Polymer waste 1 | 020559 | 74694 | 074 | PD | |
| 22-May-25 | 22-May-25 | | Unilever Thai Holding Limited 100835 | Reject product Personal care contaminated with Plastic | 608553 | 74693 | 074 | TP | |
| 22-May-25 | 22-May-25 | | Unilever Thai Holding Limited 100835 | Rejected Product (R&D Plant) | 605121 | 74696 | 074 | TP | |
| 22-May-25 | 22-May-25 | | NIPRO (THAILAND) CORPORATION LTD. | Off spec plastic compact / พลาสติกอัดก้อน | 607740 | 74711 | 074 | TP | |
| 22-May-25 | 22-May-25 | | NIPRO (THAILAND) CORPORATION LTD. | Write Off Product (medical equipment) / สินค้าเสื่อมสภาพ (อุปกรณ์การแพทย์) | 606304 | 31105680993130N | 074 | TP | |
| 22-May-25 | 22-May-25 | | AGC FLAT GLASS (THAILAND) PCL 122733 | Commercial Waste/ขยะมูลฝอยทั่วไป | 605975 | 74722 | 074 | TP | |
| 22-May-25 | 22-May-25 | | Thai Nakorn Pattana 103301 | Expired Medicine / ยาหมดอายุ | 602558 | 31105680993250N | 074 | TP | |
| 22-May-25 | 22-May-25 | | Thai Nakorn Pattana 103301 | Filter / แขนกรองจากเครื่องกรองอากาศ | 605006 | 31105680993250N | 074 | TP | |



a member of



05-EN-FDSV1

การสุ่มเลือกบันทึกของเสียอุตสาหกรรม

Random Check of Industrial Waste Receiving

| Month : May-25 | | | | | | | | | |
|----------------|------|--|---|------------|-----------------|----------------|-------------------|--------|--|
| Date | Time | Company Name | Waste name | Waste Type | Manifest | Local Disposal | Inspector Signage | Remark | |
| 23-May-25 | | NEOCOSMED CO.,LTD. 124691 | Off spec | 607084 | 31105681050870N | 074 | TP | | |
| 23-May-25 | | NEOCOSMED CO.,LTD. 124691 | Air filter | 607088 | | 074 | TP | | |
| 23-May-25 | | NEOCOSMED CO.,LTD. 124691 | Sludge from the treatment system | 607085 | 31105681050870N | 074 | TP | | |
| 23-May-25 | | NP Green Corporation Co., Ltd 124247 | Expired Products (Medicines Non-Hazardous) / สินค้าหมดอายุ (ยาไม่) | 606988 | 74735 | 074 | TP | | |
| 24-May-25 | | L'Oreal (Thailand) Ltd. 101283 | Expired Product (Cosmetics) / ผลิตภัณฑ์เสื่อมสภาพ (เครื่องสำอาง) | 607186 | 74732 | 074 | TP | | |
| 24-May-25 | | L'Oreal (Thailand) Ltd. 101283 | Expired Product (Cosmetics) / ผลิตภัณฑ์เสื่อมสภาพ (เครื่องสำอาง) | 607186 | 74746 | 074 | TP | | |
| 24-May-25 | | L'Oreal (Thailand) Ltd. 101283 | Expired Product (Cosmetics) / ผลิตภัณฑ์เสื่อมสภาพ (เครื่องสำอาง) | 607186 | 74744 | 074 | TP | | |
| 24-May-25 | | Procter&Gamble Trading (Thailand) Ltd. 123243 | Expired product (Liquid) | 606497 | 61812 | 074 | TP | | |
| 24-May-25 | | L'Oreal (Thailand) Ltd. 101283 | Expired Product (Cosmetics) / ผลิตภัณฑ์เสื่อมสภาพ (เครื่องสำอาง) | 607186 | 61813 | 074 | TP | | |
| 24-May-25 | | L'Oreal (Thailand) Ltd. 101283 | Expired Product (Cosmetics) / ผลิตภัณฑ์เสื่อมสภาพ (เครื่องสำอาง) | 607186 | 61812 | 074 | TP | | |
| 26-May-25 | | AMWAY THAILAND CO., LTD.1004043 | Off spec consumer product / สินค้าผู้บริโภคที่หมดอายุ/เสื่อมสภาพ | 604163 | 73273 | 074 | TP | | |
| 26-May-25 | | Unilever Thai Holding Limited 100835 | Rejected Product (Homocare) | 603604 | 31105681181440N | 074 | TP | | |
| 26-May-25 | | AGC FLAT GLASS (THAILAND) PLC. 122733 | Commercial Waste/ขยะมูลฝอยทั่วไป | 605975 | 73267 | 074 | TP | | |
| 26-May-25 | | SSL Manufacturing (Thailand) Co., Ltd. 100479 | Industrial Non-Hazardous waste / ขยะทั่วไปอุตสาหกรรม (เศษยาง,เศษ) | 606802 | 31105681152080N | 074 | TP | | |
| 26-May-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31105681204090N | 074 | TP | | |
| 26-May-25 | | Central Department Store Ltd. (Warehouse) 120998 | Out of spec product/ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 605135 | 73272 | 074 | TP | | |
| 26-May-25 | | Central Department Store Ltd. (Warehouse) 120998 | Out of spec product/ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 605135 | 73271 | 074 | TP | | |
| 26-May-25 | | Procter&Gamble Trading (Thailand) Ltd. 123243 | Expired product | 606179 | 73269 | 074 | TP | | |
| 26-May-25 | | Central Department Store Ltd. (Warehouse) 120998 | Out of spec product/ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 605135 | 73269 | 074 | TP | | |
| 26-May-25 | | Central Department Store Ltd. (Warehouse) 120998 | Out of spec product/ผลิตภัณฑ์ที่หมดอายุ/เสื่อมสภาพ | 605135 | 73270 | 074 | TP | | |
| 26-May-25 | | Unilever Fine Chemical Industry 100714 | Packaging from food material | 605275 | - | 074 | TP | | |
| 26-May-25 | | UNILEVER THAI TRADING LTD. 123282 | Commercial Waste | 606219 | - | 074 | TP | | |
| 26-May-25 | | DHL Express International (Thailand) Ltd. 124370 | Old uniform | 606857 | 73287 | 074 | TP | | |
| 26-May-25 | | DHL Express International (Thailand) Ltd. 124370 | Old documents | 606686 | 73286 | 074 | TP | | |
| 27-May-25 | | Unilever Thai Holding Limited 100835 | Reject product Personal care contaminated with Plastic | 608553 | 31105681251240N | 074 | TP | | |
| 27-May-25 | | Uni-Chem (Thailand) Co., Ltd. 102110 | Industrial Non-Hazardous Waste(ใบ) / เศษยาง ไม้ยางเหลือ (ใบ) | 601491 | 31105681205130N | 074 | TP | | |
| 27-May-25 | | Uni-Chem (Thailand) Co., Ltd. 102110 | Sanitary napkin & Sheet / ผ้าอนามัย และแผ่นอนามัยที่หมดอายุ | 602730 | 31105681204810N | 074 | TP | | |
| 27-May-25 | | DKSH (THAILAND) LIMITED 103982 | Expired Product (Non-hazardous medicine) | 603862 | 73296 | 074 | TP | | |
| 27-May-25 | | DKSH (THAILAND) LIMITED 103982 | Expired Product (Non-hazardous medicine) | 603862 | 73295 | 074 | TP | | |
| 27-May-25 | | BEAUTRIUM COMPANY LIMITED | Write-off product (Cosmetics) / สินค้าเสื่อมสภาพ (เครื่องสำอาง) | 609059 | 73301 | 074 | TP | | |
| 27-May-25 | | BEAUTRIUM COMPANY LIMITED | Write-off product (Cosmetics) / สินค้าเสื่อมสภาพ (เครื่องสำอาง) | 609059 | 73302 | 074 | TP | | |
| 27-May-25 | | BEAUTRIUM COMPANY LIMITED | Write-off product (Cosmetics) / สินค้าเสื่อมสภาพ (เครื่องสำอาง) | 609059 | 73299 | 074 | TP | | |
| 28-May-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31105681299140N | 074 | TP | | |
| 28-May-25 | | Johnson & Johnson PTE Ltd. (100265) | Raw Material | 607031 | 31105681291450N | 074 | TP | | |
| 28-May-25 | | Johnson & Johnson PTE Ltd. (100265) | Raw Material | 607031 | | 074 | TP | | |
| 28-May-25 | | Reckitt Bendiskier Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Pharmaceutical) / สินค้าไม่ผ่านมาตรฐาน(ยา,อุปกรณ์) | 605149 | 31105681281080N | 074 | TP | | |
| 28-May-25 | | Reckitt Bendiskier Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Personal Health care) / ผลิตภัณฑ์ที่เข้าไม่ผ่านมาตรฐาน (เวชภัณฑ์) | - | - | 074 | TP | | |
| 28-May-25 | | Reckitt Bendiskier Healthcare Manufacturing (Thailand) Ltd. 121499 | Reject product (Personal Health care) / ผลิตภัณฑ์ที่เข้าไม่ผ่านมาตรฐาน (เวชภัณฑ์) | - | - | 074 | TP | | |
| 28-May-25 | | Danone Specialized Nutrition (Thailand) Co., Ltd.120851 | Packaging plastic | 608793 | 31105681343220N | 074 | TP | | |
| 28-May-25 | | Danone Specialized Nutrition (Thailand) Co., Ltd.120851 | Off spec product (Milk UHT) | 607986 | 31105681343220N | 074 | TP | | |
| 28-May-25 | | Puratos (Thailand) Co.,Ltd. 120768 | Packaging | 608664 | 006872 | 074 | TP | | |
| 28-May-25 | | THAI OTSUKA PHARMACEUTICAL CO.,LTD. 103589 | Air Filter | 608067 | 31105681265470N | 074 | TP | | |
| 28-May-25 | | THAI OTSUKA PHARMACEUTICAL CO.,LTD. 103589 | Infusion Set | 608124 | 31105681265470N | 074 | TP | | |
| 29-May-25 | | Johnson & Johnson PTE Ltd. (100265) | Raw Material | 607031 | - | 074 | TP | | |
| 29-May-25 | | UNILEVER THAI TRADING LTD. 123282 | Commercial Waste | 606219 | 73333 | 074 | TP | | |
| 30-May-25 | | Mega Lifesciences Public Co., Ltd. 124474 2 | Expire Packaging | 608378 | 31105681402800N | 074 | TP | | |
| 30-May-25 | | Mega Lifesciences Public Co., Ltd. 124474 2 | Expire Packaging | 608378 | 31105681413280N | 074 | TP | | |
| 30-May-25 | | Friesland Campina (Thailand) PCL 121405 | Dairy waste (นมเสียจากการผลิต) / Dairy waste (นมเสียจากการผลิต) | 608515 | 31105681413420N | 074 | TP | | |
| 30-May-25 | | Mega Lifesciences Public Co., Ltd. 124474 2 | Expire Packaging | 608378 | 31105681406160N | 074 | TP | | |
| 30-May-25 | | Mega Lifesciences Public Co., Ltd. 124474 2 | Expire Packaging | 608378 | 31105681413640N | 074 | TP | | |
| 30-May-25 | | Johnson & Johnson (Thailand) Co.,Ltd. | Off spec goods (Lotion) / สินค้าไม่ผ่านมาตรฐาน (โลชั่น) | 605064 | 31105681406440N | 074 | TP | | |
| 30-May-25 | | Mega Lifesciences Public Co., Ltd. 124474 2 | Expire Packaging | 608378 | 31105681413420N | 074 | TP | | |
| 30-May-25 | | Mega Lifesciences Public Co., Ltd. 124474 2 | Expire Packaging | 608378 | 31105681406440N | 074 | TP | | |
| 30-May-25 | | CEVA Logistics (Thailand) Ltd.(CDH2 WH) 127127 | Write off product (Fodder Product) | 608683 | 73348 | 074 | TP | | |

เอกสารแนบ 2-8

ตัวอย่างตารางและบันทึกการเข้าออกของรถเก็บขนของเสีย

Site Location/ หน่วยงาน BPEC

วันที่ ๗/๘ เดือน เมษายน พ.ศ. ๒๕๖๘

| เวลาเข้า | เวลาออก | หมายเลขรถ | | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | | ชั่งหนัก | ชั่งเบา | ชื่อลูกค้า | เลขที่ขนส่ง | SG |
|----------|----------|-----------|-----|--------------|--------------|-------------------|---|--------------|-------------|------------|-------------|-------|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว Container หาง | | Gross weight | Tare weight | Customer | Manifest | |
| - | 08.01 | 521 | 716 | วิจิตร | - | - | - | - | 17380 | คาน 2 | 018659 | ธส |
| 08.45 | - | 521 | 716 | วิจิตร | - | - | - | - | 17360 | - | - | มอญ |
| - | 10.12 | 716 | 716 | วิจิตร | - | - | - | - | 17370 | คาน 2 | - | คาน 2 |
| 11.06 | - | 521 | - | วิจิตร | - | - | - | - | 17320 | คาน 2 | - | คาน 2 |
| 13.30 | - | 606 | - | คาน 2 | ธส | - | - | 11360 | - | ธส | - | มอญ |
| - | 13.36 | 606 | - | คาน 2 | ธส | - | - | - | 10100 | คาน 2 | - | ธส |
| 14.25 | - | 609 | - | คาน 2 | - | - | - | - | 10110 | คาน 2 | 018640 | ธส |
| - | 14.35 | 608 | - | คาน 2 | มอญ | - | - | - | 10410 | คาน 2 | - | คาน 2 |
| 15.25 | - | 609 | - | คาน 2 | ธส | - | - | - | 10660 | คาน 2 | - | คาน 2 |
| - | 15.38 | 609 | - | คาน 2 | ธส | - | - | - | 10670 | คาน 2 | - | ธส |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Truck/Container in-out Daily Report
รายงานการนำรถและภาชนะเข้า-ออกจากหน่วยงานประจำวัน

Site Location/ หน่วยงาน BPEC

วันที่ 1 เดือน กุมภาพันธ์ พ.ศ. 2565

| เวลาเข้า Time in | เวลาออก Time out | หมายเลขรถ | | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | | น้ำหนัก | น้ำหนัก | ชื่อลูกค้า | เลขที่ขนส่ง | SC |
|---------------------|---------------------|-----------|-----|--------------|--------------|---------------|--------|--------------|-------------|------------|-------------|--------|
| | | หัว | หาง | Driver Name | Labor | หัว Container | หาง | Gross weight | Tare weight | Customer | Manifest | |
| 04:35 | 01:32 | 527 | 717 | อ.อ.อ.อ. | — | 22226 | 22160 | — | 25590 | อ.อ.อ. | — | อ.อ.อ. |
| — | 02:25 | 522 | 719 | อ.อ.อ. | — | 3061 | FB-000 | 33580 | — | อ.อ.อ. | — | อ.อ.อ. |
| 04:23 | 02:50 | 534 | 712 | อ.อ.อ. | อ.อ.อ. | 3023 | 30234 | — | 24800 | อ.อ.อ. | — | อ.อ.อ. |
| 04:27 | 04:31 | 534 | 712 | อ.อ.อ. | อ.อ.อ. | — | — | — | 2150 | อ.อ.อ. | — | อ.อ.อ. |
| 04:50 | 05:04 | 539 | 710 | อ.อ.อ. | อ.อ.อ. | 30264 | 30144 | 34840 | — | อ.อ.อ. | — | อ.อ.อ. |
| 05:39 | 05:45 | 539 | 710 | อ.อ.อ. | อ.อ.อ. | 3015 | 3012 | 23810 | — | อ.อ.อ. | — | อ.อ.อ. |
| 05:59 | 06:28 | 538 | 716 | อ.อ.อ. | อ.อ.อ. | 3015 | 3012 | 24130 | — | อ.อ.อ. | — | อ.อ.อ. |
| 07:02 | 07:25 | 520 | 716 | อ.อ.อ. | อ.อ.อ. | 30144 | 30135 | 13190 | — | อ.อ.อ. | — | อ.อ.อ. |
| 08:19 | 08:24 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | 24220 | อ.อ.อ. | — | อ.อ.อ. |
| 08:26 | 08:40 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | 10380 | อ.อ.อ. | — | อ.อ.อ. |
| 08:52 | 09:14 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | 3140 | อ.อ.อ. | — | อ.อ.อ. |
| 09:14 | 09:35 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | 11550 | อ.อ.อ. | — | อ.อ.อ. |
| 09:35 | 09:57 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | 36750 | อ.อ.อ. | — | อ.อ.อ. |
| 09:57 | 10:10 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | 2290 | อ.อ.อ. | — | อ.อ.อ. |
| 10:10 | 10:26 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | 12780 | อ.อ.อ. | — | อ.อ.อ. |
| 10:26 | 10:57 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | 23100 | อ.อ.อ. | — | อ.อ.อ. |
| 10:57 | 11:09 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | 10590 | อ.อ.อ. | — | อ.อ.อ. |
| 11:09 | 11:29 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | 2910 | อ.อ.อ. | — | อ.อ.อ. |
| 11:29 | 11:48 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | 2910 | อ.อ.อ. | — | อ.อ.อ. |
| 11:48 | 12:10 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |
| 12:10 | 12:15 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |
| 12:15 | 12:20 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |
| 12:20 | 12:39 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |
| 12:39 | 12:44 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |
| 12:44 | 12:45 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |
| 12:45 | 12:51 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |
| 12:51 | 13:02 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |
| 13:02 | 13:05 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |
| 13:05 | 13:08 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |
| 13:08 | 13:13 | 534 | 716 | อ.อ.อ. | อ.อ.อ. | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |

Truck/Container in-out Daily Report
รายงานการนำรถและภาชนะเข้า-ออกจากหน่วยงานประจำวัน

Site Location/ หน่วยงาน BPEC

วันที่ 1 เดือน กุมภาพันธ์ พ.ศ. 2565

| เวลาเข้า Time in | เวลาออก Time out | หมายเลขรถ | | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | | น้ำหนัก | น้ำหนัก | ชื่อลูกค้า | เลขที่ขนส่ง | SC |
|---------------------|---------------------|-----------|-----|--------------|--------------|---------------|-----|--------------|-------------|------------|-------------|--------|
| | | หัว | หาง | Driver Name | Labor | หัว Container | หาง | Gross weight | Tare weight | Customer | Manifest | |
| 10:00 | 10:19 | 534 | 716 | อ.อ.อ. | — | — | — | — | 16870 | อ.อ.อ. | — | อ.อ.อ. |
| 10:19 | 10:26 | 534 | 716 | อ.อ.อ. | — | — | — | — | 1920 | อ.อ.อ. | — | อ.อ.อ. |
| 10:26 | 10:29 | 534 | 716 | อ.อ.อ. | — | — | — | — | 2010 | อ.อ.อ. | — | อ.อ.อ. |
| 10:29 | 10:31 | 534 | 716 | อ.อ.อ. | — | — | — | — | 11910 | อ.อ.อ. | — | อ.อ.อ. |
| 10:31 | 10:36 | 534 | 716 | อ.อ.อ. | — | — | — | — | 13880 | อ.อ.อ. | — | อ.อ.อ. |
| 10:36 | 10:47 | 534 | 716 | อ.อ.อ. | — | — | — | — | 1910 | อ.อ.อ. | — | อ.อ.อ. |
| 10:47 | 10:50 | 534 | 716 | อ.อ.อ. | — | — | — | — | — | อ.อ.อ. | — | อ.อ.อ. |
| 10:50 | 10:57 | 534 | 716 | อ.อ.อ. | — | — | — | — | 10730 | อ.อ.อ. | — | อ.อ.อ. |
| 10:57 | 11:09 | 534 | 716 | อ.อ.อ. | — | — | — | — | 1690 | อ.อ.อ. | — | อ.อ.อ. |
| 11:09 | 11:29 | 534 | 716 | อ.อ.อ. | — | — | — | — | 25820 | อ.อ.อ. | — | อ.อ.อ. |
| 11:29 | 11:34 | 534 | 716 | อ.อ.อ. | — | — | — | — | 10420 | อ.อ.อ. | — | อ.อ.อ. |
| 11:34 | 11:36 | 534 | 716 | อ.อ.อ. | — | — | — | — | 19150 | อ.อ.อ. | — | อ.อ.อ. |
| 11:36 | 11:43 | 534 | 716 | อ.อ.อ. | — | — | — | — | 10310 | อ.อ.อ. | — | อ.อ.อ. |
| 11:43 | 11:48 | 534 | 716 | อ.อ.อ. | — | — | — | — | 31530 | อ.อ.อ. | — | อ.อ.อ. |
| 11:48 | 12:10 | 534 | 716 | อ.อ.อ. | — | — | — | — | 1610 | อ.อ.อ. | — | อ.อ.อ. |
| 12:10 | 12:15 | 534 | 716 | อ.อ.อ. | — | — | — | — | 19400 | อ.อ.อ. | — | อ.อ.อ. |
| 12:15 | 12:15 | 534 | 716 | อ.อ.อ. | — | — | — | — | 30200 | อ.อ.อ. | — | อ.อ.อ. |
| 12:15 | 12:20 | 534 | 716 | อ.อ.อ. | — | — | — | — | 10900 | อ.อ.อ. | — | อ.อ.อ. |
| 12:20 | 12:39 | 534 | 716 | อ.อ.อ. | — | — | — | — | 10310 | อ.อ.อ. | — | อ.อ.อ. |
| 12:39 | 12:44 | 534 | 716 | อ.อ.อ. | — | — | — | — | 2120 | อ.อ.อ. | — | อ.อ.อ. |
| 12:44 | 12:45 | 534 | 716 | อ.อ.อ. | — | — | — | — | 12160 | อ.อ.อ. | — | อ.อ.อ. |
| 12:45 | 12:51 | 534 | 716 | อ.อ.อ. | — | — | — | — | 10160 | อ.อ.อ. | — | อ.อ.อ. |
| 12:51 | 13:02 | 534 | 716 | อ.อ.อ. | — | — | — | — | 2040 | อ.อ.อ. | — | อ.อ.อ. |
| 13:02 | 13:05 | 534 | 716 | อ.อ.อ. | — | — | — | — | 22470 | อ.อ.อ. | — | อ.อ.อ. |
| 13:05 | 13:08 | 534 | 716 | อ.อ.อ. | — | — | — | — | 2940 | อ.อ.อ. | — | อ.อ.อ. |
| 13:08 | 13:13 | 534 | 716 | อ.อ.อ. | — | — | — | — | 8590 | อ.อ.อ. | — | อ.อ.อ. |
| 13:13 | 13:13 | 534 | 716 | อ.อ.อ. | — | — | — | — | 8960 | อ.อ.อ. | — | อ.อ.อ. |

Site Location/ หน่วยงาน BPEC

วันเสาร์ ที่ 1 เดือน กุมภาพันธ์ พ.ศ. 256

| เวลาเข้า | เวลาออก | หมายเลขรถ | | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาษา | | ชั่งหนัก | ชั่งเบา | ชื่อลูกค้า | เลขที่ขนส่ง | S |
|----------|----------|-----------|--------|--------------|--------------|-------------|---------------|--------------|-------------|------------|-------------|----|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว | Container ทาง | Gross weight | Tare weight | Customer | Manifest | |
| 13.17 | - | 539 | 708 | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 13.32 | 12.30 | 1129 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 13.32 | - | 521 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 13.32 | 13.32 | 52-4128 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 13.41 | - | 50-6272 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 13.50 | - | 520 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 14.02 | 14.02 | 539 | 708 | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 14.06 | 14.06 | 50-6272 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 14.08 | - | 52-6201 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 14.37 | 14.37 | 809 | TR-003 | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 14.39 | 14.39 | 521 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 15.04 | - | 521 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 15.14 | - | 74-3678 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 15.24 | - | 71-2191 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 15.36 | 15.36 | 74-3678 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 15.40 | 15.40 | 52-6201 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 15.43 | - | 202917 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 15.52 | 15.52 | 202917 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 16.10 | - | 67-5113 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 16.45 | - | 523 | 710 | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 16.58 | 15.00 | 71-5301 | 492 | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 17.14 | 16.58 | 71-2191 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 17.30 | 17.14 | 523 | 710 | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 18.50 | 17.30 | 67-5113 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 19.23 | 18.50 | 521 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 19.25 | 19.23 | 521 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 20.19 | 19.25 | 521 | - | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 20.25 | 20.19 | 529 | 721 | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |
| 21.01 | 20.25 | 529 | 721 | ชินพร | ชี | 22186 | 22275 | 31910 | - | LTS | 00534 | ชี |

Site Location/ หน่วยงาน BPEC

วัน ~~เสาร์~~⁶ ที่ 1 เดือน ~~พฤษภาคม~~⁶ พ.ศ. 2568

[illegible]

Site Location/ หน่วยงาน BPEC

1

วันที่ 1 เดือน สิงหาคม พ.ศ. 2568

| เวลาเข้า | เวลาออก | หมายเลขรถ | | พนักงานขับรถ | พนักงานดีตรก | หมายเลขภาชนะ | | น้ำหนัก | น้ำหนัก | ชื่อลูกค้า | เลขที่ขนส่ง | SG |
|----------|----------|-----------|--------|--------------|--------------|--------------|---------------|--------------|-------------|------------|-------------|--------|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว | Container หาง | Gross weight | Tare weight | Customer | Manifest | |
| 00.46 | — | 544 | 713 | อริศพร | — | 2202 | 2224 | 30490 | — | อริศพร | — | 1/กม |
| — | 00.58 | 527 | 995204 | อริศพร | — | 22260 | 22160 | 41970 | — | อริศพร | — | 1/กม |
| — | 01.10 | 52-6201 | — | อริศพร | — | — | — | — | 9010 | อริศพร | — | 1/กม |
| — | 01.58 | 544 | 713 | อริศพร | — | 2202 | 2224 | 37280 | — | อริศพร | — | 1/กม |
| — | 0218 | 527 | — | อริศพร | — | 22144 | — | — | 14040 | อริศพร | — | 1/กม |
| — | 0228 | 520 | — | อริศพร | — | 22277 | — | — | 14270 | SSL | 002349 | 1/กม |
| 0310 | — | 5A-8880 | — | อริศพร | — | — | — | — | — | อริศพร | — | 1/กม |
| — | 0438 | 522 | 719 | อริศพร | อริศพร | 30228 | 30158 | — | 22820 | อริศพร | 000091 | 1/กม |
| — | 0443 | 54-8888 | — | อริศพร | — | — | — | — | 6610 | อริศพร | — | 1/กม |
| 0405 | — | 523 | — | อริศพร | — | 22267 | — | 15110 | — | อริศพร | 400009 | 1/กม |
| 0501 | — | 609 | — | อริศพร | อริศพร | — | — | 14010 | — | อริศพร | — | 1/กม |
| — | 0503 | 538 | 7 | อริศพร | อริศพร | 30264 | 3061 | — | 25960 | URC | 002263 | 1/กม |
| — | 0511 | 521 | 716 | อริศพร | — | — | — | — | 17250 | อริศพร | 001152 | 1/กม |
| 0514 | — | 520 | — | อริศพร | อริศพร | 22277 | — | 15280 | — | SSL | 002349 | 1/กม |
| — | 0519 | 609 | — | อริศพร | — | — | — | — | 10690 | อริศพร | — | 1/กม |
| — | 0523 | 534 | 710 | อริศพร | — | FB-002 | FB-018 | 35800 | — | อริศพร | — | 1/กม |
| 0537 | — | 539 | 708 | อริศพร | อริศพร | 3067 | 22275 | 35630 | — | อริศพร | — | 1/กม |
| 0550 | — | 678 | — | อริศพร | อริศพร | — | — | 12690 | — | อริศพร | — | 1/กม |
| 0558 | — | 5CR-14 | — | อริศพร | — | — | — | — | — | อริศพร | — | 1/กม |
| — | 0611 | 618 | — | อริศพร | อริศพร | — | — | — | 11330 | อริศพร | — | 1/กม |
| — | 0633 | 539 | 708 | อริศพร | อริศพร | 22273 | 3105 | — | 22730 | อริศพร | — | 1/กม |
| — | 0655 | 5CR-14 | — | อริศพร | — | FB-005 | FB-094 | — | 14500 | PMAPR | 002391 | 1/กม |
| 0741 | — | 606 | — | อริศพร | อริศพร | — | — | 19030 | — | TOYOTA | — | อริศพร |
| 0748 | — | 608 | — | อริศพร | อริศพร | — | — | 14740 | — | อริศพร | — | อริศพร |
| — | 0752 | 520 | — | อริศพร | — | 22264 | — | — | 14260 | อริศพร | 002264 | อริศพร |
| — | 0754 | 606 | — | อริศพร | อริศพร | — | — | — | 10380 | อริศพร | — | อริศพร |
| — | 0810 | 608 | — | อริศพร | อริศพร | — | — | — | 10410 | อริศพร | — | อริศพร |
| 0841 | — | 22267 | — | อริศพร | — | — | — | — | — | อริศพร | — | อริศพร |
| 0903 | — | 609 | — | อริศพร | อริศพร | — | — | 3250 | — | อริศพร | — | อริศพร |
| — | 0905 | 523 | — | อริศพร | — | — | — | 14760 | — | อริศพร | — | อริศพร |
| — | — | — | — | อริศพร | — | 3116 | — | — | 14720 | อริศพร | 001951 | อริศพร |

Site Location/ หน่วยงาน BPEC

2

วันที่ 1 เดือน สิงหาคม พ.ศ. 2568

| เวลาเข้า | เวลาออก | หมายเลขรถ | | พนักงานขับรถ | พนักงานดีตรก | หมายเลขภาชนะ | | น้ำหนัก | น้ำหนัก | ชื่อลูกค้า | เลขที่ขนส่ง | SG |
|----------|----------|-----------|---------|--------------|--------------|--------------|---------------|--------------|-------------|------------|-------------|--------|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว | Container หาง | Gross weight | Tare weight | Customer | Manifest | |
| 09.09 | — | 1057523 | — | อริศพร | — | — | — | 3070 | — | อริศพร | — | อริศพร |
| — | 09.13 | 22267 | — | อริศพร | — | — | — | — | — | อริศพร | — | อริศพร |
| — | 09.18 | 609 | — | อริศพร | อริศพร | — | — | — | 2280 | อริศพร | — | อริศพร |
| — | 09.28 | 1057523 | — | อริศพร | — | — | — | — | 10660 | อริศพร | — | อริศพร |
| 09.30 | — | 81-3120 | — | อริศพร | — | — | — | — | 2160 | อริศพร | — | อริศพร |
| 09.38 | — | 522 | 719 | อริศพร | อริศพร | 30144 | 30213 | 13120 | — | อริศพร | — | อริศพร |
| — | 10.06 | 81-3120 | — | อริศพร | — | — | — | 29040 | — | อริศพร | — | อริศพร |
| 10.10 | — | 30267 | — | อริศพร | — | — | — | — | 10590 | อริศพร | — | อริศพร |
| 10.16 | — | 74-9998 | 750085 | อริศพร | — | — | — | 2900 | — | อริศพร | — | อริศพร |
| 1025 | — | 115-1574 | — | อริศพร | — | — | — | 46060 | — | อริศพร | — | อริศพร |
| — | 1027 | 30267 | — | อริศพร | — | — | — | — | — | อริศพร | — | อริศพร |
| 1030 | — | 30267 | — | อริศพร | — | — | — | — | 2020 | KKR | — | อริศพร |
| — | 10.47 | 30267 | — | อริศพร | — | — | — | — | 1930 | PTS | 40032 | อริศพร |
| 10.50 | — | 521 | 716 | อริศพร | — | — | — | 3040 | — | PTS | 40028 | อริศพร |
| 1100 | — | 115-1574 | — | อริศพร | อริศพร | — | — | — | 1990 | PTS | 10028 | อริศพร |
| — | 11.11 | 522 | 719 | อริศพร | — | — | — | — | 14210 | อริศพร | — | อริศพร |
| — | 11.12 | 521 | — | อริศพร | — | 30144 | 30213 | 1750 | — | อริศพร | — | อริศพร |
| — | 11.14 | 22267 | — | อริศพร | — | 30149 | — | — | 23270 | อริศพร | — | อริศพร |
| 11.17 | — | 5CR-05 | — | อริศพร | — | — | — | — | 15200 | อริศพร | — | อริศพร |
| 11.20 | — | 5CR-14 | — | อริศพร | อริศพร | 30135 | — | 14960 | — | อริศพร | — | อริศพร |
| 11.22 | — | 608 | — | อริศพร | อริศพร | FB-005 | — | 23820 | — | อริศพร | — | อริศพร |
| 11.23 | — | 52-9128 | — | อริศพร | อริศพร | — | — | 14270 | — | อริศพร | — | อริศพร |
| 11.27 | — | 621 | — | อริศพร | — | — | — | 8320 | — | อริศพร | — | อริศพร |
| — | 1130 | 608 | — | อริศพร | อริศพร | — | — | 19040 | — | อริศพร | — | อริศพร |
| — | 1135 | 5CR-05 | — | อริศพร | อริศพร | — | — | — | 10400 | อริศพร | — | อริศพร |
| — | 1138 | 115-1574 | — | อริศพร | — | 30135 | — | — | 14510 | อริศพร | — | อริศพร |
| — | 1140 | 621 | — | อริศพร | — | — | — | 2930 | — | KKR | — | อริศพร |
| 1142 | — | 618 | — | อริศพร | อริศพร | — | — | — | 14240 | อริศพร | — | อริศพร |
| 11.50 | — | 5CR-22 | 73-9777 | อริศพร | อริศพร | — | — | 13220 | — | อริศพร | — | อริศพร |
| 11.56 | — | 5CR-16 | — | อริศพร | — | 3025 | 30256 | 30000 | — | อริศพร | — | อริศพร |
| — | — | — | — | อริศพร | — | 3048 | — | 15940 | — | อริศพร | — | อริศพร |

Site Location/ หน่วยงาน BPEC

3

วันที่ 1 เดือน สิงหาคม พ.ศ. 2568

| เวลาเข้า | เวลาออก | หมายเลขรถ | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | น้ำหนัก | น้ำหนัก | ชื่อลูกค้า | เลขที่ขนส่ง | SG | | |
|----------|----------|-----------|--------------|--------------|--------------|---------------|---------------------------------|--------------|-------------|----------|----------|-------|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว Container | หาง | Gross weight | Tare weight | Customer | Manifest | |
| - | 12.01 | 52-9128 | - | สุทธิ | - | - | - | 5980 | 1140 | ลูกค้า 2 | 001259 | สุทธิ |
| 12.06 | - | 521 | - | ศิริพร | รถบรรทุก | - | - | - | 10980 | ลูกค้า 2 | 002204 | สุทธิ |
| - | 12.13 | SCR 16 | - | สุทธิ | - | - | - | - | - | ลูกค้า 2 | 002204 | สุทธิ |
| 12.15 | - | 608 | - | สุทธิ | รถบรรทุก | - | - | 11560 | - | ลูกค้า 2 | 002204 | สุทธิ |
| 12.16 | - | LV 120 | - | สุทธิ | รถบรรทุก | - | - | 3380 | - | ลูกค้า 2 | 002204 | สุทธิ |
| 12.20 | - | 538 | ท12 | สุทธิ | รถบรรทุก | 30231 | 30225 | 32300 | - | ลูกค้า 2 | 002204 | สุทธิ |
| - | 12.24 | 521 | - | ศิริพร | - | 301A1 | - | - | 11670 | ลูกค้า 2 | 002204 | สุทธิ |
| - | 12.26 | 618 | - | สุทธิ | รถบรรทุก | - | - | - | 10150 | ลูกค้า 2 | 002204 | สุทธิ |
| - | 12.29 | 538 | ท12 | สุทธิ | - | 30231 | 30205 | 32310 | - | ลูกค้า 2 | 002204 | สุทธิ |
| 12.32 | - | 520 | - | สุทธิ | - | 22267 | - | 24530 | - | ลูกค้า 2 | 002204 | สุทธิ |
| 12.35 | - | 523 | - | สุทธิ | - | 22212 | - | 16480 | - | ลูกค้า 2 | 002204 | สุทธิ |
| - | 12.42 | AV140 | - | สุทธิ | - | - | - | - | 2970 | ลูกค้า 2 | 002204 | สุทธิ |
| - | 12.46 | 608 | - | สุทธิ | - | - | - | 10510 | - | ลูกค้า 2 | 002204 | สุทธิ |
| - | 12.52 | 74-0998 | 450085 | สุทธิ | - | KMW | - | 170140 | - | ลูกค้า 2 | 002204 | สุทธิ |
| - | 12.55 | 520 | - | สุทธิ | - | - | - | 11310 | - | ลูกค้า 2 | 002204 | สุทธิ |
| 12.57 | - | 606 | - | สุทธิ | รถบรรทุก | - | - | 13980 | - | ลูกค้า 2 | 002204 | สุทธิ |
| - | 12.59 | SCR 22 | 73-0979 | สุทธิ | - | 30256 | 30225 | - | 24170 | ลูกค้า 2 | 002204 | สุทธิ |
| 13.03 | - | 50-9562 | - | สุทธิ | - | - | - | 11400 | - | ลูกค้า 2 | 40012 | สุทธิ |
| 13.05 | - | 534 | 410 | สุทธิ | - | FB 002 | FB 018 | - | 24110 | ลูกค้า 2 | 002204 | สุทธิ |
| - | 13.07 | 606 | - | สุทธิ | รถบรรทุก | - | - | 10350 | - | ลูกค้า 2 | 002204 | สุทธิ |
| 13.10 | - | 521 | - | สุทธิ | - | - | - | 11120 | - | ลูกค้า 2 | 002204 | สุทธิ |
| - | 13.20 | SCR 14 | - | สุทธิ | - | FB 005 | 15000, 1643, 626, 565, 571, 021 | 16240 | - | ลูกค้า 2 | 002204 | สุทธิ |
| - | 13.25 | 534 | - | สุทธิ | - | FB 012 | - | 14840 | - | ลูกค้า 2 | 002204 | สุทธิ |
| 13.28 | - | 609 | - | สุทธิ | รถบรรทุก | - | - | 13370 | - | ลูกค้า 2 | 002204 | สุทธิ |
| 13.46 | - | 606 | - | สุทธิ | รถบรรทุก | - | - | 12050 | - | ลูกค้า 2 | 002204 | สุทธิ |
| - | 13.52 | 50-9562 | - | สุทธิ | - | - | - | 8720 | - | ลูกค้า 2 | 40012 | สุทธิ |
| 13.56 | - | 50-9562 | - | สุทธิ | - | - | - | 2770 | - | ลูกค้า 2 | 40012 | สุทธิ |
| - | 14.00 | 609 | - | สุทธิ | รถบรรทุก | - | - | 10630 | - | ลูกค้า 2 | 40012 | สุทธิ |
| 14.08 | - | 50A-10 | - | สุทธิ | - | 30220 | - | 18790 | - | ลูกค้า 2 | 606598 | สุทธิ |
| - | 14.13 | 50-9562 | - | สุทธิ | - | - | - | 2310 | - | ลูกค้า 2 | 40012 | สุทธิ |

Site Location/ หน่วยงาน BPEC

4

วันที่ 1 เดือน สิงหาคม พ.ศ. 2568

| เวลาเข้า | เวลาออก | หมายเลขรถ | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | | น้ำหนัก | ชั่งเมา | ชื่อลูกค้า | เลขที่ขนส่ง | SG | |
|----------|----------|-----------|--------------|--------------|--------------|---------------|---------|--------------|-------------|-------------|----------|-----------|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว Container | หาง | Gross weight | Tare weight | Customer | Manifest | |
| 14.15 | - | 50-6272 | - | นิกร | - | - | - | 7510 | - | ททท | 40029 | ททท |
| - | 14.25 | SCR-10 | - | อานนท์ | รถบรรทุก | 30220 | - | - | 14450 | ททท 2 | - | ททท |
| - | 14.30 | 606 | - | อานนท์ | รถบรรทุก | - | - | - | 10340 | ททท 2 | - | ททท |
| - | 14.40 | 50-6272 | - | นิกร | - | - | - | - | 5620 | ททท | 40029 | ททท |
| 14.43 | - | 52-6201 | - | เพชร | - | - | - | 13640 | - | ททท 02 | 40035 | ททท |
| 14.50 | - | LV129 | - | อ้วน | อ้วน | - | - | 2310 | - | FCP | 00238 | ททท |
| - | 15.08 | LV129 | - | อ้วน | อ้วน | - | - | - | 2160 | ททท 2 | 002324 | ททท |
| 15.25 | - | 20-0122 | - | ธีระพงษ์ | - | - | - | 3040 | - | อัครวิชัย | 40010 | ททท |
| 15.35 | - | 71-2191 | - | ฐาปนพงศ์ | - | - | - | 20500 | - | 1988 | - | ททท |
| - | 15.40 | 20-0122 | - | ธีระพงษ์ | - | - | - | - | 2700 | อัครวิชัย | 40010 | อัคร |
| 15.43 | - | 618 | - | อัครวิชัย | อัครวิชัย | - | - | 12420 | - | MG | - | อัครวิชัย |
| - | 16.00 | 52-6201 | - | เพชร | - | - | - | - | 9130 | ททท 02 | 40035 | ททท |
| - | 16.05 | 618 | - | อัครวิชัย | อัครวิชัย | - | - | - | 10110 | LTS | - | ททท |
| 16.38 | - | 20-0122 | - | เพชร | - | - | - | 2760 | - | อัครวิชัย | 40014 | อัคร |
| - | 16.49 | 20-0122 | - | เพชร | - | - | - | - | 2230 | อัครวิชัย | 40019 | อัคร |
| - | 16.50 | 71-2191 | - | ฐาปนพงศ์ | - | - | - | - | 12490 | เดอะอี | - | อัคร |
| 17.05 | - | 67-5713 | - | นิกร | - | - | - | 13820 | - | ททท | 40020 | อัคร |
| 17.32 | - | 531 | - | เอกธวัช | อานนท์ | FB-012 | - | 16290 | - | พริตติยา | 002324 | อัคร |
| - | 18.43 | 67-5713 | - | อัคร | - | - | - | - | 8180 | อัครวิชัย | 40020 | อัคร |
| 18.50 | - | 86-9980 | - | อัครวิชัย | - | - | - | 18580 | - | Miss Night | 40015 | อัครวิชัย |
| 19.00 | - | SCR 30 | TR 073 | อัครวิชัย | - | SL 015 | 3071 | 43520 | - | .S2 | 002324 | อัครวิชัย |
| - | 19.41 | SCR 30 | TR 023 | อัครวิชัย | - | SL 015 | 3071 | - | 33300 | อัคร | 40015 | อัครวิชัย |
| - | 20.05 | 86-9980 | - | อัครวิชัย | - | - | - | - | 11850 | Miss Night | 40015 | อัครวิชัย |
| 20.07 | - | 51-1080 | - | อัคร | - | - | - | 15580 | - | Thai Enrich | - | อัครวิชัย |
| - | 20.14 | 534 | - | อัคร | - | 22267 | - | - | 14440 | ททท 2 | 002324 | อัคร |
| 20.15 | - | 534 | - | เพชร | - | - | - | - | 11670 | ททท 2 | 002324 | อัคร |
| - | 20.57 | 534 | - | อัคร | - | FB-018 | - | - | 13800 | ททท 2 | 002324 | อัคร |
| - | 21.20 | 51-1080 | - | อัคร | - | - | - | - | 10240 | Thai Enrich | 40016 | อัครวิชัย |
| 21.21 | - | 531 | - | อัคร | - | - | - | - | 11160 | ททท 2 | 002324 | อัครวิชัย |
| 21.33 | - | 531 | ท05 | อัคร | - | 22195 | 22119 | - | 25100 | อัคร | 002324 | อัครวิชัย |

Site Location/ หน่วยงาน BPEC

5

วันจันทร์ ที่ 1 เดือน มีนาคม พ.ศ. 2568

| เวลาเข้า | เวลาออก | หมายเลขรถ | | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | | ชั่งหนัก | ชั่งเบา | ชื่อลูกค้า | เลขที่ขนส่ง | SG |
|----------|----------|-----------|--------|--------------|--------------|-------------------|-------|--------------|-------------|------------|-------------|-------|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว Container หาง | | Gross weight | Tare weight | Customer | Manifest | |
| - | 21.18 | 531 | - | ไอกรร | - | FB 002 | - | - | 10850 | กฟ 2 | 008828 | ไอกรร |
| 22.20 | - | 531 | - | ไอกรร | - | - | - | - | 11150 | กฟ 2 | 008828 | ไอกรร |
| - | 22.29 | 511 | ทิส | ศรีพร | ศรีพร | 22219 | 22168 | 17160 | - | กฟ 2 | 008828 | ไอกรร |
| 22.31 | - | 808 | TR 003 | ศรีพร | - | 30221 | 30223 | 19300 | - | STS | 008828 | ไอกรร |
| - | 23.16 | 808 | TR 003 | ศรีพร | - | 30221 | 3067 | 29930 | - | กฟ 2 | 008828 | ไอกรร |
| 23.22 | - | 530 | ทิส | ศรีพร | ทิสพร | 2221 | 2211 | 30850 | - | กฟ 2 | 008828 | ไอกรร |

Site Location/ หน่วยงาน BPEC

1

วันจันทร์ ที่ 1 เดือน มีนาคม พ.ศ. 2568

| เวลาเข้า | เวลาออก | หมายเลขรถ | | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | | ชั่งหนัก | ชั่งเบา | ชื่อลูกค้า | เลขที่ขนส่ง | SG |
|----------|----------|-----------|-----|--------------|--------------|-------------------|---------------------|--------------|-------------|------------|-------------|-------|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว Container หาง | | Gross weight | Tare weight | Customer | Manifest | |
| 00.24 | - | 534 | 712 | ศรีพร | - | 22160 | 22116 | - | 27130 | กฟ 2 | 008828 | ไอกรร |
| - | 02.13 | 534 | 712 | ไอกรร | - | 22116 | 22160 | - | 27130 | กฟ 2 | 008828 | ไอกรร |
| - | 02.18 | 520 | 702 | ไอกรร | - | - | 2250 | - | 21980 | กฟ 2 | 008828 | ไอกรร |
| - | 02.38 | 521 | 716 | ไอกรร | ทิสพร | 30251 | 22120 | - | 23710 | กฟ 2 | 008828 | ไอกรร |
| 02.49 | - | 523 | 710 | ศรีพร | - | 22171 | - | 26880 | - | กฟ 2 | - | ไอกรร |
| - | 03.09 | 523 | 710 | ศรีพร | ไอกรร | 30210 | 22171 | 38320 | - | กฟ 2 | 008828 | ไอกรร |
| 03.23 | - | 589 | - | ทิสพร | - | 2261 | - | - | 13910 | กฟ 2 | 008828 | ไอกรร |
| - | 03.25 | 539 | - | ทิสพร | - | 2261 | - | - | 13910 | กฟ 2 | 008828 | ไอกรร |
| 03.31 | - | 521 | 716 | ไอกรร | ทิสพร | - | - | - | 17250 | กฟ 2 | - | ไอกรร |
| - | 03.41 | 521 | - | ไอกรร | ทิสพร | 22230 | - | - | 14120 | กฟ 2 | 008828 | ไอกรร |
| - | 03.50 | 522 | - | ไอกรร | - | - | - | - | 14280 | กฟ 2 | - | ไอกรร |
| 04.00 | - | 534 | - | ไอกรร | - | 30815 | - | 17260 | - | กฟ 2 | 008828 | ไอกรร |
| - | 04.05 | LV-139 | - | ไอกรร | ทิสพร | - | - | 3430 | - | กฟ 2 | 008828 | ไอกรร |
| 04.20 | - | 609 | - | ไอกรร | ทิสพร | - | - | 12250 | - | กฟ 2 | - | ไอกรร |
| - | 04.23 | 534 | - | ไอกรร | - | 30215 | - | - | 18740 | กฟ 2 | 008828 | ไอกรร |
| - | 04.28 | 609 | - | ไอกรร | ทิสพร | - | - | - | 10640 | กฟ 2 | - | ไอกรร |
| 04.35 | - | 618 | - | ไอกรร | ทิสพร | - | - | 14240 | - | กฟ 2 | - | ไอกรร |
| 04.40 | - | 521 | - | ไอกรร | ทิสพร | - | - | - | 11190 | กฟ 2 | 008828 | ไอกรร |
| - | 04.49 | 618 | - | ไอกรร | ทิสพร | - | - | - | 10170 | กฟ 2 | - | ไอกรร |
| 04.58 | - | 521 | 716 | ไอกรร | - | 3061 | - | - | 21800 | กฟ 2 | 008828 | ไอกรร |
| 05.05 | - | 522 | 719 | ไอกรร | - | - | - | - | 21440 | กฟ 2 | - | ไอกรร |
| 05.22 | - | 534 | 712 | ไอกรร | - | 30251 | 30165 | - | 24790 | กฟ 2 | 008828 | ไอกรร |
| - | 05.34 | 522 | 719 | ไอกรร | ทิสพร | FB-015 | FB-012 | - | 22560 | กฟ 2 | 008828 | ไอกรร |
| 06.10 | 539 | 539 | - | ไอกรร | ทิสพร | 22109 | - | 14910 | - | กฟ 2 | 40615 | ไอกรร |
| - | 06.22 | 531 | 712 | ไอกรร | - | 30250 | 30165 | - | 24790 | กฟ 2 | 008828 | ไอกรร |
| - | 06.26 | 538 | - | ไอกรร | ทิสพร | FB-004 | - | - | 16540 | กฟ 2 | 008828 | ไอกรร |
| - | - | - | - | - | - | 1560240-625-407 | 288-476-420-528-596 | - | - | - | - | - |
| - | 06.30 | 539 | - | ไอกรร | ทิสพร | 22109 | - | - | 14050 | กฟ 2 | 40615 | ไอกรร |
| 08.17 | - | 608 | - | ไอกรร | ทิสพร | - | - | 14270 | - | กฟ 2 | - | ไอกรร |
| - | 08.39 | 608 | - | ไอกรร | ทิสพร | - | - | - | 10490 | กฟ 2 | - | ไอกรร |

Truck/Container in-out Daily Report
รายงานการนำรถและภาชนะเข้า-ออกจากหน่วยงานประจำวัน

Site Location/ หน่วยงาน BPEC

วันที่ ๑๓ เดือน ๑๒ พ.ศ. ๒๕๖๘

| เวลาเข้า | เวลาออก | หมายเลขรถ | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | น้ำหนัก | น้ำหนักเบ | ชื่อลูกค้า | เลขที่ขนส่ง | SG |
|----------|----------|-----------|--------------|--------------|--------------|-------------------|--------------|-------------|-------------|----------|
| Time in | Time out | หัว | ทาง | Driver Name | Labor | หัว Container ทาง | Gross weight | Tare weight | Customer | Manifest |
| 09.05 | - | SC10 | - | นายอนุช | - | 30264 | - | 14900 | ลูกค้า 2 | - |
| - | 09.15 | SR10 | - | นายอนุช | - | 30264 | - | 14900 | ลูกค้า 2 | - |
| 09.34 | - | MA-210 | - | นายอนุช | - | - | 10980 | - | ลูกค้า 2 | - |
| 09.50 | - | 84-3120 | - | นายอนุช | - | - | 14240 | - | ลูกค้า 2 | - |
| 09.52 | - | 606 | - | นายอนุช | - | - | 14100 | - | ลูกค้า 2 | - |
| - | 09.57 | 606 | - | นายอนุช | - | - | - | 10320 | ลูกค้า 2 | - |
| - | 10.00 | 74-4210 | - | นายอนุช | - | - | - | 8970 | ลูกค้า 2 | - |
| 1020 | - | 535 | - | นายอนุช | - | FB-001 | 16130 | - | ลูกค้า 2 | - |
| - | 1045 | 84-3120 | - | นายอนุช | - | - | - | 10580 | ลูกค้า 2 | - |
| - | 1105 | 535 | - | นายอนุช | - | FB-001 | - | 16060 | ลูกค้า 2 | - |
| 11.10 | - | 618 | - | นายอนุช | - | - | 13240 | - | ลูกค้า 2 | - |
| 11.12 | - | 50-9562 | - | นายอนุช | - | - | 13660 | - | ลูกค้า 2 | - |
| 11.17 | - | 698 | - | นายอนุช | - | - | 12770 | - | ลูกค้า 2 | - |
| 11.20 | - | 539 | - | นายอนุช | - | 22275 | 21650 | - | ลูกค้า 2 | - |
| - | 1122 | 608 | - | นายอนุช | - | - | - | 10460 | ลูกค้า 2 | - |
| 11.29 | - | 606 | - | นายอนุช | - | - | - | 12570 | ลูกค้า 2 | - |
| - | 11.31 | 618 | - | นายอนุช | - | - | - | 10110 | ลูกค้า 2 | - |
| 12.03 | - | LV139 | - | นายอนุช | - | - | - | 3900 | ลูกค้า 2 | - |
| - | 12.05 | 539 | - | นายอนุช | - | 22275 | - | 11140 | ลูกค้า 2 | - |
| - | 12.13 | 606 | - | นายอนุช | - | - | - | 10330 | ลูกค้า 2 | - |
| - | 12.24 | 50-9562 | - | นายอนุช | - | - | - | 9020 | ลูกค้า 2 | - |
| 1234 | - | 621 | - | นายอนุช | - | - | 19310 | - | ลูกค้า 2 | - |
| - | 1240 | LV139 | - | นายอนุช | - | - | - | 3210 | ลูกค้า 2 | - |
| 1249 | - | 609 | - | นายอนุช | - | - | 14770 | - | ลูกค้า 2 | - |
| - | 1258 | 609 | - | นายอนุช | - | - | - | 10620 | ลูกค้า 2 | - |
| 13.04 | - | 534 | 712 | นายอนุช | - | 30251 | 30165 | 37980 | AFB 003903 | ลูกค้า 2 |
| 13.08 | - | 521 | 716 | นายอนุช | - | 3061 | 30215 | 36780 | AFB 003902 | ลูกค้า 2 |
| 13.12 | - | 73-1359 | - | นายอนุช | - | - | - | 19400 | ลูกค้า 2 | - |
| - | 13.21 | 621 | - | นายอนุช | - | - | - | 14230 | ลูกค้า 2 | - |
| 13.35 | - | 52-9128 | - | นายอนุช | - | - | - | 8410 | ลูกค้า 2 | - |

Truck/Container in-out Daily Report
รายงานการนำรถและภาชนะเข้า-ออกจากหน่วยงานประจำวัน

Site Location/ หน่วยงาน BPEC

วันที่ ๑๓ เดือน ๑๒ พ.ศ. ๒๕๖๘

| เวลาเข้า | เวลาออก | หมายเลขรถ | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | น้ำหนัก | น้ำหนักเบ | ชื่อลูกค้า | เลขที่ขนส่ง | SG |
|----------|----------|-----------|--------------|--------------|--------------|-------------------|--------------|-------------|-------------|----------|
| Time in | Time out | หัว | ทาง | Driver Name | Labor | หัว Container ทาง | Gross weight | Tare weight | Customer | Manifest |
| 13.50 | - | 608 | - | นายอนุช | - | - | 13130 | - | ลูกค้า 2 | - |
| 13.51 | - | SC10 | - | นายอนุช | - | 30264 | 16170 | - | ลูกค้า 2 | - |
| 13.54 | - | LV136 | - | นายอนุช | - | - | 2100 | - | ลูกค้า 2 | - |
| 13.58 | - | SR05 | 61-5390 | นายอนุช | - | 30902 | 30143 | 32980 | ลูกค้า 2 | - |
| - | 14.02 | 73-1359 | - | นายอนุช | - | - | - | 9100 | ลูกค้า 2 | - |
| - | 14.04 | 521 | 716 | นายอนุช | - | 30215 | 3061 | 21980 | ลูกค้า 2 | - |
| - | 14.10 | SR10 | - | นายอนุช | - | - | - | 11530 | ลูกค้า 2 | - |
| - | 14.11 | 52-9128 | - | นายอนุช | - | - | - | 5930 | ลูกค้า 2 | - |
| - | 14.15 | 608 | - | นายอนุช | - | - | - | 10560 | ลูกค้า 2 | - |
| - | 1422 | LV136 | - | นายอนุช | - | - | - | 2050 | ลูกค้า 2 | - |
| 1440 | - | LV1574 | - | นายอนุช | - | - | - | 2010 | ลูกค้า 2 | - |
| - | 1442 | SR05 | 61-5392 | นายอนุช | - | - | - | 17880 | ลูกค้า 2 | - |
| 1452 | - | 51-8998 | - | นายอนุช | - | - | 12550 | - | ลูกค้า 2 | - |
| 1455 | - | 521 | 716 | นายอนุช | - | - | - | 17210 | ลูกค้า 2 | - |
| 15.10 | - | SR-22 | 73-9779 | นายอนุช | - | VT-002 | 4030 | 45410 | ลูกค้า 2 | - |
| - | 1525 | 581574 | - | นายอนุช | - | - | 2360 | - | ลูกค้า 2 | - |
| - | 1527 | 51-8998 | - | นายอนุช | - | - | - | 9370 | ลูกค้า 2 | - |
| 1529 | - | 30251 | 712 | นายอนุช | - | - | 2720 | - | ลูกค้า 2 | - |
| - | 1533 | 534 | - | นายอนุช | - | - | - | 11486 | ลูกค้า 2 | - |
| - | 1546 | 30251 | 712 | นายอนุช | - | - | - | 2090 | ลูกค้า 2 | - |
| 1546 | - | 54-8985 | - | นายอนุช | - | - | 9790 | - | ลูกค้า 2 | - |
| 1556 | - | 524 | - | นายอนุช | - | 30158 | 19290 | - | ลูกค้า 2 | - |
| 16.15 | - | 531 | - | นายอนุช | - | - | - | 14110 | ลูกค้า 2 | - |
| - | 1629 | 527 | - | นายอนุช | - | 30158 | - | - | ลูกค้า 2 | - |
| - | 1643 | 54-8985 | - | นายอนุช | - | - | - | 16130 | ลูกค้า 2 | - |
| - | 1648 | 534 | - | นายอนุช | - | - | - | 6600 | ลูกค้า 2 | - |
| - | 17.13 | SR-22 | 73-9779 | นายอนุช | - | VT002 | 4030 | 11480 | ลูกค้า 2 | - |
| 17.25 | - | 522 | 719 | นายอนุช | - | FB-012 | FB-015 | 24250 | ลูกค้า 2 | - |
| 17.33 | - | 534 | - | นายอนุช | - | 22199 | - | 21350 | ลูกค้า 2 | - |
| 17.34 | - | 866428 | - | นายอนุช | - | - | - | 13890 | ลูกค้า 2 | - |
| - | - | - | - | นายอนุช | - | - | 15310 | - | ลูกค้า 2 | - |

Site Location/ หน่วยงาน BPEC

วันอังคาร ที่ 1 เดือน พฤษภาคม พ.ศ. 2564

| เวลาเข้า | เวลาออก | หมายเลขรถ | | พนักงานขับรถ | พนักงานติดตาม | หมายเลขภาชนะ | | ชั่งหนัก | ชั่งเบา | ชื่อลูกค้า | เลขที่ขนส่ง | SG |
|----------|----------|-----------|---------|--------------|---------------|-------------------|-------------|--------------|-------------|------------|-------------|----|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว Container หาง | | Gross weight | Tare weight | Customer | Manifest | |
| 17.51 | - | 539 | - | สุวิทย์ | - | FB- | 1500255-253 | - | 17080 | บอริ | 003930 | บม |
| - | - | - | - | - | -188- | 355-646- | 362-630-351 | - | - | - | - | - |
| 18.39 | - | 50209 | 60-3737 | อ. หนึ่ง | - | LB-0081 | LB-0072 | 19230 | - | บอริ | 007874 | บม |
| - | 18.42 | 86-6428 | - | สาธิต | - | - | - | - | 10490 | บอริ | - | บม |
| - | 19.00 | 538 | 716 | วิไล | - | 1625 | 2219 | 40640 | - | บอริ | 004107 | บม |
| - | 19.05 | 522 | 719 | วิไล | - | 22107 | 2220 | 38210 | - | บอริ | 004105 | บม |
| 19.20 | - | 527 | 718 | วิไล | - | 2224 | 22263 | 27040 | - | บอริ | 007872 | บม |
| - | 19.32 | 521-09 | 60-3737 | อ. หนึ่ง | - | LB-0081 | LB-0072 | - | 17910 | บอริ | 007874 | บม |
| - | 20.38 | 534 | - | วิไล | - | 30202 | - | - | 14860 | บอริ | 003933 | บม |
| - | 20.40 | 527 | 718 | วิไล | - | 2224 | 22263 | 36510 | - | บอริ | 004510 | บม |
| 21.00 | - | 530 | 717 | วิไล | - | 3056 | 3089 | 33790 | - | บอริ | 007857 | บม |
| 21.22 | - | 534 | - | วิไล | - | - | - | - | 11660 | บอริ | 003933 | บม |
| - | 21.24 | 530 | 717 | วิไล | - | - | - | - | 18700 | บอริ | 007851 | บม |
| - | 21.26 | 532 | - | วิไล | - | 30173 | - | - | 14750 | บอริ | 003835 | บม |
| 22.03 | - | 534 | - | วิไล | - | - | - | - | 11650 | บอริ | 003875 | บม |
| 23.25 | - | 544 | 713 | วิไล | - | 2214 | 22164 | 27140 | - | บอริ | 007873 | บม |
| - | 00.01 | 522 | 719 | วิไล | - | - | - | - | 16250 | บอริ | 004105 | บม |

Site Location/ หน่วยงาน BPEC

วันที่บันทึกที่ 1 เดือนสิงหาคม พ.ศ. 2568

| เวลาเข้า | เวลาออก | หมายเลขรถ | | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | | น้ำหนัก | ชั่งเบา | ชื่อลูกค้า | เลขที่ขนส่ง | SG |
|----------|----------|-----------|---------|--------------|--------------|---------------|--------|--------------|-------------|------------|-------------|------|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว Container | หาง | Gross weight | Tare weight | Customer | Manifest | |
| — | 0005 | 541 | 723 | อริศ | อริศ | 2502 | 2224 | — | 23290 | โอบี | 010435 | โอบี |
| — | 0010 | 5409 | 60-3737 | อริศ | — | LB0074 | LB0057 | — | 17970 | โอบี | 010727 | โอบี |
| 0135 | — | 536 | 716 | อริศ | — | 22160 | 1613 | — | 26060 | โอบี | 004878 | โอบี |
| — | 0222 | 536 | — | อริศ | อริศ | 22160 | — | — | 16370 | โอบี | 005159 | โอบี |
| — | 03.22 | 538 | 712 | อริศ | — | 30237 | 30220 | 41310 | — | โอบี | 004129 | โอบี |
| — | 0435 | 520 | 719 | อริศ | — | 3023 | 30214 | 39710 | — | โอบี | 004817 | โอบี |
| 0540 | — | 539 | 708 | อริศ | — | 22275 | 22127 | 30950 | — | LTS | 005282 | โอบี |
| 0550 | — | 609 | — | อริศ | อริศ | — | — | 15780 | — | LTS | — | โอบี |
| — | 0557 | 609 | — | อริศ | อริศ | — | — | — | 10840 | LTS | — | โอบี |
| 06.20 | — | 536 | — | อริศ | — | 1602 | — | 16140 | — | AGD | 005092 | โอบี |
| — | 07.22 | 539 | 708 | อริศ | — | 22275 | 22129 | — | 22270 | LTS | 005282 | โอบี |
| 08.15 | — | 572173 | — | อริศ | อริศ | — | — | 15030 | — | โอบี | — | โอบี |
| 08.30 | — | SCP39 | TR003 | อริศ | — | 4024 | 4027 | 48380 | — | โอบี | 010074 | โอบี |
| — | 08.55 | 572173 | — | อริศ | อริศ | — | — | — | 10700 | โอบี | — | โอบี |
| 09.08 | — | 72-3551 | 69-2109 | อริศ | — | — | — | 38860 | — | โอบี | — | โอบี |
| 09.28 | — | 81-3120 | — | อริศ | — | — | — | 16100 | — | โอบี | — | โอบี |
| 09.30 | — | 500 | — | อริศ | อริศ | — | — | 14400 | — | โอบี | — | โอบี |
| — | — | 500 | — | อริศ | อริศ | — | — | — | 16990 | โอบี | — | โอบี |
| 09.50 | — | 508 | 712 | อริศ | — | 30220 | 30237 | — | 24110 | โอบี | — | โอบี |
| — | 10.11 | 81-3120 | — | อริศ | — | — | — | — | 10560 | โอบี | — | โอบี |
| 10.28 | — | 572173 | TR003 | อริศ | — | 4024 | 4027 | — | 28850 | โอบี | — | โอบี |
| — | 10.35 | SCP39 | TR003 | อริศ | — | 4024 | 4027 | — | 28850 | โอบี | — | โอบี |
| — | 10.36 | 572173 | — | อริศ | — | — | — | 3130 | 3730 | โอบี | — | โอบี |
| — | 10.48 | 572173 | 64409 | อริศ | — | — | — | 18360 | — | โอบี | — | โอบี |
| — | 10.54 | 538 | 712 | อริศ | — | 30220 | 3057 | 36370 | — | โอบี | — | โอบี |
| 10.58 | — | 544 | 718 | อริศ | อริศ | 22274 | 22134 | 30530 | — | โอบี | — | โอบี |
| 11.20 | — | 520 | 719 | อริศ | — | 3023 | 30214 | — | 22850 | โอบี | — | โอบี |
| 11.26 | — | 81-3120 | — | อริศ | — | — | — | 13170 | — | โอบี | — | โอบี |
| — | 11.30 | 544 | 718 | อริศ | — | — | — | — | 17810 | โอบี | — | โอบี |
| 11.32 | — | 621 | — | อริศ | — | — | — | 18970 | — | โอบี | — | โอบี |

Site Location/ หน่วยงาน BPEC

วันที่บันทึกที่ 1 เดือนสิงหาคม พ.ศ. 2568

| เวลาเข้า | เวลาออก | หมายเลขรถ | | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | | น้ำหนัก | น้ำหนัก | ชื่อลูกค้า | เลขที่ขนส่ง | SG |
|----------|----------|-----------|--------|--------------|--------------|---------------|-------|--------------|-------------|------------|-------------|------|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว Container | หาง | Gross weight | Tare weight | Customer | Manifest | |
| 11.35 | - | SCP32 | TR002 | อริศ | - | 3038 | 30238 | 25210 | - | โอบี | 310463 | โอบี |
| - | 11.48 | 621 | - | อริศ | อริศ | - | - | - | 14180 | โอบี | - | โอบี |
| - | 12.25 | SCP-32 | TR-002 | อริศ | - | 3038 | 30238 | 24770 | - | โอบี | 010247 | โอบี |
| - | 12.29 | 57-2173 | - | อริศ | อริศ | - | - | - | 10650 | โอบี | - | โอบี |
| - | 13.05 | 574 | - | อริศ | - | 30214 | - | - | 14450 | โอบี | - | โอบี |
| - | 13.08 | 520 | 719 | อริศ | - | 2274 | 22193 | 35980 | - | โอบี | 004823 | โอบี |
| 13.13 | - | 609 | - | อริศ | อริศ | - | - | 12280 | - | โอบี | - | โอบี |
| 13.15 | - | 530 | 717 | อริศ | - | 22252 | 2273 | - | 24210 | โอบี | 010742 | โอบี |
| 13.18 | - | 547080 | - | อริศ | - | - | - | 14020 | - | โอบี | 44079 | โอบี |
| 13.35 | - | 87-2173 | - | อริศ | อริศ | - | - | 11500 | - | โอบี | - | โอบี |
| - | 13.42 | 87-2173 | - | อริศ | อริศ | - | - | - | 10650 | โอบี | - | โอบี |
| - | 13.50 | 609 | - | อริศ | อริศ | - | - | - | 10670 | โอบี | - | โอบี |
| - | 14.10 | 547080 | - | อริศ | - | - | - | - | 10280 | โอบี | - | โอบี |
| 14.12 | - | 578998 | - | อริศ | - | - | - | 14200 | - | โอบี | - | โอบี |
| - | 14.26 | 530 | 717 | อริศ | อริศ | 2273 | 22262 | 40830 | - | โอบี | 01155 | โอบี |
| 14.37 | - | 530 | - | อริศ | อริศ | 22197 | - | 20410 | - | โอบี | 608342 | โอบี |
| - | 15.00 | 578998 | - | อริศ | - | - | - | - | 9330 | โอบี | - | โอบี |
| 15.02 | - | 621 | - | อริศ | อริศ | - | - | 15470 | - | โอบี | - | โอบี |
| 15.04 | - | 838680 | - | อริศ | - | - | - | 5180 | - | โอบี | - | โอบี |
| - | 15.12 | 621 | - | อริศ | อริศ | - | - | - | 14200 | โอบี | - | โอบี |
| - | 15.20 | 621 | - | อริศ | อริศ | 22197 | - | - | 13860 | โอบี | - | โอบี |
| - | 15.27 | 838683 | - | อริศ | - | - | - | - | 3670 | โอบี | - | โอบี |
| 16.20 | - | 52-9128 | - | อริศ | - | - | - | 8320 | - | โอบี | - | โอบี |
| 16.40 | - | 544 | 718 | อริศ | - | SS02 | SS01 | - | 23410 | โอบี | - | โอบี |
| - | 16.53 | 52-9128 | - | อริศ | - | - | - | - | 5870 | โอบี | - | โอบี |
| 16.55 | - | 675713 | - | อริศ | - | - | - | 12720 | - | โอบี | - | โอบี |
| - | 17.11 | 537 | - | อริศ | - | FB-002 | - | - | 18050 | โอบี | - | โอบี |
| 17.21 | - | 538 | - | อริศ | - | 22175 | - | - | 13900 | โอบี | - | โอบี |
| - | 17.55 | 544 | 719 | อริศ | - | SS01 | SS02 | 39220 | - | โอบี | - | โอบี |
| - | 18.01 | 67-5713 | - | อริศ | - | - | - | - | 8180 | โอบี | - | โอบี |

Site Location/ หน่วยงาน BPEC

3

วันพฤหัสบดีที่ 1 เดือนพฤษภาคมพ.ศ. 2568

[illegible]

Site Location/ หน่วยงาน BPEC

1

วันที่ 1 เดือน สิงหาคม พ.ศ. 2561

| เวลาเข้า | เวลาออก | หมายเลขรถ | | พนักงานขับรถ | พนักงานติดรถ | หมายเลขภาชนะ | | ชั่งหนัก | ชั่งเบา | ชื่อลูกค้า | เลขที่ขนส่ง | SG |
|----------|----------|-----------|--------|--------------|---------------|-------------------|-------|--------------|-------------|------------|-------------|------------|
| Time in | Time out | หัว | หาง | Driver Name | Labor | หัว Container หาง | | Gross weight | Tare weight | Customer | Manifest | |
| - | 00.51 | 520 | 720 | สุทิน | สุทิน | 2221 | 2201 | 10860 | - | สุทิน | 005001 | กรมศุลกากร |
| - | 05.39 | 536 | 704 | วิไล | - | 30261 | 3054 | - | 21120 | กรมศุลกากร | 001006 | กรมศุลกากร |
| 05.50 | - | 531 | 708 | สุทิน | - | 3061 | 3080 | 32110 | - | สุทิน | 005294 | กรมศุลกากร |
| 05.52 | - | 618 | - | สุทิน | สุทิน | - | - | 12510 | - | สุทิน | - | กรมศุลกากร |
| - | 06.03 | 818 | - | สุทิน | สุทิน + สุทิน | - | - | - | 10180 | LTS | - | กรมศุลกากร |
| 06.06 | - | 608 | - | สุทิน | สุทิน | - | - | 12800 | - | สุทิน | - | กรมศุลกากร |
| - | 06.25 | 608 | - | สุทิน | สุทิน | - | - | - | 10620 | สุทิน | - | กรมศุลกากร |
| 06.35 | - | 536 | 704 | วิไล | - | - | - | - | 16910 | กรมศุลกากร | 001006 | กรมศุลกากร |
| - | 06.50 | 536 | 707 | สุทิน | - | 2277 | 30167 | - | 22890 | สุทิน | 007008 | กรมศุลกากร |
| - | 07.40 | 539 | 708 | สุทิน | - | 30244 | 3064 | - | 23160 | สุทิน | - | กรมศุลกากร |
| 07.58 | - | 536 | 707 | สุทิน | - | - | - | - | 16930 | สุทิน | - | กรมศุลกากร |
| 10.25 | - | 618 | - | สุทิน | สุทิน | - | - | 11480 | - | LTS | - | กรมศุลกากร |
| - | 10.40 | 618 | - | สุทิน | สุทิน | - | - | - | 10080 | สุทิน | - | กรมศุลกากร |
| 11.27 | - | 608 | - | สุทิน | สุทิน | - | - | 12610 | - | สุทิน | - | กรมศุลกากร |
| - | 11.44 | 608 | - | สุทิน | สุทิน | - | - | - | 10600 | สุทิน | - | กรมศุลกากร |
| 11.50 | - | 539 | 708 | สุทิน | - | 22197 | 22101 | 33280 | - | สุทิน | 005300 | กรมศุลกากร |
| - | 13.40 | 539 | 708 | สุทิน | - | 22197 | 22225 | - | 21980 | สุทิน | 005300 | กรมศุลกากร |
| 13.54 | - | SCP32 | TR003 | สุทิน | - | 30131 | 3116 | 29620 | - | STS | 55224 | กรมศุลกากร |
| - | 14.25 | SCP-32 | TA-003 | สุทิน | - | 30131 | - | - | 22180 | สุทิน | 013206 | กรมศุลกากร |
| 17.10 | - | 539 | 708 | สุทิน | - | 3023 | 30273 | 35440 | - | สุทิน | 005301 | กรมศุลกากร |
| - | 18.43 | 539 | 708 | สุทิน | - | 3023 | 30273 | - | 23710 | LTS | 005301 | กรมศุลกากร |
| 21.57 | - | 537 | - | - | - | - | - | - | 11790 | สุทิน | - | กรมศุลกากร |

เอกสารแนบ 2-9

การฝึกอบรมก่อนเริ่มงาน

แบบทดสอบก่อนฝึกอบรม เรื่อง ขั้นตอนการปฏิบัติงานเกี่ยวกับสารเคมี

จงทำเครื่องหมายกากบาท (X) ลงบนตัวเลือกที่ถูกที่สุดเพียงข้อเดียว

ชื่อ
ตำแหน่ง 11/04/14
แผนก
คะแนน

- ข้อใดกล่าวได้ถูกต้อง
 - สารเคมีสามารถก่อให้เกิดอันตราย ทั้งที่สภาวะการเก็บรักษาปกติและผิดปกติ
 - สารเคมีทุกชนิดจัดเป็นสารเคมีอันตราย
 - สารเคมีสามารถก่อให้เกิดทั้งประ โยชน์และ โทษในเวลาเดียวกัน
 - สารเคมีสามารถทำให้เกิดอันตรายต่อทรัพย์สินเท่านั้น
- ข้อใดไม่ใช่หลักการ ในการทำงานกับสารเคมีให้ปลอดภัย
 - รู้จักสารเคมี
 - รู้จักผู้ผลิต ผู้จำหน่าย
 - ปฏิบัติตามวิธีการใช้อย่างถูกต้อง
 - มีการตรวจสอบฉีกระวัง
- เราสามารถทราบความเป็นอันตรายของสารเคมีจากแหล่งใดบ้าง
 - ฉลากสารเคมี
 - ข้อมูลความปลอดภัยสารเคมี
 - เฉพาะชื่อ ก. เท่านั้น
 - ถูกต้องทั้ง ก และ ข
- เมื่อพบสัญลักษณ์ความเป็นอันตรายดังรูป ในบริเวณสถานที่เก็บรักษาสารเคมีควรปฏิบัติอย่างไร
 - ดูรูปหวับริเวณสถานที่เก็บรักษาสารเคมี
 - เชื่อมเหล็กและโลหะ บริเวณสถานที่เก็บรักษาสารเคมี
 - จัดเตรียมถังดับเพลิง บริเวณสถานที่เก็บรักษาสารเคมี
 - ถูกต้อง
- ข้อใดคือ จะถูกระบุในข้อมูลความปลอดภัยของสารเคมี
 - ข้อมูลเกี่ยวกับผู้ผลิต หรือผู้จำหน่าย, ส่วนประกอบและส่วนผสม, นวัตกรรมของผลิตภัณฑ์
 - การจัดการเมื่อสารเคมีหกคว่ำไหล, วิธีการใช้และเก็บรักษา, อุปกรณ์ป้องกันภัยส่วนบุคคล
 - คุณสมบัติทางเคมีและกายภาพ, ข้อมูลทางพิษวิทยา, ข้อมูลสำหรับการขนส่ง
 - ถูกต้อง



แบบทดสอบหลังฝึกอบรม เรื่อง ขั้นตอนการปฏิบัติงานเกี่ยวกับสารเคมี

จงทำเครื่องหมายกากบาท (X) ลงบนตัวเลือกที่ถูกที่สุดเพียงข้อเดียว

ชื่อ
ตำแหน่ง 11/04/14
แผนก
คะแนน

- ข้อใดจัดเป็น "ขยะทั่วไป" ทั้งหมด
 - เปียไวนิล ,เศษอาหาร, กระป๋องน้ำอัดลม
 - กระดามใช้แล้วในสำนักงาน, เศษพลาสติก, เศษอาหาร
 - ถุงพลาสติกใส่อาหาร , เศษพืชจากห้องน้ำ, เศษผ้าใช้แล้ว
 - กระป๋องอูนิเมียม, ถุงพลาสติกบรรจุผงซักฟอก, ถังหมักพิมพ์
- ข้อใดจัดเป็น "ขยะรีไซเคิล" ทั้งหมด
 - ถังขยะเขียว :: ขวดพลาสติก กระดามในสำนักงาน
 - ถังขยะสีเหลือง :: กระป๋องสีเปรี้ยว ภาชนะเบียร์ดื่มหมดอาหาร
 - ถังขยะสีแดง :: กระป๋องอูนิเมียม ภาชนะบรรจุเบียร์ดื่มหมดอาหาร
 - ถูกต้อง
- ข้อใดระบุประเภทของขยะ ได้ถูกต้อง
 - สีแดง : ขยะอันตราย
 - สีแดง : ขยะรีไซเคิล
 - สีเหลือง : ขยะทั่วไป
 - ขยะทั่วไป : ขยะรีไซเคิล
- ข้อใดจัดเป็น "ขยะอันตราย" ทั้งหมด
 - เศษเหล็ก, ขวดแก้วแตก, ขวดแก้วสีชา(ขวดกระป๋อง)
 - ท่อพีวีซีใช้แล้ว, กระดามใช้แล้วในสำนักงาน, ถังไฟไม่ใช้แล้ว
 - กระป๋องกาแฟ, กระดามใช้แล้ว 2 หน้า, ขวดน้ำดื่มเบียร์เบียร์
 - กระป๋องน้ำอัดลม, หมวกเซฟตี้ผ่านการใช้งานแล้ว, ถุงพลาสติกใส่อาหาร
- ข้อใดจัดเป็น "ขยะอันตราย" ทั้งหมด
 - เศษผ้าเบียร์เบียร์, กระป๋องสีเปรี้ยว, ท่อพีวีซีใช้แล้ว, เศษกระดาษ
 - เศษหินเหล็ก, เปียไวนิล, กระป๋องน้ำอัดลม, กระดาม 2 หน้า
 - เศษผ้าเบียร์เบียร์ ขวดน้ำดื่มเบียร์เบียร์, หลอดไฟ ภาชนะเบียร์ดื่มหมดอาหาร
 - ปากกา, เศษอาหาร, หัวปิดจุกใช้แล้ว, ถังหมักพิมพ์



แบบทดสอบก่อนฝึกอบรม เรื่อง ขั้นตอนการปฏิบัติงานเกี่ยวกับสารเคมี

จงทำเครื่องหมายกากบาท (X) ลงบนตัวเลือกที่ถูกที่สุดเพียงข้อเดียว

ชื่อ
ตำแหน่ง 11/04/14
แผนก
คะแนน

- ข้อใดคือ จะถูกระบุในข้อมูลความปลอดภัยของสารเคมี
 - ข้อมูลเกี่ยวกับผู้ผลิต หรือผู้จำหน่าย, ส่วนประกอบและส่วนผสม, นวัตกรรมของผลิตภัณฑ์
 - การจัดการเมื่อสารเคมีหกคว่ำไหล, วิธีการใช้และเก็บรักษา, อุปกรณ์ป้องกันภัยส่วนบุคคล
 - คุณสมบัติทางเคมีและกายภาพ, ข้อมูลทางพิษวิทยา, ข้อมูลสำหรับการขนส่ง
 - ถูกต้อง
- ข้อใดไม่ใช่หลักการ ในการทำงานกับสารเคมีให้ปลอดภัย
 - รู้จักสารเคมี
 - รู้จักผู้ผลิต ผู้จำหน่าย
 - ปฏิบัติตามวิธีการใช้อย่างถูกต้อง
 - มีการตรวจสอบฉีกระวัง
- เมื่อพบสัญลักษณ์ความเป็นอันตรายดังรูป ในบริเวณสถานที่เก็บรักษาสารเคมีควรปฏิบัติอย่างไร
 - ดูรูปหวับริเวณสถานที่เก็บรักษาสารเคมี
 - เชื่อมเหล็กและโลหะ บริเวณสถานที่เก็บรักษาสารเคมี
 - จัดเตรียมถังดับเพลิง บริเวณสถานที่เก็บรักษาสารเคมี
 - ถูกต้อง
- ข้อใดกล่าวได้ถูกต้อง
 - สารเคมีสามารถก่อให้เกิดอันตราย ทั้งที่สภาวะการเก็บรักษาปกติและผิดปกติ
 - สารเคมีทุกชนิดจัดเป็นสารเคมีอันตราย
 - สารเคมีสามารถก่อให้เกิดทั้งประ โยชน์และ โทษในเวลาเดียวกัน
 - สารเคมีสามารถทำให้เกิดอันตรายต่อทรัพย์สินเท่านั้น
- เราสามารถทราบความเป็นอันตรายของสารเคมีจากแหล่งใดบ้าง
 - ฉลากสารเคมี
 - ข้อมูลความปลอดภัยสารเคมี
 - เฉพาะชื่อ ก. เท่านั้น
 - ถูกต้องทั้ง ก และ ข

เอกสารแนบ 2-10

Tool Box Talk ก่อนเริ่มปฏิบัติงาน

การประชุมกลุ่ม

Site/โครงการ

BPEC

DATE:

09/01/25

CONDUCTOR ผู้ดำเนินการประชุม

นางสาว กันดา ทรัพย์วิลาวัณ

Venue/สถานที่ประชุม

BPEC

SUBJ/ เรื่อง การเข้างาน กรณีเกิดเหตุฉุกเฉิน 2566

| NO. ที่ | NAME-SURNAME ชื่อ-นามสกุล | TITLE ตำแหน่ง | DEPARTMENT T แผนก | SIGNATURE ลายเซ็น | DETAILS OF TOOL BOX รายละเอียดของหัวข้อการประชุม |
|------------|------------------------------|------------------|-------------------------|----------------------|--|
| 1 | | Driver06 | TD | | <p>1. ส่วนประกอบต่างๆ ของเครื่องจักร</p> <p>2. อุปกรณ์ป้องกันส่วนบุคคล</p> <p>3. การตรวจสอบความพร้อมของเครื่องจักร</p> |
| 2 | | Labor REL | TD | | |
| 3 | | Driver08 | TD | | |
| 4 | | Labor | TD | | |
| 5 | | Driver621 | TD | | |
| 6 | | Labor REL | TD | | |
| 7 | | Labor REL | TD | | |
| 8 | | DriverLTS | TD | | |
| 9 | | Labor REL | TD | | |
| 10 | | DriverLTS | TD | | |
| 11 | | Labor | TD | | |
| 12 | | Labor | TD | | |

NUMBER OF ATTENDANTS

จำนวนผู้เข้าร่วมประชุม

ลงชื่อผู้ดำเนินการประชุม

SIGNED

SIGNED

GENERAL MANAGER

ผู้จัดการทั่วไป

PLEASE KEEP ORIGINAL WITH YOUR DEPARTMENT AND SEND COPY TO SAFETY OFFICER AFTER TOOL BOX IS CONDUCTED.

กรุณาเก็บต้นฉบับไว้ที่แผนกและส่งสำเนาการประชุมให้เจ้าหน้าที่ความปลอดภัยหลังจากการประชุมเสร็จสิ้น

การประชุมกลุ่ม

Site/โครงการ

BPEC

DATE:

10/02/25

CONDUCTOR ผู้ดำเนินการประชุม

นางสาว กันดา ทรัพย์วิลาวัณ

Venue/สถานที่ประชุม

BPEC

SUBJ/ เรื่อง การเข้างาน กรณีเกิดเหตุฉุกเฉิน 2566

| NO. ที่ | NAME-SURNAME ชื่อ-นามสกุล | TITLE ตำแหน่ง | DEPARTMENT T แผนก | SIGNATURE ลายเซ็น | DETAILS OF TOOL BOX รายละเอียดของหัวข้อการประชุม |
|------------|------------------------------|------------------|-------------------------|----------------------|---|
| 1 | | Driver06 | TD | | <p>1. Toolbox ส่วนประกอบต่างๆ ของเครื่องจักร</p> |
| 2 | | Labor REL | TD | | |
| 3 | | Driver08 | TD | | |
| 4 | | Labor | TD | | |
| 5 | | Driver621 | TD | | |
| 6 | | Labor REL | TD | | |
| 7 | | Labor REL | TD | | |
| 8 | | DriverLTS | TD | | |
| 9 | | Labor REL | TD | | |
| 10 | | DriverLTS | TD | | |
| 11 | | Labor | TD | | |
| 12 | | Labor | TD | | |

NUMBER OF ATTENDANTS

จำนวนผู้เข้าร่วมประชุม

ลงชื่อผู้ดำเนินการประชุม

SIGNED

SIGNED

GENERAL MANAGER

ผู้จัดการทั่วไป

PLEASE KEEP ORIGINAL WITH YOUR DEPARTMENT AND SEND COPY TO SAFETY OFFICER AFTER TOOL BOX IS CONDUCTED.

กรุณาเก็บต้นฉบับไว้ที่แผนกและส่งสำเนาการประชุมให้เจ้าหน้าที่ความปลอดภัยหลังจากการประชุมเสร็จสิ้น

Tool Box Meeting Form

การประชุมกลุ่ม

Site/โครงการ BPEC

DATE: 15/05/25

CONDUCTOR ผู้ดำเนินการประชุม

Venue/สถานที่ประชุม

BPEC

SUBJ/ เรื่อง

| NO. ที่ | NAME-SURNAME ชื่อ-นามสกุล | TITLE ตำแหน่ง | DEPARTMENT แผนก | SIGNATURE ลายเซ็น | DETAILS OF TOOL BOX รายละเอียดของหัวข้อการประชุม |
|------------|------------------------------|------------------|--------------------|----------------------|---|
| 1 | | WVS | TD | | |
| 2 | | WVS | TD | | |
| 3 | | WVS | TD | | |
| 4 | | WVS | TD | | |
| 5 | | WVS | TD | | |
| 6 | | WVS | TD | | |
| 7 | | WVS | TD | | |
| 8 | | WVS | TD | | |
| 9 | | WVS | TD | | |
| 10 | | WVS | TD | | |
| 11 | | | | | |
| 12 | | | | | |
| 13 | | | | | |
| 14 | | | | | |
| 15 | | | | | |
| 16 | | | | | |
| 17 | | | | | |
| 18 | | | | | |
| 19 | | | | | |
| 20 | | | | | |
| 21 | | | | | |
| 22 | | | | | |
| 23 | | | | | |
| 24 | | | | | |
| 25 | | | | | |
| 26 | | | | | |
| 27 | | | | | |
| 28 | | | | | |
| 29 | | | | | |
| 30 | | | | | |

NUMBER OF ATTENDANTS

จำนวนผู้เข้าร่วมประชุม

ลงชื่อผู้ดำเนินการประชุม

SIGNED

SIGNED

GENERAL MANAGER

ผู้จัดการทั่วไป

PLEASE KEEP ORIGINAL WITH YOUR DEPARTMENT AND SEND COPY TO SAFETY OFFICER AFTER TOOL BOX IS CONDUCTED.

กรุณาเก็บต้นฉบับไว้ที่แผนกและส่งสำเนาการประชุมในเจ้าหน้าที่ความปลอดภัยหลังจากการประชุมเสร็จสิ้น

Tool Box Meeting Form

การประชุมกลุ่ม

Site/โครงการ BPEC

DATE: 10/06/25

CONDUCTOR ผู้ดำเนินการประชุม

นางสาว กิ่งลา ทวีชัยวารธน

Venue/สถานที่ประชุม

BPEC

SUBJ/ เรื่อง การใช้งาน กรณีเกิดเหตุฉุกเฉิน 2566

| NO. ที่ | NAME-SURNAME ชื่อ-นามสกุล | TITLE ตำแหน่ง | DEPARTMENT แผนก | SIGNATURE ลายเซ็น | DETAILS OF TOOL BOX รายละเอียดของหัวข้อการประชุม |
|------------|------------------------------|------------------|--------------------|----------------------|---|
| 1 | | Driver606 | TD | | |
| 2 | | Labor REL | TD | | |
| 3 | | Driver608 | TD | | |
| 4 | | Labor | TD | | |
| 5 | | Driver621 | TD | | |
| 6 | | Labor REL | TD | | |
| 7 | | Labor REL | TD | | |
| 8 | | DriverLTS | TD | | |
| 9 | | Labor REL | TD | | |
| 10 | | DriverLTS | TD | | |
| 11 | | Labor | TD | | |
| 12 | | Labor | TD | | |

NUMBER OF ATTENDANTS

จำนวนผู้เข้าร่วมประชุม

ลงชื่อผู้ดำเนินการประชุม

SIGNED

SIGNED

GENERAL MANAGER

ผู้จัดการทั่วไป

PLEASE KEEP ORIGINAL WITH YOUR DEPARTMENT AND SEND COPY TO SAFETY OFFICER AFTER TOOL BOX IS CONDUCTED.

กรุณาเก็บต้นฉบับไว้ที่แผนกและส่งสำเนาการประชุมในเจ้าหน้าที่ความปลอดภัยหลังจากการประชุมเสร็จสิ้น

เอกสารแนบ 2-11

รายงานการปฏิบัติงานของแผนร้บกากของเสีย

[illegible]

| Fuel Blending Daily Report. | | | | | Senior SV | Supervisor | Supervisor | Supervisor | |
|------------------------------|-----------------|--------------------|------------------|--------------------------|------------------------|--------------|----------------------|-------------|-------------------|
| | | | | | Mr.Wittaya | | Mr.Surapong | Mr.Chairat | |
| Date | Month | Year | Time | | day shift | Mr.Tawat | Mr.Surachai | Mr.Suttisak | |
| 7 | Feb | 2025 | 07.00 AM-4.00 PM | | | Mr.Nonchai | Mr.Nuttawat | Mr.Narubet | |
| at 4:00 PM | | | | | | | | | |
| Pit | No. | Status | Inventory / ton | Feeding Date | Tank | Inventory m³ | Inventory in Bldg | Ton | remarks |
| | 1 | Blending | 3.0 | | Solvent | 5.3 | Solid waste | 32.50 | |
| | 2 | Blending | 3.0 | | Fix Furnace | #REF! | Liquid waste | 11.20 | In + Out Building |
| | 3 | Blending | 3.0 | | W1 | 1.0 | Inflator | 0.80 | |
| | 4 | Blending | 0.0 | | W2 | 12.3 | Battery | 0.000 | |
| Total | | | 9.0 | | Oil tank | 14.0 | Solvent&Oil | 7.20 | ESBEC+Arakawa |
| Feeding Volume | | | | | | | Spray can | #REF! | |
| Direct Feed to Incinerator | No. | Weight / kgs | Customer Name | Time | Hours | kgs/ hour | Heating Value(Cal/g) | remarks | |
| | 1 | 1,180 | 4Breeze | 12.00 ~ 12.30 | 0.50 | 2,360 | | | |
| | 2 | 4,380 | Thai Environ | 12.30 ~ 14.00 | 1.50 | 2,920 | | | |
| | 3 | 1,820 | Thai Environ | 14.00 ~ 14.30 | 0.50 | 3,640 | | | |
| | 4 | 5,060 | Thai Environ | 14.30 ~ 16.30 | 2.00 | 2,530 | | | |
| | 5 | 2,190 | Thai Environ | 16.00 ~ 17.00 | 1.00 | 2,190 | | | |
| | 6 | 294 | Songkla | 13.00 ~ 13.30 | 0.50 | 588 | | Chemo Waste | |
| | 7 | 4,100 | Trend Intertrad | 17.00 ~ 18.00 | 1.00 | 4,100 | | | |
| | 8 | | | | | | | | |
| | 9 | | | | | | | | |
| | 10 | | | | | | | | |
| Total | | 19,024 | | | 7.0 | 2,717.7 | | | |
| Battery furnace (Move to IN) | No. | Weight / kgs | Customer Name | Manual Feed (Move to IN) | Waste Name | Process | Customer Name | Remarks | |
| | 1 | 157 | Infection | | | | | | |
| | 2 | 41 | Con Con | | Expired Chemical | Pump Hz No.1 | KAO | 5 pl | |
| | 3 | 80 | Alkaline Battery | | Expired Chemical | Manual Feed | AGC | 5 bb | |
| | 4 | 227 | Filter | | | | | | |
| | 5 | | | | | | | | |
| Total | | 505 | | | | | | Total | 0 |
| Unloading Job | | | | | | | | | |
| Date MF | Truck/Container | Customer name | Mf. Number | WPA | Type of waste | Volume | Location | Send to | Notice |
| 06/02/2025 | 4024 4027 | PTT Global | | | Waste Water | | | AFR | 2 tank 15 |
| 06/02/2025 | 22109 | AGC | | H80932 | Con Con | | RA | 5 bb | 1 box 22 |
| 07/02/2025 | FB001 | CCL Label | | H64540 | Contaminated Fabric | | | Pit No.2 | 1.5 |
| 07/02/2025 | FB001 | CCL Label 2 | | H63075 | Contaminated Fabric | | | Pit No.4 | 1.5 |
| 05/02/2025 | 22244 | Sak Chaisid | | H012715 | Oil Con Fabric | | Hz | | bb |
| 05/02/2025 | 22244 | Sak Chaisid | | H012759 | Lab Waste | | Hz | | bb |
| 05/02/2025 | 22244 | Sak Chaisid | | H012753 | Air/Oil Filter | | Hz | | bb |
| 05/02/2025 | 22244 | Sak Chaisid | | H012740 | Expired Chemical | | Hz | | bb |
| 06/02/2025 | FB005 | Furukawa | | H6101500 | Contaminated Container | | RA | | bb |
| 07/02/2025 | LV139 | Trane Intertrade | 38530 | H611025 | Ammonia Waste | | Hz | | Drum |
| 07/02/2025 | LV139 | Trane Intertrade | 38533 | H610541 | Used battery | | Hz | | Drum |
| 07/02/2025 | LV139 | Trane Intertrade | 38532 | H610572 | Ink Cartridge | | Hz | | Drum |
| 07/02/2025 | LV139 | Trane Intertrade | 38531 | H610540 | Spray Can | | Hz | | Drum |
| 07/02/2025 | LV139 | Trane Intertrade | 38528 | H610482 | Xylene | | Hz | | Drum |
| 05/02/2025 | SL015 | WMS | | H92527 | Filter Scrap | | Hz | | 4 bb |
| 05/02/2025 | SL015 | Songkla University | 56844 | | Chemotherapy | | | Direct Feed | 2 ibc |
| 05/02/2025 | SL015 | Songkla University | 56819 | | Chemotherapy | | | Direct Feed | 2 ibc |
| 07/02/2025 | FB001 | Syngenta | | H67355 | Expired Chemical | | Hz | | 1 pl |
| 07/02/2025 | FB001 | Syngenta | | H64349 | Used Solvent | | Hz | | 1 pl |
| 07/02/2025 | FB001 | Syngenta | | H64346 | Contaminated Material | | Hz | | 12 bb |
| 07/02/2025 | | Mazda | 38997 | H66049 | Inflator | | Hz | | bb |
| 07/02/2025 | | Mazda | 38998 | H66049 | Inflator | | Hz | | bb |
| 07/02/2025 | | Mazda | 38996 | H66049 | Inflator | | Hz | | bb |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| Receiving Team Daily Report | | | | | Senior SV | Supervisor | Supervisor | | |
|--|-----------|----------------------|---|---------------------|------------------|----------------------|----------------------|----------------|-----|
| Shift | Date | Month | Year | Time | Mr. Wittaya | Mr. Sanong | | 12.00-9.00 pm. | |
| Day | 11 | Jan | 2025 | 7:00 am. - 7:20 pm. | Members | Mr. Anan | | Mr. Nantawat | |
| | | | | | | Mr. Veerawat | | | |
| | | | | | | Mr. Apisorn | | | |
| Inventory (ton) | | Unusable & CCE(t) | | 20 | Usable (t) | 130 | Total in RC bldg (t) | | 150 |
| Feeding Volume in a shift | | | | | | | | | |
| Feeding Job | No. | Machine | Bucket (times) | Start (hr) | Stop (hr) | Actual Working Hours | Tons / hour | | |
| | 1 | CAT902B | 0 | 14,026.7 | 14,029.2 | 2.5 | 17.04 | | |
| | 2 | Rental excavator | 213 | | | | | | |
| | 3 | Other | 0 | | | | | | |
| | 4 | | | | | | | | |
| | | | | 0:00 | Total | 2.5 | 17.04 | 42.6 Ton | |
| Feeding Summary | No. | Machine | | | | Actual Working Hours | Tons | | |
| | 1 | Crusher No.2 | | | | 14.2 | 236.4 | | |
| Unloading & loading Job | | | | | | | | | |
| Number | Truck No. | Container No. | Customer Name | | Waste Name | | Remark | | |
| 1 | 52-6052 | 2210 | Lazada | | commercial waste | | | | |
| 2 | 99-3429 | 22243 | Lazada | | commercial waste | | | | |
| 3 | 53-8458 | 2210 | SSL | | commercial waste | | | | |
| 4 | 53-8458 | 22272 | Unilever | | commercial waste | | | | |
| 5 | 74-9321 | 618 | REL | | commercial waste | | | | |
| 6 | 98-6482 | 608 | REL | | commercial waste | | | | |
| 7 | 52-6052 | 30220 | Cannon | | commercial waste | | | | |
| 8 | 99-2882 | 609 | REL | | commercial waste | | | | |
| 9 | 99-3429 | 521 | ESBEC | | commercial waste | | | | |
| 10 | 97-7365 | 606 | REL | | commercial waste | | | | |
| 11 | 74-9321 | 618 | REL | | commercial waste | | | | |
| 12 | 99-2882 | 609 | REL | | commercial waste | | | | |
| 13 | 98-6482 | 608 | REL | | commercial waste | | | | |
| 14 | 97-7365 | 606 | REL | | commercial waste | | | | |
| 15 | 99-2882 | 609 | REL | | commercial waste | | | | |
| 16 | 87-2173 | 87-2173 | REL | | commercial waste | | | | |
| 17 | 99-3430 | 22225 | Unilever | | commercial waste | | | | |
| 18 | 99-3430 | 22256 | Unilever | | expired product | | | | |
| 19 | 87-2173 | 87-2173 | REL | | commercial waste | | | | |
| 20 | 99-3429 | 521 | Biersdorf | | commercial waste | | | | |
| 21 | 99-3429 | 30236 | Biersdorf | | commercial waste | | | | |
| 22 | | | | | | | | | |
| 23 | | | | | | | | | |
| 24 | | | | | | | | | |
| 25 | | | | | | | | | |
| 26 | | | | | | | | | |
| 27 | | | | | | | | | |
| 28 | | | | | | | | | |
| 29 | | | | | | | | | |
| 30 | | | | | | | | | |
| | | | Unloaded containers | | | | | | |
| | | | | | | | | | |
| Time | | Contents and comment | | | | | | | |
| 07.30am | to | 18.00pm | sorting and feeding waste to pit | | | | | | |
| | | | cleaning loader | | | | | | |
| | | | cleaning spill waste under bulky conveyor crusher NO2 | | | | | | |
| | | | cleaning machine area | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Load unusable, fly ash and incombustible | | | | | | | | | |
| Content | | | | | | | | | |
| Unusable | | | | | | | | | |
| CCE | | | | | | | | | |
| Recycle from sorting (kg) | | | | | | | | | |
| | Steel | Steel Can | Aluminium | Glass Bottle | PET Bottle | Mix Copper | Plastic | | |
| Receive (Kg) | 50 | | | | | | | | |
| Receive (Kg) | | | | | | | | | |
| Machine Status | | | | | | | | | |
| Machine Name | Status | Informed to | Start | Finish | Hrs | Details | | | |
| CAT-902B | Normal | | 3316 | 3316 | 0 | | | | |
| Rental Excavator | Normal | | 9059 | 9065 | 6 | | | | |
| Bulky No.2 CV | Normal | | | | | | | | |
| Crusher No.2 | Normal | | | | | | | | |

| Receiving Team Daily Report | | | | | Senior SV | Supervisor | Supervisor | | |
|--|-----------|----------------------|--|---------------------|------------------|----------------------|----------------------|-----------------|-----|
| Shift | Date | Month | Year | Time | | Mr. Sanong | | 12.00-21.00 pm. | |
| Day | 14 | Feb | 2025 | 7:00 am. - 7:20 pm. | Members | Mr. Nantawat | | Mr. Songkran | |
| | | | | | | Mr. Porntawee | | | |
| | | | | | | Mr. Ramphum | | | |
| Inventory (ton) | | Unusable & CCE(t) | | 80 | Usable (t) | 80 | Total in RC bldg (t) | | 160 |
| Feeding Volume in a shift | | | | | | | | | |
| Feeding Job | No. | Machine | Bucket (times) | Start (hr) | Stop (hr) | Actual Working Hours | Tons / hour | | |
| | 1 | CAT902B | 0 | 14,144.6 | 14,144.6 | 0.0 | #DIV/0! | | |
| | 2 | Rental excavator | 0 | | | | | | |
| | 3 | Other | 0 | | | | | | |
| | 4 | | | | | | | | |
| | | | | 0:00 | Total | 0.0 | #DIV/0! | 0 Ton | |
| Feeding Summary | No. | Machine | | | | Actual Working Hours | Tons | | |
| | 1 | Crusher No.2 | | | | 51.1 | 783.4 | | |
| Unloading & loading Job | | | | | | | | | |
| Number | Truck No. | Container No. | Customer Name | | Waste Name | | Remark | | |
| 1 | 87-2173 | 87-2173 | REL | | commercial waste | | | | |
| 2 | 248-2324 | LV139 | IKANO | | commercial waste | | | | |
| 3 | 99-3429 | SL-001 | STS | | commercial waste | | | | |
| 4 | 99-3429 | 3098 | STS | | commercial waste | | | | |
| 5 | 53-8458 | 3061 | IKANO | | commercial waste | | | | |
| 6 | 98-6482 | 608 | REL | | commercial waste | | | | |
| 7 | 71-3815 | 71-3816 | Friesland | | expired product | | | | |
| 8 | 99-2882 | 609 | REL | | commercial waste | | | | |
| 9 | 71-3309 | 71-3309 | Friesland | | expired product | | | | |
| 10 | 98-6482 | 608 | REL | | commercial waste | | | | |
| 11 | 52-6052 | 22111 | Friesland | | expired product | | | | |
| 12 | 71-0899 | 71-0900 | Friesland | | expired product | | | | |
| 13 | 87-2173 | 87-2173 | REL | | commercial waste | | | | |
| 14 | 53-3915 | 621 | REL | | commercial waste | | | | |
| 15 | 71-4089 | 71-4090 | Friesland | | expired product | | | | |
| 16 | 98-6482 | 608 | REL | | commercial waste | | | | |
| 17 | 53-3915 | 621 | REL | | commercial waste | | | | |
| 18 | na-4619 | LV129 | Kerry | | commercial waste | | | | |
| 19 | 97-7365 | 606 | REL | | commercial waste | | | | |
| 20 | 99-2882 | 609 | REL | | commercial waste | | | | |
| 21 | 99-3429 | 22123 | Calbee | | expired product | | | | |
| 22 | 53-8458 | 3096 | STS | | commercial waste | | | | |
| 23 | | | | | | | | | |
| 24 | | | | | | | | | |
| 25 | | | | | | | | | |
| 26 | | | | | | | | | |
| 27 | | | | | | | | | |
| 28 | | | | | | | | | |
| 29 | | | | | | | | | |
| 30 | | | | | | | | | |
| | | | Unloaded containers | | | | | | |
| | | | | | | | | | |
| Time | | Contents and comment | | | | | | | |
| 07.30am | to | 18.00pm | pumping waste water from FRIESLAND Project 4 IBC | | | | | | |
| | | | clearing spill waste on bulky conveyor area | | | | | | |
| | | | cleaning machine area | | | | | | |
| | | | cleaning excavator | | | | | | |
| | | | cleaning loader | | | | | | |
| | | | cleaning RC yard area | | | | | | |
| | | | unloading Friesland Project 6 load | | | | | | |
| Load unusable, fly ash and incombustible | | | | | | | | | |
| Content | | | | | | | | | |
| Unusable | | | | | | | | | |
| CCE | | | | | | | | | |
| Recycle from sorting (kg) | | | | | | | | | |
| | Steel | Steel Can | Aluminium | Glass Bottle | PET Bottle | Mix Copper | Plastic | | |
| Receive (Kg) | | | | | | | | | |
| Receive (Kg) | | | | | | | | | |
| Machine Status | | | | | | | | | |
| Machine Name | Status | Informed to | Start | Finish | Hrs | Details | | | |
| CAT-902B | Normal | | 3358 | 3358 | 0 | | | | |
| Rental Excavator | Normal | | 7222 | 7227 | 5 | | | | |
| Bulky No.2 CV | Normal | | | | | | | | |
| Crusher No.2 | Normal | | | | | | | | |

Receiving Team Daily Report

Shift

Date

Month

Year

Time

Day

27

March

2025

7:00 am. - 7:20 pm.

Inventory (ton)

Unusable & CCE(t)

40

Usable (t)

160

Total in RC bldg (t)

200

Senior SV

Mr. Wittaya

Supervisor

Mr. Sanong

Supervisor

12.00-21.00 pm.

Members

Mr.Nantawat

Mr.Anan

Mr.Veerawat

Feeding Volume in a shift

Feeding Job

No.

Machine

Bucket (times)

Start (hr)

Stop (hr)

Actual Working Hours

Tons / hour

1

CAT902B

0

2

Rental excavator

198

14,285.6

14,288.0

2.4

16.50

3

Other

0

4

0:00

Total

2.4

16.50

39.6 Ton

Feeding Summary

No.

Machine

Actual Working Hours

Tons

1

Crusher No.2

97.0

1,746.8

Unloading & loading Job

Number

Truck No.

Container No.

Customer Name

Waste Name

Remark

1

53-8458

22183

Lazada

commercial waste

2

52-6052

30186

AGC

commercial waste

3

99-2882

609

REL

commercial waste

4

53-8459

22275

Unilever

ice cream

5

74-9321

618

REL

commercial waste

6

99-3430

3098

NTS

commercial waste

7

98-6482

608

REL

commercial waste

8

99-3430

22123

Cannon

commercial waste

9

99-3430

22213

Cannon

commercial waste

10

2air 9536

4 wheel

SUNYO

commercial waste

11

97-7365

606

REL

commercial waste

12

98-6482

608

REL

commercial waste

13

99-2882

609

REL

commercial waste

14

52-6052

30186

ROYALKANIN

expired product

15

52-6052

30199

ROYALKANIN

expired product

16

74-9321

618

REL

commercial waste

17

97-7365

606

REL

commercial waste

18

53-3915

621

REL

commercial waste

19

53-8459

22197

Unilever

commercial waste

20

98-6482

608

REL

commercial waste

21

2air2324

LV139

Kopfood

commercial waste

22

53-3915

621

REL

commercial waste

23

64-3492

30247

Sumitomo

commercial waste

24

64-3492

3071

Sumitomo

commercial waste

25

26

27

28

29

30

Unloaded containers

Time

Contents and comment

07.30pm

to

18.00pm

sorting and feeding waste to pit # crusher No2

separating steel from IBC tank

cleaning machine area

cleaning RC yard area

cleaning excavator

pumping waste water from gutter area



Load unusable, fly ash and incombustible

Content

Unusable

CCE

Recycle from sorting (kg)

Steel

Steel Can

Aluminium

Glass Bottle

PET Bottle

Mix Copper

Plastic

Machine Status

Machine Name

Status

Informed to

Start

Finish

Hrs

Details

CAT-902B

Normal

3393

3393

0

Rental Excavator

Normal

7640

7646

6

Bulky No.2 CV

Normal

Crusher No.2

Normal

Receiving Team Daily Report

Shift

Date

Month

Year

Time

Day

24

April

2025

7:00 am. - 7:20 pm.

Inventory (ton)

Unusable & CCE(t)

50

Usable (t)

100

Total in RC bldg (t)

150

Senior SV

Mr. Wittaya

Supervisor

Mr. Sanong

Supervisor

Mr. Thanawat

12.00-21.00 pm.

Members

Mr.Anan

Mr.Veerawat

Feeding Volume in a shift

Feeding Job

No.

Machine

Bucket (times)

Start (hr)

Stop (hr)

Actual Working Hours

Tons / hour

1

CAT902B

0

14,341.3

14,341.3

0.0

#DIV/0!

2

Rental excavator

150

3

Other

0

4

0:00

Total

0.0

#DIV/0!

30 Ton

Feeding Summary

No.

Machine

Actual Working Hours

Tons

1

Crusher No.2

41.4

816.0

Unloading & loading Job

Number

Truck No.

Container No.

Customer Name

Waste Name

Remark

1

52-6052

1602

AGC

Commercial Waste

2

99-3439

22293

LAZADA

Commercial Waste

3

53-8459

22197

Unilever

Rejected product

4

97-7365

606

REL

Commercial Waste

5

87-2173

6 wheel

REL

Commercial Waste

6

74-9321

618

REL

Commercial Waste

7

52-6052

30250

Sino-Pacific

Write off Product

8

52-6052

3080

Sino-Pacific

Write off Product

9

97-7365

606

REL

Commercial Waste

10

87-2173

6 wheel

REL

Commercial Waste

11

53-3915

621

REL

Commercial Waste

12

63-5874

22235

Carrier

Waste Commercial with chemicals

13

3air-7137

4 wheel

NP Green

Out Off spec product

14

63-5874

22120

Carrier

Waste Commercial with chemicals

15

99-3428

30214

Sino-Pacific

Write off Product

16

87-2173

6 wheel

REL

Commercial Waste

17

99-3428

30220

Sino-Pacific

Write off Product

18

97-7365

606

REL

Commercial Waste

19

53-3915

621

REL

Commercial Waste

20

74-9321

618

REL

Commercial Waste

21

99-3429

22293

We eat

Write off Product

22

1air-3821

4 wheel

Teansmedic

Medical equipment

23

99-3429

3139

Sino-Pacific

Write off Product

24

4air-6063

4 wheel

Teansmedic

Medical equipment

25

26

27

28

29

30

Unloaded containers

24

Time

Contents and comment

07.30am

to

18.00pm

stop feed # refuse pit waste full

cleaning RC building yard area

Load Unusable waste

cleaning machine area

Load unusable, fly ash and incombustible

Content

Unusable

CCE

Recycle from sorting (kg)

Steel

Steel Can

Aluminium

Glass Bottle

PET Bottle

Mix Copper

Plastic

Machine Status

Machine Name

Status

Informed to

Start

Finish

Hrs

Details

CAT-902B

Normal

3403

3403

0

Rental Excavator

Normal

7869

7872

3

Bulky No.2 CV

Normal

Crusher No.2

Normal

เอกสารแนบ 2-12

เอกสารขั้นตอนการจัดการของเสียเข้าสู่ห้องเผาและบันทึกการควบคุม
ความเหมาะสมของค่าความร้อนของการเผาขยะในเตาเผา

| | | |
|---|-----------------|---------------------------|
| Standard Operating Procedure | | Doc. No.: 05-IN-S001 |
| Subject: Operational Control for Incinerator and Associated Air Pollution Control Equipment | | Page: 1 of 9 |
| Prepared by: IN Dept. | Date: 16 Jan 20 | Effective Date: 20 Jan 20 |
| Approved by: [REDACTED] | | Revision: 8 |
| Authorization: [REDACTED] | Date: 16/1/20 | Copy No.: |

Change Control

| Revision | Change Date | Description of Change | Initial | DAR No. | Effective Date |
|----------|-------------|--|----------|---------|----------------|
| 0 | 15/07/07 | Issue new document | Mayanee | 08/029 | 1/08/07 |
| 1 | 15/12/07 | Add CO measurement into CEM system | Mayanee | 08/043 | 1/01/08 |
| 2 | 15/01/08 | - Add the corrective action in case found the differential of sand temperature more than 25°C - Add the procedure of secondary burner using | Mayanee | 08/044 | 1/02/08 |
| 3 | 20/08/09 | - Change Diesel to Bunker A or C - Change XSV-101 to T-104 | Sompong | 09/011 | 30/08/09 |
| 4 | 17/11/09 | - Change SOP name from Control of combustion Condition to Operational Control for Incinerator and Associated Air Pollution Control Equipment - Add purpose 1.1 and 1.4 - Add scope and application 2.2 - Add trouble shooting | Ito-San | 09/031 | 01/12/09 |
| 5 | 16/9/10 | - Add furnace temperature control to reduce dioxin in 4.1.2 - Add maintenance method for injection blower in 4.4 | Ito | 10/009 | 16/09/10 |
| 6 | 17/6/11 | - Addition check sheet | Kantapat | 11/005 | 17/06/11 |
| 7 | 20/6/18 | - Update combustion support system | Kantapat | 18/010 | 10/07/18 |
| 8 | 16 Jan 20 | Revive document every 2 year | Thanatat | 20/013 | 20 Jan 20 |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

| | | |
|---|-----------------|---------------------------|
| Standard Operating Procedure | | Doc. No.: 05-IN-S001 |
| Subject: Operational Control for Incinerator and Associated Air Pollution Control Equipment | | Page: 2 of 9 |
| Prepared by: IN Dept. | Date: 16 Jan 20 | Effective Date: 20 Jan 20 |
| Approved by: [REDACTED] | | Revision: 8 |

1. Purpose

- 1.1 To specify the operational controls for the incinerator and air pollution control equipment including where applicable maximum and minimum operating criteria.
- 1.2 To be the instruction of completed combustion control during waste incineration by Fluidized Bed Incinerator
- 1.3 To ensure that the waste combustion control will not cause the air emission over the standard
- 1.4 To detail the operational controls as specified in BPEC's environmental mitigation measures.

2. Scope and Application

- 2.1 This procedure will apply to control the combustion condition during waste incineration by Fluidized Bed Incinerator and make sure that the combustion condition is control to meet the requirement and not emit the air pollution over than standard.
- 2.2 This procedure controls the operating conditions of the air pollution control equipment.

3. Associated Document

- | | |
|------------|---|
| 05-IN-F002 | Operation Record at CCR |
| 05-IN-F005 | BPEC Check sheet (Bag filter, Wet scrubber, etc.) |
| 05-IN-F006 | BPEC Check sheet (Air fan, IDF, Crusher) |
| 05-IN-F007 | BPEC Check sheet (Pump, Compressor, etc.) |
| 05-IN-F008 | BPEC Check sheet (Furnace area) |

4. Procedure

- The detailed operational controls and parameters are detailed in the Operation & Maintenance Manual for Whole Plant (1) – Revision 1, Manual No. 1
- Operators should understand and follow the requirements of the Operational & Maintenance Manuals which apply to plant and equipment used in areas of their designated responsibilities.

| | |
|---|---------------------------|
| Standard Operating Procedure | Doc. No.: 05-IN-S001 |
| Subject: Operational Control for Incinerator and Associated Air Pollution Control Equipment | Page: 3 of 9 |
| Prepared by: IN Dept. Date: 16 Jan 20 | Effective Date: 20 Jan 20 |
| Approved by: [REDACTED] | Revision: 8 |

4.1 Furnace

4.1.1 The control of waste combustion in furnace will follow the program of Combustion Support System (CSS) shown in Figure 1. The main items of this program are following

- Control of waste volume and speed of feeding into the furnace
- Control of air supply into the furnace to make Fluidization and completely combustion
- Control of pressure inside the furnace
- Control of water feeding for cool down sand and flue gas temperature




Figure 1. Combustion Support System (CSS)

| | |
|---|---------------------------|
| Standard Operating Procedure | Doc. No.: 05-IN-S001 |
| Subject: Operational Control for Incinerator and Associated Air Pollution Control Equipment | Page: 4 of 9 |
| Prepared by: IN Dept. Date: 16 Jan 20 | Effective Date: 20 Jan 20 |
| Approved by: [REDACTED] | Revision: 8 |

4.1.2 The procedure of combustion control comprises:

- Start the incinerator by using auxiliary burner which is installed at the furnace and feed diesel oil to increase the sand and furnace temperature. In this step sand will be continuous feeding into the furnace until the sand temperature (T-101 and T-102) and flue gas temperature (T-103, 104) reach 550 – 650degC and 850 – 950deg.C, respectively.
- The waste will be conveyed to the furnace once the sand and flue gas temperature reach the designed value to make sure that the combustion and dioxin destroy is complete. After waste feeding diesel oil feeding will be decreased until the combustion is stable the fuel feeding will be stop.
- To monitor the combustion, BPEC has installed CO measurement from flue gas by CEMs to control the content of CO 100 ppm according to the regulation of Directive 2000/76/EC
- In case the temperature of flue gas is lower than 850deg.C and CO is increasing, the following procedures will be done;
 - (1) The volume of solid feeding will be increased or the heating value of solid waste will be increased by mixing properly. Then, the flow rate of primary air fan and secondary air fan will also be adjusted to keep oxygen and CO proper level (Oxygen: 9-12.5%, CO<100ppm).
 - (2) When temperature is still lower than 850deg.C after doing the above procedure (1), the secondary burner will operate to maintain the temperature inside the furnace and will stop once the flue gas temperature is more than 900deg.C
- During waste burning, in case CSS is alarm because the 2 sides of sand temperature detection has differential more than 25deg.C or the sand temperature is lower than 200deg.C it will lead to lost of fluidization in the furnace, shall follow below procedure
 - Continue feeding waste to maintain Fluidization condition and furnace temperature
 - Inspect sir nozzle and fan condition
 - Inspect Windbox condition
 - Inspect pressure loss in furnace, it will occur if high level of sand inside the furnace and decreasing of air supplied into the furnace
 - Inspect sand recirculation, if the error occur in sand recirculation it may lead to loss of Fluidization condition

If this solution fails to restore fluidization, shut down incinerator and investigate the problem for further corrective and preventive action.

| | |
|---|----------------------|
| Standard Operating Procedure | Doc. No.: 05-IN-S001 |
| Subject: Operational Control for Incinerator and Associated Air Pollution Control Equipment | Page: 5 of 9 |
| Prepared by: IN Dept. | Date: 16 Jan 20 |
| Effective Date: 20 Jan 20 | |
| Approved by: [REDACTED] | Revision: 8 |

4.2 Boiler

- Flue gas outlet from the furnace will be rapidly decreased from 900deg.C to 250deg.C in boiler (app. 13 seconds)
- Level of boiler water in the drum is controlled at 50mm using boiler feed water pump.
- Boiler water pH is controlled between 9.5-11.5 by feeding chemicals.
- Steam pressure in the drum is controlled at 2.1MPa.

4.3 Gas cooling tower

- Gas cooling tower is provide to reduced flue gas temp from 250-400 deg C to 160-200 deg.C. Gas cooling tower has sufficient volume, so it is possible to keep residence time that is enough to evaporate the spray water completely at the whole range of combustion capacity.
- Spray water is injected into the gas cooling tower by stainless steel nozzle with atomizing air and feed rate is controlled by the outlet temp.

4.4 Injection system of lime & activated carbon

- Injection Blower Pressure shall be monitored and control to not over than 0.03 MPa to prevent blower clogging.
- Physical conditions shall be inspected on every shift.
- **Consumption volume of lime and activated carbon shall be checked daily. Especially activated carbon is necessary for dioxin destruction. If each consumption is abnormally low, it seems that the problem is happening such as malfunction of injection feeder and clogging in the pipeline. It is necessary to inspect pipeline and inside feeder.**
- Corrosive condition of the equipment which may cause the air leakage and the reduction of treatment efficiency, shall be inspected every shut down.

4.5 Bag filter

- Manometer reading which means pressure loss shall be monitored and controlled to not more than 2.5 kPa to prevent the clogging and damage of bag filter.
- The temperature of inlet and outlet of flue as shall be monitored and controlled to be not more than 160-200 °C to ensure the treatment efficiency and lifetime of bag filter can be extended accordingly.
- Flow rate of outlet flue gas shall be monitored and controlled to not over than 65,000 cu.m/hr. If the flow rate exceeds the mentioned rate, pressure loss will be increase and could cause the damage of bag filter
- Bag filter shall be inspected for any tear twice a year or every shut down.

| | |
|---|----------------------|
| Standard Operating Procedure | Doc. No.: 05-IN-S001 |
| Subject: Operational Control for Incinerator and Associated Air Pollution Control Equipment | Page: 6 of 9 |
| Prepared by: IN Dept. | Date: 16 Jan 20 |
| Effective Date: 20 Jan 20 | |
| Approved by: [REDACTED] | Revision: 8 |

- Number of spare bag filter shall not be less than 10% of total bag filter used in the system (see BP-PM-12 section 3) to ensure that spare bag filters are available when change of bag filter is undertaken

4.6 Wet Scrubber

- pH value of absorption liquid shall be monitored and controlled to be in the normal operating range 6-8 that represent normal condition. Set point is pH7.2.
- Physical conditions shall be inspected on a monthly basis.
- Corrosive condition the equipment, which may cause the air leakage and the reduction of treatment efficiency, shall be inspected every shut down.

4.7 Stack

Stack is installed to diffuse and discharge flue gas into the atmosphere. At the stack, flue gas is sampled and sent to continuous emission monitoring system (CEMs). Here, the following parameters are analyzed to meet the standard.

- HCl (standard: 25ppm)
- SO₂ (standard: 30ppm)
- NO_x (standard: 180ppm)
- Opacity (standard: 10%)
- O₂
- CO

4.8 Wastewater treatment system

- This plant is designed to process wet scrubber waste water, boiler drain and drain from the gas analyzer. Wastewater is treated with pH adjustment and the precipitation by dosing the filtering through the sand layer to remove suspended matters and then the salt concentration is diluted by make-up water before being discharged. Collected coagulated sludge is transferred to the waste pit.
- At the neutralization tank, pH value is adjusted by dosing hydrochloric acid and caustic soda between 5.0-9.0

4.9 Steam generation equipment

4.9.1 Steam accumulator

- Ensure that the manhole packing and the flange and gasket face are adequately fitted.
- Close manhole
- Identify the state of valves in accumulator before starting operation

| | |
|---|---------------------------|
| Standard Operating Procedure | Doc. No.: 05-IN-S001 |
| Subject: Operational Control for Incinerator and Associated Air Pollution Control Equipment | Page: 7 of 9 |
| Prepared by: IN Dept. | Date: 16 Jan 20 |
| Approved by: [Redacted] | Effective Date: 20 Jan 20 |
| | Revision: 8 |

- When the accumulator pressure rises up to a normal operation slowly open the steam outlet valve and after ensuring that it fully opens, enter the operation.

4.9.2 Steam condenser

- The steam enters into the inlet header and condensed while passing through upper 3 layers. The condensate passes through rear header and enters into lower 1 layer tubes and sub-cooled at 80deg.C while passing through lower 1 layer and flows out from the outlet header.
- To keep temperature of the outlet nozzle, rotation of propeller fan is controlled.

4.9.3 Deaerator

- Confirm that the water level control valve works normally when the water level lowers due to the starting of the boiler water feed pump
- Open valves at front and rear of the deaerator main valve.
- Discharge drain from the steam pipe
- Gradually open the pressure control valve, to pass steam, by manual operating.

| | |
|--|-----------------------------|
| Standard Operating Procedure | Doc. No.: 05-IN-S001 |
| Subject: Operational Control for Incinerator and Associated Air Pollution Control Equipment | Page: 8 of 9 |
| Prepared by: IN Dept. | Date: 16 Jan 20 |
| Effective Date: 20 Jan 20 | |
| Approved by: [Redacted] | Revision: 8 |

4.10 Summary of Operational Control Parameters

Table 1 Summary of the Operational Controls.

| Item | Description | Monitor | Keep point | Max | Min | Unit | Remark |
|-----------------------------|----------------------------|----------------|------------|--------|--------|-----------------------|------------------------------------|
| 1 | Feeder | Speed | 350 | 800 | 200 | RPM | S-101 |
| | Primary air supply | Air | 13,500 | 16,500 | 12,500 | m ³ /hr(N) | F-101_1 |
| | | VFD control | 45 | 48 | 42 | Hz | F-101_1 |
| | | Sand Diff. | 14 | 18 | 12 | kPa | Sand Pressure |
| | Secondary air supply | Air | 14,000 | 18,000 | 8,000 | m ³ /hr(N) | F-103_1 |
| | Fluidized Bed Temperature | Temperature | 645 | 700 | 550 | °C | T-101,T-102 |
| | In Furnace Temperature | Temperature | 850 | 950 | 800 | °C | T-103 |
| | Furnace Outlet Temperature | Temperature | 850 | 950 | 800 | °C | T-104 |
| Combustion Pressure (P-101) | Pressure | -0.6 | -0.6 | -1.2 | kPa | P-101_1 | |
| 2 | Boiler Drum | Pressure | 2.15 | 2.25 | 1.5 | Mpa | PCV-403-1 (1.5) PCV-403-2 (2.1) |
| | | Level of water | 50 | 250 | -150 | mm | L-403 |
| | | pH | 9.8 | 11.5 | 9.5 | | Q-401 |
| | | Conductivity | < 50 | 50 | 0 | mS/m | Q-402 |
| | | Pressure | 280 | 340 | 240 | kPa | P-401 |
| 3 | Deaerator | Level of water | 30 | 150 | -150 | mm | L-402 |
| | | Temperature | 280 | 400 | 120 | °C | T-105 |
| 4 | Gas cooling tower | Temperature | 160 | 200 | 120 | °C | T-106 |
| 5 | Bag filter | Diff. Pressure | < 2.5 | 3 | 0 | kPa | PDT-160 |
| | | pH | 7.2 | 8 | 6 | | QICA-241 |
| 6 | Wet scrubber | Diff. Pressure | < 1.3 | 2.5 | 0 | kPa | PDT-241 |
| | | HCl | < 25 | 25 | 0 | ppm | Q-101AVE |
| 7 | Stack | Nox | < 180 | 180 | 0 | ppm | Q-102AVE |
| | | SO2 | < 30 | 30 | 0 | ppm | Q-103AVE |
| | | CO | < 100 | 115 | 0 | ppm | Q-106AVE |
| | | O2 | < 14 | 14 | 0 | % | Q-104AVE |
| | | Opacity | < 10 | 10 | 0 | % | Q-105AVE |

| | |
|---|---------------------------|
| Standard Operating Procedure | Doc. No.: 05-IN-S001 |
| Subject: Operational Control for Incinerator and Associated Air Pollution Control Equipment | Page: 9 of 9 |
| Prepared by: IN Dept. Date: 16 Jan 20 | Effective Date: 20 Jan 20 |
| Approved by: [REDACTED] | Revision: 8 |

5 Reference

- 5.1 Operation & Maintenance Manual for Whole Plant (1) – Revision 1, Manual No. 1
- 5.2 Furnace (Operation Procedure & Setting Methods) O-M Manual, Manual No. 7
- 5.3 Furnace (Combustion Support System) O-M Manual, Manual No. 7
- 5.4 Furnace (Summary Instruction) O-M Manual, Manual No. 7
- 5.5 Boiler O-M Manual
- 5.6 Gas cooling tower O-M Manual
- 5.7 Lime & activated carbon injection system O-M Manual
- 5.8 Bag filter O-M Manual
- 5.9 Wet Scrubber O-M Manual
- 5.10 Wastewater treatment system O-M Manual
- 5.11 Deaerator, Steam accumulator, steam condenser O-M Manual

6. Glossary

- N/A

7. Definition

- N/A

| | |
|---|--|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-IN-S001T |
| เรื่อง: ขั้นตอนการควบคุมสภาวะการเผาไหม้และอุปกรณ์ที่เกี่ยวข้องกับระบบควบคุมมลพิษอากาศ | หน้าที่: 1 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกปฏิบัติการเตาเผา วันที่: 16 ม.ค.63 | วันที่มีผลบังคับใช้: 20 ม.ค.63 |
| อนุมัติโดย: [REDACTED] | แก้ไขครั้งที่: 8 |
| ผู้มีอำนาจ: [REDACTED] | วันที่: 16/1/20 สำเนาที่: |

การเปลี่ยนแปลงเอกสาร

| เปลี่ยนแปลงครั้งที่ | วันที่ | รายละเอียดการเปลี่ยนแปลง | ลายมือชื่อ | DAR เลขที่ | วันที่มีผลบังคับใช้ |
|---------------------|-------------|--|------------|------------|---------------------|
| 0 | 15 ก.ค. 50 | ออกเอกสารใหม่ | เมยาณี | 08/029 | 1 ส.ค. 50 |
| 1 | 15 ธ.ค. 50 | เพิ่มเติมขั้นตอนปฏิบัติในการติดตามความเข้มข้นของคาร์บอนมอนอกไซด์ที่ปล่อยออกจาปล่องระบายอย่างต่อเนื่องโดยระบบ CEMs | เมยาณี | 09/043 | 1 ม.ค. 51 |
| 2 | 15 ม.ค. 51 | - เพิ่มเติมขั้นตอนการดำเนินการแก้ไข กรณีที่ความแตกต่างของอุณหภูมิในตัวถัง เกล็ด 5 องศาเซลเซียส ซึ่งเหตุการณ์ดังกล่าวจะนำไปสู่การสูญเสียสภาวะที่เหมาะสมในการเผาไหม้ - เพิ่มเติมขั้นตอนในการใช้งานหัวเผาทุติยภูมิ (Secondary Burner) ซึ่งทำงานโดยอัตโนมัติเมื่ออุณหภูมิของก๊าซจากการเผาไหม้มีค่าต่ำกว่า 850 องศาเซลเซียส และจะหยุดการจ่ายเชื้อเพลิงเมื่ออุณหภูมิมีค่าสูงกว่า 900 องศาเซลเซียส | เมยาณี | 08/044 | 1 ก.พ. 51 |
| 3 | 20 ส.ค. 52 | เปลี่ยนคำว่าน้ำมันดีเซล เป็น น้ำมันเตาเกรดเอ หรือ เกรดซี - เปลี่ยนคำว่า XSV -101 เป็น T-104 | สมพงษ์ | 09/011 | 30 ส.ค. 52 |
| 4 | 17 พ.ย. 52 | - เพิ่มวัตถุประสงค์ข้อ 1.1 และ 1.4 - เพิ่มขอบเขตและการปฏิบัติข้อ 1.2 | อิโต | 09/031 | 1 ธ.ค. 52 |
| 5 | 16 ก.ย. 53 | - เพิ่มการควบคุมอุณหภูมิในห้องเผาเพื่อลดค่าไดออกซิน ตามข้อ 4.1.2 - เพิ่มวิธีการบำรุงรักษา injection blower ตามข้อ 4.4 | อิโต | 10/009 | 16 ก.ย. 53 |
| 6 | 17 มิ.ย. 54 | - เพิ่มเติมเอกสารที่เกี่ยวข้อง | กันตพัฒน์ | 11/005 | 20 มิ.ย. 54 |
| 7 | 21 มิ.ย. 61 | - เพิ่มเติมการควบคุมการทำงานห้องเผาไหม้ | กันตพัฒน์ | 18/010 | 10 ก.ค. 61 |
| 8 | 16 ม.ค.63 | ทบทวนเอกสาร | ธนัช | 20/013 | 20 ม.ค. 63 |

| | |
|---|--------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-IN-S001T |
| เรื่อง: ขั้นตอนการควบคุมสภาวะการเผาไหม้และอุปกรณ์ที่เกี่ยวข้องกับระบบควบคุมมลพิษอากาศ | หน้าที่: 2 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกปฏิบัติการเตาเผา | วันที่: 14 ม.ค.63 |
| อนุมัติโดย: [REDACTED] | วันที่มีผลบังคับใช้: 20 ม.ค.63 |
| | แก้ไขครั้งที่: 8 |

1. วัตถุประสงค์

- 1.1 เพื่อแจ้งการปฏิบัติงานการเผาไหม้ การควบคุมอากาศร้อนจากเครื่องควบคุมอากาศร้อน โดยสอดคล้องกับค่ามากที่สุดและต่ำสุด
- 1.2 เพื่อเป็นขั้นตอนการปฏิบัติงานในการควบคุมสภาวะในการเผาไหม้ในระหว่างขณะเผาไหม้ในระบบการลอยตัวของทราย
- 1.3 เพื่อให้มั่นใจว่าการเผาไหม้ของขยะไม่ทำให้ค่าอากาศร้อนเกินจากค่ามาตรฐาน
- 1.4 เพื่อแจ้งการควบคุมการปฏิบัติงานซึ่งระบุใน การบรรเทาผลกระทบทางสิ่งแวดล้อมของ BPEC

2. ขอบเขตและการใช้งาน

- 2.1 ขอบเขตการใช้งานของมาตรฐานการปฏิบัติงานนี้จะครอบคลุมเฉพาะกระบวนการเผาไหม้ของเสียในห้องเผาไหม้ไม่ให้เกิดอากาศร้อนเกินค่ามาตรฐาน
- 2.2 การปฏิบัติงานนี้ควบคุมเรื่องควบคุมมลพิษทางอากาศ

3. เอกสารที่เกี่ยวข้อง

| | |
|------------|---|
| 05-IN-F002 | Operation Record at CCR |
| 05-IN-F005 | BPEC Check sheet (Bag filter, Wet scrubber, etc.) |
| 05-IN-F006 | BPEC Check sheet (Air fan, IDF, Crusher) |
| 05-IN-F007 | BPEC Check sheet (Pump, Compressor, etc.) |
| 05-IN-F008 | BPEC Check sheet (Furnace area) |

4. ขั้นตอนการปฏิบัติงาน

- รายละเอียดการควบคุมแต่ละส่วนแยกย่อยตามรายละเอียดในคู่มือปฏิบัติงานและการบำรุงรักษาเครื่องจักรในหัวข้อ Whole Plant(1) Revision 1, Manual No.1
- ผู้ปฏิบัติงานต้องมีความเข้าใจ และปฏิบัติตามคู่มือปฏิบัติงานและการบำรุงรักษาเครื่องจักร ซึ่งใช้ในพื้นที่ต่าง ๆ ตามที่ได้ออกแบบไว้


4.1 เตาเผาขยะ

4.1.1 การควบคุมการเผาไหม้ในเตาเผาจะถูกควบคุมโดยโปรแกรม Combustion Support System (CSS) ดังแสดงในรูปที่ 1 ส่วนประกอบหลักของโปรแกรมประกอบด้วย

- ควบคุมปริมาณและความเร็วของขยะที่ป้อนเข้าสู่เตาเผา
- ควบคุมปริมาณอากาศที่ป้อนเข้าสู่เตาเผา เพื่อให้เกิดการเผาไหม้ที่สมบูรณ์

| | |
|---|--------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-IN-S001T |
| เรื่อง: ขั้นตอนการควบคุมสภาวะการเผาไหม้และอุปกรณ์ที่เกี่ยวข้องกับระบบควบคุมมลพิษอากาศ | หน้าที่: 3 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกปฏิบัติการเตาเผา | วันที่: 14 ม.ค.63 |
| อนุมัติโดย: [REDACTED] | วันที่มีผลบังคับใช้: 20 ม.ค.63 |
| | แก้ไขครั้งที่: 8 |

- ควบคุมความดันในเตาเผา
- ควบคุมน้ำที่ฉีดเข้าเตาเผาเพื่อลดอุณหภูมิของทรายและอุณหภูมิของก๊าซ



รูปที่ 1 แสดงการควบคุมการทำงานห้องเผาไหม้ด้วยระบบ CSS

4.1.2 การปฏิบัติเพื่อควบคุมการเผาไหม้มีดังต่อไปนี้

- ทำการจุดหัวเผา (Auxiliary Burner) ที่ติดตั้งที่ตัวเตาเผาขยะโดยการพ่นและองน้ำมันที่มีค่าความร้อนจำเพาะสูง เพื่อเพิ่มอุณหภูมิให้กับทรายและเตาเผาขยะ ในช่วงนี้ทรายจะถูกป้อนเข้าสู่เตาเผาขยะอย่างต่อเนื่อง จนกระทั่งอุณหภูมิของทราย (T-101, T-102) สูงถึง 550 - 650 องศาเซลเซียส ส่วนอุณหภูมิของอากาศร้อนด้านบนของเตาเผาขยะ (T-103, T-104) มีอุณหภูมิ 850 - 950 องศาเซลเซียส
- ขยะจะถูกสับเลี้ยวเข้าสู่เตาเผาขยะเมื่ออุณหภูมิของทรายสูงถึงค่าที่ออกแบบไว้ ให้แน่ใจว่า Dioxin ได้ถูกทำลายภายหลังที่ป้อนขยะ ปริมาณการฉีดน้ำมันเตาจะลดลง และจะหยุดฉีดน้ำมันเตา เมื่ออุณหภูมิของทรายและการเผาไหม้ที่เสถียร
- BPEC ได้ทำการติดตั้งเครื่องตรวจวัดอากาศร้อน โดยการควบคุมค่า CO จะต้องไม่เกิน 100 ppm ตามข้อกำหนด 2007/6/EC

| | |
|---|--------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-IN-S001T |
| เรื่อง: ขั้นตอนการควบคุมสภาวะการเผาไหม้และอุปกรณ์ที่เกี่ยวข้องกับระบบควบคุมมลพิษอากาศ | หน้าที่: 4 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกปฏิบัติการเตาเผา | วันที่: 14 ม.ค.63 |
| อนุมัติโดย: [REDACTED] | วันที่มีผลบังคับใช้: 20 ม.ค.63 |
| | แก้ไขครั้งที่: 8 |

- ในกรณีของอุณหภูมิอากาศร้อน ต่ำกว่า 850 องศาเซลเซียส และค่า CO เพิ่มขึ้นให้ดำเนินการดังนี้
 - (1) เพิ่มปริมาณการป้อนขยะหรือขยะที่มีค่าความร้อนสูงที่ผสมกันแล้วเข้าสู่ห้องเผา จากนั้นปรับอัตราการไหลของอากาศทั้ง primary air fan และ secondary air fan โดยปรับระดับออกซิเจนและ CO ให้เหมาะสม (ออกซิเจน 9-12.5 % และ CO <100 ppm)
 - (2) หากอุณหภูมิอากาศร้อนยังคงต่ำกว่า 850 องศาเซลเซียส เมื่อดำเนินการตามข้อ (1) แล้ว ให้ทำการจุดหัวเผาทุติยภูมิ (Secondary Burner) เพื่อเพิ่มอุณหภูมิของ เตาเผาขยะ และเมื่ออุณหภูมิของอากาศร้อนสูงมากกว่า 900 องศาเซลเซียส แล้วทำการปรับหัวเผาทุติยภูมิ
 - ในระหว่างที่ทำการเผาขยะ ถ้าเกิดกรณี CSS มีการแจ้งเตือนว่าอุณหภูมิของเตาเผาขยะทั้ง 2 ด้าน มีความแตกต่างกันมากกว่า 25 องศาเซลเซียส หรืออุณหภูมิของทรายต่ำกว่า 200 องศาเซลเซียส ซึ่งจะนำไปสู่การสูญเสียการเผาไหม้ที่สมบูรณ์ ดำเนินการดังนี้
 - ให้ป้อนขยะอย่างต่อเนื่องเพื่อรักษาอุณหภูมิของเตาเผาขยะและสภาวะการเผาไหม้ที่สมบูรณ์
 - ทำการตรวจสอบหัวจ่ายลม (Air Nozzle) และ พัดลมหลัก
 - ทำการตรวจสอบช่องจ่ายลม
 - ตรวจสอบค่าความแตกต่างของระดับในเตาเผาขยะ ซึ่งจะมีค่ามากถ้าหากปริมาณของทรายในเตาเผาขยะมากเกินไป รวมทั้งการจ่ายลมหลักน้อยเกินไป
 - ตรวจสอบระบบการหมุนเวียนของทรายในเตาเผาขยะ ถ้าหากมีข้อผิดพลาดอาจจะทำให้สูญเสียการเผาไหม้ที่สมบูรณ์
- ถ้าหากยังไม่สามารถแก้ไขให้การเผาไหม้กลับคืนมาสถานะที่สมบูรณ์ได้ ให้ทำการหยุดการปฏิบัติงานเตาเผาขยะ และทำการค้นหาสาเหตุ การแก้ไข และหาหนทางป้องกัน

4.2 หม้อน้ำ (Boiler)

- อากาศร้อนที่ออกจากเตาเผาขยะ ไหลเข้าสู่หม้อน้ำ ทำให้อุณหภูมิของอากาศร้อนลดลงอย่างรวดเร็ว จาก 900 องศาเซลเซียส ลงมาถึง 250 องศาเซลเซียส (ภายในระยะเวลาประมาณ 13 วินาที)
- ระดับน้ำในหม้อน้ำ (Boiler Drum) จะถูกควบคุมไว้ ที่ระดับ 50 มม. โดยการสูบน้ำจาก Boiler feed water pump
- ค่า pH ของน้ำ Boiler อยู่ระหว่าง 9.5 -11.5 ซึ่งควบคุมโดยปัมป์จ่ายสารเคมี
- ความดันใน Boiler Drum ตั้งค่าที่ 2.1 MPa

4.3 หอลดอุณหภูมิของก๊าซ (Gas Cooling Tower)

- หอลดอุณหภูมิของก๊าซ ทำหน้าที่ลดอุณหภูมิของอากาศร้อน ในช่วงระหว่าง 250-400 องศาเซลเซียส ลงมาถึงช่วงระหว่าง 160-200 องศาเซลเซียส ปริมาตรของหอลดอุณหภูมิของก๊าซ มีปริมาณมากเพียงพอที่สามารถรองรับปริมาณก๊าซที่เกิดจากการเผาไหม้ที่สมบูรณ์ ในช่วงความสามารถของการเผาขยะ
- น้ำที่พ่นออกมาเป็นฝอย พ่นเข้าสู่หอลดอุณหภูมิของก๊าซ โดยผ่านหัวสแตนเลส ซึ่งมีลมอัดที่ปลายท่อ ทำให้น้ำระเหยเป็นไอน้ำ ซึ่งปริมาณน้ำที่พ่นเข้าหอลดอุณหภูมิของก๊าซ ถูกควบคุมโดยอุณหภูมิที่ไหลผ่าน

| | |
|---|--------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-IN-S001T |
| เรื่อง: ขั้นตอนการควบคุมสภาวะการเผาไหม้และอุปกรณ์ที่เกี่ยวข้องกับระบบควบคุมมลพิษอากาศ | หน้าที่: 5 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกปฏิบัติการเตาเผา | วันที่: 14 ม.ค.63 |
| อนุมัติโดย: [REDACTED] | วันที่มีผลบังคับใช้: 20 ม.ค.63 |
| | แก้ไขครั้งที่: 8 |

4.4 ระบบการฉีด (Injection) ของ ปูนขาว และ ผงถ่านกัมมันต์

- Injection Blower จะให้แรงดันลมป้อนเข้าสู่ระบบตลอดเวลา แรงดันไม่เกิน < 0.03 MPa เพื่อป้องกันท่อของ Injection Blower อุดตัน
- การตรวจสอบทางกายภาพ จะต้องทำการตรวจสอบทุก ๆ กะ
- ตรวจสอบปริมาณการใช้ปูนขาว และ ผงถ่านกัมมันต์ ทุกวันโดยเฉพาะผงถ่านกัมมันต์ที่มีความสำคัญในการกำจัดไดออกซิน หากมีปริมาณไม่เพียงพอจะทำให้เกิดปัญหาได้ เช่น ปัญหาที่หัวฉีด (Injection feeder) และการอุดตันในเส้นท่อ โดยมีการตรวจสอบเส้นท่อและหัวฉีดด้านในอยู่เป็นประจำ
- การตรวจสอบหารอยรั่ว และการกีดร่อนของเครื่องจักร จะตรวจสอบทุกครั้งหลังจบการปฏิบัติงาน

4.5 ถุงกรองฝุ่น (Bag Filter)

- ความดันสูญเสียของระบบ สามารถตรวจดูและควบคุม ซึ่งไม่เกิน 2.5 kPa เพื่อป้องกันการอุดตันและการชำรุดเสียหายของถุงกรองฝุ่น
- อุณหภูมิของของทางเข้าและทางออกของถุงกรองฝุ่น ควบคุมไว้ที่ 160-200 องศาเซลเซียส เพื่อประสิทธิภาพและยืดอายุการใช้งานของถุงกรองฝุ่น
- อัตราการไหลของก๊าซ ไม่ควรเกิน 65,000 ลบ.ม.ต่อวินาที หากค่าความดันเพิ่มขึ้นในระบบ จะเป็นเหตุให้ถุงกรองฝุ่นชำรุด
- ระหว่างที่ลมอัดเข้าไปในถุงกรองฝุ่นเพื่อทำความสะอาด ค่าความดันจะไม่เกิน 0.3 – 0.5 MPa ถ้าหากความดันเกินกว่าค่าที่กำหนด จะมีสัญญาณเตือน
- การตรวจหารอยฉีกขาดของถุงกรองฝุ่น สามารถกระทำได้ปีละสองครั้ง หรือทุกครั้งที่หยุดใช้งาน
- จำนวนถุงกรองฝุ่นจะต้องมีสำรองไว้ไม่น้อยกว่า 10% ของจำนวนถุงกรองฝุ่นทั้งหมด เพื่อสามารถเปลี่ยนถุงกรองฝุ่นที่ชำรุดได้เพียงพอ

4.6 Wet Scrubber

- pH ของของเหลวที่ดูดซับก๊าซ จะอยู่ในช่วง 6 – 8 ค่าที่ตั้งไว้อยู่ที่ 7.2
- การตรวจสอบทางกายภาพเพื่อตรวจหาการกัดกร่อนของเครื่องจักร การรั่ว สามารถกระทำได้ทุกเดือนและทุกครั้งที่หยุดใช้งาน

4.7 ปล่องควัน

ทำหน้าที่กระจายอากาศร้อนสู่บรรยากาศ ณ ปล่องควันได้ทำการติดตั้งระบบ CEMS เพื่อติดตามผลค่าดังต่อไปนี้

- HCl ค่ามาตรฐานไม่เกิน 25 ppm
- SO₂ " " 30 ppm
- NO₂ " " 180 ppm
- Opacity " " 10 %
- O₂
- CO

| | |
|---|--------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-IN-S001T |
| เรื่อง: ขั้นตอนการควบคุมสภาวะการเผาไหม้และอุปกรณ์ที่เกี่ยวข้องกับระบบควบคุมมลพิษอากาศ | หน้าที่: 6 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกปฏิบัติการเตาเผา วันที่: 14 ม.ค.63 | วันที่มีผลบังคับใช้: 20 ม.ค.63 |
| อนุมัติโดย: [REDACTED] | แก้ไขครั้งที่: 8 |

4.8 ระบบบำบัดน้ำเสีย

- ระบบบำบัดน้ำเสียนี้ ได้ออกแบบสำหรับรับน้ำจาก Wet Scrubber, boiler และ Gas analyzer ระบบบำบัดน้ำเสียได้แบ่งขั้นตอนดังนี้ การตกตะกอนอย่างรวดเร็วโดยให้ สารเคมี Liquid chelate กรองผ่านทรายกรอง เพื่อแยกโลหะหนักและสารแขวนลอยออกจากน้ำ เกลือที่ปนอยู่ในน้ำจะทำให้เชื้อเพลิงโดยน้ำจาก make up tank ก่อนที่จะสูบต่อไปยัง discharge tank ส่วนกากตะกอนที่เกิดจากการบำบัดจะสูบไปยังบ่อพักขยะ
- Neutralization tank ค่า pH จะถูกควบคุมโดยวาล์วเติมสารเคมี กรด hydrochloric และ NaOH โดยจะควบคุม pH อยู่ระหว่าง 5.0 – 9.0

4.9 อุปกรณ์ผลิตไอน้ำ

4.9.1 Steam accumulator

- ตรวจสอบปะเก็นผ่านแมนโฮลและหน้างานสนิทกับหน้าสัมผัสทุกตัว
- ปิดฝาแมนโฮล
- ตรวจสอบสถานะของวาล์วก่อนจะใช้งาน
- เมื่อความดันเพิ่มขึ้นโดยปกติ ให้ทำการเปิดวาล์วข้างเข้า ๆ เพื่อให้ไอน้ำค่อย ๆ ไหลผ่านวาล์ว จนกระทั่งเปิดวาล์วจนสุด

4.9.2 Steam condenser

- ให้น้ำไหลผ่านทางเข้า Header และเกิดการกลั่นตัวไอน้ำที่ผ่านด้านบน 3 ชั้นของท่อของ condenser ไอน้ำที่กลั่นตัวจะผ่านด้านหลัง Header และไหลลงด้านล่างที่ท่อชั้นที่ 1 อุ่นหมุมมี ณ จุดนี้มีค่า 80 องศาเซลเซียส และไหลออกไปยัง Outlet Header

4.9.3 Deaerator

- ตรวจสอบวาล์วควบคุมระดับน้ำ ให้สอดคล้องการใช้งาน Boiler feed water pump
- เปิดวาล์วด้านหน้าและด้านหลังของวาล์วหลักของ Deaerator
- ปล่อน้ำออกจากท่อไอน้ำ
- ค่อย ๆ เปิดวาล์วควบคุมแรงดันอย่างช้า ๆ เพื่อให้ไอน้ำไหลผ่าน

| | |
|---|--------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-IN-S001T |
| เรื่อง: ขั้นตอนการควบคุมสภาวะการเผาไหม้และอุปกรณ์ที่เกี่ยวข้องกับระบบควบคุมมลพิษอากาศ | หน้าที่: 7 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกปฏิบัติการเตาเผา วันที่: 14 ม.ค.63 | วันที่มีผลบังคับใช้: 20 ม.ค.63 |
| อนุมัติโดย: [REDACTED] | แก้ไขครั้งที่: 8 |


4.10 สรุปการปฏิบัติการควบคุมส่วนต่าง ๆ

ตารางที่ 1 สรุปการปฏิบัติการควบคุม

| Item | Description | Monitor | Keep point | Max | Min | Unit | Remark |
|-----------------------------|----------------------------|----------------|------------|--------|--------|-----------------------|------------------------------------|
| 1 | Feeder | Speed | 350 | 800 | 200 | RPM | S-101 |
| | Primary air supply | Air | 13,500 | 16,500 | 12,500 | m ³ /h(N) | F-101_1 |
| | | VFD control | 45 | 48 | 42 | Hz | F-101_1 |
| | | Sand Diff. | 14 | 18 | 12 | kPa | Sand Pressure |
| | Secondary air supply | Air | 14,000 | 18,000 | 8,000 | m ³ /hr(N) | F-103_1 |
| | Fluidized Bed Temperature | Temperature | 645 | 700 | 550 | °C | T-101,T-102 |
| | In Furnace Temperature | Temperature | 850 | 950 | 800 | °C | T-103 |
| | Furnace Outlet Temperature | Temperature | 850 | 950 | 800 | °C | T-104 |
| Combustion Pressure (P-101) | Pressure | 1.6 | -0.6 | -1.2 | kPa | P-101_1 | |
| 2 | Boiler Drum | Pressure | 2.15 | 2.25 | 1.5 | Mpa | PCV-403-1 (1.5) PCV-403-2 (2.1) |
| | | Level of water | 50 | 250 | -150 | mm | L-403 |
| | | pH | 9.8 | 11.5 | 9.5 | | Q-401 |
| | | Conductivity | <50 | 50 | 0 | mS/m | Q-402 |
| 3 | Deaerator | Pressure | 280 | 340 | 240 | kPa | P-401 |
| | | Level of water | 30 | 150 | -150 | mm | L-402 |
| 4 | Gas cooling tower | Temperature | 280 | 400 | 120 | °C | T-105 |
| 5 | Bag filter | Temperature | 160 | 200 | 120 | °C | T-106 |
| | | Diff. Pressure | <2.5 | 3 | 0 | kPa | PDT-160 |
| 6 | Wet scrubber | pH | 7.2 | 8 | 6 | | QICA-241 |
| | | Diff. Pressure | <1.3 | 2.5 | 0 | kPa | PDT-241 |
| 7 | Stack | HCl | <25 | 25 | 0 | ppm | Q-101AVE |
| | | Nox | <180 | 180 | 0 | ppm | Q-102AVE |
| | | SO2 | <30 | 30 | 0 | ppm | Q-103AVE |
| | | CO | <100 | 115 | 0 | ppm | Q-106AVE |
| | | O2 | <14 | 14 | 0 | % | Q-104AVE |
| | | Opacity | <10 | 10 | 0 | % | Q-105AVE |

5. เอกสารอ้างอิง

- 5.1 Operation & Maintenance Manual for Whole Plant (1) – Revision 1, Manual No. 1
- 5.2 Furnace (Operation Procedure & Setting Methods) O-M Manual, Manual No. 7
- 5.3 Furnace (Combustion Support System) O-M Manual, Manual No. 7
- 5.4 Furnace (Summary Instruction) O-M Manual, Manual No. 7
- 5.5 Boiler O-M Manual

| | |
|---|--------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-IN-S001T |
| เรื่อง: ขั้นตอนการควบคุมสภาวะการเผาไหม้และอุปกรณ์ที่เกี่ยวข้องกับระบบควบคุมมลพิษอากาศ | หน้าที่: 8 จาก 8 หน้า |
| จัดเตรียมโดย: แผนกปฏิบัติการเตาเผา วันที่: 14 ม.ค.63 | วันที่มีผลบังคับใช้: 20 ม.ค.63 |
| อนุมัติโดย:  | แก้ไขครั้งที่: 8 |

5.6 Gas cooling tower O-M Manual

5.7 Lime & activated carbon injection system O-M Manual

5.8 Bag filter O-M Manual

5.9 Wet scrubber O-M Manual

5.10 Waste water treatment system O-M Manual

5.11 Deaerator, steam accumulator, steam condenser O-M Manual

6. ประมวลคำศัพท์

- ไม่มี

7. คำนิยาม

- ไม่มี

เอกสารแนบ 2-13

ตัวอย่างรายงานการตรวจสอบการทำงานของเครื่องจักร หรือ Daily Report

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Method | What | Criteria | Approach | How | Judge | Remark | | |
|----------------------------|------------------------|-----------------------|-------------|---------------|-------------------------|--------------------|--------------------|---------------------|------------------------------------|---------------------|-------------------|--|
| Crushing job | | | | | | | | | | | | |
| No.2 Crusher (M2) | Crucher hydraulic pump | Thermo meter | Visual | Temprature | <70℃ | Repair/Replacement | CBM | 30℃ | ※Usually 35～50℃ | | | |
| | | Oil tank level gauge | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | | | |
| | | Crusher control panel | Visual | Dust | No dusty | Cleaning | CBM | ○ | | | | |
| | Bulky Refuse CV No.2 | Apron conveyor | Current | Visual | Current | <550A | Trend management | CBM | 110A | ※Usually 100 ～ 150A | | |
| | | CV(M2) | | | | | | | | | | |
| Refuse tipping | Apron conveyor | Motor | Visual | Current | <28A | Trend management | CBM | 15A | ※Usually 16 ～ 20A | | | |
| Feeding Solid Waste System | | | | | | | | | | | | |
| Refuse charging CV(M3) | Apron conveyor | Cyclo speed-reducer | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | | | |
| | | Motor | Visual | Current | <28A | Trend management | CBM | 23 | ※Usually 20 ～ 24A, Direct feed 24A | | | |
| | | Roller chain | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | | | |
| | | Roller chain Sprocket | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | | | |
| | | Conveyor chain | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | | | |
| | | Rail | Visual | Condition | Wear | Repair/Replacement | CBM | ○ | | | | |
| | | Conveyor sprocket | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | | | |
| | | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | | | |
| | | Apron | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | | | |
| | | Blower | | | | | | | | | | |
| | | Purge Fan | Purge Fan | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 38℃ | ※Usually 39 ～ 50℃ | |
| Pressure gage | Visual | | | Prssure | ○～○kPa | Trend management | CBM | 5.4kPa | ※Usually 5.0kPa | | | |
| Motor | Visual | | | Current | <○A | Trend management | CBM | 10A | ※Usually 10A | | | |
| PAF | Primary Air Fan | Bearing× 2 | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 43℃ | ※Usually 56 ～ 60℃ | | | |
| | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | | | |
| | | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | | | | |
| SAF | Motor | Visual | Current | <300A | Trend management | CBM | 60A | ※Usually 55 ～ 60A | | | | |
| | | Bearing× 2 | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 38℃ | ※Usually 47 ～ 49℃ | | | |
| | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | | | |
| IDF | Motor | Visual | Current | <250A | Trend management | CBM | 70A | ※Usually 100 ～ 120A | | | | |
| | | Induced Draft Fan | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 45℃ | ※Usually 50 ～ 55℃ | | |
| | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | | | |
| Injection Pump No.3 | Pump | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | | | | |
| | | Visual | Current | <75A | Trend management | CBM | 40A | ※Usually 35 ～ 50A | | | | |
| | | Motor | Visual | Current | <75A | Trend management | CBM | 40A | | | | |

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Inspection | | | | | Judge | | Remark |
|---|----------------------------------|----------------------------------|------------------|---------------|-------------------------|-------------------------|----------|---------------|--------------|---|--------|
| | | | | Method | What | Criteria | Approach | How | | | |
| Sand Circulation & Discharge Bottom Ash | | | | | | | | | | | |
| | Control panel | | | Control panel | Visual | Dust | No dusty | Cleaning | CBM | ○ | |
| | Incombustible CV | | | | | | | | | | |
| | Screw CV | Bearing (Drive side) | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Bearing (Driven side) | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Rotary joints (Drive side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Rotary joints (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Flexible tube (Drive side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Flexible tube (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Thermometer | Visual | Temperature | <70℃ | Repair/Replacement | CBM | 48 | ※Usually 70℃ | | |
| | | Drive side sprocket (MOTOR SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | Drive side sprocket (Screw SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | Roller chain | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | Cyclo speed-reducer | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | | |
| | Motor | Visual | Current | <80% | Repair/Replacement | CBM | 70 | ※Usually 60% | | | |
| | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | | | | |
| | Vibrating Screen | | | | | | | | | | |
| | Vibrating Screen | Motor×2 | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | |
| | | Casing | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| Sand Make Up CV | | | | | | | | | | | |
| Bucket CV | Casing | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | | |
| | Motor | Visual | Current | <80% | Repair/Replacement | CBM | 40 | ※Usually 40% | | | |
| | | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | | |
| Sand Circulation CV(M8) | Bucket CV | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | | |
| | Motor×1 | Visual | Current | <80% | Repair/Replacement | CBM | 30 | ※Usually 30% | | | |
| | | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | | | |
| | Bearing×3 | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | Drive side sprocket (MOTOR SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | Drive side sprocket (Screw SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | Roller chain | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | Generator System | | | | | | | | | | |
| Cooling Fan for turbine cooling water | | | | | | | | | | | |
| Cooling Fan | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | | Visual | Noise | No noise | Repair/Replacement | CBM | ○ | | | | |
| | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | | |
| | | Visual | Current | <80% | Repair/Replacement | CBM | ○ | | | | |
| Measurement | vibration | <6.36mm/sec | Trend management | CBM | | A 4900. = 0.69-1.12 | | | | | |
| Water Supply | | | | | | | | | | | |
| Cooling Fan for any equipment cooling water | | | | | | | | | | | |
| Cooling Fan | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | | |
| | | Visual | Current | <80% | Repair/Replacement | CBM | ○ | | | | |
| | | Measurement | vibration | <6.36mm/sec | Repair/Replacement | CBM | | ※Usually 100% | | | |

BPEC -PM Maintenance Sheet (Daily)

☐ OK

☐ BAD

| Process | Equipment | Machine | Parts | Inspection | | | | | | Remark |
|---------------------|-----------|----------------------------|-----------------------|-------------|-------------|---------------|-------------------------|--------------------|-------|--------|
| | | | | Method | What | Criteria | Approach | How | Judge | |
| Discharging Fly Ash | | Dust feeder | Motor | Visual | Current | <80% | Repair/Replacement | CBM | | |
| | | | | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | |
| | | Dust distributing conveyor | Cyclo drive | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | |
| | | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | |
| | | | | Visual | Current | <80% | Repair/Replacement | CBM | | |
| | | | Bearing (Drive side) | Measurement | Temperature | <70 °C | Repair/Replacement | CBM | ○ | |
| | | | Bearing (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | |
| | | | | Measurement | Temperature | <70 °C | Repair/Replacement | CBM | ○ | |
| | | | Shaft | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | |
| | | | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ |

BPEC -PM Maintenance Sheet (Daily)

☐ OK

☐ BAD

[illegible]

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Method | What | Criteria | Approach | How | Judge | Remark |
|----------------------------|------------------------|-----------------------|---------------|-------------------------|-------------------------|-------------------------|--------------------|---------------------|------------------------------------|-------------------|
| Crushing job | | | | | | | | | | |
| No.2 Crusher (M2) | Crusher hydraulic pump | Thermo meter | Visual | Temperature | <70℃ | Repair/Replacement | CBM | 35℃ | ※Usually 35～50℃ | |
| | | | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | |
| | | | Visual | Dust | No dusty | Cleaning | CBM | ○ | | |
| Bulky Refuse | CV No.2 | Crusher control panel | Visual | Current | <550A | Trend management | CBM | 110A | ※Usually 100 ～ 150A | |
| | | | Visual | Current | <28A | Trend management | CBM | 17A | ※Usually 16 ～ 20A | |
| Feeding Solid Waste System | | | | | | | | | | |
| Refuse charging CV(M3) | Apron conveyor | Cyclo speed-reducer | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | |
| | | Motor | Visual | Current | <28A | Trend management | CBM | 18 | ※Usually 20 ～ 24A, Direct feed 24A | |
| | | Roller chain | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Roller chain Sprocket | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Conveyor chain | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Rail | Visual | Condition | Wear | Repair/Replacement | CBM | ○ | | |
| | | Conveyor sprocket | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | Apron | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Blower | | | | | | | | |
| Purge Fan | Purge Fan | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 39℃ | ※Usually 39 ～ 50℃ | |
| | | Pressure gage | Visual | Pressure | ○～○kPa | Trend management | CBM | 5.4kPa | ※Usually 5.0kPa | |
| | | Motor | Visual | Current | <○A | Trend management | CBM | 10A | ※Usually 10A | |
| PAF | Primary Air Fan | Bearing× 2 | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 48℃ | ※Usually 56～ 60℃ | |
| | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | |
| | | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | | |
| SAF | Motor | Visual | Current | <300A | Trend management | CBM | 60A | ※Usually 55 ～ 60A | | |
| | | Secondary Air Fan | Bearing× 2 | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 41℃ | ※Usually 47 ～ 49℃ |
| | | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| IDF | Motor | | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | |
| | | Visual | Current | <250A | Trend management | CBM | 70A | ※Usually 100 ～ 120A | | |
| | | Induced Draft Fan | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 49℃ | ※Usually 50 ～ 55℃ |
| Hearing | Noise | | No noise | Refueling / replacement | CBM | ○ | | | | |
| Visual | Oil | | In Level Gage | Lubrication | CBM | ○ | | | | |
| Injection Pump No.3 | Pump | Visual | Current | <75A | Trend management | CBM | 40A | ※Usually 35 ～ 50A | | |
| | | Visual | Liquid | No leaks | Repair/Replacement | CBM | ○ | | | |
| | | Visual | Current | <75A | Trend management | CBM | 40A | ※Usually 35 ～ 50A | | |

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Method | What | Criteria | Approach | How | Judge | Remark | |
|---|---------------------|----------------------------------|----------------------------------|--------------------|-------------------------|-------------------------|--------------------|--------------|---------------------|--------------|--|
| Sand Circulation & Discharge Bottom Ash | | | | | | | | | | | |
| | Control panel | | Control panel | Visual | Dust | No dusty | Cleaning | CBM | ○ | | |
| | Incombustible CV | | | | | | | | | | |
| | Screw CV | Bearing (Drive side) | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | | Rotary joints (Drive side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Rotary joints (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Flexible tube (Drive side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Flexible tube (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Thermometer | Visual | Temperature | <70℃ | Repair/Replacement | CBM | 56 | ※Usually 70℃ | |
| | | | Drive side sprocket (MOTOR SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Drive side sprocket (Screw SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Roller chain | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | Cyclo speed-reducer | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | | |
| | Motor | Visual | Current | <80% | Repair/Replacement | CBM | 70 | ※Usually 60% | | | |
| | | | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | | |
| | Vibrating Screen | | | | | | | | | | |
| | Vibrating Screen | Motor×2 | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | |
| | | Casing | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| Sand Make Up CV | Bucket CV | Casing | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | |
| | | Motor | Visual | Current | <80% | Repair/Replacement | CBM | 40 | ※Usually 40% | | |
| | | | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | | |
| | | Bearing | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | | | | | | | | | | |
| Sand Circulation CV(M8) | | | | | | | | | | | |
| | Bucket CV | Motor×1 | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | |
| | | | Visual | Current | <80% | Repair/Replacement | CBM | 30 | ※Usually 30% | | |
| | | | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | | |
| | | Bearing×3 | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Drive side sprocket (MOTOR SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Drive side sprocket (Screw SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| Roller chain | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | | |
| Generator System | | | | | | | | | | | |
| Cooling Fan for turbine cooling water | | | | | | | | | | | |
| | Cooling Fan | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Gear transmission | Visual | Noise | No noise | Repair/Replacement | CBM | ○ | | | |
| | | Couping | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | |
| | | | Visual | Current | <80% | Repair/Replacement | CBM | ○ | | | |
| | | | Measurement | vibration | <6.36mm/sec | Trend management | CBM | | A 4900. = 0.95-1.58 | | |
| Water Supply | | | | | | | | | | | |
| Cooling Fan for any equipment cooling water | | | | | | | | | | | |
| | Cooling Fan | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | V belt | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Pulley | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | |
| | | | Visual | Current | <80% | Repair/Replacement | CBM | ○ | | | |
| | | | Measurement | vibration | <6.36mm/sec | Repair/Replacement | CBM | ○ | | | |
| | | | Visual | Current | <○A | Trend management | CBM | 5.5 | ※Usually 100A | | |
| | | | | | | | | | | | |

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Inspection | | | | | Remark |
|---------------------|-----------|----------------------------|-----------------------|-------------|-------------|---------------|-------------------------|-----------|--------|
| | | | | Method | What | Criteria | Approach | How Judge | |
| Discharging Fly Ash | | Dust feeder | Motor | Visual | Current | <80% | Repair/Replacement | CBM | |
| | | | Cyclo drive | Visual | Oil | In Level Gage | Lubrication | CBM | |
| | | Dust distributing conveyor | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | |
| | | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | |
| | | | | Visual | Current | <80% | Repair/Replacement | CBM | |
| | | | Bearing (Drive side) | Measurement | Temperature | <70°C | Repair/Replacement | CBM | |
| | | | Bearing (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | | Measurement | Temperature | <70°C | Repair/Replacement | CBM | |
| | | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Shaft | Visual | Condition | Need Repair | Repair/Replacement | CBM | |

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Inspection | | | | | Remark |
|-------------|-----------|--------------------------|------------------|-------------|-----------------|---------------|-------------------------|-----------|--------|
| | | | | Method | What | Criteria | Approach | How Judge | |
| Fire Pump | | Control panel | Control panel | Visual | Dust | No dusty | Cleaning | CBM | |
| | | | | | | | | | |
| | | Battery | distilled water | Visual | distilled water | In Level Gage | filling | CBM | |
| | | | Pole | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Vent Plug | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Container3 & Lid | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | SOC | Measurement | % V | Need Repair | Repair/Replacement | CBM | |
| | | | SHO | Measurement | % V | Need Repair | Repair/Replacement | CBM | |
| | | | IR | Measurement | mΩ | Need Repair | Repair/Replacement | CBM | |
| | | | | | | | | | |
| | | | | | | | | | |
| Lime silo | | Injection blower (1),(2) | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | V belt | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Pulley | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | |
| | | | | Visual | Current | <80% | Repair/Replacement | CBM | |
| | | | | Measurement | vibration | <6.36mm/sec | Trend management | CBM | |
| | | | Control panel | Visual | Dust | No dusty | Cleaning | CBM | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Boiler | | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | | | | | | | |
| Gas cooling | | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| Bag filter | | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| Dust silo | | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| Process | Equipment | Machine | Parts | Method | What | Criteria | Approach | How | Judge | Remark |
|---|----------------------------------|----------------------------------|---------------|--------------------|-------------------------|-------------------------|-------------------------|-----|--------------|--------------------|
| Sand Circulation & Discharge Bottom Ash | | | | | | | | | | |
| Incombustible CV | Control panel | | Control panel | Visual | Dust | No dusty | Cleaning | CBM | ○ | |
| | Screw CV | Bearing (Drive side) | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Bearing (Driven side) | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Rotary joints (Drive side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Rotary joints (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Flexible tube (Drive side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Flexible tube (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Thermometer | Visual | Temperature | <70℃ | Repair/Replacement | CBM | 42 | | ※Usually 70℃ |
| | | Drive side sprocket (MOTOR SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | Drive side sprocket (Screw SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | Roller chain | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | |
| | Cyclo speed-reducer | Visual | Current | <80% | Repair/Replacement | CBM | 70 | | ※Usually 60% | |
| | Motor | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | | |
| | Vibrating Screen | | | | | | | | | |
| Sand Make Up CV | Vibrating Screen | | Motor×2 | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | |
| | | | Casing | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | |
| | Bucket CV | Casing | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | | Visual | Current | <80% | Repair/Replacement | CBM | 40 | | ※Usually 40% |
| Sand Circulation CV(MB) | | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| Bucket CV | Motor×1 | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | |
| | | Visual | Current | <80% | Repair/Replacement | CBM | 30 | | ※Usually 30% | |
| | Bearing×3 | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | | |
| | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | Drive side sprocket (MOTOR SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | Drive side sprocket (Screw SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| Roller chain | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | | |
| Generator System | | | | | | | | | | |
| Cooling Fan for turbine cooling water | | | | | | | | | | |
| Cooling Fan | Cooling Fan | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Gear transmission | Visual | Noise | No noise | Repair/Replacement | CBM | ○ | | |
| | | Coupling | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | | Visual | Current | <80% | Repair/Replacement | CBM | ○ | | |
| | | | Measurement | vibration | <6.36mm/sec | Trend management | CBM | | | A 4900. = 120-1.15 |
| Water Supply | | | | | | | | | | |
| Cooling Fan for any equipment cooling water | | | | | | | | | | |
| Cooling Fan | Cooling Fan | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | V belt | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Pulley | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | | Visual | Current | <80% | Repair/Replacement | CBM | ○ | | |
| | | | Measurement | vibration | <6.36mm/sec | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Current | <80% | Repair/Replacement | CBM | ○ | | |

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Inspection | | | | | Remark |
|---------------------|-----------|----------------------------|-----------------------|-------------|-------------|---------------|-------------------------|-----------|--------|
| | | | | Method | What | Criteria | Approach | How Judge | |
| Discharging Fly Ash | | Dust feeder | Motor | Visual | Current | <80% | Repair/Replacement | CBM | |
| | | | Cyclo drive | Visual | Oil | In Level Gage | Lubrication | CBM | |
| | | Dust distributing conveyor | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | |
| | | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | |
| | | | | Visual | Current | <80% | Repair/Replacement | CBM | |
| | | | Bearing (Drive side) | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | |
| | | | Bearing (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | |
| | | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Shaft | Visual | Condition | Need Repair | Repair/Replacement | CBM | |

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Inspection | | | | | Remark |
|-----------|-------------|--------------------------|------------------|-------------|-----------------|---------------|-------------------------|-----------|--------|
| | | | | Method | What | Criteria | Approach | How Judge | |
| Fire Pump | | Control panel | Control panel | Visual | Dust | No dusty | Cleaning | CBM | |
| | | | | | | | | | |
| | | Battery | distilled water | Visual | distilled water | In Level Gage | filling | CBM | |
| | | | Pole | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Vent Plug | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Container3 & Lid | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | SOC | Measurement | % V | Need Repair | Repair/Replacement | CBM | |
| | | | SHO | Measurement | % V | Need Repair | Repair/Replacement | CBM | |
| | | | IR | Measurement | mΩ | Need Repair | Repair/Replacement | CBM | |
| | | | | | | | | | |
| | | | | | | | | | |
| Lime silo | | Injection blower (1),(2) | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | V belt | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Pulley | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | |
| | | | | Visual | Current | <80% | Repair/Replacement | CBM | |
| | | | | Measurement | vibration | <6.36mm/sec | Trend management | CBM | |
| | | | Control panel | Visual | Dust | No dusty | Cleaning | CBM | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Boiler | | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | | | | | | | |
| | Gas cooling | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | | | | | | | |
| | Bag filter | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | | | | | | | |
| | Dust silo | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

BPEC -PM Maintenance Sheet (Daily)

☐ OK

| Process | Equipment | Machine | Parts | Method | What | Inspection Criteria | Approach | How | Judge | Remark |
|----------------------------|------------------------|-----------------------|-------------|-------------|----------------|-------------------------|----------|--------|----------------------------------|--------|
| Crushing job | | | | | | | | | | |
| No.2 Crusher (M2) | | | | | | | | | | |
| | Crusher hydraulic pump | Thermo meter | Visual | Temperature | <70℃ | Repair/Replacement | CBM | 39℃ | ※Usually 35～50℃ | |
| | | Oil tank level gauge | Visual | Oil | In Level Gauge | Lubrication | CBM | ○ | | |
| | Crusher cutter | Crusher control panel | Visual | Dust | No dusty | Cleaning | CBM | ○ | | |
| Bulky Refuse CV No.2 | | | | | | | | | | |
| | Apron conveyor | Current | Visual | Current | <550A | Trend management | CBM | 110A | ※Usually 100～150A | |
| Refuse tipping CV(M2) | | | | | | | | | | |
| | Apron conveyor | Motor | Visual | Current | <28A | Trend management | CBM | 18A | ※Usually 16～20A | |
| Feeding Solid Waste System | | | | | | | | | | |
| Refuse charge CV(M3) | | | | | | | | | | |
| | Apron conveyor | Cyclo speed-reducer | Visual | Oil | In Level Gauge | Lubrication | CBM | ○ | | |
| | | Motor | Visual | Current | <28A | Trend management | CBM | 18 | ※Usually 20～24A, Direct feed 24A | |
| | | Roller chain | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Roller chain Sprocket | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Conveyor chain | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Rail | Visual | Condition | Wear | Repair/Replacement | CBM | ○ | | |
| | | Conveyor sprocket | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | Apron | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| Blower | | | | | | | | | | |
| Purge Fan | | | | | | | | | | |
| | Purge Fan | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 47℃ | ※Usually 39～50℃ | |
| | | Pressure gage | Visual | Pressure | ○～0kPa | Trend management | CBM | 5.4kPa | ※Usually 5.0kPa | |
| | | Motor | Visual | Current | <OA | Trend management | CBM | 10A | ※Usually 10A | |
| PAF | | | | | | | | | | |
| | Primary Air Fan | Bearing× 2 | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 49℃ | ※Usually 56～60℃ | |
| | | Hearing | Visual | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | | Visual | Oil | In Level Gauge | Lubrication | CBM | ○ | | |
| | | Motor | Visual | Current | <300A | Trend management | CBM | 60A | ※Usually 55～60A | |
| SAF | | | | | | | | | | |
| | Secondary Air Fan | Bearing× 2 | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 43℃ | ※Usually 47～49℃ | |
| | | Hearing | Visual | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | | Visual | Oil | In Level Gauge | Lubrication | CBM | ○ | | |
| | | Motor | Visual | Current | <250A | Trend management | CBM | 70A | ※Usually 100～120A | |
| IDF | | | | | | | | | | |
| | Induced Draft Fan | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 51℃ | ※Usually 50～55℃ | |
| | | Hearing | Visual | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | | Visual | Oil | In Level Gauge | Lubrication | CBM | ○ | | |
| | | Motor | Visual | Current | <75A | Trend management | CBM | 40A | ※Usually 35～50A | |
| Injection Pump No.3 | | | | | | | | | | |
| | Pump | Pump | Visual | Liquid | No leaks | Repair/Replacement | CBM | ○ | | |

BPEC -PM Maintenance Sheet (Daily)

☐ OK

☐ BAD

| Process | Equipment | Machine | Parts | Method | What | Inspection Criteria | Approach | How | Judge | Remark |
|---|---------------|----------------------------------|------------------|--------------------|--------------------|-------------------------|----------|---------------|-------|--------------|
| Sand Circulation & Discharge Bottom Ash | | | | | | | | | | |
| Incombustible CV | Control panel | | Control panel | Visual | Dust | No dusty | Cleaning | CBM | ○ | |
| | Screw CV | Bearing (Drive side) | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | Bearing (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Rotary joints (Drive side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Rotary joints (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Flexible tube (Drive side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Flexible tube (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Thermometer | Visual | Temperature | <70℃ | Repair/Replacement | CBM | 45 | | ※Usually 70℃ |
| | | Drive side sprocket (MOTOR SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Drive side sprocket (Screw SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Roller chain | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Cyclo speed-reducer | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| Motor | Visual | Current | <80% | Repair/Replacement | CBM | 70 | | ※Usually 60% | | |
| Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | | | | |
| Vibrating Screen | | Motor×2 | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| Vibrating Screen | | Casing | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| Sand Make Up CV | Bucket CV | Casing | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | | Visual | Current | <80% | Repair/Replacement | CBM | 40 | | ※Usually 40% |
| | | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| Sand Circulation CV(MB) | | | | | | | | | | |
| Bucket CV | Motor×1 | Bearing×3 | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | | Visual | Current | <80% | Repair/Replacement | CBM | 30 | | ※Usually 30% |
| | | | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | Drive side sprocket (MOTOR SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Drive side sprocket (Screw SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| Generater System | | | | | | | | | | |
| Cooling Fan for turbine cooling water | | | | | | | | | | |
| Cooling Fan | Cooling Fan | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Gear transmission | Visual | Noise | No noise | Repair/Replacement | CBM | ○ | | |
| | | Couping | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | Visual | Current | <80% | Repair/Replacement | CBM | ○ | | | |
| Measurement | vibration | <6.36mm/sec | Trend management | CBM | | A 4900 =0.94-1.16 | | | | |
| Water Supply | | | | | | | | | | |
| Cooling Fan for any equipment cooling water | | | | | | | | | | |
| Cooling Fan | Cooling Fan | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | V belt | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Pulley | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | Visual | Current | <80% | Repair/Replacement | CBM | ○ | | | |
| | | Measurement | vibration | <6.36mm/sec | Repair/Replacement | CBM | | | | |
| | | Visual | Current | <0A | Trend management | CBM | 5.5 | ※Usually 100A | | |

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Inspection | | | | | Remark |
|---------------------|-----------|----------------------------|-----------------------|-------------|-------------|---------------|-------------------------|-----------|--------|
| | | | | Method | What | Criteria | Approach | How Judge | |
| Discharging Fly Ash | | Dust feeder | Motor | Visual | Current | <80% | Repair/Replacement | CBM | |
| | | | Cyclo drive | Visual | Oil | In Level Gage | Lubrication | CBM | |
| | | Dust distributing conveyor | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | |
| | | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | |
| | | | | Visual | Current | <80% | Repair/Replacement | CBM | |
| | | | Bearing (Drive side) | Measurement | Temperature | <70°C | Repair/Replacement | CBM | |
| | | | Bearing (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | | Measurement | Temperature | <70°C | Repair/Replacement | CBM | |
| | | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Shaft | Visual | Condition | Need Repair | Repair/Replacement | CBM | |

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Inspection | | | | | Remark |
|-------------|-----------|--------------------------|------------------|-------------|-----------------|---------------|-------------------------|-----------|--------|
| | | | | Method | What | Criteria | Approach | How Judge | |
| Fire Pump | | Control panel | Control panel | Visual | Dust | No dusty | Cleaning | CBM | |
| | | | | | | | | | |
| | | Battery | distilled water | Visual | distilled water | In Level Gage | filling | CBM | |
| | | | Pole | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Vent Plug | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Container3 & Lid | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | SOC | Measurement | % V | Need Repair | Repair/Replacement | CBM | |
| | | | SHO | Measurement | % V | Need Repair | Repair/Replacement | CBM | |
| | | | IR | Measurement | mΩ | Need Repair | Repair/Replacement | CBM | |
| | | | | | | | | | |
| | | | | | | | | | |
| Lime silo | | Injection blower (1),(2) | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | V belt | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Pulley | Visual | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | |
| | | | | Visual | Current | <80% | Repair/Replacement | CBM | |
| | | | | Measurement | vibration | <6.36mm/sec | Trend managemnt | CBM | |
| | | | Control panel | Visual | Dust | No dusty | Cleaning | CBM | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Boiler | | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | | | | | | | |
| Gas cooling | | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| Bag filter | | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| Dust silo | | Relay Knockor | Air Knockor | Hearing | Condition | Need Repair | Repair/Replacement | CBM | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Method | What | Criteria | Approach | How | Judge | Remark |
|----------------------------|------------------------|-----------------------|-------------|-------------|---------------|-------------------------|----------|--------|------------------------------------|--------|
| Crushing job | | | | | | | | | | |
| No.2 Crusher (M2) | Crusher hydraulic pump | Thermo meter | Visual | Temperature | <70℃ | Repair/Replacement | CBM | 45℃ | ※Usually 35～50℃ | |
| | | Oil tank level gauge | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | |
| | | Crusher control panel | Visual | Dust | No dusty | Cleaning | CBM | ○ | | |
| Bulky Refuse | CV No.2 | | | | | | | | | |
| Refuse tipping | Apron conveyor | Current | Visual | Current | <550A | Trend management | CBM | 110A | ※Usually 100 ～ 150A | |
| | CV(M2) | Motor | Visual | Current | <28A | Trend management | CBM | 19A | ※Usually 16 ～ 20A | |
| Feeding Solid Waste System | | | | | | | | | | |
| Refuse charging CV(M3) | Apron conveyor | Cyclo speed-reducer | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | |
| | | Motor | Visual | Current | <28A | Trend management | CBM | 16 | ※Usually 20 ～ 24A, Direct feed 24A | |
| | | Roller chain | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Roller chain Sprocket | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Conveyor chain | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Rail | Visual | Condition | Wear | Repair/Replacement | CBM | ○ | | |
| | | Conveyor sprocket | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | Apron | Visual | Condition | Need repair | Repair/Replacement | CBM | ○ | | |
| | | | | | | | | | | |
| Blower | | | | | | | | | | |
| Purge Fan | Purge Fan | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 44℃ | ※Usually 39 ～ 50℃ | |
| | | Pressure gage | Visual | Pressure | ○～○kPa | Trend management | CBM | 5.4kPa | ※Usually 5.0kPa | |
| | | Motor | Visual | Current | <○A | Trend management | CBM | 10A | ※Usually 10A | |
| PAF | Primary Air Fan | Bearing× 2 | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 57℃ | ※Usually 56～ 60℃ | |
| | | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | |
| SAF | Secondary Air Fan | Bearing× 2 | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 46℃ | ※Usually 47 ～ 49℃ | |
| | | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | |
| IDF | Induced Draft Fan | Bearing | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | 50℃ | ※Usually 50 ～ 55℃ | |
| | | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | |
| Injection Pump No.3 | Pump | Motor | Visual | Current | <75A | Trend management | CBM | 40A | ※Usually 35 ～ 50A | |
| | | Pump | Visual | Liquid | No leaks | Repair/Replacement | CBM | ○ | | |

BPEC -PM Maintenance Sheet (Daily)

○ OK
× BAD

| Inspection Date : | | |
|-------------------|-----------|-----------|
| Authorizer | Confirmer | Inspector |
| | | |

| Process | Equipment | Machine | Parts | Method | What | Criteria | Approach | How | Judge | Remark |
|---|----------------------------------|----------------------------------|------------------|-------------|-------------------------|-------------------------|----------|---------------|--------------|--------|
| Sand Circulation & Discharge Bottom Ash | | | | | | | | | | |
| Incombustible CV | Control panel | | Control panel | Visual | Dust | No dusty | Cleaning | CBM | ○ | |
| | Screw CV | Bearing (Drive side) | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Bearing (Driven side) | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Rotary joints (Drive side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Rotary joints (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Flexible tube (Drive side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Flexible tube (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Thermometer | Visual | Temperature | <70℃ | Repair/Replacement | CBM | 40 | ※Usually 70℃ | |
| | | Drive side sprocket (MOTOR SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | Drive side sprocket (Screw SIDE) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | Roller chain | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | |
| | Cyclo speed-reducer | Visual | Current | <80% | Repair/Replacement | CBM | 70 | ※Usually 60% | | |
| Motor | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | | | | |
| Vibrating Screen | | | | | | | | | | |
| Vibrating Screen | Motor×2 | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | | |
| | Casing | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| Sand Make Up CV | | | | | | | | | | |
| Bucket CV | Casing | Motor | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | Bearing | Visual | Current | <80% | Repair/Replacement | CBM | 40 | ※Usually 40% | |
| | | | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | |
| Bucket CV | Motor×1 | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Visual | Current | <80% | Repair/Replacement | CBM | 30 | ※Usually 30% | | |
| Bearing×3 | Visual | Measurement | Temperature | <70℃ | Repair/Replacement | CBM | ○ | | | |
| | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| Drive side sprocket (MOTOR SIDE) | Visual | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| Drive side sprocket (Screw SIDE) | Visual | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | | |
| Generator System | | | | | | | | | | |
| Cooling Fan for turbine cooling water | | | | | | | | | | |
| Cooling Fan | Cooling Fan | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Gear transmission | Visual | Noise | No noise | Repair/Replacement | CBM | ○ | | |
| | | Couping | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | Visual | Current | <80% | Repair/Replacement | CBM | ○ | | | |
| Measurement | vibration | <6.36mm/sec | Trend management | CBM | | A 4900. = 0.96-1.29 | | | | |
| Water Supply | | | | | | | | | | |
| Cooling Fan for any equipment cooling water | | | | | | | | | | |
| Cooling Fan | Cooling Fan | Frame | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | V belt | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Pulley | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | | |
| | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | | |
| | | Visual | Current | <80% | Repair/Replacement | CBM | ○ | | | |
| | | Measurement | vibration | <6.36mm/sec | Repair/Replacement | CBM | ○ | | | |
| | | Visual | Current | <○A | Trend management | CBM | 5.5 | ※Usually 100A | | |

BPEC -PM Maintenance Sheet (Daily)

☐ OK

☐ BAD

| Process | Equipment | Machine | Parts | Inspection | | | | | | Remark |
|---------------------|-----------|----------------------------|-----------------------|-------------|-------------|---------------|-------------------------|--------------------|-------|--------|
| | | | | Method | What | Criteria | Approach | How | Judge | |
| Discharging Fly Ash | | Dust feeder | Motor | Visual | Current | <80% | Repair/Replacement | CBM | | |
| | | | | Visual | Oil | In Level Gage | Lubrication | CBM | ○ | |
| | | Dust distributing conveyor | Cyclo drive | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | |
| | | | Motor | Hearing | Noise | No noise | Refueling / replacement | CBM | ○ | |
| | | | | Visual | Current | <80% | Repair/Replacement | CBM | | |
| | | | Bearing (Drive side) | Measurement | Temperature | <70 °C | Repair/Replacement | CBM | ○ | |
| | | | Bearing (Driven side) | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | |
| | | | | Measurement | Temperature | <70 °C | Repair/Replacement | CBM | ○ | |
| | | | Shaft | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ | |
| | | | | | Visual | Condition | Need Repair | Repair/Replacement | CBM | ○ |

BPEC -PM Maintenance Sheet (Daily)

☐ OK

☐ BAD

[illegible]

เอกสารแนบ 2-14

แผนผังพื้นที่สีเขียวภายในโครงการ

รูปที่ 6 รูปตัดพื้นที่สีเขียวและแนวกันชนของโครงการฯ



ลงชื่อ.....

กรรมการผู้จัดการ

บริษัท บางปู เอ็นไวรอนเม้นทอล คอมพลีซ จำกัด (BPEC)

กรกฎาคม 2565
หน้า 117/122

ลง

ผู้อำนวยการ

บริษัท ไฟร์เทียร์ คอนซัลแตนต์ จำกัด



เอกสารแนบ 2-15

ผลการทดสอบประสิทธิภาพถ่านกัมมันต์

Test Report

Report No. : RE24-04-074_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex Co., Ltd.
Address : 965 Bangpoo Industrial Estate, Soi 3 Moo 2, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn, Samutprakarn 10280

Sample Description

Sample No. : LA24-04-177
Sample Name : Used Activated Carbon
Waste Profile No. : WPH66525
Manifest No. : -
Sampling By : Thanet S. (๓-212-๙-0002)

Sampling Date : 05/04/2024
Sampling Time : -
Sampling Received Date : 19/04/2024
Sample Test Date : 19/04/2024
Report Date : 29/04/2024

| Test Parameter* | Method | Unit | Result |
|--|---------------------------------|-------|--------|
| Heating Value (Gross Calorific Value) | Bomb Calorimetry ^[1] | cal/g | 4,687 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|------|------|--------|
| Arsenic (As) | Digestion, ICP Method ^[2,3] | mg/kg | 12.1 | 0.90 | 5.00 | ≤500 |
| Cadmium (Cd) | Digestion, ICP Method ^[2,3] | mg/kg | <2.00 | 0.50 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[2,3] | mg/kg | 1,411 | 0.40 | 2.00 | ≤2,500 |
| Copper (Cu) | Digestion, ICP Method ^[2,3] | mg/kg | 46.5 | 1.20 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[2,3] | mg/kg | 8.98 | 1.40 | 2.00 | ≤1,000 |
| Mercury (Hg) | Digestion, Cold-Vapor AAS Method ^[2,4] | mg/kg | 2.81 | 0.08 | 0.10 | ≤20 |
| Nikel (Ni) | Digestion, ICP Method ^[2,3] | mg/kg | 263 | 0.30 | 2.00 | ≤2,000 |
| Zinc (Zn) | Digestion, ICP Method ^[2,3] | mg/kg | 20.3 | 2.80 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] American Society for Testing and Materials. D5468-02, Standard Test Method for Gross Calorific and Ash Value of Waste Materials.

^[2] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[3] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010D, 2007

^[4] United States Environmental Protection Agency. Mercury in Solid or Semisolid Waste (Manual Cold-Vapor technique).


SW-846 Method 7471B, 2007

TTL = Total Threshold Limit Concentration.


LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : 
Thida Krongthong
Chemist
(๓-212-๙-0005)



Reviewed By : 
Kansuda Maneewong
Senior Laboratory Supervisor
(๓-212-๙-0001)

Test Report

Report No. : RE24-04-074_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex Co., Ltd.
Address : 965 Bangpoo Industrial Estate, Soi 3 Moo 2, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn, Samutprakarn 10280

Sample Description

Sample No. : LA24-04-177
Sample Name : Used Activated Carbon
Waste Profile No. : WPH66525
Manifest No. : -
Sampling By : Thanet S. (๓-212-๙-0002)

Sampling Date : 05/04/2024
Sampling Time : -
Sampling Received Date : 19/04/2024
Sample Test Date : 19/04/2024
Report Date : 29/04/2024

STLC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|------|--------|--------|--------|------|
| Arsenic (As) | Waste Extraction, Digestion, ICP Method ^[1,2] | mg/L | <0.05 | 0.016 | 0.05 | ≤5 |
| Cadmium (Cd) | Waste Extraction, Digestion, ICP Method ^[1,2] | mg/L | <0.02 | 0.001 | 0.02 | ≤1 |
| Chromium (Cr) | Waste Extraction, Digestion, ICP Method ^[1,2] | mg/L | 6.60 | 0.009 | 0.02 | ≤5 |
| Copper (Cu) | Waste Extraction, Digestion, ICP Method ^[1,2] | mg/L | ND | 0.008 | 0.02 | ≤25 |
| Lead (Pb) | Waste Extraction, Digestion, ICP Method ^[1,2] | mg/L | 0.02 | 0.007 | 0.02 | ≤5 |
| Mercury (Hg) | Waste Extraction, Cold-Vapor AAS Method ^[1,3] | mg/L | 0.0277 | 0.0002 | 0.0005 | ≤0.2 |
| Nikel (Ni) | Waste Extraction, Digestion, ICP Method ^[1,2] | mg/L | 13.4 | 0.039 | 0.05 | ≤20 |
| Zinc (Zn) | Waste Extraction, Digestion, ICP Method ^[1,2] | mg/L | 0.86 | 0.042 | 0.05 | ≤250 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] The Notification of Ministry of Industry, Subject: Disposal of wastes or unusable materials, B.E. 2566 (2023).

^[2] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996


^[3] United States Environmental Protection Agency. Mercury in Liquid Waste (Manual Cold-Vapor technique). SW-846 Method 7470A, 1994

STLC = Soluble Threshold Limit Concentration.


LOQ = Level of Quantitation.

MDL = Method Detection Limit.

ND = Not detected.

Reported By : 
Thida Krongthong
Chemist
(๓-212-๙-0005)



Reviewed By : 
Kansuda Maneewong
Senior Laboratory Supervisor
(๓-212-๙-0001)

Test Report

Report No. : RE24-04-074_3
Revision No. : 0

Customer Name : Bangpoo Environmental Complex Co., Ltd.
Address : 965 Bangpoo Industrial Estate, Soi 3 Moo 2, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn, Samutprakarn 10280


Sample Description

Sample No. : LA24-04-177
Sample Name : Used Activated Carbon
Waste Profile No. : WPH66525
Manifest No. : -
Sampling By : Thanet S.
Sampling Date : 05/04/2024
Sampling Time : -
Sampling Received Date : 19/04/2024
Sample Test Date : 19/04/2024
Report Date : 29/04/2024


| Test Parameter | Method | Result |
|----------------------------|------------------|---------------------------------------|
| Finger print test | | |
| Physical Appearance | ASTM D4979-08 | Dark gray and dark green |
| - Color | | - |
| - Turbidity | | - |
| - Viscosity | | - |
| - Layering | | Homogeneous |
| - Odor | | Slightly |
| - State | | Solid (Granular; Dry) |
| pH | ASTM D4980-89 | 5 |
| Temperature | Thermometer | 28.9 |
| Stability&Miscibility with | ASTM D5232-19 | |
| - Air | | Negative |
| - Water | | Negative (Insoluble and 100% sinking) |
| - Acid | | Negative |
| - Base | | Negative |
| - Leachate | | Negative |
| Oxidizer | ASTM D4981-19 | Negative |
| Ignitability Potential | ASTM D4982-20 | Positive (After 15 second) |
| Cyanide | Cyanide Test Kit | Not Available |
| Sulfide | ASTM D4978-16 | Negative |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : 
Thida Krongthong
Chemist
(29 / 04 / 2024)



Reviewed By : 
Kansuda Maneewong
Senior Laboratory Supervisor
(29 / 04 / 2024)

Test Report

Report No. : RE24-04-074_4
Revision No. : 0

Customer Name : Bangpoo Environmental Complex Co., Ltd.
Address : 965 Bangpoo Industrial Estate, Soi 3 Moo 2, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn, Samutprakarn 10280

Sample Description

Sample No. : LA24-04-177
Sample Name : Used Activated Carbon
Waste Profile No. : WPH66525
Manifest No. : -
Sampling By : Thanet S.
Sampling Date : 05/04/2024
Sampling Time : -
Sampling Received Date : 19/04/2024
Sample Test Date : 19/04/2024
Report Date : 29/04/2024

| Test Parameter | Method | Unit | Result |
|-----------------------------|--|-------------------|--------|
| Ash Content (as received) | Dried at 700°C | %(w/w) | 8.3 |
| Bulk Density | ASTM D5057-17 Bulk Density of waste | g/cm ³ | 0.6725 |
| Chloride (Cl ⁻) | EPA 5050 and EPA 9253 Chloride by Bomb | %(w/w) | 1.14 |
| Flash Point | ASTM D3278-78 Closed cup Method | °C | >110 |
| Moisture Content | ASTM D2216-19 ; Dried overnight @110±5°C | %(w/w) | 22.6 |
| Sulfur (S) | Digestion, ICP Method ^[1, 2] | %(w/w) | 1.68 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.


Remark : ^[1] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996


^[2] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010D, 2007


ASTM = American Society for Testing and Materials.

EPA = U.S. Environmental Protection Agency.

ND = Not detected.

Reported By : 
Thida Krongthong
Chemist
(29 / 04 / 2024)



Reviewed By : 
Kansuda Maneewong
Senior Laboratory Supervisor
(29 / 04 / 2024)



TEST REPORT

Sample's name Mark/Brand Laboratory No.
Activated carbon (15 Jan 2024) - L67/00479.1

Test Result

| | |
|-------------------------------------|---|
| Characteristics, | Black granular without any visible impurities |
| Iodine number, mg/g | 739 |
| Moisture, % | 23.0 |
| Apparent density, g/cm ³ | 0.49 |
| Ball pan hardness number, % | 98.4 |
| Particle size distribution, Mesh | 4x8 |
| - Retained on sieve # 4, % | 2.94 |
| - Passing through sieve # 8, % | 2.52 |

Customer's name Bangpoo Environmental Complex Co.,Ltd.
Customer's address 965 Moo 2 Soi 3B Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn, Samutprakarn 10280

Sample's description




Test date 17 – 31 January 2024
Test Method ASTM : Activated carbon, 2023, Volume 15.01

Approved by


(Ms. Saijit Daosukho)

Scientist, Senior Professional Level

Reported By


(Mr. Mathee Krongpong)

Scientist

แบบ จศ.7



No. 0302/ 1756

To Bangpoo Environmental Complex Co.,Ltd.

The Department of Science Service presents the test report for the sample named "Activated carbon (15 Jan 2024)" Laboratory No.L67/00479.1 as the total of 1 sample with reference to the request No.L67/00479 dated 16 January 2024.

Enclosed herewith the following result avails for your acknowledgement



Community Technology Division

Tel. 0 2201 7372

Fax 0 2201 7102

E-mail : bct@dss.go.th

เอกสารแนบ 2-16

แผนการซ่อมบำรุง ประจำปี 2568

Main MN job schedule for Feb-2025

[illegible]

Main MN job schedule for Feb-2025

[illegible]

Main MN job schedule for Mar-2025

[illegible]

Main MN job schedule for Mar-2025

[illegible]

Maintenance shutdown plan on Apr11-17,2025

[illegible]

Maintenance shutdown plan on Apr11-17,2025

| | | | | | | | | | | | | | | | | | | | | | | | Plan | Actual | | |
|------------------------------|---|---------------|----------|-------------------------|--------|--------|-----------|--------|--------|-----------|--------|--------|-----------|--------|--------|-----------|--------|--------|-----------|--------|--------|-----------|--------|--------|--|-----|
| Equipment | Job | Supplier | Progress | 11-Apr-25 | | | 12-Apr-25 | | | 13-Apr-25 | | | 14-Apr-25 | | | 15-Apr-25 | | | 16-Apr-25 | | | 17-Apr-25 | | | | PIC |
| | | | | 8:00~ | 16:00~ | 24:00~ | 8:00~ | 16:00~ | 24:00~ | 8:00~ | 16:00~ | 24:00~ | 8:00~ | 16:00~ | 24:00~ | 8:00~ | 16:00~ | 24:00~ | 8:00~ | 16:00~ | 24:00~ | 8:00~ | 16:00~ | 24:00~ | | |
| | | | | # 5:00AM stop crane job | | | | | | | | | | | | | | | | | | | | | | |
| CEMs system | PM third time | Kiss industry | 0% | | | | | | | | | | | | | | | | | | | | | | | |
| Wet Scrubber | Repair structure and spray pipe ※Media purchase as spare parts | NGE | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| ACAT | Open top of MH and check inside condition | PET | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| Stack | Repair Stage for Service Stack Work | NGE | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| | Repair Foundation Stack Work | | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| Motor | OH 25kw motor | SM Industrial | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| | Condensate pump No.1&2 15kw | | 50% | | | | | | | | | | | | | | | | | | | | | | | |
| Flow meter | Calibration steam flow meter for Thai Nissin | YOKOGAWA | 0% | | | | | | | | | | | | | | | | | | | | | | | |
| Pressure Transmitter | Calibration ACAT depressure transmitter 2 sets | | 0% | | | | | | | | | | | | | | | | | | | | | | | |
| | Gas cooling water and liquid Haz line Zsets | | 0% | | | | | | | | | | | | | | | | | | | | | | | |
| Electrical room 2nd floor | Clean up inverter IDF panel | TMEIC | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| Power generatoor | Switch 52B gear and other... | Intellect | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| Transport yard | Mobile crane truck 60 tons | KBL Crane | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Heavy oil pipe loop | Change new rubber gasket size 1" Solvent pipe | MN Team | 70% | | | | | | | | | | | | | | | | | | | | | | | |
| Refuse tipping conveyor | Add install new Manhole at left side casing. | MN Team | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| Boiler flap damper no.2 | Repair install steel tray under side area. | MN Team | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| AFR Tank no.2 | Install Blind flange Liquid waste water pipe size 2" beside | MN Team | 0% | | | | | | | | | | | | | | | | | | | | | | | |
| Bunker A area | Change new Steam trap 3 set in front of side | MN Team | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| Acroase charging conveyor | Install Water spray nozzle pipe on top side | MN Team | 0% | | | | | | | | | | | | | | | | | | | | | | | |
| Waste water treatment | Install new Filtering pump no.2 | MN Team | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| Refuse Crane room 4th floor. | Inspection clean up Magnetic contactor | MN Team | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| Feeder panel 6th floor | Inspection tighten terminal magnetic | MN Team | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| Filtering pump no.2 | Change upside Overload relay | MN Team | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| CCR Room | PM clean up Supervisory no.1 and no.2 | MN Team | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| Service Air Comp. no.2 | Change Auto drain is Ball valve 1/2" | MN Team | 0% | | | | | | | | | | | | | | | | | | | | | | | |
| Injection water no.2 | Change Ball valve size 2"and 1" water bypass pipe. | MN Team | 100% | | | | | | | | | | | | | | | | | | | | | | | |
| Liquid feeding line | Additional install spray nozzle 4 point 5 floor | MN Team | 100% | | | | | | | | | | | | | | | | | | | | | | | |

Maintenance shutdown plan on Apr11-17,2025

| Equipment | Job | Supplier | Progress | <div><div></div><div>Plan</div><div>Actual</div></div> | | | | | | | | | | | | | | | | | | PIC | | | |
|-----------|-----|----------|-----------------|--|--------|--------|-----------|--------|--------|-----------|--------|--------|-----------|--------|--------|-----------|--------|--------|-----------|--------|--------|-----|-----------|--------|--------|
| | | | | 11-Apr-25 | | | 12-Apr-25 | | | 13-Apr-25 | | | 14-Apr-25 | | | 15-Apr-25 | | | 16-Apr-25 | | | | 17-Apr-25 | | |
| | | | | 8:00~ | 16:00~ | 24:00~ | 8:00~ | 16:00~ | 24:00~ | 8:00~ | 16:00~ | 24:00~ | 8:00~ | 16:00~ | 24:00~ | 8:00~ | 16:00~ | 24:00~ | 8:00~ | 16:00~ | 24:00~ | | 8:00~ | 16:00~ | 24:00~ |
| | | | | ▲ 5:00AM stop crane job | | | | | | | | | | | | | | | | | | | | | |
| | | | | Electrical shutoff half day | | | | | | | | | | | | | | | | | | | | | |
| | | | MN team Total | 8 | | | 8 | | | 7 | | | 8 | | | 8 | | | 7 | | | 8 | | | |
| | | | Thainbask | ○ | | ○ | | | | | | ○ | | ○ | | ○ | | | ○ | | ○ | | | | |
| | | | Khendakal | ○ | | ○ | | | | | | | | ○ | | ○ | | | ○ | | ○ | | | | |
| | | | Sunchai | ○ | | ○ | | | | | | | | | | ○ | | | ○ | | ○ | | | | |
| | | | Chakarn | ○ | | ○ | | | | | | | | ○ | | ○ | | | ○ | | ○ | | | | |
| | | | Worajod | ○ | | ○ | | | | | | | | ○ | | ○ | | | ○ | | ○ | | | | |
| | | | Ketsak | ○ | | ○ | | | | | | | | ○ | | ○ | | | ○ | | ○ | | | | |
| | | | Chanchai | ○ | | ○ | | | | | | | | ○ | | ○ | | | ○ | | ○ | | | | |
| | | | Hand | ○ | | ○ | | | | | | | | ○ | | ○ | | | ○ | | ○ | | | | |
| | | | Yofu | ○ | | ○ | | | | | | | ○ | | ○ | | | ○ | | ○ | | | | | |
| | | | ○ = Holiday | | | | | | | | | | | | | | | | | | | | | | |
| | | | ○ = Working | | | | | | | | | | | | | | | | | | | | | | |
| | | | ● = Night shift | | | | | | | | | | | | | | | | | | | | | | |

เอกสารแนบ 2-17

ผลการสอบเทียบ CEMS ประจำปี 2568

| | |
|--------------------------|------------|
| Calibration record sheet | 19/04/2025 |
|--------------------------|------------|

Customer: BANGPOO ENVIROMENTAL COMPLEX CO., LTD
Address: 965 Moo 2, Bangpoo Industrial Estate, Sukhumvit Road
 Soi 3 T. Bang Pu Mai A. Muang Samut Prakan 10280

| | |
|--------------------------------|-------------------------------|
| Equipment Details: | Measurement Parameter |
| Device: MCS100E - HW | Ambient temperature: 25 deg C |
| Manufacturer: SICK MAIHAK GmbH | Ambient pressure: Intern mbar |
| Part Number: B602 0550 | Sampling Location: Main Stack |
| Serial Number: 305 | Meas. Location: CEMS Shelter |

Component: HYDROGEN CHLORIDE (HCL)

Meas. Range: 100 ppm
 Uncertainty: 2.0 % Full Scale

Gain Level: 9 step
 Calibration factor as found: 0.9005
 Calibration factor as left: 0.8924

A) CALIBRATION MEASUREMENT - Zero Gas

| Gas Flow Rate [L / hr] | Certified value [ppm] | Actual reading [ppm] | Deviation [ppm] | Results [Actual < Limit] |
|-----------------------------|----------------------------|---------------------------|----------------------|-------------------------------|
| ± 465 | 0.00 | 0.54 | -0.54 | Passed |

B) CALIBRATION MEASUREMENT - Span Gas

| Gas Flow Rate [L / hr] | Certified value [ppm] | Actual reading [ppm] | Deviation [ppm] | Results [Actual < Limit] |
|-----------------------------|----------------------------|---------------------------|----------------------|-------------------------------|
| ± 465 | 82.9 | 82.38 | 0.52 | Passed |

C) LINEARITY MEASUREMENT (if calibrator & linearity is included)

| Gas Flow Rate [L / hr] | Calibrator value [ppm] | Actual reading [ppm] | Deviation [ppm] | | Results [Actual < Limit] |
|-----------------------------|-----------------------------|---------------------------|-------------------|-------|-------------------------------|
| | | | Actual | Limit | |
| ± 465 | | | 0 | 2.00 | Passed |
| ± 465 | | | 0 | 2.00 | Passed |
| ± 465 | | | 0 | 2.00 | Passed |

Calibration Gas / Liquid:

Supplier: LOBA Chemie
 Concentration: 0.04996 mol/L
 Uncertainty: +/- 0.0004%
 Certificate No: R140A01000
 Lot No: K026692303
 Expiry Date: 01/02/2026

| TECHNICIAN | |
|------------------|---|
| MR. Olaf de Boer | |
| 19/04/2025 |  |
| DATE | SIGNATURE |

| | |
|--------------------------|------------|
| Calibration record sheet | 19/04/2025 |
|--------------------------|------------|

Customer: BANGPOO ENVIROMENTAL COMPLEX CO., LTD
Address: 965 Moo 2, Bangpoo Industrial Estate, Sukhumvit Road
 Soi 3 T. Bang Pu Mai A. Muang Samut Prakan 10280

| | |
|--------------------------------|-------------------------------|
| Equipment Details: | Measurement Parameter |
| Device: MCS100E - HW | Ambient temperature: 25 deg C |
| Manufacturer: SICK MAIHAK GmbH | Ambient pressure: Intern mbar |
| Part Number: B602 0550 | Sampling Location: Main Stack |
| Serial Number: 305 | Meas. Location: CEMS Shelter |

Component: CARBON MONOXIDE (CO)

Meas. Range: 2500 ppm
 Uncertainty: 2.0 % Full Scale

Gain Level: 12 step
 Calibration factor as found: 0.9175
 Calibration factor as left: 0.9245

A) CALIBRATION MEASUREMENT - Zero Gas

| Gas Flow Rate [L / hr] | Certified value [ppm] | Actual reading [ppm] | Deviation [ppm] | Results [Actual < Limit] |
|-----------------------------|----------------------------|---------------------------|----------------------|-------------------------------|
| ± 465 | 0.00 | 0.1 | -0.10 | Passed |

B) CALIBRATION MEASUREMENT - Span Gas

| Gas Flow Rate [L / hr] | Certified value [ppm] | Actual reading [ppm] | Deviation [ppm] | Results [Actual < Limit] |
|-----------------------------|----------------------------|---------------------------|----------------------|-------------------------------|
| ± 465 | 133 | 135.4 | -2.4 | Passed |

C) LINEARITY MEASUREMENT (if calibrator & linearity is included)

| Gas Flow Rate [L / hr] | Calibrator value [ppm] | Actual reading [ppm] | Deviation [ppm] | | Results [Actual < Limit] |
|-----------------------------|-----------------------------|---------------------------|-------------------|-------|-------------------------------|
| | | | Actual | Limit | |
| ± 465 | | | 0 | 50.00 | Passed |
| ± 465 | | | 0 | 50.00 | Passed |
| ± 465 | | | 0 | 50.00 | Passed |

Calibration Gas:

Supplier: Linde (Thailand) Co., Ltd
 Concentration: 133 ppm
 Uncertainty: +/- 1%
 Certificate No: 2971/24
 Cylinder No: A00639sv
 Expiry Date: 20/09/2026

| TECHNICIAN | |
|------------------|---|
| MR. Olaf de Boer | |
| 19/04/2025 |  |
| DATE | SIGNATURE |

Calibration record sheet
19/04/2025

Customer: BANGPOO ENVIROMENTAL COMPLEX CO., LTD
Address: 965 Moo 2, Bangpoo Industrial Estate, Sukhumvit Road
 Soi 3 T. Bang Pu Mai A. Muang Samut Prakan 10280

| | |
|--------------------------------|-------------------------------|
| Equipment Details: | Measurement Parameter |
| Device: MCS100E - HW | Ambient temperature: 25 deg C |
| Manufacturer: SICK MAIHAK GmbH | Ambient pressure: Intern mbar |
| Part Number: B602 0550 | Sampling Location: Main Stack |
| Serial Number: 305 | Meas. Location: CEMS Shelter |

Component: NITRIC OXIDE (NO)

Meas. Range: 300 ppm
 Uncertainty: 2.0 % Full Scale

Gain Level: 12 step
 Calibration factor as found: 0.9886
 Calibration factor as left: 0.924

A) CALIBRATION MEASUREMENT - Zero Gas

| Gas Flow Rate [L / hr] | Certified value [ppm] | Actual reading [ppm] | Deviation [ppm] | Results [Actual < Limit] |
|-----------------------------|----------------------------|---------------------------|----------------------|-------------------------------|
| ± 465 | 0.00 | 0.85 | -0.85 | Passed |

B) CALIBRATION MEASUREMENT - Span Gas

| Gas Flow Rate [L / hr] | Certified value [ppm] | Actual reading [ppm] | Deviation [ppm] | Results [Actual < Limit] |
|-----------------------------|----------------------------|---------------------------|----------------------|-------------------------------|
| ± 465 | 218 | 217.39 | 0.61 | Passed |

C) LINEARITY MEASUREMENT (if calibrator & linearity is included)

| Gas Flow Rate [L / hr] | Calibrator value [ppm] | Actual reading [ppm] | Deviation [ppm] | | Results [Actual < Limit] |
|-----------------------------|-----------------------------|---------------------------|-------------------|-------|-------------------------------|
| | | | Actual | Limit | |
| ± 465 | | | 0 | 6.00 | Passed |
| ± 465 | | | 0 | 6.00 | Passed |
| ± 465 | | | 0 | 6.00 | Passed |

Calibration Gas:
 Supplier: Linde (Thailand) Co., Ltd
 Concentration: 218 ppm
 Uncertainty: +/- 1%
 Certificate No: 2971/24
 Cylinder No: A00639sv
 Expiry Date: 20/09/2026

| TECHNICIAN | |
|------------------|---|
| MR. Olaf de Boer | |
| 19/04/2025 |  |
| DATE | SIGNATURE |

Calibration record sheet
19/04/2025

Customer: BANGPOO ENVIROMENTAL COMPLEX CO., LTD
Address: 965 Moo 2, Bangpoo Industrial Estate, Sukhumvit Road
 Soi 3 T. Bang Pu Mai A. Muang Samut Prakan 10280

| | |
|--------------------------------|-------------------------------|
| Equipment Details: | Measurement Parameter |
| Device: MCS100E - HW | Ambient temperature: 25 deg C |
| Manufacturer: SICK MAIHAK GmbH | Ambient pressure: Intern mbar |
| Part Number: B602 0550 | Sampling Location: Main Stack |
| Serial Number: 305 | Meas. Location: CEMS Shelter |

Component: SULPHUR DIOXIDE (SO2)

Meas. Range: 100 ppm
 Uncertainty: 2.0 % Full Scale

Gain Level: 15 step
 Calibration factor as found: 0.9625
 Calibration factor as left: #REF!

A) CALIBRATION MEASUREMENT - Zero Gas

| Gas Flow Rate [L / hr] | Certified value [ppm] | Actual reading [ppm] | Deviation [ppm] | Results [Actual < Limit] |
|-----------------------------|----------------------------|---------------------------|----------------------|-------------------------------|
| ± 465 | 0.00 | 0.1 | -0.10 | Passed |


B) CALIBRATION MEASUREMENT - Span Gas

| Gas Flow Rate [L / hr] | Certified value [ppm] | Actual reading [ppm] | Deviation [ppm] | Results [Actual < Limit] |
|-----------------------------|----------------------------|---------------------------|----------------------|-------------------------------|
| ± 465 | 71.5 | 71.99 | -0.49 | Passed |

C) LINEARITY MEASUREMENT (if calibrator & linearity is included)

| Gas Flow Rate [L / hr] | Calibrator value [ppm] | Actual reading [ppm] | Deviation [ppm] | | Results [Actual < Limit] |
|-----------------------------|-----------------------------|---------------------------|-------------------|-------|-------------------------------|
| | | | Actual | Limit | |
| ± 465 | | | 0 | 2.00 | Passed |
| ± 465 | | | 0 | 2.00 | Passed |
| ± 465 | | | 0 | 2.00 | Passed |

Calibration Gas:
 Supplier: Linde (Thailand) Co., Ltd
 Concentration: 71.5 ppm
 Uncertainty: +/- 1%
 Certificate No: 2971/24
 Cylinder No: A00639sv
 Expiry Date: 20/09/2026

| TECHNICIAN | |
|------------------|---|
| MR. Olaf de Boer | |
| 19/04/2025 |  |
| DATE | SIGNATURE |

| | |
|--------------------------|------------|
| Calibration record sheet | 19/04/2025 |
|--------------------------|------------|

Customer: BANGPOO ENVIROMENTAL COMPLEX CO., LTD
Address: 965 Moo 2, Bangpoo Industrial Estate, Sukhumvit Road
 Soi 3 T. Bang Pu Mai A. Muang Samut Prakan 10280

| | |
|--------------------------------|-------------------------------|
| Equipment Details: | Measurement Parameter |
| Device: MCS100E - HW | Ambient temperature: 25 deg C |
| Manufacturer: SICK MAIHAK GmbH | Ambient pressure: Intern mbar |
| Part Number: B602 0550 | Sampling Location: Main Stack |
| Serial Number: 305 | Meas. Location: CEMS Shelter |

Component: NITROGEN DIOXIDE (NO2)

Meas. Range: 300 ppm
 Uncertainty: 2.0 % Full Scale

Gain Level: 15 step
 Calibration factor as found: 0.9546
 Calibration factor as left: 0.9237

A) CALIBRATION MEASUREMENT - Zero Gas

| Gas Flow Rate [L / hr] | Certified value [ppm] | Actual reading [ppm] | Deviation [ppm] | Results [Actual < Limit] |
|-----------------------------|----------------------------|---------------------------|----------------------|-------------------------------|
| ± 465 | 0.00 | -0.19 | 0.19 | Passed |

B) CALIBRATION MEASUREMENT - Span Gas

| Gas Flow Rate [L / hr] | Certified value [ppm] | Actual reading [ppm] | Deviation [ppm] | Results [Actual < Limit] |
|-----------------------------|----------------------------|---------------------------|----------------------|-------------------------------|
| ± 465 | 226 | 226.23 | -0.23 | Passed |

C) LINEARITY MEASUREMENT (if calibrator & linearity is included)

| Gas Flow Rate [L / hr] | Calibrator value [ppm] | Actual reading [ppm] | Deviation [ppm] | | Results [Actual < Limit] |
|-----------------------------|-----------------------------|---------------------------|-------------------|-------|-------------------------------|
| | | | Actual | Limit | |
| ± 465 | | | 0 | 6.00 | Passed |
| ± 465 | | | 0 | 6.00 | Passed |
| ± 465 | | | 0 | 6.00 | Passed |

Calibration Gas:

Supplier: Linde (Thailand) Co., Ltd
 Concentration: 226 ppm
 Uncertainty: +/- 10%
 Certificate No: 2361/24
 Cylinder No: QA2437
 Expiry Date: 15/08/2026

| TECHNICIAN | |
|------------------|---|
| MR. Olaf de Boer | |
| 19/04/2025 |  |
| DATE | SIGNATURE |

| | |
|--------------------------|------------|
| Calibration record sheet | 19/04/2025 |
|--------------------------|------------|

Customer: BANGPOO ENVIROMENTAL COMPLEX CO., LTD
Address: 965 Moo 2, Bangpoo Industrial Estate, Sukhumvit Road
 Soi 3 T. Bang Pu Mai A. Muang Samut Prakan 10280

| | |
|--------------------------------|-------------------------------|
| Equipment Details: | Measurement Parameter |
| Device: MCS100E - HW | Ambient temperature: 25 deg C |
| Manufacturer: SICK MAIHAK GmbH | Ambient pressure: Intern mbar |
| Part Number: B602 0550 | Sampling Location: Main Stack |
| Serial Number: 305 | Meas. Location: CEMS Shelter |

Component: CARBON DIOXIDE (CO2)

Meas. Range: 100 vol %
 Uncertainty: 2.0 % Full Scale

Gain Level: 13 step
 Calibration factor as found: 1.0098
 Calibration factor as left: 0.9986

A) CALIBRATION MEASUREMENT - Zero Gas

| Gas Flow Rate [L / hr] | Certified value [vol %] | Actual reading [vol %] | Deviation [vol %] | Results [Actual < Limit] |
|-----------------------------|------------------------------|-----------------------------|------------------------|-------------------------------|
| ± 465 | 0.00 | -0.01 | 0.01 | Passed |

B) CALIBRATION MEASUREMENT - Span Gas


| Gas Flow Rate [L / hr] | Certified value [vol %] | Actual reading [vol %] | Deviation [vol %] | Results [Actual < Limit] |
|-----------------------------|------------------------------|-----------------------------|------------------------|-------------------------------|
| ± 465 | 15 | 15.17 | -0.17 | Passed |

C) LINEARITY MEASUREMENT (if calibrator & linearity is included)

| Gas Flow Rate [L / hr] | Calibrator value [vol %] | Actual reading [vol %] | Deviation [vol %] | | Results [Actual < Limit] |
|-----------------------------|-------------------------------|-----------------------------|---------------------|-------|-------------------------------|
| | | | Actual | Limit | |
| ± 465 | | | 0 | 2.00 | Passed |
| ± 465 | | | 0 | 2.00 | Passed |
| ± 465 | | | 0 | 2.00 | Passed |

Calibration Gas:

Supplier: Linde (Thailand) Co., Ltd
 Concentration: 15 vol %
 Uncertainty: +/- 2%
 Certificate No: 2388/24
 Cylinder No: 15737
 Expiry Date: 01/08/2028

| TECHNICIAN | |
|------------------|---|
| MR. Olaf de Boer | |
| 19/04/2025 |  |
| DATE | SIGNATURE |

| | |
|---------------------------------|-------------------|
| Calibration record sheet | 19/04/2025 |
|---------------------------------|-------------------|

Customer: BANGPOO ENVIROMENTAL COMPLEX CO., LTD
Address: 965 Moo 2, Bangpoo Industrial Estate, Sukhumvit Road
 Soi 3 T. Bang Pu Mai A. Muang Samut Prakan 10280

| | |
|--------------------------------|-------------------------------|
| Equipment Details: | Measurement Parameter |
| Device: MCS100E - HW | Ambient temperature: 25 deg C |
| Manufacturer: SICK MAIHAK GmbH | Ambient pressure: Intern mbar |
| Part Number: B602 0550 | Sampling Location: Main Stack |
| Serial Number: 305 | Meas. Location: CEMS Shelter |

Component: OXYGEN (O2)

| | | | | |
|--------------|-----|--------------|---------------------|-----|
| Meas. Range: | 25 | vol % | Calibration factor: | --- |
| Uncertainty: | 2.0 | % Full Scale | | |

| | | |
|-----------|---------------|-----------|
| | Line Constant | Steepness |
| As found: | -0.98 | 47.93 |
| As left: | -1.48 | 48.23 |


A) CALIBRATION MEASUREMENT - ZERO

| Gas Flow Rate [L / hr] | Certified value [vol %] | Actual reading [vol %] | Deviation [vol %] | | Results |
|-----------------------------|------------------------------|-----------------------------|---------------------|-------|--------------------|
| | | | Actual | Limit | [Actual < Limit] |
| ± 600 | 20.95 | 20.98 | -0.03 | 0.50 | Passed |

B) CALIBRATION MEASUREMENT - SPAN

| Gas Flow Rate [L / hr] | Calibrator value [vol %] | Actual reading [vol %] | Deviation [vol %] | | Results |
|-----------------------------|-------------------------------|-----------------------------|---------------------|-------|--------------------|
| | | | Actual | Limit | [Actual < Limit] |
| ± 465 | 2.07 | 2.07 | 0 | 0.50 | Passed |

Calibration Gas:
Supplier: Linde (Thailand) Co., Ltd
Concentration: 2.07 vol %
Uncertainty: +/- 2%
Certificate No: 2388/24
Cylinder No: 15737
Expiry Date: 01/08/2028

| | |
|-------------------|---|
| TECHNICIAN | |
| MR. Olaf de Boer | |
| 19/04/2025 |  |
| DATE | SIGNATURE |

เอกสารแนบ 2-18
เกณฑ์รับน้ำเสียของนิคม

มาตรฐานคุณภาพน้ำทิ้งจากโรงงานอุตสาหกรรมในนิคมอุตสาหกรรมบางปู

| ดัชนี | มาตรฐาน (มิลลิกรัม/ลิตร) | |
|----------------------------|--------------------------------|---|
| | เขตอุตสาหกรรมทั่วไป (ส่วนเดิม) | เขตอุตสาหกรรมทั่วไป (ส่วนขยาย A), เขตอุตสาหกรรมส่งออก |
| pH | 5.5-9.0 | 5.5-9.0 |
| Temperature (°C) | 45 | 45 |
| Color | 600 | 600 |
| Odour | ต้องไม่เป็นที่พึงรังเกียจ | ต้องไม่เป็นที่พึงรังเกียจ |
| TDS | 3,000 | 3,000 |
| SS | 200 | 200 |
| BOD ₅ ที่ 20 °C | 1,000 | 500 |
| COD | 1,500 | 750 |
| Sulfide | 1 | 1 |
| Cyanide as HCN | 0.2 | 0.2 |
| Oil & Grease | 10 | 10 |
| Formaldehyde | 1 | 1 |
| Phenols Compound | 1 | 1 |
| Free Chlorine | 1 | 1 |
| Pesticide | ต้องตรวจไม่พบ | ต้องตรวจไม่พบ |
| TKN | 100 | 100 |
| Fluoride | 5 | 5 |
| Surfactants | 30 | 30 |
| โลหะหนัก | | |
| Zn | 5 | 5 |
| Cr ⁶⁺ | 0.25 | 0.25 |
| Cr ³⁺ | 0.75 | 0.75 |
| As | 0.25 | 0.25 |
| Cu | 2 | 2 |
| Hg | 0.005 | 0.005 |
| Cd | 0.03 | 0.03 |
| Ba | 1 | 1 |
| Se | 0.02 | 0.02 |
| Pb | 0.2 | 0.2 |
| Ni | 1 | 1 |
| Mn | 5 | 5 |
| Ag | 1 | 1 |
| Total Iron | 10 | 10 |

ที่มา : ประกาศการนิคมอุตสาหกรรมแห่งประเทศไทย ที่ 76/2560 เรื่อง กำหนดมาตรฐานทั่วไปในการระบายน้ำเสียลงสู่ระบบบำบัดน้ำเสีย
ส่วนกลางในนิคมอุตสาหกรรม

เอกสารแนบ 2-19

เอกสารการจัดทำโครงการอนุรักษ์การไถ่ยืม

ประกาศบริษัท ที่ HS007/2014

เนื่องด้วยทางบริษัทได้ดำเนินการตรวจวัดคุณภาพสิ่งแวดล้อมประจำปี 2557 ภายในบริษัทตามที่กฎหมายกำหนดไว้ หลังการตรวจสอบพบว่า มีค่าระดับเสียงที่เกินกว่ามาตรฐานกำหนดไว้ 2 จุด ที่พื้นที่ Induce Draft Fan ภายในห้องเก็บสารเคมีและห้อง Generator Room โดยมีค่าระดับเสียงเฉลี่ย 5 นาที่ เท่ากับ 91 และ 85.4 เดซิเบลเอ ตามลำดับ (มาตรฐานอยู่ที่ 85 เดซิเบลเอ) ทางบริษัทจึงขอจัดทำโครงการอนุรักษ์การได้ยิน โดยทำเป็นประกาศบริษัท เพื่อแจ้งให้ทราบโดยทั่วกัน ทั้งนี้โครงการอนุรักษ์การได้ยินของบริษัท มีนโยบายดังต่อไปนี้

- 1.) ตรวจสอบประสิทธิภาพการได้ยินของเจ้าหน้าที่ที่เกี่ยวข้องภายในพื้นที่ที่มีเสียงดังเกินกว่ามาตรฐาน และนำมาเปรียบเทียบกับผลตรวจสุขภาพการได้ยินล่าสุด และติดตามอย่างต่อเนื่อง (ปัจจุบันมีการเปรียบเทียบตามประกาศบริษัทที่ HS001/2014 แล้ว)
- 2.) จัดอุปกรณ์ป้องกันส่วนบุคคลเพื่อลดระดับเสียงและให้พนักงานสวมใส่ก่อนเข้าปฏิบัติงานในพื้นที่ที่มีเสียงดัง
- 3.) ให้พนักงานหมุนเวียนเข้าภายในพื้นที่ที่มีเสียงดัง โดยคำนวณจากชั่วโมงการทำงานเฉลี่ยเมื่ออยู่ภายในพื้นที่ที่มีเสียงดัง (จากค่าระดับเสียงของบริษัทให้พนักงานปฏิบัติงานที่ไม่เกิน 3 และ 7 ชั่วโมงการทำงาน ตามลำดับ)

นอกจากนี้ ทางบริษัท ขอฝากให้ คุณภักธร วิวัฒน์ชัยเศรษฐ์ เป็นผู้ดำเนินโครงการอนุรักษ์การได้ยินในพื้นที่ที่มีเสียงดัง ทั้งนี้เพื่อปรับปรุงแก้ไข และติดตาม แจ้งระดับเสียงแก่พนักงาน รวมถึงจัดทำรายงานประจำปีให้ผู้บริหารทราบเพื่อร่วมกันปรับปรุงแก้ไขต่อไปจนมีค่าระดับเสียงอยู่ในเกณฑ์ที่กฎหมายกำหนด

ประกาศบริษัทฉบับนี้ให้มีผลตั้งแต่วันที่ 21 มีนาคม 2557 เป็นต้นไป

จึงเรียนมาเพื่อทราบ



ประธานบริษัท บังปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

เนื่องจากผลการตรวจวัดตามคุณภาพสิ่งแวดล้อมประจำปี 2557 ทางบริษัทพบว่า บริเวณ induce draft fan มีเสียงดัง (Leq5min) อยู่ที่ 91 เดซิเบลเอ และ Generator room มีเสียงดัง (Leq5min) อยู่ที่ 85.4 เดซิเบลเอ ซึ่งค่าอยู่ในช่วงที่ทางบริษัทต้องจัดทำโครงการอนุรักษ์การได้ยิน หลังการตรวจสอบพบว่า มีพนักงานที่เกี่ยวข้องกับพื้นที่ดังกล่าว ดังต่อไปนี้

- | | | | |
|------------|---|------------|---|
| 1.) W-0401 |  | แผนกเตาเผา |  |
| 2.) W-0511 |  | แผนกเตาเผา | |
| 3.) W-1548 |  | แผนกเตาเผา | |

เมื่อเข้าปฏิบัติงานขอให้ปฏิบัติตามข้อกำหนดดังนี้

- 1.) สวมใส่อุปกรณ์เพื่อลดระดับเสียง (Ear plug) ก่อนเข้าปฏิบัติงานทุกครั้งในพื้นที่ห้องเก็บสารเคมี
- 2.) หากทำงานเป็นระยะเวลานานๆ ภายในพื้นที่ห้องเก็บสารเคมี ให้ทำงานภายในห้องเก็บสารเคมี 30 นาที และสลับไปทำงานบริเวณพื้นที่อื่นๆ 30 นาที
- 3.) ให้หัวหน้างานตรวจสอบสุขภาพการได้ยินจากพนักงานดังกล่าว หากพบสิ่งผิดปกติโดยตรงหรือจากการแจ้งของพนักงานดังกล่าว ให้หัวหน้างานติดต่อเพื่อดำเนินการเบื้องต้นกับทางเจ้าหน้าที่ความปลอดภัยระดับวิชาชีพ และหากตรวจสอบพบว่ามีอาการรุนแรงให้ส่งไปโรงพยาบาลต่อไป

(เอกสารฉบับนี้ต่อเนื่องจากประกาศฉบับที่ HS001/2014 และ HS007/2014)



ประธานบริษัท บังปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด


เอกสารแนบ 2-20

ระบบตรวจสอบเส้นทางการขนส่งของเสีย

ค้นหา: รายงานเดินรถ รายงานเดินรถตามสายรถเมล์ แผนที่ ข้อมูลรถ เส้นทางรถเมล์

รถโดยสาร WMS38 53-8458 เส้นทาง 2025-01-20 00:00:00 ถึง 2025-01-20 23:59:59
รวมผลการเดินรถ 560.04 กิโลเมตร


| ลำดับ | สายรถ | วันที่-เวลา | สถานี | ผู้โดยสาร | ความเร็ว | สถานะ |
|-------|-------|---------------------|-----------|--------------------|----------|--------------|
| 1 | 1 | 2025-01-20 02:45:09 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 2 | 2 | 2025-01-20 02:45:10 | สถานี | | 0 | มาอยู่ที่นี่ |
| 3 | 3 | 2025-01-20 02:45:22 | สถานี | | 0 | มาอยู่ที่นี่ |
| 4 | 4 | 2025-01-20 02:47:13 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 5 | 5 | 2025-01-20 03:19:00 | สถานี | | 0 | มาอยู่ที่นี่ |
| 6 | 6 | 2025-01-20 03:19:00 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 7 | 7 | 2025-01-20 03:19:02 | สถานี | | 0 | มาอยู่ที่นี่ |
| 8 | 8 | 2025-01-20 04:19:20 | สถานี | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 9 | 9 | 2025-01-20 04:19:21 | สถานี | | 0 | มาอยู่ที่นี่ |
| 10 | 10 | 2025-01-20 04:19:39 | สถานี | | 0 | มาอยู่ที่นี่ |
| 11 | 11 | 2025-01-20 04:20:43 | สถานี | | 6 | มาอยู่ที่นี่ |
| 12 | 12 | 2025-01-20 04:21:45 | สถานี | | 0 | มาอยู่ที่นี่ |
| 13 | 13 | 2025-01-20 04:22:43 | สถานี | | 2 | มาอยู่ที่นี่ |
| 14 | 14 | 2025-01-20 04:23:43 | สถานี | | 0 | มาอยู่ที่นี่ |
| 15 | 15 | 2025-01-20 04:24:43 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 16 | 16 | 2025-01-20 04:29:47 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 17 | 17 | 2025-01-20 04:25:48 | สถานี | | 6 | มาอยู่ที่นี่ |
| 18 | 18 | 2025-01-20 04:26:48 | สถานี | | 0 | มาอยู่ที่นี่ |
| 19 | 19 | 2025-01-20 04:27:48 | สถานี | | 0 | มาอยู่ที่นี่ |
| 20 | 20 | 2025-01-20 04:28:03 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |



ค้นหา: รายงานเดินรถ รายงานเดินรถตามสายรถเมล์ แผนที่ ข้อมูลรถ เส้นทางรถเมล์

รถโดยสาร WMS38 53-8458 เส้นทาง 2025-02-20 00:00:00 ถึง 2025-02-20 23:59:59
รวมผลการเดินรถ 180.06 กิโลเมตร


| ลำดับ | สายรถ | วันที่-เวลา | สถานี | ผู้โดยสาร | ความเร็ว | สถานะ |
|-------|-------|---------------------|-----------|--------------------|----------|--------------|
| 1 | 1 | 2025-02-20 02:23:18 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 2 | 2 | 2025-02-20 02:23:19 | สถานี | | 0 | มาอยู่ที่นี่ |
| 3 | 3 | 2025-02-20 02:24:17 | สถานี | | 6 | มาอยู่ที่นี่ |
| 4 | 4 | 2025-02-20 02:24:41 | สถานี | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 5 | 5 | 2025-02-20 03:58:51 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 6 | 6 | 2025-02-20 03:58:52 | สถานี | | 0 | มาอยู่ที่นี่ |
| 7 | 7 | 2025-02-20 03:59:18 | สถานี | | 0 | มาอยู่ที่นี่ |
| 8 | 8 | 2025-02-20 04:01:09 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 9 | 9 | 2025-02-20 04:06:03 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 10 | 10 | 2025-02-20 04:06:04 | สถานี | | 5 | มาอยู่ที่นี่ |
| 11 | 11 | 2025-02-20 04:07:04 | สถานี | | 0 | มาอยู่ที่นี่ |
| 12 | 12 | 2025-02-20 04:08:04 | สถานี | | 0 | มาอยู่ที่นี่ |
| 13 | 13 | 2025-02-20 04:08:11 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 14 | 14 | 2025-02-20 04:10:06 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |
| 15 | 15 | 2025-02-20 04:10:07 | สถานี | | 8 | มาอยู่ที่นี่ |
| 16 | 16 | 2025-02-20 04:11:07 | สถานี | | 0 | มาอยู่ที่นี่ |
| 17 | 17 | 2025-02-20 04:12:07 | สถานี | | 0 | มาอยู่ที่นี่ |
| 18 | 18 | 2025-02-20 04:13:07 | สถานี | | 3 | มาอยู่ที่นี่ |
| 19 | 19 | 2025-02-20 04:14:07 | สถานี | | 0 | มาอยู่ที่นี่ |
| 20 | 20 | 2025-02-20 04:15:02 | สถานีรถไฟ | Bangkok Environ... | 0 | มาอยู่ที่นี่ |



หน้าแรก รายงานสด รายงานประวัติการแจ้งเตือน สรุป แสดงผล ค้นหา

หมายเลข WM336 53-8458 เวลาเริ่ม 2025-05-20 00:00:00 ถึง 2025-05-20 23:59:59
รวมเหตุการณ์ได้ 20531 รายการ


| ลำดับ | ทิศทาง | วัน-เวลา | สถานะ | สถานที่ | ปริมาณ | ความถี่ | ประเภท |
|-------|--------|---------------------|-----------|------------------|--------|---------|--------|
| 1 | ● | 2025-05-20 01:59:17 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 2 | ● | 2025-05-20 01:59:18 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 3 | ● | 2025-05-20 01:59:48 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 4 | ● | 2025-05-20 02:01:17 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 5 | ● | 2025-05-20 02:19:42 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 6 | ● | 2025-05-20 02:19:43 | เสร็จ | | 6 | มาตรฐาน | แจ้ง |
| 7 | ● | 2025-05-20 02:20:43 | เสร็จ | | 1 | มาตรฐาน | แจ้ง |
| 8 | ● | 2025-05-20 02:21:43 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 9 | ● | 2025-05-20 02:22:02 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 10 | ● | 2025-05-20 02:24:23 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 11 | ● | 2025-05-20 02:24:24 | เสร็จ | | 6 | มาตรฐาน | แจ้ง |
| 12 | ● | 2025-05-20 02:25:24 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 13 | ● | 2025-05-20 02:26:24 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 14 | ● | 2025-05-20 02:27:24 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 15 | ● | 2025-05-20 02:27:47 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 16 | ● | 2025-05-20 02:30:16 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 17 | ● | 2025-05-20 02:30:17 | เสร็จ | | 6 | มาตรฐาน | แจ้ง |
| 18 | ● | 2025-05-20 02:31:17 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 19 | ● | 2025-05-20 02:32:17 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 20 | ● | 2025-05-20 02:32:23 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |



หน้าแรก รายงานสด รายงานประวัติการแจ้งเตือน สรุป แสดงผล ค้นหา

หมายเลข WM336 53-8458 เวลาเริ่ม 2025-06-20 00:00:00 ถึง 2025-06-20 23:59:59
รวมเหตุการณ์ได้ 27884 รายการ

| ลำดับ | ทิศทาง | วัน-เวลา | สถานะ | สถานที่ | ปริมาณ | ความถี่ | ประเภท |
|-------|--------|---------------------|-----------|------------------|--------|---------|--------|
| 1 | ● | 2025-06-20 04:10:04 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 2 | ● | 2025-06-20 04:10:05 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 3 | ● | 2025-06-20 04:10:29 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 4 | ● | 2025-06-20 04:12:04 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 5 | ● | 2025-06-20 04:22:25 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 6 | ● | 2025-06-20 04:22:26 | เสร็จ | | 6 | มาตรฐาน | แจ้ง |
| 7 | ● | 2025-06-20 04:23:26 | เสร็จ | | 7 | มาตรฐาน | แจ้ง |
| 8 | ● | 2025-06-20 04:24:26 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 9 | ● | 2025-06-20 04:25:26 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 10 | ● | 2025-06-20 04:26:26 | เสร็จ | | 9 | มาตรฐาน | แจ้ง |
| 11 | ● | 2025-06-20 04:27:26 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 12 | ● | 2025-06-20 04:28:26 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 13 | ● | 2025-06-20 04:28:32 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 14 | ● | 2025-06-20 04:33:06 | แจ้งเตือน | Bangpoo Environ. | 0 | มาตรฐาน | แจ้ง |
| 15 | ● | 2025-06-20 04:33:07 | เสร็จ | | 5 | มาตรฐาน | แจ้ง |
| 16 | ● | 2025-06-20 04:34:07 | เสร็จ | | 8 | มาตรฐาน | แจ้ง |
| 17 | ● | 2025-06-20 04:35:07 | เสร็จ | | 6 | มาตรฐาน | แจ้ง |
| 18 | ● | 2025-06-20 04:36:07 | เสร็จ | | 2 | มาตรฐาน | แจ้ง |
| 19 | ● | 2025-06-20 04:37:07 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |
| 20 | ● | 2025-06-20 04:38:07 | เสร็จ | | 0 | มาตรฐาน | แจ้ง |



เอกสารแนบ 2-21

เอกสาร Contractor Safety Rule

CONTRACTOR SAFETY RULES**ข้อบังคับการปฏิบัติงานของผู้รับเหมา****1. ข้อบังคับทั่วไป / General Rules**

1.1 ผู้รับเหมาทุกคนต้องได้รับการอบรมด้านสิ่งแวดล้อม อาชีวอนามัยและความปลอดภัย จากเจ้าหน้าที่ความปลอดภัยของโครงการ BPEC

All contractors must have an instruction about environmental health and safety rules by BPEC Safety Officer.

1.2 ผู้รับเหมาต้องติดบัตรประจำตัวตลอดเวลาที่ปฏิบัติงานภายในโครงการ

All contractors must to stick visitor card all time

1.3 ต้องจอดรถในสถานที่กำหนด รถที่ได้รับอนุญาตเท่านั้น ที่อาจจะสามารถวิ่งเข้าไปในพื้นที่ก่อสร้างได้ และใช้ความเร็วได้ไม่เกิน 20 กม./ชั่วโมง

Parking in order at parking lodge, authorized vehicle only could be allowed for entering to construction area and speed limit is 20 km/hr

1.4 สูบบุหรี่และรับประทานอาหารในสถานที่กำหนดให้เท่านั้น

Smoking and eating at specific area only

1.5 ห้ามนอนในสถานที่ปฏิบัติงาน

No residing at work place

1.6 ห้ามดื่มหรือนำเครื่องดื่มที่มีแอลกอฮอล์เข้ามาในพื้นที่โครงการฯ

No alcohol drinking allow in BPEC area.

1.7 ห้ามขโมยทรัพย์สินของบริษัท รวมถึงขยะทั่วไปที่นำมาจัดภายในโครงการฯ

Prohibition for stealing, scavenging of any BPEC properties including dispose of individual waste

1.8 หยุดให้เจ้าหน้าที่ รปภ.ตรวจค้น บุคคลและยานพาหนะที่ประตูใหญ่ ก่อนออกจากไซต์งาน

All vehicles and personnel must stop at the main gate for security check of material & personnel belonging

2. ข้อบังคับด้านความปลอดภัย / Safety Rules

2.1 ผู้รับเหมาต้องแต่งกายให้เหมาะสม รัดกุม และสวมอุปกรณ์ป้องกันภัยส่วนบุคคล (PPE) ตามลักษณะงานที่ทำงาน โดยขั้นพื้นฐานที่ต้องมีคือ รองเท้านิรภัย, หมวกนิรภัย, เสื้อสะท้อนแสง, แว่นตา, ผ้าปิดจมูก และสวมใส่เสื้อแขนยาว ซึ่งต้องจัดเตรียมโดยผู้รับเหมาเอง หากไม่มีการเตรียมไว้ในวันที่ปฏิบัติงาน จะไม่อนุญาตให้ปฏิบัติงานในพื้นที่โครงการฯ โดยเด็ดขาด

Contractor must wear PPE to comply with there job characteristic, minimum standard requirement for PPE are safety shoe, safety helmet, safety vest, glasses, mask, long-sleeved shirts. All required PPE shall be provided by Contractor, otherwise access will be denied for failing to do so.

2.2 พนักงานผู้รับเหมาทุกคนจะต้องปฏิบัติตามป้ายเตือน สัญลักษณ์ต่าง ๆ กฎระเบียบข้อกำหนดทางด้านความปลอดภัย อาชีวอนามัยและสิ่งแวดล้อมในขณะที่ปฏิบัติงานอยู่ในพื้นที่เขตของโครงการ ฯ

All contractors shall strictly observe and perform all warning signs and environment health and safety regulation when remain in BPEC site.

2.3 ต้องมีการขออนุญาตทำงานในกรณีต่อไปนี้ *Following work shall be received a permit from Safety Officer only*

1. การทำงานในพื้นที่อับอากาศ หรือมีอากาศเป็นพิษ *Confined Space Entry*

2. การทำงานที่ทำให้เกิดประกายไฟ *Hot Work*

3. การทำงานในที่สูงกว่า 2 เมตร *Work at Height (higher than 2 meters).*

4. การทำงานที่ต้องตัดแยกระบบไฟฟ้า *Electric Isolation Work Permit*

5. การขออนุญาตทำงานล่วงเวลา *Over Time Working Permit*

6. การทำงานเกี่ยวกับสารเคมีอันตราย *Hazard Chemical Permit*

ต้องนำใบอนุญาตมาแสดงไว้ที่หน้าพื้นที่ที่ทำงานทุกครั้งที่มีการทำงาน และผู้รับเหมาจะต้องทำงานในพื้นที่ที่กำหนดให้เท่านั้น *Contractor must show work permit at working area and shall be working only in designated area*

2.4 เครื่องมือและอุปกรณ์ของผู้รับเหมาจะต้องมีการป้องกันอย่างเหมาะสม

All contractor equipments must have proper safety guard.

2.5 ห้ามผู้รับเหมาใช้อุปกรณ์หรือเครื่องมือต่างๆ ของโครงการโดยไม่ได้รับอนุญาตและต้องรับผิดชอบต่อความเสียหายที่เกิด

Contractors are not allow to use BPEC tools and equipments before receiving an approval from BPEC Supervisor or Manager and must be responsible to any damage occur.

2.6 ห้ามไม่ให้พนักงานของผู้รับเหมาใช้อุปกรณ์ดับเพลิงก่อนได้รับอนุญาตจากหัวหน้างาน หรือเจ้าหน้าที่ความปลอดภัยของโครงการฯ

Contractor shall not use fire extinguisher before getting an approval from BPEC Supervisor or Safety Officer. This will be an exception for emergency case only

2.7 ขยะที่เกิดขึ้นจากกิจกรรมของผู้รับเหมา ผู้รับเหมาต้องจัดการให้สะอาดและไม่ทิ้งขยะอันตรายปนกับขยะทั่วไป และต้องแจ้งให้หัวหน้างานหรือผู้จัดการที่ดูแลอยู่ เพื่อพิจารณาอนุญาตในการรับผิดชอบการจัดขยะดังกล่าว *Waste generated by contractor must be cleaned by contractor and hazardous wastes should be separate from general wastes before dispose. Contractor shall coordinate to supervisor or manager about hazardous waste generation management.*

2.8 ต้องรักษาความสะอาดบริเวณที่ทำงานในแต่ละวัน *Working area shall be cleaned on daily basis.*

2.9 ผู้รับเหมาต้องทำรายงาน อุบัติการณ์ อุบัติเหตุ ไฟไหม้ การหกรั่วไหลของสารเคมี ทุกครั้งต่อ หัวหน้างาน ผู้จัดการ หรือเจ้าหน้าที่ความปลอดภัยของโครงการ ฯ

All incident, accident, fire and chemical spillage must be report to BPEC Supervisor, Manager or Safety Officer as soon as possible.

2.10 ผู้รับเหมาจะต้องปฏิบัติตามกฎหมายความปลอดภัยอื่นๆ อย่างเคร่งครัด

Contractor shall comply with the government environmental health and safety laws and regulations.

2.11 ผู้รับเหมาที่ใช้เครนในการปฏิบัติงานต้องมีการปิดกั้นพื้นที่ เพื่อป้องกันผู้ที่ไม่เกี่ยวข้องเข้าในบริเวณที่มีความเสี่ยง

The work with the crane must be barricade the area. To prevent those not involved.

2.12 ผู้รับเหมาปฏิบัติงานที่ก่อให้เกิดประกายไฟต้องเตรียมอุปกรณ์ป้องกันอัคคีภัยมาเอง โดยขั้นต่ำพื้นฐานที่ต้องมีคือ ผ้ารองสะเก็ดไฟ ผ่าคลุมสะเก็ดไฟ ถังดับเพลิง(ที่พร้อมใช้งาน)

The vendor that create sparks must prepare their own fire protection equipment. The basic must have is Fire protection cloth, Fire cover, Fire extinguisher (Ready to use).

2.13 ผู้รับเหมาที่มีการปฏิบัติงานในที่สูงต้องมี Safety Belts หรือ Full Body Harness และสวมใส่ตั้งแต่ความสูง 1.5 เมตรขึ้นไป

The vendor working in high must have Safety Belts or Full Body Harness and wear at a height of 1.5 meters or more.

3 การลงโทษกรณีไม่ปฏิบัติตามกฎฯ ของโครงการ

การฝ่าฝืนข้อบังคับต่างๆ จะได้รับการเตือนด้วยวาจา หรือให้ออกจากพื้นที่ของโครงการฯ หรือดำเนินการตามกฎหมาย

Violation of the rules will be verbal warning, disqualify from BPEC or send to a prosecution process.

3.1 สำหรับการฝ่าฝืนกฎความปลอดภัยครั้งแรกจะได้รับเอกสารเตือน *First violation of procedure shall be a written warning to contractor.*

3.2 สำหรับการฝ่าฝืนกฎความปลอดภัยครั้งที่ 2 จะถูกห้ามเข้าทำงานในพื้นที่โครงการฯ 1 วัน *Second violation of procedure shall be 1 day suspension of contractor from BPEC site.*

3.3 สำหรับการฝ่าฝืนกฎความปลอดภัยครั้งที่ 3 จะถูกห้ามเข้าทำงานในพื้นที่โครงการฯ โดยถาวร *Third violation of procedure shall be invoked termination of contract with BPEC.*

เอกสารแนบ 2-22

เอกสาร Safety Talk

บันทึกการทำกิจกรรม KYT

Case...../...2024.....



ภาพประกอบ

คำอธิบายภาพ
วางของขวางประตู ทางหนีไฟฉุกเฉิน

วันที่ 1/3/69 เวลา 15.30 น. สถานที่ ห้อง 01 หอ...

ผู้ทำ KYT 01/69 แผนก R.C ส่วน

ขั้นตอนที่ 1 (R1) : ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

| ใคร , ได้รับอันตรายอะไร | เนื่องจากสาเหตุ |
|-------------------------|--------------------------|
| 1 พนักงาน | เกิดไฟไหม้ |
| 2 พนักงาน | มีสิ่งของกีดขวาง |
| 3 พนักงาน | วางสิ่งของไม่เป็นระเบียบ |

ขั้นตอนที่ 2 (R2) : เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อที่เลือก

ขั้นตอนที่ 3 (R3) : หามาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ

1. วางสิ่งของกีดขวางให้เป็นระเบียบ
2. ตรวจสอบสิ่งกีดขวางเป็นประจำ
3. แจ้งแก่ผู้เกี่ยวข้องเกี่ยวกับความปลอดภัย

ขั้นตอนที่ 4 (R4) : เลือกมาตรการป้องกันที่สำคัญ(ปฏิบัติได้จริง)จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5) : เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดนั้นตามด้วยคำว่า "OK"

ด้วยเสียงอันดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

" วางสิ่งของกีดขวางให้เป็นระเบียบเพื่อความปลอดภัย OK "

ขั้นตอนที่ 6 (R6) : มีข้อ ยินเป็นวงกลม และกล่าวพร้อมกันด้วยเสียงอันดังว่า " อุบัติเหตุเป็นศูนย์ "

บันทึกการทำกิจกรรม KYT

Case...8.../...20205....



ภาพประกอบ

คำอธิบายภาพ
หมวกนิรภัยขาด ควรตรวจเช็คก่อนนำไปใช้งาน

วันที่ 1/07/25 เวลา 13.00 น. ชื่อกลุ่ม K... Transport.....

ผู้เข้าร่วม KYT 1..... 2.....
3..... 4.....
5..... 6.....

ขั้นตอนที่ 1 (R1) : ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

1. สภาพอากาศ: ฝนตก หรืออาจมีน้ำท่วม อาจทำให้พื้นลื่น
2. สภาพอากาศ: ฝนตก อาจทำให้พื้นลื่น
3. สภาพอากาศ: ฝนตก อาจทำให้พื้นลื่น

ขั้นตอนที่ 2 (R2) : เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อที่เลือก

ขั้นตอนที่ 3 (R3) : หามาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ

1. ตรวจสอบสภาพอากาศก่อนปฏิบัติงาน
2. ตรวจสอบสภาพอากาศก่อนปฏิบัติงาน
3. ตรวจสอบสภาพอากาศก่อนปฏิบัติงาน

ขั้นตอนที่ 4 (R4) : เลือกมาตรการป้องกันที่สำคัญ(ปฏิบัติได้จริง)จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5) : เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดนั้นตามด้วยคำว่า "OK"

ด้วยเสียงอันดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

" ตรวจสอบสภาพอากาศก่อนปฏิบัติงาน OK "

ขั้นตอนที่ 6 (R6) : มีข้อ ยินเป็นวงกลม และกล่าวพร้อมกันด้วยเสียงอันดังว่า " อุบัติเหตุเป็นศูนย์ "



ภาพประกอบ

คำอธิบายภาพ
ไหลลงบนที่สูง

วันที่ 15/03/69 เวลา น. ชื่อกลุ่ม KYT แผนก...Transport.....
ผู้เข้าร่วม KYT 1. 2.
3. 4.
5. 6.

ขั้นตอนที่ 1 (R1) : ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

- 1 ฝนตกหนักตกหนัก = ฟ้าผ่า หรือ ลมพัดแรง หรือ น้ำไหลลงจากที่สูง
- 2 คนทำงานอยู่ใกล้กัน หรือ วัตถุตกจากที่สูง
- 3 วัตถุตกจากที่สูง = ฟ้าผ่า ตกจากที่สูง หรือ ลมพัดแรง

ขั้นตอนที่ 2 (R2) : เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อที่เลือก

ขั้นตอนที่ 3 (R3) : หามาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ

- 1 ระวังอันตราย เมื่อฝนตก หรือ ลมพัดแรง
- 2 ระวังอันตราย เมื่อฝนตก หรือ ลมพัดแรง
- 3 ระวังอันตราย เมื่อฝนตก หรือ ลมพัดแรง

ขั้นตอนที่ 4 (R4) : เลือกมาตรการป้องกันที่สำคัญ (ปฏิบัติได้จริง) จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5) : เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดนั้นตามด้วยคำว่า "OK"
ด้วยเสียงอันดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

" ระวังอันตราย เมื่อฝนตก หรือ ลมพัดแรง OK "

ขั้นตอนที่ 6 (R6) : มีข้อ ยินเป็นวงกลม และกล่าวพร้อมกันด้วยเสียงอันดังว่า " อุบัติเหตุเป็นศูนย์ "



ภาพประกอบ

คำอธิบายภาพ
กะโหลกตกลงทาง

วันที่ 22/3 /68 เวลา น. ชื่อกลุ่ม KYT แผนก...Transport.....
ผู้เข้าร่วม KYT 1. 2.
3. 4.
5. 6.

ขั้นตอนที่ 1 (R1) : ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

- 1 ฟ้าผ่า ตกจากที่สูง หรือ ลมพัดแรง หรือ น้ำไหลลงจากที่สูง
- 2 คนทำงานอยู่ใกล้กัน หรือ วัตถุตกจากที่สูง
- 3 วัตถุตกจากที่สูง = ฟ้าผ่า ตกจากที่สูง หรือ ลมพัดแรง

ขั้นตอนที่ 2 (R2) : เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อที่เลือก

ขั้นตอนที่ 3 (R3) : หามาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ

- 1 ระวังอันตราย เมื่อฝนตก หรือ ลมพัดแรง
- 2 ระวังอันตราย เมื่อฝนตก หรือ ลมพัดแรง
- 3 ระวังอันตราย เมื่อฝนตก หรือ ลมพัดแรง

ขั้นตอนที่ 4 (R4) : เลือกมาตรการป้องกันที่สำคัญ (ปฏิบัติได้จริง) จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5) : เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดนั้นตามด้วยคำว่า "OK"
ด้วยเสียงอันดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

" ระวังอันตราย เมื่อฝนตก หรือ ลมพัดแรง OK "

ขั้นตอนที่ 6 (R6) : มีข้อ ยินเป็นวงกลม และกล่าวพร้อมกันด้วยเสียงอันดังว่า " อุบัติเหตุเป็นศูนย์ "



ภาพประกอบ

คำอธิบายภาพ
ของเสียที่นำมาจากลูกค้าเกิด หกรั่วไหลและ มีควันขึ้น

วันที่ 20/3/68 เวลา น. ชื่อกลุ่ม KYT แผนก...Transport.....

ผู้เข้าร่วม KYT 1. 2.
3. 4.
5. 6.

ขั้นตอนที่ 1 (R1) : ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

1. พนักงานร่วมกันได้พบ อันตราย เนื่องจากของเสียอยู่ในพื้นที่
2. ผู้ปฏิบัติงานควรระวังอันตรายจากของเสียที่หกและควันขึ้น
3. ผู้ปฏิบัติงานควรระวังอันตรายจากของเสียที่หกและควันขึ้น

ขั้นตอนที่ 2 (R2) : เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อที่เลือก

ขั้นตอนที่ 3 (R3) : หามาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ


1. พนักงานร่วมกันได้พบ อันตราย เนื่องจากของเสียอยู่ในพื้นที่
2. ผู้ปฏิบัติงานควรระวังอันตรายจากของเสียที่หกและควันขึ้น
3. ผู้ปฏิบัติงานควรระวังอันตรายจากของเสียที่หกและควันขึ้น

ขั้นตอนที่ 4 (R4) : เลือกมาตรการป้องกันที่สำคัญ(ปฏิบัติได้จริง)จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5) : เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดนี้ตามด้วยคำว่า "OK"
ด้วยเสียงอันดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

"เราจะป้องกันอันตรายจากของเสียที่หกและควันขึ้น OK"

ขั้นตอนที่ 6 (R6) : มีข้อ ยินเป็นวงกลม และกล่าวพร้อมกันด้วยเสียงอันดังว่า " อุบัติเหตุเป็นศูนย์"



ภาพประกอบ

คำอธิบายภาพ
โรงงานของ TD ไม่เปิดผ้าห่อ !!!

วันที่ 11/4/68 เวลา น. สถานที่ ห้องอาหาร

ผู้ทำ KYT แผนก FB ส่วน

ขั้นตอนที่ 1 (R1) : ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

| ใคร , ได้รับอันตรายอะไร | เนื่องจากสาเหตุ |
|---|---|
| 1 พนักงาน เกิดการลื่นล้ม | พนักงานที่ปฏิบัติงานอาจลื่นล้มตกจากที่สูงได้ |
| 2 พนักงาน ชนของ | พนักงานที่ปฏิบัติงานอาจชนของได้ |
| 3 ลูกค้า ผู้มาเยี่ยมชมโรงงาน เกิดการลื่นล้ม | ลูกค้า ผู้มาเยี่ยมชมโรงงาน อาจลื่นล้มตกจากที่สูงได้ |

ขั้นตอนที่ 2 (R2) : เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อที่เลือก

ขั้นตอนที่ 3 (R3) : หามาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ

1. พนักงาน ชนของ
2. พนักงาน ชนของ
3. ลูกค้า ผู้มาเยี่ยมชมโรงงาน

ขั้นตอนที่ 4 (R4) : เลือกมาตรการป้องกันที่สำคัญ(ปฏิบัติได้จริง)จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5) : เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดนี้ตามด้วยคำว่า "OK"
ด้วยเสียงอันดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

"เราจะป้องกันอันตรายจากของเสียที่หกและควันขึ้น OK"

ขั้นตอนที่ 6 (R6) : มีข้อ ยินเป็นวงกลม และกล่าวพร้อมกันด้วยเสียงอันดังว่า " อุบัติเหตุเป็นศูนย์"

2

WMS
WASTE MANAGEMENT SIAM LTD.

a member of

DOWA

บันทึกการทำกิจกรรม KYT

Case...15.../...20205....



ภาพประกอบ

คำอธิบายภาพ
พนักงานขับรถ วางBox โดรนบนโดโหลดของเสีย

วันที่ 9/6/25 เวลา.....น. ชื่อกลุ่ม KYT.....แผนก...Transport.....
ผู้เข้าร่วม KYT 1. กิตติกร 2.....
3..... 4.....
5..... 6.....
ขั้นตอนที่ 1 (R1): ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

- | | |
|---|------------------------------------|
| 1 | พนักงานขับรถอันตรายจากการโดนกระแทก |
| 2 | พนักงานขับรถอันตรายจากการโดนกระแทก |
| 3 | พนักงานขับรถอันตรายจากการโดนกระแทก |

ขั้นตอนที่ 2 (R2): เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อที่เลือก

ขั้นตอนที่ 3 (R3): มาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ

- | | |
|---|---|
| 1 | เลือกมาตรการป้องกันที่ปฏิบัติได้จริงจาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3 |
| 2 | เลือกมาตรการป้องกันที่ปฏิบัติได้จริงจาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3 |
| 3 | เลือกมาตรการป้องกันที่ปฏิบัติได้จริงจาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3 |

ขั้นตอนที่ 4 (R4): เลือกมาตรการป้องกันที่สำคัญ(ปฏิบัติได้จริง)จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5): เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดขึ้นตามด้วยคำว่า "OK"
ด้วยเสียงดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

" เลือกมาตรการป้องกันที่ปฏิบัติได้จริงจาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3 OK"

ขั้นตอนที่ 6 (R6): เมื่อชี้ ยืนยันเป็นวงกลม และกล่าวพร้อมกันด้วยเสียงดังว่า "อุบัติเหตุเป็นศูนย์"

4

WMS
WASTE MANAGEMENT SIAM LTD.

a member of

DOWA

บันทึกการทำกิจกรรม KYT

Case...../...2025....



ภาพประกอบ

คำอธิบายภาพ
อันตรายจากไฟลัดไฟฟ้า ไฟไหม้ที่โรง RC

วันที่ 5-5-25 เวลา 15.00 น. สถานที่ โรง RC
ผู้ทำ KYT กิตติกร แผนก FM ส่วน.....

ขั้นตอนที่ 1 (R1): ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

| ใคร , ได้รับอันตรายอะไร | เนื่องจากสาเหตุ |
|-------------------------|-----------------|
| 1 พนักงานขับรถ ไฟลัด | สิ่งไม่ระวัง |
| 2 พนักงานขับรถ ไฟลัด | สิ่งไม่ระวัง |
| 3 พนักงานขับรถ ไฟลัด | สิ่งไม่ระวัง |

ขั้นตอนที่ 2 (R2): เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อที่เลือก

ขั้นตอนที่ 3 (R3): มาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ

- | | |
|---|---|
| 1 | เลือกมาตรการป้องกันที่ปฏิบัติได้จริงจาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3 |
| 2 | เลือกมาตรการป้องกันที่ปฏิบัติได้จริงจาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3 |
| 3 | เลือกมาตรการป้องกันที่ปฏิบัติได้จริงจาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3 |

ขั้นตอนที่ 4 (R4): เลือกมาตรการป้องกันที่สำคัญ(ปฏิบัติได้จริง)จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5): เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดขึ้นตามด้วยคำว่า "OK"
ด้วยเสียงดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

" เลือกมาตรการป้องกันที่ปฏิบัติได้จริงจาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3 OK"

ขั้นตอนที่ 6 (R6): เมื่อชี้ ยืนยันเป็นวงกลม และกล่าวพร้อมกันด้วยเสียงดังว่า "อุบัติเหตุเป็นศูนย์"



ภาพประกอบ

คำอธิบายภาพ

ขณะที่พนักงานขับรถ 537 ถอยหลังเพื่อถอย ไปยังลานวางกระบะ รถ 537 ได้เกิดประตูดึงคนขึ้นครูดกับภาชนะที่
อยู่บนรถ 533 ที่จอดอยู่ด้านหน้าข้อ
ทำให้ประตูดึงได้รับความเสียหาย แต่ประตูดึงสามารถใช้งานเปิดได้ปกติ มีเพียงกระดกที่ปิดลงได้นิดเดียว

วันที่ 17/5/68 เวลา 11:20 น. สถานที่ 100% แผนก Transport

ผู้เข้าร่วม KYT 2
3
4
5
6

ขั้นตอนที่ 1 (R1): ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

| | |
|---|--|
| 1 | การนำถังขยะไปทิ้ง หรือ การปล่อยถังขยะทิ้ง |
| 2 | ไม่ ตรวจสอบจากทางรถ ว่า มีคนมาขึ้นรถ โดยรอบถังขยะ 5 เมตร รอบถังขยะ |
| 3 | ถอยรถไม่เปิดกระจก ฟังเสียง ผู้ใช้ถังขยะ หรือ การเกิดอุบัติเหตุ |

ขั้นตอนที่ 2 (R2): เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อที่เลือก

ขั้นตอนที่ 3 (R3): หารมาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ

- 1 งดรถบรรทุกไปทิ้งขยะทุกตัว ยกเว้นรถบรรทุกขยะ
- 2 มองกระจกซ้าย-ขวา ท้าย-ข้างหน้า เมื่อต้องถอยรถ
- 3 ไม่ประมาทในทุกๆ เรื่อง ในการทำงาน ไม่รบกวนในทางอื่น หรือ ระวังมากเกิน

ขั้นตอนที่ 4 (R4): เลือกมาตรการป้องกันที่สำคัญ (ปฏิบัติได้จริง) จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5): เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดนั้นตามด้วยคำว่า "OK"

ด้วยเสียงอันดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

" ระวัง ไม่ประมาทในทุกๆ เรื่อง ไม่รบกวนในทางอื่น หรือ ระวังมากเกิน " OK

ขั้นตอนที่ 6 (R6): มีข้อ ยินเป็นวงกลม และกล่าวพร้อมกันด้วยเสียงอันดังว่า " อุบัติเหตุเป็นศูนย์ "



คำอธิบายภาพ

ระหว่างทางมีรถกระบะคันหนึ่งเปลี่ยนเลนกะทันหันแล้วตัดหน้า SCP 41 คนขับเบรกรถเพื่อหยุดรถ แต่รถกระบะก็พุ่งชนกลางถนน

วันที่ 31/5/68 เวลา 10:30 น. สถานที่ บางปู

ผู้นำ KYT: ทีมงาน แผนก TD ส่วน

ขั้นตอนที่ 1 (R1): ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

| ใคร , ได้รับอันตรายอะไร | เนื่องจากสาเหตุ |
|-------------------------|---|
| 1 คนขับรถ | อุบัติเหตุจากใช้เบรคผิดจังหวะ |
| 2 คนขับรถกระบะ | อุบัติเหตุจากทางรถกระบะใช้เบรคผิดจังหวะ |
| 3 รถกระบะ | อุบัติเหตุจากทางรถกระบะใช้เบรคผิดจังหวะ |

ขั้นตอนที่ 2 (R2): เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อที่เลือก

ขั้นตอนที่ 3 (R3): หารมาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ

- 1 ระวังรถกระบะ ใช้เบรคผิดจังหวะ
- 2 ใช้เบรคให้เหมาะสม สัมกับ สภาพทาง และ สภาพแวดล้อม
- 3 ขับรถอย่างระมัดระวัง ไม่ประมาทในทุกๆ เรื่อง

ขั้นตอนที่ 4 (R4): เลือกมาตรการป้องกันที่สำคัญ (ปฏิบัติได้จริง) จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5): เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดนั้นตามด้วยคำว่า "OK"

ด้วยเสียงอันดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

" ระวัง ไม่ประมาทในทุกๆ เรื่อง ไม่รบกวนในทางอื่น หรือ ระวังมากเกิน " OK

ขั้นตอนที่ 6 (R6): มีข้อ ยินเป็นวงกลม และกล่าวพร้อมกันด้วยเสียงอันดังว่า " อุบัติเหตุเป็นศูนย์ "



ภาพประกอบ

คำอธิบายภาพ

พชร ขับรถมาจนถึงจุดสามแยกเกิดอุบัติเหตุตามภาพดังกล่าว

วันที่ ๗/๖/๒๕... เวลา... น. ชื่อกลุ่ม KYT... แผนก...Transport.....

ผู้เข้าร่วม KYT 1. กุศลิตา 2.
3. 4.
5. 6.

ขั้นตอนที่ 1 (R1): ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

1. พนักงานขับรถได้ไม่ทันหาเส้นทางหรือรถบรรทุก
2. รถยนต์สิบล้อชนกับรถจักรยานยนต์
3. พนักงานขับรถขาดสมาธิเนื่องจากเหนื่อยเกินไป

ขั้นตอนที่ 2 (R2): เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อ

ขั้นตอนที่ 3 (R3): หารมาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ

1. ติดสติ๊กเกอร์เตือนภัยบนรถบรรทุก
2. ตรวจสอบสภาพรถก่อนออกเดินทางทุกครั้ง
3.


ขั้นตอนที่ 4 (R4): เลือกมาตรการป้องกันที่สำคัญ(ปฏิบัติได้จริง)จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5): เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดนั้นตามด้วยคำว่า "OK"

ด้วยเสียงอันดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

" ระวังรถสิบล้อ ชนรถจักรยานยนต์ OK"

ขั้นตอนที่ 6 (R6): มีข้อ ยืนยันวงกลม และกล่าวพร้อมกันด้วยเสียงอันดังว่า " อุบัติเหตุเป็นศูนย์"



ภาพประกอบ

คำอธิบายภาพ

อันตรายจากอุปกรณ์ไฟฟ้า ชนน้ำท่วม

วันที่ 14/6/๒๕... เวลา 13.30 น. สถานที่ บ่อฝังกลบขยะ

ผู้ทำ KYT 10747777 แผนก FB ส่วน...

ขั้นตอนที่ 1 (R1): ค้นหาอันตรายและสาเหตุที่อาจเกิดขึ้นประมาณ 1-3 ข้อ

| ใคร , ได้รับอันตรายอะไร | เนื่องจากสาเหตุ |
|-------------------------|---------------------------------|
| 1) พนักงานขับรถ ไฟรั่ว | ฝนตกชุกท่วม |
| 2) อุปกรณ์ ไฟรั่ว | น้ำท่วมขัง อุปกรณ์ไฟฟ้าพัง |
| 3) ไฟรั่ว ขน ไฟดูด | ห้ทำงานในที่มืด ไฟรั่ว ขน ไฟดูด |

ขั้นตอนที่ 2 (R2): เลือกอันตรายและสาเหตุที่สำคัญ หรืออาจเกิดขึ้นได้มากที่สุด 1 ข้อ โดยทำเครื่องหมาย O หน้าข้อที่เลือก

ขั้นตอนที่ 3 (R3): หารมาตรการที่สามารถป้องกันอันตรายที่เกิดจากข้อที่เลือกใน R2 ประมาณ 1-3 มาตรการ

1. ติดสติ๊กเกอร์เตือนภัยบนรถบรรทุก
2. ตรวจสอบสภาพรถก่อนออกเดินทางทุกครั้ง
3.

ขั้นตอนที่ 4 (R4): เลือกมาตรการป้องกันที่สำคัญ(ปฏิบัติได้จริง)จาก R3 แล้วทำเครื่องหมาย x หน้าข้อที่เลือกใน R3

ขั้นตอนที่ 5 (R5): เรียบเรียงมาตรการป้องกันที่เลือกใน R3 แล้วกล่าวคำพูดนั้นตามด้วยคำว่า "OK"

ด้วยเสียงอันดัง 3 ครั้ง พร้อมกัน เพื่อเตือนสติ

" ระวังรถสิบล้อ ชนรถจักรยานยนต์ OK"

ขั้นตอนที่ 6 (R6): มีข้อ ยืนยันวงกลม และกล่าวพร้อมกันด้วยเสียงอันดังว่า " อุบัติเหตุเป็นศูนย์"

เอกสารแนบ 2-23

ตัวอย่างเอกสารระบบใบกำกับการขนส่งขยะของโครงการ (Waste Manifest)

เลขที่อ้างอิง 1-11-0668-132796-0-N

แบบ กอ.๒

เอกสารแสดงการจัดการ (Manifest Form)

ส่วนที่ ๑ ผู้ก่อกำเริบ

ชื่อผู้ก่อกำเริบ: บริษัท แป็คเนอร์ แมนูแฟเจอริง (ประเทศไทย) จำกัด เลขทะเบียนโรงงาน: 82370026125649
 สถานที่ตั้งโรงงาน: หมู่ที่ ถนน ตำบลหนองขาม อำเภอศรีราชา จังหวัดชลบุรี 20110
 เบอร์โทรศัพท์: เบอร์โทรศัพท์ฉุกเฉิน:
 ผู้ได้รับมอบหมายให้ขนส่งสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว:
 ชื่อผู้ขับขี่: เอกชัย การเพียร เลขทะเบียนพาหนะ: 1พร2018 กท พาหนะที่ใช้: รถบรรทุก
 โดยขนส่งจากจังหวัด: ชลบุรี ไปยังจังหวัด: สมุทรปราการ ระยะเวลาประมาณ: 1 วัน
 ผู้รับดำเนินการ: บริษัท บางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด เลขทะเบียนโรงงาน (ถ้ามี): 72020000125477
 สถานที่ตั้ง: 965 หมู่ที่ 2 ถนนสุขุมวิท ตำบลบางปูใหม่ อำเภอเมืองสมุทรปราการ จังหวัดสมุทรปราการ 10280
 เบอร์โทรศัพท์: เบอร์โทรศัพท์ฉุกเฉิน:

รายละเอียดของสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว ที่ขนส่ง:

| ลำดับ | ชื่อสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | รหัสประเภท หรือชนิด | ลักษณะบรรจุ | | ปริมาณ (ตัน) |
|-------|--------------------------------------|---------------------|-------------|-------|--------------|
| | | | ชนิด | จำนวน | |
| 1 | Glue Waste | 080409 | พาเลท | 2 | 0.04 |

รวมปริมาณทั้งหมด: ของเหลว 0.04 ตัน ของแข็ง 0 ตัน ของแข็งกึ่งเหลว 0 ตัน

[] น้ำหนักข้างจริง [X] น้ำหนักประมาณการ

ขอความร่วมมือระหว่างขนส่ง:

คำรับรอง: ข้าพเจ้าขอรับรองว่าได้ส่งมอบสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ระบุข้างต้น ปริมาณที่ส่งมอบ: 0.04 ตัน
 ซึ่งมีการบรรจุ ติดป้าย หรือฉลากอย่างเหมาะสม วันที่ส่งมอบ: 27/06/2568
 และการขนส่งจะปฏิบัติตามข้อกำหนดของกฎหมายทุกประการ เวลาที่ส่งมอบ: 08.00
 ลงชื่อผู้ก่อกำเริบ: [] วันที่: 27/6/25

ส่วนที่ ๒ รายละเอียดการขนส่งสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว

คำรับรอง: ข้าพเจ้าขอรับรองว่าได้รับสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ระบุข้างต้น ซึ่งมีการบรรจุ ติดป้าย หรือฉลากอย่างเหมาะสม และการขนส่ง
 จะปฏิบัติตามข้อกำหนดของกฎหมายทุกประการ
 ลงชื่อผู้ขับขี่: [] วันที่: 27/6/25

[] ผู้ก่อกำเริบเห็นชอบนำเอกสารการจัดการจัดการตามแผนงานส่วนที่ ๑ และส่วนที่ ๒ ครบถ้วนถูกต้องแล้ว

ส่วนที่ ๓ ผู้รับดำเนินการ

ชื่อผู้รับดำเนินการ: บริษัท บางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด เลขทะเบียนโรงงาน (ถ้ามี): 72020000125477

ส่วนที่ ๓/๑
 คำรับรอง: ข้าพเจ้าขอรับรองว่าสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ได้รับมอบหมาย
 ตามที่ระบุข้างต้นมาถึงสถานที่รับจัดการ ปริมาณที่รับมอบ: 0.440 ตัน
 ลงชื่อผู้รับดำเนินการ: [] วันที่: 27/6/25 เวลาที่มาถึง: 13.35

ส่วนที่ ๓/๒
 คำรับรอง: ข้าพเจ้าขอรับรองว่ารับจัดการสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ระบุข้างต้น ปริมาณที่รับมอบ: 0.440 ตัน
 ซึ่งมีการบรรจุ ติดป้าย หรือฉลากอย่างเหมาะสม วันที่รับมอบ: 28/6/25 เวลาที่มอบ: 13.45
 ลงชื่อผู้รับดำเนินการ: [] วันที่: 28/6/25 [X] ภาพถ่ายสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว และ/หรือ [] เอกสารแสดงลักษณะสำคัญของสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว

ส่วนที่ ๓/๓
 คำรับรอง: ข้าพเจ้าขอรับรองว่าจัดการสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ได้รับมอบหมายแล้วเสร็จ ปริมาณที่จัดการแล้วเสร็จ: 0.440 ตัน
 ลงชื่อผู้รับดำเนินการ: [] วันที่: 28/6/25 เวลาที่จัดการแล้วเสร็จ: 14.00
 [X] ภาพถ่ายเอกสารการจัดการที่ลงนามครบถ้วนถูกต้อง

ส่วนที่ ๔ ผู้ก่อกำเริบสรุปผลการจัดการ

คำรับรอง: ข้าพเจ้าขอรับรองว่าสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ระบุข้างต้น

- [] ได้รับการจัดการแล้วเสร็จตามที่ได้รับอนุญาตแล้ว (ส่วนที่ ๓)
 [] ได้รับการจัดการแล้วเสร็จตามที่ได้รับอนุญาตแล้ว (ส่วนที่ ๔)
 [] ได้รับคืนจากผู้รับดำเนินการแล้ว (ส่วนที่ ๖)
 [] ได้รับการจัดการแล้วเสร็จโดยผู้รับจัดการรายใหม่ตามที่ได้รับอนุญาตแล้ว (ส่วนที่ ๗)

ลงชื่อผู้ก่อกำเริบ: ลายมือชื่อ: วันที่:

เลขที่อ้างอิง 3-11-0668-138538-0-N

เอกสารแสดงการจัดการ (Manifest Form)

ส่วนที่ ๑ ผู้ก่อกำเริบ

ชื่อผู้ก่อกำเริบ: บริษัท พารา ฟาร์มาซูติคอล จำกัด เลขทะเบียนโรงงาน: 10101700125465
 สถานที่ตั้งโรงงาน: 379 หมู่ที่ ถนนอิสราภาพ แขวงวัดอรุณ เขตบางกอกใหญ่ กรุงเทพมหานคร 10600
 เบอร์โทรศัพท์: เบอร์โทรศัพท์ฉุกเฉิน:
 ผู้ได้รับมอบหมายให้ขนส่งสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว:
 ชื่อผู้ขับขี่: นายปราโมทย์ แหทอง เลขทะเบียนพาหนะ: 2ผอ-2324 กท พาหนะที่ใช้: รถทั่วไป
 โดยขนส่งจากจังหวัด: กรุงเทพมหานคร ไปยังจังหวัด: สมุทรปราการ ระยะเวลาประมาณ: 1 วัน
 ผู้รับดำเนินการ: บริษัท บางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด เลขทะเบียนโรงงาน (ถ้ามี): 72020000125477
 สถานที่ตั้ง: 965 หมู่ที่ 2 ถนนสุขุมวิท ตำบลบางปูใหม่ อำเภอเมืองสมุทรปราการ จังหวัดสมุทรปราการ 10280
 เบอร์โทรศัพท์: เบอร์โทรศัพท์ฉุกเฉิน:

รายละเอียดของสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว ที่ขนส่ง:

| ลำดับ | ชื่อสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | รหัสประเภท หรือชนิด | ลักษณะบรรจุ | | ปริมาณ (ตัน) |
|-------|---------------------------------------|---------------------|----------------|-------|--------------|
| | | | ชนิด | จำนวน | |
| 1 | Write Off Product ผลิตภัณฑ์ไม้มาตรฐาน | 160306 | กล่องลังลูกฟูก | 80 | 1.0 |

รวมปริมาณทั้งหมด: ของเหลว 0 ตัน ของแข็ง 0 ตัน ของแข็งกึ่งเหลว 1 ตัน

[] น้ำหนักข้างจริง [X] น้ำหนักประมาณการ

ขอความร่วมมือระหว่างขนส่ง:

คำรับรอง: ข้าพเจ้าขอรับรองว่าได้ส่งมอบสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ระบุข้างต้น ปริมาณที่ส่งมอบ: 1 ตัน
 ซึ่งมีการบรรจุ ติดป้าย หรือฉลากอย่างเหมาะสม วันที่ส่งมอบ: 28/06/2568
 และการขนส่งจะปฏิบัติตามข้อกำหนดของกฎหมายทุกประการ เวลาที่ส่งมอบ: 13.15
 ลงชื่อผู้ก่อกำเริบ: [] วันที่: 28/6/25

ส่วนที่ ๒ รายละเอียดการขนส่งสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว

คำรับรอง: ข้าพเจ้าขอรับรองว่าได้รับสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ระบุข้างต้น ซึ่งมีการบรรจุ ติดป้าย หรือฉลากอย่างเหมาะสม และการขนส่ง
 จะปฏิบัติตามข้อกำหนดของกฎหมายทุกประการ

ลงชื่อผู้ขับขี่: [] วันที่: 28/6/25
 [] ผู้ก่อกำเริบเห็นชอบนำเอกสารการจัดการจัดการตามแผนงานส่วนที่ ๑ และส่วนที่ ๒ ครบถ้วนถูกต้องแล้ว

ส่วนที่ ๓ ผู้รับดำเนินการ

ชื่อผู้รับดำเนินการ: บริษัท บางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด เลขทะเบียนโรงงาน (ถ้ามี): 72020000125477

ส่วนที่ ๓/๑
 คำรับรอง: ข้าพเจ้าขอรับรองว่าสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ได้รับมอบหมาย
 ตามที่ระบุข้างต้นมาถึงสถานที่รับจัดการ ปริมาณที่รับมอบ: 1.12 ตัน
 ลงชื่อผู้รับดำเนินการ: [] วันที่: 28/6/25 เวลาที่มาถึง: 16.40

ส่วนที่ ๓/๒
 คำรับรอง: ข้าพเจ้าขอรับรองว่ารับจัดการสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ระบุข้างต้น ปริมาณที่รับมอบ: 1.12 ตัน
 ซึ่งมีการบรรจุ ติดป้าย หรือฉลากอย่างเหมาะสม วันที่รับมอบ: 28/6/25 เวลาที่มอบ: 16.45
 ลงชื่อผู้รับดำเนินการ: [] วันที่: 29/6/25 [X] ภาพถ่ายสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว และ/หรือ [] เอกสารแสดงลักษณะสำคัญของสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว

ส่วนที่ ๓/๓
 คำรับรอง: ข้าพเจ้าขอรับรองว่าจัดการสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ได้รับมอบหมายแล้วเสร็จ ปริมาณที่จัดการแล้วเสร็จ: 1.12 ตัน
 ลงชื่อผู้รับดำเนินการ: [] วันที่: 28/6/25 เวลาที่จัดการแล้วเสร็จ: 18.00
 [X] ภาพถ่ายเอกสารการจัดการที่ลงนามครบถ้วนถูกต้อง

ส่วนที่ ๔ ผู้ก่อกำเริบสรุปผลการจัดการ

คำรับรอง: ข้าพเจ้าขอรับรองว่าสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วตามที่ระบุข้างต้น

- [] ได้รับการจัดการแล้วเสร็จตามที่ได้รับอนุญาตแล้ว (ส่วนที่ ๓)
 [] ได้รับการจัดการแล้วเสร็จตามที่ได้รับอนุญาตแล้ว (ส่วนที่ ๔)
 [] ได้รับคืนจากผู้รับดำเนินการแล้ว (ส่วนที่ ๖)
 [] ได้รับการจัดการแล้วเสร็จโดยผู้รับจัดการรายใหม่ตามที่ได้รับอนุญาตแล้ว (ส่วนที่ ๗)

ลงชื่อผู้ก่อกำเริบ: ลายมือชื่อ: วันที่:

เอกสารแนบ 2-24

รายงานการตรวจสอบสภาพยานพาหนะ

Daily Truck Inspection Sheet

รายการตรวจสภาพรถประจำวัน

05-TD-F001/06

| | | | |
|--------------------------|-----------|-----------------------|--------|
| Date/วันที่ | 29/1/2025 | TD/Sup./MGR. | |
| Truck NO./หมายเลขรถ | Rel 606 | เลขไมล์ | 237779 |
| Trailer NO./รถพ่วงและหาง | No | Driver Name/ชื่อคนขับ | |

| NO. | Item Inspection รายการที่ตรวจสอบ | Detail Of Inspection รายการในการตรวจสอบ | Condition สภาพ | Before ก่อนวิ่ง | After หลังวิ่ง | Remark รายละเอียด |
|-----|--|---|-------------------|--------------------|-------------------|----------------------|
| 1 | Radiator หม้อน้ำ | Water Amount/Leaking ระดับน้ำ พอ/ไม่พอ/รั่ว/ไม่รั่ว | ปกติ ไม่ปกติ | | ✓ | 606 ok. |
| 2 | Fan Belt สายพานพัดลม | Tention/Broken หย่อน/เสียแล้ว | ปกติ ไม่ปกติ | | ✓ | |
| 3 | Lube Oil น้ำมันหล่อลื่น | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | | ✓ | |
| 4 | Brake Oil น้ำมันเบรค | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | | ✓ | |
| 5 | Clutch Oil น้ำมันคลัชช | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | | ✓ | |
| 6 | Washer Tanker ถังน้ำฉีดกระจก | Amount Leaking/Clog ระดับพอดิ/มีการรั่วซึม/อุดตัน | ปกติ ไม่ปกติ | | ✓ | |
| 7 | Traffic Light หลอดไฟต่างๆ | Dirty/Broken/No Light/Horns สกปรก/แตก/ไม่ติด/แต่ริไม่ดัง | ปกติ ไม่ปกติ | | ✓ | |
| 8 | Engine เครื่องยนต์ | Ignition/Noisy/High/Low Rotation สตาร์ท/เสียงดัง/เกียร์สูงต่ำเข้ายาก | ปกติ ไม่ปกติ | | ✓ | |
| 9 | Wiper ก้านปัดน้ำฝน | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | | ✓ | |
| 10 | Hand Brake เบรคมือ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | | ✓ | |
| 11 | Air Brake ลมเบรค | Airpressure/Leaking/Exhaust แรงดันดี/รั่ว/ระบายดี | ปกติ ไม่ปกติ | | ✓ | |
| 12 | Brake of truck เบรคตัวรถ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | | ✓ | |
| 13 | Brake of trailer เบรคหางพ่วง | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | | ✓ | |
| 14 | Tire ยาง | Airpressure/Abrasion/Broken แรงดันลม/ดอกยาง/รั่ว-มีรอยขาด | ปกติ ไม่ปกติ | | ✓ | |
| 15 | Wheel & Bolt ล้อกระทะ/น๊อต | Cracking/Lousen/Broken ร้าว-แตก/น๊อตหลวม/แตก | ปกติ ไม่ปกติ | | ✓ | |
| 16 | Fuel Tank ถังน้ำมัน | Leak Cap & Hose Condition รั่ว/ฝาปิดชำรุด/สายน้ำมันชำรุด | ปกติ ไม่ปกติ | | ✓ | |
| 17 | Air Tank ถังลม | Water Clotting มีน้ำมากเกินไป | ปกติ ไม่ปกติ | | ✓ | |
| 18 | Battery แบตเตอรี่ | Liquid Level/Electric Line ระดับน้ำกลั่น/สายไฟแบตเตอรี่ | ปกติ ไม่ปกติ | | ✓ | |
| 19 | Battery Box กล่องแบตเตอรี่ | Cable Condition/Terminal สภาพสายเคเบิล/เชลของแบตเตอรี่ | ปกติ ไม่ปกติ | | ✓ | |
| 20 | Leaf Sping แหนบรค | Break/Crack แตก-หัก/มีรอยร้าว | ปกติ ไม่ปกติ | | ✓ | |
| 21 | Air Condition ระบบแอร์ | Leaking/Not Cool/Dirty รั่ว/ไม่เย็น/สกปรก | ปกติ ไม่ปกติ | | ✓ | |
| 22 | Mirror กระจก | Broken/Unadjustable แตก-หัก/ปรับไม่ได้ | ปกติ ไม่ปกติ | | ✓ | |
| 23 | Interior In Cap สภาพในห้องโดยสาร | Tare/Dirty/Broken เบาะขาด/สกปรก/คอนโซลแตก | ปกติ ไม่ปกติ | | ✓ | |
| 24 | Mile Meter เรือนไมล์และเกย์วัด | Not Work/No Light ไม่ทำงาน/ไม่มีแสงสว่าง | ปกติ ไม่ปกติ | | ✓ | |
| 25 | Trailer Condition สภาพรถพ่วงโดยรวม | Light/Air Break/Locking/Tire หลอดไฟ/ลมเบรค/ทวนพับ/ยาง | ปกติ ไม่ปกติ | | ✓ | |
| 26 | Document truck & trailer เอกสารประจำรถทัว หาง | Hr. Permit / Regist / Ins. วอ.8 / ทะเบียน / ประกัน | ปกติ ไม่ปกติ | | ✓ | |
| 27 | Coupling ตัวล๊อคคต่อหาง | Work/Damage ใช้งานได้/ชำรุด | ปกติ ไม่ปกติ | | ✓ | |
| 28 | Fire Extinguisher ถังดับเพลิง | Pressure OK แรงดันของถังอยู่ในช่องที่กำหนด | ปกติ ไม่ปกติ | | ✓ | |
| 29 | Capping ฝาครอบท่อ | Ready to use พร้อมใช้งาน | ปกติ ไม่ปกติ | | ✓ | |
| 30 | Rope เชือกมัดท่อ | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | | ✓ | |
| 31 | Hose สายยาง | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | | ✓ | |
| 32 | Steel pole เสาปักคอก | Ready to use สภาพพร้อมใช้งาน และติดตั้งเรียบร้อยก่อนออกงาน | ปกติ ไม่ปกติ | | ✓ | |
| 33 | Webbing Sling สลิงผ้าใบรัดกันตก | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | | ✓ | |

Effective Date : November 25nd.2024.

All Item Must Be Check Daily, Specialty When Need To Go Long Distances, รายละเอียดต่างๆต้องตรวจสอบทุกวันโดยเฉพาะเมื่อต้องเดินทางไกล

โปรดตรวจสอบอย่างละเอียด

Daily Truck Inspection Sheet

รายการตรวจสภาพรถประจำวัน

05-TD-F001/06

| | | | |
|--------------------------|-----------|-----------------------|--------|
| Date/วันที่ | 24/2/2025 | TD/Sup./MGR. | |
| Truck NO./หมายเลขรถ | Rel 606 | เลขไมล์ | 241721 |
| Trailer NO./รถพ่วงและหาง | No | Driver Name/ชื่อคนขับ | |

| NO. | Item Inspection รายการที่ตรวจสอบ | Detail Of Inspection รายการในการตรวจสอบ | Condition สภาพ | Before ก่อนวิ่ง | After หลังวิ่ง | Remark รายละเอียด |
|-----|--|---|-------------------|--------------------|-------------------|----------------------|
| 1 | Radiator หม้อน้ำ | Water Amount/Leakng ระดับน้ำ พอ/ไม่พอ/รั่ว/ไม่รั่ว | ปกติ ไม่ปกติ | ✓ | ✓ | ปาลิดถังน้ำมันชำรุด |
| 2 | Fan Belt สายพานพัดลม | Tention/Broken หย่อน/เสียแล้ว | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 3 | Lube Oil น้ำมันหล่อลื่น | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 4 | Brake Oil น้ำมันเบรค | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 5 | Clutch Oil น้ำมันคลัชช | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 6 | Washer Tanker ถังน้ำฉีดกระจก | Amount Leaking/Clog ระดับพอดิ/มีการรั่วซึม/อุดตัน | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 7 | Traffic Light หลอดไฟต่างๆ | Dirty/Broken/No Light/Horns สกปรก/แตก/ไม่ติด/แต่ริไม่ดัง | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 8 | Engine เครื่องยนต์ | Ignition/Noisy/High/Low Rotation สตาร์ท/เสียงดัง/เกียร์สูงต่ำเข้ายาก | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 9 | Wiper ก้านปัดน้ำฝน | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 10 | Hand Brake เบรคมือ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 11 | Air Brake ลมเบรค | Airpressure/Leaking/Exhaust แรงดันดี/รั่ว/ระบายดี | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 12 | Brake of truck เบรคตัวรถ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 13 | Brake of trailer เบรคหางพ่วง | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 14 | Tire ยาง | Airpressure/Abrasion/Broken แรงดันลม/ดอกยาง/รั่ว-มีรอยขาด | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 15 | Wheel & Bolt ล้อกระทะ/น๊อต | Cracking/Lousen/Broken ร้าว-แตก/น๊อตหลวม/แตก | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 16 | Fuel Tank ถังน้ำมัน | Leak Cap & Hose Condition รั่ว/ฝาปิดชำรุด/สายน้ำมันชำรุด | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 17 | Air Tank ถังลม | Water Clotting มีน้ำมากเกินไป | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 18 | Battery แบตเตอรี่ | Liquid Level/Electric Line ระดับน้ำกลั่น/สายไฟแบตเตอรี่ | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 19 | Battery Box กล่องแบตเตอรี่ | Cable Condition/Terminal สภาพสายเคเบิล/เชลของแบตเตอรี่ | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 20 | Leaf Sping แหนบรค | Break/Crack แตก-หัก/มีรอยร้าว | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 21 | Air Condition ระบบแอร์ | Leaking/Not Cool/Dirty รั่ว/ไม่เย็น/สกปรก | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 22 | Mirror กระจก | Broken/Unadjustable แตก-หัก/ปรับไม่ได้ | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 23 | Interior In Cap สภาพในห้องโดยสาร | Tare/Dirty/Broken เบาะขาด/สกปรก/คอนโซลแตก | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 24 | Mile Meter เรือนไมล์และเกย์วัด | Not Work/No Light ไม่ทำงาน/ไม่มีแสงสว่าง | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 25 | Trailer Condition สภาพรถพ่วงโดยรวม | Light/Air Break/Locking/Tire หลอดไฟ/ลมเบรค/ทวนพับ/ยาง | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 26 | Document truck & trailer เอกสารประจำรถทัว หาง | Hr. Permit / Regist / Ins. วอ.8 / ทะเบียน / ประกัน | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 27 | Coupling ตัวล๊อคคต่อหาง | Work/Damage ใช้งานได้/ชำรุด | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 28 | Fire Extinguisher ถังดับเพลิง | Pressure OK แรงดันของถังอยู่ในช่องที่กำหนด | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 29 | Capping ฝาครอบท่อ | Ready to use พร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 30 | Rope เชือกมัดท่อ | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 31 | Hose สายยาง | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 32 | Steel pole เสาปักคอก | Ready to use สภาพพร้อมใช้งาน และติดตั้งเรียบร้อยก่อนออกงาน | ปกติ ไม่ปกติ | ✓ | ✓ | |
| 33 | Webbing Sling สลิงผ้าใบรัดกันตก | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ | ✓ | |

Effective Date : November 25nd.2024.

All Item Must Be Check Daily, Specialty When Need To Go Long Distances, รายละเอียดต่างๆต้องตรวจสอบทุกวันโดยเฉพาะเมื่อต้องเดินทางไกล

โปรดตรวจสอบอย่างละเอียด

Daily Truck Inspection Sheet

รายการตรวจสภาพรถประจำวัน

05-TD-F001/06

| | | | |
|--------------------------|----------|-----------------------|--------|
| Date/วันที่ | 8/3/2025 | TD/Sup./MGR. | |
| Truck NO./หมายเลขรถ | Rel 606 | เลขไมล์ | 243734 |
| Trailer NO./รถพ่วงและหาง | No | Driver Name/ชื่อคนขับ | |

| NO. | Item Inspection รายการที่ตรวจสอบ | Detail Of Inspection รายการในการตรวจสอบ | Condition สภาพ | Before ก่อนวิ่ง | After หลังวิ่ง | Remark รายละเอียด |
|-----|--|---|-------------------|--------------------|-------------------|---|
| 1 | Radiator หม้อน้ำ | Water Amount/Leaking ระดับน้ำ พอ/ไม่พอ/รั่ว/ไม่รั่ว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | 1.ฝ่าฝืนถึงน้ำมันชำรุด 2.ยางตำแหน่ง 5 หมุดตก |
| 2 | Fan Belt สายพานพัดลม | Tention/Broken หย่อน/เสียแล้ว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 3 | Lube Oil น้ำมันหล่อลื่น | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 4 | Brake Oil น้ำมันเบรค | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 5 | Clutch Oil น้ำมันคลัชช | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 6 | Washer Tanker ถังน้ำฉีดกระจก | Amount Leaking/Clog ระดับพอดิ/มีการรั่วซึม/อุดตัน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 7 | Traffic Light หลอดไฟต่างๆ | Dirty/Broken/No Light/Horns สกปรก/แตก/ไม่ติด/แต่ร์ไม่ดัง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 8 | Engine เครื่องยนต์ | Ignition/Noisy/High/Low Rotation สตาร์ท/เสียงดัง/เกียร์สูงต่ำเข้ายาก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 9 | Wiper ก้านปัดน้ำฝน | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 10 | Hand Brake เบรคมือ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 11 | Air Brake ลมเบรค | Airpressure/Leaking/Exhaust แรงดันดี/รั่ว/ระบายดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 12 | Brake of truck เบรคตัวรถ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 13 | Brake of trailer เบรคหางพ่วง | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 14 | Tire ยาง | Airpressure/Abrasion/Broken แรงดันลม/ดอกยาง/รั่ว-มีรอยขาด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 15 | Wheel & Bull ล้อกระทะ/น๊อต | Cracking/Loosen/Broken ร้าว-แตก/น๊อตหลวม/แตก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 16 | Fuel Tank ถังน้ำมัน | Leak Cap & Hose Condition รั่ว/ฝาปิดชำรุด/สายน้ำมันชำรุด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 17 | Air Tank ถังลม | Water Clotting มีน้ำมากเกินไป | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 18 | Battery แบตเตอรี่ | Liquid Level/Electric Line ระดับน้ำกลั่น/สายไฟแบตเตอรี่ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 19 | Battery Box กล่องแบตเตอรี่ | Cable Condition/Terminal สภาพสายเคเบิล/เชลของแบตเตอรี่ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 20 | Leaf Sping แหนบรค | Break/Crack แตก-หัก/มีรอยร้าว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 21 | Air Condition ระบบแอร์ | Leaking/Not Cool/Dirty รั่ว/ไม่เย็น/สกปรก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 22 | Mirror กระจก | Broken/Unadjustable แตก-หัก/ปรับไม่ได้ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 23 | Interior In Cap สภาพในห้องโดยสาร | Tare/Dirty/Broken เบาะขาด/สกปรก/คอนโซลแตก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 24 | Mile Meter เรือนไมล์และเกย์วัด | Not Work/No Light ไม่ทำงาน/ไม่มีแสงสว่าง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 25 | Trailer Condition สภาพรถพ่วงโดยรวม | Light/Air Break/Locking/Tire หลอดไฟ/ลมเบรค/ทวนพับ/ยาง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 26 | Document truck & trailer เอกสารประจำรถทัว หาง | Hr. Permit / Regist / Ins. วอ.8 / ทะเบียน / ประกัน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 27 | Coupling ตัวล๊อคคต่อหาง | Work/Damage ใช้งานได้/ชำรุด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 28 | Fire Extinguisher ถังดับเพลิง | Pressure OK แรงดันของถังอยู่ในช่องที่กำหนด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 29 | Capping ฝาครอบท่อ | Ready to use พร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 30 | Rope เชือกรัดท่อ | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 31 | Hose สายยาง | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 32 | Steel pole เสาปักคอก | Ready to use สภาพพร้อมใช้งาน และติดตั้งเรียบร้อยก่อนออกงาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 33 | Webbing Sling สลิงผ้าใบรัดกันตก | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |

Effective Date : November 25nd.2024.

All Item Must Be Check Daily, Specialty When Need To Go Long Distances, รายละเอียดต่างๆต้องตรวจสอบทุกวันโดยเฉพาะเมื่อต้องเดินทางไกล

โปรดตรวจสอบอย่างละเอียด

Daily Truck Inspection Sheet

รายการตรวจสภาพรถประจำวัน

05-TD-F001/06

| | | | |
|--------------------------|-----------|-----------------------|--------|
| Date/วันที่ | 30/4/2025 | TD/Sup./MGR. | |
| Truck NO./หมายเลขรถ | Rel 606 | เลขไมล์ | 251981 |
| Trailer NO./รถพ่วงและหาง | No | Driver Name/ชื่อคนขับ | |

| NO. | Item Inspection รายการที่ตรวจสอบ | Detail Of Inspection รายการในการตรวจสอบ | Condition สภาพ | Before ก่อนวิ่ง | After หลังวิ่ง | Remark รายละเอียด |
|-----|--|---|-------------------|--------------------|-------------------|----------------------|
| 1 | Radiator หม้อน้ำ | Water Amount/Leaking ระดับน้ำ พอ/ไม่พอ/รั่ว/ไม่รั่ว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 2 | Fan Belt สายพานพัดลม | Tention/Broken หย่อน/เสียแล้ว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 3 | Lube Oil น้ำมันหล่อลื่น | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 4 | Brake Oil น้ำมันเบรค | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 5 | Clutch Oil น้ำมันคลัชช | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 6 | Washer Tanker ถังน้ำฉีดกระจก | Amount Leaking/Clog ระดับพอดิ/มีการรั่วซึม/อุดตัน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 7 | Traffic Light หลอดไฟต่างๆ | Dirty/Broken/No Light/Horns สกปรก/แตก/ไม่ติด/แต่ร์ไม่ดัง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 8 | Engine เครื่องยนต์ | Ignition/Noisy/High/Low Rotation สตาร์ท/เสียงดัง/เกียร์สูงต่ำเข้ายาก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 9 | Wiper ก้านปัดน้ำฝน | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 10 | Hand Brake เบรคมือ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 11 | Air Brake ลมเบรค | Airpressure/Leaking/Exhaust แรงดันดี/รั่ว/ระบายดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 12 | Brake of truck เบรคตัวรถ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 13 | Brake of trailer เบรคหางพ่วง | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 14 | Tire ยาง | Airpressure/Abrasion/Broken แรงดันลม/ดอกยาง/รั่ว-มีรอยขาด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 15 | Wheel & Bull ล้อกระทะ/น๊อต | Cracking/Loosen/Broken ร้าว-แตก/น๊อตหลวม/แตก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 16 | Fuel Tank ถังน้ำมัน | Leak Cap & Hose Condition รั่ว/ฝาปิดชำรุด/สายน้ำมันชำรุด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 17 | Air Tank ถังลม | Water Clotting มีน้ำมากเกินไป | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 18 | Battery แบตเตอรี่ | Liquid Level/Electric Line ระดับน้ำกลั่น/สายไฟแบตเตอรี่ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 19 | Battery Box กล่องแบตเตอรี่ | Cable Condition/Terminal สภาพสายเคเบิล/เชลของแบตเตอรี่ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 20 | Leaf Sping แหนบรค | Break/Crack แตก-หัก/มีรอยร้าว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 21 | Air Condition ระบบแอร์ | Leaking/Not Cool/Dirty รั่ว/ไม่เย็น/สกปรก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 22 | Mirror กระจก | Broken/Unadjustable แตก-หัก/ปรับไม่ได้ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 23 | Interior In Cap สภาพในห้องโดยสาร | Tare/Dirty/Broken เบาะขาด/สกปรก/คอนโซลแตก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 24 | Mile Meter เรือนไมล์และเกย์วัด | Not Work/No Light ไม่ทำงาน/ไม่มีแสงสว่าง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 25 | Trailer Condition สภาพรถพ่วงโดยรวม | Light/Air Break/Locking/Tire หลอดไฟ/ลมเบรค/ทวนพับ/ยาง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 26 | Document truck & trailer เอกสารประจำรถทัว หาง | Hr. Permit / Regist / Ins. วอ.8 / ทะเบียน / ประกัน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 27 | Coupling ตัวล๊อคคต่อหาง | Work/Damage ใช้งานได้/ชำรุด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 28 | Fire Extinguisher ถังดับเพลิง | Pressure OK แรงดันของถังอยู่ในช่องที่กำหนด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 29 | Capping ฝาครอบท่อ | Ready to use พร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 30 | Rope เชือกรัดท่อ | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 31 | Hose สายยาง | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 32 | Steel pole เสาปักคอก | Ready to use สภาพพร้อมใช้งาน และติดตั้งเรียบร้อยก่อนออกงาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 33 | Webbing Sling สลิงผ้าใบรัดกันตก | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |

Effective Date : November 25nd.2024.

All Item Must Be Check Daily, Specialty When Need To Go Long Distances, รายละเอียดต่างๆต้องตรวจสอบทุกวันโดยเฉพาะเมื่อต้องเดินทางไกล

โปรดตรวจสอบอย่างละเอียด

Daily Truck Inspection Sheet

รายการตรวจสอบสภาพรถประจำวัน

05-TD-F001/06

| | | | |
|--------------------------|-----------|-----------------------|--------|
| Date/วันที่ | 16/5/2025 | TD/Sup./MGR. | |
| Truck NO./หมายเลขรถ | Rel 606 | เลขไมล์ | 254217 |
| Trailer NO./รถพ่วงและหาง | No | Driver Name/ชื่อคนขับ | |

| NO. | Item Inspection รายการที่ตรวจสอบ | Detail Of Inspection รายการในการตรวจสอบ | Condition สภาพ | Before ก่อนวิ่ง | After หลังวิ่ง | Remark รายละเอียด |
|-----|--|---|-------------------|--------------------|-------------------|----------------------|
| 1 | Radiator หม้อน้ำ | Water Amount/Leaking ระดับน้ำ พอ/ไม่พอ/รั่ว/ไม่รั่ว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 2 | Fan Belt สายพานพัดลม | Tention/Broken หย่อน/เสียแล้ว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 3 | Lube Oil น้ำมันหล่อลื่น | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 4 | Brake Oil น้ำมันเบรค | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 5 | Clutch Oil น้ำมันคลัชช | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 6 | Washer Tanker ถังน้ำฉีดกระจก | Amount Leaking/Clog ระดับพอดิ/มีการรั่วซึม/อุดตัน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 7 | Traffic Light หลอดไฟต่างๆ | Dirty/Broken/No Light/Horns สกปรก/แตก/ไม่ติด/แต่ร์ไม่ดัง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 8 | Engine เครื่องยนต์ | Ignition/Noisy/High/Low Rotation สตาร์ท/เสียงดัง/เกียร์สูงต่ำเข้ายาก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 9 | Wiper ก้านปัดน้ำฝน | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 10 | Hand Brake เบรคมือ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 11 | Air Brake ลมเบรค | Airpressure/Leaking/Exhaust แรงดันดี/รั่ว/ระบายดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 12 | Brake of truck เบรคตัวรถ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 13 | Brake of trailer เบรคหางพ่วง | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 14 | Tire ยาง | Airpressure/Abrasion/Broken แรงดันลม/ดอกยาง/รั่ว-มีรอยขาด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 15 | Wheel & Bolt ล้อกระทะ/น๊อต | Cracking/Loosen/Broken ร้าว-แตก/น๊อตหลวม/แตก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 16 | Fuel Tank ถังน้ำมัน | Leak Cap & Hose Condition รั่ว/ฝาปิดชำรุด/สายน้ำมันชำรุด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 17 | Air Tank ถังลม | Water Clotting มีน้ำมากเกินไป | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 18 | Battery แบตเตอรี่ | Liquid Level/Electric Line ระดับน้ำกลั่น/สายไฟแบตเตอรี่ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 19 | Battery Box กล่องแบตเตอรี่ | Cable Condition/Terminal สภาพสายเคเบิล/เชลของแบตเตอรี่ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 20 | Leaf Sping แหนบรค | Break/Crack แตก-หัก/มีรอยร้าว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 21 | Air Condition ระบบแอร์ | Leaking/Not Cool/Dirty รั่ว/ไม่เย็น/สกปรก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 22 | Mirror กระจก | Broken/Unadjustable แตก-หัก/ปรับไม่ได้ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 23 | Interior In Cap สภาพในห้องโดยสาร | Tare/Dirty/Broken เบาะขาด/สกปรก/คอนโซลแตก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 24 | Mile Meter เรือนไมล์และเกย์วัด | Not Work/No Light ไม่ทำงาน/ไม่มีแสงสว่าง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 25 | Trailer Condition สภาพรถพ่วงโดยรวม | Light/Air Break/Locking/Tire หลอดไฟ/ลมเบรค/ทวนพับ/ยาง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 26 | Document truck & trailer เอกสารประจำรถทัว หาง | Hr. Permit / Regist / Ins. วอ.8 / ทะเบียน / ประกัน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 27 | Coupling ตัวล็อกคต่อหาง | Work/Damage ใช้งานได้/ชำรุด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 28 | Fire Extinguisher ถังดับเพลิง | Pressure OK แรงดันของถังอยู่ในช่องที่กำหนด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 29 | Capping ฝาครอบท่อ | Ready to use พร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 30 | Rope เชือกรัดท่อ | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 31 | Hose สายยาง | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 32 | Steel pole เสาปักคอก | Ready to use สภาพพร้อมใช้งาน และติดตั้งเรียบร้อยก่อนออกงาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 33 | Webbing Sling สลิงผ้าไนร็คกันตก | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |

Effective Date : November 25nd.2024.

All Item Must Be Check Daily, Specialty When Need To Go Long Distances, รายละเอียดต่างๆต้องตรวจสอบทุกวันโดยเฉพาะเมื่อต้องเดินทางไกล

โปรดตรวจสอบอย่างละเอียด

Daily Truck Inspection Sheet

รายการตรวจสอบสภาพรถประจำวัน

05-TD-F001/06

| | | | |
|--------------------------|----------|-----------------------|--------|
| Date/วันที่ | 9/6/2025 | TD/Sup./MGR. | |
| Truck NO./หมายเลขรถ | Rel 606 | เลขไมล์ | 256806 |
| Trailer NO./รถพ่วงและหาง | No | Driver Name/ชื่อคนขับ | |

| NO. | Item Inspection รายการที่ตรวจสอบ | Detail Of Inspection รายการในการตรวจสอบ | Condition สภาพ | Before ก่อนวิ่ง | After หลังวิ่ง | Remark รายละเอียด |
|-----|--|---|-------------------|--------------------|-------------------|---|
| 1 | Radiator หม้อน้ำ | Water Amount/Leaking ระดับน้ำ พอ/ไม่พอ/รั่ว/ไม่รั่ว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | 1.เบรคมือดีแล้วรถไหล 2. ยางตำแหน่ง 3456 หมด คอก |
| 2 | Fan Belt สายพานพัดลม | Tention/Broken หย่อน/เสียแล้ว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 3 | Lube Oil น้ำมันหล่อลื่น | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 4 | Brake Oil น้ำมันเบรค | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 5 | Clutch Oil น้ำมันคลัชช | Amount Leaking ระดับพอดิ/มีการรั่วซึม | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 6 | Washer Tanker ถังน้ำฉีดกระจก | Amount Leaking/Clog ระดับพอดิ/มีการรั่วซึม/อุดตัน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 7 | Traffic Light หลอดไฟต่างๆ | Dirty/Broken/No Light/Horns สกปรก/แตก/ไม่ติด/แต่ร์ไม่ดัง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 8 | Engine เครื่องยนต์ | Ignition/Noisy/High/Low Rotation สตาร์ท/เสียงดัง/เกียร์สูงต่ำเข้ายาก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 9 | Wiper ก้านปัดน้ำฝน | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 10 | Hand Brake เบรคมือ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 11 | Air Brake ลมเบรค | Airpressure/Leaking/Exhaust แรงดันดี/รั่ว/ระบายดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 12 | Brake of truck เบรคตัวรถ | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 13 | Brake of trailer เบรคหางพ่วง | Good/No Good ดี/ไม่ดี | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 14 | Tire ยาง | Airpressure/Abrasion/Broken แรงดันลม/ดอกยาง/รั่ว-มีรอยขาด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 15 | Wheel & Bolt ล้อกระทะ/น๊อต | Cracking/Loosen/Broken ร้าว-แตก/น๊อตหลวม/แตก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 16 | Fuel Tank ถังน้ำมัน | Leak Cap & Hose Condition รั่ว/ฝาปิดชำรุด/สายน้ำมันชำรุด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 17 | Air Tank ถังลม | Water Clotting มีน้ำมากเกินไป | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 18 | Battery แบตเตอรี่ | Liquid Level/Electric Line ระดับน้ำกลั่น/สายไฟแบตเตอรี่ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 19 | Battery Box กล่องแบตเตอรี่ | Cable Condition/Terminal สภาพสายเคเบิล/เชลของแบตเตอรี่ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 20 | Leaf Sping แหนบรค | Break/Crack แตก-หัก/มีรอยร้าว | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 21 | Air Condition ระบบแอร์ | Leaking/Not Cool/Dirty รั่ว/ไม่เย็น/สกปรก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 22 | Mirror กระจก | Broken/Unadjustable แตก-หัก/ปรับไม่ได้ | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 23 | Interior In Cap สภาพในห้องโดยสาร | Tare/Dirty/Broken เบาะขาด/สกปรก/คอนโซลแตก | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 24 | Mile Meter เรือนไมล์และเกย์วัด | Not Work/No Light ไม่ทำงาน/ไม่มีแสงสว่าง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 25 | Trailer Condition สภาพรถพ่วงโดยรวม | Light/Air Break/Locking/Tire หลอดไฟ/ลมเบรค/ทวนพับ/ยาง | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 26 | Document truck & trailer เอกสารประจำรถทัว หาง | Hr. Permit / Regist / Ins. วอ.8 / ทะเบียน / ประกัน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 27 | Coupling ตัวล็อกคต่อหาง | Work/Damage ใช้งานได้/ชำรุด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 28 | Fire Extinguisher ถังดับเพลิง | Pressure OK แรงดันของถังอยู่ในช่องที่กำหนด | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 29 | Capping ฝาครอบท่อ | Ready to use พร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 30 | Rope เชือกรัดท่อ | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 31 | Hose สายยาง | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 32 | Steel pole เสาปักคอก | Ready to use สภาพพร้อมใช้งาน และติดตั้งเรียบร้อยก่อนออกงาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |
| 33 | Webbing Sling สลิงผ้าไนร็คกันตก | Ready to use สภาพพร้อมใช้งาน | ปกติ ไม่ปกติ | ✓ ✓ | ✓ ✓ | |

Effective Date : November 25nd.2024.

All Item Must Be Check Daily, Specialty When Need To Go Long Distances, รายละเอียดต่างๆต้องตรวจสอบทุกวันโดยเฉพาะเมื่อต้องเดินทางไกล

โปรดตรวจสอบอย่างละเอียด

เอกสารแนบ 2-25

บันทึกการคัดแยกของเสีย

| Date:14 Jan | | | | Supervisor: Surasak Kittichokmontree | |
|--|-----------------------------|----------|--------------------------------------|--------------------------------------|-------------------|
| Waste Receiving | | | | | |
| No. | Truck No. | Driver | Customer Names | Waste Type | Weight/Kg. |
| 1 | 53-8459 | | LAZADA EXPRESS LTD. | Commercial waste | 690 |
| 2 | 52-6052 | | LAZADA EXPRESS LIMITED. | Commercial waste | 200 |
| 3 | 87-2173 | | BANGPOO ENVIRONMENTAL COMPLEX | Multi-Load Transaction | 3,420 |
| 4 | 87-2173 | | BANGPOO ENVIRONMENTAL COMPLEX | Multi-Load Transaction | 2,650 |
| 5 | 74-9321 | | BANGPOO ENVIRONMENTAL COMPLEX | Multi-Load Transaction | 1,423 |
| 6 | 74-9321 | | BANGPOO ENVIRONMENTAL COMPLEX | Multi-Load Transaction | 3,820 |
| 7 | 608 | | BANGPOO ENVIRONMENTAL COMPLEX | Multi-Load Transaction | 3,790 |
| 8 | 608 | | BANGPOO ENVIRONMENTAL COMPLEX | Multi-Load Transaction | 1,910 |
| 9 | 608 | | BANGPOO ENVIRONMENTAL COMPLEX | Multi-Load Transaction | 2,120 |
| 10 | 539 | | UNILEVER THAI HOLDINGS LIMITED | waste finished product | 7,980 |
| 11 | 53-8458 | | P.M.A.P.R.CO.,LTD. | Out of spec products | 21,310 |
| 12 | 52-6052 | | WAN THAI FOODS INDUSTRY CO., LTD. (P | Seasoning | 4,700 |
| 13 | 53-8458 | | SINO PACIFIC TRADING (THAILAND) CO. | Write-Off Product | 13,720 |
| 14 | 99-3430 | | SINO PACIFIC TRADING (THAILAND) CO. | Write-Off Product | 12,620 |
| 15 | 51-3328 | | SINO PACIFIC TRADING (THAILAND) CO. | Write-Off Product | 12,220 |
| 16 | 99-3429 | | DECATHLON THAILAND CO.,LTD. (BANG | Commercial waste | 640 |
| 17 | 62-7708 | | AMCOR FLEXIBLES CHONBURI CO.,LTD. | Commercial waste | 700 |
| 18 | 621 | | BANGPOO ENVIRONMENTAL COMPLEX | Multi-Load Transaction | 2,143 |
| 19 | 606 | | BANGPOO ENVIRONMENTAL COMPLEX | Multi-Load Transaction | 2,110 |
| 20 | 606 | | BANGPOO ENVIRONMENTAL COMPLEX | Multi-Load Transaction | 3,510 |
| 21 | 99-3431 | | AB FOOD & BEVERAGES (THAILAND) LTD | Industrial Non Hazardous waste | 1,722 |
| 22 | 99-3431 | | NEOCOSMED CO.,LTD. | Non-hazardous industrial waste | 1,436 |
| 23 | 99-3431 | | NEOCOSMED CO.,LTD. | Rejected products | 1,561 |
| 24 | 99-3431 | | NEOCOSMED CO.,LTD. | Off Spec | 67 |
| 25 | 99-3431 | | NEOCOSMED CO.,LTD. | Sludge from the treatment system | 6,500 |
| 26 | 99-3431 | | NEOCOSMED CO.,LTD. | Air Filter | 46 |
| 27 | 99-3431 | | AB FOOD & BEVERAGES (THAILAND) LTD | Off Spec | 1,058 |
| 28 | 607 | | WMS DEPOT CO., | Multi-Load Transaction | 2,985 |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Waste Sorting: | | | | Total | 117,051.00 |
| No. | Material Type | Quantity | Storage Area | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Hazardous / PVC waste found | | | | | |
| <input type="checkbox"/> Yes | <input type="checkbox"/> No | If yes | Please specific waste type | Quantity | Source / Handling |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Other Tasks / Toolbox Meeting | | | | | |
| No | Task Description | Progress | Time | Remark | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Shredder Feeding Time (start and finish time): | | | | | |
| Overtime (persons and hours): | | | | | |

Prepared by

Approved by

Supervisor

Manager

| | | | | | |
|--|-----------------------------|----------|-----------------------------------|--------------------------------------|-------------------|
| Date: 22 Feb | | | | Supervisor: Surasak Kittichokmontree | |
| Waste Receiving | | | | | |
| No. | Truck No. | Driver | Customer Names | Waste Type | Weight/Kg. |
| 1 | 53-8458 | | L'OREAL (THAILAND) LTD. | Expired Product (Cosmetics) | 6,930 |
| 2 | 73-8998 | | L'OREAL (THAILAND) LTD. | Expired Product (Cosmetics) | 7,070 |
| 3 | 99-3430 | | L'OREAL (THAILAND) LTD. | Expired Product (Cosmetics) | 5,800 |
| 4 | 69-9833 | | L'OREAL (THAILAND) LTD. | Expired Product (Cosmetics) | 7,990 |
| 5 | 53-8459 | | UNILEVER THAI HOLDINGS LIMITED | Commercial waste | 3,740 |
| 6 | 52-6052 | | WIN CHANCE FOODS CO.,LTD. | Expired Products | 12,590 |
| 7 | 53-8459 | | UNILEVER THAI HOLDINGS LIMITED | waste finished product | 4,400 |
| 8 | 53-8459 | | UNILEVER THAI HOLDINGS LIMITED | General mix waste | 8,910 |
| 9 | 99-5203 | | DHL SUPPLY CHAIN (THAILAND) CO.,L | Commercial waste | 3,440 |
| 10 | 99-3429 | | DHL SUPPLY CHAIN (THAILAND) CO.,L | Commercial waste | 3,120 |
| 11 | 521 | | LAZADA EXPRESS LTD. | Commercial waste | 1,000 |
| 12 | 534 | | BEIERSDORF (THAILAND) CO.,LTD. | Expired Packaging | 1,930 |
| 13 | 520 | | SSL MANUFACTURING (THAILAND) LT | Industrial Non-Hazardous Waste | 910 |
| 14 | 2324 | | UENO FINE CHEMICALS INDUSTRY (T | Packaging from food material | 480 |
| 15 | 99-3428 | | DANONE SPECIALIZED NUTRITION (TH | Packaging plastic | 1,800 |
| 16 | 621 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 4,460 |
| 17 | 606 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 4,030 |
| 18 | 606 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 3,530 |
| 19 | 606 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 1,700 |
| 20 | 74-9321 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 1,970 |
| 21 | 74-9321 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 3,080 |
| 22 | 608 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 2,530 |
| 23 | 608 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 3,390 |
| 24 | 608 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 2,710 |
| 25 | 607 | | WMS DEPOT CO., | Multi-Load Transaction | 3,065 |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Waste Sorting: | | | | Total | 100,575.00 |
| No. | Material Type | Quantity | Storage Area | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Hazardous / PVC waste found | | | | | |
| <input type="checkbox"/> Yes | <input type="checkbox"/> No | If yes | Please specific waste type | Quantity | Source / Handling |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Other Tasks / Toolbox Meeting | | | | | |
| No | Task Description | Progress | Time | Remark | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Shredder Feeding Time (start and finish time): | | | | | |
| Overtime (persons and hours): | | | | | |
| | | | | | |

Prepared by

Approved by

Supervisor

.....
Manager

BPEC Recycling Department Daily Work Report

รายงานการปฏิบัติงานประจำวันของแผนกใช้เคล็ด บางปู

| | | | | | |
|--|-----------------------------|----------|--------------------------------------|--------------------------------|-------------------|
| Date: 5 Mar | | | Supervisor: Surasak Kittichokmontree | | |
| Waste Receiving | | | | | |
| No. | Truck No. | Driver | Customer Names | Waste Type | Weight/Kg. |
| 1 | 53-6741 | | WONGPANIT SUVARNABHUMI RECYC | Out of spec products | 3,080 |
| 2 | 99-5162 | | WONGPANIT SUVARNABHUMI RECYC | Out of spec products | 2,950 |
| 3 | 53-8459 | | ESSILOR MANUFACTURING (THAILAN | Commercial Waste | 2,630 |
| 4 | 53-8458 | | IKANO (THAILAND) LIMITED | General Waste | 1,970 |
| 5 | 99-3429 | | SSL MANUFACTURING (THAILAND) LT | Industrial Non-Hazardous Waste | 880 |
| 6 | 63-5874 | | DUNLOP SRIXON SPORTS MANUFACT | Industrial non hazardous waste | 2,970 |
| 7 | 99-3429 | | FRIESLANDCAMPINA (THAILAND) PCL | Dairy waste | 6,620 |
| 8 | 539 | | UNILEVER THAI HOLDINGS LIMITED | waste finished product | 8,340 |
| 9 | 539 | | UNILEVER THAI HOLDINGS LIMITED | Rejected Product | 3,620 |
| 10 | 52-6052 | | UNILEVER THAI HOLDINGS LIMITED | General mix waste | 6,460 |
| 11 | 98-4300 | | WONGPANIT SUVARNABHUMI RECYC | Out of spec products | 3,010 |
| 12 | 606 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 4,810 |
| 13 | 606 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 1,810 |
| 14 | 606 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 3,220 |
| 15 | 606 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 1,810 |
| 16 | 608 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 2,920 |
| 17 | 608 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 2,760 |
| 18 | 608 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 2,800 |
| 19 | 608 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 3,900 |
| 20 | 621 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 5,229 |
| 21 | 74-9321 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 2,358 |
| 22 | 74-9321 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 3,760 |
| 23 | 607 | | WMS DEPOT CO., | Multi-Load Transaction | 4,035 |
| 24 | 99-3431 | | MOTEMI CO., LTD. | Expired raw materials | 75 |
| 25 | 99-3431 | | BONDI FOODS CO.,LTD. | Expired raw materials | 53 |
| 26 | | | | | |
| | | | | | |
| | | | | | |
| Waste Sorting: | | | Total | 82,070.00 | |
| No. | Material Type | Quantity | Storage Area | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Hazardous / PVC waste found | | | | | |
| <input type="checkbox"/> Yes | <input type="checkbox"/> No | If yes | Please specific waste type | Quantity | Source / Handling |
| | | | | | |
| | | | | | |
| | | | | | |
| Other Tasks / Toolbox Meeting | | | | | |
| No | Task Description | Progress | Time | Remark | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Shredder Feeding Time (start and finish time): | | | | | |
| Overtime (persons and hours): | | | | | |

Prepared by

Approved by

Supervisor

Manager

BPEC Recycling Department Daily Work Report

รายงานการปฏิบัติงานประจำวันของแผนกใช้เคล็ด บางปู

| | | | | | |
|--|-----------------------------|----------|--------------------------------------|---|-------------------|
| Date: 28 Apr | | | Supervisor: Surasak Kittichokmontree | | |
| Waste Receiving | | | | | |
| No. | Truck No. | Driver | Customer Names | Waste Type | Weight/Kg. |
| 1 | 539 | | ESSILOR MANUFACTURING (THAILAN | Commercial Waste | 2,890 |
| 2 | 2018 | | IKANO (THAILAND) LIMITED | General Waste | 470 |
| 3 | 4619 | | LG HOUSEHOLD & HEALTH CARE (TH | Write off product (cosmetics and skin cre | 790 |
| 4 | 53-8459 | | FRIESLANDCAMPINA (THAILAND) PCL | Dairy waste | 10,230 |
| 5 | 88-1056 | | UNILEVER THAI TRADING LIMITED | Commercial Waste | 560 |
| 6 | 53-8459 | | UNILEVER THAI HOLDINGS LIMITED | waste finished product | 6,970 |
| 7 | 53-1511 | | ZUELLIG PHARMA LTD. | Damaged Product & Expired Product | 8,660 |
| 8 | LV139 | | UENO FINE CHEMICALS INDUSTRY (T | Packaging from food material | 560 |
| 9 | 53-1135 | | AGC FLAT GLASS (THAILAND) PLC. | Commercial Waste | 2,020 |
| 10 | 536 | | SINO PACIFIC TRADING (THAILAND) C | Plastic package | 1,320 |
| 11 | 606 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 3,220 |
| 12 | 606 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 3,470 |
| 13 | 608 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 3,790 |
| 14 | 608 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 2,850 |
| 15 | 608 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 3,240 |
| 16 | 621 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 4,070 |
| 17 | 621 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 1,060 |
| 18 | 609 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 4,190 |
| 19 | 609 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 4,190 |
| 20 | 609 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 4,340 |
| 21 | 53-1135 | | DKSH (THAILAND) LIMITED | Expired Product | 7,450 |
| 22 | 538 | | UNI-CHARM (THAILAND) CO.,LTD. | Industrial Non Hazardous Waste | 2,600 |
| 23 | 538 | | UNI-CHARM (THAILAND) CO.,LTD. | Sanitary napkin and panty liner | 6,670 |
| 24 | 61-5391 | | UNION DRUG LABS. LTD. | Off Spec Packaging | 3,791 |
| 25 | 607 | | WMS DEPOT CO., | Multi-Load Transaction | 778 |
| 26 | 618 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 4,390 |
| 27 | 618 | | BANGPOO ENVIRONMENTAL COMPLE | Multi-Load Transaction | 2,008 |
| | | | | | |
| | | | | | |
| | | | | | |
| Waste Sorting: | | | Total | 96,577.00 | |
| No. | Material Type | Quantity | Storage Area | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Hazardous / PVC waste found | | | | | |
| <input type="checkbox"/> Yes | <input type="checkbox"/> No | If yes | Please specific waste type | Quantity | Source / Handling |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Other Tasks / Toolbox Meeting | | | | | |
| No | Task Description | Progress | Time | Remark | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Shredder Feeding Time (start and finish time): | | | | | |
| Overtime (persons and hours): | | | | | |

Prepared by

Approved by

Supervisor

Manager

BPEC Recycling Department Daily Work Report

รายงานการปฏิบัติงานประจำวันของแผนกใช้เคิล บางปู

| Date: 6 May | | | | Supervisor: Surasak Kittichokmontree | |
|--|-----------------------------|----------|---|--------------------------------------|-------------------|
| Waste Receiving | | | | | |
| No. | Truck No. | Driver | Customer Names | Waste Type | Weight/Kg. |
| 1 | 52-6052 | | LAZADA EXPRESS LIMITED | Commercial waste | 990 |
| 2 | 53-8459 | | FRIESLANDCAMPINA (THAILAND) PCL | Dairy waste | 7,070 |
| 3 | 61-5391 | | SANKO MACHINERY (THAILAND) CO.,LTD | Foil Packaging | 840 |
| 4 | 2018 | | UENO FINE CHEMICALS INDUSTRY (THAILAND) CO.,LTD | Packaging from food material | 450 |
| 5 | 537 | | THAI-JAPANESE ASSOCIATION SCHOOL | Old Document | 4,660 |
| 6 | 52-6051 | | BRIDGESTONE TIRE MANUFACTURING CO.,LTD | Commercial waste | 6,270 |
| 7 | 53-1135 | | S.E.A CONSUMER PRODUCT CO.,LTD | Write-Off Product | 15,970 |
| 8 | LV140 | | THAI JAPANESE ASSOCIATION SCHOOL | Textbook | 1,080 |
| 9 | 52-6051 | | NEOCOSMED CO.,LTD. | Air Filter | 52 |
| 10 | 52-6051 | | NEOCOSMED CO.,LTD. | Rejected products | 411 |
| 11 | 52-6051 | | NEOCOSMED CO.,LTD. | Non-hazardous industrial waste | 3,193 |
| 12 | 52-6051 | | NEOCOSMED CO.,LTD. | Sludge from the treatment system | 4,650 |
| 13 | 52-6051 | | NEOCOSMED CO.,LTD. | Off Spec | 74 |
| 14 | 533 | | MILOTT LABORATORIES CO.,LTD. | Plastic Packaging | 9,930 |
| 15 | 53-8459 | | UNILEVER THAI HOLDINGS LIMITED | waste finished product | 7,160 |
| 16 | 539 | | UNILEVER THAI HOLDINGS LIMITED | Rejected Product | 9,750 |
| 17 | | | | | |
| 18 | | | | | |
| 19 | | | | | |
| 20 | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Waste Sorting: | | | Total | 72,550.00 | |
| No. | Material Type | Quantity | Storage Area | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Hazardous / PVC waste found | | | | | |
| <input type="checkbox"/> Yes | <input type="checkbox"/> No | If yes | Please specific waste type | Quantity | Source / Handling |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Other Tasks / Toolbox Meeting | | | | | |
| No | Task Description | Progress | Time | Remark | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Shredder Feeding Time (start and finish time): | | | | | |
| Overtime (persons and hours): | | | | | |
| | | | | | |

Prepared by

Approved by

Supervisor

Manager

เอกสารแนบ 2-26

ผลการวิเคราะห์ลักษณะสมบัติของทรายและเถ้าหนักก่อนส่งกำจัด

Test Report

Report No. : RE25-02-051_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-02-026
Sample Name : Bottom Ash
Waste Profile No. : -
Sampling By : Korrawit Y. (๙-371-๙-0001)

Sampling Date : 10/01/2025
Sampling Time : 07:00 AM
Sampling Received Date : 10/01/2025
Sample Test Date : 17/02/2025
Report Date : 18/02/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.1 °C | US EPA. 9040C, 9045D ^[1, 2] | pH unit | 10.6 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4, 5] | mg/kg | 63.4 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4, 5] | mg/kg | 23.5 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4, 5] | mg/kg | 1,357 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4, 5] | mg/kg | <2.00 | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4, 5] | mg/kg | 2.59 | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4, 5] | mg/kg | 222 | 0.26 | 5.00 | ≤2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4, 5] | mg/kg | 28.9 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4, 5] | mg/kg | 885 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4, 5] | mg/kg | 113 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4, 5] | mg/kg | 42.1 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4, 5] | mg/kg | 127 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4, 5] | mg/kg | 33.0 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4, 5] | mg/kg | 4.83 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4, 5] | mg/kg | 16.3 | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4, 5] | mg/kg | 113 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4, 5] | mg/kg | 3,572 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996


^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTL = Total Threshold Limit Concentration.


LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(๙-371-๙-0001)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)

Test Report

Report No. : RE25-02-051_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-02-026
Sample Name : Bottom Ash
Waste Profile No. : -
Sampling By : Korrawit Y. (๙-371-๙-0001)

Sampling Date : 10/01/2025
Sampling Time : 07:00 AM
Sampling Received Date : 10/01/2025
Sample Test Date : 17/02/2025
Report Date : 18/02/2025

| Test Parameter | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/Kg | 6,836 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[1, 2] | mg/kg | 456 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[1, 2] | mg/kg | 11,657 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[3] | mg/kg | 0.051 | 0.002 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[2] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation),


SW-846 Method 7473, 2007.

EPA = U.S. Environmental Protection Agency.


LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(18 / 02 / 2025)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(18 / 02 / 2025)

Test Report

Report No. : RE25-02-051_3
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-02-026
Sample Name : Bottom Ash
Waste Profile No. : -
Sampling By : Korrawit Y. (๕371-๙-0001)

Sampling Date : 10/01/2025
Sampling Time : 07:00 AM
Sampling Received Date : 10/01/2025
Sample Test Date : 17/02/2025
Report Date : 18/02/2025

| Test Parameter | Method | Method |
|----------------------------|------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Brown | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Homogeneous | |
| - Odor | Mild (None) | |
| - State | Solid (Lump) | |
| pH | 10 | ASTM D4980-89 |
| Temperature | 25.5 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Soluble 1% and Sink 99%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Positive (Generated air bubbles) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Reported By :

Korrawit Yothawong
Laboratory Staff
(18 / 02 / 2025)



Reviewed By :

Ampol Ruttanasang
Laboratory Controller
(18 / 02 / 2025)

Test Report

Report No. : RE25-02-068_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-02-041
Sample Name : Bottom Ash
Waste Profile No. : -
Sampling By : Korrawit Y. (๕-371-๙-0001)

Sampling Date : 13/02/2025
Sampling Time : 03:00 PM
Sampling Received Date : 14/02/2025
Sample Test Date : 26/02/2025
Report Date : 28/02/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.4 °C | US EPA. 9040C, 9045D ^[1, 2] | pH unit | 10.0 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4, 5] | mg/kg | 54.0 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4, 5] | mg/kg | 33.1 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4, 5] | mg/kg | 203 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4, 5] | mg/kg | 2.79 | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4, 5] | mg/kg | 41.9 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4, 5] | mg/kg | 8.16 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4, 5] | mg/kg | 19.4 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4, 5] | mg/kg | 50.5 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4, 5] | mg/kg | 6.03 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4, 5] | mg/kg | 23.8 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4, 5] | mg/kg | 45.8 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4, 5] | mg/kg | <2.00 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4, 5] | mg/kg | 19.3 | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4, 5] | mg/kg | 129 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4, 5] | mg/kg | 71.0 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996


^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTL = Total Threshold Limit Concentration.


LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(๕-371-๙-0001)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(๕-371-๙-0001)

Test Report

Report No. : RE25-02-068_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-02-041
Sample Name : Bottom Ash
Waste Profile No. : -
Sampling By : Korrawit Y. (๕-371-๙-0001)

Sampling Date : 13/02/2025
Sampling Time : 03:00 PM
Sampling Received Date : 14/02/2025
Sample Test Date : 26/02/2025
Report Date : 28/02/2025

| Test Parameter* | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/kg | 473 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4, 5] | mg/kg | 287 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4, 5] | mg/kg | 147 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[6] | mg/kg | <0.005 | 0.002 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation),


SW-846 Method 7473, 2007.

EPA = U.S. Environmental Protection Agency.


LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(28 / 02 / 2025)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(28 / 02 / 2025)

Test Report

Report No. : RE25-02-068_3

Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description


Sample No. : LA25-02-041
Sample Name : Bottom Ash
Waste Profile No. : -
Sampling By : Korrawit Y. (T-371-9-0001)

Sampling Date : 13/02/2025
Sampling Time : 03:00 PM
Sampling Received Date : 14/02/2025
Sample Test Date : 26/02/2025
Report Date : 28/02/2025


| Test Parameter | Method | Method |
|----------------------------|------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Brown | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Heterogeneous | |
| - Odor | Mild (None) | |
| - State | Solid (Lump) | |
| pH | 10 | ASTM D4980-89 |
| Temperature | 25.4 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Soluble 1% and Sink 99%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Negative | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(28 / 02 / 2025)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(28 / 02 / 2025)

Test Report

Report No. : RE25-04-025_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-03-063
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)

Sampling Date : 29/03/2025
Sampling Time : 03:00 PM
Sampling Received Date : 31/03/2025
Sample Test Date : 28/04/2025
Report Date : 28/04/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.5 °C | US EPA. 9040C, 9045D ^[1, 2] | pH unit | 9.1 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4, 5] | mg/kg | 68.9 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4, 5] | mg/kg | 5.69 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4, 5] | mg/kg | 269 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4, 5] | mg/kg | 60.9 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4, 5] | mg/kg | 3.11 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4, 5] | mg/kg | 245 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4, 5] | mg/kg | 17.4 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4, 5] | mg/kg | 996 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4, 5] | mg/kg | 24.8 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4, 5] | mg/kg | 5.99 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4, 5] | mg/kg | 2.40 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4, 5] | mg/kg | 3.27 | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4, 5] | mg/kg | 182 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4, 5] | mg/kg | 406 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DiW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTL = Total Threshold Limit Concentration. LOQ = Level of Quantitation.
ND = Not detected. MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(๙-371-๙-0002)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)

Test Report

Report No. : RE25-04-024_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-03-063
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)

Sampling Date : 29/03/2025
Sampling Time : 03:00 PM
Sampling Received Date : 31/03/2025
Sample Test Date : 28/04/2025
Report Date : 28/04/2025

| Test Parameter* | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/kg | 3,630 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4, 5] | mg/kg | 88.3 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4, 5] | mg/kg | 9,413 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[6] | mg/kg | 0.804 | 0.002 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation),

SW-846 Method 7473, 2007.

EPA = U.S. Environmental Protection Agency.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(28 / 04 / 2025)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(28 / 04 / 2025)

Test Report

Report No. : RE25-04-024_3
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-03-063
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (๒-๓71-๙-๐002)

Sampling Date : 29/03/2025
Sampling Time : 03:00 PM
Sampling Received Date : 31/03/2025
Sample Test Date : 28/04/2025
Report Date : 28/04/2025

| Test Parameter | Method | Method |
|----------------------------|------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Gray and brown | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Heterogeneous | |
| - Odor | Slightly (None) | |
| - State | Solid (Lump and bottom) | |
| pH | 9 | ASTM D4980-89 |
| Temperature | 27.2 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Soluble 1% and Sink 99%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Positive (Generated air bubbles) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(28 / 04 / 2025)



Reviewed By : [Signature]
Ampol Ruttanasang
Laboratory Controller
(28 / 04 / 2025)

Test Report

Report No. : RE25-05-035_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-04-036
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (S-371-A-0002)

Sampling Date : 28/04/2025
Sampling Time : 01:30 PM
Sampling Received Date : 28/04/2025
Sample Test Date : 08/05/2025
Report Date : 30/05/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 26.2 °C | US EPA. 9040C, 9045D ^[1, 2] | pH unit | 10.3 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4, 5] | mg/kg | 53.4 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4, 5] | mg/kg | 15.9 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4, 5] | mg/kg | 1,633 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4, 5] | mg/kg | 178 | 0.26 | 5.00 | ≤2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4, 5] | mg/kg | 22.1 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4, 5] | mg/kg | 551 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4, 5] | mg/kg | 64.9 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4, 5] | mg/kg | 33.0 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4, 5] | mg/kg | 136 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4, 5] | mg/kg | 23.9 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4, 5] | mg/kg | 4.14 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4, 5] | mg/kg | 9.41 | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4, 5] | mg/kg | 60.2 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4, 5] | mg/kg | 2,406 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. **D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020**

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. **SW-846 Method 3050B, 1996**

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. **SW-846 Method 6010C, 2007.**

TTL = Total Threshold Limit Concentration. LOQ = Level of Quantitation.
ND = Not detected. MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(S-371-A-0002)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(S-371-A-0001)

Test Report

Report No. : RE25-05-035_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-04-036
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (S-371-A-0002)

Sampling Date : 28/04/2025
Sampling Time : 01:30 PM
Sampling Received Date : 28/04/2025
Sample Test Date : 08/05/2025
Report Date : 30/05/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|-------|--------|
| Chloride (Cl) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/kg | 13,081 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4, 5] | mg/kg | 290 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4, 5] | mg/kg | 7,198 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[6] | mg/kg | <0.005 | 0.002 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[6] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation).

SW-846 Method 7473, 2007.

EPA = U.S. Environmental Protection Agency.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(30 / 05 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(30 / 05 / 2025)

Test Report

Report No. : RE25-05-035_3
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-04-036
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (๗-371-๙-0002)

Sampling Date : 28/04/2025
Sampling Time : 01:30 PM
Sampling Received Date : 28/04/2025
Sample Test Date : 08/05/2025
Report Date : 30/05/2025

| Test Parameter | Method | Method |
|----------------------------|------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Black and gray | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Heterogeneous | |
| - Odor | Slightly (None) | |
| - State | Solid (Lump) | |
| pH | 10 | ASTM D4980-89 |
| Temperature | 25.9 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Insoluble and Sink 100%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Positive (Generated air bubbles) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(30 / 05 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(30 / 05 / 2025)

Test Report

Report No. : RE25-05-038_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-05-033
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)
Sampling Date : 21/05/2025
Sampling Time : 011:30 AM
Sampling Received Date : 23/05/2025
Sample Test Date : 29/05/2025
Report Date : 30/05/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 24.8 °C | US EPA. 9040C, 9045D ^[1,2] | pH unit | 10.7 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4,5] | mg/kg | 38.8 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | 24.5 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4,5] | mg/kg | 1,332 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | 187 | 0.26 | 5.00 | ≤2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4,5] | mg/kg | 18.3 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 677 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | 44.1 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4,5] | mg/kg | 31.7 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | 140 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4,5] | mg/kg | 38.3 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4,5] | mg/kg | 3.02 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4,5] | mg/kg | 13.9 | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4,5] | mg/kg | 82.9 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 2,424 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTL = Total Threshold Limit Concentration.

ND = Not detected.

LOQ = Level of Quantitation.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(๙-371-๙-0002)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)

Site office : 965 Moo 2 Soi 3, Bangpoo Industrial Estate, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn,
Samutprakarn, Thailand 10280 Tel: (66)-2-709-2546 Fax: (66)-2-709-2547
Bangkok office : 589/142 Central City Tower 1, 25 th Floor, Bangna-trad Road, Kwaeng Bangna, Khet Bangna, Bangkok, Thailand 10260
Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928 http://www.wms-thailand.com E-mail: info@wms-thailand.com

Test Report

Report No. : RE25-05-038_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-05-033
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)
Sampling Date : 21/05/2025
Sampling Time : 011:30 AM
Sampling Received Date : 23/05/2025
Sample Test Date : 29/05/2025
Report Date : 30/05/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|-------|--------|
| Chloride (Cl) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/kg | 9,655 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4,5] | mg/kg | 334 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4,5] | mg/kg | 3,050 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[6] | mg/kg | <0.005 | 0.002 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation).

SW-846 Method 7473, 2007.

EPA = U.S. Environmental Protection Agency.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(30 / 05 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(30 / 05 / 2025)

Site office : 965 Moo 2 Soi 3, Bangpoo Industrial Estate, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn,
Samutprakarn, Thailand 10280 Tel: (66)-2-709-2546 Fax: (66)-2-709-2547
Bangkok office : 589/142 Central City Tower 1, 25 th Floor, Bangna-trad Road, Kwaeng Bangna, Khet Bangna, Bangkok, Thailand 10260
Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928 http://www.wms-thailand.com E-mail: info@wms-thailand.com

Test Report

Report No. : RE25-05-038_3
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-05-033
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (#371-9-0002)

Sampling Date : 21/05/2025
Sampling Time : 011:30 AM
Sampling Received Date : 23/05/2025
Sample Test Date : 29/05/2025
Report Date : 30/05/2025

| Test Parameter | Method | Method |
|----------------------------|------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Brown, gray and white | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Heterogeneous | |
| - Odor | Slightly (None) | |
| - State | Solid (Lump) | |
| pH | 10 | ASTM D4980-89 |
| Temperature | 25.1 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Insoluble and Sink 100%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Negative | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(30 / 05 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(30 / 05 / 2025)

Test Report

Report No. : RE25-07-022_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-06-062
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)
Sampling Date : 23/06/2025
Sampling Time : 09:00 AM
Sampling Received Date : 23/06/2025
Sample Test Date : 01/07/2025
Report Date : 02/07/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.7 °C | US EPA. 9040C,9045D ^[1,2] | pH unit | 9.8 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTLIC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4,5] | mg/kg | 79.4 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | 34.1 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4,5] | mg/kg | 1,603 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | 326 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4,5] | mg/kg | 30.3 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 1,576 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | 62.6 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4,5] | mg/kg | 44.8 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | 333 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4,5] | mg/kg | 55.7 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4,5] | mg/kg | 13.3 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4,5] | mg/kg | 20.0 | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4,5] | mg/kg | 106 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 1,986 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTLIC = Total Threshold Limit Concentration. LOQ = Level of Quantitation.
ND = Not detected. MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(๙-371-๙-0002)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)

Test Report

Report No. : RE25-07-022_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-06-062
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)
Sampling Date : 23/06/2025
Sampling Time : 09:00 AM
Sampling Received Date : 23/06/2025
Sample Test Date : 01/07/2025
Report Date : 02/07/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|-------|--------|
| Chloride (Cl) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/kg | 4,027 |

TTLIC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4,5] | mg/kg | 355 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4,5] | mg/kg | 8,604 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[6] | mg/kg | 0.025 | 0.002 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation),
SW-846 Method 7473, 2007.

EPA = U.S. Environmental Protection Agency. LOQ = Level of Quantitation.
ND = Not detected. MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(02 / 07 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(02 / 07 / 2025)

Test Report

Report No. : RE25-07-022_3

Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-06-062
Sample Name : Bottom ash
Waste Profile No. : -
Sampling By : Watcharee S. (9-371-9-0002)

Sampling Date : 23/06/2025
Sampling Time : 09:00 AM
Sampling Received Date : 23/06/2025
Sample Test Date : 01/07/2025
Report Date : 02/07/2025

| Test Parameter | Method | Method |
|----------------------------|--|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Brown | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Heterogeneous | |
| - Odor | Slightly (None) | |
| - State | Solid (Lump) | |
| pH | 11 | ASTM D4980-89 |
| Temperature | 25.1 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Soluble 1% and Sink 99%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Positive (Generate air bubbles and Temperature increase) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(02 / 07 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(02 / 07 / 2025)

เอกสารแนบ 2-27

ผลการวิเคราะห์ลักษณะสมบัติของถ้ำลอย

Test Report

Report No. : RE25-02-050_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-02-025
Sample Name : Fly Ash
Waste Profile No. : -
Sampling By : Korrawit Y. (9-371-9-0001)
Sampling Date : 10/01/2025
Sampling Time : 07:00 AM
Sampling Received Date : 10/01/2025
Sample Test Date : 17/02/2025
Report Date : 18/02/2025

| Test Parameter | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/Kg | 59,022 |


TTLIC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[1, 2] | mg/kg | 228 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[1, 2] | mg/kg | 13,336 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[3] | mg/kg | 2.22 | 0.002 | 0.005 | <20 |


The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. **SW-846 Method 3050B, 1996**
^[2] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. **SW-846 Method 6010C, 2007**
^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation), **SW-846 Method 7473, 2007.**

EPA = U.S. Environmental Protection Agency. LOQ = Level of Quantitation.
ND = Not detected. MDL = Method Detection Limit.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(18 / 02 / 2025)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(18 / 02 / 2025)

Test Report

Report No. : RE25-02-050_3
Revision No. : 0


Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description


Sample No. : LA25-02-025
Sample Name : Fly Ash
Waste Profile No. : -
Sampling By : Korrawit Y. (9-371-9-0001)
Sampling Date : 10/01/2025
Sampling Time : 07:00 AM
Sampling Received Date : 10/01/2025
Sample Test Date : 17/02/2025
Report Date : 18/02/2025

| Test Parameter | Method | Method |
|----------------------------|------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Dark gray | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Homogeneous | |
| - Odor | Mild (None) | |
| - State | Solid (Powder) | |
| pH | 12 | ASTM D4980-89 |
| Temperature | 25.5 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Soluble 1% and Sink 99%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Positive (Generated air bubbles) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(18 / 02 / 2025)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(18 / 02 / 2025)

Test Report

Report No. : RE25-02-050_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-02-025
Sample Name : Fly Ash
Waste Profile No. : -
Sampling By : Korrawit Y. (๕-371-๙-0001)

Sampling Date : 10/01/2025
Sampling Time : 07:00 AM
Sampling Received Date : 10/01/2025
Sample Test Date : 17/02/2025
Report Date : 18/02/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.6 °C | US EPA. 9040C, 9045D ^[1, 2] | pH unit | 11.9 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|---|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4, 5] | mg/kg | 160 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4, 5] | mg/kg | 14.9 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4, 5] | mg/kg | 724 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4, 5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4, 5] | mg/kg | 118 | 0.26 | 5.00 | ≤2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4, 5] | mg/kg | 15.7 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4, 5] | mg/kg | 782 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4, 5] | mg/kg | 162 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4, 5] | mg/kg | 697 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4, 5] | mg/kg | 250 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4, 5] | mg/kg | 59.1 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4, 5] | mg/kg | 7.81 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4, 5] | mg/kg | 7.67 | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4, 5] | mg/kg | 112 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4, 5] | mg/kg | 1,834 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996


^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTL = Total Threshold Limit Concentration.


LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(๕-371-๙-0001)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(๕-371-๙-0001)

Test Report

Report No. : RE25-02-067_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-02-040
Sample Name : Fly Ash
Waste Profile No. : -
Sampling By : Korrawit Y. (๙-371-๙-0001)

Sampling Date : 13/02/2025
Sampling Time : 03:00 PM
Sampling Received Date : 14/02/2025
Sample Test Date : 26/02/2025
Report Date : 28/02/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.3 °C | US EPA. 9040C, 9045D ^[1,2] | pH unit | 11.7 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4,5] | mg/kg | 76.1 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | 17.5 | 0.25 | 2.00 | <500 |
| Barium (Ba) | Digestion, ICP Method ^[4,5] | mg/kg | 765 | 0.11 | 2.00 | <10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.22 | 2.00 | <75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | <100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | 144 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4,5] | mg/kg | 24.8 | 0.17 | 2.00 | <8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 862 | 1.29 | 2.00 | <2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | 167 | 1.30 | 2.00 | <1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4,5] | mg/kg | 43.5 | 0.93 | 2.00 | <3,500 |
| Nickel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | 148 | 0.37 | 2.00 | <2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4,5] | mg/kg | 58.9 | 1.04 | 2.00 | <100 |
| Silver (Ag) | Digestion, ICP Method ^[4,5] | mg/kg | 7.80 | 0.42 | 2.00 | <500 |
| Thallium (Tl) | Digestion, ICP Method ^[4,5] | mg/kg | 9.61 | 0.68 | 2.00 | <700 |
| Vanadium (V) | Digestion, ICP Method ^[4,5] | mg/kg | 58.2 | 0.68 | 2.00 | <2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 1,860 | 3.36 | 5.00 | <5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996


^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTL = Total Threshold Limit Concentration.


LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(๙-371-๙-0001)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)

Test Report

Report No. : RE25-02-067_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-02-040
Sample Name : Fly Ash
Waste Profile No. : -
Sampling By : Korrawit Y. (๙-371-๙-0001)

Sampling Date : 13/02/2025
Sampling Time : 03:00 PM
Sampling Received Date : 14/02/2025
Sample Test Date : 26/02/2025
Report Date : 28/02/2025

| Test Parameter* | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/kg | 4,726 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4,5] | mg/kg | 468 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4,5] | mg/kg | 17,004 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[6] | mg/kg | 1.490 | 0.002 | 0.005 | <20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation),


SW-846 Method 7473, 2007.

EPA = U.S. Environmental Protection Agency.


LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(28 / 02 / 2025)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(28 / 02 / 2025)

Test Report

Report No. : RE25-02-067_3
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description


Sample No. : LA25-02-040
Sample Name : Fly Ash
Waste Profile No. : -
Sampling By : Korrawit Y.(9-371-9-0001)

Sampling Date : 13/02/2025
Sampling Time : 03:00 PM
Sampling Received Date : 14/02/2025
Sample Test Date : 26/02/2025
Report Date : 28/02/2025


| Test Parameter | Method | Method |
|----------------------------|---|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Black | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Homogeneous | |
| - Odor | Mild (None) | |
| - State | Solid (Powder) | |
| pH | 11 | ASTM D4980-89 |
| Temperature | 25.5 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Soluble 1%, Sink 1% and Float 1%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Positive (Generated air bubbles) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : 
Korrawit Yothawong
Laboratory Staff
(28 / 02 / 2025)



Reviewed By : 
Ampol Ruttanasang
Laboratory Controller
(28 / 02 / 2025)

Test Report

Report No. : RE25-04-024_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-03-062
Sample Name : Fly ash
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)

Sampling Date : 29/03/2025
Sampling Time : 03:00 PM
Sampling Received Date : 31/03/2025
Sample Test Date : 28/04/2025
Report Date : 28/04/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|--|---------|--------|
| pH at 25.2 °C | US EPA. 9040C, 9045D [1, 2] | pH unit | > 12.0 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester [3] | °C | > 110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|------------------------------|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method [4, 5] | mg/kg | 84.7 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method [4, 5] | mg/kg | 14.8 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method [4, 5] | mg/kg | 925 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method [4, 5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method [4, 5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method [4, 5] | mg/kg | 251 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method [4, 5] | mg/kg | 15.9 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method [4, 5] | mg/kg | 706 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method [4, 5] | mg/kg | 182 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method [4, 5] | mg/kg | 592 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method [4, 5] | mg/kg | 261 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method [4, 5] | mg/kg | 23.3 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method [4, 5] | mg/kg | 5.47 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method [4, 5] | mg/kg | 6.80 | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method [4, 5] | mg/kg | 232 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method [4, 5] | mg/kg | 1,553 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

pH Electrometric Measurement. SW-846 Method 9040C, 2004.

[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.

Soil and Waste pH. SW-846 Method 9045D, 2004.

[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTL = Total Threshold Limit Concentration.

ND = Not detected.

LOQ = Level of Quantitation.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(๙-371-๙-0002)

Reviewed By : Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)



Test Report

Report No. : RE25-04-024_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-03-062
Sample Name : Fly ash
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)

Sampling Date : 29/03/2025
Sampling Time : 03:00 PM
Sampling Received Date : 31/03/2025
Sample Test Date : 28/04/2025
Report Date : 28/04/2025

| Test Parameter* | Method | Unit | Result |
|-----------------------------|---|-------|--------|
| Chloride (Cl ⁻) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/kg | 91,865 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|------------------------------|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method [4, 5] | mg/kg | 220 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method [4, 5] | mg/kg | 23,053 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition [6] | mg/kg | 5.030 | 0.002 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : [1] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation).

SW-846 Method 7473, 2007.

EPA = U.S. Environmental Protection Agency.

ND = Not detected.

LOQ = Level of Quantitation.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(28 / 04 / 2025)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(28 / 04 / 2025)

Test Report

Report No. : RE25-04-024_3
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-03-062
Sample Name : Fly ash
Waste Profile No. : -
Sampling By : Watcharee S. (P-371-9-0002)

Sampling Date : 29/03/2025
Sampling Time : 03:00 PM
Sampling Received Date : 31/03/2025
Sample Test Date : 28/04/2025
Report Date : 28/04/2025

| Test Parameter | Method | Method |
|----------------------------|---|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Black | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Homogeneous | |
| - Odor | Mild (None) | |
| - State | Solid (Powder) | |
| pH meter | 12.2 | |
| Temperature | 27.4 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Soluble 1%, Float 10% and Float 89%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Positive (Generated air bubbles and Temperature increase) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(28 / 04 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(28 / 04 / 2025)

Test Report

Report No. : RE25-05-034_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-04-035
Sample Name : Fly ash
Waste Profile No. : -
Sampling By : Watcharee S. (๕-371-๙-0002)
Sampling Date : 28/04/2025
Sampling Time : 01:30 PM
Sampling Received Date : 28/04/2025
Sample Test Date : 08/05/2025
Report Date : 30/05/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 27.0 °C | US EPA. 9040C, 9045D ^[1,2] | pH unit | 11.6 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTLC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4,5] | mg/kg | 15.7 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | 6.29 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4,5] | mg/kg | 324 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | 628 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4,5] | mg/kg | 6.99 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 202 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | 20.0 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4,5] | mg/kg | 26.3 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | 49.1 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4,5] | mg/kg | 9.99 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4,5] | mg/kg | 3.46 | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4,5] | mg/kg | 24.4 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 500 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTLC = Total Threshold Limit Concentration. LOQ = Level of Quantitation.
ND = Not detected. MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(๕-371-๙-0002)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(๕-371-๙-0001)

Test Report

Report No. : RE25-05-034_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-04-035
Sample Name : Fly ash
Waste Profile No. : -
Sampling By : Watcharee S. (๕-371-๙-0002)
Sampling Date : 28/04/2025
Sampling Time : 01:30 PM
Sampling Received Date : 28/04/2025
Sample Test Date : 08/05/2025
Report Date : 30/05/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|-------|--------|
| Chloride (Cl) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/kg | 42,965 |

TTLC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4,5] | mg/kg | 167 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4,5] | mg/kg | 17,498 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[6] | mg/kg | 5.854 | 0.002 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation),
SW-846 Method 7473, 2007.

EPA = U.S. Environmental Protection Agency. LOQ = Level of Quantitation.
ND = Not detected. MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(30 / 05 / 2025)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(30 / 05 / 2025)

Test Report

Report No. : RE25-05-034_3

Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-04-035

Sample Name : Fly ash

Waste Profile No. : -

Sampling By : Watcharee S. (7-371-9-0002)

Sampling Date : 28/04/2025

Sampling Time : 01:30 PM

Sampling Received Date : 28/04/2025

Sample Test Date : 08/05/2025

Report Date : 30/05/2025

| Test Parameter | Method | Method |
|----------------------------|------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Black | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Homogeneous | |
| - Odor | Slightly (None) | |
| - State | Solid (Powder) | |
| pH | 12 | ASTM D4980-89 |
| Temperature | 25.6 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Insoluble and Sink 100%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Positive (Generated air bubbles) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(30 / 05 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(30 / 05 / 2025)

Test Report

Report No. : RE25-05-037_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-05-032
Sample Name : Fly ash
Waste Profile No. : -
Sampling By : Watcharee S. (๕-371-๙-0002)

Sampling Date : 21/05/2025
Sampling Time : 011:30 AM
Sampling Received Date : 23/05/2025
Sample Test Date : 29/05/2025
Report Date : 30/05/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.3 °C | US EPA. 9040C,9045D ^[1,2] | pH unit | 11.4 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4,5] | mg/kg | 20.5 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | 8.32 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4,5] | mg/kg | 456 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | 89.2 | 0.26 | 5.00 | ≤2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4,5] | mg/kg | 10.7 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 278 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | 35.4 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4,5] | mg/kg | 28.8 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | 69.5 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4,5] | mg/kg | 10.4 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4,5] | mg/kg | <2.00 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4,5] | mg/kg | 3.72 | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4,5] | mg/kg | 26.1 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 683 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTL = Total Threshold Limit Concentration. LOQ = Level of Quantitation.
ND = Not detected. MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(๕-371-๙-0002)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(๕-371-๙-0001)

Site office : 965 Moo 2 Soi 3, Bangpoo Industrial Estate, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn,
Samutprakarn, Thailand 10280 Tel: (66)-2-709-2546 Fax: (66)-2-709-2547
Bangkok office : 589/142 Central City Tower 1, 25 th Floor, Bangna-trad Road, Kwaeng Bangna, Khet Bangna, Bangkok, Thailand 10260
Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928 http://www.wms-thailand.com E-mail: info@wms-thailand.com

Test Report

Report No. : RE25-05-037_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-05-032
Sample Name : Fly ash
Waste Profile No. : -
Sampling By : Watcharee S. (๕-371-๙-0002)

Sampling Date : 21/05/2025
Sampling Time : 011:30 AM
Sampling Received Date : 23/05/2025
Sample Test Date : 29/05/2025
Report Date : 30/05/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|-------|--------|
| Chloride (Cl) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/kg | 43,137 |

TTL Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4,5] | mg/kg | 196 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4,5] | mg/kg | 10,319 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[6] | mg/kg | 2.457 | 0.002 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[3] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation).

SW-846 Method 7473, 2007.

EPA = U.S. Environmental Protection Agency.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(30 / 05 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(30 / 05 / 2025)

Site office : 965 Moo 2 Soi 3, Bangpoo Industrial Estate, Sukhumvit Road, Tambon Bangpoo-Mai, Amphur Muang-Samutprakarn,
Samutprakarn, Thailand 10280 Tel: (66)-2-709-2546 Fax: (66)-2-709-2547
Bangkok office : 589/142 Central City Tower 1, 25 th Floor, Bangna-trad Road, Kwaeng Bangna, Khet Bangna, Bangkok, Thailand 10260
Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928 http://www.wms-thailand.com E-mail: info@wms-thailand.com

Test Report

Report No. : RE25-05-037_3
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-05-032
Sample Name : Fly ash
Waste Profile No. : -
Sampling By : Watcharee S. (๙371-๙-0002)

Sampling Date : 21/05/2025
Sampling Time : 011:30 AM
Sampling Received Date : 23/05/2025
Sample Test Date : 29/05/2025
Report Date : 30/05/2025

| Test Parameter | Method | Method |
|----------------------------|------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Black | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Homogeneous | |
| - Odor | Slightly (None) | |
| - State | Solid (Powder) | |
| pH | 11 | ASTM D4980-89 |
| Temperature | 25.3 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Insoluble and Sink 100%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Positive (Occured air bubbles) | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(30 / 05 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(30 / 05 / 2025)

Test Report

Report No. : RE25-07-021_1
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-06-061
Sample Name : Fly ash
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)
Sampling Date : 23/06/2025
Sampling Time : 09:00 AM
Sampling Received Date : 23/06/2025
Sample Test Date : 01/07/2025
Report Date : 02/07/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|---------|--------|
| pH at 25.3 °C | US EPA. 9040C,9045D ^[1,2] | pH unit | 8.3 |
| Flash Point | Flash Point of Liquid by Setaflash Closed Tester ^[3] | °C | >110 |

TTLC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|------|------|---------|
| Antimony (Sb) | Digestion, ICP Method ^[4,5] | mg/kg | 20.7 | 1.55 | 5.00 | - |
| Arsenic (As) | Digestion, ICP Method ^[4,5] | mg/kg | 8.98 | 0.25 | 2.00 | ≤500 |
| Barium (Ba) | Digestion, ICP Method ^[4,5] | mg/kg | 374 | 0.11 | 2.00 | ≤10,000 |
| Beryllium (Be) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.22 | 2.00 | ≤75 |
| Cadmium (Cd) | Digestion, ICP Method ^[4,5] | mg/kg | ND | 0.38 | 2.00 | ≤100 |
| Chromium (Cr) | Digestion, ICP Method ^[4,5] | mg/kg | 82.2 | 0.26 | 5.00 | <2,500 |
| Cobalt (Co) | Digestion, ICP Method ^[4,5] | mg/kg | 7.70 | 0.17 | 2.00 | ≤8,000 |
| Copper (Cu) | Digestion, ICP Method ^[4,5] | mg/kg | 309 | 1.29 | 2.00 | ≤2,500 |
| Lead (Pb) | Digestion, ICP Method ^[4,5] | mg/kg | 17.7 | 1.30 | 2.00 | ≤1,000 |
| Molybdenum (Mo) | Digestion, ICP Method ^[4,5] | mg/kg | 51.3 | 0.93 | 2.00 | ≤3,500 |
| Nikel (Ni) | Digestion, ICP Method ^[4,5] | mg/kg | 75.3 | 0.37 | 2.00 | ≤2,000 |
| Selenium (Se) | Digestion, ICP Method ^[4,5] | mg/kg | 14.8 | 1.04 | 2.00 | ≤100 |
| Silver (Ag) | Digestion, ICP Method ^[4,5] | mg/kg | <2.00 | 0.42 | 2.00 | ≤500 |
| Thallium (Tl) | Digestion, ICP Method ^[4,5] | mg/kg | 5.04 | 0.68 | 2.00 | ≤700 |
| Vanadium (V) | Digestion, ICP Method ^[4,5] | mg/kg | 33.1 | 0.68 | 2.00 | ≤2,400 |
| Zinc (Zn) | Digestion, ICP Method ^[4,5] | mg/kg | 575 | 3.36 | 5.00 | ≤5,000 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : * Parameter items are under scope of DIW license.

^[1] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
pH Electrometric Measurement. SW-846 Method 9040C, 2004.

^[2] United States Environmental Protection Agency. Test Methods for Evaluation Solid Waste Physical/Chemical Methods.
Soil and Waste pH. SW-846 Method 9045D, 2004.

^[3] American Society for Testing and Materials. D3278-78 Standard Test Methods for Flash Point of Liquids by Setaflash Close Tester, 2020

^[4] United States Environmental Protection Agency. Acid Digestion of Sediments Sludge and Soils. SW-846 Method 3050B, 1996

^[5] United States Environmental Protection Agency. Inductively Coupled Plasma Atomic Emission Spectrometry. SW-846 Method 6010C, 2007

TTLC = Total Threshold Limit Concentration.

ND = Not detected.

LOQ = Level of Quantitation.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(๙-371-๙-0002)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(๙-371-๙-0001)

Test Report

Report No. : RE25-07-021_2
Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-06-061
Sample Name : Fly ash
Waste Profile No. : -
Sampling By : Watcharee S. (๙-371-๙-0002)
Sampling Date : 23/06/2025
Sampling Time : 09:00 AM
Sampling Received Date : 23/06/2025
Sample Test Date : 01/07/2025
Report Date : 02/07/2025

| Test Parameter* | Method | Unit | Result |
|-----------------|---|-------|--------|
| Chloride (Cl) | EPA 9253 Chloride (Titrimetric, Silver Nitrate) | mg/kg | 93,169 |

TTLC Analysis

| Test Parameter* | Method | Unit | Result | MDL | LOQ | Std. |
|-----------------|--|-------|--------|-------|-------|------|
| Manganese (Mn) | Digestion, ICP Method ^[4,5] | mg/kg | 167 | 0.66 | 2.00 | - |
| Sulfur (S) | Digestion, ICP Method ^[4,5] | mg/kg | 32.3 | 3.77 | 10.0 | - |
| Mercury (Hg) | Thermal Decomposition ^[6] | mg/kg | 0.073 | 0.002 | 0.005 | ≤20 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ^[1] United States Environmental Protection Agency. Mercury in Solid and Solution (Thermal Decomposition, amalgamation),

SW-846 Method 7473, 2007.

EPA = U.S. Environmental Protection Agency.

LOQ = Level of Quantitation.

ND = Not detected.

MDL = Method Detection Limit.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(02 / 07 / 2025)



Reviewed By : Ampol Ruttanasang
Laboratory Controller
(02 / 07 / 2025)

Test Report

Report No. : RE25-07-021_3

Revision No. : 0

Customer Name : Bangpoo Environmental Complex
Address : 965 Moo 2 Soi 3 Bangpoo Industrial Estate, Sukhumvit Rd Bangpoo Mai,
Muang Samutprakarn Samutprakarn 10280

Sample Description

Sample No. : LA25-06-061
Sample Name : Fly ash
Waste Profile No. : -
Sampling By : Watcharee S. (9-371-9-0002)

Sampling Date : 23/06/2025
Sampling Time : 09:00 AM
Sampling Received Date : 23/06/2025
Sample Test Date : 01/07/2025
Report Date : 02/07/2025

| Test Parameter | Method | Method |
|----------------------------|------------------------------------|------------------|
| Finger print test | | |
| Physical Appearance | | ASTM D4979-08 |
| - Color | Black | |
| - Turbidity | - | |
| - Viscosity | - | |
| - Layering | Homogeneous | |
| - Odor | Slightly (None) | |
| - State | Semi Solid (Powder and sludge) | |
| pH | 8 | ASTM D4980-89 |
| Temperature | 25.1 | Thermometer |
| Stability&Miscibility with | | ASTM D5232-92 |
| - Air | Negative | |
| - Water | Negative (Soluble 1% and Sink 99%) | |
| - Oil | Not Available | |
| - Base | Negative | |
| - Acid | Negative | |
| - Non Liquid (AFR) | Negative | |
| - Haz. Liquid (Haz.Tank) | Negative | |
| Oxidizer | Negative | ASTM D4981-19 |
| Ignitability Potential | Negative | ASTM D4982-12 |
| Cyanide | Negative | Cyanide Test Kit |
| Sulfide | Negative | ASTM D4978-16 |

The results shown in this test report refer only to the sample tested unless otherwise stated. This test report cannot be reproduced except in full, without written approval of laboratory.

Remark : ASTM = American Society for Testing and Materials.

Reported By : Watcharee S.
Watcharee Suksri
Laboratory Staff
(02 / 07 / 2025)



Reviewed By : Ampol Ruttanasang
Ampol Ruttanasang
Laboratory Controller
(02 / 07 / 2025)

เอกสารแนบ 2-28

หนังสือแจ้งผลการพิจารณาการขออนุญาตให้นำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว
ออกนอกบริเวณโรงงาน (สก.2/กอ.1)



หนังสือแจ้งผลการพิจารณา

การขออนุญาตให้นำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้วออกนอกบริเวณโรงงาน
กรมโรงงานอุตสาหกรรม

เลขที่ 2568-4232

หนังสือฉบับนี้ออกให้เพื่อแจ้งผลการพิจารณาของ

บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

ทะเบียนโรงงานเลขที่ 72020000125477

โดยมีรายละเอียดผลการพิจารณาดังนี้

| ลำดับที่ | รหัสสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | ชื่อสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | ปริมาณ(ตัน) | รหัสการจัดการ | ผู้รับดำเนินการ | เหตุผล |
|----------|--------------------------------------|--------------------------------------|-------------|---------------|-----------------|--------|
| 1 | 170101 | เศษวัสดุจากการรื้อทำลายสิ่งก่อสร้าง | 50.000 | 071 | 72080000125604 | |
| 2 | 160215 | IT waste | 10.000 | 049 | 72080000125455 | |
| 3 | 190102 | Metal scarp after burning | 150.000 | 011 | 10111500125367 | |
| 4 | 190114 | เถ้าลอย (Fly ash) | 4,800.000 | 071 | 72080000125604 | |
| 5 | 190102 | Metal scarp after burning | 100.000 | 011 | 10200008325601 | |
| 6 | 191204 | Unburnable waste | 6,500.000 | 071 | 72080000125604 | |
| 7 | 191211 | Hazardous unusable material | 600.000 | 042 | 10190104125536 | |
| 8 | 190112 | Incombustible material+Ash | 9,600.000 | 071 | 72080000125604 | |

รายการที่ได้รับอนุญาตมีผลบังคับใช้ตั้งแต่วันที่ 1 มกราคม 2568 ถึงวันที่ 31 ธันวาคม 2568

ออกให้ ณ วันที่ 1 มกราคม 2568

โดยกรมโรงงานอุตสาหกรรม

หนังสือแจ้งผลการพิจารณาฉบับนี้อนุญาตโดยใช้ระบบอิเล็กทรอนิกส์

รหัสการจัดการสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว

- 011 คัดแยกประเภทเพื่อจำหน่ายต่อ (sorting)
021 เก็บเก็บในภาชนะบรรจุ (storage) ให้ระบุลักษณะของการเก็บและภาชนะบรรจุ
031 นำกลับมาใช้ซ้ำ (reuse) ตามวัตถุประสงค์เดิมของวัสดุที่ไม่ใช่แล้วอื่น ๆ
032 ส่งกลับผู้ขายเพื่อกำจัด (return to original producer for disposal) ให้ระบุผู้ขายที่รับคืน
033 นำมารวบรวมเพื่อกลับไปยังโรงงานใหม่หรือใช้ซ้ำ (reuse container, to be refilled) ให้ระบุชื่อผู้ขายที่รับคืน
039 นำกลับมาใช้ซ้ำด้วยวิธีอื่น ๆ (other reuse methods) ตามวัตถุประสงค์เดิมของวัสดุที่ไม่ใช่แล้วอื่น ๆ ให้ระบุ
041 ใช้เป็นเชื้อเพลิงทดแทน (use as fuel substitution or burn for energy recovery) โดยตรงในเตาเผา (incinerator) หรือเตาอุตสาหกรรมซีเมนต์ (cement industrial furnace)
042 ทำเชื้อเพลิงผสม (fuel blending) เพื่อนำไปใช้เป็นเชื้อเพลิงสำหรับเตาเผา (incinerator) เตาอุตสาหกรรมซีเมนต์ (cement industrial furnace) หรือหม้อไอน้ำและเตาอุตสาหกรรม (boiler and industrial furnace) ระบุปลายทาง
043 เผาเพื่อใช้เป็นพลังงาน (burn for energy recovery) เฉพาะวัสดุที่ไม่ใช่แล้วที่ไม่เป็นของเสียอันตรายสำหรับเตาไฟ (stove) หรือหม้อไอน้ำและเตาอุตสาหกรรม (boiler and industrial furnace)
044 ใช้เป็นวัตถุดิบทดแทน (use as raw material substitution) ในเตาอุตสาหกรรมซีเมนต์ (cement industrial furnace)
045 ทำวัตถุดิบผสม (material blending) เพื่อใช้เป็นวัตถุดิบทดแทน (use as raw material substitution) ในเตาอุตสาหกรรมซีเมนต์ (cement industrial furnace) ระบุปลายทาง
046 ทำเชื้อเพลิงทดแทนจากวัสดุที่ไม่ใช่แล้วที่ไม่เป็นของเสียอันตราย สำหรับเตาอุตสาหกรรม เพื่อใช้ผลิตกระแสไฟฟ้าโดยเฉพาะ (use as fuel blending for energy recovery) ระบุปลายทาง
047 วัสดุที่ไม่ใช่แล้วที่ไม่เป็นของเสียอันตราย เพื่อใช้เป็นเชื้อเพลิงทดแทนโดยตรงในเตาเผา (incinerator) เพื่อผลิตกระแสไฟฟ้า

- 057 เข้ากระบวนการคืนสภาพทรายหลอมแบบที่ไม่ใช้งานแล้ว (spent green sand / no bake sand regeneration)
059 นำวัสดุที่ไม่ใช่แล้วอื่น ๆ กลับคืนมาใหม่ (other recovery unlisted materials) ให้ระบุ
061 นำบำบัดด้วยวิธีชีวภาพ (biological treatment) หรือวิธีเคมีชีวภาพ (chemical biological treatment)
062 บำบัดด้วยวิธีชีวภาพ (biological treatment) เพื่อใช้กำจัดชีวภาพหรือก๊าซไฮโดรเจนเป็นพลังงาน
063 บำบัดด้วยวิธีทางเคมี (chemical treatment) หรือนำบำบัดด้วยวิธีทางกายภาพ (physical treatment) หรือนำบำบัดด้วยวิธีทางเคมีกายภาพ (physico-chemical treatment)
065 นำบัติน้ำเสียด้วยวิธีทางเคมีกายภาพ (physico-chemical treatment of wastewater)
066 เข้าระบบบำบัดน้ำเสียรวม (discharge into central wastewater treatment plant)
067 ปรับเสถียรด้วยวิธีทางเคมี (chemical stabilization)
068 ปรับเสถียรหรือตรึงทางเคมีโดยใช้ซีเมนต์หรือวัสดุ pozzolanic (chemical fixation using cementitious and/or pozzolanic material)
069 ใช้วิธีบำบัดอื่น ๆ เพื่อทำลายความเป็นพิษ (other detoxification methods) ให้ระบุ
071 ผังกลบตามหลักสุขาภิบาล (sanitary landfill) เฉพาะสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว ที่ไม่เป็นของเสียอันตรายเท่านั้น
072 ผังกลบอย่างปลอดภัย (secure landfill)
073 ผังกลบอย่างปลอดภัย เมื่อทำการปรับเสถียรหรือทำให้เป็นก้อนแข็งแล้ว (secure landfill of stabilized and/or solidified wastes)
074 เผาทำลาย (burn for destruction) ในเตาเผาขยะชุมชน หรือเตาเผาเฉพาะสำหรับสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วที่ไม่เป็นของเสียอันตรายเท่านั้น
075 เผาทำลายในเตาเผาเฉพาะสำหรับของเสียอันตราย (burn for destruction in hazardous waste incinerator)
076 เผาทำลายร่วมในเตาอุตสาหกรรมซีเมนต์ (co-incineration in cement kiln)

- 048 วัสดุที่ไม่ใช่แล้วที่เป็นของเสียอันตราย เพื่อใช้เป็นเชื้อเพลิงทดแทนโดยตรง ในเตาเผา (incinerator) เพื่อผลิตกระแสไฟฟ้า
049 นำกลับมาใช้ประโยชน์อีกด้วยวิธีอื่น ๆ (other recycle methods)
051 เข้ากระบวนการนำค่าทำลายกลับมาใหม่ (solvent reclamation/regeneration)
052 เข้ากระบวนการนำโลหะกลับมาใหม่ (reclamation/regeneration of metal and metal compounds)
053 เข้ากระบวนการคืนสภาพกรด/ด่าง (acid/base regeneration)
054 เข้ากระบวนการคืนสภาพตัวเร่งปฏิกิริยา (catalyst regeneration)
055 เข้ากระบวนการคืนสภาพ ถ่านกัมมันต์ใช้งานแล้ว (spent activated carbon regeneration)
056 เข้ากระบวนการคืนสภาพเรซินหรือเมมเบรนที่ใช้งานแล้ว (spent resin or membrane regeneration)

เหตุผลกรณีอื่น ๆ

- 01 ผู้รับดำเนินการไม่ได้รับอนุญาตให้ นำบัต/ กำจัด/นำกลับไปยังประโยชน์ใหม่
02 วิธีการบำบัด/กำจัด/นำกลับไปยังประโยชน์ใหม่ ไม่เหมาะสม
03 ผู้รับดำเนินการได้รับคำสั่งปรับปรงตามมาตรา 37 หรือหยุดประกอบกิจการตามมาตรา 39 ตามพระราชบัญญัติโรงงาน
04 ผู้รับดำเนินการไม่ยื่นขอรับบัต/กำจัด/นำกลับไปยังประโยชน์ใหม่
05 ไม่สามารถยื่นขออนุญาตฯ ผ่านสื่ออิเล็กทรอนิกส์ได้
06 ผู้ให้บริการยังไม่ได้แจ้งประกอบกิจการโรงงาน หรือไม่ได้แจ้งประกอบในส่วนขยาย
07 ไม่เข้าข่ายต้องขออนุญาตตามประกาศกระทรวงอุตสาหกรรมเรื่องการจัดการสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว พ.ศ. 2566

เหตุผลที่ไม่อนุญาต

- 99 อื่นๆ ระบุ.....

- 077 สกัดดีดลบนิดใต้ หรือฉีดดินใต้ทะเล (deep well or underground injection; sea-bed insertion)
079 กำจัดด้วยวิธีอื่น ๆ (other disposal methods) ให้ระบุ
081 รวบรวมและส่งออกนอกประเทศ (collect and export)
082 กบฏทะเลหรือที่ฝัง (land reclamation) เฉพาะวัสดุที่ไม่ใช่แล้วที่ไม่เป็นของเสียอันตรายเท่านั้น
083 หมักทำปุ๋ยหรือสารปรับปรุงคุณภาพดิน (composting or soil conditioner) เฉพาะสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วที่ไม่เป็นของเสียอันตรายเท่านั้น
084 อาหารสัตว์ (animal feed) เฉพาะสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วที่ไม่เป็นของเสียอันตรายเท่านั้น
085 ศึกษา วิจัยและพัฒนา (study research and develop) เพื่อการทดลองในลักษณะโครงการนำร่องเท่านั้น

เหตุผลที่ไม่สามารถพิจารณาได้ เนื่องจากขาดเอกสาร หรือเอกสารไม่สมบูรณ์ ดังนี้

- 11 สำเนาใบอนุญาตประกอบกิจการโรงงานของผู้รับดำเนินการ และหรือ ผู้ก่อกำเนิดวัสดุที่ไม่ใช่แล้ว
12 สำเนาหนังสือรับรองจดทะเบียนนิติบุคคลของผู้รับดำเนินการ และหรือ ผู้ก่อกำเนิดวัสดุที่ไม่ใช่แล้ว
13 สัญญาหรือหนังสือยินยอมการบริหารระหว่างผู้รับดำเนินการและ ผู้ก่อกำเนิดวัสดุที่ไม่ใช่แล้ว
14 หนังสือการประกันความรับผิดชอบ (Liability) ระหว่างผู้รับดำเนินการและ ผู้ก่อกำเนิดวัสดุที่ไม่ใช่แล้ว
15 หนังสือมอบอำนาจให้ผู้หนึ่งผู้ใดกระทำการใดๆ แทนกรรมการผู้มีอำนาจพร้อมติดอากรแสตมป์ของผู้รับดำเนินการ และหรือ ผู้ก่อกำเนิดวัสดุที่ไม่ใช่แล้ว
16 ผลวิเคราะห์ค่าความเข้มข้นทั้งหมดของสิ่งเจือปน (total concentration : mg/kg)
17 ผลวิเคราะห์ด้วยวิธีการสกัดสาร (waste extraction test : mg/l)
18 รายละเอียดกระบวนการผลิตพร้อมแสดงจุดที่เกิดของเสีย
19 รายละเอียดกระบวนการนำของเสียมากำจัด/บำบัด/นำกลับมาใช้ประโยชน์ใหม่
20 สำเนาใบอนุญาตส่งออกวัตถุอันตราย (ว.6)
21 หนังสือรับรองจากกรมวิชาการเกษตรในการทำปุ๋ยหรือสารปรับปรุงคุณภาพดิน
22 รหัสประเภทหรือชนิดของวัสดุที่ไม่ใช่แล้วในถูกต้อง
23 รหัสการจัดการในถูกต้อง
24 การลงนามของกรรมการผู้มีอำนาจในคำขอ/สัญญา ใบสมัครตามเงื่อนไขหนังสือรับรองการจดทะเบียนนิติบุคคล
25 เอกสารข้อมูลความปลอดภัย

หมายเหตุ

- กรณีไม่อนุญาต หากท่านไม่เห็นด้วย สามารถแจ้งเป็นหนังสือพร้อมเหตุผลไปยังอธิบดีกรมโรงงานอุตสาหกรรม ภายใน 15 วัน นับตั้งแต่วันที่ได้รับแจ้งคำสั่งทางการปกครองนี้
- หากท่านแจ้งใจฝ่าฝืนนำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วออกนอกบริเวณโรงงานโดยไม่ได้รับอนุญาต ถือเป็นการผิดตามมาตรา 45 แห่งพระราชบัญญัติโรงงาน พ.ศ.2535 ต้องระวางโทษปรับไม่เกิน 2 แสนบาท



หนังสือแจ้งผลการพิจารณา

การขออนุญาตให้นำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้วออกนอกบริเวณโรงงาน

กรมโรงงานอุตสาหกรรม

เลขที่ 2568-4232

หนังสือฉบับนี้ออกให้เพื่อแจ้งผลการพิจารณาของ

บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

ทะเบียนโรงงานเลขที่ 72020000125477

โดยมีรายละเอียดผลการพิจารณาดังนี้

| ลำดับที่ | รหัสสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | ชื่อสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | ปริมาณ(ตัน) | รหัสการจัดการ | ผู้รับดำเนินการ | เหตุผล |
|----------|--------------------------------------|--------------------------------------|-------------|---------------|-----------------|--------|
| 1 | 170101 | เศษวัสดุจากการรื้อทำลายสิ่งก่อสร้าง | 15.000 | 071 | 72080000125604 | |
| 2 | 160215 | IT waste | 0.000 | 049 | 72080000125455 | |
| 3 | 190102 | Metal scarp after burning | 10.000 | 011 | 10111500125367 | |
| 4 | 190114 | เถ้าลอย (Fly ash) | 566.000 | 071 | 72080000125604 | |

| | | | | | | |
|---|--------|-----------------------------|---------|-----|----------------|--|
| 5 | 190102 | Metal scarp after burning | 5.000 | 011 | 10200008325601 | |
| 6 | 191204 | Unburnable waste | 404.000 | 071 | 72080000125604 | |
| 7 | 191211 | Hazardous unusable material | 23.000 | 042 | 10190104125536 | |
| 8 | 190112 | Incombustible material+Ash | 22.000 | 071 | 72080000125604 | |

รายการที่ได้รับอนุญาตมีผลบังคับใช้ตั้งแต่วันที่ 1 มกราคม 2568 ถึงวันที่ 31 มกราคม 2568

ออกให้ ณ วันที่ 1 มกราคม 2568
โดยกรมโรงงานอุตสาหกรรม

หนังสือแจ้งผลการพิจารณาขออนุญาตโดยใช้ระบบอิเล็กทรอนิกส์



หนังสือแจ้งผลการพิจารณา
การขออนุญาตให้นำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้วออกนอกบริเวณโรงงาน
กรมโรงงานอุตสาหกรรม

เลขที่ 2568-4232

หนังสือฉบับนี้ออกให้เพื่อแจ้งผลการพิจารณาของ
บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด
ทะเบียนโรงงานเลขที่ 72020000125477
โดยมีรายละเอียดผลการพิจารณาดังนี้

| ลำดับที่ | รหัสสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว | ชื่อสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว | ปริมาณ(ตัน) | รหัสการจัดการ | ผู้รับดำเนินการ | เหตุผล |
|----------|--------------------------------------|--------------------------------------|-------------|---------------|-----------------|--------|
| 1 | 170101 | เศษวัสดุจากการรีไซเคิลสิ่งก่อสร้าง | 0.000 | 071 | 72080000125604 | |
| 2 | 160215 | IT waste | 2.000 | 049 | 72080000125455 | |
| 3 | 190102 | Metal scarp after burning | 10.000 | 011 | 10111500125367 | |
| 4 | 190114 | เถ้าลอย (Fly ash) | 400.000 | 071 | 72080000125604 | |
| 5 | 190102 | Metal scarp after burning | 5.000 | 011 | 10200008325601 | |
| 6 | 191204 | Unburnable waste | 1,000.000 | 071 | 72080000125604 | |
| 7 | 191211 | Hazardous unusable material | 50.000 | 042 | 10190104125536 | |
| 8 | 190112 | Incombustible material+Ash | 800.000 | 071 | 72080000125604 | |

รายการที่ได้รับอนุญาตมีผลบังคับใช้ตั้งแต่วันที่ 1 กุมภาพันธ์ 2568 ถึงวันที่ 28 กุมภาพันธ์ 2568

ออกให้ ณ วันที่ 1 กุมภาพันธ์ 2568
โดยกรมโรงงานอุตสาหกรรม

หนังสือแจ้งผลการพิจารณาขออนุญาตโดยใช้ระบบอิเล็กทรอนิกส์



หนังสือแจ้งผลการพิจารณา
การขออนุญาตให้นำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้วออกนอกบริเวณโรงงาน
กรมโรงงานอุตสาหกรรม

เลขที่ 2568-4232

หนังสือฉบับนี้ออกให้เพื่อแจ้งผลการพิจารณาของ
บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด
ทะเบียนโรงงานเลขที่ 72020000125477
โดยมีรายละเอียดผลการพิจารณาดังนี้

| ลำดับที่ | รหัสสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว | ชื่อสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้ว | ปริมาณ(ตัน) | รหัสการจัดการ | ผู้รับดำเนินการ | เหตุผล |
|----------|--------------------------------------|--------------------------------------|-------------|---------------|-----------------|--------|
| 1 | 170101 | เศษวัสดุจากการรีไซเคิลสิ่งก่อสร้าง | 0.000 | 071 | 72080000125604 | |
| 2 | 160215 | IT waste | 0.000 | 049 | 72080000125455 | |
| 3 | 190102 | Metal scarp after burning | 5.000 | 011 | 10111500125367 | |
| 4 | 190114 | เถ้าลอย (Fly ash) | 420.000 | 071 | 72080000125604 | |
| 5 | 190102 | Metal scarp after burning | 0.000 | 011 | 10200008325601 | |
| 6 | 191204 | Unburnable waste | 700.000 | 071 | 72080000125604 | |
| 7 | 191211 | Hazardous unusable material | 15.000 | 042 | 10190104125536 | |
| 8 | 190112 | Incombustible material+Ash | 280.000 | 071 | 72080000125604 | |

รายการที่ได้รับอนุญาตมีผลบังคับใช้ตั้งแต่วันที่ 1 มีนาคม 2568 ถึงวันที่ 31 มีนาคม 2568

ออกให้ ณ วันที่ 1 มีนาคม 2568
โดยกรมโรงงานอุตสาหกรรม

หนังสือแจ้งผลการพิจารณาขออนุญาตโดยใช้ระบบอิเล็กทรอนิกส์



หนังสือแจ้งผลการพิจารณา
การขออนุญาตให้นำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช้แล้วออกนอกบริเวณโรงงาน
กรมโรงงานอุตสาหกรรม

เลขที่ 2568-4232

หนังสือฉบับนี้ออกให้เพื่อแจ้งผลการพิจารณาของ
บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

ทะเบียนโรงงานเลขที่ 72020000125477

โดยมีรายละเอียดผลการพิจารณาดังนี้

| ลำดับที่ | รหัสสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | ชื่อสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | ปริมาณ(ตัน) | รหัสการจัดการ | ผู้รับดำเนินการ | เหตุผล |
|----------|--------------------------------------|--------------------------------------|-------------|---------------|-----------------|--------|
| 1 | 170101 | เศษวัสดุจากการรื้อทำลายสิ่งก่อสร้าง | 10.000 | 071 | 72080000125604 | |
| 2 | 160215 | IT waste | 0.000 | 049 | 72080000125455 | |
| 3 | 190102 | Metal scarp after burning | 3.000 | 011 | 10111500125367 | |
| 4 | 190114 | เถ้าลอย (Fly ash) | 320.000 | 071 | 72080000125604 | |
| 5 | 190102 | Metal scarp after burning | 0.000 | 011 | 10200008325601 | |
| 6 | 191204 | Unburnable waste | 160.000 | 071 | 72080000125604 | |
| 7 | 191211 | Hazardous unusable material | 20.000 | 042 | 10190104125536 | |
| 8 | 190112 | Incombustible material+Ash | 1,250.000 | 071 | 72080000125604 | |

รายการที่ได้รับอนุญาตมีผลบังคับใช้ตั้งแต่วันที่ 1 เมษายน 2568 ถึงวันที่ 30 เมษายน 2568

ออกให้ ณ วันที่ 1 เมษายน 2568

โดยกรมโรงงานอุตสาหกรรม

หนังสือแจ้งผลการพิจารณาฉบับนี้อนุญาตโดยใช้ระบบอิเล็กทรอนิกส์



หนังสือแจ้งผลการพิจารณา

การขออนุญาตให้นำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วออกนอกบริเวณโรงงาน

กรมโรงงานอุตสาหกรรม

เลขที่ 2568-4232

หนังสือฉบับนี้ออกให้เพื่อแจ้งผลการพิจารณาของ

บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

ทะเบียนโรงงานเลขที่ 72020000125477

โดยมีรายละเอียดผลการพิจารณาดังนี้

| ลำดับที่ | รหัสสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | ชื่อสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | ปริมาณ(ตัน) | รหัสการจัดการ | ผู้รับดำเนินการ | เหตุผล |
|----------|--------------------------------------|--------------------------------------|-------------|---------------|-----------------|--------|
| 1 | 170101 | เศษวัสดุจากการรื้อทำลายสิ่งก่อสร้าง | 0.000 | 071 | 72080000125604 | |
| 2 | 160215 | IT waste | 6.800 | 049 | 72080000125455 | |
| 3 | 190102 | Metal scarp after burning | 0.000 | 011 | 10111500125367 | |
| 4 | 190114 | เถ้าลอย (Fly ash) | 420.000 | 071 | 72080000125604 | |
| 5 | 190102 | Metal scarp after burning | 0.000 | 011 | 10200008325601 | |
| 6 | 191204 | Unburnable waste | 900.000 | 071 | 72080000125604 | |
| 7 | 191211 | Hazardous unusable material | 4.500 | 042 | 10190104125536 | |
| 8 | 190112 | Incombustible material+Ash | 235.000 | 071 | 72080000125604 | |

รายการที่ได้รับอนุญาตมีผลบังคับใช้ตั้งแต่วันที่ 1 พฤษภาคม 2568 ถึงวันที่ 31 พฤษภาคม 2568

ออกให้ ณ วันที่ 1 พฤษภาคม 2568

โดยกรมโรงงานอุตสาหกรรม

หนังสือแจ้งผลการพิจารณาฉบับนี้อนุญาตโดยใช้ระบบอิเล็กทรอนิกส์



หนังสือแจ้งผลการพิจารณา

การขออนุญาตให้นำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วออกนอกบริเวณโรงงาน

กรมโรงงานอุตสาหกรรม

เลขที่ 2568-4232

หนังสือฉบับนี้ออกให้เพื่อแจ้งผลการพิจารณาของ

บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

ทะเบียนโรงงานเลขที่ 72020000125477

โดยมีรายละเอียดผลการพิจารณาดังนี้

| ลำดับที่ | รหัสสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | ชื่อสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้ว | ปริมาณ(ตัน) | รหัสการจัดการ | ผู้รับดำเนินการ | เหตุผล |
|----------|--------------------------------------|--------------------------------------|-------------|---------------|-----------------|--------|
| 1 | 170101 | เศษวัสดุจากการรื้อทำลายสิ่งก่อสร้าง | 0.000 | 071 | 72080000125604 | |
| 2 | 160215 | IT waste | 1.200 | 049 | 72080000125455 | |
| 3 | 190102 | Metal scarp after burning | 5.000 | 011 | 10111500125367 | |
| 4 | 190114 | เถ้าลอย (Fly ash) | 505.000 | 071 | 72080000125604 | |
| 5 | 190102 | Metal scarp after burning | 0.000 | 011 | 10200008325601 | |
| 6 | 191204 | Unburnable waste | 1,070.000 | 071 | 72080000125604 | |
| 7 | 191211 | Hazardous unusable material | 10.000 | 042 | 10190104125536 | |
| 8 | 190112 | Incombustible material+Ash | 245.000 | 071 | 72080000125604 | |

รายการที่ได้รับอนุญาตมีผลบังคับใช้ตั้งแต่วันที่ 1 มิถุนายน 2568 ถึงวันที่ 30 มิถุนายน 2568

ออกให้ ณ วันที่ 1 มิถุนายน 2568

โดยกรมโรงงานอุตสาหกรรม

หนังสือแจ้งผลการพิจารณาฉบับนี้อนุญาตโดยใช้ระบบอิเล็กทรอนิกส์



หนังสือแจ้งผลการพิจารณา

การขออนุญาตให้นำสิ่งปฏิกูลหรือวัสดุที่ไม่ใช่แล้วออกนอกบริเวณโรงงาน

กรมโรงงานอุตสาหกรรม

เอกสารแนบ 2-29


กิจกรรมชุมชนสัมพันธ์

Community and Public Relations Activities
Period 1 – 31 January 2025

Community and Public Relations Activities
Period 1 – 31 January 2025



ร่วมงานวันเด็กกับนิคมฯบางปู 2568
Nation children day with Bangpoo IEAT 2025



ร่วมงานวันเด็กกับนิคมฯบางปู 2568
Nation children day with Bangpoo IEAT 2025

Community and Public Relations Activities

Period 1 – 31 March 2025



ร่วมงานส่งเสริมความเข้มแข็งชุมชนรอบๆนิคมฯบางปู 2568

Community and Public Relations Activities

Period 1 – 31 March 2025



ร่วมงานส่งเสริมความเข้มแข็งชุมชนรอบๆนิคมฯบางปู 2568

Community and Public Relations Activities


Period 1 – 30 April 2025



คณะกรรมการตรวจติดตามสิ่งแวดล้อม และ คณะนักศึกษาจากมหาวิทยาลัย
เชียงใหม่ เข้าเยี่ยมชมโครงการ 2568

Community and Public Relations Activities

Period 1 – 30 April 2025



ร่วมงานรณรงค์ผู้สูงอายุเนื่องในวันสงกรานต์กับนิคมบางปู 2568

Community and Public Relations Activities

Period 1 – 31 May 2025



เอกสารแนบ 2-30

เอกสารจัดตั้งคณะกรรมการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม

ที่ อก ๕๑๐๔.๘/๓๐๕



สำนักงานนิคมอุตสาหกรรมบางปู
๖๔๙ หมู่ที่ ๔ ถนนสุขุมวิท
ตำบลแพรกษา อำเภอมะนัง
จังหวัดสมุทรปราการ ๑๐๒๘๐

๓๖ พฤษภาคม ๒๕๖๗

เรื่อง คำสั่งแต่งตั้งคณะกรรมการติดตามตรวจสอบผลกระทบสิ่งแวดล้อมโครงการโรงงานปรับปรุงคุณภาพ
ของเสียรวมของบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

เรียน กรรมการผู้จัดการ บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

อ้างถึง หนังสือบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด ที่ ๒๐๒๔/๐๒/๐๒๒/BPEC/MD/PR
ลงวันที่ ๑๖ กุมภาพันธ์ ๒๕๖๗

- สิ่งที่ส่งมาด้วย ๑. สำเนาคำสั่งการนิคมอุตสาหกรรมแห่งประเทศไทย ที่ ๑๖๓/๒๕๖๗
ลงวันที่ ๑๑ เมษายน ๒๕๖๗ เรื่อง แต่งตั้งคณะกรรมการติดตามตรวจสอบผลกระทบ
สิ่งแวดล้อมโครงการโรงงานปรับปรุงคุณภาพของเสียรวมของบริษัท บางปู เอนไวรอนเมนทอล
คอมเพล็กซ์ จำกัด จำนวน ๓ แผ่น
๒. หนังสือสำนักงานนิคมอุตสาหกรรมบางปู ที่ อก ๕๑๐๔.๘/๓๐๕๔ ลงวันที่ ๗ พฤษภาคม ๒๕๖๗
จำนวน ๑ ฉบับ

ตามหนังสือที่อ้างถึง บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด (บริษัทฯ) ขอความ
อนุเคราะห์ต่อสำนักงานนิคมอุตสาหกรรมบางปู (สนป.) แต่งตั้งคณะกรรมการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
โครงการโรงงานปรับปรุงคุณภาพของเสียรวม ของบริษัทฯ เพื่อให้การติดตามและตรวจสอบผลกระทบสิ่งแวดล้อมของ
โครงการเป็นไปอย่างมีประสิทธิภาพและสอดคล้องตามที่ได้รับไว้ในมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม
และมาตรการตรวจสอบคุณภาพสิ่งแวดล้อม ความละเอียดดังแจ้งแล้ว นั้น

การนิคมอุตสาหกรรมแห่งประเทศไทย (กนอ.) ได้มีคำสั่งแต่งตั้งคณะกรรมการติดตามตรวจสอบ
ผลกระทบสิ่งแวดล้อมโครงการโรงงานปรับปรุงคุณภาพของเสียรวมของบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์
จำกัด ตามคำสั่ง กนอ. ที่ ๑๖๓/๒๕๖๗ ลงวันที่ ๑๑ เมษายน ๒๕๖๗ และ สนป. ขอนำส่งคำสั่งดังกล่าวให้แก่บริษัทฯ
รายละเอียดดังสิ่งที่ส่งมาด้วย ๑ ทั้งนี้ ให้บริษัทฯ ดำเนินการแจ้งคณะกรรมการตามคำสั่ง รายละเอียดดังสิ่งที่ส่งมาด้วย
๒ พร้อมทั้งให้ดำเนินการจัดให้มีการประชุมของคณะกรรมการฯ โดยให้เป็นไปตามที่กำหนดไว้ในมาตรการฯ

จึงเรียนมาเพื่อทราบ และดำเนินการในส่วนที่เกี่ยวข้อง ต่อไป

ขอแสดงความนับถือ



ผู้อำนวยการสำนักงานนิคมอุตสาหกรรมบางปู

งานระบบสาธารณูปโภคและป้องกันอุบัติเหตุ/อุบัติเหตุ

โทรศัพท์ ๐ ๒๗๐๙ ๓๔๕๐ ต่อ ๑๕๐

ไปรษณีย์อิเล็กทรอนิกส์ ieat.bpo@gmail.com



คำสั่งการนิคมอุตสาหกรรมแห่งประเทศไทย

ที่ ๑๖๓ /๒๕๖๗

เรื่อง แต่งตั้งคณะกรรมการติดตามตรวจสอบผลกระทบสิ่งแวดล้อมโครงการโรงงานปรับปรุงคุณภาพ
ของเสียรวมของบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

เพื่อให้การติดตามและตรวจสอบผลกระทบสิ่งแวดล้อมโครงการโรงงานปรับปรุงคุณภาพของเสีย
รวมของบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด เป็นไปอย่างมีประสิทธิภาพและสอดคล้องกับ
มาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อม และมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อมของ
โครงการฯ

อาศัยอำนาจตามความในมาตรา ๒๘ แห่งพระราชบัญญัติการนิคมอุตสาหกรรมแห่งประเทศไทย
พ.ศ. ๒๕๒๒ จึงแต่งตั้งคณะกรรมการติดตามตรวจสอบผลกระทบสิ่งแวดล้อมโครงการโรงงานปรับปรุงคุณภาพ
ของเสียรวมของบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด ขึ้น โดยมีองค์ประกอบ หน้าที่และอำนาจ
ดังต่อไปนี้

๑. องค์ประกอบ

- | | |
|--|------------------|
| (๑) ผู้อำนวยการสำนักงานนิคมอุตสาหกรรมบางปู | ประธานกรรมการ |
| (๒) นาย [Redacted] | รองประธานกรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลเมืองแพรกษา | |
| (๓) ผู้ช่วยผู้อำนวยการสำนักงานนิคมอุตสาหกรรมบางปู | กรรมการ |
| (๔) ผู้แทนสำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อม จังหวัดสมุทรปราการ | กรรมการ |
| (๕) ผู้แทนสำนักงานสาธารณสุขจังหวัดสมุทรปราการ | กรรมการ |
| (๖) ผู้แทนเทศบาลตำบลบางปู | กรรมการ |
| (๗) นาย [Redacted] | กรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลเมืองแพรกษา | |
| (๘) นาย [Redacted] | กรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลเมืองแพรกษา | |
| (๙) นางสาว [Redacted] | กรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลเมืองแพรกษาใหม่ | |
| (๑๐) นาง [Redacted] | กรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลเมืองแพรกษาใหม่ | |
| (๑๑) นาย [Redacted] | กรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลเมืองแพรกษาใหม่ | |

/(๑๒) นางสาว...

- | | |
|---|--------------------------------|
| (๑๒) นาง [REDACTED] | กรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลตำบลแพรกษา | |
| (๑๓) นาง [REDACTED] | กรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลตำบลแพรกษา | |
| (๑๔) นางสาว [REDACTED] | กรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลตำบลแพรกษา | |
| (๑๕) นาย [REDACTED] | กรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลตำบลบางปู | |
| (๑๖) นาย [REDACTED] | กรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลตำบลบางปู | |
| (๑๗) นางสาว [REDACTED] | กรรมการ |
| ผู้แทนประชาชนพื้นที่เทศบาลตำบลบางปู | |
| (๑๘) พลโท [REDACTED] | กรรมการ |
| ผู้แทนชุมชนองค์การบริหารส่วนตำบลบางพลีใหญ่ | |
| (๑๙) นางสาว [REDACTED] | กรรมการ |
| ผู้แทนชุมชนองค์การบริหารส่วนตำบลบางพลีใหญ่ | |
| (๒๐) ผู้แทนบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด | กรรมการ และเลขานุการ |
| (๒๑) ผู้แทนบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด | กรรมการ และผู้ช่วยเลขานุการ |

โดยให้คณะกรรมการฯ มีวาระการดำรงตำแหน่งคราวละ ๔ ปี นับแต่วันที่ได้รับการแต่งตั้ง โดยมีระยะเวลาในการดำรงตำแหน่งติดต่อกันไม่เกิน ๒ วาระ และการพ้นจากตำแหน่ง ตลอดจนการประชุม คณะกรรมการฯ ให้เป็นไปตามที่กำหนดในมาตรการฯ

๒. หน้าที่และอำนาจ

๒.๑ ติดตามตรวจสอบและกำกับดูแลให้โครงการฯ ปฏิบัติให้เป็นไปตามมาตรการ ติดตามตรวจสอบผลกระทบสิ่งแวดล้อมของโครงการฯ และเผยแพร่ประชาสัมพันธ์ให้ชุมชนและหน่วยงาน ที่เกี่ยวข้องทราบ เพื่อแสดงความโปร่งใสในการบริหารจัดการด้านสิ่งแวดล้อมติดตามตรวจสอบและกำกับ ดูแลการดำเนินงานของโครงการฯ ให้สอดคล้องกับระเบียบ มาตรฐาน และกฎหมายที่เกี่ยวข้อง

๒.๒ พิจารณาเรื่องร้องเรียนเกี่ยวกับปัญหา และผลกระทบที่ได้รับจากการดำเนินโครงการฯ รวมทั้งตรวจสอบข้อเท็จจริง พร้อมทั้งสรุปแนวทางการป้องกันและแก้ไข

๒.๓ ดำเนินการไกล่เกลี่ย ร่วมเจรจา เพื่อหาข้อยุติในกรณีมีข้อพิพาทปัญหาสิ่งแวดล้อม ระหว่างโครงการฯ กับชุมชน

๒.๔ พิจารณามาตรการในการชดเชย เยียวยา กรณีเกิดผลกระทบสิ่งแวดล้อมระหว่าง ชุมชนกับโครงการฯ หากพิสูจน์ได้ว่าเกิดจากโครงการฯ รวมทั้งติดตามผลการปฏิบัติตามมาตรการในการ ชดเชยและเยียวยา จนแล้วเสร็จ

ทั้งนี้ ตั้งแต่บัดนี้เป็นต้นไป

สั่ง ณ วันที่ ๑๑ เมษายน พ.ศ. ๒๕๖๗

[REDACTED]

(นาย [REDACTED])
ผู้ว่าการการนิคมอุตสาหกรรมแห่งประเทศไทย

รายงานการประชุม
คณะกรรมการติดตามตรวจสอบผลกระทบสิ่งแวดล้อม
โครงการโรงงานปรับปรุงคุณภาพของเสียรวม
ของบริษัทบางปู เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด
ครั้งที่ 1/2568
วันศุกร์ที่ 28 กุมภาพันธ์ 2568 เวลา 9.00 – 12.00 น.

รายชื่อกรรมการผู้เข้าร่วมประชุม

ส่วนราชการ

| | | |
|--|------------------------------------|-----------------------------|
| | ผอ.สนป | สำนักงานนิคมอุตสาหกรรมบางปู |
| | ผช.ผอ.สนป. | สำนักงานนิคมอุตสาหกรรมบางปู |
| | นักวิชาการสิ่งแวดล้อมชำนาญการพิเศษ | สำนักงานทรัพยากรธรรมชาติและ |
| | ปรการ | |
| | นักวิชาการสุขาภิบาลปฏิบัติการ | เทศบาลตำบลบางปู |

ภาคประชาชน

เขตเทศบาลตำบลบางปู

| | | |
|----|--|-------------------------|
| 1. | | ชุมชนหมู่บ้านเมืองเอก |
| 2. | | ชุมชนหมู่บ้านเอื้ออาทร |
| 3. | | ชุมชนสมุทรปราการเด่นชัย |

เขตเทศบาลตำบลแพรกษา

| | | |
|----|--|-----------------|
| 1. | | ชุมชนพูนทรัพย์ |
| 2. | | ชุมชนรุ่งทวี |
| 3. | | ชุมชนพฤษภา 28/2 |

เขตเทศบาลเมืองแพะหาใหม่

| | | |
|----|--|----------------------|
| 1. | | ชุมชนพฤษภา 15 |
| 2. | | ชุมชนพฤษภา 15 เฟส 2 |
| 3. | | ผู้ใหญ่บ้านหมู่ที่ 3 |

เขตเทศบาลเมืองแพรกษา

| | | |
|----|--|-----------|
| 1. | | หมู่ที่ 4 |
| 2. | | หมู่ที่ 6 |
| 3. | | หมู่ที่ 4 |

เขตองค์การบริหารส่วนตำบลบางพลีใหญ่

| | | |
|----|--|-----------------------|
| 1. | | ผู้ใหญ่บ้านหมู่ที่ 21 |
|----|--|-----------------------|

ผู้แทนบริษัท บางปูเอนไวรอน เม้นทอล คอมเพล็กซ์ จำกัด

| | | |
|----|--|---|
| 1. | | ผู้จัดการอาวุโส แผนกสิ่งแวดล้อมและการปฏิบัติตามกฎหมาย |
| 2. | | ผู้ช่วยผู้จัดการ สื่อสารองค์กร |

ผู้เข้าร่วมประชุม

| | | |
|----|-----|--|
| 1. | นาย | |
| 2. | นาย | |
| 3. | นาง | |

ผู้ไม่เข้าร่วมประชุม

| | |
|----|-----------------------------|
| 1. | สาธารณสุขจังหวัดสมุทรปราการ |
| 2. | 1 |

เริ่มประชุมเวลา 9:20 น.

ผู้อำนวยการนิคมอุตสาหกรรมบางปู ในฐานะประธานคณะกรรมการฯ ทำหน้าที่ประธานในที่ประชุม กล่าวเปิดการประชุมฯ และมอบหมายให้ผู้แทนบริษัทฯ ดำเนินการประชุม โดยสรุปผลการประชุมได้ดังนี้

ระเบียบวาระที่ 1 เรื่องแจ้งเพื่อทราบ

เนื่องจากมีการเปลี่ยนแปลงในรายชื่อของส่วนราชการ (สำนักงานนิคมอุตสาหกรรมบางปู) ตามระเบียบการโยกย้ายของข้าราชการ จำนวน 2 ท่าน ในครั้งนี้ได้แก่

| | | |
|----|--|--|
| 1. | | ผู้อำนวยการ สำนักงานนิคมอุตสาหกรรมบางปู |
| 2. | | ผู้ช่วยผู้อำนวยการ สำนักงานนิคมอุตสาหกรรมบางปู |

มติที่ประชุม: รับทราบ

ระเบียบวาระที่ 2 เรื่องเพื่อพิจารณา

ตัวแทนโครงการฯ นำเสนอภาพรวมของการดำเนินงานของโครงการฯ และนำเสนอผลการปฏิบัติตามมาตรการป้องกันและแก้ไขผลกระทบสิ่งแวดล้อมและมาตรการติดตามตรวจสอบผลกระทบสิ่งแวดล้อมของโครงการฯ ครั้งที่ 1 และ ครั้งที่ 2/2567

มติที่ประชุม: คณะกรรมการมีความเห็นและเสนอข้อเสนอดังนี้

1. ตัวแทนชุมชนสมุทรปราการเด่นชัย สอบถามเรื่องการติดตั้งตัววัดค่าฝุ่น PM 2.5 ที่โครงการฯ ซึ่งผู้แทนโครงการฯ ได้ชี้แจงไปว่าในการวัดค่าฝุ่น PM 2.5 นั้นไม่ได้อยู่ในเกณฑ์การตรวจวัดคุณภาพสิ่งแวดล้อมตามข้อกำหนดของโครงการฯ
- ผู้อำนวยการ สำนักงานนิคมอุตสาหกรรมบางปู อธิบายการติดตามค่าฝุ่น PM 2.5 จากแอปพลิเคชันในโทรศัพท์ซึ่งระบุพิกัดปัจจุบันของแต่ละท่านได้ในทันที
- นักวิชาการสิ่งแวดล้อมชำนาญการพิเศษ สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อม จังหวัดสมุทรปราการ ได้ให้ข้อมูลเพิ่มเติมว่าปัจจุบันทางจังหวัดสมุทรปราการมีการติดตั้งเครื่องอ่านค่าฝุ่น PM 2.5 ทั้งสิ้น 6 จุด โดยจุดที่ใกล้เขตบางปูที่สุดนั้นอยู่ที่หน้าจวนผู้ว่าจังหวัดสมุทรปราการ มีรัศมีการตรวจวัด 50 กิโลเมตร ทั้งนี้สามารถตรวจเช็คได้จากแอปพลิเคชัน Air4Thai จะสะดวกกว่าเพราะเป็นแบบเรียลไทม์

2. [redacted] ตัวแทนชุมชนหมู่บ้านเมืองเอก สอบถามว่าบางครั้งในชุมชนเมืองเอกได้กลิ่นเหม็นเปรี้ยวเหมือนการหมักหมมของขยะสดไม่ทราบว่าจะเกิดจากการประกอบกิจการของโครงการฯ หรือไม่
- โดยทางโครงการฯ ได้มีการชี้แจงว่าของเสียที่เข้ามาในโครงการฯ ส่วนใหญ่จะมาจากโรงงานอุตสาหกรรมซึ่งมีบางส่วนมาจากอาคารสำนักงานและโรงอาหาร แต่โครงการฯ จะไม่มีการสะสมขยะสดข้ามวันเพื่อป้องกันการย่อยสลายซึ่งจะก่อให้เกิดกลิ่นไม่พึงประสงค์
- นายมานิต อินเมฆ (ประธานคณะกรรมการ) ได้ให้โครงการฯ นำเสนอเรื่องแผนการรับเรื่องร้องเรียนให้ทางคณะกรรมการฯ รับฟังเพื่อเป็นการยืนยันว่าโครงการฯ มีแผนและขั้นตอนการปฏิบัติการในการตอบสนองต่อเรื่องร้องเรียนอยู่แล้ว
- ผู้แทนโครงการฯ ซึ่งแจ้งเพิ่มเติมว่าได้ทำการติดตั้ง windsock ในการตรวจวัดทิศทางลมไว้ที่หมู่บ้านเมืองเอกแล้ว จึงขอให้ทางชุมชนสังเกตทิศทางลมและแจ้งโครงการฯ ทราบเพื่อช่วยดำเนินการตรวจสอบอีกทางหนึ่ง กรณีที่ windsock ชำรุดขอให้ชุมชนแจ้งเพื่อทำการเปลี่ยน
- คณะกรรมการหลายท่านให้ความเห็นว่า กลิ่นขยะสดน่าจะมีแหล่งที่มาอื่น
- [redacted] นักวิชาการสิ่งแวดล้อมชำนาญการพิเศษ สำนักงานทรัพยากรธรรมชาติและสิ่งแวดล้อม จังหวัดสมุทรปราการ ให้ความเห็นเพิ่มเติมในช่วงฤดูกาลที่สภาพอากาศปิด ไม่ถ่ายเท อาจส่งผลให้เกิดผลกระทบเรื่องกลิ่น ขอให้โครงการฯ เฝ้าระวังเป็นพิเศษ
- [redacted] (รองประธานคณะกรรมการ) ตัวแทนชุมชนเทศบาลเมืองแพรกษา ได้ให้ข้อเสนอแนะเพิ่มเติม ในการใช้แอปพลิเคชัน Line ให้เกิดประโยชน์สำหรับกลุ่มคณะกรรมการฯ โดยที่บริษัทสามารถสื่อสารกิจกรรมในการตอบสนองต่อเรื่องร้องเรียนที่เกิดขึ้น ไม่ว่าจะเป็นเรื่องร้องเรียนหรือไม่เกี่ยวข้องกับการดำเนินงานของโครงการฯ เพื่อเป็นการแสดงความรับผิดชอบต่อสังคมด้วยการลงพื้นที่ ช่วยตรวจสอบ และแจ้งผลการตรวจสอบ จากนั้นให้สรุปผลการดำเนินการเพื่อนำเสนอในการประชุมคณะกรรมการฯ ครั้งถัดไป
3. [redacted] ตัวแทนชุมชนพฤษภา 28 สอบถามถึงเรื่องการเกิดอุบัติเหตุในการทำงาน และการทำความสะอาดเสื้อผ้าพนักงานเพราะหวั่นเรื่องสุขอนามัย
- ผู้แทนโครงการฯ ซึ่งแจ้งว่าทางโครงการฯ มีสถิติการไม่เกิดอุบัติเหตุในที่ทำงานมา เกือบ 600,000 ชั่วโมง ส่วนเรื่องการทำความสะอาดเสื้อผ้าพนักงานนั้น ได้มีการว่าจ้างผู้รับเหมาภายนอกเข้ามาทำการรับ-ส่งเสื้อผ้าพนักงานไปทำความสะอาด

มติที่ประชุม: รับทราบ และทางโครงการฯ จะนำคำแนะนำของคณะกรรมการฯ ไปปรับปรุงและนำเสนอในการประชุมครั้งถัดไป

ระเบียบวาระที่ 3 การเยี่ยมชมภายในโครงการฯ

ผู้แทนโครงการฯ นำคณะกรรมการฯ เข้าเยี่ยมชมการทำงานในส่วนต่างของโครงการฯ



มติที่ประชุม: รับทราบในการดำเนินงานภายใต้การกำกับดูแลที่ดีและเหมาะสม

ระเบียบวาระที่ 5 เรื่องอื่นๆ

กำหนดการประชุมครั้งที่ 2/2568

คณะกรรมการฯ เสนอให้มีการประชุมนอกสถานที่พร้อมการฝึกอบรมการจัดการของเสีย โดยเสนอไปประชุมที่บริษัท อีสทีร์น ซิเบอร์ดี เอนไวรอนเม้นทอล คอมเพล็กซ์ จำกัด (ESBEC) ซึ่งเป็นบริษัทในเครือเดียวกับโครงการฯ ที่ดำเนินกิจกรรมการฝังกลบของเสียที่ได้มาตรฐานเพื่อนำมาเป็นข้อมูลในการเฝ้าระวังการจัดการมูลฝอยในพื้นที่

โครงการฯ รับข้อเสนอเพื่อประสานกับทาง ESBEC ต่อไป การประชุมจะมีขึ้นระหว่างเดือนสิงหาคม-ธันวาคม โดยจะประสานวันเวลาผ่านทางไลน์กลุ่มของคณะกรรมการฯ อีกครั้ง

มติที่ประชุม: รับทราบ

ปิดประชุมเวลา 12.00 น.

[redacted]

ผู้บันทึกรายงานการประชุม

[redacted]

ผู้ตรวจรายงานการประชุม

เอกสารแนบ 2-31

ขั้นตอนการรับเรื่องร้องเรียนและเอกสารแจ้งตอบกลับเรื่องร้องเรียน
จากหน่วยงานราชการ ระหว่างปี 2567-2568

ที่ สป ๐๐๓๔(๒)/๖๕๖๗



๑๗ มิ.ย. ๒๕๖๘

สำนักงานอุตสาหกรรมจังหวัดสมุทรปราการ
๔๑๔ หมู่ที่ ๔ ถนนสุขุมวิท กม.๕๒ ตำบลบางปู
อำเภอเมือง จังหวัดสมุทรปราการ ๑๐๒๘๐

เรื่อง สอบถามเรื่องข้อร้องเรียน

เรียน กรรมการบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

อ้างถึง หนังสือบริษัทฯ เลขรับที่ ๓๐๓๘ ลงวันที่ ๙ มิถุนายน ๒๕๖๘

ตามหนังสือที่อ้างถึง ท่านขอความร่วมมือในการตรวจสอบข้อมูลข้อร้องเรียนของบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด ตั้งอยู่ ณ เลขที่ ๙๖๕ หมู่ที่ ๒ ซอย ๓ นิคมอุตสาหกรรมบางปู ถนนสุขุมวิท ตำบลบางปูใหม่ อำเภอเมืองสมุทรปราการ จังหวัดสมุทรปราการ ทะเบียนโรงงานเลขที่ ๗๒๐๒๐๐๐๑๒๕๔๗๗ นั้น

สำนักงานอุตสาหกรรมจังหวัดสมุทรปราการ ได้ตรวจสอบข้อมูลโรงงานของท่านแล้วปรากฏว่า ตั้งแต่ปี พ.ศ.๒๕๖๗ ถึงปัจจุบัน ไม่มีผู้ใดร้องเรียนว่าได้รับความเดือดร้อนรำคาญจากการประกอบกิจการของโรงงานแต่อย่างใด

จึงเรียนมาเพื่อทราบ

ขอแสดงความนับถือ

(นายเทียนชัย คละประสงค์)

นักวิเคราะห์นโยบายและแผนชำนาญการพิเศษ
รักษาราชการแทน อุตสาหกรรมจังหวัดสมุทรปราการ

กลุ่มโรงงานอุตสาหกรรม

โทร.๐-๒๗๐๗-๗๖๔๒-๕ ต่อ ๒๐ และ ๒๕

โทรสาร ๐-๒๗๐๗-๗๖๔๗

ไปรษณีย์อิเล็กทรอนิกส์ : saraban_samutprakan@industry.go.th



ที่ สป ๕๒๕๐๖/๑๕๓๔

สำนักงานเทศบาลตำบลบางปู
๗๘๙ หมู่ ๑ ต.บางปูใหม่
อ.เมืองฯ จ.สมุทรปราการ ๑๐๒๘๐

๒๗ มิถุนายน ๒๕๖๘

เรื่อง ขอความอนุเคราะห์สอบถามข้อมูลเรื่องร้องเรียน โครงการโรงงานปรับปรุงสภาพของเสียรวม
บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

เรียน กรรมการผู้จัดการ บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด

อ้างถึง หนังสือบริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด ที่ ๒๐๒๕-๐๖๔/BPEC/MD/EN
ลงวันที่ ๖ มิถุนายน ๒๕๖๘

ตามหนังสือที่อ้างถึง บริษัท บางปู เอนไวรอนเมนทอล คอมเพล็กซ์ จำกัด ได้ขอความอนุเคราะห์ในการสอบถามข้อมูลเรื่องร้องเรียนจากการดำเนินกิจการของโครงการโรงงานปรับปรุงสภาพของเสียรวมของบริษัทฯ ตั้งแต่ปี พ.ศ. ๒๕๖๗ - ปัจจุบัน เพื่อเป็นเอกสารสนับสนุนเรื่องรับข้อร้องเรียน นั้น

เทศบาลตำบลบางปู ได้ดำเนินการตรวจสอบแล้ว ไม่ปรากฏข้อร้องเรียนตามพระราชบัญญัติการสาธารณสุข พ.ศ.๒๕๓๕ จากการดำเนินงานของบริษัทฯ ในห้วงระยะเวลาดังกล่าว

จึงเรียนมาเพื่อทราบ

ขอแสดงความนับถือ

(นายธีรพล ชุนเจริญ)
นายกเทศมนตรีตำบลบางปู

กองสาธารณสุขและสิ่งแวดล้อม

งานสุขาภิบาลและอนามัยสิ่งแวดล้อม

โทร. ๐ ๒๑๓๔ ๓๓๙๐-๙ ต่อ ๑๖๒๑

โทรสาร ๐ ๒๓๒๓ ๙๔๘๖

“ยึดมั่นธรรมาภิบาล บริการเพื่อประชาชน ”

| | | |
|------------------------------|-----------------|----------------------------|
| Standard Operating Procedure | | Doc No.: 05-PR-S001 |
| Subject: Community Complaint | | Page: 1 of 5 |
| Prepared by: PR Dept. | Date: 4 June 21 | Effective Date : 7 June 21 |
| Approved by: [Redacted] | | Revision: 1 |
| Authorization: [Redacted] | Date: 8/6/2021 | Copy No. : |

Change Control

[illegible]

| | | |
|----------------------------------|-----------------|---------------------------|
| WASTE MANAGEMENT FORM-173 | | |
| Standard Operating Procedure | | Doc No.: 05-PR-S001 |
| Subject: Community Complaint | | Page: 2 of 5 |
| Prepared by: Communication Dept. | Date: 4 June 21 | Effective Date :7 June 21 |
| Approved by: [Signature] | | Revision: 1 |

1. Purposes:

To set up the mechanism method for staff to process in case of having environmental complain from community. Aiming to prevent and solve the problem to satisfy community, local organization, local government and other involved party.

2. Scope and Application:

- 2.1 This procedure will be used for all the environmental impact that may cause by BPEC activities and effect to community and other involved organizations.
- 2.2 The complainants mean local people who live around BPEC including government & private agencies.
- 2.3 The complaint covers by verbal inform, face to face or other communication system and also in writing.

3. Associated Document


- | | | | |
|-----|---------------|--------------------------------|----------------|
| 3.1 | 05-PR-F001/00 | Complaint Form for Complainant | (Attachment 1) |
| 3.2 | 05-PR-F002/00 | Summary of Complaint | (Attachment 2) |
| 3.3 | 05-PR-F003/00 | Complaint Procedure Chart | (Attachment 3) |

4. Procedure:

4.1 Complaint Receiving

- 4.1.1 The Community, Government and Private through phone can make a complaint on environmental impact both by verbal and in writing on Complaint Form for Complainant (Attachment 1)
- 4.1.2 Communication Dept. shall be the first acknowledge people in every case of complaint. In case of complain calling in, the operator must transfer the line to communication officer to handle and further proceed and keep record on complaint form for receiver (Attachment 2)
- 4.1.3 Communication officer and / or Senior Management or his representative goes out to the suspect location immediately. For basic inspection, if found that the case is might effected by BPEC activities the responsible department have to take action immediately to find out the truth. If found that the case clearly not, BPEC, Communication officer has to inform the truth with evidence to complainant immediately.

4.2 Information Report

| | |
|--|---|
| Standard Operating Procedure | Doc No.: 05-PR-S001 |
| Subject: Community Complaint | Page: 3 of 5 |
| Prepared by: Communication Dept. | Date: 4 June 21 Effective Date :7 June 21 |
| Approved by:  | Revision: 1 |


- 4.2.1 Every form for both receiver and complaint has to keep record on Summary of External Communication and Complaint (Attachment 3) every month (if any) and identify concerned function and level within the facility also summary report all complaints every end of the year for submit to Senior Management sign acknowledge as well.
- 4.2.2 Every complaint has to report to the Senior Management, EN Dept., and Communication Manager and responsible persons immediately by verbal or internal communication system (e-mail or memo) and keep record on Complaint Form (Attachment 1 or 2) and signature of responsible persons for corrective and preventive action before return that form to Communication Dept. and inform to complainant as process.
- 4.2.3 After working hours, the complaint will go to security guard house then inform to Communication officer immediately. In case of serious issue Communication officer, health and safety person and/or management's representative have to be in place as soon as possible.

4.3 Site Inspection

- 4.3.1 The responsible persons to proceeding inspection within BPEC.
- 4.3.2 The result of inspection shall report to Senior Management also inform to Communication Dept. for recording.
- 4.3.3 If found that the issue is not relating to BPEC, Communication officer shall inform to the complainant immediately.
- 4.3.4 If found that the issue is truly happen because of BPEC activities, the responsible person must take action immediately and keep record on Complaint Form (Attachment 1) for follow up in each step of trouble solving and also time frame of work then report to Senior Management and inform to Communication Dept.
- 4.3.5 The responsible persons should coordinate, control situation until trouble has been, and after action must be report to Senior Management and Communication Dept.

4.4 Informing to complainant

- 4.4.1 Communication officer have to gather all information of the trouble such as cause of trouble, how to solve the trouble, period of trouble solving then arrange the meeting with local community to keep them update. Communication person to record all information into Complaint Form.

| | |
|--|---|
| Standard Operating Procedure | Doc No.: 05-PR-S001 |
| Subject: Community Complaint | Page: 4 of 5 |
| Prepared by: Communication Dept. | Date: 4 June 21 Effective Date :7 June 21 |
| Approved by:  | Revision: 1 |

4.5 Recording

- 4.5.1 Communication Dept. to recording all detail of complaint in the Complaint Receiver Form.
- 4.5.2 Communication Dept. to take a complete complaint to submit to Senior Management for sign for approves and acknowledges closing the case.
- 4.5.3 Communication Dept. summary all complaints onto Summary of External Communication and Complaint (if any) (Attachment 3) report to management.
- 4.5.4 The original form for all complaint receiving will be kept at the Communication Dept. and Copy distribution to all concern departments for record and report as responsibility of each department.

5. References


- N/A

6. Glossary:

- 6.1 BPEC : Bangpoo Environmental Complex.
- 6.2 Communication Dept. : Communications Department
- 6.3 EN Dept. : Environmental, Health & Safety Department



7. Definition

- 7.1 Environmental Complaint : All complaint about environment informed by oneself, communication system, writing as a case occur from BPEC activities create dust, noise, odor and others which effected to livelihood of community and environmental.
- 7.2 Organization : Government and Private section
- 7.3 Community : The Local people who live around BPEC Community including also the local people and neighbor company

| | | |
|--|-----------------|---------------------------|
| Standard Operating Procedure | | Doc No.: 05-PR-S001 |
| Subject: Community Complaint | | Page: 5 of 5 |
| Prepared by: Communication Dept. | Date: 4 June 21 | Effective Date :7 June 21 |
| Approved by:  | | Revision: 1 |

who live around BPEC.

7.4 Senior Management : President of BPEC Site

| | |
|---|--|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-PR-S001T |
| เรื่อง: การร้องเรียนด้านสิ่งแวดล้อม | หน้าที่: 1 จาก 4 หน้า |
| จัดเตรียมโดย: แผนกสื่อสารองค์กร | วันที่: 4 มิ.ย. 64 วันที่มีผลบังคับใช้: 7 มิ.ย. 64 |
| อนุมัติโดย:  | แก้ไขครั้งที่: 1 |
| ผู้มีอำนาจ:  | วันที่: 8/6/2564 สำเนาที่: |

การเปลี่ยนแปลงเอกสาร

[illegible]

| | |
|-------------------------------------|---------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-PR-S001T |
| เรื่อง: การร้องเรียนด้านสิ่งแวดล้อม | หน้าที่: 2 จาก 4 หน้า |
| จัดเตรียมโดย: แผนกสื่อสารองค์กร | วันที่: 4 มิ.ย. 64 |
| อนุมัติโดย: [REDACTED] | วันที่มีผลบังคับใช้: 7 มิ.ย. 64 |
| | แก้ไขครั้งที่: 1 |

1. วัตถุประสงค์

เพื่อกำหนดขั้นตอนการปฏิบัติเมื่อเกิดปัญหาการร้องเรียนด้านสิ่งแวดล้อมจากหน่วยงานราชการ,สถานประกอบการ และชุมชน มีจุดหมายเพื่อป้องกันและแก้ไขปัญหาที่เกิดขึ้นเพื่อให้ชุมชน,สถานประกอบการ และหน่วยงานที่เกี่ยวข้องพึงพอใจ

2. ขอบเขตและการใช้งาน

- 2.1 นโยบายนี้ครอบคลุมการร้องเรียนด้านสิ่งแวดล้อมที่ก่อให้เกิดผลกระทบต่อชุมชน, หน่วยงาน และองค์กร ฯลฯ อันมีสาเหตุจากการดำเนินการของโครงการบางปูฯ
- 2.2 ผู้ร้องเรียนครอบคลุมชุมชนที่อยู่รอบโครงการบางปูฯ ตลอดจนหน่วยงาน และองค์กรทั้งภาครัฐและเอกชน
- 2.3 การร้องเรียนครอบคลุมทั้งการร้องเรียนด้วยตนเองต่อหน้า หรือ ผ่านระบบสื่อสารต่างๆ และการร้องเรียนเป็นลายลักษณ์อักษร

3. เอกสารที่เกี่ยวข้อง

- 3.1 05-PR-F001/00 แบบฟอร์มบันทึกการรับร้องเรียน (เอกสารแนบ 1)
- 3.2 05-PR-F002/00 แบบฟอร์มบันทึกการรับร้องเรียน ประจำเดือน (เอกสารแนบ 2)
- 3.3 05-PR-F003/00 แผนภูมิระเบียบวิธีปฏิบัติในการรับเรื่องร้องเรียน (เอกสารแนบ 3)

4. ขั้นตอนการปฏิบัติงาน

4.1 การรับเรื่องร้องเรียน

- 4.1.1 ชุมชน หน่วยงาน และองค์กรต่างๆ สามารถร้องเรียนผลกระทบต่อสิ่งแวดล้อมที่เกิดจากโครงการได้ทั้งด้วยวาจา และลายลักษณ์อักษรที่จัดทำขึ้นเอง หรือบันทึกลงในบันทึกการร้องเรียนสำหรับผู้ร้องเรียน (เอกสารแนบ 1)
- 4.1.2 แผนกสื่อสารองค์กรฯ เป็นหน่วยงานหลักในการรับผิดชอบเกี่ยวกับการรับเรื่องร้องเรียน กรณีผู้ร้องเรียนติดต่อทางโทรศัพท์ พนักงานรับโทรศัพท์จะทำการโอนสายฯ มายังเจ้าหน้าที่แผนกสื่อสารองค์กรฯ เพื่อบันทึกข้อร้องเรียนลงในแบบฟอร์มการรับเรื่องร้องเรียนสำหรับผู้ร้องเรียน (เอกสารแนบ 2) ทุกครั้ง
- 4.1.3 แผนกสื่อสารองค์กรฯ / ผู้บริหาร และ/หรือ ผู้ที่ได้รับมอบหมายจากผู้บริหาร ออกไปยังสถานที่ที่เกิดการร้องเรียนทันทีที่ได้รับแจ้งเหตุ เพื่อตรวจสอบเบื้องต้น หากพบว่าเหตุที่เกิดเป็นผลมาจากการดำเนินงานของโครงการบางปูฯ จริง หรือมีแนวโน้มว่าอาจเกิดเหตุจาก หรือโครงการบางปูฯ ต้องทำการแจ้งไปยังผู้ที่มีหน้าที่รับผิดชอบโดยตรงทันที แต่หากพบเหตุที่เกิดไม่เกี่ยวข้องกับโครงการบางปูฯ เจ้าหน้าที่แผนกสื่อสารองค์กรฯ จะต้องแจ้งไปยังผู้ร้องเรียนทันที

| | |
|-------------------------------------|---------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-PR-S001T |
| เรื่อง: การร้องเรียนด้านสิ่งแวดล้อม | หน้าที่: 3 จาก 4 หน้า |
| จัดเตรียมโดย: แผนกสื่อสารองค์กร | วันที่: 4 มิ.ย. 64 |
| อนุมัติโดย: [REDACTED] | วันที่มีผลบังคับใช้: 7 มิ.ย. 64 |
| | แก้ไขครั้งที่: 1 |

4.2 การแจ้งข้อมูล

- 4.2.1 บันทึกแบบฟอร์มบันทึกการรับร้องเรียนประจำเดือน(เอกสารแนบ 2) เป็นประจำทุกเดือน (ถ้ามี) โดยต้องทำการสรุปและรวบรวมข้อร้องเรียนของทั้งปีทุกสิ้นปี เพื่อเสนอให้ผู้บริหารได้ลงนามรับทราบทุกครั้งด้วย
- 4.2.2 เหตุการณ์ร้องเรียนทุกกรณีจะถูกแจ้งให้ ผู้บริหาร, ผู้จัดการแผนกสิ่งแวดล้อม, ผู้จัดการแผนกสื่อสารองค์กรฯ และผู้เกี่ยวข้องท่านอื่นๆ ทราบทันทีด้วยวาจาหรือระบบการสื่อสารภายในองค์กร พร้อมกับเซ็นชื่อรับทราบในแบบฟอร์มบันทึกการร้องเรียน (เอกสารแนบ 1 และระบุวิธีแก้ไขและป้องกันปัญหา เพื่อส่งแบบฟอร์มดังกล่าว คืนให้กับแผนกประชาสัมพันธ์เพื่อชี้แจงต่อผู้ร้องเรียนต่อไป
- 4.2.3 กรณีนอกเวลาทำการของบริษัทฯ เมื่อมีผู้ร้องเรียนมายังโครงการ เจ้าหน้าที่รักษาความปลอดภัยจะต้องดำเนินการรับเรื่องและแจ้งมายังเจ้าหน้าที่แผนกสื่อสารองค์กรฯ ด้วยวาจาทันที กรณีเกิดการร้องเรียนเนื่องจากการดำเนินการของโครงการก่อให้เกิดผลกระทบต่อสิ่งแวดล้อมต่อชุมชน อย่างรุนแรง ตัวแทนฝ่ายบริหาร / เจ้าหน้าที่สื่อสารองค์กรฯ ฯลฯ จะต้องเดินทางมายังพื้นที่และชี้แจงชุมชนได้ทันที

4.3 การตรวจสอบภายในโครงการ

- 4.3.1 ผู้รับผิดชอบดำเนินการตรวจสอบสาเหตุภายในโครงการ
- 4.3.2 ผลการตรวจสอบจะถูกรายงานให้ผู้บริหารทราบพร้อมแจ้งแผนกสื่อสารองค์กรฯ เพื่อบันทึกเหตุการณ์ร้องเรียน
- 4.3.3 กรณีที่ตรวจสอบแน่ชัดแล้วหากมีสาเหตุจากโครงการอื่นที่รับฯ และโครงการบางปูฯ เจ้าหน้าที่แผนกประชาสัมพันธ์ฯ จะต้องแจ้งให้ผู้ร้องเรียนทราบทันที
- 4.3.4 กรณีที่ตรวจสอบพบว่าสาเหตุจาก โครงการบางปูฯ จริงผู้เจ้าหน้าที่รับผิดชอบจะต้องรับดำเนินการแก้ไขทันที และเขียนบันทึกเพื่อใช้ในการติดตามการแก้ไขและป้องกันปัญหา พร้อมทั้งรายงานต่อผู้จัดการทั่วไปและแจ้งแผนกสื่อสารองค์กรฯ ให้ทราบถึงสาเหตุและประมาณการเวลาในการแก้ไขเพื่อชี้แจงต่อชุมชน โดยจะบันทึกข้อมูลต่าง ๆ ลงในแบบฟอร์มบันทึกการร้องเรียน
- 4.3.5 ผู้รับผิดชอบต้องทำการประสานงาน ควบคุม และแก้ไขจนแล้วเสร็จ ให้แจ้งผู้บริหารและแผนกสื่อสารองค์กรฯ ทราบทุกครั้ง

4.4 การแจ้งผลต่อผู้ร้องเรียน

- 4.4.1 หลังจากทราบสิ่งที่เป็นสาเหตุที่ก่อให้เกิดการร้องเรียน และวิธีการแก้ไขรวมทั้งเวลาสำหรับการแก้ไขแล้ว เจ้าหน้าที่แผนกสื่อสารองค์กรฯ จะออกไปชี้แจงต่อผู้ร้องเรียนให้ทราบข้อเท็จจริงพร้อมบันทึกผลการชี้แจงลงในแบบฟอร์มบันทึกการร้องเรียน

4.5 การบันทึกผล

- 4.5.1 แผนกสื่อสารองค์กรฯ บันทึกรายละเอียดในแบบฟอร์มรับเรื่องร้องเรียนครบทุกขั้นตอน

| | |
|-------------------------------------|---------------------------------|
| มาตรฐานการปฏิบัติงาน | เอกสารหมายเลข: 05-PR-S001T |
| เรื่อง: การร้องเรียนด้านสิ่งแวดล้อม | หน้าที่: 4 จาก 4 หน้า |
| จัดเตรียมโดย: แผนกสื่อสารองค์กร | วันที่: 4 มิ.ย. 64 |
| อนุมัติโดย: น | วันที่มีผลบังคับใช้: 7 มิ.ย. 64 |
| | แก้ไขครั้งที่: 1 |

- 4.5.2 นำบันทึกการร้องเรียนตามแบบฟอร์มเสนอต่อผู้บริหารเพื่อลงนามปิดเรื่องร้องเรียน
- 4.5.3 แผนกสื่อสารองค์กรจะทำการร้องเรียนทุกเดือน (ถ้ามี) (เอกสารแนบ 2) เพื่อรายงานต่อฝ่ายบริหาร
- 4.5.4 แบบฟอร์มต้นฉบับเรื่องการรับเรื่องร้องเรียน จะถูกเก็บรักษาไว้ ณ แผนกสื่อสารองค์กร โดยสำเนาจะถูกส่งไปยังแผนกที่เกี่ยวข้องเพื่อบันทึกและรายงานในส่วนงานที่รับผิดชอบต่อไป

5. เอกสารอ้างอิง

- ไม่มี

6. ประมวลคำศัพท์

- 6.1 โครงการบางปู : บริษัท บางปู เอ็นไวรอนเม้นทอล คอมเพล็กซ์ จำกัด
- 6.2 แผนกสื่อสารองค์กร : แผนกสื่อสารองค์กร
- 6.3 แผนกสิ่งแวดล้อม : แผนกสิ่งแวดล้อม, สุขอนามัย และความปลอดภัย

7. คำนิยาม

- 7.1 การร้องเรียนด้านสิ่งแวดล้อม : การร้องเรียนทุกชนิดทั้งด้วยวาจาจดหมาย/การใช้อุปกรณ์สื่อสาร/การเขียนเป็นลายลักษณ์อักษรที่มีสาเหตุจากการดำเนินการของโครงการบางปู ซึ่งก่อให้เกิดกลิ่น ฝุ่น เสียง และอื่นๆ ที่กระทบต่อชีวิตและความเป็นอยู่ของชุมชนหรือสิ่งแวดล้อม
- 7.2 หน่วยงาน, องค์กร : หน่วยงาน และองค์กรที่เป็นของรัฐบาลและเอกชน
- 7.3 ชุมชน : รวมถึงชุมชนที่อยู่รอบโครงการบางปู และบริษัทใกล้เคียง เป็นต้น
- 7.4 ผู้บริหาร : ประธานบริหารโครงการบางปู

Attachment 1

เอกสารแนบ 1

Complaint form for complainant

แบบฟอร์มบันทึกการรับเรื่องร้องเรียน

COMPLAINT FORM FOR COMPLAINANT

แบบฟอร์มบันทึกการร้องเรียน

1. สำหรับผู้รับเรื่องร้องเรียน (For Receiver Complainant)

ลำดับที่ (No.)

ชื่อผู้ร้องเรียน (Complainant) :

ที่อยู่ (Address) : โทร. (Tel.) :

ช่องทางการร้องเรียน (Channel of Complain) :

☐ ทางโทรศัพท์ (By Phone) ☐ ชี้แจงต่อหน้า (Face to face) ☐ กรอกแบบฟอร์ม (In writing)

เรื่องที่ร้องเรียน (Subject of Complain) :

☐ กลิ่น (Odor) ☐ ฝุ่น (Dust) ☐ เสียง (Noise)

☐ หนูและแมลง (Rodent and Insect) ☐ อื่นๆ (Other)

รายละเอียด/ข้อมูลเพิ่มเติม (Details)

Acknowledge by

รับทราบ

Managing Director/President

2. สำหรับผู้รับผิดชอบ (For responsibility)

• ออกไปยังจุดที่เกิดเหตุและบริเวณข้างเคียง โดย

(Inspect the complaint location by)

• ผลการตรวจสอบ (Results of inspection)

☐ ปัญหาเกิดจากโครงการจริง เนื่องจาก

Trouble occur from ESBEC activities

☐ ไม่ใช่ปัญหาที่เกิดจากโครงการ (Not from ESBEC)

วิธีแก้ไขและป้องกันปัญหา (Corrective and Prevention Action)

ผลการชี้แจงต่อผู้ร้องเรียน (Complainant acknowledgement)

Responsible by

ผู้ดำเนินการ

(.....)

Informed by

ผู้ชี้แจง

(.....)

Approve for close issue

อนุมัติปิดข้อร้องเรียน

Managing Director / President

Date

Attachment 2

เอกสารแนบ 2

Summary of community complaint

สรุปบันทึกการร้องเรียน

ขั้นตอนการรับเรื่องร้องเรียน

Attachment 3
เอกสารแนบ 3

Complaint procedure chart
ขั้นตอนการรับเรื่องร้องเรียน



a member of



05-PR-F002700

Summary of Community Complaint (สรุปปัญหาการร้องเรียน)

For Month

ປະຈຸບັນ...

During Date

...ระหว่างงานที่...

to date

.....


 ZnO

.....ลำดับที่

[illegible]

ขั้นตอนการรับเรื่องร้องเรียน

COMPLAINT PROCEDURE CHART



เอกสารแนบ 2-32

นโยบายด้านอาชีวอนามัยและความปลอดภัย



Health & Safety Policy

Revision 3

Ref. No. : HS001/2020

The goal of Waste Management Siam Ltd. (WMS) is to prevent the occurrence of all work related injuries, illness, accident, drug, alcohol, and property damage affecting our employees and property assets. We are equally committed, to protecting the public and our customer from any event, which could cause harm or economic losses due to our operations.

Our policy is to achieve the goal by adapting the following principles:

1. Conform to all applicable Health & Safety regulations & codes.
2. Provide a safe work environmental by elimination or controlling known hazards with appropriately designed equipment and facilities; by the development, implementation, training of employees on safe operating procedures; and by providing personal protective equipment s required.
3. Test all employees for physical qualification using a medical check
4. Prevention of drugs and alcohol through the implementation of a drug and alcohol policy and medical testing of employees prior to employment and regular random checks in the workplace.
5. Inform employees of hazard associated with their job, and train them to eliminate/reduce risks
6. Emphasize that employees are responsible for performing their work related activities in a safe manner an in accordance with all applicable safety regulations.
7. Delegate accountability and responsibility to Managers and Supervisors for the safety of operations under their control and make evaluations according to their safety record, performance, and discipline.
8. Investigate and report/document all work related injuries, illness, accidents, drug and alcohol, environmental spills, discharges, or emissions.
9. Develop safe work procedure for jobs with potentially hazardous elements and review them regularly.
10. Under take proactive training of latest safety innovations.

All employees are expected to respect their fellow employees, the company and the environmental while supporting and participating in our Health & Safety programs. Together, with teamwork, we can achieve our goals and **"Returning the Environmental to the people of Thailand"** and maintained to ensure that this policy is followed Announcement No HS001/2016 on 27 October 2016

Announced as at January 10th 2020



President

Address: 589/142 Central City Tower 1 Building 25th Floor, Kwang North-Bangna, Khet Bangna Bangkok, Thailand 10260
Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928
www.wms-thailand.com E-mail: info@wms-thailand.com
Operation: Eastern Seaboard Environmental Complex (ESBEC) Tel: (66)-38-346364-7 Fax: (66)-38-346-368
Bangpoo Environmental Complex (BPEC) Tel: (66)-2-709-2546 Fax: (66)-2-709-2547



ประกาศนโยบายความปลอดภัยและอาชีวอนามัย

ฉบับแก้ไขครั้งที่ 3

เลขที่ : HS001/2020

บริษัท เวสต์ แมเนจเม้นท์ สยาม จำกัด (WMS) มีนโยบายในการป้องกันการเกิดเหตุการณ์หรืออุบัติเหตุต่างๆ ที่จะเกิดขึ้นซึ่งเกี่ยวข้องกับ การบาดเจ็บ, เจ็บป่วย, อุบัติเหตุ, ยาเสพติด เครื่องดื่มแอลกอฮอล์และทรัพย์สินเสียหาย ซึ่งจะมีผลกระทบต่อพนักงานและทรัพย์สินของ บริษัทฯ โดยบริษัทฯ มุ่งมั่นที่จะปกป้องสาธารณชนและลูกค้าของบริษัทฯ จากเหตุการณ์ใดๆ ก็ตามที่อาจก่อให้เกิดอันตรายหรือความสูญเสีย ทางเศรษฐกิจอันเนื่องมาจากการดำเนินงานของบริษัทฯ

นโยบายการบริหารดูแลโดยมีหลักการดังต่อไปนี้

1. ปฏิบัติตามข้อกำหนดและกฎหมายด้านความปลอดภัยและอาชีวอนามัย
2. จัดให้มีสภาพแวดล้อมความปลอดภัยโดยจัดหรือควบคุมอันตรายและอุปกรณ์ที่ออกแบบอย่างเหมาะสมและสถานที่ โดยปรับปรุง พัฒนาด้วยวิธีการฝึกอบรมพนักงานในขั้นตอนการปฏิบัติงานอย่างปลอดภัยและจัดหาอุปกรณ์ป้องกันส่วนบุคคล
3. จัดให้มีการตรวจสุขภาพพนักงานทุกคน
4. มีการป้องกันยาเสพติดและแอลกอฮอล์โดยการตรวจสุขภาพพนักงานก่อนจ้างงานและสุ่มตรวจเป็นประจำ
5. แจ้งให้พนักงานทราบถึงความเป็นอันตรายอันเกี่ยวเนื่องจากงานที่ท่าและอบรมพนักงานให้ทราบถึงความปลอดภัยในการทำงานเพื่อ ลดความเสี่ยง
6. ส่งเสริมให้พนักงานมีหน้าที่ดำเนินงานของกิจกรรมทุกอย่างในลักษณะที่ปลอดภัยตามกฎระเบียบด้านความปลอดภัย
7. จัดตั้งตัวแทนผู้รับผิดชอบและความรับผิดชอบในฐานะผู้จัดการและหัวหน้าเพื่อความปลอดภัยของงานดำเนินงานภายใต้การ ควบคุมดูแลและจัดให้มีการประเมินความปลอดภัย บันทึกผลการปฏิบัติและการรักษาระเบียบวินัยอย่างมีประสิทธิภาพ
8. จัดให้มีการสืบสวนและสอบสวน การรายงานและเอกสารที่เกี่ยวข้องกับการบาดเจ็บ, เจ็บป่วย, อุบัติเหตุ, ยาเสพติดและเครื่องดื่ม แอลกอฮอล์ การทกรั่วไหล การปล่อยหรือการระบายของเสียสู่สิ่งแวดล้อม
9. จัดให้มีการพัฒนากระบวนการทำงานที่ปลอดภัยสำหรับงานที่มีองค์ประกอบและอันตรายสำหรับพนักงานอย่างสม่ำเสมอ.
10. จัดให้มีการฝึกอบรมเชิงรุกและนวัตกรรมด้านความปลอดภัยอยู่เสมอ

พนักงานทุกคนจะต้องปฏิบัติตามกฎระเบียบของบริษัทฯ สนับสนุนและมีส่วนร่วมในกิจกรรมด้านความปลอดภัย รวมถึงการทำงานเป็นทีม เพื่อให้บริการเป้าหมาย และ **"คืนสภาพแวดล้อมที่ดีสู่สังคมไทย"** เพื่อให้มั่นใจว่านโยบายนี้ได้ถูกนำไปปฏิบัติอย่างแท้จริง ซึ่งมีผลบังคับใช้ ตามประกาศเดิมเลขที่ HS001/2016 เมื่อวันที่ 27 ตุลาคม 2559

ประกาศ ณ วันที่ 10 มกราคม 2563



ประธานบริหาร

Address: 589/142 Central City Tower 1 Building 25th Floor, Kwang North-Bangna, Khet Bangna Bangkok, Thailand 10260
Tel: (66)-2-745-6926-7 Fax: (66)-2-745-6928
www.wms-thailand.com E-mail: info@wms-thailand.com
Operation: Eastern Seaboard Environmental Complex (ESBEC) Tel: (66)-38-346364-7 Fax: (66)-38-346-368
Bangpoo Environmental Complex (BPEC) Tel: (66)-2-709-2546 Fax: (66)-2-709-2547

เอกสารแนบ 2-33

เอกสารแต่งตั้งคณะกรรมการบริหารความปลอดภัย

คำสั่ง บริษัท บางปู เอ็นไวรอนเมนทอล คอมเพล็กซ์ จำกัด

ที่ 2024-002/BPEC/HS

เรื่อง แต่งตั้งคณะกรรมการความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงาน

ตามที่กฎกระทรวง กำหนดมาตรฐานในการบริหารและการจัดการด้านความปลอดภัย อาชีวอนามัยและสภาพแวดล้อมในการทำงาน พ.ศ. 2549 ลงวันที่ 16 พฤษภาคม 2549 กำหนดให้สถานประกอบการที่มีลูกจ้างตั้งแต่ห้าสิบคนขึ้นไป ให้นายจ้างจัดให้มีคณะกรรมการความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงาน ของสถานประกอบกิจการตามองค์ประกอบที่กำหนด นั้น

บริษัท บางปู เอ็นไวรอนเมนทอล คอมเพล็กซ์ จำกัด ประกอบกิจการ โรงพักขยะมูลฝอย และขยะอุตสาหกรรม (เฉพาะประเภท Non-hazardous waste) และรับดำเนินการดูแล จัดการระบบเตาเผาสาธาณูปโภคของเสียที่รีไซเคิล และบริหารจัดการวัสดุเหลือใช้ ขยะมูลฝอยจากชุมชน และน้ำเสียจากผู้ใช้บริการทั่วประเทศ ตลอดจนผลิตไอน้ำ ล้างภาชนะปนเปื้อน ผลิตเชื้อเพลิงผสม และเชื้อเพลิงทดแทนจากวัสดุไม้ใช้แล้ว มีลูกจ้างจำนวน 120 คน จึงจัดให้มีคณะกรรมการความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงานของสถานประกอบกิจการเลขที่ 965 หมู่ที่ 2 นิคมอุตสาหกรรมบางปู ซอย 3บี ตำบลบางปูใหม่ อำเภอเมืองสมุทรปราการ จังหวัดสมุทรปราการ 10280 ดังนี้

| | |
|-----|---|
| 1. | ประธานกรรมการ |
| 2. | กรรมการผู้แทนนายจ้าง ระดับบังคับบัญชา |
| 3. | กรรมการผู้แทนนายจ้าง ระดับบังคับบัญชา (IN/MN) |
| 4. | กรรมการผู้แทนนายจ้าง ระดับบังคับบัญชา (MN) |
| 5. | กรรมการผู้แทนนายจ้าง ระดับบังคับบัญชา (PR) |
| 6. | กรรมการผู้แทนนายจ้าง ระดับบังคับบัญชา (RC/FB) |
| 7. | กรรมการผู้แทนนายจ้าง ระดับบังคับบัญชา (ENV) |
| 8. | กรรมการผู้แทนฝ่ายลูกจ้าง (IN) |
| 9. | กรรมการผู้แทนฝ่ายลูกจ้าง (HR) |
| 10. | กรรมการผู้แทนฝ่ายลูกจ้าง (ID) |
| 11. | กรรมการผู้แทนฝ่ายลูกจ้าง (LAB) |
| 12. | กรรมการผู้แทนฝ่ายลูกจ้าง (CS) |
| 13. | กรรมการและเลขานุการ (SAFETY) |

โดยให้คณะกรรมการความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงาน มีหน้าที่ดังต่อไปนี้

1. พิจารณานโยบายและแผนงานด้านความปลอดภัยในการทำงาน รวมทั้งความปลอดภัยนอกงาน เพื่อป้องกันและลดการเกิดอุบัติเหตุ การประสบอันตราย การเจ็บป่วย หรือการเกิดเหตุเดือดร้อนรำคาญอันเนื่องมาจากการทำงาน หรือความไม่ปลอดภัยในการทำงานเสนอต่อนายจ้าง
 2. รายงานและเสนอแนะมาตรการหรือแนวทางปรับปรุงแก้ไขให้ถูกต้องตามกฎหมายเกี่ยวกับความปลอดภัยในการทำงานและมาตรฐานความปลอดภัยในการทำงานต่อนายจ้าง เพื่อความปลอดภัยการทำงานของผู้จ้าง ผู้รับเหมา และบุคคลภายนอกที่เข้ามาปฏิบัติงานหรือเข้ามาใช้บริการในสถานประกอบกิจการ
 3. ส่งเสริม สนับสนุน กิจกรรมด้านความปลอดภัยในการทำงานของสถานประกอบกิจการ
 4. พิจารณาข้อบังคับและคู่มือตามข้อ 3 รวมทั้งมาตรฐานด้านความปลอดภัยในการทำงานของสถานประกอบกิจการเสนอต่อนายจ้าง
 5. ดำเนินการปฏิบัติการด้านความปลอดภัยในการทำงาน และตรวจสอบสถิติการประสบอันตรายที่เกิดขึ้นในสถานประกอบกิจการ อย่างน้อยเดือนละหนึ่งครั้ง
 6. พิจารณาโครงการหรือแผนการฝึกอบรมเกี่ยวกับความปลอดภัยในการทำงาน รวมถึงโครงการหรือแผนการอบรมเกี่ยวกับบทบาทหน้าที่ความรับผิดชอบในด้านความปลอดภัยของผู้จ้าง หัวหน้างาน ผู้บริหาร นายจ้าง และบุคลากรทุกระดับเพื่อเสนอความเห็นต่อนายจ้าง
 7. วางระบบการรายงานสภาพการทำงานที่ไม่ปลอดภัยให้เป็นหน้าที่ของผู้จ้างทุกคนทุกระดับต้องปฏิบัติ
 8. ติดตามผลความคืบหน้าเรื่องที่เสนอมา
 9. รายงานผลการปฏิบัติงานประจำปี รวมทั้งระบุปัญหา อุปสรรค และข้อเสนอแนะในการปฏิบัติหน้าที่ของคณะกรรมการเมื่อปฏิบัติหน้าที่ครบหนึ่งปี เพื่อเสนอต่อนายจ้าง
 10. ประเมินผลการดำเนินงานด้านความปลอดภัยในการทำงานของสถานประกอบกิจการ
 11. ปฏิบัติงานด้านความปลอดภัยในการทำงานอื่นตามที่นายจ้างมอบหมาย
- ทั้งนี้ ตั้งแต่บัดนี้เป็นต้นไป โดยให้คณะกรรมการความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงาน ปฏิบัติหน้าที่ในตำแหน่งเป็นเวลาสองปี นับตั้งแต่วันที่ 8 กรกฎาคม 2567 จนถึงวันที่ 8 กรกฎาคม 2569



สั่ง ณ วันที่ 4 เดือน พฤศจิกายน พ.ศ. 2567



ลงชื่อ ...














กรรมการผู้จัดการ
















เอกสารแนบ 2-34















บันทึกการตรวจสอบความปลอดภัยในพื้นที่ทำงาน

| | | <input checked="" type="checkbox"/> In the morning | <input type="checkbox"/> Before lunch time | | | <input type="checkbox"/> In the afternoon | | |
|-------|---|--|--|-------------------|-------------|---|--|--|
| Items | Non compliance issues | Corrective action | Issue Date | Responding person | Target date | Before | | |
| 1 | Material from maintenance job storage at car parking area. And stopper at car parking area was damaged. | Please move out and need to repair stopper. Done | 3-Jan-25 | MN | 30-Jan-25 |  |  | |
| 2 | Dirty conveyor storage outside near fence line . | Please cover by tarpaulin / . Move to 2nd yard. | 3-Jan-25 | MN | 15-Jan-25 |  |  | |
| 3 | Found concrete was damaged. Near Haz feeding area and under furnace. | Need to repair. | 4-Jan-25 | MN | 20-Jan-25 |  |  | |
| 4 | Activated carbon and sand storage block entrance of chemical room. | Please move to other area. | 18-Jan-25 | IN | 26-Jan-25 |  | | |
| 5 | Old board was damaged near infectious waste area. | Please move to dispose. Done | 18-Jan-25 | TD / FB | 22-Jan-25 |  |  | |
| 6 | Waste drop front of Haz building. | Need to cleaning. | 21-Jan-25 | FB | 21-Jan-25 |  |  | |
| 7 | Waste storage near ACAT. | Please move to dispose. | 21-Jan-25 | IN / MN | 24-Jan-25 |  |  | |
| 8 | Fly ash spill near wash bay. | Need to cleaning. | 21-Jan-25 | TD | 21-Jan-25 |  |  | |

| | | <input checked="" type="checkbox"/> In the morning | <input type="checkbox"/> Before lunch time | | | <input type="checkbox"/> In the afternoon | | |
|-------|--|--|--|-------------------|-------------|---|---|--|
| Items | Non compliance issues | Corrective action | Issue Date | Responding person | Target date | Before | | |
| 1 | Activated carbon bag was damaged. | Please change new big bag. Done | 24-Feb-25 | MN | 24-Feb-25 |  |  | |
| 2 | Aluminium scrap put near Fixed bed furnace. | Please collect and send to recycle. Done | 25-Feb-25 | FB | 28-Feb-25 |  |  | |
| 3 | Containers for collect waste for manual feed storage on walk way. | Please move to Haz building. Done | 25-Feb-25 | FB | 26-Feb-25 |  |  | |
| 4 | Found concrete was damaged under furnace. | Need to repair. | 4-Jan-25 | MN | 16-Apr-25 |  | | |
| 5 | Dirty area from fly ash spill on TD yard. | Need to cleaning. | 25-Feb-25 | TD | 28-Feb-25 |  |  | |
| 6 | Fly ash spill front of Haz building. | Need to cleaning. | 27-Feb-25 | TD | 27-Feb-25 |  |  | |
| 7 | Container storage blocked fire fighting equipment. | Please move to other area. | 27-Feb-25 | TD | 28-Feb-25 |  | | |
| 8 | Sand and activated carbon storage blocked entrance of chemical room. | Please keep space / Please move to other area. | 27-Feb-25 | IN | 5-Mar-25 |  | | |
| 9 | Fly ash room was damaged and leak to outside. | Please consider to repairing. | 27-Feb-25 | MN / IN | 31/02/2025 |  |  | |

| | | <input checked="" type="checkbox"/> In the morning | <input type="checkbox"/> Before lunch time | | | <input type="checkbox"/> In the afternoon | | |
|-------|--|---|--|-------------------|-------------|--|---|--|
| Items | Non compliance issues | Corrective action | Issue Date | Responding person | Target date | Before | | |
| 1 | Containers after treat waste storage near Fixed bed furnace. | Please move to dispose / send to recycle. Done | 1-Mar-25 | IN | 5-Mar-25 |  |  | |
| 2 | Container storage unstable near container storage area. | Please move down. Done | 1-Mar-25 | TD | 5-Mar-25 |  |  | |
| 3 | Dirty area at washbay. | Please housekeeping. Done | 4-Mar-25 | TD | 5-Mar-25 |  |  | |
| 4 | Fly ash room was damaged and leak to outside. | Please consider to repairing. Now cleaning waiting to repair. | 27-Feb-25 | MN / IN | 31/02/2025 |  |  | |
| 5 | Found concrete was damaged under furnace. | Need to repair. | 4-Jan-25 | MN | 16-Apr-25 |  | | |
| 6 | Dirty area from fly ash spill on TD yard. | Need to cleaning. | 25-Feb-25 | TD | 10-Mar-25 |  |  | |
| 7 | Waste for manual feed storage on walk way. | Please move to dispose. | 6-Mar-25 | IN | 7-Mar-25 |  |  | |

| | | <input checked="" type="checkbox"/> In the morning | <input type="checkbox"/> Before lunch time | | | <input type="checkbox"/> In the afternoon | | |
|-------|---|---|--|-------------------|-------------|---|---|--|
| Items | Non compliance issues | Corrective action | Issue Date | Responding person | Target date | Before | | |
| 1 | Waste spill on TD yard. | Please cleaning. Done | 31-Mar-25 | TD | 1-Apr-25 |  |  | |
| 2 | Waste spill on TD yard. | Please cleaning. Done | 31-Mar-25 | TD | 1-Apr-25 |  |  | |
| 3 | Found concrete was damaged under furnace. | Need to repair. | 4-Jan-25 | MN | 30-Apr-25 |  | | |
| 4 | The wall was damaged leachate from refuse pit can leak out. behind IN building. | Need to cleaning/ repair. | 17-Mar-25 | MN / IN | 25-Mar-25 |  |  | |
| 5 | Liquid waste storage out of containment area. | Please move to dispose. | 1-Apr-25 | TD | 4-Apr-25 |  |  | |
| 6 | Sludge mixed with flammable material. | Please sorting before move to collect in incombustible container. | 31-Mar-25 | IN / TD | 1-Apr-25 |  |  | |
| 7 | Spray cans put near conveyor. | Please housekeeping area. | 2-Apr-25 | MN / IN | 4-Apr-25 |  |  | |
| 8 | Hopper at direct feed area was damaged. | Need to repair. | 2-Apr-25 | MN | 17-Apr-25 |  |  | |

| Items | Non compliance issues | Corrective action | Issue Date | Responding person | Target date | Before | |
|-------|--|---|------------|-------------------|-------------|--|---|
| | | | | | | | |
| 1 | Container storage blocked fire fighting equipment. | Please move to other area. Done | 24-May-25 | TD | 26-May-25 |  |  |
| 2 | Flooding in BPEC site. | Discharging to canal outside. Done | 27-May-25 | BPEC | 28-May-25 |  |  |
| 3 | Rain water over gutter front of RC building. | Need to pumping. On process | 28-May-25 | FB | 29-May-25 |  |  |
| 4 | Dirty area at Haz liquid feeding area. | Need to cleaning. | 28-May-25 | FB | 30-May-25 |  |  |
| 5 | Haz liquid storage out of containment area. | Please move to dispose / Storage in containment area. | 28-May-25 | FB | 29-May-25 |  |  |
| 6 | Lamp waste storage outside. | Please continue move to manual feed. | 28-May-25 | IN | 31-May-25 |  |  |
| 7 | Dirty area at wash bay area. | Need to cleaning. | 28-May-25 | TD | 30-May-25 |  |  |

| Items | Non compliance issues | Corrective action | Issue Date | Responding person | Target date | Before | |
|-------|---|--|------------|-------------------|-------------|---|---|
| | | | | | | | |
| 1 | Steel plate cover gutter was damaged near car parking area. | Need to repair. Done | 17-Jun-25 | MN | 20-Jun-25 |  |  |
| 2 | Container 30Q storage blocked fire fighting equipment. | Please move to other area. Done | 20-Jun-25 | TD | 21-Jun-25 |  |  |
| 3 | Fly ash room was damaged and ash leak to outside. | Need to cleaning and repair. | 19-Jun-25 | IN / MN | 15-Jul-25 |  |  |
| 4 | Empty containers storage front of air compressor room. | Please move to containers storage area. | 19-Jun-25 | TD / IN | 21-Jun-25 |  |  |
| 5 | Found rain water over gutter around Haz building. | Need to pumping. | 20-Jun-25 | FB | 22-Jun-25 |  |  |
| 6 | Found rain water over gutter near infectious waste area. | Need to pumping. | 21-Jun-25 | FB | 22-Jun-25 |  |  |
| 7 | Container storage unstable. | Please move down. | 21-Jun-25 | TD | 22-Jun-25 |  |  |
| 8 | Waste storage outside near container storage area. | Please move to dispose. | 21-Jun-25 | TD | 22-Jun-25 |  |  |
| 9 | Dirty area from leachate. | Please cleaning. And repair the concrete. | 21-Jun-25 | IN | 22-Jun-25 |  |  |