

เอกสารแนบที่ 2

สำเนาใบอนุญาตโรงแรม



ทะเบียนเลขที่.....๑๐/๒๕๖๓

ใบอนุญาตเลขที่.....๓๐/๒๕๖๓

กระทรวงมหาดไทย

ใบอนุญาตประกอบธุรกิจโรงแรม

ใบอนุญาตฉบับนี้ให้ไว้เพื่อแสดงว่า บริษัท สตาร์โฮม บีช รีสอร์ท จำกัด

โดย นายสมพงศ์ ดาวพิเศษ

ได้รับอนุญาตให้ประกอบธุรกิจโรงแรมตามมาตรา ๑๕ แห่งพระราชบัญญัติ
โรงแรม พ.ศ. ๒๕๔๗ โดยใช้ชื่อภาษาไทยว่า ลา โรซ่า เขาหลัก

ชื่อภาษาต่างประเทศ (ถ้ามี) LA ROSA KHAOLAK

โรงแรมประเภท.....๒.....จำนวนห้องพัก.....๑๔๘.....ห้อง

สถานที่ตั้ง เลขที่ ๕๘/๒ หมู่ที่ ๕ ตำบลคึกคัก

อำเภอตะกั่วป่า จังหวัดพังงา

ตั้งแต่วันที่ ๑๒ เดือน ธันวาคม พ.ศ.๒๕๖๓ ถึง วันที่ ๒๑ เดือน ธันวาคม พ.ศ. ๒๕๖๘


ออกให้ ณ วันที่ ๑๒ เดือน ธันวาคม พ.ศ. ๒๕๖๓



ประทับตราประจำตำแหน่งเป็นสำคัญ

เอกสารแนบที่ 3

หนังสือรับรองบริษัท



The first part of the paper discusses the importance of understanding the cultural context of the research. It highlights the need for researchers to be sensitive to the values and beliefs of the communities they are studying. This is particularly important in the field of education, where cultural differences can significantly impact learning outcomes.

The second part of the paper focuses on the methodology used in the study. It describes the qualitative approach adopted, which involves in-depth interviews and focus group discussions. The researchers aimed to explore the experiences and perceptions of the participants, rather than testing a specific hypothesis.

The third part of the paper presents the findings of the study. It discusses the themes that emerged from the data, such as the role of family in education and the influence of community norms. The researchers found that there were significant differences in the way that different cultural groups viewed education and learning.

The fourth part of the paper discusses the implications of the findings for practice. It suggests that educators should be aware of the cultural context of their students and tailor their teaching accordingly. This could involve using culturally relevant materials and incorporating traditional knowledge into the curriculum.

The fifth part of the paper concludes the study and offers some final thoughts. It emphasizes the importance of ongoing research in this area and the need for collaboration between researchers and the communities being studied.

The first part of the paper discusses the importance of understanding the cultural context of the research. It highlights the need for researchers to be sensitive to the values and beliefs of the communities they are studying. This is particularly important in the field of education, where cultural differences can significantly impact learning outcomes.

The second part of the paper focuses on the methodology used in the study. It describes the qualitative approach adopted, which involves in-depth interviews and focus group discussions. The researchers aimed to explore the experiences and perceptions of the participants, rather than testing a specific hypothesis.

The third part of the paper presents the findings of the study. It discusses the themes that emerged from the data, such as the role of family in education and the influence of community norms. The researchers found that there were significant differences in the way that different cultural groups viewed education and learning.

The fourth part of the paper discusses the implications of the findings for practice. It suggests that educators should be aware of the cultural context of their students and tailor their teaching accordingly. This could involve using culturally relevant materials and incorporating traditional knowledge into the curriculum.

The fifth part of the paper concludes the study and offers some final thoughts. It emphasizes the importance of ongoing research in this area and the need for collaboration between researchers and the communities being studied.

The first part of the paper discusses the importance of understanding the cultural context of the research. It highlights the need for researchers to be sensitive to the values and beliefs of the communities they are studying. This is particularly important in the field of education, where cultural differences can significantly impact learning outcomes.

The second part of the paper focuses on the methodology used in the study. It describes the qualitative approach adopted, which involves in-depth interviews and focus group discussions. The researchers aimed to explore the experiences and perceptions of the participants, rather than testing a specific hypothesis.

The third part of the paper presents the findings of the study. It discusses the themes that emerged from the data, such as the role of family in education and the influence of community norms. The researchers found that there were significant differences in the way that different cultural groups viewed education and learning.

The fourth part of the paper discusses the implications of the findings for practice. It suggests that educators should be aware of the cultural context of their students and tailor their teaching accordingly. This could involve using culturally relevant materials and incorporating traditional knowledge into the curriculum.

The fifth part of the paper concludes the study and offers some final thoughts. It emphasizes the importance of ongoing research in this area and the need for collaboration between researchers and the communities being studied.

เอกสารแนบที่ 4

เอกสารตรวจสอบระบบน้ำใช้



Morning Shift

Daily Check List

UF

June 2025

ENGINEER DEPARTMENT



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date 1/6/63

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	50	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 70%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	12 M ³	PH 7.6 CL 0.2	
มิเตอร์น้ำประปา			
Water Meter			

Othor Comment

Report By ๙๖๖

Verify By



LAFLORE RESORT AND SPA
CHECKLIST FOR UF

Date: 2/6/63

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	50	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	160	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 60%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 70%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	12 M ³	PH 7.6 CL 0.2	
มิเตอร์น้ำประปา			
Water Meter			

Other Comment

Report By 2/6/63

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 3/1/62

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service			
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 190	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	190	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	160	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	70	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	190	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 707	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	910 F	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.6 CL 0.2	
มิเตอร์น้ำประปา			
Water Meter			

Other Comment

Report By

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 4/6/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	190	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	180	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	60	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 80	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	70	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.0 CL 0.2	
มิเตอร์น้ำประปา			
Water Meter			

Othor Comment

Report By *[Signature]*

Verify By



LAFLORES RESORT AND SPA
CHECKLIST FOR UF

Date 5/6/62

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	190	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	60	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	150	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenmer Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenmer Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenmer Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenmer Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenmer Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 90%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.6 CL 0.8	
มิเตอร์น้ำประปา			
Water Meter			

Other Comment

Report By 5/6/62

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 6/6/62

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	190	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	70	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	190	
4 Back-wash Pump	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 80%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	90%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	12 M ³	PH 7.6 CL 0.2	
มิเตอร์น้ำประปา			
Water Meter			

Othor Comment

Report By *Signature*

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 7/6/63

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	190	
2 Pump NaOCL (คลอรีน 2 ถัง น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	60	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	160	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 20	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100+	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.6 CL 0.2	
มิเตอร์น้ำประปา			
Water Meter			

Other Comment

Report By

Verify By



LAFLORESORT AND SPA
CHECKLIST FOR UF

Date: 8/6/08

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	190	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	70	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	160	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	90	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	12 M ³	PH 7.6 CL 0.9	
มิเตอร์น้ำประปา			

Other Comment

Report By 2/2/08

Verify By



LAFLORES RESORT AND SPA
CHECKLIST FOR UF

Date: 11/11/2018

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service			
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 190	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	180	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	60	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 190	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	12 M ³	PH 7.6 CL 6.2	
มิเตอร์น้ำประปา			

Other Comment

Report By: [Signature]

Verify By:



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 10/6/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	160	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	150	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	60	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	150	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenmer Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenmer Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenmer Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenmer Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenmer Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 60+	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 90+	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.2 CL 0.2	
มิเตอร์น้ำประปา			
Water Meter			

Other Comment

Report By 2/6/68

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 11/06/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	180	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
4 Back-wash Pump	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 201	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	901	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.4 CL 0.2	
มิเตอร์น้ำประปา			
Water Meter			

Other Comment

Report By

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 12/06/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 801	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	1001	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 9.6 CL 0.2	
มิเตอร์น้ำประปา			

Other Comment

Report By ๖๕๖๕๕

Verify By



LAFLORESORT AND SPA
CHECKLIST FOR UF

Date 13/06/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service			
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level	
Backwash Service			
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	<u>18</u> M ³	PH <u>7.6</u> CL <u>0.2</u>	
มิเตอร์น้ำประปา			

Other Comment

Report By นางสาว

Verify By



LAFLORE RESORT AND SPA
CHECKLIST FOR UF

Date: 14/6/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	180	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	50	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	50	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	50	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenmer Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenmer Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenmer Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenmer Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenmer Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 100%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.4 CL 0.2	
มิเตอร์น้ำประปา			

Other Comment

Report By ...

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 15/06/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	90	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 80-1	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Full	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.6 CL 0.2	
มิเตอร์น้ำประปา			

Other Comment

Report By

Verify By

Date 18/6/68



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>200</u>	
2 Pump NaOCL (คลอรีน 2 ถัง น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>100</u>	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>150</u>	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>80</u>	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>150</u>	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level <u>90%</u>	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>70%</u>	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	<u>18</u> M ³	PH <u>7.4</u> CL <u>0.2</u>	
ดอร์น้ำประปา			

or Comment

ort By สุกฤษฎี ๗

By

Water Meter



LAFLORE RESORT AND SPA
CHECKLIST FOR UF

Date

19/6/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service			
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 200	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80	
Backwash Service			
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 80	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	150	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 90%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	90%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.4 CL 0.8	
มิเตอร์น้ำประปา			
Water Meter			

Other Comment

Report By

สุทธิชัย

Verify By



LAFLORE RESORT AND SPA
CHECKLIST FOR UF

Date: 20/6/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOCL (คลอรีน 2 ถัง น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	20	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	90	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	150	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 90%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.4 CL 0.2	
มิเตอร์น้ำประปา			

Other Comment

Report By

Verify By



LAFLORE RESORT AND SPA
CHECKLIST FOR UF

Date

21/06/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service			
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 200	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	800	
Backwash Service			
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 100	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 100%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.4 CL 0.2	
มิเตอร์น้ำประปา			

Other Comment

Report By

Verify By



LAFLORESORT AND SPA
CHECKLIST FOR UF

Date 92/06/88

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	180	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 100 %	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100 %	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.6 CL 0.2	
มิเตอร์น้ำประปา			

Othor Comment

Report By 92/06/88

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 23/06/18

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	900	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	760	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 100%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.4 CL 0.2	
มิเตอร์น้ำประปา			
			Water Meter

Other Comment

Report By อนุวัฒน์

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date 29/06/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Filter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>100</u>	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>160</u>	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>90</u>	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>90</u>	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>90</u>	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level <u>90%</u>	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<u>100%</u>	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	<u>78</u> M ³	PH <u>7.6</u> CL <u>0.2</u>	
มีเตอร์น้ำประปา			

Other Comment

Report By กมลรัตน์

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 25/6/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	150	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	60	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 90%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.4 CL 0.2	
มิเตอร์น้ำประปา			

Other Comment

Report By

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 26/6/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	140	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	70	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	60	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	70	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 90%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	90%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.4 CL 0.8	
มิเตอร์น้ำประปา			

Other Comment

Report By

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 27/1/68

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	190	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	60	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	50	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	60	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 90%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.4 CL 0.3	
มิเตอร์น้ำประปา			
Water Meter			

Other Comment

Report By ฟูจิชิ

Verify By



LAFLORES RESORT AND SPA
CHECKLIST FOR UF

Date: 24/6/63

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	180	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	170	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	70	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	56	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	100	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	90%	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	90%	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	1.8 M ³	PH 7.6 CL 0.2	
มิเตอร์น้ำประปา			

Water Meter

Other Comment

Report By

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 29/6/65

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service			
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 900	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 150	
Backwash Service			
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 10	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 50	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 70	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Raw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	19 M ³	PH 7.6	
มิเตอร์น้ำประปา		CL 0.2	
Water Meter			

Other Comment

Report By 29/6/65

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR UF

Date: 30/06/18

CHECKLIST ITEM	CONDITION	STATUS	COMMENT
Ultra filtration System			
Examine Ultra filtration System Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra filtration Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Ultra Filtration Membrane	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Ultra Filtration Chemical Dosing Pump			
Fiter Service		Level	
1 Pump HCL (กรดเกลือ 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
2 Pump NaOCL (คลอรีน 2 ถัง: น้ำ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	200	
Backwash Service		Level	
1 Pump NaOCL (คลอรีน 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80	
2 Pump NaOH (โซดาไฟ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80	
3 Pump HCL (กรดเกลือ 200 ลิตร)	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80	
4 Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
4 CLP Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Softener Filtration			
Examine Softenner Controller	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Pipe	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal		
Examine Softenner Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Softenner Air-Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Examine Back-wash Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Water Tank			
Rnw water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	Level 60.7	
Cold water Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	80.7	
Deepwell Pump			
Deepwell Pump 1	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 3	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Deepwell Pump 5	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
UF Flow-rate	18 M ³	PH 7.6 CL 0.2	
มิเตอร์น้ำประปา			
Water Meter			

Other Comment

Report By กว๊าน

Verify By

เอกสารแนบที่ 5

เอกสารตรวจสอบระบบบำบัดน้ำเสีย



Morning Shift

Daily Check List

MBR

La Rosa

June 2025

ENGINEER DEPARTMENT



LAFLORES RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date: 1/6/18

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examine Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Aerator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Aerator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramete Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramete Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	8 M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Re-Used Tank	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramete Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	400	
Power Summary			
Electric Current A	6.84		
Electric Power Kwh	213.4		
Other Comment			
Report By	160106		
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date 2/6/68

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	<u>8</u> M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<u>300 ml</u>	
Power Summary			
Electric Current <u>10.58</u> A			
Electric Power <u>214.8</u> Kwh			
Other Comment			

Report By 26/10/81

Verify By



LAFLORES RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date: 3/6/68

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	8 M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	400	
Power Summary			
Electric Current 10.79 A			
Electric Power 2.15 Kw			
Other Comment			

Report By: [Signature]

Verify By:



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date 4/6/18

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	<u>8</u> M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<u>300</u>	
Power Summary			
Electric Current <u>10.10</u> A			
Electric Power <u>213.47</u> Kwh			
Other Comment			
Report By <u>gav</u>			
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date 5/6/68

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	<u>8</u> M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<u>400</u>	
Power Summary			
Electric Current <u>7.50</u> A			
Electric Power <u>212.52</u> Kwh			
Other Comment			
Report By <u>6/5/68</u>			
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date: 6/6/18

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	8 M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	400	
Power Summary			
Electric Current 10.78 A			
Electric Power 215.40 Kwh			
Othor Comment			
Report By			
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date

7/6/68

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	8 M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	100	
Power Summary			
Electric Current 9.56 A			
Electric Power 214.48 Kwh			
Other Comment			
Report By			
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date: 8/1/18

CHECKLIST ITEM	STATUS		SW-STATUS		COMMENT
Examind Pipe and Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Clip Pump	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
MBR Flow-rateM ³ /Hrs				
Tank	STATUS		WATER LEVEL		
Equalization Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Aeration Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Membrane Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Re-Used Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Valve Control	STATUS		SW-STATUS		
Auto Peramate Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT		
Check Microbes	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal		
Power Summary					
Electric CurrentA					
Electric PowerKwh					
Other Comment					

Report By

Verify By



**LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA**

Date.....

CHECKLIST ITEM	STATUS		SW-STATUS		COMMENT	
Examind Pipe and Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Influent Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Influent Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Airator Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Airator Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Feed Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Feed Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Air Scoring Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Air Scoring Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Peramate Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Peramate Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Backwash Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Backwash Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Clip Pump	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
MBR Flow-rateM ³ /Hrs					
Tank	STATUS		WATER LEVEL			
Equalization Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low		
Aeration Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low		
Membrane Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low		
Re-Used Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low		
Valve Control	STATUS		SW-STATUS			
Auto Peramate Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Return Sludge Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT			
Check Microbes	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal			
Power Summary						
Electric CurrentA						
Electric PowerKwh						
Othor Comment						

Report By

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date

CHECKLIST ITEM	STATUS		SW-STATUS		COMMENT
Examind Pipe and Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Clip Pump	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
MBR Flow-rateM ³ /Hrs				
Tank	STATUS		WATER LEVEL		
Equalization Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Aeration Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Membrane Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Re-Used Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Valve Control	STATUS		SW-STATUS		
Auto Peramate Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT		
Check Microbes	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal		
Power Summary					
Electric CurrentA					
Electric PowerKwh					
Other Comment					

Report By

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date.....

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump B	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rateM ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input type="checkbox"/> Low	
Re-Used Tank	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input type="checkbox"/> Normal <input type="checkbox"/> AbMormal	
Power Summary			
Electric CurrentA Electric PowerKwh			
Other Comment			
Report By			
Verify By			



LAFLORES RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date.....

CHECKLIST ITEM	STATUS		SW-STATUS		COMMENT
Examind Pipe and Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Clip Pump	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
MBR Flow-rateM ³ /Hrs				
Tank	STATUS		WATER LEVEL		
Equalization Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Aeration Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Membrane Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Re-Used Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Valve Control	STATUS		SW-STATUS		
Auto Peramate Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT		
Check Microbes	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal		
Power Summary					
Electric CurrentA					
Electric PowerKwh					
Othor Comment					

Report By

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date

CHECKLIST ITEM	STATUS		SW-STATUS		COMMENT
Examind Pipe and Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Clip Pump	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
MBR Flow-rateM ³ /Hrs				
Tank	STATUS		WATER LEVEL		
Equalization Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Aeration Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Membrane Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Re-Used Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Valve Control	STATUS		SW-STATUS		
Auto Peramate Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT		
Check Microbes	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal		
Power Summary					
Electric CurrentA					
Electric PowerKwh					
Othor Comment					

Report By

Verify By



LAFLORES RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date: 14/6/68

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal <input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	8 M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	300 sm/	
Power Summary			
Electric Current 13.34 A			
Electric Power 213.12 Kwh			
Other Comment			
Report By JNDAN			
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date

15/06/18

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	<u>18</u> M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<u>400 ml.</u>	
Power Summary			
Electric Current <u>12.06</u> A			
Electric Power <u>213.46</u> Kwh			
Other Comment			
Report By <u>[Signature]</u>			
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date 11/06/18

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	<u>8</u> M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<u>400 ml</u>	
Power Summary			
Electric Current <u>6.84</u> A			
Electric Power <u>213.52</u> Kwh			
Other Comment			
Report By <u>Hand</u>			
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date.....

CHECKLIST ITEM	STATUS		SW-STATUS		COMMENT
Examind Pipe and Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Clip Pump	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
MBR Flow-rateM ³ /Hrs				
Tank	STATUS		WATER LEVEL		
Equalization Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Aeration Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Membrane Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Re-Used Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Valve Control	STATUS		SW-STATUS		
Auto Peramate Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT		
Check Microbes	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal		
Power Summary					
Electric CurrentA					
Electric PowerKwh					
Othor Comment					
Report By					
Verify By					



LAFLORES RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date: 18/6/68

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examined Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal <input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	8 M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	300 m/	
Power Summary			
Electric Current 11.85 A			
Electric Power 213.80 Kwh			
Other Comment			
Report By			
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date

19/6/08

CHECKLIST ITEM	STATUS		SW-STATUS		COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal	<input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input checked="" type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
MBR Flow-rate	8 M ³ /Hrs				
Tank	STATUS		WATER LEVEL		
Equalization Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi	<input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi	<input type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input checked="" type="checkbox"/> Low	
Valve Control	STATUS		SW-STATUS		
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT		
Check Microbes	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	300 m		
Power Summary					
Electric Current 12.06 A					
Electric Power 231.97 Kwh					
Other Comment					
Report By gn884					
Verify By					



LAFLORES RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date 20/6/68

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal <input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	<u>8</u> M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<u>300 ml</u>	
Power Summary			
Electric Current <u>10.87</u> A			
Electric Power <u>214.14</u> Kwh			
Other Comment			
Report By <u>[Signature]</u>			
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date

CHECKLIST ITEM	STATUS		SW-STATUS		COMMENT
Examind Pipe and Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
Clip Pump	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF	
MBR Flow-rateM ³ /Hrs				
Tank	STATUS		WATER LEVEL		
Equalization Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Aeration Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Membrane Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Re-Used Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low	
Valve Control	STATUS		SW-STATUS		
Auto Peramate Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT		
Check Microbes	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal		
Power Summary					
Electric Current	A				
Electric Power	Kwh				
Other Comment					

Report By

Verify By



LA FLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date 22/06/18

CHECKLIST ITEM	STATUS		SW-STATUS			COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal	<input checked="" type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Influent Pump A	<input type="checkbox"/> Normal	<input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input checked="" type="checkbox"/> OFF		
Influent Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Airator Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Airator Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Feed Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Feed Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Peramate Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Peramate Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Backwash Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Backwash Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Clip Pump	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
MBR Flow-rate	8 M ³ /Hrs					
Tank	STATUS		WATER LEVEL			
Equalization Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi	<input type="checkbox"/> Low		
Aeration Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi	<input type="checkbox"/> Low		
Membrane Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input checked="" type="checkbox"/> Low		
Re-Used Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input checked="" type="checkbox"/> Low		
Valve Control	STATUS		SW-STATUS			
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT			
Check Microbes	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	300 ml.			
<p>Power Summary</p> <p>Electric Current <u>10.57</u> A</p> <p>Electric Power <u>214.42</u> Kwh</p>						
Other Comment						

Report By กมลวิมล

Verify By



LAFLORES RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date 23/06/18

CHECKLIST ITEM	STATUS		SW-STATUS		COMMENT
Examined Pipe and Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal	<input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input checked="" type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Airator Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF	
MBR Flow-rate	8 M ³ /Hrs				
Tank	STATUS		WATER LEVEL		
Equalization Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi	<input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi	<input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input checked="" type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input checked="" type="checkbox"/> Low	
Valve Control	STATUS		SW-STATUS		
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT		
Check Microbes	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	360 ml		
Power Summary					
Electric Current	10.47 A				
Electric Power	214.65 Kwh				
Other Comment					
Report By <u>9851108</u>					
Verify By					



**LAFLORES RESORT AND SPA
CHECKLIST FOR MBR LAROSA**

Date

CHECKLIST ITEM	STATUS		SW-STATUS		COMMENT	
Examind Pipe and Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Influent Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Influent Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Airator Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Airator Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Feed Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Feed Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Air Scoring Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Air Scoring Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Peramate Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Peramate Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Backwash Pump A	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Backwash Pump B	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
Clip Pump	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input type="checkbox"/> OFF		
MBR Flow-rateM ³ /Hrs					
Tank	STATUS		WATER LEVEL			
Equalization Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low		
Aeration Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low		
Membrane Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low		
Re-Used Tank	<input type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input type="checkbox"/> Low		
Valve Control	STATUS		SW-STATUS			
Auto Peramate Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Return Sludge Valve	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT			
Check Microbes	<input type="checkbox"/> Normal	<input type="checkbox"/> AbMormal			
Power Summary						
Electric CurrentA						
Electric PowerKwh						
Other Comment						

Report By

Verify By



LAFLORE RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date: 25/6/68

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal <input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	8 M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	300 ml	
Power Summary			
Electric Current 11.14 A			
Electric Power 214.93 Kwh			
Other Comment			
Report By			
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date 26/6/68

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal <input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	<u>8</u> M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<u>300 x 10⁶</u>	
Power Summary			
Electric Current <u>6.18</u> A			
Electric Power <u>275.16</u> Kwh			
Other Comment			

Report By [Signature]

Verify By



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date

27/6/68

CHECKLIST ITEM	STATUS		SW-STATUS			COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Influent Pump A	<input type="checkbox"/> Normal	<input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON	<input checked="" type="checkbox"/> OFF		
Influent Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Airator Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Airator Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Feed Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Feed Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Peramate Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Peramate Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Backwash Pump A	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Backwash Pump B	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
Clip Pump	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON	<input type="checkbox"/> OFF		
MBR Flow-rate	8 M ³ /Hrs					
Tank	STATUS		WATER LEVEL			
Equalization Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi	<input type="checkbox"/> Low		
Aeration Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input checked="" type="checkbox"/> Low		
Membrane Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input checked="" type="checkbox"/> Low		
Re-Used Tank	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi	<input checked="" type="checkbox"/> Low		
Valve Control	STATUS		SW-STATUS			
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto	<input type="checkbox"/> Off	<input type="checkbox"/> Mauaul	
Microbes	STATUS		RESULT			
Check Microbes	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> AbMormal	300 m/			
Power Summary						
Electric Current	18.32 A					
Electric Power	215.32 Kwh					
Other Comment						
Report By	2029 w					
Verify By						



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date: 23/6/03

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal <input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rateM ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Re-Used Tank	<input type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	300m ³	
Power Summary			
Electric CurrentA	10.68		
Electric PowerKwh	215.51		

Othor Comment

Report By

Verify By



LAFLORES RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date: 29/6/2024

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examined Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal <input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal 200 n	
Power Summary			
Electric Current A			
Electric Power Kwh			
Other Comment			
Report By gnr			
Verify By			



LAFLORA RESORT AND SPA
CHECKLIST FOR MBR LAROSA

Date 30/06/18

CHECKLIST ITEM	STATUS	SW-STATUS	COMMENT
Examind Pipe and Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Influent Pump A	<input type="checkbox"/> Normal <input checked="" type="checkbox"/> Abnormal	<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF	
Influent Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Airator Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Feed Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Air Scoring Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Peramate Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump A	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Backwash Pump B	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
Clip Pump	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> ON <input type="checkbox"/> OFF	
MBR Flow-rate	<u>8</u> M ³ /Hrs		
Tank	STATUS	WATER LEVEL	
Equalization Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input checked="" type="checkbox"/> Hi <input type="checkbox"/> Low	
Aeration Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Membrane Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Re-Used Tank	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Abnormal	<input type="checkbox"/> Hi <input checked="" type="checkbox"/> Low	
Valve Control	STATUS	SW-STATUS	
Auto Peramate Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Auto Backwash Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Return Sludge Valve	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<input checked="" type="checkbox"/> Auto <input type="checkbox"/> Off <input type="checkbox"/> Mauaul	
Microbes	STATUS	RESULT	
Check Microbes	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> AbMormal	<u>900 ml</u>	
Power Summary			
Electric Current <u>13.59</u> A			
Electric Power <u>215.86</u> Kwh			
Other Comment			

Report By 9601201

Verify By

เอกสารแนบที่ 6

ใบเสร็จรับสิ่งปลูก

ใบเสร็จจัดเก็บขยะมูลฝอย

เล่มที่

Book No. 2505

93/33/57 ไม้ทอนกลาง จ. อุบลราชธานี

เลขที่

Bill No. 0222

DELIVERY BILL

ใบส่งของ

送貨單

นาม 寶號

Name

ที่อยู่ 住址

Address

วันที่

Date

ทะเบียนการค้า 商標編號

Commilience

จำนวน
Quantity
數量รายการ
Description
貨名หน่วยละ
Unit Price
備註จำนวนเงิน
Amount
金額

1/ตัน ไม้ทอน

2500 20,000

font



RECEIVED

LA FLORA

Khaosk

Date 30/5/25

Received No. 010451

PO No. B202505-70222

☐ Food Inv.☐ Beverage Inv.☐ General Inv.☐ Engineering Inv.☒ Direct To Eng

Receiver By: kranh

บาท
Baht
銖

ส่งของให้ทางภาคกลาง

รวมเงิน
Total
共銀

20,000

โปรดตรวจรับสินค้าให้ถูกต้อง มิฉะนั้นจะไม่รับผิดชอบ และเมื่อชำระเงินแล้ว จะออกใบเสร็จรับเงินถูกต้องตามกฎหมาย

ผู้รับของ 收貨人

RECEIVER

kranh (กาน)

ผู้ส่งของ 送貨人

DELIVER

kranh (กาน)

25 JUN 2025

เล่มที่
Book No. 2505

เลขที่
Bill No. 9844

DELIVERY BILL ใบส่งของ 送貨單

นาม 寶號 5971 ชื่อ 5971 ที่อยู่ 5971 วันที่ 16/5/88
Name 5971 ชื่อ 5971 ที่อยู่ 5971 วันที่ 16/5/88
ที่อยู่ 住址 เลขที่ผู้เสียภาษีอากร : 0-8255-46000-14-0 ทะเบียนการค้า 商標編號
Address เลขที่ผู้เสียภาษีอากร : 0-8255-46000-14-0 Commilience

จำนวน Quantity 數量	รายการ Description 貨名	หน่วยละ Unit Price 備註	จำนวนเงิน Amount 金額
2	(ผลไม้รวม) (ผลไม้รวม)	2500	5,000
<div>RECEIVED LA FLORA Date 26/6/26 Kasolk Receiver No. 010051 PO No. B 202608 09844 <input type="checkbox"/> Food Inv. <input type="checkbox"/> Beverage Inv. <input checked="" type="checkbox"/> General Inv. <input type="checkbox"/> Engineering Inv. <input type="checkbox"/> Direct To Receiver</div>			
บาท Baht 銖	รวมเงิน Total 共銀	5,000	

โปรดตรวจรับสินค้าให้ถูกต้อง มิฉะนั้นจะไม่รับผิดชอบ และเมื่อชำระเงินแล้ว จะออกใบเสร็จรับเงินถูกต้องตามกฎหมาย
ผู้รับของ 收貨人 16/05/25 ผู้ส่งของ 送貨人 ประจักษ์
RECEIVER DELIVER

25 JUN 2025

BY:

เล่มที่

2505

เลขที่

Bill No.

8790

ใบส่งของ

送貨單

นาม 寶號

Name

ที่อยู่ 住址

Address

วันที่ 日期

Date

ทะเบียนการค้า 商標編號

Commencement

จำนวน
Quantity
數量

รายการ
Description
貨名

หน่วยละ
Unit Price
備註

จำนวนเงิน
Amount
銀額

2 / 100 01111111

1500	5000
------	------

~~RECEIVED~~

6. የግልጽ ጥያቄ

14

FLORA Date

Knoblock

Received No. 609034

Case No B202505 ✓ 08790

Food Inv.

LI Coverage Inty.

General Inv.

Engineering Inv

Wires for

Receivable Pay

บาท
Baht
銖

17/11/2020

รวมเงิน
Total
共銀

5000

โปรดตรวจรับสินค้าให้ถูกต้อง มิฉะนั้นจะไม่รับผิดชอบ และเมื่อชำระเงินแล้ว จะออกไปเสริมรับเงินถูกต้องตามกฎหมาย

ผู้รับของ 收貨人 9144

RECEIVER

ผู้ส่งของ 送貨人

DELIVER



ใบเสร็จรับเงินค่าขยะ/ใบกำกับภาษี
สำนักงานเทศบาลตำบลคึกคัก
ต.คึกคักอ.ตะกั่วป่าจ.พังงา
เลขประจำตัวผู้เสียภาษี

ค่าขยะประจำเดือน มิถุนายน-68

ได้รับเงินจาก บ.สตาร์โฮมบิซ รีสอร์ท จก.

ที่อยู่ 59/1 ม.5 ต.คึกคักอ.ตะกั่วป่า จ.พังงา

ใบเสร็จรับเงินเลขที่ 68-009-01190

เลขที่ผู้ชำระค่าขยะ 01190

เบอร์โทร -

บำบัด	ขยะ	ภาษี	รวมเป็นเงินทั้งสิ้น
0.00	2,100.00	0.00	2,100.00
สองพันหนึ่งร้อยบาทถ้วน			

๒๑๑

หัวหน้าหน่วยงานคลัง

นางสาวผกาดี ริมอ่อน
พนักงานเก็บเงิน
วันที่รับเงิน 08/07/2568



ใบเสร็จรับเงินค่าชยะ/ใบกำกับภาษี
สำนักงานเทศบาลตำบลคึกคัก
ต.คึกคักอ.ตะกั่วป่าจ.พังงา
เลขประจำตัวผู้เสียภาษี

ค่าชยะประจำเดือน มิถุนายน-68
ได้รับเงินจาก บ.สตาร์โฮม รีสอร์ท จก.
ที่อยู่ 59/1 ม.5 ต.คึกคักอ.ตะกั่วป่า จ.พังงา

ใบเสร็จรับเงินเลขที่ 68-009-01191
เลขที่ผู้ชำระค่าชยะ 01191

เบอร์โทร -

บับดา	ชยะ	ภาษี	รวมเป็นเงินทั้งสิ้น
0.00	600.00	0.00	600.00
หกกร้อยบาทถ้วน			

๑๕
หัวหน้าหน่วยงานคลัง

นางสาวผกาดี รีม่อน
พนักงานเก็บเงิน
วันที่รับเงิน 08/07/2568



ใบเสร็จรับเงินค่าขยะ/ใบกำกับภาษี

สำนักงานเทศบาลตำบลคึกคัก

ต.คึกคักอ.ตะกั่วป่าจ.พังงา

เลขประจำตัวผู้เสียภาษี

ค่าขยะประจำเดือน มิถุนายน-68

ได้รับเงินจาก บ.สตาร์โฮม รีสอร์ท จก.

ที่อยู่ 48 ม.5 ต.คึกคักอ.ตะกั่วป่า จ.พังงา

ใบเสร็จรับเงินเลขที่ 68-009-01192

เลขที่ผู้ชำระค่าขยะ 01192

เบอร์โทร -

บำบัด	ขยะ	ภาษี	รวมเป็นเงินทั้งสิ้น
0.00	1,920.00	0.00	1,920.00
หนึ่งพันเก้าร้อยยี่สิบบาทถ้วน			

๒๕

หัวหน้าหน่วยงานคลัง

นางสาวผกาดี รีม่อน

พนักงานเก็บเงิน

วันที่รับเงิน 08/07/2568