

ภาคผนวกที่ 5

สำเนาเอกสารประกอบการปฏิบัติตามมาตรการฯ


สำเนาแบบรายงานสรุปการทำงานของระบบบำบัดน้ำเสีย

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง จังหวัดกรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอช รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทธุรกิจ โรงแรม "โรงแรมชมเมอร์เชทัต รัมไนน์ แบงค็อก" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กระทรวงมหาดไทย หมดอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



กิตติและข้อมูลที่ได้เก็บจากแหล่งกำเนิดมลพิษ

[illegible]

หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทิ้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทิ้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

ลงชื่อ



นาย ภัทริติพัทธ์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : Somerset Rama9 Bangkok

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 22

หมู่ที่ :

ឥឡូវ :

ถนน : รัชดาภิเษก

แขวง/ตำบล : ห้วยขวาง

เขต/ตำบล : เขตห้วยขวาง

จังหวัด : กรุงเทพมหานคร

โทรศัพท์ : 022391999

โทรสาร : 022391900

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 445

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 214/2567

ออกให้โดย : กระทรวงมหาดไทย

หมดอายุ : 17/12/2572

ในการนี้ ขอรายงานสรุปผลการดำเนินงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน กรกฎาคม พ.ศ. 2568

ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายณัฏฐิติพัทธ์ ร้อยโสม เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ _____ ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

ลงชื่อ _____ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

2. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

1. ระบบบำบัดน้ำเสียแบบแอคติเวตเต็ดสลัดจ์ (Activated Sludge Process)

353.00 ลบ.ม./วัน

(2) การทำงานของระบบบำบัดน้ำเสีย

[X] แบบต่อเนื่อง 24 ชั่วโมง/วัน

[] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[X] เครื่องสูบน้ำ

[X] ระบบเติมอากาศ

[X] เครื่องกว่น/ผสมน้ำเสีย

[X] เครื่องกวณ/ผสมสารเคมี

[X] เครื่องสูบลมตะกอน

[] อื่นๆ

[] อื่นๆ

[] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ) ระบายออกนอกหม. ผังถนนรัชดาภิเษก

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด จ้างบริษัทสูบน้ำไปกำจัดทิ้ง

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

(1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)

337.700 หน่วย

(2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.)

3,686.000 ลบ.ม.

(3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.)

2,948.800 ลบ.ม.

(4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย

[X] ระบายทุกวัน

[] ระบายบางวัน (ระบุจำนวนวันที่ระบาย)

วัน

[] ไม่ระบายเลย

(5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้

ปริมาณ หน่วย

1.

0.000 กิโลกรัม

(6) การทำงานของระบบบำบัดน้ำเสีย

ระบบบำบัดน้ำเสีย

[X] ปกติ [] ผิดปกติ

เครื่องสูบน้ำ

[X] ปกติ [] ผิดปกติ

ระบบเติมอากาศ

[X] ปกติ [] ผิดปกติ

เครื่องกวน/ผสมน้ำเสีย

[X] ปกติ [] ผิดปกติ

เครื่องกวน/ผสมสารเคมี

[X] ปกติ [] ผิดปกติ

เครื่องสูบลตะกอน

[X] ปกติ [] ผิดปกติ

(7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม

(8) ปัญหา อุปสรรค และแนวทางแก้ไข

คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖


๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง จังหวัดกรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอช รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทธุรกิจ โรงแรม "โรงแรมซัมเมอร์เซ็ท รัชดา แอ่งค็อก" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กระทรวงมหาดไทย หมดอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทิ้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทิ้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

ลงชื่อ



นาย ณัฏฐิพัทธ์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : Somerset Rama9 Bangkok

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 22

หมู่ที่ :

ซอย :

ถนน : รัชดาภิเษก

แขวง/ตำบล : ห้วยขวาง

เขต/ตำบล : เขตห้วยขวาง

จังหวัด : กรุงเทพมหานคร

โทรศัพท์ : 022391999

โทรสาร : 022391900

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 445

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 214/2567

ออกให้โดย : กระทรวงมหาดไทย

หมดอายุ : 17/12/2572

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน สิงหาคม พ.ศ. 2568

ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายณัฏฐิพัทธ์ ร้อยโสม เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ



ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่

หมดอายุ

ออกให้โดย

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่

หมดอายุ

ออกให้โดย

2. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

1. ระบบบำบัดน้ำเสียแบบแอกทิเวเต็ดสลัดจ์ (Activated Sludge Process)

353.00 ลบ.ม./วัน

(2) การทำงานของระบบบำบัดน้ำเสีย

[X] แบบต่อเนื่อง 24 ชั่วโมง/วัน

[] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[X] เครื่องสูบน้ำ

[X] ระบบเติมอากาศ

[X] เครื่องกวน/ผสมน้ำเสีย

[X] เครื่องกวน/ผสมสารเคมี

[X] เครื่องสูบลม

[] อื่นๆ

[] อื่นๆ

[] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ) ระบายออกนอกหม. ผังถนนรัชดาภิเษก

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด จ้างบริษัทสูบน้ำไปกำจัดทิ้ง

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

(1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)

326.300 หน่วย

(2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.)

4,187.000 ลบ.ม.

(3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.)

3,349.600 ลบ.ม.

(4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย

[X] ระบายทุกวัน

[] ระบายบางวัน (ระบุจำนวนวันที่ระบาย)

วัน

[] ไม่ระบายเลย

(5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้

ปริมาณ หน่วย

1.

0.000 กิโลกรัม

(6) การทำงานของระบบบำบัดน้ำเสีย

ระบบบำบัดน้ำเสีย

[X] ปกติ [] ผิดปกติ

เครื่องสูบน้ำ

[X] ปกติ [] ผิดปกติ

ระบบเติมอากาศ

[X] ปกติ [] ผิดปกติ

เครื่องกวน/ผสมน้ำเสีย

[X] ปกติ [] ผิดปกติ

เครื่องกวน/ผสมสารเคมี

[X] ปกติ [] ผิดปกติ

เครื่องสูบลตะกอน

[X] ปกติ [] ผิดปกติ

(7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม

(8) ปัญหา อุปสรรค และแนวทางแก้ไข

คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง

ให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน

ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท

หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖

๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน

โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกิน


หนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง จังหวัดกรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอช รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทธุรกิจ โรงแรม "โรงแรมซัมเมอร์เซ็ท รัชดา บีบี" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กระทรวงมหาดไทย หมดอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทิ้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทิ้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

ลงชื่อ



นาย ฤทธิพิพัทธ์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : Somerset Rama9 Bangkok

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 22

หมู่ที่ :

ซอย :

ถนน : รัชดาภิเษก

แขวง/ตำบล : ห้วยขวาง

เขต/ตำบล : เขตห้วยขวาง

จังหวัด : กรุงเทพมหานคร

โทรศัพท์ : 022391999

โทรสาร : 022391900

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 445

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 214/2567

ออกให้โดย : กระทรวงมหาดไทย

หมดอายุ : 17/12/2572

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน กันยายน พ.ศ. 2568 ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายณัฏฐิพัทธ์ ร้อยโสม เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ  ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ _____ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

1. ระบบบำบัดน้ำเสียแบบแอกทีฟเต็ดสลัดจ์ (Activated Sludge Process)

ความสามารถในการบำบัดน้ำเสีย

353.00 ลบ.ม./วัน

(2) การทำงานของระบบบำบัดน้ำเสีย

[X] แบบต่อเนื่อง 24 ชั่วโมง/วัน

[] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[X] เครื่องสูบน้ำ

[X] ระบบเติมอากาศ

[X] เครื่องกวน/ผสมน้ำเสีย

[X] เครื่องกวน/ผสมสารเคมี

[X] เครื่องสูบลำโพง

[] อื่นๆ

[] อื่นๆ

[] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ) ระบายออกกทม. ผังถนนรัชดาภิเษก

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด จ้างบริษัทสูบน้ำไปกำจัดทิ้ง

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

(1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 294.000 หน่วย

(2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 2,759.000 ลบ.ม.

(3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 2,207.200 ลบ.ม.

(4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย [X] ระบายทุกวัน
[] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน
[] ไม่ระบายเลย

(5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย
1. 0.000 กิโลกรัม

(6) การทำงานของระบบบำบัดน้ำเสีย

ระบบบำบัดน้ำเสีย	[X] ปกติ	[] ผิดปกติ
เครื่องสูบน้ำ	[X] ปกติ	[] ผิดปกติ
ระบบเติมอากาศ	[X] ปกติ	[] ผิดปกติ
เครื่องกวน/ผสมน้ำเสีย	[X] ปกติ	[] ผิดปกติ
เครื่องกวน/ผสมสารเคมี	[X] ปกติ	[] ผิดปกติ
เครื่องสูบลตะกอน	[X] ปกติ	[] ผิดปกติ

(7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม

(8) ปัญหา อุปสรรค และแนวทางแก้ไข

คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖


๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง กรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอช รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทธุรกิจ โรงแรม "โรงแรมซัมเมอร์เซ็ท ราชไนน์ แบงค็อก" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กระทรวงมหาดไทย หมดอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



สถิติและข้อมูลที่เกี่ยวข้องกับจากแหล่งกำเนิดมลพิษ														
วัน/เดือน/ปี	ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)	ปริมาณการใช้ในกิจกรรมของแหล่งกำเนิดมลพิษ(ลบ.ม.)	ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.)	การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย (ระบาย/ไม่ระบาย)	ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ชื่อ/ปริมาณ) (ลิตรหรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย						ปริมาณตะกอนส่วนเกิน	ปัญหาอุปสรรคและแนวทางแก้ไข	ลายมือชื่อผู้บันทึก
						ระบบบำบัดน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติมอากาศ (ปกติ/ผิดปกติ)	เครื่องกวน/ผสมน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบลบตะกอน (ปกติ/ผิดปกติ)	อื่น ๆ (ระบุ)(ปกติ/ผิดปกติ)			
1-Oct-2025	๑.๖	101	๑0.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Amuohh
2-Oct-2025	10.๑	๑5	7๖.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Amuohh
3-Oct-2025	1๑.5	๑6	๑5.๖	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
4-Oct-2025	0	10๑	๑1.๖	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
5-Oct-2025	๑3.4	102	7๑.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
6-Oct-2025	10.7	๑๓	76.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
7-Oct-2025	๑.7	๑5	77.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
8-Oct-2025	๑.๑	๑7	๑0.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
9-Oct-2025	๑.๑	100	๑1.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Amuohh
10-Oct-2025	10.๑	10๑	7๑.4	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Amuohh
11-Oct-2025	10.5	๑๑	๑0.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
12-Oct-2025	๑.๑	101	77.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
13-Oct-2025	๑.๑	๑7	52.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
14-Oct-2025	10.1	65	๑0.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
15-Oct-2025	๑.7	101	7๑.4	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Amuohh
16-Oct-2025	๑.7	๑๑	๑2.4	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Amuohh
17-Oct-2025	10.0	103	๑2.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
18-Oct-2025	10.0	106	๑1.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
19-Oct-2025	๑.๑	10๑	๑6.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
20-Oct-2025	๑.๑	๑1	72.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
21-Oct-2025	๑.7	101	๑0.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
22-Oct-2025	10.0	10๑	๑7.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
23-Oct-2025	๑.๑	12๑	103.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
24-Oct-2025	10.0	1๑6	100.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Amuohh
25-Oct-2025	10.1	107	๑5.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
26-Oct-2025	10.๑	13๑	111.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
27-Oct-2025	10.6	๑2	73.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
28-Oct-2025	10.0	10๑	๑3.๑	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot
29-Oct-2025	11.7	110	๑5.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Amuohh
30-Oct-2025	๑.๑	๑7	77.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Amuohh
				ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ			Kriangyot

หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทิ้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทิ้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

ลงชื่อ



นาย ฤทธิ์พิพัทธ์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : Somerset Rama9 Bangkok

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 22

หมู่ที่ :

ซอย :

ถนน : รัชดาภิเษก

แขวง/ตำบล : ห้วยขวาง

เขต/ตำบล : เขตห้วยขวาง

จังหวัด : กรุงเทพมหานคร

โทรศัพท์ : 022391999

โทรสาร : 022391900

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 445

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 214/2567

ออกให้โดย : กระทรวงมหาดไทย

หมดอายุ : 17/12/2572

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน กันยายน พ.ศ. 2568 ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายณัฏฐิพัทธ์ ร้อยโสม เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ  ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ _____ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

2. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

1. ระบบบำบัดน้ำเสียแบบแอกทิเวเตดสลัดจ์ (Activated Sludge Process)

353.00 ลบ.ม./วัน

(2) การทำงานของระบบบำบัดน้ำเสีย

[X] แบบต่อเนื่อง 24 ชั่วโมง/วัน

[] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[X] เครื่องสูบน้ำ

[X] ระบบเติมอากาศ

[X] เครื่องกวน/ผสมน้ำเสีย

[X] เครื่องกวน/ผสมสารเคมี

[X] เครื่องสูบละกอน

[] อื่นๆ

[] อื่นๆ

[] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ) ระบายออกนอกหม. ผังถนนรัชดาภิเษก

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด จ้างบริษัทสูบน้ำไปกำจัดทิ้ง

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- | | |
|---|--|
| (1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) | 294.000 หน่วย |
| (2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) | 2,759.000 ลบ.ม. |
| (3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) | 2,207.200 ลบ.ม. |
| (4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย | [X] ระบายทุกวัน |
| | [] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน |
| | [] ไม่ระบายเลย |

(5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้	ปริมาณ หน่วย
1.	0.000 กิโลกรัม

(6) การทำงานของระบบบำบัดน้ำเสีย

- | | | |
|-----------------------|------------|-------------|
| ระบบบำบัดน้ำเสีย | [X] ปกติ | [] ผิดปกติ |
| เครื่องสูบน้ำ | [X] ปกติ | [] ผิดปกติ |
| ระบบเติมอากาศ | [X] ปกติ | [] ผิดปกติ |
| เครื่องกวน/ผสมน้ำเสีย | [X] ปกติ | [] ผิดปกติ |
| เครื่องกวน/ผสมสารเคมี | [X] ปกติ | [] ผิดปกติ |
| เครื่องสูบลบตะกอน | [X] ปกติ | [] ผิดปกติ |

(7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม

(8) ปัญหา อุปสรรค และแนวทางแก้ไข


- คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง จังหวัดกรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอส รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทธุรกิจ โรงแรม "โรงแรมซัมเมอร์เซ็ท รัชดา รัชดา บีทีเอส" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กรุงเทพมหานคร หมดอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทั้ง
ทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

ลงชื่อ



นาย นัทธิติพัทธ์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____


ออกให้โดย _____

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง จังหวัดกรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอช รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทธุรกิจ โรงแรม "โรงแรมซัมเมอร์เซ็ท ราชไนน์ แบงค็อก" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กระทรวงมหาดไทย หมุดอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



สถิติและข้อมูลที่เกี่ยวข้องกับการดำเนินงาน											
วัน/เดือน/ปี	ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)	ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ(ลบ.ม.)	ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.)	การระบายน้ำทั้งหมดจากระบบบำบัดน้ำเสีย (ระบาย/ไม่ระบาย)	ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ชื่อ/ปริมาณ) (ลิตรหรือ กิโลกรัม)	การดำเนินงานของระบบบำบัดน้ำเสีย					
						ระบบบำบัดน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติมอากาศ (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ/ผสมน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	อื่น ๆ (ระบุ) (ปกติ/ผิดปกติ)
1-Dec-2025	0.1	101	80.3	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
2-Dec-2025	10.1	100	80.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
3-Dec-2025	10.0	02	77.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
4-Dec-2025	10.6	104	88.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
5-Dec-2025	10.0	101	80.3	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
6-Dec-2025	10.7	101	80.3	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
7-Dec-2025	11.2	122	87.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
8-Dec-2025	10.0	101	80.3	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
9-Dec-2025	10.4	102	81.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
10-Dec-2025	10.1	111	81.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
11-Dec-2025	10.4	03	77.4	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
12-Dec-2025	10.3	130	104.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
13-Dec-2025	10.2	122	87.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
14-Dec-2025	10.4	105	84.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
15-Dec-2025	10.4	100	80.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
16-Dec-2025	10.2	107	85.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
17-Dec-2025	8.2	101	80.3	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
18-Dec-2025	12.6	101	80.3	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
19-Dec-2025	10.4	116	82.3	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
20-Dec-2025	10.5	135	108.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
21-Dec-2025	10.3	106	84.3	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
22-Dec-2025	10.1	100	87.9	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
23-Dec-2025	10.4	102	81.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
24-Dec-2025	10.2	110	88.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
25-Dec-2025	10.1	121	80.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
26-Dec-2025	10.4	138	110.4	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
27-Dec-2025	10.3	150	127.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
28-Dec-2025	11.7	160	135.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
29-Dec-2025	11.4	150	127.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
30-Dec-2025	10.5	153	122.4	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	
31-Dec-2025	10.2	156	124.3	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	

ลายมือชื่อ
ผู้บันทึก

ปัญหา
อุปสรรคและ
แนวทางแก้ไข

ปริมาณ
ตะกอน
ส่วนเกิน

อื่น ๆ
(ระบุ) (ปกติ/
ผิดปกติ)

เครื่องสูบน้ำ
ตะกอน
(ปกติ/ผิดปกติ)

เครื่องสูบน้ำ/ผสมน้ำเสีย
(ปกติ/ผิดปกติ)

เครื่องเติม
อากาศ
(ปกติ/ผิดปกติ)

เครื่องสูบน้ำ
(ปกติ/ผิดปกติ)

ระบบบำบัดน้ำเสีย
(ปกติ/ผิดปกติ)

ปริมาณสารเคมี
หรือสารสกัด
ชีวภาพที่ใช้
(ชื่อ/ปริมาณ)
(ลิตรหรือ
กิโลกรัม)

การระบายน้ำทั้งหมด
จากระบบบำบัดน้ำเสีย
(ระบาย/ไม่ระบาย)

ปริมาณน้ำเสียที่เข้า
ระบบบำบัดน้ำเสีย
(ลบ.ม.)

ปริมาณน้ำใช้ในทุก
กิจกรรมของ
แหล่งกำเนิด
มลพิษ(ลบ.ม.)

ปริมาณการใช้ไฟฟ้าของ
ระบบบำบัดน้ำเสีย (หน่วย)

หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทิ้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทิ้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

ลงชื่อ



นาย ฤทธิ์ทิพัทธ์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : Somerset Rama9 Bangkok

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 22

หมู่ที่ :

ซอย :

ถนน : รัชดาภิเษก

แขวง/ตำบล : ห้วยขวาง

เขต/ตำบล : เขตห้วยขวาง

จังหวัด : กรุงเทพมหานคร

โทรศัพท์ : 022391999

โทรสาร : 022391900

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 445

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 214/2567

ออกให้โดย : กระทรวงมหาดไทย

หมดอายุ : 17/12/2572

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน ธันวาคม พ.ศ. 2568 ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายปฏิวัติ ร้อยโสม เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ  ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ _____ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

2. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

1. ระบบบำบัดน้ำเสียแบบแอกทิเวเต็ดสลัดจ์ (Activated Sludge Process)

353.00 ลบ.ม./วัน

(2) การทำงานของระบบบำบัดน้ำเสีย

[X] แบบต่อเนื่อง 24 ชั่วโมง/วัน

[] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[X] เครื่องสูบน้ำ

[X] ระบบเติมอากาศ

[X] เครื่องกวน/ผสมน้ำเสีย

[X] เครื่องกวน/ผสมสารเคมี

[X] เครื่องสูบลตะกอน

[] อื่นๆ

[] อื่นๆ

[] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ) ระบายออกกทม. ผังถนนรัชดาภิเษก

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด จ้างบริษัทสูบน้ำไปกำจัดทิ้ง

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

(1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 317.400 หน่วย

(2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 3,174.000 ลบ.ม.

(3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 2,539.200 ลบ.ม.

(4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย [X] ระบายทุกวัน
[] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน
[] ไม่ระบายเลย

(5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย
1. 0.000 กิโลกรัม

(6) การทำงานของระบบบำบัดน้ำเสีย

ระบบบำบัดน้ำเสีย	[X] ปกติ	[] ผิดปกติ
เครื่องสูบน้ำ	[X] ปกติ	[] ผิดปกติ
ระบบเติมอากาศ	[X] ปกติ	[] ผิดปกติ
เครื่องกวน/ผสมน้ำเสีย	[X] ปกติ	[] ผิดปกติ
เครื่องกวน/ผสมสารเคมี	[X] ปกติ	[] ผิดปกติ
เครื่องสูบลำไส้	[X] ปกติ	[] ผิดปกติ

(7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม

(8) ปัญหา อุปสรรค และแนวทางแก้ไข

คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง ให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖

๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

สำเนาการตรวจสอบระบบไฟฟ้าของโครงการ

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 28/12/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add its.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>929</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty cleaned
- Record hours meter reading	<u>31.7</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>-</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (58°C - 70°C)	<u>40</u> °C <u>75</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.0/3.4</u> amp <u>1.5/0.9</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>115</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>928</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>31.8</u> hrs.
- Record hours meter reading	

Time start 16.00 Time stop 16.10Total 10 mins

Supervisor's comments _____

Record by

Anuchit[Signature]

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 21/12/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add its.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>930</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>31.5</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>290</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u> </u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>25/2.9</u> amp <u>4.1/0.0</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>115</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>929</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>31.7</u> hrs.
- Record hours meter reading	

Time start 15.45 Time stop 15.55Total 10 mins

Supervisor's comments _____

Record by

AnuchitPimp

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 14/12/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ <u>930</u> Low ☐ () add its.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>930</u> ltrs. Add <u> </u> ltrs.
- Clean air filter	☒ clean <u>31.4</u> hrs. ☐ dirty, cleaned
- Record hours meter reading	
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	☒ clean <u>230</u> () dirty, cleaned
- Check pressure recorder in system	<u>0</u> psi
- Check valves for free travel	(☒) normal () abnormal <u> </u>
- Suction pressure	<u> </u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>20/2.3</u> amp <u>0.5 / 1.5</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal <u> </u>
- Vibration	(☒) Normal () abnormal <u> </u>
- Smoke	(☒) Normal () abnormal <u> </u>
PUMP AND PIPING	
- Check line pressure	<u>250</u> psi
- Pressure relief valve maintain pressure at	<u>100</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak <u> </u>
- Check mechanical seal / packing for leak	(☒) Normal () leak <u> </u>
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal <u> </u>
AFTER ENGINE STOP	
- Reord diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>930</u> ltrs. Add <u> </u> ltrs.
- Record hours meter reading	<u>31.5</u> hrs.

Time start 15.00 Time stop 15.10Total 10 mins

Supervisor's comments

Record by

P. J. P. P.P. J. P. P.

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 07/12/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add its.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>930</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>31.1</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>240</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>-</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (58°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.4/2.9</u> amp <u>4.2/0.0</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>100</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>930</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>31.2</u> hrs.
- Record hours meter reading	

Time start 15.30 Time stop 15.40Total 10 mins

Supervisor's comments _____

Record by

AnuchitAmo

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 30/11/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs)	Full level <u>930</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>30.9</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow ☒ green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>240</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u> </u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.0 / 3.3</u> amp <u>0.4 / 1.5</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>100</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>930</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u> </u> hrs.

Time start 15.40 Time stop 15.50Total 10 mins

Supervisor's comments _____

Record by

PrapornPimpo

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 23/11/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs)	Full level <u>930</u> ltrs. Add _____ ltrs
- Clean air filter	(☒) clean () dirty cleaned
- Record hours meter reading	<u>30.8</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>-</u> ps
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>85</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.3/2.9</u> amp <u>4.2/0.0</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>230</u> psi
- Pressure relief valve maintain pressure at	<u>210</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Reord diesel fuel system	Full level <u>930</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>30.9</u> hrs.
- Record hours meter reading	

Time start 15.00 Time stop 15.10Total 10 mins

Supervisor's comments _____

Record by

AnuchitPump

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 16/11/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add its.
- Diesel fuel tank level (750 - 1,000 Ltrs)	Full level <u>945</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty cleaned
- Record hours meter reading	<u>30.7</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>-</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (58°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.0/2.3</u> amp <u>4.0/0.0</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>210</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>940</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>30.8</u> hrs.
- Record hours meter reading	

Time start 16.20 Time stop 16.30Total 10 mins

Supervisor's comments _____

Record by

AnuchitAmgo

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 9/11/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs)	Full level <u>950</u> ltrs. Add _____ ltrs
- Clean air filter	(☒) clean () dirty cleaned
- Record hours meter reading	<u>30.6</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>-</u> ps
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.4 / 2.9</u> amp <u>4.1 / 0.0</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Reord diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>950</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>30.7</u> hrs.

Time start 15.30 Time stop 15.35Total 5 mins

Supervisor's comments _____

Record by

AnuchitPump

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE

2/11/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs)	Full level <u>950</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty cleaned
- Record hours meter reading	<u>700</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>240</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u> </u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (58°C - 70°C)	<u>40</u> °C <u>40</u> °C
- Engine speed	<u>2,200</u> rpm <u>2,200</u> rpm
- Check current charging to battery	<u>04,20.1</u> amp <u>4.200</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>100</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>950</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>700</u> hrs.

Time start 15:00 Time stop 15:10Total 10 mins

Supervisor's comments _____

Record by

DAN SP. King

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE

26/10/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add its.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>790</u> ltrs. Add _____ ltrs.
- Clean air filter	(/) clean <u>30.3</u> hrs. () dirty, cleaned
- Record hours meter reading	
BATTERY	
- Check current charging to battery	(/) charge () No charge
- Check battery terminals	(/) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (/) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(/) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(/) normal () abnormal _____
- Suction pressure	<u>—</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (58°C - 70°C)	<u>40</u> °C <u>40</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.0 / 1.7</u> amp <u>0.4 / 1.5</u> amp
- Check for leaks around the engine	(/) Normal () leak
- Noises	(/) Normal () abnormal _____
- Vibration	(/) Normal () abnormal _____
- Smoke	(/) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>246</u> psi
- Pressure relief valve maintain pressure at	<u>116</u> psi
- Check for leaks around the pump & piping	(/) Normal () leak _____
- Check mechanical seal / packing for leak	(/) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>790</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>800</u> hrs.
- Record hours meter reading	

Time start 15-10 Time stop 15-20Total 10 mins

Supervisor's comments _____

Record by

P. JayaramP. Jayaram

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 19/10/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>290</u> ltrs. Add _____ ltrs.
- Clean air filter	(/) clean () dirty, cleaned
- Record hours meter reading	<u>30.2</u> hrs.
BATTERY	
- Check current charging to battery	(/) charge () No charge
- Check battery terminals	() tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (/) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(/) clean () dirty, cleaned
- Check pressure recorder in system	<u>242</u> psi
- Check valves for free travel	(/) normal () abnormal _____
- Suction pressure	<u>1</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0A, 0.1</u> amp <u>4.1, 0.0</u> amp
- Check for leaks around the engine	(/) Normal () leak
- Noises	(/) Normal () abnormal _____
- Vibration	(/) Normal () abnormal _____
- Smoke	(/) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>242</u> psi
- Pressure relief valve maintain pressure at	<u>125</u> psi
- Check for leaks around the pump & piping	(/) Normal () leak _____
- Check mechanical seal / packing for leak	(/) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal () abnormal _____
AFTER ENGINE STOP	
- Reord diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>290</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>30.3</u> hrs.

Time start 14.47 Time stop 14.57Total 10 mins

Supervisor's comments _____

Record by

PumpPump

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 12/10/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs)	Full level <u>790</u> ltrs. Add <u>-</u> ltrs.
- Clean air filter	(☒) clean () dirty cleaned
- Record hours meter reading	<u>30.0</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>229</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>-1</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>0</u> bar Running (10 mins) <u>5.1</u> bar
- Cooling water temp (58°C - 70°C)	<u>40</u> °C <u>70</u> °C
- Engine speed	<u>2800</u> rpm <u>2800</u> rpm
- Check current charging to battery	<u>0.1, 0.4</u> amp <u>0.6, 1.3</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>230</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>790</u> ltrs. Add <u>-</u> ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>30.2</u> hrs.
- Record hours meter reading	

Time start 14.40 Time stop 14.50Total 10 mins

Supervisor's comments _____

Record by

Bruno[Signature]

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE

9/10/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Clean air filter	(/) clean () dirty, cleaned
- Record hours meter reading	<u>29.2</u> hrs.
BATTERY	
- Check current charging to battery	(/) charge () No charge
- Check battery terminals	(/) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (/) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(/) clean () dirty, cleaned
- Check pressure recorder in system	<u>234</u> psi
- Check valves for free travel	(/) normal () abnormal _____
- Suction pressure	<u>—</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>50</u> °C <u>20</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>20, 3.6</u> amp <u>0.4, 1.5</u> amp
- Check for leaks around the engine	(/) Normal () leak
- Noises	(/) Normal () abnormal _____
- Vibration	(/) Normal () abnormal _____
- Smoke	(/) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>210</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(/) Normal () leak _____
- Check mechanical seal / packing for leak	(/) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal () abnormal _____
AFTER ENGINE STOP	
- Reord diesel fuel system	Full level <u>800</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>29.8</u> hrs.
- Record hours meter reading	

Time start 15.30 Time stop 15.40Total 10 mins

Supervisor's comments

Record by

BarPring

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE

28/9/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>29.6</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal
- Suction pressure	_____ psi <u>1250 WSW</u>
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>6.5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.4 / 2.9</u> amp <u>0.5 / 1.5</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal (☒) leak <u>no Relief st</u>
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>29.7</u> hrs.

Time start 14-30 Time stop 14-40Total 10 mins

Supervisor's comments _____

Record by

P. PrapichayP. Prapichay

SOMERSET

RAMA 3
SANDOK

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE

21/9/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>400</u> ltrs. Add _____ ltrs.
- Clean air filter	(/) clean <u>29.5</u> hrs. () dirty, cleaned
- Record hours meter reading	
BATTERY	
- Check current charging to battery	(/) charge () No charge
- Check battery terminals	(/) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (/) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(/) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(/) normal () abnormal _____
- Suction pressure	_____ psi <u>125 to 120</u>
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>22 / 3.7</u> amp <u>0.5 / 1.5</u> amp
- Check for leaks around the engine	(/) Normal () leak
- Noises	(/) Normal () abnormal _____
- Vibration	(/) Normal () abnormal _____
- Smoke	(/) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	() Normal (/) leak <u>no Relief</u>
- Check mechanical seal / packing for leak	(/) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>29.6</u> hrs.

Time start 15.00 Time stop 15.10Total 10 mins

Supervisor's comments _____

Record by

P. PrapthayP. Prapthay

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE

16/9/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>314</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>22.4</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal
- Suction pressure	_____ psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.7/2.9</u> amp <u>0.5/1.6</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
PUMP AND PIPING	
- Check line pressure	<u>2400</u> psi
- Pressure relief valve maintain pressure at	<u>100</u> psi
- Check for leaks around the pump & piping	(☒) Normal (☒) leak <u>no Relief</u>
- Check mechanical seal / packing for leak	(☒) Normal () leak
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Record hours meter reading	_____ hrs.

Time start 15.0 Time stop 15.10Total 10 mins

Supervisor's comments

Record by

P. SinghP. Singh

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE

7/6/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Clean air filter	(/) clean () dirty, cleaned
- Record hours meter reading	<u>27.3</u> hrs.
BATTERY	
- Check current charging to battery	(/) charge () No charge
- Check battery terminals	(/) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (/) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(/) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(/) normal () abnormal
- Suction pressure	<u>—</u> psi <u>1250 psi</u>
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.5/1.6</u> amp <u>0.5/1.5</u> amp
- Check for leaks around the engine	(/) Normal () leak
- Noises	(/) Normal () abnormal
- Vibration	(/) Normal () abnormal
- Smoke	(/) Normal () abnormal
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>100</u> psi
- Check for leaks around the pump & piping	(/) Normal () leak
- Check mechanical seal / packing for leak	(/) Normal () leak
- Examine for abnormal noise, heat, vibration	(/) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Record hours meter reading	_____ hrs.

Time start 15.00Time stop 15.10Total 10 mins

Supervisor's comments

Record by

P. PrithviP. Prithvi

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 31-8-25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>800</u> ltrs. Add <u>-</u> ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>29.2</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>2</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>90</u> ^{psi} bar Running (10 mins) <u>70</u> ^{psi} bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>13.5</u> VDC amp <u>13.5</u> VDC amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>29.3</u> hrs.

Time start 15.30 Time stop 15.40Total 10 mins

Supervisor's comments _____

Record by

SupagritDMG

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 24/8/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>29.1</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>4</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>80</u> bar Running (10 mins) <u>80</u> bar
- Cooling water temp (50°C - 70°C)	<u>45</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>14 VDC</u> amp <u>15 VDC</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>230</u> psi
- Pressure relief valve maintain pressure at	<u>200</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>800</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>29.2</u> hrs.

Time start 15.25 Time stop 15.35Total 10 mins

Supervisor's comments _____

Record by

Supagrit[Signature]

SOMERSET

1444A 3
3446XDC

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE

17-8-25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Clean air filter	(/) clean () dirty, cleaned
- Record hours meter reading	<u>28.9</u> hrs.
BATTERY	
- Check current charging to battery	(/) charge () No charge
- Check battery terminals	(/) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (/) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(/) clean () dirty, cleaned
- Check pressure recorder in system	<u>233</u> psi
- Check valves for free travel	(/) normal () abnormal _____
- Suction pressure	<u>5</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>50</u> °C <u>50</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.1 / 0.4</u> amp <u>0.5 / 1.5</u> amp
- Check for leaks around the engine	(/) Normal () leak _____
- Noises	(/) Normal () abnormal _____
- Vibration	(/) Normal () abnormal _____
- Smoke	(/) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>100</u> psi
- Check for leaks around the pump & piping	(/) Normal () leak _____
- Check mechanical seal / packing for leak	(/) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>800</u> ltrs. Add <u>-</u> ltrs.
- Record hours meter reading	<u>29</u> hrs.

Time start 15.30 Time stop 15.40Total 10 mins

Supervisor's comments

Record by

Supagri +

Pmg

SOMERSET

344680K

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 10/08/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>800</u> ltrs. Add ltrs.
- Clean air filter	() clean () dirty, cleaned
- Record hours meter reading	<u>28.9</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>243</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>4.5</u> bar Running (10 mins) <u>5.1</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>60</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.4/3.0</u> amp <u>0.5/1.4</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>105</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>795</u> ltrs. Add ltrs.
- Record hours meter reading	<u>28.9</u> hrs.

Time start 15.30 Time stop 15.35Total 5 mins

Supervisor's comments _____

Record by

AnuchitPmp

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 3-8-25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Clean air filter	☒ clean () dirty, cleaned
- Record hours meter reading	<u>28.8</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow ☒ green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>243.</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>4.5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>0</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.4 / 3.0</u> amp <u>0.5 / 1.4</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240.</u> psi
- Pressure relief valve maintain pressure at	<u>105</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>800</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>28.9</u> hrs.
- Record hours meter reading	

Time start 15.30 Time stop 15.40 Total 10 minsSupervisor's comments - Test Auto.

Record by

SupagritPump

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 27-7-25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Clean air filter	(/) clean () dirty, cleaned
- Record hours meter reading	<u>28.7</u> hrs.
BATTERY	
- Check current charging to battery	(/) charge () No charge
- Check battery terminals	(/) tight, clean () loose, tightened
- Check distilled water level	Full ☐ Low ☐
- Record SP.G. level	() red () yellow (/) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(/) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(/) normal () abnormal _____
- Suction pressure	<u>-30</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>0</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.6 / 3.0</u> amp <u>0.5 / 1.4</u> amp
- Check for leaks around the engine	(/) Normal () leak
- Noises	(/) Normal () abnormal _____
- Vibration	(/) Normal () abnormal _____
- Smoke	(/) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>100</u> psi
- Check for leaks around the pump & piping	(/) Normal () leak _____
- Check mechanical seal / packing for leak	(/) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>800</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>28.8</u> hrs.

Time start 15.20 Time stop 15.30Total 10 mins

Supervisor's comments _____

Record by

SupagritPingy

SOMERSET

- 11111111
34444444

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 20/7/25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>825</u> ltrs. Add ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>28.5</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>-30</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2-6/2.0</u> amp <u>0.5/1.4</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>100</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>820</u> ltrs. Add ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>28.7</u> hrs.
- Record hours meter reading	

Time start 14-40 Time stop 14-50Total 10 mins

Supervisor's comments _____

Record by

P. PhaphayP. Phaphay

SOMERSET

SOMERSET
3446806

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 13-07-25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>825</u> ltrs. Add _____ ltrs.
- Clean air filter	☒ clean () dirty, cleaned
- Record hours meter reading	<u>28.2</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow ☒ green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	☒ clean () dirty, cleaned
- Check pressure recorder in system	<u>235</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>40</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5.4</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>70</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.1 / 3.4</u> amp <u>0.5 / 1.4</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>110</u> psi
- Pressure relief valve maintain pressure at	<u>242</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>825</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>28.3</u> hrs.

Time start 14.55 Time stop 15.10Total 10 mins

Supervisor's comments _____

Record by

SupagritPmp

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 06-07-25

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>825</u> ltrs. Add _____ ltrs.
- Clean air filter	(/) clean () dirty, cleaned
- Record hours meter reading	<u>28.0</u> hrs.
BATTERY	
- Check current charging to battery	(/) charge () No charge
- Check battery terminals	(/) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (/) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(/) clean () dirty, cleaned
- Check pressure recorder in system	<u>275</u> psi
- Check valves for free travel	(/) normal () abnormal _____
- Suction pressure	<u>105</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.0</u> bar Running (10 mins) <u>5.4</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>70</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.1 / 3.4</u> amp <u>0.5 / 1.4</u> amp
- Check for leaks around the engine	(/) Normal () leak _____
- Noises	(/) Normal () abnormal _____
- Vibration	(/) Normal () abnormal _____
- Smoke	(/) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>110</u> psi
- Pressure relief valve maintain pressure at	<u>275</u> psi
- Check for leaks around the pump & piping	(/) Normal () leak _____
- Check mechanical seal / packing for leak	(/) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>825</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>28.2</u> hrs.
- Record hours meter reading	

Time start 15.00 Time stop 15.15Total 15 mins

Supervisor's comments _____

Record by

SupagritPump

สำเนาแบบบันทึกการตรวจสอบระบบป้องกันอัคคีภัยของโครงการ

Fire Extinguisher Report of July 2025

No.	Floor	Location	Type	Total	Status		Check date	Remark
					Yes	No		
1	B	Security Store	ADE 2000	4	✓		2-Jul-25	Pong
2	B	Electrical Room	ADE 2000	1	✓		2-Jul-25	Pong
3	B	Engineering Workshop	ADE 2000	2	✓		2-Jul-25	Pong
4	B	Engineering Store	ADE 2000	1	✓		2-Jul-25	Pong
5	B	Chemical Room	ADE 2000	2	✓		2-Jul-25	Pong
6	B	Houskeeping Store	ADE 2000	1	✓		2-Jul-25	Pong
7	B	Houskeeping Office	ADE 2000	1	✓		2-Jul-25	Pong
8	B	FCC Room	ADE 2000	1	✓		2-Jul-25	Pong
9	B	Fire Pump Room	ADE 2000	2	✓		2-Jul-25	Pong
10	B	Finance Accounting Office	ADE 2000	1	✓		2-Jul-25	Pong
11	B	Staff Canteen Room	ADE 2000	1	✓		2-Jul-25	Pong
12	G	MDB and Generator	ADE 2000	2	✓		2-Jul-25	Pong
13	G	Server Room	ADE 2000	2	✓		2-Jul-25	Pong
14	G	Guest Service Office	ADE 2000	1	✓		2-Jul-25	Pong
15	G	Executive Office	ADE 2000	1	✓		2-Jul-25	Pong
16	R	Control lift Rooftop	ADE 2000	1	✓		2-Jul-25	Pong
			Total	24				

CO2

1	B	Fire Cart	CO2	1	✓		2-Jul-25	Pong
2		FCC Room	CO2	1	✓		2-Jul-25	Pong
3		Security Store	CO2	10	✓		2-Jul-25	Pong
4	G	Server Room	CO2	1	✓		2-Jul-25	Pong
5		FHC - Front of Saver Room	CO2	1	✓		2-Jul-25	Pong
6	2	Rama 9 Sound Control Room	CO2	1	✓		2-Jul-25	Pong
7	8	E & E Room	CO2	1	✓		2-Jul-25	Pong
8	9	E & E Room	CO2	1	✓		2-Jul-25	Pong
9	10	E & E Room	CO2	1	✓		3-Jun-25	Saksith
10	11	E & E Room	CO2	1	✓		3-Jun-25	Saksith
11	12	E & E Room	CO2	1	✓		3-Jun-25	Saksith
12	13	E & E Room	CO2	1	✓		3-Jun-25	Saksith
13	14	E & E Room	CO2	1	✓		3-Jun-25	Saksith
14	15	E & E Room	CO2	1	✓		3-Jun-25	Saksith
15	16	E & E Room	CO2	1	✓		3-Jun-25	Saksith
16	17	E & E Room	CO2	1	✓		3-Jun-25	Saksith
17	18	E & E Room	CO2	1	✓		3-Jun-25	Saksith
18	19	E & E Room	CO2	1	✓		3-Jun-25	Saksith
19	20	E & E Room	CO2	1	✓		3-Jun-25	Saksith
20	21	E & E Room	CO2	1	✓		3-Jun-25	Saksith
21	22	E & E Room	CO2	1	✓		3-Jun-25	Saksith
22	23	E & E Room	CO2	1	✓		3-Jun-25	Saksith
23	24	E & E Room	CO2	1	✓		3-Jun-25	Saksith
24	25	E & E Room	CO2	1	✓		3-Jun-25	Saksith
25	26	E & E Room	CO2	1	✓		3-Jun-25	Saksith
26	27	E & E Room	CO2	1	✓		3-Jun-25	Saksith
27	28	E & E Room	CO2	1	✓		3-Jun-25	Saksith
28	29	E & E Room	CO2	1	✓		3-Jun-25	Saksith
29	30	E & E Room	CO2	1	✓		3-Jun-25	Saksith
30	31	E & E Room	CO2	1	✓		3-Jun-25	Saksith
31	32	E & E Room	CO2	1	✓		3-Jun-25	Saksith
32	33	E & E Room	CO2	1	✓		3-Jun-25	Saksith
33	34	E & E Room	CO2	1	✓		3-Jun-25	Saksith
34	35	E & E Room	CO2	1	✓		3-Jun-25	Saksith
35	36	Front of Control lift room	CO2	1	✓		2-Jun-25	Saksith
			Total	44				

Dry Chemical								
No.	Floor	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	Pong
2		FHC - Front of FCC	Dry Chemical	1	✓		2-Jul-25	Pong
3		Gas Station (15 lbs)	Dry Chemical	6	✓		2-Jul-25	Pong
4		Front of Garbage Room	Dry Chemical	1	✓		2-Jul-25	Pong
5		Front of Housekeeping Store	Dry Chemical	1	✓		2-Jul-25	Pong
6		Fire Cart	Dry Chemical	1	✓		2-Jul-25	Pong
7		Security Store	Dry Chemical	6	✓		2-Jul-25	ไข่มไต้ 2 ถัง
8		Fire Pump Room	Dry Chemical	1	✓		2-Jul-25	Pong
9		Front of Timekeeper	Dry Chemical	1	✓		2-Jul-25	Pong
10	G	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	Pong
11		FHC - Front ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
12	2	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	Pong
13		Front of First aid Room	Dry Chemical	1	✓		2-Jul-25	Pong
14		Front of HK Store (Outsource)	Dry Chemical	1	✓		2-Jul-25	Pong
15		FHC - Front of ST-1	Dry Chemical	1	✓		2-Jul-25	Pong
16		FHC - Front of ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
17	3	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	Pong
18		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	Pong
19		FHC - Front of ST-1	Dry Chemical	1	✓		2-Jul-25	Pong
20		Parking Area Zone 4B	Dry Chemical	1	✓		2-Jul-25	Pong
21		FHC - Front of ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
22		Parking Area Zone 2A	Dry Chemical	1	✓		2-Jul-25	Pong
23	4	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	Pong
24		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	Pong
25		FHC - Front of ST-1	Dry Chemical	1	✓		2-Jul-25	Pong
26		Parking Area Zone 4B	Dry Chemical	1	✓		2-Jul-25	Pong
27		FHC - Front of ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
28		Parking Area Zone 2A	Dry Chemical	1	✓		2-Jul-25	Pong
29		Parking Area Zone 8A	Dry Chemical	1	✓		2-Jul-25	Pong
30		Parking Area Zone C	Dry Chemical	1	✓		2-Jul-25	Pong
31	5	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	Pong
32		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	Pong
33		FHC - Front of ST-1	Dry Chemical	1	✓		2-Jul-25	Pong
34		Parking Area Zone 4B	Dry Chemical	1	✓		2-Jul-25	Pong
35		FHC - Front of ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
36		Parking Area Zone 2A	Dry Chemical	1	✓		2-Jul-25	Pong
37		Parking Area Zone 8A	Dry Chemical	1	✓		2-Jul-25	Pong
38		Parking Area Zone C	Dry Chemical	1	✓		2-Jul-25	Pong
39	6	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	Pong
40		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	Pong
41		FHC - Front of ST-1	Dry Chemical	1	✓		2-Jul-25	Pong
42		Parking Area Zone 4B	Dry Chemical	1	✓		2-Jul-25	Pong
43		Inside ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
44		FHC - Front of ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
45		Parking Area Zone 2A	Dry Chemical	1	✓		2-Jul-25	Pong
46		Parking Area Zone 8A	Dry Chemical	1	✓		2-Jul-25	Pong
47		Parking Area Zone C	Dry Chemical	1	✓		2-Jul-25	Pong
48	7	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	Pong
49		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	Pong
50		FHC - Front of ST-1	Dry Chemical	1	✓		2-Jul-25	Pong
51		Parking Area Zone 4B	Dry Chemical	1	✓		2-Jul-25	Pong
52		Inside ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
53		FHC - Front of ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
54		Parking Area Zone 2A	Dry Chemical	1	✓		2-Jul-25	Pong
55		Parking Area Zone 8A	Dry Chemical	1	✓		2-Jul-25	Pong
56		Parking Area Zone C	Dry Chemical	1	✓		2-Jul-25	Pong

57	7M	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	Pong
58		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	Pong
59		Pool Pump Room	Dry Chemical	1	✓		2-Jul-25	Pong
60		Front of Pump room	Dry Chemical	1	✓		2-Jul-25	Pong
61		Parking Area Zone A	Dry Chemical	1	✓		2-Jul-25	Pong
62		FHC - Front of ST-1	Dry Chemical	1	✓		2-Jul-25	Pong
63		Parking Area Zone 2A	Dry Chemical	1	✓		2-Jul-25	Pong
64		FHC - Inside ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
65		Inside ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
66	8	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	Pong
67		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	Pong
68		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	Pong
69		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
70		Front of Apt#810	Dry Chemical	1	✓		2-Jul-25	Pong
71		Beside Apt#817	Dry Chemical	1	✓		2-Jul-25	Pong
72	9	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	Pong
73		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	Pong
74		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	Pong
75		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	Pong
76		Front of Apt#910	Dry Chemical	1	✓		2-Jul-25	Pong
77		Beside Apt#917	Dry Chemical	1	✓		2-Jul-25	Pong
78	10	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
79		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
80		Beside Apt#1001	Dry Chemical	1	✓		2-Jul-25	A
81		Beside Apt#1017	Dry Chemical	1	✓		2-Jul-25	A
82		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
83		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
84	11	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
85		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
86		Beside Apt#1101	Dry Chemical	1	✓		2-Jul-25	A
87		Beside Apt#1117	Dry Chemical	1	✓		2-Jul-25	A
88		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
89		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
90	12	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
91		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
92		Beside Apt#1201	Dry Chemical	1		✗	2-Jul-25	A
93		Beside Apt#1217	Dry Chemical	1		✗	2-Jul-25	A
94		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
95		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
96	13	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
97		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
98		Beside Apt#1301	Dry Chemical	1	✓		2-Jul-25	A
99		Beside Apt#1317	Dry Chemical	1	✓		2-Jul-25	A
100		FHC - beside ST-1	Dry Chemical	1		✗	2-Jul-25	A
101		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
102	14	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
103		Front of Guest Lift	Dry Chemical	1		✗	2-Jul-25	A
104		Beside Apt#1401	Dry Chemical	1	✓		2-Jul-25	A
105		Beside Apt#1417	Dry Chemical	1		✗	2-Jul-25	A
106		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
107		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
108	15	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
109		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
110		Beside Apt#1501	Dry Chemical	1	✓		2-Jul-25	A
111		Beside Apt#1517	Dry Chemical	1	✓		2-Jul-25	A
111		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
112		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A

113	16	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
114		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
115		Beside Apt#1601	Dry Chemical	1	✓		2-Jul-25	A
116		Beside Apt#1617	Dry Chemical	1	✓		2-Jul-25	A
117		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
118		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
119	17	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
120		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
121		Beside Apt#1701	Dry Chemical	1	✓		2-Jul-25	A
122		Beside Apt#1717	Dry Chemical	1	✓		2-Jul-25	A
123		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
124		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
125	18	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
126		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
127		Beside Apt#1801	Dry Chemical	1	✓		2-Jul-25	A
128		Beside Apt#1817	Dry Chemical	1	✓		2-Jul-25	A
129		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
130		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
131	19	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
132		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
133		Beside Apt#1901	Dry Chemical	1	✓		2-Jul-25	A
134		Beside Apt#1917	Dry Chemical	1	✓		2-Jul-25	A
135		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
136		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
137	20	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
138		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
139		Beside Apt#2001	Dry Chemical	1	✓		2-Jul-25	A
140		Beside Apt#2017	Dry Chemical	1	✓		2-Jul-25	A
141		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
142		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
143	21	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
144		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
145		Beside Apt#2101	Dry Chemical	1	✓		2-Jul-25	A
146		Beside Apt#2117	Dry Chemical	1	✓		2-Jul-25	A
147		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
148		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
149	22	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
150		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
151		Beside Apt#2201	Dry Chemical	1	✓		2-Jul-25	A
152		Beside Apt#2217	Dry Chemical	1	✓		2-Jul-25	A
153		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
154		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
155	23	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
156		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
157		Beside Apt#2301	Dry Chemical	1	✓		2-Jul-25	A
158		Beside Apt#2317	Dry Chemical	1	✓		2-Jul-25	A
159		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
160		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
161	24	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
162		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
163		Beside Apt#2401	Dry Chemical	1	✓		2-Jul-25	A
164		Beside Apt#2415	Dry Chemical	1	✓		2-Jul-25	A
165		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
166		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
167	25	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
168		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
169		Beside Apt#2501	Dry Chemical	1	✓		2-Jul-25	A
170		Beside Apt#2517	Dry Chemical	1	✓		2-Jul-25	A
171		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
172		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A

173	26	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
174		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
175		Beside Apt#2601	Dry Chemical	1	✓		2-Jul-25	A
176		Beside Apt#2615	Dry Chemical	1	✓		2-Jul-25	A
177		FHC - beside ST-1	Dry Chemical	1	✓		2-Jul-25	A
178		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
179	27	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
180		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
181		FHC - Sky Garden	Dry Chemical	1	✓		2-Jul-25	A
182		Beside Apt#2710	Dry Chemical	1	✓		2-Jul-25	A
183		Beside Apt#2715	Dry Chemical	1	✓		2-Jul-25	A
184		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
185	28	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
186		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
187		Beside Apt#2809	Dry Chemical	1	✓		2-Jul-25	A
188		Beside Apt#2815	Dry Chemical	1	✓		2-Jul-25	A
189		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
190	29	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
191		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
192		Beside Apt#2909	Dry Chemical	1	✓		2-Jul-25	A
193		Beside Apt#2915	Dry Chemical	1	✓		2-Jul-25	A
194		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
195	30	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
196		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
197		Beside Apt#3009	Dry Chemical	1	✓		2-Jul-25	A
198		Beside Apt#3015	Dry Chemical	1	✓		2-Jul-25	A
199		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
200	31	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
201		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
202		Beside Apt#3109	Dry Chemical	1	✓		2-Jul-25	A
203		Beside Apt#3115	Dry Chemical	1	✓		2-Jul-25	A
204		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
205	32	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
206		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
207		Beside Apt#3209	Dry Chemical	1	✓		2-Jul-25	A
208		Beside Apt#3215	Dry Chemical	1	✓		2-Jul-25	A
209		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
210	33	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
211		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
212		Beside Apt#3309	Dry Chemical	1	✓		2-Jul-25	A
213		Beside Apt#3315	Dry Chemical	1	✓		2-Jul-25	A
214		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
215	34	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
216		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
217		Beside Apt#3409	Dry Chemical	1	✓		2-Jul-25	A
218		Beside Apt#3415	Dry Chemical	1	✓		2-Jul-25	A
219		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
220	35	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Jul-25	A
221		Front of Guest Lift	Dry Chemical	1	✓		2-Jul-25	A
222		Beside Apt#3509	Dry Chemical	1	✓		2-Jul-25	A
223		Beside Apt#3515	Dry Chemical	1	✓		2-Jul-25	A
224		FHC - beside ST-2	Dry Chemical	1	✓		2-Jul-25	A
225	36	FHC-Roof-ST-1	Dry Chemical	1	✓		2-Jul-25	A
226		FHC-Roof-ST-2	Dry Chemical	1	✓		2-Jul-25	A

Total	237
-------	-----

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Normal	Out of Service		
1	231	Dry Chemical (10 lbs)	225	6		Recharge (ส่งเติมกับอำนวยการ)
2	44	CO2	43	1		น้ำนักด้าเกณฑ์ (ใช้เทรนนิ่ง)
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	445	0		
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	6	0		
Tatal	754		747	7		

Reported by: Security team
20/07/2025

Acknowledged by: Security Manager

Fire Extinguisher Report of August 2025

No.	Floor	Location	Type	Total	Status		Check date	Remark
					Yes	No		
1	B	Security Store	ADE 2000	4	✓		1-Aug-25	Stone
2	B	Electrical Room	ADE 2000	1	✓		1-Aug-25	Stone
3	B	Engineering Workshop	ADE 2000	2	✓		1-Aug-25	Stone
4	B	Engineering Store	ADE 2000	1	✓		6-Aug-25	Stone
5	B	Chemical Room	ADE 2000	2	✓		1-Aug-25	Stone
6	B	Houskeeping Store	ADE 2000	1	✓		6-Aug-25	Big
7	B	Houskeeping Office	ADE 2000	1	✓		1-Aug-25	Stone
8	B	FCC Room	ADE 2000	1	✓		1-Aug-25	Stone
9	B	Fire Pump Room	ADE 2000	2	✓		1-Aug-25	Stone
10	B	Finance Accounting Office	ADE 2000	1	✓		1-Aug-25	Stone
11	B	Staff Canteen Room	ADE 2000	1	✓		2-Aug-25	Big
12	G	MDB and Generator	ADE 2000	2	✓		1-Aug-25	Stone
13	G	Server Room	ADE 2000	2	✓		1-Aug-25	Stone
14	G	Guest Service Office	ADE 2000	1	✓		1-Aug-25	Stone
15	G	Executive Office	ADE 2000	1	✓		1-Aug-25	Stone
16	R	Control lift Rooftop	ADE 2000	1	✓		6-Aug-25	Big
Total				24				

CO2

1	B	Fire Cart	CO2	1	✓		1-Aug-25	Stone
2		FCC Room	CO2	1	✓		1-Aug-25	Stone
3		Security Store	CO2	10	✓		1-Aug-25	Stone
4	G	Server Room	CO2	1	✓		1-Aug-25	Stone
5		FHC - Front of Saver Room	CO2	1	✓		1-Aug-25	Stone
6	2	Rama 9 Sound Control Room	CO2	1	✓		6-Aug-25	Saksith
7	8	E & E Room	CO2	1	✓		3-Aug-25	Somchai
8	9	E & E Room	CO2	1	✓		3-Aug-25	Somchai
9	10	E & E Room	CO2	1	✓		3-Aug-25	Somchai
10	11	E & E Room	CO2	1	✓		3-Aug-25	Somchai
11	12	E & E Room	CO2	1	✓		3-Aug-25	Somchai
12	13	E & E Room	CO2	1	✓		3-Aug-25	Somchai
13	14	E & E Room	CO2	1	✓		3-Aug-25	Somchai
14	15	E & E Room	CO2	1	✓		3-Aug-25	Somchai
15	16	E & E Room	CO2	1	✓		3-Aug-25	Somchai
16	17	E & E Room	CO2	1	✓		3-Aug-25	Somchai
17	18	E & E Room	CO2	1	✓		3-Aug-25	Somchai
18	19	E & E Room	CO2	1	✓		3-Aug-25	Somchai
19	20	E & E Room	CO2	1	✓		3-Aug-25	Somchai
20	21	E & E Room	CO2	1	✓		3-Aug-25	Somchai
21	22	E & E Room	CO2	1	✓		3-Aug-25	Somchai
22	23	E & E Room	CO2	1	✓		3-Aug-25	Somchai
23	24	E & E Room	CO2	1	✓		3-Aug-25	Somchai
24	25	E & E Room	CO2	1	✓		3-Aug-25	Somchai
25	26	E & E Room	CO2	1	✓		3-Aug-25	Somchai
26	27	E & E Room	CO2	1	✓		3-Aug-25	Somchai
27	28	E & E Room	CO2	1	✓		3-Aug-25	Somchai
28	29	E & E Room	CO2	1	✓		3-Aug-25	Somchai
29	30	E & E Room	CO2	1	✓		3-Aug-25	Somchai
30	31	E & E Room	CO2	1	✓		3-Aug-25	Somchai
31	32	E & E Room	CO2	1	✓		3-Aug-25	Somchai
32	33	E & E Room	CO2	1	✓		3-Aug-25	Somchai
33	34	E & E Room	CO2	1	✓		3-Aug-25	Somchai
34	35	E & E Room	CO2	1	✓		3-Aug-25	Somchai
35	36	Front of Control lift room	CO2	1	✓		3-Aug-25	Somchai
Total				44				

Dry Chemical								
No.	Floor	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Aug-25	Stone
2		FHC - Front of FCC	Dry Chemical	1	✓		1-Aug-25	Stone
3		Gas Station (15 lbs)	Dry Chemical	2	✓		1-Aug-25	Stone
4		Front of Garbage Room	Dry Chemical	1	✓		1-Aug-25	Stone
5		Front of Housekeeping Store	Dry Chemical	1	✓		1-Aug-25	Stone
6		Fire Cart	Dry Chemical	1	✓		1-Aug-25	Overcharg
7		Security Store	Dry Chemical	6	✓		1-Aug-25	Stone
8		Fire Pump Room	Dry Chemical	1	✓		1-Aug-25	Stone
9		Front of Timekeeper	Dry Chemical	1	✓		1-Aug-25	Recharge
10	G	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Aug-25	Stone
11		FHC - Front ST-2	Dry Chemical	1	✓		1-Aug-25	Overcharg
12	2	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Aug-25	Stone
13		Front of First aid Room	Dry Chemical	1	✓		6-Aug-25	Saksith
14		Front of HK Store (Outsource)	Dry Chemical	1	✓		6-Aug-25	Saksith
15		FHC - Front of ST-1	Dry Chemical	1	✓		1-Aug-25	Stone
16		FHC - Front of ST-2	Dry Chemical	1	✓		6-Aug-25	Saksith
17	3	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Aug-25	Overcharg
18		Front of Guest Lift	Dry Chemical	1	✓		1-Aug-25	Overcharg
19		FHC - Front of ST-1	Dry Chemical	1	✓		1-Aug-25	Recharge
20		Parking Area Zone 4B	Dry Chemical	1	✓		1-Aug-25	Overcharg
21		FHC - Front of ST-2	Dry Chemical	1	✓		1-Aug-25	Overcharg
22		Parking Area Zone 2A	Dry Chemical	1	✓		1-Aug-25	Overcharg
23	4	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Aug-25	Overcharg
24		Front of Guest Lift	Dry Chemical	1	✓		1-Aug-25	Overcharg
25		FHC - Front of ST-1	Dry Chemical	1	✓		1-Aug-25	Overcharg
26		Parking Area Zone 4B	Dry Chemical	1	✓		1-Aug-25	Overcharg
27		FHC - Front of ST-2	Dry Chemical	1	✓		1-Aug-25	Recharge
28		Parking Area Zone 2A	Dry Chemical	1	✓		1-Aug-25	Overcharg
29		Parking Area Zone 8A	Dry Chemical	1	✓		1-Aug-25	Overcharg
30		Parking Area Zone C	Dry Chemical	1	✓		1-Aug-25	Overcharg
31	5	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Aug-25	Overcharg
32		Front of Guest Lift	Dry Chemical	1	✓		1-Aug-25	Recharge
33		FHC - Front of ST-1	Dry Chemical	1	✓		1-Aug-25	Stone
34		Parking Area Zone 4B	Dry Chemical	1	✓		1-Aug-25	Stone
35		FHC - Front of ST-2	Dry Chemical	1	✓		1-Aug-25	Stone
36		Parking Area Zone 2A	Dry Chemical	1	✓		1-Aug-25	Recharge
37		Parking Area Zone 8A	Dry Chemical	1	✓		1-Aug-25	Overcharg
38		Parking Area Zone C	Dry Chemical	1	✓		1-Aug-25	Recharge
39	6	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Aug-25	Stone
40		Front of Guest Lift	Dry Chemical	1	✓		1-Aug-25	Stone
41		FHC - Front of ST-1	Dry Chemical	1	✓		1-Aug-25	Stone
42		Parking Area Zone 4B	Dry Chemical	1	✓		1-Aug-25	Stone
43		Inside ST-2	Dry Chemical	1	✓		1-Aug-25	Stone
44		FHC - Front of ST-2	Dry Chemical	1	✓		1-Aug-25	Stone
45		Parking Area Zone 2A	Dry Chemical	1	✓		1-Aug-25	Stone
46		Parking Area Zone 8A	Dry Chemical	1	✓		1-Aug-25	Stone
47		Parking Area Zone C	Dry Chemical	1	✓		1-Aug-25	Recharge
48	7	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Aug-25	Stone
49		Front of Guest Lift	Dry Chemical	1	✓		1-Aug-25	Recharge
50		FHC - Front of ST-1	Dry Chemical	1	✓		1-Aug-25	Overcharg
51		Parking Area Zone 4B	Dry Chemical	1	✓		1-Aug-25	Stone
52		Inside ST-2	Dry Chemical	1	✓		1-Aug-25	Overcharg
53		FHC - Front of ST-2	Dry Chemical	1	✓		1-Aug-25	Stone
54		Parking Area Zone 2A	Dry Chemical	1	✓		1-Aug-25	Overcharg
55		Parking Area Zone 8A	Dry Chemical	1	✓		1-Aug-25	Stone
56		Parking Area Zone C	Dry Chemical	1	✓		1-Aug-25	Overcharg

57	7M	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Aug-25	Stone
58		Front of Guest Lift	Dry Chemical	1	✓		1-Aug-25	Stone
59		Pool Pump Room	Dry Chemical	1	✓		1-Aug-25	Stone
60		Front of Pump room	Dry Chemical	1	✓		1-Aug-25	Stone
61		Parking Area Zone A	Dry Chemical	1	✓		1-Aug-25	Stone
62		FHC - Front of ST-1	Dry Chemical	1	✓		1-Aug-25	Overcharge
63		Parking Area Zone 2A	Dry Chemical	1	✓		1-Aug-25	Overcharge
64		FHC - Inside ST-2	Dry Chemical	1	✓		1-Aug-25	Stone
65		Inside ST-2	Dry Chemical	1	✓		1-Aug-25	Stone
66	8	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
67		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	Recharge
68		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	Overcharge
69		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	Recharge
70		Front of Apt#810	Dry Chemical	1	✓		02-Aug-2025	Overcharge
71		Beside Apt#817	Dry Chemical	1	✓		02-Aug-2025	Overcharge
72	9	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
73		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	A
74		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	Overcharge
75		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	Overcharge
76		Front of Apt#910	Dry Chemical	1	✓		02-Aug-2025	Overcharge
77		Beside Apt#917	Dry Chemical	1	✓		02-Aug-2025	Overcharge
78	10	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
79		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
80		Beside Apt#1001	Dry Chemical	1	✓		02-Aug-2025	Overcharge
81		Beside Apt#1017	Dry Chemical	1	✓		02-Aug-2025	A
82		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	A
83		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	A
84	11	FHC - Front of Service Lift	Dry Chemical	1	✓		03-Aug-2025	Recharge
85		Front of Guest Lift	Dry Chemical	1	✓		03-Aug-2025	Overcharge
86		Beside Apt#1101	Dry Chemical	1	✓		03-Aug-2025	A
87		Beside Apt#1117	Dry Chemical	1	✓		03-Aug-2025	Overcharge
88		FHC - beside ST-1	Dry Chemical	1	✓		03-Aug-2025	Overcharge
89		FHC - beside ST-2	Dry Chemical	1	✓		03-Aug-2025	Recharge
90	12	FHC - Front of Service Lift	Dry Chemical	1	✓		03-Aug-2025	A
91		Front of Guest Lift	Dry Chemical	1	✓		03-Aug-2025	Overcharge
92		Beside Apt#1201	Dry Chemical	1	✓		03-Aug-2025	Recharge
93		Beside Apt#1217	Dry Chemical	1	✓		03-Aug-2025	Overcharge
94		FHC - beside ST-1	Dry Chemical	1	✓		03-Aug-2025	Overcharge
95		FHC - beside ST-2	Dry Chemical	1	✓		03-Aug-2025	A
96	13	FHC - Front of Service Lift	Dry Chemical	1	✓		03-Aug-2025	Overcharge
97		Front of Guest Lift	Dry Chemical	1	✓		03-Aug-2025	Overcharge
98		Beside Apt#1301	Dry Chemical	1	✓		03-Aug-2025	Overcharge
99		Beside Apt#1317	Dry Chemical	1	✓		03-Aug-2025	Overcharge
100		FHC - beside ST-1	Dry Chemical	1		✗	03-Aug-2025	Recharge
101		FHC - beside ST-2	Dry Chemical	1	✓		03-Aug-2025	Overcharge
102	14	FHC - Front of Service Lift	Dry Chemical	1	✓		03-Aug-2025	Overcharge
103		Front of Guest Lift	Dry Chemical	1	✓		03-Aug-2025	Recharge
104		Beside Apt#1401	Dry Chemical	1	✓		03-Aug-2025	Overcharge
105		Beside Apt#1417	Dry Chemical	1		✗	03-Aug-2025	Recharge
106		FHC - beside ST-1	Dry Chemical	1	✓		03-Aug-2025	Recharge
107		FHC - beside ST-2	Dry Chemical	1	✓		03-Aug-2025	Overcharge
108	15	FHC - Front of Service Lift	Dry Chemical	1	✓		03-Aug-2025	Overcharge
109		Front of Guest Lift	Dry Chemical	1	✓		03-Aug-2025	Overcharge
110		Beside Apt#1501	Dry Chemical	1	✓		03-Aug-2025	Recharge
111		Beside Apt#1517	Dry Chemical	1	✓		03-Aug-2025	Overcharge
111		FHC - beside ST-1	Dry Chemical	1	✓		03-Aug-2025	Overcharge
112		FHC - beside ST-2	Dry Chemical	1	✓		03-Aug-2025	Overcharge

113	16	FHC - Front of Service Lift	Dry Chemical	1	✓		03-Aug-2025	Overcharge
114		Front of Guest Lift	Dry Chemical	1	✓		03-Aug-2025	Recharge
115		Beside Apt#1601	Dry Chemical	1	✓		03-Aug-2025	Overcharge
116		Beside Apt#1617	Dry Chemical	1	✓		03-Aug-2025	Overcharge
117		FHC - beside ST-1	Dry Chemical	1	✓		03-Aug-2025	Overcharge
118		FHC - beside ST-2	Dry Chemical	1	✓		03-Aug-2025	A
119	17	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
120		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
121		Beside Apt#1701	Dry Chemical	1	✓		02-Aug-2025	Overcharge
122		Beside Apt#1717	Dry Chemical	1	✓		02-Aug-2025	Recharge
123		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	A
124		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	Overcharge
125	18	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
126		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	A
127		Beside Apt#1801	Dry Chemical	1	✓		02-Aug-2025	Overcharge
128		Beside Apt#1817	Dry Chemical	1	✓		02-Aug-2025	Overcharge
129		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	A
130		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	A
131	19	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
132		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	A
133		Beside Apt#1901	Dry Chemical	1	✓		02-Aug-2025	A
134		Beside Apt#1917	Dry Chemical	1	✓		02-Aug-2025	Overcharge
135		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	Overcharge
136		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	A
137	20	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	Recharge
138		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
139		Beside Apt#2001	Dry Chemical	1	✓		02-Aug-2025	A
140		Beside Apt#2017	Dry Chemical	1	✓		02-Aug-2025	Overcharge
141		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	A
142		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	Overcharge
143	21	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
144		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
145		Beside Apt#2101	Dry Chemical	1	✓		02-Aug-2025	Overcharge
146		Beside Apt#2117	Dry Chemical	1	✓		02-Aug-2025	Overcharge
147		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	Overcharge
148		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	A
149	22	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	A
150		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
151		Beside Apt#2201	Dry Chemical	1	✓		02-Aug-2025	Overcharge
152		Beside Apt#2217	Dry Chemical	1	✓		02-Aug-2025	Overcharge
153		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	Overcharge
154		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	Overcharge
155	23	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	A
156		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	Overcharge
157		Beside Apt#2301	Dry Chemical	1	✓		02-Aug-2025	Overcharge
158		Beside Apt#2317	Dry Chemical	1	✓		02-Aug-2025	Overcharge
159		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	Overcharge
160		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	Overcharge
161	24	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	A
162		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	A
163		Beside Apt#2401	Dry Chemical	1	✓		02-Aug-2025	Overcharge
164		Beside Apt#2415	Dry Chemical	1	✓		02-Aug-2025	A
165		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	A
166		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	A
167	25	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	A
168		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	A
169		Beside Apt#2501	Dry Chemical	1	✓		02-Aug-2025	A
170		Beside Apt#2517	Dry Chemical	1	✓		02-Aug-2025	A
171		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	A
172		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	A

173	26	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	A
174		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	A
175		Beside Apt#2601	Dry Chemical	1	✓		02-Aug-2025	A
176		Beside Apt#2615	Dry Chemical	1	✓		02-Aug-2025	Overcharge
177		FHC - beside ST-1	Dry Chemical	1	✓		02-Aug-2025	A
178		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	A
179	27	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	A
180		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	A
181		FHC - Sky Garden	Dry Chemical	1	✓		02-Aug-2025	A
182		Beside Apt#2710	Dry Chemical	1	✓		02-Aug-2025	A
183		Beside Apt#2715	Dry Chemical	1	✓		02-Aug-2025	A
184		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	A
185	28	FHC - Front of Service Lift	Dry Chemical	1	✓		02-Aug-2025	A
186		Front of Guest Lift	Dry Chemical	1	✓		02-Aug-2025	A
187		Beside Apt#2809	Dry Chemical	1	✓		02-Aug-2025	A
188		Beside Apt#2815	Dry Chemical	1	✓		02-Aug-2025	A
189		FHC - beside ST-2	Dry Chemical	1	✓		02-Aug-2025	Overcharge
190	29	FHC - Front of Service Lift	Dry Chemical	1	✓		01-Aug-2025	A
191		Front of Guest Lift	Dry Chemical	1	✓		01-Aug-2025	A
192		Beside Apt#2909	Dry Chemical	1	✓		01-Aug-2025	A
193		Beside Apt#2915	Dry Chemical	1	✓		01-Aug-2025	A
194		FHC - beside ST-2	Dry Chemical	1	✓		01-Aug-2025	Recharge
195	30	FHC - Front of Service Lift	Dry Chemical	1	✓		01-Aug-2025	A
196		Front of Guest Lift	Dry Chemical	1	✓		01-Aug-2025	A
197		Beside Apt#3009	Dry Chemical	1	✓		01-Aug-2025	Overcharge
198		Beside Apt#3015	Dry Chemical	1	✓		01-Aug-2025	A
199		FHC - beside ST-2	Dry Chemical	1	✓		01-Aug-2025	Recharge
200	31	FHC - Front of Service Lift	Dry Chemical	1	✓		01-Aug-2025	A
201		Front of Guest Lift	Dry Chemical	1	✓		01-Aug-2025	A
202		Beside Apt#3109	Dry Chemical	1	✓		01-Aug-2025	A
203		Beside Apt#3115	Dry Chemical	1	✓		01-Aug-2025	A
204		FHC - beside ST-2	Dry Chemical	1	✓		01-Aug-2025	A
205	32	FHC - Front of Service Lift	Dry Chemical	1	✓		01-Aug-2025	A
206		Front of Guest Lift	Dry Chemical	1	✓		01-Aug-2025	A
207		Beside Apt#3209	Dry Chemical	1	✓		01-Aug-2025	A
208		Beside Apt#3215	Dry Chemical	1	✓		01-Aug-2025	A
209		FHC - beside ST-2	Dry Chemical	1	✓		01-Aug-2025	A
210	33	FHC - Front of Service Lift	Dry Chemical	1	✓		01-Aug-2025	A
211		Front of Guest Lift	Dry Chemical	1	✓		01-Aug-2025	A
212		Beside Apt#3309	Dry Chemical	1	✓		01-Aug-2025	A
213		Beside Apt#3315	Dry Chemical	1	✓		01-Aug-2025	A
214		FHC - beside ST-2	Dry Chemical	1	✓		01-Aug-2025	The screen looks hazy
215	34	FHC - Front of Service Lift	Dry Chemical	1	✓		01-Aug-2025	A
216		Front of Guest Lift	Dry Chemical	1	✓		01-Aug-2025	A
217		Beside Apt#3409	Dry Chemical	1	✓		01-Aug-2025	A
218		Beside Apt#3415	Dry Chemical	1	✓		01-Aug-2025	A
219		FHC - beside ST-2	Dry Chemical	1	✓		01-Aug-2025	A
220	35	FHC - Front of Service Lift	Dry Chemical	1	✓		01-Aug-2025	A
221		Front of Guest Lift	Dry Chemical	1	✓		01-Aug-2025	A
222		Beside Apt#3509	Dry Chemical	1	✓		01-Aug-2025	A
223		Beside Apt#3515	Dry Chemical	1	✓		01-Aug-2025	Recharge
224		FHC - beside ST-2	Dry Chemical	1	✓		01-Aug-2025	A
225	36	FHC-Roof-ST-1	Dry Chemical	1	✓		01-Aug-2025	A
226		FHC-Roof-ST-2	Dry Chemical	1	✓		01-Aug-2025	A
			Total	233				

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Normal	Out of Service		
1	231	Dry Chemical (10 lbs)	230	1		Recharge (ส่งเติมกับอำนวยการ)
2	44	CO2	43	1		น้ำหนัลด้าเกณฑ์ (ใช้เทรนนิ่ง)
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	445	0		
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	6	0		
Total	754		752	2		

Reported by: Security team
23/08/2025

Acknowledged by: _____
Security Manager

No.	Floor	Location	Type	Total	Status		Check date	Remark
					Yes	No		
1	B	Security Store	ADE 2000	4	✓		3-Sep-25	Big
2	B	Electrical Room	ADE 2000	1	✓		3-Sep-25	Big
3	B	Engineering Workshop	ADE 2000	2	✓		3-Sep-25	Big
4	B	Engineering Store	ADE 2000	1	✓		4-Sep-25	Big
5	B	Chemical Room	ADE 2000	2	✓		3-Sep-25	Big
6	B	Houskeeping Store	ADE 2000	1	✓		3-Sep-25	Big
7	B	Houskeeping Office	ADE 2000	1	✓		3-Sep-25	Big
8	B	FCC Room	ADE 2000	1	✓		3-Sep-25	Big
9	B	Fire Pump Room	ADE 2000	2	✓		3-Sep-25	Big
10	B	Finance Accounting Office	ADE 2000	1	✓		3-Sep-25	Big
11	B	Staff Canteen Room	ADE 2000	1	✓		3-Sep-25	Big
12	G	MDB and Generator	ADE 2000	2	✓		3-Sep-25	Big
13	G	Server Room	ADE 2000	2	✓		3-Sep-25	Big
14	G	Guest Service Office	ADE 2000	1	✓		3-Sep-25	Big
15	G	Executive Office	ADE 2000	1	✓		4-Sep-25	Big
16	R	Control lift Rooftop	ADE 2000	1	✓		4-Sep-25	Chai
Total				24				

CO2

1	B	Fire Cart	CO2	1	✓		3-Sep-25	Big
2		FCC Room	CO2	1	✓		3-Sep-25	Big
3		Security Store	CO2	10	✓		3-Sep-25	Stone
4	G	Server Room	CO2	1	✓		3-Sep-25	Big
5		FHC - Front of Saver Room	CO2	1	✓		3-Sep-25	Big
6	2	Rama 9 Sound Control Room	CO2	1	✓		3-Sep-25	Big
7	8	E & E Room	CO2	1	✓		4-Sep-25	Big
8	9	E & E Room	CO2	1	✓		4-Sep-25	Big
9	10	E & E Room	CO2	1	✓		3-Sep-25	Chai
10	11	E & E Room	CO2	1	✓		3-Sep-25	Chai
11	12	E & E Room	CO2	1	✓		3-Sep-25	Chai
12	13	E & E Room	CO2	1	✓		3-Sep-25	Chai
13	14	E & E Room	CO2	1	✓		3-Sep-25	Chai
14	15	E & E Room	CO2	1	✓		3-Sep-25	Chai
15	16	E & E Room	CO2	1	✓		3-Sep-25	Chai
16	17	E & E Room	CO2	1	✓		3-Sep-25	Chai
17	18	E & E Room	CO2	1	✓		3-Sep-25	Chai
18	19	E & E Room	CO2	1	✓		3-Sep-25	Chai
19	20	E & E Room	CO2	1	✓		3-Sep-25	Chai
20	21	E & E Room	CO2	1	✓		3-Sep-25	Chai
21	22	E & E Room	CO2	1	✓		3-Sep-25	Chai
22	23	E & E Room	CO2	1	✓		3-Sep-25	Chai
23	24	E & E Room	CO2	1	✓		3-Sep-25	Chai
24	25	E & E Room	CO2	1	✓		3-Sep-25	Chai
25	26	E & E Room	CO2	1	✓		3-Sep-25	Chai
26	27	E & E Room	CO2	1	✓		3-Sep-25	Chai
27	28	E & E Room	CO2	1	✓		3-Sep-25	Chai
28	29	E & E Room	CO2	1	✓		3-Sep-25	Chai
29	30	E & E Room	CO2	1	✓		3-Sep-25	Chai
30	31	E & E Room	CO2	1	✓		3-Sep-25	Chai
31	32	E & E Room	CO2	1	✓		3-Sep-25	Chai
32	33	E & E Room	CO2	1	✓		1-Sep-25	Big
33	34	E & E Room	CO2	1	✓		1-Sep-25	Big
34	35	E & E Room	CO2	1	✓		1-Sep-25	Big
35	36	Front of Control lift room	CO2	1	✓		3-Sep-25	Big
Total				44				

Dry Chemical								
No.	Floor	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry Chemical	1	✓		3-Sep-25	Big
2		FHC - Front of FCC	Dry Chemical	1	✓		3-Sep-25	Big
3		Gas Station (15 lbs)	Dry Chemical	2	✓		3-Sep-25	Big
4		Front of Garbage Room	Dry Chemical	1	✓		3-Sep-25	Big
5		Front of Housekeeping Store	Dry Chemical	1	✓		3-Sep-25	Big
6		Fire Cart	Dry Chemical	1	✓		3-Sep-25	Big
7		Security Store	Dry Chemical	6	✓		3-Sep-25	Stone
8		Fire Pump Room	Dry Chemical	1	✓		3-Sep-25	Big
9		Front of Timekeeper	Dry Chemical	1	✓		3-Sep-25	Big
10	G	FHC - Front of Service Lift	Dry Chemical	1	✓		3-Sep-25	Big
11		FHC - Front ST-2	Dry Chemical	1	✓		3-Sep-25	Big
12	2	FHC - Front of Service Lift	Dry Chemical	1	✓		3-Sep-25	Big
13		Front of First aid Room	Dry Chemical	1	✓		3-Sep-25	Big
14		Front of HK Store (Outsource)	Dry Chemical	1	✓		3-Sep-25	Big
15		FHC - Front of ST-1	Dry Chemical	1	✓		3-Sep-25	Big
16		FHC - Front of ST-2	Dry Chemical	1	✓		3-Sep-25	Big
17	3	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
18		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
19		FHC - Front of ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
20		Parking Area Zone 4B	Dry Chemical	1	✓		2-Sep-25	Chai
21		FHC - Front of ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
22		Parking Area Zone 2A	Dry Chemical	1	✓		2-Sep-25	Chai
23	4	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
24		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
25		FHC - Front of ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
26		Parking Area Zone 4B	Dry Chemical	1	✓		2-Sep-25	Chai
27		FHC - Front of ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
28		Parking Area Zone 2A	Dry Chemical	1	✓		2-Sep-25	Chai
29		Parking Area Zone 8A	Dry Chemical	1	✓		2-Sep-25	Chai
30		Parking Area Zone C	Dry Chemical	1	✓		2-Sep-25	Chai
31	5	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
32		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
33		FHC - Front of ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
34		Parking Area Zone 4B	Dry Chemical	1	✓		2-Sep-25	Chai
35		FHC - Front of ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
36		Parking Area Zone 2A	Dry Chemical	1	✓		2-Sep-25	Chai
37		Parking Area Zone 8A	Dry Chemical	1	✓		2-Sep-25	Chai
38		Parking Area Zone C	Dry Chemical	1	✓		2-Sep-25	Chai
39	6	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
40		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
41		FHC - Front of ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
42		Parking Area Zone 4B	Dry Chemical	1	✓		2-Sep-25	Chai
43		Inside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
44		FHC - Front of ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
45		Parking Area Zone 2A	Dry Chemical	1	✓		2-Sep-25	Chai
46		Parking Area Zone 8A	Dry Chemical	1	✓		2-Sep-25	Chai
47		Parking Area Zone C	Dry Chemical	1	✓		2-Sep-25	Chai
48	7	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
49		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
50		FHC - Front of ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
51		Parking Area Zone 4B	Dry Chemical	1	✓		2-Sep-25	Chai
52		Inside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
53		FHC - Front of ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
54		Parking Area Zone 2A	Dry Chemical	1	✓		2-Sep-25	Chai
55		Parking Area Zone 8A	Dry Chemical	1	✓		2-Sep-25	Chai
56		Parking Area Zone C	Dry Chemical	1	✓		2-Sep-25	Chai

57	7M	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
58		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
59		Pool Pump Room	Dry Chemical	1	✓		4-Sep-25	Big
60		Front of Pump room	Dry Chemical	1	✓		2-Sep-25	Chai
61		Parking Area Zone A	Dry Chemical	1	✓		2-Sep-25	Chai
62		FHC - Front of ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
63		Parking Area Zone 2A	Dry Chemical	1	✓		2-Sep-25	Chai
64		FHC - Inside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
65		Inside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
66	8	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
67		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
68		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
69		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
70		Front of Apt#810	Dry Chemical	1	✓		2-Sep-25	Chai
71		Beside Apt#817	Dry Chemical	1	✓		2-Sep-25	Chai
72	9	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
73		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
74		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
75		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
76		Front of Apt#910	Dry Chemical	1	✓		2-Sep-25	Chai
77		Beside Apt#917	Dry Chemical	1	✓		2-Sep-25	Chai
78	10	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
79		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
80		Beside Apt#1001	Dry Chemical	1	✓		2-Sep-25	Chai
81		Beside Apt#1017	Dry Chemical	1	✓		2-Sep-25	Chai
82		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
83		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
84	11	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
85		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
86		Beside Apt#1101	Dry Chemical	1	✓		2-Sep-25	Chai
87		Beside Apt#1117	Dry Chemical	1	✓		2-Sep-25	Chai
88		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
89		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
90	12	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
91		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
92		Beside Apt#1201	Dry Chemical	1	✓		2-Sep-25	Chai
93		Beside Apt#1217	Dry Chemical	1	✓		2-Sep-25	Chai
94		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
95		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
96	13	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
97		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
98		Beside Apt#1301	Dry Chemical	1	✓		2-Sep-25	Chai
99		Beside Apt#1317	Dry Chemical	1	✓		2-Sep-25	Chai
100		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
101		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
102	14	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
103		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
104		Beside Apt#1401	Dry Chemical	1	✓		2-Sep-25	Chai
105		Beside Apt#1417	Dry Chemical	1	✓		2-Sep-25	Chai
106		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
107		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
108	15	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
109		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
110		Beside Apt#1501	Dry Chemical	1	✓		2-Sep-25	Chai
111		Beside Apt#1517	Dry Chemical	1	✓		2-Sep-25	Chai
111		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
112		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai

113	16	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
114		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
115		Beside Apt#1601	Dry Chemical	1	✓		2-Sep-25	Chai
116		Beside Apt#1617	Dry Chemical	1	✓		2-Sep-25	Chai
117		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
118		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
119	17	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
120		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
121		Beside Apt#1701	Dry Chemical	1	✓		2-Sep-25	Chai
122		Beside Apt#1717	Dry Chemical	1	✓		2-Sep-25	Chai
123		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
124		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
125	18	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
126		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
127		Beside Apt#1801	Dry Chemical	1	✓		2-Sep-25	Chai
128		Beside Apt#1817	Dry Chemical	1	✓		2-Sep-25	Chai
129		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
130		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
131	19	FHC - Front of Service Lift	Dry Chemical	1	✓		2-Sep-25	Chai
132		Front of Guest Lift	Dry Chemical	1	✓		2-Sep-25	Chai
133		Beside Apt#1901	Dry Chemical	1	✓		2-Sep-25	Chai
134		Beside Apt#1917	Dry Chemical	1	✓		2-Sep-25	Chai
135		FHC - beside ST-1	Dry Chemical	1	✓		2-Sep-25	Chai
136		FHC - beside ST-2	Dry Chemical	1	✓		2-Sep-25	Chai
137	20	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
138		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
139		Beside Apt#2001	Dry Chemical	1	✓		1-Sep-25	Big
140		Beside Apt#2017	Dry Chemical	1	✓		1-Sep-25	Big
141		FHC - beside ST-1	Dry Chemical	1	✓		1-Sep-25	Big
142		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
143	21	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
144		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
145		Beside Apt#2101	Dry Chemical	1	✓		1-Sep-25	Big
146		Beside Apt#2117	Dry Chemical	1	✓		1-Sep-25	Big
147		FHC - beside ST-1	Dry Chemical	1	✓		1-Sep-25	Big
148		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
149	22	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
150		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
151		Beside Apt#2201	Dry Chemical	1	✓		1-Sep-25	Big
152		Beside Apt#2217	Dry Chemical	1	✓		1-Sep-25	Big
153		FHC - beside ST-1	Dry Chemical	1	✓		1-Sep-25	Big
154		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
155	23	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
156		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
157		Beside Apt#2301	Dry Chemical	1	✓		1-Sep-25	Big
158		Beside Apt#2317	Dry Chemical	1	✓		1-Sep-25	Big
159		FHC - beside ST-1	Dry Chemical	1	✓		1-Sep-25	Big
160		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
161	24	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
162		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
163		Beside Apt#2401	Dry Chemical	1	✓		1-Sep-25	Big
164		Beside Apt#2415	Dry Chemical	1	✓		1-Sep-25	Big
165		FHC - beside ST-1	Dry Chemical	1	✓		1-Sep-25	Big
166		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
167	25	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
168		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
169		Beside Apt#2501	Dry Chemical	1	✓		1-Sep-25	Big
170		Beside Apt#2517	Dry Chemical	1	✓		1-Sep-25	Big
171		FHC - beside ST-1	Dry Chemical	1	✓		1-Sep-25	Big
172		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big

173	26	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
174		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
175		Beside Apt#2601	Dry Chemical	1	✓		1-Sep-25	Big
176		Beside Apt#2615	Dry Chemical	1	✓		1-Sep-25	Big
177		FHC - beside ST-1	Dry Chemical	1	✓		1-Sep-25	Big
178		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
179	27	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
180		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
181		FHC - Sky Garden	Dry Chemical	1	✓		1-Sep-25	Big
182		Beside Apt#2710	Dry Chemical	1	✓		1-Sep-25	Big
183		Beside Apt#2715	Dry Chemical	1	✓		1-Sep-25	Big
184		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
185	28	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
186		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
187		Beside Apt#2809	Dry Chemical	1	✓		1-Sep-25	Big
188		Beside Apt#2815	Dry Chemical	1	✓		1-Sep-25	Big
189		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
190	29	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
191		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
192		Beside Apt#2909	Dry Chemical	1	✓		1-Sep-25	Big
193		Beside Apt#2915	Dry Chemical	1	✓		1-Sep-25	Big
194		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
195	30	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
196		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
197		Beside Apt#3009	Dry Chemical	1	✓		1-Sep-25	Big
198		Beside Apt#3015	Dry Chemical	1	✓		1-Sep-25	Big
199		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
200	31	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
201		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
202		Beside Apt#3109	Dry Chemical	1	✓		1-Sep-25	Big
203		Beside Apt#3115	Dry Chemical	1	✓		1-Sep-25	Big
204		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
205	32	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
206		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
207		Beside Apt#3209	Dry Chemical	1	✓		1-Sep-25	Big
208		Beside Apt#3215	Dry Chemical	1	✓		1-Sep-25	Big
209		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
210	33	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
211		Front of Guest Lift	Dry Chemical	1	✓		8-Sep-25	Stone
212		Beside Apt#3309	Dry Chemical	1	✓		8-Sep-25	Stone
213		Beside Apt#3315	Dry Chemical	1	✓		8-Sep-25	Stone
214		FHC - beside ST-2	Dry Chemical	1	✓		8-Sep-25	Stone
215	34	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
216		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
217		Beside Apt#3409	Dry Chemical	1	✓		1-Sep-25	Big
218		Beside Apt#3415	Dry Chemical	1	✓		1-Sep-25	Big
219		FHC - beside ST-2	Dry Chemical	1	✓		1-Sep-25	Big
220	35	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Sep-25	Big
221		Front of Guest Lift	Dry Chemical	1	✓		1-Sep-25	Big
222		Beside Apt#3509	Dry Chemical	1	✓		1-Sep-25	Big
223		Beside Apt#3515	Dry Chemical	1	✓		1-Sep-25	Big
224		FHC - beside ST-2	Dry Chemical	1	✓		8-Sep-25	Stone
225	36	FHC-Roof-ST-1	Dry Chemical	1	✓		3-Sep-25	Big
226		FHC-Roof-ST-2	Dry Chemical	1	✓		3-Sep-25	Big
			Total	233				

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Normal	Out of Service		
1	233	Dry Chemical (10 lbs)	226	3		Recharge (ส่งเติมกับอำนวยการ)
2	44	CO2	43	1		น้ำนักด้าเกณฑ์ (ใช้เทรนนิ่ง)
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	445	0		
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	6	0		
Total	756		748	4		

Reported by: Security team
10/09/2025

Acknowledged by: _____
Security Manager

No.	Floor	Location	Type	Total	Status		Check date	Remark
					Yes	No		
1	B	Security Store	ADE 2000	4	✓		21-Oct-25	Bg
2	B	Electrical Room	ADE 2000	1	✓		14-Oct-25	Chai
3	B	Engineering Workshop	ADE 2000	2	✓		15-Oct-25	Chai
4	B	Engineering Store	ADE 2000	1	✓		8-Oct-25	Big
5	B	Chemical Room	ADE 2000	2	✓		14-Oct-25	Chai
6	B	Houskeeping Store	ADE 2000	1	✓		16-Oct-25	Big
7	B	Houskeeping Office	ADE 2000	1	✓		16-Oct-25	Chai
8	B	FCC Room	ADE 2000	1	✓		8-Oct-25	Big
9	B	Fire Pump Room	ADE 2000	2	✓		8-Oct-25	Big
10	B	Finance Accounting Office	ADE 2000	1	✓		8-Oct-25	Big
11	B	Staff Canteen Room	ADE 2000	1	✓		14-Oct-25	Chai
12	G	MDB and Generator	ADE 2000	2	✓		8-Oct-25	Big
13	G	Server Room	ADE 2000	2	✓		13-Oct-25	Chai
14	G	Guest Service Office	ADE 2000	1	✓		16-Oct-25	Chai
15	G	Executive Office	ADE 2000	1	✓		16-Oct-25	Chai
16	R	Control lift Rooftop	ADE 2000	1	✓		10-Oct-25	Big
				Total	24			

CO2								
1	B	Fire Cart	CO2	1	✓		16-Oct-25	Chai
2		FCC Room	CO2	1	✓		8-Oct-25	Chai
3		Security Store	CO2	10	✓		21-Oct-25	1 น้หนักต่ำเกณฑ์
4	G	Server Room	CO2	1	✓		16-Oct-25	Chai
5		FHC - Front of Saver Room	CO2	1	✓		16-Oct-25	Chai
6	2	Rama 9 Sound Control Room	CO2	1	✓		16-Oct-25	Chai
7	8	E & E Room	CO2	1	✓		15-Oct-25	Chai
8	9	E & E Room	CO2	1	✓		15-Oct-25	Chai
9	10	E & E Room	CO2	1	✓		10-Oct-25	Chai
10	11	E & E Room	CO2	1	✓		10-Oct-25	Chai
11	12	E & E Room	CO2	1	✓		10-Oct-25	Chai
12	13	E & E Room	CO2	1	✓		10-Oct-25	Chai
13	14	E & E Room	CO2	1	✓		10-Oct-25	Chai
14	15	E & E Room	CO2	1	✓		10-Oct-25	Big
15	16	E & E Room	CO2	1	✓		10-Oct-25	Big
16	17	E & E Room	CO2	1	✓		10-Oct-25	Big
17	18	E & E Room	CO2	1	✓		10-Oct-25	Big
18	19	E & E Room	CO2	1	✓		10-Oct-25	Big
19	20	E & E Room	CO2	1	✓		10-Oct-25	Big
20	21	E & E Room	CO2	1	✓		10-Oct-25	Big
21	22	E & E Room	CO2	1	✓		10-Oct-25	Big
22	23	E & E Room	CO2	1	✓		10-Oct-25	Big
23	24	E & E Room	CO2	1	✓		10-Oct-25	Big
24	25	E & E Room	CO2	1	✓		10-Oct-25	Big
25	26	E & E Room	CO2	1	✓		10-Oct-25	Big
26	27	E & E Room	CO2	1	✓		10-Oct-25	Big
27	28	E & E Room	CO2	1	✓		10-Oct-25	Big
28	29	E & E Room	CO2	1	✓		10-Oct-25	Big
29	30	E & E Room	CO2	1	✓		10-Oct-25	Big
30	31	E & E Room	CO2	1	✓		10-Oct-25	Big
31	32	E & E Room	CO2	1	✓		3-Oct-25	Chai
32	33	E & E Room	CO2	1	✓		3-Oct-25	Chai
33	34	E & E Room	CO2	1	✓		3-Oct-25	Chai
34	35	E & E Room	CO2	1	✓		3-Oct-25	Chai
35	36	Front of Control lift room	CO2	1	✓		10-Oct-25	Big
				Total	44			

Dry Chemical								
No.	Floor	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry Chemical	1	✓		16-Oct-25	Chai
2		FHC - Front of FCC	Dry Chemical	1	✓		14-Oct-25	Chai
3		Gas Station (15 lbs)	Dry Chemical	2	✓		14-Oct-25	Chai
4		Front of Garbage Room	Dry Chemical	1	✓		14-Oct-25	Chai
5		Front of Housekeeping Store	Dry Chemical	1	✓		14-Oct-25	Chai
6		Fire Cart	Dry Chemical	1	✓		16-Oct-25	Chai
7		Security Store	Dry Chemical	7	✓		21-Oct-25	Recharge 3, รั้ว 2
8		Fire Pump Room	Dry Chemical	1	✓		8-Oct-25	Big
9		Front of Timekeeper	Dry Chemical	1	✓		14-Oct-25	Chai
10	G	FHC - Front of Service Lift	Dry Chemical	1	✓		16-Oct-25	Chai
11		FHC - Front ST-2	Dry Chemical	1	✓		14-Oct-25	Chai
12	2	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Pong
13		Front of First aid Room	Dry Chemical	1	✓		16-Oct-25	Chai
14		Front of HK Store (Outsource)	Dry Chemical	1	✓		13-Oct-25	Pong
15		FHC - Front of ST-1	Dry Chemical	1	✓		13-Oct-25	Pong
16		FHC - Front of ST-2	Dry Chemical	1	✓		13-Oct-25	Pong
17	3	FHC - Front of Service Lift	Dry Chemical	1	✓		Overcharge	Pong
18		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Pong
19		FHC - Front of ST-1	Dry Chemical	1	✓		13-Oct-25	Pong
20		Parking Area Zone 4B	Dry Chemical	1	✓		Overcharge	Pong
21		FHC - Front of ST-2	Dry Chemical	1	✓		Overcharge	Pong
22		Parking Area Zone 2A	Dry Chemical	1	✓		13-Oct-25	Pong
23	4	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Pong
24		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Pong
25		FHC - Front of ST-1	Dry Chemical	1	✓		Overcharge	Pong
26		Parking Area Zone 4B	Dry Chemical	1	✓		Overcharge	Pong
27		FHC - Front of ST-2	Dry Chemical	1	✓		Overcharge	Pong
28		Parking Area Zone 2A	Dry Chemical	1	✓		Overcharge	Pong
29		Parking Area Zone 8A	Dry Chemical	1	✓		Overcharge	Pong
30		Parking Area Zone C	Dry Chemical	1	✓		Overcharge	Pong
31	5	FHC - Front of Service Lift	Dry Chemical	1	✓		Overcharge	Pong
32		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Pong
33		FHC - Front of ST-1	Dry Chemical	1	✓		13-Oct-25	Pong
34		Parking Area Zone 4B	Dry Chemical	1	✓		13-Oct-25	Pong
35		FHC - Front of ST-2	Dry Chemical	1	✓		13-Oct-25	Pong
36		Parking Area Zone 2A	Dry Chemical	1	✓		Overcharge	Pong
37		Parking Area Zone 8A	Dry Chemical	1	✓		13-Oct-25	Pong
38		Parking Area Zone C	Dry Chemical	1	✓		13-Oct-25	Pong
39	6	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Pong
40		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Pong
41		FHC - Front of ST-1	Dry Chemical	1	✓		13-Oct-25	Pong
42		Parking Area Zone 4B	Dry Chemical	1	✓		13-Oct-25	Pong
43		Inside ST-2	Dry Chemical	1	✓		13-Oct-25	Pong
44		FHC - Front of ST-2	Dry Chemical	1	✓		13-Oct-25	Pong
45		Parking Area Zone 2A	Dry Chemical	1	✓		13-Oct-25	Pong
46		Parking Area Zone 8A	Dry Chemical	1	✓		13-Oct-25	Pong
47		Parking Area Zone C	Dry Chemical	1	✓		Overcharge	Pong
48	7	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Pong
49		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Pong
50		FHC - Front of ST-1	Dry Chemical	1	✓		13-Oct-25	Pong
51		Parking Area Zone 4B	Dry Chemical	1	✓		13-Oct-25	Pong
52		Inside ST-2	Dry Chemical	1	✓		Overcharge	Pong
53		FHC - Front of ST-2	Dry Chemical	1	✓		13-Oct-25	Pong
54		Parking Area Zone 2A	Dry Chemical	1	✓		13-Oct-25	Pong
55		Parking Area Zone 8A	Dry Chemical	1	✓		13-Oct-25	Pong
56		Parking Area Zone C	Dry Chemical	1	✓		13-Oct-25	Pong

57	7M	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Pong
58		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Pong
59		Pool Pump Room	Dry Chemical	1	✓		14-Oct-25	Chai
60		Front of Pump room	Dry Chemical	1	✓		13-Oct-25	Pong
61		Parking Area Zone A	Dry Chemical	1	✓		13-Oct-25	Pong
62		FHC - Front of ST-1	Dry Chemical	1	✓		13-Oct-25	Pong
63		Parking Area Zone 2A	Dry Chemical	1	✓		13-Oct-25	Pong
64		FHC - Inside ST-2	Dry Chemical	1	✓		13-Oct-25	Pong
65		Inside ST-2	Dry Chemical	1	✓		13-Oct-25	Pong
66	8	FHC - Front of Service Lift	Dry Chemical	1	✓		14-Oct-25	Chai
67		Front of Guest Lift	Dry Chemical	1	✓		14-Oct-25	Chai
68		FHC - beside ST-1	Dry Chemical	1	✓		Overcharge	Chai
69		FHC - beside ST-2	Dry Chemical	1	✓		14-Oct-25	Chai
70		Front of Apt#810	Dry Chemical	1	✓		14-Oct-25	Chai
71		Beside Apt#817	Dry Chemical	1	✓		14-Oct-25	Chai
72	9	FHC - Front of Service Lift	Dry Chemical	1	✓		14-Oct-25	Chai
73		Front of Guest Lift	Dry Chemical	1	✓		14-Oct-25	Chai
74		FHC - beside ST-1	Dry Chemical	1	✓		14-Oct-25	Chai
75		FHC - beside ST-2	Dry Chemical	1	✓		14-Oct-25	Chai
76		Front of Apt#910	Dry Chemical	1	✓		Overcharge	Chai
77		Beside Apt#917	Dry Chemical	1	✓		14-Oct-25	Chai
78	10	FHC - Front of Service Lift	Dry Chemical	1	✓		14-Oct-25	Chai
79		Front of Guest Lift	Dry Chemical	1	✓		14-Oct-25	Chai
80		Beside Apt#1001	Dry Chemical	1	✓		14-Oct-25	Chai
81		Beside Apt#1017	Dry Chemical	1	✓		15-Oct-25	Chai
82		FHC - beside ST-1	Dry Chemical	1	✓		14-Oct-25	Chai
83		FHC - beside ST-2	Dry Chemical	1	✓		15-Oct-25	Chai
84	11	FHC - Front of Service Lift	Dry Chemical	1	✓		Recharge	Chai
85		Front of Guest Lift	Dry Chemical	1	✓		14-Oct-25	Chai
86		Beside Apt#1101	Dry Chemical	1	✓		14-Oct-25	Chai
87		Beside Apt#1117	Dry Chemical	1	✓		14-Oct-25	Chai
88		FHC - beside ST-1	Dry Chemical	1	✓		14-Oct-25	Chai
89		FHC - beside ST-2	Dry Chemical	1	✓		14-Oct-25	Chai
90	12	FHC - Front of Service Lift	Dry Chemical	1	✓		14-Oct-25	Chai
91		Front of Guest Lift	Dry Chemical	1	✓		14-Oct-25	Chai
92		Beside Apt#1201	Dry Chemical	1	✓		Recharge	Chai
93		Beside Apt#1217	Dry Chemical	1	✓		14-Oct-25	Chai
94		FHC - beside ST-1	Dry Chemical	1	✓		Overcharge	Chai
95		FHC - beside ST-2	Dry Chemical	1	✓		14-Oct-25	Chai
96	13	FHC - Front of Service Lift	Dry Chemical	1	✓		14-Oct-25	Chai
97		Front of Guest Lift	Dry Chemical	1	✓		14-Oct-25	Chai
98		Beside Apt#1301	Dry Chemical	1	✓		14-Oct-25	Chai
99		Beside Apt#1317	Dry Chemical	1	✓		14-Oct-25	Chai
100		FHC - beside ST-1	Dry Chemical	1	✓		14-Oct-25	Chai
101		FHC - beside ST-2	Dry Chemical	1	✓		14-Oct-25	Chai
102	14	FHC - Front of Service Lift	Dry Chemical	1	✓		Overcharge	Chai
103		Front of Guest Lift	Dry Chemical	1	✓		14-Oct-25	Chai
104		Beside Apt#1401	Dry Chemical	1	✓		14-Oct-25	Chai
105		Beside Apt#1417	Dry Chemical	1	✓		14-Oct-25	Chai
106		FHC - beside ST-1	Dry Chemical	1	✓		14-Oct-25	Chai
107		FHC - beside ST-2	Dry Chemical	1	✓		14-Oct-25	Chai
108	15	FHC - Front of Service Lift	Dry Chemical	1	✓		Overcharge	Chai
109		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Chai
110		Beside Apt#1501	Dry Chemical	1	✓		14-Oct-25	Chai
111		Beside Apt#1517	Dry Chemical	1	✓		14-Oct-25	Chai
111		FHC - beside ST-1	Dry Chemical	1	✓		14-Oct-25	Chai
112		FHC - beside ST-2	Dry Chemical	1	✓		Overcharge	Chai

113	16	FHC - Front of Service Lift	Dry Chemical	1	✓		14-Oct-25	Chai
114		Front of Guest Lift	Dry Chemical	1	✓		Recharge	Chai
115		Beside Apt#1601	Dry Chemical	1	✓		14-Oct-25	Chai
116		Beside Apt#1617	Dry Chemical	1	✓		14-Oct-25	Chai
117		FHC - beside ST-1	Dry Chemical	1	✓		14-Oct-25	Chai
118		FHC - beside ST-2	Dry Chemical	1	✓		14-Oct-25	Chai
119	17	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
120		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Chai
121		Beside Apt#1701	Dry Chemical	1	✓		13-Oct-25	Chai
122		Beside Apt#1717	Dry Chemical	1	✓		Recharge	Chai
123		FHC - beside ST-1	Dry Chemical	1	✓		13-Oct-25	Chai
124		FHC - beside ST-2	Dry Chemical	1	✓		Overcharge	Chai
125	18	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
126		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
127		Beside Apt#1801	Dry Chemical	1	✓		13-Oct-25	Chai
128		Beside Apt#1817	Dry Chemical	1	✓		13-Oct-25	Chai
129		FHC - beside ST-1	Dry Chemical	1	✓		13-Oct-25	Chai
130		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
131	19	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
132		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
133		Beside Apt#1901	Dry Chemical	1	✓		13-Oct-25	Chai
134		Beside Apt#1917	Dry Chemical	1	✓		13-Oct-25	Chai
135		FHC - beside ST-1	Dry Chemical	1	✓		13-Oct-25	Chai
136		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
137	20	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
138		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Chai
139		Beside Apt#2001	Dry Chemical	1	✓		13-Oct-25	Chai
140		Beside Apt#2017	Dry Chemical	1	✓		13-Oct-25	Chai
141		FHC - beside ST-1	Dry Chemical	1	✓		13-Oct-25	Chai
142		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
143	21	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
144		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Chai
145		Beside Apt#2101	Dry Chemical	1	✓		13-Oct-25	Chai
146		Beside Apt#2117	Dry Chemical	1	✓		13-Oct-25	Chai
147		FHC - beside ST-1	Dry Chemical	1	✓		13-Oct-25	Chai
148		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
149	22	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
150		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
151		Beside Apt#2201	Dry Chemical	1	✓		13-Oct-25	Chai
152		Beside Apt#2217	Dry Chemical	1	✓		13-Oct-25	Chai
153		FHC - beside ST-1	Dry Chemical	1	✓		Overcharge	Chai
154		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
155	23	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
156		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
157		Beside Apt#2301	Dry Chemical	1	✓		13-Oct-25	Chai
158		Beside Apt#2317	Dry Chemical	1	✓		13-Oct-25	Chai
159		FHC - beside ST-1	Dry Chemical	1	✓		13-Oct-25	Chai
160		FHC - beside ST-2	Dry Chemical	1	✓		Overcharge	Chai
161	24	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
162		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
163		Beside Apt#2401	Dry Chemical	1	✓		13-Oct-25	Chai
164		Beside Apt#2415	Dry Chemical	1	✓		13-Oct-25	Chai
165		FHC - beside ST-1	Dry Chemical	1	✓		13-Oct-25	Chai
166		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
167	25	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
168		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
169		Beside Apt#2501	Dry Chemical	1	✓		13-Oct-25	Chai
170		Beside Apt#2517	Dry Chemical	1	✓		13-Oct-25	Chai
171		FHC - beside ST-1	Dry Chemical	1	✓		13-Oct-25	Chai
172		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai

173	26	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
174		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
175		Beside Apt#2601	Dry Chemical	1	✓		13-Oct-25	Chai
176		Beside Apt#2615	Dry Chemical	1	✓		13-Oct-25	Chai
177		FHC - beside ST-1	Dry Chemical	1	✓		13-Oct-25	Chai
178		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
179	27	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
180		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
181		FHC - Sky Garden	Dry Chemical	1	✓		13-Oct-25	Chai
182		Beside Apt#2710	Dry Chemical	1	✓		13-Oct-25	Chai
183		Beside Apt#2715	Dry Chemical	1	✓		13-Oct-25	Chai
184		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
185	28	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
186		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
187		Beside Apt#2809	Dry Chemical	1	✓		13-Oct-25	Chai
188		Beside Apt#2815	Dry Chemical	1	✓		13-Oct-25	Chai
189		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
190	29	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
191		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
192		Beside Apt#2909	Dry Chemical	1	✓		13-Oct-25	Chai
193		Beside Apt#2915	Dry Chemical	1	✓		13-Oct-25	Chai
194		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
195	30	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
196		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
197		Beside Apt#3009	Dry Chemical	1	✓		13-Oct-25	Chai
198		Beside Apt#3015	Dry Chemical	1	✓		13-Oct-25	Chai
199		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
200	31	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
201		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
202		Beside Apt#3109	Dry Chemical	1	✓		13-Oct-25	Chai
203		Beside Apt#3115	Dry Chemical	1	✓		13-Oct-25	Chai
204		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
205	32	FHC - Front of Service Lift	Dry Chemical	1	✓		13-Oct-25	Chai
206		Front of Guest Lift	Dry Chemical	1	✓		13-Oct-25	Chai
207		Beside Apt#3209	Dry Chemical	1	✓		13-Oct-25	Chai
208		Beside Apt#3215	Dry Chemical	1	✓		13-Oct-25	Chai
209		FHC - beside ST-2	Dry Chemical	1	✓		13-Oct-25	Chai
210	33	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Oct-25	Big
211		Front of Guest Lift	Dry Chemical	1	✓		1-Oct-25	Big
212		Beside Apt#3309	Dry Chemical	1	✓		1-Oct-25	Big
213		Beside Apt#3315	Dry Chemical	1	✓		1-Oct-25	Big
214		FHC - beside ST-2	Dry Chemical	1	✓		1-Oct-25	Big
215	34	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Oct-25	Big
216		Front of Guest Lift	Dry Chemical	1	✓		1-Oct-25	Big
217		Beside Apt#3409	Dry Chemical	1	✓		1-Oct-25	Big
218		Beside Apt#3415	Dry Chemical	1	✓		1-Oct-25	Big
219		FHC - beside ST-2	Dry Chemical	1	✓		1-Oct-25	Big
220	35	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Oct-25	Big
221		Front of Guest Lift	Dry Chemical	1	✓		1-Oct-25	Big
222		Beside Apt#3509	Dry Chemical	1	✓		1-Oct-25	Big
223		Beside Apt#3515	Dry Chemical	1	✓		1-Oct-25	Big
224		FHC - beside ST-2	Dry Chemical	1	✓		1-Oct-25	Big
225	36	FHC-Roof-ST-1	Dry Chemical	1	✓		10-Oct-25	Big
226		FHC-Roof-ST-2	Dry Chemical	1	✓		10-Oct-25	Big
			Total	234				

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Normal	Out of Service		
1	233	Dry Chemical (10 lbs)	228	6		Recharge 3, รั้ว 2 ส่งเดิม 1 (จำนวน)
2	44	CO2	43	1		น้ำหนักต่ำเกณฑ์ (ใช้เทรนนิ่ง)
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	444	1		Recharge 1 (Room 1412)
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	5	1		เคมีแข็ง
Tatal	756		748	9		

Reported by: Security team
16/10/2025

Acknowledged by: _____
Security Manager

No.	Floor	Location	Type	Total	Status		Check date	Remark
					Yes	No		
1	B	Security Store	ADE 2000	4	✓		11-Nov-25	Stone
2	B	Electrical Room	ADE 2000	1	✓		11-Nov-25	Stone
3	B	Engineering Workshop	ADE 2000	2	✓		11-Nov-25	Stone
4	B	Engineering Store	ADE 2000	1	✓		6-Nov-25	Stone
5	B	Chemical Room	ADE 2000	2	✓		6-Nov-25	Stone
6	B	Houskeeping Store	ADE 2000	1	✓		6-Nov-25	Stone
7	B	Houskeeping Office	ADE 2000	1	✓		11-Nov-25	Stone
8	B	FCC Room	ADE 2000	1	✓		6-Nov-25	Stone
9	B	Fire Pump Room	ADE 2000	2	✓		6-Nov-25	Stone
10	B	Finance Accounting Office	ADE 2000	1	✓		11-Nov-25	Stone
11	B	Staff Canteen Room	ADE 2000	1	✓		6-Nov-25	Stone
12	G	MDB and Generator	ADE 2000	2	✓		11-Nov-25	Stone
13	G	Server Room	ADE 2000	2	✓		12-Nov-25	Big
14	G	Guest Service Office	ADE 2000	1	✓		6-Nov-25	Stone
15	G	Executive Office	ADE 2000	1	✓		6-Nov-25	Stone
16	R	Control lift Rooftop	ADE 2000	1	✓		6-Nov-25	Chai
				Total	24			

CO2								
1	B	Fire Cart	CO2	1	✓		11-Nov-25	Stone
2		FCC Room	CO2	1	✓		6-Nov-25	Stone
3		Security Store	CO2	10	✓		11-Nov-25	1 น้หนักต่ำเกณฑ์
4	G	Server Room	CO2	1	✓		12-Nov-25	Big
5		FHC - Front of Saver Room	CO2	1	✓		6-Nov-25	Stone
6	2	Rama 9 Sound Control Room	CO2	1	✓		6-Nov-25	Stone
7	8	E & E Room	CO2	1	✓		7-Nov-25	Stone
8	9	E & E Room	CO2	1	✓		7-Nov-25	Stone
9	10	E & E Room	CO2	1	✓		7-Nov-25	Stone
10	11	E & E Room	CO2	1	✓		7-Nov-25	Stone
11	12	E & E Room	CO2	1	✓		7-Nov-25	Stone
12	13	E & E Room	CO2	1	✓		7-Nov-25	Stone
13	14	E & E Room	CO2	1	✓		7-Nov-25	Stone
14	15	E & E Room	CO2	1	✓		7-Nov-25	Stone
15	16	E & E Room	CO2	1	✓		7-Nov-25	Stone
16	17	E & E Room	CO2	1	✓		7-Nov-25	Stone
17	18	E & E Room	CO2	1	✓		7-Nov-25	Stone
18	19	E & E Room	CO2	1	✓		7-Nov-25	Stone
19	20	E & E Room	CO2	1	✓		7-Nov-25	Stone
20	21	E & E Room	CO2	1	✓		7-Nov-25	Stone
21	22	E & E Room	CO2	1	✓		7-Nov-25	Stone
22	23	E & E Room	CO2	1	✓		7-Nov-25	Stone
23	24	E & E Room	CO2	1	✓		7-Nov-25	Stone
24	25	E & E Room	CO2	1	✓		7-Nov-25	Stone
25	26	E & E Room	CO2	1	✓		7-Nov-25	Stone
26	27	E & E Room	CO2	1	✓		7-Nov-25	Stone
27	28	E & E Room	CO2	1	✓		7-Nov-25	Stone
28	29	E & E Room	CO2	1		x	6-Nov-25	Chai
29	30	E & E Room	CO2	1	✓		6-Nov-25	Chai
30	31	E & E Room	CO2	1	✓		6-Nov-25	Chai
31	32	E & E Room	CO2	1	✓		6-Nov-25	Chai
32	33	E & E Room	CO2	1	✓		6-Nov-25	Chai
33	34	E & E Room	CO2	1	✓		6-Nov-25	Chai
34	35	E & E Room	CO2	1	✓		6-Nov-25	Chai
35	36	Front of Control lift room	CO2	1	✓		6-Nov-25	Chai
				Total	44			

Dry Chemical								
No.	Floor	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry Chemical	1	✓		3-Nov-25	Stone
2		FHC - Front of FCC	Dry Chemical	1	✓		3-Nov-25	Stone
3		Gas Station (15 lbs)	Dry Chemical	2	✓		3-Nov-25	Stone
4		Front of Garbage Room	Dry Chemical	1	✓		3-Nov-25	Stone
5		Front of Housekeeping Store	Dry Chemical	1	✓		3-Nov-25	Stone
6		Fire Cart	Dry Chemical	1	✓		11-Nov-25	Stone
7		Security Store	Dry Chemical	7	✓		11-Nov-25	Recharge 3, รั้ว 2
8		Fire Pump Room	Dry Chemical	1	✓		6-Nov-25	Stone
9		Front of Timekeeper	Dry Chemical	1	✓		6-Nov-25	Stone
10	G	FHC - Front of Service Lift	Dry Chemical	1	✓		6-Nov-25	Stone
11		FHC - Front ST-2	Dry Chemical	1	✓		6-Nov-25	Stone
12	2	FHC - Front of Service Lift	Dry Chemical	1	✓		6-Nov-25	Stone
13		Front of First aid Room	Dry Chemical	1	✓		6-Nov-25	Stone
14		Front of HK Store (Outsource)	Dry Chemical	1	✓		6-Nov-25	Stone
15		FHC - Front of ST-1	Dry Chemical	1	✓		6-Nov-25	Stone
16		FHC - Front of ST-2	Dry Chemical	1	✓		6-Nov-25	Stone
17	3	FHC - Front of Service Lift	Dry Chemical	1	✓		Overcharge	Stone
18		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Stone
19		FHC - Front of ST-1	Dry Chemical	1	✓		3-Nov-25	Stone
20		Parking Area Zone 4B	Dry Chemical	1	✓		Overcharge	Stone
21		FHC - Front of ST-2	Dry Chemical	1	✓		Overcharge	Stone
22		Parking Area Zone 2A	Dry Chemical	1	✓		3-Nov-25	Stone
23	4	FHC - Front of Service Lift	Dry Chemical	1	✓		3-Nov-25	Stone
24		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Stone
25		FHC - Front of ST-1	Dry Chemical	1	✓		Overcharge	Stone
26		Parking Area Zone 4B	Dry Chemical	1	✓		Overcharge	Stone
27		FHC - Front of ST-2	Dry Chemical	1	✓		Overcharge	Stone
28		Parking Area Zone 2A	Dry Chemical	1	✓		Overcharge	Stone
29		Parking Area Zone 8A	Dry Chemical	1	✓		Overcharge	Stone
30		Parking Area Zone C	Dry Chemical	1	✓		Overcharge	Stone
31	5	FHC - Front of Service Lift	Dry Chemical	1	✓		Overcharge	Stone
32		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Stone
33		FHC - Front of ST-1	Dry Chemical	1	✓		3-Nov-25	Stone
34		Parking Area Zone 4B	Dry Chemical	1	✓		3-Nov-25	Stone
35		FHC - Front of ST-2	Dry Chemical	1	✓		3-Nov-25	Stone
36		Parking Area Zone 2A	Dry Chemical	1	✓		Overcharge	Stone
37		Parking Area Zone 8A	Dry Chemical	1	✓		3-Nov-25	Stone
38		Parking Area Zone C	Dry Chemical	1	✓		3-Nov-25	Stone
39	6	FHC - Front of Service Lift	Dry Chemical	1	✓		3-Nov-25	Stone
40		Front of Guest Lift	Dry Chemical	1	✓		3-Nov-25	Stone
41		FHC - Front of ST-1	Dry Chemical	1	✓		3-Nov-25	Stone
42		Parking Area Zone 4B	Dry Chemical	1	✓		3-Nov-25	Stone
43		Inside ST-2	Dry Chemical	1	✓		3-Nov-25	Stone
44		FHC - Front of ST-2	Dry Chemical	1	✓		3-Nov-25	Stone
45		Parking Area Zone 2A	Dry Chemical	1	✓		3-Nov-25	Stone
46		Parking Area Zone 8A	Dry Chemical	1	✓		3-Nov-25	Stone
47		Parking Area Zone C	Dry Chemical	1	✓		Overcharge	Stone
48	7	FHC - Front of Service Lift	Dry Chemical	1	✓		3-Nov-25	Stone
49		Front of Guest Lift	Dry Chemical	1	✓		3-Nov-25	Stone
50		FHC - Front of ST-1	Dry Chemical	1	✓		3-Nov-25	Stone
51		Parking Area Zone 4B	Dry Chemical	1	✓		3-Nov-25	Stone
52		Inside ST-2	Dry Chemical	1	✓		Overcharge	Stone
53		FHC - Front of ST-2	Dry Chemical	1	✓		3-Nov-25	Stone
54		Parking Area Zone 2A	Dry Chemical	1	✓		3-Nov-25	Stone
55		Parking Area Zone 8A	Dry Chemical	1	✓		3-Nov-25	Stone
56		Parking Area Zone C	Dry Chemical	1	✓		3-Nov-25	Stone

57	7M	FHC - Front of Service Lift	Dry Chemical	1	✓		3-Nov-25	Stone
58		Front of Guest Lift	Dry Chemical	1	✓		3-Nov-25	Stone
59		Pool Pump Room	Dry Chemical	1	✓		3-Nov-25	Stone
60		Front of Pump room	Dry Chemical	1	✓		3-Nov-25	Stone
61		Parking Area Zone A	Dry Chemical	1	✓		3-Nov-25	Stone
62		FHC - Front of ST-1	Dry Chemical	1	✓		3-Nov-25	Stone
63		Parking Area Zone 2A	Dry Chemical	1	✓		3-Nov-25	Stone
64		FHC - Inside ST-2	Dry Chemical	1	✓		3-Nov-25	Stone
65		Inside ST-2	Dry Chemical	1	✓		3-Nov-25	Stone
66	8	FHC - Front of Service Lift	Dry Chemical	1	✓		6-Nov-25	Stone
67		Front of Guest Lift	Dry Chemical	1	✓		6-Nov-25	Stone
68		FHC - beside ST-1	Dry Chemical	1	✓		6-Nov-25	Stone
69		FHC - beside ST-2	Dry Chemical	1	✓		6-Nov-25	Stone
70		Front of Apt#810	Dry Chemical	1	✓		6-Nov-25	Stone
71		Beside Apt#817	Dry Chemical	1	✓		6-Nov-25	Stone
72	9	FHC - Front of Service Lift	Dry Chemical	1	✓		5-Nov-25	Stone
73		Front of Guest Lift	Dry Chemical	1	✓		5-Nov-25	Stone
74		FHC - beside ST-1	Dry Chemical	1	✓		6-Nov-25	Stone
75		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
76		Front of Apt#910	Dry Chemical	1	✓		Overcharge	Stone
77		Beside Apt#917	Dry Chemical	1	✓		5-Nov-25	Stone
78	10	FHC - Front of Service Lift	Dry Chemical	1	✓		5-Nov-25	Stone
79		Front of Guest Lift	Dry Chemical	1	✓		5-Nov-25	Stone
80		Beside Apt#1001	Dry Chemical	1	✓		5-Nov-25	Stone
81		Beside Apt#1017	Dry Chemical	1	✓		5-Nov-25	Stone
82		FHC - beside ST-1	Dry Chemical	1	✓		5-Nov-25	Stone
83		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
84	11	FHC - Front of Service Lift	Dry Chemical	1	✓		Recharge	Stone
85		Front of Guest Lift	Dry Chemical	1	✓		5-Nov-25	Stone
86		Beside Apt#1101	Dry Chemical	1	✓		5-Nov-25	Stone
87		Beside Apt#1117	Dry Chemical	1	✓		5-Nov-25	Stone
88		FHC - beside ST-1	Dry Chemical	1	✓		5-Nov-25	Stone
89		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
90	12	FHC - Front of Service Lift	Dry Chemical	1	✓		5-Nov-25	Stone
91		Front of Guest Lift	Dry Chemical	1	✓		5-Nov-25	Stone
92		Beside Apt#1201	Dry Chemical	1	✓		Recharge	Stone
93		Beside Apt#1217	Dry Chemical	1	✓		5-Nov-25	Stone
94		FHC - beside ST-1	Dry Chemical	1	✓		Overcharge	Stone
95		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
96	13	FHC - Front of Service Lift	Dry Chemical	1	✓		5-Nov-25	Stone
97		Front of Guest Lift	Dry Chemical	1	✓		5-Nov-25	Stone
98		Beside Apt#1301	Dry Chemical	1	✓		5-Nov-25	Stone
99		Beside Apt#1317	Dry Chemical	1	✓		5-Nov-25	Stone
100		FHC - beside ST-1	Dry Chemical	1	✓		5-Nov-25	Stone
101		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
102	14	FHC - Front of Service Lift	Dry Chemical	1	✓		Overcharge	Stone
103		Front of Guest Lift	Dry Chemical	1	✓		5-Nov-25	Stone
104		Beside Apt#1401	Dry Chemical	1	✓		5-Nov-25	Stone
105		Beside Apt#1417	Dry Chemical	1	✓		5-Nov-25	Stone
106		FHC - beside ST-1	Dry Chemical	1	✓		5-Nov-25	Stone
107		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
108	15	FHC - Front of Service Lift	Dry Chemical	1	✓		Overcharge	Stone
109		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Stone
110		Beside Apt#1501	Dry Chemical	1	✓		5-Nov-25	Stone
111		Beside Apt#1517	Dry Chemical	1	✓		5-Nov-25	Stone
111		FHC - beside ST-1	Dry Chemical	1	✓		5-Nov-25	Stone
112		FHC - beside ST-2	Dry Chemical	1	✓		Overcharge	Stone

113	16	FHC - Front of Service Lift	Dry Chemical	1	✓		5-Nov-25	Stone
114		Front of Guest Lift	Dry Chemical	1	✓		Recharge	Stone
115		Beside Apt#1601	Dry Chemical	1	✓		5-Nov-25	Stone
116		Beside Apt#1617	Dry Chemical	1	✓		5-Nov-25	Stone
117		FHC - beside ST-1	Dry Chemical	1	✓		5-Nov-25	Stone
118		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
119	17	FHC - Front of Service Lift	Dry Chemical	1	✓		5-Nov-25	Stone
120		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Stone
121		Beside Apt#1701	Dry Chemical	1	✓		5-Nov-25	Stone
122		Beside Apt#1717	Dry Chemical	1	✓		Recharge	Stone
123		FHC - beside ST-1	Dry Chemical	1	✓		5-Nov-25	Stone
124		FHC - beside ST-2	Dry Chemical	1	✓		Overcharge	Stone
125	18	FHC - Front of Service Lift	Dry Chemical	1	✓		5-Nov-25	Stone
126		Front of Guest Lift	Dry Chemical	1	✓		5-Nov-25	Stone
127		Beside Apt#1801	Dry Chemical	1	✓		5-Nov-25	Stone
128		Beside Apt#1817	Dry Chemical	1	✓		5-Nov-25	Stone
129		FHC - beside ST-1	Dry Chemical	1	✓		5-Nov-25	Stone
130		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
131	19	FHC - Front of Service Lift	Dry Chemical	1	✓		5-Nov-25	Stone
132		Front of Guest Lift	Dry Chemical	1	✓		5-Nov-25	Stone
133		Beside Apt#1901	Dry Chemical	1	✓		5-Nov-25	Stone
134		Beside Apt#1917	Dry Chemical	1	✓		5-Nov-25	Stone
135		FHC - beside ST-1	Dry Chemical	1	✓		5-Nov-25	Stone
136		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
137	20	FHC - Front of Service Lift	Dry Chemical	1	✓		5-Nov-25	Stone
138		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Stone
139		Beside Apt#2001	Dry Chemical	1	✓		5-Nov-25	Stone
140		Beside Apt#2017	Dry Chemical	1	✓		5-Nov-25	Stone
141		FHC - beside ST-1	Dry Chemical	1	✓		5-Nov-25	Stone
142		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
143	21	FHC - Front of Service Lift	Dry Chemical	1	✓		5-Nov-25	Stone
144		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Stone
145		Beside Apt#2101	Dry Chemical	1	✓		5-Nov-25	Stone
146		Beside Apt#2117	Dry Chemical	1	✓		5-Nov-25	Stone
147		FHC - beside ST-1	Dry Chemical	1	✓		5-Nov-25	Stone
148		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
149	22	FHC - Front of Service Lift	Dry Chemical	1	✓		5-Nov-25	Stone
150		Front of Guest Lift	Dry Chemical	1	✓		5-Nov-25	Stone
151		Beside Apt#2201	Dry Chemical	1	✓		5-Nov-25	Stone
152		Beside Apt#2217	Dry Chemical	1	✓		5-Nov-25	Stone
153		FHC - beside ST-1	Dry Chemical	1	✓		Overcharge	Stone
154		FHC - beside ST-2	Dry Chemical	1	✓		5-Nov-25	Stone
155	23	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
156		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
157		Beside Apt#2301	Dry Chemical	1	✓		4-Nov-25	Stone
158		Beside Apt#2317	Dry Chemical	1	✓		4-Nov-25	Stone
159		FHC - beside ST-1	Dry Chemical	1	✓		4-Nov-25	Stone
160		FHC - beside ST-2	Dry Chemical	1	✓		Overcharge	Stone
161	24	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
162		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
163		Beside Apt#2401	Dry Chemical	1	✓		4-Nov-25	Stone
164		Beside Apt#2415	Dry Chemical	1	✓		4-Nov-25	Stone
165		FHC - beside ST-1	Dry Chemical	1	✓		4-Nov-25	Stone
166		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
167	25	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
168		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
169		Beside Apt#2501	Dry Chemical	1	✓		4-Nov-25	Stone
170		Beside Apt#2517	Dry Chemical	1	✓		4-Nov-25	Stone
171		FHC - beside ST-1	Dry Chemical	1	✓		4-Nov-25	Stone
172		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone

173	26	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
174		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
175		Beside Apt#2601	Dry Chemical	1	✓		4-Nov-25	Stone
176		Beside Apt#2615	Dry Chemical	1	✓		4-Nov-25	Stone
177		FHC - beside ST-1	Dry Chemical	1	✓		4-Nov-25	Stone
178		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
179	27	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
180		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
181		FHC - Sky Garden	Dry Chemical	1	✓		4-Nov-25	Stone
182		Beside Apt#2710	Dry Chemical	1	✓		4-Nov-25	Stone
183		Beside Apt#2715	Dry Chemical	1	✓		4-Nov-25	Stone
184		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
185	28	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
186		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
187		Beside Apt#2809	Dry Chemical	1	✓		4-Nov-25	Stone
188		Beside Apt#2815	Dry Chemical	1	✓		4-Nov-25	Stone
189		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
190	29	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
191		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
192		Beside Apt#2909	Dry Chemical	1	✓		4-Nov-25	Stone
193		Beside Apt#2915	Dry Chemical	1	✓		4-Nov-25	Stone
194		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
195	30	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
196		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
197		Beside Apt#3009	Dry Chemical	1	✓		4-Nov-25	Stone
198		Beside Apt#3015	Dry Chemical	1	✓		4-Nov-25	Stone
199		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
200	31	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
201		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
202		Beside Apt#3109	Dry Chemical	1	✓		4-Nov-25	Stone
203		Beside Apt#3115	Dry Chemical	1	✓		4-Nov-25	Stone
204		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
205	32	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
206		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
207		Beside Apt#3209	Dry Chemical	1	✓		4-Nov-25	Stone
208		Beside Apt#3215	Dry Chemical	1	✓		4-Nov-25	Stone
209		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
210	33	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
211		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
212		Beside Apt#3309	Dry Chemical	1	✓		4-Nov-25	Stone
213		Beside Apt#3315	Dry Chemical	1	✓		4-Nov-25	Stone
214		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
215	34	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
216		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
217		Beside Apt#3409	Dry Chemical	1	✓		4-Nov-25	Stone
218		Beside Apt#3415	Dry Chemical	1	✓		4-Nov-25	Stone
219		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
220	35	FHC - Front of Service Lift	Dry Chemical	1	✓		4-Nov-25	Stone
221		Front of Guest Lift	Dry Chemical	1	✓		4-Nov-25	Stone
222		Beside Apt#3509	Dry Chemical	1	✓		4-Nov-25	Stone
223		Beside Apt#3515	Dry Chemical	1	✓		4-Nov-25	Stone
224		FHC - beside ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
225	36	FHC-Roof-ST-1	Dry Chemical	1	✓		4-Nov-25	Stone
226		FHC-Roof-ST-2	Dry Chemical	1	✓		4-Nov-25	Stone
			Total	234				

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Normal	Out of Service		
1	233	Dry Chemical (10 lbs)	228	6		Recharge 3, รั้ว 2 ส่งเดิม 1 (จำนวน)
2	44	CO2	43	1		น้ำหนักต่ำเกณฑ์ (ใช้เทรนนิ่ง)
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	444	1		Recharge 1 (Room 1412)
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	5	1		เคมีแข็ง
Tatal	756		748	9		

Reported by: Security team
22/11/2025

Acknowledged by: _____
Security Manager

No.	Floor	Location	Type	Total	Status		Check date	Remark
					Yes	No		
1	B	Security Store	ADE 2000	4	✓		10-Dec-25	Saksith
2	B	Electrical Room	ADE 2000	1	✓		10-Dec-25	Saksith
3	B	Engineering Workshop	ADE 2000	2	✓		10-Dec-25	Saksith
4	B	Engineering Store	ADE 2000	1	✓		10-Dec-25	Saksith
5	B	Chemical Room	ADE 2000	2	✓		10-Dec-25	Saksith
6	B	Houskeeping Store	ADE 2000	1	✓		12-Dec-25	Saksith
7	B	Houskeeping Office	ADE 2000	1	✓		12-Dec-25	Saksith
8	B	FCC Room	ADE 2000	1	✓		10-Dec-25	Saksith
9	B	Fire Pump Room	ADE 2000	2	✓		10-Dec-25	Saksith
10	B	Finance Accounting Office	ADE 2000	1	✓		11-Dec-25	Saksith
11	B	Staff Canteen Room	ADE 2000	1	✓		10-Dec-25	Saksith
12	G	MDB and Generator	ADE 2000	2	✓		12-Dec-25	Saksith
13	G	Server Room	ADE 2000	2	✓		10-Dec-25	Saksith
14	G	Guest Service Office	ADE 2000	1	✓		12-Dec-25	Saksith
15	G	Executive Office	ADE 2000	1	✓		9-Dec-25	Big
16	R	Control lift Rooftop	ADE 2000	1	✓		11-Dec-25	Saksith
				Total	24			

CO2								
1	B	Fire Cart	CO2	1	✓		10-Dec-25	Saksith
2		FCC Room	CO2	1	✓		10-Dec-25	Saksith
3		Security Store	CO2	10	✓		10-Dec-25	1 น้หนักต่ำเกณฑ์
4	G	Server Room	CO2	1	✓		10-Dec-25	Saksith
5		FHC - Front of Saver Room	CO2	1	✓		10-Dec-25	Saksith
6	2	Rama 9 Sound Control Room	CO2	1	✓		10-Dec-25	Saksith
7	8	E & E Room	CO2	1	✓		9-Dec-25	Saksith
8	9	E & E Room	CO2	1	✓		9-Dec-25	Saksith
9	10	E & E Room	CO2	1	✓		9-Dec-25	Saksith
10	11	E & E Room	CO2	1	✓		9-Dec-25	Saksith
11	12	E & E Room	CO2	1	✓		9-Dec-25	Saksith
12	13	E & E Room	CO2	1	✓		9-Dec-25	Saksith
13	14	E & E Room	CO2	1	✓		9-Dec-25	Saksith
14	15	E & E Room	CO2	1	✓		9-Dec-25	Saksith
15	16	E & E Room	CO2	1	✓		9-Dec-25	Saksith
16	17	E & E Room	CO2	1	✓		9-Dec-25	Saksith
17	18	E & E Room	CO2	1	✓		9-Dec-25	Saksith
18	19	E & E Room	CO2	1	✓		9-Dec-25	Saksith
19	20	E & E Room	CO2	1	✓		9-Dec-25	Saksith
20	21	E & E Room	CO2	1	✓		9-Dec-25	Saksith
21	22	E & E Room	CO2	1	✓		9-Dec-25	Saksith
22	23	E & E Room	CO2	1	✓		9-Dec-25	Saksith
23	24	E & E Room	CO2	1	✓		9-Dec-25	Saksith
24	25	E & E Room	CO2	1	✓		9-Dec-25	Saksith
25	26	E & E Room	CO2	1	✓		9-Dec-25	Saksith
26	27	E & E Room	CO2	1	✓		9-Dec-25	Saksith
27	28	E & E Room	CO2	1	✓		9-Dec-25	Saksith
28	29	E & E Room	CO2	1	✓		9-Dec-25	Saksith
29	30	E & E Room	CO2	1	✓		9-Dec-25	Saksith
30	31	E & E Room	CO2	1	✓		9-Dec-25	Saksith
31	32	E & E Room	CO2	1	✓		9-Dec-25	Saksith
32	33	E & E Room	CO2	1	✓		9-Dec-25	Saksith
33	34	E & E Room	CO2	1	✓		9-Dec-25	Saksith
34	35	E & E Room	CO2	1	✓		9-Dec-25	Saksith
35	36	Front of Control lift room	CO2	1	✓		11-Dec-25	Saksith
				Total	44			

Dry Chemical								
No.	Floor	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry Chemical	1	✓		10-Dec-25	Saksith
2		FHC - Front of FCC	Dry Chemical	1	✓		10-Dec-25	Saksith
3		Gas Station (15 lbs)	Dry Chemical	2	✓		10-Dec-25	Saksith
4		Front of Garbage Room	Dry Chemical	1	✓		10-Dec-25	Saksith
5		Front of Housekeeping Store	Dry Chemical	1	✓		10-Dec-25	Saksith
6		Fire Cart	Dry Chemical	1	✓		10-Dec-25	Saksith
7		Security Store	Dry Chemical	7	✓		10-Dec-25	Recharge 3, รั้ว 2
8		Fire Pump Room	Dry Chemical	1	✓		10-Dec-25	Saksith
9		Front of Timekeeper	Dry Chemical	1	✓		10-Dec-25	Saksith
10	G	FHC - Front of Service Lift	Dry Chemical	1	✓		10-Dec-25	Saksith
11		FHC - Front ST-2	Dry Chemical	1	✓		10-Dec-25	Saksith
12	2	FHC - Front of Service Lift	Dry Chemical	1	✓		10-Dec-25	Saksith
13		Front of First aid Room	Dry Chemical	1	✓		10-Dec-25	Saksith
14		Front of HK Store (Outsource)	Dry Chemical	1	✓		10-Dec-25	Saksith
15		FHC - Front of ST-1	Dry Chemical	1	✓		10-Dec-25	Saksith
16		FHC - Front of ST-2	Dry Chemical	1	✓		10-Dec-25	Saksith
17	3	FHC - Front of Service Lift	Dry Chemical	1	✓		Overcharge	Saksith
18		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Saksith
19		FHC - Front of ST-1	Dry Chemical	1	✓		10-Dec-25	Saksith
20		Parking Area Zone 4B	Dry Chemical	1	✓		10-Dec-25	Saksith
21		FHC - Front of ST-2	Dry Chemical	1	✓		10-Dec-25	Saksith
22		Parking Area Zone 2A	Dry Chemical	1	✓		10-Dec-25	Saksith
23	4	FHC - Front of Service Lift	Dry Chemical	1	✓		10-Dec-25	Saksith
24		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Saksith
25		FHC - Front of ST-1	Dry Chemical	1	✓		Overcharge	Saksith
26		Parking Area Zone 4B	Dry Chemical	1	✓		Overcharge	Saksith
27		FHC - Front of ST-2	Dry Chemical	1	✓		Overcharge	Saksith
28		Parking Area Zone 2A	Dry Chemical	1	✓		Overcharge	Saksith
29		Parking Area Zone 8A	Dry Chemical	1	✓		Overcharge	Saksith
30		Parking Area Zone C	Dry Chemical	1	✓		Overcharge	Saksith
31	5	FHC - Front of Service Lift	Dry Chemical	1	✓		Overcharge	Saksith
32		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Saksith
33		FHC - Front of ST-1	Dry Chemical	1	✓		10-Dec-25	Saksith
34		Parking Area Zone 4B	Dry Chemical	1	✓		10-Dec-25	Saksith
35		FHC - Front of ST-2	Dry Chemical	1	✓		10-Dec-25	Saksith
36		Parking Area Zone 2A	Dry Chemical	1	✓		Overcharge	Saksith
37		Parking Area Zone 8A	Dry Chemical	1	✓		10-Dec-25	Saksith
38		Parking Area Zone C	Dry Chemical	1	✓		10-Dec-25	Saksith
39	6	FHC - Front of Service Lift	Dry Chemical	1	✓		10-Dec-25	Saksith
40		Front of Guest Lift	Dry Chemical	1	✓		10-Dec-25	Saksith
41		FHC - Front of ST-1	Dry Chemical	1	✓		10-Dec-25	Saksith
42		Parking Area Zone 4B	Dry Chemical	1	✓		10-Dec-25	Saksith
43		Inside ST-2	Dry Chemical	1	✓		10-Dec-25	Saksith
44		FHC - Front of ST-2	Dry Chemical	1	✓		10-Dec-25	Saksith
45		Parking Area Zone 2A	Dry Chemical	1	✓		10-Dec-25	Saksith
46		Parking Area Zone 8A	Dry Chemical	1	✓		10-Dec-25	Saksith
47		Parking Area Zone C	Dry Chemical	1	✓		Overcharge	Saksith
48	7	FHC - Front of Service Lift	Dry Chemical	1	✓		10-Dec-25	Saksith
49		Front of Guest Lift	Dry Chemical	1	✓		10-Dec-25	Saksith
50		FHC - Front of ST-1	Dry Chemical	1	✓		10-Dec-25	Saksith
51		Parking Area Zone 4B	Dry Chemical	1	✓		10-Dec-25	Saksith
52		Inside ST-2	Dry Chemical	1	✓		Overcharge	Saksith
53		FHC - Front of ST-2	Dry Chemical	1	✓		10-Dec-25	Saksith
54		Parking Area Zone 2A	Dry Chemical	1	✓		10-Dec-25	Saksith
55		Parking Area Zone 8A	Dry Chemical	1	✓		10-Dec-25	Saksith
56		Parking Area Zone C	Dry Chemical	1	✓		10-Dec-25	Saksith

57	7M	FHC - Front of Service Lift	Dry Chemical	1	✓		10-Dec-25	Saksith
58		Front of Guest Lift	Dry Chemical	1	✓		10-Dec-25	Saksith
59		Pool Pump Room	Dry Chemical	1	✓		10-Dec-25	Saksith
60		Front of Pump room	Dry Chemical	1	✓		10-Dec-25	Saksith
61		Parking Area Zone A	Dry Chemical	1	✓		10-Dec-25	Saksith
62		FHC - Front of ST-1	Dry Chemical	1	✓		10-Dec-25	Saksith
63		Parking Area Zone 2A	Dry Chemical	1	✓		10-Dec-25	Saksith
64		FHC - Inside ST-2	Dry Chemical	1	✓		10-Dec-25	Saksith
65		Inside ST-2	Dry Chemical	1	✓		10-Dec-25	Saksith
66	8	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
67		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
68		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
69		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
70		Front of Apt#810	Dry Chemical	1	✓		9-Dec-25	Saksith
71		Beside Apt#817	Dry Chemical	1	✓		9-Dec-25	Saksith
72	9	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
73		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
74		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
75		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
76		Front of Apt#910	Dry Chemical	1	✓	Overcharge		Saksith
77		Beside Apt#917	Dry Chemical	1	✓		9-Dec-25	Saksith
78	10	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
79		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
80		Beside Apt#1001	Dry Chemical	1	✓		9-Dec-25	Saksith
81		Beside Apt#1017	Dry Chemical	1	✓		9-Dec-25	Saksith
82		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
83		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
84	11	FHC - Front of Service Lift	Dry Chemical	1	✓	Recharge		Saksith
85		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
86		Beside Apt#1101	Dry Chemical	1	✓		9-Dec-25	Saksith
87		Beside Apt#1117	Dry Chemical	1	✓		9-Dec-25	Saksith
88		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
89		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
90	12	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
91		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
92		Beside Apt#1201	Dry Chemical	1	✓	Recharge		Saksith
93		Beside Apt#1217	Dry Chemical	1	✓		9-Dec-25	Saksith
94		FHC - beside ST-1	Dry Chemical	1	✓	Overcharge		Saksith
95		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
96	13	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
97		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
98		Beside Apt#1301	Dry Chemical	1	✓		9-Dec-25	Saksith
99		Beside Apt#1317	Dry Chemical	1	✓		9-Dec-25	Saksith
100		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
101		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
102	14	FHC - Front of Service Lift	Dry Chemical	1	✓	Overcharge		Saksith
103		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
104		Beside Apt#1401	Dry Chemical	1	✓		9-Dec-25	Saksith
105		Beside Apt#1417	Dry Chemical	1	✓		9-Dec-25	Saksith
106		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
107		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
108	15	FHC - Front of Service Lift	Dry Chemical	1	✓	Overcharge		Saksith
109		Front of Guest Lift	Dry Chemical	1	✓	Overcharge		Saksith
110		Beside Apt#1501	Dry Chemical	1	✓		9-Dec-25	Saksith
111		Beside Apt#1517	Dry Chemical	1	✓		9-Dec-25	Saksith
111		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
112		FHC - beside ST-2	Dry Chemical	1	✓	Overcharge		Saksith

113	16	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
114		Front of Guest Lift	Dry Chemical	1	✓		Recharge	Saksith
115		Beside Apt#1601	Dry Chemical	1	✓		9-Dec-25	Saksith
116		Beside Apt#1617	Dry Chemical	1	✓		9-Dec-25	Saksith
117		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
118		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
119	17	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
120		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Saksith
121		Beside Apt#1701	Dry Chemical	1	✓		9-Dec-25	Saksith
122		Beside Apt#1717	Dry Chemical	1	✓		9-Dec-25	Saksith
123		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
124		FHC - beside ST-2	Dry Chemical	1	✓		Overcharge	Saksith
125	18	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
126		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
127		Beside Apt#1801	Dry Chemical	1	✓		9-Dec-25	Saksith
128		Beside Apt#1817	Dry Chemical	1	✓		9-Dec-25	Saksith
129		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
130		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
131	19	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
132		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
133		Beside Apt#1901	Dry Chemical	1	✓		9-Dec-25	Saksith
134		Beside Apt#1917	Dry Chemical	1	✓		9-Dec-25	Saksith
135		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
136		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
137	20	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
138		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Saksith
139		Beside Apt#2001	Dry Chemical	1	✓		9-Dec-25	Saksith
140		Beside Apt#2017	Dry Chemical	1	✓		9-Dec-25	Saksith
141		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
142		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
143	21	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
144		Front of Guest Lift	Dry Chemical	1	✓		Overcharge	Saksith
145		Beside Apt#2101	Dry Chemical	1	✓		9-Dec-25	Saksith
146		Beside Apt#2117	Dry Chemical	1	✓		9-Dec-25	Saksith
147		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
148		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
149	22	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
150		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
151		Beside Apt#2201	Dry Chemical	1	✓		9-Dec-25	Saksith
152		Beside Apt#2217	Dry Chemical	1	✓		9-Dec-25	Saksith
153		FHC - beside ST-1	Dry Chemical	1	✓		Overcharge	Saksith
154		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
155	23	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
156		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
157		Beside Apt#2301	Dry Chemical	1	✓		9-Dec-25	Saksith
158		Beside Apt#2317	Dry Chemical	1	✓		9-Dec-25	Saksith
159		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
160		FHC - beside ST-2	Dry Chemical	1	✓		Overcharge	Saksith
161	24	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
162		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
163		Beside Apt#2401	Dry Chemical	1	✓		9-Dec-25	Saksith
164		Beside Apt#2415	Dry Chemical	1	✓		9-Dec-25	Saksith
165		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
166		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
167	25	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
168		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
169		Beside Apt#2501	Dry Chemical	1	✓		9-Dec-25	Saksith
170		Beside Apt#2517	Dry Chemical	1	✓		9-Dec-25	Saksith
171		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
172		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith

173	26	FHC - Front of Service Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
174		Front of Guest Lift	Dry Chemical	1	✓		9-Dec-25	Saksith
175		Beside Apt#2601	Dry Chemical	1	✓		9-Dec-25	Saksith
176		Beside Apt#2615	Dry Chemical	1	✓		9-Dec-25	Saksith
177		FHC - beside ST-1	Dry Chemical	1	✓		9-Dec-25	Saksith
178		FHC - beside ST-2	Dry Chemical	1	✓		9-Dec-25	Saksith
179	27	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
180		Front of Guest Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
181		FHC - Sky Garden	Dry Chemical	1	✓		1-Dec-25	Somchai
182		Beside Apt#2710	Dry Chemical	1	✓		1-Dec-25	Somchai
183		Beside Apt#2715	Dry Chemical	1	✓		1-Dec-25	Somchai
184		FHC - beside ST-2	Dry Chemical	1	✓		1-Dec-25	Somchai
185	28	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
186		Front of Guest Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
187		Beside Apt#2809	Dry Chemical	1	✓		1-Dec-25	Somchai
188		Beside Apt#2815	Dry Chemical	1	✓		1-Dec-25	Somchai
189		FHC - beside ST-2	Dry Chemical	1	✓		1-Dec-25	Somchai
190	29	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
191		Front of Guest Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
192		Beside Apt#2909	Dry Chemical	1	✓		1-Dec-25	Somchai
193		Beside Apt#2915	Dry Chemical	1	✓		1-Dec-25	Somchai
194		FHC - beside ST-2	Dry Chemical	1	✓		1-Dec-25	Somchai
195	30	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
196		Front of Guest Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
197		Beside Apt#3009	Dry Chemical	1	✓		1-Dec-25	Somchai
198		Beside Apt#3015	Dry Chemical	1	✓		1-Dec-25	Somchai
199		FHC - beside ST-2	Dry Chemical	1	✓		1-Dec-25	Somchai
200	31	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
201		Front of Guest Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
202		Beside Apt#3109	Dry Chemical	1	✓		1-Dec-25	Somchai
203		Beside Apt#3115	Dry Chemical	1	✓		1-Dec-25	Somchai
204		FHC - beside ST-2	Dry Chemical	1	✓		1-Dec-25	Somchai
205	32	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
206		Front of Guest Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
207		Beside Apt#3209	Dry Chemical	1	✓		1-Dec-25	Somchai
208		Beside Apt#3215	Dry Chemical	1	✓		1-Dec-25	Somchai
209		FHC - beside ST-2	Dry Chemical	1	✓		1-Dec-25	Somchai
210	33	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
211		Front of Guest Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
212		Beside Apt#3309	Dry Chemical	1	✓		1-Dec-25	Somchai
213		Beside Apt#3315	Dry Chemical	1	✓		1-Dec-25	Somchai
214		FHC - beside ST-2	Dry Chemical	1	✓		1-Dec-25	Somchai
215	34	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
216		Front of Guest Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
217		Beside Apt#3409	Dry Chemical	1	✓		1-Dec-25	Somchai
218		Beside Apt#3415	Dry Chemical	1	✓		1-Dec-25	Somchai
219		FHC - beside ST-2	Dry Chemical	1	✓		1-Dec-25	Somchai
220	35	FHC - Front of Service Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
221		Front of Guest Lift	Dry Chemical	1	✓		1-Dec-25	Somchai
222		Beside Apt#3509	Dry Chemical	1	✓		1-Dec-25	Somchai
223		Beside Apt#3515	Dry Chemical	1	✓		1-Dec-25	Somchai
224		FHC - beside ST-2	Dry Chemical	1	✓		1-Dec-25	Somchai
225	36	FHC-Roof-ST-1	Dry Chemical	1	✓		11-Dec-25	Saksith
226		FHC-Roof-ST-2	Dry Chemical	1	✓		11-Dec-25	Saksith
			Total	234				

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Normal	Out of Service		
1	233	Dry Chemical (10 lbs)	228	6		Recharge 3, รว 2 สงเดิม 1 (อำนวย)
2	44	CO2	43	1		น้ำนักต่ำเกณฑ์ (ใช้เทรนนิง)
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	444	1		Recharge 1 (Room 1412) Keep SEC Store
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	5	1		เคมีแข็ง
Total	756		748	9		

Reported by: Security team
25/12/2025


Acknowledged by: _____
Security Manager

รายงานการบำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2

ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

วันที่ 27-29 ตุลาคม 2568



โดย

SYSTEMS SERVICE DEPARTMENT

THE SOLUTION TO SERVE YOUR PROBLEMS



บริษัท ดียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

94 ซอยโยธินพัฒนา แขวงคลองจั่น เขตบางกะปิ กรุงเทพมหานคร 10240 Tel : 662 932 -0837

94 Soi Yothinphattana, Khlongchan, Bangkok 10240 Fax : 662 932 0838

E-mail : tms@teeyamaster.co.th www.teeyamaster.co.th



General Information	
Project : Somerset Rama9 Bangkok	
System : Fire Alarm	
Item	Procedure
1	ขั้นตอนการทดสอบอุปกรณ์ระบบ Fire Alarm
1.1	Smoke Detector - Smoke Detector เป็นอุปกรณ์ตรวจจับควันชนิด Photo Electric ทดสอบการทำงานโดยการ ใช้ Smoke Detector Tester เป็นอุปกรณ์ในการทดสอบ โดยการฉีดพ่นให้เป็นละอองไปที่ตัว Smoke แล้วรอสักครู่ ที่ตัว Smoke จะมี LED สีแดงติดสว่างแสดงการทำงาน แล้วจะมีสัญญาณส่งไปที่ Fire Alarm Control Panel ตัว Smoke จะหยุดการตรวจจับต่อเมื่อมีการ Reset ระบบ ที่ Fire Alarm Control Panel LED จึงจะดับและพร้อมในการทำงานครั้งต่อไป
1.2	Heat Detector - เป็นอุปกรณ์ตรวจจับความร้อน โดยอาศัยการโค้งงอของโลหะ 2 ชนิด มีใช้งานอยู่ 2 ชนิด 1. แบบ Rate of Rise & Fix Temp. โดยมีใช้งานตามบริเวณห้องน้ำ, Office , ทางเดิน เป็นต้น 2. แบบ Fix Temp. มีใช้งานในห้อง Generator - ชนิดที่ 1 ทดสอบการทำงานโดยใช้ไดร์เป่าผมเป็นตัวให้ความร้อนเป็นระยะเวลาหนึ่ง เพื่อให้ Heat ตรวจจับความร้อนในช่วง Rate of Rise เท่านั้นจะไม่ทดสอบในช่วง Fix Temp เนื่องจากจะเกิดความเสียหายกับตัว Heat และจะใช้งานต่อไปไม่ได้ - ชนิดที่ 2 ไม่สามารถทดสอบการทำงานที่ Fix Temp. ได้เพราะจะทำให้เกิดความเสียหาย และไม่สามารถใช้งานต่อไปได้ การทดสอบทำการ Short สายที่ขั้วอุปกรณ์แทน อุปกรณ์ชนิดนี้ไม่มีไฟ (LED) แสดงการทำงานและเมื่ออุณหภูมิลดลง ตัว Heat สามารถพร้อมทำงานครั้งต่อไปได้ เมื่ออุปกรณ์ชนิดนี้ทำงานจะมีสัญญาณส่งไปที่ Fire Alarm Control Panel ตาม Zone ที่ติดตั้งไว้
1.3	Fire Alarm Station - เป็นอุปกรณ์แจ้งเหตุเพลิงไหม้โดยบุคคลที่อยู่ในเหตุการณ์ การทดสอบขึ้นอยู่กับรูปแบบการทำงานแต่ละชนิด - Pull Station ทดสอบโดยการดึงจริง (ถอดแท่งแก้วออกก่อน) หรือโดยการเปิดฝาครอบออก แล้วยกสวิทช์ หลังจากทดสอบแล้วให้ดันกลับในตำแหน่งเดิมเพื่อปิดฝาครอบ - Breakglass ทำงานโดยการทุบกระจกให้แตก ในการทดสอบจะ Key ทดสอบดันเข้าไปดันกระจก เมื่ออุปกรณ์ชนิดนี้ทำงานจะมีสัญญาณส่งไปที่ Fire Alarm Control Panel ตาม Zone ที่ติดตั้งไว้



General Information	
Project : Somerset Rama9 Bangkok	
System : Fire Alarm	
Item	Procedure
1.4	Key Switch - Key switch ถูกติดตั้งอยู่ใน Manual Station ทดสอบโดยการไขกุญแจบิดไปยังตำแหน่ง ON เมื่ออุปกรณ์ชนิดนี้ทำงานจะมีสัญญาณส่งไปที่ Fire Alarm Control Panel ตาม Zone ที่ติดตั้งไว้
1.5	Speaker -Strobes - เป็นอุปกรณ์ส่งสัญญาณเตือนภัยโดยเสียงและแสง ทดสอบโดยให้ระบบทำงานตาม Function
1.6	Graphic Annunciator - เป็นแผงผังแสดงตำแหน่งการเกิดเหตุเพลิงไหม้ ตามจุดต่าง โดยแสดงเป็นหลอด LED และเสียงเตือน ทำงานโดยตู้ควบคุมรับสัญญาณการแจ้งเหตุจาก Detector แล้วประมวลผลตาม Function สั่งให้ Graphic Annunciator แสดงตำแหน่งที่เกิดเหตุ โดยที่ตู้มีปุ่ม ACK. ไว้หยุดเสียง Buzzer และปุ่มทดสอบหลอด LED.



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

Preventive Maintenance Report

General Information									
Project : Somerset Rama9 Bangkok			System : Fire Alarm				Model : EST3		
Revision : -			Manufacturer : GE Security Co.,Ltd.						
PM No. : 2026 - 1/2			Start : 27/10/2025				End : 31/10/2025		
Parts / Devices Types									
Part/Dev. : FCP.			Installed by : -						
Location : Engineering Room			Inspected by : Teeya Master Systems Co.,Ltd.						
Inspections and Tests List									
Item	Descriptions	Check			Functional				Remarks
		Installation	Wiring	Cleaning	Alarm	Supervisory	Trouble	Monitor	
	FAP								
01	Power Supplies								
	1.01 3-PPS Primary Power Supply	/	/	/	-	-	-	-	/
	> AC Power Input (220 Vac)	/	/	/	-	-	-	-	/
	> DC Power Connector to 3-PSMON	/	/	/	-	-	-	-	/
	> 16 Pin data line connector to 3-PSMON	/	/	/	-	-	-	-	/
	> Battery connector	/	/	/	-	-	-	-	/
	1.02 3-PSMON Primary Power Supply Monitor module	/	/	/	-	-	-	-	/
	> DC Power Connector from 3-PPS	/	/	/	-	-	-	-	/
	> 16- pin data conector from 3-PPS	/	/	/	-	-	-	-	/
	> 24 VDC Auxiliary power & connector. (2 Output)	/	/	/	-	-	-	-	/
02	3-CPU1								
	2.01 > Data Network Riser Next CPU	/	/	/	-	-	-	-	/
	2.02 > Data Network Riser Conections (RS-485).	/	/	/	-	-	-	-	/
	2.03 > RS-232 Conection.	/	/	/	-	-	-	-	/
03	3-SSDC,3-SDDC Signature Device Controller								
	3.01 > Signature Circuit Connections.	/	/	/	-	-	-	-	/
	3.02 > Filter Board	/	/	/	-	-	-	-	/
04	Battery Charger								
	4.01 > Battery Backup For FCP (12 Vdc.@ 12 Amp. 1 S	/	/	/	-	-	-	-	/
05	Indicator Lamps (At 3-LCD)								
	5.01 > Alarm	/	/	/	-	-	-	-	/
	5.02 > Supervisory	/	/	/	-	-	-	-	/
	5.03 > Trouble	/	/	/	-	-	-	-	/
	5.04 > Monitor	/	/	/	-	-	-	-	/
	5.05 > Power	/	/	/	-	-	-	-	/
	5.06 > Test	/	/	/	-	-	-	-	/
	5.07 > CPU Fail	/	/	/	-	-	-	-	/
	5.08 > Gnd Fault	/	/	/	-	-	-	-	/



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

Preventive Maintenance Report

General Information										
Project : Somerset Rama9 Bangkok			System : Fire Alarm				Model : EST3			
Revision : -			Manufacturer : GE Security Co.,Ltd.							
PM No. : 2026 - 1/2			Start : 27/10/2025				End : 31/10/2025			
Parts / Devices Types										
Part/Dev. : FCP.			Installed by : -							
Location : Engineering Room			Inspected by : Teeya Master Systems Co.,Ltd.							
Inspections and Tests List										
Item	Descriptions	Check			Functional				Remarks	
		Installation	Wiring	Cleaning	Alarm	Supervisory	Trouble	Monitor		Operation.
	5.09 > Disable	/	/	/	-	-	-	-	/	
06	Control Switches (At 3-LCD)									
	6.01 > Reset	/	/	/	-	-	-	-	/	
	6.02 > Alarm Silence	/	/	/	-	-	-	-	/	
	6.03 > Drill	/	/	/	-	-	-	-	/	
	6.04 > Panal Silence	/	/	/	-	-	-	-	/	
	6.05 > Alarm	/	/	/	-	-	-	-	/	
	6.06 > Supervisory	/	/	/	-	-	-	-	/	
	6.07 > Trouble	/	/	/	-	-	-	-	/	
	6.08 > Monitor	/	/	/	-	-	-	-	/	
	6.09 > 0-9	/	/	/	-	-	-	-	/	
	6.10 > ENTER	/	/	/	-	-	-	-	/	
	6.11 > DEL.	/	/	/	-	-	-	-	/	
	6.12 > Detail	/	/	/	-	-	-	-	/	
	6.13 > Message Next	/	/	/	-	-	-	-	/	
	6.14 > Command Manu	/	/	/	-	-	-	-	/	
07	3-FTCU Controller (Control Switches)	/	/	/	-	-	-	-	/	
	7.01 > Connect sw.	/	/	/	-	-	-	-	/	
	7.02 > Review Pending sw.	/	/	/	-	-	-	-	/	
	7.03 > ACK SW	/	/	/	-	-	-	-	/	
	7.04 > Disconnect	/	/	/	-	-	-	-	/	
	7.05 > Review Connected.	/	/	/	-	-	-	-	/	
08	LCD Display	/	/	/	-	-	-	-	/	
09	Trouble,Alarm Buzzer	/	/	/	-	-	-	-	/	
10	Computer Graphic at Operator Engineering Room	/	/	/	-	-	-	-	/	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

โครงการ Somerset Rama9 Bangkok ครั้งที่ 1/2 ประจำปี 2569

Trouble และ สรุปผลการทดสอบ

ก่อนทำการตรวจเช็คตู้ FCP Trouble 2 Point

หลังทำการตรวจเช็คตู้ FCP Trouble 2 Point

- 02070620 Demux Audio Input ต้องโปรแกรม Card LED
- 02080620 Demux Audio Input ต้องโปรแกรม Card LED

ผลการทดสอบ

- ทำความสะอาด ตู้ FCP , GA , Battery Back up , Module Box อุปกรณ์ทั่วไปใช้งานได้ปกติ
- ทำการทดสอบ Lamp Test ตู้ GA หลอดไฟ LED ใช้งานได้ปกติ
- ทำการทดสอบ Battery Backup FCP อุปกรณ์ทั่วไปใช้งานได้ปกติ
- ทำการทดสอบอุปกรณ์ Smoke ตามพื้นที่ ต่างๆ อุปกรณ์สามารถใช้งานและส่ง Alarm ได้ตามปกติ



บริษัท ทิยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
		ปกติ	ไม่ปกติ	ปกติ	ไม่ปกติ	
1020001	IM_GFL	-	-	-	-	
1020002	IM_1FL	-	-	-	-	
1020003	SMOKE_AD1 ELECTRICAL ROOM BFL	-	-	-	-	
1020004	SMOKE_AD4 FIREMAN LIFT BFL	-	-	-	-	
1020005	SMOKE_AD2 CORRIDOR EEROOM BFL	-	-	-	-	
1020007	HEAT_AD HOUSE KEERINGOFFICE BFL	-	-	-	-	
1020008	SMOKE_AD HOUSE KEEPING OFFICE	-	-	-	-	
1020009	SMOKE_AD HOUSE KEEPING STORE	-	-	-	-	
1020010	HEAT AD WORK SHOP BFL	-	-	-	-	
1020011	HEAT AD10 PUMP ROOM BFL	-	-	-	-	
1020012	HEAT AD11 PUMP ROOM BFL	-	-	-	-	
1020013	HEAT_AD12 STORAGE ROOM BFL	-	-	-	-	
1020014	HEAT_AD13 STORAGE ROOM BFL	-	-	-	-	
1020015	SMOKE_AD17 CORRIDOR FIRE PUMP BFL	-	-	-	-	
1020016	HEAT_AD5_1FL CORRIDOR ST1	-	-	-	-	
1020017	SMOKE_AD CONTRO ROOM BFL	-	-	-	-	
1020018	SMOKE_AD18_CORRIDOR ENGINEER ROOM BFL	-	-	-	-	
1020019	HEAT_AD ENGINEER OFFICE BFL	-	-	-	-	
1020020	SMOKE_AD ENGINEER STROE BFL	-	-	-	-	
1020021	SMOKE_AD FINANCE ROOMBFL	-	-	-	-	
1020022	SMOKE AD GAEBAGE2ROOMBFL	-	-	-	-	
1020023	SMOKE AD GAEBAGE1ROOMBFL	-	-	-	-	
1020024	SMOKE AD GAEBAGE4ROOMBFL	-	-	-	-	
1020025	SMOKE AD GAEBAGE3ROOMBFL	-	-	-	-	
1020026	SMOKE_AD26 CORRIDOR HOUSE KEEPING BFL	-	-	-	-	
1020027	SMOKE_AD27 CORRIDOR ENTRAN BFL	-	-	-	-	
1020028	SMOKE AD52 MDB ROOM MFL	-	-	-	-	
1020029	SMOKE AD 29 CHAMICAL RM. BFL	-	-	-	-	
1020030	SMOKE AD 30 CHAMICAL RM. BFL	-	-	-	-	
1020031	SMOKE_AD 31 CORRIDOR SECURITY ROOM BFL	-	-	-	-	
1020032	HEAT_AD SECURITY ROOMBFL	-	-	-	-	
1020033	HEAT AD33 FEMALE TOILET BFL	-	-	-	-	
1020034	HEAT_AD34 LOKER ROOM1BFL	-	-	-	-	
1020035	HEAT_AD35 LOKER ROOM1BFL	-	-	-	-	
1020036	HEAT AD36 FEMALE TOILET BFL	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1020037	SMOKE_AD40 CORRIDOR TOILET BFL	-	-	-	-	
1020038	HEAT AD38 MEN'S TOILET BFL	-	-	-	-	
1020039	HEAT AD39 MEN'S TOILET BFL	-	-	-	-	
1020040	SMOKE_AD41 CORRIDOR DINNING ROOM BFL	-	-	-	-	
1020041	HEAT_AD37 LOKER ROOM2BFL	-	-	-	-	
1020042	HEAT_AD43 DINING ROOMBFL	-	-	-	-	
1020043	HEAT_AD44 DINING ROOMBFL	-	-	-	-	
1020044	SMOKE AD45 CORRIDOR MOTORCYCLE PARK BF	-	-	-	-	
1020045	HEAT_AD47 MOTORCYCLE PARK BFL	-	-	-	-	
1020046	HEAT_AD48 MOTORCYCLE PARK BFL	-	-	-	-	
1020047	HEAT_AD49 MOTORCYCLE PARK BFL	-	-	-	-	
1020048	HEAT_AD50 MOTORCYCLE PARK BFL	-	-	-	-	
1020049	HEAT AD51 PUMP ROOM BFL	-	-	-	-	
1020050	HEAT AD28 CHAMICAL ROOM BFL	-	-	-	-	
1020051	SMOKE AD53 MDB ROOM MFL	-	-	-	-	
1020052	SMOKE AD54 GENERATOR MFL	-	-	-	-	
1020053	HEAT AD2 STAFF ROOM1 1FL	-	-	-	-	
1020054	HEAT_AD66_STAFF ROOM21FL	-	-	-	-	
1020055	HEAT_AD6_CORRIDOR 1FL	-	-	-	-	
1020056	HEAT_AD3_STAFF ROOM3 1FL	-	-	-	-	
1020058	HEAT_AD7_SHOP-1 1FL	-	-	-	-	
1020059	HEAT_AD13_MEN TOILET 1FL	-	-	-	-	
1020060	HEAT_AD14_DISABLED TOILET 1FL	-	-	-	-	
1020061	HEAT_AD15_FEMALE TOILET 1FL	-	-	-	-	
1020062	HEAT_AD16_CORRIDOR ST7 1FL	-	-	-	-	
1020063	SMOKE_AD17_PASSENGER LIFT 1FL	-	-	-	-	
1020064	HEAT_AD8_SHOP-1 1FL	-	-	-	-	
1020065	HEAT_AD9_SHOP-1 1FL	-	-	-	-	
1020066	HEAT_AD10_SHOP-1 1FL	-	-	-	-	
1020067	HEAT_AD11_CORRIDOR PABX ROOM 1FL	-	-	-	-	
1020068	SMOKE_AD12_CORRIDOR TOILET 1FL	-	-	-	-	
1020069	HEAT_AD19_SHOP-2 1FL	-	-	-	-	
1020070	HEAT_AD20_SHOP-2 1FL	-	-	-	-	
1020071	HEAT_AD21_SHOP-2 1FL	-	-	-	-	
1020072	HEAT_AD22_SHOP-2 1FL	-	-	-	-	
1020073	HEAT_AD23_SHOP-3 1FL	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1020074	HEAT_AD24_SHOP-3 1FL	-	-	-	-	
1020075	HEAT_AD25_SHOP-3 1FL	-	-	-	-	
1020076	HEAT_AD26_SHOP-4 1FL	-	-	-	-	
1020077	HEAT_AD28_SHOP-4 1FL	-	-	-	-	
1020078	HEAT_AD29_SHOP-4 1FL	-	-	-	-	
1020079	HEAT_AD30_SHOP-4 1FL	-	-	-	-	
1020080	HEAT_AD31_SHOP-4 1FL	-	-	-	-	
1020081	SMOKE_AD32_SHOP-4 1FL	-	-	-	-	
1020082	SMOKE_AD33_SHOP-4 1FL	-	-	-	-	
1020083	HEAT_AD34_SHOP-4 1FL	-	-	-	-	
1020084	HEAT_AD35_FEMALE TOILET SHOP-4 1FL	-	-	-	-	
1020085	HEAT_AD36_MEN TOILET SHOP-4 1FL	-	-	-	-	
1020086	HEAT_AD37_SHOP-3 1FL	-	-	-	-	
1020087	HEAT_AD38_MEN TOILET SHOP-3	-	-	-	-	
1020088	HEAT_AD39_FEMALE TOILET SHOP-3	-	-	-	-	
1020089	HEAT_AD40_SHOP-3 1FL	-	-	-	-	
1020090	HEAT_AD41_SHOP-3 1FL	-	-	-	-	
1020091	HEAT_AD42_SHOP-3 1FL	-	-	-	-	
1020092	HEAT_AD43_SHOP-3 1FL	-	-	-	-	
1020093	HEAT_AD44_SHOP-3 1FL	-	-	-	-	
1020094	HEAT_AD45_SHOP-2 1FL	-	-	-	-	
1020095	HEAT_AD46_SHOP-2 1FL	-	-	-	-	
1020096	HEAT_AD47_FEMALE TOILET SHOP-2	-	-	-	-	
1020097	HEAT_AD48_MEN TOILETSHOP-2	-	-	-	-	
1020098	HEAT_AD49_SHOP-2 1FL	-	-	-	-	
1020099	SMOKE_AD50_CORRIDOR FIREMAN LIFT 1FL	-	-	-	-	
1020100	SMOKE_AD51_FIREMEN LIFT 1FL	-	-	-	-	
1020101	HEAT_AD53_KITEHEN ROOM-1 1FL	-	-	-	-	
1020102	HEAT_AD55_KITEHEN ROOM-3 1FL	-	-	-	-	
1020103	HEAT_AD56_KITEHEN ROOM-4 1FL	-	-	-	-	
1020104	HEAT_AD58_KITEHEN ROOM-6 1FL	-	-	-	-	
1020105	HEAT_AD59_KITEHEN ROOM-7 1FL	-	-	-	-	
1020106	HEAT_AD60_KITEHEN ROOM-8 1FL	-	-	-	-	
1020107	HEAT_AD57_KITEHEN ROOM-5 1FL	-	-	-	-	
1020108	HEAT_AD61_FIRSTAID ROOM 1FL	-	-	-	-	
1020109	SMOKE_AD62_ELECTRICALROOM 1FL	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1020110	SMOKE_AD63_CORRIDOR EE ROOM 1FL	-	-	-	-	
1020111	SMOKE_AD64_CORRIDOR TOILET 1FL	-	-	-	-	
1020112	HEAT AD UNIFORM ROOM BFL	-	-	-	-	
1020113	SMOKE AD1 PABX ROOM 1FL	-	-	-	-	
1020126	DZ_1_BFL	-	-	-	-	
1020127	ZONE_ST1_FLOOR B-7M	-	-	-	-	
1020128	GAS STATION BFL	-	-	-	-	
1020129	STROBE_1_BFL	-	-	-	-	
1020130	STROBE_2_BFL	-	-	-	-	
1020131	STROBE_ST1_BFL	-	-	-	-	
1020132	SPEAKER_1_BFL	-	-	-	-	
1020133	SPEAKER_2_BFL	-	-	-	-	
1020134	SPEAKER_ST1_BFL	-	-	-	-	
1020135	TEL_1_BFL	-	-	-	-	
1020136	TEL_ST1_BFL	-	-	-	-	
1020137	CR_1_BFL	-	-	-	-	
1020138	CR_2_BFL	-	-	-	-	
1020139	DZ_1_1FL	-	-	-	-	
1020140	ZONE_ST2_FLOOR 1-7M	-	-	-	-	
1020141	STROBE_1_1FL	-	-	-	-	
1020142	STROBE_2_1FL	-	-	-	-	
1020143	STROBE_ST2_1FL	-	-	-	-	
1020144	SPEAKER_1_1FL	-	-	-	-	
1020145	SPEAKER_2_1FL	-	-	-	-	
1020146	SPEAKER_ST2_1FL	-	-	-	-	
1020147	TEL_1_1FL	-	-	-	-	
1020148	TEL_ST2_1FL	-	-	-	-	
1020149	MANUAL_FIREMAN LIFT BFL	-	-	-	-	
1020150	KEY_3_FIREMAN LIFT BFL	-	-	-	-	
1020151	MANUAL_CORRIDOR_BFL	-	-	-	-	
1020152	KEY_16_CORRIDOR_BFL	-	-	-	-	
1020153	MANUAL_DINING_BFL	-	-	-	-	
1020154	KEY_42_DINING_BFL	-	-	-	-	
1020155	MANUAL_MOTORCYCLE_BFL	-	-	-	-	
1020156	KEY_46_MOTORCYCLE_BFL	-	-	-	-	
1020157	MANUAL_ST1_1FL	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1020158	KEY_4_ST1_1FL	-	-	-	-	
1020159	MANUAL_PASSENGER LIFT1FL	-	-	-	-	
1020160	KEY_18_PASSENGER LIFT1FL	-	-	-	-	
1020161	MANUAL_ST2_1FL	-	-	-	-	
1020162	KEY_27_SHOP 4_1FL	-	-	-	-	
1020163	MANUAL_SHOP 2_1FL	-	-	-	-	
1020164	KEY_65_SHOP 2_1FL	-	-	-	-	
1020165	MANUAL_KITEHEN_1FL	-	-	-	-	
1020166	KEY_54_KITEHEN_1FL	-	-	-	-	
1020167	MANUAL_FIREMAN LIFT 1FL	-	-	-	-	
1020168	KEY_52 FIREMAN LIFT 1FL	-	-	-	-	
1020251	IM_2FL	-	-	-	-	
1020252	IM_7FL	-	-	-	-	
1020253	SMOKE_AD PASSENGER LIFT 5FL	-	-	-	-	
1020254	SMOKE_AD FIREMAN LIFT3FL	-	-	-	-	
1020255	SMOKE_AD PASSENGER LIFT 3FL	-	-	-	-	
1020256	SMOKE_AD FIREMAN LIFT5FL	-	-	-	-	
1020257	SMOKE_AD PASSENGER LIFT 6FL	-	-	-	-	
1020258	SMOKE_AD FIREMAN LIFT4FL	-	-	-	-	
1020259	SMOKE_AD PASSENGER LIFT 4FL	-	-	-	-	
1020260	SMOKE_AD23_RM.0812 BED ROOM	-	-	-	-	
1020261	SMOKE_AD FIREMAN LIFT6FL	-	-	-	-	
1020262	SMOKE_AD PASSENGER LIFT 7FL	-	-	-	-	
1020263	SMOKE_AD FIREMAN LIFT7FL	-	-	-	-	
1020264	SMOKE_AD FIREMAN LIFT7MFL	-	-	-	-	
1020265	SMOKE_AD CORRIDOR 3 7MFL	-	-	-	-	
1020267	SMOKE_AD CORRIDOR 5 7MFL	-	-	-	-	
1020268	HEAT AD PUMP ROOM 7MFL	-	-	-	-	
1020269	HEAT_AD66_LOBBY 1FL	-	-	-	-	
1020270	SMOKE_AD PASSENGER LIFT 7MFL	-	-	-	-	
1020271	HEAT_AD67_LOBBY 1FL	-	-	-	-	
1020272	SMOKE_AD CORRIDOR 8 7MFL	-	-	-	-	
1020273	SMOKE_AD CORRIDOR 9 7MFL	-	-	-	-	
1020274	SMOKE_AD16_8FL CORRIDOR 819	-	-	-	-	
1020275	HEAT_AD2_SMOKING ROOM8FL	-	-	-	-	
1020276	HEAT_AD3_RM.0819 BATH ROOM	-	-	-	-	



บริษัท ดิยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1020277	SMOKE_AD4_RM.0819 BED ROOM	-	-	-	-	
1020278	HEAT_AD5_RM.0818 BATH ROOM	-	-	-	-	
1020279	SMOKE_AD6_RM.0818 BED ROOM	-	-	-	-	
1020280	SMOKE_AD7_RM.0817 BED ROOM	✓				
1020281	HEAT_AD8_RM.0817 BATH ROOM	✓				
1020282	HEAT_AD57_8FL GARBAGE ROOM ST-3	-	-	-	-	
1020283	HEAT_AD10_RM.0816 BATH ROOM	✓	-	-	-	
1020284	SMOKE_AD11_RM.0816 BED ROOM	✓	-	-	-	
1020285	SMOKE_AD12_RM.0816 LIVING ROOM	✓	-	-	-	
1020286	SMOKE_AD13_RM.0815 BED ROOM	-	-	-	-	
1020287	HEAT_AD14_RM.0815 BATH ROOM	-	-	-	-	
1020288	SMOKE_AD9_8FL CORRIDOR 817	-	-	-	-	
1020289	HEAT_AD17_RM.0814 BATH ROOM	-	-	-	-	
1020290	SMOKE_AD18_RM.0814 BED ROOM	-	-	-	-	
1020291	SMOKE_AD19_RM.0814 LIVING ROOM	-	-	-	-	
1020292	SMOKE_AD26_8FL CORRIDOR 814	-	-	-	-	
1020293	SMOKE_AD20_RM.0813 BED ROOM	✓				
1020294	HEAT_AD21_RM.0813 BATH ROOM	✓				
1020295	SMOKE_AD31_8FL PASSENGER LIFT	-	-	-	-	
1020296	SMOKE_AD53_8FL FINANCIAL ROOM1	-	-	-	-	
1020297	SMOKE_AD33_8FL CORRIDOR DOOR GRASS	-	-	-	-	
1020298	HEAT_AD22_RM.0812 BATH ROOM	✓				
1020299	HEAT AD24 RM.0811 BATH ROOM	-	-	-	-	
1020300	SMOKE_AD25_RM.0811 BED ROOM	-	-	-	-	
1020301	SMOKE_AD37_8FL FIRE MAN LIFT	-	-	-	-	
1020302	SMOKE_AD34_8FL CORRIDOR 812	-	-	-	-	
1020303	SMOKE_AD38_8FL CORRIDOR FM LIFT	-	-	-	-	
1020304	HEAT_AD39_8FL MAID'S ROOM	-	-	-	-	
1020305	SMOKE AD27 RM.0810 LIVING ROOM	✓				
1020306	SMOKE AD28 RM.0810 BED ROOM	✓				
1020307	HEAT AD29 RM.0810 BATH ROOM	✓			-	
1020308	SMOKE_AD35_8FL CORRIDOR 810	-	-	-	-	
1020309	HEAT_AD42_8FL FEMALE TOILET	-	-	-	-	
1020310	HEAT_AD43_8FL STEAM ROOM	-	-	-	-	
1020311	HEAT_AD46_8FL SAUNA ROOM	-	-	-	-	
1020312	HEAT_AD68_LOBBY 1FL	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1020313	SMOKE_AD41_8FL ELECTRICAL ROOM	-	-	-	-	
1020314	SMOKE_AD58_8FL CORRIDOR ST-4	-	-	-	-	
1020315	SMOKE_AD47_8FL CORRIDOR ST-4	-	-	-	-	
1020316	SMOKE_AD40_8FL CORRIDOR TOILET	-	-	-	-	
1020317	SMOKE_AD55_8FL FINANCIAL ROOM2	-	-	-	-	
1020318	SMOKE_AD52_8FL CORRIDOR ST-1	-	-	-	-	
1020319	SMOKE_AD49_8FL MULTIPURPOSE ROOM	-	-	-	-	
1020320	SMOKE_AD50_8FL MULTIPURPOSE ROOM	-	-	-	-	
1020321	SMOKE_AD56_8FL FINANCIAL ROOM3	-	-	-	-	
1020322	SMOKE_AD48_8FL MULTIPURPOSE ROOM	-	-	-	-	
1020323	SMOKE_AD2_FIREMANLIFT2FL	-	-	-	-	
1020324	SMOKE_AD30_8FL CORRIDOR COMMU RM.	-	-	-	-	
1020325	HEAT_AD45_8FL MALE TOILET	-	-	-	-	
1020326	SMOKE_AD51_8FL CHILDREN ROOM	-	-	-	-	
1020327	SMOKE_AD3_CORRIDOOR 2FL	-	-	-	-	
1020328	SMOKE_AD4_CORRIDOOR 2FL	-	-	-	-	
1020329	SMOKE_AD5_CORRIDOOR 2FL	-	-	-	-	
1020330	HEAT_AD69_LOBBY 1FL	-	-	-	-	
1020331	SMOKE_AD7_CORRIDOOR 2FL	-	-	-	-	
1020332	SMOKE_AD8_ELECTRICAL ROOM 2FL	✓				
1020333	SMOKE_AD9_SEMINAR ROOM 2FL	✓				
1020334	SMOKE_AD10_SEMINAR ROOM 2FL	✓				
1020335	SMOKE_AD11_SEMINAR ROOM 2FL	✓				
1020336	SMOKE_AD12_SEMINAR ROOM 2FL	✓				
1020337	SMOKE_AD13_SEMINAR ROOM 2FL	✓				
1020338	SMOKE_AD15_SEMINAR ROOM 2FL					
1020339	SMOKE_AD16_SEMINAR ROOM 2FL					
1020340	SMOKE_AD17_SEMINAR ROOM 2FL					
1020341	SMOKE_AD18_SEMINAR ROOM 2FL	✓				
1020342	SMOKE_AD19_SEMINAR ROOM 2FL	✓				
1020343	HEAT_AD70_LOBBY 1FL	-	-	-	-	
1020344	SMOKE_AD21_CORRIDOOR 2FL	✓				
1020345	SMOKE_AD22_CORRIDOOR 2FL	✓				
1020346	SMOKE_AD23_CORRIDOOR 2FL	✓				
1020347	SMOKE_AD24_CORRIDOOR 2FL	-	-	-	-	
1020348	SMOKE_AD25_MEETING ROOM-2 2FL	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1020349	SMOKE_AD26_MEETING ROOM-2 2FL	-	-	-	-	
1020350	SMOKE_AD27_MEETING ROOM-1 2FL	-	-	-	-	
1020351	SMOKE_AD28_MEETING ROOM-1 2FL	-	-	-	-	
1020352	SMOKE_AD29_MEETING ROOM-1 2FL	-	-	-	-	
1020353	SMOKE_AD30_CORRIDOOR 2FL	✓				
1020354	HEAT_AD31_FEMALE TOILET 2FL	-	-	-	-	
1020355	HEAT_AD32_DISABLED TOILET 2FL	-	-	-	-	
1020356	HEAT_AD33_MALE TOILET2FL	-	-	-	-	
1020357	HEAT_AD34_2FL FOOD PREPARATION ROOM	-	-	-	-	
1020358	HEAT_AD1 8FL COMMUNICATION ROOM	-	-	-	-	
1020359	SMOKE_AD35_CORRIDOOR 2FL	✓				
1020360	SMOKE_AD36_ MULTIPURPOSE ROOM 2FL	✓				
1020361	SMOKE_AD37 MULTIPURPOSE ROOM 2FL	✓				
1020362	SMOKE_AD39_PASSENGER LIFT 2FL	✓				
1020363	SMOKE_AD40_CORRIDOOR 2FL	✓				
1020364	SMOKE_AD41_CORRIDOOR 2FL	✓				
1020365	SMOKE_AD42_SHOP-6 2FL	✓				
1020366	SMOKE_AD43_SHOP-6 2FL	✓				
1020367	SMOKE_AD44_CORRIDOOR 2FL	✓				
1020368	HEAT_AD46_MALE TOILET2FL	-	-	-	-	
1020369	HEAT_AD47_DISABLED TOILET 2FL	-	-	-	-	
1020370	HEAT_AD48_FEMALE TOILET 2FL	-	-	-	-	
1020371	SMOKE_AD49_SHOP-5 2FL	-	-	-	-	
1020372	SMOKE_AD50_SHOP-5 2FL	-	-	-	-	
1020373	SMOKE_AD51_SHOP-5 2FL	-	-	-	-	
1020374	HEAT_AD71_LOBBY 1FL	-	-	-	-	
1020375	HEAT_AD72_OFFICE 1FL	-	-	-	-	
1020376	DZ_1_2FL	-	-	-	-	
1020377	STROBE_1_2FL	-	-	-	-	
1020378	SPEAKER_1_2FL	-	-	-	-	
1020379	TEL_1_2FL	-	-	-	-	
1020380	DZ_1_3FL	-	-	-	-	
1020381	STROBE_1_3FL	-	-	-	-	
1020382	SPEAKER_1_3FL	-	-	-	-	
1020383	TEL_1_3FL	-	-	-	-	
1020384	DZ_1_4FL	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1020385	STROBE_1_4FL	-	-	-	-	
1020386	SPEAKER_1_4FL	-	-	-	-	
1020387	TEL_1_4FL	-	-	-	-	
1020388	DZ_1_5FL	-	-	-	-	
1020389	STROBE_1_5FL	-	-	-	-	
1020390	SPEAKER_1_5FL	-	-	-	-	
1020391	TEL_1_5FL	-	-	-	-	
1020392	DZ_1_6FL	-	-	-	-	
1020393	STROBE_1_6FL	-	-	-	-	
1020394	SPEAKER_1_6FL	-	-	-	-	
1020395	TEL_1_6FL	-	-	-	-	
1020396	DZ_1_7FL	-	-	-	-	
1020397	DZ_2_7FL	-	-	-	-	
1020398	DZ_4_7FL	-	-	-	-	
1020399	STROBE_1_7FL	-	-	-	-	
1020400	SPEAKER_1_7FL	-	-	-	-	
1020401	TEL_1_7FL	-	-	-	-	
1020402	CR_1_7FL	-	-	-	-	
1020403	DZ_1_7MFL	-	-	-	-	
1020404	MANUAL_ST1_8FL	-	-	-	-	
1020405	KEY_ST1_8FL	-	-	-	-	
1020406	STROBE_1_7MFL	-	-	-	-	
1020407	MANUAL_FIREMAN LIFT 2FL	-	-	-	-	
1020408	KEY_AD1_FIRE MANLIFT 2FL	-	-	-	-	
1020409	STROBE_1_7MFL	-	-	-	-	
1020410	MANUAL_ST2_2FL	-	-	-	-	
1020411	KEY_14_ST2 2FL	-	-	-	-	
1020412	TEL_1_7MFL	-	-	-	-	
1020413	MANUAL_PASSENGER LIFT2FL	-	-	-	-	
1020414	KEY_38 PASSENGER LIFT2FL	-	-	-	-	
1020415	MANUAL_ST1_2FL	-	-	-	-	
1020416	KEY_45 ST1_2FL	-	-	-	-	
1020417	MANUAL_PASSENGER LIFT8FL	-	-	-	-	
1020418	KEY_PASSENGER LIFT 8FL	-	-	-	-	
1020419	MANUAL_FIREMAN LIFT 8FL	-	-	-	-	
1020420	DZ_3_3FL	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1020421	DZ_4_3FL	-	-	-	-	
1020422	DZ_5_3FL	-	-	-	-	
1020423	DZ_2_4FL	-	-	-	-	
1020424	DZ_4_4FL	-	-	-	-	
1020425	DZ_5_4FL	-	-	-	-	
1020426	DZ_6_4FL	-	-	-	-	
1020427	DZ_7_4FL	-	-	-	-	
1020428	DZ_2_5FL	-	-	-	-	
1020429	DZ_4_5FL	-	-	-	-	
1020430	DZ_5_5FL	-	-	-	-	
1020431	DZ_6_5FL	-	-	-	-	
1020432	DZ_7_5FL	-	-	-	-	
1020433	DZ_2_6FL	-	-	-	-	
1020434	DZ_4_6FL	-	-	-	-	
1020435	DZ_5_6FL	-	-	-	-	
1020436	DZ_6_6FL	-	-	-	-	
1020437	DZ_7_6FL	-	-	-	-	
1020438	DZ_5_7FL	-	-	-	-	
1020439	DZ_6_7FL	-	-	-	-	
1020440	DZ_7_7FL	-	-	-	-	
1020441	MANUAL PASSENGER LIFT3FL	-	-	-	-	
1020442	KEY_1_PASSENGER LIFT 3FL	-	-	-	-	
1020443	MANUAL ST1 3FL	-	-	-	-	
1020444	KEY_2_ST1 3FL	-	-	-	-	
1020445	MANUAL_FIREMAN LIFT 3FL	-	-	-	-	
1020446	KEY_3_FIREMAN LIFT 3FL	-	-	-	-	
1020447	MANUAL_ST2_3FL	-	-	-	-	
1020448	KEY_4_ST2 3FL	-	-	-	-	
1020449	MANUAL ST1 B 4FL	-	-	-	-	
1020450	KEY_1_ST1 A 4FL	-	-	-	-	
1020451	MANUAL FIREMAN LIFT A 4FL	-	-	-	-	
1020452	KEY_2_FIREMAN LIFT 4FL	-	-	-	-	
1020453	MANUAL PASSENGER LIFT4FL	-	-	-	-	
1020454	KEY_3_PASSENGER LIFT4FL	-	-	-	-	
1020455	MANUAL ST1 A 4FL	-	-	-	-	
1020456	KEY_4_ST1 B 4FL	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1020457	MANUAL ST2 4FL	-	-	-	-	
1020458	KEY_5_ST2 4FL	-	-	-	-	
1020459	MANUAL_FIREMAN LIFT 5FL	-	-	-	-	
1020460	KEY_FIREMAN LIFT 5FL	-	-	-	-	
1020461	MANUAL ST1-B 5FL	-	-	-	-	
1020462	KEY ST1-B 5FL	-	-	-	-	
1020463	MANUAL_PASSENGER LIFT5FL	-	-	-	-	
1020464	KEY_3_PASSENGER LIFT 5FL	-	-	-	-	
1020465	MANUAL_ST1-A_5FL	-	-	-	-	
1020466	KEY_4_ST1-A_5FL	-	-	-	-	
1020467	MANUAL_ST2_5FL	-	-	-	-	
1020468	KEY_5_ST2_5FL	-	-	-	-	
1020469	MANUAL_ST1-B_6FL	-	-	-	-	
1020470	KEY_1_ST1-B_6FL	-	-	-	-	
1020471	MANUAL_FIREMAN LIFT 6FL	-	-	-	-	
1020472	KEY_2_FIREMAN LIFT 6FL	-	-	-	-	
1020473	MANUAL_PASSENGER LIFT6FL	-	-	-	-	
1020474	KEY_3_PASSENGER LIFT 6FL	-	-	-	-	
1020475	MANUAL_ST1-A_6FL	-	-	-	-	
1020476	KEY_4_ST1-A_6FL	-	-	-	-	
1020477	MANUAL_ST2_6FL	-	-	-	-	
1020478	KEY_5_ST2_6FL	-	-	-	-	
1020479	MANUAL FIREMAN LIFT 7FL	-	-	-	-	
1020480	KEY_1_FIREMAN LIFT 7FL	-	-	-	-	
1020481	MANUAL ST1-B 7FL	-	-	-	-	
1020482	KEY_2_ST1-B 7FL	-	-	-	-	
1020483	MANUAL PASSENGER LIFT7FL	-	-	-	-	
1020484	KEY_3_PASSENGER LIFT 7FL	-	-	-	-	
1020485	MANUAL ST1-A 7FL	-	-	-	-	
1020486	KEY_4_ST1-A 7FL	-	-	-	-	
1020487	MANUAL ST2 7FL	-	-	-	-	
1020488	KEY_5_ST2 7FL	-	-	-	-	
1020489	MANUAL ST1 7MFL	-	-	-	-	
1020490	KEY_1_ST1 7MFL	-	-	-	-	
1020491	MANUAL FIREMAN LIFT 7MFL	-	-	-	-	
1020492	KEY_2_FIREMAN LIFT 7MFL	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1020493	MANUAL ST2 7MFL	-	-	-	-	
1020494	KEY_2_ST2 7MFL	-	-	-	-	
1020495	MANUAL_ST3_8FL	-	-	-	-	
1020496	KEY_1_ST3_8FL	-	-	-	-	
1020497	KEY_4 FIREMAN LIFT 8FL	-	-	-	-	
1030001	IM_9FL	-	-	-	-	
1030002	IM_10FL	-	-	-	-	
1030003	HEAT_AD RM.1020 BATH ROOM	-	-	-	-	
1030004	SMOKE_AD RM.1020 LIVING ROOM	-	-	-	-	
1030005	HEAT_AD RM.1019 BATH ROOM	-	-	-	-	
1030006	SMOKE_AD RM.1019 BED ROOM	-	-	-	-	
1030007	HEAT_AD RM.1018 BATH ROOM	-	-	-	-	
1030008	SMOKE_AD RM.1018 BED ROOM	-	-	-	-	
1030009	HEAT_AD RM.1017 BATH ROOM	✓				
1030010	SMOKE_AD RM.1017 LIVING ROOM	✓				
1030011	HEAT_AD RM.1016 BATH ROOM	✓				
1030012	SMOKE_AD RM.1016 BED ROOM	✓				
1030013	SMOKE_AD RM.1016 LIVING ROOM	✓				
1030014	SMOKE_AD RM.1015 BED ROOM	✓				
1030015	HEAT_AD RM.1015 BATH ROOM	✓				
1030016	SMOKE_AD14 10FL CORRIDOR R1016	-	-	-	-	
1030017	SMOKE_AD16 10FL CORRIDOR R1019	-	-	-	-	
1030018	HEAT_AD RM.1014 BATH ROOM	✓				
1030019	SMOKE_AD RM.1014 BED ROOM	✓				
1030020	SMOKE_AD RM.1014 LIVING ROOM	✓				
1030021	SMOKE_AD20 10FL CORRIDOR R1013	-	-	-	-	
1030022	SMOKE_AD RM.1013 BED ROOM	✓				
1030023	HEAT_AD RM.1013 BATH ROOM	✓				
1030024	SMOKE_AD23 10FL PASSENGER LIFT	-	-	-	-	
1030025	HEAT_AD64 10FL TOILET CORRIDOR	-	-	-	-	
1030026	HEAT_AD RM.1012 BATH ROOM	✓				
1030027	SMOKE_AD RM.1012 BED ROOM	✓				อุปกรณ์เสีย
1030028	SMOKE_AD28 10FL CORRIDOR R1012	-	-	-	-	
1030029	HEAT_AD RM.1011 BATH ROOM	✓				
1030030	SMOKE_AD RM.1011 BED ROOM	✓				
1030031	SMOKE_AD RM.1010 LIVING ROOM	✓				



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1030032	SMOKE_AD RM.1010 BED ROOM	✓				
1030033	HEAT_AD RM.1010 BATH ROOM	✓				
1030034	SMOKE_AD34 10FL CORRIDOR 1010	-	-	-	-	
1030035	SMOKE_AD RM.1009 LIVING ROOM	-	-	-	-	
1030036	SMOKE_AD RM.1009 BED ROOM	-	-	-	-	
1030037	HEAT_AD RM.1009 BATH ROOM	-	-	-	-	
1030038	SMOKE_AD38 10FL CORRIDOR R1009	-	-	-	-	
1030039	SMOKE_AD39 10FL CORRIDOR R1001	-	-	-	-	
1030040	HEAT_AD RM.1008 BATH ROOM	-	-	-	-	
1030041	SMOKE_AD RM.1008 BED ROOM	-	-	-	-	
1030042	SMOKE_AD RM.1007 LIVING ROOM	✓				
1030043	HEAT_AD RM.1007 BATH ROOM	✓				
1030044	SMOKE_AD44 10FL CORRIDOR R1003	-	-	-	-	
1030045	HEAT_AD RM.1006 BATH ROOM	✓				
1030046	SMOKE_AD RM.1006 BED ROOM	✓				
1030047	SMOKE_AD RM.1005 LIVING ROOM	✓				
1030048	SMOKE_AD RM.1005 BED ROOM	✓				
1030049	HEAT_AD RM.1005 BATH ROOM	✓				
1030050	SMOKE_AD RM.1004 LIVING ROOM	-	-	-	-	
1030051	HEAT_AD RM.1004 BATH ROOM	-	-	-	-	
1030052	SMOKE_AD52 10FL CORRIDOR R1005	-	-	-	-	
1030053	SMOKE_AD RM.1003 BED ROOM	✓				
1030054	HEAT_AD RM.1003 BATH ROOM	✓				
1030055	SMOKE_AD RM.1002 BED ROOM	✓				
1030056	HEAT_AD RM.1002 BATH ROOM	✓				
1030057	SMOKE_AD RM.1001 LIVING ROOM	✓				
1030058	HEAT_AD RM.1001 BATH ROOM	✓				
1030059	HEAT_AD60 10FL MAID'S ROOM	-	-	-	-	
1030060	HEAT_AD61 10FL GARBAGE ROOM	-	-	-	-	
1030061	SMOKE_AD62 10FL FIRE MAN LIFT	-	-	-	-	
1030062	SMOKE_AD64 10FL ELECTRICAL ROOM	-	-	-	-	
1030063	HEAT_AD65 10FL COMMUNICATION ROOM	-	-	-	-	
1030064	HEAT_AD1 9FL COMMUNICATION ROOM	-	-	-	-	
1030065	HEAT_AD RM.0920 BATH ROOM	-	-	-	-	
1030066	SMOKE_AD RM.0920 BED ROOM	-	-	-	-	
1030067	HEAT_AD RM.0919 BATH ROOM	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1030068	SMOKE_AD RM.0919 BED ROOM	✓				
1030069	HEAT_AD RM.0918 BATH ROOM	✓				
1030070	SMOKE_AD RM.0918 BED ROOM	✓				
1030071	SMOKE_AD RM.0917 BED ROOM	-	-	-	-	
1030072	HEAT_AD RM.0917 BATH ROOM	-	-	-	-	
1030073	SMOKE AD10 9FL CORRIDOR R917	-	-	-	-	
1030074	HEAT_AD RM.0916 BATH ROOM	✓				
1030075	SMOKE_AD RM.0916 BED ROOM	✓				
1030076	SMOKE_AD RM.0916 LIVING ROOM	✓				
1030077	SMOKE_AD RM.0915 BED ROOM	✓				
1030078	HEAT_AD RM.0915 BATH ROOM	✓				
1030079	SMOKE AD17 9FL CORRIDOR R919	-	-	-	-	
1030080	HEAT_AD RM.0914 BATH ROOM	✓				
1030081	SMOKE_AD RM.0914 BED ROOM	✓				
1030082	SMOKE_AD RM.0914 LIVING ROOM	✓				
1030083	SMOKE AD21 9FL CORRIDOR R913	-	-	-	-	
1030084	SMOKE_AD RM.0913 BED ROOM	-	-	-	-	
1030085	HEAT_AD RM.0913 BATH ROOM	-	-	-	-	
1030086	SMOKE AD25 9FL PASSENGER LIFT	-	-	-	-	
1030087	HEAT_AD RM.0912 BATH ROOM	-	-	-	-	
1030088	SMOKE_AD RM.0912 LIVING ROOM	-	-	-	-	
1030089	HEAT_AD RM.0911 BATH ROOM	-	-	-	-	
1030090	SMOKE_AD RM.0911 BED ROOM	-	-	-	-	
1030091	SMOKE_AD RM.0910 LIVING ROOM	✓				
1030092	SMOKE_AD RM.0910 BED ROOM	✓				
1030093	HEAT_AD RM.0910 BATH ROOM	✓				
1030094	SMOKE AD33 9FL CORRIDOR R910	-	-	-	-	
1030095	SMOKE AD34 9FL CORRIDOR R912	-	-	-	-	
1030096	SMOKE AD35 9FL CORRIDOR F2	-	-	-	-	
1030097	SMOKE_AD36_9FL CORRIDOR	-	-	-	-	
1030098	SMOKE_AD37_9FL CORRIDOR EE ROOM	-	-	-	-	
1030099	SMOKE_AD38_9FL FOYER 1	-	-	-	-	
1030100	SMOKE_AD39_9FL FOYER 2	-	-	-	-	
1030101	SMOKE_AD40_9FL STORAGE ROOM	-	-	-	-	
1030102	SMOKE_AD41_9FL CORRIDOR ST4	-	-	-	-	
1030103	SMOKE_AD42_9FL FITNESS ROOM1	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1030104	SMOKE_AD43_9FL FITNESS ROOM2	-	-	-	-	
1030105	SMOKE_AD44_9FL YOGA RM.	-	-	-	-	
1030106	SMOKE_AD45_9FL FIREMAN LIFT	-	-	-	-	
1030107	SMOKE_AD48_9FL ELECTRICAL ROOM	-	-	-	-	
1030108	HEAT_AD49_9FL GARBAGE ROOM ST3	-	-	-	-	
1030109	IM_1_8FL	-	-	-	-	
1030126	ZONE_ST1_FLOOR 9-15	-	-	-	-	
1030127	ZONE_ST3_FLOOR 9-15	-	-	-	-	
1030128	STROBE_1_9FL	-	-	-	-	
1030129	SPEAKER_1_9FL	-	-	-	-	
1030130	TEL_1_9FL	-	-	-	-	
1030131	TEL_ST1_9FL	-	-	-	-	
1030132	TEL_ST3_9FL	-	-	-	-	
1030133	STROBE_1_10FL	-	-	-	-	
1030134	SPEAKER_1_10FL	-	-	-	-	
1030135	TEL_1_10FL	-	-	-	-	
1030136	MANUAL_ST3_9FL	-	-	-	-	
1030137	KEY_15_ST3_9FL	-	-	-	-	
1030138	MANUAL_PASSENGER LIFT9FL	-	-	-	-	
1030139	KEY_24_PASSENGER LIFT9FL	-	-	-	-	
1030140	MANUAL_ST1_9FL	-	-	-	-	
1030141	KEY_53_ST1_9FL	-	-	-	-	
1030142	MANUAL_FIREMAN LIFT_ 9FL	-	-	-	-	
1030143	KEY_63_FIREMAN LIFT 9FL	-	-	-	-	
1030144	MANUAL_ST3_10FL	-	-	-	-	
1030145	KEY_15_ST3_10FL	-	-	-	-	
1030146	MANUAL_PASSENGER LIFT10FL	-	-	-	-	
1030147	KEY_24_PASSENGER LIFT10FL	-	-	-	-	
1030148	MANUAL_ST1_10FL	-	-	-	-	
1030149	KEY_53_ST1_10FL	-	-	-	-	
1030150	MANUAL_FIREMAN LIFT_ 10FL	-	-	-	-	
1030151	KEY_63_FIREMAN LIFT 10FL	-	-	-	-	
1030152	STROBE_1_8FL	-	-	-	-	
1030153	SPEAKER_1_8FL	-	-	-	-	
1030154	TEL_1_8FL	-	-	-	-	
1030155	STROBE_2_ST1	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1030156	STROBE_2_ST3	-	-	-	-	
1030157	SPEAKER_2_ST1	-	-	-	-	
1030158	SPEAKER_2_ST3	-	-	-	-	
1030251	IM_11FL	-	-	-	-	
1030252	IM_12FL	-	-	-	-	
1030253	HEAT_AD RM.1120 BATH ROOM	✓				
1030254	SMOKE_AD RM.1120 LIVING ROOM	✓				
1030255	HEAT_AD RM.1119 BATH ROOM	✓				
1030256	SMOKE_AD RM.1119 BED ROOM	✓				
1030257	HEAT_AD RM.1118 BATH ROOM	✓				
1030258	SMOKE_AD RM.1118 BED ROOM	✓				
1030259	HEAT_AD RM.1117 BATH ROOM	✓				
1030260	SMOKE_AD RM.1117 BED ROOM	✓				
1030261	HEAT_AD RM.1116 BATH ROOM	✓				
1030262	SMOKE_AD RM.1116 BED ROOM	✓				
1030263	SMOKE_AD RM.1116 LIVING ROOM	✓				
1030264	SMOKE_AD RM.1115 BED ROOM	✓				
1030265	HEAT_AD RM.1115 BATH ROOM	✓				
1030266	SMOKE_AD14 11FL CORRIDOR R1116	-	-	-	-	
1030267	SMOKE_AD16 11FL CORRIDOR R1119	-	-	-	-	
1030268	HEAT_AD RM.1114 BATH ROOM	✓				
1030269	SMOKE_AD RM.1114 BED ROOM	✓				
1030270	SMOKE_AD RM.1114 LIVING ROOM	✓				
1030271	SMOKE_AD20 11FL CORRIDOR R1113	-	-	-	-	
1030272	SMOKE_AD RM.1113 BED ROOM	-	-	-	-	
1030273	HEAT_AD RM.1113 BATH ROOM	-	-	-	-	
1030274	SMOKE_AD23 11FL PASSENGER LIFT	-	-	-	-	
1030276	HEAT_AD RM.1112 BATH ROOM	-	-	-	-	
1030277	SMOKE_AD RM.1112 BED ROOM	-	-	-	-	
1030278	SMOKE_AD28 11FL CORRIDOR R1112	-	-	-	-	
1030279	HEAT_AD RM.1111 BATH ROOM	✓				
1030280	SMOKE_AD RM.1111 BED ROOM	✓				
1030281	SMOKE_AD RM.1110 LIVING ROOM	✓				
1030282	SMOKE_AD RM.1110 BED ROOM	✓				
1030283	HEAT_AD RM.1110 BATH ROOM	✓				
1030284	SMOKE_AD34 11FL CORRIDOR R1110	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1030285	SMOKE_AD RM.1109 LIVING ROOM	✓				
1030286	SMOKE_AD RM.1109 BED ROOM	✓				
1030287	HEAT_AD RM.1109 BATH ROOM	✓				
1030288	SMOKE_AD38 11FL CORRIDOR R1109	-	-	-	-	
1030289	SMOKE_AD39 11FL CORRIDOR R1101	-	-	-	-	
1030290	HEAT_AD RM.1108 BATH ROOM	✓				
1030291	SMOKE_AD RM.1108 BED ROOM	✓				
1030292	SMOKE_AD RM.1107 LIVING ROOM	✓				
1030293	HEAT_AD RM.1107 BATH ROOM	✓				
1030294	SMOKE_AD44 11FL CORRIDOR R1103	-	-	-	-	
1030295	HEAT_AD RM.1106 BATH ROOM	✓				
1030296	SMOKE_AD RM.1106 BED ROOM	✓				
1030297	SMOKE_AD RM.1105 LIVING ROOM	-	-	-	-	
1030298	SMOKE_AD RM.1105 BED ROOM	-	-	-	-	
1030299	HEAT_AD RM.1105 BATH ROOM	-	-	-	-	
1030300	SMOKE_AD RM.1104 LIVING ROOM	✓				
1030301	HEAT_AD RM.1104 BATH ROOM	✓				
1030302	SMOKE_AD52 11FL CORRIDOR R1105	-	-	-	-	
1030303	SMOKE_AD RM.1103 BED ROOM	✓				
1030304	HEAT_AD RM.1103 BATH ROOM	✓				
1030305	SMOKE_AD RM.1102 BED ROOM	✓				
1030306	HEAT_AD RM.1102 BATH ROOM	✓				
1030307	SMOKE_AD RM.1101 LIVING ROOM	✓				
1030308	HEAT_AD RM.1101 BATH ROOM	✓				
1030309	HEAT_AD60 11FL MAID'S ROOM	-	-	-	-	
1030310	HEAT_AD61 11FL GARBAGE ROOM	-	-	-	-	
1030311	SMOKE_AD62 11FL FIREMAN LIFT	-	-	-	-	
1030312	SMOKE_AD64 11FL ELECTRICAL ROOM	-	-	-	-	
1030313	HEAT_AD65 11FL COMMUNICATION ROOM	-	-	-	-	
1030314	HEAT_AD RM.1220 BATH ROOM	✓				
1030315	SMOKE_AD RM.1220 LIVING ROOM	✓				
1030316	HEAT_AD RM.1219 BATH ROOM	-	-	-	-	
1030317	SMOKE_AD RM.1219 BED ROOM	-	-	-	-	
1030318	HEAT_AD RM.1218 BATH ROOM	✓				
1030319	SMOKE_AD RM.1218 BED ROOM	✓				
1030320	HEAT_AD RM.1217 BATH ROOM	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1030321	SMOKE_AD RM.1217 BED ROOM	-	-	-	-	
1030322	HEAT_AD RM.1216 BATH ROOM	-	-	-	-	
1030323	SMOKE_AD RM.1216 BED ROOM	-	-	-	-	
1030324	SMOKE_AD RM.1216 LIVING ROOM	-	-	-	-	
1030325	SMOKE_AD RM.1215 BED ROOM	-	-	-	-	
1030326	HEAT_AD RM.1215 BATH ROOM	-	-	-	-	
1030327	SMOKE_AD14 12FL CORRIDOR R1216	-	-	-	-	
1030328	SMOKE_AD16 12FL CORRIDOR R1219	-	-	-	-	
1030329	HEAT_AD RM.1214 BATH ROOM	✓				
1030330	SMOKE_AD RM.1214 BED ROOM	✓				
1030331	SMOKE_AD20 12FL CORRIDOR R1213	-	-	-	-	
1030332	SMOKE_AD RM.1214 LIVING ROOM	✓				
1030333	SMOKE_AD RM.1213 BED ROOM	✓				
1030334	HEAT_AD RM.1213 BATH ROOM	✓				
1030335	SMOKE_AD23 12FL PASSENGER LIFT	-	-	-	-	
1030337	HEAT_AD RM.1212 BATH ROOM	-	-	-	-	
1030338	SMOKE_AD RM.1212 BED ROOM	-	-	-	-	
1030339	SMOKE_AD28 12FL CORRIDOR R1212	-	-	-	-	
1030340	HEAT_AD RM.1211 BATH ROOM	-	-	-	-	
1030341	SMOKE_AD RM.1211 BED ROOM	-	-	-	-	
1030342	SMOKE_AD RM.1210 LIVING ROOM	✓				
1030343	SMOKE_AD RM.1210 BED ROOM	✓				
1030344	HEAT_AD RM.1210 BATH ROOM	✓				
1030345	SMOKE_AD34 12FL CORRIDOR R1210	-	-	-	-	
1030346	SMOKE_AD RM.1209 LIVING ROOM	-	-	-	-	
1030347	SMOKE_AD RM.1209 BED ROOM	-	-	-	-	
1030348	HEAT_AD RM.1209 BATH ROOM	-	-	-	-	
1030349	SMOKE_AD38 12FL CORRIDOR R1209	-	-	-	-	
1030350	SMOKE_AD39 12FL CORRIDOR R1201	-	-	-	-	
1030351	HEAT_AD RM.1208 BATH ROOM	-	-	-	-	
1030352	SMOKE_AD RM.1208 BED ROOM	-	-	-	-	
1030353	SMOKE_AD RM.1207 LIVING ROOM	-	-	-	-	
1030354	HEAT_AD RM.1207 BATH ROOM	-	-	-	-	
1030355	SMOKE_AD44 12FL CORRIDOR R1203	-	-	-	-	
1030356	HEAT_AD RM.1206 BATH ROOM	✓				
1030357	SMOKE_AD RM.1206 BED ROOM	✓				



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1030358	SMOKE_AD RM.1205 LIVING ROOM	✓				
1030359	SMOKE_AD RM.1205 BED ROOM	✓				
1030360	HEAT_AD RM.1205 BATH ROOM	✓				
1030361	SMOKE_AD RM.1204 LIVING ROOM	✓				
1030362	HEAT_AD RM.1204 BATH ROOM	✓				
1030363	SMOKE_AD52 12FL CORRIDOR R1205	-	-	-	-	
1030364	SMOKE_AD RM.1203 BED ROOM	-	-	-	-	
1030365	HEAT_AD RM.1203 BATH ROOM	-	-	-	-	
1030366	SMOKE_AD RM.1202 BED ROOM	✓				
1030367	HEAT_AD RM.1202 BATH ROOM	✓				
1030368	SMOKE_AD RM.1201 LIVING ROOM	✓				
1030369	HEAT_AD RM.1201 BATH ROOM	✓				
1030370	HEAT_AD60 12FL MAID'S ROOM	-	-	-	-	
1030371	HEAT_AD61 12FL GARBAGE ROOM	-	-	-	-	
1030372	SMOKE_AD62 12FL FIREMAN LIFT	-	-	-	-	
1030373	SMOKE_AD64 12FL ELECTRICAL ROOM	-	-	-	-	
1030374	HEAT_AD65 12FL COMMUNICATION ROOM	-	-	-	-	
1030376	STROBE_1_11FL	-	-	-	-	
1030377	SPEAKER_1_11FL	-	-	-	-	
1030378	TEL_1_11FL	-	-	-	-	
1030379	STROBE_1_12FL	-	-	-	-	
1030380	SPEAKER_1_12FL	-	-	-	-	
1030381	TEL_1_12FL	-	-	-	-	
1030382	MANUAL_ST3_11FL	-	-	-	-	
1030383	KEY_15_ST3_11FL	-	-	-	-	
1030384	MANUAL_PASSENGER LIFT11FL	-	-	-	-	
1030385	KEY_24_PASSENGER LIFT11FL	-	-	-	-	
1030386	MANUAL_ST1_11FL	-	-	-	-	
1030387	KEY_53_ST1_11FL	-	-	-	-	
1030388	MANUAL_FIREMAN LIFT 11FL	-	-	-	-	
1030389	KEY_63_FIREMAN LIFT 11FL	-	-	-	-	
1030390	MANUAL_ST3_12FL	-	-	-	-	
1030391	KEY_15_ST3_12FL	-	-	-	-	
1030392	MANUAL_PASSENGER LIFT12FL	-	-	-	-	
1030393	KEY_24_PASSENGER LIFT12FL	-	-	-	-	
1030394	MANUAL_ST1_12FL	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1030395	KEY_53_ST1_12FL	-	-	-	-	
1030396	MANUAL_FIREMAN LIFT 12FL	-	-	-	-	
1030397	KEY_63_FIREMAN LIFT 12FL	-	-	-	-	
1040001	IM_12AFL	-	-	-	-	
1040002	IM_14FL	-	-	-	-	
1040003	HEAT_AD RM.1320 BATH ROOM	-	-	-	-	
1040004	SMOKE_AD RM.1320 LIVING ROOM	-	-	-	-	
1040005	HEAT_AD RM.1319 BATH ROOM	-	-	-	-	
1040006	SMOKE_AD RM.1319 BED ROOM	-	-	-	-	
1040007	HEAT_AD RM.1318 BATH ROOM	-	-	-	-	
1040008	SMOKE_AD RM.1318 BED ROOM	-	-	-	-	
1040009	HEAT_AD RM.1317 BATH ROOM	-	-	-	-	
1040010	SMOKE_AD RM.1317 BED ROOM	-	-	-	-	
1040011	HEAT_AD RM.1316 BATH ROOM	✓				
1040012	SMOKE_AD RM.1316 BED ROOM	✓				
1040013	SMOKE_AD RM.1316 LIVING ROOM	✓				
1040014	SMOKE_AD RM.1315 BED ROOM	-	-	-	-	
1040015	HEAT_AD RM.1315 BATH ROOM	-	-	-	-	
1040016	SMOKE_AD14 13FL CORRIDOR R1316	-	-	-	-	
1040017	SMOKE_AD16 13FL CORRIDOR R1319	-	-	-	-	
1040018	HEAT_AD RM.1314 BATH ROOM	✓				
1040019	SMOKE_AD RM.1314 BED ROOM	✓				
1040020	SMOKE_AD RM.1314 LIVING ROOM	✓				
1040021	SMOKE_AD20 13FL CORRIDOR R1313	-	-	-	-	
1040022	SMOKE_AD RM.1313 BED ROOM	-	-	-	-	
1040023	HEAT_AD RM.1313 BATH ROOM	✓				
1040024	SMOKE_AD23 13FL PASSENGER LIFT	✓				
1040025	HEAT_AD25 13FL CORRIDOR	-	-	-	-	
1040026	HEAT_AD RM.1312 BATH ROOM	-	-	-	-	
1040027	SMOKE_AD RM.1312 BED ROOM	-	-	-	-	
1040028	SMOKE_AD28 13FL CORRIDOR R1312	-	-	-	-	
1040029	HEAT_AD RM.1311 BATH ROOM	✓				
1040030	SMOKE_AD RM.1311 BED ROOM	✓				
1040031	SMOKE_AD RM.1310 LIVING ROOM	-	-	-	-	
1040032	SMOKE_AD RM.1310 BED ROOM	-	-	-	-	
1040033	HEAT_AD RM.1310 BATH ROOM	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1040034	SMOKE_AD34 13FL CORRIDOR R1310	-	-	-	-	
1040035	SMOKE_AD RM.1309 LIVING ROOM	✓				
1040036	SMOKE_AD RM.1309 BED ROOM	✓				
1040037	HEAT_AD RM.1309 BATH ROOM	✓				
1040038	SMOKE_AD38 13FL CORRIDOR R1309	-	-	-	-	
1040039	SMOKE_AD39 13FL CORRIDOR R1301	-	-	-	-	
1040040	HEAT_AD RM.1308 BATH ROOM	✓				
1040041	SMOKE_AD RM.1308 BED ROOM	✓				
1040042	SMOKE_AD RM.1307 LIVING ROOM	-	-	-	-	
1040043	HEAT_AD RM.1307 BATH ROOM	-	-	-	-	
1040044	SMOKE_AD44 13FL CORRIDOR R1303	-	-	-	-	
1040045	HEAT_AD RM.1306 BATH ROOM	✓				
1040046	SMOKE_AD RM.1306 BED ROOM	✓				
1040047	SMOKE_AD RM.1305 LIVING ROOM	✓				
1040048	SMOKE_AD RM.1305 BED ROOM	✓				
1040049	HEAT_AD RM.1305 BATH ROOM	✓				
1040050	SMOKE_AD RM.1304 LIVING ROOM	✓				
1040051	HEAT_AD RM.1304 BATH ROOM	✓				
1040052	SMOKE_AD52 13FL CORRIDOR R1305	-	-	-	-	
1040053	SMOKE_AD RM.1303 BED ROOM	-	-	-	-	
1040054	HEAT_AD RM.1303 BATH ROOM	-	-	-	-	
1040055	SMOKE_AD RM.1302 BED ROOM	✓				
1040056	HEAT_AD RM.1302 BATH ROOM	✓				
1040057	SMOKE_AD RM.1301 LIVING ROOM	✓				
1040058	HEAT_AD RM.1301 BATH ROOM	✓				
1040059	HEAT_AD60 13FL MAID'S ROOM	-	-	-	-	
1040060	HEAT_AD61 13FL GARBAGE ROOM	-	-	-	-	
1040061	SMOKE_AD62 13FL FIREMAN LIFT	-	-	-	-	
1040062	SMOKE_AD64 13FL ELECTRICAL ROOM	-	-	-	-	
1040063	HEAT_AD65 13FL COMMUNICATION ROOM	-	-	-	-	
1040064	HEAT_AD RM.1420 BATH ROOM	-	-	-	-	
1040065	SMOKE_AD RM.1420 LIVING ROOM	-	-	-	-	
1040066	HEAT_AD RM.1419 BATH ROOM	-	-	-	-	
1040067	SMOKE_AD RM.1419 BED ROOM	-	-	-	-	
1040068	HEAT_AD RM.1418 BATH ROOM	-	-	-	-	
1040069	SMOKE_AD RM.1418 BED ROOM	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1040070	SMOKE_AD RM.1416 BED ROOM	✓				
1040071	SMOKE_AD RM.1417 LIVING ROOM	✓				
1040072	HEAT_AD RM.1417 BATH ROOM	✓				
1040073	HEAT_AD RM.1416 BATH ROOM	✓				
1040074	SMOKE_AD RM.1416 LIVING ROOM	✓				
1040075	SMOKE_AD RM.1415 BED ROOM	✓				
1040076	HEAT_AD RM.1415 BATH ROOM	✓				
1040077	SMOKE_AD14 14FL CORRIDOR R1417	-	-	-	-	
1040078	SMOKE_AD16 14FL CORRIDOR R1419	-	-	-	-	
1040079	HEAT_AD RM.1414 BATH ROOM	✓				
1040080	SMOKE_AD RM.1414 LIVING ROOM	✓				
1040081	SMOKE_AD RM.1414 BED ROOM	✓				
1040082	SMOKE_AD20 14FL CORRIDOR R1413	-	-	-	-	
1040083	SMOKE_AD RM.1413 BED ROOM	-	-	-	-	
1040084	HEAT_AD RM.1413 BATH ROOM	-	-	-	-	
1040085	SMOKE_AD23 14FL PASSENGER LIFT	-	-	-	-	
1040087	HEAT_AD RM.1412 BATH ROOM	✓				
1040088	SMOKE_AD RM.1412 BED ROOM	✓				
1040089	SMOKE_AD28 14FL CORRIDOR R1411-R1412	-	-	-	-	
1040090	HEAT_AD RM.1411 BATH ROOM	-	-	-	-	
1040091	SMOKE_AD RM.1411 BED ROOM	-	-	-	-	
1040092	SMOKE_AD RM.1410 LIVING ROOM	-	-	-	-	
1040093	SMOKE_AD RM.1410 BED ROOM	-	-	-	-	
1040094	HEAT_AD RM.1410 BATH ROOM	-	-	-	-	
1040095	SMOKE_AD34 14FL CORRIDOR R1410	-	-	-	-	
1040096	SMOKE_AD RM.1409 LIVING ROOM	-	-	-	-	
1040097	SMOKE_AD RM.1409 BED ROOM	-	-	-	-	
1040098	HEAT_AD RM.1409 BATH ROOM	-	-	-	-	
1040099	SMOKE_AD38 14FL CORRIDOR R1409	-	-	-	-	
1040100	SMOKE_AD39 14FL CORRIDOR R1401	-	-	-	-	
1040101	HEAT_AD RM.1408 BATH ROOM	-	-	-	-	
1040102	SMOKE_AD RM.1408 BED ROOM	-	-	-	-	
1040103	SMOKE_AD RM.1407 LIVING ROOM	-	-	-	-	
1040104	HEAT_AD RM.1407 BATH ROOM	-	-	-	-	
1040105	SMOKE_AD44 14FL CORRIDOR R1403	-	-	-	-	
1040106	HEAT_AD RM.1406 BATH ROOM	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1040107	SMOKE_AD RM.1406 BED ROOM	✓				
1040108	SMOKE_AD RM.1405 LIVING ROOM	-	-	-	-	
1040109	SMOKE_AD RM.1405 BED ROOM	-	-	-	-	
1040110	HEAT_AD RM.1405 BATH ROOM	-	-	-	-	
1040111	SMOKE_AD RM.1404 LIVING ROOM	✓				
1040112	HEAT_AD RM.1404 BATH ROOM	✓				
1040113	SMOKE_AD52 14FL CORRIDOR R1405	-	-	-	-	
1040114	SMOKE_AD RM.1403 BED ROOM	-	-	-	-	
1040115	HEAT_AD RM.1403 BATH ROOM	-	-	-	-	
1040116	SMOKE_AD RM.1402 BED ROOM	✓				
1040117	HEAT_AD RM.1402 BATH ROOM	✓				
1040118	SMOKE_AD RM.1401 LIVING ROOM	-	-	-	-	
1040119	HEAT_AD RM.1401 BATH ROOM	-	-	-	-	
1040120	HEAT_AD60 14FL MAID'S ROOM	-	-	-	-	
1040121	HEAT_AD61 14FL GARBAGE ROOM	-	-	-	-	
1040122	SMOKE_AD62 14FL FIREMAN LIFT	-	-	-	-	
1040123	SMOKE_AD64 14FL ELECTRICAL ROOM	-	-	-	-	
1040124	HEAT_AD65 14FL COMMUNICATION ROOM	-	-	-	-	
1040126	STROBE_1_13FL	-	-	-	-	
1040127	SPEAKER_1_13FL	-	-	-	-	
1040128	TEL_1_13FL	-	-	-	-	
1040129	STROBE_1_14FL	-	-	-	-	
1040130	SPEAKER_1_14FL	-	-	-	-	
1040131	TEL_1_14FL	-	-	-	-	
1040132	MANUAL_ST3_13FL	-	-	-	-	
1040133	KEY_15_ST3_13FL	-	-	-	-	
1040134	MANUAL_PASSENGER LIFT13FL	-	-	-	-	
1040135	KEY_24_PASSENGER LIFT13FL	-	-	-	-	
1040136	MANUAL_ST1_13FL	-	-	-	-	
1040137	KEY_53_ST1_13FL	-	-	-	-	
1040138	MANUAL_FIREMAN LIFT 13FL	-	-	-	-	
1040139	KEY_63_FIREMAN LIFT 13FL	-	-	-	-	
1040140	MANUAL_ST3_14FL	-	-	-	-	
1040141	KEY_15_ST3_14FL	-	-	-	-	
1040142	MANUAL_PASSENGER LIFT14FL	-	-	-	-	
1040143	KEY_24_PASSENGER LIFT14FL	-	-	-	-	



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1040144	MANUAL_ST1_14FL	-	-	-	-	
1040145	KEY_53_ST1_14FL	-	-	-	-	
1040146	MANUAL_FIREMAN LIFT 14FL	-	-	-	-	
1040147	KEY_63_FIREMAN LIFT 14FL	-	-	-	-	
1040251	IM_15FL	-	-	-	-	
1040252	IM_16FL	-	-	-	-	
1040253	HEAT_AD RM.1520 BATH ROOM	-	-	-	-	
1040254	SMOKE_AD RM.1520 LIVING ROOM	-	-	-	-	
1040255	HEAT_AD RM.1519 BATH ROOM	✓				
1040256	SMOKE_AD RM.1519 BED ROOM	✓				
1040257	HEAT_AD RM.1518 BATH ROOM	✓				
1040258	SMOKE_AD RM.1518 BED ROOM	✓				
1040259	HEAT_AD RM.1517 BATH ROOM	-	-	-	-	
1040260	SMOKE_AD RM.1517 BED ROOM	-	-	-	-	
1040261	HEAT_AD RM.1516 BATH ROOM	✓				
1040262	SMOKE_AD RM.1516 BED ROOM	✓				
1040263	SMOKE_AD RM.1516 LIVING ROOM	✓				
1040264	SMOKE_AD RM.1515 BED ROOM	-	-	-	-	
1040265	HEAT_AD RM.1515 BATH ROOM	-	-	-	-	
1040266	SMOKE_AD14 15FL CORRIDOR R1517	-	-	-	-	
1040267	SMOKE_AD16 15FL CORRIDOR R1519	-	-	-	-	
1040268	HEAT_AD RM.1514 BATH ROOM	✓				
1040269	SMOKE_AD RM.1514 BED ROOM	✓				
1040270	SMOKE_AD RM.1514 LIVING ROOM	✓				
1040271	SMOKE_AD20 15FL CORRIDOR R1513-R1514	-	-	-	-	
1040272	SMOKE_AD RM.1513 BED ROOM	✓				
1040273	HEAT_AD RM.1513 BATH ROOM	✓				
1040274	SMOKE_AD23 15FL PASSENGER LIFT	-	-	-	-	
1040276	HEAT_AD RM.1512 BATH ROOM	-	-	-	-	
1040277	SMOKE_AD RM.1512 BED ROOM	-	-	-	-	
1040278	SMOKE_AD28 15FL CORRIDOR R1511	-	-	-	-	
1040279	HEAT_AD RM.1511 BATH ROOM	✓				
1040280	SMOKE_AD RM.1511 BED ROOM	✓				
1040281	SMOKE_AD RM.1510 LIVING ROOM	✓				
1040282	SMOKE_AD RM.1510 BED ROOM	✓				
1040283	HEAT_AD RM.1510 BATH ROOM	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1040284	SMOKE_AD34 15FL CORRIDOR R1510	-	-	-	-	
1040285	SMOKE_AD RM.1509 LIVING ROOM	-	-	-	-	
1040286	SMOKE_AD RM.1509 BED ROOM	-	-	-	-	
1040287	HEAT_AD RM.1509 BATH ROOM	-	-	-	-	
1040288	SMOKE_AD38 15FL CORRIDOR R1509	-	-	-	-	
1040289	SMOKE_AD39 15FL CORRIDOR R1508	-	-	-	-	
1040290	HEAT_AD RM.1508 BATH ROOM	-	-	-	-	
1040291	SMOKE_AD RM.1508 BED ROOM	-	-	-	-	
1040292	SMOKE_AD RM.1507 LIVING ROOM	✓				
1040293	HEAT_AD RM.1507 BATH ROOM	✓				
1040294	SMOKE_AD44 15FL CORRIDOR R1503	-	-	-	-	
1040295	HEAT_AD RM.1506 BATH ROOM	-	-	-	-	
1040296	SMOKE_AD RM.1506 BED ROOM	-	-	-	-	
1040297	SMOKE_AD RM.1505 LIVING ROOM	✓				
1040298	SMOKE_AD RM.1505 BED ROOM	✓				
1040299	HEAT_AD RM.1505 BATH ROOM	✓				
1040300	SMOKE_AD RM.1504 LIVING ROOM	✓				
1040301	HEAT_AD RM.1504 BATH ROOM	✓				
1040302	SMOKE_AD52 15FL CORRIDOR R1505	-	-	-	-	
1040303	SMOKE_AD RM.1503 BED ROOM	✓				
1040304	HEAT_AD RM.1503 BATH ROOM	✓				
1040305	SMOKE_AD RM.1502 BED ROOM	✓				
1040306	HEAT_AD RM.1502 BATH ROOM	✓				
1040307	SMOKE_AD RM.1501 LIVING ROOM	-	-	-	-	
1040308	HEAT_AD RM.1501 BATH ROOM	-	-	-	-	
1040309	HEAT_AD60 15FL MAID'S ROOM	-	-	-	-	
1040310	HEAT_AD61 15FL GARBAGE ROOM	-	-	-	-	
1040311	SMOKE_AD62 15FL FIREMAN LIFT	-	-	-	-	
1040312	SMOKE_AD64 15FL ELECTRICAL ROOM	-	-	-	-	
1040313	HEAT_AD65 15FL COMMUNICATION ROOM	-	-	-	-	
1040314	HEAT_AD RM.1620 BATH ROOM	✓				
1040315	SMOKE_AD RM.1620 LIVING ROOM	✓				
1040316	HEAT_AD RM.1619 BATH ROOM	✓				
1040317	SMOKE_AD RM.1619 BED ROOM	✓				
1040318	HEAT_AD RM.1618 BATH ROOM	-	-	-	-	
1040319	SMOKE_AD RM.1618 BED ROOM	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1040320	HEAT_AD RM.1617 BATH ROOM	✓				
1040321	SMOKE_AD RM.1617 BED ROOM	✓				
1040322	HEAT_AD RM.1616 BATH ROOM	-	-	-	-	
1040323	SMOKE_AD RM.1616 BED ROOM	-	-	-	-	
1040324	SMOKE_AD RM.1616 LIVING ROOM	-	-	-	-	
1040325	SMOKE_AD RM.1615 BED ROOM	✓				
1040326	HEAT_AD RM.1615 BATH ROOM	✓				
1040327	SMOKE_AD14 16FL CORRIDOR R1617	-	-	-	-	
1040328	SMOKE_AD16 16FL CORRIDOR R1619	-	-	-	-	
1040329	HEAT_AD RM.1614 BATH ROOM	-	-	-	-	
1040330	SMOKE_AD RM.1614 BED ROOM	-	-	-	-	
1040331	SMOKE_AD RM.1614 LIVING ROOM	-	-	-	-	
1040332	SMOKE_AD20 16FL CORRIDOR R1620	-	-	-	-	
1040333	SMOKE_AD RM.1613 BED ROOM	✓				
1040334	HEAT_AD RM.1613 BATH ROOM	✓				
1040335	SMOKE_AD23 16FL PASSENGER LIFT	-	-	-	-	
1040336	HEAT_AD25 16FL TOILET	-	-	-	-	
1040337	HEAT_AD RM.1612 BATH ROOM	✓				
1040338	SMOKE_AD RM.1612 BED ROOM	✓				
1040339	SMOKE_AD28 16FL CORRIDOR R1611	-	-	-	-	
1040340	SMOKE_AD RM.1611 BATH ROOM	-	-	-	-	
1040341	HEAT_AD RM.1611 BED ROOM	-	-	-	-	
1040342	SMOKE_AD RM.1610 LIVING ROOM	✓				
1040343	SMOKE_AD RM.1610 BED ROOM	✓				
1040344	HEAT_AD RM.1610 BATH ROOM	✓				
1040345	SMOKE_AD34 16FL CORRIDOR R1610	-	-	-	-	
1040346	SMOKE_AD RM.1609 LIVING ROOM	✓				
1040347	SMOKE_AD RM.1609 BED ROOM	✓				
1040348	HEAT_AD RM.1609 BATH ROOM	✓				
1040349	SMOKE_AD38 16FL CORRIDOR R1609	-	-	-	-	
1040350	SMOKE_AD39 16FL CORRIDOR R1601	-	-	-	-	
1040351	HEAT_AD RM.1608 BATH ROOM	-	-	-	-	
1040352	SMOKE_AD RM.1608 BED ROOM	-	-	-	-	
1040353	SMOKE_AD RM.1607 LIVING ROOM	✓				
1040354	HEAT_AD RM.1607 BATH ROOM	✓				
1040355	SMOKE_AD44 16FL CORRIDOR R1603	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1040356	HEAT_AD RM.1606 BATH ROOM	✓				
1040357	SMOKE_AD RM.1606 BED ROOM	✓				
1040358	SMOKE_AD RM.1605 LIVING ROOM	-	-	-	-	
1040359	SMOKE_AD RM.1605 BED ROOM	-	-	-	-	
1040360	HEAT_AD RM.1605 BATH ROOM	-	-	-	-	
1040361	SMOKE_AD RM.1604 LIVING ROOM	✓				
1040362	HEAT_AD RM.1604 BATH ROOM	✓				
1040363	SMOKE_AD52 16FL CORRIDOR R1605	-	-	-	-	
1040364	SMOKE_AD RM.1603 BED ROOM	✓				
1040365	HEAT_AD RM.1603 BATH ROOM	✓				
1040366	SMOKE_AD RM.1602 BED ROOM	✓				
1040367	HEAT_AD RM.1602 BATH ROOM	✓				
1040368	SMOKE_AD RM.1601 LIVING ROOM	✓				
1040369	HEAT_AD RM.1601 BATH ROOM	✓				
1040370	HEAT_AD60 16FL MAID'S ROOM	-	-	-	-	
1040371	HEAT_AD61 16FL GARBAGE ROOM	-	-	-	-	
1040372	SMOKE_AD62 16FL FIREMAN LIFT	-	-	-	-	
1040373	SMOKE_AD64 16FL ELECTRICAL ROOM	-	-	-	-	
1040374	HEAT_AD65 16FL COMMUNICATION ROOM	-	-	-	-	
1040376	STROBE_1_15FL	-	-	-	-	
1040377	SPEAKER_1_15FL	-	-	-	-	
1040378	TEL_1_15FL	-	-	-	-	
1040379	DZ_1_16FL	-	-	-	-	
1040380	DZ_2_16FL	-	-	-	-	
1040381	ZONE_ST1_FLOOR 16-27	-	-	-	-	
1040382	ZONE_ST3_FLOOR 16-27	-	-	-	-	
1040383	STROBE_1_16FL	-	-	-	-	
1040384	STROBE_2_16FL	-	-	-	-	
1040385	STROBE_3_16FL	-	-	-	-	
1040386	STROBE_ST1_16FL	-	-	-	-	
1040387	STROBE_ST3_16FL	-	-	-	-	
1040388	SPEAKER_1_16FL	-	-	-	-	
1040389	SPEAKER_2_16FL	-	-	-	-	
1040390	SPEAKER_3_16FL	-	-	-	-	
1040391	SPEAKER_ST1_16FL	-	-	-	-	
1040392	SPEAKER_ST3_16FL	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569						
โครงการ Somerset Rama9 Bangkok						
Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1040393	TEL_1_16FL	-	-	-	-	
1040394	TEL_ST1_16FL	-	-	-	-	
1040395	TEL_ST3_16FL	-	-	-	-	
1040396	MANUAL_ST3_15FL	-	-	-	-	
1040397	KEY_15_ST3_15FL	-	-	-	-	
1040398	MANUAL_PASSENGER LIFT15FL	-	-	-	-	
1040399	KEY_24_PASSENGER LIFT15FL	-	-	-	-	
1040400	MANUAL_ST1_15FL	-	-	-	-	
1040401	KEY_53_ST1_15FL	-	-	-	-	
1040402	MANUAL_FIREMAN LIFT 15FL	-	-	-	-	
1040403	KEY_63_FIREMAN LIFT 15FL	-	-	-	-	
1040404	MANUAL_ST3_16FL	-	-	-	-	
1040405	KEY_15_ST3_16FL	-	-	-	-	
1040406	MANUAL_PASSENGER LIFT16FL	-	-	-	-	
1040407	KEY_24_PASSENGER LIFT16FL	-	-	-	-	
1040408	MANUAL_ST1_16FL	-	-	-	-	
1040409	KEY_53_ST1_16FL	-	-	-	-	
1040410	MANUAL_FIREMAN LIFT 16FL	-	-	-	-	
1040411	KEY_63_FIREMAN LIFT 16FL	-	-	-	-	
1050001	IM_17FL	-	-	-	-	
1050002	IM_18FL	-	-	-	-	
1050003	HEAT_AD RM.1720 BATH ROOM	-	-	-	-	
1050004	SMOKE_AD RM.1720 LIVING ROOM	-	-	-	-	
1050005	HEAT_AD RM.1719 BATH ROOM	✓				
1050006	SMOKE_AD RM.1719 BED ROOM	✓				
1050007	HEAT_AD RM.1718 BATH ROOM	✓				
1050008	SMOKE_AD RM.1718 BED ROOM	✓				
1050009	SMOKE_AD RM.1716 BED ROOM	-	-	-	-	
1050010	SMOKE_AD RM.1717 BED ROOM	-	-	-	-	
1050011	HEAT_AD RM.1716 BATH ROOM	-	-	-	-	
1050012	HEAT_AD RM.1717 BATH ROOM	-	-	-	-	
1050013	SMOKE_AD RM.1716 LIVING ROOM	-	-	-	-	
1050014	SMOKE_AD RM.1715 BED ROOM	✓				
1050015	HEAT_AD RM.1715 BATH ROOM	✓				
1050016	SMOKE_AD14 17FL CORRIDOR R1716	-	-	-	-	
1050017	SMOKE_AD16 17FL CORRIDOR R1719	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1050018	HEAT_AD RM.1714 BATH ROOM	-	-	-	-	
1050019	SMOKE_AD RM.1714 BED ROOM	-	-	-	-	
1050020	SMOKE_AD RM.1714 LIVING ROOM	-	-	-	-	
1050021	SMOKE_AD20 17FL CORRIDOR R1713	-	-	-	-	
1050022	SMOKE_AD RM.1713 BED ROOM	✓				
1050023	HEAT_AD RM.1713 BATH ROOM	✓				
1050024	SMOKE_AD23 17FL PASSENGER LIFT	-	-	-	-	
1050026	HEAT_AD RM.1712 BATH ROOM	-	-	-	-	
1050027	SMOKE_AD RM.1712 BED ROOM	-	-	-	-	
1050028	SMOKE_AD28 17FL CORRIDOR R1711	-	-	-	-	
1050029	HEAT_AD RM.1711 BATH ROOM	✓				
1050030	SMOKE_AD RM.1711 BED ROOM	✓				
1050031	SMOKE_AD RM.1710 LIVING ROOM	✓				
1050032	SMOKE_AD RM.1710 BED ROOM	✓				
1050033	HEAT_AD RM.1710 BATH ROOM	✓				
1050034	SMOKE_AD34 17FL CORRIDOR R1710	-	-	-	-	
1050035	SMOKE_AD RM.1709 LIVING ROOM	✓				
1050036	SMOKE_AD RM.1709 BED ROOM	✓				
1050037	HEAT_AD RM.1709 BATH ROOM	✓				
1050038	SMOKE_AD38 17FL CORRIDOR R1709	-	-	-	-	
1050039	SMOKE_AD39 17FL CORRIDOR R1701	-	-	-	-	
1050040	HEAT_AD RM.1708 BATH ROOM	✓				
1050041	SMOKE_AD RM.1708 BED ROOM	✓				
1050042	SMOKE_AD RM.1707 LIVING ROOM	-	-	-	-	
1050043	HEAT_AD RM.1707 BATH ROOM	-	-	-	-	
1050044	SMOKE_AD44 17FL CORRIDOR R1703	-	-	-	-	
1050045	HEAT_AD RM.1706 BATH ROOM	-	-	-	-	
1050046	SMOKE_AD RM.1706 BED ROOM	-	-	-	-	
1050047	SMOKE_AD RM.1705 LIVING ROOM	✓				
1050048	SMOKE_AD RM.1705 BED ROOM	✓				
1050049	HEAT_AD RM.1705 BATH ROOM	✓				
1050050	SMOKE_AD RM.1704 LIVING ROOM	-	-	-	-	
1050051	HEAT_AD RM.1704 BATH ROOM	-	-	-	-	
1050052	SMOKE_AD52 17FL CORRIDOR R1705	-	-	-	-	
1050053	SMOKE_AD RM.1703 BED ROOM	✓				
1050054	HEAT_AD RM.1703 BATH ROOM	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1050055	SMOKE_AD RM.1702 BED ROOM	✓				
1050056	HEAT_AD RM.1702 BATH ROOM	✓				
1050057	SMOKE_AD RM.1701 LIVING ROOM	✓				
1050058	HEAT_AD RM.1701 BATH ROOM	✓				
1050059	HEAT_AD60 17FL MAID'S ROOM	-	-	-	-	
1050060	HEAT_AD61 17FL GARBAGE ROOM	-	-	-	-	
1050061	SMOKE_AD62 17FL FIREMAN LIFT	-	-	-	-	
1050062	SMOKE_AD64 17FL ELECTRICAL ROOM	-	-	-	-	
1050063	HEAT_AD65 17FL COMMUNICATION ROOM	-	-	-	-	
1050064	HEAT_AD RM.1820 BATH ROOM	✓				
1050065	SMOKE_AD RM.1820 LIVING ROOM	✓				
1050066	HEAT_AD RM.1819 BATH ROOM	-	-	-	-	
1050067	SMOKE_AD RM.1819 BED ROOM	-	-	-	-	
1050068	HEAT_AD RM.1818 BATH ROOM	✓				
1050069	SMOKE_AD RM.1818 BED ROOM	✓				
1050070	HEAT_AD RM.1817 BATH ROOM	✓				
1050071	SMOKE_AD RM.1817 BED ROOM	✓				
1050072	HEAT_AD RM.1816 BATH ROOM	-	-	-	-	
1050073	SMOKE_AD RM.1816 BED ROOM	-	-	-	-	
1050074	SMOKE_AD RM.1816 LIVING ROOM	-	-	-	-	
1050075	SMOKE_AD RM.1815 BED ROOM	-	-	-	-	
1050076	HEAT_AD RM.1815 BATH ROOM	-	-	-	-	
1050077	SMOKE_AD14 18FL CORRIDOR R1817	-	-	-	-	
1050078	SMOKE_AD16 18FL CORRIDOR R1819	-	-	-	-	
1050079	HEAT_AD RM.1814 BATH ROOM	-	-	-	-	
1050080	SMOKE_AD RM.1814 BED ROOM	-	-	-	-	
1050081	SMOKE_AD RM.1814 LIVING ROOM	-	-	-	-	
1050082	SMOKE_AD20 18FL CORRIDOR R1820	-	-	-	-	
1050083	SMOKE_AD RM.1813 BED ROOM	✓				
1050084	HEAT_AD RM.1813 BATH ROOM	✓				
1050085	SMOKE_AD23 18FL PASSENGER LIFT	-	-	-	-	
1050087	SMOKE_AD RM.1809 LIVING ROOM	✓				
1050088	HEAT_AD RM.1812 BATH ROOM	-	-	-	-	
1050089	SMOKE_AD28 18FL CORRIDOR R1811	-	-	-	-	
1050090	SMOKE_AD RM.1812 BED ROOM	-	-	-	-	
1050091	HEAT_AD RM.1811 BATH ROOM	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1050092	SMOKE_AD RM.1810 LIVING ROOM	-	-	-	-	
1050093	SMOKE_AD RM.1810 BED ROOM	-	-	-	-	
1050094	HEAT_AD RM.1810 BATH ROOM	-	-	-	-	
1050095	SMOKE_AD34 18FL CORRIDOR R1810	-	-	-	-	
1050096	SMOKE_AD RM.1811 BED ROOM	✓				
1050097	SMOKE_AD RM.1809 BED ROOM	✓				
1050098	HEAT_AD RM.1809 BATH ROOM	✓				
1050099	SMOKE_AD38 18FL CORRIDOR R1809	-	-	-	-	
1050100	SMOKE_AD39 18FL CORRIDOR R1808	-	-	-	-	
1050101	HEAT_AD RM.1808 BATH ROOM	-	-	-	-	
1050102	SMOKE_AD RM.1808 BED ROOM	-	-	-	-	
1050103	SMOKE_AD RM.1807 LIVING ROOM	-	-	-	-	
1050104	HEAT_AD RM.1807 BATH ROOM	-	-	-	-	
1050105	SMOKE_AD44 18FL CORRIDOR R1803	-	-	-	-	
1050106	HEAT_AD RM.1806 BATH ROOM	-	-	-	-	
1050107	SMOKE_AD RM.1806 BED ROOM	-	-	-	-	
1050108	SMOKE_AD RM.1805 LIVING ROOM	✓				
1050109	SMOKE_AD RM.1805 BED ROOM	✓				
1050110	HEAT_AD RM.1805 BATH ROOM	✓				
1050111	SMOKE_AD RM.1804 LIVING ROOM	✓				
1050112	HEAT_AD RM.1804 BATH ROOM	✓				
1050113	SMOKE_AD52 18FL CORRIDOR R1805	-	-	-	-	
1050114	SMOKE_AD RM.1803 BED ROOM	✓				
1050115	HEAT_AD RM.1803 BATH ROOM	✓				
1050116	SMOKE_AD RM.1802 BED ROOM	✓				
1050117	HEAT_AD RM.1802 BATH ROOM	✓				
1050118	SMOKE_AD RM.1801 LIVING ROOM	✓				
1050119	HEAT_AD RM.1801 BATH ROOM	✓				
1050120	HEAT_AD60 18FL MAID'S ROOM	-	-	-	-	
1050121	HEAT_AD61 18FL GARBAGE ROOM	-	-	-	-	
1050122	SMOKE_AD62 18FL FIREMAN LIFT	-	-	-	-	อุปกรณ์เสีย
1050123	SMOKE_AD64 18FL ELECTRICAL ROOM	-	-	-	-	
1050124	HEAT_AD65 18FL COMMUNICATION ROOM	-	-	-	-	
1050126	STROBE_1_17FL	-	-	-	-	
1050127	SPEAKER_1_17FL	-	-	-	-	
1050128	TEL_1_17FL	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569						
โครงการ Somerset Rama9 Bangkok						
Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1050129	STROBE_1_18FL	-	-	-	-	
1050130	SPEAKER_1_18FL	-	-	-	-	
1050131	TEL_1_18FL	-	-	-	-	
1050132	MANUAL_ST3_17FL	-	-	-	-	
1050133	KEY_15_ST3_17FL	-	-	-	-	
1050134	MANUAL_PASSENGER LIFT17FL	-	-	-	-	
1050135	KEY_24_PASSENGER LIFT17FL	-	-	-	-	
1050136	MANUAL_ST1_17FL	-	-	-	-	
1050137	KEY_53_ST1_17FL	-	-	-	-	
1050138	MANUAL_FIREMAN LIFT 17FL	-	-	-	-	
1050139	KEY_63_FIREMAN LIFT 17FL	-	-	-	-	
1050140	MANUAL_ST3_18FL	-	-	-	-	
1050141	KEY_15_ST3_18FL	-	-	-	-	
1050142	MANUAL_PASSENGER LIFT18FL	-	-	-	-	
1050143	KEY_24_PASSENGER LIFT18FL	-	-	-	-	
1050144	MANUAL_ST1_18FL	-	-	-	-	
1050145	KEY_53_ST1_18FL	-	-	-	-	
1050146	MANUAL_FIREMAN LIFT 18FL	-	-	-	-	
1050147	KEY_63_FIREMAN LIFT 18FL	-	-	-	-	
1050251	IM_1_19FL	-	-	-	-	
1050252	IM_1_20FL	-	-	-	-	
1050253	HEAT_AD RM.1920 BATH ROOM	-	-	-	-	
1050254	SMOKE_AD RM.1920 LIVING ROOM	-	-	-	-	
1050255	HEAT_AD RM.1919 BATH ROOM	-	-	-	-	
1050256	SMOKE_AD RM.1919 BED ROOM	-	-	-	-	
1050257	HEAT_AD RM.1918 BATH ROOM	✓				
1050258	SMOKE_AD RM.1918 BED ROOM	✓				
1050259	HEAT_AD RM.1917 BATH ROOM	-	-	-	-	
1050260	SMOKE_AD RM.1917 BED ROOM	-	-	-	-	
1050261	HEAT_AD RM.1916 BATH ROOM	-	-	-	-	
1050262	SMOKE_AD RM.1916 BED ROOM	-	-	-	-	
1050263	SMOKE_AD RM.1916 LIVING ROOM	-	-	-	-	
1050264	SMOKE_AD RM.1915 BED ROOM	✓				
1050265	HEAT_AD RM.1915 BATH ROOM	✓				
1050266	SMOKE_AD14 19FL CORRIDOR R1917	-	-	-	-	
1050267	SMOKE_AD16 19FL CORRIDOR R1919	-	-	-	-	



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1050268	HEAT_AD RM.1914 BATH ROOM	-	-	-	-	
1050269	SMOKE_AD RM.1914 BED ROOM	-	-	-	-	
1050270	SMOKE_AD RM.1914 LIVING ROOM	-	-	-	-	
1050271	SMOKE_AD20 19FL CORRIDOR R1920	-	-	-	-	
1050272	SMOKE_AD RM.1913 BED ROOM	✓				
1050273	HEAT_AD RM.1913 BATH ROOM	✓				
1050274	SMOKE_AD64 19FL ELECTRICAL ROOM	-	-	-	-	
1050275	HEAT AD25 19FL TOILET	-	-	-	-	
1050276	HEAT_AD RM.1912 BATH ROOM	-	-	-	-	
1050277	SMOKE_AD RM.1912 BED ROOM	-	-	-	-	
1050278	SMOKE_AD28 19FL CORRIDOR R1911	-	-	-	-	
1050279	SMOKE_AD RM.1909 BED ROOM	✓				
1050280	SMOKE_AD RM.1911 BED ROOM	-	-	-	-	
1050281	SMOKE_AD RM.1910 LIVING ROOM	✓				
1050282	SMOKE_AD RM.1910 BED ROOM	✓				
1050283	HEAT_AD RM.1910 BATH ROOM	✓				
1050284	SMOKE_AD34 19FL CORRIDOR R1910	-	-	-	-	
1050285	HEAT_AD RM.2015 BATH ROOM	✓				
1050286	HEAT_AD RM.1911 BATH ROOM	-	-	-	-	
1050287	HEAT_AD RM.1909 BATH ROOM	✓				
1050288	SMOKE_AD38 19FL CORRIDOR R1909	-	-	-	-	
1050289	SMOKE_AD39 19FL CORRIDOR R1908	-	-	-	-	
1050290	HEAT_AD RM.1908 BATH ROOM	✓				
1050291	SMOKE_AD RM.1908 BED ROOM	✓				
1050292	HEAT_AD65 20FL COMMUNICATION ROOM	-	-	-	-	
1050293	HEAT_AD RM.1907 BATH ROOM	-	-	-	-	
1050294	SMOKE_AD44 19FL CORRIDOR R1903	-	-	-	-	
1050295	HEAT_AD RM.1906 BATH ROOM	✓				
1050296	SMOKE_AD RM.1906 BED ROOM	✓				
1050297	SMOKE_AD RM.1905 LIVING ROOM	✓				
1050298	SMOKE_AD RM.1905 BED ROOM	✓				
1050299	HEAT_AD RM.1905 BATH ROOM	✓				
1050300	SMOKE_AD RM.1904 LIVING ROOM	✓				
1050301	HEAT_AD RM.1904 BATH ROOM	✓				
1050302	SMOKE_AD52 19FL CORRIDOR R1905	-	-	-	-	
1050303	SMOKE_AD RM.1903 BED ROOM	-	-	-	-	



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1050304	HEAT_AD RM.19203 BATH ROOM	-	-	-	-	
1050305	SMOKE_AD RM.1902 BED ROOM	✓				
1050306	HEAT_AD RM.1902 BATH ROOM	✓				
1050307	SMOKE_AD RM.1901 LIVING ROOM	-	-	-	-	
1050308	HEAT_AD RM.1901 BATH ROOM	-	-	-	-	
1050309	HEAT_AD60 19FL MAID'S ROOM	-	-	-	-	
1050310	SMOKE_AD62 19FL FIREMAN LIFT	-	-	-	-	
1050311	HEAT_AD61 19FL GARBAGE ROOM	-	-	-	-	
1050312	SMOKE_AD23 19FL PASSENGER LIFT	-	-	-	-	
1050313	SMOKE_AD RM.1909 LIVING ROOM	✓				
1050314	HEAT_AD RM.2020 BATH ROOM	✓				
1050315	SMOKE_AD RM.2020 LIVING ROOM	✓				
1050316	HEAT_AD RM.2019 BATH ROOM	✓				
1050317	SMOKE_AD RM.2019 BED ROOM	✓				
1050318	HEAT_AD RM.2018 BATH ROOM	✓				
1050319	SMOKE_AD RM.2018 BED ROOM	✓				
1050320	HEAT_AD RM.2017 BATH ROOM	✓				
1050321	SMOKE_AD RM.2017 BED ROOM	✓				
1050322	HEAT_AD RM.2016 BATH ROOM	-	-	-	-	
1050323	SMOKE_AD RM.2016 BED ROOM	-	-	-	-	
1050324	SMOKE_AD RM.2016 LIVING ROOM	-	-	-	-	
1050325	SMOKE_AD RM.2015 BED ROOM	✓				
1050326	HEAT_AD65 19FL COMMUNICATION ROOM	-	-	-	-	
1050327	SMOKE_AD14 20 CORRIDOR R2017	-	-	-	-	
1050328	SMOKE_AD16 20FL CORRIDOR R2019	-	-	-	-	
1050329	HEAT_AD RM.2014 BATH ROOM	✓				
1050330	SMOKE_AD RM.2014 BED ROOM	✓				
1050331	SMOKE_AD RM.2014 LIVING ROOM	✓				
1050332	SMOKE_AD20 20FL CORRIDOR R2020	-	-	-	-	
1050333	SMOKE_AD RM.2013 BED ROOM	-	-	-	-	
1050334	HEAT_AD RM.2013 BATH ROOM	-	-	-	-	
1050335	SMOKE_AD23 20FL PASSENGER LIFT	-	-	-	-	
1050337	HEAT_AD RM.2012 BATH ROOM	-	-	-	-	
1050338	SMOKE_AD28 20FL CORRIDOR R2011	-	-	-	-	
1050339	HEAT_AD RM.2011 BATH ROOM	✓				
1050340	SMOKE_AD RM.2011 BED ROOM	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1050341	SMOKE_AD RM.2012 BED ROOM	-	-	-	-	
1050342	SMOKE_AD RM.2010 LIVING ROOM	-	-	-	-	
1050343	SMOKE_AD RM.2010 BED ROOM	-	-	-	-	
1050344	HEAT_AD RM.2010 BATH ROOM	-	-	-	-	
1050345	SMOKE_AD34 20FL CORRIDOR	-	-	-	-	
1050346	SMOKE_AD RM.2009 LIVING ROOM	✓				
1050347	SMOKE_AD RM.2009 BED ROOM	✓				
1050348	HEAT_AD RM.2009 BATH ROOM	✓				
1050349	SMOKE_AD38 20FL CORRIDOR R2009	-	-	-	-	
1050350	SMOKE_AD39 20FL CORRIDOR R2008	-	-	-	-	
1050351	HEAT_AD RM.2008 BATH ROOM	✓				
1050352	SMOKE_AD RM.2008 BED ROOM	✓				
1050353	SMOKE_AD RM.2007 LIVING ROOM	-	-	-	-	
1050354	HEAT_AD RM.2007 BATH ROOM	-	-	-	-	
1050355	SMOKE_AD44 20FL CORRIDOR R2003	-	-	-	-	
1050356	HEAT_AD RM.2006 BATH ROOM	✓				
1050357	SMOKE_AD RM.2006 BED ROOM	✓				
1050358	SMOKE_AD RM.2005 LIVING ROOM	✓				
1050359	SMOKE_AD RM.2005 BED ROOM	✓				
1050360	HEAT_AD RM.2005 BATH ROOM	✓				
1050361	SMOKE_AD RM.2004 LIVING ROOM	✓				
1050362	HEAT_AD RM.2004 BATH ROOM	✓				
1050363	SMOKE_AD52 20FL CORRIDOR R2005	-	-	-	-	
1050364	SMOKE_AD RM.2003 BED ROOM	-	-	-	-	
1050365	HEAT_AD RM.2003 BATH ROOM	-	-	-	-	
1050366	SMOKE_AD RM.2002 BED ROOM	-	-	-	-	
1050367	HEAT_AD RM.2002 BATH ROOM	-	-	-	-	
1050368	SMOKE_AD RM.2001 LIVING ROOM	✓				
1050369	HEAT_AD RM.2001 BATH ROOM	✓				
1050370	HEAT_AD60 20FL MAID'S ROOM	-	-	-	-	
1050371	HEAT_AD61 20FL GARBAGE ROOM	-	-	-	-	
1050372	SMOKE_AD62 20FL FIREMAN LIFT	-	-	-	-	
1050373	SMOKE_AD64 20FL ELECTRICAL ROOM	-	-	-	-	
1050374	SMOKE_AD RM.1907 LIVING ROOM	-	-	-	-	
1050376	STROBE_1_19FL	-	-	-	-	
1050377	SPEAKER_1_19FL	-	-	-	-	



บริษัท ดียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1050378	TEL_1_19FL	-	-	-	-	
1050379	STROBE_1_20FL	-	-	-	-	
1050380	SPEAKER_1_20FL	-	-	-	-	
1050381	TEL_1_20FL	-	-	-	-	
1050382	MANUAL_ST3_19FL	-	-	-	-	
1050383	KEY_15_ST3_19FL	-	-	-	-	
1050384	MANUAL_PASSENGER LIFT19FL	-	-	-	-	
1050385	KEY_24_PASSENGER LIFT19FL	-	-	-	-	
1050386	MANUAL_ST1_19FL	-	-	-	-	
1050387	KEY_53_ST1_19FL	-	-	-	-	
1050388	MANUAL_FIREMAN LIFT 19FL	-	-	-	-	
1050389	KEY_63_FIREMAN LIFT 19FL	-	-	-	-	
1050390	MANUAL_ST3_20FL	-	-	-	-	
1050391	KEY_15_ST3_20FL	-	-	-	-	
1050392	MANUAL_PASSENGER LIFT20FL	-	-	-	-	
1050393	KEY_24_PASSENGER LIFT20FL	-	-	-	-	
1050394	MANUAL_ST1_20FL	-	-	-	-	
1050395	KEY_53_ST1_20FL	-	-	-	-	
1050396	MANUAL_FIREMAN LIFT 20FL	-	-	-	-	
1050397	KEY_63_FIREMAN LIFT 20FL	-	-	-	-	
1070001	IM_21FL	-	-	-	-	
1070002	IM_22FL	-	-	-	-	
1070003	HEAT_AD RM.2120 BATH ROOM	-	-	-	-	
1070004	SMOKE_AD RM.2120 LIVING ROOM	-	-	-	-	
1070005	SMOKE_AD RM.2115 BED ROOM	✓				
1070006	SMOKE_AD RM.2119 BED ROOM	✓				
1070007	HEAT_AD RM.2118 BATH ROOM	✓				
1070008	SMOKE_AD RM.2118 BED ROOM	✓				
1070009	HEAT_AD RM.2117 BATH ROOM	-	-	-	-	
1070010	SMOKE_AD RM.2117 BED ROOM	-	-	-	-	
1070011	HEAT_AD RM.2116 BATH ROOM	-	-	-	-	
1070012	SMOKE_AD RM.2116 BED ROOM	-	-	-	-	
1070013	SMOKE_AD RM.2116 LIVING ROOM	-	-	-	-	
1070014	HEAT_AD RM.2115 BATH ROOM	✓				
1070015	HEAT_AD RM.2119 BATH ROOM	✓				
1070016	SMOKE_AD14 21FL CORRIDOR R2117	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1070017	SMOKE_AD16 21FL CORRIDOR R2119	-	-	-	-	
1070018	HEAT_AD RM.2114 BATH ROOM	-	-	-	-	
1070019	SMOKE_AD RM.2114 BED ROOM	-	-	-	-	
1070020	SMOKE_AD RM.2114 LIVING ROOM	-	-	-	-	
1070021	SMOKE_AD20 21FL CORRIDOR R2120	-	-	-	-	
1070022	SMOKE_AD RM.2113 BED ROOM	-	-	-	-	
1070023	HEAT_AD RM.2113 BATH ROOM	-	-	-	-	
1070024	SMOKE_AD23 21FL PASSENGER LIFT	-	-	-	-	
1070025	SMOKE_AD RM.2212 BED ROOM	✓				
1070026	HEAT_AD RM.2112 BATH ROOM	✓				
1070027	SMOKE_AD RM.2112 BED ROOM	✓				
1070028	SMOKE_AD28 21FL CORRIDOR R2111	-	-	-	-	
1070029	HEAT_AD RM.2111 BATH ROOM	✓				
1070030	SMOKE_AD RM.2111 BED ROOM	✓				
1070031	SMOKE_AD RM.2110 LIVING ROOM	✓				
1070032	SMOKE_AD RM.2110 BED ROOM	✓				
1070033	HEAT_AD RM.2110 BATH ROOM	✓				
1070034	SMOKE_AD34 21FL CORRIDOR R2110	-	-	-	-	
1070035	SMOKE_AD RM.2109 LIVING ROOM	-	-	-	-	
1070036	SMOKE_AD RM.2109 BED ROOM	-	-	-	-	
1070037	HEAT_AD RM.2109 BATH ROOM	-	-	-	-	
1070038	SMOKE_AD38 21FL CORRIDOR R2109	-	-	-	-	
1070039	SMOKE_AD39 21FL CORRIDOR R2108	-	-	-	-	
1070040	HEAT_AD RM.2108 BATH ROOM	-	-	-	-	
1070041	SMOKE_AD RM.2108 BED ROOM	-	-	-	-	
1070042	SMOKE_AD RM.2107 LIVING ROOM	✓				
1070043	HEAT_AD RM.2107 BATH ROOM	✓				
1070044	SMOKE_AD44 21FL CORRIDOR R2103	-	-	-	-	
1070045	HEAT_AD RM.2106 BATH ROOM	✓				
1070046	SMOKE_AD RM.2106 BED ROOM	✓				
1070047	SMOKE_AD RM.2105 LIVING ROOM	✓				
1070048	SMOKE_AD RM.2105 BED ROOM	✓				
1070049	HEAT_AD RM.2105 BATH ROOM	✓				
1070050	SMOKE_AD RM.2104 LIVING ROOM	✓				
1070051	HEAT_AD RM.2104 BATH ROOM	✓				
1070052	SMOKE_AD52 21FL CORRIDOR R2105	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1070053	SMOKE_AD RM.2103 BED ROOM	-	-	-	-	
1070054	HEAT_AD RM.2103 BATH ROOM	-	-	-	-	
1070055	SMOKE_AD RM.2102 BED ROOM	✓				
1070056	HEAT_AD RM.2102 BATH ROOM	✓				
1070057	SMOKE_AD RM.2101 LIVING ROOM	-	-	-	-	
1070058	HEAT_AD RM.2101 BATH ROOM	-	-	-	-	
1070059	HEAT_AD60 21FL MAID'S ROOM	-	-	-	-	
1070060	HEAT_AD61 21FL GARBAGE ROOM	-	-	-	-	
1070061	SMOKE_AD62 21FL FIREMAN LIFT	-	-	-	-	
1070062	SMOKE_AD64 21FL ELECTRICAL ROOM	-	-	-	-	
1070063	HEAT_AD65 21FL COMMUNICATION ROOM	-	-	-	-	
1070064	HEAT_AD RM.2220 BATH ROOM	-	-	-	-	
1070065	SMOKE_AD RM.2220 LIVING ROOM	-	-	-	-	
1070066	HEAT_AD RM.2219 BATH ROOM	✓				
1070067	SMOKE_AD RM.2219 BED ROOM	✓				
1070068	HEAT_AD RM.2218 BATH ROOM	-	-	-	-	
1070069	SMOKE_AD RM.2218 BED ROOM	-	-	-	-	
1070070	SMOKE_AD62 22FL FIREMAN LIFT	-	-	-	-	
1070071	SMOKE_AD RM.2217 LIVING ROOM	✓				
1070072	HEAT_AD RM.2216 BATH ROOM	-	-	-	-	
1070073	SMOKE_AD RM.2216 BED ROOM	-	-	-	-	
1070074	SMOKE_AD RM.2216 LIVING ROOM	-	-	-	-	
1070075	SMOKE_AD RM.2215 BED ROOM	✓				
1070076	HEAT_AD RM.2215 BATH ROOM	✓				
1070077	SMOKE_AD14 22FL CORRIDOR R2217	-	-	-	-	
1070078	SMOKE_AD16 22FL CORRIDOR R2219	-	-	-	-	
1070079	HEAT_AD RM.2214 BATH ROOM	-	-	-	-	
1070080	SMOKE_AD RM.2214 BED ROOM	-	-	-	-	
1070081	SMOKE_AD RM.2214 LIVING ROOM	-	-	-	-	
1070082	SMOKE_AD20 22FL CORRIDOR R2220	-	-	-	-	
1070083	SMOKE_AD RM.2213 BED ROOM	✓				
1070084	HEAT_AD RM.2213 BATH ROOM	✓				
1070085	SMOKE_AD23 22FL PASSENGER LIFT	-	-	-	-	
1070087	HEAT_AD RM.2217 BATH ROOM	✓				
1070088	HEAT_AD RM.2212 BATH ROOM	✓				
1070089	SMOKE_AD28 22FL CORRIDOR R2211	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1070090	HEAT_AD RM.2211 BATH ROOM	-	-	-	-	
1070091	SMOKE_AD RM.2211 BED ROOM	-	-	-	-	
1070092	SMOKE_AD RM.2210 LIVING ROOM	-	-	-	-	
1070093	SMOKE_AD RM.2210 BED ROOM	-	-	-	-	
1070094	HEAT_AD RM.2210 BATH ROOM	-	-	-	-	
1070095	SMOKE_AD34 22FL CORRIDOR R2210	-	-	-	-	
1070096	SMOKE_AD RM.2209 LIVING ROOM	-	-	-	-	
1070097	SMOKE_AD RM.2209 BED ROOM	-	-	-	-	
1070098	HEAT_AD RM.2209 BATH ROOM	-	-	-	-	
1070099	SMOKE_AD38 22FL CORRIDOR R2209	-	-	-	-	
1070100	SMOKE_AD39 22FL CORRIDOR R2208	-	-	-	-	
1070101	HEAT_AD RM.2208 BATH ROOM	✓				
1070102	SMOKE_AD RM.2208 BED ROOM	✓				
1070103	SMOKE_AD RM.2207 LIVING ROOM	-	-	-	-	
1070104	HEAT_AD RM.2207 BATH ROOM	-	-	-	-	
1070105	SMOKE_AD44 22FL CORRIDOR R2203	-	-	-	-	
1070106	HEAT_AD RM.2206 BATH ROOM	✓				
1070107	SMOKE_AD RM.2206 BED ROOM	✓				
1070108	SMOKE_AD RM.2205 LIVING ROOM	✓				
1070109	SMOKE_AD RM.2205 BED ROOM	✓				
1070110	HEAT_AD RM.2205 BATH ROOM	✓				
1070111	SMOKE_AD RM.2204 LIVING ROOM	✓				
1070112	HEAT_AD RM.2204 BATH ROOM	✓				
1070113	SMOKE_AD52 22FL CORRIDOR R2205	-	-	-	-	
1070114	SMOKE_AD RM.2203 BED ROOM	✓				
1070115	HEAT_AD RM.2203 BATH ROOM	✓				
1070116	SMOKE_AD RM.2202 BED ROOM	✓				
1070117	HEAT_AD RM.2202 BATH ROOM	✓				
1070118	SMOKE_AD RM.2201 LIVING ROOM	-	-	-	-	
1070119	HEAT_AD RM.2201 BATH ROOM	-	-	-	-	
1070120	HEAT_AD60 22FL MAID'S ROOM	-	-	-	-	
1070121	HEAT_AD25 22FL TOILET	-	-	-	-	
1070122	HEAT_AD61 22FL GARBAGE ROOM	-	-	-	-	
1070123	SMOKE_AD64 22FL ELECTRICAL ROOM	-	-	-	-	
1070124	HEAT_AD65 22FL COMMUNICATION ROOM	-	-	-	-	
1070126	STROBE_1_21FL	-	-	-	-	



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1070127	SPEAKER_1_21FL	-	-	-	-	
1070128	TEL_1_21FL	-	-	-	-	
1070129	STROBE_1_22FL	-	-	-	-	
1070130	SPEAKER_1_22FL	-	-	-	-	
1070131	TEL_1_22FL	-	-	-	-	
1070132	MANUAL_ST3_21FL	-	-	-	-	
1070133	KEY_15_ST3_21FL	-	-	-	-	
1070134	MANUAL_PASSENGER LIFT21FL	-	-	-	-	
1070135	KEY_24_PASSENGER LIFT21FL	-	-	-	-	
1070136	MANUAL_ST1_21FL	-	-	-	-	
1070137	KEY_53_ST1_21FL	-	-	-	-	
1070138	MANUAL_FIREMAN LIFT 21FL	-	-	-	-	
1070139	KEY_63_FIREMAN LIFT 21FL	-	-	-	-	
1070140	MANUAL_ST3_22FL	-	-	-	-	
1070141	KEY_15_ST3_22FL	-	-	-	-	
1070142	MANUAL_PASSENGER LIFT22FL	-	-	-	-	
1070143	KEY_24_PASSENGER LIFT22FL	-	-	-	-	
1070144	MANUAL_ST1_22FL	-	-	-	-	
1070145	KEY_53_ST1_22FL	-	-	-	-	
1070146	MANUAL_FIREMAN LIFT 22FL	-	-	-	-	
1070147	KEY_63_FIREMAN LIFT 22FL	-	-	-	-	
1070251	IM_1_23FL	-	-	-	-	
1070252	IM_2_23FL	-	-	-	-	
1070253	HEAT_AD RM.2320 BATH ROOM	✓				
1070254	SMOKE_AD RM.2320 LIVING ROOM	✓				
1070255	HEAT_AD RM.2319 BATH ROOM	-	-	-	-	
1070256	SMOKE_AD RM.2319 BED ROOM	-	-	-	-	
1070257	HEAT_AD RM.2318 BATH ROOM	✓				
1070258	SMOKE_AD RM.2318 BED ROOM	✓				
1070259	HEAT_AD RM.2317 BATH ROOM	✓				
1070260	SMOKE_AD RM.2317 BED ROOM	✓				
1070261	HEAT_AD RM.2316 BATH ROOM	-	-	-	-	
1070262	SMOKE_AD RM.2316 BED ROOM	-	-	-	-	
1070263	SMOKE_AD RM.2316 LIVING ROOM	-	-	-	-	
1070264	SMOKE_AD RM.2315 BED ROOM	✓				
1070265	HEAT_AD RM.2315 BATH ROOM	✓				



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message		Zone				หมายเหตุ
			PM. 1/2		PM. 2/2		
1070266	SMOKE_AD14 23FL	CORRIDOR R2317	✓				
1070267	SMOKE_AD16 23FL	CORRIDOR R2319	✓				
1070268	HEAT_AD RM.2314	BATH ROOM	-	-	-	-	
1070269	SMOKE_AD RM.2314	BED ROOM	-	-	-	-	
1070270	SMOKE_AD RM.2314	LIVING ROOM	-	-	-	-	
1070271	SMOKE_AD20 23FL	CORRIDOR R2320	✓				
1070272	SMOKE_AD RM.2313	BED ROOM	-	-	-	-	
1070273	HEAT_AD RM.2313	BATH ROOM	-	-	-	-	
1070274	SMOKE_AD23 23FL	PASSENGER LIFT	✓				
1070276	HEAT_AD RM.2312	BATH ROOM	✓				
1070277	SMOKE_AD RM.2312	BATH ROOM	✓				
1070278	SMOKE_AD28 23FL	CORRIDOR R2311	✓				
1070279	HEAT_AD RM.2311	BATH ROOM	✓				
1070280	SMOKE_AD RM.2311	BED ROOM	✓				
1070281	SMOKE_AD RM.2310	LIVING ROOM	✓				
1070282	SMOKE_AD RM.2310	BED ROOM	✓				
1070283	HEAT_AD RM.2310	BATH ROOM	✓				
1070284	SMOKE_AD34 23FL	CORRIDOR R2310	✓				
1070285	SMOKE_AD RM.2309	LIVING ROOM	✓				
1070286	SMOKE_AD RM.2309	BED ROOM	✓				
1070287	HEAT_AD RM.2309	BATH ROOM	✓				
1070288	SMOKE_AD38 23FL	CORRIDOR R2309	✓				
1070289	SMOKE_AD39 23FL	CORRIDOR R2308	✓				
1070290	HEAT_AD RM.2308	BATH ROOM	-	-	-	-	
1070291	SMOKE_AD RM.2308	BED ROOM	-	-	-	-	
1070292	SMOKE_AD RM.2307	LIVING ROOM	-	-	-	-	
1070293	HEAT_AD RM.2307	BATH ROOM	-	-	-	-	
1070294	SMOKE_AD44 23FL	CORRIDOR R2303	✓				
1070295	HEAT_AD RM.2306	BATH ROOM	✓				
1070296	SMOKE_AD RM.2306	BED ROOM	✓				
1070297	SMOKE_AD RM.2305	LIVING ROOM	-	-	-	-	
1070298	SMOKE_AD RM.2305	BED ROOM	-	-	-	-	
1070299	HEAT_AD RM.2305	BATH ROOM	-	-	-	-	
1070300	SMOKE_AD RM.2304	LIVING ROOM	-	-	-	-	
1070301	HEAT_AD RM.2304	BATH ROOM	-	-	-	-	
1070302	SMOKE_AD52 23FL	CORRIDOR R2305	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
1070303	SMOKE_AD RM.2303 BED ROOM	✓				
1070304	HEAT_AD RM.2303 BATH ROOM	✓				
1070305	SMOKE_AD RM.2302 BED ROOM	-	-	-	-	
1070306	HEAT_AD RM.2301 BATH ROOM	-	-	-	-	
1070307	SMOKE_AD RM.2301 LIVING ROOM	-	-	-	-	
1070308	HEAT_AD RM.2302 BATH ROOM	-	-	-	-	
1070309	HEAT_AD60 23FL MAID'S ROOM	✓				
1070310	HEAT_AD61 23FL GARBAGE ROOM	✓				
1070311	SMOKE_AD62 23FL FIREMAN LIFT	✓				
1070312	SMOKE_AD64 23FL ELECTRICAL ROOM	-	-	-	-	
1070313	HEAT_AD65 23FL COMMUNICATION ROOM	-	-	-	-	
1070376	STROBE_1_23FL	-	-	-	-	
1070377	SPEAKER_1_23FL	-	-	-	-	
1070378	TEL_1_23FL	-	-	-	-	
1070379	MANUAL_ST3_23FL	✓				
1070380	KEY_15_ST3_23FL	✓				
1070381	MANUAL_PASSENGER LIFT23FL	✓				
1070382	KEY_24_PASSENGER LIFT23FL	✓				
1070383	MANUAL_ST1_23FL	✓				
1070384	KEY_53_ST1_23FL	✓				
1070385	MANUAL_FIREMAN LIFT 23FL	✓				
1070386	KEY_63_FIREMAN LIFT 23FL	✓				
1070387	CR_PA_FCP	-	-	-	-	
2020001	IM_1_24FL	-	-	-	-	
2020002	IM_2_24FL	-	-	-	-	
2020003	HEAT_AD RM.2418 BATH ROOM	-	-	-	-	
2020004	SMOKE_AD RM.2418 LIVING ROOM	-	-	-	-	
2020005	HEAT_AD RM.2417 BATH ROOM	✓				
2020006	SMOKE_AD RM.2417 BED ROOM	✓				
2020007	HEAT_AD RM.2416 BATH ROOM	✓				
2020008	SMOKE_AD RM.2416 BED ROOM	✓				
2020009	HEAT_AD RM.2415 BATH ROOM	✓				
2020010	SMOKE_AD RM.2415 LIVING ROOM	✓				
2020011	HEAT_AD RM.2414 BATH ROOM	✓				
2020012	HEAT_AD RM.2414 BATH ROOM 1	✓				
2020013	SMOKE_AD RM.2414 DRESSING ROOM	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2020014	SMOKE_AD RM.2414 BED ROOM 2	✓				
2020015	HEAT_AD RM.2414 BATH ROOM 2	✓				
2020016	SMOKE_AD RM.2414 BED ROOM 1	✓				
2020017	SMOKE_AD RM.2414 LIVING ROOM	✓				
2020018	SMOKE_AD RM.2414 CORRIDOR	✓				
2020019	SMOKE_AD17 24FL CORRIDOR R2415	✓				
2020020	SMOKE_AD19 24FL CORRIDOR R2417	✓				
2020021	HEAT_AD RM.2413 BATH ROOM	✓				
2020022	SMOKE_AD RM.2413 BED ROOM	✓				
2020023	SMOKE_AD RM.2413 LIVING ROOM	✓				
2020024	SMOKE_AD23 24FL CORRIDOR R2418	✓				
2020025	SMOKE_AD RM.2412 BED ROOM	✓				
2020026	HEAT_AD RM.2412 BATH ROOM	✓				
2020027	SMOKE_AD26 24FL PASSENGER LIFT	✓				
2020029	HEAT_AD RM.2411 BATH ROOM	✓				
2020030	SMOKE_AD RM.2411 BED ROOM	✓				
2020031	SMOKE_AD31 24FL CORRIDOR FIREMAN LIFT	✓				
2020032	SMOKE_AD RM.2410 LIVING ROOM	✓				
2020033	SMOKE_AD RM.2410 BED ROOM 1	✓				
2020034	HEAT_AD RM.2410 BATH ROOM 3	✓				
2020035	SMOKE_AD RM.2410 BED ROOM 2	✓				
2020036	SMOKE_AD RM.2410 DRESSING ROOM	✓				
2020037	HEAT_AD RM.2410 BATH ROOM 2	✓				
2020038	SMOKE_AD RM.2410 CORRIDOR	✓				
2020039	HEAT_AD RM.2410 BATH ROOM 1	✓				
2020040	SMOKE_AD40 24FL CORRIDOR R2410	✓				
2020041	SMOKE_AD RM.2409 LIVING ROOM	✓				
2020042	SMOKE_AD RM.2409 BED ROOM	✓				
2020043	HEAT_AD RM.2409 BATH ROOM	✓				
2020044	SMOKE_AD44 24FL CORRIDOR GARBAGE	✓				
2020045	SMOKE_AD45 24FL CORRIDOR 2401	✓				
2020046	HEAT_AD RM.2408 BATH ROOM	-	-	-	-	
2020047	SMOKE_AD RM.2408 BED ROOM	-	-	-	-	
2020048	SMOKE_AD RM.2407 LIVING ROOM	✓				
2020049	HEAT_AD RM.2407 BATH ROOM	✓				
2020050	SMOKE_AD50 24FL CORRIDOR R2403	✓				



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2020051	HEAT_AD RM.2406 BATH ROOM	✓				
2020052	SMOKE_AD RM.2406 BED ROOM	✓				
2020053	SMOKE_AD RM.2405 LIVING ROOM	✓				
2020054	SMOKE_AD RM.2405 BED ROOM	✓				
2020055	HEAT_AD RM.2405 BATH ROOM	✓				
2020056	SMOKE_AD RM.2404 LIVING ROOM	✓				
2020057	HEAT_AD RM.2404 BATH ROOM	✓				
2020058	SMOKE_AD58 24FL CORRIDOR R2405	✓				
2020059	SMOKE_AD RM.2403 BED ROOM	✓				
2020060	HEAT_AD RM.2403 BATH ROOM	✓				
2020061	SMOKE_AD RM.2402 BED ROOM	✓				
2020062	HEAT_AD RM.2402 BATH ROOM	✓				
2020063	SMOKE_AD RM.2401 BED ROOM	✓				
2020064	HEAT_AD RM.2401 BATH ROOM	✓				
2020065	HEAT_AD66 24FL MAID'S ROOM	✓				
2020066	HEAT_AD67 24FL GARBAGE ROOM	✓				
2020067	SMOKE_AD68 24FL FIREMAN LIFT	✓				
2020068	SMOKE_AD70 24FL ELECTRICAL ROOM	-	-	-	-	
2020069	HEAT_AD71 24FL COMMUNI CATION ROOM	-	-	-	-	
2020126	STROBE_1_24FL	-	-	-	-	
2020127	SPEAKER_1_24FL	-	-	-	-	
2020128	TZ_1_24FL	-	-	-	-	
2020129	MANUAL_ST3_24FL	✓				
2020130	KEY_18_ST3_24FL	✓				
2020131	MANUAL_PASSENGER LIFT24FL	✓				
2020132	KEY_27_PASSENGER LIFT24FL	✓				
2020133	MANUAL_ST1_24FL	✓				
2020134	KEY_59_ST1_24FL	✓				
2020135	MANUAL_FIREMAN LIFT 24FL	✓				
2020136	KEY_69_FIREMAN LIFT 24FL	✓				
2020251	IM_1_25FL	-	-	-	-	
2020252	IM_2_25FL	-	-	-	-	
2020253	HEAT_AD RM.2518 BATH ROOM	✓				
2020254	SMOKE_AD RM.2518 LIVING ROOM	✓				
2020255	HEAT_AD RM.2517 BATH ROOM	✓				
2020256	SMOKE_AD RM.2517 BED ROOM	✓				



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2020257	HEAT_AD RM.2516 BATH ROOM	✓				
2020258	SMOKE_AD RM.2516 BED ROOM	✓				
2020259	HEAT_AD RM.2515 BATH ROOM	✓				
2020260	SMOKE_AD RM.2515 LIVING ROOM	✓				
2020261	HEAT_AD RM.2514 BATH ROOM 1	✓				
2020262	SMOKE_AD RM.2514 DRESSING ROOM	✓				
2020263	SMOKE_AD RM.2514 BED ROOM 2	✓				
2020264	HEAT_AD RM.2514 BATH ROOM 2	✓				
2020265	SMOKE_AD RM.2514 BED ROOM 1	✓				
2020266	SMOKE_AD RM.2514 LIVING ROOM	✓				
2020267	HEAT_AD RM.2514 BATH ROOM	✓				
2020268	SMOKE_AD RM.2514 CORRIDOR	✓				
2020269	SMOKE_AD17 25FL CORRIDOR R2515	✓				
2020270	SMOKE_AD19 25FL CORRIDOR R2517	✓				
2020271	HEAT_AD RM.2513 BATH ROOM	✓				
2020272	SMOKE_AD RM.2513 BED ROOM	✓				
2020273	SMOKE_AD RM.2513 LIVING ROOM	✓				
2020274	SMOKE_AD23 25FL CORRIDOR R2518	✓				
2020275	SMOKE_AD RM.2512 BED ROOM	✓				
2020276	HEAT_AD RM.2512 BATH ROOM	✓				
2020277	SMOKE_AD26 25FL PASSENGER LIFT	✓				
2020278	HEAT_AD72 25FL MAID ROOM	✓				
2020279	HEAT_AD RM.2511 BATH ROOM	✓				
2020280	SMOKE_AD RM.2511 BED ROOM	✓				
2020281	SMOKE_AD31 25FL CORRIDOR FIREMAN LIFT	✓				
2020282	SMOKE_AD RM.2510 LIVING ROOM	✓				
2020283	SMOKE_AD RM.2510 BED ROOM 1	✓				
2020284	HEAT_AD RM.2510 BATH ROOM 3	✓				
2020285	SMOKE_AD RM.2510 BED ROOM 2	✓				
2020286	SMOKE_AD RM.2510 DRESSING ROOM	✓				
2020287	HEAT_AD RM.2510 BATH ROOM 2	✓				
2020288	SMOKE_AD RM.2510 CORRIDOR	✓				
2020289	HEAT_AD RM.2510 BATH ROOM 1	✓				
2020290	SMOKE_AD40 25FL CORRIDOR R2510	✓				
2020291	SMOKE_AD RM.2509 LIVING ROOM	-	-	-	-	
2020292	SMOKE_AD RM.2509 BED ROOM	-	-	-	-	



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2020293	HEAT_AD RM.2509 BATH ROOM	-	-	-	-	
2020294	SMOKE_AD44 25FL CORRIDOR GARBAGE	✓				
2020295	SMOKE_AD45 25FL CORRIDOR R2501	✓				
2020296	HEAT_AD RM.2508 BATH ROOM	-	-	-	-	
2020297	SMOKE_AD RM.2508 BED ROOM	-	-	-	-	
2020298	SMOKE_AD RM.2507 LIVING ROOM	-	-	-	-	
2020299	HEAT_AD RM.2507 BATH ROOM	-	-	-	-	
2020300	SMOKE_AD50 25FL CORRIDOR R2503	✓				
2020301	HEAT_AD RM.2506 BATH ROOM	✓				
2020302	SMOKE_AD RM.2506 BED ROOM	✓				
2020303	SMOKE_AD RM.2505 LIVING ROOM	✓				
2020304	SMOKE_AD RM.2505 BED ROOM	✓				
2020305	HEAT_AD RM.2505 BATH ROOM	✓				
2020306	SMOKE_AD RM.2504 LIVING ROOM	-	-	-	-	
2020307	HEAT_AD RM.2504 BATH ROOM	-	-	-	-	
2020308	SMOKE_AD58 25FL CORRIDOR R2505	✓				
2020309	SMOKE_AD RM.2503 BED ROOM	✓				
2020310	HEAT_AD RM.2503 BATH ROOM	✓				
2020311	SMOKE_AD RM.2502 BED ROOM	-	-	-	-	
2020312	HEAT_AD RM.2502 BATH ROOM	-	-	-	-	
2020313	SMOKE_AD RM.2501 BED ROOM	-	-	-	-	
2020314	HEAT_AD RM.2501 BATH ROOM	-	-	-	-	
2020315	HEAT_AD66 25FL TOILET	✓				
2020316	HEAT_AD67 25FL GARBAGE ROOM	✓				
2020317	SMOKE_AD68 25FL FIREMAN LIFT	✓				
2020318	SMOKE_AD70 25FL ELECTRICAL ROOM	-	-	-	-	
2020319	HEAT_AD71 25FL COMMUNI CATION ROOM	-	-	-	-	
2020376	STROBE_1_25FL	-	-	-	-	
2020377	SPEAKER_1_25FL	-	-	-	-	
2020378	TZ_1_25FL	-	-	-	-	
2020379	MANUAL_ST3_25FL	✓				
2020380	KEY_18_ST3_25FL	✓				
2020381	MANUAL_PASSENGER LIFT25FL	✓				
2020382	KEY_27_PASSENGER LIFT25FL	✓				
2020383	MANUAL_ST1 25FL	✓				
2020384	KEY_59_ST1 25FL	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2020385	MANUAL FIREMAN LIFT 25FL	✓				
2020386	KEY_69_FIREMAN LIFT 25FL	✓				
2030001	IM_26FL	-	-	-	-	
2030002	IM_27FL	-	-	-	-	
2030003	HEAT_AD RM.2618 BATH ROOM	✓				
2030004	SMOKE_AD RM.2618 LIVING ROOM	✓				
2030005	HEAT_AD RM.2617 BATH ROOM	✓				
2030006	SMOKE_AD RM.2617 BED ROOM	✓				
2030007	HEAT_AD RM.2616 BATH ROOM	✓				
2030008	SMOKE_AD RM.2616 BED ROOM	✓				
2030009	HEAT_AD RM.2615 BATH ROOM	✓				
2030010	SMOKE_AD RM.2615 LIVING ROOM	✓				
2030011	HEAT_AD RM.2614 BATH ROOM	-	-	-	-	
2030012	SMOKE_AD RM.2614 DRESSING ROOM	-	-	-	-	
2030013	SMOKE AD RM.2614 BED ROOM 2	-	-	-	-	
2030014	HEAT_AD RM.2614 BATH ROOM 2	-	-	-	-	
2030015	SMOKE_AD RM.2614 BED ROOM 1	-	-	-	-	
2030016	SMOKE_AD RM.2614 LIVING ROOM	-	-	-	-	
2030017	SMOKE_AD RM.2614 CORRIDOR	-	-	-	-	
2030018	HEAT_AD RM.2614 BATH ROOM 1	-	-	-	-	
2030019	SMOKE_AD17 26FL CORRIDOR R2615	✓				
2030020	SMOKE_AD19 26FL CORRIDOR R2617	✓				
2030021	HEAT_AD RM.2613 BATH ROOM	✓				
2030022	SMOKE_AD RM.2613 BED ROOM	✓				
2030023	SMOKE_AD RM.2613 LIVING ROOM	✓				
2030024	SMOKE_AD23 26FL CORRIDOR R2618	✓				
2030025	SMOKE_AD RM.2612 BED ROOM	✓				
2030026	HEAT_AD RM.2612 BATH ROOM	✓				
2030027	SMOKE_AD26 26FL PASSENGER LIFT	✓				
2030029	HEAT_AD RM.2611 BATH ROOM	-	-	-	-	
2030030	SMOKE_AD RM.2611 BED ROOM	-	-	-	-	
2030031	SMOKE_AD31 26FL CORRIDOR FIREMAN LIFT	✓				
2030032	SMOKE_AD RM.2610 LIVING ROOM	-	-	-	-	
2030033	SMOKE_AD RM.2610 BED ROOM 1	-	-	-	-	
2030034	HEAT_AD RM.2610 BATH ROOM 3	-	-	-	-	
2030035	SMOKE_AD RM.2610 BED ROOM 2	-	-	-	-	



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2030036	SMOKE_AD RM.2610 DRESSING ROOM	-	-	-	-	
2030037	HEAT_AD RM.2610 BATH ROOM 2	-	-	-	-	
2030038	SMOKE_AD RM.2610 CORRIDOR	-	-	-	-	
2030039	HEAT_AD RM.2610 BATH ROOM 1	-	-	-	-	
2030040	SMOKE_AD40 26FL CORRIDOR R2610	✓				
2030041	SMOKE_AD RM.2609 LIVING ROOM	-	-	-	-	
2030042	SMOKE_AD RM.2609 BED ROOM	-	-	-	-	
2030043	HEAT_AD RM.2609 BATH ROOM	-	-	-	-	
2030044	SMOKE_AD44 26FL CORRIDOR GARBAGE	✓				
2030045	SMOKE_AD45 26FL CORRIDOR R2601	✓				
2030046	HEAT_AD RM.2608 BATH ROOM	✓				
2030047	SMOKE_AD RM.2608 BED ROOM	✓				
2030048	SMOKE_AD RM.2607 LIVING ROOM	-	-	-	-	
2030049	HEAT_AD RM.2607 BATH ROOM	-	-	-	-	
2030050	SMOKE_AD50 26FL CORRIDOR R2603	✓				
2030051	HEAT_AD RM.2606 BATH ROOM	✓				
2030052	SMOKE_AD RM.2606 BED ROOM	✓				
2030053	SMOKE_AD RM.2605 LIVING ROOM	✓				
2030054	SMOKE_AD RM.2605 BED ROOM	✓				
2030055	HEAT_AD RM.2605 BATH ROOM	✓				
2030056	SMOKE_AD RM.2604 LIVING ROOM	✓				
2030057	HEAT_AD RM.2604 BATH ROOM	✓				
2030058	SMOKE_AD58 26FL CORRIDOR R2605	✓				
2030059	SMOKE_AD RM.2603 BED ROOM	-	-	-	-	
2030060	HEAT_AD RM.2603 BATH ROOM	-	-	-	-	
2030061	SMOKE_AD RM.2602 BED ROOM	✓				
2030062	HEAT_AD RM.2602 BATH ROOM	✓				
2030063	SMOKE_AD RM.2601 BED ROOM	-	-	-	-	
2030064	HEAT_AD RM.2601 BATH ROOM	-	-	-	-	
2030065	HEAT_AD66 26FL MAID'S ROOM	✓				
2030066	HEAT_AD67 26FL GARBAGE ROOM	✓				
2030067	SMOKE_AD68 26FL FIREMAN LIFT	✓				
2030068	SMOKE_AD70 26FL ELECTRICAL ROOM	-	-	-	-	
2030069	HEAT_AD71 26FL COMMUNI CATION ROOM	-	-	-	-	
2030070	HEAT_AD RM.2718 BATH ROOM	✓				
2030071	SMOKE_AD RM.2718 LIVING ROOM	✓				



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2030072	HEAT_AD RM.2717 BATH ROOM	✓				
2030073	SMOKE_AD RM.2717 BED ROOM	✓				
2030074	HEAT_AD RM.2716 BATH ROOM	-	-	-	-	
2030075	SMOKE_AD RM.2716 BED ROOM	-	-	-	-	
2030076	HEAT_AD RM.2715 BATH ROOM	✓				
2030077	SMOKE_AD RM.2715 LIVING ROOM	✓				
2030078	SMOKE_AD RM.2714 CORRIDOR	-	-	-	-	
2030079	HEAT_AD RM.2714 BATH ROOM 2	-	-	-	-	
2030080	HEAT_AD RM.2714 BATH ROOM 1	-	-	-	-	
2030081	SMOKE_AD RM.2714 DRESSING ROOM	-	-	-	-	
2030082	SMOKE_AD RM.2714 BED ROOM 2	-	-	-	-	
2030083	HEAT_AD RM.2714 BATH ROOM 3	-	-	-	-	
2030084	SMOKE_AD RM.2714 BED ROOM 1	-	-	-	-	
2030085	SMOKE_AD RM.2714 LIVING ROOM	-	-	-	-	
2030086	SMOKE_AD17 27FL CORRIDOR R2715	-	-	-	-	
2030087	SMOKE_AD19 27FL CORRIDOR R2717	-	-	-	-	
2030088	HEAT_AD RM.2713 BATH ROOM	✓				
2030089	SMOKE_AD RM.2713 BED ROOM	✓				
2030090	SMOKE_AD RM.2713 LIVING ROOM	✓				
2030091	SMOKE_AD23 27FL CORRIDOR R2712	-	-	-	-	
2030092	SMOKE_AD RM.2712 BED ROOM	✓				
2030093	HEAT_AD RM.2712 BATH ROOM	✓				
2030094	SMOKE_AD26 27FL PASSENGER LIFT	-	-	-	-	
2030095	HEAT_AD49 27FL GARBAGE ROOM	-	-	-	-	
2030096	HEAT_AD RM.2711 BATH ROOM	✓				
2030097	SMOKE_AD RM.2711 BED ROOM	✓				
2030098	SMOKE_AD31 27FL CORRIDOR R2711	-	-	-	-	
2030099	SMOKE_AD RM.2710 LIVING ROOM	✓				
2030100	SMOKE_AD RM.2710 BED ROOM 1	✓				
2030101	HEAT_AD RM.2710 BATH ROOM 3	✓				
2030102	SMOKE_AD RM.2710 BED ROOM 2	✓				
2030103	SMOKE_AD RM.2710 DRESSING ROOM	✓				
2030104	HEAT_AD RM.2710 BATH ROOM 2	✓				
2030105	SMOKE_AD RM.2710 CORRIDOR	✓				
2030106	HEAT_AD RM.2710 BATH ROOM 1	✓				
2030107	SMOKE_AD40 27FL CORRIDOR R2710	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2030108	SMOKE_AD RM.2709 LIVING ROOM	✓				
2030109	SMOKE_AD RM.2709 BED ROOM	✓				
2030110	HEAT_AD RM.2709 BATH ROOM	✓				
2030111	SMOKE_AD44 27FL CORRIDOR R2709	-	-	-	-	
2030112	SMOKE_AD45 27FL FIREMAN LIFT	-	-	-	-	
2030113	SMOKE_AD47 27FL ELECTRICAL ROOM	-	-	-	-	
2030114	HEAT_AD48 27FL COMMUNICATION ROOM	-	-	-	-	
2030126	STROBE_1_26FL	-	-	-	-	
2030127	SPEAKER_1_26FL	-	-	-	-	
2030128	TZ_1_26FL	-	-	-	-	
2030129	STROBE_1_27FL	-	-	-	-	
2030130	SPEAKER_1_27FL	-	-	-	-	
2030131	TZ_1_27FL	-	-	-	-	
2030132	MANUAL_ST3_26FL	✓				
2030133	KEY_18_ST3_26FL	✓				
2030134	MANUAL_PASSENGER LIFT26FL	✓				
2030135	KEY_27_PASSENGER LIFT26FL	✓				
2030136	MANUAL_ST1_26FL	✓				
2030137	KEY_59 ST1_26FL	✓				
2030138	MANUAL_FIREMAN LIFT 26FL	✓				
2030139	KEY_69 FIREMAN LIFT 26FL	✓				
2030140	MANUAL_ST3_27FL	-	-	-	-	
2030141	KEY_18_ST3_27FL	-	-	-	-	
2030142	MANUAL_PASSENGER LIFT27FL	-	-	-	-	
2030143	KEY_27_PASSENGER LIFT27FL	-	-	-	-	
2030144	MANUAL_FIREMAN LIFT 27FL	-	-	-	-	
2030145	KEY_46 FIREMAN LIFT 27FL	-	-	-	-	
2030146	MANUAL_ST6_27FL	-	-	-	-	
2030147	KEY_50_ST6_27FL	-	-	-	-	
2030251	IM_28FL	-	-	-	-	
2030252	IM_29FL	-	-	-	-	
2030253	HEAT_AD RM.2818 BATH ROOM	-	-	-	-	
2030254	SMOKE_AD RM.2818 LIVING ROOM	-	-	-	-	
2030255	HEAT_AD RM.2817 BATH ROOM	-	-	-	-	
2030256	SMOKE_AD RM.2817 BED ROOM	-	-	-	-	
2030257	HEAT_AD RM.2816 BATH ROOM	-	-	-	-	



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2030258	SMOKE_AD RM.2816 BED ROOM	-	-	-	-	
2030259	HEAT_AD RM.2815 BATH ROOM	-	-	-	-	
2030260	SMOKE_AD RM.2815 LIVING ROOM	-	-	-	-	
2030261	HEAT_AD RM.2814 BATH ROOM 2	-	-	-	-	
2030262	SMOKE_AD RM.2814 DRESSING ROOM	-	-	-	-	
2030263	SMOKE_AD RM.2814 BED ROOM 2	-	-	-	-	
2030264	SMOKE_AD RM.2814 BED ROOM 1	-	-	-	-	
2030265	SMOKE_AD RM.2814 CORRIDOR	✓				
2030266	HEAT_AD RM.2814 BATH ROOM 3	-	-	-	-	
2030267	HEAT_AD RM.2814 BATH ROOM 1	-	-	-	-	
2030268	SMOKE_AD RM.2814 LIVING ROOM	-	-	-	-	
2030269	SMOKE_AD17 28FL CORRIDOR R2815	✓				
2030270	SMOKE_AD19 28FL CORRIDOR R2817	✓				
2030271	HEAT_AD RM.2813 BATH ROOM	✓				
2030272	SMOKE_AD RM.2813 BED ROOM	✓				
2030273	SMOKE_AD RM.2813 LIVING ROOM	✓				
2030274	SMOKE_AD23 28FL CORRIDOR R2812	✓				
2030275	HEAT_AD RM.2812 BATH ROOM	✓				
2030276	SMOKE_AD RM.2812 BED ROOM	✓				
2030277	SMOKE_AD26 28FL PASSENGER LIFT	✓				
2030278	HEAT_AD RM.2811 BATH ROOM	✓				
2030279	HEAT_49_28FL GARBAGE ROOM	✓				
2030280	SMOKE_AD RM.2811 BED ROOM	✓				
2030281	SMOKE_AD31 28FL CORRIDOR R2811	✓				
2030282	SMOKE_AD33 28FL FIRE MAN LIFT	✓				
2030283	SMOKE_AD RM.2810 LIVING ROOM	✓				
2030284	SMOKE_AD RM.2810 BED ROOM 1	✓				
2030285	HEAT_AD RM.2810 BATH ROOM 3	✓				
2030286	SMOKE_AD RM.2810 BED ROOM 2	✓				
2030287	HEAT_AD RM.2810 BATH ROOM 2	✓				
2030288	SMOKE_AD RM.2810 DRESSING ROOM	✓				
2030289	HEAT_AD RM.2810 BATH ROOM 1	✓				
2030290	SMOKE_AD RM.2810 CORRIDOR	✓				
2030291	SMOKE_AD43 28FL CORRIDOR R2809	✓				
2030292	SMOKE_AD RM.2809 LIVING ROOM	✓				
2030293	SMOKE_AD RM.2809 BED ROOM	✓				



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2030294	HEAT_AD RM.2809 BATH ROOM	✓				
2030295	SMOKE_AD47 28FL ELECTRICAL ROOM	-	-	-	-	
2030296	HEAT_AD48 28FL COMMUNICATION ROOM	-	-	-	-	
2030297	HEAT_AD RM.2918 BATH ROOM	✓				
2030298	SMOKE_AD RM.2918 LIVING ROOM	✓				
2030299	HEAT_AD RM.2917 BATH ROOM	✓				
2030300	SMOKE_AD RM.2917 BED ROOM	✓				
2030301	HEAT_AD RM.2916 BATH ROOM	✓				
2030302	SMOKE_AD RM.2916 BED ROOM	✓				
2030303	HEAT_AD RM.2915 BATH ROOM	-	-	-	-	
2030304	HEAT_AD RM.2913 BATH ROOM	✓				
2030305	HEAT_AD RM.2914 BATH ROOM 1	-	-	-	-	
2030306	HEAT_AD RM.2914 BATH ROOM 2	-	-	-	-	
2030307	SMOKE_AD RM.2914 CORRIDOR	✓				
2030308	SMOKE_AD RM.2914 DRESSING ROOM	-	-	-	-	
2030309	SMOKE_AD RM.2914 BED ROOM 2	-	-	-	-	
2030310	HEAT_AD RM.2914 BATH ROOM 3	-	-	-	-	
2030311	SMOKE_AD RM.2914 BED ROOM 1	-	-	-	-	
2030312	SMOKE_AD RM.2914 LIVING ROOM	-	-	-	-	
2030313	SMOKE_AD17 29FL CORRIDOR R2915	✓				
2030314	SMOKE_AD19 29FL CORRIDOR R2917	✓				
2030315	HEAT_AD48 29FL COMMUNICATION ROOM	-	-	-	-	
2030316	SMOKE_AD RM.2913 BED ROOM	✓				
2030317	SMOKE_AD RM.2913 LIVING ROOM	✓				
2030318	SMOKE_AD23 29FL CORRIDOR R2913	✓				
2030319	SMOKE_AD RM.2912 BED ROOM	✓				
2030320	HEAT_AD RM.2912 BATH ROOM	✓				
2030321	SMOKE_AD26 29FL PASSENGER LIFT	✓				
2030323	HEAT_AD RM.2911 BATH ROOM	✓				
2030324	SMOKE_AD RM.2911 BED ROOM	✓				
2030325	SMOKE_AD31 29FL CORRIDOR FIREMAN LIFT	✓				
2030326	SMOKE_AD33 29FL FIREMAN LIFT	✓				
2030327	SMOKE_AD RM.2910 LIVING ROOM	✓				
2030328	SMOKE_AD RM.2910 BED ROOM 1	✓				
2030329	HEAT_AD RM.2910 BATH ROOM 3	✓				
2030330	SMOKE_AD RM.2910 BED ROOM 2	✓				



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2030331	SMOKE_AD RM.2910 DRESSING ROOM	✓				
2030332	HEAT_AD RM.2910 BATH ROOM 2	✓				
2030333	SMOKE_AD RM.2910 CORRIDOR	✓				
2030334	HEAT_AD RM.2910 BATH ROOM 1	✓				
2030335	SMOKE_AD43 29FL CORRIDOR R2909	✓				
2030336	SMOKE_AD RM.2909 LIVING ROOM	✓				
2030337	SMOKE_AD RM.2909 BED ROOM	✓				
2030338	HEAT_AD RM.2909 BATH ROOM	✓				
2030339	SMOKE_AD47 29FL ELECTRICAL ROOM	-	-	-	-	
2030340	SMOKE_AD RM.2915 LIVING ROOM	-	-	-	-	
2030341	HEAT_AD49 29FL GARBAGE ROOM	✓				
2030376	ZONE DZ#15 27FL	-	-	-	-	
2030377	DZ 2 28FL	-	-	-	-	
2030378	ZONE_ST6_FLOOR 28-R	✓				
2030379	ZONE_ST3_FLOOR 28-R	✓				
2030380	STROBE_1 28FL	-	-	-	-	
2030381	STROBE_2 28FL	-	-	-	-	
2030382	STROBE_3 28FL	-	-	-	-	
2030383	STROBE_ST6 28FL	-	-	-	-	
2030384	STROBE_ST3 28FL	-	-	-	-	
2030385	SPEAKER_1 28FL	-	-	-	-	
2030386	SPEAKER_2 28FL	-	-	-	-	
2030387	SPEAKER_3 28FL	-	-	-	-	
2030388	SPEAKER_ST6 28FL	-	-	-	-	
2030389	SPEAKER_ST3 28FL	-	-	-	-	
2030390	TZ_1 28FL	-	-	-	-	
2030391	TZ_ST6 28FL	-	-	-	-	
2030392	TZ_ST3 28FL	-	-	-	-	
2030393	STROBE_1 29FL	-	-	-	-	
2030394	SPEAKER_1 29FL	-	-	-	-	
2030395	TZ_1 29FL	-	-	-	-	
2030396	MANUAL_ST3 28FL	✓				
2030397	KEY_18_ST3 28FL	✓				
2030398	MANUAL_PASSENGER LIFT28FL	✓				
2030399	KEY_27_PASSENGER LIFT28FL	✓				
2030400	MANUAL_FIREMAN LIFT 28FL	✓				



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2030401	KEY_32_FIREMAN LIFT 28FL	✓				
2030402	MANUAL_ST6_28FL	✓				
2030403	KEY_34_ST6_28FL	✓				
2030404	MANUAL_ST3_29FL	✓				
2030405	KEY_18_ST3_29FL	✓				
2030406	MANUAL_PASSENGER_29FL	✓				
2030407	KEY_27_PASSENGER LIFT29FL	✓				
2030408	MANUAL_FIREMAN LIFT 29FL	✓				
2030409	KEY_32_FIREMAN LIFT 29FL	✓				
2030410	MANUAL_ST6_29FL	✓				
2030411	KEY_34_ST6_29FL	✓				
2040001	IM_30FL	-	-	-	-	
2040002	IM_31FL	-	-	-	-	
2040003	HEAT_AD RM.3018 BATH ROOM	✓				
2040004	SMOKE_AD RM.3018 LIVING ROOM	✓				
2040005	HEAT_AD RM.3017 BATH ROOM	✓				
2040006	SMOKE_AD RM.3017 BED ROOM	✓				
2040007	HEAT_AD RM.3016 BATH ROOM	✓				
2040008	SMOKE_AD RM.3016 BED ROOM	✓				
2040009	HEAT_AD RM.3015 BATH ROOM	✓				
2040010	SMOKE_AD RM.3015 LIVING ROOM	✓				
2040011	HEAT_AD RM.3014 BATH ROOM 1	-	-	-	-	
2040012	HEAT_AD RM.3014 BATH ROOM 2	-	-	-	-	
2040013	SMOKE_AD RM.3014 CORRIDOR	✓				
2040014	SMOKE_AD RM.3014 DRESSING ROOM	-	-	-	-	
2040015	SMOKE_AD RM.3014 BED ROOM 2	-	-	-	-	
2040016	HEAT_AD RM.3014 BATH ROOM 3	-	-	-	-	
2040017	SMOKE_AD RM.3014 BED ROOM 1	-	-	-	-	
2040018	SMOKE_AD RM.3014 LIVING ROOM	-	-	-	-	
2040019	SMOKE_AD17 30FL CORRIDOR R3015	✓				
2040020	SMOKE_AD19 30FL CORRIDOR R3017	✓				
2040021	HEAT_AD RM.3013 BATH ROOM	✓				
2040022	SMOKE_AD RM.3013 BED ROOM	✓				
2040023	SMOKE_AD RM.3013 LIVING ROOM	✓				
2040024	SMOKE_AD23 30FL CORRIDOR R3013	✓				
2040025	SMOKE_AD RM.3012 BED ROOM	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2040026	HEAT_AD RM.3012 BATH ROOM	✓				
2040027	SMOKE_AD26 30FL PASSENGER LIFT	✓				
2040028	SMOKE_AD RM.3010 DRESSING ROOM	✓				
2040029	HEAT_AD RM.3011 BATH ROOM	✓				
2040030	SMOKE_AD RM.3011 BED ROOM	✓				
2040031	SMOKE_AD31 30FL CORRIDOR FIREMAN LIFT	✓				
2040032	SMOKE_AD33 30FL FIREMAN LIFT	✓				
2040033	SMOKE_AD RM.3010 LIVING ROOM	✓				
2040034	SMOKE_AD RM.3010 BED ROOM 1	✓				
2040035	HEAT_AD RM.3010 BATH ROOM 3	✓				
2040036	SMOKE_AD RM.3010 BED ROOM 2	✓				
2040037	HEAT_AD49 30FL GARBAGE	✓				
2040038	HEAT_AD RM.3010 BATH ROOM 2	✓				
2040039	SMOKE_AD RM.3010 CORRIDOR	✓				
2040040	HEAT_AD RM.3010 BATH ROOM 1	✓				
2040041	SMOKE_AD43 30FL CORRIDOR R3009	✓				
2040042	SMOKE_AD RM.3009 LIVING ROOM	✓				
2040043	SMOKE_AD RM.3009 BED ROOM	✓				
2040044	HEAT_AD RM.3009 BATH ROOM	✓				
2040045	SMOKE_AD47 30FL ELECTRICAL ROOM	-	-	-	-	
2040046	HEAT_AD48 30FL COMMUNICATION ROOM	-	-	-	-	
2040047	HEAT_AD RM.3118 BATH ROOM	-	-	-	-	
2040048	SMOKE_AD RM.3118 LIVING ROOM	-	-	-	-	
2040049	HEAT_AD RM.3117 BATH ROOM	✓				
2040050	SMOKE_AD RM.3117 BED ROOM	✓				
2040051	HEAT_AD RM.3116 BATH ROOM	✓				
2040052	SMOKE_AD RM.3116 BED ROOM	✓				
2040053	HEAT_AD RM.3115 BATH ROOM	✓				
2040054	SMOKE_AD RM.3115 LIVING ROOM	✓				
2040055	HEAT_AD RM.3114 BATH ROOM 1	✓				
2040056	HEAT_AD RM.3114 BATH ROOM 2	✓				
2040057	SMOKE_AD RM.3114 CORRIDOR	✓				
2040058	SMOKE_AD RM.3114 BED ROOM 2	✓				
2040059	HEAT_AD RM.3114 BATH ROOM 3	✓				
2040060	SMOKE_AD RM.3114 DRESSING ROOM	✓				
2040061	SMOKE_AD RM.3114 BED ROOM 1	✓				



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2040062	SMOKE_AD RM.3114 LIVING ROOM	✓				
2040063	SMOKE_AD17 31FL CORRIDOR R3115	✓				
2040064	SMOKE_AD19 31FL CORRIDOR R3117	✓				
2040065	HEAT_AD RM.3113 BATH ROOM	✓				
2040066	SMOKE_AD RM.3113 BED ROOM	✓				
2040067	SMOKE_AD RM.3113 LIVING ROOM	✓				
2040068	SMOKE_AD23 31FL CORRIDOR	✓				
2040069	SMOKE_AD RM.3112 BED ROOM	✓				
2040070	HEAT_AD RM.3112 BATH ROOM	✓				
2040071	SMOKE_AD26 31FL PASSENGER LIFT	✓				
2040072	HEAT_AD49 31FL GARBAGE ROOM	✓				
2040073	HEAT_AD RM.3111 BATH ROOM	✓				
2040074	SMOKE_AD RM.3111 BED ROOM	✓				
2040075	SMOKE_AD31 31FL CORRIDOR FIREMAN LIFT	✓				
2040076	SMOKE_AD33 31FL FIREMAN LIFT	✓				
2040077	SMOKE_AD RM.3110 LIVING ROOM	✓				
2040078	SMOKE_AD RM.3110 BED ROOM 1	✓				
2040079	HEAT_AD RM.3110 BATH ROOM 3	✓				
2040080	SMOKE_AD RM.3110 BED ROOM 2	✓				
2040081	SMOKE_AD RM.3110 DRESSING ROOM	✓				
2040082	HEAT_AD RM.3110 BATH ROOM 2	✓				
2040083	HEAT_AD RM.3110 BATH ROOM 1	✓				
2040084	SMOKE_AD RM.3110 CORRIDOR	✓				
2040085	SMOKE_AD RM.3109 LIVING ROOM	✓				
2040086	SMOKE_AD43 31FL CORRIDOR R3109	✓				
2040087	SMOKE_AD RM.3109 BED ROOM	✓				
2040088	HEAT_AD RM.3109 BATH ROOM	✓				
2040089	SMOKE_AD47 31FL ELECTRICAL ROOM	✓				
2040090	HEAT_AD48 31FL COMMUNI CATION ROOM	✓				
2040126	STROBE_1_30FL	-	-	-	-	
2040127	SPEAKER_1_30FL	-	-	-	-	
2040128	TZ_1_30FL	-	-	-	-	
2040129	STROBE_1_31FL	-	-	-	-	
2040130	SPEAKER_1_31FL	-	-	-	-	
2040131	TZ_1_31FL	-	-	-	-	
2040132	MANUAL_ST3_30FL	✓				



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2040133	KEY_18_ST3_30FL	✓				
2040134	MANUAL_PASSENGER LIFT30FL	✓				
2040135	KEY_27_PASSENGER LIFT30FL	✓				
2040136	MANUAL FIREMAN LIFT 30FL	✓				
2040137	KEY_32_FIREMAN LIFT 30FL	✓				
2040138	MANUAL_ST6_30FL	✓				
2040139	KEY_34_ST6_30FL	✓				
2040140	MANUAL_ST3_31FL	✓				
2040141	KEY_18_ST3_31FL	✓				
2040142	MANUAL_PASSENGER LIFT31FL	✓				
2040143	KEY_27_PASSENGER LIFT31FL	✓				
2040144	MANUAL_FIREMAN LIFT 31FL	✓				
2040145	KEY_32_FIREMAN LIFT 31FL	✓				
2040146	MANUAL_ST6_31FL	✓				
2040147	KEY_34_ST6_31FL	✓				
2040251	IM_32FL	-	-	-	-	
2040252	IM_33FL	-	-	-	-	
2040253	HEAT_AD RM.3218 BATH ROOM	✓				
2040254	SMOKE_AD RM.3218 LIVING ROOM	✓				
2040255	HEAT_AD RM.3217 BATH ROOM	-	-	-	-	
2040256	SMOKE_AD RM.3217 BED ROOM	-	-	-	-	
2040257	HEAT_AD RM.3216 BATH ROOM	-	-	-	-	
2040258	SMOKE_AD RM.3216 BED ROOM	-	-	-	-	
2040259	HEAT_AD RM.3215 BATH ROOM	-	-	-	-	
2040260	SMOKE_AD RM.3215 LIVING ROOM	-	-	-	-	
2040261	HEAT_AD RM.3214 BATH ROOM 1	-	-	-	-	
2040262	HEAT_AD RM.3214 BATH ROOM 2	-	-	-	-	
2040263	SMOKE_AD RM.3214 CORRIDOR	✓				
2040264	SMOKE_AD RM.3214 DRESSING ROOM	-	-	-	-	
2040265	SMOKE_AD RM.3214 BED ROOM 2	-	-	-	-	
2040266	HEAT_AD RM.3214 BATH ROOM 3	-	-	-	-	
2040267	SMOKE_AD RM.3214 BED ROOM 1	-	-	-	-	
2040268	SMOKE_AD RM.3214 LIVING ROOM	-	-	-	-	
2040269	SMOKE_AD17 32FL CORRIDOR R3215	✓				
2040270	SMOKE_AD19 32FL CORRIDOR R3217	✓				
2040271	HEAT_AD RM.3213 BATH ROOM	✓				



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2040272	SMOKE_AD RM.3213 BED ROOM	✓				
2040273	SMOKE_AD RM.3213 LIVING ROOM	✓				
2040274	SMOKE_AD23 32FL CORRIDOR R3213	✓				
2040275	SMOKE_AD RM.3212 BED ROOM	✓				
2040276	HEAT_AD RM.3212 BATH ROOM	✓				
2040277	SMOKE_AD26 32FL PASSENGER LIFT	✓				
2040278	HEAT_AD RM.3211 BATH ROOM	-	-	-	-	
2040279	HEAT_AD49 32FL GARBAGE	✓				
2040280	SMOKE_AD RM.3211 BED ROOM	-	-	-	-	
2040281	SMOKE_AD31 32FL CORRIDOR FIREMAN LIFT	✓				
2040282	SMOKE_AD33 32FL FIRE MAN LIFT	✓				
2040283	SMOKE_AD RM.3210 LIVING ROOM	-	-	-	-	
2040284	SMOKE_AD RM.3210 BED ROOM 1	-	-	-	-	
2040285	HEAT_AD RM.3210 BATH ROOM 3	-	-	-	-	
2040286	SMOKE_AD RM.3210 BED ROOM 2	-	-	-	-	
2040287	SMOKE_AD RM.3210 DRESSING ROOM	-	-	-	-	
2040288	HEAT_AD RM.3210 BATH ROOM 2	-	-	-	-	
2040289	SMOKE_AD RM.3210 CORRIDOR	✓				
2040290	HEAT_AD RM.3210 BATH ROOM 1	✓				
2040291	SMOKE_AD43 32FL CORRIDOR R3209	-	-	-	-	
2040292	SMOKE_AD RM.3209 LIVING ROOM	-	-	-	-	
2040293	SMOKE_AD RM.3209 BED ROOM	-	-	-	-	
2040294	HEAT_AD RM.3209 BATH ROOM	-	-	-	-	
2040295	SMOKE_AD47 32FL ELECTRICAL ROOM	✓				
2040296	HEAT_AD48 32FL COMMUNI CATION ROOM	✓				
2040297	HEAT_AD RM.3318 BATH ROOM	✓				
2040298	SMOKE_AD RM.3318 LIVING ROOM	✓				
2040299	HEAT_AD RM.3317 BATH ROOM	✓				
2040300	SMOKE_AD RM.3317 BED ROOM	✓				
2040301	HEAT_AD RM.3316 BATH ROOM	-	-	-	-	
2040302	SMOKE_AD RM.3316 BED ROOM	-	-	-	-	
2040303	HEAT_AD RM.3315 BATH ROOM	-	-	-	-	
2040304	SMOKE_AD RM.3315 LIVING ROOM	-	-	-	-	
2040305	HEAT_AD RM.3314 BATH ROOM 1	-	-	-	-	
2040306	HEAT_AD RM.3314 BATH ROOM 2	-	-	-	-	
2040307	SMOKE_AD RM.3314 CORRIDOR	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2040308	SMOKE_AD RM.3314 DRESSING ROOM	-	-	-	-	
2040309	SMOKE_AD RM.3314 BED ROOM 2	-	-	-	-	
2040310	HEAT_AD RM.3314 BATH ROOM 3	-	-	-	-	
2040311	SMOKE_AD RM.3314 BED ROOM 1	-	-	-	-	
2040312	SMOKE_AD RM.3314 LIVING ROOM	-	-	-	-	
2040313	SMOKE_AD17 33FL CORRIDOR R3315	✓				
2040314	SMOKE_AD19 33FL CORRIDOR R3317	✓				
2040315	HEAT_AD RM.3313 BATH ROOM	✓				
2040316	SMOKE_AD RM.3313 BED ROOM	✓				
2040317	SMOKE_AD RM.3313 LIVING ROOM	✓				
2040318	SMOKE_AD23 33FL CORRIDOR R3313	✓				
2040319	SMOKE_AD RM.3312 BED ROOM	✓				
2040320	HEAT_AD RM.3312 BATH ROOM	✓				
2040321	SMOKE_AD26 33FL PASSENGER LIFT	✓				
2040322	HEAT_AD49 33FL GARBAGE	✓				
2040323	HEAT_AD48 33FL COMMUNI CATION ROOM	✓				
2040324	SMOKE_AD RM.3311 BED ROOM	✓				
2040325	SMOKE_AD31 33FL CORRIDOR FIREMAN LIFT	✓				
2040326	SMOKE_AD33 33FL FIRE MAN LIFT	✓				
2040327	SMOKE_AD RM.3310 LIVING ROOM	-	-	-	-	
2040328	SMOKE_AD RM.3310 BED ROOM 1	-	-	-	-	
2040329	HEAT_AD RM.3310 BATH ROOM 3	-	-	-	-	
2040330	SMOKE_AD RM.3310 BED ROOM 2	-	-	-	-	
2040331	SMOKE_AD RM.3310 DRESSING ROOM	-	-	-	-	
2040332	HEAT_AD RM.3310 BATH ROOM 2	-	-	-	-	
2040333	SMOKE_AD RM.3310 CORRIDOR	✓				
2040334	HEAT_AD RM.3310 BATH ROOM 1	-	-	-	-	
2040335	SMOKE_AD43 33FL CORRIDOR R3309	✓				
2040336	SMOKE_AD RM.3309 LIVING ROOM	-	-	-	-	
2040337	SMOKE_AD RM.3309 BED ROOM	-	-	-	-	
2040338	HEAT_AD RM.3309 BATH ROOM	-	-	-	-	
2040339	SMOKE_AD47 33FL ELECTRICAL ROOM	✓				
2040340	HEAT_AD RM.3311 BATH ROOM	✓				
2040376	STROBE_1_32FL	-	-	-	-	
2040377	SPEAKER_1_32FL	-	-	-	-	
2040378	TZ_1_32FL	-	-	-	-	



บริษัท ทีเยะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2040379	STROBE_1_33FL	-	-	-	-	
2040380	SPEAKER_1_33FL	-	-	-	-	
2040381	TZ_1_33FL	-	-	-	-	
2040382	MANUAL_ST3_32FL	✓				
2040383	KEY_18_ST3_32FL	✓				
2040384	MANUAL_PASSENGER LIFT32FL	✓				
2040385	KEY_27_PASSENGER LIFT32FL	✓				
2040386	MANUAL_FIREMAN LIFT 32FL	✓				
2040387	KEY_32_FIREMAN LIFT 32FL	✓				
2040388	MANUAL_ST6_32FL	✓				
2040389	KEY_34_ST6_32FL	✓				
2040390	MANUAL_ST3_33FL	✓				
2040391	KEY_18_ST3_33FL	✓				
2040392	MANUAL_PASSENGER LIFT33FL	✓				
2040393	KEY_27_PASSENGER LIFT33FL	✓				
2040394	MANUAL_FIREMAN LIFT 33FL	✓				
2040395	KEY_32_FIREMAN LIFT 33FL	✓				
2040396	MANUAL_ST6_33FL	✓				
2040397	KEY_34_ST6_33FL	✓				
2050001	IM_34FL	-	-	-	-	
2050002	IM_RFL	-	-	-	-	
2050003	SMOKE_AD RM.3418 LIVING ROOM	✓				
2050004	HEAT_AD RM.3418 BATH ROOM	✓				
2050005	HEAT_AD RM.3417 BATH ROOM	✓				
2050006	SMOKE_AD RM.3417 BED ROOM	✓				
2050007	HEAT_AD RM.3416 BATH ROOM	✓				
2050008	SMOKE_AD RM.3416 BED ROOM	✓				
2050009	HEAT_AD RM.3415 BATH ROOM	✓				
2050010	SMOKE_AD RM.3415 LIVING ROOM	✓				
2050011	HEAT_AD RM.3414 BATH ROOM 2	✓				
2050012	HEAT_AD RM.3414 BATH ROOM 1	✓				
2050013	SMOKE_AD RM.3414 CORRIDOR	✓				
2050014	SMOKE_AD RM.3414 DRESSING ROOM	✓				
2050015	SMOKE_AD RM.3414 BED ROOM 2	✓				
2050016	HEAT_AD RM.3414 BATH ROOM 3	✓				
2050017	SMOKE_AD RM.3414 BED ROOM 1	✓				



บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2050018	SMOKE_AD17 34FL CORRIDOR R3415	✓				
2050019	SMOKE_AD19 34FL CORRIDOR R3417	✓				
2050020	HEAT_AD RM.3413 BATH ROOM	✓				
2050021	SMOKE_AD RM.3413 BED ROOM	✓				
2050022	SMOKE_AD RM.3414 LIVING ROOM	✓				
2050023	SMOKE_AD RM.3413 LIVING ROOM	✓				
2050024	SMOKE_AD23 34FL CORRIDOR R3412	✓				
2050025	HEAT_AD RM.3412 BATH ROOM	✓				
2050026	SMOKE_AD RM.3412 BED ROOM	✓				
2050027	HEAT_AD RM.3411 BATH ROOM	✓				
2050028	SMOKE_AD30 34FL CORRIDOR FIREMAN LIFT	✓				
2050029	HEAT_AD48 34FL GARBAGE	✓				
2050030	SMOKE_AD RM.3411 BED ROOM	✓				
2050031	SMOKE_AD26 34FL PASSENGER LIFT	✓				
2050032	SMOKE_AD33 34FL FIREMAN LIFT	✓				
2050033	HEAT_AD RM.3410 BATH ROOM 3	✓				
2050034	SMOKE_AD RM.3410 BED ROOM 1	✓				
2050035	SMOKE_AD RM.3410 LIVING ROOM	✓				
2050036	SMOKE_AD RM.3410 BED ROOM 2	✓				
2050037	HEAT_AD RM.3410 BATH ROOM 1	✓				
2050038	HEAT_AD RM.3410 BATH ROOM 2	✓				
2050039	SMOKE_AD RM.3410 CORRIDOR	✓				
2050040	SMOKE_AD RM.3410 DRESSING ROOM	✓				
2050041	SMOKE_AD42 34FL CORRIDOR R3409	✓				
2050042	SMOKE_AD RM.3518 LIVING ROOM	-	-	-	-	
2050043	HEAT_AD RM.3517 BATH ROOM	-	-	-	-	
2050044	HEAT_AD RM.3409 BATH ROOM	-	-	-	-	
2050045	HEAT_AD RM.3516 BATH ROOM	-	-	-	-	
2050046	HEAT_AD47 34FL COMMUNICATION ROOM	-	-	-	-	
2050047	HEAT_AD RM.3515 BATH ROOM	-	-	-	-	
2050048	SMOKE_AD RM.3409 LIVING ROOM	-	-	-	-	
2050049	HEAT_AD RM.3514 BATH ROOM 1	✓				
2050050	HEAT_AD RM.3514 BATH ROOM 2	✓				
2050051	SMOKE_AD46 34FL ELECTRICAL ROOM	-	-	-	-	
2050052	SMOKE_AD RM.3516 BED ROOM	-	-	-	-	
2050053	HEAT_AD RM.3518 BATH ROOM	✓				



บริษัท ดียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2050054	SMOKE_AD RM.3515 LIVING ROOM	-	-	-	-	
2050055	SMOKE_AD RM.3409 BED ROOM	-	-	-	-	
2050056	SMOKE_AD RM.3517 BED ROOM	-	-	-	-	
2050057	SMOKE_AD RM.3514 CORRIDOR	✓				
2050058	SMOKE_AD RM.3514 DRESSING ROOM	✓				
2050059	SMOKE_AD RM.3514 BED ROOM 2	✓				
2050060	HEAT_AD RM.3514 BATH ROOM 3	✓				
2050061	SMOKE_AD RM.3514 BED ROOM 1	✓				
2050062	SMOKE_AD RM.3514 LIVING ROOM	✓				
2050063	SMOKE_AD17 35FL CORRIDOR R3515	✓				
2050064	SMOKE_AD19 35FL CORRIDOR R3517	✓				
2050065	HEAT_AD RM.3513 BATH ROOM	✓				
2050066	SMOKE_AD RM.3513 BED ROOM	✓				
2050067	SMOKE_AD RM.3513 LIVING ROOM	✓				
2050068	SMOKE_AD23 35FL CORRIDOR R3512	✓				
2050069	SMOKE_AD RM.3512 BED ROOM	✓				
2050070	HEAT_AD RM.3512 BATH ROOM	✓				
2050071	SMOKE_AD26 35FL PASSENGER LIFT	✓				
2050072	HEAT_AD49 35FL GARBAGE	✓				
2050073	HEAT_AD RM.3511 BATH ROOM	✓				
2050074	SMOKE_AD RM.3511 BED ROOM	✓				
2050075	SMOKE_AD31 35FL CORRIDOR FIREMAN LIFT	✓				
2050076	SMOKE_AD32 35FL FIREMAN LIFT	✓				
2050077	SMOKE_AD RM.3510 LIVING ROOM	✓				
2050078	SMOKE_AD RM.3510 BED ROOM 1	✓				
2050079	HEAT_AD RM.3510 BATH ROOM 3	✓				
2050080	SMOKE_AD RM.3510 BED ROOM 2	✓				
2050081	SMOKE_AD RM.3510 DRESSING ROOM	✓				
2050082	HEAT_AD RM.3510 BATH ROOM 2	✓				
2050083	SMOKE_AD RM.3510 CORRIDOR	✓				
2050084	HEAT_AD RM.3510 BATH ROOM 1	✓				
2050085	SMOKE_AD43 35FL CORRIDOR R3509	✓				
2050086	SMOKE_AD RM.3509 LIVING ROOM	✓				
2050087	SMOKE_AD RM.3509 BED ROOM	✓				
2050088	HEAT_AD RM.3509 BATH ROOM	✓				
2050089	SMOKE_AD47 35FL ELECTRICAL ROOM	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2050090	HEAT_AD48_35FL COMMUNI CATION ROOM	-	-	-	-	
2050091	SMOKE_AD6_RFL LIFT MOTOR ROOM	✓				
2050092	SMOKE_AD5_RFL MECHANICAL FAN ROOM	✓				
2050093	SMOKE_AD3_RFL ELEVATOR MACHINE ROOM	✓				
2050094	SMOKE_AD1_RFL ELEVATOR MACHINE ROOM	✓				
2050095	SMOKE_AD2_RFL ELEVATOR MACHINE ROOM	✓				
2050096	HEAT_AD4_RFL BOOSTERS PUMP ROOM	✓				
2050126	STROBE_1_34FL	-	-	-	-	
2050127	SPEAKER_1_34FL	-	-	-	-	
2050128	TZ_1_34FL	-	-	-	-	
2050129	STROBE_1_35FL	-	-	-	-	
2050130	SPEAKER_1_35FL	-	-	-	-	
2050131	TZ_1_35FL	-	-	-	-	
2050132	MM_1_RFL	-	-	-	-	
2050133	MM_2_RFL	-	-	-	-	
2050134	MM_3_RFL	-	-	-	-	
2050135	MM_4_RFL	-	-	-	-	
2050136	MM_5_RFL	-	-	-	-	
2050137	MM_6_RFL	-	-	-	-	
2050138	MM_7_RFL	-	-	-	-	
2050139	STROBE_1_RFL	-	-	-	-	
2050140	STROBE_2_RFL	-	-	-	-	
2050141	SPEAKER_1_RFL	-	-	-	-	
2050142	SPEAKER_2_RFL	-	-	-	-	
2050143	CR_1_RFL	-	-	-	-	
2050144	CR_2_RFL	-	-	-	-	
2050145	MANUAL_ST3_34FL	-	-	-	-	
2050146	KEY_18_34FL	-	-	-	-	
2050147	MANUAL_PASSENGER_34FL	-	-	-	-	
2050148	KEY_27_34FL	-	-	-	-	
2050149	MANUAL_LIFT FM_34FL	-	-	-	-	
2050150	KEY_32_ST3_34FL	-	-	-	-	
2050151	MANUAL_ST6_34FL	-	-	-	-	
2050152	KEY_34_ST6_34FL	-	-	-	-	
2050153	MANUAL_ST3_35FL	-	-	-	-	
2050154	KEY_18_ST3_35FL	-	-	-	-	



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ครั้งที่ 1/2 ประจำปี 2569						
โครงการ Somerset Rama9 Bangkok						
Address	Message	Zone				หมายเหตุ
		PM. 1/2		PM. 2/2		
2050155	MANUAL_PASSENGER LIFT35FL	-	-	-	-	
2050156	KEY_27_PASSENGER LIFT35FL	-	-	-	-	
2050157	MANUAL_FIREMAN LIFT_ 35FL	-	-	-	-	
2050158	KEY_32_FIREMAN LIFT_ 35FL	-	-	-	-	
2050159	MANUAL_ST6_35FL	-	-	-	-	
2050160	KEY_34_ST6_35FL	-	-	-	-	
2050161	CR_3_RFL	-	-	-	-	




บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด TEEYA MASTER SYSTEMS CO., LTD.


รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok



สถานะตู้ FCP ก่อนทำการทดสอบ



สถานะตู้ FCP หลังทำการทดสอบ



ทดสอบ Lamp Test ตู้ Graphic



เจ้าหน้าที่ปฏิบัติงาน





บริษัท ตีเย มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok

รูปภาพทำความสะอาดตู้ FCP



รูปภาพตรวจเช็ค Battery Back Up



รูปภาพแสดงการทดสอบอุปกรณ์





บริษัท ทียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok



รูปภาพแสดงการทดสอบอุปกรณ์





บริษัท ตีเย มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการดำเนินการบำรุงรักษาระบบแจ้งเหตุเพลิงไหม้ ครั้งที่ 1/2 ประจำปี 2569

โครงการ Somerset Rama9 Bangkok





บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการบริการ

บริษัท : Somerset Rama 9 วันที่ : 29 ตุลาคม 2568
โครงการ : Somerset Rama 9 ผู้ติดต่อ : _____
เรื่อง : PM Fine Alarm โทรศัพท์ : _____
ระบบ EST3 ☒ FAS ☐ TWR ☐ CCTV ☐ OTHER
☒ ถ่ายรูปก่อนดำเนินการ

รายละเอียดของงาน : ก่อน PM สัปดาห์ Trouble 2 Point.
เช็คที่وترเช็ค PCP ทดสอบลิฟต์, เช็ค Battery ทดสอบลิฟต์.
ทดสอบลิฟต์, Smoke Add, Heat Add, Manual
ทดสอบลิฟต์พื้นที่ สหกรณ์
Pl. 35, Pl. 34, Pl. 33, Pl. 32, Pl. 31. พื้นที่ สหกรณ์. Pl. 2
ลิฟต์ลิฟต์ลิฟต์ ลิฟต์ลิฟต์.

แนวทางแก้ปัญหา : _____

ความคิดเห็นลูกค้า : _____

☐ ถ่ายรูปหลังเข้าดำเนินการ

เวลาเข้า : 09:00 น. พนักงานผู้ให้บริการ
เวลาออก : 16:00 น.
1 สุวิทย์ วัฒนศิริ
2 สุวิทย์ วัฒนศิริ
3 สุวิทย์ วัฒนศิริ
4 _____

ท่านได้รับความพึงพอใจในการให้บริการในครั้งนี้
☒ ดีมาก ☐ ดี ☐ พอใช้ ☐ ควรปรับปรุง
ลูกค้า : ธนกร อธิพาน
(.....)
วันที่ : 29. 10. 68



บริษัท ตียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการบริการ

บริษัท : Somerset Rama 9 วันที่ : 28 ตุลาคม 2568
โครงการ : Somerset Rama 9 ผู้ติดต่อ : 7
เรื่อง : Pm Pire Alarm. โทรศัพท์ : _____
ระบบ ☒ FAS ☐ TWR ☐ CCTV ☐ OTHER
☐ ถ่ายรูปก่อนดำเนินการ

รายละเอียดของงาน : เช็กการทำงานของอุปกรณ์ Smoke Add, Heat Add.
ทดสอบโซนอพ.ต.ร.

01.00 - ทดสอบ - Room 3510, 3511, 3512, 3513, 3411, 3412, 3413
3414, 3417, 3418, 3311, 3312, 3313, 3317, 3212, 3111
3112, 3113, 3115, 3009, 3011, 3012, 3013, 3018, 2911
2912, 2913, 2916, 2917, 2810, 2811, 2812, 2813, 2709
2711, 2712, 2713, 2718, 2618, 2615, 2613, 2612, 2608
2606, 2605, 2602

แนวทางเดินอพ.ต.ร. 02.00 - ทดสอบ Room 2518, 2517, 2516, 2514, 2513, 2512, 2511
2506, 2505, 2403, 2404, 2405, 2409, 2410, 2411, 2412, 2413
2309, 2204, 2205, 2212, 2102, 2105, 2110, 2119, 2118, 2095
2011, 2005, 1909, 1904, 1805, 1813, 1809, 1709, 1710, 1715, 1610

ความผิดปกติ 1619, 1503, 1404, 1310, 1214, 1116, 1012, 1301, 1305, 1316
1201, 1202, 1205, 1206, 1210, 1218, 1114, 1110, 1102, 1108, 1013, 1014
1005, 1007

☐ ถ่ายรูปหลังเข้าดำเนินการ

เวลาเข้า : 09:00 น.

เวลาออก : 17:00 น.

พนักงานผู้ให้บริการ

- 1 กมลศักดิ์ กอสมพริ.
- 2 ดิเรก ชัยภุมม.
- 3 ทศกร ช่างพิน.
- 4 _____

ท่านได้รับความพึงพอใจการให้บริการในครั้งนี้

☒ ดีมาก ☐ ดี ☐ พอใช้ ☐ ควรปรับปรุง

ลูกค้า : ธนกร อธิป.

(.....)

วันที่ : 28.10.68

** หากท่านไม่ได้รับความสะดวกหรือพึงพอใจในการบริการ กรุณาติดต่อ คุณธรรมรัตน์ 081-911-0447, คุณภูวนาด 089-926-4041, คุณณัฐนิชา 065-291-9183 **

หมายเหตุ ใบรายงานนี้จะไม่ระบุจำนวนเงิน เป็นการสรุปอุปกรณ์และลักษณะงานที่ได้ดำเนินการติดตั้งตามจริง และถือเป็นหลักฐาน เพื่อการดำเนินการจัดเก็บค่าใช้จ่ายตามราคาต่อหน่วยในโครงการนั้น หรือที่จะเสนอราคาในภายหลัง



บริษัท ดียะ มาสเตอร์ ซิสเต็มส์ จำกัด
TEEYA MASTER SYSTEMS CO., LTD.

รายงานการบริการ

บริษัท : Somerset Rama 9 วันที่ : 29 ตุลาคม 2568
โครงการ : Somerset Rama 9 ผู้ติดต่อ : _____
เรื่อง : Font Pine Alaron โทรศัพท์ : _____
ระบบ BST3 ☒ FAS ☐ TWR ☐ CCTV ☐ OTHER

☐ ถ่ายรูปก่อนดำเนินการ

รายละเอียดของงาน : ใช้หมอกดดมอุปกรณ์ Smoke Adel, Heat Adel, Manual
ให้พื้นที่บันทึก และสัณทก.

09:30 - ทดสอบ Room 3016, 2710, 2503, 2303, 2318, 2213, 2009, 1915, 1918
1711, 1613, 1620, 1511, 1519, 1002, 1003, 1006, 1016, 1017, 918.

12:00 - ทดสอบ Room 1011, 1012, 1106, 1204, 1214, 1302, 1311, 1416, 1417
1602, 1513, 1518, 1801, 1905, 1910, 2014, 2104, 2202, 2203, 2208
2219, 2510, 2604, 2809, 3010, 3117

และทดสอบพื้นที่สัณทก Corridor Fl. 30, Fl. 29, Fl. 28

แนวทางแก้ไข : ทดสอบอุปกรณ์สัณทก 100% ทุกตัว

ความคิดเห็นลูกค้า : _____

☐ ถ่ายรูปหลังเข้าดำเนินการ

เวลาเข้า : 09:00H พนักงานผู้ให้บริการ

เวลาออก : 16:00
1 อติพร ดงขดทาว
2 ชนนกรณ์ กิมกุล
3 อริศฐ์ ฐานดุสิต
4 _____

ท่านได้รับความพึงพอใจในการให้บริการในครั้งนี้

☒ ดีมาก ☐ ดี ☐ พอใช้ ☐ ควรปรับปรุง

ลูกค้า : อเนกร อริฬาร

(_____)

วันที่ : 29. 10. 68

** หากท่านไม่ได้รับความสะดวกหรือพึงพอใจในการบริการ กรุณาติดต่อ คุณธรรมรัตน์ 081-911-0447, คุณอุทมาภ 089-926-4041, คุณณัฐนิชา 065-291-9183**

หมายเหตุ ใบรายงานนี้จะไม่ระบุจำนวนเงิน เป็นการสรุปอุปกรณ์และลักษณะงานที่ได้ดำเนินการติดตั้งตามจริง และถือเป็นหลักฐาน เพื่อดำเนินการจัดเก็บค่าใช้จ่ายตามราคาต่อหน่วยในโครงการนั้น หรือที่จะเสนอราคาในภายหลัง

สำเนาสัญญาการดูแลต้นไม้



รายงานการให้บริการงานดูแลสวน

ชื่อหน่วยงาน มท. เติมเอช รัชดา (สาขา 00002)

วันที่ 2/7/2568

รายชื่อหัวหน้างานและพนักงาน ท.สินทร์, อ.ดร. เต๋, โจนพ, ทมู

1. บันทึกการให้บริการและการจัดส่งวัสดุ

ชั้น 6

- ตัดหญ้าบริเวณข้างลานจอดรถ, ข้างรั้วกำแพง, ข้างร้านชาวม
- กำจัดแมลงไทร บริเวณต้นข้างศาลพระพรหมฝั่งทิศใต้กับเนินสวนหน้า
- ไร่จระเข้ พร้อมกับตัดแต่งทรงพุ่มต้นไทรในจุดที่มีการค้างฉิม
- เก็บกวาดใบไม้ในจุดที่สกปรกตัดแต่ง

ชั้น 27

- ตัดหญ้าและเก็บกวาดทำความสะอาดในจุดที่สกปรกตัดหญ้า

ลงนาม

ท.สินทร์ (2/7/68)

เจ้าหน้าที่บริษัท สวนสวยรังสิต จำกัด

2. สำหรับลูกค้า

ลงนาม

Adana K.

เจ้าหน้าที่หน่วยงาน



รายงานการให้บริการงานดูแลสวน

ชื่อหน่วยงาน..... ม. 10/10 ม. 10 รังสิต..... วันที่ 5/8/68
รายชื่อหัวหน้างานและพนักงาน..... วัชรวิทย์ พงษ์พานิช และ พนักงาน.....

1. บันทึกการให้บริการและการจัดส่งวัสดุ

วันที่ 27

1. จัดบริการตัดหญ้าในสวน, ตัดกิ่งไม้, ตัดกิ่งไม้ประดับสวน
2. ตัดกิ่งไม้ประดับสวน 2 ต้น, ตัดกิ่งไม้ประดับสวน 1 ต้น
3. เก็บเศษใบไม้ที่ตัดไว้แล้ว และใส่ลงในถังขยะในสวน
- วันที่ 8..
1. ตัดกิ่งไม้ประดับสวน 1 ต้น และใส่ลงในถังขยะในสวน
2. เก็บเศษใบไม้ที่ตัดไว้แล้ว และใส่ลงในถังขยะในสวน
- งานด้านอื่นๆ
1. จัดบริการตัดหญ้าในสวน, ตัดกิ่งไม้, ตัดกิ่งไม้ประดับสวน
2. รื้อเศษใบไม้ที่ตัดไว้แล้ว และใส่ลงในถังขยะในสวน
3. ตัดกิ่งไม้ประดับสวน 1 ต้น และใส่ลงในถังขยะในสวน
4. ตัดกิ่งไม้ประดับสวน 1 ต้น และใส่ลงในถังขยะในสวน
5. รื้อเศษใบไม้ที่ตัดไว้แล้ว และใส่ลงในถังขยะในสวน
6. ตัดกิ่งไม้ประดับสวน 1 ต้น และใส่ลงในถังขยะในสวน
7. เก็บเศษใบไม้ที่ตัดไว้แล้ว และใส่ลงในถังขยะในสวน
8. ตัดกิ่งไม้ประดับสวน 1 ต้น และใส่ลงในถังขยะในสวน
9. เก็บเศษใบไม้ที่ตัดไว้แล้ว และใส่ลงในถังขยะในสวน
10. ตัดกิ่งไม้ประดับสวน 1 ต้น และใส่ลงในถังขยะในสวน
11. เก็บเศษใบไม้ที่ตัดไว้แล้ว และใส่ลงในถังขยะในสวน
12. เก็บเศษใบไม้ที่ตัดไว้แล้ว และใส่ลงในถังขยะในสวน

ลงนาม

วัชรวิทย์ พงษ์พานิช

เจ้าหน้าที่บริษัท สวนสวยรังสิต จำกัด

2. สำหรับลูกค้า

ลงนาม

วัชรวิทย์ พงษ์พานิช

เจ้าหน้าที่หน่วยงาน



รายงานการให้บริการงานดูแลสวน

ชื่อหน่วยงาน.....

วันที่ 8/10/68

รายชื่อหัวหน้างานและพนักงาน.....

วิวัฒน์ ไกรสิทธิ์ ตรีช หนองนา ตรี นัน 10
พล วัลย์ หนองนา ตรี นัน 10

1. บันทึกการให้บริการและการจัดส่งวัสดุ

วันที่ 27
1. ตัดหญ้าสนาม ตัดแต่งกิ่งไม้กิ่งเล็กกิ่งกลาง ตัดแต่งกิ่งใหญ่กิ่งกลางกิ่งเล็กกิ่งกลาง
2. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
3. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
4. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
5. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
6. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
7. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
8. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
9. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
10. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
11. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
12. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
13. ตัดแต่งกิ่งไม้กิ่งกลางกิ่งเล็กกิ่งกลาง
ลงนาม วิวัฒน์ ไกรสิทธิ์
เจ้าหน้าที่บริษัท สวนสวยรังสิต จำกัด

2. สำหรับลูกค้า

ลงนาม Kant
เจ้าหน้าที่หน่วยงาน



รายงานการให้บริการงานดูแลสวน
บริษัท เสนอธรรม รังสิต จำกัด (สท 00002)
ชื่อหน่วยงาน พ.ศ. ๒๕๖๒ ส. ๒๕๖๒ ๑๐๓๑๐ วันที่ 4/11/68
รายชื่อหัวหน้างานและพนักงาน โกสินทร์, ทองสิน, ผดุง, เต๋, พล, นันท, ทนอ, ใจนาถ

1. บันทึกการให้บริการและการจัดส่งวัสดุ

ชั้น 6

- ตัดหญ้าบริเวณโถงรอบตัวโถงรวม
- ตัดแต่งทรงพุ่มต้นแก้วบริเวณแนวรั้วกำแพงด้านหลัง และ ต้นข้าวโถงรวม
- เข้าไปไม้บริเวณใต้พุ่มไม้ และ เก็บกวาดใบไม้ในจุดที่มีการตัดแต่ง
- ตัดแต่งทรงพุ่มต้นข้าวบริเวณด้านหน้าโถงรวมจำนวน 5 ต้น

ชั้น 8

- ตัดแต่งทรงพุ่มต้นกระโดนจำนวน 1 ต้น บริเวณข้างสระบัวหน้า
- ตัดแต่งทรงพุ่มต้นไทรบริเวณข้างสระบัวหน้า
- ตัดแต่งใบเหลียงใบแห้งต้นเบญจ
- เก็บกวาดทำความสะอาดส=อาดพื้นที่ตัดแต่งต้นไม้

ชั้น 27

- ตัดหญ้าบริเวณสนาม
 - ตัดแต่งทรงพุ่มต้นเข็มชมพู
 - ตัดแต่งเคี่ยมต้นคอกตั้งที่ยื่นออกมาเกินบลิค
 - ตัดแต่งกิ่งต้นพุดกานลาม
 - เก็บใบแห้งต้นโสร้งที่กิ่งอยู่ตามยอดไม้ดอก
 - ขุดถอนวัชพืช
 - เก็บกวาดทำความสะอาดส=อาด และฉีดล้างพื้น
- ส่งคืนรถเข็น พ.ศ. ๖๘ และ ส่งปากกัตัดหญ้า ๑ ก้าน จัดเก็บเข้า,
ป.พ. กองฯ สุรินทร์ เชื้อเพลิง ไม้กวาดแข็ง ๑ ก้าน รับตอหนึ่ง

ลงนาม

โกสินทร์ (4/11/68)

เจ้าหน้าที่บริษัท สวนสวยรังสิต จำกัด

2. สำหรับลูกค้า

ลงนาม	เจ้าหน้าที่หน่วยงาน

สำเนาเอกสารการรับ-จ่ายค่าบริการขนย้ายมูลฝอย

AMH RATCHADA CO., LTD.-BRANCH 00002
22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900


RECEIPT / TAX INVOICE

RECEIVED FROM	Mrs Sukhon Rupmao	DATE	02-Jul-2025
ADDRESS	85/5 Moo.1, Latai, Kantararom, Sri Sa Ket , Thailand		
TAX ID	3330300313774		

Description	Amount
Cash Receipt #115660 - PAID FOR GARBAGE CHARGE ON 02 JULY 2025	500.00
TOTAL	467.29
VALUE ADDED TAX	32.71
GRAND TOTAL	500.00

RECEIVED BAHT Five Hundred and Zero Satang

BY ☐ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP. DATE _____
☐ BANK TRANSFER _____ BANK _____ DATE _____



CASHIER/RECEIVER

MANAGED BY

ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 3330300313774
Address : 85/5 Moo.1
Latai, Kantararom
Sri Sa Ket Thailand
Attention :
Room :
Room Type :
Arrival : 17 Apr 2023
Departure : 17 Apr 2023
Guest : Mrs Sukhon Rupmao

Reservation : 8878228
ABN : 0115559022518
Invoice No. : 195173
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 02 Jul 2025 05:32
Cashier : jidapha.t
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
02 Jul 2025		Cash Receipt #115660	-500.00
		- PAID FOR GARBAGE CHARGE ON 02 JULY 2025	
		Miscellaneous.	467.29
		#10965 GARBAGE CHARGE ON 02 JULY 2025	
		- TH VAT - Others 7%.	32.71
		Sub-Total Before VAT	467.29
		VAT	32.71
		Total Amount Inc VAT	500.00
		Payment	-500.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor Central Plaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: <https://www.discoverasr.com>

ใบรับซื้อ-ของเก่า

Date: 13-Jun-2025

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	2	บาท/ก.ก.	30+10+13+15+15+14+3	200
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.	6+10+15	30
เศษกระดาษ		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.	50	50
ปั๊บน				
ปั๊บน (ดี)		บาท/ใบ		
ปั๊บน (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.	5	10
ขวดน้ำ ขุ่น-ใส	5	บาท/ก.ก.	15	75
แกลอน	5	บาท/ก.ก.	7	35
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก	5	บาท/ก.ก.	10	50
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระบอง-อลูมิเนียม	20	บาท/ก.ก.	2.5	50
กระบองวิปิงค์รีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				500

นางสุคนธ์ รูปเหมาะ (ป้าแต)

ที่อยู่: 85/5 หมู่ที่ 1 ต.ละทาย อ.กันทรารมย์ จ.ศรีสะเกษ 33130

เลขบัตรประจำตัวประชาชน: 3 3303 00313 77 4

เบอร์โทร: 092-901-6939


.....
Supplier


.....
Witness


.....
Income Auditor


.....
General Cashier

AMH RATCHADA CO., LTD.-BRANCH 00002
22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Mrs Sukhon Rupmao	DATE	17-Jul-2025
ADDRESS	85/5 Moo.1, Latai, Kantararom, Sri Sa Ket , Thailand		
TAX ID	3330300313774		

Description	Amount
Cash Receipt #117138 - Paid for #11309 Garbage selling on 17 July 2025	485.00
TOTAL	453.27
VALUE ADDED TAX	31.73
GRAND TOTAL	485.00

RECEIVED BAHT Four Hundred Eighty Five and Zero Satang

BY ☒ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP. DATE _____
☐ BANK TRANSFER _____ BANK _____ DATE _____

N.

CASHIER/RECEIVER
MANAGED BY
ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 3330300313774
Address : 85/5 Moo.1
Latai, Kantararom
Sri Sa Ket Thailand
Attention :
Room :
Room Type :
Arrival : 18 Jul 2024
Departure : 18 Jul 2024
Guest : Mrs Sukhon Rupmao

Reservation : 13502175
ABN : 0115559022518
Invoice No. : 197244
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 17 Jul 2025 04:04
Cashier : nareeporn.m
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
17 Jul 2025		Miscellaneous.	453.27
		#11309 Garbage selling on 17 July 2025	
		- TH VAT - Others 7%.	31.73
		Cash Receipt #117138	-485.00
		- Paid for #11309 Garbage selling on 17 July 2025	
		Sub-Total Before VAT	453.27
		VAT	31.73
		Total Amount Inc VAT	485.00
		Payment	-485.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor Central Plaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: https://www.discoverasr.com

ใบรับซื้อ-ของเก่า

Date: 17-Jul-2025

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	2	บาท/ก.ก.	8+18+16+17+10+1+40	220
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.		
เศษกระดาษ		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.	45	45
ปิ่น				
ปิ่น (ดี)		บาท/ใบ		
ปิ่น (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.	5	10
ขวดน้ำ ขุ่น-ใส	5	บาท/ก.ก.	16	80
แกลอน	5	บาท/ก.ก.	6	30
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	20	บาท/ก.ก.	2.5	50
กระป๋องวิปิงครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor กังแก๊ส	5	บาท/ก.ก.	10	50
Com / Air		บาท/ก.ก.		
TOTAL				485


นางสุคนธ์ รูปเหมาะ (บ้านแต)

ที่อยู่: 85/5 หมู่ที่ 1 ต.ละทาย อ.กันทรารมย์ จ.ศรีสะเกษ 33130

เลขบัตรประจำตัวประชาชน: 3 3303 00313 77 4

เบอร์โทร: 092-901-6939


 Supplier


 Witness


 Income Auditor


 General Cashier

AMH RATCHADA CO., LTD.-BRANCH 00002
22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Mrs Sukhon Rupmao	DATE	31-Jul-2025
ADDRESS	85/5 Moo.1, Latai, Kantararom, Sri Sa Ket , Thailand		
TAX ID	3330300313774		

Description	Amount
Cash Receipt #118604 - Paid for #11644 Garbage Selling on 31 July 2025	450.00
TOTAL	420.56
VALUE ADDED TAX	29.44
GRAND TOTAL	450.00

RECEIVED BAHT Four Hundred Fifty and Zero Satang

BY ☐ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP. DATE _____
☐ BANK TRANSFER _____ BANK _____ DATE _____

CASHIER/RECEIVER
MANAGED BY

ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 3330300313774
Address : 85/5 Moo.1
Latai, Kantararom
Sri Sa Ket Thailand
Attention :
Room :
Room Type :
Arrival : 18 Jul 2024
Departure : 18 Jul 2024
Guest : Mrs Sukhon Rupmao

Reservation : 13502175
ABN : 0115559022518
Invoice No. : 199304
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 31 Jul 2025 03:00
Cashier : puchong.t
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
31 Jul 2025		Miscellaneous.	420.56
		#11644 Garbage Selling on 31 July 2025	
		- TH VAT - Others 7%.	29.44
		Cash Receipt #118604	-450.00
		- Paid for #11644 Garbage Selling on 31 July 2025	
		Sub-Total Before VAT	420.56
		VAT	29.44
		Total Amount Inc VAT	450.00
		Payment	-450.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor CentralPlaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO
BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON
COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL
AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: https://www.discoverasr.com

ใบรับซื้อ-ของเก่า

Date: 31-Jul-2025

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	2	บาท/ก.ก.	19 + 20 + 11 + 13 + 45	216
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.		
เศษกระดาษ		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.	39	39
ป๊อป				
ป๊อป (ดี)		บาท/ใบ		
ป๊อป (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.	5	10
ขวดน้ำ ชุ่น-ใส	5	บาท/ก.ก.	15	75
แกลอน	5	บาท/ก.ก.	10	50
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	20	บาท/ก.ก.	3	60
กระป๋องวิปิงครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				450

นางสุคนธ์ รูปเหมาะ (ปั๊ม)

ที่อยู่: 85/5 หมู่ที่ 1 ต.ละทาย อ.กันทรารมย์ จ.ศรีสะเกษ 33130

เลขบัตรประจำตัวประชาชน: 3 3303 00313 77 4

เบอร์โทร: 092-901-6939




Supplier




Witness



Income Auditor



General Cashier

somerset
KANA S RATCHADA

COPY

No. 120024

AMH RATCHADA CO., LTD.-BRANCH 00002

22 Ratchadaphisek Rd, Huai Khwang,

Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Mrs Sukhon Rupmao	DATE	14-Aug-2025
ADDRESS	85/5 Moo.1, Latai, Kantararom, Sri Sa Ket , Thailand		
TAX ID	3330300313774		

Description	Amount
Cash Receipt #120024 - Paid for #12012 Garbage Selling on 14 August 2025	500.00
TOTAL	467.29
VALUE ADDED TAX	32.71
GRAND TOTAL	500.00

RECEIVED BAHT Five Hundred and Zero Satang

BY ☒ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP.DATE _____
☐ BANK TRANSFER _____ BANK _____ DATE _____

CASHIER/RECEIVER

MANAGED BY

ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 3330300313774
Address : 85/5 Moo.1
Latai, Kantararom
Sri Sa Ket Thailand
Attention :
Room :
Room Type :
Arrival : 18 Jul 2024
Departure : 18 Jul 2024
Guest : Mrs Sukhon Rupmao

Reservation : 13502175
ABN : 0115559022518
Invoice No. : 201410
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 14 Aug 2025 02:20
Cashier : siriporn.d
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
14 Aug 2025		Miscellaneous.	467.29
		#12012 Garbage Selling on 14 August 2025	
		- TH VAT - Others 7%.	32.71
		Cash Receipt #120024	-500.00
		- Paid for #12012 Garbage Selling on 14 August 2025	
		Sub-Total Before VAT	467.29
		VAT	32.71
		Total Amount Inc VAT	500.00
		Payment	-500.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Account : 430-044-7697
Bank Code : 014
Holder's Name : AMH Ratchada Co., Ltd.
Branch Code : 5300
SWIFT Code : SICOTHBK
Bank Address : No. 9/9, the 5th Floor CentralPlaza Grand Rama 9, Huai Khwang, Bangkok 10310

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: https://www.discoverasr.com

ใบรับซื้อ-ของเก่า

Date: 14-Aug-2025

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาส				
กล่องกระดาส	2	บาท/ก.ก.	9+17+16+20+23+21	109
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.		
เศษกระดาส		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.	40	40
ป๊อป				
ป๊อป (ดี)		บาท/ใบ		
ป๊อป (รอง)	2	บาท/ใบ	1	2
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.		
ขวดน้ำ ขุ่น-ใส	5	บาท/ก.ก.	16	80
แกลอน	5	บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง	5	บาท/ก.ก.	6	30
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	20	บาท/ก.ก.	3	60
กระป๋องวิปป์ครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				402

นางสุคนธ์ รูปเหมาะ (ป้าแต)

ที่อยู่: 85/5 หมู่ที่ 1 ต.ละทาย อ.กันทรารมย์ จ.ศรีสะเกษ 33130


เลขบัตรประจำตัวประชาชน: 3 3303 00313 77 4

เบอร์โทร: 092-901-6939

เงิน 500


.....
Supplier


.....
Witness


.....
Income Auditor


.....
General Cashier

图 4-3-2-1 中 1 号点为基准点

No. 121440

22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

RECEIPT / TAX INVOICE

RECEIVED FROM	Mrs Sukhon Rupmao	DATE	28-Aug-2025
ADDRESS	85/5 Moo.1, Latai, Kantararom, Sri Sa Ket , Thailand		
TAX ID	3330300313774		

Description	Amount
Cash Receipt #121440 - Tendered 2,311.00 - Change 0.00 - #12273 Paid garbage sell on 28 Aug 2025	2,311.00
TOTAL	2,159.81
VALUE ADDED TAX	151.19
GRAND TOTAL	2,311.00

RECEIVED BAHT	Two Thousand Three Hundred Eleven and Zero Satang
----------------------	---

BY	☐	CASH	☐	CHEQUE NO. _____	BANK _____	DATE _____
	☐	CREDIT CARD	☐	_____	NO. _____	EXP. DATE _____
	☐	BANK TRANSFER	☐	_____	BANK _____	DATE _____

h n s.

CASHIER/RECEIVER

MANAGED BY

ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 3330300313774
Address : 85/5 Moo.1
Latai, Kantararom
Sri Sa Ket Thailand
Attention :
Room :
Room Type :
Arrival : 18 Jul 2024
Departure : 18 Jul 2024
Guest : Mrs Sukhon Rupmao

Reservation : 13502175
ABN : 0115559022518
Invoice No. : 203334
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 28 Aug 2025 03:11
Cashier : suwakul.p
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
28 Aug 2025		Miscellaneous.	2,159.81
		#12273 Garbage sell on 28 Aug 2025	
		- TH VAT - Others 7%.	151.19
		Cash Receipt #121440	-2,311.00
		- Tendered 2,311.00 - Change 0.00 - #12273 Paid garbage sell on 28 Aug 2025	
			Sub-Total Before VAT 2,159.81
			VAT 151.19
			Total Amount Inc VAT 2,311.00
			Payment -2,311.00
			Balance 0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor CentralPlaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: https://www.discoverasr.com

ใบรับซื้อ-ของเก่า

Date: 28-Aug-2025


รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาด				
กล่องกระดาด	2	บาท/ก.ก.	10+10+17+14+12 +45	216-
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.		
เศษกระดาด		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.	40	40-
ปั๊มน้ำ				
ปั๊มน้ำ (ดี)		บาท/ใบ		
ปั๊มน้ำ (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.		
ขวดน้ำ ชุ่น-ใส	5	บาท/ก.ก.	10	50
แกลลอน	5	บาท/ก.ก.	5	25-
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง	5	บาท/ก.ก.	9	40-
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	20	บาท/ก.ก.	2	40-
กระป๋องรีปิ้งครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่	10	บาท/ก.ก.	27+34 +32 +30 +28 +27 +14	1,900-
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				2,311-

นางสุคนธ์ รูปเหมาะ (ป้าแต)


ที่อยู่: 85/5 หมู่ที่ 1 ต.ละทาย อ.กันทรารมย์ จ.ศรีสะเกษ 33130

เลขบัตรประจำตัวประชาชน: 3 3303 00313 77 4

เบอร์โทร: 092-901-6939


.....
Supplier


.....
Witness


.....
Income Auditor


.....
General Cashier

somerset

COPY

No. 123071

AMH RATCHADA CO., LTD.-BRANCH 00002

22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Mrs Sukhon Rupmao	DATE	18-Sep-2025
ADDRESS	85/5 Moo.1, Latai, Kantararom, Sri Sa Ket , Thailand		
TAX ID	3330300313774		

Description	Amount
Cash Receipt #123071 - Paid for #12736 Garbage Selling on 18 September 2025	500.00
TOTAL	467.29
VALUE ADDED TAX	32.71
GRAND TOTAL	500.00

RECEIVED BAHT Five Hundred and Zero Satang

BY ☒ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP.DATE _____
☐ BANK TRANSFER _____ BANK _____ DATE _____

FM
CASHIER/RECEIVER
MANAGED BY
ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 3330300313774
Address : 85/5 Moo.1
Latai, Kantararom
Sri Sa Ket Thailand
Attention :
Room :
Room Type :
Arrival : 04 Jul 2024
Departure : 04 Jul 2024
Guest : Mrs Sukhon Rupmao

Reservation : 13343260
ABN : 0115559022518
Invoice No. : 206002
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 18 Sep 2025 04:41
Cashier : siriporn.d
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
18 Sep 2025		Miscellaneous.	467.29
		#12736 Garbage Selling on 18 September 2025	
		- TH VAT - Others 7%.	32.71
		Cash Receipt #123071	-500.00
		- Paid for #12736 Garbage Selling on 18 September 2025	
		Sub-Total Before VAT	467.29
		VAT	32.71
		Total Amount Inc VAT	500.00
		Payment	-500.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor CentralPlaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: https://www.discoverasr.com

ใบรับซื้อ-ของเก่า

Date: 18-Sep-2025

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	2	บาท/ก.ก.	20+3+22+21+19+13+15+18 = 136	272 -
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.		
เศษกระดาษ		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.	45 + 13	13 + 45 -
ป๊อป				
ป๊อป (ดี)		บาท/ใบ		
ป๊อป (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.	5	10 -
ขวดน้ำ ขุ่น-ใส	5	บาท/ก.ก.	7+13	100 -
แกลอน	5	บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	20	บาท/ก.ก.	3	60 -
กระป๋องวิปิงค์ครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
			TOTAL	500.-

นางสุคนธ์ รูปเหมาะ (ป้าแต)

ที่อยู่: 85/5 หมู่ที่ 1 ต.ละทาย อ.กันทรารมย์ จ.ศรีสะเกษ 33130

เลขบัตรประจำตัวประชาชน: 3 3303 00313 77 4

เบอร์โทร: 092-901-6939



Supplier



Witness



Income Auditor



General Cashier

AMH RATCHADA CO., LTD.-BRANCH 00002

22 Ratchadaphisek Rd, Huai Khwang,

Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM Mrs Sukhon Rupmao		DATE 02-Oct-2025	
ADDRESS 85/5 Moo.1, Latai, Kantararom, Sri Sa Ket , Thailand			
TAX ID 3330300313774			
Description	Amount		
Cash Receipt #124103 - Tendered 441.00 - Change 0.00 - #13023 Paid garbage sell on 02 Oct 25	441.00		
TOTAL			412.15
VALUE ADDED TAX			28.85
GRAND TOTAL			441.00
RECEIVED BAHT Four Hundred Forty One and Zero Satang			
BY ☐ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____ ☐ CREDIT CARD _____ NO. _____ EXP.DATE _____ ☐ BANK TRANSFER _____ BANK _____ DATE _____ _____ nah s. CASHIER/RECEIVER MANAGED BY ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK. THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.			

INVOICE

Company :
ID : 3330300313774
Address : 85/5 Moo.1
 Latai, Kantararom
 Sri Sa Ket Thailand
Attention :
Room :
Room Type :
Arrival : 18 Jul 2024
Departure : 18 Jul 2024
Guest : Mrs Sukhon Rupmao

Reservation : 13502175
ABN : 0115559022518
Invoice No. : 207725
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 02 Oct 2025 03:09
Cashier : suwakul.p
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
02 Oct 2025		Miscellaneous.	412.15
		#13032 Garbage sell on 02 Oct 25	
		- TH VAT - Others 7%.	28.85
		Cash Receipt #124103	-441.00
		- Tendered 441.00 - Change 0.00 - #13023 Paid garbage sell on 02 Oct 25	
Sub-Total Before VAT			412.15
VAT			28.85
Total Amount Inc VAT			441.00
Payment			-441.00
Balance			0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor CentralPlaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO
 BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON
 COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL
 AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: https://www.discoverasr.com

ใบรับซื้อ-ของเก่า

Date: 18-Sep-2025

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาด				
กล่องกระดาด	2	บาท/ก.ก.	$2+16+13+19+18+45 = 113$	226-
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.		
เศษกระดาด		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.	30	30-
ป๊อป				
ป๊อป (ดี)		บาท/ใบ		
ป๊อป (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.	5	10-
ขวดน้ำ ขุ่น-ใส	5	บาท/ก.ก.	15	75-
แกลอน	5	บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง	5	บาท/ก.ก.	10	50-
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	20	บาท/ก.ก.	2.5	50-
กระป๋องวิปิงครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				441-

นางสุคนธ์ รูปเหมาะ (ป้าแต)

ที่อยู่: 85/5 หมู่ที่ 1 ต.ละทาย อ.กันทรารมย์ จ.ศรีสะเกษ 33130

เลขบัตรประจำตัวประชาชน: 3 3303 00313 77 4


เบอร์โทร: 092-901-6939



Supplier



Witness



Income Auditor

General Cashier

AMH RATCHADA CO., LTD.-BRANCH 00002

22 Ratchadaphisek Rd, Huai Khwang,

Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Mrs Sukhon Rupmao	DATE	17-Oct-2025
ADDRESS	85/5 Moo.1, Latai, Kantararom, Sri Sa Ket , Thailand		
TAX ID	3330300313774		
Description			Amount
Cash Receipt #125410 - PAID FOR GARBAGE CHARGE ON 17 OCT 2025			305.00
		TOTAL	285.05
		VALUE ADDED TAX	19.95
		GRAND TOTAL	305.00
RECEIVED BAHT	Three Hundred Five and Zero Satang		
BY	☐ CASH	☐ CHEQUE NO. _____	BANK _____ DATE _____
		☐ CREDIT CARD _____	NO. _____ EXP.DATE _____
		☐ BANK TRANSFER _____	BANK _____ DATE _____
 CASHIER/RECEIVER			
MANAGED BY			
ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED			
REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK. THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.			

INVOICE

Company :
ID : 3330300313774
Address : 85/5 Moo.1
Latai, Kantararom
Sri Sa Ket Thailand
Attention :
Room :
Room Type :
Arrival : 17 Apr 2023
Departure : 17 Apr 2023
Guest : Mrs Sukhon Rupmao

Reservation : 8878228
ABN : 0115559022518
Invoice No. : 209705
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 17 Oct 2025 11:10
Cashier : jidapha.t
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
17 Oct 2025		Cash Receipt #125410	-305.00
		- PAID FOR GARBAGE CHARGE ON 17 OCT 2025	
		Miscellaneous.	285.05
		#13311 GARBAGE CHARGE ON 17 OCT 2025	
		- TH VAT - Others 7%.	19.95
		Sub-Total Before VAT	285.05
		VAT	19.95
		Total Amount Inc VAT	305.00
		Payment	-305.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor Central Plaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: https://www.discoverasr.com

ใบรับซื้อ-ของเก่า

Date: 17-Oct-2025


รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	2	บาท/ก.ก.	$12 \times 12 + 12 + 1 + 30 = 67$	134-
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.	1	1-
เศษกระดาษ		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.	30	30-
ปิ่น				
ปิ่น (ดี)		บาท/ใบ		
ปิ่น (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.		
ขวดน้ำ ขุ่น-ใส	5	บาท/ก.ก.	10	50-
แกลอน	5	บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง	5	บาท/ก.ก.	10	50-
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	20	บาท/ก.ก.	2	40-
กระป๋องรีปิ้งครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				305-

นางสุคนธ์ รูปเหมาะ (ป้าแต)

ที่อยู่: 85/5 หมู่ที่ 1 ต.ละทาย อ.กันทรารมย์ จ.ศรีสะเกษ 33130


เลขบัตรประจำตัวประชาชน: 3 3303 00313 77 4

เบอร์โทร: 092-901-6939


.....
Supplier


.....
Witness


.....
Income Auditor


.....
General Cashier

AMH RATCHADA CO., LTD.-BRANCH 00002
22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Mrs Sukhon Rupmao	DATE	06-Nov-2025
ADDRESS	85/5 Moo.1, Latai, Kantararom, Sri Sa Ket , Thailand		
TAX ID	3330300313774		

Description	Amount
Cash Receipt #127431 - Tendered 302.00 - Change 0.00 - Paid garbage sell on 06 Nov 25	302.00
TOTAL	282.24
VALUE ADDED TAX	19.76
GRAND TOTAL	302.00

RECEIVED BAHT Three Hundred Two and Zero Satang

BY ☐ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP. DATE _____
☐ BANK TRANSFER _____ BANK _____ DATE _____

nan s.
CASHIER/RECEIVER

MANAGED BY

ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 3330300313774
Address : 85/5 Moo.1
Latai, Kantararom
Sri Sa Ket Thailand
Attention :
Room :
Room Type :
Arrival : 18 Jul 2024
Departure : 18 Jul 2024
Guest : Mrs Sukhon Rupmao

Reservation : 13502175
ABN : 0115559022518
Invoice No. : 212854
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 06 Nov 2025 06:06
Cashier : suwakul.p
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
06 Nov 2025		Miscellaneous.	282.24
		#13790 Garbage sell on 06 Nov 25	
		- TH VAT - Others 7%.	19.76
		Cash Receipt #127431	-302.00
		- Tendered 302.00 - Change 0.00 - Paid garbage sell on 06 Nov 25	
		Sub-Total Before VAT	282.24
		VAT	19.76
		Total Amount Inc VAT	302.00
		Payment	-302.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor Central Plaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: https://www.discoverasr.com

ใบรับซื้อ-ของเก่า

Date: 6-Nov-2025


รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	2	บาท/ก.ก.	๓๐	100
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.		
เศษกระดาษ		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.	45	45
ป๊อป				
ป๊อป (ดี)		บาท/ใบ		
ป๊อป (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.	๖	12
ขวดน้ำ ชุ่น-ใส	5	บาท/ก.ก.	19	95
แกลอน	5	บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	20	บาท/ก.ก.	๒.5	50
กระป๋องวิปิ้งครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				302


นางสุคนธ์ รูปเหมาะะ (บ้านต)


ที่อยู่: 85/5 หมู่ที่ 1 ต.ละทาย อ.กันทรารมย์ จ.ศรีสะเกษ 33130

เลขบัตรประจำตัวประชาชน: 3 3303 00313 77 4

เบอร์โทร: 092-901-6939


Supplier


Witness


Income Auditor


General Cashier

AMH RATCHADA CO., LTD.-BRANCH 00002

22 Ratchadaphisek Rd, Huai Khwang,

Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Mrs Sukhon Rupmao	DATE	21-Nov-2025
ADDRESS	85/5 Moo.1, Latai, Kantararom, Sri Sa Ket , Thailand		
TAX ID	3330300313774		

Description	Amount
Cash Receipt #129081 - Paid for #14149 Garbage sell on 21 Nov 25	310.00
TOTAL	289.72
VALUE ADDED TAX	20.28
GRAND TOTAL	310.00

RECEIVED BAHT Three Hundred Ten and Zero Satang

BY

☒ CASH
 ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP.DATE _____
☐ BANK TRANSFER _____ BANK _____ DATE _____



CASHIER/RECEIVER

MANAGED BY

ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 3330300313774
Address : 85/5 Moo.1
 Latai, Kantararom
 Sri Sa Ket Thailand
Attention :
Room :
Room Type :
Arrival : 18 Jul 2024
Departure : 18 Jul 2024
Guest : Mrs Sukhon Rupmao

Reservation : 13502175
ABN : 0115559022518
Invoice No. : 215184
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 21 Nov 2025 06:20
Cashier : puchong.t
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
21 Nov 2025		Miscellaneous.	289.72
		#14149 Garbage sell on 21 Nov 25	
		- TH VAT - Others 7%.	20.28
		Cash Receipt #129081	-310.00
		- Paid for #14149 Garbage sell on 21 Nov 25	
			Sub-Total Before VAT 289.72
			VAT 20.28
			Total Amount Inc VAT 310.00
			Payment -310.00
			Balance 0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name	: Siam Commercial Bank Public Company Limited	Branch Code	: 5300
Account	: 430-044-7697	SWIFT Code	: SICOTHBK
Bank Code	: 014	Bank Address	: No. 9/9, the 5th Floor CentralPlaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name	: AMH Ratchada Co., Ltd.		

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO
 BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON
 COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL
 AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: <https://www.discoverasr.com>

Somerset Rama 9 Bangkok | Tax Invoice # 215184 | Page 1/1

ใบรับซื้อ-ของเก่า

Date: 21-Nov-2025


รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	2	บาท/ก.ก.	40+15	110-
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.		
เศษกระดาษ		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.	40	40-
เบียร์				
เบียร์ (ดี)		บาท/ใบ		
เบียร์ (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.		
ขวดน้ำ ขุ่น-ใส	5	บาท/ก.ก.	20	100-
แกลอน	5	บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	20	บาท/ก.ก.	3	60
กระป๋องวิปิงครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				310-


นางสุคนธ์ รูปเหมาะ (ป้าแต)


ที่อยู่: 85/5 หมู่ที่ 1 ต.ละทาย อ.กันทรารมย์ จ.ศรีสะเกษ 33130

เลขบัตรประจำตัวประชาชน: 3 3303 00313 77 4

เบอร์โทร: 092-901-6939


.....
Supplier


.....
Witness


.....
Income Auditor


.....
General Cashier

somerset
SOMERSET

COPY

No. 130304

AMH RATCHADA CO., LTD.-BRANCH 00002
22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Mrs Sukhon Rupmao	DATE	03-Dec-2025
ADDRESS	85/5 Moo.1, Latai, Kantararom, Sri Sa Ket , Thailand		
TAX ID	3330300313774		

Description	Amount
Cash Receipt #130304 - Paid for #14422 Garbage selling on 03 December 2025	545.00
TOTAL	509.35
VALUE ADDED TAX	35.65
GRAND TOTAL	545.00

RECEIVED BAHT Five Hundred Forty Five and Zero Satang

BY ☒ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP.DATE _____
☐ BANK TRANSFER _____ BANK _____ DATE _____

FAM

CASHIER/RECEIVER
MANAGED BY
ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 3330300313774
Address : 85/5 Moo.1
Latai, Kantararom
Sri Sa Ket Thailand
Attention :
Room :
Room Type :
Arrival : 04 Jul 2024
Departure : 04 Jul 2024
Guest : Mrs Sukhon Rupmao

Reservation : 13343260
ABN : 0115559022518
Invoice No. : 216914
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 03 Dec 2025 02:48
Cashier : siriporn.d
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
03 Dec 2025		Miscellaneous.	509.34
		#14422 Garbage selling on 03 December 2025	
		- TH VAT - Others 7%.	35.65
		Excess Collection.	0.01
		Cash Receipt #130304	-545.00
		- Paid for #14422 Garbage selling on 03 December 2025	
		Sub-Total Before VAT	509.35
		VAT	35.65
		Total Amount Inc VAT	545.00
		Payment	-545.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor Central Plaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: <http://www.discoverasr.com>

ใบรับซื้อ-ของเก่า

Date: 3-Dec-2025


รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาด				
กล่องกระดาด	2	บาท/ก.ก.	$10+14+21+13 \times 58$	116-
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.		
เศษกระดาด		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.	$12+12+13+14+14+12+15+14+17+10 \times 133$	133-
ปับ				
ปับ (ดี)		บาท/ใบ		
ปับ (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.	9	16-
ขวดน้ำ ขุ่น-ใส	5	บาท/ก.ก.	$9+9+6+2+10+7 \times 42$	210-
แอลอน	5	บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง	5	บาท/ก.ก.	14	70-
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	20	บาท/ก.ก.		
กระป๋องวิปิงครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				545-


นางสุนทร รูปเหมาะ (ป้าแต)


ที่อยู่: 85/5 หมู่ที่ 1 ต.ละทาย อ.กันทรารมย์ จ.ศรีสะเกษ 33130

เลขบัตรประจำตัวประชาชน: 3 3303 00313 77 4

เบอร์โทร: 092-901-6939


.....
Supplier


.....
Witness


.....
Income Auditor


.....
General Cashier

AMH RATCHADA CO., LTD.-BRANCH 00002
22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Mr Kasem Monthasuk	DATE	25-Dec-2025
ADDRESS	, Thailand		
TAX ID	3660500083869		

Description	Amount
TT/Direct Credit 1 Receipt #132709 - #14887 Sales Garbage on 25 Dec 2025	729.00
TOTAL	681.31
VALUE ADDED TAX	47.69
GRAND TOTAL	729.00

RECEIVED BAHT Seven Hundred Twenty Nine and Zero Satang

BY ☐ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP. DATE _____
☒ BANK TRANSFER _____ BANK _____ DATE _____


CASHIER/RECEIVER

MANAGED BY

ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 3660500083869
Address : Thailand
Attention :
Room :
Room Type :
Arrival : 25 Dec 2025
Departure : 25 Dec 2025
Guest : Mr Kasem Monthasuk

Reservation : 19632433
ABN : 0115559022518
Invoice No. : 220237
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 25 Dec 2025 02:55
Cashier : puchong.t
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
25 Dec 2025		Miscellaneous.	681.31
		#14887 Sales Garbage on 25 Dec 2025	
		- TH VAT - Others 7%.	47.69
		TT/Direct Credit 1 Receipt #132709	-729.00
		- #14887 Sales Garbage on 25 Dec 2025	
		Sub-Total Before VAT	681.31
		VAT	47.69
		Total Amount Inc VAT	729.00
		Payment	-729.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor Central Plaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: <https://www.discoverasr.com>

ใบรับซื้อ-ของเก่า

Date: 25-Dec-2025

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาม				
กล่องกระดาม	2	บาท/ก.ก.	$21 + 17 + 20 + 21 + 20 = 101$	202-
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม	1	บาท/ก.ก.	5 = 5	5-
เศษกระดาม		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	1	บาท/ก.ก.		
ปิ่น				
ปิ่น (ดี)		บาท/ใบ		
ปิ่น (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	2	บาท/ก.ก.		
ขวดน้ำ ขุ่น-ใส	3	บาท/ก.ก.	$33 + 33 = 66$	198-
แกลอน	4	บาท/ก.ก.	9	36-
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	32	บาท/ก.ก.	9	288-
กระป๋องวิปิงครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				729-

นายเกษม มณฑาสุข

ที่อยู่: 64/99 หมู่ที่ 3 ต.บางคูรัด อ.บางบัวทอง จ.นนทบุรี

เลขบัตรประจำตัวประชาชน: 3 6605 00083 86 9

เบอร์โทร: 081 825 9236

เกษม มณฑาสุข
Supplier

Chutipa K
Income Auditor

Notamon K.
Witness


General Cashier

บัตรประจำตัวประชาชน Thai National ID Card
เลขประจำตัวประชาชน Identification Number [REDACTED]

ชื่อตัวและชื่อสกุล นาง [REDACTED] [REDACTED]
Name Last

เกิดวันที่ 8 มิ.ย. 2509
Date of Birth 8 Jun. 1966

ศาสนา พุทธ
[REDACTED]

28 มิ.ย. 2565 7 มิ.ย. 2574
วันออกบัตร วันบัตรหมดอายุ
28 Sep. 2022 (นายชวนชม จงจิระ) 7 Jun. 2031
Date of Issue [REDACTED] Date of Expiry

1017-03-09281526

[REDACTED]

บัตรประจำตัวประชาชน Thai National ID Card
เลขประจำตัวประชาชน Identification Number [REDACTED]

ชื่อและชื่อสกุล นาย [REDACTED]
Name Mr [REDACTED]
Last name [REDACTED]
เกิดวันที่ 28 ธ.ค. 2513
Date of Birth 28 Dec. 1970
ศาสนา WIVE
[REDACTED]

17 พ.ค. 2565 27 ธ.ค. 2573
วันออกบัตร วันบัตรหมดอายุ
17 May 2022 (นายธนวัฒน์ จงจิตระ) 27 Dec. 2030
Date of issue เจ้าหน้าที่ออกบัตร Date of Expiry

1204-06-05171535


[REDACTED]

สำนักงาน

โอนเงินสำเร็จ

25 ธ.ค. 68 11:19 น.

K+



ธ.กสิกรไทย

xxx-x-x4970-x



บริษัท เอเอ็มเอช รัชดา จำกัด

ธ.ไทยพาณิชย์

xxx-x-x4769-x

เลขที่รายการ:

015359111951BOR08905

จำนวน:

729.00 บาท

ค่าธรรมเนียม:

0.00 บาท



สแกนตรวจสอบสลิป

สำเนารับรองการฝึกซ้อมการดับเพลิงและซ้อมหนีไฟ



กรุงเทพมหานคร



วุฒิบัตรเลขที่ สปภ.(กปภ.๑) ๑๕๒๙/๒๕๖๘

ได้รับใบอนุญาตจากกรมสวัสดิการและคุ้มครองแรงงาน ใบอนุญาตเลขที่ ๐๑๐๒-๐๒-๒๕๖๗-๐๑๕๑
ขอรับรองว่า

บริษัท เอเอ็มเอช รัชดา (สาขาที่ ๒) โดยโรงแรมซัมเมอร์เซ็ท ราชานันท์ แวงค็อก

ตั้งอยู่เลขที่ ๒๒ ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง กรุงเทพมหานคร


ได้ดำเนินการฝึกซ้อมดับเพลิงและฝึกซ้อมอพยพหนีไฟ

ตามกฎหมายที่กำหนดมาตรฐานในการบริหาร จัดการ และดำเนินการด้านความปลอดภัย อาชีวอนามัย
และสภาพแวดล้อมในการทำงานเกี่ยวกับการป้องกันและระงับอัคคีภัย พ.ศ. ๒๕๕๕ ลงวันที่ ๗ ธันวาคม พ.ศ. ๒๕๕๕

มีผู้เข้ารับการฝึกอบรม จำนวน ๘๕ คน

เมื่อวันที่ ๑๕ กันยายน ๒๕๖๘

ให้ไว้ ณ วันที่ ๒๒ กันยายน ๒๕๖๘

(น )

ผู้อำนวยการสำนักป้องกันและบรรเทาสาธารณภัย
ปฏิบัติราชการแทนผู้ว่าราชการกรุงเทพมหานคร

สำเนาบ้นทีก ฟีเอช และคลอรีน สระว่ายน้้า Check List Swimming Pool

Date 1-31/12/2025

DATE	POOL		FILTER PRESSURE (PSI)			PUMP OPERATION			Back Wash	CHEMICAL (use)				CHEMICAL BALANCE			POOL CLEAN Y/N	CHECK BY
	CL	PH	NO.1	NO.2	NO.3	NO.1	NO.2	NO.3	Y/N	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)	CL (Kg.)	Powder(Kg.)			
1	0.5	7.6	16	16	16	/	/	/	22	-	0.5kg	2kg	-	-	-	Phan		
2	1.0	7.6	12	12	12	/	/	/	N	-	-	-	-	-	-	Phan		
3	1.5	7.6	12	12	12	/	/	/	N	-	-	-	-	-	-	Phan		
4	1.5	7.6	12	12	12	/	/	/	N	-	-	-	-	-	-	Phan		
5	1.0	7.6	14	14	14	/	/	/	N	-	0.5	-	-	-	-	Phan		
6	1.5	7.6	14	14	14	/	/	/	N	-	-	-	-	-	-	Phan		
7	1.5	7.6	14	14	14	/	/	/	N	-	-	-	-	-	-	Phan		
8	1.5	7.6	16	16	16	/	/	/	N	-	-	-	-	-	-	Phan		
9	1.0	7.6	10	10	10	/	/	/	N	-	0.5	-	-	-	-	Phan		
10	1.5	7.6	12	12	12	/	/	/	N	-	-	-	-	-	-	Phan		
11	1.0	7.6	12	12	12	/	/	/	N	-	-	-	-	-	-	Phan		
12	1.5	7.6	12	12	12	/	/	/	N	-	-	-	-	-	-	Phan		
13	1.5	7.6	14	14	14	/	/	/	N	-	-	-	-	-	-	Phan		
14	0.5	7.6	14	14	14	/	/	/	N	-	-	-	-	-	-	Phan		
15	1.5	7.6	14	14	14	/	/	/	N	-	0.5kg	-	-	-	-	Phan		
16	1.5	7.6	10	10	10	/	/	/	N	-	-	-	-	-	-	Phan		
17	1.0	7.6	12	12	12	/	/	/	N	-	0.5	-	-	-	-	Phan		
18	1.5	7.6	12	12	12	/	/	/	N	-	-	-	-	-	-	Phan		
19	1.5	7.6	12	12	12	/	/	/	N	-	-	-	-	-	-	Phan		
20	1.0	7.6	12	12	12	/	/	/	N	-	-	-	-	-	-	Phan		
21	0.5	7.6	16	16	16	/	/	/	22	-	-	-	-	-	-	Phan		
22	1.5	7.6	16	16	16	/	/	/	22	-	0.5	-	-	-	-	Phan		
23	1.5	7.6	10	10	10	/	/	/	22	-	-	-	-	-	-	Phan		
24	1.0	7.6	10	10	10	/	/	/	N	-	-	-	-	-	-	Phan		
25	1.5	7.6	12	12	12	/	/	/	N	-	0.5	-	-	-	-	Phan		
26	1.5	7.6	14	14	14	/	/	/	N	-	-	-	-	-	-	Phan		
27	1.0	7.6	14	14	14	/	/	/	N	-	0.5	-	-	-	-	Phan		
28	1.0	7.6	12	12	12	/	/	/	N	-	0.5	-	-	-	-	Phan		
29	1.5	7.6	14	14	14	/	/	/	N	-	-	-	-	-	-	Phan		
30	1.5	7.6	14	14	14	/	/	/	N	-	-	-	-	-	-	Phan		
31	1.0	7.6	16	16	16	/	/	/	N	-	0.5	-	-	-	-	Phan		

REMARKS :

1.All system must work in good condition
2.Cleaning filter every week on Sunday

7.Any problem please report to Engineer Manager

NOTE :

REMARKS :

1.All system must work in good condition

2.Cleaning filter every week on Sunday.

3.Check Cl PH in pool everyday.

4.Clean pool and cutter every day on night shift.

5.Water level must over flow of pool.

6.No Smell, No Colour in water pond

7.Any problem please report to Engineer Manager

NOTE :

Date 1-30/11/2025

DATE	NIGHT SHIFT																
	POOL		FILTER PRESSURE (PSI)			PUMP OPERATION			Back Wash	CHEMICAL (use)			CHEMICAL BALANCE			POOL CLEAN	CHECK BY
	CL	PH	NO.1	NO.2	NO.3	NO.1	NO.2	NO.3	Y/N	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Y/N	
1	1.5	7.2	14	14	14	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
2	0.5	7.6	16	16	14	✓	✓	✓	2	—	0.5 kg	—	—	—	—	✓	7308.1
3	1.5	7.6	16	16	16	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
4	1.0	7.6	18	18	18	✓	✓	✓	2	—	0.5 kg	—	—	—	—	✓	7308.1
5	1.0	7.6	16	16	16	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
6	1.0	7.6	18	18	18	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
7	1.0	7.6	14	14	14	✓	✓	✓	2	—	0.5	—	—	—	—	✓	7308.1
8	1.5	7.6	14	14	14	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
9	1.5	7.6	14	14	14	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
10	1.5	7.6	14	14	14	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
11	0.5	7.6	14	14	14	✓	✓	✓	2	—	0.5 kg	—	—	—	—	✓	7308.1
12	0.5	7.6	16	16	16	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
13	0.4	7.6	18	18	18	✓	✓	✓	2	—	2 kg	—	—	—	—	✓	7308.1
14	1.5	7.6	12	12	12	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
15	1.5	7.6	12	12	12	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
16	1.5	7.6	14	14	14	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
17	1.0	7.2	15	15	15	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
18	1.0	7.2	15	15	15	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
19	1.0	7.2	18	18	18	✓	✓	✓	2	—	0.5 kg	—	—	—	—	✓	7308.1
20	1.5	7.6	12	12	12	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
21	1.5	7.6	12	12	12	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
22	0.5	7.6	12	12	12	✓	✓	✓	2	—	0.5 kg	—	—	—	—	✓	7308.1
23	1.5	7.6	12	12	12	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
24	1.5	7.6	12	12	12	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
25	1.5	7.6	14	14	14	✓	✓	✓	2	—	—	2 kg	—	—	—	✓	7308.1
26	1.0	7.6	14	14	14	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
27	1.0	7.6	16	16	14	✓	✓	✓	2	—	0.5 kg	—	—	—	—	✓	7308.1
28	1.5	7.6	16	14	14	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
29	1.5	7.6	16	14	14	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
30	1.5	7.6	16	14	14	✓	✓	✓	2	—	—	—	—	—	—	✓	7308.1
31																	

REMARKS :

1.All system must work in good condition

2.Cleaning filter every week on Sunday.

3.Check Cl PH in pool everyday.

4.Clean pool and cutter every day on night shift.

5.Water level must over flow of pool.

6.No Smell, No Colour in water pond

7.Any problem please report to Engineer Manager

NOTE :

Date 1-31 Oct 2025

DATE	NIGHT SHIFT													POOL CLEAN Y/N	CHECK BY		
	POOL		FILTER PRESSURE (PSI)			PUMP OPERATION			Back Wash	CHEMICAL (use)			CHEMICAL BALANCE				
	CL	PH	NO.1	NO.2	NO.3	NO.1	NO.2	NO.3	Y/N	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)			CL (Kg.)	Powder(Kg.)
1	1.0	7.6	14	14	14	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
2	1.0	7.2	14	14	14	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
3	1.0	7.6	18	18	18	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
4	1.0	7.6	12	12	12	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
5	1.0	7.6	12	12	12	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
6	1.0	7.6	13	13	13	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
7	0.5	7.6	18	18	18	✓	✓	✓	✓	✓	1KG	✓	✓	✓	✓	7290.9	
8	1.5	7.6	16	16	16	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
9	3.0	7.2	12	12	12	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
10	3.0	7.2	14	14	14	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
11	3.0	7.2	16	16	16	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
12	0.5	7.2	16	16	16	✓	✓	✓	✓	✓	1KG	✓	✓	✓	✓	7290.9	
13	1.6	7.2	18	18	18	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
14	1.0	7.6	12	12	12	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
15	2.0	7.2	14	14	14	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
16	1.0	7.2	14	14	14	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
17	1.0	7.2	18	18	18	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
18	1.6	7.6	14	14	14	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
19	1.0	7.6	16	15	15	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
20	0.5	7.8	12	12	12	✓	✓	✓	✓	✓	1KG 2KG	✓	✓	✓	✓	7290.9	
21	1.0	7.6	14	14	14	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
22	1.0	7.2	14	14	14	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
23	1.5	7.2	14	14	14	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
24	1.0	7.2	16	16	16	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
25	0	7.2	18	18	18	✓	✓	✓	✓	✓	1KG	✓	✓	✓	✓	7290.9	
26	1.6	7.2	18	18	18	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
27	1.6	7.2	12	12	12	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7290.9	
28	1.6	7.6	16	16	16	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7305.0	
29	1.5	7.2	16	16	16	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7305.8	
30	1.0	7.6	18	18	18	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7307.7	
31	1.0	7.6	12	12	12	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	7307.8	

REMARKS :

1.All system must work in good condition

2.Cleaning filter every week on Sunday.

3.Check Cl PH in pool everyday.

4.Clean pool and cutter every day on night shift.

5.Water level must over flow of pool.

7.Any problem please report to Engineer Manager

NOTE :

Date 1-30-5-2025

DATE	NIGHT SHIFT																		
	POOL		FILTER PRESSURE (PSI)			PUMP OPERATION			Back Wash	CHEMICAL (use)			CHEMICAL BALANCE			POOL CLEAN	CHECK BY		
	CL	PH	NO.1	NO.2	NO.3	NO.1	NO.2	NO.3	Y/N	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Y/N			
1	1.5	7.2	10	10	10	✓	✓	✓	N	-	-	8 kg	-	-	-	✓	7290.0		
2	1.0	7.2	12	12	12	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
3	1.5	7.2	12	12	12	✓	✓	✓	N	-	0.5	-	-	-	-	✓	7290.0		
4	1.5	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
5	1.5	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
6	1.0	7.2	14	14	14	✓	✓	✓	N	-	0.5	-	-	-	-	✓	7290.0		
7	1.0	7.2	16	16	16	✓	✓	✓	N	-	0.5	-	-	-	-	✓	7290.0		
8	1.5	7.2	10	10	10	✓	✓	✓	N	-	-	7 kg	-	-	-	✓	7290.0		
9	1.0	7.2	12	12	12	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
10	1.5	7.2	12	12	14	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
11	1.5	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
12	1.0	7.2	16	16	14	✓	✓	✓	N	-	0.5	-	-	-	-	✓	7290.0		
13	1.5	7.2	16	16	16	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
14	1.5	7.2	10	10	12	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
15	1.5	7.2	10	10	12	✓	✓	✓	N	-	0.5	-	-	-	-	✓	7290.0		
16	1.5	7.2	12	12	14	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
17	1.5	7.2	12	12	14	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
18	1.0	7.2	14	14	16	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
19	1.5	7.2	14	14	16	✓	✓	✓	N	-	0.5	-	-	-	-	✓	7290.0		
20	1.5	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
21	1.5	7.2	14	14	16	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
22	1.5	7.2	16	16	16	✓	✓	✓	N	-	0.5	-	-	-	-	✓	7290.0		
23	1.0	7.6	18	18	18	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
24	1.5	7.6	10	10	12	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
25	1.5	7.6	12	12	14	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
26	1.5	7.6	12	12	14	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
27	1.5	7.6	14	14	14	✓	✓	✓	N	-	0.5	-	-	-	-	✓	7290.0		
28	1.0	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
29	1.5	7.6	16	16	16	✓	✓	✓	N	-	0.5	-	-	-	-	✓	7290.0		
30	1.5	7.6	12	12	14	✓	✓	✓	N	-	-	-	-	-	-	✓	7290.0		
31																			

REMARKS :

1.All system must work in good condition

2.Cleaning filter every week on Sunday.

3.Check Cl PH in pool everyday.

4.Clean pool and cutter every day on night shift.

5.Water level must over flow of pool.

6.No Smell, No Colour in water pond

7.Any problem please report to Engineer Manager

NOTE :

Date 1-31 August 2025

DATE	POOL			FILTER PRESSURE (PSI)			PUMP OPERATION			Back Wash			CHEMICAL (use)						CHEMICAL BALANCE			POOL CLEAN Y/N	CHECK BY
	CL		PH	NO.1		NO.2	NO.3		NO.1	NO.2	NO.3	Y/N	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)	CL (Kg.)	Powder(Kg.)		
1	1.5	7.2		10	10	12	12	12	✓	✓	✓	✓	✓	1.0	1.0	1.0	1.0	1.0	1.0	1.0	1.0	✓	7242.9
2	1.0	7.2		12	12	12	14	14	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
3	1.0	7.2		12	12	12	14	14	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
4	0.5	7.1		16	16	16	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
5	0.5	7.2		16	16	16	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
6	1.5	7.2		10	10	10	12	12	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
7	1.5	7.2		12	12	12	14	14	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
8	1.0	7.2		12	12	12	14	14	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
9	1.0	7.2		14	14	14	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
10	1.0	7.2		14	14	14	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
11	0.5	7.2		16	16	16	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
12	1.0	7.2		10	10	10	12	12	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
13	1.0	7.2		10	10	10	12	12	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
14	0.5	7.2		12	12	12	14	14	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
15	0.5	7.2		14	14	14	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
16	0.5	7.2		16	16	16	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
17	1.5	7.2		16	16	16	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
18	0.5	7.2		16	16	16	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
19	1.0	7.2		10	10	10	12	12	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
20	1.0	7.2		12	12	12	14	14	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
21	1.5	7.2		12	12	12	14	14	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
22	1.0	7.2		14	14	14	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
23	1.5	7.2		16	16	16	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
24	0.5	7.2		16	16	16	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
25	0.5	7.2		16	16	16	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
26	1.0	7.2		10	10	10	12	12	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
27	1.5	7.2		10	10	10	12	12	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
28	1.5	7.2		12	12	12	14	14	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
29	1.0	7.2		14	14	14	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
30	1.5	7.2		14	14	14	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9
31	1.5	7.2		16	16	16	16	16	✓	✓	✓	✓	✓	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	✓	7242.9

REM

7. Any problem please report to Engineer Manager

NOTE:

1. All system must work in good condition

2. Cleaning filter every week on Sunday.

3. Check Cl PH in pool everyday.

"san pool and cutter every day on night shift.

"avel must over flow of pool.

" Colour in water pond

Date 1-31 July 2025

DATE	POOL			FILTER PRESSURE (PSI)			PUMP OPERATION			NIGHT SHIFT		CHEMICAL (use)				CHEMICAL BALANCE		POOL CLEAN Y/N	CHECK BY
	CL		PH	NO.1	NO.2	NO.3	NO.1	NO.2	NO.3	Back Wash	Y/N	Salt (Kg.)	CL (Kg.)	Powder (Kg.)	Salt (Kg.)	CL (Kg.)	Powder (Kg.)		
1	1.5		7.6															Y	7236.2
2	1.5	15	7.6	15	15	15	✓	✓	✓									Y	7236.2
3	1.0	18	7.6	18	18	18	✓	✓	✓				0.5					Y	7236.2
4	1.5	18	7.2	18	18	18	✓	✓	✓									Y	7236.2
5	1.5	16	7.2	16	16	16	✓	✓	✓									Y	7236.2
6	1.5	12	7.2	12	12	12	✓	✓	✓									Y	7236.2
7	1.5	12	7.2	12	12	12	✓	✓	✓									Y	7236.2
8	0.5	14	7.2	14	14	14	✓	✓	✓				0.5		2kg			Y	7236.2
9	1.5	16	7.2	16	16	16	✓	✓	✓									Y	7236.2
10	1.0	16	7.2	16	16	16	✓	✓	✓									Y	7236.2
11	1.0	20	7.2	20	20	20	✓	✓	✓				0.5	2kg				Y	7236.2
12	1.5	14	7.2	14	14	14	✓	✓	✓									Y	7242.1
13	1.5	14	7.2	14	14	14	✓	✓	✓									Y	7242.1
14	0.5	16	7.2	16	16	16	✓	✓	✓				0.5					Y	7242.1
15	1.5	16	7.2	16	16	16	✓	✓	✓				0.5					Y	7242.1
16	0.5	12	7.2	12	12	12	✓	✓	✓				0.5	2kg				Y	7242.1
17	1.0	14	7.2	14	14	14	✓	✓	✓									Y	7242.1
18	1.5	15	7.2	15	15	15	✓	✓	✓									Y	7242.1
19	1.5	16	7.2	16	16	16	✓	✓	✓									Y	7242.1
20	1.0	16	7.2	16	16	16	✓	✓	✓									Y	7242.1
21	0.5	16	7.2	16	16	16	✓	✓	✓				0.5kg					Y	7242.1
22	1.5	16	7.2	16	16	16	✓	✓	✓									Y	7242.1
23	0.5	12	7.2	12	12	12	✓	✓	✓				0.5kg	2kg				Y	7242.1
24	1.0	16	7.1	16	16	16	✓	✓	✓									Y	7242.1
25	1.0	16	7.2	16	16	16	✓	✓	✓									Y	7242.1
26	1.0	16	7.2	16	16	16	✓	✓	✓									Y	7242.1
27	0.5	16	7.2	16	16	16	✓	✓	✓				0.5kg					Y	7242.1
28	1.0	12	7.2	12	12	12	✓	✓	✓					2kg				Y	7242.1
29	1.0	12	7.2	12	12	12	✓	✓	✓				0.5kg					Y	7242.1
30	0.5	14	7.2	14	14	14	✓	✓	✓									Y	7242.1
31	1.5	14	7.2	14	14	14	✓	✓	✓									Y	7242.1

REMARKS :

1. All system must work in good condition

2. Cleaning filter every week on Sunday.

3. Check Cl PH in pool everyday.

4. Clean pool and cutter every day on night shift.

5. Water level must over flow of pool

6. No Smell, No Colour in water pond

7. Any problem please report to Engineer Manager

NOTE :

ภาคผนวกที่ 6

สำเนามาตรฐานและกฎหมายที่เกี่ยวข้อง

ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม
เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด
พ.ศ. ๒๕๖๗

โดยที่เป็นการสมควรปรับปรุงการกำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคาร ให้เหมาะสมตามความก้าวหน้าในทางวิทยาศาสตร์ เทคโนโลยี และความเปลี่ยนแปลงทางเศรษฐกิจ สังคม ของประเทศ และให้สอดคล้องกับสภาพการณ์ปัจจุบัน

อาศัยอำนาจตามความในมาตรา ๕๕ แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. ๒๕๓๕ รัฐมนตรีว่าการกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม โดยคำแนะนำของคณะกรรมการควบคุมมลพิษ และโดยความเห็นชอบของคณะกรรมการสิ่งแวดล้อมแห่งชาติ จึงออกประกาศไว้ ดังต่อไปนี้

ข้อ ๑ ให้ยกเลิกประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด ฉบับลงวันที่ ๗ พฤศจิกายน พ.ศ. ๒๕๔๘

ข้อ ๒ ในประกาศนี้

“อาคาร” หมายความว่า อาคารที่ก่อสร้างขึ้น ไม่ว่าจะมียุทธศาสตร์เป็นอาคารหลังเดียวหรือเป็นกลุ่มของอาคารซึ่งตั้งอยู่ภายในพื้นที่ซึ่งเป็นบริเวณเดียวกัน และไม่มียุทธศาสตร์น้ำท่วมหรือมีหลายท่อที่เชื่อมติดต่อกันระหว่างอาคารหรือไม่ก็ตาม

“น้ำทิ้ง” หมายความว่า น้ำที่เกิดจากกิจกรรมของอาคารที่ระบายหรือจะระบายลงสู่แหล่งน้ำสาธารณะหรือออกสู่สิ่งแวดล้อม

ข้อ ๓ ให้แบ่งอาคาร ออกเป็น ๓ ชนิด คือ

ชนิดที่ ๑ อาคารอยู่อาศัย หมายถึง อาคารที่มีวัตถุประสงค์ให้เป็นที่พักอาศัยของบุคคลทั้งการอยู่อาศัยอย่างถาวรหรือชั่วคราว ได้แก่

(๑) อาคารชุด ตามกฎหมายว่าด้วยอาคารชุด

(๒) หอพัก ตามกฎหมายว่าด้วยหอพัก

(๓) หอพัก ห้องเช่า ห้องแบ่งเช่า หรือกิจการอื่นในทำนองเดียวกันตามกฎหมายว่าด้วยการสาธารณสุข

(๔) สถานรับเลี้ยงเด็ก ตามกฎหมายว่าด้วยคุ้มครองเด็ก

(๕) สถานดูแลผู้สูงอายุหรือผู้มีภาวะพึ่งพิง ตามกฎหมายว่าด้วยสถานประกอบการเพื่อสุขภาพ

(๖) ที่พักอาศัยสำหรับลูกจ้างประเภทกิจกรรมก่อสร้าง ตามกฎหมายว่าด้วยการคุ้มครองแรงงาน

ชนิดที่ ๒ อาคารพาณิชยกรรม หมายถึง อาคารที่ใช้ประโยชน์ในการพาณิชยกรรม หรือบริการธุรกิจอย่างเดียวหรือหลายอย่าง ได้แก่

(๑) โรงแรม ตามกฎหมายว่าด้วยโรงแรม

- (๒) ศูนย์การค้าหรือห้างสรรพสินค้า
 (๓) ตลาด ตามกฎหมายว่าด้วยการสาธารณสุข
 (๔) สถานบริการประเภทสถานอาบน้ำ นวดหรืออบตัว ตามกฎหมายว่าด้วยสถานบริการ
 (๕) ภัตตาคารหรือร้านอาหาร
 (๖) อาคารที่ทำการของทางราชการ รัฐวิสาหกิจ หรือองค์การระหว่างประเทศและของเอกชน
 (๗) อาคารโรงเรียนเอกชน ตามกฎหมายว่าด้วยโรงเรียนเอกชน โรงเรียนของทางราชการ อาคารสถาบันอุดมศึกษาของเอกชน ตามกฎหมายว่าด้วยสถาบันอุดมศึกษาของเอกชนและสถาบันอุดมศึกษาของทางราชการ

ชนิดที่ ๓ อาคารสถานพยาบาล หมายถึง สถานพยาบาล ตามกฎหมายว่าด้วยสถานพยาบาล ประเภทที่รับผู้ป่วยไว้ค้างคืน

ข้อ ๔ ให้แบ่งขนาดของอาคาร ออกเป็น ๔ ประเภท ดังต่อไปนี้

ประเภทอาคาร	หน่วย	อาคาร ประเภท ก.	อาคาร ประเภท ข.	อาคาร ประเภท ค.	อาคาร ประเภท ง.
๑. อาคารอยู่อาศัย					
อาคารชุด	ห้องชุด	ตั้งแต่ ๕๐๐ ขึ้นไป	ตั้งแต่ ๑๐๐ แต่ไม่ถึง ๕๐๐	ไม่ถึง ๑๐๐	-
หอพัก	ห้อง	-	ตั้งแต่ ๒๕๐ ขึ้นไป	ตั้งแต่ ๕๐ แต่ไม่ถึง ๒๕๐	ไม่ถึง ๕๐
หอพัก ห้องเช่า ห้องแบ่งเช่า หรือกิจการอื่นในทำนอง เดียวกัน ตามกฎหมาย ว่าด้วยการสาธารณสุข	ห้อง	-	ตั้งแต่ ๒๕๐ ขึ้นไป	ตั้งแต่ ๕๐ แต่ไม่ถึง ๒๕๐	ไม่ถึง ๕๐
สถานรับเลี้ยงเด็ก	-	-	-	-	ทุกขนาด
สถานดูแลผู้สูงอายุหรือ ผู้มีภาวะพึ่งพิง	-	-	-	-	ทุกขนาด
ที่พักอาศัยสำหรับลูกจ้าง ประเภทกิจกรรมก่อสร้าง	-	-	-	-	ทุกขนาด
๒. อาคารพาณิชย์					
โรงแรม	ห้อง	ตั้งแต่ ๒๐๐ ขึ้นไป	ตั้งแต่ ๖๐ แต่ไม่ถึง ๒๐๐	ไม่ถึง ๖๐	-
สถานบริการประเภท สถานอาบน้ำ นวดหรืออบตัว	ตาราง เมตร	-	ตั้งแต่ ๕,๐๐๐ ขึ้นไป	ตั้งแต่ ๑,๐๐๐ แต่ไม่ถึง ๕,๐๐๐	ไม่ถึง ๑,๐๐๐
โรงเรียนเอกชน โรงเรียนของ ทางราชการ สถาบันอุดมศึกษา ของเอกชนหรือสถาบัน อุดมศึกษาของทางราชการ		ตั้งแต่ ๒๕,๐๐๐ ขึ้นไป	ตั้งแต่ ๕,๐๐๐ แต่ไม่ถึง ๒๕,๐๐๐	-	ไม่ถึง ๕,๐๐๐

ประเภทอาคาร	หน่วย	อาคาร ประเภท ก.	อาคาร ประเภท ข.	อาคาร ประเภท ค.	อาคาร ประเภท ง.
อาคารที่ทำการของทาง ราชการ รัฐวิสาหกิจ หรือ องค์การระหว่างประเทศและ ของเอกชน		ตั้งแต่ ๕๕,๐๐๐ ขึ้นไป	ตั้งแต่ ๑๐,๐๐๐ แต่ไม่ถึง ๕๕,๐๐๐	ตั้งแต่ ๕,๐๐๐ แต่ไม่ถึง ๑๐,๐๐๐	ไม่ถึง ๕,๐๐๐
ศูนย์การค้า หรือห้างสรรพสินค้า		ตั้งแต่ ๒๕,๐๐๐ ขึ้นไป	ตั้งแต่ ๕,๐๐๐ แต่ไม่ถึง ๒๕,๐๐๐	-	ไม่ถึง ๕,๐๐๐
ตลาด		ตั้งแต่ ๒,๕๐๐ ขึ้นไป	ตั้งแต่ ๑,๕๐๐ แต่ไม่ถึง ๒,๕๐๐	ตั้งแต่ ๑,๐๐๐ แต่ไม่ถึง ๑,๕๐๐	ไม่ถึง ๑,๐๐๐
ภัตตาคารหรือร้านอาหาร		ตั้งแต่ ๒,๕๐๐ ขึ้นไป	ตั้งแต่ ๕๐๐ แต่ไม่ถึง ๒,๕๐๐	ตั้งแต่ ๒๕๐ แต่ไม่ถึง ๕๐๐	ไม่ถึง ๒๕๐
๓. อาคารสถานพยาบาล	เตียง	ตั้งแต่ ๓๐ ขึ้นไป	ตั้งแต่ ๑๐ แต่ไม่ถึง ๓๐	-	ไม่ถึง ๑๐

ข้อ ๕ กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารไว้ ดังต่อไปนี้

พารามิเตอร์	ค่ามาตรฐาน			
	อาคาร ประเภท ก.	อาคาร ประเภท ข.	อาคาร ประเภท ค.	อาคาร ประเภท ง.
๑. ความเป็นกรดและด่าง (pH)	๕.๕ - ๙.๐	๕.๕ - ๙.๐	๕.๕ - ๙.๐	๕.๕ - ๙.๐
๒. บีโอดี (Biochemical Oxygen Demand)	ไม่เกิน ๒๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๓๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๔๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๕๐ มิลลิกรัมต่อลิตร สำหรับอาคารอยู่อาศัย
				ไม่เกิน ๑๐๐ มิลลิกรัมต่อลิตร สำหรับอาคารพาณิชย์ และอาคารสถานพยาบาล
๓. ของแข็งแขวนลอยทั้งหมด (Total Suspended Solids)	ไม่เกิน ๓๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๔๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๕๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๖๐ มิลลิกรัมต่อลิตร
๔. ของแข็งละลายน้ำทั้งหมด (Total Dissolved Solids)	ไม่เกิน ๑,๐๐๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๑,๐๐๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๑,๓๐๐ มิลลิกรัมต่อลิตร	-

พารามิเตอร์	ค่ามาตรฐาน			
	อาคาร ประเภท ก.	อาคาร ประเภท ข.	อาคาร ประเภท ค.	อาคาร ประเภท ง.
	สำหรับอาคารอยู่ อาศัยและอาคาร พาณิชย์	สำหรับอาคารอยู่ อาศัยและอาคาร พาณิชย์	สำหรับอาคารอยู่ อาศัยและอาคาร พาณิชย์	
	เพิ่มขึ้นจาก ปริมาณในน้ำใช้ ปกติไม่เกิน ๑,๐๐๐ สำหรับอาคาร สถานพยาบาล	เพิ่มขึ้นจาก ปริมาณในน้ำใช้ ปกติไม่เกิน ๑,๐๐๐ สำหรับอาคาร สถานพยาบาล	-	-
๕. ซัลไฟด์ (Sulfide)	ไม่เกิน ๑.๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๑.๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๑.๐ มิลลิกรัมต่อลิตร	-
๖. ทีเคเอ็น (Total Kjeldahl Nitrogen)	ไม่เกิน ๓๕ มิลลิกรัมต่อลิตร	ไม่เกิน ๓๕ มิลลิกรัมต่อลิตร	ไม่เกิน ๔๐ มิลลิกรัมต่อลิตร	-
๗. น้ำมันและไขมัน (Oil and Grease)	ไม่เกิน ๒๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๒๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๒๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๒๐ มิลลิกรัมต่อลิตร สำหรับอาคารอยู่อาศัย
				ไม่เกิน ๕๐ มิลลิกรัม ต่อลิตร สำหรับอาคาร พาณิชย์และอาคาร สถานพยาบาล
๘. แบคทีเรียกลุ่มโคลิฟอร์มทั้งหมด (Total Coliform Bacteria) (สำหรับอาคารสถานพยาบาล)	ไม่เกิน ๕,๐๐๐ (เอ็มพีเอ็นต่อ ๑๐๐ มิลลิลิตร)	ไม่เกิน ๕,๐๐๐ (เอ็มพีเอ็นต่อ ๑๐๐ มิลลิลิตร)	-	-
๙. แบคทีเรียกลุ่มฟิคอลโคลิฟอร์ม (Fecal Coliform Bacteria) (สำหรับอาคารสถานพยาบาล)	ไม่เกิน ๑,๐๐๐ (เอ็มพีเอ็นต่อ ๑๐๐ มิลลิลิตร)	ไม่เกิน ๑,๐๐๐ (เอ็มพีเอ็นต่อ ๑๐๐ มิลลิลิตร)	-	-
๑๐. คลอรีนอิสระ (Free Chlorine) (สำหรับอาคารสถานพยาบาล)	ไม่เกิน ๑.๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๑.๐ มิลลิกรัมต่อลิตร	-	-

ข้อ ๖ การตรวจสอบมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารให้ใช้วิธีการ ดังต่อไปนี้

๖.๑ ความเป็นกรดและด่าง ให้ใช้เครื่องวัดความเป็นกรดและด่างของน้ำ (pH Meter) ที่มีความละเอียดไม่ต่ำกว่า ๐.๑ หน่วย

๖.๒ บีโอดี ให้ใช้วิธีบ่มตัวอย่างที่อุณหภูมิ ๒๐ องศาเซลเซียส เป็นเวลา ๕ วันติดต่อกัน และหาค่าออกซิเจนละลายด้วยวิธีเอไซด์มอดิฟิเคชัน (Azide Modification) หรือวิธีเมมเบรนอิเล็กโทรด (Membrane Electrode) หรือวิธีออปติคัลโพรบ (Optical Probe)

๖.๓ ของแข็งแขวนลอยทั้งหมด ให้ใช้วิธีการกรองผ่านกระดาษกรองใยแก้ว (Glass Fiber Filter) และอบแห้งที่อุณหภูมิ ตั้งแต่ ๑๐๓ ถึง ๑๐๕ องศาเซลเซียส เป็นเวลาอย่างน้อย ๑ ชั่วโมง

๖.๔ ของแข็งละลายน้ำทั้งหมด ให้ใช้วิธีระเหยตัวอย่างที่กรองผ่านกระดาษกรองใยแก้ว (Glass Fiber Filter) และอบแห้งที่อุณหภูมิ ๑๘๐ องศาเซลเซียส เป็นเวลาอย่างน้อย ๑ ชั่วโมง

๖.๕ ซัลไฟด์ ให้ใช้วิธีไอโอดิเมทริก (Iodometric Method) หรือวิธีเมทิลีนบลู (Methylene Blue Method)

๖.๖ ทีเคเอ็น ให้ใช้วิธีเจลดาล์ (Kjeldahl)

๖.๗ น้ำมันและไขมัน ให้ใช้วิธีสกัดด้วยตัวทำละลายแล้วแยกหาน้ำหนักของน้ำมันและไขมัน

๖.๘ แบคทีเรียกลุ่มโคลิฟอร์มทั้งหมดและแบคทีเรียกลุ่มฟิคอลโคลิฟอร์ม ให้ใช้วิธีมัลติเพิล ทิวบ์ เฟอ์เมนเทชัน เทคนิค (Multiple Tube Fermentation Technique)

๖.๙ คลอรีนอิสระ ให้ใช้วิธีไทเทรต (Titrimetric method) หรือวิธีเทียบสี (Colorimetric method) หรือวิธีไอโอดิเมทริก อิเล็กโทรด (Iodometric Electrode Technique)

ข้อ ๗ การคิดคำนวณขนาดของอาคารตามข้อ ๔ ให้เป็นไปตามวิธีการที่คณะกรรมการควบคุมมลพิษกำหนด โดยประกาศในราชกิจจานุเบกษา

ข้อ ๘ การตรวจสอบค่ามาตรฐานน้ำทิ้งตามข้อ ๖ ต้องเป็นไปตามคู่มือวิเคราะห์น้ำและน้ำเสียของสมาคมวิศวกรรมสิ่งแวดล้อมแห่งประเทศไทย หรือ Standard Methods for the Examination of Water and Wastewater ซึ่ง American Public Health Association, American Water Works Association และ Water Environment Federation ของประเทศสหรัฐอเมริกากำหนดฉบับล่าสุด หรือตามที่คณะกรรมการควบคุมมลพิษประกาศในราชกิจจานุเบกษา

ข้อ ๙ การเก็บตัวอย่างน้ำทิ้งเพื่อการตรวจสอบมาตรฐานควบคุมการระบายน้ำทิ้งตามข้อ ๕ ให้เป็น ดังต่อไปนี้

๙.๑ ให้เก็บในจุดระบายทิ้งลงสู่แหล่งน้ำสาธารณะหรือออกสู่สิ่งแวดล้อมหรือจุดอื่นที่สามารถใช้เป็นตัวแทนของน้ำทิ้งที่ระบายออกจากอาคาร ในกรณีมีการระบายทิ้งหลายจุดให้เก็บทุกจุด

๙.๒ วิธีการเก็บตัวอย่างน้ำทิ้ง ณ จุดเก็บตัวอย่างตามข้อ ๙.๑ ให้เก็บแบบจ้วง (Grab Sampling)

ข้อ ๑๐ ประกาศนี้ให้ใช้บังคับตั้งแต่วันถัดจากวันประกาศในราชกิจจานุเบกษาเป็นต้นไป

ประกาศ ณ วันที่ ๒๘ มิถุนายน พ.ศ. ๒๕๖๗

พลตำรวจเอก พัชรวาท วงษ์สุวรรณ

รัฐมนตรีว่าการกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม