

ภาคผนวกที่ 6

แบบบันทึกการตรวจสอบงัดดับเพลิง

FIRE EXTINGUISHER CHECK LIST (Villa)

Month: July-25

No	Location	Type					Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	Blanket	Recharge	Ready	Overcharge	Yes	No		
1	Villa 1	✓						✓			✓		
2	Villa 2	✓						✓			✓		
3	Villa 3	✓						✓			✓		
4	Villa 5	✓						✓			✓		
5	Villa 6	✓						✓			✓		
6	Villa 7	✓						✓			✓		
7	Villa 8	✓						✓			✓		
8	Villa 9	✓						✓			✓		
9	Villa 10	✓						✓			✓		
10	Villa 11	✓						✓			✓		
11	Villa 12				✓			✓			✓		
12	Villa 14				✓			✓			✓		
13	Villa 15				✓			✓			✓		
14	Villa 16	✓						✓			✓		
15	Villa 17	✓						✓			✓		
16	Villa 18	✓						✓			✓		
17	Villa 19	✓						✓			✓		
18	Villa 20	✓						✓			✓		
19	Villa 21	✓						✓			✓		
20	Villa 22	✓						✓			✓		
21	Villa 23	✓						✓			✓		
22	Villa 24	✓						✓			✓		
23	Villa 25	✓						✓			✓		
24	Villa 26	✓						✓			✓		
25	Villa 27	✓						✓			✓		
26	Villa 28	✓						✓			✓		
27	Villa 29	✓						✓			✓		
28	Villa 30	✓						✓			✓		
29	Villa 31	✓						✓			✓		
30	Villa 32	✓						✓			✓		
31	Villa 33	✓						✓			✓		
32	Villa 34	✓						✓			✓		
33	Villa 35	✓						✓			✓		
34	Villa 36	✓						✓			✓		
35	Villa 37	✓						✓			✓		
36	Villa 38	✓						✓			✓		
37	Villa 39	✓						✓			✓		
38	Villa 40	✓						✓			✓		
39	Villa 41	✓						✓			✓		
40	Villa 42	✓						✓			✓		
41	Villa 43	✓						✓			✓		
42	Villa 88	✓						✓			✓		refill

42	Villa 88	✓					✓			✓		
43	Villa 45				✓		✓			✓		
44	Villa 46	✓					✓			✓		
45	Villa 47	✓					✓			✓		
46	Villa 48	✓					✓			✓		
47	Villa 49	✓					✓			✓		
48	Villa 50				✓		✓			✓		
49	Villa 51	✓					✓			✓		
50	Villa 52	✓					✓			✓		
51	Villa 53	✓					✓			✓		
52	Villa 54	✓					✓			✓		
53	Villa 55	✓					✓			✓		
54	Villa 56				✓		✓			✓		
55	Villa 57	✓					✓			✓		
56	Villa 58	✓					✓			✓		
57	Villa 59	✓					✓			✓		
58	Villa 60	✓					✓			✓		
59	Villa 61	✓					✓			✓		
60	Villa 62	✓					✓			✓		
61	Villa 63	✓					✓			✓		
62	Villa 64	✓					✓			✓		
63	Villa 65	✓					✓			✓		
64	Villa 66	✓					✓			✓		
65	Villa 67	✓					✓			✓		
66	Villa 68	✓					✓			✓		
67	Villa 69	✓					✓			✓		
68	Villa 71	✓					✓			✓		
69	Villa 74	✓					✓			✓		
70	Villa 75	✓					✓			✓		
71	Villa 79				✓		✓			✓		
72	Villa 81	✓					✓			✓		
73	Villa 83	✓					✓			✓		
74	Villa 86				✓		✓			✓		
75	Villa 91	✓					✓			✓		
76	Villa 96	✓					✓			✓		
77	Villa 98	✓					✓			✓		

Prepared by Mr. Chainaphon Damrit/LPS

Acknowledged by _____/LPM

FIRE EXTINGUISHER CHECK LIST (BOH)													
													Month: July-25
No	Location	Type					Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	BF200	Blanket	Recharge	Ready	Overcharge	Yes		
1	Pier				✓			✓			✓		
2	Security hut				✓			✓			✓		refill
3	Ban chailay 1				✓			✓			✓		
4	Ban chailay 2				✓			✓			✓		
5	Ban chailay 3+4				✓			✓			✓		
6	Ban chailay 5+6				✓			✓			✓		
7	Ban chailay 7+8				✓			✓			✓		
8	Purchasing office				✓			✓			✓		
9	Dry store				✓			✓			✓		
10	Accounting office				✓			✓			✓		
11	Canteen Kitchen						✓	✓			✓		
12	Human resource			✓	✓			✓			✓		
13	Housekeeping				✓			✓			✓		
14	Canteen gas store 1	✓			✓			✓			✓		15 Pound
	Canteen gas store 2	✓			✓			✓			✓		15 Pound
15	ENG carpenter room				✓			✓			✓		
16	ENG work shop 1				✓			✓			✓		
17	ENG work shop 2				✓			✓			✓		
18	Fire pump				✓			✓			✓		
19	Pump room				✓			✓			✓		
20	Eng meeting room				✓			✓			✓		
21	MDB Room				✓			✓			✓		
22	Generator 1				✓			✓			✓		
23	Generator 2				✓			✓					
24	Generator 3				✓			✓			✓		
25	Multipropose Sala				✓			✓			✓		
26	IT office					✓		✓			✓		
	IT office				✓			✓			✓		
27	Meeting room				✓			✓			✓		
28	Spa reception				✓			✓			✓		
29	Spa changing room				✓			✓			✓		
30	Spa store				✓			✓			✓		
31	Spa treatment walk way				✓			✓			✓		
32	Spa Lily room				✓			✓			✓		
33	Gym				✓			✓			✓		
34	Naka retail				✓			✓			✓		
35	Kids room				✓			✓			✓		
36	Rum Chapel	✓			✓			✓			✓		
37	Rum Chapel gas store 1	✓						✓			✓		15 Pound
38	Rum Chapel gas store 2	✓			✓			✓			✓		15 Pound
39	Pool Hut				✓			✓			✓		
40	Beverage Store				✓			✓			✓		
41	Tonsai bar				✓			✓			✓		
42	Tonsai kitchen			✓				✓			✓		
							✓	✓			✓		
43	Tonsai gas store 1	✓						✓			✓		15 Pound
44	Tonsai gas store 2	✓			✓			✓			✓		15 Pound
45	Water sport				✓			✓			✓		
46	Libraly	✓						✓			✓		
47	Sala pool				✓			✓			✓		
48	Z bar				✓			✓			✓		
89	Electrical room V.19-20				✓			✓			✓		
50	Electrical room opposite V.41	✓			✓			✓			✓		
51	Electrical room opposite V.67	✓						✓			✓		
52	Electrical room V.30-31				✓			✓			✓		
53	Smoking Area				✓			✓			✓		

FIRE CABINET CHECKLIST

Month: Jul-25

No	Update Photos	Photos	Location	fire equipment									Remark
				หัวจ่ายน้ำ	ที่เปิดวาล์วน้ำ	สายฉีดแบบพอลิไธรม	หัวฉีดน้ำ	รอมหัวและซิล	ตู้	กระบอก	ขวาน	พื้นที่	
1			Back of house.	✓	1	2	✓	✓	✓	✓	✓	✓	
2			Back of Engineering building	No	1	2	✓	✓	✓	✓	✓	✓	1.The hydrant was broken
3			Nearest the meeting building	✓	1	2	✓	✓	✓	✓	✓	✓	
4			Entrance to Villa 1-7.	✓	1	1	✓	✓	✓	✓	✓	✓	
5			Between Villa 30-31	✓	1	2	✓	✓	✓	✓	✓	✓	
6			Between Villa 19-20.	✓	1	2	2	✓	✓	✓	✓	✓	1. There is an obstacle. /Engineering
7			Opposite villa 41	✓	1	2	1	✓	✓	✓	✓	✓	1.The cabinet has a little rust.

8			Between Villa 48-49	√	1	2	1	√	√	√	√	√	
9			Between Villa 58-59	√	1	2	2	√	√	√	√	√	
10	 	 	Back of Villa 78	√	1	2	√	√	√	√	√	√	
11	 	 	Front Store gas Tonsai restaurant	√	1	2	√	√	√	√	√	√	

Prepared by Mr.Chainaphon Damrit (LPS)

Acknowledged by Mr. Kaweewat Kaminsin / LPM

[illegible]

Month: Jul-25

FIRE HOSE CABINET & HYDRANT CHECK LIST												
No.	Location	fire equipment								Photos	Status	Remark
		หัวจ่ายน้ำ	ที่เปิดวาล์วน้ำ	สายฉีด	หัวฉีดน้ำ	รอยรั่วและซีล	สภาพตู้	กระจก	ขวาน			
1	Receiving area	OK	-	-	-	-	-	-	-			
2	Behind Canteen	OK	-	✓	✓	✕	✕	✓	✓			The fire cabinet has rusted.
3	Behind Building Management	OK	✓	✓	✕	✕	✕	✕	✓			The fire cabinet has rusted and the glass is broken.

Checked by Ms. Jeerapa / OH&S S

Acknowledged by _____/LPM

FIRE EXTINGUISHER CHECK LIST (Villa)

Month: August-25

No	Location	Type					Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	Blanket	Recharge	Ready	Overcharge	Yes	No		
1	Villa 1	✓						✓			✓		
2	Villa 2	✓						✓			✓		
3	Villa 3	✓						✓			✓		
4	Villa 5	✓						✓			✓		
5	Villa 6	✓						✓			✓		
6	Villa 7	✓						✓			✓		
7	Villa 8	✓						✓			✓		
8	Villa 9	✓						✓			✓		
9	Villa 10	✓						✓			✓		
10	Villa 11	✓						✓			✓		
11	Villa 12				✓			✓			✓		
12	Villa 14				✓			✓			✓		
13	Villa 15				✓			✓			✓		
14	Villa 16	✓						✓			✓		
15	Villa 17	✓						✓			✓		
16	Villa 18	✓						✓			✓		
17	Villa 19	✓						✓			✓		
18	Villa 20	✓						✓			✓		
19	Villa 21	✓						✓			✓		
20	Villa 22	✓						✓			✓		
21	Villa 23	✓						✓			✓		
22	Villa 24	✓						✓			✓		
23	Villa 25	✓						✓			✓		
24	Villa 26	✓						✓			✓		
25	Villa 27	✓						✓			✓		
26	Villa 28	✓						✓			✓		
27	Villa 29	✓						✓			✓		
28	Villa 30	✓						✓			✓		
29	Villa 31	✓						✓			✓		
30	Villa 32	✓						✓			✓		
31	Villa 33	✓						✓			✓		
32	Villa 34	✓						✓			✓		
33	Villa 35	✓						✓			✓		
34	Villa 36	✓						✓			✓		
35	Villa 37	✓						✓			✓		
36	Villa 38	✓						✓			✓		
37	Villa 39	✓						✓			✓		
38	Villa 40	✓						✓			✓		
39	Villa 41	✓						✓			✓		
40	Villa 42	✓						✓			✓		
41	Villa 43	✓						✓			✓		
42	Villa 88	✓						✓			✓		refill
	Villa 88	✓						✓			✓		
43	Villa 45				✓			✓			✓		
44	Villa 46	✓						✓			✓		
45	Villa 47	✓						✓			✓		
46	Villa 48	✓						✓			✓		
47	Villa 49	✓						✓			✓		

48	Villa 50	✓			✓			✓			✓		
49	Villa 51	✓			✓			✓			✓		
50	Villa 52	✓			✓			✓			✓		
51	Villa 53	✓			✓			✓			✓		
52	Villa 54	✓			✓			✓			✓		
53	Villa 55	✓			✓			✓			✓		
54	Villa 56	✓			✓			✓			✓		
55	Villa 57	✓			✓			✓			✓		
56	Villa 58	✓			✓			✓			✓		
57	Villa 59	✓			✓			✓			✓		
58	Villa 60	✓			✓			✓			✓		
59	Villa 61	✓			✓			✓			✓		
60	Villa 62	✓			✓			✓			✓		
61	Villa 63	✓			✓			✓			✓		
62	Villa 64	✓			✓			✓			✓		
63	Villa 65	✓			✓			✓			✓		
64	Villa 66	✓			✓			✓			✓		
65	Villa 67	✓			✓			✓			✓		
66	Villa 68	✓			✓			✓			✓		
67	Villa 69	✓			✓			✓			✓		
68	Villa 71	✓			✓			✓			✓		
69	Villa 74	✓			✓			✓			✓		
70	Villa 75	✓			✓			✓			✓		
71	Villa 79	✓			✓			✓			✓		
72	Villa 81	✓			✓			✓			✓		
73	Villa 83	✓			✓			✓			✓		
74	Villa 86	✓			✓			✓			✓		
75	Villa 91	✓			✓			✓			✓		
76	Villa 96	✓			✓			✓			✓		
77	Villa 98	✓			✓			✓			✓		

Prepared by Mr. Chainaphon Damrit/LPS

Acknowledged by _____/LPM

FIRE EXTINGUISHER CHECK LIST (BOH)

Month: August-25

No	Location	Type						Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	BF200	Blanket	Recharge	Ready	Overcharge	Yes	No		
1	Pier	✓			✓			✓			✓			
2	Security hut	✓			✓			✓			✓			refill
3	Ban chailay 1	✓			✓			✓			✓			
4	Ban chailay 2	✓			✓			✓			✓			
5	Ban chailay 3+4	✓			✓			✓			✓			
6	Ban chailay 5+6	✓			✓			✓			✓			
7	Ban chailay 7+8	✓			✓			✓			✓			
8	Purchasing office	✓			✓			✓			✓			
9	Dry store	✓			✓			✓			✓			
10	Accounting office	✓			✓			✓			✓			
11	Canteen Kitchen	✓			✓		✓	✓			✓			
12	Human resource	✓		✓	✓			✓			✓			
13	Housekeeping	✓			✓			✓			✓			
14	Canteen gas store 1	✓			✓			✓			✓			15 Pound
	Canteen gas store 2	✓			✓			✓			✓			15 Pound
15	ENG carpenter room	✓			✓			✓			✓			
16	ENG work shop 1	✓			✓			✓			✓			
17	ENG work shop 2	✓			✓			✓			✓			
18	Fire pump	✓			✓			✓			✓			
19	Pump room	✓			✓			✓			✓			
20	Eng meeting room	✓			✓			✓			✓			
21	MDB Room	✓			✓			✓			✓			
22	Generator 1	✓			✓			✓			✓			
23	Generator 2	✓			✓			✓			✓			
24	Generator 3	✓			✓			✓			✓			
25	Multipropose Sala	✓			✓			✓			✓			
26	IT office	✓			✓	✓		✓			✓			
	IT office	✓			✓			✓			✓			
27	Meeting room	✓			✓			✓			✓			
28	Spa reception	✓			✓			✓			✓			
29	Spa changing room	✓			✓			✓			✓			
30	Spa store	✓			✓			✓			✓			
31	Spa treatment walk way	✓			✓			✓			✓			
32	Spa Lily room	✓			✓			✓			✓			
33	Gym	✓			✓			✓			✓			
34	Naka retail	✓			✓			✓			✓			
35	Kids room	✓			✓			✓			✓			
36	Rum Chapel	✓			✓			✓			✓			
37	Rum Chapel gas store 1	✓			✓			✓			✓			15 Pound
38	Rum Chapel gas store 2	✓			✓			✓			✓			15 Pound
39	Pool Hut	✓			✓			✓			✓			
40	Beverage Store	✓			✓			✓			✓			
41	Tonsai bar	✓			✓			✓			✓			
42	Tonsai kitchen	✓		✓	✓			✓			✓			
		✓			✓		✓	✓			✓			
43	Tonsai gas store 1	✓			✓			✓			✓			15 Pound
44	Tonsai gas store 2	✓			✓			✓			✓			15 Pound
45	Water sport	✓			✓			✓			✓			
46	Libraly	✓			✓			✓			✓			
47	Sala pool	✓			✓			✓			✓			
48	Z bar	✓			✓			✓			✓			
89	Electrical room V.19-20	✓			✓			✓			✓			
50	Electrical room opposite V.41	✓			✓			✓			✓			
51	Electrical room opposite V.67	✓			✓			✓			✓			
52	Electrical room V.30-31	✓			✓			✓			✓			
53	Smoking Area	✓			✓			✓			✓			

Prepared by Mr. Naruedom Na Thalang/LPO

Acknowledged by _____/LPM

FIRE CABINET CHECKLIST

Month: August-25

No	Update Photos	Photos	Location	Fire equipment										Remark
				หัวจ่ายน้ำ	ที่เปิดวาล์วน้ำ	สายฉีดแบบพ่นฝอย	หัวฉีดน้ำ	รอกชักและถัง	ถัง	กระบอก	ขวาน	พื้นที่		
1			Back of house.	✓	1	2	✓	✓	✓	✓	✓	✓		
2			Back of Engineering building	No	1	2	✓	✓	✓	✓	✓	✓	1.The hydrant was broken	
3			Nearest the meeting building	✓	1	2	✓	✓	✓	✓	✓	✓		
4			Entrance to Villa 1-7.	✓	1	1	✓	✓	✓	✓	✓	✓		
5			Between Villa 30-31	✓	1	2	✓	✓	✓	✓	✓	✓		
6			Between Villa 19-20.	✓	1	2	2	✓	✓	✓	✓	✓	1. There is an obstacle. /Engineering	
7			Opposite villa 41	✓	1	2	1	✓	✓	✓	✓	✓	1.The cabinet has a little rust.	
8			Between Villa 48-49	✓	1	2	1	✓	✓	✓	✓	✓		

9		Between Villa 58-59	✓	1	2	2	✓	✓	✓	✓	✓	
10		Back of Villa 78	✓	1	2	✓	✓	✓	✓	✓	✓	
11		Front Store gas Tonsai restaurant	✓	1	2	✓	✓	✓	✓	✓	✓	

Prepared by Mr.Chainaphon Damrit (LPS)

Acknowledged by Mr. Kaweewat Kaminsin / LPM

FIRE EXTINGUISHER CHECK LIST (Star Home)

Month: August-25

[illegible]

FIRE HOSE CABINET & HYDRANT CHECK LIST												
No.	Location	fire equipment								Photos	Status	Remark
		หัวจ่ายน้ำ	ที่เปิดวาล์วน้ำ	สายฉีด	หัวฉีดน้ำ	รอยรั่วและซีล	สภาพตู้	กระจก	ขวาน			
1	Receiving area	OK	-	-	-	-	-	-	-			
2	Behind Canteen	OK	-	✓	✓	✕	✕	✓	✓			The fire cabinet has rusted.
3	Behind Building Management	OK	✓	✓	✕	✕	✕	✕	✓			The fire cabinet has rusted and the glass is broken.

Checked by Ms. Jeerapa / OH&S S

Acknowledged by _____/LPM

FIRE EXTINGUISHER CHECK LIST (Villa)

Month: September-25

No	Location	Type					Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	Blanket	Recharge	Ready	Overcharge	Yes	No		
1	Villa 1	✓						✓			✓		
2	Villa 2	✓						✓			✓		
3	Villa 3	✓						✓			✓		
4	Villa 5	✓						✓			✓		
5	Villa 6	✓						✓			✓		
6	Villa 7	✓						✓			✓		
7	Villa 8	✓						✓			✓		
8	Villa 9	✓						✓			✓		
9	Villa 10	✓						✓			✓		
10	Villa 11	✓						✓			✓		
11	Villa 12				✓			✓			✓		
12	Villa 14				✓			✓			✓		
13	Villa 15				✓			✓			✓		
14	Villa 16	✓						✓			✓		
15	Villa 17	✓						✓			✓		
16	Villa 18	✓						✓			✓		
17	Villa 19	✓						✓			✓		
18	Villa 20	✓						✓			✓		
19	Villa 21	✓						✓			✓		
20	Villa 22	✓						✓			✓		
21	Villa 23	✓						✓			✓		
22	Villa 24	✓						✓			✓		
23	Villa 25	✓						✓			✓		
24	Villa 26	✓						✓			✓		
25	Villa 27	✓						✓			✓		
26	Villa 28	✓						✓			✓		
27	Villa 29	✓						✓			✓		
28	Villa 30	✓						✓			✓		
29	Villa 31	✓						✓			✓		
30	Villa 32	✓						✓			✓		
31	Villa 33	✓						✓			✓		
32	Villa 34	✓						✓			✓		
33	Villa 35	✓						✓			✓		
34	Villa 36	✓						✓			✓		
35	Villa 37	✓						✓			✓		
36	Villa 38	✓						✓			✓		
37	Villa 39	✓						✓			✓		
38	Villa 40	✓						✓			✓		
39	Villa 41	✓						✓			✓		
40	Villa 42	✓						✓			✓		
41	Villa 43	✓						✓			✓		
42	Villa 88	✓						✓			✓		
	Villa 88	✓						✓			✓		
43	Villa 45				✓			✓			✓		
44	Villa 46	✓						✓			✓		
45	Villa 47	✓						✓			✓		
46	Villa 48	✓						✓			✓		
47	Villa 49	✓						✓			✓		

48	Villa 50	✓			✓			✓			✓		
49	Villa 51	✓			✓			✓			✓		
50	Villa 52	✓			✓			✓			✓		
51	Villa 53	✓			✓			✓			✓		
52	Villa 54	✓			✓			✓			✓		
53	Villa 55	✓			✓			✓			✓		
54	Villa 56	✓			✓			✓			✓		
55	Villa 57	✓			✓			✓			✓		
56	Villa 58	✓			✓			✓			✓		
57	Villa 59	✓			✓			✓			✓		
58	Villa 60	✓			✓			✓			✓		
59	Villa 61	✓			✓			✓			✓		
60	Villa 62	✓			✓			✓			✓		
61	Villa 63	✓			✓			✓			✓		
62	Villa 64	✓			✓			✓			✓		
63	Villa 65	✓			✓			✓			✓		
64	Villa 66	✓			✓			✓			✓		
65	Villa 67	✓			✓			✓			✓		
66	Villa 68	✓			✓			✓			✓		
67	Villa 69	✓			✓			✓			✓		
68	Villa 71	✓			✓			✓			✓		
69	Villa 74	✓			✓			✓			✓		
70	Villa 75	✓			✓			✓			✓		
71	Villa 79	✓			✓			✓			✓		
72	Villa 81	✓			✓			✓			✓		
73	Villa 83	✓			✓			✓			✓		
74	Villa 86	✓			✓			✓			✓		
75	Villa 91	✓			✓			✓			✓		
76	Villa 96	✓			✓			✓			✓		
77	Villa 98	✓			✓			✓			✓		

Prepared by Mr. Chainaphon Damrit/LPS

Acknowledged by _____/LPM

FIRE EXTINGUISHER CHECK LIST (BOH)

Month: September-25

No	Location	Type						Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	BF200	Blanket	Recharge	Ready	Overcharge	Yes	No		
1	Pier				✓			✓				✓		
2	Security hut				✓			✓				✓		refill
3	Ban chailay 1				✓			✓				✓		
4	Ban chailay 2				✓			✓				✓		
5	Ban chailay 3+4				✓			✓				✓		
6	Ban chailay 5+6				✓			✓				✓		
7	Ban chailay 7+8				✓			✓				✓		
8	Purchasing office				✓			✓				✓		
9	Dry store				✓			✓				✓		
10	Accounting office				✓			✓				✓		
11	Canteen Kitchen				✓		✓	✓				✓		
12	Human resource			✓	✓			✓				✓		
13	Housekeeping				✓			✓				✓		
14	Canteen gas store 1	✓			✓			✓				✓		15 Pound
	Canteen gas store 2	✓			✓			✓				✓		15 Pound
15	ENG carpenter room				✓			✓				✓		
16	ENG work shop 1				✓			✓				✓		
17	ENG work shop 2				✓			✓				✓		
18	Fire pump				✓			✓				✓		
19	Pump room				✓			✓				✓		
20	Eng meeting room				✓			✓				✓		
21	MDB Room				✓			✓				✓		
22	Generator 1				✓			✓				✓		
23	Generator 2				✓			✓				✓		
24	Generator 3				✓			✓				✓		
25	Multipropose Sala				✓			✓				✓		
26	IT office				✓	✓		✓				✓		
	IT office				✓			✓				✓		
27	Meeting room				✓			✓				✓		
28	Spa reception				✓			✓				✓		
29	Spa changing room				✓			✓				✓		
30	Spa store				✓			✓				✓		
31	Spa treatment walk way				✓			✓				✓		
32	Spa Lily room				✓			✓				✓		
33	Gym	✓			✓			✓				✓		
34	Naka retail				✓			✓				✓		
35	Kids room				✓			✓				✓		
36	Rum Chapel	✓			✓			✓				✓		
37	Rum Chapel gas store 1	✓			✓			✓				✓		15 Pound
38	Rum Chapel gas store 2	✓			✓			✓				✓		15 Pound
39	Rum Chapel Kitchen			✓	✓			✓				✓		
40	Pool Hut				✓			✓				✓		
41	Beverage Store				✓			✓				✓		
42	Tonsai bar				✓			✓				✓		
43	Tonsai kitchen			✓	✓			✓				✓		
							✓	✓				✓		
44	Tonsai gas store 1	✓			✓			✓				✓		15 Pound
45	Tonsai gas store 2	✓			✓			✓				✓		15 Pound
46	Water sport				✓			✓				✓		
47	Libraly	✓			✓			✓				✓		
48	Sala pool				✓			✓				✓		
49	Z bar				✓			✓				✓		
50	Electrical room V.19-20				✓			✓				✓		
51	Electrical room opposite V.41	✓			✓			✓				✓		
52	Electrical room opposite V.67	✓			✓			✓				✓		
53	Electrical room V.30-31				✓			✓				✓		
54	Smoking Area				✓			✓				✓		


Prepared by Mr. Naruedom Na Thalang/LPO

Acknowledged by _____/LPM

FIRE CABINET CHECKLIST

Month: September-25

No	Update Photos	Photos	Location	Fire equipment										Remark
				หัวจ่ายน้ำ	ที่เปิดวาล์วน้ำ	สายฉีดแบบพ่นฝอย	หัวฉีดน้ำ	รอกช่วยและซิล	ตู้	กระจก	ขวาน	พื้นที่		
1			Back of house.	✓	1	2	✓	✓	✓	✓	✓	✓		
2			Back of Engineering building	No	1	2	✓	✓	✓	✓	✓	✓	1.The hydrant was broken	
3			Nearest the meeting building	✓	1	2	✓	✓	✓	✓	✓	✓		
4			Entrance to Villa 1-7.	✓	1	1	✓	✓	✓	✓	✓	✓		
5			Between Villa 30-31	✓	1	2	✓	✓	✓	✓	✓	✓		
6			Between Villa 19-20.	✓	1	2	2	✓	✓	✓	✓	✓	1. There is an obstacle. /Engineering	
7			Opposite villa 41	✓	1	2	1	✓	✓	✓	✓	✓	1.The cabinet has a little rust.	
8			Between Villa 48-49	No	1	2	1	✓	✓	✓	✓	✓	The cover of the hydrant can hard open	

9			Between Villa 58-59	✓	1	2	2	✓	✓	✓	✓	✓	
10			Back of Villa 78	✓	1	2	✓	✓	✓	✓	✓	✓	
11			Front Store gas Tonsai restaurant	✓	1	2	✓	✓	✓	✓	✓	✓	

Prepared by Mr.Kritsanapong Kayee (LPO)

Acknowledged by Mr. Kaweewat Kaminsin / LPM

FIRE EXTINGUISHER CHECK LIST (Star Home)

Month: September-25

[illegible]

FIRE HOSE CABINET & HYDRANT CHECK LIST												
No.	Location	fire equipment								Photos	Status	Remark
		หัวจ่ายน้ำ	ที่เปิดวาล์วน้ำ	สายฉีด	หัวฉีดน้ำ	รอยรั่วและซีล	สภาพตู้	กระจก	ขวาน			
1	Receiving area	OK	-	-	-	-	-	-	-			
2	Behind Canteen	OK	-	✓	✓	✕	✕	✓	✓			The fire cabinet has rusted.
3	Behind Building Management	OK	✓	✓	✕	✕	✕	✕	✓			The fire cabinet has rusted and the glass is broken.

Checked by Ms. Jeerapa / OH&S S

Acknowledged by _____/LPM

FIRE EXTINGUISHER CHECK LIST (Villa)

Month: October-25

No	Location	Type					Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	Blanket	Recharge	Ready	Overcharge	Yes	No		
1	Villa 1	✓						✓			✓		
2	Villa 2	✓						✓			✓		
3	Villa 3	✓						✓			✓		
4	Villa 5	✓						✓			✓		
5	Villa 6	✓						✓			✓		
6	Villa 7	✓						✓			✓		
7	Villa 8	✓						✓			✓		
8	Villa 9	✓						✓			✓		
9	Villa 10	✓						✓			✓		
10	Villa 11	✓						✓			✓		
11	Villa 12				✓			✓			✓		
12	Villa 14				✓			✓			✓		
13	Villa 15				✓			✓			✓		
14	Villa 16	✓						✓			✓		
15	Villa 17	✓						✓			✓		
16	Villa 18	✓						✓			✓		
17	Villa 19	✓						✓			✓		
18	Villa 20	✓						✓			✓		
19	Villa 21	✓						✓			✓		
20	Villa 22	✓						✓			✓		
21	Villa 23	✓						✓			✓		
22	Villa 24	✓						✓			✓		
23	Villa 25	✓						✓			✓		
24	Villa 26	✓						✓			✓		
25	Villa 27	✓						✓			✓		
26	Villa 28	✓						✓			✓		
27	Villa 29	✓						✓			✓		
28	Villa 30	✓						✓			✓		
29	Villa 31	✓						✓			✓		
30	Villa 32	✓						✓			✓		
31	Villa 33	✓						✓			✓		
32	Villa 34	✓						✓			✓		
33	Villa 35	✓						✓			✓		
34	Villa 36	✓						✓			✓		
35	Villa 37	✓						✓			✓		
36	Villa 38	✓						✓			✓		
37	Villa 39	✓						✓			✓		
38	Villa 40	✓						✓			✓		
39	Villa 41	✓						✓			✓		
40	Villa 42	✓						✓			✓		
41	Villa 43	✓						✓			✓		
42	Villa 88	✓						✓			✓		
	Villa 88	✓						✓			✓		
43	Villa 45				✓			✓			✓		
44	Villa 46	✓						✓			✓		
45	Villa 47	✓						✓			✓		
46	Villa 48	✓						✓			✓		
47	Villa 49	✓						✓			✓		

48	Villa 50	✓			✓			✓			✓		
49	Villa 51	✓			✓			✓			✓		
50	Villa 52	✓			✓			✓			✓		
51	Villa 53	✓			✓			✓			✓		
52	Villa 54	✓			✓			✓			✓		
53	Villa 55	✓			✓			✓			✓		
54	Villa 56	✓			✓			✓			✓		
55	Villa 57	✓			✓			✓			✓		
56	Villa 58	✓			✓			✓			✓		
57	Villa 59	✓			✓			✓			✓		
58	Villa 60	✓			✓			✓			✓		
59	Villa 61	✓			✓			✓			✓		
60	Villa 62	✓			✓			✓			✓		
61	Villa 63	✓			✓			✓			✓		
62	Villa 64	✓			✓			✓			✓		
63	Villa 65	✓			✓			✓			✓		
64	Villa 66	✓			✓			✓			✓		
65	Villa 67	✓			✓			✓			✓		
66	Villa 68	✓			✓			✓			✓		
67	Villa 69	✓			✓			✓			✓		
68	Villa 71	✓			✓			✓			✓		
69	Villa 74	✓			✓			✓			✓		
70	Villa 75	✓			✓			✓			✓		
71	Villa 79	✓			✓			✓			✓		
72	Villa 81	✓			✓			✓			✓		
73	Villa 83	✓			✓			✓			✓		
74	Villa 86	✓			✓			✓			✓		
75	Villa 91	✓			✓			✓			✓		
76	Villa 96	✓			✓			✓			✓		
77	Villa 98	✓			✓			✓			✓		

Prepared by Mr. Chainaphon Damrit/LPS

FIRE EXTINGUISHER CHECK LIST (BOH)

Month: October-25

No	Location	Type						Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	FM200	Blanket	Recharge	Ready	Overcharge	Yes	No		
1	Pier				✓			✓				✓		
2	Security hut	✓			✓			✓				✓		
3	Ban chailay 2				✓			✓				✓		
4	Ban chailay 3+4	✓			✓			✓				✓		
5	Ban chailay 5+6	✓			✓			✓				✓		
6	Ban chailay 7+8				✓			✓				✓		
7	Purchasing office				✓			✓				✓		
8	Dry store				✓			✓				✓		
9	Accounting office				✓			✓				✓		
10	Canteen Kitchen				✓		✓	✓				✓		
11	Human resource				✓			✓				✓		
12	Housekeeping				✓			✓				✓		
13	Canteen gas store 1	✓			✓			✓				✓		
	Canteen gas store 2	✓			✓			✓				✓		15 Pound
14	ENG carpenter room				✓			✓				✓		15 Pound
15	ENG work shop 1				✓			✓				✓		
16	ENG work shop 2				✓			✓				✓		
17	Fire pump				✓			✓				✓		
18	Pump room				✓			✓				✓		
19	Eng meeting room				✓			✓				✓		
20	MDB Room				✓			✓				✓		
21	Generator 1				✓			✓				✓		
22	Generator 2				✓			✓				✓		
23	Generator 3				✓			✓				✓		
24	Multipropose Sala				✓			✓				✓		
25	IT office				✓	✓		✓				✓		
	IT office				✓			✓				✓		
26	Meeting room				✓			✓				✓		
27	Spa reception				✓			✓				✓		
28	Spa changing room				✓			✓				✓		
29	Spa store				✓			✓				✓		
30	Spa treatment walk way				✓			✓				✓		
31	Spa Lily room				✓			✓				✓		
32	Gym				✓			✓				✓		
33	Naka retail				✓			✓				✓		
34	Kids room				✓			✓				✓		
35	Rum Chapel	✓			✓			✓				✓		
36	Rum Chapel gas store 1	✓			✓			✓				✓		
37	Rum Chapel gas store 2	✓			✓			✓				✓		15 Pound
38	Rum Chapel Kitchen			✓	✓			✓				✓		15 Pound
39	Pool Hut				✓									
40	Beverage Store				✓			✓				✓		
41	Tonsai bar				✓			✓				✓		
42	Tonsai gas store 1	✓			✓			✓				✓		
	Tonsai gas store 2	✓			✓			✓				✓		
43	Water sport	✓			✓			✓				✓		15 Pound
44	Libraly				✓			✓				✓		15 Pound
45	Sala pool	✓			✓			✓				✓		
46	Z bar				✓			✓				✓		
47	Electrical room V.19-20	✓			✓			✓				✓		
48	Electrical room opposite V.41	✓			✓			✓				✓		
49	Electrical room opposite V.67	✓			✓			✓				✓		
50	Electrical room V.30-31	✓			✓			✓				✓		
51	Smoking Area				✓			✓				✓		
52	Iyara kitchen			✓	✓		✓	✓				✓		
53	Bakery kitchen				✓		✓	✓				✓		
	Tonsai kitchen				✓	✓	✓	✓				✓		

Prepared by Mr. Naruedom Na Thalang/LPO

FIRE CABINET CHECKLIST

Month: October-25

No	Update Photos	Photos	Location	Fire equipment										Remark
				น้ำยาฆ่า ไฟ	ถังดับ เพลิง	สายฉีด น้ำ	ถังดับ เพลิง	ถังดับ เพลิง	ถังดับ เพลิง	ถังดับ เพลิง	ถังดับ เพลิง	ถังดับ เพลิง	ถังดับ เพลิง	
1			Back of house.	✓	1	2	✓	✓	✓	✓	✓	✓	✓	
2			Back of Engineering building	No	1	2	✓	✓	✓	✓	✓	✓	✓	1.The hydrant was broken
3			Nearest the meeting building	✓	1	2	✓	✓	✓	✓	✓	✓	✓	
4			Entrance to Villa 1-7.	No	1	1	✓	✓	✓	✓	✓	✓	✓	1.The cover opener of the hydrant was damaged
5			Between Villa 30-31	✓	1	2	✓	✓	✓	✓	✓	✓	✓	
6			Between Villa 19-20.	✓	1	2	2	✓	✓	✓	✓	✓	✓	1. There is an obstacle. /Engineering
7			Opposite villa 41	✓	1	2	1	✓	✓	✓	✓	✓	✓	1.The cabinet has a little rust.
8			Between Villa 48-49	No	1	2	1	✓	✓	✓	✓	✓	✓	The cover of the hydrant can hard open

9		Between Villa 58-59	✓	1	2	2	✓	✓	✓	✓	✓	
10		Back of Villa 78	✓	1	2	✓	✓	✓	✓	✓	✓	
11		Front Store gas Tonsai restaurant	✓	1	2	✓	✓	✓	✓	✓	✓	

Prepared by Mr.Kritsanapong Kayee (LPO)

FIRE EXTINGUISHER CHECK LIST (Star Home)

Month: October-25

[illegible]

FIRE HOSE CABINET & HYDRANT CHECK LIST												
No.	Location	fire equipment								Photos	Status	Remark
		หัวจ่ายน้ำ	ที่เปิดวาล์วน้ำ	สายฉีด	หัวฉีดน้ำ	รอยรั่วและซีล	สภาพตู้	กระจก	ขบวน			
1	Receiving area	OK	-	-	-	-	-	-	-			
2	Behind Canteen	OK	-	✓	✓	✕	✕	✓	✓			The fire cabinet has rusted.
3	Behind Building Management	OK	✓	✓	✕	✕	✕	✕	✓			The fire cabinet has rusted and the glass is broken.

Checked by Ms. Jeerapa / OH&S S

Acknowledged by _____/LPM

FIRE EXTINGUISHER CHECK LIST (Villa)

Month: December-25

No	Location	Type					Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	Blanket	Recharge	Ready	Overcharge	Yes	No		
1	Villa 1	✓						✓			✓		
2	Villa 2	✓						✓			✓		
3	Villa 3	✓						✓			✓		
4	Villa 5	✓						✓			✓		
5	Villa 6	✓						✓			✓		
6	Villa 7	✓						✓			✓		
7	Villa 8	✓						✓			✓		
8	Villa 9	✓						✓			✓		
9	Villa 10	✓						✓			✓		
10	Villa 11	✓						✓			✓		
11	Villa 12				✓			✓			✓		
12	Villa 14				✓			✓			✓		
13	Villa 15				✓			✓			✓		
14	Villa 16	✓						✓			✓		
15	Villa 17	✓						✓			✓		
16	Villa 18	✓						✓			✓		
17	Villa 19	✓						✓			✓		
18	Villa 20	✓						✓			✓		
19	Villa 21	✓						✓			✓		
20	Villa 22	✓						✓			✓		
21	Villa 23	✓						✓			✓		
22	Villa 24	✓						✓			✓		
23	Villa 25	✓						✓			✓		
24	Villa 26	✓						✓			✓		
25	Villa 27	✓						✓			✓		
26	Villa 28	✓						✓			✓		
27	Villa 29	✓						✓			✓		
28	Villa 30	✓						✓			✓		
29	Villa 31	✓						✓			✓		
30	Villa 32	✓						✓			✓		
31	Villa 33	✓						✓			✓		
32	Villa 34	✓						✓			✓		
33	Villa 35	✓						✓			✓		
34	Villa 36	✓						✓			✓		
35	Villa 37	✓						✓			✓		
36	Villa 38	✓						✓			✓		
37	Villa 39	✓						✓			✓		
38	Villa 40	✓						✓			✓		
39	Villa 41	✓						✓			✓		
40	Villa 42	✓						✓			✓		
41	Villa 43	✓						✓			✓		
42	Villa 88	✓						✓			✓		
	Villa 88	✓						✓			✓		
43	Villa 45				✓			✓			✓		
44	Villa 46	✓						✓			✓		
45	Villa 47	✓						✓			✓		
46	Villa 48	✓						✓			✓		
47	Villa 49	✓						✓			✓		

48	Villa 50	✓			✓			✓			✓		
49	Villa 51	✓			✓			✓			✓		
50	Villa 52	✓			✓			✓			✓		
51	Villa 53	✓			✓			✓			✓		
52	Villa 54	✓			✓			✓			✓		
53	Villa 55	✓			✓			✓			✓		
54	Villa 56	✓			✓			✓			✓		
55	Villa 57	✓			✓			✓			✓		
56	Villa 58	✓			✓			✓			✓		
57	Villa 59	✓			✓			✓			✓		
58	Villa 60	✓			✓			✓			✓		
59	Villa 61	✓			✓			✓			✓		
60	Villa 62	✓			✓			✓			✓		
61	Villa 63	✓			✓			✓			✓		
62	Villa 64	✓			✓			✓			✓		
63	Villa 65	✓			✓			✓			✓		
64	Villa 66	✓			✓			✓			✓		
65	Villa 67	✓			✓			✓			✓		
66	Villa 68	✓			✓			✓			✓		
67	Villa 69	✓			✓			✓			✓		
68	Villa 71	✓			✓			✓			✓		
69	Villa 74	✓			✓			✓			✓		
70	Villa 75	✓			✓			✓			✓		
71	Villa 79	✓			✓			✓			✓		
72	Villa 81	✓			✓			✓			✓		
73	Villa 83	✓			✓			✓			✓		
74	Villa 86	✓			✓			✓			✓		
75	Villa 91	✓			✓			✓			✓		
76	Villa 96	✓			✓			✓			✓		
77	Villa 98	✓			✓			✓			✓		

Prepared by Mr. Kritsanapong Kayee/LP0

FIRE EXTINGUISHER CHECK LIST (BOH)

Month: November-25

No	Location	Type						Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	FM200	Blanket	Recharge	Ready	Overcharge	Yes	No		
1	Pier				✓			✓				✓		
2	Security hut	✓			✓			✓				✓		
3	Ban chailay 2				✓			✓				✓		
4	Ban chailay 3+4	✓			✓			✓				✓		
5	Ban chailay 5+6	✓			✓			✓				✓		
6	Ban chailay 7+8				✓			✓				✓		
7	Purchasing office				✓			✓				✓		
8	Dry store				✓			✓				✓		
9	Accounting office				✓			✓				✓		
10	Canteen Kitchen				✓		✓	✓				✓		
11	Human resource				✓			✓				✓		
12	Housekeeping				✓			✓				✓		
13	Canteen gas store 1	✓			✓			✓				✓		
	Canteen gas store 2	✓			✓			✓				✓		15 Pound
14	ENG carpenter room				✓			✓				✓		15 Pound
15	ENG work shop 1				✓			✓				✓		
16	ENG work shop 2				✓			✓				✓		
17	Fire pump				✓			✓				✓		
18	Pump room				✓			✓				✓		
19	Eng meeting room				✓			✓				✓		
20	MDB Room				✓			✓				✓		
21	Generator 1				✓			✓				✓		
22	Generator 2				✓			✓				✓		
23	Generator 3				✓			✓				✓		
24	Multipropose Sala				✓			✓				✓		
25	IT office				✓	✓		✓				✓		
	IT office				✓			✓				✓		
26	Meeting room				✓			✓				✓		
27	Spa reception				✓			✓				✓		
28	Spa changing room				✓			✓				✓		
29	Spa store				✓			✓				✓		
30	Spa treatment walk way				✓			✓				✓		
31	Spa Lily room				✓			✓				✓		
32	Gym				✓			✓				✓		
33	Naka retail				✓			✓				✓		
34	Kids room				✓			✓				✓		
35	Rum Chapel	✓			✓			✓				✓		
36	Rum Chapel gas store 1	✓			✓			✓				✓		
37	Rum Chapel gas store 2	✓			✓			✓				✓		15 Pound
38	Rum Chapel Kitchen			✓	✓			✓				✓		15 Pound
39	Pool Hut				✓									
40	Beverage Store				✓			✓				✓		
41	Veranda bar				✓			✓				✓		
42	Veranda gas store 1	✓			✓			✓				✓		
	Veranda gas store 2	✓			✓			✓				✓		
43	Water sport	✓			✓			✓				✓		15 Pound
44	Libraly				✓			✓				✓		15 Pound
45	Sala pool	✓			✓			✓				✓		
46	Z bar				✓			✓				✓		
47	Electrical room V.19-20	✓			✓			✓				✓		
48	Electrical room opposite V.41	✓			✓			✓				✓		
49	Electrical room opposite V.67	✓			✓			✓				✓		
50	Electrical room V.30-31	✓			✓			✓				✓		
51	Smoking Area				✓			✓				✓		
52	Aiyara kitchen			✓	✓		✓	✓				✓		
53	Bakery kitchen				✓		✓	✓				✓		
	Tonsai kitchen				✓									
54	Rumchapel Kitchen			✓	✓			✓				✓		

Prepared by Mr. Kritsanapong Kayee/LPO

FIRE CABINET CHECKLIST

Month: November-25

No	Update Photos	Photos	Location	Fire equipment										Remark
				หัวจ่ายน้ำ	ที่เปิดวาล์วน้ำ	สายฉีดแบบพ่นฝอย	หัวฉีดน้ำ	รอกช่วยและฮิล	ตู้	กระจก	ขวาน	พื้นที่		
1			Back of house.	✓	1	2	✓	✓	✓	✓	✓	✓		
2			Back of Engineering building	No	1	2	✓	✓	✓	✓	✓	✓	1.The hydrant was broken	
3			Nearest the meeting building	✓	1	2	✓	✓	✓	✓	✓	✓		
4			Entrance to Villa 1-7.	✓	1	1	✓	✓	✓	✓	✓	✓		
5			Between Villa 30-31	✓	1	2	✓	✓	✓	✓	✓	✓		
6			Between Villa 19-20.	✓	1	2	2	✓	✓	✓	✓	✓	1. There is an obstacle. /Engineering	
7			Opposite villa 41	✓	1	2	1	✓	✓	✓	✓	✓	1.The cabinet has a little rust.	
8			Between Villa 48-49	No	1	2	1	✓	✓	✓	✓	✓	The cover of the hydrant can hard open	

9			Between Villa 58-59	✓	1	2	2	✓	✓	✓	✓	✓	✓	
10			Back of Villa 78	✓	1	2	✓	✓	✓	✓	✓	✓	✓	
11			Front Store gas Tonsai restaurant	✓	1	2	✓	✓	✓	✓	✓	✓	✓	

Prepared by Mr.Kritsanapong Kayee (LPO)

FIRE EXTINGUISHER CHECK LIST (Star Home)

Month: November-25

[illegible]

FIRE HOSE CABINET & HYDRANT CHECK LIST												
No.	Location	fire equipment								Photos	Status	Remark
		หัวจ่ายน้ำ	ที่เปิดวาล์วน้ำ	สายฉีด	หัวฉีดน้ำ	รอยรั่วและซีล	สภาพตู้	กระจก	ขวาน			
1	Receiving area	OK	-	-	-	-	-	-	-			
2	Behind Canteen	OK	-	✓	✓	✕	✕	✓	✓			The fire cabinet has rusted.
3	Behind Building Management	OK	✓	✓	✕	✕	✕	✕	✓			The fire cabinet has rusted and the glass is broken.

Checked by Ms. Jeerapa / OH&S S

Acknowledged by _____/LPM

FIRE EXTINGUISHER CHECK LIST (Villa)

Month: December-25

No	Location	Type					Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	Blanket	Recharge	Ready	Overcharge	Yes	No		
1	Villa 1	✓						✓			✓		
2	Villa 2				✓			✓			✓		
3	Villa 3	✓						✓			✓		
4	Villa 5				✓			✓			✓		
5	Villa 6	✓						✓			✓		
6	Villa 7	✓						✓			✓		
7	Villa 8	✓						✓			✓		
8	Villa 9	✓						✓			✓		
9	Villa 10	✓						✓			✓		
10	Villa 11	✓						✓			✓		
11	Villa 12				✓			✓			✓		
12	Villa 14				✓			✓			✓		
13	Villa 15				✓			✓		Yes	✓		
14	Villa 16	✓						✓			✓		
15	Villa 17	✓						✓			✓		
16	Villa 18	✓						✓			✓		
17	Villa 19	✓						✓			✓		
18	Villa 20	✓						✓			✓		
19	Villa 21	✓						✓			✓		
20	Villa 22	✓						✓			✓		
21	Villa 23	✓						✓			✓		
22	Villa 24	✓						✓			✓		
23	Villa 25	✓						✓			✓		
24	Villa 26	✓						✓			✓		
25	Villa 27	✓						✓			✓		
26	Villa 28	✓						✓			✓		
27	Villa 29	✓						✓			✓		
28	Villa 30	✓						✓			✓		
29	Villa 31	✓						✓			✓		
30	Villa 32	✓						✓			✓		
31	Villa 33	✓						✓			✓		
32	Villa 34	✓						✓			✓		
33	Villa 35	✓						✓			✓		
34	Villa 36	✓						✓			✓		
35	Villa 37	✓						✓			✓		
36	Villa 38	✓						✓			✓		
37	Villa 39	✓						✓			✓		
38	Villa 40	✓						✓			✓		
39	Villa 41	✓						✓			✓		
40	Villa 42	✓						✓			✓		
41	Villa 43	✓						✓			✓		
42	Villa 88	✓						✓			✓		
	Villa 88	✓						✓			✓		
43	Villa 45				✓			✓			✓		
44	Villa 46	✓						✓			✓		
45	Villa 47	✓						✓			✓		
46	Villa 48	✓						✓			✓		
47	Villa 49	✓						✓			✓		

48	Villa 50	✓			✓			✓			✓		
49	Villa 51	✓			✓			✓			✓		
50	Villa 52	✓			✓			✓			✓		
51	Villa 53	✓			✓			✓			✓		
52	Villa 54	✓			✓			✓			✓		
53	Villa 55	✓			✓			✓			✓		
54	Villa 56	✓			✓			✓			✓		
55	Villa 57	✓			✓			✓			✓		
56	Villa 58	✓			✓			✓			✓		
57	Villa 59	✓			✓			✓			✓		
58	Villa 60	✓			✓			✓			✓		
59	Villa 61	✓			✓			✓			✓		
60	Villa 62	✓			✓			✓			✓		
61	Villa 63	✓			✓			✓			✓		
62	Villa 64	✓			✓			✓			✓		
63	Villa 65	✓			✓			✓			✓		
64	Villa 66	✓			✓			✓			✓		
65	Villa 67	✓			✓			✓			✓		
66	Villa 68	✓			✓			✓			✓		
67	Villa 69	✓			✓			✓			✓		
68	Villa 71	✓			✓			✓			✓		
69	Villa 74	✓			✓			✓			✓		
70	Villa 75	✓			✓			✓			✓		
71	Villa 79	✓			✓			✓			✓		
72	Villa 81	✓			✓			✓			✓		
73	Villa 83	✓			✓			✓			✓		
74	Villa 86	✓			✓			✓			✓		
75	Villa 91	✓			✓			✓			✓		
76	Villa 96	✓			✓			✓			✓		
77	Villa 98	✓			✓			✓			✓		

Prepared by Mr. Kritsanapong Kayee/LP0

FIRE EXTINGUISHER CHECK LIST (BOH)

Month: December-25

No	Location	Type						Condition			Defect		Detail	Remark
		Dry Chemical	Co2	Foam	Fireade	FM200	Blanket	Recharge	Ready	Overcharge	Yes	No		
1	Pier				✓			✓				✓		
2	Security hut	✓			✓			✓				✓		
3	Ban chailay 2				✓			✓				✓		
4	Ban chailay 3+4	✓			✓			✓				✓		
5	Ban chailay 5+6	✓			✓			✓				✓		
6	Ban chailay 7+8				✓			✓				✓		
7	Purchasing office				✓			✓				✓		
8	Dry store				✓			✓				✓		
9	Accounting office				✓			✓				✓		
10	Canteen Kitchen				✓		✓	✓				✓		
11	Human resource				✓			✓				✓		
12	Housekeeping				✓			✓				✓		
13	Canteen gas store 1	✓			✓			✓				✓		
	Canteen gas store 2	✓			✓			✓				✓		15 Pound
14	ENG carpenter room				✓			✓				✓		15 Pound
15	ENG work shop 1				✓			✓				✓		
16	ENG work shop 2				✓			✓				✓		
17	Fire pump				✓			✓				✓		
18	Pump room				✓			✓				✓		
19	Eng meeting room				✓			✓				✓		
20	MDB Room				✓			✓				✓		
21	Generator 1				✓			✓				✓		
22	Generator 2				✓			✓				✓		
23	Generator 3				✓			✓				✓		
24	Multipropose Sala				✓			✓				✓		
25	IT office				✓	✓		✓				✓		
	IT office				✓			✓				✓		
26	Meeting room				✓			✓				✓		
27	Spa reception				✓			✓				✓		
28	Spa changing room				✓			✓				✓		
29	Spa store				✓			✓				✓		
30	Spa treatment walk way				✓			✓				✓		
31	Spa Lily room				✓			✓				✓		
32	Gym				✓			✓				✓		
33	Naka retail				✓			✓				✓		
34	Kids room				✓			✓				✓		
35	Rum Chapel	✓			✓			✓				✓		
36	Rum Chapel gas store 1	✓			✓			✓				✓		
37	Rum Chapel gas store 2	✓			✓			✓				✓		15 Pound
38	Rum Chapel Kitchen			✓	✓			✓				✓		15 Pound
39	Pool Hut				✓			✓				✓		
40	Beverage Store				✓			✓				✓		
41	Veranda bar				✓			✓				✓		
42	Veranda gas store 1	✓			✓			✓				✓		
	Veranda gas store 2	✓			✓			✓				✓		
43	Water sport	✓			✓			✓				✓		15 Pound
44	Libraly				✓			✓				✓		15 Pound
45	Sala pool				✓			✓				✓		
46	Z bar				✓			✓				✓		
47	Electrical room V.19-20	✓			✓			✓				✓		
48	Electrical room opposite V.41	✓			✓			✓				✓		
49	Electrical room opposite V.67	✓			✓			✓				✓		
50	Electrical room V.30-31	✓			✓			✓				✓		
51	Smoking Area				✓			✓				✓		
52	Aiyara kitchen			✓	✓		✓	✓				✓		
53	Bakery kitchen				✓		✓	✓				✓		
	Veranda kitchen				✓			✓				✓		
54	Rumchapel Kitchen			✓	✓			✓				✓		

Prepared by Mr. Kritsanapong Kayee/LPO

FIRE CABINET CHECKLIST

Month: December-25

No	Update Photos	Photos	Location	Fire equipment										Remark
				น้ำยาฆ่า ไฟ	ถังดับ เพลิง	สายฉีด น้ำ	ถังดับ เพลิง	ถังดับ เพลิง	ถังดับ เพลิง	ถังดับ เพลิง	ถังดับ เพลิง	ถังดับ เพลิง	ถังดับ เพลิง	
1			Back of house.	✓	1	2	✓	✓	✓	✓	✓	✓	✓	
2			Back of Engineering building	No	1	2	✓	✓	✓	✓	✓	✓	✓	1.The hydrant was broken
3			Nearest the meeting building	✓	1	2	✓	✓	✓	✓	✓	✓	✓	
4			Entrance to Villa 1-7.	No	1	1	✓	✓	✓	✓	✓	✓	✓	1.The cover opener of the hydrant was damaged
5			Between Villa 30-31	✓	1	2	✓	✓	✓	✓	✓	✓	✓	
6			Between Villa 19-20.	✓	1	2	2	✓	✓	✓	✓	✓	✓	1. There is an obstacle. /Engineering
7			Opposite villa 41	✓	1	2	1	✓	✓	✓	✓	✓	✓	1.The cabinet has a little rust.
8			Between Villa 48-49	No	1	2	1	✓	✓	✓	✓	✓	✓	The cover of the hydrant can hard open

9			Between Villa 58-59	✓	1	2	2	✓	✓	✓	✓	✓	✓	
10	 	 	Back of Villa 78	✓	1	2	✓	✓	✓	✓	✓	✓		
11			Front Store gas Tonsai restaurant	✓	1	2	✓	✓	✓	✓	✓	✓		

Prepared by Mr.Kritsanapong Kayee (LPO)

FIRE EXTINGUISHER CHECK LIST (Star Home)

Month: December-25

[illegible]

FIRE HOSE CABINET & HYDRANT CHECK LIST												
No.	Location	fire equipment								Photos	Status	Remark
		หัวจ่ายน้ำ	ที่เปิดวาล์วน้ำ	สายฉีด	หัวฉีดน้ำ	รอยรั่วและซีล	สภาพตู้	กระจก	ขวาน			
1	Receiving area	OK	-	-	-	-	-	-	-			
2	Behind Canteen	OK	-	✓	✓	✕	✕	✓	✓			The fire cabinet has rusted.
3	Behind Building Management	OK	✓	✓	✕	✕	✕	✕	✓			The fire cabinet has rusted and the glass is broken.

Checked by Ms. Jeerapa / OH&S S

Acknowledged by _____/LPM