

ประเมินผลคุณภาพน้ำใช้ น้ำดื่ม และน้ำเสีย

เสนอ

Centara Grand Mirage Beach Resort Pattaya

ธันวาคม 2568

บริษัท เทสท์ เทค จำกัด

30, 32 ซอยพระรามที่ 2 ซอย 63 ถนนพระรามที่ 2 แขวงสามตำ เขตบางขุนเทียน กรุงเทพฯ 10150
Tel. 02-893-4211 - 17 Fax : 02-893-4218



SRR NO. 69A0025

Messrs : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Factory Site : Centara Grand Pattaya Date : 5 มกราคม 2569

Recommendation For : คุณภาพน้ำใช้และน้ำดื่มประจำเดือนธันวาคม 2568

Report Reference : R28226-34/68, R27903-04/68, R27628-31/68, R27759-60/68, R27905/68, R27804/68

RECOMMENDATION

1. คุณภาพน้ำใช้

1.1 Storage Tank : คุณภาพน้ำ มีค่าความขุ่นต่ำ ค่าเหล็กและแมงกานีสไม่พบ, ค่าความกระด้างมีค่าต่ำ, ค่าคลอไรด์มีค่าต่ำ ตรวจไม่พบเชื้อ Coliform/E.coli

หมายเหตุ : การดูแล

- เติมนคลอรีนในระบบผลิตน้ำและน้ำซื้อก่อนเก็บในถังพัก
- ควรตรวจสอบถังพัก 2 ครั้ง/เดือน และล้างถังเพื่อลดการสะสมของเหล็ก
- ควรดูแลขบวนการปรับสภาพน้ำส่วนต่อเนื่อง

1.2 Soft Water (Main Point) :

- pH ปกติ, ความขุ่นต่ำ
- ค่าความกระด้างต่ำ
- ค่าเหล็กไม่พบ
- ค่าแมงกานีสไม่พบ
- ตรวจไม่พบเชื้อ Coliform/E.coli
- คุณภาพน้ำทางเคมีอื่นๆ ปกติอยู่ในมาตรฐาน

หมายเหตุ : การดูแลระบบ

- ควบคุมค่าเหล็กของน้ำในถังพักให้มีค่าต่ำ เพื่อลดการสะสมของเหล็กใน Softener
- ล้างกลับระบบ Softener ให้บ่อย เพื่อลดการสะสมของเหล็กและเชื้อในระบบกรอง
- ตรวจสอบค่าความกระด้างและควบคุมการล้างเกลือ Softener ให้ต่อเนื่อง เพื่อควบคุมค่าความกระด้างและควบคุมการล้างเกลือที่ตกค้างให้หมด ก่อนใช้งานปกติ
- ควรเติมนคลอรีนในถังพักน้ำใช้และ Regenerate Softener ด้วยน้ำหลังเติมนคลอรีน เพื่อลดการสะสมของเหล็กใน Softener และฆ่าเชื้อที่สะสมในระบบกรอง

1.3 Hot Water System (Main Point) :

- ค่า pH ปกติ, ความขุ่นต่ำ
- ค่าความกระด้างต่ำ
- ค่าเหล็กไม่พบ
- ค่าแมงกานีสไม่พบ
- ตรวจไม่พบ Coliform/E.coli

หมายเหตุ : - ควร Flushing ในระบบผลิตน้ำร้อน เพื่อลดการสะสมของเหล็กในระบบ
- ควบคุม Softener เพื่อควบคุมความกระด้างในระบบผลิตน้ำร้อน อาจก่อให้เกิดปัญหา
ตะกรันในระบบ

1.4 Guest Room Usage Water (Cold Water) : คุณภาพน้ำเย็นห้องพักแยก 2 จุด South A 724

และ South A 726 พบค่าดังนี้

- ค่าความกระด้างและคลอไรด์ใกล้เคียงน้ำในถังพัก
- ค่าความขุ่นต่ำ
- ค่าเหล็กไม่พบ
- ค่าแมงกานีสไม่พบ
- ตรวจไม่พบ Coliform/E.coli

หมายเหตุ : - ในกรณีไม่ค่อยเปิดใช้ห้อง ควร Flushing ท่อก่อนเปิดใช้ใน โซนที่ไม่ค่อยเปิดห้องพัก
เพื่อลดการสะสมของเหล็ก/แมงกานีสในเส้นท่อ
- ตรวจสอบการเติมคลอรีนในถังพักน้ำประปา เพื่อฆ่าเชื้อที่สะสม

1.5 Guest Room Usage Water (Hot Water) : คุณภาพน้ำ 2 จุด คือ South A 724

และ South A 726 พบค่าดังนี้

- ค่าความกระด้างและคลอไรด์ใกล้เคียงน้ำในถังพัก
- ค่าความขุ่นต่ำ
- ค่าเหล็กต่ำ
- ค่าแมงกานีสไม่พบ
- ตรวจไม่พบ Coliform/E.coli

หมายเหตุ : ควร Flushing ระบบท่อ ก่อนเปิดใช้ห้องพักเพื่อป้องกันการสะสมของ
ตะกอนเหล็กในเส้นท่อ

1.6 Cooling :

- 1) คุณภาพน้ำมีค่าการนำไฟฟ้าสูง
- 2) ค่าความกระด้างสูงกว่ามาตรฐาน
- 3) ค่าเหล็กตรวจไม่พบ, ค่าแมงกานีสไม่พบ
- 4) เคมิป้องกันตะกรัน (phosphate) มีค่าต่ำ ควรตรวจสอบการเติมเคมี
- 5) ตรวจไม่พบ Legionella spp.

การดูแล

- ตรวจสอบระบบ Softener และผลิตน้ำ Soft ใช้เป็น Make Up Water ให้เพียงพอ และควบคุมการล้างเกลือ เพื่อควบคุมค่าความกระด้าง ≤ 20 ppm
- ควบคุมการเติมเคมีป้องกันตะกรันและตะไคร่น้ำ เนื่องจากเคมีป้องกันตะกรัน (phosphate) ยังต่ำ
- ควบคุมการระบายน้ำทิ้งให้สม่ำเสมอเพื่อควบคุมค่า การนำไฟฟ้า ≤ 2500 us/cm

1.7 Chilled Water : คุณภาพน้ำมีค่าเหล็กอยู่ในเกณฑ์ ค่า pH สูง ค่า Nitrite มีค่าต่ำกว่าเกณฑ์ควบคุม

หมายเหตุ : ควรเติมเคมีเพิ่มในรอบการบำรุงรักษาถัดไป

2. น้ำดื่ม

- 1) Canteen : ค่าความกระด้างสูงกว่าเกณฑ์เล็กน้อย ไม่พบค่าเหล็กและแมงกานีส
คุณภาพน้ำทางเคมีอื่นๆ อยู่ในมาตรฐาน ตรวจไม่พบ Coliform/E.coli
- 2) Oasis Kitchen : ค่าความกระด้างสูงกว่าเกณฑ์เล็กน้อย ไม่พบค่าเหล็กและแมงกานีส
คุณภาพน้ำทางเคมีอื่นๆ อยู่ในมาตรฐาน ตรวจไม่พบ Coliform/E.coli
- 3) Guest Room (724) : ค่าความกระด้างอยู่ในเกณฑ์มาตรฐาน ไม่พบค่าเหล็กและแมงกานีส
คุณภาพน้ำทางเคมีอื่นๆ อยู่ในมาตรฐาน ตรวจไม่พบ Coliform/E.coli

การดูแล :

- ล้างระบบกรอง Softener และล้างสม่ำเสมอ เพื่อลดค่าความกระด้าง
- Flushing line ด้วยน้ำหลังเติมคลอรีน เพื่อฆ่าเชื้อแบคทีเรียที่สะสมในระบบ
- ตรวจสอบความสะอาดของถังและแท็งก์บรรจุน้ำดื่ม

3. Swimming Pool :

1) Main Pool :

- pH ปกติ
- คลอรีนตรวจพบ 0.91 pm
- ตรวจไม่พบ Coliform/E.coli

2) Lab Pool :

- pH ปกติ
- คลอรีนตรวจพบ 0.87 ppm
- ตรวจไม่พบ Coliform/E.coli

3) Lazy Pool :

- pH ปกติ
- คลอรีนตรวจพบ 0.72 ppm
- ตรวจไม่พบ Coliform/E.coli

4) 18th Flr Pool :

- pH ปกติ
- คลอรีนตรวจพบ 0.81 ppm
- ตรวจไม่พบ Coliform/E.coli

หมายเหตุ : การดูแล

1. ควรตรวจสอบ pH สม่ำเสมอในกรณีค่า pH ทำให้ปรับด้วยโซดาไฟหรือโซดาแอช และปรับด้วยกรดเกลือในกรณีค่า pH สูง
2. ตรวจสอบคลอรีนและเติมให้สม่ำเสมอ
3. หมุนเวียนน้ำผ่านกรอง เพื่อไม่ให้ตะกอนสะสม และเชื้อแบคทีเรีย

4. น้ำแข็ง :

- 1) Canteen (Cube) : ตรวจไม่พบ Coliform/E.coli
- 2) Banquet (Flake) : ตรวจไม่พบ Coliform/E.coli
- 3) Flames : ตรวจไม่พบ Coliform/E.coli
- 4) Oasis Kitchen (Flake) : ตรวจไม่พบ Coliform/E.coli

การดูแล :

1. เติมน้ำคลอรีนในน้ำประปาและล้างระบบผลิตน้ำแข็งด้วยน้ำหลังเติมน้ำคลอรีน
 2. ตรวจสอบความสะอาดระบบผลิตน้ำแข็ง
 3. ภาชนะตักน้ำแข็งต้องสะอาด ถังบรรจุต้องสะอาด และควรล้างทุกวัน
 4. อย่าแช่อาหารปะปนในถังบรรจุน้ำแข็ง
 5. ในกรณีน้ำแข็งซื้อ ควรตรวจสอบถุงบรรจุ
5. น้ำเสียออกจากระบบ : ลักษณะน้ำเหลืองจางๆ BOD 141 mg/L และอยู่ในเกณฑ์การควบคุมของ
พหยา ในการปล่อยน้ำทิ้งลงระบบบำบัดรวม ($BOD \leq 1000 \text{ mg/L}$) โดยต้องจ่ายค่าบริการบำบัดน้ำทิ้ง
ตามข้อกำหนด
6. น้ำทะเล : มีตะกอนต่ำ ตรวจพบแบคทีเรีย 130 MPN/100 mL



Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Usage Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 22, 2025

Report Date : December 23, 2025

Report No. : R28226/68

Parameters	Unit	Method	TW25144 /68	TW25145 /68	TW25146 /68	Standard ^a
			Water in Storage Tank	Soft Water System (Main Point)	Hot Water System (Main Point)	
pH (25°C) [#]	-	Based on SM 2023 (4500-H ⁺ B)	7.3	7.3	7.4	6.5-8.5
Turbidity [#]	NTU	SM 2023 (2130 B)	< 0.50	< 0.50	< 0.50	4
Conductivity [#]	uS/cm	SM 2023 (2510 B)	507	512	500	-
* Dissolved Solids	mg/L as NaCl	Electrical Conductivity	304	307	300	600
Total Hardness [@]	mg/L as CaCO ₃	SM 2023 (2340 C)	121	124	123	300
Chloride [@]	mg/L as Cl ⁻	SM 2023 (4500-Cl ⁻ B)	50	51	50	250
Total Iron [#]	mg/L as Fe	SM 2023 (3500-Fe B)	< 0.10	< 0.10	< 0.10	0.3
Manganese [#]	mg/L	SM 2023 (3500-Mn B)	< 0.04	< 0.04	< 0.04	0.08
Nitrate [#]	mg/L as NO ₃ ⁻	SM 2023 (4500-NO ₃ ⁻ E)	18.81	18.91	18.38	50
Sulfate [#]	mg/L as SO ₄ ²⁻	Based on SM 2023 (4500-SO ₄ ²⁻ E)	52.14	55.69	54.74	250
Sample Condition		Observation	Clear	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. Test marked "# " on this report are Accredited International Standard ISO/IEC 17025 by BLA-DSS.

3. Test marked "@ " on this report are Accredited International Standard ISO/IEC 17025 by BLQS-DMSQ.

4. Test marked " * " on this report are not included in scope of Accreditation

5. a : Specification for Water Supply Quality of Provincial Waterworks Authority (PWA)



Analyst

December 23, 2025

Technical Manager

December 23, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025



Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Usage Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 22, 2025


Report Date : December 23, 2025

Report No. : R28227/68

Parameters	Unit	Method	TW25144 /68	TW25145 /68	TW25146 /68	Standard ^a
			Water in Storage Tank	Soft Water System (Main Point)	Hot Water System (Main Point)	
Coliform Bacteria	MPN/100 mL	SM 2023 (9221 B)	< 1.1	< 1.1	< 1.1	not found
<i>E. coli</i>	/100 mL	SM 2023 (9221 F, Detection)	not found	not found	not found	not found
Sample Condition		Observation	Clear	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. a : Specification for Water Supply Quality of Provincial Waterworks Authority (PWA)



Analyst

December 23, 2025



Technical Manager

December 23, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025



Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Usage Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 22, 2025

Report Date : December 23, 2025

Report No. : R28228/68

Parameters	Unit	Method	TW25147 /68	TW25148 /68	Standard ^a
			Guest Room Cold Water (South A 724)	Guest Room Cold Water (South A 726)	
pH (25°C) [#]	-	Based on SM 2023 (4500-H ⁺ B)	7.3	7.4	6.5-8.5
Turbidity [#]	NTU	SM 2023 (2130 B)	< 0.50	< 0.50	4
Conductivity [#]	uS/cm	SM 2023 (2510 B)	507	506	-
* Dissolved Solids	mg/L as NaCl	Electrical Conductivity	304	304	600
Total Hardness [@]	mg/L as CaCO ₃	SM 2023 (2340 C)	119	127	300
Chloride [@]	mg/L as Cl ⁻	SM 2023 (4500-Cl ⁻ B)	50	49	250
Total Iron [#]	mg/L as Fe	SM 2023 (3500-Fe B)	< 0.10	< 0.10	0.3
Manganese [#]	mg/L	SM 2023 (3500-Mn B)	< 0.04	< 0.04	0.08
Nitrate [#]	mg/L as NO ₃ ⁻	SM 2023 (4500-NO ₃ ⁻ E)	18.38	19.96	50
Sulfate [#]	mg/L as SO ₄ ²⁻	Based on SM 2023 (4500-SO ₄ ²⁻ E)	52.69	51.05	250
Sample Condition		Observation	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. Test marked "# " on this report are Accredited International Standard ISO/IEC 17025 by BLA-DSS.

3. Test marked "@ " on this report are Accredited International Standard ISO/IEC 17025 by BLQS-DMSQ.

4. Test marked " * " on this report are not included in scope of Accreditation

5. a : Specification for Water Supply Quality of Provincial Waterworks Authority (PWA)



Analyst

December 23, 2025

Technical Manager

December 23, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025



Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Usage Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 22, 2025

Report Date : December 23, 2025

Report No. : R28229/68

Parameters	Unit	Method	TW25147 /68	TW25148 /68	Standard ^a
			Guest Room Cold Water (South A 724)	Guest Room Cold Water (South A 726)	
Coliform Bacteria	MPN/100 mL	SM 2023 (9221 B)	< 1.1	< 1.1	not found
<i>E. coli</i>	/100 mL	SM 2023 (9221 F, Detection)	not found	not found	not found
Sample Condition		Observation	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. a : Specification for Water Supply Quality of Provincial Waterworks Authority (PWA)



Analyst

December 23, 2025



Technical Manager

December 23, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025



Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Usage Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 22, 2025

Report Date : December 23, 2025

Report No. : R28230/68

Parameters	Unit	Method	TW25149 /68	TW25150 /68	Standard ^a
			Guest Room Hot Water (South A 724)	Guest Room Hot Water (South A 726)	
pH (25°C) [#]	-	Based on SM 2023 (4500-H ⁺ B)	7.4	7.6	6.5-8.5
Turbidity [#]	NTU	SM 2023 (2130 B)	< 0.50	< 0.50	4
Conductivity [#]	uS/cm	SM 2023 (2510 B)	501	500	-
* Dissolved Solids	mg/L as NaCl	Electrical Conductivity	301	300	600
Total Hardness [@]	mg/L as CaCO ₃	SM 2023 (2340 C)	123	115	300
Chloride [@]	mg/L as Cl ⁻	SM 2023 (4500-Cl ⁻ B)	48	47	250
Total Iron [#]	mg/L as Fe	SM 2023 (3500-Fe B)	0.11	< 0.10	0.3
Manganese [#]	mg/L	SM 2023 (3500-Mn B)	< 0.04	< 0.04	0.08
Nitrate [#]	mg/L as NO ₃ ⁻	SM 2023 (4500-NO ₃ ⁻ E)	15.55	17.50	50
Sulfate [#]	mg/L as SO ₄ ²⁻	Based on SM 2023 (4500-SO ₄ ²⁻ E)	51.60	53.51	250
Sample Condition		Observation	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. Test marked "# " on this report are Accredited International Standard ISO/IEC 17025 by BLA-DSS.

3. Test marked "@ " on this report are Accredited International Standard ISO/IEC 17025 by BLQS-DMSc.

4. Test marked " * " on this report are not included in scope of Accreditation

5. a : Specification for Water Supply Quality of Provincial Waterworks Authority (PWA)



Analyst

December 23, 2025

Technical Manager

December 23, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025



Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Usage Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 22, 2025

Report Date : December 23, 2025

Report No. : R28231/68

Parameters	Unit	Method	TW25149 /68	TW25150 /68	Standard ^a
			Guest Room Hot Water (South A 724)	Guest Room Hot Water (South A 726)	
Coliform Bacteria	MPN/100 mL	SM 2023 (9221 B)	< 1.1	< 1.1	not found
<i>E. coli</i>	/100 mL	SM 2023 (9221 F, Detection)	not found	not found	not found
Sample Condition		Observation	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. a : Specification for Water Supply Quality of Provincial Waterworks Authority (PWA)



Analyst

December 23, 2025



Technical Manager

December 23, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025

TESTING
NO.0001

Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Usage Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 22, 2025

Report Date : December 23, 2025

Report No. : R28232/68

Parameters	Unit	Method	TW25151 /68	Standard ^a (Cooling Water)
			Cooling Water	
pH (25°C)	-	Based on SM 2023 (4500-H ⁺ B)	8.6	8.5 - 9.5
* Conductivity	uS/cm	SM 2023 (2510 B)	8570	< 2500
* Dissolved Solids	mg/L as NaCl	Electrical Conductivity	5142	< 2000
* P-Alkalinity	mg/L as CaCO ₃	SM 2023 (2320 B)	30	-
* M-Alkalinity	mg/L as CaCO ₃	SM 2023 (2320 B)	250	-
* Total Hardness	mg/L as CaCO ₃	SM 2023 (2340 C)	1294	< 100
* Chloride	mg/L as Cl ⁻	SM 2023 (4500-Cl ⁻ B)	1560	< 400
Total Iron	mg/L as Fe	SM 2023 (3500-Fe B)	< 0.10	< 1.0
Manganese	mg/L	SM 2023 (3500-Mn B)	< 0.04	-
* Sulfate	mg/L as SO ₄ ²⁻	Based on SM 2023 (4500-SO ₄ ²⁻ E)	1944	-
* Silica	mg/L as SiO ₂	SM 2023 (4500-SiO ₂ C)	145	-
* Total Phosphorus	mg/L as P	SM 2023 (4500-P D)	0.04	-
Sample Condition		Observation	Light Yellow, Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. Test marked " * " on this report are not included in scope of Accreditation

3. a : เกณฑ์ควบคุมคุณภาพน้ำในระบบต่าง ๆ



Analyst

December 23, 2025



Technical Manager

December 23, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025



Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Usage Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 22, 2025

Report Date : December 23, 2025

Report No. : R28233/68

Parameters	Unit	Method	TW25151 /68
			Cooling Water
<i>Legionella spp.</i>	/L	ISO 11731 : 2017	not detected
Sample Condition		Observation	Light Yellow, Clear



Analyst

December 23, 2025



Technical Manager

December 23, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025



Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Usage Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 22, 2025

Report Date : December 23, 2025

Report No. : R28234/68

Parameters	Unit	Method	TW25152 /68	Standard ^a (Chilled Water)
			Chilled Water	
* pH (25 °C)	-	Based on SM 2023 (4500-H ⁺ B)	10.0	7.5 - 9.5
Conductivity [#]	uS/cm	SM 2023 (2510 B)	851	-
* Dissolved Solids	mg/L as NaCl	Electrical Conductivity	511	-
* P-Alkalinity	mg/L as CaCO ₃	SM 2023 (2320 B)	55	-
* M-Alkalinity	mg/L as CaCO ₃	SM 2023 (2320 B)	145	-
Total Hardness [@]	mg/L as CaCO ₃	SM 2023 (2340 C)	23	-
Chloride [@]	mg/L as Cl ⁻	SM 2023 (4500-Cl ⁻ B)	48	-
Total Iron [#]	mg/L as Fe	SM 2023 (3500-Fe B)	0.13	< 1.0
Manganese [#]	mg/L	SM 2023 (3500-Mn B)	0.04	-
Sulfate [#]	mg/L as SO ₄ ²⁻	Based on SM 2023 (4500-SO ₄ ²⁻ E)	45.59	-
Silica [#]	mg/L as SiO ₂	SM 2023 (4500-SiO ₂ C)	4.53	-
* Nitrite	mg/L as NO ₂ ⁻	SM 2023 (4500-NO ₂ ⁻ B)	106	500 - 1000
Sample Condition		Observation	Colorless, a little bit Particles	


Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. Test marked "# " on this report are Accredited International Standard ISO/IEC 17025 by BLA-DSS.

3. Test marked "@ " on this report are Accredited International Standard ISO/IEC 17025 by BLQS-DMSc.

4. Test marked " * " on this report are not included in scope of Accreditation

5. a : เกณฑ์ควบคุมคุณภาพน้ำในระบบต่าง ๆ (Chilled Water)



Analyst

December 23, 2025



Technical Manager

December 23, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025



Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sampling by : Test Tech Co., Ltd.

Sampling Date : December 11, 2025

Received Date : December 11, 2025

Report Date : December 20, 2025

Sample Type : Drinking Water

Sampling Method : Grab

Sampling Time : 10:40 AM

Analytical Date : December 11 - 17, 2025

Report No. : R27903/68

Parameters	Unit	Method	TW25153 /68	TW25154 /68	TW25155 /68	Standard ^a
			Drinking Water (Canteen)	Drinking Water (Oasis Kitchen)	Drinking Water (Guest Room 724)	
pH (25°C) [#]	-	Based on SM 2023 (4500-H ⁺ B)	7.7	7.6	7.6	6.5-8.5
Turbidity [#]	NTU	SM 2023 (2130 B)	< 0.50	< 0.50	< 0.50	≤ 5.0
Conductivity [#]	uS/cm	SM 2023 (2510 B)	500	499	660	-
* Dissolved Solids	mg/L as NaCl	Electrical Conductivity	300	299	396	-
Total Hardness [@]	mg/L as CaCO ₃	SM 2023 (2340 C)	127	121	2 *	≤ 100.0
Chloride [@]	mg/L as Cl ⁻	SM 2023 (4500-Cl ⁻ B)	48	46	2 *	≤ 250.0
Total Iron [#]	mg/L as Fe	SM 2023 (3500-Fe B)	< 0.10	< 0.10	< 0.10	≤ 0.3
Manganese [#]	mg/L	SM 2023 (3500-Mn B)	< 0.04	< 0.04	< 0.04	≤ 0.05
Nitrate Nitrogen [#]	mg/L as NO ₃ ⁻ N	SM 2023 (4500-NO ₃ ⁻ E)	3.54	4.72	0.12	≤ 4.0
Sulfate [#]	mg/L as SO ₄ ²⁻	Based on SM 2023 (4500-SO ₄ ²⁻ E)	52.42	52.14	38.22	≤ 250.0
Sample Condition		Observation	Clear	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023
 2. Test marked "# " on this report are Accredited International Standard ISO/IEC 17025 by BLA-DSS.
 3. Test marked "@ " on this report are Accredited International Standard ISO/IEC 17025 by BLQS-DMSc.
 4. Test marked " * " on this report are not included in scope of Accreditation
 5. a : Notification of the Ministry of Public Health, No. 284 , B.E. 2547 (2004) on "Drinking Water in Sealed Container" (No.5)
 (Included No. 135 , B.E. 2534 (1991) and No. 61, B.E. 2524 (1981))



Analyst

December 20, 2025



Technical Manager

December 20, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025

Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Drinking Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 17, 2025


Report Date : December 20, 2025

Report No. : R27904/68

Parameters	Unit	Method	TW25153 /68	TW25154 /68	TW25155 /68	Standard ^a
			Drinking Water (Canteen)	Drinking Water (Oasis Kitchen)	Drinking Water (Guest Room 724)	
Coliform Bacteria	MPN/100 mL	SM 2023 (9221 B)	< 1.1	< 1.1	< 1.1	< 2.2
<i>E. coli</i>	/100 mL	SM 2023 (9221 F, Detection)	not found	not found	not found	negative
Sample Condition		Observation	Clear	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. a : Notification of the Ministry of Public Health, No. 284 , B.E. 2547 (2004) on "Drinking Water in Sealed Container" (No.5)
(Included No. 135 , B.E. 2534 (1991) and No. 61, B.E. 2524 (1981))



Analyst

December 20, 2025



Technical Manager

December 20, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025

Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Swimming Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 15, 2025

Report Date : December 16, 2025

Report No. : R27628/68

Parameters	Unit	Method	TW25156 /68	TW25157 /68	Standard ^a
			Main Pool	Lab Pool	
pH (25°C)	-	Based on SM 2023 (4500-H ⁺ B)	7.4	7.7	7.2-8.4
Residual Chlorine	mg/L as Cl ₂	SM 2023 (4500-Cl G)	0.91	0.87	0.6-1.0
Sample Condition		Observation	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. a : Bangkok Metropolitan Administration published in the Royal Government Gazette, Vol.104 ,Part 205,dated October 14, B.E.2530 (1987)

Analyst

December 16, 2025

Technical Manager

December 16, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025



Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Swimming Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 15, 2025


Report Date : December 16, 2025

Report No. : R27629/68

Parameters	Unit	Method	TW25156 /68	TW25157 /68	Standard ^a
			Main Pool	Lab Pool	
Coliform Bacteria	MPN/100 mL	SM 2023 (9221 B)	< 1.8	< 1.8	< 10
<i>E. coli</i>	/100 mL	SM 2023 (9221 F, Detection)	not found	not found	negative
Sample Condition		Observation	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. a : Bangkok Metropolitan Administration published in the Royal Government Gazette, Vol.104 ,Part 205,dated October 14, B.E.2530 (1987)



Analyst

December 16, 2025



Technical Manager

December 16, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025

Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Swimming Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 15, 2025

Report Date : December 16, 2025

Report No. : R27630/68

Parameters	Unit	Method	TW25158 /68	TW25159 /68	Standard ^a
			Lazy Pool	18 th Flr Pool	
pH (25°C)	-	Based on SM 2023 (4500-H ⁺ B)	7.9	7.7	7.2-8.4
Residual Chlorine	mg/L as Cl ₂	SM 2023 (4500-Cl G)	0.72	0.81	0.6-1.0
Sample Condition		Observation	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 20232. a : Bangkok Metropolitan Administration published in the Royal Government Gazette, Vol.104 ,Part 205,dated October 14,
B.E.2530 (1987)

Analyst

December 16, 2025

Technical Manager

December 16, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025



Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Swimming Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 15, 2025

Report Date : December 16, 2025

Report No. : R27631/68

Parameters	Unit	Method	TW25158 /68	TW25159 /68	Standard ^a
			Lazy Pool	18 th Flr Pool	
Coliform Bacteria	MPN/100 mL	SM 2023 (9221 B)	< 1.8	< 1.8	< 10
<i>E. coli</i>	/100 mL	SM 2023 (9221 F, Detection)	not found	not found	negative
Sample Condition		Observation	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. a : Bangkok Metropolitan Administration published in the Royal Government Gazette, Vol.104 ,Part 205,dated October 14, B.E.2530 (1987)

Analyst

December 16, 2025

December 16, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025

Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Ice

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 15, 2025

Report Date : December 18, 2025

Report No. : R27759/68

Parameters	Unit	Method	TW25160 /68	TW25161 /68	Standard ^a
			Canteen (Cube)	Banquet (Flake)	
Coliform Bacteria	MPN/100 mL	SM 2023 (9221 B)	< 1.1	< 1.1	< 2.2
<i>E. coli</i>	/100 mL	SM 2023 (9221 F, Detection)	not found	not found	negative
Sample Condition		Observation	Clear	Clear	

- Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023
2. a : Notification of the Ministry of Public Health, No. 284 , B.E. 2547 (2004) on "Drinking Water in Sealed Container" (No.5)
(Included No. 135 , B.E. 2534 (1991) and No. 61, B.E. 2524 (1981))



Analyst

December 18, 2025



Technical Manager

December 18, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025

Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Ice

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM


Received Date : December 11, 2025

Analytical Date : December 11 - 15, 2025

Report Date : December 18, 2025

Report No. : R27760/68

Parameters	Unit	Method	TW25162 /68	TW25163 /68	Standard ^a
			Flames	Oasis Kitchen (Flake)	
Coliform Bacteria	MPN/100 mL	SM 2023 (9221 B)	< 1.1	< 1.1	< 2.2
<i>E. coli</i>	/100 mL	SM 2023 (9221 F, Detection)	not found	not found	negative
Sample Condition		Observation	Clear	Clear	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 20232. a : Notification of the Ministry of Public Health, No. 284 , B.E. 2547 (2004) on "Drinking Water in Sealed Container" (No.5)
(Included No. 135 , B.E. 2534 (1991) and No. 61, B.E. 2524 (1981))

Analyst

December 18, 2025



Technical Manager

December 18, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025

Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Waste Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM

Received Date : December 11, 2025

Analytical Date : December 11 - 18, 2025

Report Date : December 20, 2025

Report No. : R27905/68

Parameters	Unit	Method	TW25165 /68	Standard ^a
			Effluent	
* pH	-	SM 2023 (4500-H ⁺ B)	6.7	-
* BOD	mg/L	SM 2023 (5210 B, 4500-O G)	141	≤ 1000
* Total Suspended Solids	mg/L	SM 2023 (2540 D)	218	-
Oil & Grease	mg/L	SM 2023 (5520 D)	39.9	-
Sample Condition		Observation	Light Yellow, Cloud, fatty sediment	

Remark : 1. SM 2023 : Standard Methods for the Examination of Water and Wastewater, APHA, AWWA & WEF, 24th ed., 2023

2. Test marked " * " on this report are not included in scope of Accreditation

3. a : ประกาศคณะกรรมการสิ่งแวดล้อมแห่งชาติ ฉบับที่ 22 (พ.ศ. 2544) เรื่อง กำหนดอัตราค่าบริการบำบัดน้ำเสียของระบบบำบัดน้ำเสียรวมเมืองพัทยา



Analyst

December 20, 2025



Technical Manager

December 20, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025

Analysis/Test Report

Customer Name : Centara Grand Mirage Beach Resort Pattaya

Address : 277 Moo 5, Naklua, Banglamung, Pattaya, Chonburi 20150, Thailand

Sampling Site : Centara Grand (Pattaya)

Sample Type : Sea Water

Sampling by : Test Tech Co., Ltd.

Sampling Method : Grab

Sampling Date : December 11, 2025

Sampling Time : 10:40 AM


Received Date : December 11, 2025

Analytical Date : December 11 - 17, 2025

Report Date : December 20, 2025

Report No. : R27804/68

Parameters	Unit	Method	TW25164 /68
			Sea Water
Dissolved Oxygen	mg/L	DO - Meter	6.71
Total Suspended Solids	mg/L	Dried at 103 - 105 °C	8
Oil & Grease	mg/L	Soxhlet Extraction	< 3.0
Total Coliform Bacteria	MPN/100 mL	MPN	1.3×10^2
Temperature	°C	Laboratory and Field	29.1
Transparency	m	Secchi Disc	1.0
Sample Condition		Observation	Colorless, a little bit Particles



Analyst

December 20, 2025



Technical Manager

December 20, 2025

Reported results refer to the sample as received only.

Test report shall not be reproduced except in full, without written approved of the laboratory.

The laboratory has been accepted as an accredited laboratory complying with the ISO/IEC 17025