



ISO/IEC 17025
Accreditation No. 1031/47

Analysis / Test Report

Client : Bangkok Phuket Hospital Co., Ltd.
2/1, Hongyok Utis Road, Taladyai, Muang, Phuket Thailand 83000

P/O :

Project Name : Water Testing : BPK

Project Location :

Lot ID: 2633719

Date Received : May 06, 2026

Date Reported : May 22, 2026

Report Number : 3577480-1

Page 1 of 1

Sample Number	2633719-14						
Sampled Date	May 05, 2026 1:40 PM						
Sample Description	น้ำอ่างล้างตา - แผนกห้องยาใน						
Location	จุดล้างด่างตัว - แผนกห้องยาใน						
Date Analysis Commenced	May 06, 2026						
Condition of Sample	Contained in three plastic bottles, sample containers comply to pretreatment - preservation standards (APHA, USEPA)						

Analyte	Unit	LOD	LOQ (LOR)	Result	Guideline / Specification	Method	Testing Location
Microbiological Testing							
<i>Escherichia coli</i>	MPN/100mL	-	-	<1.1	<1.1	Standard Methods for the Examination of Water and Wastewater. APHA, AWWA & WEF, 24th ed., 2023, part 9221 F	Bangkok
<i>Legionella spp.</i>	CFU/L	-	-	Not Detected**	No Standard	ISO 11731 (2017)	Bangkok
<i>Pseudomonas aeruginosa</i> *	in 100 mL	-	-	Not Detected	No Standard	In-house method in connection with: - Standard Methods for the Examination of Water and Wastewater. APHA, AWWA & WEF, 24th ed., 2023, part 9213 E	Bangkok
Total Coliform	MPN/100mL	-	-	<1.1	<1.1	Standard Methods for the Examination of Water and Wastewater. APHA, AWWA & WEF, 24th ed., 2023, part 9221 B	Bangkok

Guideline : เกณฑ์คุณภาพน้ำประปาดื่มได้ ประกาศ กรมอนามัย พ.ศ. 2563

Note : ** Not Detected mean Bacteria not found in agar plate.

Sampling By : Yuttapong Rattana , Furakan Kasetka

Remark :

- LOD : Limit of Detection
- "<" : Lower than LOQ (Limit of Quantitation) / LOR (Limit of Reporting)
- Analyte(s) marked * is/are not included in scope of Accreditation ISO/IEC 17025.
- Sampling is not included in scope of accreditation ISO/IEC 17025

Results apply to the sample(s) as submitted, unless the sampling was conducted by ALS. The report shall not be reproduced except in full without the written approval of the laboratory.

Approved by

Suwannee Chumkeaw
Section Head



Analysis / Test Report

Client : Bangkok Phuket Hospital Co., Ltd.
2/1, Hongyok Utis Road, Taladyai, Muang, Phuket Thailand 83000

P/O :

Project Name : Water Testing : BPK

Project Location :

Lot ID: 2633719

Date Received : May 06, 2026

Date Reported : May 22, 2026

Report Number : 3577492-1

Page 1 of 1

Sample Number	2633719-26
Sampled Date	May 05, 2026 10:20 AM
Sample Description	น้ำดื่มชดเชยในระบบ Cooling tower
Location	น้ำดื่มชดเชยในระบบ Cooling tower
Date Analysis Commenced	May 06, 2026
Condition of Sample	Contained in two plastic bottles, sample containers comply to pretreatment - preservation standards (APHA, USEPA)

Analyte	Unit	LOD	LOQ (LOR)	Result	Guideline / Specification	Method	Testing Location
Microbiological Testing							
<i>Legionella spp.</i>	CFU/L	-	-	Not Detected**	Not Detected (1)	ISO 11731 (2017)	Bangkok

Guideline : หนังสือการปรุงแต่งคุณภาพน้ำ มาตรฐานน้ำใน Cooling Tower ดร.มันสัน ตัณฑเวศน์
(1) ประกาศกรมอนามัย พ.ศ. 2544 เรื่องข้อปฏิบัติการควบคุมเชื้อลิจิโอนัลลา ในหอผึ่งเย็นของอาคารในประเทศไทย

Note : ** Not Detected mean Bacteria not found in agar plate.

Sampling By : Yuttapong Rattana , Furakan Kasetka

Remark :

- LOD : Limit of Detection
- "<" : Lower than LOQ (Limit of Quantitation) / LOR (Limit of Reporting)

Approved by

Suwannee Chuamkeaw
Section Head

Results apply to the sample(s) as submitted, unless the sampling was conducted by ALS. The report shall not be reproduced except in full without the written approval of the laboratory.



Analysis / Test Report

Client : Bangkok Phuket Hospital Co., Ltd.
2/1, Hongyok Utis Road, Taladyai, Muang, Phuket Thailand 83000

P/O :

Project Name : Water Testing : BPK

Project Location :

Lot ID: 2633719

Date Received : May 06, 2026

Date Reported : May 22, 2026

Report Number : 3577493-1

Page 1 of 1

Sample Number	2633719-27
Sampled Date	May 05, 2026 10:10 AM
Sample Description	น้ำในถาด Cooling tower
Location	Cooling tower
Date Analysis Commenced	May 06, 2026
Condition of Sample	Contained in two plastic bottles, sample containers comply to pretreatment - preservation standards (APHA, USEPA)

Analyte	Unit	LOD	LOQ (LOR)	Result	Guideline / Specification	Method	Testing Location
Microbiological Testing							
<i>Legionella spp.</i>	CFU/L	-	-	Not Detected**	Not Detected (1)	ISO 11731 (2017)	Bangkok

Guideline : หนังสือการปรุงแต่งคุณภาพน้ำ มาตรฐานน้ำใน Cooling Tower ดร.มันสัน ตัณฑเวศน์
(1) ประกาศกรมอนามัย พ.ศ. 2544 เรื่องข้อปฏิบัติการควบคุมเชื้อลิจิโอนัลลา ในหอผึ่งเย็นของอาคารในประเทศไทย

Note : ** Not Detected mean Bacteria not found in agar plate.

Sampling By : Yuttapong Rattana , Furakan Kasetka

Remark :

- LOD : Limit of Detection
- "<" : Lower than LOQ (Limit of Quantitation) / LOR (Limit of Reporting)

Results apply to the sample(s) as submitted, unless the sampling was conducted by ALS. The report shall not be reproduced except in full without the written approval of the laboratory.

Approved by

Suwannee Chuamkeaw
Section Head