Confide technology

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko. Location : Security Room

Service Date : 21-23/5/66.

| No. | รายงานปัญหาที่พบจากการดำเนินงานตรวจสอบ | แนวทางแก้ไขปัญหาที่พบจากการดำเนินงานตรวจสอบ |
|---|---|---|
| 1. | Battery 12V/65Ah. หมด FCP 4 set. | - เตรียมราคาเปลี่ยน Battery 12V/65Ah=4 set |
| | ที่ต้องเปลี่ยนตามอายุ (เกิน ต.ค/2020) | |
| 2. | Smoke ADD ชั้น 16 - ADZ#B-19 Floor 6th. | - เตรียมราคาเปลี่ยน Smoke ADD+ Base. |
| | Comm. Fault (อุปกรณ์ขัดข้อง เปลี่ยนใหม่). | |
| 3. | Smoke ADD ชั้น B2 ADZ#B2-14 DIRTY | - เตรียมราคาเปลี่ยน Smoke ADD+ Base. |
| | แก้ไขไม่หมด (เดิม). | |
| 4. | Zone DZ#701 ชั้น 7 Trouble open พื้นที่ | - มีรายการไม่เตรียมอุปกรณ์เพื่อมาเปลี่ยน |
| | ห้อง ประชุมใหญ่ (เดิม) | แก้ไขที่ตัวไม่ได้. |
| 5. | IM out FTD 19. Comm fault INTRL. | - เตรียมราคาเปลี่ยน Siga-IM = 1 set. |
| 6. | Fail Module Comm. fault 020106B1. | - เตรียมราคาเปลี่ยน Card Power Supply ใหม่ |
| | Card BPS/M990 (02-03) ที่ตู้ CAB2 | (มีระยะเวลาสั่งของนานกว่าจะได้มาเปลี่ยน) |
| 7. | Booster Power Supply ชั้น 3/14/20 | - เตรียมราคาเปลี่ยน Battery 12V/7Ah |
| | Battery 12V/7Ah ที่ต้องเปลี่ยนตามอายุ = 6 set | = 6 set (3 ตู้ BPS.) |
| | | |
| | | |
| | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 23/5/66 | SIGNATURE : | 20/6/2025 |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : Security Room

Service : ☑ Yearly 1/2 ☐ Other

FACP : No. 1 Brand : Edwards Model : EST3

| INSPECTION AND TEST REPORT FOR FIRE ALARM CONTROL PANEL | | | | |
|---|---|---|---|---|
| **1. Power Supplies** | | | | **Remark** |
| 1.1 | Main AC power | 229.9 VAC(220-230 VAC) | ☑ Pass ☐ Not Pass | |
| 1.2 | Charger Battery | 27.22 (>24 VDC) | ☑ Pass ☐ Not Pass | |
| 1.3 | Battery | 27.31 (>24 VDC) | ☐ Pass ☑ Not Pass | Battery อยู่ในรถ |
| **2. Lamps** | | | | **Remark** |
| 1.1 | Power on | | ☑ Pass ☐ Not Pass | |
| 1.2 | Alarm | | ☑ Pass ☐ Not Pass | |
| 1.3 | Supervisory | | ☑ Pass ☐ Not Pass | |
| 1.4 | Trouble | | ☑ Pass ☐ Not Pass | |
| 1.5 | Monitor | | ☑ Pass ☐ Not Pass | |
| **3 . Control Switch** | | | | **Remark** |
| 1.1 | Reset or | | ☑ Pass ☐ Not Pass | |
| 1.2 | Alarm Silence or | | ☑ Pass ☐ Not Pass | |
| 1.3 | Panel Silence or | | ☑ Pass ☐ Not Pass | |
| 1.4 | Lamp Test | | ☑ Pass ☐ Not Pass | |
| 1.5 | Drill | | ☑ Pass ☐ Not Pass | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 28/5/68 | SIGNATURE : | 20/6/2025 |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : Hotel Nikko Bangkok (Thailand)ประจำปี 2568

Building : Hotel Nikko Location : Security Room.

Service : ☑ Yearly 1/2 ☐ Other .....

Graphic Annunciator Panel : No. 1

| INSPECTION AND TEST REPORT FOR GRAPHIC ANNUNCIATOR PANEL | | | | |
|---|---|---|---|---|
| 1 | Power Supply | | | Remark |
| 1.1 | Main DC power | 24 VAC (24-26Vdc) | ☑ Pass ☐ Not Pass | |
| | | | | |
| 2 | Lamps | | | Remark |
| 2.1 | Led | | ☑ Pass ☐ Not Pass | |
| | | | | |
| 3 | Visual Check | | | Remark |
| 3.1 | Visual Check | | ☑ Pass ☐ Not Pass | |
| 3.2 | Wiring | | ☑ Pass ☐ Not Pass | |
| 3.3 | Network | | ☑ Pass ☐ Not Pass | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 23/5/68. | SIGNATURE : | 20/4/2025 |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Location : Ground Floor

Service : ☑ Yearly ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_FL1 GROUND FLOOR | 0102251 | | | | | | | | | |
| 2 | ISOLATOR | IM_OUT_FTB_FL1 GROUND FLOOR | 0102252 | | | | | | | | | |
| 3 | HEAT | ADZ#G-67 GROUND FLOOR | 0102253 | | | | | | | | | |
| 4 | SMOKE | ADZ#G-20 GROUND FLOOR | 0102254 | | | | | | | | | |
| 5 | HEAT | ADZ#G-59 GROUND FLOOR | 0102255 | | | | | | | | | |
| 6 | SMOKE | ADZ#G-39 GROUND FLOOR | 0102256 | | | | | | | | | |
| 7 | HEAT | ADZ#G-70 GROUND FLOOR | 0102257 | | | | | | | | | |
| 8 | SMOKE | ADZ#G-38 GROUND FLOOR | 0102258 | | | | | | | | | |
| 9 | SMOKE | ADZ#G-54 GROUND FLOOR | 0102259 | | | | | | | | | |
| 10 | SMOKE | ADZ#G-44 GROUND FLOOR | 0102260 | | | | | | | | | |
| 11 | SMOKE | ADZ#G-50 GROUND FLOOR | 0102261 | | | | | | | | | |
| 12 | SMOKE | ADZ#2-02 GROUND FLOOR | 0102262 | | | | | | | | | |
| 13 | SMOKE | ADZ#G-60 GROUND FLOOR | 0102263 | | | | | | | | | |
| 14 | SMOKE | ADZ#G-55 GROUND FLOOR | 0102264 | | | | | | | | | |
| 15 | SMOKE | ADZ#G-66 GROUND FLOOR | 0102265 | | | | | | | | | |
| 16 | SMOKE | ADZ#G-75 GROUND FLOOR | 0102266 | | | | | | | | | |
| 17 | SMOKE | ADZ#G-68 GROUND FLOOR | 0102267 | | | | | | | | | |
| 18 | SMOKE | ADZ#G-76 GROUND FLOOR | 0102268 | | | | | | | | | |
| 19 | SMOKE | ADZ#G-24 GROUND FLOOR | 0102269 | | | | | | | | | |
| 20 | SMOKE | ADZ#G-28 GROUND FLOOR | 0102270 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : A Location : Ground Floor

Service : ☑ Yearly 1/3 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#G-41 GROUND FLOOR | 0102271 | | | | | | | | | |
| 22 | SMOKE | ADZ#G-45 GROUND FLOOR | 0102272 | | | | | | | | | |
| 23 | SMOKE | ADZ#G-46 GROUND FLOOR | 0102273 | | | | | | | | | |
| 24 | SMOKE | ADZ#G-47 GROUND FLOOR | 0102274 | | | | | | | | | |
| 25 | SMOKE | ADZ#G-48 GROUND FLOOR | 0102275 | | | | | | | | | |
| 26 | SMOKE | ADZ#G-49 GROUND FLOOR | 0102276 | | | | | | | | | |
| 27 | SMOKE | ADZ#G-51 GROUND FLOOR | 0102277 | | | | | | | | | |
| 28 | SMOKE | ADZ#G-52 GROUND FLOOR | 0102278 | | | | | | | | | |
| 29 | SMOKE | ADZ#G-53 GROUND FLOOR | 0102279 | | | | | | | | | |
| 30 | HEAT | ADZ#G-57 GROUND FLOOR | 0102280 | | | | | | | | | |
| 31 | SMOKE | ADZ#G-58 GROUND FLOOR | 0102281 | | | | | | | | | |
| 32 | SMOKE | ADZ#G-61 GROUND FLOOR | 0102282 | | | | | | | | | |
| 33 | HEAT | ADZ#G-62 GROUND FLOOR | 0102283 | | | | | | | | | |
| 34 | SMOKE | ADZ#G-64 GROUND FLOOR | 0102284 | | | | | | | | | |
| 35 | SMOKE | ADZ#G-69 GROUND FLOOR | 0102285 | | | | | | | | | |
| 36 | HEAT | ADZ#G-74 GROUND FLOOR | 0102286 | | | | | | | | | |
| 37 | SMOKE | ADZ#G-73 GROUND FLOOR | 0102287 | | | | | | | | | |
| 38 | HEAT | ADZ#G-65 GROUND FLOOR | 0102288 | | | | | | | | | |
| 39 | HEAT | ADZ#G-63 GROUND FLOOR | 0102289 | | | | | | | | | |
| 40 | SMOKE | ADZ#G-07 GROUND FLOOR | 0102290 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : A Location : Ground Floor

Service : ☑ Yearly 1/3 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#G-05 FGROUND FLOOR | 0102291 | | | | | | | | | |
| 42 | SMOKE | ADZ#G-03 GROUND FLOOR | 0102292 | | | | | | | | | |
| 43 | SMOKE | ADZ#G-34 GROUND FLOOR | 0102293 | | | | | | | | | |
| 44 | SMOKE | ADZ#G-14 GROUND FLOOR | 0102294 | | | | | | | | | |
| 45 | SMOKE | ADZ#G-15 GROUND FLOOR | 0102295 | | | | | | | | | |
| 46 | SMOKE | ADZ#G-16 GROUND FLOOR | 0102296 | | | | | | | | | |
| 47 | HEAT | ADZ#G-18 GROUND FLOOR | 0102297 | | | | | | | | | |
| 48 | HEAT | ADZ#G-40 GROUND FLOOR | 0102304 | | | | | | | | | |
| 49 | SMOKE | ADZ#G-30 GROUND FLOOR | 0102306 | | | | | | | | | |
| 50 | SMOKE | ADZ#G-37 GROUND FLOOR | 0102307 | | | | | | | | | |
| 51 | HEAT | ADZ#G-36 GROUND FLOOR | 0102308 | | | | | | | | | |
| 52 | SMOKE | ADZ#G-56 GROUND FLOOR | 0102309 | | | | | | | | | |
| 53 | SMOKE | ADZ#G-71 GROUND FLOOR | 0102310 | | | | | | | | | |
| 54 | SMOKE | ADZ#G-72 GROUND FLOOR | 0102311 | | | | | | | | | |
| 55 | SMOKE | ADZ#G-17 GROUND FLOOR | 0102312 | | | | | | | | | |
| 56 | SMOKE | ADZ#G-04 GROUND FLOOR | 0102313 | | | | | | | | | |
| 57 | SMOKE | ADZ#G-01 GROUND FLOOR | 0102314 | | | | | | | | | |
| 58 | HEAT | ADZ#G-08 GROUND FLOOR | 0102315 | | | | | | | | | |
| 59 | SMOKE | ADZ#G-19 GROUND FLOOR | 0102316 | | | | | | | | | |
| 60 | HEAT | ADZ#G-21 GROUND FLOOR | 0102317 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : A Location : Ground Floor

Service : ☑ Yearly 1/3 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | HEAT | ADZ#G-22 GROUND FLOOR | 0102318 | | | | | | | | | |
| 62 | HEAT | ADZ#G-23 GROUND FLOOR | 0102319 | | | | | | | | | |
| 63 | HEAT | ADZ#G-27 GROUND FLOOR | 0102320 | | | | | | | | | |
| 64 | HEAT | ADZ#G-26 GROUND FLOOR | 0102321 | | | | | | | | | |
| 65 | SMOKE | ADZ#G-29 GROUND FLOOR | 0102322 | | | | | | | | | |
| 66 | SMOKE | ADZ#G-31 GROUND FLOOR | 0102323 | | | | | | | | | |
| 67 | SMOKE | ADZ#G-32 GROUND FLOOR | 0102324 | | | | | | | | | |
| 68 | SMOKE | ADZ#G-33 GROUND FLOOR | 0102325 | | | | | | | | | |
| 69 | SMOKE | ADZ#G-42 GROUND FLOOR | 0102326 | | | | | | | | | |
| 70 | SMOKE | ADZ#G-43 GROUND FLOOR | 0102327 | | | | | | | | | |
| 71 | SMOKE | ADZ#G-02 GROUND FLOOR | 0102328 | | | | | | | | | |
| 72 | SMOKE | ADZ#G-13 GROUND FLOOR | 0102329 | | | | | | | | | |
| 73 | SMOKE | ADZ#G-12 GROUND FLOOR | 0102330 | | | | | | | | | |
| 74 | SMOKE | ADZ#G-11 GROUND FLOOR | 0102331 | | | | | | | | | |
| 75 | SMOKE | ADZ#G-10 GROUND FLOOR | 0102332 | | | | | | | | | |
| 76 | SMOKE | ADZ#G-09 GROUND FLOOR | 0102333 | | | | | | | | | |
| 77 | SMOKE | ADZ#G-25 GROUND FLOOR | 0102334 | | | | | | | | | |
| 78 | SMOKE | ADZ#G-35 GROUND FLOOR | 0102335 | | | | | | | | | |
| 79 | SMOKE | ADZ#G-06 GROUND FLOOR | 0102336 | | | | | | | | | |
| 80 | FANCONTROL | ACCESS CONTROL SECURITY RM. G FL. | 0102376 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : A  Location : Ground Floor

Service : ☑ Yearly 1/3 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 81 | SMOKE | DZ#G01 GROUND FLOOR | 0102377 | | | | | | | | | |
| 82 | SUPERVISORY | SUPERVISORY_1 GROUND FLOOR | 0102378 | | | | | | | | | |
| 83 | WATERFLOW | WATERFLOW_FS_FL1_1 GROUND FLOOR | 0102379 | | | | | | | | | |
| 84 | FANCONTROL | PUBLIC ADDRESS SECURITY RM. G FL. | 0102380 | | | | | | | | | |
| 85 | FANCONTROL | PRESURIZED-FAN-01&02 LINEN HOLDING G-FL. | 0102381 | | | | | | | | | |
| 86 | FANCONTROL | LOAD CENTER PP-AGC/1 G FL. | 0102382 | | | | | | | | | |
| 87 | AUDIBLE | AUDIBLE_ABZ_FL1_1 GROUND FLOOR | 1012385 | | | | | | | | | |
| 88 | AUDIBLE | AUDIBLE_STROBE_FL1_1 GROUND FLOOR | 1012386 | | | | | | | | | |
| 89 | AUDIBLE | AUDIBLE_ASZ_FL1_1 GROUND FLOOR | 1012387 | | | | | | | | | |
| 90 | PULL | PULL_AMZ_G_01 GROUND FLOOR | 1012388 | | | | | | | | | |
| 91 | PULL | PULL_AMZ_G_03 GROUND FLOOR | 1012389 | | | | | | | | | |
| 92 | PULL | PULL_AMZ_G_02 GROUND FLOOR | 1012390 | | | | | | | | | |
| 93 | MONITOR | MONITOR_FL1_BOOSTER GROUND FLOOR | 1012391 | | | | | | | | | |
| 94 | AUDIBLE | AZ_FL1_POWERBELL GROUND FLOOR | 1012392 | | | | | | | | | |
| 95 | PULL | FIRESUPPRESSION (IT RM.) G- FL. | 1012393 | | | | | | | | | |
| 96 | FANCONTROL | CONTROL LPG STATION1 SECURITY RM. G FL. | 1012394 | | | | | | | | | |
| 97 | PULL | ANSUL G-1 KITCHEN RM. G- FL. | 1012395 | | | | | | | | | |
| 98 | PULL | ANSUL G-2 KITCHEN RM. G- FL. | 1012396 | | | | | | | | | |
| 99 | FANCONTROL | CONTROL AV SYSTEM OPERATION RM. G- FL. | 1012397 | | | | | | | | | |
| 100 | PULL | ANSUL G-3 KITCHEN RM. G- FL. | 1012398 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : B ชั้น G - ดาดฟ้า Location : Ground Floor

Service : ☑ Yearly 1/3 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 101 | PULL | GAS G-1 KITCHEN RM. G- FL. | 0102399 | | | | | | | | | |
| 102 | FANCONTROL | CONTROL LPG STATION2 SECURITY RM. G FL. | 0102400 | | | | | | | | | |
| 103 | PULL | LPG_FL1_STATION1 G- FL. | 0102401 | | | | | | | | | |
| 104 | PULL | LPG_FL1_STATION2 G- FL. | 0102402 | | | | | | | | | |
| 105 | | | | | | | | | | | | |
| 106 | | | | | | | | | | | | |
| 107 | | | | | | | | | | | | |
| 108 | | | | | | | | | | | | |
| 109 | | | | | | | | | | | | |
| 110 | | | | | | | | | | | | |
| 111 | | | | | | | | | | | | |
| 112 | | | | | | | | | | | | |
| 113 | | | | | | | | | | | | |
| 114 | | | | | | | | | | | | |
| 115 | | | | | | | | | | | | |
| 116 | | | | | | | | | | | | |
| 117 | | | | | | | | | | | | |
| 118 | | | | | | | | | | | | |
| 119 | | | | | | | | | | | | |
| 120 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : B ชั้น G - ดาดฟ้า Location : Ground Floor

Service : ☑ Yearly 1/3 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | FIREPHONE | FIREPHONE ST-1 | 0102145 | | | | | | | | | |
| 2 | FIREPHONE | FIREPHONE ST-4 | 0102146 | | | | | | | | | |
| 3 | FIREPHONE | FIREPHONE ST-3 | 0102147 | | | | | | | | | |
| 4 | FIREPHONE | FIREPHONE ST-2 | 0102383 | | | | | | | | | |
| 5 | FIREPHONE | FIREPHONE ST-5 | 0102384 | | | | | | | | | |
| 6 | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : Ground Floor

Service : ☑ Yearly 1/3 ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✗ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_B1 BASEMENT_1st | 0102004 | | | | | | | | | |
| 2 | ISOLATOR | IM_OUT_FTB_B1 BASEMENT_1st | 0102005 | | | | | | | | | |
| 3 | SMOKE | ADZ#B1-02 BASEMENT_1th | 0102063 | | | | | | | | | |
| 4 | SMOKE | ADZ#B1-03 BASEMENT_1st | 0102064 | | | | | | | | | |
| 5 | SMOKE | ADZ#B1-01 BASEMENT_1st | 0102065 | | | | | | | | | |
| 6 | SMOKE | ADZ#B1-10 BASEMENT_1st | 0102066 | | | | | | | | | |
| 7 | SMOKE | ADZ#B1-09 BASEMENT_1st | 0102067 | | | | | | | | | |
| 8 | HEAT | ADZ#B1-18 BASEMENT_1st | 0102068 | | | | | | | | | |
| 9 | HEAT | ADZ#B1-16 BASEMENT_1st | 0102069 | | | | | | | | | |
| 10 | SMOKE | ADZ#B1-23 BASEMENT_1th | 0102070 | | | | | | | | | |
| 11 | HEAT | ADZ#B1-19 BASEMENT_1st | 0102071 | | | | | | | | | |
| 12 | SMOKE | ADZ#B1-15 BASEMENT_1st | 0102072 | | | | | | | | | |
| 13 | HEAT | ADZ#B1-12 BASEMENT_1st | 0102073 | | | | | | | | | |
| 14 | HEAT | ADZ#B1-20 BASEMENT_1st | 0102074 | | | | | | | | | |
| 15 | HEAT | ADZ#B1-17 BASEMENT_1st | 0102075 | | | | | | | | | |
| 16 | HEAT | ADZ#B1-11 BASEMENT_1st | 0102076 | | | | | | | | | |
| 17 | HEAT | ADZ#B1-22 BASEMENT_1st | 0102077 | | | | | | | | | |
| 18 | HEAT | ADZ#B1-13 BASEMENT_1st | 0102078 | | | | | | | | | |
| 19 | HEAT | ADZ#B1-14 BASEMENT_1st | 0102079 | | | | | | | | | |
| 20 | SMOKE | ADZ#B1-06 BASEMENT_1st | 0102084 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Location : Ground Floor

Service : ☑ Yearly 1/3 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | HEAT | ADZ#B1-07 BASEMENT_1st | 0102085 | | | | | | | | | |
| 22 | HEAT | ADZ#B1-21 BASEMENT_1st | 0102086 | | | | | | | | | |
| 23 | HEAT | ADZ#B1-08 BASEMENT_1st | 0102087 | | | | | | | | | |
| 24 | WATERFLOW | WATERFLOW_FS_B1_1 BASEMENT_1st | 0102173 | | | | | | | | | |
| 25 | SUPERVISORY | SUPERVISORY_1 BASEMEANT_1st. | 0102172 | | | | | | | | | |
| 26 | SMOKE | DZ#B101 BASEMENT_1st | 0102169 | | | | | | | | | |
| 27 | SMOKE | DZ#B102 BASEMENT_1st | 0102170 | | | | | | | | | |
| 28 | SMOKE | DZ#B103 BASEMENT_1st | 0102171 | | | | | | | | | |
| 29 | FANCONTROL | EXHAUST-FAN-EF-B1.1 BASEMENT-1st Fl. | 0102174 | | | | | | | | | |
| 30 | AUDIBLE | AUDIBLE_ABZ_B1_1 BASEMENT_1st | 0102175 | | | | | | | | | |
| 31 | AUDIBLE | AUDIBLE_STROBE_B1_1 BASEMENT_1st | 0102176 | | | | | | | | | |
| 32 | AUDIBLE | AUDIBLE_ASZ_B1_1 BASEMENT_1st | 0102177 | | | | | | | | | |
| 33 | PULL | PULL_AMZ_B1_03 BASEMENT_1st | 0102187 | | | | | | | | | |
| 34 | PULL | PULL_AMZ_B1_01 BASEMENT_1st | 0102188 | | | | | | | | | |
| 35 | PULL | PULL_AMZ_B1_02 BASEMENT_1st | 0102189 | | | | | | | | | |
| 36 | FIREPHONE | FIREPHONE ST-2 | 0102383 | | | | | | | | | |
| 37 | FIREPHONE | FIREPHONE ST-5 | 0102384 | | | | | | | | | |
| 38 | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 2nd Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

## INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 2 | SMOKE | 0102037 | | | | | | | | | | |
| 3 | SMOKE | BASEMENT_2nd | 0102038 | | | | | | | | | |
| 4 | SMOKE | 2 BASEMENT_2nd | 0102039 | | | | | | | | | |
| 5 | SMOKE | 0 BASEMENT_2nd | 0102040 | | | | | | | | | |
| 6 | SMOKE | 9 BASEMENT_2nd | 0102041 | | | | | | | | | |
| 7 | SMOKE | 8 BASEMENT_2nd | 0102042 | | | | | | | | | |
| 8 | SMOKE | 7 BASEMENT_2nd | 0102043 | | | | | | | | | |
| 9 | SMOKE | 1 BASEMENT_2nd | 0102044 | | | | | | | | | |
| 10 | SMOKE | 6 BASEMENT_2nd | 0102048 | | | | | | | | | |
| 11 | SMOKE | 3 BASEMENT_2th | 0102049 | | | | | | | | | |
| 12 | HEAT | 5 BASEMENT_2nd | 0102050 | | | | | | | | | |
| 13 | HEAT | 7 BASEMENT_2nd | 0102051 | | | | | | | | | |
| 14 | SMOKE | 8 BASEMENT_2nd | 0102052 | | | | | | | | | |
| 15 | SMOKE | 4 BASEMENT_2nd | 0102053 | | | | | | | | | |
| 16 | SMOKE | 6 BASEMENT_2nd | 0102054 | | | | | | | | | |
| 17 | HEAT | 0 BASEMENT_2nd | 0102055 | | | | | | | | | |
| 18 | SMOKE | 1 BASEMENT_2nd | 0102056 | | | | | | | | | |
| 19 | HEAT | 9 BASEMENT_2nd | 0102057 | | | | | | | | | |
| 20 | HEAT | 2 BASEMENT_2nd | 0102058 | | | | | | | | | |

COMMENT : .....

| Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|
| | | SIGNATURE : | |
| | | SIGNATURE : | |
| | | SIGNATURE : | |

| Quarterly | TEST BY : Confide |
|---|---|
| 1 | SIGNATURE : |
| 2 | SIGNATURE : |
| 3 | SIGNATURE : |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 2nd Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | HEAT | ADZ#B2-25 BASEMENT_2nd | 0102059 | | | | | | | | | |
| 22 | HEAT | ADZ#B2-24 BASEMENT_2nd | 0102060 | | | | | | | | | |
| 23 | HEAT | ADZ#B2-21 BASEMENT_2nd | 0102061 | | | | | | | | | |
| 24 | HEAT | ADZ#B2-15 BASEMENT_2nd | 1012080 | | | | | | | | | |
| 25 | HEAT | ADZ#B2-16 BASEMENT_2nd | 1012081 | | | | | | | | | |
| 26 | SMOKE | DZ#B201 BASEMENT_2nd | 0102160 | | | | | | | | | |
| 27 | SMOKE | DZ#B202 BASEMENT_2nd | 0102161 | | | | | | | | | |
| 28 | SMOKE | DZ#B203 BASEMENT_2nd | 0102162 | | | | | | | | | |
| 29 | SUPERVISORY | SUPERVISORY_1 BASEMEANT_2nd | 0102163 | | | | | | | | | |
| 30 | WATERFLOW | WATERFLOW_FS_B2_1 BASEMENT_2nd | 0102164 | | | | | | | | | |
| 31 | FANCONTROL | EXHAUST FAN-EF-B2.1 BASEMENT-2nd Fl. | 0102165 | | | | | | | | | |
| 32 | AUDIBLE | AUDIBLE_ABZ_B2_1 BASEMENT_2nd | 0102166 | | | | | | | | | |
| 33 | AUDIBLE | AUDIBLE_STROBE_B2_1 BASEMENT_2nd | 0102167 | | | | | | | | | |
| 34 | AUDIBLE | AUDIBLE_ASZ_B2_1 BASEMENT_2nd | 0102168 | | | | | | | | | |
| 35 | PULL | PULL_AMZ_B2_02 BASEMENT_2nd | 0102184 | | | | | | | | | |
| 36 | PULL | PULL_AMZ_B2_01 BASEMENT_2nd | 0102185 | | | | | | | | | |
| 37 | PULL | PULL_AMZ_B2_03 BASEMENT_2nd | 0102186 | | | | | | | | | |
| 38 | SMOKE | ADZ#2-09 FLOOR_2nd | 0102298 | | | | | | | | | |
| 39 | SMOKE | ADZ#2-08 FLOOR_2nd | 0102299 | | | | | | | | | |
| 40 | SMOKE | ADZ#2-07 FLOOR_2nd | 0102300 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 2nd Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#2-06 FLOOR_2nd | 0102301 | | | | | | | | | |
| 42 | SMOKE | ADZ#2-05 FLOOR_2nd | 0102302 | | | | | | | | | |
| 43 | SMOKE | ADZ#2-04 FLOOR_2nd | 0102303 | | | | | | | | | |
| 44 | SMOKE | ADZ#2-03 FLOOR_2nd | 0102305 | | | | | | | | | |
| 45 | ISOLATOR | IM_IN_FTB_2 FLOOR 2nd | 0103001 | | | | | | | | | |
| 46 | ISOLATOR | IM_OUT_FTB_2 FLOOR 2nd | 0103002 | | | | | | | | | |
| 47 | SMOKE | ADZ#2-17 FLOOR 2nd. | 0103005 | | | | | | | | | |
| 48 | SMOKE | ADZ#2-18 FLOOR 2nd. | 0103006 | | | | | | | | | |
| 49 | SMOKE | ADZ#2-20 FLOOR 2nd. | 0103007 | | | | | | | | | |
| 50 | SMOKE | ADZ#2-19 FLOOR 2nd. | 0103008 | | | | | | | | | |
| 51 | SMOKE | ADZ#2-23 FLOOR 2nd. | 0103009 | | | | | | | | | |
| 52 | SMOKE | ADZ#2-24 FLOOR 2nd. | 0103010 | | | | | | | | | |
| 53 | SMOKE | ADZ#2-27 FLOOR 2nd. | 0103011 | | | | | | | | | |
| 54 | SMOKE | ADZ#2-30 FLOOR 2nd. | 0103012 | | | | | | | | | |
| 55 | SMOKE | ADZ#2-29 FLOOR 2nd. | 0103013 | | | | | | | | | |
| 56 | SMOKE | ADZ#2-37 FLOOR 2nd. | 0103014 | | | | | | | | | |
| 57 | SMOKE | ADZ#2-38 FLOOR 2nd. | 0103015 | | | | | | | | | |
| 58 | SMOKE | ADZ#2-43 FLOOR 2nd. | 0103016 | | | | | | | | | |
| 59 | SMOKE | ADZ#2-44 FLOOR 2nd. | 0103017 | | | | | | | | | |
| 60 | SMOKE | ADZ#2-45 FLOOR 2nd. | 0103018 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 2nd Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

| INSPECTION AND TEST REPORT FOR DEVICES | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | HEAT | ADZ#2-42 FLOOR 2nd. | 0103019 | | | | | | | | | |
| 62 | SMOKE | ADZ#2-26 FLOOR 2nd. | 0103040 | | | | | | | | | |
| 63 | HEAT | ADZ#2-22 FLOOR 2nd. | 0103056 | | | | | | | | | |
| 64 | SMOKE | ADZ#2-01 FLOOR 2nd. | 0103059 | | | | | | | | | |
| 65 | SMOKE | ADZ#2-21 FLOOR 2nd. | 0103082 | | | | | | | | | |
| 66 | SMOKE | ADZ#2-25 FLOOR 2nd. | 0103083 | | | | | | | | | |
| 67 | SMOKE | ADZ#2-28 FLOOR 2nd. | 0103088 | | | | | | | | | |
| 68 | SMOKE | SMK_DZ_FL2_1 FLOOR 2nd | 0103126 | | | | | | | | | |
| 69 | SMOKE | SMK_DZ_FL2_2 FLOOR 2nd | 0103127 | | | | | | | | | |
| 70 | SMOKE | SMK_DZ_FL2_3 FLOOR 2nd | 0103128 | | | | | | | | | |
| 71 | SMOKE | SMK_DZ_FL2_4 FLOOR 2nd | 0103129 | | | | | | | | | |
| 72 | SMOKE | SMK_DZ_FL2_5 FLOOR 2nd | 0103130 | | | | | | | | | |
| 73 | SMOKE | SMK_DZ_FL2_6 FLOOR 2nd | 0103131 | | | | | | | | | |
| 74 | SMOKE | SMK_DZ_FL2_7 FLOOR 2nd | 0103132 | | | | | | | | | |
| 75 | SMOKE | SMK_DZ_FL2_8 FLOOR 2nd | 0103133 | | | | | | | | | |
| 76 | SMOKE | SMK_DZ_FL2_9 FLOOR 2nd | 0103134 | | | | | | | | | |
| 77 | SMOKE | SMK_DZ_FL2_10 FLOOR 2nd | 0103135 | | | | | | | | | |
| 78 | SUPERVISORY | SUPERVISORY_1 FLOOR 2nd | 0103136 | | | | | | | | | |
| 79 | WATERFLOW | SUPERVISORY_FS_FL2_1 FLOOR 2nd | 0103137 | | | | | | | | | |
| 80 | FANCONTROL | AC2_PP_FL2_1 FLOOR 2nd | 0103138 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 3 rd Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_B3 BASEMENT_3rd | | | | | | | | | | |
| 2 | SMOKE | ADZ#B3-18 BASEMENT_3rd | | | | | | | | | | |
| 3 | HEAT | ADZ#B3-17 BASEMENT_3rd | | | | | | | | | | |
| 4 | HEAT | ADZ#B3-15 BASEMENT_3rd | | | | | | | | | | |
| 5 | HEAT | ADZ#B3-14 BASEMENT_3rd | | | | | | | | | | |
| 6 | HEAT | ADZ#B3-12 BASEMENT_3rd | | | | | | | | | | |
| 7 | HEAT | ADZ#B3-13 BASEMENT_3rd | | | | | | | | | | |
| 8 | HEAT | ADZ#B3-16 BASEMENT_3rd | | | | | | | | | | |
| 9 | HEAT | ADZ#B3-11 BASEMENT_3rd | | | | | | | | | | |
| 10 | SMOKE | ADZ#B3-10 BASEMENT_3rd | | | | | | | | | | |
| 11 | SMOKE | ADZ#B3-07 BASEMENT_3rd | | | | | | | | | | |
| 12 | SMOKE | ADZ#B3-02 BASEMENT_3th | | | | | | | | | | |
| 13 | SMOKE | ADZ#B3-03 BASEMENT_3rd | | | | | | | | | | |
| 14 | SMOKE | ADZ#B3-01 BASEMENT_3rd | | | | | | | | | | |
| 15 | HEAT | ADZ#B2-23 BASEMENT_3rd | | | | | | | | | | |
| 16 | HEAT | ADZ#B3-08 BASEMENT_3rd | | | | | | | | | | |
| 17 | HEAT | ADZ#B3-09 BASEMENT_3rd | | | | | | | | | | |
| 18 | SMOKE | DZ#B301 BASEMENT_3rd | | | | | | | | | | |
| 19 | SMOKE | DZ#B302 BASEMENT_3rd | | | | | | | | | | |
| 20 | SMOKE | DZ#B303 BASEMENT_3rd | | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 3 rd Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SUPERVISORY | SUPERVISORY_1 BASEMEANT_3rd. | 0102154 | | | | | | | | | |
| 22 | WATERFLOW | WATERFLOW_FS_B3_1 BASEMENT_3rd | 0102155 | | | | | | | | | |
| 23 | FANCONTROL | EXHAUST-FAN-EF-B3.1 BASEMENT-3rd Fl. | 0102156 | | | | | | | | | |
| 24 | AUDIBLE | AUDIBLE_ABZ_B3_1 BASEMENT_3rd | 0102157 | | | | | | | | | |
| 25 | AUDIBLE | AUDIBLE_STROBE_B3_1 BASEMENT_3rd | 0102158 | | | | | | | | | |
| 26 | AUDIBLE | AUDIBLE_ASZ_B3_1 BASEMENT_3rd | 0102159 | | | | | | | | | |
| 27 | PULL | PULL_AMZ_B3_03 BASEMENT_3rd | 0102181 | | | | | | | | | |
| 28 | PULL | PULL_AMZ_B3_02 BASEMENT_3rd | 0102182 | | | | | | | | | |
| 29 | PULL | PULL_AMZ_B3_01 BASEMENT_3rd | 0102183 | | | | | | | | | |
| 30 | ISOLATOR | IM_IN_FTB_3 FLOOR 3rd | 0103003 | | | | | | | | | |
| 31 | ISOLATOR | IM_OUT_FTB_3 FLOOR 3rd | 0103004 | | | | | | | | | |
| 32 | SMOKE | ADZ#3-01 FLOOR 3rd. | 0103020 | | | | | | | | | |
| 33 | SMOKE | ADZ#3-02 FLOOR 3rd. | 0103021 | | | | | | | | | |
| 34 | SMOKE | ADZ#3-22 FLOOR 3rd. | 0103022 | | | | | | | | | |
| 35 | SMOKE | ADZ#3-05 FLOOR 3rd. | 0103023 | | | | | | | | | |
| 36 | SMOKE | ADZ#3-09 FLOOR 3rd. | 0103024 | | | | | | | | | |
| 37 | SMOKE | ADZ#3-10 FLOOR 3rd. | 0103025 | | | | | | | | | |
| 38 | SMOKE | ADZ#3-11 FLOOR 3rd. | 0103026 | | | | | | | | | |
| 39 | SMOKE | ADZ#3-20 FLOOR 3rd. | 0103027 | | | | | | | | | |
| 40 | SMOKE | ADZ#3-21 FLOOR 3rd. | 0103028 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 3 rd Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | HEAT | ADZ#3-23 FLOOR 3rd. | 0103029 | | | | | | | | | |
| 42 | HEAT | ADZ#3-24 FLOOR 3rd. | 0103030 | | | | | | | | | |
| 43 | HEAT | ADZ#3-25 FLOOR 3rd. | 0103031 | | | | | | | | | |
| 44 | SMOKE | ADZ#3-0-3 FLOOR 3rd. | 0103032 | | | | | | | | | |
| 45 | HEAT | ADZ#3-29 FLOOR 3rd. | 0103033 | | | | | | | | | |
| 46 | SMOKE | ADZ#3-37 FLOOR 3rd. | 0103034 | | | | | | | | | |
| 47 | SMOKE | ADZ#3-38 FLOOR 3rd. | 0103035 | | | | | | | | | |
| 48 | SMOKE | ADZ#3-27 FLOOR 3rd. | 0103036 | | | | | | | | | |
| 49 | SMOKE | ADZ#3-39 FLOOR 3rd. | 0103037 | | | | | | | | | |
| 50 | SMOKE | ADZ#3-40 FLOOR 3rd. | 0103038 | | | | | | | | | |
| 51 | SMOKE | ADZ#3-42 FLOOR 3rd. | 0103039 | | | | | | | | | |
| 52 | SMOKE | ADZ#3-12 FLOOR 3rd. | 0103041 | | | | | | | | | |
| 53 | SMOKE | ADZ#3-13 FLOOR 3rd. | 0103042 | | | | | | | | | |
| 54 | SMOKE | ADZ#3-14 FLOOR 3rd. | 0103043 | | | | | | | | | |
| 55 | SMOKE | ADZ#3-15 FLOOR 3rd. | 0103044 | | | | | | | | | |
| 56 | SMOKE | ADZ#3-28 FLOOR 3rd. | 0103045 | | | | | | | | | |
| 57 | SMOKE | ADZ#3-04 FLOOR 3rd. | 0103046 | | | | | | | | | |
| 58 | HEAT | ADZ#3-17 FLOOR 3rd. | 0103047 | | | | | | | | | |
| 59 | HEAT | ADZ#3-18 FLOOR 3rd. | 0103048 | | | | | | | | | |
| 60 | SMOKE | ADZ#3-16 FLOOR 3rd. | 0103049 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 3 rd Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

| INSPECTION AND TEST REPORT FOR DEVICES | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | SMOKE | ADZ#3-26 FLOOR 3rd. | 0103050 | | | | | | | | | |
| 62 | SMOKE | ADZ#3-30 FLOOR 3rd. | 0103051 | | | | | | | | | |
| 63 | SMOKE | ADZ#3-31 FLOOR 3rd. | 0103052 | | | | | | | | | |
| 64 | SMOKE | ADZ#3-32 FLOOR 3rd. | 0103053 | | | | | | | | | |
| 65 | SMOKE | ADZ#3-33 FLOOR 3rd. | 0103054 | | | | | | | | | |
| 66 | SMOKE | ADZ#3-34 FLOOR 3rd. | 0103055 | | | | | | | | | |
| 67 | SMOKE | ADZ#3-36 FLOOR 3rd. | 0103057 | | | | | | | | | |
| 68 | SMOKE | ADZ#3-35 FLOOR 3rd. | 0103058 | | | | | | | | | |
| 69 | SMOKE | ADZ#3-08 FLOOR 3rd. | 0103060 | | | | | | | | | |
| 70 | SMOKE | ADZ#3-41 FLOOR 3rd. | 0103061 | | | | | | | | | |
| 71 | SMOKE | ADZ#3-19 FLOOR 3rd. | 0103062 | | | | | | | | | |
| 72 | SMOKE | SMK_DZ_FL3_1 FLOOR 3rd | 0103143 | | | | | | | | | |
| 73 | SMOKE | SMK_DZ_FL3_2 FLOOR 3rd | 0103144 | | | | | | | | | |
| 74 | SMOKE | SMK_DZ_FL3_3 FLOOR 3rd | 0103145 | | | | | | | | | |
| 75 | SMOKE | SMK_DZ_FL3_4 FLOOR 3rd | 0103146 | | | | | | | | | |
| 76 | SMOKE | SMK_DZ_FL3_5 FLOOR 3rd | 0103147 | | | | | | | | | |
| 77 | SMOKE | SMK_DZ_FL3_6 FLOOR 3rd | 0103148 | | | | | | | | | |
| 78 | SMOKE | SMK_DZ_FL3_7 FLOOR 3rd | 0103149 | | | | | | | | | |
| 79 | SMOKE | SMK_DZ_FL3_8 FLOOR 3rd | 0103150 | | | | | | | | | |
| 80 | SMOKE | SMK_DZ_FL3_9 FLOOR 3rd | 0103151 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 3 rd Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 81 | SMOKE | SMK_DZ_FL3_10 FLOOR 3rd | 0103152 | | | | | | | | | |
| 82 | SMOKE | SMK_DZ_FL3_11 FLOOR 3rd | 0103153 | | | | | | | | | |
| 83 | SMOKE | SMK_DZ_FL3_12 FLOOR 3rd | 0103154 | | | | | | | | | |
| 84 | SMOKE | SMK_DZ_FL3_13 FLOOR 3rd | 0103155 | | | | | | | | | |
| 85 | SMOKE | SMK_DZ_FL3_14 FLOOR 3rd | 0103156 | | | | | | | | | |
| 86 | SMOKE | SMK_DZ_FL3_15 FLOOR 3rd | 0103157 | | | | | | | | | |
| 87 | SMOKE | SMK_DZ_FL3_16 FLOOR 3rd | 0103158 | | | | | | | | | |
| 88 | SMOKE | SMK_DZ_FL3_17 FLOOR 3rd | 0103159 | | | | | | | | | |
| 89 | SUPERVISORY | SUPERVISORY_1 FLOOR 3rd. | 0103160 | | | | | | | | | |
| 90 | WATERFLOW | WATERFLOW_FS_FL3_1 FLOOR 3rd | 0103161 | | | | | | | | | |
| 91 | FANCONTROL | AC3_PP_FL3_1 FLOOR 3rd | 0103162 | | | | | | | | | |
| 92 | FANCONTROL | AC3_PP_FL3_2 FLOOR 3rd | 0103163 | | | | | | | | | |
| 93 | AUDIBLE | AUDIBLE_ABZ_FL3_1 FLOOR 3rd | 0103164 | | | | | | | | | |
| 94 | AUDIBLE | AUDIBLE_STROBE_FL3_1 FLOOR 3rd | 0103165 | | | | | | | | | |
| 95 | AUDIBLE | AUDIBLE_ASZ_FL3_1 FLOOR 3rd. | 0103166 | | | | | | | | | |
| 96 | SMOKE | SMK_DZ_FL3_18 FLOOR 3rd | 0103172 | | | | | | | | | |
| 97 | PULL | GAS_307 FLOOR 3rd. | 0103173 | | | | | | | | | |
| 98 | PULL | SPARE_GAS_307 FLOOR 3rd. | 0103174 | | | | | | | | | |
| 99 | PULL | AMZ#3-01 FLOOR 3rd. | 0103175 | | | | | | | | | |
| 100 | PULL | AMZ#3-02 FLOOR 3rd. | 0103176 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 3 rd Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

| INSPECTION AND TEST REPORT FOR DEVICES | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 101 | PULL | GAS_309 FLOOR 3rd. | 0103177 | | | | | | | | | |
| 102 | PULL | SPARE_GAS_309 FLOOR 3rd. | 0103178 | | | | | | | | | |
| 103 | PULL | GAS_308 FLOOR 3rd. | 0103179 | | | | | | | | | |
| 104 | PULL | SPARE_GAS_308 FLOOR 3rd. | 0103180 | | | | | | | | | |
| 105 | PULL | GAS_311 FLOOR 3rd. | 0103181 | | | | | | | | | |
| 106 | PULL | SPARE_GAS_311 FLOOR 3rd. | 0103182 | | | | | | | | | |
| 107 | PULL | GAS_313 FLOOR 3rd. | 0103183 | | | | | | | | | |
| 108 | PULL | SPARE_GAS_313 FLOOR 3rd. | 0103184 | | | | | | | | | |
| 109 | PULL | GAS_312 FLOOR 3rd. | 0103185 | | | | | | | | | |
| 110 | PULL | SPARE_GAS_312 FLOOR 3rd. | 0103186 | | | | | | | | | |
| 111 | PULL | AMZ#3-04 FLOOR 3rd. | 0103187 | | | | | | | | | |
| 112 | PULL | AMZ#3-05 FLOOR 3rd. | 0103188 | | | | | | | | | |
| 113 | PULL | GAS_301 FLOOR 3rd. | 0103189 | | | | | | | | | |
| 114 | PULL | SPARE_GAS_301 FLOOR 3rd. | 0103190 | | | | | | | | | |
| 115 | PULL | GAS_315 FLOOR 3rd. | 0103191 | | | | | | | | | |
| 116 | PULL | SPARE_GAS_315 FLOOR 3rd. | 0103192 | | | | | | | | | |
| 117 | PULL | GAS_314 FLOOR 3rd. | 0103193 | | | | | | | | | |
| 118 | PULL | SPARE_GAS_314 FLOOR 3rd. | 0103194 | | | | | | | | | |
| 119 | PULL | GAS_302 FLOOR 3rd. | 0103195 | | | | | | | | | |
| 120 | PULL | SPARE_GAS_302 FLOOR 3rd. | 0103196 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : _____ Location : 3 rd Floor

Service : ☐ Yearly _____ ☐ Other _____

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 121 | PULL | GAS_303 FLOOR 3rd. | 0103197 | | | | | | | | | |
| 122 | PULL | SPARE_GAS_303 FLOOR 3rd. | 0103198 | | | | | | | | | |
| 123 | PULL | AMZ#3-06 FLOOR 3rd. | 0103199 | | | | | | | | | |
| 124 | PULL | GAS_316 FLOOR 3rd. | 0103200 | | | | | | | | | |
| 125 | PULL | SPARE_GAS_316 FLOOR 3rd. | 0103201 | | | | | | | | | |
| 126 | PULL | GAS_304 FLOOR 3rd. | 0103202 | | | | | | | | | |
| 127 | PULL | SPARE_GAS_304 FLOOR 3rd. | 0103203 | | | | | | | | | |
| 128 | PULL | GAS_305 FLOOR 3rd. | 0103204 | | | | | | | | | |
| 129 | PULL | SPARE_GAS_306 FLOOR 3rd. | 0103205 | | | | | | | | | |
| 130 | AUDIBLE | AZ_FL3_POWERBELL FLOOR 3rd. | 0103207 | | | | | | | | | |
| 131 | MONITOR | MONITOR_FL3_BOOSTER FLOOR 3rd. | 0103208 | | | | | | | | | |
| 132 | PULL | AMZ#3-03 FLOOR 3rd. | 0103210 | | | | | | | | | |
| 133 | | | | | | | | | | | | |
| 134 | | | | | | | | | | | | |
| 135 | | | | | | | | | | | | |
| 136 | | | | | | | | | | | | |
| 137 | | | | | | | | | | | | |
| 138 | | | | | | | | | | | | |
| 139 | | | | | | | | | | | | |
| 140 | | | | | | | | | | | | |

COMMENT : _____

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 4 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_B4 BASEMENT_4th | 0102001 | | | | | | | | | |
| 2 | SMOKE | ADZ#B4-02 BASEMENT_4th | 0102006 | | | | | | | | | |
| 3 | HEAT | ADZ#B4-05 BASEMENT_4th | 0102007 | | | | | | | | | |
| 4 | SMOKE | ADZ#B4-03 BASEMENT_4th | 0102008 | | | | | | | | | |
| 5 | HEAT | ADZ#B4-18 BASEMENT_4th | 0102015 | | | | | | | | | |
| 6 | HEAT | ADZ#B4-08 BASEMENT_4th | 0102016 | | | | | | | | | |
| 7 | HEAT | ADZ#B4-06 BASEMENT_4th | 0102017 | | | | | | | | | |
| 8 | HEAT | ADZ#B4-13 BASEMENT_4th | 0102018 | | | | | | | | | |
| 9 | SMOKE | ADZ#B4-01 BASEMENT_4th | 0102019 | | | | | | | | | |
| 10 | HEAT | ADZ#B4-07 BASEMENT_4th | 0102020 | | | | | | | | | |
| 11 | HEAT | ADZ#B4-12 BASEMENT_4th | 0102021 | | | | | | | | | |
| 12 | SMOKE | ADZ#B1-04 BASEMENT_4th | 0102022 | | | | | | | | | |
| 13 | SMOKE | ADZ#B4-10 BASEMENT_4th | 0102023 | | | | | | | | | |
| 14 | SMOKE | ADZ#B4-19 BASEMENT_4th | 0102024 | | | | | | | | | |
| 15 | HEAT | ADZ#B4-11 BASEMENT_4th | 0102025 | | | | | | | | | |
| 16 | HEAT | ADZ#B4-14 BASEMENT_4th | 0102026 | | | | | | | | | |
| 17 | HEAT | ADZ#B4-15 BASEMENT_4th | 0102027 | | | | | | | | | |
| 18 | HEAT | ADZ#B4-17 BASEMENT_4th | 0102028 | | | | | | | | | |
| 19 | HEAT | ADZ#B4-16 BASEMENT_4th | 0102029 | | | | | | | | | |
| 20 | SMOKE | ADZ#B2-04 BASEMENT_4th | 0102036 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 4 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#B3-04 BASEMENT_4th | 0102045 | | | | | | | | | |
| 22 | HEAT | ADZ#B4-09 BASEMENT_4th | 0102046 | | | | | | | | | |
| 23 | SMOKE | ADZ#B4-04 BASEMENT_4th | 0102088 | | | | | | | | | |
| 24 | SMOKE | DZ#B401 BASEMENT_4th | 0102126 | | | | | | | | | |
| 25 | SMOKE | DZ#B402 BASEMENT_4th | 0102127 | | | | | | | | | |
| 26 | SMOKE | DZ#B403 BASEMENT_4th | 0102128 | | | | | | | | | |
| 27 | SUPERVISORY | SUPERVISORY_1 BASEMEANT_4th | 0102129 | | | | | | | | | |
| 28 | SUPERVISORY | SUPERVISORY_2 BASEMEANT_4th | 0102130 | | | | | | | | | |
| 29 | SUPERVISORY | SUPERVISORY_3 BASEMEANT_4th | 0102131 | | | | | | | | | |
| 30 | SUPERVISORY | SUPERVISORY_4 BASEMEANT_4th | 0102132 | | | | | | | | | |
| 31 | SUPERVISORY | SUPERVISORY_5 BASEMEANT_4th | 0102133 | | | | | | | | | |
| 32 | WATERFLOW | WATERFLOW_1 BASEMENT_4th | 0102134 | | | | | | | | | |
| 33 | WATERFLOW | WATERFLOW_2 BASEMENT_4th | 0102135 | | | | | | | | | |
| 34 | WATERFLOW | WATERFLOW_3 BASEMENT_4th | 0102136 | | | | | | | | | |
| 35 | WATERFLOW | WATERFLOW_4 BASEMENT_4th | 0102137 | | | | | | | | | |
| 36 | WATERFLOW | WATERFLOW_5 BASEMENT_4th | 0102138 | | | | | | | | | |
| 37 | WATERFLOW | WATERFLOW_6 BASEMENT_4th | 0102139 | | | | | | | | | |
| 38 | MONITOR | JOCKYPUMP_1 BASEMENT_4th | 0102140 | | | | | | | | | |
| 39 | MONITOR | JOCKYPUMP_2 BASEMENT_4th | 0102141 | | | | | | | | | |
| 40 | MONITOR | FIREPUMP_1 BASEMENT_4th | 0102142 | | | | | | | | | |

COMMENT : .....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 4 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | MONITOR | FIREPUMP_2 BASEMENT_4th | 0102143 | | | | | | | | | |
| 42 | FANCONTROL | EXHAUSTFAN_EF_B4_1 BASEMENT_4th | 0102144 | | | | | | | | | |
| 43 | AUDIBLE | AUDIBLE_ABZ_B4_1 BASEMENT_4th | 0102148 | | | | | | | | | |
| 44 | AUDIBLE | AUDIBLE_STROBE_B4_1 BASEMENT_4th | 0102149 | | | | | | | | | |
| 45 | AUDIBLE | AUDIBLE_ASZ_B4_1 BASEMENT_4th | 0102150 | | | | | | | | | |
| 46 | PULL | PULL_AMZ_B4_01 BASEMENT_4th | 0102178 | | | | | | | | | |
| 47 | PULL | PULL_AMZ_B4_03 BASEMENT_4th | 0102179 | | | | | | | | | |
| 48 | PULL | PULL_AMZ_B4_02 BASEMENT_4th | 0102180 | | | | | | | | | |
| 49 | SUPERVISORY | SUPERVISORY_6 BASEMEANT_4th | 0102190 | | | | | | | | | |
| 50 | SUPERVISORY | SUPERVISORY_7 BASEMEANT_4th | 0102191 | | | | | | | | | |
| 51 | SUPERVISORY | SUPERVISORY_8 BASEMEANT_4th | 0102192 | | | | | | | | | |
| 52 | SUPERVISORY | SUPERVISORY_9 BASEMEANT_4th | 0102193 | | | | | | | | | |
| 53 | SUPERVISORY | SUPERVISORY_10 BASEMEANT_4th | 0102194 | | | | | | | | | |
| 54 | SUPERVISORY | SUPERVISORY_11 BASEMEANT_4th | 0102195 | | | | | | | | | |
| 55 | SUPERVISORY | SUPERVISORY_12 BASEMEANT_4th | 0102196 | | | | | | | | | |
| 56 | SUPERVISORY | SUPERVISORY_13 BASEMEANT_4th | 0102197 | | | | | | | | | |
| 57 | SUPERVISORY | SUPERVISORY_14 BASEMEANT_4th | 0102198 | | | | | | | | | |
| 58 | SUPERVISORY | SUPERVISORY_15 BASEMEANT_4th | 0102199 | | | | | | | | | |
| 59 | SUPERVISORY | SUPERVISORY_16 BASEMEANT_4th | 0102200 | | | | | | | | | |
| 60 | SUPERVISORY | SUPERVISORY_SPARE BASEMEANT_4th | 0102201 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Location : 4 th Floor

Service : ☐ Yearly ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | SUPERVISORY | SUPERVISORY_B4 BASEMEANT_4th | 0102202 | | | | | | | | | |
| 62 | WATERFLOW | WATERFLOW_B4 BASEMENT_4th | 0102203 | | | | | | | | | |
| 63 | ISOLATOR | IM_IN_FTB_4 FLOOR 4th. | 0103251 | | | | | | | | | |
| 64 | ISOLATOR | IM_OUT_FTB_4 FLOOR 4th. | 0103252 | | | | | | | | | |
| 65 | SMOKE | ADZ#4-01 FLOOR 4th. | 0103253 | | | | | | | | | |
| 66 | SMOKE | ADZ#4-02 FLOOR 4th. | 0103254 | | | | | | | | | |
| 67 | SMOKE | ADZ#4-03 FLOOR 4th. | 0103255 | | | | | | | | | |
| 68 | SMOKE | ADZ#4-04 FLOOR 4th. | 0103256 | | | | | | | | | |
| 69 | SMOKE | ADZ#4-05 FLOOR 4th. | 0103257 | | | | | | | | | |
| 70 | SMOKE | ADZ#4-06 FLOOR 4th. | 0103258 | | | | | | | | | |
| 71 | SMOKE | ADZ#4-07 FLOOR 4th. | 0103259 | | | | | | | | | |
| 72 | SMOKE | ADZ#4-08 FLOOR 4th. | 0103260 | | | | | | | | | |
| 73 | SMOKE | ADZ#4-10 FLOOR 4th. | 0103261 | | | | | | | | | |
| 74 | SMOKE | ADZ#4-09 FLOOR 4th. | 0103262 | | | | | | | | | |
| 75 | HEAT | ADZ#4-11 FLOOR 4th. | 0103263 | | | | | | | | | |
| 76 | HEAT | ADZ#4-12 FLOOR 4th. | 0103264 | | | | | | | | | |
| 77 | HEAT | ADZ#4-14 FLOOR 4th. | 0103265 | | | | | | | | | |
| 78 | HEAT | ADZ#4-15 FLOOR 4th. | 0103266 | | | | | | | | | |
| 79 | HEAT | ADZ#4-16 FLOOR 4th. | 0103267 | | | | | | | | | |
| 80 | HEAT | ADZ#4-17 FLOOR 4th. | 0103268 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 4 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 81 | HEAT | ADZ#4-18 FLOOR 4th. | 0103269 | | | | | | | | | |
| 82 | SMOKE | ADZ#4-19 FLOOR 4th. | 0103270 | | | | | | | | | |
| 83 | SMOKE | ADZ#4-20 FLOOR 4th. | 0103271 | | | | | | | | | |
| 84 | SMOKE | ADZ#4-22 FLOOR 4th. | 0103272 | | | | | | | | | |
| 85 | SMOKE | ADZ#4-23 FLOOR 4th. | 0103273 | | | | | | | | | |
| 86 | SMOKE | ADZ#4-24 FLOOR 4th. | 0103274 | | | | | | | | | |
| 87 | SMOKE | ADZ#4-25 FLOOR 4th. | 0103275 | | | | | | | | | |
| 88 | SMOKE | ADZ#4-27 FLOOR 4th. | 0103276 | | | | | | | | | |
| 89 | SMOKE | ADZ#4-28 FLOOR 4th. | 0103277 | | | | | | | | | |
| 90 | SMOKE | ADZ#4-29 FLOOR 4th. | 0103278 | | | | | | | | | |
| 91 | SMOKE | GUEST LIFT LOBBY FLOOR 4th. | 0103279 | | | | | | | | | |
| 92 | HEAT | ADZ#4-32 FLOOR 4th. | 0103280 | | | | | | | | | |
| 93 | SMOKE | ADZ#4-33 FLOOR 4th. | 0103281 | | | | | | | | | |
| 94 | SMOKE | ADZ#4-45 FLOOR 4th. | 0103282 | | | | | | | | | |
| 95 | SMOKE | ADZ#4-34 FLOOR 4th. | 0103283 | | | | | | | | | |
| 96 | SMOKE | ADZ#4-35 FLOOR 4th. | 0103284 | | | | | | | | | |
| 97 | SMOKE | ADZ#4-37 FLOOR 4th. | 0103285 | | | | | | | | | |
| 98 | SMOKE | ADZ#4-38 FLOOR 4th. | 0103286 | | | | | | | | | |
| 99 | SMOKE | ADZ#4-39 FLOOR 4th. | 0103287 | | | | | | | | | |
| 100 | SMOKE | ADZ#4-40 FLOOR 4th. | 0103288 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 4 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 101 | SMOKE | ADZ#4-42 FLOOR 4th. | 0103289 | | | | | | | | | |
| 102 | SMOKE | ADZ#4-41 FLOOR 4th. | 0103290 | | | | | | | | | |
| 103 | SMOKE | ADZ#4-43 FLOOR 4th. | 0103291 | | | | | | | | | |
| 104 | SMOKE | ADZ#4-44 FLOOR 4th. | 0103292 | | | | | | | | | |
| 105 | SMOKE | ADZ#4-46 FLOOR 4th. | 0103293 | | | | | | | | | |
| 106 | SMOKE | ADZ#4-47 FLOOR 4th. | 0103294 | | | | | | | | | |
| 107 | SMOKE | ADZ#4-48 FLOOR 4th. | 0103295 | | | | | | | | | |
| 108 | SMOKE | ADZ#4-49 FLOOR 4th. | 0103296 | | | | | | | | | |
| 109 | SMOKE | ADZ#4-50 FLOOR 4th. | 0103297 | | | | | | | | | |
| 110 | SMOKE | ADZ#4-51 FLOOR 4th. | 0103298 | | | | | | | | | |
| 111 | SMOKE | ADZ#4-54 FLOOR 4th. | 0103299 | | | | | | | | | |
| 112 | SMOKE | ADZ#4-55 FLOOR 4th. | 0103300 | | | | | | | | | |
| 113 | SMOKE | ADZ#4-58 FLOOR 4th. | 0103301 | | | | | | | | | |
| 114 | SMOKE | ADZ#4-56 FLOOR 4th. | 0103302 | | | | | | | | | |
| 115 | SMOKE | ADZ#4-57 FLOOR 4th. | 0103303 | | | | | | | | | |
| 116 | HEAT | ADZ#4-59 FLOOR 4th. | 0103304 | | | | | | | | | |
| 117 | HEAT | ADZ#4-60 FLOOR 4th. | 0103305 | | | | | | | | | |
| 118 | SMOKE | ADZ#4-61 FLOOR 4th. | 0103306 | | | | | | | | | |
| 119 | SMOKE | ADZ#4-62 FLOOR 4th. | 0103307 | | | | | | | | | |
| 120 | SMOKE | ADZ#4-63 FLOOR 4th. | 0103308 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 4 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 121 | SMOKE | ADZ#4-64 FLOOR 4th. | 0103309 | | | | | | | | | |
| 122 | SMOKE | ADZ#4-65 FLOOR 4th. | 0103310 | | | | | | | | | |
| 123 | SMOKE | ADZ#4-67 FLOOR 4th. | 0103311 | | | | | | | | | |
| 124 | SMOKE | ADZ#4-68 FLOOR 4th. | 0103312 | | | | | | | | | |
| 125 | SMOKE | ADZ#4-69 FLOOR 4th. | 0103313 | | | | | | | | | |
| 126 | SMOKE | ADZ#4-70 FLOOR 4th. | 0103314 | | | | | | | | | |
| 127 | SMOKE | ADZ#4-71 FLOOR 4th. | 0103315 | | | | | | | | | |
| 128 | SMOKE | ENGINE LIFT FLOOR 4th. | 0103316 | | | | | | | | | |
| 129 | SMOKE | ADZ#4-30 FLOOR 4th. | 0103317 | | | | | | | | | |
| 130 | SMOKE | ADZ#4-36 FLOOR 4th. | 0103318 | | | | | | | | | |
| 131 | SMOKE | ADZ#4-52 FLOOR 4th. | 0103319 | | | | | | | | | |
| 132 | SMOKE | ADZ#4-53 FLOOR 4th. | 0103320 | | | | | | | | | |
| 133 | SMOKE | STORAGE RM. FL- 4th. | 0103321 | | | | | | | | | |
| 134 | SMOKE | F&B DIRECTOR-1 FL- 4th. | 0103322 | | | | | | | | | |
| 135 | HEAT | DROP OFF FL- 4th. | 0103323 | | | | | | | | | |
| 136 | HEAT | DISH WASH AREA FL- 4th. | 0103324 | | | | | | | | | |
| 137 | HEAT | BANQUET STORAGE 2/1 FL- 4th. | 0103325 | | | | | | | | | |
| 138 | HEAT | BANQUET STORAGE 2/2 FL- 4th. | 0103326 | | | | | | | | | |
| 139 | HEAT | STEWARD STORE FL- 4th. | 0103327 | | | | | | | | | |
| 140 | HEAT | FORNT CHEF'S OFFICE FL- 4th. | 0103328 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 4 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 141 | HEAT | BULK COOKING AREA FL- 4th. | 0103329 | | | | | | | | | |
| 142 | HEAT | HEATED COLD BANQUET-1FL- 4th. | 0103330 | | | | | | | | | |
| 143 | HEAT | BANQUET KITCHEN FL- 4th. | 0103331 | | | | | | | | | |
| 144 | HEAT | HEATED COLD BANQUET-2FL- 4th. | 0103332 | | | | | | | | | |
| 145 | HEAT | HEATED COLD BANQUET-3FL- 4th. | 0103333 | | | | | | | | | |
| 146 | HEAT | FRONT GRADE MANAGER-1FL- 4th. | 0103334 | | | | | | | | | |
| 147 | HEAT | GRADE MANAGER/COLD KITCHEN FL- 4th. | 0103335 | | | | | | | | | |
| 148 | HEAT | VEG/FRUIT PREP FL- 4th. | 0103336 | | | | | | | | | |
| 149 | HEAT | SEA FOOD PREP FL- 4th. | 0103337 | | | | | | | | | |
| 150 | HEAT | BUTSHERY PREP FL- 4th. | 0103338 | | | | | | | | | |
| 151 | HEAT | FINISHING BAKERY PASTRY RM FL- 4th. | 0103339 | | | | | | | | | |
| 152 | HEAT | PASTRY CHEF'S OFFICE FL- 4th. | 0103340 | | | | | | | | | |
| 153 | HEAT | ADZ#4-13 FLOOR 4th. | 0103341 | | | | | | | | | |
| 154 | SMOKE | ADZ#4-26 FLOOR 4th. | 0103342 | | | | | | | | | |
| 155 | SMOKE | ADZ#4-31 FLOOR 4th. | 0103343 | | | | | | | | | |
| 156 | SMOKE | ADZ#4-21 FLOOR 4th. | 0103344 | | | | | | | | | |
| 157 | SMOKE | ADZ#4-66 FLOOR 4th. | 0103345 | | | | | | | | | |
| 158 | SMOKE | F&B DIRECTOR-2 FL- 4th. | 0103346 | | | | | | | | | |
| 159 | SMOKE | ST BANQUEIT STORAGE-1FL- 4th. | 0103347 | | | | | | | | | |
| 160 | SMOKE | SMK_DZ_FL4_ASD FLOOR 4th. | 0103376 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 4 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 161 | SUPERVISORY | SUPERVISORY_1 FLOOR 4th. | 0103377 | | | | | | | | | |
| 162 | WATERFLOW | WATERFLOW_FS_FL4_1 FLOOR 4th. | 0103378 | | | | | | | | | |
| 163 | FANCONTROL | LOAD CENTER PP-AC4/1 G FL. | 0103379 | | | | | | | | | |
| 164 | FANCONTROL | LOAD CENTER PP-AC4/2 G FL. | 0103380 | | | | | | | | | |
| 165 | FANCONTROL | SERVICE LIFT 5&6 MACHINE RM 4- FL. | 0103381 | | | | | | | | | |
| 166 | FANCONTROL | CONTROL (AV-4-1) FUNCTION RM.7 4- FL. | 0103382 | | | | | | | | | |
| 167 | AUDIBLE | AUDIBLE_ABZ_FL4_1 FLOOR 4th. | 0103383 | | | | | | | | | |
| 168 | AUDIBLE | AUDIBLE_STROBE_FL4_1 FLOOR 4th. | 0103384 | | | | | | | | | |
| 169 | AUDIBLE | AUDIBLE_ASZ_FL4_1 FLOOR 4th. | 0103385 | | | | | | | | | |
| 170 | PULL | AMZ#4-01 FLOOR 4th. | 0103386 | | | | | | | | | |
| 171 | PULL | AMZ#4-02 FLOOR 4th. | 0103387 | | | | | | | | | |
| 172 | PULL | AMZ#4-03 FLOOR 4th. | 0103388 | | | | | | | | | |
| 173 | PULL | AMZ#4-04 FLOOR 4th. | 0103389 | | | | | | | | | |
| 174 | PULL | AMZ#4-05 FLOOR 4th. | 0103390 | | | | | | | | | |
| 175 | PULL | ANSUL 4-1 KITCHEN RM. 4- FL. | 0103391 | | | | | | | | | |
| 176 | PULL | GAS 4-1 KITCHEN RM. 4- FL. | 0103392 | | | | | | | | | |
| 177 | PULL | ANSUL 4-2 KITCHEN RM. 4- FL. | 0103393 | | | | | | | | | |
| 178 | PULL | ANSUL 4-3 KITCHEN RM. 4- FL. | 0103394 | | | | | | | | | |
| 179 | FANCONTROL | CONTROL (AV-4-2) FUNCTION RM.3 4- FL. | 0103395 | | | | | | | | | |
| 180 | FANCONTROL | CONTROL_NONAME_FL4_1 | 0103396 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 4 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 181 | FANCONTROL | CONTROL (AV-4-3) FUNCTION RM.1 4- FL. | 0103398 | | | | | | | | | |
| 182 | SMOKE | BEAM 01 FLOOR 4th. | 0107157 | | | | | | | | | |
| 183 | SMOKE | BEAM 02 FLOOR 4th. | 0107158 | | | | | | | | | |
| 184 | | | | | | | | | | | | |
| 185 | | | | | | | | | | | | |
| 186 | | | | | | | | | | | | |
| 187 | | | | | | | | | | | | |
| 188 | | | | | | | | | | | | |
| 189 | | | | | | | | | | | | |
| 190 | | | | | | | | | | | | |
| 191 | | | | | | | | | | | | |
| 192 | | | | | | | | | | | | |
| 193 | | | | | | | | | | | | |
| 194 | | | | | | | | | | | | |
| 195 | | | | | | | | | | | | |
| 196 | | | | | | | | | | | | |
| 197 | | | | | | | | | | | | |
| 198 | | | | | | | | | | | | |
| 199 | | | | | | | | | | | | |
| 200 | | | | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 5 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_5 FLOOR 5th. | 0107001 | | | | | | | | | |
| 2 | SMOKE | ADZ#5-01 FLOOR 5th. | 0107004 | | | | | | | | | |
| 3 | SMOKE | ADZ#5-02 FLOOR 5th. | 0107005 | | | | | | | | | |
| 4 | SMOKE | ADZ#5-30 FLOOR 5th. | 0107006 | | | | | | | | | |
| 5 | SMOKE | ADZ#5-05 FLOOR 5th. | 0107007 | | | | | | | | | |
| 6 | SMOKE | ADZ#5-32 FLOOR 5th. | 0107008 | | | | | | | | | |
| 7 | SMOKE | ADZ#5-59 FLOOR 5th. | 0107009 | | | | | | | | | |
| 8 | SMOKE | ADZ#5-08 FLOOR 5th. | 0107010 | | | | | | | | | |
| 9 | SMOKE | ADZ#5-09 FLOOR 5th. | 0107011 | | | | | | | | | |
| 10 | SMOKE | ADZ#5-11 FLOOR 5th. | 0107012 | | | | | | | | | |
| 11 | SMOKE | ADZ#5-20 FLOOR 5th. | 0107013 | | | | | | | | | |
| 12 | SMOKE | ADZ#5-21 FLOOR 5th. | 0107014 | | | | | | | | | |
| 13 | SMOKE | ADZ#5-23 FLOOR 5th. | 0107015 | | | | | | | | | |
| 14 | SMOKE | ADZ#5-22 FLOOR 5th. | 0107016 | | | | | | | | | |
| 15 | SMOKE | ADZ#5-25 FLOOR 5th. | 0107017 | | | | | | | | | |
| 16 | SMOKE | ADZ#5-24 FLOOR 5th. | 0107018 | | | | | | | | | |
| 17 | SMOKE | ADZ#5-28 FLOOR 5th. | 0107019 | | | | | | | | | |
| 18 | SMOKE | ADZ#5-37 FLOOR 5th. | 0107020 | | | | | | | | | |
| 19 | SMOKE | ADZ#5-29 FLOOR 5th. | 0107021 | | | | | | | | | |
| 20 | SMOKE | ADZ#5-04 FLOOR 5th. | 0107022 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 5 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#5-33 FLOOR 5th. | 0107023 | | | | | | | | | |
| 22 | SMOKE | ADZ#5-34 FLOOR 5th. | 0107024 | | | | | | | | | |
| 23 | SMOKE | ADZ#5-35 FLOOR 5th | 0107025 | | | | | | | | | |
| 24 | SMOKE | ADZ#5-31 FLOOR 5th. | 0107026 | | | | | | | | | |
| 25 | SMOKE | ADZ#5-06 FLOOR 5th. | 0107027 | | | | | | | | | |
| 26 | SMOKE | ADZ#5-36 FLOOR 5th. | 0107028 | | | | | | | | | |
| 27 | SMOKE | ADZ#5-38 FLOOR 5th. | 0107029 | | | | | | | | | |
| 28 | SMOKE | ADZ#5-39 FLOOR 5th. | 0107030 | | | | | | | | | |
| 29 | SMOKE | ADZ#5-40 FLOOR 5th. | 0107031 | | | | | | | | | |
| 30 | HEAT | ADZ#5-41 FLOOR 5th. | 0107032 | | | | | | | | | |
| 31 | HEAT | ADZ#5-42 FLOOR 5th. | 0107033 | | | | | | | | | |
| 32 | HEAT | ADZ#5-44 FLOOR 5th. | 0107034 | | | | | | | | | |
| 33 | HEAT | ADZ#5-43 FLOOR 5th. | 0107035 | | | | | | | | | |
| 34 | HEAT | ADZ#5-45 FLOOR 5th. | 0107036 | | | | | | | | | |
| 35 | HEAT | ADZ#5-46 FLOOR 5th. | 0107037 | | | | | | | | | |
| 36 | HEAT | ADZ#5-47 FLOOR 5th. | 0107038 | | | | | | | | | |
| 37 | SMOKE | ADZ#5-48 FLOOR 5th. | 0107039 | | | | | | | | | |
| 38 | SMOKE | ADZ#5-49 FLOOR 5th. | 0107040 | | | | | | | | | |
| 39 | SMOKE | ADZ#5-50 FLOOR 5th. | 0107041 | | | | | | | | | |
| 40 | SMOKE | ADZ#5-60 FLOOR 5th. | 0107042 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 5 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#5-61 FLOOR 5th. | 0107043 | | | | | | | | | |
| 42 | SMOKE | ADZ#5-63 FLOOR 5th. | 0107044 | | | | | | | | | |
| 43 | SMOKE | ADZ#5-64 FLOOR 5th. | 0107045 | | | | | | | | | |
| 44 | SMOKE | ADZ#5-65 FLOOR 5th. | 0107046 | | | | | | | | | |
| 45 | SMOKE | ADZ#5-66 FLOOR 5th. | 0107047 | | | | | | | | | |
| 46 | SMOKE | ADZ#5-67 FLOOR 5th. | 0107048 | | | | | | | | | |
| 47 | SMOKE | ADZ#5-68 FLOOR 5th. | 0107049 | | | | | | | | | |
| 48 | SMOKE | ADZ#5-69 FLOOR 5th. | 0107050 | | | | | | | | | |
| 49 | SMOKE | ADZ#5-54 FLOOR 5th. | 0107051 | | | | | | | | | |
| 50 | SMOKE | ADZ#5-51 FLOOR 5th. | 0107052 | | | | | | | | | |
| 51 | SMOKE | ADZ#5-52 FLOOR 5th. | 0107053 | | | | | | | | | |
| 52 | SMOKE | ADZ#5-53 FLOOR 5th. | 0107054 | | | | | | | | | |
| 53 | SMOKE | ADZ#5-57 FLOOR 5th. | 0107055 | | | | | | | | | |
| 54 | SMOKE | ADZ#5-07 FLOOR 5th. | 0107056 | | | | | | | | | |
| 55 | SMOKE | ADZ#5-10 FLOOR 5th. | 0107057 | | | | | | | | | |
| 56 | SMOKE | ADZ#5-13 FLOOR 5th. | 0107058 | | | | | | | | | |
| 57 | SMOKE | ADZ#5-19 FLOOR 5th. | 0107059 | | | | | | | | | |
| 58 | SMOKE | ADZ#5-14 FLOOR 5th. | 0107060 | | | | | | | | | |
| 59 | SMOKE | ADZ#5-15 FLOOR 5th. | 0107061 | | | | | | | | | |
| 60 | SMOKE | ADZ#5-16 FLOOR 5th. | 0107062 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 5 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | SMOKE | SUBTANK FLOOR 5th. | 0107096 | | | | | | | | | |
| 62 | SMOKE | ADZ#5-17/1 FLOOR 5th. | 0107098 | | | | | | | | | |
| 63 | SMOKE | ADZ#5-17/2 FLOOR 5th. | 0107099 | | | | | | | | | |
| 64 | SMOKE | ADZ#5-26/1 FLOOR 5th. | 0107100 | | | | | | | | | |
| 65 | SMOKE | ADZ#5-26/2 FLOOR 5th. | 0107101 | | | | | | | | | |
| 66 | SMOKE | ADZ#5-26/3 FLOOR 5th. | 0107102 | | | | | | | | | |
| 67 | SMOKE | ADZ#5-27 FLOOR 5th. | 0107103 | | | | | | | | | |
| 68 | SMOKE | ADZ#5-58 FLOOR 5th. | 0107104 | | | | | | | | | |
| 69 | SMOKE | ADZ#5-56 FLOOR 5th. | 0107105 | | | | | | | | | |
| 70 | SMOKE | ADZ#5-55 FLOOR 5th. | 0107106 | | | | | | | | | |
| 71 | SMOKE | ADZ#5-62 FLOOR 5th. | 0107107 | | | | | | | | | |
| 72 | SMOKE | SMK_DZ_FL5_1 FLOOR 5th. | 0107126 | | | | | | | | | |
| 73 | SMOKE | SMK_DZ_FL5_2 FLOOR 5th. | 0107127 | | | | | | | | | |
| 74 | SMOKE | SMK_DZ_FL5_3 FLOOR 5th. | 0107128 | | | | | | | | | |
| 75 | SMOKE | SMK_DZ_FL5_4 FLOOR 5th. | 0107129 | | | | | | | | | |
| 76 | PULL | PULL_DZ_FL5_GEN FLOOR 5th. | 0107130 | | | | | | | | | |
| 77 | SUPERVISORY | SUPERVISORY_1 FLOOR 5th. | 0107131 | | | | | | | | | |
| 78 | WATERFLOW | WATERFLOW_FS_FL5_1 FLOOR 5th. | 0107132 | | | | | | | | | |
| 79 | FANCONTROL | AC5_PP_FL5_1 FLOOR 5th. | 0107133 | | | | | | | | | |
| 80 | FANCONTROL | AC5_PP_FL5_2 FLOOR 5th. | 0107134 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Location : 5 th Floor

Service : ☐ Yearly ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 81 | AUDIBLE | AUDIBLE_ABZ_FL5_1 FLOOR 5th. | 0107135 | | | | | | | | | |
| 82 | AUDIBLE | AUDIBLE_STROBE_FL5_1 FLOOR 5th. | 0107136 | | | | | | | | | |
| 83 | AUDIBLE | AUDIBLE_ASZ_FL5_1 FLOOR 5th. | 0107137 | | | | | | | | | |
| 84 | AUDIBLE | AUDIBLE_ASZ_FL6_1 FLOOR 5th. | 0107145 | | | | | | | | | |
| 85 | PULL | AMZ#5-01 FLOOR 5th. | 0107146 | | | | | | | | | |
| 86 | MONITOR | MONITOR_FL5_BOOSTER FLOOR 5th. | 0107147 | | | | | | | | | |
| 87 | AUDIBLE | AZ_FL5_POWERBELL | 0107148 | | | | | | | | | |
| 88 | PULL | AMZ#5-02 FLOOR 5th. | 0107149 | | | | | | | | | |
| 89 | PULL | AMZ#5-05 FLOOR 5th. | 0107150 | | | | | | | | | |
| 90 | PULL | AMZ#5-04 FLOOR 5th. | 0107151 | | | | | | | | | |
| 91 | PULL | AMZ#5-03 FLOOR 5th. | 0107152 | | | | | | | | | |
| 92 | PULL | GAS 5-2 KITCHEN RM. 5- FL. | 0107160 | | | | | | | | | |
| 93 | PULL | GAS 5-1 KITCHEN RM. 5- FL. | 0107161 | | | | | | | | | |
| 94 | PULL | ANSUL 5-1 KITCHEN RM. 5- FL. | 0107162 | | | | | | | | | |
| 95 | PULL | FIRESUPPRESSION (GEN RM.) 5- FL. | 0107163 | | | | | | | | | |
| 96 | FANCONTROL | SMK_EXTRACTION FAN 1 5- FL. | 0107164 | | | | | | | | | |
| 97 | FANCONTROL | SMK_EXTRACTION FAN 2 5- FL. | 0107165 | | | | | | | | | |
| 98 | FANCONTROL | CONTROL (AV-5-1) BALL RM. 5- FL. | 0107166 | | | | | | | | | |
| 99 | PULL | FIRESUPPRESSION (MDB RM.) 5- FL. | 0107167 | | | | | | | | | |
| 100 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 6 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_6 FLOOR 6th. | 0107002 | | | | | | | | | |
| 2 | ISOLATOR | IM_OUT_FTB_6 FLOOR 6th. | 0107003 | | | | | | | | | |
| 3 | SMOKE | ADZ#6-03 FLOOR 6th. | 0107063 | | | | | | | | | |
| 4 | SMOKE | ADZ#6-04 FLOOR 6th. | 0107064 | | | | | | | | | |
| 5 | SMOKE | ADZ#6-05 FLOOR 6th. | 0107065 | | | | | | | | | |
| 6 | HEAT | ADZ#6-06 FLOOR 6th. | 0107066 | | | | | | | | | |
| 7 | SMOKE | ADZ#6-07 FLOOR 6th. | 0107067 | | | | | | | | | |
| 8 | SMOKE | ADZ#6-08 FLOOR 6th. | 0107068 | | | | | | | | | |
| 9 | SMOKE | ADZ#6-09 FLOOR 6th. | 0107069 | | | | | | | | | |
| 10 | SMOKE | ADZ#6-10 FLOOR 6th. | 0107070 | | | | | | | | | |
| 11 | SMOKE | ADZ#6-11 FLOOR 6th. | 0107071 | | | | | | | | | |
| 12 | SMOKE | ADZ#6-12 FLOOR 6th. | 0107072 | | | | | | | | | |
| 13 | SMOKE | ADZ#6-13 FLOOR 6th. | 0107073 | | | | | | | | | |
| 14 | SMOKE | ADZ#6-14 FLOOR 6th. | 0107074 | | | | | | | | | |
| 15 | SMOKE | ADZ#6-15 FLOOR 6th. | 0107075 | | | | | | | | | |
| 16 | SMOKE | ADZ#6-18 FLOOR 6th. | 0107076 | | | | | | | | | |
| 17 | SMOKE | ADZ#6-22 FLOOR 6th. | 0107078 | | | | | | | | | |
| 18 | SMOKE | ADZ#6-23 FLOOR 6th. | 0107079 | | | | | | | | | |
| 19 | SMOKE | ADZ#6-26 FLOOR 6th. | 0107080 | | | | | | | | | |
| 20 | SMOKE | ADZ#6-27 FLOOR 6th. | 0107081 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 6 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#6-28 FLOOR 6th. | 0107082 | | | | | | | | | |
| 22 | SMOKE | ADZ#6-30 FLOOR 6th. | 0107083 | | | | | | | | | |
| 23 | SMOKE | ADZ#6-31 FLOOR 6th. | 0107084 | | | | | | | | | |
| 24 | SMOKE | ADZ#6-32 FLOOR 6th. | 0107085 | | | | | | | | | |
| 25 | SMOKE | ADZ#6-33 FLOOR 6th. | 0107086 | | | | | | | | | |
| 26 | HEAT | ADZ#6-34 FLOOR 6th. | 0107087 | | | | | | | | | |
| 27 | HEAT | ADZ#6-35 FLOOR 6th. | 0107088 | | | | | | | | | |
| 28 | HEAT | ADZ#6-36 FLOOR 6th. | 0107089 | | | | | | | | | |
| 29 | HEAT | ADZ#6-37 FLOOR 6th. | 0107090 | | | | | | | | | |
| 30 | SMOKE | ADZ#6-38 FLOOR 6th. | 0107091 | | | | | | | | | |
| 31 | SMOKE | ADZ#6-39 FLOOR 6th. | 0107092 | | | | | | | | | |
| 32 | HEAT | ADZ#6-40 FLOOR 6th. | 0107093 | | | | | | | | | |
| 33 | SMOKE | ADZ#6-41 FLOOR 6th. | 0107094 | | | | | | | | | |
| 34 | HEAT | ADZ#6-42 FLOOR 6th. | 0107095 | | | | | | | | | |
| 35 | SMOKE | ADZ#6-44 FLOOR 6th. | 0107097 | | | | | | | | | |
| 36 | SMOKE | ADZ#6-43 FLOOR 6th. | 0107108 | | | | | | | | | |
| 37 | SMOKE | ADZ#6-29 FLOOR 6th. | 0107109 | | | | | | | | | |
| 38 | HEAT | ADZ#6-25 FLOOR 6th. | 0107110 | | | | | | | | | |
| 39 | HEAT | ADZ#6-24 FLOOR 6th. | 0107111 | | | | | | | | | |
| 40 | HEAT | ADZ#6-20 FLOOR 6th. | 0107112 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 6 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#6-19 FLOOR 6th. | 0107113 | | | | | | | | | |
| 42 | SMOKE | ADZ#6-17 FLOOR 6th. | 0107114 | | | | | | | | | |
| 43 | SMOKE | ADZ#6-16 FLOOR 6th. | 0107115 | | | | | | | | | |
| 44 | SMOKE | ADZ#6-02 FLOOR 6th. | 0107116 | | | | | | | | | |
| 45 | SMOKE | ADZ#6-01 FLOOR 6th. | 0107117 | | | | | | | | | |
| 46 | HEAT | ADZ#6-21 FLOOR 6th. | 0107118 | | | | | | | | | |
| 47 | SMOKE | SMK_DZ_FL6_1 FLOOR 6th. | 0107138 | | | | | | | | | |
| 48 | SUPERVISORY | SUPERVISORY_1 FLOOR 6th. | 0107139 | | | | | | | | | |
| 49 | WATERFLOW | WATERFLOW_FS_FL6_1 FLOOR 6th. | 0107140 | | | | | | | | | |
| 50 | FANCONTROL | AC6_PP_FL6_1 FLOOR 6th. | 0107141 | | | | | | | | | |
| 51 | FANCONTROL | SERVICE LIFT 3&4 MACHINE RM. 6- FL. | 0107142 | | | | | | | | | |
| 52 | FANCONTROL | CONTROL (AV-6-1) FRONT-EE RM. 6- FL. | 0107143 | | | | | | | | | |
| 53 | AUDIBLE | AUDIBLE_STROBE_FL6_1 FLOOR 6th. | 0107144 | | | | | | | | | |
| 54 | PULL | AMZ#6-02 FLOOR 6th. | 0107153 | | | | | | | | | |
| 55 | PULL | AMZ#6-03 FLOOR 6th. | 0107154 | | | | | | | | | |
| 56 | PULL | AMZ#6-04 FLOOR 6th. | 0107155 | | | | | | | | | |
| 57 | AUDIBLE | AUDIBLE_ABZ_FL6_1 FLOOR 6th. | 0107156 | | | | | | | | | |
| 58 | PULL | AMZ#6-01 FLOOR 6th. | 0107159 | | | | | | | | | |
| 59 | PULL | GAS 6-1 KITCHEN RM. 6- FL. | 0107168 | | | | | | | | | |
| 60 | PULL | GAS 6-2 KITCHEN RM. 6- FL. | 0107169 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Location : 6 th Floor

Service : ☐ Yearly ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | PULL | ANSUL 6-1 KITCHEN RM. 6- FL. | 0107170 | | | | | | | | | |
| 62 | PULL | ANSUL 6-2 KITCHEN RM. 6- FL. | 0107171 | | | | | | | | | |
| 63 | PULL | ANSUL 6-3 KITCHEN RM. 6- FL. | 0107172 | | | | | | | | | |
| 64 | PULL | ANSUL 6-4 KITCHEN RM. 6- FL. | 0107173 | | | | | | | | | |
| 65 | FANCONTROL | CONTROL (AV-6-2) STORAGE RM. 6- FL. | 0107174 | | | | | | | | | |
| 66 | FANCONTROL | PRESSURINGFAN 1 6-FL. | 0107175 | | | | | | | | | |
| 67 | | | | | | | | | | | | |
| 68 | | | | | | | | | | | | |
| 69 | | | | | | | | | | | | |
| 70 | | | | | | | | | | | | |
| 71 | | | | | | | | | | | | |
| 72 | | | | | | | | | | | | |
| 73 | | | | | | | | | | | | |
| 74 | | | | | | | | | | | | |
| 75 | | | | | | | | | | | | |
| 76 | | | | | | | | | | | | |
| 77 | | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 7 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

| INSPECTION AND TEST REPORT FOR DEVICES | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_7 FLOOR 7th. | 0107252 | | | | | | | | | |
| 2 | SMOKE | ADZ#7-02 FLOOR 7th. | 0107253 | | | | | | | | | |
| 3 | SMOKE | ADZ#7-12 FLOOR 7th. | 0107254 | | | | | | | | | |
| 4 | SMOKE | ADZ#7-01 FLOOR 7th. | 0107256 | | | | | | | | | |
| 5 | SMOKE | ADZ#7-05 FLOOR 7th. | 0107257 | | | | | | | | | |
| 6 | SMOKE | ADZ#7-04 FLOOR 7th. | 0107258 | | | | | | | | | |
| 7 | SMOKE | ADZ#7-06 FLOOR 7th. | 0107259 | | | | | | | | | |
| 8 | SMOKE | ADZ#7-03 FLOOR 7th. | 0107260 | | | | | | | | | |
| 9 | SMOKE | ADZ#7-07 FLOOR 7th. [07-1] | 0107261 | | | | | | | | | |
| 10 | SMOKE | ADZ#7-07 FLOOR 7th. [07-2] | 0107262 | | | | | | | | | |
| 11 | SMOKE | ADZ#7-09 FLOOR 7th. [09-1] | 0107263 | | | | | | | | | |
| 12 | SMOKE | ADZ#7-07 FLOOR 7th. [07-3] | 0107264 | | | | | | | | | |
| 13 | SMOKE | ADZ#7-08 FLOOR 7th. | 0107265 | | | | | | | | | |
| 14 | SMOKE | ADZ#7-09 FLOOR 7th. [09-2] | 0107266 | | | | | | | | | |
| 15 | SMOKE | ADZ#7-10 FLOOR 7th. | 0107267 | | | | | | | | | |
| 16 | SMOKE | ADZ#7-11 FLOOR 7th. | 0107268 | | | | | | | | | |
| 17 | SMOKE | ADZ#7-16 FLOOR 7th. [16-1] | 0107269 | | | | | | | | | |
| 18 | SMOKE | ADZ#7-16 FLOOR 7th. [16-2] | 0107270 | | | | | | | | | |
| 19 | SMOKE | ADZ#7-13 FLOOR 7th. | 0107271 | | | | | | | | | |
| 20 | SMOKE | ADZ#7-16 FLOOR 7th. [16-3] | 0107272 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 7 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | HEAT | ADZ#7-15 FLOOR 7th. | 0107273 | | | | | | | | | |
| 22 | HEAT | ADZ#7-14 FLOOR 7th. | 0107274 | | | | | | | | | |
| 23 | SMOKE | ADZ#7-17 FLOOR 7th. [17-1] | 0107275 | | | | | | | | | |
| 24 | SMOKE | ADZ#7-17 FLOOR 7th. [17-2] | 0107276 | | | | | | | | | |
| 25 | SMOKE | ADZ#7-18 FLOOR 7th. | 0107277 | | | | | | | | | |
| 26 | SMOKE | ADZ#7-19 FLOOR 7th. | 0107278 | | | | | | | | | |
| 27 | SMOKE | ADZ#7-20 FLOOR 7th. [20-1] | 0107279 | | | | | | | | | |
| 28 | SMOKE | ADZ#7-20 FLOOR 7th. [20-2] | 0107280 | | | | | | | | | |
| 29 | SMOKE | ADZ#7-21 FLOOR 7th. | 0107281 | | | | | | | | | |
| 30 | SMOKE | ADZ#7-22 FLOOR 7th. | 0107282 | | | | | | | | | |
| 31 | SMOKE | ADZ#7-23 FLOOR 7th. | 0107283 | | | | | | | | | |
| 32 | SMOKE | ADZ#7-24 FLOOR 7th. | 0107284 | | | | | | | | | |
| 33 | SMOKE | ADZ#7-25 FLOOR 7th. [25-1] | 0107285 | | | | | | | | | |
| 34 | SMOKE | ADZ#7-25 FLOOR 7th. [25-2] | 0107286 | | | | | | | | | |
| 35 | SUPERVISORY | SUPERVISORY_1 FLOOR 7th. | 0107376 | | | | | | | | | |
| 36 | WATERFLOW | WATERFLOW_FS_FL7_1 FLOOR 7th. | 0107377 | | | | | | | | | |
| 37 | FANCONTROL | CONTROL_LIFT_FL7_2 FLOOR 7th. | 0107378 | | | | | | | | | |
| 38 | FANCONTROL | PF07_PF_FL7_2 FLOOR 7th. | 0107379 | | | | | | | | | |
| 39 | FANCONTROL | AC7_PP_FL7_1 FLOOR 7th. | 0107380 | | | | | | | | | |
| 40 | FANCONTROL | SERVICE LIFT 1&2 MACHINE RM. 7- FL. | 0107381 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 7 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | FANCONTROL | PF07_PF_FL7_1 FLOOR 7th. | 0107382 | | | | | | | | | |
| 42 | AUDIBLE | AUDIBLE_ASZ_FL7_1 FLOOR 7th. | 0107383 | | | | | | | | | |
| 43 | AUDIBLE | AUDIBLE_ABZ_FL7_1 FLOOR 7th. | 0107384 | | | | | | | | | |
| 44 | AUDIBLE | AUDIBLE_STROBE_FL7_1 FLOOR 7th. | 0107385 | | | | | | | | | |
| 45 | SMOKE | DZ#701 FLOOR 7th. | 0107386 | | | | | | | | | |
| 46 | PULL | PULL_AMZ_7_02 FLOOR 7th. | 0107387 | | | | | | | | | |
| 47 | PULL | PULL_AMZ_7_03 FLOOR 7th. | 0107388 | | | | | | | | | |
| 48 | PULL | PULL_AMZ_7_01 FLOOR 7th. | 0107389 | | | | | | | | | |
| 49 | MONITOR | MONITOR_FL7_BOOSTER FLOOR 7th. | 0107395 | | | | | | | | | |
| 50 | AUDIBLE | AZ_FL7_POWERBELL FLOOR 7th. | 0107396 | | | | | | | | | |
| 51 | | | | | | | | | | | | |
| 52 | | | | | | | | | | | | |
| 53 | | | | | | | | | | | | |
| 54 | | | | | | | | | | | | |
| 55 | | | | | | | | | | | | |
| 56 | | | | | | | | | | | | |
| 57 | | | | | | | | | | | | |
| 58 | | | | | | | | | | | | |
| 59 | | | | | | | | | | | | |
| 60 | | | | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 8 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_8 FLOOR 8th. | 0107251 | | | | | | | | | |
| 2 | ISOLATOR | IM_OUT_FTB_8 FLOOR 8th. | 0107255 | | | | | | | | | |
| 3 | SMOKE | ADZ#8-29-33/5 FLOOR 8th. | 0107287 | | | | | | | | | |
| 4 | SMOKE | ADZ#8-39 FLOOR 8th. | 0107288 | | | | | | | | | |
| 5 | SMOKE | ADZ#814-13 FLOOR 8th. | 0107289 | | | | | | | | | |
| 6 | SMOKE | ADZ#815-14 FLOOR 8th. | 0107290 | | | | | | | | | |
| 7 | SMOKE | ADZ#816-15 FLOOR 8th. | 0107291 | | | | | | | | | |
| 8 | SMOKE | ADZ#817-16 FLOOR 8th. | 0107292 | | | | | | | | | |
| 9 | SMOKE | ADZ#818-17 FLOOR 8th. | 0107293 | | | | | | | | | |
| 10 | SMOKE | ADZ#819-18 FLOOR 8th | 0107294 | | | | | | | | | |
| 11 | SMOKE | ADZ#8-29-33/3 FLOOR 8th | 0107295 | | | | | | | | | |
| 12 | SMOKE | ADZ#820-19 FLOOR 8th. | 0107296 | | | | | | | | | |
| 13 | SMOKE | ADZ#8-29-33/2 FLOOR 8th | 0107297 | | | | | | | | | |
| 14 | SMOKE | ADZ#821-20 FLOOR 8th. | 0107298 | | | | | | | | | |
| 15 | SMOKE | ADZ#822-21 FLOOR 8th. | 0107299 | | | | | | | | | |
| 16 | SMOKE | ADZ#8-29-33/1 FLOOR 8th | 0107300 | | | | | | | | | |
| 17 | SMOKE | ADZ#823-22 FLOOR 8th | 0107301 | | | | | | | | | |
| 18 | SMOKE | ADZ#824-23 FLOOR 8th. | 0107302 | | | | | | | | | |
| 19 | SMOKE | ADZ#801-01 FLOOR 8th. | 0107303 | | | | | | | | | |
| 20 | SMOKE | ADZ#8-24-28/1 FLOOR 8th | 0107304 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 8 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#803-03 FLOOR 8th. | 0107305 | | | | | | | | | |
| 22 | SMOKE | ADZ#804-04 FLOOR 8th. | 0107306 | | | | | | | | | |
| 23 | SMOKE | ADZ#805-05 FLOOR 8th. | 0107307 | | | | | | | | | |
| 24 | SMOKE | ADZ#8-24-28/2 FLOOR 8th | 0107308 | | | | | | | | | |
| 25 | SMOKE | ADZ#806-06 FLOOR 8th. | 0107309 | | | | | | | | | |
| 26 | SMOKE | ADZ#807-07 FLOOR 8th. | 0107310 | | | | | | | | | |
| 27 | SMOKE | ADZ#8-24-28/3 FLOOR 8th | 0107311 | | | | | | | | | |
| 28 | SMOKE | ADZ#808-08 FLOOR 8th. | 0107312 | | | | | | | | | |
| 29 | SMOKE | ADZ#809-09 FLOOR 8th. | 0107313 | | | | | | | | | |
| 30 | SMOKE | ADZ#8-24-28/4 FLOOR 8th | 0107314 | | | | | | | | | |
| 31 | SMOKE | ADZ#810-10 FLOOR 8th. | 0107315 | | | | | | | | | |
| 32 | SMOKE | ADZ#811-11 FLOOR 8th. | 0107316 | | | | | | | | | |
| 33 | SMOKE | ADZ#8-24-28/5 FLOOR 8th | 0107317 | | | | | | | | | |
| 34 | SMOKE | ADZ#812-12 FLOOR 8th. | 0107318 | | | | | | | | | |
| 35 | SMOKE | ADZ#8-37 FLOOR 8th. | 0107319 | | | | | | | | | |
| 36 | SMOKE | ADZ#8-29-33/4 FLOOR 8th | 0107320 | | | | | | | | | |
| 37 | SMOKE | ADZ#8-36 FLOOR 8th. | 0107321 | | | | | | | | | |
| 38 | SMOKE | ADZ#8-35 FLOOR 8th. | 0107322 | | | | | | | | | |
| 39 | SMOKE | ADZ#8-38 FLOOR 8th. | 0107323 | | | | | | | | | |
| 40 | SMOKE | ADZ#802-02 FLOOR 8th. | 0107324 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 8 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| | SMOKE | ADZ#8-40 FLOOR 8th. | 0107325 | | | | | | | | | |
| 42 | SMOKE | ADZ#8-34 FLOOR 8th. | 0107326 | | | | | | | | | |
| 43 | SUPERVISORY | SUPERVISORY_1 FLOOR 8th. | 0107390 | | | | | | | | | |
| 44 | WATERFLOW | WATERFLOW_FS_FL8_1 FLOOR 8th. | 0107391 | | | | | | | | | |
| 45 | AUDIBLE | AUDIBLE_STROBE_FL8_1 FLOOR 8th. | 0107392 | | | | | | | | | |
| 46 | AUDIBLE | AUDIBLE_ASZ_FL8_1 FLOOR 8th. | 0107393 | | | | | | | | | |
| 47 | AUDIBLE | AUDIBLE_ABZ_FL8_1 FLOOR 8th. | 0107394 | | | | | | | | | |
| 48 | PULL | PULL_AMZ_8_04 FLOOR 8th. | 0107397 | | | | | | | | | |
| 49 | AUDIBLE | SPEAKER_ROOM814 FLOOR 8th. | 0107398 | | | | | | | | | |
| 50 | AUDIBLE | SPEAKER_ROOM815 FLOOR 8th. | 0107399 | | | | | | | | | |
| 51 | | | | | | | | | | | | |
| 52 | | | | | | | | | | | | |
| 53 | | | | | | | | | | | | |
| 54 | | | | | | | | | | | | |
| 55 | | | | | | | | | | | | |
| 56 | | | | | | | | | | | | |
| 57 | | | | | | | | | | | | |
| 58 | | | | | | | | | | | | |
| 59 | | | | | | | | | | | | |
| 60 | | | | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 8 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

| INSPECTION AND TEST REPORT FOR DEVICES | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 51 | AUDIBLE | SPEAKER_ROOM816 FLOOR 8th. | 0107400 | | | | | | | | | |
| 52 | AUDIBLE | SPEAKER_ROOM817 FLOOR 8th. | 0107401 | | | | | | | | | |
| 53 | AUDIBLE | SPEAKER_ROOM818 FLOOR 8th. | 0107402 | | | | | | | | | |
| 54 | AUDIBLE | SPEAKER_ROOM819 FLOOR 8th. | 0107403 | | | | | | | | | |
| 55 | AUDIBLE | SPEAKER_ROOM820 FLOOR 8th. | 0107404 | | | | | | | | | |
| 56 | AUDIBLE | SPEAKER_ROOM821 FLOOR 8th. | 0107405 | | | | | | | | | |
| 57 | AUDIBLE | SPEAKER_ROOM822 FLOOR 8th. | 0107406 | | | | | | | | | |
| 58 | PULL | PULL_AMZ_8_03 FLOOR 8th. | 0107407 | | | | | | | | | |
| 59 | AUDIBLE | SPEAKER_ROOM823 FLOOR 8th. | 0107408 | | | | | | | | | |
| 60 | AUDIBLE | SPEAKER_ROOM824 FLOOR 8th. | 0107409 | | | | | | | | | |
| 61 | AUDIBLE | SPEAKER_ROOM801 FLOOR 8th. | 0107410 | | | | | | | | | |
| 62 | PULL | PULL_AMZ_8_01 FLOOR 8th. | 0107411 | | | | | | | | | |
| 63 | AUDIBLE | SPEAKER_ROOM802 FLOOR 8th. | 0107412 | | | | | | | | | |
| 64 | AUDIBLE | SPEAKER_ROOM803 FLOOR 8th. | 0107413 | | | | | | | | | |
| 65 | AUDIBLE | SPEAKER_ROOM804 FLOOR 8th. | 0107414 | | | | | | | | | |
| 66 | AUDIBLE | SPEAKER_ROOM805 FLOOR 8th. | 0107415 | | | | | | | | | |
| 67 | AUDIBLE | SPEAKER_ROOM806 FLOOR 8th. | 0107416 | | | | | | | | | |
| 68 | AUDIBLE | SPEAKER_ROOM807 FLOOR 8th. | 0107417 | | | | | | | | | |
| 69 | AUDIBLE | SPEAKER_ROOM808 FLOOR 8th. | 0107418 | | | | | | | | | |
| 70 | AUDIBLE | SPEAKER_ROOM809 FLOOR 8th. | 0107419 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 9 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_OUT_FTB_9 FLOOR 09th. | 0108003 | | | | | | | | | |
| 2 | SMOKE | ADZ#9-39 FLOOR 9th. | 0108004 | | | | | | | | | |
| 3 | SMOKE | ADZ#915-14 FLOOR 9th. | 0108005 | | | | | | | | | |
| 4 | SMOKE | ADZ#916-15 FLOOR 9th. | 0108006 | | | | | | | | | |
| 5 | SMOKE | ADZ#917-16 FLOOR 9th. | 0108007 | | | | | | | | | |
| 6 | SMOKE | ADZ#918-17 FLOOR 9th. | 0108008 | | | | | | | | | |
| 7 | SMOKE | ADZ#9-29-33/3 FLOOR 9th. | 0108009 | | | | | | | | | |
| 8 | SMOKE | ADZ#919-18 FLOOR 9th. | 0108010 | | | | | | | | | |
| 9 | SMOKE | ADZ#920-19 FLOOR 9th. | 0108011 | | | | | | | | | |
| 10 | SMOKE | ADZ#9-29-33/2 FLOOR 9th. | 0108012 | | | | | | | | | |
| 11 | SMOKE | ADZ#921-20 FLOOR 9th. | 0108013 | | | | | | | | | |
| 12 | SMOKE | ADZ#922-21 FLOOR 9th. | 0108014 | | | | | | | | | |
| 13 | SMOKE | ADZ#9-29-33/1 FLOOR 9th. | 0108015 | | | | | | | | | |
| 14 | SMOKE | ADZ#923-22 FLOOR 9th. | 0108016 | | | | | | | | | |
| 15 | SMOKE | ADZ#9-38 FLOOR 9th. | 0108017 | | | | | | | | | |
| 16 | SMOKE | ADZ#924-23 FLOOR 9th. | 0108018 | | | | | | | | | |
| 17 | SMOKE | ADZ#902-02 FLOOR 9th. | 0108019 | | | | | | | | | |
| 18 | SMOKE | ADZ#903-03 FLOOR 9th. | 0108020 | | | | | | | | | |
| 19 | SMOKE | ADZ#9-24-28/1 FLOOR 9th. | 0108021 | | | | | | | | | |
| 20 | SMOKE | ADZ#904-04 FLOOR 9th. | 0108022 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 9 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#905-05 FLOOR 9th. | 0108023 | | | | | | | | | |
| 22 | SMOKE | ADZ#9-24-28/2 FLOOR 9th. | 0108024 | | | | | | | | | |
| 23 | SMOKE | ADZ#906-06 FLOOR 9th. | 0108025 | | | | | | | | | |
| 24 | SMOKE | ADZ#907-07 FLOOR 9th. | 0108026 | | | | | | | | | |
| 25 | SMOKE | ADZ#9-24-28/3 FLOOR 9th. | 0108027 | | | | | | | | | |
| 26 | SMOKE | ADZ#908-08 FLOOR 9th. | 0108028 | | | | | | | | | |
| 27 | SMOKE | ADZ#9-24-28/4 FLOOR 9th. | 0108029 | | | | | | | | | |
| 28 | SMOKE | ADZ#909-09 FLOOR 9th. | 0108030 | | | | | | | | | |
| 29 | SMOKE | ADZ#910-10 FLOOR 9th. | 0108031 | | | | | | | | | |
| 30 | SMOKE | ADZ#9-24-28/5 FLOOR 9th. | 0108032 | | | | | | | | | |
| 31 | SMOKE | ADZ#911-11 FLOOR 9th. | 0108033 | | | | | | | | | |
| 32 | SMOKE | ADZ#912-12 FLOOR 9th. | 0108034 | | | | | | | | | |
| 33 | SMOKE | ADZ#9-29-33/4 FLOOR 9th. | 0108035 | | | | | | | | | |
| 34 | SMOKE | ADZ#9-29-33/5 FLOOR 9th. | 0108036 | | | | | | | | | |
| 35 | SMOKE | ADZ#9-35 FLOOR 9th. | 0108069 | | | | | | | | | |
| 36 | SMOKE | ADZ#9-36 FLOOR 9th. | 0108070 | | | | | | | | | |
| 37 | SMOKE | ADZ#9-37 FLOOR 9th. | 0108071 | | | | | | | | | |
| 38 | SMOKE | ADZ#914-13 FLOOR 9th. | 0108074 | | | | | | | | | |
| 39 | SMOKE | ADZ#901-01 FLOOR 9th. | 0108075 | | | | | | | | | |
| 40 | SMOKE | ADZ#9-40 FLOOR 9th. | 0108080 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 9 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#9-34 FLOOR 9th. | 0108082 | | | | | | | | | |
| 42 | AUDIBLE | AUDIBLE_ASZ_1 FLOOR 9th. | 0108131 | | | | | | | | | |
| 43 | AUDIBLE | AUDIBLE_STROBE_1 FLOOR 9th. | 0108132 | | | | | | | | | |
| 44 | AUDIBLE | AUDIBLE_ABZ_1 FLOOR 9th. | 0108133 | | | | | | | | | |
| 45 | SUPERVISORY | SUPERVISORY_1 FLOOR 9th. | 0108134 | | | | | | | | | |
| 46 | WATERFLOW | WATERFLOW_1 FLOOR 9th. | 0108135 | | | | | | | | | |
| 47 | PULL | PULL_AMZ_9_04 FLOOR 9th. | 0108136 | | | | | | | | | |
| 48 | AUDIBLE | SPEAKER_ROOM914 FLOOR 9th. | 0108137 | | | | | | | | | |
| 49 | AUDIBLE | SPEAKER_ROOM915 FLOOR 9th. | 0108138 | | | | | | | | | |
| 50 | AUDIBLE | SPEAKER_ROOM916 FLOOR 9th. | 0108139 | | | | | | | | | |
| 51 | AUDIBLE | SPEAKER_ROOM917 FLOOR 9th. | 0108140 | | | | | | | | | |
| 52 | AUDIBLE | SPEAKER_ROOM918 FLOOR 9th. | 0108141 | | | | | | | | | |
| 53 | AUDIBLE | SPEAKER_ROOM919 FLOOR 9th. | 0108142 | | | | | | | | | |
| 54 | AUDIBLE | SPEAKER_ROOM920 FLOOR 9th. | 0108143 | | | | | | | | | |
| 55 | AUDIBLE | SPEAKER_ROOM921 FLOOR 9th. | 0108144 | | | | | | | | | |
| 56 | AUDIBLE | SPEAKER_ROOM922 FLOOR 9th. | 0108145 | | | | | | | | | |
| 57 | AUDIBLE | SPEAKER_ROOM923 FLOOR 9th. | 0108146 | | | | | | | | | |
| 58 | PULL | PULL_AMZ_9_03 FLOOR 9th. | 0108147 | | | | | | | | | |
| 59 | AUDIBLE | SPEAKER_ROOM924 FLOOR 9th. | 0108148 | | | | | | | | | |
| 60 | AUDIBLE | SPEAKER_ROOM901 FLOOR 9th. | 0108149 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 9 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 76 | AUDIBLE | STROBE_ROOM906 FLOOR 9th. | 0108192 | | | | | | | | | |
| 77 | | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | | | | | | | | | | | | |
| 81 | | | | | | | | | | | | |
| 82 | | | | | | | | | | | | |
| 83 | | | | | | | | | | | | |
| 84 | | | | | | | | | | | | |
| 85 | | | | | | | | | | | | |
| 86 | | | | | | | | | | | | |
| 87 | | | | | | | | | | | | |
| 88 | | | | | | | | | | | | |
| 89 | | | | | | | | | | | | |
| 90 | | | | | | | | | | | | |
| 91 | | | | | | | | | | | | |
| 92 | | | | | | | | | | | | |
| 93 | | | | | | | | | | | | |
| 94 | | | | | | | | | | | | |
| 95 | | | | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 10 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_10 FLOOR 10th. | 0108001 | | | | | | | | | |
| 2 | ISOLATOR | IM_IN_FTB_10 FLOOR 10th. | 0108002 | | | | | | | | | |
| 3 | SMOKE | ADZ#10-29-33/5 FLOOR 10th. | 0108037 | | | | | | | | | |
| 4 | SMOKE | ADZ#10-39 FLOOR 10th. | 0108038 | | | | | | | | | |
| 5 | SMOKE | ADZ#1015-14 FLOOR 10th. | 0108039 | | | | | | | | | |
| 6 | SMOKE | ADZ#1016-15 FLOOR 10th. | 0108040 | | | | | | | | | |
| 7 | SMOKE | ADZ#1017-16 FLOOR 10th. | 0108041 | | | | | | | | | |
| 8 | SMOKE | ADZ#1018-17 FLOOR 10th. | 0108042 | | | | | | | | | |
| 9 | SMOKE | ADZ#1019-18 FLOOR 10th. | 0108043 | | | | | | | | | |
| 10 | SMOKE | ADZ#10-29-33/3 FLOOR 10th. | 0108044 | | | | | | | | | |
| 11 | SMOKE | ADZ#1020-19 FLOOR 10th. | 0108045 | | | | | | | | | |
| 12 | SMOKE | ADZ#10-29-33/2 FLOOR 10th. | 0108046 | | | | | | | | | |
| 13 | SMOKE | ADZ#1021-20 FLOOR 10th. | 0108047 | | | | | | | | | |
| 14 | SMOKE | ADZ#1022-21 FLOOR 10th. | 0108048 | | | | | | | | | |
| 15 | SMOKE | ADZ#10-29-33/1 FLOOR 10th. | 0108049 | | | | | | | | | |
| 16 | SMOKE | ADZ#1023-22 FLOOR 10th. | 0108050 | | | | | | | | | |
| 17 | SMOKE | ADZ#1024-23 FLOOR 10th. | 0108051 | | | | | | | | | |
| 18 | SMOKE | ADZ#1001-01 FLOOR 10th. | 0108052 | | | | | | | | | |
| 19 | SMOKE | ADZ#1002-02 FLOOR 10th. | 0108053 | | | | | | | | | |
| 20 | SMOKE | ADZ#1003-03 FLOOR 10th. | 0108054 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 10 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#10-24-28/1 FLOOR 10th. | 0108055 | | | | | | | | | |
| 22 | SMOKE | ADZ#1004-04 FLOOR 10th. | 0108056 | | | | | | | | | |
| 23 | SMOKE | ADZ#1005-05 FLOOR 10th. | 0108057 | | | | | | | | | |
| 24 | SMOKE | ADZ#10-24-28/2 FLOOR 10th. | 0108058 | | | | | | | | | |
| 25 | SMOKE | ADZ#1006-06 FLOOR 10th. | 0108059 | | | | | | | | | |
| 26 | SMOKE | ADZ#1007-07 FLOOR 10th. | 0108060 | | | | | | | | | |
| 27 | SMOKE | ADZ#10-24-28/3 FLOOR 10th. | 0108061 | | | | | | | | | |
| 28 | SMOKE | ADZ#1008-08 FLOOR 10th. | 0108062 | | | | | | | | | |
| 29 | SMOKE | ADZ#1009-09 FLOOR 10th. | 0108063 | | | | | | | | | |
| 30 | SMOKE | ADZ#1010-10 FLOOR 10th. | 0108064 | | | | | | | | | |
| 31 | SMOKE | ADZ#10-24-28/5 FLOOR 10th. | 0108065 | | | | | | | | | |
| 32 | SMOKE | ADZ#1011-11 FLOOR 10th. | 0108066 | | | | | | | | | |
| 33 | SMOKE | ADZ#10-29-33/4 FLOOR 10th. | 0108067 | | | | | | | | | |
| 34 | SMOKE | ADZ#10-37 FLOOR 10th. | 0108068 | | | | | | | | | |
| 35 | SMOKE | ADZ#10-35 FLOOR 10th. | 0108072 | | | | | | | | | |
| 36 | SMOKE | ADZ#10-36 FLOOR 10th. | 0108073 | | | | | | | | | |
| 37 | SMOKE | ADZ#1014-13 FLOOR 10th. | 0108076 | | | | | | | | | |
| 38 | SMOKE | ADZ#10-24-28/4 FLOOR 10th. | 0108077 | | | | | | | | | |
| 39 | SMOKE | ADZ#1012-12 FLOOR 10th. | 0108078 | | | | | | | | | |
| 40 | SMOKE | ADZ#10-38 FLOOR 10th. | 0108079 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 10 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#10-40 FLOOR 10th. | 0108081 | | | | | | | | | |
| 42 | SMOKE | ADZ#10-34 FLOOR 10th. | 0108083 | | | | | | | | | |
| 43 | AUDIBLE | AUDIBLE_ASZ_1 FLOOR 10th. | 0108126 | | | | | | | | | |
| 44 | AUDIBLE | AUDIBLE_STROBE_1 FLOOR 10th. | 0108127 | | | | | | | | | |
| 45 | AUDIBLE | AUDIBLE_ABZ1_1 FLOOR 10th. | 0108128 | | | | | | | | | |
| 46 | SUPERVISORY | SUPERVISORY_1 FLOOR 10th. | 0108129 | | | | | | | | | |
| 47 | WATERFLOW | WATERFLOW_1 FLOOR 10th. | 0108130 | | | | | | | | | |
| 48 | PULL | PULL_AMZ_10_04 FLOOR 10th. | 0108165 | | | | | | | | | |
| 49 | AUDIBLE | SPEAKER_ROOM1014 FLOOR 10th. | 0108166 | | | | | | | | | |
| 50 | AUDIBLE | SPEAKER_ROOM1015 FLOOR 10th. | 0108167 | | | | | | | | | |
| 51 | AUDIBLE | SPEAKER_ROOM1016 FLOOR 10th. | 1018168 | | | | | | | | | |
| 52 | AUDIBLE | SPEAKER_ROOM1017 FLOOR 10th. | 1018169 | | | | | | | | | |
| 53 | AUDIBLE | SPEAKER_ROOM1018 FLOOR 10th. | 1018170 | | | | | | | | | |
| 54 | AUDIBLE | SPEAKER_ROOM1019 FLOOR 10th. | 1018171 | | | | | | | | | |
| 55 | AUDIBLE | SPEAKER_ROOM1020 FLOOR 10th. | 1018172 | | | | | | | | | |
| 56 | AUDIBLE | SPEAKER_ROOM1021 FLOOR 10th. | 1018173 | | | | | | | | | |
| 57 | AUDIBLE | SPEAKER_ROOM1022 FLOOR 10th. | 1018174 | | | | | | | | | |
| 58 | PULL | PULL_AMZ_10_03 FLOOR 10th. | 1018175 | | | | | | | | | |
| 59 | AUDIBLE | SPEAKER_ROOM1023 FLOOR 10th. | 1018176 | | | | | | | | | |
| 60 | AUDIBLE | SPEAKER_ROOM1024 FLOOR 10th. | 1018177 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 10 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | AUDIBLE | SPEAKER_ROOM1001 FLOOR 10th. | | | | | | | | | | |
| 62 | AUDIBLE | SPEAKER_ROOM1002 FLOOR 10th. | | | | | | | | | | |
| 63 | AUDIBLE | SPEAKER_ROOM1003 FLOOR 10th. | | | | | | | | | | |
| 64 | PULL | PULL_AMZ_10_01 FLOOR 10th. | | | | | | | | | | |
| 65 | AUDIBLE | SPEAKER_ROOM1004 FLOOR 10th. | | | | | | | | | | |
| 66 | AUDIBLE | SPEAKER_ROOM1005 FLOOR 10th. | | | | | | | | | | |
| 67 | AUDIBLE | SPEAKER_ROOM1006 FLOOR 10th. | | | | | | | | | | |
| 68 | AUDIBLE | SPEAKER_ROOM1007 FLOOR 10th. | | | | | | | | | | |
| 69 | AUDIBLE | SPEAKER_ROOM1008 FLOOR 10th. | | | | | | | | | | |
| 70 | AUDIBLE | SPEAKER_ROOM1009 FLOOR 10th. | | | | | | | | | | |
| 71 | AUDIBLE | SPEAKER_ROOM1010 FLOOR 10th. | | | | | | | | | | |
| 72 | AUDIBLE | SPEAKER_ROOM1011 FLOOR 10th. | | | | | | | | | | |
| 73 | AUDIBLE | SPEAKER_ROOM1012 FLOOR 10th. | | | | | | | | | | |
| 74 | PULL | PULL_AMZ_10_02 FLOOR 10th. | | | | | | | | | | |
| 75 | AUDIBLE | STROBE_ROOM1006 FLOOR 10th. | | | | | | | | | | |
| 76 | | | | | | | | | | | | |
| 77 | | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 11 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_11 | 0203001 | | | | | | | | | |
| 2 | SMOKE | ADZ#11-30-34/5 FLOOR 11th. | 0203004 | | | | | | | | | |
| 3 | SMOKE | ADZ#1115-14 FLOOR 11th. | 0203005 | | | | | | | | | |
| 4 | SMOKE | ADZ#1116-15 FLOOR 11th. | 0203006 | | | | | | | | | |
| 5 | SMOKE | ADZ#1117-16 FLOOR 11th. | 0203007 | | | | | | | | | |
| 6 | SMOKE | ADZ#1118-17 FLOOR 11th. | 0203008 | | | | | | | | | |
| 7 | SMOKE | ADZ#1119-18 FLOOR 11th. | 0203009 | | | | | | | | | |
| 8 | SMOKE | ADZ#11-30-34/3 FLOOR 11th. | 0203010 | | | | | | | | | |
| 9 | SMOKE | ADZ#1120-19 FLOOR 11th. | 0203011 | | | | | | | | | |
| 10 | SMOKE | ADZ#11-30-34/2 FLOOR 11th. | 0203012 | | | | | | | | | |
| 11 | SMOKE | ADZ#1121-20 FLOOR 11th. | 0203013 | | | | | | | | | |
| 12 | SMOKE | ADZ#1122-21 FLOOR 11th. | 0203014 | | | | | | | | | |
| 13 | SMOKE | ADZ#11-39 FLOOR 11th. | 0203015 | | | | | | | | | |
| 14 | SMOKE | ADZ#11-30-34/1 FLOOR 11th. | 0203016 | | | | | | | | | |
| 15 | SMOKE | ADZ#1123-22 FLOOR 11th. | 0203017 | | | | | | | | | |
| 16 | SMOKE | ADZ#1124-23 FLOOR 11th. | 0203018 | | | | | | | | | |
| 17 | SMOKE | ADZ#1101-01 FLOOR 11th. | 0203019 | | | | | | | | | |
| 18 | SMOKE | ADZ#1102-02 FLOOR 11th. | 0203020 | | | | | | | | | |
| 19 | SMOKE | ADZ#1103-03 FLOOR 11th. | 0203021 | | | | | | | | | |
| 20 | SMOKE | ADZ#11-25-29/1 FLOOR 11th. | 0203022 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 11 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#1104-04 FLOOR 11th. | 0203023 | | | | | | | | | |
| 22 | SMOKE | ADZ#1105-05 FLOOR 11th. | 0203024 | | | | | | | | | |
| 23 | SMOKE | ADZ#11-25-29/2 FLOOR 11th. | 0203025 | | | | | | | | | |
| 24 | SMOKE | ADZ#1106-06 FLOOR 11th. | 0203026 | | | | | | | | | |
| 25 | SMOKE | ADZ#1107-07 FLOOR 11th. | 0203027 | | | | | | | | | |
| 26 | SMOKE | ADZ#11-25-29/3 FLOOR 11th. | 0203028 | | | | | | | | | |
| 27 | SMOKE | ADZ#11-25-29/4 FLOOR 11th. | 0203029 | | | | | | | | | |
| 28 | SMOKE | ADZ#1109-09 FLOOR 11th. | 0203030 | | | | | | | | | |
| 29 | SMOKE | ADZ#1110-10 FLOOR 11th. | 0203031 | | | | | | | | | |
| 30 | SMOKE | ADZ#11-25-29/5 FLOOR 11th. | 0203032 | | | | | | | | | |
| 31 | SMOKE | ADZ#1111-11 FLOOR 11th. | 0203033 | | | | | | | | | |
| 32 | SMOKE | ADZ#11-35 FLOOR 11th. | 0203034 | | | | | | | | | |
| 33 | SMOKE | ADZ#11-30-34/4 FLOOR 11th. | 0203035 | | | | | | | | | |
| 34 | SMOKE | ADZ#11-38 FLOOR 11th. | 0203036 | | | | | | | | | |
| 35 | SMOKE | ADZ#11-41 FLOOR 11th. | 0203037 | | | | | | | | | |
| 36 | SMOKE | ADZ#11-40 FLOOR 11th. | 0203071 | | | | | | | | | |
| 37 | SMOKE | ADZ#1114-14 FLOOR 11th. | 0203072 | | | | | | | | | |
| 38 | SMOKE | ADZ#1108-08 FLOOR 11th. | 0203073 | | | | | | | | | |
| 39 | SMOKE | ADZ#1112-12 FLOOR 11th. | 0203074 | | | | | | | | | |
| 40 | SMOKE | ADZ#1113-13 FLOOR 11th. | 0203075 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 11 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#11-36 FLOOR 11th. | 0203076 | | | | | | | | | |
| 42 | SMOKE | ADZ#11-37 FLOOR 11th. | 0203077 | | | | | | | | | |
| 43 | SUPERVISORY | SUPERVISORY_1 FLOOR 11th. | 0203126 | | | | | | | | | |
| 44 | WATERFLOW | WATERFLOW_1 FLOOR 11th. | 0203127 | | | | | | | | | |
| 45 | AUDIBLE | AUDIBLE_ABZ_FL11_1 | 0203128 | | | | | | | | | |
| 46 | AUDIBLE | AUDIBLE_STROBE_FL11_1 | 0203129 | | | | | | | | | |
| 47 | AUDIBLE | AUDIBLE_ASZ_FL11_1 | 0203130 | | | | | | | | | |
| 48 | AUDIBLE | SPEAKER_ROOM1114 FLOOR 11th. | 0203137 | | | | | | | | | |
| 49 | AUDIBLE | SPEAKER_ROOM1115 FLOOR 11th. | 0203138 | | | | | | | | | |
| 50 | AUDIBLE | SPEAKER_ROOM1116 FLOOR 11th. | 0203139 | | | | | | | | | |
| 51 | AUDIBLE | SPEAKER_ROOM1117 FLOOR 11th. | 0203140 | | | | | | | | | |
| 52 | AUDIBLE | SPEAKER_ROOM1118 FLOOR 11th. | 0203141 | | | | | | | | | |
| 53 | AUDIBLE | SPEAKER_ROOM1119 FLOOR 11th. | 0203142 | | | | | | | | | |
| 54 | AUDIBLE | SPEAKER_ROOM1120 FLOOR 11th. | 0203143 | | | | | | | | | |
| 55 | AUDIBLE | SPEAKER_ROOM1121 FLOOR 11th. | 0203144 | | | | | | | | | |
| 56 | AUDIBLE | SPEAKER_ROOM1122 FLOOR 11th. | 0203145 | | | | | | | | | |
| 57 | PULL | AMZ#11-03 FLOOR 11th. | 0203146 | | | | | | | | | |
| 58 | AUDIBLE | SPEAKER_ROOM1123 FLOOR 11th. | 0203147 | | | | | | | | | |
| 59 | AUDIBLE | SPEAKER_ROOM1124 FLOOR 11th. | 0203148 | | | | | | | | | |
| 60 | AUDIBLE | SPEAKER_ROOM1101 FLOOR 11th. | 0203149 | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : ..... Location : 11 th Floor

Service : ☐ Yearly ..... ☐ Other .....

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | AUDIBLE | SPEAKER_ROOM1102 FLOOR 11th. | 0203150 | | | | | | | | | |
| 62 | AUDIBLE | SPEAKER_ROOM1103 FLOOR 11th. | 0203151 | | | | | | | | | |
| 63 | PULL | AMZ#11-01 FLOOR 11th. | 0203152 | | | | | | | | | |
| 64 | AUDIBLE | SPEAKER_ROOM1104 FLOOR 11th. | 0203153 | | | | | | | | | |
| 65 | AUDIBLE | SPEAKER_ROOM1105 FLOOR 11th. | 0203154 | | | | | | | | | |
| 66 | AUDIBLE | SPEAKER_ROOM1106 FLOOR 11th. | 0203155 | | | | | | | | | |
| 67 | AUDIBLE | SPEAKER_ROOM1107 FLOOR 11th. | 0203156 | | | | | | | | | |
| 68 | AUDIBLE | SPEAKER_ROOM1108 FLOOR 11th. | 0203157 | | | | | | | | | |
| 69 | AUDIBLE | SPEAKER_ROOM1109 FLOOR 11th. | 0203158 | | | | | | | | | |
| 70 | AUDIBLE | SPEAKER_ROOM1110 FLOOR 11th. | 0203159 | | | | | | | | | |
| 71 | AUDIBLE | SPEAKER_ROOM1111 FLOOR 11th. | 0203160 | | | | | | | | | |
| 72 | AUDIBLE | SPEAKER_ROOM1112 FLOOR 11th. | 0203161 | | | | | | | | | |
| 73 | AUDIBLE | SPEAKER_ROOM1113 FLOOR 11th. | 0203162 | | | | | | | | | |
| 74 | PULL | AMZ#11-02 FLOOR 11th. | 0203163 | | | | | | | | | |
| 75 | AUDIBLE | STROBE_ROOM1106 FLOOR 11th. | 0203191 | | | | | | | | | |
| 76 | | | | | | | | | | | | |
| 77 | | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | | | | | | | | | | | | |

COMMENT : .....

.....

.....

.....

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko. Location : 12 th Floor

Service : ☑ Yearly 1/2. ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_12 | 0203002 | ✓ | | | | ✓ | ✓ | - | - | |
| 2 | ISOLATOR | IM_OUT_FTB_12 | 0203003 | ✓ | | | | ✓ | ✓ | - | - | |
| 3 | SMOKE | ADZ#12-39 FLOOR 12th. | 0203038 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 4 | SMOKE | ADZ#1214-13 FLOOR 12th. | 0203039 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 5 | SMOKE | ADZ#12-29-33/5 FLOOR 12th. | 0203040 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 6 | SMOKE | ADZ#1216-15 FLOOR 12th. | 0203041 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 7 | SMOKE | ADZ#1217-16 FLOOR 12th. | 0203042 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 8 | SMOKE | ADZ#1218-17 FLOOR 12th. | 0203043 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 9 | SMOKE | ADZ#12-29-33/3 FLOOR 12th. | 0203044 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 10 | SMOKE | ADZ#1219-18 FLOOR 12th. | 0203045 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 11 | SMOKE | ADZ#1220-19 FLOOR 12th. | 0203046 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 12 | SMOKE | ADZ#12-29-33/2 FLOOR 12th. | 0203047 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 13 | SMOKE | ADZ#1221-20 FLOOR 12th. | 0203048 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 14 | SMOKE | ADZ#1222-21 FLOOR 12th. | 0203049 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 15 | SMOKE | ADZ#12-38 FLOOR 12th. | 0203050 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 16 | SMOKE | ADZ#12-29-33/1 FLOOR 12th. | 0203051 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 17 | SMOKE | ADZ#1223-22 FLOOR 12th. | 0203052 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 18 | SMOKE | ADZ#1202-02 FLOOR 12th. | 0203053 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 19 | SMOKE | ADZ#1203-03 FLOOR 12th. | 0203054 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 20 | SMOKE | ADZ#12-24-28/1 FLOOR 12th. | 0203055 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko. Location : 12 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#1204-04 FLOOR 12th. | 0203056 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 22 | SMOKE | ADZ#1205-05 FLOOR 12th. | 0203057 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 23 | SMOKE | ADZ#12-24-28/2 FLOOR 12th. | 0203058 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 24 | SMOKE | ADZ#1206-06 FLOOR 12th. | 0203059 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 25 | SMOKE | ADZ#1207-07 FLOOR 12th. | 0203060 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 26 | SMOKE | ADZ#12-24-28/3 FLOOR 12th. | 0203061 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 27 | SMOKE | ADZ#1208-08 FLOOR 12th. | 0203062 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 28 | SMOKE | ADZ#1212-12 FLOOR 12th. | 0203063 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 29 | SMOKE | ADZ#1211-11 FLOOR 12th. | 0203064 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 30 | SMOKE | ADZ#1210-10 FLOOR 12th. | 0203065 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 31 | SMOKE | ADZ#12-24-28/4 FLOOR 12th. | 0203066 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 32 | SMOKE | ADZ#1209-09 FLOOR 12th. | 0203067 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 33 | SMOKE | ADZ#12-34 FLOOR 12th. | 0203068 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 34 | SMOKE | ADZ#12-29-33/4 FLOOR 12th. | 0203069 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 35 | SMOKE | ADZ#12-37 FLOOR 12th. | 0203070 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 36 | SMOKE | ADZ#1215-14 FLOOR 12th. | 0203078 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 37 | SMOKE | ADZ#1224-23 FLOOR 12th. | 0203079 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 38 | SMOKE | ADZ#1201-01 FLOOR 12th. | 0203080 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 39 | SMOKE | ADZ#12-24-28/5 FLOOR 12th. | 0203081 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 40 | SMOKE | ADZ#12-35 FLOOR 12th. | 0203082 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | อุปกรณ์อยู่ระดับต่ำ แต่ไม่ชำรุด |

COMMENT : Item-40. อุปกรณ์อยู่ระดับต่ำ แต่ไม่ชำรุด มีการป้องกันฝุ่นที่ดี ดำ

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 12 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#12-36 FLOOR 12th. | 0203083 | / | | | | / | / | / | / | -อุปกรณ์อยู่บนเสา เข้าไม่ได้ |
| 42 | SMOKE | ADZ#12-40 FLOOR 12th. | 0203084 | / | | | | / | / | / | / | |
| 43 | SUPERVISORY | SUPERVISORY_1 FLOOR 12th. | 0203131 | / | | | | / | / | - | - | |
| 44 | WATERFLOW | WATERFLOW_1 FLOOR 12th. | 0203132 | / | | | | / | / | - | - | |
| 45 | AUDIBLE | AUDIBLE_ABZ_FL12_1 | 0203133 | / | | | | / | / | - | - | |
| 46 | AUDIBLE | AUDIBLE_STROBE_FL12_1 | 0203134 | / | | | | / | / | - | - | |
| 47 | AUDIBLE | AUDIBLE_ASZ_FL12_1 | 0203135 | / | | | | / | / | - | - | |
| 48 | PULL | AMZ#12-04 FLOOR 12th. | 0203164 | / | | | | / | / | / | / | |
| 49 | AUDIBLE | SPEAKER_ROOM1214 FLOOR 12th. | 0203165 | / | | | | / | / | - | - | |
| 50 | AUDIBLE | SPEAKER_ROOM1215 FLOOR 12th. | 0203166 | / | | | | / | / | - | - | |
| 51 | AUDIBLE | SPEAKER_ROOM1216 FLOOR 12th. | 0203167 | / | | | | / | / | - | - | |
| 52 | AUDIBLE | SPEAKER_ROOM1217 FLOOR 12th. | 0203168 | / | | | | / | / | - | - | |
| 53 | AUDIBLE | SPEAKER_ROOM1218 FLOOR 12th. | 0203169 | / | | | | / | / | - | - | |
| 54 | AUDIBLE | SPEAKER_ROOM1219 FLOOR 12th. | 0203170 | / | | | | / | / | - | - | |
| 55 | AUDIBLE | SPEAKER_ROOM1220 FLOOR 12th. | 0203171 | / | | | | / | / | - | - | |
| 56 | AUDIBLE | SPEAKER_ROOM1221 FLOOR 12th. | 0203172 | / | | | | / | / | - | - | |
| 57 | AUDIBLE | SPEAKER_ROOM1222 FLOOR 12th. | 0203173 | / | | | | / | / | - | - | |
| 58 | PULL | AMZ#12-03 FLOOR 12th. | 0203174 | / | | | | / | / | / | / | |
| 59 | AUDIBLE | SPEAKER_ROOM1223 FLOOR 12th. | 0203175 | / | | | | / | / | - | - | |
| 60 | AUDIBLE | SPEAKER_ROOM1224 FLOOR 12th. | 0203176 | / | | | | / | / | - | - | |

COMMENT : Item-41 อุปกรณ์อยู่บนเสา เข้าไม่ได้ ต้องมีการปรับปรุงพื้นที่ ต่อไป

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 12 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | AUDIBLE | SPEAKER_ROOM1201 FLOOR 12th. | 0203177 | ✓ | | | | ✓ | ✓ | - | - | |
| 62 | AUDIBLE | SPEAKER_ROOM1202 FLOOR 12th. | 0203178 | ✓ | | | | ✓ | ✓ | - | - | |
| 63 | AUDIBLE | SPEAKER_ROOM1203 FLOOR 12th. | 0203179 | ✓ | | | | ✓ | ✓ | - | - | |
| 64 | PULL | AMZ#12-01 FLOOR 12th. | 0203180 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 65 | AUDIBLE | SPEAKER_ROOM1204 FLOOR 12th. | 0203181 | ✓ | | | | ✓ | ✓ | - | - | |
| 66 | AUDIBLE | SPEAKER_ROOM1205 FLOOR 12th. | 0203182 | ✓ | | | | ✓ | ✓ | - | - | |
| 67 | AUDIBLE | SPEAKER_ROOM1206 FLOOR 12th. | 0203183 | ✓ | | | | ✓ | ✓ | - | - | |
| 68 | AUDIBLE | SPEAKER_ROOM1207 FLOOR 12th. | 0203184 | ✓ | | | | ✓ | ✓ | - | - | |
| 69 | AUDIBLE | SPEAKER_ROOM1208 FLOOR 12th. | 0203185 | ✓ | | | | ✓ | ✓ | - | - | |
| 70 | PULL | AMZ#12-02 FLOOR 12th. | 0203186 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 71 | AUDIBLE | SPEAKER_ROOM1212 FLOOR 12th. | 0203187 | ✓ | | | | ✓ | ✓ | - | - | |
| 72 | AUDIBLE | SPEAKER_ROOM1211 FLOOR 12th. | 0203188 | ✓ | | | | ✓ | ✓ | - | - | |
| 73 | AUDIBLE | SPEAKER_ROOM1210 FLOOR 12th. | 0203189 | ✓ | | | | ✓ | ✓ | - | - | |
| 74 | AUDIBLE | SPEAKER_ROOM1209 FLOOR 12th. | 0203190 | ✓ | | | | ✓ | ✓ | - | - | |
| 75 | | | | | | | | | | | | |
| 76 | | | | | | | | | | | | |
| 77 | | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 14 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_14 | 0203251 | ✓ | | | | ✓ | ✓ | - | - | |
| 2 | SMOKE | ADZ#1420-19 FLOOR 14th. | 0203263 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 3 | SMOKE | ADZ#1406-06 FLOOR 14th. | 0203277 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 4 | SMOKE | ADZ#1407-07 FLOOR 14th. | 0203278 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 5 | SMOKE | ADZ#1408-08 FLOOR 14th. | 0203279 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 6 | SMOKE | ADZ#1410-10 FLOOR 14th. | 0203280 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 7 | SMOKE | ADZ#14-24-28/5 FLOOR 14th. | 0203281 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 8 | SMOKE | ADZ#1411-11 FLOOR 14th. | 0203282 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 9 | SMOKE | ADZ#1412-12 FLOOR 14th. | 0203283 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 10 | SMOKE | ADZ#14-35 FLOOR 14th. | 0203284 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 11 | SMOKE | ADZ#14-36 FLOOR 14th. | 0203285 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 12 | SMOKE | ADZ#14-34 FLOOR 14th. | 0203286 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 13 | SMOKE | ADZ#14-37 FLOOR 14th. | 0203287 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 14 | SMOKE | ADZ#14-24-28/4 FLOOR 14th. | 0203288 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 15 | SMOKE | ADZ#1414-13 FLOOR 14th. | 0203290 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 16 | SMOKE | ADZ#1415-14 FLOOR 14th. | 0203291 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 17 | SMOKE | ADZ#14-29-33/5 FLOOR 14th. | 0203292 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 18 | SMOKE | ADZ#1416-15 FLOOR 14th. | 0203293 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 19 | SMOKE | ADZ#14-29-33/4 FLOOR 14th. | 0203294 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 20 | SMOKE | ADZ#1417-16 FLOOR 14th. | 0203295 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko. Location : 14 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#1418-17 FLOOR 14th. | 0203296 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 22 | SMOKE | ADZ#14-29-33/3 FLOOR 14th. | 0203297 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 23 | SMOKE | ADZ#1419-18 FLOOR 14th. | 0203298 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 24 | SMOKE | ADZ#14-29-33/2 FLOOR 14th. | 0203300 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 25 | SMOKE | ADZ#1421-20 FLOOR 14th. | 0203301 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 26 | SMOKE | ADZ#1422-21 FLOOR 14th. | 0203302 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 27 | SMOKE | ADZ#14-29-33/1 FLOOR 14th. | 0203303 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 28 | SMOKE | ADZ#1423-22 FLOOR 14th. | 0203304 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 29 | SMOKE | ADZ#1424-23 FLOOR 14th. | 0203307 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 30 | SMOKE | ADZ#1401-01 FLOOR 14th. | 0203309 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 31 | SMOKE | ADZ#1402-02 FLOOR 14th. | 0203310 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 32 | SMOKE | ADZ#1403-03 FLOOR 14th. | 0203311 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 33 | SMOKE | ADZ#14-24-28/1 FLOOR 14th. | 0203312 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 34 | SMOKE | ADZ#1404-04 FLOOR 14th. | 0203313 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 35 | SMOKE | ADZ#1405-05 FLOOR 14th. | 0203314 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 36 | SMOKE | ADZ#14-24-28/2 FLOOR 14th. | 0203315 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 37 | SMOKE | ADZ#14-39 FLOOR 14th. | 0203326 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 38 | SMOKE | ADZ#14-38 FLOOR 14th. | 0203327 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 39 | SMOKE | ADZ#14-24-28/3 FLOOR 14th. | 0203328 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 40 | SMOKE | ADZ#1409-09 FLOOR 14th. | 0203329 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

Confide technology

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 14 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#14-40 FLOOR 14th. | 0203330 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 42 | SUPERVISORY | SUPERVISORY_1 FLOOR 14th. | 0203376 | ✓ | | | | ✓ | ✓ | - | - | |
| 43 | WATERFLOW | WATERFLOW_1 FLOOR 14th. | 0203377 | ✓ | | | | ✓ | ✓ | - | - | |
| 44 | AUDIBLE | AUDIBLE_ABZ_FL14_1 | 0203378 | ✓ | | | | ✓ | ✓ | - | - | |
| 45 | AUDIBLE | AUDIBLE_STROBE_FL14_1 | 0203379 | ✓ | | | | ✓ | ✓ | - | - | |
| 46 | AUDIBLE | AUDIBLE_ASZ_FL14_1 | 0203380 | ✓ | | | | ✓ | ✓ | - | - | |
| 47 | MONITOR | MONITOR_FL14_BOOSTER | 0203386 | ✓ | | | | ✓ | ✓ | - | - | |
| 48 | AUDIBLE | AZ_FL14_POWERBELL | 0203387 | ✓ | | | | ✓ | ✓ | - | - | |
| 49 | AUDIBLE | SPEAKER_ROOM1409 FLOOR 14th. | 0203407 | ✓ | | | | ✓ | ✓ | - | - | |
| 50 | AUDIBLE | SPEAKER_ROOM1410 FLOOR 14th. | 0203408 | ✓ | | | | ✓ | ✓ | - | - | |
| 51 | AUDIBLE | SPEAKER_ROOM1411 FLOOR 14th. | 0203409 | ✓ | | | | ✓ | ✓ | - | - | |
| 52 | AUDIBLE | SPEAKER_ROOM1412 FLOOR 14th. | 0203410 | ✓ | | | | ✓ | ✓ | - | - | |
| 53 | PULL | AMZ#14-02 FLOOR 14th. | 0203411 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 54 | AUDIBLE | SPEAKER_ROOM1416 FLOOR 14th. | 0203413 | ✓ | | | | ✓ | ✓ | - | - | |
| 55 | AUDIBLE | SPEAKER_ROOM1417 FLOOR 14th. | 0203414 | ✓ | | | | ✓ | ✓ | - | - | |
| 56 | AUDIBLE | SPEAKER_ROOM1418 FLOOR 14th. | 0203415 | ✓ | | | | ✓ | ✓ | - | - | |
| 57 | AUDIBLE | SPEAKER_ROOM1419 FLOOR 14th. | 0203416 | ✓ | | | | ✓ | ✓ | - | - | |
| 58 | AUDIBLE | SPEAKER_ROOM1420 FLOOR 14th. | 0203417 | ✓ | | | | ✓ | ✓ | - | - | |
| 59 | AUDIBLE | SPEAKER_ROOM1421 FLOOR 14th. | 0203418 | ✓ | | | | ✓ | ✓ | - | - | |
| 60 | AUDIBLE | SPEAKER_ROOM1422 FLOOR 14th. | 0203419 | ✓ | | | | ✓ | ✓ | - | - | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 14 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | PULL | AMZ#14-03 FLOOR 14th. | 0203420 | / | | | | / | / | / | / | |
| 62 | AUDIBLE | SPEAKER_ROOM1423 FLOOR 14th. | 0203421 | / | | | | / | / | - | - | |
| 63 | AUDIBLE | SPEAKER_ROOM1424 FLOOR 14th. | 0203423 | / | | | | / | / | - | - | |
| 64 | AUDIBLE | SPEAKER_ROOM1401 FLOOR 14th. | 0203424 | / | | | | / | / | - | - | |
| 65 | AUDIBLE | SPEAKER_ROOM1402 FLOOR 14th. | 0203425 | / | | | | / | / | - | - | |
| 66 | AUDIBLE | SPEAKER_ROOM1403 FLOOR 14th. | 0203426 | / | | | | / | / | - | - | |
| 67 | PULL | AMZ#14-01 FLOOR 14th. | 0203427 | / | | | | / | / | / | / | |
| 68 | AUDIBLE | SPEAKER_ROOM1404 FLOOR 14th. | 0203429 | / | | | | / | / | - | - | |
| 69 | AUDIBLE | SPEAKER_ROOM1405 FLOOR 14th. | 0203430 | / | | | | / | / | - | - | |
| 70 | AUDIBLE | SPEAKER_ROOM1406 FLOOR 14th. | 0203431 | / | | | | / | / | - | - | |
| 71 | AUDIBLE | SPEAKER_ROOM1407 FLOOR 14th. | 0203432 | / | | | | / | / | - | - | |
| 72 | AUDIBLE | SPEAKER_ROOM1408 FLOOR 14th. | 0203433 | / | | | | / | / | - | - | |
| 73 | PULL | AMZ#14-04 FLOOR 14th. | 0203438 | / | | | | / | / | / | / | |
| 74 | AUDIBLE | SPEAKER_ROOM1414 FLOOR 14th. | 0203439 | / | | | | / | / | - | - | |
| 75 | AUDIBLE | SPEAKER_ROOM1415 FLOOR 14th. | 0203440 | / | | | | / | / | - | - | |
| 76 | | | | | | | | | | | | |
| 77 | | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko. Location : 15 th Floor

Service : ☑ Yearly 1/2. ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_15 | 0203252 | ✓ | | | | ✓ | ✓ | - | - | |
| 2 | ISOLATOR | IM_OUT_FTB_15 | 0203253 | ✓ | | | | ✓ | ✓ | - | - | |
| 3 | SMOKE | ADZ#1515-14 FLOOR 15th. | 0203254 | | | | | | | | | |
| 4 | SMOKE | ADZ#15-29-33/5 FLOOR 15th. | 0203255 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 5 | SMOKE | ADZ#1516-15 FLOOR 15th. | 0203256 | | | | | | | | | |
| 6 | SMOKE | ADZ#15-29-33/4 FLOOR 15th. | 0203257 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 7 | SMOKE | ADZ#1517-16 FLOOR 15th. | 0203258 | | | | | | | | | |
| 8 | SMOKE | ADZ#1518-17 FLOOR 15th. | 0203259 | | | | | | | | | |
| 9 | SMOKE | ADZ#1519-18 FLOOR 15th. | 0203260 | | | | | | | | | |
| 10 | SMOKE | ADZ#15-29-33/3 FLOOR 15th. | 0203261 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 11 | SMOKE | ADZ#1520-19 FLOOR 15th. | 0203262 | | | | | | | | | |
| 12 | SMOKE | ADZ#1521-20 FLOOR 15th. | 0203264 | | | | | | | | | |
| 13 | SMOKE | ADZ#1522-21 FLOOR 15th. | 0203265 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 14 | SMOKE | ADZ#15-38 FLOOR 15th. | 0203266 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 15 | SMOKE | ADZ#15-29-33/1 FLOOR 15th. | 0203267 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 16 | SMOKE | ADZ#1523-22 FLOOR 15th. | 0203268 | | | | | | | | | |
| 17 | SMOKE | ADZ#1503-03 FLOOR 15th. | 0203269 | | | | | | | | | |
| 18 | SMOKE | ADZ#1504-04 FLOOR 15th. | 0203270 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 19 | SMOKE | ADZ#1505-05 FLOOR 15th. | 0203271 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 20 | SMOKE | ADZ#15-24-28/2 FLOOR 15th. | 0203272 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko. Location : 15 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#1506-06 FLOOR 15th. | 0203273 | | | | | | | | | |
| 22 | SMOKE | ADZ#1507-07 FLOOR 15th. | 0203274 | / | | | | / | / | / | / | |
| 23 | SMOKE | ADZ#15-24-28/3 FLOOR 15th. | 0203275 | / | | | | / | / | / | / | |
| 24 | SMOKE | ADZ#1508-08 FLOOR 15th. | 0203276 | / | / | | | / | / | / | / | |
| 25 | SMOKE | ADZ#1514-13 FLOOR 15th. | 0203289 | | | | | | | | | |
| 26 | SMOKE | ADZ#15-29-23/2 FLOOR 15th. | 0203299 | / | | | | / | / | / | / | |
| 27 | SMOKE | ADZ#1501-01 FLOOR 15th. | 0203305 | | | | | | | | | |
| 28 | SMOKE | ADZ#1502-02 FLOOR 15th. | 0203306 | | | | | | | | | |
| 29 | SMOKE | ADZ#15-24-28/1 FLOOR 15th. | 0203308 | / | | | | / | / | / | / | |
| 30 | SMOKE | ADZ#15-34 FLOOR 15th. | 0203316 | / | | | | / | / | / | / | |
| 31 | SMOKE | ADZ#15-36 FLOOR 15th. | 0203317 | / | | | | / | / | / | / | |
| 32 | SMOKE | ADZ#15-35 FLOOR 15th. | 0203318 | / | | | | / | / | / | / | |
| 33 | SMOKE | ADZ#15-37 FLOOR 15th. | 0203319 | / | | | | / | / | / | / | |
| 34 | SMOKE | ADZ#15-24-28/4 FLOOR 15th. | 0203320 | / | | | | / | / | / | / | |
| 35 | SMOKE | ADZ#1509-09 FLOOR 15th. | 0203321 | / | | | | / | / | / | / | |
| 36 | SMOKE | ADZ#1510-10 FLOOR 15th. | 0203322 | | | | | | | | | |
| 37 | SMOKE | ADZ#15-24-28/5 FLOOR 15th. | 0203323 | / | | | | / | / | / | / | |
| 38 | SMOKE | ADZ#1511-11 FLOOR 15th. | 0203324 | | | | | | | | | |
| 39 | SMOKE | ADZ#1512-12 FLOOR 15th. | 0203325 | | | | | | | | | |
| 40 | SMOKE | ADZ#15-39 FLOOR 15th. | 0203331 | / | | | | / | / | / | / | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko . Location : 15 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#1524-23 FLOOR 15th. | 0203332 | / | | | | / | / | / | / | |
| 42 | SMOKE | ADZ#15-40 FLOOR 15th. | 0203333 | / | | | | / | / | / | / | |
| 43 | SUPERVISORY | SUPERVISORY_1 FLOOR 15th. | 0203381 | / | | | | / | / | - | - | |
| 44 | WATERFLOW | WATERFLOW_1 FLOOR 15th. | 0203382 | / | | | | / | / | - | - | |
| 45 | AUDIBLE | AUDIBLE_ABZ_FL15_1 | 0203383 | / | | | | / | / | - | - | |
| 46 | AUDIBLE | AUDIBLE_STROBE_FL15_1 | 0203384 | / | | | | / | / | - | - | |
| 47 | AUDIBLE | AUDIBLE_ASZ_FL15_1 | 0203385 | / | | | | / | / | - | - | |
| 48 | AUDIBLE | SPEAKER_ROOM1514 FLOOR 15th. | 0203388 | | | | | | | | | |
| 49 | AUDIBLE | SPEAKER_ROOM1515 FLOOR 15th. | 0203389 | | | | | | | | | |
| 50 | AUDIBLE | SPEAKER_ROOM1516 FLOOR 15th. | 0203390 | | | | | | | | | |
| 51 | AUDIBLE | SPEAKER_ROOM1517 FLOOR 15th. | 0203391 | | | | | | | | | |
| 52 | AUDIBLE | SPEAKER_ROOM1518 FLOOR 15th. | 0203392 | | | | | | | | | |
| 53 | AUDIBLE | SPEAKER_ROOM1519 FLOOR 15th. | 0203393 | | | | | | | | | |
| 54 | AUDIBLE | SPEAKER_ROOM1520 FLOOR 15th. | 0203394 | | | | | | | | | |
| 55 | AUDIBLE | SPEAKER_ROOM1521 FLOOR 15th. | 0203395 | | | | | | | | | |
| 56 | AUDIBLE | SPEAKER_ROOM1522 FLOOR 15th. | 0203396 | / | | | | / | / | - | - | |
| 57 | AUDIBLE | SPEAKER_ROOM1523 FLOOR 15th. | 0203397 | | | | | | | | | |
| 58 | AUDIBLE | SPEAKER_ROOM1524 FLOOR 15th. | 0203398 | | | | | | | | | |
| 59 | AUDIBLE | SPEAKER_ROOM1501 FLOOR 15th. | 0203399 | | | | | | | | | |
| 60 | AUDIBLE | SPEAKER_ROOM1502 FLOOR 15th. | 0203400 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko. Location : 15 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | AUDIBLE | SPEAKER_ROOM1503 FLOOR 15th. | 0203401 | | | | | | | | | |
| 62 | AUDIBLE | SPEAKER_ROOM1504 FLOOR 15th. | 0203402 | / | | | | / | / | - | - | |
| 63 | AUDIBLE | SPEAKER_ROOM1505 FLOOR 15th. | 0203403 | / | | | | / | / | - | - | |
| 64 | AUDIBLE | SPEAKER_ROOM1506 FLOOR 15th. | 0203404 | | | | | | | | | |
| 65 | AUDIBLE | SPEAKER_ROOM1507 FLOOR 15th. | 0203405 | / | | | | / | / | - | - | |
| 66 | AUDIBLE | SPEAKER_ROOM1508 FLOOR 15th. | 0203406 | / | | | | / | / | - | - | |
| 67 | PULL | AMZ#15-04 FLOOR 15th. | 0203412 | / | | | | / | / | / | / | |
| 68 | PULL | AMZ#15-03 FLOOR 15th. | 0203422 | / | | | | / | / | / | / | |
| 69 | PULL | AMZ#15-01 FLOOR 15th. | 0203428 | / | | | | / | / | / | / | |
| 70 | AUDIBLE | SPEAKER_ROOM1509 FLOOR 15th. | 0203434 | / | | | | / | / | - | - | |
| 71 | AUDIBLE | SPEAKER_ROOM1510 FLOOR 15th. | 0203435 | | | | | | | | | |
| 72 | AUDIBLE | SPEAKER_ROOM1511 FLOOR 15th. | 0203436 | | | | | | | | | |
| 73 | PULL | AMZ#15-02 FLOOR 15th. | 0203437 | / | | | | / | / | / | / | |
| 74 | AUDIBLE | SPEAKER_ROOM1512 FLOOR 15th. | 0203441 | | | | | | | | | |
| 75 | | | | | | | | | | | | |
| 76 | | | | | | | | | | | | |
| 77 | | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68 | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko. Location : 16 th Floor

Service : ☑ Yearly 1/2. ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_16 | 0204001 | ✓ | | | | ✓ | ✓ | - | - | |
| 2 | SMOKE | ADZ#16-29-33/5 FLOOR 16th. | 0204004 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 3 | SMOKE | ADZ#16-39 FLOOR 16th. | 0204005 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 4 | SMOKE | ADZ#1614-13 FLOOR 16th. | 0204006 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 5 | SMOKE | ADZ#1615-14 FLOOR 16th. | 0204007 | | | | | | | | | |
| 6 | SMOKE | ADZ#1616-15 FLOOR 16th. | 0204008 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 7 | SMOKE | ADZ#1617-16 FLOOR 16th. | 0204009 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 8 | SMOKE | ADZ#1618-17 FLOOR 16th. | 0204010 | | | | | | | | | |
| 9 | SMOKE | ADZ#16-29-33/3 FLOOR 16th. | 0204011 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 10 | SMOKE | ADZ#1619-18 FLOOR 16th. | 0204012 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 11 | SMOKE | ADZ#1620-19 FLOOR 16th. | 0204013 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 12 | SMOKE | ADZ#16-29-33/2 FLOOR 16th. | 0204014 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 13 | SMOKE | ADZ#1621-20 FLOOR 16th. | 0204015 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 14 | SMOKE | ADZ#1622-21 FLOOR 16th. | 0204016 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 15 | SMOKE | ADZ#16-38 FLOOR 16th. | 0204017 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 16 | SMOKE | ADZ#16-29-33/1 FLOOR 16th. | 0204018 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 17 | SMOKE | ADZ#1623-22 FLOOR 16th. | 0204019 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 18 | SMOKE | ADZ#1624-23 FLOOR 16th. | 0204020 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 19 | SMOKE | ADZ#1601-01 FLOOR 16th. | 0204021 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 20 | SMOKE | ADZ#1602-02 FLOOR 16th. | 0204022 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68 | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 16 th Floor

Service : ☑ Yearly 1/2. ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#1603-03 FLOOR 16th. | 0204023 | | | | | | | | | |
| 22 | SMOKE | ADZ#16-24-28/1 FLOOR 16th. | 0204024 | / | | | | / | / | / | / | |
| 23 | SMOKE | ADZ#1604-04 FLOOR 16th. | 0204025 | | | | | | | | | |
| 24 | SMOKE | ADZ#1605-05 FLOOR 16th. | 0204026 | | | | | | | | | |
| 25 | SMOKE | ADZ#16-24-28/2 FLOOR 16th. | 0204027 | / | | | | / | / | / | / | |
| 26 | SMOKE | ADZ#1606-06 FLOOR 16th. | 0204028 | | | | | | | | | |
| 27 | SMOKE | ADZ#1607-07 FLOOR 16th. | 0204029 | | | | | | | | | |
| 28 | SMOKE | ADZ#16-24-28/3 FLOOR 16th. | 0204030 | / | | | | / | / | / | / | |
| 29 | SMOKE | ADZ#1608-08 FLOOR 16th. | 0204031 | | | | | | | | | |
| 30 | SMOKE | ADZ#16-24-28/4 FLOOR 16th. | 0204032 | / | | | | / | / | / | / | |
| 31 | SMOKE | ADZ#1609-09 FLOOR 16th. | 0204033 | | | | | | | | | |
| 32 | SMOKE | ADZ#1610-10 FLOOR 16th. | 0204034 | / | | | | / | / | / | / | |
| 33 | SMOKE | ADZ#16-24-28/5 FLOOR 16th. | 0204035 | / | | | | / | / | / | / | |
| 34 | SMOKE | ADZ#1611-11 FLOOR 16th. | 0204036 | | | | | | | | | |
| 35 | SMOKE | ADZ#1612-12 FLOOR 16th. | 0204037 | / | | | | / | / | / | / | |
| 36 | SMOKE | ADZ#1613-13 FLOOR 16th. | 0204038 | | | | | | | | | |
| 37 | SMOKE | ADZ#16-35 FLOOR 16th. | 0204039 | / | | | | / | / | / | / | |
| 38 | SMOKE | ADZ#16-34 FLOOR 16th. | 0204040 | / | | | | / | / | / | / | |
| 39 | SMOKE | ADZ#16-36 FLOOR 16th. | 0204041 | / | | | | / | / | / | / | |
| 40 | SMOKE | ADZ#16-29-33/4 FLOOR 16th. | 0204042 | / | | | | / | / | / | / | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68 | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko. Location : 16 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#16-37 FLOOR 16th. | 0204043 | / | | | | / | / | / | / | |
| 42 | SMOKE | ADZ#16-40 FLOOR 16th. | 0204079 | / | | | | / | / | / | / | |
| 43 | SUPERVISORY | SUPERVISORY_1 FLOOR 16th. | 0204126 | / | | | | / | / | - | - | |
| 44 | WATERFLOW | WATERFLOW_1 FLOOR 16th. | 0204127 | / | | | | / | / | - | - | |
| 45 | AUDIBLE | AUDIBLE_ABZ_FL16_1 | 0204128 | / | | | | / | / | - | - | |
| 46 | AUDIBLE | AUDIBLE_STROBE_FL16_1 | 0204129 | / | | | | / | / | - | - | |
| 47 | AUDIBLE | AUDIBLE_ASZ_FL16_1 | 0204130 | / | | | | / | / | - | - | |
| 48 | MONITOR | MONITOR_FL16_BOOSTER | 0204136 | / | | | | / | / | - | - | |
| 49 | AUDIBLE | AZ_FL16_POWERBELL | 0204137 | / | | | | / | / | - | - | |
| 50 | PULL | AMZ#16-04 FLOOR 16th. | 0204138 | / | | | | / | / | / | / | |
| 51 | AUDIBLE | SPEAKER_ROOM1614 FLOOR 16th. | 0204139 | / | | | | / | / | - | - | |
| 52 | AUDIBLE | SPEAKER_ROOM1615 FLOOR 16th. | 0204140 | | | | | | | | | |
| 53 | AUDIBLE | SPEAKER_ROOM1616 FLOOR 16th. | 0204141 | / | | | | / | / | - | - | |
| 54 | AUDIBLE | SPEAKER_ROOM1617 FLOOR 16th. | 0204142 | / | | | | / | / | - | - | |
| 55 | AUDIBLE | SPEAKER_ROOM1618 FLOOR 16th. | 0204143 | | | | | | | | | |
| 56 | AUDIBLE | SPEAKER_ROOM1619 FLOOR 16th. | 0204144 | / | | | | / | / | - | - | |
| 57 | AUDIBLE | SPEAKER_ROOM1620 FLOOR 16th. | 0204145 | / | | | | / | / | - | - | |
| 58 | AUDIBLE | SPEAKER_ROOM1621 FLOOR 16th. | 0204146 | / | | | | / | / | - | - | |
| 59 | AUDIBLE | SPEAKER_ROOM1622 FLOOR 16th. | 0204147 | / | | | | / | / | - | - | |
| 60 | PULL | AMZ#16-03 FLOOR 16th. | 0204148 | / | | | | / | / | / | / | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko  Location : 16 th Floor

Service : ☑ Yearly 1/2  ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | AUDIBLE | SPEAKER_ROOM1623 FLOOR 16th. | 0204149 | / | | | | / | / | – | – | |
| 62 | AUDIBLE | SPEAKER_ROOM1624 FLOOR 16th. | 0204150 | / | | | | / | / | – | – | |
| 63 | AUDIBLE | SPEAKER_ROOM1601 FLOOR 16th. | 0204151 | / | | | | / | / | – | – | |
| 64 | AUDIBLE | SPEAKER_ROOM1602 FLOOR 16th. | 0204152 | | | | | | | | | |
| 65 | AUDIBLE | SPEAKER_ROOM1603 FLOOR 16th. | 0204153 | | | | | | | | | |
| 66 | PULL | AMZ#16-01 FLOOR 16th. | 0204154 | / | | | | / | / | / | / | |
| 67 | AUDIBLE | SPEAKER_ROOM1604 FLOOR 16th. | 0204155 | | | | | | | | | |
| 68 | AUDIBLE | SPEAKER_ROOM1605 FLOOR 16th. | 0204156 | | | | | | | | | |
| 69 | AUDIBLE | SPEAKER_ROOM1606 FLOOR 16th. | 0204157 | | | | | | | | | |
| 70 | AUDIBLE | SPEAKER_ROOM1607 FLOOR 16th. | 0204158 | | | | | | | | | |
| 71 | AUDIBLE | SPEAKER_ROOM1608 FLOOR 16th. | 0204159 | | | | | | | | | |
| 72 | AUDIBLE | SPEAKER_ROOM1609 FLOOR 16th. | 0204160 | | | | | | | | | |
| 73 | AUDIBLE | SPEAKER_ROOM1610 FLOOR 16th. | 0204161 | / | | | | / | / | – | – | |
| 74 | AUDIBLE | SPEAKER_ROOM1611 FLOOR 16th. | 0204162 | | | | | | | | | |
| 75 | AUDIBLE | SPEAKER_ROOM1612 FLOOR 16th. | 0204163 | / | | | | / | / | – | – | |
| 76 | AUDIBLE | SPEAKER_ROOM1613 FLOOR 16th. | 0204164 | | | | | | | | | |
| 77 | PULL | AMZ#16-02 FLOOR 16th. | 0204165 | / | | | | / | / | / | / | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 17 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_17 | 0204002 | / | | | | / | / | - | - | |
| 2 | ISOLATOR | IM_OUT_FTB_17 | 0204003 | / | | | | / | / | - | - | |
| 3 | SMOKE | ADZ#17-29-33/5 FLOOR 17th. | 0204044 | / | | | | / | / | / | / | |
| 4 | SMOKE | ADZ#17-39 FLOOR 17th. | 0204045 | / | | | | / | / | / | / | |
| 5 | SMOKE | ADZ#1715-14 FLOOR 17th. | 0204046 | / | | | | / | / | / | / | |
| 6 | SMOKE | ADZ#1716-15 FLOOR 17th. | 0204047 | | | | | | | | | |
| 7 | SMOKE | ADZ#1717-16 FLOOR 17th. | 0204048 | | | | | | | | | |
| 8 | SMOKE | ADZ#1718-17 FLOOR 17th. | 0204049 | | | | | | | | | |
| 9 | SMOKE | ADZ#17-29-33/3 FLOOR 17th. | 0204050 | / | | | | / | / | / | / | |
| 10 | SMOKE | ADZ#1719-18 FLOOR 17th. | 0204051 | / | | | | / | / | / | / | |
| 11 | SMOKE | ADZ#1720-19 FLOOR 17th. | 0204052 | | | | | | | | | |
| 12 | SMOKE | ADZ#17-29-33/2 FLOOR 17th. | 0204053 | / | | | | / | / | / | / | |
| 13 | SMOKE | ADZ#1721-20 FLOOR 17th. | 0204054 | | | | | | | | | |
| 14 | SMOKE | ADZ#1722-21 FLOOR 17th. | 0204055 | | | | | | | | | |
| 15 | SMOKE | ADZ#17-29-33/1 FLOOR 17th. | 0204056 | / | | | | / | / | / | / | |
| 16 | SMOKE | ADZ#17-38 FLOOR 17th. | 0204057 | | | | | | | | | |
| 17 | SMOKE | ADZ#1723-22 FLOOR 17th. | 0204058 | | | | | | | | | |
| 18 | SMOKE | ADZ#1724-23 FLOOR 17th. | 0204059 | | | | | | | | | |
| 19 | SMOKE | ADZ#1701-01 FLOOR 17th. | 0204060 | | | | | | | | | |
| 20 | SMOKE | ADZ#1702-02 FLOOR 17th. | 0204061 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 17 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#1703-03 FLOOR 17th. | 0204062 | | | | | | | | | |
| 22 | SMOKE | ADZ#17-24-28/1 FLOOR 17th. | 0204063 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 23 | SMOKE | ADZ#1704-04 FLOOR 17th. | 0204064 | | | | | | | | | |
| 24 | SMOKE | ADZ#1705-05 FLOOR 17th. | 0204065 | | | | | | | | | |
| 25 | SMOKE | ADZ#17-24-28/2 FLOOR 17th. | 0204066 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 26 | SMOKE | ADZ#1706-06 FLOOR 17th. | 0204067 | | | | | | | | | |
| 27 | SMOKE | ADZ#1707-07 FLOOR 17th. | 0204068 | | | | | | | | | |
| 28 | SMOKE | ADZ#17-24-28/3 FLOOR 17th. | 0204069 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 29 | SMOKE | ADZ#1708-08 FLOOR 17th. | 0204070 | | | | | | | | | |
| 30 | SMOKE | ADZ#17-24-28/4 FLOOR 17th. | 0204071 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 31 | SMOKE | ADZ#1710-10 FLOOR 17th. | 0204072 | | | | | | | | | |
| 32 | SMOKE | ADZ#17-24-28/5 FLOOR 17th. | 0204073 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 33 | SMOKE | ADZ#1711-11 FLOOR 17th. | 0204074 | | | | | | | | | |
| 34 | SMOKE | ADZ#17-34 FLOOR 17th. | 0204075 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 35 | SMOKE | ADZ#17-29-33/4 FLOOR 17th. | 0204076 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 36 | SMOKE | ADZ#17-37 FLOOR 17th. | 0204077 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 37 | SMOKE | ADZ#17-40 FLOOR 17th. | 0204078 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 38 | SMOKE | ADZ#1709-09 FLOOR 17th. | 0204080 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 39 | SMOKE | ADZ#17-35 FLOOR 17th. | 0204081 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 40 | SMOKE | ADZ#17-36 FLOOR 17th. | 0204082 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko  Location : 17 th Floor

Service : ☑ Yearly 1/2  ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#1714-13 FLOOR 17th. | 0204083 | / | | | | / | / | / | / | |
| 42 | SMOKE | ADZ#1712-12 FLOOR 17th. | 0204084 | | | | | | | | | |
| 43 | SUPERVISORY | SUPERVISORY_1 FLOOR 17th. | 0204131 | / | | | | / | / | - | - | |
| 44 | WATERFLOW | WATERFLOW_1 FLOOR 17th. | 0204132 | / | | | | / | / | - | - | |
| 45 | AUDIBLE | AUDIBLE_ABZ_FL17_1 | 0204133 | / | | | | / | / | - | - | |
| 46 | AUDIBLE | AUDIBLE_STROBE_FL17_1 | 0204134 | / | | | | / | / | - | - | |
| 47 | AUDIBLE | AUDIBLE_ASZ_FL17_1 | 0204135 | / | | | | / | / | - | - | |
| 48 | AUDIBLE | SPEAKER_ROOM1714 FLOOR 17th. | 0204166 | / | | | | / | / | - | - | |
| 49 | AUDIBLE | SPEAKER_ROOM1715 FLOOR 17th. | 0204167 | / | | | | / | / | - | - | |
| 50 | AUDIBLE | SPEAKER_ROOM1716 FLOOR 17th. | 0204168 | | | | | | | | | |
| 51 | AUDIBLE | SPEAKER_ROOM1717 FLOOR 17th. | 0204169 | | | | | | | | | |
| 52 | AUDIBLE | SPEAKER_ROOM1718 FLOOR 17th. | 0204170 | | | | | | | | | |
| 53 | AUDIBLE | SPEAKER_ROOM1719 FLOOR 17th. | 0204171 | / | | | | / | / | - | - | |
| 54 | AUDIBLE | SPEAKER_ROOM1720 FLOOR 17th. | 0204172 | | | | | | | | | |
| 55 | AUDIBLE | SPEAKER_ROOM1721 FLOOR 17th. | 0204173 | | | | | | | | | |
| 56 | AUDIBLE | SPEAKER_ROOM1722 FLOOR 17th. | 0204174 | | | | | | | | | |
| 57 | AUDIBLE | SPEAKER_ROOM1723 FLOOR 17th. | 0204175 | | | | | | | | | |
| 58 | AUDIBLE | SPEAKER_ROOM1724 FLOOR 17th. | 0204176 | | | | | | | | | |
| 59 | AUDIBLE | SPEAKER_ROOM1701 FLOOR 17th. | 0204177 | | | | | | | | | |
| 60 | AUDIBLE | SPEAKER_ROOM1702 FLOOR 17th. | 0204178 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68 | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 17 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | AUDIBLE | SPEAKER_ROOM1703 FLOOR 17th. | 0204179 | | | | | | | | | |
| 62 | AUDIBLE | SPEAKER_ROOM1704 FLOOR 17th. | 0204180 | | | | | | | | | |
| 63 | AUDIBLE | SPEAKER_ROOM1705 FLOOR 17th. | 0204181 | | | | | | | | | |
| 64 | AUDIBLE | SPEAKER_ROOM1706 FLOOR 17th. | 0204182 | | | | | | | | | |
| 65 | AUDIBLE | SPEAKER_ROOM1707 FLOOR 17th. | 0204183 | | | | | | | | | |
| 66 | AUDIBLE | SPEAKER_ROOM1708 FLOOR 17th. | 0204184 | | | | | | | | | |
| 67 | AUDIBLE | SPEAKER_ROOM1709 FLOOR 17th. | 0204185 | / | | | | / | / | - | - | |
| 68 | AUDIBLE | SPEAKER_ROOM1710 FLOOR 17th. | 0204186 | | | | | | | | | |
| 69 | AUDIBLE | SPEAKER_ROOM1711 FLOOR 17th. | 0204187 | | | | | | | | | |
| 70 | AUDIBLE | SPEAKER_ROOM1712 FLOOR 17th. | 0204188 | | | | | | | | | |
| 71 | PULL | AMZ#17-04 FLOOR 17th. | 0204189 | / | | | | / | / | / | / | |
| 72 | PULL | AMZ#17-03 FLOOR 17th. | 0204190 | / | | | | / | / | / | / | |
| 73 | PULL | AMZ#17-01 FLOOR 17th. | 0204191 | / | | | | / | / | / | / | |
| 74 | PULL | AMZ#17-02 FLOOR 17th. | 0204192 | / | | | | / | / | / | / | |
| 75 | | | | | | | | | | | | |
| 76 | | | | | | | | | | | | |
| 77 | | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 22/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 18 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_18 | 0204251 | ✓ | | | | ✓ | ✓ | - | - | |
| 2 | SMOKE | ADZ#18-39 FLOOR 18th. | 0204294 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 3 | SMOKE | ADZ#1814-13 FLOOR 18th. | 0204295 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 4 | SMOKE | ADZ#1815-14 FLOOR 18th. | 0204296 | | | | | | | | | |
| 5 | SMOKE | ADZ#1816-15 FLOOR 18th. | 0204297 | | | | | | | | | |
| 6 | SMOKE | ADZ#1817-16 FLOOR 18th. | 0204298 | | | | | | | | | |
| 7 | SMOKE | ADZ#1818-17 FLOOR 18th. | 0204299 | | | | | | | | | |
| 8 | SMOKE | ADZ#18-29-33/3 FLOOR 18th. | 0204300 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 9 | SMOKE | ADZ#1819-18 FLOOR 18th. | 0204301 | | | | | | | | | |
| 10 | SMOKE | ADZ#18-29-33/2 FLOOR 18th. | 0204302 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 11 | SMOKE | ADZ#1820-19 FLOOR 18th. | 0204303 | | | | | | | | | |
| 12 | SMOKE | ADZ#1821-20 FLOOR 18th. | 0204304 | | | | | | | | | |
| 13 | SMOKE | ADZ#1822-21 FLOOR 18th. | 0204305 | | | | | | | | | |
| 14 | SMOKE | ADZ#18-38 FLOOR 18th. | 0204306 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 15 | SMOKE | ADZ#18-29-33/1 FLOOR 18th. | 0204307 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 16 | SMOKE | ADZ#1823-22 FLOOR 18th. | 0204308 | | | | | | | | | |
| 17 | SMOKE | ADZ#1824-23 FLOOR 18th. | 0204309 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 18 | SMOKE | ADZ#1801-01 FLOOR 18th. | 0204310 | | | | | | | | | |
| 19 | SMOKE | ADZ#1802-02 FLOOR 18th. | 0204311 | | | | | | | | | |
| 20 | SMOKE | ADZ#1803-03 FLOOR 18th. | 0204312 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 18 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#18-24-26/1 FLOOR 18th. | 0204313 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 22 | SMOKE | ADZ#1804-04 FLOOR 18th. | 0204314 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 23 | SMOKE | ADZ#1805-05 FLOOR 18th. | 0204315 | | | | | | | | | |
| 24 | SMOKE | ADZ#18-24-26/2 FLOOR 18th. | 0204316 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 25 | SMOKE | ADZ#1806-06 FLOOR 18th. | 0204317 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 26 | SMOKE | ADZ#18-24-26/3 FLOOR 18th. | 0204318 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 27 | SMOKE | ADZ#1807-01 FLOOR 18th. | 0204319 | | | | | | | | | |
| 28 | SMOKE | ADZ#1808-01 FLOOR 18th. | 0204320 | | | | | | | | | |
| 29 | SMOKE | ADZ#18-24-26/4 FLOOR 18th. | 0204321 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 30 | SMOKE | ADZ#1809-01 FLOOR 18th. | 0204322 | | | | | | | | | |
| 31 | SMOKE | ADZ#1810-10 FLOOR 18th. | 0204323 | | | | | | | | | |
| 32 | SMOKE | ADZ#18-24-26/5 FLOOR 18th. | 0204324 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 33 | SMOKE | ADZ#1811-11 FLOOR 18th. | 0204325 | | | | | | | | | |
| 34 | SMOKE | ADZ#1812-12 FLOOR 18th. | 0204326 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 35 | SMOKE | ADZ#18-35 FLOOR 18th. | 0204327 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 36 | SMOKE | ADZ#18-34 FLOOR 18th. | 0204328 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 37 | SMOKE | ADZ#18-36 FLOOR 18th. | 0204329 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 38 | SMOKE | ADZ#18-37 FLOOR 18th. | 0204330 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 39 | SMOKE | ADZ#18-29-33/4 FLOOR 18th. | 0204331 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 40 | SMOKE | ADZ#18-29-33/5 FLOOR 18th. | 0204332 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 24/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 18 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#18-40 FLOOR 18th. | 0204333 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 42 | SUPERVISORY | SUPERVISORY_1 FLOOR 18th. | 0204376 | ✓ | | | | ✓ | ✓ | - | - | |
| 43 | WATERFLOW | WATERFLOW_1 FLOOR 18th. | 0204377 | ✓ | | | | ✓ | ✓ | - | - | |
| 44 | AUDIBLE | AUDIBLE_ABZ_FL18_1 | 0204378 | ✓ | | | | ✓ | ✓ | - | - | |
| 45 | AUDIBLE | AUDIBLE_STROBE_FL18_1 | 0204379 | ✓ | | | | ✓ | ✓ | - | - | |
| 46 | AUDIBLE | AUDIBLE_ASZ_FL18_1 | 0204380 | ✓ | | | | ✓ | ✓ | - | - | |
| 47 | PULL | AMZ#18-04 FLOOR 18th. | 0204415 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 48 | AUDIBLE | SPEAKER_ROOM1814 FLOOR 18th. | 0204416 | ✓ | | | | ✓ | ✓ | - | - | |
| 49 | AUDIBLE | SPEAKER_ROOM1815 FLOOR 18th. | 0204417 | | | | | | | | | |
| 50 | AUDIBLE | SPEAKER_ROOM1816 FLOOR 18th. | 0204418 | | | | | | | | | |
| 51 | AUDIBLE | SPEAKER_ROOM1817 FLOOR 18th. | 0204419 | | | | | | | | | |
| 52 | AUDIBLE | SPEAKER_ROOM1818 FLOOR 18th. | 0204420 | | | | | | | | | |
| 53 | AUDIBLE | SPEAKER_ROOM1819 FLOOR 18th. | 0204421 | | | | | | | | | |
| 54 | AUDIBLE | SPEAKER_ROOM1820 FLOOR 18th. | 0204422 | | | | | | | | | |
| 55 | AUDIBLE | SPEAKER_ROOM1821 FLOOR 18th. | 0204423 | | | | | | | | | |
| 56 | AUDIBLE | SPEAKER_ROOM1822 FLOOR 18th. | 0204424 | | | | | | | | | |
| 57 | AUDIBLE | SPEAKER_ROOM1823 FLOOR 18th. | 0204425 | | | | | | | | | |
| 58 | AUDIBLE | SPEAKER_ROOM1824 FLOOR 18th. | 0204426 | ✓ | | | | ✓ | ✓ | - | - | |
| 59 | AUDIBLE | SPEAKER_ROOM1801 FLOOR 18th. | 0204427 | | | | | | | | | |
| 60 | AUDIBLE | SPEAKER_ROOM1802 FLOOR 18th. | 0204428 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko . Location : 18 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | AUDIBLE | SPEAKER_ROOM1803 FLOOR 18th. | 0204429 | | | | | | | | | |
| 62 | PULL | AMZ#18-01 FLOOR 18th. | 0204430 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 63 | AUDIBLE | SPEAKER_ROOM1804 FLOOR 18th. | 0204431 | ✓ | | | | ✓ | ✓ | - | - | |
| 64 | AUDIBLE | SPEAKER_ROOM1805 FLOOR 18th. | 0204432 | | | | | | | | | |
| 65 | AUDIBLE | SPEAKER_ROOM1806 FLOOR 18th. | 0204433 | ✓ | | | | ✓ | ✓ | - | - | |
| 66 | AUDIBLE | SPEAKER_ROOM1807 FLOOR 18th. | 0204434 | | | | | | | | | |
| 67 | AUDIBLE | SPEAKER_ROOM1808 FLOOR 18th. | 0204435 | | | | | | | | | |
| 68 | AUDIBLE | SPEAKER_ROOM1809 FLOOR 18th. | 0204436 | | | | | | | | | |
| 69 | AUDIBLE | SPEAKER_ROOM1810 FLOOR 18th. | 0204437 | | | | | | | | | |
| 70 | AUDIBLE | SPEAKER_ROOM1811 FLOOR 18th. | 0204438 | | | | | | | | | |
| 71 | PULL | AMZ#18-02 FLOOR 18th. | 0204439 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 72 | AUDIBLE | SPEAKER_ROOM1812 FLOOR 18th. | 0204440 | ✓ | | | | ✓ | ✓ | - | - | |
| 73 | PULL | AMZ#18-03 FLOOR 18th. | 0204441 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 74 | MONITOR | MONITOR_FL18_BOOSTER | 0204386 | | | | | | | | | |
| 75 | AUDIBLE | AZ_FL18_POWERBELL | 0204387 | | | | | | | | | |
| 76 | | | | | | | | | | | | |
| 77 | | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68 | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 19 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_19 | 0204252 | | | | | | | | | |
| 2 | ISOLATOR | IM_OUT_FTB_19 | 0204253 | | | | | | | | | |
| 3 | SMOKE | ADZ#19-39 FLOOR 19th. | 0204254 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 4 | SMOKE | ADZ#1914-13 FLOOR 19th. | 0204255 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 5 | SMOKE | ADZ#1915-14 FLOOR 19th. | 0204256 | | | | | | | | | |
| 6 | SMOKE | ADZ#1916-15 FLOOR 19th. | 0204257 | | | | | | | | | |
| 7 | SMOKE | ADZ#1917-16 FLOOR 19th. | 0204258 | | | | | | | | | |
| 8 | SMOKE | ADZ#1918-17 FLOOR 19th. | 0204259 | | | | | | | | | |
| 9 | SMOKE | ADZ#19-29-33/3 FLOOR 19th. | 0204260 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 10 | SMOKE | ADZ#1919-18 FLOOR 19th. | 0204261 | | | | | | | | | |
| 11 | SMOKE | ADZ#1920-19 FLOOR 19th. | 0204262 | | | | | | | | | |
| 12 | SMOKE | ADZ#19-29-33/2 FLOOR 19th. | 0204263 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 13 | SMOKE | ADZ#1921-20 FLOOR 19th. | 0204264 | | | | | | | | | |
| 14 | SMOKE | ADZ#1922-21 FLOOR 19th. | 0204265 | | | | | | | | | |
| 15 | SMOKE | ADZ#19-38 FLOOR 19th. | 0204266 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 16 | SMOKE | ADZ#19-29-33/1 FLOOR 19th. | 0204267 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 17 | SMOKE | ADZ#1923-22 FLOOR 19th. | 0204268 | | | | | | | | | |
| 18 | SMOKE | ADZ#1924-23 FLOOR 19th. | 0204269 | | | | | | | | | |
| 19 | SMOKE | ADZ#1901-01 FLOOR 19th. | 0204270 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 20 | SMOKE | ADZ#1902-02 FLOOR 19th. | 0204271 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 19 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#1903-03 FLOOR 19th. | 0204272 | / | | | | / | / | / | / | |
| 22 | SMOKE | ADZ#19-24-28/1 FLOOR 19th. | 0204273 | / | | | | / | / | / | / | |
| 23 | SMOKE | ADZ#1904-04 FLOOR 19th. | 0204274 | | | | | | | | | |
| 24 | SMOKE | ADZ#1905-05 FLOOR 19th. | 0204275 | / | | | | / | / | / | / | |
| 25 | SMOKE | ADZ#19-24-28/2 FLOOR 19th. | 0204276 | / | | | | / | / | / | / | |
| 26 | SMOKE | ADZ#1906-06 FLOOR 19th. | 0204277 | / | | | | / | / | / | / | |
| 27 | SMOKE | ADZ#19-24-28/3 FLOOR 19th. | 0204278 | / | | | | / | / | / | / | |
| 28 | SMOKE | ADZ#1907-07 FLOOR 19th. | 0204279 | / | | | | / | / | / | / | |
| 29 | SMOKE | ADZ#1908-08 FLOOR 19th. | 0204280 | / | | | | / | / | / | / | |
| 30 | SMOKE | ADZ#19-24-28/4 FLOOR 19th. | 0204281 | / | | | | / | / | / | / | |
| 31 | SMOKE | ADZ#1909-09 FLOOR 19th. | 0204282 | | | | | | | | | |
| 32 | SMOKE | ADZ#1910-10 FLOOR 19th. | 0204283 | | | | | | | | | |
| 33 | SMOKE | ADZ#19-24-28/5 FLOOR 19th. | 0204284 | / | | | | / | / | / | / | |
| 34 | SMOKE | ADZ#1911-11 FLOOR 19th. | 0204285 | | | | | | | | | |
| 35 | SMOKE | ADZ#1912-12 FLOOR 19th. | 0204286 | | | | | | | | | |
| 36 | SMOKE | ADZ#19-35 FLOOR 19th. | 0204287 | / | | | | / | / | / | / | |
| 37 | SMOKE | ADZ#19-34 FLOOR 19th. | 0204288 | / | | | | / | / | / | / | |
| 38 | SMOKE | ADZ#19-36 FLOOR 19th. | 0204289 | / | | | | / | / | / | / | |
| 39 | SMOKE | ADZ#19-37 FLOOR 19th. | 0204290 | / | | | | / | / | / | / | |
| 40 | SMOKE | ADZ#19-29-33/4 FLOOR 19th. | 0204291 | / | | | | / | / | / | / | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 19 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#19-29-33/5 FLOOR 19th. | 0204292 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 42 | SMOKE | ADZ#19-40 FLOOR 19th. | 0204293 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 43 | SUPERVISORY | SUPERVISORY_1 FLOOR 19th. | 0204381 | ✓ | | | | ✓ | ✓ | - | - | |
| 44 | WATERFLOW | WATERFLOW_1 FLOOR 19th. | 0204382 | ✓ | | | | ✓ | ✓ | - | - | |
| 45 | AUDIBLE | AUDIBLE_ABZ_FL19_1 | 0204383 | ✓ | | | | ✓ | ✓ | - | - | |
| 46 | AUDIBLE | AUDIBLE_STROBE_FL19_1 | 0204384 | ✓ | | | | ✓ | ✓ | - | - | |
| 47 | AUDIBLE | AUDIBLE_ASZ_FL19_1 | 0204385 | ✓ | | | | ✓ | ✓ | - | - | |
| 48 | PULL | AMZ#19-04 FLOOR 19th. | 020388 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 49 | AUDIBLE | SPEAKER_ROOM1914 FLOOR 19th. | 020389 | ✓ | | | | ✓ | ✓ | - | - | |
| 50 | AUDIBLE | SPEAKER_ROOM1915 FLOOR 19th. | 020390 | | | | | | | | | |
| 51 | AUDIBLE | SPEAKER_ROOM1916 FLOOR 19th. | 0204391 | | | | | | | | | |
| 52 | AUDIBLE | SPEAKER_ROOM1917 FLOOR 19th. | 0204392 | | | | | | | | | |
| 53 | AUDIBLE | SPEAKER_ROOM1918 FLOOR 19th. | 0204393 | | | | | | | | | |
| 54 | AUDIBLE | SPEAKER_ROOM1919 FLOOR 19th. | 0204394 | | | | | | | | | |
| 55 | AUDIBLE | SPEAKER_ROOM1920 FLOOR 19th. | 0204395 | | | | | | | | | |
| 56 | AUDIBLE | SPEAKER_ROOM1921 FLOOR 19th. | 0204396 | | | | | | | | | |
| 57 | AUDIBLE | SPEAKER_ROOM1922 FLOOR 19th. | 0204397 | | | | | | | | | |
| 58 | PULL | AMZ#19-03 FLOOR 19th. | 0204398 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 59 | AUDIBLE | SPEAKER_ROOM1923 FLOOR 19th. | 0204399 | | | | | | | | | |
| 60 | AUDIBLE | SPEAKER_ROOM1924 FLOOR 19th. | 0204400 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68 | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 19 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | AUDIBLE | SPEAKER_ROOM1901 FLOOR 19th. | 0204401 | / | | | | / | / | - | - | |
| 62 | AUDIBLE | SPEAKER_ROOM1902 FLOOR 19th. | 0204402 | / | | | | / | / | - | - | |
| 63 | AUDIBLE | SPEAKER_ROOM1903 FLOOR 19th. | 0204403 | / | | | | / | / | - | - | |
| 64 | AUDIBLE | SPEAKER_ROOM1904 FLOOR 19th. | 0204404 | | | | | | | | | |
| 65 | PULL | AMZ#19-01 FLOOR 19th. | 0204405 | / | | | | / | / | / | / | |
| 66 | AUDIBLE | SPEAKER_ROOM1905 FLOOR 19th. | 0204406 | / | | | | / | / | - | - | |
| 67 | AUDIBLE | SPEAKER_ROOM1906 FLOOR 19th. | 0204407 | / | | | | / | / | - | - | |
| 68 | AUDIBLE | SPEAKER_ROOM1907 FLOOR 19th. | 0204408 | / | | | | / | / | - | - | |
| 69 | AUDIBLE | SPEAKER_ROOM1908 FLOOR 19th. | 0204409 | / | | | | / | / | - | - | |
| 70 | AUDIBLE | SPEAKER_ROOM1909 FLOOR 19th. | 0204410 | | | | | | | | | |
| 71 | AUDIBLE | SPEAKER_ROOM1910 FLOOR 19th. | 0204411 | | | | | | | | | |
| 72 | AUDIBLE | SPEAKER_ROOM1911 FLOOR 19th. | 0204412 | | | | | | | | | |
| 73 | PULL | AMZ#19-02 FLOOR 19th. | 0204413 | / | | | | / | / | / | / | |
| 74 | AUDIBLE | SPEAKER_ROOM1912 FLOOR 19th. | 0204414 | | | | | | | | | |
| 75 | | | | | | | | | | | | |
| 76 | | | | | | | | | | | | |
| 77 | | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko  Location : 20 th Floor

Service : ☑ Yearly 1/2  ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_20 | 0205001 | ✓ | | | | ✓ | ✓ | – | – | |
| 2 | SMOKE | ADZ#20-40 FLOOR 20th. | 0205004 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 3 | SMOKE | ADZ#20-30-34/5 FLOOR 20th. | 0205035 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 4 | SMOKE | ADZ#2014-14 FLOOR 20th. | 0205036 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 5 | SMOKE | ADZ#2015-15 FLOOR 20th. | 0205037 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 6 | SMOKE | ADZ#2016-16 FLOOR 20th. | 0205038 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 7 | SMOKE | ADZ#20-30-34/4 FLOOR 20th. | 0205039 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 8 | SMOKE | ADZ#2017-17 FLOOR 20th. | 0205040 | | | | | | | | | |
| 9 | SMOKE | ADZ#2018-18 FLOOR 20th. | 0205041 | | | | | | | | | |
| 10 | SMOKE | ADZ#20-30-34/3 FLOOR 20th. | 0205042 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 11 | SMOKE | ADZ#2019-19 FLOOR 20th. | 0205043 | | | | | | | | | |
| 12 | SMOKE | ADZ#20-30-34/2 FLOOR 20th. | 0205044 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 13 | SMOKE | ADZ#2021-21 FLOOR 20th. | 0205045 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 14 | SMOKE | ADZ#20-30-34/1 FLOOR 20th. | 0205046 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 15 | SMOKE | ADZ#20-39 FLOOR 20th. | 0205047 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 16 | SMOKE | ADZ#2022-22 FLOOR 20th. | 0205048 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 17 | SMOKE | ADZ#20-25-29/1 FLOOR 20th. | 0205049 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 18 | SMOKE | ADZ#2004-04 FLOOR 20th. | 0205050 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 19 | SMOKE | ADZ#2005-05 FLOOR 20th. | 0205051 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 20 | SMOKE | ADZ#20-25-29/2 FLOOR 20th. | 0205052 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 20 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#2006-06 FLOOR 20th. | 0205053 | / | | | | / | / | / | / | |
| 22 | SMOKE | ADZ#2007-07 FLOOR 20th. | 0205054 | | | | | | | | | |
| 23 | SMOKE | ADZ#20-25-29/3 FLOOR 20th. | 0205055 | / | | | | / | / | / | / | |
| 24 | SMOKE | ADZ#2008-08 FLOOR 20th. | 0205056 | / | | | | / | / | / | / | |
| 25 | SMOKE | ADZ#20-25-29/4 FLOOR 20th. | 0205057 | / | | | | / | / | / | / | |
| 26 | SMOKE | ADZ#2009-09 FLOOR 20th. | 0205058 | | | | | | | | | |
| 27 | SMOKE | ADZ#2010-10 FLOOR 20th. | 0205059 | / | | | | / | / | / | / | |
| 28 | SMOKE | ADZ#20-25-29/5 FLOOR 20th. | 0205060 | / | | | | / | / | / | / | |
| 29 | SMOKE | ADZ#2011-11 FLOOR 20th. | 0205061 | / | | | | / | / | / | / | |
| 30 | SMOKE | ADZ#2012-12 FLOOR 20th. | 0205062 | | | | | | | | | |
| 31 | SMOKE | ADZ#2013-13 FLOOR 20th. | 0205063 | / | | | | / | / | / | / | |
| 32 | SMOKE | ADZ#20-37 FLOOR 20th. | 0205064 | / | | | | / | / | / | / | |
| 33 | SMOKE | ADZ#20-35 FLOOR 20th. | 0205065 | / | | | | / | / | / | / | |
| 34 | SMOKE | ADZ#20-38 FLOOR 20th. | 0205066 | / | | | | / | / | / | / | |
| 35 | SMOKE | ADZ#20-41 FLOOR 20th. | 0205067 | / | | | | / | / | / | / | |
| 36 | SMOKE | ADZ#2024-24 FLOOR 20th. | 0205078 | | | | | | | | | |
| 37 | SMOKE | ADZ#2023-23 FLOOR 20th. | 0205079 | | | | | | | | | |
| 38 | SMOKE | ADZ#2001-01 FLOOR 20th. | 0205080 | / | | | | / | / | / | / | |
| 39 | SMOKE | ADZ#2002-02 FLOOR 20th. | 0205081 | / | | | | / | / | / | / | |
| 40 | SMOKE | ADZ#2003-03 FLOOR 20th. | 0205082 | / | | | | / | / | / | / | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 20 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#20-36 FLOOR 20th. | 0205083 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 42 | SUPERVISORY | SUPERVISORY_1 FLOOR 20th. | 0205126 | ✓ | | | | ✓ | ✓ | - | - | |
| 43 | WATERFLOW | WATERFLOW_1 FLOOR 20th. | 0205127 | ✓ | | | | ✓ | ✓ | - | - | |
| 44 | AUDIBLE | AUDIBLE_ABZ_FL20_1 | 0205128 | ✓ | | | | ✓ | ✓ | - | - | |
| 45 | AUDIBLE | AUDIBLE_STROBE_FL20_1 | 0205129 | ✓ | | | | ✓ | ✓ | - | - | |
| 46 | AUDIBLE | AUDIBLE_ASZ_FL20_1 | 0205130 | ✓ | | | | ✓ | ✓ | - | - | |
| 47 | MONITOR | MONITOR_FL20_BOOSTER | 0205136 | ✓ | | | | ✓ | ✓ | - | - | |
| 48 | AUDIBLE | AZ_FL20_POWERBELL | 0205137 | ✓ | | | | ✓ | ✓ | - | - | |
| 49 | PULL | AMZ#20-04 FLOOR 20th. | 0205138 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 50 | AUDIBLE | SPEAKER_ROOM2014 FLOOR 20th. | 0205152 | ✓ | | | | ✓ | ✓ | - | - | |
| 51 | AUDIBLE | SPEAKER_ROOM2015 FLOOR 20th. | 0205153 | ✓ | | | | ✓ | ✓ | - | - | |
| 52 | AUDIBLE | SPEAKER_ROOM2016 FLOOR 20th. | 0205154 | ✓ | | | | ✓ | ✓ | - | - | |
| 53 | AUDIBLE | SPEAKER_ROOM2017 FLOOR 20th. | 0205155 | | | | | | | | | |
| 54 | AUDIBLE | SPEAKER_ROOM2018 FLOOR 20th. | 0205156 | | | | | | | | | |
| 55 | AUDIBLE | SPEAKER_ROOM2019 FLOOR 20th. | 0205157 | | | | | | | | | |
| 56 | AUDIBLE | SPEAKER_ROOM2021 FLOOR 20th. | 0205158 | ✓ | | | | ✓ | ✓ | - | - | |
| 57 | PULL | AMZ#20-03 FLOOR 20th. | 0205159 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 58 | AUDIBLE | SPEAKER_ROOM2022 FLOOR 20th. | 0205160 | ✓ | | | | ✓ | ✓ | - | - | |
| 59 | AUDIBLE | SPEAKER_ROOM2023 FLOOR 20th. | 0205161 | | | | | | | | | |
| 60 | AUDIBLE | SPEAKER_ROOM2003 FLOOR 20th. | 0205162 | ✓ | | | | ✓ | ✓ | - | - | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 20 th Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | PULL | AMZ#20-01 FLOOR 20th. | 0205163 | / | | | | / | / | / | / | |
| 62 | AUDIBLE | SPEAKER_ROOM2004 FLOOR 20th. | 0205164 | | | | | | | | | |
| 63 | AUDIBLE | SPEAKER_ROOM2005 FLOOR 20th. | 0205165 | | | | | | | | | |
| 64 | AUDIBLE | SPEAKER_ROOM2006 FLOOR 20th. | 0205166 | / | | | | / | / | - | - | |
| 65 | AUDIBLE | SPEAKER_ROOM2007 FLOOR 20th. | 0205167 | | | | | | | | | |
| 66 | AUDIBLE | SPEAKER_ROOM2008 FLOOR 20th. | 0205168 | / | | | | / | / | - | - | |
| 67 | AUDIBLE | SPEAKER_ROOM2009 FLOOR 20th. | 0205169 | | | | | | | | | |
| 68 | AUDIBLE | SPEAKER_ROOM2010 FLOOR 20th. | 0205170 | / | | | | / | / | - | - | |
| 69 | AUDIBLE | SPEAKER_ROOM2011 FLOOR 20th. | 0205171 | / | | | | / | / | - | - | |
| 70 | PULL | AMZ#20-02 FLOOR 20th. | 0205172 | / | | | | / | / | / | / | |
| 71 | AUDIBLE | SPEAKER_ROOM2012 FLOOR 20th. | 0205173 | | | | | | | | | |
| 72 | AUDIBLE | SPEAKER_ROOM2013 FLOOR 20th. | 0205174 | / | | | | / | / | - | - | |
| 73 | AUDIBLE | SPEAKER_ROOM2024 FLOOR 20th. | 0205176 | | | | | | | | | |
| 74 | AUDIBLE | SPEAKER_ROOM2002 FLOOR 20th. | 0205177 | / | | | | / | / | - | - | |
| 75 | AUDIBLE | SPEAKER_ROOM2001 FLOOR 20th. | 0205178 | / | | | | / | / | - | - | |
| 76 | | | | | | | | | | | | |
| 77 | | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68 | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 21 st Floor

Service : ☑ Yearly 1/2. ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_21 | 0205002 | / | | | | / | / | – | – | |
| 2 | ISOLATOR | IM_OUT_FTB_21 | 0205003 | / | | | | / | / | – | – | |
| 3 | SMOKE | ADZ#21-39 FLOOR 21th. | 0205005 | / | | | | / | / | – | – | |
| 4 | SMOKE | ADZ#21-21 FLOOR 21th. | 0205006 | / | | | | / | / | / | / | |
| 5 | SMOKE | ADZ#21-20 FLOOR 21th. | 0205007 | / | | | | / | / | / | / | |
| 6 | SMOKE | ADZ#21-18 FLOOR 21th. | 0205008 | / | | | | / | / | / | / | |
| 7 | SMOKE | ADZ#21-19 FLOOR 21th. | 0205009 | / | | | | / | / | / | / | |
| 8 | SMOKE | ADZ#21-17 FLOOR 21th. | 0205010 | / | | | | / | / | / | / | |
| 9 | SMOKE | ADZ#21-16 FLOOR 21th. | 0205011 | / | | | | / | / | / | / | |
| 10 | SMOKE | ADZ#2110-10 FLOOR 21th. | 0205012 | | | | | | | | | |
| 11 | SMOKE | ADZ#2109-09 FLOOR 21th. | 0205013 | | | | | | | | | |
| 12 | SMOKE | ADZ#2108-08 FLOOR 21th. | 0205014 | / | | | | / | / | / | / | |
| 13 | SMOKE | ADZ#2107-07 FLOOR 21th. | 0205015 | | | | | | | | | |
| 14 | SMOKE | ADZ#21-14 FLOOR 21th. | 0205016 | / | | | | / | / | / | / | |
| 15 | SMOKE | ADZ#2106-06 FLOOR 21th. | 0205017 | | | | | | | | | |
| 16 | SMOKE | ADZ#21-13 FLOOR 21th. | 0205018 | / | | | | / | / | / | / | |
| 17 | SMOKE | ADZ#2105-05 FLOOR 21th. | 0205019 | / | | | | / | / | / | / | |
| 18 | SMOKE | ADZ#2104-04 FLOOR 21th. | 0205020 | / | | | | / | / | / | / | |
| 19 | SMOKE | ADZ#21-12 FLOOR 21th. | 0205021 | / | | | | / | / | / | / | |
| 20 | SMOKE | ADZ#21-38 FLOOR 21th. | 0205022 | / | | | | / | / | / | / | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 21 st Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#21-35 FLOOR 21th. | 0205023 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 22 | SMOKE | ADZ#21-31 FLOOR 21th. | 0205024 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 23 | SMOKE | ADZ#21-30 FLOOR 21th. | 0205025 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 24 | SMOKE | ADZ#21-29 FLOOR 21th. | 0205026 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 25 | SMOKE | ADZ#21-36 FLOOR 21th. | 0205027 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 26 | SMOKE | ADZ#21-28 FLOOR 21th. | 0205028 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 27 | SMOKE | ADZ#21-27 FLOOR 21th. | 0205029 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 28 | SMOKE | ADZ#21-26 FLOOR 21th. | 0205030 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 29 | SMOKE | ADZ#21-25 FLOOR 21th. | 0205031 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 30 | SMOKE | ADZ#21-24 FLOOR 21th. | 0205032 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 31 | SMOKE | ADZ#21-23 FLOOR 21th. | 0205033 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 32 | SMOKE | ADZ#21-40 FLOOR 21th. | 0205034 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 33 | SMOKE | ADZ#21-15 FLOOR 21th. | 0205068 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 34 | SMOKE | ADZ#21-22 FLOOR 21th. | 0205069 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 35 | SMOKE | ADZ#2111-11 FLOOR 21th. | 0205070 | | | | | | | | | |
| 36 | SMOKE | ADZ#2103-03 FLOOR 21th. | 0205071 | | | | | | | | | |
| 37 | SMOKE | ADZ#2102-02 FLOOR 21th. | 0205072 | | | | | | | | | |
| 38 | SMOKE | ADZ#2101-01 FLOOR 21th. | 0205073 | | | | | | | | | |
| 39 | SMOKE | ADZ#21-32 FLOOR 21th. | 0205074 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |
| 40 | SMOKE | ADZ#21-34 FLOOR 21th. | 0205075 | ✓ | | | | ✓ | ✓ | ✓ | ✓ | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 21 st Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | SMOKE | ADZ#21-33 FLOOR 21th. | 0205076 | / | | | | / | / | / | / | |
| 42 | SMOKE | ADZ#21-37 FLOOR 21th. | 0205077 | / | | | | / | / | / | / | |
| 43 | SUPERVISORY | SUPERVISORY_1 FLOOR 21th. | 0205131 | / | | | | / | / | - | - | |
| 44 | WATERFLOW | WATERFLOW_1 FLOOR 21th. | 0205132 | / | | | | / | / | - | - | |
| 45 | AUDIBLE | AUDIBLE_ABZ_FL21_1 | 0205133 | / | | | | / | / | - | - | |
| 46 | AUDIBLE | AUDIBLE_STROBE_FL21_1 | 0205134 | / | | | | / | / | - | - | |
| 47 | AUDIBLE | AUDIBLE_ASZ_FL21_1 | 0205135 | / | | | | / | / | - | - | |
| 48 | PULL | AMZ#21-04 FLOOR 21th. | 0205139 | / | | | | / | / | / | / | |
| 49 | AUDIBLE | SPEAKER_ROOM2111 FLOOR 21th. | 0205140 | | | | | | | | | |
| 50 | PULL | AMZ#21-02 FLOOR 21th. | 0205141 | / | | | | / | / | / | / | |
| 51 | AUDIBLE | SPEAKER_ROOM2110 FLOOR 21th. | 0205142 | | | | | | | | | |
| 52 | AUDIBLE | SPEAKER_ROOM2109 FLOOR 21th. | 0205143 | | | | | | | | | |
| 53 | AUDIBLE | SPEAKER_ROOM2108 FLOOR 21th. | 0205144 | / | | | | / | / | - | - | |
| 54 | AUDIBLE | SPEAKER_ROOM2107 FLOOR 21th. | 0205145 | | | | | | | | | |
| 55 | AUDIBLE | SPEAKER_ROOM2106 FLOOR 21th. | 0205146 | | | | | | | | | |
| 56 | AUDIBLE | SPEAKER_ROOM2105 FLOOR 21th. | 0205147 | / | | | | / | / | - | - | |
| 57 | AUDIBLE | SPEAKER_ROOM2104 FLOOR 21th. | 0205148 | / | | | | / | / | - | - | |
| 58 | PULL | AMZ#21-01 FLOOR 21th. | 0205149 | / | | | | / | / | / | / | |
| 59 | AUDIBLE | SPEAKER_ROOM2103 FLOOR 21th. | 0205150 | | | | | | | | | |
| 60 | AUDIBLE | SPEAKER_ROOM2101 FLOOR 21th. | 0205151 | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 21 st Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 61 | PULL | AMZ#21-03 FLOOR 21th. | 0205175 | / | | | | / | / | - | - | |
| 62 | FANCONTROL | CONTROL AV SYSTEM PANTRY RM. 21- FL. | 0205179 | / | | | | / | / | - | - | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko. Location : 22 nd Floor

Service : ☐ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ü | = Normal |
| û | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_22 | 0205251 | / | | | | / | / | - | - | |
| 2 | SMOKE | ADZ#22-38 FLOOR 22th. | 0205261 | / | | | | / | / | / | / | |
| 3 | SMOKE | ADZ#22-35 FLOOR 22th. | 0205262 | / | | | | / | / | / | / | |
| 4 | SMOKE | ADZ#22-32 FLOOR 22th. | 0205263 | / | | | | / | / | / | / | |
| 5 | SMOKE | ADZ#22-34 FLOOR 22th. | 0205264 | / | | | | / | / | / | / | |
| 6 | SMOKE | ADZ#22-33 FLOOR 22th. | 0205265 | / | | | | / | / | / | / | |
| 7 | SMOKE | ADZ#2211-11 FLOOR 22th. | 0205266 | / | | | | / | / | / | / | |
| 8 | SMOKE | ADZ#22-25 FLOOR 22th. | 0205267 | / | | | | / | / | / | / | |
| 9 | SMOKE | ADZ#2210-10 FLOOR 22th. | 0205268 | / | | | | / | / | / | / | |
| 10 | SMOKE | ADZ#2209-09 FLOOR 22th. | 0205269 | | | | | | | | | |
| 11 | SMOKE | ADZ#22-24 FLOOR 22th. | 0205270 | / | | | | / | / | / | / | |
| 12 | SMOKE | ADZ#2208-08 FLOOR 22th. | 0205271 | | | | | | | | | |
| 13 | SMOKE | ADZ#2207-07 FLOOR 22th. | 0205272 | / | | | | / | / | / | / | |
| 14 | SMOKE | ADZ#22-23 FLOOR 22th. | 0205273 | / | | | | / | / | / | / | |
| 15 | SMOKE | ADZ#2206-06 FLOOR 22th. | 0205274 | | | | | | | | | |
| 16 | SMOKE | ADZ#22-22 FLOOR 22th. | 0205275 | / | | | | / | / | / | / | |
| 17 | SMOKE | ADZ#2205-05 FLOOR 22th. | 0205276 | / | | | | / | / | / | / | |
| 18 | SMOKE | ADZ#2204-04 FLOOR 22th. | 0205277 | / | | | | / | / | / | / | |
| 19 | SMOKE | ADZ#22-21 FLOOR 22th. | 0205278 | / | | | | / | / | / | / | |
| 20 | SMOKE | ADZ#2203-03 FLOOR 22th. | 0205279 | / | | | | / | / | / | / | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 22 nd Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 21 | SMOKE | ADZ#2202-02 FLOOR 22th. | 0205280 | / | | | | / | / | / | / | |
| 22 | SMOKE | ADZ#2201-01 FLOOR 22th. | 0205281 | / | | | | / | / | / | / | |
| 23 | SMOKE | ADZ#2224-20 FLOOR 22th. | 0205282 | / | | | | / | / | / | / | |
| 24 | SMOKE | ADZ#2223-19 FLOOR 22th. | 0205283 | / | | | | / | / | / | / | |
| 25 | SMOKE | ADZ#22-36 FLOOR 22th. | 0205284 | / | | | | / | / | / | / | |
| 26 | SMOKE | ADZ#22-26 FLOOR 22th. | 0205285 | / | | | | / | / | / | / | |
| 27 | SMOKE | ADZ#2222-18 FLOOR 22th. | 0205286 | / | | | | / | / | / | / | |
| 28 | SMOKE | ADZ#2221-17 FLOOR 22th. | 0205287 | / | | | | / | / | / | / | |
| 29 | SMOKE | ADZ#22-27 FLOOR 22th. | 0205288 | / | | | | / | / | / | / | |
| 30 | SMOKE | ADZ#22-28 FLOOR 22th. | 0205289 | / | | | | / | / | / | / | |
| 31 | SMOKE | ADZ#2219-16 FLOOR 22th. | 0205290 | / | | | | / | / | / | / | |
| 32 | SMOKE | ADZ#22-29 FLOOR 22th. | 0205291 | / | | | | / | / | / | / | |
| 33 | SMOKE | ADZ#2218-15 FLOOR 22th. | 0205292 | / | | | | / | / | / | / | |
| 34 | SMOKE | ADZ#2217-14 FLOOR 22th. | 0205293 | / | | | | / | / | / | / | |
| 35 | SMOKE | ADZ#22-30 FLOOR 22th. | 0205294 | / | | | | / | / | / | / | |
| 36 | SMOKE | ADZ#2216-13 FLOOR 22th. | 0205295 | | | | | | | | | |
| 37 | SMOKE | ADZ#2215-12 FLOOR 22th. | 0205296 | | | | | | | | | |
| 38 | SMOKE | ADZ#22-31 FLOOR 22th. | 0205297 | / | | | | / | / | / | / | |
| 39 | SMOKE | ADZ#22-37 FLOOR 22th. | 0205298 | | | | | | | | | |
| 40 | SUPERVISORY | SUPERVISORY_1 FLOOR 22th. | 0205376 | / | | | | / | / | - | - | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 22 nd Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ü | = Normal |
| û | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 41 | WATERFLOW | WATERFLOW_1 FLOOR 22th. | 0205377 | / | | | | / | / | - | - | |
| 42 | AUDIBLE | AUDIBLE_ABZ_FL22_1 | 0205378 | / | | | | / | / | - | - | |
| 43 | AUDIBLE | AUDIBLE_STROBE_FL22_1 | 0205379 | / | | | | / | / | - | - | |
| 44 | AUDIBLE | AUDIBLE_ASZ_FL22_1 | 0205380 | / | | | | / | / | - | - | |
| 45 | MONITOR | MONITOR_FL22_BOOSTER | 0205402 | / | | | | / | / | - | - | |
| 46 | AUDIBLE | AZ_FL22_POWERBELL | 0205403 | / | | | | / | / | - | - | |
| 47 | AUDIBLE | SPEAKER_ROOM2211 FLOOR 22th. | 0205406 | / | | | | / | / | - | - | |
| 48 | PULL | AMZ#22-02 FLOOR 22th. | 0205407 | / | | | | / | / | / | / | |
| 49 | AUDIBLE | SPEAKER_ROOM2210 FLOOR 22th. | 0205408 | / | | | | / | / | - | - | |
| 50 | AUDIBLE | SPEAKER_ROOM2209 FLOOR 22th. | 0205409 | | | | | | | | | |
| 51 | AUDIBLE | SPEAKER_ROOM2208 FLOOR 22th. | 0205410 | | | | | | | | | |
| 52 | AUDIBLE | SPEAKER_ROOM2207 FLOOR 22th. | 0205411 | / | | | | / | / | - | - | |
| 53 | AUDIBLE | SPEAKER_ROOM2206 FLOOR 22th. | 0205412 | | | | | | | | | |
| 54 | AUDIBLE | SPEAKER_ROOM2205 FLOOR 22th. | 0205413 | / | | | | / | / | - | - | |
| 55 | PULL | AMZ#22-01 FLOOR 22th. | 0205414 | / | | | | / | / | / | / | |
| 56 | AUDIBLE | SPEAKER_ROOM2204 FLOOR 22th. | 0205415 | / | | | | / | / | - | - | |
| 57 | AUDIBLE | SPEAKER_ROOM2201/1 FLOOR 22th. | 0205416 | / | | | | / | / | - | - | |
| 58 | AUDIBLE | SPEAKER_ROOM2201/2 FLOOR 22th. | 0205417 | / | | | | / | / | - | - | |
| 59 | AUDIBLE | SPEAKER_ROOM2224/1 FLOOR 22th. | 0205418 | / | | | | / | / | - | - | |
| 60 | AUDIBLE | SPEAKER_ROOM2224/2 FLOOR 22th. | 0205419 | / | | | | / | / | - | - | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : 22 nd Floor

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly 1 | 2 | 3 | 4 | Actions Visual Check | Clean | Test | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 61 | PULL | AMZ#22-03 FLOOR 22th. | 0205420 | / | | | | / | / | / | / | |
| 62 | AUDIBLE | SPEAKER_ROOM2222 FLOOR 22th. | 0205421 | / | | | | / | / | - | - | |
| 63 | AUDIBLE | SPEAKER_ROOM2219 FLOOR 22th. | 0205422 | / | | | | / | / | - | - | |
| 64 | AUDIBLE | SPEAKER_ROOM2218 FLOOR 22th. | 0205423 | / | | | | / | / | - | - | |
| 65 | AUDIBLE | SPEAKER_ROOM2217 FLOOR 22th. | 0205424 | / | | | | / | / | - | - | |
| 66 | AUDIBLE | SPEAKER_ROOM2216 FLOOR 22th. | 0205425 | | | | | | | | | |
| 67 | AUDIBLE | SPEAKER_ROOM2215 FLOOR 22th. | 0205426 | | | | | | | | | |
| 68 | PULL | AMZ#22-04 FLOOR 22th. | 0205427 | / | | | | / | / | / | / | |
| 69 | AUDIBLE | SPEAKER_ROOM 2202 FLOOR 22 TH | | / | | | | / | / | - | - | |
| 70 | AUDIBLE | SPEAKER_ROOM 2203 FLOOR 22 th. | | / | | | | / | / | - | - | |
| 71 | AUDIBLE | SPEAKER_ROOM 2223 FLOOR 22 th. | | / | | | | / | / | - | - | |
| 72 | AUDIBLE | SPEAKER-ROOM 2221 FLOOR22 th. | | / | | | | / | / | - | - | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |

# FIRE ALARM SYSTEM

Project : บำรุงรักษาระบบสัญญาณแจ้งเหตุเพลิงไหม้ Hotel Nikko Bangkok (Thailand) ประจำปี 2568

Building : Hotel Nikko Location : Roof.

Service : ☑ Yearly 1/2 ☐ Other

| | |
|---|---|
| - | = N/A |
| ✓ | = Normal |
| ✖ | = Abnormal |

INSPECTION AND TEST REPORT FOR DEVICES

| Item | Type | Area Description / Location | Device Address / Zone | Quarterly | | | | Actions | | | Test Result | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1 | 2 | 3 | 4 | Visual Check | Clean | Test | | |
| 1 | ISOLATOR | IM_IN_FTB_R | 0205252 | / | | | | / | / | - | - | |
| 2 | ISOLATOR | IM_OUT_FTB_R | 0205253 | / | | | | / | / | - | - | |
| 3 | SMOKE | ADZ#LMR-02 FLOOR ROOF | 0205254 | / | | | | / | / | / | / | |
| 4 | SMOKE | ADZ#LMR-03 FLOOR ROOF | 0205255 | / | | | | / | / | / | / | |
| 5 | SMOKE | ADZ#LMR-04 FLOOR ROOF | 0205256 | / | | | | / | / | / | / | |
| 6 | SMOKE | ADZ#LMR-05 FLOOR ROOF | 0205257 | / | | | | / | / | / | / | |
| 7 | SMOKE | ADZ#LMR-06 FLOOR ROOF | 0205258 | / | | | | / | / | / | / | |
| 8 | SMOKE | ADZ#LMR-07 FLOOR ROOF | 0205259 | / | | | | / | / | / | / | |
| 9 | SMOKE | ADZ#LMR-01 FLOOR ROOF | 0205260 | / | | | | / | / | / | / | |
| 10 | SUPERVISORY | SUPERVISORY_1 ROOF FLOOR | 0205381 | / | | | | / | / | - | - | |
| 11 | SUPERVISORY | SUPERVISORY_2 ROOF FLOOR | 0205382 | / | | | | / | / | - | - | |
| 12 | SUPERVISORY | SUPERVISORY_3 ROOF FLOOR | 0205383 | / | | | | / | / | - | - | |
| 13 | WATERFLOW | WATERFLOW_1 ROOF FLOOR | 0205384 | / | | | | / | / | - | - | |
| 14 | WATERFLOW | WATERFLOW_2 ROOF FLOOR | 0205385 | / | | | | / | / | - | - | |
| 15 | FANCONTROL | PRESSURINGFAN_PF_FLR_1 | 0205386 | / | | | | / | / | - | - | |
| 16 | FANCONTROL | PRESSURINGFAN_PF_FLR_2 | 0205387 | / | | | | / | / | - | - | |
| 17 | FANCONTROL | PRESSURINGFAN_PF_FLR_3 | 0205388 | / | | | | / | / | - | - | |
| 18 | FANCONTROL | CONTROL_ ERV ROOF FL. | 0205389 | / | | | | / | / | - | - | |
| 19 | FANCONTROL | CONTROL_SERVICELIFT_FLR_1 | 0205392 | / | | | | / | / | - | - | |
| 20 | FANCONTROL | CONTROL_SERVICELIFT_FLR_2 | 0205393 | / | | | | / | / | - | - | |

COMMENT :

| Quarterly | TEST BY : Confide Technology | Date | APPOVED BY : Hotel Nikko Bangkok | Date |
|---|---|---|---|---|
| 1 | SIGNATURE : | 21/5/68. | SIGNATURE : | |
| 2 | SIGNATURE : | | SIGNATURE : | |
| 3 | SIGNATURE : | | SIGNATURE : | |