



ภาคผนวกที่ 6

Fire Exit Door Report

Fire Exit Door Monthly Checklist on July 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A2 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
2		A2 1fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓	✓	cement bag
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
1		A2 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
1		A2 3 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	




Fire Exit Door Monthly Checklist on July 2025



No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1	 BLD A3 FL G	A3 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
2	 BLD A3 FL.1	A3 1 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3	 BLD A3 FL.2	A3 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4	 BLD A3 FL.3	A3 3 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

Fire Exit Door Monthly Checklist on July 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A4 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
2		A4 1Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		A4 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	
4		A4 3 FL.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		


Fire Exit Door Monthly Checklist on July 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		B 8 FL. Beside R.5004	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
2		B 8 FL. Beside R.5022	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		B 1 FL. Beside R.5104	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 1 FL. Beside R.5119	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 2 FL. Beside R.5204	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 2 FL. Beside R.5219	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

4		B 3 FL. Beside R.5304	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 3 FL. Beside R.5319	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 4 FL. Beside R5404	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 4 FL	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	


Fire Exit Door Monthly Checklist on July 2025

No		Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		BLD. C Basement R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Kitchen Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark ; Ensure the floor is completely filled with cement			
2		BLD. C Basement Beside F/C Office	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		BLD. C Floor G Opposite 6008	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number			
			Fire escape staircase lighting	✓		
4		BLD. C Floor G Restaurant R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
5		BLD. C Floor 1 Beside 6114 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
6		BLD. C Floor 2 Beside 6215L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	


7		BLD. C Floor 2 Opposite Spa	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		Trash (cigarette butt)
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
8		BLD.C Floor 3 Beside 6309R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
9		BLD.C Floor 3 Beside 6314 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
10		BLD.C Floor 4 Beside 6416 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
11		BLD.C Floor 4 Beside 6405R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

Check By.


Security Supervisor


Fire Exit Door Monthly Checklist on August 2025						
No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A1 G FL.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
2		A1 1FL.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		A1 2 FL.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		A1 3 FL.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

Fire Exit Door Monthly Checklist on August 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A2 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
2		A2 1Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓	✓	cement bag
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
1		A2 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
1		A2 3 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

Fire Exit Door Monthly Checklist on August 2025


No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A3 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
2		A3 1 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		A3 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		A3 3 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

Fire Exit Door Monthly Checklist on August 2025						
No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A4 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
2		A4 1 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		A4 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	
4		A4 3 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		

Fire Exit Door Monthly Checklist on August 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		B G Fl. Beside R.5004	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
2		B G Fl. Beside R.5022	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		B 1 Fl. Beside R.5104	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 1 FL Beside R.5119	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 2 FL Beside R.5204	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 2 FL Beside R.5219	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

4		B 3 FL. Beside R.5304	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 3 FL. Beside R.5319	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 4 FL. Beside R5404	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 4 FL. R.5419	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	


Fire Exit Door Monthly Checklist on August 2025						
No		Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		BLD. C Basement R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Kitchen Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark ; Ensure the floor is completely filled with cement			
2		BLD. C Basement Beside F/C Office	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		BLD. C Floor G Opposite 6008	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number			
			Fire escape staircase lighting	✓		
4		BLD. C Floor G Restaurant R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
5		BLD. C Floor 1 Beside 6114 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
6		BLD. C Floor 2 Beside 6215L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

7		BLD. C Floor 2 Opposite Spa	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		Trash (cigarette butt)
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
8		BLD.C Floor 3 Beside 6309R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
9		BLD.C Floor 3 Beside 6314 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
10		BLD.C Floor 4 Beside 6416 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
11		BLD.C Floor 4 Beside 6405R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

Check By.



Security Supervisor

Fire Exit Door Monthly Checklist on September 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A1 G FL.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
2		A1 1FL.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		A1 2 FL.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		A1 3 FL.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	


Check By

Fire Exit Door Monthly Checklist on September 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A2 G Fl.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
2		A2 1 Fl.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓	✓	cement bag
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
1		A2 2 Fl.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
1		A2 3 Fl.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

Check By

Fire Exit Door Monthly Checklist on September 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A3 G FL.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
2		A3 1 FL.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		A3 2 FL.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		A3 3 FL.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	




Check By




Fire Exit Door Monthly Checklist on September 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A4 G Fl.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
2		A4 1Fl.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		A4 2 Fl.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	
4		A4 3 FL.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		

Check By


Fire Exit Door Monthly Checklist on September 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		B G Fl. Beside R.5004	Fire Exit door panel/frame	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
2		B G Fl. Beside R.5022	Fire Exit door panel/frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		B 1 Fl. Beside R.5104	Fire Exit door panel/frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 1 FL Beside R.5119	Fire Exit door panel/frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 2 FL Beside R.5204	Fire Exit door panel/frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 2 FL Beside R.5219	Fire Exit door panel/frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

4		B 3 FL. Beside R.5304	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4		B 3 FL. Beside R.5319	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4	 	B 4 FL. Beside R.5404	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
4	 	B 4 FL.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

Check By



Fire Exit Door Monthly Checklist on September 2025

No		Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		BLD. C Basement R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Kitchen Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark ; Ensure the floor is completely filled with cement			
2		BLD. C Basement Beside F/C Office	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
3		BLD. C Floor G Opposite 6008	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number			
			Fire escape staircase lighting	✓		
4		BLD.C Floor G Restaurant R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
5		BLD.C Floor 1 Beside 6114 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
6		BLD.C Floor 2 Beside 6215L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	

7		BLD. C Floor 2 Opposite Spa	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		Trash (cigarette butt)
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
8		BLD.C Floor 3 Beside 6309R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
9		BLD.C Floor 3 Beside 6314 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
10		BLD.C Floor 4 Beside 6416 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
11		BLD.C Floor 4 Beside 6405R	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	



Check By.

Fire Exit Door Monthly Checklist on October 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A1 G Fl.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓	✓	HK Equipment
			Hand pushing fire escape door	✓	✓	ตัวล็อกไม่สามารถล็อกได้
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ไม่ติด
2		A1 1 Fl.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction			No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ไม่ติด
3		A1 2 Fl.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction			construction equipment
			Hand pushing fire escape door	✓	✓	ตัวล็อกไม่สามารถล็อกได้
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ไม่ติด
4		A1 3 Fl.	Fire Exit door panel/Frame	✓		
			Fire exit door shock	✓		
			Obstruction	✓	✓	เหล็ก ฝุ่นบนมา - construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ไม่ติด


Check By. Mr.Phumisak Anantakhul

Fire Exit Door Monthly Checklist on October 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A2 G Fl.	Fire Exit door panel	✓		ครบถ้วนประตู / ด้านใน-ด้านนอก
			Fire exit door shock	✓		
			Obstruction			Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
2		A2 1 Fl.	Fire Exit door panel	✓		มีของติด ฝ้าเพดาน
			Fire exit door shock	✓		
			Obstruction		✓	cement bag
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
1		A2 2 Fl.	Fire Exit door panel	✓		ยังไม่หาซื้อประตู - ลอกพลาสติกไม่หมด
			Fire exit door shock	✓		
			Obstruction		✓	Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
1		A2 3 Fl.	Fire Exit door panel	✓		ยังไม่หาซื้อประตู - มีพลาสติกที่ขอบประตู
			Fire exit door shock	✓		
			Obstruction		✓	Trash
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		

Check By. Mr. Phumisak Anantakhul

Fire Exit Door Monthly Checklist on October 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1	 A3. G. - R.3008	A3 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓	✓	มีอุปกรณ์ แปะบ้านวางไว้ในบริเวณ
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		มีระบบฝ้าเพดาน ใกล้กับดวงไฟ
2	 A3. 1. - R. 3108	A3 1 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction			
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		ฝ้าเพดานยังมีรอยตัด - เป็นรู
3	 A3. 2. - R. 3208	A3 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction			
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		ฝ้าเพดาน ยังมีรอยตัด
4	 A3. 3. - R.3308	A3 3 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓	✓	มีกล่องของผู้รับเหมาวางไว้
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	ยังไม่มีไฟ ช่องทางเดิน - ฝ้ายังมีรอยตัด



Check By. Mr. Phumisak Anantakhul



Fire Exit Door Monthly Checklist on October 2025

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A4 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓	✓	มีอุปกรณ์กล่อง - ลีโอนี่ กีดขวางในบริเวณ
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
2		A4 1Fl.	Fire Exit door panel	✓		ไม่หาสีขอบประตู - ลอกพลาสติกไม่หมด
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
3		A4 2 Fl.	Fire Exit door panel	✓		ไม่หาสีขอบประตู - ลอกพลาสติกไม่หมด / ด้านใน - ด้านนอก
			Fire exit door shock	✓		
			Obstruction			
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ไฟช่องสว่างไม่ติด - ฝ้าเพดานยังเป็นรู
4		A4 3 Fl.	Fire Exit door panel	✓		ไม่หาสีขอบประตู - ลอกพลาสติกไม่หมด / ด้านใน - ด้านนอก
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ไฟช่องสว่างไม่ติด

Check By. Mr. Phumisak Anantakhul

Fire Exit Door Monthly Checklist on October 2025


No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
8		B G FL. Basement . B.	Fire Exit door panel	✓	✓	ติดตั้งประตู ผิดฝั่ง - ต้องผลัดออกไปด้านขวา
			Fire exit door shock	✓		
			Obstruction	✓	✓	มีอุปกรณ์ HK
			Hand pushing fire escape door	✓	✓	ติดตั้งประตู ผิดฝั่ง - ต้องผลัดออกไปด้านขวา
			Floor Number	✓		
			Fire escape staircase lighting	✓		บ่งเก็บสายไฟไม่เรียบร้อย บางส่วน
1		B G FL. Beside R.5004	Fire Exit door panel	✓	✓	ครบอุปกรณ์
			Fire exit door shock	✓		
			Obstruction	✓		HK Equipment - กล้องวงจรปิด
			Hand pushing fire escape door	✓	✓	ขึ้นสนิมเป็นบางส่วน
			Floor Number	✓		
			Fire escape staircase lighting	✓		
2		B G FL. Beside R.5021	Fire Exit door panel	✓	✓	ไม่หาซื้ออุปกรณ์ - ประตูตก (เสียบ) ไม่สามารถเปิด-ปิด ได้
			Fire exit door shock	✓	✓	ขึ้นสนิมเป็นบางส่วน
			Obstruction		✓	มีอุปกรณ์ HK
			Hand pushing fire escape door	✓	✓	ขึ้นสนิมเป็นบางส่วน
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ไฟส่องสว่างไม่ติด - เก็บสายไฟไม่เรียบร้อย
3		B 1 FL. Beside R.5104	Fire Exit door panel	✓	✓	อุปกรณ์ - ด้านใน - ด้านนอก
			Fire exit door shock	✓		
			Obstruction			
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
4		B 1 FL. Beside R.5119	Fire Exit door panel	✓	✓	มีอุปกรณ์ - ครบอุปกรณ์
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ไฟส่องสว่างไม่ติด - ติดตั้งเบี่ยงซ้าย
4		B 2 FL. Beside R.5204	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓	✓	มีอุปกรณ์ HK
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
4		B 2 FL. Beside R.5219	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ไฟส่องสว่างไม่ติด

4		B 3 FL. Beside R.5304	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction			
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
4		B 3 FL. Beside R.5319	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction			
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ไฟส่องสว่างปกติ
4		B 4 FL. Beside R5404	Fire Exit door panel	✓		ไม่หาสีขอบประตู - ขอบ มีพลาสติก
			Fire exit door shock	✓		
			Obstruction	✓	✓	มีเหล็กเส้น ม้วนหนา
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
4		B 4 FL.R.5419	Fire Exit door panel	✓		ไม่หาสีขอบประตู - สกปรก - ด้านใน-ด้านนอก
			Fire exit door shock	✓		
			Obstruction	✓		มีขยะเล็กวางไว้
			Hand pushing fire escape door	✓		ตัวล็อกผิด ไม่ติดกลับ
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ไฟส่องสว่างปกติ

Check By. Mr.Phumisak Anantakhul




Fire Exit Door Monthly Checklist on October 2025

Fire Exit door Monthly Checklist on October 2025						
No		Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1	 C. Basement accounting office	BLD. C Basement R	Fire Exit door panel/frame	✓	✓	มีมีทาสติกริม ขอบประตู - มีน้ำขังเล็กน้อย
			Fire exit door shock	✓		
			Obstruction	✓	✓	Kitchen Equipment - มีอุปกรณ์ ผสม.จีน
			Hand pushing fire escape door	✓	✓	ไม่สามารถเปิดประตู ให้ลิคได้
			Floor Number	✓		
			Fire escape staircase lighting		✓	ทางเดินไฟส่องสว่างติดแต่ เเดระกกลางคืน
			Remark :			
2	 C. Basement F/C C. Basement F/C C. Basement F/C	BLD. C Basement Beside F/C Office	Fire Exit door panel/frame	✓	✓	ไม่ทาสีขอบประตู - มีคราปนสกปรก
			Fire exit door shock	✓		
			Obstruction	✓	✓	No Obstructions. - อุปกรณ์ F/C
			Hand pushing fire escape door	✓	✓	ตัวหลัง เริ่มขึ้นสนิม
			Floor Number	✓		
			Fire escape staircase lighting		✓	ไม่มีไฟส่องสว่างทางเดินหนีไฟ
			Remark :			
3	 C. G. R. 6008	BLD. C Floor G Opposite 6008	Fire Exit door panel/frame	✓		ไม่ทาสีขอบประตู - มีคราปนสกปรก ทั้งด้านใน และ ด้านนอก
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		ไม่สามารถเปิดประตู ให้ลิคได้
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ทางเดินไฟส่องสว่างติดแต่ เเดระกกลางคืน
			Remark :			
4	 C. J. Restaurant R. C. J. Restaurant R. C. J. Restaurant R.	BLD. C Floor G Restaurant R	Fire Exit door panel/frame	✓	✓	ไม่ทาสีขอบประตู - มีคราปน - คราปนสกปรก
			Fire exit door shock	✓		
			Obstruction	✓	✓	No Obstructions. - มีสายไฟ ผสม. - กันนุหรี ตามพื้น-ตามบันได
			Hand pushing fire escape door	✓	✓	ตัวลิคเสียบ - ตัวหลักออกเริ่มขึ้นสนิม
			Floor Number	✓		
			Fire escape staircase lighting		✓	ไม่มีไฟส่องสว่างทางเดินหนีไฟ
			Remark :			
5	 C. J. R. 6114	BLD. C Floor 1 Beside 6114 L	Fire Exit door panel/frame	✓		
			Fire exit door shock	✓		
			Obstruction			
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ทางเดินไฟส่องสว่างติดแต่ เเดระกกลางคืน
			Remark :			

6		BLD.C Floor 2 Beside 6215L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ทางเดินไฟส่องสว่างตั้งแต่ เจริญกลางคืน - ยังเก็บสายไฟไม่เรียบร้อย
7		BLD. C Floor 2 Opposite Spa	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓	✓	Trash (cigarette butt) - ที่วางสูบบุหรี่
			Hand pushing fire escape door	✓	✓	ไม่สามารถเปิดประตู ไ้สือกได้ - ประตูตก
			Floor Number	✓		
			Fire escape staircase lighting	✓		
8		BLD.C Floor 3 Beside 6305R	Fire Exit door panel	✓	✓	ครบสกรปรก
			Fire exit door shock	✓		
			Obstruction	✓	✓	มีหมวกเหล็ก ผู้รับเหมา
			Hand pushing fire escape door	✓	✓	ไม่สามารถเปิดประตู ไ้สือกได้ - ประตูตก
			Floor Number	✓		
			Fire escape staircase lighting		✓	ไม่มีไฟส่องสว่างทางเดินหนีไฟ
9		BLD.C Floor 3 Beside 6314 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ทางเดินไฟส่องสว่างติดแต่ เจริญกลางคืน
10		BLD.C Floor 4 Beside 6416 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓	✓	ทางเดินไฟส่องสว่างติดแต่ เจริญกลางคืน
11		BLD.C Floor 4 Beside 6405R	Fire Exit door panel	✓	✓	มีครบสกรปรก
			Fire exit door shock	✓	✓	ไขควงประตูลดเสียง
			Obstruction			
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	ไม่มีไฟส่องสว่างทางเดินหนีไฟ

Check By: Mr.Phumisak Anantakhul

Fire Exit Door Monthly Checklist on November 2025.


No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A1 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark.			
2		A1 1Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark.			
3		A1 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark.			
4		A1 3 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	construction equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark.			

Check By.

Apirat Khongyuen




Security Supervisor

Fire Exit Door Monthly Checklist on November 2025.

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A2 6 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: There are traces of drilling holes in the ceiling. The top edge of the door is not yet finished.			
2		A2 1 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: There are traces of drilling holes in the ceiling. There are traces of a cut in the floor at the bottom of the door.			
3		A2 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: There are traces of drilling holes in the ceiling.			
4		A2 3 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: There are traces of drilling holes in the ceiling.			

Check By: Apirat Khongyuen Security Supervisor

Fire Exit Door Monthly Checklist on November 2025.

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A3 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark.			
2		A3 1Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark. There are traces of drilling holes in the ceiling.			
3		A3 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark. There are traces of drilling holes in the ceiling.			
4		A3 3 FL.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark. There are traces of drilling holes in the ceiling.			

Check By.

Apirat Khongyuen

Security Supervisor

Fire Exit Door Monthly Checklist on November 2025.





No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A4 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: There are traces of drilling holes in the ceiling.			
2		A4 1 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: There are traces of drilling holes in the ceiling. The ceiling has not been painted yet. The door frames, both inside and outside, have not been painted yet.			
3		A4 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark: There are traces of drilling holes in the ceiling. The ceiling has not been painted yet. The door frames, both inside and outside, have not been painted yet.			
4		A4 3 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark: The ceiling has not been painted yet. The door frames, both inside and outside, have not been painted yet.			






Check By.

Apirat Khongyuen

Security Supervisor

Fire Exit Door Monthly Checklist on November 2025.

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		B Fl. Basement.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark : The tape covering the door edge has not been peeled off, both inside and outside. The door that opens opens the wrong way. Door frame installed incorrect.			
2		B 8 Fl. Beside R.5004	Fire Exit door panel	✓		
			Fire exit door shock	✓		** Rusty.
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark :			
3		B 8 Fl. Beside R.5021	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark : There are wires hanging down. The door lock is not working. The door doesn't close properly			
4		B 1 Fl. Beside R.5104	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark : The corridor lights from the floor G up to floor 1 are off.			
5		B 1 Fl. Beside R.5119	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark : The corridor lights from the floor G up to floor 1 are off.			
6		B 2 Fl. Beside R.5204	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark : The corridor lights from the floor 1 up to floor 2 are off.			
7		B 2 Fl. Beside R.5219	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark : The corridor lights from the floor 1 up to floor 2 are off.			






8			B 3 FL. Beside R.5304	Fire Exit door panel	✓		
				Fire exit door shock	✓		
				Obstruction	✓		
				Hand pushing fire escape door	✓		
				Floor Number	✓		
				Fire escape staircase lighting		✓	
				Remark : The corridor lights from the floor 2 up to floor 3 are off.			
9			B 3 FL. Beside R.5319	Fire Exit door panel	✓		
				Fire exit door shock	✓		
				Obstruction	✓		
				Hand pushing fire escape door	✓		
				Floor Number	✓		
				Fire escape staircase lighting		✓	
				Remark : The corridor lights from the floor 2 up to floor 3 are off.			
10			B 4 FL. Beside R5404	Fire Exit door panel	✓		
				Fire exit door shock	✓		
				Obstruction	✓		
				Hand pushing fire escape door	✓		
				Floor Number	✓		
				Fire escape staircase lighting		✓	
				Remark : The corridor lights from the floor 3 up to floor 4 are off.			
11			B 4 FL. Beside R5419	Fire Exit door panel	✓		
				Fire exit door shock	✓		
				Obstruction	✓		
				Hand pushing fire escape door	✓		
				Floor Number	✓		
				Fire escape staircase lighting		✓	
				Remark : The corridor lights from the floor 3 up to floor 4 are off.			








Check By.

Apirat: Khongyuen

Security Supervisor

Fire Exit Door Monthly Checklist on November 2025.

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		BLD. C Basement Near restroom	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Kitchen Equipment.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: The door handle doesn't work.			
2		BLD. C Basement Beside F/C Office	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Security Equipment.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: The door lock is not working. The masking tape covering the door edge has not been removed yet.			
3		BLD. C Floor G Opposite 6008	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		Kitchen Equipment.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark:			
4		BLD. C Floor G Near Restaurant	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	There is a vehicle for transporting goods.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: The door lock is not working. The door doesn't close properly			
5		BLD. C Floor 1 Beside 6114	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark:			
6		BLD. C Floor 2 Beside 6215	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark:			

7	 	BLD. C Floor 2 Opposite Spa	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark : The door lock is not working.			
8	 	BLD.C Floor 3 Beside 6305	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark : The door lock is not working.			
9	 	BLD.C Floor 3 Beside 6314	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark : The door lock is not working.			
10	 	BLD.C Floor 4 Beside 6416 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark : The door lock is not working.			
11	 	BLD.C Floor 4 Beside 6405R	Fire Exit door panel	✓		
			Fire exit door shock		✓	The door shock is broken.
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark : The door lock is not working.			

Check By.

Apirat Khongyuen

Security Supervisor

Fire Exit Door Monthly Checklist on December 2026



No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A1 G FL.	Fire Exit door panel		✓	The door is not aligned with its lock, so it cannot be closed or locked.
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: The ceiling shows signs of drilling that have not yet been sealed. The door is not aligned with its lock, so it cannot be closed or locked.			
2		A1 1FL.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	One light went out.
			Remark.			
3		A1 2 FL.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	One light went out.
			Remark.			
4		A1 3 FL.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: The ceiling shows signs of drilling that have not yet been sealed.			

Check By.

Apirat Khongyuen




Security Supervisor

Fire Exit Door Monthly Checklist on December 2026.

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A2 G Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: There are traces of drilling holes in the ceiling. The top edge of the door is not yet finished.			
2		A2 1 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: There are traces of drilling holes in the ceiling. There are traces of a cut in the floor at the bottom of the door.			
3		A2 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: There are traces of drilling holes in the ceiling.			
4		A2 3 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: There are traces of drilling holes in the ceiling.			

Check By. Apirat: Khongyuen Security Supervisor

Fire Exit Door Monthly Checklist on December 2026.



No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A3 G Fl.	Fire Exit door panel		✓	The door is not aligned with its lock, so it cannot be closed or locked.
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: ceiling shows signs of drilling that have not yet been sealed.			
2		A3 1Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark: There are traces of drilling holes in the ceiling.			
3		A3 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark: There are traces of drilling holes in the ceiling.			
4		A3 3 FL.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark: There are traces of drilling holes in the ceiling.			


Check By.

Apirat Khongyuen

Security Supervisor

Fire Exit Door Monthly Checklist on December 2026.

No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		A4 G Fl.	Fire Exit door panel		✓	The door is not aligned with its lock, so it cannot be closed or locked.
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark.The ceiling shows signs of drilling that have not yet been sealed.The door is not aligned with its lock, so it cannot be closed or locked.			
2		A4 1Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark.There are traces of drilling holes in the ceiling.The ceiling has not been painted yet. The door frames, both inside and outside, have not been painted yet.			
3		A4 2 Fl.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark.There are traces of drilling holes in the ceiling.The ceiling has not been painted yet. The door frames, both inside and outside, have not been painted yet.			
4		A4 3 FL.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	














Remark.The ceiling has not been painted yet. The door frames, both inside and outside, have not been painted yet. One of the lights illuminating the hallway from the second floor to the third floor is out.




Check By.



Apirat Khongyuen

Security Supervisor

Fire Exit Door Monthly Checklist on December 2026.





No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1	   	B FL. Basement.	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark : The tape covering the door edge has not been peeled off, both inside and outside. The door that opens opens the wrong way. Door frame installed incorrect.			
2	  	B G FL. Beside R.5004	Fire Exit door panel	✓		
			Fire exit door shock	✓		** Rusty.
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark : No cover for the wiring box			
3	     	B G FL. Beside R.5021	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	HK Equipment
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
			Remark : There are wires hanging down. The door lock is not working. The door doesn't close properly			
4	 	B 1 FL. Beside R.5104	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
5	 	B 1 FL. Beside R.5119	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting		✓	
6		B 1 FL. Beside R.5119	Remark : The corridor lights from the floor G up to floor 1 are off.			
			Fire Exit door panel	✓		

7			B 2 FL. Beside R.5204	Fire exit door shock	✓		
				Obstruction	✓		
				Hand pushing fire escape door	✓		
				Floor Number	✓		
				Fire escape staircase lighting	✓		
	Remark : No cover for the wiring box						
			B 2 FL. Beside R.5219	Fire Exit door panel	✓		
				Fire exit door shock	✓		
		Obstruction		✓			
		Hand pushing fire escape door		✓			
		Floor Number		✓			
		Fire escape staircase lighting			✓		
Remark : The corridor lights from the floor 1 up to floor 2 are off. No cover for the wiring box							

8		B 3 FL. Beside R.5304	<table border="1"> <tr><td>Fire Exit door panel</td><td>✓</td><td></td><td></td></tr> <tr><td>Fire exit door shock</td><td>✓</td><td></td><td></td></tr> <tr><td>Obstruction</td><td>✓</td><td></td><td></td></tr> <tr><td>Hand pushing fire escape door</td><td>✓</td><td></td><td></td></tr> <tr><td>Floor Number</td><td>✓</td><td></td><td></td></tr> <tr><td>Fire escape staircase lighting</td><td>✓</td><td></td><td></td></tr> <tr><td colspan="4">Remark : No cover for the wiring box</td></tr> </table>	Fire Exit door panel	✓			Fire exit door shock	✓			Obstruction	✓			Hand pushing fire escape door	✓			Floor Number	✓			Fire escape staircase lighting	✓			Remark : No cover for the wiring box			
Fire Exit door panel	✓																														
Fire exit door shock	✓																														
Obstruction	✓																														
Hand pushing fire escape door	✓																														
Floor Number	✓																														
Fire escape staircase lighting	✓																														
Remark : No cover for the wiring box																															
9		B 3 FL. Beside R.5319	<table border="1"> <tr><td>Fire Exit door panel</td><td>✓</td><td></td><td></td></tr> <tr><td>Fire exit door shock</td><td>✓</td><td></td><td></td></tr> <tr><td>Obstruction</td><td>✓</td><td></td><td></td></tr> <tr><td>Hand pushing fire escape door</td><td>✓</td><td></td><td></td></tr> <tr><td>Floor Number</td><td>✓</td><td></td><td></td></tr> <tr><td>Fire escape staircase lighting</td><td></td><td>✓</td><td></td></tr> <tr><td colspan="4">Remark : The corridor lights from the floor 2 up to floor 3 are off.No cover for the wiring box</td></tr> </table>	Fire Exit door panel	✓			Fire exit door shock	✓			Obstruction	✓			Hand pushing fire escape door	✓			Floor Number	✓			Fire escape staircase lighting		✓		Remark : The corridor lights from the floor 2 up to floor 3 are off.No cover for the wiring box			
Fire Exit door panel	✓																														
Fire exit door shock	✓																														
Obstruction	✓																														
Hand pushing fire escape door	✓																														
Floor Number	✓																														
Fire escape staircase lighting		✓																													
Remark : The corridor lights from the floor 2 up to floor 3 are off.No cover for the wiring box																															
10		B 4 FL. Beside R5404	<table border="1"> <tr><td>Fire Exit door panel</td><td>✓</td><td></td><td></td></tr> <tr><td>Fire exit door shock</td><td>✓</td><td></td><td></td></tr> <tr><td>Obstruction</td><td>✓</td><td></td><td></td></tr> <tr><td>Hand pushing fire escape door</td><td>✓</td><td></td><td></td></tr> <tr><td>Floor Number</td><td>✓</td><td></td><td></td></tr> <tr><td>Fire escape staircase lighting</td><td>✓</td><td></td><td></td></tr> <tr><td colspan="4">Remark : The corridor lights from the floor 3 up to floor 4 are off.</td></tr> </table>	Fire Exit door panel	✓			Fire exit door shock	✓			Obstruction	✓			Hand pushing fire escape door	✓			Floor Number	✓			Fire escape staircase lighting	✓			Remark : The corridor lights from the floor 3 up to floor 4 are off.			
Fire Exit door panel	✓																														
Fire exit door shock	✓																														
Obstruction	✓																														
Hand pushing fire escape door	✓																														
Floor Number	✓																														
Fire escape staircase lighting	✓																														
Remark : The corridor lights from the floor 3 up to floor 4 are off.																															
11		B 4 FL. Beside R5419	<table border="1"> <tr><td>Fire Exit door panel</td><td>✓</td><td></td><td></td></tr> <tr><td>Fire exit door shock</td><td>✓</td><td></td><td></td></tr> <tr><td>Obstruction</td><td>✓</td><td></td><td></td></tr> <tr><td>Hand pushing fire escape door</td><td>✓</td><td></td><td></td></tr> <tr><td>Floor Number</td><td>✓</td><td></td><td></td></tr> <tr><td>Fire escape staircase lighting</td><td></td><td>✓</td><td></td></tr> <tr><td colspan="4">Remark : The corridor lights from the floor 3 up to floor 4 are off.</td></tr> </table>	Fire Exit door panel	✓			Fire exit door shock	✓			Obstruction	✓			Hand pushing fire escape door	✓			Floor Number	✓			Fire escape staircase lighting		✓		Remark : The corridor lights from the floor 3 up to floor 4 are off.			
Fire Exit door panel	✓																														
Fire exit door shock	✓																														
Obstruction	✓																														
Hand pushing fire escape door	✓																														
Floor Number	✓																														
Fire escape staircase lighting		✓																													
Remark : The corridor lights from the floor 3 up to floor 4 are off.																															
<table border="1"> <tr> <td>Check By.</td> <td>Apirat Khongyuen</td> <td>Security Supervisor</td> </tr> </table>				Check By.	Apirat Khongyuen	Security Supervisor																									
Check By.	Apirat Khongyuen	Security Supervisor																													

Fire Exit Door Monthly Checklist on December 2026.						
No	Picture	Building/ Floor	List check	Status		Remark
				Normal	Abnormal	
1		BLD. C Basement Near Restroom	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Kitchen Equipment.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark : The door handle doesn't work.			
2		BLD. C Basement Beside F/C Office	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction		✓	Security Equipment.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark : The door lock is not working. The masking tape covering the door edge has not been removed yet.			
3		BLD. C Floor G Opposite 6008	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark :			
4		BLD.C Floor G Near Restaurant	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark : There were wires hanging down, and the door was off the edge, not closing properly.			
5		BLD.C Floor 1 Beside 6114 L	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark :			
6		BLD.C Floor 2 Beside 6215	Fire Exit door panel	✓		
			Fire exit door shock	✓		
			Obstruction	✓		No Obstructions.
			Hand pushing fire escape door	✓		
			Floor Number	✓		
			Fire escape staircase lighting	✓		
			Remark :			

Remark :

7	 	BLD. C Floor 2 Opposite Spa	Fire Exit door panel ✓ Fire exit door shock ✓ Obstruction ✓ No Obstructions. Hand pushing fire escape door ✓ Floor Number ✓ Fire escape staircase lighting ✓ Remark : The door lock is not working.
8	 	BLD.C Floor 3 Beside 6305	Fire Exit door panel ✓ Fire exit door shock ✓ Obstruction ✓ No Obstructions. Hand pushing fire escape door ✓ Floor Number ✓ Fire escape staircase lighting ✓ Remark : Door was off the edge, not closing properly.
9	 	BLD.C Floor 3 Beside 6314	Fire Exit door panel ✓ Fire exit door shock ✓ Obstruction ✓ No Obstructions. Hand pushing fire escape door ✓ Floor Number ✓ Fire escape staircase lighting ✓ Remark : The door lock is not working.
10		BLD.C Floor 4 Beside 6414 L	Fire Exit door panel ✓ Fire exit door shock ✓ Obstruction ✓ No Obstructions. Hand pushing fire escape door ✓ Floor Number ✓ Fire escape staircase lighting ✓ Remark : The door lock is not working.
11		BLD.C Floor 4 Beside 6405R	Fire Exit door panel ✓ Fire exit door shock ✓ Obstruction ✓ No Obstructions. Hand pushing fire escape door ✓ Floor Number ✓ Fire escape staircase lighting ✓ Remark : The door lock is not working.
Check By. Aplrat Khongyuen Security Supervisor			