

ภาคผนวกที่ 3 รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม
(ตั้งแต่เดือน กรกฎาคม - ธันวาคม 2568)

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



บริษัท วิศวกรรมเคมี จำกัด
Thai Chemical & Engineering Co., Ltd.

จัดทำที่ : บ.วิศวกรรมเคมี จำกัด

วันที่ 15 ตุลาคม 2568

บริษัท หั่วหิน วิลเลจ จำกัด (โรงแรมอนันตราหั่วหิน)

43/1 ถนน เพชรเกษม ซ้ำมาฮ หั่วหิน

จ.ประจวบคีรีขันธ์ 77110

เรื่อง รายงานผลวิเคราะห์คุณภาพน้ำประจำเดือน กันยายน 2568

เรียน คุณโอเรเลียง ชีมี้อง

เอกสารแนบ ผลวิเคราะห์คุณภาพน้ำประจำเดือน

ตามที่บริษัท วิศวกรรมเคมี จำกัด ได้รับมอบหมายให้เก็บตัวอย่างน้ำ เพื่อทำการวิเคราะห์คุณภาพน้ำภายในโรงแรม และระบบหล่อเย็น ที่โรงแรม อนันตรา รีสอร์ท แอนด์ สปา หั่วหิน โดยทำการเก็บตัวอย่างน้ำประจำเดือน กันยายน 2568 ตั้งแต่วันที่ 29 กันยายน 2568 ตัวอย่างน้ำดังนี้

ผลวิเคราะห์เชื้อในระบบ

ตัวอย่างน้ำ	Legionella CFU/Liter	Legionella CFU/ml	Total Coliform	มาตรฐาน Total Coliform	E.Coli	มาตรฐาน E.Coli
1.) ป่อน้ำดิบ	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
2.) บ่อประปา 5 เหลี่ยม	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
3.) เครื่องทำน้ำแข็ง จุด 1	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
4.) เครื่องทำน้ำแข็ง จุด 2	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
5.) เครื่องทำน้ำแข็ง จุด 3	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
6.) น้ำเย็นห้องพักแรก 709	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
7.) น้ำร้อนห้องพักแรก 709	1000	10	< 2	< 2.2	Negative	Negative
8.) น้ำประปาห้องครัว (Main)	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
9.) น้ำประปาห้องครัว (Sea Fire Salt)	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
10.) ถาด Cooling	600	0.6	33	< 2.2	7.8	Negative
11.) Main Pool	1000	10	< 2	<10	Negative	Negative
12.) Lagoon Pool	Not Detected	Not Detected	< 2	<10	Negative	Negative

“สร้างความพึงพอใจให้ลูกค้า พัฒนาคุณภาพบริการและผลิตภัณฑ์ สร้างสรรค์บุคลากร”

1048/2 ถนนสุขุมวิท 66/1 แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพมหานคร 10260 Tel : (66) 0 2744 9911 Fax : (66) 0 2393 0165
1048/2 Sukhumvit 66/1 Road, Prakanong Tai, Prakanong, Bangkok 10260 www.tcesolutions.com E-mail : contact@tcesolutions.com

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



บริษัท วิศวกรรมเคมี จำกัด

Thai Chemical & Engineering Co., Ltd.

ระดับความรุนแรงของเชื้อ Legionella

CFU/ml			ระดับความ น่ากังวล	สิ่งที่ควรปฏิบัติ
น้ำจากหอหล่อเย็น Cooling Tower	น้ำสำหรับ อุปโภค / บริโภค	เครื่องทำความชื้น / เครื่องทำให้เกิดหมอก		
< 1	-	-	ต่ำ	ทบทวนแผนการบำรุงรักษา ให้มีการปฏิบัติอยู่เป็นประจำ
1 – 9	< 1	-	น้อย	วิเคราะห์ติดตามผลอย่าง ต่อเนื่อง
10 - 99	1 – 9	<1	ปานกลาง	ทบทวนและตรวจลักษณะ ของอาคารที่อาจเสี่ยงต่อการ ติดเชื้อ
100 - 999	10 – 99	1 – 9	ค่อนข้างสูง	ทำความสะอาดระบบโดยใช้ สารเคมีที่มีความสามารถในการ ฆ่าเชื้อจุลินทรีย์
≥1,000	>100	>10	มีความรุนแรงสูง	ใช้สารเคมีซึ่งมีความสามารถ ฆ่าเชื้อจุลินทรีย์ชนิดนี้ ใน กระบวนการทำความสะอาด โดยทันที

“สร้างความพึงพอใจให้ลูกค้า พัฒนาคุณภาพบริการและผลิตภัณฑ์ สร้างสรรค์บุคลากร”

1048/2 ถนนสุขุมวิท 66/1 แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพฯ 10260 Tel : (66) 0 2744 9911 Fax : (66) 0 2393 0165
1048/2 Sukhumvit 66/1 Road, Prakanong Tai, Prakanong, Bangkok 10260 www.tcesolutions.com E-mail : contact@tcesolutions.com

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6361089

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5339/68 = ป่อน้ำดื่ม
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701065
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.

Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 1-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

6062802
Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was/were drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6361088

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5340/68 = บ่อประปา 5 เหลี่ยม
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701066
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.
Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 1-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

6062801
Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was/were drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6361087

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5341/68 = เครื่องทำน้ำแข็ง จุด 1
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701067
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.
Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 1-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6361086

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5342/68 = เครื่องทำน้ำแข็ง จุด 2
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701068
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.

Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 1-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liable for the veracity or lack thereof of such information.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6361085

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5343/68 = เครื่องทำน้ำแข็ง จุด 3
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701069
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.
Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 7-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

6062798
*Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was/were drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited | Laboratory Services: 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6361084

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5344/68 = น้ำเย็นห้องรับแขก No.709
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701070
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.

Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 1-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liable for the veracity or lack thereof of such information.

6062797

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.

Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 583 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1097/43

Test Report 6361083

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5345/68 = น้ำร้อนห้องรับแขก No.709
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701071
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.

Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 1-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	1,000	CFU/1000mL

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

6062796
Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) were said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6361079

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5349/68 = น้ำประปาห้องครัวจุด 1 (Main)
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701075
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.

Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 1-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

"Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information."

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +86 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6361078

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5350/68 = น้ำประปาห้องครัวจุด 2 (Sea Fire Salt)
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701076
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.

Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 1-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

6062791
Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result of this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was/were drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6361082

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5346/68 = ภาต Cooling
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701072
Sample Condition : Water appears yellowish contained in a glass bottle sealed with a plastic lid and kept at a cool temperature. Sediment is showing at the bottom of the bottle.

Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 1-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	600	CFU/1000mL

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.

Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was/were drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) were said to be extracted.

6062795

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6361081

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5347/68 = Main Pool
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701073
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.Sediment is showing at the bottom of the bottle.

Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 1-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	1,000	CFU/1000mL

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.

Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited | Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน กรกฎาคม ถึง กันยายน 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6361080

Date : 15-Oct-2025

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.5348/68 = Lagoon Pool
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6701074
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.
Qty.Submitted : 1 bottle x 1L
Date Received : 30-Sep-2025 Date Commenced : 1-Oct-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per 1000mL

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

*Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.

Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

6062793

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 58, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2568



บริษัท วิศวกรรมเคมี จำกัด
Thai Chemical & Engineering Co., Ltd.

จัดทำที่ : บ.วิศวกรรมเคมี จำกัด

วันที่ 6 มกราคม 2569

บริษัท หัวหิน วิลเลจ จำกัด (โรงแรมอนันตราหัวหิน)

43/1 ถนน เพชรเกษม อำเภอ หัวหิน

จ.ประจวบคีรีขันธ์ 77110

เรื่อง รายงานผลวิเคราะห์คุณภาพน้ำประจำเดือน ธันวาคม 2568

เรียน คุณโอเรเลียง ชีมีอง

เอกสารแนบ ผลวิเคราะห์คุณภาพน้ำประจำเดือน

ตามที่บริษัท วิศวกรรมเคมี จำกัด ได้รับมอบหมายให้เก็บตัวอย่างน้ำ เพื่อทำการวิเคราะห์คุณภาพน้ำภายในโรงแรม และระบบหล่อเย็น ที่โรงแรม อนันตรา รีสอร์ท แอนด์ สปา หัวหิน โดยทำการเก็บตัวอย่างน้ำประจำเดือน ธันวาคม 2568 ตั้งแต่วันที่ 22 ธันวาคม 2568 ตัวอย่างน้ำดังนี้

ผลวิเคราะห์เชื้อในระบบ

ตัวอย่างน้ำ	Legionella CFU/Liter	Legionella CFU/ml	Total Coliform	มาตรฐาน Total Coliform	E.Coli	มาตรฐาน E.Coli
1.) ป่อน้ำดิบ	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
2.) ป่อประปา 5 เหลี่ยม	200	0.2	< 2	< 2.2	Negative	Negative
3.) เครื่องทำน้ำแข็ง จุด 1	600	0.6	< 2	< 2.2	Negative	Negative
4.) เครื่องทำน้ำแข็ง จุด 2	1000	10	< 2	< 2.2	Negative	Negative
5.) เครื่องทำน้ำแข็ง จุด 3	1000	10	< 2	< 2.2	Negative	Negative
6.) น้ำเย็นห้องพักแขก 600	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
7.) น้ำร้อนห้องพักแขก 600	1000	10	< 2	< 2.2	Negative	Negative
8.) น้ำประปาห้องครัว (Main)	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
9.) น้ำประปาห้องครัว (Sea Fire Salt)	Not Detected	Not Detected	< 2	< 2.2	Negative	Negative
10.) ถาด Cooling	Not Detected	Not Detected	33	< 2.2	7.8	Negative
11.) Main Pool	100	0.1	< 2	<10	Negative	Negative
12.) Lagoon Pool	Not Detected	Not Detected	< 2	<10	Negative	Negative

“สร้างความพึงพอใจให้ลูกค้า พัฒนาคุณภาพบริการและผลิตภัณฑ์ สร้างสรรค์บุคลากร”

1048/2 ถนนสุขุมวิท 66/1 แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพฯ 10260 Tel : (66) 0 2744 9911 Fax : (66) 0 2393 0165

1048/2 Sukhumvit 66/1 Road, Prakanong Tai, Prakanong, Bangkok 10260 www.tcesolutions.com E-mail : contact@tcesolutions.com

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2568



บริษัท วิศวกรรมเคมี จำกัด
Thai Chemical & Engineering Co., Ltd.

ระดับความรุนแรงของเชื้อ Legionella

CFU/ml			ระดับความ น่ากังวล	สิ่งที่ควรปฏิบัติ
น้ำจากหอหล่อเย็น Cooling Tower	น้ำสำหรับ อุปโภค / บริโภค	เครื่องทำความเย็น / เครื่องทำให้เกิดหมอก		
< 1	-	-	ต่ำ	ทบทวนแผนการบำรุงรักษา ให้มีการปฏิบัติเป็นประจำ
1 – 9	< 1	-	น้อย	วิเคราะห์ติดตามผลอย่าง ต่อเนื่อง
10 - 99	1 – 9	<1	ปานกลาง	ทบทวนและตรวจลักษณะ ของอาคารที่อาจเสี่ยงต่อการ ติดเชื้อ
100 - 999	10 – 99	1 – 9	ค่อนข้างสูง	ทำความสะอาดระบบโดยใช้ สารเคมีที่มีความสามารถในการ ฆ่าเชื้อจุลินทรีย์
≥1,000	>100	>10	มีความรุนแรงสูง	ใช้สารเคมีซึ่งมีความสามารถ ฆ่าเชื้อจุลินทรีย์ชนิดนี้ ใน กระบวนการทำความสะอาด โดยทันที

“สร้างภาพพจน์ให้ลูกค้า พัฒนาคุณภาพบริการและผลิตภัณฑ์ สร้างสรรค์บุคลากร”

1048/2 ถนนสุขุมวิท 66/1 แขวงพระโขนงใต้ เขตพระโขนง กรุงเทพฯ 10260 Tel : (66) 0 2744 9911 Fax : (66) 0 2393 0165
1048/2 Sukhumvit 66/1 Road, Prakanong Tai, Prakanong, Bangkok 10260 www.tcesolutions.com E-mail : contact@tcesolutions.com

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6430134

Date : 6-Jan-2026

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.7194/68 = ป่อน้ำเค็ม
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6782073
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.Suspended particulate matter showing.
Qty.Submitted : 1 bottle x 1L
Date Received : 23-Dec-2025 Date Commenced : 24-Dec-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per Liter

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

"Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information."

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited | Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6430133

Date : 6-Jan-2026

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.7195/68 = ปอประปา 5 เหลี่ยม
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6782074
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.
Qty.Submitted : 1 bottle x 1L
Date Received : 23-Dec-2025 Date Commenced : 24-Dec-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	200	CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

6131846
Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liable for the veracity or lack thereof of such information.
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6430132

Date : 6-Jan-2026

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.7196/68 = เครื่องทำน้ำแข็ง จด 1
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6782075
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature. Sediment is showing at the bottom of the bottle

Qty. Submitted : 1 bottle x 1L
Date Received : 23-Dec-2025 Date Commenced : 24-Dec-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	600	CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6430131

Date : 6-Jan-2026

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.7197/68 = เครื่องทำน้ำแข็ง จด 2
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6782076
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature. Sediment is showing at the bottom of the bottle
Qty. Submitted : 1 bottle x 1L
Date Received : 23-Dec-2025 Date Commenced : 24-Dec-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	1,000	CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.

Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6430130

Date : 6-Jan-2026

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.7198/68 = เครื่องทำน้ำแข็ง จด 3
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6782077
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.Sediment is showing at the bottom of the bottle
Qty.Submitted : 1 bottle x 1L
Date Received : 23-Dec-2025 Date Commenced : 24-Dec-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	1,000	CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

6131843
"Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information."
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.
Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.
WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was/were drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 583 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6430129

Date : 6-Jan-2026

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.7199/68 = น้ำเย็นห้องรับแขก No.600
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6782078
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.

Qty.Submitted : 1 bottle x 1L
Date Received : 23-Dec-2025 Date Commenced : 24-Dec-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per Liter

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

"Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such Information."

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.

Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited | Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 683 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6430128

Date : 6-Jan-2026

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.7200/68 = น้ำร้อนห้องรับแขก No.600
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6782079
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.

Qty.Submitted : 1 bottle x 1L
Date Received : 23-Dec-2025 Date Commenced : 24-Dec-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	1,000	CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

"Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information."

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.

Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 583 05 41 www.sgs.com

Member of the SGS Group

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6430124

Date : 6-Jan-2026

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.7204/68 = น้ำประปาห้องครัว จต1
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6782083
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.
Qty.Submitted : 1 bottle x 1L
Date Received : 23-Dec-2025 Date Commenced : 24-Dec-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per Liter

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

"Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liable for the veracity or lack thereof of such Information."

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

รายงานผลวิเคราะห์คุณภาพน้ำของโรงแรม ประจำเดือน ตุลาคม ถึง ธันวาคม 2568



ISO/IEC 17025
Accreditation No.1007/43

Test Report 6430123

Date : 6-Jan-2026

Page 1 of 1

Client : Hua Hin Village Co.,Ltd (Anantara Resort & Spa)
43/1 Phetkasem Rd,
Hua Hin, Prachuap Khiri Khan 77110 Thailand

The following sample(s) was/were submitted and identified by client as:

Sample Name : P.7205/68 = น้ำประปาห้องครัว จุด2
Sample Description : Water

The following sample(s) was/were identified by SGS as:

SGS Sample No. : 6782084
Sample Condition : Water appears transparent contained in glass bottle sealed with plastic lid and kept at a cool temperature.

Qty.Submitted : 1 bottle x 1L
Date Received : 23-Dec-2025 Date Commenced : 24-Dec-2025

Test Items	Method	Results	Units
<i>Legionella spp.</i>	ISO 11731 : 2017	Not detected**	Per Liter

Remark: ** Limit of detection = 100 CFU/Liter

Signed for and on behalf of
SGS (Thailand) Ltd.

Jirapan Vilaipol
Microbiology Laboratory Manager

***** End of Report *****

Any holder of this document is advised that should client or third party information be supplied with respect to the goods or sample, SGS may, at its discretion, attached or indicate such information to the report but SGS makes no warranties or accepts no liability for the veracity or lack thereof of such information.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request.

Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Publish or advertisement of the result or this document is prohibited, unless prior written approval of the Company.

Unless otherwise stated the results shown in this test report refer only to the sample(s) received and such sample(s) are retained for 15 days only.

WARNING: The sample(s) to which the findings recorded herein (the "Findings") relate was(were) drawn and / or provided by the Client or by a third party acting at the Client's direction. The Findings constitute no warranty of the sample's representativeness of any goods and strictly relate to the sample(s). The Company accepts no liability with regard to the origin or source from which the sample(s) is/are said to be extracted.

SGS (Thailand) Limited Laboratory Services 10, 10/1 - 4 and 12 Soi Rama III S. 59, Chong Nonsi, Yan Nawa, Bangkok 10120
t +66 (0)2 883 05 41 www.sgs.com

Member of the SGS Group