

Wing 4

Comnatz(Thailand) Co., Ltd.

888, 2nd Fl., M. Srinakarin Road.
Samrong Nua, Muang Samutprakarn
Samutprakarn 10270 THAILAND

Phone +662 361 3700-3

Fax +662 361 3704-5

Comnatz

Together - We Can Do It

**JW MARRIOTT.**
KHAO LAKComnatz(Thailand) Co., Ltd.
888 2nd Fl. M. Srinakharin Road. Samrong Nua, Muang Samutprakarn
Samutprakarn 10270 THAILAND
Phone +662 361 3700-3
Fax +662 361 3704-5**Control Panel Test Report**

Quarterly inspection, visual and function check

Customer :	JW MARRIOTT	Location :	Khaolak
Panel No :	C4 WING 4	Panel name :	Sinteso
Room :	C4 ELECTRICAL RM.	Panel model :	FC2020

General:

Item	Description	Normal	Abnormal	Remark
1	Panel Secured to Wall	☒	☐	
2	Door Mounted Correctly	☒	☐	
3	Hinges Installed Correctly	☒	☐	
4	Cable Entry Correct	☒	☐	
5	Lock Installed Correctly	☒	☐	
6	Viewing Window Installed Correctly	☒	☐	
7	Viewing Window Clean	☒	☐	

Power Supply:

Item	Description	Normal	Abnormal	Remark
1	Mains Cable Connected Correctly	☒	☐	
2	Mains Fuse Correct Type	☒	☐	
3	Surge Protection Correctly Installed	☒	☐	
4	Battery Charger Correctly Installed	☒	☐	
5	Battery Installed Correctly	☒	☐	
6	Battery Connection Free From Corrosion	☒	☐	
7	Battery Charger Output = <u>25.78</u> VDC	☒	☐	
8	Battery Voltage(Full Load)= <u>26.69</u> VDC	☒	☐	

Modules:

Item	Description	Normal	Abnormal	Remark
1	All Modules Installed Correctly	☒	☐	
2	All Modules Programmed Correctly.(DIP)	☒	☐	
3	All Module Indicators Operate Correctly	☒	☐	
4	Display Terminal Installed Correctly	☒	☐	
5	Display Terminal Operates Correctly	☒	☐	
6	Display Terminal Labeled Correctly	☒	☐	
7	Display Terminal LCD Operates Correctly	☒	☐	

Software:

Item	Description	Normal	Abnormal	Remark
1	Main CPU Software Version= 4	☒	☐	
2	Communication Software Version= 4	☒	☐	



Corrnatz(Thailand) Co., Ltd.
688, 2nd Fl./M.55Sinakarin Road SamrongNua, MuangSamutprakarn
Samutprakarn 10270 THAILAND
Phone +662 361 3700-3
Fax +662 361 3704-5

Control Panel Test Report

Quarterly inspection, visual and function check

Customer :	JW MARRIOTT	Location :	Khaolak
Panel No :	C4 WING 4	Panel name :	Sinteso
Room :	C4 ELECTRICAL RM.	Panel model :	FC2020

Control:

Item	Description	Normal	Abnormal	Remark
1	All Control Functions Individually Tested	☒	☐	
2	All Control Functions Operate Correctly	☒	☐	
3	All Control Functions Labeled Correctly	☒	☐	
4	All Control Indications Correct	☒	☐	
5	All Control Switches Individually Tested	☒	☐	
6	All Control Switches Operate Correctly	☒	☐	
7	All Control Switches Labeled Correctly	☒	☐	

Audible/Visual Devices:

Item	Description	Normal	Abnormal	Remark
1	All Audible Devices Individually Tested	☒	☐	
2	All Audible Devices Operated Correctly	☒	☐	
3	All Audible Device Text/Label Correct	☒	☐	
4	All Audible Device Documentation Completed	☒	☐	
5	All Visual Devices Individually Tested	☒	☐	
6	All Visual Devices Operated Correctly	☒	☐	
7	All Visual Device Text/Label Correct	☒	☐	

COMMENT :

Description	Tested by	Witnessed by (Customer)
Company	Comnatz(Thailand)	
Signature		
Name	Samrit Niponvechpaiboon	
Date	17-21/06/2026	

TEST OF COMPLETION REPORT

Visual and Function Check

Project : Preventive maintenance

Location : Electrical C1 WING 4

Panel No : 4

Customer: JW MARRIOTT,KHAOLAK

Model : FC2020-AA

ITEM	Section/Location	Loop. No.	Dev Type	Type	AI	CM	SB	AB	Test Date	Remarks
D4 Building G FL.										
1	4001 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
2	4002 Room	2	FDO241	SD	✓	✓	-	✓	2/27/2026	
3	4003 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
4	4004 Room	2	FDO221	SD	✓	✓	-	✓	2/27/2026	
5	4005 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
6	4006 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
7	Manual Corridor D4 (Front 4006) G FL.	2	FDM221	MCP						
8	4007 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
9	Manual Corridor D4 (Front 4007) G FL.	2	FDM221	MCP						
10	4008 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
11	4009 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
12	4010 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
13	4011 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
14	4012 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
15	D4 PANTRY RM. G FL.	2	FDO241	SD						
16	D4 ELECTRICAL RM.	2	FDO221	SD						
C4 Building G FL.										
17	4014 Room	1	FDO221	SD	✓	✓	-	✓	6/20/2026	
18	4015 Room	1	FDO241	SD	✓	✓	-	✓	2/26/2026	
19	4016 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
20	4017 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
21	4018 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
22	Manual Corridor C4 (Front 4018) G FL.	1	FDM221	MCP						
23	4019 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
24	Manual Corridor C4 (Front 4019) G FL.	1	FDM221	MCP						
25	4020 Room	1	FDO241	SD	✓	✓	-	✓	2/27/2026	
26	4021 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
27	4022 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
28	4023 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
29	C4 PANTRY RM. G FL.	1	FDO241	SD						
30	C4 ELECTRICAL RM.	1	FDO241	SD						
B4 Building G FL.										
31	4024 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
32	4025 Room	1	FDO241	SD	✓	✓	-	✓	2/27/2026	
33	4026 Room	1	FDO221	SD	✓	✓	-	✓	6/20/2026	
34	4027 Room	1	FDO221	SD	✓	✓	-	✓	6/20/2026	
35	Manual Corridor B4 (Front 4027) G FL.	1	FDM221	MCP						
36	4028 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
37	Manual Corridor B4 (Front 4028) G FL.	1	FDM221	MCP						
38	4029 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
39	4030 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
40	4031 Room	1	FDO241	SD	✓	✓	-	✓	2/27/2026	
41	B4 PANTRY RM. G FL.	1	FDO221	SD						
42	B4 ELECTRICAL RM.	1	FDO241	SD						
D4 Building 1st FL.										
43	4102 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
44	4103 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
45	4104 Room	2	FDO241	SD	✓	✓	-	✓	2/27/2026	
46	4105 Room	2	FDO221	SD	✓	✓	-	✓	6/20/2026	
47	4106 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	

TEST OF COMPLETION REPORT

Visual and Function Check

Project : Preventive maintenance

Location : Electrical C1 WING 4

Panel No : 4

Customer: JW MARRIOTT,KHAOLAK

Model : FC2020-AA

ITEM	Section/Location	Loop No.	Dev Type	Type	AI	CM	SB	AB	Test Date	Remarks
D4 Building 1st FL.										
48	Manual Corridor D4 (Front 4106) 1st FL.	2	FDM221	MCP						
49	4107 Room	2	FDO241	SD	✓	✓	-	✓	2/27/2026	
50	Manual Corridor D4 (Front 4107) 1st FL.	2	FDM221	MCP						
51	4108 Room	2	FDO241	SD	✓	✓	-	✓	2/27/2026	
52	4109 Room	2	FDO241	SD	✓	✓	-	✓	2/27/2026	
53	4110 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
54	4111 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
55	D4 PANTRY RM. 1st FL.	2	FDO241	SD						
C4 Building 1st FL.										
56	4114 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
57	4115 Room	1	FDO221	SD	✓	✓	-	✓	6/20/2026	
58	4116 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
59	4117 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
60	4118 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
61	Manual Corridor C4 (Front 4118) 1st FL.	1	FDM221	MCP						
62	4119 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
63	Manual Corridor C4 (Front 4119) 1st FL.	1	FDM221	MCP						
64	4120 Room	1	FDO221	SD	✓	✓	-	✓	6/20/2026	
65	4121 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
66	4122 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
67	4123 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
68	C4 PANTRY RM. 1st FL.	1	FDO241	SD						
B4 Building 1st FL.										
69	4124 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
70	4125 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
71	4125 MAZZ FL. Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
72	4125 High ceiling	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
73	4126 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
74	4126 MAZZ FL. Room	1	FDO221	SD	✓	✓	-	✓	6/20/2026	
75	4126 High ceiling	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
76	4127 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
77	Manual Corridor B4 (Front 4127) 1st FL.	1	FDM221	MCP						
78	4128 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
79	Manual Corridor B4 (Front 4128) 1st FL.	1	FDM221	MCP						
80	4129 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
81	4129 MAZZ FL. Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
82	4129 High ceiling	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
83	4130 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
84	4130 MAZZ FL. Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
85	4130 High ceiling	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
86	4131 Room	1	FDO241	SD	✓	✓	-	✓	6/20/2026	
87	B4 PANTRY RM. 1st FL.	1	FDO241	SD						
D4 Building 2nd FL.										
88	4203 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
89	4204 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
90	4205 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	
91	Manual Corridor D4 (Front 4205) 2nd FL.	2	FDM221	MCP						
92	4208 Room	2	FDO241	SD	✓	✓	-	✓	6/20/2026	

Visual and Function Check

Location : Electrical C1 WING 4

Customer: JW MARRIOTT,KHAOLAK

[illegible]

TEST OF COMPLETION REPORT

Visual and Function Check

Project : Preventive maintenance

Location : Electrical C1 WING 4

Panel No : 4

Customer: JW MARRIOTT,KHAOLAK

Model : FC2020-AA

[illegible]

Al - Alarm Confirmed

CM - Correct Custom Message.

SB - Silent Buzzer Acoustic base

AB - Alarm sounder beacon

Description	Tested by	Witnessed by (Customer)
Company	Comnatz (Thailand)	
Name	Samrit Niponvechpailboon	
Date	17-21/06/2026	

All Day



Control Panel Test Report

Quarterly inspection, visual and function check

Customer :	JW MARRIOTT	Location :	Khaolak
Panel No :	All Day	Panel name :	Cerberus Pro
Room :		Panel model :	FC722

General:

Item	Description	Normal	Abnormal	Remark
1	Panel Secured to Wall	☒	☐	
2	Door Mounted Correctly	☒	☐	
3	Hinges Installed Correctly	☒	☐	
4	Cable Entry Correct	☒	☐	
5	Lock Installed Correctly	☒	☐	
6	Viewing Window Installed Correctly	☒	☐	
7	Viewing Window Clean	☒	☐	

Power Supply:

Item	Description	Normal	Abnormal	Remark
1	Mains Cable Connected Correctly	☒	☐	
2	Mains Fuse Correct Type	☒	☐	
3	Surge Protection Correctly Installed	☒	☐	
4	Battery Charger Correctly Installed	☒	☐	
5	Battery Installed Correctly	☒	☐	
6	Battery Connection Free From Corrosion	☒	☐	
7	Battery Charger Output = <u>25.59</u> VDC	☒	☐	
8	Battery Voltage(Full Load)= <u>26.32</u> VDC	☒	☐	

Modules:

Item	Description	Normal	Abnormal	Remark
1	All Modules Installed Correctly	☒	☐	
2	All Modules Programmed Correctly.(DIP)	☒	☐	
3	All Module Indicators Operate Correctly	☒	☐	
4	Display Terminal Installed Correctly	☒	☐	
5	Display Terminal Operates Correctly	☒	☐	
6	Display Terminal Labeled Correctly	☒	☐	
7	Display Terminal LCD Operates Correctly	☒	☐	

Software:

Item	Description	Normal	Abnormal	Remark
1	Main CPU Software Version= 5	☒	☐	
2	Communication Software Version= 5	☒	☐	



Together - We Can Do It



JW MARRIOTT
KHAO LAK

Comnatz(Thailand) Co., Ltd
888, 2nd Fl. M.65 Sakarin Road Samrongthua, Muang Samutprakarn
Samutprakarn 10270 THAILAND
Phone : +662 361 3700-3
Fax : +662 361 3704-6

Control Panel Test Report

Quarterly inspection, visual and function check

Customer : JW MARRIOTT	Location : Khaolak
Panel No : All Day	Panel name : Cerberus Pro
Room :	Panel model : FC722

Control:

Item	Description	Normal	Abnormal	Remark
1	All Control Functions Individually Tested	☒	☐	
2	All Control Functions Operate Correctly	☒	☐	
3	All Control Functions Labeled Correctly	☒	☐	
4	All Control Indications Correct	☒	☐	
5	All Control Switches Individually Tested	☒	☐	
6	All Control Switches Operate Correctly	☒	☐	
7	All Control Switches Labeled Correctly	☒	☐	

Audible/Visual Devices:

Item	Description	Normal	Abnormal	Remark
1	All Audible Devices Individually Tested	☒	☐	
2	All Audible Devices Operated Correctly	☒	☐	
3	All Audible Device Text/Label Correct	☒	☐	
4	All Audible Device Documentation Completed	☒	☐	
5	All Visual Devices Individually Tested	☒	☐	
6	All Visual Devices Operated Correctly	☒	☐	
7	All Visual Device Text/Label Correct	☒	☐	

COMMENT :

- Up date Board New (FC722) All day จึงไม่สามารถ Connect กับ ระบบเก่าได้ แต่ยังสามารถส่งสัญญาณ Alarm มาที่ LP Office ได้
- Power Supply Supervision (Power Supply Fail)
- สายสัญญาณถูกตัดทำให้ระบบไม่สามารถใช้งานได้

Description	Tested by	Witnessed by (Customer)
Company	Comnatz(Thailand)	
Signature	<i>Samrit Niponvechpaiboon</i> (for)	
Name	Samrit Niponvechpaiboon	
Date	17-21/06/2026	

TEST OF COMPLETION REPORT

Visual and Function Check

Project : Preventive maintenance

Location : All Day

Panel No : 5

Customer: JW MARRIOTT, KHAOLAK

Model : FC2020-AA

ITEM	Section/Location	Loop. No.	Dev Type	Type	AI	CM	SB	AB	Test Date	Remarks
	ZONE Bd.B Waterfront									
1	ZONE Bd.B Waterfront	1	FDCIO223	O/P						
2	Ansul No.1 Water Front	2	FDCIO223	I/P						
3	Ansul No.2 Water Front	2	FDCIO222	I/P						
4	Ansul No.3 Water Front	2	FDCIO222	I/P						
5	Ansul No.4 Water Front	2	FDCIO222	I/P						
6	Ansul No.5 Water Front	2	FDCIO222	I/P						
7	Ansul No.6 Water Front	2	FDCIO222	I/P						
8	Ansul No.7 Water Front	2	FDCIO222	I/P						
9	CO No.1 Water Front	2	FDCIO222	I/P						
10	CO No.2 Water Front	2	FDCIO222	I/P						
11	CO No.3 Water Front	2	FDCIO222	I/P						
12	CO No.4 Water Front	2	FDCIO222	I/P						
13	Gas Detector	2	FDCI222	I/P						
	ZONE Bestment All day									
14	ZONE Bestment	1	FDCIO223	O/P						
	Building C									
15	ZONE C Building NORTH WING	1	FDCIO223	O/P						
	Building D									
16	ZONE D Building SOUTH WING	1	FDCIO223	O/P						
	Building E Main Kitchen									
17	ZONE Bd.E Main Kitchen	1	FDCIO223	O/P						
18	Corridor NO.1			Smoke						
19	Corridor NO.2			Smoke						
20	Corridor NO.3			Smoke						
21	Corridor NO.4			Smoke						
22	Corridor NO.5			Smoke						
23	Maneger RM.			Smoke						
24	Storage RM.			Smoke						
25	Preparation RM.			Heat						
26	Main Kitchen			Heat						
27	Main Kitchen			Heat						
28	Main Kitchen			Heat						
29	Manual Call Poit			Manual						
30	Manual Call Poit			Manual						
31	Manual Call Poit			Manual						
32	Ansul No.1 Main KIT E	1	FDCI222	I/P						
33	Ansul No.2 Main KIT E	2	FDCI222	I/P						
34	CO No.1 Main KIT E	2	FDCI222	I/P						
35	Gas Detector	2	FDCI222	I/P						
	Building F									
36	ZONE F Building	1	FDCIO223	O/P						
	Pool Bar									
37	Zone 1 Infinity Pool Bar	1	FDCIO223	O/P						
38	Zone 2 Toilet Pool Bar	1	FDCIO223	O/P						
39	Ansul No.1 Pool Bar KIT	2	FDCI222	I/P						
40	CO No.1 Pool KIT	2	FDCI222	I/P						
41	Gas Detector	2	FDCI222	I/P						

Visual and Function Check

Location : All Day

Customer: JW MARRIOTT,KHAOLAK

Model : FC2020-AA

AI - Alarm Confirmed	CM - Correct Custom Message.
SB - Silent Buzzer Acoustic base	AB - Alarm sounder beacon

Description	Tested by	Witnessed by (Customer)
Company	Comnatz (Thailand)	
Name	Samrit Niponvechpaiboon	
Date	17-21/06/2026	

Lobby

Comnatz(Thailand) Co., Ltd.

888, 2nd Fl., M.5 Srinakarin Road.
Samrong Nua, Muang Samutprakarn
Samutprakarn 10270 THAILAND

Phone +662 361 3700-3

Fax +662 361 3704-5



Together - We Can Do It



JW MARRIOTT
KHAO LAK

Comnatz(Thailand) Co., Ltd
888 2nd Fl. 14 ESRinakar Road Samronglue, MuangSamutprakarn
Samutprakarn 10270 THAILAND
Phone +662 361 3704-3
Fax +662 361 3704-5

Control Panel Test Report

Quarterly inspection, visual and function check

Customer : JW MARRIOTT	Location : Khaolak
Panel No : LOBBY	Panel name : Sinteso
Room :	Panel model : FC2020

General:

Item	Description	Normal	Abnormal	Remark
1	Panel Secured to Wall	☒	☐	
2	Door Mounted Correctly	☒	☐	
3	Hinges Installed Correctly	☒	☐	
4	Cable Entry Correct	☒	☐	
5	Lock Installed Correctly	☒	☐	
6	Viewing Window Installed Correctly	☒	☐	
7	Viewing Window Clean	☒	☐	

Power Supply:

Item	Description	Normal	Abnormal	Remark
1	Mains Cable Connected Correctly	☒	☐	
2	Mains Fuse Correct Type	☒	☐	
3	Surge Protection Correctly Installed	☒	☐	
4	Battery Charger Correctly Installed	☒	☐	
5	Battery Installed Correctly	☒	☐	
6	Battery Connection Free From Corrosion	☒	☐	
7	Battery Charger Output = <u>25.83</u> VDC	☒	☐	
8	Battery Voltage(Full Load)= <u>26.41</u> VDC	☒	☐	

Modules:

Item	Description	Normal	Abnormal	Remark
1	All Modules Installed Correctly	☒	☐	
2	All Modules Programmed Correctly.(DIP)	☒	☐	
3	All Module Indicators Operate Correctly	☒	☐	
4	Display Terminal Installed Correctly	☒	☐	
5	Display Terminal Operates Correctly	☒	☐	
6	Display Terminal Labeled Correctly	☒	☐	
7	Display Terminal LCD Operates Correctly	☐	☒	LCD Deteriorate

Software:

Item	Description	Normal	Abnormal	Remark
1	Main CPU Software Version= 4	☒	☐	
2	Communication Software Version= 4	☒	☐	



Control Panel Test Report

Quarterly inspection, visual and function check

Customer : JW MARRIOTT	Location : Khaolak
Panel No : LOBBY	Panel name : Sinteso
Room :	Panel model : FC2020

Control:

Item	Description	Normal	Abnormal	Remark
1	All Control Functions Individually Tested	☒	☐	
2	All Control Functions Operate Correctly	☒	☐	
3	All Control Functions Labeled Correctly	☒	☐	
4	All Control Indications Correct	☒	☐	
5	All Control Switches Individually Tested	☒	☐	
6	All Control Switches Operate Correctly	☒	☐	
7	All Control Switches Labeled Correctly	☒	☐	

Audible/Visual Devices:

Item	Description	Normal	Abnormal	Remark
1	All Audible Devices Individually Tested	☒	☐	
2	All Audible Devices Operated Correctly	☒	☐	
3	All Audible Device Text/Label Correct	☒	☐	
4	All Audible Device Documentation Completed	☒	☐	
5	All Visual Devices Individually Tested	☒	☐	
6	All Visual Devices Operated Correctly	☒	☐	
7	All Visual Device Text/Label Correct	☒	☐	

COMMENT :

LCD Deteriorate

Description	Tested by	Witnessed by (Customer)
Company	Comnatz(Thailand)	
Signature	<i>Nattapin yorabai (For)</i>	
Name	Samrit Niponvechpaiboon	
Date	17-21/06/2026	

Visual and Function Check

Location : LOBBY

Customer: JW MARRIOTT,KHAOLAK

Model : FC2020-AA

AI - Alarm Confirmed	CM - Correct Custom Message.
SB - Silent Buzzer Acoustic base	AB - Alarm sounder beacon

Description	Tested by	Witnessed by (Customer)
Company	Comnatz (Thailand)	
Name	Samrit Niponvechpalboon	
Date	17-21/06/2026	

Loss Prevention

Comnatz(Thailand) Co., Ltd.

888, 2nd Fl., M.5 Srinakarin Road.

Samrong Nua, Muang Samutprakarn

Samutprakarn 10270 THAILAND

Phone +662 361 3700-3

Fax +662 361 3704-5



Control Panel Test Report

Quarterly inspection, visual and function check

Customer :	JW MARRIOTT	Location :	Khaolak
Panel No :	BOH 1-3	Panel name :	Sinteso
Room :	LP	Panel model :	FC2020

General:

Item	Description	Normal	Abnormal	Remark
1	Panel Secured to Wall	☒	☐	
2	Door Mounted Correctly	☒	☐	
3	Hinges Installed Correctly	☒	☐	
4	Cable Entry Correct	☒	☐	
5	Lock Installed Correctly	☒	☐	
6	Viewing Window Installed Correctly	☒	☐	
7	Viewing Window Clean	☒	☐	

Power Supply:

Item	Description	Normal	Abnormal	Remark
1	Mains Cable Connected Correctly	☒	☐	
2	Mains Fuse Correct Type	☒	☐	
3	Surge Protection Correctly Installed	☒	☐	
4	Battery Charger Correctly Installed	☒	☐	
5	Battery Installed Correctly	☒	☐	
6	Battery Connection Free From Corrosion	☒	☐	
7	Battery Charger Output = <u>25.79</u> VDC	☒	☐	
8	Battery Voltage(Full Load)= <u>26.45</u> VDC	☒	☐	

Modules:

Item	Description	Normal	Abnormal	Remark
1	All Modules Installed Correctly	☒	☐	
2	All Modules Programmed Correctly.(DIP)	☒	☐	
3	All Module Indicators Operate Correctly	☒	☐	
4	Display Terminal Installed Correctly	☒	☐	
5	Display Terminal Operates Correctly	☒	☐	
6	Display Terminal Labeled Correctly	☒	☐	
7	Display Terminal LCD Operates Correctly	☒	☐	

Software:

Item	Description	Normal	Abnormal	Remark
1	Main CPU Software Version= 4	☒	☐	
2	Communication Software Version= 4	☒	☐	



Comnatz(Thailand) Co., Ltd
888, 2nd Fl. M 55Rinakarini Road SamrongNua, MuangSamutprakarn
Samutprakarn 10270 THAILAND
Phone +662 361 3700-3
Fax +662 361 3704-5

Control Panel Test Report

Quarterly inspection, visual and function check

Customer : JW MARRIOTT	Location : Khaolak
Panel No : BOH 1-3	Panel name : Sinteso
Room : LP	Panel model : FC2020

Control:

Item	Description	Normal	Abnormal	Remark
1	All Control Functions Individually Tested	☒	☐	
2	All Control Functions Operate Correctly	☒	☐	
3	All Control Functions Labeled Correctly	☒	☐	
4	All Control Indications Correct	☒	☐	
5	All Control Switches Individually Tested	☒	☐	
6	All Control Switches Operate Correctly	☒	☐	
7	All Control Switches Labeled Correctly	☒	☐	

Audible/Visual Devices:

Item	Description	Normal	Abnormal	Remark
1	All Audible Devices Individually Tested	☒	☐	
2	All Audible Devices Operated Correctly	☒	☐	
3	All Audible Device Text/Label Correct	☒	☐	
4	All Audible Device Documentation Completed	☒	☐	
5	All Visual Devices Individually Tested	☒	☐	
6	All Visual Devices Operated Correctly	☒	☐	
7	All Visual Device Text/Label Correct	☒	☐	

COMMENT :

Description	Tested by	Witnessed by (Customer)
Company	Comnatz(Thailand)	
Signature		
Name	Samrit Niponvechpaiboon	
Date	17-21/06/2026	

TEST OF COMPLETION REPORT

Visual and Funtion Check

Project : Preventive maintenance

Location : Loss Prevention

Panel No : 7

Customer: JW MARRIOTT,KHAOLAK

Model : FC2020-AA

ITEM	Section/Location	Loop. No.	Dev Type	Type	AI	CM	SB	AB	Test Date	Remarks
BOH 1										
	BOH 1 - Zone 1	1	FDCIO223	O/P						
1	Manual front Reception			Manual						
2	Reception			Smoke						
3	Training office			Smoke						
4	Training Room#1			Smoke						
5	Training Room#2			Smoke						
6	Manual Traing Room			Manual						
7	Office #1			Smoke						
8	Office #2			Smoke						
9	Uniform			Smoke						
10	Male Toilet #1			Heat						
11	Male locker room #2			Smoke						
12	Male Toilet #3			Smoke						
13	Manual front male toilet			Manual						
14	Corridor #1			Smoke						
15	Corridor #2			Smoke						
16	Corridor #3			Smoke						
	BOH 1 - Zone 2	1	FDCIO223	O/P						
1	Manual LP office			Manual						
2	LP office			Smoke						
3	Manual Kitchen area			Manual						
4	Kitchen area			Heat						
5	Dry			Smoke						
6	Wet			Smoke						
7	Bottle			Smoke						
8	Manual canteen			Manual						
9	Canteen #1			Smoke						
10	Canteen #2			Smoke						
11	Manual front toilet female			Manual						
12	Female Toilet #1			Smoke						
13	Locker Female #2			Heat						
14	Female Toilet #3			Heat						
	BOH 1 - Zone Gas Canteen									
15	Gas Detector	2	FDCI222	I/P						
16	Gas Leak Detector	2	FDCI222	I/P						
BOH 2										
	BOH 2 - Zone 1	1	FDCIO223	O/P						
1	Manual front dirty linen			Manual						
2	Dirty linen			Smoke						
3	Manager			Smoke						
4	Manual front manager			Manual						
5	Laundry #1			Smoke						
6	Laundry #2			Smoke						
7	Laundry #3			Smoke						
8	Clean linen			Smoke						
	BOH 2									
	BOH 2 - Zone 2	1	FDCIO223	O/P						
1	Manual front workshop 4			Manual						
2	Workshop 4			Heat						

TEST OF COMPLETION REPORT

Visual and Function Check

Project : Preventive maintenance

Location : Loss Prevention

Panel No : 7

Customer: JW MARRIOTT,KHAOLAK

Model : FC2020-AA

ITEM	Section/Location	Loop. No.	Dev Type	Type	AI	CM	SB	AB	Test Date	Remarks
	BOH 2									
	BOH 2 - Zone 2	1	FDCIO223	O/P						
3	Manual front workshop 2			Manual						
4	front workshop 2			Heat						
5	Workshop 2			Heat						
6	Workshop 2			Smoke						
7	Workshop 3			Heat						
8	Workshop 3			Smoke						
9	Workshop 3			Smoke						
10	Front workshop 3			Smoke						
11	Storage			Smoke						
12	Chief engineer			Smoke						
13	Engineer in office			Smoke						
14	Manual Front Clinic			Manual						
15	Clinic #1			Smoke						
16	Clinic #2			Smoke						
17	Manual clinic			Manual						
18	Manual MDB room			Manual						
19	MDB room #1			Smoke						
20	MDB room #2			Smoke						
21	Generator room #1			Smoke						
22	Generator room #2			Smoke						
23	Generator room #3			Smoke						
24	Manual Generator room			Manual						
25	Pump room #1			Smoke						
26	Pump room #2			Smoke						
27	Manual front pump room			Manual						
28	Boiler room #1			Heat						
29	Boiler room #2			Heat						
30	Gas Leak Detector Boiler	1	FDCI222	I/P						
	BOH 3									
	BOH 3 - Zone 1	1	FDCIO223	O/P						
1	Manual stair			Manual						
2	Flower room			Smoke						
3	HSKP Office			Smoke						
4	Manual HSKP office			Manual						
5	Manager HSKP			Smoke						
6	HSKP stor 1			Smoke						
7	HSKP stor 2			Smoke						
8	Chiller room No.1			Smoke						
9	Chiller room No.2			Smoke						
10	Chiller room No.3			Smoke						
11	Chiller room No.4			Smoke						
12	Gardener's room (Front)			Smoke						
13	Gardener's room (Back)			Smoke						
	BOH 3 - Zone 2	1	FDCIO223	O/P						
1	Manula stair			Manual						
2	Corridor No.1			Smoke						
3	Corridor No.2			Smoke						
4	Corridor No.3			Smoke						

Visual and Function Check

Model : FC2020-AA

AI - Alarm Confirmed	CM - Correct Custom Message.
SB - Silent Buzzer Acoustic base	AB - Alarm sounder beacon

Description	Tested by	Witnessed by (Customer)
Company	Comnatz (Thailand)	
Name	Samrit Niponvechpalboon	
Date	17-21/06/2026	

Flow Switch & Supervisory Switch

Comnatz(Thailand) Co., Ltd.

888,2nd Fl.,M.5Srinakarin Road.
SamrongNua, MuangSamutprakarn
Samutprakarn 10270 THAILAND

Phone +662 361 3700-3
Fax +662 361 3704-5

Visual and Function Check

Location : ALL Hotel

Customer: JW MARRIOTT,KHAOLAK

Model : FC2020-AA

[illegible]

TEST OF COMPLETION REPORT

Visual and Funtion Check

Project : Preventive maintenance

Location : ALL Hotel

Panel No : 1

Customer: JW MARRIOTT,KHAOLAK

Model : FC2020-AA

ITEM	Section/Location	Loop. No.	Dev Type	Type	AI	CM	SB	AB	Test Date	Remarks
	ALL DAY									
	FLOW SWITCH (ALL DAY)									
1	FLOW SWITCH (ALL DAY)C&F North Wing	1	FDCIO222	I/P						
2	FLOW SWITCH (ALL DAY) B Bd.Waterfront	1	FDCIO222	I/P						
3	FLOW SWITCH(ALL DAY)D&E South Wing	1	FDCIO222	I/P						
4	FLOW SWITCH (Olive PUB)	1	FDCIO222	I/P						
5	FLOW SWITCH (Commissary)	1	FDCIO222	I/P						
	SUPERVISORY VALVE (ALL DAY)									
6	SUP VALVE(ALL DAY) C&F Bd.	1	FDCIO222	I/P						
7	SUP VALVE(ALL DAY) B Bd. Waterfront	1	FDCIO222	I/P						
8	SUP VALVE(ALL DAY) D&E Bd.	1	FDCIO222	I/P						
9	SUP VALVE(Olive PUB)	1	FDCIO222	I/P						
10	SUP VALVE(Commissary)	1	FDCIO222	I/P						
	BOH 1-3									
	FLOW SWITCH BOH									
1	FLOW SWITCH (BOH1)	1	FDCIO222	I/P						
2	FLOW SWITCH (BOH2)	1	FDCIO222	I/P						
3	FLOW SWITCH (BOH3)	1	FDCIO222	I/P						
	SUPERVISORY VALVE BOH									
4	SUPERVISORY VALVE (BOH1)	1	FDCIO222	I/P						
5	SUPERVISORY VALVE (BOH2)	1	FDCIO222	I/P						
6	SUPERVISORY VALVE (BOH3)	1	FDCIO222	I/P						
	LOBBY									
	FLOW SWITCH (LOBBY)									
1	FLOW SWITCH (MULTIPURPOSE AREA)	2	FDCIO222	I/P						
2	FLOW SWITCH (RETAIL SHOP)	2	FDCIO222	I/P						
3	FLOW SWITCH (TOILET&CZAR BAR)	2	FDCIO222	I/P						
4	FLOW SWITCH (MAIN LOBBY)	2	FDCIO222	I/P						
5	FLOW SWITCH (LOWER LOBBY)	2	FDCIO222	I/P						
6	FLOW SWITCH (MEETING RM.&OFFICE)	2	FDCIO222	I/P						
	SUPERVISORY VALVE (LOBBY)									
7	SUP VALVE(MULTIPURPOSE AREA)	2	FDCIO222	I/P						
8	SUP VALVE(RETAIL SHOP)	2	FDCIO222	I/P						
9	SUP VALVE(TOILET&CZAR BAR)	2	FDCIO222	I/P						
10	SUP VALVE(MAIN LOBBY)	2	FDCIO222	I/P						
11	SUP VALVE(LOWER LOBBY)	2	FDCIO222	I/P						
12	SUP VALVE(MEETING RM&OFFICE)	2	FDCIO222	I/P						
	FLOW SWITCH (LOBBY)									
1	FLOW SWITCH (BANQUET)	2	FDCIO222	I/P						
	SUP VALVE(BANQUET)									
2	SUP VALVE(BANQUET)	2	FDCIO222	I/P						

AI - Alarm Confirmed

CM - Correct Custom Message.

SB - Silent Buzzer Acoustic base

AB - Alarm sounder beacon

Description	Tested by	Witnessed by (Customer)
Company	Comnatz (Thailand)	
Name	Samrit Niponvechpaiboon	
Date	17-21/06/2026	

Strobe

Comnatz(Thailand) Co., Ltd.

888,2nd Fl.,M.5Srinakarin Road.
SamrongNua, MuangSamutprakarn
Samutprakarn 10270 THAILAND

Phone +662 361 3700-3
Fax +662 361 3704-5

TEST OF COMPLETION REPORT

Visual and Funtion Check

Project : Preventive maintenance

Location :All wing

Panel No :

Customer: JW MARRIOTT,KHAOLAK

Model : FC2020-AA

ITEM	Section/Location	Active horn		Active flash light		Test Date	Remarks
		Pass	Fail	Pass	Fail		
	WING 1						
	Horn sound & Flash light						
	Front room 1001						
	Front room 1006						
	Front room 1007						
	Front room 1011						
	Front room 1014						
	Front room 1018						
	Front room 1019						
	Front room 1023						
	Front room 1024						
	Front room 1027						
	Front room 1028						
	Front room 1031						
	Front room 1103						
	Front room 1106						
	Front room 1107						
	Front room 1110						
	Front room 1114						
	Front room 1118						
	Front room 1119						
	Front room 1122						
	Front room 1124						
	Front room 1127						
	Front room 1128						
	Front room 1131						
	Front room 1205						
	Front room 1208						
	Front room 1210						
	Front room 1216						
	Front room 1217						
	Front room 1220						
	Front room 1222						
	WING 2						
	Horn sound & Flash light						
	Front room 2002						
	Front room 2006						
	Front room 2007						
	Front room 2011						
	Front room 2015						
	Front room 2018						
	Front room 2019						
	Front room 2022						
	Front room 2024						
	Front room 2027						
	Front room 2028						
	Front room 2031						
	Front room 2103						
	Front room 2106						
	Front room 2107						
	Front room 2118						

TEST OF COMPLETION REPORT

Visual and Function Check

Project : Preventive maintenance

Location :All wing

Panel No :

Customer: JW MARRIOTT,KHAOLAK

Model : FC2020-AA

ITEM	Section/Location	Active horn		Active flash light		Test Date	Remarks
		Pass	Fail	Pass	Fail		
	WING 2						
	Front room 2119						
	Front room 2122						
	Front room 2124						
	Front room 2127						
	Front room 2128						
	Front room 2131						
	Front room 2203						
	Front room 2208						
	Front room 2210						
	Front room 2215						
	Front room 2217						
	Front room 2220						
	WING 3						
	Horn sound & Flash light						
	Front room 3002						
	Front room 3006						
	Front room 3007						
	Front room 3011						
	Front room 3015						
	Front room 3018						
	Front room 3019						
	Front room 3022						
	Front room 3024						
	Front room 3027						
	Front room 3028						
	Front room 3031						
	Front room 3103						
	Front room 3106						
	Front room 3107						
	Front room 3110						
	Front room 3114						
	Front room 3118						
	Front room 3119						
	Front room 3122						
	Front room 3124						
	Front room 3127						
	Front room 3128						
	Front room 3130						
	Front room 3203						
	Front room 3205						
	Front room 3208						
	Front room 3210						
	Front room 3215						
	Front room 3217						
	Front room 3220						
	Front room 3222						
	WING 4						
	Horn sound & Flash light						
	Front room 4002						
	Front room 4006						

TEST OF COMPLETION REPORT

Visual and Function Check

Project : Preventive maintenance

Location : All wing

Panel No :

Customer: JW MARRIOTT, KHAOLAK

Model : FC2020-AA

ITEM	Section/Location	Active horn		Active flash light		Test Date	Remarks
		Pass	Fail	Pass	Fail		
	WING 4						
	Front room 4007						
	Front room 4011						
	Front room 4015						
	Front room 4018						
	Front room 4019						
	Front room 4022						
	Front room 4025						
	Front room 4027						
	Front room 4028						
	Front room 4030						
	Front room 4103						
	Front room 4106						
	Front room 4107						
	Front room 4110						
	Front room 4115						
	Front room 4118						
	Front room 4119						
	Front room 4122						
	Front room 4124						
	Front room 4127						
	Front room 4128						
	Front room 4131						
	Front room 4203						
	Front room 4205						
	Front room 4208						
	Front room 4210						
	Front room 4215						
	Front room 4218						
	Front room 4220						
	Front room 4222						
	WING 5						
	Horn sound & Flash light						
	Front room 5002						
	Front room 5007						
	Front room 5009						
	Front room 5103						
	Front room 5106						
	Front room 5109						
	Front room 5206						
	SPA						
	Front Relax room						
	Relax room						
	Front Reception						
	Reception room						
	Front spa 1 room						
	Front spa 3 room						
	Front spa 6001 room						
	BOH 1-3						
	Horn sound & Flash light						
	BOH 1						
	BOH 2						

Picture operations report


Comnatz(Thailand) Co., Ltd.

888,2nd Fl.,M.Srinakarin Road,
SamrongNua, MuangSamutprakarn
Samutprakarn 10270 THAILAND

Phone +662 361 3700-3
Fax +662 361 3704-5


JW Marriott Khao Lak
Checking & Test

Picture operations report




JW Marriott Khao Lak
Checking & Test

Picture operations report




JW Marriott Khao Lak
Checking & Test

Picture operations report




JW Marriott Khao Lak
Checking & Test

Picture operations report



JW Marriott Khao Lak
Checking & Test

Picture operations report






Comnatz(Thailand) Co., Ltd.
801/2nd Fl. 111 Srinakharin Road Samrongkha, Muang Samutprakarn
Samutprakarn 10270 THAILAND
Phone +662 361 3700-3
Fax +662 361 3704-5


JW Marriott Khao Lak
Checking & Test

Picture operations report




JW Marriott Khao Lak
Checking & Test

Picture operations report



JW Marriott Khao Lak
Checking & Test

Picture operations report






Comnatz(Thailand) Co., Ltd.
888/27 P.1, M.55/riatad Road Samronglue, MuangSamutprakam
Samutprakam 10270 THAILAND
Phone : +662 361 3700-3
Fax : +662 361 3704-6


JW Marriott Khao Lak
Checking & Test

Picture operations report



JW Marriott Khao Lak
Checking & Test

Picture operations report



Service Report

Comnatz(Thailand) Co., Ltd.

888,2nd Fl.,M.5Srinakarin Road.
SamrongNua, MuangSamutprakarn
Samutprakarn 10270 THAILAND

Phone +662 361 3700-3
Fax +662 361 3704-5

Service No. **00170**Project / Site : JW Marriot
Customer Name : K. งามรัตน Tel. : _____Job No. / So no : 50-1-2026067
Service System : _____

REASON FOR VISIT : UNDER WARRANTY/UNDER SERVICE AGREEMENT/CALL BACK SERVICES/ADDITIONAL WORKS/OTHER WORKS

WORK REQUESTED BY : _____

ARRIVAL AT AND DEPARTURE FROM SITE :

DATE: 17-21/6/26 ARRIVAL TIME: 6.30 DEPARTURE TIME: 17.00DETAIL OF WORK CARRIED OUT : ทางบริษัท Comnatz ได้ทำการตรวจสอบอุปกรณ์ที่มีปัญหาไลน์ - Sounder Base น้อย : 3015, 3026, 4015, 4027, 43209

- บริเวณ Building 1 ตู้ FCP Board Loop และ Board PMi เสีย
- บริเวณ Building 2 ตู้ FCP Board Loop เสีย
- บริเวณ Spa มีปัญหา อาจจะได้ยิน Effect จาก ไลน์ Leakage

COMMENTS/ACTION TO BE TAKEN : _____

THE ABOVE WORK INVOLVES EXTRA CHARGES AND INVOICE WILL BE ISSUED IN DUE COURSE,
THESE CHARGES WILL BE BASED ON THIS REPORT, ON A TIME AND MATERIALS BASIS, TOGETHER
WITH EXPENSES AT OUR CURRENT RATES.

SERVICE ENGINEER:

SIGNATURE: Witthawat
NAME: Witthawat Boonthaemsak
DATE: 21/6/26

CUSTOMER'S REPRESENTATIVE:

SIGNATURE: man งาม
NAME: _____
DATE: 21/6/26

Service No. 00169

Project / Site : JW Marriott

Job No. / So no : SO-1-2026067

Customer Name : K. พิเศษ

Tel. :

Service System : Fire Alarm

REASON FOR VISIT : UNDER WARRANTY/UNDER SERVICE AGREEMENT/CALL BACK SERVICES/ADDITIONAL WORKS/OTHER WORKS

WORK REQUESTED BY :

ARRIVAL AT AND DEPARTURE FROM SITE :

DATE: 17-21/6/26 ARRIVAL TIME: 9.30

DEPARTURE TIME: 17.00

DETAIL OF WORK CARRIED OUT : ตรวจสอบ Comnatz ใต้พื้นห้อง PM ชั้น 11 Fire Alarm

ใต้พื้นห้อง 11 (ชั้น 11) ชั้น 11

Wing 1 ตรวจสอบ ใต้พื้น PM, Loop 2 และอุปกรณ์ภายใน ชั้น 11 ตรวจสอบ Effect ของ ไฟ Leakage ตรวจสอบใต้พื้นห้อง Comnatz ใต้พื้น Spare Part ภายในชั้น 11

Wing 2 ตรวจสอบ ใต้พื้น Loop 5 และอุปกรณ์ภายใน ชั้น 11 ตรวจสอบ Effect ของ ไฟ Leakage ตรวจสอบ ใต้พื้นห้อง Comnatz ใต้พื้นห้อง ชั้น 11 ตรวจสอบ ใต้ พื้นห้อง all day ตรวจสอบ

Wing 3 ตรวจสอบ ใต้พื้นห้อง ชั้น 11 อุปกรณ์ภายใน Smoke detector ชั้น 11 3009, 3016, 3019

Wing 4 ตรวจสอบ ใต้พื้น ชั้น 11

All day ตรวจสอบ ใต้พื้นห้อง ชั้น 11 และอุปกรณ์ภายใน Loop

COMMENTS/ACTION TO BE TAKEN :

THE ABOVE WORK INVOLVES EXTRA CHARGES AND INVOICE WILL BE ISSUED IN DUE COURSE, THESE CHARGES WILL BE BASED ON THIS REPORT, ON A TIME AND MATERIALS BASIS, TOGETHER WITH EXPENSES AT OUR CURRENT RATES.

SERVICE ENGINEER:

SIGNATURE:

NAME: Sirisak Toyanich

DATE: 21/6/26

CUSTOMER'S REPRESENTATIVE:

SIGNATURE:

NAME:

DATE: 21/6/26

Service No. **00168**

Project / Site : JN Marriott

Job No. / So no : 50-1-2026067

Customer Name : K. ชำนาญ Tel. : _____

Service System : Fire Alarm

REASON FOR VISIT : UNDER WARRANTY/UNDER SERVICE AGREEMENT/CALL BACK SERVICES/ADDITIONAL WORKS/OTHER WORKS

WORK REQUESTED BY : _____

ARRIVAL AT AND DEPARTURE FROM SITE :

DATE: 17-21/6/26 ARRIVAL TIME: 8.30

DEPARTURE TIME: 17.00

DETAIL OF WORK CARRIED OUT : ตรวจสอบ Comnatz ใ้ทำการทดสอบระบบ Fire Alarm ดังนี้

บริเวณ ตึก - Building 5 ห้อง : 5007, 5008, 5103, 5104, 5105, 5109, 5203, 5204, 5208 อุปกรณ์
Smoke Detector และ Sounder Base สามารถทำงานได้ปกติ ทั้งหมด 9 ห้อง

- Building 4 ห้อง : 4001, 4003, 4005, 4006, 4007, 4008, 4009, 4010, 4011, 4012, 4014, 4016,
4017, 4018, 4019, 4021, 4022, 4023, 4024, 4026, 4027, 4028, 4029, 4030, 4102, 4103, 4105, 4110, 4111,
4114, 4115, 4116, 4117, 4118, 4119, 4120, 4121, 4122, 4123, 4124, 4125, 4126, 4127, 4128, 4129, 4130, 4131,
4203, 4204, 4205, 4208, 4209, 4210, 4215, 4216, 4217, 4220, 4221, 4222 อุปกรณ์สามารถทำงานได้ปกติ
ทั้งหมด 59 ห้อง

- Building 3 ห้อง : 3002, 3007, 3008, 3010, 3011, 3016, 3019, 3029, 3030, 3031, 3104, 3106,
3110, 3116, 3118, 3119, 3120, 3122, 3126, 3127, 3203, 3210, 3215, 3217, 3220, 3222 อุปกรณ์สามารถทำงานได้
ปกติ ทั้งหมด 26 ห้อง

ทำการทดสอบระบบทั้งหมด 94 ห้อง

COMMENTS/ACTION TO BE TAKEN : _____

THE ABOVE WORK INVOLVES EXTRA CHARGES AND INVOICE WILL BE ISSUED IN DUE COURSE,
THESE CHARGES WILL BE BASED ON THIS REPORT, ON A TIME AND MATERIALS BASIS, TOGETHER
WITH EXPENSES AT OUR CURRENT RATES.

SERVICE ENGINEER:

SIGNATURE: Nitthawat
NAME: Nitthawat Boonthaensuk
DATE: 21/6/26

CUSTOMER'S REPRESENTATIVE:

SIGNATURE: สมชาย งาม
NAME: _____
DATE: 21/6/26