

ภาคผนวกที่ 15

ใบเสร็จค่าสิ่งปลูก
ประจำเดือนมกราคม - มิถุนายน 2569

ในนาม บริษัท สุดาวรรณ เซฟตี้แอนด์ซีนนิ่งยูทิลิตี้ จำกัด

กฤตากรธนะ

ผู้มีอำนาจลงนาม

กิตติคุณ
ผู้มีอำนาจลงนาม

ภาคผนวกที่ 16

Checklist อุปกรณ์ดับเพลิง
ประจำเดือนมกราคม – มิถุนายน 2569

Check the condition of the fire extinguishers building A B C On January 2026

Location	Area	Date	Type Dry Chemical				Size 10 Lbs.						
			Fire Hose		Handle		Fire Extinguishers (ตัวถัง)		Pressure Gauge		Obstruction		Operator
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None	
Building A	Basement	21-Jan-26	✓		✓		✓		✓		✓		Markam
Building A	Floor 1	21-Jan-26	✓		✓		✓		✓		✓		Markam
Building A	Floor 2	21-Jan-26	✓		✓		✓		✓		✓		Markam
Building A	Floor 3	21-Jan-26	✓		✓		✓		✓		✓		Markam
Building A	Floor 4	21-Jan-26	✓		✓		✓		✓		✓		Markam
Building B	Basement	22-Jan-26	✓		✓		✓		✓		✓		Markam
Building B	Floor 1	22-Jan-26	✓		✓		✓		✓		✓		Markam
Building B	Floor 2	22-Jan-26	✓		✓		✓		✓		✓		Markam
Building B	Floor 3	22-Jan-26	✓		✓		✓		✓		✓		Markam
Building B	Floor 4	22-Jan-26	✓		✓		✓		✓		✓		Markam
Building C	Basement												
Building C	Floor 1												
Building C	Floor 2						ยังไม่ได้เปิดตึก						
Building C	Floor 3												
Building C	Floor 4												



Details of damage

Cause of damage

() Usability () Expire () Other

Reporter

Position

Date

Check the condition of the fire extinguishers building DGHUJKL On January 2026

Location	Area	Date	Type Dry Chemical				Size 10 Lbs.							Operator
			Fire Hose		Handle		Fire Extinguishers (ถังดับเพลิง)		Pressure Gauge		Obstruction			
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None		
Building D	18-May-26	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building D	Floor 1	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building D	Floor 2	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building D	Floor 3	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building D	Floor 4	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building G	Floor 1	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building G	Floor 2	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building G	Floor 3	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building G	Floor 4	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building H	Floor 1	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building H	Floor 2	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building H	Floor 3	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building H	Floor 4	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building I	Floor 1	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building I	Floor 2	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building I	Floor 3	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building I	Floor 4	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building J	Booster pump	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building J	Floor 1	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building J	Floor 2	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building J	Floor 3	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building J	Floor 4	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building K	Gas station Main K/C	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building K	Main kitchen	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building K	Basement (canteen)	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building K	Floor 1 (Clinic)	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building K	Floor 2	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building K	Floor 3	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building K	Floor 4	26-Jan-26	✓		✓		✓		✓		✓		Markam	
Building L	Gas station Sofya K/C	24-Jan-26	✓		✓		✓		✓		✓		Markam	
Building L	Basement	24-Jan-26	✓		✓		✓		✓		✓		Markam	
Building L	Pizza zone	24-Jan-26	✓		✓		✓		✓		✓		Markam	
Building L	Front of toilet	24-Jan-26	✓		✓		✓		✓		✓		Markam	
Building L	Floor 1 (Bua rest.)	24-Jan-26	✓		✓		✓		✓		✓		Markam	
Building L	Floor 2	24-Jan-26	✓		✓		✓		✓		✓		Markam	
Building L	Floor 3	24-Jan-26	✓		✓		✓		✓		✓		Markam	
Building L	Floor 4 (Sofya rest.)	24-Jan-26	✓		✓		✓		✓		✓		Markam	
Building L	Sofya kitchen	24-Jan-26	✓		✓		✓		✓		✓		Markam	
Lobby	Corridor FL 1	24-Jan-26	✓		✓		✓		✓		✓		Markam	
Building M	ENG Store	24-Jan-26	✓		✓		✓		✓		✓		Markam	



Details of damage

Cause of damage

() Usability () Expire () Other

Reporter

Position

Date

Check the condition of the fire extinguishers building A B C On February 2026

Location	Area	Date	Type Dry Chemical				Size 10 Lbs.						
			Fire Hose		Handle		Fire Extinguishers (ตัวถัง)		Pressure Gauge		Obstruction		Operator
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None	
Building A	Basement	25-Feb-26		✓		✓		✓		✓		✓	Markam
Building A	Floor 1	25-Feb-26	✓		✓		✓		✓		✓		Markam
Building A	Floor 2	25-Feb-26	✓		✓		✓		✓		✓		Markam
Building A	Floor 3	25-Feb-26	✓		✓		✓		✓		✓		Markam
Building A	Floor 4	25-Feb-26	✓		✓		✓		✓		✓		Markam
Building B	Basement	26-Feb-26		✓		✓		✓		✓		✓	Markam
Building B	Floor 1	26-Feb-26	✓		✓		✓		✓		✓		Markam
Building B	Floor 2	26-Feb-26	✓		✓		✓		✓		✓		Markam
Building B	Floor 3	26-Feb-26	✓		✓		✓		✓		✓		Markam
Building B	Floor 4	26-Feb-26	✓		✓		✓		✓		✓		Markam
Building C	Basement												
Building C	Floor 1												
Building C	Floor 2						ยังไม่ได้เปิดตึก						
Building C	Floor 3												
Building C	Floor 4												



Details of damage

Cause of damage

() Usability () Expire () Other

Reporter

Position

Date

Check the condition of the fire extinguishers building DGHUJKL On February 2026

Location	Area	Date	Type Dry Chemical				Size 10 Lbs.							Operator
			Fire Hose		Handle		Fire Extinguishers (ถังดับเพลิง)		Pressure Gauge		Obstruction			
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None		
Building D	Basement	25-Feb-26	✓		✓		✓		✓		✓		Krangkrai	
Building D	Floor 1	27-Feb-26	✓		✓		✓		✓		✓		Krangkrai	
Building D	Floor 2	27-Feb-26	✓		✓		✓		✓		✓		Krangkrai	
Building D	Floor 3	27-Feb-26	✓		✓		✓		✓		✓		Krangkrai	
Building D	Floor 4	27-Feb-26	✓		✓		✓		✓		✓		Krangkrai	
Building G	Floor 1	27-Feb-26	✓		✓		✓		✓		✓		Markam	
Building G	Floor 2	27-Feb-26	✓		✓		✓		✓		✓		Markam	
Building G	Floor 3	27-Feb-26	✓		✓		✓		✓		✓		Markam	
Building G	Floor 4	27-Feb-26	✓		✓		✓		✓		✓		Markam	
Building H	Floor 1	27-Feb-26	✓		✓		✓		✓		✓		Withoon	
Building H	Floor 2	27-Feb-26	✓		✓		✓		✓		✓		Withoon	
Building H	Floor 3	27-Feb-26	✓		✓		✓		✓		✓		Withoon	
Building H	Floor 4	27-Feb-26	✓		✓		✓		✓		✓		Withoon	
Building I	Floor 1	27-Feb-26	✓		✓		✓		✓		✓		Withoon	
Building I	Floor 2	27-Feb-26	✓		✓		✓		✓		✓		Withoon	
Building I	Floor 3	27-Feb-26	✓		✓		✓		✓		✓		Withoon	
Building I	Floor 4	27-Feb-26	✓		✓		✓		✓		✓		Withoon	
Building J	Booster pump	22-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building J	Floor 1	22-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building J	Floor 2	22-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building J	Floor 3	22-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building J	Floor 4	22-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building K	Gas station Main K/C	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building K	Main kitchen	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building K	Basement (canteen)	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building K	Floor 1 (Clinic)	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building K	Floor 2	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building K	Floor 3	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building K	Floor 4	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building L	Gas station Sofya K/C	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building L	Basement	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building L	Pizza zone	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building L	Front of toilet	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building L	Floor 1 (Bua rest.)	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building L	Floor 2	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building L	Floor 3	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building L	Floor 4 (Sofya rest.)	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Building L	Sofya kitchen	27-Feb-26	✓		✓		✓		✓		✓		Jirayut	
Lobby	Corridor FL 1	24-Feb-26	✓		✓		✓		✓		✓		Markam	
Building M	ENG Store	21-Feb-26	✓		✓		✓		✓		✓		Jirayut	



Details of damage

Cause of damage

() Usability () Expire () Other

Reporter

Position

Date

Check the condition of the fire extinguishers building ABC On March 2026



Location	Area	Date	Type Dry Chemical				Size 10 Lbs.						
			Fire Hose		Handle		Fire Extinguishers (ตัวถัง)		Pressure Gauge		Obstruction		Operator
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None	
Building A	Basement	26-Mar-26	✓		✓		✓		✓		✓		Markam
Building A	Floor 1	26-Mar-26	✓		✓		✓		✓		✓		Markam
Building A	Floor 2	26-Mar-26	✓		✓		✓		✓		✓		Markam
Building A	Floor 3	26-Mar-26	✓		✓		✓		✓		✓		Markam
Building A	Floor 4	26-Mar-26	✓		✓		✓		✓		✓		Markam
Building B	Basement	27-Mar-26	✓		✓		✓		✓		✓		Markam
Building B	Floor 1	27-Mar-26	✓		✓		✓		✓		✓		Markam
Building B	Floor 2	27-Mar-26	✓		✓		✓		✓		✓		Markam
Building B	Floor 3	27-Mar-26	✓		✓		✓		✓		✓		Markam
Building B	Floor 4	27-Mar-26	✓		✓		✓		✓		✓		Markam
Building C	Basement												
Building C	Floor 1												
Building C	Floor 2						ยังไม่ได้เปิดตึก						
Building C	Floor 3												
Building C	Floor 4												



Details of damage

Cause of damage

() Usability () Expire () Other

Reporter

Position

Date

Check the condition of the fire extinguishers building DGHUJKL On March 2026

Location	Area	Date	Type Dry Chemical				Size 10 Lbs.						
			Fire Hose		Handle		Fire Extinguishers (ถังดับเพลิง)		Pressure Gauge		Obstruction		Operator
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None	
Building D	Basement	27-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building D	Floor 1	27-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building D	Floor 2	27-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building D	Floor 3	27-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building D	Floor 4	27-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building G	Floor 1	23-Mar-26	✓		✓		✓		✓		✓		Markam
Building G	Floor 2	23-Mar-26	✓		✓		✓		✓		✓		Markam
Building G	Floor 3	23-Mar-26	✓		✓		✓		✓		✓		Markam
Building G	Floor 4	23-Mar-26	✓		✓		✓		✓		✓		Markam
Building H	Floor 1	23-Mar-26	✓		✓		✓		✓		✓		Markam
Building H	Floor 2	23-Mar-26	✓		✓		✓		✓		✓		Markam
Building H	Floor 3	23-Mar-26	✓		✓		✓		✓		✓		Markam
Building H	Floor 4	23-Mar-26	✓		✓		✓		✓		✓		Markam
Building I	Floor 1	24-Mar-26	✓		✓		✓		✓		✓		Markam
Building I	Floor 2	24-Mar-26	✓		✓		✓		✓		✓		Markam
Building I	Floor 3	24-Mar-26	✓		✓		✓		✓		✓		Markam
Building I	Floor 4	24-Mar-26	✓		✓		✓		✓		✓		Markam
Building J	Booster pump	20-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building J	Floor 1	20-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building J	Floor 2	20-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building J	Floor 3	20-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building J	Floor 4	20-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building K	Gas station Main K/C	29-Mar-26	✓		✓		✓		✓		✓		Markam
Building K	Main kitchen	29-Mar-26	✓		✓		✓		✓		✓		Markam
Building K	Basement (canteen)	29-Mar-26	✓		✓		✓		✓		✓		Markam
Building K	Floor 1 (Clinic)	29-Mar-26	✓		✓		✓		✓		✓		Markam
Building K	Floor 2	29-Mar-26	✓		✓		✓		✓		✓		Markam
Building K	Floor 3	29-Mar-26	✓		✓		✓		✓		✓		Markam
Building K	Floor 4	29-Mar-26	✓		✓		✓		✓		✓		Markam
Building L	Gas station Sofya K/C	28-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building L	Basement	28-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building L	Pizza zone	28-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building L	Front of toilet	28-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building L	Floor 1 (Bua rest.)	28-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building L	Floor 2	28-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building L	Floor 3	28-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building L	Floor 4 (Sofya rest.)	28-Mar-26	✓		✓		✓		✓		✓		Jirayut
Building L	Sofya kitchen	28-Mar-26	✓		✓		✓		✓		✓		Jirayut
Lobby	Corridor FL 1	23-Mar-26	✓		✓		✓		✓		✓		Markam
Building M	ENG Store	21-Mar-26	✓		✓		✓		✓		✓		Jirayut



Details of damage

Cause of damage
() Usability () Expire () Other

Reporter

Position

Date

Check the condition of the fire extinguishers ABC On April 2026



Location	Area	Date	Type Dry Chemical				Size 10 Lbs.						
			Fire Hose		Handle		Fire Extinguishers (ตัวถัง)		Pressure Gauge		Obstruction		Operator
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None	
Building A	Basement	27-Mar-26	✓		✓		✓		✓		✓		Withoon
Building A	Floor 1	27-Mar-26	✓		✓		✓		✓		✓		Withoon
Building A	Floor 2	27-Mar-26	✓		✓		✓		✓		✓		Withoon
Building A	Floor 3	27-Mar-26	✓		✓		✓		✓		✓		Withoon
Building A	Floor 4	27-Mar-26	✓		✓		✓		✓		✓		Withoon
Building B	Basement	27-Mar-26	✓		✓		✓		✓		✓		Withoon
Building B	Floor 1	27-Mar-26	✓		✓		✓		✓		✓		Withoon
Building B	Floor 2	27-Mar-26	✓		✓		✓		✓		✓		Withoon
Building B	Floor 3	27-Mar-26	✓		✓		✓		✓		✓		Withoon
Building B	Floor 4	27-Mar-26	✓		✓		✓		✓		✓		Withoon
Building C	Basement												
Building C	Floor 1												
Building C	Floor 2					ยังไม่ได้เปิดตึก							
Building C	Floor 3												
Building C	Floor 4												



Details of damage

Cause of damage
☐ Usability ☐ Expire ☐ Other

Reporter

Position

Date

Check the condition of the fire extinguishers building DGHUJKL on April 2026



Location	Area	Date	Type Dry Chemical				Size 10 Lbs.							Operator
			Fire Hose		Handle		Fire Extinguishers (ถังดับเพลิง)		Pressure Gauge		Obstruction			
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None		
Building D	Basement	16-Apr-26	✓		✓		✓		✓		✓		Supot	
Building D	Floor 1	16-Apr-26	✓		✓		✓		✓		✓		Supot	
Building D	Floor 2	16-Apr-26	✓		✓		✓		✓		✓		Supot	
Building D	Floor 3	16-Apr-26	✓		✓		✓		✓		✓		Supot	
Building D	Floor 4	16-Apr-26	✓		✓		✓		✓		✓		Supot	
Building G	Floor 1	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building G	Floor 2	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building G	Floor 3	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building G	Floor 4	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building H	Floor 1	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building H	Floor 2	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building H	Floor 3	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building H	Floor 4	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building I	Floor 1	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building I	Floor 2	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building I	Floor 3	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building I	Floor 4	20-Apr-26	✓		✓		✓		✓		✓		Withoon	
Building J	Booster pump	22-Apr-26	✓		✓		✓		✓		✓		Supot	
Building J	Floor 1	18-Apr-26	✓		✓		✓		✓		✓		Supot	
Building J	Floor 2	18-Apr-26	✓		✓		✓		✓		✓		Supot	
Building J	Floor 3	18-Apr-26	✓		✓		✓		✓		✓		Supot	
Building J	Floor 4	18-Apr-26	✓		✓		✓		✓		✓		Supot	
Building K	Gas station Main K/C	22-Apr-26	✓		✓		✓		✓		✓		Supot	
Building K	Main kitchen	22-Apr-26	✓		✓		✓		✓		✓		Supot	
Building K	Basement (canteen)	22-Apr-26	✓		✓		✓		✓		✓		Supot	
Building K	Floor 1 (Clinic)	-	-		-		-		-		-		Supot	
Building K	Floor 2	19-Apr-26	✓		✓		✓		✓		✓		Supot	
Building K	Floor 3	19-Apr-26	✓		✓		✓		✓		✓		Supot	
Building K	Floor 4	19-Apr-26	✓		✓		✓		✓		✓		Supot	
Building L	Gas station Sofya K/C	22-Apr-26	✓		✓		✓		✓		✓		Supot	
Building L	Basement	22-Apr-26	✓		✓		✓		✓		✓		Supot	
Building L	Pizza zone	24-Apr-26	✓		✓		✓		✓		✓		Supot	
Building L	Front of toilet	24-Apr-26	✓		✓		✓		✓		✓		Supot	
Building L	Floor 1 (Bua rest.)	24-Apr-26	✓		✓		✓		✓		✓		Supot	
Building L	Floor 2	25-Apr-26	✓		✓		✓		✓		✓		Supot	
Building L	Floor 3	25-Apr-26	✓		✓		✓		✓		✓		Supot	
Building L	Floor 4 (Sofya rest.)	25-Apr-26	✓		✓		✓		✓		✓		Supot	
Building L	Sofya kitchen	25-Apr-26	✓		✓		✓		✓		✓		Supot	
Lobby	Corridor FL 1	25-Apr-26	✓		✓		✓		✓		✓		Supot	
Building M	ENG Store	15-Apr-26	✓		✓		✓		✓		✓		Supot	



Details of damage

Cause of damage

() Usability () Expire () Other

Reporter

Position

Date

Check the condition of the fire extinguishers building ABC On May 2026

Location	Area	Date	Type Dry Chemical				Size 10 Lbs.						
			Fire Hose		Handle		Fire Extinguishers (สารดับ)		Pressure Gauge		Obstruction		Operator
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None	
Building A	Basement	17-May-26	✓		✓		✓		✓			✓	Attapol
Building A	Floor 1	17-May-26	✓		✓		✓		✓			✓	Attapol
Building A	Floor 2	17-May-26	✓		✓		✓		✓			✓	Attapol
Building A	Floor 3	17-May-26	✓		✓		✓		✓			✓	Attapol
Building A	Floor 4	17-May-26	✓		✓		✓		✓			✓	Attapol
Building B	Basement	17-May-26	✓		✓		✓		✓			✓	Attapol
Building B	Floor 1	17-May-26	✓		✓		✓		✓			✓	Attapol
Building B	Floor 2	17-May-26	✓		✓		✓		✓			✓	Attapol
Building B	Floor 3	17-May-26	✓		✓		✓		✓			✓	Attapol
Building B	Floor 4	17-May-26	✓		✓		✓		✓			✓	Attapol
Building C	Basement												
Building C	Floor 1												
Building C	Floor 2												
Building C	Floor 3												
Building C	Floor 4												



Details of damage

Cause of damage

() Usability () Expire () Other

Reporter

Position

Date

Check the condition of the fire extinguishers building DGHUJKL On May 2026

Location	Area	Date	Type Dry Chemical				Size 10 Lbs.							Operator
			Fire Hose		Handle		Fire Extinguishers (ถังดับเพลิง)		Pressure Gauge		Obstruction			
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None		
Building D	Basement	19-May-26	✓		✓		✓		✓		✓		Keena	
Building D	Floor 1	19-May-26	✓		✓		✓		✓		✓		Keena	
Building D	Floor 2	19-May-26	✓		✓		✓		✓		✓		Keena	
Building D	Floor 3	19-May-26	✓		✓		✓		✓		✓		Keena	
Building D	Floor 4	19-May-26	✓		✓		✓		✓		✓		Keena	
Building G	Floor 1	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building G	Floor 2	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building G	Floor 3	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building G	Floor 4	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building H	Floor 1	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building H	Floor 2	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building H	Floor 3	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building H	Floor 4	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building I	Floor 1	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building I	Floor 2	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building I	Floor 3	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building I	Floor 4	17-May-26	✓		✓		✓		✓		✓		Attapol	
Building J	Booster pump	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building J	Floor 1	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building J	Floor 2	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building J	Floor 3	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building J	Floor 4	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building K	Gas station Main K/C	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building K	Main kitchen	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building K	Basement (canteen)	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building K	Floor 1 (Clinic)	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building K	Floor 2	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building K	Floor 3	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building K	Floor 4	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building L	Gas station Sofya K/C	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building L	Basement	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building L	Pizza zone	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building L	Front of toilet	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building L	Floor 1 (Bua rest.)	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building L	Floor 2	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building L	Floor 3	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building L	Floor 4 (Sofya rest.)	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building L	Sofya kitchen	18-May-25	✓		✓		✓		✓		✓		Attapol	
Lobby	Corridor FL 1	18-May-25	✓		✓		✓		✓		✓		Attapol	
Building M	ENG Store	18-May-25	✓		✓		✓		✓		✓		Attapol	



Details of damage

Cause of damage

() Usability () Expire () Other

Reporter

Position

Date

Check the condition of the fire extinguishers building ABC On June 2026

Location	Area	Date	Type Dry Chemical				Size 10 Lbs.						
			Fire Hose		Handle		Fire Extinguishers (ถังดับเพลิง)		Pressure Gauge		Obstruction		Operator
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None	
Building A	Basement	18-Jun-26	✓		✓		✓		✓		✓		Kay
Building A	Floor 1	18-Jun-26	✓		✓		✓		✓		✓		Kay
Building A	Floor 2	18-Jun-26	✓		✓		✓		✓		✓		Kay
Building A	Floor 3	18-Jun-26	✓		✓		✓		✓		✓		Kay
Building A	Floor 4	18-Jun-26	✓		✓		✓		✓		✓		Kay
Building B	Basement	18-Jun-26	✓		✓		✓		✓		✓		Kay
Building B	Floor 1	18-Jun-26	✓		✓		✓		✓		✓		Kay
Building B	Floor 2	18-Jun-26	✓		✓		✓		✓		✓		Kay
Building B	Floor 3	18-Jun-26	✓		✓		✓		✓		✓		Kay
Building B	Floor 4	18-Jun-26	✓		✓		✓		✓		✓		Kay
Building C	Basement												
Building C	Floor 1												
Building C	Floor 2												
Building C	Floor 3												
Building C	Floor 4												



Details of damage

Cause of damage
() Usability () Expire () Other

Reporter _____

Position _____

Date _____

Check the condition of the fire extinguishers DGHUJKL On June 2026



Location	Area	Date	Type Dry Chemical				Size 10 Lbs.							Operator
			Fire Hose		Handle		Fire Extinguishers (ถังดับเพลิง)		Pressure Gauge		Obstruction			
			Normal	Damaged	Normal	Damaged	Normal	Damaged	Normal	Damaged	Have	None		
Building D	Basement	19-Jun-26	✓		✓		✓		✓		✓		Kay	
Building D	Floor 1	19-Jun-26	✓		✓		✓		✓		✓		Kay	
Building D	Floor 2	19-Jun-26	✓		✓		✓		✓		✓		Kay	
Building D	Floor 3	22-Jun-26	✓		✓		✓		✓		✓		Kay	
Building D	Floor 4	22-Jun-26	✓		✓		✓		✓		✓		Kay	
Building G	Floor 1	22-Jun-26	✓		✓		✓		✓		✓		Kay	
Building G	Floor 2	22-Jun-26	✓		✓		✓		✓		✓		Kay	
Building G	Floor 3	22-Jun-26	✓		✓		✓		✓		✓		Kay	
Building G	Floor 4	22-Jun-26	✓		✓		✓		✓		✓		Kay	
Building H	Floor 1	21-Jun-26	✓		✓		✓		✓		✓		Jirayut	
Building H	Floor 2	21-Jun-26	✓		✓		✓		✓		✓		Jirayut	
Building H	Floor 3	21-Jun-26	✓		✓		✓		✓		✓		Jirayut	
Building H	Floor 4	21-Jun-26	✓		✓		✓		✓		✓		Jirayut	
Building I	Floor 1	22-Jun-26	✓		✓		✓		✓		✓		Kay	
Building I	Floor 2	22-Jun-26	✓		✓		✓		✓		✓		Kay	
Building I	Floor 3	22-Jun-26	✓		✓		✓		✓		✓		Kay	
Building I	Floor 4	22-Jun-26	✓		✓		✓		✓		✓		Kay	
Building J	Booster pump	24-Jun-26	✓		✓		✓		✓		✓		Kay	
Building J	Floor 1	24-Jun-26	✓		✓		✓		✓		✓		Kay	
Building J	Floor 2	24-Jun-26	✓		✓		✓		✓		✓		Kay	
Building J	Floor 3	24-Jun-26	✓		✓		✓		✓		✓		Kay	
Building J	Floor 4	24-Jun-26	✓		✓		✓		✓		✓		Kay	
Building K	Gas station Main K/C	25-Jun-26	✓		✓		✓		✓		✓		Kay	
Building K	Main kitchen	25-Jun-26	✓		✓		✓		✓		✓		Kay	
Building K	Basement (canteen)	25-Jun-26	✓		✓		✓		✓		✓		Kay	
Building K	Floor 1 (Clinic)	25-Jun-26	✓		✓		✓		✓		✓		Kay	
Building K	Floor 2	25-Jun-26	✓		✓		✓		✓		✓		Kay	
Building K	Floor 3	25-Jun-26	✓		✓		✓		✓		✓		Kay	
Building K	Floor 4	25-Jun-26	✓		✓		✓		✓		✓		Kay	
Building L	Gas station Sofya K/C	23-Jun-26	✓		✓		✓		✓		✓		Kay	
Building L	Basement	23-Jun-26	✓		✓		✓		✓		✓		Kay	
Building L	Pizza zone	23-Jun-26	✓		✓		✓		✓		✓		Kay	
Building L	Front of toilet	23-Jun-26	✓		✓		✓		✓		✓		Kay	
Building L	Floor 1 (Bua rest.)	23-Jun-26	✓		✓		✓		✓		✓		Kay	
Building L	Floor 2	23-Jun-26	✓		✓		✓		✓		✓		Kay	
Building L	Floor 3	23-Jun-26	✓		✓		✓		✓		✓		Kay	
Building L	Floor 4 (Sofya rest.)	23-Jun-26	✓		✓		✓		✓		✓		Kay	
Building L	Sofya kitchen	23-Jun-26	✓		✓		✓		✓		✓		Kay	
Lobby	Corridor FL 1	18-Jun-25	✓		✓		✓		✓		✓		Jirayut	
Building M	ENG Store	22-Jun-25	✓		✓		✓		✓		✓		Jirayut	



Details of damage

Cause of damage

() Usability () Expire () Other

Reporter

Position

Date