

ภาคผนวก ก


Monthly Service Swimming Pool Report

MONTHLY SERVICE REPORT ON JANUARY 2026

		Date	: 31/01/2026
Project	: Hyatt Regency Bangkok Sukhumvit	Address	: Sukhumvit Soi 13 Road
Location	: Bangkok, Thailand 10110	System	: Chlorine dioxide for swimming pool
Report maker	: Korawik Kuna-boot		

DG INTERNAL III

Data Dashborad – January 2026




Data Dashborad						
Parameter	Latest report	Date/Time	Min.	Max.	Avg.	Std.*
Chlorine dioxide	2.93 ppm	30/01/2026 : 22.17	0.43	5.93	2.61	1.0 – 3.0
Free Chlorine	1.53 ppm		0.29	3.16	1.37	0.6 – 1.0
pH	7.23		7.15	7.23	7.2	7.2 – 8.4

* National Spa & Pool Institute (NSPI)


Comment : Control parameters within standard limits.

Status of DG Intergral III



Comment : The system is functioning normally.

Monthly service pictures




Comment : Perform monthly preventive maintenance (PM) on the chlorine dioxide system and check the residual chlorine levels, which were found to be within the standard range.

MONTHLY SERVICE REPORT ON FEBRUARY 2026

		Date	: 28/02/2026
Project	: Hyatt Regency Bangkok Sukhumvit	Address	: Sukhumvit Soi 13 Road
Location	: Bangkok, Thailand 10110	System	: Chlorine dioxide for swimming pool
Report maker	: Korawik Kuna-boot		

DG INTERNAL III

Data Dashborad – February 2026




Data Dashborad						
Parameter	Latest report	Date/Time	Min.	Max.	Avg.	Std.*
Chlorine dioxide	3.49 ppm	28/02/2026 : 15.30	0.18	3.55	2.09	1.0 – 3.0
Free Chlorine	1.88 ppm		0.1	1.91	1.09	0.6 – 1.0
pH	7.22		7.15	7.25	7.21	7.2 – 8.4

* National Spa & Pool Institute (NSPI)


Comment : Control parameters within standard limits.

Status of DG Intergral III



Comment : The system is functioning normally.

Monthly service pictures



Comment : Perform monthly preventive maintenance (PM) on the chlorine dioxide system and check the residual chlorine levels, which were found to be within the standard range.




MONTHLY SERVICE REPORT ON MARCH 2026

		Date	: 31/03/2026
Project	: Hyatt Regency Bangkok Sukhumvit	Address	: Sukhumvit Soi 13 Road
Location	: Bangkok, Thailand 10110	System	: Chlorine dioxide for swimming pool
Report maker	: Korawik Kuna-boot		

DG INTERNAL III

Data Dashborad – March 2026




Data Dashborad						
Parameter	Latest report	Date/Time	Min.	Max.	Avg.	Std.*
Chlorine dioxide	3.02 ppm	31/03/2026 : 23.30	2.25	3.51	2.84	1.0 – 3.0
Free Chlorine	1.57 ppm		1.17	1.77	1.49	0.6 – 1.0
pH	7.21		7.16	7.24	7.22	7.2 – 8.4

* National Spa & Pool Institute (NSPI)

Comment : Control parameters within standard limits.

Status of DG Intergral III



Comment : The system is functioning normally.

Monthly service pictures




Comment : Perform monthly preventive maintenance (PM) on the chlorine dioxide system and check the residual chlorine levels, which were found to be within the standard range.

MONTHLY SERVICE REPORT ON APRIL 2026

		Date	: 30/04/2026
Project	: Hyatt Regency Bangkok Sukhumvit	Address	: Sukhumvit Soi 13 Road
Location	: Bangkok, Thailand 10110	System	: Chlorine dioxide for swimming pool
Report maker	: Korawik Kuna-boot		

DG INTERNAL III

Data Dashborad – April 2026




Data Dashborad						
Parameter	Latest report	Date/Time	Min.	Max.	Avg.	Std.*
Chlorine dioxide	1.83 ppm	30/04/2026 : 23.49	1.33	3.03	2.26	1.0 – 3.0
Free Chlorine	0.99 ppm		0.65	1.58	1.19	0.6 – 1.0
pH	7.20		7.15	7.25	7.26	7.2 – 8.4

* National Spa & Pool Institute (NSPI)

Comment : Control parameters within standard limits.

Status of DG Intergral III



Comment : The system is functioning normally.

Monthly service pictures




Comment : Perform monthly preventive maintenance (PM) on the chlorine dioxide system and check the residual chlorine levels, which were found to be within the standard range.

MONTHLY SERVICE REPORT ON MAY 2026

		Date	: 30/05/2026
Project	: Hyatt Regency Bangkok Sukhumvit	Address	: Sukhumvit Soi 13 Road
Location	: Bangkok, Thailand 10110	System	: Chlorine dioxide for swimming pool
Report maker	: Korawik Kuna-boot		

DG INTERNAL III

Data Dashborad – MAY 2026




Data Dashborad						
Parameter	Latest report	Date/Time	Min.	Max.	Average	Std.*
Chlorine dioxide	1.43 ppm	29/05/2026 : 23.54	0.84	3.04	2.39	1.0 – 3.0
Free Chlorine	0.7 ppm		0.44	1.6	1.26	0.6 – 1.0
pH	7.17		7.15	7.25	7.20	7.2 – 8.4

* National Spa & Pool Institute (NSPI)

Comment : Control parameters within standard limits.

Status of DG Intergral III



Comment : The system is functioning normally.

Monthly service pictures




Comment : Perform monthly preventive maintenance (PM) on the chlorine dioxide system and check the residual chlorine levels, which were found to be within the standard range.

MONTHLY SERVICE REPORT ON JUNE2026

		Date	: 30/06/2026
Project	: Hyatt Regency Bangkok Sukhumvit	Address	: Sukhumvit Soi 13 Road
Location	: Bangkok, Thailand 10110	System	: Chlorine dioxide for swimming pool
Report maker	: Korawik Kuna-boot		

DG INTERNAL III

Data Dashborad – JUNE 2026




Data Dashborad						
Parameter	Latest report	Date/Time	Min.	Max.	Average	Std.*
Chlorine dioxide	1.44 ppm	29/06/2026 : 22.54	0.44	3.01	1.64	1.0 – 3.0
Free Chlorine	0.73 ppm		0.23	1.59	0.86	0.6 – 1.0
pH	7.21		7.15	7.28	7.21	7.2 – 8.4

* National Spa & Pool Institute (NSPI)

Comment : Control parameters within standard limits.

Status of DG Intergral III



Comment : The system is functioning normally.

Monthly service pictures



Comment : Perform monthly preventive maintenance (PM) on the chlorine dioxide system and check the residual chlorine levels, which were found to be within the standard range.