



วุฒิบัตรเลขที่.สปก. (ปกป. ๒) ๑๗๗๒ / ๒๕๖๘

กรุงเทพมหานคร

ได้รับใบอนุญาตจากกรมสวัสดิการและคุ้มครองแรงงาน ใบอนุญาตเลขที่ ๐๑๐๒-๐๒-๒๕๖๗-๐๑๕๑

ขอรับรองว่า

โรงแรม ซามา เลควิว อโศก กรุงเทพฯ

ตั้งอยู่เลขที่.....๔๑.ซอยสุขุมวิท.๑๖.ถนนสุขุมวิท.แขวงคลองเตย เขตวัฒนา กรุงเทพมหานคร ๑๐๑๑๐.....

ได้ดำเนินการฝึกซ้อมดับเพลิงและฝึกซ้อมอพยพหนีไฟ

ตามกฎหมายกระทรวงกำหนดมาตรฐานในการบริหาร จัดการ และดำเนินการด้านความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงานเกี่ยวกับการป้องกันและระงับอัคคีภัย พ.ศ. ๒๕๕๕ ลงวันที่ ๗ ธันวาคม พ.ศ. ๒๕๕๕

มีผู้เข้ารับการฝึกอบรม จำนวน.....๑๑๕.....คน

เมื่อวันที่.....๒๑ ตุลาคม ๒๕๖๘.....

ให้ไว้ ณ วันที่.....๒๗ ตุลาคม ๒๕๖๘.....

(นายสุริยา รวีวรรณ)

ผู้อำนวยการสำนักงานป้องกันและบรรเทาสาธารณภัย
ปฏิบัติราชการแทนผู้ว่าราชการกรุงเทพมหานคร

เอกสารการตรวจสอบระบบป้องกันและระงับอัคคีภัยและอุปกรณ์ดับเพลิง

รายงานการตรวจเช็ค ระบบ FIRE ALARM
ประจำเดือน พฤศจิกายน 2568
โครงการ SHAMA LAKEVIEW ASOKE BANGKOK

ห้างหุ้นส่วนจำกัด เจ.พี เซาท์เทิร์น
1111ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กรุงเทพฯ 10240
โทร : 02-734-9615 , 02-734-9618-9 โทรสาร : 02-734-6904

Ref. No. J.6848

วันที่ 15 พฤศจิกายน พ.ศ. 2568

เรื่อง : การเข้าตรวจเช็คระบบ FIRE ALARM (TOWER A,B)
ประจำเดือน พฤศจิกายน 2568 (ครั้งที่ 9 /10)

เรียน : โครงการ SHAMA LAKEVIEW ASOKE BANGKOK

จากการที่ทาง ห้างหุ้นส่วนจำกัด เจ.พี เซาท์เทิร์น ได้รับใบสั่งซื้อเลขที่ K0047.1 R3
ลงวันที่ 4 กุมภาพันธ์ 2568 ให้ดำเนินการตรวจเช็คระบบ FIRE ALARM ให้กับทาง JR KYUSHU
BUSINESS DEVELOPMENT (THAILAND) CO.,LTD. นั้น

ทางห้างหุ้นส่วนจำกัด เจ.พี เซาท์เทิร์น ได้เข้าดำเนินการตรวจเช็คระบบดังกล่าว
เสร็จเป็นที่เรียบร้อยแล้ว รายละเอียดตามเอกสารที่แนบ

จึงเรียนมาเพื่อทราบ

ขอแสดงความนับถือ

(นายจรัสพงษ์ พรหมรักษ์)

กรรมการผู้จัดการ



PROJECT : SHAMA LAKEVIEW

BUILDING - A

J.P SOUTHERN LIMITED PARTNERSHIP

ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ ก.ท.ม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

ตารางการตรวจเช็คระบบ FIRE ALARM

โครงการ: SHAMA LAKEVIEW TOWER A

JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ประจำงวดที่.....9/10.....

วันที่ตรวจเช็ค...13/11/2568.....

ลำดับที่	รายการตรวจเช็ค	ผลการตรวจเช็ค		หมายเหตุ
		ปกติ	ผิดปกติ	
1	ตรวจเช็คสภาพทั่วไปของตู้ FCP			
	* ทำความสะอาดตู้ FCP	✓		
	* ทำความสะอาด CARD CPU	✓		
	* ตรวจเช็คขั้วสายของ CARD NET	✓		
	* ตรวจเช็ค COLOUR GRAPHIC	✓		
	* ตรวจเช็ค BATTERY	✓		
	* LIST POINT TROUBLE	✓		
	* ตรวจเช็ค POWER SUPPLY	✓		
2	RTU MODULE			
	* ทำความสะอาดตู้ RTU	✓		
	* ตรวจเช็ค ZAM MODULE	✓		
	* ตรวจเช็คสาย NET	✓		
	* ตรวจเช็คขั้วสาย ZAM MODULE	✓		
	* ตรวจเช็คสาย POWER 24 VDC	✓		

ลงชื่อ.....ผู้ตรวจเช็ค

ลงชื่อ.....ผู้รับบริการตรวจเช็ค

(.....)

(.....)

วันที่.....

วันที่.....

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -A)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
8 FL.	Room. 804									Smoke 2 ตัว, Heat 1 ตัว
8 FL.	Room. 805									
8 FL.	Room. 806									Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Room. 807	✓		✓		✓		✓		
8 FL.	Room. 808									Smoke 2 ตัว, Heat 2 ตัว
8 FL.	Room. 809									Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Room. 810									Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Room. 811									Smoke 4 ตัว, Heat 1 ตัว
8 FL.	Room. 812									
8 FL.	Room. 814									Smoke 3 ตัว, Heat 1 ตัว
8 FL.	Room. 815									Smoke 2 ตัว, Heat 1 ตัว
8 FL.	Corridor (Lift)									Manual 1 ตัว, Smoke 2 ตัว
8 FL.	Corridor (Guest room)									Manual 2 ตัว, Smoke 3 ตัว
8 FL.	E. Room									Smoke 1 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -A)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
9 FL.	Room. 904									Smoke 2 ตัว, Heat 1 ตัว
9 FL.	Room. 905									Smoke 2 ตัว, Heat 1 ตัว
9 FL.	Room. 906									Smoke 1 ตัว, Heat 1 ตัว
9 FL.	Room. 907									Smoke 1 ตัว, Heat 1 ตัว
9 FL.	Room. 908									Smoke 2 ตัว, Heat 1 ตัว
9 FL.	Room. 909	✓		✓		✓		✓		Smoke 1 ตัว, Heat 1 ตัว
9 FL.	Room. 910									Smoke 1 ตัว, Heat 1 ตัว
9 FL.	Room. 911	✓		✓		✓		✓		Smoke 3 ตัว, Heat 3 ตัว
9 FL.	Room. 912									Smoke 2 ตัว, Heat 2 ตัว
9 FL.	Room. 914									Smoke 2 ตัว, Heat 2 ตัว
9 FL.	Room. 915	✓		✓		✓		✓		Smoke 2 ตัว, Heat 1 ตัว
9 FL.	Corridor (Lift)									Manual 1 ตัว, Smoke 2 ตัว
9 FL.	Corridor (Guest room)									Manual 2 ตัว, Smoke 3 ตัว
9 FL.	E Room									Smoke 1 ตัว
9 FL.	Zone A									
9 FL.	Zone B									
9 FL.	Zone C									

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -A)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
10 FL.	Room. 1004									Smoke 2 ตัว, Heat 1 ตัว
10 FL.	Room. 1005									Smoke 1ตัว, Heat 1 ตัว
10 FL.	Room. 1006									Smoke 1ตัว, Heat 1 ตัว
10 FL.	Room. 1007									Smoke 1ตัว, Heat 1 ตัว
10 FL.	Room. 1008									Smoke 2ตัว, Heat 1 ตัว
10 FL.	Room. 1009									Smoke 1ตัว, Heat 1 ตัว
10 FL.	Room. 1010									Smoke 1ตัว, Heat 1 ตัว
10 FL.	Room. 1011									Smoke 3ตัว, Heat 3 ตัว
10 FL.	Room. 1012									Smoke 2 ตัว, Heat 2 ตัว
10 FL.	Room. 1014									Smoke 2 ตัว, Heat 2 ตัว
10 FL.	Room. 1015	√		√		√		√		Smoke 2 ตัว, Heat 1 ตัว
10 FL.	Corridor (Lift)									Manual 1 ตัว,Smoke 2 ตัว
10 FL.	Corridor (Guest room)									Manual 2 ตัว,Smoke 3 ตัว
10 FL.	E Room									Smoke 1 ตัว
10 FL.	Zone A									
10 FL.	หน้าลิฟท์									Manual , Bell

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -A)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
11 FL.	Room. 1104	✓		✓		✓		✓		Smoke 2 ตัว, Heat 1 ตัว
11 FL.	Room. 1105									
11 FL.	Room. 1106									Smoke 1 ตัว, Heat 1 ตัว
11 FL.	Room. 1107									Smoke 1 ตัว, Heat 1 ตัว
11 FL.	Room. 1108									Smoke 2 ตัว, Heat 1 ตัว
11 FL.	Room. 1109									Smoke 2 ตัว, Heat 1 ตัว
11 FL.	Room. 1110									Smoke 1 ตัว, Heat 1 ตัว
11 FL.	Room. 1111									Smoke 5 ตัว, Heat 1 ตัว
11 FL.	Room. 1112									Smoke 2 ตัว, Heat 2 ตัว
11 FL.	Room. 1114									Smoke 2 ตัว, Heat 2 ตัว
11 FL.	Room. 1115									Smoke 2 ตัว, Heat 1 ตัว
11 FL.	Corridor (Lift)									Manual 1 ตัว, Smoke 2 ตัว
11 FL.	Corridor (Guest room)									Manual 2 ตัว, Smoke 3 ตัว
11 FL.	E Room									Smoke 1 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -A)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
12 FL.	Room. 1204									Smoke 2 ตัว, Heat 1 ตัว
12 FL.	Room. 1205									Smoke 2 ตัว, Heat 1 ตัว
12 FL.	Room. 1206									Smoke 1 ตัว, Heat 1 ตัว
12 FL.	Room. 1207									Smoke 1 ตัว, Heat 1 ตัว
12 FL.	Room. 1208									Smoke 2 ตัว, Heat 1 ตัว
12 FL.	Room. 1209									Smoke 1 ตัว, Heat 1 ตัว
12 FL.	Room. 1210									Smoke 1 ตัว, Heat 1 ตัว
12 FL.	Room. 1211									Smoke 4 ตัว, Heat 2 ตัว
12 FL.	Room. 1212	✓		✓		✓		✓		Smoke 2 ตัว, Heat 1 ตัว
12 FL.	Room. 1214									Smoke 2 ตัว, Heat 2 ตัว
12 FL.	Room. 1215									Smoke 2 ตัว, Heat 1 ตัว
12 FL.	Corridor (Lift)									Manual 1 ตัว,Smoke 2 ตัว
12 FL.	Corridor (Guest room)									Manual 2 ตัว,Smoke 3 ตัว
12 FL.	E Room									Smoke 1 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -A)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
15 FL.	Room. 1504									Smoke 2 ตัว, Heat 1 ตัว
15 FL.	Room. 1505									Smoke 2 ตัว, Heat 1 ตัว
15 FL.	Room. 1506									Smoke 1 ตัว, Heat 1 ตัว
15 FL.	Room. 1507									Smoke 1 ตัว, Heat 1 ตัว
15 FL.	Room. 1508									Smoke 2 ตัว, Heat 1 ตัว
15 FL.	Room. 1509	√		√		√		√		Smoke 1 ตัว, Heat 1 ตัว
15 FL.	Room. 1510									Smoke 1 ตัว, Heat 1 ตัว
15 FL.	Room. 1511									Smoke 3 ตัว, Heat 2 ตัว
15 FL.	Room. 1512									Smoke 2 ตัว, Heat 2 ตัว
15 FL.	Room. 1514									Smoke 2 ตัว, Heat 2 ตัว
15 FL.	Room. 1515									Smoke 2 ตัว, Heat 1 ตัว
15 FL.	Corridor (Lift)									Manual 1 ตัว, Smoke 2 ตัว
15 FL.	Corridor (Guest room)									Manual 2 ตัว, Smoke 3 ตัว
15 FL.	E Room									Smoke 1 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -A)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
20 FL.	Room. 2004									Smoke 2 ตัว, Heat 1 ตัว
20 FL.	Room. 2005									Smoke 2 ตัว, Heat 1 ตัว
20 FL.	Room. 2006									Smoke 1 ตัว, Heat 1 ตัว
20 FL.	Room. 2007									Smoke 1 ตัว, Heat 1 ตัว
20 FL.	Room. 2008									Smoke 2 ตัว, Heat 1 ตัว
20 FL.	Room. 2009									Smoke 1 ตัว, Heat 1 ตัว
20 FL.	Room. 2010									Smoke 1 ตัว, Heat 1 ตัว
20 FL.	Room. 2011	√		√		√		√		Smoke 3 ตัว, Heat 3 ตัว
20 FL.	Room. 2012									Smoke 1 ตัว, Heat 2 ตัว
20 FL.	Room. 2014									Smoke 2 ตัว, Heat 2 ตัว
20 FL.	Room. 2015									Smoke 2 ตัว, Heat 1 ตัว
20 FL.	Corridor (Lift)									Manual 1 ตัว, Smoke 2 ตัว
20 FL.	Corridor (Guest room)									Manual 2 ตัว, Smoke 3 ตัว
20 FL.	E Room									Smoke 1 ตัว
20 FL.	Zone A									

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -A)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
21 FL.	Room. 2101									Smoke 3 ตัว, Heat 4 ตัว
21 FL.	Room. 2102									Smoke 3 ตัว, Heat 3 ตัว
21 FL.	Room. 2103									Smoke 2 ตัว, Heat 2 ตัว
21 FL.	Room. 2111	✓		✓		✓		✓		Smoke 3 ตัว, Heat 2 ตัว
21 FL.	Room. 2112									Smoke ไม่มี , Heat 3 ตัว
21 FL.	Room. 2114									Smoke 2 ตัว, Heat 2 ตัว
21 FL.	Room. 2115									Smoke 2 ตัว, Heat 1 ตัว
21 FL.	Corridor (Lift)									Manual 1 ตัว,Smoke 2 ตัว
21 FL.	Corridor (Guest room)									Manual 2 ตัว,Smoke 2 ตัว
21 FL.	E Room									Smoke 1 ตัว
21 FL.	ZONE D									

หมายเหตุ :

J.P SOUTHERN LIMITED PARTNERSHIP

ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ ก.ท.ม. 10240

โทร: 02-734-9615, 02-734-9618-9 โทรสาร: 02-734-6904

.....
ปัญหาที่ยังไม่ได้รับการแก้ไข

โครงการ: SHAMA LAKEVIEW TOWER A

วันที่.....13/11/2568.....

NO.	รายการอุปกรณ์ที่มีปัญหา	อาการ	วันที่แจ้ง	หมายเหตุ

ลงชื่อผู้ตรวจเช็ค.....
วันที่.....13/11/68.....

ลงชื่อผู้รับการตรวจเช็ค.....
วันที่.....

PROJECT : SHAMA LAKEVIEW

BUILDING - B

J.P SOUTHERN LIMITED PARTNERSHIP

ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ ก.ท.ม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

ตารางการตรวจเช็คระบบ FIRE ALARM

โครงการ: SHAMA LAKEVIEW TOWER B

JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ประจำงวดที่.....9/10.....

วันที่ตรวจเช็ค.....13/11/2568.....

ลำดับที่	รายการตรวจเช็ค	ผลการตรวจเช็ค		หมายเหตุ
		ปกติ	ผิดปกติ	
1	ตรวจเช็คสภาพทั่วไปของตู้ FCP			
	* ทำความสะอาดตู้ FCP	√		
	* ทำความสะอาด CARD CPU	√		
	* ตรวจเช็คขั้วสายของ CARD NET	√		
	* ตรวจเช็ค COLOUR GRAPHIC	√		
	* ตรวจเช็ค BATTERY	√		
	* LIST POINT TROUBLE	√		
	* ตรวจเช็ค POWER SUPPLY	√		
2	RTU MODULE			
	* ทำความสะอาดตู้ RTU	√		
	* ตรวจเช็ค ZAM MODULE	√		
	* ตรวจเช็คสาย NET	√		
	* ตรวจเช็คขั้วสาย ZAM MODULE	√		
	* ตรวจเช็คสาย POWER 24 VDC	√		

ลงชื่อ มณฑิลาภรณ์ ทศพรทอง ผู้ตรวจเช็ค

(.....)

วันที่ 13 / 11 / 68

ลงชื่อ.....ผู้รับบริการตรวจเช็ค

(.....)

วันที่

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
8 FL.	Room. 801									Smoke 2 ตัว, Heat 1 ตัว
8 FL.	Room. 802									Smoke 2 ตัว, Heat 1 ตัว
8 FL.	Room. 803									Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Room. 804									Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Room. 806	✓		✓		✓		✓		Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Room. 808	✓		✓		✓		✓		Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Room. 810	✓		✓		✓		✓		Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Room. 812									Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Room. 814									Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Room. 816	✓		✓		✓		✓		Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Room. 818									Smoke 1 ตัว, Heat 1 ตัว
8 FL.	Corridor (Lift)									Smoke 2 ตัว
8 FL.	Electrical room									Smoke 1 ตัว
8 FL.	Corridor (Guest room)									Smoke 3 ตัว, Manual 3 ตัว, Heat 2 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
9 FL.	Room. 901									Smoke 2 ตัว , Heat 1 ตัว
9 FL.	Room. 902									Smoke 2 ตัว , Heat 1 ตัว
9 FL.	Room. 903									Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 904									Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 905									Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 906									Smoke 1 ตัว
9 FL.	Room. 907									Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 908	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 909									Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 910									Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 911									Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 912									Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 914									Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 915	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 916									Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Room. 918									Smoke 1 ตัว , Heat 1 ตัว
9 FL.	Corridor (Lift)									Smoke 2 ตัว
9 FL.	Electrical room									Smoke 1 ตัว
9 FL.	Corridor (Guest room)									

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
10 FL.	Room. 1001									Smoke 2 ตัว , Heat 1 ตัว
10 FL.	Room. 1002									Smoke 2 ตัว , Heat 1 ตัว
10 FL.	Room. 1003									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1004									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1005									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1006									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1007									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1008									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1009									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1010	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1011									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1012									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1014									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1015									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1016									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Room. 1018									Smoke 1 ตัว , Heat 1 ตัว
10 FL.	Corridor (Lift)									
10 FL.	Electrical room									
10 FL.	Corridor (Guest room)									

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
12 FL.	Room. 1201									Smoke 2 ตัว , Heat 1 ตัว
12 FL.	Room. 1202									Smoke 2 ตัว , Heat 1 ตัว
12 FL.	Room. 1203									Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Room. 1204									Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Room. 1205									Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Room. 1206									Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Room. 1207									Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Room. 1208	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Room. 1209									Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Room. 1210									Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Room. 1211									Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Room. 1212									Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Room. 1214									Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Room. 1216									Smoke 1 ตัว , Heat 1 ตัว
12 FL.	Corridor (Lift)									
12 FL.	Electrical room									
12 FL.	Corridor (Guest room)									

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
16 FL.	Room. 1601	✓		✓		✓		✓		Smoke 2 ตัว , Heat 1 ตัว
16 FL.	Room. 1602									Smoke 2 ตัว , Heat 1 ตัว
16 FL.	Room. 1603									Smoke 1 ตัว , Heat 1 ตัว
16 FL.	Room. 1604									Smoke 1 ตัว , Heat 1 ตัว
16 FL.	Room. 1605									Smoke 1 ตัว , Heat 1 ตัว
16 FL.	Room. 1606									Smoke 1 ตัว , Heat 1 ตัว
16 FL.	Room. 1607									Smoke 1 ตัว , Heat 1 ตัว
16 FL.	Room. 1608									Smoke 1 ตัว , Heat 1 ตัว
16 FL.	Room. 1609									Smoke 1 ตัว , Heat 1 ตัว
16 FL.	Room. 1610	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
16 FL.	Room. 1612									Smoke 1 ตัว , Heat 1 ตัว
16 FL.	Room. 1614									Smoke 1 ตัว , Heat 1 ตัว
16 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 2 ตัว
16 FL.	Electrical room									Smoke 1 ตัว
16 FL.	Corridor (Guest room)									Manual 4 ตัว , Smoke 4 ตัว
16 FL.	M-57 Open Z. A									
16 FL.	M-59 Open Z. C									

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
17 FL.	Room. 1701	✓		✓		✓		✓		Smoke 2 ตัว , Heat 1 ตัว
17 FL.	Room. 1702									Smoke 2 ตัว , Heat 1 ตัว
17 FL.	Room. 1703									Smoke 1 ตัว , Heat 1 ตัว
17 FL.	Room. 1704									Smoke 1 ตัว , Heat 1 ตัว
17 FL.	Room. 1705									Smoke 1 ตัว , Heat 1 ตัว
17 FL.	Room. 1706									Smoke 1 ตัว , Heat 1 ตัว
17 FL.	Room. 1707									Smoke 1 ตัว , Heat 1 ตัว
17 FL.	Room. 1708	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
17 FL.	Room. 1709									Smoke 1 ตัว , Heat 1 ตัว
17 FL.	Room. 1710									Smoke 1 ตัว , Heat 1 ตัว
17 FL.	Room. 1712									Smoke 1 ตัว , Heat 1 ตัว
17 FL.	Room. 1714	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
17 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 2 ตัว
17 FL.	Electrical room									Smoke 1 ตัว
17 FL.	Corridor (Guest room)									Manual 4 ตัว , Smoke 4 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
18 FL.	Room. 1801									Smoke 2 ตัว , Heat 1 ตัว
18 FL.	Room. 1802									Smoke 2 ตัว , Heat 1 ตัว
18 FL.	Room. 1803									Smoke 1 ตัว , Heat 1 ตัว
18 FL.	Room. 1804									Smoke 1 ตัว , Heat 1 ตัว
18 FL.	Room. 1805									Smoke 1 ตัว , Heat 1 ตัว
18 FL.	Room. 1806									Smoke 1 ตัว , Heat 1 ตัว
18 FL.	Room. 1807									Smoke 1 ตัว , Heat 1 ตัว
18 FL.	Room. 1808									Smoke 1 ตัว , Heat 1 ตัว
18 FL.	Room. 1809									Smoke 1 ตัว , Heat 1 ตัว
18 FL.	Room. 1810	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
18 FL.	Room. 1812									Smoke 1 ตัว , Heat 1 ตัว
18 FL.	Room. 1814	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
18 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 1 ตัว
18 FL.	Electrical room									Smoke 1 ตัว
18 FL.	Corridor (Guest room)									Manual 4 ตัว , Smoke 4 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
20 FL.	Room. 2001									Smoke 2 ตัว , Heat 1 ตัว
20 FL.	Room. 2002									Smoke 2 ตัว , Heat 1 ตัว
20 FL.	Room. 2003									Smoke 1 ตัว , Heat 1 ตัว
20 FL.	Room. 2004									Smoke 1 ตัว , Heat 1 ตัว
20 FL.	Room. 2005									Smoke 1 ตัว , Heat 1 ตัว
20 FL.	Room. 2006	√		√		√		√		Smoke 1 ตัว , Heat 1 ตัว
20 FL.	Room. 2007									Smoke 1 ตัว , Heat 1 ตัว
20 FL.	Room. 2008									Smoke 1 ตัว , Heat 1 ตัว
20 FL.	Room. 2010									Smoke 1 ตัว , Heat 1 ตัว
20 FL.	Room. 2012									Smoke 1 ตัว , Heat 1 ตัว
20 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 2 ตัว
20 FL.	Electrical room									Smoke 1 ตัว
20 FL.	Corridor (Guest room)									Manual 2 ตัว , Smoke 3 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
21 FL.	Room. 2101	✓		✓		✓		✓		Smoke 2 ตัว , Heat 1 ตัว
21 FL.	Room. 2102	✓		✓		✓		✓		Smoke 2 ตัว , Heat 1 ตัว
21 FL.	Room. 2103									Smoke 1 ตัว , Heat 1 ตัว
21 FL.	Room. 2104									ไม่ Alarm
21 FL.	Room. 2105									Smoke 1 ตัว , Heat 1 ตัว
21 FL.	Room. 2106	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
21 FL.	Room. 2107									Smoke 1 ตัว , Heat 1 ตัว
21 FL.	Room. 2108									Smoke 1 ตัว , Heat 1 ตัว
21 FL.	Room. 2110									Smoke 1 ตัว , Heat 1 ตัว
21 FL.	Room. 2112	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
21 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 2 ตัว
21 FL.	Electrical room									Smoke 1 ตัว
21 FL.	Corridor (Guest room)									Manual 2 ตัว , Smoke 2 ตัว
21 FL.	M-75 Open									

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
22 FL.	Room. 2201	✓		✓		✓		✓		Smoke 2 ตัว , Heat 1 ตัว
22 FL.	Room. 2202	✓		✓		✓		✓		Smoke 2 ตัว , Heat 1 ตัว
22 FL.	Room. 2203									Smoke 1 ตัว , Heat 1 ตัว
22 FL.	Room. 2204									Smoke 1 ตัว , Heat 1 ตัว
22 FL.	Room. 2205	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
22 FL.	Room. 2206	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
22 FL.	Room. 2208									Smoke 1 ตัว , Heat 1 ตัว
22 FL.	Room. 2210	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
22 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 2 ตัว
22 FL.	Electrical room									Smoke 1 ตัว
22 FL.	Corridor (Guest room)									Manual 2 ตัว , Smoke 3 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
23 FL.	Room. 2301									Smoke 2 ตัว , Heat 1 ตัว
23 FL.	Room. 2302									Smoke 2 ตัว , Heat 1 ตัว
23 FL.	Room. 2303									Smoke 1 ตัว , Heat 1 ตัว
23 FL.	Room. 2304									Smoke 1 ตัว , Heat 1 ตัว
23 FL.	Room. 2305									Smoke 1 ตัว , Heat 1 ตัว
23 FL.	Room. 2306									Smoke 1 ตัว , Heat 1 ตัว
23 FL.	Room. 2308									Smoke 1 ตัว , Heat 1 ตัว
23 FL.	Room. 2310	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
23 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 2 ตัว
23 FL.	Electrical room									Smoke 1 ตัว
23 FL.	Corridor (Guest room)									Manual 2 ตัว , Smoke 3 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
25 FL.	Room. 2501									Smoke 1 ตัว , Heat 1 ตัว
25 FL.	Room. 2502	✓		✓		✓		✓		Smoke 2 ตัว , Heat 1 ตัว
25 FL.	Room. 2503									Smoke 1 ตัว , Heat 1 ตัว
25 FL.	Room. 2504	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
25 FL.	Room. 2505									Smoke 1 ตัว , Heat 1 ตัว
25 FL.	Room. 2506	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
25 FL.	Room. 2508									Smoke 1 ตัว , Heat 1 ตัว
25 FL.	Room. 2510									Smoke 1 ตัว , Heat 1 ตัว
25 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 2 ตัว
25 FL.	Electrical room									Smoke 1 ตัว
25 FL.	Corridor (Guest room)									Manual 2 ตัว , Smoke 2 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
26 FL.	Room. 2601									Smoke 2 ตัว , Heat 1 ตัว
26 FL.	Room. 2602									Smoke 2 ตัว , Heat 1 ตัว
26 FL.	Room. 2603									Smoke 1 ตัว , Heat 1 ตัว
26 FL.	Room. 2604	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
26 FL.	Room. 2606	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
26 FL.	Room. 2608	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
26 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 2 ตัว
26 FL.	Electrical room									Smoke 1 ตัว
26 FL.	Corridor (Guest room)									Manual 2 ตัว , Smoke 2 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
27 FL.	Room. 2701									Smoke 2 ตัว , Heat 1 ตัว
27 FL.	Room. 2702	√		√		√		√		Smoke 2 ตัว , Heat 1 ตัว
27 FL.	Room. 2703									Smoke 1 ตัว , Heat 1 ตัว
27 FL.	Room. 2704									Smoke 1 ตัว , Heat 1 ตัว
27 FL.	Room. 2706									Smoke 1 ตัว , Heat 1 ตัว
27 FL.	Room. 2708									Smoke 1 ตัว , Heat 1 ตัว
27 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 2 ตัว
27 FL.	Electrical room									Smoke 1 ตัว
27 FL.	Corridor (Guest room)									Manual 2 ตัว , Smoke 2 ตัว
27 FL.	Zone A									

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
28 FL.	Room. 2801									Smoke 2 ตัว , Heat 1 ตัว
28 FL.	Room. 2802	✓		✓		✓		✓		Smoke 2 ตัว , Heat 1 ตัว
28 FL.	Room. 2803									Smoke 1 ตัว , Heat 1 ตัว
28 FL.	Room. 2804									Smoke 1 ตัว , Heat 1 ตัว
28 FL.	Room. 2806									Smoke 1 ตัว LED , Heat 1 ตัว
28 FL.	Room. 2808	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
28 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 2 ตัว
28 FL.	Electrical room									Smoke 1 ตัว
28 FL.	Corridor (Guest room)									Manual 2 ตัว , Smoke 2 ตัว

หมายเหตุ :

TEST REPORT FIRE ALARM SYSTEM



PROJECT : SHAMA LAKEVIEW (BUILDING -B)

FLOOR ชั้น	Location สถานที่	MANUAL PULL STATION		ALARM BELL		SMOKE DETECTOR		HEAT DETECTOR		REMARK หมายเหตุ
		Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	Pass	Not Pass	
29 FL.	Room. 2901									Smoke 2 ตัว , Heat 1 ตัว
29 FL.	Room. 2902	✓		✓		✓		✓		Smoke 2 ตัว , Heat 1 ตัว
29 FL.	Room. 2903	✓		✓		✓		✓		Smoke 1 ตัว , Heat 1 ตัว
29 FL.	Room. 2904									Smoke 1 ตัว , Heat 1 ตัว
29 FL.	Room. 2906									Smoke 1 ตัว , Heat 1 ตัว
29 FL.	Room. 2908									Smoke 1 ตัว , Heat 1 ตัว
29 FL.	Corridor (Lift)									Manual 1 ตัว , Smoke 2 ตัว
29 FL.	Electrical room									Smoke 1 ตัว
29 FL.	Corridor (Guest room)									Manual 2 ตัว , Smoke 2 ตัว

หมายเหตุ :

J.P SOUTHERN LIMITED PARTNERSHIP

ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ ก.ท.ม. 10240

โทร: 02-734-9615, 02-734-9618-9 โทรสาร: 02-734-6904

.....
ปัญหาที่ยังไม่ได้รับการแก้ไข

โครงการ: SHAMA LAKEVIEW TOWER B

วันที่.....13/11/2568.....

NO.	รายการอุปกรณ์ที่มีปัญหา	อาการ	วันที่แจ้ง	หมายเหตุ

ลงชื่อผู้ตรวจเช็ค.....*วิมลดา อารักษ์กุล*.....

วันที่.....*13/11/68*.....

ลงชื่อผู้รับการตรวจเช็ค.....

วันที่.....

รูปภาพประกอบ

BUILDING – A,B

J.P SOUTHERN LIMITED PARTNERSHIP

ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)



J.P SOUTHERN LIMITED PARTNERSHIP

ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)



J.P SOUTHERN LIMITED PARTNERSHIP


ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)



J.P SOUTHERN LIMITED PARTNERSHIP


ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)



J.P SOUTHERN LIMITED PARTNERSHIP

ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)

9



10



J.P SOUTHERN LIMITED PARTNERSHIP


ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)



J.P SOUTHERN LIMITED PARTNERSHIP


ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)



J.P SOUTHERN LIMITED PARTNERSHIP


ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)



J.P SOUTHERN LIMITED PARTNERSHIP


ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)



J.P SOUTHERN LIMITED PARTNERSHIP


ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)



J.P SOUTHERN LIMITED PARTNERSHIP


ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)

21		
22		

J.P SOUTHERN LIMITED PARTNERSHIP



ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)

23		
24		

J.P SOUTHERN LIMITED PARTNERSHIP


ห้างหุ้นส่วนจำกัด เจ. พี เซาท์เทิร์น

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กทม. 10240

โทรศัพท์ : 02-734-9615,02-734-9618-9 โทรสาร: 02-734-6904

PROJECT : JR KYUSHU BUSINESS DEVELOPMENT (THAILAND) CO.,LTD.

ตรวจเช็ค และ TEST อุปกรณ์ FIRE ALARM SYSTEM (โครงการ SHAMA LAKEVIEW TOWER A,B)



J.P. SOUTHERN LIMITED, PARTNERSHIP

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนพหลโยธิน แขวงคลองจั่น เขตบางกะปิ กรุงเทพฯ 10240
TEL : (662) 734-9615, (662) 734-9618-9 FAX : (662) 734-6904

DATE

วันที่ 9/10 พ.ค 68

ร. 6848

SERVICE REPORT รายงานการบริการ

11110696

ฉบับ

Customer Name

(ชื่อลูกค้า)

Shoma

Address

(ที่อยู่)

CONDITION
(ลักษณะงาน)

☐

WARRANTY
(ประกัน)

☐

MAINTENANCE
(บำรุงรักษา)

☐

PER CALL
(โทรตาม)

☐

OTHER
(อื่นๆ)

PRODUCT OF :
(สินค้า)

Fire Alarm System

MODEL NO.
(รุ่น)

Simplex 4100ES

SERVICE SUBJECT :-

ขอ ร.ป. โดยช่างเทคนิค Test Fire Alarm ตามปกติ

1. 806 (B)

810 (B) / View Heat 1 ตัว

2. 808 (B)

816 (B) / View Heat 1 ตัว

3. 810 (B)

4. 816 (B)

5. 908 (B)

ACTION :

6. 915 (B)

Test Smoke

7. 1010 (B)

8. 1208 (B)

9. 1601 (B)

PL 21 (B)

10. 1610 (B)

PL 19 (B)

Test Corridor

11. 1701 (B)

PL 17 (B)

12. 1703 (B)

PL 16 (B)

13. 1810 (B)

PL 15 (B)

REMARKS :

14. 1814 (B)

สฟ. 1 ตัว / 1 ตัว / 1 ตัว / 1 ตัว

ช่างเทคนิค ช่างเทคนิค

PROBLEM SOLVED
(การแก้ไข)

☐

Yes
(งานเรียบร้อย)

☐

Observing
(สังเกตการณ์)

☐

Follow Up
(ติดตาม)

SERVICE START
(เริ่มงาน)

10

11

68

FINISH
(เสร็จงาน)

10

11

68

ช่างเทคนิค ช่างเทคนิค

Visit

SERVICE REPRESENTATIVE
(ผู้ให้บริการ)

CUSTOMER
(ผู้รับบริการ)

J.P. SOUTHERN LIMITED, PARTNERSHIP

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กรุงเทพฯ 10240
TEL: (662) 734-9615, (662) 734-9618-9 FAX: (662) 734-6904

DATE 11/11/68

ครั้งที่ 9/10 ม.บ 68

5.6848

SERVICE REPORT รายงานการบริการ

11130268

ต้นฉบับ

Customer Name

(ชื่อลูกค้า)

Shams (โสด)

Address

(ที่อยู่)

CONDITION
(ลักษณะงาน)

☐ WARRANTY
(ประกัน)

☐ MAINTENANCE
(บำรุงรักษา)

☐ PER CALL
(โทรตาม)

☐ OTHER
(อื่นๆ)

PRODUCT OF :
(สินค้า)

Five Alarm

MODEL NO.
(รุ่น)

SERVICE SUBJECT :-

นาง J.P. Southern ได้เข้ามาทดสอบ test ระบบไฟ Alarm Building B

FL. 17 ห้อง 1714

FL. 20 ห้อง 2006

FL. 21 ห้อง 2101, 2102, 2106, 2112

FL. 22 ห้อง 2202, 2205, 2210, 2206, 2201

FL. 23 ห้อง 2310

FL. 25 ห้อง 2506

ACTION :- FL. 26 ห้อง 2608

FL. 27 ห้อง 2702

FL. 29 ห้อง 2902, 2903

REMARKS :-

(ห้อง 2702 Two bedroom ได้เข้ามาทดสอบ test เมื่อเวลา 11:00 น.)

PROBLEM SOLVED
(การแก้ไข)

☒ Yes
(งานเรียบร้อย)

☐ Observing
(สังเกตการณ์)

☐ Follow Up
(ติดตาม)

SERVICE START
(เริ่มงาน)

11 11 68

FINISH
(เสร็จงาน)

11 11 68

พ.ศ. 68

R/P 11/11/2025

SERVICE REPRESENTATIVE
(ผู้ให้บริการ)

CUSTOMER
(ผู้รับบริการ)

J.P. SOUTHERN LIMITED, PARTNERSHIP

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กรุงเทพฯ 10240
TEL: (662) 734-9615, (662) 734-9618-9 FAX: (662) 734-6904

DATE

วันที่ 9/10 พ.ย ๕๖
ร. ๖๘๔๘

SERVICE REPORT รายงานการบริการ

11110699

ต้นฉบับ

Customer Name	_____
(ชื่อลูกค้า)	Shama
Address	_____
(ที่อยู่)	_____

CONDITION (ลักษณะงาน)	☐ WARRANTY (ประกัน)	☐ MAINTENANCE (บำรุงรักษา)	☐ PER CALL (โทรตาม)	☐ OTHER (อื่นๆ)
PRODUCT OF : (สินค้า)	Fire Alarm System		MODEL NO. (รุ่น)	Simplex 4100 BS

SERVICE SUBJECT :-

ขอ J.P. ได้ทดสอบ Test smoke, manual ตามนั้มีดังนี้

1. 2201 (B)	9. 2802 (B)	* ได้ทดสอบ Test Alarm bell มีดังนี้
2. 2206 (B)	10. 2808 (B)	
3. 2502 (B)	11. 2902 (B)	
4. 2504 (B)	12. 2903 (B)	
5. 2604 (B)	13. 1015 (A)	
6. 2606 (B)	14. 1104 (A)	

ACTION :-

FL 22
FL 23
FL 25
FL 26
FL 27

สรุปได้ว่าระบบได้ผลเป็นที่พอใจ

REMARKS :-

7. 2606 (B)
8. 2608 (B)

ขอ ร. ๖๘๔๘

PROBLEM SOLVED (การแก้ไข)	☐ Yes (งานเรียบร้อย)	☐ Observing (สังเกตการณ์)	☐ Follow Up (ติดตาม)
SERVICE START (เริ่มงาน)	12 11 68	FINISH (เสร็จงาน)	12 11 68

ขอ ร. ๖๘๔๘	
()	()
SERVICE REPRESENTATIVE (ผู้ให้บริการ)	CUSTOMER (ผู้รับบริการ)

J.P. SOUTHERN LIMITED, PARTNERSHIP

1111 ซอย 38 (การเคหะแห่งชาติ) ถนนนวมินทร์ แขวงคลองจั่น เขตบางกะปิ กรุงเทพฯ 10240
TEL : (662) 734-9615, (662) 734-9618-9 FAX : (662) 734-6904

DATE

วันที่ 9/10 พ.ย. 68

5.6848

11110700

SERVICE REPORT รายงานการบริการ

ต้นฉบับ

Customer Name

(ชื่อลูกค้า)

Shama

Address

(ที่อยู่)

CONDITION
(ลักษณะงาน)

☐

WARRANTY
(ประกัน)

☐

MAINTENANCE
(บำรุงรักษา)

☐

PER CALL
(โทรตาม)

☐

OTHER
(อื่นๆ)

PRODUCT OF :
(สินค้า)

Fire Alarm System

MODEL NO.
(รุ่น)

Simplex 4100 ES

SERVICE SUBJECT :-

ทพ. J.P. ได้เข้าตรวจสอบ Test Smoke, ทดสอบ
ติดตั้ง

1. FL 809 (A) 8. FL 2111 (A)

2. FL 909 (A)

ACTION :-

3. FL 911 (A) * ได้ตรวจสอบ Alarm R. 20 ชั่ว

4. FL 915 (A) 2009, 2010, 2011 Zone B ได้ตรวจสอบ

5. FL 1212 (A) ใช้งานได้ปกติ

REMARKS

6. FL 1509 (A)

7. FL 2011 (A)

ทพ. ช่างเทคนิค

PROBLEM SOLVED
(การแก้ไข)

☐

Yes
(งานเรียบร้อย)

☐

Observing
(สังเกตการณ์)

☐

Follow Up
(ติดตาม)

SERVICE START
(เริ่มงาน)

13

11

68

FINISH
(เสร็จงาน)

13

11

68

ทพ. ช่างเทคนิค

()

SERVICE REPRESENTATIVE
(ผู้ให้บริการ)

X

()

CUSTOMER
(ผู้รับบริการ)

ภาคผนวกที่ 13

ทีมปฏิบัติการฉุกเฉิน

SAB

Fire & Emergency Plan

Fire Related Information

Fire Prevention and Contingency

The outbreak of a fire in a Shama lakeview asoke is a serious danger, which requires appropriate action in order to safeguard guests, Team Members and assets alike.

As indicated in the title of this dossier, a coherent fire plan must include prevention, which will minimize the chances of a fire erupting.

However, no amount of preparation may totally exclude a fire outbreak, and a contingency plan is necessary.

This document will therefore serve as a guide to establish the property's fire prevention and contingency planning

Information

General

Fire is a serious hazard which requires quick and decisive actions to combat it. In order to minimize the chances of a fire erupting and adequately fighting it, a basic understanding of the different matters related to fire and methods to extinguish it is therefore necessary.

Causes of fire

Fires occur for several reasons, either accidental or intentional. According to research, the major causes of hotel fires are the following:

- | | |
|---------------------|---|
| • Human error | (72% of hotel fires), which are induced by a Team Member or a guest's actions |
| • Equipment failure | (15%) |
| • Electrical | (9%) |
| • Arson | (4%) |

Information

Types of fire and extinguishers

There are six different classes of fire, which require different methods for extinguishing them

CLASS	FUEL/HEAT SOURCE	IDEOGRAM	EXTINGUISHER
A	Solid materials of an organic nature (e.g. wood, paper, cloth, etc.)		- Water hose - Dry chemical extinguisher (not to be used in a closed area) - Carbone dioxide extinguisher - Halon extinguisher
B	Liquids (e.g. petrol, diesel, paint, etc.)		- Dry chemical extinguisher (not to be used in a closed area) - Carbone dioxide extinguisher - Halon extinguisher
C	Flammable gases		- Dry chemical extinguisher (not to be used in a closed area) - Carbone dioxide extinguisher - Halon extinguisher
D	Flammable metals (e.g. magnesium, aluminium, titanium, etc.)		Dry powder extinguisher
E	Electric equipment		Halon extinguisher
F	Cooking oil or fat	NONE	Wet chemical extinguisher

Information

Types of fire alarms

Several systems may be implemented to warn guests and/or Team Members of the breakout of a fire in the hotel:

- Smoke detectors
- Heat detectors
- Manual stations
- Sprinkler flows
- Oral alarm

HOW TO USE A FIRE EXTINGUISHER

Remember the Phrase **PASS**



Types of fire alarms

Smoke detectors

- Provide effective and immediate warning to occupants of the building in case of problems or hazards
- Often the first warning of a fire outbreak
- Linked to the main fire alarm control room by an uninterruptible power supply system



Heat detectors

- Provide effective and immediate warning to occupants of the building in case of problems or hazards
- Linked to the main fire alarm control room by an uninterruptible power supply system



Manual stations

- Need to be physically activated in the case of a fire outbreak



Sprinkler flows

- Usually charged with water and linked to a master pumping system and water tanks
- Linked to the main fire alarm control room



Chapter 1

Actions to be taken in the event of finding a fire
or other emergencies– number to be called.



Instructions for person discover fire

1. Respond to all fire alarms as if they are real. Hesitating for even a moment can have devastating consequences.
2. Control the spread of smoke by closing all doors, including laundry chutes
3. Clear the corridors by removing all housekeeping, maintenance, and service carts. Place them in service areas or vacant rooms.
4. Help evacuate the area. Provide aid to guests with disabilities. Assist guests with directions to the nearest exits.
5. Implement departmental procedures.
6. Meet at the Assembly Area.





Fire action

1. Operate nearest fire alarm.
2. Leave building by nearest exit.
3. Report to assembly point.

Behind of Tower A

Do not use lifts



เมื่อพบเหตุเพลิงไหม้

1. กดปุ่มแจ้งเหตุฉุกเฉินที่ใกล้ที่สุด และโทรแจ้งหมายเลข '0' ทันที
2. รีบไปจุดรวมพลเพื่อความปลอดภัย โดยใช้บันไดหนีไฟที่ใกล้ที่สุด
3. จุดรวมพลของโรงแรมอยู่ที่ ด้านหลังตึก A

ห้ามใช้ลิฟต์เด็ดขาด

Security

1. Rush to the fire area.
2. Having the security guards to control the entrance of hotel in order to prevent the external persons get into the premises.
 - Entrance exit for employees
 - Front gate at guard house area
 - Hotel entrance at Lobby Area.
3. Arrange Security Guards to control the road at entrance exit area of the hotel in order to stop any vehicles getting into the hotel premises except fire trucks.
4. Coordinate with police fire truck when arriving to the hotel.
5. Take care of fire trucks to the right parking space.

THE PROCEDURE FOR RESPONSIBLE DUTIES OF VARIOUS SECTIONS

Engineering

1. Rush to the accident area.
2. Set up all elevators to station at ground floor after helping the employees.
3. Turn off all electrical switches, which connected to the accident area.
4. Inspect the operation of fire elevator.
5. Be sure all employees have already evacuated from the area.
6. Coordinate with police fire brigade department for building structure.


Accounting

1. Keep all the important documents.
2. Keep all money, checks and proprietary documents in the safe.
3. Turn off all electrical switches, remove all electrical plugs of office equipment from the outlets.
4. Close all doors and windows.
5. Rush to the assembly point.

Housekeeping

1. Check master keys including all documents in the safe place.
2. Evacuate all guests from the rooms by knocking the door starting from the highest floor.
3. Inform all guests to keep the keys with themselves and prepare wet handkerchief for helping breath.
4. Open the room for inspection if no answer when knocking the door.
5. Show the way and inform guests going to the nearest fire escape.
6. Tell everybody not to use the elevator, if necessary they must use the fire lift.
8. Hang sign "CHECKED" at all doors and windows that guests have already been evacuated.
9. Turn off the switches of all machines.
1. Turn off all electrical switches including computers and keep all diskettes in the safe place.
8. Keep all-important documents.
9. Rush to the assembly point

Emergency flow chart



Human Resources

1. Keep all-important documents.
2. Turn off all electrical switches and appliances at staff canteen.
3. Prepare all employees name list.
4. Be sure all remained employees have already been evacuated.
5. Close and lock all doors.
6. Timekeeper has to carry First Aids Boxes for helping employees.
7. Rush to the assembly point.
8. Check the name of all employees who work on that day. (repeat for every 15 minutes)
9. Make names' list of the loss persons to the police fire brigade for scorching.
10. Review the names' list of all guests.

GM's Office/Sales/ Executive Office

1. Keep all-important documents.
2. Turn off all electrical switches and office equipment.
3. Close and lock all doors.

Chapter 2 Training plan 2019

ONYX Fire Life Safety, Health & Safety and Security Training Calendar 2019				
Month	Subject	Who	Fire Life & Safety Training	Type
Jan	Fire, Life Safety	ERT & EST (Morning Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
	Fire, Life Safety	ERT & EST (Afternoon Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
Feb	Fire, Life Safety	ALL TMs	2 hours training session for all TMs on Fire Prevention, What to do in the event of a fire, OHS Emergency Codes & Evacuation Drills and Guest Requiring Assistance	Lecture & Test
	Fire, Life Safety	ERT & EST (Night Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
Mar	Fire, Life Safety	Eng/Sec/ERT/MODs	Elevator Entrapment Training	Practical Drill
	Fire, Life Safety	ERT & EST (Morning Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
Apr	Fire, Life Safety	ERT & EST (Afternoon Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
	Fire, Life Safety	Sec & Front Office TMs	Guest Requiring Evacuation Assistance Drill	Practical Drill
May	Fire, Life Safety	ERT & EST (Night Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
	Fire, Life Safety	ERT & EST (Morning Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
Jun	Fire, Life Safety	All TMs	Fire Prevention Campaign	Exhibits and Posters
	Fire, Life Safety	ERT & EST (Afternoon Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
Aug	Fire, Life Safety	Laundry TMs	Specialist Laundry Fire Training	Practical Drill
	Fire, Life Safety	ERT & EST (Night Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
Sep	Fire, Life Safety	Engineering TMs	Specialist Plant Room Fire Training	Practical Drill
	Fire, Life Safety	ERT & EST (Morning Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
Oct	Fire, Life Safety	Kitchen TMs	Specialist Plant Room Fire Training	Practical Drill
	Fire, Life Safety	ERT & EST (Afternoon Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
Nov	Fire, Life Safety	Eng/Sec/ERT/MODs	Elevator Entrapment Training	Practical Drill
	Fire, Life Safety	ERT & EST (Night Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill
Dec	Fire, Life Safety	ERT & EST (Night Shift)	Silent Reaction Drill including MOD as Fire Commander	Practical Drill

Information

Escape routes

1. A clear and uninterrupted exit to a safe ground level exterior location is mandatory throughout the hotel.
2. Escape routes must lead the guests or Team Members through a protected and smoke insulated horizontal exit zone (e.g. corridor, etc.), to a protected vertical zone (e.g. fire escape staircase, etc.), before finally leading to open air.
3. The escape routes must be direct and offer protection, as well as clear signage and segregation from potentially dangerous areas (e.g. kitchens, machine rooms, etc.).
4. Escape routes must never be obstructed by objects

Chapter 3 Escape routes



Fire escape staircases

1. Fire doors must be installed at every fire escape staircase entrance/exit, in order to make the area sealable.
2. The escape staircases must be pressurized and if possible without windows or openings other than doors.



TOWER A

TOWER B





Chapter 4

ERT&EST Organization chart

Emergency Response Team (ERT)		
Morning Shift	Afternoon Shift	Night Shift
Engineering	Engineering	Engineering
Engineering	Engineering	Engineering
Security	Security	Security



ERT + EST	
Emergency Response Team : 3 man 24/7 (Department)	Emergency Support Team : 3 man 24/7 (Department)
Engineering	Engineering
Engineering	Security
Security	House Man/Concierge or Bell Man

Emergency Support Team (EST)		
Morning Shift	Afternoon Shift	Night Shift
Engineering	House Man	House Man
Engineering	Concierge/Bell	Concierge/Bell
Security	Security	Security



Chapter 5

Evacuation Assemble points




Chapter 6

Department in the event of an Evacuation

Chapter 7

Maintenance & inspect of fire fighting equipment & system



FL501-05 Record of the monthly inspection of the Fire Fighting Team equipment									
Item	Description	Total	SAB FIRE FIGHTING TEAM EQUIPMENT PICTURE	W1	W2	W3	W4	Remark	
1.	Fire suits / ໔໔໔໔໔໔໔໔	2							
2.	Breathing apparatus / ໔໔໔໔໔໔໔໔	2							
3.	Helmet / ໔໔໔໔໔໔໔໔	2							
4.	Boots / ໔໔໔໔໔໔໔໔	2							
Item	Description	Total	SAB FIRE FIGHTING TEAM EQUIPMENT PICTURE	W1	W2	W3	W4	Remark	
10.	Big Hammer / ໔໔໔໔໔໔໔໔	1							
11.	Roll Cutter / ໔໔໔໔໔໔໔໔	1							
12.	Big Axe / ໔໔໔໔໔໔໔໔	1							
13.	Small Axe / ໔໔໔໔໔໔໔໔	2							
14.	Crowbar / ໔໔໔໔໔໔໔໔	2							

General Manager

Hotel Manager

Human resource Department

Housekeeping Department

Engineering Department

Sale & Marketing Department

IT Manager

Front office Department

Security Department

Finance Department

THANK YOU



ผลการตรวจสอบคุณภาพน้ำในสระน้ำ ประจำเดือนมกราคม-มิถุนายน 2569



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 2620126 วันที่ (Date) 23 มกราคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำระวายน้ำ
รหัสตัวอย่าง (Sample No.) No. 6901253
ลักษณะตัวอย่างทางกายภาพ ใสไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวบ์ บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามา เลดวิว โอโตก
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 14 มกราคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 14 มกราคม 2569 - 23 มกราคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 13 มกราคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำระวายน้ำ			
Alkalinity	mg/L	61.2	-	80 - 100	APHA, AWWA, WEF 24 th ed. 2023, 2320 B
Ammonia	mg/L	1.6	-	≤ 20	APHA, AWWA, WEF 24 th ed. 2023, 4500-NH ₃ C
Calcium Hardness	mg/L	102	-	250 - 600	APHA, AWWA, WEF 24 th ed. 2023, 3500-Ca B
Chloride	mg/L	70.0	-	≤ 600	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl ⁻ B
Free Chlorine	mg/L	0.65	-	0.6 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl B
Combined Chlorine	mg/L	0.25	-	0.5 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl F
Cyanuric Acid	mg/L	80	-	30 - 60	adaptation of the Turbidimetric method ^{3/}
Nitrate	mg/L	2.493	-	≤ 50	APHA, AWWA, WEF 24 th ed. 2023, 4500-NO ₃ E
pH	-	7.0	-	7.2 - 8.4	APHA, AWWA, WEF 24 th ed. 2023, 4500-H ⁺ B
Escherichia coli	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 F
Staphylococcus aureus	per 100 mL	Not Detected	-	Not Detected	In-house method based on APHA, AWWA, WEF 24 th ed. 2023, 9213 B
Total Coliform Bacteria	MPN/100 mL	< 1.1	-	< 10	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 E
Pseudomonas aeruginosa	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9213 E

หมายเหตุ : ^{1/} ค่าแนะนำของคณะกรรมการสาธารณสุข ฉบับที่ 1 / 2550 เรื่อง การควบคุมการประกอบกิจการระวายน้ำ หรือกิจการอื่นๆ ในทำนองเดียวกัน


^{3/} from Cyanuric Acid Photometer

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิภารัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้เป็นสำเนาถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 2630126 วันที่ (Date) 23 มกราคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำใช้
รหัสตัวอย่าง (Sample No.) No. 6901254
ลักษณะตัวอย่างทางกายภาพ สีไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอร์ คิววี บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 14 มกราคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 14 มกราคม 2569 - 23 มกราคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 13 มกราคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำใช้			
Total Coliform Bacteria ✓	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E

หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดื่มได้ พ.ศ. 2563


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากรหัส

- สภาวะแวดล้อมของห้องปฏิบัติการ $25 \pm 5^{\circ}\text{C}$

- ✓ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING

No.0090

รายงานหมายเลข (Report No.) 2640126 วันที่ (Date) 23 มกราคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำใช้
รหัสตัวอย่าง (Sample No.) No. 6901255
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 14 มกราคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 14 มกราคม 2569 - 23 มกราคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 13 มกราคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำใช้			
Total Coliform Bacteria √	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E

หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดี พ.ศ. 2563


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากรายงาน

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ทุกรายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025:2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง



(นายฐานันท์ นิราณันต์)
ผู้จัดการฝ่ายวิชาการ



(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำหนังสือ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0550226 วันที่ (Date) 13 กุมภาพันธ์ 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำสระว้ายน้ำ
รหัสตัวอย่าง (Sample No.) No. 6902047
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 กุมภาพันธ์ 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 กุมภาพันธ์ 2569 - 13 กุมภาพันธ์ 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 3 กุมภาพันธ์ 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำสระว้ายน้ำ			
Alkalinity	mg/L	67.9	-	80 - 100	APHA, AWWA, WEF 24 th ed. 2023, 2320 B
Ammonia	mg/L	2.2	-	≤ 20	APHA, AWWA, WEF 24 th ed. 2023, 4500-NH ₃ C
Calcium Hardness	mg/L	112	-	250 - 600	APHA, AWWA, WEF 24 th ed. 2023, 3500-Ca B
Chloride	mg/L	492	-	≤ 600	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl ⁻ B
Free Chlorine	mg/L	1.35	-	0.6 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl B
Combined Chlorine	mg/L	0.25	-	0.5 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl F
Cyanuric Acid	mg/L	80	-	30 - 60	adaptation of the Turbidimetric method ^{3/}
Nitrate	mg/L	2.195	-	≤ 50	APHA, AWWA, WEF 24 th ed. 2023, 4500-NO ₃ E
pH	-	7.5	-	7.2 - 8.4	APHA, AWWA, WEF 24 th ed. 2023, 4500-H ⁺ B
Escherichia coli	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 F
Staphylococcus aureus	per 100 mL	Not Detected	-	Not Detected	In-house method based on APHA, AWWA, WEF 24 th ed. 2023, 9213 B
Total Coliform Bacteria	MPN/100 mL	< 1.1	-	< 10	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 E
Pseudomonas aeruginosa	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9213 E

หมายเหตุ : ^{1/} ค่าแนะนำของคณะกรรมการสาธารณสุข ฉบับที่ 1 / 2550 เรื่อง การควบคุมการประกอบกิจการสระว้ายน้ำ หรือกิจการอื่นๆ ในทำนองเดียวกัน

^{3/} from Cyanuric Acid Photometer

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่ได้จากลูกค้า

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง

สุรินทร์ นิธิรัตน์
(นายสุรินทร์ นิธิรัตน์)
ผู้จัดการฝ่ายวิชาการ

ปิยนุช
(นางสาวปิยนุช วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0560226 วันที่ (Date) 13 กุมภาพันธ์ 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำใช้
รหัสตัวอย่าง (Sample No.) No. 6902048
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวบ์ บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 กุมภาพันธ์ 2569 วันที่ตรวจวิเคราะห์ (Analyse Date) 4 กุมภาพันธ์ 2569 - 13 กุมภาพันธ์ 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 3 กุมภาพันธ์ 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำใช้			
Total Coliform Bacteria √	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E

หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดื่มได้ พ.ศ. 2563


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากรหัส

- สภาวะแวดล้อมของห้องปฏิบัติการ $25 \pm 5^{\circ}\text{C}$

- √ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025:2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิรันดร์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางปิ่น เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0570226 วันที่ (Date) 13 กุมภาพันธ์ 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำใช้
รหัสตัวอย่าง (Sample No.) No. 6902049
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ ดีวู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขาม เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 กุมภาพันธ์ 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 กุมภาพันธ์ 2569 - 13 กุมภาพันธ์ 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 3 กุมภาพันธ์ 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำใช้			
Total Coliform Bacteria ✓	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E

หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดื่มได้ พ.ศ. 2563

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ✓ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง

จิรวัฒน์ นิพัทธ์
(นายฐานันท์ นิพัทธ์)
ผู้จัดการฝ่ายวิชาการ

อริพรพร
(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jaruksanitwong 46 Jarunsnitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0330326 วันที่ (Date) 13 มีนาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำสระว่ายน้ำ
รหัสตัวอย่าง (Sample No.) No. 6903028
ลักษณะตัวอย่างทางกายภาพ ใสไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวบ์ บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลควิว อโศก
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 มีนาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 มีนาคม 2569 - 13 มีนาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 มีนาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำสระว่ายน้ำ			
Alkalinity	mg/L	49.6	-	80 - 100	APHA, AWWA, WEF 24 th ed. 2023, 2320 B
Ammonia	mg/L	4.2	-	≤ 20	APHA, AWWA, WEF 24 th ed. 2023, 4500-NH ₃ C
Calcium Hardness	mg/L	160	-	250 - 600	APHA, AWWA, WEF 24 th ed. 2023, 3500-Ca B
Chloride	mg/L	560	-	≤ 600	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl ⁻ B
Free Chlorine	mg/L	0.40	-	0.6 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl B
Combined Chlorine	mg/L	0.25	-	0.5 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl F
Cyanuric Acid	mg/L	80	-	30 - 60	adaptation of the Turbidimetric method ^{3/}
Nitrate	mg/L	4.462	-	≤ 50	APHA, AWWA, WEF 24 th ed. 2023, 4500-NO ₃ E
pH	-	6.8	-	7.2 - 8.4	APHA, AWWA, WEF 24 th ed. 2023, 4500-H ⁺ B
Escherichia coli	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 F
Staphylococcus aureus	per 100 mL	Not Detected	-	Not Detected	In-house method based on APHA, AWWA, WEF 24 th ed. 2023, 9213 B
Total Coliform Bacteria	MPN/100 mL	< 1.1	-	< 10	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 E
Pseudomonas aeruginosa	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9213 E

หมายเหตุ : ^{1/} ค่าแนะนำของคณะกรรมการสาธารณสุข ฉบับที่ 1/2550 เรื่อง การควบคุมการประกอบกิจการสระว่ายน้ำ หรือกิจการอื่นๆ ในทำนองเดียวกัน

^{3/} from Cyanuric Acid Photometer

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่ได้รับจากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีใบอนุญาตไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราณัน)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0340326 วันที่ (Date) 13 มีนาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำใต้ดิน
รหัสตัวอย่าง (Sample No.) No. 6903029
ลักษณะตัวอย่างทางกายภาพ สีตะกอนสีขาว
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวบิ นิสเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชาลินา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 มีนาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 มีนาคม 2569 - 13 มีนาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 มีนาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำใต้ดิน			
pH	-	7.2	-	6.5-8.5	APHA, AWWA, WEF 24 th ed. 2023, 4500-H ⁺ B
Turbidity	NTU	0.23	-	≤ 5.0	In-house method based on APHA, AWWA, WEF 24 th ed. 2023, 2130 B
Arsenic (As)	mg/L	Not Detected	-	≤ 0.01	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Cadmium (Cd)	mg/L	Not Detected	-	≤ 0.003	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Chromium (Cr)	mg/L	Not Detected	-	≤ 0.05	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Copper (Cu)	mg/L	Not Detected	-	≤ 1.0	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3111 B
Iron (Fe)	mg/L	Not Detected	-	≤ 0.3	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3111 B
Lead (Pb)	mg/L	Not Detected	-	≤ 0.01	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Manganese (Mn)	mg/L	Not Detected	-	≤ 0.3	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Mercury (Hg)	mg/L	Not Detected	-	≤ 0.001	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Zinc (Zn)	mg/L	0.0063	-	≤ 3.0	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Total Coliform Bacteria	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E

หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดื่มได้ พ.ศ. 2563

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่ได้จากลูกค้า

- สถานะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่ปฎิบัติด้วยตัวเอง

(นายฐานันท์ นิภารัตน์)
ผู้จัดการฝ่ายวิชาการ

(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ไปรับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำให้องค์รับ



บริษัท เอชวีอี จำกัด 603 ซอยเจริญสุขนิทวงศ์ 46 ถนนเจริญสุขนิทวงศ์ แขวงบางมด เขตบางพลี กรุงเทพมหานคร 10700
HVE CO. LTD. 603 Soi Jarungrasmitwong 48 Jarungrasmitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0350326 วันที่ (Date) 13 มีนาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำใต้ดิน
รหัสตัวอย่าง (Sample No.) No. 6903030
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวซี มิลินส์ ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 มีนาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 มีนาคม 2569 - 13 มีนาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 มีนาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำใต้ดิน			
pH	-	7.2	-	6.5-8.5	APHA, AWWA, WEF 24 th ed. 2023, 4500-H ⁺ B
Turbidity	NTU	0.31	-	≤ 5.0	In-house method based on APHA, AWWA, WEF 24 th ed. 2023, 2130 B
Arsenic (As)	mg/L	Not Detected	-	≤ 0.01	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Cadmium (Cd)	mg/L	Not Detected	-	≤ 0.003	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Chromium (Cr)	mg/L	Not Detected	-	≤ 0.05	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Copper (Cu)	mg/L	Not Detected	-	≤ 1.0	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3111 B
Iron (Fe)	mg/L	Not Detected	-	≤ 0.3	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3111 B
Lead (Pb)	mg/L	Not Detected	-	≤ 0.01	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Manganese (Mn)	mg/L	Not Detected	-	≤ 0.3	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Mercury (Hg)	mg/L	Not Detected	-	≤ 0.001	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Zinc (Zn)	mg/L	0.0208	-	≤ 3.0	APHA, AWWA, WEF 24 th ed. 2023, 3030 E, 3120 B
Total Coliform Bacteria	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E


หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดื่มได้ พ.ศ. 2563

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่ยกตัวอย่างเอง


(นายฐานันท์ นิการัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทวิพรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำหนังสือ



บริษัท เอชวี จำกัด 603 ซอยเจริญสุขนิทวงศ์ 46 ถนนเจริญสุขนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0900426 วันที่ (Date) 11 เมษายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำใช้
รหัสตัวอย่าง (Sample No.) No. 6904084
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 2 เมษายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 2 เมษายน 2569 - 11 เมษายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 1 เมษายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำใช้			
Total Coliform Bacteria ✓	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E

หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดื่มได้ พ.ศ. 2563


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากรหัส

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ✓ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ใช้ตัวอย่างเอง


(นายฐานันท์ นิราธิ์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0910426 วันที่ (Date) 11 เมษายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำไข่
รหัสตัวอย่าง (Sample No.) No. 6904085
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวพี บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 2 เมษายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 2 เมษายน 2569 - 11 เมษายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 1 เมษายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำไข่			
Total Coliform Bacteria √	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E

หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดื่มได้ พ.ศ. 2563


^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- √ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิภารัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ไม่รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0890426 วันที่ (Date) 11 เมษายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำสระว่ายน้ำ
รหัสตัวอย่าง (Sample No.) No. 6904083
ลักษณะตัวอย่างทางกายภาพใสไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอร์ คิวู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 2 เมษายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 2 เมษายน 2569 - 11 เมษายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 1 เมษายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำสระว่ายน้ำ			
Alkalinity	mg/L	82.2	-	80 - 100	APHA, AWWA, WEF 24 th ed. 2023, 2320 B
Ammonia	mg/L	3.3	-	≤ 20	APHA, AWWA, WEF 24 th ed. 2023, 4500-NH ₃ C
Calcium Hardness	mg/L	155	-	250 - 600	APHA, AWWA, WEF 24 th ed. 2023, 3500-Ca B
Chloride	mg/L	60.0	-	≤ 600	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl B
Free Chlorine	mg/L	0.20	-	0.6 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl B
Combined Chlorine	mg/L	0.40	-	0.5 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl F
Cyanuric Acid	mg/L	50	-	30 - 60	adaptation of the Turbidimetric method ^{3/}
Nitrate	mg/L	2.208	-	≤ 50	APHA, AWWA, WEF 24 th ed. 2023, 4500-NO ₃ E
pH	-	7.3	-	7.2 - 8.4	APHA, AWWA, WEF 24 th ed. 2023, 4500-H ⁺ B
Escherichia coli	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 F
Staphylococcus aureus	per 100 mL	Not Detected	-	Not Detected	In-house method based on APHA, AWWA, WEF 24 th ed. 2023, 9213 B
Total Coliform Bacteria	MPN/100 mL	< 1.1	-	< 10	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 E
Pseudomonas aeruginosa	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9213 E

หมายเหตุ : ^{1/} ค่าแนะนำของคณะกรรมการสาธารณสุข ฉบับที่ 1/2550 เรื่อง การควบคุมการประกอบกิจการสระว่ายน้ำ หรือกิจการอื่นๆ ในทำนองเดียวกัน

^{3/} from Cyanuric Acid Photometer

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากรหัส

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีใบอนุญาตไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0610526 วันที่ (Date) 13 พฤษภาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำสระว่ายน้ำ
รหัสตัวอย่าง (Sample No.) No. 6905065
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมขามมา เลควิว อโศก
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 พฤษภาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 พฤษภาคม 2569 - 13 พฤษภาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 พฤษภาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำสระว่ายน้ำ			
Alkalinity	mg/L	74.5	-	80 - 100	APHA, AWWA, WEF 24 th ed. 2023, 2320 B
Ammonia	mg/L	5.6	-	≤ 20	APHA, AWWA, WEF 24 th ed. 2023, 4500-NH ₃ C
Calcium Hardness	mg/L	233	-	250 - 600	APHA, AWWA, WEF 24 th ed. 2023, 3500-Ca B
Chloride	mg/L	342	-	≤ 600	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl ⁻ B
Free Chlorine	mg/L	2.00	-	0.6 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl B
Combined Chlorine	mg/L	0.70	-	0.5 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl F
Cyanuric Acid	mg/L	80	-	30 - 60	adaptation of the Turbidimetric method ^{3/}
Nitrate	mg/L	0.264	-	≤ 50	APHA, AWWA, WEF 24 th ed. 2023, 4500-NO ₃ E
pH	-	7.1	-	7.2 - 8.4	APHA, AWWA, WEF 24 th ed. 2023, 4500-H ⁺ B
<i>Escherichia coli</i>	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 F
<i>Staphylococcus aureus</i>	per 100 mL	Not Detected	-	Not Detected	In-house method based on APHA, AWWA, WEF 24 th ed. 2023, 9213 B
Total Coliform Bacteria	MPN/100 mL	< 1.1	-	< 10	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 E
<i>Pseudomonas aeruginosa</i>	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9213 E

หมายเหตุ : ^{1/} ค่าแนะนำของคณะกรรมการสาธารณสุข ฉบับที่ 1/2550 เรื่อง การควบคุมการประกอบกิจการสระว่ายน้ำ หรือกิจการอื่นๆ ในทำนองเดียวกัน


^{3/} from Cyanuric Acid Photometer

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากการคำนวณ

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่ใช้ตัวอย่างเอง


(นายฐานันท์ นิภารัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้นำมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0620526 วันที่ (Date) 13 พฤษภาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำใช้
รหัสตัวอย่าง (Sample No.) No. 6905066
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวยู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 พฤษภาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 พฤษภาคม 2569 - 13 พฤษภาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 พฤษภาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำใช้			
Total Coliform Bacteria	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E

หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดื่มได้ พ.ศ. 2563

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สถานะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายรณันท์ นิรารัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0630526 วันที่ (Date) 13 พฤษภาคม 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำใช้
รหัสตัวอย่าง (Sample No.) No. 6905067
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวยู บิลิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 4 พฤษภาคม 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 4 พฤษภาคม 2569 - 13 พฤษภาคม 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 2 พฤษภาคม 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำใช้			
Total Coliform Bacteria	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E

หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดี พ.ศ. 2563

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากรหัส

- สภาวะแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์
ทะเบียนเลขที่ ว-358-ค-0002

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยเจริญสุขนิทวงศ์ 46 ถนนเจริญสุขนิทวงศ์ แขวงบางมด เขตบางพลี กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0630626 วันที่ (Date) 13 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำสระวัยน้ำ
รหัสตัวอย่าง (Sample No.) No. 6906052
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวู มิลินส์ ดีโพลเมนท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว โอทีค
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 5 มิถุนายน 2569 - 13 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำสระวัยน้ำ			
Alkalinity	mg/L	85.0	-	80 - 100	APHA, AWWA, WEF 24 th ed. 2023, 2320 B
Ammonia	mg/L	3.4	-	≤ 20	APHA, AWWA, WEF 24 th ed. 2023, 4500-NH ₃ C
Calcium Hardness	mg/L	111	-	250 - 600	APHA, AWWA, WEF 24 th ed. 2023, 3500-Ca B
Chloride	mg/L	50.0	-	≤ 600	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl ⁻ B
Free Chlorine	mg/L	0.00	-	0.6 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl B
Combined Chlorine	mg/L	1.70	-	0.5 - 1.0	APHA, AWWA, WEF 24 th ed. 2023, 4500-Cl F
Cyanuric Acid	mg/L	80	-	30 - 60	adaptation of the Turbidimetric method ^{3/}
Nitrate	mg/L	6.155	-	≤ 50	APHA, AWWA, WEF 24 th ed. 2023, 4500-NO ₃ ⁻ E
pH	-	6.8	-	7.2 - 8.4	APHA, AWWA, WEF 24 th ed. 2023, 4500-H ⁺ B
<i>Escherichia coli</i>	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 F
<i>Staphylococcus aureus</i>	per 100 mL	Not Detected	-	Not Detected	In-house method based on APHA, AWWA, WEF 24 th ed. 2023, 9213 B
Total Coliform Bacteria	MPN/100 mL	< 1.1	-	< 10	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 G
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9221 E
<i>Pseudomonas aeruginosa</i>	per 100 mL	Not Detected	-	Not Detected	APHA, AWWA, WEF 24 th ed. 2023, 9213 E

หมายเหตุ : ^{1/} ค่าเฉลี่ยของคณะกรรมการสาธารณสุข ฉบับที่ 1/2550 เรื่อง การควบคุมการประกอบกิจการสระวัยน้ำ หรือกิจการอื่นๆ ในทำนองเดียวกัน

^{3/} from Cyanuric Acid Photometer

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่ได้จากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ห้องปฏิบัติการมีนโยบายไม่รับตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsnitwong 46 Jarunsnitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834958 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0640626 วันที่ (Date) 13 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำใช้
รหัสตัวอย่าง (Sample No.) No. 6906053
ลักษณะตัวอย่างทางกายภาพ สีไม่ผิดปกติก่อน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ ดีวู อีสเทส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมริมน้ำ เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 5 มิถุนายน 2569 - 13 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำใช้			
Total Coliform Bacteria ✓	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E

หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดื่มได้ พ.ศ. 2563

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่มาจากลูกค้า

- สภาวะแวดล้อมของห้องปฏิบัติการ $25 \pm 5^{\circ}\text{C}$

- วัสดุภาชนะที่เก็บตัวอย่างต้องผ่านการฆ่าเชื้อและแห้งสนิทก่อนใช้

- วัสดุภาชนะที่เก็บตัวอย่างต้องผ่านการฆ่าเชื้อและแห้งสนิทก่อนใช้

- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง

สุรินทร์ นิกรรัตน์
(นายสุรินทร์ นิกรรัตน์)
ผู้จัดการฝ่ายวิชาการ

อริยาพร
(นางสาวอริยาพร วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับการทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700.
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ (ANALYSIS REPORT)



TESTING
No.0090

รายงานหมายเลข (Report No.) 0650626 วันที่ (Date) 13 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^c น้ำใช้
รหัสตัวอย่าง (Sample No.) No. 6906054
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ สิวู มัลติส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 5 มิถุนายน 2569 - 13 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน ^{1/} (Standard)	วิธีทดสอบ ^{4/} (Test Method)
		น้ำใช้			
Total Coliform Bacteria ✓	MPN/100 mL	< 1.1	-	< 1.1	APHA, AWWA, WEF 24 th ed. 2023, 9221 B, 9221 C
Fecal Coliform Bacteria	MPN/100 mL	Not Detected	-	-	APHA, AWWA, WEF 24 th ed. 2023, 9221 E

หมายเหตุ : ^{1/} ประกาศกรมอนามัย เรื่อง เกณฑ์คุณภาพน้ำประปาดื่มได้ พ.ศ. 2563

^{4/} Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 24th ed. 2023

^c เป็นข้อมูลที่ได้จากลูกค้า

- สภาพแวดล้อมของห้องปฏิบัติการ 25 ± 5 °C

- ✓ รายการที่ได้รับการรับรองความสามารถห้องปฏิบัติการทดสอบตามมาตรฐาน ISO/IEC 17025 : 2017 จากกองบริหารและรับรองห้องปฏิบัติการ กรมวิทยาศาสตร์บริการ

- ห้องปฏิบัติการมีนโยบายไม่ยกตัวอย่างเอง

สุรินทร์ นิลรัตน์
(นายสุรินทร์ นิลรัตน์)
ผู้จัดการฝ่ายวิชาการ

ปิณฑาพร
(นางสาวปิณฑาพร วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ




บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0660626 วันที่ (Date) 16 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^๐ Hot Water
รหัสตัวอย่าง (Sample No.) No. 6906055
ลักษณะตัวอย่างทางกายภาพ ใส ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^๐ บริษัท เจอาร์ คิวซ์ บิซิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^๐ โรงแรมชามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^๐ เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analyse Date) 5 มิถุนายน 2569 - 16 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^๐ 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^๐ เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ (Test Method)
		Hot Water			
Legionella	CFU/L	Not Detected	-	-	ISO 11731:2017

หมายเหตุ :^๐ เป็นข้อมูลที่มาจากลูกค้า
- สภาวะแวดล้อมของห้องปฏิบัติการ $25 \pm 5^{\circ}\text{C}$
- ห้องปฏิบัติการมีนโยบายไม่ใช้ตัวอย่างเอง


(นายฐานันท์ นิราณต์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด




บริษัท เอชวีอี จำกัด 603 ซอยเจริญสุขนิทวงศ์ 46 ถนนเจริญสุขนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0670626 วันที่ (Date) 16 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^c Hot Water
รหัสตัวอย่าง (Sample No.) No. 6906056
ลักษณะตัวอย่างทางกายภาพ ใส ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวซี บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 5 มิถุนายน 2569 - 16 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ (Test Method)
		Hot Water			
Legionella	CFU/L	Not Detected	-	-	ISO 11731:2017

หมายเหตุ :^c เป็นข้อมูลที่มาจากการสุ่ม
- สภาวะแวดล้อมของห้องปฏิบัติการ $25 \pm 5^{\circ}\text{C}$
- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราธรัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์

- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำหนังสือ



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Soi Jarunsnitwong 46 Jarunsnitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0680626 วันที่ (Date) 16 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^o Domestic Cold Water
รหัสตัวอย่าง (Sample No.) No. 6906057
ลักษณะตัวอย่างทางกายภาพ สีไม่มีตะกอน
ชื่อลูกค้า (Customer name)^o บริษัท เจอาร์ คิวบ์ อีลิเนส ดีโวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^o โรงแรมชามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^o เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 5 มิถุนายน 2569 - 16 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^o 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^o เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ (Test Method)
		Domestic Cold Water			
Legionella	CFU/L	Not Detected	-	-	ISO 11731:2017

หมายเหตุ :^o เป็นข้อมูลที่มาจากลูกค้า
- สภาวะแวดล้อมของห้องปฏิบัติการ $25 \pm 5^\circ\text{C}$
- ห้องปฏิบัติการมีนโยบายไม่ชักตัวอย่างเอง


(นายฐานันท์ นิราณันท์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งหมด



บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700
HVE CO. LTD. 603 Sol Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0690626 วันที่ (Date) 16 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^c Domestic Cold Water
รหัสตัวอย่าง (Sample No.) No. 6906058
ลักษณะตัวอย่างทางกายภาพ ใส ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^c บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^c โรงแรมชามา เลควิว อโศก (อาคาร B)
ที่อยู่ (Address)^c เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 5 มิถุนายน 2569 - 16 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^c 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^c เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ (Test Method)
		Domestic Cold Water			
Legionella	CFU/L	Not Detected	-	-	ISO 11731:2017

หมายเหตุ :^c เป็นข้อมูลที่มาจากลูกค้า
- สภาวะแวดล้อมของห้องปฏิบัติการ $25 \pm 5^{\circ}\text{C}$
- ห้องปฏิบัติการมีนโยบายไม่เก็บตัวอย่างเอง

จิรโรจน์ นันทกุล
(นายฐานันท์ นิการัตน์)
ผู้จัดการฝ่ายวิชาการ

อติพรพร
(นางสาวทิพวรรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์

- รายงานผลการทดสอบนี้ได้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ




บริษัท เอชวีอี จำกัด 603 ซอยจรัญสนิทวงศ์ 46 ถนนจรัญสนิทวงศ์ แขวงบางยี่ขัน เขตบางพลัด กรุงเทพฯ 10700 .
HVE CO. LTD. 603 Soi Jarunsanitwong 46 Jarunsanitwong Road Bangyeekan Bangplad Bangkok 10700
Tel : (02) 8834956-7 , (02) 8834274 Fax : (02) 8834956 E-mail address hv_eng@hotmail.com

รายงานผลการทดสอบ
(ANALYSIS REPORT)

รายงานหมายเลข (Report No.) 0700626 วันที่ (Date) 16 มิถุนายน 2569
ชื่อตัวอย่าง (Sample Name)^o Swimming pool
รหัสตัวอย่าง (Sample No.) No. 6906059
ลักษณะตัวอย่างทางกายภาพ ใส่ไม่มีตะกอน
ชื่อลูกค้า (Customer name)^o บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด (สาขาที่ 0001)
สถานที่เก็บตัวอย่าง (Sampling site)^o โรงแรมขามา เลควิว อโศก (อาคาร A)
ที่อยู่ (Address)^o เลขที่ 41 สุขุมวิท ซอย 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพมหานคร 10110
วันที่รับตัวอย่าง (Received Date) 5 มิถุนายน 2569 วันที่ตรวจวิเคราะห์ (Analysis Date) 5 มิถุนายน 2569 - 15 มิถุนายน 2569
วันที่เก็บตัวอย่าง (Collected Date)^o 4 มิถุนายน 2569 วิธีการเก็บตัวอย่าง (Sampling Method)^o เก็บแบบ จ้วง (Grab)

พารามิเตอร์ (Parameter)	หน่วย (Unit)	ผลการวิเคราะห์ (Result)	MDL	ค่ามาตรฐาน (Standard)	วิธีทดสอบ (Test Method)
		Swimming pool			
Legionella	CFU/L	Not Detected	-	-	ISO 11731:2017

หมายเหตุ :^o เป็นข้อมูลที่ได้จากลูกค้า
- สภาวะแวดล้อมของห้องปฏิบัติการ $25 \pm 5^{\circ}\text{C}$
- ห้องปฏิบัติการมีนโยบายไม่ใช้ตัวอย่างเอง


(นายฐานันท์ นิรารัตน์)
ผู้จัดการฝ่ายวิชาการ


(นางสาวพิชญพรณ วงศ์บุญตัน)
ผู้ควบคุมดูแลห้องปฏิบัติการวิเคราะห์


- รายงานผลการทดสอบนี้ใช้รับรองเฉพาะตัวอย่างตามที่ได้รับมาทดสอบเท่านั้น
- ห้ามนำรายงานผลการทดสอบนี้ไปประกาศโฆษณา
- รายงานผลการทดสอบนี้ห้ามคัดลอกถ่ายทำสำเนาเฉพาะเพียงบางส่วน โดยไม่ได้รับอนุญาตจากห้องปฏิบัติการเป็นลายลักษณ์อักษร ยกเว้นทำทั้งฉบับ

ภาคผนวกที่ 15

รายงานแบบ ทส.1 และ ทส.2

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

วัน เดือน ปี	สถิติและข้อมูลที่ได้รับจากแหล่งกำเนิดดังนี้													ปริมาณรวมตะกอนส่วนเกินที่ได้ออกจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรคและแนวทางแก้ไข
	ปริมาณการใช้ในธุรกิจของแหล่งกำเนิด (ลบ.ม.)	ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.)	การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย (ลบ.ม.)	ปริมาณสารเคมีหรือสารอันตรายที่ใส่ (ชื่อ/ปริมาณ) (ลิตรหรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย						ปริมาณตะกอนส่วนเกินที่ได้ออกจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรคและแนวทางแก้ไข			
					ระบบบำบัดน้ำเสีย (ประสิทธิภาพ/ประสิทธิผล)	เครื่องสูบน้ำ (ประสิทธิภาพ/ประสิทธิผล)	เครื่องเติมอากาศ/บำบัด (ประสิทธิภาพ/ประสิทธิผล)	เครื่องกรอง/แยกน้ำเสีย (ประสิทธิภาพ/ประสิทธิผล)	เครื่องกวน/ผสมสารเคมี (ประสิทธิภาพ/ประสิทธิผล)	อื่นๆ (ระบุ) (ประสิทธิภาพ/ประสิทธิผล)					
1/1/26	678.40	68	54.4	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-		
2/1/26	678.40	76	60.8	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-		
3/1/26	678.40	75	60.0	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-		
4/1/26	678.40	38	30.4	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-		
5/1/26	678.40	119	95.2	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-		
6/1/26	678.40	60	48.0	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	มีขยะจุด	
7/1/26	678.40	76	60.8	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	ต้นน้ำ	
8/1/26	678.40	45	36.0	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	โดยสายชะ	
9/1/26	678.40	76	60.8	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	ขุดจาก	
10/1/26	678.40	79	63.2	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	เครื่องเดิม	
11/1/26	678.40	75	60.0	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	อากาศ	
12/1/26	678.40	69	55.2	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-		

สถิติและข้อมูลที่ได้มาจากแหล่งกำเนิดมลพิษ															
วัน เดือน ปี	ปริมาณ การใช้ไฟฟ้า ของระบบ บำบัดน้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในภารกิจของกอง แสงสว่างเดิมพลีชน (ลบ.ม.)	ปริมาณน้ำเสียที่ เข้าระบบ บำบัดน้ำเสีย(ลบ. ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย(ระบาย/ ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด สีภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	ปริมาณ สารเคมีหรือ สารสกัด สีภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย						ปริมาณ ตะกอน ส่วนเกิน ที่เกิดขึ้นจาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรค และแนวทาง แก้ไข	ลายมือชื่อ ผู้บันทึก
							เครื่องสูบน้ำ (ประสิทธิภาพ) (ปกติ/ผิดปกติ)	เครื่องเติม อากาศ(ปกติ/ ผิดปกติ)	เครื่องถวณ/ ผสมน้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องสูบ ตะกอน (ปกติ/ผิดปกติ)	อื่นๆ (ระบุ) (ปกติ/ ผิดปกติ)				
11/1/26	678.40	68	54.4	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-		
13/1/26	678.40	50	40.0	ระบาย			ปกติ	ปกติ	-	ปกติ	-	-	-		
14/1/26	678.40	77	61.6	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-		
15/1/26	678.40	77	61.6	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-		
16/1/26	678.40	83	66.4	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-		
17/1/26	678.40	83	66.4	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-		
18/1/26	678.40	80	64.0	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-		
19/1/26	678.40	76	60.8	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-		
20/1/26	678.40	76	60.8	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-		
21/1/26	678.40	76	60.8	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-	มีขยะอุดตัน	
22/1/26	678.40	84	67.2	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-	ตันแก๊ซ	
23/1/256	678.40	43	34.4	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-	โดยเขาขยะ	
24/1/26	678.40	83	66.4	ระบาย	-	-	ปกติ	ปกติ	-	ปกติ	-	-	-	ชอกจาก	

[illegible]

แบบ ทส. ๒

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

หมายเหตุ

๑.ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน

๒.ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

.....เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(..... นาย เคนนิส ของ)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(.....นายมานพ.....วิสุทธิชัยกุล.....)

ใบอนุญาตเลขที่ หมดอายุ.....

ออกให้โดย.....

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

.....เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(..... นาย เคนนิส ของ)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(..... นายมานพวิสุทธิชัยกุล.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

- (๑) ประเภท/ชนิดของระบบบำบัดน้ำเสียระบบแอกติเวเต็ดสลัดจ์.....
ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย.....214...ลบ.ม./วัน
- (๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง.....24...ชั่วโมง/วัน
☐ แบบไม่ต่อเนื่อง (ระยะ).....
- (๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ
☐ เครื่องกวน/ผสมน้ำเสีย ☐ เครื่องกวน/ผสมสารเคมี
☐ เครื่องสูบละกอน ☐ อื่น ๆ (ระบุ).....“--“.....
- (๔) แหล่งรองรับน้ำทิ้ง (ระบุ)ท่าสะพานน้ำสาธารณะ.....
- (๕) วิธีการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด.....จ้างรถสูบลมสูบเพื่อนำไปกำจัด

๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)๖๗๘.๔๘
- (๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.).....๒๑.๑๖๓
- (๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) ...๑.๖๓๘.๔
- (๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสียระบายนทุกวัน.....
- (๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม) น้ำหมักจุลินทรีย์ 200 ลิตร.
- (๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบุ).....
 - เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบุ).....
 - เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบุ).....
 - เครื่องกวน/ผสมน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบุ) “--“.....
 - เครื่องกวน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบุ) “--“.....
 - เครื่องสูบละกอน ☐ ปกติ ☐ ผิดปกติ (ระบุ)..... “--“.....
 - อื่นๆ ☐ ปกติ ☐ ผิดปกติ (ระบุ)..... “--“.....
- (๗) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.) “--“.....
- (๘) ปัญหา อุปสรรค และแนวทางแก้ไข.....มีขยะอุดตันต้นป็นการแก้ไขโดยเอาขยะออกจากเครื่องเติมอากาศ


- คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
- ๒.ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

บบ ทส. ๑

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ซอย สุขุมวิท 16 ถนนสุขุมวิท แขวง/ตำบลคลองเตย
เขต/อำเภอคลองเตยจังหวัด.....กรุงเทพมหานคร. โทรศัพท์02-6631234.....โทรสาร02-6631250.....มี.....บริษัท/เจ้าอา
คิวิซู.มิตินส.ศ.วิไลอุปมนตรี (ไทยแลนด์) จำกัด.....เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการประเภทที่ต้
อวหุยและจอรตร.จำนวน.1๑9 ห้อง.....ใบอนุญาตเลขที่ (ถ้ามี).....129/42.....ออกให้โดย-.....หมดอายุ-.....

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

สถิติและข้อมูลที่ได้จากแหล่งกำเนิดมลพิษ															
ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)	ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.)	ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.)	การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย (ระบาย/ไม่ระบาย)	ปริมาณสารเคมีหรือสารสกัดสีภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือกิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย							ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรคและแนวทางแก้ไข	ลายมือชื่อผู้บันทึก	
					ระบบบำบัดน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)				เครื่องสูบน้ำ (ปกติ/ผิดปกติ)
666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	-	-	-	-	-	-	-	-	-
666.40	73	58.4	ระบาย	-	ปกติ	ปกติ	-	-	-	-	-	-	-	-	เครื่องเดิม
666.40	62	49.6	ระบาย	-	ปกติ	ปกติ	-	-	-	-	-	-	-	-	อากาศ
666.40	69	55.2	ระบาย	-	ปกติ	ปกติ	-	-	-	-	-	-	-	-	-
666.40	37	29.6	ระบาย	-	ปกติ	ปกติ	-	-	-	-	-	-	-	-	-
666.40	51	40.8	ระบาย	-	ปกติ	ปกติ	-	-	-	-	-	-	-	-	-
666.40	74	59.2	ระบาย	-	ปกติ	ปกติ	-	-	-	-	-	-	-	-	-
666.40	53	42.4	ระบาย	-	ปกติ	ปกติ	-	-	-	-	-	-	-	-	-
666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	-	-	-	-	-	-	-	-	-
	1,719	1,375.2													

หมายเหตุ

- 1.ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน
- 2.ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(.....นาย.....เคนนิส.....ของ.....)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(.....นาย.....มานพ.....วิสุทธิอุทัยกุล.....)

ใบอนุญาตเลขที่.....หมดอายุ.....

ออกให้โดย.....

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่.....หมดอายุ.....

ออกให้โดย.....

แบบ ทส. ๒

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

๑. ข้อมูลทั่วไป

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ - ซอย สุขุมวิท16 ถนน สุขุมวิท แขวง/ตำบล คลองเตย
เขต/อำเภอ คลองเตย จังหวัด กรุงเทพมหานคร โทรศัพท์ 02-6631234 โทรสาร 02-6631250
มี บริษัท เจริญ ถิระ นิธิเนส ดีไวออปเม้นท์ (ไทยแลนด์) จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการ
ประเภท ที่พักอาศัยและจอดรถ จำนวน 199 ห้อง ใบอนุญาตเลขที่ (ถ้ามี) 129/42 ออกให้โดย - - - - - หมดอายุ - - - - -
ในการนี้ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษสำหรับ เดือน มกราคม พ.ศ. 2568
ตามที่ได้กำหนดในมาตรา ๘๐ แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. ๒๕๓๕ ในฐานะ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ
(.....นาย เคนนิส.....ของ.....)
.....ผู้ควบคุมระบบบำบัดน้ำเสีย
(.....นายมานพ.....วิสุทธิวิทยกุล.....)
ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย
..... ผู้รับจ้างให้บริการบำบัดน้ำเสีย
(.....)
ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

- (๑) ประเภท/ชนิดของระบบบำบัดน้ำเสียระบบแอกลิเวเต็ดสลัดจ์.....
ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย147..... ลบ.ม./วัน
(๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง24..... ชั่วโมง/วัน
☐ แบบไม่ต่อเนื่อง (ระบุ).....
(๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ
☐ เครื่องกวน/ผสมน้ำเสีย ☐ เครื่องกวน/ผสมสารเคมี
☐ เครื่องสูบละกอน ☐ อื่น ๆ (ระบุ)..... “-”
(๔) แหล่งรองรับน้ำทิ้ง (ระบุ)ท่อระบายน้ำสาธารณะ.....
(๕) วิธีการการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัดจ้างรถสูบน้ำสูบเพื่อนำไปกำจัด

๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน


- (๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) ๖๖๖.๔๑.....
(๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.)๑,๗๑๖.....
(๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.).....๑,๓๗๕.๒๕.....
(๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสียระบายทุกวัน.....
(๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม) น้ำหมักจุลินทรีย์ 200 ลิตร.
(๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบุ).....
- เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
- เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
- เครื่องกวน/ผสมน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
- เครื่องกวน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
- เครื่องสูบละกอน ☐ ปกติ ☐ ผิดปกติ (ระบุ)..... “-”
- อื่นๆ ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
(๗) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.) “-”
(๘) ปัญหา อุปสรรค และแนวทางแก้ไขมีขยะอุดตันค้ำเนินการแก้ไขโดยตนเองออกจากเครื่องเติมอากาศ.....

ถ้าเดือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ
ข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท
หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
๒.ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จต้องระวาง
โทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบ ทส. ๑

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่.....41/1.....หมู่ที่.....-.....ซอย.....สุขุมวิท16.....ถนน.....สุขุมวิท.....แขวง
คลองเตย.....เขต.....คลองเตย.....จังหวัด.....กรุงเทพมหานคร.....โทรศัพท์.....02-6631234.....โทรสาร.....02-6631250.....มี
บริษัท.....เจอาร์ คิวซี บิสิเนส คิวโอปเนนท์ (ไทยแลนด์) จำกัด.....เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบ
กิจการประเภท.....ที่พักอาศัยและจอดรถ.....จำนวน.....230.....ห้อง.....ใบอนุญาตเลขที่.....(ถาวร).....129/42.....ออกให้โดย.....-
.....หมคอาช.....-
.....ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

วัน เดือน ปี	ปริมาณ การใช้ไฟฟ้า ของระบบ บำบัดน้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในธุรกิจของ แต่ละงานผลิตทั้ง (ลบ.ม.)	ปริมาณน้ำเสียที่ ใช้ระบบ บำบัดน้ำเสีย(ลบ. ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย(ระบาย ไม่ระบาย)	ปริมาณ สารเคมีหรือ ชีวภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย							ปริมาณ ตะกอน ส่วนเกิน ที่ติดเ็นจาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรค และแนวทาง แก้ไข	ลายมือชื่อ ผู้บันทึก
						รวมบำบัด น้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติม อากาศ(ปกติ/ ผิดปกติ)	เครื่องกรอง/ ผลน้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องกรอง/ ผลสารเคมี (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	อื่นๆ (รวม) (ปกติ/ ผิดปกติ)			
12/26	678.40	42	33.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
2/2/26	678.40	76	60.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
3/2/26	678.40	76	60.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
4/2/26	678.40	78	62.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
5/2/26	678.40	61	48.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
6/2/26	678.40	59	47.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	มีขยะขุด	
7/2/26	678.40	80	64.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ต้นน้ำแก้ไข	
8/2/26	678.40	75	60.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	โดยทางชะ	
9/2/26	678.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ออกจาก	
10/2/26	678.40	64	51.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	เครื่องเดิม	
11/2/256	678.40	77	61.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	อากาศ	
12/2/26	678.40	47	37.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		

สถิติและข้อมูลที่ได้มาจากแหล่งกำเนิดมลพิษ															
วัน เดือน ปี	ปริมาณ การปล่อยก๊าซ ของระบบ บำบัดน้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในภารกิจของกอง แสงสว่างและมลพิษ (ลบ.ม.)	ปริมาณน้ำเสียที่ เข้าระบบ บำบัดน้ำเสีย(ลบ. ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย(ระบาย/ ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด สีภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	ปริมาณ สารเคมีหรือ สารสกัด สีภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย						ปริมาณ ตะกอน ส่วนเกิน ที่เก็ตรักษาจาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรค และแนวทาง แก้ไข	ลายมือชื่อ ผู้บันทึก
							ระบบบำบัด น้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติม อากาศ(ปกติ/ ผิดปกติ)	เครื่องกลวง/ ผสมน้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องสูบ ตะกอน (ปกติ/ผิดปกติ)	อื่นๆ (ระบุ)			
11/2/26	678.40	42	33.6	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
13/2/26	678.40	75	60.0	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
14/2/26	678.40	80	64.0	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
15/2/26	678.40	77	61.6	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
16/2/26	678.40	78	62.4	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
17/2/26	678.40	78	62.4	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
18/2/26	678.40	77	61.6	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
19/2/26	678.40	75	60.0	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
20/2/26	678.40	75	60.0	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
21/2/26	678.40	90	72.0	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	มีขยะอุดตัน	
22/2/26	678.40	91	72.8	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	ตันแก๊ซ	
23/2/26	678.40	69	55.2	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	โดยเขาขยะ	
24/2/26	678.40	79	63.2	ระบาย	-	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	ชอกจาก	

[illegible]

แบบ ทส. ๒	
หมายเหตุ	รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย
๑.ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน	
๒.ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน	
ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ	
.....เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ (..... นาย เคนนิส ของ)	 เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ (..... นาย เคนนิส ของ)
.....ผู้ควบคุมระบบบำบัดน้ำเสีย (..... นายมานพ วิสุทธิพิทักษ์กุล)	ผู้ควบคุมระบบบำบัดน้ำเสีย (..... นายมานพ วิสุทธิพิทักษ์กุล)
ใบอนุญาตเลขที่ หมดอายุ.....	ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย.....	ออกให้โดย
.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย (.....)	ผู้รับจ้างให้บริการบำบัดน้ำเสีย (.....)
ใบอนุญาตเลขที่ หมดอายุ	ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย	ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

- (๑) ประเภท/ชนิดของระบบบำบัดน้ำเสียระบบแอกติเวเต็ดสลัดจ์.....
- ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย.....214...ลบ.ม./วัน
- (๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง.....24...ชั่วโมง/วัน
- ☐ แบบไม่ต่อเนื่อง (ระบบ).....
- (๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ
- ☐ เครื่องกวน/ผสมน้ำเสีย ☐ เครื่องกวน/ผสมสารเคมี
- ☐ เครื่องสูบละกอน ☐ อื่น ๆ (ระบบ).....“--“.....
- (๔) แหล่งรองรับน้ำทิ้ง (ระบบ)ท่อระบายน้ำสาธารณะ.....
- (๕) วิธีการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด.....จ้างรถสูบลมสูบเพื่อนำไปกำจัด.....

๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)๖๗๘.๔๘
- (๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.).....๒๑๐๐.๕
- (๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) ...๑,๖๑๗.๒๒
- (๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสียระบายนํ้าทุกวัน.....
- (๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม) น้ำหมักจุลินทรีย์ 200 ลิตร.
- (๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบบ).....
 - เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบบ).....
 - เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบบ).....
 - เครื่องกวน/ผสมน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบบ) “--“.....
 - เครื่องกวน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบบ) “--“.....
 - เครื่องสูบละกอน ☐ ปกติ ☐ ผิดปกติ (ระบบ)..... “--“.....
 - อื่นๆ ☐ ปกติ ☐ ผิดปกติ (ระบบ)..... “--“.....
- (๗) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.) “--“.....
- (๘) ปัญหา อุปสรรค และแนวทางแก้ไข.....มีขยะอุดตันต้นป็นการแก้ไขโดยเอาขยะออกจากเครื่องเติมอากาศ.....


- คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
- ๒.ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบ ทส. ๑

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ซอย สุขุมวิท 16 ถนนสุขุมวิท แขวง/ตำบลคลองเตย
เขต/อำเภอคลองเตยจังหวัดกรุงเทพมหานคร.....โทรศัพท์02-6631234.....โทรสาร02-6631250.....มี.....บริษัท/เจ้าอา
คิวิซู.มิตินส.ดีวิลอปเม้นท์ (ไทยแลนด์) จำกัด.....เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการประเภทที่ต้
ออาศัยและจอดรถ.....จำนวน 1๑9 ห้อง.....ใบอนุญาตเลขที่ (ถ้ามี).....129/42.....ออกให้โดย-.....-.....หมดอายุ-.....-.....

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

สถิติและข้อมูลที่ได้จากแหล่งกำเนิดมลพิษ															
วัน เดือน ปี	ปริมาณ การใช้ ไฟฟ้าของ ระบบบำบัด น้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในทุกระยะ ของแหล่งกำเนิด มลพิษ (ลบ.ม.)	ปริมาณน้ำ เสียที่เข้า ระบบ บำบัดน้ำเสีย (ลบ.ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย (ระบาย/ ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด สีภาพที่ใช้ (ชื่อ/ปริมาณ) (ลิตรหรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย							ปริมาณตะกอน ส่วนเกิน ที่เกิดขึ้นจากระบบ บำบัด น้ำเสียที่นำไปกำจัด (ลบ.ม.)	ปัญหา อุปสรรค และ แนวทาง แก้ไข	ลายมือ ชื่อ ผู้บันทึก
						ระบบบำบัด น้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)			
1/2/26	666.40	72	57.6	ระบาย	-	ปกติ	ปกติ	-	-	-	ปกติ	-	-		
24/2/256	666.40	57	45.6	ระบาย	-	ปกติ	ปกติ	-	-	-	ปกติ	-	-	เครื่องเดิม	
25/2/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	-	-	-	ปกติ	-	-	อากาศ	
26/2/256	666.40	51	40.8	ระบาย	-	ปกติ	ปกติ	-	-	-	ปกติ	-	-		
27/2/26	666.40	51	40.8	ระบาย	-	ปกติ	ปกติ	-	-	-	ปกติ	-	-		
28/2/26	666.40	49	39.2	ระบาย	-	ปกติ	ปกติ	-	-	-	ปกติ	-	-		
		1,637	1,309.6												

- หมายเหตุ

๑.ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน
 ๒.ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แนบผลการตรวจวัดคุณภาพน้ำทั้ง
 ทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(.....นาย.....เคนนิส.....ของ.....)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(.....นาย.....มานพ.....วิสุทธิอุทัยกุล.....)

ใบอนุญาตเลขที่หมดอายุ.....

ออกให้โดย.....

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่หมดอายุ

ออกให้โดย.....

แบบ ทส. ๒

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

๑. ข้อมูลทั่วไป

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ - ซอย สุขุมวิท16 ถนน สุขุมวิท แขวง/ตำบล คลองเตย
เขต/อำเภอ คลองเตย จังหวัด กรุงเทพมหานคร โทรศัพท์ 02-6631234 โทรสาร 02-6631250
มี บริษัท เจริญ ถิระ นิธิเนส ดีไวอปรเมนท์ (ไทยแลนด์) จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการ
ประเภท ที่พักอาศัยและจอดรถ จำนวน 199 ห้อง ใบอนุญาตเลขที่ (ถ้ามี) 129/42 ออกให้โดย - - - - - หมดอายุ - - - - -
ในการนี้ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษสำหรับ เดือน กุมภาพันธ์ พ.ศ. 2569
ตามที่ได้กำหนดในมาตรา ๘๐ แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. ๒๕๓๕ ในฐานะ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ
(.....นาย เคนนิส.....ของ.....)
.....ผู้ควบคุมระบบบำบัดน้ำเสีย
(.....นายมานพ.....วิสุทธิวิทยกุล.....)
ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย
..... ผู้รับจ้างให้บริการบำบัดน้ำเสีย
(.....
ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(๑) ประเภท/ชนิดของระบบบำบัดน้ำเสียระบบแอกลิเวเต็ดสลัดจ์.....

ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย147..... ลบ.ม./วัน

(๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง24..... ชั่วโมง/วัน

☐ แบบไม่ต่อเนื่อง (ระบุ).....

(๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ

☐ เครื่องกวน/ผสมน้ำเสีย ☐ เครื่องกวน/ผสมสารเคมี

☐ เครื่องสูบละกอน ☐ อื่น ๆ (ระบุ)..... “-“

(๔) แหล่งรองรับน้ำทิ้ง (ระบุ)ท่อระบายน้ำสาธารณะ.....

(๕) วิธีการการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัดจ้างรถสูบน้ำสูบเพื่อนำไปกำจัด.....

๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

(๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) ๖๖๖.๔๑

(๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.)๑,๖๓๗.....

(๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.).....๑,๓๑๕.๖.....

(๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสียระบายทุกวัน.....

(๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม)น้ำหมักจุลินทรีย์ 200 ลิตร.....

(๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์

- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบุ).....

- เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบุ)

- เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบุ)

- เครื่องกวน/ผสมน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-“

- เครื่องกวน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-“

- เครื่องสูบละกอน ☐ ปกติ ☐ ผิดปกติ (ระบุ)..... “-“

- อื่นๆ ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-“

(๗) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.) “-“


(๘) ปัญหา อุปสรรค และแนวทางแก้ไขมีขยะอุดตันค้ำเนินการแก้ไขโดยตนเองออกจากเครื่องเติมอากาศ.....

ถ้าเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ
ข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท
หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
๒.ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จต้องระวาง
โทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบ ทส. ๑

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่.....41/1.....หมู่ที่.....-.....ซอย.....สุขุมวิท16.....ถนน.....สุขุมวิท.....แขวง
คลองเตย.....เขต.....คลองเตย.....จังหวัด.....กรุงเทพมหานคร.....โทรศัพท์.....02-6631234.....โทรสาร.....02-6631250.....มี
บริษัท.....เจอาร์ คิวซี บิสิเนส คิวโอปเนนท์ (ไทยแลนด์) จำกัด.....เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบ
กิจการประเภท.....ที่พักอาศัยและจอดรถ.....จำนวน.....230.....ห้อง.....ใบอนุญาตเลขที่.....(ถ้ามี).....129/42.....ออกให้โดย.....-
.....หมคอาชู.....-
ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

วัน เดือน ปี	ปริมาณ การใช้ไฟฟ้า ของระบบ บำบัดน้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในปฏิบัติการของ แหล่งกำเนิดมลพิษ (ลบ.ม.)	ปริมาณน้ำเสียที่ ใช้ระบบ บำบัดน้ำเสีย(ลบ. ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย(ระบาย ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด ชีวภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	ปริมาณ รวมบำบัด น้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติม อากาศ(ปกติ/ ผิดปกติ)	เครื่องยก/ ผสมน้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องยก/ ผสมสารเคมี (ปกติ/ผิดปกติ)	เครื่องสูบลม/ ตะกอน (ปกติ/ผิดปกติ)	อื่นๆ (รวม) (ปกติ/ ผิดปกติ)	ปริมาณ ตะกอน ส่วนเกิน ที่ติดเ็นจาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปริมาณอุปสรรค และแนวทาง แก้ไข	ลายมือชื่อ ผู้บันทึก
1/3/26	678.40	38	30.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
2/3/26	678.40	84	67.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
3/3/26	678.40	56	44.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
4/3/26	678.40	62	49.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
5/3/26	678.40	48	38.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
6/3/26	678.40	67	53.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	มีขยะอุด	
7/3/26	678.40	51	40.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ดินแห้ง	
8/3/26	678.40	108	86.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	โดยทางตะ	
9/3/26	678.40	53	42.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ออกจาก	
10/3/26	678.40	113	90.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	เครื่องเดิม	
11/3/26	678.40	205	164.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	อากาศ	
12/3/26	678.40	6	4.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		

สถิติและข้อมูลที่เกี่ยวข้องกับงานแหล่งกำเนิดมลพิษ															
วัน เดือน ปี	ปริมาณ การใช้ไฟฟ้า ของระบบ บำบัดน้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในภารกิจตรวจสอบ แหล่งกำเนิดมลพิษ (ลบ.ม.)	ปริมาณน้ำเสียที่ เข้าระบบ บำบัดน้ำเสีย(ลบ. ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย(ระบาย ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด ชีวมวลที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	การทางของระบบบำบัดน้ำเสีย						ปริมาณ ตะกอน ส่วนเกิน ที่เกิดขึ้นจาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรค และแนวทาง แก้ไข	ลายมือชื่อ ผู้บันทึก	
						ระบบบำบัด น้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติม อากาศ(ปกติ/ ผิดปกติ)	เครื่องกว ส่นน้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องรวม/ ผสมสารเคมี (ปกติ/ผิดปกติ)	อื่นๆ (ระบุ) (ปกติ/ ปกติ/ ผิดปกติ)				
11/3/26	678.40	38	30.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
13/3/26	678.40	37	29.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
14/3/26	678.40	78	62.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
15/3/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
16/3/26	678.40	39	31.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
17/3/26	678.40	76	60.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
18/3/26	678.40	78	62.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
19/3/26	678.40	39	31.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
20/3/26	678.40	82	65.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
21/3/26	678.40	89	71.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	มีขยะจุด	
22/3/26	678.40	86	68.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ต้นน้ำ	
23/3/26	678.40	43	34.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	โดยเขาพระ	
24/3/26	678.40	60	48.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ออกจาก	

[illegible]

แบบ ทส. ๒

หมายเหตุ

๑.ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แบบผลการตรวจวัดคุณภาพน้ำทั้ง
ทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

.....เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ
(นาย เคนนิส ของ)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(นายมานพ วิสุมธิตูทัยกุล)

ใบอนุญาตเลขที่ หมดอายุ.....

ออกให้โดย.....

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

๑. ข้อมูลทั่วไป

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41/1 หมู่ที่ ซอย สุขุมวิท 16 ถนน สุขุมวิท แขวง คลองเตย เขต กรุงเทพมหานคร

จังหวัด.....กรุงเทพมหานคร.....โทรศัพท์.....02-6631234.....โทรสาร.....02-6631250.....

มี บริษัท เจอาร์ คิวชู บิสิเนส ดีเวลอปเม้นท์ (ไทยแลนด์) จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการประเภท

ที่พักอาศัยและจอดรถ จำนวน 230 ห้อง ใบอนุญาตเลขที่ (ถ้ามี) 129/42 ออกให้โดย หมดอายุ - ในการนี้ขอรายงาน

สรุปผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษสำหรับเดือน มีนาคม พ.ศ. 2566

ตามที่ได้กำหนดในมาตรา ๘๐ แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ

พ.ศ. ๒๕๓๕ ในฐานะ

.....เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(.....นายเคนนิส.....ของ.....)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(.....นายมานพ วิสสุทธิอุทัยกุล.....)

ใบอนุญาตเลขที่ หมุดอายุ

ออกให้โดย

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่ หมุดอายุ

ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(๑) ประเภท/ชนิดของระบบบำบัดน้ำเสีย ระบบแอกทิเวเต็ดสลัดจ์

ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย.....214.....ลบ.ม./วัน

(๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง 24 ชั่วโมง/วัน
☐ แบบไม่ต่อเนื่อง (ระบุ).....

(๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ

☐ เครื่องกวาด/ผสมน้ำเสีย ☐ เครื่องกวาด/ผสมสารเคมี

☐ เครื่องสูบลูกอม ☐ อื่น ๆ (ระบุ) “—”

(๔) แหล่งรองรับน้ำทิ้ง (ระบุ) ท่อระบายน้ำสาธารณะ

(๕) วิจารณ์การตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด จ้างรถสูบลมสูบเพื่อนำไปกำจัด

๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

(๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) ๖๓๘.๔๐

(๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.) ๑,๕๕๗

(๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) ๑,๕๖๕.๖

(๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย _____ ระบายทุกวัน

(๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม) น้ำหมักกลินทรีย์ 200 ลิตร.

(๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์

- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบุ) _____

- เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบุ) _____

- เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบุ) _____

- เครื่องงาน/ผลงานน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-” 9

- เครื่องงาน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบุ) “—”

- เครื่องสูบลูกอม ☐ ปกติ ☐ ผิดปกติ (ระบุ) “ _ “

- ถิ่นกำเนิด ☐ ภาค ☐ จังหวัด ☐ (ระบุ) “-”

(๘) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.) “-”

(๘) ปัญหาอุปสรรค และแนวทางแก้ไข มีข้อเสนอแนะดำเนินการแก้ไขโดยเอาชนะออกจากเครื่องเค็มอากาศ

คำเตือน

๑. ถ้าฟ้องหรือผู้ครอบครองแหล่งกำเนิดพิษผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติข้อมูล หรือไม่บันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖


๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จหรือวาง
 โทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบ ทส. ๑

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ ซอย สุขุมวิท 16 ถนน สุขุมวิท แขวง/ตำบล คลองเตย
เขต/อำเภอ คลองเตย จังหวัด กรุงเทพมหานคร โทรศัพท์ 02-6631234 โทรสาร 02-6631250 มี นริมิตร เจริญ
กิจสุข นิติชนส์ ดีวีดีออปเม้นท์ (ไทยแลนด์) จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการประเภท ที่หัก
ภาษีและจอร์จกร จำนวน 199 ห้อง โบนญาตเลาห์ (ถ้ำมี) 129/42 ออกให้โดย หมดาช

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

สถิติและข้อมูลที่ได้เก็บจากแหล่งกำเนิดมลพิษ														
วัน เดือน ปี	ปริมาณ การใช้ ไฟฟ้าของ ระบบบำบัด น้ำเสีย (กิโลวัต)	ปริมาณ น้ำใช้ ในปฏิบัติการ ของลงกัมมันต พิษ (ลบ.ม.)	ปริมาณน้ำ เสียที่เข้า ระบบ บำบัดน้ำเสีย (ลบ.ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย (ระบาย/ ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด สีจากพืชใช้ (ชื่อ/ปริมาณ) (ลิตรหรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย						ปริมาณตะกอน ที่เกิดขึ้นจากระบบ บำบัด น้ำเสียที่นำไปกำจัด (ลบ.ม.)	ปัญหา อุปสรรค และ แนวทาง แก้ไข	ลายมือ ชื่อ ผู้บันทึก
						ระบบบำบัด น้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ อากาศ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ สารเคมี (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ สารเคมี (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ ตะกอน (ปกติ/ ผิดปกติ)			
1/3/26	666.40	44	35.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
2/3/26	666.40	41	32.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
3/3/26	666.40	42	33.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
4/3/26	666.40	40	32.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
5/3/26	666.40	43	34.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
6/3/26	666.40	41	32.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		มีขยะอุด
7/3/26	666.40	43	34.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		ตันแก๊ซ
8/3/26	666.40	52	41.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		โดยเฉพาะตะกอน
9/3/26	666.40	52	41.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		ออกจาก
10/3/26	666.40	60	48.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		เครื่องเติม
11/3/26	666.40	50	40.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		จากท่อ
12/3/26	666.40	52	41.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		

สถิติและข้อมูลที่เกี่ยวข้องกับงานแหล่งกำเนิดมลพิษ														
วัน เดือน ปี	ปริมาณ การใช้ ไฟฟ้าของ ระบบบำบัด น้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในกิจกรรม ของแหล่งกำเนิด มลพิษ (ลบ.ม.)	ปริมาณ เสียที่เข้า ระบบ บำบัดน้ำเสีย (ลบ.ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย (ระบาย/ ไม่ระบาย)	ปริมาณ สารเคมีหรือ ชีวภาพที่ใช้ (ชื่อปริมาณ/ (สูตรหรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย						ปริมาณตะกอน ที่กักเก็บจากระบบ บำบัด น้ำเสียที่นำไปกำจัด (ลบ.ม.)	ปัญหา อุปสรรค และ แนวทาง แก้ไข	
						ระบบบำบัด น้ำเสีย ดิบ(ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ จาก (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ จาก (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ/ ผสมน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ/ ผสมสารเคมี (ปกติ/ผิดปกติ)			เครื่องสูบน้ำ ตะกอน (ปกติ/ ผิดปกติ)
1/3/26	666.40	44	35.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
13/3/26	666.40	52	41.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
14/3/26	666.40	53	42.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
15/3/26	666.40	73	58.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
16/26	666.40	56	44.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
17/3/26	666.40	56	44.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
18/3/26	666.40	54	43.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
19/3/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
20/3/26	666.40	54	43.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	มีเยลลี่
21/3/26	666.40	57	45.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ตันน้ำทิ้ง
22/3/26	666.40	54	43.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	โดยเขาจะ
23/3/26	666.40	57	45.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ออกจาก

สถิติและข้อมูลที่ได้จากแหล่งกำเนิดมลพิษ														
ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)	ปริมาณน้ำใช้ในการกิจกรรมของแหล่งกำเนิดพิษ (ลบ.ม.)	ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.)	การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย (ระบาย/ไม่ระบาย)	ปริมาณสารเคมีหรือสารสกัดสีภาพที่ใช้ (ชื่อ/ปริมาณ) (ลิตรหรือกิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย						ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรคและแนวทางแก้ไข	ลายมือชื่อผู้บันทึก	
					ระบบบำบัดน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติมอากาศ (ปกติ/ผิดปกติ)	เครื่องกวน/ผสมน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องกรอง/ผสมสารเคมี (ปกติ/ผิดปกติ)	เครื่องสูบลบตะกอน (ปกติ/ผิดปกติ)				อื่นๆ (ระบุ) (ปกติ/ผิดปกติ)
วัน เดือน ปี														
1/3/26	666.40	44	35.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
24/3/26	666.40	42	33.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	เครื่องเดิม	
25/3/26	666.40	57	45.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	อากาศ	
26/3/26	666.40	46	36.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
27/3/26	666.40	56	44.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
28/3/26	666.40	57	45.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
2893/26	666.40	57	45.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
30/3/26	666.40	73	58.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
31/3/26	666.40	39	31.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-		
		1,439	1,151.2											

หมายเหตุ

- 1.ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน
- 2.ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(.....นาย.....เคนนิส.....ของ.....)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(.....นาย.....มานพ.....วิสุทธิอุทัยกุล.....)

ใบอนุญาตเลขที่.....หมดอายุ.....

ออกให้โดย.....

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่.....หมดอายุ.....

ออกให้โดย.....

แบบ ทส. ๒

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

๑. ข้อมูลทั่วไป

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ - ซอย สุขุมวิท16 ถนน สุขุมวิท แขวง/ตำบล คลองเตย เขต/อำเภอ คลองเตย จังหวัด กรุงเทพมหานคร โทรศัพท์ 02-6631234 โทรสาร 02-6631250 มี บริษัท เจริญ ถิวัช นิธิเนส ดีวีเอปมมท (ไทยแลนด์) จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการ ประเภท ที่พักอาศัยและจอดรถ จำนวน 199 ห้อง ใบอนุญาตเลขที่ (ถ้ามี) 129/42 ออกให้โดย - - - - - หมดอายุ.....

ในการนี้ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษสำหรับ เดือน มีนาคม พ.ศ. 2566 ตามที่ได้กำหนดในมาตรา ๘๐ แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. ๒๕๓๕ ในฐานะ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ (นาย/เดนิส ของ.....)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย (นายมนท วิสุทธิวิทยกุล.....) ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

..... ผู้รับจ้างให้บริการบำบัดน้ำเสีย (.....) ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

- (๑) ประเภท/ชนิดของระบบบำบัดน้ำเสียระบบแอกลิเวเต็ดสลัดจ์.....
- ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย.....147..... ลบ.ม./วัน
- (๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง24..... ชั่วโมง/วัน
- ☐ แบบไม่ต่อเนื่อง (ระบุ).....
- (๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ
- ☐ เครื่องกวน/ผสมน้ำเสีย ☐ เครื่องกวน/ผสมสารเคมี
- ☐ เครื่องสูบละกอน ☐ อื่น ๆ (ระบุ)..... “-“
- (๔) แหล่งรองรับน้ำทิ้ง (ระบุ)ท่อระบายน้ำสาธารณะ.....
- (๕) วิธีการการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัดจ้างรถสูบน้ำสูบเพื่อนำไปกำจัด.....

๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) ๖๖๖.๔๑.....
- (๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.).....๑,๘๘๕.....
- (๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.).....๑,๑๕๑.๒.....
- (๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสียระบายทุกวัน.....
- (๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม) น้ำหนักจุลินทรีย์ 200 ลิตร.
- (๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบุ).....
- เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
- เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
- เครื่องกวน/ผสมน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-“
- เครื่องกวน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-“
- เครื่องสูบละกอน ☐ ปกติ ☐ ผิดปกติ (ระบุ)..... “-“
- อื่นๆ ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-“
- (๗) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.) “-“
- (๘) ปัญหา อุปสรรค และแนวทางแก้ไขมีขยะอุดตันค้ำเนินการแก้ไขโดยตนเองออกจากเครื่องเติมอากาศ.....


ถ้าเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖

๒.ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จต้องระวาง โทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบ ทส. ๑

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่.....41/1.....หมู่ที่.....-.....ซอย.....สุขุมวิท16.....ถนน.....สุขุมวิท.....แขวง
คลองเตย.....เขต.....คลองเตย.....จังหวัด.....กรุงเทพมหานคร.....โทรศัพท์.....02-6631234.....โทรสาร.....02-6631250.....มี
บริษัท.....เจอาร์ คิวชู บิสิเนส คิวโอปเนนท์ (ไทยแลนด์) จำกัด.....เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบ
กิจการประเภท.....ที่พักอาศัยและจอดรถ.....จำนวน.....230.....ห้อง.....ใบอนุญาตเลขที่.....(ถ้ามี).....129/42.....ออกให้โดย.....-
.....หมคอาชู.....-
ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

วัน เดือน ปี	ปริมาณ การใช้ไฟฟ้า ของระบบ บำบัดน้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในทุกกิจกรรมของ แหล่งกำเนิดมลพิษ (ลบ.ม.)	ปริมาณ น้ำเสียที่ หารระบบ บำบัดน้ำเสีย(ลบ. ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย(ระบาย ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด ชีวภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	สถิติและข้อมูลที่ได้มาจากแหล่งกำเนิดมลพิษ							ปริมาณ ตะกอน ส่วนเกินจาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรค และแนวทาง แก้ไข	ลายมือชื่อ ผู้บันทึก
						ปริมาณน้ำเสียที่ หารระบบ บำบัดน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติม อากาศ(ปกติ/ ผิดปกติ)	เครื่องยก/ผสมสารเคมี (ปกติ/ผิดปกติ)	เครื่องยก/ผสมน้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องสูบลำไส้ (ปกติ/ผิดปกติ)	อื่นๆ (รูป) (ปกติ/ ผิดปกติ)			
14/26	678.40	51	40.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	
24/26	678.40	73	58.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	
34/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	
44/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	
54/26	678.40	85	68.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	
64/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	มีขยะขุด	
74/26	678.40	83	66.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ต้นไม้ใหญ่	
84/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	โดยจะขยะ	
94/26	678.40	77	61.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ออกจาก	
10/4/26	678.40	75	60.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	เครื่องเดิม	
11/4/26	678.40	78	62.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	อากาศ	
12/4/26	678.40	78	62.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	-	

สถิติและข้อมูลที่ได้รับจากแหล่งกำเนิดมลพิษ																
วัน เดือน ปี	ปริมาณ การใช้ไฟฟ้า ของระบบ บำบัดน้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในภารกิจรวมของ แหล่งกำเนิดมลพิษ (ลบ.ม.)	ปริมาณน้ำเสียที่ เข้าระบบ บำบัดน้ำเสีย(ลบ. ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย(ระบาย ไม่ระบาย)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย(ระบาย ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด ชีวมวลที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	การทางของระบบบำบัดน้ำเสีย						ปริมาณ ตะกอน ส่วนเกิน ที่คืนสู่จาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปริมาณ ตะกอน ส่วนเกิน ที่คืนสู่จาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปริมาณ ของเสีย อันตราย และกาก ของเสีย (กิโลกรัม)	
							ระบบบำบัด น้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติม อากาศ(ปกติ/ ผิดปกติ)	เครื่องกว ม่น้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องกว ม่น้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)				เครื่องสูบน้ำ (ปกติ/ผิดปกติ)
14/26	678.40	51	40.8	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	-
13/4/26	678.40	3	2.4	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	-
14/4/26	678.40	1	0.8	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	-
15/4/26	678.40	245	196.0	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	-
16/4/26	678.40	46	36.8	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	-
17/4/26	678.40	70	56.0	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	-
18/4/26	678.40	78	62.4	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	-
19/4/26	678.40	62	49.6	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	-
20/4/26	678.40	54	43.2	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	-
21/4/26	678.40	76	60.8	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	มีขยะจุด
22/4/26	678.40	55	44.0	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	ดินเหนียว
23/4/26	678.40	66	52.8	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	โดยเขาพระ
24/4/26	678.40	79	63.2	ระบาย	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	ขอยกจาก

[illegible]

แบบ ทส. ๒

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

หมายเหตุ

๑.ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน

๒.ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

.....เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(..... นาย เคนนิส ของ)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(.....นายมานพ.....วิสุทธิชัยกุล.....)

ใบอนุญาตเลขที่ หมดอายุ.....

ออกให้โดย.....

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(..... นาย เคนนิส ของ)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(..... นายมานพวิสุทธิชัยกุล.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

- (๑) ประเภท/ชนิดของระบบบำบัดน้ำเสียระบบแอกติเวเต็ดสลัดจ์.....
- ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย.....214...ลบ.ม./วัน
- (๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง.....24...ชั่วโมง/วัน
- ☐ แบบไม่ต่อเนื่อง (ระบบ).....
- (๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ
- ☐ เครื่องกวน/ผสมน้ำเสีย ☐ เครื่องกวน/ผสมสารเคมี
- ☐ เครื่องสูบละกอน ☐ อื่น ๆ (ระบบ).....“--“.....
- (๔) แหล่งรองรับน้ำทิ้ง (ระบบ)ท่อระบายน้ำสาธารณะ.....
- (๕) วิธีการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด.....จ้างรถสูบลมสูบเพื่อนำไปกำจัด

๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน


- (๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)๖๗๘.๔๘
- (๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.).....๒๑.๐๔๐
- (๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.)...๑.๖๓๒.๑.
- (๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสียระบายนํ้าทุกวัน.....
- (๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม) น้ำหมักจุลินทรีย์ 200 ลิตร.
- (๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบบ).....
 - เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบบ)
 - เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบบ)
 - เครื่องกวน/ผสมน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบบ)“--“.....
 - เครื่องกวน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบบ)“--“.....
 - เครื่องสูบละกอน ☐ ปกติ ☐ ผิดปกติ (ระบบ)“--“.....
 - อื่นๆ ☐ ปกติ ☐ ผิดปกติ (ระบบ)“--“.....
- (๗) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.)“--“.....
- (๘) ปัญหา อุปกรณ์ และแนวทางแก้ไข.....มีขยะอุดตันต้นนินการแก้ไขโดยเอาขยะออกจากเครื่องเติมอากาศ

- คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
- ๒.ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบ ทส. ๑

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ซอย สุขุมวิท 16 ถนนสุขุมวิท แขวง/ตำบลคลองเตย
เขต/อำเภอคลองเตยจังหวัดกรุงเทพมหานคร. โทรศัพท์02-6631234 โทรสาร02-6631250 มีบริษัท/เจ้าอา
หรัช.นิติบุคคล ชื่อผู้ประกอบการ (ไทยแลนด์) จำกัด.....เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการประเภทที่ต้
ออาศัยและจอดรถ จำนวน 1๑9 ห้อง.....ใบอนุญาตเลขที่ (ถ้ามี).....129/42.....ออกให้โดยหมดอายุ
ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

วัน เดือน ปี	สถิติและข้อมูลที่ได้จากแหล่งกำเนิดมลพิษ													ปริมาณ การใช้ ไฟฟ้าของ ระบบบำบัด น้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในฤดูกาลรวม ของแหล่งกำเนิด มลพิษ (ลบ.ม.)	ปริมาณน้ำ เสียที่เข้า ระบบ บำบัดน้ำเสีย (ลบ.ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย (ระบาย/ ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด ชีวภาพที่ใช้ (ชื่อ/ปริมาณ) (ลิตร/หรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย							ปริมาณตะกอน ส่วนเกิน ที่เกิดขึ้นจากระบบ บำบัด น้ำเสียที่นำไปกำจัด (ลบ.ม.)	ปัญหา อุปสรรค และ แนวทาง แก้ไข	ลายมือ ชื่อ ผู้บันทึก																																																																																																																																																						
	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ						เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ				เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)

สถิติและข้อมูลที่ได้จากแหล่งกำเนิดมลพิษ															
วัน เดือน ปี	ปริมาณ การใช้ ไฟฟ้าของ ระบบบำบัด น้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในฤดูกาลรวม ของแหล่งกำเนิด มลพิษ (ลบ.ม.)	ปริมาณน้ำ เสียที่เข้า ระบบ บำบัดน้ำเสีย (ลบ.ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย (ระบาย/ ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด ชีวภาพที่ใช้ (ชื่อ ปริมาณ) (ลิตร หรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย						ปริมาณตะกอน ส่วนเกิน ที่เกิดขึ้นจากระบบ บำบัด น้ำเสียที่นำไปกำจัด (ลบ.ม.)	ปัญหา อุปสรรค และ แนวทาง แก้ไข	ลายมือ ชื่อ ผู้บันทึก	
						รวมบำบัด น้ำเสีย (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องสูบน้ำ อากาศ (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องเติม ออกซิเจน (ปกติ/ ผิดปกติ) ผิดปกติ	เครื่องกลวง ผสมน้ำเสีย (ปกติ/ผิดปกติ)(ปกติผิดปกติ)	เครื่องสูบน้ำ ตะกอน (ปกติ/ ผิดปกติ) ผิดปกติ				อื่นๆ (ระบุ) (ปกติ/ ผิดปกติ) ผิดปกติ
1/4/26	666.40	39	31.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
13/4/26	666.40	57	45.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
14/4/26	666.40	75	60.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
15/4/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
16/4/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
17/4/26	666.40	54	43.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
18/4/26	666.40	58	46.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
19/4/26	666.40	56	44.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
20/4/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	มีขยะติด	
21/4/26	666.40	56	44.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ดินเหนียว	
22/4/26	666.40	75	60.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	โดยเฉพา	
23/4/26	666.40	57	45.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ขอจาก	

สถิติและข้อมูลที่ได้จากแหล่งกำเนิดมลพิษ														
ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)	ปริมาณน้ำใช้ ในปฏิบัติการของแหล่งกำเนิดมลพิษ (ลบ.ม.)	ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.)	การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย (ระบาย/ไม่ระบาย)	ปริมาณสารเคมีหรือสีภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย							ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรคและแนวทางแก้ไข	ลายมือชื่อผู้บันทึก
					ระบบบำบัดน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบลบ (ปกติ/ผิดปกติ)	เครื่องเติมอากาศ (ปกติ/ผิดปกติ)	เครื่องกวน/ผสมน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบลบตะกอน (ปกติ/ผิดปกติ)	อื่นๆ (ระบุ) (ปกติ/ผิดปกติ)				
วัน เดือน ปี														
1/4/26	666.40	39	31.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
24/4/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	เครื่องเติม
25/4/26	666.40	56	44.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	อากาศ
26/4/26	666.40	58	46.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
27/4/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
28/4/26	666.40	57	45.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
28/4/26	666.40	75	60.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
30/4/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	
		1,582	1,265.6											

หมายเหตุ

- 1.ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน
- 2.ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(.....นาย.....เคนนิส.....ของ.....)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(.....นาย.....มานพ.....วิสุทธิอุทัยกุล.....)

ใบอนุญาตเลขที่.....หมดอายุ.....

ออกให้โดย.....

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่.....หมดอายุ.....

ออกให้โดย.....

แบบ ทส. ๒

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

๑. ข้อมูลทั่วไป

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ - ซอย สุขุมวิท16 ถนน สุขุมวิท แขวง/ตำบล คลองเตย
เขต/อำเภอ คลองเตย จังหวัด กรุงเทพมหานคร โทรศัพท์ 02-6631234 โทรสาร 02-6631250
มี บริษัท เจริญ ถิระ นิธิเนส ดีไวออปเม้นท์ (ไทยแลนด์) จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการ
ประเภท ที่พักอาศัยและจอดรถ จำนวน 199 ห้อง ใบอนุญาตเลขที่ (ถ้ามี) 129/42 ออกให้โดย - - - - - หมดอายุ
ในการนี้ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษสำหรับ เดือน เมษายน พ.ศ. 2566
ตามที่ได้กำหนดในมาตรา ๘๐ แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. ๒๕๓๕ ในฐานะ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ
(.....นาย เคนนิส.....ของ.....)
.....ผู้ควบคุมระบบบำบัดน้ำเสีย
(.....นายมานพ.....วิสุทธิอุทัยกุล.....)
ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย
..... ผู้รับจ้างให้บริการบำบัดน้ำเสีย
(.....)
ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

- (๑) ประเภท/ชนิดของระบบบำบัดน้ำเสียระบบแอกลิเวเตเต็ดสลัดจ์.....
ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย147ลบ.ม./วัน
(๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง24 ชั่วโมง/วัน
☐ แบบไม่ต่อเนื่อง (ระบุ).....
(๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ
☐ เครื่องกวน/ผสมน้ำเสีย ☐ เครื่องกวน/ผสมสารเคมี
☐ เครื่องสูบละกอน ☐ อื่น ๆ (ระบุ)..... “-”
(๔) แหล่งรองรับน้ำทิ้ง (ระบุ)ท่อระบายน้ำสาธารณะ.....
(๕) วิธีการการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัดจ้างรถสูบน้ำสูบเพื่อนำไปกำจัด

๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน


- (๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) ๖๖๖.๔๐
(๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.)๑,๕๔๒.....
(๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.).....๑,๒๖๕.๖.....
(๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสียระบายทุกวัน.....
(๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม) น้ำหนักจุลินทรีย์ 200. ลิตร.
(๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบุ).....
- เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
- เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
- เครื่องกวน/ผสมน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
- เครื่องกวน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
- เครื่องสูบละกอน ☐ ปกติ ☐ ผิดปกติ (ระบุ)..... “-”
- อื่นๆ ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
(๗) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.) “-”
(๘) ปัญหา อุปสรรค และแนวทางแก้ไขมีขยะอุดตันค้ำเนินการแก้ไขโดยตนเองออกจากเครื่องเติมอากาศ.....

ถ้าเดือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ
ข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท
หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
๒.ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จต้องระวาง
โทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบ ทส. ๑

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่.....41/2.....หมู่ที่.....-.....ซอย.....สุขุมวิท16.....ถนน.....สุขุมวิท.....แขวง
คลองเตย.....เขต.....คลองเตย.....จังหวัด.....กรุงเทพมหานคร.....โทรศัพท์.....02-6631234.....โทรสาร.....02-6631250.....มี
บริษัท.....เจอาร์ คิวซี บิสิเนส คิวโอปเนนท์ (ไทยแลนด์) จำกัด.....เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบ
กิจการประเภท.....ที่พักอาศัยและจัดรถ.....จำนวน.230.....ห้อง.....ใบอนุญาตเลขที่ (ถ้ามี).....129/42.....ออกให้โดย.....-
หมคอาชู-
ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

วัน เดือน ปี	ปริมาณ การใช้ไฟฟ้า ของระบบ บำบัดน้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในอุปกรณ์ของ แหล่งกำเนิดมลพิษ (ลบ.ม.)	ปริมาณน้ำเสียที่ ใช้ระบบ บำบัดน้ำเสีย(ลบ. ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย(ระบาย ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด ชีวภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	ปริมาณ รวมบำบัด น้ำเสีย (ปกติ/ผิดปกติ)	การทำงานของระบบบำบัดน้ำเสีย						ปริมาณ ตะกอน ส่วนเกิน ที่ติดเ็นจาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรค และแนวทาง แก้ไข	ลายมือชื่อ ผู้บันทึก
							เครื่องเติม อากาศ(ปกติ/ ผิดปกติ)	เครื่องยก/ ผสมน้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องรวม/ ผสมสารเคมี (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ ตะกอน (ปกติ/ผิดปกติ)	อื่นๆ (รูป) (ปกติ/ ผิดปกติ)				
1/5/26	678.40	76	60.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-		
2/5/26	678.40	41	32.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-		
3/5/26	678.40	82	65.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-		
4/5/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-		
5/5/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-		
6/5/26	678.40	76	60.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	มีขยะขุด	
7/5/26	678.40	48	38.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	ต้นน้ำแก้ไข	
8/5/26	678.40	80	64.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	โดยจะขยะ	
9/5/26	678.40	84	67.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	ออกจาก	
10/5/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	เครื่องเดิม	
11/5/26	678.40	75	60.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-	อากาศ	
12/5/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	-		

สถิติและข้อมูลที่เกี่ยวข้องกับงานแหล่งกำเนิดมลพิษ														
วัน เดือน ปี	ปริมาณ การใช้ไฟฟ้า ของระบบ บำบัดน้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในภารกิจรวมของ แหล่งกำเนิดมลพิษ (ลบ.ม.)	ปริมาณ น้ำเสียที่ เข้าระบบ บำบัดน้ำเสีย(ลบ. ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย(ระบาย ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด ชีวมวลที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	การทางของระบบบำบัดน้ำเสีย						ปริมาณ ตะกอน ส่วนเกิน ที่คืนสู่จาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรค และแนวทาง แก้ไข	
						ระบบบำบัด น้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติม อากาศ(ปกติ/ ผิดปกติ)	เครื่องกว แสงน้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องรวม/ ผสมสารเคมี (ปกติ/ผิดปกติ)	อื่นๆ (รวม) (ปกติ/ ปกติ/ ผิดปกติ)			
1/5/26	678.40	76	60.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
13/5/26	678.40	40	32.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
14/5/26	678.40	75	60.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
15/5/26	678.40	77	61.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
16/5/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
17/5/2	678.40	60	48.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
18/5/26	678.40	59	47.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
19/5/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
20/5/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-		
21/5/256	678.40	39	31.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	มีขยะจุด	
22/5/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	ต้นน้ำ	
23/5/26	678.40	85	68.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	โดยเขาพระ	
24/5/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	ปกติ	-	-	ออกจาก	

[illegible]

แบบ ทส. ๒

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

หมายเหตุ

๑.ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน

๒.ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

.....เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(..... นาย เคนนิส ของ)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(.....นายมานพ.....วิสุทธิชัยกุล.....)

ใบอนุญาตเลขที่ หมดอายุ.....

ออกให้โดย.....

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

.....เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(..... นาย เคนนิส ของ)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(..... นายมานพวิสุทธิชัยกุล.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

- (๑) ประเภท/ชนิดของระบบบำบัดน้ำเสียระบบแอกติเวเต็ดสลัดจ์.....
ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย.....214...ลบ.ม./วัน
- (๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง.....24...ชั่วโมง/วัน
☐ แบบไม่ต่อเนื่อง (ระยะ).....
- (๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ
☐ เครื่องกวน/ผสมน้ำเสีย ☐ เครื่องกวน/ผสมสารเคมี
☐ เครื่องสูบละกอน ☐ อื่น ๆ (ระบุ).....“.....”
- (๔) แหล่งรองรับน้ำทิ้ง (ระบุ)ท่าสะพานน้ำสาธารณะ.....
- (๕) วิธีการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด.....จ้างรถสูบลมสูบเพื่อนำไปกำจัด

๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน


- (๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)๖๗๘.๔๘
- (๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.).....๑,๕๘๘
- (๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) ...๑,๕๘๘.๖
- (๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสียระบายน้ำทุกวัน.....
- (๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม) น้ำหมักจุลินทรีย์ 200 ลิตร.
- (๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบุ).....
 - เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
 - เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
 - เครื่องกวน/ผสมน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบุ)“.....”
 - เครื่องกวน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบุ)“.....”
 - เครื่องสูบละกอน ☐ ปกติ ☐ ผิดปกติ (ระบุ)“.....”
 - อื่นๆ ☐ ปกติ ☐ ผิดปกติ (ระบุ)“.....”
- (๗) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.)“.....”
- (๘) ปัญหา อุปสรรค และแนวทางแก้ไข.....มีขยะอุดตันต้นป็นการแก้ไขโดยเอาขยะออกจากเครื่องเติมอากาศ

- คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
- ๒.ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบ ทส. ๑

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ซอย สุขุมวิท 16 ถนนสุขุมวิท แขวง/ตำบลคลองเตย
เขต/อำเภอคลองเตยจังหวัดกรุงเทพมหานคร. โทรศัพท์02-6631234 โทรสาร02-6631250 มีบริษัท/เจ้าอา
หรัญ.นิติบุคคล ชื่อผู้ประกอบการ (ไทยแลนด์) จำกัด.....เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการประเภทที่ต้
ออาศัยและจอดรถ จำนวน 1๑9 ห้อง.....ใบอนุญาตเลขที่ (ถ้ามี).....129/42.....ออกให้โดยหมดอายุ
ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

สถิติและข้อมูลที่ได้จากแหล่งกำเนิดมลพิษ															
ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)	ปริมาณน้ำใช้ในการกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.)	ปริมาณเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.)	การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย (ระบาย/ไม่ระบาย)	ปริมาณสารเคมีหรือสารสกัดสีภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือกิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย							ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรคและแนวทางแก้ไข	ลายมือชื่อผู้บันทึก	
					ระบบบำบัดน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติมอากาศ (ปกติ/ผิดปกติ)	เครื่องกวน/ผสมน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องกวน/ผสมสารเคมี (ปกติ/ผิดปกติ)	เครื่องสูบน้ำตะกอน (ปกติ/ผิดปกติ)	อื่นๆ (ระบุ) (ปกติ/ผิดปกติ)				
1/5/26	666.40	58	46.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
24/5/26	666.40	59	47.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	เครื่องเติม	
25/5/26	666.40	54	43.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	อากาศ	
26/5/26	666.40	56	44.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
27/5/26	666.40	54	43.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
28/5/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
29/5/26	666.40	37	29.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
30/5/26	666.40	56	44.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
31/5/26	666.40	45	36.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
		1,646	1,316.8												

หมายเหตุ

- 1.ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน
- 2.ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(.....นาย.....เคนนิส.....ของ.....)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(.....นาย.....มานพ.....วิสุทธิอุทัยกุล.....)

ใบอนุญาตเลขที่.....หมดอายุ.....

ออกให้โดย.....

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่.....หมดอายุ.....

ออกให้โดย.....

แบบ ทส. ๒

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

๑. ข้อมูลทั่วไป

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ - ซอย สุขุมวิท16 ถนน สุขุมวิท แขวง/ตำบล คลองเตย
เขต/อำเภอ คลองเตย จังหวัด กรุงเทพมหานคร โทรศัพท์ 02-6631234 โทรสาร 02-6631250
มี บริษัท เจริญ ถิระ นิธิเนส ดีไวออปเม้นท์ (ไทยแลนด์) จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการ
ประเภท ที่พักอาศัยและจอดรถ จำนวน 199 ห้อง ใบอนุญาตเลขที่ (ถ้ามี) 129/42 ออกให้โดย - - - - - หมดอายุ - - - - -
ในการนี้ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษสำหรับ เดือน พฤษภาคม พ.ศ. 2566
ตามที่ได้กำหนดในมาตรา ๘๐ แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. ๒๕๓๕ ในฐานะ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ
(.....นาย เคนนิส.....ของ.....)
.....ผู้ควบคุมระบบบำบัดน้ำเสีย
(.....นายมานพ.....วิสุทธิวิทยกุล.....)
ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย
..... ผู้รับจ้างให้บริการบำบัดน้ำเสีย
(.....)
ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

- (๑) ประเภท/ชนิดของระบบบำบัดน้ำเสียระบบแอกลิเวเต็ดสลัดจ์.....
ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย147..... ลบ.ม./วัน
(๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง24..... ชั่วโมง/วัน
☐ แบบไม่ต่อเนื่อง (ระบุ).....
(๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ
☐ เครื่องกวน/ผสมน้ำเสีย ☐ เครื่องกวน/ผสมสารเคมี
☐ เครื่องสูบละกอน ☐ อื่น ๆ (ระบุ)..... “-”
(๔) แหล่งรองรับน้ำทิ้ง (ระบุ)ท่อระบายน้ำสาธารณะ.....
(๕) วิธีการการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัดจ้างรถสูบน้ำสูบเพื่อนำไปกำจัด


๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) ๖๖๖.๔๑.....
(๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.)๑,๖๔๖.....
(๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.).....๑,๓๑๖.๘.....
(๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสียระบายทุกวัน.....
(๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม) น้ำหมักจุลินทรีย์ 200 ลิตร.
(๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบุ).....
- เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
- เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
- เครื่องกวน/ผสมน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
- เครื่องกวน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
- เครื่องสูบละกอน ☐ ปกติ ☐ ผิดปกติ (ระบุ)..... “-”
- อื่นๆ ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
(๗) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.) “-”
(๘) ปัญหา อุปสรรค และแนวทางแก้ไขมีขยะอุดตันค้ำเนินการแก้ไขโดยตนเองออกจากเครื่องเติมอากาศ.....

ถ้าเดือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ
ข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท
หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
๒.ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จต้องระวาง
โทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

วัน เดือน ปี	สถิติและข้อมูลที่ได้รับจากแหล่งกำเนิดมลพิษ														
	ปริมาณ การใช้ไฟฟ้า ของระบบ น้ำบาดาลเสีย (หน่วย)	ปริมาณ น้ำใช้ ในอุปกรณ์ของ แหล่งกำเนิดมลพิษ (ลบ.ม.)	ปริมาณ น้ำเสียที่ เสื่อมระบบ บำบัดน้ำเสีย(ลบ.ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสียระบาย "ไม่ระบาย"	ปริมาณ สารเคมีหรือ สีจากพื้นที่ใช้ (เชื้อเพลิงน้ำมัน) (ลิตรหรือ กิโลกรัม)	การทางน้ำของระบบบำบัดน้ำเสีย							ปริมาณ ตะกอน ส่วนเกิน ที่เกิดขึ้นจาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรค และแนวทาง แก้ไข	ลายมือชื่อ ผู้บันทึก
						ระบบบำบัด น้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	อากาศปกติ/ ผิดปกติ	เครื่องเติม ผสมน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องวาง/ผสมสารเคมี (ปกติ/ผิดปกติ)	เครื่องสูบลอยตัว (ปกติ/ผิดปกติ)	อื่นๆ (ระบุ) (ปกติ/ผิดปกติ)			
1/6/26	678.40	72	57.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
2/6/26	678.40	57	45.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
3/6/26	678.40	64	51.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
4/6/26	678.40	74	59.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
5/6/26	678.40	53	42.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
6/6/26	678.40	65	52.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	มีขยะจุด	
7/6/26	678.40	75	60.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ต้นน้ำใต้	
8/6/26	678.40	38	30.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	โดยสายจะ	
9/6/26	678.40	77	61.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ออกจาก	
10/6/26	678.40	49	39.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	เครื่องเดิม	
11/6/26	678.40	42	33.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	อากาศ	
12/6/26	678.40	105	84.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		

สถิติและข้อมูลที่เกี่ยวข้องกับงานแหล่งกำเนิดมลพิษ															
วัน เดือน ปี	ปริมาณ การใช้ไฟฟ้า ของระบบ บำบัดน้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในภารกิจตรวจสอบ แหล่งกำเนิดมลพิษ (อบ.ม.)	ปริมาณ น้ำเสียที่ เข้าระบบ บำบัดน้ำเสีย(ลบ. ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย(ระบาย ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด ชีวมวลที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	การทางของระบบบำบัดน้ำเสีย							ปริมาณ ตะกอน ส่วนเกิน ที่คืนสู่จาก ระบบบำบัด น้ำเสียที่ นำไปกำจัด (ลบ.ม.)	ปัญหาอุปสรรค และแนวทาง แก้ไข	ลายมือชื่อ ผู้บันทึก
						ระบบบำบัด น้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติม อากาศ(ปกติ/ ผิดปกติ)	เครื่องกว/ ผสมน้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องกว/ ผสมสารเคมี (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ อากาศ(ปกติ/ ผิดปกติ)	เครื่องกว/ ผสมน้ำเสีย (ปกติ/ ผิดปกติ)			
1/6/26	678.40	72	57.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
13/26	678.40	43	34.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
14/6/26	678.40	75	60.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
15/6/26	678.40	77	61.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
16/6/26	678.40	40	32.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
17/6/26	678.40	80	64.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
18/6/26	678.40	72	57.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
19/6/26	678.40	48	38.4	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
20/6/26	678.40	81	64.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-		
21/6/26	678.40	79	63.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	มีขยะจุด	
22/6/26	678.40	76	60.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ดินเหนียว	
23/6/26	678.40	77	61.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	โดยเขาขยะ	
24/6/26	678.40	76	60.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	ปกติ	-	-	ขอยกจาก	

[illegible]

แบบ ทส. ๒

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

หมายเหตุ

๑.ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน

๒.ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

.....เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(..... นาย เคนนิส ของ)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(.....นายมานพวิสุทธิชัยกุล.....)

ใบอนุญาตเลขที่ หมดอายุ.....

ออกให้โดย.....

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(..... นาย เคนนิส ของ)

.....ผู้ควบคุมระบบบำบัดน้ำเสีย

(..... นายมานพวิสุทธิชัยกุล.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

.....ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่ หมดอายุ

ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

- (๑) ประเภท/ชนิดของระบบบำบัดน้ำเสียระบบแอกติเวเต็ดสลัดจ์.....
ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย.....214...ลบ.ม./วัน
- (๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง.....24...ชั่วโมง/วัน
☐ แบบไม่ต่อเนื่อง (ระบุ).....
- (๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ
☐ เครื่องกวน/ผสมน้ำเสีย ☐ เครื่องกวน/ผสมสารเคมี
☐ เครื่องสูบละกอน ☐ อื่น ๆ (ระบุ).....“.....”
- (๔) แหล่งรองรับน้ำทิ้ง (ระบุ)ท่าสะพานน้ำสาธารณะ.....
- (๕) วิธีการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด.....จ้างรถสูบละกอนเพื่อนำไปกำจัด

๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)๖๗๘.๔๑
- (๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.) ๑,๘๖๘
- (๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) ...๑,๔๕๕.๔๕.
- (๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสียระบายนทุกวัน.....
- (๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม) น้ำหมักจุลินทรีย์ 200 ลิตร.
- (๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบุ).....
 - เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
 - เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
 - เครื่องกวน/ผสมน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบุ)“.....”
 - เครื่องกวน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบุ)“.....”
 - เครื่องสูบละกอน ☐ ปกติ ☐ ผิดปกติ (ระบุ)“.....”
 - อื่นๆ ☐ ปกติ ☐ ผิดปกติ (ระบุ)“.....”
- (๗) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.)“.....”
- (๘) ปัญหา อุปสรรค และแนวทางแก้ไข.....มีขยะอุดตันต้นป็นการแก้ไขโดยเอาขยะออกจากเครื่องเติมอากาศ


- คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
- ๒.ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบ ทส. ๑

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสีย
ของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ซอย สุขุมวิท 16 ถนนสุขุมวิท แขวง/ตำบลคลองเตย
เขต/อำเภอคลองเตยจังหวัดกรุงเทพมหานคร. โทรศัพท์02-6631234 โทรสาร02-6631250 มีบริษัท/เจ้าอา
หรัญ.นิติบุคคล/วิสาหกิจ/บุคคล (ไทย/แ่ลนด์) จ้งกััด.....เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการประเภทที่ต้
อากัษย์และจ้อดรด. จ้งนวน.1๑9 ห้อง.....ใบอนุญาตเลขที่ (ถ้ามี).....129/42.....ออกให้โดย-..... หมอดำย-.....

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้



ได้จัดเก็บสถิติและข้อมูลแสดงผลการทำงานของระบบบำบัดน้ำเสียปรากฏตามตาราง ดังนี้

วัน เดือน ปี	สถิติและข้อมูลที่ได้จากแหล่งกำเนิดมลพิษ													ปัญหา อุปสรรค และ แนวทาง แก้ไข	ลายมือ ชื่อ ผู้บันทึก
	ปริมาณ การใช้ ไฟฟ้าของ ระบบบำบัด น้ำเสีย (หน่วย)	ปริมาณ น้ำใช้ ในปฏิบัติการ ของแหล่งกำเนิด มลพิษ (ลบ.ม.)	ปริมาณน้ำ เสียที่เข้า ระบบ บำบัดน้ำเสีย (ลบ.ม.)	การระบาย น้ำทิ้งจากระบบ บำบัดน้ำเสีย (ระบาย/ ไม่ระบาย)	ปริมาณ สารเคมีหรือ สารสกัด สีภาพที่ใช้ (ชื่อปริมาณ) (ลิตรหรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย							ปริมาณตะกอน ส่วนเกิน ที่เกิดขึ้นจากระบบ บำบัด น้ำเสียที่นำไปกำจัด (ลบ.ม.)		
						ระบบบำบัด น้ำเสีย (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ/ อากาศ (ปกติ/ ผิดปกติ)	เครื่องสูบน้ำ/ ผสมน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ/ ตะกอน (ปกติ/ ผิดปกติ)			
1/6/26	666.40	47	37.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	-	ปกติ	-	-	
24/6/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	-	ปกติ	-	-	เครื่องเดิม
25/6/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	-	ปกติ	-	-	อากาศ
26/6/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	-	ปกติ	-	-	
27/6/26	666.40	55	44.0	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	-	ปกติ	-	-	
28/6/26	666.40	57	45.6	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	-	ปกติ	-	-	
29/6/26	666.40	54	43.2	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	-	ปกติ	-	-	
30/6/26	666.40	56	44.8	ระบาย	-	ปกติ	ปกติ	ปกติ	-	-	-	ปกติ	-	-	
		1,492	1,193.6												

- หมายเหตุ

 - ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้นๆ ในแต่ละวัน
 - ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

(..... นาย..... นิส..... ของ.....)

..... ผู้ควบคุมระบบบำบัดน้ำเสีย

(..... นาย..... นพ..... วิชา..... วิทยุ..... ทัต.....)

ใบอนุญาตเลขที่.....หมดอายุ.....

ออกให้โดย.....

..... ผู้รับจ้างให้บริการบำบัดน้ำเสีย

(.....)

ใบอนุญาตเลขที่.....หมดอายุ.....

ออกให้โดย.....

แบบ ทส. ๒

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

๑. ข้อมูลทั่วไป

แหล่งกำเนิดมลพิษตั้งอยู่เลขที่ 41 หมู่ที่ - ซอย สุขุมวิท16 ถนน สุขุมวิท แขวง/ตำบล คลองเตย
เขต/อำเภอ คลองเตย จังหวัด กรุงเทพมหานคร โทรศัพท์ 02-6631234 โทรสาร 02-6631250
มี บริษัท เจริญ ถิระ นิธิเนส ดีไวส์ จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ประกอบกิจการ
ประเภท ที่พักอาศัยและจอดรถ จำนวน 199 ห้อง ใบอนุญาตเลขที่ (ถ้ามี) 129/42 ออกให้โดย - - - - - หมดอายุ - - - - -
ในการนี้ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษสำหรับ เดือน มิถุนายน พ.ศ. 2566
ตามที่ได้กำหนดในมาตรา ๘๐ แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. ๒๕๓๕ ในฐานะ

..... เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ
(.....นาย เคนนิส.....ของ.....)
.....ผู้ควบคุมระบบบำบัดน้ำเสีย
(.....นายมานพ.....วิสุทธิวิทยกุล.....)
ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย
..... ผู้รับจ้างให้บริการบำบัดน้ำเสีย
(.....)
ใบอนุญาตเลขที่ หมดอายุ
ออกให้โดย

๒. ข้อมูลเกี่ยวกับระบบบำบัดน้ำเสีย และแหล่งรองรับน้ำทิ้ง

- (๑) ประเภท/ชนิดของระบบบำบัดน้ำเสียระบบแอกลิเวเต็ดสลัดจ์.....
ความสามารถในการรองรับน้ำเสียของระบบบำบัดน้ำเสีย147..... ลบ.ม./วัน
(๒) การทำงานของระบบบำบัดน้ำเสีย ☒ แบบต่อเนื่อง24..... ชั่วโมง/วัน
☐ แบบไม่ต่อเนื่อง (ระบุ).....
(๓) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย ☒ เครื่องสูบน้ำ ☒ เครื่องเติมอากาศ
☐ เครื่องกวน/ผสมน้ำเสีย ☐ เครื่องกวน/ผสมสารเคมี
☐ เครื่องสูบละกอน ☐ อื่น ๆ (ระบุ)..... “-”
(๔) แหล่งรองรับน้ำทิ้ง (ระบุ)ท่อระบายน้ำสาธารณะ.....
(๕) วิธีการการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัดจ้างรถสูบน้ำสูบเพื่อนำไปกำจัด

๓. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (๑) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) ๖๖๖.๔๑.....
(๒) ปริมาณน้ำใช้ทุกกิจกรรมในแหล่งกำเนิดมลพิษ (ลบ.ม.)๑,๔๕.๒.....
(๓) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.).....๑,๑๕๓.๖.....
(๔) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสียระบายทุกวัน.....
(๕) ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ลิตรหรือกิโลกรัม)น้ำหมักจุลินทรีย์ 200 ลิตร.....
(๖) การทำงานของระบบบำบัดน้ำเสียและอุปกรณ์
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ (ระบุ).....
- เครื่องสูบน้ำ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
- เครื่องเติมอากาศ ☒ ปกติ ☐ ผิดปกติ (ระบุ)
- เครื่องกวน/ผสมน้ำเสีย ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
- เครื่องกวน/ผสมสารเคมี ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
- เครื่องสูบละกอน ☐ ปกติ ☐ ผิดปกติ (ระบุ)..... “-”
- อื่นๆ ☐ ปกติ ☐ ผิดปกติ (ระบุ) “-”
(๗) ปริมาณตะกอนส่วนเกินจากระบบบำบัดน้ำเสียที่นำไปกำจัด (ลบ.ม.) “-”
(๘) ปัญหา อุปสรรค และแนวทางแก้ไขมีขยะอุดตันค้ำเนินการแก้ไขโดยตนเองออกจากเครื่องเติมอากาศ.....

ถ้าเดือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ
ข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท
หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
๒.ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จต้องระวาง
โทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

เอกสารการฝึกอบรมการป้องกันและระงับอัคคีภัย (ฝึกภายในโครงการ)

ONYX

Hospitality Group

Ref: SAB

Fire Alarm Monthly Reaction Drill (Silent)

Ref: SAB

แบบฟอร์มการฝึกการตอบสนองต่อสัญญาณแจ้งเหตุเพลิงไหม้ประจำเดือน (แบบไม่ออกใช้อุปกรณ์แจ้งเหตุฯ) เช่น กระลั่น สัญญาณไฟกระพริบ

แบบฟอร์มการฝึกการตอบสนองต่อสัญญาณแจ้งเหตุเพลิงไหม้ประจำเดือน (แบบไม่ออกใช้อุปกรณ์แจ้งเหตุฯ) เช่น กระลั่น สัญญาณไฟกระพริบ

Month:
เดือน

Shift:
ช่วงเวลาทำงาน (เช้า กลาง ดึก)

Score: (%)
คะแนน

27 JULY, 2025

AFTERNOON SHIFT

100%

Trainer to assess
ผู้ฝึกการประเมิน

Points Available (PA)
คะแนนเต็ม

Points Scored (PS)
คะแนนที่ได้

1. Reaction time for ERT (Less than 180 seconds)
ระยะเวลาที่ทีมตอบสนองการฉุกเฉินหลังจากได้รับสัญญาณไฟแดง (น้อยกว่า 180 วินาที)

1

1

2. All members of ERT carried Portable Fire Extinguishers (PFE)?
เจ้าหน้าที่ทุกคนของทีมตอบสนองการฉุกเฉินพกพาถังดับเพลิงแบบมือถือหรือไม่

1

1

3. ERT tested door with back of hand before opening?
เจ้าหน้าที่ทุกคนของทีมตอบสนองการฉุกเฉินทดสอบอุณหภูมิประตูหน้าห้องก่อนเปิดหรือไม่

1

1

4. ERT understood the re-entry procedure?
ทีมตอบสนองการฉุกเฉินเข้าใจในกระบวนการกลับเข้าไปยังพื้นที่ได้หรือไม่

1

1

5. ERT knew correct code to report 'real fire'?
ทีมตอบสนองการฉุกเฉินแจ้งรหัสที่ถูกต้องจากโทรศัพท์มือถือในขั้นต้นหรือไม่

1

1

6. Reaction time for EST (< 360 seconds from alarm activation)?
ระยะเวลาที่ทีมตอบสนองการฉุกเฉินหลังจากได้รับสัญญาณแจ้งเตือน (น้อยกว่า 360 วินาที นับตั้งแต่ได้รับสัญญาณแจ้งเตือน)

1

1

7. EST brought fully equipped Fire Cart/Bag?
ทีมตอบสนองการฉุกเฉินพกพาตู้รถดับเพลิงพร้อมอุปกรณ์ดับเพลิงหรือไม่

1

1

8. EST have self contained compressed air breathing apparatus?
ทีมตอบสนองการฉุกเฉินพกพาถังอากาศแบบอัดลมแบบเต็มรูปแบบหรือไม่

1

1

9. Breathing apparatus is fully charged?
เครื่องช่วยหายใจแบบอัดลมถูกชาร์จเต็มหรือไม่

1

1

10. MOD arrived with Master Key?
ผู้ฝึกการประเมินมาถึงพร้อมกับกุญแจหลักหรือไม่

1

1

11. ERT prepared Fire Hoses for EST?
ทีมตอบสนองการฉุกเฉินเตรียมสายดับเพลิงสำหรับทีมตอบสนองการฉุกเฉินหรือไม่

1

1

12. All ERT & EST members carried correct communication devices.
ทีมตอบสนองการฉุกเฉินและผู้ฝึกการประเมินพกพาอุปกรณ์สื่อสารที่ถูกต้องหรือไม่

1

1

12

12

Commented from fire leader team :
Post-Simulation Meeting Summary

1 Equipment for Opening Water Valve (F-Tool) ไม่พร้อมตัว F
During the drill, it was observed that the F-tool, which is required to open the water valve in the fire hose cabinet, the water valve difficult to open.
Recommendation: Ensure that the F-tool is included in the standard emergency equipment set and stored in accessible locations. ERT members should be trained on its use and know its exact storage points on each floor or zone.
2 Hand Signals for Firefighting. Coordination. Communication during active fire suppression was occasionally unclear due to the noise and pressure of the situation. Conduct regular refresher training on standardized hand signals used during firefighting operations.

Amari

OZO

shama

THE MOSAIC COLLECTION

ONYX

Hospitality Group

Ref: SAB

Fire Alarm Monthly Reaction Drill (Silent)

Ref: SAB

แบบฟอร์มการฝึกการตอบสนองต่อสัญญาณแจ้งเหตุเพลิงไหม้ประจำเดือน (แบบไม่ออกใช้อุปกรณ์แจ้งเหตุฯ) เช่น กระลั่น สัญญาณไฟกระพริบ

แบบฟอร์มการฝึกการตอบสนองต่อสัญญาณแจ้งเหตุเพลิงไหม้ประจำเดือน (แบบไม่ออกใช้อุปกรณ์แจ้งเหตุฯ) เช่น กระลั่น สัญญาณไฟกระพริบ

Month:
เดือน

Shift:
ช่วงเวลาทำงาน (เช้า กลาง ดึก)

Score: (%)
คะแนน

31 AUGUST, 2025

AFTERNOON SHIFT

100%

Trainer to assess
ผู้ฝึกการประเมิน

Points Available (PA)
คะแนนเต็ม

Points Scored (PS)
คะแนนที่ได้

1. Reaction time for ERT (Less than 180 seconds)
ระยะเวลาที่ทีมตอบสนองการฉุกเฉินหลังจากได้รับสัญญาณไฟแดง (น้อยกว่า 180 วินาที)

1

1

2. All members of ERT carried Portable Fire Extinguishers (PFE)?
เจ้าหน้าที่ทุกคนของทีมตอบสนองการฉุกเฉินพกพาถังดับเพลิงแบบมือถือหรือไม่

1

1

3. ERT tested door with back of hand before opening?
เจ้าหน้าที่ทุกคนของทีมตอบสนองการฉุกเฉินทดสอบอุณหภูมิประตูหน้าห้องก่อนเปิดหรือไม่

1

1

4. ERT understood the re-entry procedure?
ทีมตอบสนองการฉุกเฉินเข้าใจในกระบวนการกลับเข้าไปยังพื้นที่ได้หรือไม่

1

1

5. ERT knew correct code to report 'real fire'?
ทีมตอบสนองการฉุกเฉินแจ้งรหัสที่ถูกต้องจากโทรศัพท์มือถือในขั้นต้นหรือไม่

1

1

6. Reaction time for EST (< 360 seconds from alarm activation)?
ระยะเวลาที่ทีมตอบสนองการฉุกเฉินหลังจากได้รับสัญญาณแจ้งเตือน (น้อยกว่า 360 วินาที นับตั้งแต่ได้รับสัญญาณแจ้งเตือน)

1

1

7. EST brought fully equipped Fire Cart/Bag?
ทีมตอบสนองการฉุกเฉินพกพาตู้รถดับเพลิงพร้อมอุปกรณ์ดับเพลิงหรือไม่

1

1

8. EST have self contained compressed air breathing apparatus?
ทีมตอบสนองการฉุกเฉินพกพาถังอากาศแบบอัดลมแบบเต็มรูปแบบหรือไม่

1

1

9. Breathing apparatus is fully charged?
เครื่องช่วยหายใจแบบอัดลมถูกชาร์จเต็มหรือไม่

1

1

10. MOD arrived with Master Key?
ผู้ฝึกการประเมินมาถึงพร้อมกับกุญแจหลักหรือไม่

1

1

11. ERT prepared Fire Hoses for EST?
ทีมตอบสนองการฉุกเฉินเตรียมสายดับเพลิงสำหรับทีมตอบสนองการฉุกเฉินหรือไม่

1

1

12. All ERT & EST members carried correct communication devices.
ทีมตอบสนองการฉุกเฉินและผู้ฝึกการประเมินพกพาอุปกรณ์สื่อสารที่ถูกต้องหรือไม่

1

1

12

12

Commented from fire leader team :
Post-Simulation Meeting Summary

1. Fire Hose Handling , During the EST incorrectly pulled the fire hose reel in reverse order (swapping head and base) : Training the team correct technique to avoid hose tangling and delays.
Simulate a scenario requiring two connected hoses to test readiness.
2. Hose Length & Connection, A single hose reel may not cover the full distance effectively.Teams must be trained to connect two fire hose reels (or extend with coupling) when additional length is required.

Amari

OZO

shama

THE MOSAIC COLLECTION

Monthly Silent Drill – Scenario

23rd September 2025

Date: Sunday, 23rd September, 2025
Expected Time: 15:00 - 15:30 hrs
Location: Tower - A (Fire Pump Room)

Action Timeline

15:14 hrs: Simulate fire outbreak at Fire Pump- on A Building. Declared Code 1 emergency. (Security Team)
15:17 hrs: ERT arrives on site, MOD confirms fire location at Fire pump A Building. (ERT & MOD)
15:18 hrs: MOD confirms escalation to Code 2 emergency (real fire). (ERT & MOD)
15:20 hrs: EST-Firefighting team and arrive to fighting the fire. Fire hose cabinet used. Engineer cuts electricity at fire scene. (Firefighting Team, EST)
15:25 hrs: ERT leader confirms fire is under control and reports to MOD. (ERT Leader)
15:25 hrs: MOD re-checks fire scene and declares Code 2 cleared. (MOD)
15:30 hrs: Operations resume normal duty. (MOD & ERT) fire exercises

Conclusion:

The monthly fire drill conducted on 23rd September 2025 at Tower-A Fire Pump Room was completed successfully. All team such as Security, ERT, MOD, and the EST responded promptly and followed the planned timeline. The fire location was confirmed quickly, escalation to Code 2 was handled efficiently, and firefighting actions (use of fire hose cabinet and cutting electricity) were executed correctly.

The simulated fire was brought under control within minutes, and operations returned to normal at 15:30 hrs. The drill demonstrated good coordination, communication, and readiness of all teams, with minor improvements noted for clearer hand signal use and ensuring the nearest fire hose reel is always used.



26 SEP 2025



Fire Alarm Monthly Reaction Drill (Silent)

Ref: SAB

Month: 23 September, 2025
Shift: AFTERNOON SHIFT
Score: (%) 100%



Trainer to assess	Points Available (PA)	Points Scored (PS)
1. Reaction time for ERT (Less than 180 seconds)	1	1
2. All members of ERT carried portable fire extinguishers (PFE)?	1	1
3. ERT tested door with back of hand before opening?	1	1
4. ERT understood the re-entry procedure?	1	1
5. ERT knew correct code to report 'real fire'?	1	1
6. Reaction time for EST (< 300 seconds from alarm activation)?	1	1
7. EST brought fully equipped Fire Cart/Bag?	1	1
8. EST have self contained compressed air breathing apparatus?	1	1
9. Breathing apparatus is fully charged?	1	1
10. MOD arrived with Master Key?	1	1
11. ERT prepared Fire Hoses for EST?	1	1
12. All ERT & EST members carried correct communication devices.	1	1
TOTAL	12	12

Commented from fire leader team :

Post-Simulation Meeting Summary

Reinforcing Hand Signals

Reinforce standardized hand signals during firefighting operations to ensure all team members understand and respond quickly.

- Conduct a short refresher training before each drill to practice hand signals.

- Place hand signal charts at strategic locations (fire pump rooms, control rooms) for quick reference.

Use of Nearest Fire Hose Reel

Always use the nearest fire hose reel to minimize response time and prevent delays in water supply.

- Conduct walk-throughs with staff to identify the nearest hose reels in each area.

- Include hose reel usage demonstration in every quarterly drill to build confidence in real emergencies.

26 SEP 2025

Pathep

SIGNATURE



THE MOSAIC COLLECTION

Code 1 ERI

Duty Manager/MOD : K. Mam
Engineering 1 : K. Boy
Security 1 : K. Prateep
Security-FCP : K. Aey



Thail

Code 2 EST

Engineering 1 : K. Arm
Housekeeping 1 : K. Man
Security 1 : K. Umnaj



After session feedback

No.	Topic	Action
1	Firefighting Hand Signals	- Reinforce standardized hand signals during firefighting operations to ensure all team members understand and respond quickly. - Conduct a short refresher training before each drill to practice hand signals. - Place hand signal charts at strategic locations (fire pump rooms, control rooms) for quick reference.
2	Use of Nearest Fire Hose Reel	- Always use the nearest fire hose reel to minimize response time and prevent delays in water supply. - Conduct walk-throughs with staff to identify the nearest hose reels in each area. - Include hose reel usage demonstration in every quarterly drill to build confidence in real emergencies.

Thail

Training Attendance Sheet

Property: shama

Course Name: Monthly Silent drill Reaction

Date: 23-9-2025

Trainer: Prateep Prasitsung

Time: 15:00 - 16:30

Trainer's Position: Manager, Security

Venue: Rive Pump - PW-A

No.	Name - Surname	Position	Department	Signature
1	Kamonrat Sarasap	Duty Manager	Front Office	
2	Niwat Kongpuees	Se T/L	HK	
3	Sutaporn Dantachul	MDST	Revenue	
4	Wanna Pongjumnantun	DM	FO	
5	Gurav Phairankhla	HM	HK	
6	Suriya Smit	HM	HK	
7	Narannan hon	T/L	ERG	
8	Weeraphol Sriratanud	HM	HK	
9	Amrak Pongtho	Eng. Tech	Eng.	
10	Boonyasit Bootee	Eng. Tech	Eng.	
11	Tasin Pimson	MFO	FO	
12	Titirat Tisamanai	AMSEC	SC	
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				

Certified Trainer's Signature: Prateep

Date: 23-9-2026

Third



REPORT ANNUAL FIRE DRILL AND EVACUATION TRAINING 2025

Date 21 OCTOBER 2025

Exercise Objective

Purpose of exercise was to assess the readiness and response of the Emergency Response Team, Emergency support team, Crisis Management team and to ensure all TMs know the fire evacuation procedure and fire training readiness and how to operate the fire fighting equipment.

Headcounts

Total Participation approximately 115 persons
Total Hotel manning 118 persons
Total participant of basic fire training 52 persons
Percentage 97.45%
Hotel's Occupancy 78.53%

Emergency Response Team			
Name	Equipment	Communication System	Department
Kamonrat Sarasap	Master Key Card	Walkie Talkie	Front Office
Niwat Kongpuees	Fire Cart	Walkie Talkie	Engineering
Sutaporn Dantachul	Master Key Card	Walkie Talkie	Front Office
Wanna Pongjumnantun	Master Key Card	Walkie Talkie	Security
Emergency Support Team			
Name	Equipment	Communication System	Department
Wanna Pongjumnantun	Fire Suit & SCBA & Fire Hose	Walkie Talkie	Engineering
Alongkot Surprasert	Fire Suit & SCBA & Fire Hose	Walkie Talkie	Security
Wit Popsai	Fire Cart	Walkie Talkie	Engineering
Niwat Kongpuees	Fire Cart	Walkie Talkie	Housekeeping
Pratichon Makmoon	N/A	Walkie Talkie	Security
Fire Command Center (FCC)			
Name	Equipment	Communication System	Department
Pratichon Makmoon	Coordinate at FCC	Walkie Talkie	Security
Tasin Pimson	Coordinate at FCC	Walkie Talkie	Front Office
First Aider Team			
Name	Equipment	Communication System	Department
Thipayarat Keawkrase	Master Key Card	Walkie Talkie	Executive Office
Apichat Buthong	First Aid Box	Walkie Talkie	Department
Sudrabat Chaiat	First Aid Box	Walkie Talkie	Front Office

Sequence of Events

Time	Events
At 15:11 hrs.	1st Scenario - CODE 1 - Fire alarm panel at security office activated from room B1111 (0000 room) Security team member at fire control Panel acknowledged and communicate via walkie talkie to activate ERT which consists of Duty Manager, Engineering, MOD and Security to proceed to the location to check and respond the fire alarm show up Tower B Floor 11 Zone D
At 15:15 hrs.	The ERT (MOD, Duty Manager, Engineering) reached at Tower B Floor 11 Zone D The ERT entered the room and noticed a fire had broken out in Room B 1111 and that one victim was lying on the floor, unconscious. The ERT immediately began using a fire extinguisher to put out the fire while simultaneously removing the injured person from the room and bringing them outside for first aid treatment.
At 15:15 hrs	The MOD confirmed CODE M (Medical Assistant) Need First aider to support with a wheelchair and first aid supply.
At 15:17 hrs	The MOD confirmed CODE 2 The ERT needed to notify the Emergency Support Team (EST) to rush to the scene since the fire was not under control. Once arrived, the EST team (fire fighting team) must start putting out the fire from the nearest fire hose panel. At the same time, the Hotel Manager (HM) receive notified of the incident.
At 15:17 hrs	The MOD requested an ambulance via walkie talkie after confirming CODE M.
At 15:22 hrs	The EST arrived at the fire scene and began fighting the fire; this took five minutes. The ERT, via the Manager on Duty (MOD), confirmed the fire was out of control and that assistance from the local fire brigade department was needed. This request was communicated via the CMT group line and walkie talkie to get approval from the Fire Commander (HM), CODE 3 The HM needed to be notified of this matter to activate the local fire brigade department through the security office. This notification must be communicated through the ERT Line group / walkie-talkie.
At 15:22 hrs	The Fire Commander (HM) APPROVED CODE 3. The Fire Commander (HM) authorized contacting the local fire brigade department via 199 for assistance. One engineer was instructed to standby at the hotel entrance to cooperate with the local fire brigade team. For the safety of guests and Team Members (TMs), the HM was authorized to turn on the hotel's general fire alarm announcement to evacuate all in-house guests and TMs.
At 15:35 hrs	The Local Fire Brigade arrived at the hotel and was immediately coordinated by the engineer at the Tower B. The Brigade proceeded to take over fire suppression efforts from the hotel EST team.
At 15:38 hrs	CODE 3 cleared the situation back to normal.

Monthly Silent Drill – Scenario

23rd November 2025

Date: Sunday, 23rd November, 2025

Time: 20:36 – 21:00 hrs.

Location: Roof Tower B

Action Plan

- 20:36 hrs: Simulate a fire outbreak at Roof Tower B. Declare Code 1 emergency. (Security Team)
- 20:39 hrs: Duty Manager confirms escalation to Code 2 emergency (real fire). (ERT & MOD)
- 20:39 hrs: ERT arrives on site Duty Manager confirms the fire location at Roof Tower B. (ERT, Duty Manager)
- 20:45 hrs: EST Firefighting Team and first aiders arrive. Fire hose cabinet used. Engineer isolates electricity at the fire scene. (Firefighting Team, EST)
- 20:46 hrs: The patient has been safely moved out of the affected area. (First Aider)
- 20:47 hrs: ERT Leader confirms the fire is under control and reports to MOD. (ERT Leader)
- 20:49 hrs: MOD re-checks the fire scene and declares Code 2 cleared.
- 20:49 hrs: Operations resume normal and declares Code 2 cleared.
- 21:00 hrs: Operations resume normal

Conclusion:

The fire drill conducted on Sunday, 23rd November 2025 at Roof pTower B was executed successfully according to the planned timeline. All teams, including the Security Team, ERT, EST Firefighting Team, First Aiders, and Engineering personnel, responded promptly and efficiently. The escalation procedures from Code 1 to Code 2 were correctly followed, and the fire scene was managed safely and effectively.

The exercise demonstrated that emergency protocols, communication channels, and coordination among all involved parties are well-established and functioning as intended. Normal operations were resumed without incident, confirming readiness for any potential real fire emergency.

Thid
26 NOV 2025

 shama Lifeline Asia	23 NOV 2025	<i>Ratup.</i>
SIGNATURE		

Code 1 ERT

Duty Manager : K.Carrot
Engineering 1 : K.Dome
MOD/Security 1 : K.Prateep
Security-FCP : K.Sun



Code 2 EST

Engineering 1 : K. Tan

Housekeeping 1 : K. Oh

Security 1 : K. Tanarin

Concierge : K. Armie



After session feedback

No.	Topic	Action
1	Code 2 indicate the location of fire.	-The Duty Manager must clearly announce the confirmed fire location during Code 2 escalation. -Example announcement: "Code 2 – Rooftop Tower B."
2	Proper Positioning of Firefighting Personnel	-This ensures all responding teams receive precise information and can proceed to the correct location without delay. -Firefighting team members should always position themselves upwind when approaching or extinguishing the fire. -This reduces smoke inhalation, improves visibility, and enhances overall safety.
3	Use of Helmet-Mounted Flashlights	-Firefighting personnel must switch on their helmet-mounted flashlights when operating in dark, smoky, or low-visibility areas. -This supports safer movement, clearer assessment of the hazard area, and more effective firefighting operations.

ONYX

Hospitality Group

Training Attendance Sheet

Property: shama

Course Name: Fire Silent Drill Reaction: November 2025

Date: 23/11/2025

Trainer: Pinitcep

Time: 00:30 - 01:00

Trainer's Position: Security Manager

Venue: Roof Tower B

No.	Name - Surname	Position	Department	Signature
1	Shanthana C.	DM	Front office	garm
2	Weera Phol S.	HK	HM	garm
3	Arms	HK	HM	garm
4	Kittichai M.	BN	BN	garm
5	Wit	Eng	Eng	Wit
6	Arthit J.	Team Security	Security	Arthit
7	Samart S.	Security	Security	Samart
8	Arthit S.	Concierge	P/O	Arthit
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				

Certified Trainer's Signature:

Date:

ONYX

Hospitality Group

Fire Alarm Monthly Reaction Drill (Silent)

Ref: SAB

Month: 23 November, 2025

Shift: AFTERNOON SHIFT

Score: (%) 100%

Points Available (PA) 12

Points Scored (PS) 12

1. Reaction time for ERT (Less than 180 seconds)

2. All members of ERT carried portable fire extinguishers (PFE)?

3. ERT tested door with back of hand before opening?

4. ERT understood the re-entry procedure?

5. ERT knew correct code to report 'real fire'?

6. Reaction time for ERT (< 360 seconds from alarm activation)?

7. ERT brought fully equipped fire cut/bag?

8. ERT have self contained compressed air breathing apparatus?

9. Breathing apparatus is fully charged?

10. MOD arrived with Master Key?

11. ERT prepared fire hoses for ERT?

12. All ERT members carried correct communication devices?

Trainer to assess

1. Reaction time for ERT (Less than 180 seconds)

2. All members of ERT carried portable fire extinguishers (PFE)?

3. ERT tested door with back of hand before opening?

4. ERT understood the re-entry procedure?

5. ERT knew correct code to report 'real fire'?

6. Reaction time for ERT (< 360 seconds from alarm activation)?

7. ERT brought fully equipped fire cut/bag?

8. ERT have self contained compressed air breathing apparatus?

9. Breathing apparatus is fully charged?

10. MOD arrived with Master Key?

11. ERT prepared fire hoses for ERT?

12. All ERT members carried correct communication devices?

Commented from fire leader team :

Post-Simulation Meeting Summary

Indicate the location of fire.

-The Duty Manager must clearly announce the confirmed fire location during Code 2 escalation.

-Example announcement: "Code 2 - Roof Top Tower B."

-This ensures all responding teams receive precise information and can proceed to the correct location without delay.

Proper Positioning of Firefighting Personnel

-Firefighting team members should always position themselves upwind when approaching or extinguishing the fire.

-This reduces smoke inhalation, improves visibility, and enhances overall safety.

Use of Helmet-Mounted Flashlights

-Firefighting personnel must switch on their helmet-mounted flashlights when operating in dark, smoky, or low-visibility areas.

-This supports safer movement, clearer assessment of the hazard area, and more effective firefighting operations.

Amari

OZO

shama

THE MOSAIC COLLECTION

ONYX

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733152

Status

Completed

Due Date

06/03/2026 - 31/03/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

28/03/2026

2

Asset Code

SAB-HST-040

3

PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

22

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

10.7

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

260

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture

2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks1/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)

ONYX

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733152

Status

Completed

Due Date

06/03/2026 - 31/03/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

28/03/2026

2

Asset Code

SAB-HST-040

3

PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

22

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

10.6

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

250

5

Remark and Additional Note

No

6

Record and Upload By (Name & Position)

Manop

7

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks2/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)

ONYX

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733153

Status

Completed

Due Date

06/03/2026 - 31/03/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

28/03/2026

2

Asset Code

SAB-HST-039

3

PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

23

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

12.5

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

260

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture

2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks3/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)

ONYX

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733153

Status

Completed

Due Date

06/03/2026 - 31/03/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

28/03/2026

2

Asset Code

SAB-HST-039

3

PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

23

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

12.5

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

260

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture

2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks4/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

29/03/2026 10:01 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

29/03/2026 10:01 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:18

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:55

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:56

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:01

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:01

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

ONYS

Engineering

SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733155

Status

Completed

Due Date

06/03/2026 - 31/03/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date28/03/2026

2 Asset Code

SAB-HST-037

3 PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

12.7

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture

2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

10/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

29/03/2026 10:18 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

29/03/2026 10:18 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:18

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:57

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:57

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:18

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:18

3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture

4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

12.5

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

11/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

29/03/2026 10:18 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

29/03/2026 10:18 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:18

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:57

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:57

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:18

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:18

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

12/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733156

📌 Status

Completed

📅 Due Date

06/03/2026 - 31/03/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date28/03/2026

2 Asset Code

SAB-HST-036

3 PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

8.9

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

13/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

8.8

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

14/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)



29/03/2026 10:19 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

29/03/2026 10:19 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21
Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:18
This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:58
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:59
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:19
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:19

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

15/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733157

📌 Status

Completed

📅 Due Date

06/03/2026 - 31/03/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date29/03/2026

2 Asset Code

SAB-HST-035

3 PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

8.9

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

16/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

29/03/2026 10:27 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

29/03/2026 10:27 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:20

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 08:48

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 08:50

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:27

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:27

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

ONYS

Engineering

SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733163

📌 Status

Completed

📅 Due Date

06/03/2026 - 31/03/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date

29/03/2026

2 Asset Code

SAB-HST-029

3 PPM of the Quarter

☒ Quarter 1

☐ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11.1

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

34/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

35/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

29/03/2026 10:35 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

29/03/2026 10:35 - 0 hr and 2 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:20

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 08:50

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 08:50

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:35

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:35

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

36/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733164

📌 Status

Completed

📅 Due Date

06/03/2026 - 31/03/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date29/03/2026

2 Asset Code

SAB-HST-028

3 PPM of the Quarter

☒ Quarter 1

☐ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

10.6

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks37/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

10.4

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks38/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)



29/03/2026 10:31 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

29/03/2026 10:31 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21
Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:21
This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 08:51
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 08:52
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:31
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:31

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733165

📌 Status

Completed

📅 Due Date

06/03/2026 - 31/03/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date28/03/2026

2 Asset Code

SAB-HST-027

3 PPM of the Quarter

☒ Quarter 1

☐ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

12.4

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks40/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

28/03/2026 15:56 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

28/03/2026 15:57 - 0 hr and 4 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:21

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:52

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:55

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:56

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:57

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

ONYS

Engineering

SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733167

Status

Completed

Due Date

06/03/2026 - 31/03/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date29/03/2026

2 Asset Code

SAB-HST-025

3 PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

10.5

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

46/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

10.4

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

47/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

29/03/2026 09:28 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

29/03/2026 09:28 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:21

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 22/03/2026 11:00

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 08:54

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 09:28

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 09:28

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

48/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

ONYS

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733168

📌

Status

Completed

📅

Due Date

06/03/2026 - 31/03/2026

👤

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date28/03/2026

2

Asset Code

SAB-HST-024

3

PPM of the Quarter

●

Quarter 1

○

Quarter 2

○

Quarter 3

○

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

22

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

9.9

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

260

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture



2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

49/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

ONYS

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733169

📌

Status

Completed

📅

Due Date

06/03/2026 - 31/03/2026

👤

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date28/03/2026

2

Asset Code

SAB-HST-023

3

PPM of the Quarter

●

Quarter 1

○

Quarter 2

○

Quarter 3

○

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

23

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

11.4

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

260

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture



2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

50/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

ONYS

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733169

📌

Status

Completed

📅

Due Date

06/03/2026 - 31/03/2026

👤

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date28/03/2026

2

Asset Code

SAB-HST-023

3

PPM of the Quarter

●

Quarter 1

○

Quarter 2

○

Quarter 3

○

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

23

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

11.4

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

260

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture



2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

51/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

ONYS

SAB (Shama Lakeview Asoke Bangkok)

🔧

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733169

📌

Status

Completed

📅

Due Date

06/03/2026 - 31/03/2026

👤

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date28/03/2026

2

Asset Code

SAB-HST-023

3

PPM of the Quarter

●

Quarter 1

○

Quarter 2

○

Quarter 3

○

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

23

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

11.4

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

260

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture



2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

52/120



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11.1

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



28/03/2026 15:32 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

TIME SPENT

28/03/2026 15:32 - 0 hr and 3 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:22

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:29

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:31

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:32

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:32



SAB (Shama Lakeview Asoke Bangkok)

 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733170

▲ Status

Completed

📅 Due Date

06/03/2026 - 31/03/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date28/03/2026

2 Asset Code

SAB-HST-022

3 PPM of the Quarter

☒ Quarter 1

☐ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11.8

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

20

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11.2

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

28/03/2026 15:29 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

TIME SPENT

28/03/2026 15:29 - 0 hr and 2 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:22

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:26

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:28

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:29

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:29

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

ONYS

Engineering

SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733171

📌 Status

Completed

📅 Due Date

06/03/2026 - 31/03/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date

28/03/2026

2 Asset Code

SAB-HST-021

3 PPM of the Quarter

☒ Quarter 1

☐ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

8.5

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

58/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

21

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

8.4

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

59/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

28/03/2026 15:24 By SAB (Shama Lakeview Asoke Bangkok)
1.Manager Engineering

TIME SPENT

28/03/2026 15:25 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:22

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:19

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:22

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:24

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:25

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

60/120

ONYX

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733172

Status

Completed

Due Date

06/03/2026 - 31/03/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

28/03/2026

2

Asset Code

SAB-HST-020

3

PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

22

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

9.5

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

260

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture

2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks61/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)

ONYX

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733173

Status

Completed

Due Date

06/03/2026 - 31/03/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

28/03/2026

2

Asset Code

SAB-HST-019

3

PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

22

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

9.4

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

250

5

Remark and Additional Note

No

6

Record and Upload By (Name & Position)

Manop

7

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks62/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)

ONYX

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733173

Status

Completed

Due Date

06/03/2026 - 31/03/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

28/03/2026

2

Asset Code

SAB-HST-019

3

PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

23

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

11.5

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

260

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture

2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks63/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

SAB (Shama Lakeview Asoke Bangkok)

ONYX

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733173

Status

Completed

Due Date

06/03/2026 - 31/03/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

28/03/2026

2

Asset Code

SAB-HST-019

3

PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

23

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

11.5

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

260

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture

2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks64/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

28/03/2026 15:45 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

28/03/2026 15:45 - 0 hr and 2 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:23

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:43

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:45

Approval approved. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:45

This task has been completed. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:45

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

ONYS

Engineering

SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733175

📌 Status

Completed

📅 Due Date

06/03/2026 - 31/03/2026

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date

28/03/2026

2 Asset Code

SAB-HST-017

3 PPM of the Quarter

☐ Quarter 1

☒ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

20

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11.5

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

28/03/2026 15:42 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

28/03/2026 15:42 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:23

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:37

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:40

Approval approved. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:42

This task has been completed. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:42

3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

20

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11.4

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

28/03/2026 15:42 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

28/03/2026 15:42 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer System Generated • 06/03/2026 02:21

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:23

This Task's Status was changed from Open to In Progress SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:37

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:40

Approval approved. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:42

This task has been completed. SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 15:42

3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

20

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11.4

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733176

📌 Status
Completed

📅 Due Date
06/03/2026 - 31/03/2026

👤 Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

- 1 Date28/03/2026
- 2 Asset Code
SAB-HST-016
- 3 PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4
- 4 PPM Action By
Property
- 1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
23

4 Voltage (Volt)
230

5 Current (Ampere)
11.5

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260
- 2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture


2 Condenser Coil Cleanliness and Condition
Clean

1 Reference Picture



- 3 Air Filter Cleanliness and Condition
Clean
- 1 Reference Picture

- 4 Electric Connecting
Normal
- 5 Remote Control and Thermostat
Normal
- 6 Drainage System
Normal
- 7 Hanger and Support
Normal
- 3 PPM-Inspection (After)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23


3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
11.4

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
250
- 5 Remark and Additional Note
No
- 6 Record and Upload By (Name & Position)
Manop
- 7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



- TIME SPENT
29/03/2026 10:42 - 0 hr and 3 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
- COMMENTS
This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:21
Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:23
This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:31
Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:31
Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:42
This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:42



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733177

📌 Status
Completed

📅 Due Date
06/03/2026 - 31/03/2026

👤 Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

- 1 Date28/03/2026
- 2 Asset Code
SAB-HST-015
- 3 PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4
- 4 PPM Action By
Property
- 1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
11.4

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260
- 2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture


2 Condenser Coil Cleanliness and Condition
Clean

1 Reference Picture

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

29/03/2026 10:57 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

29/03/2026 10:58 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:22

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:25

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:38

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:39

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:57

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:58

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

ONYS

Engineering

SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #733183

Status

Completed

Due Date

06/03/2026 - 31/03/2026

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date28/03/2026

2 Asset Code
SAB-HST-009

3 PPM of the Quarter

- Quarter 1
- Quarter 2
- Quarter 3
- Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

8.5

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

94/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

8.4

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

95/120

12/5/69 10:58

app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

Wisit

29/03/2026 10:56 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

29/03/2026 10:56 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

This Task was assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer
System Generated • 06/03/2026 02:22

Changed Due Date from 06/03/2026 to 06/03/2026 - 31/03/2026
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 15/03/2026 13:26

This Task's Status was changed from Open to In Progress
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:39

Requested Approval to be performed. Task assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 28/03/2026 16:40

Approval approved.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:56

This task has been completed.
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering • 29/03/2026 10:56

https://app.limblecmms.com/customDashboard/226673?modalStack=tasks-list-modal.pop-bulk-tasks

96/120



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882972

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-040 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 14/06/2026 22:02		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-040

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
22

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
10.7

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
270

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition
Clean



3 Air Filter Cleanliness and Condition
Clean



4 Electric Connecting
Normal

5 Remote Control and Thermostat
Normal

6 Drainage System
Normal

7 Hanger and Support
Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
21

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
10.5

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260

5 Remark and Additional Note
No

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
14/06/2026 22:02 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882973

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-039 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 14/06/2026 22:02		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-039

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
229

5 Current (Ampere)
12.5

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
270

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

231

5 Current (Ampere)

12.3

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:02 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
14/06/2026 22:02 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882974

 Status

Completed

 Priority

4 Quarterly Jobs

 Type

PM

 Asset

SAB-HST-038 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

 Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

 Due Date

06/06/2026

 Downtime

0 hr and 0 min

 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

 Completed Date

14/06/2026 22:03

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

- 1 Date14/06/2026
- 2 Asset Code
- SAB-HST-038
- 3 PPM of the Quarter
- ☐ Quarter 1
- ☒ Quarter 2
- ☐ Quarter 3
- ☐ Quarter 4
- 4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

12.8

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

270

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

229

5 Current (Ampere)

12.6

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:03 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
14/06/2026 22:03 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882975

👤 Status Completed	🕒 Priority 4 Quarterly Jobs	🔧 Type PM	🏠 Asset SAB-HST-037 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
👤 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	📅 Due Date 06/06/2026	🕒 Downtime 0 hr and 0 min	🏠 Location SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	📅 Completed Date 14/06/2026 22:03		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

- 1 Date14/06/2026
- 2 Asset Code
SAB-HST-037
- 3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4
- 4 PPM Action By

Property
- 1 Pre-Inspection (Before)
 - 1 Temperature Setup (C°)
25
 - 2 Temperature Supply (C°)
23
 - 3 Cooling Time (Min)
20
 - 4 Voltage (Volt)
229
 - 5 Current (Ampere)
12.7
 - 6 Refrigerant Pressure Low Side (Psi)
65
 - 7 Refrigerant Pressure High Side (Psi)
270
- 2 Component
 - 1 Evaporator Coil Cleanliness and Condition

Clean
 - 1 Reference Picture

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:03 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
14/06/2026 22:03 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

- 1 Temperature Setup (C°)
25
- 2 Temperature Supply (C°)
22
- 3 Cooling Time (Min)
19
- 4 Voltage (Volt)
20
- 5 Current (Ampere)
12.5
- 6 Refrigerant Pressure Low Side (Psi)
65
- 7 Refrigerant Pressure High Side (Psi)
250

5 Remark and Additional Note

No

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882976

Status

Completed

Priority

4 Quarterly Jobs

Type

PM

Asset

SAB-HST-036 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date

06/06/2026

Downtime

0 hr and 0 min

Location

SAB (Shama Lakeview Asoke Bangkok)

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date

14/06/2026 22:03

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code

SAB-HST-036

3 PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

8.9

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
14/06/2026 22:03 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



2 Condenser Coil Cleanliness and Condition

Clean



3 Air Filter Cleanliness and Condition

Clean



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

19

4 Voltage (Volt)

229

5 Current (Ampere)

8.6

6 Refrigerant Pressure Low Side (Psi)

64

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882977

Status

Completed

Priority

4 Quarterly Jobs

Type

PM

Asset

SAB-HST-035 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date

06/06/2026

Downtime

0 hr and 0 min

Location

SAB (Shama Lakeview Asoke Bangkok)

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date

14/06/2026 22:04

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code

SAB-HST-035

3 PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

9

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

258

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

8.8

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:03 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

14/06/2026 22:04 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882978

👤 Status

Completed

📌 Priority

4 Quarterly Jobs

🕒 Type

🔧 PM

🚗 Asset

SAB-HST-034 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

👤 Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

📅 Due Date

06/06/2026

🕒 Downtime

0 hr and 0 min

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

📅 Completed Date

14/06/2026 22:04

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code

SAB-HST-034

3 PPM of the Quarter

☐ Quarter 1

☒ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

12.2

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

258

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

26

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

231

5 Current (Ampere)

12

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:04 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
14/06/2026 22:04 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882979

👤 Status Completed	🕒 Priority 4 Quarterly Jobs	🔧 Type PM	🏠 Asset SAB-HST-033 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
👤 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	📅 Due Date 06/06/2026	🕒 Downtime 0 hr and 0 min	🏠 Location SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	📅 Completed Date 14/06/2026 22:05		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

- 1 Date14/06/2026
- 2 Asset Code
SAB-HST-033
- 3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4
- 4 PPM Action By

Property
- 1 Pre-Inspection (Before)
 - 1 Temperature Setup (C°)
25
 - 2 Temperature Supply (C°)
23
 - 3 Cooling Time (Min)
20
 - 4 Voltage (Volt)
230
 - 5 Current (Ampere)
12.9
 - 6 Refrigerant Pressure Low Side (Psi)
65
 - 7 Refrigerant Pressure High Side (Psi)
270
- 2 Component
 - 1 Evaporator Coil Cleanliness and Condition

Clean
 - 1 Reference Picture

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:04 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
14/06/2026 22:05 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

- 1 Temperature Setup (C°)
25
- 2 Temperature Supply (C°)
22
- 3 Cooling Time (Min)
20
- 4 Voltage (Volt)
230
- 5 Current (Ampere)
12.7
- 6 Refrigerant Pressure Low Side (Psi)
65
- 7 Refrigerant Pressure High Side (Psi)
250

5 Remark and Additional Note

No



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882980

Status Completed	Priority 4 Quarterly Jobs	Type 🔧 PM	Asset SAB-HST-032 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 14/06/2026 22:05		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-032

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
10.8

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean



3 Air Filter Cleanliness and Condition

Clean



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
22

3 Cooling Time (Min)
20

4 Voltage (Volt)
232

5 Current (Ampere)
10.6

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
14/06/2026 22:05 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882981

Status Completed	Priority 4 Quarterly Jobs	Type 🔧 PM	Asset SAB-HST-031 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 14/06/2026 22:05		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-031

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
10.5

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture

2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture

4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
22

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
10.3

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

14/06/2026 22:05 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
14/06/2026 22:05 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882982

🔔 Status
Completed

📅 Priority
4 Quarterly Jobs

🕒 Type
PM

🚗 Asset
SAB-HST-030 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

👤 Assigned to
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

📅 Due Date
06/06/2026

🕒 Downtime
0 hr and 0 min

📍 Location
SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By
SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

📅 Completed Date
14/06/2026 22:06

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-030

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
11.5

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
259

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture

2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture

4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
22

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
11.3

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:06 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
14/06/2026 22:06 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882983

Status Completed	Priority 4 Quarterly Jobs	Type 🔧 PM	Asset SAB-HST-029 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 📅 06/06/2026	Downtime 🕒 0 hr and 0 min	Location 🏠 SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 📅 14/06/2026 22:41		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-029

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
11.1

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
270

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 20:59 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
14/06/2026 22:41 - 0 hr and 3 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



2 Condenser Coil Cleanliness and Condition

Clean



3 Air Filter Cleanliness and Condition

Clean



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
10.9

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260

5 Remark and Additional Note

No



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882984

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-028 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 15/06/2026 22:47		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026
2 Asset Code
SAB-HST-028
3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4
4 PPM Action By
Property
1 Pre-Inspection (Before)
1 Temperature Setup (C°)
25
2 Temperature Supply (C°)
23
3 Cooling Time (Min)
20
4 Voltage (Volt)
229
5 Current (Ampere)
10.6
6 Refrigerant Pressure Low Side (Psi)
65
7 Refrigerant Pressure High Side (Psi)
270
2 Component
1 Evaporator Coil Cleanliness and Condition
Clean
1 Reference Picture

6 Record and Upload By (Name & Position)
Manop
7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
15/06/2026 22:47 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



2 Condenser Coil Cleanliness and Condition
Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition
Clean

1 Reference Picture



4 Electric Connecting
Normal

5 Remote Control and Thermostat
Normal

6 Drainage System
Normal

7 Hanger and Support
Normal

3 PPM-Inspection (After)
1 Temperature Setup (C°)
25
2 Temperature Supply (C°)
22
3 Cooling Time (Min)
19
4 Voltage (Volt)
20
5 Current (Ampere)
10.5
6 Refrigerant Pressure Low Side (Psi)
65
7 Refrigerant Pressure High Side (Psi)
253

5 Remark and Additional Note
No



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882985

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-027 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 14/06/2026 22:07		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026
2 Asset Code
SAB-HST-027
3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4
4 PPM Action By
Property
1 Pre-Inspection (Before)
1 Temperature Setup (C°)
25
2 Temperature Supply (C°)
23
3 Cooling Time (Min)
20
4 Voltage (Volt)
230
5 Current (Ampere)
12.5
6 Refrigerant Pressure Low Side (Psi)
65
7 Refrigerant Pressure High Side (Psi)
270
2 Component
1 Evaporator Coil Cleanliness and Condition
Clean
1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

12.3

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:07 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

14/06/2026 22:07 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882986

👤 Status

Completed

📅 Priority

4 Quarterly Jobs

🕒 Type

PM

🚗 Asset

SAB-HST-026 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

👤 Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

📅 Due Date

06/06/2026

🕒 Downtime

0 hr and 0 min

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

📅 Completed Date

14/06/2026 22:06

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code

SAB-HST-026

3 PPM of the Quarter

☐ Quarter 1

☒ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

26

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11.5

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11.4

6 Refrigerant Pressure Low Side (Psi)

66

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:06 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
14/06/2026 22:06 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882987

👤 Status Completed	🕒 Priority 4 Quarterly Jobs	🕒 Type 🔧 PM	🏠 Asset SAB-HST-025 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
👤 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	📅 Due Date 06/06/2026	🕒 Downtime 0 hr and 0 min	🏠 Location SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	📅 Completed Date 14/06/2026 22:18		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

- 1 Date14/06/2026
- 2 Asset Code
SAB-HST-025
- 3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4
- 4 PPM Action By

Property
- 1 Pre-Inspection (Before)
 - 1 Temperature Setup (C°)
25
 - 2 Temperature Supply (C°)
23
 - 3 Cooling Time (Min)
20
 - 4 Voltage (Volt)
229
 - 5 Current (Ampere)
10.5
 - 6 Refrigerant Pressure Low Side (Psi)
65
 - 7 Refrigerant Pressure High Side (Psi)
260
- 2 Component
 - 1 Evaporator Coil Cleanliness and Condition

Clean
 - 1 Reference Picture

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:18 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
14/06/2026 22:18 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

- 1 Temperature Setup (C°)
25
- 2 Temperature Supply (C°)
22
- 3 Cooling Time (Min)
20
- 4 Voltage (Volt)
230
- 5 Current (Ampere)
10.4
- 6 Refrigerant Pressure Low Side (Psi)
65
- 7 Refrigerant Pressure High Side (Psi)
250

5 Remark and Additional Note

No



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882988

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-024 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 16/06/2026 16:45		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-024

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)
1 Temperature Setup (C°)
0
2 Temperature Supply (C°)
1
3 Cooling Time (Min)
0
4 Voltage (Volt)
1
5 Current (Ampere)
0
6 Refrigerant Pressure Low Side (Psi)
0
7 Refrigerant Pressure High Side (Psi)
0

2 Component
1 Evaporator Coil Cleanliness and Condition
Clean
1 Reference Picture

2 Condenser Coil Cleanliness and Condition
Clean

1 Reference Picture

3 Air Filter Cleanliness and Condition
Clean

1 Reference Picture

4 Electric Connecting
Normal

5 Remote Control and Thermostat
Normal

6 Drainage System
Normal

7 Hanger and Support
Normal

3 PPM-Inspection (After)
1 Temperature Setup (C°)
0
2 Temperature Supply (C°)
0
3 Cooling Time (Min)
0
4 Voltage (Volt)
0
5 Current (Ampere)
0
6 Refrigerant Pressure Low Side (Psi)
0
7 Refrigerant Pressure High Side (Psi)
0

5 Remark and Additional Note
Yes

1 Please Explain
ยกเลิกการใช้งาน

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
16/06/2026 16:45 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882989

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-023 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 16/06/2026 16:44		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-023

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)
1 Temperature Setup (C°)
0
2 Temperature Supply (C°)
0
3 Cooling Time (Min)
0
4 Voltage (Volt)
0
5 Current (Ampere)
0
6 Refrigerant Pressure Low Side (Psi)
0
7 Refrigerant Pressure High Side (Psi)
0

2 Component
1 Evaporator Coil Cleanliness and Condition
Clean
1 Reference Picture

2 Condenser Coil Cleanliness and Condition
Clean

1 Reference Picture

3 Air Filter Cleanliness and Condition
Clean

1 Reference Picture

4 Electric Connecting
Normal

5 Remote Control and Thermostat
Normal

6 Drainage System
Normal

7 Hanger and Support
Normal

3 PPM-Inspection (After)
1 Temperature Setup (C°)
0
2 Temperature Supply (C°)
0
3 Cooling Time (Min)
0
4 Voltage (Volt)
0
5 Current (Ampere)
0
6 Refrigerant Pressure Low Side (Psi)
0
7 Refrigerant Pressure High Side (Psi)
0

5 Remark and Additional Note
Yes

1 Please Explain
ยกเลิกการใช้งาน

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
16/06/2026 16:44 - 0 hr and 4 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882990

Status Completed	Priority 4 Quarterly Jobs	Type 🔧 PM	Asset SAB-HST-022 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 📅 06/06/2026	Downtime 🕒 0 hr and 0 min	Location 📍 SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 📅 14/06/2026 22:11		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-022

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
19

4 Voltage (Volt)
230

5 Current (Ampere)
11.8

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean



3 Air Filter Cleanliness and Condition

Clean



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
231

5 Current (Ampere)
11.7

6 Refrigerant Pressure Low Side (Psi)
66

7 Refrigerant Pressure High Side (Psi)
250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
14/06/2026 22:11 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882991

Status Completed	Priority 4 Quarterly Jobs	Type 🔧 PM	Asset SAB-HST-021 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 📅 06/06/2026	Downtime 🕒 0 hr and 0 min	Location 📍 SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 📅 14/06/2026 22:10		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-021

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
21

4 Voltage (Volt)
229

5 Current (Ampere)
8.5

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

229

5 Current (Ampere)

8.4

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:10 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
14/06/2026 22:10 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882992

🔔 Status

Completed

🕒 Priority

4 Quarterly Jobs

🕒 Type

🔧 PM

🚗 Asset

SAB-HST-020 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

👤 Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

📅 Due Date

06/06/2026

🕒 Downtime

0 hr and 0 min

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

📅 Completed Date

14/06/2026 22:16

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code

SAB-HST-020

3 PPM of the Quarter

☐ Quarter 1

☒ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

229

5 Current (Ampere)

9.5

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

9.4

6 Refrigerant Pressure Low Side (Psi)

66

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:16 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

14/06/2026 22:16 - 0 hr and 3 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882993

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-019 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 14/06/2026 22:27		

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-019

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
11.6

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:27 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

14/06/2026 22:27 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

19

4 Voltage (Volt)

230

5 Current (Ampere)

11.4

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882994

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-018 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 12/06/2026 09:54		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date10/06/2026

2 Asset Code
SAB-HST-018

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
20

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
7.7

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
245

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture

6 Record and Upload By (Name & Position)
Navanakorn T.L

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
12/06/2026 09:54 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



2 Condenser Coil Cleanliness and Condition
Clean



3 Air Filter Cleanliness and Condition
Clean



4 Electric Connecting
Normal

5 Remote Control and Thermostat
Normal

6 Drainage System
Normal

7 Hanger and Support
Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
20

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
7.6

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
245

5 Remark and Additional Note
No



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882995

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-017 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 12/06/2026 09:54		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date09/06/2026

2 Asset Code
SAB-HST-017

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
22

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
7.67

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
248

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture

2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture

4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

20

3 Cooling Time (Min)

19

4 Voltage (Volt)

230

5 Current (Ampere)

7.6

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

245

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Navanakorn T.L

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

12/06/2026 09:54 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

12/06/2026 09:54 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882996

👤 Status

Completed

🕒 Priority

4 Quarterly Jobs

🕒 Type

PM

🚗 Asset

SAB-HST-016 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

👤 Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

📅 Due Date

06/06/2026

🕒 Downtime

0 hr and 0 min

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

📅 Completed Date

15/06/2026 23:01

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code

SAB-HST-016

3 PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11.5

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture

3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture

4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

11.3

6 Refrigerant Pressure Low Side (Psi)

66

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



15/06/2026 23:01 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

15/06/2026 23:01 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882997

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-015 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 14/06/2026 22:24		

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-015

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
11.4

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:24 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

14/06/2026 22:24 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

229

5 Current (Ampere)

11.2

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

230

5 Remark and Additional Note

No

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882998

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-014 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 14/06/2026 22:23		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-014

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
10.4

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition
Clean



3 Air Filter Cleanliness and Condition
Clean



4 Electric Connecting
Normal

5 Remote Control and Thermostat
Normal

6 Drainage System
Normal

7 Hanger and Support
Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
22

3 Cooling Time (Min)
20

4 Voltage (Volt)
231

5 Current (Ampere)
10.3

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
250

5 Remark and Additional Note
No

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
14/06/2026 22:23 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #882999

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-013 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 14/06/2026 22:31		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-013

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
8.7

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

8.8

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:31 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

14/06/2026 22:31 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883000

👤 Status

Completed

📅 Priority

4 Quarterly Jobs

🕒 Type

🔧 PM

🔧 Asset

SAB-HST-012 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

👤 Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

📅 Due Date

06/06/2026

🕒 Downtime

0 hr and 0 min

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

📅 Completed Date

14/06/2026 22:30

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code

SAB-HST-012

3 PPM of the Quarter

☐ Quarter 1

☒ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

10.6

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

270

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

10.5

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:30 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

14/06/2026 22:30 - 0 hr and 2 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883001

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-011 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 12/06/2026 09:55		

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date10/06/2026

2 Asset Code

SAB-HST-011

3 PPM of the Quarter

☐ Quarter 1

☒ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

24

2 Temperature Supply (C°)

20

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

10.6

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

245

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture

10.5

6 Refrigerant Pressure Low Side (Psi)

64

7 Refrigerant Pressure High Side (Psi)

246

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Navanakorn T.L.

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/06/2026 09:55 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

12/06/2026 09:55 - 0 hr and 10 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

20

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883002

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-010 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 15/06/2026 22:52		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date 14/06/2026

2 Asset Code
SAB-HST-010

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
0

2 Temperature Supply (C°)
0

3 Cooling Time (Min)
0

4 Voltage (Volt)
1

5 Current (Ampere)
0

6 Refrigerant Pressure Low Side (Psi)
0

7 Refrigerant Pressure High Side (Psi)
0

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture

2 Condenser Coil Cleanliness and Condition
Clean

1 Reference Picture

3 Air Filter Cleanliness and Condition
Clean

1 Reference Picture

4 Electric Connecting
Normal

5 Remote Control and Thermostat
Normal

6 Drainage System
Normal

7 Hanger and Support
Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)
0

2 Temperature Supply (C°)
0

3 Cooling Time (Min)
0

4 Voltage (Volt)
0

5 Current (Ampere)
0

6 Refrigerant Pressure Low Side (Psi)
0

7 Refrigerant Pressure High Side (Psi)
0

5 Remark and Additional Note
Yes

1 Please Explain
ถูกต้องเรียบร้อย

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
15/06/2026 22:52 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883003

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-009 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 15/06/2026 22:49		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date 14/06/2026

2 Asset Code
SAB-HST-009

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
8.5

6 Refrigerant Pressure Low Side (Psi)
65

7 Refrigerant Pressure High Side (Psi)
260

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture

2 Condenser Coil Cleanliness and Condition
Clean

1 Reference Picture

3 Air Filter Cleanliness and Condition
Clean

1 Reference Picture

4 Electric Connecting
Normal

5 Remote Control and Thermostat
Normal

6 Drainage System
Normal

7 Hanger and Support
Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)
25

2 Temperature Supply (C°)
23

3 Cooling Time (Min)
20

4 Voltage (Volt)
230

5 Current (Ampere)
8.4

6 Refrigerant Pressure Low Side (Psi)
9

7 Refrigerant Pressure High Side (Psi)
250

5 Remark and Additional Note
No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT

15/06/2026 22:49 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883004

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-008 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 15/06/2026 22:53		

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-008

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
0

2 Temperature Supply (C°)
0

3 Cooling Time (Min)
0

4 Voltage (Volt)
0

5 Current (Ampere)
1

6 Refrigerant Pressure Low Side (Psi)
0

7 Refrigerant Pressure High Side (Psi)
0

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture

2 Condenser Coil Cleanliness and Condition
Clean

1 Reference Picture

3 Air Filter Cleanliness and Condition
Clean

1 Reference Picture

4 Electric Connecting
Normal

5 Remote Control and Thermostat
Normal

6 Drainage System
Normal

7 Hanger and Support
Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)
0

2 Temperature Supply (C°)
0

3 Cooling Time (Min)
0

4 Voltage (Volt)
0

5 Current (Ampere)
0

6 Refrigerant Pressure Low Side (Psi)
0

7 Refrigerant Pressure High Side (Psi)
0

5 Remark and Additional Note
Yes

1 Please Explain
ยกเลิกใบตรวจงาน

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT

15/06/2026 22:53 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

SAB (Shama Lakeview Asoke Bangkok)



ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883005

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HST-007 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 06/06/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 15/06/2026 23:00		

DESCRIPTION

@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1 Date14/06/2026

2 Asset Code
SAB-HST-007

3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4

4 PPM Action By
Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)
0

2 Temperature Supply (C°)
0

3 Cooling Time (Min)
0

4 Voltage (Volt)
0

5 Current (Ampere)
0

6 Refrigerant Pressure Low Side (Psi)
0

7 Refrigerant Pressure High Side (Psi)
0

2 Component

1 Evaporator Coil Cleanliness and Condition
Clean

1 Reference Picture

2 Condenser Coil Cleanliness and Condition
Clean

1

Reference Picture

3

Air Filter Cleanliness and Condition

Clean

1

Reference Picture

4

Electric Connecting

Normal

5

Remote Control and Thermostat

Normal

6

Drainage System

Normal

7

Hanger and Support

Normal

3

PPM-Inspection (After)

1

Temperature Setup (C°)

0

2

Temperature Supply (C°)

0

3

Cooling Time (Min)

0

4

Voltage (Volt)

0

5

Current (Ampere)

0

6

Refrigerant Pressure Low Side (Psi)

0

7

Refrigerant Pressure High Side (Psi)

0

5

Remark and Additional Note

Yes

1

Please Explain

ขอแจ้งการโอเครงาน

6

Record and Upload By (Name & Position)

Manop

7

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

15/06/2026 23:00 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

15/06/2026 23:00 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883006

Status

Completed

Priority

4 Quarterly Jobs

Type

PM

Asset

SAB-HST-006 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date

06/06/2026

Downtime

0 hr and 0 min

Location

SAB (Shama Lakeview Asoke Bangkok)

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date

15/06/2026 22:58

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

14/06/2026

2

Asset Code

SAB-HST-006

3

PPM of the Quarter

Quarter 1

☒ Quarter 2

Quarter 3

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

0

2

Temperature Supply (C°)

0

3

Cooling Time (Min)

0

4

Voltage (Volt)

0

5

Current (Ampere)

0

6

Refrigerant Pressure Low Side (Psi)

0

7

Refrigerant Pressure High Side (Psi)

0

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture

2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

3

Air Filter Cleanliness and Condition

Clean

1

Reference Picture

4

Electric Connecting

Normal

5

Remote Control and Thermostat

Normal

6

Drainage System

Normal

7

Hanger and Support

Normal

3

PPM-Inspection (After)

1

Temperature Setup (C°)

0

2

Temperature Supply (C°)

0

3

Cooling Time (Min)

0

4

Voltage (Volt)

0

5

Current (Ampere)

0

6

Refrigerant Pressure Low Side (Psi)

0

7

Refrigerant Pressure High Side (Psi)

0

5

Remark and Additional Note

Yes

1

Please Explain

ขอแจ้งการโอเครงาน

6

Record and Upload By (Name & Position)

Manop

7

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

15/06/2026 22:57 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

15/06/2026 22:58 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883007

Status

Completed

Priority

4 Quarterly Jobs

Type

PM

Asset

SAB-HST-005 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date

06/06/2026

Downtime

0 hr and 0 min

Location

SAB (Shama Lakeview Asoke Bangkok)

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date

15/06/2026 22:56

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

14/06/2026

2

Asset Code

SAB-HST-005

3

PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

☒ Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

0

2

Temperature Supply (C°)

0

3

Cooling Time (Min)

-1

4

Voltage (Volt)

0

5

Current (Ampere)

0

6

Refrigerant Pressure Low Side (Psi)

0

7

Refrigerant Pressure High Side (Psi)

0

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture

2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

3

Air Filter Cleanliness and Condition

Clean

1

Reference Picture

4

Electric Connecting

Normal

5

Remote Control and Thermostat

Normal

6

Drainage System

Normal

7

Hanger and Support

Normal

3

PPM-Inspection (After)

1

Temperature Setup (C°)

0

2

Temperature Supply (C°)

0

3

Cooling Time (Min)

0

4

Voltage (Volt)

0

5

Current (Ampere)

0

6

Refrigerant Pressure Low Side (Psi)

0

7

Refrigerant Pressure High Side (Psi)

0

5

Remark and Additional Note

Yes

1

Please Explain

ขอแจ้งการโอ้งาน

6

Record and Upload By (Name & Position)

Manop

7

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

15/06/2026 22:56 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

15/06/2026 22:56 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883008

Status

Completed

Priority

4 Quarterly Jobs

Type

PM

Asset

SAB-HST-004 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date

06/06/2026

Downtime

0 hr and 0 min

Location

SAB (Shama Lakeview Asoke Bangkok)

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date

15/06/2026 22:55

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

14/06/2026

2

Asset Code

SAB-HST-004

3

PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

0

2

Temperature Supply (C°)

0

3

Cooling Time (Min)

0

4

Voltage (Volt)

0

5

Current (Ampere)

0

6

Refrigerant Pressure Low Side (Psi)

0

7

Refrigerant Pressure High Side (Psi)

-1

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture

2

Condenser Coil Cleanliness and Condition

Clean

1

Reference Picture

1

Reference Picture

3

Air Filter Cleanliness and Condition

Clean

1

Reference Picture

4

Electric Connecting

Normal

5

Remote Control and Thermostat

Normal

6

Drainage System

Normal

7

Hanger and Support

Normal

3

PPM-Inspection (After)

1

Temperature Setup (C°)

0

2

Temperature Supply (C°)

0

3

Cooling Time (Min)

0

4

Voltage (Volt)

0

5

Current (Ampere)

0

6

Refrigerant Pressure Low Side (Psi)

0

7

Refrigerant Pressure High Side (Psi)

0

5

Remark and Additional Note

Yes

1

Please Explain

ขอแจ้งการโอ้งาน

6

Record and Upload By (Name & Position)

Manop

7

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

15/06/2026 22:55 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

15/06/2026 22:55 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883009

Status

Completed

Priority

4 Quarterly Jobs

Type

PM

Asset

SAB-HST-003 > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date

06/06/2026

Downtime

0 hr and 0 min

Location

SAB (Shama Lakeview Asoke Bangkok)

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date

14/06/2026 22:02

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

1

Date

14/06/2026

2

Asset Code

SAB-HST-003

3

PPM of the Quarter

Quarter 1

Quarter 2

Quarter 3

Quarter 4

4

PPM Action By

Property

1

Pre-Inspection (Before)

1

Temperature Setup (C°)

25

2

Temperature Supply (C°)

22

3

Cooling Time (Min)

20

4

Voltage (Volt)

230

5

Current (Ampere)

7.8

6

Refrigerant Pressure Low Side (Psi)

65

7

Refrigerant Pressure High Side (Psi)

270

2

Component

1

Evaporator Coil Cleanliness and Condition

Clean

1

Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

7

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

260

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)

Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



14/06/2026 22:02 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

14/06/2026 22:02 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883010

 Status

Completed

 Priority

4 Quarterly Jobs

 Type

PM

 Asset

SAB-HST-002 : Male Locker > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering

 Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

 Due Date

06/06/2026

 Downtime

0 hr and 0 min

 Location

SAB (Shama Lakeview Asoke Bangkok)

 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

 Completed Date

16/06/2026 16:32

DESCRIPTION

@Engineering Standard, @ENG 11-03;

INSTRUCTIONS

1 Date15/06/2026

2 Asset Code

SAB-HST-002

3 PPM of the Quarter

☐ Quarter 1

☒ Quarter 2

☐ Quarter 3

☐ Quarter 4

4 PPM Action By

Property

1 Pre-Inspection (Before)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

23

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

10.7

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

265

2 Component

1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

1 Temperature Setup (C°)

25

2 Temperature Supply (C°)

22

3 Cooling Time (Min)

20

4 Voltage (Volt)

230

5 Current (Ampere)

10.5

6 Refrigerant Pressure Low Side (Psi)

65

7 Refrigerant Pressure High Side (Psi)

250

5 Remark and Additional Note

No

6 Record and Upload By (Name & Position)
Manop

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



16/06/2026 16:32 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
16/06/2026 16:32 - 0 hr and 16 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 11-03 Quarter PPM Split AC Unit - SAB - #883011

👤 Status Completed	🕒 Priority 4 Quarterly Jobs	🕒 Type 🔧 PM	🏠 Asset SAB-HST-001 : Engineering office > ENG 11-01 Split Type AC Unit Asset Register (Not In Guest Rooms) > ENG 11 Split Type AC Unit > 4. SAB Engineering
👤 Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	📅 Due Date 06/06/2026	🕒 Downtime 0 hr and 0 min	🏠 Location SAB (Shama Lakeview Asoke Bangkok)
👤 Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	📅 Completed Date 12/06/2026 10:00		

DESCRIPTION
@Engineering Standard; @ENG 11-03;

INSTRUCTIONS

- 1 Date09/06/2026
- 2 Asset Code
SAB-HST-001
- 3 PPM of the Quarter
☐ Quarter 1
☒ Quarter 2
☐ Quarter 3
☐ Quarter 4
- 4 PPM Action By

Property

1 Pre-Inspection (Before)
1 Temperature Setup (C°)
25
2 Temperature Supply (C°)
22
3 Cooling Time (Min)
20
4 Voltage (Volt)
230
5 Current (Ampere)
9.9
6 Refrigerant Pressure Low Side (Psi)
65
7 Refrigerant Pressure High Side (Psi)
245

2 Component
1 Evaporator Coil Cleanliness and Condition

Clean

1 Reference Picture

6 Record and Upload By (Name & Position)
Navanakorn T.L

7 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/06/2026 10:00 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:00 - 0 hr and 8 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



2 Condenser Coil Cleanliness and Condition

Clean

1 Reference Picture



3 Air Filter Cleanliness and Condition

Clean

1 Reference Picture



4 Electric Connecting

Normal

5 Remote Control and Thermostat

Normal

6 Drainage System

Normal

7 Hanger and Support

Normal

3 PPM-Inspection (After)

- 1 Temperature Setup (C°)
25
- 2 Temperature Supply (C°)
20
- 3 Cooling Time (Min)
20
- 4 Voltage (Volt)
230
- 5 Current (Ampere)
9.9
- 6 Refrigerant Pressure Low Side (Psi)
65
- 7 Refrigerant Pressure High Side (Psi)
245

5 Remark and Additional Note

No

ภาคผนวกที่ 18

รายงานการทำความสะอาดถังพักน้ำและบ่อเก็บน้ำ



Seekiew. Supply & Service

สีเสี่ยว.ซัพพลายแอนด์เซอร์วิส

เลขที่ 710/402 ขอเชิญวันที่ 01/11 แพร่งบางจาก เขตพระโขนง กรุงเทพฯ 10260 โทร. 02-0429689 www.facebook/seekiewsupplyservice

Customer Detail / ข้อมูลลูกค้า		
Project / โครงการ	งานจ้างเปิดถนนตั้งแต่ ปี 2025 POL-SAB2505-0044	โรงแรม รามา แคว้น อโศก กรุงเทพฯ
Location / ที่ตั้ง	41 ซอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า

Engineering Service

Report



APPROVALS TO PROCEED		
Maintenance by	Maintenance by	
Khun Kittiphan Seekiew	Khun Nandol Seekiew	
Date 23-25/07/2025	Date 23-25/07/2025	



Seekiew. Supply & Service

สีเสี่ยว.ซัพพลายแอนด์เซอร์วิส

เลขที่ 710/402 ขอเชิญวันที่ 01/11 แพร่งบางจาก เขตพระโขนง กรุงเทพฯ 10260 โทร. 02-0429689 www.facebook/seekiewsupplyservice

Customer Detail / ข้อมูลลูกค้า		
Project / โครงการ	งานจ้างเปิดถนนตั้งแต่ ปี 2025 POL-SAB2505-0044	โรงแรม รามา แคว้น อโศก กรุงเทพฯ
Location / ที่ตั้ง	41 ซอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า

Table of Content

Table of Content	2
หลักการปฏิบัติงาน	3
มาตรฐานความปลอดภัยในการทำงาน	4 - 5
ภาพการทำความสะอาดบ่อ Underground Tank อาคาร A	6
ภาพการทำความสะอาดบ่อ Underground Tank อาคาร B	7
ภาพการทำความสะอาดบ่อ Roof Tank อาคาร B	8
ภาพการทำความสะอาดบ่อ Roof Tank อาคาร A	9
ภาพการทำความสะอาดบ่อ Surge Tank สระว่ายน้ำ	10
การนำเชื้อโรคด้วย UV-C	11
สรุป ข้อบกพร่องที่ควรดำเนินการแก้ไข	12

APPROVALS TO PROCEED		
Maintenance by	Maintenance by	
Khun Kittiphan Seekiew	Khun Nandol Seekiew	
Date 23-25/07/2025	Date 23-25/07/2025	



Seekiew.Supply&Service

สีเขียว.ศัพพลายแอนด์เซอร์วิส

เลขที่ 710/402 ซอยสุขุมวิท101/1 แขวงบางจาก เขตพระโขนง กรุงเทพฯ 10260 โทร.02-0429889 www.facebook/seekiewsupplyservice

Customer Detail / ข้อมูลลูกค้า			
Project / โครงการ	งานจ้างเปิดถนนที่ 2025 POL-SAB2505-0044	Name / ชื่อ	โรงแรม รามา แคว้น อีเกอ กรุงเทพฯ
Location / ที่ตั้ง	41 รอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า	- 3 -

หลักการปฏิบัติงาน



งานด้านความปลอดภัย

ปัจจุบันนโยบายของระบบการจ่ายน้ำที่ไม่มีคุณภาพ ส่งผลกระทบโดยตรงต่อการดำรงชีวิตประจำวัน และการดำเนินงานขององค์กร หน่วยงาน และยังทำให้สูญเสียโอกาสในการแข่งขันเชิงธุรกิจ อีกทั้งสาเหตุจากการขาดการวางแผนในการดูแลบำรุงรักษาระบบอย่างเหมาะสม ดังนั้นการมีแผนบำรุงรักษา จึงเป็นแนวทางที่จะช่วยให้รักษาความเสถียรภาพของระบบการจ่ายน้ำให้มีคุณภาพและสะอาดพร้อมใช้งานตลอดเวลา

การทำความสะอาดบ่อน้ำดิบ บริการเพื่อให้ลูกค้ากลุ่ม โรงแสม, อาคารชุด และโรงงานอุตสาหกรรม ที่มีความใส่ใจด้านความสะอาด เพิ่มคุณภาพในการผลิต

APPROVALS TO PROCEED			
Maintenance by	Maintenance by		
Khun Kittiphan Seekiew	Khun Nardol Seekiew		
Date 23-25/07/2025	Date 23-25/07/2025		



Seekiew.Supply&Service

สีเขียว.ศัพพลายแอนด์เซอร์วิส

เลขที่ 710/402 ซอยสุขุมวิท101/1 แขวงบางจาก เขตพระโขนง กรุงเทพฯ 10260 โทร.02-0429889 www.facebook/seekiewsupplyservice

Customer Detail / ข้อมูลลูกค้า			
Project / โครงการ	งานจ้างเปิดถนนที่ 2025 POL-SAB2505-0044	Name / ชื่อ	โรงแรม รามา แคว้น อีเกอ กรุงเทพฯ
Location / ที่ตั้ง	41 รอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า	- 4 -

มาตรการความปลอดภัยในการทำงาน



เอกสารรับรองผู้ปฏิบัติงานในพื้นที่เพื่อออกาศ / เจ้าหน้าที่ความปลอดภัยระดับหัวหน้างาน



APPROVALS TO PROCEED			
Maintenance by	Maintenance by		
Khun Kittiphan Seekiew	Khun Nardol Seekiew		
Date 23-25/07/2025	Date 23-25/07/2025		



Seekiew.Supply&Service

สีเสียว.สัพพลายแอนด์เซอร์วิส

เลขที่ 710/402 ซอยสุขุมวิท101/1 แขวงบางจาก เขตพระโขนง กรุงเทพฯ 10260 โทร.02-0429889 www.facebook/seekiewsupplyservice

Customer Detail / ข้อมูลลูกค้า			
Project / โครงการ	งานล้างบ่อเก็บน้ำ ปี2025 POI-SAB2505-0044	Name / ชื่อ	โรงแรม รามา แควรี อีตีก กรุงเทพฯ
Location / ที่ตั้ง	41 ซอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า	- 5 -

มาตรการความปลอดภัยในการทำงาน



มาตรการความปลอดภัยเรื่องการปิดกั้นพื้นที่ทำงาน



เจ้าหน้าที่ความปลอดภัย พื้นที่ ตรวจเช็คความพร้อม ชุดอุปกรณ์เรียบร้อย ทั้งทีมงานก่อนปฏิบัติงาน

APPROVALS TO PROCEED			
Maintenance by	Maintenance by		
Khun Kittiphan Seekiew	Khun Narudol Seekiew		
Date 23-25/07/2025	Date 23-25/07/2025		



Seekiew.Supply&Service

สีเสียว.สัพพลายแอนด์เซอร์วิส

เลขที่ 710/402 ซอยสุขุมวิท101/1 แขวงบางจาก เขตพระโขนง กรุงเทพฯ 10260 โทร.02-0429889 www.facebook/seekiewsupplyservice

Customer Detail / ข้อมูลลูกค้า			
Project / โครงการ	งานล้างบ่อเก็บน้ำ ปี2025 POI-SAB2505-0044	Name / ชื่อ	โรงแรม รามา แควรี อีตีก กรุงเทพฯ
Location / ที่ตั้ง	41 ซอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า	- 6 -

ภาพการทำงานทำความสะอาด Underground Tank อาคาร A



APPROVALS TO PROCEED			
Maintenance by	Maintenance by		
Khun Kittiphan Seekiew	Khun Narudol Seekiew		
Date 23-25/07/2025	Date 23-25/07/2025		



Seekiew.Supply&Service

สีเขียว.สัพพลายแอนด์เซอร์วิส

เลขที่ 710/402 ขอขยเสนอวันที่ 10/11 แพรงมางจาก เขตพระโขนง กรุงเทพฯ 10260 โทร.02-04298689 www.facebook/seekiewsupplyservice

Customer Detail / ข้อมูลลูกค้า			
Project / โครงการ	งานจ้างเปิดถนนที่ 212025 POL-SAB2505-0044	Name / ชื่อ	โรงแรม รามา แควรี่ อติกา กรุงเทพฯ
Location / ที่ตั้ง	41 ซอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า	- 7 -

ภาพการทำความสะอาด Underground Tank อาคาร B



APPROVALS TO PROCEED			
Maintenance by	Maintenance by		
Khun Kittiphan Seekiew	Khun Nardol Seekiew		
Date 23-25/07/2025	Date 23-25/07/2025		




Seekiew.Supply&Service

สีเขียว.สัพพลายแอนด์เซอร์วิส

เลขที่ 710/402 ขอขยเสนอวันที่ 10/11 แพรงมางจาก เขตพระโขนง กรุงเทพฯ 10260 โทร.02-0429889 www.facebook/seekiewsupplyservice

Customer Detail / ข้อมูลลูกค้า			
Project / โครงการ	งานจ้างเปิดถนนที่ 212025 POL-SAB2505-0044	Name / ชื่อ	โรงแรม รามา แควรี่ อติกา กรุงเทพฯ
Location / ที่ตั้ง	41 ซอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า	- 8 -

ภาพการทำความสะอาดบ่อ Roof Tank อาคาร B



APPROVALS TO PROCEED			
Maintenance by	Maintenance by		
Khun Kittiphan Seekiew	Khun Nardol Seekiew		
Date 23-25/07/2025	Date 23-25/07/2025		



Seekiew.Supply&Service

สีเขียว.ศัพพลายแอนด์เซอร์วิส

เลขที่ 710/402 ขอขยสูณวริท101/1 แพรวมางจาก เขตพระโขนง กรุงเทพฯ 10260 โทร.02-0429889 www.facebook/seekiewsupplyservice

Customer Detail / ข้อมูลลูกค้า			
Project / โครงการ	งานล้างบ่อเก็บน้ำ ปี 2025 POI-SAB2505-0044	Name / ชื่อ	โรงแรม รามา แควรี่ อโศก กรุงเทพฯ
Location / ที่ตั้ง	41 ซอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า	- 9 -

ภาพการทำความสะอาดบ่อ Roof Tank อาคาร A



APPROVALS TO PROCEED			
Maintenance by	Maintenance by		
Khun Kittiphan Seekiew	Khun Nardol Seekiew		
Date 23-25/07/2025	Date 23-25/07/2025		



Seekiew.Supply&Service

สีเขียว.ศัพพลายแอนด์เซอร์วิส

เลขที่ 710/402 ขอขยสูณวริท101/1 แพรวมางจาก เขตพระโขนง กรุงเทพฯ 10260 โทร.02-0429889 www.facebook/seekiewsupplyservice

Customer Detail / ข้อมูลลูกค้า			
Project / โครงการ	งานล้างบ่อเก็บน้ำ ปี 2025 POI-SAB2505-0044	Name / ชื่อ	โรงแรม รามา แควรี่ อโศก กรุงเทพฯ
Location / ที่ตั้ง	41 ซอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า	- 10 -

ภาพการทำความสะอาดบ่อ Surge Tank สระว่ายนํ้า



APPROVALS TO PROCEED			
Maintenance by	Maintenance by		
Khun Kittiphan Seekiew	Khun Nardol Seekiew		
Date 23-25/07/2025	Date 23-25/07/2025		

Customer Detail / ข้อมูลลูกค้า			
Project / โครงการ	งานจ้างเปลี่ยนถัง 2025 POL-SAB2505-0044	Name / ชื่อ	โรงแรม รามา แคว้น อโศก กรุงเทพฯ
Location / ที่ตั้ง	41 ซอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า	- 11 -

การฆ่าเชื้อโรคด้วย UV-C



คุณภาพอากาศที่เราหายใจ น้ำที่เราดื่ม และความสะดวกสบายของพื้นผิวมีผลอย่างมากต่อสุขภาพและความปลอดภัยของเราทุกคนมีความเสี่ยงต่อการติดเชื้อและแพร่กระจายเชื้อไวรัสและแบคทีเรีย โดยเฉพาะในพื้นที่สาธารณะที่มีผู้คนพลุกพล่าน เช่น สำนักงาน โรงงาน ร้านค้า บาร์หรือร้านอาหาร โรงเรียน พิพิธภัณฑ์ และภายในระบบขนส่งสาธารณะ

รังสี UV-C เป็นที่รู้จักกันดีว่ามีฤทธิ์ในการฆ่าเชื้อสำหรับอากาศ พื้นผิว วัตถุ และน้ำ สามารถช่วยลดความเสี่ยงในการติดเชื้อ และมีการใช้กันอย่างแพร่หลายมานานกว่า 40 ปีแล้ว แบคทีเรียและไวรัสทุกชนิดที่ทำกรทดสอบกับมานานถึงปัจจุบัน (หลายร้อยชนิดในช่วงหลายปีที่ผ่านมา รวมถึงโคโรนาไวรัสสายพันธุ์ต่างๆ) ล้วนตอบสนองต่อการฆ่าเชื้อโรคด้วยรังสี UV-C

ในการทดสอบในห้องปฏิบัติการ แหล่งกำเนิดแสง UV-C ของเรายังใช้รังสี SARS-CoV-2 ได้ 99% บนพื้นผิวที่ได้รับแสงเป็นเวลา 6 วินาที ถือเป็นข้อบ่งชี้ที่ดีเจนว่ารังสี UV-C มีส่วนสำคัญในกลยุทธ์การป้องกันดูแลสุขภาพ

APPROVALS TO PROCEED			
Maintenance by	Maintenance by		
Khun Kittiphan Seekiew	Khun Nandol Seekiew		
Date 23-25/07/2025	Date 23-25/07/2025		

Customer Detail / ข้อมูลลูกค้า			
Project / โครงการ	งานจ้างเปลี่ยนถัง 2025 POL-SAB2505-0044	Name / ชื่อ	โรงแรม รามา แคว้น อโศก กรุงเทพฯ
Location / ที่ตั้ง	41 ซอยสุขุมวิท 16 ถนนสุขุมวิท แขวงคลองเตย เขตคลองเตย กรุงเทพฯ	Page / หน้า	- 12 -

สรุป ข้อบกพร่องที่ควรดำเนินการแก้ไข

ลำดับ	ข้อบกพร่อง	ประเภท		สาเหตุ	ข้อเสนอแนะเพื่อการปรับปรุง
		ร้ายแรง	ไม่ร้ายแรง		
1	บ่อ Underground Tank ควบคุมระดับน้ำอัตโนมัติและไม่สามารถถอดแก้ไขได้นอกจากถอดหัวขาด			เสื่อมสภาพตามอายุการใช้งาน สาเหตุการเสื่อมสภาพเร็วเนื่องจากติดตั้งภายในบ่อมีความชื้นสูงส่งผลต่ออายุการใช้งาน	ควรเร่งดำเนินการเปลี่ยนเนื่องจากส่งผลต่อการเดินน้ำเข้าอาคาร เปลี่ยนใหม่แล้วเลือกวัสดุ นียัต ที่เป็นสแตนเลส 304




APPROVALS TO PROCEED			
Maintenance by	Maintenance by		
Khun Kittiphan Seekiew	Khun Nandol Seekiew		
Date 23-25/07/2025	Date 23-25/07/2025		

ภาคผนวกที่ 19

การล้างทำความสะอาดและฆ่าเชื้อโรคผักบัวภายในห้องพัก

การล้างทำความสะอาดฝักบัวภายในห้องพัก 2026



ภาคผนวกที่ 20

การบำรุงรักษาเครื่องปรับอากาศ



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738975

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HRF-012 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 16/03/2026 - 31/03/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 27/03/2026 08:49		

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date 02/04/2026

2 Asset Code
SAB-HRF-001

3 PPM Of the Quarter
Quarter 1

1 PPM By
Property Engineer

1 Power Supply Status

1 Voltage

1 L1 (V.)

1 Before
398

2 After
398

2 L2 (V.)

1 Before
398

2 After
398

3 L3 (V.)

1 Before
398

2 After
398

2 Current

1 L1 (A.)

1 Before
0

2 After
0

2 L2 (A.)

1 Before
0

2 After
0

3 L3 (A.)

1 Before
0

2 After
0

2 Cable Connector
Tidy

3 Condensing Cleaning
Yes

1 Reference Picture



4 Condensing Casing / Housing Condition
Good

1 Reference Picture




4 Remark and Additional Note
Yes

1 Please Explain
CDU เสียบใบปลิวตอนการเสนอราคาเปลี่ยนใบ

5 Inspection and Record By (Name & Position)

Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
27/03/2026 08:49 - 0 hr and 18 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738976

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HRF-011 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 16/03/2026 - 31/03/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 27/03/2026 10:56		

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date 27/03/2026

2 Asset Code
SAB-HRF-011

3 PPM Of the Quarter
Quarter 1

1 PPM By
Property Engineer

1 Power Supply Status

1 Voltage

1 L1 (V.)

1 Before
398

2 After
398

2 L2 (V.)

1 Before
398

2 After
398

3 L3 (V.)

1 Before
398

2 After
398

2 Current

1 L1 (A.)

1 Before
12

2 After
12

2 L2 (A.)

1 Before
12

2 After
11

3 L3 (A.)

1 Before
11

2 After
10

2 Cable Connector
Tidy

3 Condensing Cleaning
Yes

1 Reference Picture



4 Condensing Casing / Housing Condition
Good

1 Reference Picture



4 Remark and Additional Note
No

5 Inspection and Record By (Name & Position)

Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
27/03/2026 10:56 - 0 hr and 2 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738977

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HRF-010 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 16/03/2026 - 31/03/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 27/03/2026 10:54		

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date 27/03/2026
2 Asset Code
SAB-HRF-010
3 PPM Of the Quarter
Quarter 1
1 PPM By
Property Engineer
1 Power Supply Status
1 Voltage
1 L1 (V.)
1 Before
398
2 After
398
2 L2 (V.)
1 Before
398
2 After
398
3 L3 (V.)
1 Before
398
2 After
398
2 Current
1 L1 (A.)
1 Before
0
2 After
0
2 L2 (A.)

1 Before
0
2 After
0
3 L3 (A.)
1 Before
0
2 After
0
2 Cable Connector
Tidy
3 Condensing Cleaning
Yes
1 Reference Picture
4 Condensing Casing / Housing Condition
Good
1 Reference Picture
4 Remark and Additional Note
No
5 Inspection and Record By (Name & Position)
Manop
6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
27/03/2026 10:54 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738978


Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HRF-009 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 16/03/2026 - 31/03/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 27/03/2026 10:52		

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date 27/03/2026
2 Asset Code
SAB-HRF-009
3 PPM Of the Quarter
Quarter 1
1 PPM By
Property Engineer
1 Power Supply Status
1 Voltage
1 L1 (V.)
1 Before
398
2 After
398
2 L2 (V.)
1 Before
398
2 After
398
3 L3 (V.)
1 Before
398
2 After
398
2 Current
1 L1 (A.)
1 Before
0
2 After
0
2 L2 (A.)

1 Before
0
2 After
0
3 L3 (A.)
1 Before
0
2 After
0
2 Cable Connector
Tidy
3 Condensing Cleaning
Yes
1 Reference Picture
4 Condensing Casing / Housing Condition
Good
1 Reference Picture
4 Remark and Additional Note
Yes
1 Please Explain
ชุด CDU เลือกลงใบขออนุมัติการเสนอราคาเปลี่ยนใหม่
5 Inspection and Record By (Name & Position)
Manop
6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
27/03/2026 10:52 - 0 hr and 4 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738979

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HRF-008 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 16/03/2026 - 31/03/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 27/03/2026 10:47		

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date27/03/2026

2 Asset Code
SAB-HRF-008

3 PPM Of the Quarter
Quarter 1

1 PPM By
Property Engineer

1 Power Supply Status

1 Voltage

1 L1 (V.)

1 Before
398

2 After
398

2 L2 (V.)

1 Before
398

2 After
398

3 L3 (V.)

1 Before
398

2 After
398

2 Current

1 L1 (A.)

1 Before
0

2 After
0

2 L2 (A.)

1 Before
0

2 After
0

3 L3 (A.)

1 Before
0

2 After
0

2 Cable Connector
Tidy

3 Condensing Cleaning
Yes

1 Reference Picture



4 Condensing Casing / Housing Condition
Good

1 Reference Picture



4 Remark and Additional Note
Yes

1 Please Explain
ชุด CDU เลือกลงไปชั้นดอจนเสนอราคาเปลี่ยนชุดใหม่

5 Inspection and Record By (Name & Position)
Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
27/03/2026 10:47 - 0 hr and 6 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738980

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HRF-007 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 16/03/2026 - 31/03/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 27/03/2026 10:40		

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date27/03/2026

2 Asset Code
SAB-HRF-007

3 PPM Of the Quarter
Quarter 1

1 PPM By
Property Engineer

1 Power Supply Status

1 Voltage

1 L1 (V.)

1 Before
3968

2 After
398

2 L2 (V.)

1 Before
398

2 After
398

3 L3 (V.)

1 Before
398

2 After
398

2 Current

1 L1 (A.)

1 Before
0

2 After
0

2 L2 (A.)

1 Before
0

2 After
0

3 L3 (A.)

1 Before
0

2 After
0

2 Cable Connector
Tidy

3 Condensing Cleaning
Yes

1 Reference Picture



4 Condensing Casing / Housing Condition
Good

1 Reference Picture



4 Remark and Additional Note
Yes

1 Please Explain
ชุด CDU เลือกลงไปชั้นดอจนเสนอราคาเปลี่ยนใหม่

5 Inspection and Record By (Name & Position)
Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
27/03/2026 10:40 - 0 hr and 4 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738981

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HRF-006 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 16/03/2026 - 31/03/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 27/03/2026 10:36		

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date 27/03/2026

2 Asset Code
SAB-HRF-006

3 PPM Of the Quarter
Quarter 1

1 PPM By
Property Engineer

1 Power Supply Status

1 Voltage

1 L1 (V.)

1 Before
398

2 After
398

2 L2 (V.)

1 Before
398

2 After
398

3 L3 (V.)

1 Before
398

2 After
398

2 Current

1 L1 (A.)

1 Before
0

2 After
0

2 L2 (A.)

1 Before
0

2 After
0

3 L3 (A.)

1 Before
0

2 After
0

2 Cable Connector
Tidy

3 Condensing Cleaning
Yes



4 Condensing Casing / Housing Condition
Good



4 Remark and Additional Note
Yes

1 Please Explain
ชุด CDU เลือกลงใบแจ้งซ่อมการสนนราคาเปลี่ยนใหม่

5 Inspection and Record By (Name & Position)
Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
27/03/2026 10:36 - 0 hr and 6 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738982

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HRF-005 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 16/03/2026 - 31/03/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 27/03/2026 10:30		

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date 27/03/2026

2 Asset Code
SAB-HRF-005

3 PPM Of the Quarter
Quarter 1

1 PPM By
Property Engineer

1 Power Supply Status

1 Voltage

1 L1 (V.)

1 Before
398

2 After
398

2 L2 (V.)

1 Before
398

2 After
398

3 L3 (V.)

1 Before
398

2 After
398

2 Current

1 L1 (A.)

1 Before
0

2 After
0

2 L2 (A.)

1 Before
0

2 After
0

3 L3 (A.)

1 Before
0

2 After
0

2 Cable Connector
Tidy

3 Condensing Cleaning
Yes



4 Condensing Casing / Housing Condition
Good




4 Remark and Additional Note
Yes

1 Please Explain
ชุด CDU เลือกลงใบระหว่างสนนราคาเปลี่ยนใหม่

5 Inspection and Record By (Name & Position)
Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT
27/03/2026 10:30 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738983

Status Completed	Priority 4 Quarterly Jobs	Type 🔧 PM	Asset SAB-HRF-004 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 📅 16/03/2026 - 31/03/2026	Downtime 🕒 0 hr and 0 min	Location 📍 SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 📅 27/03/2026 10:24		

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

- 1 Date03/04/2026
- 2 Asset Code
SAB-HRF-004
- 3 PPM Of the Quarter

Quarter 2
- 1 PPM By

Property Engineer
- 1 Power Supply Status
 - 1 Voltage
 - 1 L1 (V.)
 - 1 Before
398
 - 2 After
398
 - 2 L2 (V.)
 - 1 Before
398
 - 2 After
398
 - 3 L3 (V.)
 - 1 Before
398
 - 2 After
398
 - 2 Current
 - 1 L1 (A.)
 - 1 Before
0
 - 2 After
0
 - 2 L2 (A.)

27/03/2026 10:24 - 0 hr and 6 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

- 1 Before
0
- 2 After
0
- 3 L3 (A.)
 - 1 Before
0
 - 2 After
0
- 2 Cable Connector


Tidy
- 3 Condensing Cleaning

Yes
- 1 Reference Picture
- 4 Condensing Casing / Housing Condition

Good
- 1 Reference Picture
- 2 Efficiency Check / Computer Checker Report

No
- 4 Remark and Additional Note

Yes
- 1 Please Explain
ชุด CDU เลื่อนอยู่ในขั้นตอนการเสนอราคาเปลี่ยนใหม่
- 5 Inspection and Record By (Name & Position)
Manop
- 6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



TIME SPENT



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738984

Status Completed	Priority 4 Quarterly Jobs	Type 🔧 PM	Asset SAB-HRF-003 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 📅 16/03/2026 - 31/03/2026	Downtime 🕒 0 hr and 0 min	Location 📍 SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 📅 27/03/2026 09:03		

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

- 1 Date27/03/2026
- 2 Asset Code
SAB-HRF-003
- 3 PPM Of the Quarter

Quarter 1
- 1 PPM By

Property Engineer
- 1 Power Supply Status
 - 1 Voltage
 - 1 L1 (V.)
 - 1 Before
398
 - 2 After
398
 - 2 L2 (V.)
 - 1 Before
398
 - 2 After
398
 - 3 L3 (V.)
 - 1 Before
398
 - 2 After
398
 - 2 Current
 - 1 L1 (A.)
 - 1 Before
0
 - 2 After
0
 - 2 L2 (A.)

1 Before _____
0 _____

2 After _____
0 _____

3 L3 (A.) _____
1 Before _____
0 _____
2 After _____
0 _____

2 Cable Connector

Tidy

3 Condensing Cleaning

Yes


1 Reference Picture



4 Condensing Casing / Housing Condition

Good

1 Reference Picture



4 Remark and Additional Note

Yes

1 Please Explain
ขอ CDU เชื่อมกับใบรับคองการเสนอราคาไปเขียนใหม่

5 Inspection and Record By (Name & Position)
Nanop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

2023/03/26 09:03 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Wisit

1 Before
0

2 After
0

3 L3 (A.)
1 Before
0

2 After
0

2 Cable Connector

Tidy

3 Condensing Cleaning

Yes

1 Reference Picture



4 Condensing Casing / Housing Condition

Good

1 Reference Picture



4 Remark and Additional Note

Yes

1 Please Explain

ชุด CDU เชื้ออยู่ในขั้นตอนการเสนอราคาเปลี่ยน

5 Inspection and Record By (Name & Position)

Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

27/03/2026 08:59 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

27/03/2026 08:59 10 hr and 6 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

🔧 ONYX_ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738985

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HRF-002 > ENG 25-01 VRV/VRf Air Conditioning Asset Register > ENG 25 VRV/VRf Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 16/03/2026 - 31/03/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 27/03/2026 08:59		

DESCRIPTION

@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

2 Date 27/03/2025

2 Asset Code
SAB-HFC-002

3 PPM of the Quarter

Quarter 1

1 PPM By

Property Engineer

1 Power Supply Status

1 Voltage

1 L1 (V.)

1 Before
398

2 After

398

2 L2 (V.)

1 Before
398

2 After

398

3 L3 (V.)

1 Before
398

2 After

398

2 Current

1 L1 (A.)

1 Before
0

2 After

0

2 L2 (A.)

🔧 ONYX_ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #738986

Status Completed	Priority 4 Quarterly Jobs	Type PM	Asset SAB-HRF-001 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering
Assigned to SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer	Due Date 16/03/2026 - 31/03/2026	Downtime 0 hr and 0 min	Location SAB (Shama Lakeview Asoke Bangkok)
Completed By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering	Completed Date 27/03/2026 08:52		

DESCRIPTION

@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date 26/03/2025

2 Asset Code
SAB-HRF-001

3 PPM Of the Quarter
Quarter 1

1 PPM By
Property Engineer

1 Power Supply Status

1 Voltage

1 L1 (V.)
1 Before
398

2 After
398

2 L2 (V.)
1 Before
398

2 After
398

3 L3 (V.)
1 Before
398

2 After
398

2 Current

1 L1 (A.)
1 Before
0

2 After
0

2 L2 (A.)

1 Before

0

2 After

0

3 L3 (A.)

1 Before

0

2 After

0

2 Cable Connector

Tidy

3 Condensing Cleaning

Yes

1 Reference Picture



4 Condensing Casing / Housing Condition

Good

1 Reference Picture



4 Remark and Additional Note

Yes

1 Please Explain

ชุด CDU เชื้ออยู่ใกล้ขั้นตอนการเสนอค่าเปลี่ยนชุดใหม่

5 Inspection and Record By (Name & Position)

Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Wisit

27/03/2026 08:52 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

27/03/2026 08:52 - 0 hr and 2 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

ONYX

SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888472

👤 Status

Completed

📅 Priority

4 Quarterly Jobs

🔧 Type

PM

🏠 Asset

SAB-HRF-012 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering

👤 Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

📅 Due Date

16/06/2026

🕒 Downtime

0 hr and 0 min

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

📅 Completed Date

12/06/2026 16:02

DESCRIPTION

@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date

12/06/2026

2 Asset Code

SAB-HRF-012

3 PPM Of the Quarter

Quarter 2

1 PPM By

Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report

Yes

1 Report Upload for Reference

4 Remark and Additional Note

Yes

1 Please Explain

อยู่ใกล้ขั้นตอนเปลี่ยนระบบ VRV ชุดใหม่

5 Inspection and Record By (Name & Position)

Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chann

12/06/2026 16:02 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT

12/06/2026 16:02 - 0 hr and 1 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS

ONYX

SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888473

👤 Status

Completed

📅 Priority

4 Quarterly Jobs

🔧 Type

PM

🏠 Asset

SAB-HRF-011 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering

👤 Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

📅 Due Date

16/06/2026

🕒 Downtime

0 hr and 0 min

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

📅 Completed Date

12/06/2026 10:13

DESCRIPTION

@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date

11/06/2026

2 Asset Code

SAB-HRF-011

3 PPM Of the Quarter

Quarter 2

1 PPM By

Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report

Yes

1 Report Upload for Reference

4 Remark and Additional Note

Yes

1 Please Explain

อยู่ใกล้ขั้นตอนเปลี่ยนระบบ VRV ชุดใหม่

5 Inspection and Record By (Name & Position)

Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

12/06/2026 10:13 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:13 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888474

👤 Status
Completed

📅 Priority
4 Quarterly Jobs

🔧 Type
PM

🏠 Asset
SAB-HRF-010 > ENG 25-01
VRV/VRF Air Conditioning Asset
Register > ENG 25 VRV/VRF Air
Conditioning > 4. SAB Engineering

👤 Assigned to
SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering,
SAB (Shama Lakeview Asoke
Bangkok) 2.Operation & Preventive
Maintenance Engineer

📅 Due Date
16/06/2026

🕒 Downtime
0 hr and 0 min

🏠 Location
SAB (Shama Lakeview Asoke
Bangkok)

👤 Completed By
SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering

📅 Completed Date
12/06/2026 10:14

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date11/06/2026

2 Asset Code
SAB-HRF-010

3 PPM Of the Quarter
Quarter 2

1 PPM By
Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report
Yes

1 Report Upload for Reference

4 Remark and Additional Note
Yes

1 Please Explain
อุปกรณ์ตรวจสอบประสิทธิภาพของ VRV ชุดใหญ่

5 Inspection and Record By (Name & Position)
Manop TL

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

12/06/2026 10:14 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:14 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888475

👤 Status
Completed

📅 Priority
4 Quarterly Jobs

🔧 Type
PM

🏠 Asset
SAB-HRF-009 > ENG 25-01
VRV/VRF Air Conditioning Asset
Register > ENG 25 VRV/VRF Air
Conditioning > 4. SAB Engineering

👤 Assigned to
SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering,
SAB (Shama Lakeview Asoke
Bangkok) 2.Operation & Preventive
Maintenance Engineer

📅 Due Date
16/06/2026

🕒 Downtime
0 hr and 0 min

🏠 Location
SAB (Shama Lakeview Asoke
Bangkok)

👤 Completed By
SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering

📅 Completed Date
12/06/2026 10:14

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date11/06/2026

2 Asset Code
SAB-HRF-009

3 PPM Of the Quarter
Quarter 2

1 PPM By
Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report
Yes

1 Report Upload for Reference

4 Remark and Additional Note
Yes

1 Please Explain
อุปกรณ์ตรวจสอบประสิทธิภาพของ VRV ชุดใหญ่

5 Inspection and Record By (Name & Position)
Manop TL

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

12/06/2026 10:14 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:14 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888476

👤 Status

Completed

📅 Priority

4 Quarterly Jobs

🔧 Type

🔧 PM

🏠 Asset

SAB-HRF-008 > ENG 25-01
VRV/VRF Air Conditioning Asset
Register > ENG 25 VRV/VRF Air
Conditioning > 4. SAB Engineering

👤 Assigned to

SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering,
SAB (Shama Lakeview Asoke
Bangkok) 2.Operation & Preventive
Maintenance Engineer

📅 Due Date

16/06/2026

🕒 Downtime

0 hr and 0 min

🏠 Location

SAB (Shama Lakeview Asoke
Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering

📅 Completed Date

12/06/2026 10:15

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date11/06/2026

2 Asset Code
SAB-HRF-008

3 PPM Of the Quarter
Quarter 2

1 PPM By
Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report
Yes

1 Report Upload for Reference

4 Remark and Additional Note
Yes

1 Please Explain
อุปกรณ์ตรวจสอบประสิทธิภาพของ VRV ชุดใหม่

5 Inspection and Record By (Name & Position)
Manop TL

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

12/06/2026 10:15 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:15 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888477

👤 Status

Completed

📅 Priority

4 Quarterly Jobs

🔧 Type

🔧 PM

🏠 Asset

SAB-HRF-007 > ENG 25-01
VRV/VRF Air Conditioning Asset
Register > ENG 25 VRV/VRF Air
Conditioning > 4. SAB Engineering

👤 Assigned to

SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering,
SAB (Shama Lakeview Asoke
Bangkok) 2.Operation & Preventive
Maintenance Engineer

📅 Due Date

16/06/2026

🕒 Downtime

0 hr and 0 min

🏠 Location

SAB (Shama Lakeview Asoke
Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering

📅 Completed Date

12/06/2026 10:15

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date11/06/2026

2 Asset Code
SAB-HRF-007

3 PPM Of the Quarter
Quarter 2

1 PPM By
Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report
Yes

1 Report Upload for Reference

4 Remark and Additional Note
Yes

1 Please Explain
อุปกรณ์ตรวจสอบประสิทธิภาพของ VRV ชุดใหม่

5 Inspection and Record By (Name & Position)
Manop TL

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

12/06/2026 10:15 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:15 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888478

Status

Completed

Priority

4 Quarterly Jobs

Type

🔧 PM

Asset

SAB-HRF-006 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering

Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date

16/06/2026

Downtime

0 hr and 0 min

Location

SAB (Shama Lakeview Asoke Bangkok)

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date

12/06/2026 10:15

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date18/06/2026

2 Asset Code
SAB-HRF-006

3 PPM Of the Quarter
Quarter 2

1 PPM By
Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report
Yes

1 Report Upload for Reference

4 Remark and Additional Note
Yes

1 Please Explain
อุปกรณ์ตรวจสอบประสิทธิภาพระบบ VRV ชุดใหม่

5 Inspection and Record By (Name & Position)
Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

12/06/2026 10:15 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:15 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888479

Status

Completed

Priority

4 Quarterly Jobs

Type

🔧 PM

Asset

SAB-HRF-005 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering

Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

Due Date

16/06/2026

Downtime

0 hr and 0 min

Location

SAB (Shama Lakeview Asoke Bangkok)

Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

Completed Date

12/06/2026 10:16

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date11/06/2026

2 Asset Code
SAB-HRF-005

3 PPM Of the Quarter
Quarter 2

1 PPM By
Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report
No

4 Remark and Additional Note
Yes

1 Please Explain
อุปกรณ์ตรวจสอบประสิทธิภาพระบบ VRV ชุดใหม่

5 Inspection and Record By (Name & Position)
Manop TL

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

12/06/2026 10:16 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:16 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888480

👤 Status

Completed

📅 Priority

4 Quarterly Jobs

🔧 Type

🔧 PM

🏠 Asset

SAB-HRF-004 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering

👤 Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

📅 Due Date

16/06/2026

🕒 Downtime

0 hr and 0 min

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

📅 Completed Date

12/06/2026 10:16

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date11/06/2026

2 Asset Code
SAB-HRF-004

3 PPM Of the Quarter
Quarter 2

1 PPM By
Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report
Yes

1 Report Upload for Reference

4 Remark and Additional Note
Yes

1 Please Explain
อุปกรณ์ตรวจสอบประสิทธิภาพของ VRV ชุดใหม่

5 Inspection and Record By (Name & Position)
Manop

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

12/06/2026 10:16 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:16 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888481

👤 Status

Completed

📅 Priority

4 Quarterly Jobs

🔧 Type

🔧 PM

🏠 Asset

SAB-HRF-003 > ENG 25-01 VRV/VRF Air Conditioning Asset Register > ENG 25 VRV/VRF Air Conditioning > 4. SAB Engineering

👤 Assigned to

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering, SAB (Shama Lakeview Asoke Bangkok) 2.Operation & Preventive Maintenance Engineer

📅 Due Date

16/06/2026

🕒 Downtime

0 hr and 0 min

🏠 Location

SAB (Shama Lakeview Asoke Bangkok)

👤 Completed By

SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

📅 Completed Date

12/06/2026 10:16

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date11/06/2026

2 Asset Code
SAB-HGF-003

3 PPM Of the Quarter
Quarter 2

1 PPM By
Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report
Yes

1 Report Upload for Reference

4 Remark and Additional Note
Yes

1 Please Explain
อุปกรณ์ตรวจสอบประสิทธิภาพของ VRV ชุดใหม่

5 Inspection and Record By (Name & Position)
Manop TL

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

12/06/2026 10:16 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:16 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888482

👤 Status
Completed

📅 Priority
4 Quarterly Jobs

🔧 Type
PM

🏠 Asset
SAB-HRF-002 > ENG 25-01
VRV/VRF Air Conditioning Asset
Register > ENG 25 VRV/VRF Air
Conditioning > 4. SAB Engineering

👤 Assigned to
SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering,
SAB (Shama Lakeview Asoke
Bangkok) 2.Operation & Preventive
Maintenance Engineer

📅 Due Date
16/06/2026

🕒 Downtime
0 hr and 0 min

🏠 Location
SAB (Shama Lakeview Asoke
Bangkok)

👤 Completed By
SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering

📅 Completed Date
12/06/2026 10:17

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date11/06/2026

2 Asset Code
SAB-HFC-002

3 PPM Of the Quarter
Quarter 2

1 PPM By
Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report
No

4 Remark and Additional Note
Yes

1 Please Explain
อุปกรณ์ต้องเปลี่ยนระบบ VRV ชุดใหม่

5 Inspection and Record By (Name & Position)
Manop TL

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved

Chamm.

12/06/2026 10:17 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:17 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

COMMENTS



SAB (Shama Lakeview Asoke Bangkok)

🔧 ONYX _ENG 25-03 Quarter PPM VRV/VRF Air Conditioning -SAB - #888483

👤 Status
Completed

📅 Priority
4 Quarterly Jobs

🔧 Type
PM

🏠 Asset
SAB-HRF-001 > ENG 25-01
VRV/VRF Air Conditioning Asset
Register > ENG 25 VRV/VRF Air
Conditioning > 4. SAB Engineering

👤 Assigned to
SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering,
SAB (Shama Lakeview Asoke
Bangkok) 2.Operation & Preventive
Maintenance Engineer

📅 Due Date
16/06/2026

🕒 Downtime
0 hr and 0 min

🏠 Location
SAB (Shama Lakeview Asoke
Bangkok)

👤 Completed By
SAB (Shama Lakeview Asoke
Bangkok) 1.Manager Engineering

📅 Completed Date
12/06/2026 10:17

DESCRIPTION
@Engineering Standard; @ENG 25-03;

INSTRUCTIONS

1 Date11/06/2026

2 Asset Code
SAB-HRF-001

3 PPM Of the Quarter
Quarter 2

1 PPM By
Contractor / Out Sour

1 Report Upload for Reference

2 Efficiency Check / Computer Checker Report
Yes

1 Report Upload for Reference

4 Remark and Additional Note
Yes

1 Please Explain
อุปกรณ์ต้องเปลี่ยนระบบ VRV ชุดใหม่

5 Inspection and Record By (Name & Position)
Manop TL

6 SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering successfully approved



12/06/2026 10:17 By SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering

TIME SPENT
12/06/2026 10:17 - 0 hr and 5 min by SAB (Shama Lakeview Asoke Bangkok) 1.Manager Engineering
COMMENTS

ภาคผนวกที่ 21

การตรวจสอบค่าคลอรีนอิสระตกค้างในถังพักน้ำ


Test Chlorine Roof tank Tower A&B 5 January 2026



Test Chlorine Roof tank Tower A&B 20 January 2026




Test Chlorine Roof tank Tower A&B 5 February 2026



Test Chlorine Roof tank Tower A&B 20 February 2026




Test Chlorine Roof tank Tower A&B 5 March 2026




Test Chlorine Roof tank Tower A&B 20 March 2026




Test Chlorine Roof tank Tower A&B 5 April 2026




Test Chlorine Roof tank Tower A&B 20 April 2026



Test Chlorine Roof tank Tower A&B 5 May 2026



Test Chlorine Roof tank Tower A&B 20 May 2026



Test Chlorine Roof tank Tower A&B
5 June 2026



Test Chlorine Roof tank Tower A&B
20 June 2026

