

ภาคผนวกที่ 1

สำเนาหนังสือเห็นชอบรายงานการวิเคราะห์ผลกระทบสิ่งแวดล้อม

ภาคผนวกที่ 2

สำเนาใบอนุญาตประกอบธุรกิจโรงแรม



ทะเบียนเลขที่.....๙๗๖.....

ใบอนุญาตเลขที่.....๑๘๕/๒๕๖๒

กระทรวงมหาดไทย

ใบอนุญาตประกอบธุรกิจโรงแรม

ใบอนุญาตฉบับนี้ให้ไว้เพื่อแสดงว่าบริษัท เอเอ็มเอช รัชดา จำกัด.....
.....โดย นายจักรกฤษณ์ เตชะวณิช.....
ได้รับอนุญาตให้ประกอบธุรกิจโรงแรมตามมาตรา ๑๕ แห่งพระราชบัญญัติ
โรงแรม พ.ศ. ๒๕๔๗ โดยใช้ชื่อภาษาไทยว่าโรงแรม ซัมเมอร์เซ็ท ราชมาไนน์ แบงค็อก.....
.....
ชื่อภาษาต่างประเทศ (ถ้ามี).....SOMERSET RAMA 9 BANGKOK.....
โรงแรมประเภท.....๓..... จำนวนห้องพัก.....๔๔๕..... ห้อง
สถานที่ตั้งเลขที่ ๒๒ ถนนรัชดาภิเษก แขวงห้วยขวาง.....
.....เขตห้วยขวาง กรุงเทพมหานคร.....
ตั้งแต่วันที่ ๑๘ เดือน ธันวาคม พ.ศ. ๒๕๖๒ ถึง วันที่ ๑๗ เดือน ธันวาคม พ.ศ. ๒๕๖๗

ออกให้ ณ วันที่ ๑๘ เดือน ธันวาคม พ.ศ. ๒๕๖๒



ปลัดกระทรวงมหาดไทย

ภาคผนวกที่ 3

สำเนาใบรายงานผลการตรวจวัดคุณภาพสิ่งแวดล้อม

สำเนาใบรายงานผลการวิเคราะห์น้ำ - ระบบบำบัดน้ำเสีย

สำเนาใบรายงานผลการวิเคราะห์น้ำ - สระว่ายน้ำ

สำเนาใบรายงานผลการวิเคราะห์หน้า - ลีจีโอแนลลา แบคทีเรีย

สำเนาใบรายงานผลการวิเคราะห์น้ำ - น้ำใช้ และ น้ำดื่ม

สำเนาเอกสารขึ้นทะเบียนห้องปฏิบัติการวิเคราะห์เอกชน

ที่ อก ๐๓๑๓/ ๑๗๑๕๒



กรมโรงงานอุตสาหกรรม
ถนนพระรามที่ ๖ แขวงทุ่งพญาไท
เขตราชเทวี กรุงเทพฯ ๑๐๕๐๐

๑๕ ธันวาคม ๒๕๖๖

เรื่อง หนังสือรับรองการขึ้นทะเบียนผู้ควบคุมระบบบำบัดมลพิษ ประเภทบริษัทที่ปรึกษา

เรียน กรรมการผู้จัดการ บริษัท วนาดล จำกัด

อ้างถึง คำขอเลขที่ ๑๖๔๖ ลงรับวันที่ ๑๕ ธันวาคม ๒๕๖๖

ตามคำขอที่อ้างถึง ท่านขอต่ออายุผู้ควบคุมระบบบำบัดมลพิษ ประเภทบริษัทที่ปรึกษา ของ บริษัท วนาดล จำกัด ตั้งอยู่ ณ เลขที่ ๒/๒๕ ถนนวัดเวฬุวนาราม แขวงดอนเมือง เขตดอนเมือง กรุงเทพมหานคร โทรศัพท์ ๐ ๒๕๖๕ ๔๔๐๖ ความละเอียดแจ้งแล้ว นั้น

กรมโรงงานอุตสาหกรรมพิจารณาแล้วอนุญาตให้ขึ้นทะเบียนเป็นผู้ควบคุมระบบบำบัดมลพิษ ประเภทบริษัทที่ปรึกษา เลขทะเบียน บ.๑๐๐-๔๘-๐๑๙ โดยให้หนังสือรับรองการขึ้นทะเบียนฉบับนี้สิ้นสุดอายุ ในวันที่ ๒๕ ธันวาคม ๒๕๖๙ และมีบุคลากรดังนี้

ผู้ควบคุมระบบบำบัดมลพิษน้ำ

ลำดับ	ชื่อ - สกุล	ทะเบียนผู้ควบคุมฯ ประเภทบุคคล
๑	น. [REDACTED]	[REDACTED]
๒	น. [REDACTED]	[REDACTED]

หมายเหตุ การรับจ้างเป็นผู้ควบคุมระบบบำบัดมลพิษให้กับโรงงาน หรือการต่ออายุ/ยกเลิก/เพิ่มเติม/เปลี่ยนแปลง บุคลากร ต้องส่งหนังสือฉบับนี้มาด้วย

จึงเรียนมาเพื่อโปรดทราบ

ขอแสดงความนับถือ



(นางสาว [REDACTED])

ผู้อำนวยการกองส่งเสริมเทคโนโลยีสิ่งแวดล้อมโรงงาน
ปฏิบัติราชการแทนอธิบดีกรมโรงงานอุตสาหกรรม

กองส่งเสริมเทคโนโลยีสิ่งแวดล้อมโรงงาน

กลุ่มกำกับบุคลากรด้านสิ่งแวดล้อมประจำโรงงาน

โทรศัพท์ ๐ ๒๔๓๐ ๖๓๑๕ ต่อ ๒๔๐๕

โทรสาร ๐ ๒๔๓๐ ๖๓๑๕ ต่อ ๒๔๙๙

ไปรษณีย์อิเล็กทรอนิกส์ saraban@diw.mail.go.th



ที่ อก ๐๓๑๐(๑)/ ๕๓๖๒



กรมโรงงานอุตสาหกรรม
ถนนพระรามที่ ๖ แขวงทุ่งพญาไท
เขตราชเทวี กรุงเทพฯ ๑๐๕๐๐

๐ ๕ มิถุนายน ๒๕๖๗

เรื่อง ต่ออายุหนังสือรับขึ้นทะเบียนห้องปฏิบัติการวิเคราะห์เอกซน

เรียน กรรมการผู้จัดการ บริษัท เอ็นไวรอนเม้นท์ แอนด์ แลบลอราตอรี จำกัด

อ้างถึง คำขอขึ้นทะเบียน/ต่ออายุ/เปลี่ยนแปลงบุคลากร และชนิดสารมลพิษของห้องปฏิบัติการวิเคราะห์เอกซน
ลงวันที่ ๑๐ เมษายน ๒๕๖๗

สิ่งที่ส่งมาด้วย เอกสารแนบท้ายหนังสือต่ออายุรับขึ้นทะเบียนห้องปฏิบัติการวิเคราะห์เอกซน
บริษัท เอ็นไวรอนเม้นท์ แอนด์ แลบลอราตอรี จำกัด จำนวน ๒ แผ่น

ตามคำขอที่อ้างถึง บริษัท เอ็นไวรอนเม้นท์ แอนด์ แลบลอราตอรี จำกัด ขอต่ออายุหนังสือรับขึ้น
ทะเบียนห้องปฏิบัติการวิเคราะห์เอกซน เลขทะเบียน ว-๐๒๙ สถานที่ตั้งเลขที่ ๔๐ ซอยเลี้ยวเมืองนนทบุรี ๑๓
ตำบลตลาดขวัญ อำเภอเมืองนนทบุรี จังหวัดนนทบุรี ต่อกรมโรงงานอุตสาหกรรม นั้น

กรมโรงงานอุตสาหกรรมพิจารณาแล้ว ให้บริษัท เอ็นไวรอนเม้นท์ แอนด์ แลบลอราตอรี จำกัด ต่ออายุ
หนังสือรับขึ้นทะเบียนห้องปฏิบัติการวิเคราะห์เอกซน โดยมีองค์ประกอบดังนี้

ก. ผู้ควบคุมห้องปฏิบัติการวิเคราะห์เอกซน

๑)

๒)

๓)

๔)

ข. เจ้า

๑)

๒)

๓)

๔)

๕)

๖)

๗)

๘)

๙)

๑๐

๑๑

ค. ขอบข่ายชนิดสารมลพิษที่ได้รับขึ้นทะเบียนให้วิเคราะห์ในน้ำ/น้ำเสีย ตามสิ่งที่ส่งมาด้วย

หนังสือฉบับนี้...

หนังสือฉบับนี้จะหมดอายุในวันที่ ๑๘ เมษายน ๒๕๖๑ หากประสงค์จะต่ออายุหนังสือรับขึ้นทะเบียนห้องปฏิบัติการวิเคราะห์เอกชน ให้ยื่นคำขอต่ออายุพร้อมเอกสารประกอบคำขอต่อกรมโรงงานอุตสาหกรรมภายใน ๖๐ วัน ก่อนวันสิ้นอายุของหนังสือรับขึ้นทะเบียนห้องปฏิบัติการวิเคราะห์เอกชน

จึงเรียนมาเพื่อทราบ

ขอแสดงความนับถือ

(นาย 
รองอธิบดี ปฏิบัติราชการแทน
อธิบดีกรมโรงงานอุตสาหกรรม

กองวิจัยและเตือนภัยมลพิษโรงงาน

กลุ่มมาตรฐานวิธีการวิเคราะห์ทดสอบมลพิษและทะเบียนห้องปฏิบัติการ

โทร. ๐ ๒๔๓๐ ๖๓๑๒ ต่อ ๒๑๐๓-๕

โทรสาร ๐ ๒๔๓๐ ๖๓๑๒ ต่อ ๒๑๙๙

ไปรษณีย์อิเล็กทรอนิกส์ saraban@diw.mail.go.th



เอกสารแนบท้ายหนังสือต่ออายุรับขึ้นทะเบียนห้องปฏิบัติการวิเคราะห์เอกชน

บริษัท เอ็นไวรอนเม้นท์ แอนด์ แลบลอราตอรี จำกัด

เลขทะเบียน ว-๐๒๙

ที่ อก ๐๓๑๐(๑)/ ๕๓๖๒

ลงวันที่ ๐๔ มิถุนายน ๒๕๖๗

ขอขยายสารมลพิษที่ได้รับขึ้นทะเบียนจากกรมโรงงานอุตสาหกรรม จำนวน ๒๖ รายการ

น้ำ/น้ำเสีย จำนวน 26 รายการ

ลำดับที่	สารมลพิษ	วิธีวิเคราะห์
1	Arsenic	1) Digestion, Hydride Generation/Atomic Absorption Spectrometric Method ^[2]
2	Barium	2) Digestion, Inductively Coupled Plasma Method ^[2]
3	Biochemical Oxygen Demand	Digestion, Inductively Coupled Plasma Method ^[2]
4	Cadmium	1) 5-Day BOD Test, Azide Modification Method ^[2]
5	Chemical Oxygen Demand	2) 5-Day BOD Test, Membrane Electrode Method ^[2]
6	Color	1) Digestion, Direct Air-Acetylene Flame Method ^[2]
7	Copper	2) Digestion, Inductively Coupled Plasma Method ^[2]
8	Cyanide	1) Digestion, Direct Air-Acetylene Flame Method ^[2]
9	Formaldehyde	2) Digestion, Inductively Coupled Plasma Method ^[2]
10	Free Chlorine	Closed Reflux, Titrimetric Method ^[2]
11	Hexavalent Chromium	ADMI Weighted-Ordinate Spectrophotometric Method ^[2]
12	Lead	1) Digestion, Direct Air-Acetylene Flame Method ^[2]
13	Manganese	2) Digestion, Inductively Coupled Plasma Method ^[2]
14	Mercury	1) Digestion, Direct Air-Acetylene Flame Method ^[2]
15	Nickel	2) Digestion, Inductively Coupled Plasma Method ^[2]
16	Oil & Grease	Digestion, Cold-Vapor Atomic Absorption Spectrometric Method ^[2]
17	pH	1) Digestion, Direct Air-Acetylene Flame Method ^[2]
18	Phenols	2) Digestion, Inductively Coupled Plasma Method ^[2]
		1) Liquid-Liquid, Partition-Gravimetric Method ^[2]
		2) Soxhlet Extraction Method ^[2]
		Electrometric Method ^[2]
		Distillation, Direct Photometric Method ^[2]

ลำดับที่	สารมลพิษ	วิธีวิเคราะห์
19	Selenium	1) Digestion, Hydride Generation/Atomic Absorption Spectrometric Method ^[2]
20	Sulfide	2) Digestion, Inductively Coupled Plasma Method ^[2] 1) Iodometric Method ^[2] 2) Methylene Blue Method ^[2]
21	Temperature	Laboratory and Field Methods ^[2]
22	Total Dissolved Solids	Dried at 180 °C ^[2]
23	Total Kjeldahl Nitrogen	Macro-Kjeldahl Method ^[2]
24	Total Suspended Solids	Dried at 103-105 °C ^[2]
25	Trivalent Chromium	1) Digestion, Direct Air-Acetylene Flame Method; Colorimetric Method; Calculation ^[2] 2) Digestion, Inductively Coupled Plasma Method; Colorimetric Method; Calculation ^[2]
26	Zinc	1) Digestion, Direct Air-Acetylene Flame Method ^[2] 2) Digestion, Inductively Coupled Plasma Method ^[2]

เอกสารอ้างอิง

1. สมาคมวิศวกรรมสิ่งแวดล้อมแห่งประเทศไทย. คู่มือวิเคราะห์น้ำเสีย. พิมพ์ครั้งที่ 4. กรุงเทพฯ: เรือนแก้วการพิมพ์, 2547.
2. APHA, AWWA, WEF. Standard Methods for the Examination of Water and Wastewater. 23rd ed. Washington, DC: APHA, 2017.



ใบรับรองเลขที่ 24-LB0075
(Certificate No.)

ใบรับรองระบบงาน (Certificate of Accreditation)

อาศัยอำนาจตามความในพระราชบัญญัติการมาตรฐานแห่งชาติ พ.ศ. ๒๕๕๑
(By Virtue of National Standardization Act B.E. 2551 (2008))

เลขาธิการสำนักงานมาตรฐานผลิตภัณฑ์อุตสาหกรรม
(Secretary-General, Thai Industrial Standards Institute)

ออกใบรับรองฉบับนี้ให้
(Issues this certificate to)

บริษัท เอ็นไวรอนเม้นท์ แอนด์ แล็บอราตอรี จำกัด
(Environment & Laboratory Co., Ltd.)

ตั้งอยู่เลขที่
(Address)

๔๐ ซอยเลียงเมืองนนทบุรี ๑๓ ตำบลตลาดขวัญ อำเภอเมืองนนทบุรี จังหวัดนนทบุรี
(40 Soi Liangmueangnonthaburi 13, Talad Kwan, Mueang Nonthaburi, Nonthaburi)

ได้รับการรับรองความสามารถ
(Certificate of competence)

ตามมาตรฐานเลขที่ มอก. ๑๗๐๒๕ - ๒๕๖๑
(Standard No. TIS 17025-2561 (2018) (ISO/IEC 17025: 2017))

ข้อกำหนดทั่วไปว่าด้วยความสามารถของ ห้องปฏิบัติการทดสอบและห้องปฏิบัติการสอบเทียบ
(General requirements for the competence of testing and calibration laboratories)

หมายเลขการรับรองที่ ทดสอบ ๐๒๔๐
(Accreditation No. Testing 0240)

โดยมีรายละเอียดสาขาและขอบข่ายที่ได้ใบรับรอง แสดงไว้ใน QR CODE และ www.tisi.go.th
(Details of the scheme and scope of the certificate are shown in QR CODE and www.tisi.go.th)

ออกให้ ณ วันที่ ๑๕ มกราคม พ.ศ. ๒๕๖๗
(Issue date : 15 January B.E. 2567 (2024))

(นายวีระศักดิ์ เพ็งหล่ง)

ผู้อำนวยการสำนักงานคณะกรรมการการมาตรฐานแห่งชาติ
ปฏิบัติราชการแทน
เลขาธิการสำนักงานมาตรฐานผลิตภัณฑ์อุตสาหกรรม



9620e443



รายละเอียดสาขาและขอบข่ายใบรับรองห้องปฏิบัติการ

(Scope of Accreditation for Testing)

ใบรับรองเลขที่ 24-LB0075

(Certification No. 24-LB0075)



ชื่อห้องปฏิบัติการ

(Laboratory Name)

บริษัท เอ็นไวรอนเมนต์ แอนด์ แล็บอราตอรี จำกัด

(Environment and Laboratory Co.,Ltd.)

หมายเลขการรับรองที่

(Accreditation No.)

ทดสอบ 0240

(Testing 0240)

ฉบับที่ 02

(Issue No. 02)

ออกให้ตั้งแต่วันที่ 25 ธันวาคม พ.ศ. 2566

(Valid from)

(25 December B.E. 2566 (2023))

ถึงวันที่ 18 ตุลาคม พ.ศ. 2571

(Until) (18 October B.E. 2571 (2028))

สถานภาพห้องปฏิบัติการ

(Laboratory status)

☒ ถาวร

(Permanent)

☐ นอกสถานที่

(Site)

☐ ชั่วคราว

(Temporary)

☐ เคลื่อนที่

(Mobile)

☐ หลายสถานที่

(Multisite)

สาขาการทดสอบ (Field of Testing)	รายการทดสอบ (Parameter)	วิธีทดสอบ (Test Method)
สาขาสิ่งแวดล้อม (environmental field) 1. น้ำและน้ำเสีย (water and wastewater)	- pH 4.0 to 10.0 - Total suspended solids (TSS) 5.0 mg/L to 1 000 mg/L - Copper (Cu) 0.030 mg/L to 5.00 mg/L	- Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 23rd edition, 2017, part 4500-H+ B - Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 23rd edition, 2017, part 2540 D - Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 23rd edition, 2017, part 3111 B and part 3030 E

รายละเอียดสาขาและขอบข่ายใบรับรองห้องปฏิบัติการ

(Scope of Accreditation for Testing)

ใบรับรองเลขที่ 24-LB0075

(Certification No. 24-LB0075)



ฉบับที่ 02

(Issue No.)

ออกให้ตั้งแต่วันที่ 25 ธันวาคม พ.ศ. 2566

(Valid from)

(25 December B.E. 2566 (2023))

ถึงวันที่ 18 ตุลาคม พ.ศ. 2571

(Until) (18 October B.E. 2571 (2028))

สถานภาพห้องปฏิบัติการ

(Laboratory status)

☒ ถาวร

(Permanent)

☐ นอกสถานที่

(Site)

☐ ชั่วคราว

(Temporary)

☐ เคลื่อนที่

(Mobile)

☐ หลายสถานที่

(Multisite)

สาขาการทดสอบ (Field of Testing)	รายการทดสอบ (Parameter)	วิธีทดสอบ (Test Method)
สาขาส่งแวดล้อม (environmental field) 1. น้ำและน้ำเสีย (ต่อ) (water and wastewater) (cont.) 2. น้ำเสีย (wastewater)	- Biochemical oxygen demand (BOD) 5.0 mg/L to 2 000 mg/L - Chemical oxygen demand (COD) 40.0 mg/L to 4 000 mg/L	- Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 23rd edition, 2017, part 5210 B and part 4500-O C - Standard Methods for the Examination of Water and Wastewater, APHA, AWWA, WEF, 23rd edition, 2017, part 5220 C



TECHNOLOGY PROMOTION ASSOCIATION (THAILAND-JAPAN)
CORPORATE SERVICES 3: EQUIPMENT CALIBRATION AND TESTING SERVICES
534/4 PATTANAKARN ROAD SOI 18, SUANLUANG, SUANLUANG BANGKOK 10250
TEL.0-2717-3000-29 FAX.0-2719-9484



Certificate of Calibration

Cert.No.: 25CH546

Page.: 1 of 3

Equipment : pH Meter
Manufacturer : Mettler Toledo
Model : Seven Compact S220
Serial No. : C125985375
ID No. : PHM-006
Condition As-Received: Used Item
Received Date : 13 May 2025
Calibration Date : 14 May 2025
Reference : 2505-0324DC-2
Submitted by : Environment & Laboratory Co.,Ltd.
40 Soi Liangmueangnonthaburi 13 Talad Kwan,
Mueang, Nonthaburi 11000
Ambient Temperature : (25 ± 2.5) °C
Relative Humidity : (50 ± 15) %
Calibration Procedure : In - house method :
- CP-CH5 by direct measurement with DC voltage
standard and direct measurement with
certified reference material (CRM)
- CP-CH8 by comparison with temperature standard
Calibrated by : Walalak Sirithean
Approved by : _____
Approved Signatory
() Chakrit Waewwanjua
() Ponpan Paipim
(✓) Saithip Meangmai
Issue Date : 15 May 2025

The Uncertainties are for a confidence probability of approximately 95%

This certificate may not be reproduced other than in full, except with the prior written
Approval of the head of Corporate Services 3 : Equipment Calibration and Testing Services.



Cert.No.: 25CH546

Page.: 2 of 3

Condition of this calibration result

1. Reference Standard Instrument

<u>Instrument</u>	<u>Serial No.</u>	<u>ID No.</u>	<u>Cert. No.</u>	<u>Due Date</u>
1) Document Process Calibrator	54030049	130RC116	24E2759	25 Aug 2025
2) Ref. Standard Thermometer	4982054	110RC044	24I757	14 July 2025

- This measurement result is traceable to SI through Technology Promotion Association (Thailand - Japan)

2. Certified Reference Materials :The measurement results are traceable to SI through Hach Lenge GmbH Ltd.,
Deutsche Akkreditierungsstelle, Accredited No.D-RM-15184-01-00
:The measurement results are traceable to SI through CPA chem Ltd.,
ANSI-ASQ National Accreditation Board, Accredited No. AR-1835

<u>Buffer Solution</u>	<u>Manufacturer</u>	<u>Lot No.</u>	<u>Exp. date</u>
pH 4.007	CPA chem	1066665	18 Jan 2027
pH 7.000	Hach Lenge GmbH	C03232	02 Dec 2026
pH 10.010	CPA chem	1066669	18 Jan 2026

3. This certificate is valid only to the item calibrated on date and place of calibration.

Calibration Results

Function : mV Measurement

Performing standard curve by Document Process Calibrator at pH (4,7,10)

Unit Under Calibration	Nominal Value	Standard Voltage Input	Actual Reading		Uncertainty of Measurement (±mV)	Coverage factor <i>k</i>
	pH	mV	mV	pH		
pH Meter S/N.: C125985375	4.000	177.48	177.7	4.000	0.058	2.00
	7.000	0.00	0.3	7.000	0.058	2.00
	10.000	-177.48	-177.1	10.000	0.058	2.00



Cert.No.: 25CH546

Page.: 3 of 3

Calibration Results

Function : pH Measurement

Performing three buffers standard curve by using buffer nominal pH (4,7,10)

Unit Under Calibration	Standard pH Buffer Solution	Actual pH Reading	Actual mV Reading (mV)	Uncertainty of pH Measurement ($\pm$)	Coverage factor k
pH Electrode S/N.: 1205515	4.007	4.007	176.1	0.0044	2.00
	7.000	6.999	3.7	0.0084	2.00
	10.010	10.010	-158.5	0.0065	2.00

Function : Temperature Measurement

(*) Without adjustment

This equipment was connected with Temperature Probe;

- Model : InLabExpert Pro-ISM

- Serial No. : 1205515

Dimension of probe

- Length : 120 mm.

- Diameter : 12 mm.

- Immersion Depth : 100 mm.

Calibration Point (°C)	Standard Temperature (°C)	UUC* Reading (°C)	Error (°C)	Uncertainty of measurement ($\pm$ °C)	Coverage factor k
25.0	25.001	24.9	-0.101	0.13	2.00

Remark - UUC* = Unit Under Calibration

The reported uncertainty of measurement was based on a standard uncertainty multiplied by a coverage factor k , providing a level of confidence of approximately 95 %.

-o0o-



TECHNOLOGY PROMOTION ASSOCIATION (THAILAND-JAPAN)
CORPORATE SERVICES 3: EQUIPMENT CALIBRATION AND TESTING SERVICES
534/4 PATTANAKARN ROAD SOI 18, SUANLUANG, SUANLUANG BANGKOK 10250
TEL.0-2717-3000-29 FAX.0-2719-9484



Certificate of Calibration

Cert.No.: 25MM393

Page.: 1 of 3

Equipment : Electronic Balance

Manufacturer : Mettler Toledo

Model : ML204T /00

Serial No. : B647342339

ID No. : ANB-003

Submitted by : Environment & Laboratory Co.,Ltd.
40 Soi Liangmueangnonthaburi 13
Talad Kwan, Mueang
Nonthaburi 11000

Location : Room No. 304

Received order : 08 July 2025
Calibration Date : 08 July 2025
Ambient Temperature : 15 °C to 40 °C
Relative Humidity : 30 % to 90 %

Calibrated by : Krisda Malee

Approved by :

Approved Signatory

() Chakrit Waewwanjua
() Suwit Imjai
(✓) Kunchit Promprat

Issue Date : 21 July 2025

The Uncertainties are for a confidence probability of approximately 95%

This certificate may not be reproduced other than in full, except with the prior written
Approval of the head of Corporate Services 3 : Equipment Calibration and Testing Services.



Equipment : Electronic Balance
Condition As-Received : Used Item
Reference : 2507-0148OC-7

Cert.No.: 25MM393

Page: 2 of 3

Procedure used :-

Calibration were conducted using in-house calibration procedure CP-OB01 based on UKAS LAB 14 according to direct measurement method against standard weight.

Condition of this result of calibration

1. Reference standard instruments:-

- | Instruments | Serial No. | Cert. No. | Traceable | Due date |
|-----------------------------|------------|------------|-----------|-------------|
| 1) Standard Weight Set (E2) | 24053 | MM-0013-24 | NIMT | 25 Jan 2026 |
- This certificate is valid only to the item calibrated on date and place of calibration.
 - This result of calibration was made on requested at the point specified by customer.
 - This certificate is not certified for any commercial transaction.
 - This measurement result is traceable to the International System of Unit maintained through :

Remark : NIMT : National Institute of Metrology Thailand

Result of calibration () Without Adjustment (*) After Adjustment by Internal Calibration

Range capacity : 0 g to 220 g **Resolution** 0.0001 g

Before Adjustment :

Applied Weight (g)	Balance Reading (g)	Correction (g)	Measurement Uncertainty ($\pm$ mg)	Coverage Factor (k)
100	99.9996	+0.0004	0.17	2
200	199.9998	+0.0002	0.30	2

After Adjustment :

1. **Determination of the standard deviation of weighing machine** (n = 10)

Applied Weight (g)	Standard Deviation of Reading (g)
100	0.00005
200	0.00004



Equipment : Electronic Balance
Condition As-Received : Used Item
Reference : 2507-0148OC-7


Cert.No.: 25MM393

Page: 3 of 3

Result of calibration

2. Effect of off center loading

A mass of 100 g was placed to various position on the pan.
The weighing machine reading error obtained is given in the table



Maximum difference between
off-center and central loading

Position 1 (g)	Position 2 (g)	Position 3 (g)	Position 4 (g)	Position 5 (g)	(g)
-0.0001	-0.0002	-0.0002	-0.0002	-0.0002	0.0001

3. Departure from nominal value

Applied Weight (g)	Balance Reading (g)	Correction (g)	Measurement Uncertainty ($\pm$ mg)	Coverage Factor (k)
Unload	0.0000	0.0000	0.12	2.06
0.1	0.1000	0.0000	0.12	2.06
0.2	0.2000	0.0000	0.12	2.06
1	1.0000	0.0000	0.12	2.06
5	5.0000	0.0000	0.12	2.06
10	9.9999	+0.0001	0.12	2.06
20	19.9999	+0.0001	0.12	2.05
50	50.0001	-0.0001	0.14	2
100	100.0000	0.0000	0.17	2
150	150.0000	0.0000	0.29	2
200	200.0000	0.0000	0.30	2

The reported uncertainty of measurement was based on a standard uncertainty multiplied by a coverage factor k , providing a level of confidence of approximately 95 %.

-o0o-



Certificate of Calibration

Cert. No.: 25TM977

Page : 1 of 3

Equipment : Incubator

Manufacturer : Sanden Intercool

Model : SRC-680SRTM

Serial No. : SRC680201-1107-00166

ID No. : CHI-003

Submitted by : EnvironMent & Laboratory Co.,Ltd.
40 Soi Liangmueangnonthaburi 13,
Talad Kwan, Mueang,
Nonthaburi 11000

Location : Room No. 301

Received Order : 08 July 2025

Calibration Date : 09 July 2025

Ambient Temperature : (26 ± 10) °C

Relative Humidity : (50 ± 30) %

AC Line Voltage : (220 ± 22) V

Calibrated by : Uthen Kankawi

Approved by :

Approved Signatory

() Chakrit Waewwanjua

() Suwit Imjai

(✓) Kunchit Promprat

Issue Date : 17 July 2025

The Uncertainties are for a confidence probability of approximately 95%

This certificate may not be reproduced other than in full, except with the prior written
Approval of the head of Corporate Services 3 : Equipment Calibration and Testing Services.



Equipment : Incubator
Condition As-Received : Used Item
Reference : 2507-0148OC-5

Cert. No.: 25TM977

Page : 2 of 3

Procedure Used :-

Calibration were conducted using calibration procedure CP-OT02 based on TLAS G-20 according to direct measurement method with Data Acquisition which connected with Resistance Temperature Detector (RTD).

The temperature scale used was based on ITS-90.

Condition of this result of calibration

1. Reference standard instrument:-

<u>Instrument</u>	<u>Serial No.</u>	<u>Cert. No.</u>	<u>Traceable</u>	<u>Due Date</u>
1) Data Acquisition	MY49023932	24LM119	TPA	27 Jul 2025
2) Data Acquisition	MY49023932	24LM119	TPA,	27 Jul 2025

2. This certificate is valid only to the item calibrated on date and place of calibration.

3. This measurement result is traceable to the International System of Unit maintained through :

Remark : TPA : Technology Promotion Association (Thailand - Japan)


Result of Calibration :- (*) Without Adjustment

Function of UUC* : Temperature Source

Fresh air setting : Close

Environment during calibration		
	Beginning	Finished
Temp. (°C)	28	29
REL.Humi. (%)	54	55
AC Supply (Volt)	224	225

Position :	Ref. Std. ID No.:
1	20-16RTD-01
2	20-16RTD-02
3	20-16RTD-03
4	20-16RTD-04
5	22-16RTD-05
6	20-16RTD-06
7	20-16RTD-07
8	22-16RTD-08
9 (ref.)	22-16RTD-09
10	20-16RTD-10
11	19-16RTD-01
12	19-16RTD-02
13	19-16RTD-03



Dimension of Chamber :

D = 0.60 m

Probe Installation Details :

a = 10 cm



Equipment : Incubator
Condition As-Received : Used Item
Reference : 2507-0148OC-5
Result of Calibration :- (*) Without Adjustment
Function of UUC* : Temperature Source
Fresh air setting : Close

Cert. No.: 25TM977

Page : 3 of 3

Calibration Point (°C)	UUC* Setting (°C)	UUC* Reading (°C)	Temperature stability (± °C)	Temperature uniformity (°C)	Overall Variation (°C)	Coverage Factor <i>k</i>
20.0	20.0	20.0	0.21	0.43	0.80	2

Calibration Point (°C)	Measured Temperature (°C)									Uncertainty (± °C)
	Position									
20.0	1	2	3	4	5	6	7	8	9 (ref.)	0.35
	19.957	20.008	20.073	19.725	19.753	19.679	19.701	19.670	20.012	
	10	11	12	13						
	19.789	19.773	20.168	19.744						

Average* : The average of 30 values in each position.

Temperature stability : One-half of the greatest maximum difference of measured temperature at any one sensor.

Temperature uniformity : The maximum difference of measured temperatures at any sensors and the measured temperature at the reference location which are observed at the same time or at as close an observation time as possible to determine the temperature pattern or homogeneity within the chamber under steady-state conditions.

Overall Variation : The Difference of the maximum and minimum measured temperatures throughout observation.

UUC* : Unit Under Calibration

Note : The reported uncertainty of measurement was included stability and excluded uniformity.

The reported uncertainty of measurement was based on a standard uncertainty multiplied by a coverage factor *k*, providing a level of confidence of approximately 95 %.

-o0o-



TECHNOLOGY PROMOTION ASSOCIATION (THAILAND-JAPAN)
CORPORATE SERVICES 3: EQUIPMENT CALIBRATION AND TESTING SERVICES
534/4 PATTANAKARN ROAD SOI 18, SUANLUANG, SUANLUANG BANGKOK 10250
TEL.0-2717-3000-29 FAX.0-2719-9484



Certificate of Calibration

Cert. No.: 25TM974

Page : 1 of 3

Equipment : Hot Air Oven

Manufacturer : FRANCE ETUVES

Model : XU058

Serial No. : P790

ID No. : CHO-004

Submitted by : Environment & Laboratory Co.,Ltd.
40 Soi Liangmueangnonthaburi 13
Talad Kwan, Mueang
Nonthaburi 11000

Location : Room No. 303

Received Order : 08 July 2025

Calibration Date : 08 July 2025

Ambient Temperature : (26 ± 10) °C

Relative Humidity : (50 ± 30) %

AC Line Voltage : (220 ± 22) V

Calibrated by : Krisda Malee

Approved by :

Approved Signatory

() Chakrit Waewwanjua

() Suwit Imjai

(✓) Kunchit Promprat

Issue Date : 17 July 2025

The Uncertainties are for a confidence probability of approximately 95%

This certificate may not be reproduced other than in full, except with the prior written
Approval of the head of Corporate Services 3 : Equipment Calibration and Testing Services.



Equipment : Hot Air Oven
Condition As-Received : Used Item
Reference : 2507-0148OC-2
Procedure Used :-

Cert. No.: 25TM974
Page : 2 of 3

Calibration were conducted using calibration procedure CP-OT02 based on TLAS G-20 according to direct measurement method with Data Acquisition which connected with Resistance Temperature Detector (RTD) and Thermocouple Type T.

The temperature scale used was based on ITS-90.

Condition of this result of calibration

1. Reference standard instrument:-

<u>Instrument</u>	<u>Serial No.</u>	<u>Cert. No.</u>	<u>Traceable</u>	<u>Due Date</u>
1) Data Acquisition	MY57013823	25LM75	TPA	06 May 2026

2. This certificate is valid only to the item calibrated on date and place of calibration.


3. This measurement result is traceable to the International System of Unit maintained through :

Remark : TPA : Technology Promotion Association (Thailand - Japan)

Result of Calibration :- (*) Without Adjustment

Function of UUC* : Temperature Source

Fresh air setting : Close



Environment during calibration		
	Beginning	Finished
Temp. (°C)	28	26
REL.Humid. (%)	47	51
AC Supply (Volt)	220	221

Probe Installation Details :

a = 5.0 cm
b = 5.0 cm
c = 5.0 cm

Dimension of Chamber :

D = 0.36 m
W = 0.40 m
H = 0.40 m
Capacity = 0.058 m³

**Ref. Std. ID No.: @
Calibration Point**

Position :	(180) °C	(104) °C
1	21-17TC-01	25-17RTD-01
2	21-17TC-02	25-17RTD-02
3	21-17TC-03	25-17RTD-03
4	21-17TC-04	25-17RTD-04
5	21-17TC-05	25-17RTD-05
6	21-17TC-06	25-17RTD-06
7	21-17TC-07	25-17RTD-07
8	21-17TC-08	25-17RTD-08
9 (ref.)	21-17TC-09	25-17RTD-09



Equipment : Hot Air Oven
Condition As-Received : Used Item
Reference : 2507-0148OC-2
Result of Calibration :- (*) Without Adjustment
Function of UUC* : Temperature Source
Fresh air setting : Close

Cert. No.: 25TM974

Page : 3 of 3

Calibration Point (°C)	UUC* Setting (°C)	UUC* Reading (°C)	Temperature stability (± °C)	Temperature uniformity (°C)	Overall Variation (°C)	Coverage Factor <i>k</i>
104.0	104.0	104.0	0.13	1.0	1.1	2
180.0	180.0	180.0	0.24	1.6	1.9	2

Calibration Point (°C)	Measured Temperature (°C)									Uncertainty (±°C)
	Position									
	1	2	3	4	5	6	7	8	9 (ref.)	
104.0	103.529	103.769	104.251	104.428	103.589	103.683	104.172	103.978	104.411	0.42
180.0	180.583	179.425	180.832	179.981	179.369	179.667	180.479	180.019	180.809	1.1

Average* : The average of 30 values in each position.

Temperature stability : One-half of the greatest maximum difference of measured temperature at any one sensor.

Temperature uniformity : The maximum difference of measured temperatures at any sensors and the measured temperature at the reference location which are observed at the same time or at as close an observation time as possible to determine the temperature pattern or homogeneity within the chamber under steady-state conditions.

Overall Variation : The Difference of the maximum and minimum measured temperatures throughout observation.

UUC* : Unit Under Calibration

Note : The reported uncertainty of measurement was included stability and excluded uniformity .

The reported uncertainty of measurement was based on a standard uncertainty multiplied by a coverage factor *k*, providing a level of confidence of approximately 95 %.

-o0o-



TECHNOLOGY PROMOTION ASSOCIATION (THAILAND-JAPAN)
CORPORATE SERVICES 3: EQUIPMENT CALIBRATION AND TESTING SERVICES
534/4 PATTANAKARN ROAD SOI 18, SUANLUANG, SUANLUANG BANGKOK 10250
TEL.0-2717-3000-29 FAX.0-2719-9484



Certificate of Calibration

Cert. No.: 25TM951

Page : 1 of 3

Equipment : Water Bath
Manufacturer : Memmert
Model : WNE 14
Serial No. : L418.1373
ID No. : WAB-02
Submitted by : Environment & Laboratory Co.,Ltd
40 Soi liangmueangnonthaburi 13
Talad Kwan, Mueang,
Nonthaburi 11000
Location : ห้องปฏิบัติการวิเคราะห์ 4
Received Order : 08 July 2025
Calibration Date : 08 July 2025
Ambient Temperature : (26 ± 10) °C
Relative Humidity : (50 ± 30) %
AC Line Voltage : (220 ± 22) V

Calibrated by : Preecha Hlahib

Approved by :

Approved Signatory

() Chakrit Waewwanjua

() Suwit Imjai

(✓) Kunchit Promprat

Issue Date :

21 July 2025

The Uncertainties are for a confidence probability of approximately 95%

This certificate may not be reproduced other than in full, except with the prior written
Approval of the head of Corporate Services 3 : Equipment Calibration and Testing Services.



Equipment : Water Bath
Condition As-Received : Used Item
Reference : 2507-0148OC-3

Cert. No.: 25TM951

Page : 2 of 3

Procedure Used :-

Calibration were conducted using in-house calibration procedure CP-OT04 Based on ASTM E715 according to direct measurement method with Data Acquisition which connected with Industrial Platinum Resistance Thermometer (IPRT).

The temperature scale used was based on ITS-90.

Condition of this result of calibration

1. Reference standard instrument:-

<u>Instrument</u>	<u>Serial No.</u>	<u>Cert. No.</u>	<u>Traceable</u>	<u>Due Date</u>
1) Data Acquisition	MY57013711	24LM115	TPA	13 Jul 2025

2. This certificate is valid only to the item calibrated on date and place of calibration.

3. This measurement result is traceable to the International System of Unit maintained through :


Remark : TPA : Technology Promotion Association (Thailand - Japan)

Result of Calibration :- (*) Without Adjustment

Function of UUC* : Temperature Source

Heat transfer medium used : Water

	<u>Environmental</u>		<u>AC Voltage Supply</u>
	(°C)	(%R.H.)	(Volt)
Beginning of Calibration	24	55	221
Finished of Calibration	21	56	221



Front

<u>Position :</u>	<u>Ref. Std. ID No.:</u>
1	4803988-001
2	4803988-002
3	4803988-003
4	4803988-004
5(ref.)	4803988-005



Equipment : Water Bath
Condition As-Received : Used Item
Reference : 2507-0148OC-3
Result of Calibration :- (*) Without Adjustment
Function of UUC* : Temperature Source

Cert. No.: 25TM951

Page : 3 of 3

Calibration point (°C)	UUC* Setting (°C)	UUC* Reading (°C)	Average* Standard Reading (°C)					Uncertainty
			Position					
			1	2	3	4	5 (ref.)	(± °C)
44.5	44.5	44.5	44.569	44.543	44.554	44.587	44.593	0.15
60.0	60.0	60.0	60.293	60.259	60.206	60.246	60.291	0.15

Calibration point (°C)	Uniformity (°C)	Stability (± °C)	Coverage Factor <i>k</i>
44.5	0.098	0.045	2
60.0	0.13	0.050	2

Average* : The average of 30 values in each position.

Uniformity : The maximum difference of measured temperatures at any sensors and the measured temperature at the reference location which are observed at the same time or at as close an observation time as possible to determine the temperature pattern or homogeneity within the chamber under steady-state conditions.

Stability : One-half of the greatest maximum difference of measured temperature at any one probe.

UUC* : Unit Under Calibration

Note : The reported uncertainty of measurement was included stability and excluded uniformity.

The reported uncertainty of measurement was based on a standard uncertainty multiplied by a coverage factor *k*, providing a level of confidence of approximately 95 %.

-o0o-

ภาคผนวกที่ 5

สำเนาเอกสารประกอบการปฏิบัติตามมาตรการฯ


สำเนาแบบรายงานสรุปการทำงานของระบบบำบัดน้ำเสีย

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง จังหวัดกรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอช รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทรถจักรยาน "โรงแรมซัมเมอร์เซ็ท รัชดาไนน์ แบงค็อก" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กระทรวงมหาดไทย หมดยอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



สถิติและข้อมูลที่เกี่ยวข้องกับการดำเนินงานระบบบำบัดน้ำเสีย														
วัน/เดือน/ปี	ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)	ปริมาณน้ำที่ใช้ในทุกระยะการบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ(ลบ.ม.)	ปริมาณน้ำเสียที่เข้าสู่ระบบบำบัดน้ำเสีย (ลบ.ม.)	การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย (ระบาย/ไม่ระบาย)	ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ชื่อ/ปริมาณ) (ลิตรหรือ กิโลกรัม)	ระบบบำบัดน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติมอากาศ (ปกติ/ผิดปกติ)	เครื่องกวน/ผสมน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	อื่นๆ (ระบุ) (ปกติ/ผิดปกติ)	ปริมาณตะกอนส่วนเกิน	ปัญหาอุปสรรคและแนวทางแก้ไข	ลายมือชื่อผู้บันทึก
1-Jan-2025	10.3	120	103.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
2-Jan-2025	11.7	146	116.8	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
3-Jan-2025	10.9	161	124.3	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
4-Jan-2025	10.7	103	82.1	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
5-Jan-2025	10.1	102	81.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
6-Jan-2025	10.0	100	80.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
7-Jan-2025	10.1	94	79.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
8-Jan-2025	9.7	81	67.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
9-Jan-2025	10.2	120	86.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
10-Jan-2025	10.2	129	109.9	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
11-Jan-2025	9.2	135	108.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
12-Jan-2025	8.3	99	79.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
13-Jan-2025	7.9	107	85.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
14-Jan-2025	7.9	115	82.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
15-Jan-2025	7.4	137	109.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
16-Jan-2025	8.4	111	88.3	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
17-Jan-2025	8.2	124	89.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
18-Jan-2025	7.7	135	108.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
19-Jan-2025	7.6	113	80.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
20-Jan-2025	7.6	100	80.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
21-Jan-2025	7.5	99	79.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
22-Jan-2025	7.0	115	82.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
23-Jan-2025	7.3	127	117.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
24-Jan-2025	8.0	103	82.1	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
25-Jan-2025	7.7	140	112.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
26-Jan-2025	7.7	130	108.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
27-Jan-2025	7.6	115	82.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
28-Jan-2025	7.6	129	103.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
29-Jan-2025	7.6	122	89.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
30-Jan-2025	8.4	131	108.8	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit
31-Jan-2025	7.3	138	110.8	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ				Amuchit

หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีที่ระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

ลงชื่อ



นาย ฤทธิพิพัทธ์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : Somerset Rama9 Bangkok

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 22

หมู่ที่ :

ឆ្លើយ :

ถนน : รัชดาภิเษก

แขวง/ตำบล : ห้วยขวาง

เขต/ตำบล : เขตห้วยขวาง

จังหวัด : กรุงเทพมหานคร

โทรศัพท์ : 022391999

โทรสาร : 022391900

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 445

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 214/2567

ออกให้โดย : กระทรวงมหาดไทย

หมดอายุ : 17/12/2572

ในการนี้ ขอรายงานสรุปผลการดำเนินงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน มกราคม พ.ศ. 2569 ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายณัฏฐิติพัทธ์ ร้อยโสม เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ  ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมุดอายุ _____

ออกให้โดย

ลงชื่อ _____ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

๒. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

1. ระบบบำบัดน้ำเสียแบบแอคติเวตเต็ดสลัดจ์ (Activated Sludge Process)

353.00 ลบ.ม./วัน

(2) การทำงานของระบบบำบัดน้ำเสีย

[X] แบบต่อเนื่อง 24 ชั่วโมง/วัน

[] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[X] เครื่องสูบน้ำ

[X] ระบบเติมอากาศ

[X] เครื่องกว่น/ผสมน้ำเสีย

[X] เครื่องกวาด/ผสมสารเคมี

[X] เครื่องสูบลมตะกอน

[] อื่นๆ

[] อื่นๆ

[] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ) ระบายออกนอกหม. ผังถนนรัชดาภิเษก

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด จ้างบริษัทสูบน้ำไปกำจัดทิ้ง

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

(1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 270.300 หน่วย

(2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 3,720.000 ลบ.ม.

(3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 2,976.000 ลบ.ม.

(4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย [X] ระบายทุกวัน
[] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน
[] ไม่ระบายเลย

(5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย
1. 0.000 กิโลกรัม

(6) การทำงานของระบบบำบัดน้ำเสีย

ระบบบำบัดน้ำเสีย	[X] ปกติ	[] ผิดปกติ
เครื่องสูบน้ำ	[X] ปกติ	[] ผิดปกติ
ระบบเติมอากาศ	[X] ปกติ	[] ผิดปกติ
เครื่องกวน/ผสมน้ำเสีย	[X] ปกติ	[] ผิดปกติ
เครื่องกวน/ผสมสารเคมี	[X] ปกติ	[] ผิดปกติ
เครื่องสูบตะกอน	[X] ปกติ	[] ผิดปกติ

(7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม

(8) ปัญหา อุปสรรค และแนวทางแก้ไข

คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงานตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖


๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงานโดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง จังหวัดกรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอส รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทธุรกิจ โรงแรม "โรงแรมซัมเมอร์เซ็ท รัชดาไนน์ แบงค็อก" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กระทรวงมหาดไทย หมดยอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทิ้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทิ้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ


นัทธิตีพัทธ์ ร้อยโสม

ลงชื่อ _____

นาย นัทธิตีพัทธ์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ _____

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ _____

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : Somerset Rama9 Bangkok

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 22

หมู่ที่ :

ซอย :

ถนน : รัชดาภิเษก

แขวง/ตำบล : ห้วยขวาง

เขต/ตำบล : เขตห้วยขวาง

จังหวัด : กรุงเทพมหานคร

โทรศัพท์ : 022391999

โทรสาร : 022391900

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 445

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 214/2567

ออกให้โดย : กระทรวงมหาดไทย

หมดอายุ : 17/12/2572

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน กุมภาพันธ์ พ.ศ. 2569 ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายณัฏฐิพัทธ์ ร้อยโสม เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ  ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ _____ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

3. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

(2) การทำงานของระบบบำบัดน้ำเสีย

[X] แบบต่อเนื่อง ชั่วโมง/วัน

[] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[] เครื่องสูบน้ำ

[] ระบบเติมอากาศ

[] เครื่องกวน/ผสมน้ำเสีย

[] เครื่องกวน/ผสมสารเคมี

[] เครื่องสูบลตะกอน

[] อื่นๆ

[] อื่นๆ

[] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ)

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 224.200 หน่วย
- (2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 3,741.000 ลบ.ม.
- (3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 2,992.800 ลบ.ม.
- (4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย ☒ [X] ระบายทุกวัน
☐ [] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน
☐ [] ไม่ระบายเลย
- (5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย
1. 0.000 กิโลกรัม
- (6) การทำงานของระบบบำบัดน้ำเสีย
ระบบบำบัดน้ำเสีย ☒ [X] ปกติ ☐ [] ผิดปกติ
- (7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม
- (8) ปัญหา อุปสรรค และแนวทางแก้ไข

คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง

ให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน

ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท

หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖

๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน

โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกิน


หนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง จังหวัดกรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอช รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทธุรกิจ โรงแรม "โรงแรมซัมเมอร์เซ็ท งามไนน์ แบงค็อก" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กระทรวงมหาดไทย หมดยอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทั้ง
ทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

ลงชื่อ



นาย ฤทธิ์ทิพย์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : Somerset Rama9 Bangkok

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 22

หมู่ที่ :

ซอย :

ถนน : รัชดาภิเษก

แขวง/ตำบล : ห้วยขวาง

เขต/ตำบล : เขตห้วยขวาง

จังหวัด : กรุงเทพมหานคร

โทรศัพท์ : 022391999

โทรสาร : 022391900

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 445

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 214/2567

ออกให้โดย : กระทรวงมหาดไทย

หมดอายุ : 17/12/2572

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน มีนาคม พ.ศ. 2569 ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายณัฏฐิพัทธ์ ร้อยโสม เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ  ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ _____ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

2. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

(2) การทำงานของระบบบำบัดน้ำเสีย

[X] แบบต่อเนื่อง ชั่วโมง/วัน

[] แบบไม่ต่อเนื่อง (ระบุด)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[] เครื่องสูบน้ำ

[] ระบบเติมอากาศ

[] เครื่องกวน/ผสมน้ำเสีย

[] เครื่องกวน/ผสมสารเคมี

[] เครื่องสูบลำโพง

[] อื่นๆ

[] อื่นๆ

[] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ)

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 224.200 หน่วย
- (2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 3,741.000 ลบ.ม.
- (3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 2,992.800 ลบ.ม.
- (4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย
- ☒ ระบายทุกวัน
- ☐ ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน
- ☐ ไม่ระบายเลย
- (5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย
1. 0.000 กิโลกรัม
- (6) การทำงานของระบบบำบัดน้ำเสีย
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ
- (7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม
- (8) ปัญหา อุปสรรค และแนวทางแก้ไข


- คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง ให้บริการบำบัดน้ำเสียผู้ใดไม่จดทะเบียนสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง จังหวัดกรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอช รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทธุรกิจโรงแรม "โรงแรมซัมเมอร์เซ็ท ราชินี แบล็คค็อก" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กระทรวงมหาดไทย หมดอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

ลงชื่อ



นาย ณัฏฐิตพัทธ์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

วัตถุประสงค์เพื่อเก็บข้อมูลเกี่ยวกับแหล่งกำเนิดมลพิษ

[illegible]

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : Somerset Rama9 Bangkok

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 22

หมู่ที่ :

ឥឡូវ :

ถนน : รัชดาภิเษก

แขวง/ตำบล : ห้วยขวาง

เขต/ตำบล : เขตห้วยขวาง

จังหวัด : กรุงเทพมหานคร

โทรศัพท์ : 022391999

โทรสาร : 022391900

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 445

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 214/2567

ออกให้โดย : กระทรวงมหาดไทย

หมดอายุ : 17/12/2572

ในการนี้ ขอรายงานสรุปผลการดำเนินงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน เมษายน พ.ศ. 2569 ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายณัฏฐิติพัทธ์ ร้อยโสม เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ _____ ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ _____ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

๑. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

(2) การทำงานของระบบบำบัดน้ำเสีย

[X] แบบต่อเนื่อง ชั่วโมง/วัน

[] แบบไม่ต่อเนื่อง (ระบุ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[] เครื่องสูบน้ำ

[] ระบบเติมอากาศ

[] เครื่องกวาด/ผสมน้ำเสีย

[] เครื่องกววน/ผสมสารเคมี

[] เครื่องสูบน้ำตะกอน

[] อื่นๆ

[] อื่นๆ

[] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ)

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 290.700 หน่วย
- (2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 3,308.000 ลบ.ม.
- (3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 2,646.400 ลบ.ม.
- (4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย
- ☒ ระบายทุกวัน
- ☐ ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน
- ☐ ไม่ระบายเลย
- (5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย
1. 0.000 กิโลกรัม
- (6) การทำงานของระบบบำบัดน้ำเสีย
- ระบบบำบัดน้ำเสีย ☒ ปกติ ☐ ผิดปกติ
- (7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม
- (8) ปัญหา อุปสรรค และแนวทางแก้ไข


- คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง ให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง จังหวัดกรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอช รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทธุรกิจโรงแรม "โรงแรมซัมเมอร์เซ็ท ราชไนน์ แบงค็อก" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กระทรวงมหาดไทย หมดยอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทั้ง
ทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

ลงชื่อ



นาย ฤทธิพิพัทธ์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

สถิติและข้อมูลที่เกี่ยวข้องกับการแข่งขันกีฬานานาชาติ											
วัน/เดือน/ปี	ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย)	ปริมาณน้ำที่ใช้ในกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.)	ปริมาณน้ำเสียที่เข้าสู่ระบบบำบัดน้ำเสีย (ลบ.ม.)	การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย (ระบาย/ไม่ระบาย)	ปริมาณสารเคมีหรือสารสกัดชีวภาพที่ใช้ (ชื่อ/ปริมาณ) (ลิตรหรือ กิโลกรัม)	การทำงานของระบบบำบัดน้ำเสีย					
						ระบบบำบัดน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบน้ำ (ปกติ/ผิดปกติ)	เครื่องเติมอากาศ (ปกติ/ผิดปกติ)	เครื่องกวน/ผสมน้ำเสีย (ปกติ/ผิดปกติ)	เครื่องสูบลบตะกอน (ปกติ/ผิดปกติ)	อื่น ๆ (ระบุ/ปกติ/ผิดปกติ)
1-May-2026	10.6	111	11.2	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
2-May-2026	10.2	115	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
3-May-2026	10.4	102	11.6	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
4-May-2026	10.3	100	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
5-May-2026	10.1	100	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
6-May-2026	10.1	63	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
7-May-2026	10.2	115	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
8-May-2026	10.4	115	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
9-May-2026	11.1	101	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
10-May-2026	11.7	101	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
11-May-2026	11.4	116	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
12-May-2026	11.3	71	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
13-May-2026	11.3	103	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
14-May-2026	10.3	113	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
15-May-2026	11.3	115	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
16-May-2026	12.1	100	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
17-May-2026	11.7	104	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
18-May-2026	12.2	100	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
19-May-2026	11.4	103	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
20-May-2026	11.7	102	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
21-May-2026	11.6	104	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
22-May-2026	11.6	116	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
23-May-2026	11.5	115	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
24-May-2026	11.7	102	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
25-May-2026	11.6	106	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
26-May-2026	11.3	123	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
27-May-2026	12.1	113	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
28-May-2026	12.0	111	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
29-May-2026	12.2	107	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
30-May-2026	11.0	110	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ
31-May-2026	11.7	111	11.0	ระบาย	-	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ	ปกติ

ลายมือชื่อผู้บันทึก

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : Somerset Rama9 Bangkok

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 22

หมู่ที่ :

ซอย :

ถนน : รัชดาภิเษก

แขวง/ตำบล : ห้วยขวาง

เขต/ตำบล : เขตห้วยขวาง

จังหวัด : กรุงเทพมหานคร

โทรศัพท์ : 022391999

โทรสาร : 022391900

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 445

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 214/2567

ออกให้โดย : กระทรวงมหาดไทย

หมดอายุ : 17/12/2572

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน พฤษภาคม พ.ศ. 2569 ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายณัฏฐิพัทธ์ ร้อยโสม เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ  ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ _____ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

(2) การทำงานของระบบบำบัดน้ำเสีย

[X] แบบต่อเนื่อง ชั่วโมง/วัน

[] แบบไม่ต่อเนื่อง (ระยะ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[] เครื่องสูบน้ำ

[] ระบบเติมอากาศ

[] เครื่องกวน/ผสมน้ำเสีย

[] เครื่องกวน/ผสมสารเคมี

[] เครื่องสูบละกอน

[] อื่นๆ

[] อื่นๆ

[] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ)

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 352.300 หน่วย
- (2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 3,220.000 ลบ.ม.
- (3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 2,576.000 ลบ.ม.
- (4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย [X] ระบายทุกวัน
[] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน
[] ไม่ระบายเลย
- (5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย
1. 0.000 กิโลกรัม
- (6) การทำงานของระบบบำบัดน้ำเสีย
ระบบบำบัดน้ำเสีย [X] ปกติ [] ผิดปกติ
- (7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม
- (8) ปัญหา อุปสรรค และแนวทางแก้ไข


- คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง ให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

แบบบันทึกรายละเอียดของสถิติและข้อมูลซึ่งแสดงผลการทำงานของระบบบำบัดน้ำเสียของแหล่งกำเนิดมลพิษ

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ 22 ถนนรัชดาภิเษก แขวงห้วยขวาง เขตห้วยขวาง กรุงเทพมหานคร โทรศัพท์ 02-239-1999 โทรสาร 02-239-1900 โดยมีบริษัท เอเอ็มเอช รัชดา จำกัด เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิด กำเนิดมลพิษ ประกอบกิจการประเภทธุรกิจ โรงแรม "โรงแรมซัมเมอร์เซ็ท รัมไนน์ แบงค็อก" ใบอนุญาตเลขที่ 214/2567 ออกให้โดย กระทรวงมหาดไทย หมดยอายุ วันที่ 17 ธันวาคม พ.ศ. 2572

ซึ่งมีแผนผังแสดงการทำงานของระบบบำบัดน้ำเสีย ดังนี้

ผังขั้นตอนระบบบำบัดน้ำเสีย



หมายเหตุ ๑. ให้กรอกสถิติและข้อมูลเฉพาะในกรณีที่มีสถิติและข้อมูลนั้น ๆ ในแต่ละวัน

๒. ในกรณีระบบบำบัดน้ำเสียที่มีการติดตั้งเครื่องตรวจวัดคุณภาพน้ำทั้งแบบอัตโนมัติ ให้แนบผลการตรวจวัดคุณภาพน้ำทั้งทุกวันแยกตามพารามิเตอร์ที่ตรวจวัด และทำการสรุปผลเป็นสถิติและข้อมูลรายเดือน

ขอรับรองว่าการบันทึกสถิติและข้อมูลตามตารางข้างต้นถูกต้องทุกประการ

ลงชื่อ



นาย ฤทธิพิพัทธ์ ร้อยโสม

เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ

ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ

ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

รายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย

ชื่อแหล่งกำเนิดมลพิษ : Somerset Rama9 Bangkok

แหล่งกำเนิดมลพิษ ตั้งอยู่เลขที่ : 22

หมู่ที่ :

ซอย :

ถนน : รัชดาภิเษก

แขวง/ตำบล : ห้วยขวาง

เขต/ตำบล : เขตห้วยขวาง

จังหวัด : กรุงเทพมหานคร

โทรศัพท์ : 022391999

โทรสาร : 022391900

มี : เป็นเจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ประกอบกิจการประเภท : โรงแรม

ประเภทย่อย : ประเภท ก ตั้งแต่ 200 ห้องขึ้นไป จำนวนห้อง : 445

สังกัด : เอกชน

ใบอนุญาตเลขที่ (ถ้ามี) : 214/2567

ออกให้โดย : กระทรวงมหาดไทย

หมดอายุ : 17/12/2572

ในการนี้ ขอรายงานสรุปผลการทำงานของระบบบำบัดน้ำเสีย ของแหล่งกำเนิดมลพิษสำหรับ เดือน มิถุนายน พ.ศ. 2569 ตามที่ได้กำหนดในมาตรา 80 แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. 2535 ในฐานะ

ลงชื่อ นายณัฏฐิพัทธ์ ร้อยโสม เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ

ลงชื่อ  ผู้ควบคุมระบบบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

ลงชื่อ _____ ผู้รับจ้างให้บริการบำบัดน้ำเสีย

ใบอนุญาตเลขที่ _____ หมดอายุ _____

ออกให้โดย _____

2. ข้อมูลเกี่ยวกับระบบน้ำเสีย และแหล่งรองรับน้ำทิ้ง

(1) ประเภท / ชนิดของระบบบำบัดน้ำเสีย

ความสามารถในการบำบัดน้ำเสีย

(2) การทำงานของระบบบำบัดน้ำเสีย

[X] แบบต่อเนื่อง ชั่วโมง/วัน

[] แบบไม่ต่อเนื่อง (ระยะ)

(3) อุปกรณ์และเครื่องมือที่ใช้ในระบบบำบัดน้ำเสีย

[] เครื่องสูบน้ำ

[] ระบบเติมอากาศ

[] เครื่องกวน/ผสมน้ำเสีย

[] เครื่องกวน/ผสมสารเคมี

[] เครื่องสูบลตะกอน

[] อื่นๆ

[] อื่นๆ

[] อื่นๆ

(4) แหล่งรองรับน้ำทิ้ง (ระบุ)

(5) วิธีจัดการตะกอนที่เกิดขึ้นจากระบบบำบัดน้ำเสียและวิธีการกำจัด

3. สรุปผลการทำงานของระบบบำบัดน้ำเสียเป็นรายเดือน

- (1) ปริมาณการใช้ไฟฟ้าของระบบบำบัดน้ำเสีย (หน่วย) 332.600 หน่วย
- (2) ปริมาณน้ำใช้ในทุกกิจกรรมของแหล่งกำเนิดมลพิษ (ลบ.ม.) 3,034.000 ลบ.ม.
- (3) ปริมาณน้ำเสียที่เข้าระบบบำบัดน้ำเสีย (ลบ.ม.) 2,427.200 ลบ.ม.
- (4) การระบายน้ำทิ้งจากระบบบำบัดน้ำเสีย [X] ระบายทุกวัน
[] ระบายบางวัน (ระบุจำนวนวันที่ระบาย) วัน
[] ไม่ระบายเลย
- (5) ปริมาณสารเคมี หรือสารสกัดชีวภาพที่ใช้ ปริมาณ หน่วย
1. 0.000 กิโลกรัม
- (6) การทำงานของระบบบำบัดน้ำเสีย
ระบบบำบัดน้ำเสีย [X] ปกติ [] ผิดปกติ
- (7) ปริมาณตะกอนส่วนเกินที่เกิดขึ้นจากระบบบำบัดน้ำเสียที่นำไปกำจัด 0.00 กิโลกรัม
- (8) ปัญหา อุปสรรค และแนวทางแก้ไข

- คำเตือน ๑. เจ้าของหรือผู้ครอบครองแหล่งกำเนิดมลพิษ ผู้ควบคุมระบบบำบัดน้ำเสีย หรือผู้รับจ้าง ให้บริการบำบัดน้ำเสียผู้ใดไม่จัดเก็บสถิติ ข้อมูล หรือไม่ทำบันทึกหรือรายงาน ตามมาตรา ๘๐ ต้องระวางโทษจำคุกไม่เกินหนึ่งเดือน หรือปรับไม่เกินหนึ่งหมื่นบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๖
๒. ผู้ควบคุมระบบบำบัดน้ำเสียหรือผู้รับจ้างให้บริการบำบัดน้ำเสียผู้ใดทำบันทึกหรือรายงาน โดยแสดงข้อความอันเป็นเท็จ ต้องระวางโทษจำคุกไม่เกินหนึ่งปี หรือปรับไม่เกินหนึ่งแสนบาท หรือทั้งจำทั้งปรับตามมาตรา ๑๐๗

สำเนาการตรวจสอบระบบไฟฟ้าของโครงการ

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 28/6/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>1250</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>36.5</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	() tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>9.17</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0.1</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>36</u> °C <u>70</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.2, 0.6</u> amp <u>1.7, 2.6</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>248</u> psi
- Pressure relief valve maintain pressure at	<u>240</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>1250</u> ltrs. Add <u>-</u> ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>36.7</u> hrs.
- Record hours meter reading	

Time start 19.36 Time stop 15.46

Total 10 mins

Supervisor's comments _____

Record by

Bmm

SOMERSET

RAMA 9
SANGKOK

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 21/06/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>950</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>36.3</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>-</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.1/3.3</u> amp <u>4.2/0.0</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>950</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>36.5</u> hrs.

Time start 16.30 Time stop 16.40Total 10 mins

Supervisor's comments

Record by

Anvchit

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 14/6/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>960</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>36.1</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>210</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>-1</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>2</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (58°C - 70°C)	<u>50</u> °C <u>70</u> °C
- Engine speed	<u>2,200</u> rpm <u>2,200</u> rpm
- Check current charging to battery	<u>0.2, 0.6</u> amp <u>0.6, 1.4</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>218</u> psi
- Pressure relief valve maintain pressure at	<u>210</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>960</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>36.3</u> hrs.

Time start 15:30 Time stop 15:40Total 10 mins

Supervisor's comments _____

Record by Bmm

SOMERSET

RAMA 3
BANGKOK

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 7/1/86

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>270</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>35.9</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>949</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>55</u> bar Running (10 mins) <u>0-5</u> bar
- Cooling water temp (50°C - 70°C)	<u>50</u> °C <u>70</u> °C
- Engine speed	<u>2,200</u> rpm <u>2,200</u> rpm
- Check current charging to battery	<u>0.2, 0.6</u> amp <u>0-7, 1.5</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>949</u> psi
- Pressure relief valve maintain pressure at	<u>940</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>270</u> ltrs. Add <u>-</u> ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>36.1</u> hrs.
- Record hours meter reading	

Time start 15.27 Time stop 19.37Total 10 mins

Supervisor's comments _____

Record by Bm

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 31/5/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>920</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>33.8</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>257</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0.0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>50</u> °C <u>20</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.3, 0.6</u> amp <u>0.6, 1.3</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>250</u> psi
- Pressure relief valve maintain pressure at	<u>240</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	() Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>920</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>33.9</u> hrs.

Time start 10.04 Time stop 10.09

Total 10 mins

Supervisor's comments _____

Record by

Pran

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 21/5/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>180</u> ltrs. Add _____ ltrs.
- Clean air filter	(/) clean () dirty, cleaned
- Record hours meter reading	<u>35.6</u> hrs.
BATTERY	
- Check current charging to battery	(/) charge () No charge
- Check battery terminals	(/) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (/) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(/) clean () dirty, cleaned
- Check pressure recorder in system	<u>257</u> psi
- Check valves for free travel	(/) normal () abnormal _____
- Suction pressure	<u>-1</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>70</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.2, 0.6</u> amp <u>1.7, 2.6</u> amp
- Check for leaks around the engine	(/) Normal () leak _____
- Noises	(/) Normal () abnormal _____
- Vibration	(/) Normal () abnormal _____
- Smoke	(/) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>230</u> psi
- Pressure relief valve maintain pressure at	<u>210</u> psi
- Check for leaks around the pump & piping	(/) Normal () leak _____
- Check mechanical seal / packing for leak	(/) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>180</u> ltrs. Add _____ ltrs.
- Record hours meter reading	_____ hrs.

Time start 16.00 Time stop 16.10

Total 10 mins

Supervisor's comments

Record by

Bmm

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 17/5/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>980</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>35.5</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>251</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>0</u> bar
- Cooling water temp (50°C - 70°C)	<u>50</u> °C <u>70</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.2, 0.6</u> amp <u>2.6, 3.3</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>250</u> psi
- Pressure relief valve maintain pressure at	<u>240</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>980</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>35.6</u> hrs.

Time start 15.02 Time stop 16.02

Total 10 mins

Supervisor's comments _____

Record by

Bmm

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 10/01/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>995</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>35.8</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	() tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>251</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>-1</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>60</u> °C <u>70</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.2, 0.5</u> amp <u>0.6, 1.4</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>250</u> psi
- Pressure relief valve maintain pressure at	<u>210</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>995</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>35.4</u> hrs.

Time start 10.25 Time stop 10.35

Total 10 mins

Supervisor's comments _____

Record by 

SOMERSET

RAMA 9
SANGKOK

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE

3/5/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>1000</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>35.1</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>220</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.6</u> bar Running (10 mins) <u>5.6</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>70</u> °C
- Engine speed	<u>2200</u> rpm <u>2900</u> rpm
- Check current charging to battery	<u>28.7</u> 13.9 amp <u>13.8</u> 1.8A amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>995</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>35.2</u> hrs.

Time start 15:51 Time stop 16:01Total 10 mins

Supervisor's comments

Record by

Khiangsaik

SOMERSET

RAMA 9
BANGKOK

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 26/04/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>1700</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>35.0</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.5</u> bar Running (10 mins) <u>5.4</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.7 / 3.1</u> amp <u>4.3 / 0.0</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>1,000</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>35.1</u> hrs.

Time start 15.15 Time stop 15.25Total 10 mins

Supervisor's comments _____

Record by

Anuchit

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 19/09/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>1000</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>34.9</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80°</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.5/1.6</u> amp <u>2.3/3.7</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>1,000</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>35.0</u> hrs.
- Record hours meter reading	

Time start 15.30 Time stop 15.40

Total 10 mins

Supervisor's comments _____

Record by

Anuchit

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 12/04/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>1000</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>34.7</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>23/2.9</u> amp <u>0.6/1.4</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>1000</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>34.9</u> hrs.
- Record hours meter reading	

Time start 16.20 Time stop 16.30

Total 10 mins

Supervisor's comments _____

Record by

Anuchit



WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 5/4/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>1000</u> ltrs. Add _____ ltrs.
- Clean air filter	(✓) clean () dirty, cleaned
- Record hours meter reading	<u>34.5</u> hrs.
BATTERY	
- Check current charging to battery	(✓) charge () No charge
- Check battery terminals	(✓) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (✓) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(✓) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	() normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>0.5</u> bar Running (10 mins) <u>80.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>78</u> °C
- Engine speed	<u>2200</u> rpm <u>2900</u> rpm
- Check current charging to battery	<u>13.9v 0.7A</u> amp <u>13.9v 1.4A</u> amp
- Check for leaks around the engine	(✓) Normal () leak
- Noises	(✓) Normal () abnormal _____
- Vibration	(✓) Normal () abnormal _____
- Smoke	(✓) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>220</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(✓) Normal () leak _____
- Check mechanical seal / packing for leak	(✓) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(✓) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>1000</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>34.7</u> hrs.


Time start 14:30 Time stop 14:40

Total 10 mins

Supervisor's comments _____

Record by

Kaangsak



WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 29/3/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>1000</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>34.4</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.0</u> bar Running (10 mins) <u>4.8</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>2.1/3.5</u> amp <u>42/0.0</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>1000</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>34.5</u> hrs.

Time start 15.30 Time stop 15.40

Total 10 mins

Supervisor's comments _____

Record by

Anuchit



WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 22/3/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>850</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>34.2</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>230</u> psi
- Check valves for free travel	() normal () abnormal _____
- Suction pressure	<u>-</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.</u> bar Running (10 mins) <u>4.8</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>7.1/1.4</u> amp <u>4.2/0.0</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>240</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>850</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>34.4</u> hrs.

Time start 15.20 Time stop 15.30

Total 10 mins

Supervisor's comments _____

Record by

Anuchit



WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 15/03/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>870</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>33.5</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>100</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>220</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>75</u> bar Running (10 mins) <u>70</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>1.9/0.7</u> amp <u>1.6/0.5</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>250</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>870</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>33.7</u> hrs.

Time start 15.20 Time stop 15.30

Total 10 mins

Supervisor's comments _____

Record by

Anuchit



WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 8-3-26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>885</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>33.4</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	() tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>100</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>80</u> °C
- Engine speed	<u>21</u> rpm <u>22</u> rpm
- Check current charging to battery	<u>2.5 / 3.1</u> amp <u>4.3 / 10.0</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>250</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>880</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>33.5</u> hrs.
- Record hours meter reading	

Time start 15.34 Time stop 15.44

Total 10 mins

Supervisor's comments _____

Record by

S. K. K.

[Signature]

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 1-3-26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>880</u> ltrs. Add _____ ltrs.
- Clean air filter	() clean () dirty, cleaned
- Record hours meter reading	<u>33.2</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	() tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>100</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5.5</u> bar Running (10 mins) <u>5.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>42</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.8 / 1.06</u> amp <u>0.5 / 1.6</u> amp
- Check for leaks around the engine	() Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>250</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>890</u> ltrs. Add <u>-</u> ltrs.
- Record hours meter reading	<u>33.4</u> hrs.

Time start 15.11 Time stop 15.21

Total 10 mins

Supervisor's comments _____

Record by

S. Mahajan, Piyapong

[Signature]

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 22/2/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>890</u> ltrs. Add _____ ltrs.
- Clean air filter	(/) clean () dirty, cleaned
- Record hours meter reading	<u>33.1</u> hrs.
BATTERY	
- Check current charging to battery	(/) charge () No charge
- Check battery terminals	() tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (/) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(/) clean () dirty, cleaned
- Check pressure recorder in system	<u>100</u> psi
- Check valves for free travel	(/) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>45</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.1, 0.5</u> amp <u>0.6, 1.3</u> amp
- Check for leaks around the engine	(/) Normal () leak _____
- Noises	(/) Normal () abnormal _____
- Vibration	(/) Normal () abnormal _____
- Smoke	(/) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>229</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(/) Normal () leak _____
- Check mechanical seal / packing for leak	(/) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>890</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>33.2</u> hrs.

Time start 15.35 Time stop 15.45

Total 10 mins

Supervisor's comments _____

Record by

Ban

[Signature]

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 15/2/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>890</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>32.9</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	() tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>239</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>60</u> °C <u>70</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.3.0.A</u> amp <u>2.2, 2.8</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>239</u> psi
- Pressure relief valve maintain pressure at	<u>150</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>890</u> ltrs. Add _____ ltrs.
- Record hours meter reading	<u>33.1</u> hrs.

Time start 12.48 Time stop 13.58

Total 10 mins

Supervisor's comments _____

Record by

Bm

Sp

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE

01/2/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ <u>1000</u> Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs)	Full level <u>870</u> ltrs. Add <u>870</u> ltrs.
- Clean air filter	(/) clean () dirty, cleaned
- Record hours meter reading	<u>32.7</u> hrs.
BATTERY	
- Check current charging to battery	(/) charge () No charge
- Check battery terminals	(/) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (/) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(/) clean () dirty, cleaned
- Check pressure recorder in system	_____ psi
- Check valves for free travel	(/) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>3</u> bar
- Cooling water temp (58°C - 70°C)	<u>32</u> °C <u>80</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.0/0.4</u> amp <u>0.6/1.4</u> amp
- Check for leaks around the engine	(/) Normal () leak _____
- Noises	(/) Normal () abnormal _____
- Vibration	(/) Normal () abnormal _____
- Smoke	(/) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>239</u> psi
- Pressure relief valve maintain pressure at	<u>120</u> psi
- Check for leaks around the pump & piping	(/) Normal () leak _____
- Check mechanical seal / packing for leak	(/) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(/) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>1000</u> ltrs. Add <u>865</u> ltrs.
- Record hours meter reading	<u>32.8</u> hrs.

Time start 15.16 Time stop 15.26Total 70 mins

Supervisor's comments _____

Record by

artitX

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 1/2/23

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs)	Full level <u>850</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>32.5</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	() tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>239</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (58°C - 70°C)	<u>46</u> °C <u>70</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.0, 0.4</u> amp <u>0.6, 1.3</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>239</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>850</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>32.7</u> hrs.

Time start 15.29 Time stop 15.39Total 10 mins

Supervisor's comments _____

Record by _____

BmuR

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 25/1/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs)	Full level <u>900</u> ltrs. Add <u>-</u> ltrs.
- Clean air filter	(☒) clean () dirty cleaned
- Record hours meter reading	<u>39.3</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>238</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>20</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.1, 0.1</u> amp <u>0.7, 1.4</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>238</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>900</u> ltrs. Add <u>-</u> ltrs.
- Record hours meter reading	<u>39.5</u> hrs.

Time start 15.25 Time stop 16.35Total 10 mins

Supervisor's comments _____

Record by Bur JB

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 18/01/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add <u>1</u> ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>900</u> ltrs. Add <u>1</u> ltrs.
- Clean air filter	☒ clean () dirty cleaned
- Record hours meter reading	<u>321</u> hrs.
BATTERY	
- Check current charging to battery	☒ charge () No charge
- Check battery terminals	☒ tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow ☒ green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	☒ clean () dirty, cleaned
- Check pressure recorder in system	<u>238</u> psi
- Check valves for free travel	☒ normal () abnormal
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>80</u> psi Running (10 mins) <u>5 bar/80 psi</u> psi
- Cooling water temp (58°C - 70°C)	<u>50</u> °C <u>70°C</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.0/4.7</u> amp <u>0.6/1.3</u> amp
- Check for leaks around the engine	☒ Normal () leak
- Noises	☒ Normal () abnormal
- Vibration	☒ Normal () abnormal
- Smoke	☒ Normal () abnormal
PUMP AND PIPING	
- Check line pressure	<u>238</u> psi
- Pressure relief valve maintain pressure at	<u>150</u> psi
- Check for leaks around the pump & piping	☒ Normal () leak
- Check mechanical seal / packing for leak	☒ Normal () leak
- Examine for abnormal noise, heat, vibration	☒ Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>890</u> ltrs. Add <u>1</u> ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>32.3</u> hrs.

Time start 16.13 hrs. Time stop 16.23 hrs.Total 10 mins

Supervisor's comments

Record by

Koitsanapoj PhanareePimp

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 11/1/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>900</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>31.9</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>236</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>5</u> bar Running (10 mins) <u>5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>20</u> °C
- Engine speed	<u>2200</u> rpm <u>2200</u> rpm
- Check current charging to battery	<u>0.1, 0.6</u> amp <u>1.0, 1.7</u> amp
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>236</u> psi
- Pressure relief valve maintain pressure at	<u>110</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	Full level <u>900</u> ltrs. Add _____ ltrs.
- Diesel fuel tank level (750 - 850 Ltrs.)	<u>32.1</u> hrs.
- Record hours meter reading	

Time start 16.02 Time stop 16.12Total 10 mins

Supervisor's comments _____

Record by _____

*Bmw**Dimp*

SOMERSET

WEEKLY FIRE PUMP WARM - UP LOG SHEET

ENGINEER DEPARTMENT

DATE 4/1/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level	Full ☒ Low ☐ () add _____ ltrs.
- Diesel fuel tank level (750 - 1,000 Ltrs.)	Full level <u>900</u> ltrs. Add _____ ltrs.
- Clean air filter	(☒) clean () dirty, cleaned
- Record hours meter reading	<u>31.4</u> hrs.
BATTERY	
- Check current charging to battery	(☒) charge () No charge
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
GENERAL	
- Water in serving tank	Full ☒ Low ☐
- Clean control panel	(☒) clean () dirty, cleaned
- Check pressure recorder in system	<u>213</u> psi
- Check valves for free travel	(☒) normal () abnormal _____
- Suction pressure	<u>0</u> psi
OPERATIONAL CHECK	
ENGINE	
- Check lubricating oil pressure	Started <u>0</u> bar Running (10 mins) <u>80.5</u> bar
- Cooling water temp (50°C - 70°C)	<u>40</u> °C <u>70</u> °C
- Engine speed	<u>2200</u> rpm <u>22.00</u> rpm
- Check current charging to battery	<u>0.1, 0.1</u> amp <u>0.6, 1.3</u> amp
- Check for leaks around the engine	(☒) Normal () leak _____
- Noises	(☒) Normal () abnormal _____
- Vibration	(☒) Normal () abnormal _____
- Smoke	(☒) Normal () abnormal _____
PUMP AND PIPING	
- Check line pressure	<u>213</u> psi
- Pressure relief valve maintain pressure at	<u>145</u> psi
- Check for leaks around the pump & piping	(☒) Normal () leak _____
- Check mechanical seal / packing for leak	(☒) Normal () leak _____
- Examine for abnormal noise, heat, vibration	(☒) Normal () abnormal _____
AFTER ENGINE STOP	
- Record diesel fuel system	
- Diesel fuel tank level (750 - 850 Ltrs.)	Full level <u>900</u> ltrs. Add <u>-</u> ltrs.
- Record hours meter reading	<u>31.9</u> hrs.

Time start 15.55 Time stop 16.05Total 10 mins

Supervisor's comments _____

Record by

BaumPrings

SOMERSET

RAMA 9
BANGKOK

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 2006/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>65.2</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7</u> amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.3</u> psi Running (10 mins) <u>5.4</u> psi
- Cooling water temp (70°C - 80°C)	<u>33</u> °C <u>70</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>27.6</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u>-</u> A. L2 <u>-</u> A. L3 <u>-</u> A
- Record kilowatt reading	L1 <u>-</u> Kw. L2 <u>-</u> Kw. L3 <u>-</u> Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	<u>65.4</u> hrs.
- Record hours meter reading	(☒) Normal () abnormal
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	<u>3/4</u> ltrs.
- Present fuel level	

Time start 15.51 Time stop 16.01Total 10 mins

Supervisor's comments

Record by Manu

Verified by _____

SOMERSET

RAMA 9
SANGKOK

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 21/06/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4 +</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>65</u> hrs.
BATTERY	
- check current charging to battery	_____ amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.39 bar</u> psi Running (10 mins) <u>5.18 bar</u> psi
- Cooling water temp (70°C - 80°C)	<u>34</u> °C <u>70</u> °C
- Engine speed 1500 rpm.	<u>1499</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>27.9</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>65.2</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>3/4 +</u> ltrs.

Time start 16.45 Time stop 16.55Total 10 mins

Supervisor's comments _____

Record by Anuchit

Verified by _____

SOMERSET

RAMA 9
BANGKOK

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 1A/6/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>64.8</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7</u> amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.3</u> psi Running (10 mins) <u>0.3</u> psi
- Cooling water temp (70°C - 80°C)	<u>35</u> °C <u>68</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>28.0</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u>-</u> A. L2 <u>-</u> A. L3 <u>-</u> A
- Record kilowatt reading	L1 <u>-</u> Kw. L2 <u>-</u> Kw. L3 <u>-</u> Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	<u>65.0</u> hrs.
- Record hours meter reading	(☒) Normal () abnormal
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	<u>3/4</u> ltrs.
- Present fuel level	

Time start 15.45 Time stop 15.55

Total 10 mins

Supervisor's comments

Record by Bhu

Verified by _____

SOMERSET

RAMA 9
BANGKOK

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 7/6/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>62.6</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7 V</u> amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.3</u> psi Running (10 mins) <u>8.6</u> psi
- Cooling water temp (70°C - 80°C)	<u>35</u> °C <u>70</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>26.7 V</u> Volt. <u>26.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u>-</u> A. L2 <u>-</u> A. L3 <u>-</u> A
- Record kilowatt reading	L1 <u>-</u> Kw. L2 <u>-</u> Kw. L3 <u>-</u> Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>46.7</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	_____ ltrs.

Time start 15.42 Time stop 15.52Total 10 mins

Supervisor's comments _____

Record by Bhuvan

Verified by _____

SOMERSET

RAMA 9
SANGKOK

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE

31/5/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>314</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>64.4</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7</u> v amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.24</u> psi Running (10 mins) <u>5.38</u> psi
- Cooling water temp (70°C - 80°C)	<u>35</u> °C <u>70</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>26.7</u> Volt. <u>28.0</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u>-</u> A. L2 <u>-</u> A. L3 <u>-</u> A
- Record kilowatt reading	L1 <u>-</u> Kw. L2 <u>-</u> Kw. L3 <u>-</u> Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>64.5</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>314</u> ltrs.

Time start 15.19 Time stop 15.29Total 10 mins

Supervisor's comments

Record by Dina

Verified by _____

SOMERSET

RAMA 9
SANGKOK

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 21/3/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>6A.2</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7</u> V amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>3.37</u> psi Running (10 mins) <u>5.22</u> psi
- Cooling water temp (70°C - 80°C)	<u>34</u> °C <u>68</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>26.7</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>232</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u>-</u> A. L2 <u>-</u> A. L3 <u>-</u> A
- Record kilowatt reading	L1 <u>-</u> Kw. L2 <u>-</u> Kw. L3 <u>-</u> Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	<u>64.2</u> hrs.
- Record hours meter reading	(☒) Normal () abnormal
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	<u>3/4</u> ltrs.
- Present fuel level	

Time start 16.15 Time stop 16.25Total 10 mins

Supervisor's comments _____

Record by Berni

Verified by _____

SOMERSET

RAMA 9
BANGKOK

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 17/6/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>64.1</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7</u> V amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>60</u> psi Running (10 mins) <u>5.30</u> psi
- Cooling water temp (70°C - 80°C)	<u>33</u> °C _____ °C
- Engine speed 1500 rpm.	<u>0</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>27.6</u> Volt. <u>283</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	<u>64.2</u> hrs.
- Record hours meter reading	(☒) Normal () abnormal
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	<u>3/4</u> ltrs.
- Present fuel level	

Time start 16.05 Time stop 16.10Total 10 mins

Supervisor's comments _____

Record by Bm

Verified by _____

SOMERSET

RAMA 9
BANGKOK

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 10/5/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>1700</u> ltrs. Add <u> </u> ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal (☐) abnormal
- Remove foreign body in cooling system	(☒) OK (☐) removed
- Record hours meter reading	<u>63.7</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7</u> V amp.
- Check battery terminals	(☒) tight, clean (☐) loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	(☐) red (☐) yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>3.31</u> psi Running (10 mins) <u>6.29</u> psi
- Cooling water temp (70°C - 80°C)	<u>33</u> °C <u>60</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>60</u> Hz <u>60</u> Hz
- Check volt charging to battery	<u>26.7</u> Volt. <u>27.8</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u> </u> A. L2 <u> </u> A. L3 <u> </u> A
- Record kilowatt reading	L1 <u> </u> Kw. L2 <u> </u> Kw. L3 <u> </u> Kw
- Check for leaks around the engine	(☒) Normal (☐) leak
- Noises	(☒) Normal (☐) abnormal
- Vibration	(☒) Normal (☐) abnormal
- Smoke	(☒) Normal (☐) abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>64.0</u> hrs.
- Selector Sw auto run	(☒) Normal (☐) abnormal
- Generator CB (Closed)	(☒) Normal (☐) abnormal
- Present fuel level	<u>1700</u> ltrs.

Time start 15.45 Time stop 15.55Total 10 mins

Supervisor's comments

Record by Verified by

SOMERSET

RAMA 9
SANGKOK

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE

3/5/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>1700</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>63.6</u> hrs.
BATTERY	
- check current charging to battery	_____ amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.3 bar</u> psi Running (10 mins) <u>5.40 bar</u> psi
- Cooling water temp (70°C - 80°C)	<u>35</u> °C <u>57</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1502</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>28.1</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>1700</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>63.7</u> ltrs.

Time start 16:20 Time stop 16:30Total 10 mins

Supervisor's comments

Record by Kriangsak

Verified by _____

SOMERSET

RAMA 9
BANGKOK

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE

26/04/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>1700</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>63.5</u> hrs.
BATTERY	
- check current charging to battery	_____ amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.38 bar</u> psi Running (10 mins) <u>5.38 bar</u> psi
- Cooling water temp (70°C - 80°C)	<u>34</u> °C <u>58</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1502</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>28.1</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>63.6</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>1700</u> ltrs.

Time start 15.30Time stop 15.40Total 10 mins

Supervisor's comments

Record by

Anvchit

Verified by

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 19/04/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>1700</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>63.3</u> hrs.
BATTERY	
- Check current charging to battery	_____ amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.33 bar</u> psi Running (10 mins) <u>5.34 bar</u> psi
- Cooling water temp (70°C - 80°C)	<u>42</u> °C <u>63</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>28.1</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>63.5</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>17.00</u> ltrs.

Time start 15.45 Time stop 15.55

Total 10 mins

Supervisor's comments _____

Record by Anuchit

Verified by _____

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 12/04/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>1700</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>63.1</u> hrs.
BATTERY	
- check current charging to battery	_____ amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.38 bar</u> psi Running (10 mins) <u>5.03 bar</u> psi
- Cooling water temp (70°C - 80°C)	<u>35</u> °C <u>77</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1499</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>28</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Reord diesel fuel system	
- Record hours meter reading	<u>63.3</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>1700</u> ltrs.

Time start 16.00 Time stop 16.10

Total 10 mins

Supervisor' s comments _____

Record by Anuchit

Verified by 

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 5/4/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>1300</u> ltrs. Add <u>900</u> ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>62.9</u> hrs.
BATTERY	
- Check current charging to battery	<u>0</u> amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.39</u> psi Running (10 mins) <u>5.41</u> psi
- Cooling water temp (70°C - 80°C)	<u>42</u> °C <u>61</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>28.1</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>1700</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>63.0</u> ltrs.

Time start 14:02 Time stop 14:12

Total 10 mins

Supervisor's comments _____

Record by Khiansak

Verified by [Signature]

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 29/3/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>1500</u> ltrs. Add <u>200</u> ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>62.8</u> hrs.
BATTERY	
- check current charging to battery	<u>0</u> amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.38 bar</u> psi Running (10 mins) _____ psi
- Cooling water temp (70°C - 80°C)	<u>33</u> °C _____ °C
- Engine speed 1500 rpm.	<u>1501</u> rpm _____ rpm
- Frequency 50 Hz.	<u>50</u> Hz _____ Hz
- Check volt charging to battery	<u>27.9</u> Volt. _____ Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>62.9</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>1700</u> ltrs.

Time start 15.00 Time stop 15.10

Total 10 mins

Supervisor's comments _____

Record by Anuchit

Verified by [Signature]

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 22/3/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>62.6</u> hrs.
BATTERY	
- Check current charging to battery	_____ amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.40 bar</u> psi Running (10 mins) <u>5.17 bar</u> psi
- Cooling water temp (70°C - 80°C)	<u>32</u> °C <u>70</u> °C
- Engine speed 1500 rpm.	<u>1499</u> rpm <u>1501</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>27.7</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>62.7</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>3/4</u> ltrs.

Time start 15.00 Time stop 15.10

Total 10 mins

Supervisor's comments _____

Record by Anuchit

Verified by [Signature]

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 15/03/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>62.4</u> hrs.
BATTERY	
- check current charging to battery	_____ amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.32 bar</u> psi Running (10 mins) <u>5.17 bar</u> psi
- Cooling water temp (70°C - 80°C)	<u>34</u> °C <u>71</u> °C
- Engine speed 1500 rpm.	<u>1501</u> rpm <u>1499</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>27.8</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>62.5</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>3/4</u> ltrs.

Time start 15.00 Time stop 15.10

Total 10 mins

Supervisor's comments _____

Record by Anuchit

Verified by 

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 08/03/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4+</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>62.2</u> hrs.
BATTERY	
- Check current charging to battery	_____ amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.49 Bar</u> psi Running (10 mins) <u>5.41 Bar</u> psi
- Cooling water temp (70°C - 80°C)	<u>35°C</u> °C <u>61°C</u> °C
- Engine speed 1500 rpm.	<u>1499</u> rpm <u>1501</u> rpm
- Frequency 50 Hz.	<u>50.0</u> Hz <u>50.0</u> Hz
- Check volt charging to battery	<u>28.0</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>62.4</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>3/4+</u> ltrs.

Time start 15.20 Time stop 15.30

Total 10 mins

Supervisor's comments _____

Record by Anuchit

Verified by [Signature]

SOMERSET

RAMA 9
BANGKOK

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 1-3-26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	() OK () removed
- Record hours meter reading	<u>61.4</u> hrs.
BATTERY	
- Check current charging to battery	<u>28.1</u> amp.
- Check battery terminals	() tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.37</u> psi Running (10 mins) <u>5.42</u> psi
- Cooling water temp (70°C - 80°C)	<u>35</u> °C <u>61</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1501</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>28</u> Volt. <u>28</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	() Normal () leak
- Noises	() Normal () abnormal
- Vibration	() Normal () abnormal
- Smoke	() Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>61.5</u> hrs.
- Selector Sw auto run	() Normal () abnormal
- Generator CB (Closed)	() Normal () abnormal
- Present fuel level	_____ ltrs.

Time start 15.37 Time stop 15.47

Total 10 mins

Supervisor's comments _____

Record by Sattaporn, Piyapong

Verified by [Signature]

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 22/2/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>314</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>61.3</u> hrs.
BATTERY	
- Check current charging to battery	<u>26.5</u> V amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>0.35</u> psi Running (10 mins) <u>0.45</u> psi
- Cooling water temp (70°C - 80°C)	<u>57</u> °C <u>60</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>28.1</u> Volt. <u>27.9</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u>—</u> A. L2 <u>—</u> A. L3 <u>—</u> A
- Record kilowatt reading	L1 <u>—</u> Kw. L2 <u>—</u> Kw. L3 <u>—</u> Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>61.4</u> hrs.
- Selector Sw auto run	() Normal () abnormal
- Generator CB (Closed)	() Normal () abnormal
- Present fuel level	<u>314</u> ltrs.

Time start 15.40 Time stop 15.50

Total 10 mins

Supervisor's comments _____

Record by 

Verified by 

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 16/2/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>61.0</u> hrs.
BATTERY	
- Check current charging to battery	<u>26.2 V</u> amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>0.33</u> psi Running (10 mins) <u>0.32</u> psi
- Cooling water temp (70°C - 80°C)	<u>33</u> °C <u>74</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>28.0</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>61.3</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>3/4</u> ltrs.

Time start 16.08 Time stop 16.18

Total 10 mins

Supervisor's comments _____

Record by Bum

Verified by [Signature]

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET



NO LOAD



WITH LOAD

DATE 8/2/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>4/4</u> ltrs. Add <u>3/4</u> ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>60.6</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7V</u> amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.1</u> bar 5.5 Running (10 mins) <u>5.5</u> bar
- Cooling water temp (70°C - 80°C)	<u>31</u> °C <u>71</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>26.7</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 _____ A. L2 _____ A. L3 _____ A
- Record kilowatt reading	L1 _____ Kw. L2 _____ Kw. L3 _____ Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>61.0</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>3/4</u> ltrs.

Time start 15.34 Time stop 15.44

Total 10 mins

Supervisor's comments _____

Record by ART/H

Verified by [Signature]

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET

☒ NO LOAD

☐ WITH LOAD

DATE 1/12/24

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>60.6</u> hrs.
BATTERY	
- check current charging to battery	<u>26.2 V</u> amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.34</u> psi Running (10 mins) <u>5.18</u> psi
- Cooling water temp (70°C - 80°C)	<u>32</u> °C <u>75</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>27.6</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u>-</u> A. L2 <u>-</u> A. L3 <u>-</u> A
- Record kilowatt reading	L1 <u>-</u> Kw. L2 <u>-</u> Kw. L3 <u>-</u> Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	<u>60.8</u> hrs.
- Record hours meter reading	(☒) Normal () abnormal
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	<u>3/4</u> ltrs.
- Present fuel level	

Time start 15.45 Time stop 16.55 Total 10 mins

Supervisor's comments _____

Record by [Signature]

Verified by [Signature]

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET

☒ NO LOAD

☐ WITH LOAD

DATE 25/1/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add _____ ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>60.4</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7</u> V amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.28</u> bar ^{25°} Running (10 mins) <u>5.34</u> bar ^{25°}
- Cooling water temp (70°C - 80°C)	<u>35.0</u> °C <u>60</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>28.1</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u>-</u> A. L2 <u>-</u> A. L3 <u>-</u> A
- Record kilowatt reading	L1 <u>-</u> Kw. L2 <u>-</u> Kw. L3 <u>-</u> Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Reord diesel fuel system	
- Record hours meter reading	<u>60.6</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	_____ ltrs.

Time start 10.42 Time stop 15.52

Total 10 mins

Supervisor' s comments _____

Record by Dan

Verified by [Signature]

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET

☒ NO LOAD

☐ WITH LOAD

DATE 18/1/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add <u>-</u> ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>60.2</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7</u> amp. V.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.38 bar</u> psi Running (10 mins) <u>5.38-5.40</u> psi bar
- Cooling water temp (70°C - 90°C)	<u>31</u> °C <u>66</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>403 28.1</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u>0</u> A. L2 <u>0</u> A. L3 <u>0</u> A
- Record kilowatt reading	L1 <u>0</u> Kw. L2 <u>0</u> Kw. L3 <u>0</u> Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	<u>60.4</u> hrs.
- Record hours meter reading	(☒) Normal () abnormal
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	<u>3/4</u> ltrs.
- Present fuel level	

Time start 15.53 hr. Time stop 16.00 hr.

Total 10 mins

Supervisor's comments _____

Record by Kritsanguj Manaree

Verified by Pring

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET

☒ NO LOAD

☐ WITH LOAD

DATE 11/1/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add <u> </u> ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>60.0</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7</u> V amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>5.21</u> psi Running (10 mins) <u>5.36</u> psi
- Cooling water temp (70°C - 90°C)	<u>30</u> °C <u>65</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>28.1</u> Volt. <u>28.1</u> Volt.
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V. L2-N <u>233</u> V. L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V. L2-L3 <u>403</u> V. L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u> </u> A. L2 <u> </u> A. L3 <u> </u> A
- Record kilowatt reading	L1 <u> </u> Kw. L2 <u> </u> Kw. L3 <u> </u> Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>60.2</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>3/4</u> ltrs.

Time start 16.22 Time stop 16.32 Total 10 mins

Supervisor's comments _____

Record by Danu

Verified by Danu

WEEKLY DIESEL GENERATOR WARM - UP LOG SHEET

☒ NO LOAD

☐ WITH LOAD

DATE 4/1/26

DESCRIPTION	RESULT
PRE START UP INSPECTION	
ENGINE	
- Check engine lubrication oil level (Full)	Full ☒ Low ☐
- Diesel fuel tank level (800 - 1000 Ltrs.)	Full level <u>3/4</u> ltrs. Add <u>-</u> ltrs.
- Check coolant level	Full ☒ Low ☐
- Check fan guard clearance	(☒) Normal () abnormal
- Remove foreign body in cooling system	(☒) OK () removed
- Record hours meter reading	<u>59.9</u> hrs.
BATTERY	
- check current charging to battery	<u>26.7</u> V amp.
- Check battery terminals	(☒) tight, clean () loose, tightened
- Check distilled water level	Full ☒ Low ☐
- Record SP.G. level	() red () yellow (☒) green
OPERATIONAL CHECK	
- Check lubricating oil pressure	Started <u>3.30</u> psi Running (10 mins) <u>5.40</u> psi
- Cooling water temp (70°C - 90°C)	<u>31</u> °C <u>64</u> °C
- Engine speed 1500 rpm.	<u>1500</u> rpm <u>1500</u> rpm
- Frequency 50 Hz.	<u>50</u> Hz <u>50</u> Hz
- Check volt charging to battery	<u>27.8</u> Volt <u>28.1</u> Volt
- Record - voltmeter reading (Line - Nutral)	L1-N <u>233</u> V L2-N <u>233</u> V L3-N <u>233</u> V
- Record - voltmeter reading (Line - Line)	L1-L2 <u>403</u> V L2-L3 <u>403</u> V L3-L1 <u>403</u> V
- Record - Amp meter reading	L1 <u>-</u> A L2 <u>-</u> A L3 <u>-</u> A
- Record kilowatt reading	L1 <u>-</u> Kw L2 <u>-</u> Kw L3 <u>-</u> Kw
- Check for leaks around the engine	(☒) Normal () leak
- Noises	(☒) Normal () abnormal
- Vibration	(☒) Normal () abnormal
- Smoke	(☒) Normal () abnormal
AFTER ENGINE STOP	
- Record diesel fuel system	
- Record hours meter reading	<u>60.00</u> hrs.
- Selector Sw auto run	(☒) Normal () abnormal
- Generator CB (Closed)	(☒) Normal () abnormal
- Present fuel level	<u>-</u> ltrs.

Time start 16.13 Time stop 16.23 Total 10 mins

Supervisor's comments

Record by Pan

Verified by Pan

สำเนาแบบบันทึกการตรวจสอบระบบป้องกันอัคคีภัยของโครงการ

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry	1	✓			
2		FHC - Front of FCC	Dry	1	✓			
3		Gas Station (15 lbs)	Dry	2	✓			
4		Front of Garbage Room	Dry	1	✓			
5		Front of Housekeeping Store	Dry	1	✓			
6		Fire Cart	Dry	1	✓			
7		Security Store	Dry	8	✓			Recharge 4, แห้ง 1 ร้า 1, (ส่งอำนวยการ 1)
8		Security Store (15 lbs)	Dry	3	✓			เคมีแห้ง 1
9		Security Store (20 lbs)	Dry	2	✓			
10		In front of Electrical room (50lbs)	Dry	2	✓			
11		Security Store	ADE	4	✓			
12		Electrical Room	ADE	1	✓			
13		Engineering Workshop	ADE	2	✓			
14		Engineering Store	ADE	1	✓			
15		Chemical Room	ADE	2	✓			
16		Houskeeping Store	ADE	1	✓			
17		Houskeeping Office	ADE	1	✓			
18		FCC Room	ADE	1	✓			
19		Fire Pump Room	ADE	2	✓			
20		Finance Accounting Office	ADE	1	✓			
21		Staff Canteen Room	ADE	1	✓			
22		Fire Cart	CO2	1	✓			
23		FCC Room	CO2	1	✓			
24		Security Store	CO2	10	✓			1 น้ำหนักต่ำเกณฑ์
25		Fire Pump Room	Dry	1	✓			
26		Front of Timekeeper	Dry	1	✓			
27	G	FHC - Front of Service Lift	Dry	1	✓			
25		MDB and Generator	ADE	2	✓			
26		Server Room	ADE	2	✓			
27		Guest Service Office	ADE	1	✓			
28		Executive Office	ADE	1	✓			
29		Server Room	CO2	1	✓			
30		FHC - Front of Saver Room	CO2	1	✓			
31	2	FHC - Front ST-2	Dry	1	✓			
32		FHC - Front of Service Lift	Dry	1	✓			
33		Front of First aid Room	Dry	1	✓			
34		Front of HK Store	Dry	1	✓			
35		Rama 9 Sound Control Room	CO2	1	✓			
36		FHC - Front of ST-1	Dry	1	✓			
37	3	FHC - Front of ST-2	Dry	1	✓			
38		FHC - Front of Service Lift	Dry	1	✓			Overcharge
18		Front of Guest Lift	Dry	1	✓			Overcharge
19		FHC - Front of ST-1	Dry	1	✓			
20		Parking Area Zone 4B	Dry	1	✓			
21	4	FHC - Front of ST-2	Dry	1	✓			
22		Parking Area Zone 2A	Dry	1	✓			
23		FHC - Front of Service Lift	Dry	1	✓			
24		Front of Guest Lift	Dry	1	✓			Overcharge
25		FHC - Front of ST-1	Dry	1	✓			Overcharge
26		Parking Area Zone 4B	Dry	1	✓			Overcharge
27		FHC - Front of ST-2	Dry	1	✓			Overcharge
28		Parking Area Zone 2A	Dry	1	✓			Overcharge
29		Parking Area Zone 8A	Dry	1	✓			Overcharge
30		Parking Area Zone C	Dry	1	✓			Overcharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
31	5	FHC - Front of Service Lift	Dry	1	✓			Overcharge
32		Front of Guest Lift	Dry	1	✓			Overcharge
33		FHC - Front of ST-1	Dry	1	✓			
34		Parking Area Zone 4B	Dry	1	✓			
35		FHC - Front of ST-2	Dry	1	✓			
36		Parking Area Zone 2A	Dry	1	✓			Overcharge
37		Parking Area Zone 8A	Dry	1	✓			
38		Parking Area Zone C	Dry	1	✓			
39	6	FHC - Front of Service Lift	Dry	1	✓			
40		Front of Guest Lift	Dry	1	✓			
41		FHC - Front of ST-1	Dry	1	✓			
42		Parking Area Zone 4B	Dry	1	✓			
43		Inside ST-2	Dry	1	✓			
44		FHC - Front of ST-2	Dry	1	✓			
45		Parking Area Zone 2A	Dry	1	✓			
46		Parking Area Zone 8A	Dry	1	✓			
47		Parking Area Zone C	Dry	1	✓			Overcharge
48	7	FHC - Front of Service Lift	Dry	1	✓			
49		Front of Guest Lift	Dry	1	✓			
50		FHC - Front of ST-1	Dry	1	✓			
51		Parking Area Zone 4B	Dry	1	✓			
52		Inside ST-2	Dry	1	✓			Overcharge
53		FHC - Front of ST-2	Dry	1	✓			
54		Parking Area Zone 2A	Dry	1	✓			
55		Parking Area Zone 8A	Dry	1	✓			
56		Parking Area Zone C	Dry	1	✓			
57	7M	FHC - Front of Service Lift	Dry	1	✓			
58		Front of Guest Lift	Dry	1	✓			
59		Pool Pump Room	Dry	1	✓			
60		Front of Pump room	Dry	1	✓			
61		Parking Area Zone A	Dry	1	✓			
62		FHC - Front of ST-1	Dry	1	✓			
63		Parking Area Zone 2A	Dry	1	✓			
64		FHC - Inside ST-2	Dry	1	✓			
65		Inside ST-2	Dry	1	✓			
66	8	FHC - Front of Service Lift	Dry	1	✓			
67		Front of Guest Lift	Dry	1	✓			
68		E & E Room	CO2	1	✓			
69		FHC - beside ST-1	Dry	1	✓			
70		FHC - beside ST-2	Dry	1	✓			
71		Front of Apt#810	Dry	1	✓			
72		Beside Apt#817	Dry	1	✓			
73	9	FHC - Front of Service Lift	Dry	1	✓			
74		Front of Guest Lift	Dry	1	✓			
75		E & E Room	CO2	1	✓			
76		FHC - beside ST-1	Dry	1	✓			
77		FHC - beside ST-2	Dry	1	✓			
78		Front of Apt#910	Dry	1	✓			Overcharge
79		Beside Apt#917	Dry	1	✓			

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
80	10	FHC - Front of Service Lift	Dry	1	✓			
81		Front of Guest Lift	Dry	1	✓			
82		E & E Room	CO2	1	✓			
83		Beside Apt#1001	Dry	1	✓			
84		Beside Apt#1017	Dry	1	✓			
85		FHC - beside ST-1	Dry	1	✓			
86		FHC - beside ST-2	Dry	1	✓			
87	11	FHC - Front of Service Lift	Dry	1	✓			Recharge
88		Front of Guest Lift	Dry	1	✓			
89		E & E Room	CO2	1	✓			
90		Beside Apt#1101	Dry	1	✓			
91		Beside Apt#1117	Dry	1	✓			
92		FHC - beside ST-1	Dry	1	✓			
93		FHC - beside ST-2	Dry	1	✓			
94	12	FHC - Front of Service Lift	Dry	1	✓			
95		Front of Guest Lift	Dry	1	✓			
96		E & E Room	CO2	1	✓			
97		Beside Apt#1201	Dry	1	✓			Recharge
98		Beside Apt#1217	Dry	1	✓			
99		FHC - beside ST-1	Dry	1	✓			Overcharge
100		FHC - beside ST-2	Dry	1	✓			
101	13	FHC - Front of Service Lift	Dry	1	✓			
102		Front of Guest Lift	Dry	1	✓			
103		E & E Room	CO2	1	✓			
104		Beside Apt#1301	Dry	1	✓			
105		Beside Apt#1317	Dry	1	✓			
106		FHC - beside ST-1	Dry	1	✓			
107		FHC - beside ST-2	Dry	1	✓			
108	14	FHC - Front of Service Lift	Dry	1	✓			Overcharge
109		Front of Guest Lift	Dry	1	✓			
110		E & E Room	CO2	1	✓			
111		Beside Apt#1401	Dry	1	✓			
112		Beside Apt#1417	Dry	1	✓			
113		FHC - beside ST-1	Dry	1	✓			
114		FHC - beside ST-2	Dry	1	✓			
115	15	FHC - Front of Service Lift	Dry	1	✓			Overcharge
116		Front of Guest Lift	Dry	1	✓			Overcharge
117		E & E Room	CO2	1	✓			
118		Beside Apt#1501	Dry	1	✓			
119		Beside Apt#1517	Dry	1	✓			
120		FHC - beside ST-1	Dry	1	✓			
121		FHC - beside ST-2	Dry	1	✓			Overcharge
122	16	FHC - Front of Service Lift	Dry	1	✓			
123		Front of Guest Lift	Dry	1	✓			Recharge
124		E & E Room	CO2	1	✓			
125		Beside Apt#1601	Dry	1	✓			
126		Beside Apt#1617	Dry	1	✓			
127		FHC - beside ST-1	Dry	1	✓			
128		FHC - beside ST-2	Dry	1	✓			

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
129	17	FHC - Front of Service Lift	Dry	1	✓			Overcharge
130		Front of Guest Lift	Dry	1	✓			Overcharge
131		E & E Room	CO2	1	✓			
132		Beside Apt#1701	Dry	1	✓			
133		Beside Apt#1717	Dry	1	✓			Recharge
134		FHC - beside ST-1	Dry	1	✓			
135		FHC - beside ST-2 (15 lbs.)	Dry	1	✓			Overcharge
136	18	FHC - Front of Service Lift	Dry	1	✓			Overcharge
137		Front of Guest Lift	Dry	1	✓			
138		E & E Room	CO2	1	✓			
139		Beside Apt#1801	Dry	1	✓			Overcharge
140		Beside Apt#1817	Dry	1	✓			Overcharge
141		FHC - beside ST-1	Dry	1	✓			
142		FHC - beside ST-2	Dry	1	✓			
143	19	FHC - Front of Service Lift	Dry	1	✓			Overcharge
144		Front of Guest Lift	Dry	1	✓			
145		E & E Room	CO2	1	✓			
146		Beside Apt#1901	Dry	1	✓			
147		Beside Apt#1917	Dry	1	✓			Overcharge
148		FHC - beside ST-1	Dry	1	✓			Overcharge
149		FHC - beside ST-2	Dry	1	✓			
150	20	FHC - Front of Service Lift	Dry	1	✓			Overcharge
151		Front of Guest Lift	Dry	1	✓			Overcharge
152		E & E Room	CO2	1	✓			
153		Beside Apt#2001	Dry	1	✓			
154		Beside Apt#2017	Dry	1	✓			Overcharge
155		FHC - beside ST-1	Dry	1	✓			
156		FHC - beside ST-2	Dry	1	✓			
157	21	FHC - Front of Service Lift	Dry	1	✓			
158		Front of Guest Lift	Dry	1	✓			Overcharge
159		E & E Room	CO2	1	✓			
160		Beside Apt#2101	Dry	1	✓			
161		Beside Apt#2117	Dry	1	✓			Overcharge
162		FHC - beside ST-1	Dry	1	✓			Overcharge
163		FHC - beside ST-2	Dry	1	✓			
164	22	FHC - Front of Service Lift	Dry	1	✓			Overcharge
165		Front of Guest Lift	Dry	1	✓			
166		E & E Room	CO2	1	✓			
167		Beside Apt#2201	Dry	1	✓			Overcharge
168		Beside Apt#2217	Dry	1	✓			Overcharge
169		FHC - beside ST-1	Dry	1	✓			Overcharge
170		FHC - beside ST-2	Dry	1	✓			
171	23	FHC - Front of Service Lift	Dry	1	✓			
172		Front of Guest Lift	Dry	1	✓			
173		E & E Room	CO2	1	✓			
174		Beside Apt#2301	Dry	1	✓			Overcharge
175		Beside Apt#2317	Dry	1	✓			Overcharge
176		FHC - beside ST-1	Dry	1	✓			Overcharge
177		FHC - beside ST-2	Dry	1	✓			Overcharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
178	24	FHC - Front of Service Lift	Dry	1	✓			
179		Front of Guest Lift	Dry	1	✓			
180		E & E Room	CO2	1	✓			
181		Beside Apt#2401	Dry	1	✓			Overcharge
182		Beside Apt#2415	Dry	1	✓			
183		FHC - beside ST-1	Dry	1	✓			
184		FHC - beside ST-2	Dry	1	✓			
185	25	FHC - Front of Service Lift	Dry	1	✓			
186		Front of Guest Lift	Dry	1	✓			
187		E & E Room	CO2	1	✓			
188		Beside Apt#2501	Dry	1	✓			
189		Beside Apt#2517	Dry	1	✓			
190		FHC - beside ST-1	Dry	1	✓			
191		FHC - beside ST-2	Dry	1	✓			
192	26	FHC - Front of Service Lift	Dry	1	✓			
193		Front of Guest Lift	Dry	1	✓			
194		E & E Room	CO2	1	✓			
195		Beside Apt#2601	Dry	1	✓			
196		Beside Apt#2615	Dry	1	✓			Overcharge
197		FHC - beside ST-1	Dry	1	✓			
198		FHC - beside ST-2	Dry	1	✓			
199	27	FHC - Front of Service Lift	Dry	1	✓			
200		Front of Guest Lift	Dry	1	✓			
201		E & E Room	CO2	1	✓			
202		FHC - Sky Garden	Dry	1	✓			
203		Beside Apt#2710	Dry	1	✓			
204		Beside Apt#2715	Dry	1	✓			
205		FHC - beside ST-2	Dry	1	✓			
206	28	FHC - Front of Service Lift	Dry	1	✓			
207		Front of Guest Lift	Dry	1	✓			
208		E & E Room	CO2	1	✓			
209		Beside Apt#2809	Dry	1	✓			
210		Beside Apt#2815	Dry	1	✓			
211		FHC - beside ST-2	Dry	1	✓			Overcharge
212	29	FHC - Front of Service Lift	Dry	1	✓			
213		Front of Guest Lift	Dry	1	✓			
214		E & E Room	CO2	1	✓			
215		Beside Apt#2909	Dry	1	✓			
216		Beside Apt#2915	Dry	1	✓			
217		FHC - beside ST-2	Dry	1	✓			Recharge
218	30	FHC - Front of Service Lift	Dry	1	✓			
219		Front of Guest Lift	Dry	1	✓			
220		E & E Room	CO2	1	✓			
221		Beside Apt#3009	Dry	1	✓			Recharge
222		Beside Apt#3015	Dry	1	✓			
223		FHC - beside ST-2	Dry	1	✓			Overcharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
224	31	FHC - Front of Service Lift	Dry	1	✓			
225		Front of Guest Lift	Dry	1	✓			
226		E & E Room	CO2	1	✓			
227		Beside Apt#3109	Dry	1	✓			
228		Beside Apt#3115	Dry	1	✓			
229		FHC - beside ST-2	Dry	1	✓			
230	32	FHC - Front of Service Lift	Dry	1	✓			
231		Front of Guest Lift	Dry	1	✓			
232		E & E Room	CO2	1	✓			
233		Beside Apt#3209	Dry	1	✓			
234		Beside Apt#3215	Dry	1	✓			
235		FHC - beside ST-2	Dry	1	✓			
236	33	FHC - Front of Service Lift	Dry	1	✓			
237		Front of Guest Lift	Dry	1	✓			
238		E & E Room	CO2	1	✓			
239		Beside Apt#3309	Dry	1	✓			
240		Beside Apt#3315	Dry	1	✓			
241		FHC - beside ST-2	Dry	1	✓			
242	34	FHC - Front of Service Lift	Dry	1	✓			
243		Front of Guest Lift	Dry	1	✓			
244		E & E Room	CO2	1	✓			
245		Beside Apt#3409	Dry	1	✓			
246		Beside Apt#3415	Dry	1	✓			
247		FHC - beside ST-2	Dry	1	✓			
248	35	FHC - Front of Service Lift	Dry	1	✓			
249		Front of Guest Lift	Dry	1	✓			
250		E & E Room	CO2	1	✓			
251		Beside Apt#3509	Dry	1	✓			
252		Beside Apt#3515	Dry	1	✓			Recharge
253		FHC - beside ST-2	Dry	1	✓			
254	36	FHC-Roof-ST-1	Dry	1	✓			
255		Control lift Rooftop	CO2	1	✓			
256		FHC-Roof-ST-2	Dry	1	✓			

- Note:** ตรวจเช็คถังดับเพลิงทั้งหมด 753 ถัง
1. Dry Chamecal (10 lbs.) (Overcharge & 'Recharge 54 tanks เข็มยังอยู่ในสรีรเขียว), และมี 6 ถังที่ใช้งานไม่ได้ รวมทั้งหมด 60 ถัง
 2. Dry Chamecal (15 lbs.) ใช้งานไม่ได้ 1 ถัง
 3. Dry Chamecal (2.2 lbs.) (Overcharge & 'Recharge 16 tanks เข็มยังอยู่ในสรีรเขียว), 1 ถังที่ใช้งานไม่ได้ และมี 5 ถัง แคมป์แข็ง รวมทั้งหมด 22 ถัง
 4. Co2 (10 bls) มี 1 ถังที่น้ำหนักต่ำเกณฑ์ ใช้ Training

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Yes	No		
1	230	Dry Chemical (10 lbs)	222	7		Recharge 4, รั่ว 1, แจ้ง 1, ส่งเดิม 1 (อำนวยการ)
2	44	CO2	43	1		น้ำหนักต่ำเกณฑ์ (ใช้เทรนนิ่ง)
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	444	1		Recharge 1Keep SEC Store
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	5	1		เคมีแจ้ง 1
Total	753		742	10		

Reported by: _____
Security Supervisor

Acknowledged by: _____
Security Manager

Fire Extinguisher Checklist 2026

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
2		FHC - Front of FCC	Dry	1	✓		05/02/2026	Big
3		Gas Station (15 lbs)	Dry	2	✓		14/02/2026	Big
4		Front of Garbage Room	Dry	1	✓		05/02/2026	Big
5		Front of Housekeeping Store	Dry	1	✓		05/02/2026	Big
6		Fire Cart	Dry	1	✓		14/02/2026	Big
7		Security Store	Dry	8	✓		12/02/2026	Recharge 4,แข็ง 1 ร้ว 1, (ส่งจำนวน 1)
8		Security Store (15 lbs)	Dry	3	✓		12/02/2026	เคมีแข็ง 1
9		Security Store (20 lbs)	Dry	2	✓		12/02/2026	Big
10		In fornt of Electrical room (50lbs)	Dry	2	✓		05/02/2026	Big
11		Security Store	ADE	4	✓		12/02/2026	Big
12		Electrical Room	ADE	1	✓		05/02/2026	Big
13		Engineering Workshop	ADE	2	✓		05/02/2026	Big
14		Engineering Store	ADE	1	✓		05/02/2026	Big
15		Chemical Room	ADE	2	✓		05/02/2026	Big
16		Houskeeping Store	ADE	1	✓		05/02/2026	Big
17		Houskeeping Office	ADE	1	✓		05/02/2026	Big
18		FCC Room	ADE	1	✓		05/02/2026	Big
19		Fire Pump Room	ADE	2	✓		12/02/2026	Big
20		Finance Accounting Office	ADE	1	✓		05/02/2026	Big
21		Staff Canteen Room	ADE	1	✓		05/02/2026	Big
22		Fire Cart	CO2	1	✓		14/02/2026	Big
23		FCC Room	CO2	1	✓		05/02/2026	Big
24		Security Store	CO2	10	✓		12/02/2026	1 น้ำหนักต่ำเกณฑ์
25		Fire Pump Room	Dry	1	✓		12/02/2026	Big
26		Front of Timekeeper	Dry	1	✓		05/02/2026	Big
27	G	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
25		MDB and Generator	ADE	2	✓		14/02/2026	Big
26		Server Room	ADE	2	✓		14/02/2026	Big
27		Guest Service Office	ADE	1	✓		05/02/2026	Big
28		Executive Office	ADE	1	✓		05/02/2026	Big
29		Server Room	CO2	1	✓		14/02/2026	Big
30		FHC - Front of Saver Room	CO2	1	✓		14/02/2026	Big
31		FHC - Front ST-2	Dry	1	✓		14/02/2026	Overcharge
32	2	FHC - Front of Service Lift	Dry	1	✓		14/02/2026	Big
33		Front of First aid Room	Dry	1	✓		14/02/2026	Big
34		Front of HK Store	Dry	1	✓		14/02/2026	Big
35		Rama 9 Sound Control Room	CO2	1	✓		14/02/2026	Big
36		FHC - Front of ST-1	Dry	1	✓		14/02/2026	Big
37		FHC - Front of ST-2	Dry	1	✓		14/02/2026	Big
38	3	FHC - Front of Service Lift	Dry	1	✓		04/02/2026	Overcharge
18		Front of Guest Lift	Dry	1	✓		04/02/2026	Overcharge
19		FHC - Front of ST-1	Dry	1	✓		04/02/2026	Pong
20		Parking Area Zone 4B	Dry	1	✓		04/02/2026	Overcharge
21		FHC - Front of ST-2	Dry	1	✓		04/02/2026	Overcharge
22		Parking Area Zone 2A	Dry	1	✓		04/02/2026	Overcharge
23	4	FHC - Front of Service Lift	Dry	1	✓		04/02/2026	Overcharge
24		Front of Guest Lift	Dry	1	✓		04/02/2026	Overcharge
25		FHC - Front of ST-1	Dry	1	✓		04/02/2026	Pong
26		Parking Area Zone 4B	Dry	1	✓		04/02/2026	Overcharge
27		FHC - Front of ST-2	Dry	1	✓		04/02/2026	Recharge
28		Parking Area Zone 2A	Dry	1	✓		04/02/2026	Overcharge
29		Parking Area Zone 8A	Dry	1	✓		04/02/2026	Overcharge
30		Parking Area Zone C	Dry	1	✓		04/02/2026	Overcharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
31	5	FHC - Front of Service Lift	Dry	1	✓		04/02/2026	Overcharge
32		Front of Guest Lift	Dry	1	✓		04/02/2026	Overcharge
33		FHC - Front of ST-1	Dry	1	✓		04/02/2026	Overcharge
34		Parking Area Zone 4B	Dry	1	✓		04/02/2026	Overcharge
35		FHC - Front of ST-2	Dry	1	✓		04/02/2026	Overcharge
36		Parking Area Zone 2A	Dry	1	✓		04/02/2026	Overcharge
37		Parking Area Zone 8A	Dry	1	✓		04/02/2026	Overcharge
38		Parking Area Zone C	Dry	1	✓		04/02/2026	Overcharge
39	6	FHC - Front of Service Lift	Dry	1	✓		04/02/2026	Overcahge
40		Front of Guest Lift	Dry	1	✓		04/02/2026	Recharge
41		FHC - Front of ST-1	Dry	1	✓		04/02/2026	Pong
42		Parking Area Zone 4B	Dry	1	✓		04/02/2026	Pong
43		Inside ST-2	Dry	1	✓		04/02/2026	Overcharge
44		FHC - Front of ST-2	Dry	1	✓		04/02/2026	Pong
45		Parking Area Zone 2A	Dry	1	✓		04/02/2026	Recharge
46		Parking Area Zone 8A	Dry	1	✓		04/02/2026	Overcharge
47		Parking Area Zone C	Dry	1	✓		04/02/2026	Overcharge
48	7	FHC - Front of Service Lift	Dry	1	✓		04/02/2026	Pong
49		Front of Guest Lift	Dry	1	✓		04/02/2026	Recharge
50		FHC - Front of ST-1	Dry	1	✓		04/02/2026	Pong
51		Parking Area Zone 4B	Dry	1	✓		04/02/2026	Pong
52		Inside ST-2	Dry	1	✓		04/02/2026	Overcharge
53		FHC - Front of ST-2	Dry	1	✓		04/02/2026	Pong
54		Parking Area Zone 2A	Dry	1	✓		04/02/2026	Overcharge
55		Parking Area Zone 8A	Dry	1	✓		04/02/2026	Pong
56		Parking Area Zone C	Dry	1	✓		04/02/2026	Overcharge
57	7M	FHC - Front of Service Lift	Dry	1	✓		04/02/2026	Pong
58		Front of Guest Lift	Dry	1	✓		04/02/2026	Pong
59		Pool Pump Room	Dry	1				
60		Front of Pump room	Dry	1	✓		04/02/2026	Pong
61		Parking Area Zone A	Dry	1	✓		04/02/2026	Pong
62		FHC - Front of ST-1	Dry	1	✓		04/02/2026	Overcharge
63		Parking Area Zone 2A	Dry	1	✓		04/02/2026	Pong
64		FHC - Inside ST-2	Dry	1	✓			
65		Inside ST-2	Dry	1	✓			
66	8	FHC - Front of Service Lift	Dry	1	✓		06/02/2026	Overcharge
67		Front of Guest Lift	Dry	1	✓		06/02/2026	Big
68		E & E Room	CO2	1	✓		09/02/2026	Stone
69		FHC - beside ST-1	Dry	1	✓		06/02/2026	Big
70		FHC - beside ST-2	Dry	1	✓		06/02/2026	Big
71		Front of Apt#810	Dry	1	✓		06/02/2026	Overcharge
72		Beside Apt#817	Dry	1	✓		06/02/2026	Big
73		FHC - Front of Service Lift	Dry	1	✓		06/02/2026	Big
74	9	Front of Guest Lift	Dry	1	✓		06/02/2026	Big
75		E & E Room	CO2	1	✓		09/02/2026	Stone
76		FHC - beside ST-1	Dry	1	✓		06/02/2026	Big
77		FHC - beside ST-2	Dry	1	✓		06/02/2026	Overcharge
78		Front of Apt#910	Dry	1	✓		06/02/2026	Overcharge
79		Beside Apt#917	Dry	1	✓		06/02/2026	Big

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
80	10	FHC - Front of Service Lift	Dry	1	✓		06/02/2026	Big
81		Front of Guest Lift	Dry	1	✓		06/02/2026	Overcharge
82		E & E Room	CO2	1	✓		06/02/2026	Big
83		Beside Apt#1001	Dry	1	✓		06/02/2026	Big
84		Beside Apt#1017	Dry	1	✓		06/02/2026	Big
85		FHC - beside ST-1	Dry	1	✓		06/02/2026	Big
86		FHC - beside ST-2	Dry	1	✓		06/02/2026	Big
87	11	FHC - Front of Service Lift	Dry	1	✓		06/02/2026	Recharge
88		Front of Guest Lift	Dry	1	✓		06/02/2026	Big
89		E & E Room	CO2	1	✓		06/02/2026	Big
90		Beside Apt#1101	Dry	1	✓		06/02/2026	Big
91		Beside Apt#1117	Dry	1	✓		06/02/2026	Big
92		FHC - beside ST-1	Dry	1	✓		06/02/2026	Overcharge
93		FHC - beside ST-2	Dry	1	✓		06/02/2026	Big
94	12	FHC - Front of Service Lift	Dry	1	✓		06/02/2026	Big
95		Front of Guest Lift	Dry	1	✓		06/02/2026	Big
96		E & E Room	CO2	1	✓		06/02/2026	Big
97		Beside Apt#1201	Dry	1	✓		06/02/2026	Recharge
98		Beside Apt#1217	Dry	1	✓		06/02/2026	Big
99		FHC - beside ST-1	Dry	1	✓		06/02/2026	Overcharge
100		FHC - beside ST-2	Dry	1	✓		06/02/2026	Big
101	13	FHC - Front of Service Lift	Dry	1	✓		06/02/2026	Overcharge
102		Front of Guest Lift	Dry	1	✓		06/02/2026	Big
103		E & E Room	CO2	1	✓		06/02/2026	Big
104		Beside Apt#1301	Dry	1	✓		06/02/2026	Big
105		Beside Apt#1317	Dry	1	✓		06/02/2026	Big
106		FHC - beside ST-1	Dry	1	✓		06/02/2026	Big
107		FHC - beside ST-2	Dry	1	✓		06/02/2026	Big
108	14	FHC - Front of Service Lift	Dry	1	✓		06/02/2026	Overcharge
109		Front of Guest Lift	Dry	1	✓		06/02/2026	Overcharge
110		E & E Room	CO2	1	✓		06/02/2026	Big
111		Beside Apt#1401	Dry	1	✓		06/02/2026	Big
112		Beside Apt#1417	Dry	1	✓		06/02/2026	Recharge
113		FHC - beside ST-1	Dry	1	✓		06/02/2026	Big
114		FHC - beside ST-2	Dry	1	✓		06/02/2026	Overcharge
115	15	FHC - Front of Service Lift	Dry	1	✓		06/02/2026	Overcharge
116		Front of Guest Lift	Dry	1	✓		06/02/2026	Overcharge
117		E & E Room	CO2	1	✓		06/02/2026	Big
118		Beside Apt#1501	Dry	1	✓		06/02/2026	Big
119		Beside Apt#1517	Dry	1	✓		06/02/2026	Big
120		FHC - beside ST-1	Dry	1	✓		06/02/2026	Overcharge
121		FHC - beside ST-2	Dry	1	✓		06/02/2026	Overcharge
122	16	FHC - Front of Service Lift	Dry	1	✓		06/02/2026	Big
123		Front of Guest Lift	Dry	1	✓		06/02/2026	Recharge
124		E & E Room	CO2	1	✓		06/02/2026	Big
125		Beside Apt#1601	Dry	1	✓		06/02/2026	Big
126		Beside Apt#1617	Dry	1	✓		06/02/2026	Big
127		FHC - beside ST-1	Dry	1	✓		06/02/2026	Big
128		FHC - beside ST-2	Dry	1	✓		06/02/2026	Big

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
129	17	FHC - Front of Service Lift	Dry	1	✓		06/02/2026	Overcharge
130		Front of Guest Lift	Dry	1	✓		06/02/2026	Overcharge
131		E & E Room	CO2	1	✓		06/02/2026	Big
132		Beside Apt#1701	Dry	1	✓		06/02/2026	Big
133		Beside Apt#1717	Dry	1	✓		06/02/2026	Recharge
134		FHC - beside ST-1	Dry	1	✓		06/02/2026	Big
135		FHC - beside ST-2 (15 lbs.)	Dry	1	✓		06/02/2026	Overcharge
136	18	FHC - Front of Service Lift	Dry	1	✓		02/02/2026	Overcharge
137		Front of Guest Lift	Dry	1	✓		02/02/2026	Stone
138		E & E Room	CO2	1	✓			
139		Beside Apt#1801	Dry	1	✓		02/02/2026	Overcharge
140		Beside Apt#1817	Dry	1	✓		02/02/2026	Overcharge
141		FHC - beside ST-1	Dry	1	✓		02/02/2026	Stone
142		FHC - beside ST-2	Dry	1	✓		02/02/2026	Stone
143	19	FHC - Front of Service Lift	Dry	1	✓		02/02/2026	Overcharge
144		Front of Guest Lift	Dry	1	✓		02/02/2026	Stone
145		E & E Room	CO2	1	✓			
146		Beside Apt#1901	Dry	1	✓		02/02/2026	Stone
147		Beside Apt#1917	Dry	1	✓		02/02/2026	Overcharge
148		FHC - beside ST-1	Dry	1	✓		02/02/2026	Overcharge
149		FHC - beside ST-2	Dry	1	✓		02/02/2026	Stone
150	20	FHC - Front of Service Lift	Dry	1	✓		02/02/2026	Overcharge
151		Front of Guest Lift	Dry	1	✓		02/02/2026	Overcharge
152		E & E Room	CO2	1	✓			
153		Beside Apt#2001	Dry	1	✓		02/02/2026	Stone
154		Beside Apt#2017	Dry	1	✓		02/02/2026	Overcharge
155		FHC - beside ST-1	Dry	1	✓		02/02/2026	Stone
156		FHC - beside ST-2	Dry	1	✓		02/02/2026	Stone
157	21	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
158		Front of Guest Lift	Dry	1	✓		05/02/2026	Overcharge
159		E & E Room	CO2	1	✓		05/02/2026	Big
160		Beside Apt#2101	Dry	1	✓		05/02/2026	Big
161		Beside Apt#2117	Dry	1	✓		05/02/2026	Overcharge
162		FHC - beside ST-1	Dry	1	✓		06/02/2026	Overcharge
163		FHC - beside ST-2	Dry	1	✓		05/02/2026	Big
164	22	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
165		Front of Guest Lift	Dry	1	✓		05/02/2026	Overcharge
166		E & E Room	CO2	1	✓		05/02/2026	Big
167		Beside Apt#2201	Dry	1	✓		05/02/2026	Overcharge
168		Beside Apt#2217	Dry	1	✓		05/02/2026	Overcharge
169		FHC - beside ST-1	Dry	1	✓		05/02/2026	Overcharge
170		FHC - beside ST-2	Dry	1	✓		05/02/2026	Overcharge
171	23	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
172		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
173		E & E Room	CO2	1	✓		05/02/2026	Big
174		Beside Apt#2301	Dry	1	✓		05/02/2026	Overcharge
175		Beside Apt#2317	Dry	1	✓		05/02/2026	Overcharge
176		FHC - beside ST-1	Dry	1	✓		05/02/2026	Overcharge
177		FHC - beside ST-2	Dry	1	✓		05/02/2026	Overcharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
178	24	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
179		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
180		E & E Room	CO2	1	✓		05/02/2026	Big
181		Beside Apt#2401	Dry	1	✓		05/02/2026	Big
182		Beside Apt#2415	Dry	1	✓		05/02/2026	Big
183		FHC - beside ST-1	Dry	1	✓		05/02/2026	Big
184		FHC - beside ST-2	Dry	1	✓		05/02/2026	Big
185	25	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
186		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
187		E & E Room	CO2	1	✓		05/02/2026	Big
188		Beside Apt#2501	Dry	1	✓		05/02/2026	Big
189		Beside Apt#2517	Dry	1	✓		05/02/2026	Big
190		FHC - beside ST-1	Dry	1	✓		05/02/2026	Big
191		FHC - beside ST-2	Dry	1	✓		05/02/2026	Big
192	26	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
193		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
194		E & E Room	CO2	1	✓		05/02/2026	Big
195		Beside Apt#2601	Dry	1	✓		05/02/2026	Big
196		Beside Apt#2615	Dry	1	✓		05/02/2026	Big
197		FHC - beside ST-1	Dry	1	✓		05/02/2026	Big
198		FHC - beside ST-2	Dry	1	✓		05/02/2026	Big
199	27	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
200		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
201		E & E Room	CO2	1	✓		05/02/2026	Big
202		FHC - Sky Garden	Dry	1	✓		05/02/2026	Big
203		Beside Apt#2710	Dry	1	✓		05/02/2026	Big
204		Beside Apt#2715	Dry	1	✓		05/02/2026	Big
205		FHC - beside ST-2	Dry	1	✓		05/02/2026	Big
206	28	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
207		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
208		E & E Room	CO2	1	✓		05/02/2026	Big
209		Beside Apt#2809	Dry	1	✓		05/02/2026	Big
210		Beside Apt#2815	Dry	1	✓		05/02/2026	Big
211		FHC - beside ST-2	Dry	1	✓		05/02/2026	Overcharge
212	29	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
213		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
214		E & E Room	CO2	1	✓		05/02/2026	Big
215		Beside Apt#2909	Dry	1	✓		05/02/2026	Big
216		Beside Apt#2915	Dry	1	✓		05/02/2026	Big
217		FHC - beside ST-2	Dry	1	✓		05/02/2026	Big
218	30	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
219		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
220		E & E Room	CO2	1	✓		05/02/2026	Big
221		Beside Apt#3009	Dry	1	✓		05/02/2026	Recharge
222		Beside Apt#3015	Dry	1	✓		05/02/2026	Big
223		FHC - beside ST-2	Dry	1	✓		05/02/2026	Overcharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
224	31	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
225		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
226		E & E Room	CO2	1	✓		05/02/2026	Big
227		Beside Apt#3109	Dry	1	✓		05/02/2026	Big
228		Beside Apt#3115	Dry	1	✓		05/02/2026	Big
229		FHC - beside ST-2	Dry	1	✓		05/02/2026	Big
230	32	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
231		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
232		E & E Room	CO2	1	✓		05/02/2026	Big
233		Beside Apt#3209	Dry	1	✓		05/02/2026	Big
234		Beside Apt#3215	Dry	1	✓		05/02/2026	Big
235		FHC - beside ST-2	Dry	1	✓		05/02/2026	Big
236	33	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
237		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
238		E & E Room	CO2	1	✓		05/02/2026	Big
239		Beside Apt#3309	Dry	1	✓		05/02/2026	Big
240		Beside Apt#3315	Dry	1	✓		05/02/2026	Big
241		FHC - beside ST-2	Dry	1	✓		05/02/2026	Big
242	34	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
243		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
244		E & E Room	CO2	1	✓		05/02/2026	Big
245		Beside Apt#3409	Dry	1	✓		05/02/2026	Big
246		Beside Apt#3415	Dry	1	✓		05/02/2026	Big
247		FHC - beside ST-2	Dry	1	✓		05/02/2026	Big
248	35	FHC - Front of Service Lift	Dry	1	✓		05/02/2026	Big
249		Front of Guest Lift	Dry	1	✓		05/02/2026	Big
250		E & E Room	CO2	1	✓		05/02/2026	Big
251		Beside Apt#3509	Dry	1	✓		05/02/2026	Big
252		Beside Apt#3515	Dry	1	✓		05/02/2026	Recharge
253		FHC - beside ST-2	Dry	1	✓		05/02/2026	Big
254	36	FHC-Roof-ST-1	Dry	1	✓			
255		Control lift Rooftop	CO2	1	✓			
256		FHC-Roof-ST-2	Dry	1	✓			

Note: ตรวจเช็คถังดับเพลิงทั้งหมด 753 ถัง

1. Dry Chamecal (10 lbs.) (Overcharge & 'Recharge 54 tanks เข็มยังอยู่ในสีเขียว), และมี 6 ถังที่ใช้งานไม่ได้ รวมทั้งหมด 60 ถัง
2. Dry Chamecal (15 lbs.) ใช้งานไม่ได้ 1 ถัง
3. Dry Chamecal (2.2 lbs.) (Overcharge & 'Recharge 16 tanks เข็มยังอยู่ในสีเขียว), 1 ถังที่ใช้งานไม่ได้ และมี 5 ถัง แค้มป์แข็ง รวมทั้งหมด 22 ถัง
4. Co2 (10 bls) มี 1 ถังที่น้ำหนักต่ำเกณฑ์ ใช้ Training

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Yes	No		
1	230	Dry Chemical (10 lbs)	222	7		Recharge 4, รั่ว 1, แฉียง 1, สงเดิม 1 (อำนวม)
2	44	CO2	43	1		น้ำหนกตำเกณท์ (ใช้เทรนนิ่ง)
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	444	1		Recharge 1Keep SEC Store
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	5	1		เคมี้แฉียง 1
Total	753		742	10		

Reported by: Akapol NUNTAWONG
Senior Security Supervisor

Acknowledged by: _____
Security Manager

Fire Extinguisher Checklist 2026

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry	1	✓		17/03/2026	Big
2		FHC - Front of FCC	Dry	1	✓		07/03/2026	Big
3		Gas Station (15 lbs)	Dry	2	✓		07/03/2026	Big
4		Front of Garbage Room	Dry	1	✓		07/03/2026	Big
5		Front of Housekeeping Store	Dry	1	✓		13/03/2026	Big
6		Fire Cart	Dry	1	✓		13/03/2026	Big
7		Security Store	Dry	8	✓		13/03/2026	Out of order 6, แจ้ง 1 ร้ว
8		Security Store (15 lbs)	Dry	3	✓		13/03/2026	Out of order 1
9		Security Store (20 lbs)	Dry	2	✓		13/03/2026	Big
10		In fornt of Electical room (50lbs)	Dry	2	✓		07/03/2026	Big
11		Security Store	ADE	4	✓		13/03/2026	Big
12		Electrical Room	ADE	1	✓		13/03/2026	Big
13		Engineering Workshop	ADE	2	✓		07/03/2026	Big
14		Engineering Store	ADE	1	✓		07/03/2026	Big
15		Chemical Room	ADE	2	✓		13/03/2026	Big
16		Houskeeping Store	ADE	1	✓		13/03/2026	Big
17		Houskeeping Office	ADE	1	✓		07/03/2026	Big
18		FCC Room	ADE	1	✓		07/03/2026	Big
19		Fire Pump Room	ADE	2	✓		07/03/2026	Big
20		Finance Accounting Office	ADE	1	✓		13/03/2026	Big
21		Staff Canteen Room	ADE	1	✓		07/03/2026	Big
22		Fire Cart	CO2	1	✓		12/03/2026	Big
23		FCC Room	CO2	1	✓		07/03/2026	Big
24		Security Store	CO2	10	✓		17/03/2026	1 น้ำหนักต่ำเกณฑ์
25		Fire Pump Room	Dry	1	✓		07/03/2026	Big
26		Front of Timekeeper	Dry	1	✓		07/03/2026	Big
27	G	FHC - Front of Service Lift	Dry	1	✓		17/03/2026	Big
25		MDB and Generator	ADE	2	✓		21/03/2026	Big
26		Server Room	ADE	2	✓		17/03/2026	Big
27		Guest Service Office	ADE	1	✓		17/03/2026	Big
28		Executive Office	ADE	1	✓		17/03/2026	Big
29		Server Room	CO2	1	✓		17/03/2026	Big
30		FHC - Front of Saver Room	CO2	1	✓		17/03/2026	Big
31		FHC - Front ST-2	Dry	1	✓		18/03/2026	Big
32	2	FHC - Front of Service Lift	Dry	1	✓		21/03/2026	Big
33		Front of First aid Room	Dry	1	✓		21/03/2026	Big
34		Front of HK Store	Dry	1	✓		21/03/2026	Big
35		Rama 9 Sound Control Room	CO2	1	✓		21/03/2026	Big
36		FHC - Front of ST-1	Dry	1	✓		21/03/2026	Big
37		FHC - Front of ST-2	Dry	1	✓		21/03/2026	Big
38	3	FHC - Front of Service Lift	Dry	1	✓		07/03/2026	Overcharge
18		Front of Guest Lift	Dry	1	✓		07/03/2026	Overcharge
19		FHC - Front of ST-1	Dry	1	✓		07/03/2026	Recharge
20		Parking Area Zone 4B	Dry	1	✓		07/03/2026	Big
21		FHC - Front of ST-2	Dry	1	✓		07/03/2026	Overcharge
22		Parking Area Zone 2A	Dry	1	✓		07/03/2026	Overcharge
23	4	FHC - Front of Service Lift	Dry	1	✓		07/03/2026	Overcharge
24		Front of Guest Lift	Dry	1	✓		07/03/2026	Overcharge
25		FHC - Front of ST-1	Dry	1	✓		07/03/2026	Recharge
26		Parking Area Zone 4B	Dry	1	✓		07/03/2026	Overcharge
27		FHC - Front of ST-2	Dry	1	✓		07/03/2026	Recharge
28		Parking Area Zone 2A	Dry	1	✓		07/03/2026	Overcharge
29		Parking Area Zone 8A	Dry	1	✓		07/03/2026	Overcharge
30		Parking Area Zone C	Dry	1	✓		07/03/2026	Recharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
31	5	FHC - Front of Service Lift	Dry	1	✓		07/03/2026	Overcharge
32		Front of Guest Lift	Dry	1	✓		07/03/2026	Recharge
33		FHC - Front of ST-1	Dry	1	✓		07/03/2026	Recharge
34		Parking Area Zone 4B	Dry	1	✓		07/03/2026	Overcharge
35		FHC - Front of ST-2	Dry	1	✓		07/03/2026	Overcharge
36		Parking Area Zone 2A	Dry	1	✓		07/03/2026	Recharge
37		Parking Area Zone 8A	Dry	1	✓		07/03/2026	Overcharge
38		Parking Area Zone C	Dry	1	✓		07/03/2026	Recharge
39	6	FHC - Front of Service Lift	Dry	1	✓		07/03/2026	Big
40		Front of Guest Lift	Dry	1	✓		07/03/2026	Big
41		FHC - Front of ST-1	Dry	1	✓		07/03/2026	Big
42		Parking Area Zone 4B	Dry	1	✓		07/03/2026	Big
43		Inside ST-2	Dry	1	✓		07/03/2026	Big
44		FHC - Front of ST-2	Dry	1	✓		07/03/2026	Big
45		Parking Area Zone 2A	Dry	1	✓		07/03/2026	Big
46		Parking Area Zone 8A	Dry	1	✓		07/03/2026	Overcharge
47		Parking Area Zone C	Dry	1	✓		07/03/2026	Recharge
48	7	FHC - Front of Service Lift	Dry	1	✓		07/03/2026	Big
49		Front of Guest Lift	Dry	1	✓		07/03/2026	Recharge
50		FHC - Front of ST-1	Dry	1	✓		07/03/2026	Big
51		Parking Area Zone 4B	Dry	1	✓		07/03/2026	Big
52		Inside ST-2	Dry	1	✓		07/03/2026	Overcharge
53		FHC - Front of ST-2	Dry	1	✓		07/03/2026	Big
54		Parking Area Zone 2A	Dry	1	✓		07/03/2026	Overcharge
55		Parking Area Zone 8A	Dry	1	✓		07/03/2026	Big
56		Parking Area Zone C	Dry	1	✓		07/03/2026	Overcharge
57	7M	FHC - Front of Service Lift	Dry	1	✓		07/03/2026	Big
58		Front of Guest Lift	Dry	1	✓		07/03/2026	Big
59		Pool Pump Room	Dry	1	✓		25/03/2026	Big
60		Front of Pump room	Dry	1	✓		07/03/2026	Big
61		Parking Area Zone A	Dry	1	✓		07/03/2026	Big
62		FHC - Front of ST-1	Dry	1	✓		07/03/2026	Overcharge
63		Parking Area Zone 2A	Dry	1	✓		07/03/2026	Big
64		FHC - Inside ST-2	Dry	1	✓		07/03/2026	Big
65		Inside ST-2	Dry	1	✓		07/03/2026	Big
66	8	FHC - Front of Service Lift	Dry	1	✓		05/05/1905	Overcharge
67		Front of Guest Lift	Dry	1	✓		13/03/2026	Big
68		E & E Room	CO2	1	✓		21/03/2026	Big
69		FHC - beside ST-1	Dry	1	✓		13/03/2026	Big
70		FHC - beside ST-2	Dry	1	✓		13/03/2026	Big
71		Front of Apt#810	Dry	1	✓		13/03/2026	Overcharge
72		Beside Apt#817	Dry	1	✓		13/03/2026	Big
73	9	FHC - Front of Service Lift	Dry	1	✓		13/03/2026	Big
74		Front of Guest Lift	Dry	1	✓		13/03/2026	Big
75		E & E Room	CO2	1	✓		21/03/2026	Big
76		FHC - beside ST-1	Dry	1	✓		13/03/2026	Big
77		FHC - beside ST-2	Dry	1	✓		13/03/2026	Overcharge
78		Front of Apt#910	Dry	1	✓		13/03/2026	Overcharge
79		Beside Apt#917	Dry	1	✓		13/03/2026	Big

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
80	10	FHC - Front of Service Lift	Dry	1	✓		13/03/2026	Big
81		Front of Guest Lift	Dry	1	✓		13/03/2026	Overcharge
82		E & E Room	CO2	1	✓		18/03/2026	Big
83		Beside Apt#1001	Dry	1	✓		13/03/2026	Big
84		Beside Apt#1017	Dry	1	✓		13/03/2026	Big
85		FHC - beside ST-1	Dry	1	✓		13/03/2026	Big
86		FHC - beside ST-2	Dry	1	✓		13/03/2026	Big
87	11	FHC - Front of Service Lift	Dry	1	✓		13/03/2026	Recharge
88		Front of Guest Lift	Dry	1	✓		13/03/2026	Big
89		E & E Room	CO2	1	✓		18/03/2026	Big
90		Beside Apt#1101	Dry	1	✓		13/03/2026	Big
91		Beside Apt#1117	Dry	1	✓		13/03/2026	Big
92		FHC - beside ST-1	Dry	1	✓		13/03/2026	Overcharge
93		FHC - beside ST-2	Dry	1	✓		13/03/2026	Big
94	12	FHC - Front of Service Lift	Dry	1	✓		13/03/2026	Big
95		Front of Guest Lift	Dry	1	✓		13/03/2026	Big
96		E & E Room	CO2	1	✓		18/03/2026	Big
97		Beside Apt#1201	Dry	1	✓		13/03/2026	Recharge
98		Beside Apt#1217	Dry	1	✓		13/03/2026	Big
99		FHC - beside ST-1	Dry	1	✓		13/03/2026	Overcharge
100		FHC - beside ST-2	Dry	1	✓		13/03/2026	Big
101	13	FHC - Front of Service Lift	Dry	1	✓		13/03/2026	Overcharge
102		Front of Guest Lift	Dry	1	✓		13/03/2026	Big
103		E & E Room	CO2	1	✓		18/03/2026	Big
104		Beside Apt#1301	Dry	1	✓		13/03/2026	Big
105		Beside Apt#1317	Dry	1	✓		13/03/2026	Big
106		FHC - beside ST-1	Dry	1	✓		13/03/2026	Big
107		FHC - beside ST-2	Dry	1	✓		13/03/2026	Big
108	14	FHC - Front of Service Lift	Dry	1	✓		13/03/2026	Overcharge
109		Front of Guest Lift	Dry	1	✓		13/03/2026	Overcharge
110		E & E Room	CO2	1	✓		18/03/2026	Big
111		Beside Apt#1401	Dry	1	✓		13/03/2026	Big
112		Beside Apt#1417	Dry	1	✓		13/03/2026	Recharge
113		FHC - beside ST-1	Dry	1	✓		13/03/2026	Big
114		FHC - beside ST-2	Dry	1	✓		13/03/2026	Overcharge
115	15	FHC - Front of Service Lift	Dry	1	✓		13/03/2026	Overcharge
116		Front of Guest Lift	Dry	1	✓		13/03/2026	Overcharge
117		E & E Room	CO2	1	✓		18/03/2026	Big
118		Beside Apt#1501	Dry	1	✓		13/03/2026	Big
119		Beside Apt#1517	Dry	1	✓		13/03/2026	Big
120		FHC - beside ST-1	Dry	1	✓		13/03/2026	Overcharge
121		FHC - beside ST-2	Dry	1	✓		13/03/2026	Overcharge
122	16	FHC - Front of Service Lift	Dry	1	✓		13/03/2026	Big
123		Front of Guest Lift	Dry	1	✓		13/03/2026	Recharge
124		E & E Room	CO2	1	✓		18/03/2026	Big
125		Beside Apt#1601	Dry	1	✓		13/03/2026	Big
126		Beside Apt#1617	Dry	1	✓		13/03/2026	Big
127		FHC - beside ST-1	Dry	1	✓		13/03/2026	Big
128		FHC - beside ST-2	Dry	1	✓		13/03/2026	Big

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
129	17	FHC - Front of Service Lift	Dry	1	✓		13/03/2026	Overcharge
130		Front of Guest Lift	Dry	1	✓		13/03/2026	Overcharge
131		E & E Room	CO2	1	✓		18/03/2026	Big
132		Beside Apt#1701	Dry	1	✓		13/03/2026	Big
133		Beside Apt#1717	Dry	1	✓		13/03/2026	Recharge
134		FHC - beside ST-1	Dry	1	✓		13/03/2026	Big
135		FHC - beside ST-2 (15 lbs.)	Dry	1	✓		13/03/2026	Overcharge
136	18	FHC - Front of Service Lift	Dry	1	✓		13/03/2026	Overcharge
137		Front of Guest Lift	Dry	1	✓		13/03/2026	Big
138		E & E Room	CO2	1	✓		18/03/2026	Big
139		Beside Apt#1801	Dry	1	✓		13/03/2026	Overcharge
140		Beside Apt#1817	Dry	1	✓		13/03/2026	Overcharge
141		FHC - beside ST-1	Dry	1	✓		13/03/2026	Big
142		FHC - beside ST-2	Dry	1	✓		13/03/2026	Big
143	19	FHC - Front of Service Lift	Dry	1	✓		13/03/2026	Overcharge
144		Front of Guest Lift	Dry	1	✓		13/03/2026	Big
145		E & E Room	CO2	1	✓		18/03/2026	Big
146		Beside Apt#1901	Dry	1	✓		13/03/2026	Big
147		Beside Apt#1917	Dry	1	✓		13/03/2026	Overcharge
148		FHC - beside ST-1	Dry	1	✓		13/03/2026	Overcharge
149		FHC - beside ST-2	Dry	1	✓		13/03/2026	Big
150	20	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Overcharge
151		Front of Guest Lift	Dry	1	✓		10/03/2026	Overcharge
152		E & E Room	CO2	1	✓		18/03/2026	Big
153		Beside Apt#2001	Dry	1	✓		10/03/2026	Big
154		Beside Apt#2017	Dry	1	✓		10/03/2026	Overcharge
155		FHC - beside ST-1	Dry	1	✓		10/03/2026	Big
156		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
157	21	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
158		Front of Guest Lift	Dry	1	✓		10/03/2026	Overcharge
159		E & E Room	CO2	1	✓		10/03/2026	Big
160		Beside Apt#2101	Dry	1	✓		10/03/2026	Big
161		Beside Apt#2117	Dry	1	✓		10/03/2026	Overcharge
162		FHC - beside ST-1	Dry	1	✓		10/03/2026	Overcharge
163		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
164	22	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
165		Front of Guest Lift	Dry	1	✓		10/03/2026	Overcharge
166		E & E Room	CO2	1	✓		18/03/2026	Big
167		Beside Apt#2201	Dry	1	✓		10/03/2026	Overcharge
168		Beside Apt#2217	Dry	1	✓		10/03/2026	Overcharge
169		FHC - beside ST-1	Dry	1	✓		10/03/2026	Overcharge
170		FHC - beside ST-2	Dry	1	✓		10/03/2026	Overcharge
171	23	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
172		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
173		E & E Room	CO2	1	✓		18/03/2026	Big
174		Beside Apt#2301	Dry	1	✓		10/03/2026	Overcharge
175		Beside Apt#2317	Dry	1	✓		10/03/2026	Overcharge
176		FHC - beside ST-1	Dry	1	✓		10/03/2026	Overcharge
177		FHC - beside ST-2	Dry	1	✓		10/03/2026	Overcharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
178	24	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
179		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
180		E & E Room	CO2	1	✓		18/03/2026	Big
181		Beside Apt#2401	Dry	1	✓		10/03/2026	Big
182		Beside Apt#2415	Dry	1	✓		10/03/2026	Big
183		FHC - beside ST-1	Dry	1	✓		10/03/2026	Big
184		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
185	25	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
186		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
187		E & E Room	CO2	1	✓		18/03/2026	Big
188		Beside Apt#2501	Dry	1	✓		10/03/2026	Big
189		Beside Apt#2517	Dry	1	✓		10/03/2026	Big
190		FHC - beside ST-1	Dry	1	✓		10/03/2026	Big
191		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
192	26	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
193		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
194		E & E Room	CO2	1	✓		18/03/2026	Big
195		Beside Apt#2601	Dry	1	✓		10/03/2026	Big
196		Beside Apt#2615	Dry	1	✓		10/03/2026	Big
197		FHC - beside ST-1	Dry	1	✓		10/03/2026	Big
198		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
199	27	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
200		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
201		E & E Room	CO2	1	✓		18/03/2026	Big
202		FHC - Sky Garden	Dry	1	✓		10/03/2026	Big
203		Beside Apt#2710	Dry	1	✓		10/03/2026	Big
204		Beside Apt#2715	Dry	1	✓		10/03/2026	Big
205		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
206	28	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
207		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
208		E & E Room	CO2	1	✓		18/03/2026	Big
209		Beside Apt#2809	Dry	1	✓		10/03/2026	Big
210		Beside Apt#2815	Dry	1	✓		10/03/2026	Big
211		FHC - beside ST-2	Dry	1	✓		10/03/2026	Overcharge
212	29	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
213		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
214		E & E Room	CO2	1	✓		18/03/2026	Big
215		Beside Apt#2909	Dry	1	✓		10/03/2026	Big
216		Beside Apt#2915	Dry	1	✓		10/03/2026	Big
217		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
218	30	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
219		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
220		E & E Room	CO2	1	✓		18/03/2026	Big
221		Beside Apt#3009	Dry	1	✓		10/03/2026	Recharge
222		Beside Apt#3015	Dry	1	✓		10/03/2026	Big
223		FHC - beside ST-2	Dry	1	✓		10/03/2026	Overcharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
224	31	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
225		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
226		E & E Room	CO2	1	✓		18/03/2026	Big
227		Beside Apt#3109	Dry	1	✓		10/03/2026	Big
228		Beside Apt#3115	Dry	1	✓		10/03/2026	Big
229		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
230	32	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
231		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
232		E & E Room	CO2	1	✓		18/03/2026	Big
233		Beside Apt#3209	Dry	1	✓		10/03/2026	Big
234		Beside Apt#3215	Dry	1	✓		10/03/2026	Big
235		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
236	33	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
237		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
238		E & E Room	CO2	1	✓		18/03/2026	Big
239		Beside Apt#3309	Dry	1	✓		10/03/2026	Big
240		Beside Apt#3315	Dry	1	✓		10/03/2026	Big
241		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
242	34	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
243		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
244		E & E Room	CO2	1	✓		18/03/2026	Big
245		Beside Apt#3409	Dry	1	✓		10/03/2026	Big
246		Beside Apt#3415	Dry	1	✓		10/03/2026	Big
247		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
248	35	FHC - Front of Service Lift	Dry	1	✓		10/03/2026	Big
249		Front of Guest Lift	Dry	1	✓		10/03/2026	Big
250		E & E Room	CO2	1	✓		18/03/2026	Big
251		Beside Apt#3509	Dry	1	✓		10/03/2026	Big
252		Beside Apt#3515	Dry	1	✓		10/03/2026	Big
253		FHC - beside ST-2	Dry	1	✓		10/03/2026	Big
254	36	FHC-Roof-ST-1	Dry	1	✓		18/03/2026	Big
255		Control lift Rooftop	CO2	1	✓		18/03/2026	Big
256		FHC-Roof-ST-2	Dry	1	✓		18/03/2026	Big

Note:

All Fire Extinguisher on Public area tatol 308 tanks.

** Dry Cemical Overcharge 59 Tanks. (เข้มย้งอยู่ในลิ้เขี้ยว)

** Dry Cemical Recharge 16 Tanks. (เข้มย้งอยู่ในลิ้เขี้ยว)

** Total 75 Tanks (ย้งไ้ใช้งานไ้ได้อยู่)

** Dry Cemical Out of order 8 Tanks.

** Co2 = 1 tank.

** Total 9 Tanks. Keep in Security Store. (Dry 10 lib = 7 tanks, and =Dry 15 lbs = 1, Co2 = 1 tank)

***** Total 84 Tanks.*****

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Yes	No		
1	230	Dry Chemical (10 lbs)	222	8		Recharge 5, รั่ว 1, แข็ง 1
2	44	CO2	43	1		น้ำหนักต่ำเกิน (ใช้เทรนนิ่ง)
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	433	12		3 Out of Order, 9 Overcharge, Keep SEC Store
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	5	1		Out of order 1
Total	753		731	22		

Reported by: Akapol NUNTAWONG
Senior Security Supervisor

Acknowledged by: _____
Security Manager

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry	1	✓		06/04/2026	Stone
2		FHC - Front of FCC	Dry	1	✓		06/04/2026	Stone
3		Gas Station (15 lbs)	Dry	2	✓		06/04/2026	Stone
4		Front of Garbage Room	Dry	1	✓		06/04/2026	Stone
5		Front of Housekeeping Store	Dry	1	✓		06/04/2026	Stone
6		Fire Cart	Dry	1	✓		06/04/2026	Stone
7		Security Store	Dry	8	✓		06/04/2026	Out of order 6, แบต 1 ไร่
8		Security Store (15 lbs)	Dry	3	✓		06/04/2026	Out of order 1
9		Security Store (20 lbs)	Dry	2	✓		06/04/2026	Stone
10		In front of Electrical room (50lbs)	Dry	2	✓		06/04/2026	Stone
11		Security Store	ADE	4	✓		06/04/2026	Stone
12		Electrical Room	ADE	1	✓		06/04/2026	Stone
13		Engineering Workshop	ADE	2	✓		05/04/2026	Stone
14		Engineering Store	ADE	1	✓		06/04/2026	Stone
15		Chemical Room	ADE	2	✓		05/04/2026	Stone
16		Houskeeping Store	ADE	1	✓		05/04/2026	Stone
17		Houskeeping Office	ADE	1	✓		05/04/2026	Stone
18		FCC Room	ADE	1	✓		05/04/2026	Stone
19		Fire Pump Room	ADE	2	✓		06/04/2026	Stone
20		Finance Accounting Office	ADE	1	✓		09/04/2026	Stone
21		Staff Canteen Room	ADE	1	✓		06/04/2026	Stone
22		Fire Cart	CO2	1	✓		06/04/2026	Stone
23		FCC Room	CO2	1	✓		06/04/2026	Stone
24		Security Store	CO2	10	✓		06/04/2026	1 น้หนักต่ำเกณฑ์
25		Fire Pump Room	Dry	1	✓		06/04/2026	Stone
26		Front of Timekeeper	Dry	1	✓		06/04/2026	Stone
27	G	FHC - Front of Service Lift	Dry	1	✓		06/04/2026	Stone
25		MDB and Generator	ADE	2	✓		09/04/2026	Stone
26		Server Room	ADE	2	✓		09/04/2026	Stone
27		Guest Service Office	ADE	1	✓		09/04/2026	Stone
28		Executive Office	ADE	1	✓		06/04/2026	Stone
29		Server Room	CO2	1	✓		09/04/2026	Stone
30		FHC - Front of Saver Room	CO2	1	✓		06/04/2026	Stone
31		FHC - Front ST-2	Dry	1	✓		06/04/2026	Stone
32	2	FHC - Front of Service Lift	Dry	1	✓		06/04/2026	Stone
33		Front of First aid Room	Dry	1	✓		06/04/2026	Stone
34		Front of HK Store	Dry	1	✓		06/04/2026	Stone
35		Rama 9 Sound Control Room	CO2	1	✓		06/04/2026	Stone
36		FHC - Front of ST-1	Dry	1	✓		06/04/2026	Stone
37		FHC - Front of ST-2	Dry	1	✓		06/04/2026	Stone
38	3	FHC - Front of Service Lift	Dry	1	✓		06/04/2026	Overcharge
18		Front of Guest Lift	Dry	1	✓		06/04/2026	Overcharge
19		FHC - Front of ST-1	Dry	1	✓		06/04/2026	Recharge
20		Parking Area Zone 4B	Dry	1	✓		06/04/2026	Stone
21		FHC - Front of ST-2	Dry	1	✓		06/04/2026	Overcharge
22		Parking Area Zone 2A	Dry	1	✓		06/04/2026	Overcharge
23	4	FHC - Front of Service Lift	Dry	1	✓		06/04/2026	Overcharge
24		Front of Guest Lift	Dry	1	✓		06/04/2026	Overcharge
25		FHC - Front of ST-1	Dry	1	✓		06/04/2026	Recharge
26		Parking Area Zone 4B	Dry	1	✓		06/04/2026	Overcharge
27		FHC - Front of ST-2	Dry	1	✓		06/04/2026	Recharge
28		Parking Area Zone 2A	Dry	1	✓		06/04/2026	Overcharge
29		Parking Area Zone 8A	Dry	1	✓		06/04/2026	Overcharge
30		Parking Area Zone C	Dry	1	✓		06/04/2026	Recharge

No.	Fl.	Location	Type	Total	Status			Remark
					Yes	No		
31	5	FHC - Front of Service Lift	Dry	1	✓		06/04/2026	Overcharge
32		Front of Guest Lift	Dry	1	✓		06/04/2026	Recharge
33		FHC - Front of ST-1	Dry	1	✓		06/04/2026	Recharge
34		Parking Area Zone 4B	Dry	1	✓		06/04/2026	Overcharge
35		FHC - Front of ST-2	Dry	1	✓		06/04/2026	Overcharge
36		Parking Area Zone 2A	Dry	1	✓		06/04/2026	Recharge
37		Parking Area Zone 8A	Dry	1	✓		06/04/2026	Overcharge
38		Parking Area Zone C	Dry	1	✓		06/04/2026	Recharge
39	6	FHC - Front of Service Lift	Dry	1	✓		06/04/2026	Stone
40		Front of Guest Lift	Dry	1	✓		06/04/2026	Stone
41		FHC - Front of ST-1	Dry	1	✓		06/04/2026	Stone
42		Parking Area Zone 4B	Dry	1	✓		06/04/2026	Stone
43		Inside ST-2	Dry	1	✓		06/04/2026	Stone
44		FHC - Front of ST-2	Dry	1	✓		06/04/2026	Stone
45		Parking Area Zone 2A	Dry	1	✓		06/04/2026	Stone
46		Parking Area Zone 8A	Dry	1	✓		06/04/2026	Overcharge
47		Parking Area Zone C	Dry	1	✓		06/04/2026	Recharge
48	7	FHC - Front of Service Lift	Dry	1	✓		06/04/2026	Stone
49		Front of Guest Lift	Dry	1	✓		06/04/2026	Recharge
50		FHC - Front of ST-1	Dry	1	✓		06/04/2026	Stone
51		Parking Area Zone 4B	Dry	1	✓		06/04/2026	Stone
52		Inside ST-2	Dry	1	✓		06/04/2026	Overcharge
53		FHC - Front of ST-2	Dry	1	✓		06/04/2026	Stone
54		Parking Area Zone 2A	Dry	1	✓		06/04/2026	Overcharge
55		Parking Area Zone 8A	Dry	1	✓		06/04/2026	Stone
56		Parking Area Zone C	Dry	1	✓		06/04/2026	Overcharge
57	7M	FHC - Front of Service Lift	Dry	1	✓		06/04/2026	Stone
58		Front of Guest Lift	Dry	1	✓		06/04/2026	Stone
59		Pool Pump Room	Dry	1	✓		06/04/2026	Stone
60		Front of Pump room	Dry	1	✓		06/04/2026	Stone
61		Parking Area Zone A	Dry	1	✓		06/04/2026	Stone
62		FHC - Front of ST-1	Dry	1	✓		06/04/2026	Overcharge
63		Parking Area Zone 2A	Dry	1	✓		06/04/2026	Stone
64		FHC - Inside ST-2	Dry	1	✓		09/04/2026	Stone
65		Inside ST-2	Dry	1	✓		09/04/2026	Stone
66	8	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Overcharge
67		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
68		E & E Room	CO2	1	✓			
69		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
70		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
71		Front of Apt#810	Dry	1	✓		02/04/2026	Overcharge
72		Beside Apt#817	Dry	1	✓		02/04/2026	Stone
73	9	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
74		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
75		E & E Room	CO2	1	✓			
76		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
77		FHC - beside ST-2	Dry	1	✓		02/04/2026	Overcharge
78		Front of Apt#910	Dry	1	✓		02/04/2026	Overcharge
79		Beside Apt#917	Dry	1	✓		02/04/2026	Stone

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
80	10	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
81		Front of Guest Lift	Dry	1	✓		02/04/2026	Overcharge
82		E & E Room	CO2	1	✓			
83		Beside Apt#1001	Dry	1	✓		02/04/2026	Stone
84		Beside Apt#1017	Dry	1	✓		02/04/2026	Stone
85		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
86		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
87	11	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Recharge
88		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
89		E & E Room	CO2	1	✓			
90		Beside Apt#1101	Dry	1	✓		02/04/2026	Stone
91		Beside Apt#1117	Dry	1	✓		02/04/2026	Stone
92		FHC - beside ST-1	Dry	1	✓		02/04/2026	Overcharge
93		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
94	12	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
95		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
96		E & E Room	CO2	1	✓			
97		Beside Apt#1201	Dry	1	✓		02/04/2026	Recharge
98		Beside Apt#1217	Dry	1	✓		02/04/2026	Stone
99		FHC - beside ST-1	Dry	1	✓		02/04/2026	Overcharge
100		FHC - beside ST-2	Dry	1	✓		02/04/2026	
101	13	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Overcharge
102		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
103		E & E Room	CO2	1	✓			
104		Beside Apt#1301	Dry	1	✓		02/04/2026	Stone
105		Beside Apt#1317	Dry	1	✓		02/04/2026	Stone
106		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
107		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
108	14	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Overcharge
109		Front of Guest Lift	Dry	1	✓		02/04/2026	Overcharge
110		E & E Room	CO2	1	✓			
111		Beside Apt#1401	Dry	1	✓		02/04/2026	Stone
112		Beside Apt#1417	Dry	1	✓		02/04/2026	Recharge
113		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
114		FHC - beside ST-2	Dry	1	✓		02/04/2026	Overcharge
115	15	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Overcharge
116		Front of Guest Lift	Dry	1	✓		02/04/2026	Overcharge
117		E & E Room	CO2	1	✓			
118		Beside Apt#1501	Dry	1	✓		02/04/2026	Stone
119		Beside Apt#1517	Dry	1	✓		02/04/2026	Stone
120		FHC - beside ST-1	Dry	1	✓		02/04/2026	Overcharge
121		FHC - beside ST-2	Dry	1	✓		02/04/2026	Overcharge
122	16	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
123		Front of Guest Lift	Dry	1	✓		02/04/2026	Recharge
124		E & E Room	CO2	1	✓			
125		Beside Apt#1601	Dry	1	✓		02/04/2026	Stone
126		Beside Apt#1617	Dry	1	✓		02/04/2026	Stone
127		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
128		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
129	17	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Overcharge
130		Front of Guest Lift	Dry	1	✓		02/04/2026	Overcharge
131		E & E Room	CO2	1	✓		08/04/2026	Stone
132		Beside Apt#1701	Dry	1	✓		02/04/2026	Stone
133		Beside Apt#1717	Dry	1	✓		02/04/2026	Recharge
134		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
135		FHC - beside ST-2 (15 lbs.)	Dry	1	✓		02/04/2026	Overcharge
136	18	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Overcharge
137		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
138		E & E Room	CO2	1	✓		08/04/2026	Stone
139		Beside Apt#1801	Dry	1	✓		02/04/2026	Overcharge
140		Beside Apt#1817	Dry	1	✓		02/04/2026	Overcharge
141		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
142		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
143	19	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Overcharge
144		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
145		E & E Room	CO2	1	✓		08/04/2026	Stone
146		Beside Apt#1901	Dry	1	✓		02/04/2026	Stone
147		Beside Apt#1917	Dry	1	✓		02/04/2026	Overcharge
148		FHC - beside ST-1	Dry	1	✓		02/04/2026	Overcharge
149		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
150	20	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Overcharge
151		Front of Guest Lift	Dry	1	✓		02/04/2026	Overcharge
152		E & E Room	CO2	1	✓		08/04/2026	Stone
153		Beside Apt#2001	Dry	1	✓		02/04/2026	Stone
154		Beside Apt#2017	Dry	1	✓		02/04/2026	Overcharge
155		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
156		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
157	21	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
158		Front of Guest Lift	Dry	1	✓		02/04/2026	Overcharge
159		E & E Room	CO2	1	✓		08/04/2026	Stone
160		Beside Apt#2101	Dry	1	✓		02/04/2026	Stone
161		Beside Apt#2117	Dry	1	✓		02/04/2026	Overcharge
162		FHC - beside ST-1	Dry	1	✓		02/04/2026	Overcharge
163		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
164	22	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
165		Front of Guest Lift	Dry	1	✓		02/04/2026	Overcharge
166		E & E Room	CO2	1	✓		08/04/2026	Stone
167		Beside Apt#2201	Dry	1	✓		02/04/2026	Overcharge
168		Beside Apt#2217	Dry	1	✓		02/04/2026	Overcharge
169		FHC - beside ST-1	Dry	1	✓		02/04/2026	Overcharge
170		FHC - beside ST-2	Dry	1	✓		02/04/2026	Overcharge
171	23	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
172		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
173		E & E Room	CO2	1	✓		08/04/2026	Stone
174		Beside Apt#2301	Dry	1	✓		02/04/2026	Overcharge
175		Beside Apt#2317	Dry	1	✓		02/04/2026	Overcharge
176		FHC - beside ST-1	Dry	1	✓		02/04/2026	Overcharge
177		FHC - beside ST-2	Dry	1	✓		02/04/2026	Overcharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
178	24	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
179		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
180		E & E Room	CO2	1	✓		08/04/2026	Stone
181		Beside Apt#2401	Dry	1	✓		02/04/2026	Stone
182		Beside Apt#2415	Dry	1	✓		02/04/2026	Stone
183		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
184		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
185	25	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
186		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
187		E & E Room	CO2	1	✓		08/04/2026	Stone
188		Beside Apt#2501	Dry	1	✓		02/04/2026	Stone
189		Beside Apt#2517	Dry	1	✓		02/04/2026	Stone
190		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
191		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
192	26	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
193		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
194		E & E Room	CO2	1	✓		05/04/2026	Big
195		Beside Apt#2601	Dry	1	✓		02/04/2026	Stone
196		Beside Apt#2615	Dry	1	✓		02/04/2026	Stone
197		FHC - beside ST-1	Dry	1	✓		02/04/2026	Stone
198		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
199	27	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
200		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
201		E & E Room	CO2	1	✓		05/04/2026	Big
202		FHC - Sky Garden	Dry	1	✓		02/04/2026	Stone
203		Beside Apt#2710	Dry	1	✓		02/04/2026	Stone
204		Beside Apt#2715	Dry	1	✓		02/04/2026	Stone
205		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
206	28	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
207		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
208		E & E Room	CO2	1	✓		05/04/2026	Big
209		Beside Apt#2809	Dry	1	✓		02/04/2026	Stone
210		Beside Apt#2815	Dry	1	✓		02/04/2026	Stone
211		FHC - beside ST-2	Dry	1	✓		02/04/2026	Overcharge
212	29	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
213		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
214		E & E Room	CO2	1	✓		05/04/2026	Big
215		Beside Apt#2909	Dry	1	✓		02/04/2026	Stone
216		Beside Apt#2915	Dry	1	✓		02/04/2026	Stone
217		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
218	30	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
219		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
220		E & E Room	CO2	1	✓		05/04/2026	Big
221		Beside Apt#3009	Dry	1	✓		02/04/2026	Recharge
222		Beside Apt#3015	Dry	1	✓		02/04/2026	Stone
223		FHC - beside ST-2	Dry	1	✓		02/04/2026	Overcharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
224	31	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
225		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
226		E & E Room	CO2	1	✓		05/04/2026	Big
227		Beside Apt#3109	Dry	1	✓		02/04/2026	Stone
228		Beside Apt#3115	Dry	1	✓		02/04/2026	Stone
229		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
230	32	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
231		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
232		E & E Room	CO2	1	✓		05/04/2026	Big
233		Beside Apt#3209	Dry	1	✓		02/04/2026	Stone
234		Beside Apt#3215	Dry	1	✓		02/04/2026	Stone
235		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
236	33	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
237		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
238		E & E Room	CO2	1	✓		05/04/2026	Big
239		Beside Apt#3309	Dry	1	✓		02/04/2026	Stone
240		Beside Apt#3315	Dry	1	✓		02/04/2026	Stone
241		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
242	34	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
243		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
244		E & E Room	CO2	1	✓		05/04/2026	Big
245		Beside Apt#3409	Dry	1	✓		02/04/2026	Stone
246		Beside Apt#3415	Dry	1	✓		02/04/2026	Stone
247		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
248	35	FHC - Front of Service Lift	Dry	1	✓		02/04/2026	Stone
249		Front of Guest Lift	Dry	1	✓		02/04/2026	Stone
250		E & E Room	CO2	1	✓		05/04/2026	Big
251		Beside Apt#3509	Dry	1	✓		02/04/2026	Stone
252		Beside Apt#3515	Dry	1	✓		02/04/2026	Stone
253		FHC - beside ST-2	Dry	1	✓		02/04/2026	Stone
254	36	FHC-Roof-ST-1	Dry	1	✓		01/04/2026	Big
255		Control lift Rooftop	CO2	1	✓		01/04/2026	Big
256		FHC-Roof-ST-2	Dry	1	✓		01/04/2026	Big

Note: All Fire Extinguisher on Public area tatol 308 tanks.
 ** Dry Cemical Overcharge 59 Tanks. (เข้มย้งอยู่ในลิ้เขียวก)
 ** Dry Cemical Recharge 16 Tanks. (เข้มย้งอยู่ในลิ้เขียวก)
 ** Total 75 Tanks (ย้งใช้้งานได้อยู่)

 ** Dry Cemical Out of order 8 Tanks.
 ** Co2 = 1 tank.
 ** Total 9 Tanks. Keep in Security Store. (Dry 10 lib = 7 tanks, and =Dry 15 lbs = 1, Co2 = 1 tank)
 ***** Total 84 Tanks.*****

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Yes	No		
1	230	Dry Chemical (10 lbs)	222	8		Recharge 5, รั่ว 1, แฉิง 1
2	44	CO2	43	1		น้ำหนักต่ำ เกจเซฟ (ใช้เทรนนิง)
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	433	12		3 Out of Order, 9 Overcharge, Keep SEC Store
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	5	1		Out of order 1
Total	753		731	22		

Reported by: Stone PHONYIAM
Security Supervisor

Acknowledged by: _____
Security Manager

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry	1	✓		15/05/2026	Big
2		FHC - Front of FCC	Dry	1	✓		15/05/2026	Big
3		Gas Station (15 lbs)	Dry	2	✓		14/05/20026	Big
4		Front of Garbage Room	Dry	1	✓		15/05/2026	Big
5		Front of Housekeeping Store	Dry	1	✓		14/05/20026	Big
6		Fire Cart	Dry	1	✓		15/05/2026	Big
7		Security Store	Dry	8	✓		14/05/20026	Big
8		Security Store (15 lbs)	Dry	3	✓		14/05/20026	Big
9		Security Store (20 lbs)	Dry	2	✓		14/05/20026	Big
10		In fornt of Electrical room (50lbs)	Dry	2	✓		14/05/2026	Big
11		Security Store	ADE	4	✓		14/05/20026	Big
12		Electrical Room	ADE	1	✓		14/05/2026	Big
13		Engineering Workshop	ADE	2	✓		14/05/20026	Big
14		Engineering Store	ADE	1	✓		14/05/20026	Big
15		Chemical Room	ADE	2	✓		14/05/20026	Big
16		Houskeeping Store	ADE	1	✓		14/05/20026	Big
17		Houskeeping Office	ADE	1	✓		14/05/20026	Big
18		FCC Room	ADE	1	✓		14/05/20026	Big
19		Fire Pump Room	ADE	2	✓		15/05/2026	Big
20		Finance Accounting Office	ADE	1	✓		15/05/2026	Big
21		Staff Canteen Room	ADE	1	✓		14/05/20026	Big
22		Fire Cart	CO2	1	✓		15/05/2026	Big
23		FCC Room	CO2	1	✓		15/05/2026	Big
24		Security Store	CO2	10	✓		14/05/2026	Big
25		Fire Pump Room	Dry	1	✓		14/05/2026	Big
26		Front of Timekeeper	Dry	1	✓		15/05/2026	Big
27	G	FHC - Front of Service Lift	Dry	1	✓		15/05/2026	Big
25		MDB and Generator	ADE	2	✓		15/05/2026	Big
26		Server Room	ADE	2	✓		15/05/2026	Big
27		Guest Service Office	ADE	1	✓		15/05/2026	Big
28		Executive Office	ADE	1	✓		13/05/2026	Big
29		Server Room	CO2	1	✓		15/05/2026	Big
30		FHC - Front of Saver Room	CO2	1	✓		15/05/2026	Big
31		FHC - Front ST-2	Dry	1	✓		15/05/2026	Big
32	2	FHC - Front of Service Lift	Dry	1	✓		15/05/2026	Big
33		Front of First aid Room	Dry	1	✓		15/05/2026	Big
34		Front of HK Store	Dry	1	✓		14/05/2026	Big
35		Rama 9 Sound Control Room	CO2	1	✓		15/05/2026	Big
36		FHC - Front of ST-1	Dry	1	✓		14/05/2026	Big
37		FHC - Front of ST-2	Dry	1	✓		14/05/2026	Big
38	3	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Overcharge
18		Front of Guest Lift	Dry	1	✓		09/05/2026	Overcharge
19		FHC - Front of ST-1	Dry	1	✓		09/05/2026	Big
20		Parking Area Zone 4B	Dry	1	✓		09/05/2026	Big
21		FHC - Front of ST-2	Dry	1	✓		09/05/2026	Big
22		Parking Area Zone 2A	Dry	1	✓		09/05/2026	Big
23	4	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
24		Front of Guest Lift	Dry	1	✓		09/05/2026	Overcharge
25		FHC - Front of ST-1	Dry	1	✓		09/05/2026	Big
26		Parking Area Zone 4B	Dry	1	✓		09/05/2026	Big
27		FHC - Front of ST-2	Dry	1	✓		09/05/2026	Big
28		Parking Area Zone 2A	Dry	1	✓		09/05/2026	Big
29		Parking Area Zone 8A	Dry	1	✓		09/05/2026	Big
30		Parking Area Zone C	Dry	1	✓		09/05/2026	Big

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
31	5	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
32		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
33		FHC - Front of ST-1	Dry	1	✓		09/05/2026	Big
34		Parking Area Zone 4B	Dry	1	✓		09/05/2026	Big
35		FHC - Front of ST-2	Dry	1	✓		09/05/2026	Big
36		Parking Area Zone 2A	Dry	1	✓		09/05/2026	Big
37		Parking Area Zone 8A	Dry	1	✓		09/05/2026	Big
38		Parking Area Zone C	Dry	1	✓		09/05/2026	Big
39	6	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
40		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
41		FHC - Front of ST-1	Dry	1	✓		09/05/2026	Big
42		Parking Area Zone 4B	Dry	1	✓		09/05/2026	Big
43		Inside ST-2	Dry	1	✓		09/05/2026	Big
44		FHC - Front of ST-2	Dry	1	✓		09/05/2026	Big
45		Parking Area Zone 2A	Dry	1	✓		09/05/2026	Big
46		Parking Area Zone 8A	Dry	1	✓		09/05/2026	Big
47		Parking Area Zone C	Dry	1	✓		09/05/2026	Big
48	7	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
49		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
50		FHC - Front of ST-1	Dry	1	✓		09/05/2026	Big
51		Parking Area Zone 4B	Dry	1	✓		09/05/2026	Big
52		Inside ST-2	Dry	1	✓		09/05/2026	Big
53		FHC - Front of ST-2	Dry	1	✓		09/05/2026	Big
54		Parking Area Zone 2A	Dry	1	✓		09/05/2026	Big
55		Parking Area Zone 8A	Dry	1	✓		09/05/2026	Big
56		Parking Area Zone C	Dry	1	✓		09/05/2026	Big
57	7M	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
58		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
59		Pool Pump Room	Dry	1	✓		09/05/2026	Big
60		Front of Pump room	Dry	1	✓		09/05/2026	Big
61		Parking Area Zone A	Dry	1	✓		09/05/2026	Big
62		FHC - Front of ST-1	Dry	1	✓		09/05/2026	Big
63		Parking Area Zone 2A	Dry	1	✓		09/05/2026	Big
64		FHC - Inside ST-2	Dry	1	✓		09/05/2026	Big
65		Inside ST-2	Dry	1	✓		09/05/2026	Big
66	8	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
67		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
68		E & E Room	CO2	1	✓		15/05/2026	Big
69		FHC - beside ST-1	Dry	1	✓		15/05/2026	Overcharge
70		FHC - beside ST-2	Dry	1	✓		09/05/2026	Big
71		Front of Apt#810	Dry	1	✓		09/05/2026	Big
72		Beside Apt#817	Dry	1	✓		09/05/2026	Big
73	9	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
74		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
75		E & E Room	CO2	1	✓		15/05/2026	Big
76		FHC - beside ST-1	Dry	1	✓		09/05/2026	Big
77		FHC - beside ST-2	Dry	1	✓		09/05/2026	Big
78		Front of Apt#910	Dry	1	✓		09/05/2026	Overcharge
79		Beside Apt#917	Dry	1	✓		09/05/2026	Big

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
80	10	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
81		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
82		E & E Room	CO2	1	✓		09/05/2026	Big
83		Beside Apt#1001	Dry	1	✓		09/05/2026	Big
84		Beside Apt#1017	Dry	1	✓		09/05/2026	Big
85		FHC - beside ST-1	Dry	1	✓		09/05/2026	Big
86		FHC - beside ST-2	Dry	1	✓		09/05/2026	Big
87	11	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
88		Front of Guest Lift	Dry	1	✓		09/05/2026	Overcharge
89		E & E Room	CO2	1	✓		09/05/2026	Big
90		Beside Apt#1101	Dry	1	✓		09/05/2026	Big
91		Beside Apt#1117	Dry	1	✓		09/05/2026	Big
92		FHC - beside ST-1	Dry	1	✓		09/05/2026	Big
93		FHC - beside ST-2	Dry	1	✓		09/05/2026	Big
94	12	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
95		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
96		E & E Room	CO2	1	✓		09/05/2026	Big
97		Beside Apt#1201	Dry	1	✓		09/05/2026	Big
98		Beside Apt#1217	Dry	1	✓		09/05/2026	Big
99		FHC - beside ST-1	Dry	1	✓		09/05/2026	Big
100		FHC - beside ST-2	Dry	1	✓		09/05/2026	Big
101	13	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
102		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
103		E & E Room	CO2	1	✓		09/05/2026	Big
104		Beside Apt#1301	Dry	1	✓		09/05/2026	Big
105		Beside Apt#1317	Dry	1	✓		09/05/2026	Big
106		FHC - beside ST-1	Dry	1	✓		09/05/2026	Big
107		FHC - beside ST-2	Dry	1	✓		09/05/2026	Big
108	14	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Overcharge
109		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
110		E & E Room	CO2	1	✓		09/05/2026	Big
111		Beside Apt#1401	Dry	1	✓		09/05/2026	Big
112		Beside Apt#1417	Dry	1	✓		09/05/2026	Recharge
113		FHC - beside ST-1	Dry	1	✓		09/05/2026	Big
114		FHC - beside ST-2	Dry	1	✓		09/05/2026	Big
115	15	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
116		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
117		E & E Room	CO2	1	✓		09/05/2026	Big
118		Beside Apt#1501	Dry	1	✓		09/05/2026	Big
119		Beside Apt#1517	Dry	1	✓		09/05/2026	Big
120		FHC - beside ST-1	Dry	1	✓		09/05/2026	Big
121		FHC - beside ST-2	Dry	1	✓		09/05/2026	Overcharge
122	16	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
123		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
124		E & E Room	CO2	1	✓		09/05/2026	Big
125		Beside Apt#1601	Dry	1	✓		09/05/2026	Overcharge
126		Beside Apt#1617	Dry	1	✓		09/05/2026	Big
127		FHC - beside ST-1	Dry	1	✓		09/05/2026	Big
128		FHC - beside ST-2	Dry	1	✓		09/05/2026	Big

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
129	17	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Overcharge
130		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
131		E & E Room	CO2	1	✓		09/05/2026	Big
132		Beside Apt#1701	Dry	1	✓		09/05/2026	Big
133		Beside Apt#1717	Dry	1	✓		09/05/2026	Big
134		FHC - beside ST-1	Dry	1	✓		09/05/2026	Overcharge
135		FHC - beside ST-2	Dry	1	✓		09/05/2026	Big
136	18	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Overcharge
137		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
138		E & E Room	CO2	1	✓		09/05/2026	Big
139		Beside Apt#1801	Dry	1	✓		09/05/2026	Big
140		Beside Apt#1817	Dry	1	✓		09/05/2026	Big
141		FHC - beside ST-1	Dry	1	✓		09/05/2026	Big
142		FHC - beside ST-2	Dry	1	✓		09/05/2026	Big
143	19	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
144		Front of Guest Lift	Dry	1	✓		09/05/2026	Big
145		E & E Room	CO2	1	✓		09/05/2026	Big
146		Beside Apt#1901	Dry	1	✓		09/05/2026	Big
147		Beside Apt#1917	Dry	1	✓		09/05/2026	Big
148		FHC - beside ST-1	Dry	1	✓		09/05/2026	Big
149		FHC - beside ST-2	Dry	1	✓		09/05/2026	Big
150	20	FHC - Front of Service Lift	Dry	1	✓		09/05/2026	Big
151		Front of Guest Lift	Dry	1	✓		09/05/2026	Overcharge
152		E & E Room	CO2	1	✓		09/05/2026	Big
153		Beside Apt#2001	Dry	1	✓		09/05/2026	Big
154		Beside Apt#2017	Dry	1	✓		09/05/2026	Overcharge
155		FHC - beside ST-1	Dry	1	✓		09/05/2026	Overcharge
156		FHC - beside ST-2	Dry	1	✓		09/05/2026	Overcharge
157	21	FHC - Front of Service Lift	Dry	1	✓		08/05/2026	Big
158		Front of Guest Lift	Dry	1	✓		08/05/2026	Big
159		E & E Room	CO2	1	✓		08/05/2026	Big
160		Beside Apt#2101	Dry	1	✓		08/05/2026	Big
161		Beside Apt#2117	Dry	1	✓		08/05/2026	Big
162		FHC - beside ST-1	Dry	1	✓		08/05/2026	Big
163		FHC - beside ST-2	Dry	1	✓		08/05/2026	Big
164	22	FHC - Front of Service Lift	Dry	1	✓		08/05/2026	Big
165		Front of Guest Lift	Dry	1	✓		08/05/2026	Big
166		E & E Room	CO2	1	✓		08/05/2026	Big
167		Beside Apt#2201	Dry	1	✓		08/05/2026	Big
168		Beside Apt#2217	Dry	1	✓		08/05/2026	Big
169		FHC - beside ST-1	Dry	1	✓		08/05/2026	Big
170		FHC - beside ST-2	Dry	1	✓		08/05/2026	Big
171	23	FHC - Front of Service Lift	Dry	1	✓		08/05/2026	Big
172		Front of Guest Lift	Dry	1	✓		08/05/2026	Overcharge
173		E & E Room	CO2	1	✓		08/05/2026	Big
174		Beside Apt#2301	Dry	1	✓		08/05/2026	Big
175		Beside Apt#2317	Dry	1	✓		08/05/2026	Big
176		FHC - beside ST-1	Dry	1	✓		08/05/2026	Big
177		FHC - beside ST-2	Dry	1	✓		08/05/2026	Big

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
178	24	FHC - Front of Service Lift	Dry	1	✓		08/05/2026	Big
179		Front of Guest Lift	Dry	1	✓		08/05/2026	Big
180		E & E Room	CO2	1	✓		08/05/2026	Big
181		Beside Apt#2401	Dry	1	✓		08/05/2026	Big
182		Beside Apt#2415	Dry	1	✓		08/05/2026	Big
183		FHC - beside ST-1	Dry	1	✓		08/05/2026	Big
184		FHC - beside ST-2	Dry	1	✓		08/05/2026	Big
185	25	FHC - Front of Service Lift	Dry	1	✓		08/05/2026	Big
186		Front of Guest Lift	Dry	1	✓		08/05/2026	Big
187		E & E Room	CO2	1	✓		08/05/2026	Big
188		Beside Apt#2501	Dry	1	✓		08/05/2026	Big
189		Beside Apt#2517	Dry	1	✓		08/05/2026	Big
190		FHC - beside ST-1	Dry	1	✓		08/05/2026	Big
191		FHC - beside ST-2	Dry	1	✓		08/05/2026	Big
192	26	FHC - Front of Service Lift	Dry	1	✓		08/05/2026	Big
193		Front of Guest Lift	Dry	1	✓		08/05/2026	Big
194		E & E Room	CO2	1	✓		08/05/2026	Big
195		Beside Apt#2601	Dry	1	✓		08/05/2026	Big
196		Beside Apt#2615	Dry	1	✓		08/05/2026	Big
197		FHC - beside ST-1	Dry	1	✓		08/05/2026	Big
198		FHC - beside ST-2	Dry	1	✓		08/05/2026	Big
199	27	FHC - Front of Service Lift	Dry	1	✓		06/05/2026	Big
200		Front of Guest Lift	Dry	1	✓		06/05/2026	Big
201		E & E Room	CO2	1	✓		06/05/2026	Big
202		FHC - Sky Garden	Dry	1	✓		06/05/2026	Big
203		Beside Apt#2710	Dry	1	✓		06/05/2026	Big
204		Beside Apt#2715	Dry	1	✓		06/05/2026	Big
205		FHC - beside ST-2	Dry	1	✓		06/05/2026	Big
206	28	FHC - Front of Service Lift	Dry	1	✓		06/05/2026	Big
207		Front of Guest Lift	Dry	1	✓		06/05/2026	Big
208		E & E Room	CO2	1	✓		06/05/2026	Big
209		Beside Apt#2809	Dry	1	✓		06/05/2026	Big
210		Beside Apt#2815	Dry	1	✓		06/05/2026	Big
211		FHC - beside ST-2	Dry	1	✓		06/05/2026	Big
212	29	FHC - Front of Service Lift	Dry	1	✓		06/05/2026	Big
213		Front of Guest Lift	Dry	1	✓		06/05/2026	Big
214		E & E Room	CO2	1	✓		06/05/2026	Big
215		Beside Apt#2909	Dry	1	✓		06/05/2026	Big
216		Beside Apt#2915	Dry	1	✓		06/05/2026	Big
217		FHC - beside ST-2	Dry	1	✓		06/05/2026	Big
218	30	FHC - Front of Service Lift	Dry	1	✓		06/05/2026	Big
219		Front of Guest Lift	Dry	1	✓		06/05/2026	Big
220		E & E Room	CO2	1	✓		06/05/2026	Big
221		Beside Apt#3009	Dry	1	✓		06/05/2026	Big
222		Beside Apt#3015	Dry	1	✓		06/05/2026	Big
223		FHC - beside ST-2	Dry	1	✓		06/05/2026	Big

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
224	31	FHC - Front of Service Lift	Dry	1	✓		06/05/2026	Big
225		Front of Guest Lift	Dry	1	✓		06/05/2026	Big
226		E & E Room	CO2	1	✓		06/05/2026	Big
227		Beside Apt#3109	Dry	1	✓		06/05/2026	Big
228		Beside Apt#3115	Dry	1	✓		06/05/2026	Big
229		FHC - beside ST-2	Dry	1	✓		06/05/2026	Big
230	32	FHC - Front of Service Lift	Dry	1	✓		06/05/2026	Big
231		Front of Guest Lift	Dry	1	✓		06/05/2026	Big
232		E & E Room	CO2	1	✓		06/05/2026	Big
233		Beside Apt#3209	Dry	1	✓		06/05/2026	Big
234		Beside Apt#3215	Dry	1	✓		06/05/2026	Big
235		FHC - beside ST-2	Dry	1	✓		06/05/2026	Big
236	33	FHC - Front of Service Lift	Dry	1	✓		06/05/2026	Big
237		Front of Guest Lift	Dry	1	✓		06/05/2026	Big
238		E & E Room	CO2	1	✓		06/05/2026	Big
239		Beside Apt#3309	Dry	1	✓		06/05/2026	Big
240		Beside Apt#3315	Dry	1	✓		06/05/2026	Big
241		FHC - beside ST-2	Dry	1	✓		06/05/2026	Big
242	34	FHC - Front of Service Lift	Dry	1	✓		06/05/2026	Big
243		Front of Guest Lift	Dry	1	✓		06/05/2026	Big
244		E & E Room	CO2	1	✓		06/05/2026	Big
245		Beside Apt#3409	Dry	1	✓		06/05/2026	Big
246		Beside Apt#3415	Dry	1	✓		06/05/2026	Big
247		FHC - beside ST-2	Dry	1	✓		06/05/2026	Big
248	35	FHC - Front of Service Lift	Dry	1	✓		06/05/2026	Big
249		Front of Guest Lift	Dry	1	✓		06/05/2026	Big
250		E & E Room	CO2	1	✓		06/05/2026	Big
251		Beside Apt#3509	Dry	1	✓		06/05/2026	Big
252		Beside Apt#3515	Dry	1	✓		06/05/2026	Big
253		FHC - beside ST-2	Dry	1	✓		06/05/2026	Big
254	36	FHC-Roof-ST-1	Dry	1	✓		14/05/2026	Big
255		Control lift Rooftop	CO2	1	✓		14/05/2026	Big
256		FHC-Roof-ST-2	Dry	1	✓		14/05/2026	Big

Note:

Fire extinguisher was Overcharge and Recharge = 18 Tanks. All tank is can use it normal.

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Yes	No		
1	230	Dry Chemical (10 lbs)	229	1		Out of order 1
2	44	CO2	44	0		
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	443	2		2 Tanks Out of order
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	6	0		Out of order 1
Total	753		750	3		

Reported by: Akapol NUNTAWONG
Senior Security Supervisor

Acknowledged by: _____
Security Manager

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
1	B	FHC - Front of Service Lift	Dry	1	✓		05/06/2026	Bank
2		FHC - Front of FCC	Dry	1	✓		05/06/2026	Bank
3		Gas Station (15 lbs)	Dry	2	✓		05/06/2026	Bank
4		Front of Garbage Room	Dry	1	✓		05/06/2026	Bank
5		Front of Housekeeping Store	Dry	1	✓		05/06/2026	Bank
6		Fire Cart	Dry	1	✓		06/06/2026	Bank
7		Security Store	Dry	6	✓		06/06/2026	NG 1 Pcs.(Leak)
8		Security Store (15 lbs)	Dry	3	✓		06/06/2026	Bank
9		Security Store (20 lbs)	Dry	2	✓		06/06/2026	Bank
10		In front of Electrical room (50lbs)	Dry	2	✓		05/06/2026	Bank
11		Security Store	ADE	4	✓		06/06/2026	Bank
12		Electrical Room	ADE	1	✓		06/06/2026	Bank
13		Engineering Workshop	ADE	2	✓		05/06/2026	Bank
14		Engineering Store	ADE	1	✓		06/06/2026	Bank
15		Chemical Room	ADE	2	✓		06/06/2026	Bank
16		Houskeeping Store	ADE	1	✓		06/06/2026	Overcharge
17		Houskeeping Office	ADE	1	✓		05/06/2026	Bank
18		FCC Room	ADE	1	✓		05/06/2026	Bank
19		Fire Pump Room	ADE	2	✓		06/06/2026	Bank
20		Finance Accounting Office	ADE	1	✓		06/06/2026	Bank
21		Staff Canteen Room	ADE	1	✓		05/06/2026	Bank
22		Fire Cart	CO2	1	✓		06/06/2026	Bank
23		FCC Room	CO2	1	✓		05/06/2026	Bank
24		Security Store	CO2	10	✓		06/06/2026	Bank
25		Fire Pump Room	Dry	1	✓		06/06/2026	Bank
26		Front of Timekeeper	Dry	1	✓		05/06/2026	Bank
27	G	FHC - Front of Service Lift	Dry	1	✓		05/06/2026	Bank
25		MDB and Generator	ADE	2	✓		06/06/2026	Bank
26		Server Room	ADE	2	✓		06/06/2026	Bank
27		Guest Service Office	ADE	1	✓		06/06/2026	Bank
28		Executive Office	ADE	1	✓		06/06/2026	Bank
29		Server Room	CO2	1	✓		06/06/2026	Bank
30		FHC - Front of Saver Room	CO2	1	✓		05/06/2026	Bank
31	2	FHC - Front ST-2	Dry	1	✓		05/06/2026	Bank
32		FHC - Front of Service Lift	Dry	1	✓		05/06/2026	Bank
33		Front of First aid Room	Dry	1	✓		05/06/2026	Bank
34		Front of HK Store	Dry	1	✓		05/06/2026	Bank
35		Rama 9 Sound Control Room	CO2	1	✓		05/06/2026	Bank
36		FHC - Front of ST-1	Dry	1	✓		05/06/2026	Bank
37	3	FHC - Front of ST-2	Dry	1	✓		05/06/2026	Bank
38		FHC - Front of Service Lift	Dry	1	✓		04/06/2026	Overcharge
18		Front of Guest Lift	Dry	1	✓		04/06/2026	Overcharge
19		FHC - Front of ST-1	Dry	1	✓		04/06/2026	Bank
20		Parking Area Zone 4B	Dry	1	✓		04/06/2026	Overcharge
21		FHC - Front of ST-2	Dry	1	✓		04/06/2026	Overcharge
22	4	Parking Area Zone 2A	Dry	1	✓		04/06/2026	Overcharge
23		FHC - Front of Service Lift	Dry	1	✓		04/06/2026	Bank
24		Front of Guest Lift	Dry	1	✓		04/06/2026	Overcharge
25		FHC - Front of ST-1	Dry	1	✓		04/06/2026	Bank
26		Parking Area Zone 4B	Dry	1	✓		04/06/2026	Bank
27		FHC - Front of ST-2	Dry	1	✓		04/06/2026	Bank
28		Parking Area Zone 2A	Dry	1	✓		04/06/2026	Overcharge
29		Parking Area Zone 8A	Dry	1	✓		04/06/2026	Bank
30		Parking Area Zone C	Dry	1	✓		04/06/2026	Overcharge

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
31	5	FHC - Front of Service Lift	Dry	1	✓		04/06/2026	Bank
32		Front of Guest Lift	Dry	1	✓		04/06/2026	Bank
33		FHC - Front of ST-1	Dry	1	✓		04/06/2026	Bank
34		Parking Area Zone 4B	Dry	1	✓		04/06/2026	Bank
35		FHC - Front of ST-2	Dry	1	✓		04/06/2026	Bank
36		Parking Area Zone 2A	Dry	1	✓		04/06/2026	Recharge
37		Parking Area Zone 8A	Dry	1	✓		04/06/2026	Bank
38		Parking Area Zone C	Dry	1	✓		04/06/2026	Bank
39	6	FHC - Front of Service Lift	Dry	1	✓		04/06/2026	Bank
40		Front of Guest Lift	Dry	1	✓		04/06/2026	Bank
41		FHC - Front of ST-1	Dry	1	✓		04/06/2026	Bank
42		Parking Area Zone 4B	Dry	1	✓		04/06/2026	Bank
43		Inside ST-2	Dry	1	✓		04/06/2026	Bank
44		FHC - Front of ST-2	Dry	1	✓		04/06/2026	Bank
45		Parking Area Zone 2A	Dry	1	✓		04/06/2026	Bank
46		Parking Area Zone 8A	Dry	1	✓		04/06/2026	Bank
47		Parking Area Zone C	Dry	1	✓		04/06/2026	Overcharge
48	7	FHC - Front of Service Lift	Dry	1	✓		04/06/2026	Bank
49		Front of Guest Lift	Dry	1	✓		04/06/2026	Bank
50		FHC - Front of ST-1	Dry	1	✓		04/06/2026	Bank
51		Parking Area Zone 4B	Dry	1	✓		04/06/2026	Bank
52		Inside ST-2	Dry	1	✓		04/06/2026	Bank
53		FHC - Front of ST-2	Dry	1	✓		04/06/2026	Bank
54		Parking Area Zone 2A	Dry	1	✓		04/06/2026	Overcharge
55		Parking Area Zone 8A	Dry	1	✓		04/06/2026	Bank
56		Parking Area Zone C	Dry	1	✓		04/06/2026	Overcharge
57	7M	FHC - Front of Service Lift	Dry	1	✓		04/06/2026	Bank
58		Front of Guest Lift	Dry	1	✓		04/06/2026	Bank
59		Pool Pump Room	Dry	1	✓		04/06/2026	Bank
60		Front of Pump room	Dry	1	✓		04/06/2026	Bank
61		Parking Area Zone A	Dry	1	✓		04/06/2026	Bank
62		FHC - Front of ST-1	Dry	1	✓		04/06/2026	Bank
63		Parking Area Zone 2A	Dry	1	✓		04/06/2026	Bank
64		FHC - Inside ST-2	Dry	1	✓		04/06/2026	Bank
65		Inside ST-2	Dry	1	✓		04/06/2026	Bank
66	8	FHC - Front of Service Lift	Dry	1	✓		02/06/2026	Bank
67		Front of Guest Lift	Dry	1	✓		02/06/2026	Bank
68		E & E Room	CO2	1	✓		04/06/2026	Bank
69		FHC - beside ST-1	Dry	1	✓		02/06/2026	Bank
70		FHC - beside ST-2	Dry	1	✓		02/06/2026	Bank
71		Front of Apt#810	Dry	1	✓		02/06/2026	Bank
72		Beside Apt#817	Dry	1	✓		02/06/2026	Bank
73		FHC - Front of Service Lift	Dry	1	✓		02/06/2026	Bank
74	9	Front of Guest Lift	Dry	1	✓		02/06/2026	Bank
75		E & E Room	CO2	1	✓		04/06/2026	Bank
76		FHC - beside ST-1	Dry	1	✓		02/06/2026	Bank
77		FHC - beside ST-2	Dry	1	✓		02/06/2026	Bank
78		Front of Apt#910	Dry	1	✓		02/06/2026	Bank
79		Beside Apt#917	Dry	1	✓		02/06/2026	Bank

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
80	10	FHC - Front of Service Lift	Dry	1	✓		02/06/2026	Bank
81		Front of Guest Lift	Dry	1	✓		02/06/2026	Bank
82		E & E Room	CO2	1	✓		04/06/2026	Bank
83		Beside Apt#1001	Dry	1	✓		02/06/2026	Bank
84		Beside Apt#1017	Dry	1	✓		02/06/2026	Bank
85		FHC - beside ST-1	Dry	1	✓		02/06/2026	Bank
86		FHC - beside ST-2	Dry	1	✓		02/06/2026	Bank
87	11	FHC - Front of Service Lift	Dry	1	✓		04/06/2026	Bank
88		Front of Guest Lift	Dry	1	✓		04/06/2026	Overcharge
89		E & E Room	CO2	1	✓		04/06/2026	Bank
90		Beside Apt#1101	Dry	1	✓		04/06/2026	Bank
91		Beside Apt#1117	Dry	1	✓		04/06/2026	Bank
92		FHC - beside ST-1	Dry	1	✓		04/06/2026	Bank
93		FHC - beside ST-2	Dry	1	✓		04/06/2026	Bank
94	12	FHC - Front of Service Lift	Dry	1	✓		04/06/2026	Bank
95		Front of Guest Lift	Dry	1	✓		04/06/2026	Bank
96		E & E Room	CO2	1	✓		04/06/2026	Bank
97		Beside Apt#1201	Dry	1	✓		04/06/2026	Bank
98		Beside Apt#1217	Dry	1	✓		04/06/2026	Bank
99		FHC - beside ST-1	Dry	1	✓		04/06/2026	Bank
100		FHC - beside ST-2	Dry	1	✓		04/06/1962	Bank
101	13	FHC - Front of Service Lift	Dry	1	✓		04/06/2026	Bank
102		Front of Guest Lift	Dry	1	✓		04/06/2026	Bank
103		E & E Room	CO2	1	✓		04/06/2026	Bank
104		Beside Apt#1301	Dry	1	✓		04/06/2026	Bank
105		Beside Apt#1317	Dry	1	✓		04/06/2026	Bank
106		FHC - beside ST-1	Dry	1	✓		04/06/2026	Bank
107		FHC - beside ST-2	Dry	1	✓		04/06/2026	Bank
108	14	FHC - Front of Service Lift	Dry	1	✓		04/06/2026	Overcharge
109		Front of Guest Lift	Dry	1	✓		04/06/2026	Bank
110		E & E Room	CO2	1	✓		04/06/2026	Bank
111		Beside Apt#1401	Dry	1	✓		04/06/2026	Bank
112		Beside Apt#1417	Dry	1	✓		04/06/2026	Recharge
113		FHC - beside ST-1	Dry	1	✓		04/06/2026	Bank
114		FHC - beside ST-2	Dry	1	✓		04/06/2026	Bank
115	15	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
116		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
117		E & E Room	CO2	1	✓		03/06/2026	Bank
118		Beside Apt#1501	Dry	1	✓		01/06/2026	Mod
119		Beside Apt#1517	Dry	1	✓		01/06/2026	Mod
120		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
121		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
122	16	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
123		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
124		E & E Room	CO2	1	✓		03/06/2026	Bank
125		Beside Apt#1601	Dry	1	✓		01/06/2026	Mod
126		Beside Apt#1617	Dry	1	✓		01/06/2026	Mod
127		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
128		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
129	17	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
130		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
131		E & E Room	CO2	1	✓		03/06/2026	Bank
132		Beside Apt#1701	Dry	1	✓		01/06/2026	Mod
133		Beside Apt#1717	Dry	1	✓		01/06/2026	Mod
134		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
135		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
136	18	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
137		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
138		E & E Room	CO2	1	✓		03/06/2026	Bank
139		Beside Apt#1801	Dry	1	✓		01/06/2026	Mod
140		Beside Apt#1817	Dry	1	✓		01/06/2026	Mod
141		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
142		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
143	19	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
144		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
145		E & E Room	CO2	1	✓		03/06/2026	Bank
146		Beside Apt#1901	Dry	1	✓		01/06/2026	Mod
147		Beside Apt#1917	Dry	1	✓		01/06/2026	Mod
148		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
149		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
150	20	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
151		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
152		E & E Room	CO2	1	✓		03/06/2026	Bank
153		Beside Apt#2001	Dry	1	✓		01/06/2026	Mod
154		Beside Apt#2017	Dry	1	✓		01/06/2026	Mod
155		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
156		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
157	21	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
158		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
159		E & E Room	CO2	1	✓		03/06/2026	Bank
160		Beside Apt#2101	Dry	1	✓		01/06/2026	Mod
161		Beside Apt#2117	Dry	1	✓		01/06/2026	Mod
162		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
163		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
164	22	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
165		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
166		E & E Room	CO2	1	✓		03/06/2026	Bank
167		Beside Apt#2201	Dry	1	✓		01/06/2026	Mod
168		Beside Apt#2217	Dry	1	✓		01/06/2026	Mod
169		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
170		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
171	23	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
172		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
173		E & E Room	CO2	1	✓		03/06/2026	Bank
174		Beside Apt#2301	Dry	1	✓		01/06/2026	Mod
175		Beside Apt#2317	Dry	1	✓		01/06/2026	Mod
176		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
177		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
178	24	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
179		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
180		E & E Room	CO2	1	✓		03/06/2026	Bank
181		Beside Apt#2401	Dry	1	✓		01/06/2026	Mod
182		Beside Apt#2415	Dry	1	✓		01/06/2026	Mod
183		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
184		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
185	25	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
186		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
187		E & E Room	CO2	1	✓		03/06/2026	Bank
188		Beside Apt#2501	Dry	1	✓		01/06/2026	Mod
189		Beside Apt#2517	Dry	1	✓		01/06/2026	Mod
190		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
191		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
192	26	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
193		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
194		E & E Room	CO2	1	✓		03/06/2026	Bank
195		Beside Apt#2601	Dry	1	✓		01/06/2026	Mod
196		Beside Apt#2615	Dry	1	✓		01/06/2026	Mod
197		FHC - beside ST-1	Dry	1	✓		01/06/2026	Mod
198		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
199	27	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
200		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
201		E & E Room	CO2	1	✓		03/06/2026	Bank
202		FHC - Sky Garden	Dry	1	✓		01/06/2026	Mod
203		Beside Apt#2710	Dry	1	✓		01/06/2026	Mod
204		Beside Apt#2715	Dry	1	✓		01/06/2026	Mod
205		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
206	28	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
207		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
208		E & E Room	CO2	1	✓		03/06/2026	Bank
209		Beside Apt#2809	Dry	1	✓		01/06/2026	Mod
210		Beside Apt#2815	Dry	1	✓		01/06/2026	Mod
211		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
212	29	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
213		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
214		E & E Room	CO2	1	✓		03/06/2026	Bank
215		Beside Apt#2909	Dry	1	✓		01/06/2026	Mod
216		Beside Apt#2915	Dry	1	✓		01/06/2026	Mod
217		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
218	30	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
219		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
220		E & E Room	CO2	1	✓		03/06/2026	Bank
221		Beside Apt#3009	Dry	1	✓		01/06/2026	Mod
222		Beside Apt#3015	Dry	1	✓		01/06/2026	Mod
223		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod

No.	Fl.	Location	Type	Total	Status		Check Date	Remark
					Yes	No		
224	31	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
225		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
226		E & E Room	CO2	1	✓		03/06/2026	Bank
227		Beside Apt#3109	Dry	1	✓		01/06/2026	Mod
228		Beside Apt#3115	Dry	1	✓		01/06/2026	Mod
229		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
230	32	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
231		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
232		E & E Room	CO2	1	✓		03/06/2026	Bank
233		Beside Apt#3209	Dry	1	✓		01/06/2026	Mod
234		Beside Apt#3215	Dry	1	✓		01/06/2026	Mod
235		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
236	33	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
237		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
238		E & E Room	CO2	1	✓		03/06/2026	Bank
239		Beside Apt#3309	Dry	1	✓		01/06/2026	Mod
240		Beside Apt#3315	Dry	1	✓		01/06/2026	Mod
241		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
242	34	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
243		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
244		E & E Room	CO2	1	✓		03/06/2026	Bank
245		Beside Apt#3409	Dry	1	✓		01/06/2026	Mod
246		Beside Apt#3415	Dry	1	✓		01/06/2026	Mod
247		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
248	35	FHC - Front of Service Lift	Dry	1	✓		01/06/2026	Mod
249		Front of Guest Lift	Dry	1	✓		01/06/2026	Mod
250		E & E Room	CO2	1	✓		03/06/2026	Bank
251		Beside Apt#3509	Dry	1	✓		01/06/2026	Mod
252		Beside Apt#3515	Dry	1	✓		01/06/2026	Mod
253		FHC - beside ST-2	Dry	1	✓		01/06/2026	Mod
254	36	FHC-Roof-ST-1	Dry	1	✓		03/06/2026	Bank
255		Control lift Rooftop	CO2	1	✓		06/06/2026	Big
256		FHC-Roof-ST-2	Dry	1	✓		03/06/2026	Big

Note:

Fire extinguisher was Overcharge and Recharge = 18 Tanks. All tank is can use it normal.

No.	Total	Fire Extingusher / Type	Status		Check Date	Remark
			Yes	No		
1	230	Dry Chemical (10 lbs)	229	1		Out of order 1
2	44	CO2	44	0		
3	24	ADE 2000 (10 lbs)	24	0		
4	445	Dry Chemical (2.2 lbs/In Apartment)	443	2		2 Tanks Out of order
5	2	Dry Chemical (20 lbs)	2	0		
6	2	Dry Chemical (50 lbs)	2	0		
7	6	Dry Chemical (15 lbs)	6	0		Out of order 1
Total	753		750	3		

Reported by: Nattapon NGAMBOONYARIT
Security Office

Acknowledged by: _____
Security Manager

สำเนารับรองการฝึกซ้อมการดับเพลิงและซ้อมหนีไฟ

สำเนาบ้นทีก ฟีเอช และคลอรีน สระว่ายน้้า Check List Swimming Pool

ENGINEERING DEPARTMENT
SWIMMING POOL DAILY LOG SHEET

somerset

Date 1-31/01/2026

NIGHT SHIFT																	
DATE	POOL		FILTER PRESURE (PSI)			PUMP OPERATION			Back Wash	CHEMICAL (use)			CHEMICAL BALANCE			POOL CLEAN Y/N	CHECK BY
	CL	PH	NO.1	NO.2	NO.3	NO.1	NO.2	NO.3	Y/N	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)	CL (Kg.)	Powder(Kg.)		
1	1.5	7.2	16	16	16	✓	✓	✓	N	-	-	-	-	-	-	y	Artid
2	1.0	7.2	16	16	16	✓	✓	✓	N	-	0.5	-	-	-	-	y	Artid
3	1.5	7.2	10	10	10	✓	✓	✓	N	-	-	-	-	-	-	y	Artid
4	1.0	7.2	12	12	12	✓	✓	✓	N	-	0.5	-	-	-	-	y	Anuchit
5	1.5	7.2	12	12	12	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
6	1.5	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
7	1.5	7.2	10	10	10	✓	✓	✓	N	-	0.5	3kg.	-	-	-	y	Anuchit
8	1.5	7.2	12	12	12	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
9	1.0	7.2	14	14	14	✓	✓	✓	N	-	0.5	-	-	-	-	y	Artid
10	1.5	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	y	Artid
11	1.0	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
12	1.0	7.2	16	16	16	✓	✓	✓	N	-	0.5	-	-	-	-	y	Anuchit
13	1.5	7.2	10	10	10	✓	✓	✓	N	-	-	2kg	-	-	-	y	Anuchit
14	1.5	7.2	12	12	12	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
15	1.5	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
16	1.5	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	y	Artid
17	1.0	7.2	18	18	18	✓	✓	✓	N	-	0.5	-	-	-	-	y	Artid
18	1.0	7.2	12	12	12	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
19	1.0	7.2	14	14	14	✓	✓	✓	N	-	0.5	-	-	-	-	y	Anuchit
20	1.0	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
21	1.0	7.2	16	16	16	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
22	1.0	7.2	16	16	16	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
23	1.0	7.2	16	16	16	✓	✓	✓	N	-	0.5	-	-	-	-	y	Artid
24	1.5	7.2	10	10	10	✓	✓	✓	N	-	-	-	-	-	-	y	Artid
25	1.0	7.2	12	12	12	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
26	1.5	7.2	12	12	12	✓	✓	✓	N	-	0.5	-	-	-	-	y	Anuchit
27	1.5	7.2	16	16	16	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
28	1.0	7.2	16	16	16	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit
29	1.0	7.2	10	10	10	✓	✓	✓	N	-	-	-	-	-	-	y	Artid
30	1.5	7.2	10	10	10	✓	✓	✓	N	-	0.5	-	-	-	-	y	Artid
31	1.5	7.2	14	14	14	✓	✓	✓	N	-	-	-	-	-	-	y	Anuchit

REMARKS :

1.All system must work in good condition

2.Cleaning filter every week on Sunday.

3.Check Cl PH in pool everyday.

4.Clean pool and cutter every day on night shift.

5.Water level must over flow of pool.

6.No Smell ,No Colour in water pond

7.Any problem please report to Engineer Manager

NOTE :

6/1/26 9:00 AM - 12:00 PM
14/1/26 9:00 AM - 12:00 PM
20/1/26 9:00 AM - 12:00 PM
31/1/26 9:00 AM - 12:00 PM

ENGINEERING DEPARTMENT
SWIMMING POOL DAILY LOG SHEET

somerset

Date 1-28/02/2026

DATE	NIGHT SHIFT																POOL CLEAN Y/N	CHECK BY
	POOL		FILTER PRESURE (PSI)			PUMP OPERATION			Back Wash	CHEMICAL (use)			CHEMICAL BALANCE					
	CL	PH	NO.1	NO.2	NO.3	NO.1	NO.2	NO.3	Y/N	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)	CL (Kg.)	Powder(Kg.)			
1	1.0	7.2	14	14	14	✓	✓	✓	—	—	0.5	—	—	—	—	—	✓	Anuchit
2	1.5	7.2	14	14	14	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Anuchit
3	1.5	7.2	16	16	16	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Anuchit
4	1.0	7.2	12	12	12	✓	✓	✓	—	—	0.5	2.	—	—	—	—	✓	Anuchit
5	0.6	7.2	12	12	12	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
6	1.0	7.2	14	13	13	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
7	1.0	7.2	18	18	18	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
8	0.6	7.2	10	10	10	✓	✓	✓	—	—	0.5	2 kg	—	—	—	—	✓	Khiansak
9	1.0	7.2	12	12	12	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
10	1.0	7.2	16	16	16	✓	✓	✓	—	—	1 kg	—	—	—	—	—	✓	Anuchit
11	1.0	7.2	18	18	18	✓	✓	✓	—	—	—	2 kg	—	—	—	—	✓	Anuchit
12	1.0	7.2	12	12	12	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
13	1.0	7.2	12	12	12	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
14	1.0	7.2	18	18	18	✓	✓	✓	—	—	0	2 kg	—	—	—	—	✓	Khiansak
15	1.0	7.2	12	12	12	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
16	1.0	7.2	14	14	14	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
17	1.5	7.2	10	10	12	✓	✓	✓	—	—	0.5	1 kg	—	—	—	—	✓	Anuchit
18	1.5	7.2	16	16	16	✓	✓	✓	—	—	0.5	—	—	—	—	—	✓	Anuchit
19	1.0	7.2	18	18	18	✓	✓	✓	—	—	—	2 kg	—	—	—	—	✓	Khiansak
20	1.0	7.2	16	16	16	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
21	1.0	7.2	10	10	10	✓	✓	✓	—	—	—	2 kg	—	—	—	—	✓	Khiansak
22	1.0	7.2	12	12	12	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
23	1.0	7.2	16	16	16	✓	✓	✓	—	—	—	—	—	—	—	—	—	Anuchit
24																		
25	1.0	7.2	14	14	14	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
26	1.0	7.2	16	14	14	✓	✓	✓	—	—	—	—	—	—	—	—	✓	Khiansak
27	1.5	7.2	10	10	12	✓	✓	✓	—	—	0.5	—	—	—	—	—	✓	ATL
28	1.5	7.2	12	12	14	✓	✓	✓	—	—	—	—	—	—	—	—	✓	ATL

REMARKS :

- 1.All system must work in good condition
- 2.Cleaning filter every week on Sunday.
- 3.Check CL PH in pool everyday.
- 4.Clean pool and cutter every day on night shift.
- 5.Water level must over flow of pool.
- 6.No Smell ,No Colour in water pond

7.Any problem please report to Engineer Manager

NOTE :

ENGINEERING DEPARTMENT
SWIMMING POOL DAILY LOG SHEET

somerset

Date 1-31/03 /2026

DATE	NIGHT SHIFT																POOL CLEAN Y/N	CHECK BY
	POOL		FILTER PRESURE (PSI)			PUMP OPERATION			Back Wash	CHEMICAL (use)			CHEMICAL BALANCE					
	CL	PH	NO.1	NO.2	NO.3	NO.1	NO.2	NO.3	Y/N	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)	CL (Kg.)	Powder(Kg.)			
1	1.5	7.6	12	12	12	/	/	/	2	-	-	2kg	-	-	-	Y	Man	
2	1.0	7.6	14	14	14	/	/	/	2	-	-	-	-	-	-	X	Man	
3	0.5	7.6	14	14	14	/	/	/	2	-	0.5kg	-	-	-	-	Y	7455.8	
4	1.5	7.6	14	16	16	/	/	/	2	-	-	-	-	-	-	X	7455.8	
5	1.5	7.6	12	12	12	/	/	/	2	-	-	-	-	-	-	Y	7468.2	
6	1.0	7.2	16	16	16	/	/	/	2	-	-	-	-	-	-	X	7468.7	
7	1.5	7.2	16	16	16	/	/	/	2	-	0.5kg	-	-	-	-	Y	7468.7	
8	1.5	7.2	16	16	16	/	/	/	2	-	-	-	-	-	-	X	7468.2	
9	0.5	7.6	16	16	16	/	/	/	2	-	0.5	-	-	-	-	Y	7468.2	
10	1.5	7.6	16	16	16	/	/	/	2	-	-	-	-	-	-	Y	7468.2	
11	0.5	7.6	16	16	16	/	/	/	2	-	0.5	-	-	-	-	X	7468.2	
12	1.5	7.6	12	16	12	/	/	/	2	-	-	-	-	-	-	Y	7468.7	
13	1.5	7.2	16	14	14	/	/	/	2	-	-	-	-	-	-	X	7468.7	
14	1.5	7.6	16	14	14	/	/	/	2	-	-	-	-	-	-	X	7468.7	
15	0.5	7.6	16	14	14	/	/	/	2	-	0.5	-	-	-	-	X	7468.7	
16	1.5	7.6	12	12	12	/	/	/	2	-	-	2kg	-	-	-	X	7468.7	
17	0.5	7.6	12	12	12	/	/	/	2	-	0.5	-	-	-	-	Y	7468.2	
18	1.5	7.6	12	12	12	/	/	/	2	-	-	-	-	-	-	X	7468.2	
19	1.5	7.2	14	14	14	/	/	/	2	-	-	-	-	-	-	X	7468.8	
20	0.5	7.2	14	14	14	/	/	/	2	-	0.5	-	-	-	-	Y	7468.8	
21	1.5	7.2	14	14	14	/	/	/	2	-	-	-	-	-	-	X	7468.8	
22	0.5	7.6	14	14	14	/	/	/	2	-	0.5	-	-	-	-	Y	7484.4	
23	1.5	7.6	16	16	16	/	/	/	2	-	-	-	-	-	-	X	7484.6	
24	1.5	7.6	12	12	12	/	/	/	2	-	-	-	-	-	-	Y	7487.2	
25	1.0	7.6	12	12	12	/	/	/	2	-	-	-	-	-	-	Y	7490.6	
26	0.5	7.0	14	14	14	/	/	/	2	-	0.5	-	-	-	-	X	7491.7	
27	1.5	7.0	16	16	16	/	/	/	2	-	-	-	-	-	-	X	7491.7	
28	1.0	7.0	16	16	18	/	/	/	2	-	-	-	-	-	-	X	7492.8	
29	1.0	7.0	10	10	10	/	/	/	2	-	-	2kg	-	-	-	Y	7496.3	
30	1.0	7.6	12	12	12	/	/	/	2	-	-	-	-	-	-	Y	7499.9	
31	0.5	7.6	14	14	14	/	/	/	2	-	0.5	-	-	-	-	Y	7501.3	

REMARKS :

1.All system must work in good condition

2.Cleaning filter every week on Sunday.

3.Check Cl PH in pool everyday.

4.Clean pool and cutter every day on night shift.

5.Water level must over flow of pool.

6.No Smell ,No Colour in water pond

7.Any problem please report to Engineer Manager

NOTE :

ENGINEERING DEPARTMENT
SWIMMING POOL DAILY LOG SHEET

somerset

Date 1-30 April 2026

DATE	NIGHT SHIFT																
	POOL		FILTER PRESURE (PSI)			PUMP OPERATION			Back Wash	CHEMICAL (use)			CHEMICAL BALANCE			POOL CLEAN Y/N	CHECK BY
	CL	PH	NO.1	NO.2	NO.3	NO.1	NO.2	NO.3	Y/N	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)	CL (Kg.)	Powder(Kg.)		
1	1.5	7.2	14	18	18	✓	✓	✓	-	-	-	-	-	-	-	Y	ATTH
2	1.0	7.2	10	10	10	✓	✓	✓	-	-	0.5	-	-	-	-	Y	ATTH
3	1.5	7.2	12	12	12	✓	✓	✓	-	-	-	-	-	-	-	Y	ATTH
4	1.0	7.2	14	14	14	✓	✓	✓	-	-	-	-	-	-	-	Y	7509.6
5	0.5	7.2	16	16	16	✓	✓	✓	-	-	0.5	-	-	-	-	Y	7509.6
6	1.5	7.2	10	10	10	✓	✓	✓	-	-	-	-	-	-	-	Y	7507.6
7	1.0	7.2	10	10	10	✓	✓	✓	-	-	0.5	-	-	-	-	Y	7514.5
8	1.5	7.2	14	14	14	✓	✓	✓	-	-	-	-	-	-	-	Y	7514.5
9	1.0	7.2	10	10	10	✓	✓	✓	-	-	0.5	-	-	-	-	Y	7514.5
10	1.5	7.2	12	12	12	✓	✓	✓	-	-	-	-	-	-	-	Y	7519.6
11	1.0	7.2	14	14	14	✓	✓	✓	-	-	0.5	-	-	-	-	Y	7520.5
12	1.5	7.2	14	14	14	✓	✓	✓	-	-	-	-	-	-	-	Y	7521.7
13	0.5	7.6	14	14	14	✓	✓	✓	-	-	0.5	-	-	-	-	Y	7523.7
14	1.5	7.2	10	10	10	✓	✓	✓	-	-	-	-	-	-	-	Y	7525.1
15	1.0	7.2	12	12	12	✓	✓	✓	-	-	0.5	-	-	-	-	Y	7528.1
16	1.5	7.2	14	14	14	✓	✓	✓	-	-	-	-	-	-	-	Y	7529.4
17	1.0	7.2	14	14	14	✓	✓	✓	-	-	0.5	-	-	-	-	Y	7530.9
18	1.5	7.2	16	16	16	✓	✓	✓	-	-	-	-	-	-	-	Y	7534.3
19	1.5	7.2	12	12	12	✓	✓	✓	-	-	-	-	-	-	-	Y	7531.3
20	1.5	7.2	12	12	12	✓	✓	✓	-	-	-	-	-	-	-	Y	7531.3
21	1.5	7.2	14	14	16	✓	✓	✓	-	-	0.5	-	-	-	-	Y	Anuchit
22	1.5	7.2	16	16	16	✓	✓	✓	-	-	-	-	-	-	-	Y	Run 7531.3
23	0.5	7.2	12	12	12	✓	✓	✓	-	-	0.5	2kg	-	-	-	Y	Run 7531.3
24	1.0	7.2	12	12	12	✓	✓	✓	-	-	-	-	-	-	-	Y	Run 7531.3
25	1.5	7.2	12	12	12	✓	✓	✓	-	-	-	-	-	-	-	Y	Run 7531.3
26	1.5	7.2	14	14	14	✓	✓	✓	-	-	0.5	-	-	-	-	Y	Run 7531.3
27	1.5	7.2	10	10	10	✓	✓	✓	-	-	-	-	-	-	-	Y	2531.3
28	1.0	7.2	12	12	12	✓	✓	✓	-	-	0.5	-	-	-	-	Y	2531.3
29	1.0	7.2	14	14	14	✓	✓	✓	-	-	-	-	-	-	-	Y	7531.3
30	1.5	7.2	16	16	16	✓	✓	✓	-	-	0.5	-	-	-	-	Y	7531.3
31																	

REMARKS :

- 1.All system must work in good condition
- 2.Cleaning filter every week on Sunday.
- 3.Check CL PH in pool everyday.
- 4.Clean pool and cutter every day on night shift.
- 5.Water level must over flow of pool.
- 6.No Smell, No Colour in water pond

7.Any problem please report to Engineer Manager

NOTE :

ENGINEERING DEPARTMENT
SWIMMING POOL DAILY LOG SHEET

somerset

Date 1-31 May 2026

DATE	NIGHT SHIFT																
	POOL		FILTER PRESURE (PSI)			PUMP OPERATION			Back Wash	CHEMICAL (use)			CHEMICAL BALANCE			POOL CLEAN	CHECK BY
	CL	PH	NO.1	NO.2	NO.3	NO.1	NO.2	NO.3	Y/N	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Y/N	
31/04/2026																	
1-May	1.0	7.2	10	10	10	✓	✓	✓	-	-	0.5	-	-	-	-	✓	2533.8
2-May	1.5	7.2	12	12	12	✓	✓	✓	-	-	-	-	-	-	-	✓	2545.6
3-May	1.5	7.2	12	12	14	✓	✓	✓	-	-	-	-	-	-	-	✓	7551.3
4-May	1.5	7.2	14	14	14	✓	✓	✓	-	-	0.5	-	-	-	-	✓	7551.3
5-May	1.5	7.2	14	14	14	✓	✓	✓	-	-	-	-	-	-	-	✓	7551.3
6-May	1.5	7.2	14	14	14	✓	✓	✓	-	-	-	-	-	-	-	✓	7551.3
7-May	1.5	7.2	10		12	✓		✓	-	-	0.5	3kg	-	-	-	✓	7551.3
8-May	1.5	7.2	12		12	✓		✓	-	-	-	-	-	-	-	✓	2551.3
9-May	1.5	7.2	14		14	✓		✓	-	-	0.5	-	-	-	-	✓	7551.3
10-May	1.5	7.2	10		10	✓		✓	-	-	-	-	-	-	-	✓	7551.3
11-May	1.0	7.2	12		12	✓		✓	-	-	0.5	-	-	-	-	✓	2551.3
12-May	1.5	7.2	14		14	✓		✓	-	-	-	-	-	-	-	✓	2551.3
13-May	1.0	7.2	10		10	✓		✓	-	-	0.5	-	-	-	-	✓	7551.3
14-May	1.5	7.2	12		12	✓		✓	-	-	-	-	-	-	-	✓	7551.3
15-May	1.0	7.2	14		14	✓		✓	-	-	0.5	-	-	-	-	✓	2551.3
16-May	1.5	7.2	14		14	✓		✓	-	-	-	-	-	-	-	✓	7551.3
17-May	3.0	7.2	10		12	✓		✓	-	-	-	3kg	-	-	-	✓	7551.3
18-May	1.5	7.2	12		14	✓		✓	-	-	-	-	-	-	-	✓	7551.3
19-May	1.5	7.2	14		14	✓		✓	-	-	-	-	-	-	-	✓	7551.3
20-May	1.5	7.2	14		14	✓		✓	-	-	0.5	-	-	-	-	✓	7551.3
21-May	1.5	7.2	14		16	✓		✓	-	-	-	-	-	-	-	✓	7551.3
22-May	1.0	7.2	16			✓			-	-	0.5	-	-	-	-	✓	2551.3
23-May	1.5	7.2	10			✓			-	-	-	-	-	-	-	✓	2551.3
24-May	1.5	7.2	12			✓			-	-	-	-	-	-	-	✓	7551.3
25-May	3.0	7.2	14			✓			-	-	-	-	-	-	-	✓	7551.3
26-May	1.5	7.2	16			✓			-	-	0.5	-	-	-	-	✓	7551.3
27-May	1.5	7.2	10			✓			-	-	-	1kg	-	-	-	✓	7551.3
28-May	1.5	7.2	12			✓			-	-	-	-	-	-	-	✓	7551.3
29-May	1.5	7.2	14			✓			-	-	-	-	-	-	-	✓	7551.3
30-May	1.5	7.2	10			✓			-	-	-	1kg	-	-	-	✓	7551.3
31-May	1.5	7.2	10			✓			-	-	-	-	-	-	-	✓	7551.3

1.All system must work in good condition

2.Cleaning filter every week on Sunday.

3.Check CL PH in pool everyday.

4.Clean pool and cutter every day on night shift.

5.Water level must over flow of pool.

6.No Smell ,No Colour in water pond

7.Any problem please report to Engineer Manager

NOTE :

ENGINEERING DEPARTMENT
SWIMMING POOL DAILY LOG SHEET

somerset

Date 1-30 June 2026

DATE	NIGHT SHIFT																POOL CLEAN Y/N	CHECK BY
	POOL		FILTER PRESURE (PSI)			PUMP OPERATION			Back Wash	CHEMICAL (use)			CHEMICAL BALANCE					
	CL	PH	NO.1	NO.2	NO.3	NO.1	NO.2	NO.3	Y/N	Salt (Kg.)	CL (Kg.)	Powder(Kg.)	Salt (Kg.)	CL (Kg.)	Powder(Kg.)			
31-May	1.5	7.2	10			✓			-	-	-	-	-	-	-	Y	7551.3	
1-Jun	1.5	7.2	12			✓			-	-	0.5	-	-	-	-	Y	7561.5	
2-Jun	1.5	7.2	14			✓			-	-	-	-	-	-	-	Y	7561.5	
3-Jun	1.5	7.2	16			✓			-	-	0.5	-	-	-	-	Y	7561.5	
4-Jun	1.5	7.2	10			✓			-	-	-	1.0	-	-	✓	Y	7561.5	
5-Jun	1.5	7.6	12			✓			-	-	-	-	-	-	-	Y	7561.5	
6-Jun	0.5	7.0	14			✓			-	-	0.5	-	-	-	-	Y	7561.5	
7-Jun	1.5	7.2	16			✓			-	-	-	-	-	-	-	Y	7561.5	
8-Jun	1.5	7.2	10			✓			-	-	0.5	1.0	-	-	-	Y	7561.5	
9-Jun	1.5	7.2	10			✓			-	-	-	-	-	-	-	Y	7565.8	
10-Jun	1.5	7.2	12			✓			-	-	-	-	-	-	-	Y	7565.8	
11-Jun	1.5	7.2	10			✓			-	-	0.5	1.0	-	-	-	Y	7565.8	
12-Jun	1.0	7.2	12			✓			-	-	-	-	-	-	-	Y	7565.8	
13-Jun	1.0	7.2	14			✓			-	-	-	-	-	-	-	Y	7565.8	
14-Jun	1.0	7.2	10			✓			-	-	-	1.0	-	-	-	Y	7565.8	
15-Jun	1.0	7.2	10			✓			-	-	-	-	-	-	-	Y	7565.8	
16-Jun	0.5	7.2	12			✓			-	-	0.5	-	-	-	-	Y	7565.8	
17-Jun	2.0	7.2	10			✓			-	-	-	1.0	-	-	-	Y	7565.8	
18-Jun	1.0	7.2	12			✓			-	-	-	-	-	-	-	Y	7565.8	
19-Jun	1.0	7.2	12	12		✓	✓		-	-	-	-	-	-	-	Y	7565.8	
20-Jun	1.0	7.2	12	12		✓	✓		-	-	-	-	-	-	-	Y	7565.8	
21-Jun	1.0	7.2	10	10		✓	✓		-	-	0.5	2.0	-	-	-	Y	7565.8	
22-Jun	1.5	7.6	12	12		✓	✓		-	-	-	-	-	-	-	Y	7565.8	
23-Jun	1.5	7.2	14	14		✓	✓		-	-	-	-	-	-	-	Y	7565.8	
24-Jun	1.5	7.2	14	14		✓	✓		-	-	0.5	-	-	-	-	Y	7565.8	
25-Jun																Y	7565.8	
26-Jun	1.0	7.2	14	14		✓	✓		-	-	-	-	-	-	-	Y	7565.8	
27-Jun	0.5	7.0	10	10		✓	✓		-	-	0.5	2.0	-	-	-	Y	7565.8	
28-Jun	1.5	7.2	12	12		✓	✓		-	-	-	-	-	-	-	Y	7565.8	
29-Jun	1.0	7.2	12	12		✓	✓		-	-	-	-	-	-	-	Y	7565.8	
30-Jun	1.0	7.2	14	14		✓	✓		-	-	-	-	-	-	-	Y	7565.8	

1.All system must work in good condition

2.Cleaning filter every week on Sunday.

3.Check CL PH in pool everyday.

4.Clean pool and cutter every day on night shift.

5.Water level must over flow of pool.

6.No Smell ,No Colour in water pond

7.Any problem please report to Engineer Manager

NOTE :

สำเนาเอกสารการรับ-จ่ายค่าบริการขนย้ายมูลฝอย

MANUSCRIPT

No. 136835

Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Ms Thanomchit Channamom	DATE	03-Feb-2026
ADDRESS	, Thailand		
TAX ID	5340400017235		
Description			Amount
TT/Direct Credit 1 Receipt #136835, Drawer: 15:23 hrs. (KBank) - Paid for garbage sell on 03 Feb 2026			556.50
	TOTAL	520.09	
	VALUE ADDED TAX	36.41	
	GRAND TOTAL	556.50	
RECEIVED BAHT	Five Hundred Fifty Six and Fifty Satang		
BY	☐ CASH	☐ CHEQUE NO. _____	BANK _____ DATE _____
	☐ CREDIT CARD	_____ NO. _____	EXP. DATE _____
	☐ BANK TRANSFER	_____ BANK _____	DATE _____
nan s. CASHIER/RECEIVER MANAGED BY ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED			
REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK. THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.			

INVOICE

Company :
ID : 5340400017235
Address : Thailand
Attention :
Room :
Room Type :
Arrival : 30 Jan 2026
Departure : 31 Jan 2026
Guest : Ms Thanomchit Channamom

Reservation : 20093484
ABN : 0115559022518
Invoice No. : 226190
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 03 Feb 2026 07:22
Cashier : suwakul.p
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
03 Feb 2026		TT/Direct Credit 1 Receipt #136835, Drawer: 15:23 hrs. (KBank)	-556.50
		- Paid for garbage sell on 03 Feb 2026	
		Miscellaneous.	520.09
		#15523 Garbage sell	
		- TH VAT - Others 7%.	36.41
		Sub-Total Before VAT	520.09
		VAT	36.41
		Total Amount Inc VAT	556.50
		Payment	-556.50
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor Central Plaza Grand
Holder's Name : AMH Ratchada Co., Ltd.
Rama 9, Huai Khwang, Bangkok 10310

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO
BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON
COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL
AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: <https://www.discoverasr.com>

ใบรับซื้อ-ของเก่า


Date: 3-Feb-2026


รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	3.00	บาท/ก.ก.	23 +	69-
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม		บาท/ก.ก.		
เศษกระดาษ	2	บาท/ก.ก.	10 + 3 = 13	26-
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	0.50	บาท/ก.ก.	17 + 15 + 15 + 15 + 19 + 10 + 15 + 27 + 14 = 147	73.50-
ป๊อป				
ป๊อป (ดี)		บาท/ใบ		
ป๊อป (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	3.00	บาท/ก.ก.	12 + 4 = 16	48-
ขวดน้ำ ชุ่น-ใส	5.00	บาท/ก.ก.	16 + 12 + 7 = 35	175-
แกลอน		บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก	1.00	บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	40.00	บาท/ก.ก.	4	160-
กระป๋องวิปิงครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				556.5


นางณอมจิต จันทนามอม


ที่อยู่: 179 หมู่ที่ 10 ต.โสภณกเต็น อ.พล จ.ขอนแก่น

เลขบัตรประจำตัวประชาชน: 5 3404 00017 23 5


Supplier


Income Auditor


Witness


General Cashier

โอนเงินสำเร็จ

3 ก.พ. 69 15:23 น.

K+



นาง ถนอมจิต จ
ธ.กสิกรไทย
xxx-x-x4930-x



บริษัท เอเอ็มเอช รัชดา จำกัด
ธ.ไทยพาณิชย์
xxx-x-x4769-x

เลขที่รายการ:

016034152357AOR06881

จำนวน:


556.50 บาท

ค่าธรรมเนียม:

0.00 บาท



สแกนตรวจสอบสลิป



✓
10/10

INVOICE

Company :
ID : 5340400017235
Address : Thailand
Attention :
Room :
Room Type :
Arrival : 30 Jan 2026
Departure : 31 Jan 2026
Guest : Ms Thanomchit Channamom

Reservation : 20093484
ABN : 0115559022518
Invoice No. : 227331
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 11 Feb 2026 09:01
Cashier : puchong.t
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
11 Feb 2026		Miscellaneous.	934.58
		#15626 Garbage sell	
		- TH VAT - Others 7%.	65.42
		TT/Direct Credit 1 Receipt #137587	-1,000.00
		- Paid for #15626 Garbage sell	
Sub-Total Before VAT			934.58
VAT			65.42
Total Amount Inc VAT			1,000.00
Payment			-1,000.00
Balance			0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Account : 430-044-7697
Bank Code : 014
Holder's Name : AMH Ratchada Co., Ltd.

Branch Code : 5300
SWIFT Code : SICOTHBK
Bank Address : No. 9/9, the 5th Floor CentralPlaza Grand Rama 9, Huai Khwang, Bangkok 10310

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: <https://www.discoverasr.com>

Somerset Rama 9 Bangkok | Tax Invoice # 227331 | Page 1/1

6:16



< 99+ Somerset R...ชื่อของเก่า (4)



10:21 AM



ใน

พิจารณา
ถึงน้ำเงิน 13 ใบ 500 บาท
ถึงน้ำเงิน 10 ใบ 500 บาท
รวมเป็นเงิน 1,000 บาท

11:24 AM



POURÉE

@x.jaoeye

11:25 AM



ใน



11:25 AM



POURÉE

ขอบคุณ

11:25 AM



ใน

ขอบคุณ

11:35 AM



6:16 PM



All







โอนเงินสำเร็จ

11 ก.พ. 69 10:21 น.

K+



นาง ถนอมจิต จ
ธ.กสิกรไทย
xxx-x-x4930-x



บริษัท เอเอ็มเอช รัชดา จำกัด
ธ.ไทยพาณิชย์
xxx-x-x4769-x

เลขที่รายการ:

016042102125BOR09688

จำนวน:

1,000.00 บาท

ค่าธรรมเนียม:

0.00 บาท



สแกนตรวจสอบสลิป

 **บัตรประจำตัวประชาชน Thai National ID Card**
เลขประจำตัวประชาชน 5 3404 00017 23 5
Identification Number

นาง ธนอมจิต จันนามอม
Name Mrs. Thanomchit
Last name Channamom

เกิด 13 ก.ค. 2517
Date of Birth 13 Jul. 1974

สูง 179 ซม. น้ำหนัก 50 กก. สีตา น้ำตาล
สีผม ดำ สีผิว ดำ

24 เม.ย. 2567
Date of Issue

 12 ก.ค. 2575
Date of Expiry

1037-08-04261515

040257 04072021

No. 139839

AMH RATCHADA CO., LTD.-BRANCH 00002
22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Ms Thanomchit Channamom	DATE	04-Mar-2026
ADDRESS	, Thailand		
TAX ID	5340400017235		
Description		Amount	
TT/Direct Credit 1 Receipt #139839 - Paid for #15950 Garbage sell on 04 Mar 26		738.00	
TOTAL		689.72	
VALUE ADDED TAX		48.28	
GRAND TOTAL		738.00	
RECEIVED BAHT	Seven Hundred Thirty Eight and Zero Satang		
BY	☐ CASH	☐ CHEQUE NO. _____	BANK _____
		☐ CREDIT CARD _____	NO. _____
		☐ BANK TRANSFER _____	BANK _____
			DATE _____
			EXP.DATE _____
			DATE _____
CASHIER/RECEIVER MANAGED BY ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED			
REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK. THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.			

ใบรับซื้อ-ของเก่า

Date: 4-Mar-2026

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	3.00	บาท/ก.ก.	15+25 = 40	120-
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม		บาท/ก.ก.		
เศษกระดาษ	2	บาท/ก.ก.	14	48-
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	0.50	บาท/ก.ก.	26120 + 15 + 18 + 13 + 19 + 22 + 20 + 19 + 19 + 19 = 215	108-
ป๊อป				
ป๊อป (ดี)		บาท/ใบ		
ป๊อป (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	3.00	บาท/ก.ก.	15	45-
ขวดน้ำ ขุน-ใส	5.00	บาท/ก.ก.	14+10+15+12 = 51	255-
แกลลอน		บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก	1.00	บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	27.00	บาท/ก.ก.	6	162-
กระป๋องวิปิงครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
ถังแก๊ส	50.00	บาท/ใบ		
ถังน้ำมันเหล็ก	30.00	บาท/ใบ		
TOTAL				738-

นางณอมจิต จันทนามอม

ที่อยู่: 179 หมู่ที่ 10 ต.โสภณนฤดิน อ.พล จ.ขอนแก่น

เลขบัตรประจำตัวประชาชน: 5 3404 00017 23 5

.....
Supplier

.....
Witness

.....
Income Auditor

.....
General Cashier

INVOICE

Company :
ID : 5340400017235
Address : Thailand
Attention :
Room :
Room Type :
Arrival : 30 Jan 2026
Departure : 31 Jan 2026
Guest : Ms Thanomchit Channamom

Reservation : 20093484
ABN : 0115559022518
Invoice No. : 230594
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 04 Mar 2026 10:18
Cashier : kanthamane.kaorat
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
04 Mar 2026		Miscellaneous.	689.72
		#15950 Garbage sell on 04 Mar 26	
		- TH VAT - Others 7%.	48.28
		TT/Direct Credit 1 Receipt #139839	-738.00
		- Paid for #15950 Garbage sell on 04 Mar 26	
		Sub-Total Before VAT	689.72
		VAT	48.28
		Total Amount Inc VAT	738.00
		Payment	-738.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor Central Plaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: <https://www.discoverasr.com>

โอนเงินสำเร็จ

4 มี.ค. 69 16:05 น.

K+



นาง ถนอมจิต จ
ธ.กสิกรไทย
xxx-x-x4930-x



บริษัท เอเอ็มเอช รัชดา จำกัด
ธ.ไทยพาณิชย์
xxx-x-x4769-x

เลขที่รายการ:

016063160528AOR04755

จำนวน:

738.00 บาท

ค่าธรรมเนียม:


0.00 บาท



สแกนตรวจสอบสลิป



ราชอาณาจักรไทย Thai National ID Card
เลขประจำตัวประชาชน 5 3404 00017 23 5
Identification Number



2/4/

๒๓/๑๒/๖๖

๒๔๔๑๐๐๐๑

AMH RATCHADA CO., LTD.-BRANCH 00002
22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Mr Folio Cash	DATE	20-Mar-2026
ADDRESS	, Thailand		
TAX ID	0000000000000		

Description	Amount
Cash Receipt #141523 - Paid for #16191 Garbage Selling on 20 March 2026	854.00
TOTAL	798.13
VALUE ADDED TAX	55.87
GRAND TOTAL	854.00

RECEIVED BAHT Eight Hundred Fifty Four and Zero Satang

BY ☒ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP. DATE _____
☐ BANK TRANSFER _____ BANK _____ DATE _____

FM
CASHIER/RECEIVER
MANAGED BY
ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 0000000000000
Address : Thailand
Attention :
Room :
Room Type :
Arrival : 01 Jan 2026
Departure : 31 Dec 2026
Guest : Mr Folio Cash

Reservation : 19698102
ABN : 0115559022518
Invoice No. : 232893
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 20 Mar 2026 03:04
Cashier : siriporn.d
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
20 Mar 2026		Miscellaneous.	798.13
		#16191 Garbage Selling on 20 March 2026	
		- TH VAT - Others 7%.	55.87
		Cash Receipt #141523	-854.00
		- Paid for #16191 Garbage Selling on 20 March 2026	
		Sub-Total Before VAT	798.13
		VAT	55.87
		Total Amount Inc VAT	854.00
		Payment	-854.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Account : 430-044-7697
Bank Code : 014
Holder's Name : AMH Ratchada Co., Ltd.

Branch Code : 5300
SWIFT Code : SICOTHBK
Bank Address : No. 9/9, the 5th Floor CentralPlaza Grand Rama 9, Huai Khwang, Bangkok 10310

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: <https://www.discoverasr.com>

ใบรับซื้อ-ของเก่า

Date: 20-Mar-2026

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	3.00	บาท/ก.ก.	14+14+29	171
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม		บาท/ก.ก.		
เศษกระดาษ		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	0.50	บาท/ก.ก.	20+17+18+16+25+15+18+20+16	82.5
ปั๊บน				
ปั๊บน (ดี)		บาท/ใบ		
ปั๊บน (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	3.00	บาท/ก.ก.	9	27
ขวดน้ำ ชุ่น-ใส	5.00	บาท/ก.ก.	20+17+18 17+13+13	185
แกลอน		บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก	1.00	บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	40.00	บาท/ก.ก.	94	360
กระป๋องวิปปิ้งครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
ถังแก๊ส	50.00	บาท/ใบ		
ถังน้ำมันเหล็ก	30.00	บาท/ใบ		
กระดาษสี	2	บาท/ใบ	14	28
			TOTAL	854

นางณอมจิต จันทนามอม

ที่อยู่: 179 หมู่ที่ 10 ต. โสภนภเต็น อ. พล จ. ขอนแก่น

เลขบัตรประจำตัวประชาชน: 5 3404 00017 23 5

.....
Supplier

Thamchakorn
.....
Income Auditor

Champen S.
.....
Witness

Sriporn D.
.....
General Cashier

22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Ms Thanomchit Channamom	DATE	15-Apr-2026
ADDRESS	, Thailand		
TAX ID	5340400017235		

Description	Amount
TT/Direct Credit 1 Receipt #144125 - PAID FOR #16599 GARBAGE SELL ON 15 APR 26	648.50
TOTAL	606.07
VALUE ADDED TAX	42.43
GRAND TOTAL	648.50

RECEIVED BAHT Six Hundred Forty Eight and Fifty Satang

BY ☐ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
 ☐ CREDIT CARD _____ NO. _____ EXP. DATE _____
 ☐ BANK TRANSFER _____ BANK _____ DATE _____

CASHIER/RECEIVER

MANAGED BY

ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 5340400017235
Address : Thailand
Attention :
Room :
Room Type :
Arrival : 30 Jan 2026
Departure : 31 Jan 2026
Guest : Ms Thanomchit Channamom

Reservation : 20093484
ABN : 0115559022518
Invoice No. : 236444
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 15 Apr 2026 05:55
Cashier : jidapha.t
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
15 Apr 2026		Miscellaneous.	606.07
		#16599 GARBAGE SELL ON 15 APR 26	
		- TH VAT - Others 7%.	42.42
		TT/Direct Credit 1 Receipt #144125	-648.50
		- PAID FOR #16599 GARBAGE SELL ON 15 APR 26	
		Excess Collection.	0.01
		Sub-Total Before VAT	606.08
		VAT	42.42
		Total Amount Inc VAT	648.50
		Payment	-648.50
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor CentralPlaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO
BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON
COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL
AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: <https://www.discoverasr.com>

SomerSET Rama 9 Bangkok | Tax Invoice # 236444 | Page 1/1

ใบรับซื้อ-ของเก่า

Date: 15-Apr-2026

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	3.00	บาท/ก.ก.		
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม		บาท/ก.ก.		
เศษกระดาษ		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	0.50	บาท/ก.ก.	21+25+15+23+24+26+19+18+20+22+18+20+10	130.5
ป๊อป			2261	
ป๊อป (ดี)		บาท/ใบ		
ป๊อป (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	4 2.00	บาท/ก.ก.	17	68
ขวดน้ำ ขุ่น-ใส	5.00	บาท/ก.ก.	13+10+13+12+12 = 60	300
แกลอน		บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก	1.00	บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	30 48.00	บาท/ก.ก.	5	150
กระป๋องรีปป์ครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
ถังแก๊ส	50.00	บาท/ใบ		
ถังน้ำมันเหล็ก	30.00	บาท/ใบ		
TOTAL				648.5

นางณอมจิต จันทนามอม

ที่อยู่: 179 หมู่ที่ 10 ต. โสภนภเต็น อ. พล จ. ขอนแก่น

เลขบัตรประจำตัวประชาชน: 5 3404 00017 23 5

ธน/พจวันท2024

Supplier

Chutipat R.

Income Auditor

พณต K H/K

Witness

Adaporn T.

General Cashier

โอนเงินสำเร็จ

15 เม.ย. 69 17:33 น.

K+



นาง ธนอมจิต จ
ธ.กสิกรไทย
xxx-x-x4930-x



บริษัท เอเอ็มเอช รัชดา จำกัด
ธ.ไทยพาณิชย์
xxx-x-x4769-x

เลขที่รายการ:

016105173348BOR03008

จำนวน:

648.50 บาท

ค่าธรรมเนียม:

0.00 บาท



สแกนตรวจสอบสลิป

AMH RATCHADA CO., LTD.-BRANCH 00002
22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Mrs Tanomjit Jannamom	DATE	17-Apr-2026
ADDRESS	, Thailand		
TAX ID	5340400017235		

Description	Amount
TT/Direct Credit 1 Receipt #144305, Drawer: 13:23 hrs. KBank - #16623 Paid for garbage sell on 16 Apr 2026	488.00
TOTAL	456.07
VALUE ADDED TAX	31.93
GRAND TOTAL	488.00

RECEIVED BAHT Four Hundred Eighty Eight and Zero Satang

BY ☐ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP. DATE _____
☐ BANK TRANSFER _____ BANK _____ DATE _____

han s.

CASHIER/RECEIVER

MANAGED BY

ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 5340400017235
Address : Thailand
Attention :
Room :
Room Type :
Arrival : 17 Apr 2026
Departure : 18 Apr 2026
Guest : Mrs Tanomjit Jannamom

Reservation : 21027645
ABN : 0115559022518
Invoice No. : 236694
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 17 Apr 2026 10:58
Cashier : suwakul.p
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
17 Apr 2026		Miscellaneous.	456.07
		#16623 Garbage sell	
		- TH VAT - Others 7%.	31.92
		Excess Collection.	0.01
		TT/Direct Credit 1 Receipt #144305, Drawer: 13:23 hrs. KBank	-488.00
		- #16623 Paid for garbage sell on 16 Apr 2026	
		Sub-Total Before VAT	456.08
		VAT	31.92
		Total Amount Inc VAT	488.00
		Payment	-488.00
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Branch Code : 5300
Account : 430-044-7697
SWIFT Code : SICOTHBK
Bank Code : 014
Bank Address : No. 9/9, the 5th Floor CentralPlaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name : AMH Ratchada Co., Ltd.

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: <https://www.discoverasr.com>

Somerset Rama 9 Bangkok | Tax Invoice # 236694 | Page 1/1

โอนเงินสำเร็จ

16 เม.ย. 69 13:23 น.

K+



นาง ถนอมจิต จ
ธ.กสิกรไทย
xxx-x-x4930-x



บริษัท เอเอ็มเอช รัชดา จำกัด
ธ.ไทยพาณิชย์
xxx-x-x4769-x

เลขที่รายการ:

016106132317BOR00787

จำนวน:

488.00 บาท

ค่าธรรมเนียม:

0.00 บาท



สแกนตรวจสอบสลิป

ใบรับซื้อ-ของเก่า

Date: 16-Apr-2026

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	3.00	บาท/ก.ก.	18 + 15 + 18 + 12 + 27 + 22 + 5 + 24 = 141	423 -
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม		บาท/ก.ก.		
เศษกระดาษ		บาท/ก.ก.		
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	0.50	บาท/ก.ก.		
ป๊อป				
ป๊อป (ดี)		บาท/ใบ		
ป๊อป (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	3.00	บาท/ก.ก.		
ขวดน้ำ ขุ่น-ใส	5.00	บาท/ก.ก.	13 +	65
แกลอน		บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก	1.00	บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	40.00	บาท/ก.ก.		
กระป๋องวิปิงครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				493 .

นางณอมจิต จันทนามอม

ที่อยู่: 179 หมู่ที่ 10 ต. โสภนภเต็น อ. พล จ. ขอนแก่น

เลขบัตรประจำตัวประชาชน: 5 3404 00017 23 5

ธนอม จันทนามอม

Supplier

Chutipat

Income Auditor

Notanog K. H/K

Witness

nan s.

General Cashier

INVOICE

Company :
ID : 5340400017235
Address : Thailand
Attention :
Room :
Room Type :
Arrival : 30 Jan 2026
Departure : 31 Jan 2026
Guest : Ms Thanomchit Channamom

Reservation : 20093484
ABN : 0115559022518
Invoice No. : 241469
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 27 May 2026 05:14
Cashier : siriporn.d
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
27 May 2026		Miscellaneous.	874.30
		#17190 Garbage Selling on 27 May 2026	
		- TH VAT - Others 7%.	61.20
		TT/Direct Credit 1 Receipt #148047, Drawer: BTF 27/05/26 (14.04 hrs)	-935.50
		- Paid for Garbage Selling on 27 May 2026	
		Sub-Total Before VAT	874.30
		VAT	61.20
		Total Amount Inc VAT	935.50
		Payment	-935.50
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name	: Siam Commercial Bank Public Company Limited	Branch Code	: 5300
Account	: 430-044-7697	SWIFT Code	: SICOTHBK
Bank Code	: 014	Bank Address	: No. 9/9, the 5th Floor Central Plaza Grand Rama 9, Huai Khwang, Bangkok 10310
Holder's Name	: AMH Ratchada Co., Ltd.		

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO
 BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON
 COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL
 AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: <https://www.discoverasr.com>

Somerset Rama 9 Bangkok | Tax Invoice # 241469 | Page 1/1

ใบรับซื้อ-ของเก่า

Date: 27-May-2026

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	3.00	บาท/ก.ก.	$26 + 24 + 24 + 16 + 25 = 115$	345-
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม		บาท/ก.ก.		
เศษกระดาษ	2	บาท/ก.ก.	20	40-
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	0.50	บาท/ก.ก.	$15 + 19 + 17 + 21 + 16 + 21 = 109$	54.5-
ปิ่น				
ปิ่น (ดี)		บาท/ใบ		
ปิ่น (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	3.00	บาท/ก.ก.	$11 + 11 = 22$	66-
ขวดน้ำ ขุ่น-ใส	5.00	บาท/ก.ก.	$12 + 9 + 14 + 8 = 43$	215-
แกลอน		บาท/ก.ก.		
อื่นๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก	1.00	บาท/ก.ก.		
เศษเหล็ก-บาง	5	บาท/ก.ก.	13	65-
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	30 40.00	บาท/ก.ก.	5	150-
กระป๋องวิปิงครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Com / Air		บาท/ก.ก.		
TOTAL				935.5

นางธนอมจิต จันนามอม

ที่อยู่: 179 หมู่ที่ 10 ต. โสภนภเต็น อ. พล จ. ขอนแก่น

เลขบัตรประจำตัวประชาชน: 5 3404 00017 23 5

.....
 Supplier

.....
 Income Auditor

.....
 Witness

.....
 General Cashier

โอนเงินสำเร็จ

27 พ.ค. 69 14:04 น.

K+



นาง ธนอมจิต จ
ธ.กสิกรไทย
xxx-x-x4930-x



บริษัท เอเอ็มเอช รัชดา จำกัด
ธ.ไทยพาณิชย์
xxx-x-x4769-x

เลขที่รายการ:

016147140419AOR00998

จำนวน:

935.50 บาท

ค่าธรรมเนียม:

0.00 บาท



สแกนตรวจสอบสลิป

AMH RATCHADA CO., LTD.-BRANCH 00002

22 Ratchadaphisek Rd, Huai Khwang,
Huai Khwang, Bangkok 10310

TAX ID: 0115559022518 Tel. +66 (0) 22391999 Fax: +66 (0) 22391900

RECEIPT / TAX INVOICE

RECEIVED FROM	Ms Thanomchit Channamom	DATE	26-Jun-2026
ADDRESS	, Thailand		
TAX ID	5340400017235		

Description	Amount
TT/Direct Credit 1 Receipt #150970, Drawer: 15.23 hrs Kbank - Paid for #17590 Garbage selling on 26 Jun 2026	1,102.50
TOTAL	1,030.37
VALUE ADDED TAX	72.13
GRAND TOTAL	1,102.50

RECEIVED BAHT One Thousand One Hundred Two and Fifty Satang

BY ☐ CASH ☐ CHEQUE NO. _____ BANK _____ DATE _____
☐ CREDIT CARD _____ NO. _____ EXP. DATE _____
☒ BANK TRANSFER _____ BANK _____ DATE _____

Matchmoo
CASHIER/RECEIVER

MANAGED BY
ASCOTT INTERNATIONAL MANAGEMENT (THAILAND) LIMITED

REMARKS: IF PAYMENT IS MADE BY CHEQUE, RECEIPT WILL NOT BE VALID UNTIL THE CHEQUE IS HONORED BY BANK.
THIS RECEIPT IS VALID ONLY WHEN IT BEARS THE SIGNATURE OF AUTHORIZED CASHIER/RECEIVER.

INVOICE

Company :
ID : 5340400017235
Address : Thailand
Attention :
Room :
Room Type :
Arrival : 30 Jan 2026
Departure : 31 Jan 2026
Guest : Ms Thanomchit Channamom

Reservation : 20093484
ABN : 0115559022518
Invoice No. : 245071
A/R No. :
PO/Cost Centre :
3rd Party No. :
Print Date/Time : 26 Jun 2026 07:00
Cashier : matchima.m
Page : 1

DATE	Room	DESCRIPTION	AMOUNT (THB)
26 Jun 2026		Miscellaneous.	1,030.37
		#17590 Garbage selling on 26 Jun 2026	
		- TH VAT - Others 7%.	72.13
		TT/Direct Credit 1 Receipt #150970, Drawer: 15.23 hrs Kbank	-1,102.50
		- Paid for #17590 Garbage selling on 26 Jun 2026	
		Sub-Total Before VAT	1,030.37
		VAT	72.13
		Total Amount Inc VAT	1,102.50
		Payment	-1,102.50
		Balance	0.00

Note: Please do not pay to any bank accounts that the beneficially name differs from AMH Ratchada Co., Ltd. and immediately contact the authorized person for verification and confirmation upon receipt of any instruction to change of bank account.

Bank Details

Bank Name : Siam Commercial Bank Public Company Limited
Account : 430-044-7697
Bank Code : 014
Holder's Name : AMH Ratchada Co., Ltd.

Branch Code : 5300
SWIFT Code : SICOTHBK
Bank Address : No. 9/9, the 5th Floor Central Plaza Grand Rama 9, Huai Khwang, Bangkok 10310

I ACCEPT THAT MY LIABILITY FOR THIS BILL IS NOT WAIVED AND AGREE TO BE HELD PERSONALLY LIABLE IN THE EVENT THAT THE INDICATED PERSON COMPANY OR ASSOCIATION FAILS TO PAY FOR ANY PART OF THE FULL AMOUNT OF THESE CHARGES

SIGNATURE: _____

AMH RATCHADA CO., LTD. BRANCH 00002 - Tax ID: 0115559022518

22 Ratchadaphisek Rd, Huai Khwang, Bangkok 10310

Tel.: +66 (0) 22391999 Fax: +66 (0) 22391900 Email: guestservice.sr9@the-ascott.com Website: https://www.discoverasr.com

โอนเงินสำเร็จ

26 มิ.ย. 69 15:23 น.

K+



นาง ธนอมจิต จ
ธ.กสิกรไทย
xxx-x-x4930-x



บริษัท เอเอ็มเอช รัชดา จำกัด
ธ.ไทยพาณิชย์
xxx-x-x4769-x

เลขที่รายการ:

016177152347AOR04132

จำนวน:

1,102.50 บาท

ค่าธรรมเนียม:

0.00 บาท



สแกนตรวจสอบสลิป

ใบรับซื้อ-ของเก่า

Date: 26-Jun-2026

รายการ	ราคา/หน่วย	หน่วย	จำนวนที่ขายได้	จำนวนเงิน
กระดาษ				
กล่องกระดาษ	3	บาท/ก.ก.	$19 + 18 + 29 + 30 + 20 = 116$	348
หนังสือพิมพ์		บาท/ก.ก.		
เล่ม		บาท/ก.ก.		
เศษกระดาษ	2	บาท/ก.ก.	$10 + 19 = 29$	58
ขาว-ดำ		บาท/ก.ก.		
แก้ว				
HEINECKEN (S)		บาท/ลัง		
HEINECKEN (L)		บาท/ลัง		
SINGHA (S)		บาท/ลัง		
SINGHA (L)		บาท/ลัง		
LEO - CHANG		บาท/ลัง		
เศษแก้ว	0.5	บาท/ก.ก.	$22 + 21 + 22 + 19 + 22 + 23 = 129$	64.50
ปิ่น				
ปิ่น (ดี)		บาท/ใบ		
ปิ่น (รอง)		บาท/ใบ		
พลาสติก				
พลาสติก-สี	3	บาท/ก.ก.	19	57
ขวดน้ำ ขุ่น-ใส	5	บาท/ก.ก.	$15 + 18 + 16 + 6 = 55$	275
แกลอน		บาท/ก.ก.		
อื่น ๆ				
ท่อ PVC		บาท/ก.ก.		
เศษเหล็ก		บาท/ก.ก.		
เศษเหล็ก-บาง		บาท/ก.ก.		
อลูมิเนียม		บาท/ก.ก.		
กระป๋อง-อลูมิเนียม	30	บาท/ก.ก.	10	300
กระป๋องวิปป์ครีม		บาท/ก.ก.		
ทองเหลือง		บาท/ก.ก.		
แบตเตอรี่		บาท/ก.ก.		
Motor		บาท/ก.ก.		
Corn / Air		บาท/ก.ก.		
TOTAL				1,102.50

๒๒-พค ๐๖/๖๖ 2๐2๖

Supplier

Narakorn T.

Income Auditor

Saengden

Witness

Makong

General Cashier

สำเนาเอกสารการรับ-จ่ายค่าบริการสูงสิ่งปฏิกูลและไขมัน

ที่ PE/03001/2026

วันที่ 7 มีนาคม 2569

เรื่อง ขอส่งมอบงานสูบกู้กำจัดไขมันและสิ่งปฏิกูล (Somerset Rama 9) ครั้งที่ 1/12
เรียน คุณณัฏฐิติพัทธ์ ร้อยโสม
อ้างถึง ใบสั่งซื้อเลขที่ PUR-THB21301-0000005366 ลงวันที่ 27 กุมภาพันธ์ 2569

ตามที่ บริษัท เอเอ็มเอช รัชดา จำกัด ได้ทำการตกลงว่าจ้าง บริษัท พราว เอ็นจิเนียริง จำกัด ให้เป็นผู้ดำเนินการสูบกู้กำจัดไขมันและสิ่งปฏิกูล (Somerset Rama 9 Bangkok) ตามอ้างถึง นั้น

บัดนี้ บริษัท พราว เอ็นจิเนียริง จำกัด ได้ดำเนินการงานดังกล่าว ให้กับ บริษัท เอเอ็มเอช รัชดา จำกัด แล้วเสร็จเป็นที่เรียบร้อยแล้วเมื่อวันที่ 7 มีนาคม 2569 จึงขอเรียนแจ้งส่งมอบงานและขอเบิกจ่ายค่าดำเนินการสูบกู้กำจัดไขมันและสิ่งปฏิกูล เป็นจำนวนเงิน 23,000.00 บาท (สองหมื่นสามพันบาทถ้วน) ให้แก่ทางบริษัทฯ ด้วย ทั้งนี้ ราคาดังกล่าวยังไม่รวมภาษีมูลค่าเพิ่ม 7%

จึงเรียนมาเพื่อพิจารณาและอนุมัติ



ขอแสดงความนับถือ



(นายสุภชัย จตุรงค์)

ผู้จัดการแผนกบริการ

บริษัท พราว เอ็นจิเนียริง จำกัด



ผู้ตรวจรับมอบงาน



ที่ PE/04001/2026

วันที่ 23 เมษายน 2569

เรื่อง ขอส่งมอบงานสูบกู้กำจัดไขมันและสิ่งปฏิกูล (Somerset Rama 9) ครั้งที่ 2/12

เรียน คุณณัฏฐิติพัทธ์ ร้อยโสม

อ้างถึง ใบสั่งซื้อเลขที่ PUR-THB21301-0000005570 ลงวันที่ 17 เมษายน 2569

ตามที่ บริษัท เอเอ็มเอช รัชดา จำกัด ได้ทำการตกลงว่าจ้าง บริษัท พราว เอ็นจิเนียริง จำกัด ให้เป็นผู้ดำเนินการสูบกู้กำจัดไขมันและสิ่งปฏิกูล (Somerset Rama 9 Bangkok) ตามอ้างถึง นั้น

บัดนี้ บริษัท พราว เอ็นจิเนียริง จำกัด ได้ดำเนินการงานดังกล่าว ให้กับ บริษัท เอเอ็มเอช รัชดา จำกัด แล้วเสร็จเป็นที่เรียบร้อยแล้วเมื่อวันที่ 23 เมษายน 2569 จึงขอเรียนแจ้งส่งมอบงานและขอเบิกจ่ายค่าดำเนินการสูบกู้กำจัดไขมันและสิ่งปฏิกูล เป็นจำนวนเงิน 23,000.00 บาท (สองหมื่นสามพันบาทถ้วน) ให้แก่ทางบริษัทฯ ด้วย ทั้งนี้ ราคาดังกล่าวยังไม่รวมภาษีมูลค่าเพิ่ม 7%

จึงเรียนมาเพื่อพิจารณาและอนุมัติ



ขอแสดงความนับถือ



(นายสุชาติ จตฺรรงค์)

ผู้จัดการแผนกบริการ

บริษัท พราว เอ็นจิเนียริง จำกัด

67/9/10 กส
23, 4, 26

ผู้ตรวจรับมอบงาน



ที่ PE/05001/2026

วันที่ 25 พฤษภาคม 2569

เรื่อง ขอส่งมอบงานสูบกู้กำจัดไขมันและสิ่งปฏิกูล (Somerset Rama 9) ครั้งที่ 3/12
เรียน คุณณัฏฐิติพัทธ์ ร้อยโสม
อ้างถึง ใบสั่งซื้อเลขที่ PUR-THB21301-0000005668 ลงวันที่ 11 พฤษภาคม 2569

ตามที่ บริษัท เอเอ็มเอช รัชดา จำกัด ได้ทำการตกลงว่าจ้าง บริษัท พราว เอ็นจิเนียริง จำกัด ให้เป็นผู้ดำเนินการสูบกู้กำจัดไขมันและสิ่งปฏิกูล (Somerset Rama 9 Bangkok) ตามอ้างถึง นั้น

บัดนี้ บริษัท พราว เอ็นจิเนียริง จำกัด ได้ดำเนินการงานดังกล่าว ให้กับ บริษัท เอเอ็มเอช รัชดา จำกัด แล้วเสร็จเป็นที่เรียบร้อยแล้วเมื่อวันที่ 25 พฤษภาคม 2569 จึงขอเรียนแจ้งส่งมอบงานและขอเบิกจ่ายค่าดำเนินการสูบกู้กำจัดไขมันและสิ่งปฏิกูล เป็นจำนวนเงิน 23,000.00 บาท (สองหมื่นสามพันบาทถ้วน) ให้แก่ทางบริษัทฯ ด้วย ทั้งนี้ ราคาดังกล่าวยังไม่รวมภาษีมูลค่าเพิ่ม 7%

จึงเรียนมาเพื่อพิจารณาและอนุมัติ



ขอแสดงความนับถือ



(นายคุชชัย จตุรงค์)

ผู้จัดการแผนกบริการ

บริษัท พราว เอ็นจิเนียริง จำกัด

อนุชิต
25 / 05 / 26

ผู้ตรวจรับมอบงาน



63/921 ซอยราชบุรีพัฒนา 5 ถนนราชบุรีพัฒนา แขวงราชบุรีพัฒนา เขตสะพานสูง กรุงเทพฯ 10240



63/921, Soi Rajphattana 5, Rajphattana Rd., Rajphattana, Saphansong, Bangkok 10240

Tel : 02-1 707284 Fax :02-1708408

ท PE/06001/2026

วันที่ 21 มิถุนายน 2569

เรื่อง ขอส่งมอบงานสูบกู้จัดไข่มันและสิ่งปฏิกูล (Somerset Rama 9) ครั้งที่ 4/12
เรียน คุณณัฏฐิพัทธ์ ร้อยโสม
อ้างถึง ใบสั่งซื้อเลขที่ PUR-THB21301-0000005756 ลงวันที่ 10 มิถุนายน 2569

ตามที่ บริษัท เอเอ็มเอช รัชดา จำกัด ได้ทำการตกลงว่าจ้าง บริษัท พราว เอ็นจิเนียริง จำกัด ให้เป็นผู้ดำเนินการสูบกู้จัดไข่มันและสิ่งปฏิกูล (Somerset Rama 9 Bangkok) ตามอ้างถึง นั้น

บัดนี้ บริษัท พราว เอ็นจิเนียริง จำกัด ได้ดำเนินการงานดังกล่าว ให้กับ บริษัท เอเอ็มเอช รัชดา จำกัด แล้วเสร็จเป็นที่เรียบร้อยแล้วเมื่อวันที่ 21 มิถุนายน 2569 จึงขอเรียนแจ้งส่งมอบงานและขอเบิกจ่ายค่าดำเนินการสูบกู้จัดไข่มันและสิ่งปฏิกูล เป็นจำนวนเงิน 23,000.00 บาท (สองหมื่นสามพันบาทถ้วน) ให้แก่ทางบริษัทฯ ด้วย ทั้งนี้ ราคาดังกล่าวยังไม่รวมภาษีมูลค่าเพิ่ม 7%

จึงเรียนมาเพื่อพิจารณาและอนุมัติ




ขอแสดงความนับถือ



(นายสุภชัย จตุรงค์)

ผู้จัดการแผนกบริการ

บริษัท พราว เอ็นจิเนียริง จำกัด



21, 06, 26

ผู้ตรวจรับมอบงาน



สำเนาสัญญาการดูแลต้นไม้

รายงานการให้บริการงานดูแลสวน

ชื่อหน่วยงาน.....บริษัท เคเอ็มเอส รัชดา จำกัด..... วันที่ 22/1/69
 รายชื่อหัวหน้างานและพนักงาน.....อ.พล, อ.กันต์, อ.จิรภัทร, อ.กมล, อ.กันต์, อ.ศร, อ.ณัฏ, อ.โชนพ, อ.นง, อ.พน

1. บันทึกการให้บริการและการจัดส่งวัสดุ

ชั้น 8 ลระว่าพนา - ขนดินจากชั้น 8 ขึ้นไปเติมดินลงในบล็อกดต้นหน้าเต้าบริเวณข้างลระว่าพนา จำนวน 840 ตง และนำอิฐเสกโก้ จำนวน 64 ก้อน วางปิดล้อมโคนต้นหน้าเต้า จำนวน 3 ต้น เพื่อป้องกันดินไหลพังไปถมที่โคนต้นไม้ และเก็บกวาดล้างพื้นที่ทำความสะอาดพื้นที่ทำงานเสร็จเรียบร้อยแล้วพร้อมส่งมอบงาน	ลงนาม.....จิรภัทร (22/1/69)..... เจ้าหน้าที่บริษัท สวนสวยรังสิต จำกัด
--	---

2. สำหรับลูกค้า

ลงนาม.....กมล (22/1/69)..... เจ้าหน้าที่หน่วยงาน
--





รายงานการให้บริการงานดูแลสวน

ชื่อหน่วยงาน บริษัท เจริญผล รัชดา จำกัด (สาท๐๐๐๒) วันที่ 9/4/69
รายชื่อหัวหน้างานและพนักงาน โกสินทร์, ศิวรินทร์, ดอร, มั่นเท่ง, เต, พล, นันท, ทน, พอล, ธีร

1. บันทึกการให้บริการและการจัดส่งวัสดุ

ชั้น 8

- ตัดหญ้าบริเวณโถงรอบ
- ตัดแต่งทรงพุ่มต้นไทรบริเวณศาลพระภูมิ
- ตัดแต่งทรงพุ่มต้นหน้าเข้าบริเวณหน้าลิบบมี
- ตัดแต่งทรงพุ่มต้นแก้วบริเวณด้านหลัง และ ด้านข้างโรงแรม
- ตัดแต่งทรงพุ่มต้นพุดศรีใจดี และ ต้นแก้วบริเวณสวนหินหน้าโรงแรม
- ตัดแต่งใบเลื้อยไม้หน้าต้นแพนไอรিস บริเวณจุดชมจันทร์
- ทำขึ้นต้นน้ำเต้าที่โอ้ว บริเวณหน้าร้าน 7-11 จำนวน 1 ต้น
- เก็บใบแห้งต้นมะฮอกกานี บริเวณด้านข้างแนวกำแพงฝั่งศาล
- เป่าใบไม้และเก็บกวาดใบไม้

ชั้น 8

- ปลุกต้นไทรกระทิง พร้อมด้วยต้นลำต้น จำนวน 1 ต้น
- ปลุกต้นทับทิมสยาม จำนวน 12 ต้น และปลุกต้นแพนไอรিস ลงไปในบล็อคดีด้วยกับต้นไทรกระทิง
- เติบโตต้นลงในบล็อกต้นไม้ที่ปลุกใหม่จำนวน 200 ดวง (ต้นไม้จากใบ PO จำนวน 100 ดวง และ ต้นเก่าของหน่วยงาน 100 ดวง)
- รวบน้ำขารังรากในต้นไม้ปลุกใหม่แล้ว รวบน้ำต้นไม้
- ปลุกต้นบอนกระดาดลงในกระถางปูน 1 ต้น (แทนต้นเก่าที่ตาย)
- ขุดเปิดหน้าตุ่มต้นกระโดน แล้วนำต้นเฟิร์นสาธยาย ห้อยในบล็อกออกไปพักหน้าฮาดากำจัดโรค รากเน่าโคนเน่า และน้ำขารังรากในต้นกระโดน

ชั้น 27

- ตัดต้นหญ้า - ฮอนซ์พืชในบล็อก - ตัดแต่งกิ่งต้นยี่โถ
- ตัดแต่งต้นคริสต์มาส - ตัดแต่งทรงพุ่มต้นโสมขาวพุ่ม - ทำความสะอาด


ลงนาม

โกสินทร์ (9/4/69)

เจ้าหน้าที่บริษัท สวนสงรังสิต จำกัด

2. สำหรับลูกค้า

ลงนาม	<u>ScmW.</u>	เจ้าหน้าที่หน่วยงาน
-------	--------------	---------------------



ชื่อหน่วยงาน เลขที่ 22 ต. รัชดาภิเษก แขวงหน้าแขวน เขตหน้าแขวน วันที่

รายชื่อหัวหน้างานและพนักงาน

1. บันทึกการให้บริการและการจัดส่งวัสดุ

26

- ตัดถนนบริเวณโถงรวมโรงโม่
- ตัดแต่งทรงพุ่มต้นแก้วบริเวณ แนวรั้วกำแพงด้านหลังโรงโม่
- ตัดแต่งทรงพุ่มแนวโถงบริเวณกำแพงรอบด้านข้างโรงโม่
- ตัดแต่งทรงพุ่มต้นตองบริเวณจุดสมบรูณ์หน้าโรงโม่
- ตัดแต่งใบไม้สีใบไม้แห้งต้นแพนไถ้บริเวณจุดสมบรูณ์หน้าโรงโม่
- ตัดแต่งทรงพุ่มต้นเข็มชมพู ต้นพุดกลีบดำ ต้นตองฝรั่ง ต้นสนใบพวงบริเวณด้านหน้าข้างหน้าโรงโม่
- ตัดแต่งทรงพุ่มต้นสนใบพวง ต้นพุดศรีโชค ต้นแก้ว ต้นปลาฉลามทะเล
- ตัดแต่งทรงพุ่มต้นกันเกรา หัตถ์ทรงพุ่มปลูกหาเรื่อง ด้านตรง และตรงหน้าจำนวน 1 ต้น เพื่อช่วยในรากที่มีปัญหารากเหี่ยวได้งอกขึ้นใหม่ประกอบด้วยดินสวน วัสดุกำจัดโรครากเหี่ยวเพื่อช่วยฟื้นฟูสภาพของรากให้ดีขึ้น (บริเวณจุดสมบรูณ์หน้าโรงโม่)
- ปลูกใบไม้ ตามพุ่มไม้ และเก็บกวาดใบไม้

27

- ตัดแต่งทรงผมสั้นตรีศุน้ำ
- ตัดแต่งทรงผมสั้นค้อน
- ตัดแต่งทรงผมสั้นเข็มหมุด
- ตัดแต่งทรงผมสั้นไทรยี่ห้าตัว
- ตัดแต่งทรงผมสั้นพอกหน้า
- สดจนหัวพัน
- สดหน้า
- เป่าลมแล้ว = ได้บกวาดใบไม้ ในเรือนกระจก

लगनाम

ทฤษฎี (8/5/69)

เจ้าหน้าที่บริษัท สวนสวขรังสิต จำกัด

2. สำหรับลูกค้า

ฉงนาม

Notano a

เจ้าหน้าที่หน่วยงาน



รายงานการให้บริการงานดูแลสวน

ชื่อหน่วยงาน

โรงเรียนสวนสวเรียงสิต

วันที่

23/5/69

รายชื่อหัวหน้างานและพนักงาน

วิมล อดิศักดิ์ มณี

15/500

1. บันทึกการให้บริการและการจัดส่งวัสดุ

1. ต้นไม้ต้นใหม่ในสวน 1000 และ ต้นไม้ต้นใหม่ในสวน 1000

2. วัสดุและเครื่องมือในสวน 1000

ลงนาม

วิมล

1/5/69

เจ้าหน้าที่บริษัท สวนสวเรียงสิต จำกัด

2. สำหรับลูกค้า

Samsat L.

23/05/69

ลงนาม

เจ้าหน้าที่หน่วยงาน



รายงานการให้บริการงานดูแลสวน

ชื่อหน่วยงาน

บริษัท เกล็ดเคส รับทำ จำกัด (เลขที่ ๐๐๐๒)

วันที่

2/6/2569

รายชื่อหัวหน้างานและพนักงาน

ทิสันท์, ศิวรินทร์, ออร, เป้, โท

1. บันทึกการให้บริการและการจัดส่งวัสดุ

ชั้น 5

- ตัดหญ้าบริเวณด้านหน้าโรงแรม สดสมบูรณ์ และ ศาลพระภูมิ
- ตัดหญ้าบริเวณด้านหลังโรงแรม บริเวณลานจอดรถ และ ข้างกำแพง
- ตัดแต่งทรงพุ่มต้นแก้ว และ ต้นค้อขี้ผึ้งบริเวณ ข้างแนวกำแพงฝั่งต้นชงโค

- ตัดแต่งทรงพุ่มต้นน้ำเต้า 1 ต้น บริเวณหน้าลิโอมบี้
- ตัดแต่งทรงพุ่มต้นคนจำนวน 5 ต้น บริเวณข้างกำแพงฝั่งรถวิ่งเข้าไปจอดด้านหลังโรงแรม
- ฟ้าไม้ และ เก็บกวาดใบไม้
- ปลูกต้น 5 กันกรา พร้อมค้ำยันจำนวน 1 ต้น บริเวณ สดสมบูรณ์ หน้าโรงแรม

ชั้น 27

- ตัดหญ้าบริเวณ สนาม
- ตัดแต่งทรงพุ่มต้นโพธิ์ศรี
- ออกรั้วพืช
- เก็บกวาดใบไม้ และ ต้นหญ้า อุ่นพาทเดินก่อนเข้าลิฟท์

ลงนาม

ทิสันท์ (2/6/2569)

เจ้าหน้าที่บริษัท สุนสวยรังสิต จำกัด

2. สำหรับลูกค้า

ลงนาม

ทิสันท์, 2/6/2569

เจ้าหน้าที่หน่วยงาน

ภาคผนวกที่ 6

สำเนามาตรฐานและกฎหมายที่เกี่ยวข้อง

ประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม
เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด
พ.ศ. ๒๕๖๗

โดยที่เป็นการสมควรปรับปรุงการกำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคาร ให้เหมาะสมตามความก้าวหน้าในทางวิทยาศาสตร์ เทคโนโลยี และความเปลี่ยนแปลงทางเศรษฐกิจ สังคม ของประเทศ และให้สอดคล้องกับสภาพการณ์ปัจจุบัน

อาศัยอำนาจตามความในมาตรา ๕๕ แห่งพระราชบัญญัติส่งเสริมและรักษาคุณภาพสิ่งแวดล้อมแห่งชาติ พ.ศ. ๒๕๓๕ รัฐมนตรีว่าการกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม โดยคำแนะนำของคณะกรรมการควบคุมมลพิษ และโดยความเห็นชอบของคณะกรรมการสิ่งแวดล้อมแห่งชาติ จึงออกประกาศไว้ ดังต่อไปนี้

ข้อ ๑ ให้ยกเลิกประกาศกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม เรื่อง กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารบางประเภทและบางขนาด ฉบับลงวันที่ ๗ พฤศจิกายน พ.ศ. ๒๕๔๘

ข้อ ๒ ในประกาศนี้

“อาคาร” หมายความว่า อาคารที่ก่อสร้างขึ้น ไม่ว่าจะมียุทธศาสตร์เป็นอาคารหลังเดียวหรือเป็นกลุ่มของอาคารซึ่งตั้งอยู่ภายในพื้นที่ซึ่งเป็นบริเวณเดียวกัน และไม่มียุทธศาสตร์น้ำท่วมหรือมีหลายท่อที่เชื่อมติดต่อกันระหว่างอาคารหรือไม่ก็ตาม

“น้ำทิ้ง” หมายความว่า น้ำที่เกิดจากกิจกรรมของอาคารที่ระบายหรือจะระบายลงสู่แหล่งน้ำสาธารณะหรือออกสู่สิ่งแวดล้อม

ข้อ ๓ ให้แบ่งอาคาร ออกเป็น ๓ ชนิด คือ

ชนิดที่ ๑ อาคารอยู่อาศัย หมายถึง อาคารที่มีวัตถุประสงค์ให้เป็นที่พักอาศัยของบุคคลทั้งการอยู่อาศัยอย่างถาวรหรือชั่วคราว ได้แก่

(๑) อาคารชุด ตามกฎหมายว่าด้วยอาคารชุด

(๒) หอพัก ตามกฎหมายว่าด้วยหอพัก

(๓) หอพัก ห้องเช่า ห้องแบ่งเช่า หรือกิจการอื่นในทำนองเดียวกันตามกฎหมายว่าด้วยการสาธารณสุข

(๔) สถานรับเลี้ยงเด็ก ตามกฎหมายว่าด้วยคุ้มครองเด็ก

(๕) สถานดูแลผู้สูงอายุหรือผู้มีภาวะพึ่งพิง ตามกฎหมายว่าด้วยสถานประกอบการเพื่อสุขภาพ

(๖) ที่พักอาศัยสำหรับลูกจ้างประเภทกิจกรรมก่อสร้าง ตามกฎหมายว่าด้วยการคุ้มครองแรงงาน

ชนิดที่ ๒ อาคารพาณิชยกรรม หมายถึง อาคารที่ใช้ประโยชน์ในการพาณิชยกรรม หรือบริการธุรกิจอย่างเดียวหรือหลายอย่าง ได้แก่

(๑) โรงแรม ตามกฎหมายว่าด้วยโรงแรม

- (๒) ศูนย์การค้าหรือห้างสรรพสินค้า
 (๓) ตลาด ตามกฎหมายว่าด้วยการสาธารณสุข
 (๔) สถานบริการประเภทสถานอาบน้ำ นวดหรืออบตัว ตามกฎหมายว่าด้วยสถานบริการ
 (๕) ภัตตาคารหรือร้านอาหาร
 (๖) อาคารที่ทำการของทางราชการ รัฐวิสาหกิจ หรือองค์การระหว่างประเทศและของเอกชน
 (๗) อาคารโรงเรียนเอกชน ตามกฎหมายว่าด้วยโรงเรียนเอกชน โรงเรียนของทางราชการ อาคารสถาบันอุดมศึกษาของเอกชน ตามกฎหมายว่าด้วยสถาบันอุดมศึกษาของเอกชนและสถาบันอุดมศึกษาของทางราชการ

ชนิดที่ ๓ อาคารสถานพยาบาล หมายถึง สถานพยาบาล ตามกฎหมายว่าด้วยสถานพยาบาล ประเภทที่รับผู้ป่วยไว้ค้างคืน

ข้อ ๔ ให้แบ่งขนาดของอาคาร ออกเป็น ๔ ประเภท ดังต่อไปนี้

ประเภทอาคาร	หน่วย	อาคาร ประเภท ก.	อาคาร ประเภท ข.	อาคาร ประเภท ค.	อาคาร ประเภท ง.
๑. อาคารอยู่อาศัย					
อาคารชุด	ห้องชุด	ตั้งแต่ ๕๐๐ ขึ้นไป	ตั้งแต่ ๑๐๐ แต่ไม่ถึง ๕๐๐	ไม่ถึง ๑๐๐	-
หอพัก	ห้อง	-	ตั้งแต่ ๒๕๐ ขึ้นไป	ตั้งแต่ ๕๐ แต่ไม่ถึง ๒๕๐	ไม่ถึง ๕๐
หอพัก ห้องเช่า ห้องแบ่งเช่า หรือกิจการอื่นในทำนอง เดียวกัน ตามกฎหมาย ว่าด้วยการสาธารณสุข	ห้อง	-	ตั้งแต่ ๒๕๐ ขึ้นไป	ตั้งแต่ ๕๐ แต่ไม่ถึง ๒๕๐	ไม่ถึง ๕๐
สถานรับเลี้ยงเด็ก	-	-	-	-	ทุกขนาด
สถานดูแลผู้สูงอายุหรือ ผู้มีภาวะพึ่งพิง	-	-	-	-	ทุกขนาด
ที่พักอาศัยสำหรับลูกจ้าง ประเภทกิจกรรมก่อสร้าง	-	-	-	-	ทุกขนาด
๒. อาคารพาณิชย์					
โรงแรม	ห้อง	ตั้งแต่ ๒๐๐ ขึ้นไป	ตั้งแต่ ๖๐ แต่ไม่ถึง ๒๐๐	ไม่ถึง ๖๐	-
สถานบริการประเภท สถานอาบน้ำ นวดหรืออบตัว	ตาราง เมตร	-	ตั้งแต่ ๕,๐๐๐ ขึ้นไป	ตั้งแต่ ๑,๐๐๐ แต่ไม่ถึง ๕,๐๐๐	ไม่ถึง ๑,๐๐๐
โรงเรียนเอกชน โรงเรียนของ ทางราชการ สถาบันอุดมศึกษา ของเอกชนหรือสถาบัน อุดมศึกษาของทางราชการ		ตั้งแต่ ๒๕,๐๐๐ ขึ้นไป	ตั้งแต่ ๕,๐๐๐ แต่ไม่ถึง ๒๕,๐๐๐	-	ไม่ถึง ๕,๐๐๐

ประเภทอาคาร	หน่วย	อาคาร ประเภท ก.	อาคาร ประเภท ข.	อาคาร ประเภท ค.	อาคาร ประเภท ง.
อาคารที่ทำการของทาง ราชการ รัฐวิสาหกิจ หรือ องค์การระหว่างประเทศและ ของเอกชน		ตั้งแต่ ๕๕,๐๐๐ ขึ้นไป	ตั้งแต่ ๑๐,๐๐๐ แต่ไม่ถึง ๕๕,๐๐๐	ตั้งแต่ ๕,๐๐๐ แต่ไม่ถึง ๑๐,๐๐๐	ไม่ถึง ๕,๐๐๐
ศูนย์การค้า หรือห้างสรรพสินค้า		ตั้งแต่ ๒๕,๐๐๐ ขึ้นไป	ตั้งแต่ ๕,๐๐๐ แต่ไม่ถึง ๒๕,๐๐๐	-	ไม่ถึง ๕,๐๐๐
ตลาด		ตั้งแต่ ๒,๕๐๐ ขึ้นไป	ตั้งแต่ ๑,๕๐๐ แต่ไม่ถึง ๒,๕๐๐	ตั้งแต่ ๑,๐๐๐ แต่ไม่ถึง ๑,๕๐๐	ไม่ถึง ๑,๐๐๐
ภัตตาคารหรือร้านอาหาร		ตั้งแต่ ๒,๕๐๐ ขึ้นไป	ตั้งแต่ ๕๐๐ แต่ไม่ถึง ๒,๕๐๐	ตั้งแต่ ๒๕๐ แต่ไม่ถึง ๕๐๐	ไม่ถึง ๒๕๐
๓. อาคารสถานพยาบาล	เตียง	ตั้งแต่ ๓๐ ขึ้นไป	ตั้งแต่ ๑๐ แต่ไม่ถึง ๓๐	-	ไม่ถึง ๑๐

ข้อ ๕ กำหนดมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารไว้ ดังต่อไปนี้

พารามิเตอร์	ค่ามาตรฐาน			
	อาคาร ประเภท ก.	อาคาร ประเภท ข.	อาคาร ประเภท ค.	อาคาร ประเภท ง.
๑. ความเป็นกรดและด่าง (pH)	๕.๕ - ๙.๐	๕.๕ - ๙.๐	๕.๕ - ๙.๐	๕.๕ - ๙.๐
๒. บีโอดี (Biochemical Oxygen Demand)	ไม่เกิน ๒๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๓๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๔๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๕๐ มิลลิกรัมต่อลิตร สำหรับอาคารอยู่อาศัย
				ไม่เกิน ๑๐๐ มิลลิกรัมต่อลิตร สำหรับอาคารพาณิชย์ และอาคารสถานพยาบาล
๓. ของแข็งแขวนลอยทั้งหมด (Total Suspended Solids)	ไม่เกิน ๓๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๔๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๕๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๖๐ มิลลิกรัมต่อลิตร
๔. ของแข็งละลายน้ำทั้งหมด (Total Dissolved Solids)	ไม่เกิน ๑,๐๐๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๑,๐๐๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๑,๓๐๐ มิลลิกรัมต่อลิตร	-

พารามิเตอร์	ค่ามาตรฐาน			
	อาคาร ประเภท ก.	อาคาร ประเภท ข.	อาคาร ประเภท ค.	อาคาร ประเภท ง.
	สำหรับอาคารอยู่ อาศัยและอาคาร พาณิชย์	สำหรับอาคารอยู่ อาศัยและอาคาร พาณิชย์	สำหรับอาคารอยู่ อาศัยและอาคาร พาณิชย์	
	เพิ่มขึ้นจาก ปริมาณในน้ำใช้ ปกติไม่เกิน ๑,๐๐๐ สำหรับอาคาร สถานพยาบาล	เพิ่มขึ้นจาก ปริมาณในน้ำใช้ ปกติไม่เกิน ๑,๐๐๐ สำหรับอาคาร สถานพยาบาล	-	-
๕. ซัลไฟด์ (Sulfide)	ไม่เกิน ๑.๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๑.๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๑.๐ มิลลิกรัมต่อลิตร	-
๖. ทีเคเอ็น (Total Kjeldahl Nitrogen)	ไม่เกิน ๓๕ มิลลิกรัมต่อลิตร	ไม่เกิน ๓๕ มิลลิกรัมต่อลิตร	ไม่เกิน ๔๐ มิลลิกรัมต่อลิตร	-
๗. น้ำมันและไขมัน (Oil and Grease)	ไม่เกิน ๒๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๒๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๒๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๒๐ มิลลิกรัมต่อลิตร สำหรับอาคารอยู่อาศัย
				ไม่เกิน ๕๐ มิลลิกรัม ต่อลิตร สำหรับอาคาร พาณิชย์และอาคาร สถานพยาบาล
๘. แบคทีเรียกลุ่มโคลิฟอร์มทั้งหมด (Total Coliform Bacteria) (สำหรับอาคารสถานพยาบาล)	ไม่เกิน ๕,๐๐๐ (เอ็มพีเอ็นต่อ ๑๐๐ มิลลิลิตร)	ไม่เกิน ๕,๐๐๐ (เอ็มพีเอ็นต่อ ๑๐๐ มิลลิลิตร)	-	-
๙. แบคทีเรียกลุ่มฟีคอลโคลิฟอร์ม (Fecal Coliform Bacteria) (สำหรับอาคารสถานพยาบาล)	ไม่เกิน ๑,๐๐๐ (เอ็มพีเอ็นต่อ ๑๐๐ มิลลิลิตร)	ไม่เกิน ๑,๐๐๐ (เอ็มพีเอ็นต่อ ๑๐๐ มิลลิลิตร)	-	-
๑๐. คลอรีนอิสระ (Free Chlorine) (สำหรับอาคารสถานพยาบาล)	ไม่เกิน ๑.๐ มิลลิกรัมต่อลิตร	ไม่เกิน ๑.๐ มิลลิกรัมต่อลิตร	-	-

ข้อ ๖ การตรวจสอบมาตรฐานควบคุมการระบายน้ำทิ้งจากอาคารให้ใช้วิธีการ ดังต่อไปนี้

๖.๑ ความเป็นกรดและด่าง ให้ใช้เครื่องวัดความเป็นกรดและด่างของน้ำ (pH Meter) ที่มีความละเอียดไม่ต่ำกว่า ๐.๑ หน่วย

๖.๒ บีโอดี ให้ใช้วิธีบ่มตัวอย่างที่อุณหภูมิ ๒๐ องศาเซลเซียส เป็นเวลา ๕ วันติดต่อกัน และหาค่าออกซิเจนละลายด้วยวิธีเอไซด์มอดิฟิเคชัน (Azide Modification) หรือวิธีเมมเบรนอิเล็กโทรด (Membrane Electrode) หรือวิธีออปติคัลโพรบ (Optical Probe)

๖.๓ ของแข็งแขวนลอยทั้งหมด ให้ใช้วิธีการกรองผ่านกระดาษกรองใยแก้ว (Glass Fiber Filter) และอบแห้งที่อุณหภูมิ ตั้งแต่ ๑๐๓ ถึง ๑๐๕ องศาเซลเซียส เป็นเวลาอย่างน้อย ๑ ชั่วโมง

๖.๔ ของแข็งละลายน้ำทั้งหมด ให้ใช้วิธีระเหยตัวอย่างที่กรองผ่านกระดาษกรองใยแก้ว (Glass Fiber Filter) และอบแห้งที่อุณหภูมิ ๑๘๐ องศาเซลเซียส เป็นเวลาอย่างน้อย ๑ ชั่วโมง

๖.๕ ซัลไฟด์ ให้ใช้วิธีไอโอดิเมทริก (Iodometric Method) หรือวิธีเมทิลีนบลู (Methylene Blue Method)

๖.๖ ทีเคเอ็น ให้ใช้วิธีเจลดาล์ (Kjeldahl)

๖.๗ น้ำมันและไขมัน ให้ใช้วิธีสกัดด้วยตัวทำละลายแล้วแยกหาน้ำมันและไขมัน

๖.๘ แบคทีเรียกลุ่มโคลิฟอร์มทั้งหมดและแบคทีเรียกลุ่มฟิคอลโคลิฟอร์ม ให้ใช้วิธีมัลติเพิล ทิวบ์ เฟอร์เมนเทชัน เทคนิค (Multiple Tube Fermentation Technique)

๖.๙ คลอรีนอิสระ ให้ใช้วิธีไทเทรต (Titrimetric method) หรือวิธีเทียบสี (Colorimetric method) หรือวิธีไอโอดิเมทริก อิเล็กโทรด (Iodometric Electrode Technique)

ข้อ ๗ การคิดคำนวณขนาดของอาคารตามข้อ ๔ ให้เป็นไปตามวิธีการที่คณะกรรมการควบคุมมลพิษกำหนด โดยประกาศในราชกิจจานุเบกษา

ข้อ ๘ การตรวจสอบค่ามาตรฐานน้ำทิ้งตามข้อ ๖ ต้องเป็นไปตามคู่มือวิเคราะห์น้ำและน้ำเสียของสมาคมวิศวกรรมสิ่งแวดล้อมแห่งประเทศไทย หรือ Standard Methods for the Examination of Water and Wastewater ซึ่ง American Public Health Association, American Water Works Association และ Water Environment Federation ของประเทศสหรัฐอเมริกากำหนดฉบับล่าสุด หรือตามที่คณะกรรมการควบคุมมลพิษประกาศในราชกิจจานุเบกษา

ข้อ ๙ การเก็บตัวอย่างน้ำทิ้งเพื่อการตรวจสอบมาตรฐานควบคุมการระบายน้ำทิ้งตามข้อ ๕ ให้เป็น ดังต่อไปนี้

๙.๑ ให้เก็บในจุดระบายทิ้งลงสู่แหล่งน้ำสาธารณะหรือออกสู่สิ่งแวดล้อมหรือจุดอื่นที่สามารถใช้เป็นตัวแทนของน้ำทิ้งที่ระบายออกจากอาคาร ในกรณีมีการระบายทิ้งหลายจุดให้เก็บทุกจุด

๙.๒ วิธีการเก็บตัวอย่างน้ำทิ้ง ณ จุดเก็บตัวอย่างตามข้อ ๙.๑ ให้เก็บแบบจ้วง (Grab Sampling)

ข้อ ๑๐ ประกาศนี้ให้ใช้บังคับตั้งแต่วันถัดจากวันประกาศในราชกิจจานุเบกษาเป็นต้นไป

ประกาศ ณ วันที่ ๒๘ มิถุนายน พ.ศ. ๒๕๖๗

พลตำรวจเอก พัชรวาท วงษ์สุวรรณ

รัฐมนตรีว่าการกระทรวงทรัพยากรธรรมชาติและสิ่งแวดล้อม